#### **Rincon Consultants, Inc.**

RINCON CONSULTANTS, INC. SINCE 1994

180 North Ashwood Avenue Ventura, CA 93003 Phone: 805-644-4455

December 24, 2024 Project No: 24-16251

Christopher Solis, P.E.
Engineering Manager, Roads & Transportation
Ventura County Public Works Agency
800 S Victoria Ave
Ventura, CA 93009

Via email: christopher.solis@ventura.org

Subject: Statutory Exemption Memorandum under the California Environmental Quality Act

for the Lockwood Valley Road Emergency Repairs Project

**Ventura County, California** 

Dear Mr. Solis:

Rincon Consultants, Inc. is pleased to submit this memorandum for the Lockwood Valley Road Emergency Repairs Project (project), located at mile point (MP) 1.75 and MP 12.69 in unincorporated Ventura County, California. The purpose of this memorandum is to verify that the project meets the provisions of a Statutory Exemption under Section 15269(d) of the California Environmental Quality Act (CEQA) Guidelines. This memorandum will accompany the Notice of Exemption for the project.

### **Project Overview**

Following severe storm events that occurred in February 2024, Lockwood Valley Road requires permanent emergency repairs in two areas, the first at MP 1.75 and the second at MP 12.69 (Attachment A, Figures 1-3). At MP 1.75, the Cuyama River undermined the roadbed, breaking apart the asphalt and causing severe damage, leading to the closure of the road in both directions. The southern shoulder at MP 1.75 has been backfilled and fortified with road base allowing residents to drive onto the shoulder and around the damaged roadway. Non-resident drivers must detour around the closure, resulting in increased commute times and vehicle miles traveled (VMT). The roadway needs to be repaired to facilitate safe reopening. At MP 12.69, the corrugated metal pipe (CMP) culvert passing beneath the roadway was damaged by high water pressure during the storm events. The culvert needs to be repaired for proper stormwater management, and to prevent additional erosion and undercutting of the roadway. Representative site photographs depicting existing conditions are provided in Attachment B.

The Ventura County Public Works Agency – Roads and Transportation (Agency) intends to complete repair work within existing Agency rights of way or within temporary construction easements obtained by the Agency, as illustrated in the attached project plans (Attachment C).

Improvements at MP 1.75 include the reconstruction and repair of an approximately 310-linear foot segment of Lockwood Valley Road. The repairs necessitate removal and recycling of damaged road material, excavation and placement of rock rip-rap revetment with a buried rock toe along the Cuyama River, re-creation of the road foundation, and reconstruction of the roadway with asphalt concrete (AC) and processed miscellaneous base (PMB). Temporary diversion of river water would be required to facilitate these improvements; a project-specific water diversion plan would be prepared in compliance with the Ventura County Watershed Protection District's Water



Diversion Guide<sup>1</sup>. The project would also entail reconstruction of the southerly shoulder, restriping of the road, and re-construction of a rumble strip along the roadway centerline. Erosion and slope control measures would include armored rock riprap to protect the soil and road from erosion caused by future water flow. These proposed improvements would not expand the existing roadway. Following completion, the lane widths at MP 1.75 would remain 12 feet, and the southern shoulder width would remain 10 feet.

At MP 12.69, the project involves removal and disposal of an existing rusted CMP that ruptured on the south side roadway embankment, construction of a new headwall, installation of a reinforced concrete pipe connecting to the existing functional CMP with a concrete collar, placement of Class IV rock riprap with filter fabric, backfill with controlled low-strength material, and implementation of erosion control measures, including hydroseeding, to mitigate future erosion around the new culvert.

#### **Consistency Analysis**

Section 15269(d) of the *CEQA Guidelines* provides a Statutory Exemption for emergency projects. Specifically, Section 15269(d), exempts the following emergency projects from the requirements of CEQA:

"(d) Projects undertaken, carried out, or approved by a public agency to maintain, repair, or restore an existing highway damaged by fire, flood, storm, earthquake, land subsidence, gradual earth movement, or landslide, provided that the project is within the existing right of way of that highway and is initiated within one year of the damage occurring. This exemption does not apply to highways designated as official state scenic highways, nor any project undertaken, carried out, or approved by a public agency to expand or widen a highway damaged by fire, flood, storm, earthquake, land subsidence, gradual earth movement, or landslide."

The Lockwood Valley Road Emergency Repairs Project qualifies for a Statutory Exemption under CEQA Guidelines Section 15269(d) as a project being undertaken by a public agency to repair an existing highway damaged by flood and storm. A project exempt from CEQA under Section 15269(d) must also be in conformance with the following requirements:

- (1) The project is within the existing right of way.
  The project area is located entirely within the Agency's existing right of way, including within temporary construction easements previously obtained by the Agency, as illustrated in the attached project plans in Attachment C.
- (2) The project is initiated within one year of the damage occurring.

  The damage to Lockwood Valley Road occurred during the storm events of February 2024. The development of construction plans for the repair and the initiation of the environmental approval process have occurred within 12 months of the initial damage. Therefore, the proejct has been initiated within one year of the damage occurring.
- (3) The project is not located on a highway designated as official state scenic highways.

<sup>&</sup>lt;sup>1</sup> Ventura County Watershed Protection District. 2019. Water Diversion Guide for the Ventura County Maintenance Program EIR. December 2007.



Lockwood Valley Road is not designated as an official state scenic highway<sup>2</sup>.

(4) The project is not undertaken to expand or widen a damaged highway.

The project would restore the road to its original condition with the addition of stormwater management and erosion control features. As shown in the project plans in Attachment C, the project would not add extra lanes. Following construction, lanes would be restored to their original widths.

#### Conclusion

Based on the analysis documented in this memorandum, the proposed Lockwood Valley Road Emergency Repairs Project meets all criteria for a Statutory Exemption under CEQA Guidelines Section 15269(d). Therefore, it is concluded that the project is statutorily exempt from CEQA.

Sincerely,

**Rincon Consultants, Inc.** 

Taylor Freeman, MEERM Senior Project Manager Kim Avila, AICP ENV SP Principal

<sup>&</sup>lt;sup>2</sup> California Department of Transportation. 2019. California State Scenic Highway System Map. Available: <a href="https://caltrans.maps.arcgis.com/apps/webappviewer/index.html?id=465dfd3d807c46cc8e8057116f1aacaa">https://caltrans.maps.arcgis.com/apps/webappviewer/index.html?id=465dfd3d807c46cc8e8057116f1aacaa</a>.

### **Attachment A**

Figures








Figure 2 Project Location Map, MP 1.75






Figure 3 Project Location Map, MP 12.69




Fig 2 Project Location MP 12.69 Lar

## **Attachment B**

Representative Site Photos



#### MP 1.75, Existing Conditions

Image 1: Lockwood Valley Road looking east, showing the fortified southern shoulder adjacent to the eastbound travel lane



Image 2: Lockwood Valley Road looking east, showing damage to the westbound travel lane





Image 3: Lockwood Valley Road looking west, showing initial damage immediately following the severe storm event





#### MP 12.69, Existing Conditions

Images 1 and 2: Looking northeast and northwest toward Lockwood Valley Road, showing the erosion and blown-out culvert on the southern side of the roadway.







Images 3 and 4: Looking southeast and southwest toward Lockwood Valley Road, showing the existing headwall on the northern side of the roadway.






# Appendix C

Project Plans

# **COUNTY OF VENTURA PUBLIC WORKS AGENCY** LOCKWOOK VALLEY ROAD EMERGENCY REPAIR

**MILEPOST 1.75 AND MILEPOST 12.69** 

**SPECIFICATION NO. RD24-XX** 



DEPUTY DIRECTOR, DESIGN DIVISION

**GENERAL NOTES:** 

COUNTY RIGHT OF WAY.

RIPRAP PLACEMENT AND CULVERT REPAIR.

DIRECTOR OF ROADS & TRANSPORTATION


DIRECTOR OF PUBLIC WORKS


**COUNTY OF VENTURA PUBLIC WORKS AGENCY ROADS & TRANSPORTATION** 

RD25-XX P6X50661

LOCKWOOD VLY. RD. EMERGENCY REPAIR **MILEPOST 1.75 AND MILEPOST 12.69** TITLE SHEET







HORIZONTAL DATUM - CCS83, ZONE 5, 2017.50 EPOCH (US FEET) PER CSRC PUBLICATION STATIONS CONNECTED

STATION N E ELEV DESCRIPTION LVMS 2091177.10 6230079.58 5167.82 Lockwood Valley NHRG 2005804.63 6217820.68 5520.58 NHRG\_SCGN\_CS2000 OZST 2073813.85 6154811.34 3583.56 OZST\_SCGN\_CS2000


VERTICAL DATUM - NAVD88 PER NGS DATA SHEET BENCHMARKS CONNECTED

STATION ELEV DESCRIPTION 5096 3935.35 BCM Z 594 5486 4880.63 BCM Z 1098 5488 4851.49 BCM H 595

CONVERGENCE ANGLE AND GRID FACTORS

CONVERGENCE ----- FACTORS -----SCALE X ELEVATION = COMBINED STATION ANGLE 5096 -0-43-51.39 0.99992251 0.99981679 0.99973932 -0-40-21.72 0.99992223 0.99977290 0.99969515

DISTANCES SHOWN HEREON ARE CCS83 ZONE 5 GRID DISTANCES. TO APPROXIMATE LOCAL GROUND DISTANCES DIVIDE THE DISTANCES BY THE COMBINED FACTOR.



PER CALTRANS STD.

PLAN A40D /

#### **CENTERLINE RUMBLE STRIP**

200'±

PER CALTRANS A40D & A40F

SURVEY CONTROL							
SURVEY PT.	NORTHING	EASTING	ELEV.	DESCRIPTION			
1001	2078082.52	6162305.18	3658.14	mag & tin flush in ac			
1002	2078088.58	6162049.14	3654.12	mag & tin flush in ac			
1003	2088940.65	6209496.20	4910.01	60D FLUSH DIRT			
1004	2089013.81	6209616.70	4914.87	60d flush in dirt			
3101	2078174.25	6162478.14	3655.29	60d flush in dirt			
3102	2078021.84	6162469.71	3661.22	60d flush in dirt			
3103	2078032.01	6162113.94	3654.66	60d flush in dirt			
3104	2078195.62	6162085.00	3651.86	60d flush in dirt			
3111	2089031.48	6209569.80	4923.33	60D FLUSH DIRT			
3112	2088908.78	6209587.04	4910.01	GCP			
3113	2088875.67	6209479.66	4893.12	60D FLUSH DIRT			
3114	2089030.24	6209482.93	4917.65	60D FLUSH DIRT			
POINTS NOT SHOWN ON PLAN							
3003	2077960.50	6164061.38	3685.89	60d flush in dirt			
5096	2079906.73	6176255.79	3935.35	BCM Z 594			
5483	2089585.68	6194352.57	4880.63	BCM Z 1098			
5488	2088237.65	6207066.56	4851.49	BCM H 595			

DESIGNED CHRISTOPHER SOLIS

CHECKED

APPROVED


JULIE STUART

XX

**COUNTY OF VENTURA PUBLIC WORKS AGENCY ROADS & TRANSPORTATION** 



LOCKWOOD VLY. RD. EMERGENCY REPAIR **MILEPOST 1.75 AND MILEPOST 12.69 SURVEY DATA AND MILEPOST 1.75 DETAILS** 



P6X50661

No. C 70776

EXP. 06/30/25

