PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT

Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001


May 19, 2026

Prepared by:



Steffany Aguilar, P.G.
Associate Geologist

Reviewed by:



Tina Huff, R.E.P.A., C.E.P,
Principal Regulatory Specialist

For:
Mileski Living Trust
1971 West 190th Street #100
Torrence, California, 90504

Submitted by:
Farallon Consulting, L.L.C.
1901 Harrison Street, Suite 1100
Oakland, California 94612

TABLE OF CONTENTS

ENVIRONMENTAL PROFESSIONAL STATEMENT iii

EXECUTIVE SUMMARY iv

1.0 INTRODUCTION 1-1
- 1.1 PROJECT AUTHORIZATION AND SCOPE OF WORK 1-1
- 1.2 PROFESSIONAL QUALIFICATIONS 1-1
- 1.3 PROJECT PURPOSE AND OBJECTIVE 1-1
- 1.4 SHELF LIFE OF ALL APPROPRIATE INQUIRIES RECORDS 1-3
- 1.5 DEVIATIONS 1-3
- 1.6 DATA GAPS 1-3

2.0 SUBJECT PROPERTY OVERVIEW 2-1
- 2.1 SUBJECT PROPERTY LOCATION 2-1
- 2.2 SUBJECT PROPERTY DESCRIPTION 2-1
- 2.3 SUBJECT PROPERTY OPERATIONS 2-1
- 2.4 ADJOINING AND SURROUNDING LAND USE 2-1

3.0 PHYSICAL SETTING 3-1
- 3.1 TOPOGRAPHY 3-1
- 3.2 GEOLOGY AND HYDROGEOLOGY 3-1
- 3.3 OIL AND GAS RECORDS 3-2
- 3.4 SENSITIVE RECEPTORS 3-3

4.0 USER-PROVIDED INFORMATION 4-1
- 4.1 TITLE AND LIEN RECORDS 4-1
- 4.2 EXPERIENCE AND SPECIALIZED KNOWLEDGE 4-1
- 4.3 COMMONLY KNOWN INFORMATION 4-1
- 4.4 PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT USERS 4-1
- 4.5 PREVIOUS ENVIRONMENTAL STUDIES 4-1

5.0 SUBJECT PROPERTY AND ADJOINING PROPERTY HISTORY 5-1
- 5.1 SUBJECT PROPERTY 5-1
- 5.2 ADJOINING PROPERTIES 5-2

6.0 STATE AND LOCAL GOVERNMENT AGENCY INTERVIEWS 6-1
- 6.1 STATE AGENCIES 6-1
- 6.2 SAN BERNARDINO COUNTY PLANNING AND BUILDING DEPARTMENT 6-1
- 6.3 SAN BERNARDINO COUNTY PUBLIC WORKS 6-1
- 6.4 SAN BERARDINO COUNTY ENVIRONMENTAL HEALTH SERVICES 6-1
- 6.5 SAN BERNARDINO COUNTY FIRE PROTECTION DISTRICT 6-2
- 6.6 CITY OF ADELANTO 6-2
- 6.7 LOCAL DRINKING WATER AUTHORITY 6-2

7.0 RECORDS REVIEW 7-1
- 7.1 SUBJECT PROPERTY LISTINGS 7-1

7.2 ADJOINING FACILITY LISTINGS 7-2
7.3 SURROUNDING FACILITY LISTINGS 7-5
7.4 UNPLOTTABLE LISTINGS 7-5

8.0 SUBJECT PROPERTY INTERVIEW(S) 8-1
8.1 INTERVIEW WITH SUBJECT PROPERTY REPRESENTATIVE 8-1

9.0 SITE RECONNAISSANCE 9-1
9.1 SITE RECONNAISSANCE METHODOLOGY 9-1
9.1.1 Limiting Conditions 9-1
9.2 INTERIOR OBSERVATIONS 9-1
9.3 EXTERIOR OBSERVATIONS 9-1
9.3.1 Exterior Observation Comments 9-2

10.0 FINDINGS AND OPINIONS 10-1

11.0 CONCLUSIONS 11-1

12.0 BIBLIOGRAPHY 12-1

13.0 LIMITATIONS 13-1
13.1 GENERAL LIMITATIONS 13-1
13.2 LIMITATION ON RELIANCE BY THIRD PARTIES 13-1

FIGURES

Figure 1 *Subject Property Vicinity Map*

Figure 2 *Subject Property Plan*

APPENDICES

Appendix A Professional Qualifications

Appendix B Subject Property Photographs

Appendix C User Questionnaire

Appendix D Environmental Database Report

ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as established in Part 312.10 of Title 40 of the Code of Federal Regulations (40 CFR 312.10) and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR 312.

Name	Steffany Aguilar, P.G.	Name	Tina Huff, R.E.P.A., C.E.P.
Title	Associate Geologist	Title	Principal Regulatory Specialist

EXECUTIVE SUMMARY

Farallon Consulting, L.L.C. (Farallon) has prepared this Phase I Environmental Site Assessment (ESA) Report for the Adelanto Gateway Logistics Center property in Adelanto, California (herein referred to as the Subject Property). The Phase I ESA was conducted by Steffany Aguilar and was reviewed and approved by Tina Huff. The Phase I ESA Report was prepared for Mileski Living Trust (Client and User) in accordance with ASTM International Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E1527-21). There were no deviations from ASTM E1527-21 during this Phase I ESA.

The Subject Property is 459.94 acres of land comprising 27 adjacent parcels, San Bernardino County Assessor Numbers 0459-841-01 to 0459-841-15 and 0459-451-51 to 459-451-62. The Subject Property consists of unimproved, undeveloped desert land with natural vegetation. Unimproved roadways along the Subject Property perimeters include Powerline Road, Adelanto Airport Road, an unnamed road, Joshua Avenue, Yucca Road, and Cobalt Road, and improved roadways along the perimeters include Adelanto Road and Air Base Road/Air Expressway Boulevard (referred to as Air Base Road in this report). No address is associated with the Subject Property. The Subject Property is located within a proposed commercial development referred to as the Adelanto Gateway Center.

At the time of the site reconnaissance, Farallon observed debris such as plastics, waste tires, and municipal waste, including paper and construction materials, along the Subject Property access roads. No evidence of release was observed.

Based on historical sources reviewed, the Subject Property has historically been largely undeveloped, with the exception of a rectangular area in the central portion that appeared to be graded and possibly used for agriculture purposes in a 1953 aerial photograph. By 1968, the former graded area was no longer present, and the Subject Property has appeared relatively unchanged since. Given the historical use of the Subject Property, it is possible that pesticides and other agricultural chemicals may have been applied to the property and residual soil impacts may be present. Although this historical use is not considered a recognized environmental condition, Farallon cannot confirm that shallow subsurface soil was not adversely impacted from the possible former application of pesticides and/or herbicides. Based on the intended future use of the Subject Property for commercial purposes, potential residual impacts associated with historical agricultural uses is considered a de minimis condition in connection with the Subject Property.

Adjoining properties at the time of Farallon's site reconnaissance included a mixture of undeveloped desert land, single family residences and industrial and commercial uses. According to signage observed along the Subject Property boundaries, petroleum pipeline easements exist along Air Base Road to the north and Adelanto Road to the west. The southeast-adjoining property boundary is bisected by a utility easement road consisting of a graded dirt road on which high-voltage electrical towers are present. A Kinder Morgan Terminal is located northwest-adjoining the Subject Property and an additional Kinder Morgan Terminal is located on the northeast-adjoining property across Air Base Road and is part of the larger Southern California Logistics Airport, formerly George Air Force Base Site (collectively GAFB). A DHL Supply chain northeast-adjoining the Subject Property across Air Base Road is also part of GAFB. Historically, adjoining properties included primarily undeveloped land prior to 1980 and development on the surrounding properties began in 1985 and continued up to the present. Due to the subsurface nature of underground pipelines, there is a potential for a release to occur. Current regulations require that hydrostatic testing be conducted at least every 5 years by an approved independent third party. Based on the likely implementation of integrity management plans for the active pipeline and regulatory oversight, the likelihood of a pipeline release in the vicinity of the Subject Property is considered low and does not represent a recognized environmental condition in connection to the Subject Property.

The Environmental Risk Information Services (ERIS) *Database Report* dated April 10, 2026, prepared for the Subject Property (ERIS Report), did not identify the Subject Property in the databases reviewed. Farallon searched the California State Water Resources Control Board GeoTracker database (GeoTracker database) and the California Department of Toxic Substances Control EnviroStor database for the Subject Property, but found no listings.

The ERIS Report identified several facilities adjoining or proximate to the Subject Property in regulatory databases. The north-northeast–adjoining property, GAFB, has known or suspected releases of hazardous substances to soil and/or groundwater. GAFB is a 5,347-acre property first developed in 1941, and the boundaries of GAFB include the north-northeast properties and east-adjoining corrections facility. Several chemical plumes exist in groundwater throughout GAFB, some of which are near the northern and eastern Subject Property boundaries. These chemical plumes are being remediated by the U.S. Department of Defense (DoD) under the oversight of the U.S. Environmental Protection Agency and the California Regional Water Quality Control Board. The chemical plumes appear isolated to GAFB in the Subject Property area, although groundwater flow patterns are complex due to

active pumping by DoD to clean up the chemical releases. The potential migration of hazardous substances in groundwater originating from the adjoining GAFB to the Subject Property represents a recognized environmental condition in connection with the Subject Property. Based on the down-gradient location with respect to groundwater, depth to groundwater in the region of greater than 100 feet below ground surface and information obtained from the GeoTracker database, releases from GAFB are not expected to pose a threat to human health for Subject Property occupants under a commercial land use.

Based on review of the Subject Property history, interviews with persons knowledgeable about the Subject Property, reconnaissance of the Subject Property, and review of the ERIS Report, this Phase I ESA identified the following environmental condition in connection with the Subject Property:

- The potential migration of hazardous substances in groundwater originating from the adjoining GAFB to the Subject Property.

1.0 INTRODUCTION

Farallon Consulting, L.L.C. (Farallon) has prepared this Phase I Environmental Site Assessment (ESA) Report for the Adelanto Gateway Logistics Center property in Adelanto, California (herein referred to as the Subject Property) (Figure 1). This section discusses the project authorization and scope of work, the qualifications of the Environmental Professionals who conducted and reviewed the Phase I ESA work, the project purpose and objective, the shelf life of records per the All Appropriate Inquiries (AAI) Final Rule established in Part 312.10 of Title 40 of the Code of Federal Regulations (40 CFR 312.10), deviations, and data gaps.

1.1 PROJECT AUTHORIZATION AND SCOPE OF WORK

This Phase I ESA Report was prepared for Mileski Living Trust (Client and User) in accordance with the letter regarding Proposal for Phase I Environmental Site Assessment, Adelanto Gateway Logistics Center, Air Expressway Boulevard/Adelanto Road, Adelanto, California dated March 30, 2026, from Steffany Aguilar and Tina Huff of Farallon to Michael Mileski of Mileski Living Trust (Authorization). The scope of work for this Phase I ESA included a records review, literature research and review, a site reconnaissance, interviews with individuals familiar with the Subject Property, interviews with local governmental officials, and preparation of this report. The scope of work is consistent with ASTM International Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM E1527-21).

1.2 PROFESSIONAL QUALIFICATIONS

The Phase I ESA was conducted by Steffany Aguilar and was reviewed and approved by Tina Huff. Both have an understanding of surface and subsurface environmental conditions and the processes used to evaluate these conditions, and the ability to develop opinions regarding conditions indicative of a release or a threatened release of hazardous substances and petroleum products. AAI has been performed in conformance with the standards and practices set forth in 40 CFR 312.10. The professional qualifications of the Environmental Professionals are provided in Appendix A.

1.3 PROJECT PURPOSE AND OBJECTIVE

The purpose of the Phase I ESA was to identify, as practicable, recognized environmental conditions at the Subject Property and within the appropriate study area that have caused and/or may cause an adverse environmental impact. ASTM E1527-21 is intended to permit

a user to satisfy one of the requirements to qualify for protection from potential liability under the Comprehensive Environmental Response, Compensation, and Liability Act as the innocent landowner, contiguous property owner, or bona fide prospective purchaser. ASTM E1527-21 constitutes "all appropriate inquiry" into the previous ownership, uses, and environmental conditions of a property consistent with good commercial or customary practice, as defined in Section 9601(35)(B) of Title 42 of the U.S. Code.

The objective of the Phase I ESA was to perform an appropriate inquiry into past and present ownership and uses of the Subject Property, consistent with good commercial and/or customary practice. This Phase I ESA Report is to be used as a risk management tool to meet AAI Final Rule requirements and the Comprehensive Environmental Response, Compensation, and Liability Act liability defense. The Phase I ESA does not guarantee that there are no impacts to the Subject Property.

For the purpose of this Phase I ESA Report, the term "recognized environmental condition" is defined as (1) the presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the Subject Property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the Subject Property under conditions that pose a material threat of a future release to the environment. A de minimis condition is not a recognized environmental condition.

The term "controlled recognized environmental condition" is defined as a recognized environmental condition affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities, with hazardous substances or petroleum products allowed to remain in-place subject to implementation of required controls.

The term "historical recognized environmental condition" is defined as a previous release of hazardous substances or petroleum products affecting the Subject Property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the Subject Property to any controls (e.g., activity and use limitations or other property use limitations). A historical recognized environmental condition is not a recognized environmental condition.

1.4 SHELF LIFE OF ALL APPROPRIATE INQUIRIES RECORDS

The AAI Final Rule prepared by the U.S. Environmental Protection Agency (EPA)[1] specifies that AAI must be conducted within 1 year prior to the date of acquisition of the Subject Property. EPA has defined the date of acquisition as the date a person acquires title to the property. To ensure full coverage under the AAI Final Rule, a valid Phase I ESA Report must be completed within 1 year prior to the date of acquisition of title.

The following Phase I ESA Report components and supporting information sources must be updated if they were completed more than 6 months (180 days) prior to acquisition of title. The date on the cover of this Phase I ESA Report is the production date of the written report. The Phase I ESA components with a 180-day shelf life consist of:

Phase I ESA Component:	Date Completed:	Expiration Date:
Site Reconnaissance	April 8, 2026	October 5, 2026
Subject Property interview(s)	April 9, 2026	October 6, 2026
User-Provided Information	April 9, 2026	October 6, 2026
Review of government regulatory records	April 10, 2026	October 7, 2026
Declaration/signature of certifying Environmental Professional	May 19, 2026	November 15, 2026

1.5 DEVIATIONS

There were no deviations from ASTM E1527-21 during this Phase I ESA.

1.6 DATA GAPS

Data gaps may affect the ability to identify recognized environmental conditions and Farallon's ability to render opinions and conclusions for presentation in the Phase I ESA Report. Farallon did not identify significant data gaps during this Phase I ESA.

[1] Part 312 of Subchapter J of Chapter I of Title 40 of the Code of Federal Regulations.

2.0 SUBJECT PROPERTY OVERVIEW

This section presents the Subject Property location, description, and operations. A description of adjoining and surrounding land use is also provided.

2.1 SUBJECT PROPERTY LOCATION

The Subject Property is southeast of the intersection of Adelanto Road and Air Base Road/ Air Expressway (referred to as Air Base Road in this report) and northwest of the intersection of Powerline Road and Cobalt Road in Adelanto, San Bernardino County, California. No address is associated with the Subject Property. The Subject Property is in a primarily undeveloped area with sporadic commercial and industrial uses approximately 1 mile southeast of downtown Adelanto. The Subject Property is located within a proposed commercial development referred to as the Adelanto Gateway Center. The Subject Property vicinity is shown on Figure 1.

2.2 SUBJECT PROPERTY DESCRIPTION

The Subject Property is 459.94 acres of land comprising 27 adjacent parcels, San Bernardino County Assessor Numbers 0459-841-01 to 0459-841-15 and 0459-451-51 to 459-451-62. The Subject Property consists of unimproved, undeveloped desert land with natural vegetation. Unimproved roadways along the Subject Property perimeters include Powerline Road, Adelanto Airport Road, an unnamed road, Joshua Avenue, Yucca Road, and Cobalt Road, and improved roadways along the perimeters include Adelanto Road and Air Base Road. According to the San Berardino County Assessor's Office, the Subject Property owner is Adelanto Industrial LLC, and the Subject Property is zoned "Industrial."

Figure 2 presents a plan map of the Subject Property. Additional details pertaining to the Subject Property are provided in Section 9, Site Reconnaissance. Subject Property photographs are presented in Appendix B.

2.3 SUBJECT PROPERTY OPERATIONS

The Subject Property is undeveloped desert land.

2.4 ADJOINING AND SURROUNDING LAND USE

Adjoining properties at the time of the site reconnaissance included a mixture of undeveloped desert land, single family residences, and industrial and commercial uses. According to signage observed along the Subject Property boundaries, petroleum pipeline

easements exist along Air Base Road to the north and Adelanto Road to the west. The southeast-adjoining property boundary is bisected by a utility easement road consisting of a graded dirt road on which high-voltage electrical towers are present. A Kinder Morgan Terminal is located northwest-adjoining the Subject Property and an additional Kinder Morgan Terminal is located on the northeast-adjoining property across Air Base Road and is part of the larger Southern California Logistics Airport, formerly George Air Force Base Site (collectively GAFB). A DHL Supply chain northeast-adjoining the Subject Property across Air Base Road is also part of GAFB. A Federal Correction Complex and undeveloped land adjoin the Subject Property to the east. Adjoining commercial and industrial businesses to the south, west, and northwest include Mobile Pipe Lining & Coating, Valley Quality Truck Bodies, XPO & Fast Lane Transportation, United Truck Trailer Storage Yard, Soil Safe of California, Toads Pad, High Desert Recycling/Adelanto Metal Recycling, MT Truck and Trailer Repair, Jet Room Dispensary & Lounge, Miguelito's Restaurant, Frontier, Yoly's Taqueria, and GM Precision Metal Spinning adjoin

Observations were restricted to areas readily observable from the Subject Property and to public rights-of-way. No evidence of recognized environmental conditions was observed on adjoining or nearby properties during the site reconnaissance.

3.0 PHYSICAL SETTING

The topography, geology, and hydrogeology of the Subject Property are described in this section. Farallon's assessment of sensitive receptors in the area is also discussed. Farallon reviewed the following physical setting sources as part of this Phase I ESA:

- U.S. Geological Survey (USGS) topographic maps of Adelanto, California dated 1956, 1968, 1980, 1993;
- The EDR *Radius Map Report with GeoCheck* dated September 21, 2015, prepared for the Subject Property (EDR Report); and/or
- Documentation of previous environmental studies referenced in Section 4.5, Previous Environmental Studies, and/or documents cited in Section 7, Records Review.

3.1 TOPOGRAPHY

Farallon reviewed the USGS topographic maps for the Subject Property area provided by EDR. The maps depict the Subject Property at an elevation of approximately 2,919 feet above mean sea level. Subject Property topography is relatively flat. Regional topography is generally flat, with a slight slope down to the north and northeast.

3.2 GEOLOGY AND HYDROGEOLOGY

The Subject Property is in the southwestern portion of the Mojave Desert geomorphic province of Southern California. The Mojave Desert is a 25,000-square-mile landlocked desert formed from movement along the San Andreas and Garlock faults on the southern portion of the Basin and Range Province. The Mojave Desert is enclosed to the southwest by the San Andreas Fault and the Transverse Ranges and on the north and northeast by the Garlock Fault, the Tehachapi Mountains, and the Basin and Range Province. The Subject Property area is in the eastern portion of the Mojave Desert known as the Victor Valley, which consists of a broad alluvial basin filled mainly with non-marine continental deposits from adjacent lands. The Subject Property is located north of the San Bernardino Mountains in a relatively flat plain that gently dips to the north toward the Tehachapi Mountains.

According to the *Phase I Environmental Site Assessment, Proposed Adelanto Gateway Center, Adelanto, California* dated June 13, 2007, prepared by URS Corporation (URS) (2007 Phase I ESA), the Subject Property is underlain by undifferentiated Quaternary (recent) alluvium and alluvial wash deposits deposited on Pleistocene through Paleozoic

marine and non-marine clastic sedimentary, volcanic, and meta-sedimentary rocks. This general area is structurally complex with a series of northerly plunging folds and northwest-trending faults primarily from the San Andreas and Garlock Fault Zones. According to the City of Adelanto Building and Safety Department, the Subject Property is not located within a fault ruptured hazard zone, as defined in the Alquist-Priolo Earthquake Fault Zoning Act.

According to documents obtained from the GeoTracker database for GAFB , soil in the Subject Property vicinity is mapped as well-drained, nearly level soil (0 to 2 percent slopes) on terraces and broad, nearly level alluvial fans in the Bryman Series mapping unit. This soil is described as pale brown to light-yellow brown loamy fine sand and brown sandy loam and reddish-brown sandy clay loam underlain by various sandy loam layers to approximately 7 feet below ground surface (bgs).

According to the City of Adelanto, potable water supplied to the Subject Property area is obtained from deep groundwater wells in the underlying Upper Mojave River Basin, Alto Subarea. According to the 2007 Phase I ESA a groundwater well was formerly present near the southwestern boundary of the Subject Property. The groundwater well was destroyed in 2004, but the depth to groundwater at the well was recorded to be 330 feet bgs between the years 1995 and 2001.

According to information provided for adjoining properties, discussed in Section 7.2, Adjoining Facility Listings, groundwater in the vicinity of the Subject Property flows to the north-northeast and is influenced by groundwater cleanup actions being performed at GAFB by the U.S. Department of Defense (DoD), and groundwater is encountered at depths greater than 100 feet bgs.

3.3 OIL AND GAS RECORDS

Farallon reviewed the California Department of Conservation, Geologic Energy Management Division (CalGEM) Well Finder online database for records pertaining to the presence of oil and gas fields and associated wells on the Subject Property and surrounding properties. According to the CalGEM Well Finder database, no oil or gas wells are located on or near the Subject Property.

Farallon conducted a review of the National Pipeline Mapping System (NPMS) for records pertaining to pipelines that may impact the Subject Property. According to NPMS, an active jet fuel (non-Highly Volatile Liquid) Kinder Morgan pipeline is located to the west and northwest of the Subject Property in the adjoining right-of way. This section of the pipeline is

operated by CalNev Pipeline Company. No violations and/or releases have been reported for this section of the pipeline and no stressed vegetation or other evidence of a release was observed along the pipeline easement or at the northwest adjoining Kinder Morgan Terminal during the site reconnaissance.

Due to the subsurface nature of underground pipelines, there is a potential for a release to occur. Current regulations require that hydrostatic testing be conducted at least every 5 years by an approved independent third party. Based on the likely implementation of integrity management plans for the active pipeline and regulatory oversight, the likelihood of a pipeline release in the vicinity of the Subject Property is considered low and does not represent a recognized environmental condition in connection to the Subject Property.

3.4 SENSITIVE RECEPTORS

No sensitive receptors were identified on or adjoining the Subject Property at the time of the site reconnaissance. According to the EDR Report, the Subject Property is in a 500-year flood plain. No federally designated wetlands are located within 1 mile of the Subject Property. No public water or irrigation supply wells were identified within 1 mile of the Subject Property. Two private domestic water supply wells were identified on the east-adjoining property. The water body nearest the Subject Property was identified as an unidentified dry riverbed located on an adjacent property across Airport Expressway Boulevard to the north.

4.0 USER-PROVIDED INFORMATION

Farallon understands that the User of this report is seeking to follow the standards set forth in ASTM E1527-21 to complete an environmental assessment of the Subject Property. The User has specific responsibilities for fulfilling ASTM E1527-21 requirements to help identify the possibility of recognized environmental conditions in connection with the Subject Property. These responsibilities do not require the technical expertise of an Environmental Professional, and were not performed by Farallon.

To facilitate fulfillment of the ASTM E1527-21 requirements identified below, Farallon provided the User with a copy of the *Phase I Environmental Site Assessment User Questionnaire* (User Questionnaire) to complete. Information from the completed User Questionnaire is summarized below in Sections 4.1 through 4.3. The completed User Questionnaire is provided in Appendix C of this Phase I ESA Report.

4.1 TITLE AND LIEN RECORDS

The User was not aware of environmental liens against the Subject Property.

4.2 EXPERIENCE AND SPECIALIZED KNOWLEDGE

The User has no experience or specialized knowledge regarding the Subject Property.

4.3 COMMONLY KNOWN INFORMATION

The User is not aware of commonly known information that would lead to identification of recognized environmental conditions in connection with the Subject Property.

4.4 PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT USERS

The User will rely on this Phase I ESA Report.

4.5 PREVIOUS ENVIRONMENTAL STUDIES

Farallon was provided with the 2007 Phase I Report and the *Phase I Environmental Site Assessment Report Adelanto Gateway Center, Air Expressway Boulevard/Adelanto Road, Adelanto, California* dated October 21, 2015, prepared by Farallon (2015 Phase I Report), which included the Subject Property. These reports are summarized below.

At the time of the 2007 and 2015 Phase I ESAs, the Subject Property consisted of undeveloped desert land, similar to the present. The 2007 and 2015 Phase I ESAs identified the following recognized environmental condition in connection with the Subject Property:

The Subject Property is located in close proximity to the southern boundary of the former GAFB, which is a National Priority List (NPL) site. While GAFB is suspected to exist in a down-gradient orientation from the Subject Property, groundwater beneath the Subject Property may be impacted by industrial constituents originating from GAFB. The 2007 and 2015 Phase I Reports concluded that based on the on the depth to groundwater in the region of greater than 100 feet bgs and information obtained from the California Water Resources Control Board GeoTracker database (GeoTracker database), releases from GAFB are not expected to pose a threat to human health for Subject Property occupants under a commercial land use.

5.0 SUBJECT PROPERTY AND ADJOINING PROPERTY HISTORY

Farallon reviewed the historical sources listed below as part of this Phase I ESA. The historical sources documented were reasonably ascertainable and practically reviewable during this Phase I ESA. Farallon is not responsible for the accuracy or completeness of the historical sources reviewed.

- Aerial photographs of the Subject Property and its vicinity dated 1953, 1968, 1980, 1989, 1994, and 2002 obtained from EDR; and dated 1985, 1994, 2005, 2006, 2009, 2013, 2015 through 2018, and 2022 through 2025 obtained from Google Earth; and
- USGS topographic maps of Adelanto, California dated 1956, 1968, 1980, 1993.

A search for fire insurance maps resulted in notification that there was no coverage for the Subject Property.

No historical sources from 1940 to 1953 were available for review, which represents a historical data failure for this report. Based on the lack of development on the Subject Property, this data gap is not expected to affect the conclusions of this Phase I ESA Report.

5.1 SUBJECT PROPERTY

In the 1953 aerial photograph, the Subject Property appears to consist of vacant land in its natural state, with the exception of a rectangular area in the central portion that appeared to be graded and possibly used for agriculture purposes. A dirt road running west-east bisects the graded area and several small, dark rectangles are visible, possibly small residences and/or storage structures. In the 1953 aerial photograph unimproved roads including Yucca Road and Cobalt Road were present. By 1968 the formerly graded portion appeared to be desert land and structures were no longer present, and the Subject Property has appeared relatively unchanged to the present.

Given the historical use of the Subject Property, it is possible that pesticides and other agricultural chemicals may have been applied to the property and residual soil impacts may be present. Although this historical use is not considered a recognized environmental condition, Farallon cannot confirm that shallow subsurface soil was not adversely impacted from the possible former application of pesticides and/or herbicides. Based on the intended future use of the Subject Property for commercial purposes, potential residual impacts

associated with historical agricultural uses is considered a de minimis condition in connection with the Subject Property.

Additional information regarding the Subject Property history is provided in Section 4.5, Previous Environmental Studies.

5.2 ADJOINING PROPERTIES

Adjoining properties appeared to primarily consist of undeveloped land in its natural state from at least 1953 through 1980, with the exception of the high-voltage power lines on the southeast-adjoining property, and a small structure and well on the east-adjoining property. Commercial and industrial activities were first evident on the south-adjoining property in the 1985 aerial photograph, with continued development and adjoining properties appeared similar to the present by 2025. The Federal Correctional Complex was present east-adjoining the Subject Property by 2005.

Additional information regarding adjoining properties is provided in Section 4.5, Previous Environmental Studies, and Section 7.2, Adjoining Facility Listings.

6.0 STATE AND LOCAL GOVERNMENT AGENCY INTERVIEWS

The objective of interviews with state and/or local government agencies is to obtain information related to recognized environmental conditions in connection with the Subject Property. The interviews consist of questions asked in person, or by email, telephone, and/or online request for records.

Farallon contacted the agencies listed in this section to inquire whether notices of violations and/or reported hazardous spills at the Subject Property were on file, regarding previous and current aboveground storage tanks (ASTs) and underground storage tanks (USTs) at the Subject Property, and/or other records that may contain information related to recognized environmental conditions in connection with the Subject Property.

6.1 STATE AGENCIES

Farallon conducted a review of the California Environmental Reporting System (CERS) Regulated Site Portal (Portal) maintained by the California Environmental Protection Agency (CalEPA) on April 16, 2026 for records pertaining to facilities on the Subject Property and surrounding properties. Numerous listings of regulated entities were identified in the vicinity of the Subject Property. Regulatory oversight and enforcement of these facilities is generally conducted by the local Certified Unified Program Agency (CUPA). The CUPA with jurisdiction over the Subject Property and surrounding properties is identified as the San Bernardino County Fire Protection District, which is discussed in Sections 6.5, San Bernardino County Fire Protection District, and 7, Records Review.

6.2 SAN BERNARDINO COUNTY PLANNING AND BUILDING DEPARTMENT

On April 7, 2026, a representative of the San Bernardino County Planning and Building Department stated that it had no records associated with the Subject Property.

6.3 SAN BERNARDINO COUNTY PUBLIC WORKS

On April 6, 2026, a representative of the San Bernardino County Public Works Department stated that it had no records associated with the Subject Property.

6.4 SAN BERARDINO COUNTY ENVIRONMENTAL HEALTH SERVICES

On April 6, 2026, a representative of the San Berardino County Environmental Health Services stated that it had no records associated with the Subject Property.

6.5 SAN BERNARDINO COUNTY FIRE PROTECTION DISTRICT

On April 6, 2026 a representative of San Bernardino County Fire Protection District requested a fee to begin the process review for records and did not state if any records were available. However, according to the 2015 Phase I Report, at the time the San Bernardino County Fire Protection District stated that it had no records associated with the Subject Property.

6.6 CITY OF ADELANTO

On April 9, 2026, Farallon was provided with the following documentation supporting the proposed development of the Subject Property from the City of Adelanto Engineering and Building Departments, none of which suggested a recognized environmental condition in connection with the Subject Property:

- Cultural Resources Inventory, Biological Resources Report, Sewer Capacity Memo, Tentative Parcel Map, development plans, hazardous waste site certification, and development application.

6.7 LOCAL DRINKING WATER AUTHORITY

Farallon reviewed the 2024 Consumer Confidence Report for the City of Adelanto to determine whether drinking water is monitored for per- and polyfluoroalkyl substances (PFAS) and if there have been any detections of PFAS in the public drinking water system that supplies the Subject Property. The 2024 Consumer Confidence Report indicated the City of Adelanto monitors PFAS in drinking water supplied to the Subject Property and PFAS are not present at concentrations that exceed the response level in the drinking water system.

7.0 RECORDS REVIEW

ERIS conducted a review of environmental regulatory agency database listings to identify reported environmental issues related to the Subject Property and facilities in the Subject Property vicinity. Pertinent regulatory files and/or records associated with the listings that were reasonably ascertainable during this Phase I ESA were reviewed by Farallon. Farallon used the greater of each approximate minimum search distance from the Subject Property for each of the referenced federal and state environmental databases, as specified in ASTM E1527-21.

Farallon reviewed the ERIS *Database Report* dated April 10, 2026, prepared for the Subject Property (ERIS Report), to note reported facilities in the vicinity of the Subject Property that were considered to have a potential to adversely impact the Subject Property (i.e., are known to have resulted in or are expected to result in a recognized environmental condition). Reported facilities were evaluated with respect to the nature and extent of a given release, the distance of the reported facility from the Subject Property, the geology of the area, and the topographic position of a reported facility with respect to known or expected local and/or regional groundwater flow direction.

Farallon searched the GeoTracker database, and the California Department of Toxic Substances Control EnviroStor Database (EnviroStor database), and adjoining and vicinity properties. Farallon requested regulatory files for the Subject Property, all adjoining properties, and cleanup sites within 0.25 mile up-gradient or 0.125 mile cross-gradient of the Subject Property.

The complete database names for the abbreviations used in this Phase I ESA Report, the descriptions of the databases searched, and the associated search distances from the Subject Property are provided in the ERIS Report presented in Appendix D.

7.1 SUBJECT PROPERTY LISTINGS

The ERIS Report did not identify the Subject Property in the databases reviewed.

Additional information regarding the Subject Property is provided in Section 4.5, Previous Environmental Studies.

7.2 ADJOINING FACILITY LISTINGS

ASTM defines "adjoining" as "any real property or properties the border of which is contiguous or partially contiguous with that of the Subject Property, or that would be contiguous or partially contiguous with that of the Subject Property but for a street, road, or other public thoroughfare separating them."

The ERIS Report identified the following adjoining facilities in the databases reviewed.

GAFB (Including Kinder Morgan/Calnev Terminal) at Air Base Road/17374 Phantom West Street/13334 Air Express Way, north-northeast–adjoining the Subject Property and down-gradient with respect to estimated groundwater flow direction, was identified in the NPL, FINDS FRS, RESPONSE, CERCLIS, CLEANUP SITES, DEED, FED ENG, FED INST, PFAS NPL, SUPERFUND ROD databases. According to the GeoTracker database, GAFB is a 5,347-acre property first developed in 1941 and the boundaries of GAFB include the east-adjoining corrections facility. In 1941 the facility was the as Victorville Army Airfield and from 1950 to 1992, GAFB was a tactical jet fighter operation training facility. Several chemical plumes exist in groundwater throughout GAFB, some of which are near the northern and eastern Subject Property boundaries. These chemical plumes are being remediated by the U.S. Department of Defense (DoD) under the oversight of EPA and the California Regional Water Quality Control Board. The chemical plumes appear isolated to GAFB in the Subject Property area, although groundwater flow patterns are complex due to active pumping by DoD to clean up the chemical releases. The potential migration of hazardous substances in groundwater originating from the adjoining GAFB to the Subject Property represents a recognized environmental condition in connection with the Subject Property. Based on the down-gradient location with respect to groundwater, the depth to groundwater in the region of greater than 100 feet bgs, and information obtained from the GeoTracker database, releases from GAFB are not expected to pose a threat to human health for Subject Property occupants under a commercial land use.

Victorville City Fire formerly at Air Base Road and Phantom Street, north-northeast–adjoining the Subject Property and down-gradient with respect to estimated groundwater flow direction, was identified in the CHMIRS database. According to the ERIS Report, on January 22, 1999 a truck hauling material to an incinerator facility inadvertently dumped the material to the roadway. The material was subsequently cleaned up under the oversight of San Bernardino County Fire Department. Based on regulatory status and the down-gradient

location of this reported incident with respect to groundwater flow, this incident does not represent a recognized environmental condition in connection with the Subject Property.

Hazmat One formerly at Air Base Road, north-northeast–adjoining the Subject Property and down-gradient with respect to estimated groundwater flow direction, was identified in the CHMIRS database. According to the ERIS Report, on February 24, 2014 a mechanical failure on a big rig punctured a saddle tank resulting in the release of approximately 100 to 150 gallons of diesel onto the ground; the release was contained and cleaned up, with no waterways impacted. Based on the regulatory status and the down-gradient location of this reported incident with respect to groundwater flow, this incident does not represent a recognized environmental condition in connection with the Subject Property.

Federal Corrections Facility currently at 13289 Air Base Road, east-adjoining the Subject Property and at a lower elevation, was identified in the HAZ GEN database. According to the ERIS Report, the facility generated 6.9 tons of asbestos-containing wastes and disposed of the wastes at a landfill. Based on the lack of reported violations and down-gradient location relative to the Subject Property, this facility does not represent a recognized environmental condition in connection with the Subject Property.

Verizon/Frontier currently at 17640 Adelanto Road, west-adjoining the Subject Property and at a lower elevation, was identified in the CHMIRS, EMISSIONS, FINDS/FRS, HAZ GEN, HAZNET, HIST MANIFEST, UST and SANBERN CUPA databases. According to the ERIS Report, the facility, which operates as a high-speed internet and phone provider, is a generator of hazardous waste and handler of hazardous materials, including a permitted diesel AST, with no reported violations. There was a report of a small, remediated spill. Based on the lack of reported violations and down-gradient location relative to the Subject Property, this facility does not represent a recognized environmental condition in connection with the Subject Property.

Mobile Pipe Wrappers currently at 12766 Violet Road, south-adjoining the Subject Property and up-gradient with respect to estimated groundwater flow direction, was identified in the AFS, CERS HAZ, EMISSIONS, FINDS/FRS, HAZ GEN, HAZNET, ICIS, RCRA NON-GEN and SANBERN CUPA databases. According to the ERIS Report, the pipe lining and coating facility facility is a generator of hazardous waste and handler of hazardous material, with no active reported violations as of November 2025. The previous violations listed in the databases relate to handling, storing, and disposing of hazardous materials and waste with no significant violations indicated in the databases. Based on the lack of significant violations,

this facility does not represent a recognized environmental condition in connection with the Subject Property.

Kinder Morgan/Calnev Terminal currently at Air Base Road and Aelanto Road, northwest-adjoining the Subject Property and cross-gradient with respect to estimated groundwater flow direction, was identified in the RCRA NON GEN database. According to the ERIS Report, there are no reported violations as of November 2025. Based on the lack of reported violations, this facility does not represent a recognized environmental condition in connection with the Subject Property.

DHL/United Furniture Industries currently at 13133 Innovation Way, north-adjoining the Subject Property and down-gradient with respect to estimated groundwater flow direction, was identified in the CERS HAZ, EMISSIONS, RCRA NON GEN, and SANBERN CUPA. According to the ERIS Report, the distribution center facility is a generator of hazardous waste, with no reported violations as of November 2025. Based on the lack of significant violations and down-gradient location relative to the Subject Property, this facility does not represent a recognized environmental condition in connection with the Subject Property.

Soil Safe/TPS Technologies currently at 12328 Hibiscus Avenue, south-adjoining the Subject Property and up-gradient with respect to estimated groundwater flow direction, was identified in the PFAS IND, AST, C&D DEBRIS RECY, CERS TANK, EMISSIONS, HWP, LDS, RCRA NON GEN, SANBERN CUPA, SWF/LF databases. According to the ERIS Report this facility is a non-hazardous petroleum contaminated soil recycler that is monitored by various regulatory agencies, including the Regional Water Quality Control Board and the Mojave Desert Air Quality Management District, with no significant violations indicated in the databases. Previous violations identified in the ERIS Report were resolved and there are no reported active violations as of September 2024. Quarterly groundwater monitoring is conducted at the facility for compliance. According to Soil Safe's website, the company has operated as a thermal desorption facility since 1992. Based on the lack of reported violations, this facility does not represent a recognized environmental condition in connection with the Subject Property.

High Desert Recycling/Adelanto Metal Recycling currently at 12325 Hibiscus Avenue, south-adjoining the Subject Property and up-gradient with respect to estimated groundwater flow direction, was identified in the RCRA NON GEN and SANBERN CUPA databases. According to the ERIS Report, the facility was a metal recycling facility with no reported violations as of

November 2025. Based on the lack of reported violations, this facility does not represent a recognized environmental condition in connection with the Subject Property.

7.3 SURROUNDING FACILITY LISTINGS

Reported facilities within 0.25 mile up-gradient or 0.125 mile cross-gradient of the Subject Property are considered to have a potential to have impacted the Subject Property, depending on the depth and the directional flow of groundwater. Facilities commonly known to be potential PFAS sources and that are within 1 mile up-gradient of the Subject Property were evaluated for the potential to impact the Subject Property. Facilities that were listed in the ERIS Report but not identified as a reported facility (e.g., a facility listed as a hazardous waste generator but not as having had a release), and facilities that were listed as "Closed" were not considered to have a potential to have impacted the Subject Property.

Based on the information provided in the ERIS Report and regulatory files, their topographic location and distance relative to the Subject Property, and/or known or presumed soil and groundwater conditions in the vicinity of the Subject Property, none of the surrounding facilities identified was considered to represent a recognized environmental condition in connection with the Subject Property.

7.4 UNPLOTTABLE LISTINGS

Listings or facilities that cannot be mapped due to inaccurate or inadequate address information are identified as "unplottable" in the ERIS Report. The ERIS Report identified 141 unplottable facilities. Farallon located these unplottable facilities and, according to the information provided by ERIS, they are not located within 0.25 mile up-gradient or 0.125 mile cross-gradient search radii or associated listings were related to minor releases on public roadways that were cleaned up with no additional action required, or they were associated with GAFB. The unplottable facilities located (except those that are part of GAFB) do not represent a recognized environmental condition in connection with the Subject Property.

8.0 SUBJECT PROPERTY INTERVIEW(S)

Farallon attempted to interview individuals familiar with the Subject Property, including owners, operators, and occupants, to obtain additional Subject Property information. Interviews were conducted in person, in writing, or by telephone. The individual(s) interviewed, and their responses are discussed in the following sections.

8.1 INTERVIEW WITH SUBJECT PROPERTY REPRESENTATIVE

On April 8, 2026, Farallon interviewed Jessica Haughton, Project Manager at Synergy Consulting and representative of the Subject Property. The following information was obtained from this interview:

- Jessica Haughton is a project manager at Synergy Consulting, which is managing the Mileski Living Trust.
- No known ASTs or USTs are present at the Subject Property.
- No hazardous materials are present at the Subject Property.
- No utilities are provided to the Subject Property.
- The Subject Property was formerly owned by Prologis.
- PFAS have not been manufactured, stored, and/or handled at the facility.
- No reportable spills or releases have occurred at the Subject Property.

Jessica Haughton stated on behalf of the Subject Property owner that there have not been any pending, threatened, or past:

- Litigation relevant to hazardous substances or petroleum products in, on, or from the Subject Property;
- Administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the Subject Property; or
- Notices from a governmental entity regarding violations of environmental laws or liability relating to hazardous substances or petroleum products.

9.0 SITE RECONNAISSANCE

Farallon conducted a site reconnaissance on April 8, 2026 to observe the Subject Property for physical evidence of recognized environmental conditions. The methodology used for the site reconnaissance and the observations made and limiting conditions encountered are discussed below. Photographs taken during the site reconnaissance are presented in Appendix B.

9.1 SITE RECONNAISSANCE METHODOLOGY

Weather conditions at the time of the reconnaissance were sunny, with a temperature of approximately 70 degrees Fahrenheit. Farallon conducted a walk around the entire perimeter of the Subject Property.

9.1.1 Limiting Conditions

A limiting condition encountered during this Phase I ESA was the presence of vegetation that prevented Farallon from observing the entire ground surface of the Subject Property. Based on information obtained from the Subject Property representative, this limiting condition is not expected to affect the conclusions of this Phase I ESA Report.

9.2 INTERIOR OBSERVATIONS

No buildings were present on the Subject Property at the time of Farallon's site reconnaissance.

9.3 EXTERIOR OBSERVATIONS

Farallon's comments related to observations of the exterior of the Subject Property during the site reconnaissance are provided in Section 9.3.1.

EXTERIOR OBSERVATIONS	YES	NO
Odor(s)		X
Staining and/or Corrosion		X
Storage Tank(s), Vent Pipe(s), and/or Fuel Port(s)		X
Clarifier(s)		X
Drum(s) and/or Other Container(s)		X
Pool(s) of Liquid		X
Hazardous Material(s) and/or Petroleum Product(s)		X

EXTERIOR OBSERVATIONS	YES	NO
Hazardous Waste(s)		X
Pit(s), Pond(s), and/or Lagoon(s)		X
Stressed Vegetation		X
Solid (Nonhazardous) Waste(s)—Evidence of Dumping	X	
Wastewater		X
Domestic Water		X
Well(s)		X
Septic/Sewer System(s)		X
Stormwater	X	
Item(s) Containing Polychlorinated Biphenyls		X
Significant Amount of Fill Material		X
Other		X

9.3.1 Exterior Observation Comments

Solid (Nonhazardous) Waste(s)—Evidence of Dumping

Farallon observed debris such as plastics, waste tires, and municipal waste, including paper and construction materials, along the Subject Property access roads. No evidence of release was observed.

Stormwater

Stormwater generated at the Subject Property infiltrates the ground surface.

10.0 FINDINGS AND OPINIONS

Farallon performed a Phase I ESA in accordance with ASTM E1527-21 and the Authorization.

Given the potential agricultural historical use of the Subject Property, it is possible that pesticides and other agricultural chemicals may have been applied to the property and residual soil impacts may be present. Although this historical use is not considered a recognized environmental condition, Farallon cannot confirm that shallow subsurface soil was not adversely impacted from the possible former application of pesticides and/or herbicides. Based on the intended future use of the Subject Property for commercial purposes, potential residual impacts associated with historical agricultural uses is considered a de minimis condition in connection with the Subject Property.

Known or suspected releases of hazardous substances to soil and/or groundwater have occurred at GAFB, the north-northeast–adjoining property GAFB. GAFB is a 5,347-acre property first developed in 1941 and the boundaries of GAFB include the north-northeast properties and east-adjoining corrections facility. Several chemical plumes exist in groundwater throughout GAFB, some of which are near the northern and eastern Subject Property boundaries. These chemical plumes are being remediated by DoD under the oversight of EPA and the California Regional Water Quality Control Board. The chemical plumes appear isolated to GAFB in the Subject Property area, although groundwater flow patterns are complex due to active pumping by DoD to clean up the chemical releases. The potential migration of hazardous substances in groundwater originating from the adjoining GAFB to the Subject Property represents a recognized environmental condition in connection with the Subject Property. Based on the down-gradient location with respect to groundwater, depth to groundwater in the region of greater than 100 feet bgs, and information obtained from the GeoTracker database, releases from GAFB are not expected to pose a threat to human health for Subject Property occupants under a commercial land use.

11.0 CONCLUSIONS

Farallon conducted a Phase I ESA for the Adelanto Gateway Logistics Center in conformance with the scope and limitations of ASTM E1527-21. Any exceptions to or deletions from this practice are described in Section 1.5, Deviations.

This assessment identified the following recognized environmental condition in connection with the Subject Property:

- The potential migration of hazardous substances in groundwater originating from the adjoining GAFB to the Subject Property.

Based on the down-gradient location with respect to groundwater, and the depth to groundwater in the region of greater than 100 feet bgs and information obtained from the GeoTracker database, releases from GAFB are not expected to pose a threat to human health for Subject Property occupants under commercial land use.

12.0 BIBLIOGRAPHY

California Department of Conservation, Geologic Energy Management Division. No Date. Well Finder Database Search. <https://www.conservation.ca.gov/calgem/Pages/WellFinder.aspx>. (April 15, 2026.)

California Department of Toxic Substances Control (DTSC). 2026. EnviroStor Database Search. <https://www.envirostor.dtsc.ca.gov/public/>. (April 15, 2026.)

———. 2025. Hazardous Waste Tracking System Database Search. <https://hwts.dtsc.ca.gov/search>. (April 15, 2026.)

California Department of Water Resources. No Date. Well Completion Report Map Application. <https://dwr.maps.arcgis.com/apps/webappviewer/index.html?id=181078580a214c0986e2da28f8623b37>.(April 15, 2026.)

California Environmental Protection Agency. 2026. California Environmental Protection Agency Regulated Site Portal. <https://siteportal.calepa.ca.gov/nsite>. (April 15, 2026.)

California State Water Resources Control Board. 2026. GeoTracker Database Search. <http://geotracker.waterboards.ca.gov>. (April 15, 2026.)

———. 2026. GeoTracker PFAS Map Search. <https://geotracker.waterboards.ca.gov/map/pfas_map>. (April 15, 2026.)

———. 2026. Groundwater Ambient Monitoring and Assessment Program Groundwater Information System Map Search. <https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/Default.asp>. (April 15, 2026.)

City of Adelanto. 2024.Consumer Confidence Report <https://cms3.revize.com/revize/adelanto/Documents/Services/Water%20&%20Sewer/Consumer%20Confidence%20Reports/Consumer%20Confidence%20Report%202024.English.pdf >. (April 15, 2026.)

Environmental Data Resources, Inc. (EDR). 2007. *The EDR Sanborn Map Report, Adelanto Gateway Center, Adelanto Airport Road / Yucca Road, Adelanto, CA 92301*. March 23.

———. 2007. *The EDR Historical Topographic Map Report, Adelanto Gateway Center, Adelanto Airport Road / Yucca Road, Adelanto, CA 92301*. March 26.

———. 2007. *The EDR Aerial Photo Decade Package, Adelanto Gateway Center, Adelanto Airport Road / Yucca Road, Adelanto, CA 92301*. March 27.

———. 2015. *The EDR Radius Map Report with GeoCheck, Adelanto Gateway Center, Adelanto Airport Road / Yucca Road, Adelanto, CA 92301*. September 21.

Environmental Risk Information Services (ERIS). 2026. *Database Report.* Adelanto Gateway Logistics, Adelanto, California. April 10.

Farallon Consulting, L.L.C. (Farallon) 2015. Phase I Environmental Site Assessment, Adelanto Gateway Logistics Center, Air Expressway Boulevard/Adelanto Road, Adelanto, California. October 21.

———.2026. Letter Regarding Proposal for Phase I Environmental Site Assessment, Adelanto Gateway Logistics Center, Air Expressway Boulevard/Adelanto Road, Adelanto, California. From Steffany Aguilar and Tina Huff. To Michael Mileski, Mileski Living Trust. March 30.

———. 2026. Communication Regarding Permits for Aboveground and Underground Storage Tanks, Notices of Violations, and Hazardous Spills Between a Representative of Farallon and a Representative of the San Berardino County Environmental Health Services. April 6.

———. 2026. Communication Regarding Permits for Aboveground and Underground Storage Tanks, Notices of Violations, and Hazardous Spills Between a Representative of Farallon and a Representative of the San Bernardino County Fire Protection District. April 6.

———. 2026. Communication Regarding Permits for Aboveground and Underground Storage Tanks, Notices of Violations, and Hazardous Spills Between a Representative of Farallon and a Representative of the San Bernardino County Public Works Department. April 6.

——. 2026. Communication Regarding Permits for Aboveground and Underground Storage Tanks, Notices of Violations, and Hazardous Spills Between a Representative of Farallon and a Representative of the San Bernardino County Planning and Building Department. April 7.

——. 2026. Communication Regarding the Subject Property Between a Representative of Farallon and Jessica Haughton , Project Manager at, a Representative of Synergy Consulting, project manager and Representative of the Subject Property. April 8.

——. 2026. *Phase I Environmental Site Assessment User Questionnaire*. Completed by Mileski Living Trust. April 8.

——. 2026. Communication Regarding Permits for Aboveground and Underground Storage Tanks, Notices of Violations, and Hazardous Spills Between a Representative of Farallon and a Representative of the City of Adelanto Engineering and Building Departments. April 9.

Google Earth. No Date. Aerial Photographs of the Adelanto, California Area. <https://www.google.com/earth/>. (April 15, 2026.)

San Bernardino County Assessor. 2026. Property Information for Parcel Nos. 0459-841-01 to 0459-841-15 and 0459-451-51 to 459-451-62. <https://arc.sbcounty.gov/property-information/ >. (April 15, 2026.)

U.S. Department of Transportation. No Date. National Pipeline Mapping System. Public Viewer. <https://pvnpms.phmsa.dot.gov/PublicViewer/>. (April 15, 2026.)

URS Corporation. 2007. *Phase I Environmental Site Assessment, Proposed Adelanto Gateway Center, Adelanto, California*. Prepared for Prologis. June 13.

13.0 LIMITATIONS

13.1 GENERAL LIMITATIONS

The conclusions contained in this report/assessment are based on professional opinions with regard to the subject matter. These opinions have been arrived at in accordance with currently accepted hydrogeologic and engineering standards and practices applicable to this location. The conclusions contained herein are subject to the following inherent limitations:

- **Accuracy of Information.** Farallon obtained, reviewed, and evaluated certain information used in this report/assessment from sources that were believed to be reliable. Farallon's conclusions, opinions, and recommendations are based in part on such information. Farallon's services did not include verification of its accuracy or authenticity. Should the information upon which Farallon relied prove to be inaccurate or unreliable, Farallon reserves the right to amend or revise its conclusions, opinions, and/or recommendations.
- **Reconnaissance and/or Characterization.** Farallon performed a reconnaissance and/or characterization of the Subject Property that is the subject of this report/assessment to document current conditions. Farallon focused on areas deemed more likely to exhibit hazardous materials conditions. Contamination may exist in other areas of the Subject Property that were not investigated or were inaccessible. Subject Property activities beyond Farallon's control could change at any time after the completion of this report/assessment.

For the foregoing reasons, Farallon cannot and does not warrant or guarantee that the Subject Property is free of hazardous or potentially hazardous substances or conditions, or that latent or undiscovered conditions will not become evident in the future. Farallon's observations, findings, and opinions can be considered valid only as of the date of the report.

This report/assessment has been prepared in accordance with the contract for services between Farallon and Mileski Living Trust, and currently accepted industry standards. No other warranties, representations, or certifications are made.

13.2 LIMITATION ON RELIANCE BY THIRD PARTIES


Reliance by third parties is prohibited. This report/assessment has been prepared for the exclusive use of Mileski Living Trust to address the unique needs of Mileski Living Trust at the Subject Property at a specific point in time.

This is not a general grant of reliance. No one other than Mileski Living Trust may rely on this report unless Farallon agrees in advance to such reliance in writing. Any unauthorized use, interpretation, or reliance on this report/assessment is at the sole risk of that party, and Farallon will have no liability for such unauthorized use, interpretation, or reliance.

FIGURES

PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT
Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001



REFERENCE: 7.5 MINUTE USGS ADELANTO, CALIFORNIA, DATED 2013



N

FARALLON CONSULTING

Your Challenges. Our Priority. | farallonconsulting.com

Washington
Bellevue | Bellingham | Seattle

Oregon
Portland | Baker City

California
Oakland | Irvine

FIGURE 1


SUBJECT PROPERTY VICINITY MAP
ADELANTO GATEWAY LOGISTICS CENTER
ADELANTO, CALIFORNIA

FARALLON PN: 4001-001

Drawn By: nbedell | Checked By: SA | Date: 4/3/2026

Figure-01_SubjectPropertyVicinityMap

Path: Q:\Projects\4001_Mileski_LivingTrust\001_AdelantoGateway\Mapfiles\001\4001-001_PhaseI.aprx



LEGEND

- CALNEV JET JUEL PIPELINE (KINDER MORGAN)
- HIGH-VOLTAGE ELECTRICAL TOWERS
- SUBJECT PROPERTY BOUNDARY
- SAN BERNADINO COUNTY PARCEL BOUNDARY

0 1,500

SCALE IN FEET

N

NOTES:
1. ALL LOCATIONS ARE APPROXIMATE
2. FIGURES WERE PRODUCED IN COLOR. GRAYSCALE COPIES MAY NOT REPRODUCE ALL ORIGINAL INFORMATION.

FARALLON CONSULTING
Your Challenges. Our Priority. | farallonconsulting.com

Washington
Bellevue | Bellingham | Seattle

Oregon
Portland | Baker City

California
Oakland | Irvine

FIGURE 2

SUBJECT PROPERTY PLAN
ADELANTO GATEWAY LOGISTICS CENTER
ADELANTO, CALIFORNIA

FARALLON PN: 4001-001

Drawn By: lmurock Checked By: SA Date: 4/22/2026

Figure-02_SubjectPropertyPlan

Path: Q:\Projects\4001_Mileski_LivingTrust\001_AdelantoGateway\Mapfiles\001\4001-001_PhaseI.aprx

APPENDIX A
PROFESSIONAL QUALIFICATIONS

PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT
Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001

STEFFANY AGUILAR, P.G.
Associate Geologist

BS Geology
MS Geology
9 years' experience

Steffany Aguilar earned a Bachelor of Science degree in Geology from California State University, Fresno, and a Master of Science degree in Geology from San Jose State University. She has 9 years of experience in environmental consulting and the public environmental sector. Steffany's professional experience includes site characterization for small to large sites in the San Francisco Bay Area, and due diligence projects throughout California.

TINA HUFF, R.E.P.A., C.E.P.
Principal Regulatory Specialist

BA Environmental Studies
25 years' experience

Tina Huff has a broad range of experience with environmental due diligence and regulatory requirements. She manages and conducts environmental due diligence for property transactions, including Phase I ESAs, risk assessment audits, environmental compliance audits, and Phase II Site Investigations across the United States. She is a Registered Environmental Property Assessor, is Asbestos Hazard Emergency Response Act certified for asbestos, and has completed training for mold in construction. Tina has certificates in Dangerous Waste Management and Occupational Safety and Health Administration Compliance. She is an active member on the committee for ASTM International Standard E1527, and has been a returning instructor at Continuing Legal Education events for attorneys throughout the United States.

STEFFANY AGUILAR, P.G.
Associate Geologist

BS Geology
MS Geology
9 years' experience

Steffany Aguilar earned a Bachelor of Science degree in Geology from California State University, Fresno, and a Master of Science degree in Geology from San Jose State University. She has 9 years of experience in environmental consulting and the public environmental sector. Steffany's professional experience includes site characterization for small to large sites in the San Francisco Bay Area, and due diligence projects throughout California.

TINA HUFF, R.E.P.A., C.E.P.
Principal Regulatory Specialist

BA Environmental Studies
25 years' experience

Tina Huff has a broad range of experience with environmental due diligence and regulatory requirements. She manages and conducts environmental due diligence for property transactions, including Phase I ESAs, risk assessment audits, environmental compliance audits, and Phase II Site Investigations across the United States. She is a Registered Environmental Property Assessor, is Asbestos Hazard Emergency Response Act certified for asbestos, and has completed training for mold in construction. Tina has certificates in Dangerous Waste Management and Occupational Safety and Health Administration Compliance. She is an active member on the committee for ASTM International Standard E1527, and has been a returning instructor at Continuing Legal Education events for attorneys throughout the United States.

APPENDIX B
SUBJECT PROPERTY PHOTOGRAPHS

PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT
Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001

SUBJECT PROPERTY PHOTOGRAPHS

Phase I Environmental Site Assessment Report
Adelanto Gateway Logistics Center
Adelanto, California
Farallon PN: 4001-001.001

Photograph 1. Northwestern boundary of Subject Property, looking south.

Photograph 2. Northeastern boundary of Subject Property, looking southwest.

Photograph 3. Eastern Subject Property boundary, looking west.

Photograph 4. Southern boundary of central portion of Subject Property, looking north.

Photograph 5. Southwestern boundary of Subject Property, looking northeast.

Photograph 6. Unnamed dirt road on western portion of Subject Property, looking south.

Photograph 7. Debris on southern portion of Subject Property, looking east.

Photograph 8. Northwest-adjoining Kinder Morgan pipeline easement on Air Base Road, looking north.

Photograph 9. Northwest-adjoining Kinder Morgan Terminal, looking north.

Photograph 10. Northwest-adjoining undeveloped land, residential and commercial properties, looking north.

Photograph 11. North-adjoining Kinder Morgan pipeline easement on Air Base Road and undeveloped land, looking north.

Photograph 12. North-adjoining DHL Supply Chain facility, looking north.

Photograph 13. East-adjoining Federal Correction Complex, looking east.

Photograph 14. South-adjoining powerlines and undeveloped land, looking south.

Photograph 15. South-adjoining Mobile Pipe Lining & Coating, looking south.

Photograph 16. South-adjoining Soil Safe of California, looking south.

Photograph 17. South-adjoining United Truck Trailer Storage Yard, looking southwest.

Photograph 18. Southwest-adjoining XPO & Fast Lane Transportation, looking southwest.

Photograph 19. West-adjoining commercial and industrial properties, looking northwest.

Photograph 20. West-adjoining undeveloped land, looking west.



Photograph 1. Northwestern boundary of Subject Property, looking south.



Photograph 2. Northeastern boundary of Subject Property, looking southwest.



Photograph 3. Eastern Subject Property boundary, looking west.



Photograph 4. Southern boundary of central portion of Subject Property, looking north.



Photograph 5. Southwestern boundary of Subject Property, looking northeast.



Photograph 6. Unnamed dirt road on western portion of Subject Property, looking south.



Photograph 7. Debris on southern portion of Subject Property, looking east.



Photograph 8. Northwest-adjoining Kinder Morgan pipeline easement on Air Base Road, looking north.



Photograph 9. Northwest-adjoining Kinder Morgan Terminal, looking north.



Photograph 10. Northwest-adjoining undeveloped land, residential and commercial properties, looking north.



Photograph 11. North-adjoining Kinder Morgan pipeline easement on Air Base Road and undeveloped land, looking north.



Photograph 12. North-adjoining DHL Supply Chain facility, looking north.



Photograph 13. East-adjoining Federal Correction Complex, looking east.



Photograph 14. South-adjoining powerlines and undeveloped land, looking south.



Photograph 15. South-adjoining Mobile Pipe Lining & Coating, looking south.



Photograph 16. South-adjoining Soil Safe of California, looking south.



Photograph 17. South-adjoining United Truck Trailer Storage Yard, looking southwest.



Photograph 18. Southwest-adjoining XPO & Fast Lane Transportation, looking southwest.



Photograph 19. West-adjoining commercial and industrial properties, looking northwest.



Photograph 20. West-adjoining undeveloped land, looking west.

APPENDIX C
USER QUESTIONNAIRE

PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT
Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001

PHASE I ENVIRONMENTAL SITE ASSESSMENT
USER QUESTIONNAIRE

To qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001, the Phase I Environmental Site Assessment (Phase I ESA) Report user must provide the following information (if available) to the Environmental Professional (Farallon Consulting, L.L.C. [Farallon]). Failure to provide this information could result in the determination that "all appropriate inquiry" has not been completed.

This Phase I Environmental Site Assessment (ESA) was prepared in accordance with ASTM E1527 (herein defined as "the ASTM Standard"). Please state any additional scope items outlined in the Phase I ESA proposal, if applicable:
N/A

Farallon understands that the User of the Phase I ESA Report is seeking to follow the standards set forth in the ASTM Standard to complete an environmental assessment of the Subject Property. The User is defined as the party seeking to use the ASTM Standard to complete a Phase I ESA of the Subject Property. The User has specific responsibilities for fulfilling the ASTM Standard requirements to help identify the possibility of recognized environmental conditions in connection with the Subject Property. These responsibilities do not require the technical expertise of an Environmental Professional, and are to be provided by the User. The completed User Questionnaire will be included in the Phase I ESA Report.

■ DATE COMPLETED

4.8.2026

■ USER INFORMATION

Client (**User**) Name:

This User Questionnaire was completed by:

Name: Mileski Living Trust

Address: 1971 W. 190th Street Suite 100 Torrance, CA 90504

Phone: 702-330-1715

Relationship to User:

☐ User ☐ Legal Counsel ☐ Lender ☐ Realtor/Broker

☐X Other (specify): Project Manager

■ SUBJECT PROPERTY INFORMATION

Subject Property Name (if any): Adelanto Gateway Logistics Center

Subject Property Address:

Vacant Land

Parcel No(s).:

See attach APN spreadsheet

Client Project/Asset #:

Subject Property Contact Information	Phone:
Name:Jessica Haughton Email: jhaughton@synergyconsultingca.com Relation to the Subject Property: Project Manager	702-330-1715

What is the reason this Phase I ESA is required?

Property Transaction: ☐ Sale ☐ Purchase ☐ Exchange

Other (specify): Entitlements

The U.S. Environmental Protection Agency (EPA) All Appropriate Inquiries Final Rule (40 CFR Part 312) requires that the below tasks and questions be performed by or on behalf of a party (i.e., User) seeking to qualify for an LLP to the Comprehensive Environmental Response, Compensation, and Liability Act (CERLA) liability. This purpose of this questionnaire is to assist the User in gathering and providing information that may be material to identifying recognized environmental conditions. The User should provide the following information to the Environmental Professional. Failure to conduct these tasks and inquiries could result in a determination that All Appropriate Inquiries is not complete.

(1) **Environmental cleanup liens that have been filed or recorded against the Subject Property (Part 312.25 of Title 40 of the Code of Federal Regulations [40 CFR 312.25])**

Any environmental liens and activity and use limitations (AULs) known to the **User** should be reported to the Environmental Professional conducting a Phase I ESA. The **User** should either (1) engage a title company, real estate attorney, or title professional to undertake a review of reasonably ascertainable recorded land title records and lien records for environmental liens and AULs currently recorded against or relating to the Subject Property, or (2) negotiate such an engagement of a title company, real estate attorney, or title professional as an addition to the scope of work of the Environmental Professional.

A lien search obtained through a database company at the request of the User does not replace the User obligations to review Land Title and Judicial records for the Subject Property as described in ASTM E1527.

Are you aware of any environmental cleanup liens against the Subject Property that have been filed or recorded under federal, tribal, state, or local law? If yes, please provide details to the best of your knowledge.

No

(2) **Activity and use limitations that are in place on the Subject Property or that have been filed or recorded in a registry against the Subject Property (40 CFR 312.26)**

ASTM E1527 does not impose on the Environmental Professional the responsibility to undertake review of recorded land title records or judicial records for environmental liens and activity use limitations.

Are you aware of any activity and use limitation (such as engineering controls, land use restrictions, or institutional controls) that are in place at the Subject Property and/or have been

filed or recorded in a registry under federal, tribal, state, or local law? If yes, please provide details to the best of your knowledge.

No

(3) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28)

As the User of the Phase I ESA Report, please indicate any specialized knowledge or experience you have related to the Subject Property or nearby properties. For example, are you involved in the same line of business as the current or former occupant(s) of the Subject Property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

N/A

(4) Relationship of the purchase price to the fair market value of the Subject Property if it were not contaminated (40 CFR 312.29)

Does the purchase price being paid for this Subject Property reasonably reflect the fair market value of the Subject Property?

N/A

If you conclude that there is a difference between the purchase price and the fair market value, have you considered whether the lower purchase price is because contamination is known or believed to be present at the Subject Property?

N/A

(5) Commonly known or reasonably ascertainable information about the Subject Property (40 CFR 312.30)

Are you aware of commonly known or reasonably ascertainable information about the Subject Property that would help Farallon Consulting, L.L.C. to identify conditions indicative of a chemical or other release or threatened release? For example, as user of the Phase I ESA Report:

Do you know the past use(s) of the Subject Property? (If yes, please specify.)

Unimproved, vacant land, no past use

Do you know of a specific chemical(s) present at the Subject Property, or present at one time? (If yes, please specify.)

No

Do you know of a chemical and/or other spill(s) or release(s) that has taken place at the Subject Property? (If yes, please specify.)

No

Do you know of any environmental cleanup(s) that has taken place at the Subject Property? (If yes, please specify.)

No

(6) **The degree of obviousness of the presence or likely presence of contamination at the Subject Property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31)**

Based on your knowledge and experience related to the Subject Property, is there any obvious indicator(s) that points to the presence or likely presence of contamination at the Subject Property? (If yes, please specify.)

None

Additional information about the Subject Property, if known.

■ OWNERS

Current Owner(s):

Mileski Living Trust

Previous Owner(s):

Prologis

■ OCCUPANTS/TENANTS AND OPERATIONS

Current Occupant(s)/Tenant(s):

N/A

Current Operations: N/A

Previous Occupant(s)/Tenant(s):

None

Former Operations:

■ PREVIOUS INVESTIGATIONS

Have previous environmental investigations been conducted at Subject Property?
If yes, have they been provided to Farallon Consulting, L.L.C.?

Yes, a 2015 Phase I conducted by Farallon.

■ SUBJECT PROPERTY ENVIRONMENTAL CONDITIONS

Are you aware of any of the following environmental conditions at the Subject Property, either current or former?

Environmental Condition/Issue	Response	Comment if Yes Response
Aboveground Storage Tank	☐ Yes ☐ No	
Underground Storage Tank	☐ Yes ☐ No	
Dump Area/Landfill	☐ Yes ☐ No	
Waste Treatment System	☐ Yes ☐ No	
Wastewater Discharge	☐ Yes ☐ No	
Air Stack/Vent/Odor	☐ Yes ☐ No	

Indoor Air Quality Complaint	☐ Yes ☐ No	
Floor Drain/Sump	☐ Yes ☐ No	
Pit, Pond, Lagoon	☐ Yes ☐ No	
Stained Soil/Vegetation Impact	☐ Yes ☐ No	

■ RELIANCE

Reliance: The Phase I ESA Report will be prepared for the sole use of the User. Please be advised that Farallon limits third parties' right to rely on the Phase I ESA Report. Farallon may issue a letter granting the right to rely on terms Farallon has pre-approved. However, in no case will Farallon grant reliance to the Small Business Administration.
Farallon is not obligated to provide reliance. All requests for the right to rely should be discussed prior to commencement of the Phase I ESA.

Please identify all parties who intend to use the Phase I ESA Report for informational purposes:

EPC Environmental, CEQA Consultant

APPENDIX D
ENVIRONMENTAL DATABASE REPORT

PHASE I
ENVIRONMENTAL SITE ASSESSMENT REPORT
Adelanto Gateway Logistics Center
Air Base Road/Adelanto Road
Adelanto, California

Farallon PN: 4001-001.001

DATABASE REPORT

Project Property:	*ADELANTO GATEWAY LOGISTICS CENTER* *ADELANTO GATEWAY LOGISTICS CENTER* *Adelanto CA*
Project No:	*4001-001*
Report Type:	*Database Report*
Order No:	*26040900380*
Requested by:	*Farallon Consulting, LLC*
Date Completed:	*April 10, 2026*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....9
Executive Summary: Site Report Summary - Surrounding Properties.....10
Executive Summary: Summary by Data Source.....24
Map.....42
Aerial.....45
Topographic Map.....46
Detail Report.....47
Unplottable Summary.....408
Unplottable Report.....419
Appendix: Database Descriptions.....684
Definitions.....704

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:	*ADELANTO GATEWAY LOGISTICS CENTER* *ADELANTO GATEWAY LOGISTICS CENTER Adelanto CA*
Project No:	*4001-001*

Coordinates:

Latitude:	*34.56776803*
Longitude:	*-117.3841462*
UTM Northing:	*3,825,178.91*
UTM Easting:	*464,762.60*
UTM Zone:	*11S*

Elevation: *2,907 FT*

Order Information:

Order No:	*26040900380*
Date Requested:	*April 9, 2026*
Requested by:	*Farallon Consulting, LLC*
Report Type:	*Database Report*

Historicals/Products:

ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	**1**	0	0	0	0	**1**
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	**1**	0	0	-	**1**
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	**1**	**1**
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	0	**2**	-	-	**2**
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	**1**	**6**	**11**	-	-	**18**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	**1**	0	0	-	**1**
FED INST	Y	0.5	0	**1**	0	0	-	**1**
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	**7**	-	-	-	**7**
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	**1**	0	0	0	**1**
State								
RESPONSE	Y	1	**1**	0	0	0	0	**1**
ENVIROSTOR	Y	1	0	0	0	0	**4**	**4**
DELISTED ENVS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	**1**	0	-	**1**
SWRCB SWF	Y	0.5	0	0	0	0	-	0
WMUD	Y	0.5	0	0	0	0	-	0
HWP	Y	1	0	0	**1**	0	**1**	**2**
SWAT	Y	0.5	0	0	0	0	-	0
C&D DEBRIS RECY	Y	0.5	0	0	**1**	0	-	**1**
RECYCLING	Y	0.5	0	0	0	0	-	0
PROCESSORS	Y	0.5	0	0	0	0	-	0
CONTAINER RECY	Y	0.5	0	0	**1**	0	-	**1**
LDS	Y	0.5	0	0	**1**	0	-	**1**
LUST	Y	0.5	0	0	0	**5**	-	**5**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	**1**	0	-	-	**1**
UST CLOSURE	Y	0.5	0	0	0	0	-	0
HHSS	Y	0.25	0	0	0	-	-	0
UST SWEEPS	Y	0.25	0	0	0	-	-	0
AST	Y	0.25	0	0	**1**	-	-	**1**
AST SWRCB	Y	0.25	0	0	0	-	-	0
TANK OIL GAS	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	0	0	-	-	0
CERS TANK	Y	0.25	0	0	**1**	-	-	**1**
DELISTED CTNK	Y	0.25	0	0	0	-	-	0
HIST TANK	Y	0.25	0	0	0	-	-	0
LUR	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CALSITES	Y	0.5	0	0	0	0	-	0
HLUR	Y	0.5	0	0	0	0	-	0
DEED	Y	0.5	0	**3**	**1**	**8**	-	**12**
VCP	Y	0.5	0	0	0	0	-	0
CLEANUP SITES	Y	0.5	0	**3**	**1**	**6**	-	**10**
DELISTED CLEANUP	Y	0.5	0	0	0	**2**	-	**2**
DELISTED COUNTY	Y	0.25	0	0	0	-	-	0
DELISTED COUNTY TANK	Y	0.25	0	0	0	-	-	0
DELISTED COUNTY LTANK	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County								
SANBERN CUPA	Y	0.25	0	**5**	**14**	-	-	**19**
Additional Environmental Records								
Federal								
PFAS GHG	Y	0.5	0	0	0	0	-	0
OSC RESPONSE	Y	0.125	0	0	-	-	-	0
FINDS/FRS	Y	PO	**2**	**10**	-	-	-	**12**
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	**1**	0	0	-	**1**
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	**1**	**3**	**1**	-	**5**
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	**1**	-	-	-	**1**
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	**1**	-	-	-	**1**
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	0	0	-	-	-	0
NPDES BIOSOLIDS	Y	PO	0	-	-	-	-	0
State								
PFAS SAMPLING	Y	0.5	0	0	0	0	-	0
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DRYC GRANT	Y	0.25	0	0	0	-	-	0
PFAS GT CLEANUPS	Y	0.5	0	0	0	0	-	0
PFAS GW	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PFAS INVEST	Y	0.5	0	0	0	0	-	0
HWSS CLEANUP	Y	0.5	0	0	0	0	-	0
TOXIC PITS	Y	1	0	0	0	0	0	0
DTSC HWF	Y	0.5	0	0	0	0	-	0
INSP COMP ENF	Y	1	0	0	0	0	**1**	**1**
SCH	Y	1	0	0	0	0	0	0
CHMIRS	Y	PO	0	**8**	-	-	-	**8**
HIST CHMIRS	Y	PO	0	-	-	-	-	0
HAZNET	Y	PO	**1**	**3**	-	-	-	**4**
HAZ GEN	Y	PO	0	**7**	-	-	-	**7**
HAZ TSD	Y	0.5	0	0	0	0	-	0
HIST MANIFEST	Y	PO	0	**1**	-	-	-	**1**
HW TRANSPORT	Y	0.125	0	0	-	-	-	0
WASTE TIRE	Y	PO	0	-	-	-	-	0
MEDICAL WASTE	Y	0.25	0	0	0	-	-	0
HIST CORTESE	Y	0.5	0	0	0	0	-	0
CDO/CAO	Y	0.5	0	0	0	0	-	0
CERS HAZ	Y	0.125	0	**3**	-	-	-	**3**
DELISTED HAZ	Y	0.5	0	0	0	**1**	-	**1**
GEOTRACKER	Y	0.125	0	0	-	-	-	0
MINE	Y	1	0	0	0	0	0	0
LIEN	Y	PO	0	-	-	-	-	0
WASTE DISCHG	Y	0.25	0	0	0	-	-	0
EMISSIONS	Y	0.25	0	**13**	**12**	-	-	**25**
CDL	Y	0.125	0	**1**	-	-	-	**1**
Tribal	***No Tribal additional environmental record sources available for this State.***							
County								
MED WST SANBERN	Y	0.25	0	0	0	-	-	0
Total:			**6**	**79**	**51**	**23**	**7**	**166**

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	NPL	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***EPA ID:*** *CA2570024453*	ENE	0.00 / 0.00	0	47
2	FINDS/FRS	GEORGE AIR FORCE BASE	5 VICTORVILLE CA 92392 ***Registry ID:*** *110033619813*	ESE	0.00 / 0.00	16	48
2	RESPONSE	GEORGE AIR FORCE BASE	5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA VICTORVILLE CA 92392 ***Envirostor ID:*** *36970005* ***Cleanup Status:*** *ACTIVE AS OF 7/9/2025*	ESE	0.00 / 0.00	16	48
3	FINDS/FRS	CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301 ***Registry ID:*** *110071114147*	WNW	0.00 / 0.00	-9	63
3	HAZNET	CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	WNW	0.00 / 0.00	-9	63
3	RCRA NON GEN	CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301 ***Handler ID | Recycler Activity?:*** *CAC003125475 | NO*	WNW	0.00 / 0.00	-9	64

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
4	CHMIRS	Victorville City Fire	Airbase Rd. and Phantom Rd. Victorville CA ***Control No* | *Notified Date:*** 1/22/199902:12:46 PM	ENE	0.00 / 23.48	-5	66
5	HAZ GEN	FEDERAL CORRECTIONS COMPLEX	13289 AIRBASE RD VICTORVILLE CA 923940000	ENE	0.01 / 26.50	-2	66
6	CHMIRS	Hazmat One	Air Expressway at Adelanto Rd. Victorville CA ***Control No* | *Notified Date:*** 14-1107 |	NNE	0.01 / 31.13	-4	66
7	CERCLIS	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***Site EPA ID:*** CA2570024453	WNW	0.01 / 35.78	-10	68
7	FED ENG	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***EPA ID:*** CA2570024453	WNW	0.01 / 35.78	-10	81
7	FED INST	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***EPA ID:*** CA2570024453	WNW	0.01 / 35.78	-10	86
7	PFAS NPL	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***Identifier:*** CA2570024453	WNW	0.01 / 35.78	-10	87
7	SUPERFUND ROD	GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 9239	WNW	0.01 / 35.78	-10	87
8	CHMIRS	Verizon California Inc.	17640 Adelanto Rd. Adelanto CA ***Control No* | *Notified Date:*** 12-3863 |	W	0.01 / 63.36	-4	89
8	EMISSIONS	VERIZON-ADELANTO C. O.	17640 ADELANTO ROAD ADELANTO CA 92301	W	0.01 / 63.36	-4	90
8	EMISSIONS	VERIZON ADELANTO1	17640 ADELANTO RD. ADELANTO CA 92301	W	0.01 / 63.36	-4	93
8	EMISSIONS	FRONTIER - ADELANTO # 1	17640 ADELANTO ROAD ADELANTO CA 92301	W	0.01 / 63.36	-4	95

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
8	FINDS/FRS	VERIZON ADELANTO1	17640 ADELANTO ROAD ADELANTO CA 92301-1744 ***Registry ID:*** 110021317724	W	0.01 / 63.36	-4	98
8	FINDS/FRS	FRONTIER - ADELANTO # 1	17640 ADELANTO ROAD ADELANTO CA 92301 ***Registry ID:*** 110071764845	W	0.01 / 63.36	-4	98
8	FINDS/FRS	VERIZON ADELANTO1	17640 ADELANTO RD. ADELANTO CA 92301 ***Registry ID:*** 110071765790	W	0.01 / 63.36	-4	99
8	HAZ GEN	VERIZON CALIFORNIA INC	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	-4	99
8	HAZ GEN	VERIZON CALIFORNIA INC	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	-4	100
8	HAZ GEN	VERIZON CALIFORNIA INC.	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	-4	100
8	HAZNET	CONTEL ADELANTO CO	17640 ADELANTO RD ADELANTO CA 923010000	W	0.01 / 63.36	-4	100
8	HIST MANIFEST		17640 ADELANTO RD ADELANTO CA 923010000	W	0.01 / 63.36	-4	100
8	SANBERN CUPA	FRONTIER CALIFORNIA INC.: ADELANTO CO	17640 Adelanto Rd Adelanto CA 92301	W	0.01 / 63.36	-4	101
9	AFS	MOBILE PIPE WRAPPERS & COATERS, INC.	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	101
9	CERS HAZ	Mobile Coating Solutions Inc.	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	18	114
9	EMISSIONS	MOBILE PIPE WRAPPERS & COATERS	12766VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	124
9	EMISSIONS	MOBILE PIPE LINING AND COATING	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	125

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
9	EMISSIONS	MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	126
9	EMISSIONS	MOBILE PIPE LINING AND COATING, INC.	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	126
9	EMISSIONS	MOBILE COATING SOLUTIONS	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	18	128
9	FINDS/FRS	MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET ROAD ADELANTO CA 92301-2706 ***Registry ID:*** 110014324070	S	0.02 / 85.79	18	129
9	FINDS/FRS	MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID:*** 110065163673	S	0.02 / 85.79	18	130
9	FINDS/FRS	UNDERGROUND SOLUTIONS INC DBA MOBILE PIPE LINING	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID:*** 110070318896	S	0.02 / 85.79	18	131
9	FINDS/FRS	MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID:*** 110071291812	S	0.02 / 85.79	18	131
9	FINDS/FRS	MOBILE PIPE LINING AND COATING, INC.	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID:*** 110071764766	S	0.02 / 85.79	18	132
9	FINDS/FRS	MOBILE COATING SOLUTIONS	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID:*** 110071765817	S	0.02 / 85.79	18	133
9	HAZ GEN	MOBILE PIPE LINING & COATING INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	18	133
9	HAZ GEN	MOBILE PIPE WRAPPERS & COATERS INC	12766 VIOLET RD ADELANTO CA 923010000	S	0.02 / 85.79	18	134
9	HAZ GEN	MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	18	134

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
9	HAZNET	BECK OIL INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	18	135
9	ICIS	MOBILE PIPE WRAPPERS & COATERS, INC.	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID:*** 110014324070	S	0.02 / 85.79	18	135
9	RCRA NON GEN	MOBILE PIPE LINING & COATING INC	12766 VIOLET RD ADELANTO CA 92301 ***Handler ID | Recycler Activity?:*** CAL000364933 | NO	S	0.02 / 85.79	18	135
9	RCRA NON GEN	MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301 ***Handler ID | Recycler Activity?:*** CAL000471420 | NO	S	0.02 / 85.79	18	138
9	SANBERN CUPA	MOBILE COATING SOLUTIONS INC.	12766 VIOLET ADELANTO CA 92301	S	0.02 / 85.79	18	140
10	CHMIRS	Kinder Morgan	13334 Air Expressway Rd Victorville CA 92394 ***Control No | Notified Date:*** 09-3605 |	ENE	0.02 / 104.47	-3	140
10	CHMIRS	Kinder Morgan	13334 Air Express Way Victorville CA 92394 ***Control No | Notified Date:*** 07-2762 |	ENE	0.02 / 104.47	-3	143
10	CHMIRS	Kinder Morgan	13334 Air Express Way Victorville CA 92392 ***Control No | Notified Date:*** 07-4551 |	ENE	0.02 / 104.47	-3	146
10	CHMIRS	Kinder Morgan	13334 Air Express Way Victorville CA 92392 ***Control No | Notified Date:*** 07-0783 |	ENE	0.02 / 104.47	-3	148
10	CHMIRS	Kinder Morgan	13334 Air Express Way Victorville CA ***Control No | Notified Date:*** 07-0338 |	ENE	0.02 / 104.47	-3	151
10	ERNS		13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No:*** 884663	ENE	0.02 / 104.47	-3	154
10	ERNS		13334 AIR EXPRESSWAY VICTORVILLE CA 92868 ***NRC Report No:*** 825576	ENE	0.02 / 104.47	-3	156
10	ERNS		13334 AIR EXPRESSWAY VICTORVILLE CA ***NRC Report No:*** 823858	ENE	0.02 / 104.47	-3	158

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
10	ERNS		13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No:*** 795717	ENE	0.02 / 104.47	-3	160
10	ERNS		1334 AIR EXPRESS WAY VICTORYVILLE CA 92392 ***NRC Report No:*** 843835	ENE	0.02 / 104.47	-3	162
10	ERNS		13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No:*** 834574	ENE	0.02 / 104.47	-3	164
10	ERNS		13334 AIR EXPRESSWAY ROAD VICTORVILLE CA 92394 ***NRC Report No:*** 905367	ENE	0.02 / 104.47	-3	166
10	FINDS/FRS	CALNEV TERMINAL GEORGE AFB JET FUEL SPILL	13334 AIR EXPRESSWAY BLVD. VICTORVILLE CA 92394 ***Registry ID:*** 110066125767	ENE	0.02 / 104.47	-3	168
10	HAZNET	KINDER MORGAN	13334 AIR EXPRESS WAY VICTORVILLE CA 92392	ENE	0.02 / 104.47	-3	168
11	UST	Frontier California Inc.: Adelanto CO	17640 Adelanto Rd Adelanto CA 92301 ***Facility ID:*** FA0007064 ***Tank ID No.*** | ***Tank Status*** | ***Tank Closure Date:*** 1 | Confirmed/Updated Information |	W	0.04 / 189.66	-5	169
12	CLEANUP SITES	George Air Force Base - DP001 OU3 Paint Drum Burial	18374 Phantom West St Victorville CA 92394-1504 ***Global ID:*** DOD100226200	NE	0.05 / 246.61	-7	169
12	DEED	George Air Force Base - DP001 OU3 Paint Drum Burial	18374 Phantom West St Victorville CA 92394-1504	NE	0.05 / 246.61	-7	173
13	CDL		17664 1/2 ADELANO ROAD ADELANTO CA 92301	WNW	0.06 / 299.93	-6	174
14	RCRA NON GEN	AAA TIRE SHOP	17664 ADELANTO RD #B ADELANTO CA 92301 ***Handler ID*** | ***Recycler Activity?:*** CAL000470969 | NO	WNW	0.06 / 309.22	-6	174
15	CERS HAZ	CENTURYLINK - ADELANTO - ADLNCABC	17437 ADELANTO RD ADELANTO CA 92301	W	0.09 / 470.63	8	176
15	EMISSIONS	GST TELECOM CALIFORNIA - ADELANTO RD.	17437 ADELANTO ROAD ADELANTO CA 92301	W	0.09 / 470.63	8	178

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
15	EMISSIONS	TW TELECOM - ADELANTO RD	17437 ADELANTO ROAD ADELANTO CA 92301	W	0.09 / 470.63	8	180
15	SANBERN CUPA	CENTURYLINK - ADELANTO - ADLNCABC	17437 Adelanto Rd Adelanto CA 92301	W	0.09 / 470.63	8	183
16	PFAS IND	SOIL SAFE - ADELANTO	ADELANTO CA	W	0.10 / 517.01	9	183
17	CERS HAZ	Exel	13133 INNOVATION WAY STE 100 VICTORVILLE CA 92394	NNE	0.10 / 527.91	-9	184
17	EMISSIONS	UNITED FURNITURE INDUSTRIES	13133 INNOVATION WAY VICTORVILLE CA 92394	NNE	0.10 / 527.91	-9	187
17	EMISSIONS	SCI LOT 1 - INNOVATION WAY	13133 INNOVATION WAY VICTORVILLE CA 92392	NNE	0.10 / 527.91	-9	190
17	EMISSIONS	DC1	13133 INNOVATION WAY VICTORVILLE CA 92392	NNE	0.10 / 527.91	-9	191
17	RCRA NON GEN	DHL SUPPLY CHAIN - MARS	13133 INNOVATION WAY SUITE 100 VICTORVILLE CA 92394 ***Handler ID | Recycler Activity?:*** CAC002963703 | NO	NNE	0.10 / 527.91	-9	193
17	RCRA NON GEN	UNITED FURNITURE INDUSTRIES INC	13133 INNOVATION WAY STE 200 VICTORVILLE CA 92394 ***Handler ID | Recycler Activity?:*** CAL000442896 | NO	NNE	0.10 / 527.91	-9	195
17	SANBERN CUPA	DHL - EXEL	13133 Innovation WAY Ste 100 Victorville CA 92394	NNE	0.10 / 527.91	-9	197
17	SANBERN CUPA	United Furniture Industries, Inc	13133 Innovation WAY Ste 200 Victorville CA 92394	NNE	0.10 / 527.91	-9	198
18	RCRA NON GEN	CALNEV PIPE LINE LLC - ADELANTO JUNCTION	AIR EXPRESSWAY AND ADELANTO RD ADELANTO CA 92301 ***Handler ID | Recycler Activity?:*** CAP000253971 | NO	WNW	0.11 / 556.26	-7	198
19	CLEANUP SITES	CALNEV Terminal GEORGE AFB Jet Fuel	13334 Air Expressway Blvd. VICTORVILLE CA	ENE	0.11 / 600.05	-4	201

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
		Spill					
			Global ID: SLT6V0083835				
19	DEED	CALNEV Terminal GEORGE AFB Jet Fuel Spill	13334 Air Expressway Blvd. VICTORVILLE CA	ENE	0.11 / 600.05	-4	210
20	CLEANUP SITES	George Air Force Base - OT072 OU5 Current Skeet Range	18374 Phantom West St Victorville CA -92392	NE	0.12 / 631.20	-13	210
			Global ID: DOD100234400				
20	DEED	George Air Force Base - OT072 OU5 Current Skeet Range	18374 Phantom West St Victorville CA -92392	NE	0.12 / 631.20	-13	218
21	AST	TPST SOIL RECYCLERS OF CALIFORNIA	12328 HIBISCUS ADELANTO CA 92301	W	0.13 / 671.18	11	219
21	C&D DEBRIS RECY	SOIL SAFE OF CALIFORNIA, INC.	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	11	219
21	CERS TANK	Soil Safe-Adelanto Soil Recycling Center	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	11	219
			Site ID: 163019				
21	EMISSIONS	TPS TECHNOLOGIES INC.	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	11	226
21	EMISSIONS	SOIL SAFE OF CALIFORNIA, INC	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	11	233
21	EMISSIONS	SOIL SAFE - ADELANTO	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	11	234
21	HWP	TPS TECHNOLOGIES INC	12328 HIBISCUS RD ADELANTO CA 923011700	W	0.13 / 671.18	11	236
			Envirostor ID: CAL930834777				
21	LDS	SOIL SAFE - ADELANTO SOIL RECYCLING CENTER	12328 HIBISCUS AVE ADELANTO CA 92301	W	0.13 / 671.18	11	238

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
21	RCRA NON GEN	SOIL SAFE OF CALIFORNIA INC	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	11	267
			***Handler ID	Recycler Activity?:*** CAL000298752 | NO			
21	SANBERN CUPA	Soil Safe	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	11	269
21	SWF/LF	Soil Safe of California, Inc.	12328 Hibiscus Avenue Adelanto CA 92301	W	0.13 / 671.18	11	269
			***Act Opl Status	Activity:*** Active | Contaminated Soil Transfer/Processing Operation			
22	RCRA NON GEN	HIGH DESERT RECYCLING	12325 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 683.83	11	271
			***Handler ID	Recycler Activity?:*** CAL000464648 | NO			
22	SANBERN CUPA	ADELANTO METAL RECYCLING	12325 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 683.83	11	273
23	PFAS IND	MOBILE PIPE WRAPPERS & COATERS	ADELANTO CA	S	0.13 / 697.50	22	274
24	PFAS IND	MOBILE COATING SOLUTIONS	ADELANTO CA	S	0.13 / 712.55	21	274
25	PFAS IND	MOBILE PIPE WRAPPERS & COATERS	ADELANTO CA	S	0.13 / 712.56	25	275
26	RCRA NON GEN	A H TRANSPORTATION GROUP	12191 HIBISCUS RD ADELANTO CA 92301	W	0.15 / 775.78	11	276
			***Handler ID	Recycler Activity?:*** CAL000429595 | NO			
27	EMISSIONS	SOUTHLAND MIXER SERVICE, INC	12231 HIBISCUS ROAD ADELANTO CA 92301	W	0.17 / 898.78	14	278
27	RCRA NON GEN	LOYAL BROTHERS TRUCK REPAIR INC	12231 HIBISCUS RD ADELANTO CA 92301	W	0.17 / 898.78	14	281
			***Handler ID	Recycler Activity?:*** CAL000409594 | NO			
27	RCRA NON GEN	WITHOUT BORDERS TRANSPORT INC	12231 HIBISCUS RD ADELANTO CA 92371	W	0.17 / 898.78	14	284
			***Handler ID	Recycler Activity?:*** CAL000431745 | NO			
27	RCRA NON GEN	SOUTHLAND MIXER SERVICES INC	12231 HIBISCUS RD ADELANTO CA 92301-1702	W	0.17 / 898.78	14	286
			***Handler ID	Recycler Activity?:*** CAL000287666 | NO			

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
27	RCRA NON GEN	PARAMOUNT ROLL & FORMING, INC.	12231 HIBISCUS ROAD ADELANTO CA 92301 ***Handler ID* | *Recycler Activity?:*** CAC003252796 | NO	W	0.17 / 898.78	14	288
27	RCRA NON GEN	PARAMOUNT ROLL & FORMING INC	12231 HIBISCUS RD BLDG 2 ADELANTO CA 92301 ***Handler ID* | *Recycler Activity?:*** CAL000482107 | NO	W	0.17 / 898.78	14	291
27	RCRA NON GEN	PARAMOUNT ROLL & FORMING INC	12231 HIBISCUS RD BLDG #2 ADELANTO CA 92301 ***Handler ID* | *Recycler Activity?:*** CAL000482208 | NO	W	0.17 / 898.78	14	293
27	RCRA NON GEN	MWC GROUP INC	12231 HIBISCUS RD ADELANTO CA 92301 ***Handler ID* | *Recycler Activity?:*** CAL000493962 | NO	W	0.17 / 898.78	14	295
27	SANBERN CUPA	EXTRA TANK LINE, INC	12231 HIBISCUS RD ADELANTO CA 92301	W	0.17 / 898.78	14	297
27	SANBERN CUPA	DIESEL PROS	12231 HIBISCUS UNIT 1 ADELANTO CA 92301	W	0.17 / 898.78	14	298
27	SANBERN CUPA	SOUTHLAND MIXER SERVICE, INC	12231 HIBISCUS ADELANTO CA 92301	W	0.17 / 898.78	14	298
27	SANBERN CUPA	RAYCO WELDING	12231 HIBISCUS UNIT C ADELANTO CA 92301	W	0.17 / 898.78	14	299
27	SANBERN CUPA	MORRISON EQUIPMENT/HEAVY DUTY GATES INC	12231 HIBISCUS RD UNIT 2 ADELANTO CA 92301	W	0.17 / 898.78	14	299
27	SANBERN CUPA	Loyal Brothers Mobile Truck Repair	12231 Hibiscus Rd Adelanto CA 92301	W	0.17 / 898.78	14	299
28	EMISSIONS	TRAFFIX DEVICES, INC. DBA COAST RUBBER PRODUCTS	12128 YUCCA ROAD ADELANTO CA 92301	W	0.18 / 930.94	13	300
28	RCRA NON GEN	COAST RUBBER PRODUCTS	12128 YUCCA RD ADELANTO CA 92301 ***Handler ID* | *Recycler Activity?:*** CAL000426709 | NO	W	0.18 / 930.94	13	301
28	RCRA SQG	TRAFFIX DEVICES INC	12128 YUCCA RD ADELANTO CA 92301	W	0.18 / 930.94	13	303

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Handler ID	Recycler Activity?:*** CAR000083592 | NO			
28	SANBERN CUPA	TRAFFIX DEVICES INC	12128 YUCCA RD ADELANTO CA 92301	W	0.18 / 930.94	13	305
29	EMISSIONS	CALIFORNIA SILICA PRODUCTS LLC	12808 RANCHO ROAD ADELANTO CA 92301	S	0.18 / 939.79	31	306
29	EMISSIONS	CALIFORNIA SILICA PRODUCTS LLC	12808 RANCHO RD ADELANTO CA 92301	S	0.18 / 939.79	31	307
29	EMISSIONS	DIVERSIFIED MINERALS, INC.	12808 RANCHO RD ADELANTO CA 92301	S	0.18 / 939.79	31	307
30	SANBERN CUPA	SPRINT-ADELANTO	17824 ADELANTO RD ADELANTO CA 92301	WNW	0.19 / 1,005.69	-14	308
31	EMISSIONS	VALEW WELDING & FABRICATION, INC	12522 VIOLET ROAD ADELANTO CA 92301	SW	0.21 / 1,099.76	29	309
31	RCRA SQG	VALEW WELDING AND FABRICATION	12522 VIOLET RD ADELANTO CA 92301	SW	0.21 / 1,099.76	29	312
			***Handler ID	Recycler Activity?:*** CAR000095141 | NO			
31	SANBERN CUPA	VALEW WELDING AND FABRICATION	12522 VIOLET RD ADELANTO CA 92301	SW	0.21 / 1,099.76	29	316
32	CLEANUP SITES	George Air Force Base - LF036 OU3 Construction debris/trash	18374 Phantom West St Victorville CA 92392-1504	NW	0.23 / 1,189.93	-16	317
			Global ID: DOD100235700				
32	DEED	George Air Force Base - LF036 OU3 Construction debris/trash	18374 Phantom West St Victorville CA 92392-1504	NW	0.23 / 1,189.93	-16	320
33	CONTAINER RECY	Federal Bureau of Prisons/Federal Correctional Complex Recycling	13777 Air Expway Victorville CA 92394	E	0.23 / 1,231.74	8	321
34	EMISSIONS	SPRINT	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	-15	321

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
34	EMISSIONS	SPRINT ADLNCAUS	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	-15	322
34	EMISSIONS	COGENT ADLNCAUS	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	-15	325
34	SANBERN CUPA	EMPIRE ONE AUTO SERVICES	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	-15	325
34	SANBERN CUPA	GOLDEN HAWK TOWING	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	-15	326
34	SANBERN CUPA	Sprint Adelanto POP/REGEN CAADEA	17834 Adelanto Rd Adelanto CA 92301	WNW	0.24 / 1,254.44	-15	326
35	LUST	TURNER FORD	17909 ADELANTO RD ADELANTO CA 92301 ***Global ID*	*Status:*** T0607100733 |	WNW	0.29 / 1,557.14	-21	326
36	CLEANUP SITES	George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal	18374 Phantom West St Victorville CA -92392 ***Global ID:*** DOD100235600	NNW	0.33 / 1,751.12	-16	329
36	DEED	George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal	18374 Phantom West St Victorville CA -92392	NNW	0.33 / 1,751.12	-16	336
37	LUST	ADELANTO SCHOOL DISTRICT	11824 AIR BASE RD ADELANTO CA 92301 ***Global ID*	*Status:*** T0607100739 |	W	0.34 / 1,782.96	-5	336
38	PFAS IND	COMAV TECHNICAL SERVICES	VICTORVILLE CA	E	0.36 / 1,881.57	10	339
39	DELISTED CLEANUP	George Air Force Base - George Air Force Base - OU2 - ST067b JP-4 AST/Bulk Fuel	Yard 18374 PHANTOM WEST ST VICTORVILLE CA -92392	NE	0.36 / 1,895.74	-12	340
40	CLEANUP SITES	George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range	(Building 615) 18374 Phantom West St Victorville CA -92392	NNE	0.37 / 1,959.08	-16	340

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Global ID: DOD100235900				
40	DEED	George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range	(Building 615) 18374 Phantom West St Victorville CA -92392	NNE	0.37 / 1,959.08	-16	344
41	CLEANUP SITES	George Air Force Base - OT074 OU5 Original Skeet Range	18374 Phantom West St Victorville CA 92392	NE	0.38 / 1,994.65	-12	344
			Global ID: DOD100234600				
41	CLEANUP SITES	George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field	18374 Phantom West St Victorville CA -92392	NE	0.38 / 1,994.65	-12	351
			Global ID: DOD100229500				
41	DEED	George Air Force Base - OT074 OU5 Original Skeet Range	18374 Phantom West St Victorville CA 92392	NE	0.38 / 1,994.65	-12	357
41	DEED	George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field	18374 Phantom West St Victorville CA -92392	NE	0.38 / 1,994.65	-12	357
42	DEED	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST Victorville CA 92392	NE	0.39 / 2,063.73	-14	358
42	LUST	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST Victorville CA 92392	NE	0.39 / 2,063.73	-14	359
			Global ID | Status: T10000001719 |			
43	DELISTED CLEANUP	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST VICTORVILLE CA 92392	NE	0.39 / 2,065.19	-14	364
44	DELISTED HAZ	Pacific Aerospace	18200 PHANTOM W VICTORVILLE CA 92394	NE	0.40 / 2,090.45	-14	364
45	CLEANUP SITES	George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL Disposal	18374 Phantom West St Victorville CA -92392	NNE	0.45 / 2,392.35	-18	364
			Global ID: DOD100241700				
45	DEED	George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL	18374 Phantom West St Victorville CA -92392	NNE	0.45 / 2,392.35	-18	368

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
		Disposal					
46	LUST	CIRCLE K#8644	11724 AIR BASE RD ADELANTO CA 92301 ***Global ID*	*Status:*** T0607100928 |	W	0.47 / 2,481.34	-7	368
47	DEED	George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop	12985 Aerospace Drive Victorville CA 92394	NNE	0.47 / 2,488.41	-19	371
47	LUST	George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop	12985 Aerospace Drive Victorville CA 92394 ***Global ID*	*Status:*** T10000002045 |	NNE	0.47 / 2,488.41	-19	372
48	CLEANUP SITES	George Air Force Base - SS024 Building 580 OU3 unserviced transformer storage	18374 Phantom West St Victorville CA -92392 ***Global ID:*** DOD100226300	NNE	0.50 / 2,629.30	-20	377
48	DEED	George Air Force Base - SS024 Building 580 OU3 unserviced transformer storage	18374 Phantom West St Victorville CA -92392	NNE	0.50 / 2,629.30	-20	381
49	INSP COMP ENF	ANCON MARINE - VICTORVILLE - CAD980737068	13313 SABRE BLVD UNIT 1 VICTORVILLE CA 92394	NNE	0.63 / 3,328.58	-21	381
50	ENVIROSTOR	Sumiden Wire Products Corp.	13290 Sabre Boulevard Victorville CA 92394 ***Envirostor ID:*** 71003480 ***Cleanup Status:*** INACTIVE - NEEDS EVALUATION AS OF	NNE	0.78 / 4,098.44	-25	382
51	ENVIROSTOR	VV ARMY FLYING SCHOOL	Victorville CA ***Envirostor ID:*** 80000869 ***Cleanup Status:*** INACTIVE - NEEDS EVALUATION AS OF 7/1/2005	NE	0.78 / 4,109.50	-24	383
51	ENVIROSTOR	VICTORVILLE AFB	Victorville CA ***Envirostor ID:*** 80000728 ***Cleanup Status:*** INACTIVE - NEEDS EVALUATION AS OF 7/1/2005	NE	0.78 / 4,109.50	-24	384
52	ENVIROSTOR	GEORGE AIR FORCE BASE	18374 PHANTOM WEST ST VICTORVILLE CA 923920000 ***Envirostor ID:*** 80001244 ***Cleanup Status:*** REFER: RWQCB AS OF 12/7/2018	NNE	0.80 / 4,215.80	-26	386
52	HWP	GEORGE AIR FORCE BASE	18374 PHANTOM WEST ST VICTORVILLE CA 923920000	NNE	0.80 / 4,215.80	-26	390

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Envirostor ID: CA2570024453				
52	RCRA CORRACTS	AIR FORCE REAL PROPERTY AGENCY	18374 PHANTOM STREET VICTORVILLE CA 95652	NNE	0.80 / 4,215.80	-26	394
			***Handler ID	Recycler Activity?:*** CA2570024453	NO		

Executive Summary: Summary by Data Source

Standard

Federal

NPL - National Priority List

A search of the NPL database, dated Jan 18, 2026 has found that there are 1 NPL site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	ENE	0.00 / 0.00	1
	***EPA ID**: CA2570024453*			

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	WNW	0.01 / 35.78	7
	***Site EPA ID**: CA2570024453*			

RCRA CORRACTS - RCRA CORRACTS-Corrective Action

A search of the RCRA CORRACTS database, dated Nov 30, 2025 has found that there are 1 RCRA CORRACTS site(s) within approximately 1.00miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
AIR FORCE REAL PROPERTY AGENCY	18374 PHANTOM STREET VICTORVILLE CA 95652	NNE	0.80 / 4,215.80	52
	***Handler ID**	**Recycler Activity?**: CA2570024453	NO*		

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Nov 30, 2025 has found that there are 2 RCRA SQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
TRAFFIX DEVICES INC	12128 YUCCA RD ADELANTO CA 92301	W	0.18 / 930.94	28
	***Handler ID**	**Recycler Activity?**: CAR000083592	NO*		
VALEW WELDING AND FABRICATION	12522 VIOLET RD ADELANTO CA 92301	SW	0.21 / 1,099.76	31
	***Handler ID**	**Recycler Activity?**: CAR000095141	NO*		

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Nov 30, 2025 has found that there are 18 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE LINING & COATING INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9
	***Handler ID | Recycler Activity?**: CAL000364933 | NO*			
MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9
	***Handler ID | Recycler Activity?**: CAL000471420 | NO*			
SOIL SAFE OF CALIFORNIA INC	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	21
	***Handler ID | Recycler Activity?**: CAL000298752 | NO*			
HIGH DESERT RECYCLING	12325 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 683.83	22
	***Handler ID | Recycler Activity?**: CAL000464648 | NO*			
A H TRANSPORTATION GROUP	12191 HIBISCUS RD ADELANTO CA 92301	W	0.15 / 775.78	26
	***Handler ID | Recycler Activity?**: CAL000429595 | NO*			
PARAMOUNT ROLL & FORMING, INC.	12231 HIBISCUS ROAD ADELANTO CA 92301	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAC003252796 | NO*			
PARAMOUNT ROLL & FORMING INC	12231 HIBISCUS RD BLDG 2 ADELANTO CA 92301	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000482107 | NO*			
PARAMOUNT ROLL & FORMING INC	12231 HIBISCUS RD BLDG #2 ADELANTO CA 92301	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000482208 | NO*			
MWC GROUP INC	12231 HIBISCUS RD ADELANTO CA 92301	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000493962 | NO*			
SOUTHLAND MIXER SERVICES INC	12231 HIBISCUS RD ADELANTO CA 92301-1702	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000287666 | NO*			
WITHOUT BORDERS TRANSPORT INC	12231 HIBISCUS RD ADELANTO CA 92371	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000431745 | NO*			
LOYAL BROTHERS TRUCK REPAIR INC	12231 HIBISCUS RD ADELANTO CA 92301	W	0.17 / 898.78	27
	***Handler ID | Recycler Activity?**: CAL000409594 | NO*			

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
COAST RUBBER PRODUCTS	12128 YUCCA RD ADELANTO CA 92301	W	0.18 / 930.94	28
	***Handler ID | Recycler Activity?**: CAL000426709 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	WNW	0.00 / 0.00	3
	***Handler ID | Recycler Activity?**: CAC003125475 | NO*			
AAA TIRE SHOP	17664 ADELANTO RD #B ADELANTO CA 92301	WNW	0.06 / 309.22	14
	***Handler ID | Recycler Activity?**: CAL000470969 | NO*			
DHL SUPPLY CHAIN - MARS	13133 INNOVATION WAY SUITE 100 VICTORVILLE CA 92394	NNE	0.10 / 527.91	17
	***Handler ID | Recycler Activity?**: CAC002963703 | NO*			
UNITED FURNITURE INDUSTRIES INC	13133 INNOVATION WAY STE 200 VICTORVILLE CA 92394	NNE	0.10 / 527.91	17
	***Handler ID | Recycler Activity?**: CAL000442896 | NO*			
CALNEV PIPE LINE LLC - ADELANTO JUNCTION	AIR EXPRESSWAY AND ADELANTO RD ADELANTO CA 92301	WNW	0.11 / 556.26	18
	***Handler ID | Recycler Activity?**: CAP000253971 | NO*			

FED ENG - Federal Engineering Controls-ECs

A search of the FED ENG database, dated Jan 30, 2026 has found that there are 1 FED ENG site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	WNW	0.01 / 35.78	7
	***EPA ID**: CA2570024453*			

FED INST - Federal Institutional Controls- ICs

A search of the FED INST database, dated Jan 30, 2026 has found that there are 1 FED INST site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	WNW	0.01 / 35.78	7
	***EPA ID**: CA2570024453*			

ERNS - Emergency Response Notification System

A search of the ERNS database, dated Feb 8, 2026 has found that there are 7 ERNS site(s) within approximately 0.02miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	1334 AIR EXPRESS WAY VICTORYVILLE CA 92392 ***NRC Report No**: 843835*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No**: 795717*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESSWAY VICTORVILLE CA ***NRC Report No**: 823858*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESSWAY ROAD VICTORVILLE CA 92394 ***NRC Report No**: 905367*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No**: 884663*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESS WAY VICTORVILLE CA ***NRC Report No**: 834574*	ENE	0.02 / 104.47	10
	13334 AIR EXPRESSWAY VICTORVILLE CA 92868 ***NRC Report No**: 825576*	ENE	0.02 / 104.47	10

SUPERFUND ROD - Superfund Decision Documents

A search of the SUPERFUND ROD database, dated Jan 30, 2026 has found that there are 1 SUPERFUND ROD site(s) within approximately 1.00miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 9239	WNW	0.01 / 35.78	7

State

RESPONSE - State Response Sites

A search of the RESPONSE database, dated Oct 2, 2025 has found that there are 1 RESPONSE site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA VICTORVILLE CA 92392 ***Envirostor ID**: 36970005* ***Cleanup Status**: ACTIVE AS OF 7/9/2025*	ESE	0.00 / 0.00	2

ENVIROSTOR - EnviroStor Database

A search of the ENVIROSTOR database, dated Oct 2, 2025 has found that there are 4 ENVIROSTOR site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Sumiden Wire Products Corp.	13290 Sabre Boulevard Victorville CA 92394 ***Envirostor ID**: 71003480* ***Cleanup Status**: INACTIVE - NEEDS EVALUATION AS OF*	NNE	0.78 / 4,098.44	50
VV ARMY FLYING SCHOOL	Victorville CA ***Envirostor ID**: 80000869* ***Cleanup Status**: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*	NE	0.78 / 4,109.50	51
VICTORVILLE AFB	Victorville CA ***Envirostor ID**: 80000728* ***Cleanup Status**: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*	NE	0.78 / 4,109.50	51
GEORGE AIR FORCE BASE	18374 PHANTOM WEST ST VICTORVILLE CA 923920000 ***Envirostor ID**: 80001244* ***Cleanup Status**: REFER: RWQCB AS OF 12/7/2018*	NNE	0.80 / 4,215.80	52

SWF/LF - Solid Waste Information System (SWIS)

A search of the SWF/LF database, dated Feb 20, 2026 has found that there are 1 SWF/LF site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Soil Safe of California, Inc.	12328 Hibiscus Avenue Adelanto CA 92301 ***Act Opl Status**	**Activity**: Active | Contaminated Soil Transfer/Processing Operation*	W	0.13 / 671.18	21

HWP - EnviroStor Hazardous Waste Facilities

A search of the HWP database, dated Oct 2, 2025 has found that there are 2 HWP site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
TPS TECHNOLOGIES INC	12328 HIBISCUS RD ADELANTO CA 923011700 ***Envirostor ID**: CAL930834777*	W	0.13 / 671.18	21

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	18374 PHANTOM WEST ST VICTORVILLE CA 923920000 ***Envirostor ID**: CA2570024453*	NNE	0.80 / 4,215.80	52

C&D DEBRIS RECY - Construction and Demolition Debris Recyclers

A search of the C&D DEBRIS RECY database, dated Jun 20, 2018 has found that there are 1 C&D DEBRIS RECY site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SOIL SAFE OF CALIFORNIA, INC.	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	21

CONTAINER RECY - Listing of Certified Dropoff, Collection, and Community Service Programs

A search of the CONTAINER RECY database, dated Jul 18, 2025 has found that there are 1 CONTAINER RECY site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Federal Bureau of Prisons/Federal Correctional Complex Recycling	13777 Air Expway Victorville CA 92394	E	0.23 / 1,231.74	33

LDS - Land Disposal Sites

A search of the LDS database, dated Aug 11, 2025 has found that there are 1 LDS site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SOIL SAFE - ADELANTO SOIL RECYCLING CENTER	12328 HIBISCUS AVE ADELANTO CA 92301	W	0.13 / 671.18	21

LUST - Leaking Underground Fuel Tank Reports

A search of the LUST database, dated Sep 14, 2025 has found that there are 5 LUST site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TURNER FORD	17909 ADELANTO RD ADELANTO CA 92301 ***Global ID*** **|** ***Status***: *T0607100733* |	WNW	0.29 / 1,557.14	35
ADELANTO SCHOOL DISTRICT	11824 AIR BASE RD ADELANTO CA 92301 ***Global ID*** **|** ***Status***: *T0607100739* |	W	0.34 / 1,782.96	37
George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST Victorville CA 92392 ***Global ID*** **|** ***Status***: *T10000001719* |	NE	0.39 / 2,063.73	42
CIRCLE K#8644	11724 AIR BASE RD ADELANTO CA 92301 ***Global ID*** **|** ***Status***: *T0607100928* |	W	0.47 / 2,481.34	46
George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop	12985 Aerospace Drive Victorville CA 92394 ***Global ID*** **|** ***Status***: *T10000002045* |	NNE	0.47 / 2,488.41	47

UST - Permitted Underground Storage Tank (UST) in GeoTracker

A search of the UST database, dated Feb 20, 2026 has found that there are 1 UST site(s) within approximately 0.25miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Frontier California Inc.: Adelanto CO	17640 Adelanto Rd Adelanto CA 92301	W	0.04 / 189.66	11
	***Facility ID**: FA0007064* ***Tank ID No. | Tank Status | Tank Closure Date**: 1 | Confirmed/Updated Information |*			

AST - Aboveground Storage Tanks

A search of the AST database, dated Aug 31, 2009 has found that there are 1 AST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
TPST SOIL RECYCLERS OF CALIFORNIA	12328 HIBISCUS ADELANTO CA 92301	W	0.13 / 671.18	21

CERS TANK - California Environmental Reporting System (CERS) Tanks

A search of the CERS TANK database, dated Jan 12, 2026 has found that there are 1 CERS TANK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Soil Safe-Adelanto Soil Recycling Center	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	21
	***Site ID**: 163019*			

DEED - Deed Restrictions and Land Use Restrictions

A search of the DEED database, dated Sep 13, 2025 has found that there are 12 DEED site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
George Air Force Base - DP001 OU3 Paint Drum Burial	18374 Phantom West St Victorville CA 92394-1504	NE	0.05 / 246.61	12
CALNEV Terminal GEORGE AFB Jet Fuel Spill	13334 Air Expressway Blvd. VICTORVILLE CA	ENE	0.11 / 600.05	19
George Air Force Base - OT072 OU5 Current Skeet Range	18374 Phantom West St Victorville CA -92392	NE	0.12 / 631.20	20
George Air Force Base - LF036 OU3 Construction debris/trash	18374 Phantom West St Victorville CA 92392-1504	NW	0.23 / 1,189.93	32

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal	18374 Phantom West St Victorville CA -92392	NNW	0.33 / 1,751.12	36
George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range	(Building 615) 18374 Phantom West St Victorville CA -92392	NNE	0.37 / 1,959.08	40
George Air Force Base - OT074 OU5 Original Skeet Range	18374 Phantom West St Victorville CA 92392	NE	0.38 / 1,994.65	41
George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field	18374 Phantom West St Victorville CA -92392	NE	0.38 / 1,994.65	41
George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST Victorville CA 92392	NE	0.39 / 2,063.73	42
George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL Disposal	18374 Phantom West St Victorville CA -92392	NNE	0.45 / 2,392.35	45
George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop	12985 Aerospace Drive Victorville CA 92394	NNE	0.47 / 2,488.41	47
George Air Force Base - SS024 Building 580 OU3 unserviced transformer storage	18374 Phantom West St Victorville CA -92392	NNE	0.50 / 2,629.30	48

CLEANUP SITES - GeoTracker Cleanup Program Sites

A search of the CLEANUP SITES database, dated Sep 14, 2025 has found that there are 10 CLEANUP SITES site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
George Air Force Base - DP001 OU3 Paint Drum Burial	18374 Phantom West St Victorville CA 92394-1504 ***Global ID**: DOD100226200*	NE	0.05 / 246.61	12
CALNEV Terminal GEORGE AFB Jet Fuel Spill	13334 Air Expressway Blvd. VICTORVILLE CA ***Global ID**: SLT6V0083835*	ENE	0.11 / 600.05	19
George Air Force Base - OT072 OU5 Current Skeet Range	18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100234400*	NE	0.12 / 631.20	20

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
George Air Force Base - LF036 OU3 Construction debris/trash	18374 Phantom West St Victorville CA 92392-1504 ***Global ID**: DOD100235700*	NW	0.23 / 1,189.93	32
George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal	18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100235600*	NNW	0.33 / 1,751.12	36
George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range	(Building 615) 18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100235900*	NNE	0.37 / 1,959.08	40
George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field	18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100229500*	NE	0.38 / 1,994.65	41
George Air Force Base - OT074 OU5 Original Skeet Range	18374 Phantom West St Victorville CA 92392 ***Global ID**: DOD100234600*	NE	0.38 / 1,994.65	41
George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL Disposal	18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100241700*	NNE	0.45 / 2,392.35	45
George Air Force Base - SS024 Building 580 OU3 unserviced transformer storage	18374 Phantom West St Victorville CA -92392 ***Global ID**: DOD100226300*	NNE	0.50 / 2,629.30	48

DELISTED CLEANUP - Delisted Cleanup Program Sites

A search of the DELISTED CLEANUP database, dated Sep 14, 2025 has found that there are 2 DELISTED CLEANUP site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
George Air Force Base - George Air Force Base - OU2 - ST067b JP-4 AST/Bulk Fuel	Yard 18374 PHANTOM WEST ST VICTORVILLE CA -92392	NE	0.36 / 1,895.74	39
George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop	PHANTOM WEST ST VICTORVILLE CA 92392	NE	0.39 / 2,065.19	43

County

SANBERN CUPA - San Bernardino County - CUPA List

A search of the SANBERN CUPA database, dated Sep 17, 2024 has found that there are 19 SANBERN CUPA site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE COATING SOLUTIONS INC.	12766 VIOLET ADELANTO CA 92301	S	0.02 / 85.79	9
CENTURYLINK - ADELANTO - ADLNCABC	17437 Adelanto Rd Adelanto CA 92301	W	0.09 / 470.63	15
Soil Safe	12328 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 671.18	21
ADELANTO METAL RECYCLING	12325 HIBISCUS RD ADELANTO CA 92301	W	0.13 / 683.83	22
Loyal Brothers Mobile Truck Repair	12231 Hibiscus Rd Adelanto CA 92301	W	0.17 / 898.78	27
MORRISON EQUIPMENT/HEAVY DUTY GATES INC	12231 HIBISCUS RD UNIT 2 ADELANTO CA 92301	W	0.17 / 898.78	27
RAYCO WELDING	12231 HIBISCUS UNIT C ADELANTO CA 92301	W	0.17 / 898.78	27
SOUTHLAND MIXER SERVICE, INC	12231 HIBISCUS ADELANTO CA 92301	W	0.17 / 898.78	27
DIESEL PROS	12231 HIBISCUS UNIT 1 ADELANTO CA 92301	W	0.17 / 898.78	27
EXTRA TANK LINE, INC	12231 HIBISCUS RD ADELANTO CA 92301	W	0.17 / 898.78	27
TRAFFIX DEVICES INC	12128 YUCCA RD ADELANTO CA 92301	W	0.18 / 930.94	28
VALEW WELDING AND FABRICATION	12522 VIOLET RD ADELANTO CA 92301	SW	0.21 / 1,099.76	31

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FRONTIER CALIFORNIA INC.: ADELANTO CO	17640 Adelanto Rd Adelanto CA 92301	W	0.01 / 63.36	8

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
United Furniture Industries, Inc	13133 Innovation WAY Ste 200 Victorville CA 92394	NNE	0.10 / 527.91	17
DHL - EXEL	13133 Innovation WAY Ste 100 Victorville CA 92394	NNE	0.10 / 527.91	17
SPRINT-ADELANTO	17824 ADELANTO RD ADELANTO CA 92301	WNW	0.19 / 1,005.69	30
EMPIRE ONE AUTO SERVICES	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	34
GOLDEN HAWK TOWING	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	34
Sprint Adelanto POP/REGEN CAADEA	17834 Adelanto Rd Adelanto CA 92301	WNW	0.24 / 1,254.44	34

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Jan 1, 2026 has found that there are 12 FINDS/FRS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	5 VICTORVILLE CA 92392 ***Registry ID**: 110033619813*	ESE	0.00 / 0.00	2
MOBILE COATING SOLUTIONS	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID**: 110071765817*	S	0.02 / 85.79	9
MOBILE PIPE LINING AND COATING, INC.	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID**: 110071764766*	S	0.02 / 85.79	9
UNDERGROUND SOLUTIONS INC DBA MOBILE PIPE LINING	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID**: 110070318896*	S	0.02 / 85.79	9

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID**: 110065163673*	S	0.02 / 85.79	9
MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301 ***Registry ID**: 110071291812*	S	0.02 / 85.79	9
MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET ROAD ADELANTO CA 92301-2706 ***Registry ID**: 110014324070*	S	0.02 / 85.79	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301 ***Registry ID**: 110071114147*	WNW	0.00 / 0.00	3
VERIZON ADELANTO1	17640 ADELANTO RD. ADELANTO CA 92301 ***Registry ID**: 110071765790*	W	0.01 / 63.36	8
FRONTIER - ADELANTO # 1	17640 ADELANTO ROAD ADELANTO CA 92301 ***Registry ID**: 110071764845*	W	0.01 / 63.36	8
VERIZON ADELANTO1	17640 ADELANTO ROAD ADELANTO CA 92301-1744 ***Registry ID**: 110021317724*	W	0.01 / 63.36	8
CALNEV TERMINAL GEORGE AFB JET FUEL SPILL	13334 AIR EXPRESSWAY BLVD. VICTORVILLE CA 92394 ***Registry ID**: 110066125767*	ENE	0.02 / 104.47	10

PFAS NPL - PFOA/PFOS Contaminated Sites

A search of the PFAS NPL database, dated Dec 29, 2025 has found that there are 1 PFAS NPL site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEORGE AIR FORCE BASE	AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392 ***Identifier**: CA2570024453*	WNW	0.01 / 35.78	7

PFAS IND - PFAS Industry Sectors

A search of the PFAS IND database, dated Feb 16, 2026 has found that there are 5 PFAS IND site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SOIL SAFE - ADELANTO	ADELANTO CA	W	0.10 / 517.01	16
MOBILE PIPE WRAPPERS & COATERS	ADELANTO CA	S	0.13 / 697.50	23
MOBILE COATING SOLUTIONS	ADELANTO CA	S	0.13 / 712.55	24
MOBILE PIPE WRAPPERS & COATERS	ADELANTO CA	S	0.13 / 712.56	25
COMAV TECHNICAL SERVICES	VICTORVILLE CA	E	0.36 / 1,881.57	38

ICIS - Integrated Compliance Information System (ICIS)

A search of the ICIS database, dated Oct 18, 2025 has found that there are 1 ICIS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE WRAPPERS & COATERS, INC.	12766 VIOLET ROAD ADELANTO CA 92301 ***Registry ID**: 110014324070*	S	0.02 / 85.79	9

AFS - Air Facility System

A search of the AFS database, dated Oct 17, 2014 has found that there are 1 AFS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE WRAPPERS & COATERS, INC.	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9

State

INSP COMP ENF - EnviroStor Inspection, Compliance, and Enforcement

A search of the INSP COMP ENF database, dated Feb 9, 2026 has found that there are 1 INSP COMP ENF site(s) within approximately 1.00miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ANCON MARINE - VICTORVILLE - CAD980737068	13313 SABRE BLVD UNIT 1 VICTORVILLE CA 92394	NNE	0.63 / 3,328.58	49

CHMIRS - California Hazardous Material Incident Report System (CHMIRS)

A search of the CHMIRS database, dated Jul 11, 2025 has found that there are 8 CHMIRS site(s) within approximately 0.02miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Victorville City Fire	Airbase Rd. and Phantom Rd. Victorville CA	ENE	0.00 / 23.48	4
	***Control No | Notified Date**: 1/22/199902:12:46 PM*			
Hazmat One	Air Expressway at Adelanto Rd. Victorville CA	NNE	0.01 / 31.13	6
	***Control No | Notified Date**: 14-1107 |*			
Verizon California Inc.	17640 Adelanto Rd. Adelanto CA	W	0.01 / 63.36	8
	***Control No | Notified Date**: 12-3863 |*			
Kinder Morgan	13334 Air Express Way Victorville CA	ENE	0.02 / 104.47	10
	***Control No | Notified Date**: 07-0338 |*			
Kinder Morgan	13334 Air Express Way Victorville CA 92392	ENE	0.02 / 104.47	10
	***Control No | Notified Date**: 07-0783 |*			
Kinder Morgan	13334 Air Express Way Victorville CA 92392	ENE	0.02 / 104.47	10
	***Control No | Notified Date**: 07-4551 |*			
Kinder Morgan	13334 Air Express Way Victorville CA 92394	ENE	0.02 / 104.47	10
	***Control No | Notified Date**: 07-2762 |*			
Kinder Morgan	13334 Air Expressway Rd Victorville CA 92394	ENE	0.02 / 104.47	10
	***Control No | Notified Date**: 09-3605 |*			

HAZNET - Handlers from Hazardous Waste Manifest Data

A search of the HAZNET database, dated Feb 20, 2025 has found that there are 4 HAZNET site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BECK OIL INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CITY OF VICTORVILLE	GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	WNW	0.00 / 0.00	3

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONTEL ADELANTO CO	17640 ADELANTO RD ADELANTO CA 923010000	W	0.01 / 63.36	8
KINDER MORGAN	13334 AIR EXPRESS WAY VICTORVILLE CA 92392	ENE	0.02 / 104.47	10

HAZ GEN - Generators from Hazardous Waste Manifest Data

A search of the HAZ GEN database, dated Feb 20, 2025 has found that there are 7 HAZ GEN site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE COATING SOLUTIONS INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9
MOBILE PIPE LINING & COATING INC	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9
MOBILE PIPE WRAPPERS & COATERS INC	12766 VIOLET RD ADELANTO CA 923010000	S	0.02 / 85.79	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FEDERAL CORRECTIONS COMPLEX	13289 AIRBASE RD VICTORVILLE CA 923940000	ENE	0.01 / 26.50	5
VERIZON CALIFORNIA INC	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	8
VERIZON CALIFORNIA INC	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	8
VERIZON CALIFORNIA INC.	17640 ADELANTO RD ADELANTO CA 923011744	W	0.01 / 63.36	8

HIST MANIFEST - Historical Hazardous Waste Manifest Data

A search of the HIST MANIFEST database, dated Dec 31, 1992 has found that there are 1 HIST MANIFEST site(s) within approximately 0.02miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	17640 ADELANTO RD ADELANTO CA 923010000	W	0.01 / 63.36	8

CERS HAZ - California Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the CERS HAZ database, dated Jan 12, 2026 has found that there are 3 CERS HAZ site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Mobile Coating Solutions Inc.	12766 VIOLET RD ADELANTO CA 92301	S	0.02 / 85.79	9
CENTURYLINK - ADELANTO - ADLNCABC	17437 ADELANTO RD ADELANTO CA 92301	W	0.09 / 470.63	15

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Exel	13133 INNOVATION WAY STE 100 VICTORVILLE CA 92394	NNE	0.10 / 527.91	17

DELISTED HAZ - Delisted Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the DELISTED HAZ database, dated Nov 29, 2018 has found that there are 1 DELISTED HAZ site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Pacific Aerospace	18200 PHANTOM W VICTORVILLE CA 92394	NE	0.40 / 2,090.45	44

EMISSIONS - Toxic Pollutant Emissions Facilities

A search of the EMISSIONS database, dated Dec 31, 2023 has found that there are 25 EMISSIONS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE WRAPPERS & COATERS	12766VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9
MOBILE PIPE LINING AND COATING	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9
MOBILE PIPE WRAPPERS & COATERS	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBILE PIPE LINING AND COATING, INC.	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9
MOBILE COATING SOLUTIONS	12766 VIOLET ROAD ADELANTO CA 92301	S	0.02 / 85.79	9
GST TELECOM CALIFORNIA - ADELANTO RD.	17437 ADELANTO ROAD ADELANTO CA 92301	W	0.09 / 470.63	15
TW TELECOM - ADELANTO RD	17437 ADELANTO ROAD ADELANTO CA 92301	W	0.09 / 470.63	15
TPS TECHNOLOGIES INC.	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	21
SOIL SAFE OF CALIFORNIA, INC	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	21
SOIL SAFE - ADELANTO	12328 HIBISCUS AVENUE ADELANTO CA 92301	W	0.13 / 671.18	21
SOUTHLAND MIXER SERVICE, INC	12231 HIBISCUS ROAD ADELANTO CA 92301	W	0.17 / 898.78	27
TRAFFIX DEVICES, INC. DBA COAST RUBBER PRODUCTS	12128 YUCCA ROAD ADELANTO CA 92301	W	0.18 / 930.94	28
CALIFORNIA SILICA PRODUCTS LLC	12808 RANCHO ROAD ADELANTO CA 92301	S	0.18 / 939.79	29
CALIFORNIA SILICA PRODUCTS LLC	12808 RANCHO RD ADELANTO CA 92301	S	0.18 / 939.79	29
DIVERSIFIED MINERALS, INC.	12808 RANCHO RD ADELANTO CA 92301	S	0.18 / 939.79	29
VALEW WELDING & FABRICATION, INC	12522 VIOLET ROAD ADELANTO CA 92301	SW	0.21 / 1,099.76	31


Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VERIZON-ADELANTO C.O.	17640 ADELANTO ROAD ADELANTO CA 92301	W	0.01 / 63.36	8
VERIZON ADELANTO1	17640 ADELANTO RD. ADELANTO CA 92301	W	0.01 / 63.36	8
FRONTIER - ADELANTO # 1	17640 ADELANTO ROAD ADELANTO CA 92301	W	0.01 / 63.36	8
UNITED FURNITURE INDUSTRIES	13133 INNOVATION WAY VICTORVILLE CA 92394	NNE	0.10 / 527.91	17
SCI LOT 1 - INNOVATION WAY	13133 INNOVATION WAY VICTORVILLE CA 92392	NNE	0.10 / 527.91	17
DC1	13133 INNOVATION WAY VICTORVILLE CA 92392	NNE	0.10 / 527.91	17
SPRINT	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	34
SPRINT ADLNCAUS	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	34
COGENT ADLNCAUS	17834 ADELANTO RD ADELANTO CA 92301	WNW	0.24 / 1,254.44	34

CDL - Clandestine Drug Lab Sites

A search of the CDL database, dated Dec 13, 2024 has found that there are 1 CDL site(s) within approximately 0.12miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	17664 1/2 ADELANO ROAD ADELANTO CA 92301	WNW	0.06 / 299.93	13



Map: 1.0 Mile Radius


Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial


Year: 2024

Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Year: 2021

Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, CA

Quadrangle(s): Victorville CA, Adelanto CA

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 1	ENE	0.00 / 0.00	2,907.60 / 0	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	NPL

EPA ID: CA2570024453
Data Source: U.S. EPA Superfund Program. Source: SEMS Superfund Public User Database. FOIA4 All Final NPL Sites. (as of 26 Dec 2025); U.S. EPA Site Boundaries Shapefile Download (as of 18 Jan 2026); Superfund NPR Sites with Status Information (as of 8 Jan 2026)

NPL (FOIA-004 All Final NPL Sites)

NPL Status Dt: 02/21/90
Federal Facility: Yes
SAA (Superfund Alt):
NAI: No
NA Entity (NAI Status):
Site Name: GEORGE AIR FORCE BASE
Address: AIR BASE RD- NR ST RTE 395
City: VICTORVILLE
Zip: 92392
State: CA
Region: 09
County: SAN BERNARDINO
Latitude: +34.595000
Longitude: -117.383300

NPL (Superfund Sites List)

SEMS ID: 902737
SITS ID: 1144
Site Score: 33.62
Status: NPL Site
Proposed Date: 07/14/1989
Listing Date: 02/21/1990
NOID Date:
Deletion Date:
Notice of Data Availability:
Site Name: George Air Force Base
City: Victorville
Site Listing Narrative URL: https://semspub.epa.gov/src/document/09/2400162
Site Progress Profile URL: https://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0902737
Proposed Fr Notice URL: https://semspub.epa.gov/src/document/11/189650
Final Fr Notice URL: https://semspub.epa.gov/src/document/11/189635
NOID Fr Notice URL:
Deletion Fr Notice URL:
Restoration Fr Notice URL:
Site Partial Deletion URL: No
Constr Complete No: 0
Constr Complete Dt:
Region: 9
State: California
County: San Bernardino
Latitude: 34.595
Longitude: -117.3833

NPL (EPA Boundaries)

EPA Program: Superfund
Npl Status Code: F
Federal Facility Deter Code: Yes
Region Code: 9
County: SAN BERNARDINO
Site Contact Name: John Hopkins
Site Contact Email: hopkins.john@epa.gov
Feature Info Url:
Feature Info Url Desc:
GIS Area: 8.26891485
GIS Area Units: Miles
Primary Telephone No: (628) 204-9004

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Feature Class: 5
Site Feature Type: Site Boundary
Site Feature Name: Total Site Boundary
Site Feature Source: Site Boundary based on GIS data provided by previous RPM.
Site Feature Description: Site Boundary based on GIS data provided by previous RPM.
Projection:
Sf Geospatial Data Disclaimer:
Addr Comment:
URL Alias Txt: https://www.epa.gov/superfund/georgeafb

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of 2	ESE	0.00 / 0.00	2,923.04 / 16	GEORGE AIR FORCE BASE 5 VICTORVILLE CA 92392	FINDS/FRS

Registry ID: 110033619813
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 18-MAR-08
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: DTSC-ENVIROSTOR
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091164107
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude: 34.5625
Longitude: -117.375
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110033619813
Program Acronyms:

DTSC-ENVIROSTOR:36970005

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	2 of 2	ESE	0.00 / 0.00	2,923.04 / 16	GEORGE AIR FORCE BASE 5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA VICTORVILLE CA 92392	RESPONSE

Envirostor ID: 36970005
Site History:

George Air Force Base (GAFB) is a 5,347 - acre facility located within Victor Valley, San Bernardino County approximately 70 miles northeast of the City of Los Angeles. GAFB was initially activated on October 1, 1941 as Victorville Army Airfield. From 1950 to 1992, GAFB was a tactical jet fighter operation training facility. Several investigations have been conducted under the USAF's IRP at GAFB. During the Phase I investigation, 54 sites were formerly identified as known or suspected to have received hazardous materials in the past (1982). Groundwater containinated with Trichloroethylene (TCE) has been documented both on and off base. Additional hazardous wastes on the base include: asbestos, pesticides, paint, paint thinner, sludges, fuels (jp-4), petroleum lubricant and oils (POLs), leaded tank bottoms, explosives, polychlorinated biphenyls (PCBs), solvents, acids, metals, low level radioactive wastes, and hospital wastes. Past mitigation activities conducted at the base include site characterization and installation of a groundwater extraction and treatment system (Air Stripper). The site was listed on the NPL in 1989. A Federal Facilities Agreement (FFA) between the Department, U.S. EPA, Lahontan RWQCB, and the Air Force was signed in September 1990. The FFA outlines the investigation and mitigation process for the Base.

GAFB closed on December 5, 1992. The Base was the first in California to close under the BRAC I program.

Facilities Details

Estor/EPA ID:	36970005	***Site Code:***	400071
Program Type:	FEDERAL SUPERFUND - LISTED	***APN:***	NONE SPECIFIED
Program Type1:		***Assembly District:***	39
Status:	ACTIVE	***Census Tract:***	6071009116
Site Facility Name:	GEORGE AIR FORCE BASE	***Funding:***	BRAC LEGACY
Site Type:	CLOSED BASE	***Office:***	ENGINEERING & SPECIAL PROJECTS
Address Description:	5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA	***Project Manager:***	ANDREW REIMANIS
City:	VICTORVILLE	***Special Program:***	
County:	SAN BERNARDINO	***Supervisor:***	DUANE WHITE
Zip:	92392	***Senate District:***	23
Acres:	5347 ACRES		

Public Participation Specialis:
CalEnviroScreen Score: 75-80%
National Priorities List: YES
Past Use that Caused Contam: NONE SPECIFIED
Permit Renewal Lead:
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM
RWQCB 6V - LAHONTAN - LEAD AGENCY
US EPA
Cleanup Status: ACTIVE AS OF 7/9/2025
Potential Cont of Conc: ASBESTOS CONTAINING MATERIALS (ACM)
PESTICIDES - WASTES FROM PRODUCTION
SLUDGE - PAINT
UNSPECIFIED OIL CONTAINING WASTE
UNSPECIFIED SLUDGE WASTE
Potential Media Affected: NONE SPECIFIED
School District:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005

Currently Scheduled Activities

Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Due Date: 3/15/2026
Revised Date:
Activity Type: Currently Scheduled Activities Through 6/30/2026

Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation / Feasibility Study
Due Date: 5/31/2026
Revised Date:
Activity Type: Currently Scheduled Activities Through 6/30/2026

Future Activities

Area Name:
Area Link:
Sub Area: MMRP sites XU-400 and SR 401
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2009851
Document Type: Record of Decision
Due Date: 2027
Activity Type: Future Activities

Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-H
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004021
Document Type: Finding of Suitability to Transfer
Date Completed: 6/10/1994
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: P-B
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004014
Document Type: Environmental Baseline Survey
Date Completed: 7/31/1995
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: RAIL
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004026
Document Type: Finding of Suitability to Transfer
Date Completed: 3/19/1998
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001005
Area Name:
Area Link:
Sub Area: SS-52
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004030
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: SEWER
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004029
Document Type: Environmental Baseline Survey
Date Completed: 3/7/1997
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: LF-14
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004010
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name:
Area Link:
Sub Area: LFDS
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004011
Document Type: Feasibility Study Report
Date Completed: 2/28/1994
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: P-J
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004023
Document Type: Environmental Baseline Survey
Date Completed: 10/31/1995
Comments:
Activity Type: Completed Activities

Title: Remedial Investigation Report OU3 MMRP Sites DP033,DP034,XU400, and SR401
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60317674
Area Name:
Area Link:
Sub Area: MMRP sites XU-400 and SR 401
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2009851
Document Type: Remedial Investigation Report
Date Completed: 9/8/2021
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-K
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004024
Document Type: Finding of Suitability to Transfer
Date Completed: 6/2/1994
Comments:
Activity Type: Completed Activities

Title: * CEQA
Title Link:
Area Name:
Area Link:
Sub Area: GW
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004005
Document Type: * CEQA
Date Completed: 11/25/1991
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001002
Area Name:
Area Link:
Sub Area: DP-34
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004003
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: * Operations and Maintenance Workplan / Report
Title Link:

Area Name:	OU1
Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970161&hideside=True&printerfriendly=True
Sub Area:	
Sub Area Link:	
Document Type:	Operation and Maintenance Plan
Date Completed:	9/10/1997
Comments:	OM - OU-1: As a result of a Record of Decision which was signed in February 1994, the Air Force installed 9 extrac- tion wells to simultaneously contain a TCE plume, extract and treat in fluent waters contaminated with volatile organic compounds and discharge to the percolation ponds. The percolation ponds were established expressly to receive and flush volatile organics into the existing extraction wells. In 1996 the Air Force implemented Phase II, which is comprised of nine additional extraction wells and a complete rewiring of the existing system. The Operation and Mainten- ance Manual being approved addresses: system description, environmental controls, equipment components, service schedules, startup/normal operation and shutdown procedures and other information needed to operate the system. The system is performing well and is expected to run for a total of 30 years. At this time it costs approximately $400,000.00 a year to operate, mostly in electrical costs and routine maintenance.
Activity Type:	Completed Activities
Title:	Reuse - Finding of Suitability to Transfer
Title Link:	
Area Name:	
Area Link:	
Sub Area:	STORM
Sub Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004031
Document Type:	Finding of Suitability to Transfer
Date Completed:	10/8/1997
Comments:	
Activity Type:	Completed Activities
Title:	Reuse - Site Specific Environmental Baseline Survey
Title Link:	
Area Name:	
Area Link:	
Sub Area:	P-G
Sub Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004020
Document Type:	Environmental Baseline Survey
Date Completed:	9/30/1995
Comments:	
Activity Type:	Completed Activities
Title:	* Engineering Evaluation / Cost Analysis
Title Link:	
Area Name:	
Area Link:	
Sub Area:	NDA
Sub Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004012
Document Type:	* Engineering Evaluation / Cost Analysis
Date Completed:	10/1/1991
Comments:	
Activity Type:	Completed Activities
Title:	Reuse - Finding of Suitability to Lease
Title Link:	
Area Name:	
Area Link:	
Sub Area:	P-D
Sub Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004016
Document Type:	Finding of Suitability to Lease
Date Completed:	9/7/1995
Comments:	
Activity Type:	Completed Activities
Title:	Reuse - Finding of Suitability to Transfer
Title Link:	
Area Name:	
Area Link:	
Sub Area:	P-G
Sub Area Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004020

Document Type: Finding of Suitability to Transfer
Date Completed: 10/10/1997
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Date Completed: 5/5/1995
Comments:
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name:
Area Link:
Sub Area: LFDS
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004011
Document Type: Feasibility Study Report
Date Completed: 3/11/1994
Comments: RIFS - LFDS -- DTSC approved a Removal Action Workplan on March 11, 1994 for the Removal Action at the Liquid Fuel Distribution System (LFDS). Approximate cost = N/A; funding = BRAC.
Activity Type: Completed Activities

Title: Public Participation Plan / Community Relations Plan
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Participation Plan / Community Relations Plan
Date Completed: 6/30/1991
Comments:
Activity Type: Completed Activities

Title: Supplemental Site Investigation Report Sites XU400 and SR401 40mm Practice Grenade Range East
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60471922
Area Name:
Area Link:
Sub Area: MMRP sites XU-400 and SR 401
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2009851
Document Type: Supplemental Site Investigation Tech Memo
Date Completed: 5/23/2022
Comments:
Activity Type: Completed Activities

Title: Remedial Action Plan
Title Link:
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan
Date Completed: 6/30/1998
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001004
Area Name:
Area Link:
Sub Area: DP-15
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004001

Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: UFP-QAPP, Addendum 1, MMRP Site XU400 Expanded, Monitoring Well Installation and Sampling Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60592712
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Monitoring Plan
Date Completed: 7/10/2025
Comments: DTSC reviewed and has no comments.
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: DP-04
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004000
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Expanded Site XU400 Munitions Amphitheater Restoration Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60585748
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 2/26/2025
Comments:
Activity Type: Completed Activities

Title: Reuse - Basewide Environmental Baseline Survey
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Environmental Baseline Survey
Date Completed: 12/9/1993
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: DP-03
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2003999
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: P-F
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004019
Document Type: Environmental Baseline Survey

Date Completed: 9/30/1995
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5000991
Area Name:
Area Link:
Sub Area: LF-08
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004008
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments: RA - DP-04: As a result of aerial GPR, subsurface geophysics including GPR, EM and MAG, extensive soil gas, surface and sub- surface test pits, the Base Closure Team (BCT), including DTSC, have agreed that sufficient information was available to implement a presumptive remedy at this site as it qualifies under EPA guidance. Numerous meetings and tele-conferences from 1990 to 1996 resulted in the BCT implementing the following activities at DP-04 as a presumptive remedy under CERCLA: restoration of the existing soil cover, garding or cutting of the surface to produce slopes of 1.5 to 3.0 percent to promote surface runoff and decrease infiltration of surface water into the refuse, installation of drainage ditches above the landfill to prevent surface water from running onto the landfills sites, installation of site perimeter fencing and posting to control site access, and re-establishment of native plant species on the graded surface. During the course of thses activities the DTSC performed field oversight and verified that revegatation, fencing and posting work was implemented as agreed to. RA - LF08, LF12, LF14, DP15, SS52, DP33, DP34, RW09, WP40, DP03 are same as DP04. RA - LF-07: From 1991 to April 1997 the Base Closure Team has been involved in Remedial Investigation/Feasiblity Study regarding the base landfills. The USEPA promotes the absence of a former EE/CA. The regulators concurred, including DTSC, while the following activities took place: restoration of the existing soil cover, grading or cutting of the surface to produce slopes of 1.5 percent to promote surface runoff and decrease infiltration of surface water into the landfill contents, installation of drainage ditches adjacent to the landfill boundaries to prevent surface water from running onto the landfill sites, installation of site perimeter fencing and signage to control site access, and re-establishment of native plant species on the graded surface.
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001016
Area Name:
Area Link:
Sub Area: FT19B
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004004
Document Type: Removal Action Completion Report
Date Completed: 3/5/1997
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001042
Area Name: OU2
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970162&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Date Completed: 3/16/1992
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: WATER
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004033
Document Type: Finding of Suitability to Transfer
Date Completed: 10/8/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Lease
Title Link:
Area Name:
Area Link:

Sub Area: P-C
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004015
Document Type: Finding of Suitability to Lease
Date Completed: 2/22/1994
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Lease
Title Link:
Area Name:
Area Link:
Sub Area: P-A
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004013
Document Type: Finding of Suitability to Lease
Date Completed: 2/22/1994
Comments:
Activity Type: Completed Activities

Title: Expanded Site XU400 Munitions Amphitheater Restoration Work Plan Amendment #1
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60592097
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 7/10/2025
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001044
Area Name:
Area Link:
Sub Area: L-3
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004006
Document Type: Removal Action Completion Report
Date Completed: 2/25/1992
Comments: RA STORM: Work consisted of removal and replacement of perf- orated sections of the east storm drain; re-routing of the normal flow bypass line with cleaning and plugging of the old section; cleaning of the upper west storm drain; and cleaning and plugging of the high flow bypass section be- tween manhole 199 and the outfall ditch. The draft RI Re- port submitted 2/4/92 indicated that the RA was complete.
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name: OU1
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970161&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Feasibility Study Report
Date Completed: 7/21/1992
Comments: Draft Final RI/FS/PP for OU#1 was approved conditioned upon Air Force submitting a proposed schedule for additional field work. There are data gaps; without the knowledge of the gross dimensions of the plume, the preferred alternative presented will not ensure complete capture of the plume.
Activity Type: Completed Activities

Title: * Engineering Evaluation / Cost Analysis
Title Link:
Area Name:
Area Link:
Sub Area: GW
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004005
Document Type: * Engineering Evaluation / Cost Analysis
Date Completed: 9/19/1991
Comments: FRIFS GW: Focused RI/FS for GW was prepared as an Engineer- ing Analysis/ Cost Analysis (EE/CA) by the Air Force. DTSC prepared a Neg. Dec. in compliance with CEQA and filed with the State Clearing House. Completion of the EE/CA was coun- ted as the focused RI/FS.

Activity Type: Completed Activities

Title: MMRP Site UX400 Expansion, Quality Assurance Program Plan (QAPP)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60520520
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Quality Assurance Workplan
Date Completed: 1/26/2024
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001007
Area Name:
Area Link:
Sub Area: RW-09
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004027
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: SEWER
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004029
Document Type: Finding of Suitability to Transfer
Date Completed: 10/8/1997
Comments:
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Feasibility Study Report
Date Completed: 7/29/1997
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: STORM
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004031
Document Type: Removal Action Completion Report
Date Completed: 2/25/1992
Comments:
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name:
Area Link:
Sub Area: RW09
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004028
Document Type: Feasibility Study Report
Date Completed: 8/15/1994
Comments: RIFS OU9 August 15, 1995 GAFB submitted in August 1994, a work plan for character- ization of low-level radioactive waste disposal site RW-09. The characterization work plan included investigation and testing of the

RW-09 disposal site to determine background levels of radiation, testing for the presence of radio- nuclide contamination (radium {Ra}-226, Ra-228, thorium {Th}-232, and tritium), and confirmation sampling for this 2.4 acres site. The work plan proposed the following activities: Excavation of soils/debris areas as discrete targets, three test pits, and other excavation areas. Transportation of excavated soils to a mechanical sizing apparatus, where soils and landfill debris will be segregated by mechanical sizing and field screening of gamma counts. Analyze collected sample for the presence of Ra-226, Ra-228, Th-232, and tritium. Field screen and sample excavation bottoms for the presence of radionuclides. Place clean backfill soils and debris into the open excavations. Properly dispose of radioactive contaminated soils and debris. Decontamination of all site equipment before demobilization. Volume Treated, Stabilized, or Disposed: Approximately 4,000 cubic yards of soil/debris were esti- mated to be excavated within the RW-09 site. All materials to be excavated were to be screened and sampled for analysis. The materials were to be fed into a feed hopper, then through screen for mechanical sizing, then conveyed beneath a plastic scintillator and detector for sampling.

Activity Type: Completed Activities

Title: * Remedial or Removal Design
Title Link:
Area Name: OU1
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970161&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: * Remedial or Removal Design
Date Completed: 2/16/1996
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-F
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004019
Document Type: Finding of Suitability to Transfer
Date Completed: 10/10/1997
Comments:
Activity Type: Completed Activities

Title: Feasibility Study Report
Title Link:
Area Name:
Area Link:
Sub Area: TCE
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004032
Document Type: Feasibility Study Report
Date Completed: 8/2/1995
Comments: RIFS TCE - During the Operable Unit Two (OU-2) JP-4 invetigation, TCE/PCE plumes were discovered. GAFB submitted on October 1, 1993 Remedial Investigation Feasibility Study (RIFS) Workplan to the agencies and implemented the investigation activities. A draft final RI/FS report was submitted to the agencies in June 1994, DTSC, the RWQCB, and USEPA met at GAFB and agreed in the meeting that GAFB needs to conduct additional investigation to determine if there are any source of contamination in the vicinity of MW-49. IF the additional field work does not reveal source of contamination, natural attenuation/monitoring will be accepted for the TCE/PCE plumes. GAFB completed the additional investigation in March 1994 and submitted in July 1995, a final RI/FS report for OU-3 TCE/PCE study area. The report summarizes the results of remedial investigation activities performed at the area and presents the development, evaluation, and recommendation of remedial alternatives. No source of contamination were discovered and the Air Force preferred remedy is natural attenuation/monitoring. The findings from the report will be integrated into the basewide RI/FS report scheduled to be sub- mitted to the agencies on August 15, 1995. A decision on the selected remedy for the TCEF/PCE study area will be documented in the basewide (OU-3) RAP/ROD. Therefore, a separate RAP/ROD will not be prepared for the TCE/PCE study area. Volume Treated, Stabilized, or Disposed: N/A Approximate cost and funding source: 1.5 million, BRAC 1
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001003
Area Name:
Area Link:
Sub Area: DP-33
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004002
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:

Activity Type: Completed Activities

Title: RI/FS Work Plan OU3 Sites DP033,DP034,WP040,SS052,XU400, and SR401
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60313177
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Site Characterization Workplan
Date Completed: 8/22/2013
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-E2
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004018
Document Type: Finding of Suitability to Transfer
Date Completed: 10/21/1994
Comments:
Activity Type: Completed Activities

Title: Community Environmental Response Facilitation Act
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Community Environmental Response Facilitation Act
Date Completed: 4/19/1994
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: WP-40
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004034
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Lease
Title Link:
Area Name:
Area Link:
Sub Area: P-B
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004014
Document Type: Finding of Suitability to Lease
Date Completed: 9/7/1995
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=5001045
Area Name:
Area Link:
Sub Area: GW
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004005
Document Type: Removal Action Completion Report
Date Completed: 2/15/1992
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-E1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004017
Document Type: Finding of Suitability to Transfer
Date Completed: 10/21/1994
Comments:
Activity Type: Completed Activities

Title: Supplemental Site Investigation Work Plan, Sites XU400 and SR401 40 mm PGR
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60410867
Area Name:
Area Link:
Sub Area: MMRP sites XU-400 and SR 401
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2009851
Document Type: Site Characterization Workplan
Date Completed: 1/3/2017
Comments: A final DTSC letter was not issued since the Federal Facility Agreement for the base does not require DTSC approval for a final secondary document.
Activity Type: Completed Activities

Title: Remedial Action Plan
Title Link:
Area Name: OU1
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970161&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan
Date Completed: 3/7/1994
Comments: ROD - OU#1 -- This Record of Decision (ROD) set forth the remedial action to be conducted to remediate groundwater contaminated by trichloroethene (TCE) beneath the Northeast Disposal Area (NEDA) and adjacent off-base areas. OU#1 includes the following sites: SD-25 (5-20), the Industrial Storm Drain, and WP-26 (5-21), the STP Percolation Ponds. No further action is planned for these sites in OU#1 as remedial activities have been completed and these sites were within acceptable risk levels based on the risk assessment performed as part of the remedial investigation. Approximate cost = $7.9 million; funding = BRAC.
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: STORM
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004031
Document Type: Environmental Baseline Survey
Date Completed: 3/7/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: WATER
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004033
Document Type: Environmental Baseline Survey
Date Completed: 3/7/1997
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: LFDS
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004011
Document Type: Removal Action Completion Report

Date Completed: 2/17/1995
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-I
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004022
Document Type: Finding of Suitability to Transfer
Date Completed: 7/1/1994
Comments:
Activity Type: Completed Activities

Title: Non-Time-Critical Removal Action Report, SR401 Small Arms Range
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36970005&doc_id=60508039
Area Name: OU3
Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&ou_id=1970163&hideside=True&printerfriendly=True
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Date Completed: 9/22/2022
Comments:
Activity Type: Completed Activities

Title: * Order
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Federal Facility Agreement
Date Completed: 9/27/1990
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Transfer
Title Link:
Area Name:
Area Link:
Sub Area: P-SS
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004025
Document Type: Finding of Suitability to Transfer
Date Completed: 1/31/1996
Comments:
Activity Type: Completed Activities

Title: Reuse - Site Specific Environmental Baseline Survey
Title Link:
Area Name:
Area Link:
Sub Area: P-D
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004016
Document Type: Environmental Baseline Survey
Date Completed: 7/31/1995
Comments:
Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: LF-12
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004009
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:

Activity Type: Completed Activities

Title: Removal Action Completion Report
Title Link:
Area Name:
Area Link:
Sub Area: LF-07
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004007
Document Type: Removal Action Completion Report
Date Completed: 12/15/1997
Comments:
Activity Type: Completed Activities

Title: Reuse - Finding of Suitability to Lease
Title Link:
Area Name:
Area Link:
Sub Area: P-J
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36970005&site_id=2004023
Document Type: Finding of Suitability to Lease
Date Completed: 10/31/1995
Comments:
Activity Type: Completed Activities

Search Results Details

Program Type: FEDERAL SUPERFUND - LISTED
Site Code: 400071
Status: ACTIVE
Status Date: 7/9/2025
CalEnviroScreen Score: 75-80%
Office: Engineering & Special Projects
PM: ANDREW REIMANIS
Supervisor: Duane White
Branch Chief: Dominique Forrester
Address Description: 5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA
Site Facility Name: GEORGE AIR FORCE BASE
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 92392
Latitude: 34.5625
Longitude: -117.375

Sites Details

Status: Active
Status Date: 7/09/2025
Site Code: 400071
Site Type: Federal Superfund
Site Type Detailed: Closed Base
Special Program: DSMOA
City: VICTORVILLE
County: SAN BERNARDINO
Congre Dist: 23
State: CA
Latitude: 34.5625
Longitude: -117.375
Assembly: 39
Division Branch: Engineering & Special Projects
Funding: BRAC Legacy
Lead Agency: RWQCB 6V - Lahontan
Project Manager: Andrew Reimanis
Supervisor: Duane White
Restricted Use: NO
Senate: 23
Site Mgmt Req: NONE SPECIFIED
Acres: 5347
Zip: 92392
Address: 5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA
National Priorities List: YES
APN: NONE SPECIFIED
Confirmed Coc: NONE SPECIFIED
Past Uses: NONE SPECIFIED
Potential Coc: 10196, 10197, 40001, 10077, 10179
Potential Media Affected: NONE SPECIFIED
Project Name: GEORGE AIR FORCE BASE
Regulatory Agencies Involved: SMBRP, RWQCB 6V - Lahontan, US EPA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 3	WNW	0.00 / 0.00	2,897.80 / -9	CITY OF VICTORVILLE GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	FINDS/FRS

Registry ID: 110071114147
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 28-OCT-21
Update Date:
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 339940
NAICS Code Descriptions:
Conveyor: RCRAINFO
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091164003
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude: 34.572129
Longitude: -117.39679
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: GDT-ADDRESS MATCHING (GEOCODING)
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071114147
Program Acronyms:

RCRAINFO:CAC003125475

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	2 of 3	WNW	0.00 / 0.00	2,897.80 / -9	CITY OF VICTORVILLE GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	HAZNET

EPA ID: CAC003125475
NAICS Code:
SIC Code:
Create Date:
Fac Act Ind:
Inact Date:
County: SAN BERNARDINO
County Name:
County:
Mail Name:
Mailing Addr 1:
Mailing Addr 2:

Mailing City:
Mailing State:
Mailing Zip:
Region Code:
Owner Name:
Owner Addr 1:
Owner Addr 2:
Owner City:
Owner State:
Owner Zip:
Owner Phone:
Owner Fax:

Contact Details

Contact Name: CITY OF VICTORVILLE
Mailing Street: 14343 CIVIC DRIVE
Mailing City: 14343 CIVIC DRIVE
Mailing Zip: 92392

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Phone:		7609555000				
Year:		2021				
3	3 of 3	WNW	0.00 / 0.00	2,897.80 / -9	CITY OF VICTORVILLE GATEWAY DRIVE & AIR EXPRESSWAY ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAC003125475
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	339940
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20210618	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.572129
In Handler Univ:	N	**Location Longitude:**	-117.39679
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: CA
State Waste Generator: 2
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal WrkId: ------
Permwrk ID: ------
Perm Prog: ------

Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20210630
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	CITY OF VICTORVILLE
Location Street No:	
Location Street1:	GATEWAY DRIVE & AIR EXPRESSWAY
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	CITY OF VICTORVILLE
Contact Street No:	
Contact Street1:	14343 CIVIC DRIVE
Contact Street2:	
Contact City:	VICTORVILLE
Contact State:	CA
Contact Zip:	92392
Contact Country:	
Contact Phone & Ext:	760-955-5000
Contact Fax:	
Contact Email Address:	DFROST@PATRIOTENVIRONMENTAL.COM
Contact Title:	
Owner Name:	CITY OF VICTORVILLE
Owner Type:	O
Owner Seq:	1
Operator Name:	CITY OF VICTORVILLE
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20210618
Handler Name:	CITY OF VICTORVILLE
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	14343 CIVIC DRIVE
Name:	CITY OF VICTORVILLE	***Street2:***	
Dt Became Current:		***City:***	VICTORVILLE
Dt Ended Current:		***State:***	CA
Phone:	760-955-5000	***Country:***	
Source Type:	Implementer	***Zip:***	92392
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	14343 CIVIC DRIVE
Name:	CITY OF VICTORVILLE	***Street2:***	
Dt Became Current:		***City:***	VICTORVILLE
Dt Ended Current:		***State:***	CA
Phone:	760-955-5000	***Country:***	
Source Type:	Implementer	***Zip:***	92392

4	*1 of1*	*ENE*	*0.00 / 23.48*	*2,901.99 / -5*	***Victorville City Fire*** ***Airbase Rd. and Phantom Rd.*** ***Victorville CA***	*CHMIRS*

Control No:		***Notified Date:***	1/22/199902:12:46 PM
Year:	1999	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	Yes	***Bbls:***	0
Substance:	Water/Sand/Oil	***Cups:***	0
Incident Date:	1/22/199912:00:00 AM	***Cu Ft:***	0
No of Injuries:	0	***Gals:***	75
No of Fatals:	0	***Grams:***	0
No of Evacs:	0	***Lbs:***	0
Cleanup:	Contractor	***Liters:***	0
Water:	No	***Oz:***	0
Water Way:		***Pts:***	0
City:	Victorville	***Qts:***	0
County:	San Bernardino County	***Sheen:***	0
ZIP:		***Tons:***	0
Site:	Road	***Unknown:***	0

Admin Agency: Victorville Fire Department
Location: Airbase Rd. and Phantom Rd.
Description: While hauling to an incinerator facility the substance was inadvertently dumped to the roadway. Fire standing by for cleanup contractor.

5	*1 of1*	*ENE*	*0.01 / 26.50*	*2,905.49 / -2*	***FEDERAL CORRECTIONS COMPLEX*** ***13289 AIRBASE RD*** ***VICTORVILLE CA 923940000***	*HAZ GEN*

EPA ID:	CAC001063472	***Facility County:***	36
Address 2:		***County:***	San Bernardino

Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC001063472

6	*1 of1*	*NNE*	*0.01 / 31.13*	*2,903.06 / -4*	***Hazmat One*** ***Air Expressway at Adelanto Rd.*** ***Victorville CA***	*CHMIRS*

Control No:	14-1107	***Notified Date:***	
Year:	2014	***Notified Date Time:***	

County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/dfde93b37706aa5b88257c89005cbb4a?OpenDocument

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Yes	**3 Ves >= 300 Tons:**	No
1 Substance:	Diesel	**Incident Date:**	2/24/2014
1 Measure:	Gal(s)	**Incident Time:**	825
1 Other:		**Spill Site:**	Road
1 Quantity:	100-150	**Injuries?:**	No
1 Type:	PETROLEUM	**No of Injuries:**	
1 Pipeline:	No	**Fatals?:**	No
1 Vessel >= 300 Tons:	No	**No of Fatals:**	
2 Substance:		**Evacs?:**	No
2 Quantity:		**No of Evacs:**	
2 Measure:		**Cleanup:**	Contractor
2 Type:		**Site:**	
2 Other:		**Cause:**	Mechanical
2 Pipeline:	No	**Cause Other:**	
2 Vessel >= 300 Tons:	No	**Dog No:**	
3 Substance:		**Water:**	No
3 Quantity:		**Water Way:**	
3 Measure:		**City:**	Victorville
3 Type:		**County:**	San Bernardino County
3 Other:		**ZIP:**	
3 Pipeline:	No		

Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS,CALTRANS
Location: Air Expressway at Adelanto Rd.
Description: RP states that a mechanical failure on a big rig punctured a saddle tank resulting in the release of approx. 100-150 gal of diesel onto the ground. The release is contained and cleanup is en route and no waterways were impacted.

Spill Report View

Water:		**Creation Date:**	02/24/2014 08:52 AM
Document Title:	SPILL Report		
Spill Site:	Road		
Type:	PETROLEUM		

Hazardous Materials Spill Report

Date :	02/24/2014	**Name:**	
Time:	0852	**Phone:**	
Incident Date:	02/24/2014	**Ext:**	
Incident Time:	0825	**Pag Cell:**	
Control Cal OES:	14-1107	**Prs Name:**	
Control NRC:		**Prs Phone:**	
Water Involved:	No	**Prs Ext:**	
Drink Wtr Impact:	No	**Prs Pag Cell:**	
Detail for Other:		**Incident Desc:**	
UPRR Rim No:		**Notification Info:**	
DOG Unit:		**Notification List:**	
RWQCB Unit:	6B		

Contained: Yes
Waterway:
Received By:
Cleanup By: Contractor
Incident Location: Air Expressway at Adelanto Rd.
Additional County:
1 Substance: Diesel
1 Qty: =
1 Amount : 100-150
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

1 Pipeline:	No
1 Ves >= 300 Tons:	No
2 Substance:	
2 Qty:	=
2 Amount:	
2 Measure:	
2 Type:	
2 Other:	
2 Pipeline:	No
2 Ves >= 300 Tns:	No
3 Substance:	
3 Qty:	=
3 Amount:	
3 Measure:	
3 Type:	
3 Other:	
3 Pipeline:	No
3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	None
Agency:	Hazmat One
PRS Agency:	
Sec Agency:	San Bernardino County Fire Department
Admin Agency:	Victorville Fire Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	
Header Unknown:	MOJAVE DESERT AQMD
Site:	Road
Reported Cause:	Mechanical
R R Crssing < 50 Ft:	
Description:	RP states that a mechanical failure on a big rig punctured a saddle tank resulting in the release of approx. 100-150 gal of diesel onto the ground. The release is contained and cleanup is en route and no waterways were impacted.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of5	WNW	0.01 / 35.78	2,897.01 / -10	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	CERCLIS

Site ID:	0902737	**RNPL Status Code:**	F
Site EPA ID:	CA2570024453	**NPL Status:**	Currently on the Final NPL
Site Street Address 2:		**RFED Facility Code:**	Y
Site County Name:	SAN BERNARDINO	**RFED Facility Desc:**	Federal Facility
Site FIPS Code:	06071	**USGS Hydro Unit No.:**	18090208
Region Code:	09	**Site Cong. Dist. Code:**	8
Site SMSA No.:	6780	**ROT Desc:**	Federally Owned
Site Prim. Latitude:	+34.595000	**FR NPL Update No.:**	12
Site Prim. Longitude:	-117.383300	**RFRA Code:**	F
Lat Long Source:	EPA HQ		
RNON NPL Status Desc:			

CERCLIS Site Contact Name(s)

Person ID:	13003858.00
First Name:	Sharon
Last Name:	Murray
Phone No.:	4159724250
Email:	

CERCLIS Site Contact Name(s)

Person ID:	13003854.00
First Name:	Leslie
Last Name:	Ramirez

Phone No.: 4159723978
Email:

CERCLIS Site Contact Name(s)

Person ID: 9270192.00
First Name: Nadia
Last Name: Burke
Phone No.: 4159723187
Email:

CERCLIS Site Contact Name(s)

Person ID: 13004003.00
First Name: Carl
Last Name: Brickner
Phone No.:
Email:

CERCLIS Site Contact Name(s)

Person ID: 9270865.00
First Name: Mary
Last Name: Aycock
Phone No.: 4159723289
Email:

CERCLIS Assess History

OU ID: 00
Act Code ID: 001
RAT Code: HR
RAT Short Name: HAZRANK
RAT Name: HAZARD RANKING SYSTEM PACKAGE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: P
SPA Code: 13
RALT Short Name: EPA Fund
Act Start Date:
Act Complete Date: 6/1/1987 00:00:00
AGT Order No.: 190
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
RAT Def: A numeric estimate of the relative severity of a hazardous substance release or potential release based on: (1) the relative potential of substances to cause hazardous situations; (2) the likelihood and rate at which the substances may affect human and environmental receptors; and (3) the severity and magnitude of potential effects. The score is computed using the hazard ranking system (HRS).
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID: 05
Act Code ID: 020
RAT Code: LV
RAT Short Name: FF RV
RAT Name: FEDERAL FACILITY REMOVAL
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: L
SPA Code: 12
RALT Short Name: Fed Fac
Act Start Date: 11/14/1998 00:00:00
Act Complete Date: 2/26/1999 00:00:00
AGT Order No.: 80
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	02	***RALT Short Name:***	Fed Fac
Act Code ID:	003	***Act Start Date:***	3/27/2002 00:00:00
RAT Code:	LV	***Act Complete Date:***	
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	012	***Act Start Date:***	9/30/2000 00:00:00
RAT Code:	LV	***Act Complete Date:***	
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	013	***Act Start Date:***	3/17/1995 00:00:00
RAT Code:	LV	***Act Complete Date:***	8/27/2003 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	
RAT Code:	JF	***Act Complete Date:***	8/26/1992 00:00:00

RAT Short Name:	ECO RISK	**AGT Order No.:**	542
RAT Name:	ECOLOGICAL RISK ASSESSMENT	**SH OU:**	
RAT Hist. Only Flag:	T	**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	09		

RAT Def: Assessment of the baseline risks posed by the site to ecological receptors.
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	Fed Fac
Act Code ID:	001	**Act Start Date:**	
RAT Code:	PA	**Act Complete Date:**	6/1/1987 00:00:00
RAT Short Name:	PA	**AGT Order No.:**	130
RAT Name:	PRELIMINARY ASSESSMENT	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	02	**RALT Short Name:**	Fed Fac
Act Code ID:	001	**Act Start Date:**	3/30/2000 00:00:00
RAT Code:	TA	**Act Complete Date:**	3/30/2001 00:00:00
RAT Short Name:	TECH A	**AGT Order No.:**	500
RAT Name:	TECHNICAL ASSISTANCE	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	09		

RAT Def: Participation in the conduct of fund-financed Remedial Investigation/Feasibility Study (RI/FS).
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	**RALT Short Name:**	Fed Fac
Act Code ID:	011	**Act Start Date:**	3/17/1995 00:00:00
RAT Code:	LV	**Act Complete Date:**	8/27/2003 00:00:00
RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	017	***Act Start Date:***	3/12/1996 00:00:00
RAT Code:	LV	***Act Complete Date:***	4/29/2005 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	002	***Act Start Date:***	
RAT Code:	RO	***Act Complete Date:***	10/5/1998 00:00:00
RAT Short Name:	ROD	***AGT Order No.:***	610
RAT Name:	RECORD OF DECISION	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		

RAT Def: The final Record of Decision (ROD) is signed by the appropriate agency indicating that the agency has chosen the remedy for site remediation. ROD signature is signified by the complete date.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	
RAT Code:	NP	***Act Complete Date:***	7/14/1989 00:00:00
RAT Short Name:	PROPOSED	***AGT Order No.:***	200
RAT Name:	PROPOSAL TO NATIONAL PRIORITIES LIST	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: Site proposed for inclusion on the National Priority List based on the Hazard Ranking System (HRS) score for the site.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	02	***RALT Short Name:***	Fed Fac
Act Code ID:	002	***Act Start Date:***	9/21/1990 00:00:00
RAT Code:	LW	***Act Complete Date:***	3/29/2005 00:00:00
RAT Short Name:	FF RI/FS	***AGT Order No.:***	460
RAT Name:	FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	

RAT Level: 1
RAT DEF OU:
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for Remedial Investigation/Feasibility Study (RI/FS), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 01
Act Code ID: 001
RAT Code: LW
RAT Short Name: FF RI/FS
RAT Name: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU:
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for Remedial Investigation/Feasibility Study (RI/FS), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:
RALT Short Name: Fed Fac
Act Start Date: 9/21/1990 00:00:00
Act Complete Date: 3/7/1994 00:00:00
AGT Order No.: 460
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 03
Act Code ID: 003
RAT Code: LW
RAT Short Name: FF RI/FS
RAT Name: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU:
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for Remedial Investigation/Feasibility Study (RI/FS), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:
RALT Short Name: Fed Fac
Act Start Date: 8/27/1991 00:00:00
Act Complete Date: 10/5/1998 00:00:00
AGT Order No.: 460
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 03
Act Code ID: 002
RAT Code: OM
RAT Short Name: OM
RAT Name: OPERATIONS AND MAINTENANCE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU:
RFBS Code: P
SPA Code: 09
RAT Def: Site requirements associated with a remedy that must be performed after the completion of a remedial action.
Site Desc:
Site Alias:
RALT Short Name: Fed Fac
Act Start Date: 1/3/2000 00:00:00
Act Complete Date:
AGT Order No.: 990
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID:	05	***RALT Short Name:***	Fed Fac
Act Code ID:	019	***Act Start Date:***	8/7/2000 00:00:00
RAT Code:	LV	***Act Complete Date:***	4/1/2002 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	05	***RALT Short Name:***	Fed Fac
Act Code ID:	002	***Act Start Date:***	8/31/2010 00:00:00
RAT Code:	FS	***Act Complete Date:***	
RAT Short Name:	FS	***AGT Order No.:***	550
RAT Name:	FEASIBILITY STUDY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: A study of a hazardous waste site intended to (1) evaluate alternative remedial actions from technical, environmental, and cost-effectiveness perspectives; (2) recommend the cost-effective remedial action; and (3) prepare a conceptual design, a cost estimate for budgetary purposes, and a preliminary construction schedule.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	2/18/2010 00:00:00
RAT Code:	FS	***Act Complete Date:***	
RAT Short Name:	FS	***AGT Order No.:***	550
RAT Name:	FEASIBILITY STUDY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: A study of a hazardous waste site intended to (1) evaluate alternative remedial actions from technical, environmental, and cost-effectiveness perspectives; (2) recommend the cost-effective remedial action; and (3) prepare a conceptual design, a cost estimate for budgetary purposes, and a preliminary construction schedule.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	
RAT Code:	RO	***Act Complete Date:***	3/7/1994 00:00:00
RAT Short Name:	ROD	***AGT Order No.:***	610
RAT Name:	RECORD OF DECISION	***SH OU:***	

RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU:
RFBS Code:
SPA Code: 13
RAT Def: The final Record of Decision (ROD) is signed by the appropriate agency indicating that the agency has chosen the remedy for site remediation. ROD signature is signified by the complete date.
Site Desc:
Site Alias:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 02
Act Code ID: 005
RAT Code: LV
RAT Short Name: FF RV
RAT Name: FEDERAL FACILITY REMOVAL
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:
RALT Short Name: Fed Fac
Act Start Date: 2/10/2002 00:00:00
Act Complete Date: 4/12/2004 00:00:00
AGT Order No.: 80
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 03
Act Code ID: 008
RAT Code: LV
RAT Short Name: FF RV
RAT Name: FEDERAL FACILITY REMOVAL
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
Site Alias:
RALT Short Name: Fed Fac
Act Start Date: 4/7/1996 00:00:00
Act Complete Date:
AGT Order No.: 80
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 03
Act Code ID: 010
RAT Code: LV
RAT Short Name: FF RV
RAT Name: FEDERAL FACILITY REMOVAL
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: L
SPA Code: 12
RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.
Site Desc:
RALT Short Name: Fed Fac
Act Start Date: 3/29/1996 00:00:00
Act Complete Date:
AGT Order No.: 80
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	
RAT Code:	DS	***Act Complete Date:***	8/1/1980 00:00:00
RAT Short Name:	DISCVRY	***AGT Order No.:***	10
RAT Name:	DISCOVERY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	05	***RALT Short Name:***	Fed Fac
Act Code ID:	016	***Act Start Date:***	9/20/2002 00:00:00
RAT Code:	LV	***Act Complete Date:***	9/26/2003 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	02	***RALT Short Name:***	Fed Fac
Act Code ID:	004	***Act Start Date:***	6/17/2002 00:00:00
RAT Code:	LV	***Act Complete Date:***	
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	05	***RALT Short Name:***	Fed Fac
Act Code ID:	021	***Act Start Date:***	6/16/2006 00:00:00
RAT Code:	LV	***Act Complete Date:***	
RAT Short Name:	FF RV	***AGT Order No.:***	80

RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	05	**RALT Short Name:**	Fed Fac
Act Code ID:	022	**Act Start Date:**	6/16/2006 00:00:00
RAT Code:	LV	**Act Complete Date:**	
RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	Fed Fac
Act Code ID:	001	**Act Start Date:**	
RAT Code:	SI	**Act Complete Date:**	6/1/1987 00:00:00
RAT Short Name:	SI	**AGT Order No.:**	160
RAT Name:	SITE INSPECTION	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	**RALT Short Name:**	Fed Fac
Act Code ID:	015	**Act Start Date:**	7/7/2002 00:00:00
RAT Code:	LV	**Act Complete Date:**	1/13/2003 00:00:00
RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	**RALT Short Name:**	Fed Fac
Act Code ID:	002	**Act Start Date:**	5/22/1995 00:00:00
RAT Code:	LX	**Act Complete Date:**	
RAT Short Name:	FF RD	**AGT Order No.:**	810
RAT Name:	FEDERAL FACILITY REMEDIAL DESIGN	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	09		

RAT Def: Provides for oversight of Federal facility response action for Remedial Design (RD), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	
Act Code ID:		**Act Start Date:**	
RAT Code:		**Act Complete Date:**	
RAT Short Name:		**AGT Order No.:**	0
RAT Name:		**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:		**SH Seq:**	
RAT Level:		**SH Start Date:**	
RAT DEF OU:		**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:			
RAT Def:			

Site Desc: The 5,347 acre George Air Force Base (GAFB) site is located in the western Mojave Desert in the areas of Victorville, California adjacent to the City of Adelanto, California. Victorville is located on Interstate 15, approximately 35 miles north of San Be

Site Alias: GEORGE AIR FORCE BASE,AIR BASE RD- NR ST RTE 395,VICTORVILLE,CA,92392;GEORGE USAF BASE, 831 CSG/DE,GEORGE AFB,CA,96630;

CERCLIS Assess History

OU ID:	00	**RALT Short Name:**	EPA Fund
Act Code ID:	001	**Act Start Date:**	
RAT Code:	NF	**Act Complete Date:**	2/21/1990 00:00:00
RAT Short Name:	NPL FINL	**AGT Order No.:**	202
RAT Name:	FINAL LISTING ON NATIONAL PRIORITIES LIST	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	P	**SH Lead:**	
SPA Code:	13		

RAT Def: Site moved from proposed list to final National Priority List.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	**RALT Short Name:**	Fed Fac
Act Code ID:	001	**Act Start Date:**	
RAT Code:	ED	**Act Complete Date:**	8/26/1992 00:00:00

RAT Short Name:	R/H ASMT	***AGT Order No.:***	540
RAT Name:	RISK/HEALTH ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	09		

RAT Def: Assessment of the baseline risks posed by the site to human health.

Site Desc:

Site Alias:

CERCLIS Assess History

OU ID:	02	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	
RAT Code:	EE	***Act Complete Date:***	12/15/1991 00:00:00
RAT Short Name:	EE/CA	***AGT Order No.:***	50
RAT Name:	ENGINEERING EVALUATION/COST ANALYSIS	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: Study to identify the objectives of a removal action and to analyze the cost effectiveness and implementability of the various alternatives that may be used to satisfy these objectives.

Site Desc:

Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	006	***Act Start Date:***	3/17/1995 00:00:00
RAT Code:	LV	***Act Complete Date:***	8/20/2003 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:

Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	9/21/1990 00:00:00
RAT Code:	LV	***Act Complete Date:***	2/1/1992 00:00:00
RAT Short Name:	FF RV	***AGT Order No.:***	80
RAT Name:	FEDERAL FACILITY REMOVAL	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	3/7/1994 00:00:00
RAT Code:	LX	***Act Complete Date:***	4/30/1996 00:00:00
RAT Short Name:	FF RD	***AGT Order No.:***	810
RAT Name:	FEDERAL FACILITY REMEDIAL DESIGN	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	09		

RAT Def: Provides for oversight of Federal facility response action for Remedial Design (RD), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	***RALT Short Name:***	Fed Fac
Act Code ID:	002	***Act Start Date:***	4/29/1996 00:00:00
RAT Code:	LY	***Act Complete Date:***	
RAT Short Name:	FF RA	***AGT Order No.:***	860
RAT Name:	FEDERAL FACILITY REMEDIAL ACTION	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	09		

RAT Def: Provides for oversight of Federal facility response action for Remedial Action (RA), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	01	***RALT Short Name:***	Fed Fac
Act Code ID:	001	***Act Start Date:***	4/30/1996 00:00:00
RAT Code:	LY	***Act Complete Date:***	2/21/1997 00:00:00
RAT Short Name:	FF RA	***AGT Order No.:***	860
RAT Name:	FEDERAL FACILITY REMEDIAL ACTION	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:	L	***SH Lead:***	
SPA Code:	09		

RAT Def: Provides for oversight of Federal facility response action for Remedial Action (RA), including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	02	***RALT Short Name:***	Fed Fac
Act Code ID:	002	***Act Start Date:***	9/21/1990 00:00:00
RAT Code:	LV	***Act Complete Date:***	5/1/1992 00:00:00

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	**RALT Short Name:**	Fed Fac
Act Code ID:	007	**Act Start Date:**	3/17/1995 00:00:00
RAT Code:	LV	**Act Complete Date:**	8/20/2003 00:00:00
RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	03	**RALT Short Name:**	Fed Fac
Act Code ID:	009	**Act Start Date:**	1/7/1991 00:00:00
RAT Code:	LV	**Act Complete Date:**	2/28/1992 00:00:00
RAT Short Name:	FF RV	**AGT Order No.:**	80
RAT Name:	FEDERAL FACILITY REMOVAL	**SH OU:**	
RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:	L	**SH Lead:**	
SPA Code:	12		

RAT Def: Provides for oversight of Federal facility response action for removals including all activities for monitoring and supervising the performance of Federal facilities to determine whether such performance is consistent with the requirements of SARA and IAG or MOA.

Site Desc:
Site Alias:

7	2 of5	WNW	0.01 / 35.78	2,897.01 / -10	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	FED ENG

EPA ID:	CA2570024453
Region Code:	09
County:	SAN BERNARDINO
Latitude:	+34.595000
Longitude:	-117.383300

Control Details

Actual Completion Date: 9/2/2021 5:00:00 AM

Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - RAO(s) Change
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 11/15/2003 5:00:00 AM
Fiscal Year: 2004
NPL Status: Currently on the Final NPL
Action Type: Explanation of Significant Differences
Remedy Component: No Further Action
Media: Debris
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 4

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - ICs/Five-Year Reviews Removal
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 3/7/1994 5:00:00 AM
Fiscal Year: 1994
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Air Stripping (P&T, exsitu)
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 01
Sequence ID: 1

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Soil Vapor Extraction (insitu)
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Monitoring
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 5/28/2015 5:00:00 AM
Fiscal Year: 2015
NPL Status: Currently on the Final NPL
Action Type: Record of Decision

Remedy Component: No Further Action
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 05
Sequence ID: 5

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - ARAR(s) Change
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - ICs/Five-Year Reviews Removal
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Cap (engineered cap)
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Monitoring
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: Disposal (offsite)
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: Disposal (offsite)
Media: Soil
Federal Facility: Yes

Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - ARAR(s) Change
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - Cleanup/Performance Standard Change
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: Excavation
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Monitored Natural Attenuation
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: No Further Action
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: No Further Action
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 7/2/2002 4:00:00 AM
Fiscal Year: 2002
NPL Status: Currently on the Final NPL
Action Type: Explanation of Significant Differences
Remedy Component: Soil Vapor Extraction (insitu)
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 3/7/1994 5:00:00 AM
Fiscal Year: 1994
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Discharge (surface water/NPDES discharge)
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 01
Sequence ID: 1

Actual Completion Date: 3/7/1994 5:00:00 AM
Fiscal Year: 1994
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Monitoring
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 01
Sequence ID: 1

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: No Further Action
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 11/15/2003 5:00:00 AM
Fiscal Year: 2004
NPL Status: Currently on the Final NPL
Action Type: Explanation of Significant Differences
Remedy Component: No Further Action
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 4

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - RAO(s) Change
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: Excavation
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Operations & Maintenance (O&M)
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 9/2/2021 5:00:00 AM
Fiscal Year: 2021
NPL Status: Currently on the Final NPL
Action Type: ROD Amendment
Remedy Component: ESD/Amd - Cleanup/Performance Standard Change
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 3

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Bioventing (insitu)
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Drainage/Erosion Control (other, not otherwise specified)
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Operations & Maintenance (O&M)
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

7	3 of5	WNW	0.01 / 35.78	2,897.01 / -10	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	FED INST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

EPA ID: CA2570024453
Region Code: 09
County: SAN BERNARDINO
Latitude: +34.595000
Longitude: -117.383300

Control Details

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Institutional Controls
Media: Soil
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 3/7/1994 5:00:00 AM
Fiscal Year: 1994
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Institutional Controls
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 01
Sequence ID: 1

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Institutional Controls
Media: Groundwater
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

Actual Completion Date: 10/5/1998 4:00:00 AM
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Action Type: Record of Decision
Remedy Component: Institutional Controls
Media: Solid Waste
Federal Facility: Yes
Superfund Alt. Agreement: No
Operable Unit No: 03
Sequence ID: 2

7	4 of5	WNW	0.01 / 35.78	2,897.01 / -10	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395 VICTORVILLE CA 92392	PFAS NPL

Identifier: CA2570024453
NPL Status: Final
NPL Site: Yes
Data System: SEMS
Superfund Alt Appr: No
Site Type: Federal
EPA Region: 09
County: SAN BERNARDINO
Latitude: 34.59500000000001
Longitude: -117.3833
Link: https://www.epa.gov/superfund/georgeafb

7	5 of5	WNW	0.01 / 35.78	2,897.01 / -10	GEORGE AIR FORCE BASE AIR BASE RD- NR ST RTE 395	SUPERFUND ROD

EPA ID: CA2570024453
Site ID: 0902737
NPL Status: Final
Non NPL Status:
Region: 09
EPA ID (SFDB): CA2570024453
Site Name (SFDB): GEORGE AIR FORCE BASE
State (SFDB): CA
Region (SFDB): 09
Data Source(s): SEMS Superfund Public User Database (as of 30 Jan 2026); Searchable Superfund Decision Documents Database (SFDB) (as of 26 Jan 2026)

Superfund Decision Documents Details (SFDB)

Doc ID: 1107639
Date: 07/01/2002
Pub No:
Description:
PDF Link: https://semspub.epa.gov/src/document/09/1107639
Title: Final explanation of significant differences, site OT-51 remediation, OU 3, w/attchs & TL to J Bingham fr P Craig, 7/8/02

Doc ID: 48592
Date: 10/05/1998
Pub No:
Description:
PDF Link: https://semspub.epa.gov/src/document/09/48592
Title: Final record of decision, OU 3, w/appendices A-F

Doc ID: 2255292
Date: 03/01/1994
Pub No:
Description:
PDF Link: https://semspub.epa.gov/src/document/09/2255292
Title: Final record of decision (ROD) for OU 1, w/app B & w/o app A

Doc ID: 2253061
Date: 09/01/1993
Pub No:
Description:
PDF Link: https://semspub.epa.gov/src/document/09/2253061
Title: Supplemental record of decision (ROD) for disposal & reuse of site, w/TL fr S Widnall, 9/21/93

Completed RODs, ROD Amendments and ESDs (FOIA 2) Details

Seq ID: 3
Actual Comp Date: 9/2/2021 5:00:00 AM
Action Name: Record of Decision (ROD) Amendment
Operable Unit Name: OU03

Seq ID: 5
Actual Comp Date: 5/28/2015 5:00:00 AM
Action Name: Record of Decision (ROD)
Operable Unit Name: OU05

Seq ID: 4
Actual Comp Date: 11/15/2003 5:00:00 AM
Action Name: Explanation Of Significant Differences (ESD)
Operable Unit Name: OU03

Seq ID: 3
Actual Comp Date: 7/2/2002 4:00:00 AM
Action Name: Explanation Of Significant Differences (ESD)
Operable Unit Name: OU03

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq ID: 2
Actual Comp Date: 10/5/1998 4:00:00 AM
Action Name: Record of Decision (ROD)
Operable Unit Name: OU03

Seq ID: 1
Actual Comp Date: 3/7/1994 5:00:00 AM
Action Name: Record of Decision (ROD)
Operable Unit Name: OVERALL SITE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	1 of13	W	0.01 / 63.36	2,903.26 / -4	Verizon California Inc. 17640 Adelanto Rd. Adelanto CA	CHMIRS

Control No: 12-3863
Year: 2012
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/63cfd5ee73e3ac7888257a30006e2884?OpenDocument
Notified Date:
Notified Date Time:

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained: Yes
1 Substance: Antifreeze
1 Measure: Gal(s)
1 Other:
1 Quantity: 20-30
1 Type: CHEMICAL
1 Pipeline: No
1 Vessel >= 300 Tons: No
2 Substance:
2 Quantity:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Vessel >= 300 Tons: No
3 Substance:
3 Quantity:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Incident Date: 4/12/2007
Incident Time: 1200
Spill Site: Merchant/Business
Injuries?: No
No of Injuries:
Fatals?: No
No of Fatals:
Evacs?: No
No of Evacs:
Cleanup: Contractor
Site:
Cause: Mechanical
Cause Other:
Dog No:
Water: No
Water Way:
City: Adelanto
County: San Bernardino County
ZIP:
Admin Agency: San Bernardino County Health Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: 17640 Adelanto Rd.
Description: HISTORICAL SPILL Caller states: A radiator hose to a generator came loose causing the release. It was contained in secondary containment. There was no release to the environment.

Spill Report View

Water:
Document Title: SPILL Report
Spill Site: Merchant/Business
Type: CHEMICAL
Creation Date: 07/03/2012 01:03 PM

Hazardous Materials Spill Report

Date : 07/03/2012
Time: 1303
Incident Date: 04/12/2007
Incident Time: 1200
Control Cal OES: 12-3863
Control NRC:
Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Water Involved:	No	**Prs Ext:**	
Drink Wtr Impact:	No	**Prs Pag Cell:**	
Detail for Other:		**Incident Desc:**	
UPRR Rim No:		**Notification Info:**	
DOG Unit:		**Notification List:**	
RWQCB Unit:	6B		
Contained:	Yes		
Waterway:			
Received By:			
Cleanup By:	Contractor		
Incident Location:	17640 Adelanto Rd.		
Additional County:			
1 Substance:	Antifreeze		
1 Qty:	=		
1 Amount :	20-30		
1 Measure:	Gal(s)		
1 Type:	CHEMICAL		
1 Other:			
1 Pipeline:	No		
1 Ves >= 300 Tons:	No		
2 Substance:			
2 Qty:	=		
2 Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:	No		
2 Ves >= 300 Tns:	No		
3 Substance:			
3 Qty:	=		
3 Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:	No		
3 Ves >= 300 Tons:	No		
Injuries:	No		
Fatality:	No		
Evacuation:	No		
Known Impact:	None		
Agency:	Verizon California Inc.		
PRS Agency:			
Sec Agency:			
Admin Agency:	San Bernardino County Health Department		
Admin Agency 2:			
On Scene:			
Other on Scene:			
Other Notified:	Fire Department		
Header Unknown:	MOJAVE DESERT AQMD		
Site:	Merchant/Business		
Reported Cause:	Mechanical		
R R Crssing < 50 Ft:			
Description:	HISTORICAL SPILL Caller states: A radiator hose to a generator came loose causing the release. It was contained in secondary containment. There was no release to the environment.		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	2 of13	W	0.01 / 63.36	2,903.26 / -4	VERIZON-ADELANTO C.O. 17640 ADELANTO ROAD ADELANTO CA 92301	EMISSIONS

Source:

2001 Criteria Data

Facility ID:	7601321	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	0
CO:	36	**ROGT:**	0
Air Basin:	MD	**COT:**	0

District:	MOJ	***NOXT:***	0
COID:	SBD	***SOXT:***	0
DISN:	MOJAVE DESERT AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

2001 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2002 Criteria Data

Facility ID:	7601321	***CERR Code:***	
Facility SIC Code:	4813	***TOGT:***	.0002946
CO:	36	***ROGT:***	.00024649182
Air Basin:	MD	***COT:***	.0006509
District:	MOJ	***NOXT:***	.0030215
COID:	SBD	***SOXT:***	.0000355
DISN:	MOJAVE DESERT AQMD	***PMT:***	.0002124
CHAPIS:		***PM10T:***	.0002073024

2002 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2004 Criteria Data

Facility ID:	7601321	***CERR Code:***	
Facility SIC Code:	4813	***TOGT:***	.0002946
CO:	36	***ROGT:***	.00024649182
Air Basin:	MD	***COT:***	.0006509
District:	MOJ	***NOXT:***	.0030215
COID:	SBD	***SOXT:***	.0000355
DISN:	MOJAVE DESERT AQMD	***PMT:***	.0002124
CHAPIS:		***PM10T:***	.0002073024

2004 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	7601321	***CERR Code:***	
Facility SIC Code:	4813	***TOGT:***	.0002946
CO:	36	***ROGT:***	.00024649182
Air Basin:	MD	***COT:***	.0006509
District:	MOJ	***NOXT:***	.0030215
COID:	SBD	***SOXT:***	.0000355
DISN:	MOJAVE DESERT AQMD	***PMT:***	.0002124
CHAPIS:		***PM10T:***	.0002073024

2005 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2006 Criteria Data

Facility ID:	7601321	***CERR Code:***	
Facility SIC Code:	4813	***TOGT:***	.0002946
CO:	36	***ROGT:***	.00024649182
Air Basin:	MD	***COT:***	.0006509
District:	MOJ	***NOXT:***	.0030215
COID:	SBD	***SOXT:***	.0000355
DISN:	MOJAVE DESERT AQMD	***PMT:***	.0002124
CHAPIS:		***PM10T:***	.0002073024

2006 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2007 Criteria Data

Facility ID:	7601321	***CERR Code:***	
Facility SIC Code:	4813	***TOGT:***	.0002946
CO:	36	***ROGT:***	.00024649182
Air Basin:	MD	***COT:***	.0006509
District:	MOJ	***NOXT:***	.0030215
COID:	SBD	***SOXT:***	.0000355
DISN:	MOJAVE DESERT AQMD	***PMT:***	.0002124
CHAPIS:		***PM10T:***	.0002073024

2007 Toxic Data

Facility ID:	7601321	***COID:***	SBD
Facility SIC Code:	4813	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CERR Code:

2008 Criteria Data

Facility ID: 7601321
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: .0002946
ROGT: .00024649182
COT: .0006509
NOXT: .0030215
SOXT: .0000355
PMT: .0002124
PM10T: .0002073024

2008 Toxic Data

Facility ID: 7601321
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2009 Criteria Data

Facility ID: 7601321
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: .0002946
ROGT: .00024649182
COT: .0006509
NOXT: .0030215
SOXT: .0000355
PMT: .0002124
PM10T: .0002073024

2009 Toxic Data

Facility ID: 7601321
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	3 of13	W	0.01 / 63.36	2,903.26 / -4	VERIZON ADELANTO1 17640 ADELANTO RD. ADELANTO CA 92301	EMISSIONS

Source:

2003 Criteria Data

Facility ID: 7601321
CERR Code:

Facility SIC Code:	4813	**TOGT:**	.0009864
CO:	36	**ROGT:**	0
Air Basin:	MD	**COT:**	.0093184
District:	MOJ	**NOXT:**	.0324488
COID:	SBD	**SOXT:**	.0000284
DISN:	MOJAVE DESERT AQMD	**PMT:**	.000628
CHAPIS:		**PM10T:**	0

2003 Toxic Data

Facility ID:	7601321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2010 Toxic Data

Facility ID:	7601321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2011 Criteria Data

Facility ID:	7601321	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	.0031227
CO:	36	**ROGT:**	.00261276309
Air Basin:	MD	**COT:**	.0006509
District:	MOJ	**NOXT:**	.0320279
COID:	SBD	**SOXT:**	.00005254
DISN:	MOJAVE DESERT AQMD	**PMT:**	.0022514
CHAPIS:		**PM10T:**	.0021973664

2011 Toxic Data

Facility ID:	7601321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2012 Criteria Data

Facility ID:	7601321	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	.0031227
CO:	36	**ROGT:**	.00261276309
Air Basin:	MD	**COT:**	.0006509
District:	MOJ	**NOXT:**	.0320279
COID:	SBD	**SOXT:**	.00005254

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DISN:	MOJAVE DESERT AQMD	**PMT:**	.0022514
CHAPIS:		**PM10T:**	.0021973664

2012 Toxic Data

Facility ID:	7601321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2013 Criteria Data

Facility ID:	7601321	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	.0031227
CO:	36	**ROGT:**	.00261276309
Air Basin:	MD	**COT:**	.0006509
District:	MOJ	**NOXT:**	.0320279
COID:	SBD	**SOXT:**	.00005254
DISN:	MOJAVE DESERT AQMD	**PMT:**	.0022514
CHAPIS:		**PM10T:**	.0021973664

2013 Toxic Data

Facility ID:	7601321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	***4 of13***	***W***	***0.01 / 63.36***	***2,903.26 / -4***	***FRONTIER - ADELANTO # 1 17640 ADELANTO ROAD ADELANTO CA 92301***	***EMISSIONS***

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2017 Toxic Data

Facility ID:	227801321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	7.94		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Toxic Data

Facility ID:	1321	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	

District: MOJ
TS: 7.94
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2019 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 1321
District: MOJ
Facility SIC Code: 4813
CO ID: SBD
DISN: MOJAVE DESERT AQMD
PM10T: .01191696
TOGT: .033913568582811610700056915196357427433 1
PMT: .011988893360160965794768611670020120724 3
CHAPIS:
CERR Code:
ROGT: .02979307
COT: .2532394
NOXT: .2055709
SOXT: .000142923

2019 Toxic Data

CO: 36
Air Basin: MD
Faccility ID: 1321
District: MOJ
Facility SIC Code: 4813
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TS: 4.57
Health Risk Asmt:

2020 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 1321
District: MOJ
Facility SIC Code: 4813
CO ID: SBD
DISN: MOJAVE DESERT AQMD
TOGT: .033913568582811610700056915196357427433 1
PMT: .011988893360160965794768611670020120724 3
PM10T: .01191696
CHAPIS:
CERR Code:
ROGT: .02979307
COT: .2532394
NOXT: .2055709
SOXT: .000142923

2020 Toxic Data

CO: 36
Air Basin: MD
Facility ID: 1321
District: MOJ
Facility SIC Code: 4813
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
CHERR Code:
TS: 4.57
Health Risk Asmt:

2021 Toxic Data

Co: 36
Air Basin: MD
Facility ID: 1321
District: MOJ
Facility SIC Code: 4813
COID: SBD
Non-Cancer Chronic Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
Cerr Code:
TS: 4.57
Health Risk Asmt:

Non-Cancer Acute Haz Ind:

2021 Criteria Data

Co:	36	***CHAPIS:***	
Air Basin:	MD	***Cerr Code:***	
Facility ID:	1321	***ROGT:***	.02979307
District:	MOJ	***COT:***	.2532394
Facility SIC Code:	4813	***NOXT:***	.2055709
CO ID:	SBD	***SOXT:***	.000142923
DISN:	MOJAVE DESERT AQMD		
TOGT:	.033913568582811610700056915196357427433 1		
PMT:	.011988893360160965794768611670020120724 3		
PM10T:	.01191696		

2023 Pollutant Data

Facility ID:	1321	***CO:***	36
Facility SIC Code:	4813	***CO ID:***	SBD
CERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
ROGT:	.006837754	***NOXT:***	.04718021
COT:	.058120522	***SOXT:***	.000032802
DISN:	MOJAVE DESERT AQMD		
TOGT:	.007775476461223561519217648396634068683193		
PMT:	.002751549295774647887323943661971830985916		
PM10T:	.00273504		
Source:	2023 Pollutant Data		

2022 Criteria Data

Facility ID:	1321	***District:***	MOJ
Facility SIC Code:	4813	***Air Basin:***	MD
Cerr Code:		***Co:***	36
CHAPIS:		***CO ID:***	SBD
ROGT:	.006837754	***NOXT:***	.04718021
COT:	.058120522	***SOXT:***	.00003279
DISN:	MOJAVE DESERT AQMD		
TOGT:	.007783442231075697211155378486055776892 43		
PMT:	.002751549295774647887323943661971830985916		
PM10T:	.00273504		
Source:	2022 Criteria Data		

2022 Toxic Data

Facility ID:	1321	***CO:***	36
Facility SIC Code:	4813	***Air Basin:***	MD
CHERR Code:		***District:***	MOJ
CHAPIS:		***COID:***	SBD
Health Risk Asmt:		***TS:***	1.47
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2022 Toxic Data		

2023 Toxic Data

Facility ID:	1321	***CO:***	36
Facility SIC Code:	4813	***COID:***	SBD
CHERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
TS:	1.47		
Health Risk Asmt:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data

---

8 | **5 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **VERIZON ADELANTO1**
17640 ADELANTO ROAD
ADELANTO CA 92301-1744 | **FINDS/FRS**

Registry ID: 110021317724
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 19-MAY-05
Update Date: 01-JUN-17
Interest Types: STATE MASTER
SIC Codes: 4813
SIC Code Descriptions: TELEPHONE COMMUNICATIONS, EXCEPT RADIOTELEPHONE
NAICS Codes: 517110
NAICS Code Descriptions: WIRED TELECOMMUNICATIONS CARRIERS.
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091164101
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude: 34.570938
Longitude: -117.40068
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110021317724
Program Acronyms:

CA-ENVIROVIEW:166358

---

8 | **6 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **FRONTIER - ADELANTO # 1**
17640 ADELANTO ROAD
ADELANTO CA 92301 | **FINDS/FRS**

Registry ID: 110071764845
FIPS Code: 06071
HUC Code:
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 15-JUL-24
Update Date: 27-AUG-24
Interest Types: AIR EMISSIONS CLASSIFICATION UNKNOWN
SIC Codes: 4813
SIC Code Descriptions: TELEPHONE COMMUNICATIONS, EXCEPT RADIOTELEPHONE
NAICS Codes: 517112, 517122
NAICS Code Descriptions:
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071764845
Program Acronyms:

CARB-TCH:36MDMOJ1321, EIS:21000011

8	7 of13	W	0.01 / 63.36	2,903.26 / -4	VERIZON ADELANTO1 17640 ADELANTO RD. ADELANTO CA 92301	FINDS/FRS

Registry ID: 110071765790
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 15-JUL-24
Update Date: 27-AUG-24
Interest Types: HAZARDOUS AIR POLLUTANT MAJOR
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 517111
NAICS Code Descriptions:
Conveyor: EIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091164005
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude: 34.57773
Longitude: -117.40076
Reference Point: POINT WHERE SUBSTANCE IS RELEASED
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 100
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071765790
Program Acronyms:

CARB-TCH:36MDMOJ7601321, EIS:1475511

8	8 of13	W	0.01 / 63.36	2,903.26 / -4	VERIZON CALIFORNIA INC 17640 ADELANTO RD ADELANTO CA 923011744	HAZ GEN

EPA ID: CAC002605162
Facility County: 36
Address 2:
County: San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Code, its description, and annual amounts in its Hazardous Waste Tracking System:
https://hwts.dtsc.ca.gov/search

Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC002605162

---

8 | **9 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **VERIZON CALIFORNIA INC**
17640 ADELANTO RD
ADELANTO CA 923011744 | **HAZ GEN**

EPA ID: CAC002615452
Address 2:
Facility County: 36
County: San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System:
https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC002615452

---

8 | **10 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **VERIZON CALIFORNIA INC.**
17640 ADELANTO RD
ADELANTO CA 923011744 | **HAZ GEN**

EPA ID: CAC002769752
Address 2:
Facility County: 36
County: San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System:
https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC002769752

---

8 | **11 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **CONTEL ADELANTO CO**
17640 ADELANTO RD
ADELANTO CA 923010000 | **HAZNET**

EPA ID: CAD981437064
NAICS Code:
SIC Code:
Create Date: 4/10/1987
Fac Act Ind: No
Inact Date: 1/1/1995
County: 36
County Name: San Bernardino
County:
Mail Name:
Mailing Addr 1: 16071 MOJAVE DR
Mailing Addr 2:
Mailing City: VICTORVILLE
Mailing State: CA
Mailing Zip: 923920000
Region Code: 4
Owner Name: --
Owner Addr 1: --
Owner Addr 2:
Owner City: --
Owner State: 99
Owner Zip: --
Owner Phone: 0000000000
Owner Fax:

---

8 | **12 of13** | **W** | **0.01 / 63.36** | **2,903.26 / -4** | **17640 ADELANTO RD**
ADELANTO CA 923010000 | **HIST MANIFEST**

Gen EPA ID: CAD981437064
Create Date: 04/10/1987 0:00
Inact Date: 01/01/1995 0:00
Facility Mail Street: 16071 MOJAVE DR
Facility Mail City: VICTORVILLE
Facility Mail State: CA
Facility Mail Zip: 923920000
Contact Phone(s): --
File Year(s): 1987
Contact Name(s): CANCEL PER SURVEY 1-27-95 LC

Tanner Information

State Waste Code: 111
Year: 1987
Tons: 12.5
Method Code:
State Waste Code Desc:
Generator County: San Bernardino
Tsd Epa ID:
Tsd County:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Method Description:						
8	13 of13	W	0.01 / 63.36	2,903.26 / -4	FRONTIER CALIFORNIA INC.: ADELANTO CO 17640 Adelanto Rd Adelanto CA 92301	SANBERN CUPA

Facility ID: FA0007064
Owner Info: Frontier California Inc.
Mailing Care of: MASOON.CHOUDHURY@FTR.COM
Mailing Address 2:
Mailing City: POMONA
Mailing State: CA
Mailing Zip: 91766

Detail(s)

Permit ID: PT0024081
Status: INACTIVE
Program Element Code: 4270
Permit Desc: EPCRA FACILITY
To: 5/31/2013
Mailing Address 1: 280 S. LOCUST STREET

Permit ID: PT0006828
Status: ACTIVE
Program Element Code: 4241
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
To: 5/31/2025
Mailing Address 1: 280 S. LOCUST STREET

Permit ID: PT0010379
Status: ACTIVE
Program Element Code: 4104
Permit Desc: REGULAR UST ANNUAL INSPECTION (PER TANK)
To: 5/31/2025
Mailing Address 1: 280 S. LOCUST STREET

9	1 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE WRAPPERS & COATERS, INC. 12766 VIOLET ROAD ADELANTO CA 92301	AFS

Afs ID: 06071M1067
Plant ID: 1014646
Epa Region: 09
Plant County: San Bernardino
State No: 06
Primary Sic Code: 3479
Secondary Sic Code:
Naics Code: 339914
Fed Reportable: Yes
Current Hpv:
Loc Contrl Region: 17
Afs Gov Fac Code: 0
Operating Status: O
Epa Class Code: A
Epa Complian Stat: C
State Comp Status: C
Afs Gov Facility Des: PRIVATELY OWNED/OPERATED
Operating Status Def: Operating
Epa Classification Des: Actual or potential emissions are above the applicable major source thresholds.
Epa Compliance Status: In Compliance With Procedural Requirements
State Compliance Status: In Compliance With Procedural Requirements

Actions

Plant ID: 1014646
Anu1: 43
Date Achieved: 20110915
Penalty Amount: 0
Record Updated Dt: 20110915
Creation Date: 20110915
National Actn Type: FS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Key Action No:
Regional Data Element:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 34
Date Achieved: 20090507
Penalty Amount: 0
Record Updated Dt: 20090508
Creation Date: 20090508
National Actn Type: SR
All Air Prog Codes: 0, V
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 1
Date Achieved: 20030227
Penalty Amount: 0
Record Updated Dt: 20030827
Creation Date:
National Actn Type: SR
All Air Prog Codes: V
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 10
Date Achieved: 20040421
Penalty Amount: 0
Record Updated Dt: 20040707
Creation Date:
National Actn Type: SR
All Air Prog Codes: 0, V
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 14
National Actn Type: 3A
All Air Prog Codes: 0

Date Achieved:	20040426	**Result Code:**	PP
Penalty Amount:	0	**Pollutant Code:**	
Record Updated Dt:	20050301	**Violating Poll Cds:**	
Creation Date:		**Violation Type Cds:**	
Key Action No:			
Regional Data Element:			
National Action Desc:	OWNER/OPERATOR-CONDUCTED SOURCE TEST		
All Air Program Def:	0-SIP Source		
Result Def:	STACK TEST PASSED		
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	**National Actn Type:**	FS
Anu1:	19	**All Air Prog Codes:**	0, V
Date Achieved:	20050825	**Result Code:**	25
Penalty Amount:	0	**Pollutant Code:**	
Record Updated Dt:	20050825	**Violating Poll Cds:**	
Creation Date:		**Violation Type Cds:**	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE CONDUCTED FCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	**National Actn Type:**	PS
Anu1:	42	**All Air Prog Codes:**	0, V
Date Achieved:	20110603	**Result Code:**	25
Penalty Amount:	0	**Pollutant Code:**	
Record Updated Dt:	20110823	**Violating Poll Cds:**	
Creation Date:	20110823	**Violation Type Cds:**	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE PCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	**National Actn Type:**	CC
Anu1:	13	**All Air Prog Codes:**	V
Date Achieved:	20050520	**Result Code:**	
Penalty Amount:	0	**Pollutant Code:**	
Record Updated Dt:	20050628	**Violating Poll Cds:**	
Creation Date:		**Violation Type Cds:**	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA		
All Air Program Def:	V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	FS
Anu1:	47	***All Air Prog Codes:***	0, V
Date Achieved:	20131101	***Result Code:***	
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20140303	***Violating Poll Cds:***	
Creation Date:	20140303	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE CONDUCTED FCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	PS
Anu1:	26	***All Air Prog Codes:***	0, V
Date Achieved:	20070711	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20070911	***Violating Poll Cds:***	
Creation Date:	20070911	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE PCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	SR
Anu1:	45	***All Air Prog Codes:***	0, V
Date Achieved:	20130328	***Result Code:***	MC
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20130708	***Violating Poll Cds:***	
Creation Date:	20130708	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:	IN COMPLIANCE		
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	CB
Anu1:	44	***All Air Prog Codes:***	0, V
Date Achieved:	20120514	***Result Code:***	MC
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20130312	***Violating Poll Cds:***	
Creation Date:	20130312	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V ANNUAL COMPL CERT DUE/RECVD BY STATE/LOCAL		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:	IN COMPLIANCE		
Pollutant Def:			

All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 16
Date Achieved: 20050106
Penalty Amount: 0
Record Updated Dt: 20050412
Creation Date:
Key Action No:
Regional Data Element:
National Actn Type: ER
All Air Prog Codes: V
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY EPA
All Air Program Def: V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 2
Date Achieved: 20001127
Penalty Amount: 0
Record Updated Dt: 20030415
Creation Date:
Key Action No:
Regional Data Element:
National Actn Type: PS
All Air Prog Codes: 0
Result Code: 24
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 46
Date Achieved: 20131021
Penalty Amount: 0
Record Updated Dt: 20131029
Creation Date: 20131029
Key Action No:
Regional Data Element:
National Actn Type: PS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 27
Date Achieved: 20070911
Penalty Amount: 0
Record Updated Dt: 20070911
Creation Date: 20070911
Key Action No:
Regional Data Element:
National Actn Type: FS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 39
Date Achieved: 20101221
Penalty Amount: 0
Record Updated Dt: 20101221
Creation Date: 20101221
Key Action No:
Regional Data Element:
National Actn Type: FS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 3
Date Achieved: 20010713
Penalty Amount: 0
Record Updated Dt: 20030415
Creation Date:
Key Action No:
Regional Data Element:
National Actn Type: PS
All Air Prog Codes: 0
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 21
Date Achieved: 20060605
Penalty Amount: 0
Record Updated Dt: 20060609
Creation Date: 20060609
Key Action No:
Regional Data Element:
National Actn Type: PS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 41
Date Achieved: 20110408
Penalty Amount: 0
National Actn Type: SR
All Air Prog Codes: 0, V
Result Code: MC
Pollutant Code:

Record Updated Dt: 20110426 ***Violating Poll Cds:***
Creation Date: 20110426 ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** PS
Anu1: 9 ***All Air Prog Codes:*** 0, V
Date Achieved: 20040330 ***Result Code:*** 25
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20040421 ***Violating Poll Cds:***
Creation Date: ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** FS
Anu1: 7 ***All Air Prog Codes:*** 0, V
Date Achieved: 20031020 ***Result Code:*** 25
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20031020 ***Violating Poll Cds:***
Creation Date: ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** PS
Anu1: 40 ***All Air Prog Codes:*** 0, V
Date Achieved: 20100917 ***Result Code:*** 24
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20110405 ***Violating Poll Cds:***
Creation Date: 20110405 ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** SR
Anu1: 30 ***All Air Prog Codes:*** 0, V
Date Achieved: 20080319 ***Result Code:*** MC
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20080618 ***Violating Poll Cds:***
Creation Date: 20080618 ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** PS
Anu1: 4 ***All Air Prog Codes:*** 0, V
Date Achieved: 20020509 ***Result Code:*** 25
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20030415 ***Violating Poll Cds:***
Creation Date: ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** PS
Anu1: 32 ***All Air Prog Codes:*** 0, V
Date Achieved: 20080818 ***Result Code:*** 25
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20080908 ***Violating Poll Cds:***
Creation Date: 20080908 ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646 ***National Actn Type:*** CC
Anu1: 38 ***All Air Prog Codes:*** V
Date Achieved: 20100713 ***Result Code:***
Penalty Amount: 0 ***Pollutant Code:***
Record Updated Dt: 20101019 ***Violating Poll Cds:***
Creation Date: 20101019 ***Violation Type Cds:***
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA
All Air Program Def: V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID:	1014646	***National Actn Type:***	PS
Anu1:	35	***All Air Prog Codes:***	0, V
Date Achieved:	20090605	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20090731	***Violating Poll Cds:***	
Creation Date:	20090731	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE PCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	SR
Anu1:	37	***All Air Prog Codes:***	V
Date Achieved:	20100311	***Result Code:***	MC
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20100324	***Violating Poll Cds:***	
Creation Date:	20100324	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE		
All Air Program Def:	V-Title V Permits		
Result Def:	IN COMPLIANCE		
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	PS
Anu1:	5	***All Air Prog Codes:***	0, V
Date Achieved:	20030423	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20030827	***Violating Poll Cds:***	
Creation Date:		***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE PCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	CC
Anu1:	24	***All Air Prog Codes:***	V
Date Achieved:	20070308	***Result Code:***	
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20070309	***Violating Poll Cds:***	
Creation Date:	20070309	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA		
All Air Program Def:	V-Title V Permits		

Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 28
Date Achieved: 20080321
Penalty Amount: 0
Record Updated Dt: 20080331
Creation Date: 20080331
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA
All Air Program Def: V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:
National Actn Type: CC
All Air Prog Codes: V
Result Code:
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Actions

Plant ID: 1014646
Anu1: 31
Date Achieved: 20080624
Penalty Amount: 0
Record Updated Dt: 20080624
Creation Date: 20080624
Key Action No:
Regional Data Element:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:
National Actn Type: FS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Actions

Plant ID: 1014646
Anu1: 6
Date Achieved: 20030827
Penalty Amount: 0
Record Updated Dt: 20030827
Creation Date:
Key Action No:
Regional Data Element:
National Action Desc: STATE CONDUCTED FCE/OFF=SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:
National Actn Type: FF
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Actions

Plant ID: 1014646
Anu1: 22
Date Achieved: 20060613
Penalty Amount: 0
Record Updated Dt: 20060613
Creation Date: 20060613
National Actn Type: FS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:

Key Action No:
Regional Data Element:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 18
Date Achieved: 20050512
Penalty Amount: 0
Record Updated Dt: 20050613
Creation Date:
National Actn Type: SR
All Air Prog Codes: 0, V
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 17
Date Achieved: 20050512
Penalty Amount: 0
Record Updated Dt: 20050613
Creation Date:
National Actn Type: PS
All Air Prog Codes: 0, V
Result Code: 25
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: STATE PCE/ON-SITE
All Air Program Def: 0-SIP Source; V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 11
Date Achieved: 20030303
Penalty Amount: 0
Record Updated Dt: 20051006
Creation Date:
National Actn Type: CC
All Air Prog Codes: V
Result Code:
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
Key Action No:
Regional Data Element:
National Action Desc: TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA
All Air Program Def: V-Title V Permits
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 1014646
Anu1: 15
National Actn Type: FS
All Air Prog Codes: 0, V

Date Achieved:	20040513	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20040811	***Violating Poll Cds:***	
Creation Date:		***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE CONDUCTED FCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	PS
Anu1:	29	***All Air Prog Codes:***	0, V
Date Achieved:	20080410	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20080529	***Violating Poll Cds:***	
Creation Date:	20080529	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE PCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	SR
Anu1:	25	***All Air Prog Codes:***	0, V
Date Achieved:	20070302	***Result Code:***	MC
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20070330	***Violating Poll Cds:***	
Creation Date:	20070330	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:	IN COMPLIANCE		
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	SR
Anu1:	20	***All Air Prog Codes:***	0, V
Date Achieved:	20060411	***Result Code:***	MC
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20060413	***Violating Poll Cds:***	
Creation Date:		***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERTIFICATION REVIEW BY STATE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:	IN COMPLIANCE		
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	FS
Anu1:	36	***All Air Prog Codes:***	0, V
Date Achieved:	20090820	***Result Code:***	25
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20090820	***Violating Poll Cds:***	
Creation Date:	20090820	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	STATE CONDUCTED FCE/ON-SITE		
All Air Program Def:	0-SIP Source; V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Actions

Plant ID:	1014646	***National Actn Type:***	CC
Anu1:	33	***All Air Prog Codes:***	V
Date Achieved:	20090331	***Result Code:***	
Penalty Amount:	0	***Pollutant Code:***	
Record Updated Dt:	20090331	***Violating Poll Cds:***	
Creation Date:	20090331	***Violation Type Cds:***	
Key Action No:			
Regional Data Element:			
National Action Desc:	TITLE V COMPLIANCE CERT DUE/RECEIVED BY EPA		
All Air Program Def:	V-Title V Permits		
Result Def:			
Pollutant Def:			
All Violating Poll Def:			
All Violation Type Def:			

Historical Compliance - Air Program Level

Air Program Code:	0
Air Program Code Ref:	SIP Source
Historical Compliance Date:	0604, 0701, 0702, 0703, 0704, 0801, 0802, 0803, 0804, 0901, 0902, 0903, 0904, 1001, 1002, 1003, 1004, 1101, 1102, 1103, 1104, 1201, 1202, 1203, 1204, 1301, 1302, 1303, 1304, 1401, 1402, 1403
Historical Compliance Status:	C
Historical Compliance Stat Ref:	In Compliance With Procedural Requirements

Historical Compliance - Air Program Level

Air Program Code:	V
Air Program Code Ref:	Title V Permits
Historical Compliance Date:	0604, 0701, 0702, 0703, 0704, 0801, 0802, 0803, 0804, 0901, 0902, 0903, 0904, 1001, 1002, 1003, 1004, 1101, 1102, 1103, 1104, 1201, 1202, 1203, 1204, 1301, 1302, 1303, 1402, 1403
Historical Compliance Status:	C
Historical Compliance Stat Ref:	In Compliance With Procedural Requirements

Historical Compliance - Air Program Level

Air Program Code:	V
Air Program Code Ref:	Title V Permits
Historical Compliance Date:	1304, 1401
Historical Compliance Status:	U
Historical Compliance Stat Ref:	Unknown By Evaluation Calculation (Generated Value-Not Available For Input)

Air Program

Plant ID:	1014646	***Poll Classificatn:***	A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Program Code: V
Air Program Status: O
Pollutant Code: VOC
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Air Program Code Ref: Title V Permits
Epa Classification Code Ref: Actual or potential emissions are above the applicable major source thresholds.
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:
Pollutant Classification Ref: Actual or potential emissions are above the applicable major source thresholds.
Pollutant Complian Status Ref: In Compliance With Procedural Requirements
Poll Compli Status: C
Epa Class Code: A
Epa Compli Status: C

Air Program

Plant ID: 1014646
Air Program Code: 0
Air Program Status: O
Pollutant Code: ADMIN
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Air Program Code Ref: SIP Source
Epa Classification Code Ref: Actual or potential emissions are above the applicable major source thresholds.
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:
Pollutant Classification Ref: Actual or potential emissions are above the applicable major source thresholds.
Pollutant Complian Status Ref: In Compliance - Inspection
Poll Classificatn: A
Poll Compli Status: 3
Epa Class Code: A
Epa Compli Status: C

Air Program

Plant ID: 1014646
Air Program Code: 0
Air Program Status: O
Pollutant Code: VOC
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Air Program Code Ref: SIP Source
Epa Classification Code Ref: Actual or potential emissions are above the applicable major source thresholds.
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:
Pollutant Classification Ref: Actual or potential emissions are above the applicable major source thresholds.
Pollutant Complian Status Ref: In Compliance With Procedural Requirements
Poll Classificatn: A
Poll Compli Status: C
Epa Class Code: A
Epa Compli Status: C

Air Program

Plant ID: 1014646
Air Program Code: V
Air Program Status: O
Pollutant Code: FACIL
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Air Program Code Ref: Title V Permits
Epa Classification Code Ref: Actual or potential emissions are above the applicable major source thresholds.
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:
Pollutant Classification Ref:
Pollutant Complian Status Ref: Present, See Other Program(s)
Poll Classificatn:
Poll Compli Status: P
Epa Class Code: A
Epa Compli Status: C

9	2 of21	S	0.02 / 85.79	2,924.95 / 18	Mobile Coating Solutions Inc. 12766 VIOLET RD ADELANTO CA 92301	CERS HAZ

Latitude: 34.561160
Longitude: -117.386150

Regulated Programs

EI ID: 10046962 ***EI Description:*** Hazardous Waste Generator

EI ID: 10046962 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 12/11/2013 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Notes:

Returned to compliance on 01/10/2014. weekly insp recd

Violation Description:

Failure to properly handle, manage, label, and recycle used oil and fuel filters.

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Notes:

Returned to compliance on 06/30/2022. OBSERVATION: (2) 55 gallon drums of waste oily water located east of the maintenance building were observed open when not in use. CORRECTIVE ACTION: Close all the hazardous waste containers and submit photos to the CUPA demonstrating that the containers listed above has been properly closed.

Violation Description:

Failure to meet the following container management requirements:
(a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.
(b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to complete hazardous waste labels (CCR 66262.34(f)(3)) The following were found to have incomplete hazardous waste labels: (1) 250-gallon tank of used oil (1) 55-gallon drum of oily dirt (1) 55-gallon drum of waste antifreeze (2) 55-gallon drum of waste paint materials (1) 55-gallon drum of waste oily water (1) ~5-gallon container of waste oily material

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/07/2017. Hazardous Materials Business Plan (HMBP) was not accurate, complete, and/or current. Update the following

and resubmit in California Environmental Reporting System (CERS): 1) Update inventory to include: Archo 454HTP part A, Archo 454HTP part B, Powercrete J epoxy Part A, Powercrete J epoxy Part B; Wohl AA-133 pipe coating; (1) 55-gallon drum of oily dirt; (1) 55-gallon drum of waste antifreeze; (2) 55-gallon drums of waste paint; Universal Wastes i.e. (1) 55-gallon drum light bulbs; and (1) 55-gallon drum batteries 2) Facility site map was not current and/or complete. Last update was 3/14/12. Update submitted facility site map to include the following: north orientation, loading areas (if applicable), internal roads and/or adjacent streets, storm and sewer drains (if applicable), access and exit points, emergency shutoff (electricity, water, gas), evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. 3) Regulated [Truncated]

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Notes:

OBSERVATION: At time of inspection, observed (1) 55 gallon drum of used oil with accumulation start date of 10-22-21 on label and (1) 55 gallon drum of waste antifreeze with accumulation start date of 8-18-21 on label, located along west fence of the property. Accumulation time has exceeded. CORRECTIVE ACTION: Dispose of hazardous waste that has been stored over the applicable time limit and provide documentation that the violation has been corrected.

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met:
(1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to manage contaminated containers lawfully (CCR 66261.7) Empty containers that previously held a hazardous materials must be marked with the date it was emptied and be shipped for recycling, reconditioning, or reclamation of its scrap value; or managed on-site within one year of being emptied. Observed numerous empty containers stored throughout the facility that are not marked with the date it was emptied.

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: Un-Specified
Violation Notes:

Returned to compliance on 07/29/2022. OBSERVATION: At time of inspection, new owner has not obtained a current hazardous material handler permit with this Division. CORRECTIVE ACTION: Pay permit fees upon receipt of invoice.

Violation Description:

Business Plan Program - Administration/Documentation - General Local Ordinance

Violations

Violation Date: 12/11/2013 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Notes:

Returned to compliance on 01/10/2014. Failure to operate and maintain facility to prevent a fire, spill or release (CCR 66265.31) C of C recd

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to note accumulation start date on labels (CCR 66262.34(f)(2)) The following were lacking accumulation start dates: (1) 250-gallon tank of used oil (1) 55-gallon drum of oily dirt (1) 55-gallon drum of waste antifreeze (2) 55-gallon drum of waste paint materials (1) 55-gallon drum of waste oily water (yard) (1) ~5-gallon container of waste oily material (yard)

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 06/30/2022. OBSERVATION: (1) 55 gallon drum of used oil located along eastern wall of the maintenance building was observed without a hazardous waste label, (2) 55 gallon drums of waste oily water located east of the maintenance building were observed with faded and illegible hazardous waste labels, and (1) approximate 200 gallon container of used oil located along west fence of the property was observed without a hazardous waste label. CORRECTIVE ACTION: Properly label all hazardous waste containers and submit a photo to the CUPA demonstrating that the containers listed above has been properly labeled.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 06/20/2022. OBSERVATION: At time of inspection, a permanent EPA ID number has not been obtained. CORRECTIVE ACTION: Obtain a permanent EPA ID number by submitting form 1358 to DTSC. Submit a signed statement indicating that a valid EPA ID number has been obtained.

Violation Description:

Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 07/10/2017. Failure to determine if waste is hazardous waste (CCR 66262.11) Facilities that generate waste must determine if the waste meets hazardous waste criteria either by analytical testing or using generator knowledge. Observed the following: 1) Observed (10) 55-gallon drums of waste paint related materials outside west of the building. Per Manager, some containers were waste. 2) Observed several 5-gallon containers with unknown / unspecified contents found in the yard. Per Manager, containers were waste. 3) Observed (1) 55-gallon drum on unknown waste stored near the tar kettle area. 4) Observed approximately 18' x 10' of 10 mm of visqueen plastic set up on the ground outside west of the building with waste paint related materials out in the sun. Note: A facility cannot treat hazardous waste without appropriate permit and authorization from this Division. 5) Facility uses sand blasting to prepare pipe surfaces for lining and coating operations within the building [Truncated]

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/07/2017. Business Plan was not annually reviewed and electronically certified in California Environmental Reporting System (CERS).

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to label hazardous waste containers (CCR 66262.34(f)(3)) The following were found to be lacking hazardous waste labels: (2) 55-gallon drums of oily water (outside of maintenance shop) (1) 55-gallon drum of used oil (maintenance shop) (1) 55-gallon drum of waste oily water (yard) (1) ~5-gallon container of waste oily material (yard)

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to operate and maintain facility to prevent a fire, spill or release (CCR 66265.31) Observed spillage, paint, and oil on the ground at the following locations: hazardous material storage area outside of the building; tar kettle area; at the yard around open hazardous waste containers.

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: Un-Specified
Violation Notes:

Returned to compliance on 07/29/2022. OBSERVATION: At time of inspection, new owner has not obtained a current hazardous waste generator permit. CORRECTIVE ACTION: Pay permit fees upon receipt of invoice.

Violation Description:

Hazardous Waste Generator Program - Administration/Documentation - General Local Ordinance

Violations

Violation Date: 12/11/2013 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Notes:

Returned to compliance on 01/10/2014. Failure to manage hazardous waste lawfully (CHSC 25154) weekly insp recd

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 12/11/2013 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Notes:

Returned to compliance on 12/11/2013. Failure to label hazardous waste containers (CCR 66262.34(f)(3))

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Notes:

Returned to compliance on 06/07/2017. Used oil filters were not managed lawfully. (1) 55-gallon drum of drained used oil filters was lacking an accumulation start date.

Violation Description:

Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 06/30/2022. OBSERVATION: At time of inspection, employee safety and hazardous communications training was last

conducted in October 2020. CORRECTIVE ACTION: Conduct initial and annual employee training and maintain training records for a minimum of three years. Submit a signed statement indicating that training has been conducted and that training records will be kept on site for review.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Failure to keep hazardous waste containers closed when not in active use (CCR 66265.173(a)) The following hazardous waste containers were not maintained closed/secure: (2) 55-gallon drums of oily water (1) ~5-gallon container of waste oily material (yard)

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/02/2022. OBSERVATION: At time of inspection, new owner has not submitted a complete business plan in CERS. CORRECTED: A complete business plan was submitted on 6-2-2022.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 04/11/2017 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/07/2017. Hazardous waste accumulation time exceeded (CCR 66262.34(a)) Since there was no way of determining the exact time the waste material has been on site, all waste materials are required to be removed. (1) 250-gallon tank of used oil (1) 55-gallon drum of oily dirt (1) 55-gallon drum of waste antifreeze (2) 55-gallon drum of waste paint materials (1) 55-gallon drum of waste oily water (yard) (1) ~5-gallon container of waste oily material (yard)

Violation Description:

Hazardous Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 06/01/2022 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 22 CCR 23 66273.35 - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.35
Violation Notes:

OBSERVATION: (1) 55 gallon drum of waste aerosol cans located along west fence of the property was observed with an accumulation start date of 7-25-20. Accumulation time has exceeded. CORRECTIVE ACTION: Dispose of waste aerosol cans and submit a copy of the manifest/receipt.

Violation Description:

Failure to accumulate universal waste for one year or less and to demonstrate the length of time that the universal waste has been accumulated from the date it became a waste or was received.

Enforcements

Enf Action Date: 04/11/2017 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: San Bernardino County Fire Department
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 04/11/2017 ***Enf Action Program:*** HW
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: San Bernardino County Fire Department
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 12/11/2013 ***Enf Action Program:*** HW
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: San Bernardino County Fire Department
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 12/11/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 07/28/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/01/2022
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 12/11/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval Notes:

insp hand mobile pipe; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/11/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

HANDLER INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/28/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 04/11/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

GENERATOR INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/01/2022
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Environmental Contact
Entity Name: Greg Evans
Entity Title:
Address: 12766 VIOLET RD
City: Rialto
State: CA
Country:
Zip Code: 92377
Phone:

Affil Type Desc: Legal Owner
Entity Name: State Pipe & Supply Inc.
Entity Title:
Address: 183 S. Cedar Ave.
City: Rialto
State: CA
Country: United States
Zip Code: 92376

Phone: (909) 877-9999

Affil Type Desc: Identification Signer
Entity Name: Angel Carcamo
Entity Title: Plant Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: Angel Carcamo
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 12766 Violet Rd
City: Adelanto
State: CA
Country:
Zip Code: 92301
Phone:

Affil Type Desc: Parent Corporation
Entity Name: MOBILE COATING SOLUTIONS, INC.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: San Bernardino County Fire
Entity Title:
Address: 598 South Tippecanoe Avenue, First Floor
City: San Bernardino
State: CA
Country:
Zip Code: 92415-0153
Phone: (909) 386-8401

Affil Type Desc: Operator
Entity Name: Mobile Coating Solutions Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (760) 246-4707

Coordinates

Env Int Type Code: HWG
Program ID: 10046962
Latitude: 34.561981
Longitude: -117.385193
Coord Name:
Ref Point Type Desc: Unknown

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	3 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE WRAPPERS & COATERS 12766VIOLET ROAD ADELANTO CA 92301	EMISSIONS

Source:

2001 Criteria Data

Facility ID:	39701067	**CERR Code:**	
Facility SIC Code:	3479	**TOGT:**	14.57
CO:	36	**ROGT:**	14.57
Air Basin:	MD	**COT:**	.07
District:	MOJ	**NOXT:**	.24
COID:	SBD	**SOXT:**	0
DISN:	MOJAVE DESERT AQMD	**PMT:**	18.03
CHAPIS:	Y	**PM10T:**	8.89

2001 Toxic Data

Facility ID:	39701067	**COID:**	SBD
Facility SIC Code:	3479	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2002 Criteria Data

Facility ID:	39701067	**CERR Code:**	
Facility SIC Code:	3479	**TOGT:**	14.5721207
CO:	36	**ROGT:**	14.57014999754
Air Basin:	MD	**COT:**	.0636566
District:	MOJ	**NOXT:**	.236439
COID:	SBD	**SOXT:**	.0015094
DISN:	MOJAVE DESERT AQMD	**PMT:**	18.0310687
CHAPIS:	Y	**PM10T:**	8.889810415

2002 Toxic Data

Facility ID:	39701067	**COID:**	SBD
Facility SIC Code:	3479	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2003 Criteria Data

Facility ID:	39701067	**CERR Code:**	
Facility SIC Code:	3479	**TOGT:**	14.5721207
CO:	36	**ROGT:**	14.56871
Air Basin:	MD	**COT:**	.0636566
District:	MOJ	**NOXT:**	.236439
COID:	SBD	**SOXT:**	.0015094
DISN:	MOJAVE DESERT AQMD	**PMT:**	18.0310687

CHAPIS:	Y	**PM10T:**	8.885258

2003 Toxic Data

Facility ID:	39701067	**COID:**	SBD
Facility SIC Code:	3479	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	1.2		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2004 Criteria Data

Facility ID:	39701067	**CERR Code:**	
Facility SIC Code:	3479	**TOGT:**	14.5674266
CO:	36	**ROGT:**	13.29293751052
Air Basin:	MD	**COT:**	.0506169
District:	MOJ	**NOXT:**	.188006
COID:	SBD	**SOXT:**	.0012002
DISN:	MOJAVE DESERT AQMD	**PMT:**	16.7741214
CHAPIS:	Y	**PM10T:**	14.79871581

2004 Toxic Data

Facility ID:	39701067	**COID:**	SBD
Facility SIC Code:	3479	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	.76		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	4 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE LINING AND COATING 12766 VIOLET ROAD ADELANTO CA 92301	EMISSIONS

Source:

2013 Criteria Data

Facility ID:	39701067	**CERR Code:**	
Facility SIC Code:	3479	**TOGT:**	16.9990906
CO:	36	**ROGT:**	11.8755648
Air Basin:	MD	**COT:**	
District:	MOJ	**NOXT:**	
COID:	SBD	**SOXT:**	
DISN:	MOJAVE DESERT AQMD	**PMT:**	28.694450815
CHAPIS:		**PM10T:**	22.727192915

2013 Toxic Data

Facility ID:	39701067	**COID:**	SBD
Facility SIC Code:	3479	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TS: 3.74
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2015 Criteria Data

Facility ID:	39701067	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	14.012
CO:	36	***ROGT:***	9.789
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	37.93429
CHAPIS:		***PM10T:***	29.71489

2015 Toxic Data

Facility ID:	39701067	***COID:***	SBD
Facility SIC Code:	3479	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		

TS: .11
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2016 Criteria Data

Facility ID:	39701067	***CERR CODE:***	
Facility SIC Code:	3479	***TOGT:***	13.8160963
CO:	36	***ROGT:***	9.6510673
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	40.279298
CHAPIS:		***PM10T:***	31.349353

2016 Toxic Data

Facility ID:	39701067	***TS:***	3.25
Facility SIC Code:	3479	***HRA:***	
CERR CODE:		***CH Index:***	
COID:	SBD	***AH Index:***	
CO:	36	***Air Basin:***	MD
DISN:	MOJAVE DESERT AQMD	***District:***	MOJ
CHAPIS:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	5 of21	S	0.02 / 85.79	2,924.95 / 18	***MOBILE PIPE WRAPPERS & COATERS*** ***12766 VIOLET ROAD*** ***ADELANTO CA 92301***	***EMISSIONS***

Source:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	6 of21	S	0.02 / 85.79	2,924.95 / 18	***MOBILE PIPE LINING AND COATING, INC.*** ***12766 VIOLET ROAD*** ***ADELANTO CA 92301***	***EMISSIONS***

Source:

2017 Criteria Data

Facility ID:	198801067	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	11.6874735
CO:	36	***ROGT:***	8.164871
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	38.764265
CHAPIS:		***PM10T:***	29.9853207

2017 Toxic Data

Facility ID:	198801067	***COID:***	SBD
Facility SIC Code:	3479	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	1.76		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	1067	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	13.2311446
CO:	36	***ROGT:***	9.2438
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	41.6335641
CHAPIS:		***PM10T:***	30.6270165

2018 Toxic Data

Facility ID:	1067	***COID:***	SBD
Facility SIC Code:	3479	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	1.45		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	1067	***ROGT:***	9.2438
District:	MOJ	***COT:***	
Facility SIC Code:	3479	***NOXT:***	
CO ID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
PM10T:	30.6270165		
TOGT:	13.2311446		
PMT:	41.6335641		

2019 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Basin:	MD	**CHAPIS:**	
Faccility ID:	1067	**CERR Code:**	
District:	MOJ	**TS:**	1.51
Facility SIC Code:	3479	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	1067	**ROGT:**	5.02
District:	MOJ	**COT:**	
Facility SIC Code:	3479	**NOXT:**	
CO ID:	SBD	**SOXT:**	
DISN:	MOJAVE DESERT AQMD		
TOGT:	7.188		
PMT:	23.988764		
PM10T:	15.482723375		

2020 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	1067	**CHERR Code:**	
District:	MOJ	**TS:**	1.51
Facility SIC Code:	3479	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	7 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE COATING SOLUTIONS 12766 VIOLET ROAD ADELANTO CA 92301	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2021 Toxic Data

Co:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	1067	**Cerr Code:**	
District:	MOJ	**TS:**	1.07
Facility SIC Code:	3479	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	**CHAPIS:**	
Air Basin:	MD	**Cerr Code:**	
Facility ID:	1067	**ROGT:**	5.644
District:	MOJ	**COT:**	
Facility SIC Code:	3479	**NOXT:**	
CO ID:	SBD	**SOXT:**	
DISN:	MOJAVE DESERT AQMD		
TOGT:	8.078		
PMT:	20.25496575		
PM10T:	13.375445906		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2023 Pollutant Data

Facility ID:	1067	***CO:***	36
Facility SIC Code:	3479	***CO ID:***	SBD
CERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
ROGT:	9.0136206	***NOXT:***	
COT:		***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
TOGT:	12.9024159		
PMT:	24.531689994		
PM10T:	15.052632391		
Source:	2023 Pollutant Data		

2022 Criteria Data

Facility ID:	1067	***District:***	MOJ
Facility SIC Code:	3479	***Air Basin:***	MD
Cerr Code:		***Co:***	36
CHAPIS:		***CO ID:***	SBD
ROGT:	5.644	***NOXT:***	
COT:		***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
TOGT:	8.078		
PMT:	20.25496575		
PM10T:	13.375445906		
Source:	2022 Criteria Data		

2022 Toxic Data

Facility ID:	1067	***CO:***	36
Facility SIC Code:	3479	***Air Basin:***	MD
CHERR Code:		***District:***	MOJ
CHAPIS:		***COID:***	SBD
Health Risk Asmt:		***TS:***	1.07
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2022 Toxic Data		

2023 Toxic Data

Facility ID:	1067	***CO:***	36
Facility SIC Code:	3479	***COID:***	SBD
CHERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
TS:	.78		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2023 Toxic Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	*8 of21*	*S*	*0.02 / 85.79*	*2,924.95 / 18*	***MOBILE PIPE WRAPPERS & COATERS*** ***12766 VIOLET ROAD*** ***ADELANTO CA 92301-2706***	***FINDS/FRS***

Registry ID:	110014324070
FIPS Code:	06071
HUC Code:	18090208
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Create Date:	25-APR-03
Update Date:	01-JUN-17
Interest Types:	AIR MAJOR, AIR SYNTHETIC MINOR
SIC Codes:	3479
SIC Code Descriptions:	COATING, ENGRAVING, AND ALLIED SERVICES, NOT ELSEWHERE CLASSIFIED
NAICS Codes:	339914
NAICS Code Descriptions:	COSTUME JEWELRY AND NOVELTY MANUFACTURING.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	25
Census Block Code:	060710091164111
EPA Region Code:	09
County Name:	SAN BERNARDINO
US/Mexico Border Ind:	
Latitude:	34.56102
Longitude:	-117.38524
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Frs Facility Detail Report URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110014324070
Program Acronyms:	

AIR:CAMDA00006071M1067, AIRS/AFS:06071M1067

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	9 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE WRAPPERS & COATERS 12766 VIOLET RD ADELANTO CA 92301	FINDS/FRS

Registry ID:	110065163673
FIPS Code:	06071
HUC Code:	18090208
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	10-OCT-15
Update Date:	
Interest Types:	AIR PROGRAM, HAZARDOUS AIR POLLUTANT MAJOR, ICIS-NPDES NON-MAJOR, STATE MASTER, STORM WATER INDUSTRIAL, UNSPECIFIED UNIVERSE
SIC Codes:	3479
SIC Code Descriptions:	COATING, ENGRAVING, AND ALLIED SERVICES, NOT ELSEWHERE CLASSIFIED
NAICS Codes:	332812, 339910
NAICS Code Descriptions:	METAL COATING, ENGRAVING (EXCEPT JEWELRY AND SILVERWARE), AND ALLIED SERVICES TO MANUFACTURERS.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	25
Census Block Code:	060710091164129
EPA Region Code:	09
County Name:	SAN BERNARDINO
US/Mexico Border Ind:	
Latitude:	34.56198
Longitude:	-117.38519
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065163673
Program Acronyms:

CA-ENVIROVIEW:49666, EIS:4838911, EPS:EPS10043776, NPDES:CAZ423192, RCRAINFO:CAL000364933

9	10 of21	S	0.02 / 85.79	2,924.95 / 18	**UNDERGROUND SOLUTIONS INC** **DBA MOBILE PIPE LINING** **12766 VIOLET RD** **ADELANTO CA 92301**	FINDS/FRS

Registry ID: 110070318896
FIPS Code:
HUC Code:
Site Type Name:
Location Description:
Supplemental Location:
Create Date: 27-SEP-18
Update Date:
Interest Types: OSHA ESTABLISHMENT
SIC Codes: 3479
SIC Code Descriptions: COATING, ENGRAVING, AND ALLIED SERVICES, NOT ELSEWHERE CLASSIFIED
NAICS Codes: 332812
NAICS Code Descriptions: METAL COATING, ENGRAVING (EXCEPT JEWELRY AND SILVERWARE), AND ALLIED SERVICES TO MANUFACTURERS.
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name:
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070318896
Program Acronyms:

OSHA-OIS:316212349

9	11 of21	S	0.02 / 85.79	2,924.95 / 18	**MOBILE COATING SOLUTIONS INC** **12766 VIOLET RD** **ADELANTO CA 92301**	FINDS/FRS

Registry ID: 110071291812
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 04-JUL-22
Update Date:
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Conveyor:	RCRAINFO
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	25
Census Block Code:	060710091164129
EPA Region Code:	
County Name:	SAN BERNARDINO
US/Mexico Border Ind:	
Latitude:	34.561058
Longitude:	-117.38521
Reference Point:	ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method:	GDT-ADDRESS MATCHING (GEOCODING)
Accuracy Value:	
Datum:	NAD83
Source:	
Frs Facility Detail Report URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071291812
Program Acronyms:	

RCRAINFO:CAL000471420

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	12 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE LINING AND COATING, INC. 12766 VIOLET ROAD ADELANTO CA 92301	FINDS/FRS

Registry ID:	110071764766
FIPS Code:	06071
HUC Code:	
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	15-JUL-24
Update Date:	27-AUG-24
Interest Types:	
SIC Codes:	3479
SIC Code Descriptions:	COATING, ENGRAVING, AND ALLIED SERVICES, NOT ELSEWHERE CLASSIFIED
NAICS Codes:	332812
NAICS Code Descriptions:	METAL COATING, ENGRAVING (EXCEPT JEWELRY AND SILVERWARE), AND ALLIED SERVICES TO MANUFACTURERS.
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	09
County Name:	UNITED STATES
US/Mexico Border Ind:	
Latitude:	
Longitude:	
Reference Point:	
Coord Collection Method:	
Accuracy Value:	
Datum:	NAD83
Source:	
Frs Facility Detail Report URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071764766
Program Acronyms:	

CARB-TCH:36MDMOJ1067

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	13 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE COATING SOLUTIONS 12766 VIOLET ROAD ADELANTO CA 92301	FINDS/FRS

Registry ID: 110071765817
FIPS Code: 06071
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 15-JUL-24
Update Date: 27-AUG-24
Interest Types: AIR EMISSIONS CLASSIFICATION UNKNOWN
SIC Codes: 3479
SIC Code Descriptions: COATING, ENGRAVING, AND ALLIED SERVICES, NOT ELSEWHERE CLASSIFIED
NAICS Codes: 332812
NAICS Code Descriptions: METAL COATING, ENGRAVING (EXCEPT JEWELRY AND SILVERWARE), AND ALLIED SERVICES TO MANUFACTURERS.
Conveyor: EIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091164129
EPA Region Code: 09
County Name: SAN BERNARDINO
US/Mexico Border Ind:
Latitude: 34.562174
Longitude: -117.385236
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110071765817
Program Acronyms:

CARB-TCH:36MDMOJ39701067, EIS:18333711

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	14 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE LINING & COATING INC 12766 VIOLET RD ADELANTO CA 92301	HAZ GEN

EPA ID: CAL000364933
Facility County: SAN BERNARDINO
Address 2:
County:
Details DTSC HWTS:
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAL000364933

Tanner Details

Waste Category Code: 331
Waste Category: Off-specification, aged or surplus organics
Yearly Totals:

2024: 0.3065
2018: 0.495

Waste Category Code: 352
Waste Category: Other organic solids
Yearly Totals:

2024: 0.1375
2018: 0.05

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Details

Contact Name: SAMANTHA LAWS
Mailing Street: 550 SYCAMORE DR
Mailing City: 550 SYCAMORE DR
Mailing Zip: 95035
Contact Phone: 4088193048
Year: 2024

Contact Details

Contact Name: SAMANTHA LAWS
Mailing Street: 550 SYCAMORE DR
Mailing City: 550 SYCAMORE DR
Mailing Zip: 95035
Contact Phone: 4088193048
Year: 2018

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	15 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE PIPE WRAPPERS & COATERS INC 12766 VIOLET RD ADELANTO CA 923010000	HAZ GEN

EPA ID: CAL000111623
Address 2:
Facility County: 36
County: San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAL000111623

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	16 of21	S	0.02 / 85.79	2,924.95 / 18	MOBILE COATING SOLUTIONS INC 12766 VIOLET RD ADELANTO CA 92301	HAZ GEN

EPA ID: CAL000471420
Address 2:
Facility County: SAN BERNARDINO
County:
Details DTSC HWTS:
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAL000471420

Tanner Details

Waste Category Code: 352
Waste Category: Other organic solids
Yearly Totals:

2023: 4.5125

Waste Category Code: 331
Waste Category: Off-specification, aged or surplus organics
Yearly Totals:

2024: 1.45872
2023: 6.36049

Contact Details

Contact Name: ANGEL CARCAMO
Mailing Street: 12766 VIOLET RD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Mailing City: 12766 VIOLET RD
Mailing Zip: 92301
Contact Phone: 7604681075
Year: 2023

Contact Details

Contact Name: ANGEL CARCAMO
Mailing Street: 12766 VIOLET RD
Mailing City: 12766 VIOLET RD
Mailing Zip: 92301
Contact Phone: 7604681075
Year: 2024

---

9 | ***17 of21*** | ***S*** | ***0.02 / 85.79*** | ***2,924.95 / 18*** | ***BECK OIL INC***
12766 VIOLET RD
ADELANTO CA 92301 | ***HAZNET***

EPA ID: CAC002670575
NAICS Code:
SIC Code:
Create Date: 7/6/2011
Fac Act Ind: No
Inact Date: 1/3/2012
County: 36
County Name: San Bernardino
County:
Mail Name:
Mailing Addr 1: 16640 S D ST
Mailing Addr 2:

Mailing City: VICTORVILLE
Mailing State: CA
Mailing Zip: 923953169
Region Code: 4
Owner Name: BECK OIL INC
Owner Addr 1: 16640 S D ST
Owner Addr 2:
Owner City: VICTORVILLE
Owner State: CA
Owner Zip: 923953169
Owner Phone: 7602454191
Owner Fax:

---

9 | ***18 of21*** | ***S*** | ***0.02 / 85.79*** | ***2,924.95 / 18*** | ***MOBILE PIPE WRAPPERS & COATERS, INC.***
12766 VIOLET ROAD
ADELANTO CA 92301 | ***ICIS***

EPA Region: 09
Registry ID: 110014324070
Pgm Sys ID: CAMDA00006071M1067
Pgm Sys Acrnm: AIR
Permit Type:

Federal Fac ID:
Tribal Land Code:
County: San Bernardino
Latitude 83: 34.56102
Longitude 83: -117.38524

---

9 | ***19 of21*** | ***S*** | ***0.02 / 85.79*** | ***2,924.95 / 18*** | ***MOBILE PIPE LINING & COATING INC***
12766 VIOLET RD
ADELANTO CA 92301 | ***RCRA NON GEN***

Handler ID: CAL000364933
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No

Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No

Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	D	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20220218	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:		***Location Latitude:***	34.561048
In Handler Univ:	N	***Location Longitude:***	-117.385316
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	D
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20220302
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	MOBILE PIPE LINING & COATING INC
Location Street No:	
Location Street1:	12766 VIOLET RD

Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ANDY STERLING
Contact Street No:	
Contact Street1:	12766 VIOLET RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	US
Contact Phone & Ext:	760-246-4707
Contact Fax:	760-246-4348
Contact Email Address:	ASTERLING@MOBILEPIPE.NET
Contact Title:	
Owner Name:	
Owner Type:	
Owner Seq:	
Operator Name:	UGSI INC.
Operator Type:	O
Operator Seq:	1
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20110627
Handler Name:	MOBILE PIPE LINING & COATING INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20220218
Handler Name:	MOBILE PIPE LINING & COATING INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Deactivation
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	13135 DANIELSON ST STE 203
Name:	UGSI INC.	***Street2:***	
Dt Became Current:		***City:***	POWAY
Dt Ended Current:		***State:***	CA
Phone:	858-679-9551	***Country:***	US
Source Type:	Deactivation	***Zip:***	92064-0000

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	13135 DANIELSON ST STE 203
Name:	UGSI INC.	***Street2:***	
Dt Became Current:		***City:***	POWAY
Dt Ended Current:		***State:***	CA
Phone:	858-679-9551	***Country:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Implementer	**Zip:**	92064-0000
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street1:**	12766 VIOLET RD
Name:	JIM HARVEY	**Street2:**	
Dt Became Current:		**City:**	ADELANTO
Dt Ended Current:		**State:**	CA
Phone:	760-246-4707	**Country:**	
Source Type:	Implementer	**Zip:**	92301

Historical Handler Details

Receive Dt:	20110627
Generator Code Description:	Not a Generator, Verified
Handler Name:	MOBILE PIPE LINING & COATING INC

9	*20 of21*	*S*	*0.02 / 85.79*	*2,924.95 / 18*	***MOBILE COATING SOLUTIONS INC*** ***12766 VIOLET RD*** ***ADELANTO CA 92301***	***RCRA NON GEN***

Handler ID:	CAL000471420
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	56299
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20220620	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.561058
In Handler Univ:	N	**Location Longitude:**	-117.38521
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		

Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20220620
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	MOBILE COATING SOLUTIONS INC
Location Street No:	
Location Street1:	12766 VIOLET RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	GREG EVANS
Contact Street No:	
Contact Street1:	12766 VIOLET RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	
Contact Phone & Ext:	562-209-8774
Contact Fax:	
Contact Email Address:	GREGE@STATEPIPE.COM
Contact Title:	
Owner Name:	MOBILE COATING SOLUTIONS INC
Owner Type:	O
Owner Seq:	1
Operator Name:	GREG EVANS
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20220620
Handler Name:	MOBILE COATING SOLUTIONS INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	12766 VIOLET RD
Name:	GREG EVANS	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	562-209-8774	***Country:***	
Source Type:	Implementer	***Zip:***	92301
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	183 S CEDAR AVE
Name:	MOBILE COATING SOLUTIONS INC	***Street2:***	
Dt Became Current:		***City:***	RIALTO
Dt Ended Current:		***State:***	CA
Phone:	909-877-9999	***Country:***	
Source Type:	Implementer	***Zip:***	92376

9	***21 of21***	***S***	***0.02 / 85.79***	***2,924.95 / 18***	***MOBILE COATING SOLUTIONS INC. 12766 VIOLET ADELANTO CA 92301***	***SANBERN CUPA***

Facility ID:	FA0007469
Owner Info:	STATE PIPE & SUPPLY INC
Mailing Care of:	OSANCHEZ@MOBILEPIPE.NET
Mailing Address 2:	
Mailing City:	ADELANTO
Mailing State:	CA
Mailing Zip:	92301

Detail(s)

Permit ID:	PT0012708
Status:	ACTIVE
Program Element Code:	4453
Permit Desc:	SMALL QUANTITY GENERATOR
To:	5/31/2025
Mailing Address 1:	12766 VIOLET RD
Permit ID:	PT0012707
Status:	ACTIVE
Program Element Code:	4244
Permit Desc:	HAZARDOUS MATERIALS 11-30 CHEMICALS
To:	5/31/2025
Mailing Address 1:	12766 VIOLET RD

10	***1 of14***	***ENE***	***0.02 / 104.47***	***2,904.52 / -3***	***Kinder Morgan 13334 Air Expressway Rd Victorville CA 92394***	***CHMIRS***

Control No:	09-3605	***Notified Date:***	

Year: 2009 **Notified Date Time:**
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/894f60a7a0b81c28882575b40052fb25?OpenDocument

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Yes	**3 Ves >= 300 Tons:**	
1 Substance:	Trans Mix	**Incident Date:**	5/12/2009
1 Measure:	Gal(s)	**Incident Time:**	804
1 Other:		**Spill Site:**	Other
1 Quantity:	3	**Injuries?:**	
1 Type:	PETROLEUM	**No of Injuries:**	0
1 Pipeline:		**Fatals?:**	
1 Vessel >= 300 Tons:		**No of Fatals:**	0
2 Substance:		**Evacs?:**	
2 Quantity:		**No of Evacs:**	0
2 Measure:		**Cleanup:**	Reporting Party
2 Type:		**Site:**	
2 Other:		**Cause:**	Mechanical
2 Pipeline:		**Cause Other:**	
2 Vessel >= 300 Tons:		**Dog No:**	
3 Substance:		**Water:**	No
3 Quantity:		**Water Way:**	
3 Measure:		**City:**	Victorville
3 Type:		**County:**	San Bernardino County
3 Other:		**ZIP:**	92394
3 Pipeline:			

Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: 13334 Air Expressway Rd
Description: Caller states substance was released due to a leaky pump seal. Caller states substance released to a diked area. Caller states repairs are being made.

Spill Report View

Water:		**Creation Date:**	05/12/2009 08:06 AM
Document Title:	SPILL Report		

Spill Site: Other
Type: PETROLEUM

Hazardous Materials Spill Report

Date :	05/12/2009	**Name:**	
Time:	0806	**Phone:**	
Incident Date:	05/12/2009	**Ext:**	
Incident Time:	0804	**Pag Cell:**	
Control Cal OES:	09-3605	**Prs Name:**	
Control NRC:		**Prs Phone:**	
Water Involved:	No	**Prs Ext:**	
Drink Wtr Impact:		**Prs Pag Cell:**	
Detail for Other:		**Incident Desc:**	
UPRR Rim No:		**Notification Info:**	
DOG Unit:		**Notification List:**	
RWQCB Unit:	6B		

Contained: Yes
Waterway:
Received By:
Cleanup By: Reporting Party
Incident Location: 13334 Air Expressway Rd
Additional County:
1 Substance: Trans Mix
1 Qty: =
1 Amount : 3
1 Measure: Gal(s)
1 Type: PETROLEUM

1 Other:	
1 Pipeline:	No
1 Ves >= 300 Tons:	No
2 Substance:	
2 Qty:	=
2 Amount:	
2 Measure:	
2 Type:	
2 Other:	
2 Pipeline:	No
2 Ves >= 300 Tns:	No
3 Substance:	
3 Qty:	=
3 Amount:	
3 Measure:	
3 Type:	
3 Other:	
3 Pipeline:	No
3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	None
Agency:	Kinder Morgan
PRS Agency:	
Sec Agency:	San Bernardino County Health Department
Admin Agency:	Victorville Fire Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	
Header Unknown:	MOJAVE DESERT AQMD
Site:	Other Description for Other :
Reported Cause:	Mechanical
R R Crssing < 50 Ft:	
Description:	Caller states substance was released due to a leaky pump seal. Caller states substance released to a diked area. Caller states repairs are being made.

Spill Report View

Water:		***Creation Date:***	05/12/2009 08:34 AM
Document Title:	Cal OES-Update		
Spill Site:			
Type:	PETROLEUM		

OES Hazardous Materials Spill Update

Occurrence Date:	05/12/2009	***Prs Notif Upd Nm:***	
Occurrence Time:	0804	***Phone No:***	
Notify Date:	05/12/2009	***Ext:***	
Notify Time:	0806	***Pag Cell:***	
NRC:	905367	***Fax Notific List 2:***	
RWQCB Unit:		***Admin Agency 2:***	
Unknown Header:		***Add Admin Agency 2:***	
OP Area:	San Bernardino County	***Secondary Agency 2:***	
RWQCB Unit 2:		***Dog Unit 2:***	
Add Counties 2:			
1 Substance:	Trans Mix		
1 Qty Amount:	3		
1 Measure:	Gal(s)		
1 Type:	PETROLEUM		
1 Other:			
1 Pipeline:			
1 Ves >= 300 Tons:			
2 Substance:			
2 Qty Amount:			

2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS
Other Notified:
Confirmation Request:
Administering Agency: Victorville Fire Department
Secondary Agency: San Bernardino County Health Department
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/5d1309c619178240882575b400558f82?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

05/12/2009 08:34:32 AM - 05/12/09 0835 Hrs, Received NRC fax 905367.

Situation Update:

05/12/09 0835 Hrs, Received NRC fax 905367.

Original Description:

Caller states substance was released due to a leaky pump seal. Caller states substance released to a diked area. Caller states repairs are being made.

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

10	2 of14	ENE	0.02 / 104.47	2,904.52 / -3	Kinder Morgan 13334 Air Express Way Victorville CA 92394	CHMIRS

Control No: 07-2762
Year: 2007
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/0c2620cbe09a1f6b882572d4005d2952?OpenDocument
Notified Date:
Notified Date Time:

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained: Yes
1 Substance: Jet Fuel
1 Measure: Gal(s)
1 Other:
1 Quantity: Unknown
1 Type: PETROLEUM
1 Pipeline:
1 Vessel >= 300 Tons:
2 Substance:
2 Quantity:
2 Measure:
2 Type:
3 Ves >= 300 Tons:
Incident Date: 5/7/2007
Incident Time: 952
Spill Site: Other
Injuries?:
No of Injuries: 0
Fatals?:
No of Fatals: 0
Evacs?:
No of Evacs: 0
Cleanup: Reporting Party
Site:

2 Other:		**Cause:**	
2 Pipeline:		**Cause Other:**	
2 Vessel >= 300 Tons:		**Dog No:**	
3 Substance:		**Water:**	No
3 Quantity:		**Water Way:**	
3 Measure:		**City:**	Victorville
3 Type:		**County:**	San Bernardino County
3 Other:		**ZIP:**	92394
3 Pipeline:			
Admin Agency:	Victorville Fire Department		
Notification Area:	AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS		
Location:	13334 Air Express Way		
Description:	Equipment failure caused this spill		

Spill Report View

Water:		**Creation Date:**	05/07/2007 10:20 AM
Document Title:	Cal OES-Update		
Spill Site:			
Type:	PETROLEUM		

OES Hazardous Materials Spill Update

Occurrence Date:	05/07/2007	**Prs Notif Upd Nm:**	
Occurrence Time:		**Phone No:**	
Notify Date:	05/07/2007	**Ext:**	
Notify Time:	0957	**Pag Cell:**	
NRC:		**Fax Notific List 2:**	
RWQCB Unit:		**Admin Agency 2:**	
Unknown Header:		**Add Admin Agency 2:**	
OP Area:	San Bernardino County	**Secondary Agency 2:**	
RWQCB Unit 2:		**Dog Unit 2:**	
Add Counties 2:			
1 Substance:	Jet Fuel		
1 Qty Amount:	Unknown		
1 Measure:	Gal(s)		
1 Type:	PETROLEUM		
1 Other:			
1 Pipeline:			
1 Ves >= 300 Tons:			
2 Substance:			
2 Qty Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:			
2 Ves >= 300 Tons:			
3 Substance:			
3 Qty Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:			
3 Ves >= 300 Tons:			
Pers Reporting Spill Agency:			
Pers Notifying CA OES Agency:	Kinder Morgan		
Fax Notifi List:	AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS		
Other Notified:			
Confirmation Request:			
Administering Agency:	Victorville Fire Department		
Secondary Agency:	San Bernardino County Health Department		
Additional Admin Agency:			
Additional Counties:			
Doc URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/553cee4adb32ed2d882572d4005f47ce?OpenDocument		
Update Known Impact:			
Update Cause:			

Update Description:

Situation Update:

NRC report # 834574 received

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

Spill Report View

Water: ***Creation Date:*** 05/07/2007 09:57 AM
Document Title: SPILL Report
Spill Site: Other
Type: PETROLEUM

Hazardous Materials Spill Report

Date :	05/07/2007	***Name:***	
Time:	0957	***Phone:***	
Incident Date:	05/07/2007	***Ext:***	
Incident Time:	0952	***Pag Cell:***	
Control Cal OES:	07-2762	***Prs Name:***	
Control NRC:		***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	
UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		

Contained: Yes
Waterway:
Received By:
Cleanup By: Reporting Party
Incident Location: 13334 Air Express Way
Additional County:
1 Substance: Jet Fuel
1 Qty: =
1 Amount : Unknown
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fatality: No
Evacuation: No
Known Impact:
Agency: Kinder Morgan
PRS Agency:
Sec Agency: San Bernardino County Health Department
Admin Agency: Victorville Fire Department
Admin Agency 2:
On Scene:
Other on Scene:
Other Notified:
Header Unknown: MOJAVE DESERT AQMD
Site: Other
Description for Other :
Reported Cause:
R R Crssing < 50 Ft:
Description: Equipment failure caused this spill

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	3 of14	ENE	0.02 / 104.47	2,904.52 / -3	Kinder Morgan 13334 Air Express Way Victorville CA 92392	CHMIRS

Control No: 07-4551
Year: 2007
Notified Date:
Notified Date Time:
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/abd1b0858ed33eae8825732800523840?OpenDocument

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained: Yes
1 Substance: JP8, Jet Fuel
1 Measure: Gal(s)
1 Other:
1 Quantity: 20
1 Type: PETROLEUM
1 Pipeline:
1 Vessel >= 300 Tons:
2 Substance:
2 Quantity:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Vessel >= 300 Tons:
3 Substance:
3 Quantity:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Incident Date: 7/30/2007
Incident Time: 754
Spill Site: Merchant/Business
Injuries?:
No of Injuries: 0
Fatals?:
No of Fatals: 0
Evacs?:
No of Evacs: 0
Cleanup: Reporting Party
Site:
Cause:
Cause Other:
Dog No:
Water: No
Water Way:
City: Victorville
County: San Bernardino County
ZIP: 92392
Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: 13334 Air Express Way
Description: Caller states a sump overfilled resulting in release of substance. In addition, stain size appears to be 2 feet by 3 feet.

Spill Report View

Water:
Creation Date: 07/30/2007 07:58 AM
Document Title: SPILL Report
Spill Site: Merchant/Business
Type: PETROLEUM

Hazardous Materials Spill Report

Date :	07/30/2007	***Name:***	
Time:	0758	***Phone:***	
Incident Date:	07/30/2007	***Ext:***	
Incident Time:	0754	***Pag Cell:***	
Control Cal OES:	07-4551	***Prs Name:***	
Control NRC:		***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:		***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	
UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		
Contained:	Yes		
Waterway:			
Received By:			
Cleanup By:	Reporting Party		
Incident Location:	13334 Air Express Way		
Additional County:			
1 Substance:	JP8, Jet Fuel		
1 Qty:	<		
1 Amount :	20		
1 Measure:	Gal(s)		
1 Type:	PETROLEUM		
1 Other:			
1 Pipeline:	No		
1 Ves >= 300 Tons:	No		
2 Substance:			
2 Qty:	=		
2 Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:	No		
2 Ves >= 300 Tns:	No		
3 Substance:			
3 Qty:	=		
3 Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:	No		
3 Ves >= 300 Tons:	No		
Injuries:	No		
Fatality:	No		
Evacuation:	No		
Known Impact:			
Agency:	Kinder Morgan		
PRS Agency:			
Sec Agency:	San Bernardino County Health Department		
Admin Agency:	Victorville Fire Department		
Admin Agency 2:			
On Scene:			
Other on Scene:			
Other Notified:			
Header Unknown:	MOJAVE DESERT AQMD		
Site:	Merchant/Business		
Reported Cause:			
R R Crssing < 50 Ft:			
Description:	Caller states a sump overfilled resulting in release of substance. In addition, stain size appears to be 2 feet by 3 feet.		

Spill Report View

Water:		***Creation Date:***	07/30/2007 08:26 AM
Document Title:	Cal OES-Update		
Spill Site:			
Type:	PETROLEUM		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

OES Hazardous Materials Spill Update

Occurrence Date:	07/30/2007	***Prs Notif Upd Nm:***	
Occurrence Time:		***Phone No:***	
Notify Date:	07/30/2007	***Ext:***	
Notify Time:	0758	***Pag Cell:***	
NRC:	843835	***Fax Notific List 2:***	
RWQCB Unit:		***Admin Agency 2:***	
Unknown Header:		***Add Admin Agency 2:***	
OP Area:	San Bernardino County	***Secondary Agency 2:***	
RWQCB Unit 2:		***Dog Unit 2:***	
Add Counties 2:			
1 Substance:	JP8, Jet Fuel		
1 Qty Amount:	20		
1 Measure:	Gal(s)		
1 Type:	PETROLEUM		
1 Other:			
1 Pipeline:			
1 Ves >= 300 Tons:			
2 Substance:			
2 Qty Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:			
2 Ves >= 300 Tons:			
3 Substance:			
3 Qty Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:			
3 Ves >= 300 Tons:			
Pers Reporting Spill Agency:			
Pers Notifying CA OES Agency:	Kinder Morgan		
Fax Notifi List:	AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS		
Other Notified:			
Confirmation Request:			
Administering Agency:	Victorville Fire Department		
Secondary Agency:	San Bernardino County Health Department		
Additional Admin Agency:			
Additional Counties:			
Doc URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/a66410b982bd50e2882573280054d18c?OpenDocument		
Update Known Impact:			
Update Cause:			
Update Description:			

Situation Update:

07/30/07 0821 Hours; NRC Report # 843835 received. Per NRC Report, "caller is reporting a discharge of jet fuel onto the ground. The fuel discharged from sump on metered piping due to a valve failure. The sump was attached to a transmission line which is where the material originated from." Incident Type: Pipeline, above ground. Remedial Actions: "Material is contained and the soil will be excavated soil."

Original Description:

OES Hazardous Materials Update Quantities

Amount:	
Measure:	Gal(s)

10	*4 of14*	*ENE*	*0.02 / 104.47*	*2,904.52 / -3*	***Kinder Morgan*** ***13334 Air Express Way*** ***Victorville CA 92392***	***CHMIRS***

Control No: 07-0783
Year: 2007
Notified Date:
Notified Date Time:
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/5a4019ed3ec22a7788257279006db406?OpenDocument

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained: Yes
1 Substance: JP-8 Jet Fuel
1 Measure: Gal(s)
1 Other:
1 Quantity: 5
1 Type: PETROLEUM
1 Pipeline:
1 Vessel >= 300 Tons:
2 Substance:
2 Quantity:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Vessel >= 300 Tons:
3 Substance:
3 Quantity:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Incident Date: 2/5/2007
Incident Time: 1149
Spill Site: Industrial Plant
Injuries?:
No of Injuries: 0
Fatals?:
No of Fatals: 0
Evacs?:
No of Evacs: 0
Cleanup: Reporting Party
Site: No
Cause:
Cause Other:
Dog No:
Water: No
Water Way: No
City: Victorville
County: San Bernardino County
ZIP: 92392
Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: 13334 Air Express Way
Description: 02/05/07 at 1149 hours, a sump overfilled believed to be caused by a thermal relief valve which stuck open, spilling less than 5 gallons of JP-8 Jet Fuel on the ground. Kinder Morgan will clean up the spill.

Spill Report View

Water:
Document Title: Cal OES-Update
Spill Site:
Type: PETROLEUM
Creation Date: 02/05/2007 12:14 PM

OES Hazardous Materials Spill Update

Occurrence Date: 02/05/2007
Occurrence Time:
Notify Date: 02/05/2007
Notify Time: 1158
NRC:
RWQCB Unit:
Unknown Header:
OP Area: San Bernardino County
RWQCB Unit 2:
Add Counties 2:
1 Substance: JP-8 Jet Fuel
1 Qty Amount: 5
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline:
1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
Prs Notif Upd Nm:
Phone No:
Ext:
Pag Cell:
Fax Notific List 2:
Admin Agency 2:
Add Admin Agency 2:
Secondary Agency 2:
Dog Unit 2:

2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS
Other Notified:
Confirmation Request:
Administering Agency: Victorville Fire Department
Secondary Agency: San Bernardino County Health Department
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/408c3cbccfd0ea3e88257279006f3562?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

02/05/07 1211 hours, per Robert Brown, NRC Report number is: 825576

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

Spill Report View

Water:
Creation Date: 02/05/2007 11:58 AM
Document Title: SPILL Report
Spill Site: Industrial Plant
Type: PETROLEUM

Hazardous Materials Spill Report

Date : 02/05/2007
Time: 1158
Incident Date: 02/05/2007
Incident Time: 1149
Control Cal OES: 07-0783
Control NRC:
Water Involved: No
Drink Wtr Impact: No
Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 6B
Contained: Yes
Waterway: No
Received By:
Cleanup By: Reporting Party
Incident Location: 13334 Air Express Way
Additional County:
1 Substance: JP-8 Jet Fuel
1 Qty: <

Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:
Prs Ext:
Prs Pag Cell:
Incident Desc:
Notification Info:
Notification List:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

1 Amount :	5
1 Measure:	Gal(s)
1 Type:	PETROLEUM
1 Other:	
1 Pipeline:	No
1 Ves >= 300 Tons:	No
2 Substance:	
2 Qty:	=
2 Amount:	
2 Measure:	
2 Type:	
2 Other:	
2 Pipeline:	No
2 Ves >= 300 Tns:	No
3 Substance:	
3 Qty:	=
3 Amount:	
3 Measure:	
3 Type:	
3 Other:	
3 Pipeline:	No
3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	
Agency:	Kinder Morgan
PRS Agency:	
Sec Agency:	San Bernardino County Health Department
Admin Agency:	Victorville Fire Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	
Header Unknown:	MOJAVE DESERT AQMD
Site:	Industrial Plant
Reported Cause:	
R R Crssing < 50 Ft:	
Description:	02/05/07 at 1149 hours, a sump overfilled believed to be caused by a thermal relief valve which stuck open, spilling less than 5 gallons of JP-8 Jet Fuel on the ground. Kinder Morgan will clean up the spill.

10	5 of14	ENE	0.02 / 104.47	2,904.52 / -3	**Kinder Morgan** **13334 Air Express Way** **Victorville CA**	CHMIRS

Control No:	07-0338	**Notified Date:**	
Year:	2007	**Notified Date Time:**	
County:	San Bernardino County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/d2065755442da3f988257265006eadfb?OpenDocument		

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Yes	**3 Ves >= 300 Tons:**	
1 Substance:	JP 8	**Incident Date:**	1/16/2007
1 Measure:	Pt.(s)	**Incident Time:**	1200
1 Other:		**Spill Site:**	Other
1 Quantity:	1	**Injuries?:**	
1 Type:	PETROLEUM	**No of Injuries:**	0
1 Pipeline:		**Fatals?:**	
1 Vessel >= 300 Tons:		**No of Fatals:**	0
2 Substance:		**Evacs?:**	
2 Quantity:		**No of Evacs:**	0
2 Measure:		**Cleanup:**	Reporting Party
2 Type:		**Site:**	
2 Other:		**Cause:**	
2 Pipeline:		**Cause Other:**	

2 Vessel >= 300 Tons:
3 Substance:
3 Quantity:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
Dog No:
Water: No
Water Way:
City: Victorville
County: San Bernardino County
ZIP:
Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: 13334 Air Express Way
Description: The caller is reporting a 4 foot by 4 foot stain on floor.

Spill Report View

Water:
Creation Date: 01/16/2007 12:54 PM
Document Title: Cal OES-Update
Spill Site:
Type: PETROLEUM

OES Hazardous Materials Spill Update

Occurrence Date: 01/16/2007
Occurrence Time:
Notify Date: 01/16/2007
Notify Time: 1208
NRC: 823858
RWQCB Unit:
Unknown Header:
OP Area: San Bernardino County
RWQCB Unit 2:
Add Counties 2:
Prs Notif Upd Nm:
Phone No:
Ext:
Pag Cell:
Fax Notific List 2:
Admin Agency 2:
Add Admin Agency 2:
Secondary Agency 2:
Dog Unit 2:
1 Substance: JP 8
1 Qty Amount: 1
1 Measure: Pt.(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline:
1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS
Other Notified:
Confirmation Request:
Administering Agency: Victorville Fire Department
Secondary Agency: San Bernardino County Health Department
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/17379b002f90d93b882572650072d1d2?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

NRC 823858

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Pt.(s)

Spill Report View

Water:
Creation Date: 01/16/2007 12:08 PM
Document Title: SPILL Report
Spill Site: Other
Type: PETROLEUM

Hazardous Materials Spill Report

Date : 01/16/2007
Time: 1208
Incident Date: 01/16/2007
Incident Time: 1200
Control Cal OES: 07-0338
Control NRC:
Water Involved: No
Drink Wtr Impact: No
Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 6B
Contained: Yes
Waterway:
Received By:
Cleanup By: Reporting Party
Incident Location: 13334 Air Express Way
Additional County:
1 Substance: JP 8
1 Qty: =
1 Amount : 1
1 Measure: Pt.(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No
Fatality: No
Evacuation: No
Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:
Prs Ext:
Prs Pag Cell:
Incident Desc:
Notification Info:
Notification List:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Known Impact:
Agency: Kinder Morgan
PRS Agency:
Sec Agency: San Bernardino County Health Department
Admin Agency: Victorville Fire Department
Admin Agency 2:
On Scene:
Other on Scene:
Other Notified:
Header Unknown: MOJAVE DESERT AQMD
Site: Other
Description for Other :
Reported Cause:
R R Crssing < 50 Ft:
Description: The caller is reporting a 4 foot by 4 foot stain on floor.

10	6 of14	ENE	0.02 / 104.47	2,904.52 / -3	13334 AIR EXPRESS WAY VICTORVILLE CA	ERNS

NRC Report No: 884663
Type of Incident: FIXED
Incident Cause: UNKNOWN
Incident Date: 19-Sep-2008 11:35:00
Incident Location:
Incident Dtg: OCCURRED
Distance from City:
Distance Units:
Direction from City:
Location County: SAN BERNARDINO
Potential Flag: No
Year: Year 2008 Reports
Latitude Degrees:
Latitude Minutes:
Latitude Seconds:
Longitude Degrees:
Longitude Minutes:
Longitude Seconds:
Lat Quad:
Long Quad:
Location Section:
Location Township:
Location Range:
Description of Incident: THE CALLER IS REPORTING THE DISCHARGE OF OIL ONTO THE GROUND FROM AN UNKOWN SOURCE AT THE FACILITY DUE TO UNKNOWN CAUSES

Material Spill Information

Chris Code: JPE
CAS No: 000000-00-0
UN No:
Name of Material: JET FUEL: JP-8
Amount of Material: 0
Unit of Measure: UNKNOWN AMOUNT
If Reached Water: NO
Amount in Water:
Unit Reach Water:

Calls Information

Date Time Received: 20-Sep-2008 03:16:33
Date Time Complete: 20-Sep-2008 03:20:58
Call Type: INC
Resp Company: KINDER MORGAN ENERGY PARTNERS
Resp Org Type: PRIVATE ENTERPRISE
Responsible City: ORANGE
Responsible State: CA
Responsible Zip: 92868
Source: TELEPHONE

Incident Information

Tank ID:
Tank Regulated: U
Tank Regulated By:
Capacity of Tank:
Capacity Tank Units:
Description of Tank:
Actual Amount:
Actual Amount Units:
Tank Above Ground: ABOVE
NPDES:
NPDES Compliance: U
Init Contin Rel No:
Building ID:
Location Area ID:
Location Block ID:
OCSG No:
OCSP No:
State Lease No:
Pier Dock No:
Berth Slip No:
Brake Failure: U
Airbag Deployed: U
Transport Contain: U
Location Subdiv:

Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	U
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	U	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:	TANK FARM	**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:		**No of Conductor Tested:**	
Pipeline Abv Ground:	ABOVE	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	U	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	Y	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	U	**State Agen Report No:**	08-6850
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	OES
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	CLEAN UP WILL BEGIN IN THE MORNING	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	CLEAR
Radius of Evac:		**Air Temperature:**	
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	
No. Hospitalized:		**Wind Speed Unit:**	
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	
Waterway Close Time:		**Passengers Transfer:**	NO
Road Closed:	N	**Passenger Injuries:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Road Desc:		**Employee Injuries:**	
Road Closure Time:		**Occupant Fatality:**	
Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:	GROUND	**Additional Info:**	NONE

10	7 of14	ENE	0.02 / 104.47	2,904.52 / -3	13334 AIR EXPRESSWAY VICTORVILLE CA 92868	ERNS

NRC Report No:	825576	**Latitude Degrees:**	
Type of Incident:	FIXED	**Latitude Minutes:**	
Incident Cause:	EQUIPMENT FAILURE	**Latitude Seconds:**	
Incident Date:	05-Feb-2007 11:49:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	DISCOVERED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:	No	**Location Range:**	
Year:	Year 2007 Reports		

Description of Incident: THE CALLER IS REPORTING A RELEASE OF MATERIALS ONTO THE GROUND FROM A SUMP PUMP DUE TO EQUIPMENT FAILURE.

Material Spill Information

Chris Code:	JPE	**Unit of Measure:**	GALLON(S)
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	JET FUEL: JP-8	**Unit Reach Water:**	
Amount of Material:	5		

Calls Information

Date Time Received:	05-Feb-2007 15:06:10	**Responsible City:**	ORANGE
Date Time Complete:	05-Feb-2007 15:11:32	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92868
Resp Company:	KINDER MORGAN ENERGY PARTNERS	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		**Building ID:**	
Tank Regulated:	U	**Location Area ID:**	
Tank Regulated By:		**Location Block ID:**	
Capacity of Tank:		**OCSG No:**	
Capacity Tank Units:		**OCSP No:**	
Description of Tank:		**State Lease No:**	
Actual Amount:		**Pier Dock No:**	
Actual Amount Units:		**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	U
NPDES:		**Airbag Deployed:**	U
NPDES Compliance:	U	**Transport Contain:**	U
Init Contin Rel No:		**Location Subdiv:**	
Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	

Aircraft ID:		**Allision:**	U
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	N	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:	OTHER	**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:		**No of Conductor Tested:**	
Pipeline Abv Ground:	ABOVE	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	U	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	Y	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	Y	**State Agen Report No:**	07-0783
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	OES
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	CLEAN UP UNDERWAY	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	OVERCAST
Radius of Evac:		**Air Temperature:**	75
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	
No. Hospitalized:		**Wind Speed Unit:**	
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	N
Waterway Close Time:		**Passengers Transfer:**	NO
Road Closed:	N	**Passenger Injuries:**	
Road Desc:		**Employee Injuries:**	
Road Closure Time:		**Occupant Fatality:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:		**Additional Info:**	THE CALLER HAD NO ADDITIONAL INFORMATION

10	8 of14	ENE	0.02 / 104.47	2,904.52 / -3	13334 AIR EXPRESSWAY VICTORVILLE CA	ERNS

NRC Report No:	823858	**Latitude Degrees:**	
Type of Incident:	STORAGE TANK	**Latitude Minutes:**	
Incident Cause:	UNKNOWN	**Latitude Seconds:**	
Incident Date:	16-Jan-2007 12:00:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	OCCURRED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:	No	**Location Range:**	
Year:	Year 2007 Reports		

Description of Incident: THE CALLER STATES THAT JET FUEL WAS DISCHARGED DUE TO UNKNOWN CAUSES FROM A STORAGE TANK.

Material Spill Information

Chris Code:	JPE	**Unit of Measure:**	UNKNOWN AMOUNT
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	JET FUEL: JP-8	**Unit Reach Water:**	
Amount of Material:	0		

Calls Information

Date Time Received:	16-Jan-2007 15:15:16	**Responsible City:**	ORANGE
Date Time Complete:	16-Jan-2007 15:21:29	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92868
Resp Company:	KINDER MORGAN ENERGY PARTNERS	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:	TANK 210	**Building ID:**	
Tank Regulated:	Y	**Location Area ID:**	
Tank Regulated By:	DOT	**Location Block ID:**	
Capacity of Tank:	20000	**OCSG No:**	
Capacity Tank Units:	BARREL(S)	**OCSP No:**	
Description of Tank:	STEEL JET FUEL STORAGE TANK	**State Lease No:**	
Actual Amount:	17020	**Pier Dock No:**	
Actual Amount Units:	BARREL(S)	**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	U
NPDES:		**Airbag Deployed:**	U
NPDES Compliance:	U	**Transport Contain:**	N
Init Contin Rel No:		**Location Subdiv:**	
Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	U

Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:		***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	U	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:		***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:		***No of Conductor Tested:***	
Pipeline Abv Ground:	ABOVE	***No of Engineer Tested:***	
Pipeline Covered:	U	***No of Trainman Tested:***	
Exposed Underwater:	N	***No of Yard Foreman Tested:***	
Railroad Hotline:		***No of RCL Operator Tested:***	
Railroad Milepost:		***No of Brakeman Tested:***	
Grade Crossing:	U	***No of Train Dispat Tested:***	
Crossing Device Ty:		***No of Signalman Tested:***	
Ty Vehicle Involved:		***No of Other Emp Tested:***	
Device Operational:	Y	***No of Unknown Emp Tested:***	

Incident Details Information

Release Secured:	Y	***State Agen Report No:***	07-0338
Release Rate:		***State Agen on Scene:***	NONE
Release Rate Unit:		***State Agen Notified:***	CAOES
Release Rate Rate:		***Fed Agency Notified:***	NONE
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	MATERIAL WILL BE PICKED UP AND DISPOSED OF	***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	CLEAR
Radius of Evac:		***Air Temperature:***	39
Any Injuries:	N	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	N	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	N
Waterway Close Time:		***Passengers Transfer:***	NO
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:	CONCRETE PAD UNDER TANK, SAND AND CLAY SURROUNDING PAD	**Additional Info:**	THE CALLER WILL NOTIFY THE CITY AND COUNTY CUPA AND THE BUREAU OF RECLAMATION.

10	9 of14	ENE	0.02 / 104.47	2,904.52 / -3	13334 AIR EXPRESS WAY VICTORVILLE CA	ERNS

NRC Report No:	795717	**Latitude Degrees:**	
Type of Incident:	STORAGE TANK	**Latitude Minutes:**	
Incident Cause:	OTHER	**Latitude Seconds:**	
Incident Date:	01-May-2006 09:12:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	DISCOVERED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:		**Location Range:**	
Year:	Year 2006 Reports		

Description of Incident: THE CALLER STATED AS HE WENT TO THE GEORGIA TERMINAL FACILITY TO OPEN A JP-8 FUEL VALVE. THE VALVE WAS CLOSED BUT THERE WAS A DISCHARGE OF THE PRODUCT ON THE GROUND. THERE WAS ANOTHER TANK VALVE OPEN WHICH COULD BE THE SOURCE OF THE DISCHARGE BECAUSE AS SOON AS IT WAS CLOSED THE RELEASE STOPPED.

Material Spill Information

Chris Code:	OTH	**Unit of Measure:**	UNKNOWN AMOUNT
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	JP-8	**Unit Reach Water:**	
Amount of Material:	0		

Calls Information

Date Time Received:	01-May-2006 12:20:08	**Responsible City:**	ORANGE
Date Time Complete:	01-May-2006 12:35:38	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92868
Resp Company:	KINDER MORGAN ENERGY	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		**Building ID:**	
Tank Regulated:	U	**Location Area ID:**	
Tank Regulated By:		**Location Block ID:**	
Capacity of Tank:		**OCSG No:**	
Capacity Tank Units:		**OCSP No:**	
Description of Tank:		**State Lease No:**	
Actual Amount:		**Pier Dock No:**	
Actual Amount Units:		**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	N
NPDES:		**Airbag Deployed:**	
NPDES Compliance:	U	**Transport Contain:**	U
Init Contin Rel No:		**Location Subdiv:**	

Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	N
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	U	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:	OTHER	**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:		**No of Conductor Tested:**	
Pipeline Abv Ground:	ABOVE	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	N	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	Y	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	Y	**State Agen Report No:**	06-2599
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	OES
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	THE CALLER STATED THE TANK VALVE BELIEVED TO BE THE SOURCE HAS BEEN SECURED.	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	CLEAR
Radius of Evac:		**Air Temperature:**	75
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	
No. Hospitalized:		**Wind Speed Unit:**	
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waterway Close Time:		**Passengers Transfer:**	UNK
Road Closed:	N	**Passenger Injuries:**	
Road Desc:		**Employee Injuries:**	
Road Closure Time:		**Occupant Fatality:**	
Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:		**Additional Info:**	NONE

---

10 | ***10 of14*** | ***ENE*** | ***0.02 / 104.47*** | ***2,904.52 / -3*** | ***1334 AIR EXPRESS WAY VICTORYVILLE CA 92392*** | ***ERNS***

NRC Report No:	843835	**Latitude Degrees:**	
Type of Incident:	PIPELINE	**Latitude Minutes:**	
Incident Cause:	EQUIPMENT FAILURE	**Latitude Seconds:**	
Incident Date:	30-Jul-2007 07:54:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	OCCURRED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:	No	**Location Range:**	
Year:	Year 2007 Reports		

Description of Incident: CALLER IS REPORTING A DISCHARGE OF JET FUEL ONTO THE GROUND. THE FUEL DISCHARGED FROM SUMP ON METERED PIPING DUE TO A VALVE FAILURE. THE SUMP WAS ATTACHED TO A TRANSMISSION LINE WHICH IS WHERE THE MATERIAL ORIGINATED FROM.

Material Spill Information

Chris Code:	OTH	**Unit of Measure:**	GALLON(S)
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	OTHER OIL (JP-8 JET FUEL)	**Unit Reach Water:**	
Amount of Material:	20		

Calls Information

Date Time Received:	30-Jul-2007 11:08:37	**Responsible City:**	ORANGE
Date Time Complete:	30-Jul-2007 11:26:25	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92868
Resp Company:	KINDER MORGAN ENERGY PARTNERS	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		**Building ID:**	
Tank Regulated:	U	**Location Area ID:**	
Tank Regulated By:		**Location Block ID:**	
Capacity of Tank:		**OCSG No:**	
Capacity Tank Units:		**OCSP No:**	
Description of Tank:		**State Lease No:**	
Actual Amount:		**Pier Dock No:**	
Actual Amount Units:		**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	U
NPDES:		**Airbag Deployed:**	U
NPDES Compliance:	U	**Transport Contain:**	U

Init Contin Rel No:		**Location Subdiv:**	
Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	U
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	U	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:		**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:	TRANSMISSION	**No of Conductor Tested:**	
Pipeline Abv Ground:	ABOVE	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	U	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	Y	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	Y	**State Agen Report No:**	07-4551
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	CA OES
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	MATERIAL IS CONTAINED AND THE SOIL WILL BE EXCAVATED	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	SUNNY
Radius of Evac:		**Air Temperature:**	80
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	
No. Hospitalized:		**Wind Speed Unit:**	
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waterway Close Time:		**Passengers Transfer:**	NO
Road Closed:	N	**Passenger Injuries:**	
Road Desc:		**Employee Injuries:**	
Road Closure Time:		**Occupant Fatality:**	
Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:		**Additional Info:**	CALLER HAD NO ADDITIONAL INFORMATION.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	11 of14	ENE	0.02 / 104.47	2,904.52 / -3	13334 AIR EXPRESS WAY VICTORVILLE CA	ERNS

NRC Report No:	834574	**Latitude Degrees:**	
Type of Incident:	PIPELINE	**Latitude Minutes:**	
Incident Cause:	EQUIPMENT FAILURE	**Latitude Seconds:**	
Incident Date:	07-May-2007 09:53:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	DISCOVERED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:	No	**Location Range:**	
Year:	Year 2007 Reports		

Description of Incident: CALLER IS REPORTING A RELEASE OF CHEMICALS ONTO THE GROUND. THE CAUSE OF THE RELEASE WAS DUE TO A SEAL FAILURE ON A DIRTY FILTERING SYSTEM.

Material Spill Information

Chris Code:	JPE	**Unit of Measure:**	UNKNOWN AMOUNT
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	JET FUEL: JP-8	**Unit Reach Water:**	
Amount of Material:	0		

Calls Information

Date Time Received:	07-May-2007 13:03:39	**Responsible City:**	BAGGETT
Date Time Complete:	07-May-2007 13:18:50	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92327
Resp Company:	KINDER MORGAN	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE CITIZEN		

Incident Information

Tank ID:		**Building ID:**	
Tank Regulated:	U	**Location Area ID:**	
Tank Regulated By:		**Location Block ID:**	
Capacity of Tank:		**OCSG No:**	
Capacity Tank Units:		**OCSP No:**	
Description of Tank:		**State Lease No:**	
Actual Amount:		**Pier Dock No:**	
Actual Amount Units:		**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	U
NPDES:		**Airbag Deployed:**	U
NPDES Compliance:	U	**Transport Contain:**	U

Init Contin Rel No:		**Location Subdiv:**	
Contin Rel Permit:		**Platform Rig Name:**	
Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	U
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	U	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:		**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:	DISTRIBUTION	**No of Conductor Tested:**	
Pipeline Abv Ground:	BELOW	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	U	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	Y	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	Y	**State Agen Report No:**	07-2762
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	CA OEC
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	DIGGING UP THE AFFECTED AREA.	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	CLEAR
Radius of Evac:		**Air Temperature:**	82
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	5
No. Hospitalized:		**Wind Speed Unit:**	MPH
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	
Waterway Close Time:		**Passengers Transfer:**	NO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Road Closed:	N	**Passenger Injuries:**	
Road Desc:		**Employee Injuries:**	
Road Closure Time:		**Occupant Fatality:**	
Road Closure Units:		**Sheen Size:**	
Closure Direction:		**Sheen Size Units:**	
Major Artery:	No	**Sheen Size Length:**	
Track Closed:	N	**Sheen Size Length U:**	
Track Desc:		**Sheen Size Width:**	
Track Closure Time:		**Sheen Size Width U:**	
Track Closure Units:		**Sheen Color:**	
Track Close Dir:		**Dir of Sheen Travel:**	
Media Interest:	NONE	**Sheen Odor Desc:**	
Medium Desc:	LAND	**Duration Unit:**	
Addl Medium Info:		**Additional Info:**	CALLER HAD NO ADDITIONAL INFORMATION.

---

10 | **12 of14** | **ENE** | **0.02 / 104.47** | **2,904.52 / -3** | **13334 AIR EXPRESSWAY ROAD VICTORVILLE CA 92394** | **ERNS**

NRC Report No:	905367	**Latitude Degrees:**	
Type of Incident:	FIXED	**Latitude Minutes:**	
Incident Cause:	EQUIPMENT FAILURE	**Latitude Seconds:**	
Incident Date:	12-May-2009 08:04:00	**Longitude Degrees:**	
Incident Location:		**Longitude Minutes:**	
Incident Dtg:	OCCURRED	**Longitude Seconds:**	
Distance from City:		**Lat Quad:**	
Distance Units:		**Long Quad:**	
Direction from City:		**Location Section:**	
Location County:	SAN BERNARDINO	**Location Township:**	
Potential Flag:	No	**Location Range:**	
Year:	Year 2009 Reports		

Description of Incident: CALLER IS REPORTING A SPILL OF TRAMSMIX MATERIAL DUE TO A SEAL LEAK ON THEIR PUMP.

Material Spill Information

Chris Code:	NCC	**Unit of Measure:**	GALLON(S)
CAS No:	000000-00-0	**If Reached Water:**	NO
UN No:		**Amount in Water:**	
Name of Material:	TRAMSMIX	**Unit Reach Water:**	
Amount of Material:	3		

Calls Information

Date Time Received:	12-May-2009 11:15:51	**Responsible City:**	VICTORVILLE
Date Time Complete:	12-May-2009 11:24:17	**Responsible State:**	CA
Call Type:	INC	**Responsible Zip:**	92394
Resp Company:	KINDER MORGAN PIPELINE	**Source:**	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		**Building ID:**	STORAGE
Tank Regulated:	U	**Location Area ID:**	
Tank Regulated By:		**Location Block ID:**	
Capacity of Tank:		**OCSG No:**	
Capacity Tank Units:		**OCSP No:**	
Description of Tank:		**State Lease No:**	
Actual Amount:		**Pier Dock No:**	
Actual Amount Units:		**Berth Slip No:**	
Tank Above Ground:	ABOVE	**Brake Failure:**	U
NPDES:		**Airbag Deployed:**	U
NPDES Compliance:	U	**Transport Contain:**	U
Init Contin Rel No:		**Location Subdiv:**	
Contin Rel Permit:		**Platform Rig Name:**	

Contin Release Type:		**Platform Letter:**	
Aircraft ID:		**Allision:**	U
Aircraft Runway No:		**Type of Structure:**	
Aircraft Spot No:		**Structure Name:**	
Aircraft Type:		**Structure Oper:**	U
Aircraft Model:		**Transit Bus Flag:**	
Aircraft Fuel Cap:		**Date Time Norm Serv:**	
Aircraft Fuel Cap U:		**Serv Disrupt Time:**	
Aircraft Fuel on Brd:		**Serv Disrupt Units:**	
Aircraft Fuel OB U:		**CR Begin Date:**	
Aircraft Hanger:		**CR End Date:**	
Road Mile Marker:		**CR Change Date:**	
Power Gen Facility:	N	**FBI Contact:**	
Generating Capacity:		**FBI Contact Dt Tm:**	
Type of Fixed Obj:	OTHER	**Passenger Handling:**	
Type of Fuel:		**Passenger Route:**	XXX
DOT Crossing No:		**Passenger Delay:**	XXX
DOT Regulated:	U	**Sub Part C Test Req:**	XXX
Pipeline Type:		**No of Conductor Tested:**	
Pipeline Abv Ground:	ABOVE	**No of Engineer Tested:**	
Pipeline Covered:	U	**No of Trainman Tested:**	
Exposed Underwater:	N	**No of Yard Foreman Tested:**	
Railroad Hotline:		**No of RCL Operator Tested:**	
Railroad Milepost:		**No of Brakeman Tested:**	
Grade Crossing:	U	**No of Train Dispat Tested:**	
Crossing Device Ty:		**No of Signalman Tested:**	
Ty Vehicle Involved:		**No of Other Emp Tested:**	
Device Operational:	U	**No of Unknown Emp Tested:**	

Incident Details Information

Release Secured:	Y	**State Agen Report No:**	NONE
Release Rate:		**State Agen on Scene:**	NONE
Release Rate Unit:		**State Agen Notified:**	CA OES
Release Rate Rate:		**Fed Agency Notified:**	NONE
Est Duration of Rel:		**Oth Agency Notified:**	
Desc Remedial Act:	MATERIAL CONTAINED, CLEAN UP UNDERWAY	**Body of Water:**	
Fire Involved:	N	**Tributary of:**	
Fire Extinguished:	U	**Near River Mile Make:**	
Any Evacuations:	N	**Near River Mile Mark:**	
No Evacuated:		**Offshore:**	N
Who Evacuated:		**Weather Conditions:**	CLEAR
Radius of Evac:		**Air Temperature:**	80
Any Injuries:	N	**Wind Direction:**	
No. Injured:		**Wind Speed:**	
No. Hospitalized:		**Wind Speed Unit:**	
No. Fatalities:		**Water Supp Contam:**	U
Any Fatalities:	N	**Water Temperature:**	
Any Damages:	N	**Wave Condition:**	
Damage Amount:		**Current Speed:**	
Air Corridor Closed:	N	**Current Direction:**	
Air Corridor Desc:		**Current Speed Unit:**	
Air Closure Time:		**EMPL Fatality:**	
Waterway Closed:	N	**Pass Fatality:**	
Waterway Desc:		**Community Impact:**	
Waterway Close Time:		**Passengers Transfer:**	NO
Road Closed:	N	**Passenger Injuries:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Road Desc:			**Employee Injuries:**		
Road Closure Time:			**Occupant Fatality:**		
Road Closure Units:			**Sheen Size:**		
Closure Direction:			**Sheen Size Units:**		
Major Artery:	No		**Sheen Size Length:**		
Track Closed:	N		**Sheen Size Length U:**		
Track Desc:			**Sheen Size Width:**		
Track Closure Time:			**Sheen Size Width U:**		
Track Closure Units:			**Sheen Color:**		
Track Close Dir:			**Dir of Sheen Travel:**		
Media Interest:	NONE		**Sheen Odor Desc:**		
Medium Desc:	SOIL		**Duration Unit:**		
Addl Medium Info:	DIRT		**Additional Info:**	CALLER HAS NO ADDITIONAL INFORMATION.	

10	13 of14	ENE	0.02 / 104.47	2,904.52 / -3	**CALNEV TERMINAL GEORGE AFB** **JET FUEL SPILL** **13334 AIR EXPRESSWAY BLVD.** **VICTORVILLE CA 92394**	FINDS/FRS

Registry ID:	110066125767
FIPS Code:	
HUC Code:	18090208
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	14-OCT-15
Update Date:	
Interest Types:	STATE MASTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	CALEPA
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	25
Census Block Code:	060719802001141
EPA Region Code:	09
County Name:	SAN BERNARDINO COUNT
US/Mexico Border Ind:	
Latitude:	34.573016
Longitude:	-117.37235
Reference Point:	
Coord Collection Method:	UNKNOWN
Accuracy Value:	
Datum:	NAD83
Source:	
Frs Facility Detail Report URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066125767
Program Acronyms:	

CA-ENVIROVIEW:222382

10	14 of14	ENE	0.02 / 104.47	2,904.52 / -3	**KINDER MORGAN** **13334 AIR EXPRESS WAY** **VICTORVILLE CA 92392**	HAZNET

EPA ID:	CAC002603245	**Mailing City:**	VICTORVILLE
NAICS Code:		**Mailing State:**	CA
SIC Code:		**Mailing Zip:**	92392
Create Date:	5/2/2006	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	KINDER MORGAN
Inact Date:	10/30/2006	**Owner Addr 1:**	13334 AIR EXPRESS WAY
County:	36	**Owner Addr 2:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name:	San Bernardino	**Owner City:**	VICTORVILLE
County:		**Owner State:**	CA
Mail Name:		**Owner Zip:**	92392
Mailing Addr 1:	13334 AIR EXPRESS WAY	**Owner Phone:**	7602542616
Mailing Addr 2:		**Owner Fax:**	

11	1 of1	W	0.04 / 189.66	2,901.94 / -5	**Frontier California Inc.: Adelanto CO** **17640 Adelanto Rd** **Adelanto CA 92301**	UST

Facility ID:	FA0007064	**CERS ID:**	10046209
Site Facility Type:	PERMITTED UNDERGROUND STORAGE TANK (UST)		
Note:	Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search		

Permitted UST Tank Details

EPA Region:	9	**Tank Closure Date:**	
No. of Closed UST:	0	**Tank Configuration:**	Stand Alone Tank
No. of Inuse UST:		**Tank Contents:**	Diesel
No. of Oos UST:	0	**Tank Cp Impr Curr:**	No
Owner Type:	Non-Government	**Tank Cp Shutoff:**	No
Tank ID No.:	1	**Tank Installatn Dt:**	10/16/2000 12:00:00 AM
Tank Status:	Confirmed/Updated Information	**Tank No of Compart:**	1
Tank Type:	Double Wall	**Tank Pc Constructn:**	Steel
Tank Alarms:	Yes	**Tank Spill Bucket:**	Yes
Tank Ball Float:	No	**Tribal Lands:**	No
Tank Operator Name:	Frontier California Inc.		
Tank Operator Mail Address:	280 South Locust Street		
Tank Operator Mail City:	Pomona		
Tank Operator Mail State:	CA		
Tank Operator Mail Zip:	91766		
Tank Owner Name:	Frontier California Inc.		
Tank Owner Mailing Address:	280 South Locust Street		
Tank Owner Mailing City:	Pomona		
Tank Owner Mailing State:	CA		
Tank Owner Mailing Zip:	91766		
Tank Capacity Gallons:	5000		
Tank Piping Construction:	Double Walled		
Tank Piping Type:	Conventional Suction		
Tank Pw Piping Construction:	Flexible		
Tank Sacrificial Anode:	No		

Permitted UST Site Details

CERS ID:	10046209	**CalEnviroScrn 4 Pct:**	75-80%
Facility ID:	FA0007064	**Latitude:**	34.571033
Permitting Agency:	San Bernardino County Fire Department	**Longitude:**	-117.400846
Senate District:	23	**County:**	San Bernardino
Congress District:	23		

12	1 of2	NE	0.05 / 246.61	2,900.45 / -7	**George Air Force Base - DP001 OU3 Paint Drum Burial** **18374 Phantom West St** **Victorville CA 92394-1504**	CLEANUP SITES

Global ID:	DOD100226200	**Site Facility Type:**	MILITARY CLEANUP SITE
Site Fac Type (SRCH):		**Case Type (DL):**	Military Cleanup Site
Status (SRCH):		**RWQCB Region (DL):**	LAHONTAN RWQCB (REGION 6V)
Status (DL):	Completed - Case Closed	**Census Tract (SRCH):**	
Status Date (DL):	11/1/1998	**Latitude (DL):**	34.5728040443332
Cleanup Status:	COMPLETED - CASE CLOSED AS OF 11/1/1998	**Longitude (DL):**	-117.377457618713
Site Facility Name (SRCH):			

Address (SRCH):	
City (SRCH):	
Zip (SRCH):	
County (SRCH):	
Street No (DL):	18374
Street Name (DL):	Phantom West St
City (DL):	Victorville
Zip (DL):	92394-1504
County (DL):	San Bernardino
State (DL):	CA
Site Facility Name :	DP001 OU3 PAINT DRUM BURIAL
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	92394-1504
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 75
Local Case No:	400071 -- 75
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	1998-11-01 00:00:00
Potential Media of Concern:	Soil
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	
Coordinate Source:	Google Geocode
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NULL
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

Selected for No Further Action in final Operable Unit three Record of Decision.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	1998-11-01 00:00:00

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100226200
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/1/1998
Potential COC: NONE SPECIFIED
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 75
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 75
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100226200&tabname=regulatoryhistory
Site History:

Selected for No Further Action in final Operable Unit three Record of Decision.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226200&doc_id=5666578
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226200&doc_id=6288158
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226200&doc_id=6280546
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226200&doc_id=6277730

Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&enforcement_id=6090762&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226200&doc_id=6226146
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&enforcement_id=6104599&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100226200&enforcement_id=6090762

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&document_id=6288158

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&document_id=6277730

Document Type: Site Documents ***Document Date:*** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&enforcement_id=6090762

Document Type: Site Documents ***Document Date:*** 11/29/1998
Type: RECORD OF DECISION ***Submitted:***
Submitted By: (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&document_id=5666578

Document Type: Site Documents
Document Date: 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE
Submitted:
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&document_id=6226146

Document Type: Site Documents
Document Date: 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER
Submitted:
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&enforcement_id=6104599

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&document_id=6280546

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 11/1/1998

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	2 of2	NE	0.05 / 246.61	2,900.45 / -7	George Air Force Base - DP001 OU3 Paint Drum Burial 18374 Phantom West St Victorville CA 92394-1504	DEED

Global ID: DOD100226200
Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 11/1/1998
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100226200
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.377457618713
Latitude: 34.5728040443332

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226200&enforcement_id=6090762&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100226200&enforcement_id=6090762

---

13 | **1 of1** | **WNW** | **0.06 / 299.93** | **2,901.24 / -6** | **17664 1/2 ADELANO ROAD ADELANTO CA 92301** | **CDL**

Clue: 1996-01-078
Date: 1/29/1996
County: SAN BERNARDINO
Lab Type: L
Lab Type Desc: Illegal Drug Lab - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

---

14 | **1 of1** | **WNW** | **0.06 / 309.22** | **2,901.55 / -6** | **AAA TIRE SHOP 17664 ADELANTO RD #B ADELANTO CA 92301** | **RCRA NON GEN**

Handler ID: CAL000470969
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	811111
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20220526	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.571288
In Handler Univ:	N	**Location Longitude:**	-117.40071
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		

Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20220602
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	AAA TIRE SHOP
Location Street No:	
Location Street1:	17664 ADELANTO RD #B
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	SERGIO MENDOZA LOPEZ
Contact Street No:	
Contact Street1:	21159 PINE RIDGE AVE
Contact Street2:	
Contact City:	APPLE VALLEY
Contact State:	CA
Contact Zip:	92307
Contact Country:	
Contact Phone & Ext:	760-912-8940
Contact Fax:	760-596-4527
Contact Email Address:	AAATIRESHOP1@GMAIL.COM
Contact Title:	
Owner Name:	AAA TIRE SHOP LLC
Owner Type:	O
Owner Seq:	1
Operator Name:	SERGIO MENDOZA LOPEZ
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20220526
Handler Name: AAA TIRE SHOP
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: AAA TIRE SHOP LLC
Dt Became Current:
Dt Ended Current:
Phone: 442-249-1940
Source Type: Implementer
Street No:
Street1: 17664 ADELANTO RD #B
Street2:
City: ADELANTO
State: CA
Country:
Zip: 92301

Owner/Operator Ind: Current Operator
Type: Other
Name: SERGIO MENDOZA LOPEZ
Dt Became Current:
Dt Ended Current:
Phone: 760-912-8940
Source Type: Implementer
Street No:
Street1: 21159 PINE RIDGE AVE
Street2:
City: APPLE VALLEY
State: CA
Country:
Zip: 92307

15	1 of4	W	0.09 / 470.63	2,914.76 / 8	***CENTURYLINK - ADELANTO - ADLNCABC*** ***17437 ADELANTO RD*** ***ADELANTO CA 92301***	***CERS HAZ***

Latitude: 34.566698
Longitude: -117.400616

Regulated Programs

EI ID: 10482136
EI Description: Chemical Storage Facilities

Evaluations

Eval Date: 02/25/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 04/09/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 05/24/2024

Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 12/09/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

INSPECTION - BP FA0016055; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: CenturyLink
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: Holly Ebright
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO Box 1330
City: Camarillo
State: CA
Country:
Zip Code: 93011
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Holly Ebright
Entity Title:
Address: PO Box 1330
City: Camarillo
State: CA
Country:
Zip Code: 93011
Phone:

Affil Type Desc: CUPA District
Entity Name: San Bernardino County Fire
Entity Title:
Address: 598 South Tippecanoe Avenue, First Floor
City: San Bernardino

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State: CA
Country:
Zip Code: 92415-0153
Phone: (909) 386-8401

Affil Type Desc: Operator
Entity Name: CenturyLink Communications
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (805) 233-1973

Affil Type Desc: Identification Signer
Entity Name: Holly Ebright
Entity Title: Regional EHS Manager III
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: CenturyLink Communications
Entity Title:
Address: 100 CenturyLink Drive
City: Monroe
State: LA
Country: United States
Zip Code: 71203
Phone: (800) 244-1111

Coordinates

Env Int Type Code: HMBP
Program ID: 10482136
Latitude: 34.566700
Longitude: -117.400620
Coord Name:
Ref Point Type Desc: Center of a facility or station.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	2 of4	W	0.09 / 470.63	2,914.76 / 8	GST TELECOM CALIFORNIA - ADELANTO RD. 17437 ADELANTO ROAD ADELANTO CA 92301	EMISSIONS

Source:

2003 Criteria Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: .0068347
ROGT: .01
COT: .0151008
NOXT: .0700988
SOXT: .0008236
PMT: .0049276
PM10T: 0

2003 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2007 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2008 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2009 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2010 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2011 Toxic Data

Facility ID: 107402189
Facility SIC Code: 4813
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2012 Toxic Data

Facility ID:	107402189	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2013 Toxic Data

Facility ID:	107402189	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	3 of4	W	0.09 / 470.63	2,914.76 / 8	TW TELECOM - ADELANTO RD 17437 ADELANTO ROAD ADELANTO CA 92301	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2017 Criteria Data

Facility ID:	132902189	**CERR Code:**	
Facility SIC Code:	9999	**TOGT:**	.000206498
CO:	36	**ROGT:**	.000181408493
Air Basin:	MD	**COT:**	.000495595
District:	MOJ	**NOXT:**	.002684471
COID:	SBD	**SOXT:**	.00000165
DISN:	MOJAVE DESERT AQMD	**PMT:**	. 00008309859154929577464788732394366197183099
CHAPIS:		**PM10T:**	.0000826

2017 Toxic Data

Facility ID:	132902189	**COID:**	SBD
Facility SIC Code:	9999	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	.1		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	2189	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	.000206498

CO:	36	**ROGT:**	.000181408493
Air Basin:	MD	**COT:**	.000495595
District:	MOJ	**NOXT:**	.002684471
COID:	SBD	**SOXT:**	.00000165
DISN:	MOJAVE DESERT AQMD	**PMT:**	.00008309859154929577464788732394366197183099
CHAPIS:		**PM10T:**	.0000826

2018 Toxic Data

Facility ID:	2189	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	.1		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	2189	**ROGT:**	.0000219625
District:	MOJ	**COT:**	.00006
Facility SIC Code:	4813	**NOXT:**	.000324732
CO ID:	SBD	**SOXT:**	.0000002
DISN:	MOJAVE DESERT AQMD		
PM10T:	.00000999		
TOGT:	.000025		
PMT:	.000010050301810865191146881287726358148893336		

2019 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Faccility ID:	2189	**CERR Code:**	
District:	MOJ	**TS:**	.01
Facility SIC Code:	4813	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	2189	**ROGT:**	.0000219625
District:	MOJ	**COT:**	.00006
Facility SIC Code:	4813	**NOXT:**	.000324732
CO ID:	SBD	**SOXT:**	.0000002
DISN:	MOJAVE DESERT AQMD		
TOGT:	.000025		
PMT:	.000010050301810865191146881287726358148893336		
PM10T:	.00000999		

2020 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	2189	**CHERR Code:**	

District:	MOJ	**TS:**	.01
Facility SIC Code:	4813	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Toxic Data

Co:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	2189	**Cerr Code:**	
District:	MOJ	**TS:**	.01
Facility SIC Code:	4813	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	**CHAPIS:**	
Air Basin:	MD	**Cerr Code:**	
Facility ID:	2189	**ROGT:**	.0000219625
District:	MOJ	**COT:**	.00006
Facility SIC Code:	4813	**NOXT:**	.000324732
CO ID:	SBD	**SOXT:**	.0000002
DISN:	MOJAVE DESERT AQMD		
TOGT:	.000025		
PMT:	.000010050301810865191146881287726358148893336		
PM10T:	.00000999		

2023 Pollutant Data

Facility ID:	2189	**CO:**	36
Facility SIC Code:	4813	**CO ID:**	SBD
CERR Code:		**Air Basin:**	MD
CHAPIS:		**District:**	MOJ
ROGT:	.001113777688	**NOXT:**	.016464761
COT:	.003039647	**SOXT:**	.000010132144
DISN:	MOJAVE DESERT AQMD		
TOGT:	.00126652		
PMT:	.000509665995975855130784708249496981891348		
PM10T:	.000506608		
Source:	2023 Pollutant Data		

2022 Criteria Data

Facility ID:	2189	**District:**	MOJ
Facility SIC Code:	4813	**Air Basin:**	MD
Cerr Code:		**Co:**	36
CHAPIS:		**CO ID:**	SBD
ROGT:	.00111263782	**NOXT:**	.016464761
COT:	.003039647	**SOXT:**	.00001013
DISN:	MOJAVE DESERT AQMD		
TOGT:	.00126652		
PMT:	.000509665995975855130784708249496981891348		
PM10T:	.000506608		
Source:	2022 Criteria Data		

2022 Toxic Data

Facility ID:	2189	**CO:**	36
Facility SIC Code:	4813	**Air Basin:**	MD
CHERR Code:		**District:**	MOJ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CHAPIS: ***COID:*** SBD
Health Risk Asmt: ***TS:*** .36
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data

2023 Toxic Data

Facility ID: 2189 ***CO:*** 36
Facility SIC Code: 4813 ***COID:*** SBD
CHERR Code: ***Air Basin:*** MD
CHAPIS: ***District:*** MOJ
TS: .36
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data

---

15 | ***4 of4*** | ***W*** | ***0.09 / 470.63*** | ***2,914.76 / 8*** | ***CENTURYLINK - ADELANTO - ADLNCABC***
17437 Adelanto Rd
Adelanto CA 92301 | ***SANBERN CUPA***

Facility ID: FA0016055
Owner Info: CENTURYLINK COMMUNICATIONS
Mailing Care of: HOLLY.EBRIGHT@LUMEN.COM
Mailing Address 2:
Mailing City: CAMARILLO
Mailing State: CA
Mailing Zip: 93011

Detail(s)

Permit ID: PT0034760
Status: ACTIVE
Program Element Code: 4241
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
To: 5/31/2025
Mailing Address 1: PO BOX 1330

---

16 | ***1 of1*** | ***W*** | ***0.10 / 517.01*** | ***2,916.47 / 9*** | ***SOIL SAFE - ADELANTO***
ADELANTO CA | ***PFAS IND***

Status: Inactive ***Fac Fips Code:*** 06071
Fac Indian Cntry Flg: No ***Compliance Status:*** No Violation Identified
Fac Derived Huc: 18090208 ***EPA Programs:*** RCRA
Fac Derived Wbd: 180902080503 ***Federal Facility:*** No
Fac Derived Cd113: 08 ***Federal Agency:*** -
Fac Derived Cb2010: 060710091164115 ***Fac Snc Flg:*** No
Fac Informal Count: 0 ***AIR Flag:*** No
Last Informal Action: - ***NPDES Flag:*** No
Formal Action Count: 0 ***SDWIS Flag:*** No
Last Formal Action: - ***RCRAFlag:*** Yes
Fac Total Penalties: 0 ***TRI Flag:*** No
Fac Penalty Count: - ***GHG Flag:*** No
Date Last Penalty: - ***TRI IDs:*** -
Last Penalty Amt: 0 ***TRI Releases Trnsfrs:*** -
Fac Qtrs With Nc: 0 ***TRI on Site Releases:*** -
Programs With Snc: 0 ***TRI off Site Trnsfrs:*** -
Fac Percent Minority: 82.574 ***TRI Reporter:*** -
Fac Pop Den: 721.25 ***Fac Imp Water Flg:*** -
Count: 1 ***Fac Major Flag:*** -

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fac County:	SAN BERNARDINO	**Fac Active Flag:**	-
State Other:		**Fac Inspection Count:**	0
Region:	09	**Date Last Inspection:**	-
Latitude:	34.567	**Days Last Inspection:**	-
Longitude:	-117.3955		
Fac Derived Tribes:	-		
AIR IDs:	-		
CAA Permit Types:	-		
CAA NAICS:	-		
CAA SICS:	-		
NPDES IDs:	-		
CWA Permit Types:	-		
CWA NAICS:	-		
CWA SICS:	-		
RCRA IDs:	CAL000298752		
RCRA Permit Types:	Other		
RCRA NAICS:	562920		
SDWA IDs:	-		
SDWA System Types:	-		
SDWA Compliance Status:	-		
SDWA Snc Flag:	No		
Fac Collection Meth:	INTERPOLATION-MAP		
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110002413834		

Details

Industry:	Waste Management

17	1 of8	NNE	0.10 / 527.91	2,898.17 / -9	**Exel** **13133 INNOVATION WAY STE 100** **VICTORVILLE CA 92394**	CERS HAZ

Latitude:	34.574330
Longitude:	-117.380000

Regulated Programs

EI ID:	10414909	**EI Description:**	Chemical Storage Facilities

Violations

Violation Date:	06/27/2017	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	San Bernardino County Fire Department
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)		
Violation Notes:			

Returned to compliance on 04/29/2020. A site map must contain north orientation, loading areas, internal roads, adjacent streets, storm & sewer drains, access & exit points, emergency shutoffs, evacuation staging areas, hazardous material handling & storage areas, and emergency response equipment. The site map submitted on 02/07/17 is missing one or more of these elements.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date:	06/27/2017	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	San Bernardino County Fire Department
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)		
Violation Notes:			

Returned to compliance on 04/29/2020. The Emergency Response Plan submitted on 02/07/17 has the incorrect phone number for the Local Unified Program Agency (UPA/CUPA). The correct phone number is (909) 386-8425.

Violation Description:

Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Violations

Violation Date: 04/29/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 05/06/2020. OBSERVATION: At the time of inspection, the business plan was last reviewed and certified on 03/03/2018. The business plan is to be reviewed and certified annually. CORRECTIVE ACTION: Review and certify the business plan via CERS. CERS ID # 10414909

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 06/27/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 04/29/2020. The Owner, Primary Emergency Contact, Billing Contact, and Environmental Contact is outdated. Update information on CERS.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Enforcements

Enf Action Date: 06/27/2017 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: San Bernardino County Fire Department
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 03/31/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/27/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

ROUTINE HANDLER INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/29/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/27/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

ROUTINE GENERATOR INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: San Bernardino County Fire
Entity Title:
Address: 598 South Tippecanoe Avenue, First Floor
City: San Bernardino
State: CA
Country:
Zip Code: 92415-0153
Phone: (909) 386-8401

Affil Type Desc: Legal Owner
Entity Name: DHL/Exel
Entity Title:
Address: 13133 Innovation Way Ste 100
City: Victorville
State: CA
Country: United States
Zip Code: 92394
Phone: (760) 991-8209

Affil Type Desc: Property Owner
Entity Name: Mike Thrasher
Entity Title:
Address: 745 Leo Bullocks Pkwy
City: Elyria
State: OH
Country: United States
Zip Code: 44035
Phone: (440) 258-5619

Affil Type Desc: Document Preparer
Entity Name: Billy Martin
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Parent Corporation
Entity Name: DHL Supply Chain
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Damen Burris
Entity Title:
Address: 9267 Haven Ave Suite 230
City: Rancho Cucamonga
State: CA
Country:
Zip Code: 91730
Phone:

Affil Type Desc: Identification Signer
Entity Name: Billy Martin
Entity Title: General Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 13133 Innovation Way #100
City: Victorville
State: CA
Country:
Zip Code: 92394
Phone:

Affil Type Desc: Operator
Entity Name: DHL/ EXEL
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (760) 991-8212

17	*2 of8*	*NNE*	*0.10 / 527.91*	*2,898.17 / -9*	***UNITED FURNITURE INDUSTRIES*** ***13133 INNOVATION WAY*** ***VICTORVILLE CA 92394***	***EMISSIONS***

Source:

2013 Criteria Data

Facility ID: 3316
Facility SIC Code: 2599
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:

CERR Code:
TOGT: .1875
ROGT: .162675
COT:
NOXT:
SOXT:
PMT:
PM10T:

2013 Toxic Data

Facility ID:	3316	***COID:***	SBD
Facility SIC Code:	2599	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2016 Criteria Data

Facility ID:	200903316	***CERR CODE:***	
Facility SIC Code:	2599	***TOGT:***	
CO:	36	***ROGT:***	
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	.2664473684210526315789473684210526315789
CHAPIS:		***PM10T:***	.162

2016 Toxic Data

Facility ID:	200903316	***TS:***	
Facility SIC Code:	2599	***HRA:***	
CERR CODE:		***CH Index:***	
COID:	SBD	***AH Index:***	
CO:	36	***Air Basin:***	MD
DISN:	MOJAVE DESERT AQMD	***District:***	MOJ
CHAPIS:			

2017 Criteria Data

Facility ID:	200903316	***CERR Code:***	
Facility SIC Code:	2599	***TOGT:***	
CO:	36	***ROGT:***	
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	.2664473684210526315789473684210526315789
CHAPIS:		***PM10T:***	.162

2017 Toxic Data

Facility ID:	200903316	***COID:***	SBD
Facility SIC Code:	2599	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID: 3316
Facility SIC Code: 2599
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT:
ROGT:
COT:
NOXT:
SOXT:
PMT: .2664473684210526315789473684210526315789
PM10T: .162

2018 Toxic Data

Facility ID: 3316
Facility SIC Code: 2599
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2019 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 3316
District: MOJ
Facility SIC Code: 2512
CO ID: SBD
DISN: MOJAVE DESERT AQMD
PM10T: 3.65
TOGT:
PMT: 3.80208333333333333333333333333333333333
CHAPIS:
CERR Code:
ROGT:
COT:
NOXT:
SOXT:

2019 Toxic Data

CO: 36
Air Basin: MD
Faccility ID: 3316
District: MOJ
Facility SIC Code: 2512
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TS: 0
Health Risk Asmt:

2020 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 3316
District: MOJ
Facility SIC Code: 2512
CO ID: SBD
DISN: MOJAVE DESERT AQMD
TOGT:
PMT: 3.80208333333333333333333333333333333333
PM10T: 3.65
CHAPIS:
CERR Code:
ROGT:
COT:
NOXT:
SOXT:

2020 Toxic Data

CO: 36
DISN: MOJAVE DESERT AQMD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Basin: MD
Facility ID: 3316
District: MOJ
Facility SIC Code: 2512
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CHAPIS:
CHERR Code:
TS: 0
Health Risk Asmt:

2021 Toxic Data

Co: 36
Air Basin: MD
Facility ID: 3316
District: MOJ
Facility SIC Code: 2512
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
Cerr Code:
TS: 0
Health Risk Asmt:

2021 Criteria Data

Co: 36
Air Basin: MD
Facility ID: 3316
District: MOJ
Facility SIC Code: 2512
CO ID: SBD
DISN: MOJAVE DESERT AQMD
TOGT:
PMT: 3.80208333333333333333333333333333333333
PM10T: 3.65
CHAPIS:
Cerr Code:
ROGT:
COT:
NOXT:
SOXT:

17	3 of8	NNE	0.10 / 527.91	2,898.17 / -9	SCI LOT 1 - INNOVATION WAY 13133 INNOVATION WAY VICTORVILLE CA 92392	EMISSIONS

Source:

2018 Criteria Data

Facility ID: 3061
Facility SIC Code: 4225
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: .00205913488901536710301650540694365395 5606
ROGT: .00180895
COT: .020477314
NOXT: .09505639
SOXT: .00003306
PMT: .00124225855130784708249496981891348088 5311
PM10T: .001234805

2018 Toxic Data

Facility ID: 3061
Facility SIC Code: 4225
CO: 36
Air Basin: MD
District: MOJ
TS: 5.7
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2019 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	3061	***ROGT:***	.00180895
District:	MOJ	***COT:***	.020477314
Facility SIC Code:	4225	***NOXT:***	.09505639
CO ID:	SBD	***SOXT:***	.00003306
DISN:	MOJAVE DESERT AQMD		
PM10T:	.001234805		
TOGT:	.00205913488901536710301650540694365395560 6		
PMT:	.00124225855130784708249496981891348088531 1		

2019 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Faccility ID:	3061	***CERR Code:***	
District:	MOJ	***TS:***	5.7
Facility SIC Code:	4225	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	3061	***ROGT:***	.00180895
District:	MOJ	***COT:***	.020477314
Facility SIC Code:	4225	***NOXT:***	.09505639
CO ID:	SBD	***SOXT:***	.00003306
DISN:	MOJAVE DESERT AQMD		
TOGT:	.00205913488901536710301650540694365395560 6		
PMT:	.00124225855130784708249496981891348088531 1		
PM10T:	.001234805		

2020 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	3061	***CHERR Code:***	
District:	MOJ	***TS:***	5.7
Facility SIC Code:	4225	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

17	***4 of8***	***NNE***	***0.10 / 527.91***	***2,898.17 / -9***	***DC1 13133 INNOVATION WAY VICTORVILLE CA 92392***	***EMISSIONS***

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2021 Toxic Data

Co:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	3061	***Cerr Code:***	
District:	MOJ	***TS:***	5.7
Facility SIC Code:	4225	***Health Risk Asmt:***	

COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2021 Criteria Data

Co:	36	**CHAPIS:**	
Air Basin:	MD	**Cerr Code:**	
Facility ID:	3061	**ROGT:**	.00180895
District:	MOJ	**COT:**	.020477314
Facility SIC Code:	4225	**NOXT:**	.09505639
CO ID:	SBD	**SOXT:**	.00003306

DISN: MOJAVE DESERT AQMD
TOGT: .00205913488901536710301650540694365395606
PMT: .00124225855130784708249496981891348088531 1
PM10T: .001234805

2023 Pollutant Data

Facility ID:	3061	**CO:**	36
Facility SIC Code:	4225	**CO ID:**	SBD
CERR Code:		**Air Basin:**	MD
CHAPIS:		**District:**	MOJ
ROGT:	.00180895	**NOXT:**	.09505639
COT:	.020477314	**SOXT:**	.000033033

DISN: MOJAVE DESERT AQMD
TOGT: .00205702751876279281328178303388674095974 5
PMT: .00124225855130784708249496981891348088531 1
PM10T: .001234805
Source: 2023 Pollutant Data

2022 Criteria Data

Facility ID:	3061	**District:**	MOJ
Facility SIC Code:	4225	**Air Basin:**	MD
Cerr Code:		**Co:**	36
CHAPIS:		**CO ID:**	SBD
ROGT:	.00180895	**NOXT:**	.09505639
COT:	.020477314	**SOXT:**	.00003306

DISN: MOJAVE DESERT AQMD
TOGT: .00205913488901536710301650540694365395606
PMT: .00124225855130784708249496981891348088531 1
PM10T: .001234805
Source: 2022 Criteria Data

2022 Toxic Data

Facility ID:	3061	**CO:**	36
Facility SIC Code:	4225	**Air Basin:**	MD
CHERR Code:		**District:**	MOJ
CHAPIS:		**COID:**	SBD
Health Risk Asmt:		**TS:**	5.7

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data

2023 Toxic Data

Facility ID:	3061	**CO:**	36
Facility SIC Code:	4225	**COID:**	SBD
CHERR Code:		**Air Basin:**	MD
CHAPIS:		**District:**	MOJ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TS: 5.7
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	5 of8	NNE	0.10 / 527.91	2,898.17 / -9	DHL SUPPLY CHAIN - MARS 13133 INNOVATION WAY SUITE 100 VICTORVILLE CA 92394	RCRA NON GEN

Handler ID: CAC002963703
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No
Transfer Facility: No
Recycler: No
Onsite Burner Exem: No
Furnace Exemption: No
Underground Injec: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Commercial TSD: No
Recycl Nonstorage: No

Additional Handler Summary Details

Source Type: I
Seq No: 1
Non Notifier:
Receive Date: 20180529
Active Site: H----
Land Type:
In Handler Univ: Y
In A Universe: Y
Gen Status: N
Report Cycle:
Accessibility:
Region: 09
Fed Waste Gen Owner: HQ
State Waste Generator Owner: CA
State Waste Generator: 2
Short Term Generator: N
Uni Waste: Y
Universal Waste Dest Facility: Y
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N

NAIC 1: 236210
NAIC 2:
NAIC 3:
NAIC 4:
State: CA
Location Latitude: 34.576079
Location Longitude: -117.380091
Loc GIS Primary: N
Loc GIS Origin: AG
State District Owner:
State District:

GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20180830
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	DHL SUPPLY CHAIN - MARS
Location Street No:	
Location Street1:	13133 INNOVATION WAY
Location Street2:	SUITE 100
Location City:	VICTORVILLE
Location State:	CA
Location Zip:	92394
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	JEFF PARR
Contact Street No:	
Contact Street1:	13133 INNOVATION WAY
Contact Street2:	SUITE 100
Contact City:	VICTORVILLE
Contact State:	CA
Contact Zip:	92394
Contact Country:	
Contact Phone & Ext:	760-381-8823
Contact Fax:	760-530-1603
Contact Email Address:	CHARLES.KAPLAN@DHL.COM
Contact Title:	
Owner Name:	JEFF PARR
Owner Type:	O
Owner Seq:	1
Operator Name:	JEFF PARR
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20180529
Handler Name:	DHL SUPPLY CHAIN - MARS
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified

Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street1:**	13133 INNOVATION WAY
Name:	JEFF PARR	**Street2:**	SUITE 100
Dt Became Current:		**City:**	VICTORVILLE
Dt Ended Current:		**State:**	CA
Phone:	760-381-8823	**Country:**	
Source Type:	Implementer	**Zip:**	92394

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street1:**	13133 INNOVATION WAY
Name:	JEFF PARR	**Street2:**	SUITE 100
Dt Became Current:		**City:**	VICTORVILLE
Dt Ended Current:		**State:**	CA
Phone:	760-381-8823	**Country:**	
Source Type:	Implementer	**Zip:**	92394

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	6 of8	NNE	0.10 / 527.91	2,898.17 / -9	UNITED FURNITURE INDUSTRIES INC 13133 INNOVATION WAY STE 200 VICTORVILLE CA 92394	RCRA NON GEN

Handler ID: CAL000442896
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	337121
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20190131	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:		**Location Latitude:**	34.576076
In Handler Univ:	Y	**Location Longitude:**	-117.380078
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	2
Short Term Generator:	N
Uni Waste:	Y
Universal Waste Dest Facility:	Y
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20190222
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	UNITED FURNITURE INDUSTRIES INC
Location Street No:	
Location Street1:	13133 INNOVATION WAY STE 200
Location Street2:	
Location City:	VICTORVILLE
Location State:	CA
Location Zip:	92394
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	LAURA ARENDARIZ
Contact Street No:	
Contact Street1:	13133 INNOVATION WAY STE 200
Contact Street2:	
Contact City:	VICTORVILLE
Contact State:	CA
Contact Zip:	92394
Contact Country:	
Contact Phone & Ext:	760-246-0909
Contact Fax:	662-276-1959
Contact Email Address:	LARMENDARIZ@UFIFURNITURE.COM
Contact Title:	
Owner Name:	UNITED FURNITURE INDUSTRIES CA INC
Owner Type:	O
Owner Seq:	1
Operator Name:	LAURA ARENDARIZ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operator Type: O
Operator Seq: 2
Public Notes:

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20190131
Handler Name: UNITED FURNITURE INDUSTRIES INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: LAURA ARENDARIZ
Dt Became Current:
Dt Ended Current:
Phone: 760-246-0909
Source Type: Implementer
Street No:
Street1: 13133 INNOVATION WAY STE 200
Street2:
City: VICTORVILLE
State: CA
Country:
Zip: 92394

Owner/Operator Ind: Current Owner
Type: Other
Name: UNITED FURNITURE INDUSTRIES CA INC
Dt Became Current:
Dt Ended Current:
Phone: 662-432-0000
Source Type: Implementer
Street No:
Street1: PO BOX 519
Street2:
City: VERONA
State: MS
Country:
Zip: 38879

17	7 of8	NNE	0.10 / 527.91	2,898.17 / -9	**DHL - EXEL** **13133 Innovation WAY Ste 100** **Victorville CA 92394**	SANBERN CUPA

Facility ID: FA0016320
Owner Info: DHL/EXEL
Mailing Care of: BILLY.MARTIN@DHL.COM
Mailing Address 2:
Mailing City: Victorville
Mailing State: CA
Mailing Zip: 92394

Detail(s)

Permit ID: PT0035448
Status: ACTIVE
Program Element Code: 4241
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
To: 2/28/2025
Mailing Address 1: 13133 Innovation Way Ste 100

Permit ID: PT0035449
Status: INACTIVE
Program Element Code: 4452
Permit Desc: CONDITIONALLY EXEMPT SM QTY GENERATOR
To: 2/28/2018
Mailing Address 1: 13133 Innovation Way Ste 100

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	8 of8	NNE	0.10 / 527.91	2,898.17 / -9	United Furniture Industries, Inc 13133 Innovation WAY Ste 200 Victorville CA 92394	SANBERN CUPA

Facility ID: FA0016434
Owner Info: United Furniture Industries
Mailing Care of: APINVOICES@LANEFURNITURE.COM
Mailing Address 2:
Mailing City: Victorville
Mailing State: CA
Mailing Zip: 92394

Detail(s)

Permit ID: PT0035418
Status: INACTIVE
Program Element Code: 4242
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS
To: 5/31/2024
Mailing Address 1: 13133 Innovation Way Ste 200

Permit ID: PT0035419
Status: INACTIVE
Program Element Code: 4452
Permit Desc: CONDITIONALLY EXEMPT SM QTY GENERATOR
To: 5/31/2022
Mailing Address 1: 13133 Innovation Way Ste 200

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	1 of1	WNW	0.11 / 556.26	2,899.86 / -7	CALNEV PIPE LINE LLC - ADELANTO JUNCTION AIR EXPRESSWAY AND ADELANTO RD ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAP000253971
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	486910
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20150917	**NAIC 4:**	

Active Site:	-----	**State:**	CA
Land Type:	P	**Location Latitude:**	34.572033
In Handler Univ:	N	**Location Longitude:**	-117.400698
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20240815
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	CALNEV PIPE LINE LLC - ADELANTO JUNCTION
Location Street No:	
Location Street1:	AIR EXPRESSWAY AND ADELANTO RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	RICH BRITO
Contact Street No:	1100
Contact Street1:	TOWN AND COUNTRY RD
Contact Street2:	
Contact City:	ORANGE
Contact State:	CA
Contact Zip:	92868
Contact Country:	US

Contact Phone & Ext: 714-560-4875
Contact Fax:
Contact Email Address: RICH_BRITO@KINDERMORGAN.COM
Contact Title: EHS SPECIALIST
Owner Name:
Owner Type:
Owner Seq:
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20150608
Handler Name: CALNEV PIPE LINE LLC - ADELANTO JUNCTION
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: 343
Waste Code Desc: Unspecified organic liquid mixture

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20150917
Handler Name: CALNEV PIPE LINE LLC - ADELANTO JUNCTION
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: CALNEV PIPE LINE LLC
Dt Became Current: 20010330
Dt Ended Current:
Phone:
Source Type: Notification
Street No:
Street1:
Street2:
City:
State:
Country: US
Zip:

Owner/Operator Ind: Current Owner
Type: Private
Name: CALNEV PIPE LINE LLC
Dt Became Current: 20010330
Dt Ended Current:
Phone: 714-560-4875
Source Type: Notification
Street No: 1100
Street1: TOWN AND COUNTRY RD
Street2:
City: ORANGE
State: CA
Country: US
Zip: 92868

Historical Handler Details

Receive Dt: 20150608
Generator Code Description: Large Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Handler Name:		CALNEV PIPE LINE LLC - ADELANTO JUNCTION				
19	1 of2	ENE	0.11 / 600.05	2,902.82 / -4	CALNEV Terminal GEORGE AFB Jet Fuel Spill 13334 Air Expressway Blvd. VICTORVILLE CA	CLEANUP SITES

Global ID: SLT6V0083835
Site Fac Type (SRCH): CLEANUP PROGRAM SITE
Status (SRCH): COMPLETED - CASE CLOSED
Status (DL): Completed - Case Closed
Status Date (DL): 8/13/2015
Cleanup Status: COMPLETED - CASE CLOSED
Site Facility Type: CLEANUP PROGRAM SITE
Case Type (DL): Cleanup Program Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH): 6071980200
Latitude (DL): 34.573016064525
Longitude (DL): -117.372350692749
Site Facility Name (SRCH): CALNEV TERMINAL GEORGE AFB JET FUEL SPILL
Address (SRCH): 13334 AIR EXPRESSWAY BLVD.
City (SRCH): VICTORVILLE
Zip (SRCH):
County (SRCH): SAN BERNARDINO
Street No (DL): 13334
Street Name (DL): Air Expressway Blvd.
City (DL): VICTORVILLE
Zip (DL):
County (DL): San Bernardino
State (DL): CA
Site Facility Name : CALNEV TERMINAL GEORGE AFB JET FUEL SPILL
Address : 13334 AIR EXPRESSWAY BLVD.
City : VICTORVILLE
Zip :
County : SAN BERNARDINO
Report Source: GeoTracker Search Results (SRCH); Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No: SLT6V008
Local Case No:
Begin Date: 5/1/2006
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Local Agency: SAN BERNARDINO COUNTY
CUF Case:
CalEnvScreen Score:
EPA Region: 9
Qty Rlsd Gallons: 30000
Potential COC: Aviation
How Discovered: * RPR
Stop Method:
Stop Description:
Case Worker:
Military DoD Site: No
Leak Reported Dt: 2006-05-01 00:00:00
No Further Action Dt: 2015-08-13 00:00:00
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name: Upper Mojave River Valley (6-042)
Disadvantaged Community:
Coordinate Source: Manual Entry on Screens
Discharge Cause:
Discharge Source:
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
File Location: Regional Board
Claim No:
Claim Status:
A2022 Assembly District: 34
A2022 Congressional District: 23

A2022 Senate District: 23
Site History:

This facility stored jet fuel for delivery into former George AFB. After George AFB closed in 1992, Calnev continues to use two above ground storage tanks for storage of fuel delivered to Southern California Logistics Airport. The City of Victorville CUPA oversaw cleanup of historical releases at this location. 944 barrels of JP-4 were released on May 1, 2006. The release was the result of a faulty valve. 151 gallons of jet fuel were recovered. 7,269 tones (4,500 cubic yards of impacted soil ws excavated and tranported to a fuel recycling facility. Impacted soil was observed to remain along the northern wall of the excation and in the bottom and side of the southeastern portion of the excavation. The excavation was not expanded because of the presence of infrastructure. An October 2006 investigation consisted of soil sampled from eight soil borings. One soil boring was advanced to groundwater soil samples showed TPH impacts. Consultant concluded an upgradient GAFB release fro ST-67 was the source of this contamination. The site was referred to the Water Board by the County on Dec 13, 2006. The AF's speciation of the jet fuel indicated that the impacts in the saturated zone are due to the GAFB release not from the CalNev release. 03/23/2015 CalNev submitted a report of investigation to fill LTCP checklist. 05/05/2015 Site meets LTCP checklist and is proposed for closure.

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2015-08-13 00:00:00

Status: Completed - Case Closed
Status Date: 2015-08-12 00:00:00

Status: Open - Site Assessment
Status Date: 2006-11-13 00:00:00

Status: Open - Case Begin Date
Status Date: 2006-05-01 00:00:00

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: GREG COON
Organization Name: SAN BERNARDINO COUNTY
Address:
City: VICTORVILLE
Email: gcoon@ci.victorville.ca.us
Phone No:

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=SLT6V0083835
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/13/2015
Potential COC: AVIATION
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: SLT6V008
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?

global_id=SLT6V0083835&tabname=regulatoryhistory

Site History:

This facility stored jet fuel for delivery into former George AFB. After George AFB closed in 1992, Calnev continues to use two above ground storage tanks for storage of fuel delivered to Southern California Logistics Airport. The City of Victorville CUPA oversaw cleanup of historical releases at this location. 944 barrels of JP-4 were released on May 1, 2006. The release was the result of a faulty valve. 151 gallons of jet fuel were recovered. 7,269 tones (4,500 cubic yards of impacted soil ws excavated and tranported to a fuel recycling facility. Impacted soil was observed to remain along the northern wall of the excation and in the bottom and side of the southeastern portion of the excavation. The excavation was not expanded because of the presence of infrastructure. An October 2006 investigation consisted of soil sampled from eight soil borings. One soil boring was advanced to groundwater soil samples showed TPH impacts. Consultant concluded an upgradient GAFB release fro ST-67 was the source of this contamination. The site was referred to the Water Board by the County on Dec 13, 2006. The AF's speciation of the jet fuel indicated that the impacts in the saturated zone are due to the GAFB release not from the CalNev release.
03/23/2015 CalNev submitted a report of investigation to fill LTCP checklist.
05/05/2015 Site meets LTCP checklist and is proposed for closure.

GeoTracker Search - Cleanup Action Report

Action Type: EXCAVATION
Begin Date: 5/11/2006
End Date: 5/11/2006
Phase: Soil
Contaminant Mass Removed:
Description: 151 gallons of jet fuel were recovered via vacuum truck in addition to the excavation and disposal of impacted soil.

Action Type: EXCAVATION
Begin Date: 5/1/2006
End Date: 5/10/2006
Phase: Soil, Liquid Waste
Contaminant Mass Removed: 7,269 Tons
Description: Evacated to a deppth of 20 feet. Covered bottom of excavation with visqueen and backfilled with clean soil.

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 8/12/2015
Received Issue Date: 8/12/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6256510&temptable=ENFORCEMENT
Title Description Comments:

NFAR letter

Action Type: Notices
Action: Notification - Preclosure
Action Date: 5/18/2015
Received Issue Date: 5/18/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6255908&temptable=ENFORCEMENT
Title Description Comments:

Notification of Consideration of NFAR

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 4/21/2015
Received Issue Date: 4/21/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6242267&temptable=ENFORCEMENT
Title Description Comments:

Low-threat Closure Policy checklist

Action Type: Other Regulatory Actions

Action: Staff Letter
Action Date: 1/29/2015
Received Issue Date: 1/29/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6234765&temptable=ENFORCEMENT
Title Description Comments:

Water Board Acceptance of Revised LTCP Work Plan

Action Type: Response Requested - Workplans
Action: Site Investigation Workplan
Action Date: 1/15/2015
Received Issue Date: 12/5/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5824862
Title Description Comments:

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/24/2014
Received Issue Date: 12/24/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6231785&temptable=ENFORCEMENT
Title Description Comments:

Staff Comments on Low-Threat Closure Work Plan

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/1/2014
Received Issue Date: 12/1/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6231320&temptable=ENFORCEMENT
Title Description Comments:

Request for Work Plan

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 8/1/2014
Received Issue Date: 8/1/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6245057&temptable=ENFORCEMENT
Title Description Comments:

City of Victorville Letter Accepting July 2014 Closure Report CalNev Terminal GAFB

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 4/18/2014
Received Issue Date: 4/18/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5917682
Title Description Comments:

Notification of Monitoring Well Destruction

Action Type: Response Requested - Workplans
Action: Other Workplan
Action Date: 12/31/2013
Received Issue Date:
Doc Link:
Title Description Comments:

Soil Sample Plan for Demolition Activity

Action Type: Response Requested - Workplans
Action: Tank Removal Workplan
Action Date: 5/10/2013
Received Issue Date: 5/10/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5784718
Title Description Comments:

CalNev Demolition Plan for Fueling Facilities at Former GAFB

Action Type: Response Requested - Workplans
Action: Interim Remedial Action Plan
Action Date: 7/23/2007
Received Issue Date: 7/23/2007
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5815891
Title Description Comments:

Work Plan for Jet Fuel Release GAFB Fuel Terminal

Action Type: Referral to Other Agency
Action: Referral to Regional Board
Action Date: 12/13/2006
Received Issue Date: 12/13/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6048478&temptable=ENFORCEMENT
Title Description Comments:

Referral letter from City of Victorville CUPA

Action Type: Response Requested - Reports
Action: Site Investigation
Action Date: 11/13/2006
Received Issue Date: 11/13/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5815892
Title Description Comments:

Site Assessment Report Jet Fuel Release GAFB Fuel Terminal

Action Type: Response Requested - Reports
Action: Site Investigation
Action Date: 6/30/2006
Received Issue Date: 6/30/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SLT6V0083835&doc_id=5815894
Title Description Comments:

Response to Jet Fuel Release GAFB Fuel Terminal

Action Type: Cleanup Action
Action: Excavation
Action Date: 5/11/2006
Received Issue Date:
Doc Link:
Title Description Comments:

151 gallons of jet fuel were recovered via vacuum truck in addition to the excavation and disposal of impacted soil.

Action Type: Leak Action
Action: Leak Began
Action Date: 5/1/2006
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Cleanup Action

Action: Excavation
Action Date: 5/1/2006
Received Issue Date:
Doc Link:
Title Description Comments:

Evacated to a deppth of 20 feet. Covered bottom of excavation with visqueen and backfilled with clean soil.

Action Type: Leak Action
Action: Leak Reported
Action Date: 5/1/2006
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Stopped
Action Date: 5/1/2006
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Discovery
Action Date: 5/1/2006
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 10/3/2005
Received Issue Date: 10/3/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6090494&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Cal-Nev Subparcel D-5B [CalNev AST Bulk Fuels]

GeoTracker Search - Deed Restrictions

Date Recorded: 10/3/2005
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8578297257/Quitclaim%20Deed_Parcel%20D-5B.pdf

GeoTracker Search - Documents

Document Type: Site Documents
Type: CLOSURE/NO FURTHER ACTION LETTER
Submitted By: LINDA STONE (REGULATOR)
Title: NFAR LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6256510
Document Date: 8/12/2015
Submitted:

Document Type: Site Documents
Type: NOTIFICATION - PRECLOSURE
Submitted By: LINDA STONE (REGULATOR)
Title: NOTIFICATION OF CONSIDERATION OF NFAR
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6255908
Document Date: 5/18/2015
Submitted:

Document Type: Site Documents
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER
Document Date: 4/21/2015
Submitted:

Submitted By: LINDA STONE (REGULATOR)
Title: LOW-THREAT CLOSURE POLICY CHECKLIST
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6242267

Document Type: Site Documents **Document Date:** 3/23/2015
Type: CLOSURE REPORT **Submitted:**
Submitted By: ROBIN SIMON (AUTH_RP)
Title: KMEP GAFB ASSESSMENT_032315
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4468923985/SLT6V0083835.PDF

Document Type: Site Documents **Document Date:** 1/29/2015
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: WATER BOARD ACCEPTANCE OF REVISED LTCP WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6234765

Document Type: Site Documents **Document Date:** 1/13/2015
Type: SOIL VAPOR INTRUSION INVESTIGATION WORKPLAN **Submitted:**
Submitted By: ROBIN SIMON (AUTH_RP)
Title: REVISED LOW THREAT CLOSURE INVESTIGATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8184862256/SLT6V0083835.PDF

Document Type: Site Documents **Document Date:** 12/24/2014
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: STAFF COMMENTS ON LOW-THREAT CLOSURE WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6231785

Document Type: Site Documents **Document Date:** 12/5/2014
Type: SITE INVESTIGATION WORKPLAN **Submitted:**
Submitted By: ROBIN SIMON (AUTH_RP)
Title: LOW THREAT CLOSURE INVESTIGATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1461663424/SLT6V0083835.PDF

Document Type: Site Documents **Document Date:** 12/1/2014
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: REQUEST FOR WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6231320

Document Type: Site Documents **Document Date:** 8/1/2014
Type: CLOSURE/NO FURTHER ACTION LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: CITY OF VICTORVILLE LETTER ACCEPTING JULY 2014 CLOSURE REPORT CALNEV TERMINAL GAFB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6245057

Document Type: Site Documents **Document Date:** 7/30/2014
Type: REQUEST FOR CLOSURE **Submitted:**
Submitted By: ROBIN SIMON (AUTH_RP)
Title: CALNEV GEORGE AFB TERMINAL FACILITY CLOSURE REPORT 073014
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3011466324/SLT6V0083835.PDF

Document Type: Site Documents **Document Date:** 4/18/2014
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: NOTIFICATION OF MONITORING WELL DESTRUCTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&document_id=5917682

Document Type: Site Documents **Document Date:** 5/10/2013
Type: TANK REMOVAL WORKPLAN **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: CALNEV DEMOLITION PLAN FOR FUELING FACILITIES AT FORMER GAFB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&document_id=5784718

Document Type: Site Documents **Document Date:** 7/23/2007
Type: INTERIM REMEDIAL ACTION PLAN **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: WORK PLAN FOR JET FUEL RELEASE GAFB FUEL TERMINAL

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&document_id=5815891

Document Type: Site Documents **Document Date:** 12/13/2006
Type: REFERRAL TO REGIONAL BOARD **Submitted:**
Submitted By: OMAR PACHECO (REGULATOR)
Title: REFERRAL LETTER FROM CITY OF VICTORVILLE CUPA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6048478

Document Type: Site Documents **Document Date:** 11/13/2006
Type: SITE INVESTIGATION **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: SITE ASSESSMENT REPORT JET FUEL RELEASE GAFB FUEL TERMINAL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&document_id=5815892

Document Type: Site Documents **Document Date:** 6/30/2006
Type: SITE INVESTIGATION **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: RESPONSE TO JET FUEL RELEASE GAFB FUEL TERMINAL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&document_id=5815894

Document Type: Site Documents **Document Date:** 10/3/2005
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED CAL-NEV SUBPARCEL D-5B [CALNEV AST BULK FUELS]
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6090494

GeoTracker Search - Site Maps

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-03 (SV-03)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6915991246/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-10 (SV-10)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4033457159/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-01 (SB-01)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8868003189/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-05 (SB-05)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6666193366/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-01 (SV-01)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1541297674/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-05 (SV-05)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9137376904/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-02 (SV-02)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9957665622/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-02 (SB-02)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9772904872/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-03 (SB-03)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7307603955/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-09 (SV-09)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5365287125/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-04 (SB-04)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7437522649/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-04 (SV-04)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6933569371/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-07 (SB-07)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4613672614/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-06 (SV-06)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3297462224/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6832785904/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SB-06 (SB-06)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8341439425/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-07 (SV-07)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6812257885/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-08 (SV-08)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9971717178/SLT6V0083835.PDF

Submitted: 3/24/2015
Submitted By: ROBIN SIMON (AUTH_RP)
Title: SV-11 (SV-11)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7065696060/SLT6V0083835.PDF

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 8/13/2015

Status: Completed - Case Closed
Date: 8/12/2015

Status: Open - Site Assessment
Date: 11/13/2006

Status: Open - Case Begin Date

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Date:		5/1/2006				

19	2 of2	ENE	0.11 / 600.05	2,902.82 / -4	CALNEV Terminal GEORGE AFB Jet Fuel Spill 13334 Air Expressway Blvd. VICTORVILLE CA	DEED

Global ID: SLT6V0083835
Site Type: Cleanup Program Site
Status: Completed - Case Closed
Status Date: 8/13/2015
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=SLT6V0083835
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.372350692749
Latitude: 34.573016064525

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 10/3/2005

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 10/3/2005
Received Issue Date: 10/3/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SLT6V0083835&enforcement_id=6090494&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Cal-Nev Subparcel D-5B [CalNev AST Bulk Fuels]

GeoTracker Search - Deed Restrictions

Date Recorded: 10/3/2005
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8578297257/Quitclaim%20Deed_Parcel%20D-5B.pdf

20	1 of2	NE	0.12 / 631.20	2,894.00 / -13	George Air Force Base - OT072 OU5 Current Skeet Range 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100234400
Site Fac Type (SRCH):
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 1/2/2013
Cleanup Status: COMPLETED - CASE CLOSED AS OF 1/2/2013
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): -92392
County (DL): San Bernardino
Site Facility Type: MILITARY CLEANUP SITE
Case Type (DL): Military Cleanup Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH):
Latitude (DL): 34.5738464717369
Longitude (DL): -117.379474639893

State (DL):	CA
Site Facility Name :	OT072 OU5 CURRENT SKEET RANGE
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	-92392
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 33
Local Case No:	400071 -- 33
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	2013-01-02 00:00:00
Potential Media of Concern:	Soil
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
Coordinate Source:	Google Map Move
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NA
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

In 2001 a soil removal project excavated and recovered 155,000 pounds lead, which was transported to a disposal facility in Illinois. The site property was transferred to Southern California Logistics Airport in 2006. In 2008, the site was graded and covered with 4 to 6 feet of fill material and a concrete foundation for construction of a one-million square-foot warehouse, parking lot, and service road. The warehouse structure and the associated parking lot and service road now cover approximately 98 percent of Site OT072. Post-excavation confirmation soil sampling documented that lead and antimony concentrations were below the USEPA residential PRGs, and arsenic concentrations were within the range of GAFB background values in soil. The ROD for the OU 5 skeet sites OT072, OT073, and OT074 was finalized in October 2014. No Further Action was proposed for Site OT072 in the final ROD, which was approved by the USEPA and the Lahontan Regional Water Quality Control Board.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	2013-01-02 00:00:00
Status:	Open - Site Assessment
Status Date:	2010-04-23 00:00:00
Status:	Open - Inactive
Status Date:	2010-01-14 00:00:00

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100234400
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/2/2013
Potential COC: NONE SPECIFIED
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management: LAND USE COVENANT
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 33
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 33
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100234400&tabname=regulatoryhistory
Site History:

In 2001 a soil removal project excavated and recovered 155,000 pounds lead, which was transported to a disposal facility in Illinois. The site property was transferred to Southern California Logistics Airport in 2006. In 2008, the site was graded and covered with 4 to 6 feet of fill material and a concrete foundation for construction of a one-million square-foot warehouse, parking lot, and service road. The warehouse structure and the associated parking lot and service road now cover approximately 98 percent of Site OT072.

Post-excavation confirmation soil sampling documented that lead and antimony concentrations were below the USEPA residential PRGs, and arsenic concentrations were within the range of GAFB background values in soil.

The ROD for the OU 5 skeet sites OT072, OT073, and OT074 was finalized in October 2014. No Further Action was proposed for Site OT072 in the final ROD, which was approved by the USEPA and the Lahontan Regional Water Quality Control Board.

GeoTracker Search - Cleanup Action Report

Action Type: EXCAVATION
Begin Date: 12/1/2000
End Date:
Phase: Soil
Contaminant Mass Removed:
Description: In December 2000 approximately 725 Cubic Feet (48 tons) of metal laden soil was excavated and disposed inot a Class I Hazardous Waste Landfill. Confirmation samples were collected.

Action Type: EXCAVATION
Begin Date: 4/1/2001
End Date: 5/30/2001
Phase: Soil
Contaminant Mass Removed: 155,000 Pounds
Description: Interim Removal Action completed resulting in excavationand offsite disposal of 155,000 pounds lead.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Workplans
Action: Proposed Plan
Action Date:
Received Issue Date: 10/10/2014

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6105357
Title Description Comments:

Final Proposed Plan for Operable Unit (OU5) Sites FT082, SS083, OT072, OT073, and OT074, former George Air Force Base, regulatory acceptance and reviews of draft versions

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 10/10/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6105369
Title Description Comments:

Final Record of Decision (ROD), OU-5, Sites OT072, OT073, and OT074, Former George Air Force Base

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 12/20/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6093999
Title Description Comments:

Draft Skeet Range Record of Decision

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6280637
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6277821
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6288249
Title Description Comments:

Notice to Not Establish RAB

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/24/2014
Received Issue Date: 7/24/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6285355&temptable=ENFORCEMENT
Title Description Comments:

EPA Comments on Response to Comments Draft OU5 Skeet Range Sites OT 072 OT073 OT074

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/22/2014

Received Issue Date: 7/22/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6285336&temptable=ENFORCEMENT
Title Description Comments:

State Comments on Draft Final Record of Decision OU5 Skeet Range Sites OT072, OT073, OT074

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 3/25/2014
Received Issue Date: 3/25/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6198429&temptable=ENFORCEMENT
Title Description Comments:

Water Board Comments on Draft Skeet Range ROD

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/23/2013
Received Issue Date: 12/23/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6186616&temptable=ENFORCEMENT
Title Description Comments:

Water Board Deferal to USEPA on three documents

Action Type: Response Requested - Other
Action: Correspondence
Action Date: 10/1/2013
Received Issue Date: 10/4/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6181618
Title Description Comments:

AF decision to produce one Record of Decision for the OU 5 skeet range sites and one for TCE source areas.

Action Type: Response Requested - Other
Action: Correspondence
Action Date: 11/30/2011
Received Issue Date: 11/30/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6076593
Title Description Comments:

Air Force Response to EPA - RE: Informal Dispute on Focused Feasibility Study for OU5 sites

Action Type: Enforcement/Orders
Action: Warning Letter
Action Date: 11/28/2011
Received Issue Date: 11/28/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6104901&temptable=ENFORCEMENT
Title Description Comments:

EPA - EPA Review and Invocation of Informal Dispute Resolution Regarding Final Operable Unit 5 Focused Feasibility Study, GAFB, CA August 2011

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 8/26/2011
Received Issue Date: 8/26/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6097273&temptable=ENFORCEMENT
Title Description Comments:

Final Operable Unit Five Focused Feasibility Study Former George AFB, MWH 8-26-11

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/21/2010
Received Issue Date: 12/21/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6072595&temptable=ENFORCEMENT
Title Description Comments:

Draft Final OU-5 Focused Feasibility Study, December 21, 2010

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 11/1/2010
Received Issue Date: 11/1/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6068416&temptable=ENFORCEMENT
Title Description Comments:

EPA Letter - Draft Operable Unit 5 Focused Feasibility Study, Former George Air Force Base, California, dated August 31, 2010

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 9/22/2006
Received Issue Date: 9/22/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6090439&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel D-18 - Current Skate Range

Action Type: Cleanup Action
Action: Excavation
Action Date: 4/1/2001
Received Issue Date:
Doc Link:
Title Description Comments:

Interim Removal Action completed resulting in excavationand offsite disposal of 155,000 pounds lead.

Action Type: Cleanup Action
Action: Excavation
Action Date: 12/1/2000
Received Issue Date:
Doc Link:
Title Description Comments:

In December 2000 approximately 725 Cubic Feet (48 tons) of metal laden soil was excavated and disposed inot a Class I Hazardous Waste Landfill. Confirmation samples were collected.

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234400&doc_id=6226118
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6104640&temptable=ENFORCEMENT

Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 9/22/2006
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100234400&enforcement_id=6090439

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6288249

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6277821

Document Type: Site Documents ***Document Date:*** 10/10/2014
Type: PROPOSED PLAN ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: FINAL PROPOSED PLAN FOR OPERABLE UNIT (OU5) SITES FT082, SS083, OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE, REGULATORY ACCEPTANCE AND REVIEWS OF DRAFT VERSIONS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6105357

Document Type: Site Documents ***Document Date:*** 10/10/2014
Type: PROPOSED PLAN ***Submitted:***
Submitted By: AUSTIN WHITE (REGULATOR)
Title: FINAL PROPOSED PLAN FOR OPERABLE UNIT (OU5) SITES FT082, SS083, OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE, REGULATORY ACCEPTANCE AND REVIEWS OF DRAFT VERSIONS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6105357

Document Type: Site Documents ***Document Date:*** 10/10/2014
Type: RECORD OF DECISION ***Submitted:***
Submitted By: AUSTIN WHITE (REGULATOR)
Title: FINAL RECORD OF DECISION (ROD), OU-5, SITES OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6105369

Document Type: Site Documents ***Document Date:*** 7/24/2014
Type: STAFF LETTER ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: EPA COMMENTS ON RESPONSE TO COMMENTS DRAFT OU5 SKEET RANGE SITES OT 072 OT073 OT074
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6285355

Document Type: Site Documents ***Document Date:*** 7/22/2014
Type: STAFF LETTER ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: STATE COMMENTS ON DRAFT FINAL RECORD OF DECISION OU5 SKEET RANGE SITES OT072, OT073, OT074
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6285336

Document Type: Site Documents ***Document Date:*** 3/25/2014
Type: STAFF LETTER ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: WATER BOARD COMMENTS ON DRAFT SKEET RANGE ROD
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6198429

Document Type: Site Documents ***Document Date:*** 12/23/2013

Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: WATER BOARD DEFERAL TO USEPA ON THREE DOCUMENTS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6186616

Document Type: Site Documents **Document Date:** 12/20/2013
Type: RECORD OF DECISION **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: DRAFT SKEET RANGE RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6093999

Document Type: Site Documents **Document Date:** 10/4/2013
Type: CORRESPONDENCE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: AF DECISION TO PRODUCE ONE RECORD OF DECISION FOR THE OU 5 SKEET RANGE SITES AND ONE FOR TCE SOURCE AREAS.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6181618

Document Type: Site Documents **Document Date:** 11/30/2011
Type: CORRESPONDENCE **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: AIR FORCE RESPONSE TO EPA - RE: INFORMAL DISPUTE ON FOCUSED FEASIBILITY STUDY FOR OU5 SITES
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6076593

Document Type: Site Documents **Document Date:** 11/28/2011
Type: WARNING LETTER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA - EPA REVIEW AND INVOCATION OF INFORMAL DISPUTE RESOLUTION REGARDING FINAL OPERABLE UNIT 5 FOCUSED FEASIBILITY STUDY, GAFB, CA AUGUST 2011
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6104901

Document Type: Site Documents **Document Date:** 8/26/2011
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: FINAL OPERABLE UNIT FIVE FOCUSED FEASIBILITY STUDY FORMER GEORGE AFB, MWH 8-26-11
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6097273

Document Type: Site Documents **Document Date:** 12/21/2010
Type: STAFF LETTER **Submitted:**
Submitted By: (REGULATOR)
Title: DRAFT FINAL OU-5 FOCUSED FEASIBILITY STUDY, DECEMBER 21, 2010
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6072595

Document Type: Site Documents **Document Date:** 11/1/2010
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: (REGULATOR)
Title: EPA LETTER - DRAFT OPERABLE UNIT 5 FOCUSED FEASIBILITY STUDY, FORMER GEORGE AIR FORCE BASE, CALIFORNIA, DATED AUGUST 31, 2010
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6068416

Document Type: Site Documents **Document Date:** 9/22/2006
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED PARCEL D-18 - CURRENT SKATE RANGE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6090439

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6226118

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / **Submitted:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ASSISTANCE / OTHER
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6104640

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&document_id=6280637

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 1/2/2013

Status: Open - Site Assessment
Date: 4/23/2010

Status: Open - Inactive
Date: 1/14/2010

20	2 of2	NE	0.12 / 631.20	2,894.00 / -13	George Air Force Base - OT072 OU5 Current Skeet Range 18374 Phantom West St Victorville CA -92392	DEED

Global ID: DOD100234400
Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 1/2/2013
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100234400
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.379474639893
Latitude: 34.5738464717369

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 9/22/2006

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 9/22/2006
Received Issue Date: 9/22/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234400&enforcement_id=6090439&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel D-18 - Current Skate Range

GeoTracker Search - Deed Restrictions

Date Recorded: 9/22/2006
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100234400&enforcement_id=6090439

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	1 of11	W	0.13 / 671.18	2,917.88 / 11	TPST SOIL RECYCLERS OF CALIFORNIA 12328 HIBISCUS ADELANTO CA 92301	AST

Total Capacity(Gal): 42,655
Owner Name: SOIL SAFE OF CALIFORNIA
CUPA: San Bernardino
County: San Bernardino

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	2 of11	W	0.13 / 671.18	2,917.88 / 11	SOIL SAFE OF CALIFORNIA, INC. 12328 HIBISCUS RD ADELANTO CA 92301	C&D DEBRIS RECY

County: SAN BERNARDINO

Activity Type: OTHER RECYCLING MANUFACTURING
Phone No: (760) 246-8001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	3 of11	W	0.13 / 671.18	2,917.88 / 11	Soil Safe-Adelanto Soil Recycling Center 12328 HIBISCUS RD ADELANTO CA 92301	CERS TANK

Site ID: 163019
Latitude: 34.567497
Longitude: -117.395400

Regulated Programs

EI ID: 10045696
EI Description: Hazardous Waste Generator

EI ID: 10045696
EI Description: Aboveground Petroleum Storage

Violations

Violation Date: 09/04/2024
Violation Source: CIWQS
Violation Program: LNDISPOTH
Violation Division: Water Boards
Citation: California Water Code
Violation Notes:

Violation of BO 6-91-95 Section, I.D.1

Violation Description:

Violations

Violation Date: 01/31/2023
Violation Source: CERS
Violation Program: APSA
Violation Division: San Bernardino County Fire Department
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 02/06/2023. OBSERVATION: (2) 20K OUT OF SERVICE OIL (AST) TANKS WERE MARKED EMPTY AND A START DATE. AS PER SPCC REQUIREMENT, ALL OUT OF SERVED TANKS MUST BE MARKED WITH THE WORDS " PERMANENTLY CLOSED AND A DATE. COMPLIANCE REQUIREMENT: 1) MARKED THE (2) 20K OUT SERVICE ASTS WITH THE WORDS "PERMANENTLY CLOSED AND A DATE" 2) SUBMIT THE SIGNED OF CERTIFICATE OF COMPLIANCE , ONCE COMPLETED.

Violation Description:

Failure to properly close tanks when making a claim of "permanently closed."

Violations

Violation Date: 05/29/2020 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** San Bernardino County Fire Department
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 06/25/2020. OBSERVATION: The generator has not obtained an active EPA ID number to manage hazardous waste. A hazardous waste generator shall not treat, store, dispose of, transport or offer for transportation, hazardous waste without an active EPA ID number. EPA ID number CAL000298752 was inactive. CORRECTIVE ACTION: Submit documentation to the CUPA demonstrating that you have obtained an EPA ID number.

Violation Description:

Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.

Violations

Violation Date: 01/31/2023 ***Violation Source:*** CERS
Violation Program: APSA ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 02/06/2023. OBSERVATION: DURING THE INSPECTION, FACILITY WAS PERFORMING WEEK HAZARDOUS WASTE INSPECTIONS, HOWEVER MONTH & ANNUAL SPCC STI - SP001 DOCUMENTED INSPECTIONS WERE NOT PERFORMED. COMPLIANCE REQUIREMENT: 1) PERFORM STI SP001 MONTHLY & ANNUAL DOCUMENTED INSPECTIONS. FORMS PROVIDED TO OPERATOR. 2) SUBMIT SIGNED CERTIFICATE OF COMPLIANCE ONCE COMPLETE.

Violation Description:

Failure to comply with one or more of the following requirements:

1. Have record of inspections and tests, including integrity tests, signed by the appropriate supervisor or inspector.

2. Keep written procedures and records of inspections and tests, including integrity tests, for at least three years.

3. Keep comparison records.

Violations

Violation Date: 01/31/2023 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** San Bernardino County Fire Department
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Returned to compliance on 02/06/2023. OBSERVATION: ANY HAZARDOUS MATERIAL AT OR ABOVE 55-GALLONS, 500-POUNDS AND/ OR 200 CUBIC FEET OF A COMPRESSED GAS, MUST BE LISTED IN THE HAZARDOUS MATERIALS INVENTORY. DURING THE INSPECTION, (2) 55-GALLON POLY DRUMS OF DEF WERE OBSERVED AND NOT LISTED IN THE CERS INVENTORY. COMPLIANCE REQUIREMENT: UPDATE THE CERS INVENTORY WITH THE (2) 55-GALLON POLY DRUMS OF DEF.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Enforcements

Enf Action Date: 11/03/2009 ***Enf Action Program:*** LNDISPOTH
Enf Action Type: Notice of Violation (Water) ***Enf Action Source:*** CIWQS
Enf Action Division: Water Boards
Enf Action Description: Notice of Violation Letter (Informal)
Enf Action Notes:

Enf Action Date: 11/08/2010
Enf Action Type: Notice of Violation (Water)
Enf Action Division: Water Boards
Enf Action Description: Notice of Violation Letter (Informal)
Enf Action Notes:
Enf Action Program: LNDISPOTH
Enf Action Source: CIWQS

Enf Action Date: 11/07/2014
Enf Action Type: Oral Communication
Enf Action Division: Water Boards
Enf Action Description: Oral Communication
Enf Action Notes:
Enf Action Program: LNDISPOTH
Enf Action Source: CIWQS

Enf Action Date: 09/04/2024
Enf Action Type: Oral Communication
Enf Action Division: Water Boards
Enf Action Description: Oral Communication
Enf Action Notes:
Enf Action Program: LNDISPOTH
Enf Action Source: CIWQS

Evaluations

Eval Date: 04/23/2002
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 01/31/2023
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

SOIL SAFE CUPA- ADELANTO; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/29/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 07/25/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 06/14/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: San Bernardino County Fire Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

ROUTINE APSA INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/14/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

ROUTINE GENERATOR INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/01/2001
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 09/04/2024
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 05/29/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Eval Date: 08/22/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 06/17/2010
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 06/01/2006
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 01/29/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 05/29/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/23/2008
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 02/02/2000
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 02/22/2007
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 01/31/2023
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

ASPA CUPA SOIL SAFE- ADELANTO; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/14/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

ROUTINE HANDLER INSPECTION; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/01/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 05/30/1996
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 05/12/2009
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 01/04/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 01/31/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: San Bernardino County Fire Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

SOIL SAFE- CUPA WASTE- ADELANTO; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/11/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection

Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Eval Date: 12/22/2011
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: RWQCB Type B compliance inspection
Eval Division: Water Boards
Eval Program: LNDISPOTH
Eval Source: CIWQS
Eval Notes:

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: Soil Safe
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Bill Bishop
Entity Title: VP Operations Western Region
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Soil Safe of California, Inc
Entity Title:
Address: 12328 HIBISCUS RD
City: ADELANTO
State: CA
Country: United States
Zip Code: 92301
Phone: (760) 246-8001

Affil Type Desc: CUPA District
Entity Name: San Bernardino County Fire
Entity Title:
Address: 598 South Tippecanoe Avenue, First Floor
City: San Bernardino
State: CA
Country:
Zip Code: 92415-0153
Phone: (909) 386-8401

Affil Type Desc: Operator
Entity Name: Soil Safe of California, Inc
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (760) 246-8001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Environmental Contact
Entity Name: BILL BISHOP
Entity Title:
Address: 12328 Hibiscus Rd
City: ADELANTO
State: CA
Country:
Zip Code: 92301
Phone:

Affil Type Desc: Document Preparer
Entity Name: Bill Bishop
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 12328 HIBISCUS RD
City: ADELANTO
State: CA
Country:
Zip Code: 92301
Phone:

Coordinates

Env Int Type Code:	CIWQS_LNDI	**Longitude:**	-117.395499
Program ID:	204473	**Coord Name:**	
Latitude:	34.566560	**Ref Point Type Desc:**	Unknown

21	4 of11	W	0.13 / 671.18	2,917.88 / 11	TPS TECHNOLOGIES INC. 12328 HIBISCUS AVENUE ADELANTO CA 92301	EMISSIONS

Source:

1993 Criteria Data

Facility ID:	50201188	**CERR Code:**	
Facility SIC Code:	4959	**TOGT:**	.1
CO:	36	**ROGT:**	.1
Air Basin:	MD	**COT:**	1.9
District:	MOJ	**NOXT:**	2.6
COID:	SBD	**SOXT:**	.9
DISN:	MOJAVE DESERT AQMD	**PMT:**	4.3
CHAPIS:		**PM10T:**	4.3

1993 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4959	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

1995 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

1995 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1996 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

1996 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1997 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

1997 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	

Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CERR Code:

1998 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

1998 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1999 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

1999 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2000 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.1
CO:	36	***ROGT:***	.1
Air Basin:	MD	***COT:***	22.8
District:	MOJ	***NOXT:***	20.2
COID:	SBD	***SOXT:***	8.3
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.6
CHAPIS:		***PM10T:***	6.6

2000 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2001 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.51
CO:	36	***ROGT:***	.25
Air Basin:	MD	***COT:***	17.69
District:	MOJ	***NOXT:***	15.67
COID:	SBD	***SOXT:***	1.36
DISN:	MOJAVE DESERT AQMD	***PMT:***	5.15
CHAPIS:	Y	***PM10T:***	1.55

2001 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	Y
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2002 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.51
CO:	36	***ROGT:***	.248093
Air Basin:	MD	***COT:***	17.69
District:	MOJ	***NOXT:***	15.67
COID:	SBD	***SOXT:***	1.36
DISN:	MOJAVE DESERT AQMD	***PMT:***	5.15
CHAPIS:	Y	***PM10T:***	1.545

2002 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	Y
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2003 Criteria Data

Facility ID:	50201188	***CERR Code:***	

Facility SIC Code:	4953	**TOGT:**	1.51
CO:	36	**ROGT:**	.25
Air Basin:	MD	**COT:**	17.69
District:	MOJ	**NOXT:**	15.67
COID:	SBD	**SOXT:**	1.36
DISN:	MOJAVE DESERT AQMD	**PMT:**	5.15
CHAPIS:	Y	**PM10T:**	1.55

2003 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2004 Criteria Data

Facility ID:	50201188	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	1.462
CO:	36	**ROGT:**	.2402066
Air Basin:	MD	**COT:**	16.13
District:	MOJ	**NOXT:**	21.17
COID:	SBD	**SOXT:**	20.03
DISN:	MOJAVE DESERT AQMD	**PMT:**	11.14
CHAPIS:	Y	**PM10T:**	3.342

2004 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	2.39		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	50201188	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	1.462
CO:	36	**ROGT:**	.2402066
Air Basin:	MD	**COT:**	16.13
District:	MOJ	**NOXT:**	21.17
COID:	SBD	**SOXT:**	20.03
DISN:	MOJAVE DESERT AQMD	**PMT:**	11.14
CHAPIS:	Y	**PM10T:**	3.342

2005 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	2.39		
Health Risk Asmt:			

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2006 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.462
CO:	36	***ROGT:***	.2402066
Air Basin:	MD	***COT:***	16.13
District:	MOJ	***NOXT:***	21.17
COID:	SBD	***SOXT:***	20.03
DISN:	MOJAVE DESERT AQMD	***PMT:***	11.14
CHAPIS:	Y	***PM10T:***	3.342

2006 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	Y
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	2.39		

Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2007 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.462
CO:	36	***ROGT:***	.2402066
Air Basin:	MD	***COT:***	16.13
District:	MOJ	***NOXT:***	21.17
COID:	SBD	***SOXT:***	20.03
DISN:	MOJAVE DESERT AQMD	***PMT:***	11.14
CHAPIS:	Y	***PM10T:***	3.342

2007 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	Y
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	2.39		

Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2008 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.462
CO:	36	***ROGT:***	.2402066
Air Basin:	MD	***COT:***	16.13
District:	MOJ	***NOXT:***	21.17
COID:	SBD	***SOXT:***	20.03
DISN:	MOJAVE DESERT AQMD	***PMT:***	11.14
CHAPIS:	Y	***PM10T:***	3.342

2008 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	2.39		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2009 Criteria Data

Facility ID:	50201188	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	1.462
CO:	36	**ROGT:**	.2402066
Air Basin:	MD	**COT:**	16.13
District:	MOJ	**NOXT:**	21.17
COID:	SBD	**SOXT:**	20.03
DISN:	MOJAVE DESERT AQMD	**PMT:**	11.14
CHAPIS:	Y	**PM10T:**	3.342

2009 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	Y
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	2.39		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2010 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	1.19		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2011 Criteria Data

Facility ID:	50201188	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	1.25366
CO:	36	**ROGT:**	.205976338
Air Basin:	MD	**COT:**	24.216
District:	MOJ	**NOXT:**	21.002
COID:	SBD	**SOXT:**	1.36
DISN:	MOJAVE DESERT AQMD	**PMT:**	6.722
CHAPIS:		**PM10T:**	2.0166

2011 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TS: 1.19
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2012 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.25366
CO:	36	***ROGT:***	.205976338
Air Basin:	MD	***COT:***	24.216
District:	MOJ	***NOXT:***	21.002
COID:	SBD	***SOXT:***	1.36
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.722
CHAPIS:		***PM10T:***	2.0166

2012 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		

TS: 1.19
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2013 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	1.25366
CO:	36	***ROGT:***	.205976338
Air Basin:	MD	***COT:***	24.216
District:	MOJ	***NOXT:***	21.002
COID:	SBD	***SOXT:***	1.36
DISN:	MOJAVE DESERT AQMD	***PMT:***	6.722
CHAPIS:		***PM10T:***	2.0166

2013 Toxic Data

Facility ID:	50201188	***COID:***	SBD
Facility SIC Code:	4953	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		

TS: 1.19
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	5 of11	W	0.13 / 671.18	2,917.88 / 11	SOIL SAFE OF CALIFORNIA, INC 12328 HIBISCUS AVENUE ADELANTO CA 92301	EMISSIONS

Source:

2017 Criteria Data

Facility ID:	50201188	***CERR Code:***	
Facility SIC Code:	4953	***TOGT:***	.06534
CO:	36	***ROGT:***	.01104246

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Basin:	MD	**COT:**	2.273
District:	MOJ	**NOXT:**	5.871
COID:	SBD	**SOXT:**	.7543
DISN:	MOJAVE DESERT AQMD	**PMT:**	5.794
CHAPIS:		**PM10T:**	1.7382

2017 Toxic Data

Facility ID:	50201188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	3.48		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

21	6 of11	W	0.13 / 671.18	2,917.88 / 11	**SOIL SAFE - ADELANTO** **12328 HIBISCUS AVENUE** **ADELANTO CA 92301**	**EMISSIONS**

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2018 Criteria Data

Facility ID:	1188	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	.06534
CO:	36	**ROGT:**	.01104246
Air Basin:	MD	**COT:**	2.273
District:	MOJ	**NOXT:**	5.871
COID:	SBD	**SOXT:**	.7543
DISN:	MOJAVE DESERT AQMD	**PMT:**	5.794
CHAPIS:		**PM10T:**	1.7382

2018 Toxic Data

Facility ID:	1188	**COID:**	SBD
Facility SIC Code:	4953	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	3.48		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	1188	**ROGT:**	.05815564
District:	MOJ	**COT:**	2.020793
Facility SIC Code:	4953	**NOXT:**	5.221667
CO ID:	SBD	**SOXT:**	.6710266
DISN:	MOJAVE DESERT AQMD		
PM10T:	17.19988		
TOGT:	.3441162130177514792899408284023668639053		
PMT:	57.332933333333333333333333333333333333333		

2019 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Faccility ID:	1188	**CERR Code:**	
District:	MOJ	**TS:**	.28
Facility SIC Code:	4953	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	1188	**ROGT:**	.05815564
District:	MOJ	**COT:**	2.020793
Facility SIC Code:	4953	**NOXT:**	5.221667
CO ID:	SBD	**SOXT:**	.6710266
DISN:	MOJAVE DESERT AQMD		
TOGT:	.3441162130177514792899408284023668639053		
PMT:	57.33293333333333333333333333333333333333		
PM10T:	17.19988		

2020 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	1188	**CHERR Code:**	
District:	MOJ	**TS:**	.28
Facility SIC Code:	4953	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Toxic Data

Co:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Facility ID:	1188	**Cerr Code:**	
District:	MOJ	**TS:**	.28
Facility SIC Code:	4953	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	**CHAPIS:**	
Air Basin:	MD	**Cerr Code:**	
Facility ID:	1188	**ROGT:**	.05815564
District:	MOJ	**COT:**	2.020793
Facility SIC Code:	4953	**NOXT:**	5.221667
CO ID:	SBD	**SOXT:**	.6710266
DISN:	MOJAVE DESERT AQMD		
TOGT:	.3441162130177514792899408284023668639053		
PMT:	57.33293333333333333333333333333333333333		
PM10T:	17.19988		

2023 Pollutant Data

Facility ID:	1188	**CO:**	36
Facility SIC Code:	4953	**CO ID:**	SBD
CERR Code:		**Air Basin:**	MD
CHAPIS:		**District:**	MOJ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ROGT:	.01183	**NOXT:**	2.76
COT:	3.65	**SOXT:**	.67
DISN:	MOJAVE DESERT AQMD		
TOGT:	.07		
PMT:	2.46		
PM10T:	.738		
Source:	2023 Pollutant Data		

2022 Criteria Data

Facility ID:	1188	**District:**	MOJ
Facility SIC Code:	4953	**Air Basin:**	MD
Cerr Code:		**Co:**	36
CHAPIS:		**CO ID:**	SBD
ROGT:	.01183	**NOXT:**	2.76
COT:	3.65	**SOXT:**	.67
DISN:	MOJAVE DESERT AQMD		
TOGT:	.07		
PMT:	2.46		
PM10T:	.738		
Source:	2022 Criteria Data		

2022 Toxic Data

Facility ID:	1188	**CO:**	36
Facility SIC Code:	4953	**Air Basin:**	MD
CHERR Code:		**District:**	MOJ
CHAPIS:		**COID:**	SBD
Health Risk Asmt:		**TS:**	1.01
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2022 Toxic Data		

2023 Toxic Data

Facility ID:	1188	**CO:**	36
Facility SIC Code:	4953	**COID:**	SBD
CHERR Code:		**Air Basin:**	MD
CHAPIS:		**District:**	MOJ
TS:	1.01		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2023 Toxic Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
21	7 of11	W	0.13 / 671.18	2,917.88 / 11	**TPS TECHNOLOGIES INC** **12328 HIBISCUS RD** **ADELANTO CA 923011700**	HWP

Envirostor ID: CAL930834777
Site History:

This facility submitted an application for standardized permit. The permit was never issued and they never operated under STD permit.

Quarterly Update:

This facility submitted an application for standardized permit. The permit was never issued and they never operated under STD permit.

Facilities Details

Estor/EPA ID:	CAL930834777	**Site Code:**	

Program Type:	HAZ WASTE - Standardized	**APN:**	
Program Type1:	HAZARDOUS WASTE FACILITY	**Assembly District:**	39
Status:	CLOSED	**Census Tract:**	6071009116
Site Facility Name:	TPS TECHNOLOGIES INC	**Funding:**	
Site Type:	CLOSED	**Office:**	
Address Description:	12328 HIBISCUS RD	**Project Manager:**	
City:	ADELANTO	**Special Program:**	
County:	SAN BERNARDINO	**Supervisor:**	
Zip:	923011700	**Senate District:**	23
Acres:			
Public Participation Specialis:			
CalEnviroScreen Score:	75-80%		
National Priorities List:			
Past Use that Caused Contam:			
Permit Renewal Lead:			
Cleanup Oversight Agencies:			
Cleanup Status:			
Potential Cont of Conc:			
Potential Media Affected:			
School District:			
Summary Link:	https://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CAL930834777		

Units Undergoing Closure

Event Description:	ISSUE CLOSURE VERIFICATION
Date:	7/9/2019
Unit:	
Doc Link:	https://www.envirostor.dtsc.ca.gov/public/hwmp_final_documents?global_id=CAL930834777&link_key=1726&document_category=CLOSURE+VERIFICATION&event_description=ISSUE+CLOSURE+VERIFICATION+&mytype=pa
Activity Type:	Units Undergoing Closure - Completed Activities

Search Results Details

Program Type:	HAZ WASTE - Standardized
Site Code:	540028
Status:	CLOSED
Status Date:	
CalEnviroScreen Score:	75-80%
Supervisor:	
Pm:	
Office:	CYPRESS, GEOLOGY CAL SUPPORT
Branch Chief:	
Address Description:	12328 HIBISCUS RD
Site Facility Name:	TPS TECHNOLOGIES INC
City:	ADELANTO
County:	SAN BERNARDINO
Zip:	923011700
Latitude:	34.566911
Longitude:	-117.395828

Haz Waste Facility Details

Address:	12328 HIBISCUS RD	**Permit Effec Dt:**	
City:	ADELANTO	**Permit Exp Date:**	
County:	SAN BERNARDINO	**Permit Type:**	Standardized
Facility Size:		**Project Manager:**	
Facility Status:	CLOSED	**Project Mnger Lead:**	
Facility Type:	Historical - Non-Operating	**Pub Info Officer:**	
Latitude:	34.566911	**Senate District:**	23
Longitude:	-117.395828	**Supervisor:**	
Zip:	923011700	**Total Actual Hours:**	
Site Code:	540028	**Total Planned Amt:**	
State :	CA	**Total Planned Hrs:**	
Assembly District:	39		
Facility Name:	TPS TECHNOLOGIES INC		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Public Participation Specialis:
CalEnviroScreen Score: 81-85%
Commercial Offsite Facility Ty:

21	8 of11	W	0.13 / 671.18	2,917.88 / 11	SOIL SAFE - ADELANTO SOIL RECYCLING CENTER 12328 HIBISCUS AVE ADELANTO CA 92301	LDS

Global ID: L10008643443
Facility ID: L10008643443
Cleanup Status: OPEN - OPERATING
Site Facility Type: LAND DISPOSAL SITE
Census Tract (SRCH): 6071009116
Address: 12328 HIBISCUS AVE
City: ADELANTO
County: San Bernardino
State: CA
Zip: 92301

RWQCB Region: LAHONTAN RWQCB (REGION 6V)
Longitude: -117.395399
Latitude: 34.567492
Site Fac Type (SRCH): LAND DISPOSAL SITE

GeoTracker Sites Data Download – Site Details

RB Case No: 6B369107002
Loc Case No:
Status: Open - Operating
Status Date: 1/1/1965
Begin Date:
Case Type: Land Disposal Site
Cal Enviroscreen:
Qty Released Gallons:
CUF Case:
EPA Region: 9
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Case Worker: AT
Local Agency:
File Location:
Potential COC:
Military DoD Site: No
Leak Reported Dt:
No Further Action Dt:
Potential Media of Concern:
How Discovered:
How Discovered Description:
Stop Method:
Stop Description:
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name: Upper Mojave River Valley (6-042)
Disadvantaged Community: Severely Disadvantaged Community
Discharge Cause:
Coordinate Source: Google Geocode
Discharge Source:
Facility Project Sub Type: Title 27 - Municipal Solid Waste Landfill
Calenviroscreen 3 Score: 81-85%
Calenviroscreen 4 Score: 75-80%
Claim No:
Claim Status:
Site History:

GeoTracker Sites Data Download - Reg Activity

Date: 2025-07-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2025-06-12 00:00:00

Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2025-04-23 00:00:00
Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2025-04-22 00:00:00
Action: Annual Estimation Letter
Action Type: ENFORCEMENT

Date: 2025-04-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2025-04-01 00:00:00
Action: Letter - Notice
Action Type: ENFORCEMENT

Date: 2025-01-31 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2025-01-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2024-12-16 00:00:00
Action: Email Correspondence
Action Type: ENFORCEMENT

Date: 2024-10-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2024-09-13 00:00:00
Action: Email Correspondence
Action Type: ENFORCEMENT

Date: 2024-09-04 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2024-08-03 00:00:00
Action: Email Correspondence
Action Type: ENFORCEMENT

Date: 2024-07-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2024-04-10 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2024-01-25 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2024-01-11 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2023-12-13 00:00:00
Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2023-11-20 00:00:00
Action: Annual Estimation Letter

Action Type: ENFORCEMENT

Date: 2023-10-13 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2023-08-22 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2023-07-13 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2023-04-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2023-01-23 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2023-01-13 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2022-12-27 00:00:00
Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2022-12-20 00:00:00
Action: Annual Estimation Letter
Action Type: ENFORCEMENT

Date: 2022-10-13 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2022-07-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2022-04-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2022-01-21 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2022-01-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2021-12-12 00:00:00
Action: Annual Estimation Letter
Action Type: ENFORCEMENT

Date: 2021-10-13 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2021-07-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2021-04-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2021-01-15 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2021-01-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2020-10-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2020-07-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2020-04-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2020-01-14 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2020-01-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2019-10-21 00:00:00
Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2019-10-15 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2019-10-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2019-10-01 00:00:00
Action: Staff Letter
Action Type: ENFORCEMENT

Date: 2019-08-14 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2019-07-16 00:00:00
Action: Email Correspondence
Action Type: RESPONSE

Date: 2019-07-12 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2019-06-12 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2019-04-12 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2019-02-13 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2019-01-15 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2019-01-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2018-10-26 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2018-10-12 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2018-07-12 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2018-05-24 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2018-04-12 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2018-02-14 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2018-01-11 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2018-01-11 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2017-11-09 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

Date: 2017-10-11 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2017-09-14 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2017-07-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2017-07-25 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2017-06-02 00:00:00
Action: Site Visit / Inspection / Sampling
Action Type: ENFORCEMENT

Date: 2017-04-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2017-04-25 00:00:00

Action: Financial Assurance
Action Type: RESPONSE

Date: 2017-04-24 00:00:00
Action: Email Correspondence
Action Type: ENFORCEMENT

Date: 2017-03-28 00:00:00
Action: Letter - Notice
Action Type: ENFORCEMENT

Date: 2017-02-08 00:00:00
Action: Technical Correspondence / Assistance / Other
Action Type: ENFORCEMENT

Date: 2016-07-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2016-04-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2016-01-30 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2016-01-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2016-01-27 00:00:00
Action: Monitoring Report - Annually
Action Type: RESPONSE

Date: 2016-01-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2015-10-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2015-10-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2015-07-30 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2015-04-15 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 2015-04-14 00:00:00
Action: Monitoring Report - Quarterly
Action Type: RESPONSE

Date: 1994-02-10 00:00:00
Action: Amendment to Order
Action Type: ENFORCEMENT

Date: 1991-11-14 00:00:00
Action: Waste Discharge Requirements - #6-91-935
Action Type: ENFORCEMENT

Date: 1991-10-11 00:00:00
Action: Other Report / Document

Action Type: RESPONSE

Date: 1991-06-10 00:00:00
Action: Other Report / Document
Action Type: RESPONSE

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker - Primary Caseworker
Contact Name: ASHLEY TAYLOR
Organization Name: LAHONTAN RWQCB (REGION 6V)
Address: 15095 Amargosa Road, Bldg 2 - Suite 210
City: VICTORVILLE
Email: ashley.taylor@waterboards.ca.gov
Phone No: 7602434350

GeoTracker Search - Facilities

Site Facility Name: SOIL SAFE - ADELANTO SOIL RECYCLING CENTER
Site Facility Type: LAND DISPOSAL SITE
Cleanup Status: OPEN - OPERATING
Project Status:
Potential COC: NONE SPECIFIED
WDR Place Type:
Wdr File No:
Wdr Order No:
Address: 12328 HIBISCUS AVE
City: ADELANTO
Zip: 92301
County: SAN BERNARDINO
Cuf Claim No:
CUF Priority Assig:
CUF Amount Paid:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=L10008643443
Cleanup Status Detail: OPEN - OPERATING AS OF 1/1/1965
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=L10008643443&tabname=regulatoryhistory
Potential Media of Concern: NONE SPECIFIED
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Facility Type: TITLE 27 - MUNICIPAL SOLID WASTE LANDFILL
Composting Method:
Gndwater Monitoring Frequen:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 6B369107002
CASE MANAGER: ASHLEY TAYLOR
File Location:
Site History:

No site history available

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/15/2025
Received Issue Date: 7/15/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6152169
Title Description Comment: Q2 2025

Action Type: Other Regulatory Actions

Action: Staff Letter
Action Date: 6/12/2025
Received Issue Date: 6/12/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6635524&temptable=ENFORCEMENT
Title Description Comment: Return of Financial Assurances

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 4/23/2025
Received Issue Date: 4/23/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6629126&temptable=ENFORCEMENT
Title Description Comment: Acceptance of Amended Closure and Post Closure Cost Estimates

Action Type: Other Regulatory Actions
Action: Annual Estimation Letter
Action Date: 4/22/2025
Received Issue Date: 4/22/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6629035&temptable=ENFORCEMENT
Title Description Comment: Soil Safe Updated Closure and Post Closure Cost Estimate

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/15/2025
Received Issue Date: 4/15/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6145749
Title Description Comment: Q1 2025

Action Type: Notices
Action: Letter - Notice
Action Date: 4/1/2025
Received Issue Date: 4/1/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6623781&temptable=ENFORCEMENT
Title Description Comment: Soil Safe Updated FA delivered to office 4.1.2025

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/31/2025
Received Issue Date: 1/31/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6140132
Title Description Comment: Annual Report 2024

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/15/2025
Received Issue Date: 1/15/2025
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6139086
Title Description Comment: Q4 2024

Action Type: Other Regulatory Actions
Action: Email Correspondence
Action Date: 12/16/2024
Received Issue Date: 12/16/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6614342&temptable=ENFORCEMENT
Title Description Comment: Update to FA and Bond Increase Mechanism

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/15/2024
Received Issue Date: 10/15/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6131698
Title Description Comment: Q3 2024

Action Type: Other Regulatory Actions
Action: Email Correspondence

Action Date: 9/13/2024
Received Issue Date: 9/13/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6603326&temptable=ENFORCEMENT
Title Description Comment: Soil Unloading Pad Photograph

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 9/4/2024
Received Issue Date: 9/4/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6601797&temptable=ENFORCEMENT
Title Description Comment: Complaint and Compliance Inspection 9.4.24

Action Type: Other Regulatory Actions
Action: Email Correspondence
Action Date: 8/3/2024
Received Issue Date: 8/3/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6599099&temptable=ENFORCEMENT
Title Description Comment: Barstow 4.9 Earthquake Inquiry and Response

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/15/2024
Received Issue Date: 7/15/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6124624
Title Description Comment: Q2 2024

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/10/2024
Received Issue Date: 4/10/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6117650
Title Description Comment: Q1 2024

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/25/2024
Received Issue Date: 1/25/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6112490
Title Description Comment: 2023 Annual

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/11/2024
Received Issue Date: 1/11/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6111626
Title Description Comment: Q4 2023

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/13/2023
Received Issue Date: 12/13/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6565877&temptable=ENFORCEMENT
Title Description Comment: Bond Acceptance Letter

Action Type: Other Regulatory Actions
Action: Annual Estimation Letter
Action Date: 11/20/2023
Received Issue Date: 11/20/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6565169&temptable=ENFORCEMENT
Title Description Comment: USFIC Closure & Post Closure bond Letter

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/13/2023

Received Issue Date: 10/13/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6106324
Title Description Comment: Q3 2023

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 8/22/2023
Received Issue Date: 8/22/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6552264&temptable=ENFORCEMENT
Title Description Comment: Field Inspection

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/13/2023
Received Issue Date: 7/13/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6100716
Title Description Comment: Q2 2023

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/14/2023
Received Issue Date: 4/14/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6094270
Title Description Comment: Q1 2023

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/23/2023
Received Issue Date: 1/23/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6088832
Title Description Comment: 2022 Annual

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/13/2023
Received Issue Date: 1/13/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6088021
Title Description Comment: Q4 2022

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/27/2022
Received Issue Date: 12/27/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6519817&temptable=ENFORCEMENT
Title Description Comment: Bond Acceptance Letter

Action Type: Other Regulatory Actions
Action: Annual Estimation Letter
Action Date: 12/20/2022
Received Issue Date: 12/20/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6519579&temptable=ENFORCEMENT
Title Description Comment: USFIC Closure & Post Closure bond Letter

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/13/2022
Received Issue Date: 10/13/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6081476
Title Description Comment: Q 3 2022

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/15/2022
Received Issue Date: 7/15/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6076453
Title Description Comment: Q2 2022

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/14/2022
Received Issue Date: 4/14/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6071356
Title Description Comment: Q1 2022

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/21/2022
Received Issue Date: 1/21/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6064976
Title Description Comment: 2021 Annual

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2022
Received Issue Date: 1/14/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6064382
Title Description Comment: Q4 2021

Action Type: Other Regulatory Actions
Action: Annual Estimation Letter
Action Date: 12/12/2021
Received Issue Date: 12/12/2021
Doc Link:
Title Description Comment: Bond Updates From Aspen to Fire Insurance Change 2021

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/13/2021
Received Issue Date: 10/13/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6059039
Title Description Comment: Q3 2021

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/15/2021
Received Issue Date: 7/15/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6054069
Title Description Comment: Q2 2021

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/15/2021
Received Issue Date: 4/15/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6048505
Title Description Comment: Q1 2021

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/15/2021
Received Issue Date: 1/15/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6040983
Title Description Comment: Annual 2020

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2021
Received Issue Date: 1/14/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6040982
Title Description Comment: Q4 2020

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/14/2020
Received Issue Date: 10/14/2020
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6034059

Title Description Comment:	Q3 2020
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	7/14/2020
Received Issue Date:	7/14/2020
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6027628
Title Description Comment:	2nd Quarter 2020
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	4/14/2020
Received Issue Date:	4/14/2020
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6020406
Title Description Comment:	Q1 2020
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Annually
Action Date:	1/14/2020
Received Issue Date:	1/14/2020
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013980
Title Description Comment:	2019
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	1/14/2020
Received Issue Date:	1/14/2020
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013981
Title Description Comment:	Q4 2019
Action Type:	Other Regulatory Actions
Action:	Staff Letter
Action Date:	10/21/2019
Received Issue Date:	10/21/2019
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6424832&temptable=ENFORCEMENT
Title Description Comment:	Acceptance of Aspen American Insurance Company Surety Bonds Nos. SU61102 and SU61103 and Return of JP Morgan Chase Bank Letters of Credit Nos. TFTS-910366 and TFTS-910365
Action Type:	Response Requested - Other
Action:	Other Report / Document
Action Date:	10/15/2019
Received Issue Date:	10/15/2019
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013353
Title Description Comment:	SAN BERNARDINO COUNTY EHS (LEA) INSPECTION
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	10/14/2019
Received Issue Date:	10/14/2019
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6006667
Title Description Comment:	Q3 2019
Action Type:	Other Regulatory Actions
Action:	Staff Letter
Action Date:	10/1/2019
Received Issue Date:	10/1/2019
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6424833&temptable=ENFORCEMENT
Title Description Comment:	RESPONSE TO SUBMITTAL OF ASPEN AMERICAN INSURANCE COMPANY SURETY BONDS NOS. SU61102 AND SU61103
Action Type:	Response Requested - Other
Action:	Other Report / Document
Action Date:	8/14/2019
Received Issue Date:	8/14/2019
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013350
Title Description Comment:	SAN BERNARDINO COUNTY EHS (LEA) INSPECTION

Action Type: Response Requested - Other
Action: Email Correspondence
Action Date: 7/16/2019
Received Issue Date: 7/16/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013355
Title Description Comment: Emergency Response and Contact Information

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/12/2019
Received Issue Date: 7/12/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5998820
Title Description Comment: Q2 2019

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 6/12/2019
Received Issue Date: 6/12/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5998742
Title Description Comment: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/12/2019
Received Issue Date: 4/12/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5990492
Title Description Comment: Q1 2019

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 2/13/2019
Received Issue Date: 2/13/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6013351
Title Description Comment: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/15/2019
Received Issue Date: 1/15/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5983055
Title Description Comment: 2018

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2019
Received Issue Date: 1/14/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5983054
Title Description Comment: Q4 Soil Safe of California

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 10/26/2018
Received Issue Date: 10/26/2018
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6375208&temptable=ENFORCEMENT
Title Description Comment: San Bernardino County EHS (LEA) Inspection

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/12/2018
Received Issue Date: 10/12/2018
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5976918
Title Description Comment: Third Quarter 2018 Monitoring Report

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/12/2018
Received Issue Date: 7/12/2018
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5969965

Title Description Comment:	Second Quarter 2018 Monitoring Report
Action Type:	Response Requested - Other
Action:	Other Report / Document
Action Date:	5/24/2018
Received Issue Date:	5/24/2018
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5998740
Title Description Comment:	SAN BERNARDINO COUNTY EHS (LEA) INSPECTION
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	4/12/2018
Received Issue Date:	4/12/2018
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5962010
Title Description Comment:	First Quarter 2018 Monitoring Report
Action Type:	Response Requested - Other
Action:	Other Report / Document
Action Date:	2/14/2018
Received Issue Date:	3/1/2018
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5958608
Title Description Comment:	San Bernardino County Environmental Health Services Routine Inspection Report.
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	1/11/2018
Received Issue Date:	1/11/2018
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5952183
Title Description Comment:	Fourth Quarter 2017 Monitoring Report - Review In Progress
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Annually
Action Date:	1/11/2018
Received Issue Date:	1/11/2018
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5952184
Title Description Comment:	Annual 2017 Monitoring Report
Action Type:	Response Requested - Other
Action:	Other Report / Document
Action Date:	11/9/2017
Received Issue Date:	11/9/2017
Doc Link:	
Title Description Comment:	San Bernardino County Environmental Health Services Routine Inspection Report.
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	10/11/2017
Received Issue Date:	10/11/2017
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5946407
Title Description Comment:	Third Quarter 2017 Monitoring Report
Action Type:	Other Regulatory Actions
Action:	Site Visit / Inspection / Sampling
Action Date:	9/14/2017
Received Issue Date:	9/14/2017
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents? global_id=L10008643443&enforcement_id=6338587&temptable=ENFORCEMENT
Title Description Comment:	San Bernardino County Environmental Health Services Routine Inspection Report.
Action Type:	Response Requested - Reports
Action:	Monitoring Report - Quarterly
Action Date:	7/30/2017
Received Issue Date:	7/13/2017
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5933888
Title Description Comment:	Second Quarter 2017 Monitoring Report
Action Type:	Other Regulatory Actions
Action:	Site Visit / Inspection / Sampling
Action Date:	7/25/2017

Received Issue Date: 7/25/2017
Doc Link:
Title Description Comment: Site Inspection Compliance inspection. Facility closed for maintenance. Yard was swept/clean. Storm water down drain clogged, Site manager agreed to clear drain that day. No violations noted. Staff evaluated site for updated financial assurances.

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 6/2/2017
Received Issue Date: 6/2/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6324226&temptable=ENFORCEMENT
Title Description Comment: San Bernardino County Environmental Health Services Routine Inspection Report

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/30/2017
Received Issue Date: 4/14/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5933887
Title Description Comment: First Quarter 2017 Monitoring Report

Action Type: Response Requested - Other
Action: Financial Assurance
Action Date: 4/25/2017
Received Issue Date: 4/25/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5919005
Title Description Comment: Extension Request; April 21, 2017

Action Type: Other Regulatory Actions
Action: Email Correspondence
Action Date: 4/24/2017
Received Issue Date: 4/24/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6319243&temptable=ENFORCEMENT
Title Description Comment: Financial Assurance Cost Estimate Extension Request Acceptance; April 21, 2017

Action Type: Notices
Action: Letter - Notice
Action Date: 3/28/2017
Received Issue Date: 3/28/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6317981&temptable=ENFORCEMENT
Title Description Comment: San Bernardino County, Department of Public Health Environmental Health Services Inspection Report

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/8/2017
Received Issue Date: 2/8/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6311297&temptable=ENFORCEMENT
Title Description Comment: request update closure costs, 2016 annual self-monitoring report, Adelanto regional soil recycling facility, san Bernardino county Water Board staff response to requested 1-month extension to submit FA cost estimates. New Due Date July 1, 2017.

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/8/2017
Received Issue Date: 2/8/2017
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6311302&temptable=ENFORCEMENT
Title Description Comment: unacceptable replacement financial assurance documents: closure and post-closure costs, Adelanto Regional Soil Recycling Center, San Bernardino County please see referenced letter dated 2/8/2017: request updated closure costs, 2016 Annual self-monitoring report.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 7/30/2016
Received Issue Date: 7/13/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5896214
Title Description Comment: 2nd Quarter 2016 Monitoring Report - No violations of the WDR or MRP were observed.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/30/2016
Received Issue Date: 4/14/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5889278
Title Description Comment: 1st Quarter 2016 Self Monitoring Report - Violations of Board Order 91-935A1 were not observed during the reporting period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/30/2016
Received Issue Date: 1/14/2016
Doc Link:
Title Description Comment: 4th Quarter 2015 Self Monitoring Report - No violations of Board Order 91-935A1 occurred during the reporting period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/30/2016
Received Issue Date: 1/29/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5889190
Title Description Comment: 2015 Annual Monitoring Report - No violations of Board Order 91-935A1 occurred during the reporting period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Annually
Action Date: 1/27/2016
Received Issue Date: 1/27/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096953
Title Description Comment: Annual 2015

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2016
Received Issue Date: 1/14/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096951
Title Description Comment: Q4 2015 Monitoring Report Part 2

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2016
Received Issue Date: 1/14/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096950
Title Description Comment: Q4 2015 Monitoring Report Part 1

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 1/14/2016
Received Issue Date: 1/14/2016
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096952
Title Description Comment: Q4 2015 Monitoring Report Part 3

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/30/2015
Received Issue Date: 10/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5874028
Title Description Comment: 3rd Quarter 2015 Self Monitoring Report - No violations of the WDR or MRP were observed for the reporting period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 10/14/2015
Received Issue Date: 10/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096949
Title Description Comment: 3rd Quarter Report 2015

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly

Action Date: 7/30/2015
Received Issue Date: 7/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5848422
Title Description Comment: 2nd Quarter 2015 Self Monitoring Report - No violations of the WDR or MRP occured during the reporting period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/15/2015
Received Issue Date: 4/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5842359
Title Description Comment: 1st Quarter 2015 Self Monitoring Report - No violations occured during the first quarter 2015 monitoring period.

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/14/2015
Received Issue Date: 4/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096946
Title Description Comment: 1st Quarter Monitoring Report 2015 Part 1

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/14/2015
Received Issue Date: 4/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096947
Title Description Comment: 1st Quarter 2015 Part 2

Action Type: Response Requested - Reports
Action: Monitoring Report - Quarterly
Action Date: 4/14/2015
Received Issue Date: 4/14/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=6096948
Title Description Comment: 1st Quarter 2015 Part 3

Action Type: Enforcement/Orders
Action: Amendment to Order
Action Date: 2/10/1994
Received Issue Date: 2/10/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6246213&temptable=ENFORCEMENT
Title Description Comment: Amended Board Order No. 91-935A1

Action Type: Enforcement/Orders
Action: Waste Discharge Requirements - #6-91-935
Action Date: 11/14/1991
Received Issue Date: 11/14/1991
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6246212&temptable=ENFORCEMENT
Title Description Comment: Waste Discharge Requirements for Adelanto Soil Recycling Center

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 10/11/1991
Received Issue Date: 10/11/1991
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5885659
Title Description Comment: Preliminary hydrogeologic investigation TPS Technologies Incorporated proposed soil recycleing facility Adelanto, California

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date: 6/10/1991
Received Issue Date: 6/10/1991
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=L10008643443&doc_id=5886207
Title Description Comment: TPS Technologies Inc. Southern California Regional Soil Recycling Center East of Adelanto Road - Report of Waste Discharge

GeoTracker Search - Documents

Title: Q1 2021

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7731209516/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/15/2021
Size: 28,946 KB

Title: SAN BERNARDINO COUNTY ENVIRONMENTAL HEALTH SERVICES ROUTINE INSPECTION REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6324226
Type: SITE VISIT / INSPECTION / SAMPLING
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 6/2/2017
Size:

Title: Q 3 2022
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5975594282/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/13/2022
Size: 70,220 KB

Title: EXTENSION REQUEST
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6758192598/L10008643443.PDF
Type: FINANCIAL ASSURANCE
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Site Documents
Document Date: 4/25/2017
Size: 1,248 KB

Title: Q3 2024
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4742019534/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/15/2024
Size: 51,018 KB

Title: 3RD QUARTER REPORT 2015
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4229288458/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/14/2015
Size: 63,950 KB

Title: 1ST QUARTER MONITORING REPORT 2015 PART 1
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8824744522/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2015
Size: 75,934 KB

Title: 2021 ANNUAL
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9835598289/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/21/2022

Size: 4,568 KB

Title: 2019
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1846365153/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2020
Size: 4,230 KB

Title: EMERGENCY RESPONSE AND CONTACT INFORMATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=6013355
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 7/16/2019
Size:

Title: ANNUAL 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1581594645/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/15/2021
Size: 4,592 KB

Title: Q1 2017
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4843786835/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2017
Size: 29,803 KB

Title: WB Q1 2016
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5510294318/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2016
Size: 14,792 KB

Title: Q2 2021
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6034793317/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/15/2021
Size: 32,509 KB

Title: ANNUAL MONITORING REPORT 2014
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1071901440/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/15/2015
Size: 1,806 KB

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=6013350
Type: OTHER REPORT / DOCUMENT
Submitted:

Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 8/14/2019
Size:

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=5998742
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 6/12/2019
Size:

Title: USFIC CLOSURE & POST CLOSURE BOND LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6565169
Type: ANNUAL ESTIMATION LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 11/20/2023
Size:

Title: TPS TECHNOLOGIES INC. SOUTHERN CALIFORNIA REGIONAL SOIL RECYCLING CENTER EAST OF ADELANTO ROAD - REPORT OF WASTE DISCHARGE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=5886207
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: CHRISTY HUNTER (REGULATOR)
Document Type: Site Documents
Document Date: 6/10/1991
Size:

Title: COMPLAINT AND COMPLIANCE INSPECTION 9.4.24
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6601797
Type: SITE VISIT / INSPECTION / SAMPLING
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 9/4/2024
Size:

Title: FINANCIAL ASSURANCE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9736930549/L10008643443.PDF
Type: CORRESPONDENCE
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Site Documents
Document Date: 6/28/2017
Size: 91 KB

Title: FINANCIAL ASSURANCE COST ESTIMATE EXTENSION REQUEST ACCEPTANCE; APRIL 21, 2017
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6319243
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 4/24/2017
Size:

Title: Q2 2024
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4270829439/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/15/2024
Size: 41,898 KB

Title: 2016 ANNUAL
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8304277420/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/13/2017
Size: 3,397 KB

Title: ACCEPTANCE OF AMENDED CLOSURE AND POST CLOSURE COST ESTIMATES
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6629126
Type: STAFF LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 4/23/2025
Size:

Title: BOND ACCEPTANCE LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6565877
Type: STAFF LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 12/13/2023
Size:

Title: Q2 2025
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8853769242/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/15/2025
Size: 24,027 KB

Title: RETURN OF FINANCIAL ASSURANCES
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6635524
Type: STAFF LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 6/12/2025
Size:

Title: FIELD INSPECTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6552264
Type: SITE VISIT / INSPECTION / SAMPLING
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 8/22/2023
Size:

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=5998740
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 5/24/2018
Size:

Title: Q3 2017
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4059882819/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports

Document Date: 10/11/2017
Size: 36,805 KB

Title: RESPONSE TO SUBMITTAL OF ASPEN AMERICAN INSURANCE COMPANY SURETY BONDS NOS. SU61102 AND SU61103
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6424833
Type: STAFF LETTER
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 10/1/2019
Size:

Title: Q1 2025
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6858798503/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/15/2025
Size: 30,530 KB

Title: Q1 2023
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2447268486/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2023
Size: 36,962 KB

Title: Q3 2018
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9984201252/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/12/2018
Size: 234,322 KB

Title: 1ST QUARTER 2015 PART 2
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4358071506/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2015
Size: 73,259 KB

Title: SAN BERNARDINO COUNTY ENVIRONMENTAL HEALTH SERVICES ROUTINE INSPECTION REPORT. - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=5958608
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 3/1/2018
Size:

Title: WASTE DISCHARGE REQUIREMENTS FOR ADELANTO SOIL RECYCLING CENTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6246212
Type: WASTE DISCHARGE REQUIREMENTS
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 11/14/1991
Size:

Title: ANNUAL REPORT 2024

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9771864712/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/31/2025
Size: 8,458 KB

Title: 2023 ANNUAL
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5297530770/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/25/2024
Size: 4,999 KB

Title: 2022 ANNUAL
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5273503005/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/23/2023
Size: 7,561 KB

Title: Q4 2019
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2093865454/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2020
Size: 47,315 KB

Title: Q3 2016
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5329490363/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/12/2016
Size: 30,635 KB

Title: SAN BERNARDINO COUNTY, DEPARTMENT OF PUBLIC HEALTH ENVIRONMENTAL HEALTH SERVICES INSPECTION REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6317981
Type: LETTER - NOTICE
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 3/28/2017
Size:

Title: Q3 2019
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8768142938/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/14/2019
Size: 35,805 KB

Title: UNACCEPTABLE REPLACEMENT FINANCIAL ASSURANCE DOCUMENTS: CLOSURE AND POST-CLOSURE COSTS, ADELANTO REGIONAL SOIL RECYCLING CENTER, SAN BERNARDINO COUNTY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6311302
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER
Submitted:
Submitted By: CHRISTY HUNTER (REGULATOR), SHELBY BARKER (REGULATOR)

Document Type: Site Documents
Document Date: 2/8/2017
Size:

Title: REQUEST UPDATE CLOSURE COSTS, 2016 ANNUAL SELF-MONITORING REPORT, ADELANTO REGIONAL SOIL RECYCLING FACILITY, SAN BERNARDINO COUNTY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6311297
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER
Submitted:
Submitted By: CHRISTY HUNTER (REGULATOR)
Document Type: Site Documents
Document Date: 2/8/2017
Size:

Title: Q1 2019
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4201403141/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/12/2019
Size: 32,807 KB

Title: 2018
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9644816517/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/15/2019
Size: 1,920 KB

Title: MONITORING AND REPORTING PROGRAM Q2
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5512025952/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/14/2015
Size: 14,701 KB

Title: SOIL SAFE UPDATED CLOSURE AND POST CLOSURE COST ESTIMATE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6629035
Type: ANNUAL ESTIMATION LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 4/22/2025
Size:

Title: Q1 2024
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4388000130/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/10/2024
Size: 37,331 KB

Title: USFIC CLOSURE & POST CLOSURE BOND LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6519579
Type: ANNUAL ESTIMATION LETTER
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 12/20/2022
Size:

Title: ACCEPTANCE OF ASPEN AMERICAN INSURANCE COMPANY SURETY BONDS NOS. SU61102 AND

SU61103 AND RETURN OF JP MORGAN CHASE BANK LETTERS OF CREDIT NOS. TFTS-910366 AND TFTS-910365
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6424832
Type: STAFF LETTER
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 10/21/2019
Size:

Title: Q3 2021
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6723422050/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/13/2021
Size: 30,101 KB

Title: Q4 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2774864912/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2021
Size: 23,070 KB

Title: Q4 SOIL SAFE OF CALIFORNIA
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6982727289/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2019
Size: 32,634 KB

Title: Q4 2017
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1861482620/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/11/2018
Size: 34,742 KB

Title: Q4 2024
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4072402834/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/15/2025
Size: 44,292 KB

Title: Q4 2023
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9403960049/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/11/2024
Size: 45,797 KB

Title: Q2 2022
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5926914870/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)

Document Type: Monitoring Reports
Document Date: 7/15/2022
Size: 46,693 KB

Title: Q2 2017
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9815757453/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/13/2017
Size: 34,535 KB

Title: 2ND QTR 2016 MR
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2306814610/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/13/2016
Size: 14,826 KB

Title: SOIL UNLOADING PAD PHOTOGRAPH
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6603326
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 9/13/2024
Size:

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=6013353
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 10/15/2019
Size:

Title: Q1 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7595042347/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2020
Size: 38,382 KB

Title: Q2 2019
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4892083227/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/12/2019
Size: 52,192 KB

Title: SOIL SAFE UPDATED FA DELIVERED TO OFFICE 4.1.2025
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6623781
Type: LETTER - NOTICE
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 4/1/2025
Size:

Title: BARSTOW 4.9 EARTHQUAKE INQUIRY AND RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6599099

Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 8/3/2024
Size:

Title: Q2 2018
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7616510212/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/12/2018
Size: 44,516 KB

Title: ANNUAL 2017
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9175470173/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/11/2018
Size: 1,838 KB

Title: Q4 2022
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6728640556/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/13/2023
Size: 61,036 KB

Title: 2ND QUARTER 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5239436268/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/14/2020
Size: 30,719 KB

Title: SAN BERNARDINO COUNTY ENVIRONMENTAL HEALTH SERVICES ROUTINE INSPECTION REPORT.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6338587
Type: SITE VISIT / INSPECTION / SAMPLING
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 9/14/2017
Size:

Title: Q4 2015 MONITORING REPORT PART 1
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4563406407/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2016
Size: 78,473 KB

Title: Q4 2015 MONITORING REPORT PART 2
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3271143317/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2016
Size: 75,584 KB

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6375208
Type: SITE VISIT / INSPECTION / SAMPLING
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 10/26/2018
Size:

Title: PRELIMINARY HYDROGEOLOGIC INVESTIGATION TPS TECHNOLOGIES INCORPORATED PROPOSED SOIL RECYCLEING FACILITY ADELANTO, CALIFORNIA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=5885659
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: CHRISTY HUNTER (REGULATOR)
Document Type: Site Documents
Document Date: 10/11/1991
Size:

Title: Q3 2023
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6376113533/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/13/2023
Size: 47,615 KB

Title: UPDATE TO FA AND BOND INCREASE MECHANISM
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6614342
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 12/16/2024
Size:

Title: AMENDED BOARD ORDER NO. 91-935A1
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6246213
Type: AMENDMENT TO ORDER
Submitted:
Submitted By: KERRI A. OKEEFE (REGULATOR)
Document Type: Site Documents
Document Date: 2/10/1994
Size:

Title: Q1 2022
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2323122978/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2022
Size: 43,657 KB

Title: Q4 2016
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4471624970/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/13/2017
Size: 49,626 KB

Title: BOND ACCEPTANCE LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&enforcement_id=6519817
Type: STAFF LETTER
Submitted:

Submitted By: ASHLEY TAYLOR (REGULATOR)
Document Type: Site Documents
Document Date: 12/27/2022
Size:

Title: Q3 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7186663150/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 10/14/2020
Size: 28,406 KB

Title: 1ST QTR 2018
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9965378046/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/12/2018
Size: 28,442 KB

Title: 1ST QUARTER 2015 PART 3
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8561880528/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 4/14/2015
Size: 79,229 KB

Title: Q2 2023
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3425738334/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 7/13/2023
Size: 41,357 KB

Title: Q4 2021
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8365268170/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2022
Size: 34,931 KB

Title: ANNUAL 2015
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5072852849/L10008643443.PDF
Type: MONITORING REPORT - ANNUALLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/27/2016
Size: 8,588 KB

Title: Q4 2015 MONITORING REPORT PART 3
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8746065139/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/14/2016
Size: 58,167 KB

Title: MONITORING REPORT Q4 2014

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7398383855/L10008643443.PDF
Type: MONITORING REPORT - QUARTERLY
Submitted:
Submitted By: SOIL SAFE OF CALIFORNIA, INC. (RP)
Document Type: Monitoring Reports
Document Date: 1/15/2015
Size: 10,782 KB

Title: SAN BERNARDINO COUNTY EHS (LEA) INSPECTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=L10008643443&document_id=6013351
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: SHELBY BARKER (REGULATOR)
Document Type: Site Documents
Document Date: 2/13/2019
Size:

21	9 of11	W	0.13 / 671.18	2,917.88 / 11	SOIL SAFE OF CALIFORNIA INC 12328 HIBISCUS RD ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAL000298752
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	562920
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20200529	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:	P	**Location Latitude:**	34.566586
In Handler Univ:	N	**Location Longitude:**	-117.395578
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		

Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20200604
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	SOIL SAFE OF CALIFORNIA INC
Location Street No:	12328
Location Street1:	HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	BILL BISHOP
Contact Street No:	12328
Contact Street1:	HIBISCUS RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	US
Contact Phone & Ext:	760-246-8001
Contact Fax:	760-246-8004
Contact Email Address:	BBISHOP@SOILSAFE.COM
Contact Title:	
Owner Name:	
Owner Type:	
Owner Seq:	
Operator Name:	SOIL SAFE OF CALIFORNIA INC
Operator Type:	P
Operator Seq:	1
Public Notes:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20200529
Handler Name: SOIL SAFE OF CALIFORNIA INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: SOIL SAFE OF CALIFORNIA INC
Dt Became Current:
Dt Ended Current:
Phone: 760-246-8001
Source Type: Implementer
Street No: 12328
Street1: HIBISCUS RD
Street2:
City: ADELANTO
State: CA
Country: US
Zip: 92301

21	10 of11	W	0.13 / 671.18	2,917.88 / 11	**Soil Safe** **12328 HIBISCUS RD** **ADELANTO CA 92301**	**SANBERN** **CUPA**

Facility ID: FA0006766
Owner Info: SOIL SAFE OF CALIFORNIA, INC.
Mailing Care of: bbishop@gflenv.com
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0006320
Status: ACTIVE
Program Element Code: 4453
Permit Desc: SMALL QUANTITY GENERATOR
To: 10/31/2024
Mailing Address 1: 12328 HIBISCUS DR

Permit ID: PT0017185
Status: ACTIVE
Program Element Code: 4243
Permit Desc: HAZARDOUS MATERIALS 4-10 CHEMICALS
To: 10/31/2024
Mailing Address 1: 12328 HIBISCUS DR

Permit ID: PT0017184
Status: ACTIVE
Program Element Code: 4032
Permit Desc: APSA 10,001-100,000 GAL FAC CAPACITY
To: 10/31/2023
Mailing Address 1: 12328 HIBISCUS DR

Permit ID: PT0006319
Status: INACTIVE
Program Element Code: 4210
Permit Desc: SPECIAL HANDLER
To: 10/31/2005
Mailing Address 1: 12328 HIBISCUS DR

21	11 of11	W	0.13 / 671.18	2,917.88 / 11	**Soil Safe of California, Inc.** **12328 Hibiscus Avenue**	**SWF/LF**

Adelanto CA 92301

SWIS No:	36-AA-0422	***ARB District:***	Mojave Desert
Site ID:	4245	***SWRCB Region:***	Lahontan
EPA Fed Regist ID:	110002413834	***Site Point of Cont:***	Megan Emslander
Site Op Status:	Active	***Site ZIP:***	92301
Regulatory Status:	Notification	***County:***	San Bernardino
Site is Archived:	No	***Latitude:***	34.56694
Absorbed on:		***Longitude:***	-117.39621
Absorbed by:			

Site Inert Debris Eng Fill:	No
Closed Illegal Aband:	No
Closed Illegal Aband Cat:	
Finance Assuran Responsible:	No
Local Government:	Adelanto
Reporting Agency Legal Name:	County of San Bernardino
Reporting Agency Department:	Div. of Environmental Health Services
Enforcing Agency Legal Name:	County of San Bernardino
Enforcing Agency Department:	Div. of Environmental Health Services

Site Owners

Site Type:	Non-Disposal Only
Started On:	
Contact Name:	
Contact First Name:	
Contact Last Name:	
Contact Title:	
Contact Email:	
Contact Phone:	(760) 246-8001
Owner Name:	Soil Safe of California, Inc.
Owner Address:	12328 Hibiscus Rd
Owner City:	Adelanto
Owner State:	CA
Owner Zip Code:	92301

Site Activities (Search Result)

Activity Category:	Transfer/Processing	***Act Regulat Stat:***	Notification
Act Opl Status:	Active		
Site Name:	Soil Safe of California, Inc.		
Activity:	Contaminated Soil Transfer/Processing Operation		

Site Operators

Site Type:	Non-Disposal Only
Started on:	
Contact Name:	
Contact First Name:	
Contact Last Name:	
Contact Title:	
Contact Email:	
Contact Phone:	(760) 246-8001
Operator Name:	Soil Safe of California, Inc.
Operator Address:	dba TPST Soil Recyclers of California 12328 Hibiscus Avenue
Operator City:	Adelanto
Operator State:	CA
Operator Zip:	92301

Site Waste

Site Type:	Non-Disposal Only	***Activity Category:***	Transfer/Processing
Waste Type:	Contaminated Soil	***Act Classification:***	Solid Waste Operation
Activity Oper Stat:	Active	***Act Is Archived:***	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Act Regulat Stat: Notification
Activity: Contaminated Soil Transfer/Processing Operation

22	1 of2	W	0.13 / 683.83	2,917.82 / 11	HIGH DESERT RECYCLING 12325 HIBISCUS RD ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAL000464648
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	D	**NAIC 1:**	425120
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20211130	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.566526
In Handler Univ:	N	**Location Longitude:**	-117.39605
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	D		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal WrkId:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		

Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20211130
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	HIGH DESERT RECYCLING
Location Street No:	
Location Street1:	12325 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	MICHAEL CURRAN
Contact Street No:	
Contact Street1:	1432 E FIRST ST
Contact Street2:	
Contact City:	POMONA
Contact State:	CA
Contact Zip:	91766
Contact Country:	US
Contact Phone & Ext:	909-623-1373
Contact Fax:	909-623-3803
Contact Email Address:	PSMSCRAP@AOL.COM
Contact Title:	
Owner Name:	C&C SCRAP SERVICES INC
Owner Type:	O
Owner Seq:	1
Operator Name:	C&C SCRAP SERVICES INC
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20210809
Handler Name:	HIGH DESERT RECYCLING
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq No: 1
Receive Date: 20211130
Handler Name: HIGH DESERT RECYCLING
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Deactivation
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: C&C SCRAP SERVICES INC
Dt Became Current:
Dt Ended Current:
Phone: 909-623-1373
Source Type: Deactivation
Street No:
Street1: 1432 E FIRST ST
Street2:
City: POMONA
State: CA
Country: US
Zip: 91766

Owner/Operator Ind: Current Owner
Type: Other
Name: C&C SCRAP SERVICES INC
Dt Became Current:
Dt Ended Current:
Phone: 909-623-1373
Source Type: Deactivation
Street No:
Street1: 1432 E FIRST ST
Street2:
City: POMONA
State: CA
Country: US
Zip: 91766

Owner/Operator Ind: Current Operator
Type: Other
Name: MICHAEL CURRAN
Dt Became Current:
Dt Ended Current:
Phone: 909-623-1373
Source Type: Implementer
Street No:
Street1: 1432 E FIRST ST
Street2:
City: POMONA
State: CA
Country:
Zip: 91766

Owner/Operator Ind: Current Owner
Type: Other
Name: C&C SCRAP SERVICES INC
Dt Became Current:
Dt Ended Current:
Phone: 909-623-1373
Source Type: Implementer
Street No:
Street1: 1432 E FIRST ST
Street2:
City: POMONA
State: CA
Country:
Zip: 91766

Historical Handler Details

Receive Dt: 20210809
Generator Code Description: Not a Generator, Verified
Handler Name: HIGH DESERT RECYCLING

22	2 of2	W	0.13 / 683.83	2,917.82 / 11	ADELANTO METAL RECYCLING 12325 HIBISCUS RD ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0014326
Owner Info: NAVARRO, JUAN
Mailing Care of: JUAN NAVARRO
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0025183
Status: INACTIVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Element Code: 4420
Permit Desc: SPECIAL GENERATOR
To: 4/30/2013
Mailing Address 1: 12325 HIBISCUS RD

Permit ID: PT0025182
Status: INACTIVE
Program Element Code: 4210
Permit Desc: SPECIAL HANDLER
To: 4/30/2013
Mailing Address 1: 12325 HIBISCUS RD

23	1 of1	S	0.13 / 697.50	2,929.19 / 22	MOBILE PIPE WRAPPERS & COATERS ADELANTO CA	PFAS IND

Status:	Inactive	**Fac Fips Code:**	06071
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	18090208	**EPA Programs:**	CWA; RCRA
Fac Derived Wbd:	180902080503	**Federal Facility:**	No
Fac Derived Cd113:	08	**Federal Agency:**	-
Fac Derived Cb2010:	060710091164129	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	No
Last Informal Action:	-	**NPDES Flag:**	Yes
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	Yes
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	0	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	80.375	**TRI Reporter:**	-
Fac Pop Den:	876.56	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	SAN BERNARDINO	**Fac Active Flag:**	-
State Other:		**Fac Inspection Count:**	0
Region:	09	**Date Last Inspection:**	-
Latitude:	34.56198	**Days Last Inspection:**	-
Longitude:	-117.38519		

Fac Derived Tribes: -
AIR IDs: -
CAA Permit Types: -
CAA NAICS: -
CAA SICS: -
NPDES IDs: CAZ423192
CWA Permit Types: Non-M
CWA NAICS: -
CWA SICS: 3479
RCRA IDs: CAL000364933
RCRA Permit Types: Other
RCRA NAICS: -
SDWA IDs: -
SDWA System Types: -
SDWA Compliance Status: -
SDWA Snc Flag: No
Fac Collection Meth: ADDRESS MATCHING-HOUSE NUMBER
ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110065163673

Details

Industry: Metal Coating

24	1 of1	S	0.13 / 712.55	2,928.53 / 21	MOBILE COATING SOLUTIONS	PFAS IND

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					ADELANTO CA	

Status:	Unknown	**Fac Fips Code:**	06071
Fac Indian Cntry Flg:	No	**Compliance Status:**	-
Fac Derived Huc:	18090208	**EPA Programs:**	-
Fac Derived Wbd:	180902080503	**Federal Facility:**	No
Fac Derived Cd113:	08	**Federal Agency:**	-
Fac Derived Cb2010:	060710091164129	**Fac Snc Flg:**	No
Fac Informal Count:	0	**AIR Flag:**	No
Last Informal Action:	-	**NPDES Flag:**	No
Formal Action Count:	0	**SDWIS Flag:**	No
Last Formal Action:	-	**RCRAFlag:**	No
Fac Total Penalties:	0	**TRI Flag:**	No
Fac Penalty Count:	-	**GHG Flag:**	No
Date Last Penalty:	-	**TRI IDs:**	-
Last Penalty Amt:	0	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	-	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	80.395	**TRI Reporter:**	-
Fac Pop Den:	873.31	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	-
Fac County:	SAN BERNARDINO	**Fac Active Flag:**	-
State Other:		**Fac Inspection Count:**	0
Region:	09	**Date Last Inspection:**	-
Latitude:	34.562174	**Days Last Inspection:**	-
Longitude:	-117.385236		

Fac Derived Tribes:	-
AIR IDs:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	-
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110071765817

Details

Industry:	Metal Coating

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	1 of1	S	0.13 / 712.56	2,932.24 / 25	MOBILE PIPE WRAPPERS & COATERS	PFAS IND
					ADELANTO CA	

Status:	Active	**Fac Fips Code:**	06071
Fac Indian Cntry Flg:	No	**Compliance Status:**	No Violation Identified
Fac Derived Huc:	18090208	**EPA Programs:**	CAA
Fac Derived Wbd:	180902080503	**Federal Facility:**	No
Fac Derived Cd113:	08	**Federal Agency:**	-
Fac Derived Cb2010:	060710091164111	**Fac Snc Flg:**	No
Fac Informal Count:	1	**AIR Flag:**	Yes
Last Informal Action:	11/17/2021	**NPDES Flag:**	No
Formal Action Count:	1	**SDWIS Flag:**	No
Last Formal Action:	11/17/2021	**RCRAFlag:**	No
Fac Total Penalties:	5000	**TRI Flag:**	No
Fac Penalty Count:	1	**GHG Flag:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Last Penalty:	11/17/2021	**TRI IDs:**	-
Last Penalty Amt:	5000	**TRI Releases Trnsfrs:**	-
Fac Qtrs With Nc:	0	**TRI on Site Releases:**	-
Programs With Snc:	0	**TRI off Site Trnsfrs:**	-
Fac Percent Minority:	80.357	**TRI Reporter:**	-
Fac Pop Den:	901.97	**Fac Imp Water Flg:**	-
Count:	1	**Fac Major Flag:**	Yes
Fac County:	SAN BERNARDINO	**Fac Active Flag:**	Yes
State Other:		**Fac Inspection Count:**	5
Region:	09	**Date Last Inspection:**	7/24/2025
Latitude:	34.56102	**Days Last Inspection:**	205
Longitude:	-117.38524		

Fac Derived Tribes:	-
AIR IDs:	CAMDA00006071M1067
CAA Permit Types:	Major Emissions
CAA NAICS:	339914
CAA SICS:	3479
NPDES IDs:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDs:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDs:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA Snc Flag:	No
Fac Collection Meth:	ADDRESS MATCHING-HOUSE NUMBER
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110014324070

Details

Industry:	Metal Coating

26	1 of1	W	0.15 / 775.78	2,917.89 / 11	**A H TRANSPORTATION GROUP** **12191 HIBISCUS RD** **ADELANTO CA 92301**	**RCRA NON GEN**

Handler ID:	CAL000429595
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	56299
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20170727	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:		**Location Latitude:**	34.566517
In Handler Univ:	Y	**Location Longitude:**	-117.39884
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	2
Short Term Generator:	N
Uni Waste:	Y
Universal Waste Dest Facility:	Y
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20180907
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	A H TRANSPORTATION GROUP
Location Street No:	
Location Street1:	12191 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ANTONIA HENRIQUEZ
Contact Street No:	
Contact Street1:	12191 HIBISCUS RD

Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	
Contact Phone & Ext:	760-605-5814
Contact Fax:	
Contact Email Address:	SANTIGO205@YAHOO.COM
Contact Title:	
Owner Name:	ANTONIA HENRIQUEZ
Owner Type:	O
Owner Seq:	1
Operator Name:	ANTONIA HENRIQUEZ
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20170727
Handler Name:	A H TRANSPORTATION GROUP
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street1:**	12191 HIBISCUS RD
Name:	ANTONIA HENRIQUEZ	**Street2:**	
Dt Became Current:		**City:**	ADELANTO
Dt Ended Current:		**State:**	CA
Phone:	760-605-5814	**Country:**	
Source Type:	Implementer	**Zip:**	92301
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street1:**	12191 HIBISCUS RD
Name:	ANTONIA HENRIQUEZ	**Street2:**	
Dt Became Current:		**City:**	ADELANTO
Dt Ended Current:		**State:**	CA
Phone:	714-605-5814	**Country:**	
Source Type:	Implementer	**Zip:**	92301

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	1 of14	W	0.17 / 898.78	2,920.90 / 14	**SOUTHLAND MIXER SERVICE, INC** **12231 HIBISCUS ROAD** **ADELANTO CA 92301**	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2017 Criteria Data

Facility ID:	159202685	**CERR Code:**	
Facility SIC Code:	3273	**TOGT:**	.00010017074558907228229937393284006829 8236
CO:	36	**ROGT:**	.000088
Air Basin:	MD	**COT:**	.000097
District:	MOJ	**NOXT:**	.0006085
COID:	SBD	**SOXT:**	.000000441

DISN:	MOJAVE DESERT AQMD	**PMT:**	. 00003551307847082494969818913480885311871227
CHAPIS:		**PM10T:**	.0000353

2017 Toxic Data

Facility ID:	159202685	**COID:**	SBD
Facility SIC Code:	3273	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	.16		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	2685	**CERR Code:**	
Facility SIC Code:	3273	**TOGT:**	. 0001001707455890722822993739328400682982236
CO:	36	**ROGT:**	.000088
Air Basin:	MD	**COT:**	.000097
District:	MOJ	**NOXT:**	.0006085
COID:	SBD	**SOXT:**	.000000441
DISN:	MOJAVE DESERT AQMD	**PMT:**	. 00003551307847082494969818913480885311871227
CHAPIS:		**PM10T:**	.0000353

2018 Toxic Data

Facility ID:	2685	**COID:**	SBD
Facility SIC Code:	3273	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	.16		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	2685	**ROGT:**	0
District:	MOJ	**COT:**	0
Facility SIC Code:	3273	**NOXT:**	0
CO ID:	SBD	**SOXT:**	0
DISN:	MOJAVE DESERT AQMD		
PM10T:	0		
TOGT:	0		
PMT:	0		

2019 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Faccility ID:	2685	**CERR Code:**	
District:	MOJ	**TS:**	0

Facility SIC Code: 3273
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
Health Risk Asmt:

2020 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 2685
District: MOJ
Facility SIC Code: 3273
CO ID: SBD
DISN: MOJAVE DESERT AQMD
TOGT: 0
PMT: 0
PM10T: 0
CHAPIS:
CERR Code:
ROGT: 0
COT: 0
NOXT: 0
SOXT: 0

2020 Toxic Data

CO: 36
Air Basin: MD
Facility ID: 2685
District: MOJ
Facility SIC Code: 3273
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
CHERR Code:
TS: 0
Health Risk Asmt:

2021 Toxic Data

Co: 36
Air Basin: MD
Facility ID: 2685
District: MOJ
Facility SIC Code: 3273
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
Cerr Code:
TS: 0
Health Risk Asmt:

2021 Criteria Data

Co: 36
Air Basin: MD
Facility ID: 2685
District: MOJ
Facility SIC Code: 3273
CO ID: SBD
DISN: MOJAVE DESERT AQMD
TOGT: 0
PMT: 0
PM10T: 0
CHAPIS:
Cerr Code:
ROGT: 0
COT: 0
NOXT: 0
SOXT: 0

2023 Pollutant Data

Facility ID: 2685
Facility SIC Code: 3273
CERR Code:
CHAPIS:
ROGT: 0
COT: 0
DISN: MOJAVE DESERT AQMD
TOGT: 0
CO: 36
CO ID: SBD
Air Basin: MD
District: MOJ
NOXT: 0
SOXT: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

PMT: 0
PM10T: 0
Source: 2023 Pollutant Data

2022 Criteria Data

Facility ID: 2685
Facility SIC Code: 3273
Cerr Code:
CHAPIS:
ROGT: 0
COT: 0
DISN: MOJAVE DESERT AQMD
TOGT: 0
PMT: 0
PM10T: 0
Source: 2022 Criteria Data
District: MOJ
Air Basin: MD
Co: 36
CO ID: SBD
NOXT: 0
SOXT: 0

2022 Toxic Data

Facility ID: 2685
Facility SIC Code: 3273
CHERR Code:
CHAPIS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
TS: 0

2023 Toxic Data

Facility ID: 2685
Facility SIC Code: 3273
CHERR Code:
CHAPIS:
TS: 0
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data
CO: 36
COID: SBD
Air Basin: MD
District: MOJ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	2 of14	W	0.17 / 898.78	2,920.90 / 14	LOYAL BROTHERS TRUCK REPAIR INC 12231 HIBISCUS RD ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAL000409594
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer: No
Used Oil Transpor: No

Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	811111
Seq No:	2	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20240823	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:		**Location Latitude:**	34.565337
In Handler Univ:	Y	**Location Longitude:**	-117.394988
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: CA
State Waste Generator: 2
Short Term Generator: N
Uni Waste: Y
Universal Waste Dest Facility: Y
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal Wrkld: ------
Permwrk ID: ------
Perm Prog: ------
Pcwrkld: ------
Closwrkld: ------
GPRA Ca: N
Cawrkld: N
Subjca Tsd Discretion: N
NCAPS: N
EC Indicator: N
Ca725 Indicator: N
Ca750 Indicator: N
Operating Tsdf: ------
Full Enforcement: ------
Snc: N
Unaddressed Snc: N
Addressed Snc: N
Snc With Comp Sched: N
Fa Required: -----
Hhandler Last Change: 20240906
Recognized Trader Importer: N
Recognized Trader Exporter: N
Slab Importer: N
Slab Exporter: N
Manifest Broker: N
Subpart P: N
Contact Language: EN
Handler Name: LOYAL BROTHERS TRUCK REPAIR INC

Location Street No:	
Location Street1:	12231 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ADRIAN LEAL
Contact Street No:	
Contact Street1:	12231 HIBISCUS RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301-0000
Contact Country:	US
Contact Phone & Ext:	909-827-4389
Contact Fax:	
Contact Email Address:	LOYALBROS@OUTLOOK.COM
Contact Title:	
Owner Name:	LOYAL BROTHERS TRUCK REPAIR INC
Owner Type:	O
Owner Seq:	1
Operator Name:	ADRIAN LEAL
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20150824
Handler Name:	LOYAL BROTHERS MOBILE TRUCK REPAIR
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20240823
Handler Name:	LOYAL BROTHERS TRUCK REPAIR INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	12231 HIBISCUS RED
Name:	LOYAL BROTHERS TRUCK REPAIR INC	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	909-782-8798	***Country:***	US
Source Type:	Implementer	***Zip:***	92301

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	12231 HIBISCUS RD
Name:	ADRIAN LEAL	***Street2:***	
Dt Became Current:		***City:***	ADELANTO

Dt Ended Current:		**State:**	CA
Phone:	909-827-4389	**Country:**	
Source Type:	Implementer	**Zip:**	92301-0000
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street1:**	14012 NORSTAR AVE
Name:	ADRIAN LEAL	**Street2:**	
Dt Became Current:		**City:**	VICTORVILLE
Dt Ended Current:		**State:**	CA
Phone:	909-782-8798	**Country:**	
Source Type:	Implementer	**Zip:**	92392
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street1:**	12231 HIBISCUS RD
Name:	ADRIAN LEAL	**Street2:**	
Dt Became Current:		**City:**	ADELANTO
Dt Ended Current:		**State:**	CA
Phone:	909-827-4389	**Country:**	US
Source Type:	Implementer	**Zip:**	92301-0000

Historical Handler Details

Receive Dt:	20150824
Generator Code Description:	Not a Generator, Verified
Handler Name:	LOYAL BROTHERS MOBILE TRUCK REPAIR

27	**3 of14**	**W**	**0.17 / 898.78**	**2,920.90 / 14**	***WITHOUT BORDERS TRANSPORT INC*** ***12231 HIBISCUS RD*** ***ADELANTO CA 92371***	***RCRA NON GEN***

Handler ID:	CAL000431745
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	541614
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20171024	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:		**Location Latitude:**	34.565337
In Handler Univ:	Y	**Location Longitude:**	-117.394988

In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	2
Short Term Generator:	N
Uni Waste:	Y
Universal Waste Dest Facility:	Y
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20180907
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	WITHOUT BORDERS TRANSPORT INC
Location Street No:	
Location Street1:	12231 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92371
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	JAVIER BLANCHARD PRESIDENT
Contact Street No:	
Contact Street1:	5808 SNOWLINE DR
Contact Street2:	
Contact City:	PHELAN
Contact State:	CA
Contact Zip:	92371
Contact Country:	
Contact Phone & Ext:	661-952-7778
Contact Fax:	760-513-9558
Contact Email Address:	JAVIER@WITHOUTBORDERSINC.NET

Contact Title:
Owner Name: JAVIER BLANCHARD
Owner Type: O
Owner Seq: 1
Operator Name: JAVIER BLANCHARD PRESIDENT
Operator Type: O
Operator Seq: 2
Public Notes:

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20171024
Handler Name: WITHOUT BORDERS TRANSPORT INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: JAVIER BLANCHARD
Dt Became Current:
Dt Ended Current:
Phone: 661-952-7778
Source Type: Implementer
Street No:
Street1: 5808 SNOWLINE DR
Street2:
City: PHELAN
State: CA
Country:
Zip: 92371

Owner/Operator Ind: Current Operator
Type: Other
Name: JAVIER BLANCHARD PRESIDENT
Dt Became Current:
Dt Ended Current:
Phone: 661-952-7778
Source Type: Implementer
Street No:
Street1: 5808 SNOWLINE DR
Street2:
City: PHELAN
State: CA
Country:
Zip: 92371

27	4 of14	W	0.17 / 898.78	2,920.90 / 14	***SOUTHLAND MIXER SERVICES INC*** ***12231 HIBISCUS RD*** ***ADELANTO CA 92301-1702***	***RCRA NON GEN***

Handler ID: CAL000287666
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No
Transfer Facility: No
Recycler: No
Onsite Burner Exem: No
Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Commercial TSD: No

Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	811118
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20041027	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:		**Location Latitude:**	34.565337
In Handler Univ:	Y	**Location Longitude:**	-117.394988
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	2
Short Term Generator:	N
Uni Waste:	Y
Universal Waste Dest Facility:	Y
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20180905
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	SOUTHLAND MIXER SERVICES INC
Location Street No:	
Location Street1:	12231 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location Zip: 92301-1702
Location County Code: CA071
Location County Name: SAN BERNARDINO
Location Country: US
Contact Name: ESTEBAN CASTILLEJA
Contact Street No:
Contact Street1: 16653 LILAC ST
Contact Street2:
Contact City: HESPERIA
Contact State: CA
Contact Zip: 92345
Contact Country:
Contact Phone & Ext: 760-508-8548
Contact Fax: 760-246-9508
Contact Email Address: SOMIXER@VERIZON.NET
Contact Title:
Owner Name: STEVE CASTILLEJA
Owner Type: O
Owner Seq: 1
Operator Name: ESTEBAN CASTILLEJA
Operator Type: O
Operator Seq: 2
Public Notes:

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20041027
Handler Name: SOUTHLAND MIXER SERVICES INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: STEVE CASTILLEJA
Dt Became Current:
Dt Ended Current:
Phone: 760-508-8548
Source Type: Implementer
Street No:
Street1: 16653 LILAC ST
Street2:
City: HESPERIA
State: CA
Country:
Zip: 92345

Owner/Operator Ind: Current Operator
Type: Other
Name: ESTEBAN CASTILLEJA
Dt Became Current:
Dt Ended Current:
Phone: 760-508-8548
Source Type: Implementer
Street No:
Street1: 16653 LILAC ST
Street2:
City: HESPERIA
State: CA
Country:
Zip: 92345

27	5 of14	W	0.17 / 898.78	2,920.90 / 14	PARAMOUNT ROLL & FORMING, INC. 12231 HIBISCUS ROAD ADELANTO CA 92301	RCRA NON GEN

Handler ID: CAC003252796
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	331315
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20230921	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:		***Location Latitude:***	34.566551
In Handler Univ:	N	***Location Longitude:***	-117.394938
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		

Fa Required:	-----
Hhandler Last Change:	20230921
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PARAMOUNT ROLL & FORMING, INC.
Location Street No:	
Location Street1:	12231 HIBISCUS ROAD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	KEN MOSCRIP
Contact Street No:	
Contact Street1:	9128 ROSE ST
Contact Street2:	
Contact City:	BELLFLOWER
Contact State:	CA
Contact Zip:	90706
Contact Country:	
Contact Phone & Ext:	562-944-6151
Contact Fax:	
Contact Email Address:	PARAMOUNTROLL@GMAIL.COM
Contact Title:	
Owner Name:	KEN MOSCRIP
Owner Type:	O
Owner Seq:	1
Operator Name:	KEN MOSCRIP
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20230921
Handler Name:	PARAMOUNT ROLL & FORMING, INC.
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	9128 ROSE ST
Name:	KEN MOSCRIP	***Street2:***	
Dt Became Current:		***City:***	BELLFLOWER
Dt Ended Current:		***State:***	CA
Phone:	562-944-6151	***Country:***	
Source Type:	Implementer	***Zip:***	90706

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	9128 ROSE ST
Name:	KEN MOSCRIP	***Street2:***	
Dt Became Current:		***City:***	BELLFLOWER
Dt Ended Current:		***State:***	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: 562-944-6151 **Country:**
Source Type: Implementer **Zip:** 90706

---

27 **6 of14** **W** **0.17 / 898.78** **2,920.90 / 14**

PARAMOUNT ROLL & FORMING INC
12231 HIBISCUS RD BLDG 2
ADELANTO CA 92301

RCRA NON GEN

Handler ID: CAL000482107
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	331315
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20231129	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.566551
In Handler Univ:	N	**Location Longitude:**	-117.394938
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: CA
State Waste Generator: 2
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal Wrkld: ------
Permwrk ID: ------
Perm Prog: ------

Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20231201
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PARAMOUNT ROLL & FORMING INC
Location Street No:	
Location Street1:	12231 HIBISCUS RD BLDG 2
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ARMANDO INIGUEZ
Contact Street No:	
Contact Street1:	12231 HIBISCUS RD BLDG 2
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	
Contact Phone & Ext:	562-577-6981
Contact Fax:	562-944-6151
Contact Email Address:	PARAMOUNTROLL@GMAIL.COM
Contact Title:	
Owner Name:	PARAMOUNT ROLL & FORMING INC
Owner Type:	O
Owner Seq:	1
Operator Name:	ARMANDO INIGUEZ
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20231129
Handler Name:	PARAMOUNT ROLL & FORMING INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	12231 HIBISCUS RD BLDG 2
Name:	ARMANDO INIGUEZ	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	562-577-6981	***Country:***	
Source Type:	Implementer	***Zip:***	92301
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	9128 ROSE ST
Name:	PARAMOUNT ROLL & FORMING INC	***Street2:***	
Dt Became Current:		***City:***	BELLFLOWER
Dt Ended Current:		***State:***	CA
Phone:	562-944-6151	***Country:***	
Source Type:	Implementer	***Zip:***	90706

27	***7 of14***	***W***	***0.17 / 898.78***	***2,920.90 / 14***	***PARAMOUNT ROLL & FORMING INC 12231 HIBISCUS RD BLDG #2 ADELANTO CA 92301***	***RCRA NON GEN***

Handler ID:	CAL000482208
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	331315
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20231201	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:		***Location Latitude:***	34.566551
In Handler Univ:	N	***Location Longitude:***	-117.394938
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		

Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20231201
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PARAMOUNT ROLL & FORMING INC
Location Street No:	
Location Street1:	12231 HIBISCUS RD BLDG #2
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ARMANDO INIGUEZ
Contact Street No:	
Contact Street1:	12231 HIBISCUS RD BLDG #2
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	
Contact Phone & Ext:	562-577-6981
Contact Fax:	562-941-8102
Contact Email Address:	PARAMOUNTROLL@GMAIL.COM
Contact Title:	
Owner Name:	PARAMOUNT ROLL & FORMING, INC.
Owner Type:	O
Owner Seq:	1
Operator Name:	ARMANDO INIGUEZ
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20231201
Handler Name:	PARAMOUNT ROLL & FORMING INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	12231 HIBISCUS RD BLDG #2
Name:	ARMANDO INIGUEZ	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	562-577-6981	***Country:***	
Source Type:	Implementer	***Zip:***	92301

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	9128 ROSE ST
Name:	PARAMOUNT ROLL & FORMING, INC.	***Street2:***	
Dt Became Current:		***City:***	BELLFLOWER
Dt Ended Current:		***State:***	CA
Phone:	562-944-6151	***Country:***	
Source Type:	Implementer	***Zip:***	90706

27	***8 of14***	***W***	***0.17 / 898.78***	***2,920.90 / 14***	***MWC GROUP INC 12231 HIBISCUS RD ADELANTO CA 92301***	***RCRA NON GEN***

Handler ID:	CAL000493962
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	332312

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20250602	**NAIC 4:**	
Active Site:	-----	**State:**	CA
Land Type:		**Location Latitude:**	34.566551
In Handler Univ:	N	**Location Longitude:**	-117.394938
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	2
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20250607
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	MWC GROUP INC
Location Street No:	
Location Street1:	12231 HIBISCUS RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	CHRIS ROBERTSON
Contact Street No:	
Contact Street1:	12231 HIBISCUS RD
Contact Street2:	
Contact City:	ADELANTO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact State: CA
Contact Zip: 92301
Contact Country:
Contact Phone & Ext: 909-641-7289
Contact Fax: 760-418-4658
Contact Email Address: CHRIS.ROBERTSON@MWCGROUP.NET
Contact Title:
Owner Name: MWC GROUP INC
Owner Type: O
Owner Seq: 1
Operator Name: CHRIS ROBERTSON
Operator Type: O
Operator Seq: 2
Public Notes:

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20250602
Handler Name: MWC GROUP INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: CHRIS ROBERTSON
Dt Became Current:
Dt Ended Current:
Phone: 909-641-7289
Source Type: Implementer
Street No:
Street1: 12231 HIBISCUS RD
Street2:
City: ADELANTO
State: CA
Country:
Zip: 92301

Owner/Operator Ind: Current Owner
Type: Other
Name: MWC GROUP INC
Dt Became Current:
Dt Ended Current:
Phone: 760-701-0254
Source Type: Implementer
Street No:
Street1: 12321 HIBISCUS RD
Street2:
City: ADELANTO
State: CA
Country:
Zip: 92301

27	9 of14	W	0.17 / 898.78	2,920.90 / 14	EXTRA TANK LINE, INC 12231 HIBISCUS RD ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0008018
Owner Info: EXTRA TANK LINES, INC.
Mailing Care of:
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0014086
Status: INACTIVE
Program Element Code: 4210
Permit Desc: SPECIAL HANDLER
To: 11/30/2003

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Mailing Address 1: 12331 HIBISCUS RD

Permit ID: PT0014085
Status: INACTIVE
Program Element Code: 4420
Permit Desc: SPECIAL GENERATOR
To: 11/30/2003
Mailing Address 1: 12331 HIBISCUS RD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	10 of14	W	0.17 / 898.78	2,920.90 / 14	DIESEL PROS 12231 HIBISCUS UNIT 1 ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0010305
Owner Info: REYES, ALFONSO
Mailing Care of:
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0017509
Status: INACTIVE
Program Element Code: 4210
Permit Desc: SPECIAL HANDLER
To: 4/30/2007
Mailing Address 1: 12231 HIBISCUS UNIT 1

Permit ID: PT0017508
Status: INACTIVE
Program Element Code: 4420
Permit Desc: SPECIAL GENERATOR
To: 4/30/2007
Mailing Address 1: 12231 HIBISCUS UNIT 1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	11 of14	W	0.17 / 898.78	2,920.90 / 14	SOUTHLAND MIXER SERVICE, INC 12231 HIBISCUS ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0010307
Owner Info: CASTILLEJA, STEVE
Mailing Care of:
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0017512
Status: ACTIVE
Program Element Code: 4452
Permit Desc: CONDITIONALLY EXEMPT SM QTY GENERATOR
To: 1/31/2025
Mailing Address 1: 12231 HIBISCUS RD

Permit ID: PT0017511
Status: ACTIVE
Program Element Code: 4242
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS
To: 1/31/2025
Mailing Address 1: 12231 HIBISCUS RD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	12 of14	W	0.17 / 898.78	2,920.90 / 14	RAYCO WELDING 12231 HIBISCUS UNIT C ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0010509
Owner Info: SMITH, RAY
Mailing Care of:
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0017873
Status: INACTIVE
Program Element Code: 4221
Permit Desc: HAZMAT HANDLER 0-10 EMPLOYEES
To: 8/31/2007
Mailing Address 1: 12231 HIBISCUS UNIT C

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	13 of14	W	0.17 / 898.78	2,920.90 / 14	MORRISON EQUIPMENT/HEAVY DUTY GATES INC 12231 HIBISCUS RD UNIT 2 ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0014169
Owner Info: MORRISON, JOEL
Mailing Care of: JOEL MORRISON
Mailing Address 2:
Mailing City: APPLE VALLEY
Mailing State: CA
Mailing Zip: 92308

Detail(s)

Permit ID: PT0024890
Status: INACTIVE
Program Element Code: 4221
Permit Desc: HAZMAT HANDLER 0-10 EMPLOYEES
To: 12/31/2012
Mailing Address 1: 20045 SUNSET DR

Permit ID: PT0024891
Status: INACTIVE
Program Element Code: 4430
Permit Desc: CONDITIONALLY EXEMPT SMALL QUANTITY GENERATOR
To: 12/31/2012
Mailing Address 1: 20045 SUNSET DR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	14 of14	W	0.17 / 898.78	2,920.90 / 14	Loyal Brothers Mobile Truck Repair 12231 Hibiscus Rd Adelanto CA 92301	SANBERN CUPA

Facility ID: FA0016237
Owner Info: Adrian Leal
Mailing Care of:
Mailing Address 2:
Mailing City: Victorville
Mailing State: CA
Mailing Zip: 92392

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Detail(s)

Permit ID: PT0035029
Status: ACTIVE
Program Element Code: 4243
Permit Desc: HAZARDOUS MATERIALS 4-10 CHEMICALS
To: 9/30/2024
Mailing Address 1: 14012 Northstar Ave

Permit ID: PT0035030
Status: ACTIVE
Program Element Code: 4454
Permit Desc: LARGE QUANTITY GENERATOR
To: 9/30/2024
Mailing Address 1: 14012 Northstar Ave

28	1 of4	W	0.18 / 930.94	2,920.49 / 13	TRAFFIX DEVICES, INC. DBA COAST RUBBER PRODUCTS 12128 YUCCA ROAD ADELANTO CA 92301	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2023 Pollutant Data

Facility ID: 3965
Facility SIC Code: 3069
CERR Code:
CHAPIS:
ROGT: .053044366
COT: .810132145
DISN: MOJAVE DESERT AQMD
TOGT: .120555377272727272727272727272727272727273
PMT: .073297668
PM10T: .073297668
Source: 2023 Pollutant Data
CO: 36
CO ID: SBD
Air Basin: MD
District: MOJ
NOXT: .482221514
SOXT: .005786658

2022 Criteria Data

Facility ID: 3965
Facility SIC Code: 3069
Cerr Code:
CHAPIS:
ROGT: .053044366
COT: .810132145
DISN: MOJAVE DESERT AQMD
TOGT: .120555377272727272727272727272727272727273
PMT: .073297668
PM10T: .073297668
Source: 2022 Criteria Data
District: MOJ
Air Basin: MD
Co: 36
CO ID: SBD
NOXT: .482221514
SOXT: .005786658

2022 Toxic Data

Facility ID: 3965
Facility SIC Code: 3069
CHERR Code:
CHAPIS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
TS: .1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2023 Toxic Data

Facility ID:	3965	***CO:***	36
Facility SIC Code:	3069	***COID:***	SBD
CHERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
TS:	.1		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2023 Toxic Data		

28	*2 of4*	*W*	*0.18 / 930.94*	*2,920.49 / 13*	***COAST RUBBER PRODUCTS*** ***12128 YUCCA RD*** ***ADELANTO CA 92301***	***RCRA NON GEN***

Handler ID:	CAL000426709
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	326291
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20170410	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:		***Location Latitude:***	34.564755
In Handler Univ:	N	***Location Longitude:***	-117.397113
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		

As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20190910
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	COAST RUBBER PRODUCTS
Location Street No:	
Location Street1:	12128 YUCCA RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	ALBERT IDOWU
Contact Street No:	
Contact Street1:	12128 YUCCA RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	
Contact Phone & Ext:	760-246-7171
Contact Fax:	760-246-7150
Contact Email Address:	AIDOWU@TRAFFIXDEVICES.COM
Contact Title:	
Owner Name:	JACK KULP
Owner Type:	O
Owner Seq:	1
Operator Name:	ALBERT IDOWU
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq No: 1
Receive Date: 20170410
Handler Name: COAST RUBBER PRODUCTS
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street1:***	160 AVENIDA LA PATA
Name:	JACK KULP	***Street2:***	
Dt Became Current:		***City:***	SAN CLEMENTE
Dt Ended Current:		***State:***	CA
Phone:	949-361-5663	***Country:***	
Source Type:	Implementer	***Zip:***	92673

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street1:***	12128 YUCCA RD
Name:	ALBERT IDOWU	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	760-246-7171	***Country:***	
Source Type:	Implementer	***Zip:***	92301

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	3 of4	W	0.18 / 930.94	2,920.49 / 13	TRAFFIX DEVICES INC 12128 YUCCA RD ADELANTO CA 92301	RCRA SQG

Handler ID: CAR000083592
Generator Status: SQG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20000928	***NAIC 4:***	
Active Site:	H----	***State:***	CA
Land Type:	P	***Location Latitude:***	34.564746
In Handler Univ:	Y	***Location Longitude:***	-117.397041

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	SQG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:			
State Waste Generator:			
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20021007		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		
Contact Language:	EN		
Handler Name:	TRAFFIX DEVICES INC		
Location Street No:			
Location Street1:	12128 YUCCA RD		
Location Street2:			
Location City:	ADELANTO		
Location State:	CA		
Location Zip:	92301		
Location County Code:	CA071		
Location County Name:	SAN BERNARDINO		
Location Country:	US		
Contact Name:	DAN PRUITT		
Contact Street No:			
Contact Street1:	12128 YUCCA RD		
Contact Street2:			
Contact City:	ADELANTO		
Contact State:	CA		
Contact Zip:	92301		
Contact Country:	US		
Contact Phone & Ext:	760-246-9835		
Contact Fax:			
Contact Email Address:			

Contact Title:
Owner Name: TRAFFIX DEVICES
Owner Type: P
Owner Seq: 1
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20000928
Handler Name: TRAFFIX DEVICES INC
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D018
Waste Code Desc: BENZENE

Waste Code: D039
Waste Code Desc: TETRACHLOROETHYLENE

Waste Code: D040
Waste Code Desc: TRICHLOROETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: TRAFFIX DEVICES
Dt Became Current:
Dt Ended Current:
Phone: 760-246-9835
Source Type: Notification
Street No:
Street1: 220 CALLE PINTORESCO
Street2:
City: SAN CLEMENTE
State: CA
Country:
Zip: 92672

28	4 of4	W	0.18 / 930.94	2,920.49 / 13	TRAFFIX DEVICES INC 12128 YUCCA RD ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0002407
Owner Info: TRAFFIX DEVICES, INC
Mailing Care of: JLOYA@TRAFFIXDEVICES.COM
Mailing Address 2:
Mailing City: SAN CLEMENTE
Mailing State: CA
Mailing Zip: 92673

Detail(s)

Permit ID: PT0005885
Status: ACTIVE
Program Element Code: 4244
Permit Desc: HAZARDOUS MATERIALS 11-30 CHEMICALS
To: 9/30/2025
Mailing Address 1: 160 AVENIDA LA PATA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit ID: PT0005886
Status: ACTIVE
Program Element Code: 4453
Permit Desc: SMALL QUANTITY GENERATOR
To: 9/30/2025
Mailing Address 1: 160 AVENIDA LA PATA

29	1 of3	S	0.18 / 939.79	2,937.92 / 31	CALIFORNIA SILICA PRODUCTS LLC 12808 RANCHO ROAD ADELANTO CA 92301	EMISSIONS

Source:

2018 Criteria Data

Facility ID: 2582
Facility SIC Code: 5032
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: 0
ROGT: 0
COT: 0
NOXT: 0
SOXT: 0
PMT: 2.7834971297142857142857142857142857143
PM10T: 1.420465338

2018 Toxic Data

Facility ID: 2582
Facility SIC Code: 5032
CO: 36
Air Basin: MD
District: MOJ
TS: 2.09
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2019 Criteria Data

CO: 36
Air Basin: MD
Facility ID: 2582
District: MOJ
Facility SIC Code: 1442
CO ID: SBD
DISN: MOJAVE DESERT AQMD
PM10T: 1.368696472
TOGT: .017562204545454545454545454545454545454545
PMT: 2.654026914857142857142857142857142857142857
CHAPIS:
CERR Code:
ROGT: .013909266
COT: .218375157
NOXT: .296684253
SOXT: .001573675

2019 Toxic Data

CO: 36
Air Basin: MD
Faccility ID: 2582
District: MOJ
Facility SIC Code: 1442
COID: SBD
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TS: .88
Health Risk Asmt:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2020 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	2582	***ROGT:***	.013909266
District:	MOJ	***COT:***	.218375157
Facility SIC Code:	1442	***NOXT:***	.296684253
CO ID:	SBD	***SOXT:***	.001573675
DISN:	MOJAVE DESERT AQMD		
TOGT:	.017562204545454545454545454545454545		
PMT:	2.8103382195		
PM10T:	1.368696472		

2020 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	2582	***CHERR Code:***	
District:	MOJ	***TS:***	.88
Facility SIC Code:	1442	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

29	*2 of3*	*S*	*0.18 / 939.79*	*2,937.92 / 31*	***CALIFORNIA SILICA PRODUCTS LLC*** ***12808 RANCHO RD*** ***ADELANTO CA 92301***	***EMISSIONS***

Source:

2021 Toxic Data

Co:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	2582	***Cerr Code:***	
District:	MOJ	***TS:***	.58
Facility SIC Code:	5032	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	***CHAPIS:***	
Air Basin:	MD	***Cerr Code:***	
Facility ID:	2582	***ROGT:***	.013909266
District:	MOJ	***COT:***	.218375157
Facility SIC Code:	5032	***NOXT:***	.296684253
CO ID:	SBD	***SOXT:***	.001573675
DISN:	MOJAVE DESERT AQMD		
TOGT:	.017562204545454545454545454545454545		
PMT:	2.430759123		
PM10T:	1.208161891		

29	*3 of3*	*S*	*0.18 / 939.79*	*2,937.92 / 31*	***DIVERSIFIED MINERALS, INC.*** ***12808 RANCHO RD*** ***ADELANTO CA 92301***	***EMISSIONS***

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2023 Pollutant Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 2582
Facility SIC Code: 5032
CERR Code:
CHAPIS:
ROGT: .013909266
COT: .218375157
DISN: MOJAVE DESERT AQMD
TOGT: .017562204545454545454545454545454545
PMT: 2.430759123
PM10T: 1.208161891
Source: 2023 Pollutant Data
CO: 36
CO ID: SBD
Air Basin: MD
District: MOJ
NOXT: .296684253
SOXT: .0015736745

2022 Criteria Data

Facility ID: 2582
Facility SIC Code: 5032
Cerr Code:
CHAPIS:
ROGT: .013909266
COT: .218375157
DISN: MOJAVE DESERT AQMD
TOGT: .017562204545454545454545454545454545
PMT: 2.430759123
PM10T: 1.208161891
Source: 2022 Criteria Data
District: MOJ
Air Basin: MD
Co: 36
CO ID: SBD
NOXT: .296684253
SOXT: .001573675

2022 Toxic Data

Facility ID: 2582
Facility SIC Code: 5032
CHERR Code:
CHAPIS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
TS: .58

2023 Toxic Data

Facility ID: 2582
Facility SIC Code: 5032
CHERR Code:
CHAPIS:
TS: .58
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data
CO: 36
COID: SBD
Air Basin: MD
District: MOJ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	1 of1	WNW	0.19 / 1,005.69	2,893.43 / -14	SPRINT-ADELANTO 17824 ADELANTO RD ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0006357
Owner Info: Sprint PCS Assets, LLC dba T-Mobile
Mailing Care of: CALIFORNIA EHS SPECIALIST
Mailing Address 2:
Mailing City: SNOQUALMIE
Mailing State: WA
Mailing Zip: 98065

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Detail(s)

Permit ID: PT0006846
Status: INACTIVE
Program Element Code: 4221
Permit Desc: HAZMAT HANDLER 0-10 EMPLOYEES
To: 9/30/2008
Mailing Address 1: 34931 SE Douglas St

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
31	1 of3	SW	0.21 / 1,099.76	2,935.69 / 29	VALEW WELDING & FABRICATION, INC 12522 VIOLET ROAD ADELANTO CA 92301	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data; 2022 Toxic Data; 2022 Pollutant Data

2015 Criteria Data

Facility ID: 81201538
Facility SIC Code: 3713
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: 9.283587456
ROGT: 9.1712560477824
COT:
NOXT:
SOXT:
PMT: .9962267552083333333333333333333333333333
PM10T: .956377685

2015 Toxic Data

Facility ID: 81201538
Facility SIC Code: 3713
CO: 36
Air Basin: MD
District: MOJ
TS: .98
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

2016 Criteria Data

Facility ID: 81201538
Facility SIC Code: 3713
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR CODE:
TOGT: 9.283587456
ROGT: 9.1712560477824
COT:
NOXT:
SOXT:
PMT: .9962267552083333333333333333333333333333
PM10T: .956377685

2016 Toxic Data

Facility ID: 81201538
Facility SIC Code: 3713
CERR CODE:
COID: SBD
CO: 36
DISN: MOJAVE DESERT AQMD
CHAPIS:
TS: .98
HRA:
CH Index:
AH Index:
Air Basin: MD
District: MOJ

2017 Criteria Data

Facility ID:	81201538	***CERR Code:***	
Facility SIC Code:	3713	***TOGT:***	9.283587456
CO:	36	***ROGT:***	9.1712560477824
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	.9962267552083333333333333333333333333333
CHAPIS:		***PM10T:***	.956377685

2017 Toxic Data

Facility ID:	81201538	***COID:***	SBD
Facility SIC Code:	3713	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	.98		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	1538	***CERR Code:***	
Facility SIC Code:	3713	***TOGT:***	9.387671471
CO:	36	***ROGT:***	9.2740806462009
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	1.39487345920804297328687572590011614402
CHAPIS:		***PM10T:***	1.189512263

2018 Toxic Data

Facility ID:	1538	***COID:***	SBD
Facility SIC Code:	3713	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:	6.75		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	1538	***ROGT:***	9.2740806462009
District:	MOJ	***COT:***	
Facility SIC Code:	3713	***NOXT:***	
CO ID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
PM10T:	1.189512263		
TOGT:	9.387671471		
PMT:	1.39487345920804297328687572590011614402		

2019 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Faccility ID:	1538	***CERR Code:***	
District:	MOJ	***TS:***	6.75
Facility SIC Code:	3713	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	1538	***ROGT:***	9.2740806462009
District:	MOJ	***COT:***	
Facility SIC Code:	3713	***NOXT:***	
CO ID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
TOGT:	9.387671471		
PMT:	1.3948734592080429732868757259001161440 2		
PM10T:	1.189512263		

2020 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	1538	***CHERR Code:***	
District:	MOJ	***TS:***	6.75
Facility SIC Code:	3713	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Toxic Data

Co:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	1538	***Cerr Code:***	
District:	MOJ	***TS:***	1.76
Facility SIC Code:	3713	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	***CHAPIS:***	
Air Basin:	MD	***Cerr Code:***	
Facility ID:	1538	***ROGT:***	4.62704396
District:	MOJ	***COT:***	
Facility SIC Code:	3713	***NOXT:***	
CO ID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD		
TOGT:	4.6837169349124405304180585079461483955 9		
PMT:	.7587090665432636469221835075493612078977		
PM10T:	.641368052		

2023 Pollutant Data

Facility ID:	1538	***CO:***	36

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility SIC Code: 3713 **CO ID:** SBD
CERR Code: **Air Basin:** MD
CHAPIS: **District:** MOJ
ROGT: 4.62704396 **NOXT:**
COT: **SOXT:**
DISN: MOJAVE DESERT AQMD
TOGT: 4.68371693491244053041805850794614839559
PMT: .75870906654326364692218350754936120789 77
PM10T: .641368052
Source: 2023 Pollutant Data

2022 Criteria Data

Facility ID: 1538 **District:** MOJ
Facility SIC Code: 3713 **Air Basin:** MD
Cerr Code: **Co:** 36
CHAPIS: **CO ID:** SBD
ROGT: 4.62704396 **NOXT:**
COT: **SOXT:**
DISN: MOJAVE DESERT AQMD
TOGT: 4.68371693491244053041805850794614839559
PMT: .75870906654326364692218350754936120789 77
PM10T: .641368052
Source: 2022 Criteria Data

2022 Toxic Data

Facility ID: 1538 **CO:** 36
Facility SIC Code: 3713 **Air Basin:** MD
CHERR Code: **District:** MOJ
CHAPIS: **COID:** SBD
Health Risk Asmt: **TS:** 1.76
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2022 Toxic Data

2023 Toxic Data

Facility ID: 1538 **CO:** 36
Facility SIC Code: 3713 **COID:** SBD
CHERR Code: **Air Basin:** MD
CHAPIS: **District:** MOJ
TS: 1.76
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
DISN: MOJAVE DESERT AQMD
Source: 2023 Toxic Data

31	2 of3	SW	0.21 / 1,099.76	2,935.69 / 29	VALEW WELDING AND FABRICATION 12522 VIOLET RD ADELANTO CA 92301	RCRA SQG

Handler ID: CAR000095141
Generator Status: SQG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	B	**NAIC 1:**	336211
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20220729	**NAIC 4:**	
Active Site:	H----	**State:**	CA
Land Type:	P	**Location Latitude:**	34.561845
In Handler Univ:	Y	**Location Longitude:**	-117.391266
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	SQG	**Loc GIS Origin:**	AG
Report Cycle:	2021	**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20220803		
Recognized Trader Importer:	N		

Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	VALEW WELDING AND FABRICATION
Location Street No:	12522
Location Street1:	VIOLET RD
Location Street2:	
Location City:	ADELANTO
Location State:	CA
Location Zip:	92301
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	FIDEL VELA
Contact Street No:	12522
Contact Street1:	VIOLET RD
Contact Street2:	
Contact City:	ADELANTO
Contact State:	CA
Contact Zip:	92301
Contact Country:	US
Contact Phone & Ext:	760-246-4878
Contact Fax:	
Contact Email Address:	FIDEL@VALEW.COM
Contact Title:	PRODUCTION MANAGER
Owner Name:	COURTNEY HAYES
Owner Type:	P
Owner Seq:	1
Operator Name:	VALEW WELDING AND FABRICATION
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20010418
Handler Name:	VALEW WELDING AND FABRICATION
Fed Waste Generator:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D008
Waste Code Desc:	LEAD
Waste Code:	D018
Waste Code Desc:	BENZENE
Waste Code:	D035
Waste Code Desc:	METHYL ETHYL KETONE
Waste Code:	D039
Waste Code Desc:	TETRACHLOROETHYLENE
Waste Code:	D040
Waste Code Desc:	TRICHLOROETHYLENE

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20220729
Handler Name: VALEW WELDING AND FABRICATION
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Annual/Biennial Report update with Notification
TSD Activity: N

Waste Code Details

Waste Code: 213
Waste Code Desc: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Waste Code: 343
Waste Code Desc: Unspecified organic liquid mixture

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D008
Waste Code Desc: LEAD

Waste Code: D018
Waste Code Desc: BENZENE

Waste Code: D035
Waste Code Desc: METHYL ETHYL KETONE

Waste Code: D039
Waste Code Desc: TETRACHLOROETHYLENE

Waste Code: D040
Waste Code Desc: TRICHLOROETHYLENE

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT

SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	12522 VIOLET RD
Name:	COURTNEY HAYES	***Street2:***	
Dt Became Current:	20220729	***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	760-246-4878	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip:***	92301-2704
Owner/Operator Ind:	Current Operator	***Street No:***	125222
Type:	Private	***Street1:***	VIOLET RD
Name:	VALEW WELDING AND FABRICATION	***Street2:***	
Dt Became Current:	20220729	***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	760-780-9555	***Country:***	US
Source Type:	Annual/Biennial Report update with Notification	***Zip:***	92301
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	12522 VIOLET RD
Name:	VELMA HAYES	***Street2:***	
Dt Became Current:		***City:***	ADELANTO
Dt Ended Current:		***State:***	CA
Phone:	760-246-4878	***Country:***	
Source Type:	Notification	***Zip:***	92301-2704

Historical Handler Details

Receive Dt:	20010418
Generator Code Description:	Small Quantity Generator
Handler Name:	VALEW WELDING AND FABRICATION

31	***3 of3***	***SW***	***0.21 / 1,099.76***	***2,935.69 / 29***	***VALEW WELDING AND FABRICATION 12522 VIOLET RD ADELANTO CA 92301***	***SANBERN CUPA***

Facility ID:	FA0007008
Owner Info:	Hayes Welding Inc.
Mailing Care of:	
Mailing Address 2:	
Mailing City:	Adelanto
Mailing State:	CA
Mailing Zip:	92301

Detail(s)

Permit ID:	PT0004994
Status:	ACTIVE
Program Element Code:	4244
Permit Desc:	HAZARDOUS MATERIALS 11-30 CHEMICALS
To:	9/30/2025
Mailing Address 1:	PO Box 310
Permit ID:	PT0014205
Status:	ACTIVE
Program Element Code:	4453
Permit Desc:	SMALL QUANTITY GENERATOR
To:	9/30/2025
Mailing Address 1:	PO Box 310

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit ID: PT0037807
Status: INACTIVE
Program Element Code: 4031
Permit Desc: APSA 1,320-10,000 GAL FAC CAPACITY
To: 9/30/2018
Mailing Address 1: PO Box 310

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	1 of2	NW	0.23 / 1,189.93	2,890.99 / -16	George Air Force Base - LF036 OU3 Construction debris/trash 18374 Phantom West St Victorville CA 92392-1504	CLEANUP SITES

Global ID: DOD100235700
Site Fac Type (SRCH):
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 11/1/1998
Cleanup Status: COMPLETED - CASE CLOSED AS OF 11/1/1998
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Site Facility Type: MILITARY CLEANUP SITE
Case Type (DL): Military Cleanup Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH):
Latitude (DL): 34.575348250949
Longitude (DL): -117.389430999756
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): 92392-1504
County (DL): San Bernardino
State (DL): CA
Site Facility Name : LF036 OU3 CONSTRUCTION DEBRIS/TRASH
Address : 18374 PHANTOM WEST ST
City : VICTORVILLE
Zip : 92392-1504
County : SAN BERNARDINO
Report Source: Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No: 166-61 -- 28
Local Case No: 400071 -- 28
Begin Date:
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Local Agency:
CUF Case:
CalEnvScreen Score:
EPA Region: 9
Qty Rlsd Gallons:
Potential COC:
How Discovered:
Stop Method:
Stop Description:
Case Worker:
Military DoD Site: Yes
Leak Reported Dt:
No Further Action Dt: 1998-11-01 00:00:00
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name: Upper Mojave River Valley (6-042)
Disadvantaged Community:
Coordinate Source: Google Map Move
Discharge Cause:
Discharge Source:
Facility Project Sub Type:

Calenviroscreen 3 Score: 81-85%
Calenviroscreen 4 Score: 75-80%
File Location: Regional Board
Claim No:
Claim Status:
A2022 Assembly District: 34
A2022 Congressional District: 23
A2022 Senate District: 23
Site History:

No Further Action identified in the final Operable Unit three Record of Decision.

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1998-11-01 00:00:00

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235700
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/1/1998
Potential COC: NONE SPECIFIED
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management: LAND USE COVENANT
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 28
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 28
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100235700&tabname=regulatoryhistory
Site History:

No Further Action identified in the final Operable Unit three Record of Decision.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235700&doc_id=6288167
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Reports
Action: Record of Decision

Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235700&doc_id=5666586
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235700&doc_id=6280555
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235700&doc_id=6277739
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004
Received Issue Date: 5/21/2004
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&enforcement_id=6088618&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel A Airport Conveyance - Former George AFB - North South Runway

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235700&doc_id=6226155
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&enforcement_id=6104607&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 5/21/2004
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100235700&enforcement_id=6088618

GeoTracker Search - Documents

Document Type: Site Documents **Document Date:** 7/11/2023
Type: COMMUNITY RELATIONS **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&document_id=6288167

Document Type: Site Documents **Document Date:** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&document_id=6277739

Document Type: Site Documents **Document Date:** 5/21/2004
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED PARCEL A AIRPORT CONVEYANCE - FORMER GEORGE AFB - NORTH SOUTH RUNWAY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&enforcement_id=6088618

Document Type: Site Documents **Document Date:** 11/29/1998
Type: RECORD OF DECISION **Submitted:**
Submitted By: (REGULATOR)
Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&document_id=5666586

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&document_id=6226155

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&enforcement_id=6104607

Document Type: Site Documents **Document Date:** 1/1/1983
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&document_id=6280555

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 11/1/1998

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	2 of 2	NW	0.23 / 1,189.93	2,890.99 / -16	George Air Force Base - LF036 OU3 Construction debris/trash 18374 Phantom West St Victorville CA 92392-1504	DEED

Global ID: DOD100235700 **RWQCB Region:** LAHONTAN RWQCB (REGION 6V)
Site Type: Military Cleanup Site **County:** San Bernardino
Status: Completed - Case Closed **Longitude:** -117.389430999756
Status Date: 11/1/1998 **Latitude:** 34.575348250949
Facility Project Sub Type:
Calenviroscreen 3 Score: 81-85%
Calenviroscreen 4 Score: 75-80%
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235700

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004
Received Issue Date: 5/21/2004
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235700&enforcement_id=6088618&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel A Airport Conveyance - Former George AFB - North South Runway

GeoTracker Search - Deed Restrictions

Date Recorded: 5/21/2004
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100235700&enforcement_id=6088618

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
33	1 of1	E	0.23 / 1,231.74	2,915.65 / 8	Federal Bureau of Prisons/Federal Correctional Complex Recycling 13777 Air Expway Victorville CA 92394	CONTAINER RECY

Account No: SP64491.001
County: San Bernardino
Phone No: (760) 530-5874
Website:
Email:
Organization Name: Federal Bureau of Prisons
Mailing Address: PO Box 5400
Materials Accepted: Aluminum, Bimetal
Operation Begin Dt: 9/9/2010
Mailing City: Adelanto
Mailing State: CA
Mailing Postal Cod: 92301

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	1 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	SPRINT 17834 ADELANTO RD ADELANTO CA 92301	EMISSIONS

Source:

2014 Criteria Data

Facility ID: 163302803
Facility SIC Code: 161
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: .000493
ROGT: .0004331005
COT: .00102
NOXT: .00469
SOXT: .000071
PMT: .000478
PM10T: .000478

2014 Toxic Data

Facility ID: 163302803
Facility SIC Code: 161
CO: 36
Air Basin: MD
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2015 Criteria Data

Facility ID:	163302803	**CERR Code:**	
Facility SIC Code:	161	**TOGT:**	.000493
CO:	36	**ROGT:**	.0004331005
Air Basin:	MD	**COT:**	.00102
District:	MOJ	**NOXT:**	.00469
COID:	SBD	**SOXT:**	.000071
DISN:	MOJAVE DESERT AQMD	**PMT:**	.000478
CHAPIS:		**PM10T:**	.000478

2015 Toxic Data

Facility ID:	163302803	**COID:**	SBD
Facility SIC Code:	161	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2016 Criteria Data

Facility ID:	163302803	**CERR CODE:**	
Facility SIC Code:	161	**TOGT:**	.000493
CO:	36	**ROGT:**	.0004331005
Air Basin:	MD	**COT:**	.00102
District:	MOJ	**NOXT:**	.00469
COID:	SBD	**SOXT:**	.000071
DISN:	MOJAVE DESERT AQMD	**PMT:**	.000478
CHAPIS:		**PM10T:**	.000478

2016 Toxic Data

Facility ID:	163302803	**TS:**	
Facility SIC Code:	161	**HRA:**	
CERR CODE:		**CH Index:**	
COID:	SBD	**AH Index:**	
CO:	36	**Air Basin:**	MD
DISN:	MOJAVE DESERT AQMD	**District:**	MOJ
CHAPIS:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	2 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	SPRINT ADLNCAUS 17834 ADELANTO RD ADELANTO CA 92301	EMISSIONS

Source: 2022 Toxic Data; 2022 Pollutant Data

2017 Criteria Data

Facility ID:	163302803	**CERR Code:**	
Facility SIC Code:	161	**TOGT:**	.002408144
CO:	36	**ROGT:**	.002115554504
Air Basin:	MD	**COT:**	.006406187

District:	MOJ	**NOXT:**	.02972644
COID:	SBD	**SOXT:**	.00000958
DISN:	MOJAVE DESERT AQMD	**PMT:**	.002110049
CHAPIS:		**PM10T:**	.002110049

2017 Toxic Data

Facility ID:	163302803	**COID:**	SBD
Facility SIC Code:	161	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	7.09		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	2803	**CERR Code:**	
Facility SIC Code:	4813	**TOGT:**	.002408144
CO:	36	**ROGT:**	.002115554504
Air Basin:	MD	**COT:**	.006406187
District:	MOJ	**NOXT:**	.02972644
COID:	SBD	**SOXT:**	.00000958
DISN:	MOJAVE DESERT AQMD	**PMT:**	.002110049
CHAPIS:		**PM10T:**	.002110049

2018 Toxic Data

Facility ID:	2803	**COID:**	SBD
Facility SIC Code:	4813	**DISN:**	MOJAVE DESERT AQMD
CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
District:	MOJ		
TS:	7.09		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	36	**CHAPIS:**	
Air Basin:	MD	**CERR Code:**	
Facility ID:	2803	**ROGT:**	.0009404439135
District:	MOJ	**COT:**	.002847792
Facility SIC Code:	4813	**NOXT:**	.013214527
CO ID:	SBD	**SOXT:**	.00000426
DISN:	MOJAVE DESERT AQMD		
PM10T:	.000937996		
TOGT:	.001070511		
PMT:	.000937996		

2019 Toxic Data

CO:	36	**DISN:**	MOJAVE DESERT AQMD
Air Basin:	MD	**CHAPIS:**	
Faccility ID:	2803	**CERR Code:**	
District:	MOJ	**TS:**	3.15
Facility SIC Code:	4813	**Health Risk Asmt:**	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Criteria Data

CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
Facility ID:	2803	***ROGT:***	.0009404439135
District:	MOJ	***COT:***	.002847792
Facility SIC Code:	4813	***NOXT:***	.013214527
CO ID:	SBD	***SOXT:***	.00000426
DISN:	MOJAVE DESERT AQMD		
TOGT:	.001070511		
PMT:	.000937996		
PM10T:	.000937996		

2020 Toxic Data

CO:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	2803	***CHERR Code:***	
District:	MOJ	***TS:***	3.15
Facility SIC Code:	4813	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Toxic Data

Co:	36	***DISN:***	MOJAVE DESERT AQMD
Air Basin:	MD	***CHAPIS:***	
Facility ID:	2803	***Cerr Code:***	
District:	MOJ	***TS:***	3.15
Facility SIC Code:	4813	***Health Risk Asmt:***	
COID:	SBD		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Criteria Data

Co:	36	***CHAPIS:***	
Air Basin:	MD	***Cerr Code:***	
Facility ID:	2803	***ROGT:***	.0009404439135
District:	MOJ	***COT:***	.002847792
Facility SIC Code:	4813	***NOXT:***	.013214527
CO ID:	SBD	***SOXT:***	.00000426
DISN:	MOJAVE DESERT AQMD		
TOGT:	.001070511		
PMT:	.000937996		
PM10T:	.000937996		

2022 Criteria Data

Facility ID:	2803	***District:***	MOJ
Facility SIC Code:	4813	***Air Basin:***	MD
Cerr Code:		***Co:***	36
CHAPIS:		***CO ID:***	SBD
ROGT:	.000703288446	***NOXT:***	.009882168
COT:	.002129653	***SOXT:***	.00000318
DISN:	MOJAVE DESERT AQMD		
TOGT:	.000800556		
PMT:	.000705692152917505030181086519114688128773		
PM10T:	.000701458		
Source:	2022 Criteria Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2022 Toxic Data

Facility ID:	2803	***CO:***	36
Facility SIC Code:	4813	***Air Basin:***	MD
CHERR Code:		***District:***	MOJ
CHAPIS:		***COID:***	SBD
Health Risk Asmt:		***TS:***	1.75
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2022 Toxic Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	3 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	COGENT ADLNCAUS 17834 ADELANTO RD ADELANTO CA 92301	EMISSIONS

Source: 2023 Toxic Data; 2023 Pollutant Data

2023 Pollutant Data

Facility ID:	2803	***CO:***	36
Facility SIC Code:	4813	***CO ID:***	SBD
CERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
ROGT:	.0007040089464	***NOXT:***	.009882168
COT:	.002129653	***SOXT:***	.00000318458
DISN:	MOJAVE DESERT AQMD		
TOGT:	.000800556		
PMT:	.000705692152917505030181086519114688128773		
PM10T:	.000701458		
Source:	2023 Pollutant Data		

2023 Toxic Data

Facility ID:	2803	***CO:***	36
Facility SIC Code:	4813	***COID:***	SBD
CHERR Code:		***Air Basin:***	MD
CHAPIS:		***District:***	MOJ
TS:	1.75		
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			
DISN:	MOJAVE DESERT AQMD		
Source:	2023 Toxic Data		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	4 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	EMPIRE ONE AUTO SERVICES 17834 ADELANTO RD ADELANTO CA 92301	SANBERN CUPA

Facility ID:	FA0009060
Owner Info:	LOUBET, ARNOLD HERRERA
Mailing Care of:	
Mailing Address 2:	
Mailing City:	ADELANTO
Mailing State:	CA
Mailing Zip:	92301

Detail(s)

Permit ID:	PT0015073
Status:	INACTIVE
Program Element Code:	4210
Permit Desc:	SPECIAL HANDLER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

To: 9/30/2007
Mailing Address 1: 17834 ADELANTO RD

Permit ID: PT0015072
Status: INACTIVE
Program Element Code: 4420
Permit Desc: SPECIAL GENERATOR
To: 9/30/2006
Mailing Address 1: 17834 ADELANTO RD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	5 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	GOLDEN HAWK TOWING 17834 ADELANTO RD ADELANTO CA 92301	SANBERN CUPA

Facility ID: FA0015288
Owner Info: MUSHARBASH, ISSA
Mailing Care of:
Mailing Address 2:
Mailing City: ADELANTO
Mailing State: CA
Mailing Zip: 92301

Detail(s)

Permit ID: PT0026634
Status: INACTIVE
Program Element Code: 4451
Permit Desc: CONDITIONALLY EXEMPT SM QTY GENERATOR SPECIAL
To: 3/31/2015
Mailing Address 1: 17834 ADELANTO RD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	6 of6	WNW	0.24 / 1,254.44	2,892.40 / -15	Sprint Adelanto POP/REGEN CAADEA 17834 Adelanto Rd Adelanto CA 92301	SANBERN CUPA

Facility ID: FA0016595
Owner Info: Sprint PCS Assets, LLC dba T-Mobile
Mailing Care of: environmental_compliance@cogentco.com
Mailing Address 2:
Mailing City: Washington
Mailing State: DC
Mailing Zip: 20037

Detail(s)

Permit ID: PT0035769
Status: ACTIVE
Program Element Code: 4241
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
To: 2/28/2025
Mailing Address 1: 2450 N Street NW

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	1 of1	WNW	0.29 / 1,557.14	2,886.47 / -21	TURNER FORD 17909 ADELANTO RD ADELANTO CA 92301	LUST

Global ID: T0607100733
Site Facility Type: LUST CLEANUP SITE
Site Fac Type (SRCH): LUST CLEANUP SITE
Status:
Status (SRCH): COMPLETED - CASE CLOSED
Status (DL): Completed - Case Closed
Status Date (DL): 1/9/1992
Case Type (DL): LUST Cleanup Site
Oil Field (SRCH):
Oil Field Oper (SRCH):
Census Tract (SRCH): 6071009116
Latitude (DL): 34.576139
Longitude (DL): -117.399598
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)

Cleanup Status:	COMPLETED - CASE CLOSED
Site Facility Name (SRCH):	TURNER FORD
Address (SRCH):	17909 ADELANTO RD
City (SRCH):	ADELANTO
Zip (SRCH):	92301
County (SRCH):	SAN BERNARDINO
Street No (DL):	17909
Street Name (DL):	ADELANTO RD
City (DL):	ADELANTO
Zip (DL):	92301
County (DL):	San Bernardino
State (DL):	CA
Business Name (DL):	TURNER FORD
Site Facility Name:	TURNER FORD
Address :	17909 ADELANTO RD
City :	ADELANTO
Zip :	92301
County :	SAN BERNARDINO
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	CR2
Local Agency:	SAN BERNARDINO COUNTY
RB Case No:	6B3600296T
Local Case No:	91012
File Location:	Local Agency
Potential COC:	Diesel
Potential Media of Concern:	Soil
Begin Date:	10/24/1990
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	
Stop Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
CalEnvScreen Score:	
Coordinate Source:	Google Geocode
Discharge Cause:	Unknown
Discharge Source:	Other
EPA Region:	9
Leak Reported Dt:	1991-05-23 00:00:00
Military DoD Site:	No
No Further Action Dt:	1992-01-09 00:00:00
Qty Rlsd Gallons:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	81-85%
Calenviroscreen 4 Score:	75-80%
Claim No:	
Claim Status:	
A2022 Assembly District:	39
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:	Local Agency Caseworker - Primary Caseworker
Contact Name:	CATHERINE RICHARDS
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO

Email: crichards@sbcfire.org
Phone No: 9093868419

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1/9/1992

Status: Open - Site Assessment
Status Date: 10/24/1991

Status: Open - Remediation
Status Date: 4/2/1991

Status: Open - Case Begin Date
Status Date: 10/24/1990

GeoTracker Search - Regulatory Profile

Site Facility Name: TURNER FORD
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 17909 ADELANTO RD
City: ADELANTO
Zip: 92301
County: SAN BERNARDINO
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0607100733
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/9/1992
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0607100733&tabname=regulatoryhistory
Potential COC: DIESEL
Potential Media of Concern: SOIL
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SAN BERNARDINO COUNTY (LEAD) - CASE #: 91012
CASE MANAGER: CATHERINE RICHARDS
LAHONTAN RWQCB (REGION 6V) - CASE #: 6B3600296T
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Site History:

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 1/9/1992

Status: Open - Site Assessment
Date : 10/24/1991

Status: Open - Remediation
Date : 4/2/1991

Status: Open - Case Begin Date
Date : 10/24/1990

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 4/3/2002
Received Issue Date: 4/3/2002
Doc Link:
Title Description Comments:

AEO-signed mass mailed letter reminding RP of EDF submittal requirement per AB 2886

Action Type: Enforcement/Orders
Action: * Historical Enforcement
Action Date: 11/26/1991
Received Issue Date: 11/26/1991
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Reported
Action Date: 5/23/1991
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Discovery
Action Date: 10/30/1990
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Stopped
Action Date: 10/24/1990
Received Issue Date:
Doc Link:
Title Description Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	1 of2	NNW	0.33 / 1,751.12	2,891.35 / -16	George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100235600
Site Fac Type (SRCH):
Status (SRCH):
Status (DL): Open - Verification Monitoring
Status Date (DL): 11/1/1998
Cleanup Status: OPEN - VERIFICATION MONITORING AS OF 11/1/1998
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
Site Facility Type: MILITARY CLEANUP SITE
Case Type (DL): Military Cleanup Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH):
Latitude (DL): 34.5769030055509
Longitude (DL): -117.387371063232

County (SRCH):	
Street No (DL):	18374
Street Name (DL):	Phantom West St
City (DL):	Victorville
Zip (DL):	-92392
County (DL):	San Bernardino
State (DL):	CA
Site Facility Name :	LF035 OU3 LANDFILL WOOD DEBRIS ASBESTOS DISPOSAL
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	-92392
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 29
Local Case No:	400071 -- 29
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	Asbestos Containing Materials (ACM)
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	MH
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	
Potential Media of Concern:	Soil
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
Coordinate Source:	Google Geocode
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	81-85%
Calenviroscreen 4 Score:	75-80%
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

Unless mobilized via extraction activities, any asbestos or fiberglass present should not pose a threat to human health or the environment. 1998 OU3 ROD selected land use restrictions for LF035. Effectiveness of LU restrictions should continue to be reviewed.

GeoTracker Sites Data Download - Status History

Status:	Open - Verification Monitoring
Status Date:	1998-11-01 00:00:00

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:	Regional Board Caseworker
Contact Name:	LORIEN SANDERS

Organization Name: LAHONTAN RWQCB (REGION 6V)
Address: 15095 Amargosa Road – Bldg 2, Ste 210
City: VICTORVILLE
Email: lorien.sanders@waterboards.ca.gov
Phone No: 7602414942

Contact Type: Regional Board Caseworker - Primary Caseworker
Contact Name: MOLINA HAUV
Organization Name: LAHONTAN RWQCB (REGION 6V)
Address: 15095 Amargosa Road, Bldg. 2, Ste 210
City: VICTORVILLE
Email: molina.hauv@waterboards.ca.gov
Phone No: 7602413408

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235600
Cleanup Status Detail: OPEN - VERIFICATION MONITORING AS OF 11/1/1998
Potential COC: ASBESTOS CONTAINING MATERIALS (ACM)
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management: LAND USE COVENANT
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 29
CASE MANAGER: MOLINA HAUV
CASE MANAGER: LORIEN SANDERS
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 29
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100235600&tabname=regulatoryhistory
Site History:

Unless mobilized via extraction activities, any asbestos or fiberglass present should not pose a threat to human health or the environment. 1998 OU3 ROD selected land use restrictions for LF035.
Effectiveness of LU restrictions should continue to be reviewed.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 6/26/2006
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=5695187
Title Description Comments:

Amendment to the Landfill Long-Term Monitoring and Maintenance Plan Former George Air Force Base, California

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:

Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6288124
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Workplans
Action: Soil and Water Investigation Workplan
Action Date:
Received Issue Date: 1/30/2003
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6180990
Title Description Comments:

Final Long-term Monitoring and Maintenance Plan for Landfills

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6280512
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6277696
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - Workplans
Action: Corrective Action Plan / Remedial Action Plan
Action Date:
Received Issue Date: 4/1/1996
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6180975
Title Description Comments:

Closure and Post Closure Maintanence Plans DP003, DP004, LF-12, LF-14 and SEDA

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=5666567
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 11/21/2022
Received Issue Date: 11/21/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6545331&temptable=ENFORCEMENT
Title Description Comments:

Change In Lahontan Water Board Remedial Project Managers

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 10/20/2022

Received Issue Date: 10/20/2022
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6509939&temptable=ENFORCEMENT
Title Description Comments:

Water Board Staff Comment Letter on the Revised Draft Basewide Quality Assurance Project Plan, Former George Air Force Base (AFB), Victorville, California, San Bernardino County

Action Type: Response Requested - JEP Activity
Action: Report
Action Date: 7/11/2021
Received Issue Date: 7/11/2021
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6248677
Title Description Comments:

2020 Annual Groundwater Monitoring and Operations Report

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/3/2019
Received Issue Date: 9/3/2019
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6493349&temptable=ENFORCEMENT
Title Description Comments:

Public Safety Regarding Military Munitions Hazards GAFB

Action Type: Referral to Other Agency
Action: Referral to Other State Agency
Action Date: 6/22/2015
Received Issue Date: 6/22/2015
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6284407&temptable=ENFORCEMENT
Title Description Comments:

Distribution of State Lead Agency Responsibilities on Munitions and Explosive Concerns GAFB

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 3/25/2011
Received Issue Date: 3/25/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6081775&temptable=ENFORCEMENT
Title Description Comments:

Water Board email regarding WQPS for Landfills - email jwc 2011-03-25)

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004
Received Issue Date: 5/21/2004
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6088617&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel A Airport Conveyance - Former George AFB - North South Runway

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235600&doc_id=6226107
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6104589&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 5/21/2004
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100235600&enforcement_id=6088617

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6288124

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6277696

Document Type: Site Documents ***Document Date:*** 11/21/2022
Type: STAFF LETTER ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: CHANGE IN LAHONTAN WATER BOARD REMEDIAL PROJECT MANAGERS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6545331

Document Type: Site Documents ***Document Date:*** 10/20/2022
Type: STAFF LETTER ***Submitted:***
Submitted By: CHRISTOPHER AVALOS (REGULATOR)
Title: WATER BOARD STAFF COMMENT LETTER ON THE REVISED DRAFT BASEWIDE QUALITY ASSURANCE PROJECT PLAN, FORMER GEORGE AIR FORCE BASE (AFB), VICTORVILLE, CALIFORNIA, SAN BERNARDINO COUNTY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6509939

Document Type: Site Documents ***Document Date:*** 7/11/2021
Type: REPORT ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: 2020 ANNUAL GROUNDWATER MONITORING AND OPERATIONS REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6248677

Document Type: Site Documents ***Document Date:*** 9/3/2019
Type: STAFF LETTER ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: PUBLIC SAFETY REGARDING MILITARY MUNITIONS HAZARDS GAFB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6493349

Document Type: Site Documents ***Document Date:*** 6/22/2015
Type: REFERRAL TO OTHER STATE AGENCY ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: DISTRIBUTION OF STATE LEAD AGENCY RESPONSIBILITIES ON MUNITIONS AND EXPLOSIVE CONCERNS GAFB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6284407

Document Type: Site Documents **Document Date:** 3/25/2011
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: WATER BOARD EMAIL REGARDING WQPS FOR LANDFILLS - EMAIL JWC 2011-03-25)
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6081775

Document Type: Site Documents **Document Date:** 6/26/2006
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: (REGULATOR)
Title: AMENDMENT TO THE LANDFILL LONG-TERM MONITORING AND MAINTENANCE PLAN FORMER GEORGE AIR FORCE BASE, CALIFORNIA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=5695187

Document Type: Site Documents **Document Date:** 5/21/2004
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED PARCEL A AIRPORT CONVEYANCE - FORMER GEORGE AFB - NORTH SOUTH RUNWAY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6088617

Document Type: Site Documents **Document Date:** 1/30/2003
Type: SOIL AND WATER INVESTIGATION WORKPLAN **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: FINAL LONG-TERM MONITORING AND MAINTENANCE PLAN FOR LANDFILLS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6180990

Document Type: Site Documents **Document Date:** 11/29/1998
Type: RECORD OF DECISION **Submitted:**
Submitted By: (REGULATOR)
Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=5666567

Document Type: Site Documents **Document Date:** 4/1/1996
Type: CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: CLOSURE AND POST CLOSURE MAINTANENCE PLANS DP003, DP004, LF-12, LF-14 AND SEDA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6180975

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6226107

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6104589

Document Type: Site Documents **Document Date:** 1/1/1983
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&document_id=6280512

GeoTracker Search - Cleanup Status History

Status: Open - Verification Monitoring
Date: 11/1/1998

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	2 of2	NNW	0.33 / 1,751.12	2,891.35 / -16	George Air Force Base - LF035 OU3 Landfill Wood Debris Asbestos Disposal 18374 Phantom West St Victorville CA -92392	DEED

Global ID: DOD100235600
Site Type: Military Cleanup Site
Status: Open - Verification Monitoring
Status Date: 11/1/1998
Facility Project Sub Type:
Calenviroscreen 3 Score: 81-85%
Calenviroscreen 4 Score: 75-80%
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235600
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.387371063232
Latitude: 34.5769030055509

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 5/21/2004
Received Issue Date: 5/21/2004
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235600&enforcement_id=6088617&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed Parcel A Airport Conveyance - Former George AFB - North South Runway

GeoTracker Search - Deed Restrictions

Date Recorded: 5/21/2004
Site Manage Req: LAND USE COVENANT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100235600&enforcement_id=6088617

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	1 of1	W	0.34 / 1,782.96	2,901.76 / -5	ADELANTO SCHOOL DISTRICT 11824 AIR BASE RD ADELANTO CA 92301	LUST

Global ID: T0607100739
Site Facility Type: LUST CLEANUP SITE
Site Fac Type (SRCH): LUST CLEANUP SITE
Status:
Status (SRCH): COMPLETED - CASE CLOSED
Status (DL): Completed - Case Closed
Status Date (DL): 6/9/1994
Cleanup Status: COMPLETED - CASE CLOSED
Site Facility Name (SRCH): ADELANTO SCHOOL DISTRICT
Address (SRCH): 11824 AIR BASE RD
City (SRCH): ADELANTO
Zip (SRCH): 92301
County (SRCH): SAN BERNARDINO
Street No (DL): 11824
Street Name (DL): AIR BASE RD
City (DL): ADELANTO
Zip (DL): 92301
County (DL): San Bernardino
State (DL): CA
Business Name (DL): ADELANTO SCHOOL DISTRICT
Case Type (DL): LUST Cleanup Site
Oil Field (SRCH):
Oil Field Oper (SRCH):
Census Tract (SRCH): 6071009116
Latitude (DL): 34.5720215
Longitude (DL): -117.4064884
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)

Site Facility Name:	ADELANTO SCHOOL DISTRICT
Address :	11824 AIR BASE RD
City :	ADELANTO
Zip :	92301
County :	SAN BERNARDINO
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	
Local Agency:	
RB Case No:	6B3600330T
Local Case No:	91025
File Location:	Local Agency
Potential COC:	Diesel
Potential Media of Concern:	Soil
Begin Date:	11/14/1991
How Discovered:	Nuisance Conditions
How Discovered Description:	
Stop Method:	
Stop Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	Google Geocode
Discharge Cause:	Corrosion
Discharge Source:	Piping
EPA Region:	9
Leak Reported Dt:	1991-12-16 00:00:00
Military DoD Site:	No
No Further Action Dt:	1994-06-09 00:00:00
Qty Rlsd Gallons:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	81-85%
Calenviroscreen 4 Score:	75-80%
Claim No:	
Claim Status:	
A2022 Assembly District:	39
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	6/9/1994
Status:	Open - Remediation
Status Date:	6/11/1992
Status:	Open - Site Assessment
Status Date:	12/16/1991
Status:	Open - Case Begin Date
Status Date:	11/14/1991
Status:	Open - Site Assessment
Status Date:	11/14/1991

GeoTracker Search - Regulatory Profile

Site Facility Name:	ADELANTO SCHOOL DISTRICT
Site Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Address:	11824 AIR BASE RD
City:	ADELANTO
Zip:	92301
County:	SAN BERNARDINO
Report Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T0607100739
Cleanup Status Detail:	COMPLETED - CASE CLOSED AS OF 6/9/1994
Project Status:	
Cleanup History Link:	https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0607100739&tabname=regulatoryhistory
Potential COC:	DIESEL
Potential Media of Concern:	SOIL
File Location:	LOCAL AGENCY
User Defined Beneficial Use:	
Designated Beneficial Use:	MUN, AGR, IND, FRSH, AQUA
DWR GW Sub Basin:	Upper Mojave River Valley (6-042)
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
Post Closure Site Management:	
Future Land Use:	
Cleanup Oversight Agencies:	SAN BERNARDINO COUNTY (LEAD) - CASE #: 91025 LAHONTAN RWQCB (REGION 6V) - CASE #: 6B3600330T
CUF Claim No:	
CUF Priority Assig:	
CUF Amount Paid:	
WDR Place Type:	
WDR File No:	
WDR Order No:	
Project Oversight Agencies:	
Facility Type:	
Composting Method:	
Grndwtr Monitoring Frequency:	
Designated Beneficial Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Site History:	

No site history available

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	6/9/1994
Status:	Open - Remediation
Date :	6/11/1992
Status:	Open - Site Assessment
Date :	12/16/1991
Status:	Open - Site Assessment
Date :	11/14/1991
Status:	Open - Case Begin Date
Date :	11/14/1991

GeoTracker Search - Regulatory Activities

Action Type:	Enforcement/Orders
Action:	* Historical Enforcement
Action Date:	12/17/1991
Received Issue Date:	12/17/1991
Doc Link:	
Title Description Comments:	
Action Type:	Leak Action

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action: Leak Reported
Action Date: 12/16/1991
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Discovery
Action Date: 11/14/1991
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Stopped
Action Date: 11/14/1991
Received Issue Date:
Doc Link:
Title Description Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	1 of1	E	0.36 / 1,881.57	2,917.12 / 10	COMAV TECHNICAL SERVICES VICTORVILLE CA	PFAS IND

Status: Active
Fac Indian Cntry Flg: No
Fac Derived Huc: -
Fac Derived Wbd: 180902080706
Fac Derived Cd113: -
Fac Derived Cb2010: -
Fac Informal Count: 0
Last Informal Action: -
Formal Action Count: 0
Last Formal Action: -
Fac Total Penalties: 0
Fac Penalty Count: -
Date Last Penalty: -
Last Penalty Amt: 0
Fac Qtrs With Nc: 0
Programs With Snc: 0
Fac Percent Minority: 78.229
Fac Pop Den: 770.73
Count: 1
Fac County: SAN BERNARDINO
State Other:
Region: 09
Latitude: 34.56663
Longitude: -117.367784
Fac Derived Tribes: -
AIR IDs: -
CAA Permit Types: -
CAA NAICS: -
CAA SICS: -
NPDES IDs: -
CWA Permit Types: -
CWA NAICS: -
CWA SICS: -
RCRA IDs: CAL000382042
RCRA Permit Types: Other
RCRA NAICS: 56172 48819 488119
SDWA IDs: -
SDWA System Types: -
SDWA Compliance Status: -
SDWA Snc Flag: No
Fac Collection Meth: GDT-ADDRESS MATCHING (GEOCODING)
ECHO Facility Report: https://echo.epa.gov/detailed-facility-report?fid=110070479947

Fac Fips Code: 06071
Compliance Status: No Violation Identified
EPA Programs: RCRA
Federal Facility: Yes
Federal Agency: -
Fac Snc Flg: No
AIR Flag: No
NPDES Flag: No
SDWIS Flag: No
RCRAFlag: Yes
TRI Flag: No
GHG Flag: No
TRI IDs: -
TRI Releases Trnsfrs: -
TRI on Site Releases: -
TRI off Site Trnsfrs: -
TRI Reporter: -
Fac Imp Water Flg: -
Fac Major Flag: -
Fac Active Flag: Yes
Fac Inspection Count: 0
Date Last Inspection: -
Days Last Inspection: -

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
39	1 of1	NE	0.36 / 1,895.74	2,895.40 / -12	George Air Force Base - George Air Force Base - OU2 - ST067b JP-4 AST/Bulk Fuel Yard 18374 PHANTOM WEST ST VICTORVILLE CA -92392	DELISTED CLEANUP

Details

Industry: Airports

Delisted GeoTracker Cleanup Program Sites

Global ID: DOD100226000
RB Case No:
Loc Case No: 400071 -- 77
Status: Open
Status Date: 1965-01-01 00:00:00
Case Type: Military Cleanup Site
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Case Worker:
Local Agency: DEPARTMENT OF TOXIC SUBSTANCES CONTROL
Begin Date:
Year: 2009
Potential Contaminants of Con:
Potential Media Affected:
Site History:

Business Name: George Air Force Base - George Air Force Base - OU2 - ST067b JP-4 AST/Bulk Fuel Yard
Street No: 18374
Street Name: PHANTOM WEST ST
City: VICTORVILLE
State: CA
Zip: -92392
County: San Bernardino
Latitude: 34.5773270244865
Longitude: -117.373509407043
File Location:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
40	1 of2	NNE	0.37 / 1,959.08	2,890.75 / -16	George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range (Building 615) 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100235900
Site Fac Type (SRCH):
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 9/26/2008
Cleanup Status: COMPLETED - CASE CLOSED AS OF 9/26/2008
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): -92392
County (DL): San Bernardino
State (DL): CA
Site Facility Name : OT075/SR404
Address : 18374 PHANTOM WEST ST
City : VICTORVILLE
Zip : -92392
County : SAN BERNARDINO
Report Source: Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

Site Facility Type: MILITARY CLEANUP SITE
Case Type (DL): Military Cleanup Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH):
Latitude (DL): 34.5770443454364
Longitude (DL): -117.379560470581

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 26
Local Case No:	400071 -- 26
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	2008-09-26 00:00:00
Potential Media of Concern:	
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
Coordinate Source:	Google Map Move
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NA
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

No Further Remedial Action Planned. In 1998, a remedial action was implemented to remove the lead-contaminated plywood and pea gravels from the Indoor Shooting Range.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	2008-09-26 00:00:00
Status:	Open - Remediation
Status Date:	1998-01-01 00:00:00

GeoTracker Search - Facilities

Project Status:	
Cuf Claim No:	
CUF Priority Assign:	
CUF Amount Paid:	
Composting Method:	
Facility Type:	
WDR Place Type:	
WDR File No:	
WDR Order No:	
File Location:	REGIONAL BOARD
User Defined Beneficial Use:	
Designated Beneficial Use:	MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:	

Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235900
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 9/26/2008
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 26
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 26
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100235900&tabname=regulatoryhistory
Site History:

No Further Remedial Action Planned. In 1998, a remedial action was implemented to remove the lead-contaminated plywood and pea gravels from the Indoor Shooting Range.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235900&doc_id=6288199
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235900&doc_id=6280587
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235900&doc_id=6277771
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 9/30/2008
Received Issue Date: 9/30/2008
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6043542&temptable=ENFORCEMENT
Title Description Comments:

Signature Page - No Further Remedial Action Planned

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6090761&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100235900&doc_id=6226187
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6104570&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&document_id=6288199

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&document_id=6277771

Document Type: Site Documents ***Document Date:*** 9/30/2008
Type: CLOSURE/NO FURTHER ACTION LETTER ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: SIGNATURE PAGE - NO FURTHER REMEDIAL ACTION PLANNED
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6043542

Document Type: Site Documents ***Document Date:*** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6090761

Document Type: Site Documents ***Document Date:*** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&document_id=6226187

Document Type: Site Documents ***Document Date:*** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ***Submitted:***

ASSISTANCE / OTHER
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6104570

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&document_id=6280587

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 9/26/2008

Status: Open - Remediation
Date: 1/1/1998

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
40	2 of2	NNE	0.37 / 1,959.08	2,890.75 / -16	George Air Force Base - OT075/SR404 (formerly AOC 75) Indoor Shooting Range (Building 615) 18374 Phantom West St Victorville CA -92392	DEED

Global ID: DOD100235900
Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 9/26/2008
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100235900
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.379560470581
Latitude: 34.5770443454364

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100235900&enforcement_id=6090761&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	1 of4	NE	0.38 / 1,994.65	2,895.31 / -12	George Air Force Base - OT074 OU5 Original Skeet Range	CLEANUP SITES

18374 Phantom West St
Victorville CA 92392

Global ID:	DOD100234600	***Site Facility Type:***	MILITARY CLEANUP SITE
Site Fac Type (SRCH):		***Case Type (DL):***	Military Cleanup Site
Status (SRCH):		***RWQCB Region (DL):***	LAHONTAN RWQCB (REGION 6V)
Status (DL):	Completed - Case Closed	***Census Tract (SRCH):***	
Status Date (DL):	1/2/2013	***Latitude (DL):***	34.5761786348656
Cleanup Status:	COMPLETED - CASE CLOSED AS OF 1/2/2013	***Longitude (DL):***	-117.374861240387

Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):

Street No (DL):	18374
Street Name (DL):	Phantom West St
City (DL):	Victorville
Zip (DL):	92392
County (DL):	San Bernardino
State (DL):	CA
Site Facility Name :	OT074 OU5 ORIGINAL SKEET RANGE
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	92392
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 31
Local Case No:	400071 -- 31
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	Munitions Debris (MD), Polynuclear aromatic hydrocarbons (PAHs)
How Discovered:	Site Assessment/Site Investigation
Stop Method:	Other Means
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	2013-01-02 00:00:00
Potential Media of Concern:	Soil
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
Coordinate Source:	Google Map Move
Discharge Cause:	Other
Discharge Source:	Other
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NA
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

After the range was discontinued, the lead shot accumulation area was distured and soil redistributed when the Bulk Fuel Storage Area was constructed

and the paved Weapons Movement Road constructed. No Further Action is proposed in the draft (September 2010) Feasibility Study. The final determination will be documented in the OU-5 Record of Decision.

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2013-01-02 00:00:00

Status: Open - Site Assessment
Status Date: 2010-04-23 00:00:00

Status: Open - Inactive
Status Date: 2010-01-14 00:00:00

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100234600
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/2/2013
Potential COC: MUNITIONS DEBRIS (MD), POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)
Potential Media of Concern: SOIL
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 31
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 31
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100234600&tabname=regulatoryhistory
Site History:

After the range was discontinued, the lead shot accumulation area was distured and soil redistributed when the Bulk Fuel Storage Area was constructed and the paved Weapons Movement Road constructed. No Further Action is proposed in the draft (September 2010) Feasibility Study. The final determination will be documented in the OU-5 Record of Decision.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Workplans
Action: Proposed Plan
Action Date:
Received Issue Date: 10/10/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6105359
Title Description Comments:

Final Proposed Plan for Operable Unit (OU5) Sites FT082, SS083, OT072, OT073, and OT074, former George Air Force Base, regulatory acceptance and reviews of draft versions

Action Type: Response Requested - Other
Action: Other Report / Document

Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6280639
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 10/10/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6105371
Title Description Comments:

Final Record of Decision (ROD), OU-5, Sites OT072, OT073, and OT074, Former George Air Force Base

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 12/20/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6094001
Title Description Comments:

Draft Skeet Range Record of Decision

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6288251
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6277823
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/24/2014
Received Issue Date: 7/24/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6285357&temptable=ENFORCEMENT
Title Description Comments:

EPA Comments on Response to Comments Draft OU5 Skeet Range Sites OT 072 OT073 OT074

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/22/2014
Received Issue Date: 7/22/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6285338&temptable=ENFORCEMENT
Title Description Comments:

State Comments on Draft Final Record of Decision OU5 Skeet Range Sites OT072, OT073, OT074

Action Type: Other Regulatory Actions

Action: Staff Letter
Action Date: 3/25/2014
Received Issue Date: 3/25/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6198431&temptable=ENFORCEMENT
Title Description Comments:

Water Board Comments on Draft Skeet Range ROD

Action Type: Response Requested - Other
Action: Correspondence
Action Date: 10/1/2013
Received Issue Date: 10/4/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6181620
Title Description Comments:

AF decision to produce one Record of Decision for the OU 5 skeet range sites and one for TCE source areas.

Action Type: Response Requested - Other
Action: Correspondence
Action Date: 11/30/2011
Received Issue Date: 11/30/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6076595
Title Description Comments:

Air Force Response to EPA - RE: Informal Dispute on Focused Feasibility Study for OU5 sites

Action Type: Enforcement/Orders
Action: Warning Letter
Action Date: 11/28/2011
Received Issue Date: 11/28/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6104903&temptable=ENFORCEMENT
Title Description Comments:

EPA - EPA Review and Invocation of Informal Dispute Resolution Regarding Final Operable Unit 5 Focused Feasibility Study, GAFB, CA August 2011

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 8/26/2011
Received Issue Date: 8/26/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6097275&temptable=ENFORCEMENT
Title Description Comments:

Final Operable Unit Five Focused Feasibility Study Former George AFB, MWH 8-26-11

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 12/21/2010
Received Issue Date: 12/21/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6072597&temptable=ENFORCEMENT
Title Description Comments:

Draft Final OU-5 Focused Feasibility Study, December 21, 2010

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 11/1/2010
Received Issue Date: 11/1/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6068418&temptable=ENFORCEMENT
Title Description Comments:

EPA Letter - Draft Operable Unit 5 Focused Feasibility Study, Former George Air Force Base, California, dated August 31, 2010

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6090764&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100234600&doc_id=6226120
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6104642&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6288251

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6277823

Document Type: Site Documents ***Document Date:*** 10/10/2014
Type: PROPOSED PLAN ***Submitted:***
Submitted By: AUSTIN WHITE (REGULATOR)
Title: FINAL PROPOSED PLAN FOR OPERABLE UNIT (OU5) SITES FT082, SS083, OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE, REGULATORY ACCEPTANCE AND REVIEWS OF DRAFT VERSIONS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6105359

Document Type: Site Documents ***Document Date:*** 10/10/2014
Type: RECORD OF DECISION ***Submitted:***
Submitted By: AUSTIN WHITE (REGULATOR)
Title: FINAL RECORD OF DECISION (ROD), OU-5, SITES OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6105371

Document Type: Site Documents **Document Date:** 10/10/2014
Type: PROPOSED PLAN **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: FINAL PROPOSED PLAN FOR OPERABLE UNIT (OU5) SITES FT082, SS083, OT072, OT073, AND OT074, FORMER GEORGE AIR FORCE BASE, REGULATORY ACCEPTANCE AND REVIEWS OF DRAFT VERSIONS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6105359

Document Type: Site Documents **Document Date:** 7/24/2014
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: EPA COMMENTS ON RESPONSE TO COMMENTS DRAFT OU5 SKEET RANGE SITES OT 072 OT073 OT074
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6285357

Document Type: Site Documents **Document Date:** 7/22/2014
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: STATE COMMENTS ON DRAFT FINAL RECORD OF DECISION OU5 SKEET RANGE SITES OT072, OT073, OT074
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6285338

Document Type: Site Documents **Document Date:** 3/25/2014
Type: STAFF LETTER **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: WATER BOARD COMMENTS ON DRAFT SKEET RANGE ROD
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6198431

Document Type: Site Documents **Document Date:** 12/20/2013
Type: RECORD OF DECISION **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: DRAFT SKEET RANGE RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6094001

Document Type: Site Documents **Document Date:** 10/4/2013
Type: CORRESPONDENCE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: AF DECISION TO PRODUCE ONE RECORD OF DECISION FOR THE OU 5 SKEET RANGE SITES AND ONE FOR TCE SOURCE AREAS.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6181620

Document Type: Site Documents **Document Date:** 11/30/2011
Type: CORRESPONDENCE **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: AIR FORCE RESPONSE TO EPA - RE: INFORMAL DISPUTE ON FOCUSED FEASIBILITY STUDY FOR OU5 SITES
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6076595

Document Type: Site Documents **Document Date:** 11/28/2011
Type: WARNING LETTER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA - EPA REVIEW AND INVOCATION OF INFORMAL DISPUTE RESOLUTION REGARDING FINAL OPERABLE UNIT 5 FOCUSED FEASIBILITY STUDY, GAFB, CA AUGUST 2011
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6104903

Document Type: Site Documents **Document Date:** 8/26/2011
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: FINAL OPERABLE UNIT FIVE FOCUSED FEASIBILITY STUDY FORMER GEORGE AFB, MWH 8-26-11
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6097275

Document Type: Site Documents **Document Date:** 12/21/2010
Type: STAFF LETTER **Submitted:**
Submitted By: (REGULATOR)
Title: DRAFT FINAL OU-5 FOCUSED FEASIBILITY STUDY, DECEMBER 21, 2010
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6072597

Document Type: Site Documents **Document Date:** 11/1/2010

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: (REGULATOR)
Title: EPA LETTER - DRAFT OPERABLE UNIT 5 FOCUSED FEASIBILITY STUDY, FORMER GEORGE AIR FORCE BASE, CALIFORNIA, DATED AUGUST 31, 2010
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6068418

Document Type: Site Documents **Document Date:** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6090764

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6226120

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6104642

Document Type: Site Documents **Document Date:** 1/1/1983
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&document_id=6280639

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 1/2/2013

Status: Open - Site Assessment
Date: 4/23/2010

Status: Open - Inactive
Date: 1/14/2010

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	2 of4	NE	0.38 / 1,994.65	2,895.31 / -12	George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100229500
Site Facility Type: MILITARY CLEANUP SITE
Site Fac Type (SRCH):
Case Type (DL): Military Cleanup Site
Status (SRCH):
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Status (DL): Completed - Case Closed
Census Tract (SRCH):
Status Date (DL): 9/30/2011
Latitude (DL): 34.5778791292339
Cleanup Status: COMPLETED - CASE CLOSED AS OF 9/30/2011
Longitude (DL): -117.376137971878
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): -92392
County (DL): San Bernardino

State (DL):	CA
Site Facility Name :	WP017 OU3 FUELS LABORATORY LEACH FIELD
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	-92392
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 58
Local Case No:	400071 -- 58
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	2011-09-30 00:00:00
Potential Media of Concern:	
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	
Coordinate Source:	Manual Entry on Screens
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NULL
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

Bioventing selected as boht interim and final remedy in the 1998 OU-3 Record of Decision. Bioventing was completed in 2004 and the system was decommissioned in 2005.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	2011-09-30 00:00:00
Status:	Open - Verification Monitoring
Status Date:	2001-01-01 00:00:00
Status:	Open - Remediation
Status Date:	1998-11-01 00:00:00

GeoTracker Search - Facilities

Project Status:	
Cuf Claim No:	

CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100229500
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 9/30/2011
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL
DAY CARE CENTER PROHIBITED
ELDER CARE CENTER PROHIBITED
HOSPITAL USE PROHIBITED
LAND USE COVENANT
NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL
NOTIFY PRIOR TO CHANGE IN LAND USE
ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED
PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED
RAISING OF FOOD PROHIBITED
RESIDENCE USE PROHIBITED
Future Land Use: COMMERCIAL
INDUSTRIAL
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 58
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 58
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100229500&tabname=regulatoryhistory
Site History:

Bioventing selected as boht interim and final remedy in the 1998 OU-3 Record of Decision. Bioventing was completed in 2004 and the system was decommissioned in 2005.

GeoTracker Search - Cleanup Action Report

Action Type: IN SITU BIOLOGICAL TREATMENT
Begin Date: 8/1/1995
End Date: 5/1/2004
Phase: Soil
Contaminant Mass Removed:
Description: Soil bioventing system operated form February 1994 until May 1998 and again from late 1998 until 2005 injecting air into subsurface to promote aerobic biodegradation of petroleum hydrocarbons.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=5666575
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Response Requested - Other
Action: Correspondence
Action Date:

Received Issue Date: 2/14/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=6075884
Title Description Comments:

Draft Risk Evaluation for Operable Unit 3 SIte WP-17 of November 2004

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=6288191
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=6277763
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=6280579
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 9/30/2011
Received Issue Date: 9/30/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6099803&temptable=ENFORCEMENT
Title Description Comments:

No Further Action Required - Operable Unit 3 Site WP-17 George AFB San Bernardino Co Geotracker ID# DOD100229500

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009
Received Issue Date: 1/21/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6087292&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed, CERCLA 120(h) Notices and Covenants and Environmental Restrictions - Parcel C-21 (Former George AFB, Aviation Parcels) [AST Bulk Fuels Storage]

Action Type: Response Requested - Other
Action: Correspondence
Action Date: 4/29/2005
Received Issue Date: 4/29/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=5718613
Title Description Comments:

Final OU-3 Site WP-017 Closure Report, Malcolm Pirnie

Action Type: Notices

Action: Letter - Notice
Action Date: 1/20/2005
Received Issue Date: 1/20/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6098537&temptable=ENFORCEMENT
Title Description Comments:

Draft Site WP-17 Risk Evaluation Report (Document 199)

Action Type: Response Requested - Reports
Action: Risk Assessment Report
Action Date: 1/17/2005
Received Issue Date: 1/17/2005
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=5719317
Title Description Comments:

Draft Site WP-17 Risk Evaluation Report

Action Type: Cleanup Action
Action: In Situ Biological Treatment
Action Date: 8/1/1995
Received Issue Date:
Doc Link:
Title Description Comments:

Soil bioventing system operated form February 1994 until May 1998 and again from late 1998 until 2005 injecting air into subsurface to promote aerobic biodegradation of petroleum hydrocarbons.

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100229500&doc_id=6226179
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6104597&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 1/21/2009
Site Manage Req: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, NOTIFY PRIOR TO CHANGE IN LAND USE, ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, RESIDENCE USE PROHIBITED
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/9225568473/George%20Deed%20-%20Parcel%20C-21%20%28Final%20FOST%20PBC%29.pdf

GeoTracker Search - Documents

Document Type: Site Documents
Type: COMMUNITY RELATIONS
Document Date: 7/11/2023
Submitted:

Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=6288191

Document Type: Site Documents **Document Date:** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=6277763

Document Type: Site Documents **Document Date:** 9/30/2011
Type: CLOSURE/NO FURTHER ACTION LETTER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: NO FURTHER ACTION REQUIRED - OPERABLE UNIT 3 SITE WP-17 GEORGE AFB SAN BERNARDINO CO GEOTRACKER ID# DOD100229500
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6099803

Document Type: Site Documents **Document Date:** 1/21/2009
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED, CERCLA 120(H) NOTICES AND COVENANTS AND ENVIRONMENTAL RESTRICTIONS - PARCEL C-21 (FORMER GEORGE AFB, AVIATION PARCELS) [AST BULK FUELS STORAGE]
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6087292

Document Type: Site Documents **Document Date:** 4/29/2005
Type: CORRESPONDENCE **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: FINAL OU-3 SITE WP-017 CLOSURE REPORT, MALCOLM PIRNIE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=5718613

Document Type: Site Documents **Document Date:** 2/14/2005
Type: CORRESPONDENCE **Submitted:**
Submitted By: (REGULATOR)
Title: DRAFT RISK EVALUATION FOR OPERABLE UNIT 3 SITE WP-17 OF NOVEMBER 2004
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=6075884

Document Type: Site Documents **Document Date:** 1/20/2005
Type: LETTER - NOTICE **Submitted:**
Submitted By: (REGULATOR)
Title: DRAFT SITE WP-17 RISK EVALUATION REPORT (DOCUMENT 199)
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6098537

Document Type: Site Documents **Document Date:** 1/17/2005
Type: RISK ASSESSMENT REPORT **Submitted:**
Submitted By: (REGULATOR)
Title: DRAFT SITE WP-17 RISK EVALUATION REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=5719317

Document Type: Site Documents **Document Date:** 11/29/1998
Type: RECORD OF DECISION **Submitted:**
Submitted By: (REGULATOR)
Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=5666575

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=6226179

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6104597

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&document_id=6280579

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 9/30/2011

Status: Open - Verification Monitoring
Date: 1/1/2001

Status: Open - Remediation
Date: 11/1/1998

41	3 of4	NE	0.38 / 1,994.65	2,895.31 / -12	George Air Force Base - OT074 OU5 Original Skeet Range 18374 Phantom West St Victorville CA 92392	DEED

Global ID: DOD100234600
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
Site Type: Military Cleanup Site
County: San Bernardino
Status: Completed - Case Closed
Longitude: -117.374861240387
Status Date: 1/2/2013
Latitude: 34.5761786348656
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100234600

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100234600&enforcement_id=6090764&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf

---

41	4 of4	NE	0.38 / 1,994.65	2,895.31 / -12	George Air Force Base - WP017 OU3 Fuels Laboratory Leach Field 18374 Phantom West St Victorville CA -92392	DEED

Global ID: DOD100229500
RWQCB Region: LAHONTAN RWQCB (REGION 6V)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 9/30/2011
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100229500
County: San Bernardino
Longitude: -117.376137971878
Latitude: 34.5778791292339

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009
Received Issue Date: 1/21/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100229500&enforcement_id=6087292&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed, CERCLA 120(h) Notices and Covenants and Environmental Restrictions - Parcel C-21 (Former George AFB, Aviation Parcels) [AST Bulk Fuels Storage]

GeoTracker Search - Deed Restrictions

Date Recorded: 1/21/2009
Site Manage Req: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, NOTIFY PRIOR TO CHANGE IN LAND USE, ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, RESIDENCE USE PROHIBITED
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/9225568473/George%20Deed%20-%20Parcel%20C-21%20%28Final%20FOST%20PBC%29.pdf

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	1 of2	NE	0.39 / 2,063.73	2,893.60 / -14	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop PHANTOM WEST ST Victorville CA 92392	DEED

Global ID: T10000001719
Site Type: Military UST Site
Status: Completed - Case Closed
Status Date: 10/19/2009
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000001719
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.375955581665
Latitude: 34.5778040432037

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions

Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009
Received Issue Date: 1/21/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6087294&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed, CERCLA 120(h) Notices and Covenants and Environmental Restrictions - Parcel C-21 (Former George AFB, Aviation Parcels) [AST Bulk Fuels Storage]

GeoTracker Search - Deed Restrictions

Date Recorded: 1/21/2009
Site Manage Req: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, NOTIFY PRIOR TO CHANGE IN LAND USE, ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, RESIDENCE USE PROHIBITED
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=T10000001719&enforcement_id=6087294

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	2 of2	NE	0.39 / 2,063.73	2,893.60 / -14	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop PHANTOM WEST ST Victorville CA 92392	LUST

Global ID: T10000001719
Site Facility Type: MILITARY UST SITE
Site Fac Type (SRCH):
Status:
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 10/19/2009
Cleanup Status: COMPLETED - CASE CLOSED AS OF 10/19/2009
Case Type (DL): Military UST Site
Oil Field (SRCH):
Oil Field Oper (SRCH):
Census Tract (SRCH):
Latitude (DL): 34.5778040432037
Longitude (DL): -117.375955581665
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL):
Street Name (DL): PHANTOM WEST ST
City (DL): Victorville
Zip (DL): 92392
County (DL): San Bernardino
State (DL): CA
Business Name (DL): George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop
Site Facility Name: OWS 552-S2 FUEL TRUCK MAINTENANCE SHOP
Address : PHANTOM WEST ST
City : VICTORVILLE
Zip : 92392
County : SAN BERNARDINO
Report Source: LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Case Worker:
Local Agency:
RB Case No:
Local Case No:
File Location: Regional Board

Potential COC:
Potential Media of Concern:
Begin Date: 4/6/2005
How Discovered:
How Discovered Description:
Stop Method:
Stop Description:
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name: Upper Mojave River Valley (6-042)
Disadvantaged Community: Severely Disadvantaged Community
CalEnvScreen Score:
Coordinate Source:
Discharge Cause:
Discharge Source:
EPA Region: 9
Leak Reported Dt:
Military DoD Site: Yes
No Further Action Dt: 2009-10-19 00:00:00
Qty Rlsd Gallons:
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Claim No:
Claim Status:
A2022 Assembly District: 34
A2022 Congressional District: 23
A2022 Senate District: 23
Site History:

No further assessment required. Soil remediation was completed by bioventing. Part of CERCLA SIte WP017 (OU-3).

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 10/19/2009

Status: Completed - Case Closed
Status Date: 4/6/2005

Status: Open - Case Begin Date
Status Date: 4/6/2005

GeoTracker Search - Regulatory Profile

Site Facility Name: OWS 552-S2 FUEL TRUCK MAINTENANCE SHOP
Site Facility Type: MILITARY UST SITE
Cleanup Status: COMPLETED - CASE CLOSED AS OF 10/19/2009
Address: PHANTOM WEST ST
City: VICTORVILLE
Zip: 92392
County: SAN BERNARDINO
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000001719
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/19/2009
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000001719&tabname=regulatoryhistory
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL
DAY CARE CENTER PROHIBITED

ELDER CARE CENTER PROHIBITED
HOSPITAL USE PROHIBITED
LAND USE COVENANT
NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL
NOTIFY PRIOR TO CHANGE IN LAND USE
ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED
PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED
RESIDENCE USE PROHIBITED

Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD)
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Site History:

No further assessment required. Soil remediation was completed by bioventing. Part of CERCLA SIte WP017 (OU-3).

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 10/19/2009

Status: Open - Case Begin Date
Date : 4/6/2005

Status: Completed - Case Closed
Date : 4/6/2005

GeoTracker Search - Cleanup Action Report

Date Recorded: 1/21/2009
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=T10000001719&enforcement_id=6087294
Site Management Rqmts: ACTIVITIES PROHIBITED WHICH DISTURB THE REMEDY AND MONITORING SYSTEMS WITHOUT APPROVAL, DAY CARE CENTER PROHIBITED, ELDER CARE CENTER PROHIBITED, HOSPITAL USE PROHIBITED, LAND USE COVENANT, NO GROUNDWATER EXTRACTION AT ANY DEPTH WITHOUT APPROVAL, NOTIFY PRIOR TO CHANGE IN LAND USE, ONLY EXTRACTION OF GROUNDWATER FOR SITE REMEDIATION PERMITTED, PUBLIC OR PRIVATE SCHOOL FOR PERSONS UNDER 21 PROHIBITED, RESIDENCE USE PROHIBITED

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/19/2012
Received Issue Date: 7/19/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6285706&temptable=ENFORCEMENT
Title Description Comments:

Water Board Comments Draft Final Oil/Water Separator Removal, Sampling, and Closure Report

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 7/29/2010

Received Issue Date: 7/29/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6059994&temptable=ENFORCEMENT
Title Description Comments:

Draft Quality Program Plan for Oil/Water Separator Removal and Closure Sampling

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 10/19/2009
Received Issue Date: 10/19/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6050294&temptable=ENFORCEMENT
Title Description Comments:

Oil/Water Separators Summary Report, Former George AFB, Victorville, San Bernardino County

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 1/21/2009
Received Issue Date: 1/21/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6087294&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed, CERCLA 120(h) Notices and Covenants and Environmental Restrictions - Parcel C-21 (Former George AFB, Aviation Parcels) [AST Bulk Fuels Storage]

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000001719&doc_id=6226121
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6104643&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000001719&doc_id=6288252
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000001719&doc_id=6277824
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000001719&doc_id=6280640
Title Description Comments:

George Air Force Base, Master Plan Base Map

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&document_id=6288252

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&document_id=6277824

Document Type: Site Documents ***Document Date:*** 7/19/2012
Type: STAFF LETTER ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: WATER BOARD COMMENTS DRAFT FINAL OIL/WATER SEPARATOR REMOVAL, SAMPLING, AND CLOSURE REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6285706

Document Type: Site Documents ***Document Date:*** 7/29/2010
Type: SITE VISIT / INSPECTION / SAMPLING ***Submitted:***
Submitted By: (REGULATOR)
Title: DRAFT QUALITY PROGRAM PLAN FOR OIL/WATER SEPARATOR REMOVAL AND CLOSURE SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6059994

Document Type: Site Documents ***Document Date:*** 10/19/2009
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: OIL/WATER SEPARATORS SUMMARY REPORT, FORMER GEORGE AFB, VICTORVILLE, SAN BERNARDINO COUNTY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6050294

Document Type: Site Documents ***Document Date:*** 1/21/2009
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED, CERCLA 120(H) NOTICES AND COVENANTS AND ENVIRONMENTAL RESTRICTIONS - PARCEL C-21 (FORMER GEORGE AFB, AVIATION PARCELS) [AST BULK FUELS STORAGE]
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6087294

Document Type: Site Documents ***Document Date:*** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&document_id=6226121

Document Type: Site Documents ***Document Date:*** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&enforcement_id=6104643

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000001719&document_id=6280640

43	1 of1	NE	0.39 / 2,065.19	2,893.60 / -14	George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop PHANTOM WEST ST VICTORVILLE CA 92392	DELISTED CLEANUP

Delisted GeoTracker Cleanup Program Sites

Global ID: T10000001719
Business Name: George Air Force Base - OWS 552-S2 Fuel Truck Maintenance Shop
RB Case No:
Street No:
Loc Case No:
Street Name: PHANTOM WEST ST
Status: Completed - Case Closed
City: VICTORVILLE
Status Date: 2009-10-19 00:00:00
State: CA
Case Type: Military Cleanup Site
Zip: 92392
Lead Agency: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Case Worker: LCS
Latitude: 34.5778040432037
Local Agency:
Longitude: -117.375955581665
Begin Date: 2005-04-06 00:00:00
File Location: Regional Board
Year: 2016
Potential Contaminants of Con:
Potential Media Affected:
Site History:

No further assessment required. Soil remediation was completed by bioventing. Part of CERCLA SIte WP017 (OU-3).

44	1 of1	NE	0.40 / 2,090.45	2,893.14 / -14	Pacific Aerospace 18200 PHANTOM W VICTORVILLE CA 92394	DELISTED HAZ

Siteid: 54538
Latitude: 34.580383
Longitude: -117.378502
Original Source: CHAZ
Record Date: 04-JAN-2018

45	1 of2	NNE	0.45 / 2,392.35	2,888.95 / -18	George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL Disposal 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100241700
Site Facility Type: MILITARY CLEANUP SITE
Site Fac Type (SRCH):
Case Type (DL): Military Cleanup Site
Status (SRCH):
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Status (DL): Completed - Case Closed
Census Tract (SRCH):
Status Date (DL): 11/1/1998
Latitude (DL): 34.5786874039702
Cleanup Status: COMPLETED - CASE CLOSED AS OF 11/1/1998
Longitude (DL): -117.379710674286
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): -92392

County (DL):	San Bernardino
State (DL):	CA
Site Facility Name :	SD027 OU3 ABANDONED DRAIN PIT/DRY WELL FOR POL DISPOSAL
Address :	18374 PHANTOM WEST ST
City :	VICTORVILLE
Zip :	-92392
County :	SAN BERNARDINO
Report Source:	Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No:	166-61 -- 4
Local Case No:	400071 -- 4
Begin Date:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Local Agency:	
CUF Case:	
CalEnvScreen Score:	
EPA Region:	9
Qty Rlsd Gallons:	
Potential COC:	
How Discovered:	
Stop Method:	
Stop Description:	
Case Worker:	
Military DoD Site:	Yes
Leak Reported Dt:	
No Further Action Dt:	1998-11-01 00:00:00
Potential Media of Concern:	
How Discovered Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	
Coordinate Source:	Google Map Move
Discharge Cause:	
Discharge Source:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NULL
Calenviroscreen 4 Score:	NA
File Location:	Regional Board
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

No Further Action identified in the final Operable Unit Three Record of Decision.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	1998-11-01 00:00:00

GeoTracker Search - Facilities

Project Status:	
Cuf Claim No:	
CUF Priority Assign:	
CUF Amount Paid:	
Composting Method:	
Facility Type:	
WDR Place Type:	
WDR File No:	

WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100241700
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/1/1998
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 4
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 4
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100241700&tabname=regulatoryhistory
Site History:

No Further Action identified in the final Operable Unit Three Record of Decision.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100241700&doc_id=6288179
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100241700&doc_id=5666598
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100241700&doc_id=6280567
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100241700&doc_id=6277751
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&enforcement_id=6090763&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100241700&doc_id=6226167
Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&enforcement_id=6104619&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100241700&enforcement_id=6090763

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&document_id=6288179

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&document_id=6277751

Document Type: Site Documents ***Document Date:*** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&enforcement_id=6090763

Document Type: Site Documents ***Document Date:*** 11/29/1998
Type: RECORD OF DECISION ***Submitted:***
Submitted By: (REGULATOR)
Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&document_id=5666598

Document Type: Site Documents ***Document Date:*** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&document_id=6226167

Document Type: Site Documents
Document Date: 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER
Submitted:
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&enforcement_id=6104619

Document Type: Site Documents
Document Date: 1/1/1983
Type: OTHER REPORT / DOCUMENT
Submitted:
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&document_id=6280567

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 11/1/1998

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	2 of2	NNE	0.45 / 2,392.35	2,888.95 / -18	George Air Force Base - SD027 OU3 Abandoned Drain Pit/Dry Well for POL Disposal 18374 Phantom West St Victorville CA -92392	DEED

Global ID: DOD100241700
Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 11/1/1998
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100241700
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.379710674286
Latitude: 34.5786874039702

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100241700&enforcement_id=6090763&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100241700&enforcement_id=6090763

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
46	1 of1	W	0.47 / 2,481.34	2,900.12 / -7	CIRCLE K#8644 11724 AIR BASE RD	LUST

ADELANTO CA 92301

Global ID:	T0607100928	***Case Type (DL):***	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	***Oil Field (SRCH):***	
Site Fac Type (SRCH):	LUST CLEANUP SITE	***Oil Field Oper (SRCH):***	
Status:		***Census Tract (SRCH):***	6071009116
Status (SRCH):	COMPLETED - CASE CLOSED	***Latitude (DL):***	34.572334
Status (DL):	Completed - Case Closed	***Longitude (DL):***	-117.408801
Status Date (DL):	7/6/2001	***RWQCB Region (DL):***	LAHONTAN RWQCB (REGION 6V)
Cleanup Status:	COMPLETED - CASE CLOSED		

Site Facility Name (SRCH):	CIRCLE K#8644
Address (SRCH):	11724 AIR BASE RD
City (SRCH):	ADELANTO
Zip (SRCH):	92301
County (SRCH):	SAN BERNARDINO
Street No (DL):	11724
Street Name (DL):	AIR BASE RD
City (DL):	ADELANTO
Zip (DL):	92301
County (DL):	San Bernardino
State (DL):	CA
Business Name (DL):	CIRCLE K#8644
Site Facility Name:	CIRCLE K#8644
Address :	11724 AIR BASE RD
City :	ADELANTO
Zip :	92301
County :	SAN BERNARDINO
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	SAN BERNARDINO COUNTY
Case Worker:	JC
Local Agency:	SAN BERNARDINO COUNTY
RB Case No:	6B3600913T
Local Case No:	98071
File Location:	Local Agency
Potential COC:	Gasoline
Potential Media of Concern:	Soil
Begin Date:	7/1/1998
How Discovered:	Other Means
How Discovered Description:	
Stop Method:	
Stop Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	Google Geocode
Discharge Cause:	Unknown
Discharge Source:	Piping
EPA Region:	9
Leak Reported Dt:	1998-07-10 00:00:00
Military DoD Site:	No
No Further Action Dt:	2001-07-06 00:00:00
Qty Rlsd Gallons:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	81-85%
Calenviroscreen 4 Score:	75-80%
Claim No:	
Claim Status:	
A2022 Assembly District:	39
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:	Local Agency Caseworker - Primary Caseworker
Contact Name:	JACKSON CRUTSINGER
Organization Name:	SAN BERNARDINO COUNTY
Address:	620 SOUTH E STREET
City:	SAN BERNARDINO
Email:	jcrutsinger@sbcfire.org
Phone No:	

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	7/6/2001
Status:	Open - Site Assessment
Status Date:	10/15/1998
Status:	Open - Site Assessment
Status Date:	7/10/1998
Status:	Open - Case Begin Date
Status Date:	7/1/1998

GeoTracker Search - Regulatory Profile

Site Facility Name:	CIRCLE K#8644
Site Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Address:	11724 AIR BASE RD
City:	ADELANTO
Zip:	92301
County:	SAN BERNARDINO
Report Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T0607100928
Cleanup Status Detail:	COMPLETED - CASE CLOSED AS OF 7/6/2001
Project Status:	
Cleanup History Link:	https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0607100928&tabname=regulatoryhistory
Potential COC:	GASOLINE
Potential Media of Concern:	SOIL
File Location:	LOCAL AGENCY
User Defined Beneficial Use:	
Designated Beneficial Use:	MUN, AGR, IND, FRSH, AQUA
DWR GW Sub Basin:	Upper Mojave River Valley (6-042)
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
Post Closure Site Management:	
Future Land Use:	
Cleanup Oversight Agencies:	SAN BERNARDINO COUNTY (LEAD) - CASE #: 98071 CASE MANAGER: JACKSON CRUTSINGER LAHONTAN RWQCB (REGION 6V) - CASE #: 6B3600913T
CUF Claim No:	
CUF Priority Assig:	
CUF Amount Paid:	
WDR Place Type:	
WDR File No:	
WDR Order No:	
Project Oversight Agencies:	
Facility Type:	
Composting Method:	
Grndwtr Monitoring Frequency:	
Designated Beneficial Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Site History:	

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 7/6/2001

Status: Open - Site Assessment
Date : 10/15/1998

Status: Open - Site Assessment
Date : 7/10/1998

Status: Open - Case Begin Date
Date : 7/1/1998

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 4/3/2002
Received Issue Date: 4/3/2002
Doc Link:
Title Description Comments:

AEO-signed mass mailed letter reminding RP of EDF submittal requirement per AB 2886

Action Type: Enforcement/Orders
Action: * Historical Enforcement
Action Date: 10/15/1998
Received Issue Date: 10/15/1998
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Stopped
Action Date: 9/2/1998
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Reported
Action Date: 7/10/1998
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Discovery
Action Date: 7/1/1998
Received Issue Date:
Doc Link:
Title Description Comments:

47	***1 of2***	***NNE***	***0.47 / 2,488.41***	***2,887.80 / -19***	***George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop 12985 Aerospace Drive Victorville CA 92394***	***DEED***

Global ID: T10000002045
Site Type: Military UST Site
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino

Status: Completed - Case Closed
Status Date: 10/12/2010
Facility Project Sub Type:
Calenviroscreen 3 Score: NA
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000002045
Longitude: -117.380847930908
Latitude: 34.5789524103695

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6090765&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
47	2 of2	NNE	0.47 / 2,488.41	2,887.80 / -19	George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop 12985 Aerospace Drive Victorville CA 92394	LUST

Global ID: T10000002045
Site Facility Type: MILITARY UST SITE
Site Fac Type (SRCH):
Status:
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 10/12/2010
Cleanup Status: COMPLETED - CASE CLOSED AS OF 10/12/2010
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 12985
Street Name (DL): Aerospace Drive
City (DL): Victorville
Zip (DL): 92394
County (DL): San Bernardino
State (DL): CA
Business Name (DL): George Air Force Base - BLDG 686 - Jet Engine Maintenance Shop
Site Facility Name: BLDG 686 - JET ENGINE MAINTENANCE SHOP
Address : 12985 AEROSPACE DRIVE
City : VICTORVILLE
Zip : 92394
County : SAN BERNARDINO
Report Source: LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites
Case Type (DL): Military UST Site
Oil Field (SRCH):
Oil Field Oper (SRCH):
Census Tract (SRCH):
Latitude (DL): 34.5789524103695
Longitude (DL): -117.380847930908
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)

from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	LAHONTAN RWQCB (REGION 6V)
Case Worker:	
Local Agency:	
RB Case No:	
Local Case No:	
File Location:	Regional Board
Potential COC:	Diesel
Potential Media of Concern:	Soil
Begin Date:	9/24/1990
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	Remove Contents
Stop Description:	
Calwater Watershed Name:	Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name:	Upper Mojave River Valley (6-042)
Disadvantaged Community:	Severely Disadvantaged Community
CalEnvScreen Score:	
Coordinate Source:	Manual Entry on Screens
Discharge Cause:	Physc / Mech Damage
Discharge Source:	Tank
EPA Region:	9
Leak Reported Dt:	2009-07-30 00:00:00
Military DoD Site:	Yes
No Further Action Dt:	2010-10-12 00:00:00
Qty Rlsd Gallons:	
Facility Project Sub Type:	
Calenviroscreen 3 Score:	NA
Calenviroscreen 4 Score:	NA
Claim No:	
Claim Status:	
A2022 Assembly District:	34
A2022 Congressional District:	23
A2022 Senate District:	23
Site History:	

Building 686 contained one (1) 12,000-gallon heating oil (Diesel #2) steel UST. This UST was removed on December 4, 1990 and two (2) confirmation soil samples were collected and analyzed by EPA Method 8015 modified-diesel. The east sample result was 25.0 micrograms per gram (ppm) for Total Petroleum Hydrocarbon (TPH)-deisel, and the west sample was non detect.

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	10/12/2010
Status:	Open - Site Assessment
Status Date:	3/22/2001
Status:	Open - Case Begin Date
Status Date:	9/24/1990

GeoTracker Search - Regulatory Profile

Site Facility Name:	BLDG 686 - JET ENGINE MAINTENANCE SHOP
Site Facility Type:	MILITARY UST SITE
Cleanup Status:	COMPLETED - CASE CLOSED AS OF 10/12/2010
Address:	12985 AEROSPACE DRIVE
City:	VICTORVILLE
Zip:	92394
County:	SAN BERNARDINO
Report Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000002045

Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/12/2010
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000002045&tabname=regulatoryhistory
Potential COC: DIESEL
Potential Media of Concern: SOIL
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD)
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Site History:

Building 686 contained one (1) 12,000-gallon heating oil (Diesel #2) steel UST. This UST was removed on December 4, 1990 and two (2) confirmation soil samples were collected and analyzed by EPA Method 8015 modified-diesel. The east sample result was 25.0 micrograms per gram (ppm) for Total Petroleum Hydrocarbon (TPH)-deisel, and the west sample was non detect.

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 10/12/2010

Status: Open - Site Assessment
Date : 3/22/2001

Status: Open - Case Begin Date
Date : 9/24/1990

GeoTracker Search - Cleanup Action Report

Date Recorded: 2/28/2002
Covenant Doc Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4807357609/Quitclaim%20Deed%20Recorded%2002.28.02re%20Portion%20of%20Parcel%20D-1%20%28Except.pdf
Site Management Rqmts: SEE LAND USE CONTROL DOCUMENT

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 10/12/2010
Received Issue Date: 10/12/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6066461&temptable=ENFORCEMENT
Title Description Comments:

Completed - Case Closed - 24 Leaking USTs at Former GAFB

Action Type: Response Requested - Other
Action: Correspondence

Action Date: 6/17/2010
Received Issue Date: 6/17/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=5670082
Title Description Comments:

BLDG 686 UST Information

Action Type: Leak Action
Action: Leak Reported
Action Date: 7/30/2009
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6090765&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=6226208
Title Description Comments:

Environmental Baseline Survey

Action Type: Leak Action
Action: Leak Discovery
Action Date: 12/4/1990
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6104679&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=6288220
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023

Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=6277792
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - Reports
Action: Tank Removal Report / UST Sampling Report
Action Date:
Received Issue Date: 5/11/2007
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=6334237
Title Description Comments:

Final UST Summary Report

Action Type: Response Requested - Other
Action: Correspondence
Action Date:
Received Issue Date: 5/23/1999
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=5669788
Title Description Comments:

City of Victorville UST Closure Letter

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000002045&doc_id=6280608
Title Description Comments:

George Air Force Base, Master Plan Base Map

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=6288220

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=6277792

Document Type: Site Documents ***Document Date:*** 10/12/2010
Type: CLOSURE/NO FURTHER ACTION LETTER ***Submitted:***
Submitted By: (REGULATOR)
Title: COMPLETED - CASE CLOSED - 24 LEAKING USTS AT FORMER GAFB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6066461

Document Type: Site Documents ***Document Date:*** 6/17/2010
Type: CORRESPONDENCE ***Submitted:***
Submitted By: (REGULATOR)
Title: BLDG 686 UST INFORMATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=5670082

Document Type: Site Documents ***Document Date:*** 5/11/2007
Type: TANK REMOVAL REPORT / UST SAMPLING REPORT ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: FINAL UST SUMMARY REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=6334237

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type: Site Documents **Document Date:** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6090765

Document Type: Site Documents **Document Date:** 5/23/1999
Type: CORRESPONDENCE **Submitted:**
Submitted By: (REGULATOR)
Title: CITY OF VICTORVILLE UST CLOSURE LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=5669788

Document Type: Site Documents **Document Date:** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE **Submitted:**
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=6226208

Document Type: Site Documents **Document Date:** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER **Submitted:**
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&enforcement_id=6104679

Document Type: Site Documents **Document Date:** 1/1/1983
Type: OTHER REPORT / DOCUMENT **Submitted:**
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000002045&document_id=6280608

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
48	1 of2	NNE	0.50 / 2,629.30	2,887.63 / -20	George Air Force Base - SS024 Building 580 OU3 unserviced transformer storage 18374 Phantom West St Victorville CA -92392	CLEANUP SITES

Global ID: DOD100226300
Site Fac Type (SRCH):
Status (SRCH):
Status (DL): Completed - Case Closed
Status Date (DL): 11/1/1998
Cleanup Status: COMPLETED - CASE CLOSED AS OF 11/1/1998
Site Facility Type: MILITARY CLEANUP SITE
Case Type (DL): Military Cleanup Site
RWQCB Region (DL): LAHONTAN RWQCB (REGION 6V)
Census Tract (SRCH):
Latitude (DL): 34.5793410848935
Longitude (DL): -117.380075454712
Site Facility Name (SRCH):
Address (SRCH):
City (SRCH):
Zip (SRCH):
County (SRCH):
Street No (DL): 18374
Street Name (DL): Phantom West St
City (DL): Victorville
Zip (DL): -92392
County (DL): San Bernardino
State (DL): CA
Site Facility Name : SS024 BUILDING 580 OU3 UNSERVICED TRANSFORMER STORAGE
Address : 18374 PHANTOM WEST ST
City : VICTORVILLE
Zip : -92392
County : SAN BERNARDINO
Report Source: Cleanup Sites from GeoTracker Cleanup Sites Data Download; GeoTracker Search Results Report (as of 11 Aug 2025)

GeoTracker Sites Data Download - Site Details

RB Case No: 166-61 -- 74
Local Case No: 400071 -- 74
Begin Date:
Lead Agency: LAHONTAN RWQCB (REGION 6V)
Local Agency:
CUF Case:
CalEnvScreen Score:
EPA Region: 9
Qty Rlsd Gallons:
Potential COC:
How Discovered:
Stop Method:
Stop Description:
Case Worker:
Military DoD Site: Yes
Leak Reported Dt:
No Further Action Dt: 1998-11-01 00:00:00
Potential Media of Concern:
How Discovered Description:
Calwater Watershed Name: Mojave - Upper Mojave (628.20)
DWR GW Subbasin Name: Upper Mojave River Valley (6-042)
Disadvantaged Community:
Coordinate Source: Manual Entry on Screens
Discharge Cause:
Discharge Source:
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
File Location: Regional Board
Claim No:
Claim Status:
A2022 Assembly District: 34
A2022 Congressional District: 23
A2022 Senate District: 23
Site History:

No Further Action identified in the final Operable Unit Three Record of Decision.

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1998-11-01 00:00:00

GeoTracker Search - Facilities

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
WDR File No:
WDR Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, FRSH, AQUA
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100226300
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/1/1998
Potential COC: NONE SPECIFIED
Potential Media of Concern: NONE SPECIFIED
Groundwater Monitoring Freq:
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
CalWater Watershed Name: Mojave - Upper Mojave (628.20)

Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD) - CASE #: 166-61 -- 74
DEPARTMENT OF TOXIC SUBSTANCES CONTROL - CASE #: 400071 -- 74
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=DOD100226300&tabname=regulatoryhistory
Site History:

No Further Action identified in the final Operable Unit Three Record of Decision.

GeoTracker Search - Regulatory Activities

Action Type: Response Requested - Other
Action: Fact Sheets - Public Participation
Action Date:
Received Issue Date: 4/7/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226300&doc_id=6277757
Title Description Comments:

GAFB RAB Interest Flier 4/2023

Action Type: Response Requested - Reports
Action: Record of Decision
Action Date:
Received Issue Date: 11/29/1998
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226300&doc_id=5666603
Title Description Comments:

George AFB OU3 Record of Decision

Action Type: Response Requested - JEP Activity
Action: Community Relations
Action Date:
Received Issue Date: 7/11/2023
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226300&doc_id=6288185
Title Description Comments:

Notice to Not Establish RAB

Action Type: Response Requested - Other
Action: Other Report / Document
Action Date:
Received Issue Date: 1/1/1983
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226300&doc_id=6280573
Title Description Comments:

George Air Force Base, Master Plan Base Map

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&enforcement_id=6091915&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

Action Type: Response Requested - Reports
Action: Environmental Baseline Survey Complete
Action Date: 12/14/1994
Received Issue Date: 12/14/1994
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=DOD100226300&doc_id=6226173

Title Description Comments:

Environmental Baseline Survey

Action Type: Other Regulatory Actions
Action: Technical Correspondence / Assistance / Other
Action Date: 2/1/1990
Received Issue Date: 2/1/1990
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&enforcement_id=6104625&temptable=ENFORCEMENT
Title Description Comments:

EPA Aerial Photograph Aalysis of George AFB - Feb 1990

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100226300&enforcement_id=6091915

GeoTracker Search - Documents

Document Type: Site Documents ***Document Date:*** 7/11/2023
Type: COMMUNITY RELATIONS ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: NOTICE TO NOT ESTABLISH RAB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&document_id=6288185

Document Type: Site Documents ***Document Date:*** 4/7/2023
Type: FACT SHEETS - PUBLIC PARTICIPATION ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)
Title: GAFB RAB INTEREST FLIER 4/2023
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&document_id=6277757

Document Type: Site Documents ***Document Date:*** 2/28/2002
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: QUITCLAIM DEED - MAIN GATE PARCEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&enforcement_id=6091915

Document Type: Site Documents ***Document Date:*** 11/29/1998
Type: RECORD OF DECISION ***Submitted:***
Submitted By: (REGULATOR)
Title: GEORGE AFB OU3 RECORD OF DECISION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&document_id=5666603

Document Type: Site Documents ***Document Date:*** 12/14/1994
Type: ENVIRONMENTAL BASELINE SURVEY COMPLETE ***Submitted:***
Submitted By: LINDA STONE (REGULATOR)
Title: ENVIRONMENTAL BASELINE SURVEY
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&document_id=6226173

Document Type: Site Documents ***Document Date:*** 2/1/1990
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER ***Submitted:***
Submitted By: JEHIEL CASS (REGULATOR)
Title: EPA AERIAL PHOTOGRAPH AALYSIS OF GEORGE AFB - FEB 1990
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&enforcement_id=6104625

Document Type: Site Documents ***Document Date:*** 1/1/1983
Type: OTHER REPORT / DOCUMENT ***Submitted:***
Submitted By: LORIEN SANDERS (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title: GEORGE AIR FORCE BASE, MASTER PLAN BASE MAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&document_id=6280573

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date: 11/1/1998

---

48 | **2 of2** | **NNE** | **0.50 / 2,629.30** | **2,887.63 / -20** | **George Air Force Base - SS024**
Building 580 OU3 unserviced transformer storage
18374 Phantom West St
Victorville CA -92392 | **DEED**

Global ID: DOD100226300
Site Type: Military Cleanup Site
Status: Completed - Case Closed
Status Date: 11/1/1998
Facility Project Sub Type:
Calenviroscreen 3 Score: NULL
Calenviroscreen 4 Score: NA
Search URL: https://geotracker.waterboards.ca.gov/profile_report?global_id=DOD100226300
RWQCB Region: LAHONTAN RWQCB (REGION 6V)
County: San Bernardino
Longitude: -117.380075454712
Latitude: 34.5793410848935

GeoTracker Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Deed Restriction / Land Use Restriction / Covenant
Action Date: 2/28/2002
Received Issue Date: 2/28/2002
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=DOD100226300&enforcement_id=6091915&temptable=ENFORCEMENT
Title Description Comments:

Quitclaim Deed - Main Gate Parcel

GeoTracker Search - Deed Restrictions

Date Recorded: 2/28/2002
Site Manage Req: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=DOD100226300&enforcement_id=6091915

---

49 | **1 of1** | **NNE** | **0.63 / 3,328.58** | **2,886.64 / -21** | **ANCON MARINE - VICTORVILLE - CAD980737068**
13313 SABRE BLVD UNIT 1
VICTORVILLE CA 92394 | **INSP**
COMP ENF

EPA ID: 3005643
Geotracker Address:
Geotracker City:
Report URL:
County: SAN BERNARDINO
Geotracker Lat:
Geotracker Long:

EnviroStor Site / Facility Export - Inspection Details

Inspection Type: Compliance Evaluation Inspection -
Return to Complnc:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Transporter

Violations: No Violations
Inspection Date: 1/22/2026
Report Sent Date:
Address: 13313 SABRE BLVD UNIT 1
Project Name: ANCON MARINE - VICTORVILLE - CAD980737068
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 92394

Inspection, Compliance and Enforcement Download - Site Details

Envirostor ID: 3005643
Site Type: INSPECTION
Status: No Action

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
50	1 of1	NNE	0.78 / 4,098.44	2,881.91 / -25	Sumiden Wire Products Corp. 13290 Sabre Boulevard Victorville CA 92394	ENVIROSTOR

Envirostor ID: 71003480
Site History:

Facilities Details

Estor/EPA ID: 71003480
Program Type: TIERED PERMIT
Program Type1:
Status: INACTIVE - NEEDS EVALUATION
Site Facility Name: SUMIDEN WIRE PRODUCTS CORP.
Site Type: TIERED PERMIT
Address Desc: 13290 SABRE BOULEVARD
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 92394
Acres: NONE SPECIFIED
Site Code:
APN: NONE SPECIFIED
Assembly District: 34
Census Tract: 6071980200
Funding:
Office: CLEANUP CYPRESS
Project Manager:
Special Program:
Supervisor:
Senate District: 23
Public Participation Specialis:
Cal Enviro Screen Score: NA
National Priority List: NO
Past Use that Caused Contam: NONE SPECIFIED
Permit Renewal Lead:
Cleanup Oversight Agencies: NONE SPECIFIED
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF
Potential Conta of Conc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
School District:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003480

Search Results Details

Program Type: TIERED PERMIT
Site Code:
Status: INACTIVE - NEEDS EVALUATION
Status Date:
Cal Enviroscreen Score: NA
Office: Cleanup Cypress
PM:
Supervisor:
Branch Chief:
Address Description: 13290 SABRE BOULEVARD
Site Facility Name: SUMIDEN WIRE PRODUCTS CORP.
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 92394
Latitude: 34.583235
Longitude: -117.374169

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sites Details

Status:	Inactive - Needs Evaluation	***Assembly:***	34
Status Date:		***Division Branch:***	Cleanup Cypress
Site Code:		***Funding:***	
Site Type:	Tiered Permit	***Lead Agency:***	NONE SPECIFIED
Site Type Detailed:	Tiered Permit	***Project Manager:***	
Special Program:		***Supervisor:***	
City:	Victorville	***Restricted Use:***	NO
County:	SAN BERNARDINO	***Senate:***	23
Congres Dis:	23	***Site Mgmt Req:***	NONE SPECIFIED
State :	CA	***Acres:***	
Latitude:	34.583235	***Zip:***	92394
Longitude:	-117.374169		
Address:	13290 Sabre Boulevard		
National Priorities List:	NO		
APN:	NONE SPECIFIED		
Confirmed Coc:	NONE SPECIFIED		
Past Uses:	NONE SPECIFIED		
Potential Coc:	NONE SPECIFIED		
Potential Media Affected:	NONE SPECIFIED		
Project Name:	Sumiden Wire Products Corp.		
Regulatory Agencies Involved:	NONE SPECIFIED		

51	***1 of2***	***NE***	***0.78 / 4,109.50***	***2,882.67 / -24***	***VV ARMY FLYING SCHOOL*** ***Victorville CA***	***ENVIROSTOR***

Envirostor ID:	80000869
Site History:	

Facilities Details

Estor/EPA ID:	80000869	***Site Code:***	
Program Type:	MILITARY EVALUATION	***APN:***	NONE SPECIFIED
Program Type1:		***Assembly District:***	34
Status:	INACTIVE - NEEDS EVALUATION	***Census Tract:***	6071980200
Site Facility Name:	VV ARMY FLYING SCHOOL	***Funding:***	DERA
Site Type:	FUDS	***Office:***	CLEANUP CYPRESS
Address Desc:		***Project Manager:***	
City:	VICTORVILLE	***Special Program:***	
County:	SAN BERNARDINO	***Supervisor:***	EILEEN MANANIAN
Zip:		***Senate District:***	23
Acres:	0 ACRES		
Public Participation Specialis:			
Cal Enviro Screen Score:	NA		
National Priority List:	NO		
Past Use that Caused Contam:	NONE SPECIFIED		
Permit Renewal Lead:			
Cleanup Oversight Agencies:	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
Cleanup Status:	INACTIVE - NEEDS EVALUATION AS OF 7/1/2005		
Potential Conta of Conc:	NONE SPECIFIED		
Potential Media Affected:	NONE SPECIFIED		
School District:			
Summary Link:	https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000869		

Completed Activities

Title:	USACE INPR Summary J0CA716700 30 Mar 1999
Title Link:	https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80000869&doc_id=5011180
Area Name:	
Area Link:	
Sub Area:	
Sub Area Link:	
Document Type:	Inventory Project Report (INPR)

Date Completed: 3/30/1999
Comments:
Activity Type: Completed Activities

Search Results Details

Program Type: MILITARY EVALUATION
Site Code:
Status: INACTIVE - NEEDS EVALUATION
Status Date: 7/1/2005
Cal Enviroscreen Score: NA
Office: Cleanup Cypress
PM:
Supervisor: Eileen Mananian
Branch Chief: Benjamin Stanphill
Address Description:
Site Facility Name: VV ARMY FLYING SCHOOL
City: VICTORVILLE
County: SAN BERNARDINO
Zip:
Latitude: 34.5833333333333
Longitude: -117.372222222222

Sites Details

Status: Inactive - Needs Evaluation
Status Date: 7/01/2005
Site Code:
Site Type: Military Evaluation
Site Type Detailed: FUDS
Special Program:
City: Victorville
County: SAN BERNARDINO
Congres Dis: 23
State : CA
Latitude: 34.5833333333333
Longitude: -117.372222222222
Address:
Assembly: 34
Division Branch: Cleanup Cypress
Funding: DERA
Lead Agency: SMBRP
Project Manager:
Supervisor: Eileen Mananian
Restricted Use: NO
Senate: 23
Site Mgmt Req: NONE SPECIFIED
Acres: 0
Zip:
National Priorities List: NO
APN: NONE SPECIFIED
Confirmed Coc: NONE SPECIFIED
Past Uses: NONE SPECIFIED
Potential Coc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Project Name: VV ARMY FLYING SCHOOL
Regulatory Agencies Involved: SMBRP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	2 of2	NE	0.78 / 4,109.50	2,882.67 / -24	VICTORVILLE AFB Victorville CA	ENVIROSTOR

Envirostor ID: 80000728
Site History:

Facilities Details

Estor/EPA ID: 80000728
Program Type: MILITARY EVALUATION
Program Type1:
Status: INACTIVE - NEEDS EVALUATION
Site Facility Name: VICTORVILLE AFB
Site Type: FUDS
Address Desc:
City: VICTORVILLE
Site Code:
APN: NONE SPECIFIED
Assembly District: 34
Census Tract: 6071980200
Funding: DERA
Office: CLEANUP CYPRESS
Project Manager:
Special Program:

County: SAN BERNARDINO
Supervisor: EILEEN MANANIAN
Zip:
Senate District: 23
Acres: 0 ACRES
Public Participation Specialis:
Cal Enviro Screen Score: NA
National Priority List: NO
Past Use that Caused Contam: NONE SPECIFIED
Permit Renewal Lead:
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Potential Conta of Conc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
School District:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000728

Completed Activities

Title: USACE ASR Summary J0CA700300 5 Jan 1995
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80000728&doc_id=5011439
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Archive Search Report (ASR)
Date Completed: 1/5/1995
Comments:
Activity Type: Completed Activities

Title: USACE INPR Summary J0CA700300 5 Jan 1995
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80000728&doc_id=5011102
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Inventory Project Report (INPR)
Date Completed: 1/5/1995
Comments:
Activity Type: Completed Activities

Search Results Details

Program Type: MILITARY EVALUATION
Site Code:
Status: INACTIVE - NEEDS EVALUATION
Status Date: 7/1/2005
Cal Enviroscreen Score: NA
Office: Cleanup Cypress
PM:
Supervisor: Eileen Mananian
Branch Chief: Benjamin Stanphill
Address Description:
Site Facility Name: VICTORVILLE AFB
City: VICTORVILLE
County: SAN BERNARDINO
Zip:
Latitude: 34.5833333333333
Longitude: -117.372222222222

Sites Details

Status: Inactive - Needs Evaluation
Assembly: 34
Status Date: 7/01/2005
Division Branch: Cleanup Cypress
Site Code:
Funding: DERA
Site Type: Military Evaluation
Lead Agency: SMBRP
Site Type Detailed: FUDS
Project Manager:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Special Program:
City: Victorville
County: SAN BERNARDINO
Congres Dis: 23
State : CA
Latitude: 34.5833333333333
Longitude: -117.372222222222
Address:
National Priorities List: NO
APN: NONE SPECIFIED
Confirmed Coc: NONE SPECIFIED
Past Uses: NONE SPECIFIED
Potential Coc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Project Name: VICTORVILLE AFB
Regulatory Agencies Involved: SMBRP

Supervisor: Eileen Mananian
Restricted Use: NO
Senate: 23
Site Mgmt Req: NONE SPECIFIED
Acres: 0
Zip:

52	1 of3	NNE	0.80 / 4,215.80	2,880.88 / -26	GEORGE AIR FORCE BASE 18374 PHANTOM WEST ST VICTORVILLE CA 923920000	ENVIROSTOR

Envirostor ID: 80001244
Site History:

George AFB had various hazardous waste operations. Although there are lots of files on this facility (75 boxes), RCRA or Permitting files are limited, most of documents are related to CERCLA work.

On 11/19/80, facility submitted a Part A application for 4 units. 1) Storage container unit 2) PCB container unit 3) Wastewater treatment unit 4) OBOD unit

It is not known if an ISD was issued for the WW treatment unit but ISD was issued for container storage/PCB/OBOD units. George AFB submitted a Part B application on 7/18/83. The part B application does not show the WW treatment unit but included a tank storage unit consisting of three 6000 gallon tanks. Therefore permit was issued for 1) Container Storage unit 2) PCB storage unit 3) OBOD unit 4) Tank Storage unit. Part B permit was issued on 6/28/95.

In 1992 closure process of the permitted units except for OBOD units began. A draft CP was submitted in Jan 1992. The closure plan was public noticed on 8/17/93. Closure certification was submitted on February 1994. Closure verification was issued on 6/6/94.

Very little of closure documents for OB/OD could be found in files. A letter requesting public notice of closure for 10/26/94 was issued. Closure plan approval letter was issued on 1/31/95. A closure certification document dated December 1999 (draft)/August 2000. was found in file. As of 1/1/08, PM states closure has not been completed for the OB/OD unit.

All the corrective action work looks to be undertaken by Site Mitigation. See Site Mit Envirostor for more info.

Facilities Details

Estor/EPA ID: 80001244
Program Type: CORRECTIVE ACTION
Program Type1:
Status: REFER: RWQCB
Site Facility Name: GEORGE AIR FORCE BASE
Site Type: CORRECTIVE ACTION
Address Desc: 18374 PHANTOM WEST ST
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 923920000
Acres: 0 ACRES
Public Participation Specialis:
Cal Enviro Screen Score: NA
National Priority List: NO
Past Use that Caused Contam: NONE SPECIFIED
Permit Renewal Lead:
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM
Cleanup Status: REFER: RWQCB AS OF 12/7/2018
Potential Conta of Conc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
School District:

Site Code:
APN: NONE SPECIFIED
Assembly District: 34
Census Tract: 6071980200
Funding:
Office: CLEANUP CYPRESS
Project Manager:
Special Program:
Supervisor:
Senate District: 23

Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244

Completed Activities

Title: PA OR CERCLA INSPECTION-NOT A PA PLUS (CA049PA)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Assessment Report
Date Completed: 6/1/1987
Comments:
Activity Type: Completed Activities

Title: CMS APPROVED (CA350)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Corrective Measures Study Report
Date Completed: 7/29/1997
Comments:
Activity Type: Completed Activities

Title: RFI REPORT APPROVED (CA200)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: RFI Report
Date Completed: 7/29/1997
Comments:
Activity Type: Completed Activities

Title: Remedy Selected
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Remedy Selected
Date Completed: 3/7/1994
Comments:
Activity Type: Completed Activities

Title: CORRECTIVE MEASURES DESIGN APPROVED (CA450)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Design/Implementation Workplan
Date Completed: 2/16/1996
Comments:
Activity Type: Completed Activities

Title: DATE FOR REMEDY SELECTION (CM IMPOSED) (CA400)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Remedy Selection and Statement of Basis
Date Completed: 3/7/1994
Comments:

Activity Type: Completed Activities

Title:
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: RCRA Facility Assessment Report
Date Completed: 6/1/1987
Comments:
Activity Type: Completed Activities

Title: STABILIZATION MEASURES IMPLEMENTED-PRIMARY MEAS IS SOURCE REMOVL &/OR TRT (CA600SR)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Interim Measures Workplan
Date Completed: 7/1/1991
Comments:
Activity Type: Completed Activities

Title: PA OR CERCLA INSPECTION-CERCLA SITE INSPECTION (CA049SI)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Assessment Report
Date Completed: 6/1/1987
Comments:
Activity Type: Completed Activities

Title: Human Exposure Controlled
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Human Exposure Controlled
Date Completed: 6/18/1998
Comments:
Activity Type: Completed Activities

Title: RFA COMPLETED (CA050R9)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: RCRA Facility Assessment Report
Date Completed: 6/1/1987
Comments:
Activity Type: Completed Activities

Title: Consent Order
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Consent Order
Date Completed: 7/1/1991
Comments:
Activity Type: Completed Activities

Title: STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION (CA225NR)

Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Interim Measures Questionnaire
Date Completed: 6/18/1998
Comments:
Activity Type: Completed Activities

Title: Remedy Constructed
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedy Construction Complete
Date Completed: 12/30/1996
Comments:
Activity Type: Completed Activities

Title: CMS WORKPLAN APPROVED (CA300)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Corrective Measures Study Workplan
Date Completed: 7/29/1997
Comments:
Activity Type: Completed Activities

Title: CMI WORKPLAN APPROVED (CA500)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Corrective Measure Implementation Workplan
Date Completed: 9/10/1997
Comments:
Activity Type: Completed Activities

Title: CERTIFICATION OF REMEDY COMPLETION (CMI) (CA550)
Title Link:
Area Name:
Area Link:
Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Remedy Constructed: Operating Properly & Successfully
Date Completed: 12/30/1996
Comments:
Activity Type: Completed Activities

Title: RFI WORKPLAN APPROVED (CA150)
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: RFI Workplan
Date Completed: 7/29/1997
Comments:
Activity Type: Completed Activities

Title: STABILIZATION CONSTRUCTION COMPLETED (CA650)
Title Link:
Area Name:
Area Link:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sub Area: OU 1
Sub Area Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001244&site_id=2008925
Document Type: Interim Measures Implementation Report
Date Completed: 1/1/1995
Comments:
Activity Type: Completed Activities

Title: Groundwater Migration Controlled
Title Link:
Area Name: PROJECT WIDE
Area Link:
Sub Area:
Sub Area Link:
Document Type: Groundwater Migration Controlled
Date Completed: 6/18/1998
Comments:
Activity Type: Completed Activities

Search Results Details

Program Type: CORRECTIVE ACTION
Site Code:
Status: REFER: RWQCB
Status Date: 12/7/2018
Cal Enviroscreen Score: NA
Office: Cleanup Cypress
PM:
Supervisor: * Unknown
Branch Chief:
Address Description: 18374 PHANTOM WEST ST
Site Facility Name: GEORGE AIR FORCE BASE
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 923920000
Latitude: 34.583983
Longitude: -117.378706

Sites Details

Status: Refer: RWQCB
Status Date: 12/07/2018
Site Code:
Site Type: Corrective Action
Site Type Detailed: Corrective Action
Special Program:
City: VICTORVILLE
County: SAN BERNARDINO
Congres Dis: 23
State : CA
Latitude: 34.583983
Longitude: -117.378706
Address: 18374 PHANTOM WEST ST
National Priorities List: NO
APN: NONE SPECIFIED
Confirmed Coc: NONE SPECIFIED
Past Uses: NONE SPECIFIED
Potential Coc: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Project Name: GEORGE AIR FORCE BASE
Regulatory Agencies Involved: SMBRP

Assembly: 34
Division Branch: Cleanup Cypress
Funding:
Lead Agency: MBR
Project Manager:
Supervisor: * Unknown
Restricted Use: NO
Senate: 23
Site Mgmt Req: NONE SPECIFIED
Acres: 0
Zip: 923920000

52	2 of3	NNE	0.80 / 4,215.80	2,880.88 / -26	GEORGE AIR FORCE BASE 18374 PHANTOM WEST ST VICTORVILLE CA 923920000	HWP

Envirostor ID: CA2570024453

Site History:

George Air Force Base (GAFB) generated hazardous waste from various operations involving aircraft equipment, operation, and maintenance. GAFB submitted a Part A on 11/19/1980 and was later issued an ISD. They submitted a Part B and obtained a permit on 6/28/1995 for their container storage, tank storage, PCB storage, and OBOD units. A Wastewater Treatment unit was also mentioned on their Part A but was not included in their final permit.

According to a Sampling Strategy dated 4/21/1993, the Part B expired in 1990 and a Corrective Action Order was issued in 1991 for operating without a valid permit. The closure process for GAFB began in 1992 for all their permitted units except the OBOD unit whose closure would be overseen by the Environmental Management Office at Nellis Air Force Base. A Closure Plan was submitted in June of 1993 and the Closure Verification was issued on 6/6/1994 for the three units. The OBOD unit was later verified closed on 1/23/2009.

Quarterly Update:

George Air Force Base (GAFB) generated hazardous waste from various operations involving aircraft equipment, operation, and maintenance. GAFB submitted a Part A on 11/19/1980 and was later issued an ISD. They submitted a Part B and obtained a permit on 6/28/1995 for their container storage, tank storage, PCB storage, and OBOD units. A Wastewater Treatment unit was also mentioned on their Part A but was not included in their final permit. According to a Sampling Strategy dated 4/21/1993, the Part B expired in 1990 and a Corrective Action Order was issued in 1991 for operating without a valid permit. The closure process for GAFB began in 1992 for all their permitted units except the OBOD unit whose closure would be overseen by the Environmental Management Office at Nellis Air Force Base. A Closure Plan was submitted in June of 1993 and the Closure Verification was issued on 6/6/1994 for the three units. The OBOD unit was later verified closed on 1/23/2009.

Facilities Details

Estor/EPA ID:	CA2570024453	***Site Code:***	
Program Type:	HAZ WASTE - RCRA	***APN:***	
Program Type1:	HAZARDOUS WASTE FACILITY	***Assembly District:***	34
Status:	CLOSED	***Census Tract:***	6071980200
Site Facility Name:	GEORGE AIR FORCE BASE	***Funding:***	
Site Type:	CLOSED - PERMIT AUTHORITY: RCRA	***Office:***	
Address Description:	18374 PHANTOM WEST ST	***Project Manager:***	
City:	VICTORVILLE	***Special Program:***	
County:	SAN BERNARDINO	***Supervisor:***	
Zip:	923920000	***Senate District:***	23
Acres:			
Public Participation Specialis:			
CalEnviroScreen Score:	NA		
National Priorities List:			
Past Use that Caused Contam:			
Permit Renewal Lead:			
Cleanup Oversight Agencies:			
Cleanup Status:			
Potential Cont of Conc:			
Potential Media Affected:			
School District:			
Summary Link:	https://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CA2570024453		

Permit Units - Completed Activities

Event Description:	New Operating Permit - APPLICATION PART B RECEIVED
Date:	7/18/1983
Unit:	
Doc Link:	
Unit Link:	https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=438
Activity Type:	Permitted Units - Completed Activities
Event Description:	New Operating Permit - APPLICATION PART B RECEIVED
Date:	7/18/1983
Unit:	
Doc Link:	
Unit Link:	https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type:	Permitted Units - Completed Activities
Event Description:	New Operating Permit - PUBLIC COMMENT (END)
Date:	6/10/1985

Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Date: 4/26/1985
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - FINAL PERMIT
Date: 6/28/1985
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - FINAL PERMIT (EXPIRES)
Date: 6/28/1990
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - FINAL PERMIT - WITHDRAWAL REQUEST RECEIVED
Date: 11/19/1983
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=438
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - FINAL PERMIT (EFFECTIVE)
Date: 6/28/1985
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=434
Activity Type: Permitted Units - Completed Activities

Event Description: New Operating Permit - FINAL PERMIT - WITHDRAWAL REQUEST ACKNOWLEDGED
Date: 11/19/1983
Unit:
Doc Link:
Unit Link: https://www.envirostor.dtsc.ca.gov/public/hwmp_showunits?cmd=showpaunits&global_id=CA2570024453&link_key=438
Activity Type: Permitted Units - Completed Activities

Units Undergoing Closure

Event Description: RECEIVE CLOSURE CERTIFICATION
Date: 12/1/1999
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: ISSUE CLOSURE VERIFICATION
Date: 1/23/2009
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: ISSUE CLOSURE VERIFICATION
Date: 11/20/1983
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: PUBLIC COMMENT (END)
Date: 11/27/1994
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: PUBLIC COMMENT (BEGIN)
Date: 10/28/1994
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: CLOSURE PLAN APPROVED
Date: 11/8/1993
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: RECEIVE CLOSURE CERTIFICATION
Date: 2/1/1994
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: RESPONSE TO 1ST NOD RECEIVED
Date: 6/1/1993
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: CLOSURE PLAN RECEIVED
Date: 1/27/1992
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: PUBLIC COMMENT (END)
Date: 9/16/1993
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: ISSUE CLOSURE VERIFICATION
Date: 6/6/1994
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: CLOSURE PLAN APPROVED
Date: 1/31/1995
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Event Description: PUBLIC COMMENT (BEGIN)
Date: 8/17/1993
Unit:
Doc Link:
Activity Type: Units Undergoing Closure - Completed Activities

Search Results Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Program Type: HAZ WASTE - RCRA
Site Code:
Status: CLOSED
Status Date:
CalEnviroScreen Score: NA
Supervisor:
Pm:
Office: CYPRESS, GEOLOGY CAL SUPPORT
Branch Chief:
Address Description: 18374 PHANTOM WEST ST
Site Facility Name: GEORGE AIR FORCE BASE
City: VICTORVILLE
County: SAN BERNARDINO
Zip: 923920000
Latitude: 34.583983
Longitude: -117.378706

Haz Waste Facility Details

Address: 18374 PHANTOM WEST ST
City: VICTORVILLE
County: SAN BERNARDINO
Facility Size:
Facility Status: CLOSED
Facility Type: Historical - Non-Operating
Latitude: 34.583983
Longitude: -117.378706
Zip: 923920000
Site Code:
State : CA
Assembly District: 34
Facility Name: GEORGE AIR FORCE BASE
Public Participation Specialis:
CalEnviroScreen Score: NA
Commercial Offsite Facility Ty:

Permit Effec Dt:
Permit Exp Date:
Permit Type: RCRA
Project Manager:
Project Mnger Lead:
Pub Info Officer:
Senate District: 23
Supervisor:
Total Actual Hours:
Total Planned Amt:
Total Planned Hrs:

52	*3 of3*	*NNE*	*0.80 / 4,215.80*	*2,880.88 / -26*	***AIR FORCE REAL PROPERTY AGENCY*** ***18374 PHANTOM STREET*** ***VICTORVILLE CA 95652***	***RCRA CORRACTS***

Handler ID: CA2570024453
Generator Status: LQG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Event/Area Details

Area Name: ENTIRE FACILITY
Event Code: CA550RC
Corrective Action Event Descri: REMEDY CONSTRUCTION-REMEDY CONSTRUCTED
Actual Date: 19961230
Schedule Date Orig: 19961230
Schedule Date New:
Best Date: 19961230
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: OU 1
Event Code: CA500
Corrective Action Event Descri: CMI WORKPLAN APPROVED
Actual Date: 19970910

Schedule Date Orig:
Schedule Date New:
Best Date: 19970910
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA300
Corrective Action Event Descri: CMS WORKPLAN APPROVED
Actual Date: 19970729
Schedule Date Orig:
Schedule Date New:
Best Date: 19970729
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA400
Corrective Action Event Descri: REMEDY DECISION
Actual Date: 19940307
Schedule Date Orig: 19940307
Schedule Date New:
Best Date: 19940307
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA725YE
Corrective Action Event Descri: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date: 19980618
Schedule Date Orig: 19980618
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: OU 1
Event Code: CA350
Corrective Action Event Descri: CMS COMPLETE
Actual Date: 19970729
Schedule Date Orig:
Schedule Date New:
Best Date: 19970729
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA750IN
Corrective Action Event Descri: RELEASE TO GW CONTROLLED DETERMINATION-MORE INFORMATION NEEDED
Actual Date: 19980618
Schedule Date Orig: 19980618
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:

Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA150
Corrective Action Event Descri: INVESTIGATION WORKPLAN APPROVED
Actual Date: 19970729
Schedule Date Orig:
Schedule Date New:
Best Date: 19970729
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: ENTIRE FACILITY
Event Code: CA200
Corrective Action Event Descri: INVESTIGATION COMPLETE
Actual Date: 19970729
Schedule Date Orig:
Schedule Date New:
Best Date: 19970729
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA029SF
Corrective Action Event Descri: LEAD AGENCY DETERMINATION
Actual Date: 19870601
Schedule Date Orig:
Schedule Date New:
Best Date: 19870601
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA049SI
Corrective Action Event Descri: PA OR CERCLA INSPECTION
Actual Date: 19870601
Schedule Date Orig:
Schedule Date New:
Best Date: 19870601
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA210
Corrective Action Event Descri: REFERRED TO A NON-RCRA AUTHORITY
Actual Date: 19980618
Schedule Date Orig:
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA550
Corrective Action Event Descri: REMEDY CONSTRUCTION
Actual Date: 19961230
Schedule Date Orig:
Schedule Date New:
Best Date: 19961230
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA225NR
Corrective Action Event Descri: STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION
Actual Date: 19980618
Schedule Date Orig:
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA210SF
Corrective Action Event Descri: REFERRED TO A NON-RCRA AUTHORITY-REFERRED TO CERCLA
Actual Date: 19940815
Schedule Date Orig:
Schedule Date New:
Best Date: 19940815
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA725YE
Corrective Action Event Descri: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Actual Date: 19980618
Schedule Date Orig:
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA400
Corrective Action Event Descri: REMEDY DECISION
Actual Date: 19940307
Schedule Date Orig:
Schedule Date New:
Best Date: 19940307
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA450
Corrective Action Event Descri: CORRECTIVE MEASURES DESIGN APPROVED

Actual Date: 19960216
Schedule Date Orig:
Schedule Date New:
Best Date: 19960216
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA049PA
Corrective Action Event Descri: PA OR CERCLA INSPECTION
Actual Date: 19870601
Schedule Date Orig:
Schedule Date New:
Best Date: 19870601
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA050
Corrective Action Event Descri: RFA COMPLETED
Actual Date: 19870601
Schedule Date Orig:
Schedule Date New:
Best Date: 19870601
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA750IN
Corrective Action Event Descri: RELEASE TO GW CONTROLLED DETERMINATION-MORE INFORMATION NEEDED
Actual Date: 19980618
Schedule Date Orig:
Schedule Date New:
Best Date: 19980618
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA100
Corrective Action Event Descri: INVESTIGATION IMPOSITION
Actual Date: 19910701
Schedule Date Orig:
Schedule Date New:
Best Date: 19910701
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA075ME
Corrective Action Event Descri: CA PRIORITIZATION-MEDIUM CA PRIORITY
Actual Date: 19940815
Schedule Date Orig:
Schedule Date New:
Best Date: 19940815

Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: E

Area Name:
Event Code: CA650
Corrective Action Event Descri: STABILIZATION CONSTRUCTION COMPLETED
Actual Date: 19950101
Schedule Date Orig:
Schedule Date New:
Best Date: 19950101
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name:
Event Code: CA250
Corrective Action Event Descri: CMS IMPOSITION
Actual Date: 19910701
Schedule Date Orig:
Schedule Date New:
Best Date: 19910701
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Area Name: OU 1
Event Code: CA600SR
Corrective Action Event Descri: STABILIZATION/INTERIM MEASURES DECISION-PRIMARY MEAS IS SOURCE REMOVL &/OR TRT
Actual Date: 19910701
Schedule Date Orig:
Schedule Date New:
Best Date: 19910701
Groundwater Release Ind:
Soil Release Ind:
Air Release Ind:
Surface Water Release Ind:
Event Agency: S

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Nov 2025.

Violation Details

Viol Type: 262.A
Citation: F - 262.30-34.C
Determined Date: 19920226
Scheduled Compliance Date: 19920327
Eval Activity Location: CA
Viol Determined By Agency: State
Viol Short Desc: Generators - General
Actual Rtc Date: 19930628
Found Violation: Yes
Rtc Qualifier: Observed

Enforcement Details

Enf Type: 210
Enf Type Desc: INITIAL 3008(A) COMPLIANCE
Enf Action Date: 19920226
Disposition Status Desc:

Disposition Status Date:
Enf Agency: State
Proposed Amount: 1100
Final Amount:
Paid Amount:

Violation Details

Viol Type: 262.A
Citation: F - 262.50-60
Determined Date: 19920226
Scheduled Compliance Date: 19920327
Eval Activity Location: CA
Viol Determined By Agency: State
Viol Short Desc: Generators - General
Actual Rtc Date: 19930628
Found Violation: Yes
Rtc Qualifier: Observed

Enforcement Details

Enf Type: 210
Enf Type Desc: INITIAL 3008(A) COMPLIANCE
Enf Action Date: 19920226
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount: 1100
Final Amount:
Paid Amount:

Violation Details

Viol Type: 264.A
Citation: FR - 270
Determined Date: 19900626
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - General
Actual Rtc Date: 19910423
Found Violation: Yes
Rtc Qualifier: Unverifiable

Violation Details

Viol Type: 268.A
Citation: FR - 268 ALL
Determined Date: 19900626
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: LDR - General
Actual Rtc Date: 19910423
Found Violation: Yes
Rtc Qualifier: Unverifiable

Violation Details

Viol Type: 268.A
Citation: FR - 268.7
Determined Date: 19900626
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: LDR - General
Actual Rtc Date: 19910423
Found Violation: Yes
Rtc Qualifier: Unverifiable

Violation Details

Viol Type: 264.A
Citation: FR - 264.70-77.E
Actual Rtc Date: 19900216
Found Violation: Yes

Determined Date: 19890913 ***Rtc Qualifier:*** Observed
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - General

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19891130
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 264.A ***Actual Rtc Date:*** 19900216
Citation: FR - 270 ***Found Violation:*** Yes
Determined Date: 19890913 ***Rtc Qualifier:*** Observed
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - General

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19891130
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 264.G ***Actual Rtc Date:*** 19900216
Citation: FR - 264.110-120.G ***Found Violation:*** Yes
Determined Date: 19890913 ***Rtc Qualifier:*** Observed
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - Closure/Post-Closure

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19891130
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 268.A
Citation: FR - 268 ALL
Determined Date: 19890913
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: LDR - General
Actual Rtc Date: 19900216
Found Violation: Yes
Rtc Qualifier: Observed

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19891130
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 268.A
Citation: FR - 268.7
Determined Date: 19890913
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: LDR - General
Actual Rtc Date: 19900216
Found Violation: Yes
Rtc Qualifier: Observed

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19891130
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 264.A
Citation: FR - 270
Determined Date: 19880224
Scheduled Compliance Date:
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - General
Actual Rtc Date: 19890913
Found Violation: Yes
Rtc Qualifier: Unverifiable

Violation Details

Viol Type: 264.A
Citation: FR - 270
Determined Date: 19870413
Scheduled Compliance Date: 19880128
Eval Activity Location: CA
Viol Determined By Agency: EPA
Viol Short Desc: TSD - General
Actual Rtc Date: 19880224
Found Violation: Yes
Rtc Qualifier: Unverifiable

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 19871221
Disposition Status Desc:
Disposition Status Date:
Enf Agency: EPA
Proposed Amount:
Final Amount:
Paid Amount:

Enf Type: 810
Enf Type Desc: STATE TO EPA ADMINISTRATIVE REFERRAL
Enf Action Date: 19871209
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Evaluation Details

Eval Start Date: 19940322
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Eval Start Date: 19930628
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Eval Start Date: 19920114
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Generators - General
Actual Rtc Date: 19930628
Eval Agency: State

Eval Start Date: 19910423
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Eval Start Date: 19900626
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: TSD - General
Actual Rtc Date: 19910423
Eval Agency: EPA

Eval Start Date: 19900626
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: LDR - General
Actual Rtc Date: 19910423
Eval Agency: EPA

Eval Start Date: 19890913
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: TSD - Closure/Post-Closure
Actual Rtc Date: 19900216
Eval Agency: EPA

Eval Start Date:	19890913
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	TSD - General
Actual Rtc Date:	19900216
Eval Agency:	EPA

Eval Start Date:	19890913
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	LDR - General
Actual Rtc Date:	19900216
Eval Agency:	EPA

Eval Start Date:	19880224
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	TSD - General
Actual Rtc Date:	19890913
Eval Agency:	EPA

Eval Start Date:	19870413
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	TSD - General
Actual Rtc Date:	19880224
Eval Agency:	EPA

Additional Handler Summary Details

Source Type:	R	**NAIC 1:**	53119
Seq No:	3	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20080228	**NAIC 4:**	
Active Site:	H-A--	**State:**	CA
Land Type:	F	**Location Latitude:**	34.582302
In Handler Univ:	Y	**Location Longitude:**	-117.377879
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	LQG	**Loc GIS Origin:**	AG
Report Cycle:	2007	**State District Owner:**	
Accessibility:		**State District:**	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	CA
State Waste Generator:	1
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	LOP
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	---ST-
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	Y
Subjca Tsd Discretion:	Y
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	+
Ca750 Indicator:	-
Operating Tsdf:	------
Full Enforcement:	------

Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20081015
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	AIR FORCE REAL PROPERTY AGENCY
Location Street No:	
Location Street1:	18374 PHANTOM STREET
Location Street2:	
Location City:	VICTORVILLE
Location State:	CA
Location Zip:	95652
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	MICHAEL H SWART
Contact Street No:	
Contact Street1:	
Contact Street2:	
Contact City:	
Contact State:	
Contact Zip:	
Contact Country:	US
Contact Phone & Ext:	916-643-0830 x230
Contact Fax:	
Contact Email Address:	MIKE.SWART@AFRPA.PENTAGON.AF.MIL
Contact Title:	
Owner Name:	AIR FORCE REAL PROPERTY AGENCY
Owner Type:	F
Owner Seq:	1
Operator Name:	AIR FORCE REAL PROPERTY AGENCY
Operator Type:	F
Operator Seq:	2
Public Notes:	

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		

Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19800818
Handler Name:	USAF GEORGE AFB
Fed Waste Generator:	1
Generator Code Description:	Large Quantity Generator
Source Type:	Notification
TSD Activity:	N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19900517
Handler Name: GEORGE AIR FORCE BASE
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report
TSD Activity: Y

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 19920224
Handler Name: GEORGE AIR FORCE BASE, CA
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 19960901
Handler Name: USAF GEORGE AFB
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 20080228
Handler Name: AIR FORCE REAL PROPERTY AGENCY
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report
TSD Activity: N

Waste Code Details

Waste Code: D022
Waste Code Desc: CHLOROFORM

Waste Code: D029
Waste Code Desc: 1,1-DICHLOROETHYLENE

Waste Code: D040
Waste Code Desc: TRICHLOROETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Federal
Name: MULTIPLE OPS-ALL USAF COMMANDS
Dt Became Current:
Dt Ended Current:
Phone: 714-269-2971
Source Type: Notification
Street No:
Street1: 35CSG/DEEV
Street2:
City: GEORGE AFB
State: CA
Country:
Zip: 92392

Owner/Operator Ind: Current Operator
Street No:

Type:	Federal	***Street1:***	35CSG/DEEV
Name:	MULTIPLE OPS-ALL USAF COMMANDS	***Street2:***	
Dt Became Current:		***City:***	CITY NOT REPORTED
Dt Ended Current:		***State:***	CA
Phone:	714-269-2971	***Country:***	
Source Type:	Implementer	***Zip:***	99999
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Federal	***Street1:***	3411 OLSON STREET
Name:	AIR FORCE REAL PROPERTY AGENCY	***Street2:***	
Dt Became Current:	19921201	***City:***	MCCLELLAN
Dt Ended Current:		***State:***	CA
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip:***	95652
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Federal	***Street1:***	
Name:	AIR FORCE REAL PROPERTY AGENCY	***Street2:***	
Dt Became Current:	19921201	***City:***	
Dt Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Annual/Biennial Report	***Zip:***	

Historical Handler Details

Receive Dt:	19960901
Generator Code Description:	Small Quantity Generator
Handler Name:	USAF GEORGE AFB
Receive Dt:	19920224
Generator Code Description:	Large Quantity Generator
Handler Name:	GEORGE AIR FORCE BASE, CA
Receive Dt:	19900517
Generator Code Description:	Large Quantity Generator
Handler Name:	GEORGE AIR FORCE BASE
Receive Dt:	19800818
Generator Code Description:	Large Quantity Generator
Handler Name:	USAF GEORGE AFB

Unplottable Summary

Total: 141 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
AST	Kindermorgan	Air Express Way	Victorville CA	92392	820216354
AST SWRCB	CALNEV GEORGE TERMINAL	1 5/8 MILE E. OF ADELANTO RD.	ADELANTO CA		886753273
BULK TERMINAL	CALNEV DELIVERY AT US AIR FORCE (SOUTHERN CALIFORNIA LOGISTICS AIRPORT)	AIR EXPRESSWAY & PHANTOM W	VICTORVILLE CA		920992446
CALSITES	GEORGE AIR FORCE BASE	5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA	VICTORVILLE CA	92392	891190641
CDL		ON AUBURN LANE, CROSS ADELANTO ROAD	ADELANTO CA	92301	820121747
CDL		.5 MILE SO OF SYCAMORE & E OF COBALT	VICTORVILLE CA	92392	820127043
CHMIRS	NRC	Southern California Logistics Airport, north end of George Air Force Base ***Control No*	*Notified Date:*** 07-2980 |	Victorville CA		821825788
CHMIRS	City of Victorville	between Air Base Dr and Turner Rd. ***Control No*	*Notified Date:*** 12/6/199704:18:20 PM	Victorville CA	92392	821799664
CHMIRS	Victorville City FD	SoCAl Logistics Airport, Airbase Road & Bantom West ***Control No*	*Notified Date:*** 6/18/200303:17:22 PM	Victorville CA		821777204
CHMIRS	Montgomery Watson	Former George Air Force Base at The Current Skeet Range	Victorville CA	94596	821757839

Control No* | *Notified Date: 4/10/200109:56:45 AM

CHMIRS	Southern CA Edison	7401 Adelanto Road cross street Violet ***Control No*	*Notified Date:*** 08-2902 |	Adelanto CA	821837886
CHMIRS	Kinder Morgan Southern Region	Southern California Logistics Airport, 13334 Air Express Way ***Control No*	*Notified Date:*** 08-6850 |	Victorville CA	821879425
CHMIRS	Kinder Morgan	At the pipeline's entry point to George AFB, Southern California Logistics Airport ***Control No*	*Notified Date:*** 07-3142 |	George Air Force Base CA	821890125
CHMIRS	Kinder Morgan	Edwards AFB, 13334 Air Express Way ***Control No*	*Notified Date:*** 06-2599 |	Victorville CA	821893631
CHMIRS	ComAv Technical Services	Southern California Logistics Airport - Hangar 761 ***Control No*	*Notified Date:*** 23-2479 | 4/7/2023 10:34:00 AM	Victorville CA 92394	919654270
CHMIRS	NRC	1007 Yucca Road - IN A DESERT AREA; IN THE BACK OF THE PROPERTY; BEHIND THE TRAILERS ***Control No*	*Notified Date:*** 23-2532 | 4/10/2023 12:11:00 PM	Adelanto CA	919655393
CHMIRS	Comav	Southern California Logistics Airport, Lat 34 35 north x 33 17 west ***Control No*	*Notified Date:*** 23-5186 | 8/14/2023 11:05:00 AM	Victorville CA 92394	923063098
CHMIRS	Cherokee Nation	(George Air Force Base) Phantom West and Innovation Way ***Control No*	*Notified Date:*** 24-0975 | 2/15/2024 10:22:00 AM	Victorville CA 92394	923858021
CHMIRS	Calnev Pipeline Co	George Terminal, on Airbase Rd., 1 5/8 miles east of Adelanto Rd. ***Control No*	*Notified Date:*** 7/27/199811:16:40 AM	Victorville CA 92412	821865672
CHMIRS	calnev pipeline co	1 and 5/8 miles east of adelanto rd on airbase rd at the george airforce base area ***Control No*	*Notified Date:*** 10/4/1994	adelanto CA	860460226
CHMIRS	calnev pipeline co	george airforce base terminal 1and 5/8 mile east of adelanto rd on air		adelanto CA	860460559

		base rd approx 2 miles from ***Control No | Notified Date:*** 8/29/1994			
DELISTED CLEANUP	GEORGE AIR FORCE BASE - OWS 645-S1	BUILDING 645 PHANTOM	VICTORVILLE CA	92392	820154979
EMISSIONS	CALNEV PIPE LINE COMPANY	AIR BASE RD	VICTORVILLE CA	92392	861190725
EMISSIONS	CALNEV PIPE LINE COMPANY	AIR BASE RD	ADELANTO CA	92301	861248435
ERNS		GEORGE AIR FORCE BASE ***NRC Report No:*** 836260	VICTORYVILLE CA		806991070
ERNS		GEORGE AFB TANK NO. 548,POL BULK FUEL STORAGE ***NRC Report No:*** 19432	GEORGE AFB CA	923945000	807190039
ERNS		1007 YUCCA RD ***NRC Report No:*** 1364423	ADELANTO CA		920895851
ERNS		GEORGE AFB AIR BASE RD ***NRC Report No:*** 20210	GEORGE AFB CA		806793784
FINDS/FRS	CALNEV PIPE LINE, LLC - GEORGE AFB	AIR BASE ROAD ***Registry ID:*** 110070736989	GEORGE AFB CA	92392	885023976
FINDS/FRS	WESTWINDS GOLF COURSE	SO CALIF LOGISTICS AIRPORT ***Registry ID:*** 110064910020	VICTORVILLE CA	92392	840211166
FINDS/FRS	MOUNTAIN VIEW ACRES STORM DRAIN PROJECT	COBALT ***Registry ID:*** 110065777500	VICTORVILLE CA	92392	840153974
FINDS/FRS	COBALT MIDDLE SCHOOL	1380 COBALT RD ***Registry ID:*** 110066225070	VICTORVILLE CA	92392	840112278
FINDS/FRS	SO. CAL LOGISTICS AIRPORT	FORMER GEORGE AIR FORCE BASE ***Registry ID:*** 110065928811	VICTORVILLE CA	92392	840108391
HAZ GEN	SOUTHER CALIFORNIA LOGISTICS AIRPORT	1800 PHANTOM WEST DRIVE	VICTORVILLE CA	923940000	900450509

HAZ GEN	NORTHROP GRUMMAN CORP	GEORGE AIR FORCE BASE	VICTORVILLE CA	923940000	900536463
HAZ GEN	CALNEV PIPE LINE LLC - GEORGE AFB	AIR BASE RD	GEORGE AFB CA	923920000	900578466
HAZ GEN	COMMERICAL WOOD PRODUCTS	1051 YUCCA	ADELANTO CA	923010000	900243007
HAZNET	DH WRIGHT	2662 PHANTOM WEST ST	ADELANTO CA	92301	826399475
HAZNET	US AIRFORCE	B-723 PHANTOM BLVD	VICTORVILLE CA	923940000	826584370
HAZNET	1X ADELANTO UNIFIED SCHOOL DISTRICT	GEORGE AIR FORCE ELEMENTARY	GERORGE AIR FORCE BA CA	923940000	826865464
HAZNET	CIRCLE K STORES #8644	NEC HWY 395 & AIR BASE	ADELANTO CA	000000000	826119416
HHSS	GEORGE AIR FORCE BASE	831ST CSG/DEEV AIR BASE ROAD	GEORGE AFB CA	92394	822970693
HHSS	GEORGE AIR FORCE BASE	AIR BASE RAD, GEORGE AIR FORCE ADELANTO ROAD	ADELANTO CA	92392	822929055
HIST CHMIRS		GEORGE AFB	VICTORVILLE CA		826012315
HIST MANIFEST		AIR BASE RD	GEORGE AFB CA	923920000	827497349
HIST TANK	GEORGE AIR FORCE BASE	AIR BASE RAD, GEORGE AIR FORCE	ADELANTO CA		865036518
HMIRS		ADELANTO RD	ADELANTO CA		818542317

HMIRS	ADELANTO RD	ADELANTO CA	818538252
HMIRS	ADELANTO ROAD	ADELANTO CA	818536068
HMIRS	ADELANTO RD	ADELANTO CA	818515952
HMIRS	ADELANTO RD	ADELANTO CA	818514214
HMIRS	ADELANTO RD	ADELANTO CA	818514119
HMIRS	ADELANTO ROAD	ADELANTO CA	818490493
HMIRS	ADELANTO RD	ADELANTO CA	818478010
HMIRS	ADELANTO RD	ADELANTO CA	818473174
HMIRS	ADELANTO RD	ADELANTO CA	818450283
HMIRS	ADELANTO ROAD	ADELANTO CA	818449538
HMIRS	ADELANTO ROAD	ADELANTO CA	818433979
HMIRS	ADELANTO ROAD	ADELANTO CA	818426769
HMIRS	ADELANTO RD	ADELANTO CA	818423931
HMIRS	ADELANTO RD	ADELANTO CA	818422100
HMIRS	ADELANTO RD	ADELANTO CA	818420298

HMIRS	ADELANTO RD	ADELANTO CA	818417075
HMIRS	ADELANTO ROAD	ADELANTO CA	818410379
HMIRS	ADELANTO RD	ADELANTO CA	818409617
HMIRS	ADELANTO RD	ADELANTO CA	818406657
HMIRS	ADELANTO RD	ADELANTO CA	818400763
HMIRS	ADELANTO RD	ADELANTO CA	818396418
HMIRS	ADELANTO RD	ADELANTO CA	818395419
HMIRS	ADELANTO ROAD	ADELANTO CA	818394101
HMIRS	ADELANTO RD	ADELANTO CA	818377888
HMIRS	ADELANTO RD	ADELANTO CA	818377529
HMIRS	ADELANTO RD	ADELANTO CA	818369909
HMIRS	ADELANTO RD	ADELANTO CA	818358275
HMIRS	ADELANTO ROAD	ADELANTO CA	818341229
HMIRS	ADELANTO ROAD	ADELANTO CA	818323396

HMIRS	ADELANTO RD	ADELANTO CA	818312529
HMIRS	ADELANTO RD	ADELANTO CA	818309170
HMIRS	ADELANTO RD	ADELANTO CA	818299949
HMIRS	ADELANTO ROAD	ADELANTO CA	818296802
HMIRS	ADELANTO ROAD	ADELANTO CA	818287518
HMIRS	ADELANTO RD	ADELANTO CA	818275941
HMIRS	ADELANTO RD	ADELANTO CA	818268878
HMIRS	ADELANTO RD	ADELANTO CA	818264576
HMIRS	ADELANTO ROAD	ADELANTO CA	818259181
HMIRS	ADELANTO ROAD	ADELANTO CA	818256198
HMIRS	ADELANTO RD	ADELANTO CA	818245439
HMIRS	ADELANTO RD	ADELANTO CA	818239751
HMIRS	ADELANTO RD	ADELANTO CA	818238604
HMIRS	ADELANTO RD.	ADELANTO CA	818230692

HMIRS	ADELANTO RD	ADELANTO CA	818223394
HMIRS	ADELANTO RD.	ADELANTO CA	818217064
HMIRS	ADELANTO RD	ADELANTO CA	818194147
HMIRS	ADELANTO ROAD	ADELANTO CA	818192991
HMIRS	ADELANTO RD	ADELANTO CA	818186388
HMIRS	ADELANTO RD	ADELANTO CA	818176859
HMIRS	ADELANTO ROAD	ADELANTO CA	818156715
HMIRS	ADELANTO RD	ADELANTO CA	818156572
HMIRS	ADELANTO RD	ADELANTO CA	818140788
HMIRS	ADELANTO RD	ADELANTO CA	818137342
HMIRS	ADELANTO ROAD	ADELANTO CA	818136002
HMIRS	ADELANTO RD	ADELANTO CA	818109181
HMIRS	ADELANTO RD	ADELANTO CA	818099508
HMIRS	ADELANTO RD.	ADELANTO CA	818130497
HMIRS	ADELANTO RD	ADELANTO CA	818123068

HMIRS	ADELANTO ROAD	ADELANTO CA	818122810
HMIRS	ADELANTO RD	ADELANTO CA	818120555
HMIRS	ADELANTO ROAD	ADELANTO CA	818119531
HMIRS	ADELANTO RD	ADELANTO CA	818117990
HMIRS	ADELANTO ROAD	ADELANTO CA	818110712
HMIRS	143601 ADELANTO RD	ADELANTO CA	880651041
HMIRS	909 ADELANTO RD	ADELANTO CA	880623095
HMIRS	ADELANTO RD	ADELANTO CA	818625092
HMIRS	ADELANTO ROAD	ADELANTO CA	818617676
HMIRS	ADELANTO RD	ADELANTO CA	818616952
HMIRS	ADELANTO RD	ADELANTO CA	818611155
HMIRS	ADELANTO RD	ADELANTO CA	818588930
HMIRS	ADELANTO RD	ADELANTO CA	818584975
HMIRS	ADELANTO ROAD	ADELANTO CA	818575932

HMIRS		ADELANTO ROAD	ADELANTO CA		818574898
HMIRS		ADELANTO ROAD	ADELANTO CA		818569048
HMIRS		ADELANTO ROAD	ADELANTO CA		818564527
HMIRS		ADELANTO RD	ADELANTO CA		818549166
HMIRS		ADELANTO RD	ADELANTO CA		818544531
MINES	CALIFORNIA SILICA PRODUCTS	Highway 395 & Rancho Road, go East on Rancho Road to Adelanto Road go South, to Rancho Road (again, road jogs) go East to 12808 Rancho Road. ***Mine ID:*** 0405847	Victorville CA		848318649
PRP	U.S. AIR FORCE	831 ST. CSG/CC GEORGE AFB ***Site EPA ID:*** CA2570024453	GEORGE AFB CA	92394	860496824
PRP	U.S. AIR FORCE	831 ST. CSG/CC GEORGE AFB ***Site EPA ID:*** CAD980736151	GEORGE AFB CA	92394	860560622
RCRA NON GEN	NORTHROP GRUMMAN GAFB B559	GEORGE AIR FORCE BASE BUILDING 559 ***Handler ID | Recycler Activity?:*** CAR000000604 | NO	VICTORVILLE CA	92394	810338543
RCRA NON GEN	CALNEV PIPE LINE, LLC - GEORGE AFB	AIR BASE ROAD ***Handler ID | Recycler Activity?:*** CAT080013881 | YES	GEORGE AFB CA	92392	867222684
SANBERN CUPA	Cobalt Middle School	1380 Cobalt RD	Victorville CA	92392	867340044
UST CLOSURE	OWS 768-S1 Metal Fabrication Shop	Phantom West Street, Victorville, San Bernardino County ***Claim Case No:*** Case No. T10000001728	CA		917563651
UST CLOSURE	OWS 55775 Storm Drain System/Waste Treatment Building	Phantom West Street, Victorville, San Bernardino County	CA		917563698

Claim Case No: Case No. T10000001737

UST CLOSURE	OWS 723-S1 Old Fire Station	Phantom West Street, Victorville, San Bernardino County ***Claim Case No:*** Case No. T10000001724	CA		917563675
UST SWEEPS	GEORGE AIR FORCE BASE	AIR BASE RADL GEORGE ***C C | Status:*** A36-000-9667 | ACTIVE ***Tank ID:*** 000001	ADELANTO CA		888145863
UST SWEEPS	GEORGE AIR FORCE BASE	831ST CSG/DEEV ***C C | Status:*** A36-000-24808 | ACTIVE ***Tank ID:*** 000012, 000049, 000052, 000062, 000081, 000090, 000095, 000100, 000103, 000107, 000053, 000060, 000072, 000073, 000077, 000091, 000110, 000008, 000009, 000011, 000020, 000022, 000033, 000035, 000039, 000043, 000047, 000048, 000078, 000006, 000018, 000032, 000038, 000040, 000064, 000067, 000068, 000071, 000003, 000007, 000010, 000013, 000014, 000017, 000021, 000025, 000031, 000041, 000050, 000054, 000056, 000057, 000058, 000059, 000070, 000075, 000080, 000082, 000083, 000086, 000088, 000097, 000102, 000105, 000106, 000111, 000005, 000026, 000028, 000029, 000045, 000065, 000079, 000084, 000089, 000096, 000046, 000051, 000055, 000061, 000074, 000085, 000092, 000098, 000099, 000104, 000109, 000001, 000004, 000015, 000016, 000027, 000030, 000034, 000036, 000037, 000042, 000044, 000069, 000076, 000002, 000094, 000108, 000019, 000023, 000024, 000063, 000066, 000087, 000093, 000101	GEORGE AFB CA		888197647
UST SWEEPS	GEORGE AIR FORCE BASE OL-C/AFBDA SITE OT-51/SS-59	ENGINE TEST CELLS ***C C | Status:*** I36-000-9640 | INACTIVE ***Tank ID:*** 000001, 000002	GEORGE AFB CA		888140415
WASTE DISCHG	WESTWINDS GOLF COURSE	SO CALIF LOGISTICS AIRPORT ***Global ID:*** WDR100036879	VICTORVILLE CA		866880733
WMUD	GEORGE AFB (L-7) DISPOSAL SITE		GEORGE AFB CA	92392	895465596
WMUD	GEORGE AFB (L-6,8,9) DISPOSAL		GEORGE AFB CA	92392	895465135
WMUD	GEORGE AFB (L-10) DISPOSAL SIT		GEORGE AFB CA	92392	895465955
WMUD	GEORGE AFB DISP. AREA		GEORGE AFB CA	92392	895466429

Unplottable Report

Site: ***Kindermorgan***
Air Express Way Victorville CA 92392

AST

Total Capacity(Gal):	500,000	***Owner Name:***	
CUPA:	Victorville	***County:***	San Bernardino

Site: ***CALNEV GEORGE TERMINAL***
1 5/8 MILE E. OF ADELANTO RD. ADELANTO CA

AST SWRCB

Total Gals:	2940000
Owner Name:	CALNEV PIPE LINE CO.
Data Source:	SWRCB Aboveground Storage Tanks Listing 2006;SWRCB Aboveground Storage Tanks Listing 2003;SWRCB Aboveground Storage Tanks Listing 2005;SWRCB Aboveground Storage Tanks Listing 2007

Site: ***CALNEV DELIVERY AT US AIR FORCE (SOUTHERN CALIFORNIA LOGISTICS AIRPORT)***
AIR EXPRESSWAY & PHANTOM W VICTORVILLE CA

BULK TERMINAL

PADD:		***Crude Oil:***	NO
FID:		***Jetfuel:***	YES
Term ID:	ANLTK06117	***Gasoline:***	NO
Site:		***Distillate:***	YES
Facility Type:	AFB TERMINAL	***Avgas:***	NOT AVAILABLE
Station Type:		***Period:***	
Status:	IN SERVICE	***Truck In:***	NO
Handling:		***Truck Out:***	NO
Telephone:	NOT AVAILABLE	***Pipe In:***	YES
Population:	-999	***Pipe Out:***	YES
Source Date:	7/27/2015 12:00:00 AM	***Marine In:***	NO
Val Method:	IMAGERY/OTHER	***Marine Out:***	NO
Val Date:	9/20/2018 12:00:00 AM	***Rail In:***	NO
Exstars I:	NONE	***Rail Out:***	NO
Posrel:	WITHIN 40 FEET	***County Fips:***	06071
Capacity:	1128560	***County:***	SAN BERNARDINO
Asphalt:	NO	***Zip:***	92394
Chemicals:	YES	***Zip4:***	NOT AVAILABLE
Propane:	NO	***Country:***	USA
Butane:	NO	***Latitude:***	34.577142611
Refined:	YES	***Longitude:***	-117.373360668
Ethanol:	NOT AVAILABLE	***X:***	-117.373360668
Biodiesel:	NOT AVAILABLE	***Y:***	34.5771426110001

Owner:	NOT AVAILABLE
Operator:	NOT AVAILABLE
Address:	AIR EXPRESSWAY & PHANTOM W
Commodity:	REFINED, CHEMICALS
NAICS Code:	424710
NAICS Desc:	PETROLEUM BULK STATIONS AND TERMINALS
Source:	EIA
Website:	www.kindermorgan.com/
Data Source:	Homeland Infrastructure Foundation-Level Data (HIFLD) Geoplatform Petroleum Terminals (as of Jul 2020) (GIS)

Site: ***GEORGE AIR FORCE BASE***
5,347 ACRES, 4 MLS NW OF VICTORVILLE, CA VICTORVILLE CA 92392

CALSITES

ID No:	36970005	***Assembly:***	34
Status Date:	07/01/1998	***Senate:***	17
NPL:	L	***Region:***	3

Tier:		***Region Name:***	GLENDALE
Fund:		***County Co:***	36
Access :	C	***Facility County:***	SAN BERNARDINO
Access Code:	CONTROLLED	***Lat Deg:***	0
Cortese:		***Lat Min:***	0
Hrscore:		***Lat Sec:***	0
Hrsdate:		***Lat Dir:***	
Groundwater Contam:	C	***Long Deg:***	0
GW Code:	CONTROLLED	***Long Min:***	0
No Sources:	54	***Long Sec:***	0
RWQCB Name:	LAHONTAN	***Long Dir:***	
Branch Name:	OMF-SOUTHERN CALIF	***Llmethod:***	
Staff:		***Lldesc:***	
Senior:			

Status Name: PROPERTY/SITE REFERRED TO RWQCB
Type Name: CLOSED MILITARY BASE
Lead Name: REGIONAL WATER QUALITY CONTROL BOARD
SIC Name: NATIONAL SECURITY/INTERNATIONAL AFFAIRS
Filename:
Comments:

RA L-3: Landfill L-3 is located in the SE disposal area. It was fenced and posted with barbed wire and warning signs on approximately 75 foot centers. This site had vacuum tubes and radium instrument dials disposed of from 1965 to 1970. RA - LFDS -- This Removal Action was for the Liquid Fuel Distribution System (LFDS) which consisted of approximately 29,514 feet of pipeline, ten underground storage tanks (UST) and seven concrete fuel pits (pits 1, 2, 3, 4, 5, 6, and 7). In addition, the following USTs were removed: three from the BX Service Station; three from Building 550 Vehicle Maintenance Area; and three from the Age Service Area. The pipeline and USTs were steam cleaned, cut into pieces, and sent off-site for recycling. In addition, 1,000 cubic yards of soils were treated. Approximate cost = $2.2 million; funding = BRAC. RA STORM: Work consisted of removal and replacement of perf- orat ed sections of the east storm drain; re-routing of the normal flo w bypass line with cleaning and plugging of the old section; clea ning of the upper west storm drain; and cleaning and plugging of the high flow bypass section be- tween manhole 199 and the outfal l ditch. The draft RI Re- port submitted 2/4/92 indicated that t he RA was complete. RA OU#2: Pump & Treat of free floating product from upper aquifer commenced. It is anticipated that 2-phase pumping will commence in mid August. Free floating produce is being recycled at present. ROD - OU#1 -- This Record of Decision (ROD) set forth the remedia l action to be conducted to remediate groundwater contaminated by trichloroethene (TCE) beneath the Northeast Disposal Area (NEDA) and adjacent off-base areas. OU#1 includes the following sites: SD-25 (5-20), the Industrial Storm Drain, and WP-26 (5-21), the STP Percolation Ponds. No further action is planned for these sit es in OU#1 as remedial activities have been completed and these s ites were within acceptable risk levels based on the risk assessm ent performed as part of the remedial investigation. Approximate cost = $7.9 million; funding = BRAC. RIFS - LFDS -- DTSC approved a Removal Action Workplan on March 11, 1994 for the Removal Action at the Liquid Fuel Distribution S ystem (LFDS). Approximate cost = N/A; funding = BRAC. DTSC rejected the Engineering Evaluation/Cost Analysis (EE/ CA) for Site RW-09, SW Disposal Area (SEDA) which contains low level Rad. waste, submitted by AF 3/13/93. AF did not evaluate threats that may result from imp. of the RA that could affect human health and the environment. The EE/CA did not address mitigative measures to be taken to deal with any threats. GAFB submitted in March 1995, a Final report for Removal action/ site characterization of low-level radioactive waste disposal site RW-09. The report documented site characterization for radionuclide, background radiation level, excavation activities at this 2.4-acres site, radioactivity scanning and confirmation sampling. The excavation soils debris was fed into a feed hopper, then through screens for mechanical sizing, then conveyed beneath a plastic scintillator and detector. One 28-gram cesium source was recovered from the largets excavation. Only one of the tubes had radioactivity levels above than background; the other tubes found contained low level radioactivity. Volume treated, stabilized, or disposed: Approximately 4,000 cubic yards of soil/ debris were excavated within the RW-09 site. All materials excavated were fed into a feed hopper, then through screen for mechanical sizing, then conveyed beneath a plastic scintillator and detector for sampling. RAP - OU3: Sixty sites were investigated in the Remedial Investigation, these same sites were either agreed to for no further action or were cleaned up as removal actions. See Report of Completions for the landfills recently submitted. All of the work performed is summarized in this RAP/ROD (NPL site). In addition, there are some Soil Vapor Extraction systems. Bioventing systems and Institutional Controls which will need to be observed, monitored and wrapped up as they come to a close. The vapor phases are currently off for 90 days as they are almost at the cleanup levels agreed to. Dispute for OU#1 resolved. ARAR for the final discharge level will be State of CA Res. 68-16. Effluent level from sampling port will be 2.5ppb TCE on a median basis with a max. discharge level of 5ppb TCE. The nonenforceable dis- charge goal at the perc. ponds will be 0.5ppb TCE. Draft Final RI/FS/PP for OU#1 was approved conditioned upon Air F orce submitting a proposed schedule for additional field work. T here are data gaps; without the knowledge of the gross dimensions of the plume, the preferred alternative presented will not ensur e complete capture of the plume. RIFS TCE - During the Operable Unit Two (OU-2) JP-4 invetigation, TCE/PCE plumes were discovered. GAFB submitted on October 1, 199 3 Remedial Investigation Feasibility Study (RIFS) Workplan to the agencies and implemented the investigation activities. A draft f inal RI/FS report was submitted to the agencies in June 1994, DTS C, the RWQCB, and USEPA met at GAFB and agreed in the meeting tha t GAFB needs to conduct additional investigation to determine if there are any source of contamination in the vicinity of MW-49. I F the additional field work does not reveal source of contaminati on, natural attenuation/monitoring will be accepted for the TCE/P CE plumes. GAFB completed the additional investigation in March 1 994 and submitted in July 1995, a final RI/FS report for OU-3 TCE /PCE study area. The report summarizes the results of remedial in vestigation activities performed at the area and presents the dev elopment, evaluation, and recommendation of remedial alternatives . No source of contamination were discovered and the Air Force pr eferred remedy is natural attenuation/monitoring. The findings fr om the report will be integrated into the basewide RI/FS report s cheduled to be sub- mitted to the agencies on August 15, 1995. A decision on the selected remedy for the TCEF/PCE study area will be documented in the basewide (OU-3) RAP/ROD. Therefore, a separa te RAP/ROD will not be prepared for the TCE/PCE study area. V olume Treated, Stabilized, or Disposed: N/A Approximate cost and funding source: 1.5 million, BRAC 1 RIFS - OU3: The Remedial Investigation and Feasibility Study Report approval letter is enclosed. The following landfills sites were satisfactorily delineated and alternatives provided: RW-09, LF-11, DP-10, WP-40, SS-52, DP-15, DP-33, DP-34 which are in the southeast disposal areas; DP-03,DP-04 LF-12, LF-14, which are in the northeast disposal area. The following sites have TCE and petroleum hydrocarbons in soils , as chemicals of concern; WP-17, FT-20, FT-19a, FT-19b, FT- 19c, OT-51, OT-69. In ADDITION, SITES FT-20 and SS-69 have TCE in groundwater which will be remedied. Schedule for OU#2 revised. Final FS/PP will be due 1/30/94 instead of 11/30/94 because PCE/TCE plume will be handled as RI/FS addendum and ROD will follow OU#3 schedule. OU#2 ROD will be an Interim Contingency ROD/RAP. For a per- iod of 5 years, Air Force will conduct a Natural Attenuation study on the JP-4 plume. In case Natural Attenuation is found not effective, AF to implement contingency alternative remediation specified in the ROD. RIFS OU9 August 15, 1995 GAFB submitted in August 1994, a work pl an for character- ization of low-level radioactive waste disposal site RW-09. The characterization work plan included investigatio n and

testing of the RW-09 disposal site to determine background levels of radiation, testing for the presence of radio- nuclide c ontamination (radium {Ra} -226, Ra-228, thorium {Th}-232, and trit ium), and confirmation sampling for this 2.4 acres site. The wor k plan proposed the following activities: Excavation of soils/d ebris areas as discrete targets, three test pits, and other excav ation areas. Transportation of excavated soils to a mechanical si zing apparatus, where soils and landfill debris will be segregate d by mechanical sizing and field screening of gamma counts. Analy ze collected sample for the presence of Ra-226, Ra-228, Th-232, a nd tritium. Field screen and sample excavation bottoms for the pr esence of radionuclides. Place clean backfill soils and debris in to the open excavations. Properly dispose of radioactive contamin ated soils and debris. Decontamination of all site equipment befo re demobilization. Volume Treated, Stabilized, or Disposed: App roximately 4,000 cubic yards of soil/debris were esti- mated to b e excavated within the RW-09 site. All materials to be excavated were to be screened and sampled for analysis. The materials wer e to be fed into a feed hopper, then through screen for mechanica l sizing, then conveyed beneath a plastic scintillator and detect or for sampling. OM - OU-1: As a result of a Record of Decision which was signed i n February 1994, the Air Force installed 9 extrac- tion wells to simultaneously contain a TCE plume, extract and treat in fluent w aters contaminated with volatile organic compounds and discharge to the percolation ponds. The percolation ponds were established expressly to receive and flush volatile organics into the existin g extraction wells. In 1996 the Air Force implemented Phase II, w hich is comprised of nine additional extraction wells and a compl ete rewiring of the existing system. The Operation and Mainten- a nce Manual being approved addresses: system description, environm ental controls, equipment components, service schedules, startup/ normal operation and shutdown procedures and other information ne eded to operate the system. The system is performing well and is expected to run for a total of 30 years. At this time it costs ap proximately $400,000.00 a year to operate, mostly in electrical c osts and routine maintenance. FRIFS GW: Focused RI/FS for GW was prepared as an Engineer- ing Analysis/ Cost Analysis (EE/CA) by the Air Force. DTSC prepared a Neg. Dec. in compliance with CEQA and filed with the State Clea ring House. Completion of the EE/CA was coun- ted as the focused RI/FS. Federal Facility Agreement (FFA) was signed by Air Force, USEPA, DTSC, and RWQCB. The Remedial Project Managers are: Air Force.. Denise Caron (619)269-2047, USEPA.. Brian Swart- hout (415)744-24 09, DTSC.. Emad Yemut (310)590-4915, RWQCB Jay Cass (619)241-6583 . Contact for reuse issues.. Maria Gillette (310)590-4990. Dispute Resolution was invoked over cleanup levels for TCE and RWQCB's Anti-Degradation Policy (res. 68-16) as an ARAR. Dispute was elevated to Senior Exec. Committee 10/23/92. EPA recommended elevation 3/5/93, stating Region IX posi- tion. RWQCB sent position letter 3/16/93. EPA Administra- tor is expected to render a decision by 5/22/93. The following abbreviations describe the commitments for the AWP activities: NDA: Northeast Disposal Area JET: Jet Fuel Product Collection and Removal Area POL: Petroleum, Oil, and Lubrication Sites, Landfill Sites, and Liquid Fuel Distribution System An RPM meeting was held at George AFB re Natural Attenuation on OU#2 fuel plume. It was decided that a 5 year treatabil. study to determine if Nat. Attn. is working. The FS for OU2 would remain a draft document until after the study. CEQA Notice of Determination, Groundwater Pump & Treat filed RA - DP-04: As a result of aerial GPR, subsurface geophysics incl uding GPR, EM and MAG, extensive soil gas, surface and sub- surfa ce test pits, the Base Closure Team (BCT), including DTSC, have a greed that sufficient information was available to implement a pr esumptive remedy at this site as it qualifies under EPA guidance. Numerous meetings and tele-conferences from 1990 to 1996 resulte d in the BCT implementing the following activities at DP-04 as a presumptive remedy under CERCLA: restoration of the existing soil cover, garding or cutting of the surface to produce slopes of 1. 5 to 3.0 percent to promote surface runoff and decrease infiltrat ion of surface water into the refuse, installation of drainage di tches above the landfill to prevent surface water from running on to the landfills sites, installation of site perimeter fencing an d posting to control site access, and re-establishment of native plant species on the graded surface. During the course of thses a ctivities the DTSC performed field oversight and verified that re vegatation, fencing and posting work was implemented as agreed to . RA - LF08, LF12, LF14, DP15, SS52, DP33, DP34, RW09, WP4 0, DP03 are same as DP04. RA - LF-07: From 1991 to April 1997 t he Base Closure Team has been involved in Remedial Investigation/ Feasiblity Study regarding the base landfills. The USEPA promotes the absence of a former EE/CA. The regulators concurred, includi ng DTSC, while the following activities took place: restoration o f the existing soil cover, grading or cutting of the surface to p roduce slopes of 1.5 percent to promote surface runoff and decrea se infiltration of surface water into the landfill contents, inst allation of drainage ditches adjacent to the landfill boundaries to prevent surface water from running onto the landfill sites, in stallation of site perimeter fencing and signage to control site access, and re-establishment of native plant species on the grade d surface. RA GW: The pump & treat system at OU#1, Northeast Disposal Area consists of 19 extraction wells (9 wells in the first phase) to treat and slow the advance of the TCE plume.

Background:

George Air Force Base (GAFB) is a 5,347 - acre facility located w ithin Victor Valley, San Bernardino County approximately 70 miles northeast of the City of Los Angeles. GAFB was initially activa ted on October 1, 1941 as Victorville Army Airfield. From 1950 t o 1992, GAFB was a tactical jet fighter operation training facili ty. Several investigations have been conducted under the USAF's I RP at GAFB. During the Phase I investigation, 54 sites were form erly identified as known or suspected to have received hazardous materials in the past (1982). Groundwater containinated with Tric hloroethylene (TCE) has been documented both on and off base. Ad ditional hazardous wastes on the base include: asbestos, pesticid es, paint, paint thinner, sludges, fuels (jp-4), petroleum lubric ant and oils (POLs), leaded tank bottoms, explosives, polychlorin ated biphenyls (PCBs), solvents, acids, metals, low level radioac tive wastes, and hospital wastes. Past mitigation activities cond ucted at the base include site characterization and installation of a groundwater extraction and treatment system (Air Stripper). The site was listed on the NPL in 1989. A Federal Facilities Agr eement (FFA) between the Department, U.S. EPA, Lahontan RWQCB, an d the Air Force was signed in September 1990. The FFA outlines t he investigation and mitigation process for the Base. GAFB close d on December 5, 1992. The Base was the first in California to c lose under the BRAC I program.

Site:
ON AUBURN LANE, CROSS ADELANTO ROAD ADELANTO CA 92301 CDL

Clue:	2002-05-063
Date:	5/11/2002
County:	SAN BERNARDINO
Lab Type:	A
Lab Type Desc:	Abandoned Drug Lab Waste - location away from an actual illegal drug lab where drug lab waste and/or equipment were abandoned.

Site:
.5 MILE SO OF SYCAMORE & E OF COBALT VICTORVILLE CA 92392 CDL

Clue:	1998-05-041
Date:	5/9/1998
County:	SAN BERNARDINO
Lab Type:	A
Lab Type Desc:	Abandoned Drug Lab Waste - location away from an actual illegal drug lab where drug lab waste and/or equipment were abandoned.

Site: ***NRC***
Southern California Logistics Airport, north end of George Air Force Base Victorville CA CHMIRS

Control No:	07-2980	***Notified Date:***	
Year:	2007	***Notified Date Time:***	
County:	San Bernardino County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/2f00ff6a3bf0e4d7882572dd00674550?OpenDocument		

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Unknown	***3 Ves >= 300 Tons:***	
1 Substance:	Human Waste	***Incident Date:***	5/15/2007
1 Measure:	N/A	***Incident Time:***	1630
1 Other:	500/PPM	***Spill Site:***	Military Base
1 Quantity:	500	***Injuries?:***	
1 Type:	SEWAGE	***No of Injuries:***	0
1 Pipeline:		***Fatals?:***	
1 Vessel >= 300 Tons:		***No of Fatals:***	0
2 Substance:		***Evacs?:***	
2 Quantity:		***No of Evacs:***	0
2 Measure:		***Cleanup:***	Unknown
2 Type:		***Site:***	Mojave River Basin
2 Other:		***Cause:***	
2 Pipeline:		***Cause Other:***	
2 Vessel >= 300 Tons:		***Dog No:***	
3 Substance:		***Water:***	Yes
3 Quantity:		***Water Way:***	Mojave River Basin
3 Measure:		***City:***	Victorville
3 Type:		***County:***	San Bernardino County
3 Other:		***ZIP:***	
3 Pipeline:			
Admin Agency:	Victorville Fire Department		
Notification Area:	AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS,COASTAL COM,DHS-D.O.,LANDS,PARKS & REC, USCG		
Location:	Southern California Logistics Airport, north end of George Air Force Base		
Description:	Per the NRC report, "THE CALLER STATES THAT A PROPERTY PHASE ONE ENVIRONMENTAL REPORT WAS DONE ON 40 ACRES OF LAND. THE TESTS TESTED POSITIVE FOR 500 PARTS PER MILLION HUMAN WASTE IN THE MOJAVE RIVER BASIN. THE CALLER STATES THAT THE WASTE OVERFLOWS FROM THE PONDS AT THE TREATMENT FACILITY." In the REMEDIAL ACTIONS section of the NRC report, it is reported that "NONE" have been taken.		

Spill Report View

Water:		***Creation Date:***	05/16/2007 11:47 AM
Document Title:	SPILL Report		
Spill Site:	Military Base		
Type:	SEWAGE		

Hazardous Materials Spill Report

Date :	05/16/2007	***Name:***	
Time:	1147	***Phone:***	
Incident Date:	05/15/2007	***Ext:***	
Incident Time:	1630	***Pag Cell:***	
Control Cal OES:	07-2980	***Prs Name:***	
Control NRC:	835573	***Prs Phone:***	
Water Involved:	Yes	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	

UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		
Contained:	Unknown		
Waterway:	Mojave River Basin		
Received By:			
Cleanup By:	Unknown		
Incident Location:	Southern California Logistics Airport, north end of George Air Force Base		
Additional County:			
1 Substance:	Human Waste		
1 Qty:	=		
1 Amount :	500		
1 Measure:	N/A		
1 Type:	SEWAGE		
1 Other:	500/PPM		
1 Pipeline:	No		
1 Ves >= 300 Tons:	No		
2 Substance:			
2 Qty:	=		
2 Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:	No		
2 Ves >= 300 Tns:	No		
3 Substance:			
3 Qty:	=		
3 Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:	No		
3 Ves >= 300 Tons:	No		
Injuries:	No		
Fatality:	No		
Evacuation:	No		
Known Impact:			
Agency:	NRC		
PRS Agency:	Mgr./Real Estate Services		
Sec Agency:	San Bernardino County Health Department		
Admin Agency:	Victorville Fire Department		
Admin Agency 2:			
On Scene:			
Other on Scene:			
Other Notified:			
Header Unknown:	MOJAVE DESERT AQMD		
Site:	Military Base		
Reported Cause:			
R R Crssing < 50 Ft:			
Description:	Per the NRC report, "THE CALLER STATES THAT A PROPERTY PHASE ONE ENVIRONMENTAL REPORT WAS DONE ON 40 ACRES OF LAND. THE TESTS TESTED POSITIVE FOR 500 PARTS PER MILLION HUMAN WASTE IN THE MOJAVE RIVER BASIN. THE CALLER STATES THAT THE WASTE OVERFLOWS FROM THE PONDS AT THE TREATMENT FACILITY." In the REMEDIAL ACTIONS section of the NRC report, it is reported that "NONE" have been taken.		

Site: ***City of Victorville***
between Air Base Dr and Turner Rd. Victorville CA 92392

CHMIRS

Control No:		***Notified Date:***	12/6/199704:18:20 PM
Year:	1997	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	No	***Bbls:***	0
Substance:	Raw sewage	***Cups:***	0
Incident Date:	12/6/199712:00:00 AM	***Cu Ft:***	0
No of Injuries:	0	***Gals:***	Unk

No of Fatals:	0	***Grams:***	0
No of Evacs:	0	***Lbs:***	0
Cleanup:	Reporting Party	***Liters:***	0
Water:	Yes	***Oz:***	0
Water Way:	Wash to Mojave River	***Pts:***	0
City:	Victorville	***Qts:***	0
County:	San Bernardino County	***Sheen:***	0
ZIP:	92392	***Tons:***	0
Site:	Other	***Unknown:***	0

Admin Agency: Victorville Fire Department
Location: between Air Base Dr and Turner Rd.
Description: Storm water undemined a manhole and line broke. Wash located between Air Base Dr and Turner Rd. and ends up a Mojave River

---

Site: ***Victorville City FD***
SoCAl Logistics Airport, Airbase Road & Bantom West Victorville CA CHMIRS

Control No:		***Notified Date:***	6/18/200303:17:22 PM
Year:	2003	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	Yes	***Bbls:***	0
Substance:	Jet Fuel	***Cups:***	0
Incident Date:	6/18/200312:00:00 AM	***Cu Ft:***	0
No of Injuries:	0	***Gals:***	600
No of Fatals:	0	***Grams:***	0
No of Evacs:	0	***Lbs:***	0
Cleanup:	Contractor	***Liters:***	0
Water:	No	***Oz:***	0
Water Way:		***Pts:***	0
City:	Victorville	***Qts:***	0
County:	San Bernardino County	***Sheen:***	0
ZIP:		***Tons:***	0
Site:	Airport	***Unknown:***	0

Admin Agency: Victorville Fire Department
Location: SoCAl Logistics Airport, Airbase Road & Bantom West
Description: Human error at airport, fuel cap was left off of some storage tanks at the airport. This caused a release.

Site: ***Montgomery Watson***
Former George Air Force Base at The Current Skeet Range Victorville CA 94596 CHMIRS

Control No:		***Notified Date:***	4/10/200109:56:45 AM
Year:	2001	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	Yes	***Bbls:***	0
Substance:	Hydraulic Fluid;;;	***Cups:***	0
Incident Date:	4/6/200112:00:00 AM	***Cu Ft:***	0
No of Injuries:	0	***Gals:***	50
No of Fatals:	0	***Grams:***	0
No of Evacs:	0	***Lbs:***	0
Cleanup:	Reporting Party	***Liters:***	0
Water:	No	***Oz:***	0
Water Way:		***Pts:***	0
City:	Victorville	***Qts:***	0
County:	San Bernardino County	***Sheen:***	0
ZIP:	94596	***Tons:***	0
Site:	Other	***Unknown:***	0.000000

Admin Agency: Victorville Fire Department
Location: Former George Air Force Base at The Current Skeet Range
Description: While performing a Lead Remediation one of the pieces of equipment in use ruptured a seal. Clean up is complete and contaminated soil has been put in drums.

Site: ***Southern CA Edison***
7401 Adelanto Road cross street Violet Adelanto CA

CHMIRS

Control No:	08-2902	***Notified Date:***	
Year:	2008	***Notified Date Time:***	
County:	San Bernardino County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/7b4c4e13e4c18f9588257430000ab300?OpenDocument		

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Yes	***3 Ves >= 300 Tons:***	
1 Substance:	mineral oil	***Incident Date:***	4/18/2008
1 Measure:	Gal(s)	***Incident Time:***	1700
1 Other:		***Spill Site:***	Road
1 Quantity:	40	***Injuries?:***	
1 Type:	PETROLEUM	***No of Injuries:***	0
1 Pipeline:		***Fatals?:***	
1 Vessel >= 300 Tons:		***No of Fatals:***	0
2 Substance:		***Evacs?:***	
2 Quantity:		***No of Evacs:***	0
2 Measure:		***Cleanup:***	Contractor
2 Type:		***Site:***	
2 Other:		***Cause:***	
2 Pipeline:		***Cause Other:***	
2 Vessel >= 300 Tons:		***Dog No:***	
3 Substance:		***Water:***	No
3 Quantity:		***Water Way:***	
3 Measure:		***City:***	Adelanto
3 Type:		***County:***	San Bernardino County
3 Other:		***ZIP:***	
3 Pipeline:			
Admin Agency:	San Bernardino County Health Department		
Notification Area:	AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS		
Location:	7401 Adelanto Road cross street Violet		
Description:	Thieves cut down a power pole to get the copper from the transformer.		

Spill Report View

Water:		***Creation Date:***	04/18/2008 06:56 PM
Document Title:	SPILL Report		
Spill Site:	Road		
Type:	PETROLEUM		

Hazardous Materials Spill Report

Date :	04/18/2008	***Name:***	
Time:	1856	***Phone:***	
Incident Date:	04/18/2008	***Ext:***	
Incident Time:	1700	***Pag Cell:***	
Control Cal OES:	08-2902	***Prs Name:***	
Control NRC:		***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	
UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		
Contained:	Yes		
Waterway:			
Received By:			
Cleanup By:	Contractor		
Incident Location:	7401 Adelanto Road cross street Violet		
Additional County:			
1 Substance:	mineral oil		
1 Qty:	=		
1 Amount :	40		

1 Measure:	Gal(s)
1 Type:	PETROLEUM
1 Other:	
1 Pipeline:	No
1 Ves >= 300 Tons:	No
2 Substance:	
2 Qty:	=
2 Amount:	
2 Measure:	
2 Type:	
2 Other:	
2 Pipeline:	No
2 Ves >= 300 Tns:	No
3 Substance:	
3 Qty:	=
3 Amount:	
3 Measure:	
3 Type:	
3 Other:	
3 Pipeline:	No
3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	
Agency:	Southern CA Edison
PRS Agency:	
Sec Agency:	
Admin Agency:	San Bernardino County Health Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	County Fire Haz Mat
Header Unknown:	MOJAVE DESERT AQMD
Site:	Road
Reported Cause:	
R R Crssing < 50 Ft:	
Description:	Thieves cut down a power pole to get the copper from the transformer.

Site: ***Kinder Morgan Southern Region***
Southern California Logistics Airport, 13334 Air Express Way Victorville CA

CHMIRS

Control No:	08-6850	***Notified Date:***	
Year:	2008	***Notified Date Time:***	
County:	San Bernardino County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/3ae42d422b6f052c882574ca002722a0?OpenDocument		

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Yes	***3 Ves >= 300 Tons:***	
1 Substance:	JPA (Jet Fuel)	***Incident Date:***	9/19/2008
1 Measure:	Unknown	***Incident Time:***	2335
1 Other:		***Spill Site:***	Airport
1 Quantity:	unknown mist amount	***Injuries?:***	
1 Type:	PETROLEUM	***No of Injuries:***	0
1 Pipeline:		***Fatals?:***	
1 Vessel >= 300 Tons:		***No of Fatals:***	0
2 Substance:		***Evacs?:***	
2 Quantity:		***No of Evacs:***	0
2 Measure:		***Cleanup:***	Reporting Party
2 Type:		***Site:***	
2 Other:		***Cause:***	
2 Pipeline:		***Cause Other:***	
2 Vessel >= 300 Tons:		***Dog No:***	
3 Substance:		***Water:***	No
3 Quantity:		***Water Way:***	
3 Measure:		***City:***	Victorville
3 Type:		***County:***	San Bernardino County

3 Other: ***ZIP:***
3 Pipeline:
Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS
Location: Southern California Logistics Airport, 13334 Air Express Way
Description: Spill occurred during fuel delivery at an airport. There is a 4 feet by 8 feet wet area on concrete due to the fuel spilling in mist form. Caller states it is "a small amount".

Spill Report View

Water: ***Creation Date:*** 09/20/2008 12:30 AM
Document Title: Cal OES-Update
Spill Site:
Type: PETROLEUM

OES Hazardous Materials Spill Update

Occurrence Date: 09/19/2008 ***Prs Notif Upd Nm:***
Occurrence Time: ***Phone No:***
Notify Date: 09/20/2008 ***Ext:***
Notify Time: 007 ***Pag Cell:***
NRC: 884663 ***Fax Notific List 2:***
RWQCB Unit: ***Admin Agency 2:***
Unknown Header: ***Add Admin Agency 2:***
OP Area: San Bernardino County ***Secondary Agency 2:***
RWQCB Unit 2: ***Dog Unit 2:***
Add Counties 2:
1 Substance: JPA (Jet Fuel)
1 Qty Amount: unknown mist amount
1 Measure: Unknown
1 Type: PETROLEUM
1 Other:
1 Pipeline:
1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan Southern Region
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS
Other Notified:
Confirmation Request:
Administering Agency: Victorville Fire Department
Secondary Agency: San Bernardino County Health Department
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/565e4a97e25156b9882574ca00293eda?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

Received NRC report #884663

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Unknown

Spill Report View

Water:
Creation Date: 09/20/2008 12:07 AM
Document Title: SPILL Report
Spill Site: Airport
Type: PETROLEUM

Hazardous Materials Spill Report

Date : 09/20/2008
Time: 007
Incident Date: 09/19/2008
Incident Time: 2335
Control Cal OES: 08-6850
Control NRC:
Water Involved: No
Drink Wtr Impact:
Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 6B
Contained: Yes
Waterway:
Received By:
Cleanup By: Reporting Party
Incident Location: Southern California Logistics Airport, 13334 Air Express Way
Additional County:
1 Substance: JPA (Jet Fuel)
1 Qty: =
1 Amount : unknown mist amount
1 Measure: Unknown
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No
Fatality: No
Evacuation: No
Known Impact:
Agency: Kinder Morgan Southern Region
PRS Agency:
Sec Agency: San Bernardino County Health Department
Admin Agency: Victorville Fire Department
Admin Agency 2:
On Scene:
Other on Scene:
Other Notified:
Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:
Prs Ext:
Prs Pag Cell:
Incident Desc:
Notification Info:
Notification List:

Header Unknown:	MOJAVE DESERT AQMD
Site:	Airport
Reported Cause:	
R R Crssing < 50 Ft:	
Description:	Spill occurred during fuel delivery at an airport. There is a 4 feet by 8 feet wet area on concrete due to the fuel spilling in mist form. Caller states it is "a small amount".

Site: ***Kinder Morgan***
At the pipeline's entry point to George AFB, Southern California Logistics Airport George Air Force Base CA

CHMIRS

Control No:	07-3142	***Notified Date:***	
Year:	2007	***Notified Date Time:***	
County:	San Bernardino County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/89ce57dcf3c03041882572e4005d51b0?OpenDocument		

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained:	Unknown	***3 Ves >= 300 Tons:***	
1 Substance:	Jet Fuel (Potential Release)	***Incident Date:***	5/23/2007
1 Measure:	Gal(s)	***Incident Time:***	900
1 Other:		***Spill Site:***	Military Base
1 Quantity:	Unknown	***Injuries?:***	
1 Type:	PETROLEUM	***No of Injuries:***	0
1 Pipeline:		***Fatals?:***	
1 Vessel >= 300 Tons:		***No of Fatals:***	0
2 Substance:		***Evacs?:***	
2 Quantity:		***No of Evacs:***	0
2 Measure:		***Cleanup:***	Reporting Party
2 Type:		***Site:***	
2 Other:		***Cause:***	
2 Pipeline:		***Cause Other:***	
2 Vessel >= 300 Tons:		***Dog No:***	1
3 Substance:		***Water:***	No
3 Quantity:		***Water Way:***	
3 Measure:		***City:***	George Air Force Base
3 Type:		***County:***	San Bernardino County
3 Other:		***ZIP:***	
3 Pipeline:			
Admin Agency:			
Notification Area:	AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS,DOG		
Location:	At the pipeline's entry point to George AFB, Southern California Logistics Airport		
Description:	The static pressure on a small pipeline lost pressure and may (potentially) released some jet fuel. This event is still under investigation.		

Spill Report View

Water:		***Creation Date:***	05/29/2007 11:48 AM
Document Title:	Cal OES-Update		
Spill Site:			
Type:	PETROLEUM		

OES Hazardous Materials Spill Update

Occurrence Date:	05/23/2007	***Prs Notif Upd Nm:***	
Occurrence Time:		***Phone No:***	
Notify Date:	05/23/2007	***Ext:***	
Notify Time:	0959	***Pag Cell:***	
NRC:		***Fax Notific List 2:***	
RWQCB Unit:		***Admin Agency 2:***	
Unknown Header:		***Add Admin Agency 2:***	
OP Area:	San Bernardino County	***Secondary Agency 2:***	
RWQCB Unit 2:		***Dog Unit 2:***	
Add Counties 2:			
1 Substance:	Jet Fuel (Potential Release)		
1 Qty Amount:	Unknown		
1 Measure:	Gal(s)		

1 Type: PETROLEUM
1 Other:
1 Pipeline:
1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS, DOG
Other Notified:
Confirmation Request:
Administering Agency:
Secondary Agency:
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/112d6d7e2119b163882572ea00674a7d?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

Per RP George Oballe, pressure test results were positive, pipeline restarted today.

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

Spill Report View

Water:
Creation Date: 05/23/2007 09:59 AM
Document Title: SPILL Report
Spill Site: Military Base
Type: PETROLEUM

Hazardous Materials Spill Report

Date : 05/23/2007
Time: 0959
Incident Date: 05/23/2007
Incident Time: 0900
Control Cal OES: 07-3142
Control NRC:
Water Involved: No
Drink Wtr Impact:
Detail for Other:
UPRR Rim No:
DOG Unit: 1
RWQCB Unit: 6B
Contained: Unknown
Waterway:
Received By:
Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:
Prs Ext:
Prs Pag Cell:
Incident Desc:
Notification Info:
Notification List:

Cleanup By: Reporting Party
Incident Location: At the pipeline's entry point to George AFB, Southern California Logistics Airport
Additional County:
1 Substance: Jet Fuel (Potential Release)
1 Qty: =
1 Amount : Unknown
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No
Fatality: No
Evacuation: No
Known Impact:
Agency: Kinder Morgan
PRS Agency:
Sec Agency:
Admin Agency:
Admin Agency 2:
On Scene:
Other on Scene:
Other Notified:
Header Unknown: SOUTH COAST AQMD
Site: Military Base
Reported Cause:
R R Crssing < 50 Ft:
Description: The static pressure on a small pipeline lost pressure and may (potentially) released some jet fuel. This event is still under investigation.

Spill Report View

Water:
Creation Date: 05/23/2007 10:18 AM
Document Title: Cal OES-Update
Spill Site:
Type: PETROLEUM

OES Hazardous Materials Spill Update

Occurrence Date: 05/23/2007
Occurrence Time:
Notify Date: 05/23/2007
Notify Time: 0959
NRC: 836260
RWQCB Unit:
Unknown Header:
OP Area: San Bernardino County
RWQCB Unit 2:
Add Counties 2:
Prs Notif Upd Nm:
Phone No:
Ext:
Pag Cell:
Fax Notific List 2:
Admin Agency 2:
Add Admin Agency 2:
Secondary Agency 2:
Dog Unit 2:
1 Substance: Jet Fuel (Potential Release)
1 Qty Amount: Unknown
1 Measure: Gal(s)
1 Type: PETROLEUM

1 Other:
1 Pipeline:
1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS, DOG
Other Notified:
Confirmation Request:
Administering Agency:
Secondary Agency:
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/7ccceb91b0a99e0c882572e4005f11da?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

Received NRC # 836260

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

Spill Report View

Water:
Creation Date: 05/23/2007 10:26 AM
Document Title: Cal OES-Update
Spill Site:
Type: PETROLEUM

OES Hazardous Materials Spill Update

Occurrence Date: 05/23/2007
Occurrence Time:
Notify Date: 05/23/2007
Notify Time: 0959
NRC:
RWQCB Unit:
Unknown Header:
OP Area: San Bernardino County
RWQCB Unit 2:
Add Counties 2:
1 Substance: Jet Fuel (Potential Release)
1 Qty Amount: Unknown
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline:
Prs Notif Upd Nm:
Phone No:
Ext:
Pag Cell:
Fax Notific List 2:
Admin Agency 2:
Add Admin Agency 2:
Secondary Agency 2:
Dog Unit 2:

1 Ves >= 300 Tons:
2 Substance:
2 Qty Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Ves >= 300 Tons:
3 Substance:
3 Qty Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline:
3 Ves >= 300 Tons:
Pers Reporting Spill Agency:
Pers Notifying CA OES Agency: Kinder Morgan
Fax Notifi List: AA/CUPA, DFG-OSPR, DTSC, RWQCB, US EPA, USFWS, DOG
Other Notified:
Confirmation Request:
Administering Agency:
Secondary Agency:
Additional Admin Agency:
Additional Counties:
Doc URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/d7212fb1535b4280882572e4005fcc37?OpenDocument
Update Known Impact:
Update Cause:
Update Description:

Situation Update:

RP updates address info as : 13334 Air Expressway, Victorville, CA

Original Description:

OES Hazardous Materials Update Quantities

Amount:
Measure: Gal(s)

Site: ***Kinder Morgan***
Edwards AFB, 13334 Air Express Way Victorville CA CHMIRS

Control No: 06-2599
Year: 2006
Notified Date:
Notified Date Time:
County: San Bernardino County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/b9d0f1d9072db8a28825716100590544?OpenDocument

California Hazardous Material Incident Report System (as of 2006 to 2015)

Contained: Unknown
1 Substance: JP8
1 Measure: Unknown
1 Other:
1 Quantity: UNK
1 Type: PETROLEUM
1 Pipeline:
1 Vessel >= 300 Tons:
2 Substance:
2 Quantity:
2 Measure:
2 Type:
2 Other:
2 Pipeline:
2 Vessel >= 300 Tons:
3 Substance:
3 Ves >= 300 Tons:
Incident Date: 5/1/2006
Incident Time: 912
Spill Site: Pipe Line
Injuries?:
No of Injuries: 0
Fatals?:
No of Fatals: 0
Evacs?:
No of Evacs: 0
Cleanup: Unknown
Site:
Cause:
Cause Other:
Dog No: 1
Water: No

3 Quantity: ***Water Way:***
3 Measure: ***City:*** Victorville
3 Type: ***County:*** San Bernardino County
3 Other: ***ZIP:***
3 Pipeline:
Admin Agency: Victorville Fire Department
Notification Area: AA/CUPA,DFG-OSPR,DTSC,RWQCB,US EPA,USFWS,DOG,SFM
Location: Edwards AFB, 13334 Air Express Way
Description: The caller discovered a leak at pumping station.

Spill Report View

Water: ***Creation Date:*** 05/01/2006 09:12 AM
Document Title: SPILL Report
Spill Site: Pipe Line
Type: PETROLEUM

Hazardous Materials Spill Report

Date : 05/01/2006 ***Name:***
Time: 0912 ***Phone:***
Incident Date: 05/01/2006 ***Ext:***
Incident Time: 0912 ***Pag Cell:***
Control Cal OES: 06-2599 ***Prs Name:***
Control NRC: 795717 ***Prs Phone:***
Water Involved: No ***Prs Ext:***
Drink Wtr Impact: No ***Prs Pag Cell:***
Detail for Other: ***Incident Desc:***
UPRR Rim No: ***Notification Info:***
DOG Unit: 1 ***Notification List:***
RWQCB Unit: 6B
Contained: Unknown
Waterway:
Received By:
Cleanup By: Unknown
Incident Location: Edwards AFB, 13334 Air Express Way
Additional County:
1 Substance: JP8
1 Qty: =
1 Amount : UNK
1 Measure: Unknown
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No
Fatality: No
Evacuation: No
Known Impact:
Agency: Kinder Morgan
PRS Agency:
Sec Agency: San Bernardino County Health Department
Admin Agency: Victorville Fire Department

Admin Agency 2:
On Scene:
Other on Scene:
Other Notified:
Header Unknown: MOJAVE DESERT AQMD
Site: Pipe Line
Reported Cause:
R R Crssing < 50 Ft:
Description: The caller discovered a leak at pumping station.

Site: ***ComAv Technical Services***
Southern California Logistics Airport - Hangar 761 Victorville CA 92394

CHMIRS

Control No: 23-2479
Year: 2023
County: San Bernardino County
URL:

Notified Date: 4/7/2023 10:34:00 AM
Notified Date Time:

Spill Report View

Water:
Document Title: SPILL Report
Spill Site: Airport
Type: PETROLEUM

Creation Date: 04/07/2023 10:34 AM

Hazardous Materials Spill Report

Date : 04/07/2023
Time: 1034
Incident Date: 04/07/2023
Incident Time: 1015
Control Cal OES: 23-2479
Control NRC:
Water Involved: No
Drink Wtr Impact: No
Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 6B
Contained: Stopped, Contained
Waterway: None
Received By:
Cleanup By: Reporting Party
Incident Location: Southern California Logistics Airport - Hangar 761
Additional County:
1 Substance: Jet A Fuel
1 Qty: =
1 Amount : 5
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No

Name:
Phone:
Ext:
Pag Cell:
Prs Name:
Prs Phone:
Prs Ext:
Prs Pag Cell:
Incident Desc:
Notification Info:
Notification List:

3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	None
Agency:	ComAv Technical Services
PRS Agency:	
Sec Agency:	San Bernardino County Fire Department
Admin Agency:	Victorville Fire Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	
Header Unknown:	MOJAVE DESERT AQMD
Site:	Airport
Reported Cause:	Mechanical
R R Crssing < 50 Ft:	
Description:	While removing a fuel line from the engine, a ComAV mechanic noticed a fuel line was open, resulting in 5 gallons spilling onto the Tarmac ramp. Contained and cleanup up by on-site personnel.

California Hazardous Material Incident Report System (2023)

Incident Date:	4/7/2023	***Injuries Yes/No:***	No
Time:	1015	***Injuries No:***	
Water:	No	***Fatals Yes/No:***	No
Cause:	Mechanical	***Fatals No:***	
DOG No:		***Evacs Yes/No:***	No

Spill Site:	Airport
Site:	None
City:	Victorville
County:	San Bernardino County
Zip:	92394
Contained:	Stopped,Contained
Water Way:	None
Evacs No:	
Cleanup:	Reporting Party
A1 Substance:	Jet A Fuel
A1 Quantity:	5
A1 Measure:	Gal(s)
A1 Type:	PETROLEUM
A1 Other:	
A1 Pipeline:	No
A1 Vessel 300 Tons:	No
A2 Substance:	
A2 Quantity:	
A2 Measure:	
A2 Type:	
A2 Other:	
A2 Pipeline:	No
A2 Vessel 300 Tons:	No
A3 Substance:	
A3 Quantity:	
A3 Measure:	
A3 Type:	
A3 Other:	
A3 Pipeline:	No
A3 Vessel 300 Tons:	No
Cause Other:	
Admin Agency:	Victorville Fire Department
Notification Area:	AA/CUPA,DTSC,RWQCB,US EPA,USFWS,DFW-OSPR,Co/WP,Co/Hlth,Co/E-Hlth
Description:	While removing a fuel line from the engine, a ComAV mechanic noticed a fuel line was open, resulting in 5 gallons spilling onto the Tarmac ramp. Contained and cleanup up by on-site personnel.
Location:	Southern California Logistics Airport - Hangar 761

Site: ***NRC***
1007 Yucca Road - IN A DESERT AREA; IN THE BACK OF THE PROPERTY; BEHIND THE TRAILERS
Adelanto CA

CHMIRS

Control No:	23-2532	***Notified Date:***	4/10/2023 12:11:00 PM

Year:	2023	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

Spill Report View

Water:		***Creation Date:***	04/10/2023 12:11 PM
Document Title:	SPILL Report		
Spill Site:	Merchant/Business		
Type:	UNSPECIFIED		

Hazardous Materials Spill Report

Date :	04/10/2023	***Name:***	
Time:	1211	***Phone:***	
Incident Date:	04/10/2023	***Ext:***	
Incident Time:	0900	***Pag Cell:***	
Control Cal OES:	23-2532	***Prs Name:***	
Control NRC:	1364423	***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	
UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		
Contained:	Unknown if stopped, Unknown if contained		
Waterway:	None		
Received By:			
Cleanup By:	Unknown		
Incident Location:	1007 Yucca Road - IN A DESERT AREA; IN THE BACK OF THE PROPERTY; BEHIND THE TRAILERS		
Additional County:			
1 Substance:	Unknown Material		
1 Qty:	=		
1 Amount :	Unknown		
1 Measure:	Gal(s)		
1 Type:	UNSPECIFIED		
1 Other:			
1 Pipeline:	No		
1 Ves >= 300 Tons:	No		
2 Substance:			
2 Qty:	=		
2 Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:	No		
2 Ves >= 300 Tns:	No		
3 Substance:			
3 Qty:	=		
3 Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:	No		
3 Ves >= 300 Tons:	No		
Injuries:	No		
Fatality:	No		
Evacuation:	No		
Known Impact:	None		
Agency:	NRC		
PRS Agency:	Unknown		
Sec Agency:			
Admin Agency:	San Bernardino County Fire Department		
Admin Agency 2:			
On Scene:			
Other on Scene:			
Other Notified:			
Header Unknown:	MOJAVE DESERT AQMD		
Site:	Merchant/Business		

Reported Cause: Unknown
R R Crssing < 50 Ft:
Description: Per NRC: "Paint and other chemicals are being dumped in holes that they dig up inn the dessert. This has been ongoing for several years."

California Hazardous Material Incident Report System (2023)

Incident Date:	4/10/2023	***Injuries Yes/No:***	No
Time:	900	***Injuries No:***	
Water:	No	***Fatals Yes/No:***	No
Cause:	Unknown	***Fatals No:***	
DOG No:		***Evacs Yes/No:***	No

Spill Site: Merchant/Business
Site: None
City: Adelanto
County: San Bernardino County
Zip:
Contained: Unknown if stopped,Unknown if contained
Water Way: None
Evacs No:
Cleanup: Unknown
A1 Substance: Unknown Material
A1 Quantity: Unknown
A1 Measure: Gal(s)
A1 Type: UNSPECIFIED
A1 Other:
A1 Pipeline: No
A1 Vessel 300 Tons: No
A2 Substance:
A2 Quantity:
A2 Measure:
A2 Type:
A2 Other:
A2 Pipeline: No
A2 Vessel 300 Tons: No
A3 Substance:
A3 Quantity:
A3 Measure:
A3 Type:
A3 Other:
A3 Pipeline: No
A3 Vessel 300 Tons: No
Cause Other:
Admin Agency: San Bernardino County Fire Department
Notification Area: AA/CUPA,DTSC,RWQCB,US EPA,USFWS,Co/WP,Co/Hlth,Co/E-Hlth
Description: Per NRC: "Paint and other chemicals are being dumped in holes that they dig up inn the dessert. This has been ongoing for several years."
Location: 1007 Yucca Road - IN A DESERT AREA; IN THE BACK OF THE PROPERTY; BEHIND THE TRAILERS

Site: ***Comav***
Southern California Logistics Airport, Lat 34 35 north x 33 17 west Victorville CA 92394 CHMIRS

Control No:	23-5186	***Notified Date:***	8/14/2023 11:05:00 AM
Year:	2023	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

Spill Report View

Water:		***Creation Date:***	08/14/2023 11:05 AM
Document Title:	SPILL Report		
Spill Site:	Airport		
Type:	PETROLEUM		

Hazardous Materials Spill Report

Date :	08/14/2023	***Name:***	
Time:	1105	***Phone:***	

Incident Date:	08/14/2023	***Ext:***	
Incident Time:	1000	***Pag Cell:***	
Control Cal OES:	23-5186	***Prs Name:***	
Control NRC:		***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	
Detail for Other:		***Incident Desc:***	
UPRR Rim No:		***Notification Info:***	
DOG Unit:		***Notification List:***	
RWQCB Unit:	6B		

Contained:	Stopped, Contained
Waterway:	
Received By:	
Cleanup By:	Reporting Party
Incident Location:	Southern California Logistics Airport, Lat 34 35 north x 33 17 west
Additional County:	
1 Substance:	Jet A Fuel
1 Qty:	=
1 Amount :	5
1 Measure:	Gal(s)
1 Type:	PETROLEUM
1 Other:	
1 Pipeline:	No
1 Ves >= 300 Tons:	No
2 Substance:	
2 Qty:	=
2 Amount:	
2 Measure:	
2 Type:	
2 Other:	
2 Pipeline:	No
2 Ves >= 300 Tns:	No
3 Substance:	
3 Qty:	=
3 Amount:	
3 Measure:	
3 Type:	
3 Other:	
3 Pipeline:	No
3 Ves >= 300 Tons:	No
Injuries:	No
Fatality:	No
Evacuation:	No
Known Impact:	None
Agency:	Comav
PRS Agency:	
Sec Agency:	San Bernardino County Fire Department
Admin Agency:	Victorville Fire Department
Admin Agency 2:	
On Scene:	
Other on Scene:	
Other Notified:	
Header Unknown:	MOJAVE DESERT AQMD
Site:	Airport
Reported Cause:	Other Description for Other : Heat
R R Crssing < 50 Ft:	
Description:	RP states, Due to a wing tank being overfilled on an aircraft, caused the release of approx 5 gallons of Jet A Fuel. No waterways or storrm drains are being impacted. The release has been stopped and contained. Reporting party conducted cleanup of the release.

Spill Report View

Water:		***Creation Date:***	08/14/2023 11:34 AM
Document Title:	Cal OES-Update		
Spill Site:			
Type:	PETROLEUM		

OES Hazardous Materials Spill Update

Occurrence Date:	08/14/2023	***Prs Notif Upd Nm:***	
Occurrence Time:	1000	***Phone No:***	
Notify Date:	08/14/2023	***Ext:***	
Notify Time:	1105	***Pag Cell:***	
NRC:	1376166	***Fax Notific List 2:***	
RWQCB Unit:	6B	***Admin Agency 2:***	
Unknown Header:	MOJAVE DESERT AQMD	***Add Admin Agency 2:***	
OP Area:	San Bernardino County	***Secondary Agency 2:***	
RWQCB Unit 2:		***Dog Unit 2:***	
Add Counties 2:			
1 Substance:	Jet A Fuel		
1 Qty Amount:	5		
1 Measure:	Gal(s)		
1 Type:	PETROLEUM		
1 Other:			
1 Pipeline:	No		
1 Ves >= 300 Tons:	No		
2 Substance:			
2 Qty Amount:			
2 Measure:			
2 Type:			
2 Other:			
2 Pipeline:	No		
2 Ves >= 300 Tons:	No		
3 Substance:			
3 Qty Amount:			
3 Measure:			
3 Type:			
3 Other:			
3 Pipeline:	No		
3 Ves >= 300 Tons:	No		
Pers Reporting Spill Agency:			
Pers Notifying CA OES Agency:	Comav		
Fax Notifi List:	AA/CUPA, DTSC, RWQCB, US EPA, USFWS, Co/Hlth, Co/E-Hlth		
Other Notified:			
Confirmation Request:			
Administering Agency:	Victorville Fire Department		
Secondary Agency:	San Bernardino County Fire Department		
Additional Admin Agency:			
Additional Counties:			
Doc URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/9e4c1b9293d1e47188258a0b00660280?OpenDocument		
Update Known Impact:			
Update Cause:			
Update Description:			

08/14/2023 11:34:13 AM - Per NRC 1376166: CALLER STATES 5 GALLONS OF JET "A" FUEL WAS RELEASED ONTO THE SOIL ON THE EDGE OF THE ASPHALT FROM A COMMERCIAL AIRCRAFT'S OVERFILL VENT. THE HEAT CAUSED THE FUEL TO EXPAND WHICH CAUSED THE RELEASE. EXCAVATED THE SOIL AND PLACED IN DRUMS.

Situation Update:

Per NRC 1376166: CALLER STATES 5 GALLONS OF JET "A" FUEL WAS RELEASED ONTO THE SOIL ON THE EDGE OF THE ASPHALT FROM A COMMERCIAL AIRCRAFT'S OVERFILL VENT. THE HEAT CAUSED THE FUEL TO EXPAND WHICH CAUSED THE RELEASE. EXCAVATED THE SOIL AND PLACED IN DRUMS.

Original Description:

RP states, Due to a wing tank being overfilled on an aircraft, caused the release of approx 5 gallons of Jet A Fuel. No waterways or storrm drains are being impacted. The release has been stopped and contained. Reporting party conducted cleanup of the release.

OES Hazardous Materials Update Quantities

Amount:	
Measure:	Gal(s)

California Hazardous Material Incident Report System (2023)

Incident Date:	8/14/2023	***Injuries Yes/No:***	No
Time:	1000	***Injuries No:***	
Water:	No	***Fatals Yes/No:***	No
Cause:	Other	***Fatals No:***	
DOG No:		***Evacs Yes/No:***	No
Spill Site:	Airport		
Site:			
City:	Victorville		
County:	San Bernardino County		
Zip:	92394		
Contained:	Stopped,Contained		
Water Way:			
Evacs No:			
Cleanup:	Reporting Party		
A1 Substance:	Jet A Fuel		
A1 Quantity:	5		
A1 Measure:	Gal(s)		
A1 Type:	PETROLEUM		
A1 Other:			
A1 Pipeline:	No		
A1 Vessel 300 Tons:	No		
A2 Substance:			
A2 Quantity:			
A2 Measure:			
A2 Type:			
A2 Other:			
A2 Pipeline:	No		
A2 Vessel 300 Tons:	No		
A3 Substance:			
A3 Quantity:			
A3 Measure:			
A3 Type:			
A3 Other:			
A3 Pipeline:	No		
A3 Vessel 300 Tons:	No		
Cause Other:	Heat		
Admin Agency:	Victorville Fire Department		
Notification Area:	AA/CUPA,DTSC,RWQCB,US EPA,USFWS,Co/Hlth,Co/E-Hlth		
Description:	RP states, Due to a wing tank being overfilled on an aircraft, caused the release of approx 5 gallons of Jet A Fuel. No waterways or storrm drains are being impacted. The release has been stopped and contained. Reporting party conducted cleanup of the release.		
Location:	Southern California Logistics Airport, Lat 34 35 north x 33 17 west		

Site: ***Cherokee Nation***
(George Air Force Base) Phantom West and Innovation Way Victorville CA 92394

CHMIRS

Control No:	24-0975	***Notified Date:***	2/15/2024 10:22:00 AM
Year:	2024	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

Spill Report View

Water:		***Creation Date:***	02/15/2024 10:22 AM
Document Title:	SPILL Report		
Spill Site:	Military Base		
Type:	PETROLEUM		

Hazardous Materials Spill Report

Date :	02/15/2024	***Name:***	
Time:	1022	***Phone:***	
Incident Date:	02/08/2024	***Ext:***	
Incident Time:	1030	***Pag Cell:***	
Control Cal OES:	24-0975	***Prs Name:***	
Control NRC:		***Prs Phone:***	
Water Involved:	No	***Prs Ext:***	
Drink Wtr Impact:	No	***Prs Pag Cell:***	

Detail for Other:
UPRR Rim No:
DOG Unit:
RWQCB Unit: 6B
Contained: Stopped, Contained
Waterway:
Received By:
Cleanup By: Contractor
Incident Location: (George Air Force Base) Phantom West and Innovation Way
Additional County:
1 Substance: Contaminated Water
1 Qty: =
1 Amount : 350
1 Measure: Gal(s)
1 Type: PETROLEUM
1 Other:
1 Pipeline: No
1 Ves >= 300 Tons: No
2 Substance:
2 Qty: =
2 Amount:
2 Measure:
2 Type:
2 Other:
2 Pipeline: No
2 Ves >= 300 Tns: No
3 Substance:
3 Qty: =
3 Amount:
3 Measure:
3 Type:
3 Other:
3 Pipeline: No
3 Ves >= 300 Tons: No
Injuries: No
Fatality: No
Evacuation: No
Known Impact: None
Agency: Cherokee Nation
PRS Agency:
Sec Agency: San Bernardino County Fire Department
Admin Agency: Victorville Fire Department
Admin Agency 2:
On Scene:
Other on Scene:
Other Notified: Lahontan Water Board
Header Unknown: MOJAVE DESERT AQMD
Site: Military Base
Reported Cause: Human Error
R R Crssing < 50 Ft:
Description: Per reporting party: An employee was transferring contaminated water from a tank to a treatment system at an inactive military base (George Air Force Base). The transfer was pumped top fast which resulted in the release of 350 gallons onto concrete and soil. This release has been stopped and contained and no water ways were impacted. A contractor will perform the clean up.

California Hazardous Material Incident Report System (2024)

Incident Date: 2/8/2024
Time: 1030
Water: No
Cause: Human Error
DOG No:
Spill Site: Military Base
Site:
City: Victorville
County: San Bernardino County
Zip: 92394
Contained: Stopped,Contained
Water Way:
Evacs No:
Injuries Yes/No: No
Injuries No:
Fatals Yes/No: No
Fatals No:
Evacs Yes/No: No

Cleanup:	Contractor
A1 Substance:	Contaminated Water
A1 Quantity:	350
A1 Measure:	Gal(s)
A1 Type:	PETROLEUM
A1 Other:	
A1 Pipeline:	No
A1 Vessel 300 Tons:	No
A2 Substance:	
A2 Quantity:	
A2 Measure:	
A2 Type:	
A2 Other:	
A2 Pipeline:	No
A2 Vessel 300 Tons:	No
A3 Substance:	
A3 Quantity:	
A3 Measure:	
A3 Type:	
A3 Other:	
A3 Pipeline:	No
A3 Vessel 300 Tons:	No
Cause Other:	
Admin Agency:	Victorville Fire Department
Notification Area:	AA/CUPA,DTSC,RWQCB,US EPA,USFWS,Co/Hlth,Co/E-Hlth
Description:	Per reporting party: An employee was transferring contaminated water from a tank to a treatment system at an inactive military base (George Air Force Base). The transfer was pumped top fast which resulted in the release of 350 gallons onto concrete and soil. This release has been stopped and contained and no water ways were impacted. A contractor will perform the clean up.
Location:	(George Air Force Base) Phantom West and Innovation Way

---

Site: ***Calnev Pipeline Co***
George Terminal, on Airbase Rd., 1 5/8 miles east of Adelanto Rd. Victorville CA 92412

CHMIRS

Control No:		***Notified Date:***	7/27/199811:16:40 AM
Year:	1998	***Notified Date Time:***	
County:	San Bernardino County		
URL:			

California Hazardous Material Incident Report System (as of 1997 to 2005)

Contained:	Yes	***Bbls:***	0
Substance:	Jet Fuel	***Cups:***	0
Incident Date:	7/23/199812:00:00 AM	***Cu Ft:***	0
No of Injuries:	0	***Gals:***	50
No of Fatals:	0	***Grams:***	0
No of Evacs:	0	***Lbs:***	0
Cleanup:	Responsible Party	***Liters:***	0
Water:	No	***Oz:***	0
Water Way:		***Pts:***	0
City:	Victorville	***Qts:***	0
County:	San Bernardino County	***Sheen:***	0
ZIP:	92412	***Tons:***	0
Site:	Other	***Unknown:***	0
Admin Agency:	Victorville Fire Department		
Location:	George Terminal, on Airbase Rd., 1 5/8 miles east of Adelanto Rd.		
Description:	Broken or failed pipe joint below ground on an above ground tank.		

Site: ***calnev pipeline co***
1 and 5/8 miles east of adelanto rd on airbase rd at the george airforce base area adelanto CA

CHMIRS

Control No:		***Notified Date:***	10/4/1994
Year:	1994	***Notified Date Time:***	08:27:55 AM
County:	SAN BERNARDINO		
URL:			

California Hazardous Material Incident Report System (as of 1993 to 1996)

Contained:	NO	***Incident Date:***	unk/25sept94
Substance:	jet fuel	***Injuries?:***	NO
Type:	PETROLEUM	***Fatals?:***	NO
Qty:		***Evacs?:***	NO
Other:		***Cleanup:***	arizona pipeline contractors
Measure:		***Site:***	OTHER
Amount:	approx 4bbls	***City:***	adelanto
Water:	YES	***County:***	SAN BERNARDINO
Water Way:		***ZIP:***	

Location: 1 and 5/8 miles east of adelanto rd on airbase rd at the george airforce base area
Description: sampling line on tank valve was left open

Site: ***calnev pipeline co***
george airforce base terminal 1and 5/8 mile east of adelanto rd on air base rd approx 2 miles from adelanto CA

CHMIRS

Control No:		***Notified Date:***	8/29/1994
Year:	1994	***Notified Date Time:***	03:56:10 PM
County:	SAN BERNARDINO		
URL:			

California Hazardous Material Incident Report System (as of 1993 to 1996)

Contained:	NO	***Incident Date:***	1300/29aug94
Substance:	methyl carbitol (jet fuel additive)	***Injuries?:***	NO
Type:	CHEMICAL	***Fatals?:***	NO
Qty:		***Evacs?:***	NO
Other:		***Cleanup:***	supervise by calnev
Measure:		***Site:***	OTHER
Amount:	6,676 gals	***City:***	adelanto
Water:	YES	***County:***	SAN BERNARDINO
Water Way:		***ZIP:***	

Location: george airforce base terminal 1and 5/8 mile east of adelanto rd on air base rd approx 2 miles from
Description: above ground storage tank valve broke off and discharged above substance to ground and then to containment area

---

Site: ***GEORGE AIR FORCE BASE - OWS 645-S1***
BUILDING 645 PHANTOM VICTORVILLE CA 92392

DELISTED CLEANUP

Delisted GeoTracker Cleanup Program Sites

Global ID:	T10000004119
Site Facility Type:	MILITARY CLEANUP SITE
Status:	OPEN - SITE ASSESSMENT
Status Date:	
County:	SAN BERNARDINO
Latitude:	
Longitude:	
Data Source:	Cleanup Program Sites from GeoTracker Search (as of May 29, 2021)
Record Date:	22-JUN-2021
RWQCB Region:	
Original Source:	GTCL

Site: ***CALNEV PIPE LINE COMPANY***
AIR BASE RD VICTORVILLE CA 92392

EMISSIONS

Source:

1996 Criteria Data

Facility ID:	200255	***CERR Code:***	
Facility SIC Code:	5171	***TOGT:***	5.326091
CO:	36	***ROGT:***	5.326091
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	

COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
SOXT:
PMT:
PM10T:

1996 Toxic Data

Facility ID: 200255
Facility SIC Code: 5171
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

1997 Criteria Data

Facility ID: 200255
Facility SIC Code: 5171
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: 5.326091
ROGT: 5.326091
COT:
NOXT:
SOXT:
PMT:
PM10T:

1997 Toxic Data

Facility ID: 200255
Facility SIC Code: 5171
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

1998 Criteria Data

Facility ID: 200255
Facility SIC Code: 5171
CO: 36
Air Basin: MD
District: MOJ
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:
TOGT: 5.326091
ROGT: 5.326091
COT:
NOXT:
SOXT:
PMT:
PM10T:

1998 Toxic Data

Facility ID: 200255
Facility SIC Code: 5171
CO: 36
Air Basin: MD
District: MOJ
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SBD
DISN: MOJAVE DESERT AQMD
CHAPIS:
CERR Code:

1999 Criteria Data

Facility ID: 200255
Facility SIC Code: 5171
CERR Code:
TOGT: 5.326091

CO:	36	***ROGT:***	5.326091
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1999 Toxic Data

Facility ID:	200255	***COID:***	SBD
Facility SIC Code:	5171	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Site: ***CALNEV PIPE LINE COMPANY***
AIR BASE RD ADELANTO CA 92301

EMISSIONS

Source:

1995 Criteria Data

Facility ID:	200255	***CERR Code:***	
Facility SIC Code:	5171	***TOGT:***	4.5
CO:	36	***ROGT:***	4.5
Air Basin:	MD	***COT:***	
District:	MOJ	***NOXT:***	
COID:	SBD	***SOXT:***	
DISN:	MOJAVE DESERT AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1995 Toxic Data

Facility ID:	200255	***COID:***	SBD
Facility SIC Code:	5171	***DISN:***	MOJAVE DESERT AQMD
CO:	36	***CHAPIS:***	
Air Basin:	MD	***CERR Code:***	
District:	MOJ		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Site:
GEORGE AIR FORCE BASE VICTORYVILLE CA

ERNS

NRC Report No:	836260	***Latitude Degrees:***	
Type of Incident:	PIPELINE	***Latitude Minutes:***	
Incident Cause:	UNKNOWN	***Latitude Seconds:***	
Incident Date:	23-May-2007 09:00:00	***Longitude Degrees:***	
Incident Location:	PIPELINE SECTION NAME: 14 INCH CAL-NAV LINE	***Longitude Minutes:***	
Incident Dtg:	DISCOVERED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	SAN BERNARDINO	***Location Township:***	
Potential Flag:	Yes	***Location Range:***	
Year:	Year 2007 Reports		

Description of Incident: CALLER STATED THERE IS A POTENTIAL RELEASE OF MATERIALS FROM A 14 INCH STEEL PIPELINE DUE TO UNKNOWN CAUSES.

Material Spill Information

Chris Code:	JPE	***Unit of Measure:***	UNKNOWN AMOUNT
CAS No:	000000-00-0	***If Reached Water:***	NO
UN No:		***Amount in Water:***	
Name of Material:	JET FUEL: JP-8	***Unit Reach Water:***	
Amount of Material:	0		

Calls Information

Date Time Received:	23-May-2007 13:09:20	***Responsible City:***	ORANGE
Date Time Complete:	23-May-2007 13:14:49	***Responsible State:***	CA
Call Type:	INC	***Responsible Zip:***	92868
Resp Company:	KINDER MORGAN LIQUID TERMINALS LLC	***Source:***	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	U
NPDES:		***Airbag Deployed:***	U
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	U
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:		***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	U	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:		***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:	DISTRIBUTION	***No of Conductor Tested:***	
Pipeline Abv Ground:	BELOW	***No of Engineer Tested:***	
Pipeline Covered:	U	***No of Trainman Tested:***	
Exposed Underwater:	N	***No of Yard Foreman Tested:***	
Railroad Hotline:		***No of RCL Operator Tested:***	
Railroad Milepost:		***No of Brakeman Tested:***	
Grade Crossing:	U	***No of Train Dispat Tested:***	
Crossing Device Ty:		***No of Signalman Tested:***	
Ty Vehicle Involved:		***No of Other Emp Tested:***	
Device Operational:	Y	***No of Unknown Emp Tested:***	

Incident Details Information

Release Secured:	U	***State Agen Report No:***	07-3142
Release Rate:		***State Agen on Scene:***	NONE
Release Rate Unit:		***State Agen Notified:***	CALIFORNIA OFFICE OF EMERGENCY SERVICES
Release Rate Rate:		***Fed Agency Notified:***	NONE
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	CALLER STATED NO ACTIONS TAKEN.	***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	SUNNY
Radius of Evac:		***Air Temperature:***	80
Any Injuries:	N	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	N	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	
Waterway Close Time:		***Passengers Transfer:***	NO
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:	NONE	***Sheen Odor Desc:***	
Medium Desc:	NON-RELEASE (N/A)	***Duration Unit:***	
Addl Medium Info:		***Additional Info:***	CALLER DID NOT HAVE ANY ADDITIONAL INFORMATION.

Site:

GEORGE AFB TANK NO. 548,POL BULK FUEL STORAGE GEORGE AFB CA 923945000 ERNS

NRC Report No:	19432	***Latitude Degrees:***	
Type of Incident:	PIPELINE	***Latitude Minutes:***	
Incident Cause:	OPERATOR ERROR	***Latitude Seconds:***	
Incident Date:	27-Apr-1990 07:10:00	***Longitude Degrees:***	
Incident Location:		***Longitude Minutes:***	
Incident Dtg:	OCCURRED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	SAN BERNARDINO	***Location Township:***	
Potential Flag:		***Location Range:***	
Year:	Year 1990 Reports		

Description of Incident: 8" PIPELINE / VALVE RELEASED AND PIPELINE WAS PUT UNDER PRESSURE WHILECREWS WERE PERFORMING MAINTENANCE ON THE PIPELINE - HUMAN ERROR

Material Spill Information

Chris Code:	JPF	***Unit of Measure:***	GALLON(S)
CAS No:		***If Reached Water:***	YES
UN No:		***Amount in Water:***	0
Name of Material:	JET FUEL: JP-4	***Unit Reach Water:***	NONE

Amount of Material: 1200

Calls Information

Date Time Received: 27-Apr-1990 16:35:16
Date Time Complete: 27-Apr-1990 16:44:30
Call Type: INC
Resp Company: USAF - GEORGE AFB
Resp Org Type: FEDERAL GOVERNMENT
Responsible City: GEORGE AFB
Responsible State: CA
Responsible Zip: 923945000
Source: UNAVAILABLE

Incident Information

Tank ID:
Tank Regulated: U
Tank Regulated By:
Capacity of Tank:
Capacity Tank Units:
Description of Tank:
Actual Amount:
Actual Amount Units:
Tank Above Ground: ABOVE
NPDES:
NPDES Compliance: U
Init Contin Rel No:
Contin Rel Permit:
Contin Release Type:
Aircraft ID:
Aircraft Runway No:
Aircraft Spot No:
Aircraft Type: UNKNOWN
Aircraft Model:
Aircraft Fuel Cap:
Aircraft Fuel Cap U:
Aircraft Fuel on Brd:
Aircraft Fuel OB U:
Aircraft Hanger:
Road Mile Marker:
Power Gen Facility: U
Generating Capacity:
Type of Fixed Obj: UNKNOWN
Type of Fuel:
DOT Crossing No:
DOT Regulated: U
Pipeline Type: UNKNOWN
Pipeline Abv Ground: ABOVE
Pipeline Covered: U
Exposed Underwater: U
Railroad Hotline: No
Railroad Milepost: UNKNOWN
Grade Crossing: N
Crossing Device Ty:
Ty Vehicle Involved: UNKNOWN
Device Operational: Y

Building ID:
Location Area ID:
Location Block ID:
OCSG No:
OCSP No:
State Lease No:
Pier Dock No:
Berth Slip No:
Brake Failure: N
Airbag Deployed:
Transport Contain: U
Location Subdiv:
Platform Rig Name:
Platform Letter:
Allision: N
Type of Structure:
Structure Name:
Structure Oper: Y
Transit Bus Flag:
Date Time Norm Serv:
Serv Disrupt Time:
Serv Disrupt Units:
CR Begin Date:
CR End Date:
CR Change Date:
FBI Contact:
FBI Contact Dt Tm:
Passenger Handling:
Passenger Route: XXX
Passenger Delay: XXX
Sub Part C Test Req: XXX
No of Conductor Tested:
No of Engineer Tested:
No of Trainman Tested:
No of Yard Foreman Tested:
No of RCL Operator Tested:
No of Brakeman Tested:
No of Train Dispat Tested:
No of Signalman Tested:
No of Other Emp Tested:
No of Unknown Emp Tested:

Incident Details Information

Release Secured: U
Release Rate:
State Agen Report No:
State Agen on Scene:

Release Rate Unit:		***State Agen Notified:***	
Release Rate Rate:		***Fed Agency Notified:***	
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	USED A PUMP AND TANK TO SIPHON OFF THE SPILLED MATERIAL (500 GALS) REMAINDER OF MATERIAL ABSORBED INTO SOIL AND WILL BE EXCAVATED.	***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	
Radius of Evac:		***Air Temperature:***	
Any Injuries:	U	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	U	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	N
Waterway Close Time:		***Passengers Transfer:***	UNK
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:		***Sheen Odor Desc:***	
Medium Desc:	LAND	***Duration Unit:***	
Addl Medium Info:	ASPHALT AND SOIL SURFACE CONTAINMENT AREA	***Additional Info:***	WILL NOTIFY EPA 9, OES, COUNTY DEPT. ENV. HEALTH, WATER QUALITY BOARD.

Site:

1007 YUCCA RD ADELANTO CA

ERNS

NRC Report No:	1364423	***Latitude Degrees:***	
Type of Incident:	FIXED	***Latitude Minutes:***	
Incident Cause:	DUMPING	***Latitude Seconds:***	
Incident Date:	4/10/2023 9:00	***Longitude Degrees:***	
Incident Location:	IN A DESERT AREA; IN THE BACK OF THE PROPERTY; BEHIND THE TRAILERS	***Longitude Minutes:***	
Incident Dtg:	OCCURRED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	SAN BERNARDINO	***Location Township:***	
Potential Flag:	No	***Location Range:***	
Year:	Year 2023 Reports		

Description of Incident: PAINT AND OTHER CHEMICALS ARE BEING DUMPED IN HOLES THAT THEY DIG UP IN THE DESSERT. THIS HAS BEEN ONGOING FOR SEVERAL YEARS.

Material Spill Information

Chris Code:	UNK	***Unit of Measure:***	UNKNOWN AMOUNT
CAS No:	000000-00-0	***If Reached Water:***	NO
UN No:		***Amount in Water:***	
Name of Material:	UNKNOWN MATERIAL (UNKNOWN CHEMICALS)	***Unit Reach Water:***	
Amount of Material:	0		

Chris Code:	NCC	***Unit of Measure:***	UNKNOWN AMOUNT
CAS No:	000000-00-0	***If Reached Water:***	NO
UN No:		***Amount in Water:***	
Name of Material:	NO CHRIS CODE - PAINT	***Unit Reach Water:***	
Amount of Material:	0		

Calls Information

Date Time Received:	4/10/2023 2:58:00 PM	***Responsible City:***	
Date Time Complete:	4/10/2023 3:09:00 PM	***Responsible State:***	CA
Call Type:	INC	***Responsible Zip:***	
Resp Company:	REXDOT LLC	***Source:***	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	U
NPDES:		***Airbag Deployed:***	U
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	U
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:		***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	N	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:	OTHER	***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:		***No of Conductor Tested:***	
Pipeline Abv Ground:	ABOVE	***No of Engineer Tested:***	
Pipeline Covered:	U	***No of Trainman Tested:***	
Exposed Underwater:	N	***No of Yard Foreman Tested:***	
Railroad Hotline:		***No of RCL Operator Tested:***	
Railroad Milepost:		***No of Brakeman Tested:***	
Grade Crossing:	U	***No of Train Dispat Tested:***	
Crossing Device Ty:		***No of Signalman Tested:***	
Ty Vehicle Involved:		***No of Other Emp Tested:***	
Device Operational:	U	***No of Unknown Emp Tested:***	

Incident Details Information

Release Secured:	U	***State Agen Report No:***	
Release Rate:		***State Agen on Scene:***	
Release Rate Unit:		***State Agen Notified:***	
Release Rate Rate:		***Fed Agency Notified:***	
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:		***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	No
Who Evacuated:		***Weather Conditions:***	
Radius of Evac:		***Air Temperature:***	
Any Injuries:	N	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	N	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	
Waterway Close Time:		***Passengers Transfer:***	NO
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:	NONE	***Sheen Odor Desc:***	
Medium Desc:	LAND	***Duration Unit:***	
Addl Medium Info:	IN HOLES THAT ARE DUG UP IN THE DESERT	***Additional Info:***	

Site:

GEORGE AFB AIR BASE RD GEORGE AFB CA

ERNS

NRC Report No:	20210	***Latitude Degrees:***	
Type of Incident:	FIXED	***Latitude Minutes:***	
Incident Cause:	DUMPING	***Latitude Seconds:***	
Incident Date:	02-May-1990 15:00:00	***Longitude Degrees:***	
Incident Location:		***Longitude Minutes:***	
Incident Dtg:	OCCURRED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	SAN BERNARDINO	***Location Township:***	
Potential Flag:		***Location Range:***	
Year:	Year 1990 Reports		
Description of Incident:	30 GALLON DRUM/DUMPED IN RAVINE		

Material Spill Information

Chris Code:	PCB	***Unit of Measure:***	UNKNOWN AMOUNT
CAS No:		***If Reached Water:***	YES
UN No:		***Amount in Water:***	0
Name of Material:	POLYCHLORINATED BIPHENYLS	***Unit Reach Water:***	UNKNOWN AMOUNT
Amount of Material:	0		
Chris Code:	RAM	***Unit of Measure:***	UNKNOWN AMOUNT

CAS No:		***If Reached Water:***	YES
UN No:		***Amount in Water:***	0
Name of Material:	RADIOACTIVE MATERIAL	***Unit Reach Water:***	UNKNOWN AMOUNT
Amount of Material:	0		

Calls Information

Date Time Received:	02-May-1990 17:11:50	***Responsible City:***	GEORGE AFB
Date Time Complete:	02-May-1990 17:20:30	***Responsible State:***	CA
Call Type:	INC	***Responsible Zip:***	
Resp Company:	USAF GEORGE AFB	***Source:***	UNAVAILABLE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	N
NPDES:		***Airbag Deployed:***	
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	N
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:	UNKNOWN	***Structure Oper:***	Y
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	U	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:	UNKNOWN	***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:	UNKNOWN	***No of Conductor Tested:***	
Pipeline Abv Ground:	ABOVE	***No of Engineer Tested:***	
Pipeline Covered:	U	***No of Trainman Tested:***	
Exposed Underwater:	U	***No of Yard Foreman Tested:***	
Railroad Hotline:	No	***No of RCL Operator Tested:***	
Railroad Milepost:	UNKNOWN	***No of Brakeman Tested:***	
Grade Crossing:	N	***No of Train Dispat Tested:***	
Crossing Device Ty:		***No of Signalman Tested:***	
Ty Vehicle Involved:	UNKNOWN	***No of Other Emp Tested:***	
Device Operational:	Y	***No of Unknown Emp Tested:***	

Incident Details Information

Release Secured:	U	***State Agen Report No:***	
Release Rate:		***State Agen on Scene:***	
Release Rate Unit:		***State Agen Notified:***	
Release Rate Rate:		***Fed Agency Notified:***	
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	NONE.	***Body of Water:***	
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	
Radius of Evac:		***Air Temperature:***	
Any Injuries:	U	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	
No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	U	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	N
Waterway Close Time:		***Passengers Transfer:***	UNK
Road Closed:	N	***Passenger Injuries:***	
Road Desc:		***Employee Injuries:***	
Road Closure Time:		***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:		***Sheen Size Units:***	
Major Artery:	No	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:		***Sheen Odor Desc:***	
Medium Desc:	LAND	***Duration Unit:***	
Addl Medium Info:	SOIL	***Additional Info:***	DISPOSAL SITE L-3. DUMPING OCCURED ON AUGUST 7, 1973.CALLER CLAIMS TO SUFFER FROM ACUTE RADIATION TOXICITY.

Site: ***CALNEV PIPE LINE, LLC - GEORGE AFB***
AIR BASE ROAD GEORGE AFB CA 92392

FINDS/FRS

Registry ID:	110070736989
FIPS Code:	06071
HUC Code:	
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	04-MAY-20
Update Date:	
Interest Types:	HAZARDOUS WASTE BIENNIAL REPORTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	09
County Name:	SAN BERNARDINO
US/Mexico Border Ind:	

Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070736989
Program Acronyms:

BR:CAT080013881

Site: ***WESTWINDS GOLF COURSE***
SO CALIF LOGISTICS AIRPORT VICTORVILLE CA 92392

FINDS/FRS

Registry ID: 110064910020
FIPS Code:
HUC Code:
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 10-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: SAN BERNARDINO COUNTY
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110064910020
Program Acronyms:

CA-ENVIROVIEW:263711

Site: ***MOUNTAIN VIEW ACRES STORM DRAIN PROJECT***
COBALT VICTORVILLE CA 92392

FINDS/FRS

Registry ID: 110065777500
FIPS Code:
HUC Code:
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 13-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:

Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: SAN BERNARDINO COUNTY
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065777500
Program Acronyms:

CA-ENVIROVIEW:266910

Site: ***COBALT MIDDLE SCHOOL***
1380 COBALT RD VICTORVILLE CA 92392 FINDS/FRS

Registry ID: 110066225070
FIPS Code:
HUC Code: 18090208
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 14-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 25
Census Block Code: 060710091182003
EPA Region Code: 09
County Name: SAN BERNARDINO COUNTY
US/Mexico Border Ind:
Latitude: 34.50669
Longitude: -117.37318
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066225070
Program Acronyms:

CA-ENVIROVIEW:107174

Site: ***SO. CAL LOGISTICS AIRPORT***
FORMER GEORGE AIR FORCE BASE VICTORVILLE CA 92392 FINDS/FRS

Registry ID: 110065928811
FIPS Code:
HUC Code:

Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 14-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: SAN BERNARDINO COUNTY
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Frs Facility Detail Report URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065928811
Program Acronyms:

CA-ENVIROVIEW:327277

Site: ***SOUTHER CALIFORNIA LOGISTICS AIRPORT***
1800 PHANTOM WEST DRIVE VICTORVILLE CA 923940000

HAZ GEN

EPA ID: CAC002594347 ***Facility County:*** 36
Address 2: ***County:*** San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC002594347

Site: ***NORTHROP GRUMMAN CORP***
GEORGE AIR FORCE BASE VICTORVILLE CA 923940000

HAZ GEN

EPA ID: CAR000000604 ***Facility County:*** 36
Address 2: ***County:*** San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAR000000604

Site: ***CALNEV PIPE LINE LLC - GEORGE AFB***
AIR BASE RD GEORGE AFB CA 923920000

HAZ GEN

EPA ID: CAT080013881 ***Facility County:*** 36
Address 2: ***County:*** San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAT080013881

Site: ***COMMERICAL WOOD PRODUCTS***
1051 YUCCA ADELANTO CA 923010000

HAZ GEN

EPA ID: CAC001413832 ***Facility County:*** 36

Address 2: ***County:*** San Bernardino
Details DTSC HWTS: The Department of Toxic Substances Control (DTSC) makes available a Waste Code Matrix showing each Waste Code, its description, and annual amounts in its Hazardous Waste Tracking System: https://hwts.dtsc.ca.gov/search
Handler Profile URL: https://hwts.dtsc.ca.gov/facility/CAC001413832

Site: ***DH WRIGHT***
2662 PHANTOM WEST ST ADELANTO CA 92301 HAZNET

EPA ID:	CAC002595312	***Mailing City:***	MURRIETA
NAICS Code:		***Mailing State:***	CA
SIC Code:		***Mailing Zip:***	92562
Create Date:	9/12/2005	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	DH WRIGHT
Inact Date:	3/12/2006	***Owner Addr 1:***	40960 CALIFORNIA OAKS RD STE 236
County:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	MURRIETA
County:		***Owner State:***	CA
Mail Name:		***Owner Zip:***	92562
Mailing Addr 1:	40960 CALIFORNIA OAKS RD STE 236	***Owner Phone:***	9099574282
Mailing Addr 2:		***Owner Fax:***	

Site: ***US AIRFORCE***
B-723 PHANTOM BLVD VICTORVILLE CA 923940000 HAZNET

EPA ID:	CAC001251816	***Mailing City:***	VICTORVILLE
NAICS Code:		***Mailing State:***	CA
SIC Code:		***Mailing Zip:***	923940000
Create Date:	10/17/1997	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	US AIRFORCE
Inact Date:	10/25/2000	***Owner Addr 1:***	13436 SABRE BLVD BOX 2 B 321
County:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	VICTORVILLE
County:		***Owner State:***	CA
Mail Name:		***Owner Zip:***	923940000
Mailing Addr 1:	13436 SABRE BLVD BOX 2 B 321	***Owner Phone:***	0000000000
Mailing Addr 2:		***Owner Fax:***	

Site: ***1X ADELANTO UNIFIED SCHOOL DISTRICT***
GEORGE AIR FORCE ELEMENTARY GERORGE AIR FORCE BA CA 923940000 HAZNET

EPA ID:	CAC000266905	***Mailing City:***	ADELANTO
NAICS Code:		***Mailing State:***	CA
SIC Code:		***Mailing Zip:***	923010000
Create Date:	4/4/1990	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	ADELANTO UNIFIED SCHOOL DIST.
Inact Date:	10/25/2000	***Owner Addr 1:***	--
County:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	--
County:		***Owner State:***	99
Mail Name:		***Owner Zip:***	--
Mailing Addr 1:	--	***Owner Phone:***	0000000000
Mailing Addr 2:		***Owner Fax:***	

Site: ***CIRCLE K STORES #8644***
NEC HWY 395 & AIR BASE ADELANTO CA 000000000 HAZNET

EPA ID:	CAL000013076	***Mailing City:***	CARMICHAEL
NAICS Code:		***Mailing State:***	CA
SIC Code:		***Mailing Zip:***	956080137
Create Date:	11/14/1989	***Region Code:***	1
Fac Act Ind:	No	***Owner Name:***	CIRCLE K CORPORATION
Inact Date:	6/30/1998	***Owner Addr 1:***	--
County:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	--
County:		***Owner State:***	99
Mail Name:		***Owner Zip:***	--

Mailing Addr 1:	5811 MANZANITA AVE	***Owner Phone:***	0000000000
Mailing Addr 2:		***Owner Fax:***	

Site: ***GEORGE AIR FORCE BASE***
831ST CSG/DEEV AIR BASE ROAD GEORGE AFB CA 92394

HHSS

County:	San Bernardino
Tank Details Microfiche:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00029d86.pdf

Site: ***GEORGE AIR FORCE BASE***
AIR BASE RAD, GEORGE AIR FORCE ADELANTO ROAD ADELANTO CA 92392

HHSS

County:	San Bernardino
Tank Details Microfiche:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00029b34.pdf

Site:
GEORGE AFB VICTORVILLE CA

HIST CHMIRS

OES Control NO:	8906246	***Incident Date:***	5/22/1989
Release Factors:	Failure to Control Hazmat,Operational Deficiency	***Date Reported:***	5/30/1989
Release Text:		***Fatalities:***	0
Equipm Involved:	Other	***Other Injury:***	2
Action Taken Text:		***Other Decon:***	0
Chemicals:	CHLORINE	***Other Fatal:***	0
Case Number:		***Vehicle:***	
HazMat Other:	RESPONSIBL,	***State:***	
HM Injury:	0	***CA DOT PUC ICC:***	
Decon:	2	***Company Name:***	
Agency Name:	SAN BERNARDINO CDEHS	***County:***	SAN BERNARDINO
HazMat Pers:	Other,On-site Fire Services		
Action Taken:	63,Decon-Person/Equip,Establish Safe Area,Investigate,Remove Hazard (Neutralize)		
More than three involved?:	2		

Site:
AIR BASE RD GEORGE AFB CA 923920000

HIST MANIFEST

Gen EPA ID:	CAT080013881
Create Date:	7/23/1982 0:00:00
Inact Date:	
Facility Mail Street:	1100 TOWN AND COUNTRY RD
Facility Mail City:	ORANGE
Facility Mail State:	CA
Facility Mail Zip:	928680000
Contact Phone(s):	7145604887
File Year(s):	1988; 1991
Contact Name(s):	KARINA HANKINS

Tanner Information

State Waste Code:	222	***Generator County:***	San Bernardino
Year:	1991	***Tsd Epa ID:***	CAT080013352
Tons:	55.87	***Tsd County:***	Los Angeles
Method Code:	R01		
State Waste Code Desc:	Oil/water separation sludge		
Method Description:			

Tanner Information

State Waste Code:	222	***Generator County:***	San Bernardino
Year:	1988	***Tsd Epa ID:***	CAD028409019
Tons:	15.76	***Tsd County:***	Los Angeles
Method Code:	R01		

State Waste Code Desc: Oil/water separation sludge
Method Description:

Site: ***GEORGE AIR FORCE BASE***
AIR BASE RAD, GEORGE AIR FORCE ADELANTO CA

HIST TANK

Owner Name:	CALNEV PIPE LINE COMPANY	***No of Containers:***	2
Owner Street:	412 HOSPITALITY LANE	***County:***	SAN BERNARDINO
Owner City:	SAN BERNARDINO	***Facility State:***	CA
Owner State:	CA	***Facility Zip:***	92392
Owner Zip:	92408		

Site:
ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1990101061	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-09-09	***Report Submit Src:***	Paper
Time of Incident:	1250	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	***Transport Phase:***	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	***Incident Occrrnce:***	
Trade Name:	SODIUM HYDROXIDE SOL	***Mat Ship Approval?:***	No
ID No:	UN1824	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.03125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	109	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FISHER SCIENTIFIC CO
Cont1 Pkging Type:		***Shipper Street Name:***	1600 W GLENDALE AVE
Cont1 Const Mat:		***Shipper City:***	ITASCA
Cont1 Head Type:		***Shipper State:***	IL
Cont1 Pkg Capacity:	4	***Shipper Postal:***	60143
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	305-096463-X
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FRESNO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	93701
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	8

C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	20	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	40	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCK WORKER FOUND ONE CARTON LYING ON ITS SIDE WHEN UNLOADING TRAILER. INNER CONTIANER CAPS HAD APPARENTLY COME LOOSE WHEN CARTON FELL. CARDBOARD CARTON ABSORBED ALL SPILLAGE AND THE DAMAGED CARTON WAS PLACED INSIDE A RECOVERY PAIL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1990060638	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-06-12	***Report Submit Src:***	Paper
Time of Incident:	0600	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	RESIN SOLUTION, FLAMMABLE	***Transport Phase:***	Unloading

Commodity Long Nm:	RESIN SOLUTION, FLAMMABLE	***Incident Occrrnce:***	
Trade Name:	RESIN SOLUTION	***Mat Ship Approval?:***	No
ID No:	UN1866	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	304	***CR Non US State:***	
How Failed Desc:	Cracked	***CR Fed DOT ID:***	71821
Failure Cause Code:	508	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Defective Component or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	REICHHOLD CHEMICALS INC
Cont1 Pkging Type:		***Shipper Street Name:***	5980 ARCTURUS
Cont1 Const Mat:		***Shipper City:***	OXNARD
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	55	***Shipper Postal:***	93022
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	823-069484-5
Cont1 Pkg No:	9	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	KELSO
C1 Pkg Dsign Pres.:	0	***Destination State:***	WASHINGTON
C1 Dsign Press UOM:		***Destination Postal:***	98626
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	

Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	100	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCK WORKER COULD SMELL AN ODOR AND DISCOVERED ONE DRUM LEAKING AT THE SEAM. SUPERVISOR REFERRED TO THE EMERGENCY RESPONSE GUIDE FOR CLEANUP PROCEDURES. THE DAMAGED DRUM WAS PLACED INTO A RECOVERY DRUM AND FORWARDED. NO GROUND CONTAMINATION OCCURRED AND ALL SPILLAGE WAS CLEANED FROM TRAILER.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996070253	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-06-16	***Report Submit Src:***	Paper
Time of Incident:	1310	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE, AQUEO	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	HYDROGEN PEROXIDE, AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40 PERCENT HYDROGEN PEROXIDE (STABILIZED AS NECESSARY)	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2014	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2.5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	109	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	512	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Fire, Temperature, or Heat	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	PAINT & LACQUER CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	2705 S RARITAN
Cont1 Const Mat:		***Shipper City:***	ENGLEWOOD
Cont1 Head Type:		***Shipper State:***	CO
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	890 142091
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	

Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	CORONA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	Yes	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: CRUSHED CARTON WAS FOUND WHILE TRAILER WAS BEING STRIPPED. APPEARS TO BE THE RESULT OF FREIGHT SHIFTING IN TRANSIT. THE AREA WAS ISOLATED AND MATERIAL IDENTIFIED. CHEMTREC WAS CONTACTED. SPILL WAS CLEANED UP AND PLACED IN A RECOVERY DRUM.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992100663	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-09-25	***Report Submit Src:***	Paper
Time of Incident:	0700	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	NAPHTHA, PETROLEUM	***Transport Phase:***	Loading
Commodity Long Nm:	NAPHTHA, PETROLEUM	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1255	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Portable Tank
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	102; 106; 141	***CR State:***	OH
What Failed Desc:	Auxiliary Valve; Bottom Outlet Valve; Piping or Fittings	***CR Postal Code:***	44310
How Failed Code:	; ;	***CR Non US State:***	
How Failed Desc:	; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	526; 517;	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Loose Closure, Component, or Device; Improper Preparation for Transportation;	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	CHEM ARROW CORP
Cont1 Pkging Type:		***Shipper Street Name:***	13643 LIVE OAK LN
Cont1 Const Mat:		***Shipper City:***	IRWINDALE
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	150	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	815-680588
Cont1 Pkg No:	4	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	YUMA
C1 Pkg Dsign Pres.:	0	***Destination State:***	ARIZONA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0

RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	100	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	200	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	TANK
Haz Hosp Old Form:	0	***HMIS Container Code:***	TANK PRT
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Portable tank
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	Yes
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING UNLOADING, DOCKWORKER DETECT4D A SMALL AMOUNT OF LIQUID ON THE TRAILER FLOOR UNDER ONE OF THE TANKS. THE EMERGENCY PHONE NUMBER WAS CONTACTED AND ALL SPILLAGE CLEANED PER INSTRUCTIONS. WHEN THE TANK WAS REMOVED FROM THE TRAILER, IT WAS DISCOVERED THE VALVE WAS STUCK, CAUSING IT TO DRAIN, THE SHIPPER GAVE INSTRUCTIONS. WHEN THE TANK WAS REMOVED FROM THE TRAILER, IT WAS DISCOVERED THE VALVE WAS STUCK, CAUSING IT TO DRAIN, THE SHIPPER GAVE REPAIR INSTRUCTIONS AND THE VALVE WAS CLOSED AND END CAP TIGHTENED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994010932	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-12-21	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	POISONOUS SOLIDS, N.O.S	***Transport Phase:***	In Transit
Commodity Long Nm:	POISONOUS SOLIDS, N.O.S	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2811	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0	***CR Street Name:***	1077 GORGE BLVD

Unit of Measure:		***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	501	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Abrasion	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	NOT REPORTED BY CARRIER
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	UNKNOWN
Cont1 Head Type:		***Shipper State:***	
Cont1 Pkg Capacity:	50	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	XX
Cont1 Pkg Amt:	0	***Shipper Country:***	
C1 Pkg Amt UOM:		***Shipper Waybill:***	265 573861
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	
C1 Pkg Dsign Pres.:	0	***Destination State:***	
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No

Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BAG PAPER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BAG PPR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Paper bag (cont1 for solid materials)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER NOTED SPILLAGE FROM ONE BAG AND DISCOVERED IT HAD APPARENTLY BEEN PUNCTURED IN TRANSIT FORM OVERHANGING THE EDGE OF THE SKID. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. ALL SPILLAGE WAS CLEANED AND RECOUPED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992100141	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-08-24	***Report Submit Src:***	Paper
Time of Incident:	2300	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	PHOSPHORIC ACID SOLUTION	***Transport Phase:***	Unloading
Commodity Long Nm:	PHOSPHORIC ACID SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1805	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.0625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	TWECO PROD
Cont1 Pkging Type:		***Shipper Street Name:***	4200 W HARRY
Cont1 Const Mat:		***Shipper City:***	WICHITA
Cont1 Head Type:		***Shipper State:***	KS
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	569-735765
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA FE SPRINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	2.5
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA

C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	120	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER WAS MOVING A SKID WHEN ONE CARTON FELL FROM THE TOP, HIT THE TRAILER FLOOR AND BEGAN TO LEAK. THE MATERIAL WAS IDENTIFIED AND THE AREA WAS ISOLATED. THE EMERGENCY RESPONSE GUIDEBOOK WAS CONSULTED AND THE DAMAGED CONTAINER PLACE INSIDE A RECOVERY DRUM. THE SHIPPER WAS CONTACTED AND THE DAMAGED MATERIAL IS BEING HELD FOR DISPOSITION.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994120872	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	

Date of Incident:	1994-11-12	***Report Submit Src:***	Paper
Time of Incident:	1100	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	ISOCYANATES, LIQUID OR S	***Transport Phase:***	Loading
Commodity Long Nm:	ISOCYANATES, LIQUID OR SOLID, N.O.S. OR ISOCYANTE SOLUTIONS, N.O.S. BOILING POINT NOT LESS THAN 300 DEGREES C	***Incident Occrrnce:***	
Trade Name:	STA BOND	***Mat Ship Approval?:***	No
ID No:	UN2207	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	55	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	STABOND CORP
Cont1 Pkging Type:		***Shipper Street Name:***	14010 SOUTH WESTERN
Cont1 Const Mat:		***Shipper City:***	GARDENA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831-949866
Cont1 Pkg No:	24	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	DECATUR
C1 Pkg Dsign Pres.:	0	***Destination State:***	INDIANA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No

Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	500	***Contact Business:***	
Carrier Damage:	2800	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	5000	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	8300	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DRUM WAS APPARENTLY PUNCTURED DURING LOADING, ALLOWING MATERIAL TO LEAK. HAZMAT RECOVERY TEAM WAS CALLED IN AND RESPONDED TO CONT AND CLEANED UP SPILLED MATERIAL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996101024	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-09-23	***Report Submit Src:***	Paper
Time of Incident:	1900	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	PHOSPHORIC ACID SOLUTION	***Transport Phase:***	Loading
Commodity Long Nm:	PHOSPHORIC ACID SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1805	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MALLINCKRODT BAKER INC
Cont1 Pkging Type:		***Shipper Street Name:***	600 N BROAD
Cont1 Const Mat:		***Shipper City:***	PHILLIPSBURG
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	134-347563

Cont1 Pkg No:	40	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	THOUSAND OAKS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: EMPLOYEE NOTIFIED RELAY OF TRAILER WITH SMALL LEAK ON REAR. FURTHER INVESTIGATION REVEALED A PUNCTURED DRUM. APPEARS PUNCTURE WAS RESULT OF FORKLIFT BLADE. THE AREA WAS ISOLATED AND SHIPPING PAPERS CONSULTED. CHEMTREC WAS CALLED AND MSDS OBTAINED.

Recommend Actions Taken: CLEANUP AND RECOVERY WERE HANDLED ACCORDING TO EMERGENCY RESPONSE GUIDELINES.

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993040505	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-04-06	***Report Submit Src:***	Paper
Time of Incident:	1025	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	SULFURIC ACID	***Transport Phase:***	Unloading
Commodity Long Nm:	SULFURIC ACID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1830	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	; ;	***CR State:***	OH
What Failed Desc:	; ;	***CR Postal Code:***	44310
How Failed Code:	303; ;	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 519; 517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Inadequate Blocking and Bracing; Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SPECTRUM CHEMICAL MFG
Cont1 Pkging Type:		***Shipper Street Name:***	14422 SO SAN PEDRO ST
Cont1 Const Mat:		***Shipper City:***	GARDENA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	7.5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831-887748
Cont1 Pkg No:	3	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	DARIEN
C1 Pkg Dsign Pres.:	0	***Destination State:***	ILLINOIS
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1.875
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	12
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0

RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	200	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	225	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	12B
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Boxes
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN DOCKWORKER OPENED DOOR TO UNLOAD TRAILER, TWO CARTONS FELL FROM THE REAR OF THE TRAILER, STRIKING THE DOCK FLOOR AND CAUSING THE INNER CONTAINERS TO LEAK MATERIAL ONTO THE DOCK AND THE PAVEMENT BELOW. THE AREA WAS ISOLATED AND THE SPILLAGE CONTAINED. THE SHIPPER WAS CONTACTED AND A MATERIAL SAFETY DATA SHEET OBTAINED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996120119	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-09-14	***Report Submit Src:***	Paper
Time of Incident:	0750	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANOPHOSPHORUS PESTICI	***Transport Phase:***	Unloading
Commodity Long Nm:	ORGANOPHOSPHORUS PESTICIDES, LIQUID, TOXIC, FLAMMABLE, FLASH POINT NOT LESS THAN 23 DEGREES C	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3017	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	

TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.046875	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	;	***CR State:***	OH
What Failed Desc:	;	***CR Postal Code:***	44310
How Failed Code:	303;	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VAN WATERS & ROGERS
Cont1 Pkging Type:		***Shipper Street Name:***	777 BRISBANE
Cont1 Const Mat:		***Shipper City:***	HOUSTON
Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	521261369
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	NATIONAL CITY
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US

Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: BOX OF HAZMAT FELL DURING UNLOADING PROCESS. THE AREA WAS ISOLATED AND SHIPPING PAPERS CONSULTED. CHEMTREC WAS NOTIFIED AND MSDS OBTAINED. CLEANUP AND RECOVERY WERE HANDLED ACCORDING TO EMERGENCY RESPONSE GUIDELINES. RECOOPED DRUM WITH PRODUCT WAS FORWARDED TO DESTINATION.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994061433	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-05-31	***Report Submit Src:***	Paper
Time of Incident:	0230	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	ACETIC ACID SOLUTION, NO	***Transport Phase:***	Unloading
Commodity Long Nm:	ACETIC ACID SOLUTION, NOT LESS THAN 50 PERCENT BUT NOT MORE THAN 80 PERCENT ACID, BY MASS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2790	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.046875	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	109; 103	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Basic Material	***CR Postal Code:***	44310
How Failed Code:	;	***CR Non US State:***	
How Failed Desc:	;	***CR Fed DOT ID:***	71821
Failure Cause Code:	508;	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Defective Component or Device;	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	U S GOVT - DEFENSE DEPOT(DGSC)
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	RICHMOND
Cont1 Head Type:		***Shipper State:***	VA
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	162-091023
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA ANA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA

C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER FOUND ONE CARTON WET AND STAINED AND DISCOVERED THE CAP ON ONE INNER CONTAINER WAS LOOSE, ALLOWING THE MATERIAL TO SPILL INTO THE CARTON. ALL SPILLAGE WAS ABSORBED BY THE CARDBOARD AND THE SOAKED CONTAINER WAS SEALED INSIDE A RECOVERY PAIL FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996060205	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-05-19	***Report Submit Src:***	Paper
Time of Incident:	1300	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ETHYLENE DICHLORIDE	***Transport Phase:***	Loading
Commodity Long Nm:	ETHYLENE DICHLORIDE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1184	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.15625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	TEDIA COMPANY INC
Cont1 Pkging Type:		***Shipper Street Name:***	2880 SYMMES ROAD
Cont1 Const Mat:		***Shipper City:***	FAIRFIELD
Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	241-551870
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	GARDENA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No

Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE STACKING ANOTHER SKID GLASS BOTTLE WAS PUNCTURED. THE AREA WAS ISOLATED AND PRODUCT IDENTIFIED. CLEANUP AND RECOVERY WERE HANDLED ACCORDING TO EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992070526	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-06-28	***Report Submit Src:***	Paper
Time of Incident:	1400	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	2.2	***Mode Transport:***	Highway
Commodity Short Nm:	DICHLORODIFLUOROMETHANE	***Transport Phase:***	Unloading
Commodity Long Nm:	DICHLORODIFLUOROMETHANE OR REFRIGERANT GAS R 12	***Incident Occrrnce:***	
Trade Name:	R-12	***Mat Ship Approval?:***	No
ID No:	UN1028	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	30	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	TECHNICAL CHEM CO
Cont1 Pkging Type:		***Shipper Street Name:***	10737 SPANGLER RD
Cont1 Const Mat:		***Shipper City:***	DALLAS

Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	30	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	511-676733
Cont1 Pkg No:	120	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	CARSON
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	30
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	SLB
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	120
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	100	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	0	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	100	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton

Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: ONE SKID OF CYLINDERS SHIFTED BACK ONTO THE FORKLIFT MAST DURING UNLOADING DUE TO LOOSE STACKING. ONE CYLINDER WAS PUNCTURED AND THE CONTENTS ESCAPED. NO CLEANUP WAS NECESSARY.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995090207	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-07-13	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	HYDRAZINE HYDRATE OR HYD	***Transport Phase:***	Unloading
Commodity Long Nm:	HYDRAZINE HYDRATE OR HYDRAZINE AQUEOUS SOLUTIONS, WITH NOT MORE THAN 64 PERCENT HYDRAZINE, BY MASS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2030	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.09375	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	516	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	BACHEM
Cont1 Pkging Type:		***Shipper Street Name:***	3132 KASHIWA ST
Cont1 Const Mat:		***Shipper City:***	TORRANCE
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	828821295
Cont1 Pkg No:	11	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	MILWAUKEE
C1 Pkg Dsign Pres.:	0	***Destination State:***	WISCONSIN
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0

RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	90	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	100	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DOCK WORKER DISCOVERED A LEAKING PAIL AND ISOLATED THE AREA. THE MATERIAL WAS IDENTIFIED AND CLEAN UP AND RECOVERY HANDLED PER EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993040270	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-03-07	***Report Submit Src:***	Paper
Time of Incident:	1400	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	OXIDIZING LIQUID, CORROS	***Transport Phase:***	Unloading
Commodity Long Nm:	OXIDIZING LIQUID, CORROSIVE, N.O.S.	***Incident Occrrnce:***	
Trade Name:	HYDROGEN PEROXIDE	***Mat Ship Approval?:***	No
ID No:	UN3098	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No

Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	161; ;	***CR State:***	OH
What Failed Desc:	Weld or Seam; ;	***CR Postal Code:***	44310
How Failed Code:	; ;	***CR Non US State:***	
How Failed Desc:	; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 519; 517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Inadequate Blocking and Bracing; Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MINNTECH/RENAL SYSTEMS
Cont1 Pkging Type:		***Shipper Street Name:***	14905 28TH AVE
Cont1 Const Mat:		***Shipper City:***	MINNEAPOLIS
Cont1 Head Type:		***Shipper State:***	MN
Cont1 Pkg Capacity:	6.25	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	385-660477
Cont1 Pkg No:	3	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LONG BEACH
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1.5
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	12
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	15	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	

Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	30	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED ONE CARTON THAT WAS NOT LOADED TIGHTLY HAD APPARENTLY SHIFTED IN TRANSIT. CAUSING THE BOX TO FALL AND ALLOW THE MATERIAL TO LEAK. THE AREA WAS ISOLATED AND THE PRODUCT RELEASED WAS IDENTIFIED. THE EMERGENCY RESPONSE GUIDEBOOK WAS CONSULTED AND THE CONTAINMENT AND RECOVERY INSTRUCTIOND FOLLOWED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992100665	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-09-27	***Report Submit Src:***	Paper
Time of Incident:	1350	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	INK PRINTERS FLAMMABLE	***Transport Phase:***	Unloading
Commodity Long Nm:	INK PRINTERS FLAMMABLE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1210	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.09375	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	U S GOVT - GSA
Cont1 Pkging Type:		***Shipper Street Name:***	501 FELIX & HEMPHILL
Cont1 Const Mat:		***Shipper City:***	FORT WORTH
Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	514-905002
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	UNKNOWN
C1 Pkg Dsign Pres.:	0	***Destination State:***	HAWAII

C1 Dsign Press UOM:		***Destination Postal:***	UNKNOWN
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	110	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER WAS REMOVING CARTONS FROM THE TRAILER, WHEN THE CARTON OF HAZARDOUS MATERIALS FELL TO THE TRAILER FLOOR, CAUSING THE INNER CONTAINER TO BURST OPEN. THE MATERIAL WAS IDENTIFIED AND THE DAMAGED CARTON RECOUPED INTO A RECOVERY DRUM ALONG WITH ALL CONTAMINATED MATERIALS FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998040365	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-03-15	***Report Submit Src:***	Paper
Time of Incident:	0530	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	PHOSPHORIC ACID SOLUTION	***Transport Phase:***	Unloading
Commodity Long Nm:	PHOSPHORIC ACID SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1805	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1.88	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FISHER SCIENTIFIC CO
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	SOMERVILLE
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	129 135497
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	UNKNOWN
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	UNKNOWN
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No

Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	500	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	300	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	800	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING UNLOADING THE DOCK WORKER NOTICED A LEAKAGE AND ISOLATED THE AREA. CHEMTREC WAS NOTIFIED AND AN MSDS OBTAINED. UPON INVESTIGATION, ONE CARTON WAS FOUND THAT HAD BEEN PUNCTURED BY ADJACENT FREIGHT. AMPLIMAG RESPONDED TO THE SITE TO CLEAN UP THE SPILL. ALL DAMAGED MATERIALS WERE SEALED INSIDE A RECOVERY DRUM AND HELD FOR DISPOSAL. THE REST OF THE SHIPMENT WAS FORWARDED.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998020935	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-01-30	***Report Submit Src:***	Paper
Time of Incident:	1700	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	9	***Mode Transport:***	Highway
Commodity Short Nm:	ENVIRONMENTALLY HAZARDOU	***Transport Phase:***	Loading
Commodity Long Nm:	ENVIRONMENTALLY HAZARDOUS SUBSTANCES, LIQUID, N.O.S.	***Incident Occrrnce:***	
Trade Name:	NUGRO CAPTAN 4000	***Mat Ship Approval?:***	No
ID No:	UN3082	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	H P I PRODUCTS

Cont1 Pkging Type:		***Shipper Street Name:***	222 SYLVANIA STREET
Cont1 Const Mat:		***Shipper City:***	ST JOSEPH
Cont1 Head Type:		***Shipper State:***	MO
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	365-474290
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FRESNO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	275	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	300	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL

Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: ONE DRUM WAS FOUND PUNCTURED DURING LOADING AND WAS RECOUPED. AN MSDS AND SHIPPER INSTRUCTIONS WERE REQUESTED AND ALL RELEASED MATERIAL CLEANED. THE DAMAGED DRUM WILL BE HELD FOR DISPOSITION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997121276	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-11-25	***Report Submit Src:***	Paper
Time of Incident:	1652	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	XYLENES	***Transport Phase:***	In Transit
Commodity Long Nm:	XYLENES	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1307	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MORTON INTERNATIONAL
Cont1 Pkging Type:		***Shipper Street Name:***	335 MCLEAN BLVD
Cont1 Const Mat:		***Shipper City:***	PATERSON
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	750003474
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	
C1 Pkg Dsign Pres.:	0	***Destination State:***	
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	

RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	185	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING LOADING, CONTAINER WAS PUNCTURED. CAUSING MATERIAL TO LEAK. THE AREA WAS ISOLATED AND THE DAMAGED CONTAINER RECOVERED INTO A DRUM FOR FORWARDING TO DESTINATION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997101630	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-09-18	***Report Submit Src:***	Paper
Time of Incident:	1219	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	POISONOUS SOLIDS, N.O.S	***Transport Phase:***	Unloading
Commodity Long Nm:	POISONOUS SOLIDS, N.O.S	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2811	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No

Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	4	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	WYCKOFF CHEMICAL COMPANY
Cont1 Pkging Type:		***Shipper Street Name:***	1421 KALAMAZOO ST
Cont1 Const Mat:		***Shipper City:***	SOUTH HAVEN
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	312-082116
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	NORTHRIDGE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	150	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	

Total Damages Amt:	175	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Drum - fiber, metal or plastic not specified
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING UNLOADING, DOCKWORKER NOTICED DRUM HAD BEEN PUNCTURED AND RELEASED SMALL AMOUNT OF PRODUCT. CHEMTREC WAS NOTIFIED AND AN MSDS REQUESTED ALL SPILLAGE WAS SWEPT AND PLACED INTO A FIBER DRUM ALONG WITH THE REMAINDER OF THE PRODUCT. ALL MATERIAL WILL BE RETURNED TO SHIPPER, AS REQUESTED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997101631	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-09-04	***Report Submit Src:***	Paper
Time of Incident:	0945	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	EXTRACTS, AROMATIC, LIQU	***Transport Phase:***	Unloading
Commodity Long Nm:	EXTRACTS, AROMATIC, LIQUID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1169	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	4	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	516	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	HIGH RISE RECYCLING
Cont1 Pkging Type:		***Shipper Street Name:***	16255 NW 54TH AVE
Cont1 Const Mat:		***Shipper City:***	MIAMI LAKES
Cont1 Head Type:		***Shipper State:***	FL
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	721-414408
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	COVINA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	

C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	85	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	PAIL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE UNLOADING A SKID FROM THE TRAILER, A NEARBY PAIL WAS PUNCTURED. CHEMTREC WAS CONTACTED AND MSDS OBTAINED. THE CONTAINER AND DAMAGED PRODUCT WERE PLACED INTO A RECOVERY DRUM AND IS BEING HELD FOR DISPOSITION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995010775	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-12-18	***Report Submit Src:***	Paper
Time of Incident:	1849	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	POISONOUS SOLIDS, N.O.S	***Transport Phase:***	Unloading
Commodity Long Nm:	POISONOUS SOLIDS, N.O.S	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2811	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103; ;	***CR State:***	OH
What Failed Desc:	Basic Material; ;	***CR Postal Code:***	44310
How Failed Code:	303; 310;	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured; Ripped or Torn;	***CR Fed DOT ID:***	71821
Failure Cause Code:	511; 517; 519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped; Improper Preparation for Transportation; Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VANDERBILT R T CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	820 FLORANE
Cont1 Const Mat:		***Shipper City:***	AKRON
Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	50	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	211603558
Cont1 Pkg No:	4	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA FE SPRINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No

Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BAG PAPER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BAG PPR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Paper bag (cont1 for solid materials)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN THE DOCK WORKER OPENED THE TRAILER DOOR THE MATERIAL FELL OUT ON THE DOCK. THE BAGS HAD BEEN POORLY STACKED WITH LOOSE SHRINK WRAP AND SHIFTED IN TRANSIT. THE AREA WAS ISOLATED, THE MATERIAL IDENTIFIED AND THE EMERGENCY RESPONSE TEAM NOTIFIED FOR CLEAN UP AND RECOVERY.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996050774	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-04-24	***Report Submit Src:***	Paper
Time of Incident:	1430	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	SULFURIC ACID	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	SULFURIC ACID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1830	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.023438	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SCOTCH CORP
Cont1 Pkging Type:		***Shipper Street Name:***	4774 ALGIERS
Cont1 Const Mat:		***Shipper City:***	DALLAS

Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	3	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	511776432
Cont1 Pkg No:	32	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SIGNAL HILL
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.5
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	192
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton

Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER FOUND HOLE IN BOTTOM CARTON WHILE LOADING FREIGHT. ONE OF THE BOTTLES HAD LEAKED A SMALL AMOUNT OF MATERIAL. PRODUCT WAS RECOUPED INTO A RECOVERY DRUM AND FORWARDED ON TO CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995060642	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-05-26	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	NAPHTHA, PETROLEUM	***Transport Phase:***	Unloading
Commodity Long Nm:	NAPHTHA, PETROLEUM	***Incident Occrrnce:***	
Trade Name:	COLEMAN FUEL	***Mat Ship Approval?:***	No
ID No:	UN1255	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.023438	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	301	***CR Non US State:***	
How Failed Desc:	Abraded	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	COLEMAN CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	2111 E 37TH STREET N
Cont1 Const Mat:		***Shipper City:***	WICHITA
Cont1 Head Type:		***Shipper State:***	KS
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	569-854611
Cont1 Pkg No:	61	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FONTANA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	244
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0

RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	5	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	30	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DOCK WORKER DISCOVERED A SATURATED CARTON WHILE UNLOADING A TRAILER. THE AREA WAS ISOLATED, THE MATERIAL IDENTIFIED AND THE EMERGENCY RESPONSE NUMBER WAS CONTACTED FOR CLEAN UP AND RECOVERY INSTRUCTIONS.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996070252	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-06-04	***Report Submit Src:***	Paper
Time of Incident:	1545	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANOPHOSPHORUS PESTICI	***Transport Phase:***	In Transit
Commodity Long Nm:	ORGANOPHOSPHORUS PESTICIDES, LIQUID, TOXIC, FLAMMABLE, FLASH POINT NOT LESS THAN 23 DEGREES C	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3017	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk

HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.015625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SNYDER TRADING
Cont1 Pkging Type:		***Shipper Street Name:***	4505 BOONVILLE
Cont1 Const Mat:		***Shipper City:***	EVANSVILLE
Cont1 Head Type:		***Shipper State:***	IN
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	322 637009
Cont1 Pkg No:	337	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	REEDLEY
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	337
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US

Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED WET CARTONS ON A PALLET. THE AREA WAS IMMEDIATELY ISOLATED AND PRODUCT IDENTIFIED. EMERGENCY RESPONSE TEAM MEMBER CLEANED UP AND PLACED DAMAGED MATERIAL INTO A RECOVERY DRUM. RECOVERY DRUM WAS RETURNED TO SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995090210	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-08-14	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CAUSTIC ALKALI LIQUIDS,	***Transport Phase:***	Unloading
Commodity Long Nm:	CAUSTIC ALKALI LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	SODIUM HYDROXIDE	***Mat Ship Approval?:***	No
ID No:	UN1719	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.046875	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	304;	***CR Non US State:***	
How Failed Desc:	Cracked;	***CR Fed DOT ID:***	71821
Failure Cause Code:	506; 501	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Corrosion - Exterior; Abrasion	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	DIVERSEY CHEMICALS CORP
Cont1 Pkging Type:		***Shipper Street Name:***	1201 S GRAHAM ST
Cont1 Const Mat:		***Shipper City:***	CHARLOTTE
Cont1 Head Type:		***Shipper State:***	NC
Cont1 Pkg Capacity:	6	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	681776761
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	BREA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	

C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	5	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	20	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE UNLOADING A TRAILER, THE DOCK WORKER DISCOVERED A LEAKING DEFECTIVE DRUM. THE AREA WAS ISOLATED, THE MATERIAL IDENTIFIED AND CLEAN UP AND RECOVERY WAS HANDLED PER EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No: I-1993060906 ***Fed DOT Agency Nm:***

Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-05-24	***Report Submit Src:***	Paper
Time of Incident:	0530	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	AMMONIUM SULFIDE SOLUTION	***Transport Phase:***	Unloading
Commodity Long Nm:	AMMONIUM SULFIDE SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2683	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	JOST CHEMICAL
Cont1 Pkging Type:		***Shipper Street Name:***	3260 BRANNON
Cont1 Const Mat:		***Shipper City:***	SAINT LOUIS
Cont1 Head Type:		***Shipper State:***	MO
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	341-609723
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	GARDENA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No

Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	100	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	200	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	300	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: UPON OPENING THE TRAILER DOOR, DOCKWORKER NOTED TWO DRUMS WITH A PUNCTURE MARK NEAR THE TOP OF THE CONTAINER, RESULTING IN SPILLAGE. THE AREA WAS ISOLATED AND THE EMERGENCY RESPONSE NUMBER CONTACTED. ALL SPILLED MATERIAL WAS CLEANED AND THE DAMAGED DRUMS WERE RECOVERED AS INSTRUCTED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998010370	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-12-16	***Report Submit Src:***	Paper
Time of Incident:	1724	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	TRICHLOROETHYLENE	***Transport Phase:***	In Transit
Commodity Long Nm:	TRICHLOROETHYLENE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1710	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.007809	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; ;	***CR State:***	OH
What Failed Desc:	Basic Material; ;	***CR Postal Code:***	44310
How Failed Code:	305; ;	***CR Non US State:***	
How Failed Desc:	Crushed; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 519; 534	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Inadequate Blocking and Bracing; Too Much Weight on Package	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MYSTIC METAL MOVER
Cont1 Pkging Type:		***Shipper Street Name:***	1216 NORTH 6TH
Cont1 Const Mat:		***Shipper City:***	PRINCETON
Cont1 Head Type:		***Shipper State:***	IL
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	

Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	358434193
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	CARSON
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	5	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	180	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE LOAD APPARENTLY SHIFTED ENROUTE, CAUSING A SMALL AMOUNT OF PRODUCT TO LEAK FROM

ONE CONTAINER. THE AREA WAS ISOLATED AND THE DAMAGED CONTAINER PLACED INTO A RECOVERY DRUM FOR FORWARDING TO CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995060618	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-06-05	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, POISO	***Transport Phase:***	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, POISONOUS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	SODIUM HYDROXIDE	***Mat Ship Approval?:***	No
ID No:	UN2922	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	161	***CR State:***	OH
What Failed Desc:	Weld or Seam	***CR Postal Code:***	44310
How Failed Code:	304	***CR Non US State:***	
How Failed Desc:	Cracked	***CR Fed DOT ID:***	71821
Failure Cause Code:	506	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Corrosion - Exterior	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	LAROX INC
Cont1 Pkging Type:		***Shipper Street Name:***	9730 PATUXENT WOODS
Cont1 Const Mat:		***Shipper City:***	COLUMBIA
Cont1 Head Type:		***Shipper State:***	MD
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	156-576319
Cont1 Pkg No:	3	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA FE SPRINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0

RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	1500	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1550	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DRUM SEAMS CRACKED RELEASING A SMALL AMOUNT OF MATERIAL ONTO THE TRAILER FLOOR WAS DISCOVERED BY A DOCK WORKER WHILE UNLOADING THE TRAILER. THE AREA WAS ISOLATED, THE MATERIAL IDENTIFIED AND CHEMTREC CONTACTED FOR CLEAN UP AND RECOVERY INSTRUCTIONS.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994061432	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-05-24	***Report Submit Src:***	Paper
Time of Incident:	0345	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	9	***Mode Transport:***	Highway
Commodity Short Nm:	ENVIRONMENTALLY HAZARDOU	***Transport Phase:***	Unloading
Commodity Long Nm:	ENVIRONMENTALLY HAZARDOUS SUBSTANCES, LIQUID, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3082	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.0625	***CR Street Name:***	1077 GORGE BLVD

Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; 109	***CR State:***	OH
What Failed Desc:	Basic Material; Closure (e.g., Cap, Top, or Plug)	***CR Postal Code:***	44310
How Failed Code:	305; 305	***CR Non US State:***	
How Failed Desc:	Crushed; Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	PANG RUBBER
Cont1 Pkging Type:		***Shipper Street Name:***	1650 NAND
Cont1 Const Mat:		***Shipper City:***	LOS ANGELES
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0.0625	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	821-563055
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SIOUX FALLS
C1 Pkg Dsign Pres.:	0	***Destination State:***	SOUTH DAKOTA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.0625
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	50	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	100	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	

Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED CARTON HAD APPRENTLY BEEN CRUSHED BY FREIGHT SHIFTING IN TRANSIT. AND ISOALTED THE AREA. THE SPILLAGE WAS CONTAINED BY CARDBOARD OF ADJACENT CARTONS AND NO SPILLAGE REACHED OUTSIDE THE TRAILER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992060819	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-06-11	***Report Submit Src:***	Paper
Time of Incident:	0450	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	PHOSPHORIC ACID	***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.0625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	501	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Abrasion	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	HELENA CHEMICAL CO
Cont1 Pkging Type:		***Shipper Street Name:***	2589 N AIR PRESNO DR
Cont1 Const Mat:		***Shipper City:***	FRESNO
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	361351
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LUBBOCK
C1 Pkg Dsign Pres.:	0	***Destination State:***	TEXAS
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	

C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	10	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	60	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN ONE PALLET WAS REMOVED DURING UNLOADING, DOCKWORKER NOTED MATERIAL SPILLED ONTO THE TRAILER FLOOR AND FOUND ONE CARTON LEAKING. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. THE DAMAGED CONTAINER WAS PLACED INTO A RECOVERY DRUM AND HELD FOR DISPOSITION. NO GROUND CONTAMINATION OCCURRED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No: I-1995110544 ***Fed DOT Agency Nm:***

Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-10-27	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ADHESIVES, CONTAINING A	***Transport Phase:***	Unloading
Commodity Long Nm:	ADHESIVES, CONTAINING A FLAMMABLE LIQUID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1133	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	3	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	STABOND CORP
Cont1 Pkging Type:		***Shipper Street Name:***	14010 S WESTERN AVE
Cont1 Const Mat:		***Shipper City:***	GARDENA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831950130
Cont1 Pkg No:	14	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	INDIANAPOLIS
C1 Pkg Dsign Pres.:	0	***Destination State:***	INDIANA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No

Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	20	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	40	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DOCK WORKER PUNCTURED A PAIL WITH THE FORKLIFT WHILE UNLOADING A TRAILER. THE AREA WAS ISOLATED, THE MATERIAL IDENTIFIED AND CLEAN UP AND RECOVERY WAS HANDLED PER EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1990030693	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-03-19	***Report Submit Src:***	Paper
Time of Incident:	0445	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	AMMONIA SOLUTION, RELATI	***Transport Phase:***	In Transit
Commodity Long Nm:	AMMONIA SOLUTION, RELATIVE DENSITY BETWEEN 0.880 AND 0.957 AT 15 DEGREES C IN WATER, WITH MORE THAN 10 PERCENT BUT NOT MORE THAN 35 PERCENT AMMONIA	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2672	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	109; 161	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Weld or Seam	***CR Postal Code:***	44310
How Failed Code:	;	***CR Non US State:***	
How Failed Desc:	;	***CR Fed DOT ID:***	71821
Failure Cause Code:	;	***CR Hazmat Reg ID:***	
Failure Cause Desc:	;	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	KELLERMEYER CO
Cont1 Pkging Type:		***Shipper Street Name:***	1025 BROWN AVE
Cont1 Const Mat:		***Shipper City:***	TOLEDO

Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	6	***Shipper Postal:***	43607
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	251 405648 1
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	ARCADIA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	91006
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	6
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	2000	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	0	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	2020	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton

Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: TWO CONTAINERS WERE DISCOVERED IN AN OVERTURNED CARTON HAVING LEAKED THEIR CONTENTS ONTO FREIGHT BELOW THEM.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997031197	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-02-24	***Report Submit Src:***	Paper
Time of Incident:	0130	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	PERCHLORIC ACID WITH MOR	***Transport Phase:***	In Transit
Commodity Long Nm:	PERCHLORIC ACID WITH MORE THAN 50 PERCENT BUT NOT MORE THAN 72 PERCENT ACID, BY MASS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1873	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.015625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	;	***CR Non US State:***	
How Failed Desc:	;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	CMS
Cont1 Pkging Type:		***Shipper Street Name:***	7383 EMPIRE DRIVE
Cont1 Const Mat:		***Shipper City:***	FLORENCE
Cont1 Head Type:		***Shipper State:***	KY
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	299750080
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	VAN NUYS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	

RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	20	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	30	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WET BOX AND DAMP SPOT ON TRAILER FLOOR WERE DISCOVERED DURING UNLOADING PROCESS. APPEARS CARTONS FELL OVER DURING TRANSIT. THE AREA WAS SECURED AND PRODUCT IDENTIFIED. SHIPPER WAS NOTIFIED. ABSORBENT MATERIAL WAS PLACED ONTO SPILL AREA AND THEN PUT INTO A RECOVERY DRUM. DAMAGED BOX WAS PLACED INTO ANOTHER DRUM AND IS BEING HELD UNTIL DISPOSITION IS RECEIVED FROM THE SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998010955	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-12-21	***Report Submit Src:***	Paper
Time of Incident:	1100	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	DICHLOROBUTENE	***Transport Phase:***	Unloading
Commodity Long Nm:	DICHLOROBUTENE	***Incident Occrrnce:***	
Trade Name:	DIMETHYLAMINO PROPYL	***Mat Ship Approval?:***	No
ID No:	NA2920	***Mat Ship Approv No:***	

Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:		***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	43310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	RAYCHEM CHEMICAL
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	CHULA VISTA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	1.25	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	839-233979
Cont1 Pkg No:	5	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	HOUSTON
C1 Pkg Dsign Pres.:	0	***Destination State:***	TEXAS
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	30	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	

Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	105	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: FORKLIFT DRIVER NOTICED A LEAKING CONTAINER AND ISOLATED THE AREA. SORBANT MATERIAL WAS USED TO CLEAN AND CONTAIN THE SPILLAGE THEN SEALED INSIDE A DRUM FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998080178	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-07-16	***Report Submit Src:***	Paper
Time of Incident:	0522	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	1,1,1-TRICHLOROETHANE	***Transport Phase:***	In Transit
Commodity Long Nm:	1,1,1-TRICHLOROETHANE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2831	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.359375	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	L P S RESEARCH LABS INC
Cont1 Pkging Type:		***Shipper Street Name:***	4647 HOWELL RD
Cont1 Const Mat:		***Shipper City:***	TUCKER
Cont1 Head Type:		***Shipper State:***	GA
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	411 261041
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	WHITTIER
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	

C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	680	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	345	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1025	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE UNLOADING THE TRAILER A PAIL WAS FOUND LEAKING. THE AREA WAS ISOLATED AND CHEMTREC NOTIFIED. AN MSDS WAS OBTAINED. ABSORBENT MATERIAL WAS USED TO CONTAIN FREE PRODUCT. CLEAN UP MATERIAL AND DAMAGED PAIL WERE PLACED INTO A RECOVERY DRUM WHICH WILL BE RETURNED TO THE SHIPPER. BALANCE OF SHIPMENT WAS FORWARDED TO CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997120151	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-10-28	***Report Submit Src:***	Paper
Time of Incident:	2115	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANOCHLORINE PESTICIDE	***Transport Phase:***	Not Available
Commodity Long Nm:	ORGANOCHLORINE PESTICIDES, LIQUID, TOXIC	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2996	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	NOVARTIS CROP PROTECTION
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	MEMPHIS
Cont1 Head Type:		***Shipper State:***	TN
Cont1 Pkg Capacity:	3	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	431-968853
Cont1 Pkg No:	7	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SAN MARCOS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.25
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	84
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No

Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	95	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: BOTTLE FELL FROM A BOX AND WAS CRUSHED BY A TOW MOTOR. THE AREA WAS ISOLATED AND CHEMTREC CONTACTED. CHEMTREC FAXED MSDS AND NOTIFIED SHIPPER. SPILL WAS CLEANED UP AND DAMAGED MATERIALS PLACED INTO A RECOVERY DRUM. DRUM IS BEING HELD PENDING DISPOSITION FROM THE SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995010776	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-11-14	***Report Submit Src:***	Paper
Time of Incident:	1849	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	DITHIOCARBAMATE PESTICID	***Transport Phase:***	Unloading
Commodity Long Nm:	DITHIOCARBAMATE PESTICIDES, SOLID, TOXIC, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2771	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	4	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	309; 310	***CR Non US State:***	
How Failed Desc:	Punctured; Ripped or Torn	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 501	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Abrasion	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	GROWER SERV CORP

Cont1 Pkging Type:		***Shipper Street Name:***	1673 INDUSTRIAL PKWY
Cont1 Const Mat:		***Shipper City:***	LANSING
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	50	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	265573861
Cont1 Pkg No:	80	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FRESNO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	50	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	75	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BAG PLASTIC

Haz Hosp Old Form:	0	***HMIS Container Code:***	BAG PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic bag (cont1 for solid materials)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DOCK WORKER DISCOVERED A SPILL WHILE UNLOADING THE TRAILER. A BAG HAD BECOME PUNCTURED DURING TRANSIT. THE AREA WAS ISOLATED AND CHEMTREC CONTACTED FOR HANDLING. THE MANUFACTURER ADVISED CLEAN UP AND RECOVERY INSTRUCTIONS.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994120873	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-11-03	***Report Submit Src:***	Paper
Time of Incident:	1030	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, N.O.S.	***Transport Phase:***	Loading
Commodity Long Nm:	FLAMMABLE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	XYLENE	***Mat Ship Approval?:***	No
ID No:	UN1993	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	516	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FERMENTA ANIMAL HEALTH
Cont1 Pkging Type:		***Shipper Street Name:***	225 INDUSTRIAL PARK DRIVE
Cont1 Const Mat:		***Shipper City:***	LAKE HAVASU CITY
Cont1 Head Type:		***Shipper State:***	AZ
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	341-010921
Cont1 Pkg No:	40	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	PERRIS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	40
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0

RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	35	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: YARD WORKER NOTED TRAILER LEAKING AND SECURED THE TRAILER IN AN ISOLATED AREA OF THE DOCK. WHEN LEAKING STOPPED, FREIGHT BILL WAS SECURED AND COMMODITY IDENTIFIED. EMERGENCY RESPONSE NUMBER WAS CALLED, AND DAMAGED CARTON WAS REMOVED AND RECOVERED. REMAINDER OF THE SHIPMENT WAS FORWARDED PER SHIPPER'S INSTRUCTIONS.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997040074	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-03-10	***Report Submit Src:***	Paper
Time of Incident:	2130	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	PRINTING INK, FLAMMABLE	***Transport Phase:***	In Transit
Commodity Long Nm:	PRINTING INK, FLAMMABLE OR PRINTING INK RELATED MATERIAL (INCLUDING PRINTING INK THINNING OR REDUCING	***Incident Occrrnce:***	

COMPOUND), FLAMMABLE

Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1210	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.007813	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	516	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g., nails)	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SUN CHEMICAL CORP
Cont1 Pkging Type:		***Shipper Street Name:***	12049 CENTRON PLAZA
Cont1 Const Mat:		***Shipper City:***	CINCINNATI
Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	241750818
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA FE SPRINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	

Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: A DRUM WITH A SMALL PINHOLE WAS DISCOVERED DURING UNLOADING PROCESS. APPEARS PUNCTURE WAS CAUSED BY A NAIL. ABSORBENT MATERIAL WAS PLACED ON SPILLED PRODUCT AND THEN PLACED IN A RECOVERY DRUM. DRUM OF WASTE IS BEING HELD FOR DISPOSAL. DAMAGED DRUM WAS PLACED IN OVERPACK AND BEING HELD UNTIL DISPOSITION IS RECEIVED FROM THE SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996090975	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-08-09	***Report Submit Src:***	Paper
Time of Incident:	0800	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SOCO LYNCH
Cont1 Pkging Type:		***Shipper Street Name:***	3270 E WASHINGTON
Cont1 Const Mat:		***Shipper City:***	LOS ANGELES
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	821-842261
Cont1 Pkg No:	5	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	

Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	EAST GRANBY
C1 Pkg Dsign Pres.:	0	***Destination State:***	CONNECTICUT
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	CAN
Haz Hosp Old Form:	0	***HMIS Container Code:***	CAN MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal can, capacity 7 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: LEAKING CAN WAS DISCOVERED DURING UNLOADING PROCESS. LEAK WAS CAUSED BY THE LID COMING OFF AND THE CAN BEING DENTED. THE AREA WAS ISOLATED AND PRODUCT IDENTIFIED. DAMAGED MATERIAL WAS PLACED IN A RECOVERY DRUM AND FORWARDED ON TO THE CONSIGNEE.

Recommend Actions Taken:

Site:

HMIRS

ADELANTO RD ADELANTO CA

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995091325	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-09-05	***Report Submit Src:***	Paper
Time of Incident:	1100	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	SODIUM CYANIDE	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	SODIUM CYANIDE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1689	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.007813	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VAN WATERS & ROGERS
Cont1 Pkging Type:		***Shipper Street Name:***	1363 S BONNIE BEACH
Cont1 Const Mat:		***Shipper City:***	LOS ANGELES
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	25	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	821-537567
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	GLENDALE
C1 Pkg Dsign Pres.:	0	***Destination State:***	ARIZONA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0

Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	35	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Drum - fiber, metal or plastic not specified
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED PUNCTURED DRUM ON DOCK. AREA WAS ISOLATED AND PRODUCT IDENTIFIED. CLEAN UP RECOVERY HANDLED PER EMERGENCY RESPONSE GUIDELINES. DRUM BEING RETURNED TO SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993060172	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-05-13	***Report Submit Src:***	Paper
Time of Incident:	1130	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	PETROLEUM OIL	***Transport Phase:***	Loading
Commodity Long Nm:	PETROLEUM OIL	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	NA1270	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Other -
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	40	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	APPLIED SILICONE CORP

Cont1 Pkging Type:		***Shipper Street Name:***	1375 N OLIVE ST
Cont1 Const Mat:		***Shipper City:***	VENTURA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	125	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	823-203327
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	IRVING
C1 Pkg Dsign Pres.:	0	***Destination State:***	TEXAS
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	30	***Contact Business:***	
Carrier Damage:	3000	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	1000	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	4030	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	CONTAINER

Haz Hosp Old Form:	0	***HMIS Container Code:***	CONT
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: MACHINERY WAS HEAVIER THAT PALLET COULD HOLD AND PALLET APPARENTLY BROKE WHEN IT WAS MOVED FOR LOADING. THE SPILLAGE WAS CONTAINED USING ABSORBENTS AND THE CONTAMINATED MATERIAL WAS THEN RECOVERED INTO RECOVERY DRUMS.

Recommend Actions Taken:

Site:

ADELANTO RD. ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993010681	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-01-08	***Report Submit Src:***	Paper
Time of Incident:	1000	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	DIPHENYLMETHANE-4,4DIISO	***Transport Phase:***	Unloading
Commodity Long Nm:	DIPHENYLMETHANE-4,4DIISOCYANATE	***Incident Occrrnce:***	
Trade Name:	DIIOSCYANATE	***Mat Ship Approval?:***	No
ID No:	UN2489	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	THERMOSET PLASTICS INC
Cont1 Pkging Type:		***Shipper Street Name:***	5101 E 65TH ST.
Cont1 Const Mat:		***Shipper City:***	INDIANAPOLIS
Cont1 Head Type:		***Shipper State:***	IN
Cont1 Pkg Capacity:	3.75	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	321503364
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	TORRANCE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0

RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	15	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	10	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER NOTICED CARTON TURNED ONTO ITS SIDE AND FOUND MATERIAL LEAKING FROM THE INNER CONTAINERS. THE SUPERVISOR WAS NOTIFIED AND THE AREA ISOLATED. THE MATERAIL WAS IDENTIFED AND THE DAMAGED CARTON PLACED INTO A RECOVERY PAIL PER THE CONSIGNEE'S INSTRUCTIONS. ALL MATERIAL WAS FORWARDED TO CONSIGNEE AS INSTRUCTED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997071542	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-07-09	***Report Submit Src:***	Paper
Time of Incident:	1515	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	CHLOROFORM	***Transport Phase:***	Loading
Commodity Long Nm:	CHLOROFORM	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1888	***Mat Ship Approv No:***	

Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FISHER SCIENTIFIC CO
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	SUWANEE
Cont1 Head Type:		***Shipper State:***	GA
Cont1 Pkg Capacity:	15	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	405-938683
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LOS ANGELES
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:	394416		

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	

Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	PAIL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN TRAILER DOORS WERE OPENED FOR UNLOADING DAMPNESS WAS NOTICED ON THE FLOOR. THE HAZMAT TEAM WAS NOTIFIED AND THE AREA ISOLATED TO 75 FEET. CHEMTREC WAS CALLED AND AN MSDS OBTAINED. DUE TO THE EVAPORATION RATE OF THE MATERIAL, ALL PRODUCT EVAPORATED BEFORE CLEANUP WAS COMMENCED. THE REMAINDER OF THE SHIPMENT WAS FORWARDED TO THE CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO RD. ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993010368	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-12-27	***Report Submit Src:***	Paper
Time of Incident:	0130	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	4.1	***Mode Transport:***	Highway
Commodity Short Nm:	METALDEHYDE	***Transport Phase:***	Unloading
Commodity Long Nm:	METALDEHYDE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1332	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	LONZA INC
Cont1 Pkging Type:		***Shipper Street Name:***	20851 S SANTA FE
Cont1 Const Mat:		***Shipper City:***	LONG BEACH
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	828488467
Cont1 Pkg No:	132	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	RANDOLPH
C1 Pkg Dsign Pres.:	0	***Destination State:***	NEW JERSEY

C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	150	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN DOCKWORKER REMOVED ADJACENT FREIGHT, HE NOTICED A FORKLIFT BLADE MARK ON ONE CARTON. THE DAMAGED CARTON WAS REMOVED AND PLACED INTO A RECOVERY DRUM ALONG WITH ALL RESIDUE.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994020655	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-01-04	***Report Submit Src:***	Paper
Time of Incident:	0750	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	POTASSIUM NITRATE	***Transport Phase:***	Unloading
Commodity Long Nm:	POTASSIUM NITRATE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1486	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	303; 305	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured; Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 501	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Abrasion	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VAN WATERS & ROGERS
Cont1 Pkging Type:		***Shipper Street Name:***	2041 N MOSLEY
Cont1 Const Mat:		***Shipper City:***	WICHITA
Cont1 Head Type:		***Shipper State:***	KS
Cont1 Pkg Capacity:	101	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	569 795257
Cont1 Pkg No:	3	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LOS ANGELES
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No

Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	15	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	115	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BAG PAPER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BAG PPR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Paper bag (cont1 for solid materials)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: UPON OPENING THE TRAILER DOOR FOR UNLOADING, DOCKWORKER NOTICED BAG BURST OPEN, ALLOWING MATERIAL TO SPILL. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. THE EMERGENCY RESPONSE NUMBER WAS CALLED AND THE MSDS OBTAINED FROM THE SHIPPER. ALL MATERIAL WAS RECOVERED AND FORWARDED TO DESTINATION AS REQUESTED. NO GROUND CONTAMINATION OCCURRED.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998020933	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-01-15	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	PHENOXY PESTICIDES, SOLI	***Transport Phase:***	Loading
Commodity Long Nm:	PHENOXY PESTICIDES, SOLID, TOXIC, N.O.S.	***Incident Occrrnce:***	
Trade Name:	HERBICIDE	***Mat Ship Approval?:***	No
ID No:	UN2765	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	132	***CR State:***	OH
What Failed Desc:	Liner	***CR Postal Code:***	44310
How Failed Code:	310	***CR Non US State:***	
How Failed Desc:	Ripped or Torn	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	PBI GORDON CORP

Cont1 Pkging Type:		***Shipper Street Name:***	JAYHAWK IND PARK
Cont1 Const Mat:		***Shipper City:***	CRESTLINE
Cont1 Head Type:		***Shipper State:***	KS
Cont1 Pkg Capacity:	22	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	548-975747
Cont1 Pkg No:	336	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	3	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LOS ANGELES
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	22
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	SLB
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	336
C1 Device Model:		***Cont2 Pkg No Failed:***	3
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	95	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER

Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: AN ODOR WAS DETECTED COMING ROM THE TRAILER AND THREE CARTONS WERE FOUND CRUSHED BY HEAVY TOPFREIGHT. THE TRAILER WAS ISOLATED AND AN MSDS OBTAINED FROM CHEMTREC. THE PRODUCT AND CLEANUP MATERIALS WERE PLACED INTO A PLASTIC RECOVERY DRUM FOR RETURN TO THE SHIPPER. THE REMAINDER OF THE SHIPMENT WILL BE FORWARDED TO DESTINATION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1992100664	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-09-24	***Report Submit Src:***	Paper
Time of Incident:	0415	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	POTASSIUM CYANIDE SOLUTI	***Transport Phase:***	Unloading
Commodity Long Nm:	POTASSIUM CYANIDE SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3413	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; ;	***CR State:***	OH
What Failed Desc:	Basic Material; ;	***CR Postal Code:***	44310
How Failed Code:	303; 310; 305	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured; Ripped or Torn; Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	511; 517; 511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped; Improper Preparation for Transportation; Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	KROHN IND INC
Cont1 Pkging Type:		***Shipper Street Name:***	303 VETERAN BLVD
Cont1 Const Mat:		***Shipper City:***	CARLSTADT
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	1.5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	190-924827
Cont1 Pkg No:	23	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	RIVERSIDE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.25
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	138
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	Yes	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	150	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	200	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE UNLOADING TRAILER, DOCKWORKER REMOVED ADJACENT FREIGHT AND CRATE FELL AND CRUSHED CARTON AND INNER CONTAINERS. SUPERVISOR WAS NOTIFIED AND THE AREA ISOLATED. THE TRAILER WAS MOVED TO A REMOVE AREA OF THE DOCK AND MATERIAL IDENTIFIED. THE EMERGENCY RESPONSE GUIDEBOOK CONSULTED AND CHEMTRELL NOTIFIED. SHIPPER WAS CONTACTED AND THE SPILLAGE RECOUPED AS INSTRUCTED. ABSORBENT WAS PLACED ON THE TRAILER FLOOR AND ALL CONTAMINATED MATERIALS WERE RETURNED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1991090645	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1991-09-03	***Report Submit Src:***	Paper
Time of Incident:	0900	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	Unloading

Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	ALIPHATIC AMINE	***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	6.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	CIBA-GEIGY CORP
Cont1 Pkging Type:		***Shipper Street Name:***	N CRAFT HWY
Cont1 Const Mat:		***Shipper City:***	MOBILE
Cont1 Head Type:		***Shipper State:***	AL
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	429-560978
Cont1 Pkg No:	13	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	CHATSWORTH
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	30	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	

Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	130	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE WORKING INSIDE TRAILER, FORKLIFT OPERATOR SPEARED ONE DUM. THE DRUM WAS RECOUPED INTO A RECOVERY DRUM AND THE LIQUID WAS COVERED WITH ABSORBENT MATERIAL. ALL SPILLED MATERIAL WAS CONTAINED WITHIN THE TRAILER.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997110745	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-09-22	***Report Submit Src:***	Paper
Time of Incident:	1556	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES, N	***Transport Phase:***	Unloading
Commodity Long Nm:	PETROLEUM DISTILLATES, N.O.S. OR PETROLEUM PRODUCTS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1268	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	COLEMAN CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	WICHITA
Cont1 Head Type:		***Shipper State:***	KS
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	569-965395
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US

C1 Test Const Mat:		***Destination City:***	FONTANA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	185	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING UNLOADING A FORKLIFT PUNCTURED A CARTON CAUSING A LEAK. THE AREA WAS SECURED. CHEMTREC AND SHIPPER WERE NOTIFIED AND MSDS REQUESTED. ABSORBENT MATERIALS WERE UTILIZED FOR CONTAINMENT OF SPILL AND CLEANUP. AFFECTED MATERIALS WERE PLACED INTO A RECOVERY DRUM TO BE HELD FOR DISPOSAL. BALANCE OF SHIPMENT WAS FORWARDED TO CONSIGNEE.

Recommend Actions Taken:

Site:

HMIRS

ADELANTO RD ADELANTO CA

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997040075	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-03-05	***Report Submit Src:***	Paper
Time of Incident:	0100	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	TETRACHLOROETHYLENE	***Transport Phase:***	Unloading
Commodity Long Nm:	TETRACHLOROETHYLENE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1897	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; 103	***CR State:***	OH
What Failed Desc:	Basic Material; Basic Material	***CR Postal Code:***	44310
How Failed Code:	303;	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VPK OQDEGEM
Cont1 Pkging Type:		***Shipper Street Name:***	755 ROUTE 202
Cont1 Const Mat:		***Shipper City:***	SUMMERFIELD
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	5.625	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	129109490
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	TORRANCE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	5.625
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No

Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: A WET CARDBOARD CARTON WAS DISCOVERED DURING UNLOADING PROCESS. THE AREA WAS ISOLATED AND PRODUCT IDENTIFIED. CLEANUP MATERIAL AND DAMAGED BOX WERE PLACED IN A RECOVERY DRUM AND IS BEING HELD PENDING DISPOSITION FROM SHIPPER.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998010371	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-12-30	***Report Submit Src:***	Paper
Time of Incident:	1740	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	METHANOL	***Transport Phase:***	Unloading
Commodity Long Nm:	METHANOL	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1230	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US

Ident. Markings:		***Shipper Name:***	BAYER CORPORATION
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	ONTARIO
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	826862729
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	HOUSTON
C1 Pkg Dsign Pres.:	0	***Destination State:***	TEXAS
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	3
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	210	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	285	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No

Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING UNLOADING, ONE CARTON WAS PUNCTURED BY A FORKLIFT BLADE. THE AREA WAS ISOLATED AND CHEMTREC CONTACTED. AN MSDS WAS RECEIVED AND TERMINAL PERSONNEL PERFORMED THE CLEANUP USING ONE POUND OF ABSORBENT MATERIAL. ALL DAMAGED PRODUCT WAS SEALED INSIDE A DRUM AND HELD FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993060176	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-05-19	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	TRICHLOROETHYLENE	***Transport Phase:***	Loading
Commodity Long Nm:	TRICHLOROETHYLENE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1710	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	;	***CR State:***	OH
What Failed Desc:	;	***CR Postal Code:***	44310
How Failed Code:	309; 305	***CR Non US State:***	
How Failed Desc:	Punctured; Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	;	***CR Hazmat Reg ID:***	
Failure Cause Desc:	;	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	PANG RUBBER
Cont1 Pkging Type:		***Shipper Street Name:***	1650 LAND ST
Cont1 Const Mat:		***Shipper City:***	LOS ANGELES
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	2.5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	821-514240
Cont1 Pkg No:	10	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	ALBERT LEA
C1 Pkg Dsign Pres.:	0	***Destination State:***	MINNESOTA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.25
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	200
C1 Device Model:		***Cont2 Pkg No Failed:***	20
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	125	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHEN DOCKWORKER MOVED SKID, TWO LOOSE CARTONS FELL TO THE FLOOR AND WERE DAMAGED. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. THE DAMAGED CARTONS WERE SEALED INSIDE A RECOVERY DRUM FOR DISPOSITION.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998020934	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-01-15	***Report Submit Src:***	Paper
Time of Incident:	1535	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	DICHLOROMETHANE	***Transport Phase:***	Unloading
Commodity Long Nm:	DICHLOROMETHANE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1593	***Mat Ship Approv No:***	

Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	IPS CORP
Cont1 Pkging Type:		***Shipper Street Name:***	
Cont1 Const Mat:		***Shipper City:***	COMPTON
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	828-010186
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	BATON ROUGE
C1 Pkg Dsign Pres.:	0	***Destination State:***	LOUISIANA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	75	***Contact Postal:***	

Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	100	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THREE SHIPMENTS WERE LOADED ON TOP OF OTHER SKIDS AND FELL WHEN THE LOAD SHIFTED, CAUSING ONE CONTAINER TO BE CRUSHED. THE DAMAGED CONTAINER WAS ISOLATED AND CHEMTREC CONTACTED. TERMINAL HAZMAT TEAM PERFORMED CLEANUP AND RECOVERED ALL CONTAMINATED MATERIALS. THE DRUM WILL BE HELD FOR DISPOSITION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996120118	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1996-09-10	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	TRICHLOROETHYLENE	***Transport Phase:***	Unloading
Commodity Long Nm:	TRICHLOROETHYLENE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1710	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.0625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	TRUFLEX PANG
Cont1 Pkging Type:		***Shipper Street Name:***	NANCY STREET
Cont1 Const Mat:		***Shipper City:***	LOS ANGELES
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	821658982
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	
C1 Pkg Dsign Pres.:	0	***Destination State:***	
C1 Dsign Press UOM:		***Destination Postal:***	

C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: CARTON WAS RECEIVED PARTIALLY CRUSHED AT TERMINAL. CAN WITHIN CARTON WAS DENTED AND SLIGHTLY LEAKING. CAN WAS RECOOPED AND RETURNED TO SHIPPER. REMAINDER OF FREIGHT WAS FORWARDED TO CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993040160	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-03-26	***Report Submit Src:***	Paper
Time of Incident:	1510	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	POTASSIUM NITRATE	***Transport Phase:***	Unloading
Commodity Long Nm:	POTASSIUM NITRATE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1486	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	40	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	309; 310	***CR Non US State:***	
How Failed Desc:	Punctured; Ripped or Torn	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	BATTELLE & RENWICK
Cont1 Pkging Type:		***Shipper Street Name:***	258 JELLIF AVE
Cont1 Const Mat:		***Shipper City:***	NEWARK
Cont1 Head Type:		***Shipper State:***	NJ
Cont1 Pkg Capacity:	40	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	111-194370
Cont1 Pkg No:	40	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	GARDENA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No

No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	120	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BAG PAPER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BAG PPR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Paper bag (cont1 for solid materials)
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: UPON UNLOADING TRAILER, IT WAS NOTICED TWO BAGS HAD HOLES IN THE CORNER AND CHEMICAL, MATERIAL WAS SPILLING INTO THE TRAILER. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. ALL SPILLAGE WAS SWEPT UP AS INSTRUCTED AND THE DAMAGED BAGS WERE SEALED INSIDE A RECOVERY DRUM ALONG WITH THE CONTAMINATED MATERIAL.

Recommend Actions Taken:

Site:

ADELANTO RD. ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993010375	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1992-12-15	***Report Submit Src:***	Paper
Time of Incident:	0100	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	***Transport Phase:***	Unloading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1219	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	2	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	CHRISTOPHER ASSOCIATES INC
Cont1 Pkging Type:		***Shipper Street Name:***	2601 S. OAK ST
Cont1 Const Mat:		***Shipper City:***	SANTA ANA
Cont1 Head Type:		***Shipper State:***	CA

Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	825393877
Cont1 Pkg No:	20	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	ANDERSON
C1 Pkg Dsign Pres.:	0	***Destination State:***	SOUTH CAROLINA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	10	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	20	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No

Haz Non Hosp Resp: 0 ***Undeclared Shipment:*** No
Description of Events: ONE DRUM WAS APPARENTLY PUNCTURED BY THE FORKLIFT BLADE DURING LOADING AND LEAKED MATERAIL ENROUTE. DOCKWORKER ISOLATED THE AREA AND NOTIFIED SUPERVISOR. CHEMTREC WAS CONTACTED AND ALL SPILLAGE CLEANED AS INSTRUCTED.
Recommend Actions Taken:

Site:
ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993060905	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-06-06	***Report Submit Src:***	Paper
Time of Incident:	0400	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ALCOHOLS, N.O.S.	***Transport Phase:***	Loading
Commodity Long Nm:	ALCOHOLS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	ETHANOL	***Mat Ship Approval?:***	No
ID No:	UN1987	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	M D T CHEMICAL CORP
Cont1 Pkging Type:		***Shipper Street Name:***	19645 RANCHO WAY
Cont1 Const Mat:		***Shipper City:***	RANCH
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831-858755
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FORT WAYNE
C1 Pkg Dsign Pres.:	0	***Destination State:***	INDIANA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No

RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	0	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	10	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED ONE SKID HAD APPARENTLY BEEN PUSHED INTO ANOTHER DURING LOADING, CAUSING A SPILL. THE AREA WAS ISOLATED AND ABSORBANT WAS PLACED ON THE MATERIAL. THE DAMAGED CARTON WAS PLACED INSIDE A RECOVERY DRUM.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998020932	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1998-01-29	***Report Submit Src:***	Paper
Time of Incident:	2125	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	***Incident Occrrnce:***	
Trade Name:	SODIUM HYDROXIDE	***Mat Ship Approval?:***	No
ID No:	UN3266	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC

Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	106	***CR State:***	OH
What Failed Desc:	Bottom Outlet Valve	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	526	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Loose Closure, Component, or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	NALCO CHEMICAL CO
Cont1 Pkging Type:		***Shipper Street Name:***	2111 E DOMINGAS
Cont1 Const Mat:		***Shipper City:***	CARSON
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	10	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	828-335245
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	DENVER
C1 Pkg Dsign Pres.:	0	***Destination State:***	COLORADO
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	185	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No

Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: ONE 10 GALLON ALUMINUM DRUM WAS FOUND ON THE DOCK LEAKING FROM THE BOTTOM. THE AREA WAS ISOLATED AND CHEMTREC WAS NOTIFIED. AN MSDS WAS OBTAINED AND AN EMERGENCY COORDINATOR CONTACTED. ABSORBENT WAS USED BY TERMINAL PERSONNEL TO CLEAN THE SPILLAGE AND ALL CONTAMINATED MATERIALS WERE SEALED INSIDE A DRUM FOR DISPOSAL. THE DAMAGED DRUM WAS RETURNED TO THE SHIPPER AS INSTRUCTED.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997010821	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-01-08	***Report Submit Src:***	Paper
Time of Incident:	1000	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	PETROLEUM DISTILLATES, N	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	PETROLEUM DISTILLATES, N.O.S. OR PETROLEUM PRODUCTS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1268	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	3	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103;	***CR State:***	OH
What Failed Desc:	Basic Material;	***CR Postal Code:***	44310
How Failed Code:	309; 309	***CR Non US State:***	
How Failed Desc:	Punctured; Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	;	***CR Hazmat Reg ID:***	
Failure Cause Desc:	;	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	BRUNSWICK BWLING & BLRDS
Cont1 Pkging Type:		***Shipper Street Name:***	525 W LAKETON
Cont1 Const Mat:		***Shipper City:***	MUSKEGON
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	273608275
Cont1 Pkg No:	96	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LONG BEACH
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US

C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	2
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	192
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	200	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	500	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	700	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: SPILL WAS DISCOVERED WHILE UNLOADING FREIGHT. SPILL WAS CONTAINED AND ABSORBED BY PACKAGING. THE AREA WAS ISOLATED AND PRODUCT IDENTIFIED. HAZMAT TEAM CLEANED UP SPILL AND PLACED DAMAGED FREIGHT INTO A RECOVERY DRUM. DRUM IS BEING HELD FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993081174	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-07-26	***Report Submit Src:***	Paper
Time of Incident:	2015	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	DIPHENYLMETHANE-4,4DIISO	***Transport Phase:***	Unloading
Commodity Long Nm:	DIPHENYLMETHANE-4,4DIISOCYANATE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2489	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	THERMOSET PLASTICS INC
Cont1 Pkging Type:		***Shipper Street Name:***	5101 EAST 65TH
Cont1 Const Mat:		***Shipper City:***	INDIANAPOLIS
Cont1 Head Type:		***Shipper State:***	IN
Cont1 Pkg Capacity:	0.625	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	321-503456
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	IRWINDALE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.625
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	2
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No

Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	20	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	60	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	80	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: PAIL WAS APPARENTLY COMPRESSED IN TRANSIT, LEAKING MATERIAL ONTO THE FLOOR OF THE TRAILER. THE AREA WAS ISOLATED AND CHEMTREC CALLED. THE SHIPPER WAS CONTACTED AND ADVISED CLEANUP PROCEDURES USING ABSORBENT MATERIAL AND WASHING THE AREA WITH WATER. CONSIGNEE WAS CONTACTED AND RECEIVED FREIGHT.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1990030692	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-03-10	***Report Submit Src:***	Paper
Time of Incident:	1648	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ALCOHOLS, N.O.S.	***Transport Phase:***	Unloading
Commodity Long Nm:	ALCOHOLS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1987	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; 103	***CR State:***	OH
What Failed Desc:	Basic Material; Basic Material	***CR Postal Code:***	44310
How Failed Code:	309;	***CR Non US State:***	
How Failed Desc:	Punctured;	***CR Fed DOT ID:***	71821
Failure Cause Code:	517; 516	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation; Impact with Sharp or Protruding Object (e.g., nails)	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	M D T CHEMICAL CORP
Cont1 Pkging Type:		***Shipper Street Name:***	19645 RANCHO WAY
Cont1 Const Mat:		***Shipper City:***	RANCHO DOMINGUEZ
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	4	***Shipper Postal:***	90220

C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831 547369 7
Cont1 Pkg No:	26	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	DALLAS
C1 Pkg Dsign Pres.:	0	***Destination State:***	TEXAS
C1 Dsign Press UOM:		***Destination Postal:***	75204
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	104
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	20	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	45	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCK WORKER DISCOVERED ONE WET CARTON DURING UNLOADING. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. DAMAGED CARTON WAS RECOUPED INTO A RECOVERY PAIL AND THE NAIL WAS DISCOVERED PROTRUDING FROM THE TRAILER FLOOR. THE REMAINDER OF THE SHIPMENT WAS FORWARDED TO DESTINATION.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997120152	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-10-25	***Report Submit Src:***	Paper
Time of Incident:	2030	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	2.3	***Mode Transport:***	Highway
Commodity Short Nm:	ETHYLENE OXIDE OR ETHYLE	***Transport Phase:***	Unloading
Commodity Long Nm:	ETHYLENE OXIDE OR ETHYLENE OXIDE WITH NITROGEN UP TO A TOTAL PRESSURE OF 1MPA (10 BAR) AT 50 DEGREES C	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1040	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Cylinder
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MINNESOTA MINING & MFG CO
Cont1 Pkging Type:		***Shipper Street Name:***	5151 E PHILADELPHIA
Cont1 Const Mat:		***Shipper City:***	ONTARIO
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	826-849946
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SPOKANE
C1 Pkg Dsign Pres.:	0	***Destination State:***	WASHINGTON
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	

RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	185	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	CYLINDER
Haz Hosp Old Form:	0	***HMIS Container Code:***	CYL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Cylinder, a pressure vessel for compressed gases
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: FREIGHT WAS DISCOVERED DAMAGED AND LEAKING. CONTENTS THAT HAD LEAKED HAD EVAPORATED PRIOR TO ARRIVAL. THE AREA WAS ISOLATED AND CHEMTREC NOTIFIED. DAMAGED PRODUCT WAS PLACED INTO A RECOVERY DRUM WHICH IS BEING HELD PENDING DISPOSITION.

Recommend Actions Taken:

Site:

143601 ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994051227	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-05-12	***Report Submit Src:***	Paper
Time of Incident:	0300	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	FLUOROSILICIC ACID	***Transport Phase:***	Unloading
Commodity Long Nm:	FLUOROSILICIC ACID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1778	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No

Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.015625	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	301	***CR Non US State:***	
How Failed Desc:	Abraded	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	VAN WATERS & ROGERS
Cont1 Pkging Type:		***Shipper Street Name:***	10889 BEKAY ST
Cont1 Const Mat:		***Shipper City:***	DALLAS
Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	526272744
Cont1 Pkg No:	8	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	PORTERVILLE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	

Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER REPORTED TO SUPERVISOR THAT MATERIAL HAD APPARENTLY LEAKED IN TRANSIT FROM THE BUNG OF THE DRUM. THE SPILLAGE WAS NEUTRALIZED AND CLEANED.

Recommend Actions Taken:

Site:

909 ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-2011100403	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	2011-09-21	***Report Submit Src:***	Paper
Time of Incident:	1700	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L	***Transport Phase:***	In Transit
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1263	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	REDDAWAY
Qty Released:	1	***CR Street Name:***	16277 SE 130TH AVE.
Unit of Measure:	Liquid - Gallon	***CR City:***	Clackamas
What Failed:	128	***CR State:***	OR
What Failed Desc:	Inner Packaging	***CR Postal Code:***	97015
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	62227
Failure Cause Code:	517	***CR Hazmat Reg ID:***	052909550094RT
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	EI DUPONT
Cont1 Pkging Type:	Box	***Shipper Street Name:***	11535 PRODUCTION DR
Cont1 Const Mat:	Fiberboard	***Shipper City:***	RENO
Cont1 Head Type:		***Shipper State:***	NV
Cont1 Pkg Capacity:	4	***Shipper Postal:***	89506
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	4	***Shipper Country:***	US
C1 Pkg Amt UOM:	LGA	***Shipper Waybill:***	5253910793
Cont1 Pkg No:	9	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:		***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	ADELANTO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	92301

C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	Can
C1 Head Thick UOM:		***Cont2 Const Mat:***	Metal (any type)
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	1
C1 Device Type:		***Cont2 Pkg Amt UOM:***	LGA
C1 Device Mnfctr:		***Cont2 Pkg No:***	36
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	Yes	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	STEVE SHINNERS
Damage > 500:	Yes	***Contact Title:***	SR MGR INDUSTRIAL SAFETY AND ENV
Material Loss:	200	***Contact Business:***	YRC INC
Carrier Damage:	0	***Contact Street:***	10990 ROE AVENUE
Property Damage:	0	***Contact City:***	OVERLAND PARK
Response Cost:	0	***Contact State:***	KS
Remediation Cost:	800	***Contact Postal:***	66211
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1000	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	Carrier
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: WHILE EN ROUTE TO THE CONSIGNEE, ONE BOX FELL AND RUPTURED. THE RELEASE WAS PROPERLY MANAGED. THE DAMAGED FREIGHT WAS PLACED INTO A LINED SALVAGE DRUM AND HELD PENDING DISPOSITION FROM THE SHIPPER.

Recommend Actions Taken: ALL FREIGHT MUST BE PROPERLY BLOCKED AND BRACED TO PREVENT MOVEMENT.

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1991100485	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1991-09-28	***Report Submit Src:***	Paper
Time of Incident:	0900	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROCHLORIC ACID, SOLUT	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	HYDROCHLORIC ACID, SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1789	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FISHER SCIENTIFIC CO
Cont1 Pkging Type:		***Shipper Street Name:***	2761 WALNUT
Cont1 Const Mat:		***Shipper City:***	TUSTIN
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	1.25	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	829-673440
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SWAINSBORO
C1 Pkg Dsign Pres.:	0	***Destination State:***	GEORGIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1.25
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	2
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	

Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	0	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: TWO CARTONS WERE SITTING ON THE DOCK WHEN ONE WAS APPRENTLY STRUCK, BREAKING THE INNER CONTAINER. DOCK WORKER NOTICED VAPOR COMING FROM THE AREA AND THE AREA WAS SECURED. CHEMTREC WAS CONTACTED AND ADVISED CALLING THE FIRE DEPARTMENT. A DISPOSAL CONTRACTOR WAS CALLED FOR CLEANUP AND ALL SPILLAGE WAS REMOVED.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1996010353	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-12-09	***Report Submit Src:***	Paper
Time of Incident:	1545	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CAUSTIC ALKALI LIQUIDS,	***Transport Phase:***	Unloading
Commodity Long Nm:	CAUSTIC ALKALI LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1719	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	50	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:	511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MAY CHEM CO
Cont1 Pkging Type:		***Shipper Street Name:***	5544 OARDALE ROAD
Cont1 Const Mat:		***Shipper City:***	SMYRNA
Cont1 Head Type:		***Shipper State:***	GA
Cont1 Pkg Capacity:	50	***Shipper Postal:***	

C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	411-725957
Cont1 Pkg No:	11	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	GARDEN GROVE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiber drum, cont1 for solids, cont2 for liquids
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: TOP DRUM COLLAPSED WHILE DOCKWORKER WAS ROLLING DRUM OFF OF PALLET. THE AREA WAS ISOLATED AND PRODUCT IDENTIFIED. CHEMTREC WAS CALLED AND THEY FAXED A COPY OF THE MSDS. CLEANUP AND RECOVERY WERE HANDLED ACCORDING TO EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994050358	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-03-09	***Report Submit Src:***	Paper
Time of Incident:	0930	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	STYRENE MONOMER, STABILI	***Transport Phase:***	Unloading
Commodity Long Nm:	STYRENE MONOMER, STABILIZED	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2055	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.5	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	44310
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	HEXCEL CORP
Cont1 Pkging Type:		***Shipper Street Name:***	20701 NORDHOFF
Cont1 Const Mat:		***Shipper City:***	CHATSWORTH
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	8.75	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	827103159
Cont1 Pkg No:	11	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	WASHINGTON
C1 Pkg Dsign Pres.:	0	***Destination State:***	NORTH CAROLINA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No

RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	75	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DRUM ATTACHMENT APPARENTLY PUNCTURED DRUM IN THE MIDDLE WHEN DOCKWORKER ATTEMPTED TO LOAD THE FREIGHT. THE AREA WAS ISOLATED AND THE MATERIAL IDENTIFIED. ABSORBENT MATERIAL WAS USED TO CONTAIN AND CLEAN THE RESIDUE OF THE SPILLAGE.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994010145	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-12-05	***Report Submit Src:***	Paper
Time of Incident:	1400	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL	***Transport Phase:***	Loading
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1170	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk

HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	RIMET
Cont1 Pkging Type:		***Shipper Street Name:***	16511 KNOTT ST
Cont1 Const Mat:		***Shipper City:***	LA MIRADA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	816-506597
Cont1 Pkg No:	20	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	PORTLAND
C1 Pkg Dsign Pres.:	0	***Destination State:***	OREGON
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	100	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	125	***Contact Country:***	US

Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER STRUCK DRUM WITH THE SIDE OF THE DRUM ATTACHMENT, CAUSING A SMALL HOLE IN THE SIDE OF THE DRUM AND ALLOWING MATERIAL TO RELEASE. THE DAMAGED DRUM WAS PLACED ON ITS SIDE TO PREVENT FURTHER SPILLAGE AND THEN SEALED INSIDE A RECOVERY DRUM. THE SHIPPER WAS NOTIFIED AND REQUESTED RETURN OF THE DRUM FOR INSPECTION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1998010381	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-12-10	***Report Submit Src:***	Paper
Time of Incident:	2025	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ISOPROPANOL OR ISOPROPYL	***Transport Phase:***	Loading
Commodity Long Nm:	ISOPROPANOL OR ISOPROPYL ALCOHOL	***Incident Occrrnce:***	
Trade Name:	2-PROPYL	***Mat Ship Approval?:***	No
ID No:	UN1219	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	4	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FISHER SCIENTIFIC CO
Cont1 Pkging Type:		***Shipper Street Name:***	4700 MOLINE ST
Cont1 Const Mat:		***Shipper City:***	DENVER
Cont1 Head Type:		***Shipper State:***	CO
Cont1 Pkg Capacity:	1	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	890335007
Cont1 Pkg No:	4	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	4	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SAN DIEGO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US

C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	175	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	200	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	CAN
Haz Hosp Old Form:	0	***HMIS Container Code:***	CAN MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal can, capacity 7 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DURING LOADING, CONTAINER WAS PUNCTURED BY FORKLIFT BLADE. THE AREA WAS ISOLATED AND CHEMTREC CONTACTED FOR AN MSDS. CLEANUP WAS PERFORMED BY TERMINAL HAZMAT TEAM AND ALL RESIDUE SEALED INSIDE A PLASTIC DRUM FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995020565	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-01-15	***Report Submit Src:***	Paper
Time of Incident:	1805	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.2	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANIC PEROXIDE TYPE E,	***Transport Phase:***	Unloading
Commodity Long Nm:	ORGANIC PEROXIDE TYPE E, LIQUID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3107	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.039063	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	305	***CR Non US State:***	
How Failed Desc:	Crushed	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	STERIS CORPORATION
Cont1 Pkging Type:		***Shipper Street Name:***	9450 PINENEEDLE
Cont1 Const Mat:		***Shipper City:***	MENTOR
Cont1 Head Type:		***Shipper State:***	OH
Cont1 Pkg Capacity:	0.1875	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	224-608614
Cont1 Pkg No:	4	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	KEALAKEKUA
C1 Pkg Dsign Pres.:	0	***Destination State:***	HAWAII
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.1875
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No

Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	15	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	25	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE CARTON WAS IMPROPERLY LOADED IN BETWEEN SKIDS AND WAS CRUSHED IN TRANSIT RESULTING IN A LEAK. THE AREA WAS ISOLATED AND CHEMTREC CONTACTED FOR INSTRUCTIONS. THE MATERIAL WAS PLACED IN A RECOVERY DRUM FOR DISPOSAL.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994120874	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-11-01	***Report Submit Src:***	Paper
Time of Incident:	1730	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	CALCIUM PEROXIDE	***Transport Phase:***	Unloading
Commodity Long Nm:	CALCIUM PEROXIDE	***Incident Occrrnce:***	
Trade Name:	CALCIUM PEROXIDE	***Mat Ship Approval?:***	No
ID No:	UN1457	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	15	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:	519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FMC CORP
Cont1 Pkging Type:		***Shipper Street Name:***	15453 GALE
Cont1 Const Mat:		***Shipper City:***	CITY OF INDUSTRY
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	112	***Shipper Postal:***	
C1 Capacity UOM:	SLB	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	815-101310

Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LITTLETON
C1 Pkg Dsign Pres.:	0	***Destination State:***	COLORADO
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	25	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	35	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiber drum, cont1 for solids, cont2 for liquids
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER DISCOVERED ADJACENT FREIGHT HAD APPARENTLY BEEN LOADED AGAINST FIBER DRUM AND HAD PUNCHED A SMALL HOLE IN THE LOWER SIDE OF THE DRUM DURING TRANSIT. THE AREA WAS ISOLATED, AND THE FREIGHT BILL SECURED. THE EMERGENCY RESPONSE GUIDEBOOK

WAS CONSULTED, AND THE DAMAGED CONTAINER PLACED IN A RECOVERY DRUM.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995060612	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-06-03	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROCHLORIC ACID, SOLUT	***Transport Phase:***	Unloading
Commodity Long Nm:	HYDROCHLORIC ACID, SOLUTION	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1789	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.03125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	109; 109;	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Closure (e. g., Cap, Top, or Plug);	***CR Postal Code:***	44310
How Failed Code:	; ;	***CR Non US State:***	
How Failed Desc:	; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	526; 517; 519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Loose Closure, Component, or Device; Improper Preparation for Transportation; Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	SPECTRUM CHEMICAL MFG
Cont1 Pkging Type:		***Shipper Street Name:***	149222 S SAN PEDRO STREET
Cont1 Const Mat:		***Shipper City:***	GARDENA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	4	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	831-203652
Cont1 Pkg No:	5	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	PORTLAND
C1 Pkg Dsign Pres.:	0	***Destination State:***	OREGON
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	1
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	20
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No

RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	5	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	110	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	115	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: A SKID TIPPED OVER IN TRANSIT CAUSING A CAP ON A BOTTLE TO LOOSEN AND LEAK A SMALL AMOUNT OF MATERIAL. THE DOCK WORKER DISCOVERED THE LEAK WHILE UNLOADING THE TRAILER AND ISOLATED THE AREA. THE MATERIAL WAS IDENTIFIED AND CLEAN UP AND RECOVERY WAS HANDLED PER EMERGENCY RESPONSE GUIDELINES.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1997030169	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1997-01-22	***Report Submit Src:***	Paper
Time of Incident:	1225	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	FLAMMABLE LIQUIDS, CORRO	***Transport Phase:***	In Transit
Commodity Long Nm:	FLAMMABLE LIQUIDS, CORROSIVE, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN2924	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC

Qty Released:	0.125	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:		***CR State:***	OH
What Failed Desc:		***CR Postal Code:***	43310
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	71821
Failure Cause Code:	508	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Defective Component or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	DUCOA
Cont1 Pkging Type:		***Shipper Street Name:***	1ST STREET
Cont1 Const Mat:		***Shipper City:***	VERONA
Cont1 Head Type:		***Shipper State:***	MO
Cont1 Pkg Capacity:	55	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	547359353
Cont1 Pkg No:	45	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA FE SPRINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	15	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	40	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	55	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No

Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE DOCKWORKER DISCOVERED A LEAKING DRUM DURING UNLOADING PROCESS. THE PLUG ON TOP OF THE DRUM WAS NOT COVERED TIGHTLY. THE SHIPPER WAS CONTACTED, MSDS OBTAINED AND THE SPILL WAS CLEANED UP ACCORDING TO EMERGENCY RESPONSE GUIDELINES. THE DRUM WAS FORWARDED ON TO DESTINATION.

Recommend Actions Taken:

Site:

ADELANTO ROAD ADELANTO CA

HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1994061431	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1994-06-08	***Report Submit Src:***	Paper
Time of Incident:	0200	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	6.1	***Mode Transport:***	Highway
Commodity Short Nm:	ORGANOPHOSPHORUS PESTICI	***Transport Phase:***	In Transit
Commodity Long Nm:	ORGANOPHOSPHORUS PESTICIDES, LIQUID, TOXIC	***Incident Occrrnce:***	
Trade Name:	DICHLORVOS	***Mat Ship Approval?:***	No
ID No:	UN3018	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:		***CR City:***	AKRON
What Failed:	103	***CR State:***	OH
What Failed Desc:	Basic Material	***CR Postal Code:***	44310
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	71821
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FERMENTA
Cont1 Pkging Type:		***Shipper Street Name:***	225 IND PARK
Cont1 Const Mat:		***Shipper City:***	SULLIVAN
Cont1 Head Type:		***Shipper State:***	MO
Cont1 Pkg Capacity:	5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	341-957174
Cont1 Pkg No:	2	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FRESNO
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	

C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	Yes	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	500	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	100	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	600	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	PAIL MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: DOCKWORKER STRUCK TWO PAILS WITH FORKLIFT BLADES, PUNCTURING THEN AND ALLOWING MATERIAL TO RELEASE. THE AREA WAS ISOALTED AND THE SUPERVISOR NOTIFIED. THE SHIPPER WAS CALLED AN THE TRAILER MOVED TO A REMOTE AREA TO PREVENT INJURIES. ALL SPILLAGE WAS CLEANED AS INSTRUCTED AND THE DAMAGED CONTAINERS RECOVERED AND HELD FOR DISPOSITION. ALL PRODUCT REMAINED INSIDE THE TRAILER AND THERE WAS NO GROUND CONTAMINATION.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1995090225	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1995-07-21	***Report Submit Src:***	Paper
Time of Incident:		***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	***Transport Phase:***	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3149	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	0.25	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	AKRON
What Failed:	103; ;	***CR State:***	OH
What Failed Desc:	Basic Material; ;	***CR Postal Code:***	44310
How Failed Code:	305; ;	***CR Non US State:***	
How Failed Desc:	Crushed; ;	***CR Fed DOT ID:***	71821
Failure Cause Code:	511; 517; 519	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped; Improper Preparation for Transportation; Inadequate Blocking and Bracing	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MINNTECH/RENAL SYSTEMS
Cont1 Pkging Type:		***Shipper Street Name:***	14905 28TH AVE N
Cont1 Const Mat:		***Shipper City:***	MINNEAPOLIS
Cont1 Head Type:		***Shipper State:***	MN
Cont1 Pkg Capacity:	0	***Shipper Postal:***	
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	385142628
Cont1 Pkg No:	7	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	FOUNTAIN VALLEY
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	7
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0

Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	10	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	40	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: A CARTON HAD BEEN STACKED LOOSE ON SKID AND SHIFTED IN TRANSIT. IT FELL BETWEEN SKIDS AND BECAME CRUSHED AND LEAKED MATERIAL. THE DOCK WORKER DETECTED THE ODOR WHEN THE TRAILER WAS OPENED FOR UNLOADING AND ISOLATED THE AREA. THE MATERIAL WAS IDENTIFIED AND THE SHIPPER CONTACTED FOR CLEAN UP AND RECOVERY INSTRUCTIONS. THE DAMAGED CARTON WAS PLACED IN A RECOVERY DRUM AND RETURNED TO THE SHIPPER. THE REMAINDER WAS DELIVERED TO THE CONSIGNEE.

Recommend Actions Taken:

Site:

ADELANTO RD ADELANTO CA HMIRS

Incident County: SAN BERNARDINO

HMIR Historical Reports

Report No:	I-1993060904	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1993-05-26	***Report Submit Src:***	Paper
Time of Incident:	0001	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CAUSTIC ALKALI LIQUIDS,	***Transport Phase:***	Unloading
Commodity Long Nm:	CAUSTIC ALKALI LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	DIETHYLENETRIAMINE	***Mat Ship Approval?:***	No
ID No:	UN1719	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY EXPRESS INC
Qty Released:	1	***CR Street Name:***	1077 GORGE BLVD
Unit of Measure:	Solid - Pound	***CR City:***	AKRON
What Failed:	109	***CR State:***	OH
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	***CR Postal Code:***	44310

How Failed Code:	304	***CR Non US State:***	
How Failed Desc:	Cracked	***CR Fed DOT ID:***	71821
Failure Cause Code:	517	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Improper Preparation for Transportation	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	GOUGEON BROTHERS INC
Cont1 Pkging Type:		***Shipper Street Name:***	100 PATTERSON ST.
Cont1 Const Mat:		***Shipper City:***	BAY CITY
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	0.5	***Shipper Postal:***	
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	263-275028
Cont1 Pkg No:	9	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	LOS ANGELES
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.5
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	9
C1 Device Model:		***Cont2 Pkg No Failed:***	2
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	SUSAN CAMARA
Damage > 500:	No	***Contact Title:***	HAZMAT SPECIALIST
Material Loss:	25	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	50	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	75	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No

Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	BOX FBR
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box or carton
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: THE TOP OF ONE CAN APPARENTLY BROKE OPEN WHEN THE SKID SHIFTED IN TRANSIT, FALLING TO THE TRAILER FLOOR. THE SPILLED MATERIAL WAS ISOLATED AND IDENTIFIED. THE EMERGENGY RESPONSE GUIDEBOOK WAS CONSULTED AND CHEMTREC CALLED. ALL SPILLAGE WAS CLEANED AS INSTRUCTED.

Recommend Actions Taken:

Site: ***CALIFORNIA SILICA PRODUCTS***
Highway 395 & Rancho Road, go East on Rancho Road to Adelanto Road go South, to Rancho Road (again, road jogs) go East to 12808 Rancho Road. Victorville CA

MINES

Mine ID:	0405847	***Miles from Office:***	50
Status Code:	4	***SIC:***	144201
Mine Status:	Permanently Abandoned	***Primary SIC:***	Sand, Common
Status Date:	20230106	***Primary SIC CD 1:***	1442
Operation Class:	2 - Non-coal mining	***Primary SIC CD SFX:***	01
Company Type:	Other	***Primary Canvass:***	SandAndGravel
Assess Ctrl No:	000546977	***Primary Canvass CD:***	5
Current Mine Type:	Surface	***Secondary SIC:***	
Currnt Mine Status:	Abandoned	***Secondary SIC 1:***	000000
Current Status Dt:	01/06/2023	***Secondary SIC 2:***	000000
Curr Controller ID:	0105135	***Secondary SIC 3:***	000000
Curr Cont Begin Dt:	05/23/2012	***Secondary SIC 4:***	000000
Curr Operator ID:	0123751	***Secondary SIC 5:***	000000
Coal Metal Ind:	M	***Secondary SIC CD:***	
Mine Gas Ctgry CD:		***Secondary SIC CD 1:***	
Miners Rep Ind:	No	***Sec SIC CD Sfx:***	
Mines Prim SIC CD:	144201	***Sec Canvass CD:***	
Mines State:	CA	***Secondary Canvass:***	
No Employees:		***Primary SIC CD:***	Sand, Common
No Non-Prod Pits:		***Country:***	USA
No Producing Pits:		***Province:***	
No Tailing Ponds:	0	***Postal CD:***	
No of Pits:	000	***State Abbrev:***	CA
No of Plants:	0	***County Code:***	071
No of Shops:	0	***State Code:***	06
Current 103I:	Never Had 103I Status	***District:***	M7
Current 103I Dt:		***BOM State CD:***	04
Portable Operation:	No	***FIPS Cnty CD:***	071
Portble FIPS St CD:		***FIPS Cnty Nm:***	San Bernardino
Days Per Week:	0	***Cong Dist CD:***	
Hours Per Shift:		***Contact Title:***	Admin
Prod Shift Per Day:		***FIPS State CD:***	06
Maint Shift PerDay:		***Lat Deg:***	34
Part48 Training:	Yes	***Lat Min:***	33
Avg Mine Height:		***Lat Sec:***	29
Methane Liberation:		***Long Deg:***	117
Multiple Pits:	No	***Long Min:***	23
Safety Committ Ind:	No	***Long Sec:***	02
Office CD:	M7831	***Latitude:***	34.558333
Office Name:	San Bernardino CA Field Office	***Longitude:***	-117.383889

Entity Name: CALIFORNIA SILICA PRODUCTS
Current Mine Name: California Silica Products
Curr Controller Name: Randall Humphreys; Robert Humphreys
Curr Operator Name: Western States Wholesale
Status Description: The mine has been permanently shut down.
Pillar Recovery Used: No
Highwall Miner Used: No
Directions to Mine: Highway 395 & Rancho Road, go East on Rancho Road to Adelanto Road go South, to Rancho Road (again, road jogs) go East to 12808 Rancho Road.
Street: 1420 S. Bon View Avenue
City: Ontario

Po Box:
State Abbr: CA
State: California
Zip Code: 91761
Data Source: Master Index File;MINES Data Set

Violation Details

Event No: 6595256
Initial Viol No:
Replaced by Ord No:
Controller ID: 0105135
Contractor ID:
Violation No: 8697699
Violator ID: 0123751
Docket No:
Docket Stat Cd:
Mine Type: Surface
Likelihood: Unlikely
Amount Due: 308
Amount Paid: 308
Asmt Generated Ind: No
Asses Case Stat Cd: Closed
Bill Print Dt: 04/15/2014
Cal Qtr: 1
Cal Yr: 2014
Cit Ord Safe: Citation
Coal Metal Ind: M
Inj Illness: Fatal
No Affected: 1
Negligence: ModNegligence
Written Notice:
Enforcement Area:
Special Assess: No
Primary or Mill: Primary
Right to Conf Dt:
Proposed Penalty: 308
Contested Ind: No
Contested Dt:
Final Ord Issue Dt: 05/18/2014
Fiscal Qtr: 2
Fiscal Yr: 2014
Violator Type CD: Operator
Viola Insp Day Cnt: 8
Violat Violatn Cnt: 14
Violation Issue Dt: 02/20/2014
Violatn Issue Time: 0837
Violation Occur Dt: 02/20/2014
Orig Term Due Dt: 02/21/2014
Orig Term Due Tm: 0900
Inspectn Begin Dt: 02/20/2014
Inspection End Dt: 02/20/2014
Last Action Cd: Paid
Last Action Dt: 05/18/2014
Latest Term Due Dt: 02/21/2014
Latest Term Due Tm: 0900
Termination Dt: 02/24/2014
Termination Time: 0905
Termination Type: Terminated
Vacate Dt:
Vacate Time:
Sig Sub: No
Part Section: 56.12032
Section of Act:
Section of Act 1: 104(a)
Section of Act 2:
Mine Name: California Silica Products
Controller Name: Randall Humphreys; Robert Humphreys
Violator Name: Western States Wholesale

Violation Details

Event No: 6668655
Initial Viol No:
Replaced by Ord No:
Controller ID: 0105135
Contractor ID:
Violation No: 8788599
Violator ID: 0123751
Docket No:
Docket Stat Cd:
Mine Type: Surface
Likelihood: Unlikely
Amount Due: 150
Amount Paid: 150
Asmt Generated Ind: No
Asses Case Stat Cd: Closed
Bill Print Dt: 06/14/2016
Cal Qtr: 2
Cal Yr: 2016
Cit Ord Safe: Citation
Coal Metal Ind: M
Inj Illness: LostDays
No Affected: 1
Negligence: ModNegligence
Written Notice:
Enforcement Area:
Special Assess: No
Contested Ind: No
Contested Dt:
Final Ord Issue Dt: 07/18/2016
Fiscal Qtr: 3
Fiscal Yr: 2016
Violator Type CD: Operator
Viola Insp Day Cnt: 5
Violat Violatn Cnt: 16
Violation Issue Dt: 04/27/2016
Violatn Issue Time: 1030
Violation Occur Dt: 04/27/2016
Orig Term Due Dt: 04/27/2016
Orig Term Due Tm: 1045
Inspectn Begin Dt: 04/27/2016
Inspection End Dt: 04/28/2016
Last Action Cd: Paid
Last Action Dt: 06/27/2016
Latest Term Due Dt: 04/27/2016
Latest Term Due Tm: 1045
Termination Dt: 04/27/2016
Termination Time: 1040
Termination Type: Terminated
Vacate Dt:
Vacate Time:
Sig Sub: No
Part Section: 56.12032

Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	150	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727336	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/30/2017
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788962	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	04/06/2017
Mine Type:	Surface	***Violatn Issue Time:***	0905
Likelihood:	Unlikely	***Violation Occur Dt:***	04/06/2017
Amount Due:	577	***Orig Term Due Dt:***	04/06/2017
Amount Paid:	577	***Orig Term Due Tm:***	0930
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/06/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/07/2017
Bill Print Dt:	05/16/2017	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	05/31/2017
Cal Yr:	2017	***Latest Term Due Dt:***	04/06/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0930
Coal Metal Ind:	M	***Termination Dt:***	04/06/2017
Inj Illness:	Fatal	***Termination Time:***	0955
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	577	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689114	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	1059
Likelihood:	Unlikely	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/19/2012
Inj Illness:	Permanent	***Termination Time:***	1104
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No

Special Assess:	No	***Part Section:***	56.12032
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500615	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019
Mine Type:	Surface	***Violatn Issue Time:***	1149
Likelihood:	Unlikely	***Violation Occur Dt:***	10/08/2019
Amount Due:	121	***Orig Term Due Dt:***	10/08/2019
Amount Paid:	121	***Orig Term Due Tm:***	1157
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/08/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1157
Coal Metal Ind:	M	***Termination Dt:***	10/08/2019
Inj Illness:	LostDays	***Termination Time:***	1153
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.11003
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/03/2021
Controller ID:		***Fiscal Qtr:***	1
Contractor ID:	B8135	***Fiscal Yr:***	2021
Violation No:	9375508	***Violator Type CD:***	Contractor
Violator ID:	B8135	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0900
Likelihood:	Unlikely	***Violation Occur Dt:***	12/29/2020
Amount Due:	202	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	202	***Orig Term Due Tm:***	0910
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/23/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	05/10/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0910
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	Fatal	***Termination Time:***	0910
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	

Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.18002(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	202	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:			
Violator Name:	BlastRite Services		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689105	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1106
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	243	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	243	***Orig Term Due Tm:***	1330
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1330
Coal Metal Ind:	M	***Termination Dt:***	07/19/2012
Inj Illness:	Fatal	***Termination Time:***	0826
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	243	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821165	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/16/2019
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432492	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	03/21/2019
Mine Type:	Surface	***Violatn Issue Time:***	1105
Likelihood:	Reasonably	***Violation Occur Dt:***	03/21/2019
Amount Due:	121	***Orig Term Due Dt:***	03/21/2019
Amount Paid:	121	***Orig Term Due Tm:***	1130
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	03/21/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	03/26/2019
Bill Print Dt:	05/14/2019	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	03/21/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1130
Coal Metal Ind:	M	***Termination Dt:***	03/21/2019
Inj Illness:	Permanent	***Termination Time:***	1120
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	

Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.15003
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607921	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1358
Likelihood:	Reasonably	***Violation Occur Dt:***	05/07/2013
Amount Due:	10106	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	10106	***Orig Term Due Tm:***	1600
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	04/21/2016
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1600
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Fatal	***Termination Time:***	0753
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	37416	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/28/2021
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2021
Violation No:	9375511	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	10
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	1010
Likelihood:	Reasonably	***Violation Occur Dt:***	12/29/2020
Amount Due:	856	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	856	***Orig Term Due Tm:***	1040
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/16/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	03/14/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1040
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	LostDays	***Termination Time:***	1015
No Affected:	1	***Termination Type:***	Terminated

Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	856	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689118	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	0958
Likelihood:	Reasonably	***Violation Occur Dt:***	07/24/2012
Amount Due:	807	***Orig Term Due Dt:***	07/24/2012
Amount Paid:	807	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/24/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/25/2012
Inj Illness:	Fatal	***Termination Time:***	0854
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	807	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727314	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/03/2017
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788922	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	12
Docket Stat Cd:		***Violation Issue Dt:***	11/15/2016
Mine Type:	Surface	***Violatn Issue Time:***	0946
Likelihood:	Reasonably	***Violation Occur Dt:***	11/15/2016
Amount Due:	848	***Orig Term Due Dt:***	11/15/2016
Amount Paid:	848	***Orig Term Due Tm:***	1046
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	11/15/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	11/16/2016
Bill Print Dt:	01/17/2017	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/31/2017
Cal Yr:	2016	***Latest Term Due Dt:***	11/15/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1046
Coal Metal Ind:	M	***Termination Dt:***	11/16/2016
Inj Illness:	LostDays	***Termination Time:***	0757

No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	848	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6871540	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/23/2020
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500788	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	05/19/2020
Mine Type:	Surface	***Violatn Issue Time:***	0902
Likelihood:	Unlikely	***Violation Occur Dt:***	05/19/2020
Amount Due:	123	***Orig Term Due Dt:***	05/20/2020
Amount Paid:	123	***Orig Term Due Tm:***	1122
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/19/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/20/2020
Bill Print Dt:	07/14/2020	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/09/2020
Cal Yr:	2020	***Latest Term Due Dt:***	05/20/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1122
Coal Metal Ind:	M	***Termination Dt:***	06/02/2020
Inj Illness:	Permanent	***Termination Time:***	1821
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	123	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2013
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607918	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1114
Likelihood:	Unlikely	***Violation Occur Dt:***	05/07/2013
Amount Due:	100	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	100	***Orig Term Due Tm:***	1500
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/10/2013
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1500
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013

Inj Illness:	Permanent	***Termination Time:***	0759
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(b)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689106	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1128
Likelihood:	Unlikely	***Violation Occur Dt:***	07/18/2012
Amount Due:	100	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	100	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	07/18/2012
Inj Illness:	Permanent	***Termination Time:***	1137
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500614	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019
Mine Type:	Surface	***Violatn Issue Time:***	1034
Likelihood:	Unlikely	***Violation Occur Dt:***	10/08/2019
Amount Due:	121	***Orig Term Due Dt:***	10/08/2019
Amount Paid:	121	***Orig Term Due Tm:***	1038
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/08/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1038

Coal Metal Ind:	M	***Termination Dt:***	10/08/2019
Inj Illness:	LostDays	***Termination Time:***	1037
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689116	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	0831
Likelihood:	Unlikely	***Violation Occur Dt:***	07/24/2012
Amount Due:	100	***Orig Term Due Dt:***	07/24/2012
Amount Paid:	100	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/24/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000
Coal Metal Ind:	M	***Termination Dt:***	07/24/2012
Inj Illness:	Fatal	***Termination Time:***	1409
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.13011
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689512	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	11/06/2012
Mine Type:	Surface	***Violatn Issue Time:***	1415
Likelihood:	Unlikely	***Violation Occur Dt:***	10/17/2012
Amount Due:	100	***Orig Term Due Dt:***	12/04/2012
Amount Paid:	100	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	05/20/2013

Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	05/29/2013
Inj Illness:	Permanent	***Termination Time:***	0957
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.5001(a)/.5005
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607917	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1008
Likelihood:	Reasonably	***Violation Occur Dt:***	05/07/2013
Amount Due:	22106	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	22106	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	11/25/2014
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Fatal	***Termination Time:***	1634
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	37416	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432552	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	0950
Likelihood:	Reasonably	***Violation Occur Dt:***	06/12/2019
Amount Due:	405	***Orig Term Due Dt:***	06/13/2019
Amount Paid:	405	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019
Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019

Cal Yr:	2019	***Latest Term Due Dt:***	06/13/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	06/13/2019
Inj Illness:	Fatal	***Termination Time:***	1030
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	405	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607923	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1420
Likelihood:	Reasonably	***Violation Occur Dt:***	05/07/2013
Amount Due:	2473	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	2473	***Orig Term Due Tm:***	1600
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	04/21/2016
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1600
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	LostDays	***Termination Time:***	1052
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	2473	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689101	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1015
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	108	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	108	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid

Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Permanent	***Termination Time:***	1447
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	108	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/03/2021
Controller ID:		***Fiscal Qtr:***	1
Contractor ID:	B8135	***Fiscal Yr:***	2021
Violation No:	9375506	***Violator Type CD:***	Contractor
Violator ID:	B8135	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0835
Likelihood:	NoLikelihood	***Violation Occur Dt:***	07/16/2020
Amount Due:	125	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	125	***Orig Term Due Tm:***	0836
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/23/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	05/10/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0836
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	NoLostDays	***Termination Time:***	0837
No Affected:	0	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	50.30(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:			
Violator Name:	BlastRite Services		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689103	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1040
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	243	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	243	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012

Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Fatal	***Termination Time:***	1356
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	243	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788494	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/28/2015
Mine Type:	Surface	***Violatn Issue Time:***	0930
Likelihood:	Reasonably	***Violation Occur Dt:***	10/28/2015
Amount Due:	425	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	425	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	LostDays	***Termination Time:***	0833
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	425	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781917	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/10/2014
Mine Type:	Surface	***Violatn Issue Time:***	1015
Likelihood:	Unlikely	***Violation Occur Dt:***	12/10/2014
Amount Due:	150	***Orig Term Due Dt:***	12/11/2014
Amount Paid:	150	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014

Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/11/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	12/18/2014
Inj Illness:	LostDays	***Termination Time:***	1009
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	150	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595285	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/20/2014
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781869	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	08/14/2014
Mine Type:	Surface	***Violatn Issue Time:***	1009
Likelihood:	Reasonably	***Violation Occur Dt:***	08/14/2014
Amount Due:	2473	***Orig Term Due Dt:***	08/14/2014
Amount Paid:	2473	***Orig Term Due Tm:***	1015
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	08/14/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	08/19/2014
Bill Print Dt:	09/16/2014	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	09/28/2014
Cal Yr:	2014	***Latest Term Due Dt:***	08/14/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1015
Coal Metal Ind:	M	***Termination Dt:***	08/14/2014
Inj Illness:	Fatal	***Termination Time:***	1012
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14112(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	2473	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/03/2021
Controller ID:		***Fiscal Qtr:***	1
Contractor ID:	B8135	***Fiscal Yr:***	2021
Violation No:	9375505	***Violator Type CD:***	Contractor
Violator ID:	B8135	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0830
Likelihood:	NoLikelihood	***Violation Occur Dt:***	04/16/2020
Amount Due:	125	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	125	***Orig Term Due Tm:***	0831

Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/23/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	05/10/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0831
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	NoLostDays	***Termination Time:***	0832
No Affected:	0	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	50.30(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:			
Violator Name:	BlastRite Services		

Violation Details

Event No:	6595256	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/18/2014
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8697700	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	14
Docket Stat Cd:		***Violation Issue Dt:***	02/20/2014
Mine Type:	Surface	***Violatn Issue Time:***	0845
Likelihood:	Unlikely	***Violation Occur Dt:***	02/20/2014
Amount Due:	308	***Orig Term Due Dt:***	02/21/2014
Amount Paid:	308	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	02/20/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	02/20/2014
Bill Print Dt:	04/15/2014	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/18/2014
Cal Yr:	2014	***Latest Term Due Dt:***	02/21/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	02/24/2014
Inj Illness:	Fatal	***Termination Time:***	0910
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	308	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689104	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1050
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	108	***Orig Term Due Dt:***	07/18/2012

Amount Paid:	108	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Permanent	***Termination Time:***	1357
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14109
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	108	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432553	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	1230
Likelihood:	Reasonably	***Violation Occur Dt:***	06/12/2019
Amount Due:	450	***Orig Term Due Dt:***	
Amount Paid:	450	***Orig Term Due Tm:***	
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019
Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	
Cit Ord Safe:	Order	***Latest Term Due Tm:***	
Coal Metal Ind:	M	***Termination Dt:***	06/13/2019
Inj Illness:	Fatal	***Termination Time:***	0800
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	46.11(b)(5)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(g)(1)
Proposed Penalty:	450	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781918	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/10/2014
Mine Type:	Surface	***Violatn Issue Time:***	1020
Likelihood:	Reasonably	***Violation Occur Dt:***	12/10/2014

Amount Due:	745	***Orig Term Due Dt:***	12/10/2014
Amount Paid:	745	***Orig Term Due Tm:***	1025
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/10/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1025
Coal Metal Ind:	M	***Termination Dt:***	12/18/2014
Inj Illness:	LostDays	***Termination Time:***	1013
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11002
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	745	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500617	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019
Mine Type:	Surface	***Violatn Issue Time:***	1221
Likelihood:	Reasonably	***Violation Occur Dt:***	10/08/2019
Amount Due:	405	***Orig Term Due Dt:***	10/08/2019
Amount Paid:	405	***Orig Term Due Tm:***	1444
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/08/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1444
Coal Metal Ind:	M	***Termination Dt:***	10/08/2019
Inj Illness:	LostDays	***Termination Time:***	1344
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	405	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788496	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/28/2015
Mine Type:	Surface	***Violatn Issue Time:***	0955

Likelihood:	Reasonably	***Violation Occur Dt:***	10/28/2015
Amount Due:	425	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	425	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	LostDays	***Termination Time:***	0837
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	425	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689513	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	11/06/2012
Mine Type:	Surface	***Violatn Issue Time:***	1430
Likelihood:	Unlikely	***Violation Occur Dt:***	10/17/2012
Amount Due:	100	***Orig Term Due Dt:***	12/04/2012
Amount Paid:	100	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	05/20/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	05/28/2013
Inj Illness:	Permanent	***Termination Time:***	1527
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.5001(a)/.5005
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500618	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019

Mine Type:	Surface	***Violatn Issue Time:***	1254
Likelihood:	Reasonably	***Violation Occur Dt:***	10/08/2019
Amount Due:	121	***Orig Term Due Dt:***	10/08/2019
Amount Paid:	121	***Orig Term Due Tm:***	1451
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/08/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1451
Coal Metal Ind:	M	***Termination Dt:***	10/08/2019
Inj Illness:	Permanent	***Termination Time:***	1436
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14101(a)(2)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500619	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019
Mine Type:	Surface	***Violatn Issue Time:***	1348
Likelihood:	Reasonably	***Violation Occur Dt:***	10/08/2019
Amount Due:	405	***Orig Term Due Dt:***	10/09/2019
Amount Paid:	405	***Orig Term Due Tm:***	1700
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/09/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1700
Coal Metal Ind:	M	***Termination Dt:***	10/10/2019
Inj Illness:	LostDays	***Termination Time:***	1023
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.18002(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	405	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506822	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9

Docket Stat Cd:		***Violation Issue Dt:***	10/26/2021
Mine Type:	Surface	***Violatn Issue Time:***	1308
Likelihood:	Unlikely	***Violation Occur Dt:***	10/26/2021
Amount Due:	125	***Orig Term Due Dt:***	10/26/2021
Amount Paid:	125	***Orig Term Due Tm:***	1400
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/26/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1400
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	Permanent	***Termination Time:***	0851
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12008
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607924	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	12
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/08/2013
Mine Type:	Surface	***Violatn Issue Time:***	0808
Likelihood:	Unlikely	***Violation Occur Dt:***	05/08/2013
Amount Due:	499	***Orig Term Due Dt:***	05/08/2013
Amount Paid:	499	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	04/21/2016
Cal Yr:	2013	***Latest Term Due Dt:***	05/08/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Fatal	***Termination Time:***	0830
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12016
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	499	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668655	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2016
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788597	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5

Docket No:		***Violat Violatn Cnt:***	16
Docket Stat Cd:		***Violation Issue Dt:***	04/27/2016
Mine Type:	Surface	***Violatn Issue Time:***	0900
Likelihood:	Unlikely	***Violation Occur Dt:***	04/27/2016
Amount Due:	499	***Orig Term Due Dt:***	04/27/2016
Amount Paid:	499	***Orig Term Due Tm:***	0915
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/27/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/28/2016
Bill Print Dt:	06/14/2016	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/27/2016
Cal Yr:	2016	***Latest Term Due Dt:***	04/27/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0915
Coal Metal Ind:	M	***Termination Dt:***	04/27/2016
Inj Illness:	Fatal	***Termination Time:***	0905
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4200(b)(2)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	499	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607920	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1352
Likelihood:	Unlikely	***Violation Occur Dt:***	05/07/2013
Amount Due:	745	***Orig Term Due Dt:***	05/08/2013
Amount Paid:	745	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	11/25/2014
Cal Yr:	2013	***Latest Term Due Dt:***	05/08/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Permanent	***Termination Time:***	0754
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12007
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	745	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595256	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/18/2014
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8697698	***Violator Type CD:***	Operator

Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	14
Docket Stat Cd:		***Violation Issue Dt:***	02/20/2014
Mine Type:	Surface	***Violatn Issue Time:***	0733
Likelihood:	Unlikely	***Violation Occur Dt:***	02/20/2014
Amount Due:	100	***Orig Term Due Dt:***	02/20/2014
Amount Paid:	100	***Orig Term Due Tm:***	0830
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	02/20/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	02/20/2014
Bill Print Dt:	04/15/2014	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/18/2014
Cal Yr:	2014	***Latest Term Due Dt:***	02/20/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0830
Coal Metal Ind:	M	***Termination Dt:***	02/20/2014
Inj Illness:	LostDays	***Termination Time:***	0745
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12008
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668655	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2016
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788596	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	16
Docket Stat Cd:		***Violation Issue Dt:***	04/27/2016
Mine Type:	Surface	***Violatn Issue Time:***	0845
Likelihood:	Unlikely	***Violation Occur Dt:***	04/27/2016
Amount Due:	224	***Orig Term Due Dt:***	04/27/2016
Amount Paid:	224	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/27/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/28/2016
Bill Print Dt:	06/14/2016	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/27/2016
Cal Yr:	2016	***Latest Term Due Dt:***	04/27/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	04/27/2016
Inj Illness:	Permanent	***Termination Time:***	0855
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	47.41(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	224	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018

Violation No:	8994970	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	10
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/17/2018
Mine Type:	Surface	***Violatn Issue Time:***	1322
Likelihood:	Unlikely	***Violation Occur Dt:***	01/17/2018
Amount Due:	118	***Orig Term Due Dt:***	01/17/2018
Amount Paid:	118	***Orig Term Due Tm:***	1340
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	01/17/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1340
Coal Metal Ind:	M	***Termination Dt:***	02/13/2018
Inj Illness:	LostDays	***Termination Time:***	0810
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.11001
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	118	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821379	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	12/15/2019
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500616	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/08/2019
Mine Type:	Surface	***Violatn Issue Time:***	1159
Likelihood:	Reasonably	***Violation Occur Dt:***	10/08/2019
Amount Due:	121	***Orig Term Due Dt:***	10/08/2019
Amount Paid:	121	***Orig Term Due Tm:***	1211
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/07/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/08/2019
Bill Print Dt:	11/12/2019	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	11/25/2019
Cal Yr:	2019	***Latest Term Due Dt:***	10/08/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1211
Coal Metal Ind:	M	***Termination Dt:***	10/08/2019
Inj Illness:	LostDays	***Termination Time:***	1201
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11003
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3

Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432550	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	0930
Likelihood:	Reasonably	***Violation Occur Dt:***	06/12/2019
Amount Due:	405	***Orig Term Due Dt:***	06/12/2019
Amount Paid:	405	***Orig Term Due Tm:***	0940
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019
Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	06/12/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0940
Coal Metal Ind:	M	***Termination Dt:***	06/12/2019
Inj Illness:	Fatal	***Termination Time:***	0935
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.4603(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	405	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689110	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	0838
Likelihood:	Unlikely	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	1030
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1030
Coal Metal Ind:	M	***Termination Dt:***	07/19/2012
Inj Illness:	Permanent	***Termination Time:***	1125
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727336	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/30/2017

Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788963	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	04/06/2017
Mine Type:	Surface	***Violatn Issue Time:***	0925
Likelihood:	Unlikely	***Violation Occur Dt:***	04/06/2017
Amount Due:	259	***Orig Term Due Dt:***	04/06/2017
Amount Paid:	259	***Orig Term Due Tm:***	0945
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/06/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/07/2017
Bill Print Dt:	05/16/2017	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	05/31/2017
Cal Yr:	2017	***Latest Term Due Dt:***	04/06/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0945
Coal Metal Ind:	M	***Termination Dt:***	04/06/2017
Inj Illness:	Fatal	***Termination Time:***	0940
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14100(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	259	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727336	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/30/2017
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788961	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	04/06/2017
Mine Type:	Surface	***Violatn Issue Time:***	0825
Likelihood:	Unlikely	***Violation Occur Dt:***	04/06/2017
Amount Due:	173	***Orig Term Due Dt:***	04/06/2017
Amount Paid:	173	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/06/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/07/2017
Bill Print Dt:	05/16/2017	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	05/31/2017
Cal Yr:	2017	***Latest Term Due Dt:***	04/06/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	04/06/2017
Inj Illness:	LostDays	***Termination Time:***	0940
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4203
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	173	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595285	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	

Replaced by Ord No:		***Final Ord Issue Dt:***	10/20/2014
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781868	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	08/14/2014
Mine Type:	Surface	***Violatn Issue Time:***	0915
Likelihood:	Unlikely	***Violation Occur Dt:***	08/14/2014
Amount Due:	224	***Orig Term Due Dt:***	08/14/2014
Amount Paid:	224	***Orig Term Due Tm:***	1130
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	08/14/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	08/19/2014
Bill Print Dt:	09/16/2014	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	09/28/2014
Cal Yr:	2014	***Latest Term Due Dt:***	08/14/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1130
Coal Metal Ind:	M	***Termination Dt:***	08/14/2014
Inj Illness:	Permanent	***Termination Time:***	1250
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	224	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788495	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/28/2015
Mine Type:	Surface	***Violatn Issue Time:***	0940
Likelihood:	Reasonably	***Violation Occur Dt:***	10/28/2015
Amount Due:	425	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	425	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	LostDays	***Termination Time:***	0835
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11001
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	425	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No

Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607916	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	0928
Likelihood:	Reasonably	***Violation Occur Dt:***	05/07/2013
Amount Due:	1111	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	1111	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/19/2014
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	05/07/2013
Inj Illness:	Permanent	***Termination Time:***	0938
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.12023
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	1111	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595256	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/18/2014
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781801	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	14
Docket Stat Cd:		***Violation Issue Dt:***	02/20/2014
Mine Type:	Surface	***Violatn Issue Time:***	0930
Likelihood:	Unlikely	***Violation Occur Dt:***	02/20/2014
Amount Due:	308	***Orig Term Due Dt:***	02/21/2014
Amount Paid:	308	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	02/20/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	02/20/2014
Bill Print Dt:	04/15/2014	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/18/2014
Cal Yr:	2014	***Latest Term Due Dt:***	02/21/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	02/24/2014
Inj Illness:	Fatal	***Termination Time:***	0914
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12008
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	308	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6871540	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/23/2020
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500789	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	05/19/2020
Mine Type:	Surface	***Violatn Issue Time:***	0903
Likelihood:	Reasonably	***Violation Occur Dt:***	05/19/2020
Amount Due:	846	***Orig Term Due Dt:***	05/20/2020
Amount Paid:	846	***Orig Term Due Tm:***	1128
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/19/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/20/2020
Bill Print Dt:	07/14/2020	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/09/2020
Cal Yr:	2020	***Latest Term Due Dt:***	05/20/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1128
Coal Metal Ind:	M	***Termination Dt:***	06/02/2020
Inj Illness:	LostDays	***Termination Time:***	1823
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	846	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727314	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/03/2017
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788923	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	12
Docket Stat Cd:		***Violation Issue Dt:***	11/15/2016
Mine Type:	Surface	***Violatn Issue Time:***	1121
Likelihood:	Reasonably	***Violation Occur Dt:***	11/15/2016
Amount Due:	1265	***Orig Term Due Dt:***	11/15/2016
Amount Paid:	1265	***Orig Term Due Tm:***	1221
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	11/15/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	11/16/2016
Bill Print Dt:	01/17/2017	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/31/2017
Cal Yr:	2016	***Latest Term Due Dt:***	11/15/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1221
Coal Metal Ind:	M	***Termination Dt:***	11/16/2016
Inj Illness:	Permanent	***Termination Time:***	0704
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20008(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	1265	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/28/2021
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2021
Violation No:	9375510	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	10
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0950
Likelihood:	Unlikely	***Violation Occur Dt:***	12/29/2020
Amount Due:	574	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	574	***Orig Term Due Tm:***	1020
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/16/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	03/14/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1020
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	Fatal	***Termination Time:***	1125
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	574	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018
Violation No:	8994974	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/23/2018
Mine Type:	Surface	***Violatn Issue Time:***	1355
Likelihood:	Unlikely	***Violation Occur Dt:***	01/23/2018
Amount Due:	118	***Orig Term Due Dt:***	07/23/2018
Amount Paid:	118	***Orig Term Due Tm:***	1600
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	07/23/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1600
Coal Metal Ind:	M	***Termination Dt:***	01/24/2018
Inj Illness:	LostDays	***Termination Time:***	1027
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(a)(1)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	118	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/03/2021
Controller ID:		***Fiscal Qtr:***	1
Contractor ID:	B8135	***Fiscal Yr:***	2021
Violation No:	9375507	***Violator Type CD:***	Contractor
Violator ID:	B8135	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0850
Likelihood:	Unlikely	***Violation Occur Dt:***	12/29/2020
Amount Due:	125	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	125	***Orig Term Due Tm:***	0920
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/23/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	05/10/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0920
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	Fatal	***Termination Time:***	0855
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4101
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:			
Violator Name:	BlastRite Services		

Violation Details

Event No:	6727566	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/28/2021
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2021
Violation No:	9375509	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	10
Docket Stat Cd:		***Violation Issue Dt:***	12/29/2020
Mine Type:	Surface	***Violatn Issue Time:***	0925
Likelihood:	Reasonably	***Violation Occur Dt:***	12/29/2020
Amount Due:	856	***Orig Term Due Dt:***	12/29/2020
Amount Paid:	856	***Orig Term Due Tm:***	0955
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/29/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/30/2020
Bill Print Dt:	02/16/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	03/14/2021
Cal Yr:	2020	***Latest Term Due Dt:***	12/29/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0955
Coal Metal Ind:	M	***Termination Dt:***	12/29/2020
Inj Illness:	LostDays	***Termination Time:***	1130
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	856	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018
Violation No:	8994971	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	10
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/17/2018
Mine Type:	Surface	***Violatn Issue Time:***	1340
Likelihood:	Reasonably	***Violation Occur Dt:***	01/17/2018
Amount Due:	363	***Orig Term Due Dt:***	01/18/2018
Amount Paid:	363	***Orig Term Due Tm:***	0700
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	01/18/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0700
Coal Metal Ind:	M	***Termination Dt:***	01/24/2018
Inj Illness:	Fatal	***Termination Time:***	1003
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	363	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689496	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012
Mine Type:	Surface	***Violatn Issue Time:***	0901
Likelihood:	Reasonably	***Violation Occur Dt:***	10/16/2012
Amount Due:	100	***Orig Term Due Dt:***	10/16/2012
Amount Paid:	100	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/16/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	10/17/2012
Inj Illness:	LostDays	***Termination Time:***	0800
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11001
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689102	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1036
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	100	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	100	***Orig Term Due Tm:***	1230
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1230
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	LostDays	***Termination Time:***	1355
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11002
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781920	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/11/2014
Mine Type:	Surface	***Violatn Issue Time:***	1240
Likelihood:	NoLikelihood	***Violation Occur Dt:***	12/11/2014
Amount Due:	138	***Orig Term Due Dt:***	12/11/2014
Amount Paid:	138	***Orig Term Due Tm:***	1245
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/11/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1245
Coal Metal Ind:	M	***Termination Dt:***	12/11/2014
Inj Illness:	NoLostDays	***Termination Time:***	1245
No Affected:	0	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	50.30(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	138	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		

Violator Name: Western States Wholesale

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788497	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/28/2015
Mine Type:	Surface	***Violatn Issue Time:***	1010
Likelihood:	Unlikely	***Violation Occur Dt:***	10/28/2015
Amount Due:	100	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	100	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	LostDays	***Termination Time:***	0840
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12018
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781915	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/10/2014
Mine Type:	Surface	***Violatn Issue Time:***	0831
Likelihood:	Unlikely	***Violation Occur Dt:***	12/10/2014
Amount Due:	224	***Orig Term Due Dt:***	12/10/2014
Amount Paid:	224	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/10/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	12/10/2014
Inj Illness:	Permanent	***Termination Time:***	0845
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	224	***Section of Act 2:***	
Mine Name:	California Silica Products		

Controller Name: Randall Humphreys; Robert Humphreys
Violator Name: Western States Wholesale

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689115	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	0819
Likelihood:	Unlikely	***Violation Occur Dt:***	07/24/2012
Amount Due:	100	***Orig Term Due Dt:***	07/24/2012
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/24/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/24/2012
Inj Illness:	Permanent	***Termination Time:***	1420
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(b)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	

Mine Name: California Silica Products
Controller Name: Randall Humphreys; Robert Humphreys
Violator Name: Western States Wholesale

Violation Details

Event No:	6595727	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/31/2015
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781955	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	23
Docket Stat Cd:		***Violation Issue Dt:***	05/06/2015
Mine Type:	Surface	***Violatn Issue Time:***	0830
Likelihood:	Reasonably	***Violation Occur Dt:***	05/06/2015
Amount Due:	687	***Orig Term Due Dt:***	05/06/2015
Amount Paid:	687	***Orig Term Due Tm:***	0835
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/06/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/07/2015
Bill Print Dt:	06/16/2015	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/30/2015
Cal Yr:	2015	***Latest Term Due Dt:***	05/06/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0835
Coal Metal Ind:	M	***Termination Dt:***	05/06/2015
Inj Illness:	LostDays	***Termination Time:***	0835
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.12032
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	687	***Section of Act 2:***	

Mine Name: California Silica Products
Controller Name: Randall Humphreys; Robert Humphreys
Violator Name: Western States Wholesale

Violation Details

Event No:	6595285	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/20/2014
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781867	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	08/14/2014
Mine Type:	Surface	***Violatn Issue Time:***	0901
Likelihood:	Unlikely	***Violation Occur Dt:***	08/14/2014
Amount Due:	150	***Orig Term Due Dt:***	08/14/2014
Amount Paid:	150	***Orig Term Due Tm:***	0930
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	08/14/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	08/19/2014
Bill Print Dt:	09/16/2014	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	09/28/2014
Cal Yr:	2014	***Latest Term Due Dt:***	08/14/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0930
Coal Metal Ind:	M	***Termination Dt:***	08/14/2014
Inj Illness:	LostDays	***Termination Time:***	0907
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	150	***Section of Act 2:***	

Mine Name: California Silica Products
Controller Name: Randall Humphreys; Robert Humphreys
Violator Name: Western States Wholesale

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788498	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/29/2015
Mine Type:	Surface	***Violatn Issue Time:***	0937
Likelihood:	Reasonably	***Violation Occur Dt:***	10/29/2015
Amount Due:	1111	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	1111	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	Fatal	***Termination Time:***	1007
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.16001
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)

Proposed Penalty:	1111	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2013
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607925	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/08/2013
Mine Type:	Surface	***Violatn Issue Time:***	1124
Likelihood:	NoLikelihood	***Violation Occur Dt:***	04/16/2013
Amount Due:	100	***Orig Term Due Dt:***	05/08/2013
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/10/2013
Cal Yr:	2013	***Latest Term Due Dt:***	05/08/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	NoLostDays	***Termination Time:***	1126
No Affected:	0	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	50.30(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018
Violation No:	8994969	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	10
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/17/2018
Mine Type:	Surface	***Violatn Issue Time:***	1335
Likelihood:	Unlikely	***Violation Occur Dt:***	01/17/2018
Amount Due:	118	***Orig Term Due Dt:***	01/18/2018
Amount Paid:	118	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	01/18/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	01/24/2018
Inj Illness:	Permanent	***Termination Time:***	0937
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Primary	***Section of Act:***	

Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	118	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506820	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/26/2021
Mine Type:	Surface	***Violatn Issue Time:***	1207
Likelihood:	Unlikely	***Violation Occur Dt:***	10/26/2021
Amount Due:	125	***Orig Term Due Dt:***	10/26/2021
Amount Paid:	125	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/26/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	Fatal	***Termination Time:***	0847
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12008
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689119	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	1043
Likelihood:	Reasonably	***Violation Occur Dt:***	07/24/2012
Amount Due:	108	***Orig Term Due Dt:***	07/24/2012
Amount Paid:	108	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/24/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/24/2012
Inj Illness:	Permanent	***Termination Time:***	1049
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14100(c)

Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	108	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6871540	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/23/2020
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500790	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	05/19/2020
Mine Type:	Surface	***Violatn Issue Time:***	1003
Likelihood:	Reasonably	***Violation Occur Dt:***	05/19/2020
Amount Due:	378	***Orig Term Due Dt:***	05/20/2020
Amount Paid:	378	***Orig Term Due Tm:***	1141
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/19/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/20/2020
Bill Print Dt:	07/14/2020	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/09/2020
Cal Yr:	2020	***Latest Term Due Dt:***	05/20/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1141
Coal Metal Ind:	M	***Termination Dt:***	05/19/2020
Inj Illness:	LostDays	***Termination Time:***	1134
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.12005
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	378	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595727	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/31/2015
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781956	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	23
Docket Stat Cd:		***Violation Issue Dt:***	05/06/2015
Mine Type:	Surface	***Violatn Issue Time:***	0910
Likelihood:	Reasonably	***Violation Occur Dt:***	05/06/2015
Amount Due:	1026	***Orig Term Due Dt:***	05/06/2015
Amount Paid:	1026	***Orig Term Due Tm:***	0920
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/06/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/07/2015
Bill Print Dt:	06/16/2015	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/30/2015
Cal Yr:	2015	***Latest Term Due Dt:***	05/06/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0920
Coal Metal Ind:	M	***Termination Dt:***	05/07/2015
Inj Illness:	Permanent	***Termination Time:***	1000
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes

Special Assess:	No	***Part Section:***	56.14112(a)(1)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	1026	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018
Violation No:	8994972	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	10
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/17/2018
Mine Type:	Surface	***Violatn Issue Time:***	1354
Likelihood:	Unlikely	***Violation Occur Dt:***	01/17/2018
Amount Due:	118	***Orig Term Due Dt:***	01/18/2018
Amount Paid:	118	***Orig Term Due Tm:***	0700
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	01/18/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0700
Coal Metal Ind:	M	***Termination Dt:***	01/24/2018
Inj Illness:	Fatal	***Termination Time:***	1018
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	118	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689497	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012
Mine Type:	Surface	***Violatn Issue Time:***	0958
Likelihood:	Unlikely	***Violation Occur Dt:***	10/16/2012
Amount Due:	100	***Orig Term Due Dt:***	10/17/2012
Amount Paid:	100	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/17/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	10/16/2012
Inj Illness:	LostDays	***Termination Time:***	1243
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	

Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689511	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	11/06/2012
Mine Type:	Surface	***Violatn Issue Time:***	1400
Likelihood:	Unlikely	***Violation Occur Dt:***	10/17/2012
Amount Due:	100	***Orig Term Due Dt:***	12/04/2012
Amount Paid:	100	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/30/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0400
Coal Metal Ind:	M	***Termination Dt:***	09/19/2013
Inj Illness:	Permanent	***Termination Time:***	1123
No Affected:	2	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.5001(a)/.5005
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788493	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/28/2015
Mine Type:	Surface	***Violatn Issue Time:***	0910
Likelihood:	Reasonably	***Violation Occur Dt:***	10/28/2015
Amount Due:	4689	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	4689	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	10/29/2015
Inj Illness:	Fatal	***Termination Time:***	0830
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	

Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.9300(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	4689	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668626	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/17/2016
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788499	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	13
Docket Stat Cd:		***Violation Issue Dt:***	10/29/2015
Mine Type:	Surface	***Violatn Issue Time:***	1040
Likelihood:	Unlikely	***Violation Occur Dt:***	10/29/2015
Amount Due:	100	***Orig Term Due Dt:***	10/29/2015
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/28/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/30/2015
Bill Print Dt:	12/15/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/14/2016
Cal Yr:	2015	***Latest Term Due Dt:***	10/29/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	10/30/2015
Inj Illness:	Permanent	***Termination Time:***	0815
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(a)(1)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727339	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	09/02/2017
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	6727561	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	8
Docket Stat Cd:		***Violation Issue Dt:***	05/04/2017
Mine Type:	Surface	***Violatn Issue Time:***	1028
Likelihood:	Reasonably	***Violation Occur Dt:***	04/18/2017
Amount Due:	387	***Orig Term Due Dt:***	05/05/2017
Amount Paid:	387	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/18/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/08/2017
Bill Print Dt:	06/13/2017	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/10/2017
Cal Yr:	2017	***Latest Term Due Dt:***	09/08/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0905
Coal Metal Ind:	M	***Termination Dt:***	08/28/2017
Inj Illness:	Fatal	***Termination Time:***	1027
No Affected:	1	***Termination Type:***	Terminated

Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.5001(a)/.5005
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	387	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506823	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/27/2021
Mine Type:	Surface	***Violatn Issue Time:***	0917
Likelihood:	Reasonably	***Violation Occur Dt:***	10/27/2021
Amount Due:	355	***Orig Term Due Dt:***	10/27/2021
Amount Paid:	355	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/27/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	Fatal	***Termination Time:***	1125
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14130(i)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	355	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689121	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	1326
Likelihood:	Reasonably	***Violation Occur Dt:***	07/24/2012
Amount Due:	807	***Orig Term Due Dt:***	07/25/2012
Amount Paid:	807	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/25/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	07/31/2012
Inj Illness:	Fatal	***Termination Time:***	1214

No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.15001
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	807	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781916	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/10/2014
Mine Type:	Surface	***Violatn Issue Time:***	0940
Likelihood:	Unlikely	***Violation Occur Dt:***	12/10/2014
Amount Due:	150	***Orig Term Due Dt:***	12/10/2014
Amount Paid:	150	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/10/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000
Coal Metal Ind:	M	***Termination Dt:***	12/10/2014
Inj Illness:	LostDays	***Termination Time:***	0945
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	150	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727339	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	09/02/2017
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788969	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	10
Docket No:		***Violat Violatn Cnt:***	8
Docket Stat Cd:		***Violation Issue Dt:***	05/08/2017
Mine Type:	Surface	***Violatn Issue Time:***	1330
Likelihood:	Reasonably	***Violation Occur Dt:***	05/08/2017
Amount Due:	387	***Orig Term Due Dt:***	05/08/2017
Amount Paid:	387	***Orig Term Due Tm:***	1500
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/18/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/08/2017
Bill Print Dt:	06/13/2017	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/10/2017
Cal Yr:	2017	***Latest Term Due Dt:***	07/10/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	08/18/2017

Inj Illness:	Fatal	***Termination Time:***	0958
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.5002
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	387	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821165	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/16/2019
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432490	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	03/21/2019
Mine Type:	Surface	***Violatn Issue Time:***	0940
Likelihood:	Unlikely	***Violation Occur Dt:***	03/21/2019
Amount Due:	121	***Orig Term Due Dt:***	03/21/2019
Amount Paid:	121	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	03/21/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	03/26/2019
Bill Print Dt:	05/14/2019	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	03/21/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	03/26/2019
Inj Illness:	LostDays	***Termination Time:***	0845
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.9300(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668655	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2016
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8788598	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	16
Docket Stat Cd:		***Violation Issue Dt:***	04/27/2016
Mine Type:	Surface	***Violatn Issue Time:***	0940
Likelihood:	Unlikely	***Violation Occur Dt:***	04/27/2016
Amount Due:	150	***Orig Term Due Dt:***	04/27/2016
Amount Paid:	150	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/27/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/28/2016
Bill Print Dt:	06/14/2016	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/27/2016
Cal Yr:	2016	***Latest Term Due Dt:***	04/27/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000

Coal Metal Ind:	M	***Termination Dt:***	04/27/2016
Inj Illness:	LostDays	***Termination Time:***	0955
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	150	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689108	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	0818
Likelihood:	Unlikely	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	07/19/2012
Inj Illness:	LostDays	***Termination Time:***	0830
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14206(b)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432549	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	0755
Likelihood:	Unlikely	***Violation Occur Dt:***	06/12/2019
Amount Due:	121	***Orig Term Due Dt:***	06/12/2019
Amount Paid:	121	***Orig Term Due Tm:***	0830
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019
Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	06/12/2019

Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0830
Coal Metal Ind:	M	***Termination Dt:***	06/12/2019
Inj Illness:	LostDays	***Termination Time:***	0825
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4101
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607919	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1209
Likelihood:	Unlikely	***Violation Occur Dt:***	05/07/2013
Amount Due:	499	***Orig Term Due Dt:***	05/07/2013
Amount Paid:	499	***Orig Term Due Tm:***	1400
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	11/25/2014
Cal Yr:	2013	***Latest Term Due Dt:***	05/07/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1400
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Fatal	***Termination Time:***	0808
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12016
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	499	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6871540	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/23/2020
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2020
Violation No:	9500787	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	05/19/2020
Mine Type:	Surface	***Violatn Issue Time:***	0756
Likelihood:	Unlikely	***Violation Occur Dt:***	05/19/2020
Amount Due:	123	***Orig Term Due Dt:***	05/20/2020
Amount Paid:	123	***Orig Term Due Tm:***	1117
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/19/2020
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/20/2020
Bill Print Dt:	07/14/2020	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	08/09/2020

Cal Yr:	2020	***Latest Term Due Dt:***	05/20/2020
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1117
Coal Metal Ind:	M	***Termination Dt:***	06/02/2020
Inj Illness:	LostDays	***Termination Time:***	1816
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14132(b)(2)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	123	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595285	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	11/16/2014
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781870	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	15
Docket Stat Cd:		***Violation Issue Dt:***	08/14/2014
Mine Type:	Surface	***Violatn Issue Time:***	1020
Likelihood:	Reasonably	***Violation Occur Dt:***	08/14/2014
Amount Due:	2473	***Orig Term Due Dt:***	08/14/2014
Amount Paid:	2473	***Orig Term Due Tm:***	1025
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	08/14/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	08/19/2014
Bill Print Dt:	10/14/2014	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/26/2014
Cal Yr:	2014	***Latest Term Due Dt:***	08/14/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1025
Coal Metal Ind:	M	***Termination Dt:***	08/14/2014
Inj Illness:	Fatal	***Termination Time:***	1025
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	Yes	***Part Section:***	56.20011
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	2473	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727339	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	09/02/2017
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	6727560	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	7
Docket No:		***Violat Violatn Cnt:***	8
Docket Stat Cd:		***Violation Issue Dt:***	05/04/2017
Mine Type:	Surface	***Violatn Issue Time:***	1027
Likelihood:	Reasonably	***Violation Occur Dt:***	04/18/2017
Amount Due:	387	***Orig Term Due Dt:***	05/05/2017
Amount Paid:	387	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/18/2017
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/08/2017
Bill Print Dt:	06/13/2017	***Last Action Cd:***	Paid

Cal Qtr:	2	***Last Action Dt:***	08/10/2017
Cal Yr:	2017	***Latest Term Due Dt:***	09/08/2017
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	08/28/2017
Inj Illness:	Fatal	***Termination Time:***	1015
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.5001(a)/.5005
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	387	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689113	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	1045
Likelihood:	Unlikely	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	1230
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1230
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Fatal	***Termination Time:***	1415
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4101
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432548	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	0750
Likelihood:	Unlikely	***Violation Occur Dt:***	06/12/2019
Amount Due:	121	***Orig Term Due Dt:***	06/12/2019
Amount Paid:	121	***Orig Term Due Tm:***	0800
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019

Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	06/12/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0800
Coal Metal Ind:	M	***Termination Dt:***	06/12/2019
Inj Illness:	LostDays	***Termination Time:***	0805
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.16005
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821165	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	06/16/2019
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432491	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	03/21/2019
Mine Type:	Surface	***Violatn Issue Time:***	1010
Likelihood:	Unlikely	***Violation Occur Dt:***	03/21/2019
Amount Due:	121	***Orig Term Due Dt:***	03/21/2019
Amount Paid:	121	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	03/21/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	03/26/2019
Bill Print Dt:	05/14/2019	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	03/21/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	03/26/2019
Inj Illness:	LostDays	***Termination Time:***	0830
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.9300(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689500	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012
Mine Type:	Surface	***Violatn Issue Time:***	1026
Likelihood:	Unlikely	***Violation Occur Dt:***	10/16/2012
Amount Due:	100	***Orig Term Due Dt:***	10/16/2012
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012

Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/16/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	10/16/2012
Inj Illness:	Permanent	***Termination Time:***	1247
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.15004
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727464	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	04/18/2018
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2018
Violation No:	8994975	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	01/23/2018
Mine Type:	Surface	***Violatn Issue Time:***	1436
Likelihood:	Unlikely	***Violation Occur Dt:***	01/23/2018
Amount Due:	118	***Orig Term Due Dt:***	01/23/2018
Amount Paid:	118	***Orig Term Due Tm:***	1600
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	01/17/2018
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	01/24/2018
Bill Print Dt:	03/13/2018	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	03/28/2018
Cal Yr:	2018	***Latest Term Due Dt:***	01/23/2018
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1600
Coal Metal Ind:	M	***Termination Dt:***	01/24/2018
Inj Illness:	Fatal	***Termination Time:***	1036
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12032
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	118	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689498	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012
Mine Type:	Surface	***Violatn Issue Time:***	1018
Likelihood:	Reasonably	***Violation Occur Dt:***	10/16/2012
Amount Due:	108	***Orig Term Due Dt:***	10/16/2012
Amount Paid:	108	***Orig Term Due Tm:***	1200

Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/16/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	10/16/2012
Inj Illness:	Permanent	***Termination Time:***	1238
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14100(c)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	108	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506821	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/26/2021
Mine Type:	Surface	***Violatn Issue Time:***	1229
Likelihood:	Unlikely	***Violation Occur Dt:***	10/26/2021
Amount Due:	125	***Orig Term Due Dt:***	10/26/2021
Amount Paid:	125	***Orig Term Due Tm:***	1330
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/26/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1330
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	Fatal	***Termination Time:***	0845
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(a)(1)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595256	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/18/2014
Controller ID:	0105135	***Fiscal Qtr:***	2
Contractor ID:		***Fiscal Yr:***	2014
Violation No:	8781802	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	8
Docket No:		***Violat Violatn Cnt:***	14
Docket Stat Cd:		***Violation Issue Dt:***	02/20/2014
Mine Type:	Surface	***Violatn Issue Time:***	1021
Likelihood:	Reasonably	***Violation Occur Dt:***	02/20/2014
Amount Due:	207	***Orig Term Due Dt:***	02/21/2014

Amount Paid:	207	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	02/20/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	02/20/2014
Bill Print Dt:	04/15/2014	***Last Action Cd:***	Paid
Cal Qtr:	1	***Last Action Dt:***	05/18/2014
Cal Yr:	2014	***Latest Term Due Dt:***	02/21/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	02/24/2014
Inj Illness:	LostDays	***Termination Time:***	0918
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14100(c)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	207	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506819	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/26/2021
Mine Type:	Surface	***Violatn Issue Time:***	1155
Likelihood:	Unlikely	***Violation Occur Dt:***	10/26/2021
Amount Due:	125	***Orig Term Due Dt:***	10/26/2021
Amount Paid:	125	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/26/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	Fatal	***Termination Time:***	0841
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.12004
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727585	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/30/2021
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2021
Violation No:	9375568	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	7
Docket Stat Cd:		***Violation Issue Dt:***	05/04/2021
Mine Type:	Surface	***Violatn Issue Time:***	0955
Likelihood:	Unlikely	***Violation Occur Dt:***	05/04/2021

Amount Due:	125	***Orig Term Due Dt:***	05/04/2021
Amount Paid:	125	***Orig Term Due Tm:***	1055
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/04/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/05/2021
Bill Print Dt:	06/15/2021	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/12/2021
Cal Yr:	2021	***Latest Term Due Dt:***	05/04/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1055
Coal Metal Ind:	M	***Termination Dt:***	05/04/2021
Inj Illness:	Permanent	***Termination Time:***	1410
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14112(a)(1)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6821184	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	08/18/2019
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2019
Violation No:	9432551	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	6
Docket Stat Cd:		***Violation Issue Dt:***	06/12/2019
Mine Type:	Surface	***Violatn Issue Time:***	0935
Likelihood:	Unlikely	***Violation Occur Dt:***	06/12/2019
Amount Due:	121	***Orig Term Due Dt:***	06/12/2019
Amount Paid:	121	***Orig Term Due Tm:***	0940
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	06/11/2019
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	06/13/2019
Bill Print Dt:	07/16/2019	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/29/2019
Cal Yr:	2019	***Latest Term Due Dt:***	06/12/2019
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0940
Coal Metal Ind:	M	***Termination Dt:***	06/12/2019
Inj Illness:	LostDays	***Termination Time:***	0945
No Affected:	1	***Termination Type:***	Terminated
Negligence:	LowNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.16006
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	121	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689107	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	1135

Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	807	***Orig Term Due Dt:***	07/18/2012
Amount Paid:	807	***Orig Term Due Tm:***	1330
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/18/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1330
Coal Metal Ind:	M	***Termination Dt:***	07/19/2012
Inj Illness:	Fatal	***Termination Time:***	0810
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.18002(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	807	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689120	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	1130
Likelihood:	Unlikely	***Violation Occur Dt:***	07/24/2012
Amount Due:	100	***Orig Term Due Dt:***	07/25/2012
Amount Paid:	100	***Orig Term Due Tm:***	0900
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/25/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0900
Coal Metal Ind:	M	***Termination Dt:***	07/31/2012
Inj Illness:	Fatal	***Termination Time:***	1221
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.13015(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689501	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012

Mine Type:	Surface	***Violatn Issue Time:***	1103
Likelihood:	Unlikely	***Violation Occur Dt:***	10/16/2012
Amount Due:	100	***Orig Term Due Dt:***	10/16/2012
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/16/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	10/16/2012
Inj Illness:	Fatal	***Termination Time:***	1115
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.13001
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6872077	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/26/2022
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2022
Violation No:	9506824	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	9
Docket Stat Cd:		***Violation Issue Dt:***	10/27/2021
Mine Type:	Surface	***Violatn Issue Time:***	0926
Likelihood:	NoLikelihood	***Violation Occur Dt:***	10/16/2021
Amount Due:	125	***Orig Term Due Dt:***	10/27/2021
Amount Paid:	125	***Orig Term Due Tm:***	0930
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/26/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/27/2021
Bill Print Dt:	12/14/2021	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/03/2022
Cal Yr:	2021	***Latest Term Due Dt:***	10/27/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0930
Coal Metal Ind:	M	***Termination Dt:***	10/27/2021
Inj Illness:	NoLostDays	***Termination Time:***	0935
No Affected:	0	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	50.30(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689499	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	0

Docket Stat Cd:		***Violation Issue Dt:***	10/16/2012
Mine Type:	Surface	***Violatn Issue Time:***	1022
Likelihood:	Unlikely	***Violation Occur Dt:***	10/16/2012
Amount Due:	100	***Orig Term Due Dt:***	10/16/2012
Amount Paid:	100	***Orig Term Due Tm:***	1300
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/16/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1300
Coal Metal Ind:	M	***Termination Dt:***	10/16/2012
Inj Illness:	Permanent	***Termination Time:***	1246
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.14211(c)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689111	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	0929
Likelihood:	Unlikely	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Fatal	***Termination Time:***	1408
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.4101
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689503	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6

Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/17/2012
Mine Type:	Surface	***Violatn Issue Time:***	0915
Likelihood:	Reasonably	***Violation Occur Dt:***	10/17/2012
Amount Due:	243	***Orig Term Due Dt:***	10/17/2012
Amount Paid:	243	***Orig Term Due Tm:***	1115
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/17/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1115
Coal Metal Ind:	M	***Termination Dt:***	10/29/2012
Inj Illness:	Fatal	***Termination Time:***	1141
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	243	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689100	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	0
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/18/2012
Mine Type:	Surface	***Violatn Issue Time:***	0942
Likelihood:	Reasonably	***Violation Occur Dt:***	07/18/2012
Amount Due:	403	***Orig Term Due Dt:***	
Amount Paid:	403	***Orig Term Due Tm:***	
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	
Cit Ord Safe:	Order	***Latest Term Due Tm:***	
Coal Metal Ind:	M	***Termination Dt:***	07/25/2012
Inj Illness:	Fatal	***Termination Time:***	1211
No Affected:	4	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	46.5(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(g)(1)
Proposed Penalty:	403	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160674	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	05/08/2014
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8607922	***Violator Type CD:***	Operator

Violator ID:	0123751	***Viola Insp Day Cnt:***	11
Docket No:		***Violat Violatn Cnt:***	33
Docket Stat Cd:		***Violation Issue Dt:***	05/07/2013
Mine Type:	Surface	***Violatn Issue Time:***	1405
Likelihood:	Reasonably	***Violation Occur Dt:***	05/07/2013
Amount Due:	5080	***Orig Term Due Dt:***	05/08/2013
Amount Paid:	5080	***Orig Term Due Tm:***	1600
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/07/2013
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/09/2013
Bill Print Dt:	06/11/2013	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	04/21/2016
Cal Yr:	2013	***Latest Term Due Dt:***	05/08/2013
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1600
Coal Metal Ind:	M	***Termination Dt:***	05/08/2013
Inj Illness:	Permanent	***Termination Time:***	0750
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	5080	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689109	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	0835
Likelihood:	Reasonably	***Violation Occur Dt:***	07/19/2012
Amount Due:	807	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	807	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	Fatal	***Termination Time:***	1405
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14107(a)
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	807	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727585	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/30/2021
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2021

Violation No:	9375569	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	4
Docket No:		***Violat Violatn Cnt:***	7
Docket Stat Cd:		***Violation Issue Dt:***	05/04/2021
Mine Type:	Surface	***Violatn Issue Time:***	1010
Likelihood:	Unlikely	***Violation Occur Dt:***	05/04/2021
Amount Due:	125	***Orig Term Due Dt:***	05/04/2021
Amount Paid:	125	***Orig Term Due Tm:***	1030
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/04/2021
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/05/2021
Bill Print Dt:	06/15/2021	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	07/12/2021
Cal Yr:	2021	***Latest Term Due Dt:***	05/04/2021
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1030
Coal Metal Ind:	M	***Termination Dt:***	05/04/2021
Inj Illness:	LostDays	***Termination Time:***	1015
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:	No	***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	125	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6668655	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	07/18/2016
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2016
Violation No:	8994001	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	16
Docket Stat Cd:		***Violation Issue Dt:***	04/27/2016
Mine Type:	Surface	***Violatn Issue Time:***	1100
Likelihood:	Reasonably	***Violation Occur Dt:***	04/27/2016
Amount Due:	1111	***Orig Term Due Dt:***	04/27/2016
Amount Paid:	1111	***Orig Term Due Tm:***	1115
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	04/27/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	04/28/2016
Bill Print Dt:	06/14/2016	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/27/2016
Cal Yr:	2016	***Latest Term Due Dt:***	04/27/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1115
Coal Metal Ind:	M	***Termination Dt:***	04/28/2016
Inj Illness:	Permanent	***Termination Time:***	0820
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.14112(b)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	1111	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595706	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	02/15/2015
Controller ID:	0105135	***Fiscal Qtr:***	1

Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781919	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	17
Docket Stat Cd:		***Violation Issue Dt:***	12/11/2014
Mine Type:	Surface	***Violatn Issue Time:***	0901
Likelihood:	Unlikely	***Violation Occur Dt:***	12/11/2014
Amount Due:	499	***Orig Term Due Dt:***	12/11/2014
Amount Paid:	499	***Orig Term Due Tm:***	0915
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	12/10/2014
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	12/11/2014
Bill Print Dt:	01/13/2015	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/26/2015
Cal Yr:	2014	***Latest Term Due Dt:***	12/11/2014
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	0915
Coal Metal Ind:	M	***Termination Dt:***	12/11/2014
Inj Illness:	LostDays	***Termination Time:***	0915
No Affected:	1	***Termination Type:***	Terminated
Negligence:	HighNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.16006
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	499	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	10/18/2012
Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689112	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	1
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/19/2012
Mine Type:	Surface	***Violatn Issue Time:***	0949
Likelihood:	Reasonably	***Violation Occur Dt:***	07/19/2012
Amount Due:	100	***Orig Term Due Dt:***	07/19/2012
Amount Paid:	100	***Orig Term Due Tm:***	1200
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	09/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	10/04/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/19/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1200
Coal Metal Ind:	M	***Termination Dt:***	07/23/2012
Inj Illness:	LostDays	***Termination Time:***	1414
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11001
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160088	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	11/22/2012

Controller ID:	0105135	***Fiscal Qtr:***	4
Contractor ID:		***Fiscal Yr:***	2012
Violation No:	8689117	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	3
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	07/24/2012
Mine Type:	Surface	***Violatn Issue Time:***	0837
Likelihood:	Reasonably	***Violation Occur Dt:***	07/24/2012
Amount Due:	100	***Orig Term Due Dt:***	07/24/2012
Amount Paid:	100	***Orig Term Due Tm:***	1000
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	07/18/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	07/25/2012
Bill Print Dt:	10/16/2012	***Last Action Cd:***	Paid
Cal Qtr:	3	***Last Action Dt:***	11/06/2012
Cal Yr:	2012	***Latest Term Due Dt:***	07/24/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1000
Coal Metal Ind:	M	***Termination Dt:***	07/24/2012
Inj Illness:	LostDays	***Termination Time:***	0842
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	Yes	***Part Section:***	56.14205
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	100	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6727314	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	03/03/2017
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2017
Violation No:	8788921	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	5
Docket No:		***Violat Violatn Cnt:***	12
Docket Stat Cd:		***Violation Issue Dt:***	11/15/2016
Mine Type:	Surface	***Violatn Issue Time:***	0907
Likelihood:	Unlikely	***Violation Occur Dt:***	11/15/2016
Amount Due:	171	***Orig Term Due Dt:***	11/15/2016
Amount Paid:	171	***Orig Term Due Tm:***	1100
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	11/15/2016
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	11/16/2016
Bill Print Dt:	01/17/2017	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/31/2017
Cal Yr:	2016	***Latest Term Due Dt:***	11/15/2016
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1100
Coal Metal Ind:	M	***Termination Dt:***	11/16/2016
Inj Illness:	LostDays	***Termination Time:***	0826
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	No
Special Assess:	No	***Part Section:***	56.20003(a)
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	171	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	6595727	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	

Replaced by Ord No:		***Final Ord Issue Dt:***	07/31/2015
Controller ID:	0105135	***Fiscal Qtr:***	3
Contractor ID:		***Fiscal Yr:***	2015
Violation No:	8781957	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	23
Docket Stat Cd:		***Violation Issue Dt:***	05/06/2015
Mine Type:	Surface	***Violatn Issue Time:***	1310
Likelihood:	Reasonably	***Violation Occur Dt:***	05/06/2015
Amount Due:	2282	***Orig Term Due Dt:***	05/06/2015
Amount Paid:	2282	***Orig Term Due Tm:***	1320
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	05/06/2015
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	05/07/2015
Bill Print Dt:	06/16/2015	***Last Action Cd:***	Paid
Cal Qtr:	2	***Last Action Dt:***	06/30/2015
Cal Yr:	2015	***Latest Term Due Dt:***	05/06/2015
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1320
Coal Metal Ind:	M	***Termination Dt:***	05/06/2015
Inj Illness:	Fatal	***Termination Time:***	1315
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Primary	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	2282	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Violation Details

Event No:	1160638	***Contested Ind:***	No
Initial Viol No:		***Contested Dt:***	
Replaced by Ord No:		***Final Ord Issue Dt:***	01/16/2013
Controller ID:	0105135	***Fiscal Qtr:***	1
Contractor ID:		***Fiscal Yr:***	2013
Violation No:	8689502	***Violator Type CD:***	Operator
Violator ID:	0123751	***Viola Insp Day Cnt:***	6
Docket No:		***Violat Violatn Cnt:***	0
Docket Stat Cd:		***Violation Issue Dt:***	10/17/2012
Mine Type:	Surface	***Violatn Issue Time:***	0912
Likelihood:	Reasonably	***Violation Occur Dt:***	10/17/2012
Amount Due:	243	***Orig Term Due Dt:***	10/17/2012
Amount Paid:	243	***Orig Term Due Tm:***	1115
Asmt Generated Ind:	No	***Inspectn Begin Dt:***	10/16/2012
Asses Case Stat Cd:	Closed	***Inspection End Dt:***	10/17/2012
Bill Print Dt:	12/11/2012	***Last Action Cd:***	Paid
Cal Qtr:	4	***Last Action Dt:***	01/08/2013
Cal Yr:	2012	***Latest Term Due Dt:***	10/17/2012
Cit Ord Safe:	Citation	***Latest Term Due Tm:***	1115
Coal Metal Ind:	M	***Termination Dt:***	10/29/2012
Inj Illness:	Fatal	***Termination Time:***	1139
No Affected:	1	***Termination Type:***	Terminated
Negligence:	ModNegligence	***Vacate Dt:***	
Written Notice:		***Vacate Time:***	
Enforcement Area:		***Sig Sub:***	Yes
Special Assess:	No	***Part Section:***	56.11012
Primary or Mill:	Mill	***Section of Act:***	
Right to Conf Dt:		***Section of Act 1:***	104(a)
Proposed Penalty:	243	***Section of Act 2:***	
Mine Name:	California Silica Products		
Controller Name:	Randall Humphreys; Robert Humphreys		
Violator Name:	Western States Wholesale		

Site: ***U.S. AIR FORCE***
831 ST. CSG/CC GEORGE AFB GEORGE AFB CA 92394

PRP

Site EPA ID: CA2570024453
Site NPL Status: Currently on the Final NPL
Site Non NPL Status:
Site Name: GEORGE AIR FORCE BASE
Site Address: AIR BASE RD- NR ST RTE 395
Site City: VICTORVILLE
Site State: CA
Site Zip: 92392
Site Primary Latitude: +34.595000
Site Primary Longitude: -117.383300

Noticed Party Action Information

Action Type Seq: NJ-1
Action Abbrev: Not Ltrs
Action Date: GENERAL NOTICE 3/7/1990 5:00:00 AM

Site: ***U.S. AIR FORCE***
831 ST. CSG/CC GEORGE AFB GEORGE AFB CA 92394

PRP

Site EPA ID: CAD980736151
Site NPL Status: Currently on the Final NPL
Site Non NPL Status:
Site Name: PURITY OIL SALES, INC.
Site Address: 3265 S MAPLE AVE
Site City: MALAGA
Site State: CA
Site Zip: 93725
Site Primary Latitude: +36.687400
Site Primary Longitude: -119.746700

Noticed Party Action Information

Action Type Seq: NJ-3
Action Abbrev: Not Ltrs
Action Date: GENERAL NOTICE 4/19/1990 4:00:00 AM

Site: ***NORTHROP GRUMMAN GAFB B559***
GEORGE AIR FORCE BASE BUILDING 559 VICTORVILLE CA 92394

RCRA NON GEN

Handler ID: CAR000000604
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	19980924	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:	F	***Location Latitude:***	
In Handler Univ:	N	***Location Longitude:***	
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	HQ
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	L--
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20020627
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	NORTHROP GRUMMAN GAFB B559
Location Street No:	
Location Street1:	GEORGE AIR FORCE BASE
Location Street2:	BUILDING 559
Location City:	VICTORVILLE
Location State:	CA
Location Zip:	92394
Location County Code:	CA071
Location County Name:	SAN BERNARDINO
Location Country:	US
Contact Name:	MARY ELAINE PALACIO
Contact Street No:	
Contact Street1:	ONE HORNET WY
Contact Street2:	
Contact City:	EL SEGUNDO

Contact State: CA
Contact Zip: 90245-2804
Contact Country: US
Contact Phone & Ext: 310-332-4114
Contact Fax:
Contact Email Address:
Contact Title:
Owner Name: NORTHROP GRUMMAN CORP
Owner Type: P
Owner Seq: 1
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19960901
Handler Name: NORTHROP GRUMMAN GAFB B559
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19980924
Handler Name: NORTHROP GRUMMAN GAFB B559
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: NORTHROP GRUMMAN CORP
Dt Became Current:
Dt Ended Current:
Phone: 805-272-6279
Source Type: Notification

Street No:
Street1: 3520 E AVE M
Street2:
City: PALMDALE
State: CA
Country:
Zip: 93550

Historical Handler Details

Receive Dt: 19960901
Generator Code Description: Small Quantity Generator
Handler Name: NORTHROP GRUMMAN GAFB B559

Site: ***CALNEV PIPE LINE, LLC - GEORGE AFB***
AIR BASE ROAD GEORGE AFB CA 92392

RCRA NON GEN

Handler ID: CAT080013881
Generator Status: N
Recycler Activity?: YES
Recycler Activity Note: This facility has been identified as a Recycler Facility with indication of Reclamation and Recovery in the RCRA Biennial Report Module for Management Methods
H010 - Metals recovery including retorting, smelting, chemical, etc.
H011 - Mercury recovery (includes mercury retorting, bulb/lamp crushing and mercury vapor recovery, thermostat recovery, mercury from medical equipment recovery, mercury car switch recovery, etc.)
H015 - Deployment/deactivation of airbag waste followed by metals recovery
H020 - Solvents recovery
H039 - Other recovery or reclamation for reuse including acid regeneration, organics recovery, etc.
H050 - Energy recovery at this site; used as fuel (includes on-site fuel blending before energy recovery)

H061 - Fuel blending prior to energy recovery at another site (waste generated on-site or received from off-site)

Violation/Evaluation Summary

Note: NO RECORDS: As of Nov 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	D	***NAIC 1:***	48691
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20180205	***NAIC 4:***	
Active Site:	-----	***State:***	CA
Land Type:	P	***Location Latitude:***	
In Handler Univ:	N	***Location Longitude:***	
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	
Report Cycle:		***State District Owner:***	
Accessibility:		***State District:***	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	D		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		

Hhandler Last Change: 20180226
Recognized Trader Importer: N
Recognized Trader Exporter: N
Slab Importer: N
Slab Exporter: N
Manifest Broker: N
Subpart P: N
Contact Language: EN
Handler Name: CALNEV PIPE LINE, LLC - GEORGE AFB
Location Street No:
Location Street1: AIR BASE ROAD
Location Street2:
Location City: GEORGE AFB
Location State: CA
Location Zip: 92392
Location County Code: CA071
Location County Name: SAN BERNARDINO
Location Country: US
Contact Name: RICH BRITO
Contact Street No: 1100
Contact Street1: TOWN AND COUNTRY ROAD
Contact Street2:
Contact City: ORANGE
Contact State: CA
Contact Zip: 92868
Contact Country: US
Contact Phone & Ext: 714-560-4875
Contact Fax: 714-560-6569
Contact Email Address: RICH_BRITO@KINDERMORGAN.COM
Contact Title: EHS - SPECIALIST
Owner Name: CALNEV PIPE LINE, LLC
Owner Type: P
Owner Seq: 1
Operator Name: CALNEV PIPE LINE, LLC
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19801208
Handler Name: CALNEV PIPE LINE CO
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 19801208
Handler Name: CALNEV PIPE LINE CO
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19960901
Handler Name: CALNEV PIPE LINE CO
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 19980129
Handler Name: CALNEV PIPE LINE CO
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 19980129
Handler Name: CALNEV PIPE LINE CO
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20140301
Handler Name: CALNEV PIPE LINE, LLC - GEORGE AFB
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20180205
Handler Name: CALNEV PIPE LINE, LLC - GEORGE AFB
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Deactivation
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: CALNEV PIPE LINE, LLC
Dt Became Current: 20010330
Dt Ended Current:
Phone:
Source Type: Annual/Biennial Report update with Notification
Street No:
Street1:
Street2:
City:
State:
Country:
Zip:

Owner/Operator Ind: Current Operator
Type: Private
Name: NOT REQUIRED
Dt Became Current:
Dt Ended Current:
Phone: 415-555-1212
Source Type: Implementer
Street No:
Street1: NOT REQUIRED
Street2:
City: NOT REQUIRED
State: ME
Country:
Zip: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: CALNEV PIPE LINE COMPANY
Street No:
Street1: NOT REQUIRED
Street2:

Dt Became Current:		***City:***	NOT REQUIRED
Dt Ended Current:		***State:***	ME
Phone:	415-555-1212	***Country:***	
Source Type:	Implementer	***Zip:***	99999
Owner/Operator Ind:	Current Owner	***Street No:***	1100
Type:	Private	***Street1:***	TOWN AND COUNTRY ROAD
Name:	CALNEV PIPE LINE, LLC	***Street2:***	
Dt Became Current:	20010330	***City:***	ORANGE
Dt Ended Current:		***State:***	CA
Phone:	714-560-4875	***Country:***	US
Source Type:	Deactivation	***Zip:***	92868
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street1:***	
Name:	CALNEV PIPE LINE, LLC	***Street2:***	
Dt Became Current:	20010330	***City:***	
Dt Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Deactivation	***Zip:***	
Owner/Operator Ind:	Current Owner	***Street No:***	1100
Type:	Private	***Street1:***	TOWN AND COUNTRY ROAD
Name:	CALNEV PIPE LINE, LLC	***Street2:***	
Dt Became Current:	20010330	***City:***	ORANGE
Dt Ended Current:		***State:***	CA
Phone:	714-560-4875	***Country:***	
Source Type:	Annual/Biennial Report update with Notification	***Zip:***	92868
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	NOT REQUIRED
Name:	CALNEV PIPE LINE COMPANY	***Street2:***	
Dt Became Current:		***City:***	NOT REQUIRED
Dt Ended Current:		***State:***	ME
Phone:	415-555-1212	***Country:***	
Source Type:	Notification	***Zip:***	99999

Historical Handler Details

Receive Dt:	20140301
Generator Code Description:	Large Quantity Generator
Handler Name:	CALNEV PIPE LINE, LLC - GEORGE AFB
Receive Dt:	19980129
Generator Code Description:	Large Quantity Generator
Handler Name:	CALNEV PIPE LINE CO
Receive Dt:	19980129
Generator Code Description:	Small Quantity Generator
Handler Name:	CALNEV PIPE LINE CO
Receive Dt:	19960901
Generator Code Description:	Small Quantity Generator
Handler Name:	CALNEV PIPE LINE CO
Receive Dt:	19801208
Generator Code Description:	Large Quantity Generator
Handler Name:	CALNEV PIPE LINE CO
Receive Dt:	19801208
Generator Code Description:	Large Quantity Generator
Handler Name:	CALNEV PIPE LINE CO

Site: ***Cobalt Middle School***
1380 Cobalt RD Victorville CA 92392

SANBERN CUPA

Facility ID:	FA0016999
Owner Info:	Victor Valley Union High School District
Mailing Care of:	

Mailing Address 2:
Mailing City: Victorville
Mailing State: CA
Mailing Zip: 92395

Detail(s)

Permit ID: PT0038760
Status: INACTIVE
Program Element Code: 4241
Permit Desc: HAZARDOUS MATERIALS 1-3 CHEMICALS SPECIAL
To: 8/31/2019
Mailing Address 1: 16350 S Mojave Dr

Site: ***OWS 768-S1 Metal Fabrication Shop***
Phantom West Street, Victorville, San Bernardino County CA

UST CLOSURE

Claim Case No: Case No. T10000001728
ID: T10000001728
Deadline to Recv Comments: 2022/01/07
Prop UST Case Closure Type: Closure of Underground Storage Tank (UST) Cases - Closure Denials and Approved Orders

Documents

Doc Type: Summary
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001728-summary.pdf

Doc Type: Notice
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001728-notice.pdf

Doc Type: Draft Order
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001728-do.pdf

Closure/ Denial /Approved Orders

Doc Title: WQ 2022-0004-UST (1/26/2022)
Denial Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2022/T10000001728_finalorder.pdf

Closure Letter Signed

Letter Title: Uniform Closure Letter (02/25/2022)
Letter Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/2022/t10000001728-ucl.pdf

Main Info Details

Site Name: OWS 768-S1 Metal Fabrication Shop
Site Address: Phantom West Street, Victorville, San Bernardino County

---

Site: ***OWS 55775 Storm Drain System/Waste Treatment Building***
Phantom West Street, Victorville, San Bernardino County CA

UST CLOSURE

Claim Case No: Case No. T10000001737
ID: T10000001737
Deadline to Recv Comments: 2022/01/07
Prop UST Case Closure Type: Closure of Underground Storage Tank (UST) Cases - Closure Denials and Approved Orders

Documents

Doc Type: Notice
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001737-

notice.pdf

Doc Type: Draft Order
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001737-do.pdf

Doc Type: Summary
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001737-summary.pdf

Closure/ Denial /Approved Orders

Doc Title: WQ 2022-0006-UST (1/26/2022)
Denial Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2022/T10000001737_finalorder.pdf

Closure Letter Signed

Letter Title: Uniform Closure Letter (02/25/2022)
Letter Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/2022/t10000001737-ucl.pdf

Main Info Details

Site Name: OWS 55775 Storm Drain System/Waste Treatment Building
Site Address: Phantom West Street, Victorville, San Bernardino County

---

Site: ***OWS 723-S1 Old Fire Station***
Phantom West Street, Victorville, San Bernardino County CA

UST CLOSURE

Claim Case No: Case No. T10000001724
ID: T10000001724
Deadline to Recv Comments: 2022/01/07
Prop UST Case Closure Type: Closure of Underground Storage Tank (UST) Cases - Closure Denials and Approved Orders

Documents

Doc Type: Notice
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001724-notice.pdf

Doc Type: Draft Order
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001724-do.pdf

Doc Type: Summary
Documents Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/prop_closure_cases/2021/t10000001724-summary.pdf

Closure/ Denial /Approved Orders

Doc Title: WQ 2022-0009-UST (2/3/2022)
Denial Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/2022/t10000001724-finalorder.pdf

Closure Letter Signed

Letter Title: Uniform Closure Letter (02/25/2022)
Letter Link: https://www.waterboards.ca.gov/water_issues/programs/ustcf/docs/2022/t10000001724-ucl.pdf

Main Info Details

Site Name: OWS 723-S1 Old Fire Station
Site Address: Phantom West Street, Victorville, San Bernardino County

---

Site: ***GEORGE AIR FORCE BASE***

AIR BASE RADL GEORGE ADELANTO CA

UST SWEEPS

C C:	A36-000-9667	***D Filename:***	SITE10A
BOE:	44-020214	***Page No:***	2
Comp:	9667	***County:***	SAN BERNARDINO
Status:	ACTIVE	***State :***	CA
No of Tanks:	1	***Zip:***	92392
Jurisdict:	SAN BERNARDINO COUNTY	***Latitude:***	0
Agency:	ENVIRONMENTAL HEALTH - U.S.T.	***Longitude:***	0
Phone:		***Georesult:***	N

Tank Details

Tank ID:	000001	***S Contain:***	
O Tank ID:	GU-02	***Stg:***	P
SWRCB No:	36-000-009667-000001	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	5000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Site: ***GEORGE AIR FORCE BASE***
831ST CSG/DEEV GEORGE AFB CA

UST SWEEPS

C C:	A36-000-24808	***D Filename:***	SITE10A
BOE:		***Page No:***	97
Comp:	24808	***County:***	SAN BERNARDINO
Status:	ACTIVE	***State :***	CA
No of Tanks:		***Zip:***	92394
Jurisdict:	SAN BERNARDINO COUNTY	***Latitude:***	0
Agency:	ENVIRONMENTAL HEALTH - U.S.T.	***Longitude:***	0
Phone:		***Georesult:***	N

Tank Details

Tank ID:	000012	***S Contain:***	
O Tank ID:	VALLEY -3	***Stg:***	P
SWRCB No:	36-000-024808-000012	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	6000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000049	***S Contain:***	
O Tank ID:	761-1	***Stg:***	P
SWRCB No:	36-000-024808-000049	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	1000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000052	***S Contain:***	
O Tank ID:	730-1	***Stg:***	P
SWRCB No:	36-000-024808-000052	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000062	***S Contain:***	
O Tank ID:	701-1	***Stg:***	P
SWRCB No:	36-000-024808-000062	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000081	***S Contain:***	
O Tank ID:	660 T-4	***Stg:***	P
SWRCB No:	36-000-024808-000081	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	12045	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000090	***S Contain:***	
O Tank ID:	593-1	***Stg:***	P
SWRCB No:	36-000-024808-000090	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000095	***S Contain:***	
O Tank ID:	568-1	***Stg:***	P
SWRCB No:	36-000-024808-000095	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	5000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000100	***S Contain:***	
O Tank ID:	550 T-8	***Stg:***	P
SWRCB No:	36-000-024808-000100	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	2007	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000103	***S Contain:***	
O Tank ID:	501-1	***Stg:***	P
SWRCB No:	36-000-024808-000103	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	8000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000107	***S Contain:***	
O Tank ID:	299-1	***Stg:***	P
SWRCB No:	36-000-024808-000107	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000053	***S Contain:***	
O Tank ID:	723-2	***Stg:***	P
SWRCB No:	36-000-024808-000053	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	1250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000060	***S Contain:***	
O Tank ID:	707-2	***Stg:***	P
SWRCB No:	36-000-024808-000060	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000072	***S Contain:***	
O Tank ID:	685-2	***Stg:***	P
SWRCB No:	36-000-024808-000072	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	120	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000073	***S Contain:***	
O Tank ID:	685-1	***Stg:***	P
SWRCB No:	36-000-024808-000073	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	12000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000077	***S Contain:***	
O Tank ID:	669-1	***Stg:***	P
SWRCB No:	36-000-024808-000077	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	7518	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000091	***S Contain:***	
O Tank ID:	592-1	***Stg:***	P
SWRCB No:	36-000-024808-000091	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	550	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000110	***S Contain:***	
O Tank ID:	256-1	***Stg:***	P
SWRCB No:	36-000-024808-000110	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	8000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000008	***S Contain:***	
O Tank ID:	AQUA-4	***Stg:***	W
SWRCB No:	36-000-024808-000008	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000009	***S Contain:***	
O Tank ID:	AQUA-3	***Stg:***	W
SWRCB No:	36-000-024808-000009	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000011	***S Contain:***	
O Tank ID:	AQUA-1	***Stg:***	W
SWRCB No:	36-000-024808-000011	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000020	***S Contain:***	
O Tank ID:	32000 D-1	***Stg:***	P
SWRCB No:	36-000-024808-000020	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	5654	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000022	***S Contain:***	
O Tank ID:	32000 T-5	***Stg:***	P
SWRCB No:	36-000-024808-000022	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50695	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000033	***S Contain:***	
O Tank ID:	1155-4	***Stg:***	P
SWRCB No:	36-000-024808-000033	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	20000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000035	***S Contain:***	
O Tank ID:	1155-2	***Stg:***	P
SWRCB No:	36-000-024808-000035	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:		***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000039	***S Contain:***	
O Tank ID:	1055-2	***Stg:***	P
SWRCB No:	36-000-024808-000039	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:		***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000043	***S Contain:***	
O Tank ID:	799-1	***Stg:***	P
SWRCB No:	36-000-024808-000043	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	2500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000047	***S Contain:***	
O Tank ID:	763-1	***Stg:***	P
SWRCB No:	36-000-024808-000047	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	1250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000048	***S Contain:***	
O Tank ID:	761-2	***Stg:***	P
SWRCB No:	36-000-024808-000048	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000078	***S Contain:***	
O Tank ID:	687-2	***Stg:***	P
SWRCB No:	36-000-024808-000078	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	1200	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000006	***S Contain:***	
O Tank ID:	AQUA-6	***Stg:***	W
SWRCB No:	36-000-024808-000006	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000018	***S Contain:***	
O Tank ID:	32000 D-4	***Stg:***	P
SWRCB No:	36-000-024808-000018	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	5400	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000032	***S Contain:***	
O Tank ID:	1185-1	***Stg:***	P
SWRCB No:	36-000-024808-000032	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000038	***S Contain:***	
O Tank ID:	1120-1	***Stg:***	P
SWRCB No:	36-000-024808-000038	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:		***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000040	***S Contain:***	
O Tank ID:	1055	***Stg:***	P
SWRCB No:	36-000-024808-000040	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:		***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000064	***S Contain:***	
O Tank ID:	690-1	***Stg:***	P
SWRCB No:	36-000-024808-000064	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	50000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000067	***S Contain:***	
O Tank ID:	690-4	***Stg:***	P
SWRCB No:	36-000-024808-000067	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	50000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000068	***S Contain:***	
O Tank ID:	690-5	***Stg:***	P
SWRCB No:	36-000-024808-000068	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	50000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000071	***S Contain:***	
O Tank ID:	686-1	***Stg:***	P
SWRCB No:	36-000-024808-000071	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	12000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000003	***S Contain:***	
O Tank ID:	AQUA-9	***Stg:***	W
SWRCB No:	36-000-024808-000003	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000007	***S Contain:***	
O Tank ID:	AQUA-5	***Stg:***	W
SWRCB No:	36-000-024808-000007	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000010	***S Contain:***	
O Tank ID:	AQUA-2	***Stg:***	W
SWRCB No:	36-000-024808-000010	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000013	***S Contain:***	
O Tank ID:	VALLEY -2	***Stg:***	P
SWRCB No:	36-000-024808-000013	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	2000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000014	***S Contain:***	
O Tank ID:	VALLEY -1	***Stg:***	P
SWRCB No:	36-000-024808-000014	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000017	***S Contain:***	
O Tank ID:	46001-1	***Stg:***	P
SWRCB No:	36-000-024808-000017	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	10000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000021	***S Contain:***	
O Tank ID:	32000 T-6	***Stg:***	P
SWRCB No:	36-000-024808-000021	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50730	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000025	***S Contain:***	
O Tank ID:	32000 T-2	***Stg:***	P
SWRCB No:	36-000-024808-000025	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50790	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000031	***S Contain:***	
O Tank ID:	1188-1	***Stg:***	P
SWRCB No:	36-000-024808-000031	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	600	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000041	***S Contain:***	
O Tank ID:	841-1	***Stg:***	P
SWRCB No:	36-000-024808-000041	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	600	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000050	***S Contain:***	
O Tank ID:	756-1	***Stg:***	P
SWRCB No:	36-000-024808-000050	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	10000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000054	***S Contain:***	
O Tank ID:	723-1	***Stg:***	P
SWRCB No:	36-000-024808-000054	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	1250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000056	***S Contain:***	
O Tank ID:	711-2	***Stg:***	P
SWRCB No:	36-000-024808-000056	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	1000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000057	***S Contain:***	
O Tank ID:	711-1	***Stg:***	P
SWRCB No:	36-000-024808-000057	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	1500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000058	***S Contain:***	
O Tank ID:	710-2	***Stg:***	P
SWRCB No:	36-000-024808-000058	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	600	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000059	***S Contain:***	
O Tank ID:	710-1	***Stg:***	P
SWRCB No:	36-000-024808-000059	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	1250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000070	***S Contain:***	
O Tank ID:	682 OS	***Stg:***	W
SWRCB No:	36-000-024808-000070	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	1300	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000075	***S Contain:***	
O Tank ID:	678-2	***Stg:***	P
SWRCB No:	36-000-024808-000075	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	400	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000080	***S Contain:***	
O Tank ID:	660 T-5	***Stg:***	P
SWRCB No:	36-000-024808-000080	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	1000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000082	***S Contain:***	
O Tank ID:	660 T-3	***Stg:***	P
SWRCB No:	36-000-024808-000082	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	12108	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000083	***S Contain:***	
O Tank ID:	660 T-2	***Stg:***	P
SWRCB No:	36-000-024808-000083	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	12045	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000086	***S Contain:***	
O Tank ID:	643-2	***Stg:***	P
SWRCB No:	36-000-024808-000086	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000088	***S Contain:***	
O Tank ID:	596-2	***Stg:***	P
SWRCB No:	36-000-024808-000088	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	125	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000097	***S Contain:***	
O Tank ID:	559-2	***Stg:***	P
SWRCB No:	36-000-024808-000097	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	2000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000102	***S Contain:***	
O Tank ID:	550 T-6	***Stg:***	P
SWRCB No:	36-000-024808-000102	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	10129	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000105	***S Contain:***	
O Tank ID:	497-1	***Stg:***	P
SWRCB No:	36-000-024808-000105	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	8000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000106	***S Contain:***	
O Tank ID:	310-1	***Stg:***	P
SWRCB No:	36-000-024808-000106	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	6000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000111	***S Contain:***	
O Tank ID:	253-1	***Stg:***	P
SWRCB No:	36-000-024808-000111	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	8000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000005	***S Contain:***	
O Tank ID:	AQUA-7	***Stg:***	W
SWRCB No:	36-000-024808-000005	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000026	***S Contain:***	
O Tank ID:	32000 T-1	***Stg:***	P
SWRCB No:	36-000-024808-000026	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50550	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000028	***S Contain:***	
O Tank ID:	1209-1	***Stg:***	P
SWRCB No:	36-000-024808-000028	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	75	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000029	***S Contain:***	
O Tank ID:	1200-2	***Stg:***	P
SWRCB No:	36-000-024808-000029	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	600	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000045	***S Contain:***	
O Tank ID:	766-1	***Stg:***	P
SWRCB No:	36-000-024808-000045	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	550	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000065	***S Contain:***	
O Tank ID:	690-2	***Stg:***	P
SWRCB No:	36-000-024808-000065	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	50000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000079	***S Contain:***	
O Tank ID:	687-1	***Stg:***	P
SWRCB No:	36-000-024808-000079	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	1200	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000084	***S Contain:***	
O Tank ID:	660 T-1	***Stg:***	P
SWRCB No:	36-000-024808-000084	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	12093	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000089	***S Contain:***	
O Tank ID:	596-1	***Stg:***	P
SWRCB No:	36-000-024808-000089	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	125	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000096	***S Contain:***	
O Tank ID:	559-3	***Stg:***	P
SWRCB No:	36-000-024808-000096	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	2000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000046	***S Contain:***	
O Tank ID:	763-2	***Stg:***	P
SWRCB No:	36-000-024808-000046	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	1250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000051	***S Contain:***	
O Tank ID:	730-2	***Stg:***	P
SWRCB No:	36-000-024808-000051	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000055	***S Contain:***	
O Tank ID:	711-3	***Stg:***	W
SWRCB No:	36-000-024808-000055	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	WASTE OIL
Capac:	1000	***ONA:***	
Tank Use:	OIL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000061	***S Contain:***	
O Tank ID:	707-1	***Stg:***	P
SWRCB No:	36-000-024808-000061	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000074	***S Contain:***	
O Tank ID:	678-3	***Stg:***	P
SWRCB No:	36-000-024808-000074	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	125	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000085	***S Contain:***	
O Tank ID:	643-3	***Stg:***	P
SWRCB No:	36-000-024808-000085	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000092	***S Contain:***	
O Tank ID:	591-1	***Stg:***	P
SWRCB No:	36-000-024808-000092	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	10000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000098	***S Contain:***	
O Tank ID:	559-1	***Stg:***	P
SWRCB No:	36-000-024808-000098	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	2000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000099	***S Contain:***	
O Tank ID:	555-1	***Stg:***	W
SWRCB No:	36-000-024808-000099	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	WASTE OIL
Capac:	3000	***ONA:***	
Tank Use:	OIL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000104	***S Contain:***	
O Tank ID:	499-1	***Stg:***	P
SWRCB No:	36-000-024808-000104	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	8000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000109	***S Contain:***	
O Tank ID:	280-1	***Stg:***	P
SWRCB No:	36-000-024808-000109	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	200	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000001	***S Contain:***	
O Tank ID:	111-1	***Stg:***	P
SWRCB No:	36-000-024808-000001	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	6000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000004	***S Contain:***	
O Tank ID:	AQUA-8	***Stg:***	W
SWRCB No:	36-000-024808-000004	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000015	***S Contain:***	
O Tank ID:	46001-3	***Stg:***	P
SWRCB No:	36-000-024808-000015	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	2000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000016	***S Contain:***	
O Tank ID:	46001-2	***Stg:***	P
SWRCB No:	36-000-024808-000016	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:		***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000027	***S Contain:***	
O Tank ID:	1213-1	***Stg:***	P
SWRCB No:	36-000-024808-000027	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:		***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000030	***S Contain:***	
O Tank ID:	1200-1	***Stg:***	P
SWRCB No:	36-000-024808-000030	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	75	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000034	***S Contain:***	
O Tank ID:	1155-3	***Stg:***	P
SWRCB No:	36-000-024808-000034	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	25000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000036	***S Contain:***	
O Tank ID:	1155-1	***Stg:***	P
SWRCB No:	36-000-024808-000036	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	10000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000037	***S Contain:***	
O Tank ID:	1139-1	***Stg:***	P
SWRCB No:	36-000-024808-000037	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:		***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000042	***S Contain:***	
O Tank ID:	814-1	***Stg:***	P
SWRCB No:	36-000-024808-000042	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000044	***S Contain:***	
O Tank ID:	785-1	***Stg:***	P
SWRCB No:	36-000-024808-000044	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	1100	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000069	***S Contain:***	
O Tank ID:	676-SW OS	***Stg:***	W
SWRCB No:	36-000-024808-000069	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	3500	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000076	***S Contain:***	
O Tank ID:	678-1	***Stg:***	P
SWRCB No:	36-000-024808-000076	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	500	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000002	***S Contain:***	
O Tank ID:	AQUA -10	***Stg:***	W
SWRCB No:	36-000-024808-000002	***Storage :***	
Removed:		***Storag Type:***	WASTE
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	25000	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	TANK10A

Tank Details

Tank ID:	000094	***S Contain:***	
O Tank ID:	568-2	***Stg:***	P
SWRCB No:	36-000-024808-000094	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	2500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000108	***S Contain:***	
O Tank ID:	285-1	***Stg:***	P
SWRCB No:	36-000-024808-000108	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	500	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000019	***S Contain:***	
O Tank ID:	32000 D-3	***Stg:***	P
SWRCB No:	36-000-024808-000019	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	5655	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000023	***S Contain:***	
O Tank ID:	32000 T-4	***Stg:***	P
SWRCB No:	36-000-024808-000023	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50593	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000024	***S Contain:***	
O Tank ID:	32000 T-3	***Stg:***	P
SWRCB No:	36-000-024808-000024	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	JET FUEL
Capac:	50645	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000063	***S Contain:***	
O Tank ID:	700-1	***Stg:***	P
SWRCB No:	36-000-024808-000063	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	250	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000066	***S Contain:***	
O Tank ID:	690-3	***Stg:***	P
SWRCB No:	36-000-024808-000066	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	
Capac:	50000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000087	***S Contain:***	
O Tank ID:	643-1	***Stg:***	P
SWRCB No:	36-000-024808-000087	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	LEADED
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000093	***S Contain:***	
O Tank ID:	588-1	***Stg:***	P
SWRCB No:	36-000-024808-000093	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	DIESEL
Capac:	4000	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Tank Details

Tank ID:	000101	***S Contain:***	
O Tank ID:	550 T-7	***Stg:***	P
SWRCB No:	36-000-024808-000101	***Storage :***	
Removed:		***Storag Type:***	PRODUCT
Installed:		***P Contain:***	
A Date:	07-01-85	***Content:***	REG UNLEADED
Capac:	10279	***ONA:***	
Tank Use:	M.V. FUEL	***D File Name:***	TANK10A

Site: ***GEORGE AIR FORCE BASE OL-C/AFBDA SITE OT-51/SS-59 ENGINE TEST CELLS GEORGE AFB CA***

UST SWEEPS

C C:	I36-000-9640	***D Filename:***	NSITE1
BOE:		***Page No:***	129
Comp:	9640	***County:***	SAN BERNARDINO
Status:	INACTIVE	***State :***	CA
No of Tanks:	2	***Zip:***	92394
Jurisdict:	SAN BERNARDINO COUNTY	***Latitude:***	0
Agency:	ENVIRONMENTAL HEALTH - U.S.T.	***Longitude:***	0
Phone:	(619) 246-5360	***Georesult:***	N

Tank Details

Tank ID:	000001	***S Contain:***	NONE
O Tank ID:		***Stg:***	
SWRCB No:	36-000-009640-000001	***Storage :***	WASTE
Removed:	01-01-01	***Storag Type:***	WASTE
Installed:	01-01-01	***P Contain:***	BARE STEEL
A Date:		***Content:***	
Capac:	500	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	NTANK1

Tank Details

Tank ID:	000002	***S Contain:***	NONE
O Tank ID:		***Stg:***	
SWRCB No:	36-000-009640-000002	***Storage :***	WASTE
Removed:	01-01-01	***Storag Type:***	WASTE
Installed:	01-01-01	***P Contain:***	BARE STEEL
A Date:		***Content:***	
Capac:	500	***ONA:***	
Tank Use:	UNKNOWN	***D File Name:***	NTANK1

Site: ***WESTWINDS GOLF COURSE SO CALIF LOGISTICS AIRPORT VICTORVILLE CA***

WASTE DISCHG

Global ID:	WDR100036879	***Census Tract:***	6071980200
Site Facility Type:	* WDR SITE	***Longitude:***	
Cleanup Status:	HISTORICAL - WDR	***Latitude:***	
Address:	SO CALIF LOGISTICS AIRPORT		
City:	VICTORVILLE		
County:	SAN BERNARDINO		
State:	CA		
Zip:			

GeoTracker Search - Facilities

Site Facility Name:	WESTWINDS GOLF COURSE
Site Facility Type:	* WDR SITE
Cleanup Status:	HISTORICAL - WDR
Cleanup Stat Detail:	
Potential COC:	
CUF Claimno No:	
CUF Amount Paid:	
WDR Place Type:	Outdoor Event Venue
WDR File No:	
WDR Order No:	R6V-2003-0028
File Location:	
Address/Partial Add:	SO CALIF LOGISTICS AIRPORT
City:	VICTORVILLE
ZIP:	
County:	SAN BERNARDINO
Potential Media of Concern:	
User Defined Beneficial Use:	
Designated Beneficial Use:	MUN, AGR, IND, FRSH, AQUA
Designated Benefic Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Freshwater Replenishment, AQUA

Post Closure Site Management:
Future Land Use Reported:
CUF Priority Assigned:
Project Status: HISTORICAL - WDR AS OF 6/11/2003
DWR GW Sub Basin: Upper Mojave River Valley (6-042)
Calwater Watershed:
Cleanup Oversight Agencies:
Project Oversight Agencies: LAHONTAN RWQCB (REGION 6V) (LEAD)
CASE MANAGER: Sergio Alonso
Facility Type:
Composting Method:
Groundwater Monitoring Frq:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=WDR100036879
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=WDR100036879&tabname=regulatoryhistory
Site History:

No site history available

GeoTracker Search - Project Status History

Status: Open - Case Begin Date
Date: 6/11/2003

Status: Active - WDR
Date: 6/11/2003

Status: Historical - WDR
Date: 6/11/2003

Site: ***GEORGE AFB (L-7) DISPOSAL SITE***
GEORGE AFB CA 92392

WMUD

Wmu ID No:	6 360043NUR	***Npid:***	
Wds ID No:	6 360043NUR	***Rptf:***	
Swis ID No:	36-AA-0284	***Sic1:***	
Reg ID No:		***Sic2:***	
Edit Date:		***Swat Anms:***	U.S. AIR FORCE
Last Edit:		***Swat Fnms:***	GEORGE AFB (L-7) DISPOSAL SITE
Region:	6V	***Atyp:***	
County:	36	***Anms:***	U.S. AIR FORCE
Wds:	FALSE	***Adep:***	
Msw:	FALSE	***A Street:***	35 CGS/DEEV
Superorder:		***A City:***	GEORGE AFB
Sc15:	FALSE	***A Zip:***	92392
Swat:	TRUE	***A County:***	
Tpca:	FALSE	***Afon:***	7142692245
Rcra:	FALSE	***Lnms:***	U.S. AIR FORCE
Dod:	TRUE	***Ldep:***	
Rbpo:	C_S	***L Street:***	35 CGS/DEEV
Openpub:	FALSE	***L City:***	GEORGE AFB
Waste List:		***L State:***	CA
Tot Wmus:	1	***L Zip:***	92392
Secrange:	06N05W24	***L County:***	
Basemer:	SB	***Lfon:***	7142692245
Fcnt:		***Ttwq:***	
Fdep:		***Toxi:***	
F State:	CA	***Cplx:***	
Ffon:		***Wdrs:***	
Ftyp:		***Wtp1:***	
Tonnage:	0	***Wtp2:***	
Fac Comment:			

WMU Details

Wmu ID:	6 360043NUR-01	***G Monitor:***	FALSE
Edit Date:	18-May-1994	***S Monitor:***	FALSE
Last Edit:	JHMJHM	***V Monitor:***	FALSE

Wmu Type:	LANDFILL	***G Back:***	0
Wmu Name:	GEORGE AFB DISPOSAL SITE L-7	***S Back:***	0
Wmustatus:	CEASE DISCHARGE	***V Back:***	0
Wmu Size:		***G Nonback:***	0
Listed:		***S Nonback:***	0
Printed:		***V Nonback:***	0
Msw:	FALSE	***G Date:***	
Superorder:		***S Date:***	
Sc15:	FALSE	***V Date:***	
Swat:	TRUE	***Perm Test:***	
Tpca:	FALSE	***Gw Depth:***	0
Rcra:	FALSE	***Precip:***	0
Dod:	TRUE	***Site Alt:***	FALSE
Old Class:	UNKN	***Site Alta:***	FALSE
Old Waste:		***Line Alt:***	FALSE
Old First:		***Line Alta:***	FALSE
New Class:	UNK	***Lcrs Alt:***	FALSE
New Waste:		***Lcrs Alta:***	FALSE
New First:		***Composite:***	
Stat Date:		***Line Des:***	FALSE
Cap Year:		***Liner1:***	FALSE
Closeplan:	FALSE	***Line1 Type:***	
Township:		***Liner2:***	FALSE
Fault Name:	UNKNOWN	***Line2 Type:***	
Fault Distance:		***Liner3:***	FALSE
Withquake:	FALSE	***Line3 Type:***	
Type Op:			
Gen Com1:	CONSTRUCTION DEBRIS SITE.		
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:	FALSE		
Lcrs Type:			
Lcrs Des:	FALSE		
Cons Com1:			
Cons Com2:			
Cons Com3:			
Cons Com4:			

Site: ***GEORGE AFB (L-6,8,9) DISPOSAL***
GEORGE AFB CA 92392

WMUD

Wmu ID No:	6 360042NUR	***Npid:***	
Wds ID No:	6 360042NUR	***Rptf:***	
Swis ID No:	36-AA-0285	***Sic1:***	
Reg ID No:		***Sic2:***	
Edit Date:		***Swat Anms:***	U.S. AIR FORCE
Last Edit:		***Swat Fnms:***	GEORGE AFB (L-6,8,9) DISPOSAL SITE
Region:	6V	***Atyp:***	
County:	36	***Anms:***	U.S. AIR FORCE
Wds:	FALSE	***Adep:***	
Msw:	FALSE	***A Street:***	35 CGS/DEEV
Superorder:		***A City:***	GEORGE AFB
Sc15:	FALSE	***A Zip:***	92392
Swat:	TRUE	***A County:***	
Tpca:	FALSE	***Afon:***	7142692245
Rcra:	FALSE	***Lnms:***	U.S. AIR FORCE
Dod:	TRUE	***Ldep:***	
Rbpo:	C_S	***L Street:***	35 CGS/DEEV
Openpub:	FALSE	***L City:***	GEORGE AFB
Waste List:		***L State:***	CA
Tot Wmus:	1	***L Zip:***	92392

Secrange:	06N05W24	***L County:***	
Basemer:	SB	***Lfon:***	7142692245
Fcnt:		***Ttwq:***	
Fdep:		***Toxi:***	
F State:	CA	***Cplx:***	
Ffon:		***Wdrs:***	
Ftyp:		***Wtp1:***	
Tonnage:	0	***Wtp2:***	
Fac Comment:			

WMU Details

Wmu ID:	6 360042NUR-01	***G Monitor:***	FALSE
Edit Date:	15-Aug-1989	***S Monitor:***	FALSE
Last Edit:	JHM	***V Monitor:***	FALSE
Wmu Type:	LANDFILL	***G Back:***	0
Wmu Name:	GEORGE AFB DISPOSAL SITE L-6, 8, 9	***S Back:***	0
Wmustatus:	CEASE DISCHARGE	***V Back:***	0
Wmu Size:		***G Nonback:***	0
Listed:		***S Nonback:***	0
Printed:		***V Nonback:***	0
Msw:	FALSE	***G Date:***	
Superorder:		***S Date:***	
Sc15:	FALSE	***V Date:***	
Swat:	TRUE	***Perm Test:***	
Tpca:	FALSE	***Gw Depth:***	0
Rcra:	FALSE	***Precip:***	0
Dod:	TRUE	***Site Alt:***	FALSE
Old Class:	UNKN	***Site Alta:***	FALSE
Old Waste:		***Line Alt:***	FALSE
Old First:		***Line Alta:***	FALSE
New Class:	UNK	***Lcrs Alt:***	FALSE
New Waste:		***Lcrs Alta:***	FALSE
New First:		***Composite:***	
Stat Date:		***Line Des:***	FALSE
Cap Year:		***Liner1:***	FALSE
Closeplan:	FALSE	***Line1 Type:***	
Township:		***Liner2:***	FALSE
Fault Name:	UNKNOWN	***Line2 Type:***	
Fault Distance:		***Liner3:***	FALSE
Withquake:	FALSE	***Line3 Type:***	
Type Op:			
Gen Com1:			
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:	FALSE		
Lcrs Type:			
Lcrs Des:	FALSE		
Cons Com1:			
Cons Com2:			
Cons Com3:			
Cons Com4:			

Site: ***GEORGE AFB (L-10) DISPOSAL SIT***
GEORGE AFB CA 92392

WMUD

Wmu ID No:	6B360044NUR	***Npid:***	
Wds ID No:	6B360044NUR	***Rptf:***	
Swis ID No:	36-AA-0286	***Sic1:***	
Reg ID No:		***Sic2:***	

Edit Date:		***Swat Anms:***	U.S. AIR FORCE
Last Edit:		***Swat Fnms:***	GEORGE AFB (L-10) DISPOSAL SITE
Region:	6V	***Atyp:***	
County:	36	***Anms:***	U.S. AIR FORCE
Wds:	FALSE	***Adep:***	
Msw:	FALSE	***A Street:***	35 CGS/DEEV
Superorder:		***A City:***	GEORGE AFB
Sc15:	FALSE	***A Zip:***	92392
Swat:	TRUE	***A County:***	
Tpca:	FALSE	***Afon:***	7142692245
Rcra:	FALSE	***Lnms:***	U.S. AIR FORCE
Dod:	TRUE	***Ldep:***	
Rbpo:	C_S	***L Street:***	35 CGS/DEEV
Openpub:	FALSE	***L City:***	GEORGE AFB
Waste List:		***L State:***	CA
Tot Wmus:	1	***L Zip:***	92392
Secrange:	06N05W24	***L County:***	
Basemer:	SB	***Lfon:***	7142692245
Fcnt:		***Ttwq:***	
Fdep:		***Toxi:***	
F State:	CA	***Cplx:***	
Ffon:		***Wdrs:***	
Ftyp:		***Wtp1:***	
Tonnage:	0	***Wtp2:***	
Fac Comment:			

WMU Details

Wmu ID:	6B360044NUR-01	***G Monitor:***	FALSE
Edit Date:	26-Oct-1995	***S Monitor:***	FALSE
Last Edit:	JHMJHMJHM	***V Monitor:***	FALSE
Wmu Type:	LANDFILL	***G Back:***	0
Wmu Name:	US AIR FORCE-GEORGE AFB SITE L-10	***S Back:***	0
Wmustatus:	CEASE DISCHARGE	***V Back:***	0
Wmu Size:		***G Nonback:***	0
Listed:		***S Nonback:***	0
Printed:		***V Nonback:***	0
Msw:	FALSE	***G Date:***	
Superorder:		***S Date:***	
Sc15:	FALSE	***V Date:***	
Swat:	TRUE	***Perm Test:***	
Tpca:	FALSE	***Gw Depth:***	0
Rcra:	FALSE	***Precip:***	0
Dod:	TRUE	***Site Alt:***	FALSE
Old Class:	UNCL	***Site Alta:***	FALSE
Old Waste:		***Line Alt:***	FALSE
Old First:		***Line Alta:***	FALSE
New Class:	UNC	***Lcrs Alt:***	FALSE
New Waste:		***Lcrs Alta:***	FALSE
New First:		***Composite:***	
Stat Date:		***Line Des:***	FALSE
Cap Year:		***Liner1:***	FALSE
Closeplan:	FALSE	***Line1 Type:***	
Township:		***Liner2:***	FALSE
Fault Name:	UNKNOWN	***Line2 Type:***	
Fault Distance:		***Liner3:***	FALSE
Withquake:	FALSE	***Line3 Type:***	
Type Op:			
Gen Com1:	CONSTRUCTION DEBRIS SITE.		
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			

Lcrs:	FALSE
Lcrs Type:	
Lcrs Des:	FALSE
Cons Com1:	
Cons Com2:	
Cons Com3:	
Cons Com4:	

Site: ***GEORGE AFB DISP. AREA***
GEORGE AFB CA 92392

WMUD

Wmu ID No:	6B360332001	***Npid:***	
Wds ID No:	6B360332001	***Rptf:***	
Swis ID No:	36-AA-0076	***Sic1:***	
Reg ID No:		***Sic2:***	
Edit Date:		***Swat Anms:***	US AIR FORCE
Last Edit:		***Swat Fnms:***	GEORGE AFB DISP. AREA
Region:	6V	***Atyp:***	
County:	36	***Anms:***	US AIR FORCE
Wds:	FALSE	***Adep:***	
Msw:	FALSE	***A Street:***	35CGS/DEEV
Superorder:		***A City:***	GEORGE AFB
Sc15:	FALSE	***A Zip:***	92392
Swat:	TRUE	***A County:***	
Tpca:	FALSE	***Afon:***	7142692245
Rcra:	FALSE	***Lnms:***	US AIR FORCE
Dod:	TRUE	***Ldep:***	
Rbpo:	C_S	***L Street:***	35 CGS/DEEV
Openpub:	FALSE	***L City:***	GEORGE AFB
Waste List:		***L State:***	CA
Tot Wmus:	2	***L Zip:***	92392
Secrange:	06N05W24	***L County:***	
Basemer:	SB	***Lfon:***	7142692245
Fcnt:		***Ttwq:***	
Fdep:		***Toxi:***	
F State:	CA	***Cplx:***	
Ffon:		***Wdrs:***	
Ftyp:		***Wtp1:***	
Tonnage:	0	***Wtp2:***	
Fac Comment:			

WMU Details

Wmu ID:	6B360332001-01	***G Monitor:***	FALSE
Edit Date:	18-May-1994	***S Monitor:***	FALSE
Last Edit:	JHMJHM	***V Monitor:***	FALSE
Wmu Type:	LANDFILL	***G Back:***	0
Wmu Name:	GEORGE AFB BASE DISPOSAL AREA	***S Back:***	0
Wmustatus:		***V Back:***	0
Wmu Size:		***G Nonback:***	0
Listed:		***S Nonback:***	0
Printed:		***V Nonback:***	0
Msw:	FALSE	***G Date:***	
Superorder:		***S Date:***	
Sc15:	FALSE	***V Date:***	
Swat:	TRUE	***Perm Test:***	
Tpca:	FALSE	***Gw Depth:***	0
Rcra:	FALSE	***Precip:***	0
Dod:	TRUE	***Site Alt:***	FALSE
Old Class:	UNKN	***Site Alta:***	FALSE
Old Waste:		***Line Alt:***	FALSE
Old First:		***Line Alta:***	FALSE
New Class:	UNK	***Lcrs Alt:***	FALSE
New Waste:		***Lcrs Alta:***	FALSE
New First:		***Composite:***	
Stat Date:		***Line Des:***	FALSE
Cap Year:		***Liner1:***	FALSE
Closeplan:	FALSE	***Line1 Type:***	
Township:		***Liner2:***	FALSE

Fault Name:	UNKNOWN	***Line2 Type:***	
Fault Distance:		***Liner3:***	FALSE
Withquake:	FALSE	***Line3 Type:***	
Type Op:			
Gen Com1:	CHEMICAL TOILET SLUDGE SITE.		
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:	FALSE		
Lcrs Type:			
Lcrs Des:	FALSE		
Cons Com1:			
Cons Com2:			
Cons Com3:			
Cons Com4:			

WMU Details

Wmu ID:	6B360332001-02	***G Monitor:***	FALSE
Edit Date:	18-May-1994	***S Monitor:***	FALSE
Last Edit:	JHMJHMJHM	***V Monitor:***	FALSE
Wmu Type:	LANDFILL	***G Back:***	0
Wmu Name:	GEORGE NE RIPRAP PLACEMENT SITE B-3	***S Back:***	0
Wmustatus:	INACTIVE	***V Back:***	0
Wmu Size:		***G Nonback:***	0
Listed:		***S Nonback:***	0
Printed:		***V Nonback:***	0
Msw:	FALSE	***G Date:***	
Superorder:		***S Date:***	
Sc15:	FALSE	***V Date:***	
Swat:	TRUE	***Perm Test:***	
Tpca:	FALSE	***Gw Depth:***	0
Rcra:	FALSE	***Precip:***	0
Dod:	TRUE	***Site Alt:***	FALSE
Old Class:	UNKN	***Site Alta:***	FALSE
Old Waste:		***Line Alt:***	FALSE
Old First:		***Line Alta:***	FALSE
New Class:	UNK	***Lcrs Alt:***	FALSE
New Waste:		***Lcrs Alta:***	FALSE
New First:		***Composite:***	
Stat Date:		***Line Des:***	FALSE
Cap Year:		***Liner1:***	FALSE
Closeplan:	FALSE	***Line1 Type:***	
Township:		***Liner2:***	FALSE
Fault Name:	UNKNOWN	***Line2 Type:***	
Fault Distance:		***Liner3:***	FALSE
Withquake:	FALSE	***Line3 Type:***	
Type Op:			
Gen Com1:			
Gen Com2:			
Gen Com3:			
Gen Com4:			
Formation:	UNKNOWN		
Form Type:	UNKNOWN		
Form Permit:	UNKNOWN		
Form Com1:			
Form Com2:			
Form Com3:			
Form Com4:			
Liner Com:			
Lcrs:	FALSE		
Lcrs Type:			

Lcrs Des: FALSE
Cons Com1:
Cons Com2:
Cons Com3:
Cons Com4:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Currently on the Final NPL (F)' and/or the 'Site is Part of NPL Site (A)'. These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Jan 18, 2026

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Jan 18, 2026

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Jan 18, 2026

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Dec 26, 2025

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Dec 26, 2025

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Nov 30, 2025

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Nov 30, 2025

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste. This list also includes RCRAInfo sites that have notified as LQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Nov 30, 2025

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month. This list also includes RCRAInfo sites that have notified as SQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Nov 30, 2025

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Nov 30, 2025

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Nov 30, 2025

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Nov 30, 2025

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made available by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Jan 30, 2026

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Jan 30, 2026

Land Use Controls Information System: LUCIS

The Land Use Controls Information System (LUCIS) database is sourced from the U.S. Department of the Navy (DON). This data contains information for former Base Realignment and Closure (BRAC) properties across the United States. DON's BRAC office was tasked with tracking certain base closures while requiring the prevention of risks to human health and the environment of those properties with LUCs in place. Regarding currently available LUC Sites data, the sites listing is limited to centroid point locations for the overall installation property boundaries. Formerly obtained LUC Sites data may reflect site details that applied previously for a BRAC property.

Government Publication Date: Jun 13, 2024

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Jan 18, 2026

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Feb 8, 2026

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 8, 2025

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. The list includes FRP facilities sourced from the EPA FOIA office and from previously available Homeland Infrastructure Foundation-Level Data (HIFLD) file/s. Disclaimer: Per the EPA FOIA Office, the verification process for current requested FRP data is undergoing review and revision, and any similar reporting will be made public in Fiscal Year 2026. For this reason, the latest available FOIA file may be incomplete.

Government Publication Date: Jun 1, 2025

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jun 1, 2025

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 5, 2025

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Dec 26, 2025

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Jan 30, 2026

State

State Response Sites: RESPONSE

A list of identified confirmed release sites where the Department of Toxic Substances Control (DTSC) is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. This database serves a purpose similar to that of the federal NPL, functioning as a state-level counterpart for prioritizing cleanup efforts at hazardous substance release sites.

Government Publication Date: Oct 2, 2025

EnviroStor Database: ENVIROSTOR

The EnviroStor Data Management System is made available by the Department of Toxic Substances Control (DTSC). Includes Corrective Action sites, Tiered Permit sites, Historical Sites and Evaluation/Investigation sites. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Oct 2, 2025

Delisted State Response Sites: DELISTED ENVS

Sites removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC).

Government Publication Date: Oct 2, 2025

Solid Waste Information System (SWIS): SWF/LF

The Solid Waste Information System (SWIS) database made available by the Department of Resources Recycling and Recovery (CalRecycle) contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites.

Government Publication Date: Feb 20, 2026

Solid Waste Disposal Sites with Waste Constituents Above Hazardous Waste Levels: SWRCB SWF

This is a list of solid waste disposal sites identified by California State Water Resources Control Board with waste constituents above hazardous waste levels outside the waste management unit.

Government Publication Date: Sep 20, 2006

Waste Management Unit Database: WMUD

The Waste Management Unit Database System tracks and inventories waste management units. CCR Title 27 contains criteria stating that Waste Management Units are classified according to their ability to contain wastes. Containment shall be determined by geology, hydrology, topography, climatology, and other factors relating to the ability of the Unit to protect water quality. Water Code Section 13273.1 requires that operators submit a water quality solid waste assessment test (SWAT) report to address leak status. The WMUDS was last updated by the State Water Resources control board in 2000.

Government Publication Date: Jan 1, 2000

EnviroStor Hazardous Waste Facilities: HWP

A list of hazardous waste facilities including permitted, post-closure and historical facilities found in the Department of Toxic Substances Control (DTSC) EnviroStor database.

Government Publication Date: Oct 2, 2025

Sites Listed in the Solid Waste Assessment Test (SWAT) Program Report: SWAT

In a 1993 Memorandum of Understanding, the State Water Resources Control Board (SWRCB) agreed to submit a comprehensive report on the Solid Waste Assessment Test (SWAT) Program to the California Integrated Waste Management Board (CIWMB). This report summarizes the work completed to date on the SWAT Program, and addresses both the impacts that leakage from solid waste disposal sites (SWDS) may have upon waters of the State and the actions taken to address such leakage.

Government Publication Date: Dec 31, 1995

Construction and Demolition Debris Recyclers: C&D DEBRIS RECY

This listing of Construction and Demolition Debris Recyclers is maintained by the California Integrated Waste Management Board-common C&D materials include lumber, drywall, metals, masonry (brick, concrete, etc.), carpet, plastic, pipe, rocks, dirt, paper, cardboard, or green waste related to land development.

Government Publication Date: Jun 20, 2018

Recycling Centers: RECYCLING

This list of Certified Recycling Centers that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Feb 10, 2026

Listing of Certified Processors: PROCESSORS

This list of Certified Processors that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Feb 20, 2026

Listing of Certified Dropoff, Collection, and Community Service Programs: CONTAINER RECY

This list of Certified Dropoff, Collection, and Community Service Programs (non-buyback) operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Jul 18, 2025

Land Disposal Sites: LDS

Land Disposal Sites in GeoTracker, the State Water Resources Control Board (SWRCB)'s data management system. The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units. Waste management units include waste piles, surface impoundments, and landfills.

Government Publication Date: Aug 11, 2025

Leaking Underground Fuel Tank Reports: LUST

List of Leaking Underground Storage Tanks within the Cleanup Sites data in GeoTracker database. GeoTracker is the State Water Resources Control Board's (SWRCB) data management system for managing sites that impact groundwater, especially those that require groundwater cleanup (Underground Storage Tanks, Department of Defense and Site Cleanup Program) as well as permitted facilities such as operating Underground Storage Tanks. The Leak Prevention Program that overlooks LUST sites is the SWRCB in California's Environmental Protection Agency.

Government Publication Date: Sep 14, 2025

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Underground Storage Tanks (LUST) cleanup sites removed from GeoTracker, the State Water Resources Control Board (SWRCB)'s database system, as well as sites removed from the SWRCB's list of UST Case closures.

Government Publication Date: Jan 27, 2026

Permitted Underground Storage Tank (UST) in GeoTracker: UST

List of Permitted Underground Storage Tank (UST) sites, Single Walled UST sites, and Abandoned UST sites made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA).

Government Publication Date: Feb 20, 2026

Proposed Closure of Underground Storage Tank Cases: UST CLOSURE

This listing includes Proposed Closure of Underground Storage Tank (UST) Cases which are being considered for closure by either the State Water Resources Control Board at a Future Board Meeting or the Executive Director that have been posted for a 60-day public comment period, and Closure of UST Cases with Closure Denials and Approved Orders. The lists are provided by the California Water Boards.

Government Publication Date: Jan 27, 2026

Historical Hazardous Substance Storage Information Database: HHSS

The Historical Hazardous Substance Storage database contains information collected in the 1980s from facilities that stored hazardous substances. The information was originally collected on paper forms, was later transferred to microfiche, and recently indexed as a searchable database. When using this database, please be aware that it is based upon self-reported information submitted by facilities which has not been independently verified. It is unlikely that every facility responded to the survey and the database should not be expected to be a complete inventory of all facilities that were operating at that time. This database is maintained by the California State Water Resources Control Board's (SWRCB) Geotracker.

Government Publication Date: Aug 27, 2015

Statewide Environmental Evaluation and Planning System: UST SWEEPS

The Statewide Environmental Evaluation and Planning System (SWEEPS) is a historical listing of active and inactive underground storage tanks made available by the California State Water Resources Control Board (SWRCB).

Government Publication Date: Oct 1, 1994

Aboveground Storage Tanks: AST

A statewide list from 2009 of aboveground storage tanks (ASTs) made available by the Cal FIRE Office of the State Fire Marshal (OSFM). This list is no longer maintained or updated by the Cal FIRE OSFM.

Government Publication Date: Aug 31, 2009

SWRCB Historical Aboveground Storage Tanks: AST SWRCB

A list of aboveground storage tanks made available by the California State Water Resources Control Board (SWRCB). Effective January 1, 2008, the Certified Unified Program Agencies (CUPAs) are vested with the responsibility and authority to implement the Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Dec 1, 2007

Oil and Gas Facility Tanks: TANK OIL GAS

Locations of oil and gas tanks that fall under the jurisdiction of the Geologic Energy Management Division of the California Department of Conservation (CalGEM) (CCR 1760). CalGEM was formerly the Division of Oil, Gas, and Geothermal Resources (DOGGR).

Government Publication Date: Apr 1, 2026

Delisted Storage Tanks: DELISTED TNK

This database contains a list of storage tank sites that were removed by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA) and the Cal FIRE Office of State Fire Marshal (OSFM).

Government Publication Date: Apr 1, 2026

California Environmental Reporting System (CERS) Tanks: CERS TANK

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials. This data also includes military underground storage tank sites sourced from the CalEPA's Water Boards' GeoTracker system.

Government Publication Date: Jan 12, 2026

Delisted California Environmental Reporting System (CERS) Tanks: DELISTED CTNK

This database contains a list of Aboveground Petroleum Storage and Underground Storage Tank sites that were removed from in the California Environmental Protection Agency (CalEPA) Regulated Site Portal.

Government Publication Date: Jan 12, 2026

Historical Hazardous Substance Storage Container Information - Facility Summary: HIST TANK

The State Water Resources Control Board maintained the Hazardous Substance Storage Containers listing and inventory in the 1980s. This facility summary lists historic tank sites where the following container types were present: farm motor vehicle fuel tanks; waste tanks; sumps; pits, ponds, lagoons, and others; and all other product tanks. This set, published in May 1988, lists facility and owner information, as well as the number of containers. This data is historic and will not be updated.

Government Publication Date: May 27, 1988

Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions: LUR

The Department of Toxic Substances Control (DTSC) Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents land use restrictions that are active. Some sites have multiple land use restrictions.

Government Publication Date: Oct 2, 2025

CALSITES Database: CALSITES

This historical database was maintained by the Department of Toxic Substance Control (DTSC) for more than a decade. CALSITES contains information on Brownfield properties with confirmed or potential hazardous contamination. In 2006, DTSC introduced EnviroStor as the latest Brownfields site database.

Government Publication Date: May 1, 2004

Hazardous Waste Management Program Facility Sites with Deed / Land Use Restrictions: HLUR

The Department of Toxic Substances Control (DTSC) Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Government Publication Date: Feb 18, 2021

Deed Restrictions and Land Use Restrictions: DEED

List of Deed Restrictions, Land Use Restrictions and Covenants in GeoTracker made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency. A deed restriction (land use covenant) may be required to facilitate the remediation of past environmental contamination and to protect human health and the environment by reducing the risk of exposure to residual hazardous materials.

Government Publication Date: Sep 13, 2025

Voluntary Cleanup Program: VCP

List of sites in the Voluntary Cleanup Program made available by the Department of Toxic Substances and Control (DTSC). The Voluntary Cleanup Program was designed to respond to lower priority sites. Under the Voluntary Cleanup Program, DTSC enters site-specific agreements with project proponents for DTSC oversight of site assessment, investigation, and/or removal or remediation activities, and the project proponents agree to pay DTSC's reasonable costs for those services.

Government Publication Date: Oct 2, 2025

GeoTracker Cleanup Program Sites: CLEANUP SITES

A list of Cleanup Program sites in the state of California made available by The State Water Resources Control Board (SWRCB) of the California Environmental Protection Agency (EPA). SWRCB tracks leaking underground storage tank cleanups as well as other water board cleanups.

Government Publication Date: Sep 14, 2025

Delisted Cleanup Program Sites: DELISTED CLEANUP

A list of Cleanup Program sites which were once included - and have since been removed from - the list of Cleanup Program Sites in GeoTracker. GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Government Publication Date: Sep 14, 2025

Delisted County Records: DELISTED COUNTY

Records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Mar 17, 2026

Delisted County Tanks: DELISTED COUNTY TANK

Storage Tank records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Mar 4, 2026

Delisted County Leaking Tanks: DELISTED COUNTY LTANK

Leaking Storage tank records removed from county or CUPA databases.

Government Publication Date: Mar 4, 2026

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 9, which includes California, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 21, 2025

Underground Storage Tanks on Tribal/Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 9, which includes California, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 21, 2025

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 21, 2025

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 21, 2025

County

San Bernardino County - CUPA List: SANBERN CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Bernardino County. This list is made available by San Bernardino County Fire Department which is the CUPA for all areas of the County except the city of Victorville.

Government Publication Date: Sep 17, 2024

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's (EPA) Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. This dataset is sourced from the EPA's PFAS Analytic Tools, and it includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified as PFAS based on EPA's CompTox Chemicals Dashboard lists of PFAS with defined and undefined structures. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: Mar 2, 2026

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Oct 8, 2025

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Jan 1, 2026

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Dec 29, 2025

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2025 per agency entity dataset. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: May 30, 2025

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Aug 1, 2025

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Feb 16, 2026

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Feb 2, 2026

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest: PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Feb 14, 2026

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The dataset was developed from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors, based on the North American Industry Classification System (NAICS) Codes and Standard Industrial Classification (SIC) Codes associated federal regulatory programs (e.g., Clean Water Act, Clean Air Act, and Resource Conservation and Recovery Act) at the facility level; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Feb 16, 2026

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: Jan 29, 2026

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Dec 26, 2025

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: Oct 18, 2025

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jan 24, 2026

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites which once appeared on - and have since been removed from - the list of drycleaner facilities included in Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jan 24, 2026

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: Jul 10, 2025

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 8, 2025

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: Oct 30, 2025

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). The intent of the site location is to provide a general reference point to the site on a national scale. The coordinates of each site point can be the location of a site monument, the centroid of the site boundary, or a general location of the site. This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Nov 6, 2025

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the U.S. Department of Energy's (DOE) Alternative Fuels Data Center (AFDC) and National Renewable Energy Laboratory (NREL). The DOE's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Mar 11, 2026

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Dec 30, 2025

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Sep 26, 2025

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Aug 12, 2025

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Jun 5, 2025

Historical Business Activity Risk: HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

NPDES Biosolids Program Permit Holders: NPDES BIOSOLIDS

This Water National Pollutant Discharge Elimination System (NPDES) Biosolids Permits list is sourced from the U.S. Environmental Protection Agency's (EPA) Enforcement and Compliance History Online data. EPA's Integrated Compliance Information System (ICIS) for NPDES includes facility and compliance information for NPDES permits in the ECHO Biosolids facility universe. Per the EPA, when sewage from households and businesses (and sometimes wastewater from industrial dischargers) is sent to a wastewater treatment plant, the liquids are separated from the solids, producing a semi-solid, nutrient-rich product known as "sewage sludge" or "biosolids". The EPA typically uses the term "biosolids" to mean sewage sludge that has been treated to meet the agency's regulatory requirements and is intended to be land applied as a soil conditioner or fertilizer.

Government Publication Date: Feb 7, 2026

State

PFAS Sampling Locations: PFAS SAMPLING

This data is sourced from the State Water Board's GeoTracker Per- and Polyfluoroalkyl Substances (PFAS) Map tool which contains individual sampling points (i.e., soil boring, groundwater monitoring well, drinking water well for municipal drinking water systems, etc.) or a site location with PFAS analytical data. Includes analytical results that are finalized and submitted electronically by the Responsible Parties via GeoTracker's Electronic Submittal of Information Portal, and after it's accepted by a Regional Water Quality Control Board.

Government Publication Date: Mar 4, 2026

Dry Cleaning Facilities: DRYCLEANERS

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial, linen supply, commercial laundry, dry cleaning and pressing machines - Coin Operated Laundry and Dry Cleaning. This is provided by the Department of Toxic Substance Control.

Government Publication Date: Dec 20, 2021

Delisted Drycleaners: DELISTED DRYCLEANERS

Sites removed from the list of drycleaner related facilities that have EPA ID numbers, made available by the California Department of Toxic Substance Control.

Government Publication Date: Aug 3, 2023

Non-Toxic Dry Cleaning Incentive Program: DRYC GRANT

This list of past Non-Toxic Dry Cleaning Incentive Program grant award recipients is provided by the California Air Resources Board (CARB). The program provided grants to eligible dry cleaning businesses to assist them in transitioning away from perchloroethylene (Perc) machines to alternative non-toxic and non-smog forming technologies such as water-based and CO2 cleaning systems. Per the CARB, this program ended in January 2023 and the information is historical.

Government Publication Date: Aug 3, 2023

PFAS GeoTracker Cleanup Sites: PFAS GT CLEANUPS

A list of applicable cleanup sites from the State Water Resources Control Board's (SWRCB) GeoTracker data management system where one or more of the potential contaminants of concern are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA).

Government Publication Date: Sep 13, 2025

PFOA/PFOS Groundwater: PFAS GW

A list of water wells from the Groundwater Ambient Monitoring and Assessment Program (GAMA) Groundwater Information System with the groundwater chemical perfluorooctanoic acid (PFOA) (NL = 0.014 UG/L) or perfluorooctanoic sulfonate (PFOS) (NL = 0.013 UG/L). The GAMA Groundwater Information System search is made available by California Water Boards.

Government Publication Date: Feb 21, 2026

PFAS Investigations: PFAS INVEST

This list of potential Per- and Polyfluoroalkyl Substance (PFAS) sites is compiled from the California State Water Resources Control Board's (SWRCB) PFAS Investigations Map tool. The SWRCB issued investigative orders, per California Water Code (CWC) Section 13267 and/or 13383, to these sites. Orders were also issued to the public water systems to sample wells in the vicinity of these locations. Military facilities have been identified by the Department of Defense (DOD) as part of their efforts to investigate PFAS per the Defense Environmental Restoration Program (DERP) under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). The data includes locations for Airports, Chrome Plating Facilities, Landfills, Publicly Owned Treatment Works, Refineries and Bulk Terminals, DOD Facilities, and Monitored Drinking Water Wells being investigated for potential PFAS.

Government Publication Date: Jan 23, 2024

Hazardous Waste and Substances Site List - Site Cleanup: HWSS CLEANUP

The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements in providing information about the location of hazardous materials release sites. This list is published by California Department of Toxic Substance Control.

Government Publication Date: Mar 15, 2023

Toxic Pit Cleanup Act Sites: TOXIC PITS

The Toxic Pits Cleanup Act (TPCA) list identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. This list was maintained by the State Water Resources Control Board (SWRCB), is not longer maintained, and updates are not planned.

Government Publication Date: Jul 1, 1995

List of Hazardous Waste Facilities Subject to Corrective Action: DTSC HWF

This is a list of hazardous waste facilities identified in Health and Safety Code (HSC) § 25187.5. These facilities are those where Department of Toxic Substances Control (DTSC) has taken or contracted for corrective action because a facility owner/operator has failed to comply with a date for taking corrective action in an order issued under HSC § 25187, or because DTSC determined that immediate corrective action was necessary to abate an imminent or substantial endangerment.
Government Publication Date: Jul 18, 2016

EnviroStor Inspection, Compliance, and Enforcement: INSP COMP ENF
A list of permitted facilities with inspections and enforcements tracked by the California Department of Toxic Substance Control's (DTSC) EnviroStor data management system.
Government Publication Date: Feb 9, 2026

School Property Evaluation Program Sites: SCH
A list of sites registered with The Department of Toxic Substances Control (DTSC) School Property Evaluation and Cleanup (SPEC) Division. SPEC is responsible for assessing, investigating and cleaning up proposed school sites. The Division ensures that selected properties are free of contamination or, if the properties were previously contaminated, that they have been cleaned up to a level that protects the students and staff who will occupy the new school.
Government Publication Date: Oct 2, 2025

California Hazardous Material Incident Report System (CHMIRS): CHMIRS
A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS). This listing has been made available by the California Governor's Office of Emergency Services (Cal OES).
Government Publication Date: Jul 11, 2025

Historical California Hazardous Material Incident Report System (CHMIRS): HIST CHMIRS
A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS) prior to 1993. This list has been made available by the California Office of Emergency Services (OES).
Government Publication Date: Jan 1, 1993

Handlers from Hazardous Waste Manifest Data: HAZNET
A list of handlers not otherwise classified as Treatment, Storage, Disposal facilities (TSDF) or generators from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).
Government Publication Date: Feb 20, 2025

Generators from Hazardous Waste Manifest Data: HAZ GEN
List of handlers listed as having generated waste from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).
Government Publication Date: Feb 20, 2025

TSDF from Hazardous Waste Manifest Data: HAZ TSD
List of Treatment, Storage, and Disposal Facilities (TSDFs) from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).
Government Publication Date: Feb 20, 2025

Historical Hazardous Waste Manifest Data: HIST MANIFEST
A list of historic hazardous waste manifests received by the Department of Toxic Substances Control (DTSC) from year the 1980 to 1992. The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.
Government Publication Date: Dec 31, 1992

DTSC Registered Hazardous Waste Transporters: HW TRANSPORT
The California Department of Toxic Substances Control (DTSC) maintains this list of Registered Hazardous Waste Transporters.
Government Publication Date: Feb 20, 2026

Registered Waste Tire Haulers: WASTE TIRE
This list of registered waste tire haulers is maintained by the California Department of Resources Recycling and Recovery.
Government Publication Date: Mar 22, 2026

California Medical Waste Management Program Facility List: MEDICAL WASTE

This list of Medical Waste Management Program Facilities is maintained by the California Department of Public Health. The Medical Waste Management Program (MWMP) regulates the generation, handling, storage, treatment, and disposal of medical waste by providing oversight for the implementation of the Medical Waste Management Act (MWMA). The MWMP permits and inspects all medical waste off-site treatment facilities, medical waste transporters, and medical waste transfer stations. This list contains transporters, treatment, and transfer facilities.

Government Publication Date: Jan 20, 2026

Historical Cortese List: HIST CORTESE

List of sites which were once included on the Cortese list. The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements for providing information about the location of hazardous sites.

Government Publication Date: Nov 13, 2008

Cease and Desist Orders and Cleanup and Abatement Orders: CDO/CAO

The California Environment Protection Agency "Cortese List" of active Cease and Desist Orders (CDO) and Cleanup and Abatement Orders (CAO). This list contains many CDOs and CAOs that do NOT concern the discharge of wastes that are hazardous materials. Many of the listed orders concern, as examples, discharges of domestic sewage, food processing wastes, or sediment that do not contain hazardous materials, but the Water Boards' database does not distinguish between these types of orders.

Government Publication Date: Dec 6, 2021

California Environmental Reporting System (CERS) Hazardous Waste Sites: CERS HAZ

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Jan 12, 2026

Delisted Environmental Reporting System (CERS) Hazardous Waste Sites: DELISTED HAZ

This database contains a list of sites that were removed from the California Environmental Protection Agency (CalEPA) in the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator.

Government Publication Date: Nov 29, 2018

Sites in GeoTracker: GEOTRACKER

GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. This is a list of sites in GeoTracker that aren't otherwise categorized as LUST, Land Disposal Sites (LDS), Cleanup Sites, or sites having Waste Discharge Requirements (WDR). This listing includes program types such as Underground Injection Control (UIC), Confined Animal Facilities (CAF), Irrigated Lands Regulatory Program, plans, and non-case information.

Government Publication Date: Aug 11, 2025

Mines Listing: MINE

This list includes mine site locations extracted from the Mines Online database, maintained by the California Department of Conservation. Mines Online (MOL) is an interactive web map designed with GIS features that provide information such as the mine name, mine status, commodity sold, location, and other mine specific data. Please note: Mine location information is provided to assist experts in determining the location of mine operators in accordance with California Civil Code section 1103.4 and reflects information reported by mine operators in annual reports provided under Public Resources Code section 2207. While the Division of Mine Reclamation (DMR) attempts to populate MOL with accurate location information, the DMR cannot guarantee the accuracy of operator reported location information.

Government Publication Date: Oct 25, 2025

Recorded Environmental Cleanup Liens: LIEN

The California Department of Toxic Substance Control (DTSC) maintains this list of liens placed upon real properties. A lien is utilized by the DTSC to obtain reimbursement from responsible parties for costs associated with the remediation of contaminated properties.

Government Publication Date: Feb 5, 2026

Waste Discharge Requirements: WASTE DISCHG

List of sites in California State Water Resources Control Board (SWRCB) Waste Discharge Requirements (WDRs) Program in California, made available by the SWRCB via GeoTracker. The WDR program regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Government Publication Date: Aug 11, 2025

Toxic Pollutant Emissions Facilities: EMISSIONS

A list of criteria and toxic pollutant emissions data for facilities in California made available by the California Environmental Protection Agency - Air Resources Board (ARB). Risk data may be based on previous inventory submittals. The toxics data are submitted to the ARB by the local air districts as requirement of the Air Toxics "Hot Spots" Program.

Government Publication Date: Dec 31, 2023

Clandestine Drug Lab Sites: CDL

The Department of Toxic Substances Control (DTSC) maintains a listing of drug lab sites. DTSC is responsible for removal and disposal of hazardous substances discovered by law enforcement officials while investigating illegal/clandestine drug laboratories.

Government Publication Date: Dec 13, 2024

Tribal

No Tribal additional environmental record sources available for this State.

County

San Bernardino County - Medical Waste Facility List: MED WST SANBERN

This list of San Bernardino County medical waste facilities is maintained by the County of San Bernardino Department of Public Health Medical Waste Program. The Medical Waste Program regulates generators of medical waste based on the Medical Waste Management Act. The program inspects medical waste facilities, facilities with on-site medical waste treatment units, and common storage areas annually. This program also investigates complaints regarding mishandling of medical waste and facilities that may be operating without a valid health permit. Some facilities that may generate medical waste include hospitals, skilled nursing facilities, blood banks, and doctors, dental and veterinarian offices.

Government Publication Date: Oct 6, 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

SUBJECT PROPERTY PHOTOGRAPHS

Phase I Environmental Site Assessment Report
Adelanto Gateway Logistics Center
Adelanto, California
Farallon PN: 4001-001.001

Photograph 1. Northwestern boundary of Subject Property, looking south.

Photograph 2. Northeastern boundary of Subject Property, looking southwest.

Photograph 3. Eastern Subject Property boundary, looking west.

Photograph 4. Southern boundary of central portion of Subject Property, looking north.

Photograph 5. Southwestern boundary of Subject Property, looking northeast.

Photograph 6. Unnamed dirt road on western portion of Subject Property, looking south.

Photograph 7. Debris on southern portion of Subject Property, looking east.

Photograph 8. Northwest-adjoining Kinder Morgan pipeline easement on Air Base Road, looking north.

Photograph 9. Northwest-adjoining Kinder Morgan Terminal, looking north.

Photograph 10. Northwest-adjoining undeveloped land, residential and commercial properties, looking north.

Photograph 11. North-adjoining Kinder Morgan pipeline easement on Air Base Road and undeveloped land, looking north.

Photograph 12. North-adjoining DHL Supply Chain facility, looking north.

Photograph 13. East-adjoining Federal Correction Complex, looking east.

Photograph 14. South-adjoining powerlines and undeveloped land, looking south.

Photograph 15. South-adjoining Mobile Pipe Lining & Coating, looking south.


Photograph 16. South-adjoining Soil Safe of California, looking south.

Photograph 17. South-adjoining United Truck Trailer Storage Yard, looking southwest.

Photograph 18. Southwest-adjoining XPO & Fast Lane Transportation, looking southwest.

Photograph 19. West-adjoining commercial and industrial properties, looking northwest.

Photograph 20. West-adjoining undeveloped land, looking west.



Map: 1.0 Mile Radius


Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius

Order Number: 26040900380


Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 26040900380

Address: ADELANTO GATEWAY LOGISTICS CENTER, Adelanto, CA

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.