Appendix D: Phase I Environmental Site Assessment

Page Intentionally Left Blank

ProTech

1208 MAIN STREET, REDWOOD CITY, CA 94063
TELE: 650.569.4020 / FAX: 650.569.4023

PHASE I - ENVIRONMENTAL SITE ASSESSMENT

CONDUCTED AT:

1214 - 1220 DONNELLY, BURLINGAME, CA

PREPARED FOR:

JOHN BRITTON
W. J. BRITTON & CO
1345 MISSION ST., SAN FRANCISCO, CA 94103
JFBRITT@PACBELL.NET

7 SEPTEMBER 2016

PHASE I - ENVIRONMENTAL SITE ASSESSMENT

CONDUCTED AT:

1214 - 1220 DONNELLY, BURLINGAME, CA

PREPARED FOR:

JOHN BRITTON
W. J. BRITTON & CO
1345 MISSION ST., SAN FRANCISCO, CA 94103
JFBRITT@PACBELL.NET

PREPARED BY:

PROTECH CONSULTING & ENGINEERING
1208 MAIN STREET, REDWOOD CITY, CA 94063
info@protech-cal.com

PROTECH PROJECT #601-OH16

7 SEPTEMBER 2016



SHERWOOD LOVEJOY, JR.
ENVIRONMENTAL ASSESSOR
CONSULTING HYDROGEOLOGIST

CERTIFICATION

"WE DECLARE THAT, TO THE BEST OF OUR PROFESSIONAL KNOWLEDGE AND BELIEF, WE MEET THE DEFINITION OF ENVIRONMENTAL PROFESSIONALS AS DEFINED IN §312.10 OF THIS PART."

"WE HAVE THE SPECIFIC QUALIFICATIONS BASED ON EDUCATION, TRAINING, AND EXPERIENCE TO ASSESS A PROPERTY OF THE NATURE, HISTORY, AND SETTING OF THE SP. WE HAVE DEVELOPED AND PERFORMED THE ALL APPROPRIATE INQUIRIES IN CONFORMANCE WITH THE STANDARDS AND PRACTICES SET FORTH IN 40 CFR PART 312."

LIMITATION

THIS PHASE I - ENVIRONMENTAL SITE ASSESSMENT REPORT (REPORT) HAS BEEN PREPARED BY PROTECH CONSULTING & ENGINEERING (PROTECH) FOR THE EXCLUSIVE USE OF PROTECH AND **COMMUNITY SCHOOL OF MUSIC AND ARTS** (CLIENT), AND NOT FOR USE BY ANY OTHER PARTY. ANY USE BY A THIRD PARTY OF ANY OF THE INFORMATION CONTAINED IN THIS REPORT SHALL BE AT THEIR OWN RISK AND SHALL CONSTITUTE A RELEASE AND AN AGREEMENT TO DEFEND AND INDEMNIFY PROTECH FROM AND AGAINST ANY AND ALL LIABILITY IN CONNECTION THEREWITH WHETHER ARISING OUT OF PROTECH'S NEGLIGENCE OR OTHERWISE.

ALL INTERPRETATIONS, CONCLUSIONS, AND RECOMMENDATIONS ARE BASED SOLELY ON INFORMATION GATHERED DURING THIS INVESTIGATIVE STAGE AND ON NO OTHER UNSPECIFIED INFORMATION. THIS REPORT IS PREPARED AS A TOOL FOR THE CLIENT TO USE IN DETERMINING THE CONDITION OF THE SP. THIS REPORT MAKES NO CERTIFICATION, EITHER IMPLIED OR OTHERWISE, THAT THE SP IS FREE FROM CONTAMINATION; IT SIMPLY REPORTS THE FINDINGS OF THE STUDY. SAMPLING, IF PERFORMED, IS SO SAMPLE SPECIFIC THAT IF CONTAMINANTS ARE NOT FOUND IN A SAMPLE IT DOES NOT UNIVERSALLY SUGGEST THAT THERE ARE NONE OF THESE CONTAMINANTS PRESENT AT THE SP. IT WOULD BE EXTREMELY DIFFICULT, IMPRACTICAL AND COSTLY TO CERTIFY THAT A SP WAS COMPLETELY FREE OF CONTAMINANTS AND A PHASE I - ENVIRONMENTAL SITE ASSESSMENT IS NOT INTENDED TO DO SO.

THE RESULTS AND FINDINGS CONTAINED IN THIS REPORT ARE BASED ON CERTAIN INFORMATION FROM SOURCES OUTSIDE THE CONTROL OF PROTECH. WHILE EXERCISING ALL REASONABLE DILIGENCE IN THE ACCEPTANCE AND USE OF INFORMATION PROVIDED, PROTECH DOES NOT WARRANT OR GUARANTEE THE ACCURACY THEREOF. THE REPORT WAS DEVELOPED SPECIFICALLY FOR THIS PROJECT (**1214-1220 DONNELLY AVENUE, BURLINGAME, CA, APNS: 029-151-150, 029-151-160, 029-151-170**) AND SHOULD NOT BE USED FOR ANY OTHER SITE.

THIS REPORT IS COVERED BY COPYRIGHT LAW. ANY REPRODUCTION, EITHER IN TOTAL OR IN PART, WITHOUT THE PERMISSION OF PROTECH IS PROHIBITED.

RECS, CRECS, HRECS AND DE MINIMIS DEFINITIONS[1]

3.2.78 *recognized environmental conditions*—the presence or likely presence of any *hazardous substances* or *petroleum products* in, on, or at a *property*: (*1*) due to release to the environment; (*2*) under conditions indicative of a *release* to the *environment*; or (*3*) under conditions that pose a *material threat* of a future *release* to the *environment*. *De minimis conditions* are not *recognized environmental conditions*.

3.2.18 *controlled recognized environmental condition*[2]—a *recognized environmental condition* resulting from a past *release* of *hazardous substances* or *petroleum products* that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, *property* use restrictions, *activity and use limitations*, *institutional controls*, or *engineering controls*). (See Note 2.) A condition considered by the *environmental professional* to be a *controlled recognized environmental condition* shall be listed in the findings section of the *Phase I Environmental Site Assessment report*, and as a *recognized environmental condition* in the conclusions section of the *Phase I Environmental Site Assessment report*. (See Note 3.)

3.2.42 *historical recognized environmental condition*—a past *release* of any *hazardous substances* or *petroleum products* that has occurred in connection with the *property* and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the *property* to any required controls (for example, *property* use restrictions, *activity and use limitations*, *institutional controls*, or *engineering controls*). Before calling the past *release* a *historical recognized environmental condition*, the *environmental professional* must determine whether the past *release* is a *recognized environmental condition* at the time the *Phase I Environmental Site Assessment* is conducted (for example, if there has been a change in the regulatory criteria). If the EP considers the past *release* to be a *recognized environmental condition* at the time the Phase I ESA is conducted, the condition shall be included in the conclusions section of the report as a *recognized environmental condition*.

3.2.22 *de minimis condition*—a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis conditions* are not *recognized environmental conditions* or *controlled recognized environmental conditions*.

[1] From ASTM E1527-13.

[2] NOTE 2—For example, if a leaking underground storage tank has been cleaned up to a commercial use standard, but does not meet unrestricted residential cleanup criteria, this would be considered a controlled recognized environmental condition. The "control" is represented by the restriction that the property use remains commercial.
NOTE 3—A condition identified as a *controlled recognized environmental condition* does not imply that the *environmental professional* has evaluated or confirmed the adequacy, implementation, or continued effectiveness of the required control that has been, or is intended to be, implemented.

TABLE OF CONTENTS

CERTIFICATION 3

LIMITATION 3

RECS, CRECS, HRECS AND DE MINIMIS DEFINITIONS 4

TABLE OF CONTENTS 5

TABLES IN TEXT 7

LIST OF ATTACHED TABLES 7

LIST OF ATTACHED FIGURES 8

LIST OF APPENDICES 8

EXECUTIVE SUMMARY 9

1.0 - INTRODUCTION 16

1.1 - INTRODUCTION 16
1.2 - SCOPE-OF-WORK 16
1.3 – LIMITATION OF STUDY/DATA GAPS 17
1.4 – CLIENT PROVIDED INFORMATION 17
1.5 – KEY SITE MANAGER 17

2.0 - SUBJECT PROPERTY INSPECTION 18

2.1 - INTRODUCTION 18
2.2 - SUBJECT PROPERTY DESCRIPTION 18
2.3 - PROPERTY INSPECTION 18
2.4 – AREA/NEIGHBORHOOD DRIVE-BY 20

3.0 - DATABASE SEARCH AND REVIEW 21

3.1 - INTRODUCTION 21
3.2 – SUBJECT PROPERTY 21

3.3 - INSIDE ONE-EIGHTH MILE RADIUS SURVEY 22
3.4 - ONE-EIGHTH MILE TO ONE-QUARTER MILE RADIUS SURVEY 23
3.5 - ONE-QUARTER MILE TO ONE-HALF MILE RADIUS SURVEY 25
3.6 – ONE-HALF MILE TO ONE MILE RADIUS SURVEY 25
3.7 – OVER ONE MILE RADIUS SURVEY 25
3.8 - UNMAPPED SITES 26

4.0 - HISTORICAL INFORMATION REVIEW 27

4.1 - INTRODUCTION 27
4.2 – HISTORICAL TOPOGRAPHIC MAPS 27
4.3 - SANBORN® MAPS 27
4.4 - HISTORICAL AERIAL PHOTOGRAPHS 28
4.5 – CITY DIRECTORY 28
4.6 – ENVIRONMENTAL LIENS AND AUL REPORT 29
4.7 – PROPERTY TAX MAP REPORT 31
4.8 – BUILDING PERMIT REPORT 31

5.0 - GEOLOGY AND HYDROGEOLOGY 32

5.1 - INTRODUCTION 32
5.2 - LOCAL GEOLOGY AND HYDROGEOLOGY 32
5.3 - GROUNDWATER WELLS IN THE AREA 33
5.4 – RADON 34
5.5 – VAPOR ENCROACHMENT SCREEN REPORT 35

6.0 – OBSERVATIONS, CONCLUSIONS, AND RECOMMENDATIONS 36

6.1 - OBSERVATIONS 36
6.1.1 - GENERAL ENVIRONMENTAL INSPECTION 36
6.1.2 - DATABASE SEARCH AND REVIEW 38
6.1.2.1 – Subject Property 38
6.1.2.2 - Within 1/8 Radius 38
6.1.2.3 - Between 1/8 and 1/4 Mile Radius 39
6.1.2.4 - Between 1/4 and 1/2 Mile Radius 39
6.1.2.5 - Between 1/2 and 1 Mile Radius 39
6.1.2.6 – Over 1 Mile 39
6.1.2.7 - Unmapped Sites 40
6.1.3 - HISTORICAL INFORMATION REVIEW 40
6.1.4 - GEOLOGY AND HYDROGEOLOGY 40
6.2 - CONCLUSIONS 41
6.3 - RECOMMENDATIONS 41

7.0 - REFERENCES 42

TABLES IN TEXT

Table ES.1 – Structures at APNs: **029-151-150, 029-151-160, 029-151-170**
Table ES.2 - Items Noted at **SP**
Table ES.3 – Historical and Current Sources
Table 1.1 - Scope-of-Work
Table 1.2 – Client-Provided Information
Table 2.1 – Structures at APNs: **029-151-150, 029-151-160, 029-151-170**
Table 2.2 - Items Noted at **SP**
Table 3.1 – Search Radii
Table 3.2 – Listings at **SP**
Table 3.3 - Environmental Concerns Inside of ⅛ of Mile
Table 3.4 - Environmental Concerns Between ⅛ and ¼ of Mile
Table 4.1 – Historical and Current Sources
Table 4.2 - City Directory Summary
Table 4.3 - Environmental Liens and AULs – Deed #1
Table 4.4 - Environmental Liens and AULs – Deed #2
Table 4.5 - Environmental Liens and AULs – Deed #3
Table 5.1 – Topography a Mile Around the **SP**
Table 5.2 - Federal USGS Well Information
Table 5.3 - Federal FRDS Public Water Supply System Information
Table 5.4 - State Database Well Information
Table 5.5 - Aquiflow Information
Table 6.1 – Structures at APNs: **029-151-150, 029-151-160, 029-151-170**
Table 6.2 - Items Noted at **SP**
Table 6.3 – Listings at **SP**
Table 6.4 – Items to be Addressed Before, During and After Demolition

LIST OF ATTACHED TABLES

Table 1 – “Listed” Sites within 1760 feet

LIST OF ATTACHED FIGURES

Figure 1 - Site Location
Figure 2 - Site Vicinity
Figure 3 - Site Layout
Figure 4 - EDR Provided Parcel Map
Figure 5 - Geotracker w/Sites within 1760 ft
Figure 6 – Satellite Photo w/Sites within 1760 ft

LIST OF APPENDICES

Appendix 1 - Environmental Inspection Forms
Appendix 2 - Selected Photographs
Appendix 3 - Database Search Report
Appendix 4 - Historic Topographic Maps
Appendix 5 - Historic Sanborn® Maps
Appendix 6 - Historical Aerial Photographs
Appendix 7 - City Directory Report
Appendix 8 - Environmental Liens and AULs
Appendix 9 - Property Tax Map Report
Appendix 10 - Building Permits Report
Appendix 11 - Vapor Encroachment Screen
Appendix 12 - Summary Resume

EXECUTIVE SUMMARY

This report presents the findings of the Phase I - Environmental Site Assessment (Phase I) performed by ProTech Consulting & Engineering (ProTech) in Burlingame, California at 1214 – 1220 Donnelly Avenue (Subject Property [**SP**]). The Phase I was performed in accordance with the American Society of Testing Materials (ASTM) practice standards E1527-13, California State and Local Requirements and the EPA regulation – All Appropriate Inquiry (AAI).

The **SP** is located (Figures 1 through 6) in a mixed Commercial/Residential area of Burlingame. The **SP** is made of three (3) parcel APNs: **029-151-150, 029-151-160, 029-151-170**. There are either remnants of a residence or residences in various stages of repair at the three (3) parcels as listed below:

Table ES.1 – Structures at APN: 029-151-150, 029-151-160, 029-151-170

Address	Tenant	Access
1214 Donnelly	unoccupied fire damaged former residential unit that was converted to office spaces	Yes
1218 Donnelly	burned down multiunit residential complex, only foundation remains with one small unoccupied unit	Yes
1220 Donnelly	occupied two bldg 4 unit residential complex with detached 2 car garage	no access inside units, occupied

The Phase I is a non-intrusive historical study consisting of inspection of the **SP** grounds, all accessible buildings and the surrounding area.

Inspection of the **SP** revealed some issues of potential concern for the Phase I, and possible environmental concerns that are not part of a normal Phase I, so they are presented as Out-of-Scope [non-scope] possible concerns. There are no "Recognized Environmental Condition" (REC), no "Controlled Recognized Environmental Conditions" (CRECs) and no "Historical Recognized Environmental Conditions" (HRECs) on the **SP**. All properties are immediately adjacent to each other in a residential/commercial/retail area in downtown Burlingame. The **SP** is surrounded by numerous retail shops, salons, and restaurants.

Table ES.2 - Items Noted at SP

Address	Out-of-Scope Possible Concerns	Non-REC	REC	CREC	HREC	De Minimis
1214 Donnelly	▪ Loose and peeling paint inside 1214 Donnelly. ▪ -Suspect asbestos includes: roofing, sheetrock and JTC, surfacing texture, 9x9 VFT, roofing ▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring
1218 Donnelly	▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	2 soil borings
1220 Donnelly	▪ 2 Five gallon non empty paint container observed on property. ▪ loose and peeling paint observed on the exterior. ▪ Sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring

Notes: Out-of-Scope = beyond scope of ASTM E1527-13, REC = Recognized Environmental Condition, CREC = Controlled Recognized Environmental Condition [subset of REC], HREC = Historical Recognized Environmental Condition, "de minimis" = issue present, but no impact. (all according to E1527-13 definitions), Soil boring were to 4 feet below grade (fbg) and geotechnical in nature.

The adjacent parcels are used as:

- Northeast of properties = Blush Frozen Yogurt @ 1212 Donnelly, Renda Zaarour Hair Salon @ 1210 Donnelly.
- Southeast of properties = Pottery Barn 1230 Burlingame Ave, St Clairs Catering @ 1215 Donnelly, Didi Hair Salon @ 1221 Donnelly.
- Southwest of properties = City of Burlingame Public Parking.
- Northwest of properties = Residential apt complex @ 1211 Lortan Ave.

A neighborhood/area drive-by did reveal some listed sites and their potential environmental issues can be classified as RECs, CRECs or HRECs. The closest listed site was the **SP** itself (**John Britton, 1218 Donnelly Avenue for HAZNET**). Sites seen during neighborhood/area drive-by, not on the **SP**, are:

- Peninsula Prime Motors auto repair @ 621 California Ave.
- The 4 Car Garage auto repair @ 609 California Ave.
- Valero Gas Station @601 California Ave.
- Burlingame 1 hour Cleaners (on site drycleaners) @ 507 California Ave.
- Primrose Cleaners (on site drycleaners) @ 339 Primrose Ave.

Regulatory agency databases and other sources were reviewed to determine environmental conditions at the **SP**, adjacent properties, and/or nearby properties that may affect the **SP**. Radii of zero miles to over one-mile were established, depending on database searched, for the search.

The **SP** is three parcels with three (3) addresses: 1214 Donnelly Avenue, 1218 Donnelly Avenue and 1220 Donnelly Avenue. The Assessor's Parcel Number (APNs) are: **029-151-150, 029-151-160, 029-151-170**. The **SP** was identified on one (1) of the databases searched. It was listed on (Listed):

- (**HAZNET)** The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency. This database begins with calendar year 1993.

Adjacent/nearby or vicinity properties were identified on the following Federal, State, or regional databases (Environmental Concerns, Operating Permits or Lists):

- (**LUST**) The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.
- (**SLIC**) Statewide SLIC Cases, the SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.
- (**DEED**) The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes.
- (**EDR US Hist Auto Stat**) EDR Exclusive Historic Gas Stations Database has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The

categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

- **(EDR US Hist Cleaners**) EDR Exclusive Historic Dry Cleaners Database has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.
- (**RGA LUST**) The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.
- (**RCRA-SQG**) RCRA - Small Quantity-RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites, which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.
- (**RCRA-LQG**) RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites, which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.
- (**RCRA-CESQG**) RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.
- (**SWF/LF**) The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.
- (**CA UST**) The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.
- (**San Mateo Co Bl**) Hazardous Materials Business Plan, Hazardous Waste Generator, Underground Storage tanks.
- (**CA DRYCLEANERS**) A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners' agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.
- (**CA NPDES**) A listing of NPDES permits, including stormwater.
- (**SEMS-ARCHIVE**) SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the

inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

- (**ENVIROSTOR**) The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifies sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.
- (**SWRCY**) A listing of recycling facilities in California.
- (**SCH**) This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category. depending on the level of threat to public health and safety or the. environment they pose.
- (**CDL**) A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.
- (**SWEEPS UST**) Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.
- (**HIST UST**) Historical UST Registered Database.
- (**CA FID UST**) The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.
- (**CHMIRS**) The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.
- (**SPILLS 90**) Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.
- (**RCRA NonGen / NLR**) RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites, which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.
- (**FINDS**) The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.
- (**CORTESE)** The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

- (**EMI**) Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.
- (ENF) A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.
- (**HAZNET**) The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency.
- (**HIST CORTESE**) The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.
- (**PEST LIC**) A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.
- (**NOTIFY 65**) Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.
- (ECHO) ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A discussion regarding the sites identified, and their impact on the **SP**, is included in the text of the report.

The historic information gathered and reviewed showed generally good correlation and nothing out of the ordinary was seen. For the environmental liens, none were found and no use restrictions were recorded. Historical information was gathered to identify potential environmental concerns due to historical activities. Information gathered[3] was from:

Table ES.3 – Historical and Current Sources

Source	Used	Current	Historical
USGS Historical Topographical Maps	X		X
Historical Aerial Photographs	X	X	X
Sanborn Maps	X		X
City Directory	X		X
Environmental Liens and AULs	X	X	
Building Permits	X		
Vapor Encroachment	X	X	
Assessor Parcel Map (APM)	X	X	
Geotracker	X	X	X

The geology of the area is clayey silts and sands extending to at least six fbg, but more likely, this soil type extends to about 20 to 25 feet below grade (fbg). Below this is weathered and unweathered bedrock and Bay Muds to the northwest through the northeast and weathered and unweathered bedrock to the southeast through the southwest. The **SP** does not appear to sit on

[3] There were no Sanborn Maps available for the SP.

any active faults, but to the west is the San Andreas Fault and to the east, across the San Francisco Bay, is the Hayward Fault, both of which cause earth movement. The shallow groundwater in the area is in contact with the atmosphere (Water Table Condition), and appears to be variable. Regional flow is toward the bay and can be affected by topography, rainfall, and/or groundwater pumping.

As the VEC report indicates, there is no direct evidence of vapor intrusion at the **SP**, and the Ninety-One (91) listings representing: (One (1) for the **SP,** twenty-one (21) for listings within $^{1}/_{10}$ mile representing twelve (13) sites, and Seventy-one (71) listed sites representing forty-seven (47) sites between $^{1}/_{10}$ mile and ⅓ mile) listed as possible have all been dismissed in the VEC screen report. The report is included as Appendix 11.

A review of the radon results provided in the physical setting section of the Radius Map™ Report with GeoCheck® indicates that radon in the area is not a problem.

During our 11 August 2016 inspection, nothing out of the ordinary was observed and an Area/Neighborhood Drive-By was also performed on 11 August 2016, where nothing out of the ordinary was observed. There is surficial evidence (some staining and fire damage) of impact to the site, but no subsurface evidence of impact from the database listings for the **SP**. The listings around the site do not appear to affect the **SP** either.

Nothing unusual was seen during our site inspection our data review. However:

1. During any building renovation or demolition activities, we recommend:
    a. Following all Asbestos-Containing Materials (ACM), Lead-Based Paint (LBP) and Lead-Containing Materials (LCM) regulations and requirements with regard to identifying, handling, and disposal
    b. Following all HAZMAT regulations and requirements with regard to identification, characterization, waste and debris disposal, and recycling.

1.0 - INTRODUCTION

1.1 - INTRODUCTION

This report presents the findings of the Phase I - Environmental Site Assessment (Phase I) performed by ProTech Consulting & Engineering (ProTech) in Burlingame, California at 1214 - 1220 Donnelly Avenue (Subject Property [**SP**]) [Figures 1 through 6]. The Phase I[4] was performed in accordance with the American Society of Testing Materials (ASTM) practice standard #E1527-13, California Requirements and the EPA regulation – All Appropriate Inquiry (AAI).

1.2 - SCOPE-OF-WORK

The Phase I study is a non-intrusive study that looks at the property, its history, and surroundings. During this project, the following scope-of-work was performed for the Phase I:

Table 1.1 - Scope-of-Work

Source	Section
Site Inspection, including: SP and Boundary Walk	2
Area/Neighborhood Drive-By	2
Search and Review of Federal, State, and Regional Databases	3
Search and Review of Historical Topographs, Sanborn® Maps, Aerial Photographs, and a City Directory	4
Search and Review of Environmental Liens and AULs, Property Tax Map, and Building Permits	4
Search and Review of Geology, Hydrogeology, Groundwater, Well information, Radon review, and a Vapor Encroachment Concern Screen Report	5
Observations, Conclusions, and Recommendations	6
References	7
Environmental Inspection Form and Questionnaires	App. 1
Site Pictures	App. 2
Database Report – GeoCheck/Radius Report	App. 3
Historical Topographs	App. 4
Sanborn Maps	App. 5
Historical Aerial Photographs	App. 6
City Directory	App. 7
Environmental Liens and AULs	App. 8
Property Tax Map Report	App. 9

[4] The research conducted for this study and the report prepared are in general conformance with the EPA "All Appropriate Inquiries" standard and the ASTM 1527-13 "Standard Practices for Environmental Site Assessments: Phase I Environmental Site Assessment Process". The primary purpose for performing a Phase I ESA is to "…permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations (commonly known as Landowner Liability Protections) listed in Comprehensive Emergency Response Compensation and Liability Act (CERCLA) liability." (ASTM, 2013) Further, it is the goal of this study to identify business risks associated with the property associated with environmental conditions.

Source	Section
Building Permits Report	App. 10
Vapor Encroachment Condition (VEC) Screen	App. 11
Summary Resumes	App. 12

Figures are also attached in support of the information presented below.

1.3 – LIMITATION OF STUDY/DATA GAPS

"Data Gaps" are missing database reports or other historical information and drawings/maps, but certain reports are only pieces of the historical record used for the Phase I and should be considered as such. There are no Building Permits for this **SP** and this is considered Data Gap. Missing data can be somewhat re-created by other historical reports, but you must have an understanding of the history of the **SP**, its occupants, and the area. The missing Building Permits is considered a "Data Gap" because this historical information is not readily re-created by other sources.

1.4 – CLIENT PROVIDED INFORMATION

The client provided the APNs and some history about the site.

Table 1.2 – Client-Provided Information

Title	Date
APN	29 July 2016
Status and History of Site	11 August 2016
Teleconference with Christina Tipp, Re: 4 boring	15 August 2016

1.5 – KEY SITE MANAGER

Met with **Andrew Britton** (Owner Representative). He is unaware of any environmental liens, use restrictions, or issues with the properties. He did show me Four (4) borings on the properties. Three (3) drilled on 1214 and 1218 Donnelly and one (1) drilled on 1220 Donnelly. He believes they are to a total depth of around 4' not sure if drilled for environmental or geotechnical reasons. Drilled by Romig Engineering about a month ago. Point of contact is Christina Tipp P.G. 408 824-4586. Called Romig Engineering on 15 August 2016, spoke with Christina Tipp who indicated that boring were geotechnical in nature.

2.0 - SUBJECT PROPERTY INSPECTION

2.1 - INTRODUCTION

On 11 August 2016, Ryan Cozart inspected the three addresses that make up the **SP** (APN**#s 029-151-150, 029-151-160, 029-151-170)** in Burlingame, California at 1214-1220 Donnelly Avenue **[SP**], and its boundaries with other properties. An Area/Neighborhood Drive-by was also performed during this inspection.

2.2 - SUBJECT PROPERTY DESCRIPTION

The **SP** is located in a mixed residential/commercial area at 1214-1220 Donnelly Avenue in Burlingame, California (Figures 1 through 6). The **SP** is three parcels with three addresses, detailed below:

Table 2.1 – Businesses at APNs: 029-151-150, 029-151-160, 029-151-170

Address	Tenant	Access
1214 Donnelly	unoccupied fire damaged former residential unit that was converted to office spaces	Yes
1218 Donnelly	burned down multiunit residential complex, only foundation remains with one small unoccupied unit	Yes
1220 Donnelly	occupied two bldg 4 unit residential complex with detached 2 car garage	no access inside units, occupied

The Assessors Parcel Numbers (APNs) are **#s: 029-151-150, 029-151-160, 029-151-170**. An Environmental Inspection Form (EIF) for the address is attached in Appendix 1. Selected photographs of the **SP** and its surroundings are included as Appendix 2.

2.3 - PROPERTY INSPECTION

On 11 August 2016, the **SP**: three parcels, the remaining buildings and property boundaries were inspected. We met with **Andrew Britton,** the Key Site Manager. He gave us some history of the **SP**. The **SP** and its boundaries with adjacent parcels were walked and inspected, for any evidence of surface contamination, staining, or other unusual conditions. The tabulated items are

organized as Out-of-Scope Possible Concerns, Non-Recognized Environmental Conditions, RECs[5], Controlled RECs (CRECs), or Historic RECs (HRECs), and De Minimis.

Table 2.2 - Items Noted in Address

Address	Out-of-Scope Possible Concerns	Non-REC	REC	CREC	HREC	De Minimis
1214 Donnelly	▪ Loose and peeling paint inside 1214 Donnelly. ▪ -Suspect asbestos includes: roofing, sheetrock and JTC, surfacing texture, 9x9 VFT, roofing ▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring
1218 Donnelly	▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	2 soil borings

[5] The goal of this process is to identify Recognized Environmental Conditions (RECs) associated with the property. A recognized environmental condition is defined as "…the presence or likely presence of any hazardous substances or petroleum products on a property that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property." This definition does not include "*de minimis* conditions that generally do not pose a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate government agencies" (ASTM, 2013).

Address	Out-of-Scope Possible Concerns	Non-REC	REC	CREC	HREC	De Minimis
1220 Donnelly	▪ 2 Five gallon non empty paint container observed on property. ▪ loose and peeling paint observed on the exterior. ▪ Sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring
Notes: Out-of-Scope = beyond scope of ASTM E1527-13, REC = Recognized Environmental Condition, CREC = Controlled Recognized Environmental Condition [subset of REC], HREC = Historical Recognized Environmental Condition, "de minimis" = issue present, but no impact. (all according to E1527-13 definitions), Soil boring were to 4 feet below grade (fbg) and geotechnical in nature.						

During this inspection, nothing out of the ordinary was observed in any of the structures. We were able to inspect most of the structures (1220 Donnelly was not accessible) and walk the grounds. During this inspection, nothing out of the ordinary was observed on the parcels. Four (4) decommissioned soil borings were evident and a teleconference with Romig Engineering indicated that they were drilled to a depth of four (4) feet below grade (fbg) for geotechnical purposes. The staining seen was do to the fires that burned down the structures of 1218 Donnelly and damaged those on 1214 Donnelly.

2.4 – AREA/NEIGHBORHOOD DRIVE-BY

An Area/Neighborhood Drive-By was also performed on 11 August 2016. During this inspection, nothing out of the ordinary was observed. Listed sites that were seen are shown on Figures 5 and 6 for orientation.

The adjacent parcels are used as:

- Northeast of properties = Blush Frozen Yogurt @ 1212 Donnelly, Renda Zaarour Hair Salon @ 1210 Donnelly.
- Southeast of properties = Pottery Barn 1230 Burlingame Ave, St Clairs Catering @ 1215 Donnelly, Didi Hair Salon @ 1221 Donnelly.
- Southwest of properties = City of Burlingame Public Parking.
- Northwest of properties = Residential apt complex @ 1211 Lortan Ave.

None of the listed sites within ⅓ of a mile, which is the outer radius for the Vapor Encroachment Concern (VEC) report (Appendix 11), is considered an issue in regard to the site. The REC, CREC[6], or HREC determination is in Section 3.

[6] CREC is a new category under REC, where the site is undergoing mitigation supervised by an agency.

3.0 - DATABASE SEARCH AND REVIEW

3.1 - INTRODUCTION

Environmental Data Resources, Inc. (EDR), under contract to ProTech, performed a database search (Radius Map™ Report with GeoCheck®). The database search and review was performed according to ASTM standards[7] with additional regional databases included to meet California requirements. The search was over five radii:

Table 3.1 – Search Radii

Radius	Radius Dimension
SP	Subject Property Only
⅛ mile	Within ⅛ mile of **SP**
¼ mile	Between ⅛ mile and ¼ mile of **SP**
½ mile	Between ¼ mile and ½ mile of **SP**
1 Mile	Between ½ mile and 1 mile of **SP**
>1 mile	>1 mile of **SP**

The results of the search and review are briefly described below. Map Index Numbers (MINs) presented in the descriptions below refer to the MINs assigned in the Database Search Report that is attached as Appendix 3. In some cases, a MIN may contain several different site listings and citations with either the same or adjoining addresses.

3.2 – SUBJECT PROPERTY

The **SP** was identified on one (1) database of all those searched as part of this study. These are:

Table 3.2 – Listing at SP

Map ID #	Name	Address	Dis (mi)	Dir	Topo	Listing	Status
A1	**JOHN BRITTON**	**1218 DONNELLY AVE**	**SP**	**-**	**-**	**HAZNET**	**LISTED**

Notes: Dis = distance from SP in miles; Dir = direction from SP (west, north, east, south, or some combination); Topo = topographic elevation compared to SP (D: down-gradient/U: up-gradient/E: equivalent); HAZNET = data from hazardous waste manifests..

[7] Adherence to ASTM also complies with EPA regulations.

3.3 - INSIDE ONE-EIGHTH MILE RADIUS SURVEY

Within this search radius, there are 22 MINs classified as being of environmental concern[8], 20 MINs listed as having operating permits, and 86 MINs was on hazardous substance lists. The details of the databases searched are presented in the database report included as Appendix 3. Below, if provided, we list "active" sites ("NFA" or "closed" for LUFT sites within an eighth of a mile as well), as these are the sites of potential concern. Other "NFA" or "closed" sites have met their regulatory obligations and should not be a problem in the future from their present cleanup. Following each table, if generated, we summarize the information on referenced sites as they relate to potentially affecting the **SP**. Additional regulatory information, gathered during this Phase I that updates the database, is also presented here. A complete list of "active", "NFA", or "closed" sites, "hazardous substance" listed sites, and "operating permit" listed sites is included in the Radius Map™ Report with GeoCheck® in Appendix 3.

Table 3.3 - Environmental Concerns Inside of ⅛ of Mile

Map ID #	Name	Address	Dis (mi)	Dir	Topo	Listing	Status
A5	LORTON PLACE OWNERS ASSOCIATION	345 LORTON AVENUE	0.025	N	D	LUST	Closed
A6/A7/A8/A9/A10/A11	KIRKBRIDE PROPERTY	307 LORTON	0.058	E	U	RGA LUST	Listed
						LUST	Closed
A12/A13/A14/A16/A17 /A18/A19	SABATINI TRUST	361 CALIFORNIA	0.059	NE	D	LUST	Closed
						RGA LUST	Listed
A23	GERRITSON PROPERTY	1229 BURLINGAME AVE	0.072	ESE	U	RGA LUST	Listed
A24/A25	KIM MILLS TEXACO (FORMER)	401 CALIFORNIA	0.073	N	D	RGA LUST	Listed
						LUST	Closed
A31		345 CALIFORNIA DR	0.075	NE	D	EDR Hist Cleaners	Listed
A43/A44/A45/A46/A47 /A48/A49/A50/A51	PRIMROSE CLEANERS GATES GLOBE CLEANERS	339 PRIMROSE RD	0.084	SSW	U	EDR Hist Cleaners	Listed
						Dry-cleaners	Listed
A52		337 PRIMROSE RD	0.084	SSW	U	EDR Cleaners	Listed
D83/D84/D85/D86/D87 /D88/D89/D90/D91	BURLINGAME HIGH SCHOOL	400 CAROLAN AVENUE	0.117	NNE	D	DEED	Certified O&M

[8] Environmental Concerns, as depicted on the database maps, are divided into three categories: Environmental Concerns - High Priority: possible Recognized Environmental Condition (RECs); Environmental Concerns; and Environmental Concerns - With a "no further action status". The maps included in the database report illustrate the different statuses of sites and their proximity to the SP.
Environmental Concerns – "Active" are those sites that have a citation, or some other listing that warrants special attention.
Environmental Concerns – "no further action" are those sites that cited, but have been closed to the satisfaction of the regulatory agencies. They are not labeled "closed" because they still operate in the manner that caused their listing in the first place.
Environmental Concerns - "closed" are those sites that have met their regulatory requirements and no longer operate in the manner that caused their listing in the first place.

B99/B100/B101/B102/ B103/B104/B105/B106/ B107/B108	BURLINGAME POST OFFICE	220 PARK	0.119	SE	U	RGA LUST	Listed
						LUST	Closed

Notes: Dis = distance from SP in miles; Dir = direction from SP (west, north, east, south, or some combination); Topo = topographic elevation compared to SP (D: down-gradient/U: up-gradient/E: equivalent); RGA LUST = recovered government files, LUST = leaking underground storage tank, REM = remediation, CUPA = Certified Unified Program Agencies, **EDR** Auto = EDR proprietary database of historic sites, EDR Cleaners = EDR proprietary database of historic sites, RGA = recovered government files.

Based on the information in the EDR database for this search interval, our site reconnaissance, and our understanding of the area, the SP outward to ⅛ of a mile had forty-seven (47) listings, representing ten (10) addresses for environmental concerns. Of these forty-seven (47) listings, one (1) was listed as active: **BURLINGAME HIGH SCHOOL** at 400 Carolan Avenue for a DEED restriction[9]. All the other listings are closed or on a list. No evidence of impact was found during our site reconnaissance. A complete list of "active", "NFA", or "closed" sites, "hazardous substance" listed sites, and "operating permit" listed sites is included in the database search report in Appendix 3.

3.4 - ONE-EIGHTH MILE TO ONE-QUARTER MILE RADIUS SURVEY

Within this search radius, there are 65 MINs classified as being of environmental concern, 68 MIN has operating permits, and 161 MINs were on hazardous substance lists.

Table 3.4 - Environmental Concerns Between ⅛ and ¼ of Mile

Map ID #	Name	Address	Dis (mi)	Dir	Topo	Listing	Status
F120/F121/F122/F123 /F124/F125	BURLINGAME ONE HOUR CLEANERS	507 CALIFORNIA	0.140	NNW	D	Dry-Cleaners	Listed
						EDR Hist Cleaners	Listed
C126		240 PRIMROSE RD	0.140	S	U	EDR Hist Cleaners	Listed
B131/B132/B133/B13 4/B137	German Car Care Auto Mobile Care	251 CALIFORNIA DR	0.150	E	U	EDR Hist Auto	Listed
						EDR Auto	Listed
G135		229 PARK RD	0.151	SE	U	EDR Hist Cleaner	Listed
C136		1440 CHAPIN AVE	0.154	SW	U	EDR Hist Auto	Listed
B146/B147	STERLING CLEANERS (FORMER)	215 CALIFORNIA DRIVE	0.167	ESE	U	LUST	SA
						RGA LUST	Listed
						SLIC	SA
B156		215 HATCH LN	0.180	ESE	U	EDR Hist Auto	Listed
E157/E158	ARLINGTON APARTMENTS	1401 FLORIBUNDA	0.180	W	D	LUST	Closed
G160/G161/G162/G1 63	200 PARK RD COMPANY LLC	200 PARK RD	0.180	SE	U	LUST	IRA
						RGA Lust	Listed

[9] This site is Certified Operation & Maintenance after remediation and capping.

G166/G167/G168/G169/G170/G171/G172/G173/G174/G175	HARRIS PROPERTY	1234 HOWARD AVE	0.182	SE	U	RGA Lust	Listed
						LUST	REM
G176		1220 HOWARD AVE	0.183	SE	U	EDR Hist Lust	Listed
G177/G178/G179/G180/G181/G182	KING YEE PROPERTY SHAFFER PROPERTY TRUST	1200 HOWARD AVE	0.185	SE	U	RGA Lust	Listed
						LUST	REM
G186/G187/G188/G189/G190	BERENSTEIN ASSOC. PROPERTY FORMER CAINE CLEANERS GREEN BANKER	1319 HOWARD	0.189	SSE	U	RGA Lust	Listed
						LUST	REM
						SLIC	SA
G191/G192/G193/G194/G195/G196/G197	CAINE CLEANERS	1321 HOWARD AVE	0.189	SSE	U	EDR Hist Cleaners	Listed
						Dry-Cleaner	Listed
G198/G199		1325 HOWARD AVE	0.189	SSE	U	EDR Hist Lust	Listed
						EDR Hist Cleaners	Listed
G202/G203/G204/G205/G206	STERLING CLEANERS INC	1140 HOWARD AVE	0.191	ESE	U	EDR Hist Cleaner	Listed
						LUST	PAU
						SLIC	SA
						Dry-Cleaner	Listed
F211/F212/F213/F214/F215/F216/F217/F218/F219/F220	SHELL Burlingame Texaco Burlingame Beacon	601 CALIFORNIA	0.194	NW	D	LUST	Closed
						RGA LUST	Listed
						EDR Hist Auto	Listed
H221/H222/H223/H224/H226/H227/H228/H229	PACIFIC BELL	1480 BURLINGAME AVENUE	0.198	SSW	U	LUST	Closed
						RGA LUST	Listed
I238/I239/I240/I241/I242/I243	D + R Auto Paint	270 EAST LN	0.211	E	D	EDR Hist Auto	Listed
H246/H247/H248/H249/H250/H251/H252/H253	SHELL SERVICE STATION	1490 BURLINGAME	0.216	SSW	U	LUST	Closed
						RGA LUST	Listed
F261	FOUR CAR GARAGE INC	609 CALIFORNIA DR	0.218	NW	D	EDR Hist Auto	Listed
I267/I268/I269/I270	RUPPELS AUTO FIXATION INC	260 EAST LN	0.219	E	D	EDR Hist Auto	Listed
K271/K272/K273/K274/K275/K276/K277/K278/K279/K280/K281/K282/K283/K284/K285/K286/K287/K288/K289	CHEVRON 9-0571 Walgreens #12257 Bob's Chevron 5973 San Mateo Environmental Health	260 EL CAMINO REAL	0.222	SSW	U	LUST	PC
						RGA LUST	Listed
						EDR Hist Auto	Listed
M309/M310/M311/M312/M313/M314	AUTO TIGER BURLINGAME PRIME MOTOR ON TRACK AUTOMOTIVE CALIFORNIA DRIVE AUTO SERVICE	621 CALIFORNIA	0.235	NW	D	EDR Hist Auto	Listed
I321/I322/I323/I324/I325/I326/I327/I328/I329/I330/I331	CHEVRON, FORMER/EAGLE GAS STA BUBBLE MACHINE	177 CALIFORNIA	0.248	ESE	U	RGA LUST	Listed
						LUST	Closed

J332/J333/J334/J335	ALL MAKES AUTO BODY SHOP	257 MYRTLE ROAD	0.245	ENE	D	EDR Hist Auto	Listed

Notes: Dis = distance from SP in miles; Dir = direction from SP (west, north, east, south, or some combination); Topo = topographic elevation compared to SP (D: down-gradient/U: up-gradient/E: equivalent); EDR Cleaners = EDR proprietary list of previous dry cleaners, Lust =proprietary list of previous auto stations, LUST = leaking underground storage tank, RGA Lust = recovered government records.

Based on the information in the EDR database for this search interval, and our site reconnaissance, there are one hundred twenty-five (125) listings[10] representing twenty-six (26) addresses. Only seven (7) sites are LUST or SLIC sites that are open, but they are in various stages of remediation and do not appear to impact the the **SP**. All the others are either "closed" or on lists. None of these sites poses a threat to the **SP**. A complete list of "active", "NFA", or "closed" sites, "hazardous substance" listed sites, and "operating permit" listed sites is included in the Radius Map™ Report with GeoCheck® in Appendix 3.

3.5 - ONE-QUARTER MILE TO ONE-HALF MILE RADIUS SURVEY

Within the search radius, there are 102 MINs classified as being of environmental concern, 63 MINs having an operating permit, and 230 MINs on hazardous substance lists. Due to the distance from, and the unlikely event that these sites would materially affect the **SP**, they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

3.6 – ONE-HALF MILE TO ONE MILE RADIUS SURVEY

Within the search radius there are 81 MINs classified as being of environmental concern, 72 MINs were listed as having an operating permit, and 36 MINs were on hazardous substance lists. Again, due to the distance from, and the unlikely event, if sites were listed, they would materially affect the SP; they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

3.7 – OVER ONE MILE RADIUS SURVEY

Within the search radius, there are 0 MINs classified as being of environmental concern, 0 MINs was listed as having an operating permit, and 5 MINs were on hazardous substance lists. Again, due to the distance from, and the unlikely event, if sites were listed, they would materially affect the SP; they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

[10] The one hundred twenty-five (125) listings cover all three categories: (Environmental Concerns, Operating Permits or Lists)

3.8 - UNMAPPED SITES

There were three (3) unmapped sites: ENVIROSTOR (2), CDL (1). No addresses had multiple database listings.

4.0 - HISTORICAL INFORMATION REVIEW

4.1 - INTRODUCTION

As part of our research, we also performed a search of records. This search included:

Table 4.1 – Historical and Current Sources

Source	Used	Current	Historical
USGS Historical Topographical Maps	X	X	X
Sanborn Maps	X		X
Historical Aerial Photographs	X	X	X
City Directory	X		X
Environmental Liens and AULs	X	X	
Building Permits			
Vapor Encroachment	X	X	
Assessor Parcel Map (APN)	X	X	
Geotracker	X	X	X

4.2 – HISTORICAL TOPOGRAPHIC MAPS

Historic topographs were reviewed and presented in Appendix 4 from 1896, 1899, 1915, 1939, 1947, 1949, 1956, 1968, 1973, 1980, 1993, 1997 and 2012. The source sheets were:

- The San Mateo Quadrangle (1896, 1899, 1915, 1939, 1947, 1949, 1956, 1968, 1973, 1980, 1993, 1997 and 2012), and
- The Montara Mountain Quadrangle (2012).

They show the area developing over time as a mixed residential/commercial area. By 1939, the area around the future **SP** is beginning to develop. By 1947, the streets around the **SP** look more like an urban area. In addition, by 1961, more neighborhoods have been established. From 1968 through 2012 the area becomes more densely populated and appears developed as today.

4.3 - SANBORN® MAPS

Sanborn Maps were available for this property. We reviewed the following years: 1908, 1913, 1921, 1946, 1949, 1959 and 1970. The Sanborn Maps reviewed is included as Appendix 5.

The SP (three (3) parcels and addresses) were undeveloped until 1946 when 1214 Donnelly (**029-151-150**) appeared to be a restaurant, while both 1218 Donnelly (**029-151-160**) and 1220 Donnelly (**029-151-170**) appeared to be residences. They all stayed this way through the 1970 Sanborn. The neighborhood had several residences and commercial buildings as early as the 1913 Sanborn and the density continued to grow from 1921 through 1970. Nothing unusual was seen on the Sanborn maps.

4.4 - HISTORICAL AERIAL PHOTOGRAPHS

Aerial photographs were reviewed during this project. The years reviewed were 1943, 1946, 1956, 1968, 1974, 1982, 1993, 1998, 2005, 2009, 2010 and 2012. In 1943, the **SP** appears to be developed with buildings. The area surrounding the **SP** is also developed. In 1946, the middle parcel of the **SP** is developed with a larger structure than in the next aerial (1956). The 2005 aerial shows development, as today and all newer aerial's that were reviewed are pretty much the same. Copies of the aerial photographs reviewed are included as Appendix 6.

4.5 – CITY DIRECTORY

Most searches span circa-1922 to 2013. The city directory for the **SP** is between 1922 and 2013. The City Directory indicates the **SP** was listed on the City Directory from 1970 through 2013. The first listing of adjacent addresses was 1970 also. Documentation of the City Directory is included as Appendix 7. A summary is below:

Table 4.2 – City Directory Adjacent Properties Summary

Date	Addresses				
	1214 Donnelly Ave – SP	**1218 Donnelly Ave – SP**	**1220 Donnelly Ave – SP**	**1215 Donnelly Ave**	**1221Donnelly Ave**
2013	TANDEM ENTREPRENEURS TDA INVESTMENT GROUP INC	ALFREDO GARCIA	ARMANDO ROMERO	ST CLAIRS CATERING	DIDI SALON
2008	DALE TURNER ASSOCIATES INC	ALFREDO GARCIA ILLIANA RUIZ RUKSHAN ALI	ARMANDO ROMERO BLANCA MARTINEZ	ST CLAIRS GOURMET ST CLIRS PERSONALIZED GRMT SERVICE	DIDI SALON
2003	TURNER DALE ASSOCS		JENNIFER LASICH	ST CLAIRS GOURMET	OCCUPANT UNKNOWN
1999	TDA INCORPORATED	ALFREDO GARCIA ILLIANA RUIZ QUENT CORDAIR RUKSHAN ALI	ARMANDO ROMERO BLANCA MARTINEZ		TU SALON
19	BROWN, JANET J B & ASSOC	CORDAIR, QUENT			OCCUPANT UNKNOWNN TU

Date	Addresses				
	1214 Donnelly Ave – SP	**1218 Donnelly Ave – SP**	**1220 Donnelly Ave – SP**	**1215 Donnelly Ave**	**1221Donnelly Ave**
95	TURNER DEHONEY & ASSOC				SALON
1992	J B&ASSOCIATES TURNER DEHONEY&ASC	MARLIN, LOUIS JR	ABERDROTH, DIANE		TU SALON
1985	Founders Title Nor Penn Investments	XXXX	Shea M	Berta Gray Enterprises	The Encore Shop Martha's Vlg Store Village Telephone Vivian's Salon
1980	XXXX	Steve Gorran William Long	Richard Moulding J Reiter		The Encore Shop Martha's Vlg Store Village Telephone Vivian's Salon
1977	Kim Leong Miguels Antiques	R S Kelly	Eloise Bishop James Mraz		The Encore Shop Martha's Vlg Store Village Telephone Vivian's Salon
1970	Kims Restaurant	Verna Benhard Betty Braun Margaret Fox Dora Gribble	Eloise Bishop Leslie Brooks Maria Favalessa B Vasatka H Willstadter		The Encore Shop Vivian's Salon

4.6 – ENVIRONMENTAL LIENS AND AUL REPORT

There were three (3) deeds found for this **SP**. Below is a description of the deed. A copy of the Environmental Liens and AUL Report is included as Appendix 8.

Table 4.3 – Environmental Liens and AULs – Deed #1

Category	Result
Type of Deed:	deed
Title is vested in:	Patricia Ann Britton Trustee
Title received from:	Patricia Ann Britton
Deed Dated:	12/10/1997
Deed Recorded:	1/3/1998
Book:	NA
Page:	NA
Volume:	NA
Instrument:	NA
Docket:	NA
Land Record Comments:	NA
Miscellaneous Comments:	NA
Legal Description:	See Exhibit
Legal Current Owner:	Patricia Ann Britton Trustee
Parcel # / Property Identifier:	029-151-160
Comments:	See Exhibit
ENVIRONMENTAL LIEN	Found ☐ Not Found ☑
OTHER ACTIVITY AND USE LIMITATIONS (AULs)	Found ☐ Not Found ☑

Table 4.4 – Environmental Liens and AULs – Deed #2

Category	Result
Type of Deed:	deed
Title is vested in:	Patricia Ann Britton Trustee
Title received from:	Patricia Ann Britton
Deed Dated:	12/10/1997
Deed Recorded:	1/3/1998
Book:	NA
Page:	NA
Volume:	NA
Instrument:	NA
Docket:	NA
Land Record Comments:	NA
Miscellaneous Comments:	NA
Legal Description:	See Exhibit
Legal Current Owner:	Patricia Ann Britton Trustee
Parcel # / Property Identifier:	029-151-150
Comments:	See Exhibit
ENVIRONMENTAL LIEN	Found ☐ Not Found ☑
OTHER ACTIVITY AND USE LIMITATIONS (AULs)	Found ☐ Not Found ☑

Table 4.5 – Environmental Liens and AULs – Deed #3

Category	Result
Type of Deed:	**deed**
Title is vested in:	**Patricia Ann Britton Trustee**
Title received from:	**Patricia Ann Britton**
Deed Dated:	**12/10/1997**
Deed Recorded:	**02/25/1998**
Book:	**NA**
Page:	**NA**
Volume:	**NA**
Instrument:	**NA**
Docket:	**NA**
Land Record Comments:	**NA**
Miscellaneous Comments:	**NA**
Legal Description:	**See Exhibit**
Legal Current Owner:	**Patricia Ann Britton Trustee**
Parcel # / Property Identifier:	**029-151-170**
Comments:	**See Exhibit**
ENVIRONMENTAL LIEN	**Found** ☐ **Not Found** ☑
OTHER ACTIVITY AND USE LIMITATIONS (AULs)	**Found** ☐ **Not Found** ☑

4.7 – PROPERTY TAX MAP REPORT

The Property Tax Map Report is included as Appendix 9. The parcel APNs are **#s: 029-151-150, 029-151-160, 029-151-170,** and the parcel map is in Appendix 9 with **SP** shown.

4.8 – BUILDING PERMIT REPORT

The report indicted that the building permits for this **SP** were not available. It was considered as a "Data Gap" because this missing information cannot be re-created by other sources. Inspection of the site shows the presence of Hazardous Materials/Hazardous Wastes. The Building Permit Report documentation is included as Appendix 10.

5.0 - GEOLOGY AND HYDROGEOLOGY

5.1 - INTRODUCTION

ProTech reviewed readily available regional and local geologic and hydrogeologic information. The results of that review are briefly described below. The information reviewed included data in Appendix 3, in the Physical Setting Appendix to the Radius Map™ Report with GeoCheck® as well as other referenced material, including Appendix 11 – Vapor Encroachment Condition (VEC) screen report.

5.2 - LOCAL GEOLOGY AND HYDROGEOLOGY

The **SP** is located west of the San Francisco Bay. The **SP** is in a commercial/residential area that is north of Howard Avenue and south of California Avenue in Burlingame in San Mateo County with listed properties up-gradient and down-gradient. The shallow subsurface is made of alluvial deposits (clayey silts to silty sands in nature): these fine-grained soils go to approximately 20 - 25 feet below grade (fbg). Weathered bedrock and Bay Mud underlie the area from the northwest to northeast toward the bay at various depths and various thicknesses (Norris & Webb, 1990) and weathered and unweathered bedrock underlie the area from the southeast to the southwest. The area topography gently rises from the north to the **SP** and then more noticeably to the south. The topography slopes downward from west to the **SP** and then continues sloping gently downward to the east (see Physical Setting Appendix to the Radius Map™ Report with GeoCheck® for north to south elevation profile and a west to east elevation profile). The topography slopes:

Table 5.1 – Topography a Mile Around the SP

Elevation at 1-mile north/west	Elevation at SP	Elevation At 1-mile south/east	Grade (west to SP)	Grade (SP to east)	Grade (north to SP)	Grade (SP to south
0	32	110			0.61%	1.48%
53	32	19	-0.40%	-0.25%		
Negative grade reflects downward slope.						

Groundwater in the area is typically a layered aquifer system with the shallowest being an unconfined aquifer (Water Table). Below this layer there are multiple layers that are considered semi-confined to confined aquifers. The shallowest aquifer that would most directly influence the **SP** is affected by topography, seasonal rainfall, and pumping activities (Norris & Webb, 1990).

The **SP** does not sit on any active faults, but to the west is the San Andreas Fault and to the west, across the bay, is the Hayward fault, both of which cause earth movement.

5.3 - GROUNDWATER WELLS IN THE AREA

ProTech reviewed available information for groundwater wells found in the Physical Setting Appendix of Radius Map™ Report with GeoCheck®. The results of that review are briefly described below. The information reviewed is in the Physical Setting Appendix of the Radius Map™ Report with GeoCheck® included in Appendix 3.

No groundwater monitor wells were found on the **SP**. Shallow borings (4 fbg) that were abandoned properly, by visual inspection[11], were on the **SP**.

No wells were found the Federal database researched: **Federal USGS Well Information**.

Table 5.2 - Federal USGS Well Information

MAP ID	WELL ID	LOCATION FROM SP
NONE		

No wells were found the Federal database researched: **Federal FRDS Public Water Supply System Information**.

Table 5.3 - Federal FRDS Public Water Supply System Information

MAP ID	WELL ID	LOCATION FROM SP
NONE		

One (1) well was found the State database researched **State Database Well Information**. It was in the ¼ - ½ mile radius.

Table 5.4 - State Database Well Information

MAP ID	WELL ID	LOCATION FROM SP
5	4839	1/4 - 1/2 Mile North

The groundwater flow, according to AQUIFLOW[12], in the area is variable, while regionally it is easterly, toward the San Francisco Bay. Pumping wells, topography and/or seasonal rainfall can all retard/alter groundwater flow. Nothing out of the ordinary was seen. AQUIFLOW monitoring points are tabulated below:

[11] Confirmed with the Engineer who installed them.
[12] AQUIFLOW is a modeling program used to interpret groundwater flow direction and gradient.

Table 5.5 - Aquiflow Flow Information

MAP ID	LOCATION FROM SP	GENERAL DIRECTION GROUNDWATER FLOW
1	0 - 1/8 Mile ESE	Not Reported
2	1/8 - 1/4 Mile ESE	E, Flat
A3	1/8 - 1/4 Mile NW	N
4	1/8 - 1/4 Mile SW	N
A6	1/4 - 1/2 Mile NW	NW
7	1/4 - 1/2 Mile NW	N
8	1/2 - 1 Mile WNW	Not Reported
B9	1/4 - 1/2 Mile ESE	SE
B10	1/4 - 1/2 Mile ESE	E
C11	1/4 - 1/2 Mile NW	N
C12	1/4 - 1/2 Mile NW	NNE
C13	1/4 - 1/2 Mile NW	NNE
D14	1/4 - 1/2 Mile ESE	E
D15	1/4 - 1/2 Mile ESE	E
16	1/4 - 1/2 Mile West	NNE
17	1/4 - 1/2 Mile WSW	Not Reported
18	1/2 - 1 Mile SSW	Not Reported
D19	1/2 - 1 Mile ESE	NE
E20	1/2 - 1 Mile ESE	NE
E21	1/2 - 1 Mile ESE	varies
22	1/2 - 1 Mile NW	NE
23	1/2 - 1 Mile North	NNW
24	1/2 - 1 Mile SSW	Not Reported
F25	1/2 - 1 Mile South	Not Reported
F26	1/2 - 1 Mile South	NE
27	1/2 - 1 Mile SSE	NNE
28	1/2 - 1 Mile NE	N
29	1/2 - 1 Mile NE	NNE
G30	1/2 - 1 Mile WNW	N
G31	1/2 - 1 Mile WNW	N
32	1/2 - 1 Mile SE	E

5.4 – RADON

A review of the radon results provided in the Physical Setting Appendix of the Radius Map™ Report with GeoCheck® indicates that radon standards (Federal and State) are not exceeded and radon in the area is not a problem. The (Zip Code: 94010) average Living Area 1st floor activity is 1.350 Pico Curies/Liter (pCi/L), which the USEPA is considering this Zone 2 (≥2 pCi/L and

≤4 pCi/L - Federal EPA) indoor average level – first floor (EDR, 2015). The radon information is in Physical Setting appendix of the Radius Map™ Report with GeoCheck® included as Appendix 3.

5.5 – VAPOR ENCROACHMENT SCREEN REPORT

There is no direct evidence of vapor intrusion at the **SP**, and the Ninety-One (91) listings representing: (One (1) for the **SP,** twenty-one (21) for listings within $^{1}/_{10}$ mile representing twelve (13) sites, and Seventy-one (71) listed sites representing forty-seven (47) sites between $^{1}/_{10}$ mile and ⅓ mile) listed as possible have all been dismissed in the VEC screen report. The report is included as Appendix 11. Listings sites were found between 528 feet and 1760 feet[13].

Ninety-One (91) listings, all were ruled out as a Vapor Encroachment Concern (VEC) since they are "not an environmental concern listing", closed, or outside 0.10 of a mile threshold, if down-gradient. Chemicals of concern (COC) are not likely to be a vapor threat to the **SP**. The report is included as Appendix 11.

[13] Second threshold in the VEC calculations.

6.0 – OBSERVATIONS, CONCLUSIONS, AND RECOMMENDATIONS

6.1 - OBSERVATIONS

6.1.1 - General Environmental Inspection

During the general environmental inspection on 11 August 2016, we noted any evidence of contamination or the presence of structures that would lead to suspicion of contamination. The tenants at each Center are tabulated below:

Table 6.1 – Structures at APN: 029-151-150, 029-151-160, 029-151-170

Address	Tenant	Access
1214 Donnelly	unoccupied fire damaged former residential unit that was converted to office spaces	Yes
1218 Donnelly	burned down multiunit residential complex, only foundation remains with one small unoccupied unit	Yes
1220 Donnelly	occupied two bldg 4 unit residential complex with detached 2 car garage	no access inside units, occupied

Inspection of the **SP** revealed no "Recognized Environmental Concerns" (RECs), no "Controlled Recognized Environmental Concerns" (CRECs) and no "Historical Recognized Environmental Concerns" (HRECs). However, other issues of potential concern, as detailed in the Table below, were found. These potential issues were non-Phase I issues that are presented here for convenience.

Table 6.2 - Items Noted at SP

Address	Out-of-Scope Possible Concerns	Non-REC	REC	CREC	HREC	De Minimis
1214 Donnelly	▪ Loose and peeling paint inside 1214 Donnelly. ▪ -Suspect asbestos includes: roofing, sheetrock and JTC, surfacing texture, 9x9 VFT, roofing ▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring
1218 Donnelly	▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	2 soil borings
1220 Donnelly	▪ 2 Five gallon non empty paint container observed on property. ▪ loose and peeling paint observed on the exterior. ▪ Sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring

Notes: Out-of-Scope = beyond scope of ASTM E1527-13, REC = Recognized Environmental Condition, CREC = Controlled Recognized Environmental Condition [subset of REC], HREC = Historical Recognized Environmental Condition, "de minimis" = issue present, but no impact. (all according to E1527-13 definitions), Soil boring were to 4 feet below grade (fbg) and geotechnical in nature.

The adjacent parcels are used as:

- Northeast of properties = Blush Frozen Yogurt @ 1212 Donnelly, Renda Zaarour Hair Salon @ 1210 Donnelly.
- Southeast of properties = Pottery Barn 1230 Burlingame Ave, St Clairs Catering @ 1215 Donnelly, Didi Hair Salon @ 1221 Donnelly.
- Southwest of properties = City of Burlingame Public Parking.
- Northwest of properties = Residential apt complex @ 1211 Lortan Ave.

During this inspection, nothing out of the ordinary was observed. An Area/Neighborhood Drive-By was also performed on 11 August 2016, where nothing out of the ordinary was observed. None of the listed sites within ⅓ of a mile, which is the outer radius for the Vapor Encroachment Concern (VEC) report, is considered a threat even though they can be a REC, CREC[14], or HREC as defined by AAI, or ASTM. The listings were mostly issues with regard to the subsurface soils and petroleum hydrocarbons and dry cleaner chemicals.

6.1.2 - Database Search and Review

6.1.2.1 – Subject Property

The **SP** was identified on four (4) databases of all those searched as part of this study. These are:

Table 6.3 – Listings at SP

Map ID #	Name	Address	Dis (mi)	Dir	Topo	Listing	Status
A1	**JOHN BRITTON**	**1218 DONNELLY AVE**	**SP**	**-**	**-**	**HAZNET**	**LISTED**

Notes: Dis = distance from SP in miles; Dir = direction from SP (west, north, east, south, or some combination); Topo = topographic elevation compared to SP (D: down-gradient/U: up-gradient/E: equivalent); HAZNET = data from hazardous waste manifests..

From our site reconnaissance there is surficial evidence of the fires on two (2) of the three (3) parcels and four shallow soil borings. This listing does not affect the site, and the borings were only four (4) fbg and geotechnical in nature.

6.1.2.2 - Within 1/8 Radius

Based on the information in the EDR database for this search interval, our site reconnaissance, and our understanding of the area, the SP outward to ⅛ of a mile had forty-seven (47) listings, representing ten (10) addresses for environmental concerns. Of these forty-seven (47) listings, one (1) was listed as active: **BURLINGAME HIGH SCHOOL** at 400 Carolan Avenue for a

[14] CREC is a new category under REC, where the site is undergoing mitigation supervised by an agency.

DEED restriction[15]. All the other listings are closed or on a list. No evidence of impact was found during our site reconnaissance. A complete list of "active", "NFA", or "closed" sites, "hazardous substance" listed sites, and "operating permit" listed sites is included in the database search report in Appendix 3.

6.1.2.3 - Between 1/8 and 1/4 Mile Radius

Based on the information in the EDR database for this search interval, and our site reconnaissance, there are one hundred twenty-five (125) listings[16] representing twenty-six (26) addresses. Only seven (7) sites are LUST or SLIC sites that are open, but they in various stages of remediation and do not appear to impact the the **SP**. All the others are either "closed" or on lists. None of these sites poses a threat to the **SP**. A complete list of "active", "NFA", or "closed" sites, "hazardous substance" listed sites, and "operating permit" listed sites is included in the Radius Map™ Report with GeoCheck® in Appendix 3.

6.1.2.4 - Between 1/4 and 1/2 Mile Radius

Within the search radius, there are 102 MINs classified as being of environmental concern, 63 MINs having an operating permit, and 230 MINs on hazardous substance lists. Due to the distance from, and the unlikely event that these sites would materially affect the **SP**, they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

6.1.2.5 - Between 1/2 and 1 Mile Radius

Within the search radius there are 81 MINs classified as being of environmental concern, 72 MINs were listed as having an operating permit, and 36 MINs were on hazardous substance lists. Again, due to the distance from, and the unlikely event, if sites were listed, they would materially affect the SP; they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

6.1.2.6 – Over 1 Mile

Within the search radius, there are 0 MINs classified as being of environmental concern, 0 MINs was listed as having an operating permit, and 5 MINs were on hazardous substance lists. Again, due to the distance from, and the unlikely event, if sites were listed, they would materially affect the SP; they are not presented in the text. The details of the database search are presented in the Radius Map™ Report with GeoCheck® included as Appendix 3.

[15] This site is Certified Operation & Maintenance after remediation and capping.
[16] The one hundred twenty-five (125) listings cover all three categories: (Environmental Concerns, Operating Permits or Lists)

6.1.2.7 - Unmapped Sites

There were three (3) unmapped sites: ENVIROSTOR (2), CDL (1). No addresses had multiple database listings.

6.1.3 - Historical Information Review

The historical information[17] review was Topographic Maps, Sanborn Maps, Aerial Photographs, City Directory, Environmental Liens, and Property Tax Map. There was good correlation between each of these items and nothing out of the ordinary was seen. The EDR reports for each of these sources are attached in Appendices. Building Permits were not found by EDR and are considered a "Data Gap", however, this did not hamper our ability to review the addresses. The EDR documentation for this is also included.

6.1.4 - Geology and Hydrogeology

The **SP** is located west of the San Francisco Bay. The **SP** is in a commercial/residential area that is north of Howard Avenue and south of California Avenue in Burlingame in San Mateo County with listed properties up-gradient and down-gradient. The shallow subsurface is made of alluvial deposits (clayey silts to silty sands in nature): these fine-grained soils go to approximately 20 - 25 feet below grade (fbg). Weathered bedrock and Bay Mud underlie the area from the northwest to northeast toward the bay at various depths and various thicknesses (Norris & Webb, 1990) and weathered and unweathered bedrock underlie the area from the southeast to the southwest. The area topography gently rises from the north to the **SP** and then more noticeably to the south. The topography slopes downward from west to the **SP** and then continues sloping gently downward to the east (see Physical Setting Appendix to the Radius Map™ Report with GeoCheck® for north to south elevation profile and a west to east elevation profile). There is no direct evidence of vapor intrusion at the **SP**, and the Ninety-One (91) listings representing: (One (1) for the **SP,** twenty-one (21) for listings within $^{1}/_{10}$ mile representing twelve (13) sites, and Seventy-one (71) listed sites representing forty-seven (47) sites between $^{1}/_{10}$ mile and ⅓ mile) listed as possible have all been dismissed in the VEC screen report. The report is included as Appendix 11. Listings sites were found between 528 feet and 1760 feet[18]..

A review of the radon results provided in the physical setting section of the Radius Map™ Report with GeoCheck® indicates that radon in the area is not a problem.

[17] Sanborn maps were not available.
[18] Second threshold in the VEC calculations.

6.2 - CONCLUSIONS

During our 11 August 2016 inspection, nothing out of the ordinary was observed and an Area/Neighborhood Drive-By was also performed on 11 August 2016, where nothing out of the ordinary was observed. There is surficial evidence (some staining and fire damage) of impact to the site, but no subsurface evidence of impact from the database listings for the **SP**. The listings around the site do not appear to affect the **SP** either.

6.3 - RECOMMENDATIONS

Nothing unusual was seen during our site inspection or our data review. However, during any building renovation or demolition activities, we recommend:

a. Following all Asbestos-Containing Materials (ACM), Lead-Based Paint (LBP) and Lead-Containing Materials (LCM) regulations and requirements with regard to identifying, handling, and disposal
b. Following all HAZMAT regulations and requirements with regard to identification, characterization, waste and debris disposal, and recycling.

7.0 - REFERENCES

ASTM, 2013, Phase I Environmental Site Assessment Process, ASTM Designation: E1527-05.

_____, 2000, Transaction Screening Process, ASTM Designation: E1528.

_____, 2002, Phase II Environmental Site Assessment Process, ASTM Designation: E1903.

California Code of Regulations, Title 8; Department of Industrial Relations - California Occupational Safety and Health Regulations (Title 8).

_____, Title 22: Social Security; Division 4: Environmental Health and Division 4.5: Chapter 11: Identification of Hazardous Waste; article 3: Characterization of Hazardous Waste (Title 22).

Code of Federal Regulations, Title 29; part 1910: Occupational Safety and Health Standards (29 CFR).

_____, Title 40; part 261; subpart B - Criteria for identifying the Characteristics of Hazardous Waste and for Listing Hazardous Waste, and subpart C - Characteristics of Hazardous Waste (40 CFR).

Designated Level Methodology for Waste Classification and Cleanup Level Determination; California Regional Water Quality Control Board, Central Valley Region (Marshack Document).

Dragun & Chiasson, 1991, Elements in North American Soils.

Environmental Data Resources, Inc. (EDR), 2016, The EDR Radius Map with GeoCheck®, **Donnelly,** 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.2s, August 02, 2016.

_____, 2016, The EDR – Historical Topographic Map Report, **Donnelly**, 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.4, August 01, 2016.

_____, 2016, Sanborn® Map Report, **Donnelly** , 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.3, August 01, 2016.

_____, 2016, The EDR – Aerial Photo Decade Package, **Donnelly**, 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.12, August 01, 2016.

_____, 2016, The EDR-City Directory Abstract, **Donnelly**, 1214 Donnelly, Burlingame, CA,

94010, Inquiry Number: 4688986.5, August 02, 2016.

_____, 2016, The EDR Environmental Liens and AUL Report, **Donnelly**, 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.7, August 04, 2016.

_____, 2016, The EDR Tax Map Report, **Donnelly**, 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.6, August 01, 2016.

_____, 2016, The EDR Building Permit Report, **Donnelly**, 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.8, August 01, 2016.

_____, 2016, The EDR Vapor Encroachment Screen Report, **Donnelly,** 1214 Donnelly, Burlingame, CA, 94010, Inquiry Number: 4688986.9s, August 16, 2016.

Environmental Protection Agency, 2004, Test Methods for Evaluating Solid Waste, Physical/Chemical Methods.

Norris, Robert M, & Webb, Robert W., 1990, Geology of California, Second Edition

ProTech Consulting & Engineering, 2006, *Phase I - Environmental Site Assessment & "Limited" Phase II – Environmental Site Assessment*, 250 San Antonio Road, Mountain View, CA, March 2006.

Scott, 1995, Background Metal Concentrations in Soil in Northern Santa Clara County, California.


Table

Table 1 - Geotracker Listings within 1760 feet (⅓ mile)

1214 - 1220 Donnelly Avenue, Burlingame, CA

SITE NAME	GLOBAL ID	FAC ID	STATUS	ADDRESS	CITY
200 PARK	T10000004152		OPEN - ASSESSMENT & INTERIM REMEDIAL	200 PARK ROAD	BURLINGAME
ARATA PROPERTY	T0608101044		COMPLETED - CASE CLOSED	198 CALIFORNIA DRIVE	BURLINGAME
ARLINGTON APARTMENTS	T10000005179		COMPLETED - CASE CLOSED	1401 FLORIBUNDA AVENUE	BURLINGAME
BERENSTEIN ASSOC. PROPERTY	T0608186803		OPEN - SITE ASSESSMENT	1319 HOWARD	BURLINGAME
BUBBLE CAR WASH		41-000-660026		177 CALIFORNIA DR	BURLINGAME
BURLINGAME POST OFFICE	T0608100091		COMPLETED - CASE CLOSED	220 PARK	BURLINGAME
CHEVRON 9-0571	T0608100128		COMPLETED - CASE CLOSED	260 EL CAMINO REAL	BURLINGAME
CHEVRON 9-0571		41--017976		260 EL CAMINO REAL	BURLINGAME
CHEVRON, FORMER/EAGLE GAS STA	T0608194030		COMPLETED - CASE CLOSED	177 CALIFORNIA	BURLINGAME
DEITER BLUHM	T0608100073		COMPLETED - CASE CLOSED	1285 OAK GROVE	BURLINGAME
HARRIS PROPERTY	T0608100253		OPEN - REMEDIATION	1234 HOWARD	BURLINGAME
KIM MILLS TEXACO (FORMER)	T10000003636		COMPLETED - CASE CLOSED	401 CALIFORNIA	BURLINGAME
KING YEE PROPERTY	T0608100813		OPEN - REMEDIATION	1200 HOWARD	BURLINGAME
KIRKBRIDE PROPERTY	T0608100953		COMPLETED - CASE CLOSED	307 LORTON	BURLINGAME
LORTON PLACE OWNERS ASSOCIATION	T10000004932		COMPLETED - CASE CLOSED	345 LORTON AVENUE	BURLINGAME
PACIFIC BELL	T0608100377		COMPLETED - CASE CLOSED	1480 BURLINGAME	BURLINGAME
PACIFIC BELL		41-000-022765		1480 BURLINGAME AVE.	BURLINGAME
SABATINI TRUST	T10000004188		COMPLETED - CASE CLOSED	361 CALIFORNIA	BURLINGAME
SHELL	T0608100468		COMPLETED - CASE CLOSED	1490 BURLINGAME	BURLINGAME
SHELL	T0608100487		COMPLETED - CASE CLOSED	601 CALIFORNIA	BURLINGAME
STERLING CLEANERS	T10000006541		OPEN - SITE ASSESSMENT	1140 HOWARD AVENUE	BURLINGAME
STERLING CLEANERS (FORMER)	T10000005652		OPEN - SITE ASSESSMENT	215 CALIFORNIA DRIVE	BURLINGAME
STERLING CLEANERS (FORMER)	T10000003211		OPEN - SITE ASSESSMENT	215 CALIFORNIA DRIVE	BURLINGAME
W. J. BRITTON COMPANY	T0608100626		COMPLETED - CASE CLOSED	701 CALIFORNIA	BURLINGAME

Figures



ProTech Consulting & Engineering
1208 Main Street, Redwood City, CA 94063
Tele: 650.569.4020 / Fax: 650.569.4023

Job No.	601-16
Date	06 Sept 2016
Drawn by	WL
Rev	RC
Apprvd	WL

Site Location

Project
Phase I - 1214-1220 Donnelly Avenue
Burlingame, CA
for: John Burton
W.J. Burton Co.
1345 Mission St., San Francisco

N

Figure
1



ProTech Consulting & Engineering
1208 Main Street, Redwood City, CA 94063
Tele: 650.569.4020 / Fax: 650.569.4023

Job No.	601-16
Date	06 Sept 2016
Drawn by	WL
Rev	RC
Apprvd	WL

Site Vicinity

Project
Phase I - 1214-1220 Donnelly Avenue
Burlingame, CA
for: John Burton
W.J. Burton Co.
1345 Mission St., San Francisco

N

Figure
2



ProTech Consulting & Engineering
1208 Main Street, Redwood City, CA 94063
Tele: 650.569.4020 / Fax: 650.569.4023

Job No.	601-16
Date	06 Sept 2016
Drawn by	WL
Rev	RC
Apprvd	WL

Site Layout


Project

Phase I - 1214-1220 Donnelly Avenue
Burlingame, CA
for: John Burton
W.J. Burton Co.
1345 Mission St., San Francisco

N

Figure

3



From: EDR, 2016

ProTech Consulting & Engineering
1208 Main Street, Redwood City, CA 94063
Tele: 650.569.4020 / Fax: 650.569.4023

Job No.	601-16
Date	06 Sept 2016
Drawn by	WL
Rev	RC
Apprvd	WL


Assessor Parcel Map

Project

Phase I - 1214-1220 Donnelly Avenue
Burlingame, CA
for: John Burton
W.J. Burton Co.
1345 Mission St., San Francisco

N

Figure **4**




SITES FOUND IN SEARCH RADIUS

http://geotracker.waterboards.ca.gov/map/?CMD=runreport&myaddress=60000822 Page 1 of 1

▲ - SP

ProTech Consulting & Engineering 1208 Main Street, Redwood City, CA 94063 Tele: 650.569.4020 / Fax: 650.569.4023					Geotracker Sites w/in 1760 ft Project Phase I - 1214-1220 Donnelly Avenue Burlingame, CA for: John Burton W.J. Burton Co. 1345 Mission St., San Francisco	Figure 5
Job No. 601-16	Date 06 Sept 2016	Drawn by SL	Rev. RC	Apprvd. SL		



SITES FOUND IN SEARCH RADIUS

- SP

ProTech Consulting & Engineering 1208 Main Street, Redwood City, CA 94063 Tele: 650.569.4020 / Fax: 650.569.4023					Satellite w/in 1760 ft Project Phase I - 1214-1220 Donnelly Avenue Burlingame, CA for: John Burton W.J. Burton Co. 1345 Mission St., San Francisco		Figure 6
Job No. 601-16	Date 06 Sept 2016	Drawn by SL	Rev. RC	Apprvd. SL			

Appendix 1 - Environmental Inspection Form

ENVIRONMENTAL INSPECTION FORM

INSPECTION LOCATION

Property Address: **1214 – 1220 Donnelly Avenue**
City/County: **Burlingame / San Mateo**
State/Zip: **California**
Legal Description: **See Environmenal Liens Section**
APNs **029-151-150, 029-151-160, 029-151-170**
Property Is: ☐ Vacant Land ☒ Improved
Occupied By Whom:
Describe:
Report Prepared for:
Environmental Inspector: **Ryan Cozart**
Date: **11 August 2016**

PROPERTY DESCRIPTION & ANALYSIS

Current Use of Property: ☒ Residential ☒ Commercial ☐ Industrial ☐ Undeveloped Land ☐ Other:

Past Property Use (if known): ☒ Residential ☒ Commercial ☐ Industrial ☐ Undeveloped Land ☐ Other:

Past Tenants Business: 1.
Time at Location:
2.
Time at Location:
3.
Time at Location
Current Tenants Business:
Time at Location:

Comments:

Address	Tenant	Access
1214 Donnelly	unoccupied fire damaged former residential unit that was converted to office spaces	Yes
1218 Donnelly	burned down multiunit residential complex, only foundation remains with one small unoccupied unit	Yes
1220 Donnelly	occupied two bldg 4 unit residential complex with detached 2 car garage	no access inside units, occupied

GENERAL FIELD OBSERVATIONS

Subject Property:

Were there any physical signs of the following observed on the property? ☒ Yes ☐ No

☐ Underground Storage Tanks	☐ Streams, Lakes or ponds	☒ Lead Paint
☐ Aboveground Storage Tanks	☐ Storage Buildings/Rooms	☐ Unlabeled Drums
☐ Stained Soil	☐ Batteries	☒ Asbestos
☐ Vegetation Damage	☐ Oil/Gas Drums	☐ Groundwater wells
☐ Oily Sheens on Water	☐ Septic System	☐ Hydraulic Lifts
☐ Hydraulic Elevators		

Adjacent Property:

Were there any physical signs of the following observed on the property? ☐ Yes ☒ No

☐ Underground Storage Tanks	☐ Streams, Lakes or ponds	☐ Lead Paint
☐ Aboveground Storage Tanks	☐ Storage Buildings/Rooms	☐ Unlabeled Drums
☐ Stained Soil	☐ Discarded Batteries	☐ Asbestos
☐ Vegetation Damage	☐ Oil/Gas Drums	☐ Groundwater wells
☐ Oily Sheens on Water	☐ Septic System	☐ Hydraulic Lifts
☐ Hydraulic Elevators		

Comments:

Map ID #	Name	Address	Dis (mi)	Dir	Topo	Listing	Status
A1	JOHN BRITTON	1218 DONNELLY AVE	SP	-	-	HAZNET	LISTED

Notes: Dis = distance from SP in miles; Dir = direction from SP (west, north, east, south, or some combination); Topo = topographic elevation compared to SP (D: down-gradient/U: up-gradient/E: equivalent); HAZNET = data from hazardous waste manifests..

STORAGE BUILDINGS/ROOMS, STORAGE TANKS INSPECTION

Storage Buildings/Rooms:

☐ Yes ☒ No Are any buildings or rooms present that may contain or have contained hazardous materials for storage purposes**?**

☒ Yes ☐ No Is there any indication that hazardous materials/waste are or have been stored on the property? - **paints**

☐ Yes ☐ No Are there plans for the layout of this facility?

Underground Storage Tanks (UST's):

☐ Yes ☒ No Were any underground storage tanks observed on the property?

☐ Yes ☒ No Did any tanks, if present, contain any materials, liquid or solid?

☐ Yes ☒ No Was any evidence of soil contamination observed around the surface cover of the tanks, if present, on the property?

☐ Yes ☒ No Were any chemical plants, manufacturing plants, gas stations or petroleum refining, delivery or storage facilities observed on surrounding properties?

☐ Yes ☒ No Are there plans for the underground storage tanks, if in use or present in the past?

Aboveground Storage Tanks (AST's):

☐ Yes ☒ No Were any aboveground storage tanks observed on the property?

☐ Yes ☒ No Was any evidence of soil contamination observed around the tanks, if present, on the property?

☐ Yes ☒ No Were any chemical plants, manufacturing plants, gas stations or petroleum refining, delivery or storage facilities observed on surrounding properties?

☐ Yes ☒ No Are there plans for the aboveground storage tanks, if in use or present in the past?

Waste Sites:

☐ Yes ☒ No Is the subject or any neighboring property engaged in storing, transporting or producing waste, chemicals or hazardous substances?

Comments:

The adjacent parcels are used as:

- Northeast of properties = Blush Frozen Yogurt @ 1212 Donnelly , Renda Zaarour Hair Salon @ 1210 Donnelly.
- Southeast of properties = Pottery Barn 1230 Burlingame Ave, St Clairs Catering @ 1215 Donnelly, Didi Hair Salon @ 1221 Donnelly.
- Southwest of properties = City of Burlingame Public Parking.
- Northwest of properties = Residential apt complex @ 1211 Lortan Ave.

WATER RESOURCES INSPECTION

Surface Water:

☐ Yes ☒ No Are there any surface water bodies on the site or passing through it?
☐ Yes ☒ No Was there any evidence of contamination on these surface water bodies (odors, sheen, etc)?
☐ Yes ☒ No Are there plans for the surface water drainage system of this facility?

Groundwater: - Not Tested

☐ Yes ☒ No Were any groundwater monitoring wells, in use or abandoned, observed on the property?
☐ Yes ☒ No Was there any evidence of contamination around the well?
☐ Yes ☒ No Was there any evidence of contamination in the well (odors, sheen, etc.)?
☐ Yes ☒ No Are there plans for the groundwater system of this facility, if one is or was present?

Drinking Water:

☐ Yes ☒ No Were any water wells, in use or abandoned, observed on the property?
☐ Yes ☒ No Are these wells the primary or sole source of drinking water?
☒ Yes ☐ No Is SP on municipal drinking water?
☐ Yes ☒ No Are lead or lead soldered pipes visible on the property?
☐ Yes ☒ No Are there plans for the drinking water system of this facility?

Septic System:

☐ Yes ☒ No Was a septic system, in use or abandoned, observed on the property?
☒ Yes ☐ No Is the property presently on a municipal sewer system?
☐ Yes ☒ No Are there plans for the septic system of this facility?

Drains:

☐ Yes ☒ No Are drains present in work areas that could be used for draining liquids from cleaning or flushing machinery or equipment?
☐ Yes ☒ No Are the drains full?
☐ Yes ☒ No Are the drains coated heavily with sludge-type materials?
☐ Yes ☒ No Are there plans for the drain system of this facility?

Comments:

Address	Tenant	Access
1214 Donnelly	unoccupied fire damaged former residential unit that was converted to office spaces	Yes
1218 Donnelly	burned down multiunit residential complex, only foundation remains with one small unoccupied unit	Yes
1220 Donnelly	occupied two bldg 4 unit residential complex with detached 2 car garage	no access inside units, occupied

CHEMICAL, GAS & MINERAL INSPECTION

Asbestos: -Reported Under Separate Cover-Suspect

☒ Yes ☐ No Were signs of asbestos observed on the property?

☒ Yes ☐ No Was the structure constructed prior to 1979?

☒ Yes ☐ No Were any suspected asbestos containing materials observed; such as sprayed materials on fireproofing areas, pipe insulation, floor tiles, etc?

UREA Formaldehyde Foam Insulation (UFFI):

☐ Yes ☒ No Was any evidence of Formaldehyde Foam Insulation observed on the property?

Lead Paint: - Reported Under Separate Cover-Suspect

☒ Yes ☐ No Was any visible evidence of peeling, cracking or flaking paint observed?

☒ Yes ☐ No Was any visible evidence of lead paint on the ceilings, walls or floors of any structure observed on the property?

Pesticides/Herbicides:

☐ Yes ☒ No Does it appear pesticides or herbicides have been used in excess of normal use?

☐ Yes ☒ No Is the property used for agricultural purposes?

☐ Yes ☒ No Are there any noticeable pesticide/herbicide odors?

Fiberglass:

☐ Yes ☒ No Is fiberglass observed as an insulator or for any other purpose?

☐ Yes ☒ No Is fiberglass observed on any surface that appears worn, where individual fibers are exposed in a condition where release into the air appears likely?

Polychlorinated Biphenyls (PCB's):

☐ Yes ☒ No Were any transformers, electrical devices or hydraulic equipment observed on the property labeled as containing PCB's

☐ Yes ☒ No Was evidence of PCB contamination to the soil, surface water or groundwater observed on the property?

☐ Yes ☒ No Were any fluorescent light ballasts suspected to contain or labeled as containing PCB's observed?

Mercury:

☐ Yes ☐ No Are there mercury switches present?

☐ Yes ☐ No Are there fluorescent tubes present?

Radon:

☒ Yes ☐ No Is there reason to suspect that radon may be a problem in the dwelling or in the immediate property's locality?

☐ Yes ☒ No Has screening been conducted which indicates that the property may have elevated levels of radon?

Comments:

Address	Out-of-Scope Possible Concerns	Non-REC	REC	CREC	HREC	De Minimis
1214 Donnelly	▪ Loose and peeling paint inside 1214 Donnelly. ▪ -Suspect asbestos includes: roofing, sheetrock and JTC, surfacing texture, 9x9 VFT, roofing ▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring
1218 Donnelly	▪ Approximately 15 Five gallon non empty paint container observed on properties. ▪ Approximately 70 one gallon non empty paint containers observed on properties. ▪ Approximately 10 non empty containers of stains, wood protectors, and sealers on properties. ▪ sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	2 soil borings
1220 Donnelly	▪ 2 Five gallon non empty paint container observed on property. ▪ loose and peeling paint observed on the exterior. ▪ Sump pump. ▪ No staining observed on the property.	NONE	NONE	NONE	NONE	1 soil boring

Notes: Out-of-Scope = beyond scope of ASTM E1527-13, REC = Recognized Environmental Condition, CREC = Controlled Recognized Environmental Condition [subset of REC], HREC = Historical Recognized Environmental Condition, "de minimis" = issue present, but no impact. (all according to E1527-13 definitions), Soil boring were to 4 feet below grade (fbg) and geotechnical in nature.

GENERAL

☐ Yes ☒ No Are there any conditions present not mentioned above that need to be corrected to remove any potential risks?

☐ Yes ☒ No Activities on adjacent properties that pose potential environmental risks to the subject property?

SUMMARY & CONCLUSIONS OF INSPECTION

Underground Storage Tanks (UST's):
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Asbestos:
☐ Acceptable
☒ Suggest Phase II Environmental Audit

Aboveground Storage tanks (AST's):
☒ Acceptable
☐ Suggest Phase II Environmental Audit

UREA Formaldehyde Foam Insulation (UFFI):
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Waste Sites:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Lead Paint:
☐ Acceptable
☒ Suggest Phase II Environmental Audit

Surface Water:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Pesticides/Herbicides:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Groundwater: - Not Tested
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Polychlorinated Biphenyls (PCB's):
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Drinking Water:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Radon:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Septic System:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Hydraulic Lifts
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Elevators:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

Mercury:
☒ Acceptable
☐ Suggest Phase II Environmental Audit

CERTIFICATION

I certify that to the best of my knowledge and belief the facts and data used and presented in this inspection are true and accurate, based on currently accepted and available information as of the inspection date; I personally supervise the inspector of the subject property; and we have no undisclosed interest, present or prospective therein.

Addendums are attached and are made a part of this report. Number of pages attached **0**

Sherwood Lovejoy, Jr.
Environmental Assessor

Appendix 2 – Selected Photographs



Figure 1-1214 Donnelly Southwest side fire damage



Figure 2-1218 Donnelly foundation and small unit behind



Figure 3-1214 Donnelly front



Figure 4-1214 Donnelly Northeast side



Figure 5-1214 Donnelly rear



Figure 6-1214 Donnelly Southwest side



Figure 7-1218 Donnelly small unit behind




Figure 8-1214 Donnelly Paint Containers



Figure 9-1218 Donnelly foundation and small unit behind



Figure 10-1214 Donnelly loose and peeling paint



Figure 11-1214 Donnelly loose and peeling paint



Figure 12-1214 Donnelly fire damage



Figure 13-1214 Donnelly Paint containers



Figure 14-1214 Donnelly Paint containers



Figure 15-1214 Donnelly Paint container




Figure 16-1214 Donnelly Paint containers



Figure 17-1218 Donnelly Paint container



Figure 21-1218 Foundation



Figure 18-1218 Donnelly Paint containers



Figure 22-1218 Drain



Figure 19-1218 Donnelly Paint containers




Figure 23-1220 Donnelly Front



Figure 20-1218 Donnelly Sump




Figure 24-1220 Donnelly Northeast side



Figure 25-1220 Rear unit



Figure 29-1220 Rear Unit



Figure 26-1220 Garages



Figure 30-1220 fire extinguisher



Figure 27-1220 Sump pump



Figure 31-1220 Paint containers



Figure 28-1220 Sump pump



Figure 32-1220 Loose and Peeling Paint



Figure 33-1214 Sump pump



Figure 36-1218 Boring



Figure 34-1214 Drain



Figure 37-1218 Boring



Figure 35-1214 Boring



Figure 38-1220 Boring

Appendix 3 - Database Search Report

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.2s
August 02, 2016

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	863
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-6
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

1214 DONNELLY
BURLINGAME, CA 94010

COORDINATES

Latitude (North):	37.5795060 - 37° 34' 46.22''
Longitude (West):	122.3477890 - 122° 20' 52.04''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	557589.6
UTM Y (Meters):	4159157.2
Elevation:	32 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5640626 SAN MATEO, CA
Version Date:	2012
West Map:	5641104 MONTARA MOUNTAIN, CA
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140608
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	JOHN BRITTON	1218 DONNELLY AVE	HAZNET		TP
A2	CITY BURLINGAME/PUB	1230 DONNELLY AVE	HAZNET	Higher	1 ft.
A3	MIKE'S AUTOMOTIVE SE	1212 DONNELLY AVENUE	HAZNET	Higher	114, 0.022, ENE
A4	MIKES AUTOMOTIVE SER	1212 DONNELLY	San Mateo Co. BI	Higher	114, 0.022, ENE
A5	LORTON PLACE OWNERS	345 LORTON AVENUE	LUST	Lower	130, 0.025, North
A6	KIRKBRIDE PROPERTY	307 LORTON	RGA LUST	Higher	308, 0.058, East
A7	COMMERCIAL BUILDING	307 LORTON	San Mateo Co. BI	Higher	308, 0.058, East
A8	KIRKBRIDE PROPERTY	307 LORTON AVE	RGA LUST	Higher	308, 0.058, East
A9	KIRKBRIDE PROPERTY	307 LORTON	LUST	Higher	308, 0.058, East
A10	KIRKBRIDE PROPERTY	307 LORTON	LUST, HIST CORTESE	Higher	308, 0.058, East
A11	KIRKBRIDE PROPERTIES	307 LORTON AVE	HAZNET	Higher	308, 0.058, East
A12	SABATINI TRUST	361 CALIFORNIA	LUST	Lower	310, 0.059, NE
A13	DON SABATINI	361 CALIFORNIA DR	HAZNET	Lower	310, 0.059, NE
A14	DON SABATINI	361 CALIFORNIA DR	LUST, HAZNET	Lower	310, 0.059, NE
A15	RODGER REINHART LESL	1241 BURLINGAME AVE	HAZNET	Higher	372, 0.070, ESE
A16	UST SITE	361 CALIFORNIA	San Mateo Co. BI	Lower	374, 0.071, NE
A17	SABATINI TRUSTS	361 CALIFORNIA DR	HAZNET	Lower	374, 0.071, NE
A18	UST SITE	361 CALIFORNIA	San Mateo Co. BI	Lower	374, 0.071, NE
A19	SABATINI TRUST	361 CALIFORNIA	RGA LUST	Lower	374, 0.071, NE
A20	ANN TAYLOR S0497/BUR	1325 BURLINGAME AVE	HAZNET	Higher	375, 0.071, SSE
A21	KIRKBRIDE PROPERTIES	1202 BURLINGAME AVE	HAZNET	Higher	375, 0.071, ESE
A22		1229 BURLINGAME AVE.	FINDS, ECHO	Higher	380, 0.072, ESE
A23	GERRITSON PROPERTY	1229 BURLINGAME AVE	RGA LUST	Higher	380, 0.072, ESE
A24	KIM MILLS TEXACO (FO	401 CALIFORNIA	RGA LUST	Lower	386, 0.073, North
A25	KIM MILLS TEXACO (FO	401 CALIFORNIA	LUST	Lower	386, 0.073, North
A26	UST SITE	401 CALIFORNIA	San Mateo Co. BI	Lower	386, 0.073, North
A27	401 ALPROP LLC	401 CALIFORNIA DR	HAZNET	Lower	386, 0.073, North
A28	UST SITE	401 CALIFORNIA	San Mateo Co. BI	Lower	386, 0.073, North
A29	CITY NATIONAL BANK	350 PRIMROSE RD	HAZNET	Higher	389, 0.074, SW
A30	REDLICH JR, CHRISTOP	360 PRIMROSE	San Mateo Co. BI	Higher	393, 0.074, WSW
A31		345 CALIFORNIA DR	EDR Hist Cleaner	Lower	395, 0.075, NE
A32	KARP FAMILY TRUST	1209 BURLINGAME	HAZNET	Higher	397, 0.075, ESE
A33	AW DEVELOPMENT INC	330 PRIMROSE RD STE	HAZNET	Higher	415, 0.079, SSW
A34	MIKE WOODS	330 PRIMROSE RD	HAZNET	Higher	415, 0.079, SSW
A35	VERIZON WIRELESS EL	330 PRIMROSE RD STE	FINDS, ECHO	Higher	415, 0.079, SSW
A36	VERIZON WIRELESS EL		San Mateo Co. BI	Higher	415, 0.079, SSW
A37	AVTAR JOHAL FAMILY &	1301 BURLINGAME AVE	HAZNET	Higher	426, 0.081, SSE
A38	AUTAR JOHAL PROPERTY	1301 BURLINGAME	San Mateo Co. BI	Higher	426, 0.081, SSE
A39	R & B EQUIPMENT	1301 BURLINGAME AVE	HAZNET	Higher	426, 0.081, SSE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A40	CAMMISSA MOTOR CAR C	321 CALIFORNIA DR	HAZNET	Higher	426, 0.081, ENE
A41	CAMMISA MOTOR CAR CO	321 CALIFORNIA DRIVE	EMI	Higher	426, 0.081, ENE
A42	GOLDEN STATE BREWING	321 CALIFORNIA AVENU	HAZNET	Higher	426, 0.081, ENE
A43		339 PRIMROSE RD	EDR Hist Cleaner	Higher	439, 0.083, SSW
A44	PRIMROSE CLEANERS	339 PRIMROSE RD	HAZNET	Higher	439, 0.083, SSW
A45	PRIMROSE CLEANERS	339 PRIMROSE RD	DRYCLEANERS	Higher	439, 0.083, SSW
A46	PRIMROSE CLEANERS	339 PRIMROSE ROAD	FINDS, EMI, ECHO	Higher	439, 0.083, SSW
A47	PRIMROSE CLEANERS	339 PRIMROSE	San Mateo Co. BI	Higher	439, 0.083, SSW
A48	NEW GATES GLOBE CLEA	339 PRIMROSE ROAD	HAZNET	Higher	439, 0.083, SSW
A49	GATES GLOBE CLEANERS	339 PRIMROSE RD	HAZNET	Higher	439, 0.083, SSW
A50	GW WILLIAMS COMPANY	329 PRIMROSE RD	HAZNET	Higher	441, 0.084, SSW
A51	WOODSTOCK-BOWERS LLC	329 PRIMROSE RD	HAZNET	Higher	441, 0.084, SSW
A52		337 PRIMROSE RD	EDR Hist Cleaner	Higher	442, 0.084, SSW
A53	SEPHORA STORE 52 BUR	1205 BURLINGAME AVEN	FINDS, ECHO	Higher	451, 0.085, ESE
A54	HARRIS & CRISAFI C/O	1205 HOWARD AVENUE	FINDS, ECHO	Higher	451, 0.085, ESE
A55	HARRIS & CRISAFI C/O	1205 HOWARD AVENUE	EMI	Higher	451, 0.085, ESE
A56	SEPHORA STORE 52 BUR	1205 BURLINGAME AVEN	RCRA-SQG	Higher	451, 0.085, ESE
A57	KARP FAMILY TRUST	1205 BURLINGAME AVE/	HAZNET	Higher	451, 0.085, ESE
A58	SEPHORA #052	1205 BURLINGAME	San Mateo Co. BI	Higher	451, 0.085, ESE
A59	SEPHORA STORE 52 BUR	1205 BURLINGAME AVE	HAZNET	Higher	451, 0.085, ESE
A60	CITY OF BURLINGAME	480 PRIMROSE RD	HAZNET	Lower	464, 0.088, West
B61	AVENUE PLAZA	1110 BURLINGAME AVE	HAZNET	Higher	494, 0.094, East
B62	AVENUE PLAZA	1110 BURLINGAME AVE	HAZNET	Higher	494, 0.094, East
C63	LW DESIGN HAIR SALON	309 PRIMROSE RD	HAZNET	Higher	512, 0.097, SSW
C64	PICKRELL D J	1408 CHAPIN AVE	SEMS-ARCHIVE	Higher	519, 0.098, WSW
B65	88 PHOTO LAB	1109 BURLINGAME	San Mateo Co. BI	Higher	524, 0.099, East
B66	88 PHOTO LAB	1109 BURLINGAME AVEN	HAZNET	Higher	524, 0.099, East
B67	CRYO CREAM	240 PARK	San Mateo Co. BI	Higher	530, 0.100, SE
C68	HAAG N HAAG	1402 BURLINGAME AVEN	HAZNET	Higher	532, 0.101, SSW
C69	JOSEPH KARP	1411 CHAPIN AVE	HAZNET	Higher	535, 0.101, SW
C70	EDWARD ZUKAUSKAS	1410 BURLINGAME AVE	HAZNET	Higher	581, 0.110, SSW
D71	CITY OF BURLINGAME	425 CAROLAN AVENUE	FINDS, ECHO	Lower	582, 0.110, NNE
D72	CITY OF BURLINGAME	425 CAROLAN AVENUE	EMI	Lower	582, 0.110, NNE
E73	JOHN K LEUNG DDS	500 PRIMROSE RD	HAZNET	Lower	586, 0.111, WNW
E74	DR SCOTT HALLSTED	500 PRIMROSE RD	HAZNET	Lower	586, 0.111, WNW
C75	LINO NICCOLI	277 PRIMROSE RD	HAZNET	Higher	599, 0.113, South
E76	BURLINGAME CITY HALL	501 PRIMROSE RD	HAZNET	Lower	610, 0.116, West
E77	CITY OF BURLINGAME	501 PRIMROSE ROAD	FINDS, ECHO	Lower	610, 0.116, West
E78	CITY OF BURLINGAME	501 PRIMROSE RD	HAZNET	Lower	610, 0.116, West

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E79	CITY OF BURLINGAME	501 PRIMROSE RD	HAZNET	Lower	610, 0.116, West
E80	CTY OF SAN MATEO	501 PRIMROSE RD	San Mateo Co. BI, HAZNET	Lower	610, 0.116, West
E81	CITY OF BURLINGAME	501 PRIMROSE RD	HAZNET	Lower	610, 0.116, West
E82	CITY OF BURLINGAME	501 PRIMROSE ROAD	EMI	Lower	610, 0.116, West
D83	SAN MATEO UNION HIGH	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D84	BURLINGAME HIGH SCHO	400 CAROLAN AVENUE	FINDS, ECHO	Lower	616, 0.117, NNE
D85	BURLINGAME HIGH SCHO	400 CAROLAN AVENUE	ENVIROSTOR, SCH, DEED	Lower	616, 0.117, NNE
D86	SAN MATEO UNION HIGH	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D87	BURLINGAME HIGH SCHO	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D88	SAN MATEO UNION H/S	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D89	SAN MATEO UNION HIGH	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D90	SAN MATEO UNION HIGH	400 CAROLAN AVE	HAZNET	Lower	616, 0.117, NNE
D91	BURLINGAME HS	400 CAROLINE AVE	HAZNET	Lower	616, 0.117, NNE
D92	PARK DEPT CORPORATIO	420 CAROLAN	HIST UST	Lower	618, 0.117, NNE
D93	CITY OF BURLINGAME P	420 CAROLAN AVE	HAZNET	Lower	618, 0.117, NNE
C94	WELLS FARGO BANK	261 PARK ROAD	HAZNET	Higher	620, 0.117, SSE
B95	BLUE CHALK CAFE	1100 BURLINGAME AVE	HAZNET	Higher	621, 0.118, East
D96		442 CALIFORNIA DR	CDL	Lower	624, 0.118, NNW
C97	LINO NICCOLI	269 PRIMROSE RD	HAZNET	Higher	626, 0.119, South
B98	BURLINGAME AVENUE ST	BURLINGAME AVENUE BE	NPDES	Higher	628, 0.119, East
B99	BURLINGAME POST OFFI	220 PARK	RGA LUST	Higher	629, 0.119, SE
B100	BURLINGAME POST OFFI	220 PARK	RGA LUST	Higher	629, 0.119, SE
B101	BURLINGAME POST OFFI	220 PARK RD	RGA LUST	Higher	630, 0.119, SE
B102	BURLINGAME POST OFFI	220 PARK	LUST	Higher	630, 0.119, SE
B103	BURLINGAME POST OFFI	220 PARK ROAD	RGA LUST	Higher	630, 0.119, SE
B104	US POSTAL SERVICE	220 PARK RD	HAZNET	Higher	630, 0.119, SE
B105	US POSTAL SERVICE	220 PARK	LUST, HIST CORTESE	Higher	630, 0.119, SE
B106	US POSTAL SERVICE	220 PARK RD	HAZNET	Higher	630, 0.119, SE
B107	1X U. S. POSTAL SERV	220 PARK ROAD	HAZNET	Higher	630, 0.119, SE
B108	US POSTAL SERVICE	220 PARK RD	RGA LUST	Higher	630, 0.119, SE
B109	PENINSULA CORRIDOR J	290 CALIFORNIA DR	HAZNET	Higher	632, 0.120, ENE
B110	CALTRAIN	290 CALIFORNIA DR	HAZNET	Higher	632, 0.120, ENE
C111	CITY OF BURLINGAME	1415 BURLINGAME AVE	HAZNET	Higher	636, 0.120, SSW
C112	NEXTEL-SITE ID CA-03	1420 BURLINGAME	San Mateo Co. BI	Higher	642, 0.122, SSW
C113	SPRINT NEXTEL CELL S	1420 BURLINGAME	San Mateo Co. BI	Higher	642, 0.122, SSW
C114	UST SITE - FORMER FO	1417-15 BURLINGAME	San Mateo Co. BI	Higher	650, 0.123, SSW
C115		1419 BURLINGAME AVE	CHMIRS	Higher	664, 0.126, SSW
C116	LINO NICCOLI	257 PRIMROSE RD	HAZNET	Higher	669, 0.127, South
E117	JUNE NEWLING	1405 BELLEVUE AVE	HAZNET	Lower	675, 0.128, West

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
F118		CALIFORNIA DR. AT DO	CHMIRS	Lower	709, 0.134, NNW
C119	JP MORGAN CHASE - BU	1430 CHAPIN AVE	HAZNET	Higher	724, 0.137, SW
F120	BURLINGAME ONE HOUR	507 CALIFORNIA	San Mateo Co. BI, DRYCLEANERS	Lower	737, 0.140, NNW
F121	BURLINGAME ONE HOUR	507 CALIFORNIA	San Mateo Co. BI	Lower	737, 0.140, NNW
F122	BURLINGAME ONE HOUR	507 CALIFORNIA DR	DRYCLEANERS	Lower	737, 0.140, NNW
F123	BURLINGAME ONE HOUR	507 CALIFORNIA DRIVE	EMI	Lower	737, 0.140, NNW
F124	BURLINGAME ONE HOUR	507 CALIFORNIA DRIVE	FINDS, ECHO	Lower	737, 0.140, NNW
F125		507 CALIFORNIA DR	EDR Hist Cleaner	Lower	737, 0.140, NNW
C126		240 PRIMROSE RD	EDR Hist Cleaner	Higher	738, 0.140, South
G127	CARR MCLELLAN	216 PARK AVE	HAZNET	Higher	774, 0.147, SE
C128	WELLS FARGO BANK	1435 BURLINGAME AVE	HAZNET	Higher	775, 0.147, SSW
B129		7474 E. DIVISION ROA	CHMIRS	Lower	784, 0.148, ENE
F130		525 CALIFORNIA DRIVE	CHMIRS	Lower	790, 0.150, NNW
B131	GERMAN CAR CARE	251 CALIFORNIA	San Mateo Co. BI	Higher	792, 0.150, East
B132	G&C AUTO BODY	251 CALIFORNIA	San Mateo Co. BI	Higher	792, 0.150, East
B133		251 CALIFORNIA DR	EDR Hist Auto	Higher	792, 0.150, East
B134	GERMAN CAR CARE	251 CALIFORNIA DR	HAZNET	Higher	792, 0.150, East
G135		229 PARK RD	EDR Hist Cleaner	Higher	796, 0.151, SE
C136		1440 CHAPIN AVE	EDR Hist Auto	Higher	813, 0.154, SW
B137	AUTO MOBILE CARE	251 CALIFORNIA DR	HAZNET	Higher	814, 0.154, East
B138	CHRISTIE'S	240 HATCH LANE	HAZNET	Higher	824, 0.156, ESE
D139	BURLINGAME HIGH SCHO	1 MANGINI	San Mateo Co. BI	Lower	866, 0.164, NNW
D140	SAN MATEO UNION HIGH	1 MANGINI WAY	HAZNET	Lower	866, 0.164, NNW
D141	BURLINGAME HIGH SCHO	1 MANGINI WAY	HAZNET	Lower	866, 0.164, NNW
D142	BURLINGAME HUGH SCHO	1 MANGINI WAY	HAZNET	Lower	866, 0.164, NNW
E143	CRAIG ROGERS	1418 BELLEVUE	HAZNET	Lower	869, 0.165, West
B144	BB STERN COMPANY	222 CALIFORNIA	San Mateo Co. BI	Higher	881, 0.167, East
B145	A J A INVESTMENTS, L	222 CALIFORNIA DR	HAZNET	Higher	881, 0.167, East
B146	STERLING CLEANERS (F	215 CALIFORNIA DRIVE	LUST	Higher	884, 0.167, ESE
B147	STERLING CLEANERS (F	215 CALIFORNIA DRIVE	RGA LUST	Higher	884, 0.167, ESE
B148	UST SITE	215 CALIFORNIA	SLIC, San Mateo Co. BI	Higher	884, 0.167, ESE
B149	FEDERAL AUTO PARTS	231 CALIFORNIA	San Mateo Co. BI	Higher	895, 0.170, East
B150	FEDERAL AUTO PARTS	231 CALIFORNIA DR	HAZNET	Higher	895, 0.170, East
C151	PANDA EXPRESS #907	1453 BURLINGAME	San Mateo Co. BI	Higher	907, 0.172, SSW
H152	DEWEY LAND COMPANY,	1450 CHAPIN AVE	HAZNET	Higher	910, 0.172, SW
E153	CHATEAU APARTMENTS	1422 BELLEVUE AVE	HAZNET	Lower	914, 0.173, West
G154	UST SITE	1290 HOWARD	San Mateo Co. BI	Higher	947, 0.179, SE
B155	TUCKER TRANSMISSIONS	215 HATCH	San Mateo Co. BI	Higher	948, 0.180, ESE
B156		215 HATCH LN	EDR Hist Auto	Higher	948, 0.180, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E157	ARLINGTON APARTMENTS	1401 FLORIBUNDA	LUST, San Mateo Co. BI	Lower	948, 0.180, West
E158	THE ARLINGTON APARTM	1401 FLORIBUNDA AVE	LUST, HAZNET	Lower	948, 0.180, West
G159	210 PRIMROSE LLC	210 PRIMROSE RD	HAZNET	Higher	950, 0.180, SSE
G160	200 PARK RD COMPANY	200 PARK RD	EMI, HAZNET	Higher	950, 0.180, SE
G161	UST SITE	200 PARK	San Mateo Co. BI	Higher	950, 0.180, SE
G162	200 PARK	200 PARK ROAD	RGA LUST	Higher	950, 0.180, SE
G163	200 PARK	200 PARK ROAD	LUST	Higher	950, 0.180, SE
G164	BRIAN KELLEHER	1234 HOWARD AVE	HAZNET	Higher	959, 0.182, SE
G165	CHRISASI HARRIS TRUS	1234 HOWARD AVE	HAZNET	Higher	959, 0.182, SE
G166	HARRIS PROPERTY	1234 HOWARD AVE	RGA LUST	Higher	959, 0.182, SE
G167	HARRIS PROPERTY	1234 HOWARD	RGA LUST	Higher	959, 0.182, SE
G168	HARRIS-CRISAFI CLEAN	1234 HOWARD AVENUE	FINDS, ECHO	Higher	959, 0.182, SE
G169	HARRIS & CRISAFI C/O	1234 HOWARD AVENUE	FINDS, EMI, ECHO	Higher	959, 0.182, SE
G170	CHRISAFI/HARRIS TRUS	1234 HOWARD AVE	HAZNET	Higher	959, 0.182, SE
G171	CHRISAFI/HARRIS TRUS	1234 HOWARD AVE	HAZNET	Higher	959, 0.182, SE
G172	NORMAN HARRIS	1234 HOWARD AVENUE	HAZNET	Higher	959, 0.182, SE
G173	HARRIS PROPERTY	1234 HOWARD	LUST, HIST CORTESE	Higher	959, 0.182, SE
G174	HARRIS-CRISAFI CLEAN	1234 HOWARD AVENUE	EMI	Higher	959, 0.182, SE
G175	CHRISAFI/HARRIS TRUS	1234 HOWARD AVE	HAZNET	Higher	959, 0.182, SE
G176		1220 HOWARD AVE	EDR Hist Auto	Higher	965, 0.183, SE
G177	KING YEE PROPERTY	1200 HOWARD AVE	RGA LUST	Higher	975, 0.185, SE
G178	KING YEE PROPERTY	1200 HOWARD	LUST, HIST CORTESE	Higher	975, 0.185, SE
G179	SHAFFER PROPERTY TRU	1200 HOWARD AVE	HAZNET	Higher	975, 0.185, SE
G180	SHAFFER PROPERTY TRU	1200 HOWARD AVENUE	EMI	Higher	975, 0.185, SE
G181	KING YEE PROPERTY	1200 HOWARD	RGA LUST	Higher	975, 0.185, SE
G182	SHAFFER PROPERTY TRU	1200 HOWARD AVENUE	FINDS, ECHO	Higher	975, 0.185, SE
G183	GRAY'S PAINT	1166 HOWARD AVE	HAZNET	Higher	994, 0.188, ESE
G184	GRAYS PAINTING	1166 HOWARD AVE	HAZNET	Higher	994, 0.188, ESE
G185	BERENSTEIN ASSOC. PR	1319 HOWARD	RGA LUST	Higher	997, 0.189, SSE
G186	STANLEY LO (GREEN BA	1319 HOWARD AVE	EMI, HAZNET	Higher	997, 0.189, SSE
G187	BERENSTEIN ASSOC. PR	1319 HOWARD	LUST, SLIC, HAZNET	Higher	997, 0.189, SSE
G188	FORMER CAINE CLEANER	1319 HOWARD AVE	FINDS	Higher	997, 0.189, SSE
G189	FORMER CAINE CLEANER	1319 HOWARD AVE	RCRA-SQG, ECHO	Higher	997, 0.189, SSE
G190	FORMER CAINE CLEANER	1319/1321 HOWARD AVE	FINDS, ECHO	Higher	997, 0.189, SSE
G191	FORMER CAINE CLEANER	1319/1321 HOWARD AVE	RCRA-LQG	Higher	997, 0.189, SSE
G192	CAINES CLEANERS	1321 HOWARD AVENUE	RCRA-SQG, FINDS, EMI, HAZNET, ECHO	Higher	997, 0.189, SSE
G193	CAINE CLEANERS	1321 HOWARD	San Mateo Co. BI	Higher	997, 0.189, SSE
G194	STANLEY LO/GREENBANK	1321 HOWARD AVE	HAZNET	Higher	997, 0.189, SSE
G195		1321 HOWARD AVE	EDR Hist Cleaner	Higher	997, 0.189, SSE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G196	CAINE CLEANERS	1321 HOWARD	DRYCLEANERS	Higher	997, 0.189, SSE
G197	CAINE CLEANERS	1321 HOWARD	HAZNET	Higher	997, 0.189, SSE
G198		1325 HOWARD AVE	EDR Hist Auto	Higher	1000, 0.189, SSE
G199		1325 HOWARD AVE	EDR Hist Cleaner	Higher	1000, 0.189, SSE
G200	HARRIS-CRISAFI CLEAN	1209 HOWARD AVENUE	EMI	Higher	1007, 0.191, SE
G201	HARRIS-CRISAFI CLEAN	1209 HOWARD AVENUE	FINDS, ECHO	Higher	1007, 0.191, SE
G202	STERLING CLEANERS IN	1140 HOWARD AVE	HAZNET	Higher	1010, 0.191, ESE
G203		1140 HOWARD AVE	EDR Hist Cleaner	Higher	1010, 0.191, ESE
G204	STERLING CLEANERS	1140 HOWARD AVENUE	LUST, SLIC, San Mateo Co. BI	Higher	1010, 0.191, ESE
G205	STERLING CLEANERS	1140 HOWARD AVE	RCRA-SQG, FINDS, DRYCLEANERS, HAZNET, ECHO	Higher	1010, 0.191, ESE
G206	STERLING CLEANERS, I	1140 HOWARD AVENUE	EMI	Higher	1010, 0.191, ESE
G207	SHAFER PROPERTY TRUS	1201 HOWARD AVE	HAZNET	Higher	1014, 0.192, SE
G208	BRIAN KELLEHER	1201 HOWARD AVE	HAZNET	Higher	1014, 0.192, SE
G209	HARRIS-CRISAFI CLEAN	1201 HOWARD AVENUE	EMI	Higher	1014, 0.192, SE
G210	HARRIS-CRISAFI CLEAN	1201 HOWARD AVENUE	FINDS, ECHO	Higher	1014, 0.192, SE
F211	SHELL	601 CALIFORNIA	LUST, San Mateo Co. BI	Lower	1023, 0.194, NW
F212	SHELL	601 CALIFORNIA DR	RGA LUST	Lower	1023, 0.194, NW
F213	BURLINGAME VALERO	601 CALIFORNIA	San Mateo Co. BI	Lower	1023, 0.194, NW
F214	SHELL	601 CALIFORNIA	LUST, HIST CORTESE	Lower	1023, 0.194, NW
F215	SHELL	601 CALIFORNIA	RGA LUST	Lower	1023, 0.194, NW
F216	BURLINGAME TEXACO	601 CALIFORNIA DR	HAZNET	Lower	1023, 0.194, NW
F217		601 CALIFORNIA DR	EDR Hist Auto	Lower	1023, 0.194, NW
F218	BURLINGAME BEACON	601 CALIFORNIA DR	SWEEPS UST, CA FID UST	Lower	1023, 0.194, NW
F219	R SPERING	601 CALIFORNIA	HIST UST	Lower	1023, 0.194, NW
F220	BURLINGAME TEXACO	601CALIFORNIA DR.	UST	Lower	1026, 0.194, NW
H221	PACIFIC BELL	1480 BURLINGAME AVEN	RCRA-SQG, LUST, FINDS, San Mateo Co. BI, HIST...	Higher	1047, 0.198, SSW
H222	PACIFIC BELL	1480 BURLINGAME AVEN	EMI	Higher	1047, 0.198, SSW
H223	PACIFIC BELL	1480 BURLINGAME AVE	RGA LUST	Higher	1047, 0.198, SSW
H224	PACIFIC BELL TELEPHO	1480 BURLINGAME AVE	HAZNET	Higher	1047, 0.198, SSW
H225	PACIFIC BELL	1480 BURLINGAME AVE.	LUST, UST, SWEEPS UST, HIST UST	Higher	1047, 0.198, SSW
H226	T MOBILE WEST CORP S	1480 BURLINGAME	San Mateo Co. BI	Higher	1047, 0.198, SSW
H227	SBC	1480 BURLINGAME	San Mateo Co. BI	Higher	1047, 0.198, SSW
H228	PACIFIC BELL	1480 BURLINGAME	RGA LUST	Higher	1047, 0.198, SSW
H229	AT & T MOBILITY - CE	1480 BURLINGAME	San Mateo Co. BI	Higher	1047, 0.198, SSW
G230	BLUE BIRD CLEANERS	190 PRIMROSE RD	RCRA-SQG, FINDS, ECHO	Higher	1066, 0.202, SSE
I231	JEWELL PARTNERS LP	217 HIGHLAND AVE	HAZNET	Higher	1072, 0.203, ESE
J232	UST SITE	1021 BURLINGAME	San Mateo Co. BI	Lower	1072, 0.203, ENE
G233	WALGREENS #0086	1420 HOWARD AVE	HAZNET	Higher	1073, 0.203, South
G234	WALGREENS #86	1420 HOWARD	San Mateo Co. BI	Higher	1073, 0.203, South

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
G235	WALGREENS NO 86	1420 HOWARD AVE	RCRA-SQG, FINDS, ECHO	Higher	1073, 0.203, South
I236	D & R AUTO BODY AND	270 EAST LANE, #2	FINDS, ECHO	Lower	1115, 0.211, East
I237	BURLINGAME DIAGNOSTI	270 EAST	San Mateo Co. BI	Lower	1115, 0.211, East
I238		270 EAST LN	EDR Hist Auto	Lower	1115, 0.211, East
I239	D&R AUTO BODY & PAIN	270 EAST LANE #2	HAZNET	Lower	1115, 0.211, East
I240	D&R AUTO BODY & PAIN	270 EAST	San Mateo Co. BI	Lower	1115, 0.211, East
I241	SILVER AUTO SVC	270 EAST	San Mateo Co. BI	Lower	1115, 0.211, East
I242	D & R AUTO BODY AND	270 EAST LANE, #2	EMI	Lower	1115, 0.211, East
I243	G & C AUTO BODY	270 EAST LANE	HAZNET	Lower	1115, 0.211, East
I244	UST SITE	1100 HOWARD	San Mateo Co. BI	Higher	1127, 0.213, ESE
I245	1X BURLINGAME BUS DE	1080 HOWARD AVE	HAZNET	Higher	1135, 0.215, ESE
H246	SHELL SERVICE STATIO	1490 BURLINGAME	San Mateo Co. BI	Higher	1140, 0.216, SSW
H247	SHELL	1490 BURLINGAME	LUST, HIST CORTESE	Higher	1140, 0.216, SSW
H248	SHELL	1490 BURLINGAME	RGA LUST	Higher	1140, 0.216, SSW
H249	HUGHES BURLINGAME SH	1490 BURLINGAME AVE	SWEEPS UST, CA FID UST	Higher	1140, 0.216, SSW
H250	SHELL OIL COMPANY C/	1490 BURLINGAME AVEN	EMI	Higher	1140, 0.216, SSW
H251	BURLINGAME/EL CAMINO	1490 BURLINGAME AVE	HIST UST	Higher	1140, 0.216, SSW
H252	SHELL	1490 BURLINGAME	LUST	Higher	1140, 0.216, SSW
H253	SHELL	1490 BURLINGAME AVE	RGA LUST	Higher	1140, 0.216, SSW
H254	MOLLIE STONES MARKET	1477 CHAPIN AVE	HAZNET	Higher	1144, 0.217, SW
I255	LINDA GRIMES	1101 HOWARD AVE # 11	HAZNET	Higher	1148, 0.217, ESE
I256	UST SITE	1101-07 HOWARD	San Mateo Co. BI	Higher	1148, 0.217, ESE
G257	1X BANK OF THE WEST	149 PARK RD	HAZNET	Higher	1150, 0.218, SE
F258	FOUR CAR GARAGE INC	609 CALIFORNIA DRIVE	HAZNET	Lower	1152, 0.218, NW
F259	FOUR CAR GARAGE INC	609 CALIFORNIA	San Mateo Co. BI	Lower	1152, 0.218, NW
F260	FOUR CAR GARAGE THE	609 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Lower	1152, 0.218, NW
F261		609 CALIFORNIA DR	EDR Hist Auto	Lower	1152, 0.218, NW
K262	NEW SAFEWAY BURLINGA	1450 HOWARD AVENUE	NPDES	Higher	1155, 0.219, South
K263	SAFEWAY STORE #948/1	1450 HOWARD AVE	HAZNET	Higher	1155, 0.219, South
K264	SAFEWAY 1547	1450 HOWARD AVE	FINDS, ECHO	Higher	1155, 0.219, South
K265	SAFEWAY 1547	1450 HOWARD	San Mateo Co. BI	Higher	1155, 0.219, South
K266		1450 HOWARD AVE.	CHMIRS	Higher	1155, 0.219, South
I267	RUPPEL'S AUTO FIXATI	260 EAST LANE	HAZNET	Lower	1156, 0.219, East
I268		260 EAST LN	EDR Hist Auto	Lower	1156, 0.219, East
I269	RUPPELS AUTO FIXATIO	260 EAST	San Mateo Co. BI	Lower	1156, 0.219, East
I270	RUPPELS AUTO FIXATIO	260 EAST	San Mateo Co. BI	Lower	1156, 0.219, East
K271	CHEVRON 90571	260 EL CAMINO REAL	RCRA-SQG, FINDS, ECHO	Higher	1170, 0.222, SSW
K272	CHEVRON 9-0571	260 EL CAMINO REAL	LUST	Higher	1170, 0.222, SSW
K273	WALGREENS #12257	260 EL CAMINO REAL	San Mateo Co. BI	Higher	1170, 0.222, SSW

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K274	WALGREENS #12257	260 EL CAMINO REAL	RCRA-CESQG	Higher	1170, 0.222, SSW
K275	CHEVRON 9-0571	260 EL CAMINO REAL	RGA LUST	Higher	1170, 0.222, SSW
K276	BOBS CHEVRON	260 EL CAMINO REAL	SWEEPS UST, CA FID UST	Higher	1170, 0.222, SSW
K277	CHEVRON	260 EL CAMINO REAL	HIST CORTESE	Higher	1170, 0.222, SSW
K278	CHEVRON 9-0571	260 EL CAMINO REAL	RGA LUST	Higher	1170, 0.222, SSW
K279	CHEVRON	260 EL CAMINO REAL	RGA LUST	Higher	1170, 0.222, SSW
K280	5793 SAN MATEO COUNT	260 EL CAMINO REAL	FINDS, ECHO	Higher	1170, 0.222, SSW
K281		260 EL CAMINO REAL	EDR Hist Auto	Higher	1170, 0.222, SSW
K282	CHEVRON 9-0571	260 EL CAMINO REAL	UST	Higher	1170, 0.222, SSW
K283	260 EL CAMINO REAL	260 EL CAMINO REAL	NPDES	Higher	1170, 0.222, SSW
K284	CHEVRON STATION 9057	260 EL CAMINO REAL	HAZNET	Higher	1170, 0.222, SSW
K285	90571	260 EL CAMINO REAL	LUST, HIST UST	Higher	1170, 0.222, SSW
K286	WALGREENS #12257	260 EL CAMINO REAL	HAZNET	Higher	1170, 0.222, SSW
K287	CHEVRON 90571	260 EL CAMINO REAL	HAZNET	Higher	1170, 0.222, SSW
K288	CURRIES CHEVRON SERV	260 EL CAMINO REAL	HAZNET	Higher	1170, 0.222, SSW
K289	CURRIES CHEVRON STAT	260 EL CAMINO REAL	San Mateo Co. BI	Higher	1170, 0.222, SSW
K290	SZTO & ASSOCIATES	1443 HOWARD AVE	HAZNET	Higher	1175, 0.223, South
I291	MIKE HARVEY HONDA	200 CALIFORNIA	San Mateo Co. BI	Higher	1200, 0.227, East
I292	MWE HARVEY CHRYSLER	200 CALIFORNIA DRIVE	HIST UST, HAZNET	Higher	1200, 0.227, East
I293	MIKE HARVEY HONDA	200 CALIFORNIA	San Mateo Co. BI	Higher	1200, 0.227, East
K294	MAURICE APTS	255 EL CAMINO REAL 2	HAZNET	Higher	1205, 0.228, SSW
L295	WINDY HILL PV SEVEN,	1415 FLORIBUNDA AVE	HAZNET	Lower	1207, 0.229, West
I296		198 CALIFORNIA DR AN	CHMIRS	Higher	1216, 0.230, East
I297	PUTNAM CHEVROLET CAD	198 CALIFORNIA	San Mateo Co. BI	Higher	1216, 0.230, East
I298	PUTNAM AUTOMOTIVE	198 CALIFORNIA DRIVE	FINDS, ECHO	Higher	1216, 0.230, East
I299	SATURN OF BURLINGAME	198 CALIFORNIA DR	HAZNET	Higher	1216, 0.230, East
I300	ARATA PROPERTY	198 CALIFORNIA DR	RGA LUST	Higher	1216, 0.230, East
I301	ARATA PROPERTY	198 CALIFORNIA	RGA LUST	Higher	1216, 0.230, East
I302	ARATA PROPERTY	198 CALIFORNIA	LUST	Higher	1216, 0.230, East
I303	SATURN DEVELOPMENT N	198 CALIFORNIA	San Mateo Co. BI	Higher	1216, 0.230, East
I304	ARATA PROPERTY	198 CALIFORNIA DRIVE	RGA LUST	Higher	1216, 0.230, East
I305	PUTNAM AUTOMOTIVE	198 CALIFORNIA DRIVE	EMI	Higher	1216, 0.230, East
I306	PUTNAM CHEVROLET CAD	198 CALIFORNIA DR	RCRA-SQG, LUST, FINDS, HIST CORTESE, ECHO	Higher	1216, 0.230, East
H307	OKI OHATA	1500 BURLINGAME AVE	HAZNET	Higher	1230, 0.233, SSW
J308		NEAR 1000 BURLINGAME	CHMIRS	Lower	1231, 0.233, ENE
M309	AUTO TIGER	621 CALIFORNIA	San Mateo Co. BI	Lower	1239, 0.235, NW
M310		621 CALIFORNIA DR	EDR Hist Auto	Lower	1239, 0.235, NW
M311	PENINSULA PRIME MOTO	621 CALIFORNIA	San Mateo Co. BI	Lower	1239, 0.235, NW
M312	BURLINGAME PRIME MOT	621 CALIFORNIA	San Mateo Co. BI	Lower	1239, 0.235, NW

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M313	ON TRACK AUTOMOTIVE	621 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Lower	1239, 0.235, NW
M314	CALIFORNIA DRIVE AUT	621 CALIFORNIA	San Mateo Co. BI	Lower	1239, 0.235, NW
I315	HARRIS & CRISAFI C/O	137 LORTON AVENUE	FINDS, ECHO	Higher	1255, 0.238, SE
I316	HARRIS & CRISAFI C/O	137 LORTON AVENUE	EMI	Higher	1255, 0.238, SE
L317	DAVID & YVONNE BERNI	1427 FLORIBUNDA AVE	HAZNET	Lower	1259, 0.238, West
G318	ST CATHERINES CHURCH	121 PARK RD	HAZNET	Higher	1261, 0.239, SE
319	T MOBILE SITE ID SF5	850 BURLINGAME	San Mateo Co. BI	Lower	1267, 0.240, NE
K320	MURDOCH LABORITORIES	123 PRIMROSE	FINDS, ECHO	Higher	1284, 0.243, SSE
I321	CHEVRON, FORMER/EAGL	177 CALIFORNIA	RGA LUST	Higher	1307, 0.248, ESE
I322	CHEVRON	177 CALIFORNIA AVE	RGA LUST	Higher	1307, 0.248, ESE
I323	BUBBLE MACHINE	177 CALIFORNIA DR	SWEEPS UST, CA FID UST	Higher	1307, 0.248, ESE
I324	FORMER CHEVRON/EAGLE	177 CALIFORNIA	RGA LUST	Higher	1307, 0.248, ESE
I325	CHEVRON, FORMER/EAGL	177 CALIFORNIA	LUST	Higher	1307, 0.248, ESE
I326	CHEVRON, FORMER/EAGL	177 CALIFORNIA	LUST, HIST CORTESE	Higher	1307, 0.248, ESE
I327	FORMER CHEVRON/EAGLE	177 CALIFORNIA AVE	RGA LUST	Higher	1307, 0.248, ESE
I328	CHEVRON	177 CALIFORNIA ST	RGA LUST	Higher	1307, 0.248, ESE
I329	BUBBLE CAR WASH	177 CALIFORNIA DR	UST	Higher	1307, 0.248, ESE
I330	CHEVRON STORE #90364	177 CALIFORNIA DR	HAZNET	Higher	1307, 0.248, ESE
I331	EAGLE CAR WASH & FIL	177 CALIFORNIA	San Mateo Co. BI	Higher	1307, 0.248, ESE
J332		257 MYRTLE RD	EDR Hist Auto	Lower	1320, 0.250, ENE
J333	ALL MAKES AUTO BODY	257 MYRTLE	San Mateo Co. BI	Lower	1320, 0.250, ENE
J334	ALL MAKES AUTO BODY	257 MYRTLE ROAD	HAZNET	Lower	1320, 0.250, ENE
J335	ALL MAKES AUTO BODY	257 MYRTLE ROAD	FINDS, EMI, ECHO	Lower	1320, 0.250, ENE
J336	A & I CUSTOMS	255 MYRTLE	San Mateo Co. BI	Lower	1324, 0.251, ENE
J337		255 MYRTLE RD	EDR Hist Auto	Lower	1324, 0.251, ENE
J338	UNITED AUTO COLLISIO	255 MYRTLE ROAD	FINDS, EMI, ECHO	Lower	1324, 0.251, ENE
J339	UNITED AUTO COLLISIO	255 MYRTLE ROAD	HAZNET	Lower	1324, 0.251, ENE
J340	I&M AUTO BODY & PAIN	255 MYRTLE ROAD #6	EMI	Lower	1324, 0.251, ENE
J341	2M AUTOMOTIVE	255 MYRTLE	San Mateo Co. BI	Lower	1324, 0.251, ENE
I342	JACK WONG	220 E LANE	HAZNET	Lower	1325, 0.251, East
M343	BELINDA LIN	1209 OAK GROVE AVE	HAZNET	Lower	1340, 0.254, NW
M344	W. J. BRITTON COMPAN	701 CALIFORNIA	LUST, HIST CORTESE	Lower	1343, 0.254, NW
M345	WJ BRITTON	701 CALIFORNIA DR	RGA LUST	Lower	1343, 0.254, NW
M346	W.J. BRITTON COMPANY	701 CALIFORNIA DR	RGA LUST	Lower	1343, 0.254, NW
M347	W. J. BRITTON COMPAN	701 CALIFORNIA	RGA LUST	Lower	1343, 0.254, NW
M348	WJ BRITTON COMPANY	701 CALIFORNIA DR	RGA LUST	Lower	1343, 0.254, NW
M349	WJ BRITTON	701 CALIFORNIA	RGA LUST	Lower	1343, 0.254, NW
M350	WJ BRITTON COMPANY	701 CALIFORNIA DR	RGA LUST	Lower	1343, 0.254, NW
M351		OAK GROVE AND CALIFO	CHMIRS	Lower	1346, 0.255, NW

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M352		1217 OAK GROVE AVE	CHMIRS	Lower	1356, 0.257, NW
I353	MIKE HARVEY HONDA	212 EAST LANE	FINDS, ECHO	Lower	1360, 0.258, East
I354	MIKE HARVEY HONDA	212 EAST LANE	EMI	Lower	1360, 0.258, East
I355	MIKE HARVEY ACURA AU	212 LANE	San Mateo Co. BI	Lower	1360, 0.258, East
I356	MIKE HARVEY HONDA	212 E LANE	HAZNET	Lower	1360, 0.258, East
I357		212 EAST LN	EDR Hist Auto	Lower	1360, 0.258, East
N358	JD GIUSTI TRANSPORTA	125 LORTON AVE #2	RCRA NonGen / NLR, FINDS, ECHO	Higher	1366, 0.259, SE
J359	RETIREMENT INN OF BU	250 MYRTLE RD	HAZNET	Lower	1369, 0.259, ENE
J360	ATRIA BURLINGAME	250 MYRTLE RD	HAZNET	Lower	1369, 0.259, ENE
O361		1460 BELLEVUE AVE	EDR Hist Cleaner	Higher	1390, 0.263, WSW
L362	GUS PAROS	1440 FLORI BUNDA AVE	HAZNET	Lower	1410, 0.267, West
H363	ST PAUL EPISCOPAL CH	415 EL CAMINO REAL	HAZNET	Higher	1417, 0.268, SW
H364	ST PAULS EPISCOPAL C	415 EL CAMINO REAL	HAZNET	Higher	1417, 0.268, SW
N365	BURT BERENSTEIN	110 PARK ROAD #206	HAZNET	Higher	1419, 0.269, SE
N366	DAVE TOWNSEND	110 PARK RD APT 601	HAZNET	Higher	1419, 0.269, SE
O367	BURLINGAME TOWERS	1469 BELLEVUE AVE	HAZNET	Higher	1437, 0.272, WSW
O368	BURLINGAME TOWERS	1469 BELLEVUE AVE.	HAZNET	Higher	1437, 0.272, WSW
P369	OLDE ENGLISH GARAGE	988 HOWARD	San Mateo Co. BI	Lower	1451, 0.275, East
P370	RICKS TEXACO	988 HOWARD	HIST UST	Lower	1451, 0.275, East
P371	RICK'S SERVICE	988 HOWARD AVE	HAZNET	Lower	1451, 0.275, East
P372	1X OLD ENGLISH GARAG	988 HOWARD AVE	HAZNET	Lower	1451, 0.275, East
P373	RICKS SERVICE	988 HOWARD	San Mateo Co. BI	Lower	1451, 0.275, East
P374	RICKS BEACON	988 HOWARD AVE	SWEEPS UST, CA FID UST	Lower	1451, 0.275, East
P375	OLDE ENGLISH GARAGE	988 HOWARD AVE	HAZNET	Lower	1451, 0.275, East
P376	OLDE ENGLISH GARAGE	988 HOWARD AVE	HAZNET	Lower	1451, 0.275, East
M377		715 CALIFORNIA DR	EDR Hist Cleaner	Lower	1452, 0.275, NW
M378	ROGER & REBECCA EMER	715 CALIFORNIA DR	HAZNET	Lower	1452, 0.275, NW
K379		120 EL CAMINO REAL	EDR Hist Auto	Higher	1456, 0.276, SSE
K380	C&D AUTOMOTIVE AND M	120 EL CAMINO REAL	San Mateo Co. BI	Higher	1456, 0.276, SSE
L381	FLORIBUNDA HOA	1477 FLORIBUNDA AVE	HAZNET	Higher	1464, 0.277, West
L382	RAPHEL AGUIRRE	525 ALMER RD APT 302	HAZNET	Higher	1487, 0.282, WSW
L383	JAMIE RICE	525 ALMER RD APT 101	HAZNET	Higher	1487, 0.282, WSW
N384	NORMAN GOLDAU	111 LORTON	HAZNET	Higher	1495, 0.283, SE
I385	BURLINGAME SUBARU AL	150 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Higher	1498, 0.284, ESE
Q386	DAVID DESJARBAN	1538 BURLINGAME AVE	HAZNET	Higher	1550, 0.294, SSW
Q387	UST SITE	1538 BURLINGAME	San Mateo Co. BI	Higher	1550, 0.294, SSW
I388	PACIFIC AUTO REPAIR	124 HIGHLAND	San Mateo Co. BI	Higher	1556, 0.295, ESE
I389	PACIFIC AUTO REPAIR	124 HIGHLAND AVE	HAZNET	Higher	1556, 0.295, ESE
I390		124 HIGHLAND AVE	EDR Hist Auto	Higher	1556, 0.295, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M391	WOODHALL INVESTMENTS	731 SAN MATEO AVE	RGA LUST	Lower	1578, 0.299, NW
R392	ST CATHERINE CATHOLI	1310 BAYSWATER AVE	HAZNET	Higher	1598, 0.303, SSE
R393	ROMAN CATHOLIC ARCHB	1310 BAYSWATER AVE	HAZNET	Higher	1598, 0.303, SSE
P394	THE NEW DATSONVILLE	927 HOWARD AVE	HAZNET	Lower	1610, 0.305, East
P395		927 HOWARD AVE	EDR Hist Auto	Lower	1610, 0.305, East
P396	NEW DATSONVILLE	927 HOWARD	San Mateo Co. BI	Lower	1610, 0.305, East
I397	NOEL L MILLER INC	129 CALIFORNIA	San Mateo Co. BI	Higher	1616, 0.306, ESE
I398	NOEL L MILLER INC	129 CALIFORNIA DR	HAZNET	Higher	1616, 0.306, ESE
P399	RICHARD SAMUELSON	917 HOWARD AVE.	HAZNET	Lower	1630, 0.309, East
L400	DEITER BLUHM	1285 OAK GROVE	LUST, HIST CORTESE	Lower	1630, 0.309, WNW
L401	BLUHM PROPERTY	1285 OAK GROVE	RGA LUST	Lower	1630, 0.309, WNW
L402	DEITER BLUHM	1285 OAK GROVE	RGA LUST	Lower	1630, 0.309, WNW
S403	HAROLDS MACHINE SHOP	127 CALIFORNIA	San Mateo Co. BI	Higher	1631, 0.309, ESE
S404	HAROLD'S MACHINE SHO	127 CALIFORNIA DRIVE	FINDS, ECHO	Higher	1631, 0.309, ESE
R405	CAMINO REAL PET CLIN	1317 BAYSWATER AVE	HAZNET	Higher	1636, 0.310, SSE
M406	BLUE RIBBON CLEANERS	741 CALIFORNIA	San Mateo Co. BI	Lower	1640, 0.311, NW
M407	BLUE RIBBON CLEANERS	741 CALIFORNIA	San Mateo Co. BI	Lower	1640, 0.311, NW
M408	GEORGES HOLIDAY CLEA	741 CALIFORNIA DRIVE	EMI	Lower	1640, 0.311, NW
M409	BLUE RIBBON CLEANERS	741 CALIFORNIA DR	CHMIRS, DRYCLEANERS	Lower	1640, 0.311, NW
M410	GEORGES HOLIDAY CLEA	741 CALIFORNIA DRIVE	FINDS, ECHO	Lower	1640, 0.311, NW
M411		741 CALIFORNIA DR	EDR Hist Cleaner	Lower	1640, 0.311, NW
M412	BLUE RIBBON CLEANERS	741 CALIFORNIA DR	HAZNET	Lower	1640, 0.311, NW
M413	BLUE RIBBON CLEANERS	741 CALIFORNIA	San Mateo Co. BI, DRYCLEANERS	Lower	1640, 0.311, NW
M414	GEORGE'S HOLIDAY CLE	741 CALIFORNIA DR	HAZNET	Lower	1640, 0.311, NW
T415	PENINSULA TENNIS CLU	433 CHATHAM RD	HAZNET	Lower	1643, 0.311, NNE
416	BOB N DISCO	850 BURLINGAME AVE	PEST LIC	Lower	1643, 0.311, ENE
S417	BURLINGAME COLLISON	123 CALIFORNIA	San Mateo Co. BI	Higher	1661, 0.315, ESE
S418		123 CALIFORNIA DR	EDR Hist Auto	Higher	1661, 0.315, ESE
S419	MONTALVO CORP DBA BU	123 CALIFORNIA DR	HAZNET	Higher	1661, 0.315, ESE
S420	BENZ DOCTOR	123 CALIFORNIA	San Mateo Co. BI	Higher	1661, 0.315, ESE
S421	BURLINGAME COLLISION	123 CALIFORNIA DRIVE	RCRA-SQG, FINDS, EMI, HAZNET, ECHO	Higher	1661, 0.315, ESE
M422	FLOYDS AUTOMOTIVE	741 SAN MATEO AVE	LUST, SWEEPS UST, HIST CORTESE	Lower	1661, 0.315, NW
M423	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE	RGA LUST	Lower	1661, 0.315, NW
M424	FLOYD'S AUTOMOTIVE	741 SAN MATEO	LUST	Lower	1661, 0.315, NW
M425	FLOYDS AUTOMOTIVE	741 SAN MATEO	San Mateo Co. BI	Lower	1661, 0.315, NW
M426	FLOYD'S AUTOMOTIVE	741 SAN MATEO	RGA LUST	Lower	1661, 0.315, NW
U427		708 LAUREL AVE	EDR Hist Auto	Lower	1678, 0.318, North
V428	TRAMMEL CROW COMPANY	1531 HOWARD AVE	HAZNET	Higher	1700, 0.322, South
R429	EVELYN CONDON	1501 CYPRESS AVE	HAZNET	Higher	1700, 0.322, SSE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M430	CALIFORNIA AUTO CENT	751 CALIFORNIA	San Mateo Co. BI	Lower	1723, 0.326, NW
M431		751 CALIFORNIA DR	EDR Hist Auto	Lower	1723, 0.326, NW
M432	FLOYD'S AUTO REPAIR	751 CALIFORNIA DR	HAZNET	Lower	1723, 0.326, NW
M433	EUROPEAN PERFORMANCE	751 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Lower	1723, 0.326, NW
M434	FLOYDS AUTO REPAIR	751 CALIFORNIA	San Mateo Co. BI	Lower	1723, 0.326, NW
T435	GREG TAYLOR	446 CHATHAM RD	HAZNET	Lower	1729, 0.327, NNE
Q436	KIIKO, OHATA	1537 RALSTON AVE	HAZNET	Higher	1731, 0.328, SSW
M437	K & B INVESTMENTS	755 CALIFORNIA ST	HAZNET	Lower	1745, 0.330, NW
O438	TOP TOYO LOTUS INC	530 EL CAMINO REAL	HAZNET	Higher	1761, 0.334, WSW
U439	NELSON NG	730 OAK GROVE AVE	HAZNET	Lower	1766, 0.334, North
S440	PUTNAM GM	998 BAYSWATER AVE	HAZNET	Higher	1766, 0.334, ESE
W441	JIM SHANNON	744 NEUCHATEL AVE	HAZNET	Lower	1781, 0.337, WNW
U442	DOUG DIEHL	705 WINCHESTER DR	HAZNET	Lower	1807, 0.342, North
R443	MAJEL GILMARTIN	48 PARK RD	HAZNET	Higher	1819, 0.345, SE
S444	BURLINGAME FORD	101 CALIFORNIA	San Mateo Co. BI	Higher	1825, 0.346, ESE
S445	PUTNAM AUTOMOTIVE GR	101 CALIFORNIA	San Mateo Co. BI	Higher	1825, 0.346, ESE
S446	BURLINGAME FORD	101 CALIFORNIA DRIVE	RCRA-SQG, SWEEPS UST, HIST UST, CA FID UST, FINDS,...	Higher	1825, 0.346, ESE
S447	SAREMI PROPERTY	100 CALIFORNIA DR	RGA LUST	Higher	1833, 0.347, ESE
S448	GMAC	100 CALIFORNIA BLVD	HAZNET	Higher	1833, 0.347, ESE
S449	ARATA HONDA	100 CALIFORNIA DR	RGA LUST	Higher	1833, 0.347, ESE
S450	HOBBY STORE	100 CALIFORNIA	San Mateo Co. BI	Higher	1833, 0.347, ESE
S451	SAREMI PROPERTY	100 CALIFORNIA	LUST	Higher	1833, 0.347, ESE
S452	PUTNAM TOYOTA	100 CALIFORNIA	San Mateo Co. BI	Higher	1833, 0.347, ESE
S453	HOBBY STORE	100 CALIFORNIA DR	SWEEPS UST, CA FID UST	Higher	1833, 0.347, ESE
S454	SAREMI PROPERTY	100 CALIFORNIA	LUST, HIST CORTESE	Higher	1833, 0.347, ESE
S455	PUTNAM TOYOTA	100 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Higher	1833, 0.347, ESE
S456	SAREMI PROPERTY	100 CALIFORNIA	RGA LUST	Higher	1833, 0.347, ESE
S457	GMAC	100 CALIFORNIA BLVD	HAZNET	Higher	1833, 0.347, ESE
S458	PUTNAM AUTOMOTIVE	100 CALIFORNIA DRIVE	EMI	Higher	1833, 0.347, ESE
U459	RICK CORY	730 LAUREL AVE	HAZNET	Lower	1833, 0.347, NNW
P460		136 MYRTLE RD	EDR Hist Auto	Higher	1836, 0.348, East
P461		132 MYRTLE RD	EDR Hist Auto	Higher	1853, 0.351, East
P462	BURLINGAME AUTO CLIN	132 MYRTLE RD	HAZNET	Higher	1853, 0.351, East
P463	BURLINGAME AUTO CLIN	132 MYRTLE	San Mateo Co. BI	Higher	1853, 0.351, East
W464	NICKS HONDA	775 CALIFORNIA DRIVE	LUST, SLIC	Lower	1854, 0.351, NW
W465	NICKS HONDA / ACURA	775 CALIFORNIA DR	San Mateo Co. BI, HAZNET	Lower	1854, 0.351, NW
W466		775 CALIFORNIA DR	EDR Hist Auto	Lower	1854, 0.351, NW
S467	BURLINGAME FORD	99 CALIFORNIA	LUST, HIST CORTESE	Higher	1859, 0.352, ESE
S468	BURLINGAME FORD	99 CALIFORNIA	RGA LUST	Higher	1859, 0.352, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
S469	BURLINGAME FORD	99 CALIFORNIA DR	RGA LUST	Higher	1859, 0.352, ESE
W470	CARBARR DBA SHAFFERS	777 CALIFORNIA DR	HAZNET	Lower	1866, 0.353, NW
W471	SHAFFER'S TIRE CENTE	777 CALIFORNIA	RGA LUST	Lower	1866, 0.353, NW
W472	SHAFFER'S TIRE CENTE	777 CALIFORNIA DR	RGA LUST	Lower	1866, 0.353, NW
W473		777 CALIFORNIA DR	EDR Hist Auto	Lower	1866, 0.353, NW
W474	SHAFFERS AUTO SVC	777 CALIFORNIA DR	HAZNET	Lower	1866, 0.353, NW
W475	777 TO 783 CALIFORNI	777 CALIFORNIA DR #	HAZNET	Lower	1866, 0.353, NW
W476	SHAFFERS AUTO SERVIC	777 CALIFORNIA	San Mateo Co. BI	Lower	1866, 0.353, NW
X477	BO THORENFIELDT	1512 FLORIBUNDA AVE	HAZNET	Higher	1886, 0.357, West
W478	LARRY SPECKMAN	743 CROSSWAY RD	HAZNET	Lower	1898, 0.359, WNW
W479	GRAYS PAINT	783 CALIFORNIA	San Mateo Co. BI	Lower	1898, 0.359, NW
V480	JOHN TREADWELL	1540 NEWLANDS AVE	HAZNET	Higher	1933, 0.366, South
U481	1X ARTHUR W.BROWN	746 LAUREL AVE.	HAZNET	Lower	1955, 0.370, NNW
U482	ARTHUR BROWN	746 LAUREL	SWEEPS UST	Lower	1955, 0.370, NNW
U483	RESIDENCE	746 LAUREL	San Mateo Co. BI	Lower	1955, 0.370, NNW
W484	SHAFFER'S TIRE CENTE	777 CALIFORNIA	LUST, SLIC, HIST CORTESE	Lower	1956, 0.370, NW
W485	SHAEFFER'S TIRE CENT	777 CALIFORNIA DR	SWEEPS UST, CA FID UST	Lower	1956, 0.370, NW
W486	SHAFFER'S TIRE CENTE	777 CALIFORNIA	LUST	Lower	1956, 0.370, NW
Y487	KAVANAGH ENGINEERING	708 CAROLAN AVENUE	HAZNET	Lower	1957, 0.371, NW
Q488	MARION SPADONI	1557 RALSTON AVE	HAZNET	Higher	1960, 0.371, SSW
U489	MICHAEL LUTZ	719 WINCHESTER DR	HAZNET	Lower	1962, 0.372, North
S490		920 BAYSWATER AVE	EDR Hist Auto	Higher	1967, 0.373, ESE
S491	HOWER AUTO REPAIR	920 BAYSWATER	San Mateo Co. BI	Higher	1967, 0.373, ESE
S492	HOWER AUTO REPAIR	920 BAYSWATER ST	HAZNET	Higher	1967, 0.373, ESE
S493	HOWER AUTO REPAIR IN	920 BAYSWATER AVE	HIST UST	Higher	1967, 0.373, ESE
S494	MILE HIGH TRUCKING	108 MYRTLE RD #4	RCRA NonGen / NLR, FINDS, ECHO	Higher	1971, 0.373, East
X495	DAVID CUNNINGHAM	700 ACACIA AVE	HAZNET	Higher	1980, 0.375, West
W496	FIRE DEPARTMENT	799 CALIFORNIA DR.	SWEEPS UST, CA FID UST	Lower	1987, 0.376, NW
W497	BURLINGAME FIRE DEPT	799 CALIFORNIA DR	RGA LUST	Lower	1987, 0.376, NW
W498	CITY OF BURLINGAME	799 CALIFORNIA DRIVE	EMI	Lower	1987, 0.376, NW
W499	FIRE STATION 1	799 CALIFORNIA DRIVE	HIST UST	Lower	1987, 0.376, NW
W500	BURLINGAME FIRE DEPT	799 CALIFORNIA	RGA LUST	Lower	1987, 0.376, NW
W501	BURLINGAME FIRE DEPT	799 CALIFORNIA	San Mateo Co. BI	Lower	1987, 0.376, NW
W502	BURLINGAME FIRE DEPT	799 CALIFORNIA	LUST, San Mateo Co. BI, HIST CORTESE	Lower	1987, 0.376, NW
W503	CITY OF BURLINGAME	799 CALIFORNIA DRIVE	FINDS, ECHO	Lower	1987, 0.376, NW
R504	MR. M. AFLAK	51 EL CAMINO REAL	HAZNET	Higher	2003, 0.379, SSE
Y505	HOWARD ENGINEERING	724 CAROLAN AVE	HAZNET	Lower	2044, 0.387, NW
506	SAM YU	749 FARRINGDON LN	HAZNET	Lower	2061, 0.390, WNW
Z507	RESIDENCE	732 LEXINGTON	San Mateo Co. BI	Lower	2071, 0.392, NE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
V508	LAURA GSCHWIND	1553 NEWLANDS AVE	HAZNET	Higher	2072, 0.392, South
S509	COLE EUROPEAN MOTORS	65 CALIFORNIA DRIVE	HAZNET	Higher	2081, 0.394, ESE
U510	MEGAN DYER	743 WINCHESTER DR	HAZNET	Lower	2083, 0.395, North
AA511	JOSEPH KELLER	ONE PARK ROAD	HAZNET	Higher	2085, 0.395, SE
T512	PETER WBORBERG	478 MARIN DR	HAZNET	Lower	2087, 0.395, NNE
S513	COLE EUROPEAN JAGUAR	65 CALIFORNIA DR	HIST UST	Higher	2094, 0.397, ESE
S514	PUTNAM AUTOMOTIVE	65 CALIFORNIA DRIVE	FINDS, ECHO	Higher	2094, 0.397, ESE
S515	PUTNAM AUTOMOTIVE	65 CALIFORNIA DRIVE	EMI	Higher	2094, 0.397, ESE
S516		65 CALIFORNIA DR	EDR Hist Auto	Higher	2094, 0.397, ESE
Z517	TUHIN & SHELBY SINHA	728 LEXINGTON WAY	HAZNET	Lower	2098, 0.397, NE
AB518	MICHAEL R UHL	800 HOWARD AVE	HAZNET	Lower	2135, 0.404, ENE
Z519	BELINDA BURNS	721 LEXINGTON WAY	HAZNET	Lower	2146, 0.406, NE
AA520	SERVICE STATION 709	1 PARK ROAD	LUST, HIST UST	Higher	2151, 0.407, SE
AA521	NICKS HONDA / ACURA	1 PARK RD	HAZNET	Higher	2151, 0.407, SE
AA522		1 PARK RD	EDR Hist Auto	Higher	2151, 0.407, SE
AA523	ARMSTRONG PROPERTY	1 PARK ROAD	RGA LUST	Higher	2151, 0.407, SE
AA524	ARMSTRONG PROPERTY	1 PARK RD	LUST, HIST CORTESE	Higher	2151, 0.407, SE
AA525	RRM, INC	1 PARK RD	HAZNET	Higher	2151, 0.407, SE
AA526	ARMSTRONG PROPERTY	1 PARK RD	RGA LUST	Higher	2151, 0.407, SE
AA527	ARMSTRONG PROPERTY	1 PARK	RGA LUST	Higher	2151, 0.407, SE
AA528	NICKS HONDA & ACURA	1 PARK	San Mateo Co. BI	Higher	2151, 0.407, SE
AA529	ANY CAR SERVICE	1 PARK	San Mateo Co. BI	Higher	2151, 0.407, SE
AB530	BSD-WASHINGTON ELEME	801 HOWARD AVE	HAZNET	Lower	2153, 0.408, ENE
AB531	BESD - WASHINGTON EL	801 HOWARD ST	HAZNET	Lower	2153, 0.408, ENE
AC532	BO THORENFELDT	101 ANITA RD	HAZNET	Lower	2167, 0.410, East
AA533	DEBRA GWIN	1529 CAROL AVENUE	HAZNET	Higher	2176, 0.412, SSE
AD534	UST SITE	20 HIGHLAND	San Mateo Co. BI	Higher	2181, 0.413, ESE
AD535	PETE ROSSI	20 HIGHLAND AVE	HAZNET	Higher	2181, 0.413, ESE
S536	PUTNAM AUTOMOTIVE	50 CALIFORNIA DRIVE	FINDS, ECHO	Higher	2184, 0.414, ESE
S537	PUTNAM MAZDA II	50 CALIFORNIA	LUST, HIST CORTESE	Higher	2184, 0.414, ESE
S538	PUTNAM MAZDA II	50 CALIFORNIA	LUST	Higher	2184, 0.414, ESE
S539	J AND M MOTORS D B A	50 CALIFORNIA DR	RCRA-SQG, SWEEPS UST, HIST UST, CA FID UST, FINDS,...	Higher	2184, 0.414, ESE
S540	PUTNAM MAZDA II	50 CALIFORNIA	RGA LUST	Higher	2184, 0.414, ESE
S541	PUTNAM MAZDA II	50 CALIFORNIA DR	RGA LUST	Higher	2184, 0.414, ESE
S542	PUTNUM MAZADA	50 CALIFORNIA	San Mateo Co. BI	Higher	2184, 0.414, ESE
S543	PUTNAM AUTOMOTIVE	50 CALIFORNIA DRIVE	EMI	Higher	2184, 0.414, ESE
S544	J&M MOTORS INC PUTNA	50 CALIFORNIA DR	HAZNET	Higher	2184, 0.414, ESE
S545	PUTNAM TOYOTA	50 CALIFORNIA D	HAZNET	Higher	2184, 0.414, ESE
S546	PUTNAM BUICK	50 CALIFORNIA DR	RGA LUST	Higher	2184, 0.414, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
X547		SB EL CAMINO REAL AN	CHMIRS	Higher	2186, 0.414, WSW
X548	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	2190, 0.415, WSW
549	LARRY PUTMAN & JENNY	1547 CYPRESS AVE	HAZNET	Higher	2191, 0.415, SSE
AC550	CHILTON AUTO BODY (B	925 BAYSWATER	San Mateo Co. BI	Lower	2193, 0.415, East
AC551	CHILTON AUTO BODY BU	925 BAYSWATER AVE	HAZNET	Lower	2193, 0.415, East
AC552	CHILTON AUTO BODY (S	925 BAYSWATER STREET	EMI	Lower	2193, 0.415, East
AC553	PUTNAM BUICK,PONTIAC	925 BAYSWATER STREET	FINDS, ECHO	Lower	2193, 0.415, East
AA554	STERLING COURT PROJE	EL CAMINO REAL & PEN	SPILLS 90	Higher	2228, 0.422, SE
555	ROB DOMENICI	515 MARIN DR	HAZNET	Lower	2248, 0.426, North
AE556	ROB LYNCH	707 CONCORD WAY	HAZNET	Lower	2250, 0.426, NE
AA557	TONY LEUNG	19 E CAROL AVE	HAZNET	Higher	2252, 0.427, SSE
AE558	JANE CALAVANO	715 BURLINGAME AVE	HAZNET	Lower	2253, 0.427, ENE
X559	1X MCKINLEY SCHOOL	701 PALOMA AVENUE	HAZNET	Higher	2266, 0.429, West
X560	MCKINLEY ELEMENTARY	701 PALOMA	San Mateo Co. BI	Higher	2266, 0.429, West
X561	MCKINLEY ELEM./BURLI	701 PALOMA AVE	HAZNET	Higher	2266, 0.429, West
X562	MCKINLEY SCHOOL	701 PALOMA	RGA LUST	Higher	2266, 0.429, West
X563	1X MCKINLEY SCHOOL	701 PALOMA AVENUE	HAZNET	Higher	2266, 0.429, West
X564	BSD- MCKINLEY ELEMEN	701 PALOMA AVE	HAZNET	Higher	2266, 0.429, West
X565	MCKINLEY SCHOOL	701 PALOMA	LUST, SWEEPS UST, HIST CORTESE	Higher	2266, 0.429, West
X566	MCKINLEY SCHOOL	701 PALOMA AVE	RGA LUST	Higher	2266, 0.429, West
X567	MCKINLEY SCHOOL	701 PALOMA	LUST	Higher	2266, 0.429, West
AA568	PHILIP CHAN	15 EL CAMINO REAL	HAZNET	Higher	2270, 0.430, SE
Y569		CALIFORNIA DR. @ PAL	CHMIRS	Lower	2285, 0.433, NW
W570	CALIF FEDERAL SAVING	1112 PALM DR	RGA LUST	Lower	2291, 0.434, NW
W571		1112 PALM DRIVE	SWEEPS UST	Lower	2291, 0.434, NW
W572	CALIF. FEDERAL SAVIN	1112 PALM	RGA LUST	Lower	2291, 0.434, NW
W573	HAGGERTY RESIDENCE	1112 PALM DR	RGA LUST	Lower	2291, 0.434, NW
W574	RESIDENCE	1112 PALM	San Mateo Co. BI	Lower	2291, 0.434, NW
W575	CALIF. FEDERAL SAVIN	1112 PALM	LUST, HIST CORTESE	Lower	2291, 0.434, NW
W576	CALIF. FEDERAL SAVIN	1112 PALM	LUST	Lower	2291, 0.434, NW
AE577	GREG FRAZER	701 BURLINGAME AVE	HAZNET	Lower	2302, 0.436, ENE
AF578	MATT ROSSIE	812 MAPLE AVE	HAZNET	Lower	2315, 0.438, NNW
AG579	SMITH RESIDENCE	1615 FLORIBUNDA AVE	RGA LUST	Higher	2321, 0.440, WSW
AG580	RAY SMITH	1615 FLORABUNDA AVE	HAZNET	Higher	2321, 0.440, WSW
AG581	SMITH RESIDENCE	1615 FLORIBUNDA	LUST, HIST CORTESE	Higher	2321, 0.440, WSW
AG582	RESIDENCE	1615 FLORIBUNDA	San Mateo Co. BI	Higher	2321, 0.440, WSW
AG583	SMITH RESIDENCE	1615 FLORIBUNDA	RGA LUST	Higher	2321, 0.440, WSW
AG584	SMITH RESIDENCE	1615 FLORIBUNDA	LUST	Higher	2321, 0.440, WSW
Z585	SHIRLEY KWOK	430 BLOOMFIELD RD	HAZNET	Lower	2323, 0.440, NE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG586	HILLSBOROUGH FIRE DE	1600 FLORIBUNDA	Cortese, HAZNET	Higher	2351, 0.445, WSW
AG587	CITY OF HILLSBOROUGH	1600 FLORIBUNDA	RGA LUST	Higher	2351, 0.445, WSW
AG588	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA AVE	SWEEPS UST, CHMIRS	Higher	2351, 0.445, WSW
AG589	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA	LUST, CHMIRS, ENF	Higher	2351, 0.445, WSW
AG590		1600 FLORABUNDA AVEN	CHMIRS	Higher	2351, 0.445, WSW
AG591	HILLSBOROUGH CITY OF	1600 FLORIBUNDA	RGA LUST	Higher	2351, 0.445, WSW
AG592	HILLSBOROUGH TOWN HA	1600 FLORIBUNDA	San Mateo Co. BI	Higher	2351, 0.445, WSW
AG593	HILLSBOROUGH TOWN OF	1600 FLORIBUNDA AVE	RGA LUST	Higher	2351, 0.445, WSW
AG594	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA	RGA LUST	Higher	2351, 0.445, WSW
AG595		1600 FLORIBUNDA AVE.	CHMIRS	Higher	2351, 0.445, WSW
AG596	HILLSBOROUGH TOWN OF	1600 FLORIBUNDA	LUST, HIST CORTESE	Higher	2351, 0.445, WSW
AD597	SUSAN STEFFEN	214 PENINSULA AVE	HAZNET	Higher	2353, 0.446, ESE
AH598	NICK ROGERS	325 CHAPIN LN	HAZNET	Higher	2371, 0.449, SSW
AB599	DENISE DIRICKSON	209 BLOOMFIELD RD	PEST LIC	Lower	2436, 0.461, ENE
600	TARA & BRIAN WATSON	460 BLOOMFIELD RD	HAZNET	Lower	2468, 0.467, NNE
AI601	HERMAN HSU	20 SUMMERHOLME PL	HAZNET	Higher	2477, 0.469, WSW
AB602	ANTOSIK, EDWIN	701 HOWARD	San Mateo Co. BI	Lower	2479, 0.470, ENE
AB603	EDWIN ANTOSIK	701 HOWARD AVE	HAZNET	Lower	2479, 0.470, ENE
AD604	T MOBILE WEST CORP S	3 CALIFORNIA	San Mateo Co. BI	Higher	2485, 0.471, ESE
AD605	ARCO #0249	3 CALIFORNIA	RGA LUST	Higher	2485, 0.471, ESE
AD606	ARCO #0249	3 CALIFORNIA DRIVE	RGA LUST	Higher	2485, 0.471, ESE
AD607	PUTNAM MAZDA	3 CALIFORNIA DRIVE	EMI	Higher	2485, 0.471, ESE
AD608	PUTNAM AUTOMOTIVE CH	3-85 CALIFORNIA	San Mateo Co. BI	Higher	2485, 0.471, ESE
AD609	IN-ACTIVE ARCO STATI	3 CALIFORNIA DR	HIST UST	Higher	2485, 0.471, ESE
AD610	ARCO #0249	3 CALIFORNIA	LUST	Higher	2485, 0.471, ESE
AD611	ARCO	3 CALIFORNIA DR	RGA LUST	Higher	2485, 0.471, ESE
AD612	FORMER ARCO # 00249	3 CALIFORNIA	RGA LUST	Higher	2485, 0.471, ESE
AD613	PUTNAM MAZDA	3 CALIFORNIA DR	HAZNET	Higher	2485, 0.471, ESE
AD614	BP WEST COAST PRODUC	3 CALIFORNIA DR	HAZNET	Higher	2485, 0.471, ESE
AD615	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR	RGA LUST	Higher	2485, 0.471, ESE
AD616	PUTNAM MAZDA	3 CALIFORNIA DR	HAZNET	Higher	2485, 0.471, ESE
AD617	PUTNAM VOLVO	3-65 CALIFORNIA	San Mateo Co. BI	Higher	2485, 0.471, ESE
AD618	PUTNAM MAZDA BUICK	3 CALIFORNIA DR	RGA LUST	Higher	2485, 0.471, ESE
AD619	PUTNAM MAZDA	3 CALIFORNIA DR	RCRA-SQG, LUST, FINDS, HIST CORTESE, ECHO	Higher	2485, 0.471, ESE
AA620		BARROILHETT & EL CAM	CHMIRS	Higher	2486, 0.471, SE
AJ621	SHEN LINCOLN MERCURY	2 CALIFORNIA DR	HAZNET	Higher	2502, 0.474, ESE
AJ622	PUTNAM AUTOMOTIVE FI	2-50 CALIFORNIA	San Mateo Co. BI	Higher	2502, 0.474, ESE
AJ623	SHEN-LINCOLN MERCURY	2 CALIFORNIA	RGA LUST	Higher	2502, 0.474, ESE
AJ624	SHEN-LINCOLN MERCURY	2 CALIFORNIA	LUST	Higher	2502, 0.474, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AJ625	SHEN MITSUBISHI	2 CALIFORNIA DR	RGA LUST	Higher	2502, 0.474, ESE
AJ626	SHEN MITSUBISHI	2 CALIFORNIA	San Mateo Co. BI	Higher	2502, 0.474, ESE
AJ627	PUTNAM LINCOLN MERCU	2 CALIFORNIA DR	HAZNET	Higher	2502, 0.474, ESE
AJ628	SHEN-MITSUBISHI	2 CALIFORNIA DR	RGA LUST	Higher	2502, 0.474, ESE
AJ629	PUTNAM LINCOLN MERCU	2 CALIFORNIA DR	RCRA-SQG, LUST, HIST CORTESE	Higher	2502, 0.474, ESE
AJ630	PUTNAM TOYOTA	2 CALIFORNIA	San Mateo Co. BI	Higher	2502, 0.474, ESE
AJ631	PUTNAM AUTOMOTIVE	2 CALIFORNIA DRIVE	EMI	Higher	2502, 0.474, ESE
AJ632	SHEN-LINCOLN MERCURY	2 CALIFORNIA DR	RGA LUST	Higher	2502, 0.474, ESE
AJ633	SHEN LINCOLN MERCURY	2 CALIFORNIA DR	RGA LUST	Higher	2502, 0.474, ESE
AJ634	PUTNAM AUTOMOTIVE	2 CALIFORNIA DRIVE	FINDS, ECHO	Higher	2502, 0.474, ESE
Z635	LYNETTE ADAMS	609 VERNON WAY	HAZNET	Lower	2504, 0.474, NE
AI636	GARY YEUNG	15 SUMMERHOLME PL	HAZNET	Higher	2508, 0.475, WSW
AK637	ELLEN GRUBER	840 EDGEHILL DR	HAZNET	Lower	2510, 0.475, NW
AH638	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	2546, 0.482, SW
AH639	SHUBINER PROPERTY	1715 RALSTON	LUST, HIST CORTESE	Higher	2598, 0.492, SSW
AH640	SHUBINER PROPERTY	1715 RALSTON AVE	RGA LUST	Higher	2598, 0.492, SSW
AH641	SHUBINER PROPERTY	1715 RALSTON	RGA LUST	Higher	2598, 0.492, SSW
AH642	RESIDENCE	1715 RALSTON	San Mateo Co. BI	Higher	2598, 0.492, SSW
AH643	JEFF & ADRIENNE SCHU	1715 RALSTON AVE	HAZNET	Higher	2598, 0.492, SSW
AJ644	VERACOM AUTOMOTIVE G	885 N SAN MATEO DR	HAZNET	Higher	2603, 0.493, ESE
AJ645	VERACOM AUTOMOTIVE G	885 SAN MATEO	San Mateo Co. BI	Higher	2603, 0.493, ESE
AJ646	PUTNAM VOLVO	900 PENINSULA	San Mateo Co. BI	Higher	2629, 0.498, ESE
AJ647	PUTNAM BUICK INC	900 PENINSULA	San Mateo Co. BI	Higher	2629, 0.498, ESE
AJ648	PUTNAM AUTOMOTIVE	900 PENINSULA AVENUE	EMI	Higher	2629, 0.498, ESE
AJ649		900 PENINSULA AVE	EDR Hist Auto	Higher	2629, 0.498, ESE
AJ650	PUTNAM AUTOMOTIVE	900 PENINSULA AVENUE	FINDS, ECHO	Higher	2629, 0.498, ESE
AJ651	PUTNAM BUICK PONTIAC	900 PENINSULA AVE	FINDS, ECHO	Higher	2629, 0.498, ESE
AJ652	PUTNAM BUICK PONTIAC	900 PENINSULA AVE	HAZNET	Higher	2629, 0.498, ESE
AJ653	DUTNAM HYUNDAI	900 PENINSULA AVE	RCRA-SQG, FINDS, ECHO	Higher	2629, 0.498, ESE
AH654	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	2640, 0.500, SSW
655	CROCKER ESTATE	1178 BARROIHET	San Mateo Co. BI	Higher	2642, 0.500, South
AH656	UST SITE	310 PEPPER	San Mateo Co. BI	Higher	2652, 0.502, SW
AH657	OFFIELD ESTATE TRUST	310 PEPPER AVE	LUST, HAZNET	Higher	2652, 0.502, SW
AK658		867 CALIFORNIA DR	EDR Hist Auto	Lower	2675, 0.507, NW
AF659	T MOBILE WEST CORP S	777 MORRELL	San Mateo Co. BI	Lower	2725, 0.516, NNW
AJ660	SHEN LINCOLN MERCURY	888 N SAN MATEO AVE	RCRA-SQG, LUST, FINDS, HAZNET, ECHO	Higher	2733, 0.518, ESE
AJ661	SHEN LINCOLN MERCURY	888 SAN MATEO	SLIC, San Mateo Co. BI, NPDES	Higher	2733, 0.518, ESE
AJ662	EXXON CO USA SAN MAT	320 PENINSULA	LUST, RCRA NonGen / NLR, FINDS, HIST CORTESE, ECHO	Higher	2740, 0.519, ESE
AJ663	WHITECLIFF CO	859 SAN MATEO	San Mateo Co. BI	Higher	2792, 0.529, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AJ664	WHITECLIFF COMPANY I	859 SAN MATEO DRIVE	HIST UST	Higher	2792, 0.529, ESE
AL665		149 WARREN RD	SWEEPS UST	Higher	2804, 0.531, SSE
AL666	REVEREND PHEOPHILOS	149 WARREN	LUST	Higher	2804, 0.531, SSE
AL667	RESIDENCE	149 WARREN	LUST, San Mateo Co. BI, HIST CORTESE	Higher	2804, 0.531, SSE
AM668		847 ACACIA AVE	EDR Hist Auto	Lower	2856, 0.541, WNW
669	BER MANAGEMENT, INC.	789 EL CAMINO REAL	San Mateo Co. BI	Higher	2870, 0.544, West
670	HERRMANN, DIANNA	141 PEPPER	San Mateo Co. BI	Higher	2916, 0.552, SSW
AM671	SPECKMAN, LARRY	843 CROSSWAY	San Mateo Co. BI	Higher	2964, 0.561, WNW
AJ672	PK AUTOMOTIVE	839 SAN MATEO	San Mateo Co. BI	Higher	2984, 0.565, ESE
AJ673		839 N SAN MATEO DR	EDR Hist Auto	Higher	2984, 0.565, ESE
AJ674	PACIFIC READY MIX	850 SAN MATEO	ENVIROSTOR, LUST	Higher	3000, 0.568, ESE
AJ675	PACIFIC READY MIX	850 SAN MATEO	LUST, HIST CORTESE	Higher	3000, 0.568, ESE
AJ676	PACIFIC READY MIX IN	850 SAN MATEO DR	HIST UST	Higher	3000, 0.568, ESE
AJ677	REMMERS D SON	833 SAN MATEO	San Mateo Co. BI	Higher	3040, 0.576, ESE
AN678		400 PENINSULA AVE	EDR Hist Auto	Lower	3072, 0.582, East
AN679	SAIS SUPER SHELL 6	400 PENINSULA	HIST UST	Lower	3072, 0.582, East
AN680	PENINSULA SHELL	400 PENINSULA AVE	RCRA-SQG, LUST, FINDS, San Mateo Co. BI, HAZNET,...	Lower	3072, 0.582, East
AN681	SHELL OIL STATION, #	400 PENINSULA AVE	SWEEPS UST, CA FID UST	Lower	3072, 0.582, East
AN682	K&B PRODUCTS	863 WOODSIDE	San Mateo Co. BI	Higher	3075, 0.582, East
AO683	BUD'S TIRE SERVICE	836 NORTH SAN MATEO	LUST	Higher	3098, 0.587, ESE
AO684	BUD'S TIRE SERVICE	836 SAN MATEO	LUST, HIST CORTESE	Higher	3098, 0.587, ESE
685		217 STATE RD	EDR Hist Auto	Higher	3136, 0.594, ESE
AO686	AUTOPLUS	823 SAN MATEO	San Mateo Co. BI	Higher	3136, 0.594, ESE
AO687	BURLINGAME SAAB	825 SAN MATEO	San Mateo Co. BI	Higher	3147, 0.596, ESE
AO688	COLE EUROPEAN VOLVO	825 N SAN MATEO DRIV	HIST UST, HAZNET	Higher	3147, 0.596, ESE
AO689		825 N SAN MATEO DR	EDR Hist Auto	Higher	3147, 0.596, ESE
690	BROSNAN, JOHN	760 OCCIDENTAL	San Mateo Co. BI	Higher	3182, 0.603, South
AO691	SHEN INFINITY	800 N SAN MATEO DR	RCRA-SQG, LUST, FINDS, San Mateo Co. BI, ENF, HIST...	Higher	3225, 0.611, ESE
AO692	SHEN INFINITI	800 SAN MATEO DR N	LUST	Higher	3225, 0.611, ESE
693	DICK GREGORY, D.D.S.	720 EL CAMINO REAL	San Mateo Co. BI	Higher	3285, 0.622, SE
AL694		151 SYCAMORE	SWEEPS UST	Higher	3328, 0.630, SSE
AL695	RESIDENCE	151 SYCAMORE	SWEEPS UST	Higher	3328, 0.630, SSE
AO696	ALL TUNE & LUBE	801 SAN MATEO	San Mateo Co. BI	Higher	3343, 0.633, ESE
AP697	MALCOLM PROPERTY	625 HURLINGHAM	LUST, San Mateo Co. BI, HIST CORTESE	Higher	3387, 0.641, SSE
AP698	MALCOLM PROPERTY	625 HURLINGHAM	LUST	Higher	3387, 0.641, SSE
AO699	P K AUTO SERVICE	790 N SAN MATEO DR	RCRA-SQG, LUST, FINDS, ECHO	Higher	3415, 0.647, ESE
AO700	VERACOM MITSUBISHI	790 SAN MATEO	LUST, San Mateo Co. BI	Higher	3415, 0.647, ESE
AO701	MIKE HARVEY TOYOTA,	790 N SAN MATEO DR	LUST	Higher	3415, 0.647, ESE
AO702	P K AUTO SERVICE	790 N SAN MATEO DR	RCRA-SQG	Higher	3415, 0.647, ESE

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AO703	TOYOTA CENTER INC	790 N SAN MATEO DRIV	HIST UST, HAZNET	Higher	3415, 0.647, ESE
AP704	RESIDENCE	625 HULINGHAM	SWEEPS UST, CA FID UST	Higher	3439, 0.651, SSE
AQ705	ALL CAR AUTO PAINTIN	903 CALIFORNIA DR	RCRA-SQG	Lower	3449, 0.653, NW
AQ706	SUNNY AUTO BODY	903 CALIFORNIA	San Mateo Co. BI	Lower	3449, 0.653, NW
AN707	AUTO WORKS	815 WOODSIDE	ENVIROSTOR, San Mateo Co. BI	Higher	3449, 0.653, ESE
AN708	PARAMOUNT COLLISION	815 WOODSIDE WAY	RCRA-SQG, FINDS, EMI, ECHO	Higher	3449, 0.653, ESE
AQ709	AUTOHAUS EXEC	909 CALIFORNIA	San Mateo Co. BI	Lower	3487, 0.660, NW
AQ710	MULTI CRAFT AUTO BOD	917 CALIFORNIA	San Mateo Co. BI	Lower	3536, 0.670, NW
AQ711	MULTI CRAFT AUTO BOD	917 CALIFORNIA	San Mateo Co. BI	Lower	3536, 0.670, NW
AQ712	BARTLETTS AUTO BODY	917 CALIFORNIA DR	RCRA-SQG, FINDS, ECHO	Lower	3536, 0.670, NW
AQ713	ANCHOR BODY & DETAIL	1008 CAROLAN	San Mateo Co. BI	Lower	3546, 0.672, NW
AQ714	ADVANCE AUTOMOTIVE	921 CALIFORNIA	San Mateo Co. BI	Lower	3560, 0.674, NW
AQ715	ARTISAN MOTORS	921 CALIFORNIA	San Mateo Co. BI	Lower	3560, 0.674, NW
AR716	INTERSTATE FLORAL CO	801 WOODSIDE	SWEEPS UST, CA FID UST, San Mateo Co. BI	Higher	3621, 0.686, ESE
717	CITY OF BURLINGAME	399 ROLLINS ROAD	San Mateo Co. BI, EMI	Lower	3634, 0.688, NE
AQ718	BURLINGAME SUBARU	1020 CAROLAN	San Mateo Co. BI	Lower	3640, 0.689, NW
AQ719	BURLINGAME SUBARU	1020 CAROLAN AVE	SWEEPS UST, CA FID UST	Lower	3640, 0.689, NW
AS720	METRO PARK AIRPORT P	615 AIRPORT BLVD	SWEEPS UST, CA FID UST	Lower	3658, 0.693, NNE
AS721	ANZA PARKING	615 AIRPORT BLVD	LUST, HIST UST, San Mateo Co. BI	Lower	3658, 0.693, NNE
AT722	7 ELEVEN	975 ROLLINS RD	San Mateo Co. BI, HAZNET	Lower	3659, 0.693, NW
AU723	SAN MATEO IMAGING	715 N SAN MATEO DR	RCRA-SQG, FINDS, ECHO	Higher	3671, 0.695, ESE
724	STROMBERG, LOUISE	617 CRESCENT	San Mateo Co. BI	Higher	3672, 0.695, SSE
725	RESIDENCE	215 CHANNING	San Mateo Co. BI	Lower	3679, 0.697, ENE
AU726	COMMERCIAL PROPERTY	716 N SAN MATEO DR	SWEEPS UST	Higher	3680, 0.697, ESE
AU727	COMMERCIAL PROPERTY	716 SAN MATEO	San Mateo Co. BI	Higher	3683, 0.698, ESE
AQ728	TOPLINE AUTOMOBILE I	1028 CAROLAN	San Mateo Co. BI	Lower	3703, 0.701, NW
AQ729	CAMMISA MOTOR CAR CO	1028 CAROLAN	San Mateo Co. BI	Lower	3703, 0.701, NW
AQ730	BAY CITIES COLLISION	1028 CAROLAN	San Mateo Co. BI	Lower	3703, 0.701, NW
AU731	SAN MATEO MOTORS	704 N SAN MATEO DR	RCRA-SQG, FINDS, ECHO	Higher	3722, 0.705, ESE
AU732	MA'S AUTO REPAIR & S	704 SAN MATEO	San Mateo Co. BI	Higher	3722, 0.705, ESE
AU733	MARTIN AUTO COLOR IN	305 VILLA TERRACE	San Mateo Co. BI, HAZNET	Higher	3751, 0.710, ESE
AQ734	ARATA HONDA	1020 CALOLAN AVE	HIST UST	Lower	3783, 0.716, NW
AS735	SHERATON GATEWAY HOT	600 AIRPORT	San Mateo Co. BI	Lower	3788, 0.717, NNE
AS736	HILTON SAN FRANCISCO	600 AIRPORT	San Mateo Co. BI	Lower	3788, 0.717, NNE
AV737	BAY PARK PLAZA	577/555 AIRPORT	San Mateo Co. BI	Lower	3821, 0.724, NNE
AV738	HUDSON BAY PARK PLAZ	555/577 AIRPORT	San Mateo Co. BI	Lower	3821, 0.724, NNE
AS739	VIRGIN AMERICA INC	555 AIRPORT	San Mateo Co. BI	Lower	3828, 0.725, NNE
AW740	CHEVRON STATION NO 9	880 N DELAWARE ST	RCRA NonGen / NLR, FINDS, HAZNET, ECHO	Lower	3840, 0.727, East
AW741	CHEVRON STATION	880 DELAWARE	LUST, San Mateo Co. BI, HIST CORTESE	Lower	3840, 0.727, East

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AW742	PENINSULA CHEVRON	880 N DELAWARE	LUST, SWEEPS UST, HIST UST, CA FID UST	Lower	3840, 0.727, East
743	CHEVRON STATION #005	610 N EL CAMINO REAL	LUST, SWEEPS UST, CA FID UST	Higher	3863, 0.732, SE
AW744	CVS PHARMACY NO 9940	872 N DELAWARE	RCRA-LQG, FINDS, ECHO	Lower	3872, 0.733, East
AT745	LES VOGEL	1007 ROLLINS	LUST	Lower	3875, 0.734, NW
AT746	LES VOGEL DODGE	1007 ROLLINS RD	RCRA-SQG, SWEEPS UST, CA FID UST, FINDS, HAZNET,...	Lower	3875, 0.734, NW
AT747	MIKE HARVEY TOYOTA	1007 ROLLINS	San Mateo Co. BI	Lower	3875, 0.734, NW
AT748	FOUR CAR GARAGE INC	1007 ROLLINS	San Mateo Co. BI	Lower	3875, 0.734, NW
AW749	PETCO #5313	866 DELAWARE	San Mateo Co. BI	Lower	3888, 0.736, East
AT750	CALBAY	1009 ROLLINS ROAD	San Mateo Co. BI, EMI	Lower	3890, 0.737, NW
AW751	SAFEWAY 0694	860 DELAWARE	San Mateo Co. BI	Lower	3904, 0.739, East
AT752	MIKE HARVEY OLSMOBIL	1008 ROLLINS RD	RCRA-SQG, HIST UST, FINDS, ECHO	Lower	3908, 0.740, NW
AW753	HOLIDAY CLEANERS	850 DELAWARE	ENVIROSTOR, San Mateo Co. BI	Lower	3931, 0.745, East
AX754	RESIDENCE	632 OCCIDENTAL	SWEEPS UST, San Mateo Co. BI	Higher	3935, 0.745, South
AT755	ANCHOR DETAILING	1008 CAROLAN AVE STE	San Mateo Co. BI, HAZNET	Lower	3935, 0.745, NW
AT756	BAY CITIES COLLISION	1017 ROLLINS	San Mateo Co. BI	Lower	3949, 0.748, NW
AR757	PENINSULA CAR CARE	717 WOODSIDE	San Mateo Co. BI	Higher	3954, 0.749, ESE
AT758	ALFRED MOLAKDIS PROP	1019 ROLLINS ROAD	LUST, SLIC, HIST CORTESE	Lower	3964, 0.751, NW
AT759	TEEVAN EXTERIOR CONT	1019 ROLLINS RD	SLIC	Lower	3964, 0.751, NW
AX760	RESIDENCE	706 EDGEWOOD	LUST, SWEEPS UST	Higher	4040, 0.765, South
AY761	ZIMMERMAN RESIDENCE	2135 RALSTON AVE	LUST	Higher	4090, 0.775, SW
AX762	MORISON PROPERTY	420 WESTMORELAND	LUST, SWEEPS UST, San Mateo Co. BI, HIST CORTESE	Higher	4125, 0.781, South
AX763	RESIDENCE	610 OCCIDENTAL	LUST, SWEEPS UST, San Mateo Co. BI, HIST CORTESE	Higher	4159, 0.788, South
AZ764	REAL ESTATE NORTH IN	370 LANG	LUST, SLIC	Lower	4194, 0.794, NE
BA765	AUTOPRIDE CAR WASH	1095 CAROLAN AVENUE	LUST, HAZNET, HIST CORTESE	Lower	4217, 0.799, NW
BA766	BROADWAY LOCKSMITH	1009 CALIFORNIA	LUST, HIST CORTESE	Lower	4265, 0.808, NW
BA767	BROADWAY LOCKSMITH	1009 CALIFORNIA	LUST	Lower	4265, 0.808, NW
AZ768	GOLDEN GATE DRYWALL	399 BEACH	LUST, HIST CORTESE	Lower	4288, 0.812, NE
AZ769	GOLDEN GATE DRYWALL	399 BEACH RD	LUST, HIST UST, CA FID UST	Lower	4288, 0.812, NE
BA770	MARTINELLI PROPERTY	1015 CALIFORNIA	LUST, HIST CORTESE	Lower	4298, 0.814, NW
BB771	JORDAN RESIDENCE	245 W BELLEVUE	LUST, SWEEPS UST	Higher	4362, 0.826, SSE
BC772	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4407, 0.835, SW
BD773	SPRINT	828 AIRPORT	LUST	Lower	4479, 0.848, North
BD774	SPRINT	828 AIRPORT	LUST, HIST CORTESE	Lower	4479, 0.848, North
AY775	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4519, 0.856, SW
BC776	DURCATO RESIDENCE	1888 FLORIBUNDA	LUST, HIST CORTESE	Higher	4600, 0.871, SW
BB777	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4601, 0.871, SSE
778	BURLINGAME DISPOSAL	1001 S AIRPORT ROAD	SWF/LF	Lower	4628, 0.877, NNW
BE779	GREENE, JAMES & MARR	725 HILLSBOROUGH BLV	LUST, SWEEPS UST, HIST CORTESE	Higher	4669, 0.884, SSW
BF780	CLEVELAND PROPERTY	2215 RALSTON	LUST, HIST CORTESE	Higher	4731, 0.896, SW

MAPPED SITES SUMMARY

Target Property Address:
1214 DONNELLY
BURLINGAME, CA 94010

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BE781	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4758, 0.901, SSW
782	UST SITE - RESIDENTI	505 OCCIDENTAL	LUST, San Mateo Co. BI	Higher	4773, 0.904, South
BE783	YUAN PROPERTY	839 SEABURY	LUST, HIST CORTESE	Higher	4774, 0.904, SSW
BE784	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4776, 0.905, SSW
BE785	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4818, 0.913, SSW
BF786	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4854, 0.919, SW
BG787	UNITED TRANSMISSION	1131 CALIFORNIA	LUST, SWEEPS UST, HIST CORTESE	Lower	4903, 0.929, WNW
BG788	UNITED TRANSMISSION	1131 CALIFORNIA DR	RCRA-SQG, LUST, CA FID UST, FINDS, ECHO	Lower	4903, 0.929, WNW
BH789	ARCO FACILITY #725	402 N EL CAMINO REAL	LUST, SWEEPS UST, CA FID UST, HAZNET	Lower	4933, 0.934, SE
BH790	AAA SPEEDY SMOG	402 EL CAMINO	LUST, San Mateo Co. BI, HIST CORTESE	Lower	4933, 0.934, SE
BI791	PRIVATE RESIDENCE	PRIVATE RESIDENCE	LUST	Higher	4953, 0.938, SSW
792	BOWER RESIDENCE	8 PENINSULA AVE	LUST	Lower	4963, 0.940, ENE
BJ793	UNOCAL #3885	1147 ROLLINS	LUST	Lower	4964, 0.940, NW
BJ794	UNOCAL	1147 ROLLINS	LUST, SWEEPS UST, HIST CORTESE	Lower	4964, 0.940, NW
BK795	HAMBLIN TRUST	1065 AMPHLETT BOULEV	LUST	Lower	5017, 0.950, ENE
796	MCALLISTO TRUST	700 EUCALYPTUS	LUST, SWEEPS UST, HIST CORTESE	Higher	5037, 0.954, WSW
BE797	MILLER PROPERTY	730 SEABURY	LUST, HIST CORTESE	Higher	5043, 0.955, SSW
BG798	RECTOR CADILLAC	1010 CADILLAC	LUST	Lower	5050, 0.956, NW
BG799	DENT WIZARD INTERNAT	1010 CADILLAC WAY	RCRA-SQG, LUST, FINDS, EMI, HAZNET, HIST CORTESE,...	Lower	5050, 0.956, NW
BH800	UNION OIL SERVICE ST	346 N EL CAMINO REAL	LUST, SWEEPS UST, HIST UST, CA FID UST	Lower	5099, 0.966, SE
BH801	UNION OIL SERVICE ST	346 EL CAMINO REAL	LUST, San Mateo Co. BI, HIST CORTESE	Lower	5099, 0.966, SE
802	MCCARTHY RESIDENCE	828 IRWIN DR	LUST	Higher	5130, 0.972, WSW
BI803	CHOZEN RESIDENCE	640 BREWER DR	LUST	Higher	5131, 0.972, SSW
BG804	ENCORE THEATRE	1159 CALIFORNIA	LUST, SWEEPS UST, HIST CORTESE	Lower	5136, 0.973, WNW
BG805	ENCORE THEATER	1159 CALIFORNIA	LUST	Lower	5136, 0.973, WNW
BL806	SAN MATEO HIGH AUTO	506 DELAWARE	LUST, San Mateo Co. BI, HIST CORTESE	Lower	5139, 0.973, ESE
BL807	SAN MATEO HIGH SCHOO	506 DELAWARE	LUST	Lower	5139, 0.973, ESE
BL808	SAN MATEO UNION HIGH	506 N DELAWARE ST	LUST	Lower	5139, 0.973, ESE
BK809	J D RECYCLING	1015 N AMPHLETT BLVD	SWRCY, NPDES	Lower	5269, 0.998, ENE
810	CARUFF CALIFORNIA CO	350 AIRPORT BOULEVAR	Notify 65	Lower	5404, 1.023, NE
811	MOBILE SERVICE STATI	1200 BAYSHORE HIGHWA	Notify 65	Lower	5620, 1.064, NW
812	PACIFIC CONSTRUCTION	1369 NORTH CAROLAN A	LUST, HIST CORTESE, Notify 65	Lower	6764, 1.281, NW
813	PURI PROPERTY	20 NORTH RAILROAD AV	ENVIROSTOR, SLIC, San Mateo Co. BI	Lower	7474, 1.416, ESE
814	BELLA MANGIATA RESTA	233 BALDWIN	ENVIROSTOR, LUST, San Mateo Co. BI	Lower	7775, 1.473, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
JOHN BRITTON 1218 DONNELLY AVE BURLINGAME, CA 94010	HAZNET GEPAID: CAC002779641	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent NPL

RESPONSE ---- State Response Sites

State and tribal leaking storage tank lists

INDIAN LUST ---- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST ---- Underground Storage Tank Listing
AST ---- Aboveground Petroleum Storage Tank Facilities
INDIAN UST ---- Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing
VCP ---- Voluntary Cleanup Program Properties

State and tribal Brownfields sites

BROWNFIELDS ---- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ---- Waste Management Unit Database
HAULERS ---- Registered Waste Tire Haulers Listing
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---- Open Dump Inventory

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
HIST Cal-Sites ---- Historical Calsites Database
Toxic Pits ---- Toxic Pits Cleanup Act Sites
US CDL ---- National Clandestine Laboratory Register

Local Land Records

LIENS ---- Environmental Liens Listing
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
LDS ---- Land Disposal Sites Listing

MCS Military Cleanup Sites Listing

Other Ascertainable Records

FUDS Formerly Used Defense Sites
DOD Department of Defense Sites
SCRD DRYCLEANERS State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR Financial Assurance Information
EPA WATCH LIST EPA WATCH LIST
2020 COR ACTION 2020 Corrective Action Program List
TSCA Toxic Substances Control Act
TRIS Toxic Chemical Release Inventory System
SSTS Section 7 Tracking Systems
ROD Records Of Decision
RMP Risk Management Plans
RAATS RCRA Administrative Action Tracking System
PRP Potentially Responsible Parties
PADS PCB Activity Database System
ICIS Integrated Compliance Information System
FTTS FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS Material Licensing Tracking System
COAL ASH DOE Steam-Electric Plant Operation Data
COAL ASH EPA Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER PCB Transformer Registration Database
RADINFO Radiation Information Database
HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS Incident and Accident Data
CONSENT Superfund (CERCLA) Consent Decrees
INDIAN RESERV Indian Reservations
FUSRAP Formerly Utilized Sites Remedial Action Program
UMTRA Uranium Mill Tailings Sites
LEAD SMELTERS Lead Smelter Sites
US AIRS Aerometric Information Retrieval System Facility Subsystem
US MINES Mines Master Index File
UXO Unexploded Ordnance Sites
DOCKET HWC Hazardous Waste Compliance Docket Listing
CA BOND EXP. PLAN Bond Expenditure Plan
CUPA Listings CUPA Resources List
Financial Assurance Financial Assurance Information Listing
HWP EnviroStor Permitted Facilities Listing
HWT Registered Hazardous Waste Transporter Database
MINES Mines Site Location Listing
MWMP Medical Waste Management Program Listing
PROC Certified Processors Database
UIC UIC Listing
WASTEWATER PITS Oil Wastewater Pits Listing
WDS Waste Discharge System
WIP Well Investigation Program Case List
FUELS PROGRAM EPA Fuels Program Registered Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF ---------- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 03/07/2016 has revealed that there is 1 SEMS-ARCHIVE site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PICKRELL D J	1408 CHAPIN AVE	WSW 0 - 1/8 (0.098 mi.)	C64	57

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity

generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 2 RCRA-LQG sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER CAINE CLEANER	1319/1321 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G191	203

Lower Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY NO 9940	***872 N DELAWARE***	***E 1/2 - 1 (0.733 mi.)***	***AW744***	***728***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/09/2015 has revealed that there are 32 RCRA-SQG sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SEPHORA STORE 52 BUR	1205 BURLINGAME AVEN	ESE 0 - 1/8 (0.085 mi.)	A56	50
FORMER CAINE CLEANER	***1319 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G189***	***201***
CAINES CLEANERS	***1321 HOWARD AVENUE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G192***	***205***
STERLING CLEANERS	***1140 HOWARD AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G205***	***221***
PACIFIC BELL	***1480 BURLINGAME AVEN***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H221***	***238***
BLUE BIRD CLEANERS	***190 PRIMROSE RD***	***SSE 1/8 - 1/4 (0.202 mi.)***	***G230***	***250***
WALGREENS NO 86	***1420 HOWARD AVE***	***S 1/8 - 1/4 (0.203 mi.)***	***G235***	***254***
CHEVRON 90571	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K271***	***284***
PUTNAM CHEVROLET CAD	***198 CALIFORNIA DR***	***E 1/8 - 1/4 (0.230 mi.)***	***I306***	***325***
BURLINGAME SUBARU AL	***150 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.284 mi.)***	***I385***	***391***
BURLINGAME COLLISION	***123 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.315 mi.)***	***S421***	***421***
BURLINGAME FORD	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
PUTNAM TOYOTA	***100 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.347 mi.)***	***S455***	***456***
J AND M MOTORS D B A	***50 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S539***	***519***
PUTNAM MAZDA	***3 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.471 mi.)***	***AD619***	***586***
PUTNAM LINCOLN MERCU	***2 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.474 mi.)***	***AJ629***	***606***
DUTNAM HYUNDAI	***900 PENINSULA AVE***	***ESE 1/4 - 1/2 (0.498 mi.)***	***AJ653***	***628***
SHEN LINCOLN MERCURY	***888 N SAN MATEO AVE***	***ESE 1/2 - 1 (0.518 mi.)***	***AJ660***	***633***
SHEN INFINITY	***800 N SAN MATEO DR***	***ESE 1/2 - 1 (0.611 mi.)***	***AO691***	***672***
P K AUTO SERVICE	***790 N SAN MATEO DR***	***ESE 1/2 - 1 (0.647 mi.)***	***AO699***	***681***
P K AUTO SERVICE	790 N SAN MATEO DR	ESE 1/2 - 1 (0.647 mi.)	AO702	686
PARAMOUNT COLLISION	***815 WOODSIDE WAY***	***ESE 1/2 - 1 (0.653 mi.)***	***AN708***	***694***
SAN MATEO IMAGING	***715 N SAN MATEO DR***	***ESE 1/2 - 1 (0.695 mi.)***	***AU723***	***710***
SAN MATEO MOTORS	***704 N SAN MATEO DR***	***ESE 1/2 - 1 (0.705 mi.)***	***AU731***	***714***

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOUR CAR GARAGE THE	***609 CALIFORNIA DR***	***NW 1/8 - 1/4 (0.218 mi.)***	***F260***	***273***
ON TRACK AUTOMOTIVE	***621 CALIFORNIA DR***	***NW 1/8 - 1/4 (0.235 mi.)***	***M313***	***332***
EUROPEAN PERFORMANCE	***751 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.326 mi.)***	***M433***	***437***
PENINSULA SHELL	***400 PENINSULA AVE***	***E 1/2 - 1 (0.582 mi.)***	***AN680***	***653***
ALL CAR AUTO PAINTIN	903 CALIFORNIA DR	NW 1/2 - 1 (0.653 mi.)	AQ705	690
BARTLETTS AUTO BODY	***917 CALIFORNIA DR***	***NW 1/2 - 1 (0.670 mi.)***	***AQ712***	***697***

Lower Elevation	Address	Direction / Distance	Map ID	Page
LES VOGEL DODGE	***1007 ROLLINS RD***	***NW 1/2 - 1 (0.734 mi.)***	***AT746***	***731***
MIKE HARVEY OLSMOBIL	***1008 ROLLINS RD***	***NW 1/2 - 1 (0.740 mi.)***	***AT752***	***738***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/09/2015 has revealed that there is 1 RCRA-CESQG site within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WALGREENS #12257	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K274	287

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 05/02/2016 has revealed that there are 6 ENVIROSTOR sites within approximately 1.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PACIFIC READY MIX	***850 SAN MATEO***	***ESE 1/2 - 1 (0.568 mi.)***	***AJ674***	***648***
Facility Id: 41320028				
Status: Refer: Other Agency				
AUTO WORKS	***815 WOODSIDE***	***ESE 1/2 - 1 (0.653 mi.)***	***AN707***	***692***
Facility Id: 41750034				
Status: No Further Action				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME HIGH SCHO	***400 CAROLAN AVENUE***	***NNE 0 - 1/8 (0.117 mi.)***	***D85***	***79***
Facility Id: 41820008				
Status: Certified / Operation & Maintenance				
HOLIDAY CLEANERS	***850 DELAWARE***	***E 1/2 - 1 (0.745 mi.)***	***AW753***	***741***
Facility Id: 41720099				
Status: Refer: Other Agency				
PURI PROPERTY	***20 NORTH RAILROAD AV***	***ESE 1 - 2 (1.416 mi.)***	***813***	***852***

Facility Id: 60001044
Status: Refer: 1248 Local Agency

BELLA MANGIATA RESTA ***233 BALDWIN*** ***SE 1 - 2 (1.473 mi.)*** ***814*** ***854***
Facility Id: 41720090
Status: Refer: Other Agency

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME DISPOSAL	1001 S AIRPORT ROAD	NNW 1/2 - 1 (0.877 mi.)	778	780
Database: SWF/LF (SWIS), Date of Government Version: 05/16/2016 Facility ID: 41-CR-0014 Operational Status: Closed Regulation Status: Permitted				

State and tribal leaking storage tank lists

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, has revealed that there are 130 LUST sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KIRKBRIDE PROPERTY	307 LORTON	E 0 - 1/8 (0.058 mi.)	A9	13
Database: LUST REG 2, Date of Government Version: 09/30/2004 Facility Status: Case Closed date9: 12/9/1997				
KIRKBRIDE PROPERTY	***307 LORTON***	***E 0 - 1/8 (0.058 mi.)***	***A10***	***14***
Database: LUST, Date of Government Version: 03/14/2016 Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016 Status: Completed - Case Closed Facility Id: 660081 Facility Status: 9- Case Closed Global Id: T0608100953 Global ID: T0608100953				
BURLINGAME POST OFFI	220 PARK	SE 0 - 1/8 (0.119 mi.)	B102	115
Database: LUST, Date of Government Version: 03/14/2016 Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016 Status: Completed - Case Closed				

Facility Id: 660040
Facility Status: 9- Case Closed
Global Id: T0608100091
Global ID: T0608100091

US POSTAL SERVICE ***220 PARK*** ***SE 0 - 1/8 (0.119 mi.)*** ***B105*** ***117***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 11/28/1995

STERLING CLEANERS (F 215 CALIFORNIA DRIVE ESE 1/8 - 1/4 (0.167 mi.) B146 151
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Open - Site Assessment
Facility Id: 660105
Facility Id: 669113
Facility Status: 3B- Preliminary Assessment Underway
Global Id: T10000003211
Global ID: T10000003211
Global ID: T10000005652

200 PARK 200 PARK ROAD SE 1/8 - 1/4 (0.180 mi.) G163 164
Database: LUST, Date of Government Version: 03/14/2016
Status: Open - Assessment & Interim Remedial Action
Global Id: T10000004152

HARRIS PROPERTY ***1234 HOWARD*** ***SE 1/8 - 1/4 (0.182 mi.)*** ***G173*** ***172***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Status: Open - Remediation
Facility Status: Remedial action (cleanup) Underway
Global Id: T0608100253

KING YEE PROPERTY ***1200 HOWARD*** ***SE 1/8 - 1/4 (0.185 mi.)*** ***G178*** ***182***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Status: Open - Remediation
Facility Status: Remedial action (cleanup) Underway
Global Id: T0608100813

BERENSTEIN ASSOC. PR ***1319 HOWARD*** ***SSE 1/8 - 1/4 (0.189 mi.)*** ***G187*** ***199***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 669096
Facility Status: 5R- Remediation Plan
Global ID: T0608186803

STERLING CLEANERS ***1140 HOWARD AVENUE*** ***ESE 1/8 - 1/4 (0.191 mi.)*** ***G204*** ***220***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 669111
Facility Status: 3B- Preliminary Assessment Underway
Global ID: T10000006541

PACIFIC BELL ***1480 BURLINGAME AVEN*** ***SSW 1/8 - 1/4 (0.198 mi.)*** ***H221*** ***238***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 7/9/1992

PACIFIC BELL ***1480 BURLINGAME AVE.*** ***SSW 1/8 - 1/4 (0.198 mi.)*** ***H225*** ***246***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed

Facility Id: 660023
Facility Status: 9- Case Closed
Global Id: T0608100377
Global ID: T0608100377

SHELL ***1490 BURLINGAME*** ***SSW 1/8 - 1/4 (0.216 mi.)*** ***H247*** ***264***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660001
Facility Status: 9- Case Closed
Global Id: T0608100468
Global ID: T0608100468

SHELL 1490 BURLINGAME SSW 1/8 - 1/4 (0.216 mi.) H252 269
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 8/21/2001

CHEVRON 9-0571 260 EL CAMINO REAL SSW 1/8 - 1/4 (0.222 mi.) K272 287
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Pollution Characterization

90571 ***260 EL CAMINO REAL*** ***SSW 1/8 - 1/4 (0.222 mi.)*** ***K285*** ***297***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660046
Facility Status: 9- Case Closed
Global Id: T0608100128
Global ID: T0608100128

ARATA PROPERTY 198 CALIFORNIA E 1/8 - 1/4 (0.230 mi.) I302 322
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 12/27/2001

PUTNAM CHEVROLET CAD ***198 CALIFORNIA DR*** ***E 1/8 - 1/4 (0.230 mi.)*** ***I306*** ***325***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660060
Facility Status: 9- Case Closed
Global Id: T0608101044
Global ID: T0608101044

CHEVRON, FORMER/EAGL 177 CALIFORNIA ESE 1/8 - 1/4 (0.248 mi.) I325 340
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Pollution Characterization

CHEVRON, FORMER/EAGL ***177 CALIFORNIA*** ***ESE 1/8 - 1/4 (0.248 mi.)*** ***I326*** ***340***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660013
Facility Status: 9- Case Closed
Global Id: T0608194030
Global ID: T0608194030

SAREMI PROPERTY 100 CALIFORNIA ESE 1/4 - 1/2 (0.347 mi.) S451 453
Database: LUST REG 2, Date of Government Version: 09/30/2004

Facility Status: Case Closed
date9: 12/27/2001

SAREMI PROPERTY ***100 CALIFORNIA*** ***ESE 1/4 - 1/2 (0.347 mi.)*** ***S454*** ***455***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660068
Facility Status: 9- Case Closed
Global Id: T0608100232
Global ID: T0608100232

BURLINGAME FORD ***99 CALIFORNIA*** ***ESE 1/4 - 1/2 (0.352 mi.)*** ***S467*** ***466***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660043
Facility Status: 9- Case Closed
Global Id: T0608100090
Global ID: T0608100090
date9: 5/15/1995

SERVICE STATION 709 ***1 PARK ROAD*** ***SE 1/4 - 1/2 (0.407 mi.)*** ***AA520*** ***507***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Global Id: T0608100043
date9: 3/16/2001

ARMSTRONG PROPERTY ***1 PARK RD*** ***SE 1/4 - 1/2 (0.407 mi.)*** ***AA524*** ***512***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 660027
Facility Status: 9- Case Closed
Global ID: T0608100043

PUTNAM MAZDA II ***50 CALIFORNIA*** ***ESE 1/4 - 1/2 (0.414 mi.)*** ***S537*** ***517***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660048
Facility Status: 9- Case Closed
Global Id: T0608100409
Global ID: T0608100409

PUTNAM MAZDA II 50 CALIFORNIA ESE 1/4 - 1/2 (0.414 mi.) S538 519
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 12/27/1995

PRIVATE RESIDENCE PRIVATE RESIDENCE WSW 1/4 - 1/2 (0.415 mi.) X548 530
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608101015

MCKINLEY SCHOOL ***701 PALOMA*** ***W 1/4 - 1/2 (0.429 mi.)*** ***X565*** ***546***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Id: 660066
Facility Status: 9- Case Closed
Global Id: T0608100742
Global ID: T0608100742

MCKINLEY SCHOOL | 701 PALOMA | W 1/4 - 1/2 (0.429 mi.) | X567 | 548
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 12/5/1994

SMITH RESIDENCE | 1615 FLORIBUNDA | WSW 1/4 - 1/2 (0.440 mi.) | AG581 | 557
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 870018
Facility Status: 9- Case Closed
Global ID: T0608101015

SMITH RESIDENCE | 1615 FLORIBUNDA | WSW 1/4 - 1/2 (0.440 mi.) | AG584 | 558
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 9/1/2000

TOWN OF HILLSBOROUGH | 1600 FLORIBUNDA | WSW 1/4 - 1/2 (0.445 mi.) | AG589 | 562
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 3/5/1999

HILLSBOROUGH TOWN OF | 1600 FLORIBUNDA | WSW 1/4 - 1/2 (0.445 mi.) | AG596 | 569
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 870005
Facility Status: 9- Case Closed
Global Id: T0608100704
Global ID: T0608100704

ARCO #0249 | 3 CALIFORNIA | ESE 1/4 - 1/2 (0.471 mi.) | AD610 | 579
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Pollution Characterization

PUTNAM MAZDA | 3 CALIFORNIA DR | ESE 1/4 - 1/2 (0.471 mi.) | AD619 | 586
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Open - Site Assessment
Facility Id: 660026
Facility Status: 5C- Pollution Characterization
Global Id: T0608100410
Global ID: T0608100410

SHEN-LINCOLN MERCURY | 2 CALIFORNIA | ESE 1/4 - 1/2 (0.474 mi.) | AJ624 | 604
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 7/30/2004

PUTNAM LINCOLN MERCU | 2 CALIFORNIA DR | ESE 1/4 - 1/2 (0.474 mi.) | AJ629 | 606
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660005
Facility Status: 9- Case Closed
Global Id: T0608100495

Global ID: T0608100495

PRIVATE RESIDENCE | PRIVATE RESIDENCE | SW 1/4 - 1/2 (0.482 mi.) | AH638 | 613
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608125944
Global Id: T10000002008

SHUBINER PROPERTY | ***1715 RALSTON*** | ***SSW 1/4 - 1/2 (0.492 mi.)*** | ***AH639*** | ***619***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 668078
Facility Status: 9- Case Closed
Global ID: T0608100938

PRIVATE RESIDENCE | PRIVATE RESIDENCE | SSW 1/4 - 1/2 (0.500 mi.) | AH654 | 630
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100938

OFFIELD ESTATE TRUST | ***310 PEPPER AVE*** | ***SW 1/2 - 1 (0.502 mi.)*** | ***AH657*** | ***631***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 668102
Facility Status: 9- Case Closed

SHEN LINCOLN MERCURY | ***888 N SAN MATEO AVE*** | ***ESE 1/2 - 1 (0.518 mi.)*** | ***AJ660*** | ***633***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 119177
Facility Status: 9- Case Closed
Global ID: TI0000003682

EXXON CO USA SAN MAT | ***320 PENINSULA*** | ***ESE 1/2 - 1 (0.519 mi.)*** | ***AJ662*** | ***639***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 110013
Facility Status: 9- Case Closed
Global Id: T0608100208
Global ID: T0608100208
date9: 6/4/2001

REVEREND PHEOPHILOS | 149 WARREN | SSE 1/2 - 1 (0.531 mi.) | AL666 | 643
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Post remedial action monitoring

RESIDENCE | ***149 WARREN*** | ***SSE 1/2 - 1 (0.531 mi.)*** | ***AL667*** | ***644***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110092
Facility Status: 9- Case Closed
Global Id: T0608100773
Global ID: T0608100773

PACIFIC READY MIX | ***850 SAN MATEO*** | ***ESE 1/2 - 1 (0.568 mi.)*** | ***AJ674*** | ***648***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110006
Facility Status: 9- Case Closed

Global Id: T0608100382
Global ID: T0608100382

PACIFIC READY MIX ***850 SAN MATEO*** ***ESE 1/2 - 1 (0.568 mi.)*** ***AJ675*** ***650***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 8/31/2001

BUD'S TIRE SERVICE 836 NORTH SAN MATEO ESE 1/2 - 1 (0.587 mi.) AO683 667
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110015
Facility Status: 9- Case Closed
Global Id: T0608100086
Global ID: T0608100086

BUD'S TIRE SERVICE ***836 SAN MATEO*** ***ESE 1/2 - 1 (0.587 mi.)*** ***AO684*** ***669***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 10/6/1995

SHEN INFINITY ***800 N SAN MATEO DR*** ***ESE 1/2 - 1 (0.611 mi.)*** ***AO691*** ***672***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Id: 48-0147
Facility Status: Preliminary site assessment underway

SHEN INFINITI 800 SAN MATEO DR N ESE 1/2 - 1 (0.611 mi.) AO692 676
Database: LUST, Date of Government Version: 03/14/2016
Status: Open - Inactive
Global Id: T0609500138

MALCOLM PROPERTY ***625 HURLINGHAM*** ***SSE 1/2 - 1 (0.641 mi.)*** ***AP697*** ***679***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110075
Facility Status: 9- Case Closed
Global Id: T0608100636
Global ID: T0608100636

MALCOLM PROPERTY 625 HURLINGHAM SSE 1/2 - 1 (0.641 mi.) AP698 681
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 9/30/1992

P K AUTO SERVICE ***790 N SAN MATEO DR*** ***ESE 1/2 - 1 (0.647 mi.)*** ***AO699*** ***681***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 5/28/2004

VERACOM MITSUBISHI ***790 SAN MATEO*** ***ESE 1/2 - 1 (0.647 mi.)*** ***AO700*** ***684***
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100333

MIKE HARVEY TOYOTA, 790 N SAN MATEO DR ESE 1/2 - 1 (0.647 mi.) AO701 686
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 110023
Facility Status: 9- Case Closed
Global ID: T0608100333

CHEVRON STATION #005 ***610 N EL CAMINO REAL*** ***SE 1/2 - 1 (0.732 mi.)*** ***743*** ***727***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Facility Id: 110016
Facility Status: 9- Case Closed
Global ID: T0608100142

RESIDENCE ***706 EDGEWOOD*** ***S 1/2 - 1 (0.765 mi.)*** ***AX760*** ***747***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 110068
Facility Status: 9- Case Closed
Global Id: T0608100275
Global ID: T0608100275
date9: 9/22/1992

ZIMMERMAN RESIDENCE 2135 RALSTON AVE SW 1/2 - 1 (0.775 mi.) AY761 749
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878011
Facility Status: 9- Case Closed
Global ID: T0608100916

MORISON PROPERTY ***420 WESTMORELAND*** ***S 1/2 - 1 (0.781 mi.)*** ***AX762*** ***749***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 110084
Facility Status: 9- Case Closed
Global Id: T0608100689
Global ID: T0608100689
date9: 4/10/1996

RESIDENCE ***610 OCCIDENTAL*** ***S 1/2 - 1 (0.788 mi.)*** ***AX763*** ***752***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 41-0202
Facility Status: Case Closed
Global Id: T0608100192
date9: 8/7/1992

JORDAN RESIDENCE ***245 W BELLEVUE*** ***SSE 1/2 - 1 (0.826 mi.)*** ***BB771*** ***773***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 118074
Facility Status: 9- Case Closed
Global ID: T0608100187

PRIVATE RESIDENCE PRIVATE RESIDENCE SW 1/2 - 1 (0.835 mi.) BC772 774
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608159713

PRIVATE RESIDENCE PRIVATE RESIDENCE SW 1/2 - 1 (0.856 mi.) AY775 777
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100916

DURCATO RESIDENCE ***1888 FLORIBUNDA*** ***SW 1/2 - 1 (0.871 mi.)*** ***BC776*** ***778***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Facility Id: 118001
Facility Status: 9- Case Closed
Global ID: T0608159713

PRIVATE RESIDENCE PRIVATE RESIDENCE SSE 1/2 - 1 (0.871 mi.) BB777 779
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100187

GREENE, JAMES & MARR ***725 HILLSBOROUGH BLV*** ***SSW 1/2 - 1 (0.884 mi.)*** ***BE779*** ***781***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878007
Facility Status: 9- Case Closed
Global ID: T0608100706

CLEVELAND PROPERTY ***2215 RALSTON*** ***SW 1/2 - 1 (0.896 mi.)*** ***BF780*** ***782***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878008
Facility Status: 9- Case Closed
Global ID: T0608194884

PRIVATE RESIDENCE PRIVATE RESIDENCE SSW 1/2 - 1 (0.901 mi.) BE781 782
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100706

UST SITE - RESIDENTI ***505 OCCIDENTAL*** ***S 1/2 - 1 (0.904 mi.)*** ***782*** ***783***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 118188
Facility Status: 3B- Preliminary Assessment Underway
Global ID: T10000008170

YUAN PROPERTY ***839 SEABURY*** ***SSW 1/2 - 1 (0.904 mi.)*** ***BE783*** ***784***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 870016
Facility Status: 9- Case Closed
Global ID: T0608100971

PRIVATE RESIDENCE PRIVATE RESIDENCE SSW 1/2 - 1 (0.905 mi.) BE784 784
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608101061

PRIVATE RESIDENCE PRIVATE RESIDENCE SSW 1/2 - 1 (0.913 mi.) BE785 785
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608100971

PRIVATE RESIDENCE PRIVATE RESIDENCE SW 1/2 - 1 (0.919 mi.) BF786 786
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608194884

PRIVATE RESIDENCE PRIVATE RESIDENCE SSW 1/2 - 1 (0.938 mi.) BI791 809
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608176244

MCALLISTO TRUST ***700 EUCALYPTUS*** ***WSW 1/2 - 1 (0.954 mi.)*** ***796*** ***824***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 870006
Facility Status: 9- Case Closed
Global Id: T0608100703
Global ID: T0608100703
date9: 3/30/1994

MILLER PROPERTY ***730 SEABURY*** ***SSW 1/2 - 1 (0.955 mi.)*** ***BE797*** ***826***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878012
Facility Status: 9- Case Closed
Global ID: T0608101061

MCCARTHY RESIDENCE 828 IRWIN DR WSW 1/2 - 1 (0.972 mi.) 802 842
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878024
Facility Status: 9- Case Closed
Global ID: TI0000003500

CHOZEN RESIDENCE 640 BREWER DR SSW 1/2 - 1 (0.972 mi.) BI803 842
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 878019
Facility Status: 9- Case Closed
Global ID: T0608176244

Lower Elevation	Address	Direction / Distance	Map ID	Page

LORTON PLACE OWNERS 345 LORTON AVENUE N 0 - 1/8 (0.025 mi.) A5 11
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660111
Facility Status: 9- Case Closed
Global Id: T10000004932

SABATINI TRUST 361 CALIFORNIA NE 0 - 1/8 (0.059 mi.) A12 17
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T10000004188

DON SABATINI ***361 CALIFORNIA DR*** ***NE 0 - 1/8 (0.059 mi.)*** ***A14*** ***19***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 660110
Facility Status: 9- Case Closed

KIM MILLS TEXACO (FO 401 CALIFORNIA N 0 - 1/8 (0.073 mi.) A25 24
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660107
Facility Status: 9- Case Closed
Global Id: T10000003636
Global ID: T100003636

ARLINGTON APARTMENTS ***1401 FLORIBUNDA*** ***W 1/8 - 1/4 (0.180 mi.)*** ***E157*** ***160***
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T10000005179

THE ARLINGTON APARTM ***1401 FLORIBUNDA AVE*** ***W 1/8 - 1/4 (0.180 mi.)*** ***E158*** ***161***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Facility Id: 660112
Facility Status: 9- Case Closed

SHELL ***601 CALIFORNIA*** ***NW 1/8 - 1/4 (0.194 mi.)*** ***F211*** ***229***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 10/10/1991

SHELL ***601 CALIFORNIA*** ***NW 1/8 - 1/4 (0.194 mi.)*** ***F214*** ***230***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660017
Facility Status: 9- Case Closed
Global Id: T0608100487
Global ID: T0608100487

W. J. BRITTON COMPAN ***701 CALIFORNIA*** ***NW 1/4 - 1/2 (0.254 mi.)*** ***M344*** ***360***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660006
Facility Status: 9- Case Closed
Global Id: T0608100626
Global ID: T0608100626
date9: 6/30/1998

DEITER BLUHM ***1285 OAK GROVE*** ***WNW 1/4 - 1/2 (0.309 mi.)*** ***L400*** ***402***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660042
Facility Status: 9- Case Closed
Global Id: T0608100073
Global ID: T0608100073
date9: 9/30/1991

FLOYDS AUTOMOTIVE ***741 SAN MATEO AVE*** ***NW 1/4 - 1/2 (0.315 mi.)*** ***M422*** ***429***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660061
Facility Status: 9- Case Closed
Global Id: T0608100222
Global ID: T0608100222

FLOYD'S AUTOMOTIVE 741 SAN MATEO NW 1/4 - 1/2 (0.315 mi.) M424 431
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 9/5/2000

NICKS HONDA ***775 CALIFORNIA DRIVE*** ***NW 1/4 - 1/2 (0.351 mi.)*** ***W464*** ***464***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 669109
Facility Status: 9- Case Closed
Global ID: T10000004181

SHAFFER'S TIRE CENTE ***777 CALIFORNIA*** ***NW 1/4 - 1/2 (0.370 mi.)*** ***W484*** ***477***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Id: 669108
Facility Id: 660034
Facility Status: 9- Case Closed
Global Id: T0608100458
Global ID: T10000004180

SHAFFER'S TIRE CENTE | 777 CALIFORNIA | NW 1/4 - 1/2 (0.370 mi.) | W486 | 480
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 1/14/1992

BURLINGAME FIRE DEPT | 799 CALIFORNIA | NW 1/4 - 1/2 (0.376 mi.) | W502 | 494
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660062
Facility Status: 9- Case Closed
Global Id: T0608100642
Global ID: T0608100642
date9: 8/9/2002

CALIF. FEDERAL SAVIN | 1112 PALM | NW 1/4 - 1/2 (0.434 mi.) | W575 | 552
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660063
Facility Status: 9- Case Closed
Global Id: T0608100675
Global ID: T0608100675

CALIF. FEDERAL SAVIN | 1112 PALM | NW 1/4 - 1/2 (0.434 mi.) | W576 | 554
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 11/12/1995

PENINSULA SHELL | 400 PENINSULA AVE | E 1/2 - 1 (0.582 mi.) | AN680 | 653
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110151
Facility Status: 9- Case Closed
Global Id: T0608196925
Global ID: T0608196925

ANZA PARKING | 615 AIRPORT BLVD | NNE 1/2 - 1 (0.693 mi.) | AS721 | 707
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660085
Facility Status: 9- Case Closed
Global Id: T0608192381
Global ID: T0608192381
date9: 3/17/2000

CHEVRON STATION | 880 DELAWARE | E 1/2 - 1 (0.727 mi.) | AW741 | 722
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Status: Case Closed
Global Id: T0608100943
date9: 3/15/2004

PENINSULA CHEVRON ***880 N DELAWARE*** ***E 1/2 - 1 (0.727 mi.)*** ***AW742*** ***725***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 110108
Facility Status: 9- Case Closed
Global ID: T0608100943

LES VOGEL 1007 ROLLINS NW 1/2 - 1 (0.734 mi.) AT745 730
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 669083
Facility Status: 9- Case Closed
Global Id: T0608189622
Global ID: T0608189622

ALFRED MOLAKDIS PROP ***1019 ROLLINS ROAD*** ***NW 1/2 - 1 (0.751 mi.)*** ***AT758*** ***746***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 669002
Facility Status: 9- Case Closed
Global ID: T0608190888

REAL ESTATE NORTH IN ***370 LANG*** ***NE 1/2 - 1 (0.794 mi.)*** ***AZ764*** ***754***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 669104
Facility Id: 660100
Facility Status: 9- Case Closed
Global Id: T0608108772
Global ID: T10000003038

AUTOPRIDE CAR WASH ***1095 CAROLAN AVENUE*** ***NW 1/2 - 1 (0.799 mi.)*** ***BA765*** ***759***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Preliminary site assessment underway
Facility Id: 660080
Facility Status: 9- Case Closed
Global Id: T0608100954
Global ID: T0608100954

BROADWAY LOCKSMITH ***1009 CALIFORNIA*** ***NW 1/2 - 1 (0.808 mi.)*** ***BA766*** ***767***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660035
Facility Status: 9- Case Closed
Global Id: T0608100094
Global ID: T0608100094

BROADWAY LOCKSMITH 1009 CALIFORNIA NW 1/2 - 1 (0.808 mi.) BA767 769
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 3/30/2000

GOLDEN GATE DRYWALL ***399 BEACH*** ***NE 1/2 - 1 (0.812 mi.)*** ***AZ768*** ***769***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Id: 660069
Facility Status: 9- Case Closed
Global Id: T0608100992
Global ID: T0608100992

GOLDEN GATE DRYWALL ***399 BEACH RD*** ***NE 1/2 - 1 (0.812 mi.)*** ***AZ769*** ***770***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 10/4/2002

MARTINELLI PROPERTY ***1015 CALIFORNIA*** ***NW 1/2 - 1 (0.814 mi.)*** ***BA770*** ***772***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Facility Id: 660079
Facility Status: 9- Case Closed
Global Id: T0608100936
Global ID: T0608100936
date9: 5/17/2000

SPRINT 828 AIRPORT N 1/2 - 1 (0.848 mi.) BD773 775
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 10/4/2000

SPRINT ***828 AIRPORT*** ***N 1/2 - 1 (0.848 mi.)*** ***BD774*** ***776***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660084
Facility Status: 9- Case Closed
Global Id: T0608101111
Global ID: T0608101111

UNITED TRANSMISSION ***1131 CALIFORNIA*** ***WNW 1/2 - 1 (0.929 mi.)*** ***BG787*** ***787***
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660053
Facility Status: 9- Case Closed
Global Id: T0608100229
Global ID: T0608100229

UNITED TRANSMISSION ***1131 CALIFORNIA DR*** ***WNW 1/2 - 1 (0.929 mi.)*** ***BG788*** ***789***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 11/20/1996

ARCO FACILITY #725 ***402 N EL CAMINO REAL*** ***SE 1/2 - 1 (0.934 mi.)*** ***BH789*** ***791***
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 110011
Facility Status: 7- Remedial Action Underway
Global ID: T0608100037

AAA SPEEDY SMOG ***402 EL CAMINO*** ***SE 1/2 - 1 (0.934 mi.)*** ***BH790*** ***795***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016

Status: Open - Site Assessment
Facility Status: Remedial action (cleanup) Underway
Global Id: T0608100037

BOWER RESIDENCE | 8 PENINSULA AVE | ENE 1/2 - 1 (0.940 mi.) | 792 | 810
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 668098
Facility Status: 9- Case Closed
Global ID: T0608125944

UNOCAL #3885 | 1147 ROLLINS | NW 1/2 - 1 (0.940 mi.) | BJ793 | 810
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Post remedial action monitoring

UNOCAL | 1147 ROLLINS | NW 1/2 - 1 (0.940 mi.) | BJ794 | 811
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Open - Verification Monitoring
Facility Id: 660055
Facility Status: 5C- Pollution Characterization
Global Id: T0608100566
Global ID: T0608100566

HAMBLIN TRUST | 1065 AMPHLETT BOULEV | ENE 1/2 - 1 (0.950 mi.) | BK795 | 821
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 110176
Facility Status: 9- Case Closed
Global Id: T10000003674
Global ID: TI0000003674

RECTOR CADILLAC | 1010 CADILLAC | NW 1/2 - 1 (0.956 mi.) | BG798 | 827
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 6/9/1992

DENT WIZARD INTERNAT | 1010 CADILLAC WAY | NW 1/2 - 1 (0.956 mi.) | BG799 | 827
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Id: 660022
Facility Status: 9- Case Closed
Global Id: T0608100418
Global ID: T0608100418

UNION OIL SERVICE ST | 346 N EL CAMINO REAL | SE 1/2 - 1 (0.966 mi.) | BH800 | 836
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 110062
Facility Status: 9- Case Closed
Global ID: T0608100582

UNION OIL SERVICE ST | 346 EL CAMINO REAL | SE 1/2 - 1 (0.966 mi.) | BH801 | 840
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Facility Status: Case Closed
Global Id: T0608100582
date9: 3/18/2002

ENCORE THEATRE | 1159 CALIFORNIA | WNW 1/2 - 1 (0.973 mi.) | BG804 | 842
Database: LUST, Date of Government Version: 03/14/2016
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016

Status: Completed - Case Closed
Facility Id: 660041
Facility Status: 9- Case Closed
Global Id: T0608100196
Global ID: T0608100196

ENCORE THEATER | 1159 CALIFORNIA | WNW 1/2 - 1 (0.973 mi.) | BG805 | 844
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 9/23/1997

SAN MATEO HIGH AUTO | ***506 DELAWARE*** | ***ESE 1/2 - 1 (0.973 mi.)*** | ***BL806*** | ***845***
Database: LUST, Date of Government Version: 03/14/2016
Status: Completed - Case Closed
Global Id: T0608101053

SAN MATEO HIGH SCHOO | 506 DELAWARE | ESE 1/2 - 1 (0.973 mi.) | BL807 | 847
Database: LUST REG 2, Date of Government Version: 09/30/2004
Facility Status: Case Closed
date9: 1/9/1998

SAN MATEO UNION HIGH | 506 N DELAWARE ST | ESE 1/2 - 1 (0.973 mi.) | BL808 | 847
Database: SAN MATEO CO. LUST, Date of Government Version: 03/14/2016
Facility Id: 110115
Facility Id: 110173
Facility Status: 9- Case Closed
Global ID: T0608101053
Global ID: T10000002505

SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, has revealed that there are 9 SLIC sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UST SITE	***215 CALIFORNIA***	***ESE 1/8 - 1/4 (0.167 mi.)***	***B148***	***156***
Database: SLIC, Date of Government Version: 03/14/2016 Facility Status: Open - Site Assessment Global Id: T10000005652				
BERENSTEIN ASSOC. PR	***1319 HOWARD***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G187***	***199***
Database: SLIC, Date of Government Version: 03/14/2016 Facility Status: Open - Site Assessment Global Id: T0608186803				
STERLING CLEANERS	***1140 HOWARD AVENUE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G204***	***220***
Database: SLIC, Date of Government Version: 03/14/2016 Facility Status: Open - Site Assessment Global Id: T10000006541				
SHEN LINCOLN MERCURY	***888 SAN MATEO***	***ESE 1/2 - 1 (0.518 mi.)***	***AJ661***	***637***
Database: SLIC, Date of Government Version: 03/14/2016 Facility Status: Completed - Case Closed Global Id: T10000003682				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NICKS HONDA	***775 CALIFORNIA DRIVE***	***NW 1/4 - 1/2 (0.351 mi.)***	***W464***	***464***
Database: SLIC, Date of Government Version: 03/14/2016				

Facility Status: Completed - Case Closed
Global Id: T10000004181

SHAFFER'S TIRE CENTE ***777 CALIFORNIA*** ***NW 1/4 - 1/2 (0.370 mi.)*** ***W484*** ***477***
Database: SLIC, Date of Government Version: 03/14/2016
Facility Status: Completed - Case Closed
Global Id: T10000004180

ALFRED MOLAKDIS PROP ***1019 ROLLINS ROAD*** ***NW 1/2 - 1 (0.751 mi.)*** ***AT758*** ***746***
Database: SLIC, Date of Government Version: 03/14/2016
Facility Status: Completed - Case Closed
Global Id: T0608190888

TEEVAN EXTERIOR CONT 1019 ROLLINS RD NW 1/2 - 1 (0.751 mi.) AT759 746
Database: SLIC REG 2, Date of Government Version: 09/30/2004
Facility Id: 41S0015

REAL ESTATE NORTH IN ***370 LANG*** ***NE 1/2 - 1 (0.794 mi.)*** ***AZ764*** ***754***
Database: SLIC, Date of Government Version: 03/14/2016
Facility Status: Completed - Case Closed
Global Id: T10000003038

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 4 UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PACIFIC BELL	***1480 BURLINGAME AVE.***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H225***	***246***
Database: UST, Date of Government Version: 03/14/2016 Facility Id: 41-000-022765				
CHEVRON 9-0571	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K282	294
Database: UST, Date of Government Version: 03/14/2016 Facility Id: 41--017976				
BUBBLE CAR WASH	177 CALIFORNIA DR	ESE 1/8 - 1/4 (0.248 mi.)	I329	344
Database: UST, Date of Government Version: 03/14/2016 Facility Id: 41-000-660026				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME TEXACO	601CALIFORNIA DR.	NW 1/8 - 1/4 (0.194 mi.)	F220	238
Database: UST, Date of Government Version: 03/14/2016 Facility Id: 41-000-018003				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 03/15/2016 has revealed that there is 1 SWRCY site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
J D RECYCLING	***1015 N AMPHLETT BLVD***	***ENE 1/2 - 1 (0.998 mi.)***	***BK809***	***848***
Cert Id: RC130155.001				

Local Lists of Hazardous waste / Contaminated Sites

SCH: This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category. depending on the level of threat to public health and safety or the. environment they pose.

A review of the SCH list, as provided by EDR, and dated 05/02/2016 has revealed that there is 1 SCH site within approximately 0.75 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME HIGH SCHO	***400 CAROLAN AVENUE***	***NNE 0 - 1/8 (0.117 mi.)***	***D85***	***79***
Facility Id: 41820008				
Status: Certified / Operation & Maintenance				

CDL: A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

A review of the CDL list, as provided by EDR, and dated 12/31/2015 has revealed that there is 1 CDL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	442 CALIFORNIA DR	NNW 0 - 1/8 (0.118 mi.)	D96	112
Facility Id: 2001-01-097				

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are

EXECUTIVE SUMMARY

29 SWEEPS UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PACIFIC BELL Status: A Tank Status: A Comp Number: 660034	***1480 BURLINGAME AVE.***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H225***	***246***
HUGHES BURLINGAME SH Comp Number: 660052	***1490 BURLINGAME AVE***	***SSW 1/8 - 1/4 (0.216 mi.)***	***H249***	***266***
BOBS CHEVRON Comp Number: 660025	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K276***	***290***
BUBBLE MACHINE Status: A Tank Status: A Comp Number: 660026	***177 CALIFORNIA DR***	***ESE 1/8 - 1/4 (0.248 mi.)***	***I323***	***338***
BURLINGAME FORD Status: A Tank Status: A Comp Number: 665014	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
HOBBY STORE Comp Number: 660030	***100 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.347 mi.)***	***S453***	***454***
J AND M MOTORS D B A Comp Number: 660003	***50 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S539***	***519***
MCKINLEY SCHOOL Comp Number: 660100	***701 PALOMA***	***W 1/4 - 1/2 (0.429 mi.)***	***X565***	***546***
TOWN OF HILLSBOROUGH Status: A Tank Status: A Comp Number: 870006	***1600 FLORIBUNDA AVE***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG588***	***560***
Not reported Comp Number: 110201	149 WARREN RD	SSE 1/2 - 1 (0.531 mi.)	AL665	643
Not reported Comp Number: 110157	151 SYCAMORE	SSE 1/2 - 1 (0.630 mi.)	AL694	678
RESIDENCE Status: A Comp Number: 110157	151 SYCAMORE	SSE 1/2 - 1 (0.630 mi.)	AL695	678
RESIDENCE Comp Number: 110181	***625 HULINGHAM***	***SSE 1/2 - 1 (0.651 mi.)***	***AP704***	***690***
INTERSTATE FLORAL CO Comp Number: 110121	***801 WOODSIDE***	***ESE 1/2 - 1 (0.686 mi.)***	***AR716***	***700***
COMMERCIAL PROPERTY Comp Number: 110186	716 N SAN MATEO DR	ESE 1/2 - 1 (0.697 mi.)	AU726	712
CHEVRON STATION #005 Comp Number: 110036	***610 N EL CAMINO REAL***	***SE 1/2 - 1 (0.732 mi.)***	***743***	***727***
RESIDENCE Comp Number: 110200	***632 OCCIDENTAL***	***S 1/2 - 1 (0.745 mi.)***	***AX754***	***742***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME BEACON	***601 CALIFORNIA DR***	***NW 1/8 - 1/4 (0.194 mi.)***	***F218***	***235***

Status: A Tank Status: A Comp Number: 660053				
RICKS BEACON Status: A Tank Status: A Comp Number: 660101 Comp Number: 660061	***988 HOWARD AVE***	***E 1/4 - 1/2 (0.275 mi.)***	***P374***	***383***
FLOYDS AUTOMOTIVE Status: A Comp Number: 660096	***741 SAN MATEO AVE***	***NW 1/4 - 1/2 (0.315 mi.)***	***M422***	***429***
ARTHUR BROWN Status: A Tank Status: A Comp Number: 660099	746 LAUREL	NNW 1/4 - 1/2 (0.370 mi.)	U482	476
SHAEFFER'S TIRE CENT Status: A Comp Number: 2540	***777 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.370 mi.)***	***W485***	***479***
FIRE DEPARTMENT Comp Number: 660097	***799 CALIFORNIA DR.***	***NW 1/4 - 1/2 (0.376 mi.)***	***W496***	***489***
Not reported Comp Number: 660098	1112 PALM DRIVE	NW 1/4 - 1/2 (0.434 mi.)	W571	551
SHELL OIL STATION, # Status: A Tank Status: A Comp Number: 110063	***400 PENINSULA AVE***	***E 1/2 - 1 (0.582 mi.)***	***AN681***	***665***
BURLINGAME SUBARU Comp Number: 660085	***1020 CAROLAN AVE***	***NW 1/2 - 1 (0.689 mi.)***	***AQ719***	***705***
METRO PARK AIRPORT P Status: A Tank Status: A Comp Number: 660013	***615 AIRPORT BLVD***	***NNE 1/2 - 1 (0.693 mi.)***	***AS720***	***706***
PENINSULA CHEVRON Status: A Tank Status: A Comp Number: 110033	***880 N DELAWARE***	***E 1/2 - 1 (0.727 mi.)***	***AW742***	***725***
LES VOGEL DODGE Comp Number: 660067	***1007 ROLLINS RD***	***NW 1/2 - 1 (0.734 mi.)***	***AT746***	***731***

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 23 HIST UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PACIFIC BELL Facility Id: 00000036935	***1480 BURLINGAME AVE.***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H225***	***246***
BURLINGAME/EL CAMINO	1490 BURLINGAME AVE	SSW 1/8 - 1/4 (0.216 mi.)	H251	268

Facility Id: 00000004470				
90571	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K285***	***297***
Facility Id: 00000061848				
MWE HARVEY CHRYSLER	***200 CALIFORNIA DRIVE***	***E 1/8 - 1/4 (0.227 mi.)***	***I292***	***314***
BURLINGAME FORD	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
Facility Id: 00000009930				
HOWER AUTO REPAIR IN	920 BAYSWATER AVE	ESE 1/4 - 1/2 (0.373 mi.)	S493	486
Facility Id: 00000010367				
COLE EUROPEAN JAGUAR	65 CALIFORNIA DR	ESE 1/4 - 1/2 (0.397 mi.)	S513	501
Facility Id: 00000002509				
SERVICE STATION 709	***1 PARK ROAD***	***SE 1/4 - 1/2 (0.407 mi.)***	***AA520***	***507***
Facility Id: 00000009205				
J AND M MOTORS D B A	***50 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S539***	***519***
Facility Id: 00000013309				
IN-ACTIVE ARCO STATI	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD609	578
Facility Id: 00000015802				
WHITECLIFF COMPANY I	859 SAN MATEO DRIVE	ESE 1/2 - 1 (0.529 mi.)	AJ664	642
Facility Id: 00000031738				
PACIFIC READY MIX IN	850 SAN MATEO DR	ESE 1/2 - 1 (0.568 mi.)	AJ676	651
Facility Id: 00000010292				
COLE EUROPEAN VOLVO	***825 N SAN MATEO DRIV***	***ESE 1/2 - 1 (0.596 mi.)***	***AO688***	***671***
TOYOTA CENTER INC	***790 N SAN MATEO DRIV***	***ESE 1/2 - 1 (0.647 mi.)***	***AO703***	***687***

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
PARK DEPT CORPORATIO	420 CAROLAN	NNE 0 - 1/8 (0.117 mi.)	D92	109
Facility Id: 00000024256				
R SPERING	601 CALIFORNIA	NW 1/8 - 1/4 (0.194 mi.)	F219	237
Facility Id: 00000010689				
RICKS TEXACO	988 HOWARD	E 1/4 - 1/2 (0.275 mi.)	P370	379
Facility Id: 00000018076				
FIRE STATION 1	799 CALIFORNIA DRIVE	NW 1/4 - 1/2 (0.376 mi.)	W499	493
Facility Id: 00000024311				
SAIS SUPER SHELL 6	400 PENINSULA	E 1/2 - 1 (0.582 mi.)	AN679	652
Facility Id: 00000060248				
ANZA PARKING	***615 AIRPORT BLVD***	***NNE 1/2 - 1 (0.693 mi.)***	***AS721***	***707***
Facility Id: 00000004118				
ARATA HONDA	1020 CALOLAN AVE	NW 1/2 - 1 (0.716 mi.)	AQ734	717
Facility Id: 00000021935				
PENINSULA CHEVRON	***880 N DELAWARE***	***E 1/2 - 1 (0.727 mi.)***	***AW742***	***725***
MIKE HARVEY OLSMOBIL	***1008 ROLLINS RD***	***NW 1/2 - 1 (0.740 mi.)***	***AT752***	***738***
Facility Id: 00000038202				

EXECUTIVE SUMMARY

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 18 CA FID UST sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUGHES BURLINGAME SH Facility Id: 41000464 Status: I	***1490 BURLINGAME AVE***	***SSW 1/8 - 1/4 (0.216 mi.)***	***H249***	***266***
BOBS CHEVRON Facility Id: 41000155 Status: A	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K276***	***290***
BUBBLE MACHINE Facility Id: 41000151 Status: A	***177 CALIFORNIA DR***	***ESE 1/8 - 1/4 (0.248 mi.)***	***I323***	***338***
BURLINGAME FORD Facility Id: 41002676 Status: A	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
HOBBY STORE Facility Id: 41000061 Status: A	***100 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.347 mi.)***	***S453***	***454***
J AND M MOTORS D B A Facility Id: 41000412 Status: A	***50 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S539***	***519***
RESIDENCE Facility Id: 41004728 Status: I	***625 HULINGHAM***	***SSE 1/2 - 1 (0.651 mi.)***	***AP704***	***690***
INTERSTATE FLORAL CO Facility Id: 41000881 Status: A	***801 WOODSIDE***	***ESE 1/2 - 1 (0.686 mi.)***	***AR716***	***700***
CHEVRON STATION #005 Facility Id: 41000162 Status: A	***610 N EL CAMINO REAL***	***SE 1/2 - 1 (0.732 mi.)***	***743***	***727***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME BEACON Facility Id: 41002016 Status: A	***601 CALIFORNIA DR***	***NW 1/8 - 1/4 (0.194 mi.)***	***F218***	***235***
RICKS BEACON Facility Id: 41003227 Status: A	***988 HOWARD AVE***	***E 1/4 - 1/2 (0.275 mi.)***	***P374***	***383***
SHAEFFER'S TIRE CENT Facility Id: 41001213 Status: A	***777 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.370 mi.)***	***W485***	***479***
FIRE DEPARTMENT Facility Id: 41000122 Status: I	***799 CALIFORNIA DR.***	***NW 1/4 - 1/2 (0.376 mi.)***	***W496***	***489***
SHELL OIL STATION, # Facility Id: 41003064	***400 PENINSULA AVE***	***E 1/2 - 1 (0.582 mi.)***	***AN681***	***665***

Status: A

BURLINGAME SUBARU Facility Id: 41004956 Status: A	***1020 CAROLAN AVE***	***NW 1/2 - 1 (0.689 mi.)***	***AQ719***	***705***
METRO PARK AIRPORT P Facility Id: 41001450 Status: A	***615 AIRPORT BLVD***	***NNE 1/2 - 1 (0.693 mi.)***	***AS720***	***706***
PENINSULA CHEVRON Facility Id: 41003378 Status: A	***880 N DELAWARE***	***E 1/2 - 1 (0.727 mi.)***	***AW742***	***725***
LES VOGEL DODGE Facility Id: 41002958 Status: A	***1007 ROLLINS RD***	***NW 1/2 - 1 (0.734 mi.)***	***AT746***	***731***

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 06/06/2016 has revealed that there is 1 DEED site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME HIGH SCHO Status: CERTIFIED / OPERATION & MAINTENANCE Envirostor ID: 41820008	***400 CAROLAN AVENUE***	***NNE 0 - 1/8 (0.117 mi.)***	***D85***	***79***

Records of Emergency Release Reports

CHMIRS: The California Hazardous Material Incident Report System contains information on reported hazardous material incidents, i.e., accidental releases or spills. The source is the California Office of Emergency Services.

A review of the CHMIRS list, as provided by EDR, and dated 04/11/2016 has revealed that there are 17 CHMIRS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported OES Incident Number: 9-1788	1419 BURLINGAME AVE	SSW 1/8 - 1/4 (0.126 mi.)	C115	123
Not reported OES Incident Number: 1-6240	1450 HOWARD AVE.	S 1/8 - 1/4 (0.219 mi.)	K266	280
Not reported OES Incident Number: 4-4165	198 CALIFORNIA DR AN	E 1/8 - 1/4 (0.230 mi.)	I296	318
Not reported OES Incident Number: 9-5313	SB EL CAMINO REAL AN	WSW 1/4 - 1/2 (0.414 mi.)	X547	529
TOWN OF HILLSBOROUGH	***1600 FLORIBUNDA AVE***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG588***	***560***

OES Incident Number: 08-0773				
TOWN OF HILLSBOROUGH OES Incident Number: 08-0157	***1600 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG589***	***562***
Not reported OES Incident Number: 1-1928	1600 FLORABUNDA AVEN	WSW 1/4 - 1/2 (0.445 mi.)	AG590	565
Not reported OES Incident Number: 7-1296	1600 FLORIBUNDA AVE.	WSW 1/4 - 1/2 (0.445 mi.)	AG595	568
Not reported OES Incident Number: 4-7095	BARROILHETT & EL CAM	SE 1/4 - 1/2 (0.471 mi.)	AA620	600

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
Not reported OES Incident Number: 991259 Date Completed: 26-JUN-88	CALIFORNIA DR. AT DO	NNW 1/8 - 1/4 (0.134 mi.)	F118	125
Not reported OES Incident Number: 2-1471	7474 E. DIVISION ROA	ENE 1/8 - 1/4 (0.148 mi.)	B129	137
Not reported OES Incident Number: 7-1762	525 CALIFORNIA DRIVE	NNW 1/8 - 1/4 (0.150 mi.)	F130	138
Not reported OES Incident Number: 08-6849	NEAR 1000 BURLINGAME	ENE 1/8 - 1/4 (0.233 mi.)	J308	329
Not reported OES Incident Number: 7-1540	OAK GROVE AND CALIFO	NW 1/4 - 1/2 (0.255 mi.)	M351	364
Not reported OES Incident Number: 6-7517	1217 OAK GROVE AVE	NW 1/4 - 1/2 (0.257 mi.)	M352	365
BLUE RIBBON CLEANERS OES Incident Number: 08-0849	***741 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.311 mi.)***	***M409***	***409***
Not reported OES Incident Number: 6-1552	CALIFORNIA DR. @ PAL	NW 1/4 - 1/2 (0.433 mi.)	Y569	550

SPILLS 90: Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

A review of the SPILLS 90 list, as provided by EDR, and dated 06/06/2012 has revealed that there is 1 SPILLS 90 site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
STERLING COURT PROJE Status: INACTIVE Site Id: SLC241S0039	EL CAMINO REAL & PEN	SE 1/4 - 1/2 (0.422 mi.)	AA554	540

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/09/2015 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JD GIUSTI TRANSPORTA	***125 LORTON AVE #2***	***SE 1/4 - 1/2 (0.259 mi.)***	***N358***	***372***
MILE HIGH TRUCKING	***108 MYRTLE RD #4***	***E 1/4 - 1/2 (0.373 mi.)***	***S494***	***487***
EXXON CO USA SAN MAT	***320 PENINSULA***	***ESE 1/2 - 1 (0.519 mi.)***	***AJ662***	***639***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CHEVRON STATION NO 9	***880 N DELAWARE ST***	***E 1/2 - 1 (0.727 mi.)***	***AW740***	***719***

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 07/20/2015 has revealed that there are 53 FINDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	***1229 BURLINGAME AVE.***	***ESE 0 - 1/8 (0.072 mi.)***	***A22***	***23***
VERIZON WIRELESS EL	***330 PRIMROSE RD STE***	***SSW 0 - 1/8 (0.079 mi.)***	***A35***	***30***
PRIMROSE CLEANERS	***339 PRIMROSE ROAD***	***SSW 0 - 1/8 (0.083 mi.)***	***A46***	***37***
SEPHORA STORE 52 BUR	***1205 BURLINGAME AVEN***	***ESE 0 - 1/8 (0.085 mi.)***	***A53***	***47***
HARRIS & CRISAFI C/O	***1205 HOWARD AVENUE***	***ESE 0 - 1/8 (0.085 mi.)***	***A54***	***47***
HARRIS-CRISAFI CLEAN	***1234 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.182 mi.)***	***G168***	***168***
HARRIS & CRISAFI C/O	***1234 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.182 mi.)***	***G169***	***168***
SHAFFER PROPERTY TRU	***1200 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.185 mi.)***	***G182***	***194***
FORMER CAINE CLEANER	1319 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G188	200
FORMER CAINE CLEANER	***1319/1321 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G190***	***203***
CAINES CLEANERS	***1321 HOWARD AVENUE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G192***	***205***
HARRIS-CRISAFI CLEAN	***1209 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.191 mi.)***	***G201***	***217***
STERLING CLEANERS	***1140 HOWARD AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G205***	***221***
HARRIS-CRISAFI CLEAN	***1201 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.192 mi.)***	***G210***	***229***
PACIFIC BELL	***1480 BURLINGAME AVEN***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H221***	***238***
BLUE BIRD CLEANERS	***190 PRIMROSE RD***	***SSE 1/8 - 1/4 (0.202 mi.)***	***G230***	***250***
WALGREENS NO 86	***1420 HOWARD AVE***	***S 1/8 - 1/4 (0.203 mi.)***	***G235***	***254***
SAFEWAY 1547	***1450 HOWARD AVE***	***S 1/8 - 1/4 (0.219 mi.)***	***K264***	***279***
CHEVRON 90571	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K271***	***284***
5793 SAN MATEO COUNT	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K280***	***292***
PUTNAM AUTOMOTIVE	***198 CALIFORNIA DRIVE***	***E 1/8 - 1/4 (0.230 mi.)***	***I298***	***319***
PUTNAM CHEVROLET CAD	***198 CALIFORNIA DR***	***E 1/8 - 1/4 (0.230 mi.)***	***I306***	***325***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HARRIS & CRISAFI C/O	*137 LORTON AVENUE*	*SE 1/8 - 1/4 (0.238 mi.)*	*I315*	*334*
MURDOCH LABORITORIES	*123 PRIMROSE*	*SSE 1/8 - 1/4 (0.243 mi.)*	*K320*	*337*
JD GIUSTI TRANSPORTA	*125 LORTON AVE #2*	*SE 1/4 - 1/2 (0.259 mi.)*	*N358*	*372*
BURLINGAME SUBARU AL	*150 CALIFORNIA DR*	*ESE 1/4 - 1/2 (0.284 mi.)*	*I385*	*391*
HAROLD'S MACHINE SHO	*127 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.309 mi.)*	*S404*	*405*
BURLINGAME COLLISION	*123 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.315 mi.)*	*S421*	*421*
BURLINGAME FORD	*101 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.346 mi.)*	*S446*	*445*
PUTNAM TOYOTA	*100 CALIFORNIA DR*	*ESE 1/4 - 1/2 (0.347 mi.)*	*S455*	*456*
MILE HIGH TRUCKING	*108 MYRTLE RD #4*	*E 1/4 - 1/2 (0.373 mi.)*	*S494*	*487*
PUTNAM AUTOMOTIVE	*65 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.397 mi.)*	*S514*	*501*
PUTNAM AUTOMOTIVE	*50 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.414 mi.)*	*S536*	*517*
J AND M MOTORS D B A	*50 CALIFORNIA DR*	*ESE 1/4 - 1/2 (0.414 mi.)*	*S539*	*519*
PUTNAM MAZDA	*3 CALIFORNIA DR*	*ESE 1/4 - 1/2 (0.471 mi.)*	*AD619*	*586*
PUTNAM AUTOMOTIVE	*2 CALIFORNIA DRIVE*	*ESE 1/4 - 1/2 (0.474 mi.)*	*AJ634*	*611*
PUTNAM AUTOMOTIVE	*900 PENINSULA AVENUE*	*ESE 1/4 - 1/2 (0.498 mi.)*	*AJ650*	*626*
PUTNAM BUICK PONTIAC	*900 PENINSULA AVE*	*ESE 1/4 - 1/2 (0.498 mi.)*	*AJ651*	*626*
DUTNAM HYUNDAI	*900 PENINSULA AVE*	*ESE 1/4 - 1/2 (0.498 mi.)*	*AJ653*	*628*

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY OF BURLINGAME	*425 CAROLAN AVENUE*	*NNE 0 - 1/8 (0.110 mi.)*	*D71*	*63*
CITY OF BURLINGAME	*501 PRIMROSE ROAD*	*W 0 - 1/8 (0.116 mi.)*	*E77*	*71*
BURLINGAME HIGH SCHO	*400 CAROLAN AVENUE*	*NNE 0 - 1/8 (0.117 mi.)*	*D84*	*79*
BURLINGAME ONE HOUR	*507 CALIFORNIA DRIVE*	*NNW 1/8 - 1/4 (0.140 mi.)*	*F124*	*134*
D & R AUTO BODY AND	*270 EAST LANE, #2*	*E 1/8 - 1/4 (0.211 mi.)*	*I236*	*257*
FOUR CAR GARAGE THE	*609 CALIFORNIA DR*	*NW 1/8 - 1/4 (0.218 mi.)*	*F260*	*273*
ON TRACK AUTOMOTIVE	*621 CALIFORNIA DR*	*NW 1/8 - 1/4 (0.235 mi.)*	*M313*	*332*
ALL MAKES AUTO BODY	*257 MYRTLE ROAD*	*ENE 1/8 - 1/4 (0.250 mi.)*	*J335*	*348*
UNITED AUTO COLLISIO	*255 MYRTLE ROAD*	*ENE 1/4 - 1/2 (0.251 mi.)*	*J338*	*354*
MIKE HARVEY HONDA	*212 EAST LANE*	*E 1/4 - 1/2 (0.258 mi.)*	*I353*	*366*
GEORGES HOLIDAY CLEA	*741 CALIFORNIA DRIVE*	*NW 1/4 - 1/2 (0.311 mi.)*	*M410*	*411*
EUROPEAN PERFORMANCE	*751 CALIFORNIA DR*	*NW 1/4 - 1/2 (0.326 mi.)*	*M433*	*437*
CITY OF BURLINGAME	*799 CALIFORNIA DRIVE*	*NW 1/4 - 1/2 (0.376 mi.)*	*W503*	*496*
PUTNAM BUICK,PONTIAC	*925 BAYSWATER STREET*	*E 1/4 - 1/2 (0.415 mi.)*	*AC553*	*539*

Hazardous Materials Business Plan, Hazardous Waste Generator, Underground Storage tanks

A review of the San Mateo Co. BI list, as provided by EDR, and dated 06/02/2016 has revealed that there are 173 San Mateo Co. BI sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MIKES AUTOMOTIVE SER Facility Id: FA0018039	1212 DONNELLY	ENE 0 - 1/8 (0.022 mi.)	A4	10
COMMERCIAL BUILDING Facility Id: FA0024376	307 LORTON	E 0 - 1/8 (0.058 mi.)	A7	13
REDLICH JR, CHRISTOP Facility Id: FA0027489	360 PRIMROSE	WSW 0 - 1/8 (0.074 mi.)	A30	27
VERIZON WIRELESS EL Facility Id: FA0027902		SSW 0 - 1/8 (0.079 mi.)	A36	30
AUTAR JOHAL PROPERTY	1301 BURLINGAME	SSE 0 - 1/8 (0.081 mi.)	A38	31

Facility Id: FA0027566				
PRIMROSE CLEANERS Facility Id: FA0056769 Facility Id: FA0007475	339 PRIMROSE	SSW 0 - 1/8 (0.083 mi.)	A47	42
SEPHORA #052 Facility Id: FA0038931	1205 BURLINGAME	ESE 0 - 1/8 (0.085 mi.)	A58	52
88 PHOTO LAB Facility Id: FA0025962	1109 BURLINGAME	E 0 - 1/8 (0.099 mi.)	B65	57
CRYO CREAM Facility Id: FA0000510	240 PARK	SE 0 - 1/8 (0.100 mi.)	B67	60
NEXTEL-SITE ID CA-03 Facility Id: FA0027316	1420 BURLINGAME	SSW 0 - 1/8 (0.122 mi.)	C112	122
SPRINT NEXTEL CELL S Facility Id: FA0044826	1420 BURLINGAME	SSW 0 - 1/8 (0.122 mi.)	C113	122
UST SITE - FORMER FO Facility Id: FA0053257	1417-15 BURLINGAME	SSW 0 - 1/8 (0.123 mi.)	C114	122
GERMAN CAR CARE Facility Id: FA0015787	251 CALIFORNIA	E 1/8 - 1/4 (0.150 mi.)	B131	140
G&C AUTO BODY Facility Id: FA0015679	251 CALIFORNIA	E 1/8 - 1/4 (0.150 mi.)	B132	140
BB STERN COMPANY Facility Id: FA0025127	222 CALIFORNIA	E 1/8 - 1/4 (0.167 mi.)	B144	151
UST SITE Facility Id: FA0046059	***215 CALIFORNIA***	***ESE 1/8 - 1/4 (0.167 mi.)***	***B148***	***156***
FEDERAL AUTO PARTS Facility Id: FA0018038	231 CALIFORNIA	E 1/8 - 1/4 (0.170 mi.)	B149	156
PANDA EXPRESS #907 Facility Id: FA0028060	1453 BURLINGAME	SSW 1/8 - 1/4 (0.172 mi.)	C151	157
UST SITE Facility Id: FA0046413	1290 HOWARD	SE 1/8 - 1/4 (0.179 mi.)	G154	159
TUCKER TRANSMISSIONS Facility Id: FA0009063	215 HATCH	ESE 1/8 - 1/4 (0.180 mi.)	B155	159
UST SITE Facility Id: FA0048379	200 PARK	SE 1/8 - 1/4 (0.180 mi.)	G161	164
CAINE CLEANERS Facility Id: FA0007336	1321 HOWARD	SSE 1/8 - 1/4 (0.189 mi.)	G193	210
STERLING CLEANERS Facility Id: FA0018042	***1140 HOWARD AVENUE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G204***	***220***
PACIFIC BELL Facility Id: FA0017985	***1480 BURLINGAME AVEN***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H221***	***238***
T MOBILE WEST CORP S Facility Id: FA0045341	1480 BURLINGAME	SSW 1/8 - 1/4 (0.198 mi.)	H226	249
SBC Facility Id: FA0005133	1480 BURLINGAME	SSW 1/8 - 1/4 (0.198 mi.)	H227	249
AT & T MOBILITY - CE Facility Id: FA0045945	1480 BURLINGAME	SSW 1/8 - 1/4 (0.198 mi.)	H229	250
WALGREENS #86	1420 HOWARD	S 1/8 - 1/4 (0.203 mi.)	G234	254

Facility Id: FA0032087				
UST SITE Facility Id: FA0046061	1100 HOWARD	ESE 1/8 - 1/4 (0.213 mi.)	I244	263
SHELL SERVICE STATIO Facility Id: FA0018002	1490 BURLINGAME	SSW 1/8 - 1/4 (0.216 mi.)	H246	264
UST SITE Facility Id: FA0046060	1101-07 HOWARD	ESE 1/8 - 1/4 (0.217 mi.)	I256	272
SAFEWAY 1547 Facility Id: FA0051396	1450 HOWARD	S 1/8 - 1/4 (0.219 mi.)	K265	280
WALGREENS #12257 Facility Id: FA0047974	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K273	287
CURRIES CHEVRON STAT Facility Id: FA0017976	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K289	313
MIKE HARVEY HONDA Facility Id: FA0010382	200 CALIFORNIA	E 1/8 - 1/4 (0.227 mi.)	I291	314
MIKE HARVEY HONDA Facility Id: FA0029336	200 CALIFORNIA	E 1/8 - 1/4 (0.227 mi.)	I293	316
PUTNAM CHEVROLET CAD Facility Id: FA0027495	198 CALIFORNIA	E 1/8 - 1/4 (0.230 mi.)	I297	319
SATURN DEVELOPMENT N Facility Id: FA0010375	198 CALIFORNIA	E 1/8 - 1/4 (0.230 mi.)	I303	323
EAGLE CAR WASH & FIL Facility Id: FA0017977	177 CALIFORNIA	ESE 1/8 - 1/4 (0.248 mi.)	I331	345
C&D AUTOMOTIVE AND M Facility Id: FA0008139	120 EL CAMINO REAL	SSE 1/4 - 1/2 (0.276 mi.)	K380	389
UST SITE Facility Id: FA0036526	1538 BURLINGAME	SSW 1/4 - 1/2 (0.294 mi.)	Q387	393
PACIFIC AUTO REPAIR Facility Id: FA0017997	124 HIGHLAND	ESE 1/4 - 1/2 (0.295 mi.)	I388	394
NOEL L MILLER INC Facility Id: FA0018009	129 CALIFORNIA	ESE 1/4 - 1/2 (0.306 mi.)	I397	400
HAROLDS MACHINE SHOP Facility Id: FA0018044	127 CALIFORNIA	ESE 1/4 - 1/2 (0.309 mi.)	S403	405
BURLINGAME COLLISON Facility Id: FA0002575	123 CALIFORNIA	ESE 1/4 - 1/2 (0.315 mi.)	S417	418
BENZ DOCTOR Facility Id: FA0045263	123 CALIFORNIA	ESE 1/4 - 1/2 (0.315 mi.)	S420	421
BURLINGAME FORD Facility Id: FA0018026	101 CALIFORNIA	ESE 1/4 - 1/2 (0.346 mi.)	S444	444
PUTNAM AUTOMOTIVE GR Facility Id: FA0055469 Facility Id: FA0026642	101 CALIFORNIA	ESE 1/4 - 1/2 (0.346 mi.)	S445	444
HOBBY STORE Facility Id: FA0009390	100 CALIFORNIA	ESE 1/4 - 1/2 (0.347 mi.)	S450	453
PUTNAM TOYOTA Facility Id: FA0014152	100 CALIFORNIA	ESE 1/4 - 1/2 (0.347 mi.)	S452	453
BURLINGAME AUTO CLIN	132 MYRTLE	E 1/4 - 1/2 (0.351 mi.)	P463	464

Facility Id: FA0006538				
HOWER AUTO REPAIR Facility Id: FA0018019	920 BAYSWATER	ESE 1/4 - 1/2 (0.373 mi.)	S491	484
NICKS HONDA & ACURA Facility Id: FA0015055	1 PARK	SE 1/4 - 1/2 (0.407 mi.)	AA528	513
ANY CAR SERVICE Facility Id: FA0049228	1 PARK	SE 1/4 - 1/2 (0.407 mi.)	AA529	513
UST SITE Facility Id: FA0026400	20 HIGHLAND	ESE 1/4 - 1/2 (0.413 mi.)	AD534	516
PUTNUM MAZADA Facility Id: FA0009730	50 CALIFORNIA	ESE 1/4 - 1/2 (0.414 mi.)	S542	523
MCKINLEY ELEMENTARY Facility Id: FA0015392	701 PALOMA	W 1/4 - 1/2 (0.429 mi.)	X560	543
RESIDENCE Facility Id: FA0024853	1615 FLORIBUNDA	WSW 1/4 - 1/2 (0.440 mi.)	AG582	557
HILLSBOROUGH TOWN HA Facility Id: FA0010329	1600 FLORIBUNDA	WSW 1/4 - 1/2 (0.445 mi.)	AG592	567
T MOBILE WEST CORP S Facility Id: FA0045342	3 CALIFORNIA	ESE 1/4 - 1/2 (0.471 mi.)	AD604	574
PUTNAM AUTOMOTIVE CH Facility Id: FA0052041	3-85 CALIFORNIA	ESE 1/4 - 1/2 (0.471 mi.)	AD608	577
PUTNAM VOLVO Facility Id: FA0006062	3-65 CALIFORNIA	ESE 1/4 - 1/2 (0.471 mi.)	AD617	586
PUTNAM AUTOMOTIVE FI Facility Id: FA0014577	2-50 CALIFORNIA	ESE 1/4 - 1/2 (0.474 mi.)	AJ622	603
SHEN MITSUBISHI Facility Id: FA0018045	2 CALIFORNIA	ESE 1/4 - 1/2 (0.474 mi.)	AJ626	605
PUTNAM TOYOTA Facility Id: FA0027496	2 CALIFORNIA	ESE 1/4 - 1/2 (0.474 mi.)	AJ630	609
RESIDENCE Facility Id: FA0024323	1715 RALSTON	SSW 1/4 - 1/2 (0.492 mi.)	AH642	620
VERACOM AUTOMOTIVE G Facility Id: FA0036915	885 SAN MATEO	ESE 1/4 - 1/2 (0.493 mi.)	AJ645	621
PUTNAM VOLVO Facility Id: FA0050090	900 PENINSULA	ESE 1/4 - 1/2 (0.498 mi.)	AJ646	621
PUTNAM BUICK INC Facility Id: FA0006097	900 PENINSULA	ESE 1/4 - 1/2 (0.498 mi.)	AJ647	622
CROCKER ESTATE Facility Id: FA0023670	1178 BARROIHET	S 1/2 - 1 (0.500 mi.)	655	631
UST SITE Facility Id: FA0045755	310 PEPPER	SW 1/2 - 1 (0.502 mi.)	AH656	631
SHEN LINCOLN MERCURY Facility Id: FA0012852	***888 SAN MATEO***	***ESE 1/2 - 1 (0.518 mi.)***	***AJ661***	***637***
WHITECLIFF CO Facility Id: FA0023669	859 SAN MATEO	ESE 1/2 - 1 (0.529 mi.)	AJ663	642
RESIDENCE	***149 WARREN***	***SSE 1/2 - 1 (0.531 mi.)***	***AL667***	***644***

Facility Id: FA0016525				
BER MANAGEMENT, INC. Facility Id: FA0027128	789 EL CAMINO REAL	W 1/2 - 1 (0.544 mi.)	669	646
HERRMANN, DIANNA Facility Id: FA0026864	141 PEPPER	SSW 1/2 - 1 (0.552 mi.)	670	646
SPECKMAN, LARRY Facility Id: FA0027870	843 CROSSWAY	WNW 1/2 - 1 (0.561 mi.)	AM671	646
PK AUTOMOTIVE Facility Id: FA0004412	839 SAN MATEO	ESE 1/2 - 1 (0.565 mi.)	AJ672	646
REMMERS D SON Facility Id: FA0017028	833 SAN MATEO	ESE 1/2 - 1 (0.576 mi.)	AJ677	652
K&B PRODUCTS Facility Id: FA0010886	863 WOODSIDE	E 1/2 - 1 (0.582 mi.)	AN682	667
AUTOPLUS Facility Id: FA0045421 Facility Id: FA0059717	823 SAN MATEO	ESE 1/2 - 1 (0.594 mi.)	AO686	670
BURLINGAME SAAB Facility Id: FA0001693	825 SAN MATEO	ESE 1/2 - 1 (0.596 mi.)	AO687	670
BROSNAN, JOHN Facility Id: FA0025649	760 OCCIDENTAL	S 1/2 - 1 (0.603 mi.)	690	672
SHEN INFINITY Facility Id: FA0012849	***800 N SAN MATEO DR***	***ESE 1/2 - 1 (0.611 mi.)***	***AO691***	***672***
DICK GREGORY, D.D.S. Facility Id: FA0026542	720 EL CAMINO REAL	SE 1/2 - 1 (0.622 mi.)	693	678
ALL TUNE & LUBE Facility Id: FA0013808 Facility Id: FA0027007	801 SAN MATEO	ESE 1/2 - 1 (0.633 mi.)	AO696	679
MALCOLM PROPERTY Facility Id: FA0013829	***625 HURLINGHAM***	***SSE 1/2 - 1 (0.641 mi.)***	***AP697***	***679***
VERACOM MITSUBISHI Facility Id: FA0015102 Facility Id: FA0036925	***790 SAN MATEO***	***ESE 1/2 - 1 (0.647 mi.)***	***AO700***	***684***
AUTO WORKS Facility Id: FA0016464 Facility Id: FA0017023	***815 WOODSIDE***	***ESE 1/2 - 1 (0.653 mi.)***	***AN707***	***692***
INTERSTATE FLORAL CO Facility Id: FA0007021	***801 WOODSIDE***	***ESE 1/2 - 1 (0.686 mi.)***	***AR716***	***700***
STROMBERG, LOUISE Facility Id: FA0026623	617 CRESCENT	SSE 1/2 - 1 (0.695 mi.)	724	712
COMMERCIAL PROPERTY Facility Id: FA0014884	716 SAN MATEO	ESE 1/2 - 1 (0.698 mi.)	AU727	713
MA'S AUTO REPAIR & S Facility Id: FA0037691 Facility Id: FA0040785 Facility Id: FA0055820	704 SAN MATEO	ESE 1/2 - 1 (0.705 mi.)	AU732	715
MARTIN AUTO COLOR IN Facility Id: FA0055486	***305 VILLA TERRACE***	***ESE 1/2 - 1 (0.710 mi.)***	***AU733***	***716***
RESIDENCE	***632 OCCIDENTAL***	***S 1/2 - 1 (0.745 mi.)***	***AX754***	***742***

Lower Elevation	Address	Direction / Distance	Map ID	Page
Facility Id: FA0016358				
PENINSULA CAR CARE Facility Id: FA0037692	717 WOODSIDE	ESE 1/2 - 1 (0.749 mi.)	AR757	745
UST SITE Facility Id: FA0024618	361 CALIFORNIA	NE 0 - 1/8 (0.071 mi.)	A16	21
UST SITE Facility Id: FA0051675	361 CALIFORNIA	NE 0 - 1/8 (0.071 mi.)	A18	22
UST SITE Facility Id: FA0051083	401 CALIFORNIA	N 0 - 1/8 (0.073 mi.)	A26	25
UST SITE Facility Id: FA0051084	401 CALIFORNIA	N 0 - 1/8 (0.073 mi.)	A28	27
CTY OF SAN MATEO Facility Id: FA0054565	***501 PRIMROSE RD***	***W 0 - 1/8 (0.116 mi.)***	***E80***	***73***
BURLINGAME ONE HOUR Facility Id: FA0052736	***507 CALIFORNIA***	***NNW 1/8 - 1/4 (0.140 mi.)***	***F120***	***127***
BURLINGAME ONE HOUR Facility Id: FA0018022	507 CALIFORNIA	NNW 1/8 - 1/4 (0.140 mi.)	F121	127
BURLINGAME HIGH SCHO Facility Id: FA0000060	1 MANGINI	NNW 1/8 - 1/4 (0.164 mi.)	D139	146
ARLINGTON APARTMENTS Facility Id: FA0043363	***1401 FLORIBUNDA***	***W 1/8 - 1/4 (0.180 mi.)***	***E157***	***160***
SHELL Facility Id: FA0059026	***601 CALIFORNIA***	***NW 1/8 - 1/4 (0.194 mi.)***	***F211***	***229***
BURLINGAME VALERO Facility Id: FA0018003	601 CALIFORNIA	NW 1/8 - 1/4 (0.194 mi.)	F213	230
UST SITE Facility Id: FA0046818	1021 BURLINGAME	ENE 1/8 - 1/4 (0.203 mi.)	J232	252
BURLINGAME DIAGNOSTI Facility Id: FA0016125	270 EAST	E 1/8 - 1/4 (0.211 mi.)	I237	257
D&R AUTO BODY & PAIN Facility Id: FA0012242	270 EAST	E 1/8 - 1/4 (0.211 mi.)	I240	260
SILVER AUTO SVC Facility Id: FA0012240	270 EAST	E 1/8 - 1/4 (0.211 mi.)	I241	260
FOUR CAR GARAGE INC Facility Id: FA0007603	609 CALIFORNIA	NW 1/8 - 1/4 (0.218 mi.)	F259	273
RUPPELS AUTO FIXATIO Facility Id: FA0050716	260 EAST	E 1/8 - 1/4 (0.219 mi.)	I269	283
RUPPELS AUTO FIXATIO Facility Id: FA0018024	260 EAST	E 1/8 - 1/4 (0.219 mi.)	I270	283
AUTO TIGER Facility Id: FA0022465	621 CALIFORNIA	NW 1/8 - 1/4 (0.235 mi.)	M309	330
PENINSULA PRIME MOTO Facility Id: FA0038617	621 CALIFORNIA	NW 1/8 - 1/4 (0.235 mi.)	M311	331
BURLINGAME PRIME MOT	621 CALIFORNIA	NW 1/8 - 1/4 (0.235 mi.)	M312	331

Facility Id: FA0058084 Facility Id: FA0028258				
CALIFORNIA DRIVE AUT Facility Id: FA0025639	621 CALIFORNIA	NW 1/8 - 1/4 (0.235 mi.)	M314	333
T MOBILE SITE ID SF5 Facility Id: FA0049056	850 BURLINGAME	NE 1/8 - 1/4 (0.240 mi.)	319	337
ALL MAKES AUTO BODY Facility Id: FA0010115	257 MYRTLE	ENE 1/8 - 1/4 (0.250 mi.)	J333	346
A & I CUSTOMS Facility Id: FA0016140	255 MYRTLE	ENE 1/4 - 1/2 (0.251 mi.)	J336	353
2M AUTOMOTIVE Facility Id: FA0040750	255 MYRTLE	ENE 1/4 - 1/2 (0.251 mi.)	J341	358
MIKE HARVEY ACURA AU Facility Id: FA0027657	212 LANE	E 1/4 - 1/2 (0.258 mi.)	I355	369
OLDE ENGLISH GARAGE Facility Id: FA0018048	988 HOWARD	E 1/4 - 1/2 (0.275 mi.)	P369	379
RICKS SERVICE Facility Id: FA0018010	988 HOWARD	E 1/4 - 1/2 (0.275 mi.)	P373	382
NEW DATSONVILLE Facility Id: FA0018023	927 HOWARD	E 1/4 - 1/2 (0.305 mi.)	P396	399
BLUE RIBBON CLEANERS Facility Id: FA0027971	741 CALIFORNIA	NW 1/4 - 1/2 (0.311 mi.)	M406	407
BLUE RIBBON CLEANERS Facility Id: FA0040425	741 CALIFORNIA	NW 1/4 - 1/2 (0.311 mi.)	M407	407
BLUE RIBBON CLEANERS Facility Id: FA0058098 Facility Id: FA0007269	***741 CALIFORNIA***	***NW 1/4 - 1/2 (0.311 mi.)***	***M413***	***414***
FLOYDS AUTOMOTIVE Facility Id: FA0022880	741 SAN MATEO	NW 1/4 - 1/2 (0.315 mi.)	M425	432
CALIFORNIA AUTO CENT Facility Id: FA0025641	751 CALIFORNIA	NW 1/4 - 1/2 (0.326 mi.)	M430	435
FLOYDS AUTO REPAIR Facility Id: FA0007267	751 CALIFORNIA	NW 1/4 - 1/2 (0.326 mi.)	M434	439
NICKS HONDA / ACURA Facility Id: FA0038835	***775 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.351 mi.)***	***W465***	***465***
SHAFFERS AUTO SERVIC Facility Id: FA0012292	777 CALIFORNIA	NW 1/4 - 1/2 (0.353 mi.)	W476	473
GRAYS PAINT Facility Id: FA0045272	783 CALIFORNIA	NW 1/4 - 1/2 (0.359 mi.)	W479	475
RESIDENCE Facility Id: FA0023064	746 LAUREL	NNW 1/4 - 1/2 (0.370 mi.)	U483	477
BURLINGAME FIRE DEPT Facility Id: FA0014319	799 CALIFORNIA	NW 1/4 - 1/2 (0.376 mi.)	W501	494
BURLINGAME FIRE DEPT Facility Id: FA0054555 Facility Id: FA0059890	***799 CALIFORNIA***	***NW 1/4 - 1/2 (0.376 mi.)***	***W502***	***494***
RESIDENCE	732 LEXINGTON	NE 1/4 - 1/2 (0.392 mi.)	Z507	498

Facility Id: FA0024735				
CHILTON AUTO BODY (B Facility Id: FA0055544 Facility Id: FA0026641	925 BAYSWATER	E 1/4 - 1/2 (0.415 mi.)	AC550	532
RESIDENCE Facility Id: FA0014606	1112 PALM	NW 1/4 - 1/2 (0.434 mi.)	W574	552
ANTOSIK, EDWIN Facility Id: FA0026863	701 HOWARD	ENE 1/4 - 1/2 (0.470 mi.)	AB602	573
T MOBILE WEST CORP S Facility Id: FA0045344	777 MORRELL	NNW 1/2 - 1 (0.516 mi.)	AF659	633
PENINSULA SHELL Facility Id: FA0016933 Facility Id: FA0046138 Facility Id: FA0056158	***400 PENINSULA AVE***	***E 1/2 - 1 (0.582 mi.)***	***AN680***	***653***
SUNNY AUTO BODY Facility Id: FA0055204 Facility Id: FA0007253	903 CALIFORNIA	NW 1/2 - 1 (0.653 mi.)	AQ706	692
AUTOHAUS EXEC Facility Id: FA0022914	909 CALIFORNIA	NW 1/2 - 1 (0.660 mi.)	AQ709	696
MULTI CRAFT AUTO BOD Facility Id: FA0018029	917 CALIFORNIA	NW 1/2 - 1 (0.670 mi.)	AQ710	696
MULTI CRAFT AUTO BOD Facility Id: FA0038679	917 CALIFORNIA	NW 1/2 - 1 (0.670 mi.)	AQ711	697
ANCHOR BODY & DETAIL Facility Id: FA0013201	1008 CAROLAN	NW 1/2 - 1 (0.672 mi.)	AQ713	698
ADVANCE AUTOMOTIVE Facility Id: FA0007251	921 CALIFORNIA	NW 1/2 - 1 (0.674 mi.)	AQ714	699
ARTISAN MOTORS Facility Id: FA0025278	921 CALIFORNIA	NW 1/2 - 1 (0.674 mi.)	AQ715	699
CITY OF BURLINGAME Facility Id: FA0054562	***399 ROLLINS ROAD***	***NE 1/2 - 1 (0.688 mi.)***	***717***	***701***
BURLINGAME SUBARU Facility Id: FA0009394	1020 CAROLAN	NW 1/2 - 1 (0.689 mi.)	AQ718	704
ANZA PARKING Facility Id: FA0017965	***615 AIRPORT BLVD***	***NNE 1/2 - 1 (0.693 mi.)***	***AS721***	***707***
7 ELEVEN Facility Id: FA0055290	***975 ROLLINS RD***	***NW 1/2 - 1 (0.693 mi.)***	***AT722***	***710***
RESIDENCE Facility Id: FA0022988	215 CHANNING	ENE 1/2 - 1 (0.697 mi.)	725	712
TOPLINE AUTOMOBILE I Facility Id: FA0027671	1028 CAROLAN	NW 1/2 - 1 (0.701 mi.)	AQ728	713
CAMMISA MOTOR CAR CO Facility Id: FA0012192	1028 CAROLAN	NW 1/2 - 1 (0.701 mi.)	AQ729	713
BAY CITIES COLLISION Facility Id: FA0026440	1028 CAROLAN	NW 1/2 - 1 (0.701 mi.)	AQ730	714
SHERATON GATEWAY HOT Facility Id: FA0011654	600 AIRPORT	NNE 1/2 - 1 (0.717 mi.)	AS735	718
HILTON SAN FRANCISCO	600 AIRPORT	NNE 1/2 - 1 (0.717 mi.)	AS736	718

Facility Id: FA0008100				
BAY PARK PLAZA Facility Id: FA0038430	577/555 AIRPORT	NNE 1/2 - 1 (0.724 mi.)	AV737	718
HUDSON BAY PARK PLAZ Facility Id: FA0058246	555/577 AIRPORT	NNE 1/2 - 1 (0.724 mi.)	AV738	719
VIRGIN AMERICA INC Facility Id: FA0037458	555 AIRPORT	NNE 1/2 - 1 (0.725 mi.)	AS739	719
CHEVRON STATION Facility Id: FA0016907	***880 DELAWARE***	***E 1/2 - 1 (0.727 mi.)***	***AW741***	***722***
MIKE HARVEY TOYOTA Facility Id: FA0002803	1007 ROLLINS	NW 1/2 - 1 (0.734 mi.)	AT747	735
FOUR CAR GARAGE INC Facility Id: FA0058402 Facility Id: FA0014608	1007 ROLLINS	NW 1/2 - 1 (0.734 mi.)	AT748	736
PETCO #5313 Facility Id: FA0054807	866 DELAWARE	E 1/2 - 1 (0.736 mi.)	AW749	736
CALBAY Facility Id: FA0045009	***1009 ROLLINS ROAD***	***NW 1/2 - 1 (0.737 mi.)***	***AT750***	***737***
SAFEWAY 0694 Facility Id: FA0001582	860 DELAWARE	E 1/2 - 1 (0.739 mi.)	AW751	738
HOLIDAY CLEANERS Facility Id: FA0005322 Facility Id: FA0058159	***850 DELAWARE***	***E 1/2 - 1 (0.745 mi.)***	***AW753***	***741***
ANCHOR DETAILING Facility Id: FA0060083	***1008 CAROLAN AVE STE***	***NW 1/2 - 1 (0.745 mi.)***	***AT755***	***743***
BAY CITIES COLLISION Facility Id: FA0014863	1017 ROLLINS	NW 1/2 - 1 (0.748 mi.)	AT756	745

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 03/28/2016 has revealed that there is 1 Cortese site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HILLSBOROUGH FIRE DE	***1600 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG586***	***559***

DRYCLEANERS: A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners' agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

A review of the DRYCLEANERS list, as provided by EDR, and dated 02/08/2016 has revealed that there are 7 DRYCLEANERS sites within approximately 0.75 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PRIMROSE CLEANERS	339 PRIMROSE RD	SSW 0 - 1/8 (0.083 mi.)	A45	36

EPA Id: CAL000343005				
CAINE CLEANERS EPA Id: CAL000017479	1321 HOWARD	SSE 1/8 - 1/4 (0.189 mi.)	G196	212
STERLING CLEANERS EPA Id: CAL000215134	***1140 HOWARD AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G205***	***221***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME ONE HOUR EPA Id: CAL000381651	***507 CALIFORNIA***	***NNW 1/8 - 1/4 (0.140 mi.)***	***F120***	***127***
BURLINGAME ONE HOUR EPA Id: CAD981171382	507 CALIFORNIA DR	NNW 1/8 - 1/4 (0.140 mi.)	F122	128
BLUE RIBBON CLEANERS EPA Id: CAL000277436 EPA Id: CAL000335309	***741 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.311 mi.)***	***M409***	***409***
BLUE RIBBON CLEANERS EPA Id: CAL000401706	***741 CALIFORNIA***	***NW 1/4 - 1/2 (0.311 mi.)***	***M413***	***414***

EMI: Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies

A review of the EMI list, as provided by EDR, and dated 12/31/2014 has revealed that there are 35 EMI sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAMMISA MOTOR CAR CO Facility Id: 3536	321 CALIFORNIA DRIVE	ENE 0 - 1/8 (0.081 mi.)	A41	33
PRIMROSE CLEANERS Facility Id: 8628 Facility Id: 4352	***339 PRIMROSE ROAD***	***SSW 0 - 1/8 (0.083 mi.)***	***A46***	***37***
HARRIS & CRISAFI C/O Facility Id: 16013	1205 HOWARD AVENUE	ESE 0 - 1/8 (0.085 mi.)	A55	48
200 PARK RD COMPANY Facility Id: 22688 Facility Id: 21444	***200 PARK RD***	***SE 1/8 - 1/4 (0.180 mi.)***	***G160***	***162***
HARRIS & CRISAFI C/O Facility Id: 10105	***1234 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.182 mi.)***	***G169***	***168***
HARRIS-CRISAFI CLEAN Facility Id: 17222	1234 HOWARD AVENUE	SE 1/8 - 1/4 (0.182 mi.)	G174	179
SHAFFER PROPERTY TRU Facility Id: 11731	1200 HOWARD AVENUE	SE 1/8 - 1/4 (0.185 mi.)	G180	191
STANLEY LO (GREEN BA Facility Id: 20929	***1319 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G186***	***197***
CAINES CLEANERS Facility Id: 1139	***1321 HOWARD AVENUE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G192***	***205***
HARRIS-CRISAFI CLEAN Facility Id: 17224	1209 HOWARD AVENUE	SE 1/8 - 1/4 (0.191 mi.)	G200	215
STERLING CLEANERS, I	1140 HOWARD AVENUE	ESE 1/8 - 1/4 (0.191 mi.)	G206	224

Facility Id: 419				
HARRIS-CRISAFI CLEAN Facility Id: 17223	1201 HOWARD AVENUE	SE 1/8 - 1/4 (0.192 mi.)	G209	227
PACIFIC BELL Facility Id: 13454	1480 BURLINGAME AVEN	SSW 1/8 - 1/4 (0.198 mi.)	H222	241
SHELL OIL COMPANY C/ Facility Id: 8608	1490 BURLINGAME AVEN	SSW 1/8 - 1/4 (0.216 mi.)	H250	268
PUTNAM AUTOMOTIVE Facility Id: 14911	198 CALIFORNIA DRIVE	E 1/8 - 1/4 (0.230 mi.)	I305	323
HARRIS & CRISAFI C/O Facility Id: 16014	137 LORTON AVENUE	SE 1/8 - 1/4 (0.238 mi.)	I316	334
BURLINGAME COLLISION Facility Id: 9867 Facility Id: 4900	***123 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.315 mi.)***	***S421***	***421***
BURLINGAME FORD Facility Id: 5036	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
PUTNAM AUTOMOTIVE Facility Id: 14912	100 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.347 mi.)	S458	459
PUTNAM AUTOMOTIVE Facility Id: 14914	65 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.397 mi.)	S515	502
PUTNAM AUTOMOTIVE Facility Id: 14910	50 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.414 mi.)	S543	523
PUTNAM MAZDA Facility Id: 3812	3 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.471 mi.)	AD607	574
PUTNAM AUTOMOTIVE Facility Id: 14915	2 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.474 mi.)	AJ631	609
PUTNAM AUTOMOTIVE Facility Id: 14913 Facility Id: 3817	900 PENINSULA AVENUE	ESE 1/4 - 1/2 (0.498 mi.)	AJ648	622

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CITY OF BURLINGAME Facility Id: 14468	425 CAROLAN AVENUE	NNE 0 - 1/8 (0.110 mi.)	D72	63
CITY OF BURLINGAME Facility Id: 14474	501 PRIMROSE ROAD	W 0 - 1/8 (0.116 mi.)	E82	74
BURLINGAME ONE HOUR Facility Id: 5283 Facility Id: 270	507 CALIFORNIA DRIVE	NNW 1/8 - 1/4 (0.140 mi.)	F123	128
D & R AUTO BODY AND Facility Id: 7071	270 EAST LANE, #2	E 1/8 - 1/4 (0.211 mi.)	I242	261
ALL MAKES AUTO BODY Facility Id: 8582	***257 MYRTLE ROAD***	***ENE 1/8 - 1/4 (0.250 mi.)***	***J335***	***348***
UNITED AUTO COLLISIO Facility Id: 9012	***255 MYRTLE ROAD***	***ENE 1/4 - 1/2 (0.251 mi.)***	***J338***	***354***
I&M AUTO BODY & PAIN Facility Id: 6033	255 MYRTLE ROAD #6	ENE 1/4 - 1/2 (0.251 mi.)	J340	358
MIKE HARVEY HONDA	212 EAST LANE	E 1/4 - 1/2 (0.258 mi.)	I354	367

Facility Id: 12305				
GEORGES HOLIDAY CLEA Facility Id: 14937	741 CALIFORNIA DRIVE	NW 1/4 - 1/2 (0.311 mi.)	M408	408
CITY OF BURLINGAME Facility Id: 14463	799 CALIFORNIA DRIVE	NW 1/4 - 1/2 (0.376 mi.)	W498	490
CHILTON AUTO BODY (S Facility Id: 3817 Facility Id: 22369	925 BAYSWATER STREET	E 1/4 - 1/2 (0.415 mi.)	AC552	533

ENF: A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

A review of the ENF list, as provided by EDR, and dated 05/25/2016 has revealed that there is 1 ENF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
TOWN OF HILLSBOROUGH Status: Historical Status: Active Facility Id: 630900	***1600 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG589***	***562***

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency. This database begins with calendar year 1993.

A review of the HAZNET list, as provided by EDR, and dated 12/31/2014 has revealed that there are 239 HAZNET sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CITY BURLINGAME/PUB GEPAID: CAC001109280	1230 DONNELLY AVE	0 - 1/8 (0.000 mi.)	A2	8
MIKE'S AUTOMOTIVE SE GEPAID: CAL000015688	1212 DONNELLY AVENUE	ENE 0 - 1/8 (0.022 mi.)	A3	9
KIRKBRIDE PROPERTIES GEPAID: CAC001146992	307 LORTON AVE	E 0 - 1/8 (0.058 mi.)	A11	15
RODGER REINHART LESL GEPAID: CAC002625227	1241 BURLINGAME AVE	ESE 0 - 1/8 (0.070 mi.)	A15	20
ANN TAYLOR S0497/BUR GEPAID: CAC002629432	1325 BURLINGAME AVE	SSE 0 - 1/8 (0.071 mi.)	A20	22
KIRKBRIDE PROPERTIES GEPAID: CAC001166456	1202 BURLINGAME AVE	ESE 0 - 1/8 (0.071 mi.)	A21	23
CITY NATIONAL BANK GEPAID: CAC002192353	350 PRIMROSE RD	SW 0 - 1/8 (0.074 mi.)	A29	27
KARP FAMILY TRUST	1209 BURLINGAME	ESE 0 - 1/8 (0.075 mi.)	A32	28

GEPAID: CAC002549947				
AW DEVELOPMENT INC GEPAID: CAC002667952	330 PRIMROSE RD STE	SSW 0 - 1/8 (0.079 mi.)	A33	28
MIKE WOODS GEPAID: CAC001168984	330 PRIMROSE RD	SSW 0 - 1/8 (0.079 mi.)	A34	29
AVTAR JOHAL FAMILY & GEPAID: CAC002560076	1301 BURLINGAME AVE	SSE 0 - 1/8 (0.081 mi.)	A37	30
R & B EQUIPMENT GEPAID: CAC002561465	1301 BURLINGAME AVE	SSE 0 - 1/8 (0.081 mi.)	A39	31
CAMMISSA MOTOR CAR C GEPAID: CAL000029239	321 CALIFORNIA DR	ENE 0 - 1/8 (0.081 mi.)	A40	32
GOLDEN STATE BREWING GEPAID: CAC000926824	321 CALIFORNIA AVENU	ENE 0 - 1/8 (0.081 mi.)	A42	34
PRIMROSE CLEANERS GEPAID: CAL000343005	339 PRIMROSE RD	SSW 0 - 1/8 (0.083 mi.)	A44	35
NEW GATES GLOBE CLEA GEPAID: CAL000026929	339 PRIMROSE ROAD	SSW 0 - 1/8 (0.083 mi.)	A48	43
GATES GLOBE CLEANERS GEPAID: CAL000013474	339 PRIMROSE RD	SSW 0 - 1/8 (0.083 mi.)	A49	44
GW WILLIAMS COMPANY GEPAID: CAC001389640	329 PRIMROSE RD	SSW 0 - 1/8 (0.084 mi.)	A50	45
WOODSTOCK-BOWERS LLC GEPAID: CAC002701480	329 PRIMROSE RD	SSW 0 - 1/8 (0.084 mi.)	A51	46
KARP FAMILY TRUST GEPAID: CAC002563355	1205 BURLINGAME AVE/	ESE 0 - 1/8 (0.085 mi.)	A57	51
SEPHORA STORE 52 BUR GEPAID: CAR000147256	1205 BURLINGAME AVE	ESE 0 - 1/8 (0.085 mi.)	A59	52
AVENUE PLAZA GEPAID: CAC001169864	1110 BURLINGAME AVE	E 0 - 1/8 (0.094 mi.)	B61	55
AVENUE PLAZA GEPAID: CAC001166480	1110 BURLINGAME AVE	E 0 - 1/8 (0.094 mi.)	B62	56
LW DESIGN HAIR SALON GEPAID: CAC002631696	309 PRIMROSE RD	SSW 0 - 1/8 (0.097 mi.)	C63	56
88 PHOTO LAB GEPAID: CAL930225842	1109 BURLINGAME AVEN	E 0 - 1/8 (0.099 mi.)	B66	58
HAAG N HAAG GEPAID: CAL000130501	1402 BURLINGAME AVEN	SSW 0 - 1/8 (0.101 mi.)	C68	60
JOSEPH KARP GEPAID: CAC001446088	1411 CHAPIN AVE	SW 0 - 1/8 (0.101 mi.)	C69	62
EDWARD ZUKAUSKAS GEPAID: CAC002709300	1410 BURLINGAME AVE	SSW 0 - 1/8 (0.110 mi.)	C70	62
LINO NICCOLI GEPAID: CAC002694334	277 PRIMROSE RD	S 0 - 1/8 (0.113 mi.)	C75	70
WELLS FARGO BANK GEPAID: CAC000712560	261 PARK ROAD	SSE 0 - 1/8 (0.117 mi.)	C94	111
BLUE CHALK CAFE	1100 BURLINGAME AVE	E 0 - 1/8 (0.118 mi.)	B95	111

GEPAID: CAC001140352				
LINO NICCOLI GEPAID: CAC002551348	269 PRIMROSE RD	S 0 - 1/8 (0.119 mi.)	C97	112
US POSTAL SERVICE GEPAID: CAC002582582	220 PARK RD	SE 0 - 1/8 (0.119 mi.)	B104	116
US POSTAL SERVICE GEPAID: CAC001386560	220 PARK RD	SE 0 - 1/8 (0.119 mi.)	B106	117
1X U. S. POSTAL SERV GEPAID: CAC000956136	220 PARK ROAD	SE 0 - 1/8 (0.119 mi.)	B107	119
PENINSULA CORRIDOR J GEPAID: CAC002642629	290 CALIFORNIA DR	ENE 0 - 1/8 (0.120 mi.)	B109	120
CALTRAIN GEPAID: CAC002632809	290 CALIFORNIA DR	ENE 0 - 1/8 (0.120 mi.)	B110	120
CITY OF BURLINGAME GEPAID: CAC002726090	1415 BURLINGAME AVE	SSW 0 - 1/8 (0.120 mi.)	C111	121
LINO NICCOLI GEPAID: CAC002766594	257 PRIMROSE RD	S 1/8 - 1/4 (0.127 mi.)	C116	124
JP MORGAN CHASE - BU GEPAID: CAC002710896	1430 CHAPIN AVE	SW 1/8 - 1/4 (0.137 mi.)	C119	126
CARR MCLELLAN GEPAID: CAC002310089	216 PARK AVE	SE 1/8 - 1/4 (0.147 mi.)	G127	136
WELLS FARGO BANK GEPAID: CAC002706277	1435 BURLINGAME AVE	SSW 1/8 - 1/4 (0.147 mi.)	C128	136
GERMAN CAR CARE GEPAID: CAL000379554	251 CALIFORNIA DR	E 1/8 - 1/4 (0.150 mi.)	B134	141
AUTO MOBILE CARE GEPAID: CAL000115987	251 CALIFORNIA DR	E 1/8 - 1/4 (0.154 mi.)	B137	144
CHRISTIE'S GEPAID: CAC001417624	240 HATCH LANE	ESE 1/8 - 1/4 (0.156 mi.)	B138	145
A J A INVESTMENTS, L GEPAID: CAC001486552	222 CALIFORNIA DR	E 1/8 - 1/4 (0.167 mi.)	B145	151
FEDERAL AUTO PARTS GEPAID: CAL913235870	231 CALIFORNIA DR	E 1/8 - 1/4 (0.170 mi.)	B150	157
DEWEY LAND COMPANY, GEPAID: CAC002744728	1450 CHAPIN AVE	SW 1/8 - 1/4 (0.172 mi.)	H152	157
210 PRIMROSE LLC GEPAID: CAC002709747	210 PRIMROSE RD	SSE 1/8 - 1/4 (0.180 mi.)	G159	162
200 PARK RD COMPANY GEPAID: CAC002703041	***200 PARK RD***	***SE 1/8 - 1/4 (0.180 mi.)***	***G160***	***162***
BRIAN KELLEHER GEPAID: CAC002289577	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G164	166
CHRISASI HARRIS TRUS GEPAID: CAC002197025	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G165	166
CHRISAFI/HARRIS TRUS GEPAID: CAL000290514	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G170	170
CHRISAFI/HARRIS TRUS	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G171	171

GEPAID: CAC002556147				
NORMAN HARRIS GEPAID: CAC001400272	1234 HOWARD AVENUE	SE 1/8 - 1/4 (0.182 mi.)	G172	172
CHRISAFI/HARRIS TRUS GEPAID: CAC002574154	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G175	181
SHAFFER PROPERTY TRU GEPAID: CAL000293133	1200 HOWARD AVE	SE 1/8 - 1/4 (0.185 mi.)	G179	189
GRAY'S PAINT GEPAID: CAL000226366	1166 HOWARD AVE	ESE 1/8 - 1/4 (0.188 mi.)	G183	195
GRAYS PAINTING GEPAID: CAC002358415	1166 HOWARD AVE	ESE 1/8 - 1/4 (0.188 mi.)	G184	196
STANLEY LO (GREEN BA GEPAID: CAC002613377	***1319 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G186***	***197***
BERENSTEIN ASSOC. PR GEPAID: CAR000233643	***1319 HOWARD***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G187***	***199***
CAINES CLEANERS GEPAID: CAD981631831	***1321 HOWARD AVENUE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G192***	***205***
STANLEY LO/GREENBANK GEPAID: CAC002599320	1321 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G194	211
CAINE CLEANERS GEPAID: CAL000017479	1321 HOWARD	SSE 1/8 - 1/4 (0.189 mi.)	G197	212
STERLING CLEANERS IN GEPAID: CAL000215134	1140 HOWARD AVE	ESE 1/8 - 1/4 (0.191 mi.)	G202	217
STERLING CLEANERS GEPAID: CAD981632094	***1140 HOWARD AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G205***	***221***
SHAFER PROPERTY TRUS GEPAID: CAC002556158	1201 HOWARD AVE	SE 1/8 - 1/4 (0.192 mi.)	G207	226
BRIAN KELLEHER GEPAID: CAC002311569	1201 HOWARD AVE	SE 1/8 - 1/4 (0.192 mi.)	G208	226
PACIFIC BELL TELEPHO GEPAID: CAT080022270	1480 BURLINGAME AVE	SSW 1/8 - 1/4 (0.198 mi.)	H224	244
JEWELL PARTNERS LP GEPAID: CAC002662352	217 HIGHLAND AVE	ESE 1/8 - 1/4 (0.203 mi.)	I231	252
WALGREENS #0086 GEPAID: CAR000049866	1420 HOWARD AVE	S 1/8 - 1/4 (0.203 mi.)	G233	252
1X BURLINGAME BUS DE GEPAID: CAC000796032	1080 HOWARD AVE	ESE 1/8 - 1/4 (0.215 mi.)	I245	263
MOLLIE STONES MARKET GEPAID: CAC001484952	1477 CHAPIN AVE	SW 1/8 - 1/4 (0.217 mi.)	H254	270
LINDA GRIMES GEPAID: CAC002654964	1101 HOWARD AVE # 11	ESE 1/8 - 1/4 (0.217 mi.)	I255	271
1X BANK OF THE WEST GEPAID: CAC000790672	149 PARK RD	SE 1/8 - 1/4 (0.218 mi.)	G257	272
SAFEWAY STORE #948/1 GEPAID: CAL000353509 GEPAID: CAC002585657	1450 HOWARD AVE	S 1/8 - 1/4 (0.219 mi.)	K263	277
CHEVRON STATION 9057	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K284	295

GEPAID: CAR000116699				
WALGREENS #12257 GEPAID: CAL000352316	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K286	307
CHEVRON 90571 GEPAID: CAL000029692	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K287	309
CURRIES CHEVRON SERV GEPAID: CAL000122545	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K288	311
SZTO & ASSOCIATES GEPAID: CAC002577719	1443 HOWARD AVE	S 1/8 - 1/4 (0.223 mi.)	K290	313
MWE HARVEY CHRYSLER GEPAID: CAL000049077	***200 CALIFORNIA DRIVE***	***E 1/8 - 1/4 (0.227 mi.)***	***I292***	***314***
MAURICE APTS GEPAID: CAC002456159	255 EL CAMINO REAL 2	SSW 1/8 - 1/4 (0.228 mi.)	K294	317
SATURN OF BURLINGAME GEPAID: CAD983606716	198 CALIFORNIA DR	E 1/8 - 1/4 (0.230 mi.)	I299	320
OKI OHATA GEPAID: CAC002602300	1500 BURLINGAME AVE	SSW 1/8 - 1/4 (0.233 mi.)	H307	328
ST CATHERINES CHURCH GEPAID: CAC000873680	121 PARK RD	SE 1/8 - 1/4 (0.239 mi.)	G318	337
CHEVRON STORE #90364 GEPAID: CAC002607181	177 CALIFORNIA DR	ESE 1/8 - 1/4 (0.248 mi.)	I330	344
ST PAUL EPISCOPAL CH GEPAID: CAC002685468	415 EL CAMINO REAL	SW 1/4 - 1/2 (0.268 mi.)	H363	375
ST PAULS EPISCOPAL C GEPAID: CAC002246089	415 EL CAMINO REAL	SW 1/4 - 1/2 (0.268 mi.)	H364	376
BURT BERENSTEIN GEPAID: CAC002785056	110 PARK ROAD #206	SE 1/4 - 1/2 (0.269 mi.)	N365	376
DAVE TOWNSEND GEPAID: CAC002670998	110 PARK RD APT 601	SE 1/4 - 1/2 (0.269 mi.)	N366	377
BURLINGAME TOWERS GEPAID: CAL000206240	1469 BELLEVUE AVE	WSW 1/4 - 1/2 (0.272 mi.)	O367	377
BURLINGAME TOWERS GEPAID: CAC002681309 GEPAID: CAC002739397	1469 BELLEVUE AVE.	WSW 1/4 - 1/2 (0.272 mi.)	O368	378
FLORIBUNDA HOA GEPAID: CAC002606820	1477 FLORIBUNDA AVE	W 1/4 - 1/2 (0.277 mi.)	L381	389
RAPHEL AGUIRRE GEPAID: CAC002658423	525 ALMER RD APT 302	WSW 1/4 - 1/2 (0.282 mi.)	L382	390
JAMIE RICE GEPAID: CAC002695530	525 ALMER RD APT 101	WSW 1/4 - 1/2 (0.282 mi.)	L383	390
NORMAN GOLDAU GEPAID: CAC001270792	111 LORTON	SE 1/4 - 1/2 (0.283 mi.)	N384	391
DAVID DESJARBAN GEPAID: CAC002622719	1538 BURLINGAME AVE	SSW 1/4 - 1/2 (0.294 mi.)	Q386	393
PACIFIC AUTO REPAIR GEPAID: CAL000036973	124 HIGHLAND AVE	ESE 1/4 - 1/2 (0.295 mi.)	I389	394
ST CATHERINE CATHOLI	1310 BAYSWATER AVE	SSE 1/4 - 1/2 (0.303 mi.)	R392	397

GEPAID: CAC002632579				
ROMAN CATHOLIC ARCHB GEPAID: CAC001430948	1310 BAYSWATER AVE	SSE 1/4 - 1/2 (0.303 mi.)	R393	397
NOEL L MILLER INC GEPAID: CAD982038754	129 CALIFORNIA DR	ESE 1/4 - 1/2 (0.306 mi.)	I398	400
CAMINO REAL PET CLIN GEPAID: CAL923054441	1317 BAYSWATER AVE	SSE 1/4 - 1/2 (0.310 mi.)	R405	405
MONTALVO CORP DBA BU GEPAID: CAL000344253	123 CALIFORNIA DR	ESE 1/4 - 1/2 (0.315 mi.)	S419	419
BURLINGAME COLLISION GEPAID: CAD981417074	***123 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.315 mi.)***	***S421***	***421***
TRAMMEL CROW COMPANY GEPAID: CAC002606788	1531 HOWARD AVE	S 1/4 - 1/2 (0.322 mi.)	V428	433
EVELYN CONDON GEPAID: CAC002755275	1501 CYPRESS AVE	SSE 1/4 - 1/2 (0.322 mi.)	R429	434
KIIKO, OHATA GEPAID: CAC002766354	1537 RALSTON AVE	SSW 1/4 - 1/2 (0.328 mi.)	Q436	440
TOP TOYO LOTUS INC GEPAID: CAC002111728	530 EL CAMINO REAL	WSW 1/4 - 1/2 (0.334 mi.)	O438	441
PUTNAM GM GEPAID: CAL000378374	998 BAYSWATER AVE	ESE 1/4 - 1/2 (0.334 mi.)	S440	442
MAJEL GILMARTIN GEPAID: CAC001137400	48 PARK RD	SE 1/4 - 1/2 (0.345 mi.)	R443	443
BURLINGAME FORD GEPAID: CAD098513096	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
GMAC GEPAID: CAC000732784	100 CALIFORNIA BLVD	ESE 1/4 - 1/2 (0.347 mi.)	S448	452
GMAC GEPAID: CAC001135216	100 CALIFORNIA BLVD	ESE 1/4 - 1/2 (0.347 mi.)	S457	458
BURLINGAME AUTO CLIN GEPAID: CAL000039370	132 MYRTLE RD	E 1/4 - 1/2 (0.351 mi.)	P462	464
BO THORENFIELDT GEPAID: CAC002610438	1512 FLORIBUNDA AVE	W 1/4 - 1/2 (0.357 mi.)	X477	473
JOHN TREADWELL GEPAID: CAC002670332	1540 NEWLANDS AVE	S 1/4 - 1/2 (0.366 mi.)	V480	475
MARION SPADONI GEPAID: CAC002696329	1557 RALSTON AVE	SSW 1/4 - 1/2 (0.371 mi.)	Q488	482
HOWER AUTO REPAIR GEPAID: CAL000006801	920 BAYSWATER ST	ESE 1/4 - 1/2 (0.373 mi.)	S492	484
DAVID CUNNINGHAM GEPAID: CAC002742119	700 ACACIA AVE	W 1/4 - 1/2 (0.375 mi.)	X495	488
MR. M. AFLAK GEPAID: CAC001076976	51 EL CAMINO REAL	SSE 1/4 - 1/2 (0.379 mi.)	R504	497
LAURA GSCHWIND GEPAID: CAC002683364	1553 NEWLANDS AVE	S 1/4 - 1/2 (0.392 mi.)	V508	498
COLE EUROPEAN MOTORS	65 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.394 mi.)	S509	499

GEPAID: CAL000012547				
JOSEPH KELLER GEPAID: CAC001400280	ONE PARK ROAD	SE 1/4 - 1/2 (0.395 mi.)	AA511	500
NICKS HONDA / ACURA GEPAID: CAL000042369	1 PARK RD	SE 1/4 - 1/2 (0.407 mi.)	AA521	509
RRM, INC GEPAID: CAC001434076	1 PARK RD	SE 1/4 - 1/2 (0.407 mi.)	AA525	512
DEBRA GWIN GEPAID: CAC002784839	1529 CAROL AVENUE	SSE 1/4 - 1/2 (0.412 mi.)	AA533	515
PETE ROSSI GEPAID: CAC002327809	20 HIGHLAND AVE	ESE 1/4 - 1/2 (0.413 mi.)	AD535	516
J&M MOTORS INC PUTNA GEPAID: CAL000089519	50 CALIFORNIA DR	ESE 1/4 - 1/2 (0.414 mi.)	S544	525
PUTNAM TOYOTA GEPAID: CAD981368244	50 CALIFORNIA D	ESE 1/4 - 1/2 (0.414 mi.)	S545	526
LARRY PUTMAN & JENNY GEPAID: CAC002759653	1547 CYPRESS AVE	SSE 1/4 - 1/2 (0.415 mi.)	549	531
TONY LEUNG GEPAID: CAC002704336	19 E CAROL AVE	SSE 1/4 - 1/2 (0.427 mi.)	AA557	542
1X MCKINLEY SCHOOL GEPAID: CAC000033522	701 PALOMA AVENUE	W 1/4 - 1/2 (0.429 mi.)	X559	543
MCKINLEY ELEM./BURLI GEPAID: CAC000878232	701 PALOMA AVE	W 1/4 - 1/2 (0.429 mi.)	X561	544
1X MCKINLEY SCHOOL GEPAID: CAC000871632	701 PALOMA AVENUE	W 1/4 - 1/2 (0.429 mi.)	X563	544
BSD- MCKINLEY ELEMEN GEPAID: CAL000376179	701 PALOMA AVE	W 1/4 - 1/2 (0.429 mi.)	X564	545
PHILIP CHAN GEPAID: CAC002709758	15 EL CAMINO REAL	SE 1/4 - 1/2 (0.430 mi.)	AA568	548
RAY SMITH GEPAID: CAC001461928	1615 FLORABUNDA AVE	WSW 1/4 - 1/2 (0.440 mi.)	AG580	556
HILLSBOROUGH FIRE DE GEPAID: CAC000916672	***1600 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG586***	***559***
SUSAN STEFFEN GEPAID: CAC002640146	214 PENINSULA AVE	ESE 1/4 - 1/2 (0.446 mi.)	AD597	571
NICK ROGERS GEPAID: CAC002721395	325 CHAPIN LN	SSW 1/4 - 1/2 (0.449 mi.)	AH598	571
HERMAN HSU GEPAID: CAC002732610	20 SUMMERHOLME PL	WSW 1/4 - 1/2 (0.469 mi.)	AI601	572
PUTNAM MAZDA GEPAID: CAL000015634	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD613	580
BP WEST COAST PRODUC GEPAID: CAL000260681	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD614	581
PUTNAM MAZDA GEPAID: CAD981983356	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD616	584
SHEN LINCOLN MERCURY	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ621	601

GEPAID: CAD073936528				
PUTNAM LINCOLN MERCU GEPAID: CAL000153763	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ627	605
GARY YEUNG GEPAID: CAC002764816	15 SUMMERHOLME PL	WSW 1/4 - 1/2 (0.475 mi.)	AI636	612
JEFF & ADRIENNE SCHU GEPAID: CAC001164984	1715 RALSTON AVE	SSW 1/4 - 1/2 (0.492 mi.)	AH643	620
VERACOM AUTOMOTIVE G GEPAID: CAL000304666	885 N SAN MATEO DR	ESE 1/4 - 1/2 (0.493 mi.)	AJ644	621
PUTNAM BUICK PONTIAC GEPAID: CAD982409344	900 PENINSULA AVE	ESE 1/4 - 1/2 (0.498 mi.)	AJ652	626

Lower Elevation	Address	Direction / Distance	Map ID	Page
DON SABATINI GEPAID: CAC002134305	361 CALIFORNIA DR	NE 0 - 1/8 (0.059 mi.)	A13	18
DON SABATINI GEPAID: CAC001172856	***361 CALIFORNIA DR***	***NE 0 - 1/8 (0.059 mi.)***	***A14***	***19***
SABATINI TRUSTS GEPAID: CAC002695644	361 CALIFORNIA DR	NE 0 - 1/8 (0.071 mi.)	A17	21
401 ALPROP LLC GEPAID: CAC002687510	401 CALIFORNIA DR	N 0 - 1/8 (0.073 mi.)	A27	26
CITY OF BURLINGAME GEPAID: CAC001158096	480 PRIMROSE RD	W 0 - 1/8 (0.088 mi.)	A60	54
JOHN K LEUNG DDS GEPAID: CAL000162042	500 PRIMROSE RD	WNW 0 - 1/8 (0.111 mi.)	E73	66
DR SCOTT HALLSTED GEPAID: CAL000174200	500 PRIMROSE RD	WNW 0 - 1/8 (0.111 mi.)	E74	68
BURLINGAME CITY HALL GEPAID: CAC002617396	501 PRIMROSE RD	W 0 - 1/8 (0.116 mi.)	E76	70
CITY OF BURLINGAME GEPAID: CAC002626525	501 PRIMROSE RD	W 0 - 1/8 (0.116 mi.)	E78	72
CITY OF BURLINGAME GEPAID: CAC002679613	501 PRIMROSE RD	W 0 - 1/8 (0.116 mi.)	E79	72
CTY OF SAN MATEO GEPAID: CAH111000675	***501 PRIMROSE RD***	***W 0 - 1/8 (0.116 mi.)***	***E80***	***73***
CITY OF BURLINGAME GEPAID: CAC002345303	501 PRIMROSE RD	W 0 - 1/8 (0.116 mi.)	E81	73
SAN MATEO UNION HIGH GEPAID: CAL000299728	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D83	77
SAN MATEO UNION HIGH GEPAID: CAC001082416	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D86	106
BURLINGAME HIGH SCHO GEPAID: CAC002570503	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D87	106
SAN MATEO UNION H/S GEPAID: CAC001217784	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D88	107
SAN MATEO UNION HIGH	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D89	108

GEPAID: CAC001438160				
SAN MATEO UNION HIGH GEPAID: CAC001380488	400 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D90	108
BURLINGAME HS GEPAID: CAC002529015	400 CAROLINE AVE	NNE 0 - 1/8 (0.117 mi.)	D91	109
CITY OF BURLINGAME P GEPAID: CAL000094712	420 CAROLAN AVE	NNE 0 - 1/8 (0.117 mi.)	D93	110
JUNE NEWLING GEPAID: CAC002722376	1405 BELLEVUE AVE	W 1/8 - 1/4 (0.128 mi.)	E117	124
SAN MATEO UNION HIGH GEPAID: CAC002566377	1 MANGINI WAY	NNW 1/8 - 1/4 (0.164 mi.)	D140	146
BURLINGAME HIGH SCHO GEPAID: CAC002578338	1 MANGINI WAY	NNW 1/8 - 1/4 (0.164 mi.)	D141	147
BURLINGAME HUGH SCHO GEPAID: CAC002558884	1 MANGINI WAY	NNW 1/8 - 1/4 (0.164 mi.)	D142	148
CRAIG ROGERS GEPAID: CAC001212424	1418 BELLEVUE	W 1/8 - 1/4 (0.165 mi.)	E143	150
CHATEAU APARTMENTS GEPAID: CAC002569610	1422 BELLEVUE AVE	W 1/8 - 1/4 (0.173 mi.)	E153	158
THE ARLINGTON APARTM GEPAID: CAC002643932	***1401 FLORIBUNDA AVE***	***W 1/8 - 1/4 (0.180 mi.)***	***E158***	***161***
BURLINGAME TEXACO GEPAID: CAL000036395	601 CALIFORNIA DR	NW 1/8 - 1/4 (0.194 mi.)	F216	232
D&R AUTO BODY & PAIN GEPAID: CAL920275206	270 EAST LANE #2	E 1/8 - 1/4 (0.211 mi.)	I239	258
G & C AUTO BODY GEPAID: CAL000046827	270 EAST LANE	E 1/8 - 1/4 (0.211 mi.)	I243	262
FOUR CAR GARAGE INC GEPAID: CAL000032270	609 CALIFORNIA DRIVE	NW 1/8 - 1/4 (0.218 mi.)	F258	272
RUPPEL'S AUTO FIXATI GEPAID: CAL000040117	260 EAST LANE	E 1/8 - 1/4 (0.219 mi.)	I267	281
WINDY HILL PV SEVEN, GEPAID: CAC002798077	1415 FLORIBUNDA AVE	W 1/8 - 1/4 (0.229 mi.)	L295	317
DAVID & YVONNE BERNI GEPAID: CAC002695770	1427 FLORIBUNDA AVE	W 1/8 - 1/4 (0.238 mi.)	L317	336
ALL MAKES AUTO BODY GEPAID: CAL912943159	257 MYRTLE ROAD	ENE 1/8 - 1/4 (0.250 mi.)	J334	346
UNITED AUTO COLLISIO GEPAID: CAL000208381	255 MYRTLE ROAD	ENE 1/4 - 1/2 (0.251 mi.)	J339	357
JACK WONG GEPAID: CAC001313056	220 E LANE	E 1/4 - 1/2 (0.251 mi.)	I342	359
BELINDA LIN GEPAID: CAC002697012	1209 OAK GROVE AVE	NW 1/4 - 1/2 (0.254 mi.)	M343	360
MIKE HARVEY HONDA GEPAID: CAL000153481	212 E LANE	E 1/4 - 1/2 (0.258 mi.)	I356	370
RETIREMENT INN OF BU	250 MYRTLE RD	ENE 1/4 - 1/2 (0.259 mi.)	J359	373

GEPAID: CAC002117792				
ATRIA BURLINGAME GEPAID: CAC002708561	250 MYRTLE RD	ENE 1/4 - 1/2 (0.259 mi.)	J360	374
GUS PAROS GEPAID: CAC001477224	1440 FLORI BUNDA AVE	W 1/4 - 1/2 (0.267 mi.)	L362	375
RICK'S SERVICE GEPAID: CAL000139790	988 HOWARD AVE	E 1/4 - 1/2 (0.275 mi.)	P371	381
1X OLD ENGLISH GARAG GEPAID: CAC000940120	988 HOWARD AVE	E 1/4 - 1/2 (0.275 mi.)	P372	382
OLDE ENGLISH GARAGE GEPAID: CAL000014965	988 HOWARD AVE	E 1/4 - 1/2 (0.275 mi.)	P375	385
OLDE ENGLISH GARAGE GEPAID: CAL000039922	988 HOWARD AVE	E 1/4 - 1/2 (0.275 mi.)	P376	386
ROGER & REBECCA EMER GEPAID: CAC002654559	715 CALIFORNIA DR	NW 1/4 - 1/2 (0.275 mi.)	M378	387
THE NEW DATSONVILLE GEPAID: CAL000374202	927 HOWARD AVE	E 1/4 - 1/2 (0.305 mi.)	P394	398
RICHARD SAMUELSON GEPAID: CAC002715539	917 HOWARD AVE.	E 1/4 - 1/2 (0.309 mi.)	P399	402
BLUE RIBBON CLEANERS GEPAID: CAL000277436	741 CALIFORNIA DR	NW 1/4 - 1/2 (0.311 mi.)	M412	412
GEORGE'S HOLIDAY CLE GEPAID: CAL000092918	741 CALIFORNIA DR	NW 1/4 - 1/2 (0.311 mi.)	M414	415
PENINSULA TENNIS CLU GEPAID: CAC002622450	433 CHATHAM RD	NNE 1/4 - 1/2 (0.311 mi.)	T415	417
FLOYD'S AUTO REPAIR GEPAID: CAL000008740	751 CALIFORNIA DR	NW 1/4 - 1/2 (0.326 mi.)	M432	436
GREG TAYLOR GEPAID: CAC002711508	446 CHATHAM RD	NNE 1/4 - 1/2 (0.327 mi.)	T435	439
K & B INVESTMENTS GEPAID: CAC002572272	755 CALIFORNIA ST	NW 1/4 - 1/2 (0.330 mi.)	M437	440
NELSON NG GEPAID: CAC002645088	730 OAK GROVE AVE	N 1/4 - 1/2 (0.334 mi.)	U439	441
JIM SHANNON GEPAID: CAC002740457	744 NEUCHATEL AVE	WNW 1/4 - 1/2 (0.337 mi.)	W441	442
DOUG DIEHL GEPAID: CAC002773869	705 WINCHESTER DR	N 1/4 - 1/2 (0.342 mi.)	U442	443
RICK CORY GEPAID: CAC002707471	730 LAUREL AVE	NNW 1/4 - 1/2 (0.347 mi.)	U459	462
NICKS HONDA / ACURA GEPAID: CAL000321397	***775 CALIFORNIA DR***	***NW 1/4 - 1/2 (0.351 mi.)***	***W465***	***465***
CARBARR DBA SHAFFERS GEPAID: CAL000172183	777 CALIFORNIA DR	NW 1/4 - 1/2 (0.353 mi.)	W470	469
SHAFFERS AUTO SVC GEPAID: CAL000003169	777 CALIFORNIA DR	NW 1/4 - 1/2 (0.353 mi.)	W474	471
777 TO 783 CALIFORNI	777 CALIFORNIA DR #	NW 1/4 - 1/2 (0.353 mi.)	W475	472

GEPAID: CAC002706341				
LARRY SPECKMAN GEPAID: CAC002566502	743 CROSSWAY RD	WNW 1/4 - 1/2 (0.359 mi.)	W478	474
1X ARTHUR W.BROWN GEPAID: CAC000844904	746 LAUREL AVE.	NNW 1/4 - 1/2 (0.370 mi.)	U481	475
KAVANAGH ENGINEERING GEPAID: CAL000115838	708 CAROLAN AVENUE	NW 1/4 - 1/2 (0.371 mi.)	Y487	480
MICHAEL LUTZ GEPAID: CAC002693662	719 WINCHESTER DR	N 1/4 - 1/2 (0.372 mi.)	U489	482
HOWARD ENGINEERING GEPAID: CAC002412759	724 CAROLAN AVE	NW 1/4 - 1/2 (0.387 mi.)	Y505	497
SAM YU GEPAID: CAC002740725	749 FARRINGDON LN	WNW 1/4 - 1/2 (0.390 mi.)	506	498
MEGAN DYER GEPAID: CAC002667662	743 WINCHESTER DR	N 1/4 - 1/2 (0.395 mi.)	U510	499
PETER WBORBERG GEPAID: CAC002757348	478 MARIN DR	NNE 1/4 - 1/2 (0.395 mi.)	T512	500
TUHIN & SHELBY SINHA GEPAID: CAC002797135	728 LEXINGTON WAY	NE 1/4 - 1/2 (0.397 mi.)	Z517	505
MICHAEL R UHL GEPAID: CAC002612214	800 HOWARD AVE	ENE 1/4 - 1/2 (0.404 mi.)	AB518	506
BELINDA BURNS GEPAID: CAC002688007	721 LEXINGTON WAY	NE 1/4 - 1/2 (0.406 mi.)	Z519	506
BSD-WASHINGTON ELEME GEPAID: CAC002658966	801 HOWARD AVE	ENE 1/4 - 1/2 (0.408 mi.)	AB530	514
BESD - WASHINGTON EL GEPAID: CAC002581752	801 HOWARD ST	ENE 1/4 - 1/2 (0.408 mi.)	AB531	514
BO THORENFELDT GEPAID: CAC002732156	101 ANITA RD	E 1/4 - 1/2 (0.410 mi.)	AC532	515
CHILTON AUTO BODY BU GEPAID: CAL000392040	925 BAYSWATER AVE	E 1/4 - 1/2 (0.415 mi.)	AC551	532
ROB DOMENICI GEPAID: CAC002788107	515 MARIN DR	N 1/4 - 1/2 (0.426 mi.)	555	541
ROB LYNCH GEPAID: CAC002678383	707 CONCORD WAY	NE 1/4 - 1/2 (0.426 mi.)	AE556	541
JANE CALAVANO GEPAID: CAC002679712	715 BURLINGAME AVE	ENE 1/4 - 1/2 (0.427 mi.)	AE558	542
GREG FRAZER GEPAID: CAC002776701	701 BURLINGAME AVE	ENE 1/4 - 1/2 (0.436 mi.)	AE577	554
MATT ROSSIE GEPAID: CAC002698970	812 MAPLE AVE	NNW 1/4 - 1/2 (0.438 mi.)	AF578	555
SHIRLEY KWOK GEPAID: CAC002770060	430 BLOOMFIELD RD	NE 1/4 - 1/2 (0.440 mi.)	Z585	558
TARA & BRIAN WATSON GEPAID: CAC002719030	460 BLOOMFIELD RD	NNE 1/4 - 1/2 (0.467 mi.)	600	572
EDWIN ANTOSIK	701 HOWARD AVE	ENE 1/4 - 1/2 (0.470 mi.)	AB603	573

GEPAID: CAC002384099				
LYNETTE ADAMS GEPAID: CAC002659826	609 VERNON WAY	NE 1/4 - 1/2 (0.474 mi.)	Z635	612
ELLEN GRUBER GEPAID: CAC002682629	840 EDGEHILL DR	NW 1/4 - 1/2 (0.475 mi.)	AK637	613

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 26 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KIRKBRIDE PROPERTY Reg Id: 41-1040	***307 LORTON***	***E 0 - 1/8 (0.058 mi.)***	***A10***	***14***
US POSTAL SERVICE Reg Id: 41-0096	***220 PARK***	***SE 0 - 1/8 (0.119 mi.)***	***B105***	***117***
HARRIS PROPERTY Reg Id: 41-0265	***1234 HOWARD***	***SE 1/8 - 1/4 (0.182 mi.)***	***G173***	***172***
KING YEE PROPERTY Reg Id: 41-0871	***1200 HOWARD***	***SE 1/8 - 1/4 (0.185 mi.)***	***G178***	***182***
PACIFIC BELL Reg Id: 41-0396	***1480 BURLINGAME AVEN***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H221***	***238***
SHELL Reg Id: 41-0492	***1490 BURLINGAME***	***SSW 1/8 - 1/4 (0.216 mi.)***	***H247***	***264***
CHEVRON Reg Id: 41-0135	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K277	291
PUTNAM CHEVROLET CAD Reg Id: 41-1137	***198 CALIFORNIA DR***	***E 1/8 - 1/4 (0.230 mi.)***	***I306***	***325***
CHEVRON, FORMER/EAGL Reg Id: 41-0128	***177 CALIFORNIA***	***ESE 1/8 - 1/4 (0.248 mi.)***	***I326***	***340***
SAREMI PROPERTY Reg Id: 41-0244	***100 CALIFORNIA***	***ESE 1/4 - 1/2 (0.347 mi.)***	***S454***	***455***
BURLINGAME FORD Reg Id: 41-0095	***99 CALIFORNIA***	***ESE 1/4 - 1/2 (0.352 mi.)***	***S467***	***466***
ARMSTRONG PROPERTY Reg Id: 41-0044	***1 PARK RD***	***SE 1/4 - 1/2 (0.407 mi.)***	***AA524***	***512***
PUTNAM MAZDA II Reg Id: 41-0430	***50 CALIFORNIA***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S537***	***517***
MCKINLEY SCHOOL Reg Id: 41-0786	***701 PALOMA***	***W 1/4 - 1/2 (0.429 mi.)***	***X565***	***546***
SMITH RESIDENCE Reg Id: 41-1105	***1615 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.440 mi.)***	***AG581***	***557***
HILLSBOROUGH TOWN OF Reg Id: 41-0744	***1600 FLORIBUNDA***	***WSW 1/4 - 1/2 (0.445 mi.)***	***AG596***	***569***
PUTNAM MAZDA	***3 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.471 mi.)***	***AD619***	***586***

Reg Id: 41-0431				
PUTNAM LINCOLN MERCU	***2 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.474 mi.)***	***AJ629***	***606***
Reg Id: 41-0519				
SHUBINER PROPERTY	***1715 RALSTON***	***SSW 1/4 - 1/2 (0.492 mi.)***	***AH639***	***619***
Reg Id: 41-1025				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHELL	***601 CALIFORNIA***	***NW 1/8 - 1/4 (0.194 mi.)***	***F214***	***230***
Reg Id: 41-0511				
W. J. BRITTON COMPAN	***701 CALIFORNIA***	***NW 1/4 - 1/2 (0.254 mi.)***	***M344***	***360***
Reg Id: 41-0657				
DEITER BLUHM	***1285 OAK GROVE***	***WNW 1/4 - 1/2 (0.309 mi.)***	***L400***	***402***
Reg Id: 41-0078				
FLOYDS AUTOMOTIVE	***741 SAN MATEO AVE***	***NW 1/4 - 1/2 (0.315 mi.)***	***M422***	***429***
Reg Id: 41-0233				
SHAFFER'S TIRE CENTE	***777 CALIFORNIA***	***NW 1/4 - 1/2 (0.370 mi.)***	***W484***	***477***
Reg Id: 41-0482				
BURLINGAME FIRE DEPT	***799 CALIFORNIA***	***NW 1/4 - 1/2 (0.376 mi.)***	***W502***	***494***
Reg Id: 41-0675				
CALIF. FEDERAL SAVIN	***1112 PALM***	***NW 1/4 - 1/2 (0.434 mi.)***	***W575***	***552***
Reg Id: 41-0710				

NPDES: A listing of NPDES permits, including stormwater.

A review of the NPDES list, as provided by EDR, and dated 05/16/2016 has revealed that there are 3 NPDES sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BURLINGAME AVENUE ST	BURLINGAME AVENUE BE	E 0 - 1/8 (0.119 mi.)	B98	113
Facility Status: Terminated				
NEW SAFEWAY BURLINGA	1450 HOWARD AVENUE	S 1/8 - 1/4 (0.219 mi.)	K262	276
260 EL CAMINO REAL	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K283	294

PEST LIC: A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

A review of the PEST LIC list, as provided by EDR, and dated 06/06/2016 has revealed that there are 2 PEST LIC sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BOB N DISCO	850 BURLINGAME AVE	ENE 1/4 - 1/2 (0.311 mi.)	416	417
DENISE DIRICKSON	209 BLOOMFIELD RD	ENE 1/4 - 1/2 (0.461 mi.)	AB599	572

EXECUTIVE SUMMARY

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 09/10/2015 has revealed that there are 3 Notify 65 sites within approximately 1.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CARUFF CALIFORNIA CO	350 AIRPORT BOULEVAR	NE 1 - 2 (1.023 mi.)	810	850
MOBILE SERVICE STATI	1200 BAYSHORE HIGHWA	NW 1 - 2 (1.064 mi.)	811	850
PACIFIC CONSTRUCTION	***1369 NORTH CAROLAN A***	***NW 1 - 2 (1.281 mi.)***	***812***	***850***

ECHO: ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A review of the ECHO list, as provided by EDR, and dated 09/20/2015 has revealed that there are 53 ECHO sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	***1229 BURLINGAME AVE.***	***ESE 0 - 1/8 (0.072 mi.)***	***A22***	***23***
VERIZON WIRELESS EL	***330 PRIMROSE RD STE***	***SSW 0 - 1/8 (0.079 mi.)***	***A35***	***30***
PRIMROSE CLEANERS	***339 PRIMROSE ROAD***	***SSW 0 - 1/8 (0.083 mi.)***	***A46***	***37***
SEPHORA STORE 52 BUR	***1205 BURLINGAME AVEN***	***ESE 0 - 1/8 (0.085 mi.)***	***A53***	***47***
HARRIS & CRISAFI C/O	***1205 HOWARD AVENUE***	***ESE 0 - 1/8 (0.085 mi.)***	***A54***	***47***
HARRIS-CRISAFI CLEAN	***1234 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.182 mi.)***	***G168***	***168***
HARRIS & CRISAFI C/O	***1234 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.182 mi.)***	***G169***	***168***
SHAFFER PROPERTY TRU	***1200 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.185 mi.)***	***G182***	***194***
FORMER CAINE CLEANER	***1319 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G189***	***201***
FORMER CAINE CLEANER	***1319/1321 HOWARD AVE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G190***	***203***
CAINES CLEANERS	***1321 HOWARD AVENUE***	***SSE 1/8 - 1/4 (0.189 mi.)***	***G192***	***205***
HARRIS-CRISAFI CLEAN	***1209 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.191 mi.)***	***G201***	***217***
STERLING CLEANERS	***1140 HOWARD AVE***	***ESE 1/8 - 1/4 (0.191 mi.)***	***G205***	***221***
HARRIS-CRISAFI CLEAN	***1201 HOWARD AVENUE***	***SE 1/8 - 1/4 (0.192 mi.)***	***G210***	***229***
PACIFIC BELL	***1480 BURLINGAME AVEN***	***SSW 1/8 - 1/4 (0.198 mi.)***	***H221***	***238***
BLUE BIRD CLEANERS	***190 PRIMROSE RD***	***SSE 1/8 - 1/4 (0.202 mi.)***	***G230***	***250***
WALGREENS NO 86	***1420 HOWARD AVE***	***S 1/8 - 1/4 (0.203 mi.)***	***G235***	***254***
SAFEWAY 1547	***1450 HOWARD AVE***	***S 1/8 - 1/4 (0.219 mi.)***	***K264***	***279***
CHEVRON 90571	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K271***	***284***
5793 SAN MATEO COUNT	***260 EL CAMINO REAL***	***SSW 1/8 - 1/4 (0.222 mi.)***	***K280***	***292***
PUTNAM AUTOMOTIVE	***198 CALIFORNIA DRIVE***	***E 1/8 - 1/4 (0.230 mi.)***	***I298***	***319***
PUTNAM CHEVROLET CAD	***198 CALIFORNIA DR***	***E 1/8 - 1/4 (0.230 mi.)***	***I306***	***325***
HARRIS & CRISAFI C/O	***137 LORTON AVENUE***	***SE 1/8 - 1/4 (0.238 mi.)***	***I315***	***334***
MURDOCH LABORITORIES	***123 PRIMROSE***	***SSE 1/8 - 1/4 (0.243 mi.)***	***K320***	***337***
JD GIUSTI TRANSPORTA	***125 LORTON AVE #2***	***SE 1/4 - 1/2 (0.259 mi.)***	***N358***	***372***
BURLINGAME SUBARU AL	***150 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.284 mi.)***	***I385***	***391***
HAROLD'S MACHINE SHO	***127 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.309 mi.)***	***S404***	***405***
BURLINGAME COLLISION	***123 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.315 mi.)***	***S421***	***421***
BURLINGAME FORD	***101 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.346 mi.)***	***S446***	***445***
PUTNAM TOYOTA	***100 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.347 mi.)***	***S455***	***456***
MILE HIGH TRUCKING	***108 MYRTLE RD #4***	***E 1/4 - 1/2 (0.373 mi.)***	***S494***	***487***
PUTNAM AUTOMOTIVE	***65 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.397 mi.)***	***S514***	***501***
PUTNAM AUTOMOTIVE	***50 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S536***	***517***
J AND M MOTORS D B A	***50 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.414 mi.)***	***S539***	***519***
PUTNAM MAZDA	***3 CALIFORNIA DR***	***ESE 1/4 - 1/2 (0.471 mi.)***	***AD619***	***586***
PUTNAM AUTOMOTIVE	***2 CALIFORNIA DRIVE***	***ESE 1/4 - 1/2 (0.474 mi.)***	***AJ634***	***611***
PUTNAM AUTOMOTIVE	***900 PENINSULA AVENUE***	***ESE 1/4 - 1/2 (0.498 mi.)***	***AJ650***	***626***

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PUTNAM BUICK PONTIAC	*900 PENINSULA AVE*	*ESE 1/4 - 1/2 (0.498 mi.)*	*AJ651*	*626*
DUTNAM HYUNDAI	*900 PENINSULA AVE*	*ESE 1/4 - 1/2 (0.498 mi.)*	*AJ653*	*628*

Lower Elevation	Address	Direction / Distance	Map ID	Page
CITY OF BURLINGAME	*425 CAROLAN AVENUE*	*NNE 0 - 1/8 (0.110 mi.)*	*D71*	*63*
CITY OF BURLINGAME	*501 PRIMROSE ROAD*	*W 0 - 1/8 (0.116 mi.)*	*E77*	*71*
BURLINGAME HIGH SCHO	*400 CAROLAN AVENUE*	*NNE 0 - 1/8 (0.117 mi.)*	*D84*	*79*
BURLINGAME ONE HOUR	*507 CALIFORNIA DRIVE*	*NNW 1/8 - 1/4 (0.140 mi.)*	*F124*	*134*
D & R AUTO BODY AND	*270 EAST LANE, #2*	*E 1/8 - 1/4 (0.211 mi.)*	*I236*	*257*
FOUR CAR GARAGE THE	*609 CALIFORNIA DR*	*NW 1/8 - 1/4 (0.218 mi.)*	*F260*	*273*
ON TRACK AUTOMOTIVE	*621 CALIFORNIA DR*	*NW 1/8 - 1/4 (0.235 mi.)*	*M313*	*332*
ALL MAKES AUTO BODY	*257 MYRTLE ROAD*	*ENE 1/8 - 1/4 (0.250 mi.)*	*J335*	*348*
UNITED AUTO COLLISIO	*255 MYRTLE ROAD*	*ENE 1/4 - 1/2 (0.251 mi.)*	*J338*	*354*
MIKE HARVEY HONDA	*212 EAST LANE*	*E 1/4 - 1/2 (0.258 mi.)*	*I353*	*366*
GEORGES HOLIDAY CLEA	*741 CALIFORNIA DRIVE*	*NW 1/4 - 1/2 (0.311 mi.)*	*M410*	*411*
EUROPEAN PERFORMANCE	*751 CALIFORNIA DR*	*NW 1/4 - 1/2 (0.326 mi.)*	*M433*	*437*
CITY OF BURLINGAME	*799 CALIFORNIA DRIVE*	*NW 1/4 - 1/2 (0.376 mi.)*	*W503*	*496*
PUTNAM BUICK,PONTIAC	*925 BAYSWATER STREET*	*E 1/4 - 1/2 (0.415 mi.)*	*AC553*	*539*

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 34 EDR Hist Auto sites within approximately 0.625 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	251 CALIFORNIA DR	E 1/8 - 1/4 (0.150 mi.)	B133	140
Not reported	1440 CHAPIN AVE	SW 1/8 - 1/4 (0.154 mi.)	C136	143
Not reported	215 HATCH LN	ESE 1/8 - 1/4 (0.180 mi.)	B156	159
Not reported	1220 HOWARD AVE	SE 1/8 - 1/4 (0.183 mi.)	G176	181
Not reported	1325 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G198	214
Not reported	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K281	293
Not reported	120 EL CAMINO REAL	SSE 1/4 - 1/2 (0.276 mi.)	K379	388
Not reported	124 HIGHLAND AVE	ESE 1/4 - 1/2 (0.295 mi.)	I390	396
Not reported	123 CALIFORNIA DR	ESE 1/4 - 1/2 (0.315 mi.)	S418	418
Not reported	136 MYRTLE RD	E 1/4 - 1/2 (0.348 mi.)	P460	462
Not reported	132 MYRTLE RD	E 1/4 - 1/2 (0.351 mi.)	P461	463
Not reported	920 BAYSWATER AVE	ESE 1/4 - 1/2 (0.373 mi.)	S490	483
Not reported	65 CALIFORNIA DR	ESE 1/4 - 1/2 (0.397 mi.)	S516	505
Not reported	1 PARK RD	SE 1/4 - 1/2 (0.407 mi.)	AA522	511

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	900 PENINSULA AVE	ESE 1/4 - 1/2 (0.498 mi.)	AJ649	625
Not reported	839 N SAN MATEO DR	ESE 1/2 - 1 (0.565 mi.)	AJ673	647
Not reported	217 STATE RD	ESE 1/2 - 1 (0.594 mi.)	685	669
Not reported	825 N SAN MATEO DR	ESE 1/2 - 1 (0.596 mi.)	AO689	672

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	601 CALIFORNIA DR	NW 1/8 - 1/4 (0.194 mi.)	F217	234
Not reported	270 EAST LN	E 1/8 - 1/4 (0.211 mi.)	I238	257
Not reported	609 CALIFORNIA DR	NW 1/8 - 1/4 (0.218 mi.)	F261	275
Not reported	260 EAST LN	E 1/8 - 1/4 (0.219 mi.)	I268	282
Not reported	621 CALIFORNIA DR	NW 1/8 - 1/4 (0.235 mi.)	M310	330
Not reported	257 MYRTLE RD	ENE 1/8 - 1/4 (0.250 mi.)	J332	345
Not reported	255 MYRTLE RD	ENE 1/4 - 1/2 (0.251 mi.)	J337	354
Not reported	212 EAST LN	E 1/4 - 1/2 (0.258 mi.)	I357	372
Not reported	927 HOWARD AVE	E 1/4 - 1/2 (0.305 mi.)	P395	399
Not reported	708 LAUREL AVE	N 1/4 - 1/2 (0.318 mi.)	U427	432
Not reported	751 CALIFORNIA DR	NW 1/4 - 1/2 (0.326 mi.)	M431	435
Not reported	775 CALIFORNIA DR	NW 1/4 - 1/2 (0.351 mi.)	W466	466
Not reported	777 CALIFORNIA DR	NW 1/4 - 1/2 (0.353 mi.)	W473	470
Not reported	867 CALIFORNIA DR	NW 1/2 - 1 (0.507 mi.)	AK658	632
Not reported	847 ACACIA AVE	WNW 1/2 - 1 (0.541 mi.)	AM668	645
Not reported	400 PENINSULA AVE	E 1/2 - 1 (0.582 mi.)	AN678	652

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 12 EDR Hist Cleaner sites within approximately 0.625 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	339 PRIMROSE RD	SSW 0 - 1/8 (0.083 mi.)	A43	34
Not reported	337 PRIMROSE RD	SSW 0 - 1/8 (0.084 mi.)	A52	46
Not reported	240 PRIMROSE RD	S 1/8 - 1/4 (0.140 mi.)	C126	135
Not reported	229 PARK RD	SE 1/8 - 1/4 (0.151 mi.)	G135	143
Not reported	1321 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G195	211
Not reported	1325 HOWARD AVE	SSE 1/8 - 1/4 (0.189 mi.)	G199	214
Not reported	1140 HOWARD AVE	ESE 1/8 - 1/4 (0.191 mi.)	G203	219
Not reported	1460 BELLEVUE AVE	WSW 1/4 - 1/2 (0.263 mi.)	O361	374

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	345 CALIFORNIA DR	NE 0 - 1/8 (0.075 mi.)	A31	28
Not reported	507 CALIFORNIA DR	NNW 1/8 - 1/4 (0.140 mi.)	F125	134
Not reported	715 CALIFORNIA DR	NW 1/4 - 1/2 (0.275 mi.)	M377	386
Not reported	741 CALIFORNIA DR	NW 1/4 - 1/2 (0.311 mi.)	M411	411

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LUST: The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

A review of the RGA LUST list, as provided by EDR, has revealed that there are 84 RGA LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KIRKBRIDE PROPERTY	307 LORTON	E 0 - 1/8 (0.058 mi.)	A6	13
KIRKBRIDE PROPERTY	307 LORTON AVE	E 0 - 1/8 (0.058 mi.)	A8	13
GERRITSON PROPERTY	1229 BURLINGAME AVE	ESE 0 - 1/8 (0.072 mi.)	A23	23
BURLINGAME POST OFFI	220 PARK	SE 0 - 1/8 (0.119 mi.)	B99	114
BURLINGAME POST OFFI	220 PARK	SE 0 - 1/8 (0.119 mi.)	B100	114
BURLINGAME POST OFFI	220 PARK RD	SE 0 - 1/8 (0.119 mi.)	B101	115
BURLINGAME POST OFFI	220 PARK ROAD	SE 0 - 1/8 (0.119 mi.)	B103	116
US POSTAL SERVICE	220 PARK RD	SE 0 - 1/8 (0.119 mi.)	B108	120
STERLING CLEANERS (F	215 CALIFORNIA DRIVE	ESE 1/8 - 1/4 (0.167 mi.)	B147	155
200 PARK	200 PARK ROAD	SE 1/8 - 1/4 (0.180 mi.)	G162	164
HARRIS PROPERTY	1234 HOWARD AVE	SE 1/8 - 1/4 (0.182 mi.)	G166	167
HARRIS PROPERTY	1234 HOWARD	SE 1/8 - 1/4 (0.182 mi.)	G167	167
KING YEE PROPERTY	1200 HOWARD AVE	SE 1/8 - 1/4 (0.185 mi.)	G177	181
KING YEE PROPERTY	1200 HOWARD	SE 1/8 - 1/4 (0.185 mi.)	G181	194
BERENSTEIN ASSOC. PR	1319 HOWARD	SSE 1/8 - 1/4 (0.189 mi.)	G185	197
PACIFIC BELL	1480 BURLINGAME AVE	SSW 1/8 - 1/4 (0.198 mi.)	H223	244
PACIFIC BELL	1480 BURLINGAME	SSW 1/8 - 1/4 (0.198 mi.)	H228	249
SHELL	1490 BURLINGAME	SSW 1/8 - 1/4 (0.216 mi.)	H248	266
SHELL	1490 BURLINGAME AVE	SSW 1/8 - 1/4 (0.216 mi.)	H253	270
CHEVRON 9-0571	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K275	289
CHEVRON 9-0571	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K278	292
CHEVRON	260 EL CAMINO REAL	SSW 1/8 - 1/4 (0.222 mi.)	K279	292
ARATA PROPERTY	198 CALIFORNIA DR	E 1/8 - 1/4 (0.230 mi.)	I300	322
ARATA PROPERTY	198 CALIFORNIA	E 1/8 - 1/4 (0.230 mi.)	I301	322
ARATA PROPERTY	198 CALIFORNIA DRIVE	E 1/8 - 1/4 (0.230 mi.)	I304	323
CHEVRON, FORMER/EAGL	177 CALIFORNIA	ESE 1/8 - 1/4 (0.248 mi.)	I321	338
CHEVRON	177 CALIFORNIA AVE	ESE 1/8 - 1/4 (0.248 mi.)	I322	338
FORMER CHEVRON/EAGLE	177 CALIFORNIA	ESE 1/8 - 1/4 (0.248 mi.)	I324	340
FORMER CHEVRON/EAGLE	177 CALIFORNIA AVE	ESE 1/8 - 1/4 (0.248 mi.)	I327	343
CHEVRON	177 CALIFORNIA ST	ESE 1/8 - 1/4 (0.248 mi.)	I328	344
SAREMI PROPERTY	100 CALIFORNIA DR	ESE 1/4 - 1/2 (0.347 mi.)	S447	452
ARATA HONDA	100 CALIFORNIA DR	ESE 1/4 - 1/2 (0.347 mi.)	S449	452
SAREMI PROPERTY	100 CALIFORNIA	ESE 1/4 - 1/2 (0.347 mi.)	S456	458
BURLINGAME FORD	99 CALIFORNIA	ESE 1/4 - 1/2 (0.352 mi.)	S468	468
BURLINGAME FORD	99 CALIFORNIA DR	ESE 1/4 - 1/2 (0.352 mi.)	S469	468
ARMSTRONG PROPERTY	1 PARK ROAD	SE 1/4 - 1/2 (0.407 mi.)	AA523	511
ARMSTRONG PROPERTY	1 PARK RD	SE 1/4 - 1/2 (0.407 mi.)	AA526	512
ARMSTRONG PROPERTY	1 PARK	SE 1/4 - 1/2 (0.407 mi.)	AA527	513
PUTNAM MAZDA II	50 CALIFORNIA	ESE 1/4 - 1/2 (0.414 mi.)	S540	523
PUTNAM MAZDA II	50 CALIFORNIA DR	ESE 1/4 - 1/2 (0.414 mi.)	S541	523
PUTNAM BUICK	50 CALIFORNIA DR	ESE 1/4 - 1/2 (0.414 mi.)	S546	528
MCKINLEY SCHOOL	701 PALOMA	W 1/4 - 1/2 (0.429 mi.)	X562	544
MCKINLEY SCHOOL	701 PALOMA AVE	W 1/4 - 1/2 (0.429 mi.)	X566	548

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SMITH RESIDENCE	1615 FLORIBUNDA AVE	WSW 1/4 - 1/2 (0.440 mi.)	AG579	555
SMITH RESIDENCE	1615 FLORIBUNDA	WSW 1/4 - 1/2 (0.440 mi.)	AG583	557
CITY OF HILLSBOROUGH	1600 FLORIBUNDA	WSW 1/4 - 1/2 (0.445 mi.)	AG587	559
HILLSBOROUGH CITY OF	1600 FLORIBUNDA	WSW 1/4 - 1/2 (0.445 mi.)	AG591	566
HILLSBOROUGH TOWN OF	1600 FLORIBUNDA AVE	WSW 1/4 - 1/2 (0.445 mi.)	AG593	567
TOWN OF HILLSBOROUGH	1600 FLORIBUNDA	WSW 1/4 - 1/2 (0.445 mi.)	AG594	567
ARCO #0249	3 CALIFORNIA	ESE 1/4 - 1/2 (0.471 mi.)	AD605	574
ARCO #0249	3 CALIFORNIA DRIVE	ESE 1/4 - 1/2 (0.471 mi.)	AD606	574
ARCO	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD611	579
FORMER ARCO # 00249	3 CALIFORNIA	ESE 1/4 - 1/2 (0.471 mi.)	AD612	579
PUTNAM-MAZDA BUICK	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD615	583
PUTNAM MAZDA BUICK	3 CALIFORNIA DR	ESE 1/4 - 1/2 (0.471 mi.)	AD618	586
SHEN-LINCOLN MERCURY	2 CALIFORNIA	ESE 1/4 - 1/2 (0.474 mi.)	AJ623	604
SHEN MITSUBISHI	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ625	604
SHEN-MITSUBISHI	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ628	605
SHEN-LINCOLN MERCURY	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ632	611
SHEN LINCOLN MERCURY	2 CALIFORNIA DR	ESE 1/4 - 1/2 (0.474 mi.)	AJ633	611
SHUBINER PROPERTY	1715 RALSTON AVE	SSW 1/4 - 1/2 (0.492 mi.)	AH640	619
SHUBINER PROPERTY	1715 RALSTON	SSW 1/4 - 1/2 (0.492 mi.)	AH641	619

Lower Elevation	Address	Direction / Distance	Map ID	Page
SABATINI TRUST	361 CALIFORNIA	NE 0 - 1/8 (0.071 mi.)	A19	22
KIM MILLS TEXACO (FO	401 CALIFORNIA	N 0 - 1/8 (0.073 mi.)	A24	24
SHELL	601 CALIFORNIA DR	NW 1/8 - 1/4 (0.194 mi.)	F212	230
SHELL	601 CALIFORNIA	NW 1/8 - 1/4 (0.194 mi.)	F215	232
WJ BRITTON	701 CALIFORNIA DR	NW 1/4 - 1/2 (0.254 mi.)	M345	362
W.J. BRITTON COMPANY	701 CALIFORNIA DR	NW 1/4 - 1/2 (0.254 mi.)	M346	362
W. J. BRITTON COMPAN	701 CALIFORNIA	NW 1/4 - 1/2 (0.254 mi.)	M347	363
WJ BRITTON COMPANY	701 CALIFORNIA DR	NW 1/4 - 1/2 (0.254 mi.)	M348	363
WJ BRITTON	701 CALIFORNIA	NW 1/4 - 1/2 (0.254 mi.)	M349	363
WJ BRITTON COMPANY	701 CALIFORNIA DR	NW 1/4 - 1/2 (0.254 mi.)	M350	363
WOODHALL INVESTMENTS	731 SAN MATEO AVE	NW 1/4 - 1/2 (0.299 mi.)	M391	397
BLUHM PROPERTY	1285 OAK GROVE	WNW 1/4 - 1/2 (0.309 mi.)	L401	404
DEITER BLUHM	1285 OAK GROVE	WNW 1/4 - 1/2 (0.309 mi.)	L402	404
FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE	NW 1/4 - 1/2 (0.315 mi.)	M423	431
FLOYD'S AUTOMOTIVE	741 SAN MATEO	NW 1/4 - 1/2 (0.315 mi.)	M426	432
SHAFFER'S TIRE CENTE	777 CALIFORNIA	NW 1/4 - 1/2 (0.353 mi.)	W471	469
SHAFFER'S TIRE CENTE	777 CALIFORNIA DR	NW 1/4 - 1/2 (0.353 mi.)	W472	470
BURLINGAME FIRE DEPT	799 CALIFORNIA DR	NW 1/4 - 1/2 (0.376 mi.)	W497	489
BURLINGAME FIRE DEPT	799 CALIFORNIA	NW 1/4 - 1/2 (0.376 mi.)	W500	493
CALIF FEDERAL SAVING	1112 PALM DR	NW 1/4 - 1/2 (0.434 mi.)	W570	551
CALIF. FEDERAL SAVIN	1112 PALM	NW 1/4 - 1/2 (0.434 mi.)	W572	552
HAGGERTY RESIDENCE	1112 PALM DR	NW 1/4 - 1/2 (0.434 mi.)	W573	552

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 3 records.

Site Name	Database(s)
	CDL
BROWNING-FERRIS INDUSTRIES	ENVIROSTOR
BROWNING-FERRIS IND (SAN MATEO LAN	ENVIROSTOR

OVERVIEW MAP - 4688986.2S




This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
		INQUIRY #:	4688986.2s
LAT/LONG:	37.579506 / 122.347789	DATE:	August 02, 2016 9:22 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 4688986.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA

Pipelines

100-year flood zone

500-year flood zone

National Wetland Inventory

State Wetlands

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
LAT/LONG:	37.579506 / 122.347789	INQUIRY #:	4688986.2s
		DATE:	August 02, 2016 9:25 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

EC OP L

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.500		0	0	0	0	0	0
Proposed NPL	1.500		0	0	0	0	0	0
NPL LIENS	0.500		0	0	0	NR	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.500		0	0	0	0	0	0
Federal CERCLIS list								
FEDERAL FACILITY	1.000		0	0	0	0	NR	0
SEMS	1.000		0	0	0	0	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	1.000		1	0	0	0	NR	1
Federal RCRA CORRACTS facilities list								
CORRACTS	1.500		0	0	0	0	0	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	1.000		0	0	0	0	NR	0
Federal RCRA generators list								
RCRA-LQG	0.750		0	1	0	1	NR	2
RCRA-SQG	0.750		1	10	9	12	NR	32
RCRA-CESQG	0.750		0	1	0	0	NR	1
Federal institutional controls / engineering controls registries								
LUCIS	1.000		0	0	0	0	NR	0
US ENG CONTROLS	1.000		0	0	0	0	NR	0
US INST CONTROL	1.000		0	0	0	0	NR	0
Federal ERNS list								
ERNS	0.500		0	0	0	NR	NR	0
State- and tribal - equivalent NPL								
RESPONSE	1.500		0	0	0	0	0	0
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.500		1	0	0	3	2	6
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	1.000		0	0	0	1	NR	1
State and tribal leaking storage tank lists								
LUST	1.000		8	20	31	71	NR	130

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	1.000		0	0	0	0	NR	0
SLIC	1.000		0	3	2	4	NR	9
State and tribal registered storage tank lists								
FEMA UST	0.750		0	0	0	0	NR	0
UST	0.750		0	4	0	0	NR	4
AST	0.750		0	0	0	0	NR	0
INDIAN UST	0.750		0	0	0	0	NR	0
State and tribal voluntary cleanup sites								
INDIAN VCP	1.000		0	0	0	0	NR	0
VCP	1.000		0	0	0	0	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	1.000		0	0	0	0	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	1.000		0	0	0	0	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	1.000		0	0	0	0	NR	0
SWRCY	1.000		0	0	0	1	NR	1
HAULERS	0.500		0	0	0	NR	NR	0
INDIAN ODI	1.000		0	0	0	0	NR	0
DEBRIS REGION 9	1.000		0	0	0	0	NR	0
ODI	1.000		0	0	0	0	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.500		0	0	0	NR	NR	0
HIST Cal-Sites	1.500		0	0	0	0	0	0
SCH	0.750		1	0	0	0	NR	1
CDL	0.500		1	0	0	NR	NR	1
Toxic Pits	1.500		0	0	0	0	0	0
US CDL	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.750		0	5	11	13	NR	29
HIST UST	0.750		1	5	8	9	NR	23
CA FID UST	0.750		0	4	6	8	NR	18
Local Land Records								
LIENS	0.500		0	0	0	NR	NR	0
LIENS 2	0.500		0	0	0	NR	NR	0
DEED	1.000		1	0	0	0	NR	1
Records of Emergency Release Reports								
HMIRS	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CHMIRS	0.500		0	7	10	NR	NR	17
LDS	0.500		0	0	0	NR	NR	0
MCS	0.500		0	0	0	NR	NR	0
SPILLS 90	0.500		0	0	1	NR	NR	1
Other Ascertainable Records								
RCRA NonGen / NLR	0.750		0	0	2	2	NR	4
FUDS	1.500		0	0	0	0	0	0
DOD	1.500		0	0	0	0	0	0
SCRD DRYCLEANERS	1.000		0	0	0	0	NR	0
US FIN ASSUR	0.500		0	0	0	NR	NR	0
EPA WATCH LIST	0.500		0	0	0	NR	NR	0
2020 COR ACTION	0.750		0	0	0	0	NR	0
TSCA	0.500		0	0	0	NR	NR	0
TRIS	0.500		0	0	0	NR	NR	0
SSTS	0.500		0	0	0	NR	NR	0
ROD	1.500		0	0	0	0	0	0
RMP	0.500		0	0	0	NR	NR	0
RAATS	0.500		0	0	0	NR	NR	0
PRP	0.500		0	0	0	NR	NR	0
PADS	0.500		0	0	0	NR	NR	0
ICIS	0.500		0	0	0	NR	NR	0
FTTS	0.500		0	0	0	NR	NR	0
MLTS	0.500		0	0	0	NR	NR	0
COAL ASH DOE	0.500		0	0	0	NR	NR	0
COAL ASH EPA	1.000		0	0	0	0	NR	0
PCB TRANSFORMER	0.500		0	0	0	NR	NR	0
RADINFO	0.500		0	0	0	NR	NR	0
HIST FTTS	0.500		0	0	0	NR	NR	0
DOT OPS	0.500		0	0	0	NR	NR	0
CONSENT	1.500		0	0	0	0	0	0
INDIAN RESERV	1.500		0	0	0	0	0	0
FUSRAP	1.500		0	0	0	0	0	0
UMTRA	1.000		0	0	0	0	NR	0
LEAD SMELTERS	0.500		0	0	0	NR	NR	0
US AIRS	0.500		0	0	0	NR	NR	0
US MINES	0.750		0	0	0	0	NR	0
FINDS	0.500		8	24	21	NR	NR	53
UXO	1.500		0	0	0	0	0	0
DOCKET HWC	0.500		0	0	0	NR	NR	0
CA BOND EXP. PLAN	1.500		0	0	0	0	0	0
San Mateo Co. BI	0.750		17	46	52	58	NR	173
Cortese	1.000		0	0	1	0	NR	1
CUPA Listings	0.750		0	0	0	0	NR	0
DRYCLEANERS	0.750		1	4	2	0	NR	7
EMI	0.500		5	16	14	NR	NR	35
ENF	0.500		0	0	1	NR	NR	1
Financial Assurance	0.500		0	0	0	NR	NR	0
HAZNET	0.500	1	58	64	117	NR	NR	240
HIST CORTESE	0.500		2	8	16	NR	NR	26
HWP	1.500		0	0	0	0	0	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
HWT	0.750		0	0	0	0	NR	0
MINES	0.500		0	0	0	NR	NR	0
MWMP	0.750		0	0	0	0	NR	0
NPDES	0.500		1	2	0	NR	NR	3
PEST LIC	0.500		0	0	2	NR	NR	2
PROC	1.000		0	0	0	0	NR	0
Notify 65	1.500		0	0	0	0	3	3
UIC	0.500		0	0	0	NR	NR	0
WASTEWATER PITS	1.000		0	0	0	0	NR	0
WDS	0.500		0	0	0	NR	NR	0
WIP	0.750		0	0	0	0	NR	0
ECHO	0.500		8	24	21	NR	NR	53
FUELS PROGRAM	0.750		0	0	0	0	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.500		0	0	0	0	0	0
EDR Hist Auto	0.625		0	12	16	6	NR	34
EDR Hist Cleaner	0.625		3	6	3	0	NR	12
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.500		0	0	0	NR	NR	0
RGA LUST	0.500		10	24	50	NR	NR	84
- Totals --		1	128	290	396	189	5	1009

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target Property
Actual: 32 ft.

JOHN BRITTON
1218 DONNELLY AVE
BURLINGAME, CA 94010

HAZNET **S118217302** **N/A**

Site 1 of 60 in cluster A

HAZNET:

envid:	S118217302
Year:	2014
GEPAID:	CAC002779641
Contact:	JOHN BRITTON
Telephone:	4159341151
Mailing Name:	Not reported
Mailing Address:	1218 DONNELLY AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

A2
< 1/8
1 ft.

Relative: Higher

Actual: 32 ft.

CITY BURLINGAME/PUB WORKS
1230 DONNELLY AVE
BURLINGAME, CA 94010

HAZNET **S112867236** **N/A**

Site 2 of 60 in cluster A

HAZNET:

envid:	S112867236
Year:	1996
GEPAID:	CAC001109280
Contact:	CITY OF BURLINGAME
Telephone:	4156967230
Mailing Name:	Not reported
Mailing Address:	501 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	8.4280
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

A3 **MIKE'S AUTOMOTIVE SERVICE** **HAZNET** **S113027046**
ENE **1212 DONNELLY AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.022 mi.
114 ft. **Site 3 of 60 in cluster A**

Relative:
Higher

Actual:
32 ft.

HAZNET:

envid:	S113027046
Year:	1998
GEPAID:	CAL000015688
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	991 SO COLONEL WAY
Mailing City,St,Zip:	HALF MOON BAY, CA 940190000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.4170
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113027046
Year:	1998
GEPAID:	CAL000015688
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	991 SO COLONEL WAY
Mailing City,St,Zip:	HALF MOON BAY, CA 940190000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Transfer Station
Tons:	2.3850
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113027046
Year:	1997
GEPAID:	CAL000015688
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	991 SO COLONEL WAY
Mailing City,St,Zip:	HALF MOON BAY, CA 940190000
Gen County:	Not reported
TSD EPA ID:	CAD000088252
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Transfer Station
Tons:	.3000
Cat Decode:	Other inorganic solid waste
Method Decode:	Transfer Station

MIKE'S AUTOMOTIVE SERVICE (Continued) **S113027046**

Facility County: San Mateo

envid: S113027046
Year: 1996
GEPAID: CAL000015688
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 991 SO COLONEL WAY
Mailing City,St,Zip: HALF MOON BAY, CA 940190000
Gen County: Not reported
TSD EPA ID: CAD000088252
TSD County: Not reported
Waste Category: Other inorganic solid waste
Disposal Method: Transfer Station
Tons: .2500
Cat Decode: Other inorganic solid waste
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113027046
Year: 1994
GEPAID: CAL000015688
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 991 SO COLONEL WAY
Mailing City,St,Zip: HALF MOON BAY, CA 940190000
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Disposal, Other
Tons: .2293
Cat Decode: Unspecified oil-containing waste
Method Decode: Disposal, Other
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

A4
ENE
< 1/8
0.022 mi.
114 ft.

MIKES AUTOMOTIVE SERVICE **San Mateo Co. BI** **S113756632**
1212 DONNELLY **N/A**
BURLINGAME, CA 94010

Site 4 of 60 in cluster A

Relative:
Higher

Actual:
32 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0018039
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011855
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018039
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3

MIKES AUTOMOTIVE SERVICE (Continued) **S113756632**

Record Id: PR0004635
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

A5 **LORTON PLACE OWNERS ASSOCIATION** **LUST** **S113804525**
North **345 LORTON AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.025 mi.
130 ft. **Site 5 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

LUST:
Region: STATE
Global Id: T10000004932
Latitude: 37.5801979256519
Longitude: -122.347689136246
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 10/22/2013
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 660111
File Location: Not reported
Potential Media Affect: Aquifer used for drinking water supply, Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Diesel, Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000004932
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T10000004932
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T10000004932
Status: Completed - Case Closed
Status Date: 10/22/2013

Global Id: T10000004932
Status: Open - Case Begin Date
Status Date: 02/16/2013

LORTON PLACE OWNERS ASSOCIATION (Continued) **S113804525**

Global Id: T10000004932
Status: Open - Eligible for Closure
Status Date: 07/23/2013

Global Id: T10000004932
Status: Open - Site Assessment
Status Date: 07/11/2013

Regulatory Activities:
Global Id: T10000004932
Action Type: ENFORCEMENT
Date: 10/22/2013
Action: Closure/No Further Action Letter - #20131022

Global Id: T10000004932
Action Type: ENFORCEMENT
Date: 08/07/2013
Action: Notification - Public Notice of Case Closure - #20130807

Global Id: T10000004932
Action Type: RESPONSE
Date: 05/08/2013
Action: Site Assessment Report

Global Id: T10000004932
Action Type: ENFORCEMENT
Date: 07/19/2013
Action: Notice of Responsibility - #20130719

Global Id: T10000004932
Action Type: Other
Date: 02/16/2013
Action: Leak Discovery

Global Id: T10000004932
Action Type: Other
Date: 03/21/2013
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660111
Facility Status: 9- Case Closed
Global ID: Not reported
APN Number: MULTIPLE APNS
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

A6 **KIRKBRIDE PROPERTY** **RGA LUST** **S114640204**
East **307 LORTON** **N/A**
< 1/8 **BURLINGAME, CA**
0.058 mi.
308 ft. **Site 6 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2012	KIRKBRIDE PROPERTY	307 LORTON
2011	KIRKBRIDE PROPERTY	307 LORTON
2010	KIRKBRIDE PROPERTY	307 LORTON
2009	KIRKBRIDE PROPERTY	307 LORTON
2008	KIRKBRIDE PROPERTY	307 LORTON
2007	KIRKBRIDE PROPERTY	307 LORTON
2006	KIRKBRIDE PROPERTY	307 LORTON
2005	KIRKBRIDE PROPERTY	307 LORTON
2003	KIRKBRIDE PROPERTY	307 LORTON

A7 **COMMERCIAL BUILDING** **San Mateo Co. BI** **S113757130**
East **307 LORTON** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.058 mi.
308 ft. **Site 7 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0024376
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0029020
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

A8 **KIRKBRIDE PROPERTY** **RGA LUST** **S114640203**
East **307 LORTON AVE** **N/A**
< 1/8 **BURLINGAME, CA**
0.058 mi.
308 ft. **Site 8 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2002	KIRKBRIDE PROPERTY	307 LORTON AVE
2001	KIRKBRIDE PROPERTY	307 LORTON AVE
2000	KIRKBRIDE PROPERTY	307 LORTON AVE
1998	KIRKBRIDE PROPERTY	307 LORTON AVE

A9 **KIRKBRIDE PROPERTY** **LUST** **S104493529**
East **307 LORTON** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.058 mi.
308 ft. **Site 9 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660081
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown

KIRKBRIDE PROPERTY (Continued) **S104493529**

Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

A10 **KIRKBRIDE PROPERTY** **LUST S103171184**
East **307 LORTON** **HIST CORTESE N/A**
< 1/8 **BURLINGAME, CA 94010**
0.058 mi.
308 ft. **Site 10 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

LUST:
Region: STATE
Global Id: T0608100953
Latitude: 37.5794701
Longitude: -122.346454
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/09/1997
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1040
LOC Case Number: 660081
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100953
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100953
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100953
Status: Completed - Case Closed
Status Date: 12/09/1997

KIRKBRIDE PROPERTY (Continued) **S103171184**

Global Id: T0608100953
Status: Open - Case Begin Date
Status Date: 06/20/1997

Regulatory Activities:
Global Id: T0608100953
Action Type: ENFORCEMENT
Date: 06/20/1997
Action: Notice of Responsibility - #1

Global Id: T0608100953
Action Type: Other
Date: 06/03/1997
Action: Leak Discovery

Global Id: T0608100953
Action Type: Other
Date: 06/23/1997
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660081
Facility Status: 9- Case Closed
Global ID: T0608100953
APN Number: 029152110
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1040

A11 **KIRKBRIDE PROPERTIES** **HAZNET** **S112869317**
East **307 LORTON AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.058 mi.
308 ft. **Site 11 of 60 in cluster A**

Relative:
Higher

Actual:
33 ft.

HAZNET:
envid: S112869317
Year: 1997
GEPAID: CAC001146992
Contact: BRUCE KIRKBRIDE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1229 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: NVD982358483
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Not reported

KIRKBRIDE PROPERTIES (Continued) **S112869317**

Tons: .7500
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Not reported
Facility County: San Mateo

envid: S112869317
Year: 1997
GEPAID: CAC001146992
Contact: BRUCE KIRKBRIDE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1229 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Tons: 1.2510
Cat Decode: Unspecified oil-containing waste
Method Decode: Transfer Station
Facility County: San Mateo

envid: S112869317
Year: 1997
GEPAID: CAC001146992
Contact: BRUCE KIRKBRIDE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1229 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000048571
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Transfer Station
Tons: 7.5060
Cat Decode: Unspecified oil-containing waste
Method Decode: Transfer Station
Facility County: San Mateo

envid: S112869317
Year: 1997
GEPAID: CAC001146992
Contact: BRUCE KIRKBRIDE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1229 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: .7500
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler

KIRKBRIDE PROPERTIES (Continued) **S112869317**

Facility County: San Mateo

A12 **SABATINI TRUST** **LUST** **S103960987**
NE **361 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.059 mi.
310 ft. **Site 12 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

LUST:

Region:	STATE
Global Id:	T10000004188
Latitude:	37.5802678
Longitude:	-122.3470527
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/01/2012
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	660110
File Location:	Not reported
Potential Media Affect:	Not reported
Potential Contaminants of Concern:	Diesel
Site History:	Site to be opened and closed

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T10000004188
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T10000004188
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T10000004188
Status:	Completed - Case Closed
Status Date:	08/01/2012

Global Id:	T10000004188
Status:	Open - Case Begin Date
Status Date:	06/13/2012

Global Id:	T10000004188
Status:	Open - Verification Monitoring

SABATINI TRUST (Continued) **S103960987**

Status Date: 07/26/2012

Regulatory Activities:
Global Id: T10000004188
Action Type: ENFORCEMENT
Date: 07/25/2012
Action: Notice of Responsibility - #20120725

Global Id: T10000004188
Action Type: Other
Date: 06/13/2012
Action: Leak Discovery

Global Id: T10000004188
Action Type: Other
Date: 06/28/2012
Action: Leak Reported

Global Id: T10000004188
Action Type: ENFORCEMENT
Date: 08/01/2012
Action: Closure/No Further Action Letter - #20120801

A13 **DON SABATINI** **HAZNET** **S112899752**
NE **361 CALIFORNIA DR** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.059 mi.
310 ft. **Site 13 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

HAZNET:
envid: S112899752
Year: 1999
GEPAID: CAC002134305
Contact: DON SABATINI
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 340 LORTON AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAT000646117
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Disposal, Land Fill
Tons: .1750
Cat Decode: Waste oil and mixed oil
Method Decode: Disposal, Land Fill
Facility County: San Mateo

envid: S112899752
Year: 1999
GEPAID: CAC002134305
Contact: DON SABATINI
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 340 LORTON AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000

DON SABATINI (Continued) **S112899752**

Gen County: Not reported
TSD EPA ID: CAD008302903
TSD County: Not reported
Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: Transfer Station
Tons: 3.3360
Cat Decode: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode: Transfer Station
Facility County: San Mateo

A14 **DON SABATINI** **LUST S112871639**
NE **361 CALIFORNIA DR** **HAZNET N/A**
< 1/8 **BURLINGAME, CA 94010**
0.059 mi.
310 ft. **Site 14 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660110
Facility Status: 9- Case Closed
Global ID: Not reported
APN Number: 029153010
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HAZNET:
envid: S112871639
Year: 1999
GEPAID: CAC001172856
Contact: DON SABATINI
Telephone: 6506855666
Mailing Name: Not reported
Mailing Address: 300 EL PORTEL
Mailing City,St,Zip: HILLSBOROUGH, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: .7500
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler
Facility County: San Mateo

envid: S112871639
Year: 1999
GEPAID: CAC001172856
Contact: DON SABATINI
Telephone: 6506855666
Mailing Name: Not reported
Mailing Address: 300 EL PORTEL
Mailing City,St,Zip: HILLSBOROUGH, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Not reported

DON SABATINI (Continued) **S112871639**

Tons: 3.3360
Cat Decode: Not reported
Method Decode: Not reported
Facility County: San Mateo

envid: S112871639
Year: 1998
GEPAID: CAC001172856
Contact: DON SABATINI
Telephone: 6506855666
Mailing Name: Not reported
Mailing Address: 300 EL PORTEL
Mailing City,St,Zip: HILLSBOROUGH, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000180993
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Not reported
Tons: .9591
Cat Decode: Unspecified oil-containing waste
Method Decode: Not reported
Facility County: San Mateo

envid: S112871639
Year: 1998
GEPAID: CAC001172856
Contact: DON SABATINI
Telephone: 6506855666
Mailing Name: Not reported
Mailing Address: 300 EL PORTEL
Mailing City,St,Zip: HILLSBOROUGH, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD088838222
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Recycler
Tons: .9591
Cat Decode: Unspecified oil-containing waste
Method Decode: Recycler
Facility County: San Mateo

A15 **RODGER REINHART LESLIE MARSDEN** **HAZNET** **S112966920**
ESE **1241 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.070 mi.
372 ft. **Site 15 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

HAZNET:
envid: S112966920
Year: 2008
GEPAID: CAC002625227
Contact: RODGER REINHART
Telephone: 6508791674
Mailing Name: Not reported
Mailing Address: 1235 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: Not reported
TSD EPA ID: CAD982042475

RODGER REINHART LESLIE MARSDEN (Continued) **S112966920**

TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	2.8
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

A16 **UST SITE** **San Mateo Co. BI** **S113757182**
NE **361 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.071 mi.
374 ft. **Site 16 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0024618
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0029446
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

A17 **SABATINI TRUSTS** **HAZNET** **S113781386**
NE **361 CALIFORNIA DR** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.071 mi.
374 ft. **Site 17 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S113781386
Year:	2012
GEPAID:	CAC002695644
Contact:	MATT KEMPH
Telephone:	8314758141
Mailing Name:	Not reported
Mailing Address:	1 FAIROAKS CT
Mailing City,St,Zip:	SAN MATEO, CA 94403
Gen County:	San Mateo
TSD EPA ID:	CAD009466392
TSD County:	Contra Costa
Waste Category:	Not reported
Disposal Method:	Other Treatment
Tons:	0.25
Cat Decode:	Not reported
Method Decode:	Other Treatment
Facility County:	San Mateo

A18 **UST SITE** **San Mateo Co. BI** **S113759048**
NE **361 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.071 mi.
374 ft. **Site 18 of 60 in cluster A**

Relative: San Mateo Co. BI:
Lower

Region:	SAN MATEO
Facility ID:	FA0051675
Actual: Prog Element Code:	UNDERGROUND TANK - GENERAL
31 ft. Record Id:	PR0071628
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

A19 **SABATINI TRUST** **RGA LUST** **S114679957**
NE **361 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA**
0.071 mi.
374 ft. **Site 19 of 60 in cluster A**

Relative: RGA LUST:
Lower

2012 SABATINI TRUST 361 CALIFORNIA

Actual:
31 ft.

A20 **ANN TAYLOR S0497/BURLINGAME AVE** **HAZNET** **S112969597**
SSE **1325 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.071 mi.
375 ft. **Site 20 of 60 in cluster A**

Relative: HAZNET:
Higher

envid:	S112969597
Year:	2008
Actual: GEPAID:	CAC002629432
36 ft. Contact:	STEVEN ROOT/X121
Telephone:	2127516300
Mailing Name:	Not reported
Mailing Address:	200 VARICK ST
Mailing City,St,Zip:	NEW YORK, NY 10014
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.075
Cat Decode:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

A21
ESE
< 1/8
0.071 mi.
375 ft.

KIRKBRIDE PROPERTIES
1202 BURLINGAME AVE
BURLINGAME, CA 94010

Site 21 of 60 in cluster A

HAZNET **S112871016**
N/A

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112871016
Year:	1997
GEPAID:	CAC001166456
Contact:	BRUCE & HAROLD KIRKBRIBE,ELIZA
Telephone:	4153444470
Mailing Name:	Not reported
Mailing Address:	1229 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	46.3540
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

A22
ESE
< 1/8
0.072 mi.
380 ft.

1229 BURLINGAME AVE., BURLINGAME
BURLINGAME, CA 94010

Site 22 of 60 in cluster A

FINDS **1016991092**
ECHO **N/A**

Relative:
Higher

Actual:
34 ft.

FINDS:

Registry ID: 110020812138

Environmental Interest/Information System
US EPA Air Quality System (AQS) contains ambient air pollution data collected by EPA, State, Local, and Tribal air pollution control agencies from thousands of monitoring stations.

ECHO:

Envid:	1016991092
Registry ID:	110020812138
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110020812138

A23
ESE
< 1/8
0.072 mi.
380 ft.

GERRITSON PROPERTY
1229 BURLINGAME AVE
BURLINGAME, CA

Site 23 of 60 in cluster A

RGA LUST **S114626930**
N/A

Relative:
Higher

Actual:
34 ft.

RGA LUST:

1998	GERRITSON PROPERTY	1229 BURLINGAME AVE
1997	GERRITSON PROPERTY	1229 BURLINGAME AVE
1996	GERRITSON PROPERTY	1229 BURLINGAME AVE
1995	GERRITSON PROPERTY	1229 BURLINGAME AVE
1994	GERRITSON PROPERTY	1229 BURLINGAME AVE

GERRITSON PROPERTY (Continued) **S114626930**

1993 GERRITSON PROPERTY 1229 BURLINGAME AVE

A24 **KIM MILLS TEXACO (FORMER)** **RGA LUST** **S114639991**
North **401 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA**
0.073 mi.
386 ft. **Site 24 of 60 in cluster A**

Relative:
Lower

RGA LUST:

2012 KIM MILLS TEXACO (FORMER) 401 CALIFORNIA

Actual:
29 ft.

A25 **KIM MILLS TEXACO (FORMER)** **LUST** **S111711481**
North **401 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.073 mi.
386 ft. **Site 25 of 60 in cluster A**

Relative:
Lower

Actual:
29 ft.

LUST:

Region:	STATE
Global Id:	T10000003636
Latitude:	37.5806028815452
Longitude:	-122.347826957703
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/15/2012
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	660107
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Open/Close case, Opened 3/28/2012

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T10000003636
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T10000003636
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

KIM MILLS TEXACO (FORMER) (Continued) **S111711481**

Status History:
Global Id: T10000003636
Status: Completed - Case Closed
Status Date: 05/15/2012

Global Id: T10000003636
Status: Open - Case Begin Date
Status Date: 03/21/2012

Global Id: T10000003636
Status: Open - Verification Monitoring
Status Date: 03/28/2012

Regulatory Activities:
Global Id: T10000003636
Action Type: ENFORCEMENT
Date: 04/03/2012
Action: Notice of Responsibility - #20120403

Global Id: T10000003636
Action Type: ENFORCEMENT
Date: 05/15/2012
Action: Closure/No Further Action Letter - #20120515

Global Id: T10000003636
Action Type: Other
Date: 03/21/2012
Action: Leak Discovery

Global Id: T10000003636
Action Type: Other
Date: 03/27/2012
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660107
Facility Status: 9- Case Closed
Global ID: T100003636
APN Number: 029133200
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

A26 **UST SITE** **San Mateo Co. BI** **S113759021**
North **401 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.073 mi.
386 ft. **Site 26 of 60 in cluster A**

Relative:
Lower

Actual:
29 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0051083
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0070859
Description: UNDERGROUND TANK - GENERAL

UST SITE (Continued) **S113759021**

Facility Status: INACTIVE

A27
North
< 1/8
0.073 mi.
386 ft.

401 ALPROP LLC **HAZNET** **S113774798**
401 CALIFORNIA DR **N/A**
BURLINGAME, CA 94010

Site 27 of 60 in cluster A

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S113774798
Year:	2012
GEPAID:	CAC002687510
Contact:	MARCI PALATELLA
Telephone:	6506961700
Mailing Name:	Not reported
Mailing Address:	1199 HOWARD AVE STE 350
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	NVT330010000
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	1.35525
Cat Decode:	Not reported
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113774798
Year:	2012
GEPAID:	CAC002687510
Contact:	MARCI PALATELLA
Telephone:	6506961700
Mailing Name:	Not reported
Mailing Address:	1199 HOWARD AVE STE 350
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD009466392
TSD County:	Contra Costa
Waste Category:	Not reported
Disposal Method:	Other Treatment
Tons:	0.25
Cat Decode:	Not reported
Method Decode:	Other Treatment
Facility County:	San Mateo

A28 **UST SITE** **San Mateo Co. BI** **S113759022**
North **401 CALIFORNIA** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.073 mi.
386 ft. **Site 28 of 60 in cluster A**

Relative: **Lower**

Actual: **29 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0051084
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0070860
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

A29 **CITY NATIONAL BANK** **HAZNET** **S112902541**
SW **350 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94101**
0.074 mi.
389 ft. **Site 29 of 60 in cluster A**

Relative: **Higher**

Actual: **33 ft.**

HAZNET:

envid:	S112902541
Year:	2000
GEPAID:	CAC002192353
Contact:	STEVE KEENER
Telephone:	2133472617
Mailing Name:	Not reported
Mailing Address:	606 SO OLIVE 6TH FLR
Mailing City,St,Zip:	LOS ANGELES, CA 900140000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

A30 **REDLICH JR, CHRISTOPHER** **San Mateo Co. BI** **S113757752**
WSW **360 PRIMROSE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.074 mi.
393 ft. **Site 30 of 60 in cluster A**

Relative: **Higher**

Actual: **32 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0027489
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0043724
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

A31
NE
< 1/8
0.075 mi.
395 ft.

345 CALIFORNIA DR
BURLINGAME, CA 94010

Site 31 of 60 in cluster A

EDR Hist Cleaner **1015047032**
N/A

Relative:
Lower

Actual:
31 ft.

EDR Historical Cleaners:

Name:	J C CARPET & UPHOLSTERY CLEANING SPE
Year:	2011
Address:	345 CALIFORNIA DR
Name:	J C CARPET & UPHOLSTERY CLEANING SPE
Year:	2012
Address:	345 CALIFORNIA DR

A32
ESE
< 1/8
0.075 mi.
397 ft.

KARP FAMILY TRUST
1209 BURLINGAME
BURLINGAME, CA 94010

Site 32 of 60 in cluster A

HAZNET **S112920866**
N/A

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112920866
Year:	2002
GEPAID:	CAC002549947
Contact:	RON KARP
Telephone:	6503483055
Mailing Name:	Not reported
Mailing Address:	1209 BURLINGAME
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	5.89
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

A33
SSW
< 1/8
0.079 mi.
415 ft.

AW DEVELOPMENT INC
330 PRIMROSE RD STE 409
BURLINGAME, CA 94010

Site 33 of 60 in cluster A

HAZNET **S112987274**
N/A

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S112987274
Year:	2011
GEPAID:	CAC002667952
Contact:	VIERRA WONG
Telephone:	6503408133
Mailing Name:	Not reported
Mailing Address:	330 PRIMROSE RD STE 409
Mailing City,St,Zip:	BURLINGAME, CA 940104029
Gen County:	Not reported
TSD EPA ID:	AZR000501510
TSD County:	Not reported

AW DEVELOPMENT INC (Continued) **S112987274**

Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.02
Cat Decode:	Other organic solids
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S112987274
Year:	2011
GEPAID:	CAC002667952
Contact:	VIERRA WONG
Telephone:	6503408133
Mailing Name:	Not reported
Mailing Address:	330 PRIMROSE RD STE 409
Mailing City,St,Zip:	BURLINGAME, CA 940104029
Gen County:	Not reported
TSD EPA ID:	AZR000501510
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.02
Cat Decode:	Other organic solids
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

A34 **MIKE WOODS** **HAZNET** **S112871260**
SSW **330 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94401**
0.079 mi.
415 ft. **Site 34 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S112871260
Year:	1997
GEPAID:	CAC001168984
Contact:	MIKE WOODS
Telephone:	4153730701
Mailing Name:	Not reported
Mailing Address:	330 PRIMROSE RD STE 606
Mailing City,St,Zip:	BURLINGAME, CA 944010000
Gen County:	Not reported
TSD EPA ID:	AZR000005454
TSD County:	Not reported
Waste Category:	Polychlorinated biphenyls and material containing PCBs
Disposal Method:	Recycler
Tons:	2.5346
Cat Decode:	Polychlorinated biphenyls and material containing PCBs
Method Decode:	Recycler
Facility County:	San Mateo

A35
SSW
< 1/8
0.079 mi.
415 ft.

VERIZON WIRELESS EL CAMINO HOWARD
330 PRIMROSE RD STE 501
BURLINGAME, CA 94010

Site 35 of 60 in cluster A

FINDS **1016430609**
ECHO **N/A**

Relative:
Higher

Actual:
35 ft.

FINDS:

Registry ID: 110055816988

Environmental Interest/Information System
STATE MASTER

ECHO:

Envid:	1016430609
Registry ID:	110055816988
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110055816988

A36
SSW
< 1/8
0.079 mi.
415 ft.

VERIZON WIRELESS EL CAMINO HOWARD
BURLINGAME, CA 94010

Site 36 of 60 in cluster A

San Mateo Co. BI **S113757879**
N/A

Relative:
Higher

Actual:
35 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0027902
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0045802
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE

A37
SSE
< 1/8
0.081 mi.
426 ft.

AVTAR JOHAL FAMILY & TRUST
1301 BURLINGAME AVE
BURLINGAME, CA 94010

Site 37 of 60 in cluster A

HAZNET **S112926879**
N/A

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112926879
Year:	2003
GEPAID:	CAC002560076
Contact:	AVTAR JOHAL
Telephone:	6503420570
Mailing Name:	Not reported
Mailing Address:	1300 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

AVTAR JOHAL FAMILY & TRUST (Continued) **S112926879**

envid: S112926879
Year: 2002
GEPAID: CAC002560076
Contact: AVTAR JOHAL
Telephone: 6503420570
Mailing Name: Not reported
Mailing Address: 1300 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: Not reported
TSD EPA ID: CAD981382732
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 6.74
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

A38 **AUTAR JOHAL PROPERTY** **San Mateo Co. BI** **S113757785**
SSE **1301 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.081 mi.
426 ft. **Site 38 of 60 in cluster A**

Relative:
Higher

Actual:
36 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027566
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0044116
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

A39 **R & B EQUIPMENT** **HAZNET** **S112927677**
SSE **1301 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.081 mi.
426 ft. **Site 39 of 60 in cluster A**

Relative:
Higher

Actual:
36 ft.

HAZNET:
envid: S112927677
Year: 2003
GEPAID: CAC002561465
Contact: RICK JEFFERY
Telephone: 5107823774
Mailing Name: Not reported
Mailing Address: 2215 DUNN RD
Mailing City,St,Zip: HAYWARD, CA 94545
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: 1.5
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler
Facility County: San Mateo

A40
ENE
< 1/8
0.081 mi.
426 ft.

CAMMISSA MOTOR CAR CO
321 CALIFORNIA DR
BURLINGAME, CA 94010

Site 40 of 60 in cluster A

HAZNET **S113032542**
N/A

Relative:
Higher

Actual:
32 ft.

HAZNET:

envid:	S113032542
Year:	2004
GEPAID:	CAL000029239
Contact:	LARY CAMMISA / OWNER
Telephone:	6503407300
Mailing Name:	Not reported
Mailing Address:	1020 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940102506
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Recycler
Tons:	0.41
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113032542
Year:	2004
GEPAID:	CAL000029239
Contact:	LARY CAMMISA / OWNER
Telephone:	6503407300
Mailing Name:	Not reported
Mailing Address:	1020 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940102506
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Recycler
Tons:	0.41
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113032542
Year:	2000
GEPAID:	CAL000029239
Contact:	LARY CAMMISA / OWNER
Telephone:	6503407300
Mailing Name:	Not reported
Mailing Address:	1020 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940102506
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	1.04
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station

CAMMISSA MOTOR CAR CO (Continued) **S113032542**

Facility County: San Mateo

envid: S113032542
Year: 2000
GEPAID: CAL000029239
Contact: LARY CAMMISA / OWNER
Telephone: 6503407300
Mailing Name: Not reported
Mailing Address: 1020 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940102506
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Recycler
Tons: 0.22
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Recycler
Facility County: San Mateo

envid: S113032542
Year: 2000
GEPAID: CAL000029239
Contact: LARY CAMMISA / OWNER
Telephone: 6503407300
Mailing Name: Not reported
Mailing Address: 1020 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940102506
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Recycler
Tons: 0.22
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Recycler
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
19 additional CA_HAZNET: record(s) in the EDR Site Report.

A41 **CAMMISA MOTOR CAR CO** **EMI** **S106827930**
ENE **321 CALIFORNIA DRIVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.081 mi.
426 ft. **Site 41 of 60 in cluster A**

Relative:
Higher

Actual:
32 ft.

EMI:
Year: 1990
County Code: 41
Air Basin: SF
Facility ID: 3536
Air District Name: BA
SIC Code: 5511
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1

CAMMISA MOTOR CAR CO (Continued) **S106827930**

Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

A42 **GOLDEN STATE BREWING CO.** **HAZNET** **S112853582**
ENE **321 CALIFORNIA AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.081 mi.
426 ft. **Site 42 of 60 in cluster A**

Relative:
Higher

Actual:
32 ft.

HAZNET:

envid:	S112853582
Year:	1994
GEPAID:	CAC000926824
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	321 CALIFORNIA AVENUE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Disposal, Other
Tons:	.5000
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Disposal, Other
Facility County:	San Mateo

A43 **EDR Hist Cleaner** **1015045918**
SSW **339 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 43 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

EDR Historical Cleaners:

Name:	PRIMROSE CLEANERS
Year:	2001
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANERS
Year:	2003
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANERS
Year:	2004
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2005
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER

(Continued) **1015045918**

Year: 2006
Address: 339 PRIMROSE RD

Name: PRIMROSE CLEANER
Year: 2008
Address: 339 PRIMROSE RD

Name: PRIMROSE CLEANER
Year: 2010
Address: 339 PRIMROSE RD

Name: PRIMROSE CLEANER
Year: 2011
Address: 339 PRIMROSE RD

Name: PRIMROSE CLEANER
Year: 2012
Address: 339 PRIMROSE RD

A44 **PRIMROSE CLEANERS** **HAZNET** **S113156052**
SSW **339 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 44 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:
envid: S113156052
Year: 2014
GEPAID: CAL000343005
Contact: CHONG LEE OWNER
Telephone: 5104895722
Mailing Name: Not reported
Mailing Address: 30963 SAN BENITO ST
Mailing City,St,Zip: HAYWARD, CA 94544
Gen County: San Mateo
TSD EPA ID: CA0000084517
TSD County: Sacramento
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.18
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113156052
Year: 2012
GEPAID: CAL000343005
Contact: CHONG LEE OWNER
Telephone: 5104895722
Mailing Name: Not reported
Mailing Address: 30963 SAN BENITO ST
Mailing City,St,Zip: HAYWARD, CA 94544
Gen County: San Mateo
TSD EPA ID: CA0000084517
TSD County: Sacramento
Waste Category: Not reported

PRIMROSE CLEANERS (Continued) **S113156052**

Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.3
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113156052
Year:	2010
GEPAID:	CAL000343005
Contact:	CHONG LEE OWNER
Telephone:	5104895722
Mailing Name:	Not reported
Mailing Address:	30963 SAN BENITO ST
Mailing City,St,Zip:	HAYWARD, CA 94544
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.1
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113156052
Year:	2009
GEPAID:	CAL000343005
Contact:	CHONG LEE
Telephone:	6503432680
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Not reported
Tons:	0.15
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Not reported
Facility County:	San Mateo

A45 **PRIMROSE CLEANERS** **DRYCLEANERS** **S103892226**
SSW **339 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 45 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

DRYCLEANERS:

EPA Id:	CAL000343005
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial

PRIMROSE CLEANERS (Continued) **S103892226**

Create Date:	05/15/2009
Facility Active:	No
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	JAMES LEE
Owner Address:	30963 SAN BENITO ST
Owner Address 2:	Not reported
Owner Telephone:	5104895722
Contact Name:	CHONG LEE OWNER
Contact Address:	30963 SAN BENITO ST
Contact Address 2:	Not reported
Contact Telephone:	5104895722
Mailing Name:	Not reported
Mailing Address 1:	30963 SAN BENITO ST
Mailing Address 2:	Not reported
Mailing City:	HAYWARD
Mailing State:	CA
Mailing Zip:	94544
Owner Fax:	2
Region Code:	0000000000

A46 **PRIMROSE CLEANERS** **FINDS** **1004440249**
SSW **339 PRIMROSE ROAD** **EMI** **N/A**
< 1/8 **BURLINGAME, CA 94010** **ECHO**
0.083 mi.
439 ft. **Site 46 of 60 in cluster A**

Relative: Higher

Actual: 35 ft.

FINDS:

Registry ID: 110002412372

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

EMI:

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	4352
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	8628

PRIMROSE CLEANERS (Continued) **1004440249**

Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0

PRIMROSE CLEANERS (Continued) **1004440249**

Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

PRIMROSE CLEANERS (Continued) **1004440249**

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.196
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.256
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216

PRIMROSE CLEANERS (Continued) **1004440249**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.317
Reactive Organic Gases Tons/Yr:	.2214562
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.155
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.155
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.16200000000000001
Reactive Organic Gases Tons/Yr:	0.1131732
Carbon Monoxide Emissions Tons/Yr:	0

PRIMROSE CLEANERS (Continued) **1004440249**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.162
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	8628
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.162
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

ECHO:

Envid:	1004440249
Registry ID:	110002412372
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002412372

A47 **PRIMROSE CLEANERS** **San Mateo Co. BI** **S113755385**
SSW **339 PRIMROSE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 47 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0056769
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0078772
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

PRIMROSE CLEANERS (Continued) **S113755385**

Region:	SAN MATEO
Facility ID:	FA0056769
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0078771
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0007475
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011893
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0007475
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0026812
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

A48 **NEW GATES GLOBE CLEANERS** **HAZNET** **S113031438**
SSW **339 PRIMROSE ROAD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 48 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S113031438
Year:	2009
GEPAID:	CAL000026929
Contact:	INACTIVE/VALID #CAL000013474
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE ROAD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.15
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

A49 **GATES GLOBE CLEANERS** **HAZNET** **S113026229**
SSW **339 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.083 mi.
439 ft. **Site 49 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S113026229
Year:	1997
GEPAID:	CAL000013474
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.3525
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113026229
Year:	1996
GEPAID:	CAL000013474
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.0975
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113026229
Year:	1996
GEPAID:	CAL000013474
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CAO000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.0600
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station

GATES GLOBE CLEANERS (Continued) **S113026229**

Facility County:	San Mateo
envid:	S113026229
Year:	1995
GEPAID:	CAL000013474
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CAT000613950
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.2550
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	S113026229
Year:	1994
GEPAID:	CAL000013474
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	339 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CAT000613893
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.1875
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
4 additional CA_HAZNET: record(s) in the EDR Site Report.

A50 **GW WILLIAMS COMPANY** **HAZNET** **S112887271**
SSW **329 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.084 mi.
441 ft. **Site 50 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S112887271
Year:	1998
GEPAID:	CAC001389640
Contact:	GW WILLIAMS COMPANY
Telephone:	6503729711
Mailing Name:	Not reported
Mailing Address:	3190 CLEARVIEW WY
Mailing City,St,Zip:	SAN MATEO, CA 944020000
Gen County:	Not reported
TSD EPA ID:	CAD981382732

GW WILLIAMS COMPANY (Continued) **S112887271**

TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 2.9498
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

A51 **WOODSTOCK-BOWERS LLC** **HAZNET** **S113786051**
SSW **329 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.084 mi.
441 ft. **Site 51 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

HAZNET:
envid: S113786051
Year: 2012
GEPAID: CAC002701480
Contact: KIRK SYME
Telephone: 6505791901
Mailing Name: Not reported
Mailing Address: 330 PRIMROSE RD STE 203
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD982042475
TSD County: Solano
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 8
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

A52 **EDR Hist Cleaner** **1015045718**
SSW **337 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.084 mi.
442 ft. **Site 52 of 60 in cluster A**

Relative:
Higher

Actual:
35 ft.

EDR Historical Cleaners:
Name: DIRTY LAUNDRY
Year: 2005
Address: 337 PRIMROSE RD

A53 **SEPHORA STORE 52 BURLINGGAME** **FINDS** **1007087646**
ESE **1205 BURLINGAME AVENUE** **ECHO** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 53 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

FINDS:

Registry ID: 110015671913

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1007087646
Registry ID: 110015671913
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110015671913

A54 **HARRIS & CRISAFI C/O RRM, INC** **FINDS** **1011978897**
ESE **1205 HOWARD AVENUE** **ECHO** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 54 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

FINDS:

Registry ID: 110038081535

Environmental Interest/Information System

AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011978897
Registry ID: 110038081535
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038081535

A55 **HARRIS & CRISAFI C/O RRM, INC** **EMI** **S107621093**
ESE **1205 HOWARD AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 55 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.008
Reactive Organic Gases Tons/Yr:	.0055888
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.064
Reactive Organic Gases Tons/Yr:	.0447104
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007

HARRIS & CRISAFI C/O RRM, INC (Continued) **S107621093**

County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.094
Reactive Organic Gases Tons/Yr:	.0656684
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.097
Reactive Organic Gases Tons/Yr:	.0677642
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.1999999999999999E-2
Reactive Organic Gases Tons/Yr:	0.0153692
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	16013
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD

HARRIS & CRISAFI C/O RRM, INC (Continued) **S107621093**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.1999999999999999E-2
Reactive Organic Gases Tons/Yr:	0.0153692
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

A56 **SEPHORA STORE 52 BURLINGGAME** **RCRA-SQG** **1006930241**
ESE **1205 BURLINGAME AVENUE** **CAR000147256**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 56 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

RCRA-SQG:

Date form received by agency:	08/19/2003
Facility name:	SEPHORA STORE 52 BURLINGGAME
Facility address:	1205 BURLINGAME AVENUE BURLINGAME, CA 94010
EPA ID:	CAR000147256
Mailing address:	525 MARKET STREET SAN FRANCISCO, CA 94105
Contact:	SANDI BAKER
Contact address:	525 MARKET STREET SAN FRANCISCO, CA 94105
Contact country:	US
Contact telephone:	415-348-3488
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	KARP COMPANIES
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	09/13/2002
Owner/Op end date:	Not reported
Owner/operator name:	SEPHORA
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/13/2002

SEPHORA STORE 52 BURLINGGAME (Continued) **1006930241**

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

A57 **KARP FAMILY TRUST** **HAZNET** **S112928741**
ESE **1205 BURLINGAME AVE/283LORTON AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 57 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112928741
Year:	2003
GEPAID:	CAC002563355
Contact:	RON KARP
Telephone:	6503483055
Mailing Name:	Not reported
Mailing Address:	PO BOX 271
Mailing City,St,Zip:	BURLINGAME, CA 94011
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

A58 **SEPHORA #052** **San Mateo Co. BI** **S113758480**
ESE **1205 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 58 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0038931
Prog Element Code:	GEN <1 TONS HAZ WASTE/YR
Record Id:	PR0055206
Description:	GEN <1 TONS HAZ WASTE/YR
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0038931
Prog Element Code:	BUSINESS PLAN - GENERAL
Record Id:	PR0065034
Description:	BUSINESS PLAN - GENERAL
Facility Status:	INACTIVE

A59 **SEPHORA STORE 52 BURLINGGAME** **HAZNET** **S113177406**
ESE **1205 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.085 mi.
451 ft. **Site 59 of 60 in cluster A**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S113177406
Year:	2008
GEPAID:	CAR000147256
Contact:	SANDI BAKER FACILITIES MGR
Telephone:	4152843488
Mailing Name:	Not reported
Mailing Address:	425 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052708
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.099
Cat Decode:	Off-specification, aged or surplus organics
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113177406
Year:	2008
GEPAID:	CAR000147256
Contact:	SANDI BAKER FACILITIES MGR
Telephone:	4152843488
Mailing Name:	Not reported
Mailing Address:	425 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052708
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics

SEPHORA STORE 52 BURLINGGAME (Continued) **S113177406**

Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.099
Cat Decode:	Off-specification, aged or surplus organics
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113177406
Year:	2008
GEPAID:	CAR000147256
Contact:	SANDI BAKER FACILITIES MGR
Telephone:	4152843488
Mailing Name:	Not reported
Mailing Address:	425 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052708
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.227
Cat Decode:	Off-specification, aged or surplus organics
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

envid:	S113177406
Year:	2008
GEPAID:	CAR000147256
Contact:	SANDI BAKER FACILITIES MGR
Telephone:	4152843488
Mailing Name:	Not reported
Mailing Address:	425 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052708
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.227
Cat Decode:	Off-specification, aged or surplus organics
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

envid:	S113177406
Year:	2007
GEPAID:	CAR000147256
Contact:	SANDI BAKER FACILITIES MGR
Telephone:	4152843488
Mailing Name:	Not reported
Mailing Address:	425 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052708
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site

SEPHORA STORE 52 BURLINGGAME (Continued) **S113177406**

Tons: 0.25
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Fuel Blending Prior To Energy Recovery At Another Site
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
19 additional CA_HAZNET: record(s) in the EDR Site Report.

A60 **CITY OF BURLINGAME** **HAZNET** **S112870253**
West **480 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.088 mi.
464 ft. **Site 60 of 60 in cluster A**

Relative:
Lower

Actual:
31 ft.

HAZNET:
envid: S112870253
Year: 1996
GEPAID: CAC001158096
Contact: CITY OF BURLINGAME
Telephone: 4156967230
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 25.2840
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

envid: S112870253
Year: 1996
GEPAID: CAC001158096
Contact: CITY OF BURLINGAME
Telephone: 4156967230
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAT000646117
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Not reported
Tons: 2.9498
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Not reported
Facility County: San Mateo

envid: S112870253
Year: 1996
GEPAID: CAC001158096
Contact: CITY OF BURLINGAME
Telephone: 4156967230
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD

CITY OF BURLINGAME (Continued) **S112870253**

Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Polychlorinated biphenyls and material containing PCBs
Disposal Method:	Disposal, Land Fill
Tons:	2.9498
Cat Decode:	Polychlorinated biphenyls and material containing PCBs
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

B61 **AVENUE PLAZA** **HAZNET** **S112871346**
East **1110 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.094 mi.
494 ft. **Site 1 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112871346
Year:	1998
GEPAID:	CAC001169864
Contact:	LORENZ & LOUISA KAO
Telephone:	6503427955
Mailing Name:	Not reported
Mailing Address:	1110 BURLINGAME AVE, #300
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	7.5060
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112871346
Year:	1998
GEPAID:	CAC001169864
Contact:	LORENZ & LOUISA KAO
Telephone:	6503427955
Mailing Name:	Not reported
Mailing Address:	1110 BURLINGAME AVE, #300
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Not reported
Tons:	.1876
Cat Decode:	Waste oil and mixed oil
Method Decode:	Not reported
Facility County:	San Mateo

B62 **AVENUE PLAZA** **HAZNET** **S112871018**
East **1110 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.094 mi.
494 ft. **Site 2 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112871018
Year:	1997
GEPAID:	CAC001166480
Contact:	ZEKA GROUP
Telephone:	4153427997
Mailing Name:	Not reported
Mailing Address:	1110 BURLINGAME AVE, #300
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.1668
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

C63 **LW DESIGN HAIR SALON** **HAZNET** **S112971078**
SSW **309 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.097 mi.
512 ft. **Site 1 of 19 in cluster C**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S112971078
Year:	2008
GEPAID:	CAC002631696
Contact:	LAURA RIGHT
Telephone:	6503438612
Mailing Name:	Not reported
Mailing Address:	309 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940104004
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

C64 **PICKRELL D J** **SEMS-ARCHIVE** **1003878368**
WSW **1408 CHAPIN AVE** **CAD074632522**
< 1/8 **BURLINGAME, CA 94010**
0.098 mi.
519 ft. **Site 2 of 19 in cluster C**

Relative:
Higher

Actual:
33 ft.

SEMS-ARCHIVE:
Site ID: 901576
EPA ID: CAD074632522
Federal Facility: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:
Site ID: 0901576
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 13287240.00000
Person ID: 13003854.00000

Contact Sequence ID: 13292835.00000
Person ID: 13003858.00000

Contact Sequence ID: 13298693.00000
Person ID: 13004003.00000

CERCLIS-NFRAP Assessment History:
Action: DISCOVERY
Date Started: / /
Date Completed: 12/01/79
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 12/01/87
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 12/01/87
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

---

B65 **88 PHOTO LAB** **San Mateo Co. BI** **S113757419**
East **1109 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.099 mi.
524 ft. **Site 3 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0025962
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0037389
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

88 PHOTO LAB (Continued) **S113757419**

Region:	SAN MATEO
Facility ID:	FA0025962
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0037390
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

B66 **88 PHOTO LAB** **HAZNET** **S113168999**
East **1109 BURLINGAME AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.099 mi.
524 ft. **Site 4 of 35 in cluster B**

Relative: **Higher**

Actual: **34 ft.**

HAZNET:

envid:	S113168999
Year:	2003
GEPAID:	CAL930225842
Contact:	--
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1109 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104105
Gen County:	Not reported
TSD EPA ID:	CAD981429673
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	0.12
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113168999
Year:	2002
GEPAID:	CAL930225842
Contact:	--
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1109 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104105
Gen County:	Not reported
TSD EPA ID:	CAD981429673
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	0.18
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113168999
Year:	2001
GEPAID:	CAL930225842
Contact:	--
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1109 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104105

88 PHOTO LAB (Continued) **S113168999**

Gen County:	Not reported
TSD EPA ID:	CAD981429673
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	0.37
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113168999
Year:	2000
GEPAID:	CAL930225842
Contact:	--
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1109 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104105
Gen County:	Not reported
TSD EPA ID:	CAD981429673
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	1.18
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113168999
Year:	1998
GEPAID:	CAL930225842
Contact:	88 PHOTO LAB
Telephone:	4155797768
Mailing Name:	Not reported
Mailing Address:	1109 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104105
Gen County:	Not reported
TSD EPA ID:	CAL000121946
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	.0625
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
4 additional CA_HAZNET: record(s) in the EDR Site Report.

B67 **CRYO CREAM** **San Mateo Co. BI** **S113755187**
SE **240 PARK** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.100 mi.
530 ft. **Site 5 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0000510
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0074131
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

C68 **HAAG N HAAG** **HAZNET** **S113074031**
SSW **1402 BURLINGAME AVENUE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.101 mi.
532 ft. **Site 3 of 19 in cluster C**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S113074031
Year:	2000
GEPAID:	CAL000130501
Contact:	DAVE WINSLOW
Telephone:	4153473456
Mailing Name:	Not reported
Mailing Address:	92 E 3RD AVE
Mailing City,St,Zip:	SAN MATEO, CA 944014011
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	0.45
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113074031
Year:	1998
GEPAID:	CAL000130501
Contact:	STEPHEN HAAG/PRESIDENT
Telephone:	4153434224
Mailing Name:	Not reported
Mailing Address:	92 E 3RD AVE
Mailing City,St,Zip:	SAN MATEO, CA 944014011
Gen County:	Not reported
TSD EPA ID:	CAT080025711
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	1.6680
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113074031
Year:	1997
GEPAID:	CAL000130501

HAAG N HAAG (Continued) **S113074031**

Contact:	STEPHEN HAAG/PRESIDENT
Telephone:	4153434224
Mailing Name:	Not reported
Mailing Address:	92 E 3RD AVE
Mailing City,St,Zip:	SAN MATEO, CA 944014011
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	1.7514
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113074031
Year:	1996
GEPAID:	CAL000130501
Contact:	STEPHEN HAAG/PRESIDENT
Telephone:	4153434224
Mailing Name:	Not reported
Mailing Address:	92 E 3RD AVE
Mailing City,St,Zip:	SAN MATEO, CA 944014011
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	2.1684
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113074031
Year:	1995
GEPAID:	CAL000130501
Contact:	STEPHEN HAAG/PRESIDENT
Telephone:	4153434224
Mailing Name:	Not reported
Mailing Address:	92 E 3RD AVE
Mailing City,St,Zip:	SAN MATEO, CA 944014011
Gen County:	Not reported
TSD EPA ID:	CAD003963592
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Recycler
Tons:	1.3761
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

C69 **JOSEPH KARP** **HAZNET** **S112892341**
SW **1411 CHAPIN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.101 mi.
535 ft. **Site 4 of 19 in cluster C**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112892341
Year:	2001
GEPAID:	CAC001446088
Contact:	JOSEPH KARP
Telephone:	6503483055
Mailing Name:	Not reported
Mailing Address:	PO BOX 271
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	10.95
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

C70 **EDWARD ZUKAUSKAS** **HAZNET** **S113791207**
SSW **1410 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.110 mi.
581 ft. **Site 5 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S113791207
Year:	2012
GEPAID:	CAC002709300
Contact:	EDWARD ZUKAUSKAS
Telephone:	5307556931
Mailing Name:	Not reported
Mailing Address:	1410 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104111
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

D71
NNE
< 1/8
0.110 mi.
582 ft.

CITY OF BURLINGAME
425 CAROLAN AVENUE
BURLINGAME, CA 94010

Site 1 of 18 in cluster D

FINDS **1011976288**
ECHO **N/A**

Relative:
Lower

Actual:
28 ft.

FINDS:

Registry ID: 110038089396

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011976288
Registry ID:	110038089396
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110038089396

D72
NNE
< 1/8
0.110 mi.
582 ft.

CITY OF BURLINGAME
425 CAROLAN AVENUE
BURLINGAME, CA 94010

Site 2 of 18 in cluster D

EMI **S107620536**
N/A

Relative:
Lower

Actual:
28 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.006
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	.001
NOX - Oxides of Nitrogen Tons/Yr:	.006
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CITY OF BURLINGAME (Continued) **S107620536**

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	.001
NOX - Oxides of Nitrogen Tons/Yr:	.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199

CITY OF BURLINGAME (Continued) **S107620536**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001

CITY OF BURLINGAME (Continued) **S107620536**

NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	14468
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.00023644
Reactive Organic Gases Tons/Yr:	0.000230196
Carbon Monoxide Emissions Tons/Yr:	0.000714
NOX - Oxides of Nitrogen Tons/Yr:	0.001465631
SOX - Oxides of Sulphur Tons/Yr:	1.522e-006
Particulate Matter Tons/Yr:	0.000244485
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000234706

E73 **JOHN K LEUNG DDS** **HAZNET** **S113086619**
WNW **500 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.111 mi.
586 ft. **Site 1 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S113086619
Year:	2006
GEPAID:	CAL000162042
Contact:	JOHN K LEUNG DDS
Telephone:	6503432120
Mailing Name:	Not reported
Mailing Address:	500 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103907
Gen County:	Not reported
TSD EPA ID:	CAD981429673
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste

JOHN K LEUNG DDS (Continued) **S113086619**

Disposal Method: Recycler
Tons: 0.02
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113086619
Year: 2005
GEPAID: CAL000162042
Contact: JOHN K LEUNG DDS
Telephone: 6503432120
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103907
Gen County: Not reported
TSD EPA ID: CAD981429673
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: 0.04
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113086619
Year: 2003
GEPAID: CAL000162042
Contact: JOHN K LEUNG DDS
Telephone: 6503432120
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103907
Gen County: Not reported
TSD EPA ID: CAD981429673
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: 0.03
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113086619
Year: 2001
GEPAID: CAL000162042
Contact: JOHN K LEUNG DDS
Telephone: 6503432120
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103907
Gen County: Not reported
TSD EPA ID: CAD981429673
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: 0.04
Cat Decode: Photochemicals/photoprocessing waste

JOHN K LEUNG DDS (Continued) **S113086619**

Method Decode: Recycler
Facility County: San Mateo

envid: S113086619
Year: 1999
GEPAID: CAL000162042
Contact: DR JOHN K LEUNG
Telephone: 6503432120
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103907
Gen County: Not reported
TSD EPA ID: CAL000121946
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .0291
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

E74 **DR SCOTT HALLSTED** **HAZNET** **S113091650**
WNW **500 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.111 mi.
586 ft. **Site 2 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

HAZNET:
envid: S113091650
Year: 2014
GEPAID: CAL000174200
Contact: SHEILA REED-OFFICE MANAGER
Telephone: 6503431104
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAD981429673
TSD County: Marin
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.06255
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

envid: S113091650
Year: 2013
GEPAID: CAL000174200
Contact: SHEILA REED-OFFICE MANAGER
Telephone: 6503431104
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo

DR SCOTT HALLSTED (Continued) **S113091650**

TSD EPA ID: CAD981429673
TSD County: Marin
Waste Category: Not reported
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.06255
Cat Decode: Not reported
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: Not reported

envid: S113091650
Year: 2012
GEPAID: CAL000174200
Contact: SHEILA REED-OFFICE MANAGER
Telephone: 6503431104
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAD981429673
TSD County: Marin
Waste Category: Not reported
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.06255
Cat Decode: Not reported
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

envid: S113091650
Year: 2012
GEPAID: CAL000174200
Contact: SHEILA REED-OFFICE MANAGER
Telephone: 6503431104
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAD981429673
TSD County: Marin
Waste Category: Not reported
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.06255
Cat Decode: Not reported
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

envid: S113091650
Year: 2012
GEPAID: CAL000174200
Contact: SHEILA REED-OFFICE MANAGER
Telephone: 6503431104
Mailing Name: Not reported
Mailing Address: 500 PRIMROSE ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAD981429673
TSD County: Marin
Waste Category: Not reported

DR SCOTT HALLSTED (Continued) **S113091650**

Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.06255
Cat Decode: Not reported
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
39 additional CA_HAZNET: record(s) in the EDR Site Report.

C75 **LINO NICCOLI** **HAZNET** **S113780289**
South **277 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.113 mi.
599 ft. **Site 6 of 19 in cluster C**

Relative: **Higher**

Actual: **38 ft.**

HAZNET:
envid: S113780289
Year: 2012
GEPAID: CAC002694334
Contact: LINO NICCOLI
Telephone: 5099431862
Mailing Name: Not reported
Mailing Address: 277 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

E76 **BURLINGAME CITY HALL** **HAZNET** **S112961899**
West **501 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 3 of 14 in cluster E**

Relative: **Lower**

Actual: **29 ft.**

HAZNET:
envid: S112961899
Year: 2007
GEPAID: CAC002617396
Contact: PHILLIP MONAGHAN
Telephone: 6505587241
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103906
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration,

BURLINGAME CITY HALL (Continued) **S112961899**

Organics Recovery Ect
Tons: 0.5
Cat Decode: Unspecified oil-containing waste
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

envid: S112961899
Year: 2007
GEPAID: CAC002617396
Contact: PHILLIP MONAGHAN
Telephone: 6505587241
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103906
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 1.9
Cat Decode: Waste oil and mixed oil
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

E77 **CITY OF BURLINGAME** **FINDS** **1011978868**
West **501 PRIMROSE ROAD** **ECHO** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 4 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

FINDS:

Registry ID: 110038068667

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011978868
Registry ID: 110038068667
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038068667

E78 **CITY OF BURLINGAME** **HAZNET** **S112967754**
West **501 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 5 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112967754
Year:	2008
GEPAID:	CAC002626525
Contact:	PATTY FRENCH
Telephone:	6505587381
Mailing Name:	Not reported
Mailing Address:	501 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103906
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

E79 **CITY OF BURLINGAME** **HAZNET** **S112996317**
West **501 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 6 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112996317
Year:	2011
GEPAID:	CAC002679613
Contact:	CYNTHIA RIPLEY
Telephone:	6505587691
Mailing Name:	Not reported
Mailing Address:	501 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103906
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

E80 **CTY OF SAN MATEO** **San Mateo Co. BI** **S113796067**
West **501 PRIMROSE RD** **HAZNET** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 7 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0054565
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0075252
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

HAZNET:

envid:	S113796067
Year:	2012
GEPAID:	CAH111000675
Contact:	PETE SMITH
Telephone:	6505991600
Mailing Name:	Not reported
Mailing Address:	590 HAMILTON ST 4TH FLOOR
Mailing City,St,Zip:	REDWOOD CITY, CA 940630000
Gen County:	San Mateo
TSD EPA ID:	ARD981057870
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	2.275
Cat Decode:	Not reported
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

E81 **CITY OF BURLINGAME** **HAZNET** **S112913763**
West **501 PRIMROSE RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 8 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112913763
Year:	2001
GEPAID:	CAC002345303
Contact:	ARAHN BECKER/MGR
Telephone:	6505587222
Mailing Name:	Not reported
Mailing Address:	501 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

E82 **CITY OF BURLINGAME** **EMI** **S107620537**
West **501 PRIMROSE ROAD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.116 mi.
610 ft. **Site 9 of 14 in cluster E**

Relative:
Lower

Actual:
29 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.003
NOX - Oxides of Nitrogen Tons/Yr:	0.012
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000976

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.003
NOX - Oxides of Nitrogen Tons/Yr:	.012
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.000976

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007

CITY OF BURLINGAME (Continued) **S107620537**

County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	.003
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	3.0000000000000001E-3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD

CITY OF BURLINGAME (Continued) **S107620537**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0.001
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0.001

CITY OF BURLINGAME (Continued) **S107620537**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	14474
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.4932e-005
Reactive Organic Gases Tons/Yr:	5.0025e-005
Carbon Monoxide Emissions Tons/Yr:	8.3376e-005
NOX - Oxides of Nitrogen Tons/Yr:	0.00103484
SOX - Oxides of Sulphur Tons/Yr:	1.196e-006
Particulate Matter Tons/Yr:	1.7556e-005
Part. Matter 10 Micrometers and Smllr Tons/Yr:	1.6854e-005

D83 **SAN MATEO UNION HIGH SCHOOL DIST.** **HAZNET** **S113139565**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 3 of 18 in cluster D**

Relative: **Lower**

Actual: **28 ft.**

HAZNET:

envid:	S113139565
Year:	2014
GEPAID:	CAL000299728
Contact:	SARA DWIGHT
Telephone:	6505582470
Mailing Name:	Not reported
Mailing Address:	650 N DELAWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 944011732
Gen County:	San Mateo
TSD EPA ID:	CAD008364432
TSD County:	Los Angeles
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.01
Cat Decode:	Other inorganic solid waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113139565
Year:	2012
GEPAID:	CAL000299728
Contact:	VICTOR TALAVERA
Telephone:	6505582470
Mailing Name:	Not reported
Mailing Address:	650 N DELAWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 944011732
Gen County:	San Mateo
TSD EPA ID:	ARD069748192

SAN MATEO UNION HIGH SCHOOL DIST. (Continued) **S113139565**

TSD County: 99
Waste Category: Not reported
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.005
Cat Decode: Not reported
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: San Mateo

envid: S113139565
Year: 2012
GEPAID: CAL000299728
Contact: VICTOR TALAVERA
Telephone: 6505582470
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 944011732
Gen County: San Mateo
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0294
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113139565
Year: 2012
GEPAID: CAL000299728
Contact: VICTOR TALAVERA
Telephone: 6505582470
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 944011732
Gen County: San Mateo
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.01251
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113139565
Year: 2011
GEPAID: CAL000299728
Contact: P. BRUCE/TRANS.
Telephone: 6505582444
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 944011732
Gen County: Not reported

SAN MATEO UNION HIGH SCHOOL DIST. (Continued) **S113139565**

TSD EPA ID: ARD069748192
TSD County: Not reported
Waste Category: Laboratory waste chemicals
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.0075
Cat Decode: Laboratory waste chemicals
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
23 additional CA_HAZNET: record(s) in the EDR Site Report.

D84 **BURLINGAME HIGH SCHOOL** **FINDS** **1008295556**
NNE **400 CAROLAN AVENUE** **ECHO** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 4 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

FINDS:

Registry ID: 110021905143

Environmental Interest/Information System
California Department of Toxic Substances Control EnviroStor System (DTSC-EnviroStor) is an online search and Geographic Information System (GIS) tool for identifying sites that have known contamination or sites for which there may be reasons to investigate further. The EnviroStor database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites.

ECHO:
Envid: 1008295556
Registry ID: 110021905143
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110021905143

D85 **BURLINGAME HIGH SCHOOL** **ENVIROSTOR** **S103986521**
NNE **400 CAROLAN AVENUE** **SCH** **N/A**
< 1/8 **BURLINGAME, CA 94010** **DEED**
0.117 mi.
616 ft. **Site 5 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

ENVIROSTOR:
Facility ID: 41820008
Status: Certified / Operation & Maintenance
Status Date: 08/04/2011
Site Code: 204083
Site Type: School Cleanup
Site Type Detailed: School
Acres: 22
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Mellan Songco

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Supervisor: Jose Salcedo
Division Branch: Northern California Schools & Santa Susana
Assembly: 22
Senate: 13
Special Program: Not reported
Restricted Use: YES
Site Mgmt Req: NONE SPECIFIED
Funding: School District
Latitude: 37.58249
Longitude: -122.3468
APN: 026290380, 029-141-010, 029141010
Past Use: UNKNOWN, SCHOOL - HIGH SCHOOL
Potential COC: Arsenic Lead Polychlorinated biphenyls (PCBs
Confirmed COC: Arsenic Polychlorinated biphenyls (PCBs Lead
Potential Description: SOIL, SOIL
Alias Name: BURLINGAME HIGH SCHOOOL
Alias Type: Alternate Name
Alias Name: SAN MATEO UHSD-BURLINGAME HIGH
Alias Type: Alternate Name
Alias Name: SAN MATEO UNION HIGH SCHOOL DISTRICT
Alias Type: Alternate Name
Alias Name: 026290380
Alias Type: APN
Alias Name: 029-141-010
Alias Type: APN
Alias Name: 029141010
Alias Type: APN
Alias Name: 110021905143
Alias Type: EPA (FRS #)
Alias Name: 204083
Alias Type: Project Code (Site Code)
Alias Name: 41820008
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/16/2001
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 11/05/2002
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 09/06/2007
Comments: Office of Env. Planning & Analysis has approved the NOE. Division signatures will be added to the tracking form when the RAW is approved.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date: 10/01/2007
Comments: DTSC issued approval to begin construction on the rear athletic field.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 01/25/2007
Comments: Sharon received a draft response letter from the District that did not comply with the DNONC. Comments were written on the response; Additional internal meetings are needed to determine if an order will be issued.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/05/2007
Comments: Held a face-to-face meeting to discuss outstanding issues for the project: Schedule for remainder of activities; Discussion regarding remediation in the planter boxes. Discussed a couple of options for the planter boxes; the District will include their final recommendation for their remediation in the arsenic RAW.

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/02/2007
Comments: Site Visit to oversee confirmation sampling for PCB remediation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/30/2007
Comments: Phone conference to discuss 1. Fact sheet; 2. Start of the Lead/PCB removal; 3. Recent arsenic characterization; 4. Meeting in DTSC Berkeley Office to develop the dates for the remaining of the remediation activities.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/22/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/08/2007
Comments: Meet with Kim, Diane and Mark to discuss the work notice Kim prepared for Burlingame. Based on the significant amount of time that has lapsed since the last communication from DTSC to the community, Fact Sheet was recommended instead of a work notice. It will include the dates of the PCB and lead removals as well as a date on the additional arsenic investigation. A reference will be made regarding the arsenic removal, but no specific date will be mentioned.

Completed Area Name: PROJECT WIDE

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	02/01/2007
Comments:	Project Team to discuss outstanding issues for project: fence the PCB area; financal capabilities of the District; look up the requirements for proper signage and will send it to Burlingame via email; Cost Estimates to complete all of the work at BHS- cost to complete the PCB and Lead removal actions, cost to completed and arsenic characterization; prepare another timeline of tasks that need to be completed; Stabalization of site press release and future fact sheets; Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	01/29/2007
Comments:	Project team discussed Measure M (Proposition 39) that was passed in November 06 for $298,000,000. discussed if an Imminent and Substantial Endangerment order would appropriate to issue or , a Determination of Non-Compliance (DoNC) or a Fence and Post on a temporary fence
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	12/26/2006
Comments:	Meeting to discuss: the letter of proposed Determination of Non-Compliance was signed and sent to the District and the letter sent to the City of Burlingame (Jim Nantell) . The DNONC identified three thing: Completion of removal action for lead and PCBs around the main building and a submittal of a RACR; Submittal of an SSI to document the extent of arsenic-contamination on BHS; and submittal of a RAW to address the mitigation of arsenic. District to provide a response by January 17, 2007
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	School Cleanup Agreement
Completed Date:	10/12/2005
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	08/25/2008
Comments:	DTSC issued a letter to the District outlining the current status of the project and requesting a response to DTSC comments regarding the RACR and a schedule of mitigation activities.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	12/03/2009
Comments:	Not reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Document Type:	Operation & Maintenance Order/Agreement
Completed Date:	08/04/2009
Comments:	DTSC issued a fully executed Operation and Maintenance Agreement.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	01/04/2013
Comments:	On January 4, 2013, the County of San Mateo recorded the land use covenant for the Burlingame High School.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/10/2013
Comments:	On July 10, 2013, DTSC participated on the annual site inspection with Victor Talavera and Patrick Sing (District), and Wes Hawthorne (Locus).
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	06/18/2012
Comments:	DTSC participated in the annual arsenic inspection at the Burlingame HS with Zeke Lyles and Wes Hawthorne. The Burlingame HS is still undergoing modernization. DTSC was notified by W. Hawthorne that Victor Talaveras (Arsenic Coordinator) is aware of the project and is monitoring the progress of the modernization project to ensure that if any of the areas of concern is impacted the proper SOP will be followed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/09/2014
Comments:	On July 9, 2014, DTSC participated on the 5-Year review inspection of the cap at the site with the District representatives Sara Dwight (Arsenic Coordinator), Ricky Carrillo (Plant Manager), Wes Hawthorne (Locus Technologies). Cap measurements were taken at two areas in Area E and both areas meet or exceeds the minimum cap thickness.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	08/21/2015
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	08/27/2009
Comments:	Project Manager Change
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	06/28/2010

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/04/2013
Comments: On December 2, 2013, DTSC was notified via email from Mr. Victor Talaveras (District's Arsenic Coordinator) that Building F (Home Economics Building) will be demolished which would impact Areas G and C identified in the DTSC-approved O&M Plan. The proposed schedule for the demolition work is from December 16, 2013 until January 24, 2014. Mr. Talaveras stated that the SOP included in the approved O&M Plan will be implemented for this project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/20/2011
Comments: DTSC conducted the 2011 Annual Arsenic Inpection with Zeke Lyles, District's Arsenic Coordinator; J. Wesley Hawthorne (Locus Technologies), O&M Professional; and, George. The following were observed during the walkthrough: bare soils w/ mesh visible around some trees in Area E; some of the planters in Area F2 needs additional granite; Area C behind building C and by the library needs additional wood chips to fill bald spots around plants; a new building D is almost complete - need to verify if Area C is beneath the new building; some of the Area C around the gym that is not concreted needs woodchips to fill bald spots. Z. Lyles mentioned that after the ongoing modernization he is planning on putting concrete over the grassy area around the gym instead on maintaning the grass. The trees will stay and the root area will have bark as covering. Currently, area soil is exposed. During the site inspection Z. Lyles mentioned that the parking area in the south side of the site will be re-finished in the coming months. DTSC reminded them that Area G2 is part of the parking area and therefore there's a potential for arsenic in the soil. In addition, Z. Lyles also mentioned that the track area will also be modernized in the coming months. DTSC recommended that samples be taken & that the consultants follow the SOP included in the O&M plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/20/2013
Comments: On August 20, 2013, DTSC notified the District about the Agreement manager change.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/29/2013
Comments: On January 29, 2013, DTSC completed the site certification.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Amendment - Order/Agreement
Completed Date: 07/07/2014

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/02/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/05/2004
Comments: DTSC approved the PEA with further action required determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 08/07/2002
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 04/06/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 12/23/2002
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 06/02/2005
Comments: Not reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 12/19/2005
Comments: DTSC issued conditional approval. The newspaper did not run the public comment period notification as scheduled. Conditional approval allowed the District to move forward with the removal action for lead and PCBs with the undersanding that changes to the RAW may be neccessary if significant public comments are recevied. PCB clean-up goal is 0.3 mg/kg and lead clean-up goal is 255 mg/kg.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Document Type: Supplemental Site Investigation Report
Completed Date: 04/27/2007
Comments: DTSC approved the SSI report with a remediation required determination. A Removal Action Workplan (RAW) will be prepared to address arsenic impacted soils at the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/04/2006
Comments: District requested DTSC to assist the in solicitation of state funding by crafting a letter to CDE indicating that the removal actions on the school will take more than six months to complete.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/23/2006
Comments: Delays in Investigation letter to the School District. OLC has been contacted and staff has been assigned to project.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/15/2005
Comments: DTSC PM memo regarding the evaluation for concentrations of arsenic in the City Easement. Memo is part of a letter to the City of Burlingame.

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 11/14/2005
Comments: Fast Sheet developed to announce the start of the public comment period for the lead RAW and the contamination identified on the site.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/20/2006
Comments: DTSC put an unofficial summary together of all of the arsenic investigation for discussion purposes only.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/20/2006
Comments: Established a new cost estimate to complete the remainder of the project. Cost estimate considered the oversight for the remainder of the lead/PCB removal, additional investigation of arsenic, the remediation of arsenic and project closure.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/17/2004
Comments: Letter was constructed to encourage San Mateo Union HSD to enter into

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

a VCA for the clean-up of elevated levels of arsenic found on the campus.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/26/2006
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/12/2007
Comments: DTSC approval of temporary mitigation for cement slurry over City's dirt easment area.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/15/2007
Comments: DTSC issued Status of Investigation for arsenic Letter.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 03/21/2007
Comments: DTSC received (via email), reviewed and approved the TM for arsenic characterization

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 03/28/2007
Comments: Received 2 copies of Fact Sheet. Uploaded document.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 11/07/2007
Comments: DTSC issued a RAW approval and concurrently reponded to public comments regarding the RAW (in a separate but enclosed letter) and filed the NOE.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 10/01/2007
Comments: DTSC issued the Fact Sheet and public notice establishing the beginning of the public comment period. The public comment period will run from 10/5/07 - 11/05/07.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/02/2007
Comments: Following a comprehensive review of the laboratory reports on the soils to be used as fill material in the remediation at Burlingame

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

High School, DTSC has approved the use of the proposed fill materials.
Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/18/2008
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/07/2008
Comments: DTSC reviewed and determined that based on the results of the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/15/2008
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/29/2007
Comments: DTSC/District weekly remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/06/2007
Comments: DTSC/Distict arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/13/2007
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/27/2007
Comments: DTSC/District arsenic remediaiton meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/03/2008
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date: 01/17/2008
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/14/2008
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/28/2008
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/27/2008
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 10/27/2008
Comments: DTSC developed and approved the ESD for the project. The ESD serves as a bridging document to explain that a Land Use Covenant (LUC) is needed for the project, even though the LUC was not mentioned in the removal action workplan.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 08/04/2011
Comments: On July 19, 2012, DTSC received the complete revised Final O&M Plan (July 10, 2012 version)

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 05/06/2010
Comments: DTSC approved the Removal Action Completion Report for arsenic impacted soils

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 01/07/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/07/2008
Comments: DTSC reviewed and determined that based on the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

in Area B.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 06/06/2011
Comments: DTSC approved the 2010 Arsenic Annual Inspection summary Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 05/03/2012
Comments: On May 3, 2012, DTSC approved the Arsenic Annual Inspection Summary Report. This letter also identified two new areas of concern located at the Athletic Field area that will be included and managed under the O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 02/22/2012
Comments: On February 22, 2012, DTSC received a notification from the SMUHGD via e-mail indicating that Mr. Victor Talavera will be the new Arsenic Coordinator (replacing Mr. Ezekiel Lyles).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 09/07/2012
Comments: On September 4, 2012, DTSC approved the 2012 Annual Summary Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 12/09/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/04/2013
Comments: On October 2, 2013, DTSC received one hard copy of the revised 2013 Arsenic Annual Report; the e-copy was received via email on September 25, 2013.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 07/17/2014
Comments: Final public notice for publishing before July 8, 2014.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 06/17/2015
Comments: Not reported

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/20/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/15/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/06/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/13/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/29/2006
Comments: Not reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 11/10/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/20/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/27/2005
Comments: Not reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 09/20/2005
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date: 04/26/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/20/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 08/03/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/19/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/23/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/15/2006
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Operations and Maintenance Report
Future Due Date: 2016
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

SCH:

Facility ID: 41820008
Site Type: School Cleanup
Site Type Detail: School
Site Mgmt. Req.: NONE SPECIFIED
Acres: 22
National Priorities List: NO

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Mellan Songco
Supervisor:	Jose Salcedo
Division Branch:	Northern California Schools & Santa Susana
Site Code:	204083
Assembly:	22
Senate:	13
Special Program Status:	Not reported
Status:	Certified / Operation & Maintenance
Status Date:	08/04/2011
Restricted Use:	YES
Funding:	School District
Latitude:	37.58249
Longitude:	-122.3468
APN:	026290380, 029-141-010, 029141010
Past Use:	UNKNOWN, SCHOOL - HIGH SCHOOL
Potential COC:	Arsenic, Lead, Polychlorinated biphenyls (PCBs
Confirmed COC:	Arsenic, , Polychlorinated biphenyls (PCBs, Polychlorinated biphenyls (PCBs, Lead
Potential Description:	SOIL, SOIL
Alias Name:	BURLINGAME HIGH SCHOOOL
Alias Type:	Alternate Name
Alias Name:	SAN MATEO UHSD-BURLINGAME HIGH
Alias Type:	Alternate Name
Alias Name:	SAN MATEO UNION HIGH SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	026290380
Alias Type:	APN
Alias Name:	029-141-010
Alias Type:	APN
Alias Name:	029141010
Alias Type:	APN
Alias Name:	110021905143
Alias Type:	EPA (FRS #)
Alias Name:	204083
Alias Type:	Project Code (Site Code)
Alias Name:	41820008
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/16/2001
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	11/05/2002
Comments:	Not reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	CEQA - Notice of Exemption
Completed Date:	09/06/2007

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Comments: Office of Env. Planning & Analysis has approved the NOE. Division signatures will be added to the tracking form when the RAW is approved.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 10/01/2007
Comments: DTSC issued approval to begin construction on the rear athletic field. Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 01/25/2007
Comments: Sharon received a draft response letter from the District that did not comply with the DNONC. Comments were written on the response; Additional internal meetings are needed to determine if an order will be issued.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/05/2007
Comments: Held a face-to-face meeting to discuss outstanding issues for the project: Schedule for remainder of activities; Discussion regarding remediation in the planter boxes. Discussed a couple of options for the planter boxes; the District will include their final recommendation for their remediation in the arsenic RAW.

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/02/2007
Comments: Site Visit to oversee confirmation sampling for PCB remediation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/30/2007
Comments: Phone conference to discuss 1. Fact sheet; 2. Start of the Lead/PCB removal; 3. Recent arsenic characterization; 4. Meeting in DTSC Berkeley Office to develop the dates for the remaining of the remediation activities.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/22/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/08/2007
Comments: Meet with Kim, Diane and Mark to discuss the work notice Kim prepared for Burlingame. Based on the significant amount of time that has

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

lapsed since the last communication from DTSC to the community, Fact Sheet was recommended instead of a work notice. It will include the dates of the PCB and lead removals as well as a date on the additional arsenic investigation. A reference will be made regarding the arsenic removal, but no specific date will be mentioned.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/01/2007
Comments: Project Team to discuss outstanding issues for project: fence the PCB area; financal capabilities of the District; look up the requirements for proper signage and will send it to Burlingame via email; Cost Estimates to complete all of the work at BHS- cost to complete the PCB and Lead removal actions, cost to completed and arsenic characterization; prepare another timeline of tasks that need to be completed; Stabalization of site press release and future fact sheets; Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 01/29/2007
Comments: Project team discussed Measure M (Proposition 39) that was passed in November 06 for $298,000,000. discussed if an Imminent and Substantial Endangerment order would appropriate to issue or , a Determination of Non-Compliance (DoNC) or a Fence and Post on a temporary fence

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/26/2006
Comments: Meeting to discuss: the letter of proposed Determination of Non-Compliance was signed and sent to the District and the letter sent to the City of Burlingame (Jim Nantell) . The DNONC identified three thing: Completion of removal action for lead and PCBs around the main building and a submittal of a RACR; Submittal of an SSI to document the extent of arsenic-contamination on BHS; and submittal of a RAW to address the mitigation of arsenic. District to provide a response by January 17, 2007

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: School Cleanup Agreement
Completed Date: 10/12/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/25/2008
Comments: DTSC issued a letter to the District outlining the current status of the project and requesting a response to DTSC comments regarding the RACR and a schedule of mitigation activities.

Completed Area Name: Arsenic

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/03/2009
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 08/04/2009
Comments: DTSC issued a fully executed Operation and Maintenance Agreement.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 01/04/2013
Comments: On January 4, 2013, the County of San Mateo recorded the land use covenant for the Burlingame High School.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/10/2013
Comments: On July 10, 2013, DTSC participated on the annual site inspection with Victor Talavera and Patrick Sing (District), and Wes Hawthorne (Locus).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 06/18/2012
Comments: DTSC participated in the annual arsenic inspection at the Burlingame HS with Zeke Lyles and Wes Hawthorne. The Burlingame HS is still undergoing modernization. DTSC was notified by W. Hawthorne that Victor Talaveras (Arsenic Coordinator) is aware of the project and is monitoring the progress of the modernization project to ensure that if any of the areas of concern is impacted the proper SOP will be followed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 07/09/2014
Comments: On July 9, 2014, DTSC participated on the 5-Year review inspection of the cap at the site with the District representatives Sara Dwight (Arsenic Coordinator), Ricky Carrillo (Plant Manager), Wes Hawthorne (Locus Technologies). Cap measurements were taken at two areas in Area E and both areas meet or exceeds the minimum cap thickness.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 08/21/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date: 08/27/2009
Comments: Project Manager Change

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 06/28/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/04/2013
Comments: On December 2, 2013, DTSC was notified via email from Mr. Victor Talaveras (District's Arsenic Coordinator) that Building F (Home Economics Building) will be demolished which would impact Areas G and C identified in the DTSC-approved O&M Plan. The proposed schedule for the demolition work is from December 16, 2013 until January 24, 2014. Mr. Talaveras stated that the SOP included in the approved O&M Plan will be implemented for this project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/20/2011
Comments: DTSC conducted the 2011 Annual Arsenic Inpection with Zeke Lyles, District's Arsenic Coordinator; J. Wesley Hawthorne (Locus Technologies), O&M Professional; and, George. The following were observed during the walkthrough: bare soils w/ mesh visible around some trees in Area E; some of the planters in Area F2 needs additional granite; Area C behind building C and by the library needs additional wood chips to fill bald spots around plants; a new building D is almost complete - need to verify if Area C is beneath the new building; some of the Area C around the gym that is not concreted needs woodchips to fill bald spots. Z. Lyles mentioned that after the ongoing modernization he is planning on putting concrete over the grassy area around the gym instead on maintaning the grass. The trees will stay and the root area will have bark as covering. Currently, area soil is exposed. During the site inspection Z. Lyles mentioned that the parking area in the south side of the site will be re-finished in the coming months. DTSC reminded them that Area G2 is part of the parking area and therefore there's a potential for arsenic in the soil. In addition, Z. Lyles also mentioned that the track area will also be modernized in the coming months. DTSC recommended that samples be taken & that the consultants follow the SOP included in the O&M plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/20/2013
Comments: On August 20, 2013, DTSC notified the District about the Agreement manager change.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date:	01/29/2013
Comments:	On January 29, 2013, DTSC completed the site certification.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Amendment - Order/Agreement
Completed Date:	07/07/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	05/27/2015
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/02/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	02/05/2004
Comments:	DTSC approved the PEA with further action required determination.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	08/07/2002
Comments:	Not reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Workplan
Completed Date:	04/06/2005
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	12/23/2002
Comments:	Not reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Workplan
Completed Date:	06/02/2005
Comments:	Not reported
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Workplan
Completed Date:	12/19/2005
Comments:	DTSC issued conditional approval. The newspaper did not run the public comment period notification as scheduled. Conditional approval

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

allowed the District to move forward with the removal action for lead and PCBs with the undersanding that changes to the RAW may be neccessary if significant public comments are recevied. PCB clean-up goal is 0.3 mg/kg and lead clean-up goal is 255 mg/kg.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Report
Completed Date: 04/27/2007
Comments: DTSC approved the SSI report with a remediation required determination. A Removal Action Workplan (RAW) will be prepared to address arsenic impacted soils at the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/04/2006
Comments: District requested DTSC to assist the in solicitation of state funding by crafting a letter to CDE indicating that the removal actions on the school will take more than six months to complete.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/23/2006
Comments: Delays in Investigation letter to the School District. OLC has been contacted and staff has been assigned to project.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/15/2005
Comments: DTSC PM memo regarding the evaluation for concentrations of arsenic in the City Easement. Memo is part of a letter to the City of Burlingame.

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 11/14/2005
Comments: Fast Sheet developed to announce the start of the public comment period for the lead RAW and the contamination identified on the site.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/20/2006
Comments: DTSC put an unofficial summary together of all of the arsenic investigation for discussion purposes only.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/20/2006
Comments: Established a new cost estimate to complete the remainder of the project. Cost estimate considered the oversight for the remainder of the lead/PCB removal, additional investigation of arsenic, the

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

remediation of arsenic and project closure.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/17/2004
Comments: Letter was constructed to encourage San Mateo Union HSD to enter into a VCA for the clean-up of elevated levels of arsenic found on the campus.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/26/2006
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/12/2007
Comments: DTSC approval of temporary mitigation for cement slurry over City's dirt easment area.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/15/2007
Comments: DTSC issued Status of Investigation for arsenic Letter.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 03/21/2007
Comments: DTSC received (via email), reviewed and approved the TM for arsenic characterization

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 03/28/2007
Comments: Received 2 copies of Fact Sheet. Uploaded document.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 11/07/2007
Comments: DTSC issued a RAW approval and concurrently reponded to public comments regarding the RAW (in a separate but enclosed letter) and filed the NOE.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 10/01/2007
Comments: DTSC issued the Fact Sheet and public notice establishing the beginning of the public comment period. The public comment period will run from 10/5/07 - 11/05/07.

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/02/2007
Comments: Following a comprehensive review of the laboratory reports on the soils to be used as fill material in the remediation at Burlingame High School, DTSC has approved the use of the proposed fill materials.
Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/18/2008
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/07/2008
Comments: DTSC reviewed and determined that based on the results of the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/15/2008
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/29/2007
Comments: DTSC/District weekly remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/06/2007
Comments: DTSC/Distict arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/13/2007
Comments: DTSC/District arsenic remediation meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/27/2007
Comments: DTSC/District arsenic remediaiton meeting

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Other Report

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date:	01/03/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	01/17/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	02/14/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	02/28/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	10/27/2008
Comments:	Not reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	10/27/2008
Comments:	DTSC developed and approved the ESD for the project. The ESD serves as a bridging document to explain that a Land Use Covenant (LUC) is needed for the project, even though the LUC was not mentioned in the removal action workplan.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Operations and Maintenance Plan
Completed Date:	08/04/2011
Comments:	On July 19, 2012, DTSC received the complete revised Final O&M Plan (July 10, 2012 version)
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	05/06/2010
Comments:	DTSC approved the Removal Action Completion Report for arsenic impacted soils
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not reported
Completed Document Type:	Fact Sheets
Completed Date:	01/07/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/07/2008
Comments: DTSC reviewed and determined that based on the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 06/06/2011
Comments: DTSC approved the 2010 Arsenic Annual Inspection summary Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 05/03/2012
Comments: On May 3, 2012, DTSC approved the Arsenic Annual Inspection Summary Report. This letter also identified two new areas of concern located at the Athletic Field area that will be included and managed under the O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 02/22/2012
Comments: On February 22, 2012, DTSC received a notification from the SMUHGD via e-mail indicating that Mr. Victor Talavera will be the new Arsenic Coordinator (replacing Mr. Ezekiel Lyles).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 09/07/2012
Comments: On September 4, 2012, DTSC approved the 2012 Annual Summary Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 12/09/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/04/2013
Comments: On October 2, 2013, DTSC received one hard copy of the revised 2013 Arsenic Annual Report; the e-copy was received via email on September 25, 2013.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 07/17/2014
Comments: Final public notice for publishing before July 8, 2014.

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 06/17/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/20/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/15/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/06/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/13/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/29/2006
Comments: Not reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 11/10/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/20/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/27/2005
Comments: Not reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Completed Date: 09/20/2005
Comments: Not reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/26/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/20/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 08/03/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/19/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/23/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/15/2006
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Operations and Maintenance Report
Future Due Date: 2016
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

DEED:
Envirostor ID: 41820008

BURLINGAME HIGH SCHOOL (Continued) **S103986521**

Area: ARSENIC
Sub Area: Not reported
Site Type: SCHOOL CLEANUP
Status: CERTIFIED / OPERATION & MAINTENANCE
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): 01/04/2013

D86 **SAN MATEO UNION HIGH SCHOOL DIST** **HAZNET** **S112865882**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 6 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112865882
Year: 1998
GEPAID: CAC001082416
Contact: SAN MATEO UNION HIGH SCHOOL DI
Telephone: 6503488834
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE STE
Mailing City,St,Zip: SAN MATEO, CA 944010000
Gen County: Not reported
TSD EPA ID: CAL000027741
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 15.1704
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

D87 **BURLINGAME HIGH SCHOOL (SAN MATEO UION HIGH SCHOOL DISTRICT)** **HAZNET** **S112933040**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 7 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112933040
Year: 2004
GEPAID: CAC002570503
Contact: DENNIS BLATCHFORD/FAC COORD
Telephone: 6507620110
Mailing Name: Not reported
Mailing Address: 65 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94010
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: 0.17
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Transfer Station

BURLINGAME HIGH SCHOOL (SAN MATEO UION HIGH SCHOOL DISTRICT) (Continued) **S112933040**

Facility County: San Mateo

envid: S112933040
Year: 2004
GEPAID: CAC002570503
Contact: DENNIS BLATCHFORD/FAC COORD
Telephone: 6507620110
Mailing Name: Not reported
Mailing Address: 65 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94010
Gen County: Not reported
TSD EPA ID: CAD981382732
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 0.84
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

envid: S112933040
Year: 2003
GEPAID: CAC002570503
Contact: DENNIS BLATCHFORD/FAC COORD
Telephone: 6507620110
Mailing Name: Not reported
Mailing Address: 65 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94010
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Transfer Station
Tons: 0.84
Cat Decode: Other organic solids
Method Decode: Transfer Station
Facility County: San Mateo

D88 **SAN MATEO UNION H/S DIST** **HAZNET** **S112875067**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 8 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112875067
Year: 1996
GEPAID: CAC001217784
Contact: SAN MATEO UNION H/S DIST
Telephone: 4153488834
Mailing Name: Not reported
Mailing Address: 400 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: AZD982465866
TSD County: Not reported
Waste Category: Polychlorinated biphenyls and material containing PCBs
Disposal Method: Recycler

SAN MATEO UNION H/S DIST (Continued) **S112875067**

Tons: .5510
Cat Decode: Polychlorinated biphenyls and material containing PCBs
Method Decode: Recycler
Facility County: San Mateo

D89 **SAN MATEO UNION HIGH SCHOOL DISTRICT** **HAZNET** **S112891627**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 9 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112891627
Year: 2000
GEPAID: CAC001438160
Contact: SHERYL O'CONNOR-EXEC SECRETARY
Telephone: 6505582413
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 944010000
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 6.74
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

D90 **SAN MATEO UNION HIGH SCHOOL DISTRICT** **HAZNET** **S112886422**
NNE **400 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 10 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112886422
Year: 1998
GEPAID: CAC001380488
Contact: SAN MATEO UNION HS DISTRICT
Telephone: 6505582413
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 944010000
Gen County: Not reported
TSD EPA ID: CAD981382732
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 16.8560
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

D91 **BURLINGAME HS** **HAZNET** **S112920694**
NNE **400 CAROLINE AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
616 ft. **Site 11 of 18 in cluster D**

Relative:
Lower

Actual:
28 ft.

HAZNET:

envid:	S112920694
Year:	2002
GEPAID:	CAC002529015
Contact:	MIKE PALMER
Telephone:	6507620215
Mailing Name:	Not reported
Mailing Address:	400 CAROLINE AVE
Mailing City,St,Zip:	BURLINGAME, CA 940102797
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Laboratory waste chemicals
Disposal Method:	Transfer Station
Tons:	0.03
Cat Decode:	Laboratory waste chemicals
Method Decode:	Transfer Station
Facility County:	San Mateo

D92 **PARK DEPT CORPORATION YARD** **HIST UST** **U001593937**
NNE **420 CAROLAN** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
618 ft. **Site 12 of 18 in cluster D**

Relative:
Lower

Actual:
27 ft.

HIST UST:

File Number:	0002BD3D
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BD3D.pdf
Region:	STATE
Facility ID:	00000024256
Facility Type:	Other
Other Type:	CORP. YARD
Contact Name:	RICHARD QUADRI, DIRECTOR
Telephone:	4153428931
Owner Name:	CITY OF BURLINGAME
Owner Address:	501 PRIMROSE ROAD
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0001
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

D93 **CITY OF BURLINGAME PARKS DIVISION** **HAZNET** **S113057935**
NNE **420 CAROLAN AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.117 mi.
618 ft. **Site 13 of 18 in cluster D**

Relative:
Lower

Actual:
27 ft.

HAZNET:

envid:	S113057935
Year:	2004
GEPAID:	CAL000094712
Contact:	TIMOTHY RICHMOND/PARK SUPT
Telephone:	6505587330
Mailing Name:	Not reported
Mailing Address:	850 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Recycler
Tons:	0.22
Cat Decode:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113057935
Year:	2003
GEPAID:	CAL000094712
Contact:	TIMOTHY RICHMOND/PARK SUPT
Telephone:	6505587330
Mailing Name:	Not reported
Mailing Address:	850 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.07
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113057935
Year:	2000
GEPAID:	CAL000094712
Contact:	TIMOTHY RICHMOND/PARK SUPT
Telephone:	6505587330
Mailing Name:	Not reported
Mailing Address:	850 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	AZD980892731
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Not reported
Tons:	0.22
Cat Decode:	Waste oil and mixed oil
Method Decode:	Not reported

CITY OF BURLINGAME PARKS DIVISION (Continued) **S113057935**

Facility County: San Mateo

C94 **WELLS FARGO BANK** **HAZNET** **S112839406**
SSE **261 PARK ROAD** **N/A**
< 1/8 **BURLINGAME, CA 94011**
0.117 mi.
620 ft. **Site 7 of 19 in cluster C**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S112839406
Year:	1993
GEPAID:	CAC000712560
Contact:	WELLS FARGO BANK
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	525 MARKET STREET
Mailing City,St,Zip:	SAN FRANCISCO, CA 941630000
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	5.0568
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

B95 **BLUE CHALK CAFE** **HAZNET** **S112868777**
East **1100 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.118 mi.
621 ft. **Site 6 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112868777
Year:	1996
GEPAID:	CAC001140352
Contact:	BLUE CHALK CAFE
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1100 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	.8428
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

D96
NNW
< 1/8
0.118 mi.
624 ft.

442 CALIFORNIA DR
BURLINGAME, CA 94010

Site 14 of 18 in cluster D

CDL **S107534115**
N/A

Relative:
Lower

Actual:
27 ft.

CDL:

Facility ID:	2001-01-097
Date:	01/18/2001
Lab Type:	Illegal Drug Lab (L) - location where an illegal drug lab was operated or drug lab equipment and/or materials were stored.

C97
South
< 1/8
0.119 mi.
626 ft.

LINO NICCOLI
269 PRIMROSE RD
BURLINGAME, CA 94010

Site 8 of 19 in cluster C

HAZNET **S112921716**
N/A

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S112921716
Year:	2002
GEPAID:	CAC002551348
Contact:	Louis Harding/Shannon's Mgt
Telephone:	6506968373
Mailing Name:	Not reported
Mailing Address:	PO Box 1338
Mailing City,St,Zip:	San Mateo, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAL000190080
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	29.49
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112921716
Year:	2002
GEPAID:	CAC002551348
Contact:	Louis Harding/Shannon's Mgt
Telephone:	6506968373
Mailing Name:	Not reported
Mailing Address:	PO Box 1338
Mailing City,St,Zip:	San Mateo, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	96.92
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

B98 **BURLINGAME AVENUE STREETSCAPE IMPROVEMENTS PROJECT** **NPDES** **S113449997**
East **BURLINGAME AVENUE BETWEEN EL CAMINO REAL AND CALIFORNIA DRIV** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
628 ft. **Site 7 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	2
Regulatory Measure Id:	436472
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	2 41C366061
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	04/04/2013
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	04/16/2015
Discharge Name:	City of Burlingame
Discharge Address:	501 Primrose Road
Discharge City:	Burlingame
Discharge State:	California
Discharge Zip:	94010
RECEIVED DATE:	Not reported
PROCESSED DATE:	Not reported
STATUS CODE NAME:	Not reported
STATUS DATE:	Not reported
PLACE SIZE:	Not reported
PLACE SIZE UNIT:	Not reported
FACILITY CONTACT NAME:	Not reported
FACILITY CONTACT TITLE:	Not reported
FACILITY CONTACT PHONE:	Not reported
FACILITY CONTACT PHONE EXT:	Not reported
FACILITY CONTACT EMAIL:	Not reported
OPERATOR NAME:	Not reported
OPERATOR ADDRESS:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR CONTACT NAME:	Not reported
OPERATOR CONTACT TITLE:	Not reported
OPERATOR CONTACT PHONE:	Not reported
OPERATOR CONTACT PHONE EXT:	Not reported
OPERATOR CONTACT EMAIL:	Not reported
OPERATOR TYPE:	Not reported
DEVELOPER NAME:	Not reported
DEVELOPER ADDRESS:	Not reported
DEVELOPER CITY:	Not reported
DEVELOPER STATE:	Not reported
DEVELOPER ZIP:	Not reported
DEVELOPER CONTACT NAME:	Not reported
DEVELOPER CONTACT TITLE:	Not reported
CONSTYPE LINEAR UTILITY IND:	Not reported
EMERGENCY PHONE NO:	Not reported
EMERGENCY PHONE EXT:	Not reported
CONSTYPE ABOVE GROUND IND:	Not reported

BURLINGAME AVENUE STREETSCAPE IMPROVEMENTS PROJECT (Continued) **S113449997**

CONSTYPE BELOW GROUND IND:	Not reported
CONSTYPE CABLE LINE IND:	Not reported
CONSTYPE COMM LINE IND:	Not reported
CONSTYPE COMMERTIAL IND:	Not reported
CONSTYPE ELECTRICAL LINE IND:	Not reported
CONSTYPE GAS LINE IND:	Not reported
CONSTYPE INDUSTRIAL IND:	Not reported
CONSTYPE OTHER DESRIPTION:	Not reported
CONSTYPE OTHER IND:	Not reported
CONSTYPE RECONS IND:	Not reported
CONSTYPE RESIDENTIAL IND:	Not reported
CONSTYPE TRANSPORT IND:	Not reported
CONSTYPE UTILITY DESCRIPTION:	Not reported
CONSTYPE UTILITY IND:	Not reported
CONSTYPE WATER SEWER IND:	Not reported
DIR DISCHARGE USWATER IND:	Not reported
RECEIVING WATER NAME:	Not reported
CERTIFIER NAME:	Not reported
CERTIFIER TITLE:	Not reported
CERTIFICATION DATE:	Not reported
PRIMARY SIC:	Not reported
SECONDARY SIC:	Not reported
TERTIARY SIC:	Not reported

B99 **BURLINGAME POST OFFICE** **RGA LUST** **S114588305**
SE **220 PARK** **N/A**
< 1/8 **BURLINGAME, CA**
0.119 mi.
629 ft. **Site 8 of 35 in cluster B**

Relative: **Higher**

Actual: **36 ft.**

RGA LUST:

2012	BURLINGAME POST OFFICE	220 PARK
2011	BURLINGAME POST OFFICE	220 PARK
2010	BURLINGAME POST OFFICE	220 PARK
2009	BURLINGAME POST OFFICE	220 PARK
2008	BURLINGAME POST OFFICE	220 PARK
2007	BURLINGAME POST OFFICE	220 PARK
2006	BURLINGAME POST OFFICE	220 PARK
2005	BURLINGAME POST OFFICE	220 PARK
2003	BURLINGAME POST OFFICE	220 PARK

B100 **BURLINGAME POST OFFICE** **RGA LUST** **S114588306**
SE **220 PARK** **N/A**
< 1/8 **SAN MATEO, CA**
0.119 mi.
629 ft. **Site 9 of 35 in cluster B**

Relative: **Higher**

Actual: **36 ft.**

RGA LUST:

2004	BURLINGAME POST OFFICE	220 PARK

B101 **BURLINGAME POST OFFICE** **RGA LUST** **S114588303**
SE **220 PARK RD** **N/A**
< 1/8 **BURLINGAME, CA**
0.119 mi.
630 ft. **Site 10 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

1998	BURLINGAME POST OFFICE	220 PARK RD
1997	BURLINGAME POST OFFICE	220 PARK RD
1996	BURLINGAME POST OFFICE	220 PARK RD
1995	BURLINGAME POST OFFICE	220 PARK RD
1994	BURLINGAME POST OFFICE	220 PARK RD
1993	BURLINGAME POST OFFICE	220 PARK RD

B102 **BURLINGAME POST OFFICE** **LUST** **S104493543**
SE **220 PARK** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
630 ft. **Site 11 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

LUST:

Region:	STATE
Global Id:	T0608100091
Latitude:	37.5776778
Longitude:	-122.3461348
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/28/1995
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0096
LOC Case Number:	660040
File Location:	Local Agency Warehouse
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100091
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100091
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

BURLINGAME POST OFFICE (Continued) **S104493543**

Status History:
Global Id: T0608100091
Status: Completed - Case Closed
Status Date: 11/28/1995

Global Id: T0608100091
Status: Open - Case Begin Date
Status Date: 04/23/1990

Regulatory Activities:
Global Id: T0608100091
Action Type: Other
Date: 04/23/1990
Action: Leak Discovery

Global Id: T0608100091
Action Type: Other
Date: 04/23/1990
Action: Leak Reported

Global Id: T0608100091
Action Type: ENFORCEMENT
Date: 12/05/1992
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660040
Facility Status: 9- Case Closed
Global ID: T0608100091
APN Number: 029204250
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

B103 **BURLINGAME POST OFFICE** **RGA LUST** **S114588304**
SE **220 PARK ROAD** **N/A**
< 1/8 **BURLINGAME, CA**
0.119 mi.
630 ft. **Site 12 of 35 in cluster B**

Relative:
Higher

RGA LUST:
1992 BURLINGAME POST OFFICE 220 PARK ROAD

Actual:
36 ft.

B104 **US POSTAL SERVICE** **HAZNET** **S112940702**
SE **220 PARK RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
630 ft. **Site 13 of 35 in cluster B**

Relative:
Higher

HAZNET:
envid: S112940702
Year: 2004

Actual:
36 ft.

GEPAID: CAC002582582
Contact: KEVIN TONG

US POSTAL SERVICE (Continued) **S112940702**

Telephone:	6503474686
Mailing Name:	Not reported
Mailing Address:	220 PARK RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	5.89
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

B105 **US POSTAL SERVICE** **LUST** **S104234098**
SE **220 PARK** **HIST CORTESE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
630 ft. **Site 14 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660040
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0096

B106 **US POSTAL SERVICE** **HAZNET** **S112887001**
SE **220 PARK RD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
630 ft. **Site 15 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112887001
Year:	1999
GEPAID:	CAC001386560
Contact:	US POSTAL SERVICE
Telephone:	4155505316
Mailing Name:	Not reported

US POSTAL SERVICE (Continued) **S112887001**

Mailing Address: PO BOX 880010
Mailing City,St,Zip: SAN FRANCISCO, CA 941880010
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Disposal, Other
Tons: .0125
Cat Decode: Household waste
Method Decode: Disposal, Other
Facility County: San Mateo

envid: S112887001
Year: 1999
GEPAID: CAC001386560
Contact: US POSTAL SERVICE
Telephone: 4155505316
Mailing Name: Not reported
Mailing Address: PO BOX 880010
Mailing City,St,Zip: SAN FRANCISCO, CA 941880010
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Laboratory waste chemicals
Disposal Method: Disposal, Other
Tons: .0025
Cat Decode: Laboratory waste chemicals
Method Decode: Disposal, Other
Facility County: San Mateo

envid: S112887001
Year: 1999
GEPAID: CAC001386560
Contact: US POSTAL SERVICE
Telephone: 4155505316
Mailing Name: Not reported
Mailing Address: PO BOX 880010
Mailing City,St,Zip: SAN FRANCISCO, CA 941880010
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Alkaline solution without metals pH >= 12.5
Disposal Method: Disposal, Other
Tons: .0400
Cat Decode: Alkaline solution without metals pH >= 12.5
Method Decode: Disposal, Other
Facility County: San Mateo

envid: S112887001
Year: 1999
GEPAID: CAC001386560
Contact: US POSTAL SERVICE
Telephone: 4155505316
Mailing Name: Not reported
Mailing Address: PO BOX 880010
Mailing City,St,Zip: SAN FRANCISCO, CA 941880010
Gen County: Not reported

US POSTAL SERVICE (Continued) **S112887001**

TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: .3750
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Transfer Station
Facility County: San Mateo

B107 **1X U. S. POSTAL SERVICE** **HAZNET** **S112856075**
SE **220 PARK ROAD** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.119 mi.
630 ft. **Site 16 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

HAZNET:
envid: S112856075
Year: 1995
GEPAID: CAC000956136
Contact: U. S. POSTAL SERVICE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 220 PARK ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAT080011059
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: 41.7000
Cat Decode: Waste oil and mixed oil
Method Decode: Recycler
Facility County: San Mateo

envid: S112856075
Year: 1994
GEPAID: CAC000956136
Contact: U. S. POSTAL SERVICE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 220 PARK ROAD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAT080014079
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Not reported
Tons: .1300
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Not reported
Facility County: San Mateo

B108 **US POSTAL SERVICE** **RGA LUST** **S114715248**
SE **220 PARK RD** **N/A**
< 1/8 **BURLINGAME, CA**
0.119 mi.
630 ft. **Site 17 of 35 in cluster B**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

2002	US POSTAL SERVICE	220 PARK RD
2001	US POSTAL SERVICE	220 PARK RD
2000	US POSTAL SERVICE	220 PARK RD

B109 **PENINSULA CORRIDOR JOINT POWERS BOARD** **HAZNET** **S112978074**
ENE **290 CALIFORNIA DR** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.120 mi.
632 ft. **Site 18 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112978074
Year:	2009
GEPAID:	CAC002642629
Contact:	DANIEL CHEN
Telephone:	4085917703
Mailing Name:	Not reported
Mailing Address:	1250 SAN CARLOS AVE
Mailing City,St,Zip:	SAN CARLOS, CA 94070
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0275
Cat Decode:	Other inorganic solid waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

B110 **CALTRAIN** **HAZNET** **S112971801**
ENE **290 CALIFORNIA DR** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.120 mi.
632 ft. **Site 19 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112971801
Year:	2008
GEPAID:	CAC002632809
Contact:	CHIACHI CHAN
Telephone:	6505087789
Mailing Name:	Not reported
Mailing Address:	1250 SAN CARLOS AVE
Mailing City,St,Zip:	SAN CARLOS, CA 94070
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery

CALTRAIN (Continued) **S112971801**

(H010-H129) Or (H131-H135)
Tons: 0.9
Cat Decode: Other inorganic solid waste
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

C111 **CITY OF BURLINGAME** **HAZNET** **S117289175**
SSW **1415 BURLINGAME AVE** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.120 mi.
636 ft. **Site 9 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

HAZNET:
envid: S117289175
Year: 2014
GEPAID: CAC002726090
Contact: LISHA MAI, ASSISSTANT ENGINEER
Telephone: 6505587239
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103906
Gen County: San Mateo
TSD EPA ID: CAD009466392
TSD County: Contra Costa
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Other Treatment
Tons: 0.25
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Other Treatment
Facility County: San Mateo

envid: S117289175
Year: 2013
GEPAID: CAC002726090
Contact: LISHA MAI, ASSISSTANT ENGINEER
Telephone: 6505587239
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103906
Gen County: San Mateo
TSD EPA ID: CAL000190816
TSD County: Stanislaus
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.596
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: Not reported

envid: S117289175
Year: 2013
GEPAID: CAC002726090
Contact: LISHA MAI, ASSISSTANT ENGINEER
Telephone: 6505587239
Mailing Name: Not reported

CITY OF BURLINGAME (Continued) **S117289175**

Mailing Address: 501 PRIMROSE RD
Mailing City,St,Zip: BURLINGAME, CA 940103906
Gen County: San Mateo
TSD EPA ID: CAD009466392
TSD County: Contra Costa
Waste Category: Not reported
Disposal Method: Other Treatment
Tons: 0.5
Cat Decode: Not reported
Method Decode: Other Treatment
Facility County: Not reported

C112 **NEXTEL-SITE ID CA-0323** **San Mateo Co. BI** **S113757706**
SSW **1420 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.122 mi.
642 ft. **Site 10 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027316
Prog Element Code: STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id: PR0043207
Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: INACTIVE

C113 **SPRINT NEXTEL CELL SITE FS04XC321** **San Mateo Co. BI** **S113758635**
SSW **1420 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.122 mi.
642 ft. **Site 11 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0044826
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0056965
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

C114 **UST SITE - FORMER FOX PENINSULA THEATER** **San Mateo Co. BI** **S113759145**
SSW **1417-15 BURLINGAME** **N/A**
< 1/8 **BURLINGAME, CA 94010**
0.123 mi.
650 ft. **Site 12 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0053257
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0073711
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

C115 **CHMIRS** **S105661928**
SSW **1419 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94014**
0.126 mi.
664 ft. **Site 13 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

CHMIRS:

OES Incident Number:	9-1788
OES notification:	04/22/1999
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1999
Agency:	PGE
Incident Date:	4/22/199912:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	mineral oil
Gallons:	10
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S105661928**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Underground electric transformer failed and lost some of its mineral oil to its underground vault.

C116 **LINO NICCOLI** **HAZNET** **S118206658**
South **257 PRIMROSE RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.127 mi.
669 ft. **Site 14 of 19 in cluster C**

Relative: **Higher**

Actual: **38 ft.**

HAZNET:

envid:	S118206658
Year:	2014
GEPAID:	CAC002766594
Contact:	LINO NICCOLI
Telephone:	5094303402
Mailing Name:	Not reported
Mailing Address:	1923 HARRIS AVE
Mailing City,St,Zip:	RICHLAND, WA 993542339
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

E117 **JUNE NEWLING** **HAZNET** **S117286596**
West **1405 BELLEVUE AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.128 mi.
675 ft. **Site 10 of 14 in cluster E**

Relative: **Lower**

Actual: **31 ft.**

HAZNET:

envid:	S117286596
Year:	2013
GEPAID:	CAC002722376
Contact:	JUNE NEWLING
Telephone:	6503473455
Mailing Name:	Not reported

JUNE NEWLING (Continued) **S117286596**

Mailing Address:	1405 BELLEVUE AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

F118 **CHMIRS** **S100280829**
NNW **CALIFORNIA DR. AT DOUGLAS** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.134 mi.
709 ft. **Site 1 of 22 in cluster F**

Relative:
Lower

Actual:
26 ft.

CHMIRS:

OES Incident Number:	991259
OES notification:	Not reported
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**26-JUN-88**
Property Use:	962
Agency Id Number:	41085
Agency Incident Number:	1363
Time Notified:	859
Time Completed:	1010
Surrounding Area:	500
Estimated Temperature:	75
Property Management:	C
More Than Two Substances Involved?:	N
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	CAPT. ROD ENGLISH
Report Date:	26-JUN-88
Facility Telephone:	415 593-8016
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Not reported
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported

(Continued) **S100280829**

Other:	Not reported
Date/Time:	Not reported
Year:	88-92
Agency:	Not reported
Incident Date:	26-JUN-88
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Not reported
Site Type:	Not reported
E Date:	14-FEB-89
Substance:	Not reported
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	N
Description:	Not reported

C119 **JP MORGAN CHASE - BURLINGAME** **HAZNET** **S113792467**
SW **1430 CHAPIN AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.137 mi.
724 ft. **Site 15 of 19 in cluster C**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S113792467
Year:	2012
GEPAID:	CAC002710896
Contact:	CARL WESTERDAHL
Telephone:	2065005437
Mailing Name:	Not reported
Mailing Address:	1301 2ND AVE # WA1-3442
Mailing City,St,Zip:	SEATTLE, WA 981013800
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	2.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

F120
NNW
1/8-1/4
0.140 mi.
737 ft.

BURLINGAME ONE HOUR CLEANERS
507 CALIFORNIA
BURLINGAME, CA 94010

San Mateo Co. BI
DRYCLEANERS

S113759107
N/A

Site 2 of 22 in cluster F

Relative:
Lower

Actual:
26 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0052736
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0073049
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

DRYCLEANERS:

EPA Id:	CAL000381651
NAICS Code:	333312
NAICS Description:	Commercial Laundry, Drycleaning, and Pressing Machine Manufacturing
SIC Code:	3582
SIC Description:	Commercial Laundry, Drycleaning and Pressing Machines
Create Date:	01/16/2013
Facility Active:	Yes
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	SEUNG KYUNG PARK
Owner Address:	1860 HARDING AVE
Owner Address 2:	Not reported
Owner Telephone:	4153105000
Contact Name:	SEUNG KYUNG PARK
Contact Address:	507 CALIFORNIA DR
Contact Address 2:	Not reported
Contact Telephone:	4153105000
Mailing Name:	Not reported
Mailing Address 1:	507 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940100000
Owner Fax:	2
Region Code:	0000000000

F121
NNW
1/8-1/4
0.140 mi.
737 ft.

BURLINGAME ONE HOUR CLEANERS
507 CALIFORNIA
BURLINGAME, CA 94010

San Mateo Co. BI

S113756625
N/A

Site 3 of 22 in cluster F

Relative:
Lower

Actual:
26 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018022
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011840
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018022
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004620

BURLINGAME ONE HOUR CLEANERS (Continued) **S113756625**

Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

F122 **BURLINGAME ONE HOUR CLEANERS** **DRYCLEANERS** **1002851178**
NNW **507 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.140 mi.
737 ft. **Site 4 of 22 in cluster F**

Relative:
Lower

Actual:
26 ft.

DRYCLEANERS:

EPA Id:	CAD981171382
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	04/10/1987
Facility Active:	No
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	SEUNG KYUNG PARK
Owner Address:	1860 HARDING AVE.
Owner Address 2:	Not reported
Owner Telephone:	4153105000
Contact Name:	SEUNG KYUNG PARK
Contact Address:	507 CALIFORNIA DR.
Contact Address 2:	Not reported
Contact Telephone:	6503471875
Mailing Name:	Not reported
Mailing Address 1:	507 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	94010
Owner Fax:	2
Region Code:	0000000000

F123 **BURLINGAME ONE HOUR CLEANERS** **EMI** **S105936845**
NNW **507 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.140 mi.
737 ft. **Site 5 of 22 in cluster F**

Relative:
Lower

Actual:
26 ft.

EMI:

Year:	1987
County Code:	41
Air Basin:	SF
Facility ID:	270
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1993
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.125
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.142
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2007
County Code:	41
Air Basin:	SF

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.145
Reactive Organic Gases Tons/Yr:	.101297
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.094
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	7.0999999999999994E-2
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	5283
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

BURLINGAME ONE HOUR CLEANERS (Continued) **S105936845**

Total Organic Hydrocarbon Gases Tons/Yr: 7.0999999999999994E-2
Reactive Organic Gases Tons/Yr: 4.9600600000000002E-2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

F124 **BURLINGAME ONE HOUR CLEANERS** **FINDS** **1004442796**
NNW **507 CALIFORNIA DRIVE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.140 mi.
737 ft. **Site 6 of 22 in cluster F**

Relative:
Lower

Actual:
26 ft.

FINDS:

Registry ID: 110001197892

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

ECHO:
Envid: 1004442796
Registry ID: 110001197892
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110001197892

F125 **EDR Hist Cleaner** **1015069399**
NNW **507 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.140 mi.
737 ft. **Site 7 of 22 in cluster F**

Relative:
Lower

Actual:
26 ft.

EDR Historical Cleaners:

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2001
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2005
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2006
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2007
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2008
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2010

(Continued) **1015069399**

Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2011
Address: 507 CALIFORNIA DR

Name: BURLINGAME 1 HOUR CLEANERS
Year: 2012
Address: 507 CALIFORNIA DR

C126 **EDR Hist Cleaner** **1015025506**
South **240 PRIMROSE RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.140 mi.
738 ft. **Site 16 of 19 in cluster C**

Relative:
Higher

Actual:
38 ft.

EDR Historical Cleaners:

Name: A 1 CLEANERS
Year: 2001
Address: 240 PRIMROSE RD

Name: A 1 CLEANERS
Year: 2002
Address: 240 PRIMROSE RD

Name: A 1 CLEANERS
Year: 2004
Address: 240 PRIMROSE RD

Name: A1 CLEANERS
Year: 2005
Address: 240 PRIMROSE RD

Name: A1 CLEANERS
Year: 2006
Address: 240 PRIMROSE RD

Name: A1 CLEANERS
Year: 2008
Address: 240 PRIMROSE RD

Name: A 1 CLEANERS
Year: 2010
Address: 240 PRIMROSE RD

Name: A1 CLEANERS
Year: 2011
Address: 240 PRIMROSE RD

Name: A1 CLEANERS
Year: 2012
Address: 240 PRIMROSE RD

G127 **CARR MCLELLAN** **HAZNET** **S112911094**
SE **216 PARK AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.147 mi.
774 ft. **Site 1 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S112911094
Year:	2001
GEPAID:	CAC002310089
Contact:	JERRY HUGHES
Telephone:	5103468800
Mailing Name:	Not reported
Mailing Address:	216 PARK AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000190080
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

C128 **WELLS FARGO BANK** **HAZNET** **S113789213**
SSW **1435 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.147 mi.
775 ft. **Site 17 of 19 in cluster C**

Relative:
Higher

Actual:
39 ft.

HAZNET:

envid:	S113789213
Year:	2012
GEPAID:	CAC002706277
Contact:	WELLS FARGO BANK CPG COMPLIANCE
Telephone:	4158943298
Mailing Name:	Not reported
Mailing Address:	333 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052101
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S113789213
Year:	2012
GEPAID:	CAC002706277
Contact:	WELLS FARGO BANK CPG COMPLIANCE
Telephone:	4158943298
Mailing Name:	Not reported
Mailing Address:	333 MARKET ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941052101

WELLS FARGO BANK (Continued) **S113789213**

Gen County:	San Mateo
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.3
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

B129 **CHMIRS** **S105882946**
ENE **7474 E. DIVISION ROAD. CLOSEST CITY IS MANTECA** **N/A**
1/8-1/4 **UNINCORPORATED COUNTY AREA, CA**
0.148 mi.
784 ft. **Site 20 of 35 in cluster B**

Relative:
Lower

Actual:
30 ft.

CHMIRS:

OES Incident Number:	2-1471
OES notification:	03/18/2002
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	DDTSC
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported

(Continued) **S105882946**

Year:	2002
Agency:	San Joaquin OES
Incident Date:	3/18/200212:00:00 AM
Admin Agency:	San Joaquin County Emergency Services
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	drug lab waste
Gallons:	0.000000
Pounds:	250
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Abandoned drug lab wsste found in a farmer's field.

F130 **CHMIRS** **S109039770**
NNW **525 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.150 mi.
790 ft. **Site 8 of 22 in cluster F**

Relative: CHMIRS:
Lower

OES Incident Number:	7-1762
OES notification:	03/19/2007
Actual: OES Date:	Not reported
24 ft. OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported

(Continued) **S109039770**

Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	storm drain
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2007
Agency:	City of Burlingame
Incident Date:	3/19/2007 12:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	No
Site Type:	Residence
E Date:	Not reported
Substance:	Sewage
Gallons:	2250
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	03/19/07 at 0950 hours, A main blockage which resulted in an overflow from a 4 inch cleanout. Some of the overflow went into a strom drain.

B131 **GERMAN CAR CARE** **San Mateo Co. BI** **S113756147**
East **251 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.150 mi.
792 ft. **Site 21 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0015787
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011961
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0015787
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0028871
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

B132 **G&C AUTO BODY** **San Mateo Co. BI** **S113756140**
East **251 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.150 mi.
792 ft. **Site 22 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0015679
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011960
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0015679
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0026838
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

B133 **EDR Hist Auto** **1015364327**
East **251 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.150 mi.
792 ft. **Site 23 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

EDR Historical Auto Stations:

Name:	AUTOMOBILE CARE
Year:	2001
Address:	251 CALIFORNIA DR

Name:	AUTO MOBILE CARE
Year:	2002
Address:	251 CALIFORNIA DR

Name:	AUTOMOBILE CARE

(Continued) **1015364327**

Year: 2003
Address: 251 CALIFORNIA DR

Name: AUTO MOBILE CARE
Year: 2004
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2005
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2006
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2007
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2008
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2009
Address: 251 CALIFORNIA DR

Name: GERMAN CAR CARE
Year: 2010
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2011
Address: 251 CALIFORNIA DR

Name: AUTOMOBILE CARE
Year: 2012
Address: 251 CALIFORNIA DR

B134 **GERMAN CAR CARE** **HAZNET** **S113802795**
East **251 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.150 mi.
792 ft. **Site 24 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:
envid: S113802795
Year: 2013
GEPAID: CAL000379554
Contact: DAVID FANUCCHI
Telephone: 6503751201
Mailing Name: Not reported
Mailing Address: 251 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD009007626
TSD County: Los Angeles
Waste Category: Not reported

GERMAN CAR CARE (Continued) **S113802795**

Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported
envid:	S113802795
Year:	2013
GEPAID:	CAL000379554
Contact:	DAVID FANUCCHI
Telephone:	6503751201
Mailing Name:	Not reported
Mailing Address:	251 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8428
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported
envid:	S113802795
Year:	2012
GEPAID:	CAL000379554
Contact:	DAVID FANUCCHI
Telephone:	6503751201
Mailing Name:	Not reported
Mailing Address:	251 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.22935
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

G135 **EDR Hist Cleaner** **1015022629**
SE **229 PARK RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.151 mi.
796 ft. **Site 2 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

EDR Historical Cleaners:

Name:	BLU WHITE CLEANERS
Year:	2003
Address:	229 PARK RD
Name:	BLUE WHITE CLEANERS
Year:	2004
Address:	229 PARK RD
Name:	BLUE WHITE CLEANERS
Year:	2005
Address:	229 PARK RD
Name:	BLUE WHITE CLEANERS
Year:	2006
Address:	229 PARK RD
Name:	BLU WHITE CLEANERS
Year:	2008
Address:	229 PARK RD
Name:	BLU WHITE CLEANERS
Year:	2010
Address:	229 PARK RD
Name:	BLUWHITE CLEANERS
Year:	2011
Address:	229 PARK RD
Name:	BLUWHITE CLEANERS
Year:	2012
Address:	229 PARK RD

C136 **EDR Hist Auto** **1015228685**
SW **1440 CHAPIN AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.154 mi.
813 ft. **Site 18 of 19 in cluster C**

Relative:
Higher

Actual:
36 ft.

EDR Historical Auto Stations:

Name:	BODY SHOP
Year:	2001
Address:	1440 CHAPIN AVE

B137 **AUTO MOBILE CARE** **HAZNET** **S113066149**
East **251 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.154 mi.
814 ft. **Site 25 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113066149
Year:	2000
GEPAID:	CAL000115987
Contact:	DAVID R FANUCCHI - OWNER
Telephone:	6503751201
Mailing Name:	Not reported
Mailing Address:	251 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104112
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.22
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113066149
Year:	1999
GEPAID:	CAL000115987
Contact:	DAVID FANUCCHI
Telephone:	6503751201
Mailing Name:	Not reported
Mailing Address:	251 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104112
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.2293
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113066149
Year:	1998
GEPAID:	CAL000115987
Contact:	DAVID FANUCCHI
Telephone:	6503751201
Mailing Name:	Not reported
Mailing Address:	251 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104112
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.5420
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station

AUTO MOBILE CARE (Continued) **S113066149**

Facility County: San Mateo

envid: S113066149
Year: 1997
GEPAID: CAL000115987
Contact: DAVID FANUCCHI
Telephone: 6503751201
Mailing Name: Not reported
Mailing Address: 251 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104112
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: .4170
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113066149
Year: 1996
GEPAID: CAL000115987
Contact: DAVID FANUCCHI
Telephone: 6503751201
Mailing Name: Not reported
Mailing Address: 251 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104112
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: .2085
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

B138 **CHRISTIE'S** **HAZNET** **S112889790**
ESE **240 HATCH LANE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.156 mi.
824 ft. **Site 26 of 35 in cluster B**

Relative:
Higher

Actual:
35 ft.

HAZNET:
envid: S112889790
Year: 1998
GEPAID: CAC001417624
Contact: BASIM AZAR
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 240 HATCH LANE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000027741

CHRISTIE'S (Continued) **S112889790**

TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: .8428
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

D139 **BURLINGAME HIGH SCHOOL** **San Mateo Co. BI** **S113755172**
NNW **1 MANGINI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.164 mi.
866 ft. **Site 15 of 18 in cluster D**

Relative:
Lower

Actual:
25 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0000060
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0038069
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0000060
Prog Element Code: STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id: PR0038068
Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: ACTIVE

D140 **SAN MATEO UNION HIGH SCHOOL DISTRICT** **HAZNET** **S112930524**
NNW **1 MANGINI WAY** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.164 mi.
866 ft. **Site 16 of 18 in cluster D**

Relative:
Lower

Actual:
25 ft.

HAZNET:
envid: S112930524
Year: 2003
GEPAID: CAC002566377
Contact: BOB ARNOLD
Telephone: 6507620200
Mailing Name: Not reported
Mailing Address: 650 N DELAWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94010
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Not reported
Tons: 61.52
Cat Decode: Asbestos containing waste
Method Decode: Not reported
Facility County: San Mateo

D141 **BURLINGAME HIGH SCHOOL** **HAZNET** **S112938050**
NNW **1 MANGINI WAY** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.164 mi.
866 ft. **Site 17 of 18 in cluster D**

Relative:
Lower

Actual:
25 ft.

HAZNET:

envid:	S112938050
Year:	2005
GEPAID:	CAC002578338
Contact:	DENNIS BLATCHFORD
Telephone:	6503757116
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Latex waste
Disposal Method:	Transfer Station
Tons:	0.04
Cat Decode:	Latex waste
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S112938050
Year:	2004
GEPAID:	CAC002578338
Contact:	DENNIS BLATCHFORD
Telephone:	6503757116
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	101.97
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112938050
Year:	2004
GEPAID:	CAC002578338
Contact:	DENNIS BLATCHFORD
Telephone:	6503757116
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Transfer Station
Tons:	0.42
Cat Decode:	Other inorganic solid waste
Method Decode:	Transfer Station

BURLINGAME HIGH SCHOOL (Continued) **S112938050**

Facility County: San Mateo

envid: S112938050
Year: 2004
GEPAID: CAC002578338
Contact: DENNIS BLATCHFORD
Telephone: 6503757116
Mailing Name: Not reported
Mailing Address: 650 N DELEWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94401
Gen County: Not reported
TSD EPA ID: AZ0000337360
TSD County: Not reported
Waste Category: Polychlorinated biphenyls and material containing PCBs
Disposal Method: Not reported
Tons: 1.48
Cat Decode: Polychlorinated biphenyls and material containing PCBs
Method Decode: Not reported
Facility County: San Mateo

envid: S112938050
Year: 2004
GEPAID: CAC002578338
Contact: DENNIS BLATCHFORD
Telephone: 6503757116
Mailing Name: Not reported
Mailing Address: 650 N DELEWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94401
Gen County: Not reported
TSD EPA ID: CAD028409019
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Transfer Station
Tons: 0.06
Cat Decode: Asbestos containing waste
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

D142 **BURLINGAME HUGH SCHOOL** **HAZNET** **S112926187**
NNW **1 MANGINI WAY** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.164 mi.
866 ft. **Site 18 of 18 in cluster D**

Relative:
Lower

Actual:
25 ft.

HAZNET:
envid: S112926187
Year: 2014
GEPAID: CAC002558884
Contact: STEVE DEWAN
Telephone: 6507620110
Mailing Name: Not reported
Mailing Address: 650 N DELEWARE ST
Mailing City,St,Zip: SAN MATEO, CA 94401
Gen County: San Mateo
TSD EPA ID: CAD980675276

BURLINGAME HUGH SCHOOL (Continued) **S112926187**

TSD County:	Kern
Waste Category:	Contaminated soil from site clean-up
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	273.54
Cat Decode:	Contaminated soil from site clean-up
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S112926187
Year:	2005
GEPAID:	CAC002558884
Contact:	STEVE DEWAN
Telephone:	6507620110
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	5.89
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112926187
Year:	2003
GEPAID:	CAC002558884
Contact:	STEVE DEWAN
Telephone:	6507620110
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAT080014079
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Transfer Station
Tons:	0.45
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S112926187
Year:	2002
GEPAID:	CAC002558884
Contact:	STEVE DEWAN
Telephone:	6507620110
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAL000153023
TSD County:	Not reported

BURLINGAME HUGH SCHOOL (Continued) **S112926187**

Waste Category:	Not reported
Disposal Method:	Disposal, Land Fill
Tons:	345.54
Cat Decode:	Not reported
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112926187
Year:	2002
GEPAID:	CAC002558884
Contact:	STEVE DEWAN
Telephone:	6507620110
Mailing Name:	Not reported
Mailing Address:	650 N DELEWARE ST
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.76
Cat Decode:	Other organic solids
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

E143
West
1/8-1/4
0.165 mi.
869 ft.

CRAIG ROGERS **HAZNET** **S112874587**
1418 BELLEVUE **N/A**
BURLINGAME, CA 94010

Site 11 of 14 in cluster E

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S112874587
Year:	1996
GEPAID:	CAC001212424
Contact:	CRAIG ROGERS
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	P.O. BOX 546‘
Mailing City,St,Zip:	MILLBRAE, CA 940300000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	1.0425
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

B144 **BB STERN COMPANY** **San Mateo Co. BI** **S113757288**
East **222 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.167 mi.
881 ft. **Site 27 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0025127
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0033106
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

B145 **A J A INVESTMENTS, L.P.** **HAZNET** **S112895095**
East **222 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.167 mi.
881 ft. **Site 28 of 35 in cluster B**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112895095
Year:	1998
GEPAID:	CAC001486552
Contact:	A J A INVESTMENTS, L.P.
Telephone:	6503435146
Mailing Name:	Not reported
Mailing Address:	5 TERRIER PLACE
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	.2750
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

B146 **STERLING CLEANERS (FORMER)** **LUST** **S110275436**
ESE **215 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.167 mi.
884 ft. **Site 29 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

LUST:

Region:	STATE
Global Id:	T10000003211
Latitude:	37.5788130708654
Longitude:	-122.344790697098
Case Type:	LUST Cleanup Site
Status:	Open - Site Assessment
Status Date:	08/11/2011
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	660105

STERLING CLEANERS (FORMER) (Continued) **S110275436**

File Location: All Files are on GeoTracker or in the Local Agency Database
Potential Media Affect: Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Stoddard solvent / Mineral Spriits / Distillates
Site History: multiple stoddard tanks removed 3/2011. Case opened 8/11/2011 based on evidence of free-product in groundwater.

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000003211
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T10000003211
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T10000003211
Status: Open - Case Begin Date
Status Date: 08/11/2011

Global Id: T10000003211
Status: Open - Site Assessment
Status Date: 08/11/2011

Regulatory Activities:
Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 04/21/2015
Action: Staff Letter - #20150421

Global Id: T10000003211
Action Type: RESPONSE
Date: 04/25/2014
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 01/12/2012
Action: Staff Letter - #20120112

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 02/28/2012
Action: Staff Letter - #20120228

STERLING CLEANERS (FORMER) (Continued) **S110275436**

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 01/19/2012
Action: Notice of Responsibility - #20120119

Global Id: T10000003211
Action Type: RESPONSE
Date: 11/21/2014
Action: Site Assessment Report - Regulator Responded

Global Id: T10000003211
Action Type: RESPONSE
Date: 09/18/2015
Action: Proposed Plan - Regulator Responded

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 02/03/2015
Action: Staff Letter - #20150203

Global Id: T10000003211
Action Type: RESPONSE
Date: 03/13/2015
Action: Remedial Investigation Workplan - Regulator Responded

Global Id: T10000003211
Action Type: RESPONSE
Date: 11/15/2015
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 02/13/2014
Action: Staff Letter - #20140213

Global Id: T10000003211
Action Type: RESPONSE
Date: 09/30/2011
Action: Verbal Communication

Global Id: T10000003211
Action Type: RESPONSE
Date: 02/15/2016
Action: Other Report / Document

Global Id: T10000003211
Action Type: RESPONSE
Date: 02/24/2012
Action: Verbal Communication

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 07/23/2014
Action: Staff Letter - #2014072014

Global Id: T10000003211
Action Type: ENFORCEMENT

STERLING CLEANERS (FORMER) (Continued) **S110275436**

Date: 08/11/2011
Action: Staff Letter - #20110811

Global Id: T10000003211
Action Type: RESPONSE
Date: 06/29/2012
Action: Site Assessment Report

Global Id: T10000003211
Action Type: Other
Date: 03/17/2011
Action: Leak Discovery

Global Id: T10000003211
Action Type: RESPONSE
Date: 05/15/2014
Action: Monitoring Report - Quarterly

Global Id: T10000003211
Action Type: Other
Date: 07/06/2011
Action: Leak Reported

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 03/28/2013
Action: Staff Letter - #20130328

Global Id: T10000003211
Action Type: RESPONSE
Date: 04/20/2015
Action: Correspondence

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 09/30/2015
Action: Staff Letter - #20150930

Global Id: T10000003211
Action Type: RESPONSE
Date: 02/15/2015
Action: Monitoring Report - Quarterly

Global Id: T10000003211
Action Type: RESPONSE
Date: 12/31/2015
Action: CAP/RAP - Feasibility Study Report

Global Id: T10000003211
Action Type: Other
Date: 03/17/2011
Action: Leak Stopped

Global Id: T10000003211
Action Type: RESPONSE
Date: 02/15/2012
Action: Preliminary Site Assessment Workplan - Regulator Responded

STERLING CLEANERS (FORMER) (Continued) **S110275436**

Global Id: T10000003211
Action Type: RESPONSE
Date: 01/11/2013
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T10000003211
Action Type: RESPONSE
Date: 08/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T10000003211
Action Type: RESPONSE
Date: 08/23/2013
Action: Site Assessment Report - Regulator Responded

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 09/29/2011
Action: Staff Letter - #20110929

Global Id: T10000003211
Action Type: ENFORCEMENT
Date: 09/06/2012
Action: Staff Letter - #20120906

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660105
Facility Status: 3B- Preliminary Assessment Underway
Global ID: T10000003211
APN Number: 029211080
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

Region: SAN MATEO
Facility ID: 669113
Facility Status: 3B- Preliminary Assessment Underway
Global ID: T10000005652
APN Number: 029211080
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

B147 **STERLING CLEANERS (FORMER)** **RGA LUST** **S114696023**
ESE **215 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.167 mi.
884 ft. **Site 30 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2012	STERLING CLEANERS (FORMER)	215 CALIFORNIA DRIVE
2011	STERLING CLEANERS (FORMER)	215 CALIFORNIA DRIVE

B148 **UST SITE** **SLIC** **S113758800**
ESE **215 CALIFORNIA** **San Mateo Co. BI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.167 mi.
884 ft. **Site 31 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	02/13/2014
Global Id:	T10000005652
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669113
Latitude:	37.5788353
Longitude:	-122.3444406
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Likely PCE detected is from adjacent site, will likely close upon confirmation.

Click here to access the California GeoTracker records for this facility:

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0046059
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0061786
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

B149 **FEDERAL AUTO PARTS** **San Mateo Co. BI** **S113756631**
East **231 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.170 mi.
895 ft. **Site 32 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018038
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011854
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018038
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004672
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

B150 **FEDERAL AUTO PARTS** **HAZNET** **S113164103**
East **231 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.170 mi.
895 ft. **Site 33 of 35 in cluster B**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S113164103
Year:	1994
GEPAID:	CAL913235870
Contact:	W BERRY HURLEY
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	231 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD083166728
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	.2085
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

C151 **PANDA EXPRESS #907** **San Mateo Co. BI** **S118584898**
SSW **1453 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.172 mi.
907 ft. **Site 19 of 19 in cluster C**

Relative:
Higher

Actual:
40 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0028060
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0082163
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

H152 **DEWEY LAND COMPANY, INC.** **HAZNET** **S117301576**
SW **1450 CHAPIN AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.172 mi.
910 ft. **Site 1 of 22 in cluster H**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S117301576
Year:	2013
GEPAID:	CAC002744728
Contact:	OPI COMMERCIAL BUILDERS
Telephone:	4083774800
Mailing Name:	Not reported
Mailing Address:	999 BAKER WAY STE 300
Mailing City,St,Zip:	SAN MATEO, CA 944041581
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported

DEWEY LAND COMPANY, INC. (Continued) **S117301576**

Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	22
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

E153 **CHATEAU APARTMENTS** **HAZNET** **S112932473**
West **1422 BELLEVUE AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.173 mi.
914 ft. **Site 12 of 14 in cluster E**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S112932473
Year:	2003
GEPAID:	CAC002569610
Contact:	MIKE DROUIN
Telephone:	6505965300
Mailing Name:	Not reported
Mailing Address:	350 BRIDGE PKWY
Mailing City,St,Zip:	REDWOOD CITY, CA 94065
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method:	Disposal, Land Fill
Tons:	2.52
Cat Decode:	Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112932473
Year:	2003
GEPAID:	CAC002569610
Contact:	MIKE DROUIN
Telephone:	6505965300
Mailing Name:	Not reported
Mailing Address:	350 BRIDGE PKWY
Mailing City,St,Zip:	REDWOOD CITY, CA 94065
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	6.74
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

G154 **UST SITE** **San Mateo Co. BI** **S113758833**
SE **1290 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94011**
0.179 mi.
947 ft. **Site 3 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0046413
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0063109
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

B155 **TUCKER TRANSMISSIONS** **San Mateo Co. BI** **S113755456**
ESE **215 HATCH** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
948 ft. **Site 34 of 35 in cluster B**

Relative:
Higher

Actual:
35 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0009063
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011911
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0009063
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0029207
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

B156 **EDR Hist Auto** **1015327067**
ESE **215 HATCH LN** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
948 ft. **Site 35 of 35 in cluster B**

Relative:
Higher

Actual:
35 ft.

EDR Historical Auto Stations:

Name:	TUCKERS TRANSMISSIONS
Year:	1999
Address:	215 HATCH LN

Name:	TUCKERS TRANSMISSIONS
Year:	2000
Address:	215 HATCH LN

E157 **ARLINGTON APARTMENTS** **LUST** **S113758618**
West **1401 FLORIBUNDA** **San Mateo Co. BI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
948 ft. **Site 13 of 14 in cluster E**

Relative:
Lower

Actual:
28 ft.

LUST:

Region:	STATE
Global Id:	T10000005179
Latitude:	37.580006
Longitude:	-122.351129
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/29/2014
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	660112
File Location:	Local Agency
Potential Media Affect:	Not reported
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T10000005179
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T10000005179
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T10000005179
Status:	Completed - Case Closed
Status Date:	01/29/2014

Global Id:	T10000005179
Status:	Open - Case Begin Date
Status Date:	06/05/2013

Global Id:	T10000005179
Status:	Open - Eligible for Closure
Status Date:	10/02/2013

ARLINGTON APARTMENTS (Continued) **S113758618**

Regulatory Activities:

Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	10/23/2013
Action:	Notice of Responsibility - #20131023
Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	11/07/2013
Action:	Notification - Preclosure - #20131107
Global Id:	T10000005179
Action Type:	Other
Date:	06/05/2013
Action:	Leak Discovery
Global Id:	T10000005179
Action Type:	Other
Date:	06/11/2013
Action:	Leak Reported
Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	01/29/2014
Action:	Closure/No Further Action Letter - #20140129

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0043363
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0073857
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

E158 **THE ARLINGTON APARTMENTS** **LUST** **S112978903**
West **1401 FLORIBUNDA AVE** **HAZNET** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
948 ft. **Site 14 of 14 in cluster E**

Relative:
Lower

Actual:
28 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660112
Facility Status:	9- Case Closed
Global ID:	Not reported
APN Number:	029112320
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HAZNET:

envid:	S112978903
Year:	2009
GEPAID:	CAC002643932
Contact:	ELAINE RIBAY
Telephone:	6505923960

THE ARLINGTON APARTMENTS (Continued) **S112978903**

Mailing Name:	Not reported
Mailing Address:	1050 RALSTON AVE
Mailing City,St,Zip:	BELMONT, CA 94002
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.085
Cat Decode:	Other inorganic solid waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

G159 **210 PRIMROSE LLC** **HAZNET** **S113791563**
SSE **210 PRIMROSE RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
950 ft. **Site 4 of 61 in cluster G**

Relative: **Higher**

Actual: **39 ft.**

HAZNET:

envid:	S113791563
Year:	2012
GEPAID:	CAC002709747
Contact:	210 PRIMROSE LLC
Telephone:	6503482345
Mailing Name:	Not reported
Mailing Address:	5 WOODGATE CT
Mailing City,St,Zip:	HILLSBOROUGH, CA 940106245
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

G160 **200 PARK RD COMPANY LLC** **EMI** **S113787268**
SE **200 PARK RD** **HAZNET** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
950 ft. **Site 5 of 61 in cluster G**

Relative: **Higher**

Actual: **37 ft.**

EMI:

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	21444
Air District Name:	BA
SIC Code:	6512
Air District Name:	BAY AREA AQMD

200 PARK RD COMPANY LLC (Continued) **S113787268**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	22688
Air District Name:	BA
SIC Code:	6512
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.225033081
Reactive Organic Gases Tons/Yr:	0.225033081
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HAZNET:

envid:	S113787268
Year:	2012
GEPAID:	CAC002703041
Contact:	MARK GREEN
Telephone:	6505088018
Mailing Name:	Not reported
Mailing Address:	216 PARK RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	NVT330010000
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.126
Cat Decode:	Not reported
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113787268
Year:	2012
GEPAID:	CAC002703041
Contact:	MARK GREEN
Telephone:	6505088018
Mailing Name:	Not reported
Mailing Address:	216 PARK RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo

200 PARK RD COMPANY LLC (Continued) **S113787268**

TSD EPA ID: NVT330010000
TSD County: 99
Waste Category: Not reported
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 1.60545
Cat Decode: Not reported
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

G161 **UST SITE** **San Mateo Co. BI** **S113758908**
SE **200 PARK** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
950 ft. **Site 6 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0048379
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0066115
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

G162 **200 PARK** **RGA LUST** **S114565938**
SE **200 PARK ROAD** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.180 mi.
950 ft. **Site 7 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

RGA LUST:
2012 200 PARK 200 PARK ROAD

G163 **200 PARK** **LUST** **S112141896**
SE **200 PARK ROAD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.180 mi.
950 ft. **Site 8 of 61 in cluster G**

Relative:
Higher

Actual:
37 ft.

LUST:
Region: STATE
Global Id: T10000004152
Latitude: 37.5774101
Longitude: -122.3457145
Case Type: LUST Cleanup Site
Status: Open - Assessment & Interim Remedial Action
Status Date: 06/25/2012
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker: MEJ
Local Agency: Not reported
RB Case Number: 41-1312
LOC Case Number: Not reported
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)

200 PARK (Continued) **S112141896**

Potential Contaminants of Concern: Gasoline, Total Petroleum Hydrocarbons (TPH)
Site History: The Site is located at the north corner of the intersection of Howard Avenue and Park Road in downtown Burlingame, California was previously the location of the former Pitts Nelson Service Station. Historic City directories show that the 200 Park Road property operated as a gasoline service station from at least 1930 to no later than 1961. The property has since been redeveloped and includes an 80 by 100 foot multi-story commercial building that roughly occupies the entire footprint of the property. A 500-1,000 gallon underground storage tank was closed in place by RRM Inc. in March 2011. (Low Threat Closure Policy Assessment and Proposed Workplan to Address Remaining Potential Environmental Impacts related to a Former Underground Fuel Storage Tank, March 31, 2015)

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000004152
Contact Type: Regional Board Caseworker
Contact Name: MARK JOHNSON
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY STREET, SUITE 1400
City: OAKLAND
Email: mjohnson@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T10000004152
Status: Open - Assessment & Interim Remedial Action
Status Date: 06/25/2012

Global Id: T10000004152
Status: Open - Case Begin Date
Status Date: 01/01/2012

Regulatory Activities:
Global Id: T10000004152
Action Type: ENFORCEMENT
Date: 10/22/2012
Action: Staff Letter

Global Id: T10000004152
Action Type: RESPONSE
Date: 04/07/2015
Action: Interim Remedial Action Plan - Regulator Responded

Global Id: T10000004152
Action Type: ENFORCEMENT
Date: 07/23/2012
Action: Staff Letter

Global Id: T10000004152
Action Type: ENFORCEMENT
Date: 10/19/2012
Action: Staff Letter

Global Id: T10000004152

200 PARK (Continued) **S112141896**

Action Type:	Other
Date:	01/01/2012
Action:	Leak Discovery
Global Id:	T10000004152
Action Type:	Other
Date:	01/01/2012
Action:	Leak Reported
Global Id:	T10000004152
Action Type:	RESPONSE
Date:	04/16/2012
Action:	Other Report / Document
Global Id:	T10000004152
Action Type:	Other
Date:	01/01/2012
Action:	Leak Began

G164 **BRIAN KELLEHER** **HAZNET** **S112909857**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 9 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112909857
Year:	2000
GEPAID:	CAC002289577
Contact:	JULIE DASINGER - ENG
Telephone:	8314758141
Mailing Name:	Not reported
Mailing Address:	3912 PORTOLA DR STE 8
Mailing City,St,Zip:	SANTA CRUZ, CA 950620000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.62
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

G165 **CHRISASI HARRIS TRUST** **HAZNET** **S112902936**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 10 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112902936
Year:	2000
GEPAID:	CAC002197025
Contact:	KATHY HARRIS/PROJ MGR

CHRISASI HARRIS TRUST (Continued) **S112902936**

Telephone:	4086629411
Mailing Name:	Not reported
Mailing Address:	21265 STEVENS CREEK BLVD STE 205
Mailing City,St,Zip:	CUPERTINO, CA 950140000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.95
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

G166 **HARRIS PROPERTY** **RGA LUST** **S114630931**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.182 mi.
959 ft. **Site 11 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

2002	HARRIS PROPERTY	1234 HOWARD AVE
2001	HARRIS PROPERTY	1234 HOWARD AVE
2000	HARRIS PROPERTY	1234 HOWARD AVE
1998	HARRIS PROPERTY	1234 HOWARD AVE
1997	HARRIS PROPERTY	1234 HOWARD AVE
1996	HARRIS PROPERTY	1234 HOWARD AVE
1995	HARRIS PROPERTY	1234 HOWARD AVE
1994	HARRIS PROPERTY	1234 HOWARD AVE
1993	HARRIS PROPERTY	1234 HOWARD AVE
1992	HARRIS PROPERTY	1234 HOWARD AVE

G167 **HARRIS PROPERTY** **RGA LUST** **S114630932**
SE **1234 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.182 mi.
959 ft. **Site 12 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

2012	HARRIS PROPERTY	1234 HOWARD
2011	HARRIS PROPERTY	1234 HOWARD
2010	HARRIS PROPERTY	1234 HOWARD
2009	HARRIS PROPERTY	1234 HOWARD
2008	HARRIS PROPERTY	1234 HOWARD
2007	HARRIS PROPERTY	1234 HOWARD
2006	HARRIS PROPERTY	1234 HOWARD
2005	HARRIS PROPERTY	1234 HOWARD
2003	HARRIS PROPERTY	1234 HOWARD

G168 **HARRIS-CRISAFI CLEAN-UP TRUST** **FINDS** **1011988062**
SE **1234 HOWARD AVENUE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 13 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110038003344

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011988062
Registry ID: 110038003344
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038003344

G169 **HARRIS & CRISAFI C/O RRM** **FINDS** **1006825561**
SE **1234 HOWARD AVENUE** **EMI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.182 mi.
959 ft. **Site 14 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110013845802

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

EMI:

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	10105
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	10105
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported

HARRIS & CRISAFI C/O RRM (Continued) **1006825561**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	10105
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	10105
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	10105
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

HARRIS & CRISAFI C/O RRM (Continued) **1006825561**

Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2003
County Code: 41
Air Basin: SF
Facility ID: 10105
Air District Name: BA
SIC Code: 6512
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

ECHO:
Envid: 1006825561
Registry ID: 110013845802
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110013845802

G170 **CHRISAFI/HARRIS TRUST** **HAZNET** **S113135683**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 15 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:
envid: S113135683
Year: 2008
GEPAID: CAL000290514
Contact: BRIAN KELLEHER
Telephone: 4085287719
Mailing Name: Not reported
Mailing Address: 1658 CAPITOL EXPRESSWAY
Mailing City,St,Zip: SAN JOSE, CA 95121
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.19
Cat Decode: Waste oil and mixed oil
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113135683
Year: 2006
GEPAID: CAL000290514
Contact: BRIAN KELLEHER
Telephone: 4085287719

CHRISAFI/HARRIS TRUST (Continued) **S113135683**

Mailing Name:	Not reported
Mailing Address:	1658 CAPITOL EXPRESSWAY
Mailing City,St,Zip:	SAN JOSE, CA 95121
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	2.5
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113135683
Year:	2006
GEPAID:	CAL000290514
Contact:	BRIAN KELLEHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 CAPITOL EXPRESSWAY
Mailing City,St,Zip:	SAN JOSE, CA 95121
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.68
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

G171 **CHRISAFI/HARRIS TRUST** **HAZNET** **S112924592**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 16 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112924592
Year:	2003
GEPAID:	CAC002556147
Contact:	BRIAN KELLEHER
Telephone:	4082538365
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPRESSWAY PMB 293
Mailing City,St,Zip:	SAN JOSE, CA 951210000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.06
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112924592
Year:	2002

CHRISAFI/HARRIS TRUST (Continued) **S112924592**

GEPAID:	CAC002556147
Contact:	BRIAN KELLEHER
Telephone:	4082538365
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPRESSWAY PMB 293
Mailing City,St,Zip:	SAN JOSE, CA 951210000
Gen County:	Not reported
TSD EPA ID:	CAL000190816
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.56
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

G172 **NORMAN HARRIS** **HAZNET** **S112888171**
SE **1234 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 17 of 61 in cluster G**

Relative: **Higher**

Actual: **36 ft.**

HAZNET:

envid:	S112888171
Year:	1998
GEPAID:	CAC001400272
Contact:	NORMAN HARRIS
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	3912 PORTOLA DR #8
Mailing City,St,Zip:	SANTA CRUZ, CA 950620000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.0417
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

G173 **HARRIS PROPERTY** **LUST** **S100234001**
SE **1234 HOWARD** **HIST CORTESE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 18 of 61 in cluster G**

Relative: **Higher**

Actual: **36 ft.**

LUST:

Region:	STATE
Global Id:	T0608100253
Latitude:	37.577708
Longitude:	-122.344647
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	08/01/1989
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)

HARRIS PROPERTY (Continued) **S100234001**

Case Worker:	MEJ
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0265
LOC Case Number:	Not reported
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from RRM's March 17, 2010, Second Semi-annual 2009 remediation Performance and Groundwater Monitoring Report. San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. Evidence of subsurface fuel contamination at the 1234 Howard Avenue site was discovered in May 1989 during the removal of a 1,000gallon gasoline UST. Evidence of subsurface contamination at the 1200 Howard Avenue site was discovered in June 1994 during subsurface investigations associated with the 1234 Howard Avenue site. Site investigations conducted between 1994 and 1998 revealed a commingled plume of gasolineimpacted groundwater projecting southeast from the two properties. The plume crosses Howard Avenue and impacts a portion of the city block bounded by Howard, Lorton, and Park Avenues. Impacted properties include three commercial properties on Howard Avenue (1201, 1205, and 1209 Howard Avenue); a portion of the Colewood Apartment complex at 137 Lorton Avenue; and a portion of the City of Burlingame public parking lot at 130 Park Avenue. As of 1999, dissolved total petroleum hydrocarbon concentrations as gasoline (TPHg) within the center of the plume exceeded 100,000 parts per billion (ppb) and separatephase hydrocarbons (SPH) on the water table surface at some locations. The groundwater table ranges seasonally between approximately 10 feet and 20 feet bgs; the soil column within this zone is also impacted. To provide a practical approach to remediate the area impacted with petroleum hydrocarbons, RRM divided the commingled plume into three sections for the purpose of addressing each section in phases as follows: Phase 1: Up to January 1997, the plume section under remediation was the portion beneath the former police station fuel UST and pump island (1234 Howard Avenue). This included the installation of an extraction well network and a treatment compound located to the northwest (rear) of the 1234 Howard Avenue property that was started up in June 1996 (Crisafi treatment compound). Phase 2: In 1997, RRM completed installation of an extraction well network for the second phase of work, which encompasses the area of the former fuel UST at 1200 Howard Avenue. The zone between 1234 Howard Avenue, and 1200 Howard Avenue; the remediation system was reactivated on July 15, 1997. Phase 3: In 19992000, RRM completed installation of an extraction well network for the third phase of work, which encompasses the area on the southeastern side of Howard Avenue (across the street from 1200 and 1234 Howard Avenues). At that time, RRM constructed a second treatment compound in the public parking lot located on the south side of Howard Avenue between Park Road and Lorton Avenue (Shaffer treatment compound). The second remediation system was activated on October 3, 2000. Collectively, the remediation well network includes 32 coextraction wells and 33 sparging wells. The treatment system compounds include the following unit processes: (1) the coextraction systems utilize regenerative blowers for the purpose of creating negative pressure gradients on the unsaturated andsaturated zones beneath the surface via the coextraction wells; (2) the extracted vapors are abated through the use of catalytic incinerators prior to

HARRIS PROPERTY (Continued) **S100234001**

atmospheric discharge; (3) the extracted groundwater is treated with granular activated carbon prior to discharge to the sanitary sewer; (4) the air sparging systems utilize air compressors to inject air beneath the water table for the purpose of stripping volatiles and providing oxygen to groundwater in order to promote aerobic biodegradation of dissolved petroleum hydrocarbons; and, (3) at 1234 Howard Avenue, ozone sparging was initiated in November 2001. This process utilizes the existing sparging well network to deliver ozone to the groundwater for the purpose of chemically oxidizing dissolved petroleum hydrocarbons. As established in 19941997, the objectives of the interim site remediation program were: 1. As a priority, remove any residual SPH layers and mitigate all potential human health impacts associated with vaporphase migration of volatile gasoline constituents. 2. Meet department of Health Services maximum contaminant levels (MCLs) for benzene, toluene, ethylbenzene, and xylenes (collectively BTEX) in groundwater. 3. Meet the tentative TPHg cleanup goal for soil of 100 parts per million (ppm). 4. Cleanup petroleum impacted soils and groundwater to the extent practical, using commercially proven control technologies that best represent the current state of the art for cost effective LUFT site remediation. If such technologies prove incapable of meeting MCLs for groundwater, then reduce concentrations to an asymptotic level and/or riskbased corrective action levels. 5. Implement the program in a manner that avoids or minimizes to the greatest extent possible, any disruptions to the normal course of business on all affected properties. This includes, but is not limited to, compliance with the noise control ordinance of The City of Burlingame and careful consideration in scheduling constructionrelated work activities such as the installation of wells, piping, drainage, electrical service, and water or sewer service. Due to the pronounced seasonal fluctuations of the shallow groundwater table, RRM has limited spargingenhanced soil vapor extraction (SESVE) system operations to approximately sixmonth intervals, operating from approximately July through January. During the winter, spring, and early summer, the high water table conditions close the screened intervals of the extraction wells. The CAP approved by the County on June 3, 2005, calls for meeting the San Francisco Bay Regional Water Quality Control Boards (RWQCB) environmental screening levels (ESLs) for TPHg and benzene by upgrading and expanding SESVE system. The upgrades include the following work all of which has been completed as of the third quarter 2007 except for replacement of sparging well SP3A and installation of ozone sparging unit processes: 1. Remove the treatment compound from 1234 Howard Avenue and replace it with a satellite ozonesparging system. The satellite ozonesparging system will serve the existing/expanded sparging well network on the north side of Howard Avenue and will be enclosed in a custom designed enclosure with a leakdetection/autoshutoff system. The system will also be designed/installed to shut down under lowvacuum conditions in the vapor extraction conveyance lines. RRM is currently recommending the installation of a satellite airsparging system (25 HP rotary screw air compressor) in lieu of the originally proposed satellite ozone sparging system. 2. Connect the existing/expanded extractionwell network on the north side of Howard Avenue to the extractionwell network on the south side of Howard Avenue by running subsurface conveyance piping across Howard Avenue. 3. Upgrade the remediation equipment in the existing treatment compound located in the City parking lot on the south side of Howard Avenue to include

HARRIS PROPERTY (Continued) **S100234001**

either reconfiguring the exiting vacuum pump to operate at higher vacuum or replacing it with a highvacuum liquidring pump. RRM originally proposed conducting some quick performance testing to help decide between the two options, but ultimately recommended replacing the existing pump assembly with a 400 standard cubic feet per minute (scfm) capacity clawtype vacuum pump capable of operating efficiently under both high and low vacuum conditions. 4. Install six additional extraction wells to provide complete coverage of the heavily impacted area of soil and groundwater (50,000 ppb TPHg contour) including three new wells to the south of Howard Avenue and three new wells to the north of Howard to include at least one interior well at 1200 Howard subject to the approval of the owner. In addition, existing monitoring well MW7 on the south side of Howard is to be connected into the system. Three interior vapor extraction wells were ultimately installed inside 1200 Howard based on the large amount of contamination encountered. 5. Install fourteen additional air/ozonesparging wells to provide complete coverage of the heavily impacted area of groundwater (50,000 ppb TPHg contour) including eight new wells to the south of Howard Avenue and six new wells to the north of Howard to include at least one interior well at 1200 Howard subject to the approval of the owner. This includes the replacement of existing sparge well SP3A located in the basement of 1234 Howard. Three interior sparge wells were ultimately installed inside 1200 Howard based on the large amount of contamination encountered. 6. Complete slabinstallation work at 1234 Howard and install additional slabventing systems for the commercial buildings at 1200 Howard, 1209 Howard, and the northern half of 1201 Howard. Slabventing system have already been installed at 1205 Howard and 127 Lorton Avenue and are working well. The slabventing systems will provide insurance that fugitive vapors will not enter buildings during the period of active remediation.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100253
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0608100253
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100253
Status:	Open - Case Begin Date
Status Date:	08/01/1989

HARRIS PROPERTY (Continued) **S100234001**

Global Id: T0608100253
Status: Open - Remediation
Status Date: 08/01/1989

Regulatory Activities:
Global Id: T0608100253
Action Type: RESPONSE
Date: 08/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 06/01/1990
Action: Notice of Responsibility - #1

Global Id: T0608100253
Action Type: RESPONSE
Date: 02/15/2010
Action: Other Report / Document

Global Id: T0608100253
Action Type: RESPONSE
Date: 10/15/2011
Action: Site Assessment Report

Global Id: T0608100253
Action Type: RESPONSE
Date: 02/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: Other
Date: 08/01/1989
Action: Leak Discovery

Global Id: T0608100253
Action Type: Other
Date: 10/10/1989
Action: Leak Reported

Global Id: T0608100253
Action Type: RESPONSE
Date: 09/18/2009
Action: Other Workplan

Global Id: T0608100253
Action Type: RESPONSE
Date: 08/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 04/29/2010
Action: Staff Letter - #20100429

Global Id: T0608100253
Action Type: RESPONSE

HARRIS PROPERTY (Continued) **S100234001**

Date: 08/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: REMEDIATION
Date: 10/01/1996
Action: Soil Vapor Extraction (SVE)

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 06/08/2011
Action: Staff Letter - #20110608

Global Id: T0608100253
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: RESPONSE
Date: 02/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: REMEDIATION
Date: 10/01/1996
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 03/26/2009
Action: Staff Letter - #20090326

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 05/24/2007
Action: Staff Letter - #20070524

Global Id: T0608100253
Action Type: RESPONSE
Date: 07/30/2010
Action: Other Workplan - Regulator Responded

Global Id: T0608100253
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 03/09/2011
Action: Staff Letter - #20110309

Global Id: T0608100253
Action Type: RESPONSE
Date: 02/15/2011
Action: Monitoring Report - Semi-Annually

HARRIS PROPERTY (Continued) **S100234001**

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 10/14/2009
Action: Staff Letter - #20091014

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 07/07/2009
Action: Staff Letter - #20090707

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 10/20/2009
Action: Letter - Notice - #20091020

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 09/21/2011
Action: Referral to Regional Board - #20110921

Global Id: T0608100253
Action Type: ENFORCEMENT
Date: 04/01/2011
Action: Staff Letter - #20110401

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Remedial action (cleanup) Underway
Case Number: 660036
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: 1/1/1965
Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0265

G174 **HARRIS-CRISAFI CLEAN-UP TRUST** **EMI** **S108432063**
SE **1234 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 19 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EMI:

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.003
Reactive Organic Gases Tons/Yr:	.0020958
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0006986
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008

HARRIS-CRISAFI CLEAN-UP TRUST (Continued) **S108432063**

County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0006986
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	17222
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	6.9859999999999996E-4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

G175 **CHRISAFI/HARRIS TRUST** **HAZNET** **S112935416**
SE **1234 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.182 mi.
959 ft. **Site 20 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112935416
Year:	2004
GEPAID:	CAC002574154
Contact:	BRIAN KELLEHER/CLIENT
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	3912 PORTOLA DR STE 8
Mailing City,St,Zip:	SANTA CRUZ, CA 95062
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.5
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

G176 **EDR Hist Auto** **1015186200**
SE **1220 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.183 mi.
965 ft. **Site 21 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EDR Historical Auto Stations:

Name:	DEANS AUTO BODY & PAINTING INC
Year:	2002
Address:	1220 HOWARD AVE

G177 **KING YEE PROPERTY** **RGA LUST** **S114640085**
SE **1200 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.185 mi.
975 ft. **Site 22 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

2002	KING YEE PROPERTY	1200 HOWARD AVE
2001	KING YEE PROPERTY	1200 HOWARD AVE
2000	KING YEE PROPERTY	1200 HOWARD AVE
1998	KING YEE PROPERTY	1200 HOWARD AVE
1997	KING YEE PROPERTY	1200 HOWARD AVE
1996	KING YEE PROPERTY	1200 HOWARD AVE
1995	KING YEE PROPERTY	1200 HOWARD AVE

G178 **KING YEE PROPERTY** **LUST** **S102432235**
SE **1200 HOWARD** **HIST CORTESE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.185 mi.
975 ft. **Site 23 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

LUST:

Region:	STATE
Global Id:	T0608100813
Latitude:	37.577876
Longitude:	-122.344407
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	03/03/1994
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	MEJ
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0871
LOC Case Number:	Not reported
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Excerpts extracted from RRM's March 19, 2010, second semi-annual 2009 groundwater monitoring report. San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. Beginning with the fourth quarter 2001, the activities for the 1200 Howard Avenue site and the 1234 Howard Avenue site are combined into one section, which include the twocoextraction/air sparging systems. The activities completed from January 2002 through 2008 are summarized below. 1. Attended a site meeting on January 16, 2002; representatives of the SMCHSA were present. During the meeting, water levels were gauged and an inspection was made in the basement of the restaurant at 1205 Howard Avenue in response to complaints of odors. Pursuant to the resolves of the meeting, the SESVE system serving the 1205 Howard Avenue area (the Shaffer treatment compound) was deactivated due to high water table conditions and concerns regarding migrant vapors. 2. Initiated an ozone sparging pilot test at 1234 Howard Avenue on February 5, 2002. RRM conducted biweekly grab groundwater sampling of wells MW1, MW2, MW3, EW3, EW4, EW5, EW6, EW7, EW8, EW9, EW10, PSB4, and PSB5 on November 29, 2001, December 26, 2001, January 10, 2002, and January 28, 2002. 3. Initiated an ozone sparging pilot test followup groundwater monitoring event on February 15, 2002, ten days after shut down of the combined ozonesparging enhanced SVE system on February 5, 2002 using the same wells incorporated into the biweekly groundwater sampling program. 6. Performed soil vapor sampling at two locations to the rear of the restaurant property at 1205 Howard Avenue on February 1, 2002 to evaluate the potential inhalation risk to residents of the apartment complex at 137 Lorton Avenue. 11. Initiated remediation system operations at 1200 Howard Avenue on July 10, 2002 and at 1234 Howard Avenue on July 9, 2002. Began ozone sparging at 1234 Howard Avenue on July 22, 2002. 12. Between July 22, 2002 and August 30, 2002, ozone was sparged into wells EW4 through EW8 for 30 minutes every hour. From August 30, 2002 through December 30, 2002, ozone was sparged into wells EW4, EW7, EW8, and SP1 through SP4 for 30 minutes every hour. Conducted approximately six months of routine remediation system operation and maintenance at the 1200 Howard Avenue and 1234 Howard Avenue sites through mid January 2003 and December 30, 2002,

KING YEE PROPERTY (Continued) **S102432235**

respectively. Tasks included: system performance optimization; measurement of operating parameters; measurement of extracted soil vapor concentrations before and after treatment using a field instrument equipped with an FID; collection of influent and effluent soil vapor samples (contained in Tedlar bags), collection of groundwater treatment system samples, and completion of field reports. Soil vapor and groundwater samples were analyzed for TPHg and BTEX by Entech Analytical Labs, Inc. 15. Installed groundwatermonitoring wells MW9 and MW10 on April 14, 2003. Installed groundwatermonitoring well MW11 on August 15, 2003. Installed slabvapor recovery systems at 1205 Howard Avenue, and at 137 Lorton Avenue during the third and fourth quarters 2003 with the aid of Max Llanos Construction, Inc. of Poway, California. Also during this period, upgraded the basement ventilation system at 1234 Howard Avenue in lieu of installing a slab venting system. 27. Deactivated the remediation system at 1200 Howard Avenue (Shaffer treatment compound) on January 21, 2004. 55. During October 2005 trenched, plumbed and connected seven (7) new sparge wells (SP15 through SP21) and four (4) new vapor extraction wells (EW23 through EW26) installed south of Howard Avenue to the existing SVE treatment system. 56. In October 2005 the original vacuum pump and motor associated with the Thermtech Thermal Oxidizer unit was changedout. Procedures included removal of the old blower and motor, fabrication of a new motor mount, retrofitting the intake and exhaust piping manifold, installation of a highvolume air filter, rewiring the power supply, replacing the knockout tank, and finally mounting the new blower and motor assembly that consisted of a Rietschle Corporation Zephyr VLR 400 highefficiency 400scfm vacuum pump. 57. The SVE and air sparging unit processes were restarted on November 2, 2005 and operated near continuously through December 2005. During this period operations were cycled through three sections of the well field on the south side of Howard Avenue at approximately twoweek intervals to maximize mass removal. 62. Drilled and constructed air sparge (SP23 through SP24) and soil vapor extraction (EW27 through EW29) wells inside the building located at 1200 Howard Avenue during February 2006. Also performed underground work to plumb new wells to the existing AS and SVE subsurface piping network. 63. Developed, sampled and surveyed for elevation wells EW27 and EW28 on February 8 and 9, 2006. 64. The slab venting system installed at 1234 Howard Avenue underwent initial startup operations on February 1 and 2, 2006. 65. Continually operated the slab venting systems located at 1200, 1201, 1205 and 1209 Howard Avenue and 137 Lorton Avenue from January through March 2006. Collected compliance airbag samples of the effluent at 1200, 1201, and 1209 Howard Avenue on a monthly basis. 81. In January 2007, RRM installed the remaining air sparge well proposed in RRMs May 31, 2005 Corrective Action Implementation Workplan as well as one additional vapor extraction well in the vicinity of existing sparge well SP18. The additional sparge well was installed on the south side of Howard Avenue in front of the alleyway separating the buildings at 1205 and 1209 Howard. The new well locations were plumbed to the existing SVE conveyancepiping system. 82. On March 30, 2007, RRM attended a meeting called by the City of Burlingame Building Department at the apartment complex located at 125/129 Lorton Avenue. The City called this meeting in response to complaints they had received from the property manager regarding gasoline odors in the garage and an apartment overlying the garage as well as foultasting tap water. The meeting was attended by a City of Burlingame

KING YEE PROPERTY (Continued) **S102432235**

representative, the property manager, several of the building owners, and the Court Consultant/Project Coordinator, Brian Kelleher. During the course of the meeting, RRM inspected the garage and a crawl space under the west side of the building in the presence of all parties, and took field measurements of total volatile hydrocarbons using a photoionization detector (PID). There were no detectable hydrocarbon odors or PID readings. RRM observed that there was a large hole in the ceiling of the garage surrounding a sewer drain line that would allow any exhaust fumes in the garage to enter the apartment located above the garage. RRM also collected a sample of the tap water and submitted it for certified analyses. RRM is preparing a separate report covering the site visit and test findings to include conclusions and recommendations. The property owners resolved to make immediate repairs to the ceiling of the garage. During the start of the meeting, the property manager had indicated that the fumes entering the apartment above the garage appeared to be entering from the area of the sewer drain lines. During the second and third quarters 2007, the SVE system removed and combusted approximately 3,578 pounds of gasoline vapors bringing the total mass removed to date to approximately 23,083 pounds. Through the end of September 2007, the average gasoline vapor removal rate was approximately 38.5 pounds per day. The system operated a total of 93 days during the second and third quarters 2007. 98. During the second, third, and fourth quarter 2008, RRM continued routine operation of the slab venting systems located at 1200, 1201, 1205, 1209, and 1234 Howard Avenue and 137 Lorton Avenue. RRM collected quarterly compliance airbag samples of the effluent from these systems during the months of June 2008, September 2008, and December 2008. In addition to compliance sampling, RRM performed monthly site visits to measure and record amp usage, discharge airflow, and hourmeter readings.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100813
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0608100813
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100813
Status:	Open - Case Begin Date
Status Date:	03/03/1994

KING YEE PROPERTY (Continued) **S102432235**

Global Id: T0608100813
Status: Open - Remediation
Status Date: 03/03/1994

Regulatory Activities:
Global Id: T0608100813
Action Type: RESPONSE
Date: 08/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 04/07/2005
Action: Staff Letter - #20050407

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 05/24/2007
Action: Staff Letter - #20070524

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 06/22/2005
Action: Staff Letter - #20050622

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 05/24/2005
Action: Staff Letter - #20050524

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 06/26/2001
Action: Staff Letter - #20010626

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 03/15/1994
Action: Notice of Responsibility - #1

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 10/20/2009
Action: Letter - Notice - #20091020

Global Id: T0608100813
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE

KING YEE PROPERTY (Continued) **S102432235**

Date: 09/18/2009
Action: Other Workplan

Global Id: T0608100813
Action Type: RESPONSE
Date: 10/15/2011
Action: Site Assessment Report

Global Id: T0608100813
Action Type: RESPONSE
Date: 08/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: RESPONSE
Date: 01/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: RESPONSE
Date: 07/15/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: Other
Date: 03/03/1994
Action: Leak Discovery

Global Id: T0608100813
Action Type: REMEDIATION
Date: 10/14/1996
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100813
Action Type: REMEDIATION
Date: 10/03/2000
Action: Soil Vapor Extraction (SVE)

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2010
Action: Other Report / Document

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 04/29/2010
Action: Staff Letter - #20100429

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 09/21/2011
Action: Referral to Regional Board - #20110921

Global Id: T0608100813
Action Type: Other
Date: 03/03/1994
Action: Leak Reported

KING YEE PROPERTY (Continued) **S102432235**

Global Id: T0608100813
Action Type: RESPONSE
Date: 08/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 03/26/2009
Action: Staff Letter - #20090326

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 03/09/2011
Action: Staff Letter - #20110309

Global Id: T0608100813
Action Type: RESPONSE
Date: 08/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 05/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100813
Action Type: RESPONSE
Date: 04/14/2004
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0608100813
Action Type: RESPONSE
Date: 06/02/2005
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0608100813
Action Type: RESPONSE

KING YEE PROPERTY (Continued) **S102432235**

Date: 06/21/2005
Action: Other Workplan

Global Id: T0608100813
Action Type: RESPONSE
Date: 07/19/2005
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0608100813
Action Type: RESPONSE
Date: 10/18/2005
Action: CAP/RAP - Other Report

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 02/12/2004
Action: Staff Letter - #20040212

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 04/12/2005
Action: Staff Letter - #20050412

Global Id: T0608100813
Action Type: RESPONSE
Date: 07/30/2010
Action: Other Workplan - Regulator Responded

Global Id: T0608100813
Action Type: RESPONSE
Date: 02/15/2011
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 10/14/2009
Action: Staff Letter - #20091014

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 07/07/2009
Action: Staff Letter - #20090707

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 04/01/2011
Action: Staff Letter - #20110401

Global Id: T0608100813
Action Type: ENFORCEMENT
Date: 06/08/2011
Action: Staff Letter - #20110608

LUST REG 2:
Region: 2
Facility Id: Not reported

KING YEE PROPERTY (Continued) **S102432235**

Facility Status:	Remedial action (cleanup) Underway
Case Number:	660070
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	1/1/1965
Date Post Remedial Action Monitoring Began:	Not reported

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0871

G179 **SHAFFER PROPERTY TRUST** **HAZNET** **S113136781**
SE **1200 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.185 mi.
975 ft. **Site 24 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S113136781
Year:	2008
GEPAID:	CAL000293133
Contact:	BRIAN KELLCHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPY
Mailing City,St,Zip:	SAN JOSE, CA 951211839
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.741
Cat Decode:	Waste oil and mixed oil
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113136781
Year:	2007
GEPAID:	CAL000293133
Contact:	BRIAN KELLCHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPY
Mailing City,St,Zip:	SAN JOSE, CA 951211839
Gen County:	Not reported
TSD EPA ID:	CAL000161743

SHAFFER PROPERTY TRUST (Continued) **S113136781**

TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.72
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113136781
Year:	2007
GEPAID:	CAL000293133
Contact:	BRIAN KELLCHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPY
Mailing City,St,Zip:	SAN JOSE, CA 951211839
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	1.14
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113136781
Year:	2006
GEPAID:	CAL000293133
Contact:	BRIAN KELLCHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPY
Mailing City,St,Zip:	SAN JOSE, CA 951211839
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.68
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113136781
Year:	2006
GEPAID:	CAL000293133
Contact:	BRIAN KELLCHER
Telephone:	4085287719
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPY
Mailing City,St,Zip:	SAN JOSE, CA 951211839
Gen County:	Not reported

SHAFFER PROPERTY TRUST (Continued) **S113136781**

TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.12
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

G180 **SHAFFER PROPERTY TRUST C/O RRM** **EMI** **S105939538**
SE **1200 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.185 mi.
975 ft. **Site 25 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EMI:

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF

SHAFFER PROPERTY TRUST C/O RRM (Continued) **S105939538**

Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.085
Reactive Organic Gases Tons/Yr:	0.059381
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.003493
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

SHAFFER PROPERTY TRUST C/O RRM (Continued) **S105939538**

Total Organic Hydrocarbon Gases Tons/Yr:	.004
Reactive Organic Gases Tons/Yr:	.0027944
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.385
Reactive Organic Gases Tons/Yr:	.268961
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.382
Reactive Organic Gases Tons/Yr:	.2668652
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.255
Reactive Organic Gases Tons/Yr:	0.178143
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

SHAFFER PROPERTY TRUST C/O RRM (Continued) **S105939538**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	11731
Air District Name:	BA
SIC Code:	6733
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.29899999999999999
Reactive Organic Gases Tons/Yr:	0.20888139999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

G181 **KING YEE PROPERTY** **RGA LUST** **S114640086**
SE **1200 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.185 mi.
975 ft. **Site 26 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

RGA LUST:

2012	KING YEE PROPERTY	1200 HOWARD
2011	KING YEE PROPERTY	1200 HOWARD
2010	KING YEE PROPERTY	1200 HOWARD
2009	KING YEE PROPERTY	1200 HOWARD
2008	KING YEE PROPERTY	1200 HOWARD
2007	KING YEE PROPERTY	1200 HOWARD
2006	KING YEE PROPERTY	1200 HOWARD
2005	KING YEE PROPERTY	1200 HOWARD
2003	KING YEE PROPERTY	1200 HOWARD

G182 **SHAFFER PROPERTY TRUST C/O RRM** **FINDS** **1011987873**
SE **1200 HOWARD AVENUE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.185 mi.
975 ft. **Site 27 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110038003228

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011987873
Registry ID:	110038003228
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110038003228

G183 **GRAY'S PAINT** **HAZNET** **S113114468**
ESE **1166 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.188 mi.
994 ft. **Site 28 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S113114468
Year:	2008
GEPAID:	CAL000226366
Contact:	JEFFREY GRAY
Telephone:	6503436535
Mailing Name:	Not reported
Mailing Address:	783 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Latex waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2085
Cat Decode:	Latex waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113114468
Year:	2007
GEPAID:	CAL000226366
Contact:	JEFFREY GRAY
Telephone:	6503436535
Mailing Name:	Not reported
Mailing Address:	1166 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Latex waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2
Cat Decode:	Latex waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113114468
Year:	2004
GEPAID:	CAL000226366
Contact:	JEFFREY GRAY
Telephone:	6503436535
Mailing Name:	Not reported
Mailing Address:	1166 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Latex waste

GRAY'S PAINT (Continued) **S113114468**

Disposal Method: Recycler
Tons: 0.41
Cat Decode: Latex waste
Method Decode: Recycler
Facility County: San Mateo

G184 **GRAYS PAINTING** **HAZNET** **S112915316**
ESE **1166 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.188 mi.
994 ft. **Site 29 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:
envid: S112915316
Year: 2003
GEPAID: CAC002358415
Contact: JEFF GRAY-OWNER
Telephone: 6503436535
Mailing Name: Not reported
Mailing Address: 1166 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Latex waste
Disposal Method: Transfer Station
Tons: 1.31
Cat Decode: Latex waste
Method Decode: Transfer Station
Facility County: San Mateo

envid: S112915316
Year: 2001
GEPAID: CAC002358415
Contact: JEFF GRAY-OWNER
Telephone: 6503436535
Mailing Name: Not reported
Mailing Address: 1166 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Latex waste
Disposal Method: Transfer Station
Tons: 0.45
Cat Decode: Latex waste
Method Decode: Transfer Station
Facility County: San Mateo

envid: S112915316
Year: 2001
GEPAID: CAC002358415
Contact: JEFF GRAY-OWNER
Telephone: 6503436535
Mailing Name: Not reported
Mailing Address: 1166 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported

GRAYS PAINTING (Continued) **S112915316**

TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Latex waste
Disposal Method: Not reported
Tons: 0.22
Cat Decode: Latex waste
Method Decode: Not reported
Facility County: San Mateo

G185 **BERENSTEIN ASSOC. PROPERTY** **RGA LUST** **S114582385**
SSE **1319 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.189 mi.
997 ft. **Site 30 of 61 in cluster G**

Relative:
Higher

RGA LUST:
2005 BERENSTEIN ASSOC. PROPERTY 1319 HOWARD

Actual:
38 ft.

G186 **STANLEY LO (GREEN BANKER)** **EMI** **S112959395**
SSE **1319 HOWARD AVE** **HAZNET** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 31 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

EMI:

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	20929
Air District Name:	BA
SIC Code:	7211
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.01
Reactive Organic Gases Tons/Yr:	0.006986
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	20929
Air District Name:	BA
SIC Code:	7211
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.014054768
Reactive Organic Gases Tons/Yr:	0.014054768
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

STANLEY LO (GREEN BANKER) (Continued) **S112959395**

Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr:0

HAZNET:

envid:	S112959395
Year:	2010
GEPAID:	CAC002613377
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	398 PRIMROSE RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Drilling mud
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Drilling mud
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S112959395
Year:	2007
GEPAID:	CAC002613377
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	199 CALIFORNIA DR STE 168
Mailing City,St,Zip:	MILLBRAE, CA 94030
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	164.28
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S112959395
Year:	2007
GEPAID:	CAC002613377
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	199 CALIFORNIA DR STE 168
Mailing City,St,Zip:	MILLBRAE, CA 94030
Gen County:	Not reported
TSD EPA ID:	CAT00646117
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To

STANLEY LO (GREEN BANKER) (Continued) **S112959395**

	Include On-Site Treatment And/Or Stabilization)
Tons:	93.71
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo
envid:	S112959395
Year:	2007
GEPAID:	CAC002613377
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	199 CALIFORNIA DR STE 168
Mailing City,St,Zip:	MILLBRAE, CA 94030
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Contaminated soil from site clean-up
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	23.6
Cat Decode:	Contaminated soil from site clean-up
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

G187 **BERENSTEIN ASSOC. PROPERTY** **LUST** **S106131260**
SSE **1319 HOWARD** **SLIC** **N/A**
1/8-1/4 **BURLINGAME, CA 94010** **HAZNET**
0.189 mi.
997 ft. **Site 32 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	669096
Facility Status:	5R- Remediation Plan
Global ID:	T0608186803
APN Number:	029222040
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	10/19/2005
Global Id:	T0608186803
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669096
Latitude:	37.5766905377104
Longitude:	-122.345870286226
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil

BERENSTEIN ASSOC. PROPERTY (Continued) **S106131260**

Potential Contaminants of Concern: Tetrachloroethylene (PCE)
Site History: Extracted from RRM's April 22, 2010 Additional Site Investigation Results, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is occupied by a two-story building located at 1319 Howard Avenue in Burlingame, California. The building is approximately 45 feet wide by 100 feet long and is constructed with reinforced concrete walls, concrete floors, and flat pitch-tar and gravel roofing. The first floor, a former dry cleaning facility (Caine Cleaners), is currently vacant. The second floor, built above the front half of the building only, is occupied by an architectural design firm. The facade of the building is mostly plate glass and opens up onto the sidewalk adjacent to Howard Avenue. The rear of the building abuts asphalt-paved parking areas owned by the City of Burlingame and Bank of the West. Soil and groundwater beneath the site is known to be impacted with PCE. Soil excavation activities were completed in 2007 to remove PCE impacted soils beneath the former cleaning machinery and floor drain area inside the building to a depth of approximately 25 feet below ground surface (bgs).

Click here to access the California GeoTracker records for this facility:

HAZNET:

envid:	S106131260
Year:	2013
GEPAID:	CAR000233643
Contact:	MATT KAEMPF
Telephone:	8314758141
Mailing Name:	Not reported
Mailing Address:	1319 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104212
Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.35
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

G188 **FORMER CAINE CLEANERS GREEN BANKER** **FINDS** **1015791185**
SSE **1319 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94030**
0.189 mi.
997 ft. **Site 33 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

FINDS:

Registry ID: 110055055318

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

FORMER CAINE CLEANERS GREEN BANKER (Continued) **1015791185**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

G189 **FORMER CAINE CLEANERS GREEN BANKER** **RCRA-SQG** **1015753033**
SSE **1319 HOWARD AVE** **ECHO** **CAR000233643**
1/8-1/4 **BURLINGAME, CA 94030**
0.189 mi.
997 ft. **Site 34 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

RCRA-SQG:

Date form received by agency:	04/07/2015
Facility name:	FORMER CAINE CLEANERS GREEN BANKER
Facility address:	1319 HOWARD AVE BURLINGAME, CA 94030
EPA ID:	CAR000233643
Mailing address:	398 PRIMROSE RD NO 1 BURLINGAME, CA 94010
Contact:	MATT KAEMPF
Contact address:	2560 SOQUEL AVE STE 202 SANTA CRUZ, CA 95062
Contact country:	US
Contact telephone:	831-475-8141
Contact email:	MATT@RRMSC.COM
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	RRM INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/2005
Owner/Op end date:	Not reported
Owner/operator name:	STANLEY LO
Owner/operator address:	398 PRIMROSE RD NO 1 BURLINGAME, CA 94010
Owner/operator country:	US
Owner/operator telephone:	650-692-4459
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/01/2002
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

FORMER CAINE CLEANERS GREEN BANKER (Continued) **1015753033**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: 611
. Waste name: 611

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 01/08/2013
Site name: FORMER CAINE CLEANERS
Classification: Small Quantity Generator

. Waste code: 611
. Waste name: 611

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

ECHO:
Envid: 1015753033
Registry ID: 110055055318
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110055055318

G190
SSE
1/8-1/4
0.189 mi.
997 ft.

FORMER CAINE CLEANERS
1319/1321 HOWARD AVENUE
BURLINGAME, CA 94010

Site 35 of 61 in cluster G

Database(s): FINDS, ECHO
EDR ID Number: 1012073964
EPA ID Number: N/A

Relative:
Higher

Actual:
38 ft.

FINDS:

Registry ID: 110038854790

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ECHO:

Envid:	1012073964
Registry ID:	110038854790
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110038854790

G191
SSE
1/8-1/4
0.189 mi.
997 ft.

FORMER CAINE CLEANERS
1319/1321 HOWARD AVENUE
BURLINGAME, CA 94030

Site 36 of 61 in cluster G

Database(s): RCRA-LQG
EDR ID Number: 1012175468
EPA ID Number: CAC002613377

Relative:
Higher

Actual:
38 ft.

RCRA-LQG:

Date form received by agency:	04/24/2008
Facility name:	FORMER CAINE CLEANERS
Facility address:	1319/1321 HOWARD AVENUE BURLINGAME, CA 94030
EPA ID:	CAC002613377
Mailing address:	199 CALIFORNIA ST. SU 168 MILLBRAE, CA 94030
Contact:	STANLEY LO
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	(650) 692-6777
Contact email:	Not reported
EPA Region:	09
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

FORMER CAINE CLEANERS (Continued) **1012175468**

100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: STANLEY LO
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/01/1900
Owner/Op end date: Not reported

Owner/operator name: GREENBANKER
Owner/operator address: 199 CALIFORNIA ST. SU 168
MILLBRAE, CA 94030
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/01/1900
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

G192 **CAINES CLEANERS** **RCRA-SQG** **1000313713**
SSE **1321 HOWARD AVENUE** **FINDS** **CAD981631831**
1/8-1/4 **BURLINGAME, CA 94010** **EMI**
0.189 mi. **HAZNET**
997 ft. **Site 37 of 61 in cluster G** **ECHO**

Relative:
Higher

Actual:
38 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	CAINES CLEANERS
Facility address:	1321 HOWARD AVE BURLINGAME, CA 94010
EPA ID:	CAD981631831
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WILLIAM BUCK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CAINES CLEANERS (Continued) **1000313713**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/09/1986
Site name: CAINES CLEANERS
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001181774

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS AIR POLLUTANT MAJOR

EMI:
Year: 1987
County Code: 41
Air Basin: SF
Facility ID: 1139
Air District Name: BA
SIC Code: 7216
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 1990
County Code: 41
Air Basin: SF
Facility ID: 1139
Air District Name: BA
SIC Code: 7216
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1
Reactive Organic Gases Tons/Yr: 0

CAINES CLEANERS (Continued) **1000313713**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1993
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CAINES CLEANERS (Continued) **1000313713**

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	1139
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HAZNET:

envid:	1000313713
Year:	2002
GEPAID:	CAD981631831
Contact:	KIL HYON CHUNG
Telephone:	6503446371

CAINES CLEANERS (Continued) **1000313713**

Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104212
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Liquids with pH <= 2
Disposal Method: Disposal, Other
Tons: 0
Cat Decode: Liquids with pH <= 2
Method Decode: Disposal, Other
Facility County: San Mateo

envid: 1000313713
Year: 2002
GEPAID: CAD981631831
Contact: KIL HYON CHUNG
Telephone: 6503446371
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104212
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Transfer Station
Tons: 2.29
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Transfer Station
Facility County: San Mateo

envid: 1000313713
Year: 2002
GEPAID: CAD981631831
Contact: KIL HYON CHUNG
Telephone: 6503446371
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104212
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: 0.13
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Transfer Station
Facility County: San Mateo

envid: 1000313713
Year: 2002
GEPAID: CAD981631831
Contact: KIL HYON CHUNG
Telephone: 6503446371
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104212

CAINES CLEANERS (Continued) **1000313713**

Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Disposal, Other
Tons:	0
Cat Decode:	Other inorganic solid waste
Method Decode:	Disposal, Other
Facility County:	San Mateo

envid:	1000313713
Year:	2002
GEPAID:	CAD981631831
Contact:	KIL HYON CHUNG
Telephone:	6503446371
Mailing Name:	Not reported
Mailing Address:	1321 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104212
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Disposal, Other
Tons:	0
Cat Decode:	Alkaline solution without metals pH >= 12.5
Method Decode:	Disposal, Other
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

ECHO:

Envid:	1000313713
Registry ID:	110001181774
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110001181774

G193 **CAINE CLEANERS** **San Mateo Co. BI** **S113755375**
SSE **1321 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 38 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0007336
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011889
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0007336
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004670
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

G194 **STANLEY LO/GREENBANKER** **HAZNET** **S112950786**
SSE **1321 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 39 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S112950786
Year:	2007
GEPAID:	CAC002599320
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	199 CALIFORNIA DR STE 168
Mailing City,St,Zip:	MILLBRAE, CA 94030
Gen County:	Not reported
TSD EPA ID:	ORD089452353
TSD County:	Not reported
Waste Category:	Not reported
Disposal Method:	Biological Treatment With Or Without Precitation
Tons:	40.92
Cat Decode:	Not reported
Method Decode:	Biological Treatment With Or Without Precitation
Facility County:	San Mateo

envid:	S112950786
Year:	2006
GEPAID:	CAC002599320
Contact:	STANLEY LO
Telephone:	6506924459
Mailing Name:	Not reported
Mailing Address:	199 CALIFORNIA DR STE 168
Mailing City,St,Zip:	MILLBRAE, CA 94030
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Contaminated soil from site clean-up
Disposal Method:	Disposal, Land Fill
Tons:	14.32
Cat Decode:	Contaminated soil from site clean-up
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

G195 **EDR Hist Cleaner** **1014988377**
SSE **1321 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 40 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

EDR Historical Cleaners:

Name:	CAINES CLEANERS
Year:	2001
Address:	1321 HOWARD AVE

Name:	CAINES CLEANERS
Year:	2002
Address:	1321 HOWARD AVE

G196 **CAINE CLEANERS** **DRYCLEANERS** **S102267661**
SSE **1321 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 41 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

DRYCLEANERS:

EPA Id:	CAL000017479
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	11/14/1989
Facility Active:	No
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	KIL HYON, CHUNG
Owner Address:	--
Owner Address 2:	Not reported
Owner Telephone:	0000000000
Contact Name:	KIL HYON, CHUNG
Contact Address:	1321 HOWARD AVE
Contact Address 2:	Not reported
Contact Telephone:	--
Mailing Name:	Not reported
Mailing Address 1:	1321 HOWARD AVE
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940100000
Owner Fax:	2
Region Code:	Not reported

G197 **CAINE CLEANERS** **HAZNET** **S113027789**
SSE **1321 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
997 ft. **Site 42 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S113027789
Year:	1999
GEPAID:	CAL000017479
Contact:	KIL HYON, CHUNG
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1321 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD981696420
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.2293
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113027789
Year:	1998

CAINE CLEANERS (Continued) **S113027789**

GEPAID: CAL000017479
Contact: KIL HYON, CHUNG
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 1.5220
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113027789
Year: 1997
GEPAID: CAL000017479
Contact: KIL HYON, CHUNG
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 2.1809
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113027789
Year: 1996
GEPAID: CAL000017479
Contact: KIL HYON, CHUNG
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 1321 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD981696420
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 1.5220
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113027789
Year: 1995
GEPAID: CAL000017479
Contact: KIL HYON, CHUNG
Telephone: 0000000000

CAINE CLEANERS (Continued) **S113027789**

Mailing Name:	Not reported
Mailing Address:	1321 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD981696420
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.9173
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
3 additional CA_HAZNET: record(s) in the EDR Site Report.

G198 **EDR Hist Auto** **1015208163**
SSE **1325 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
1000 ft. **Site 43 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:

Name:	WEST COAST AUTO CTR
Year:	2002
Address:	1325 HOWARD AVE
Name:	WEST COAST AUTO CTR
Year:	2003
Address:	1325 HOWARD AVE
Name:	AUTO TOWING
Year:	2011
Address:	1325 HOWARD AVE
Name:	AUTO TOWING
Year:	2012
Address:	1325 HOWARD AVE

G199 **EDR Hist Cleaner** **1014988586**
SSE **1325 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.189 mi.
1000 ft. **Site 44 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

EDR Historical Cleaners:

Name:	CENTURY CARPET CLEANERS
Year:	2003
Address:	1325 HOWARD AVE
Name:	CENTURY CARPET CLEANERS
Year:	2004
Address:	1325 HOWARD AVE
Name:	CENTURY CARPET CLEANERS
Year:	2005

(Continued) **1014988586**

Address: 1325 HOWARD AVE

Name: CENTURY CARPET CLEANERS
Year: 2006
Address: 1325 HOWARD AVE

Name: CENTURY CARPET CLEANERS
Year: 2007
Address: 1325 HOWARD AVE

Name: CENTURY CARPET CLEANERS
Year: 2008
Address: 1325 HOWARD AVE

Name: CENTURY CARPET CLEANERS
Year: 2009
Address: 1325 HOWARD AVE

Name: CENTURY CARPET CLEANERS
Year: 2010
Address: 1325 HOWARD AVE

G200 **HARRIS-CRISAFI CLEAN-UP TRUST** **EMI** **S108432062**
SE **1209 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.191 mi.
1007 ft. **Site 45 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EMI:

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	17224
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.003
Reactive Organic Gases Tons/Yr:	.0020958
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	17224
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

HARRIS-CRISAFI CLEAN-UP TRUST (Continued) **S108432062**

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2007
County Code: 41
Air Basin: SF
Facility ID: 17224
Air District Name: BA
SIC Code: 1799
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: .001
Reactive Organic Gases Tons/Yr: .0006986
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2008
County Code: 41
Air Basin: SF
Facility ID: 17224
Air District Name: BA
SIC Code: 1799
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: .001
Reactive Organic Gases Tons/Yr: .0006986
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2009
County Code: 41
Air Basin: SF
Facility ID: 17224
Air District Name: BA
SIC Code: 1799
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2010

HARRIS-CRISAFI CLEAN-UP TRUST (Continued) **S108432062**

County Code:	41
Air Basin:	SF
Facility ID:	17224
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	6.9859999999999996E-4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

G201 **HARRIS-CRISAFI CLEAN-UP TRUST** **FINDS** **1011977116**
SE **1209 HOWARD AVENUE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.191 mi.
1007 ft. **Site 46 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110038082204

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011977116
Registry ID:	110038082204
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110038082204

G202 **STERLING CLEANERS INC** **HAZNET** **S113109067**
ESE **1140 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.191 mi.
1010 ft. **Site 47 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S113109067
Year:	2003
GEPAID:	CAL000215134
Contact:	DAVID PLACK/PRESIDENT
Telephone:	6503430125
Mailing Name:	Not reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not reported
TSD EPA ID:	CAT080014079
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Not reported
Tons:	Not reported

STERLING CLEANERS INC (Continued) **S113109067**

Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Not reported
Facility County: San Mateo

envid: S113109067
Year: 2003
GEPAID: CAL000215134
Contact: DAVID PLACK/PRESIDENT
Telephone: 6503430125
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CAT080014079
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: 0.45
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113109067
Year: 2003
GEPAID: CAL000215134
Contact: DAVID PLACK/PRESIDENT
Telephone: 6503430125
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CAT080014079
TSD County: Not reported
Waste Category: Solids or sludges with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Not reported
Tons: Not reported
Cat Decode: Solids or sludges with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Not reported
Facility County: San Mateo

envid: S113109067
Year: 2002
GEPAID: CAL000215134
Contact: DAVID PLACK/PRESIDENT
Telephone: 6503430125
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CAT080014079
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Transfer Station
Tons: 1.37
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Transfer Station
Facility County: San Mateo

STERLING CLEANERS INC (Continued) **S113109067**

envid:	S113109067
Year:	2002
GEPAID:	CAL000215134
Contact:	DAVID PLACK/PRESIDENT
Telephone:	6503430125
Mailing Name:	Not reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not reported
TSD EPA ID:	CAT080014079
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Not reported
Tons:	Not reported
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Not reported
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
3 additional CA_HAZNET: record(s) in the EDR Site Report.

G203 **EDR Hist Cleaner** **1014977823**
ESE **1140 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.191 mi.
1010 ft. **Site 48 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EDR Historical Cleaners:

Name:	STERLING CLEANERS
Year:	2001
Address:	1140 HOWARD AVE
Name:	STERLIND CLEANERS INC
Year:	2004
Address:	1140 HOWARD AVE
Name:	STERLING CLEANERS
Year:	2010
Address:	1140 HOWARD AVE
Name:	STERLING CLEANERS
Year:	2011
Address:	1140 HOWARD AVE
Name:	STERLING CLEANERS
Year:	2012
Address:	1140 HOWARD AVE

G204 **STERLING CLEANERS** **LUST** **S113756634**
ESE **1140 HOWARD AVENUE** **SLIC** **N/A**
1/8-1/4 **BURLINGAME, CA 94010** **San Mateo Co. BI**
0.191 mi.
1010 ft. **Site 49 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	669111
Facility Status:	3B- Preliminary Assessment Underway
Global ID:	T10000006541
APN Number:	029211130
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	03/10/2015
Global Id:	T10000006541
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669116
Latitude:	37.578388
Longitude:	-122.3445489
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Case opened 2015, no signed RAA, out of compliance (6/18/2015)

Click here to access the California GeoTracker records for this facility:

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018042
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011857
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018042
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004614
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

G205 **STERLING CLEANERS** **RCRA-SQG** **1000364529**
ESE **1140 HOWARD AVE** **FINDS** **CAD981632094**
1/8-1/4 **BURLINGAME, CA 94010** **DRYCLEANERS**
0.191 mi. **HAZNET**
1010 ft. **Site 50 of 61 in cluster G** **ECHO**

Relative:
Higher

Actual:
36 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	STERLING CLEANERS
Facility address:	1140 HOWARD AVE BURLINGAME, CA 94010
EPA ID:	CAD981632094
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CHARLES KIM
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

STERLING CLEANERS (Continued) **1000364529**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/09/1986
Site name: STERLING CLEANERS
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110001153796

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

DRYCLEANERS:
EPA Id: CAL000215134
NAICS Code: 81232
NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)
SIC Code: 7211
SIC Description: Power Laundries, Family and Commercial
Create Date: 01/19/2000
Facility Active: No
Inactive Date: Not reported
Facility Addr2: Not reported
Owner Name: STERLING CLEANERS INC
Owner Address: 1140 HOWARD AVE
Owner Address 2: Not reported
Owner Telephone: 6503433605
Contact Name: DAVID PLACK/PRESIDENT
Contact Address: 1140 HOWARD AVE
Contact Address 2: Not reported
Contact Telephone: 6503430125
Mailing Name: Not reported
Mailing Address 1: 7076 FAIRWAY PL
Mailing Address 2: Not reported
Mailing City: CARMEL
Mailing State: CA
Mailing Zip: 93923
Owner Fax: 2
Region Code: 0000000000

HAZNET:
envid: 1000364529
Year: 1997

STERLING CLEANERS (Continued) **1000364529**

GEPAID: CAD981632094
Contact: STERLING CLEANERS
Telephone: 4153433605
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Transfer Station
Tons: .8775
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Transfer Station
Facility County: San Mateo

envid: 1000364529
Year: 1996
GEPAID: CAD981632094
Contact: STERLING CLEANERS
Telephone: 4153433605
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Transfer Station
Tons: 1.1700
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Transfer Station
Facility County: San Mateo

envid: 1000364529
Year: 1996
GEPAID: CAD981632094
Contact: STERLING CLEANERS
Telephone: 4153433605
Mailing Name: Not reported
Mailing Address: 1140 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940104226
Gen County: Not reported
TSD EPA ID: CAO000084517
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Transfer Station
Tons: .1950
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Transfer Station
Facility County: San Mateo

envid: 1000364529
Year: 1995
GEPAID: CAD981632094
Contact: STERLING CLEANERS
Telephone: 4153433605

STERLING CLEANERS (Continued) **1000364529**

Mailing Name:	Not reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not reported
TSD EPA ID:	CAT000613950
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	1.0725
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	1000364529
Year:	1994
GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605
Mailing Name:	Not reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not reported
TSD EPA ID:	CAT000613893
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	2.2050
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
3 additional CA_HAZNET: record(s) in the EDR Site Report.

ECHO:

Envid:	1000364529
Registry ID:	110001153796
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110001153796

G206 **STERLING CLEANERS, INC** **EMI** **S106840096**
ESE **1140 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.191 mi.
1010 ft. **Site 51 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EMI:

Year:	1987
County Code:	41
Air Basin:	SF
Facility ID:	419
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	0

STERLING CLEANERS, INC (Continued) **S106840096**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	419
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	419
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	419
Air District Name:	BA
SIC Code:	7216
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

G207 **SHAFER PROPERTY TRUST** **HAZNET** **S112924600**
SE **1201 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.192 mi.
1014 ft. **Site 52 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112924600
Year:	2003
GEPAID:	CAC002556158
Contact:	BRIAN KELLEHER
Telephone:	4082538365
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPRESSWAY PMB293
Mailing City,St,Zip:	SAN JOSE, CA 951210000
Gen County:	Not reported
TSD EPA ID:	CAL000161753
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.04
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

G208 **BRIAN KELLEHER** **HAZNET** **S112911229**
SE **1201 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.192 mi.
1014 ft. **Site 53 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

HAZNET:

envid:	S112911229
Year:	2002
GEPAID:	CAC002311569
Contact:	RYAN SPARROW- RRM
Telephone:	8314758141
Mailing Name:	Not reported
Mailing Address:	1658 E CAPITOL EXPRESSWAY # 293
Mailing City,St,Zip:	SAN JOSE, CA 951210000
Gen County:	Not reported
TSD EPA ID:	CAL000190816
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Not reported
Tons:	0.1
Cat Decode:	Waste oil and mixed oil
Method Decode:	Not reported
Facility County:	San Mateo

G209 **HARRIS-CRISAFI CLEAN-UP TRUST** **EMI** **S108432061**
SE **1201 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.192 mi.
1014 ft. **Site 54 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

EMI:

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.003
Reactive Organic Gases Tons/Yr:	.0020958
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0006986
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008

HARRIS-CRISAFI CLEAN-UP TRUST (Continued) **S108432061**

County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0006986
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	17223
Air District Name:	BA
SIC Code:	1799
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	6.9859999999999996E-4
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

G210 **HARRIS-CRISAFI CLEAN-UP TRUST** **FINDS** **1011977015**
SE **1201 HOWARD AVENUE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.192 mi.
1014 ft. **Site 55 of 61 in cluster G**

Relative:
Higher

Actual:
36 ft.

FINDS:

Registry ID: 110038082197

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011977015
Registry ID: 110038082197
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038082197

F211 **SHELL** **LUST** **S105194473**
NW **601 CALIFORNIA** **San Mateo Co. BI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 9 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660017
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0059026
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0081735
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0059026
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0081734
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0059026

SHELL (Continued) **S105194473**

Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0081737
Description: UNDERGROUND TANK - GENERAL
Facility Status: ACTIVE

F212 **SHELL** **RGA LUST** **S114690176**
NW **601 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.194 mi.
1023 ft. **Site 10 of 22 in cluster F**

Relative: RGA LUST:
Lower

	2002	SHELL	601 CALIFORNIA DR
	2001	SHELL	601 CALIFORNIA DR
Actual:	2000	SHELL	601 CALIFORNIA DR
24 ft.			

F213 **BURLINGAME VALERO** **San Mateo Co. BI** **S113756614**
NW **601 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 11 of 22 in cluster F**

Relative: San Mateo Co. BI:
Lower
Region: SAN MATEO
Facility ID: FA0018003
Actual: Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
24 ft. Record Id: PR0023920
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018003
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0004632
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018003
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022776
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

F214 **SHELL** **LUST** **S100931284**
NW **601 CALIFORNIA** **HIST CORTESE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 12 of 22 in cluster F**

Relative: LUST:
Lower
Region: STATE
Global Id: T0608100487
Actual: Latitude: 37.581697
24 ft. Longitude: -122.350487

SHELL (Continued) **S100931284**

Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/10/1991
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0511
LOC Case Number:	660017
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100487
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100487
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100487
Status:	Completed - Case Closed
Status Date:	10/10/1991

Global Id:	T0608100487
Status:	Open - Case Begin Date
Status Date:	10/21/1986

Regulatory Activities:

Global Id:	T0608100487
Action Type:	Other
Date:	10/21/1986
Action:	Leak Discovery

Global Id:	T0608100487
Action Type:	Other
Date:	10/21/1986
Action:	Leak Reported

Global Id:	T0608100487
Action Type:	ENFORCEMENT
Date:	10/10/1991

SHELL (Continued) **S100931284**

Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660017
Facility Status: 9- Case Closed
Global ID: T0608100487
APN Number: 029131380
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0511

F215 **SHELL** **RGA LUST** **S114690177**
NW **601 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.194 mi.
1023 ft. **Site 13 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

RGA LUST:

2012	SHELL	601 CALIFORNIA
2011	SHELL	601 CALIFORNIA
2010	SHELL	601 CALIFORNIA
2009	SHELL	601 CALIFORNIA
2008	SHELL	601 CALIFORNIA
2007	SHELL	601 CALIFORNIA
2006	SHELL	601 CALIFORNIA
2005	SHELL	601 CALIFORNIA
2003	SHELL	601 CALIFORNIA
1998	SHELL	601 CALIFORNIA
1997	SHELL	601 CALIFORNIA
1996	SHELL	601 CALIFORNIA
1995	SHELL	601 CALIFORNIA
1994	SHELL	601 CALIFORNIA
1993	SHELL	601 CALIFORNIA
1992	SHELL	601 CALIFORNIA

F216 **BURLINGAME TEXACO** **HAZNET** **S113035991**
NW **601 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 14 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

HAZNET:
envid: S113035991
Year: 2009
GEPAID: CAL000036395
Contact: BURLINGAME VALERO
Telephone: 6503470486
Mailing Name: Not reported

BURLINGAME TEXACO (Continued) **S113035991**

Mailing Address: 601 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103730
Gen County: Not reported
TSD EPA ID: CAD097030993
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.125
Cat Decode: Other organic solids
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113035991
Year: 2009
GEPAID: CAL000036395
Contact: BURLINGAME VALERO
Telephone: 6503470486
Mailing Name: Not reported
Mailing Address: 601 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103730
Gen County: Not reported
TSD EPA ID: CAD097030993
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.125
Cat Decode: Other organic solids
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113035991
Year: 2009
GEPAID: CAL000036395
Contact: BURLINGAME VALERO
Telephone: 6503470486
Mailing Name: Not reported
Mailing Address: 601 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103730
Gen County: Not reported
TSD EPA ID: CAD097030993
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.125
Cat Decode: Other organic solids
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113035991
Year: 2008
GEPAID: CAL000036395

BURLINGAME TEXACO (Continued) **S113035991**

Contact:	BURLINGAME VALERO
Telephone:	6503420760
Mailing Name:	Not reported
Mailing Address:	601 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103730
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.68805
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113035991
Year:	2008
GEPAID:	CAL000036395
Contact:	BURLINGAME VALERO
Telephone:	6503420760
Mailing Name:	Not reported
Mailing Address:	601 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103730
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.68805
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
31 additional CA_HAZNET: record(s) in the EDR Site Report.

F217 **EDR Hist Auto** **1015568623**
NW **601 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 15 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

EDR Historical Auto Stations:

Name:	BURLINGAME TEXACO
Year:	1999
Address:	601 CALIFORNIA DR

Name:	BURLINGAME TEXACO
Year:	2000
Address:	601 CALIFORNIA DR

Name:	BURLINGAME TEXACO
Year:	2005
Address:	601 CALIFORNIA DR

(Continued) **1015568623**

Name: BURLINGAME TEXACO
Year: 2006
Address: 601 CALIFORNIA DR

Name: BURLINGAME VALERO
Year: 2007
Address: 601 CALIFORNIA DR

Name: BURLINGAME TEXACO
Year: 2008
Address: 601 CALIFORNIA DR

Name: BURLINGAME TEXACO
Year: 2009
Address: 601 CALIFORNIA DR

Name: VALERO
Year: 2010
Address: 601 CALIFORNIA DR

Name: BURLINGAME VALERO
Year: 2011
Address: 601 CALIFORNIA DR

Name: BURLINGAME VALERO
Year: 2012
Address: 601 CALIFORNIA DR

F218 **BURLINGAME BEACON** **SWEEPS UST** **S101593890**
NW **601 CALIFORNIA DR** **CA FID UST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 16 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

SWEEPS UST:
Status: Active
Comp Number: 660053
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660053-000001
Tank Status: A
Capacity: 10000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Status: Active
Comp Number: 660053
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94

BURLINGAME BEACON (Continued) **S101593890**

Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660053-000002
Tank Status: A
Capacity: 10000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 660053
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660053-000003
Tank Status: A
Capacity: 10000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 660053
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660053-000004
Tank Status: A
Capacity: 550
Active Date: 03-24-94
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41002016
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 601 CALIFORNIA DR
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported

BURLINGAME BEACON (Continued) **S101593890**

Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

F219 **R SPERING** **HIST UST** **U001593943**
NW **601 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1023 ft. **Site 17 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

HIST UST:
File Number: 0002C2B1
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C2B1.pdf
Region: STATE
Facility ID: 00000010689
Facility Type: Gas Station
Other Type: Not reported
Contact Name: R. SPERRING
Telephone: 4153470486
Owner Name: SHELL OIL COMPANY
Owner Address: P.O. BOX 4848
Owner City,St,Zip: ANAHEIM, CA 92803
Total Tanks: 0004

Tank Num: 001
Container Num: 1
Year Installed: 69
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Tank Num: 002
Container Num: 2
Year Installed: 69
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Tank Num: 003
Container Num: 3
Year Installed: 69
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Tank Num: 004
Container Num: 4
Year Installed: 70
Tank Capacity: 00000000

R SPERING (Continued) **U001593943**

Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Click here for Geo Tracker PDF:

F220 **BURLINGAME TEXACO** **UST** **U003782694**
NW **601CALIFORNIA DR.** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.194 mi.
1026 ft. **Site 18 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

UST:
Facility ID: 41-000-018003
Permitting Agency: SAN MATEO COUNTY
Latitude: 37.57678
Longitude: -122.36886

H221 **PACIFIC BELL** **RCRA-SQG** **1000251378**
SSW **1480 BURLINGAME AVENUE** **LUST** **CAT080022270**
1/8-1/4 **BURLINGAME, CA 94010** **FINDS**
0.198 mi. **San Mateo Co. BI**
1047 ft. **Site 2 of 22 in cluster H** **HIST CORTESE**
ECHO

Relative:
Higher

Actual:
41 ft.

RCRA-SQG:
Date form received by agency: 09/01/1996
Facility name: PACIFIC BELL
Facility address: 1480 BURLINGAME AVENUE
BURLINGAME, CA 94010
EPA ID: CAT080022270
Mailing address: 2 NORTH SECOND ST ROOM 1125
SAN JOSE, CA 95113
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: THE PACIFIC TELEPHONE AND TELEGRAPH CO
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner

PACIFIC BELL (Continued) **1000251378**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/19/1981
Site name: PACIFIC BELL
Classification: Large Quantity Generator

Violation Status: No violations found

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660023
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

FINDS:

PACIFIC BELL (Continued) **1000251378**

Registry ID: 110055778724

Environmental Interest/Information System
STATE MASTER

Registry ID: 110002950487

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0017985
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0049364
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0017985
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004643
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0017985
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022765
Description: UNDERGROUND TANK - GENERAL
Facility Status: ACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0396

ECHO:
Envid: 1000251378
Registry ID: 110055778724
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110055778724

PACIFIC BELL (Continued) **1000251378**

Envid: 1000251378
Registry ID: 110002950487
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002950487

H222 **PACIFIC BELL** **EMI** **S107621645**
SSW **1480 BURLINGAME AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.198 mi.
1047 ft. **Site 3 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.058
Reactive Organic Gases Tons/Yr:	0.0485286
Carbon Monoxide Emissions Tons/Yr:	0.159
NOX - Oxides of Nitrogen Tons/Yr:	0.731
SOX - Oxides of Sulphur Tons/Yr:	0.011
Particulate Matter Tons/Yr:	0.052
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.050752

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.058
Reactive Organic Gases Tons/Yr:	.0485286
Carbon Monoxide Emissions Tons/Yr:	.159
NOX - Oxides of Nitrogen Tons/Yr:	.731
SOX - Oxides of Sulphur Tons/Yr:	.011
Particulate Matter Tons/Yr:	.052
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.050752

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.0041835
Carbon Monoxide Emissions Tons/Yr:	.013
NOX - Oxides of Nitrogen Tons/Yr:	.06

PACIFIC BELL (Continued) **S107621645**

SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.004
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.003904

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.0041835
Carbon Monoxide Emissions Tons/Yr:	.013
NOX - Oxides of Nitrogen Tons/Yr:	.06
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.004
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.003904

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.018
Reactive Organic Gases Tons/Yr:	.0150606
Carbon Monoxide Emissions Tons/Yr:	.049
NOX - Oxides of Nitrogen Tons/Yr:	.224
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.016
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.015616

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.7999999999999999E-2
Reactive Organic Gases Tons/Yr:	0.0150606
Carbon Monoxide Emissions Tons/Yr:	4.9000000000000002E-2
NOX - Oxides of Nitrogen Tons/Yr:	0.224
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0163934426229508
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.016

Year:	2010
County Code:	41

PACIFIC BELL (Continued) **S107621645**

Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.012
Reactive Organic Gases Tons/Yr:	0.0100404
Carbon Monoxide Emissions Tons/Yr:	3.5999999999999997E-2
NOX - Oxides of Nitrogen Tons/Yr:	0.16700000000000001
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1.2295081967213101E-2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.012

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.012
Reactive Organic Gases Tons/Yr:	0.0100404
Carbon Monoxide Emissions Tons/Yr:	0.036
NOX - Oxides of Nitrogen Tons/Yr:	0.167
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.007
Reactive Organic Gases Tons/Yr:	0.0058569
Carbon Monoxide Emissions Tons/Yr:	0.022
NOX - Oxides of Nitrogen Tons/Yr:	0.102
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0071721311475
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.007

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported

PACIFIC BELL (Continued) **S107621645**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.007
Reactive Organic Gases Tons/Yr:	0.0058569
Carbon Monoxide Emissions Tons/Yr:	0.022
NOX - Oxides of Nitrogen Tons/Yr:	0.102
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.008
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.007

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	13454
Air District Name:	BA
SIC Code:	4813
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.008731399
Reactive Organic Gases Tons/Yr:	0.008500799
Carbon Monoxide Emissions Tons/Yr:	0.026366997
NOX - Oxides of Nitrogen Tons/Yr:	0.121282617
SOX - Oxides of Sulphur Tons/Yr:	5.6224e-005
Particulate Matter Tons/Yr:	0.009028487
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.008667347

H223 **PACIFIC BELL** **RGA LUST** **S114665606**
SSW **1480 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.198 mi.
1047 ft. **Site 4 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

RGA LUST:

2002	PACIFIC BELL	1480 BURLINGAME AVE
2001	PACIFIC BELL	1480 BURLINGAME AVE
2000	PACIFIC BELL	1480 BURLINGAME AVE
1998	PACIFIC BELL	1480 BURLINGAME AVE
1997	PACIFIC BELL	1480 BURLINGAME AVE
1996	PACIFIC BELL	1480 BURLINGAME AVE
1995	PACIFIC BELL	1480 BURLINGAME AVE
1994	PACIFIC BELL	1480 BURLINGAME AVE
1993	PACIFIC BELL	1480 BURLINGAME AVE
1992	PACIFIC BELL	1480 BURLINGAME AVE

H224 **PACIFIC BELL TELEPHONE CO DBA AT&T CALIF** **HAZNET** **S113179894**
SSW **1480 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.198 mi.
1047 ft. **Site 5 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

HAZNET:

envid:	S113179894
Year:	2013
GEPAID:	CAT080022270
Contact:	Sean McFarlane
Telephone:	9258230280

PACIFIC BELL TELEPHONE CO DBA AT&T CALIF (Continued) **S113179894**

Mailing Name: Not reported
Mailing Address: 2525 WATNEY
Mailing City,St,Zip: FAIRFIELD, CA 945330000
Gen County: San Mateo
TSD EPA ID: UTD981552177
TSD County: 99
Waste Category: Not reported
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.7
Cat Decode: Not reported
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: Not reported

envid: S113179894
Year: 2009
GEPAID: CAT080022270
Contact: EH & S RECORDKEEPER-RRC
Telephone: 8005669347
Mailing Name: Not reported
Mailing Address: 1 AT&T WAY RM 2C140
Mailing City,St,Zip: BEDMINSTER, NJ 079210000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.033
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113179894
Year: 2009
GEPAID: CAT080022270
Contact: EH & S RECORDKEEPER-RRC
Telephone: 8005669347
Mailing Name: Not reported
Mailing Address: 1 AT&T WAY RM 2C140
Mailing City,St,Zip: BEDMINSTER, NJ 079210000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.122
Cat Decode: Unspecified organic liquid mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113179894
Year: 2009
GEPAID: CAT080022270
Contact: EH & S RECORDKEEPER-RRC

PACIFIC BELL TELEPHONE CO DBA AT&T CALIF (Continued) **S113179894**

Telephone: 8005669347
Mailing Name: Not reported
Mailing Address: 1 AT&T WAY RM 2C140
Mailing City,St,Zip: BEDMINSTER, NJ 079210000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.122
Cat Decode: Unspecified organic liquid mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113179894
Year: 2009
GEPAID: CAT080022270
Contact: EH & S RECORDKEEPER-RRC
Telephone: 8005669347
Mailing Name: Not reported
Mailing Address: 1 AT&T WAY RM 2C140
Mailing City,St,Zip: BEDMINSTER, NJ 079210000
Gen County: Not reported
TSD EPA ID: CAD044429835
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.033
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
54 additional CA_HAZNET: record(s) in the EDR Site Report.

H225 **PACIFIC BELL** **LUST U001595280**
SSW **1480 BURLINGAME AVE.** **UST N/A**
1/8-1/4 **BURLINGAME, CA 94010** **SWEEPS UST**
0.198 mi. **HIST UST**
1047 ft. **Site 6 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

LUST:
Region: STATE
Global Id: T0608100377
Latitude: 37.5767309
Longitude: -122.3497364
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/09/1992
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0396
LOC Case Number: 660023

PACIFIC BELL (Continued) **U001595280**

File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100377
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100377
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100377
Status: Completed - Case Closed
Status Date: 07/09/1992

Global Id: T0608100377
Status: Open - Case Begin Date
Status Date: 11/21/1985

Regulatory Activities:
Global Id: T0608100377
Action Type: ENFORCEMENT
Date: 06/08/1990
Action: Notice of Responsibility - #1

Global Id: T0608100377
Action Type: Other
Date: 01/31/1986
Action: Leak Discovery

Global Id: T0608100377
Action Type: Other
Date: 11/21/1985
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660023
Facility Status: 9- Case Closed

PACIFIC BELL (Continued) **U001595280**

Global ID: T0608100377
APN Number: 029122999
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

UST:
Facility ID: 41-000-022765
Permitting Agency: SAN MATEO COUNTY
Latitude: 37.5767
Longitude: -122.34977

SWEEPS UST:
Status: Active
Comp Number: 660034
Number: 9
Board Of Equalization: 44-001027
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: 92
SWRCB Tank Id: 41-000-660034-000001
Tank Status: A
Capacity: 4000
Active Date: 03-24-94
Tank Use: PETROLEUM
STG: P
Content: DIESEL
Number Of Tanks: 1

HIST UST:
File Number: 0002C129
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C129.pdf
Region: STATE
Facility ID: 00000036935
Facility Type: Other
Other Type: SIC 4800
Contact Name: E.J. KOEHLER
Telephone: 4155426758
Owner Name: PACIFIC BELL
Owner Address: 370 THIRD STREET
Owner City,St,Zip: SAN FRANCISCO, CA 94107
Total Tanks: 0002

Tank Num: 001
Container Num: D-XX-3K
Year Installed: Not reported
Tank Capacity: 00003000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: Not reported
Leak Detection: Pressure Test

Tank Num: 002
Container Num: D-67-3K
Year Installed: 1967
Tank Capacity: 00003000

PACIFIC BELL (Continued) **U001595280**

Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	D-67-3K
Year Installed:	1967
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

H226 **T MOBILE WEST CORP SITE ID SF03108A** **San Mateo Co. BI** **S113758727**
SSW **1480 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.198 mi.
1047 ft. **Site 7 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045341
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0058977
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

H227 **SBC** **San Mateo Co. BI** **S113755294**
SSW **1480 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.198 mi.
1047 ft. **Site 8 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0005133
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0064366
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

H228 **PACIFIC BELL** **RGA LUST** **S114665607**
SSW **1480 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.198 mi.
1047 ft. **Site 9 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

RGA LUST:

2012	PACIFIC BELL	1480 BURLINGAME
2011	PACIFIC BELL	1480 BURLINGAME
2010	PACIFIC BELL	1480 BURLINGAME
2009	PACIFIC BELL	1480 BURLINGAME

PACIFIC BELL (Continued) **S114665607**

2008	PACIFIC BELL	1480 BURLINGAME
2007	PACIFIC BELL	1480 BURLINGAME
2006	PACIFIC BELL	1480 BURLINGAME
2005	PACIFIC BELL	1480 BURLINGAME
2003	PACIFIC BELL	1480 BURLINGAME

H229 **AT & T MOBILITY - CENTRAL BG #13300** **San Mateo Co. BI** **S113758792**
SSW **1480 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.198 mi.
1047 ft. **Site 10 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045945
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0061209
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

G230 **BLUE BIRD CLEANERS** **RCRA-SQG** **1000195485**
SSE **190 PRIMROSE RD** **FINDS** **CAD981632433**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.202 mi.
1066 ft. **Site 56 of 61 in cluster G**

Relative:
Higher

Actual:
39 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	BLUE BIRD CLEANERS
Facility address:	190 PRIMROSE RD BURLINGAME, CA 94010
EPA ID:	CAD981632433
Mailing address:	PRIMROSE RD BURLINGAME, CA 94010
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	GEORGE RIZK
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner

BLUE BIRD CLEANERS (Continued) **1000195485**

Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002731198

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000195485
Registry ID: 110002731198
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002731198

I231 **JEWELL PARTNERS LP** **HAZNET** **S112983160**
ESE **217 HIGHLAND AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.203 mi.
1072 ft. **Site 1 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112983160
Year:	2011
GEPAID:	CAC002662352
Contact:	LINDA MARVER
Telephone:	9252081317
Mailing Name:	Not reported
Mailing Address:	PO BOX 2396
Mailing City,St,Zip:	DANVILLE, CA 945267396
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Other Treatment
Tons:	2.5
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Other Treatment
Facility County:	San Mateo

J232 **UST SITE** **San Mateo Co. BI** **S113758849**
ENE **1021 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.203 mi.
1072 ft. **Site 1 of 14 in cluster J**

Relative:
Lower

Actual:
28 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0046818
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0063724
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

G233 **WALGREENS #0086** **HAZNET** **S113174436**
South **1420 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.203 mi.
1073 ft. **Site 57 of 61 in cluster G**

Relative:
Higher

Actual:
40 ft.

HAZNET:

envid:	S113174436
Year:	2010
GEPAID:	CAR000049866
Contact:	ANDREW MARKS
Telephone:	8473152602
Mailing Name:	Not reported
Mailing Address:	104 WILMOT RD MS 1434
Mailing City,St,Zip:	DEERFIELD, IL 600150000
Gen County:	Not reported
TSD EPA ID:	CAD981402522
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste

WALGREENS #0086 (Continued) **S113174436**

Disposal Method: Not reported
Tons: 0.13761
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Not reported
Facility County: San Mateo

envid: S113174436
Year: 2010
GEPAID: CAR000049866
Contact: ANDREW MARKS
Telephone: 8473152602
Mailing Name: Not reported
Mailing Address: 104 WILMOT RD MS 1434
Mailing City,St,Zip: DEERFIELD, IL 600150000
Gen County: Not reported
TSD EPA ID: CAD981402522
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 1.73472
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

envid: S113174436
Year: 2010
GEPAID: CAR000049866
Contact: ANDREW MARKS
Telephone: 8473152602
Mailing Name: Not reported
Mailing Address: 104 WILMOT RD MS 1434
Mailing City,St,Zip: DEERFIELD, IL 600150000
Gen County: Not reported
TSD EPA ID: CAD981402522
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 1.73472
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Facility County: San Mateo

envid: S113174436
Year: 2010
GEPAID: CAR000049866
Contact: ANDREW MARKS
Telephone: 8473152602
Mailing Name: Not reported
Mailing Address: 104 WILMOT RD MS 1434
Mailing City,St,Zip: DEERFIELD, IL 600150000
Gen County: Not reported
TSD EPA ID: OHD083377010
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.018
Cat Decode: Unspecified solvent mixture

WALGREENS #0086 (Continued) **S113174436**

Method Decode: Fuel Blending Prior To Energy Recovery At Another Site
Facility County: San Mateo

envid: S113174436
Year: 2010
GEPAID: CAR000049866
Contact: ANDREW MARKS
Telephone: 8473152602
Mailing Name: Not reported
Mailing Address: 104 WILMOT RD MS 1434
Mailing City,St,Zip: DEERFIELD, IL 600150000
Gen County: Not reported
TSD EPA ID: OHD083377010
TSD County: Not reported
Waste Category: Pharmaceutical waste
Disposal Method: Not reported
Tons: 0.018
Cat Decode: Pharmaceutical waste
Method Decode: Not reported
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
127 additional CA_HAZNET: record(s) in the EDR Site Report.

G234 **WALGREENS #86** **San Mateo Co. BI** **S113758266**
South **1420 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.203 mi.
1073 ft. **Site 58 of 61 in cluster G**

Relative: Higher

Actual: 40 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0032087
Prog Element Code: BUSINESS PLAN - GENERAL
Record Id: PR0066931
Description: BUSINESS PLAN - GENERAL
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0032087
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0051849
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

G235 **WALGREENS NO 86** **RCRA-SQG** **1001481065**
South **1420 HOWARD AVE** **FINDS** **CAR000049866**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.203 mi.
1073 ft. **Site 59 of 61 in cluster G**

Relative: Higher

Actual: 40 ft.

RCRA-SQG:
Date form received by agency: 02/16/2004
Facility name: WALGREENS NO 86
Facility address: 1420 HOWARD AVE
BURLINGAME, CA 94010

WALGREENS NO 86 (Continued) **1001481065**

EPA ID: CAR000049866
Mailing address: 3404 N DUKE ST
C/O QUALEX INC
DURHAM, NC 27704
Contact: MICHAEL E RICHARDSON
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: (919) 484-3663
Contact email: RICHARMI@QUALEXPHOTO.COM
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: WALGREENS CO
Owner/operator address: 200 WILMOT RD
DEERFIELD, IL 60015
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/30/1999
Owner/Op end date: Not reported

Owner/operator name: WALGREENS NO 86
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/30/1999
Owner/Op end date: Not reported

Owner/operator name: QUALEX INC
Owner/operator address: 4020 STIRRUP CREEK DR NO 211
DURHAM, NC 27703
Owner/operator country: Not reported
Owner/operator telephone: (919) 484-3631
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No

WALGREENS NO 86 (Continued) **1001481065**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2004
Site name: WALGREENS NO 86
Classification: Large Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 02/07/2002
Site name: WALGREENS 0086
Classification: Large Quantity Generator

Date form received by agency: 03/08/1999
Site name: WALGREENS NO 0086
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110002926861

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ECHO:
Envid: 1001481065
Registry ID: 110002926861

WALGREENS NO 86 (Continued) **1001481065**

DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002926861

I236 **D & R AUTO BODY AND PAINT** **FINDS** **1005773694**
East **270 EAST LANE, #2** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 2 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

FINDS:

Registry ID: 110002412791

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

ECHO:

Envid: 1005773694
Registry ID: 110002412791
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002412791

I237 **BURLINGAME DIAGNOSTIC CTR** **San Mateo Co. BI** **S113756194**
East **270 EAST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 3 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:

Region: SAN MATEO
Facility ID: FA0016125
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0024505
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0016125
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0024506
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

I238 **EDR Hist Auto** **1015378378**
East **270 EAST LN** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 4 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

EDR Historical Auto Stations:

Name: D & R AUTO BODY & PAINT
Year: 1999
Address: 270 EAST LN

Name: D & R AUTO BODY & PAINT

(Continued) **1015378378**

Year: 2000
Address: 270 EAST LN

Name: D & R AUTO BODY & PAINT
Year: 2001
Address: 270 EAST LN

Name: SILVER AUTO SERVICE
Year: 2002
Address: 270 EAST LN

Name: SILVER AUTO SERVICE
Year: 2007
Address: 270 EAST LN

Name: SILVER AUTO SERVICE
Year: 2008
Address: 270 EAST LN

I239 **D&R AUTO BODY & PAINT** **HAZNET** **S113164585**
East **270 EAST LANE #2** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 5 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

HAZNET:
envid: S113164585
Year: 2000
GEPAID: CAL920275206
Contact: RICHARD BOLING
Telephone: 6505797617
Mailing Name: Not reported
Mailing Address: 6161 POWER INN ROAD #B
Mailing City,St,Zip: SACRAMENTO, CA 958242322
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Unspecified aqueous solution
Disposal Method: Recycler
Tons: 0.22
Cat Decode: Unspecified aqueous solution
Method Decode: Recycler
Facility County: San Mateo

envid: S113164585
Year: 1999
GEPAID: CAL920275206
Contact: RICHARD BOLING
Telephone: 6505797617
Mailing Name: Not reported
Mailing Address: 270 EAST LN STE 2
Mailing City,St,Zip: BURLINGAME, CA 940102802
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Recycler
Tons: 1.6053

D&R AUTO BODY & PAINT (Continued) **S113164585**

Cat Decode: Unspecified solvent mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113164585
Year: 1998
GEPAID: CAL920275206
Contact: RICHARD BOLING
Telephone: 6505797617
Mailing Name: Not reported
Mailing Address: 270 EAST LN STE 2
Mailing City,St,Zip: BURLINGAME, CA 940102802
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Recycler
Tons: .6880
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Recycler
Facility County: San Mateo

envid: S113164585
Year: 1997
GEPAID: CAL920275206
Contact: RICHARD BOLING
Telephone: 6505797617
Mailing Name: Not reported
Mailing Address: 270 EAST LN STE 2
Mailing City,St,Zip: BURLINGAME, CA 940102802
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Transfer Station
Tons: .1440
Cat Decode: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113164585
Year: 1997
GEPAID: CAL920275206
Contact: RICHARD BOLING
Telephone: 6505797617
Mailing Name: Not reported
Mailing Address: 270 EAST LN STE 2
Mailing City,St,Zip: BURLINGAME, CA 940102802
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Recycler
Tons: .6879
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Recycler
Facility County: San Mateo

D&R AUTO BODY & PAINT (Continued) **S113164585**

Click this hyperlink while viewing on your computer to access
10 additional CA_HAZNET: record(s) in the EDR Site Report.

I240 **D&R AUTO BODY & PAINT** **San Mateo Co. BI** **S113755775**
East **270 EAST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 6 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0012242
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024648
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012242
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0024647
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

I241 **SILVER AUTO SVC** **San Mateo Co. BI** **S113755774**
East **270 EAST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 7 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0012240
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024646
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012240
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0024645
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

I242 **D & R AUTO BODY AND PAINT** **EMI** **S105937420**
East **270 EAST LANE, #2** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 8 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

EMI:

Year:	1993
County Code:	41
Air Basin:	SF
Facility ID:	7071
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	7071
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	7071
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997

D & R AUTO BODY AND PAINT (Continued) **S105937420**

County Code:	41
Air Basin:	SF
Facility ID:	7071
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	7071
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

I243 **G & C AUTO BODY** **HAZNET** **S113040728**
East **270 EAST LANE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.211 mi.
1115 ft. **Site 9 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S113040728
Year:	1994
GEPAID:	CAL000046827
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	270 E LANE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Not reported
Tons:	.2085
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Not reported
Facility County:	San Mateo

G & C AUTO BODY (Continued) **S113040728**

envid: S113040728
Year: 1993
GEPAID: CAL000046827
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 270 E LANE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Disposal, Other
Tons: 0.2293
Cat Decode: Unspecified solvent mixture
Method Decode: Disposal, Other
Facility County: San Mateo

I244 **UST SITE** **San Mateo Co. BI** **S113758802**
ESE **1100 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.213 mi.
1127 ft. **Site 10 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0046061
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0061788
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

I245 **1X BURLINGAME BUS DEPOT** **HAZNET** **S112845597**
ESE **1080 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.215 mi.
1135 ft. **Site 11 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

HAZNET:
envid: S112845597
Year: 1993
GEPAID: CAC000796032
Contact: CITY OF BURLINGAME
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 501 PRIMROSE_RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 2.5284
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

H246 **SHELL SERVICE STATION** **San Mateo Co. BI** **S113756613**
SSW **1490 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.216 mi.
1140 ft. **Site 11 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018002
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022775
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

H247 **SHELL** **LUST** **S103892165**
SSW **1490 BURLINGAME** **HIST CORTESE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.216 mi.
1140 ft. **Site 12 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

LUST:

Region:	STATE
Global Id:	T0608100468
Latitude:	37.5765782
Longitude:	-122.3499433
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/21/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0492
LOC Case Number:	660001
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100468
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100468
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

SHELL (Continued) **S103892165**

Status History:
Global Id: T0608100468
Status: Completed - Case Closed
Status Date: 08/21/2001

Global Id: T0608100468
Status: Open - Case Begin Date
Status Date: 04/25/1988

Regulatory Activities:
Global Id: T0608100468
Action Type: Other
Date: 08/08/1988
Action: Leak Discovery

Global Id: T0608100468
Action Type: Other
Date: 04/25/1988
Action: Leak Reported

Global Id: T0608100468
Action Type: REMEDIATION
Date: 09/30/1993
Action: Not reported

Global Id: T0608100468
Action Type: ENFORCEMENT
Date: 01/31/1989
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660001
Facility Status: 9- Case Closed
Global ID: T0608100468
APN Number: 029122360
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0492

H248
SSW
1/8-1/4
0.216 mi.
1140 ft.

SHELL
1490 BURLINGAME
BURLINGAME, CA

Site 13 of 22 in cluster H

RGA LUST **S114689381**
N/A

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2012	SHELL	1490 BURLINGAME
2011	SHELL	1490 BURLINGAME
2010	SHELL	1490 BURLINGAME
2009	SHELL	1490 BURLINGAME
2008	SHELL	1490 BURLINGAME
2007	SHELL	1490 BURLINGAME
2006	SHELL	1490 BURLINGAME
2005	SHELL	1490 BURLINGAME
2003	SHELL	1490 BURLINGAME

H249
SSW
1/8-1/4
0.216 mi.
1140 ft.

HUGHES BURLINGAME SHELL
1490 BURLINGAME AVE
BURLINGAME, CA 94010

Site 14 of 22 in cluster H

SWEEPS UST **S101593759**
CA FID UST **N/A**

Relative:
Higher

Actual:
43 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660052
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660052-000001
Tank Status:	Not reported
Capacity:	8000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	5

Status:	Not reported
Comp Number:	660052
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660052-000002
Tank Status:	Not reported
Capacity:	8000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660052

HUGHES BURLINGAME SHELL (Continued) **S101593759**

Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660052-000003
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 660052
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660052-000004
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 660052
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660052-000005
Tank Status: Not reported
Capacity: 550
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41000464
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported

HUGHES BURLINGAME SHELL (Continued) **S101593759**

Mailing Address: P. O. BOX 5500
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

H250 **SHELL OIL COMPANY C/O WEIS ASS** **EMI** **S106839241**
SSW **1490 BURLINGAME AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.216 mi.
1140 ft. **Site 15 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

EMI:

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	8608
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

H251 **BURLINGAME/EL CAMINO** **HIST UST** **U001593906**
SSW **1490 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.216 mi.
1140 ft. **Site 16 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

HIST UST:

File Number:	0002C29F
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C29F.pdf
Region:	STATE
Facility ID:	00000004470
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	JOHN J HUGHES JR
Telephone:	4153441191
Owner Name:	SHELL OIL COMPANY
Owner Address:	P.O. BOX 4848
Owner City,St,Zip:	ANAHEIM, CA 92803
Total Tanks:	0004
Tank Num:	001

BURLINGAME/EL CAMINO (Continued) **U001593906**

Container Num:	1
Year Installed:	1968
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, 10

Tank Num:	002
Container Num:	2
Year Installed:	1968
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, 10

Tank Num:	003
Container Num:	3
Year Installed:	1968
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, 10

Tank Num:	004
Container Num:	4
Year Installed:	1968
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	12
Leak Detection:	Stock Inventor, 10

Click here for Geo Tracker PDF:

H252 **SHELL** **LUST** **S105194454**
SSW **1490 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.216 mi.
1140 ft. **Site 17 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660001
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported

SHELL (Continued) **S105194454**

Date Post Remedial Action Monitoring Began: Not reported

H253 **SHELL** **RGA LUST** **S114689380**
SSW **1490 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.216 mi.
1140 ft. **Site 18 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2002	SHELL	1490 BURLINGAME AVE
2001	SHELL	1490 BURLINGAME AVE
2000	SHELL	1490 BURLINGAME AVE
1998	SHELL	1490 BURLINGAME AVE
1997	SHELL	1490 BURLINGAME AVE
1996	SHELL	1490 BURLINGAME AVE
1995	SHELL	1490 BURLINGAME AVE
1994	SHELL	1490 BURLINGAME AVE
1993	SHELL	1490 BURLINGAME AVE
1992	SHELL	1490 BURLINGAME AVE

H254 **MOLLIE STONES MARKET** **HAZNET** **S112894959**
SW **1477 CHAPIN AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.217 mi.
1144 ft. **Site 19 of 22 in cluster H**

Relative:
Higher

Actual:
39 ft.

HAZNET:

envid:	S112894959
Year:	1998
GEPAID:	CAC001484952
Contact:	MIKE STONE & DAVE BENETTE
Telephone:	4152895720
Mailing Name:	Not reported
Mailing Address:	150 SHORELINE HWY., BLDG D, STE 5
Mailing City,St,Zip:	MILL VALLEY, CA 949410000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Polychlorinated biphenyls and material containing PCBs
Disposal Method:	Not reported
Tons:	.7600
Cat Decode:	Polychlorinated biphenyls and material containing PCBs
Method Decode:	Not reported
Facility County:	San Mateo

envid:	S112894959
Year:	1998
GEPAID:	CAC001484952
Contact:	MIKE STONE & DAVE BENETTE
Telephone:	4152895720
Mailing Name:	Not reported
Mailing Address:	150 SHORELINE HWY., BLDG D, STE 5
Mailing City,St,Zip:	MILL VALLEY, CA 949410000
Gen County:	Not reported
TSD EPA ID:	CAT080014079
TSD County:	Not reported

MOLLIE STONES MARKET (Continued) **S112894959**

Waste Category: Not reported
Disposal Method: Not reported
Tons: .2000
Cat Decode: Not reported
Method Decode: Not reported
Facility County: San Mateo

I255 **LINDA GRIMES** **HAZNET** **S113461148**
ESE **1101 HOWARD AVE # 1107** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.217 mi.
1148 ft. **Site 12 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

HAZNET:
envid: S113461148
Year: 2010
GEPAID: CAC002654964
Contact: MARIE LE
Telephone: 4156212700
Mailing Name: Not reported
Mailing Address: 2148A MARKET ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941141319
Gen County: Not reported
TSD EPA ID: NVD982358483
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 2.919
Cat Decode: Unspecified oil-containing waste
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

envid: S113461148
Year: 2010
GEPAID: CAC002654964
Contact: MARIE LE
Telephone: 4156212700
Mailing Name: Not reported
Mailing Address: 2148A MARKET ST
Mailing City,St,Zip: SAN FRANCISCO, CA 941141319
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Other Treatment
Tons: 1.25
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Other Treatment
Facility County: San Mateo

I256 **UST SITE** **San Mateo Co. BI** **S113758801**
ESE **1101-07 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.217 mi.
1148 ft. **Site 13 of 56 in cluster I**

Relative: **Higher**

Actual: **34 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0046060
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0061787
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

G257 **1X BANK OF THE WEST** **HAZNET** **S112845528**
SE **149 PARK RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.218 mi.
1150 ft. **Site 60 of 61 in cluster G**

Relative: **Higher**

Actual: **38 ft.**

HAZNET:

envid:	S112845528
Year:	1993
GEPAID:	CAC000790672
Contact:	BANK OF THE WEST
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1450 TREAT BLVD
Mailing City,St,Zip:	WALNUT CREEK, CA 945960000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.2107
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	Marin

F258 **FOUR CAR GARAGE INC** **HAZNET** **S113033945**
NW **609 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.218 mi.
1152 ft. **Site 19 of 22 in cluster F**

Relative: **Lower**

Actual: **24 ft.**

HAZNET:

envid:	S113033945
Year:	1995
GEPAID:	CAL000032270
Contact:	KALDOR GARY E
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	609 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103730
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent

FOUR CAR GARAGE INC (Continued) **S113033945**

Disposal Method:	Transfer Station
Tons:	1.1676
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	S113033945
Year:	1994
GEPAID:	CAL000032270
Contact:	KALDOR GARY E
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	609 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103730
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	1.2510
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

F259 **FOUR CAR GARAGE INC** **San Mateo Co. BI** **S113755394**
NW **609 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.218 mi.
1152 ft. **Site 20 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0007603
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011866
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0007603
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004666
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

F260 **FOUR CAR GARAGE THE** **RCRA-SQG** **1000350943**
NW **609 CALIFORNIA DR** **FINDS** **CAD020008231**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.218 mi.
1152 ft. **Site 21 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	FOUR CAR GARAGE THE
Facility address:	609 CALIFORNIA DR BURLINGAME, CA 94012

FOUR CAR GARAGE THE (Continued) **1000350943**

EPA ID: CAD020008231
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: GARY KALDOR
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/23/1985
Site name: FOUR CAR GARAGE THE

FOUR CAR GARAGE THE (Continued) **1000350943**

Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110006466822

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000350943
Registry ID: 110006466822
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110006466822

F261 **EDR Hist Auto** **1015573503**
NW **609 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.218 mi.
1152 ft. **Site 22 of 22 in cluster F**

Relative:
Lower

Actual:
24 ft.

EDR Historical Auto Stations:

Name: FOUR CAR GARAGE INC
Year: 2001
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC
Year: 2002
Address: 609 CALIFORNIA DR

Name: BURLINGAME MOTOR WORKS
Year: 2003
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC
Year: 2004
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC
Year: 2005
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC
Year: 2007
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC
Year: 2008
Address: 609 CALIFORNIA DR

Name: FOUR CAR GARAGE INC

(Continued) **1015573503**

Year:	2009
Address:	609 CALIFORNIA DR
Name:	FOUR CAR GARAGE INC
Year:	2010
Address:	609 CALIFORNIA DR
Name:	LAND ROVERFOUR CAR GARAGE
Year:	2011
Address:	609 CALIFORNIA DR
Name:	LAND ROVERFOUR CAR GARAGE
Year:	2012
Address:	609 CALIFORNIA DR

K262 **NEW SAFEWAY BURLINGAME** **NPDES** **S117706139**
South **1450 HOWARD AVENUE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1155 ft. **Site 1 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

NPDES:

Npdes Number:	Not reported
Facility Status:	Not reported
Agency Id:	Not reported
Region:	2
Regulatory Measure Id:	408928
Order No:	Not reported
Regulatory Measure Type:	Construction
Place Id:	Not reported
WDID:	2 41C359864
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	2/14/2012
Discharge Name:	Not reported
Discharge Address:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
RECEIVED DATE:	11/3/2010
PROCESSED DATE:	11/9/2010
STATUS CODE NAME:	Terminated
STATUS DATE:	2/23/2012
PLACE SIZE:	3.4
PLACE SIZE UNIT:	52
FACILITY CONTACT NAME:	Jason Gomes
FACILITY CONTACT TITLE:	Not reported
FACILITY CONTACT PHONE:	925-467-2628
FACILITY CONTACT PHONE EXT:	Not reported
FACILITY CONTACT EMAIL:	jason.gomes@safeway.com
OPERATOR NAME:	Safeway Incorporated
OPERATOR ADDRESS:	5918 Stoneridge Mall Road
OPERATOR CITY:	Pleasanton
OPERATOR STATE:	California
OPERATOR ZIP:	94588
OPERATOR CONTACT NAME:	Charlie Kelly

NEW SAFEWAY BURLINGAME (Continued) **S117706139**

OPERATOR CONTACT TITLE:	Not reported
OPERATOR CONTACT PHONE:	209-983-4893
OPERATOR CONTACT PHONE EXT:	Not reported
OPERATOR CONTACT EMAIL:	Charlie.kelly@wlbutler.com
OPERATOR TYPE:	Private Business
DEVELOPER NAME:	Safeway Incorporated
DEVELOPER ADDRESS:	5918 Stoneridge Mall Road
DEVELOPER CITY:	Pleasanton
DEVELOPER STATE:	California
DEVELOPER ZIP:	94588
DEVELOPER CONTACT NAME:	Jason Gomes
DEVELOPER CONTACT TITLE:	Not reported
CONSTYPE LINEAR UTILITY IND:	N
EMERGENCY PHONE NO:	Not reported
EMERGENCY PHONE EXT:	Not reported
CONSTYPE ABOVE GROUND IND:	Not reported
CONSTYPE BELOW GROUND IND:	Not reported
CONSTYPE CABLE LINE IND:	Not reported
CONSTYPE COMM LINE IND:	Not reported
CONSTYPE COMMERTIAL IND:	Y
CONSTYPE ELECTRICAL LINE IND:	Not reported
CONSTYPE GAS LINE IND:	Not reported
CONSTYPE INDUSTRIAL IND:	Not reported
CONSTYPE OTHER DESRIPTION:	Not reported
CONSTYPE OTHER IND:	Not reported
CONSTYPE RECONS IND:	Not reported
CONSTYPE RESIDENTIAL IND:	Not reported
CONSTYPE TRANSPORT IND:	Not reported
CONSTYPE UTILITY DESCRIPTION:	Not reported
CONSTYPE UTILITY IND:	Not reported
CONSTYPE WATER SEWER IND:	Not reported
DIR DISCHARGE USWATER IND:	Y
RECEIVING WATER NAME:	San Francisco Bay
CERTIFIER NAME:	Jason Gomes
CERTIFIER TITLE:	Not reported
CERTIFICATION DATE:	03-NOV-10
PRIMARY SIC:	Not reported
SECONDARY SIC:	Not reported
TERTIARY SIC:	Not reported

K263 **SAFEWAY STORE #948/1547** **HAZNET** **S112942603**
South **1450 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1155 ft. **Site 2 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

HAZNET:

envid:	S112942603
Year:	2014
GEPAID:	CAL000353509
Contact:	SHARON PLOUFFE
Telephone:	9252265097
Mailing Name:	Not reported
Mailing Address:	5918 STONERIDGE MALL RD
Mailing City,St,Zip:	PLEASANTON, CA 945883229
Gen County:	San Mateo
TSD EPA ID:	INR000110197
TSD County:	Not reported

SAFEWAY STORE #948/1547 (Continued) **S112942603**

Waste Category: Detergent waste chemicals
Disposal Method: Not reported
Tons: 0.01
Cat Decode: Detergent waste chemicals
Method Decode: Not reported
Facility County: San Mateo

envid: S112942603
Year: 2014
GEPAID: CAL000353509
Contact: SHARON PLOUFFE
Telephone: 9252265097
Mailing Name: Not reported
Mailing Address: 5918 STONERIDGE MALL RD
Mailing City,St,Zip: PLEASANTON, CA 945883229
Gen County: San Mateo
TSD EPA ID: INR000110197
TSD County: Not reported
Waste Category: Alkaline solution without metals pH >= 12.5
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.003
Cat Decode: Alkaline solution without metals pH >= 12.5
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S112942603
Year: 2014
GEPAID: CAL000353509
Contact: SHARON PLOUFFE
Telephone: 9252265097
Mailing Name: Not reported
Mailing Address: 5918 STONERIDGE MALL RD
Mailing City,St,Zip: PLEASANTON, CA 945883229
Gen County: San Mateo
TSD EPA ID: INR000110197
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0075
Cat Decode: Unspecified solvent mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S112942603
Year: 2014
GEPAID: CAL000353509
Contact: SHARON PLOUFFE
Telephone: 9252265097
Mailing Name: Not reported
Mailing Address: 5918 STONERIDGE MALL RD
Mailing City,St,Zip: PLEASANTON, CA 945883229
Gen County: San Mateo
TSD EPA ID: INR000110197

SAFEWAY STORE #948/1547 (Continued) **S112942603**

TSD County:	Not reported
Waste Category:	Pharmaceutical waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.002
Cat Decode:	Pharmaceutical waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S112942603
Year:	2014
GEPAID:	CAL000353509
Contact:	SHARON PLOUFFE
Telephone:	9252265097
Mailing Name:	Not reported
Mailing Address:	5918 STONERIDGE MALL RD
Mailing City,St,Zip:	PLEASANTON, CA 945883229
Gen County:	San Mateo
TSD EPA ID:	NVD980895338
TSD County:	99
Waste Category:	Off-specification, aged or surplus inorganics
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0375
Cat Decode:	Off-specification, aged or surplus inorganics
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
12 additional CA_HAZNET: record(s) in the EDR Site Report.

K264 **SAFEWAY 1547** **FINDS** **1016418909**
South **1450 HOWARD AVE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1155 ft. **Site 3 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

FINDS:

Registry ID: 110055654509

Environmental Interest/Information System
STATE MASTER

ECHO:

Envid:	1016418909
Registry ID:	110055654509
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110055654509

K265 **SAFEWAY 1547** **San Mateo Co. BI** **S113759038**
South **1450 HOWARD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1155 ft. **Site 4 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0051396
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0071242
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0051396
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076051
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

K266 **CHMIRS** **S105670990**
South **1450 HOWARD AVE.** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.219 mi.
1155 ft. **Site 5 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

CHMIRS:

OES Incident Number:	1-6240
OES notification:	10/30/2001
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	storm drain
Spill Site:	Not reported

(Continued) **S105670990**

Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2001
Agency:	Safeway
Incident Date:	10/30/200112:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	milk
Gallons:	20
Unknown:	0.000000
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Driver was off-loading milk and some released from a pallet. The milk went into the storm drain. Not reported

---

I267 **RUPPEL'S AUTO FIXATION INC** **HAZNET** **S113037704**
East **260 EAST LANE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1156 ft. **Site 14 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S113037704
Year:	1993
GEPAID:	CAL000040117
Contact:	KEN SCHRUM
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	260 EAST LN
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAT080031628
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	0.20849999999

RUPPEL'S AUTO FIXATION INC (Continued) **S113037704**

Cat Decode: Waste oil and mixed oil
Method Decode: Recycler
Facility County: San Mateo

envid: S113037704
Year: 1993
GEPAID: CAL000040117
Contact: KEN SCHRUM
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 260 EAST LN
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAT080031628
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Not reported
Tons: 0.1668
Cat Decode: Waste oil and mixed oil
Method Decode: Not reported
Facility County: San Mateo

I268 **EDR Hist Auto** **1015371079**
East **260 EAST LN** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1156 ft. **Site 15 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

EDR Historical Auto Stations:

Name: SMOG CHECK STATIONS BURLINGAME
Year: 1999
Address: 260 EAST LN

Name: SMOG CHECK STATIONS BURLINGAME
Year: 2000
Address: 260 EAST LN

Name: SMOG CHECK STATIONS BURLINGAME
Year: 2001
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION
Year: 2002
Address: 260 EAST LN

Name: SMOG CHECK STATIONS BURLINGAME
Year: 2003
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION
Year: 2004
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION
Year: 2006
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION

(Continued) **1015371079**

Year: 2007
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION
Year: 2008
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION INC
Year: 2009
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION INC
Year: 2010
Address: 260 EAST LN

Name: SMOG CHECK STATIONS
Year: 2011
Address: 260 EAST LN

Name: RUPPELS AUTO FIXATION INC
Year: 2012
Address: 260 EAST LN

I269 **RUPPELS AUTO FIXATION** **San Mateo Co. BI** **S113759009**
East **260 EAST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1156 ft. **Site 16 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0050716
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0070419
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0050716
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0070418
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

I270 **RUPPELS AUTO FIXATION** **San Mateo Co. BI** **S113756627**
East **260 EAST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.219 mi.
1156 ft. **Site 17 of 56 in cluster I**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0018024
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011842
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT

RUPPELS AUTO FIXATION (Continued) **S113756627**

Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018024
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004621
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018024
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0070141
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

K271 **CHEVRON 90571** **RCRA-SQG 1005441208**
SSW **260 EL CAMINO REAL** **FINDS CAR000116699**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.222 mi.
1170 ft. **Site 6 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

RCRA-SQG:
Date form received by agency: 02/16/2006
Facility name: CHEVRON 90571
Facility address: 260 EL CAMINO REAL
BURLINGAME, CA 94010
EPA ID: CAR000116699
Mailing address: PO BOX 6004
SAN RAMON, CA 94583
Contact: KATHY L NORRIS
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: (925) 842-5931
Contact email: KNORRIS@CHEVRON.COM
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: CHEVRON USA INC.
Owner/operator address: PO BOX 6004
SAN RAMON, 94583
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/26/1971
Owner/Op end date: Not reported

Owner/operator name: CHEVRON USA INC.
Owner/operator address: Not reported

CHEVRON 90571 (Continued) **1005441208**

Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/26/1971
Owner/Op end date: Not reported

Owner/operator name: CHEVRON PRODUCTS COMPANY
Owner/operator address: P O BOX 6004
SAN RAMON, CA 94583
Owner/operator country: Not reported
Owner/operator telephone: (925) 842-5931
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/16/2006
Site name: CHEVRON 90571
Classification: Large Quantity Generator

. Waste code: 134
. Waste name: 134

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 05/16/2002
Site name: CHEVRON STATION 90571
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

CHEVRON 90571 (Continued) **1005441208**

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110055806999

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

STATE MASTER

Registry ID: 110012545772

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

ECHO:

Envid: 1005441208
Registry ID: 110055806999
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110055806999

Envid: 1005441208
Registry ID: 110012545772
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110012545772

K272 **CHEVRON 9-0571** **LUST** **S105030425**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 7 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Pollution Characterization
Case Number:	660046
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	1/1/1965
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

K273 **WALGREENS #12257** **San Mateo Co. BI** **S113758890**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 8 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0047974
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0065591
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0047974
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076050
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

K274 **WALGREENS #12257** **RCRA-CESQG** **1016954604**
SSW **260 EL CAMINO REAL** **CAL000352316**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 9 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

RCRA-CESQG:

Date form received by agency:	06/09/2014
Facility name:	WALGREENS #12257
Facility address:	260 EL CAMINO REAL BURLINGAME, CA 94010
EPA ID:	CAL000352316
Mailing address:	GREY HAWK CT, STE 200 CARLSBAD, CA 92010

WALGREENS #12257 (Continued) **1016954604**

Contact:	KARINA E ROMERO
Contact address:	N LAKE AVE PASADENA, CA 91101
Contact country:	Not reported
Contact telephone:	(760) 602-8887
Contact email:	KROMERO@3ECOMPANY.COM
EPA Region:	09
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	WALGREEN CO
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/27/2010
Owner/Op end date:	Not reported

Owner/operator name:	BRAD & GINA SOMBERG
Owner/operator address:	S ELLSWORTH SAN MATEO, CA 94401
Owner/operator country:	Not reported
Owner/operator telephone:	(650) 342-3030
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	05/27/2010
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

WALGREENS #12257 (Continued) **1016954604**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U165
. Waste name: NAPHTHALENE

Violation Status: No violations found

K275 **CHEVRON 9-0571** **RGA LUST** **S114597981**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.222 mi.
1170 ft. **Site 10 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2012	CHEVRON 9-0571	260 EL CAMINO REAL
2011	CHEVRON 9-0571	260 EL CAMINO REAL

K276
SSW
1/8-1/4
0.222 mi.
1170 ft.

BOBS CHEVRON
260 EL CAMINO REAL
BURLINGAME, CA 94010

Site 11 of 29 in cluster K

SWEEPS UST
CA FID UST

S101593684
N/A

Relative:
Higher

Actual:
43 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660025
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660025-000005
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	4

Status:	Not reported
Comp Number:	660025
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660025-000006
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660025
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660025-000007
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

Status:	Not reported

BOBS CHEVRON (Continued) **S101593684**

Comp Number:	660025
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660025-000008
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

CA FID UST:

Facility ID:	41000155
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4153446120
Mail To:	Not reported
Mailing Address:	P.O. BOX
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

K277 **CHEVRON** **HIST CORTESE** **S110060516**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.222 mi.
1170 ft. **Site 12 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0135

K278
SSW
1/8-1/4
0.222 mi.
1170 ft.

CHEVRON 9-0571 — **RGA LUST** — **S114595185** / **N/A**
260 EL CAMINO REAL
BURLINGAME, CA

Site 13 of 29 in cluster K

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2010	CHEVRON 9-0571	260 EL CAMINO REAL
2009	CHEVRON 9-0571	260 EL CAMINO REAL
2008	CHEVRON 9-0571	260 EL CAMINO REAL
2007	CHEVRON 9-0571	260 EL CAMINO REAL
2006	CHEVRON 9-0571	260 EL CAMINO REAL
2005	CHEVRON 9-0571	260 EL CAMINO REAL
2003	CHEVRON 9-0571	260 EL CAMINO REAL

K279
SSW
1/8-1/4
0.222 mi.
1170 ft.

CHEVRON — **RGA LUST** — **S114600471** / **N/A**
260 EL CAMINO REAL
BURLINGAME, CA

Site 14 of 29 in cluster K

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2002	CHEVRON	260 EL CAMINO REAL
2001	CHEVRON	260 EL CAMINO REAL
2000	CHEVRON	260 EL CAMINO REAL
1998	CHEVRON	260 EL CAMINO REAL
1997	CHEVRON	260 EL CAMINO REAL
1996	CHEVRON	260 EL CAMINO REAL
1995	CHEVRON	260 EL CAMINO REAL
1994	CHEVRON	260 EL CAMINO REAL
1993	CHEVRON	260 EL CAMINO REAL
1992	CHEVRON	260 EL CAMINO REAL

K280
SSW
1/8-1/4
0.222 mi.
1170 ft.

5793 SAN MATEO COUNTY ENVIRONMENTAL HEALTH — **FINDS** / **ECHO** — **1014869104** / **N/A**
260 EL CAMINO REAL
BURLINGAME, CA 94010

Site 15 of 29 in cluster K

Relative:
Higher

Actual:
43 ft.

FINDS:

Registry ID: 110043844551

Environmental Interest/Information System
LEAKING UNDERGROUND STORAGE TANK - ARRA

ECHO:

Envid:	1014869104
Registry ID:	110043844551
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110043844551

K281
SSW
1/8-1/4
0.222 mi.
1170 ft.

Relative:
Higher

Actual:
43 ft.

260 EL CAMINO REAL
BURLINGAME, CA 94010

Site 16 of 29 in cluster K

EDR Hist Auto **1015371082**
N/A

EDR Historical Auto Stations:

Name:	CHEVRON STATIONS BURLINGAME
Year:	1999
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON STATIONS
Year:	2000
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON STATIONS
Year:	2001
Address:	260 EL CAMINO REAL
Name:	BOBS CHEVRON
Year:	2002
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON STATIONS
Year:	2003
Address:	260 EL CAMINO REAL
Name:	CURRIES AUTOMOTIVE
Year:	2004
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON INC
Year:	2006
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON INC
Year:	2007
Address:	260 EL CAMINO REAL
Name:	CURRIES AUTOMOTIVE INC
Year:	2008
Address:	260 EL CAMINO REAL
Name:	CHEVRON
Year:	2010
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON STATIONS
Year:	2011
Address:	260 EL CAMINO REAL
Name:	CURRIES CHEVRON STATIONS
Year:	2012
Address:	260 EL CAMINO REAL

K282 **CHEVRON 9-0571** **UST** **U003782648**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 17 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

UST:

Facility ID:	41--017976
Permitting Agency:	SAN MATEO COUNTY
Latitude:	37.5779175
Longitude:	-122.3481818

K283 **260 EL CAMINO REAL** **NPDES** **S118586085**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 24010**
0.222 mi.
1170 ft. **Site 18 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

NPDES:

Npdes Number:	Not reported
Facility Status:	Not reported
Agency Id:	Not reported
Region:	2
Regulatory Measure Id:	347882
Order No:	Not reported
Regulatory Measure Type:	Construction
Place Id:	Not reported
WDID:	2 41C352441
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	9/2/2010
Discharge Name:	Not reported
Discharge Address:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
RECEIVED DATE:	6/25/2008
PROCESSED DATE:	7/7/2008
STATUS CODE NAME:	Terminated
STATUS DATE:	9/2/2010
PLACE SIZE:	0.49
PLACE SIZE UNIT:	52
FACILITY CONTACT NAME:	Bill Plant
FACILITY CONTACT TITLE:	Not reported
FACILITY CONTACT PHONE:	999-999-9999
FACILITY CONTACT PHONE EXT:	Not reported
FACILITY CONTACT EMAIL:	Not reported
OPERATOR NAME:	Kevin & Lisa Cullinane et Al
OPERATOR ADDRESS:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR CONTACT NAME:	Not reported
OPERATOR CONTACT TITLE:	Not reported
OPERATOR CONTACT PHONE:	Not reported
OPERATOR CONTACT PHONE EXT:	Not reported
OPERATOR CONTACT EMAIL:	Not reported
OPERATOR TYPE:	Private Individual

260 EL CAMINO REAL (Continued) **S118586085**

DEVELOPER NAME:	WL Butler Construction
DEVELOPER ADDRESS:	204 Franklin
DEVELOPER CITY:	Redwood City
DEVELOPER STATE:	California
DEVELOPER ZIP:	94063
DEVELOPER CONTACT NAME:	Bill Plant
DEVELOPER CONTACT TITLE:	Not reported
CONSTYPE LINEAR UTILITY IND:	Not reported
EMERGENCY PHONE NO:	650-342-3030
EMERGENCY PHONE EXT:	Not reported
CONSTYPE ABOVE GROUND IND:	Not reported
CONSTYPE BELOW GROUND IND:	Not reported
CONSTYPE CABLE LINE IND:	Not reported
CONSTYPE COMM LINE IND:	Not reported
CONSTYPE COMMERTIAL IND:	Y
CONSTYPE ELECTRICAL LINE IND:	Not reported
CONSTYPE GAS LINE IND:	Not reported
CONSTYPE INDUSTRIAL IND:	Not reported
CONSTYPE OTHER DESRIPTION:	Not reported
CONSTYPE OTHER IND:	Not reported
CONSTYPE RECONS IND:	Not reported
CONSTYPE RESIDENTIAL IND:	Not reported
CONSTYPE TRANSPORT IND:	Not reported
CONSTYPE UTILITY DESCRIPTION:	Not reported
CONSTYPE UTILITY IND:	Not reported
CONSTYPE WATER SEWER IND:	Not reported
DIR DISCHARGE USWATER IND:	Not reported
RECEIVING WATER NAME:	Not reported
CERTIFIER NAME:	Not reported
CERTIFIER TITLE:	Not reported
CERTIFICATION DATE:	Not reported
PRIMARY SIC:	Not reported
SECONDARY SIC:	Not reported
TERTIARY SIC:	Not reported

K284 **CHEVRON STATION 90571** **HAZNET** **S113176546**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 19 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S113176546
Year:	2013
GEPAID:	CAR000116699
Contact:	KATHY NORRIS-SLUSHER
Telephone:	8773866044
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 945830000
Gen County:	San Mateo
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.1125
Cat Decode:	Not reported

CHEVRON STATION 90571 (Continued) **S113176546**

Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported
envid:	S113176546
Year:	2007
GEPAID:	CAR000116699
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	5.21
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113176546
Year:	2007
GEPAID:	CAR000116699
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Not reported
Tons:	3
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Not reported
Facility County:	San Mateo
envid:	S113176546
Year:	2007
GEPAID:	CAR000116699
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Tons:	0.03

CHEVRON STATION 90571 (Continued) **S113176546**

Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Facility County:	San Mateo
envid:	S113176546
Year:	2007
GEPAID:	CAR000116699
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	8
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
9 additional CA_HAZNET: record(s) in the EDR Site Report.

K285 **90571** **LUST** **U001593888**
SSW **260 EL CAMINO REAL** **HIST UST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 20 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

LUST:

Region:	STATE
Global Id:	T0608100128
Latitude:	37.5764790250825
Longitude:	-122.3495221138
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/10/2013
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0135
LOC Case Number:	660046
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from CRA's April 27, 2009 WELL INSTALLATION AND DESTUCTION REPORT, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is an inactive Chevron retail gasoline service station. The subject property was first developed in the late 1910s or early 1920s as a service station. Details of the station facilities are not available; however, historical Sanborn maps and aerial photos indicate two structures occupying the site.

90571 (Continued) **U001593888**

The property remained unchanged until approximately 1965 when the dispenser island configuration changed from a rectangular to a square structure. In June 1990, the configuration of the site went through a third change when the adjacent office/store building on the northern property was demolished and the property was merged with the subject property. At the same time, two steel 10,000-gallon gasoline, one steel 5,000-gallon gasoline and one 1,000-gallon used-oil underground storage tanks (USTs) and associated product line piping were removed from beneath the site. A new station building containing an automotive service shop equipped with three hydraulic lifts was constructed in the northeast corner of the site. Two 10,000-gallon and one 5,000-gallon gasoline USTs and two fuel dispenser islands were installed in the central portion of the site, and one 1,000-gallon used-oil UST was installed next to the service bays in the eastern portion of the site. In 1998, the second generation USTs were removed and replaced with a third generation of USTs comprised of three fiberglass and steel 10,000-gallon gasoline USTs in the same location. One 1,000-gallon used-oil UST replaced the previous tank in the same location. In May 2007, as part of the debranding of the Chevron station, all USTs, dispenser islands, associated product piping, and three hydraulic lifts were removed from the site. The station building, canopy and concrete apron still occupy the site. 1990 Soil Vapor Contaminant Assessment: On June 5, 1990, EA Engineering, Science, and Technology (EA) collected soil gas samples from 15 locations. The volatile hydrocarbon distribution pattern indicated two distinct sources of petroleum hydrocarbons. EA stated that a former Shell Service Station site with a known history of UST leaks, located directly across Burlingame Avenue, may have contributed to the presence of petroleum hydrocarbons beneath the northwestern portion of the Chevron site. Furthermore, EA found that a second source of subsurface petroleum hydrocarbons originated beneath the northern portion of the Chevron tank field. 1990 UST and Product Line Removal: In June 1990, two 10,000-gallon and one 5,000-gallon gasoline, and one 1,000-gallon used-oil USTs and associated product line piping were removed. Total petroleum hydrocarbons as gasoline (TPHg) were detected as high as 4,100 milligrams per kilogram (mg/kg) in a soil sample collected from the southwest corner of the former tank pit. A September 20, 1990 Unauthorized Release Report states that an unknown volume of gasoline and used-oil was released from the site and discovered on June 13, 1990 during tank removal. To remediate impacted soil in the vicinity of the tank field, EA installed four vapor extraction pipes on the floor of the excavation and covered them with pea gravel and a heavy gauge Hypalon vapor barrier before additional gravel and replacement double-walled fiberglass tanks were placed in the pit. 1990 Well Installation: Between August 20 and September 4, 1990, EA installed groundwater monitoring wells MW-1 through MW-6. Petroleum hydrocarbon concentrations in soil were generally higher in the northern and southern edges of the site. The highest detected hydrocarbon concentrations in soil were 1,100 mg/kg total petroleum hydrocarbons as diesel (TPHd), 4,100 mg/kg TPHg, and 13 mg/kg benzene from boring MW-5, located on the southeast corner of the site. Soil samples were not analyzed for methyl tertiary butyl ether (MTBE). Light non-aqueous phase liquids (LNAPL) were detected in well MW-5 upon installation. 1991 Soil Vapor Extraction Pilot Test: On February 15 and August 15, 1991, EA conducted a soil vapor extraction pilot test to evaluate soil vapor extraction feasibility for remediation of

90571 (Continued) **U001593888**

subsurface petroleum hydrocarbons at the site. EA concluded that despite relatively low soil permeability, the site could be remediated by a vapor extraction system equipped with a high vacuum pump. 1995 Well Installation: On March 13 and 14, 1995, Groundwater Technology, Inc. (GTI) installed groundwater monitoring wells MW-7 through MW-9. No benzene, toluene, ethylbenzene, or xylenes (BTEX), or TPHg were detected in soil. Soil samples were not analyzed for TPHd or MTBE. 1995 Hydrocarbon Removal from Tank Backfill: According to a December 5, 1995 unauthorized release report, approximately 2,200 gallons of gasoline were released from the northernmost UST into the tank backfill after both of the tanks fiberglass walls were ruptured during station remodeling. Vacuum trucks pumped NAPL and groundwater from the tank backfill area on December 5 and 29, 1995, recovering an estimated 2,000 gallons of NAPL. Cambria Environmental Technology, Inc. (Cambria) extracted soil vapor from two tank backfill wells between December 20, 1995 and January 17, 1996, removing an estimated 253 gallons of petroleum hydrocarbons. Therefore, remedial actions after the release appear to have recovered the released hydrocarbon mass. 1996 Area Well Survey: On October 24, 1996, Cambria performed a door-to-door area well survey of properties in an arc extending approximately 400 feet downgradient (north to northeast) from the site. No active or abandoned wells were identified. 1998 Soil Vapor Investigation: On March 11, 1998, Cambria advanced soil vapor borings SB-1 through SB-4. Soil vapor samples were collected from 2 and 5 feet below grade (fbg) in each boring. The only benzene concentration detected was 0.0028 parts per million by volume in sample SB-4 collected from 2 fbg near the southeast corner of the station building. 2002-2003 Well Survey: Cambria contacted SMCHD and the City of Burlingame Water Division to obtain records of any wells within a 2000-foot radius of the site. Cambria also distributed a questionnaire to owners of all properties within 800 feet downgradient and 400 feet upgradient and crossgradient of the site to identify any wells or sumps present on their properties. Ten irrigation wells were identified over 1,500 feet upgradient and crossgradient of the site. The only wells identified downgradient of the site were groundwater monitoring wells. Cambrias February 12, 2003 Well Survey Report concluded that based on the topography, drainage patterns and groundwater gradient, it was unlikely that any wells would be impacted by petroleum hydrocarbons originating from the site. 2005 Baseline Investigation: On November 11 through 15, 2005, SECOR International, Inc. (SECOR) conducted a baseline investigation, advancing soil borings BA-1 through BA-4. Soil collected from borings BA-1 and BA-2 were analyzed for TPHg, BTEX, and oxygenates including MTBE. TPHg was only detected at 130 mg/kg in the 15 fbg sample from boring BA-2, advanced near the dispenser islands. No BTEX or oxygenates were detected in soil. Soil samples from BA-3 and BA-4 were only analyzed for TPHd. Soil samples from BA-3 contained 53 mg/kg at 15 fbg and BA-4 contained 13 mg/kg at 15 fbg. Groundwater was encountered in boring BA-1 and a grab-groundwater sample was collected. The grab-groundwater sample contained 4,400 micrograms per liter (μg/L) TPHg and 19 μg/L benzene. No fuel oxygenates, including MTBE, were detected in the grab-groundwater sample from boring BA-1. 2006 Well Installation: On November 8, 2006, Cambria installed monitoring well MW-10 to further define the downgradient extent of petroleum hydrocarbons in groundwater northeast of the site. TPHg was detected in soil from 10.5 fbg at 770 mg/kg and from 15.5 fbg at 1,100 mg/kg.

90571 (Continued) **U001593888**

No benzene or MTBE was detected in soil. 2007 Well Destruction: On May 18, 2007, Conestoga-Rovers & Associates (CRA) destroyed onsite wells MW-3 and MW-4 by pressure grouting in anticipation of station demolition activities that would have compromised well integrity. The well destruction is detailed in CRAs June 1, 2007 Well Destruction Report. 2007 Station Demolition: The station was de-branded on April 2, 2007. In May 2007, CRA observed Gettler-Ryan, Inc. (G-R) of Dublin, California remove the hydraulic lifts, fuel dispensers, product lines and USTs and collected compliance soil samples. Only TPHg and ethylbenzene were detected in the three gasoline UST soil samples. TPHg concentrations ranged from 820 to 2,100 mg/kg, and ethylbenzene concentrations ranged from 5.2 to 12 mg/kg. No hydrocarbons were detected in the six soil samples collected beneath the dispenser islands. Only 1.1 mg/kg TPHd was detected in the soil sample collected from the used-oil tank pit. No total petroleum hydrocarbons as hydraulic oil (TPHho) was detected in the soil samples collected beneath the hydraulic lifts. The grab-groundwater sample collected from the gasoline UST pit contained 3,000 g/L TPHg, 23 g/L benzene, and 15 g/L MTBE. No hydrocarbons were detected in the grab-groundwater sample collected from the used-oil tank pit. The tank cavities and hydraulic lift cavity were backfilled to the surface with gravel. As a condition of the City of Burlingame permit approval, G-R was required to leave the station building and canopy intact. 2007 Soil Boring and Soil Vapor Investigation: In October and November 2007, CRA advanced soil borings B4 through B12 and installed soil vapor probes VP-1, VP-2, and VP-3 to define the extent and distribution of petroleum hydrocarbons in soil and groundwater beneath the site and to evaluate soil vapor exposure pathways in anticipation of property redevelopment. TPHg was detected in seven of the nine soil borings at concentrations ranging from 11 mg/kg in sample B7 at 20 fbg to 2,600 mg/kg in sample B5 at 15 fbg. Benzene was detected in five of the soil borings at concentrations ranging from 0.001 mg/kg in sample B12 at 20 fbg to 4.7 mg/kg in sample B5 at 15 fbg. MTBE was detected in six soil borings at concentrations ranging from 0.0008 mg/kg in sample B4 at 15 fbg to 0.088 mg/kg in sample B5 at 15 fbg. No TPHd was detected in any of the soil borings. The grab-groundwater sample collected from boring B9 contained 1,000 g/L TPHg, 1 g/L benzene, and 38 g/L MTBE. Soil vapor samples were collected in November and December 2007. No benzene was detected in any of the vapor wells. Vapor probe VP-1 contained 1,000,000 micrograms per cubic meter (μg/m%) TPHg during the November sampling event and 1,100,000 g/m% during the December sampling event. Due to the lack of carcinogenic constituents detected in any of the vapor samples, it was determined remediation based solely on the soil vapor results is not necessary. On July 21, 2008, CRA destroyed onsite monitoring wells MW-1, MW-2 and MW-6 to facilitate construction of a Walgreens retail store at the site, as requested by the property owner. On February 26, 2009, CRA installed groundwater monitoring well MW-11 to define the extent of the dissolved hydrocarbon plume northeast (downgradient) of well MW-10, and destroyed vapor wells VP-1 through VP-3 to facilitate site construction.

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100128

90571 (Continued) **U001593888**

Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100128
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100128
Status: Completed - Case Closed
Status Date: 05/10/2013

Global Id: T0608100128
Status: Open - Case Begin Date
Status Date: 07/17/1990

Global Id: T0608100128
Status: Open - Eligible for Closure
Status Date: 04/11/2012

Global Id: T0608100128
Status: Open - Site Assessment
Status Date: 08/16/1990

Global Id: T0608100128
Status: Open - Verification Monitoring
Status Date: 04/27/2009

Regulatory Activities:
Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 10/29/2009
Action: Staff Letter - #20091029

Global Id: T0608100128
Action Type: RESPONSE
Date: 08/16/2006
Action: Other Report / Document

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 04/11/2012
Action: Notification - Public Notice of Case Closure - #20120411

Global Id: T0608100128
Action Type: ENFORCEMENT

90571 (Continued) **U001593888**

Date: 01/20/2010
Action: Staff Letter - #20100120

Global Id: T0608100128
Action Type: RESPONSE
Date: 07/20/2010
Action: Well Installation Report

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/03/2009
Action: Soil and Water Investigation Report

Global Id: T0608100128
Action Type: RESPONSE
Date: 08/16/2006
Action: Soil and Water Investigation Workplan

Global Id: T0608100128
Action Type: RESPONSE
Date: 01/04/2007
Action: Well Installation Report

Global Id: T0608100128
Action Type: RESPONSE
Date: 06/07/2007
Action: Electronic Reporting Submittal Due

Global Id: T0608100128
Action Type: RESPONSE
Date: 10/31/2007
Action: Soil and Water Investigation Report

Global Id: T0608100128
Action Type: RESPONSE
Date: 04/07/2007
Action: Other Workplan

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/05/2005
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2004
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 03/20/2006
Action: Other Report / Document

90571 (Continued) **U001593888**

Global Id: T0608100128
Action Type: RESPONSE
Date: 02/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: Other
Date: 08/16/1990
Action: Leak Discovery

Global Id: T0608100128
Action Type: Other
Date: 07/17/1990
Action: Leak Reported

Global Id: T0608100128
Action Type: RESPONSE
Date: 06/21/2009
Action: Electronic Reporting Submittal Due

Global Id: T0608100128
Action Type: REMEDIATION
Date: 10/03/1990
Action: Excavation

Global Id: T0608100128
Action Type: REMEDIATION
Date: 10/03/1990
Action: Other (Use Description Field)

Global Id: T0608100128
Action Type: RESPONSE
Date: 08/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 02/07/2007
Action: * Verbal Communication - #20070207

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 10/15/2008
Action: Staff Letter - #20081015

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 03/25/2011
Action: Staff Letter - #20110325

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 05/10/2013
Action: Closure/No Further Action Letter - #20130510

Global Id: T0608100128
Action Type: RESPONSE

90571 (Continued) **U001593888**

Date: 02/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: Staff Letter - #20110510

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 05/18/2012
Action: Staff Letter - #20120518

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2005
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 07/18/1991
Action: Notice of Responsibility - #1

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 09/07/2006
Action: Staff Letter - #20060907

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 05/07/2007
Action: Staff Letter - #20070507

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 01/11/2006
Action: Staff Letter - #20060111

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 06/13/2006
Action: Staff Letter - #20060613

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 07/18/2007
Action: Staff Letter - #20070718

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Semi-Annually

90571 (Continued) **U001593888**

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 05/21/2009
Action: Staff Letter - #20090521

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 07/02/2009
Action: Staff Letter - #20090702

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2002
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2003
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2003
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2004
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2007
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 08/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE

90571 (Continued) **U001593888**

Date: 05/06/2011
Action: Other Report / Document - Regulator Responded

Global Id: T0608100128
Action Type: RESPONSE
Date: 08/10/2011
Action: Site Assessment Report - Regulator Responded

Global Id: T0608100128
Action Type: RESPONSE
Date: 01/27/2011
Action: Clean Up Fund - 5-Year Review Summary - Regulator Responded

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/03/2009
Action: Well Installation Report

Global Id: T0608100128
Action Type: RESPONSE
Date: 05/18/2013
Action: Well Destruction Report - Regulator Responded

Global Id: T0608100128
Action Type: RESPONSE
Date: 11/15/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0608100128
Action Type: ENFORCEMENT
Date: 08/09/2000
Action: Staff Letter - #20000809

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660046
Facility Status: 9- Case Closed
Global ID: T0608100128
APN Number: 029201320
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST UST:
File Number: 0002BCB5
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BCB5.pdf
Region: STATE
Facility ID: 00000061848
Facility Type: Gas Station
Other Type: Not reported
Contact Name: SEDLEMYER, ROBERT V

90571 (Continued) **U001593888**

Telephone:	4153446120
Owner Name:	CHEVRON U.S.A. INC.
Owner Address:	575 MARKET
Owner City,St,Zip:	SAN FRANCISCO, CA 94105
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	1971
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0000250
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	1971
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0000250
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3
Year Installed:	1979
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0000250
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

K286 **WALGREENS #12257** **HAZNET** **S113158535**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 21 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S113158535
Year:	2014
GEPAID:	CAL000352316
Contact:	KARINA ROMERO
Telephone:	7606028700
Mailing Name:	Not reported
Mailing Address:	3207 GREY HAWK CT., SUITE 200
Mailing City,St,Zip:	CARLSBAD, CA 920100000
Gen County:	San Mateo
TSD EPA ID:	INR000110197
TSD County:	Not reported
Waste Category:	Not reported
Disposal Method:	Not reported
Tons:	0.001
Cat Decode:	Not reported
Method Decode:	Not reported

WALGREENS #12257 (Continued) **S113158535**

Facility County:	San Mateo
envid:	S113158535
Year:	2014
GEPAID:	CAL000352316
Contact:	KARINA ROMERO
Telephone:	7606028700
Mailing Name:	Not reported
Mailing Address:	3207 GREY HAWK CT., SUITE 200
Mailing City,St,Zip:	CARLSBAD, CA 920100000
Gen County:	San Mateo
TSD EPA ID:	INR000110197
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.003
Cat Decode:	Alkaline solution without metals pH >= 12.5
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113158535
Year:	2014
GEPAID:	CAL000352316
Contact:	KARINA ROMERO
Telephone:	7606028700
Mailing Name:	Not reported
Mailing Address:	3207 GREY HAWK CT., SUITE 200
Mailing City,St,Zip:	CARLSBAD, CA 920100000
Gen County:	San Mateo
TSD EPA ID:	INR000110197
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0125
Cat Decode:	Unspecified solvent mixture
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113158535
Year:	2014
GEPAID:	CAL000352316
Contact:	KARINA ROMERO
Telephone:	7606028700
Mailing Name:	Not reported
Mailing Address:	3207 GREY HAWK CT., SUITE 200
Mailing City,St,Zip:	CARLSBAD, CA 920100000
Gen County:	San Mateo
TSD EPA ID:	INR000110197
TSD County:	Not reported
Waste Category:	Pharmaceutical waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.003

WALGREENS #12257 (Continued) **S113158535**

Cat Decode: Pharmaceutical waste
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113158535
Year: 2014
GEPAID: CAL000352316
Contact: KARINA ROMERO
Telephone: 7606028700
Mailing Name: Not reported
Mailing Address: 3207 GREY HAWK CT., SUITE 200
Mailing City,St,Zip: CARLSBAD, CA 920100000
Gen County: San Mateo
TSD EPA ID: INR000110197
TSD County: Not reported
Waste Category: Pharmaceutical waste
Disposal Method: Not reported
Tons: 0.0005
Cat Decode: Pharmaceutical waste
Method Decode: Not reported
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
38 additional CA_HAZNET: record(s) in the EDR Site Report.

K287 **CHEVRON 90571** **HAZNET** **S113032765**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 22 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

HAZNET:
envid: S113032765
Year: 2002
GEPAID: CAL000029692
Contact: KATHY NORRIS
Telephone: 9258425931
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Recycler
Tons: 0.2
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Recycler
Facility County: San Mateo

envid: S113032765
Year: 2001
GEPAID: CAL000029692
Contact: KATHY NORRIS
Telephone: 9258425931
Mailing Name: Not reported
Mailing Address: PO BOX 6004

CHEVRON 90571 (Continued) **S113032765**

Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Recycler
Tons: 0.06
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Recycler
Facility County: San Mateo

envid: S113032765
Year: 2000
GEPAID: CAL000029692
Contact: KATHY NORRIS
Telephone: 9258425931
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Recycler
Tons: 0.16
Cat Decode: Aqueous solution with total organic residues 10 percent or more
Method Decode: Recycler
Facility County: San Mateo

envid: S113032765
Year: 1996
GEPAID: CAL000029692
Contact: CHERVON PRODUCTS CO
Telephone: 9258425931
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: Recycler
Tons: 5.6295
Cat Decode: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode: Recycler
Facility County: San Mateo

envid: S113032765
Year: 1995
GEPAID: CAL000029692
Contact: CHERVON PRODUCTS CO
Telephone: 9258425931
Mailing Name: Not reported
Mailing Address: PO BOX 6004
Mailing City,St,Zip: SAN RAMON, CA 945830000
Gen County: Not reported
TSD EPA ID: CAD009452657

CHEVRON 90571 (Continued) **S113032765**

TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Recycler
Tons:	6.6720
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
3 additional CA_HAZNET: record(s) in the EDR Site Report.

K288 **CURRIES CHEVRON SERVICE** **HAZNET** **S113068947**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 23 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S113068947
Year:	2004
GEPAID:	CAL000122545
Contact:	LINDA J BEALS CONTROLLER
Telephone:	6509526661
Mailing Name:	Not reported
Mailing Address:	434 N CANAL UNIT 7
Mailing City,St,Zip:	SOUTH SAN FRANCISCO, CA 940800000
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Not reported
Disposal Method:	Transfer Station
Tons:	Not reported
Cat Decode:	Not reported
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113068947
Year:	2004
GEPAID:	CAL000122545
Contact:	LINDA J BEALS CONTROLLER
Telephone:	6509526661
Mailing Name:	Not reported
Mailing Address:	434 N CANAL UNIT 7
Mailing City,St,Zip:	SOUTH SAN FRANCISCO, CA 940800000
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.44
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113068947
Year:	2003
GEPAID:	CAL000122545
Contact:	LINDA J BEALS CONTROLLER

CURRIES CHEVRON SERVICE (Continued) **S113068947**

Telephone:	6509526661
Mailing Name:	Not reported
Mailing Address:	434 N CANAL UNIT 7
Mailing City,St,Zip:	SOUTH SAN FRANCISCO, CA 940800000
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.35
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113068947
Year:	2002
GEPAID:	CAL000122545
Contact:	LINDA J BEALS CONTROLLER
Telephone:	6509526661
Mailing Name:	Not reported
Mailing Address:	434 N CANAL UNIT 7
Mailing City,St,Zip:	SOUTH SAN FRANCISCO, CA 940800000
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.04
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113068947
Year:	2000
GEPAID:	CAL000122545
Contact:	LINDA J BEALS CONTROLLER
Telephone:	6509526661
Mailing Name:	Not reported
Mailing Address:	434 N CANAL UNIT 7
Mailing City,St,Zip:	SOUTH SAN FRANCISCO, CA 940800000
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.33
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
7 additional CA_HAZNET: record(s) in the EDR Site Report.

K289 **CURRIES CHEVRON STATION** **San Mateo Co. BI** **S113756597**
SSW **260 EL CAMINO REAL** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.222 mi.
1170 ft. **Site 24 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023079
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004694
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022757
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

K290 **SZTO & ASSOCIATES** **HAZNET** **S112937648**
South **1443 HOWARD AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.223 mi.
1175 ft. **Site 25 of 29 in cluster K**

Relative:
Higher

Actual:
42 ft.

HAZNET:

envid:	S112937648
Year:	2004
GEPAID:	CAC002577719
Contact:	LARRY AZTO
Telephone:	4153990859
Mailing Name:	Not reported
Mailing Address:	133 KEARNY ST STE 202
Mailing City,St,Zip:	SAN FRANCISCO, CA 94108
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	16.01
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

I291 **MIKE HARVEY HONDA** **San Mateo Co. BI** **S113755548**
East **200 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.227 mi.
1200 ft. **Site 18 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0010382
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011929
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010382
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004700
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

I292 **MWE HARVEY CHRYSLER PLYMOUTH** **HIST UST** **S113041816**
East **200 CALIFORNIA DRIVE** **HAZNET** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.227 mi.
1200 ft. **Site 19 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

HIST UST:

File Number:	0002C0AA
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C0AA.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported

Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

HAZNET:

envid:	S113041816
Year:	2009
GEPAID:	CAL000049077
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796800
Mailing Name:	Not reported

MWE HARVEY CHRYSLER PLYMOUTH (Continued) **S113041816**

Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110943
Gen County:	Not reported
TSD EPA ID:	NVD982358483
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.22935
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo
envid:	S113041816
Year:	2008
GEPAID:	CAL000049077
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796800
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110943
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.076
Cat Decode:	Waste oil and mixed oil
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113041816
Year:	2008
GEPAID:	CAL000049077
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796800
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110943
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.2085
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113041816
Year:	2007
GEPAID:	CAL000049077

MWE HARVEY CHRYSLER PLYMOUTH (Continued) **S113041816**

Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796800
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110943
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.12
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113041816
Year:	2006
GEPAID:	CAL000049077
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796800
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110943
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.14
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
17 additional CA_HAZNET: record(s) in the EDR Site Report.

I293 **MIKE HARVEY HONDA** **San Mateo Co. BI** **S113758114**
East **200 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.227 mi.
1200 ft. **Site 20 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0029336
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0049815
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0029336
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0049814

MIKE HARVEY HONDA (Continued) **S113758114**

Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: ACTIVE

K294 **MAURICE APTS** **HAZNET** **S112919415**
SSW **255 EL CAMINO REAL 200-300** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.228 mi.
1205 ft. **Site 26 of 29 in cluster K**

Relative:
Higher

Actual:
44 ft.

HAZNET:
envid: S112919415
Year: 2003
GEPAID: CAC002456159
Contact: JOHN CLIFFORD/PROPERTY MGR
Telephone: 6505481567
Mailing Name: Not reported
Mailing Address: 255 EL CAMINO REAL STE 309
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: Not reported
TSD EPA ID: CAL000153023
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Not reported
Tons: 19.3
Cat Decode: Asbestos containing waste
Method Decode: Not reported
Facility County: San Mateo

L295 **WINDY HILL PV SEVEN, LP** **HAZNET** **S118229809**
West **1415 FLORIBUNDA AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.229 mi.
1207 ft. **Site 1 of 9 in cluster L**

Relative:
Lower

Actual:
27 ft.

HAZNET:
envid: S118229809
Year: 2014
GEPAID: CAC002798077
Contact: DAVID MCMILLAN
Telephone: 6504779474
Mailing Name: Not reported
Mailing Address: 1050 RALSTON AVE
Mailing City,St,Zip: BELMONT, CA 94002
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Asbestos containing waste
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.69
Cat Decode: Asbestos containing waste
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

I296 **CHMIRS** **S107449053**
East **198 CALIFORNIA DR AND BAYS WATER /// THIS IS THE BACK REPAIR** **N/A**
1/8-1/4 **BURLINGAME, CA 94011**
0.230 mi.
1216 ft. **Site 21 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

CHMIRS:

OES Incident Number:	4-4165
OES notification:	08/11/2004
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2004
Agency:	Citizen
Incident Date:	8/11/200412:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	No
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	Unknown Oils
Gallons:	0.000000
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S107449053**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Caller is stating that a business is dumping Oils, Grease and anti freeze into a grease trap over the last 6 years and it's soaking into the soil.

I297 **PUTNAM CHEVROLET CADILLAC** **San Mateo Co. BI** **S113757757**
East **198 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 22 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0027495
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0043745
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0027495
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0043746
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

I298 **PUTNAM AUTOMOTIVE** **FINDS** **1011987256**
East **198 CALIFORNIA DRIVE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 23 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

FINDS:

Registry ID: 110037963852

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011987256
Registry ID:	110037963852

PUTNAM AUTOMOTIVE (Continued) **1011987256**

DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110037963852

I299 **SATURN OF BURLINGAME** **HAZNET** **S113017965**
East **198 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 24 of 56 in cluster I**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113017965
Year:	2013
GEPAID:	CAD983606716
Contact:	MARK CORSO - SERV. MGR.
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	5.7
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

envid:	S113017965
Year:	2012
GEPAID:	CAD983606716
Contact:	MARK CORSO - SERV. MGR.
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	2
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S113017965
Year:	2012
GEPAID:	CAD983606716
Contact:	MARK CORSO - SERV. MGR.
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	San Mateo

SATURN OF BURLINGAME (Continued) **S113017965**

TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	2
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S113017965
Year:	2006
GEPAID:	CAD983606716
Contact:	JOHNNY DUMAS
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.22
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113017965
Year:	2006
GEPAID:	CAD983606716
Contact:	JOHNNY DUMAS
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.22
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
42 additional CA_HAZNET: record(s) in the EDR Site Report.

I300 **ARATA PROPERTY** **RGA LUST** **S114572611**
East **198 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.230 mi.
1216 ft. **Site 25 of 56 in cluster I**

Relative: RGA LUST:
Higher

2002	ARATA PROPERTY	198 CALIFORNIA DR
2001	ARATA PROPERTY	198 CALIFORNIA DR
2000	ARATA PROPERTY	198 CALIFORNIA DR

Actual:
33 ft.

I301 **ARATA PROPERTY** **RGA LUST** **S114572613**
East **198 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.230 mi.
1216 ft. **Site 26 of 56 in cluster I**

Relative: RGA LUST:
Higher

2008	ARATA PROPERTY	198 CALIFORNIA
2007	ARATA PROPERTY	198 CALIFORNIA
2006	ARATA PROPERTY	198 CALIFORNIA
2005	ARATA PROPERTY	198 CALIFORNIA
2003	ARATA PROPERTY	198 CALIFORNIA

Actual:
33 ft.

I302 **ARATA PROPERTY** **LUST** **S104493499**
East **198 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 27 of 56 in cluster I**

Relative: LUST REG 2:
Higher

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660060
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

Actual:
33 ft.

I303 **SATURN DEVELOPMENT NORTH, LLC** **San Mateo Co. BI** **S113755547**
East **198 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 28 of 56 in cluster I**

Relative: **Higher**

Actual: **33 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0010375
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011928
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010375
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004699
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

I304 **ARATA PROPERTY** **RGA LUST** **S114572612**
East **198 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.230 mi.
1216 ft. **Site 29 of 56 in cluster I**

Relative: **Higher**

Actual: **33 ft.**

RGA LUST:

2012	ARATA PROPERTY	198 CALIFORNIA DRIVE
2011	ARATA PROPERTY	198 CALIFORNIA DRIVE
2010	ARATA PROPERTY	198 CALIFORNIA DRIVE
2009	ARATA PROPERTY	198 CALIFORNIA DRIVE

I305 **PUTNAM AUTOMOTIVE** **EMI** **S106921348**
East **198 CALIFORNIA DRIVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.230 mi.
1216 ft. **Site 30 of 56 in cluster I**

Relative: **Higher**

Actual: **33 ft.**

EMI:

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004

PUTNAM AUTOMOTIVE (Continued) **S106921348**

County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.019
Reactive Organic Gases Tons/Yr:	0.0158973
Carbon Monoxide Emissions Tons/Yr:	0.051
NOX - Oxides of Nitrogen Tons/Yr:	0.234
SOX - Oxides of Sulphur Tons/Yr:	0.004
Particulate Matter Tons/Yr:	0.017
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.016592

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.0041835
Carbon Monoxide Emissions Tons/Yr:	.013
NOX - Oxides of Nitrogen Tons/Yr:	.059
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.004
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.003904

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.4000000000000002E-2
Reactive Organic Gases Tons/Yr:	2.8447799999999999E-2
Carbon Monoxide Emissions Tons/Yr:	0.10100000000000001
NOX - Oxides of Nitrogen Tons/Yr:	0.46600000000000003
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	3.3000000000000002E-2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.2208000000000001E-2

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD

PUTNAM AUTOMOTIVE (Continued) **S106921348**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.0000000000000001E-3
Reactive Organic Gases Tons/Yr:	2.5100999999999999E-3
Carbon Monoxide Emissions Tons/Yr:	8.9999999999999993E-3
NOX - Oxides of Nitrogen Tons/Yr:	4.2000000000000003E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00307377049180327
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.0000000000000001E-3

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.009
NOX - Oxides of Nitrogen Tons/Yr:	0.042
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14911
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.009
NOX - Oxides of Nitrogen Tons/Yr:	0.042
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0030737704918
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.003

I306 **PUTNAM CHEVROLET CADILLAC** **RCRA-SQG** **1000596695**
East **198 CALIFORNIA DR** **LUST** **CAD983606716**
1/8-1/4 **BURLINGAME, CA 94010** **FINDS**
0.230 mi. **HIST CORTESE**
1216 ft. **Site 31 of 56 in cluster I** **ECHO**

Relative: Higher

Actual: 33 ft.

RCRA-SQG:

Date form received by agency:	03/22/2001
Facility name:	PUTNAM CHEVROLET CADILLAC
Facility address:	198 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD983606716
Contact:	RICK CORSO
Contact address:	198 CALIFORNIA DR

PUTNAM CHEVROLET CADILLAC (Continued) **1000596695**

BURLINGAME, CA 94010
Contact country: US
Contact telephone: (650) 342-9500
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: JOE PUTNAM
Owner/operator address: 3 CALIFORNIA DR
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (650) 347-4800
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

LUST:
Region: STATE
Global Id: T0608101044
Latitude: 37.5785749930435
Longitude: -122.342392802238
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/27/2001
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1137

PUTNAM CHEVROLET CADILLAC (Continued) **1000596695**

LOC Case Number: 660060
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608101044
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608101044
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608101044
Status: Completed - Case Closed
Status Date: 12/27/2001

Global Id: T0608101044
Status: Open - Case Begin Date
Status Date: 03/25/1987

Regulatory Activities:
Global Id: T0608101044
Action Type: Other
Date: 05/06/1992
Action: Leak Discovery

Global Id: T0608101044
Action Type: Other
Date: 03/25/1987
Action: Leak Reported

Global Id: T0608101044
Action Type: ENFORCEMENT
Date: 05/06/1992
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660060

PUTNAM CHEVROLET CADILLAC (Continued) **1000596695**

Facility Status: 9- Case Closed
Global ID: T0608101044
APN Number: 029233080
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

FINDS:

Registry ID: 110002861591

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1137

ECHO:
Envid: 1000596695
Registry ID: 110002861591
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002861591

H307 **OKI OHATA** **HAZNET** **S112952633**
SSW **1500 BURLINGAME AVE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.233 mi.
1230 ft. **Site 20 of 22 in cluster H**

Relative:
Higher

Actual:
43 ft.

HAZNET:
envid: S112952633
Year: 2006
GEPAID: CAC002602300
Contact: OKI OHATA
Telephone: 4083942315
Mailing Name: Not reported
Mailing Address: 1500 BURLINGAME AVE
Mailing City,St,Zip: BURLINGAME, CA 940105199
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 0.84
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

J308 **CHMIRS** **S110423176**
ENE **NEAR 1000 BURLINGAME AVE.** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.233 mi.
1231 ft. **Site 2 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

CHMIRS:

OES Incident Number:	08-6849
OES notification:	09/19/2008
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Rail Road
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	N/A
Other:	Not reported
Date/Time:	1802
Year:	2008
Agency:	AMTRAK-San Jose
Incident Date:	9/19/2008
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Train vs. Trespasser
Quantity Released:	N/A
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S110423176**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	1
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Train ID# Caltrain 373 struck and killed a trespasser at DOT crossing # 7554887M MP# 16.2 on the Peninsula Commuter Service Sub-division.

M309 **AUTO TIGER** **San Mateo Co. BI** **S113756760**
NW **621 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.235 mi.
1239 ft. **Site 1 of 39 in cluster M**

Relative: **Lower**

Actual: **22 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0022465
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024553
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0022465
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0024554
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

M310 **EDR Hist Auto** **1015580102**
NW **621 CALIFORNIA DR** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.235 mi.
1239 ft. **Site 2 of 39 in cluster M**

Relative: **Lower**

Actual: **22 ft.**

EDR Historical Auto Stations:

Name:	AUTO TIGER
Year:	1999
Address:	621 CALIFORNIA DR

Name:	CALIFORNIA DR AUTO SERVICE
Year:	2001
Address:	621 CALIFORNIA DR

Name:	CALIFORNIA DR AUTO SERVICE
Year:	2002
Address:	621 CALIFORNIA DR

(Continued) **1015580102**

Name: CALIFORNIA DRIVE AUTO SERVICE INC
Year: 2003
Address: 621 CALIFORNIA DR

Name: PENINSULA PRIME MOTORZ
Year: 2010
Address: 621 CALIFORNIA DR

M311 **PENINSULA PRIME MOTORZ LLC** **San Mateo Co. BI** **S113758467**
NW **621 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.235 mi.
1239 ft. **Site 3 of 39 in cluster M**

Relative:
Lower

Actual:
22 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0038617
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0055058
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0038617
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0055057
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

M312 **BURLINGAME PRIME MOTORZ** **San Mateo Co. BI** **S113757955**
NW **621 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.235 mi.
1239 ft. **Site 4 of 39 in cluster M**

Relative:
Lower

Actual:
22 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0058084
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0080570
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0058084
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0080569
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0028258
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0046746
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

BURLINGAME PRIME MOTORZ (Continued) **S113757955**

Region: SAN MATEO
Facility ID: FA0028258
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0046747
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

M313 **ON TRACK AUTOMOTIVE** **RCRA-SQG** **1000418397**
NW **621 CALIFORNIA DR** **FINDS** **CAD982489106**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.235 mi.
1239 ft. **Site 5 of 39 in cluster M**

Relative:
Lower

Actual:
22 ft.

RCRA-SQG:
Date form received by agency: 04/27/1990
Facility name: ON TRACK AUTOMOTIVE
Facility address: 621 CALIFORNIA DR
BURLINGAME, CA 94010
EPA ID: CAD982489106
Contact: ENVIRONMENTAL MANAGER
Contact address: 621 CALIFORNIA DR
BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 343-4594
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: W BARNES & R VERNAZZA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

ON TRACK AUTOMOTIVE (Continued) **1000418397**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110002828968

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:

Envid:	1000418397
Registry ID:	110002828968
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002828968

M314 **CALIFORNIA DRIVE AUTO SERVICE** **San Mateo Co. BI** **S113757362**
NW **621 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.235 mi.
1239 ft. **Site 6 of 39 in cluster M**

Relative:
Lower

Actual:
22 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0025639
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0034580
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0025639
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0034581
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

I315
SE
1/8-1/4
0.238 mi.
1255 ft.

HARRIS & CRISAFI C/O RRM, INC
137 LORTON AVENUE
BURLINGAME, CA 94010

Site 32 of 56 in cluster I

FINDS **1011978884**
ECHO **N/A**

Relative:
Higher

Actual:
37 ft.

FINDS:

Registry ID: 110038081544

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011978884
Registry ID:	110038081544
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110038081544

I316
SE
1/8-1/4
0.238 mi.
1255 ft.

HARRIS & CRISAFI C/O RRM, INC
137 LORTON AVENUE
BURLINGAME, CA 94010

Site 33 of 56 in cluster I

EMI **S107621094**
N/A

Relative:
Higher

Actual:
37 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.017
Reactive Organic Gases Tons/Yr:	0.0118762
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.006
Reactive Organic Gases Tons/Yr:	.0041916
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HARRIS & CRISAFI C/O RRM, INC (Continued) **S107621094**

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.042
Reactive Organic Gases Tons/Yr:	.0293412
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.057
Reactive Organic Gases Tons/Yr:	.0398202
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.05
Reactive Organic Gases Tons/Yr:	.03493
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953

HARRIS & CRISAFI C/O RRM, INC (Continued) **S107621094**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	5.0000000000000003E-2
Reactive Organic Gases Tons/Yr:	3.4930000000000003E-2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	16014
Air District Name:	BA
SIC Code:	4953
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.5000000000000003E-2
Reactive Organic Gases Tons/Yr:	2.4451000000000001E-2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

L317 **DAVID & YVONNE BERNIER** **HAZNET** **S113781491**
West **1427 FLORIBUNDA AVE APT 205** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.238 mi.
1259 ft. **Site 2 of 9 in cluster L**

Relative:
Lower

Actual:
28 ft.

HAZNET:

envid:	S113781491
Year:	2012
GEPAID:	CAC002695770
Contact:	DAVID & YVONNE BERNIER
Telephone:	4102247017
Mailing Name:	Not reported
Mailing Address:	1427 FLORIBUNDA AVE APT 205
Mailing City,St,Zip:	BURLINGAME, CA 940103807
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

G318 **ST CATHERINES CHURCH** **HAZNET** **S112849014**
SE **121 PARK RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.239 mi.
1261 ft. **Site 61 of 61 in cluster G**

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S112849014
Year:	1993
GEPAID:	CAC000873680
Contact:	ROMAN CATHOLIC WELFARE CORP
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1310 BAYSWATER AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	5.0568
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

---

319 **T MOBILE SITE ID SF53613A** **San Mateo Co. BI** **S113758919**
NE **850 BURLINGAME** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.240 mi.
1267 ft.

Relative:
Lower

Actual:
22 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0049056
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0067005
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

K320 **MURDOCH LABORITORIES** **FINDS** **1005622707**
SSE **123 PRIMROSE** **ECHO** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.243 mi.
1284 ft. **Site 27 of 29 in cluster K**

Relative:
Higher

Actual:
41 ft.

FINDS:

Registry ID: 110011463022

Environmental Interest/Information System
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

MURDOCH LABORITORIES (Continued) **1005622707**

ECHO:
Envid: 1005622707
Registry ID: 110011463022
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110011463022

I321 **CHEVRON, FORMER/EAGLE GAS STA** **RGA LUST** **S114599940**
ESE **177 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.248 mi.
1307 ft. **Site 34 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2012	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2011	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2010	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2009	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2008	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2007	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2006	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA
2005	CHEVRON, FORMER/EAGLE GAS STA	177 CALIFORNIA

I322 **CHEVRON** **RGA LUST** **S114600280**
ESE **177 CALIFORNIA AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.248 mi.
1307 ft. **Site 35 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2002	CHEVRON	177 CALIFORNIA AVE
2001	CHEVRON	177 CALIFORNIA AVE
2000	CHEVRON	177 CALIFORNIA AVE

I323 **BUBBLE MACHINE** **SWEEPS UST** **S101593682**
ESE **177 CALIFORNIA DR** **CA FID UST** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.248 mi.
1307 ft. **Site 36 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

SWEEPS UST:

Status:	Active
Comp Number:	660026
Number:	9
Board Of Equalization:	Not reported
Referral Date:	03-24-94
Action Date:	03-24-94
Created Date:	10-13-88
Owner Tank Id:	UNK
SWRCB Tank Id:	41-000-660026-000001
Tank Status:	A
Capacity:	10000
Active Date:	03-24-94
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED

BUBBLE MACHINE (Continued) **S101593682**

Number Of Tanks: 3

Status: Active
Comp Number: 660026
Number: 9
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: UNK
SWRCB Tank Id: 41-000-660026-000002
Tank Status: A
Capacity: 10000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 660026
Number: 9
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: UNK
SWRCB Tank Id: 41-000-660026-000003
Tank Status: A
Capacity: 6000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: DIESEL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41000151
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 2 ANNABEL LN
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

I324 **FORMER CHEVRON/EAGLE GAS STA** **RGA LUST** **S114622143**
ESE **177 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.248 mi.
1307 ft. **Site 37 of 56 in cluster I**

Relative:
Higher

RGA LUST:

2003	FORMER CHEVRON/EAGLE GAS STA	177 CALIFORNIA

Actual:
34 ft.

I325 **CHEVRON, FORMER/EAGLE GAS STA** **LUST** **S104891007**
ESE **177 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.248 mi.
1307 ft. **Site 38 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Pollution Characterization
Case Number:	660013
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	1/1/1965
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

I326 **CHEVRON, FORMER/EAGLE GAS STA** **LUST** **S101438110**
ESE **177 CALIFORNIA** **HIST CORTESE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.248 mi.
1307 ft. **Site 39 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

LUST:

Region:	STATE
Global Id:	T0608194030
Latitude:	37.578459
Longitude:	-122.34303
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/17/2006
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0128
LOC Case Number:	660013
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CHEVRON, FORMER/EAGLE GAS STA (Continued) **S101438110**

Contact:

Global Id:	T0608194030
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608194030
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608194030
Status:	Completed - Case Closed
Status Date:	05/17/2006

Global Id:	T0608194030
Status:	Open - Case Begin Date
Status Date:	08/04/1987

Global Id:	T0608194030
Status:	Open - Site Assessment
Status Date:	08/04/1987

Global Id:	T0608194030
Status:	Open - Verification Monitoring
Status Date:	11/22/2000

Regulatory Activities:

Global Id:	T0608194030
Action Type:	Other
Date:	08/04/1987
Action:	Leak Discovery

Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	05/17/2006
Action:	Closure/No Further Action Letter - #20060517

Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	10/25/2005
Action:	Staff Letter - #20051025

Global Id:	T0608194030
Action Type:	REMEDIATION
Date:	07/03/1989
Action:	Pump & Treat (P&T) Groundwater

CHEVRON, FORMER/EAGLE GAS STA (Continued) **S101438110**

Global Id: T0608194030
Action Type: Other
Date: 09/01/1987
Action: Leak Reported

Global Id: T0608194030
Action Type: REMEDIATION
Date: 07/03/1989
Action: Free Product Removal

Global Id: T0608194030
Action Type: RESPONSE
Date: 05/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 05/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 11/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 05/15/2002
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 10/15/2002
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 05/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 10/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608194030
Action Type: RESPONSE
Date: 01/06/2006
Action: Unknown

Global Id: T0608194030
Action Type: RESPONSE

CHEVRON, FORMER/EAGLE GAS STA (Continued) **S101438110**

Date: 01/25/2006
Action: Unknown

Global Id: T0608194030
Action Type: RESPONSE
Date: 10/01/2005
Action: Request for Closure

Global Id: T0608194030
Action Type: ENFORCEMENT
Date: 02/27/1989
Action: Notice of Responsibility - #1

Global Id: T0608194030
Action Type: ENFORCEMENT
Date: 10/11/2005
Action: Staff Letter - #20051011

Global Id: T0608194030
Action Type: ENFORCEMENT
Date: 06/01/2005
Action: * Verbal Communication - #20050601

Global Id: T0608194030
Action Type: ENFORCEMENT
Date: 08/09/2000
Action: Staff Letter - #20000809

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660013
Facility Status: 9- Case Closed
Global ID: T0608194030
APN Number: 029232160
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0128

I327 **FORMER CHEVRON/EAGLE GAS** **RGA LUST** **S114622144**
ESE **177 CALIFORNIA AVE** **N/A**
1/8-1/4 **BURLINGAME, CA**
0.248 mi.
1307 ft. **Site 40 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2002	FORMER CHEVRON/EAGLE GAS	177 CALIFORNIA AVE
2001	FORMER CHEVRON/EAGLE GAS	177 CALIFORNIA AVE

I328
ESE
1/8-1/4
0.248 mi.
1307 ft.

CHEVRON
177 CALIFORNIA ST
BURLINGAME, CA

Site 41 of 56 in cluster I

RGA LUST **S114600281**
N/A

Relative:
Higher

Actual:
34 ft.

RGA LUST:

1998	CHEVRON	177 CALIFORNIA ST
1997	CHEVRON	177 CALIFORNIA ST
1996	CHEVRON	177 CALIFORNIA ST
1995	CHEVRON	177 CALIFORNIA ST
1994	CHEVRON	177 CALIFORNIA ST
1993	CHEVRON	177 CALIFORNIA ST
1992	CHEVRON	177 CALIFORNIA ST

I329
ESE
1/8-1/4
0.248 mi.
1307 ft.

BUBBLE CAR WASH
177 CALIFORNIA DR
BURLINGAME, CA 94010

Site 42 of 56 in cluster I

UST **U003782725**
N/A

Relative:
Higher

Actual:
34 ft.

UST:

Facility ID:	41-000-660026
Permitting Agency:	SAN MATEO COUNTY
Latitude:	37.5797326
Longitude:	-122.3420162

I330
ESE
1/8-1/4
0.248 mi.
1307 ft.

CHEVRON STORE #90364
177 CALIFORNIA DR
BURLINGAME, CA 94010

Site 43 of 56 in cluster I

HAZNET **S112955703**
N/A

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112955703
Year:	2006
GEPAID:	CAC002607181
Contact:	KATHY NORRIS
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	SAN RAMON, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.07
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

I331 **EAGLE CAR WASH & FILL** **San Mateo Co. BI** **S113756598**
ESE **177 CALIFORNIA** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.248 mi.
1307 ft. **Site 44 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004623
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022758
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0027807
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

J332 **EDR Hist Auto** **1015369170**
ENE **257 MYRTLE RD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.250 mi.
1320 ft. **Site 3 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

EDR Historical Auto Stations:

Name:	ALL MAKES AUTO BODY SHOP
Year:	1999
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO BODY SHOP
Year:	2000
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO BODY SHOP
Year:	2001
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO BODY SHOP
Year:	2002
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO BODY SHOP
Year:	2003
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO B ODY SH OP
Year:	2004
Address:	257 MYRTLE RD

Name:	ALL MAKES AUTO BODY SHOP

(Continued) **1015369170**

Year: 2009
Address: 257 MYRTLE RD

Name: ALL MAKES AUTO BODY SHOP
Year: 2010
Address: 257 MYRTLE RD

Name: ALL MAKES AUTO BODY SHOP
Year: 2011
Address: 257 MYRTLE RD

Name: ALL MAKES AUTO BODY SHOP
Year: 2012
Address: 257 MYRTLE RD

J333 **ALL MAKES AUTO BODY** **San Mateo Co. BI** **S113755525**
ENE **257 MYRTLE** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.250 mi.
1320 ft. **Site 4 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0010115
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0011925
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0010115
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004697
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

J334 **ALL MAKES AUTO BODY SHOP** **HAZNET** **S113163925**
ENE **257 MYRTLE ROAD** **N/A**
1/8-1/4 **BURLINGAME, CA 94010**
0.250 mi.
1320 ft. **Site 5 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

HAZNET:
envid: S113163925
Year: 2013
GEPAID: CAL912943159
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 257 MYRTLE RD
Mailing City,St,Zip: BURLINGAME, CA 940103029
Gen County: San Mateo
TSD EPA ID: NED981723513
TSD County: 99
Waste Category: Not reported
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel

ALL MAKES AUTO BODY SHOP (Continued) **S113163925**

Tons: 0.198
Cat Decode: Not reported
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: Not reported

envid: S113163925
Year: 2010
GEPAID: CAL912943159
Contact: Not reported
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 257 MYRTLE RD
Mailing City,St,Zip: BURLINGAME, CA 940103029
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.198
Cat Decode: Unspecified solvent mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113163925
Year: 2008
GEPAID: CAL912943159
Contact: Not reported
Telephone: Not reported
Mailing Name: Not reported
Mailing Address: 257 MYRTLE RD
Mailing City,St,Zip: BURLINGAME, CA 940103029
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.198
Cat Decode: Unspecified solvent mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113163925
Year: 2007
GEPAID: CAL912943159
Contact: Not reported
Telephone: Not reported
Mailing Name: Not reported
Mailing Address: 257 MYRTLE RD
Mailing City,St,Zip: BURLINGAME, CA 940103029
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified solvent mixture

ALL MAKES AUTO BODY SHOP (Continued) **S113163925**

Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.19
Cat Decode:	Unspecified solvent mixture
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113163925
Year:	2006
GEPAID:	CAL912943159
Contact:	--
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	257 MYRTLE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103029
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Recycler
Tons:	0.22
Cat Decode:	Unspecified solvent mixture
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
13 additional CA_HAZNET: record(s) in the EDR Site Report.

J335 **ALL MAKES AUTO BODY SHOP** **FINDS** **1005773723**
ENE **257 MYRTLE ROAD** **EMI** **N/A**
1/8-1/4 **BURLINGAME, CA 94010** **ECHO**
0.250 mi.
1320 ft. **Site 6 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

FINDS:

Registry ID: 110002413031

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

EMI:

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0

ALL MAKES AUTO BODY SHOP (Continued) **1005773723**

SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41

ALL MAKES AUTO BODY SHOP (Continued) **1005773723**

Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported

ALL MAKES AUTO BODY SHOP (Continued) **1005773723**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.272
Reactive Organic Gases Tons/Yr:	0.2527894
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.618
Reactive Organic Gases Tons/Yr:	.493158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.618
Reactive Organic Gases Tons/Yr:	.493158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

ALL MAKES AUTO BODY SHOP (Continued) **1005773723**

Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.618
Reactive Organic Gases Tons/Yr:	.493158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.618
Reactive Organic Gases Tons/Yr:	.493158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.68999999999999995
Reactive Organic Gases Tons/Yr:	0.55854360000000003
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	2010
County Code:	41
Air Basin:	SF

ALL MAKES AUTO BODY SHOP (Continued) **1005773723**

Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.68999999999999995
Reactive Organic Gases Tons/Yr:	0.55854360000000003
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	8582
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.69
Reactive Organic Gases Tons/Yr:	0.5585436
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

ECHO:

Envid:	1005773723
Registry ID:	110002413031
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002413031

J336 **A & I CUSTOMS** **San Mateo Co. BI** **S113756196**
ENE **255 MYRTLE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.251 mi.
1324 ft. **Site 7 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0016140
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011924
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0016140
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0027454
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

J337
ENE
1/4-1/2
0.251 mi.
1324 ft.

255 MYRTLE RD
BURLINGAME, CA 94010

Site 8 of 14 in cluster J

EDR Hist Auto **1015367902**
N/A

Relative:
Lower

Actual:
27 ft.

EDR Historical Auto Stations:

Name: UNITED AUTO COLLISON CENTER
Year: 1999
Address: 255 MYRTLE RD

Name: UNITED AUTO COLLISON CENTER
Year: 2000
Address: 255 MYRTLE RD

Name: UNITED AUTO COLLISON CTR
Year: 2001
Address: 255 MYRTLE RD

Name: UNITED AUTO COLLISION CTR
Year: 2003
Address: 255 MYRTLE RD

Name: 2M AUTOMOTIVE
Year: 2011
Address: 255 MYRTLE RD

J338
ENE
1/4-1/2
0.251 mi.
1324 ft.

UNITED AUTO COLLISION CENTER C
255 MYRTLE ROAD
BURLINGAME, CA 94010

Site 9 of 14 in cluster J

FINDS **1005775836**
EMI **N/A**
ECHO

Relative:
Lower

Actual:
27 ft.

FINDS:

Registry ID: 110002412176

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

EMI:

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

UNITED AUTO COLLISION CENTER C (Continued) **1005775836**

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532

UNITED AUTO COLLISION CENTER C (Continued) **1005775836**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.273
Reactive Organic Gases Tons/Yr:	0.2569902
Carbon Monoxide Emissions Tons/Yr:	0

UNITED AUTO COLLISION CENTER C (Continued) **1005775836**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	9012
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.273
Reactive Organic Gases Tons/Yr:	.2569902
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

ECHO:

Envid:	1005775836
Registry ID:	110002412176
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002412176

J339 **UNITED AUTO COLLISION CENTER CORP.** **HAZNET** **S113106110**
ENE **255 MYRTLE ROAD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.251 mi.
1324 ft. **Site 10 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

HAZNET:

envid:	S113106110
Year:	2005
GEPAID:	CAL000208381
Contact:	GABRIEL ARIAS/OWNER
Telephone:	6503758698
Mailing Name:	Not reported
Mailing Address:	255 MYRTLE RD STE 6
Mailing City,St,Zip:	BURLINGAME, CA 940103029
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Recycler
Tons:	0.25
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113106110
Year:	2003
GEPAID:	CAL000208381
Contact:	GABRIEL ARIAS/OWNER
Telephone:	6503758698

UNITED AUTO COLLISION CENTER CORP. (Continued) **S113106110**

Mailing Name:	Not reported
Mailing Address:	255 MYRTLE RD STE 6
Mailing City,St,Zip:	BURLINGAME, CA 940103029
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Recycler
Tons:	0.39
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Recycler
Facility County:	San Mateo

J340 **I&M AUTO BODY & PAINT SHOP** **EMI** **S106832882**
ENE **255 MYRTLE ROAD #6** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.251 mi.
1324 ft. **Site 11 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

EMI:

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	6033
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

J341 **2M AUTOMOTIVE** **San Mateo Co. BI** **S113758563**
ENE **255 MYRTLE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.251 mi.
1324 ft. **Site 12 of 14 in cluster J**

Relative:
Lower

Actual:
27 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0040750
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0056556
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0040750
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0066844
Description:	STORES MV FUELS OR WASTE ONLY

2M AUTOMOTIVE (Continued) **S113758563**

Facility Status: INACTIVE

I342 **JACK WONG** **HAZNET** **S112881538**
East **220 E LANE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.251 mi.
1325 ft. **Site 45 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S112881538
Year:	1998
GEPAID:	CAC001313056
Contact:	JACK WONG
Telephone:	6506974093
Mailing Name:	Not reported
Mailing Address:	1867 HUNT DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD044429835
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.0625
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112881538
Year:	1998
GEPAID:	CAC001313056
Contact:	JACK WONG
Telephone:	6506974093
Mailing Name:	Not reported
Mailing Address:	1867 HUNT DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	.2000
Cat Decode:	Other organic solids
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112881538
Year:	1998
GEPAID:	CAC001313056
Contact:	JACK WONG
Telephone:	6506974093
Mailing Name:	Not reported
Mailing Address:	1867 HUNT DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD044429835
TSD County:	Not reported
Waste Category:	Alkaline solution without metals pH >= 12.5
Disposal Method:	Disposal, Other

JACK WONG (Continued) **S112881538**

Tons: .0075
Cat Decode: Alkaline solution without metals pH >= 12.5
Method Decode: Disposal, Other
Facility County: San Mateo

M343 **BELINDA LIN** **HAZNET** **S113782516**
NW **1209 OAK GROVE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.254 mi.
1340 ft. **Site 7 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

HAZNET:
envid: S113782516
Year: 2012
GEPAID: CAC002697012
Contact: BELINDA LIN
Telephone: 4153351619
Mailing Name: Not reported
Mailing Address: 1209 OAK GROVE AVE
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

M344 **W. J. BRITTON COMPANY** **LUST** **S103065158**
NW **701 CALIFORNIA** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.254 mi.
1343 ft. **Site 8 of 39 in cluster M**

Relative:
Lower

Actual:
21 ft.

LUST:
Region: STATE
Global Id: T0608100626
Latitude: 37.582236
Longitude: -122.351484
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 06/30/1998
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0657
LOC Case Number: 660006
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

W. J. BRITTON COMPANY (Continued) **S103065158**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100626
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100626
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100626
Status:	Completed - Case Closed
Status Date:	06/30/1998

Global Id:	T0608100626
Status:	Open - Case Begin Date
Status Date:	08/06/1986

Regulatory Activities:

Global Id:	T0608100626
Action Type:	Other
Date:	01/09/1987
Action:	Leak Discovery

Global Id:	T0608100626
Action Type:	Other
Date:	08/06/1986
Action:	Leak Reported

Global Id:	T0608100626
Action Type:	REMEDIATION
Date:	05/01/1997
Action:	Excavation

Global Id:	T0608100626
Action Type:	ENFORCEMENT
Date:	11/15/1989
Action:	Notice of Responsibility - #1

LUST REG 2:

Region:	2
Facility Id:	Not reported

W. J. BRITTON COMPANY (Continued) **S103065158**

Facility Status: Case Closed
Case Number: 660006
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660006
Facility Status: 9- Case Closed
Global ID: T0608100626
APN Number: 029053160
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0657

M345 **WJ BRITTON** **RGA LUST** **S114722851**
NW **701 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 9 of 39 in cluster M**

Relative: RGA LUST:
Lower

1995	WJ BRITTON	701 CALIFORNIA DR
1994	WJ BRITTON	701 CALIFORNIA DR
1993	WJ BRITTON	701 CALIFORNIA DR

Actual:
21 ft.

M346 **W.J. BRITTON COMPANY** **RGA LUST** **S114719597**
NW **701 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 10 of 39 in cluster M**

Relative: RGA LUST:
Lower

1996	W.J. BRITTON COMPANY	701 CALIFORNIA DR

Actual:
21 ft.

M347 **W. J. BRITTON COMPANY** **RGA LUST** **S114719553**
NW **701 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 11 of 39 in cluster M**

Relative: RGA LUST:
Lower

2012	W. J. BRITTON COMPANY	701 CALIFORNIA
2011	W. J. BRITTON COMPANY	701 CALIFORNIA
2010	W. J. BRITTON COMPANY	701 CALIFORNIA
2009	W. J. BRITTON COMPANY	701 CALIFORNIA
2008	W. J. BRITTON COMPANY	701 CALIFORNIA
2007	W. J. BRITTON COMPANY	701 CALIFORNIA
2006	W. J. BRITTON COMPANY	701 CALIFORNIA
2005	W. J. BRITTON COMPANY	701 CALIFORNIA
2003	W. J. BRITTON COMPANY	701 CALIFORNIA

Actual:
21 ft.

M348 **WJ BRITTON COMPANY** **RGA LUST** **S114722850**
NW **701 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 12 of 39 in cluster M**

Relative: RGA LUST:
Lower

2002	WJ BRITTON COMPANY	701 CALIFORNIA DR
2001	WJ BRITTON COMPANY	701 CALIFORNIA DR
2000	WJ BRITTON COMPANY	701 CALIFORNIA DR

Actual:
21 ft.

M349 **WJ BRITTON** **RGA LUST** **S114722852**
NW **701 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 13 of 39 in cluster M**

Relative: RGA LUST:
Lower

1992	WJ BRITTON	701 CALIFORNIA

Actual:
21 ft.

M350 **WJ BRITTON COMPANY** **RGA LUST** **S114722849**
NW **701 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.254 mi.
1343 ft. **Site 14 of 39 in cluster M**

Relative: RGA LUST:
Lower

1998	WJ BRITTON COMPANY	701 CALIFORNIA DR
1997	WJ BRITTON COMPANY	701 CALIFORNIA DR

Actual:
21 ft.

M351 **CHMIRS** **S109045898**
NW **OAK GROVE AND CALIFORNIA STREETS** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.255 mi.
1346 ft. **Site 15 of 39 in cluster M**

Relative: **Lower**

Actual: **21 ft.**

CHMIRS:

OES Incident Number:	7-1540
OES notification:	03/10/2007
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	storm drain
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2007
Agency:	City of Burlingame
Incident Date:	3/10/2007 12:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	No
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	Sewage
Gallons:	4500
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S109045898**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	03/10/07 at 0930 hours, a blockage in a main line cause an overflow out of a manhole. The sewage flowed into a catch basin, then into a storm drain and then into an underground boxed culvert. 500 gallons were recovered.

M352 **CHMIRS** **S109035846**
NW **1217 OAK GROVE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.257 mi.
1356 ft. **Site 16 of 39 in cluster M**

Relative: **Lower**

Actual: **18 ft.**

CHMIRS:

OES Incident Number:	6-7517
OES notification:	12/20/2006
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Ralston Creek
Spill Site:	Not reported

(Continued) **S109035846**

Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2006
Agency:	City of Burlingame
Incident Date:	12/20/2006 12:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Road
E Date:	Not reported
Substance:	Sewage
Gallons:	1800
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Due to a sewer main being blocked a release occurred from 2 man holes. Approximately half was recovered.

I353 **MIKE HARVEY HONDA** **FINDS** **1008244237**
East **212 EAST LANE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.258 mi.
1360 ft. **Site 46 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

FINDS:

Registry ID: 110021334055

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1008244237
Registry ID:	110021334055
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110021334055

I354 **MIKE HARVEY HONDA** **EMI** **S106248795**
East **212 EAST LANE** **N/A**
1/4-1/2 **BURLINGAME, CA 94011**
0.258 mi.
1360 ft. **Site 47 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

EMI:

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7538
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7538
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7538
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.114
Reactive Organic Gases Tons/Yr:	0.937989
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005

MIKE HARVEY HONDA (Continued) **S106248795**

County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7538
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.015
Reactive Organic Gases Tons/Yr:	.898389
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7538
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.015
Reactive Organic Gases Tons/Yr:	.898389
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.015
Reactive Organic Gases Tons/Yr:	.898389
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD

MIKE HARVEY HONDA (Continued) **S106248795**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.015
Reactive Organic Gases Tons/Yr:	.898389
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	12305
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.0149999999999999
Reactive Organic Gases Tons/Yr:	0.89838899999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

I355 **MIKE HARVEY ACURA AUTO REPAIR** **San Mateo Co. BI** **S113757820**
East **212 LANE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.258 mi.
1360 ft. **Site 48 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0027657
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0044412
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0027657
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0044413
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

I356 **MIKE HARVEY HONDA** **HAZNET** **S113083231**
East **212 E LANE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.258 mi.
1360 ft. **Site 49 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S113083231
Year:	2014
GEPAID:	CAL000153481
Contact:	ERIC USHER
Telephone:	6505796810
Mailing Name:	Not reported
Mailing Address:	200 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	San Mateo
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.2085
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113083231
Year:	2013
GEPAID:	CAL000153481
Contact:	ERIC USHER
Telephone:	6505796810
Mailing Name:	Not reported
Mailing Address:	200 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	San Mateo
TSD EPA ID:	CAT080013352
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.93825
Cat Decode:	Not reported
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	Not reported

envid:	S113083231
Year:	2011
GEPAID:	CAL000153481
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796820
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture

MIKE HARVEY HONDA (Continued) **S113083231**

Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.187
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113083231
Year:	2011
GEPAID:	CAL000153481
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796820
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.187
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113083231
Year:	2011
GEPAID:	CAL000153481
Contact:	ERIC USHER SERVICE DIRECTOR
Telephone:	6505796820
Mailing Name:	Not reported
Mailing Address:	PO BOX 943
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	1.2093
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
35 additional CA_HAZNET: record(s) in the EDR Site Report.

I357 **EDR Hist Auto** **1015323308**
East **212 EAST LN** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.258 mi.
1360 ft. **Site 50 of 56 in cluster I**

Relative:
Lower

Actual:
31 ft.

EDR Historical Auto Stations:

Name:	MIKE HARVEY HONDA BODY SHOP
Year:	2005
Address:	212 EAST LN
Name:	MIKE HARVEY HONDA BODY SHOP
Year:	2006
Address:	212 EAST LN
Name:	MIKE HARVEY HONDA BODY SHOP
Year:	2011
Address:	212 EAST LN
Name:	MIKE HARVEY HONDA BODY SHOP
Year:	2012
Address:	212 EAST LN

N358 **JD GIUSTI TRANSPORTATION** **RCRA NonGen / NLR** **1000235583**
SE **125 LORTON AVE #2** **FINDS** **CAD982319444**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.259 mi.
1366 ft. **Site 1 of 4 in cluster N**

Relative:
Higher

Actual:
38 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/26/1988
Facility name:	JD GIUSTI TRANSPORTATION
Facility address:	125 LORTON AVE #2 BURLINGAME, CA 94010
EPA ID:	CAD982319444
Mailing address:	LORTON AVE #SECOND BURLINGAME, CA 94010
Contact:	ENVIRONMENTAL MANAGER
Contact address:	125 LORTON AVE #SECOND BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 579-0545
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JOHN DAVID GIUSTI
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	NOT REQUIRED

JD GIUSTI TRANSPORTATION (Continued) **1000235583**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002792960

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000235583
Registry ID: 110002792960
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002792960

J359 **RETIREMENT INN OF BURLINGAME** **HAZNET** **S112898451**
ENE **250 MYRTLE RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.259 mi.
1369 ft. **Site 13 of 14 in cluster J**

Relative:
Lower

Actual:
28 ft.

HAZNET:
envid: S112898451
Year: 1999
GEPAID: CAC002117792
Contact: ARV ASSITED LIVING

RETIREMENT INN OF BURLINGAME (Continued) **S112898451**

Telephone:	7143422369
Mailing Name:	Not reported
Mailing Address:	250 MYRTLE RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	.1000
Cat Decode:	Other organic solids
Method Decode:	Transfer Station
Facility County:	San Mateo

J360 **ATRIA BURLINGAME** **HAZNET** **S113790667**
ENE **250 MYRTLE RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.259 mi.
1369 ft. **Site 14 of 14 in cluster J**

Relative:
Lower

Actual:
28 ft.

HAZNET:

envid:	S113790667
Year:	2012
GEPAID:	CAC002708561
Contact:	ATRIA BURLINGAME
Telephone:	6503432747
Mailing Name:	Not reported
Mailing Address:	250 MYRTLE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103094
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

O361 **EDR Hist Cleaner** **1014994591**
WSW **1460 BELLEVUE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.263 mi.
1390 ft. **Site 1 of 4 in cluster O**

Relative:
Higher

Actual:
37 ft.

EDR Historical Cleaners:

Name:	AMRO CARPET CLEANING SVC
Year:	2010
Address:	1460 BELLEVUE AVE

L362 **GUS PAROS** **HAZNET** **S112894247**
West **1440 FLORI BUNDA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.267 mi.
1410 ft. **Site 3 of 9 in cluster L**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S112894247
Year:	1999
GEPAID:	CAC001477224
Contact:	GUS PAROS
Telephone:	6503499077
Mailing Name:	Not reported
Mailing Address:	2695 S EL CAMINO REAL
Mailing City,St,Zip:	SAN MATEO, CA 944030000
Gen County:	Not reported
TSD EPA ID:	CAL000190080
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	.4214
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

H363 **ST PAUL EPISCOPAL CHURCH** **HAZNET** **S113773153**
SW **415 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.268 mi.
1417 ft. **Site 21 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

HAZNET:

envid:	S113773153
Year:	2012
GEPAID:	CAC002685468
Contact:	CAROL MARTIN
Telephone:	6503484811
Mailing Name:	Not reported
Mailing Address:	415 EL CAMINO REAL
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

H364 **ST PAULS EPISCOPAL CHURCH** **HAZNET** **S112906865**
SW **415 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.268 mi.
1417 ft. **Site 22 of 22 in cluster H**

Relative:
Higher

Actual:
41 ft.

HAZNET:

envid:	S112906865
Year:	2000
GEPAID:	CAC002246089
Contact:	LLOYD AUBRY-PARISH ADMN
Telephone:	6503484811
Mailing Name:	Not reported
Mailing Address:	415 EL CAMINO REAL
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000190080
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.26
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

N365 **BURT BERENSTEIN** **HAZNET** **S118221623**
SE **110 PARK ROAD #206** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.269 mi.
1419 ft. **Site 2 of 4 in cluster N**

Relative:
Higher

Actual:
39 ft.

HAZNET:

envid:	S118221623
Year:	2014
GEPAID:	CAC002785056
Contact:	BURT BERENSTEIN
Telephone:	6506857422
Mailing Name:	Not reported
Mailing Address:	110 PARK ROAD #206
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

N366 **DAVE TOWNSEND** **HAZNET** **S112989585**
SE **110 PARK RD APT 601** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.269 mi.
1419 ft. **Site 3 of 4 in cluster N**

Relative:
Higher

Actual:
39 ft.

HAZNET:

envid:	S112989585
Year:	2011
GEPAID:	CAC002670998
Contact:	DAVE TOWNSEND
Telephone:	6507930863
Mailing Name:	Not reported
Mailing Address:	110 PARK RD APT 601
Mailing City,St,Zip:	BURLINGAME, CA 940104343
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

O367 **BURLINGAME TOWERS** **HAZNET** **S113104853**
WSW **1469 BELLEVUE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.272 mi.
1437 ft. **Site 2 of 4 in cluster O**

Relative:
Higher

Actual:
38 ft.

HAZNET:

envid:	S113104853
Year:	2002
GEPAID:	CAL000206240
Contact:	RAY OTUS
Telephone:	6503750772
Mailing Name:	Not reported
Mailing Address:	1419 BURLINGAME AVE SUITE P2
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S113104853
Year:	2002
GEPAID:	CAL000206240
Contact:	RAY OTUS
Telephone:	6503750772
Mailing Name:	Not reported
Mailing Address:	1419 BURLINGAME AVE SUITE P2
Mailing City,St,Zip:	BURLINGAME, CA 940100000

BURLINGAME TOWERS (Continued) **S113104853**

Gen County: Not reported
TSD EPA ID: CAL000190080
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 1.68
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

envid: S113104853
Year: 2001
GEPAID: CAL000206240
Contact: RAY OTUS
Telephone: 6503750772
Mailing Name: Not reported
Mailing Address: 1419 BURLINGAME AVE SUITE P2
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD981382732
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Disposal, Land Fill
Tons: 11.58
Cat Decode: Asbestos containing waste
Method Decode: Disposal, Land Fill
Facility County: San Mateo

O368 **BURLINGAME TOWERS** **HAZNET** **S112997523**
WSW **1469 BELLEVUE AVE.** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.272 mi.
1437 ft. **Site 3 of 4 in cluster O**

Relative:
Higher

Actual:
38 ft.

HAZNET:
envid: S112997523
Year: 2013
GEPAID: CAC002739397
Contact: BRANDON SILVERSPRINGS
Telephone: 6504948600
Mailing Name: Not reported
Mailing Address: 2275 E BAYSHORE RD STE 130
Mailing City,St,Zip: EAST PALO ALTO, CA 943033222
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: Not reported

envid: S112997523
Year: 2011
GEPAID: CAC002681309

BURLINGAME TOWERS (Continued) **S112997523**

Contact:	JOLEEN SALBANA
Telephone:	6503430400
Mailing Name:	Not reported
Mailing Address:	1469 BELLEVUE AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103987
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

P369 **OLDE ENGLISH GARAGE** **San Mateo Co. BI** **S113756639**
East **988 HOWARD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 1 of 16 in cluster P**

Relative: **Lower**

Actual: **30 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018048
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011862
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0018048
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004660
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0018048
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0047429
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

P370 **RICKS TEXACO** **HIST UST** **U001593944**
East **988 HOWARD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 2 of 16 in cluster P**

Relative: **Lower**

Actual: **30 ft.**

HIST UST:

File Number:	0002C1D5
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C1D5.pdf
Region:	STATE
Facility ID:	00000018076

RICKS TEXACO (Continued) **U001593944**

Facility Type:	Gas Station
Other Type:	REPAIR
Contact Name:	RICK STURIZA
Telephone:	4153448031
Owner Name:	RICK STURIZA
Owner Address:	505 HOWARD AVE
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0005
Tank Num:	001
Container Num:	5
Year Installed:	Not reported
Tank Capacity:	00000250
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000300
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	004
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	005
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

P371 **RICK'S SERVICE** **HAZNET** **S113076426**
East **988 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 3 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S113076426
Year:	2000
GEPAID:	CAL000139790
Contact:	BRIAN MYERS-OWNER
Telephone:	6503448031
Mailing Name:	Not reported
Mailing Address:	718 CHAPEL CT
Mailing City,St,Zip:	LUCAS, TX 750020000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.62
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113076426
Year:	1998
GEPAID:	CAL000139790
Contact:	BRIAN MYERS
Telephone:	6503448031
Mailing Name:	Not reported
Mailing Address:	988 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	.4170
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113076426
Year:	1998
GEPAID:	CAL000139790
Contact:	BRIAN MYERS
Telephone:	6503448031
Mailing Name:	Not reported
Mailing Address:	988 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	1.6680
Cat Decode:	Waste oil and mixed oil
Method Decode:	Transfer Station

RICK'S SERVICE (Continued) **S113076426**

Facility County: San Mateo

P372 **1X OLD ENGLISH GARAGE** **HAZNET** **S112854697**
East **988 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 4 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S112854697
Year:	1993
GEPAID:	CAC000940120
Contact:	ROBERT LUGLIANI
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	ROBERT LUGLIANI
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	0.14999999999
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

P373 **RICKS SERVICE** **San Mateo Co. BI** **S113756619**
East **988 HOWARD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 5 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018010
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023922
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018010
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004616
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018010
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022780
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

P374 **RICKS BEACON** **SWEEPS UST** **S101629555**
East **988 HOWARD AVE** **CA FID UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 6 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660101
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660101-000001
Tank Status:	Not reported
Capacity:	300
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	1

Status:	Active
Comp Number:	660061
Number:	2
Board Of Equalization:	Not reported
Referral Date:	03-24-94
Action Date:	03-24-94
Created Date:	10-13-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660061-000001
Tank Status:	A
Capacity:	8000
Active Date:	03-24-94
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	4

Status:	Active
Comp Number:	660061
Number:	2
Board Of Equalization:	Not reported
Referral Date:	03-24-94
Action Date:	03-24-94
Created Date:	10-13-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660061-000002
Tank Status:	A
Capacity:	4000
Active Date:	03-24-94
Tank Use:	M.V. FUEL
STG:	P
Content:	LEADED
Number Of Tanks:	Not reported

Status:	Active

RICKS BEACON (Continued) **S101629555**

Comp Number: 660061
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660061-000003
Tank Status: A
Capacity: 4000
Active Date: 03-24-94
Tank Use: M.V. FUEL
STG: P
Content: DIESEL
Number Of Tanks: Not reported

Status: Active
Comp Number: 660061
Number: 2
Board Of Equalization: Not reported
Referral Date: 03-24-94
Action Date: 03-24-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660061-000005
Tank Status: A
Capacity: 150
Active Date: 03-24-94
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Active
Comp Number: 660101
Number: 2
Board Of Equalization: Not reported
Referral Date: 01-28-94
Action Date: 01-28-94
Created Date: 12-13-93
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41003227
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported

RICKS BEACON (Continued) **S101629555**

Mail To: Not reported
Mailing Address: 228 HIGHLAND AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

P375 **OLDE ENGLISH GARAGE** **HAZNET** **S113026834**
East **988 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 7 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:
envid: S113026834
Year: 2004
GEPAID: CAL000014965
Contact: BOB LUGLIANI
Telephone: 6503448030
Mailing Name: Not reported
Mailing Address: 988 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940103009
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: Recycler
Tons: 0.16
Cat Decode: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Decode: Recycler
Facility County: San Mateo

envid: S113026834
Year: 2004
GEPAID: CAL000014965
Contact: BOB LUGLIANI
Telephone: 6503448030
Mailing Name: Not reported
Mailing Address: 988 HOWARD AVE
Mailing City,St,Zip: BURLINGAME, CA 940103009
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: 12
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler
Facility County: San Mateo

envid: S113026834
Year: 2004
GEPAID: CAL000014965

OLDE ENGLISH GARAGE (Continued) **S113026834**

Contact:	BOB LUGLIANI
Telephone:	6503448030
Mailing Name:	Not reported
Mailing Address:	988 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103009
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.62
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

P376 **OLDE ENGLISH GARAGE** **HAZNET** **S113037603**
East **988 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1451 ft. **Site 8 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S113037603
Year:	1999
GEPAID:	CAL000039922
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	988 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103009
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Transfer Station
Tons:	2.7516
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Transfer Station
Facility County:	San Mateo

M377 **EDR Hist Cleaner** **1015090483**
NW **715 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1452 ft. **Site 17 of 39 in cluster M**

Relative:
Lower

Actual:
20 ft.

EDR Historical Cleaners:

Name:	MR & MRS BUBBLES COIN LAUNDRIES
Year:	1999
Address:	715 CALIFORNIA DR
Name:	MR & MRS BUBBLES COIN LAUNDRIES
Year:	2000
Address:	715 CALIFORNIA DR
Name:	MR & MRS BUBBLES COIN LNDRY

(Continued) **1015090483**

Year: 2001
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LNDRY
Year: 2002
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LNDRY
Year: 2003
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LNDRY
Year: 2004
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2005
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2006
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2007
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2008
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2009
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRY
Year: 2010
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2011
Address: 715 CALIFORNIA DR

Name: MR & MRS BUBBLES COIN LAUNDRIES
Year: 2012
Address: 715 CALIFORNIA DR

M378 **ROGER & REBECCA EMERICK** **HAZNET** **S113460897**
NW **715 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.275 mi.
1452 ft. **Site 18 of 39 in cluster M**

Relative:
Lower

Actual:
20 ft.

HAZNET:
envid: S113460897
Year: 2010
GEPAID: CAC002654559
Contact: ROGER & REBECCA

ROGER & REBECCA EMERICK (Continued) **S113460897**

Telephone:	4082491590
Mailing Name:	Not reported
Mailing Address:	4125 BLACKFORD AVE STE 250
Mailing City,St,Zip:	SAN JOSE, CA 95117
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

K379 **EDR Hist Auto** **1015178053**
SSE **120 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.276 mi.
1456 ft. **Site 28 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

EDR Historical Auto Stations:

Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2001
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2002
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2003
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2004
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2005
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2006
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2007
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2008
Address:	120 EL CAMINO REAL
Name:	C & D AUTOMOTIVE & MARINE INC
Year:	2011
Address:	120 EL CAMINO REAL

(Continued) **1015178053**

Name: C & D AUTOMOTIVE & MARINE INC
Year: 2012
Address: 120 EL CAMINO REAL

K380 **C&D AUTOMOTIVE AND MARINE INC** **San Mateo Co. BI** **S113755421**
SSE **120 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.276 mi.
1456 ft. **Site 29 of 29 in cluster K**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0008139
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011903
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0008139
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004721
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

L381 **FLORIBUNDA HOA** **HAZNET** **S112955476**
West **1477 FLORIBUNDA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.277 mi.
1464 ft. **Site 4 of 9 in cluster L**

Relative:
Higher

Actual:
32 ft.

HAZNET:
envid: S112955476
Year: 2006
GEPAID: CAC002606820
Contact: HERSCHEL HERZBERG/VP
Telephone: 6505792653
Mailing Name: Not reported
Mailing Address: 1477 FLORIBUNDA AVE
Mailing City,St,Zip: BURLINGAME, CA 940107516
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 5.51
Cat Decode: Waste oil and mixed oil
Method Decode: Transfer Station
Facility County: San Mateo

L382 **RAPHEL AGUIRRE** **HAZNET** **S113463223**
WSW **525 ALMER RD APT 302** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.282 mi.
1487 ft. **Site 5 of 9 in cluster L**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S113463223
Year:	2010
GEPAID:	CAC002658423
Contact:	RAPHEL AGUIRRE
Telephone:	4802722142
Mailing Name:	Not reported
Mailing Address:	525 ALMER RD APT 302
Mailing City,St,Zip:	BURLINGAME, CA 940107611
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

L383 **JAMIE RICE** **HAZNET** **S113781300**
WSW **525 ALMER RD APT 101** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.282 mi.
1487 ft. **Site 6 of 9 in cluster L**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S113781300
Year:	2012
GEPAID:	CAC002695530
Contact:	JAMIE RICE
Telephone:	4153109183
Mailing Name:	Not reported
Mailing Address:	525 ALMER RD APT 101
Mailing City,St,Zip:	BURLINGAME, CA 940103945
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

N384 **NORMAN GOLDAU** **HAZNET** **S112879626**
SE **111 LORTON** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.283 mi.
1495 ft. **Site 4 of 4 in cluster N**

Relative: Higher

Actual: 39 ft.

HAZNET:

envid:	S112879626
Year:	1998
GEPAID:	CAC001270792
Contact:	NORMAN GOLDAU
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1201 HOWARD ST STE 101
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD990794133
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	.6321
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

I385 **BURLINGAME SUBARU ALFA** **RCRA-SQG** **1000595765**
ESE **150 CALIFORNIA DR** **FINDS** **CAD983597204**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.284 mi.
1498 ft. **Site 51 of 56 in cluster I**

Relative: Higher

Actual: 33 ft.

RCRA-SQG:

Date form received by agency:	07/30/1991
Facility name:	BURLINGAME SUBARU ALFA
Facility address:	150 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD983597204
Mailing address:	CALIFORNIA DR BURLINGAME, CA 94010
Contact:	RICHARD BILBREY
Contact address:	150 CALIFORNIA DR BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 348-8600
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212

BURLINGAME SUBARU ALFA (Continued) **1000595765**

Legal status: County
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BURLINGAME SUBARU ALFA INC
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002854652

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000595765
Registry ID: 110002854652
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002854652

Q386 **DAVID DESJARBAN** **HAZNET** **S112965257**
SSW **1538 BURLINGAME AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.294 mi.
1550 ft. **Site 1 of 4 in cluster Q**

Relative:
Higher

Actual:
47 ft.

HAZNET:

envid:	S112965257
Year:	2007
GEPAID:	CAC002622719
Contact:	GREG SCAPAZZI
Telephone:	6508264777
Mailing Name:	Not reported
Mailing Address:	1538 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	1.87
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S112965257
Year:	2007
GEPAID:	CAC002622719
Contact:	GREG SCAPAZZI
Telephone:	6508264777
Mailing Name:	Not reported
Mailing Address:	1538 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.6
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Q387 **UST SITE** **San Mateo Co. BI** **S113758352**
SSW **1538 BURLINGAME** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.294 mi.
1550 ft. **Site 2 of 4 in cluster Q**

Relative:
Higher

Actual:
47 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0036526
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0053566
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

I388 **PACIFIC AUTO REPAIR** **San Mateo Co. BI** **S113756608**
ESE **124 HIGHLAND** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.295 mi.
1556 ft. **Site 52 of 56 in cluster I**

Relative:
Higher

Actual:
37 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0017997
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011839
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0017997
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004622
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

I389 **PACIFIC AUTO REPAIR** **HAZNET** **S113036258**
ESE **124 HIGHLAND AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.295 mi.
1556 ft. **Site 53 of 56 in cluster I**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S113036258
Year:	2002
GEPAID:	CAL000036973
Contact:	VIELBAUM GARY PRE
Telephone:	6503434931
Mailing Name:	Not reported
Mailing Address:	124 HIGHLAND AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.22
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113036258
Year:	2001
GEPAID:	CAL000036973
Contact:	VIELBAUM GARY PRE
Telephone:	6503434931
Mailing Name:	Not reported
Mailing Address:	124 HIGHLAND AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.89

PACIFIC AUTO REPAIR (Continued) **S113036258**

Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113036258
Year: 2000
GEPAID: CAL000036973
Contact: VIELBAUM GARY PRE
Telephone: 6503434931
Mailing Name: Not reported
Mailing Address: 124 HIGHLAND AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 1.25
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113036258
Year: 1999
GEPAID: CAL000036973
Contact: GARY VIELBAUM - PRES
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 124 HIGHLAND AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: .8340
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113036258
Year: 1999
GEPAID: CAL000036973
Contact: GARY VIELBAUM - PRES
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 124 HIGHLAND AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD982446874
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: .4587
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

PACIFIC AUTO REPAIR (Continued) **S113036258**

Click this hyperlink while viewing on your computer to access
5 additional CA_HAZNET: record(s) in the EDR Site Report.

I390 **EDR Hist Auto** **1015190522**
ESE **124 HIGHLAND AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.295 mi.
1556 ft. **Site 54 of 56 in cluster I**

Relative:
Higher

Actual:
37 ft.

EDR Historical Auto Stations:

Name: PACIFIC AUTO REPAIR
Year: 1999
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2000
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2001
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2002
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2003
Address: 124 HIGHLAND AVE

Name: VIELBAUM AUTOMOTIVE INC
Year: 2006
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2007
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2008
Address: 124 HIGHLAND AVE

Name: VIELBAUM AUTOMOTIVE INC
Year: 2009
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2010
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2011
Address: 124 HIGHLAND AVE

Name: PACIFIC AUTO REPAIR
Year: 2012
Address: 124 HIGHLAND AVE

M391 **WOODHALL INVESTMENTS** **RGA LUST** **S114723006**
NW **731 SAN MATEO AVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.299 mi.
1578 ft. **Site 19 of 39 in cluster M**

Relative: **Lower**

Actual: **18 ft.**

RGA LUST:

1998	WOODHALL INVESTMENTS	731 SAN MATEO AVE
1997	WOODHALL INVESTMENTS	731 SAN MATEO AVE
1996	WOODHALL INVESTMENTS	731 SAN MATEO AVE
1995	WOODHALL INVESTMENTS	731 SAN MATEO AVE
1994	WOODHALL INVESTMENTS	731 SAN MATEO AVE
1993	WOODHALL INVESTMENTS	731 SAN MATEO AVE

R392 **ST CATHERINE CATHOLIC CHURCH** **HAZNET** **S112971667**
SSE **1310 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.303 mi.
1598 ft. **Site 1 of 6 in cluster R**

Relative: **Higher**

Actual: **41 ft.**

HAZNET:

envid:	S112971667
Year:	2008
GEPAID:	CAC002632579
Contact:	MIKE SMIMADA
Telephone:	6503446884
Mailing Name:	Not reported
Mailing Address:	1310 BAYSWATER AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

R393 **ROMAN CATHOLIC ARCHBISHOP OF SAN FRAN** **HAZNET** **S112890978**
SSE **1310 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.303 mi.
1598 ft. **Site 2 of 6 in cluster R**

Relative: **Higher**

Actual: **41 ft.**

HAZNET:

envid:	S112890978
Year:	1999
GEPAID:	CAC001430948
Contact:	ARCHDIOCESE OF SAN FRANCISCO
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	445 CHURCH ST
Mailing City,St,Zip:	SAN FRANCISCO, CA 941140000
Gen County:	Not reported
TSD EPA ID:	CAT080033681

ROMAN CATHOLIC ARCHBISHOP OF SAN FRAN (Continued) **S112890978**

TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	.4000
Cat Decode:	Other organic solids
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

P394 **THE NEW DATSONVILLE** **HAZNET** **S113801954**
East **927 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.305 mi.
1610 ft. **Site 9 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S113801954
Year:	2012
GEPAID:	CAL000374202
Contact:	JAN BUNZEL
Telephone:	6503488856
Mailing Name:	Not reported
Mailing Address:	927 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0834
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113801954
Year:	2012
GEPAID:	CAL000374202
Contact:	JAN BUNZEL
Telephone:	6503488856
Mailing Name:	Not reported
Mailing Address:	927 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.03
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

P395 **EDR Hist Auto** **1015677274**
East **927 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.305 mi.
1610 ft. **Site 10 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

EDR Historical Auto Stations:

Name:	TOYOTA REPAIRS BY DATSONVILLE
Year:	2003
Address:	927 HOWARD AVE
Name:	DATSONVILLE AUTOMOTIVE CENTER
Year:	2005
Address:	927 HOWARD AVE
Name:	DATSONVILLE AUTOMOTIVE CENTER
Year:	2008
Address:	927 HOWARD AVE
Name:	DATSONVILLE AUTOMOTIVE CENTER
Year:	2009
Address:	927 HOWARD AVE
Name:	DATSONVILLE AUTOMOTIVE CTR
Year:	2010
Address:	927 HOWARD AVE
Name:	NISSAN REPAIRS BY DATSONVILLE
Year:	2011
Address:	927 HOWARD AVE
Name:	NISSAN REPAIRS BY DATSONVILLE
Year:	2012
Address:	927 HOWARD AVE

P396 **NEW DATSONVILLE** **San Mateo Co. BI** **S113756626**
East **927 HOWARD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.305 mi.
1610 ft. **Site 11 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018023
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011841
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0018023
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0024660
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

I397 **NOEL L MILLER INC** **San Mateo Co. BI** **S113756618**
ESE **129 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.306 mi.
1616 ft. **Site 55 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018009
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011877
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0018009
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004625
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

I398 **NOEL L MILLER INC** **HAZNET** **S113013196**
ESE **129 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.306 mi.
1616 ft. **Site 56 of 56 in cluster I**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S113013196
Year:	2007
GEPAID:	CAD982038754
Contact:	STEVEN SOMA
Telephone:	6503438656
Mailing Name:	Not reported
Mailing Address:	129 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Solvents Recovery
Tons:	0.35
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Solvents Recovery
Facility County:	San Mateo

envid:	S113013196
Year:	2006
GEPAID:	CAD982038754
Contact:	STEVEN SOMA
Telephone:	6503438656
Mailing Name:	Not reported
Mailing Address:	129 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	0.25

NOEL L MILLER INC (Continued) **S113013196**

Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113013196
Year: 2006
GEPAID: CAD982038754
Contact: STEVEN SOMA
Telephone: 6503438656
Mailing Name: Not reported
Mailing Address: 129 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Solvents Recovery
Tons: 0.22
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Solvents Recovery
Facility County: San Mateo

envid: S113013196
Year: 2006
GEPAID: CAD982038754
Contact: STEVEN SOMA
Telephone: 6503438656
Mailing Name: Not reported
Mailing Address: 129 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.22
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113013196
Year: 2005
GEPAID: CAD982038754
Contact: STEVEN SOMA
Telephone: 6503438656
Mailing Name: Not reported
Mailing Address: 129 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 0.43
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

NOEL L MILLER INC (Continued) **S113013196**

Click this hyperlink while viewing on your computer to access
14 additional CA_HAZNET: record(s) in the EDR Site Report.

P399 **RICHARD SAMUELSON** **HAZNET** **S117281808**
East **917 HOWARD AVE.** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.309 mi.
1630 ft. **Site 12 of 16 in cluster P**

Relative:
Lower

Actual:
30 ft.

HAZNET:

envid:	S117281808
Year:	2013
GEPAID:	CAC002715539
Contact:	JANICE SAMUELSON
Telephone:	5102133833
Mailing Name:	Not reported
Mailing Address:	917 HOWARD AVE.
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0035
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

L400 **DEITER BLUHM** **LUST** **S103472705**
WNW **1285 OAK GROVE** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.309 mi.
1630 ft. **Site 7 of 9 in cluster L**

Relative:
Lower

Actual:
26 ft.

LUST:

Region:	STATE
Global Id:	T0608100073
Latitude:	37.58111
Longitude:	-122.352541
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/30/1991
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0078
LOC Case Number:	660042
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

DEITER BLUHM (Continued) **S103472705**

Contact:
Global Id: T0608100073
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100073
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100073
Status: Completed - Case Closed
Status Date: 09/30/1991

Global Id: T0608100073
Status: Open - Case Begin Date
Status Date: 05/25/1990

Regulatory Activities:
Global Id: T0608100073
Action Type: Other
Date: 05/25/1990
Action: Leak Reported

Global Id: T0608100073
Action Type: ENFORCEMENT
Date: 09/30/1991
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660042
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported

DEITER BLUHM (Continued) **S103472705**

Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660042
Facility Status:	9- Case Closed
Global ID:	T0608100073
APN Number:	029131010
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0078

L401 **BLUHM PROPERTY** **RGA LUST** **S114585017**
WNW **1285 OAK GROVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.309 mi.
1630 ft. **Site 8 of 9 in cluster L**

Relative:
Lower

Actual:
26 ft.

RGA LUST:

1998	BLUHM PROPERTY	1285 OAK GROVE
1997	BLUHM PROPERTY	1285 OAK GROVE
1996	BLUHM PROPERTY	1285 OAK GROVE
1995	BLUHM PROPERTY	1285 OAK GROVE
1994	BLUHM PROPERTY	1285 OAK GROVE
1993	BLUHM PROPERTY	1285 OAK GROVE
1992	BLUHM PROPERTY	1285 OAK GROVE

L402 **DEITER BLUHM** **RGA LUST** **S114609800**
WNW **1285 OAK GROVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.309 mi.
1630 ft. **Site 9 of 9 in cluster L**

Relative:
Lower

Actual:
26 ft.

RGA LUST:

2012	DEITER BLUHM	1285 OAK GROVE
2011	DEITER BLUHM	1285 OAK GROVE
2010	DEITER BLUHM	1285 OAK GROVE
2009	DEITER BLUHM	1285 OAK GROVE
2008	DEITER BLUHM	1285 OAK GROVE
2007	DEITER BLUHM	1285 OAK GROVE
2006	DEITER BLUHM	1285 OAK GROVE
2005	DEITER BLUHM	1285 OAK GROVE
2003	DEITER BLUHM	1285 OAK GROVE
2002	DEITER BLUHM	1285 OAK GROVE
2001	DEITER BLUHM	1285 OAK GROVE
2000	DEITER BLUHM	1285 OAK GROVE

S403 **HAROLDS MACHINE SHOP** **San Mateo Co. BI** **S113756636**
ESE **127 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.309 mi.
1631 ft. **Site 1 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018044
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0025196
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018044
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004655
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

S404 **HAROLD'S MACHINE SHOP** **FINDS** **1006306066**
ESE **127 CALIFORNIA DRIVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.309 mi.
1631 ft. **Site 2 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

FINDS:

Registry ID: 110012421343

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

ECHO:

Envid:	1006306066
Registry ID:	110012421343
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110012421343

R405 **CAMINO REAL PET CLINIC** **HAZNET** **S113168420**
SSE **1317 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.310 mi.
1636 ft. **Site 3 of 6 in cluster R**

Relative:
Higher

Actual:
42 ft.

HAZNET:

envid:	S113168420
Year:	1998
GEPAID:	CAL923054441
Contact:	GERALD SANDULTS
Telephone:	6503445711
Mailing Name:	Not reported
Mailing Address:	1317 BAYSWATER AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104312
Gen County:	Not reported
TSD EPA ID:	CAL000121946
TSD County:	Not reported

CAMINO REAL PET CLINIC (Continued) **S113168420**

Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .2502
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113168420
Year: 1997
GEPAID: CAL923054441
Contact: GERALD SANDULTS
Telephone: 6503445711
Mailing Name: Not reported
Mailing Address: 1317 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940104312
Gen County: Not reported
TSD EPA ID: CAL000121946
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .1251
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113168420
Year: 1995
GEPAID: CAL923054441
Contact: GERALD SANDULTS
Telephone: 6503445711
Mailing Name: Not reported
Mailing Address: 1317 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940104312
Gen County: Not reported
TSD EPA ID: CAL000121946
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .1251
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113168420
Year: 1994
GEPAID: CAL923054441
Contact: GERALD SANDULTS
Telephone: 6503445711
Mailing Name: Not reported
Mailing Address: 1317 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940104312
Gen County: Not reported
TSD EPA ID: CAD981161367
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .1251

CAMINO REAL PET CLINIC (Continued) **S113168420**

Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113168420
Year: 1993
GEPAID: CAL923054441
Contact: GERALD SANDULTS
Telephone: 6503445711
Mailing Name: Not reported
Mailing Address: 1317 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940104312
Gen County: Not reported
TSD EPA ID: Not reported
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: 0.12509999999
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

M406 **BLUE RIBBON CLEANERS** **San Mateo Co. BI** **S113757904**
NW **741 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 20 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027971
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0045984
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0027971
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0045985
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

M407 **BLUE RIBBON CLEANERS** **San Mateo Co. BI** **S113758551**
NW **741 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 21 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0040425
Prog Element Code: GENERATES <27 GAL/YEAR

BLUE RIBBON CLEANERS (Continued) **S113758551**

Record Id:	PR0056461
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0040425
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0056460
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

M408 **GEORGES HOLIDAY CLEANERS** **EMI** **S110502360**
NW **741 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 22 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

EMI:

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14937
Air District Name:	BA
SIC Code:	7211
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.325
Reactive Organic Gases Tons/Yr:	.13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14937
Air District Name:	BA
SIC Code:	7211
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.32500000000000001
Reactive Organic Gases Tons/Yr:	0.13
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

M409 **BLUE RIBBON CLEANERS** **CHMIRS** **S102267607**
NW **741 CALIFORNIA DR** **DRYCLEANERS** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 23 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

CHMIRS:

OES Incident Number:	08-0849
OES notification:	01/28/2008
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	Box Culvert
Spill Site:	Road
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1616
Year:	2008
Agency:	City of Burlingame
Incident Date:	1/25/2008
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Box Culvert
E Date:	Not reported
Substance:	Sewage
Quantity Released:	600
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported

BLUE RIBBON CLEANERS (Continued) **S102267607**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Due to infiltration from rain - an overflow occurred. It went to a catch basin and then to Box Culvert.

DRYCLEANERS:

EPA Id:	CAL000277436
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	12/17/2003
Facility Active:	No
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	TONI MINTGOMERY & CLAY HAYES
Owner Address:	741 CALIFORNIA DR
Owner Address 2:	Not reported
Owner Telephone:	6503421682
Contact Name:	SUZIE KWON
Contact Address:	741 CALIFORNIA DR
Contact Address 2:	Not reported
Contact Telephone:	6503440838
Mailing Name:	Not reported
Mailing Address 1:	741 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940103703
Owner Fax:	2
Region Code:	Not reported

EPA Id:	CAL000335309
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	08/08/2008
Facility Active:	No
Inactive Date:	Not reported
Facility Addr2:	Not reported
Owner Name:	YOUNG JUN SHIM
Owner Address:	YOUNG JUN SHIM
Owner Address 2:	Not reported
Owner Telephone:	4157302859

BLUE RIBBON CLEANERS (Continued) **S102267607**

Contact Name:	YOUNG JUN SHIM
Contact Address:	741 CALIFORNIA DR
Contact Address 2:	Not reported
Contact Telephone:	6503440838
Mailing Name:	Not reported
Mailing Address 1:	741 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940103703
Owner Fax:	2
Region Code:	0000000000

M410 **GEORGES HOLIDAY CLEANERS** **FINDS** **1015878317**
NW **741 CALIFORNIA DRIVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 24 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

FINDS:

Registry ID: 110054255774

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1015878317
Registry ID:	110054255774
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110054255774

M411 **EDR Hist Cleaner** **1015092831**
NW **741 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 25 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

EDR Historical Cleaners:

Name:	HOLIDAY CLEANERS OF AMERICA
Year:	2001
Address:	741 CALIFORNIA DR
Name:	HOLIDAY CLEANERS OF AMERICA
Year:	2003
Address:	741 CALIFORNIA DR
Name:	BLUE RIBBON CLEANERS
Year:	2006
Address:	741 CALIFORNIA DR
Name:	BLUE RIBBON CLEANERS
Year:	2007
Address:	741 CALIFORNIA DR
Name:	BLUE RIBBON CLEANERS

(Continued) **1015092831**

Year: 2008
Address: 741 CALIFORNIA DR

Name: BLUE RIBBON CLEANERS
Year: 2010
Address: 741 CALIFORNIA DR

Name: BLUE RIBBON CLEANERS
Year: 2011
Address: 741 CALIFORNIA DR

Name: BLUE RIBBON CLEANERS
Year: 2012
Address: 741 CALIFORNIA DR

M412 **BLUE RIBBON CLEANERS** **HAZNET** **S113129726**
NW **741 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 26 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

HAZNET:
envid: S113129726
Year: 2012
GEPAID: CAL000277436
Contact: SUZIE KWON
Telephone: 6503440838
Mailing Name: Not reported
Mailing Address: 741 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103703
Gen County: San Mateo
TSD EPA ID: TXD077603371
TSD County: 99
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.1
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113129726
Year: 2009
GEPAID: CAL000277436
Contact: SUZIE KWON
Telephone: 6503440838
Mailing Name: Not reported
Mailing Address: 741 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103703
Gen County: Not reported
TSD EPA ID: TXD077603371
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.3
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L

BLUE RIBBON CLEANERS (Continued) **S113129726**

Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113129726
Year:	2008
GEPAID:	CAL000277436
Contact:	SUZIE KWON
Telephone:	6503440838
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.4
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113129726
Year:	2007
GEPAID:	CAL000277436
Contact:	TONI MONTGOMERY
Telephone:	6502186801
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	TXD077603371
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.15
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S113129726
Year:	2004
GEPAID:	CAL000277436
Contact:	TONI MONTGOMERY
Telephone:	6502186801
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	KYD053348108
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station

BLUE RIBBON CLEANERS (Continued) **S113129726**

Tons: 0.25
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

M413 **BLUE RIBBON CLEANERS** **San Mateo Co. BI** **S113755373**
NW **741 CALIFORNIA** **DRYCLEANERS** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 27 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0058098
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0080590
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0058098
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0080589
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0007269
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011887
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0007269
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0004715
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

DRYCLEANERS:
EPA Id: CAL000401706
NAICS Code: 81232
NAICS Description: Drycleaning and Laundry Services (except Coin-Operated)
SIC Code: 7211
SIC Description: Power Laundries, Family and Commercial
Create Date: 10/29/2014
Facility Active: No
Inactive Date: Not reported
Facility Addr2: Not reported
Owner Name: GREGORY HALL
Owner Address: 741 CALIFORNIA DR
Owner Address 2: Not reported
Owner Telephone: 4157933474

BLUE RIBBON CLEANERS (Continued) **S113755373**

Contact Name:	GREGORY HALL
Contact Address:	741 CALIFORNIA DR
Contact Address 2:	Not reported
Contact Telephone:	4157933474
Mailing Name:	Not reported
Mailing Address 1:	741 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940103703
Owner Fax:	2
Region Code:	Not reported

M414 **GEORGE'S HOLIDAY CLEANERS** **HAZNET** **S113057053**
NW **741 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1640 ft. **Site 28 of 39 in cluster M**

Relative:
Lower

Actual:
19 ft.

HAZNET:

envid:	S113057053
Year:	2003
GEPAID:	CAL000092918
Contact:	ARPINA KEVRANIAN
Telephone:	4153438907
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	0.55
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113057053
Year:	1999
GEPAID:	CAL000092918
Contact:	GEORGE AND ARPINA KEVRANIAN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.0975
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113057053
Year:	1998

GEORGE'S HOLIDAY CLEANERS (Continued) **S113057053**

GEPAID:	CAL000092918
Contact:	GEORGE AND ARPINA KEVRANIAN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.0975
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113057053
Year:	1997
GEPAID:	CAL000092918
Contact:	GEORGE AND ARPINA KEVRANIAN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.1950
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113057053
Year:	1996
GEPAID:	CAL000092918
Contact:	GEORGE AND ARPINA KEVRANIAN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	741 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.1950
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

T415 **PENINSULA TENNIS CLUB** **HAZNET** **S112965088**
NNE **433 CHATHAM RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1643 ft. **Site 1 of 3 in cluster T**

Relative:
Lower

Actual:
19 ft.

HAZNET:

envid:	S112965088
Year:	2008
GEPAID:	CAC002622450
Contact:	ERNIE LONG
Telephone:	6503444700
Mailing Name:	Not reported
Mailing Address:	433 CHATHAM RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	S112965088
Year:	2007
GEPAID:	CAC002622450
Contact:	ERNIE LONG
Telephone:	6503444700
Mailing Name:	Not reported
Mailing Address:	433 CHATHAM RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

---

416 **BOB N DISCO** **PEST LIC** **S117646835**
ENE **850 BURLINGAME AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.311 mi.
1643 ft.

Relative:
Lower

Actual:
28 ft.

PEST LIC:

Facility Type:	QAC
Categories:	C
License No:	78946
Issued or Renewed Date:	01/01/2015
Expiration Date:	12/31/2016

S417 **BURLINGAME COLLISON REPAIR** **San Mateo Co. BI** **S113755223**
ESE **123 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 3 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0002575
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011865
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0002575
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004656
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

S418 **EDR Hist Auto** **1015188230**
ESE **123 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 4 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

EDR Historical Auto Stations:

Name:	BURLINGAME COLLISION CENTER
Year:	1999
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CENTER
Year:	2000
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CTR
Year:	2001
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CTR
Year:	2002
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CTR
Year:	2003
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CTR
Year:	2004
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CENTER
Year:	2005
Address:	123 CALIFORNIA DR

Name:	BURLINGAME COLLISION CENTER
Year:	2006
Address:	123 CALIFORNIA DR

(Continued) **1015188230**

Name: BURLINGAME COLLISION CTR
Year: 2010
Address: 123 CALIFORNIA DR

Name: BURLINGAME COLLISION CENTER
Year: 2011
Address: 123 CALIFORNIA DR

Name: BURLINGAME COLLISION CENTER
Year: 2012
Address: 123 CALIFORNIA DR

S419 **MONTALVO CORP DBA BURLINGAME COLLISION CENTER** **HAZNET** **S113156444**
ESE **123 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 5 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

HAZNET:
envid: S113156444
Year: 2014
GEPAID: CAL000344253
Contact: DON MONTALVO
Telephone: 6503750600
Mailing Name: Not reported
Mailing Address: 123 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: San Mateo
TSD EPA ID: CAD059494310
TSD County: Santa Clara
Waste Category: Unspecified organic liquid mixture
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.102
Cat Decode: Unspecified organic liquid mixture
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113156444
Year: 2013
GEPAID: CAL000344253
Contact: DON MONTALVO
Telephone: 6503750600
Mailing Name: Not reported
Mailing Address: 123 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: San Mateo
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Not reported
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.231
Cat Decode: Not reported
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: Not reported

MONTALVO CORP DBA BURLINGAME COLLISION CENTER (Continued) **S113156444**

envid: S113156444
Year: 2012
GEPAID: CAL000344253
Contact: DON MONTALVO
Telephone: 6503750600
Mailing Name: Not reported
Mailing Address: 123 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: San Mateo
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Not reported
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.108
Cat Decode: Not reported
Method Decode: Fuel Blending Prior To Energy Recovery At Another Site
Facility County: San Mateo

envid: S113156444
Year: 2011
GEPAID: CAL000344253
Contact: DON MONTALVO
Telephone: 6503750600
Mailing Name: Not reported
Mailing Address: 123 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.165
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113156444
Year: 2009
GEPAID: CAL000344253
Contact: DON MONTALVO
Telephone: 6503750600
Mailing Name: Not reported
Mailing Address: 123 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Off-specification, aged or surplus organics
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0495
Cat Decode: Off-specification, aged or surplus organics
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

MONTALVO CORP DBA BURLINGAME COLLISION CENTER (Continued) **S113156444**

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

S420 **BENZ DOCTOR** **San Mateo Co. BI** **S113758711**
ESE **123 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 6 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045263
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0058556
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0045263
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0058555
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

S421 **BURLINGAME COLLISION REPAIR CE** **RCRA-SQG** **1000285912**
ESE **123 CALIFORNIA DRIVE** **FINDS** **CAD981417074**
1/4-1/2 **BURLINGAME, CA 94010** **EMI**
0.315 mi. **HAZNET**
1661 ft. **Site 7 of 47 in cluster S** **ECHO**

Relative:
Higher

Actual:
34 ft.

RCRA-SQG:

Date form received by agency:	06/03/1986
Facility name:	BURLINGAME BODY SHOP
Facility address:	123 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD981417074
Mailing address:	CALIFORNIA DR BURLINGAME, CA 94010
Contact:	ENVIRONMENTAL MANAGER
Contact address:	123 CALIFORNIA DR BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 347-6372
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	LARRY MASON
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110001168744

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS AIR POLLUTANT MAJOR

EMI:
Year: 1990
County Code: 41
Air Basin: SF
Facility ID: 4900
Air District Name: BA

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.271
Reactive Organic Gases Tons/Yr:	0.224932
Carbon Monoxide Emissions Tons/Yr:	0.003
NOX - Oxides of Nitrogen Tons/Yr:	0.011
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.097
Reactive Organic Gases Tons/Yr:	.0827412
Carbon Monoxide Emissions Tons/Yr:	.003
NOX - Oxides of Nitrogen Tons/Yr:	.011
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.082
Reactive Organic Gases Tons/Yr:	.0680197
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.015
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.08
Reactive Organic Gases Tons/Yr:	.0660517
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.015
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.08
Reactive Organic Gases Tons/Yr:	.0660517
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.015
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	6.7000000000000004E-2
Reactive Organic Gases Tons/Yr:	5.5321500000000003E-2
Carbon Monoxide Emissions Tons/Yr:	4.0000000000000001E-3

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

NOX - Oxides of Nitrogen Tons/Yr:	0.014
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	9.6000000000000002E-2
Reactive Organic Gases Tons/Yr:	0.0834255
Carbon Monoxide Emissions Tons/Yr:	3.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	0.014
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.101
Reactive Organic Gases Tons/Yr:	0.0863797
Carbon Monoxide Emissions Tons/Yr:	0.003
NOX - Oxides of Nitrogen Tons/Yr:	0.011
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.101
Reactive Organic Gases Tons/Yr:	0.0863797
Carbon Monoxide Emissions Tons/Yr:	0.003
NOX - Oxides of Nitrogen Tons/Yr:	0.011
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year: 2013

BURLINGAME COLLISION REPAIR CE (Continued) **1000285912**

County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.087
Reactive Organic Gases Tons/Yr:	0.0739053
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.009
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	9867
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.081447543
Reactive Organic Gases Tons/Yr:	0.081332186
Carbon Monoxide Emissions Tons/Yr:	0.002125001
NOX - Oxides of Nitrogen Tons/Yr:	0.008514027
SOX - Oxides of Sulphur Tons/Yr:	3.4501e-005
Particulate Matter Tons/Yr:	0.000182143
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000182143

HAZNET:

envid:	1000285912
Year:	1993
GEPAID:	CAD981417074
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	123 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method:	Recycler
Tons:	0.27100000000
Cat Decode:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Decode:	Recycler
Facility County:	San Mateo

ECHO:

Envid:	1000285912
Registry ID:	110001168744
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110001168744

M422 **FLOYDS AUTOMOTIVE** **LUST** **S103892239**
NW **741 SAN MATEO AVE** **SWEEPS UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010** **HIST CORTESE**
0.315 mi.
1661 ft. **Site 29 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

LUST:

Region:	STATE
Global Id:	T0608100222
Latitude:	37.5680556
Longitude:	-122.3072222
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/05/2000
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0233
LOC Case Number:	660061
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100222
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100222
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100222
Status:	Completed - Case Closed
Status Date:	09/05/2000

Global Id:	T0608100222
Status:	Open - Case Begin Date
Status Date:	05/27/1992

Regulatory Activities:

Global Id:	T0608100222
Action Type:	Other
Date:	05/28/1992
Action:	Leak Discovery

FLOYDS AUTOMOTIVE (Continued) **S103892239**

Global Id: T0608100222
Action Type: Other
Date: 05/27/1992
Action: Leak Reported

Global Id: T0608100222
Action Type: ENFORCEMENT
Date: 05/28/1992
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660061
Facility Status: 9- Case Closed
Global ID: T0608100222
APN Number: 029053480
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 660096
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660096-000001
Tank Status: Not reported
Capacity: 550
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

Status: Active
Comp Number: 660096
Number: 9
Board Of Equalization: Not reported
Referral Date: 10-19-93
Action Date: 10-19-93
Created Date: 07-08-92
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

FLOYDS AUTOMOTIVE (Continued) **S103892239**

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0233

M423 **FLOYD'S AUTOMOTIVE** **RGA LUST** **S114621138**
NW **741 SAN MATEO AVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.315 mi.
1661 ft. **Site 30 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

RGA LUST:

2002	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
2001	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
2000	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1998	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1997	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1996	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1995	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1994	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE
1993	FLOYD'S AUTOMOTIVE	741 SAN MATEO AVE

M424 **FLOYD'S AUTOMOTIVE** **LUST** **S104493557**
NW **741 SAN MATEO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 31 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660061
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

M425 **FLOYDS AUTOMOTIVE** **San Mateo Co. BI** **S113756848**
NW **741 SAN MATEO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.315 mi.
1661 ft. **Site 32 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0022880
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0025721
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

M426 **FLOYD'S AUTOMOTIVE** **RGA LUST** **S114621139**
NW **741 SAN MATEO** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.315 mi.
1661 ft. **Site 33 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

RGA LUST:

2012	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2011	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2010	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2009	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2008	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2007	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2006	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2005	FLOYD'S AUTOMOTIVE	741 SAN MATEO
2003	FLOYD'S AUTOMOTIVE	741 SAN MATEO

U427 **EDR Hist Auto** **1015609621**
North **708 LAUREL AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.318 mi.
1678 ft. **Site 1 of 9 in cluster U**

Relative:
Lower

Actual:
20 ft.

EDR Historical Auto Stations:

Name:	S & J AUTO
Year:	2004
Address:	708 LAUREL AVE
Name:	S & J AUTO
Year:	2005
Address:	708 LAUREL AVE
Name:	S & J AUTO
Year:	2006
Address:	708 LAUREL AVE

V428 **TRAMMEL CROW COMPANY** **HAZNET** **S112955451**
South **1531 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.322 mi.
1700 ft. **Site 1 of 3 in cluster V**

Relative:
Higher

Actual:
47 ft.

HAZNET:

envid:	S112955451
Year:	2007
GEPAID:	CAC002606788
Contact:	KIMBERLY SMITH
Telephone:	5106388400
Mailing Name:	Not reported
Mailing Address:	2655 GROUND ST
Mailing City,St,Zip:	NAPA, CA 94588
Gen County:	Not reported
TSD EPA ID:	AZC950823111
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Not reported
Tons:	95.2
Cat Decode:	Asbestos containing waste
Method Decode:	Not reported
Facility County:	San Mateo

envid:	S112955451
Year:	2007
GEPAID:	CAC002606788
Contact:	KIMBERLY SMITH
Telephone:	5106388400
Mailing Name:	Not reported
Mailing Address:	2655 GROUND ST
Mailing City,St,Zip:	NAPA, CA 94588
Gen County:	Not reported
TSD EPA ID:	AZC000033763
TSD County:	Not reported
Waste Category:	Polychlorinated biphenyls and material containing PCBs
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	6.06
Cat Decode:	Polychlorinated biphenyls and material containing PCBs
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S112955451
Year:	2007
GEPAID:	CAC002606788
Contact:	KIMBERLY SMITH
Telephone:	5106388400
Mailing Name:	Not reported
Mailing Address:	2655 GROUND ST
Mailing City,St,Zip:	NAPA, CA 94588
Gen County:	Not reported
TSD EPA ID:	AZ0000337360
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)

TRAMMEL CROW COMPANY (Continued) **S112955451**

Tons: 12
Cat Decode: Asbestos containing waste
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

envid: S112955451
Year: 2007
GEPAID: CAC002606788
Contact: KIMBERLY SMITH
Telephone: 5106388400
Mailing Name: Not reported
Mailing Address: 2655 GROUND ST
Mailing City,St,Zip: NAPA, CA 94588
Gen County: Not reported
TSD EPA ID: AZC950823111
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 15.2
Cat Decode: Asbestos containing waste
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

envid: S112955451
Year: 2006
GEPAID: CAC002606788
Contact: KIMBERLY SMITH
Telephone: 5106388400
Mailing Name: Not reported
Mailing Address: 2655 GROUND ST
Mailing City,St,Zip: NAPA, CA 94588
Gen County: Not reported
TSD EPA ID: AZC950823111
TSD County: Not reported
Waste Category: Asbestos containing waste
Disposal Method: Not reported
Tons: 25.28
Cat Decode: Asbestos containing waste
Method Decode: Not reported
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
7 additional CA_HAZNET: record(s) in the EDR Site Report.

R429 **EVELYN CONDON** **HAZNET** **S118198099**
SSE **1501 CYPRESS AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.322 mi.
1700 ft. **Site 4 of 6 in cluster R**

Relative:
Higher

Actual:
42 ft.

HAZNET:
envid: S118198099
Year: 2014
GEPAID: CAC002755275
Contact: EVELYN CONDON

EVELYN CONDON (Continued) **S118198099**

Telephone:	6505883413
Mailing Name:	Not reported
Mailing Address:	1501 CYPRESS AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

M430 **CALIFORNIA AUTO CENTER** **San Mateo Co. BI** **S113757364**
NW **751 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.326 mi.
1723 ft. **Site 34 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0025641
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0034586
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0025641
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0034587
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

M431 **EDR Hist Auto** **1015625427**
NW **751 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.326 mi.
1723 ft. **Site 35 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

EDR Historical Auto Stations:

Name:	FLOYDS AUTO REPAIR
Year:	1999
Address:	751 CALIFORNIA DR

Name:	FLOYDS AUTO REPAIR
Year:	2000
Address:	751 CALIFORNIA DR

Name:	CITY AUTO CARE
Year:	2002
Address:	751 CALIFORNIA DR

(Continued) **1015625427**

Name: CITY AUTO CARE
Year: 2003
Address: 751 CALIFORNIA DR

Name: CITY AUTO CARE
Year: 2004
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2005
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2006
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2007
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2008
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2009
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CTR
Year: 2010
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2011
Address: 751 CALIFORNIA DR

Name: CALIFORNIA AUTO CENTER
Year: 2012
Address: 751 CALIFORNIA DR

M432 **FLOYD'S AUTO REPAIR** **HAZNET** **S113024652**
NW **751 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.326 mi.
1723 ft. **Site 36 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

HAZNET:
envid: S113024652
Year: 1997
GEPAID: CAL000008740
Contact: FLOYD GREGORY
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 751 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103703
Gen County: Not reported
TSD EPA ID: AZD983481813
TSD County: Not reported

FLOYD'S AUTO REPAIR (Continued) **S113024652**

Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	10.6192
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo
envid:	S113024652
Year:	1997
GEPAID:	CAL000008740
Contact:	FLOYD GREGORY
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	751 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	AZD983481813
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Not reported
Tons:	5.5624
Cat Decode:	Asbestos containing waste
Method Decode:	Not reported
Facility County:	San Mateo

M433 **EUROPEAN PERFORMANCE OF BURLINGAME, INC** **RCRA-SQG** **1000340147**
NW **751 CALIFORNIA DR** **FINDS** **CAD051261758**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.326 mi.
1723 ft. **Site 37 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	EUROPEAN PERFORMANCE OF BURLINGAME, INC
Facility address:	751 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD051261758
Mailing address:	CALIFORNIA DR BURLINGAME, CA 94010
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WILLIAM ANDERSON
Owner/operator address:	NOT REQUIRED

EUROPEAN PERFORMANCE OF BURLINGAME, INC (Continued) **1000340147**

NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/21/1986
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State Contractor/Grantee

FINDS:

Registry ID: 110002648332

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

EUROPEAN PERFORMANCE OF BURLINGAME, INC (Continued) **1000340147**

ECHO:
Envid: 1000340147
Registry ID: 110002648332
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002648332

M434 **FLOYDS AUTO REPAIR** **San Mateo Co. BI** **S113755372**
NW **751 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.326 mi.
1723 ft. **Site 38 of 39 in cluster M**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0007267
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011886
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0007267
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0004678
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

T435 **GREG TAYLOR** **HAZNET** **S113792939**
NNE **446 CHATHAM RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.327 mi.
1729 ft. **Site 2 of 3 in cluster T**

Relative:
Lower

Actual:
19 ft.

HAZNET:
envid: S113792939
Year: 2012
GEPAID: CAC002711508
Contact: GREG TAYLOR
Telephone: 6509061277
Mailing Name: Not reported
Mailing Address: 446 CHATHAM RD
Mailing City,St,Zip: BURLINGAME, CA 940102712
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

Q436
SSW
1/4-1/2
0.328 mi.
1731 ft.

KIIKO, OHATA
1537 RALSTON AVE
BURLINGAME, CA 94010

Site 3 of 4 in cluster Q

HAZNET **S118206458**
N/A

Relative:
Higher

Actual:
49 ft.

HAZNET:

envid:	S118206458
Year:	2014
GEPAID:	CAC002766354
Contact:	KIIKO, OHATA
Telephone:	6503763232
Mailing Name:	Not reported
Mailing Address:	1537 RALSTON AVE
Mailing City,St,Zip:	BURLINGAME, CA 940105109
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

M437
NW
1/4-1/2
0.330 mi.
1745 ft.

K & B INVESTMENTS
755 CALIFORNIA ST
BURLINGAME, CA 94010

Site 39 of 39 in cluster M

HAZNET **S112934171**
N/A

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S112934171
Year:	2003
GEPAID:	CAC002572272
Contact:	KENNETH HALL
Telephone:	7608063436
Mailing Name:	Not reported
Mailing Address:	3529 CANNON RD UNIT2B-134
Mailing City,St,Zip:	OCEANSIDE, CA 92056
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

O438 **TOP TOYO LOTUS INC** **HAZNET** **S112897901**
WSW **530 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.334 mi.
1761 ft. **Site 4 of 4 in cluster O**

Relative:
Higher

Actual:
41 ft.

HAZNET:

envid:	S112897901
Year:	1999
GEPAID:	CAC002111728
Contact:	DU SHIYUEN
Telephone:	6504016928
Mailing Name:	Not reported
Mailing Address:	181 SECOND AVE STE 568
Mailing City,St,Zip:	SAN MATEO, CA 944010000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.2642
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

U439 **NELSON NG** **HAZNET** **S112979643**
North **730 OAK GROVE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.334 mi.
1766 ft. **Site 2 of 9 in cluster U**

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S112979643
Year:	2009
GEPAID:	CAC002645088
Contact:	NELSON NG
Telephone:	6508687710
Mailing Name:	Not reported
Mailing Address:	730 OAK GROVE AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.01
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

S440 **PUTNAM GM** **HAZNET** **S118232747**
ESE **998 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.334 mi.
1766 ft. **Site 8 of 47 in cluster S**

Relative:
Higher

Actual:
35 ft.

HAZNET:

envid:	S118232747
Year:	2014
GEPAID:	CAL000378374
Contact:	BEN POMEROY
Telephone:	6503429500
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110000
Gen County:	San Mateo
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.08265
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

W441 **JIM SHANNON** **HAZNET** **S117298627**
WNW **744 NEUCHATEL AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.337 mi.
1781 ft. **Site 1 of 31 in cluster W**

Relative:
Lower

Actual:
19 ft.

HAZNET:

envid:	S117298627
Year:	2013
GEPAID:	CAC002740457
Contact:	JIM SHANNON
Telephone:	6507596875
Mailing Name:	Not reported
Mailing Address:	744 NEUCHATEL AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103707
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

U442 **DOUG DIEHL** **HAZNET** **S118212614**
North **705 WINCHESTER DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.342 mi.
1807 ft. **Site 3 of 9 in cluster U**

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S118212614
Year:	2014
GEPAID:	CAC002773869
Contact:	DOUG DIEHL
Telephone:	6503472600
Mailing Name:	Not reported
Mailing Address:	705 WINCHESTER DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

R443 **MAJEL GILMARTIN** **HAZNET** **S112868497**
SE **48 PARK RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.345 mi.
1819 ft. **Site 5 of 6 in cluster R**

Relative:
Higher

Actual:
41 ft.

HAZNET:

envid:	S112868497
Year:	1996
GEPAID:	CAC001137400
Contact:	MAJEL GILMARTIN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	48 PARK RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.2642
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

S444 **BURLINGAME FORD** **San Mateo Co. BI** **S113756628**
ESE **101 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.346 mi.
1825 ft. **Site 9 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018026
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011844
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018026
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004648
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018026
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0025602
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

S445 **PUTNAM AUTOMOTIVE GROUP, NISSAN** **San Mateo Co. BI** **S113757534**
ESE **101 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.346 mi.
1825 ft. **Site 10 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0055469
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0076479
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0055469
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076478
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0026642
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0038701
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0026642
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0038700

PUTNAM AUTOMOTIVE GROUP, NISSAN (Continued) **S113757534**

Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: INACTIVE

S446
ESE
1/4-1/2
0.346 mi.
1825 ft.

Site 11 of 47 in cluster S

Relative:
Higher

Actual:
34 ft.

BURLINGAME FORD
101 CALIFORNIA DRIVE
BURLINGAME, CA 94010

Database(s): RCRA-SQG, SWEEPS UST, HIST UST, CA FID UST, FINDS, EMI, HAZNET, ECHO

EDR ID Number: 1000285908
EPA ID Number: CAD098513096

RCRA-SQG:
Date form received by agency: 06/03/1986
Facility name: BURLINGAME FORD
Facility address: 101 CALIFORNIA DRIVE
BURLINGAME, CA 94010
EPA ID: CAD098513096
Mailing address: CALIFORNIA DRIVE
BURLINGAME, CA 94010
Contact: ENVIRONMENTAL MANAGER
Contact address: 101 CALIFORNIA DRIVE
BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 344-1111
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: GERRY FALK
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

BURLINGAME FORD (Continued) **1000285908**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

SWEEPS UST:
Status: Active
Comp Number: 665014
Number: 1
Board Of Equalization: 44-025370
Referral Date: 01-28-94
Action Date: 01-28-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-665014-000001
Tank Status: A
Capacity: 1
Active Date: 08-15-89
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 2

Status: Active
Comp Number: 665014
Number: 1
Board Of Equalization: 44-025370
Referral Date: 01-28-94
Action Date: 01-28-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-665014-000005
Tank Status: A
Capacity: 300
Active Date: 08-15-89
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

HIST UST:
File Number: 0002BEE3
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BEE3.pdf
Region: STATE
Facility ID: 00000009930

BURLINGAME FORD (Continued) **1000285908**

Facility Type:	Other
Other Type:	Not reported
Contact Name:	RON CALAVANO
Telephone:	4153441111
Owner Name:	GERRY FALK
Owner Address:	101 CALIFORNIA DRIVE
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0002
Tank Num:	001
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	002
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	41002676
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	2900 VALLEJO ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

FINDS:

Registry ID: 110001181480

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

RCRAInfo is a national information system that supports the Resource

BURLINGAME FORD (Continued) **1000285908**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

EMI:

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

BURLINGAME FORD (Continued) **1000285908**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	5036
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	5036

BURLINGAME FORD (Continued) **1000285908**

Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HAZNET:

envid:	1000285908
Year:	2002
GEPAID:	CAD098513096
Contact:	DONALD REID
Telephone:	4153441111
Mailing Name:	Not reported
Mailing Address:	PO BOX 311
Mailing City,St,Zip:	BURLINGAME, CA 940104322
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Oil/water separation sludge
Disposal Method:	Transfer Station
Tons:	1.39
Cat Decode:	Oil/water separation sludge
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	1000285908
Year:	2001
GEPAID:	CAD098513096
Contact:	DONALD REID
Telephone:	4153441111
Mailing Name:	Not reported
Mailing Address:	PO BOX 311
Mailing City,St,Zip:	BURLINGAME, CA 940104322
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Disposal, Other
Tons:	0.06
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Disposal, Other
Facility County:	San Mateo

envid:	1000285908
Year:	2001
GEPAID:	CAD098513096
Contact:	DONALD REID
Telephone:	4153441111
Mailing Name:	Not reported
Mailing Address:	PO BOX 311

BURLINGAME FORD (Continued) **1000285908**

Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Recycler
Tons: 0.61
Cat Decode: Unspecified solvent mixture
Method Decode: Recycler
Facility County: San Mateo

envid: 1000285908
Year: 2001
GEPAID: CAD098513096
Contact: DONALD REID
Telephone: 4153441111
Mailing Name: Not reported
Mailing Address: PO BOX 311
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Not reported
Tons: 0.07
Cat Decode: Unspecified solvent mixture
Method Decode: Not reported
Facility County: San Mateo

envid: 1000285908
Year: 2001
GEPAID: CAD098513096
Contact: DONALD REID
Telephone: 4153441111
Mailing Name: Not reported
Mailing Address: PO BOX 311
Mailing City,St,Zip: BURLINGAME, CA 940104322
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Transfer Station
Tons: 0.2
Cat Decode: Waste oil and mixed oil
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
33 additional CA_HAZNET: record(s) in the EDR Site Report.

ECHO:
Envid: 1000285908
Registry ID: 110001181480
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110001181480

S447 **SAREMI PROPERTY** **RGA LUST** **S114683096**
ESE **100 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.347 mi.
1833 ft. **Site 12 of 47 in cluster S**

Relative: **Higher**

Actual: **34 ft.**

RGA LUST:

2002	SAREMI PROPERTY	100 CALIFORNIA DR
2001	SAREMI PROPERTY	100 CALIFORNIA DR
2000	SAREMI PROPERTY	100 CALIFORNIA DR
1998	SAREMI PROPERTY	100 CALIFORNIA DR
1997	SAREMI PROPERTY	100 CALIFORNIA DR
1996	SAREMI PROPERTY	100 CALIFORNIA DR

S448 **GMAC** **HAZNET** **S112841198**
ESE **100 CALIFORNIA BLVD** **N/A**
1/4-1/2 **BURLINGAME, CA 95001**
0.347 mi.
1833 ft. **Site 13 of 47 in cluster S**

Relative: **Higher**

Actual: **34 ft.**

HAZNET:

envid:	S112841198
Year:	1995
GEPAID:	CAC000732784
Contact:	RICHARD ESTRELLA
Telephone:	4087735302
Mailing Name:	Not reported
Mailing Address:	333 WEST EL CAMINO REAL
Mailing City,St,Zip:	SUNNYVALE, CA 940870000
Gen County:	Not reported
TSD EPA ID:	CAT080011059
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	1.6054
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

S449 **ARATA HONDA** **RGA LUST** **S114572610**
ESE **100 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.347 mi.
1833 ft. **Site 14 of 47 in cluster S**

Relative: **Higher**

Actual: **34 ft.**

RGA LUST:

1995	ARATA HONDA	100 CALIFORNIA DR
1994	ARATA HONDA	100 CALIFORNIA DR
1993	ARATA HONDA	100 CALIFORNIA DR

S450 **HOBBY STORE** **San Mateo Co. BI** **S113755477**
ESE **100 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 15 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0009390
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022761
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

S451 **SAREMI PROPERTY** **LUST** **S102436498**
ESE **100 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 16 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660068
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

S452 **PUTNAM TOYOTA** **San Mateo Co. BI** **S113755987**
ESE **100 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 17 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0014152
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0030415
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0014152
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0030416
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

S453 **HOBBY STORE** **SWEEPS UST** **S101593656**
ESE **100 CALIFORNIA DR** **CA FID UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 18 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660030
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660030-000001
Tank Status:	Not reported
Capacity:	750
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	3

Status:	Not reported
Comp Number:	660030
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660030-000002
Tank Status:	Not reported
Capacity:	750
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660030
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660030-000003
Tank Status:	Not reported
Capacity:	250
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

HOBBY STORE (Continued) **S101593656**

CA FID UST:

Facility ID:	41000061
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	198 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

S454 **SAREMI PROPERTY** **LUST** **S103892173**
ESE **100 CALIFORNIA** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 19 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

LUST:

Region:	STATE
Global Id:	T0608100232
Latitude:	37.5779635
Longitude:	-122.3414611
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/27/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0244
LOC Case Number:	660068
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100232
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100232
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN

SAREMI PROPERTY (Continued) **S103892173**

Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100232
Status: Completed - Case Closed
Status Date: 12/27/2001

Global Id: T0608100232
Status: Open - Case Begin Date
Status Date: 02/08/1993

Regulatory Activities:
Global Id: T0608100232
Action Type: ENFORCEMENT
Date: 02/08/1993
Action: Notice of Responsibility - #1

Global Id: T0608100232
Action Type: Other
Date: 02/18/1993
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660068
Facility Status: 9- Case Closed
Global ID: T0608100232
APN Number: 029233080
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0244

S455 **PUTNAM TOYOTA** **RCRA-SQG** **1001217536**
ESE **100 CALIFORNIA DR** **FINDS** **CAR000036483**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.347 mi.
1833 ft. **Site 20 of 47 in cluster S**

Relative: Higher

Actual: 34 ft.

RCRA-SQG:
Date form received by agency: 02/16/1998
Facility name: PUTNAM TOYOTA
Facility address: 100 CALIFORNIA DR
BURLINGAME, CA 94010
EPA ID: CAR000036483
Contact: PAT OBRIEN
Contact address: 100 CALIFORNIA DR

PUTNAM TOYOTA (Continued) **1001217536**

BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 340-6900
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: JOE PUTNAM
Owner/operator address: 50 CALIFORNIA DR
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (415) 347-4800
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110002921036

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

PUTNAM TOYOTA (Continued) **1001217536**

corrective action activities required under RCRA.

ECHO:
Envid: 1001217536
Registry ID: 110002921036
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002921036

S456 **SAREMI PROPERTY** **RGA LUST** **S114683097**
ESE **100 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.347 mi.
1833 ft. **Site 21 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2012	SAREMI PROPERTY	100 CALIFORNIA
2011	SAREMI PROPERTY	100 CALIFORNIA
2010	SAREMI PROPERTY	100 CALIFORNIA
2009	SAREMI PROPERTY	100 CALIFORNIA
2008	SAREMI PROPERTY	100 CALIFORNIA
2007	SAREMI PROPERTY	100 CALIFORNIA
2006	SAREMI PROPERTY	100 CALIFORNIA
2005	SAREMI PROPERTY	100 CALIFORNIA
2003	SAREMI PROPERTY	100 CALIFORNIA

S457 **GMAC** **HAZNET** **S112868299**
ESE **100 CALIFORNIA BLVD** **N/A**
1/4-1/2 **BURLINGAME, CA 95001**
0.347 mi.
1833 ft. **Site 22 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

HAZNET:

envid:	S112868299
Year:	1996
GEPAID:	CAC001135216
Contact:	RICHARD ESTRELLA
Telephone:	4087735302
Mailing Name:	Not reported
Mailing Address:	333 WEST EL CAMINO REAL
Mailing City,St,Zip:	SUNNYVALE, CA 940870000
Gen County:	Not reported
TSD EPA ID:	CAT080011059
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Disposal, Other
Tons:	.2710
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Disposal, Other
Facility County:	San Mateo

S458 **PUTNAM AUTOMOTIVE** **EMI** **S106837805**
ESE **100 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 23 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

EMI:

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.009
Reactive Organic Gases Tons/Yr:	0.0075303
Carbon Monoxide Emissions Tons/Yr:	0.025
NOX - Oxides of Nitrogen Tons/Yr:	0.117
SOX - Oxides of Sulphur Tons/Yr:	0.002
Particulate Matter Tons/Yr:	0.008
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.007808

Year:	2005

PUTNAM AUTOMOTIVE (Continued) **S106837805**

County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.009
Reactive Organic Gases Tons/Yr:	.0075303
Carbon Monoxide Emissions Tons/Yr:	.025
NOX - Oxides of Nitrogen Tons/Yr:	.117
SOX - Oxides of Sulphur Tons/Yr:	.002
Particulate Matter Tons/Yr:	.008
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.007808

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD

PUTNAM AUTOMOTIVE (Continued) **S106837805**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	.001
NOX - Oxides of Nitrogen Tons/Yr:	.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.002
Reactive Organic Gases Tons/Yr:	0.0016734
Carbon Monoxide Emissions Tons/Yr:	6.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	2.8000000000000001E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00204918032786885
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.002

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14912
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.002
Reactive Organic Gases Tons/Yr:	0.0016734
Carbon Monoxide Emissions Tons/Yr:	0.006
NOX - Oxides of Nitrogen Tons/Yr:	0.028

PUTNAM AUTOMOTIVE (Continued) **S106837805**

SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

U459 **RICK CORY** **HAZNET** **S113789953**
NNW **730 LAUREL AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.347 mi.
1833 ft. **Site 4 of 9 in cluster U**

Relative:
Lower

Actual:
19 ft.

HAZNET:

envid:	S113789953
Year:	2012
GEPAID:	CAC002707471
Contact:	RICK CORY
Telephone:	9254130074
Mailing Name:	Not reported
Mailing Address:	730 LAUREL AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.1
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

P460 **EDR Hist Auto** **1015213751**
East **136 MYRTLE RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.348 mi.
1836 ft. **Site 13 of 16 in cluster P**

Relative:
Higher

Actual:
32 ft.

EDR Historical Auto Stations:

Name:	DEANS AUTO BODY
Year:	2010
Address:	136 MYRTLE RD
Name:	DEANS AUTO BODY & PAINTING
Year:	2011
Address:	136 MYRTLE RD
Name:	DEANS AUTO BODY & PAINTING
Year:	2012
Address:	136 MYRTLE RD

P461 **EDR Hist Auto** **1015206898**
East **132 MYRTLE RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1853 ft. **Site 14 of 16 in cluster P**

Relative:
Higher

Actual:
32 ft.

EDR Historical Auto Stations:

Name:	BURLINGAME AUTO CLINIC
Year:	1999
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2000
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2001
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2002
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2003
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2004
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2007
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2008
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2009
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2010
Address:	132 MYRTLE RD
Name:	BURLINGAME AUTO CLINIC
Year:	2011
Address:	132 MYRTLE RD

P462 **BURLINGAME AUTO CLINIC** **HAZNET** **S113037339**
East **132 MYRTLE RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1853 ft. **Site 15 of 16 in cluster P**

Relative:
Higher

Actual:
32 ft.

HAZNET:

envid:	S113037339
Year:	2001
GEPAID:	CAL000039370
Contact:	DONALD MC GRATH /OWNER
Telephone:	4153472886
Mailing Name:	Not reported
Mailing Address:	132 MYRTLE RD
Mailing City,St,Zip:	BURLINGAME, CA 940103031
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Recycler
Tons:	0.12
Cat Decode:	Unspecified solvent mixture
Method Decode:	Recycler
Facility County:	San Mateo

P463 **BURLINGAME AUTO CLINIC** **San Mateo Co. BI** **S113755339**
East **132 MYRTLE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1853 ft. **Site 16 of 16 in cluster P**

Relative:
Higher

Actual:
32 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0006538
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011884
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0006538
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004725
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

W464 **NICKS HONDA** **LUST** **S109280319**
NW **775 CALIFORNIA DRIVE** **SLIC** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1854 ft. **Site 2 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	669109
Facility Status:	9- Case Closed
Global ID:	T10000004181
APN Number:	029053430

NICKS HONDA (Continued) **S109280319**

Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SLIC:
Region: STATE
Facility Status: Completed - Case Closed
Status Date: 08/21/2013
Global Id: T10000004181
Lead Agency: SAN MATEO COUNTY LOP
Lead Agency Case Number: 669109
Latitude: 37.5825159332734
Longitude: -122.353008985519
Case Type: Cleanup Program Site
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
File Location: Not reported
Potential Media Affected: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Site Opened 7/18/2012

Click here to access the California GeoTracker records for this facility:

W465 **NICKS HONDA / ACURA SERVICE** **San Mateo Co. BI** **S113758476**
NW **775 CALIFORNIA DR** **HAZNET** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1854 ft. **Site 3 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0038835
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0055174
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0038835
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0055173
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

HAZNET:
envid: S113758476
Year: 2013
GEPAID: CAL000321397
Contact: PHILIP NICHOLAS THEROUX
Telephone: 6503756464
Mailing Name: Not reported
Mailing Address: 775 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAT080013352
TSD County: Los Angeles
Waste Category: Not reported

NICKS HONDA / ACURA SERVICE (Continued) **S113758476**

Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.06672
Cat Decode: Not reported
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: Not reported

W466 **EDR Hist Auto** **1015630948**
NW **775 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.351 mi.
1854 ft. **Site 4 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

EDR Historical Auto Stations:
Name: ANY CAR SERVICES INC
Year: 2008
Address: 775 CALIFORNIA DR

Name: NICKS WE SERVICE HONDA & ACURA AUTOM
Year: 2009
Address: 775 CALIFORNIA DR

S467 **BURLINGAME FORD** **LUST** **S104493496**
ESE **99 CALIFORNIA** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.352 mi.
1859 ft. **Site 24 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

LUST:
Region: STATE
Global Id: T0608100090
Latitude: 37.5779133
Longitude: -122.3414422
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 05/15/1995
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0095
LOC Case Number: 660043
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100090
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported

BURLINGAME FORD (Continued) **S104493496**

Phone Number: Not reported

Global Id: T0608100090
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100090
Status: Completed - Case Closed
Status Date: 05/15/1995

Global Id: T0608100090
Status: Open - Case Begin Date
Status Date: 06/01/1990

Regulatory Activities:
Global Id: T0608100090
Action Type: Other
Date: 06/01/1990
Action: Leak Discovery

Global Id: T0608100090
Action Type: Other
Date: 06/01/1990
Action: Leak Reported

Global Id: T0608100090
Action Type: ENFORCEMENT
Date: 05/29/1991
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660043
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:

BURLINGAME FORD (Continued) **S104493496**

Region: SAN MATEO
Facility ID: 660043
Facility Status: 9- Case Closed
Global ID: T0608100090
APN Number: 029242040
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0095

S468 **BURLINGAME FORD** **RGA LUST** **S114588301**
ESE **99 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.352 mi.
1859 ft. **Site 25 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2012	BURLINGAME FORD	99 CALIFORNIA
2011	BURLINGAME FORD	99 CALIFORNIA
2010	BURLINGAME FORD	99 CALIFORNIA
2009	BURLINGAME FORD	99 CALIFORNIA
2008	BURLINGAME FORD	99 CALIFORNIA
2007	BURLINGAME FORD	99 CALIFORNIA
2006	BURLINGAME FORD	99 CALIFORNIA
2005	BURLINGAME FORD	99 CALIFORNIA
2003	BURLINGAME FORD	99 CALIFORNIA

S469 **BURLINGAME FORD** **RGA LUST** **S114588300**
ESE **99 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.352 mi.
1859 ft. **Site 26 of 47 in cluster S**

Relative:
Higher

Actual:
34 ft.

RGA LUST:

2002	BURLINGAME FORD	99 CALIFORNIA DR
2001	BURLINGAME FORD	99 CALIFORNIA DR
2000	BURLINGAME FORD	99 CALIFORNIA DR
1998	BURLINGAME FORD	99 CALIFORNIA DR
1997	BURLINGAME FORD	99 CALIFORNIA DR
1996	BURLINGAME FORD	99 CALIFORNIA DR
1995	BURLINGAME FORD	99 CALIFORNIA DR
1994	BURLINGAME FORD	99 CALIFORNIA DR
1993	BURLINGAME FORD	99 CALIFORNIA DR
1992	BURLINGAME FORD	99 CALIFORNIA DR

W470 **CARBARR DBA SHAFFERS AUTO SVC** **HAZNET** **S113090500**
NW **777 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.353 mi.
1866 ft. **Site 5 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S113090500
Year:	2007
GEPAID:	CAL000172183
Contact:	STEVE BARRESE/PRES
Telephone:	6503440302
Mailing Name:	Not reported
Mailing Address:	777 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.22
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

envid:	S113090500
Year:	2007
GEPAID:	CAL000172183
Contact:	STEVE BARRESE/PRES
Telephone:	6503440302
Mailing Name:	Not reported
Mailing Address:	777 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc)
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.22
Cat Decode:	Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc)
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

W471 **SHAFFER'S TIRE CENTER** **RGA LUST** **S114685490**
NW **777 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.353 mi.
1866 ft. **Site 6 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

RGA LUST:

2012	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2011	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2010	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2009	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2008	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2007	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2006	SHAFFER'S TIRE CENTER	777 CALIFORNIA

SHAFFER'S TIRE CENTER (Continued) **S114685490**

2005	SHAFFER'S TIRE CENTER	777 CALIFORNIA
2003	SHAFFER'S TIRE CENTER	777 CALIFORNIA

W472
NW
1/4-1/2
0.353 mi.
1866 ft.

SHAFFER'S TIRE CENTER
777 CALIFORNIA DR
BURLINGAME, CA

Site 7 of 31 in cluster W

Relative:
Lower

Actual:
18 ft.

RGA LUST **S114685489**
N/A

RGA LUST:

2002	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
2001	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
2000	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1998	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1997	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1996	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1995	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1994	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1993	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR
1992	SHAFFER'S TIRE CENTER	777 CALIFORNIA DR

W473
NW
1/4-1/2
0.353 mi.
1866 ft.

777 CALIFORNIA DR
BURLINGAME, CA 94010

Site 8 of 31 in cluster W

Relative:
Lower

Actual:
18 ft.

EDR Hist Auto **1015631291**
N/A

EDR Historical Auto Stations:

Name:	SHAFFERS TIRE & AUTO SERVICE
Year:	1999
Address:	777 CALIFORNIA DR
Name:	SHAFFERS TIRE & AUTO SERVICE
Year:	2000
Address:	777 CALIFORNIA DR
Name:	SHAFFERS TIRE & AUTO SERVICE
Year:	2002
Address:	777 CALIFORNIA DR
Name:	SHAFFERS AUTO SERVICE CTR
Year:	2003
Address:	777 CALIFORNIA DR
Name:	SHAFFERS TIRE & AUTO SERVICE
Year:	2004
Address:	777 CALIFORNIA DR
Name:	SHAFFERS TIRE & AUTO SERVICE
Year:	2009
Address:	777 CALIFORNIA DR
Name:	SHAFFERS TIRE & AUTO SVC
Year:	2010
Address:	777 CALIFORNIA DR

W474
NW
1/4-1/2
0.353 mi.
1866 ft.

SHAFFERS AUTO SVC
777 CALIFORNIA DR
BURLINGAME, CA 94010

Site 9 of 31 in cluster W

HAZNET **S113022766**
N/A

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S113022766
Year:	1999
GEPAID:	CAL000003169
Contact:	CARBARR INC DBA SHAFFER'S AUTO
Telephone:	6503440302
Mailing Name:	Not reported
Mailing Address:	777 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.2293
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113022766
Year:	1998
GEPAID:	CAL000003169
Contact:	CARBARR INC DBA SHAFFER'S AUTO
Telephone:	6503440302
Mailing Name:	Not reported
Mailing Address:	777 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CAD059494310
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Disposal, Other
Tons:	.2293
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Disposal, Other
Facility County:	San Mateo

envid:	S113022766
Year:	1994
GEPAID:	CAL000003169
Contact:	CARBARR INC DBA SHAFFER'S AUTO
Telephone:	6503440302
Mailing Name:	Not reported
Mailing Address:	777 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940103703
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.2085
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station

SHAFFERS AUTO SVC (Continued) **S113022766**

Facility County: San Mateo

envid: S113022766
Year: 1993
GEPAID: CAL000003169
Contact: CARBARR INC DBA SHAFFER'S AUTO
Telephone: 6503440302
Mailing Name: Not reported
Mailing Address: 777 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103703
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Not reported
Tons: 0.29189999999
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Not reported
Facility County: San Mateo

envid: S113022766
Year: 1993
GEPAID: CAL000003169
Contact: CARBARR INC DBA SHAFFER'S AUTO
Telephone: 6503440302
Mailing Name: Not reported
Mailing Address: 777 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940103703
Gen County: Not reported
TSD EPA ID: CAD980887418
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Transfer Station
Tons: 0
Cat Decode: Not reported
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

W475 **777 TO 783 CALIFORNIA DRIVE** **HAZNET** **S113789256**
NW **777 CALIFORNIA DR # 783** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.353 mi.
1866 ft. **Site 10 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

HAZNET:
envid: S113789256
Year: 2012
GEPAID: CAC002706341
Contact: JAMES PROFFITT
Telephone: 8314269023
Mailing Name: Not reported
Mailing Address: 1995 SMITH GRADE
Mailing City,St,Zip: SANTA CRUZ, CA 95060
Gen County: San Mateo
TSD EPA ID: CAL000190816

777 TO 783 CALIFORNIA DRIVE (Continued) **S113789256**

TSD County: Stanislaus
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 3.61
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

W476 **SHAFFERS AUTO SERVICE CTR** **San Mateo Co. BI** **S113755791**
NW **777 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.353 mi.
1866 ft. **Site 11 of 31 in cluster W**

Relative: **Lower**
Actual: **18 ft.**

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0012292
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0024650
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0012292
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0024649
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0012292
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0026609
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

X477 **BO THORENFIELDT** **HAZNET** **S112957633**
West **1512 FLORIBUNDA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.357 mi.
1886 ft. **Site 1 of 13 in cluster X**

Relative: **Higher**
Actual: **36 ft.**

HAZNET:
envid: S112957633
Year: 2006
GEPAID: CAC002610438
Contact: SUSAN THORENFIELDT
Telephone: 6505589495
Mailing Name: Not reported
Mailing Address: 725 JACARANDA CIR
Mailing City,St,Zip: HILLSBOROUGH, CA 940106556
Gen County: Not reported
TSD EPA ID: CAD982042475
TSD County: Not reported

BO THORENFIELDT (Continued) **S112957633**

Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	Not reported
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

W478 **LARRY SPECKMAN** **HAZNET** **S112930613**
WNW **743 CROSSWAY RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.359 mi.
1898 ft. **Site 12 of 31 in cluster W**

Relative:
Lower

Actual:
24 ft.

HAZNET:

envid:	S112930613
Year:	2003
GEPAID:	CAC002566502
Contact:	LARRY SPECKMAN
Telephone:	6503751917
Mailing Name:	Not reported
Mailing Address:	743 CROSSWAY RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	1.39
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112930613
Year:	2003
GEPAID:	CAC002566502
Contact:	LARRY SPECKMAN
Telephone:	6503751917
Mailing Name:	Not reported
Mailing Address:	743 CROSSWAY RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	0.55
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

W479 **GRAYS PAINT** **San Mateo Co. BI** **S113758713**
NW **783 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.359 mi.
1898 ft. **Site 13 of 31 in cluster W**

Relative: **Lower**

Actual: **18 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045272
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0058651
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

V480 **JOHN TREADWELL** **HAZNET** **S112989080**
South **1540 NEWLANDS AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.366 mi.
1933 ft. **Site 2 of 3 in cluster V**

Relative: **Higher**

Actual: **50 ft.**

HAZNET:

envid:	S112989080
Year:	2011
GEPAID:	CAC002670332
Contact:	JOHN TREADWELL
Telephone:	6509359529
Mailing Name:	Not reported
Mailing Address:	1540 NEWLANDS AVE
Mailing City,St,Zip:	BURLINGAME, CA 940105243
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

U481 **1X ARTHUR W.BROWN** **HAZNET** **S112847694**
NNW **746 LAUREL AVE.** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.370 mi.
1955 ft. **Site 5 of 9 in cluster U**

Relative: **Lower**

Actual: **18 ft.**

HAZNET:

envid:	S112847694
Year:	1993
GEPAID:	CAC000844904
Contact:	ARTHUR W.BROWN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	746 LAUREL AVE.
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD004771168

1X ARTHUR W.BROWN (Continued) **S112847694**

TSD County:	Not reported
Waste Category:	Empty containers less than 30 gallons
Disposal Method:	Recycler
Tons:	2.50000000000
Cat Decode:	Empty containers less than 30 gallons
Method Decode:	Recycler
Facility County:	San Mateo
envid:	S112847694
Year:	1993
GEPAID:	CAC000844904
Contact:	ARTHUR W.BROWN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	746 LAUREL AVE.
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD004771168
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	0.25
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

U482 **ARTHUR BROWN** **SWEEPS UST** **S106922882**
NNW **746 LAUREL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.370 mi.
1955 ft. **Site 6 of 9 in cluster U**

Relative:
Lower

Actual:
18 ft.

SWEEPS UST:

Status:	Active
Comp Number:	660099
Number:	2
Board Of Equalization:	Not reported
Referral Date:	10-19-93
Action Date:	10-19-93
Created Date:	07-21-93
Owner Tank Id:	UNK
SWRCB Tank Id:	41-000-660099-000001
Tank Status:	A
Capacity:	500
Active Date:	07-21-93
Tank Use:	M.V. FUEL
STG:	P
Content:	CONCRETE
Number Of Tanks:	1

U483 **RESIDENCE** **San Mateo Co. BI** **S113756884**
NNW **746 LAUREL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.370 mi.
1955 ft. **Site 7 of 9 in cluster U**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0023064
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0026187
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

W484 **SHAFFER'S TIRE CENTER** **LUST** **S100873976**
NW **777 CALIFORNIA** **SLIC** **N/A**
1/4-1/2 **BURLINGAME, CA 94010** **HIST CORTESE**
0.370 mi.
1956 ft. **Site 14 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

LUST:

Region:	STATE
Global Id:	T0608100458
Latitude:	37.582736
Longitude:	-122.35305
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/14/1992
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0482
LOC Case Number:	660034
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100458
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100458
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

SHAFFER'S TIRE CENTER (Continued) **S100873976**

Status History:
Global Id: T0608100458
Status: Completed - Case Closed
Status Date: 01/14/1992

Global Id: T0608100458
Status: Open - Case Begin Date
Status Date: 01/08/1990

Regulatory Activities:
Global Id: T0608100458
Action Type: Other
Date: 01/08/1990
Action: Leak Discovery

Global Id: T0608100458
Action Type: Other
Date: 01/08/1990
Action: Leak Reported

Global Id: T0608100458
Action Type: ENFORCEMENT
Date: 01/08/1990
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 669108
Facility Status: 9- Case Closed
Global ID: T10000004180
APN Number: 029053430
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

Region: SAN MATEO
Facility ID: 660034
Facility Status: 9- Case Closed
Global ID: T0608100458
APN Number: 029053430
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SLIC:
Region: STATE
Facility Status: Completed - Case Closed
Status Date: 08/21/2013
Global Id: T10000004180
Lead Agency: SAN MATEO COUNTY LOP
Lead Agency Case Number: 669108
Latitude: 37.5827795054363
Longitude: -122.352998256683
Case Type: Cleanup Program Site
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP

SHAFFER'S TIRE CENTER (Continued) **S100873976**

RB Case Number: Not reported
File Location: Not reported
Potential Media Affected: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Site opened 7/18/2012

Click here to access the California GeoTracker records for this facility:

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0482

W485 **SHAEFFER'S TIRE CENTER** **SWEEPS UST** **S101593852**
NW **777 CALIFORNIA DR** **CA FID UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94019**
0.370 mi.
1956 ft. **Site 15 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

SWEEPS UST:
Status: Active
Comp Number: 2540
Number: 9
Board Of Equalization: Not reported
Referral Date: 02-02-94
Action Date: 02-02-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41001213
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4155931493
Mail To: Not reported
Mailing Address: 400 DAVEY GLEN RD
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94019
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

W486 **SHAFFER'S TIRE CENTER** **LUST** **S104493502**
NW **777 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.370 mi.
1956 ft. **Site 16 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660034
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

Y487 **KAVANAGH ENGINEERING** **HAZNET** **S113066067**
NW **708 CAROLAN AVENUE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.371 mi.
1957 ft. **Site 1 of 3 in cluster Y**

Relative:
Lower

Actual:
17 ft.

HAZNET:

envid:	S113066067
Year:	2002
GEPAID:	CAL000115838
Contact:	CHARLES KAVANAGH
Telephone:	6505791944
Mailing Name:	Not reported
Mailing Address:	708 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	NVR000043927
TSD County:	Not reported
Waste Category:	Photochemicals/photoprocessing waste
Disposal Method:	Not reported
Tons:	0.01
Cat Decode:	Photochemicals/photoprocessing waste
Method Decode:	Not reported
Facility County:	San Mateo

envid:	S113066067
Year:	1998
GEPAID:	CAL000115838
Contact:	CHARLES L KAVANAGH
Telephone:	6505791944
Mailing Name:	Not reported
Mailing Address:	708 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	NVD981639826
TSD County:	Not reported
Waste Category:	Not reported

KAVANAGH ENGINEERING (Continued) **S113066067**

Disposal Method: Invalid Code
Tons: .0000
Cat Decode: Not reported
Method Decode: Invalid Code
Facility County: San Mateo

envid: S113066067
Year: 1998
GEPAID: CAL000115838
Contact: CHARLES L KAVANAGH
Telephone: 6505791944
Mailing Name: Not reported
Mailing Address: 708 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: NVD981639826
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .0166
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113066067
Year: 1997
GEPAID: CAL000115838
Contact: CHARLES L KAVANAGH
Telephone: 6505791944
Mailing Name: Not reported
Mailing Address: 708 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: NVD981639826
TSD County: Not reported
Waste Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Tons: .0250
Cat Decode: Photochemicals/photoprocessing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113066067
Year: 1997
GEPAID: CAL000115838
Contact: CHARLES L KAVANAGH
Telephone: 6505791944
Mailing Name: Not reported
Mailing Address: 708 CAROLAN AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: NVD981639826
TSD County: Not reported
Waste Category: Not reported
Disposal Method: Invalid Code
Tons: .0000
Cat Decode: Not reported

KAVANAGH ENGINEERING (Continued) **S113066067**

Method Decode: Invalid Code
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

Q488 **MARION SPADONI** **HAZNET** **S113781960**
SSW **1557 RALSTON AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.371 mi.
1960 ft. **Site 4 of 4 in cluster Q**

Relative:
Higher

Actual:
54 ft.

HAZNET:
envid: S113781960
Year: 2012
GEPAID: CAC002696329
Contact: MARION SPADONI
Telephone: 6503437777
Mailing Name: Not reported
Mailing Address: 1557 RALSTON AVE
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

U489 **MICHAEL LUTZ** **HAZNET** **S113779745**
North **719 WINCHESTER DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.372 mi.
1962 ft. **Site 8 of 9 in cluster U**

Relative:
Lower

Actual:
17 ft.

HAZNET:
envid: S113779745
Year: 2012
GEPAID: CAC002693662
Contact: MICHAEL LUTZ
Telephone: 6503426572
Mailing Name: Not reported
Mailing Address: 719 WINCHESTER DR
Mailing City,St,Zip: BURLINGAME, CA 940102738
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported

MICHAEL LUTZ (Continued) **S113779745**

Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

S490 **EDR Hist Auto** **1015675042**
ESE **920 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.373 mi.
1967 ft. **Site 27 of 47 in cluster S**

Relative:
Higher

Actual:
32 ft.

EDR Historical Auto Stations:

Name: HOWER AUTO REPAIR
Year: 1999
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2000
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2001
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2002
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2003
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2005
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2006
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2007
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2008
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2009
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2010
Address: 920 BAYSWATER AVE

Name: HOWER AUTO REPAIR
Year: 2011
Address: 920 BAYSWATER AVE

(Continued) **1015675042**

Name: HOWER AUTO REPAIR
Year: 2012
Address: 920 BAYSWATER AVE

S491 **HOWER AUTO REPAIR** **San Mateo Co. BI** **S113756623**
ESE **920 BAYSWATER** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.373 mi.
1967 ft. **Site 28 of 47 in cluster S**

Relative:
Higher

Actual:
32 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0018019
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011837
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0018019
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004698
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

S492 **HOWER AUTO REPAIR** **HAZNET** **S113024059**
ESE **920 BAYSWATER ST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.373 mi.
1967 ft. **Site 29 of 47 in cluster S**

Relative:
Higher

Actual:
32 ft.

HAZNET:
envid: S113024059
Year: 2004
GEPAID: CAL000006801
Contact: JOHN C HOWER OR JAMES D HOWER
Telephone: 6503448029
Mailing Name: Not reported
Mailing Address: 920 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.06
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113024059
Year: 2003
GEPAID: CAL000006801
Contact: JOHN C HOWER OR JAMES D HOWER
Telephone: 6503448029
Mailing Name: Not reported

HOWER AUTO REPAIR (Continued) **S113024059**

Mailing Address: 920 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.1
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113024059
Year: 2003
GEPAID: CAL000006801
Contact: JOHN C HOWER OR JAMES D HOWER
Telephone: 6503448029
Mailing Name: Not reported
Mailing Address: 920 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Oil/water separation sludge
Disposal Method: Transfer Station
Tons: 0.2
Cat Decode: Oil/water separation sludge
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113024059
Year: 2002
GEPAID: CAL000006801
Contact: JOHN C HOWER OR JAMES D HOWER
Telephone: 6503448029
Mailing Name: Not reported
Mailing Address: 920 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CA0000084517
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 0.02
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113024059
Year: 1995
GEPAID: CAL000006801
Contact: HOWER WALTER A
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 920 BAYSWATER AVE
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported

HOWER AUTO REPAIR (Continued) **S113024059**

TSD EPA ID: CAD093459485
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Transfer Station
Tons: .0332
Cat Decode: Unspecified solvent mixture
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

S493 **HOWER AUTO REPAIR INC** **HIST UST** **U001593920**
ESE **920 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.373 mi.
1967 ft. **Site 30 of 47 in cluster S**

Relative:
Higher

Actual:
32 ft.

HIST UST:
File Number: 0002C443
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C443.pdf
Region: STATE
Facility ID: 00000010367
Facility Type: Other
Other Type: AUTO REPAIR SHOP
Contact Name: OWNER
Telephone: 4153478029
Owner Name: WALTER A HOWER
Owner Address: 1124 CAMBRIDGE RD.
Owner City,St,Zip: BURLINGAME, CA 94010
Total Tanks: 0003

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00000200
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 002
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00000550
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: None

HOWER AUTO REPAIR INC (Continued) **U001593920**

Click here for Geo Tracker PDF:

S494 **MILE HIGH TRUCKING** **RCRA NonGen / NLR** **1000197022**
East **108 MYRTLE RD #4** **FINDS** **CAD981983299**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.373 mi.
1971 ft. **Site 31 of 47 in cluster S**

Relative:
Higher

Actual:
32 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/01/1987
Facility name:	MILE HIGH TRUCKING
Facility address:	108 MYRTLE RD #4 BURLINGAME, CA 94010
EPA ID:	CAD981983299
Mailing address:	108 MYRTLEE RD #FOURTH BURLINGAME, CA 94010
Contact:	ENVIRONMENTAL MANAGER
Contact address:	108 MYRTLE RD #FOURTH BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 344-1405
Contact email:	Not reported
EPA Region:	09
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	GARY A OGLE
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

MILE HIGH TRUCKING (Continued) **1000197022**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110005995110

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000197022
Registry ID: 110005995110
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110005995110

X495 **DAVID CUNNINGHAM** **HAZNET** **S117299791**
West **700 ACACIA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.375 mi.
1980 ft. **Site 2 of 13 in cluster X**

Relative:
Higher

Actual:
34 ft.

HAZNET:
envid: S117299791
Year: 2013
GEPAID: CAC002742119
Contact: DAVID CUNNINGHAM
Telephone: 4084609386
Mailing Name: Not reported
Mailing Address: 700 ACACIA AVE
Mailing City,St,Zip: BURLINGAME, CA 940103702
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: Not reported

W496
NW
1/4-1/2
0.376 mi.
1987 ft.

FIRE DEPARTMENT
799 CALIFORNIA DR.
BURLINGAME, CA 94010

Site 17 of 31 in cluster W

SWEEPS UST **S101593678**
CA FID UST **N/A**

Relative:
Lower

Actual:
18 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660097
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660097-000001
Tank Status:	Not reported
Capacity:	1500
Active Date:	Not reported
Tank Use:	OIL
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	1

CA FID UST:

Facility ID:	41000122
Regulated By:	UTNKI
Regulated ID:	CAD980814
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4153434545
Mail To:	Not reported
Mailing Address:	501 PRIMROSE
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

W497
NW
1/4-1/2
0.376 mi.
1987 ft.

BURLINGAME FIRE DEPT
799 CALIFORNIA DR
BURLINGAME, CA

Site 18 of 31 in cluster W

RGA LUST **S114588296**
N/A

Relative:
Lower

Actual:
18 ft.

RGA LUST:

2002	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
2001	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
2000	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1998	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1997	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1996	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1995	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1994	BURLINGAME FIRE DEPT	799 CALIFORNIA DR
1993	BURLINGAME FIRE DEPT	799 CALIFORNIA DR

W498 **CITY OF BURLINGAME** **EMI** **S107620539**
NW **799 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.376 mi.
1987 ft. **Site 19 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

EMI:

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.004
NOX - Oxides of Nitrogen Tons/Yr:	0.016
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000976

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.004
NOX - Oxides of Nitrogen Tons/Yr:	.016
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.000976

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2007

CITY OF BURLINGAME (Continued) **S107620539**

County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.003
NOX - Oxides of Nitrogen Tons/Yr:	.014
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.000976

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	8.3670000000000001E-4
Carbon Monoxide Emissions Tons/Yr:	3.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	0.014
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	9.7599999999999998E-4

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD

CITY OF BURLINGAME (Continued) **S107620539**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.005
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	14463
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.005

CITY OF BURLINGAME (Continued) **S107620539**

SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

W499 **FIRE STATION 1** **HIST UST** **U001593912**
NW **799 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.376 mi.
1987 ft. **Site 20 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

HIST UST:

File Number:	0002BD45
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BD45.pdf
Region:	STATE
Facility ID:	00000024311
Facility Type:	Other
Other Type:	FIRE STATION
Contact Name:	O.F. FRICKE, CHIEF
Telephone:	4153434545
Owner Name:	CITY OF BURLINGAME
Owner Address:	501 PRIMROSSE ROAD
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0002
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	1974
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

W500 **BURLINGAME FIRE DEPT.** **RGA LUST** **S114588294**
NW **799 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.376 mi.
1987 ft. **Site 21 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

RGA LUST:

2012	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2011	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2010	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2009	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2008	BURLINGAME FIRE DEPT.	799 CALIFORNIA

BURLINGAME FIRE DEPT. (Continued) **S114588294**

2007	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2006	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2005	BURLINGAME FIRE DEPT.	799 CALIFORNIA
2003	BURLINGAME FIRE DEPT.	799 CALIFORNIA

W501 **BURLINGAME FIRE DEPT** **San Mateo Co. BI** **S113755997**
NW **799 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.376 mi.
1987 ft. **Site 22 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0014319
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022806
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

W502 **BURLINGAME FIRE DEPT.** **LUST** **S101303047**
NW **799 CALIFORNIA** **San Mateo Co. BI** **N/A**
1/4-1/2 **BURLINGAME, CA 94010** **HIST CORTESE**
0.376 mi.
1987 ft. **Site 23 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

LUST:

Region:	STATE
Global Id:	T0608100642
Latitude:	37.5834877
Longitude:	-122.3541009
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/09/2002
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0675
LOC Case Number:	660062
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100642
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100642
Contact Type:	Local Agency Caseworker

BURLINGAME FIRE DEPT. (Continued) **S101303047**

Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100642
Status: Completed - Case Closed
Status Date: 08/09/2002

Global Id: T0608100642
Status: Open - Case Begin Date
Status Date: 08/17/1992

Regulatory Activities:
Global Id: T0608100642
Action Type: Other
Date: 08/17/1992
Action: Leak Discovery

Global Id: T0608100642
Action Type: Other
Date: 08/17/1992
Action: Leak Reported

Global Id: T0608100642
Action Type: ENFORCEMENT
Date: 08/19/1992
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660062
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660062
Facility Status: 9- Case Closed
Global ID: T0608100642

BURLINGAME FIRE DEPT. (Continued) **S101303047**

APN Number: 029053450
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0054555
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0076494
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0054555
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0075225
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0059890
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0082311
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0059890
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0082310
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0675

W503 **CITY OF BURLINGAME** **FINDS 1011977968**
NW **799 CALIFORNIA DRIVE** **ECHO N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.376 mi.
1987 ft. **Site 24 of 31 in cluster W**

Relative:
Lower

Actual:
18 ft.

FINDS:

Registry ID: 110038077229

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011977968
Registry ID: 110038077229

CITY OF BURLINGAME (Continued) **1011977968**

DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038077229

R504 **MR. M. AFLAK** **HAZNET** **S112865372**
SSE **51 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.379 mi.
2003 ft. **Site 6 of 6 in cluster R**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S112865372
Year:	1997
GEPAID:	CAC001076976
Contact:	MR. M. AFLAK
Telephone:	4155971948
Mailing Name:	Not reported
Mailing Address:	22 CLUB DRIVE
Mailing City,St,Zip:	SAN CARLOS, CA 940700000
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	1.6856
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

Y505 **HOWARD ENGINEERING** **HAZNET** **S112918071**
NW **724 CAROLAN AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.387 mi.
2044 ft. **Site 2 of 3 in cluster Y**

Relative:
Lower

Actual:
17 ft.

HAZNET:

envid:	S112918071
Year:	2002
GEPAID:	CAC002412759
Contact:	CON HOWARD
Telephone:	6508140673
Mailing Name:	Not reported
Mailing Address:	724 CAROLAN AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAT080033681
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Disposal, Land Fill
Tons:	0.1
Cat Decode:	Other organic solids
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

506
WNW
1/4-1/2
0.390 mi.
2061 ft.

SAM YU
749 FARRINGDON LN
BURLINGAME, CA 94010

HAZNET **S117298817**
N/A

Relative:
Lower

Actual:
27 ft.

HAZNET:

envid:	S117298817
Year:	2013
GEPAID:	CAC002740725
Contact:	SAM YU
Telephone:	4083178185
Mailing Name:	Not reported
Mailing Address:	749 FARRINGDON LN
Mailing City,St,Zip:	BURLINGAME, CA 940103726
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

Z507
NE
1/4-1/2
0.392 mi.
2071 ft.

RESIDENCE
732 LEXINGTON
BURLINGAME, CA 94010
Site 1 of 5 in cluster Z

San Mateo Co. BI **S113757215**
N/A

Relative:
Lower

Actual:
24 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0024735
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0030048
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

V508
South
1/4-1/2
0.392 mi.
2072 ft.

LAURA GSCHWIND
1553 NEWLANDS AVE
BURLINGAME, CA 94010
Site 3 of 3 in cluster V

HAZNET **S113771450**
N/A

Relative:
Higher

Actual:
51 ft.

HAZNET:

envid:	S113771450
Year:	2012
GEPAID:	CAC002683364
Contact:	LAURA GSCHWIND
Telephone:	6506782311
Mailing Name:	Not reported
Mailing Address:	1553 NEWLANDS AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732

LAURA GSCHWIND (Continued) **S113771450**

TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

S509 **COLE EUROPEAN MOTORS** **HAZNET** **S113025834**
ESE **65 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.394 mi.
2081 ft. **Site 32 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113025834
Year:	1993
GEPAID:	CAL000012547
Contact:	COLE EUROPEAN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	65 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	1.8973
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

U510 **MEGAN DYER** **HAZNET** **S112987045**
North **743 WINCHESTER DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.395 mi.
2083 ft. **Site 9 of 9 in cluster U**

Relative:
Lower

Actual:
17 ft.

HAZNET:

envid:	S112987045
Year:	2011
GEPAID:	CAC002667662
Contact:	MEGAN DYER
Telephone:	6503481326
Mailing Name:	Not reported
Mailing Address:	743 WINCHESTER DR
Mailing City,St,Zip:	BURLINGAME, CA 940102738
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Household waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)

MEGAN DYER (Continued) **S112987045**

Tons: 0.05
Cat Decode: Household waste
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

AA511 **JOSEPH KELLER** **HAZNET** **S112888172**
SE **ONE PARK ROAD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.395 mi.
2085 ft. **Site 1 of 16 in cluster AA**

Relative:
Higher

Actual:
42 ft.

HAZNET:
envid: S112888172
Year: 1998
GEPAID: CAC001400280
Contact: JOSEPH KELLER
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 3912 PORTOLA DR #8
Mailing City,St,Zip: SANTA CRUZ, CA 950620000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: .5838
Cat Decode: Waste oil and mixed oil
Method Decode: Recycler
Facility County: San Mateo

T512 **PETER WBORBERG** **HAZNET** **S118199140**
NNE **478 MARIN DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.395 mi.
2087 ft. **Site 3 of 3 in cluster T**

Relative:
Lower

Actual:
19 ft.

HAZNET:
envid: S118199140
Year: 2014
GEPAID: CAC002757348
Contact: PETER WBORBERG
Telephone: 7073217946
Mailing Name: Not reported
Mailing Address: 478 MARIN DR
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Asbestos containing waste
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Asbestos containing waste
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)

PETER WBORBERG (Continued) **S118199140**

Facility County: San Mateo

S513 **COLE EUROPEAN JAGUAR** **HIST UST** **U001593909**
ESE **65 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.397 mi.
2094 ft. **Site 33 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

HIST UST:

File Number:	0002C37A
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C37A.pdf
Region:	STATE
Facility ID:	00000002509
Facility Type:	Other
Other Type:	AUTO DEALERSHIP
Contact Name:	RON ALLEE
Telephone:	4153484200
Owner Name:	THE COLE CAR CO.
Owner Address:	65 CALIFORNIA DR
Owner City,St,Zip:	BURLINGAME,, CA 94010
Total Tanks:	0001
Tank Num:	001
Container Num:	#1
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

S514 **PUTNAM AUTOMOTIVE** **FINDS** **1011987332**
ESE **65 CALIFORNIA DRIVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.397 mi.
2094 ft. **Site 34 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

FINDS:

Registry ID: 110037963861

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid:	1011987332
Registry ID:	110037963861
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110037963861

S515 **PUTNAM AUTOMOTIVE** **EMI** **S100932923**
ESE **65 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.397 mi.
2094 ft. **Site 35 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

EMI:

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.01
Reactive Organic Gases Tons/Yr:	0.008367
Carbon Monoxide Emissions Tons/Yr:	0.027
NOX - Oxides of Nitrogen Tons/Yr:	0.123
SOX - Oxides of Sulphur Tons/Yr:	0.002
Particulate Matter Tons/Yr:	0.009
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.008784

Year:	2005

PUTNAM AUTOMOTIVE (Continued) **S100932923**

County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.01
Reactive Organic Gases Tons/Yr:	.008367
Carbon Monoxide Emissions Tons/Yr:	.027
NOX - Oxides of Nitrogen Tons/Yr:	.123
SOX - Oxides of Sulphur Tons/Yr:	.002
Particulate Matter Tons/Yr:	.009
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.008784

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.005
NOX - Oxides of Nitrogen Tons/Yr:	.023
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.005
NOX - Oxides of Nitrogen Tons/Yr:	.023
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD

PUTNAM AUTOMOTIVE (Continued) **S100932923**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.005
NOX - Oxides of Nitrogen Tons/Yr:	.023
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.002
Reactive Organic Gases Tons/Yr:	0.0016734
Carbon Monoxide Emissions Tons/Yr:	6.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	2.8000000000000001E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.001952

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.002
Reactive Organic Gases Tons/Yr:	0.0016734
Carbon Monoxide Emissions Tons/Yr:	6.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	2.8000000000000001E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00204918032786885
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.002

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14914
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.002
Reactive Organic Gases Tons/Yr:	0.0016734
Carbon Monoxide Emissions Tons/Yr:	0.006
NOX - Oxides of Nitrogen Tons/Yr:	0.028

PUTNAM AUTOMOTIVE (Continued) **S100932923**

SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

S516 **EDR Hist Auto** **1015590153**
ESE **65 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.397 mi.
2094 ft. **Site 36 of 47 in cluster S**

Relative: Higher

Actual: 33 ft.

EDR Historical Auto Stations:

Name:	PUTNAM AUTOMOTIVE
Year:	2007
Address:	65 CALIFORNIA DR
Name:	PUTNAM AUTOMOTIVE
Year:	2008
Address:	65 CALIFORNIA DR
Name:	PUTNAM AUTOMOTIVE
Year:	2009
Address:	65 CALIFORNIA DR

Z517 **TUHIN & SHELBY SINHA** **HAZNET** **S118229453**
NE **728 LEXINGTON WAY** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.397 mi.
2098 ft. **Site 2 of 5 in cluster Z**

Relative: Lower

Actual: 24 ft.

HAZNET:

envid:	S118229453
Year:	2014
GEPAID:	CAC002797135
Contact:	TUHIN & SHELBY SINHA
Telephone:	6154038228
Mailing Name:	Not reported
Mailing Address:	728 LEXINGTON WAY
Mailing City,St,Zip:	BURLINGAME, CA 940102750
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.23
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AB518 **MICHAEL R UHL** **HAZNET** **S112958707**
ENE **800 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.404 mi.
2135 ft. **Site 1 of 6 in cluster AB**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112958707
Year:	2007
GEPAID:	CAC002612214
Contact:	MICHAEL R UHL
Telephone:	6503421353
Mailing Name:	Not reported
Mailing Address:	800 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD008252405
TSD County:	Not reported
Waste Category:	Off-specification, aged or surplus organics
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	1.68
Cat Decode:	Off-specification, aged or surplus organics
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

Z519 **BELINDA BURNS** **HAZNET** **S113775193**
NE **721 LEXINGTON WAY** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.406 mi.
2146 ft. **Site 3 of 5 in cluster Z**

Relative:
Lower

Actual:
24 ft.

HAZNET:

envid:	S113775193
Year:	2012
GEPAID:	CAC002688007
Contact:	BELINDA BURNS
Telephone:	6505792778
Mailing Name:	Not reported
Mailing Address:	721 LEXINGTON WAY
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

AA520 **SERVICE STATION 709** **LUST** **U001593949**
SE **1 PARK ROAD** **HIST UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 2 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

LUST:

Region:	STATE
Global Id:	T0608100043
Latitude:	37.574723128212
Longitude:	-122.343141138554
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/16/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0044
LOC Case Number:	660027
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100043
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100043
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100043
Status:	Completed - Case Closed
Status Date:	03/16/2001

Global Id:	T0608100043
Status:	Open - Case Begin Date
Status Date:	01/27/1987

Regulatory Activities:

Global Id:	T0608100043
Action Type:	Other
Date:	01/27/1987
Action:	Leak Discovery

SERVICE STATION 709 (Continued) **U001593949**

Global Id: T0608100043
Action Type: Other
Date: 01/27/1987
Action: Leak Reported

Global Id: T0608100043
Action Type: REMEDIATION
Date: 05/01/1997
Action: Other (Use Description Field)

Global Id: T0608100043
Action Type: ENFORCEMENT
Date: 06/22/1989
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660027
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST UST:
File Number: 0002BE28
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BE28.pdf
Region: STATE
Facility ID: 00000009205
Facility Type: Gas Station
Other Type: Not reported
Contact Name: NEDDIE ARCHULETA
Telephone: 4153489512
Owner Name: DESERT PETROLEUM, INC.
Owner Address: POST OFFICE BOX 1601
Owner City,St,Zip: OXNARD, CA 93032
Total Tanks: 0004

Tank Num: 001
Container Num: #1
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor

SERVICE STATION 709 (Continued) **U001593949**

Tank Num:	002
Container Num:	#2
Year Installed:	Not reported
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor

Tank Num:	003
Container Num:	#3
Year Installed:	Not reported
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor

Tank Num:	004
Container Num:	#4
Year Installed:	Not reported
Tank Capacity:	00000280
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	1/4
Leak Detection:	None

Click here for Geo Tracker PDF:

AA521 **NICKS HONDA / ACURA SERVICE** **HAZNET** **S113038579**
SE **1 PARK RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 3 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S113038579
Year:	1999
GEPAID:	CAL000042369
Contact:	PHILIP NICHOLAS THEROUX
Telephone:	6503756464
Mailing Name:	Not reported
Mailing Address:	1 PARK RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	.4170
Cat Decode:	Waste oil and mixed oil
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113038579
Year:	1999
GEPAID:	CAL000042369
Contact:	PHILIP NICHOLAS THEROUX

NICKS HONDA / ACURA SERVICE (Continued) **S113038579**

Telephone: 6503756464
Mailing Name: Not reported
Mailing Address: 1 PARK RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Recycler
Tons: .3961
Cat Decode: Unspecified oil-containing waste
Method Decode: Recycler
Facility County: San Mateo

envid: S113038579
Year: 1998
GEPAID: CAL000042369
Contact: PHILIP NICHOLAS THEROUX
Telephone: 6503756464
Mailing Name: Not reported
Mailing Address: 1 PARK RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Waste oil and mixed oil
Disposal Method: Recycler
Tons: .4378
Cat Decode: Waste oil and mixed oil
Method Decode: Recycler
Facility County: San Mateo

envid: S113038579
Year: 1998
GEPAID: CAL000042369
Contact: PHILIP NICHOLAS THEROUX
Telephone: 6503756464
Mailing Name: Not reported
Mailing Address: 1 PARK RD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Transfer Station
Tons: .2293
Cat Decode: Aqueous solution with total organic residues 10 percent or more
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113038579
Year: 1995
GEPAID: CAL000042369
Contact: PHILIP NICHOLAS THEROUX
Telephone: 6503756464
Mailing Name: Not reported
Mailing Address: 1 PARK RD

NICKS HONDA / ACURA SERVICE (Continued) **S113038579**

Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD093459485
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Transfer Station
Tons:	.0166
Cat Decode:	Unspecified solvent mixture
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
1 additional CA_HAZNET: record(s) in the EDR Site Report.

AA522 **EDR Hist Auto** **1015115784**
SE **1 PARK RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 4 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

EDR Historical Auto Stations:

Name:	ANY CAR SVC INC
Year:	2010
Address:	1 PARK RD
Name:	ANY CAR SERVICES INC
Year:	2011
Address:	1 PARK RD
Name:	ANY CAR SERVICES INC
Year:	2012
Address:	1 PARK RD

AA523 **ARMSTRONG PROPERTY** **RGA LUST** **S114577920**
SE **1 PARK ROAD** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.407 mi.
2151 ft. **Site 5 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2012	ARMSTRONG PROPERTY	1 PARK ROAD
2011	ARMSTRONG PROPERTY	1 PARK ROAD
2010	ARMSTRONG PROPERTY	1 PARK ROAD
2009	ARMSTRONG PROPERTY	1 PARK ROAD

AA524 **ARMSTRONG PROPERTY** **LUST** **S101438025**
SE **1 PARK RD** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.407 mi.
2151 ft. **Site 6 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660027
Facility Status:	9- Case Closed
Global ID:	T0608100043
APN Number:	029223160
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0044

AA525 **RRM, INC** **HAZNET** **S112891269**
SE **1 PARK RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 7 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

HAZNET:

envid:	S112891269
Year:	1999
GEPAID:	CAC001434076
Contact:	RRM, INC
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	3912 PORTOLA DR STE 8
Mailing City,St,Zip:	SANTA CRUZ, CA 950620000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.1668
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

AA526 **ARMSTRONG PROPERTY** **RGA LUST** **S114577919**
SE **1 PARK RD** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.407 mi.
2151 ft. **Site 8 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2002	ARMSTRONG PROPERTY	1 PARK RD
2001	ARMSTRONG PROPERTY	1 PARK RD
2000	ARMSTRONG PROPERTY	1 PARK RD
1998	ARMSTRONG PROPERTY	1 PARK RD
1997	ARMSTRONG PROPERTY	1 PARK RD

ARMSTRONG PROPERTY (Continued) **S114577919**

1996	ARMSTRONG PROPERTY	1 PARK RD
1995	ARMSTRONG PROPERTY	1 PARK RD
1994	ARMSTRONG PROPERTY	1 PARK RD
1993	ARMSTRONG PROPERTY	1 PARK RD
1992	ARMSTRONG PROPERTY	1 PARK RD

AA527 **ARMSTRONG PROPERTY** **RGA LUST** **S114577921**
SE **1 PARK** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.407 mi.
2151 ft. **Site 9 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

RGA LUST:

2008	ARMSTRONG PROPERTY	1 PARK
2007	ARMSTRONG PROPERTY	1 PARK
2006	ARMSTRONG PROPERTY	1 PARK
2005	ARMSTRONG PROPERTY	1 PARK
2003	ARMSTRONG PROPERTY	1 PARK

AA528 **NICKS HONDA & ACURA SERVICE** **San Mateo Co. BI** **S113756080**
SE **1 PARK** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 10 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0015055
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011954
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0015055
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004752
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

AA529 **ANY CAR SERVICE** **San Mateo Co. BI** **S113758927**
SE **1 PARK** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.407 mi.
2151 ft. **Site 11 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0049228
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0067251
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO

ANY CAR SERVICE (Continued) **S113758927**

Facility ID:	FA0049228
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0067250
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AB530 **BSD-WASHINGTON ELEMENTARY** **HAZNET** **S112982057**
ENE **801 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.408 mi.
2153 ft. **Site 2 of 6 in cluster AB**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112982057
Year:	2011
GEPAID:	CAC002658966
Contact:	JULIE EASTMAN
Telephone:	6502593880
Mailing Name:	Not reported
Mailing Address:	1825 TROUSDALE DR
Mailing City,St,Zip:	BURLINGAME, CA 940104509
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.6
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AB531 **BESD - WASHINGTON ELEMENTARY SCHOOL** **HAZNET** **S112940203**
ENE **801 HOWARD ST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.408 mi.
2153 ft. **Site 3 of 6 in cluster AB**

Relative:
Lower

Actual:
29 ft.

HAZNET:

envid:	S112940203
Year:	2004
GEPAID:	CAC002581752
Contact:	DANNY CHAN
Telephone:	6503338966
Mailing Name:	Not reported
Mailing Address:	1825 TRUESDALE DR
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD028409019
TSD County:	Not reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Transfer Station
Tons:	0.21
Cat Decode:	Other inorganic solid waste
Method Decode:	Transfer Station

BESD - WASHINGTON ELEMENTARY SCHOOL (Continued) **S112940203**

Facility County: San Mateo

AC532 **BO THORENFELDT** **HAZNET** **S117293060**
East **101 ANITA RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.410 mi.
2167 ft. **Site 1 of 5 in cluster AC**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S117293060
Year:	2013
GEPAID:	CAC002732156
Contact:	BO THORENFELDT
Telephone:	6505589495
Mailing Name:	Not reported
Mailing Address:	101 ANITA RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

AA533 **DEBRA GWIN** **HAZNET** **S118221451**
SSE **1529 CAROL AVENUE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.412 mi.
2176 ft. **Site 12 of 16 in cluster AA**

Relative:
Higher

Actual:
46 ft.

HAZNET:

envid:	S118221451
Year:	2014
GEPAID:	CAC002784839
Contact:	DEBRA GWIN
Telephone:	6503438440
Mailing Name:	Not reported
Mailing Address:	1529 CAROL AVENUE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.8
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AD534 **UST SITE** **San Mateo Co. BI** **S113757493**
ESE **20 HIGHLAND** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.413 mi.
2181 ft. **Site 1 of 19 in cluster AD**

Relative:
Higher

Actual:
37 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0026400
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0038239
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AD535 **PETE ROSSI** **HAZNET** **S112912645**
ESE **20 HIGHLAND AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.413 mi.
2181 ft. **Site 2 of 19 in cluster AD**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S112912645
Year:	2000
GEPAID:	CAC002327809
Contact:	PETE ROSSI
Telephone:	4158226370
Mailing Name:	Not reported
Mailing Address:	PO BOX 24001
Mailing City,St,Zip:	SAN FRANCISCO, CA 941240000
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	0.84
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112912645
Year:	2000
GEPAID:	CAC002327809
Contact:	PETE ROSSI
Telephone:	4158226370
Mailing Name:	Not reported
Mailing Address:	PO BOX 24001
Mailing City,St,Zip:	SAN FRANCISCO, CA 941240000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	5.1
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112912645
Year:	2000
GEPAID:	CAC002327809

PETE ROSSI (Continued) **S112912645**

Contact: PETE ROSSI
Telephone: 4158226370
Mailing Name: Not reported
Mailing Address: PO BOX 24001
Mailing City,St,Zip: SAN FRANCISCO, CA 941240000
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: 0.75
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler
Facility County: San Mateo

S536 **PUTNAM AUTOMOTIVE** **FINDS** **1011992088**
ESE **50 CALIFORNIA DRIVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 37 of 47 in cluster S**

Relative: Higher

Actual: 33 ft.

FINDS:

Registry ID: 110038053815

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:

Envid: 1011992088
Registry ID: 110038053815
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038053815

S537 **PUTNAM MAZDA II** **LUST** **S103892172**
ESE **50 CALIFORNIA** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 38 of 47 in cluster S**

Relative: Higher

Actual: 33 ft.

LUST:

Region: STATE
Global Id: T0608100409
Latitude: 37.577862
Longitude: -122.340431
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/27/1995
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0430
LOC Case Number: 660048
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline

PUTNAM MAZDA II (Continued) **S103892172**

Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100409
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100409
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100409
Status:	Completed - Case Closed
Status Date:	12/27/1995

Global Id:	T0608100409
Status:	Open - Case Begin Date
Status Date:	11/27/1990

Regulatory Activities:

Global Id:	T0608100409
Action Type:	Other
Date:	11/27/1990
Action:	Leak Discovery

Global Id:	T0608100409
Action Type:	Other
Date:	11/27/1990
Action:	Leak Reported

Global Id:	T0608100409
Action Type:	ENFORCEMENT
Date:	05/29/1991
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660048
Facility Status:	9- Case Closed
Global ID:	T0608100409
APN Number:	029243020
Case Type:	SAN MATEO CO. LUST

PUTNAM MAZDA II (Continued) **S103892172**

EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0430

S538 **PUTNAM MAZDA II** **LUST** **S104493495**
ESE **50 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 39 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660048
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

S539 **J AND M MOTORS D B A PUTNAM TOYOTA** **RCRA-SQG** **1000307165**
ESE **50 CALIFORNIA DR** **SWEEPS UST** **CAD981368244**
1/4-1/2 **BURLINGAME, CA 94010** **HIST UST**
0.414 mi. **CA FID UST**
2184 ft. **Site 40 of 47 in cluster S** **FINDS**
ECHO

Relative:
Higher

Actual:
33 ft.

RCRA-SQG:
Date form received by agency: 09/01/1996
Facility name: J AND M MOTORS D B A PUTNAM TOYOTA
Facility address: 50 CALIFORNIA DR
BURLINGAME, CA 94010
EPA ID: CAD981368244
Mailing address: CALIFORNIA DR
BURLINGAME, CA 94010
Contact: Not reported
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of

J AND M MOTORS D B A PUTNAM TOYOTA (Continued) **1000307165**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: J AND M MOTORS PUTNAM TOYOTA
Owner/operator address: 50 CALIFORNIA DR
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (415) 340-6900
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/01/1996
Site name: J AND M MOTORS D B A PUTNAM TOYOTA
Classification: Large Quantity Generator

Violation Status: No violations found

SWEEPS UST:
Status: Not reported
Comp Number: 660003
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660003-000001
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: Not reported
STG: PRODUCT
Content: Not reported
Number Of Tanks: 3

J AND M MOTORS D B A PUTNAM TOYOTA (Continued) **1000307165**

Status: Not reported
Comp Number: 660003
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660003-000002
Tank Status: Not reported
Capacity: 300
Active Date: Not reported
Tank Use: Not reported
STG: PRODUCT
Content: Not reported
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 660003
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660003-000003
Tank Status: Not reported
Capacity: 250
Active Date: Not reported
Tank Use: Not reported
STG: PRODUCT
Content: Not reported
Number Of Tanks: Not reported

HIST UST:
File Number: 0002C196
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C196.pdf
Region: STATE
Facility ID: 00000013309
Facility Type: Other
Other Type: AUTO DEALERSHIP
Contact Name: JOSEPH D. PUTNAM PRES.
Telephone: 4153424321
Owner Name: PUTNAM LEASING INC
Owner Address: 50 CALIFORNIA DR
Owner City,St,Zip: BURLINGAME, CA 94010
Total Tanks: 0003

Tank Num: 001
Container Num: #3
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: Not reported
Leak Detection: Stock Inventor

J AND M MOTORS D B A PUTNAM TOYOTA (Continued) **1000307165**

Tank Num:	002
Container Num:	#2
Year Installed:	Not reported
Tank Capacity:	00000350
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

Tank Num:	003
Container Num:	#1
Year Installed:	Not reported
Tank Capacity:	00000300
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	41000412
Regulated By:	UTNKA
Regulated ID:	CAP981368
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	P O BOX
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

FINDS:

Registry ID: 110002682482

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:

Envid:	1000307165
Registry ID:	110002682482
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002682482

S540 **PUTNAM MAZDA II** **RGA LUST** **S114672883**
ESE **50 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.414 mi.
2184 ft. **Site 41 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2012	PUTNAM MAZDA II	50 CALIFORNIA
2011	PUTNAM MAZDA II	50 CALIFORNIA
2010	PUTNAM MAZDA II	50 CALIFORNIA
2009	PUTNAM MAZDA II	50 CALIFORNIA
2008	PUTNAM MAZDA II	50 CALIFORNIA
2007	PUTNAM MAZDA II	50 CALIFORNIA
2006	PUTNAM MAZDA II	50 CALIFORNIA
2005	PUTNAM MAZDA II	50 CALIFORNIA
2003	PUTNAM MAZDA II	50 CALIFORNIA

S541 **PUTNAM MAZDA II** **RGA LUST** **S114672882**
ESE **50 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.414 mi.
2184 ft. **Site 42 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2002	PUTNAM MAZDA II	50 CALIFORNIA DR
2001	PUTNAM MAZDA II	50 CALIFORNIA DR
2000	PUTNAM MAZDA II	50 CALIFORNIA DR

S542 **PUTNUM MAZADA** **San Mateo Co. BI** **S113755498**
ESE **50 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 43 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0009730
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022744
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

S543 **PUTNAM AUTOMOTIVE** **EMI** **S108432934**
ESE **50 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 44 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

EMI:

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14910
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported

PUTNAM AUTOMOTIVE (Continued) **S108432934**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.0041835
Carbon Monoxide Emissions Tons/Yr:	.013
NOX - Oxides of Nitrogen Tons/Yr:	.059
SOX - Oxides of Sulphur Tons/Yr:	.002
Particulate Matter Tons/Yr:	.004
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.003904

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14910
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.0000000000000001E-3
Reactive Organic Gases Tons/Yr:	2.5100999999999999E-3
Carbon Monoxide Emissions Tons/Yr:	8.9999999999999993E-3
NOX - Oxides of Nitrogen Tons/Yr:	4.1000000000000002E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00307377049180327
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.0000000000000001E-3

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14910
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.009
NOX - Oxides of Nitrogen Tons/Yr:	0.041
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14910
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.009
NOX - Oxides of Nitrogen Tons/Yr:	0.041
SOX - Oxides of Sulphur Tons/Yr:	0

PUTNAM AUTOMOTIVE (Continued) **S108432934**

Particulate Matter Tons/Yr: 0.0030737704918
Part. Matter 10 Micrometers and Smllr Tons/Yr:0.003

S544 **J&M MOTORS INC PUTNAM TOYOTA** **HAZNET** **S113055399**
ESE **50 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 45 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113055399
Year:	2006
GEPAID:	CAL000089519
Contact:	DEACT PER VQ96-RK
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.12
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113055399
Year:	2006
GEPAID:	CAL000089519
Contact:	DEACT PER VQ96-RK
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.16
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113055399
Year:	2006
GEPAID:	CAL000089519
Contact:	DEACT PER VQ96-RK
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste

J&M MOTORS INC PUTNAM TOYOTA (Continued) **S113055399**

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.08
Cat Decode: Unspecified oil-containing waste
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113055399
Year: 2005
GEPAID: CAL000089519
Contact: DEACT PER VQ96-RK
Telephone: --
Mailing Name: Not reported
Mailing Address: 50 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Not reported
Tons: 0.12
Cat Decode: Unspecified oil-containing waste
Method Decode: Not reported
Facility County: San Mateo

envid: S113055399
Year: 2004
GEPAID: CAL000089519
Contact: DEACT PER VQ96-RK
Telephone: --
Mailing Name: Not reported
Mailing Address: 50 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Recycler
Tons: 0.12
Cat Decode: Unspecified oil-containing waste
Method Decode: Recycler
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

S545 **PUTNAM TOYOTA** **HAZNET** **S113003724**
ESE **50 CALIFORNIA D** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.414 mi.
2184 ft. **Site 46 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

HAZNET:
envid: S113003724
Year: 2014
GEPAID: CAD981368244
Contact: ERIC HUNTER/SERVICE MGR

PUTNAM TOYOTA (Continued) **S113003724**

Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104411
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	2.502
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113003724
Year:	2014
GEPAID:	CAD981368244
Contact:	ERIC HUNTER/SERVICE MGR
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104411
Gen County:	San Mateo
TSD EPA ID:	CAD059494310
TSD County:	Santa Clara
Waste Category:	Unspecified solvent mixture
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.075
Cat Decode:	Unspecified solvent mixture
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113003724
Year:	2013
GEPAID:	CAD981368244
Contact:	ERIC HUNTER/SERVICE MGR
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104411
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.22935
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

envid:	S113003724

PUTNAM TOYOTA (Continued) **S113003724**

Year:	2011
GEPAID:	CAD981368244
Contact:	DAVID HALEY/SERVICE MANAGER
Telephone:	6503406900
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104411
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.43785
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113003724
Year:	2010
GEPAID:	CAD981368244
Contact:	ERIC HUNTER/SERVICE MGR
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	50 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940104411
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.22935
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
57 additional CA_HAZNET: record(s) in the EDR Site Report.

S546 **PUTNAM BUICK** **RGA LUST** **S114672877**
ESE **50 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.414 mi.
2184 ft. **Site 47 of 47 in cluster S**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

1998	PUTNAM BUICK	50 CALIFORNIA DR
1997	PUTNAM BUICK	50 CALIFORNIA DR
1996	PUTNAM BUICK	50 CALIFORNIA DR
1995	PUTNAM BUICK	50 CALIFORNIA DR
1994	PUTNAM BUICK	50 CALIFORNIA DR
1993	PUTNAM BUICK	50 CALIFORNIA DR
1992	PUTNAM BUICK	50 CALIFORNIA DR

X547
WSW
1/4-1/2
0.414 mi.
2186 ft.

Relative:
Higher

Actual:
39 ft.

CHMIRS **S105658608**
N/A

SB EL CAMINO REAL AND FLORABUNDA
BURLINGAME, CA

Site 3 of 13 in cluster X

CHMIRS:

OES Incident Number:	9-5313
OES notification:	12/16/1999
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1999
Agency:	CALTRANS
Incident Date:	12/16/199912:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Road
E Date:	Not reported
Substance:	Pool Cleaning Supplies
Gallons:	3
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S105658608**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Traffic accident. Truck overturned spilling product. The products have not mixed. Est cleanup time 1045.

X548 **PRIVATE RESIDENCE** **LUST** **S110655258**
WSW **PRIVATE RESIDENCE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.415 mi.
2190 ft. **Site 4 of 13 in cluster X**

Relative:
Higher

Actual:
43 ft.

LUST:

Region:	STATE
Global Id:	T0608101015
Latitude:	37.577516
Longitude:	-122.355241
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/01/2000
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1105
LOC Case Number:	870018
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608101015
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608101015
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS

PRIVATE RESIDENCE (Continued) **S110655258**

City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608101015
Status: Completed - Case Closed
Status Date: 09/01/2000

Global Id: T0608101015
Status: Open - Case Begin Date
Status Date: 05/26/1998

Regulatory Activities:
Global Id: T0608101015
Action Type: Other
Date: 07/01/1998
Action: Leak Reported

Global Id: T0608101015
Action Type: ENFORCEMENT
Date: 05/26/1998
Action: Notice of Responsibility - #1

549
SSE
1/4-1/2
0.415 mi.
2191 ft.

LARRY PUTMAN & JENNY DIEHL
1547 CYPRESS AVE
BURLINGAME, CA 94010

HAZNET **S118201016**
N/A

Relative:
Higher

Actual:
48 ft.

HAZNET:
envid: S118201016
Year: 2014
GEPAID: CAC002759653
Contact: LARRY PUTMAN
Telephone: 2107487730
Mailing Name: Not reported
Mailing Address: 1547 CYPRESS AVE
Mailing City,St,Zip: BURLINGAME, CA 940105240
Gen County: San Mateo
TSD EPA ID: CAD981382732
TSD County: Alameda
Waste Category: Asbestos containing waste
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Asbestos containing waste
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

AC550 **CHILTON AUTO BODY (BURLINGAME SOUTH)** **San Mateo Co. BI** **S113757533**
East **925 BAYSWATER** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.415 mi.
2193 ft. **Site 2 of 5 in cluster AC**

Relative:
Lower

Actual:
31 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0055544
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0076578
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0026641
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0038698
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0026641
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0038697
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

AC551 **CHILTON AUTO BODY BURLINGAME SOUTH INC** **HAZNET** **S118234685**
East **925 BAYSWATER AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.415 mi.
2193 ft. **Site 3 of 5 in cluster AC**

Relative:
Lower

Actual:
31 ft.

HAZNET:

envid:	S118234685
Year:	2014
GEPAID:	CAL000392040
Contact:	JOE LOPEZ
Telephone:	6503428719
Mailing Name:	Not reported
Mailing Address:	925 BAYSWATER AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.39615
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo
envid:	S118234685
Year:	2014
GEPAID:	CAL000392040
Contact:	JOE LOPEZ
Telephone:	6503428719
Mailing Name:	Not reported
Mailing Address:	925 BAYSWATER AVE

CHILTON AUTO BODY BURLINGAME SOUTH INC (Continued) **S118234685**

Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.075
Cat Decode:	Other organic solids
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	S118234685
Year:	2014
GEPAID:	CAL000392040
Contact:	JOE LOPEZ
Telephone:	6503428719
Mailing Name:	Not reported
Mailing Address:	925 BAYSWATER AVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.108
Cat Decode:	Unspecified solvent mixture
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

AC552 **CHILTON AUTO BODY (SOUTH)** **EMI** **S104972652**
East **925 BAYSWATER STREET** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.415 mi.
2193 ft. **Site 4 of 5 in cluster AC**

Relative:
Lower

Actual:
31 ft.

EMI:

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Year:	1996
County Code:	41
Air Basin:	SF

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.965
Reactive Organic Gases Tons/Yr:	0.8787816
Carbon Monoxide Emissions Tons/Yr:	0.161
NOX - Oxides of Nitrogen Tons/Yr:	0.732
SOX - Oxides of Sulphur Tons/Yr:	0.022
Particulate Matter Tons/Yr:	0.05
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.0488

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.551
Reactive Organic Gases Tons/Yr:	.4848572
Carbon Monoxide Emissions Tons/Yr:	.018
NOX - Oxides of Nitrogen Tons/Yr:	.075
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.003
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.002928

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	3817

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.913
Reactive Organic Gases Tons/Yr:	.8352732
Carbon Monoxide Emissions Tons/Yr:	.018
NOX - Oxides of Nitrogen Tons/Yr:	.075
SOX - Oxides of Sulphur Tons/Yr:	.001
Particulate Matter Tons/Yr:	.003
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.002928

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.909
Reactive Organic Gases Tons/Yr:	.8319264
Carbon Monoxide Emissions Tons/Yr:	.009
NOX - Oxides of Nitrogen Tons/Yr:	.033
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.899
Reactive Organic Gases Tons/Yr:	.8242057
Carbon Monoxide Emissions Tons/Yr:	.005
NOX - Oxides of Nitrogen Tons/Yr:	.019
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.25600000000000001

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Reactive Organic Gases Tons/Yr:	0.20119619999999999
Carbon Monoxide Emissions Tons/Yr:	8.9999999999999993E-3
NOX - Oxides of Nitrogen Tons/Yr:	3.3000000000000002E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.48399999999999999
Reactive Organic Gases Tons/Yr:	0.3965766
Carbon Monoxide Emissions Tons/Yr:	8.0000000000000002E-3
NOX - Oxides of Nitrogen Tons/Yr:	2.8000000000000001E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.492
Reactive Organic Gases Tons/Yr:	0.4032702
Carbon Monoxide Emissions Tons/Yr:	0.033
NOX - Oxides of Nitrogen Tons/Yr:	0.145
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	3817
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.492
Reactive Organic Gases Tons/Yr:	0.4032702
Carbon Monoxide Emissions Tons/Yr:	0.033
NOX - Oxides of Nitrogen Tons/Yr:	0.145
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0081967213115
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.008

CHILTON AUTO BODY (SOUTH) (Continued) **S104972652**

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	22369
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.911
Reactive Organic Gases Tons/Yr:	0.7479562
Carbon Monoxide Emissions Tons/Yr:	0.005
NOX - Oxides of Nitrogen Tons/Yr:	0.02
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	22369
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.912032082
Reactive Organic Gases Tons/Yr:	0.911839979
Carbon Monoxide Emissions Tons/Yr:	0.004608332
NOX - Oxides of Nitrogen Tons/Yr:	0.019220061
SOX - Oxides of Sulphur Tons/Yr:	5.6837e-005
Particulate Matter Tons/Yr:	0.000722295
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000704831

AC553 **PUTNAM BUICK,PONTIAC & GMC** **FINDS** **1005773657**
East **925 BAYSWATER STREET** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.415 mi.
2193 ft. **Site 5 of 5 in cluster AC**

Relative:
Lower

Actual:
31 ft.

FINDS:

Registry ID: 110002412381

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

ECHO:

Envid:	1005773657
Registry ID:	110002412381
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002412381

AA554 **STERLING COURT PROJECT** **SPILLS 90** **S112286149**
SE **EL CAMINO REAL & PENINSULA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.422 mi.
2228 ft. **Site 13 of 16 in cluster AA**

Relative:
Higher

Actual:
43 ft.

Spills:

Status:	INACTIVE
Contact Name:	Not reported
Contact Phone:	Not reported
Site ID:	SLC241S0039
Secondary ID:	Not reported
Cross Street:	Not reported
County:	SAN MATEO
Longitude:	-122342995
Latitude:	37574518
Elevation:	41
Last Agency Update:	6/15/89
Staff:	DW
Status:	INACTIVE
Facility Description:	Not reported
Status:	INACTIVE
Comment:	Not reported
Npl Site:	NOT AN NPL SITE
	Is This A Leaking Underground Tank
	NON TANK
Date Disclosed:	Not reported
Contamination Source:	Not reported
Sample Date:	Not reported
Lead:	RWQCB
# Of Municipal Wells:	0
# Of Private Wells:	0
Agency Comments:	Not reported
Soil Remediation:	Not reported
	Date Soil Removal Or Containment Action Started
	Was Onsite Groundwater Extraction Or Containment Action Needed At Site
	Date On-Stie Gw Extraction Or Containment Action Was Started Or Is Due To Start
	Was Off-Site Groundwater Extraction Or Containment Action Needed
	Date Off-Site Gw Extraction Or Containment Action Was Started Or Is Due To Start
	Most Current Estimate In Gpm S Of The Rate Of Gw Extraction
	0
	Most Recent Date Gw Extraction Flow Rate Was Monitored
	Estimated % Of Contaminants Contained &
	Contamination Plume Length (In Feet)
	0
	Contamination Plume Depth (In Feet)
	0
	Contamination Level If Any Of The Nearest Drinking Water Well
	Wells Closed Due To Contamination From The Site
Date Of Well Closures:	Not reported
	Distance To Nearest Public Or Private Drinking Water Well To Site (In Feet)
	0
	Latitude & Longitude Provided By Facility
	37.5747-122.3422
	Date Site Name Under Preview By Lead Agency

555
North
1/4-1/2
0.426 mi.
2248 ft.

ROB DOMENICI
515 MARIN DR
BURLINGAME, CA 94010

HAZNET **S118223788**
N/A

Relative:
Lower

Actual:
18 ft.

HAZNET:

envid:	S118223788
Year:	2014
GEPAID:	CAC002788107
Contact:	ROB DOMENICI
Telephone:	4086947461
Mailing Name:	Not reported
Mailing Address:	515 MARIN DR
Mailing City,St,Zip:	BURLINGAME, CA 940102726
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.23
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AE556
NE
1/4-1/2
0.426 mi.
2250 ft.

ROB LYNCH
707 CONCORD WAY
BURLINGAME, CA 94010

Site 1 of 3 in cluster AE

HAZNET **S112995368**
N/A

Relative:
Lower

Actual:
22 ft.

HAZNET:

envid:	S112995368
Year:	2011
GEPAID:	CAC002678383
Contact:	ROB LYNCH
Telephone:	4155319787
Mailing Name:	Not reported
Mailing Address:	707 CONCORD WAY
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AA557 **TONY LEUNG** **HAZNET** **S113788082**
SSE **19 E CAROL AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.427 mi.
2252 ft. **Site 14 of 16 in cluster AA**

Relative:
Higher

Actual:
45 ft.

HAZNET:

envid:	S113788082
Year:	2012
GEPAID:	CAC002704336
Contact:	Tony Leung
Telephone:	6508631307
Mailing Name:	Not reported
Mailing Address:	1325 CABRILLO AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104716
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AE558 **JANE CALAVANO** **HAZNET** **S112996404**
ENE **715 BURLINGAME AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.427 mi.
2253 ft. **Site 2 of 3 in cluster AE**

Relative:
Lower

Actual:
24 ft.

HAZNET:

envid:	S112996404
Year:	2011
GEPAID:	CAC002679712
Contact:	JANE CALAVANO
Telephone:	6503486698
Mailing Name:	Not reported
Mailing Address:	715 BURLINGAME AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	Not reported
TSD EPA ID:	CAD981382732
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

X559 **1X MCKINLEY SCHOOL** **HAZNET** **S112836847**
West **701 PALOMA AVENUE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 5 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112836847
Year:	1995
GEPAID:	CAC000033522
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2303 TRUSDALE_DRIVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	4.6354
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

envid:	S112836847
Year:	1994
GEPAID:	CAC000033522
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2303 TRUSDALE_DRIVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000027741
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Disposal, Land Fill
Tons:	6.7424
Cat Decode:	Asbestos containing waste
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

X560 **MCKINLEY ELEMENTARY SCHOOL** **San Mateo Co. BI** **S113756117**
West **701 PALOMA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 6 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0015392
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022808
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

X561 **MCKINLEY ELEM./BURLINGAME USD** **HAZNET** **S112849384**
West **701 PALOMA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 7 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112849384
Year:	1995
GEPAID:	CAC000878232
Contact:	BURLINGAME USD
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2303 TROUSDALE DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAT000646117
TSD County:	Not reported
Waste Category:	Liquids with polychloronated biphenyls >= 50 Mg./L
Disposal Method:	Disposal, Land Fill
Tons:	1.3500
Cat Decode:	Liquids with polychloronated biphenyls >= 50 Mg./L
Method Decode:	Disposal, Land Fill
Facility County:	San Mateo

X562 **MCKINLEY SCHOOL** **RGA LUST** **S114649826**
West **701 PALOMA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.429 mi.
2266 ft. **Site 8 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2012	MCKINLEY SCHOOL	701 PALOMA
2011	MCKINLEY SCHOOL	701 PALOMA
2010	MCKINLEY SCHOOL	701 PALOMA
2009	MCKINLEY SCHOOL	701 PALOMA
2008	MCKINLEY SCHOOL	701 PALOMA
2007	MCKINLEY SCHOOL	701 PALOMA
2006	MCKINLEY SCHOOL	701 PALOMA
2005	MCKINLEY SCHOOL	701 PALOMA
2003	MCKINLEY SCHOOL	701 PALOMA

X563 **1X MCKINLEY SCHOOL** **HAZNET** **S112848855**
West **701 PALOMA AVENUE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 9 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S112848855
Year:	1993
GEPAID:	CAC000871632
Contact:	CITY OF BURLINGAME
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2303 TRUSDALE_DRIVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported

1X MCKINLEY SCHOOL (Continued) **S112848855**

TSD EPA ID:	CAD083166728
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	1.66799999999
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo
envid:	S112848855
Year:	1993
GEPAID:	CAC000871632
Contact:	CITY OF BURLINGAME
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	2303 TRUSDALE_DRIVE
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD004771168
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	2
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

X564 **BSD- MCKINLEY ELEMENTARY SCHOOL** **HAZNET** **S113802302**
West **701 PALOMA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 10 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113802302
Year:	2013
GEPAID:	CAL000376179
Contact:	Laurie Futrell / DTA
Telephone:	6506961200
Mailing Name:	Not reported
Mailing Address:	701 PALOMA AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103728
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.2
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported
envid:	S113802302
Year:	2012
GEPAID:	CAL000376179
Contact:	PAULA VALERIO

BSD- MCKINLEY ELEMENTARY SCHOOL (Continued) **S113802302**

Telephone:	6502593870
Mailing Name:	Not reported
Mailing Address:	701 PALOMA AVE
Mailing City,St,Zip:	BURLINGAME, CA 940103728
Gen County:	San Mateo
TSD EPA ID:	NVT330010000
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	25.284
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

X565 **MCKINLEY SCHOOL** **LUST** **S103892225**
West **701 PALOMA** **SWEEPS UST** **N/A**
1/4-1/2 **BURLINGAME, CA 94010** **HIST CORTESE**
0.429 mi.
2266 ft. **Site 11 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

LUST:

Region:	STATE
Global Id:	T0608100742
Latitude:	37.579533
Longitude:	-122.356663
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/05/1994
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0786
LOC Case Number:	660066
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100742
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100742
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO

MCKINLEY SCHOOL (Continued) **S103892225**

Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100742
Status: Completed - Case Closed
Status Date: 12/05/1994

Global Id: T0608100742
Status: Open - Case Begin Date
Status Date: 09/16/1993

Regulatory Activities:
Global Id: T0608100742
Action Type: Other
Date: 09/16/1993
Action: Leak Reported

Global Id: T0608100742
Action Type: ENFORCEMENT
Date: 10/12/1993
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660066
Facility Status: 9- Case Closed
Global ID: T0608100742
APN Number: 029042120
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 660100
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660100-000001
Tank Status: Not reported
Capacity: 4000
Active Date: Not reported
Tank Use: OIL
STG: PRODUCT
Content: BUNKER FUEL
Number Of Tanks: 1

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA

MCKINLEY SCHOOL (Continued) **S103892225**

Reg Id: 41-0786

X566 **MCKINLEY SCHOOL** **RGA LUST** **S114649825**
West **701 PALOMA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.429 mi.
2266 ft. **Site 12 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2002	MCKINLEY SCHOOL	701 PALOMA AVE
2001	MCKINLEY SCHOOL	701 PALOMA AVE
2000	MCKINLEY SCHOOL	701 PALOMA AVE
1998	MCKINLEY SCHOOL	701 PALOMA AVE
1997	MCKINLEY SCHOOL	701 PALOMA AVE
1996	MCKINLEY SCHOOL	701 PALOMA AVE
1995	MCKINLEY SCHOOL	701 PALOMA AVE
1994	MCKINLEY SCHOOL	701 PALOMA AVE

X567 **MCKINLEY SCHOOL** **LUST** **S104493541**
West **701 PALOMA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.429 mi.
2266 ft. **Site 13 of 13 in cluster X**

Relative:
Higher

Actual:
33 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660066
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

AA568 **PHILIP CHAN** **HAZNET** **S113791572**
SE **15 EL CAMINO REAL** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.430 mi.
2270 ft. **Site 15 of 16 in cluster AA**

Relative:
Higher

Actual:
44 ft.

HAZNET:

envid:	S113791572
Year:	2012
GEPAID:	CAC002709758
Contact:	PHILIP CHAN
Telephone:	4156688267
Mailing Name:	Not reported
Mailing Address:	PO BOX 210388

PHILIP CHAN (Continued) **S113791572**

Mailing City,St,Zip:	SAN FRANCISCO, CA 941210388
Gen County:	San Mateo
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0075
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113791572
Year:	2012
GEPAID:	CAC002709758
Contact:	PHILIP CHAN
Telephone:	4156688267
Mailing Name:	Not reported
Mailing Address:	PO BOX 210388
Mailing City,St,Zip:	SAN FRANCISCO, CA 941210388
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.7
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113791572
Year:	2012
GEPAID:	CAC002709758
Contact:	PHILIP CHAN
Telephone:	4156688267
Mailing Name:	Not reported
Mailing Address:	PO BOX 210388
Mailing City,St,Zip:	SAN FRANCISCO, CA 941210388
Gen County:	San Mateo
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.0825
Cat Decode:	Not reported
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

Y569 **CHMIRS** **S109041896**
NW **CALIFORNIA DR. @ PALM DR.** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.433 mi.
2285 ft. **Site 3 of 3 in cluster Y**

Relative:
Lower

Actual:
15 ft.

CHMIRS:

OES Incident Number:	6-1552
OES notification:	03/14/2006
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Storm Drain
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2006
Agency:	City of Burlingame
Incident Date:	3/14/2006 12:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Road
E Date:	Not reported
Substance:	Sewage
Gallons:	800
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S109041896**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Blockage in line caused this release.

W570 **CALIF FEDERAL SAVING BANK** **RGA LUST** **S114589775**
NW **1112 PALM DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.434 mi.
2291 ft. **Site 25 of 31 in cluster W**

Relative: RGA LUST:
Lower

2002	CALIF FEDERAL SAVING BANK	1112 PALM DR
2001	CALIF FEDERAL SAVING BANK	1112 PALM DR
2000	CALIF FEDERAL SAVING BANK	1112 PALM DR
1998	CALIF FEDERAL SAVING BANK	1112 PALM DR
1997	CALIF FEDERAL SAVING BANK	1112 PALM DR
1996	CALIF FEDERAL SAVING BANK	1112 PALM DR
1995	CALIF FEDERAL SAVING BANK	1112 PALM DR
1994	CALIF FEDERAL SAVING BANK	1112 PALM DR
1993	CALIF FEDERAL SAVING BANK	1112 PALM DR

Actual:
17 ft.

W571 **SWEEPS UST** **S106922158**
NW **1112 PALM DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.434 mi.
2291 ft. **Site 26 of 31 in cluster W**

Relative: SWEEPS UST:
Lower

Status:	Not reported
Comp Number:	660098
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660098-000001
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

Actual:
17 ft.

W572 **CALIF. FEDERAL SAVINGS BANK** **RGA LUST** **S114589795**
NW **1112 PALM** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.434 mi.
2291 ft. **Site 27 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

RGA LUST:

2012	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2011	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2010	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2009	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2008	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2007	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2006	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2005	CALIF. FEDERAL SAVINGS BANK	1112 PALM
2003	CALIF. FEDERAL SAVINGS BANK	1112 PALM

W573 **HAGGERTY RESIDENCE** **RGA LUST** **S114630157**
NW **1112 PALM DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.434 mi.
2291 ft. **Site 28 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

RGA LUST:

1998	HAGGERTY RESIDENCE	1112 PALM DR
1997	HAGGERTY RESIDENCE	1112 PALM DR
1996	HAGGERTY RESIDENCE	1112 PALM DR
1995	HAGGERTY RESIDENCE	1112 PALM DR
1994	HAGGERTY RESIDENCE	1112 PALM DR
1993	HAGGERTY RESIDENCE	1112 PALM DR

W574 **RESIDENCE** **San Mateo Co. BI** **S113756031**
NW **1112 PALM** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.434 mi.
2291 ft. **Site 29 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0014606
Prog Element Code:	UST/TANK ABANDONMENT/REMOVAL FEE
Record Id:	PR0022807
Description:	UST/TANK ABANDONMENT/REMOVAL FEE
Facility Status:	INACTIVE

W575 **CALIF. FEDERAL SAVINGS BANK** **LUST** **S102431136**
NW **1112 PALM** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.434 mi.
2291 ft. **Site 30 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

LUST:

Region:	STATE
Global Id:	T0608100675
Latitude:	37.583184
Longitude:	-122.35483
Case Type:	LUST Cleanup Site

CALIF. FEDERAL SAVINGS BANK (Continued) **S102431136**

Status:	Completed - Case Closed
Status Date:	11/12/1995
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0710
LOC Case Number:	660063
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100675
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100675
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100675
Status:	Completed - Case Closed
Status Date:	11/12/1995

Global Id:	T0608100675
Status:	Open - Case Begin Date
Status Date:	03/03/1993

Regulatory Activities:

Global Id:	T0608100675
Action Type:	ENFORCEMENT
Date:	04/20/1993
Action:	Notice of Responsibility - #1

Global Id:	T0608100675
Action Type:	Other
Date:	03/03/1993
Action:	Leak Discovery

Global Id:	T0608100675
Action Type:	Other
Date:	03/24/1993
Action:	Leak Reported

CALIF. FEDERAL SAVINGS BANK (Continued) **S102431136**

SAN MATEO CO. LUST:
- Region: SAN MATEO
- Facility ID: 660063
- Facility Status: 9- Case Closed
- Global ID: T0608100675
- APN Number: 029021150
- Case Type: SAN MATEO CO. LUST
- EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
- Region: CORTESE
- Facility County Code: 41
- Reg By: LTNKA
- Reg Id: 41-0710

W576 **CALIF. FEDERAL SAVINGS BANK** **LUST** **S101308557**
NW **1112 PALM** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.434 mi.
2291 ft. **Site 31 of 31 in cluster W**

Relative:
Lower

Actual:
17 ft.

LUST REG 2:
- Region: 2
- Facility Id: Not reported
- Facility Status: Case Closed
- Case Number: 660063
- How Discovered: OM
- Leak Cause: Unknown
- Leak Source: Unknown
- Date Leak Confirmed: Not reported
- Oversight Program: LUST
- Prelim. Site Assesment Wokplan Submitted: Not reported
- Preliminary Site Assesment Began: Not reported
- Pollution Characterization Began: Not reported
- Pollution Remediation Plan Submitted: Not reported
- Date Remediation Action Underway: Not reported
- Date Post Remedial Action Monitoring Began: Not reported

AE577 **GREG FRAZER** **HAZNET** **S118214923**
ENE **701 BURLINGAME AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.436 mi.
2302 ft. **Site 3 of 3 in cluster AE**

Relative:
Lower

Actual:
24 ft.

HAZNET:
- envid: S118214923
- Year: 2014
- GEPAID: CAC002776701
- Contact: GREG FRAZER
- Telephone: 6506854121
- Mailing Name: Not reported
- Mailing Address: 701 BURLINGAME AVE
- Mailing City,St,Zip: BURLINGAME, CA 94010
- Gen County: San Mateo
- TSD EPA ID: CAD982444481

GREG FRAZER (Continued) **S118214923**

TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.3
Cat Decode:	Household waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

AF578 **MATT ROSSIE** **HAZNET** **S113784057**
NNW **812 MAPLE AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.438 mi.
2315 ft. **Site 1 of 2 in cluster AF**

Relative: **Lower**

Actual: **15 ft.**

HAZNET:

envid:	S113784057
Year:	2012
GEPAID:	CAC002698970
Contact:	MATT ROSSIE
Telephone:	6508235714
Mailing Name:	Not reported
Mailing Address:	812 MAPLE AVE
Mailing City,St,Zip:	BURLINGAME, CA 940102620
Gen County:	San Mateo
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

AG579 **SMITH RESIDENCE** **RGA LUST** **S114692435**
WSW **1615 FLORIBUNDA AVE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.440 mi.
2321 ft. **Site 1 of 17 in cluster AG**

Relative: **Higher**

Actual: **42 ft.**

RGA LUST:

2002	SMITH RESIDENCE	1615 FLORIBUNDA AVE
2001	SMITH RESIDENCE	1615 FLORIBUNDA AVE
2000	SMITH RESIDENCE	1615 FLORIBUNDA AVE

AG580 **RAY SMITH** **HAZNET** **S112892807**
WSW **1615 FLORABUNDA AVE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.440 mi.
2321 ft. **Site 2 of 17 in cluster AG**

Relative:
Higher

Actual:
42 ft.

HAZNET:

envid:	S112892807
Year:	1998
GEPAID:	CAC001461928
Contact:	RAY SMITH
Telephone:	6505722100
Mailing Name:	Not reported
Mailing Address:	1615 FLORABUNDA AVE
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	.7500
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112892807
Year:	1998
GEPAID:	CAC001461928
Contact:	RAY SMITH
Telephone:	6505722100
Mailing Name:	Not reported
Mailing Address:	1615 FLORABUNDA AVE
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Transfer Station
Tons:	2.8773
Cat Decode:	Waste oil and mixed oil
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S112892807
Year:	1998
GEPAID:	CAC001461928
Contact:	RAY SMITH
Telephone:	6505722100
Mailing Name:	Not reported
Mailing Address:	1615 FLORABUNDA AVE
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Recycler
Tons:	.3127
Cat Decode:	Waste oil and mixed oil
Method Decode:	Recycler

RAY SMITH (Continued) **S112892807**

Facility County: San Mateo

AG581 **SMITH RESIDENCE** **LUST** **S103892534**
WSW **1615 FLORIBUNDA** **HIST CORTESE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.440 mi.
2321 ft. **Site 3 of 17 in cluster AG**

Relative:
Higher

Actual:
42 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	870018
Facility Status:	9- Case Closed
Global ID:	T0608101015
APN Number:	029090320
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-1105

AG582 **RESIDENCE** **San Mateo Co. BI** **S113757239**
WSW **1615 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.440 mi.
2321 ft. **Site 4 of 17 in cluster AG**

Relative:
Higher

Actual:
42 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0024853
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0031258
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AG583 **SMITH RESIDENCE** **RGA LUST** **S114692436**
WSW **1615 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.440 mi.
2321 ft. **Site 5 of 17 in cluster AG**

Relative:
Higher

Actual:
42 ft.

RGA LUST:

2009	SMITH RESIDENCE	1615 FLORIBUNDA
2008	SMITH RESIDENCE	1615 FLORIBUNDA
2007	SMITH RESIDENCE	1615 FLORIBUNDA
2006	SMITH RESIDENCE	1615 FLORIBUNDA
2005	SMITH RESIDENCE	1615 FLORIBUNDA
2003	SMITH RESIDENCE	1615 FLORIBUNDA

AG584 **SMITH RESIDENCE** **LUST** **S104493745**
WSW **1615 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.440 mi.
2321 ft. **Site 6 of 17 in cluster AG**

Relative:
Higher

Actual:
42 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	870018
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

Z585 **SHIRLEY KWOK** **HAZNET** **S118209482**
NE **430 BLOOMFIELD RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.440 mi.
2323 ft. **Site 4 of 5 in cluster Z**

Relative:
Lower

Actual:
22 ft.

HAZNET:

envid:	S118209482
Year:	2014
GEPAID:	CAC002770060
Contact:	SHIRLEY KWOK
Telephone:	6504507008
Mailing Name:	Not reported
Mailing Address:	430 BLOOMFIELD RD
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD982444481
TSD County:	San Bernardino
Waste Category:	Household waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.175
Cat Decode:	Household waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

AG586 **HILLSBOROUGH FIRE DEPARTMENT** **Cortese** **S112852715**
WSW **1600 FLORIBUNDA** **HAZNET** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 7 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

CORTESE:

Region:	CORTESE
Envirostor Id:	Not reported
Site/Facility Type:	Not reported
Cleanup Status:	Not reported
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	CORTESE
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported

HAZNET:

envid:	S112852715
Year:	1993
GEPAID:	CAC000916672
Contact:	HILLSBOROUGH FIRE DEPARTMENT
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	1600 FLORIBUNDA
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Not reported
Tons:	0.77500000000
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Not reported
Facility County:	San Mateo

AG587 **CITY OF HILLSBOROUGH PROPERTY** **RGA LUST** **S114602807**
WSW **1600 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.445 mi.
2351 ft. **Site 8 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

RGA LUST:

1997	CITY OF HILLSBOROUGH PROPERTY	1600 FLORIBUNDA
1996	CITY OF HILLSBOROUGH PROPERTY	1600 FLORIBUNDA
1995	CITY OF HILLSBOROUGH PROPERTY	1600 FLORIBUNDA
1994	CITY OF HILLSBOROUGH PROPERTY	1600 FLORIBUNDA
1993	CITY OF HILLSBOROUGH PROPERTY	1600 FLORIBUNDA

AG588 **TOWN OF HILLSBOROUGH** **SWEEPS UST** **S104493744**
WSW **1600 FLORIBUNDA AVE** **CHMIRS** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 9 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

SWEEPS UST:

Status:	Active
Comp Number:	870006
Number:	4
Board Of Equalization:	Not reported
Referral Date:	05-13-94
Action Date:	05-13-94
Created Date:	07-21-93
Owner Tank Id:	UNK
SWRCB Tank Id:	41-000-870006-000001
Tank Status:	A
Capacity:	500
Active Date:	07-21-93
Tank Use:	UNKNOWN
STG:	P
Content:	Not reported
Number Of Tanks:	3

Status:	Active
Comp Number:	870006
Number:	4
Board Of Equalization:	Not reported
Referral Date:	05-13-94
Action Date:	05-13-94
Created Date:	07-21-93
Owner Tank Id:	UNK
SWRCB Tank Id:	41-000-870006-000002
Tank Status:	A
Capacity:	1000
Active Date:	07-21-93
Tank Use:	EMPTY
STG:	P
Content:	Not reported
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	870006
Number:	4
Board Of Equalization:	Not reported
Referral Date:	05-13-94
Action Date:	05-13-94
Created Date:	07-21-93
Owner Tank Id:	UNK
SWRCB Tank Id:	41-000-870006-000003
Tank Status:	A
Capacity:	2000
Active Date:	07-21-93
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

TOWN OF HILLSBOROUGH (Continued) **S104493744**

CHMIRS:

OES Incident Number:	08-0773
OES notification:	01/26/2008
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	Storm Drain
Spill Site:	Road
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1700
Year:	2008
Agency:	Town of Hillsborough Public Works
Incident Date:	1/25/2008
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Storm Drain
E Date:	Not reported
Substance:	Sewage
Quantity Released:	20,000
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported

TOWN OF HILLSBOROUGH (Continued) **S104493744**

#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Substance was released from a manhole due to surcharge caused by heavy rains.

AG589 **TOWN OF HILLSBOROUGH** **LUST S103472740**
WSW **1600 FLORIBUNDA** **CHMIRS N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010** **ENF**
0.445 mi.
2351 ft. **Site 10 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	870005
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

CHMIRS:

OES Incident Number:	08-0157
OES notification:	01/05/2008
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported

TOWN OF HILLSBOROUGH (Continued) **S103472740**

Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	San Mateo Creek
Spill Site:	Road
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1400
Year:	2008
Agency:	Town Of Hillsborough Public Works
Incident Date:	1/4/2008
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	San Mateo Creek
E Date:	Not reported
Substance:	Sewage
Quantity Released:	18,000
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Sanitary sewage overflow from the manhole to the street and storm drain.

ENF:

Region:	2
Facility Id:	630900
Agency Name:	Town Of Hillsborough
Place Type:	Utility
Place Subtype:	Collection_System
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	Not reported

TOWN OF HILLSBOROUGH (Continued) **S103472740**

Place Longitude:	Not reported
SIC Code 1:	Not reported
SIC Desc 1:	Not reported
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	3
Complexity:	C
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	SSOMUNILRG
Program Category1:	SSO
Program Category2:	SSO
# Of Programs:	1
WDID:	2SSO10142
Reg Measure Id:	299939
Reg Measure Type:	Enrollee
Region:	2
Order #:	2006-0003-DWQ
Npdes# CA#:	Not reported
Major-Minor:	Minor
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	872
Status:	Active
Status Date:	04/10/2006
Effective Date:	11/02/2006
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	Y
Individual/General:	I
Fee Code:	58 - Non15 Based on (TTWQ)/CPLX)
Direction/Voice:	Passive
Enforcement Id(EID):	362438
Region:	2
Order / Resolution Number:	R2-2009-0014

TOWN OF HILLSBOROUGH (Continued) **S103472740**

Enforcement Action Type:	Admin Civil Liability
Effective Date:	03/11/2009
Adoption/Issuance Date:	03/11/2009
Achieve Date:	Not reported
Termination Date:	10/20/2014
ACL Issuance Date:	09/16/2008
EPL Issuance Date:	Not reported
Status:	Historical
Title:	ACL R2-2009-0014 for Town Of Hillsborough
Description:	ACLO ISSUED TO TOWN OF HILLSBOROUGH WITH INITIAL ACLC NO. R2-2008-0066 TOTAL PENALTY OF $405,000 WITH A $225,000 SEP.
Program:	SSOMUNILRG
Latest Milestone Completion Date:	2014-06-19
# Of Programs1:	1
Total Assessment Amount:	$405,000.0
Initial Assessed Amount:	$750,000.0
Liability $ Amount:	$180,000.0
Project $ Amount:	$0.00
Liability $ Paid:	$180,000.0
Project $ Completed:	$0.00
Total $ Paid/Completed Amount:	$180,000.0

AG590 **CHMIRS** **S111754318**
WSW **1600 FLORABUNDA AVENUE, TOWN OF HILLSBOROUGH CITY HALL** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 11 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

CHMIRS:

OES Incident Number:	1-1928
OES notification:	03/25/2011
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported

(Continued) **S111754318**

Waterway Involved:	Yes
Waterway:	Storm Drain, unknown where it runs to
Spill Site:	Other
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1130
Year:	2011
Agency:	Town of Hillsborough
Incident Date:	3/24/2011
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Storm Drain, unknown where it runs to
E Date:	Not reported
Substance:	Mixture of Rain Water (85%) and Raw Sewage (15%)
Quantity Released:	27,000
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Caller states capacity deficiency on a sewer main line due to a weather storm resulted in the release of substance from a man hole. Release was contained at 1430 hours on 03/24/11.

AG591 **HILLSBOROUGH CITY OF** **RGA LUST** **S114632559**
WSW **1600 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.445 mi.
2351 ft. **Site 12 of 17 in cluster AG**

Relative:
Higher

RGA LUST:

1998 HILLSBOROUGH CITY OF 1600 FLORIBUNDA

Actual:
41 ft.

AG592 **HILLSBOROUGH TOWN HALL** **San Mateo Co. BI** **S113755541**
WSW **1600 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 13 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0010329
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0026550
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010329
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0023370
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AG593 **HILLSBOROUGH TOWN OF** **RGA LUST** **S114632565**
WSW **1600 FLORIBUNDA AVE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.445 mi.
2351 ft. **Site 14 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

RGA LUST:

2002	HILLSBOROUGH TOWN OF	1600 FLORIBUNDA AVE
2001	HILLSBOROUGH TOWN OF	1600 FLORIBUNDA AVE
2000	HILLSBOROUGH TOWN OF	1600 FLORIBUNDA AVE

AG594 **TOWN OF HILLSBOROUGH** **RGA LUST** **S114705800**
WSW **1600 FLORIBUNDA** **N/A**
1/4-1/2 **HILLSBOROUGH, CA**
0.445 mi.
2351 ft. **Site 15 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

RGA LUST:

2012	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2011	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2010	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2009	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2008	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2007	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2006	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2005	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA
2003	TOWN OF HILLSBOROUGH	1600 FLORIBUNDA

AG595 **CHMIRS** **S109036513**
WSW **1600 FLORIBUNDA AVE.** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 16 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

CHMIRS:

OES Incident Number:	7-1296
OES notification:	02/28/2007
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Storm Drain
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2007
Agency:	Town of Hillsborough Public Works
Incident Date:	2/26/2007 12:00:00 AM
Admin Agency:	San Mateo County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Other
E Date:	Not reported
Substance:	Sewage
Gallons:	6000
Unknown:	0
Substance #2:	Not reported
Substance #3:	Not reported

(Continued) **S109036513**

Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Heavy rains infiltrated the system causing this over flow.

AG596 **HILLSBOROUGH TOWN OF** **LUST** **S100864064**
WSW **1600 FLORIBUNDA** **HIST CORTESE** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.445 mi.
2351 ft. **Site 17 of 17 in cluster AG**

Relative:
Higher

Actual:
41 ft.

LUST:

Region:	STATE
Global Id:	T0608100704
Latitude:	37.57818
Longitude:	-122.355074
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/05/1999
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0744
LOC Case Number:	870005
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100704
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100704
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO

HILLSBOROUGH TOWN OF (Continued) **S100864064**

Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100704
Status: Completed - Case Closed
Status Date: 03/05/1999

Global Id: T0608100704
Status: Open - Case Begin Date
Status Date: 04/28/1993

Regulatory Activities:
Global Id: T0608100704
Action Type: ENFORCEMENT
Date: 06/09/1993
Action: Notice of Responsibility - #1

Global Id: T0608100704
Action Type: Other
Date: 06/09/1993
Action: Leak Discovery

Global Id: T0608100704
Action Type: Other
Date: 04/28/1993
Action: Leak Reported

Global Id: T0608100704
Action Type: REMEDIATION
Date: 07/26/1993
Action: Excavation

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 870005
Facility Status: 9- Case Closed
Global ID: T0608100704
APN Number: 028141090
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0744

AD597 **SUSAN STEFFEN** **HAZNET** **S112976493**
ESE **214 PENINSULA AVE** **N/A**
1/4-1/2 **SAN MATEO, CA 94401**
0.446 mi.
2353 ft. **Site 3 of 19 in cluster AD**

Relative:
Higher

Actual:
37 ft.

HAZNET:

envid:	S112976493
Year:	2009
GEPAID:	CAC002640146
Contact:	ANN TREMAROLI
Telephone:	4154459989
Mailing Name:	Not reported
Mailing Address:	150 CLARK DR
Mailing City,St,Zip:	SAN MATEO, CA 944021003
Gen County:	Not reported
TSD EPA ID:	CAD982042475
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AH598 **NICK ROGERS** **HAZNET** **S117285917**
SSW **325 CHAPIN LN** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.449 mi.
2371 ft. **Site 1 of 10 in cluster AH**

Relative:
Higher

Actual:
57 ft.

HAZNET:

envid:	S117285917
Year:	2013
GEPAID:	CAC002721395
Contact:	NICK ROGERS
Telephone:	6502078005
Mailing Name:	Not reported
Mailing Address:	325 CHAPIN LN
Mailing City,St,Zip:	BURLINGAME, CA 940105103
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

AB599 **DENISE DIRICKSON** **PEST LIC** **S117626685**
ENE **209 BLOOMFIELD RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.461 mi.
2436 ft. **Site 4 of 6 in cluster AB**

Relative:
Lower

Actual:
27 ft.

PEST LIC:

Facility Type:	QAL
Categories:	B
License No:	104637
Issued or Renewed Date:	01/01/2015
Expiration Date:	12/31/2016

---

600 **TARA & BRIAN WATSON** **HAZNET** **S117284232**
NNE **460 BLOOMFIELD RD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.467 mi.
2468 ft.

Relative:
Lower

Actual:
19 ft.

HAZNET:

envid:	S117284232
Year:	2013
GEPAID:	CAC002719030
Contact:	TARA WATSON
Telephone:	Not reported
Mailing Name:	Not reported
Mailing Address:	460 BLOOMFIELD RD
Mailing City,St,Zip:	BURLINGAME, CA 940102754
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

AI601 **HERMAN HSU** **HAZNET** **S117293384**
WSW **20 SUMMERHOLME PL** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.469 mi.
2477 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
55 ft.

HAZNET:

envid:	S117293384
Year:	2013
GEPAID:	CAC002732610
Contact:	HERMAN HSU
Telephone:	6502553544
Mailing Name:	Not reported
Mailing Address:	20 SUMMERHOLME PL
Mailing City,St,Zip:	HILLSBOROUGH, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda

HERMAN HSU (Continued) **S117293384**

Waste Category: Not reported
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.4
Cat Decode: Not reported
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: Not reported

AB602 **ANTOSIK, EDWIN** **San Mateo Co. BI** **S113757580**
ENE **701 HOWARD** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.470 mi.
2479 ft. **Site 5 of 6 in cluster AB**

Relative:
Lower

Actual:
27 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0026863
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0039854
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AB603 **EDWIN ANTOSIK** **HAZNET** **S112917577**
ENE **701 HOWARD AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.470 mi.
2479 ft. **Site 6 of 6 in cluster AB**

Relative:
Lower

Actual:
27 ft.

HAZNET:
envid: S112917577
Year: 2001
GEPAID: CAC002384099
Contact: ANGELIPA SALAPUDDIN-CEECON
Telephone: 6508277474
Mailing Name: Not reported
Mailing Address: 225 BLOOMFIELD
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Recycler
Tons: 0.09
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Recycler
Facility County: San Mateo

AD604 **T MOBILE WEST CORP SF13047A** **San Mateo Co. BI** **S113758728**
ESE **3 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 4 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045342
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0058980
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AD605 **ARCO #0249** **RGA LUST** **S114573085**
ESE **3 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 5 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2008	ARCO #0249	3 CALIFORNIA
2007	ARCO #0249	3 CALIFORNIA
2006	ARCO #0249	3 CALIFORNIA
2005	ARCO #0249	3 CALIFORNIA

AD606 **ARCO #0249** **RGA LUST** **S114573084**
ESE **3 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 6 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2012	ARCO #0249	3 CALIFORNIA DRIVE
2011	ARCO #0249	3 CALIFORNIA DRIVE
2010	ARCO #0249	3 CALIFORNIA DRIVE
2009	ARCO #0249	3 CALIFORNIA DRIVE

AD607 **PUTNAM MAZDA** **EMI** **S106921350**
ESE **3 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 7 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

EMI:

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

PUTNAM MAZDA (Continued) **S106921350**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.011
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000976

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.007
NOX - Oxides of Nitrogen Tons/Yr:	.03
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.005
NOX - Oxides of Nitrogen Tons/Yr:	.004
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year: 2007

PUTNAM MAZDA (Continued) **S106921350**

County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.01
NOX - Oxides of Nitrogen Tons/Yr:	.008
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.001
Reactive Organic Gases Tons/Yr:	.0008367
Carbon Monoxide Emissions Tons/Yr:	.01
NOX - Oxides of Nitrogen Tons/Yr:	.008
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	8.3670000000000001E-4
Carbon Monoxide Emissions Tons/Yr:	0.01
NOX - Oxides of Nitrogen Tons/Yr:	8.0000000000000002E-3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD

PUTNAM MAZDA (Continued) **S106921350**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.0000000000000001E-3
Reactive Organic Gases Tons/Yr:	0.0033468
Carbon Monoxide Emissions Tons/Yr:	3.6999999999999998E-2
NOX - Oxides of Nitrogen Tons/Yr:	2.9999999999999999E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00204918032786885
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.002

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.004
Reactive Organic Gases Tons/Yr:	0.0033468
Carbon Monoxide Emissions Tons/Yr:	0.037
NOX - Oxides of Nitrogen Tons/Yr:	0.03
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	3812
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.004
Reactive Organic Gases Tons/Yr:	0.0033468
Carbon Monoxide Emissions Tons/Yr:	0.037
NOX - Oxides of Nitrogen Tons/Yr:	0.03
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0020491803279
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.002

AD608 **PUTNAM AUTOMOTIVE CHRYSLER, MAZDA & SUBARU** **San Mateo Co. BI** **S113759064**
ESE **3-85 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 8 of 19 in cluster AD**

Relative: Higher

Actual: 33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0052041
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0072136
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

PUTNAM AUTOMOTIVE CHRYSLER, MAZDA & SUBARU (Continued) **S113759064**

Region: SAN MATEO
Facility ID: FA0052041
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0072135
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0052041
Prog Element Code: 2352
Record Id: PR0072139
Description: TIER I: TANK STOR CAP =>1,320 & <5,000 GAL
Facility Status: ACTIVE

AD609 **IN-ACTIVE ARCO STATION** **HIST UST** **U001593921**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 9 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

HIST UST:
File Number: 0002BF9E
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BF9E.pdf
Region: STATE
Facility ID: 00000015802
Facility Type: Gas Station
Other Type: Not reported
Contact Name: Not reported
Telephone: 4153424321
Owner Name: JOSEPH D. PUTNAM
Owner Address: 50 CALIFORNIA DR.
Owner City,St,Zip: BURLINGAME, CA 94010
Total Tanks: 0000

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported

IN-ACTIVE ARCO STATION (Continued) **U001593921**

Container Construction Thickness: Not reported
Leak Detection: None

Click here for Geo Tracker PDF:

AD610 **ARCO #0249** **LUST** **S103396197**
ESE **3 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 10 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Pollution Characterization
Case Number:	660026
How Discovered:	Tank Closure
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	11/22/2002
Pollution Characterization Began:	12/27/2002
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

AD611 **ARCO** **RGA LUST** **S114576725**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 11 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2002	ARCO	3 CALIFORNIA DR
2001	ARCO	3 CALIFORNIA DR
2000	ARCO	3 CALIFORNIA DR

AD612 **FORMER ARCO # 00249** **RGA LUST** **S114621881**
ESE **3 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 12 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2003	FORMER ARCO # 00249	3 CALIFORNIA

AD613 **PUTNAM MAZDA** **HAZNET** **S113027025**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 13 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113027025
Year:	2000
GEPAID:	CAL000015634
Contact:	INACTIVE PER SURVEY 2-22-95 CM
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	3 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	6.85
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113027025
Year:	1999
GEPAID:	CAL000015634
Contact:	PUTNAM JOE
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	3 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	6.9762
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113027025
Year:	1998
GEPAID:	CAL000015634
Contact:	PUTNAM JOE
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	3 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified organic liquid mixture
Disposal Method:	Recycler
Tons:	2.7562
Cat Decode:	Unspecified organic liquid mixture
Method Decode:	Recycler

PUTNAM MAZDA (Continued) **S113027025**

Facility County: San Mateo

envid: S113027025
Year: 1997
GEPAID: CAL000015634
Contact: PUTNAM JOE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 3 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 2.9814
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

envid: S113027025
Year: 1996
GEPAID: CAL000015634
Contact: PUTNAM JOE
Telephone: 0000000000
Mailing Name: Not reported
Mailing Address: 3 CALIFORNIA DR
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: Not reported
TSD EPA ID: CAD009452657
TSD County: Not reported
Waste Category: Unspecified organic liquid mixture
Disposal Method: Recycler
Tons: 2.8063
Cat Decode: Unspecified organic liquid mixture
Method Decode: Recycler
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
2 additional CA_HAZNET: record(s) in the EDR Site Report.

AD614 **BP WEST COAST PRODUCTS LLC 00249** **HAZNET** **S113122671**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 14 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

HAZNET:
envid: S113122671
Year: 2012
GEPAID: CAL000260681
Contact: JACKIE DOUGHERTY
Telephone: 9497354632
Mailing Name: Not reported
Mailing Address: PO BOX 80249
Mailing City,St,Zip: RCHO STA MARG, CA 926880000
Gen County: San Mateo
TSD EPA ID: CAT080013352

BP WEST COAST PRODUCTS LLC 00249 (Continued) **S113122671**

TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.966
Cat Decode:	Not reported
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo
envid:	S113122671
Year:	2010
GEPAID:	CAL000260681
Contact:	JACKIE DOUGHERTY
Telephone:	9497354632
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.05
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo
envid:	S113122671
Year:	2009
GEPAID:	CAL000260681
Contact:	Waste Specialist
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.084
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo
envid:	S113122671
Year:	2009
GEPAID:	CAL000260681
Contact:	Waste Specialist
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249

BP WEST COAST PRODUCTS LLC 00249 (Continued) **S113122671**

Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	NVT330010000
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.1125
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo
envid:	S113122671
Year:	2008
GEPAID:	CAL000260681
Contact:	RUTH HA / WASTE SPECIALIST
Telephone:	5035246191
Mailing Name:	Not reported
Mailing Address:	PO BOX 80249
Mailing City,St,Zip:	RCHO STA MARG, CA 926880000
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.7686
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access additional CA_HAZNET: detail in the EDR Site Report.

AD615 **PUTNAM-MAZDA BUICK** **RGA LUST** **S114672888**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 15 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

1996	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR
1995	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR
1994	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR
1993	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR
1992	PUTNAM-MAZDA BUICK	3 CALIFORNIA DR

AD616 **PUTNAM MAZDA** **HAZNET** **S113011373**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 16 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113011373
Year:	2014
GEPAID:	CAD981983356
Contact:	ERIC HUNTER/PARTS MANAGER
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	BOX 982
Mailing City,St,Zip:	BURLINGAME, CA 940110982
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	3.44025
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113011373
Year:	2013
GEPAID:	CAD981983356
Contact:	ERIC HUNTER/PARTS MANAGER
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	BOX 982
Mailing City,St,Zip:	BURLINGAME, CA 940110982
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.3336
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

envid:	S113011373
Year:	2012
GEPAID:	CAD981983356
Contact:	ERIC HUNTER/PARTS MANAGER
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	BOX 982
Mailing City,St,Zip:	BURLINGAME, CA 940110982
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported

PUTNAM MAZDA (Continued) **S113011373**

Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.125
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113011373
Year:	2012
GEPAID:	CAD981983356
Contact:	ERIC HUNTER/PARTS MANAGER
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	BOX 982
Mailing City,St,Zip:	BURLINGAME, CA 940110982
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.125
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113011373
Year:	2012
GEPAID:	CAD981983356
Contact:	ERIC HUNTER/PARTS MANAGER
Telephone:	6503474800
Mailing Name:	Not reported
Mailing Address:	BOX 982
Mailing City,St,Zip:	BURLINGAME, CA 940110982
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.1676
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
69 additional CA_HAZNET: record(s) in the EDR Site Report.

AD617 **PUTNAM VOLVO** **San Mateo Co. BI** **S113755327**
ESE **3-65 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.471 mi.
2485 ft. **Site 17 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0006062
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011881
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0006062
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004658
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AD618 **PUTNAM MAZDA BUICK** **RGA LUST** **S114672881**
ESE **3 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.471 mi.
2485 ft. **Site 18 of 19 in cluster AD**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

1998	PUTNAM MAZDA BUICK	3 CALIFORNIA DR
1997	PUTNAM MAZDA BUICK	3 CALIFORNIA DR

AD619 **PUTNAM MAZDA** **RCRA-SQG** **1000307166**
ESE **3 CALIFORNIA DR** **LUST** **CAD981983356**
1/4-1/2 **BURLINGAME, CA 94010** **FINDS**
0.471 mi. **HIST CORTESE**
2485 ft. **Site 19 of 19 in cluster AD** **ECHO**

Relative:
Higher

Actual:
33 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	PUTNAM MAZDA
Facility address:	3 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD981983356
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

PUTNAM MAZDA (Continued) **1000307166**

Owner/Operator Summary:
Owner/operator name: PUTNAM AUTOMOTIVE INC
Owner/operator address: 3 CALIFORNIA DR
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (415) 347-4800
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/12/1991
Site name: PUTNAM MAZDA
Classification: Large Quantity Generator

Violation Status: No violations found

LUST:
Region: STATE
Global Id: T0608100410
Latitude: 37.5770317201304
Longitude: -122.339678406715
Case Type: LUST Cleanup Site
Status: Open - Site Assessment
Status Date: 12/27/2002
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: DGM
Local Agency: SAN MATEO COUNTY LOP

PUTNAM MAZDA (Continued) **1000307166**

RB Case Number: 41-0431
LOC Case Number: 660026
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Extracted from Stantec's September 16, 2009 THIRD QUARTER 2009 GROUNDWATER MONITORING REPORT, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is a former ARCO service station that currently operates as an automotive dealership (Putnam Volvo), and is located at the western corner of California Drive and Peninsula Avenue in Burlingame, California. The site currently has eight groundwater monitoring wells (MW-1 through MW-8). MW-1 through MW-4 have been monitored since the fourth quarter 2002. The former underground storage tanks (USTs) were located near the eastern portion of the site. Based on available information, the site (at the time a vacant lot) was acquired by ARCO in November 1946. In April 1948 ARCO constructed the service station and installed two 1,000-gallon USTs. In March 1950, ARCO replaced the previously installed USTs with four 2,000-gallon USTs. A review of aerial photographs indicates an apparent gas station on the site in 1955. In December 1963, a 280-gallon waste oil UST was installed at the site. In November 1971, ARCO replaced four fuel dispensers. In August 1977, ARCO replaced product piping and replaced the four 2,000-gallon gasoline USTs with two 8,000-gallon USTs and one 6,000-gallon UST. In 1983, Joseph and Mary Lou Putnam acquired the site and developed Putnam Buick (Putnam) onsite in 1985. According to currently available information, ARCO divested the site with the USTs, product lines, dispensers, and station building in place. On December 28, 1983, the Burlingame Fire Department inspected the site gasoline USTs in response to a UST permit renewal request. Putman had the USTs removed from the site in March 1985. Blaine Tech Services March 22, 1985 Soil Sampling Report states that four USTs were removed from the site on March 18, 1985. Three of the USTs reportedly stored gasoline, and the fourth stored waste oil. Soil excavated during UST removals was reportedly spread onsite and aerated. Analytical results of soil samples collected from the waste oil UST excavation indicated no detectable concentrations of oil by gas chromatograph and flame ionization (no specific laboratory method was reported). Samples collected from the gasoline UST excavation yielded concentrations of TPHg ranging from 58 to 6,200 milligrams per kilogram (mg/kg). No other remedial activities have been conducted at the site. During two mobilizations, October 17 through October 18, 2002 and November 22, 2002, a URS geologist supervised Gregg Drilling and Testing, Inc. (Gregg), of Martinez, California, during drilling and installation of four groundwater monitoring wells (MW-1 through MW-4). On May 27 and 28, 2004 and July 27 and 29, 2004, a URS geologist supervised Gregg in advancing six Geoprobe borings (SB-4 through SB-9) using vehicle-mounted direct-push equipment. Each boring was advanced to approximately 25 to 30 feet bgs. Soil samples were collected every five feet and selected soil samples were submitted for chemical analyses. On July 26 and 31, 2004, a URS geologist supervised Gregg during drilling and installing four groundwater monitoring wells (MW-5 through MW-8) to approximately 25 feet bgs. During drilling, groundwater was encountered at a depth of approximately 23 to 24 feet bgs. On January 15, 2008, SECOR submitted a Work Plan for Groundwater Batch Extraction. Groundwater batch

PUTNAM MAZDA (Continued) **1000307166**

extraction was proposed as a means to remove separate phase hydrocarbons (SPH) and hydrocarbon impacted groundwater from wells MW-1, MW-2, and MW-3. In a letter dated July 30, 2008, GPP conditionally approved the use of vacuum truck equipment for groundwater batch extraction based on the current depth to groundwater. GPP approved the use of vacuum trucks to remove SPH and groundwater when the groundwater level was below the top of the well screen in wells containing SPH. Adsorbent socks were approved to be used to recover SPH when the groundwater is above the top of the well screens. Per SWRCB Resolution 2009-0042, Stantec submitted a Proposed Groundwater Monitoring and Sampling Schedule to the GPP, dated July 28, 2009. The proposal recommended monitoring and sampling on a semi-annual basis during the months of April and October. Site visits will continue on a monthly basis for passive SPH removal.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100410
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100410
Contact Type:	Local Agency Caseworker
Contact Name:	DENO MILANO
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	dmilano@smcgov.org
Phone Number:	6503726292

Status History:

Global Id:	T0608100410
Status:	Open - Case Begin Date
Status Date:	03/21/1985

Global Id:	T0608100410
Status:	Open - Site Assessment
Status Date:	11/22/2002

Global Id:	T0608100410
Status:	Open - Site Assessment
Status Date:	12/27/2002

Regulatory Activities:

Global Id:	T0608100410
Action Type:	ENFORCEMENT
Date:	03/19/2003
Action:	Staff Letter - #20030319

Global Id:	T0608100410
Action Type:	RESPONSE

PUTNAM MAZDA (Continued) **1000307166**

Date: 08/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 03/31/2010
Action: Staff Letter - #20100331

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 07/20/2005
Action: Staff Letter - #20050720

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 10/30/2002
Action: Notice of Responsibility - #20021030

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 05/15/1995
Action: Notice of Responsibility - #19950515

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 09/10/2002
Action: Staff Letter - #20020910

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 06/30/2004
Action: Staff Letter - #20040630

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 04/22/2005
Action: Staff Letter - #20050422

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 04/13/2004
Action: Staff Letter - #20040413

PUTNAM MAZDA (Continued) **1000307166**

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2015
Action: Electronic Reporting Submittal Due

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/01/2014
Action: Soil and Water Investigation Workplan - Addendum - Regulator Responded

Global Id: T0608100410
Action Type: RESPONSE
Date: 07/16/2015
Action: Corrective Action Plan / Remedial Action Plan - Regulator Responded

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 09/28/2009
Action: Staff Letter - #20090928

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 11/20/2007
Action: Staff Letter - #20071120

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 10/09/2014
Action: Technical Correspondence / Assistance / Other - #10/9/2014

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/08/2011
Action: Soil and Water Investigation Report

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 08/29/2003
Action: Staff Letter - #20030829

Global Id: T0608100410
Action Type: ENFORCEMENT

PUTNAM MAZDA (Continued) **1000307166**

Date: 08/21/2014
Action: Technical Correspondence / Assistance / Other - #20140821

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/31/2010
Action: Soil and Water Investigation Workplan

Global Id: T0608100410
Action Type: RESPONSE
Date: 10/29/2003
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 08/11/2009
Action: Staff Letter - #20090811

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 08/14/2013
Action: Staff Letter - #20130814

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 06/14/2012
Action: Staff Letter - #20120614

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 05/22/2014
Action: Staff Letter - #20140522

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 12/22/2009
Action: Technical Correspondence / Assistance / Other - #20091222

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/31/2016
Action: Well Installation Report

PUTNAM MAZDA (Continued) **1000307166**

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 10/09/2015
Action: Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 09/24/2014
Action: Site Visit / Inspection / Sampling - #20140924

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 03/04/2015
Action: Staff Letter - #20150304

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: Other
Date: 03/21/1985
Action: Leak Discovery

Global Id: T0608100410
Action Type: RESPONSE
Date: 04/30/2016
Action: Soil Vapor Intrusion Investigation Report

Global Id: T0608100410
Action Type: Other
Date: 03/26/1985
Action: Leak Reported

Global Id: T0608100410

PUTNAM MAZDA (Continued) **1000307166**

Action Type: ENFORCEMENT
Date: 07/15/2014
Action: Technical Correspondence / Assistance / Other - #20140715

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 11/24/2014
Action: Technical Correspondence / Assistance / Other - #20141124

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/16/2017
Action: Remedial Progress Report

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 05/13/2003
Action: Staff Letter - #20030513

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 01/13/2011
Action: Staff Letter - #20110113

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 03/05/2014
Action: Staff Letter - #20140305

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 07/28/2005
Action: Staff Letter - #20050728

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 09/09/2015
Action: Staff Letter - #20150909

Global Id: T0608100410
Action Type: RESPONSE
Date: 06/21/2005
Action: Correspondence

Global Id: T0608100410
Action Type: RESPONSE
Date: 04/05/2014
Action: Electronic Reporting Submittal Due

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2007

PUTNAM MAZDA (Continued) **1000307166**

Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/31/2016
Action: Other Report / Document

Global Id: T0608100410
Action Type: REMEDIATION
Date: 10/16/2008
Action: Free Product Removal

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 07/30/2008
Action: Staff Letter - #20080730

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 05/22/2013
Action: Staff Letter - #20130522

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 12/06/2002
Action: Correspondence

PUTNAM MAZDA (Continued) **1000307166**

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 01/14/2016
Action: Meeting - #20160114

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: RESPONSE
Date: 01/15/2013
Action: Pilot Study/ Treatability Report

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 12/15/2015
Action: Staff Letter - #20151215

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 09/14/2005
Action: Correspondence

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 10/14/2011
Action: Staff Letter - #20111014

Global Id: T0608100410
Action Type: RESPONSE
Date: 05/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE

PUTNAM MAZDA (Continued) **1000307166**

Date: 05/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 01/16/2014
Action: Notice of Violation - #20140116

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/06/2015
Action: Well Installation Report

Global Id: T0608100410
Action Type: RESPONSE
Date: 10/29/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 04/30/2015
Action: Soil Vapor Intrusion Investigation Report

Global Id: T0608100410
Action Type: RESPONSE
Date: 10/29/2003
Action: Soil and Water Investigation Report

Global Id: T0608100410
Action Type: REMEDIATION
Date: 01/01/2010
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 01/01/2009
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 04/01/2009
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 07/01/2009
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 01/01/2011
Action: Free Product Removal

PUTNAM MAZDA (Continued) **1000307166**

Global Id: T0608100410
Action Type: REMEDIATION
Date: 10/30/2008
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 07/01/2010
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 10/01/2009
Action: Free Product Removal

Global Id: T0608100410
Action Type: REMEDIATION
Date: 11/06/2012
Action: Other (Use Description Field)

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/14/2011
Action: Correspondence

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 09/10/2014
Action: Staff Letter - #20140910

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 12/03/2014
Action: Site Assessment Report

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 01/31/2014
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0608100410
Action Type: RESPONSE
Date: 11/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE

PUTNAM MAZDA (Continued) **1000307166**

Date: 02/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 02/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: RESPONSE
Date: 06/24/2003
Action: Electronic Reporting Submittal Due

Global Id: T0608100410
Action Type: RESPONSE
Date: 09/08/2004
Action: Soil and Water Investigation Report

Global Id: T0608100410
Action Type: RESPONSE
Date: 10/04/2004
Action: Site Assessment Report

Global Id: T0608100410
Action Type: RESPONSE
Date: 08/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100410
Action Type: ENFORCEMENT
Date: 04/14/2011
Action: Staff Letter - #20110414

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660026
Facility Status: 5C- Pollution Characterization
Global ID: T0608100410
APN Number: 029242240
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

FINDS:

Registry ID: 110002764508

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource

PUTNAM MAZDA (Continued) **1000307166**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0431

ECHO:

Envid:	1000307166
Registry ID:	110002764508
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002764508

AA620 **CHMIRS** **S117454885**
SE **BARROILHETT & EL CAMINO REAL** **N/A**
1/4-1/2 **SAN MATEO, CA 94401**
0.471 mi.
2486 ft. **Site 16 of 16 in cluster AA**

Relative:
Higher

Actual:
44 ft.

CHMIRS:

OES Incident Number:	4-7095
OES notification:	12/11/2014
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Yes
Waterway:	Storm Drain
Spill Site:	Road

(Continued) **S117454885**

Cleanup By:	No
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Type:	SEWAGE
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1400
Year:	2014
Agency:	City of San Mateo
Incident Date:	12/11/2014
Admin Agency:	Not reported
Amount:	Not reported
Contained:	Yes
Site Type:	Storm Drain
E Date:	Not reported
Substance:	Sanitary overflow w/ Storm Water
Quantity Released:	1.3
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Storm Surge
Number of Fatalities:	Not reported
#1 Pipeline:	No
#2 Pipeline:	No
#3 Pipeline:	No
#1 Vessel >= 300 Tons:	No
#2 Vessel >= 300 Tons:	No
#3 Vessel >= 300 Tons:	No
Evacs:	No
Injuries:	Other
Fatals:	No
Comments:	Not reported
Description:	This release from a manhole that was caused by a storm surge.

AJ621 **SHEN LINCOLN MERCURY MITSUBISHI** **HAZNET** **S113001669**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94014**
0.474 mi.
2502 ft. **Site 1 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113001669
Year:	2000
GEPAID:	CAD073936528
Contact:	MICHAEL SHEN/OWNER
Telephone:	4153428100
Mailing Name:	Not reported
Mailing Address:	888 NORTH SAN MATEO DRIVE
Mailing City,St,Zip:	SAN MATEO, CA 944014411
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent

SHEN LINCOLN MERCURY MITSUBISHI (Continued) **S113001669**

Disposal Method:	Transfer Station
Tons:	0.93
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	S113001669
Year:	1997
GEPAID:	CAD073936528
Contact:	MICHAEL SHEN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	888 NORTH SAN MATEO DRIVE
Mailing City,St,Zip:	SAN MATEO, CA 944014411
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Recycler
Tons:	.8340
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Recycler
Facility County:	San Mateo
envid:	S113001669
Year:	1997
GEPAID:	CAD073936528
Contact:	MICHAEL SHEN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	888 NORTH SAN MATEO DRIVE
Mailing City,St,Zip:	SAN MATEO, CA 944014411
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	.4587
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Recycler
Facility County:	San Mateo
envid:	S113001669
Year:	1997
GEPAID:	CAD073936528
Contact:	MICHAEL SHEN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	888 NORTH SAN MATEO DRIVE
Mailing City,St,Zip:	SAN MATEO, CA 944014411
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Contaminated soil from site clean-up
Disposal Method:	Disposal, Land Fill
Tons:	1.8000
Cat Decode:	Contaminated soil from site clean-up

SHEN LINCOLN MERCURY MITSUBISHI (Continued) **S113001669**

Method Decode:	Disposal, Land Fill
Facility County:	San Mateo
envid:	S113001669
Year:	1996
GEPAID:	CAD073936528
Contact:	MICHAEL SHEN
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	888 NORTH SAN MATEO DRIVE
Mailing City,St,Zip:	SAN MATEO, CA 944014411
Gen County:	Not reported
TSD EPA ID:	CAT080013352
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Recycler
Tons:	1.2510
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Recycler
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
5 additional CA_HAZNET: record(s) in the EDR Site Report.

AJ622 **PUTNAM AUTOMOTIVE FIAT & TOYOTA** **San Mateo Co. BI** **S113756029**
ESE **2-50 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 2 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0014577
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011945
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0014577
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004746
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0014577
Prog Element Code:	2352
Record Id:	PR0072073
Description:	TIER I: TANK STOR CAP =>1,320 & <5,000 GAL
Facility Status:	ACTIVE

AJ623 **SHEN-LINCOLN MERCURY** **RGA LUST** **S114690476**
ESE **2 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.474 mi.
2502 ft. **Site 3 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

2012	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2011	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2010	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2009	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2008	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2007	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2006	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2005	SHEN-LINCOLN MERCURY	2 CALIFORNIA
2003	SHEN-LINCOLN MERCURY	2 CALIFORNIA

AJ624 **SHEN-LINCOLN MERCURY** **LUST** **S100944971**
ESE **2 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 4 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660005
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	1/1/1965

AJ625 **SHEN MITSUBISHI** **RGA LUST** **S114690473**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.474 mi.
2502 ft. **Site 5 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

RGA LUST:

1998	SHEN MITSUBISHI	2 CALIFORNIA DR
1997	SHEN MITSUBISHI	2 CALIFORNIA DR

AJ626 **SHEN MITSUBISHI** **San Mateo Co. BI** **S113756637**
ESE **2 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 6 of 35 in cluster AJ**

Relative: **Higher**

Actual: **33 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0018045
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011859
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018045
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004714
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

AJ627 **PUTNAM LINCOLN MERCURY** **HAZNET** **S113083382**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 7 of 35 in cluster AJ**

Relative: **Higher**

Actual: **33 ft.**

HAZNET:

envid:	S113083382
Year:	2002
GEPAID:	CAL000153763
Contact:	DAVID MARTINEZ/SERVICE MGR
Telephone:	6503428600
Mailing Name:	Not reported
Mailing Address:	2 CALIFORNIA DR
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	0.25
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

AJ628 **SHEN-MITSUBISHI** **RGA LUST** **S114690478**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.474 mi.
2502 ft. **Site 8 of 35 in cluster AJ**

Relative: **Higher**

Actual: **33 ft.**

RGA LUST:

1996	SHEN-MITSUBISHI	2 CALIFORNIA DR
1995	SHEN-MITSUBISHI	2 CALIFORNIA DR
1994	SHEN-MITSUBISHI	2 CALIFORNIA DR
1993	SHEN-MITSUBISHI	2 CALIFORNIA DR

AJ629 **PUTNAM LINCOLN MERCURY** **RCRA-SQG** **1000305500**
ESE **2 CALIFORNIA DR** **LUST** **CAD073936528**
1/4-1/2 **BURLINGAME, CA 94012** **HIST CORTESE**
0.474 mi.
2502 ft. **Site 9 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

RCRA-SQG:

Date form received by agency:	07/25/2000
Facility name:	PUTNAM LINCOLN MERCURY
Facility address:	2 CALIFORNIA DR BURLINGAME, CA 94012
EPA ID:	CAD073936528
Contact:	PAT OBRIEN
Contact address:	2 CALIFORNIA DR BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(650) 342-8600
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	J AND K MOTORS
Owner/operator address:	3 CALIFORNIA DR BURLINGAME, CA 94010
Owner/operator country:	Not reported
Owner/operator telephone:	(650) 342-8600
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

PUTNAM LINCOLN MERCURY (Continued) **1000305500**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

LUST:
Region: STATE
Global Id: T0608100495
Latitude: 37.577388
Longitude: -122.339307
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/30/2004
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0519
LOC Case Number: 660005
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100495
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100495
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100495
Status: Completed - Case Closed
Status Date: 07/30/2004

Global Id: T0608100495
Status: Open - Case Begin Date
Status Date: 03/02/1988

PUTNAM LINCOLN MERCURY (Continued) **1000305500**

Global Id: T0608100495
Status: Open - Verification Monitoring
Status Date: 03/02/1988

Regulatory Activities:
Global Id: T0608100495
Action Type: ENFORCEMENT
Date: 10/03/1989
Action: Notice of Responsibility - #1

Global Id: T0608100495
Action Type: ENFORCEMENT
Date: 07/30/2004
Action: Closure/No Further Action Letter - #20040730

Global Id: T0608100495
Action Type: ENFORCEMENT
Date: 06/13/2003
Action: Staff Letter - #20030613

Global Id: T0608100495
Action Type: Other
Date: 10/06/1989
Action: Leak Discovery

Global Id: T0608100495
Action Type: Other
Date: 03/02/1988
Action: Leak Reported

Global Id: T0608100495
Action Type: ENFORCEMENT
Date: 03/30/2004
Action: Staff Letter - #20040330

Global Id: T0608100495
Action Type: RESPONSE
Date: 10/31/2003
Action: Other Report / Document

Global Id: T0608100495
Action Type: RESPONSE
Date: 07/30/2004
Action: Unknown

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660005
Facility Status: 9- Case Closed
Global ID: T0608100495
APN Number: 029243070
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

PUTNAM LINCOLN MERCURY (Continued) **1000305500**

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0519

AJ630 **PUTNAM TOYOTA** **San Mateo Co. BI** **S113757758**
ESE **2 CALIFORNIA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 10 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027496
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0043749
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0027496
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0043750
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

AJ631 **PUTNAM AUTOMOTIVE** **EMI** **S106921349**
ESE **2 CALIFORNIA DRIVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 11 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

EMI:
Year: 2003
County Code: 41
Air Basin: SF
Facility ID: 14915
Air District Name: BA
SIC Code: 5511
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Year: 2004
County Code: 41
Air Basin: SF
Facility ID: 14915
Air District Name: BA

PUTNAM AUTOMOTIVE (Continued) **S106921349**

SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.006
Reactive Organic Gases Tons/Yr:	0.0050202
Carbon Monoxide Emissions Tons/Yr:	0.016
NOX - Oxides of Nitrogen Tons/Yr:	0.073
SOX - Oxides of Sulphur Tons/Yr:	0.002
Particulate Matter Tons/Yr:	0.005
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.00488

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14915
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.005
Reactive Organic Gases Tons/Yr:	.0041835
Carbon Monoxide Emissions Tons/Yr:	.013
NOX - Oxides of Nitrogen Tons/Yr:	.059
SOX - Oxides of Sulphur Tons/Yr:	.002
Particulate Matter Tons/Yr:	.004
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.003904

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14915
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.0000000000000001E-3
Reactive Organic Gases Tons/Yr:	2.5100999999999999E-3
Carbon Monoxide Emissions Tons/Yr:	8.0000000000000002E-3
NOX - Oxides of Nitrogen Tons/Yr:	0.039
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00307377049180327
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.0000000000000001E-3

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14915
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101

PUTNAM AUTOMOTIVE (Continued) **S106921349**

Carbon Monoxide Emissions Tons/Yr:	0.008
NOX - Oxides of Nitrogen Tons/Yr:	0.039
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14915
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.008
NOX - Oxides of Nitrogen Tons/Yr:	0.039
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0030737704918
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.003

AJ632 **SHEN-LINCOLN MERCURY** **RGA LUST** **S114690475**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.474 mi.
2502 ft. **Site 12 of 35 in cluster AJ**

Relative:
Higher

RGA LUST:

1992	SHEN-LINCOLN MERCURY	2 CALIFORNIA DR

Actual:
33 ft.

AJ633 **SHEN LINCOLN MERCURY** **RGA LUST** **S114690472**
ESE **2 CALIFORNIA DR** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.474 mi.
2502 ft. **Site 13 of 35 in cluster AJ**

Relative:
Higher

RGA LUST:

2002	SHEN LINCOLN MERCURY	2 CALIFORNIA DR
2001	SHEN LINCOLN MERCURY	2 CALIFORNIA DR
2000	SHEN LINCOLN MERCURY	2 CALIFORNIA DR

Actual:
33 ft.

AJ634 **PUTNAM AUTOMOTIVE** **FINDS** **1011976741**
ESE **2 CALIFORNIA DRIVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2502 ft. **Site 14 of 35 in cluster AJ**

Relative:
Higher

FINDS:

Registry ID: 110038091891

Actual:
33 ft.

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

PUTNAM AUTOMOTIVE (Continued) **1011976741**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1011976741
Registry ID: 110038091891
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038091891

Z635 **LYNETTE ADAMS** **HAZNET** **S113464024**
NE **609 VERNON WAY** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.474 mi.
2504 ft. **Site 5 of 5 in cluster Z**

Relative:
Lower

Actual:
19 ft.

HAZNET:
envid: S113464024
Year: 2010
GEPAID: CAC002659826
Contact: LYNETTE ADAMS
Telephone: 6503332550
Mailing Name: Not reported
Mailing Address: 609 VERNON WAY
Mailing City,St,Zip: BURLINGAME, CA 940102817
Gen County: Not reported
TSD EPA ID: CAD982444481
TSD County: Not reported
Waste Category: Household waste
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.15
Cat Decode: Household waste
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

AI636 **GARY YEUNG** **HAZNET** **S118205217**
WSW **15 SUMMERHOLME PL** **N/A**
1/4-1/2 **HILLSBOROUGH, CA 94010**
0.475 mi.
2508 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
55 ft.

HAZNET:
envid: S118205217
Year: 2014
GEPAID: CAC002764816
Contact: GARY YEUNG
Telephone: 6503431101
Mailing Name: Not reported
Mailing Address: 15 SUMMERHOLME PL
Mailing City,St,Zip: HILLSBOROUGH, CA 940106440
Gen County: San Mateo

GARY YEUNG (Continued) **S118205217**

TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	1.6
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AK637 **ELLEN GRUBER** **HAZNET** **S113770942**
NW **840 EDGEHILL DR** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.475 mi.
2510 ft. **Site 1 of 2 in cluster AK**

Relative: **Lower**

Actual: **16 ft.**

HAZNET:

envid:	S113770942
Year:	2012
GEPAID:	CAC002682629
Contact:	ELLEN GRUBER
Telephone:	8316481651
Mailing Name:	Not reported
Mailing Address:	2918 BIRD ROCK RD
Mailing City,St,Zip:	PEBBLE BEACH, CA 93953
Gen County:	San Mateo
TSD EPA ID:	CAD982042475
TSD County:	Solano
Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

AH638 **PRIVATE RESIDENCE** **LUST** **S110655274**
SW **PRIVATE RESIDENCE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.482 mi.
2546 ft. **Site 2 of 10 in cluster AH**

Relative: **Higher**

Actual: **53 ft.**

LUST:

Region:	STATE
Global Id:	T0608125944
Latitude:	37.582976
Longitude:	-122.331343
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/30/2007
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported

PRIVATE RESIDENCE (Continued) **S110655274**

LOC Case Number: 668098
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608125944
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608125944
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608125944
Status: Completed - Case Closed
Status Date: 10/30/2007

Global Id: T0608125944
Status: Open - Case Begin Date
Status Date: 01/27/2005

Global Id: T0608125944
Status: Open - Remediation
Status Date: 08/03/2005

Global Id: T0608125944
Status: Open - Site Assessment
Status Date: 03/23/2005

Global Id: T0608125944
Status: Open - Verification Monitoring
Status Date: 11/30/2006

Regulatory Activities:
Global Id: T0608125944
Action Type: Other
Date: 01/27/2005
Action: Leak Discovery

Global Id: T0608125944
Action Type: REMEDIATION
Date: 08/03/2005

PRIVATE RESIDENCE (Continued) **S110655274**

Action: Excavation

Global Id: T0608125944
Action Type: Other
Date: 02/24/2005
Action: Leak Reported

Global Id: T0608125944
Action Type: RESPONSE
Date: 05/23/2005
Action: Preliminary Site Assessment Workplan

Global Id: T0608125944
Action Type: RESPONSE
Date: 09/22/2005
Action: CAP/RAP - Other Report

Global Id: T0608125944
Action Type: ENFORCEMENT
Date: 03/23/2005
Action: Notice of Responsibility - #20050323

Global Id: T0608125944
Action Type: ENFORCEMENT
Date: 10/30/2007
Action: Closure/No Further Action Letter - #20071030

Global Id: T0608125944
Action Type: ENFORCEMENT
Date: 05/26/2005
Action: Staff Letter - #20050526

Region: STATE
Global Id: T10000002008
Latitude: 37.573561364969
Longitude: -122.352958694101
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/15/2015
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 668102
File Location: All Files are on GeoTracker or in the Local Agency Database
Potential Media Affect: Soil, Surface water
Potential Contaminants of Concern: Diesel, Heating Oil / Fuel Oil
Site History: Site was opened in march 22, 2010. Initial workplan is due 10/22/2010.
Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T10000002008
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)

PRIVATE RESIDENCE (Continued) **S110655274**

Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T10000002008
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T10000002008
Status: Completed - Case Closed
Status Date: 07/15/2015

Global Id: T10000002008
Status: Open - Case Begin Date
Status Date: 03/22/2010

Global Id: T10000002008
Status: Open - Eligible for Closure
Status Date: 12/27/2014

Global Id: T10000002008
Status: Open - Site Assessment
Status Date: 05/06/2010

Regulatory Activities:
Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 03/31/2015
Action: Staff Letter

Global Id: T10000002008
Action Type: RESPONSE
Date: 12/20/2013
Action: Site Assessment Report - Regulator Responded

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 01/22/2015
Action: Notification - Public Notice of Case Closure - #20150122

Global Id: T10000002008
Action Type: RESPONSE
Date: 02/15/2013
Action: Monitoring Report - Quarterly

Global Id: T10000002008
Action Type: RESPONSE
Date: 08/28/2015
Action: Well Destruction Report

PRIVATE RESIDENCE (Continued) **S110655274**

Global Id: T10000002008
Action Type: RESPONSE
Date: 10/22/2010
Action: Soil and Water Investigation Workplan

Global Id: T10000002008
Action Type: RESPONSE
Date: 05/15/2013
Action: Monitoring Report - Quarterly

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 08/22/2013
Action: Staff Letter - #20130822

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 05/11/2010
Action: Staff Letter - #2010511

Global Id: T10000002008
Action Type: RESPONSE
Date: 05/16/2014
Action: Sensitive Receptor Survey Report

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 04/17/2013
Action: Staff Letter - #20130417

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 01/22/2013
Action: Staff Letter - #20130113

Global Id: T10000002008
Action Type: RESPONSE
Date: 06/25/2010
Action: Verbal Communication

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 07/15/2015
Action: Closure/No Further Action Letter - #20150715

Global Id: T10000002008
Action Type: Other
Date: 03/22/2010
Action: Leak Discovery

Global Id: T10000002008
Action Type: RESPONSE
Date: 05/15/2014
Action: Monitoring Report - Quarterly

Global Id: T10000002008
Action Type: Other

PRIVATE RESIDENCE (Continued) **S110655274**

Date: 03/22/2010
Action: Leak Reported

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 07/08/2010
Action: Staff Letter - #20100708

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 09/08/2011
Action: Staff Letter - #20110908

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 03/03/2011
Action: Staff Letter - #20110303

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 12/04/2013
Action: Staff Letter - #20131204

Global Id: T10000002008
Action Type: RESPONSE
Date: 06/03/2014
Action: Monitoring Report - Quarterly

Global Id: T10000002008
Action Type: ENFORCEMENT
Date: 11/30/2010
Action: Staff Letter - #20101130

Global Id: T10000002008
Action Type: Other
Date: 03/22/2010
Action: Leak Stopped

Global Id: T10000002008
Action Type: RESPONSE
Date: 06/03/2011
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T10000002008
Action Type: RESPONSE
Date: 04/15/2011
Action: Preliminary Site Assessment Report - Regulator Responded

Global Id: T10000002008
Action Type: RESPONSE
Date: 01/13/2012
Action: Site Assessment Report - Regulator Responded

Global Id: T10000002008
Action Type: RESPONSE
Date: 08/15/2014
Action: Monitoring Report - Quarterly

PRIVATE RESIDENCE (Continued) **S110655274**

Global Id: T10000002008
Action Type: RESPONSE
Date: 06/19/2013
Action: Soil and Water Investigation Workplan - Regulator Responded

---

AH639 **SHUBINER PROPERTY** **LUST** **S103892228**
SSW **1715 RALSTON** **HIST CORTESE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.492 mi.
2598 ft. **Site 3 of 10 in cluster AH**

Relative:
Higher

Actual:
59 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 668078
Facility Status: 9- Case Closed
Global ID: T0608100938
APN Number: 028313030
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1025

AH640 **SHUBINER PROPERTY** **RGA LUST** **S114690814**
SSW **1715 RALSTON AVE** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.492 mi.
2598 ft. **Site 4 of 10 in cluster AH**

Relative:
Higher

Actual:
59 ft.

RGA LUST:

2002	SHUBINER PROPERTY	1715 RALSTON AVE
2001	SHUBINER PROPERTY	1715 RALSTON AVE
2000	SHUBINER PROPERTY	1715 RALSTON AVE
1998	SHUBINER PROPERTY	1715 RALSTON AVE
1997	SHUBINER PROPERTY	1715 RALSTON AVE

AH641 **SHUBINER PROPERTY** **RGA LUST** **S114690815**
SSW **1715 RALSTON** **N/A**
1/4-1/2 **BURLINGAME, CA**
0.492 mi.
2598 ft. **Site 5 of 10 in cluster AH**

Relative:
Higher

Actual:
59 ft.

RGA LUST:

2009	SHUBINER PROPERTY	1715 RALSTON
2008	SHUBINER PROPERTY	1715 RALSTON
2007	SHUBINER PROPERTY	1715 RALSTON
2006	SHUBINER PROPERTY	1715 RALSTON
2005	SHUBINER PROPERTY	1715 RALSTON
2003	SHUBINER PROPERTY	1715 RALSTON

AH642 **RESIDENCE** **San Mateo Co. BI** **S113757117**
SSW **1715 RALSTON** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.492 mi.
2598 ft. **Site 6 of 10 in cluster AH**

Relative:
Higher

Actual:
59 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0024323
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0028909
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AH643 **JEFF & ADRIENNE SCHUBINER** **HAZNET** **S112870882**
SSW **1715 RALSTON AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.492 mi.
2598 ft. **Site 7 of 10 in cluster AH**

Relative:
Higher

Actual:
59 ft.

HAZNET:

envid:	S112870882
Year:	1997
GEPAID:	CAC001164984
Contact:	JEFF & ADRIENNE SCHUBINER
Telephone:	4153477353
Mailing Name:	Not reported
Mailing Address:	1001 SNEATH LANE STE 112
Mailing City,St,Zip:	SAN BRUNO, CA 940660000
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Waste oil and mixed oil
Disposal Method:	Not reported
Tons:	.4170
Cat Decode:	Waste oil and mixed oil
Method Decode:	Not reported
Facility County:	San Mateo

envid:	S112870882
Year:	1997
GEPAID:	CAC001164984
Contact:	JEFF & ADRIENNE SCHUBINER
Telephone:	4153477353
Mailing Name:	Not reported
Mailing Address:	1001 SNEATH LANE STE 112
Mailing City,St,Zip:	SAN BRUNO, CA 940660000
Gen County:	Not reported
TSD EPA ID:	CAD009466392
TSD County:	Not reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	.1500
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

AJ644 **VERACOM AUTOMOTIVE GROUP DBA VERACOM MITSUBISHI** **HAZNET** **S113141628**
ESE **885 N SAN MATEO DR** **N/A**
1/4-1/2 **SAN MATEO, CA 94401**
0.493 mi.
2603 ft. **Site 15 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

HAZNET:

envid:	S113141628
Year:	2009
GEPAID:	CAL000304666
Contact:	PHILIP BRANZUELA
Telephone:	6503407199
Mailing Name:	Not reported
Mailing Address:	790 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 94401
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.22935
Cat Decode:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

AJ645 **VERACOM AUTOMOTIVE GROUP** **San Mateo Co. BI** **S108937492**
ESE **885 SAN MATEO** **N/A**
1/4-1/2 **SAN MATEO, CA 94401**
0.493 mi.
2603 ft. **Site 16 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0036915
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0053774
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0036915
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0053773
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AJ646 **PUTNAM VOLVO** **San Mateo Co. BI** **S113758979**
ESE **900 PENINSULA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 17 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0050090
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT

PUTNAM VOLVO (Continued) **S113758979**

Record Id: PR0068546
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0050090
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0068545
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0050090
Prog Element Code: 2352
Record Id: PR0068550
Description: TIER I: TANK STOR CAP =>1,320 & <5,000 GAL
Facility Status: ACTIVE

AJ647 **PUTNAM BUICK INC** **San Mateo Co. BI** **S113755328**
ESE **900 PENINSULA** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 18 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0006097
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011882
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0006097
Prog Element Code: STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id: PR0004659
Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: INACTIVE

AJ648 **PUTNAM AUTOMOTIVE** **EMI** **S106837806**
ESE **900 PENINSULA AVENUE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 19 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

EMI:
Year: 1990
County Code: 41
Air Basin: SF
Facility ID: 3817
Air District Name: BA
SIC Code: 7532
Air District Name: BAY AREA AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2

PUTNAM AUTOMOTIVE (Continued) **S106837806**

Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.026
Reactive Organic Gases Tons/Yr:	0.0217542
Carbon Monoxide Emissions Tons/Yr:	0.071
NOX - Oxides of Nitrogen Tons/Yr:	0.328
SOX - Oxides of Sulphur Tons/Yr:	0.01
Particulate Matter Tons/Yr:	0.023
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.022448

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.006
NOX - Oxides of Nitrogen Tons/Yr:	.029
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

PUTNAM AUTOMOTIVE (Continued) **S106837806**

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.002
Reactive Organic Gases Tons/Yr:	.0016734
Carbon Monoxide Emissions Tons/Yr:	.006
NOX - Oxides of Nitrogen Tons/Yr:	.029
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	.002
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.001952

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.4000000000000002E-2
Reactive Organic Gases Tons/Yr:	2.8447799999999999E-2
Carbon Monoxide Emissions Tons/Yr:	0.10199999999999999
NOX - Oxides of Nitrogen Tons/Yr:	0.46899999999999997
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	3.4000000000000002E-2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.3183999999999998E-2

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.0000000000000001E-3
Reactive Organic Gases Tons/Yr:	2.5100999999999999E-3
Carbon Monoxide Emissions Tons/Yr:	8.0000000000000002E-3
NOX - Oxides of Nitrogen Tons/Yr:	3.6999999999999998E-2
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00307377049180327
Part. Matter 10 Micrometers and Smllr Tons/Yr:	3.0000000000000001E-3

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511

PUTNAM AUTOMOTIVE (Continued) **S106837806**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.008
NOX - Oxides of Nitrogen Tons/Yr:	0.037
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14913
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.003
Reactive Organic Gases Tons/Yr:	0.0025101
Carbon Monoxide Emissions Tons/Yr:	0.008
NOX - Oxides of Nitrogen Tons/Yr:	0.037
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0030737704918
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.003

AJ649 **EDR Hist Auto** **1015666708**
ESE **900 PENINSULA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 20 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

EDR Historical Auto Stations:

Name:	PUTNAM BUICK PONTIAC BODY SHOP INC
Year:	2005
Address:	900 PENINSULA AVE
Name:	PUTNAM BUICK PONTIAC BODY SHOP INC
Year:	2006
Address:	900 PENINSULA AVE
Name:	PUTNAM BUICK PONTIAC BODY SHOP
Year:	2007
Address:	900 PENINSULA AVE

AJ650 **PUTNAM AUTOMOTIVE** **FINDS** **1011990890**
ESE **900 PENINSULA AVENUE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 21 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

FINDS:

Registry ID: 110038016982

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

ECHO:
Envid: 1011990890
Registry ID: 110038016982
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110038016982

AJ651 **PUTNAM BUICK PONTIAC GMC** **FINDS** **1008152782**
ESE **900 PENINSULA AVE** **ECHO** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 22 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

FINDS:

Registry ID: 110018964389

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

ECHO:
Envid: 1008152782
Registry ID: 110018964389
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110018964389

AJ652 **PUTNAM BUICK PONTIAC GMC** **HAZNET** **S113015795**
ESE **900 PENINSULA AVE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.498 mi.
2629 ft. **Site 23 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

HAZNET:
envid: S113015795
Year: 2014
GEPAID: CAD982409344
Contact: BEN POMEROY-PARTS MGR
Telephone: 6503429500
Mailing Name: Not reported
Mailing Address: PO BOX 588
Mailing City,St,Zip: BURLINGAME, CA 940110588
Gen County: San Mateo

PUTNAM BUICK PONTIAC GMC (Continued) **S113015795**

TSD EPA ID: UTD981552177
TSD County: 99
Waste Category: Unspecified organic liquid mixture
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.0875
Cat Decode: Unspecified organic liquid mixture
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: San Mateo

envid: S113015795
Year: 2014
GEPAID: CAD982409344
Contact: BEN POMEROY-PARTS MGR
Telephone: 6503429500
Mailing Name: Not reported
Mailing Address: PO BOX 588
Mailing City,St,Zip: BURLINGAME, CA 940110588
Gen County: San Mateo
TSD EPA ID: CAD980887418
TSD County: Alameda
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.6255
Cat Decode: Aqueous solution with total organic residues 10 percent or more
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: S113015795
Year: 2013
GEPAID: CAD982409344
Contact: MARK CORSO
Telephone: 6503424321
Mailing Name: Not reported
Mailing Address: PO BOX 588
Mailing City,St,Zip: BURLINGAME, CA 940110588
Gen County: San Mateo
TSD EPA ID: CAD980887418
TSD County: Alameda
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.06255
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: Not reported

envid: S113015795
Year: 2013
GEPAID: CAD982409344
Contact: MARK CORSO
Telephone: 6503424321
Mailing Name: Not reported
Mailing Address: PO BOX 588
Mailing City,St,Zip: BURLINGAME, CA 940110588

PUTNAM BUICK PONTIAC GMC (Continued) **S113015795**

Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.3753
Cat Decode:	Not reported
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	Not reported
envid:	S113015795
Year:	2013
GEPAID:	CAD982409344
Contact:	MARK CORSO
Telephone:	6503424321
Mailing Name:	Not reported
Mailing Address:	PO BOX 588
Mailing City,St,Zip:	BURLINGAME, CA 940110588
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.125
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

Click this hyperlink while viewing on your computer to access
68 additional CA_HAZNET: record(s) in the EDR Site Report.

AJ653 **DUTNAM HYUNDAI** **RCRA-SQG** **1000307167**
ESE **900 PENINSULA AVE** **FINDS** **CAD982409344**
1/4-1/2 **BURLINGAME, CA 94010** **ECHO**
0.498 mi.
2629 ft. **Site 24 of 35 in cluster AJ**

Relative:
Higher

Actual:
32 ft.

RCRA-SQG:

Date form received by agency:	03/25/1988
Facility name:	DUTNAM HYUNDAI
Facility address:	900 PENINSULA AVE BURLINGAME, CA 94010
EPA ID:	CAD982409344
Mailing address:	PO BOX 707 BURLINGAME, CA 94011
Contact:	ENVIRONMENTAL MANAGER
Contact address:	900 PENINSULA AVE BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 347-4277
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous

DUTNAM HYUNDAI (Continued) **1000307167**

waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	PUTNAM HYUNDAI
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110009544751

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

DUTNAM HYUNDAI (Continued) **1000307167**

ECHO:
Envid: 1000307167
Registry ID: 110009544751
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110009544751

AH654 **PRIVATE RESIDENCE** **LUST** **S110655246**
SSW **PRIVATE RESIDENCE** **N/A**
1/4-1/2 **BURLINGAME, CA 94010**
0.500 mi.
2640 ft. **Site 8 of 10 in cluster AH**

Relative:
Higher

Actual:
60 ft.

LUST:
Region: STATE
Global Id: T0608100938
Latitude: 37.572897
Longitude: -122.352235
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 04/01/1997
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1025
LOC Case Number: 668078
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100938
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100938
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100938
Status: Completed - Case Closed
Status Date: 04/01/1997

Global Id: T0608100938
Status: Open - Case Begin Date

PRIVATE RESIDENCE (Continued) **S110655246**

Status Date: 03/21/1997

Regulatory Activities:
Global Id: T0608100938
Action Type: ENFORCEMENT
Date: 03/21/1997
Action: Notice of Responsibility - #1

Global Id: T0608100938
Action Type: Other
Date: 03/13/1997
Action: Leak Reported

---

655 **CROCKER ESTATE** **San Mateo Co. BI** **S106981769**
South **1178 BARROIHET** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.500 mi.
2642 ft.

Relative:
Higher

Actual:
59 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0023670
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0027497
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AH656 **UST SITE** **San Mateo Co. BI** **S113758785**
SW **310 PEPPER** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.502 mi.
2652 ft. **Site 9 of 10 in cluster AH**

Relative:
Higher

Actual:
53 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0045755
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0060929
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AH657 **OFFIELD ESTATE TRUST** **LUST** **S113458158**
SW **310 PEPPER AVE** **HAZNET** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.502 mi.
2652 ft. **Site 10 of 10 in cluster AH**

Relative:
Higher

Actual:
53 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 668102
Facility Status: 9- Case Closed
Global ID: Not reported
APN Number: 028311110

OFFIELD ESTATE TRUST (Continued) **S113458158**

Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HAZNET:
envid: S113458158
Year: 2010
GEPAID: CAC002649959
Contact: DONNA COLSIN
Telephone: 6506780952
Mailing Name: Not reported
Mailing Address: 2616 HALE DR
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: Not reported
TSD EPA ID: NVD982358483
TSD County: Not reported
Waste Category: Unspecified oil-containing waste
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 2.085
Cat Decode: Unspecified oil-containing waste
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

envid: S113458158
Year: 2010
GEPAID: CAC002649959
Contact: DONNA COLSIN
Telephone: 6506780952
Mailing Name: Not reported
Mailing Address: 2616 HALE DR
Mailing City,St,Zip: BURLINGAME, CA 94010
Gen County: Not reported
TSD EPA ID: CAD009466392
TSD County: Not reported
Waste Category: Other empty containers 30 gallons or more
Disposal Method: Other Treatment
Tons: 0.25
Cat Decode: Other empty containers 30 gallons or more
Method Decode: Other Treatment
Facility County: San Mateo

AK658 **EDR Hist Auto** **1015659357**
NW **867 CALIFORNIA DR** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.507 mi.
2675 ft. **Site 2 of 2 in cluster AK**

Relative:
Lower

Actual:
16 ft.

EDR Historical Auto Stations:
Name: BILLS AUTO UPHOLSTERY
Year: 2001
Address: 867 CALIFORNIA DR

Name: BILLS AUTO & BOAT UPHLSTRY
Year: 2003
Address: 867 CALIFORNIA DR

(Continued) **1015659357**

Name: BILLS AUTO & BOAT UPHLSTRY
Year: 2004
Address: 867 CALIFORNIA DR

Name: BILLS AUTO UPHOLSTERY
Year: 2008
Address: 867 CALIFORNIA DR

Name: BILLS AUTO & BOAT UPHOLSTERY
Year: 2009
Address: 867 CALIFORNIA DR

Name: BILLS AUTO & BOAT UPHOLSTERY
Year: 2010
Address: 867 CALIFORNIA DR

Name: BILLS AUTO & BOAT UPHOLSTERY
Year: 2011
Address: 867 CALIFORNIA DR

Name: BILLS AUTO & BOAT UPHOLSTERY
Year: 2012
Address: 867 CALIFORNIA DR

AF659 **T MOBILE WEST CORP SF13046A** **San Mateo Co. BI** **S113758730**
NNW **777 MORRELL** **N/A**
1/2-1 **BURLINGAME, CA 94066**
0.516 mi.
2725 ft. **Site 2 of 2 in cluster AF**

Relative:
Lower

Actual:
13 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0045344
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0058986
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

AJ660 **SHEN LINCOLN MERCURY** **RCRA-SQG** **1000597461**
ESE **888 N SAN MATEO AVE** **LUST** **CAD983614744**
1/2-1 **SAN MATEO, CA 94401** **FINDS**
0.518 mi. **HAZNET**
2733 ft. **Site 25 of 35 in cluster AJ** **ECHO**

Relative:
Higher

Actual:
33 ft.

RCRA-SQG:
Date form received by agency: 06/30/1992
Facility name: SHEN LINCOLN MERCURY
Facility address: 888 N SAN MATEO AVE
SAN MATEO, CA 94401
EPA ID: CAD983614744
Mailing address: N SAN MATEO AVE
SAN MATEO, CA 94401
Contact: PAT OBRIEN
Contact address: 888 N SAN MATEO AVE
SAN MATEO, CA 94401
Contact country: US

SHEN LINCOLN MERCURY (Continued) **1000597461**

Contact telephone: (415) 342-8601
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: MICHAEL SHEN
Owner/operator address: 888 N SAN MATEO AVE
SAN MATEO, CA 94401
Owner/operator country: Not reported
Owner/operator telephone: (415) 342-8600
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 119177
Facility Status: 9- Case Closed
Global ID: TI0000003682
APN Number: 032121210
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

FINDS:

Registry ID: 110002865935

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

SHEN LINCOLN MERCURY (Continued) **1000597461**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

envid:	1000597461
Year:	1999
GEPAID:	CAD983614744
Contact:	MICHAEL SHEN
Telephone:	4153428600
Mailing Name:	Not reported
Mailing Address:	888 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012261
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues 10 percent or more
Disposal Method:	Transfer Station
Tons:	1.5720
Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	1000597461
Year:	1999
GEPAID:	CAD983614744
Contact:	MICHAEL SHEN
Telephone:	4153428600
Mailing Name:	Not reported
Mailing Address:	888 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012261
Gen County:	Not reported
TSD EPA ID:	CAD093459485
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Treatment, Tank
Tons:	2.7637
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Treatment, Tank
Facility County:	San Mateo

envid:	1000597461
Year:	1999
GEPAID:	CAD983614744
Contact:	MICHAEL SHEN
Telephone:	4153428600
Mailing Name:	Not reported
Mailing Address:	888 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012261
Gen County:	Not reported
TSD EPA ID:	CA0000084517
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Treatment, Tank
Tons:	1.3506

SHEN LINCOLN MERCURY (Continued) **1000597461**

Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Treatment, Tank
Facility County: San Mateo

envid: 1000597461
Year: 1999
GEPAID: CAD983614744
Contact: MICHAEL SHEN
Telephone: 4153428600
Mailing Name: Not reported
Mailing Address: 888 N SAN MATEO DR
Mailing City,St,Zip: SAN MATEO, CA 944012261
Gen County: Not reported
TSD EPA ID: CAD093459485
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Not reported
Tons: .2668
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Not reported
Facility County: San Mateo

envid: 1000597461
Year: 1998
GEPAID: CAD983614744
Contact: MICHAEL SHEN
Telephone: 4153428600
Mailing Name: Not reported
Mailing Address: 888 N SAN MATEO DR
Mailing City,St,Zip: SAN MATEO, CA 944012261
Gen County: Not reported
TSD EPA ID: CAL000161743
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Transfer Station
Tons: 3.0441
Cat Decode: Aqueous solution with total organic residues 10 percent or more
Method Decode: Transfer Station
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
9 additional CA_HAZNET: record(s) in the EDR Site Report.

ECHO:
Envid: 1000597461
Registry ID: 110002865935
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002865935

AJ661 **SHEN LINCOLN MERCURY** **SLIC** **S106981276**
ESE **888 SAN MATEO** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401** **NPDES**
0.518 mi.
2733 ft. **Site 26 of 35 in cluster AJ**

Relative:
Higher

Actual:
33 ft.

SLIC:

Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	10/07/2014
Global Id:	T10000003682
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	119177
Latitude:	37.57697
Longitude:	-122.338327
Case Type:	Cleanup Program Site
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Cleanup planned for PCE area.

Click here to access the California GeoTracker records for this facility:

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0012852
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0010796
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012852
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0003468
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

NPDES:

Npdes Number:	CAS000002
Facility Status:	Terminated
Agency Id:	0
Region:	2
Regulatory Measure Id:	427255
Order No:	2009-0009-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	2 41C363684
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	05/21/2012
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	05/19/2014
Discharge Name:	BIT Holdings Sixty Nine Inc
Discharge Address:	1601 K Street NW

SHEN LINCOLN MERCURY (Continued) **S106981276**

Discharge City:	Washington
Discharge State:	District of Columbia
Discharge Zip:	20006
RECEIVED DATE:	Not reported
PROCESSED DATE:	Not reported
STATUS CODE NAME:	Not reported
STATUS DATE:	Not reported
PLACE SIZE:	Not reported
PLACE SIZE UNIT:	Not reported
FACILITY CONTACT NAME:	Not reported
FACILITY CONTACT TITLE:	Not reported
FACILITY CONTACT PHONE:	Not reported
FACILITY CONTACT PHONE EXT:	Not reported
FACILITY CONTACT EMAIL:	Not reported
OPERATOR NAME:	Not reported
OPERATOR ADDRESS:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR CONTACT NAME:	Not reported
OPERATOR CONTACT TITLE:	Not reported
OPERATOR CONTACT PHONE:	Not reported
OPERATOR CONTACT PHONE EXT:	Not reported
OPERATOR CONTACT EMAIL:	Not reported
OPERATOR TYPE:	Not reported
DEVELOPER NAME:	Not reported
DEVELOPER ADDRESS:	Not reported
DEVELOPER CITY:	Not reported
DEVELOPER STATE:	Not reported
DEVELOPER ZIP:	Not reported
DEVELOPER CONTACT NAME:	Not reported
DEVELOPER CONTACT TITLE:	Not reported
CONSTYPE LINEAR UTILITY IND:	Not reported
EMERGENCY PHONE NO:	Not reported
EMERGENCY PHONE EXT:	Not reported
CONSTYPE ABOVE GROUND IND:	Not reported
CONSTYPE BELOW GROUND IND:	Not reported
CONSTYPE CABLE LINE IND:	Not reported
CONSTYPE COMM LINE IND:	Not reported
CONSTYPE COMMERTIAL IND:	Not reported
CONSTYPE ELECTRICAL LINE IND:	Not reported
CONSTYPE GAS LINE IND:	Not reported
CONSTYPE INDUSTRIAL IND:	Not reported
CONSTYPE OTHER DESRIPTION:	Not reported
CONSTYPE OTHER IND:	Not reported
CONSTYPE RECONS IND:	Not reported
CONSTYPE RESIDENTIAL IND:	Not reported
CONSTYPE TRANSPORT IND:	Not reported
CONSTYPE UTILITY DESCRIPTION:	Not reported
CONSTYPE UTILITY IND:	Not reported
CONSTYPE WATER SEWER IND:	Not reported
DIR DISCHARGE USWATER IND:	Not reported
RECEIVING WATER NAME:	Not reported
CERTIFIER NAME:	Not reported
CERTIFIER TITLE:	Not reported
CERTIFICATION DATE:	Not reported
PRIMARY SIC:	Not reported

SHEN LINCOLN MERCURY (Continued) **S106981276**

SECONDARY SIC: Not reported
TERTIARY SIC: Not reported

AJ662 **EXXON CO USA SAN MATEO BULK PLT** **LUST** **1000336472**
ESE **320 PENINSULA** **RCRA NonGen / NLR** **CAT080010713**
1/2-1 **SAN MATEO, CA 94402** **FINDS**
0.519 mi. **HIST CORTESE**
2740 ft. **Site 27 of 35 in cluster AJ** **ECHO**

Relative: Higher

Actual: 32 ft.

LUST:

Region:	STATE
Global Id:	T0608100208
Latitude:	37.577669
Longitude:	-122.337732
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/04/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0218
LOC Case Number:	110013
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100208
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100208
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100208
Status:	Completed - Case Closed
Status Date:	06/04/2001

Global Id:	T0608100208
Status:	Open - Case Begin Date
Status Date:	09/28/1985

EXXON CO USA SAN MATEO BULK PLT (Continued) **1000336472**

Regulatory Activities:

Global Id:	T0608100208
Action Type:	Other
Date:	10/09/1985
Action:	Leak Discovery
Global Id:	T0608100208
Action Type:	Other
Date:	09/28/1985
Action:	Leak Reported
Global Id:	T0608100208
Action Type:	REMEDIATION
Date:	08/15/1985
Action:	Excavation
Global Id:	T0608100208
Action Type:	ENFORCEMENT
Date:	04/11/1989
Action:	Notice of Responsibility - #1

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	110013
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110013
Facility Status:	9- Case Closed
Global ID:	T0608100208
APN Number:	Not reported
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

RCRA NonGen / NLR:

Date form received by agency:	08/15/1980
Facility name:	EXXON CO USA SAN MATEO BULK PLT
Facility address:	320 PENINSULA SAN MATEO, CA 94402
EPA ID:	CAT080010713
Mailing address:	P.O. BOX FIFTH THOUSAND SECOND

EXXON CO USA SAN MATEO BULK PLT (Continued) **1000336472**

SAN MATEO, CA 94402
Contact: ENVIRONMENTAL MANAGER
Contact address: 320 PENINSULA
SAN MATEO, CA 94402
Contact country: US
Contact telephone: (214) 385-4728
Contact email: Not reported
EPA Region: 09
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EXXON CORPORATION
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002945261

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

EXXON CO USA SAN MATEO BULK PLT (Continued) **1000336472**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HIST CORTESE:
- Region: CORTESE
- Facility County Code: 41
- Reg By: LTNKA
- Reg Id: 41-0218

ECHO:
- Envid: 1000336472
- Registry ID: 110002945261
- DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002945261

AJ663 **WHITECLIFF CO** **San Mateo Co. BI** **S103951282**
ESE **859 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.529 mi.
2792 ft. **Site 28 of 35 in cluster AJ**

Relative: Higher

Actual: 34 ft.

San Mateo Co. BI:
- Region: SAN MATEO
- Facility ID: FA0023669
- Prog Element Code: UNDERGROUND TANK - GENERAL
- Record Id: PR0027495
- Description: UNDERGROUND TANK - GENERAL
- Facility Status: INACTIVE

AJ664 **WHITECLIFF COMPANY INC** **HIST UST** **U001596018**
ESE **859 SAN MATEO DRIVE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.529 mi.
2792 ft. **Site 29 of 35 in cluster AJ**

Relative: Higher

Actual: 34 ft.

HIST UST:
- File Number: 0002C456
- URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C456.pdf
- Region: STATE
- Facility ID: 00000031738
- Facility Type: Other
- Other Type: CONTRACTOR
- Contact Name: Not reported
- Telephone: 4153478201
- Owner Name: WHITECLIFF COMPANY, INC.
- Owner Address: 859 SAN MATEO DRIVE
- Owner City,St,Zip: SAN MATEO, CA 944401
- Total Tanks: 0001

- Tank Num: 001
- Container Num: 1
- Year Installed: 1979

WHITECLIFF COMPANY INC (Continued) **U001596018**

Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

AL665 **SWEEPS UST** **S106922167**
SSE **149 WARREN RD** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.531 mi.
2804 ft. **Site 1 of 5 in cluster AL**

Relative:
Higher

Actual:
56 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	110201
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110201-000001
Tank Status:	Not reported
Capacity:	500
Active Date:	Not reported
Tank Use:	OIL
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	1

AL666 **REVEREND PHEOPHILOS RES** **LUST** **S104494615**
SSE **149 WARREN** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.531 mi.
2804 ft. **Site 2 of 5 in cluster AL**

Relative:
Higher

Actual:
56 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Post remedial action monitoring
Case Number:	110092
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	1/1/1965

AL667 **RESIDENCE** **LUST** **S103894432**
SSE **149 WARREN** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94402** **HIST CORTESE**
0.531 mi.
2804 ft. **Site 3 of 5 in cluster AL**

Relative:
Higher

Actual:
56 ft.

LUST:

Region:	STATE
Global Id:	T0608100773
Latitude:	37.572021
Longitude:	-122.344042
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/19/2007
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0825
LOC Case Number:	110092
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100773
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100773
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100773
Status:	Completed - Case Closed
Status Date:	01/19/2007

Global Id:	T0608100773
Status:	Open - Case Begin Date
Status Date:	06/09/1994

Global Id:	T0608100773
Status:	Open - Verification Monitoring
Status Date:	06/09/1994

RESIDENCE (Continued) **S103894432**

Regulatory Activities:
Global Id: T0608100773
Action Type: ENFORCEMENT
Date: 06/09/1994
Action: Notice of Responsibility - #1

Global Id: T0608100773
Action Type: Other
Date: 05/27/1997
Action: Leak Reported

Global Id: T0608100773
Action Type: ENFORCEMENT
Date: 01/19/2007
Action: Closure/No Further Action Letter - #20070119

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110092
Facility Status: 9- Case Closed
Global ID: T0608100773
APN Number: 032083160
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016525
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022219
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0825

AM668 **EDR Hist Auto** **1015654618**
WNW **847 ACACIA AVE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.541 mi.
2856 ft. **Site 1 of 2 in cluster AM**

Relative:
Lower

Actual:
26 ft.

EDR Historical Auto Stations:
Name: SWENDIGS AUTO CHECK
Year: 2002
Address: 847 ACACIA AVE

669
West
1/2-1
0.544 mi.
2870 ft.

BER MANAGEMENT, INC.
789 EL CAMINO REAL
BURLINGAME, CA 94010

San Mateo Co. BI

S113757656
N/A

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027128
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0042700
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

670
SSW
1/2-1
0.552 mi.
2916 ft.

HERRMANN, DIANNA
141 PEPPER
BURLINGAME, CA 94010

San Mateo Co. BI

S113757581
N/A

Relative:
Higher

Actual:
65 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0026864
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0039855
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AM671
WNW
1/2-1
0.561 mi.
2964 ft.

SPECKMAN, LARRY
843 CROSSWAY
BURLINGAME, CA 94010

Site 2 of 2 in cluster AM

San Mateo Co. BI

S113757875
N/A

Relative:
Higher

Actual:
43 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0027870
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0045052
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AJ672
ESE
1/2-1
0.565 mi.
2984 ft.

PK AUTOMOTIVE
839 SAN MATEO
SAN MATEO, CA 94401

Site 30 of 35 in cluster AJ

San Mateo Co. BI

S106798193
N/A

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0004412
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0071762
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

Region: SAN MATEO

PK AUTOMOTIVE (Continued) **S106798193**

Facility ID: FA0004412
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0010628
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0004412
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0003325
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

AJ673 **EDR Hist Auto** **1015652562**
ESE **839 N SAN MATEO DR** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.565 mi.
2984 ft. **Site 31 of 35 in cluster AJ**

Relative:
Higher

Actual:
34 ft.

EDR Historical Auto Stations:

Name: HAROLDS AUTOMOTIVE
Year: 2001
Address: 839 N SAN MATEO DR

Name: PK AUTO INC
Year: 2006
Address: 839 N SAN MATEO DR

Name: P K AUTO SERVICE
Year: 2007
Address: 839 N SAN MATEO DR

Name: P K AUTO SERVICE
Year: 2008
Address: 839 N SAN MATEO DR

Name: PK AUTO INC
Year: 2009
Address: 839 N SAN MATEO DR

Name: P K AUTO SVC
Year: 2010
Address: 839 N SAN MATEO DR

Name: PK AUTOMOTIVE
Year: 2011
Address: 839 N SAN MATEO DR

Name: PK AUTOMOTIVE
Year: 2012
Address: 839 N SAN MATEO DR

AJ674 **PACIFIC READY MIX** **ENVIROSTOR** **S101482212**
ESE **850 SAN MATEO** **LUST** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.568 mi.
3000 ft. **Site 32 of 35 in cluster AJ**

Relative:
Higher

Actual:
34 ft.

ENVIROSTOR:

Facility ID:	41320028
Status:	Refer: Other Agency
Status Date:	03/25/2002
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	3.6
NPL:	NO
Regulatory Agencies:	SAN MATEO COUNTY
Lead Agency:	SAN MATEO COUNTY
Program Manager:	Not reported
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Assembly:	22
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.57666
Longitude:	-122.3383
APN:	NONE SPECIFIED
Past Use:	MANUFACTURING - OTHER
Potential COC:	TPH-diesel TPH-gas TPH-MOTOR OIL
Confirmed COC:	TPH-diesel TPH-gas TPH-MOTOR OIL
Potential Description:	OTH, SOIL
Alias Name:	41320028
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	08/15/1980
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	11/07/1991
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	05/27/1987
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	03/25/2002
Comments:	Site screening completed. Site referred to San Mateo County Health

PACIFIC READY MIX (Continued) **S101482212**

Services Department.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST:
Region: STATE
Global Id: T0608100382
Latitude: 37.5763937
Longitude: -122.3377654
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 08/31/2001
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0401
LOC Case Number: 110006
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100382
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100382
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100382
Status: Completed - Case Closed
Status Date: 08/31/2001

Global Id: T0608100382

PACIFIC READY MIX (Continued) **S101482212**

Status: Open - Case Begin Date
Status Date: 04/13/1988

Regulatory Activities:
Global Id: T0608100382
Action Type: ENFORCEMENT
Date: 12/21/1988
Action: Notice of Responsibility - #1

Global Id: T0608100382
Action Type: Other
Date: 04/13/1988
Action: Leak Discovery

Global Id: T0608100382
Action Type: Other
Date: 04/13/1988
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110006
Facility Status: 9- Case Closed
Global ID: T0608100382
APN Number: Not reported
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

AJ675 **PACIFIC READY MIX** **LUST S104494606**
ESE **850 SAN MATEO** **HIST CORTESE N/A**
1/2-1 **SAN MATEO, CA 94401**
0.568 mi.
3000 ft. **Site 33 of 35 in cluster AJ**

Relative:
Higher

Actual:
34 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110006
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA

PACIFIC READY MIX (Continued) **S104494606**

Reg Id: 41-0401

AJ676 **PACIFIC READY MIX INC** **HIST UST** **U001596007**
ESE **850 SAN MATEO DR** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.568 mi.
3000 ft. **Site 34 of 35 in cluster AJ**

Relative:
Higher

Actual:
34 ft.

HIST UST:

File Number:	0002C147
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C147.pdf
Region:	STATE
Facility ID:	00000010292
Facility Type:	Other
Other Type:	READY MIX CONCRETE
Contact Name:	KEN GARINO
Telephone:	4153431861
Owner Name:	PACIFIC READY MIX INC
Owner Address:	850 SAN MATEO DR
Owner City,St,Zip:	SAN MATEO, CA 94401
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual, Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Visual, Stock Inventor

Click here for Geo Tracker PDF:

AJ677 **REMMERS D SON** **San Mateo Co. BI** **S102270534**
ESE **833 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.576 mi.
3040 ft. **Site 35 of 35 in cluster AJ**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0017028
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0003429
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0017028
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0010665
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

AN678 **EDR Hist Auto** **1015468726**
East **400 PENINSULA AVE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.582 mi.
3072 ft. **Site 1 of 7 in cluster AN**

Relative:
Lower

Actual:
31 ft.

EDR Historical Auto Stations:

Name:	PENINSULA SHELL AUTO CARE
Year:	2001
Address:	400 PENINSULA AVE

AN679 **SAIS SUPER SHELL 6** **HIST UST** **U001596009**
East **400 PENINSULA** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.582 mi.
3072 ft. **Site 2 of 7 in cluster AN**

Relative:
Lower

Actual:
31 ft.

HIST UST:

File Number:	0002C2EC
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C2EC.pdf
Region:	STATE
Facility ID:	00000060248
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	4155794991
Owner Name:	SHELL OIL COMPANY
Owner Address:	P.O. BOX 4848
Owner City,St,Zip:	ANAHEIM, CA 92803
Total Tanks:	0003

Tank Num:	001
Container Num:	1
Year Installed:	1971
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED

SAIS SUPER SHELL 6 (Continued) **U001596009**

Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Tank Num: 002
Container Num: 2
Year Installed: 1971
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Tank Num: 003
Container Num: 3
Year Installed: 1971
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

Click here for Geo Tracker PDF:

AN680 **PENINSULA SHELL** **RCRA-SQG** **1005904272**
East **400 PENINSULA AVE** **LUST** **CAR000118778**
1/2-1 **SAN MATEO, CA 94401** **FINDS**
0.582 mi. **San Mateo Co. BI**
3072 ft. **Site 3 of 7 in cluster AN** **HAZNET**
ECHO

Relative:
Lower

Actual:
31 ft.

RCRA-SQG:
Date form received by agency: 06/04/2002
Facility name: SHELL SERVICE STATION
Facility address: 400 PENINSULA
S A P 136035
SAN MATEO, CA 94401
EPA ID: CAR000118778
Mailing address: P O BOX 2648
HOUSTON, CA 772522648
Contact: SONDRA BIENVENU
Contact address: P O BOX 2648
HOUSTON, CA 772522648
Contact country: US
Contact telephone: (713) 241-5036
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: EQUILON ENT LLC DBA S O P US
Owner/operator address: P O BOX 2648
HOUSTON, CA 77252

PENINSULA SHELL (Continued) **1005904272**

Owner/operator country: Not reported
Owner/operator telephone: (713) 241-5036
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

LUST:
Region: STATE
Global Id: T0608196925
Latitude: 37.578315261
Longitude: -122.337427205
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/01/2014
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 110151
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Can be extracted from most recent report in Geotracker or at San Mateo County offices if submitted prior to 2005, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report.

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608196925
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS

PENINSULA SHELL (Continued) **1005904272**

City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608196925
Status: Completed - Case Closed
Status Date: 07/01/2014

Global Id: T0608196925
Status: Open - Case Begin Date
Status Date: 12/03/2002

Global Id: T0608196925
Status: Open - Eligible for Closure
Status Date: 12/28/2012

Global Id: T0608196925
Status: Open - Site Assessment
Status Date: 12/03/2002

Global Id: T0608196925
Status: Open - Site Assessment
Status Date: 04/06/2004

Regulatory Activities:
Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 06/24/2014
Action: Notification - Public Notice of Case Closure - #20140624

Global Id: T0608196925
Action Type: RESPONSE
Date: 01/31/2014
Action: Well Destruction Report - Regulator Responded

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 10/23/2009
Action: Staff Letter - #20091023

Global Id: T0608196925
Action Type: RESPONSE
Date: 04/09/2004
Action: CAP/RAP - Feasibility Study Report

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 06/25/2013
Action: Notification - Preclosure - #20130625

PENINSULA SHELL (Continued) **1005904272**

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 07/05/2012
Action: Staff Letter - #20120705

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2011
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2011
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2011
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE

PENINSULA SHELL (Continued) **1005904272**

Date: 02/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2011
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2012
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: Other
Date: 12/03/2002
Action: Leak Discovery

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: REMEDIATION
Date: 04/06/2006
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 10/31/2012
Action: Staff Letter - #20121031

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 09/27/2013
Action: Notification - Preclosure - #20130927

Global Id: T0608196925
Action Type: Other
Date: 12/03/2002
Action: Leak Reported

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 05/27/2004
Action: Staff Letter - #20040527

PENINSULA SHELL (Continued) **1005904272**

Global Id: T0608196925
Action Type: RESPONSE
Date: 09/07/2012
Action: Site Assessment Report

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2012
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2012
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 08/29/2013
Action: Staff Letter - #20130829

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 10/31/2013
Action: 13267 Monitoring Program - #20131031

Global Id: T0608196925
Action Type: Other
Date: 12/19/2002
Action: Leak Stopped

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 07/06/2009
Action: Staff Letter - #20090706

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 03/19/2004
Action: Other Report / Document

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/06/2004
Action: CAP/RAP - Feasibility Study Report

Global Id: T0608196925
Action Type: RESPONSE

PENINSULA SHELL (Continued) **1005904272**

Date: 08/26/2004
Action: Sensitive Receptor Survey Report

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/16/2004
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/17/2004
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Quarterly

PENINSULA SHELL (Continued) **1005904272**

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 02/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 11/20/2013
Action: Staff Letter - #20131120

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 01/22/2014
Action: Staff Letter - #20140122

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2012
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 12/23/2002
Action: Notice of Responsibility - #1

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 04/06/2004
Action: Staff Letter - #20040406

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 12/24/2003
Action: Staff Letter - #20031224

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 03/28/2003
Action: Staff Letter - #20030328

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 10/28/2003
Action: Staff Letter - #20031028

Global Id: T0608196925
Action Type: RESPONSE

PENINSULA SHELL (Continued) **1005904272**

Date: 03/04/2010
Action: Site Assessment Report - Regulator Responded

Global Id: T0608196925
Action Type: RESPONSE
Date: 03/20/2011
Action: Site Assessment Report - Regulator Responded

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/01/2011
Action: Site Assessment Report - Regulator Responded

Global Id: T0608196925
Action Type: RESPONSE
Date: 03/10/2012
Action: Soil and Water Investigation Report - Regulator Responded

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 09/29/2010
Action: Staff Letter - #20100929

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 07/27/2011
Action: Staff Letter - #20110727

Global Id: T0608196925
Action Type: RESPONSE
Date: 11/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 08/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608196925
Action Type: RESPONSE
Date: 12/02/2013
Action: Well Destruction Workplan - Regulator Responded

Global Id: T0608196925
Action Type: ENFORCEMENT
Date: 11/08/2011
Action: Staff Letter - #20111108

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110151

PENINSULA SHELL (Continued) **1005904272**

Facility Status: 9- Case Closed
Global ID: T0608196925
APN Number: 032131680
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

FINDS:

Registry ID: 110055779457

Environmental Interest/Information System
STATE MASTER

Registry ID: 110012544504

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016933
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0025161
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0016933
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0003436
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0016933
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022131
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0046138
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0064293
Description: GENERATES <27 GAL/YEAR

PENINSULA SHELL (Continued) **1005904272**

Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0046138
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0064292
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0046138
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0064294
Description: UNDERGROUND TANK - GENERAL
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0056158
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0077446
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

HAZNET:
envid: 1005904272
Year: 2010
GEPAID: CAR000118778
Contact: JEANNE TRAYLOR
Telephone: 7132416992
Mailing Name: Not reported
Mailing Address: PO BOX 3127
Mailing City,St,Zip: HOUSTON, TX 772530000
Gen County: Not reported
TSD EPA ID: UTD981552177
TSD County: Not reported
Waste Category: Other organic solids
Disposal Method: Incineration--Thermal Destruction Other Than Use As A Fuel
Tons: 0.015
Cat Decode: Other organic solids
Method Decode: Incineration--Thermal Destruction Other Than Use As A Fuel
Facility County: San Mateo

envid: 1005904272
Year: 2009
GEPAID: CAR000118778
Contact: R HULL/ENV. REPORTING ANALYST
Telephone: 2818742224
Mailing Name: Not reported
Mailing Address: 12700 NORTHBOROUGH DR 300G03
Mailing City,St,Zip: Houston, TX 770670000
Gen County: Not reported
TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.10425

PENINSULA SHELL (Continued) **1005904272**

Cat Decode:	Aqueous solution with total organic residues 10 percent or more
Method Decode:	Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County:	San Mateo
envid:	1005904272
Year:	2009
GEPAID:	CAR000118778
Contact:	R HULL/ENV. REPORTING ANALYST
Telephone:	2818742224
Mailing Name:	Not reported
Mailing Address:	12700 NORTHBOROUGH DR 300G03
Mailing City,St,Zip:	Houston, TX 770670000
Gen County:	Not reported
TSD EPA ID:	CAD008302903
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.02
Cat Decode:	Other organic solids
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	1005904272
Year:	2008
GEPAID:	CAR000118778
Contact:	R HULL/ENV. REPORTING ANALYST
Telephone:	2818742224
Mailing Name:	Not reported
Mailing Address:	12700 NORTHBOROUGH DR 300G03
Mailing City,St,Zip:	Houston, TX 770670000
Gen County:	Not reported
TSD EPA ID:	CAD097030993
TSD County:	Not reported
Waste Category:	Unspecified aqueous solution
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.021
Cat Decode:	Unspecified aqueous solution
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo
envid:	1005904272
Year:	2008
GEPAID:	CAR000118778
Contact:	R HULL/ENV. REPORTING ANALYST
Telephone:	2818742224
Mailing Name:	Not reported
Mailing Address:	12700 NORTHBOROUGH DR 300G03
Mailing City,St,Zip:	Houston, TX 770670000
Gen County:	Not reported
TSD EPA ID:	CAD008830290
TSD County:	Not reported
Waste Category:	Other organic solids

PENINSULA SHELL (Continued) **1005904272**

Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.01
Cat Decode: Other organic solids
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
13 additional CA_HAZNET: record(s) in the EDR Site Report.

ECHO:
Envid: 1005904272
Registry ID: 110055779457
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110055779457

Envid: 1005904272
Registry ID: 110012544504
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110012544504

AN681 **SHELL OIL STATION, #6** **SWEEPS UST** **S101593926**
East **400 PENINSULA AVE** **CA FID UST** **N/A**
1/2-1 **SAN MATEO, CA 94404**
0.582 mi.
3072 ft. **Site 4 of 7 in cluster AN**

Relative:
Lower

Actual:
31 ft.

SWEEPS UST:
Status: Active
Comp Number: 110063
Number: 2
Board Of Equalization: Not reported
Referral Date: 04-20-94
Action Date: 04-20-94
Created Date: 10-13-88
Owner Tank Id: 6894-1206-SR-1
SWRCB Tank Id: 41-000-110063-000001
Tank Status: A
Capacity: 10000
Active Date: 04-20-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Status: Active
Comp Number: 110063
Number: 2
Board Of Equalization: Not reported
Referral Date: 04-20-94
Action Date: 04-20-94
Created Date: 10-13-88
Owner Tank Id: 6894-1206-1RU1
SWRCB Tank Id: 41-000-110063-000002
Tank Status: A
Capacity: 10000
Active Date: 04-20-94
Tank Use: M.V. FUEL

SHELL OIL STATION, #6 (Continued) **S101593926**

STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110063
Number: 2
Board Of Equalization: Not reported
Referral Date: 04-20-94
Action Date: 04-20-94
Created Date: 10-13-88
Owner Tank Id: 6894-1206-3RG1
SWRCB Tank Id: 41-000-110063-000003
Tank Status: A
Capacity: 10000
Active Date: 04-20-94
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110063
Number: 2
Board Of Equalization: Not reported
Referral Date: 04-20-94
Action Date: 04-20-94
Created Date: 10-13-88
Owner Tank Id: 6894-1206-3RG1
SWRCB Tank Id: 41-000-110063-000004
Tank Status: A
Capacity: 500
Active Date: 04-20-94
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41003064
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: P O BOX
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN MATEO 94401
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

AN682 **K&B PRODUCTS** **San Mateo Co. BI** **S106981152**
East **863 WOODSIDE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.582 mi.
3075 ft. **Site 5 of 7 in cluster AN**

Relative:
Higher

Actual:
33 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0010886
Prog Element Code:	STORES HAZ MAT <3,499GAL,27,999LB,13,999FT3
Record Id:	PR0003443
Description:	STORES HAZ MAT <3,499GAL,27,999LB,13,999CF
Facility Status:	INACTIVE

AO683 **BUD'S TIRE SERVICE** **LUST** **S109285522**
ESE **836 NORTH SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.587 mi.
3098 ft. **Site 1 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

LUST:

Region:	STATE
Global Id:	T0608100086
Latitude:	37.5289962
Longitude:	-122.2881485
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/06/1995
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0091
LOC Case Number:	110015
File Location:	Local Agency Warehouse
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100086
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100086
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

BUD'S TIRE SERVICE (Continued) **S109285522**

Status History:

Global Id:	T0608100086
Status:	Completed - Case Closed
Status Date:	10/06/1995
Global Id:	T0608100086
Status:	Open - Case Begin Date
Status Date:	03/16/1987

Regulatory Activities:

Global Id:	T0608100086
Action Type:	RESPONSE
Date:	02/01/2012
Action:	Soil Vapor Intrusion Investigation Report
Global Id:	T0608100086
Action Type:	RESPONSE
Date:	05/15/1995
Action:	Correspondence
Global Id:	T0608100086
Action Type:	Other
Date:	08/10/1987
Action:	Leak Discovery
Global Id:	T0608100086
Action Type:	Other
Date:	03/16/1987
Action:	Leak Reported
Global Id:	T0608100086
Action Type:	RESPONSE
Date:	09/22/2011
Action:	Other Report / Document
Global Id:	T0608100086
Action Type:	RESPONSE
Date:	05/15/1995
Action:	Correspondence
Global Id:	T0608100086
Action Type:	ENFORCEMENT
Date:	10/05/1995
Action:	Notice of Responsibility - #1
Global Id:	T0608100086
Action Type:	RESPONSE
Date:	09/23/2011
Action:	Soil Vapor Intrusion Investigation Workplan
Global Id:	T0608100086
Action Type:	RESPONSE
Date:	08/07/1987
Action:	Tank Removal Report / UST Sampling Report
Global Id:	T0608100086

BUD'S TIRE SERVICE (Continued) **S109285522**

Action Type: RESPONSE
Date: 03/17/1987
Action: Other Report / Document

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110015
Facility Status: 9- Case Closed
Global ID: T0608100086
APN Number: Not reported
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

AO684 **BUD'S TIRE SERVICE** **LUST** **S101308758**
ESE **836 SAN MATEO** **HIST CORTESE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.587 mi.
3098 ft. **Site 2 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110015
How Discovered: Tank Closure
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0091

---

685 **EDR Hist Auto** **1015329362**
ESE **217 STATE RD** **N/A**
1/2-1 **SAN MATEO, CA 94497**
0.594 mi.
3136 ft.

Relative:
Higher

Actual:
38 ft.

EDR Historical Auto Stations:
Name: SARABIAS AUTO RE PAIR & TOWING
Year: 2005
Address: 217 STATE RD

AO686 **AUTOPLUS** **San Mateo Co. BI** **S109953987**
ESE **823 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.594 mi.
3136 ft. **Site 3 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045421
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0059174
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0059717
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0082088
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0059717
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0082087
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AO687 **BURLINGAME SAAB** **San Mateo Co. BI** **S113755203**
ESE **825 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.596 mi.
3147 ft. **Site 4 of 14 in cluster AO**

Relative:
Higher

Actual:
35 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0001693
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0010684
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0001693
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0003395
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

AO688 **COLE EUROPEAN VOLVO** **HIST UST** **S113025831**
ESE **825 N SAN MATEO DRIVE** **HAZNET** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.596 mi.
3147 ft. **Site 5 of 14 in cluster AO**

Relative:
Higher

Actual:
35 ft.

HIST UST:

File Number:	0002C37C
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C37C.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

HAZNET:

envid:	S113025831
Year:	1999
GEPAID:	CAL000012539
Contact:	COLE ROBERT
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	825 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944100000
Gen County:	Not reported
TSD EPA ID:	CAD099452708
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	.2293
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Recycler
Facility County:	San Mateo
envid:	S113025831
Year:	1998
GEPAID:	CAL000012539
Contact:	COLE ROBERT
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	825 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944100000
Gen County:	Not reported

COLE EUROPEAN VOLVO (Continued) **S113025831**

TSD EPA ID: CAT080013352
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Recycler
Tons: .2293
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Recycler
Facility County: San Mateo

AO689 **EDR Hist Auto** **1015649103**
ESE **825 N SAN MATEO DR** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.596 mi.
3147 ft. **Site 6 of 14 in cluster AO**

Relative:
Higher

Actual:
35 ft.

EDR Historical Auto Stations:
Name: BURLINGAME SAAB JAGUAR
Year: 2001
Address: 825 N SAN MATEO DR

Name: BURLINGAME SAAB JAGUAR
Year: 2002
Address: 825 N SAN MATEO DR

---

690 **BROSNAN, JOHN** **San Mateo Co. BI** **S104566507**
South **760 OCCIDENTAL** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.603 mi.
3182 ft.

Relative:
Higher

Actual:
69 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0025649
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0034601
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AO691 **SHEN INFINITY** **RCRA-SQG** **1000597460**
ESE **800 N SAN MATEO DR** **LUST** **CAD983614736**
1/2-1 **SAN MATEO, CA 94401** **FINDS**
0.611 mi. **San Mateo Co. BI**
3225 ft. **Site 7 of 14 in cluster AO** **ENF**
HIST CORTESE
ECHO

Relative:
Higher

Actual:
33 ft.

RCRA-SQG:
Date form received by agency: 11/12/1991
Facility name: SHEN INFINITY
Facility address: 800 N SAN MATEO DR
SAN MATEO, CA 94401
EPA ID: CAD983614736
Contact: PAT OBRIEN
Contact address: 800 N SAN MATEO DR
SAN MATEO, CA 94401

SHEN INFINITY (Continued) **1000597460**

Contact country: US
Contact telephone: (415) 342-8600
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: MICHAEL SHEN
Owner/operator address: 888 N SAN MATEO DR
SAN MATEO, CA 94401
Owner/operator country: Not reported
Owner/operator telephone: (415) 342-8600
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

LUST REG 2:
Region: 2
Facility Id: 48-0147
Facility Status: Preliminary site assessment underway
Case Number: 48-0147
How Discovered: Tank Closure
Leak Cause: Structure Failure
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 2/18/1992
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SHEN INFINITY (Continued) **1000597460**

FINDS:

Registry ID: 110002865926

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0012849
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0010798
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012849
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0003467
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

ENF:

Region:	2
Facility Id:	260990
Agency Name:	Shen Infiniti
Place Type:	Facility
Place Subtype:	Not reported
Facility Type:	All other facilities
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	Not reported
Place Longitude:	Not reported
SIC Code 1:	Not reported
SIC Desc 1:	Not reported
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported

SHEN INFINITY (Continued) **1000597460**

Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	UST
Program Category1:	TANKS
Program Category2:	TANKS
# Of Programs:	1
WDID:	2 48-0147
Reg Measure Id:	168235
Reg Measure Type:	Unregulated
Region:	2
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Never Active
Status Date:	02/20/2013
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	237237
Region:	2
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	04/22/1999
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 2 48-0147
Description:	Requirements for MTBE Info Pertaining to the Leaking Underground Storage Tank
Program:	UST
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	$0.00
Initial Assessed Amount:	$0.00
Liability $ Amount:	$0.00
Project $ Amount:	$0.00

SHEN INFINITY (Continued) **1000597460**

Liability $ Paid: $0.00
Project $ Completed: $0.00
Total $ Paid/Completed Amount: $0.00

HIST CORTESE:
Region: CORTESE
Facility County Code: 48
Reg By: LTNKA
Reg Id: 48-0147

ECHO:
Envid: 1000597460
Registry ID: 110002865926
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002865926

AO692 **SHEN INFINITI** **LUST** **S106567389**
ESE **800 SAN MATEO DR N** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.611 mi.
3225 ft. **Site 8 of 14 in cluster AO**

Relative:
Higher

Actual:
33 ft.

LUST:
Region: STATE
Global Id: T0609500138
Latitude: 37.576011
Longitude: -122.336788
Case Type: LUST Cleanup Site
Status: Open - Inactive
Status Date: 01/01/2011
Lead Agency: SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker: JGU
Local Agency: Not reported
RB Case Number: Not reported
LOC Case Number: Not reported
File Location: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0609500138
Contact Type: Regional Board Caseworker
Contact Name: JOLANTA UCHMAN
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: juchman@waterboards.ca.gov
Phone Number: Not reported

Status History:
Global Id: T0609500138
Status: Open - Case Begin Date
Status Date: 09/05/1990

Global Id: T0609500138

SHEN INFINITI (Continued) **S106567389**

Status: Open - Inactive
Status Date: 01/01/2011

Global Id: T0609500138
Status: Open - Site Assessment
Status Date: 02/18/1992

Regulatory Activities:
Global Id: T0609500138
Action Type: ENFORCEMENT
Date: 01/12/2012
Action: File review

Global Id: T0609500138
Action Type: RESPONSE
Date: 01/25/2011
Action: Other Report / Document

Global Id: T0609500138
Action Type: Other
Date: 09/05/1990
Action: Leak Discovery

Global Id: T0609500138
Action Type: Other
Date: 09/05/1990
Action: Leak Reported

Global Id: T0609500138
Action Type: Other
Date: 09/05/1990
Action: Leak Stopped

Global Id: T0609500138
Action Type: RESPONSE
Date: 09/23/2011
Action: Soil and Water Investigation Workplan

Global Id: T0609500138
Action Type: RESPONSE
Date: 09/23/2011
Action: CAP/RAP - Other Report

Global Id: T0609500138
Action Type: RESPONSE
Date: 02/01/2012
Action: Soil and Water Investigation Report

693
SE
1/2-1
0.622 mi.
3285 ft.

DICK GREGORY, D.D.S.
720 EL CAMINO REAL
SAN MATEO, CA 94401

San Mateo Co. BI

S108540457
N/A

Relative:
Higher

Actual:
46 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0026542
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0052604
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

AL694
SSE
1/2-1
0.630 mi.
3328 ft.

151 SYCAMORE
SAN MATEO, CA 94402
Site 4 of 5 in cluster AL

SWEEPS UST

S106922168
N/A

Relative:
Higher

Actual:
69 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	110157
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110157-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	PRODUCT
Content:	HEATING OIL
Number Of Tanks:	1

AL695
SSE
1/2-1
0.630 mi.
3328 ft.

RESIDENCE
151 SYCAMORE
SAN MATEO, CA 94402
Site 5 of 5 in cluster AL

SWEEPS UST

S106931270
N/A

Relative:
Higher

Actual:
69 ft.

SWEEPS UST:

Status:	Active
Comp Number:	110157
Number:	2
Board Of Equalization:	Not reported
Referral Date:	11-10-93
Action Date:	11-10-93
Created Date:	07-08-92
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported

RESIDENCE (Continued) **S106931270**

STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

AO696 **ALL TUNE & LUBE** **San Mateo Co. BI** **S102270530**
ESE **801 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.633 mi.
3343 ft. **Site 9 of 14 in cluster AO**

Relative: Higher

Actual: 35 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0013808
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023909
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0013808
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0023908
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0027007
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0041668
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0027007
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0041667
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

AP697 **MALCOLM PROPERTY** **LUST** **S103894283**
SSE **625 HURLINGHAM** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94402** **HIST CORTESE**
0.641 mi.
3387 ft. **Site 1 of 3 in cluster AP**

Relative: Higher

Actual: 58 ft.

LUST:

Region:	STATE
Global Id:	T0608100636
Latitude:	37.570829
Longitude:	-122.340839
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/30/1992
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP

MALCOLM PROPERTY (Continued) **S103894283**

RB Case Number: 41-0669
LOC Case Number: 110075
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Heating Oil / Fuel Oil
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100636
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100636
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100636
Status: Completed - Case Closed
Status Date: 09/30/1992

Global Id: T0608100636
Status: Open - Case Begin Date
Status Date: 09/30/1992

Regulatory Activities:
Global Id: T0608100636
Action Type: Other
Date: 09/30/1992
Action: Leak Discovery

Global Id: T0608100636
Action Type: Other
Date: 09/30/1992
Action: Leak Reported

Global Id: T0608100636
Action Type: ENFORCEMENT
Date: 09/30/1992
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO

MALCOLM PROPERTY (Continued) **S103894283**

Facility ID: 110075
Facility Status: 9- Case Closed
Global ID: T0608100636
APN Number: 032084220
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0013829
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022201
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0669

AP698 **MALCOLM PROPERTY** **LUST** **S104494575**
SSE **625 HURLINGHAM** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.641 mi.
3387 ft. **Site 2 of 3 in cluster AP**

Relative: Higher

Actual: 58 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110075
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

AO699 **P K AUTO SERVICE** **RCRA-SQG** **1000196962**
ESE **790 N SAN MATEO DR** **LUST** **CAD982516296**
1/2-1 **SAN MATEO, CA 94401** **FINDS**
0.647 mi. **ECHO**
3415 ft. **Site 10 of 14 in cluster AO**

Relative: Higher

Actual: 34 ft.

RCRA-SQG:
Date form received by agency: 09/01/1996
Facility name: MIKE HARVEY TOYOTA
Facility address: 790 N SAN MATEO DR
SAN MATEO, CA 94401

P K AUTO SERVICE (Continued) **1000196962**

EPA ID:	CAD982516296
Mailing address:	PO BOX 943
	BURLINGAME, CA 94010
Contact:	Not reported
Contact address:	Not reported
	Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MIKE HARVEY TOYOTA
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

P K AUTO SERVICE (Continued) **1000196962**

Historical Generators:
Date form received by agency: 02/15/1989
Site name: MIKE HARVEY TOYOTA
Classification: Large Quantity Generator

Violation Status: No violations found

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110023
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: 1/1/1965
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: 5/22/2003

FINDS:

Registry ID: 110009547366

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110002820519

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000196962
Registry ID: 110009547366
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110009547366

Envid: 1000196962
Registry ID: 110002820519
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002820519

AO700 **VERACOM MITSUBISHI** **LUST** **S109285658**
ESE **790 SAN MATEO** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.647 mi.
3415 ft. **Site 11 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

LUST:

Region:	STATE
Global Id:	T0608100333
Latitude:	37.575743
Longitude:	-122.336144
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/28/2004
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0349
LOC Case Number:	110023
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100333
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100333
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100333
Status:	Completed - Case Closed
Status Date:	05/28/2004

Global Id:	T0608100333
Status:	Open - Case Begin Date
Status Date:	07/01/1987

Global Id:	T0608100333
Status:	Open - Site Assessment
Status Date:	07/01/1987

Global Id:	T0608100333

VERACOM MITSUBISHI (Continued) **S109285658**

Status: Open - Verification Monitoring
Status Date: 05/22/2003

Regulatory Activities:
Global Id: T0608100333
Action Type: ENFORCEMENT
Date: 03/07/1991
Action: Notice of Responsibility - #1

Global Id: T0608100333
Action Type: ENFORCEMENT
Date: 10/07/2003
Action: Staff Letter - #20031007

Global Id: T0608100333
Action Type: ENFORCEMENT
Date: 05/28/2004
Action: Closure/No Further Action Letter - #20040528

Global Id: T0608100333
Action Type: ENFORCEMENT
Date: 08/27/2003
Action: Staff Letter - #20030827

Global Id: T0608100333
Action Type: Other
Date: 10/27/1987
Action: Leak Discovery

Global Id: T0608100333
Action Type: Other
Date: 07/01/1987
Action: Leak Reported

Global Id: T0608100333
Action Type: RESPONSE
Date: 09/29/2003
Action: Other Workplan

Global Id: T0608100333
Action Type: RESPONSE
Date: 01/07/2004
Action: Other Report / Document

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0015102
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0010807
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0015102
Prog Element Code: STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3

VERACOM MITSUBISHI (Continued) **S109285658**

Record Id:	PR0003478
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0036925
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0053790
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0036925
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0053789
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AO701 **MIKE HARVEY TOYOTA, FORMER** **LUST** **U001596017**
ESE **790 N SAN MATEO DR** **N/A**
1/2-1 **SAN MATEO, CA**
0.647 mi.
3415 ft. **Site 12 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110023
Facility Status:	9- Case Closed
Global ID:	T0608100333
APN Number:	032121060
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

AO702 **P K AUTO SERVICE** **RCRA-SQG** **1000196961**
ESE **790 N SAN MATEO DR** **CAD982472060**
1/2-1 **SAN MATEO, CA 94401**
0.647 mi.
3415 ft. **Site 13 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

RCRA-SQG:

Date form received by agency:	02/17/1993
Facility name:	P K AUTO SERVICE
Facility address:	790 N SAN MATEO DR SAN MATEO, CA 94401
EPA ID:	CAD982472060
Contact:	FREDERICK KOO
Contact address:	790 N SAN MATEO DR SAN MATEO, CA 94401
Contact country:	US
Contact telephone:	(415) 375-8822
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous

P K AUTO SERVICE (Continued) **1000196961**

waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FREDERICK KOO
Owner/operator address: 975 MACADAMIA DR
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (415) 347-4207
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AO703 **TOYOTA CENTER INC** **HIST UST** **S113016455**
ESE **790 N SAN MATEO DRIVE** **HAZNET** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.647 mi.
3415 ft. **Site 14 of 14 in cluster AO**

Relative:
Higher

Actual:
34 ft.

HIST UST:
File Number: 0002C39E
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C39E.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported

TOYOTA CENTER INC (Continued) **S113016455**

Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

Click here for Geo Tracker PDF:

HAZNET:
envid: S113016455
Year: 2001
GEPAID: CAD982472060
Contact: NON-DELIVERABLE 11/94 SURVEY
Telephone: --
Mailing Name: Not reported
Mailing Address: 790 N SAN MATEO DR
Mailing City,St,Zip: SAN MATEO, CA 944012224
Gen County: Not reported
TSD EPA ID: CAD059494310
TSD County: Not reported
Waste Category: Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: Disposal, Other
Tons: 0.22
Cat Decode: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode: Disposal, Other
Facility County: San Mateo

envid: S113016455
Year: 2000
GEPAID: CAD982472060
Contact: NON-DELIVERABLE 11/94 SURVEY
Telephone: --
Mailing Name: Not reported
Mailing Address: 790 N SAN MATEO DR
Mailing City,St,Zip: SAN MATEO, CA 944012224
Gen County: Not reported
TSD EPA ID: CAD982446874
TSD County: Not reported
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Transfer Station
Tons: 1.29
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Transfer Station
Facility County: San Mateo

envid: S113016455
Year: 1999
GEPAID: CAD982472060
Contact: Not reported

TOYOTA CENTER INC (Continued) **S113016455**

Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	790 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012224
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	2.8355
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	S113016455
Year:	1998
GEPAID:	CAD982472060
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	790 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012224
Gen County:	Not reported
TSD EPA ID:	CAD980887418
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	.3961
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S113016455
Year:	1998
GEPAID:	CAD982472060
Contact:	Not reported
Telephone:	0000000000
Mailing Name:	Not reported
Mailing Address:	790 N SAN MATEO DR
Mailing City,St,Zip:	SAN MATEO, CA 944012224
Gen County:	Not reported
TSD EPA ID:	CAD982446874
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	.5838
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
11 additional CA_HAZNET: record(s) in the EDR Site Report.

AP704 **RESIDENCE** **SWEEPS UST** **S101593973**
SSE **625 HULINGHAM** **CA FID UST** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.651 mi.
3439 ft. **Site 3 of 3 in cluster AP**

Relative:
Higher

Actual:
70 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	110181
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110181-000001
Tank Status:	Not reported
Capacity:	750
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	PRODUCT
Content:	WASTE OIL
Number Of Tanks:	1

CA FID UST:

Facility ID:	41004728
Regulated By:	UTNKI
Regulated ID:	CAC000817
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4153430207
Mail To:	Not reported
Mailing Address:	625 HULINGHAM
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN MATEO 94402
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

AQ705 **ALL CAR AUTO PAINTING & BODY REPAIR** **RCRA-SQG** **1000106274**
NW **903 CALIFORNIA DR** **CAD982487431**
1/2-1 **BURLINGAME, CA 94010**
0.653 mi.
3449 ft. **Site 1 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

RCRA-SQG:

Date form received by agency:	05/14/1990
Facility name:	ALL CAR AUTO PAINTING & BODY REPAIR
Facility address:	903 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD982487431
Mailing address:	CALIFORNIA DR BURLINGAME, CA 94010
Contact:	ENVIRONMENTAL MANAGER
Contact address:	903 CALIFORNIA DR

ALL CAR AUTO PAINTING & BODY REPAIR (Continued) **1000106274**

BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 343-5624
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: DOWIAT ROD
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

AQ706 **SUNNY AUTO BODY** **San Mateo Co. BI** **S113755370**
NW **903 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.653 mi.
3449 ft. **Site 2 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0055204
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0076122
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0007253
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011956
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0007253
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004753
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AN707 **AUTO WORKS** **ENVIROSTOR** **S103994250**
ESE **815 WOODSIDE** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.653 mi.
3449 ft. **Site 6 of 7 in cluster AN**

Relative:
Higher

Actual:
33 ft.

ENVIROSTOR:

Facility ID:	41750034
Status:	No Further Action
Status Date:	08/30/2002
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	1
NPL:	NO
Regulatory Agencies:	SAN MATEO COUNTY
Lead Agency:	SAN MATEO COUNTY
Program Manager:	Not reported
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Assembly:	22
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.57696
Longitude:	-122.3360
APN:	032122120
Past Use:	PAINT/DEPAINT FACILITY
Potential COC:	Arsenic Total Chromium (1:6 ratio Cr VI:Cr III Lead Zinc
Confirmed COC:	Arsenic Total Chromium (1:6 ratio Cr VI:Cr III Lead Zinc

AUTO WORKS (Continued) **S103994250**

Potential Description: SOIL
Alias Name: 032122120
Alias Type: APN
Alias Name: 110010466744
Alias Type: EPA (FRS #)
Alias Name: 41750034
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 04/03/1981
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 05/07/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 08/30/2002
Comments: No action required.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016464
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0023089
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0017023
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0010661
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0017023
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0003289
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF

AUTO WORKS (Continued) **S103994250**

Facility Status: ACTIVE

AN708 **PARAMOUNT COLLISION SPECIALIST** **RCRA-SQG** **1000429759**
ESE **815 WOODSIDE WAY** **FINDS** **CAD981375512**
1/2-1 **SAN MATEO, CA 94401** **EMI**
0.653 mi. **ECHO**
3449 ft. **Site 7 of 7 in cluster AN**

Relative: Higher

Actual: 33 ft.

RCRA-SQG:

Date form received by agency:	01/29/1986
Facility name:	STEVE'S CAR CAPITAL
Facility address:	815 WOODSIDE WAY SAN MATEO, CA 94401
EPA ID:	CAD981375512
Mailing address:	815 WOODSIDE WY SAN MATEO, CA 94401
Contact:	ENVIRONMENTAL MANAGER
Contact address:	815 WOODSIDE WAY SAN MATEO, CA 94401
Contact country:	US
Contact telephone:	(415) 340-9200
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	DAVID STEPHEN
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

PARAMOUNT COLLISION SPECIALIST (Continued) **1000429759**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110010466744

Environmental Interest/Information System
HAZARDOUS AIR POLLUTANT MAJOR

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

EMI:

Year:	1987
County Code:	41
Air Basin:	SF
Facility ID:	3641
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1990
County Code:	41
Air Basin:	SF
Facility ID:	3641
Air District Name:	BA
SIC Code:	5511
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1

PARAMOUNT COLLISION SPECIALIST (Continued) **1000429759**

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

ECHO:
Envid: 1000429759
Registry ID: 110010466744
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110010466744

AQ709 **AUTOHAUS EXEC** **San Mateo Co. BI** **S113756853**
NW **909 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.660 mi.
3487 ft. **Site 3 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0022914
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0025795
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0022914
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0025796
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

AQ710 **MULTI CRAFT AUTO BODY** **San Mateo Co. BI** **S113756629**
NW **917 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.670 mi.
3536 ft. **Site 4 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0018029
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011847
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0018029
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004627
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

AQ711 **MULTI CRAFT AUTO BODY** **San Mateo Co. BI** **S113758470**
NW **917 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.670 mi.
3536 ft. **Site 5 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0038679
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0055094
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0038679
Prog Element Code:	BUSINESS PLAN - GENERAL
Record Id:	PR0066927
Description:	BUSINESS PLAN - GENERAL
Facility Status:	INACTIVE

AQ712 **BARTLETTS AUTO BODY** **RCRA-SQG** **1000414684**
NW **917 CALIFORNIA DR** **FINDS** **CAD982011900**
1/2-1 **BURLINGAME, CA 94010** **ECHO**
0.670 mi.
3536 ft. **Site 6 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

RCRA-SQG:

Date form received by agency:	07/07/1987
Facility name:	BARTLETTS AUTO BODY
Facility address:	917 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD982011900
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	J BARTLETT
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	NOT REQUIRED

BARTLETTS AUTO BODY (Continued) **1000414684**

Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110001156436

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
Envid: 1000414684
Registry ID: 110001156436
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110001156436

AQ713 **ANCHOR BODY & DETAILING** **San Mateo Co. BI** **S113755914**
NW **1008 CAROLAN** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.672 mi.
3546 ft. **Site 7 of 15 in cluster AQ**

Relative:
Lower

Actual:
12 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0013201
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011942

ANCHOR BODY & DETAILING (Continued) **S113755914**

Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0013201
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0044436
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

AQ714 **ADVANCE AUTOMOTIVE** **San Mateo Co. BI** **S113755368**
NW **921 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.674 mi.
3560 ft. **Site 8 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0007251
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011843
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0007251
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0004664
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

AQ715 **ARTISAN MOTORS** **San Mateo Co. BI** **S113757315**
NW **921 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.674 mi.
3560 ft. **Site 9 of 15 in cluster AQ**

Relative:
Lower

Actual:
18 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0025278
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0033627
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0025278
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0033628
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

AR716 **INTERSTATE FLORAL CO INC** **SWEEPS UST** **S101593833**
ESE **801 WOODSIDE** **CA FID UST** **N/A**
1/2-1 **SAN MATEO, CA 94401** **San Mateo Co. BI**
0.686 mi.
3621 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
33 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	110121
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110121-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

CA FID UST:

Facility ID:	41000881
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	801 WOODSIDE WAY
Mailing Address 2:	Not reported
Mailing City,St,Zip:	SAN MATEO 94401
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0007021
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022173
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

717
NE
1/2-1
0.688 mi.
3634 ft.

CITY OF BURLINGAME
399 ROLLINS ROAD
BURLINGAME, CA 94010

San Mateo Co. BI
EMI

S106920410
N/A

Relative:
Lower

Actual:
13 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0054562
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0075243
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

EMI:

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.01
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000976

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.019

CITY OF BURLINGAME (Continued) **S106920410**

Reactive Organic Gases Tons/Yr:	.0158973
Carbon Monoxide Emissions Tons/Yr:	.051
NOX - Oxides of Nitrogen Tons/Yr:	.234
SOX - Oxides of Sulphur Tons/Yr:	.004
Particulate Matter Tons/Yr:	.017
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.016592

Year:	2006
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.019
Reactive Organic Gases Tons/Yr:	.0158973
Carbon Monoxide Emissions Tons/Yr:	.051
NOX - Oxides of Nitrogen Tons/Yr:	.234
SOX - Oxides of Sulphur Tons/Yr:	.004
Particulate Matter Tons/Yr:	.017
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.016592

Year:	2007
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	.001
NOX - Oxides of Nitrogen Tons/Yr:	.003
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2008
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	.001
NOX - Oxides of Nitrogen Tons/Yr:	.003
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CITY OF BURLINGAME (Continued) **S106920410**

Year:	2009
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	8.3670000000000001E-4
Carbon Monoxide Emissions Tons/Yr:	3.0000000000000001E-3
NOX - Oxides of Nitrogen Tons/Yr:	8.0000000000000002E-3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.001
Part. Matter 10 Micrometers and Smllr Tons/Yr:	9.7599999999999998E-4

Year:	2010
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	8.3670000000000001E-4
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	5.0000000000000001E-3
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.00102459016393442
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.001

Year:	2011
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.005
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199

CITY OF BURLINGAME (Continued) **S106920410**

Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.001
Reactive Organic Gases Tons/Yr:	0.0008367
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.005
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0.0010245901639
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.001

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0.001
NOX - Oxides of Nitrogen Tons/Yr:	0.002
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF
Facility ID:	14464
Air District Name:	BA
SIC Code:	9199
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.000168886
Reactive Organic Gases Tons/Yr:	0.000164426
Carbon Monoxide Emissions Tons/Yr:	0.00051
NOX - Oxides of Nitrogen Tons/Yr:	0.001674173
SOX - Oxides of Sulphur Tons/Yr:	1.087e-006
Particulate Matter Tons/Yr:	0.000174632
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.000167647

AQ718 **BURLINGAME SUBARU** **San Mateo Co. BI** **S113755478**
NW **1020 CAROLAN** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.689 mi.
3640 ft. **Site 10 of 15 in cluster AQ**

Relative:
Lower

Actual:
11 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0009394
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022796
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AQ719
NW
1/2-1
0.689 mi.
3640 ft.

BURLINGAME SUBARU
1020 CAROLAN AVE
BURLINGAME, CA 94010

Site 11 of 15 in cluster AQ

SWEEPS UST
CA FID UST

S101594090
N/A

Relative:
Lower

Actual:
11 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	660085
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660085-000001
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	4

Status:	Not reported
Comp Number:	660085
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660085-000002
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660085
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660085-000003
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

Status:	Not reported

BURLINGAME SUBARU (Continued) **S101594090**

Comp Number: 660085
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660085-000004
Tank Status: Not reported
Capacity: 550
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41004956
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 198 CALIFORNIA DR
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

AS720 **METRO PARK AIRPORT PARKING** **SWEEPS UST** **S101593862**
NNE **615 AIRPORT BLVD** **CA FID UST** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.693 mi.
3658 ft. **Site 1 of 5 in cluster AS**

Relative:
Lower

Actual:
13 ft.

SWEEPS UST:
Status: Active
Comp Number: 660013
Number: 1
Board Of Equalization: Not reported
Referral Date: 03-23-94
Action Date: 03-23-94
Created Date: 10-13-88
Owner Tank Id: 86
SWRCB Tank Id: 41-000-660013-000001
Tank Status: A
Capacity: 10000
Active Date: 03-23-94
Tank Use: M.V. FUEL
STG: P
Content: DIESEL

METRO PARK AIRPORT PARKING (Continued) **S101593862**

Number Of Tanks: 1

CA FID UST:
Facility ID: 41001450
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4153488801
Mail To: Not reported
Mailing Address: 475 SANSOME ST
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

AS721 **ANZA PARKING** **LUST** **U001593894**
NNE **615 AIRPORT BLVD** **HIST UST** **N/A**
1/2-1 **BURLINGAME, CA 94010** **San Mateo Co. BI**
0.693 mi.
3658 ft. **Site 2 of 5 in cluster AS**

Relative:
Lower

Actual:
13 ft.

LUST:
Region: STATE
Global Id: T0608192381
Latitude: 37.5892239795631
Longitude: -122.344114780426
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/17/2000
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-4038
LOC Case Number: 660085
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608192381
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608192381

ANZA PARKING (Continued) **U001593894**

Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608192381
Status: Completed - Case Closed
Status Date: 03/17/2000

Global Id: T0608192381
Status: Open - Case Begin Date
Status Date: 04/21/1999

Regulatory Activities:
Global Id: T0608192381
Action Type: Other
Date: 04/21/1999
Action: Leak Discovery

Global Id: T0608192381
Action Type: Other
Date: 04/21/1999
Action: Leak Reported

Global Id: T0608192381
Action Type: ENFORCEMENT
Date: 04/21/1999
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660085
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660085
Facility Status: 9- Case Closed

ANZA PARKING (Continued) **U001593894**

Global ID: T0608192381
APN Number: 026363320
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST UST:
File Number: 0002C057
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C057.pdf
Region: STATE
Facility ID: 00000004118
Facility Type: Gas Station
Other Type: AIRPORT PARKING SHUT
Contact Name: RICK BASTIAN
Telephone: 4153488801
Owner Name: METROPOLITAN PARKING CORPORATI
Owner Address: 615 AIRPORT BLVD.
Owner City,St,Zip: BURLINGAME, CA 94010
Total Tanks: 0001

Tank Num: 001
Container Num: 86-1D
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: Not reported
Leak Detection: Pressure Test

Click here for Geo Tracker PDF:

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0017965
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0027342
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0017965
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0004646
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0017965
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022750
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AT722 **7 ELEVEN** **San Mateo Co. BI** **S112933120**
NW **975 ROLLINS RD** **HAZNET** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.693 mi.
3659 ft. **Site 1 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0055290
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076236
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

HAZNET:

envid:	S112933120
Year:	2003
GEPAID:	CAC002570636
Contact:	OLLIN SMITH
Telephone:	9164636780
Mailing Name:	Not reported
Mailing Address:	PO BOX 711
Mailing City,St,Zip:	DALLAS, TX 75221
Gen County:	Not reported
TSD EPA ID:	AZC950823111
TSD County:	Not reported
Waste Category:	Asbestos containing waste
Disposal Method:	Not reported
Tons:	0.25
Cat Decode:	Asbestos containing waste
Method Decode:	Not reported
Facility County:	San Mateo

AU723 **SAN MATEO IMAGING** **RCRA-SQG** **1000818892**
ESE **715 N SAN MATEO DR** **FINDS** **CAD983648262**
1/2-1 **SAN MATEO, CA 94401** **ECHO**
0.695 mi.
3671 ft. **Site 1 of 6 in cluster AU**

Relative:
Higher

Actual:
38 ft.

RCRA-SQG:

Date form received by agency:	09/16/1992
Facility name:	SAN MATEO IMAGING
Facility address:	715 N SAN MATEO DR SAN MATEO, CA 94401
EPA ID:	CAD983648262
Contact:	CHERYL HALCOVICH
Contact address:	1783 EL CAMINO REAL BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(415) 696-5515
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

SAN MATEO IMAGING (Continued) **1000818892**

Owner/Operator Summary:
- Owner/operator name: SAN MATEO IMAGING INC
- Owner/operator address: 715 N SAN MATEO DR
  SAN MATEO, CA 94401
- Owner/operator country: Not reported
- Owner/operator telephone: (415) 375-8833
- Legal status: Private
- Owner/Operator Type: Owner
- Owner/Op start date: Not reported
- Owner/Op end date: Not reported

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110002884567

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
- Envid: 1000818892
- Registry ID: 110002884567
- DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110002884567

724
SSE
1/2-1
0.695 mi.
3672 ft.

STROMBERG, LOUISE
617 CRESCENT
SAN MATEO, CA 94402

San Mateo Co. BI **S106982133**
N/A

Relative:
Higher

Actual:
59 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0026623
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0038647
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

725
ENE
1/2-1
0.697 mi.
3679 ft.

RESIDENCE
215 CHANNING
BURLINGAME, CA 94010

San Mateo Co. BI **S113756869**
N/A

Relative:
Lower

Actual:
17 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0022988
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0025970
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AU726
ESE
1/2-1
0.697 mi.
3680 ft.

COMMERCIAL PROPERTY
716 N SAN MATEO DR
SAN MATEO, CA 94402

Site 2 of 6 in cluster AU

SWEEPS UST **S106924827**
N/A

Relative:
Higher

Actual:
38 ft.

SWEEPS UST:

Status:	Not reported
Comp Number:	110186
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110186-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

AU727
ESE
1/2-1
0.698 mi.
3683 ft.

COMMERCIAL PROPERTY
716 SAN MATEO
SAN MATEO, CA 94402

Site 3 of 6 in cluster AU

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI | **S106981363** | **N/A**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0014884
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022206
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AQ728
NW
1/2-1
0.701 mi.
3703 ft.

TOPLINE AUTOMOBILE INC
1028 CAROLAN
BURLINGAME, CA 94010

Site 12 of 15 in cluster AQ

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI | **S113757822** | **N/A**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0027671
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0044437
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0027671
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0044438
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AQ729
NW
1/2-1
0.701 mi.
3703 ft.

CAMMISA MOTOR CAR CO
1028 CAROLAN
BURLINGAME, CA 94010

Site 13 of 15 in cluster AQ

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI | **S113755771** | **N/A**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0012192
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0025184
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012192
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004674
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AQ730 **BAY CITIES COLLISION CTR** **San Mateo Co. BI** **S113757501**
NW **1028 CAROLAN** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.701 mi.
3703 ft. **Site 14 of 15 in cluster AQ**

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0026440
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0038327
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0026440
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0038326
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AU731 **SAN MATEO MOTORS** **RCRA-SQG** **1001115401**
ESE **704 N SAN MATEO DR** **FINDS** **CAR000013359**
1/2-1 **SAN MATEO, CA 94401** **ECHO**
0.705 mi.
3722 ft. **Site 4 of 6 in cluster AU**

Relative:
Higher

Actual:
38 ft.

RCRA-SQG:

Date form received by agency:	06/24/1996
Facility name:	SAN MATEO MOTORS
Facility address:	704 N SAN MATEO DR SAN MATEO, CA 94401
EPA ID:	CAR000013359
Contact:	LAKHNINDER SINGH
Contact address:	704 N SAN MATEO DR SAN MATEO, CA 944102224
Contact country:	US
Contact telephone:	(415) 347-1111
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	HARJIT KAELEY
Owner/operator address:	106 ESCANYO DR SOUTH SAN FRANCISCO, CA 94080
Owner/operator country:	Not reported
Owner/operator telephone:	(415) 615-0813
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

SAN MATEO MOTORS (Continued) **1001115401**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110008286737

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:
- Envid: 1001115401
- Registry ID: 110008286737
- DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110008286737

AU732 **MA'S AUTO REPAIR & SMOG STATION** **San Mateo Co. BI** **S109048894**
ESE **704 SAN MATEO** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.705 mi.
3722 ft. **Site 5 of 6 in cluster AU**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
- Region: SAN MATEO
- Facility ID: FA0037691
- Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
- Record Id: PR0054663
- Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
- Facility Status: INACTIVE

- Region: SAN MATEO
- Facility ID: FA0037691
- Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
- Record Id: PR0054662
- Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
- Facility Status: INACTIVE

MA'S AUTO REPAIR & SMOG STATION (Continued) **S109048894**

Region: SAN MATEO
Facility ID: FA0040785
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0056609
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0055820
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0076921
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0055820
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0076920
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

AU733 **MARTIN AUTO COLOR INC** **San Mateo Co. BI** **S113145231**
ESE **305 VILLA TERRACE** **HAZNET** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.710 mi.
3751 ft. **Site 6 of 6 in cluster AU**

Relative:
Higher

Actual:
38 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0055486
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0076517
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

HAZNET:
envid: S113145231
Year: 2010
GEPAID: CAL000313640
Contact: MICHAEL ACKERMAN, MANAGER
Telephone: 6503483242
Mailing Name: Not reported
Mailing Address: 305 VILLA TER
Mailing City,St,Zip: SAN MATEO, CA 944012218
Gen County: Not reported
TSD EPA ID: CAD008252405
TSD County: Not reported
Waste Category: Unspecified solvent mixture
Disposal Method: Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.108
Cat Decode: Unspecified solvent mixture
Method Decode: Fuel Blending Prior To Energy Recovery At Another Site
Facility County: San Mateo

envid: S113145231
Year: 2007
GEPAID: CAL000313640

MARTIN AUTO COLOR INC (Continued) **S113145231**

Contact:	ROSIE MORSE
Telephone:	6503483242
Mailing Name:	Not reported
Mailing Address:	305 VILLA TER
Mailing City,St,Zip:	SAN MATEO, CA 944012218
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Unspecified solvent mixture
Disposal Method:	Solvents Recovery
Tons:	0.05
Cat Decode:	Unspecified solvent mixture
Method Decode:	Solvents Recovery
Facility County:	San Mateo

AQ734 **ARATA HONDA** **HIST UST** **U001593895**
NW **1020 CALOLAN AVE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.716 mi.
3783 ft. **Site 15 of 15 in cluster AQ**

Relative:
Lower

Actual:
9 ft.

HIST UST:

File Number:	0002BB9C
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BB9C.pdf
Region:	STATE
Facility ID:	00000021935
Facility Type:	Other
Other Type:	DEALER
Contact Name:	AL ARATA
Telephone:	4153482233
Owner Name:	ARATA MOTOR SALES
Owner Address:	100 CALIF. DR.
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0004
Tank Num:	001
Container Num:	001
Year Installed:	1980
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	Not reported

ARATA HONDA (Continued) **U001593895**

Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

AS735 **SHERATON GATEWAY HOTEL SFIA** **San Mateo Co. BI** **S113755699**
NNE **600 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.717 mi.
3788 ft. **Site 3 of 5 in cluster AS**

Relative:
Lower

Actual:
12 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0011654
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004739
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AS736 **HILTON SAN FRANCISCO AIRPORT** **San Mateo Co. BI** **S113755416**
NNE **600 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.717 mi.
3788 ft. **Site 4 of 5 in cluster AS**

Relative:
Lower

Actual:
12 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0008100
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0071363
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AV737 **BAY PARK PLAZA** **San Mateo Co. BI** **S113758462**
NNE **577/555 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.724 mi.
3821 ft. **Site 1 of 2 in cluster AV**

Relative:
Lower

Actual:
14 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0038430
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0054934
Description:	STORES MV FUELS OR WASTE ONLY

BAY PARK PLAZA (Continued) **S113758462**

Facility Status: INACTIVE

AV738 **HUDSON BAY PARK PLAZA** **San Mateo Co. BI** **S117976197**
NNE **555/577 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.724 mi.
3821 ft. **Site 2 of 2 in cluster AV**

Relative:
Lower

Actual:
14 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0058246
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0080753
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

AS739 **VIRGIN AMERICA INC** **San Mateo Co. BI** **S113758415**
NNE **555 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.725 mi.
3828 ft. **Site 5 of 5 in cluster AS**

Relative:
Lower

Actual:
13 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0037458
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0054250
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: ACTIVE

AW740 **CHEVRON STATION NO 93989** **RCRA NonGen / NLR** **1006804956**
East **880 N DELAWARE ST** **FINDS** **CAR000118893**
1/2-1 **SAN MATEO, CA 94401** **HAZNET**
0.727 mi. **ECHO**
3840 ft. **Site 1 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

RCRA NonGen / NLR:
Date form received by agency: 03/13/2013
Facility name: CHEVRON STATION NO 93989
Facility address: 880 N DELAWARE ST
SAN MATEO, CA 94401 1504
EPA ID: CAR000118893
Mailing address: PO BOX 6004
SAN RAMON, CA 94583
Contact: KATHY NORRIS SLUSHER
Contact address: PO BOX 6004
SAN RAMON, CA 94583
Contact country: US
Contact telephone: 877-386-6044
Contact email: NAWTDESK@CHEVRON.COM
EPA Region: 09
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CHEVRON STATION NO 93989 (Continued) **1006804956**

Owner/Operator Summary:
Owner/operator name: CHEVRON USA
Owner/operator address: PO BOX 6004
SAN RAMON, CA 94583
Owner/operator country: US
Owner/operator telephone: 877-386-6044
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/08/1968
Owner/Op end date: Not reported

Owner/operator name: KATHY NORRIS SLUSHER
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/08/1968
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/16/2002
Site name: CHEVRON STATION NO 93989
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110013310960

Environmental Interest/Information System

CHEVRON STATION NO 93989 (Continued) **1006804956**

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:

envid:	1006804956
Year:	2005
GEPAID:	CAR000118893
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD009452657
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	0.32
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Recycler
Facility County:	San Mateo

envid:	1006804956
Year:	2004
GEPAID:	CAR000118893
Contact:	Kathy Norris
Telephone:	9258425931
Mailing Name:	Not reported
Mailing Address:	PO BOX 6004
Mailing City,St,Zip:	San Ramon, CA 94583
Gen County:	Not reported
TSD EPA ID:	CAD982444481
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Recycler
Tons:	0.02
Cat Decode:	Other organic solids
Method Decode:	Recycler
Facility County:	San Mateo

ECHO:

Envid:	1006804956
Registry ID:	110013310960
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110013310960

AW741 **CHEVRON STATION** **LUST** **S103894103**
East **880 DELAWARE** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401** **HIST CORTESE**
0.727 mi.
3840 ft. **Site 2 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

LUST:

Region:	STATE
Global Id:	T0608100943
Latitude:	37.580096
Longitude:	-122.33395
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/15/2004
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1030
LOC Case Number:	110108
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100943
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100943
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100943
Status:	Completed - Case Closed
Status Date:	03/15/2004

Global Id:	T0608100943
Status:	Open - Case Begin Date
Status Date:	10/25/1996

Global Id:	T0608100943
Status:	Open - Site Assessment
Status Date:	10/25/1996

Global Id:	T0608100943

CHEVRON STATION (Continued) **S103894103**

Status: Open - Verification Monitoring
Status Date: 07/10/2003

Regulatory Activities:

Global Id: T0608100943
Action Type: ENFORCEMENT
Date: 07/10/2003
Action: Staff Letter - #20030710

Global Id: T0608100943
Action Type: ENFORCEMENT
Date: 01/20/2004
Action: Staff Letter - #20040120

Global Id: T0608100943
Action Type: ENFORCEMENT
Date: 01/28/1997
Action: Notice of Responsibility - #1

Global Id: T0608100943
Action Type: ENFORCEMENT
Date: 03/15/2004
Action: Closure/No Further Action Letter - #20040315

Global Id: T0608100943
Action Type: Other
Date: 10/25/1996
Action: Leak Discovery

Global Id: T0608100943
Action Type: Other
Date: 01/22/1997
Action: Leak Reported

Global Id: T0608100943
Action Type: REMEDIATION
Date: 10/25/1996
Action: Excavation

Global Id: T0608100943
Action Type: ENFORCEMENT
Date: 08/03/2000
Action: Staff Letter - #20000803

Global Id: T0608100943
Action Type: RESPONSE
Date: 02/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100943
Action Type: RESPONSE
Date: 10/31/2003
Action: Request for Closure

Global Id: T0608100943
Action Type: RESPONSE
Date: 04/20/2004

CHEVRON STATION (Continued) **S103894103**

Action: Unknown

Global Id: T0608100943
Action Type: RESPONSE
Date: 08/15/2003
Action: Monitoring Report - Quarterly

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110108
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: 1/1/1965
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: 7/10/2003

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016907
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0044481
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0016907
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0023714
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0016907
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022109
Description: UNDERGROUND TANK - GENERAL
Facility Status: ACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1030

AW742 **PENINSULA CHEVRON** **LUST** **S101593949**
East **880 N DELAWARE** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94401** **HIST UST**
0.727 mi. **CA FID UST**
3840 ft. **Site 3 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110108
Facility Status:	9- Case Closed
Global ID:	T0608100943
APN Number:	033010060
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SWEEPS UST:

Status:	Active
Comp Number:	110033
Number:	2
Board Of Equalization:	Not reported
Referral Date:	04-12-94
Action Date:	04-12-94
Created Date:	10-13-88
Owner Tank Id:	002136
SWRCB Tank Id:	41-000-110033-000001
Tank Status:	A
Capacity:	10000
Active Date:	04-12-94
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	4

Status:	Active
Comp Number:	110033
Number:	2
Board Of Equalization:	Not reported
Referral Date:	04-12-94
Action Date:	04-12-94
Created Date:	10-13-88
Owner Tank Id:	002138
SWRCB Tank Id:	41-000-110033-000002
Tank Status:	A
Capacity:	10000
Active Date:	04-12-94
Tank Use:	M.V. FUEL
STG:	P
Content:	PRM UNLEADED
Number Of Tanks:	Not reported

Status:	Active
Comp Number:	110033
Number:	2
Board Of Equalization:	Not reported
Referral Date:	04-12-94
Action Date:	04-12-94
Created Date:	10-13-88
Owner Tank Id:	002137
SWRCB Tank Id:	41-000-110033-000003

PENINSULA CHEVRON (Continued) **S101593949**

Tank Status: A
Capacity: 10000
Active Date: 04-12-94
Tank Use: M.V. FUEL
STG: P
Content: PLUS UNLEADE
Number Of Tanks: Not reported

Status: Active
Comp Number: 110033
Number: 2
Board Of Equalization: Not reported
Referral Date: 04-12-94
Action Date: 04-12-94
Created Date: 10-13-88
Owner Tank Id: UNK
SWRCB Tank Id: 41-000-110033-000004
Tank Status: A
Capacity: 10000
Active Date: 04-12-94
Tank Use: M.V. FUEL
STG: P
Content: DIESEL
Number Of Tanks: Not reported

HIST UST:
File Number: 0002BCE8
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BCE8.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 41003378
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported

PENINSULA CHEVRON (Continued) **S101593949**

Facility Phone: 4153488870
Mail To: Not reported
Mailing Address: 880 N DELAWARE
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN MATEO 94401
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

---

743 **CHEVRON STATION #0056** **LUST** **S101593686**
SE **610 N EL CAMINO REAL** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94401** **CA FID UST**
0.732 mi.
3863 ft.

Relative:
Higher

Actual:
47 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110016
Facility Status: 9- Case Closed
Global ID: T0608100142
APN Number: 032141320
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 110036
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: 0

CA FID UST:
Facility ID: 41000162
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4150000000
Mail To: Not reported
Mailing Address: 2 ANNABEL LN
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN MATEO 94401

CHEVRON STATION #0056 (Continued) **S101593686**

Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

AW744 **CVS PHARMACY NO 9940** **RCRA-LQG 1016168152**
East **872 N DELAWARE** **FINDS CAR000240531**
1/2-1 **SAN MATEO, CA 94401** **ECHO**
0.733 mi.
3872 ft. **Site 4 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

RCRA-LQG:
Date form received by agency: 06/19/2013
Facility name: CVS PHARMACY NO 9940
Facility address: 872 N DELAWARE
SAN MATEO, CA 94401
EPA ID: CAR000240531
Mailing address: ONE CVS DR
WOONSOCKET, RI 02895
Contact: WENDY L BRANT
Contact address: ONE CVS DR
WOONSOCKET, RI 02895
Contact country: US
Contact telephone: 401-765-1500
Contact email: WENDY.BRANT@CVSCAREMARK.COM
EPA Region: 09
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: LONGS DRUG STORES CALIFORNIA LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/22/2008
Owner/Op end date: Not reported

Owner/operator name: PENINSULA INVESTORS LP
Owner/operator address: 2187 NEWCASTLE AVE STE 202
CARDIFF, CA 92007

CVS PHARMACY NO 9940 (Continued) **1016168152**

Owner/operator country: US
Owner/operator telephone: 760-944-9700
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/01/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Violation Status: No violations found

FINDS:

Registry ID: 110055523116

CVS PHARMACY NO 9940 (Continued) **1016168152**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

STATE MASTER

ECHO:
Envid: 1016168152
Registry ID: 110055523116
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110055523116

AT745 **LES VOGEL** **LUST** **S109285862**
NW **1007 ROLLINS** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.734 mi.
3875 ft. **Site 2 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

LUST:
Region: STATE
Global Id: T0608189622
Latitude: 37.587503
Longitude: -122.356376
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 04/28/2000
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
LOC Case Number: 669083
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608189622
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608189622
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO

LES VOGEL (Continued) **S109285862**

Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608189622
Status: Completed - Case Closed
Status Date: 04/28/2000

Global Id: T0608189622
Status: Open - Case Begin Date
Status Date: 08/11/1998

Regulatory Activities:
Global Id: T0608189622
Action Type: Other
Date: 08/11/1998
Action: Leak Reported

Global Id: T0608189622
Action Type: ENFORCEMENT
Date: 08/31/1998
Action: * Historical Enforcement - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 669083
Facility Status: 9- Case Closed
Global ID: T0608189622
APN Number: 026240360
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

AT746 **LES VOGEL DODGE** **RCRA-SQG** **1000597473**
NW **1007 ROLLINS RD** **SWEEPS UST** **CAD983614868**
1/2-1 **BURLINGAME, CA 94010** **CA FID UST**
0.734 mi. **FINDS**
3875 ft. **Site 3 of 11 in cluster AT** **HAZNET**
ECHO

Relative:
Lower

Actual:
9 ft.

RCRA-SQG:
Date form received by agency: 12/09/1998
Facility name: LES VOGEL DODGE
Facility address: 1007 ROLLINS RD
BURLINGAME, CA 94010
EPA ID: CAD983614868
Contact: DAVID SCOTT
Contact address: 1007 ROLLINS RD
BURLINGAME, CA 94010
Contact country: US
Contact telephone: (650) 342-2120
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of

LES VOGEL DODGE (Continued) **1000597473**

hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: PHIL VOGEL
Owner/operator address: 1007 ROLLINS RD
BURLINGAME, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (650) 342-2120
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

SWEEPS UST:
Status: Not reported
Comp Number: 660067
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660067-000001
Tank Status: Not reported
Capacity: 550
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: 2

Status: Not reported
Comp Number: 660067

LES VOGEL DODGE (Continued) **1000597473**

Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660067-000002
Tank Status: Not reported
Capacity: 250
Active Date: Not reported
Tank Use: UNKNOWN
STG: WASTE
Content: Not reported
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41002958
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4155794221
Mail To: Not reported
Mailing Address: 1007 ROLLINS RD
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94010
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

FINDS:

Registry ID: 110009549131

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET:
envid: 1000597473
Year: 2001
GEPAID: CAD983614868
Contact: SERVICE MANAGER
Telephone: --
Mailing Name: Not reported
Mailing Address: 1007 ROLLINS RD
Mailing City,St,Zip: BURLINGAME, CA 940100000

LES VOGEL DODGE (Continued) **1000597473**

Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.3
Cat Decode:	Other organic solids
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000597473
Year:	2000
GEPAID:	CAD983614868
Contact:	SERVICE MANAGER
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1007 ROLLINS RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Transfer Station
Tons:	0.5
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000597473
Year:	2000
GEPAID:	CAD983614868
Contact:	SERVICE MANAGER
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1007 ROLLINS RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Other organic solids
Disposal Method:	Transfer Station
Tons:	0.45
Cat Decode:	Other organic solids
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000597473
Year:	2000
GEPAID:	CAD983614868
Contact:	SERVICE MANAGER
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1007 ROLLINS RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported

LES VOGEL DODGE (Continued) **1000597473**

Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Recycler
Tons:	1.37
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Recycler
Facility County:	San Mateo

envid:	1000597473
Year:	2000
GEPAID:	CAD983614868
Contact:	SERVICE MANAGER
Telephone:	--
Mailing Name:	Not reported
Mailing Address:	1007 ROLLINS RD
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	Not reported
TSD EPA ID:	CAL000161743
TSD County:	Not reported
Waste Category:	Aqueous solution with total organic residues less than 10 percent
Disposal Method:	Transfer Station
Tons:	0.5
Cat Decode:	Aqueous solution with total organic residues less than 10 percent
Method Decode:	Transfer Station
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
10 additional CA_HAZNET: record(s) in the EDR Site Report.

ECHO:

Envid:	1000597473
Registry ID:	110009549131
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110009549131

AT747 **MIKE HARVEY TOYOTA** **San Mateo Co. BI** **S113755240**
NW **1007 ROLLINS** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.734 mi.
3875 ft. **Site 4 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0002803
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022011
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AT748 **FOUR CAR GARAGE INC** **San Mateo Co. BI** **S113756032**
NW **1007 ROLLINS** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.734 mi.
3875 ft. **Site 5 of 11 in cluster AT**

Relative: **Lower**

Actual: **9 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0058402
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0080931
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0058402
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0080930
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0014608
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023924
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0014608
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004747
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0014608
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022784
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

AW749 **PETCO #5313** **San Mateo Co. BI** **S114561931**
East **866 DELAWARE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.736 mi.
3888 ft. **Site 5 of 7 in cluster AW**

Relative: **Lower**

Actual: **25 ft.**

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0054807
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0075584
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

AT750 **CALBAY** **San Mateo Co. BI** **S113758664**
NW **1009 ROLLINS ROAD** **EMI** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.737 mi.
3890 ft. **Site 6 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0045009
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0057272
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0045009
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0057271
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

EMI:

Year:	2012
County Code:	41
Air Basin:	SF
Facility ID:	21169
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.496
Reactive Organic Gases Tons/Yr:	0.389879
Carbon Monoxide Emissions Tons/Yr:	0.002
NOX - Oxides of Nitrogen Tons/Yr:	0.007
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2013
County Code:	41
Air Basin:	SF
Facility ID:	21169
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.206
Reactive Organic Gases Tons/Yr:	0.152263
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2014
County Code:	41
Air Basin:	SF

CALBAY (Continued) **S113758664**

Facility ID:	21169
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.205285895
Reactive Organic Gases Tons/Yr:	0.205285525
Carbon Monoxide Emissions Tons/Yr:	6.817e-006
NOX - Oxides of Nitrogen Tons/Yr:	2.7312e-005
SOX - Oxides of Sulphur Tons/Yr:	1.11e-007
Particulate Matter Tons/Yr:	5.84e-007
Part. Matter 10 Micrometers and Smllr Tons/Yr:	5.84e-007

AW751 **SAFEWAY 0694** **San Mateo Co. BI** **S112057049**
East **860 DELAWARE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.739 mi.
3904 ft. **Site 6 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0001582
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0071625
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0001582
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0075334
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

AT752 **MIKE HARVEY OLSMOBILE** **RCRA-SQG** **1000196960**
NW **1008 ROLLINS RD** **HIST UST** **CAD981580756**
1/2-1 **BURLINGAME, CA 94010** **FINDS**
0.740 mi. **ECHO**
3908 ft. **Site 7 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

RCRA-SQG:

Date form received by agency:	09/01/1996
Facility name:	MIKE HARVEY OLSMOBILE
Facility address:	1008 ROLLINS RD BURLINGAME, CA 94010
EPA ID:	CAD981580756
Contact:	Not reported
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous

MIKE HARVEY OLSMOBILE (Continued) **1000196960**

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MIKE HARVEY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/25/1986
Site name: MIKE HARVEY OLSMOBILE
Classification: Large Quantity Generator

Violation Status: No violations found

HIST UST:
File Number: 0002C0AC
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C0AC.pdf
Region: STATE
Facility ID: 00000038202
Facility Type: Not reported

MIKE HARVEY OLSMOBILE (Continued) **1000196960**

Other Type:	NEW CAR DEALERSHIP
Contact Name:	JERRY E. HOSKING
Telephone:	4153426453
Owner Name:	MR. M. HARVEY
Owner Address:	P.O. BOX 511
Owner City,St,Zip:	BURLINGAME, CA 94010
Total Tanks:	0004
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Visual, None
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00001500
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	004
Container Num:	4
Year Installed:	1980
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Visual, None

Click here for Geo Tracker PDF:

FINDS:

Registry ID: 110008270209

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MIKE HARVEY OLSMOBILE (Continued) **1000196960**

ECHO:
Envid: 1000196960
Registry ID: 110008270209
DFR URL: http://echo.epa.gov/detailed_facility_report?fid=110008270209

AW753 **HOLIDAY CLEANERS** **ENVIROSTOR** **S100932195**
East **850 DELAWARE** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.745 mi.
3931 ft. **Site 7 of 7 in cluster AW**

Relative:
Lower

Actual:
25 ft.

ENVIROSTOR:
Facility ID: 41720099
Status: Refer: Other Agency
Status Date: 07/29/1994
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 0.04
NPL: NO
Regulatory Agencies: SAN MATEO COUNTY
Lead Agency: SAN MATEO COUNTY
Program Manager: Not reported
Supervisor: Denise Tsuji
Division Branch: Cleanup Berkeley
Assembly: 22
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.57916
Longitude: -122.3336
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 41720099
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 10/15/1980
Comments: FACILITY IDENTIFIED ACTIVE SITE ID'D BY DRIVE BY

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 08/18/2003
Comments: Site screening completed. The local agency permits and oversee activities at the site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported

HOLIDAY CLEANERS (Continued) **S100932195**

Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0005322
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0010713
Description: GENERATES <27 GAL/YEAR
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0005322
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0003419
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0058159
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0080648
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

AX754 **RESIDENCE** **SWEEPS UST** **S106922204**
South **632 OCCIDENTAL** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.745 mi.
3935 ft. **Site 1 of 4 in cluster AX**

Relative:
Higher

Actual:
95 ft.

SWEEPS UST:
Status: Not reported
Comp Number: 110200
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110200-000001
Tank Status: Not reported
Capacity: 350
Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: DIESEL
Number Of Tanks: 1

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016358
Prog Element Code: UNDERGROUND TANK - GENERAL

RESIDENCE (Continued) **S106922204**

Record Id: PR0022218
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

AT755 **ANCHOR DETAILING** **San Mateo Co. BI** **S113058650**
NW **1008 CAROLAN AVE STE B** **HAZNET** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.745 mi.
3935 ft. **Site 8 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0060083
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0082539
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0060083
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0082538
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

HAZNET:
envid: S113058650
Year: 2014
GEPAID: CAL000097035
Contact: ANDREW KLINK
Telephone: 6505792776
Mailing Name: Not reported
Mailing Address: 1008 CAROLAN AVE STE B
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: NVT330010000
TSD County: 99
Waste Category: Unspecified organic liquid mixture
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.544
Cat Decode: Unspecified organic liquid mixture
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

envid: S113058650
Year: 2014
GEPAID: CAL000097035
Contact: ANDREW KLINK
Telephone: 6505792776
Mailing Name: Not reported
Mailing Address: 1008 CAROLAN AVE STE B
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAT080012602
TSD County: Solano

ANCHOR DETAILING (Continued) **S113058650**

Waste Category:	Unspecified oil-containing waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.251
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

envid:	S113058650
Year:	2013
GEPAID:	CAL000097035
Contact:	ANDREW KLINK
Telephone:	6505792776
Mailing Name:	Not reported
Mailing Address:	1008 CAROLAN AVE STE B
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CAD059494310
TSD County:	Santa Clara
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.1836
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

envid:	S113058650
Year:	2012
GEPAID:	CAL000097035
Contact:	ANDREW KLINK
Telephone:	6505792776
Mailing Name:	Not reported
Mailing Address:	1008 CAROLAN AVE STE B
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	ARD981057870
TSD County:	99
Waste Category:	Not reported
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.108
Cat Decode:	Not reported
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

envid:	S113058650
Year:	2012
GEPAID:	CAL000097035
Contact:	ANDREW KLINK
Telephone:	6505792776
Mailing Name:	Not reported
Mailing Address:	1008 CAROLAN AVE STE B
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	NVT330010000

ANCHOR DETAILING (Continued) **S113058650**

TSD County: 99
Waste Category: Not reported
Disposal Method: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.18765
Cat Decode: Not reported
Method Decode: Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Facility County: San Mateo

Click this hyperlink while viewing on your computer to access
18 additional CA_HAZNET: record(s) in the EDR Site Report.

AT756 **BAY CITIES COLLISION CTR** **San Mateo Co. BI** **S113756063**
NW **1017 ROLLINS** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.748 mi.
3949 ft. **Site 9 of 11 in cluster AT**

Relative: Lower

Actual: 9 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0014863
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0011951
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0014863
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0004750
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

AR757 **PENINSULA CAR CARE** **San Mateo Co. BI** **S109048895**
ESE **717 WOODSIDE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.749 mi.
3954 ft. **Site 2 of 2 in cluster AR**

Relative: Higher

Actual: 33 ft.

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0037692
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0054666
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0037692
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0054665
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

AT758 **ALFRED MOLAKDIS PROPERTIES** **LUST** **S104493546**
NW **1019 ROLLINS ROAD** **SLIC** **N/A**
1/2-1 **BURLINGAME, CA 94010** **HIST CORTESE**
0.751 mi.
3964 ft. **Site 10 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	669002
Facility Status:	9- Case Closed
Global ID:	T0608190888
APN Number:	026240370
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SLIC:

Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	12/31/1993
Global Id:	T0608190888
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669002
Latitude:	37.587642
Longitude:	-122.356906
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41S0015
File Location:	Local Agency
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0921

AT759 **TEEVAN EXTERIOR CONTRACTORS** **SLIC** **S101321700**
NW **1019 ROLLINS RD** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.751 mi.
3964 ft. **Site 11 of 11 in cluster AT**

Relative:
Lower

Actual:
9 ft.

SLIC REG 2:

Region:	2
Facility ID:	41S0015
Facility Status:	Preliminary site assessment workplan submitted
Date Closed:	Not reported
Local Case #:	Not reported
How Discovered:	Tank Closure
Leak Cause:	UNK
Leak Source:	UNK
Date Confirmed:	Not reported
Date Prelim Site Assmnt Workplan Submitted:	6/1/1986
Date Preliminary Site Assessment Began:	Not reported

TEEVAN EXTERIOR CONTRACTORS (Continued) **S101321700**

Date Pollution Characterization Began: Not reported
Date Remediation Plan Submitted: Not reported
Date Remedial Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

AX760 **RESIDENCE** **LUST** **S102431682**
South **706 EDGEWOOD** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94403**
0.765 mi.
4040 ft. **Site 2 of 4 in cluster AX**

Relative:
Higher

Actual:
91 ft.

LUST:

Region:	STATE
Global Id:	T0608100275
Latitude:	37.568656
Longitude:	-122.349807
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/22/1992
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0289
LOC Case Number:	110068
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100275
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100275
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100275
Status:	Completed - Case Closed
Status Date:	09/22/1992

Global Id:	T0608100275
Status:	Open - Case Begin Date
Status Date:	06/01/1992

RESIDENCE (Continued) **S102431682**

Regulatory Activities:

Global Id:	T0608100275
Action Type:	Other
Date:	06/01/1992
Action:	Leak Discovery
Global Id:	T0608100275
Action Type:	Other
Date:	06/01/1992
Action:	Leak Reported
Global Id:	T0608100275
Action Type:	ENFORCEMENT
Date:	09/22/1992
Action:	Notice of Responsibility - #1

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	110068
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110068
Facility Status:	9- Case Closed
Global ID:	T0608100275
APN Number:	031041170
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SWEEPS UST:

Status:	Not reported
Comp Number:	110166
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110166-000001
Tank Status:	Not reported
Capacity:	350

RESIDENCE (Continued) **S102431682**

Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	1
Status:	Active
Comp Number:	110166
Number:	2
Board Of Equalization:	Not reported
Referral Date:	11-10-93
Action Date:	11-10-93
Created Date:	07-08-92
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

AY761 **ZIMMERMAN RESIDENCE** **LUST** **S104493752**
SW **2135 RALSTON AVE** **N/A**
1/2-1 **HILLSBOROUGH, CA**
0.775 mi.
4090 ft. **Site 1 of 2 in cluster AY**

Relative:
Higher

Actual:
88 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	878011
Facility Status:	9- Case Closed
Global ID:	T0608100916
APN Number:	028252170
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

AX762 **MORISON PROPERTY** **LUST** **S101308759**
South **420 WESTMORELAND** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94402** **San Mateo Co. BI**
0.781 mi. **HIST CORTESE**
4125 ft. **Site 3 of 4 in cluster AX**

Relative:
Higher

Actual:
92 ft.

LUST:

Region:	STATE
Global Id:	T0608100689
Latitude:	37.568145
Longitude:	-122.347935
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	04/10/1996
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0728

MORISON PROPERTY (Continued) **S101308759**

LOC Case Number: 110084
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100689
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100689
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100689
Status: Completed - Case Closed
Status Date: 04/10/1996

Global Id: T0608100689
Status: Open - Case Begin Date
Status Date: 03/04/1993

Regulatory Activities:
Global Id: T0608100689
Action Type: ENFORCEMENT
Date: 03/04/1993
Action: Notice of Responsibility - #1

Global Id: T0608100689
Action Type: Other
Date: 04/01/2009
Action: Leak Discovery

Global Id: T0608100689
Action Type: Other
Date: 04/01/1993
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: Not reported

MORISON PROPERTY (Continued) **S101308759**

Facility Status: Case Closed
Case Number: 110084
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110084
Facility Status: 9- Case Closed
Global ID: T0608100689
APN Number: Not reported
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 110185
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110185-000001
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: OIL
STG: PRODUCT
Content: WASTE OIL
Number Of Tanks: 1

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0014348
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022205
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0728

AX763 **RESIDENCE** **LUST** **S102428975**
South **610 OCCIDENTAL** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94402** **San Mateo Co. BI**
0.788 mi. **HIST CORTESE**
4159 ft. **Site 4 of 4 in cluster AX**

Relative:
Higher

Actual:
99 ft.

LUST:

Region:	STATE
Global Id:	T0608100192
Latitude:	37.567882
Longitude:	-122.34812
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/07/1992
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	Not reported
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0202
LOC Case Number:	110058
File Location:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100192
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100192
Status:	Completed - Case Closed
Status Date:	08/07/1992
Global Id:	T0608100192
Status:	Open - Case Begin Date
Status Date:	06/07/1991
Global Id:	T0608100192
Status:	Open - Remediation
Status Date:	04/22/1992
Global Id:	T0608100192
Status:	Open - Remediation
Status Date:	06/18/1992
Global Id:	T0608100192
Status:	Open - Site Assessment
Status Date:	12/27/1991

Regulatory Activities:

Global Id:	T0608100192

RESIDENCE (Continued) **S102428975**

Action Type: Other
Date: 06/07/1991
Action: Leak Discovery

Global Id: T0608100192
Action Type: Other
Date: 06/07/1991
Action: Leak Reported

Global Id: T0608100192
Action Type: Other
Date: 06/07/1991
Action: Leak Stopped

LUST REG 2:
Region: 2
Facility Id: 41-0202
Facility Status: Case Closed
Case Number: 110058
How Discovered: Tank Closure
Leak Cause: Structure Failure
Leak Source: Tank
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: 12/27/1991
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: 4/22/1992
Date Remediation Action Underway: 6/18/1992
Date Post Remedial Action Monitoring Began: Not reported

SWEEPS UST:
Status: Not reported
Comp Number: 110142
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110142-000001
Tank Status: Not reported
Capacity: 350
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: 1

Status: Active
Comp Number: 110142
Number: 9
Board Of Equalization: Not reported
Referral Date: 11-10-93
Action Date: 11-10-93

RESIDENCE (Continued) **S102428975**

Created Date:	07-09-92
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0022952
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0025885
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0202

AZ764 **REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP** **LUST S108536388**
NE **370 LANG** **SLIC N/A**
1/2-1 **BURLINGAME, CA 94010**
0.794 mi.
4194 ft. **Site 1 of 3 in cluster AZ**

Relative:
Lower

Actual:
12 ft.

LUST:

Region:	STATE
Global Id:	T0608108772
Latitude:	37.5875130175821
Longitude:	-122.336913049221
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/12/2012
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	660100
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from Green Environment's July 7, 2010 second quarter 2010 groundwater monitoring report, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. Two (2) independent Phase I Environmental Site Assessments (ESAs) were conducted of the subject property by Kleinfelder, Inc. in January 1990 and ERAS Environmental, Inc. (ERAS) in February 2007, respectively. Both of the Phase I ESAs documented that a single 1,000- gallon underground gasoline storage tank (UST) was removed from the subject property in 1985 without the collection of

REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP (Continued) **S108536388**

confirmation soil or groundwater samples. It was recommended by both consultants that soil in the vicinity of the former UST be assessed for potential impact by petroleum hydrocarbons. Kleinfelder, Inc.s Phase I ESA also documented extensive paint staining on concrete flooring and around a sewer floor drain within a paint storage room in the northwest corner of the warehouse building on the subject property, and recommended soil sampling in this area to determine potential impact by paints and solvents. Two (2) preliminary subsurface investigations were performed by Green Environment inc. (GEI), the first in April 2007, and the second between December 8, 2007 and February 1, 2008. The subsurface investigations were documented in reports dated April 30, 2007 and April 11, 2008, respectively. The preliminary subsurface investigations were designed to determine the extent of petroleum hydrocarbons related to the former UST and volatile organic compounds (VOCs) related to the former paint storage area, in soil, soil vapor and groundwater at the subject property. Based on the results of the preliminary subsurface investigations, GEI performed interim remediation measures and an additional subsurface investigation between August of 2008 and January of 2009. The activities were summarized in GEIs Subsurface Investigation and Interim Remedial Report, dated March 17, 2009. The interim remediation measures consisted of soil excavations in the vicinity of the former UST and paint storage areas, and dewatering of petroleum hydrocarbon-impacted groundwater from the open excavations prior to backfilling. The purpose of the additional subsurface investigation was to assess the extent of off-site fuel hydrocarbons downgradient of the subject property.Based on review of GEIs Subsurface Investigation and Interim Remedial Report (GEI, March 17, 2009), the SMCoGPP identified data gaps with respect to the subject property meeting low risk criteria and presented those data gaps in a letter dated April 16, 2009. In order to address the data gaps outlined by SMCoGPP, GEI performed additional work at the SMCoGPP which included the installation of one (1) groundwater monitoring well within the former UST pit area (Well MW-1) as well as three (3) additional down-gradient groundwater monitoring wells (Wells MW-2, MW-3 and MW-4) to monitor and evaluate groundwater quality and flow direction trends over time (Well Installation and Soil Vapor Sampling Report, GEI January 22, 2010). Previous groundwater monitoring events have been conducted on October 9, 2009 and February 10, 2010. This report summarizes the third quarterly monitoring event overall, and the second quarterly event of 2010 (Q2 2010) which was conducted on May 28, 2010.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608108772
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608108772
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN

REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP (Continued) **S108536388**

Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608108772
Status: Completed - Case Closed
Status Date: 01/12/2012

Global Id: T0608108772
Status: Open - Case Begin Date
Status Date: 04/19/2007

Global Id: T0608108772
Status: Open - Site Assessment
Status Date: 05/03/2007

Regulatory Activities:
Global Id: T0608108772
Action Type: RESPONSE
Date: 05/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 01/12/2012
Action: Closure/No Further Action Letter - #20120112

Global Id: T0608108772
Action Type: RESPONSE
Date: 09/23/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608108772
Action Type: RESPONSE
Date: 04/10/2009
Action: Soil and Water Investigation Workplan

Global Id: T0608108772
Action Type: RESPONSE
Date: 10/29/2010
Action: Interim Remedial Action Report

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 02/10/2010
Action: Staff Letter - #20100210

Global Id: T0608108772
Action Type: RESPONSE
Date: 04/02/2009
Action: Soil and Water Investigation Report

Global Id: T0608108772

REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP (Continued) **S108536388**

Action Type: RESPONSE
Date: 12/31/2009
Action: Site Assessment Report

Global Id: T0608108772
Action Type: RESPONSE
Date: 07/16/2007
Action: Preliminary Site Assessment Workplan

Global Id: T0608108772
Action Type: RESPONSE
Date: 10/20/2007
Action: Other Workplan

Global Id: T0608108772
Action Type: RESPONSE
Date: 12/03/2007
Action: Other Report / Document

Global Id: T0608108772
Action Type: RESPONSE
Date: 03/30/2008
Action: Soil and Water Investigation Report

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 05/11/2010
Action: Staff Letter - #20100511

Global Id: T0608108772
Action Type: Other
Date: 04/19/2007
Action: Leak Discovery

Global Id: T0608108772
Action Type: Other
Date: 04/30/2007
Action: Leak Reported

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 05/16/2007
Action: Notice of Responsibility - #20070516

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 11/05/2007
Action: Staff Letter - #20071105B

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 09/28/2011
Action: Staff Letter - #20110928

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 09/19/2007

REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP (Continued) **S108536388**

Action: Staff Letter - #20070919

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 11/05/2007
Action: Staff Letter - #20071105A

Global Id: T0608108772
Action Type: REMEDIATION
Date: 08/23/2008
Action: Excavation

Global Id: T0608108772
Action Type: RESPONSE
Date: 08/15/2010
Action: Monitoring Report - Quarterly

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 04/16/2009
Action: Staff Letter - #20090416

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 07/08/2009
Action: Staff Letter - #20090708

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 11/17/2010
Action: Staff Letter - #20101117

Global Id: T0608108772
Action Type: RESPONSE
Date: 04/15/2011
Action: Risk Assessment Report - Regulator Responded

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 06/30/2010
Action: Staff Letter - #20100630

Global Id: T0608108772
Action Type: RESPONSE
Date: 10/23/2009
Action: Soil and Water Investigation Workplan

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 08/06/2009
Action: Staff Letter - #20090806

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 05/19/2011
Action: Staff Letter - #20110519

REAL ESTATE NORTH INVESTMENT PARTNERSHIP LP (Continued) **S108536388**

Global Id: T0608108772
Action Type: ENFORCEMENT
Date: 12/02/2008
Action: Staff Letter - #20081202

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 669104
Facility Status: 9- Case Closed
Global ID: T10000003038
APN Number: 026331260
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

Region: SAN MATEO
Facility ID: 660100
Facility Status: 9- Case Closed
Global ID: T0608108772
APN Number: 026331260
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SLIC:
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 08/15/2012
Global Id: T10000003038
Lead Agency: SAN MATEO COUNTY LOP
Lead Agency Case Number: 669104
Latitude: 37.5874365015934
Longitude: -122.33705252409
Case Type: Cleanup Program Site
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: Not reported
File Location: Not reported
Potential Media Affected: Other Groundwater (uses other than drinking water), Soil, Soil Vapor
Potential Contaminants of Concern: Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride
Site History: Site opened to deal with remaining VOC issues, see LUST site for more historical information.

Click here to access the California GeoTracker records for this facility:

BA765 **AUTOPRIDE CAR WASH** **LUST** **S104493509**
NW **1095 CAROLAN AVENUE** **HAZNET** **N/A**
1/2-1 **BURLINGAME, CA 94010** **HIST CORTESE**
0.799 mi.
4217 ft. **Site 1 of 4 in cluster BA**

Relative:
Lower

Actual:
8 ft.

LUST:
Region: STATE
Global Id: T0608100954
Latitude: 37.587677226
Longitude: -122.362455834
Case Type: LUST Cleanup Site
Status: Completed - Case Closed

AUTOPRIDE CAR WASH (Continued) **S104493509**

Status Date:	06/30/2011
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1041
LOC Case Number:	660080
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from RRM's September 9, 2004 Feasibility Study Corrective Action Plan, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The Auto Pride Car Wash facility is located in a mixed commercial/residential area just north of the downtown section of Burlingame. The site is a narrow strip of land bordered by Carolan Avenue to the north, the Cal Train right-of-way to the south, a vacant lot to the east and Broadway Avenue to the west. The city block across Carolan Avenue is the address of the Mike Harvey automobile dealership complex, including an Audi Porsche showroom directly across the street. Land use at the properties surrounding the site is commercial and residential. The site bas two gasoline dispensing islands, three gasoline underground storage tanks (USTs), and a oar wash unit. The Cable Car Wash Company, Inc. built a car wash and gas station at the site in 1973. The operation was sold to Rapid Car Wash in 1975. Auto Pride Car Wash purchased the business in 1982. The existing USTs, distribution lines, and dispensers were installed in 1999 to replace the first generation of storage and dispensing equipment. The original car wash utilized three 10,000-gallon USTs and two dispensing islands. In June 1996, prior to the sale of the property to San Mateo County Transit District, Geomatrix drilled five brings to 22 feet below grade to collect grab groundwater samples. Petroleum hydrocarbons were detected in all five &groundwater samples, with the highest concentrations of total petroleum hydrocarbons as gasoline (TPHg) and benzene 9,300 parts per billion (ppb) and 690 ppb, respectively, occurring at Boring B3, located down gradient (east) of the pump islands. VOCs were detected in groundwater samples at relatively low concentrations. In December 1998, Environmental Resource Group, Inc. (ERG) conducted Phase I1 site characterization work based on a work plan prepared by RRM in July 1998. Work included the collection of 14 grab-groundwater samples outside the site boundaries, and the installation of six groundwater-monitoring wells (MW-1 through MW-6. During this same period, RRM performed a soil vapor extraction (SVE) performance test. The studies revealed gasoline and MtBE impact to groundwater extending northeasterly from the pump islands at the Auto Pride site. Gasoline impact to groundwater was shown to extend approximately 200 feet beyond the site boundary, while MtBE was estimated to extend at least 6M) feet offsite. According to ERG, the site subsurface appeared unsuitable for soil vapor extraction because of the very shallow depth to groundwater and fine grained soil. Auto Pride contracted with DECON to remove the existing UST and distribution system and upgrade the Facility with new double wall tanks, lines and dispensers. Since it was shown that petroleum hydrocarbons affected soil at the site, remedial soil excavation was conducted at the time of the UST system upgrade. Between December 22, 1998 and January 7, 1999, RRM was present at the site during product-island, piping, and UST removal, and remedial excavation to collect confirmation soil

AUTOPRIDE CAR WASH (Continued) **S104493509**

samples from the excavation sidewalls. Details are summarized below. Pump Island Area Soil Boring: On December 22, 1998, four soil borings (SB-I, SB-2, SB-3, and SB-5) were advanced to 11 feet below ground surface bgs), and one boring (SB-4) was advanced to 22 feet bgs. The deeper boring was advanced to delineate the vertical extent of soil contamination in the present are of maximum impact. Nine soil samples collected between 5 and 22 feet bgs were analyzed for TPHg; benzene, toluene, ethylbenzene, and xylenes (BTEX); and MtBE. TPHg was detected in four of nine soil samples at concentrations up to 770 parts per million (ppm). Benzene was detected in three of nine soil samples at concentrations up to 0.012ppm. MtBE was detected in three of nine soil samples at concentrations up to 51 ppm. TPHg and MtBE contamination extended 12 to 15 feet below grade. Pump Island Area Remedial Excavation: DECON removed the dispensers, light stands and concrete pads. DECON then excavated soil from beneath the pump island, creating an open excavation approximately 40 feet by 20 feet by 7 feet deep. On December 31, 1998 and January 4, 1999, RRM collected seven soil samples at 5 feet bgs from the excavation sidewalls for analysis of TPH& BTEX, and MtBE. TPHg was detected in all seven samples at concentrations up to 1,100ppm. Benzene was detected in six of seven soil samples at concentrations up to 1.6 ppm MtBE was detected in three of seven soil samples at concentration up to 7.1 ppm. Tank Pull and Tank Area Over-Excavation and Dewatering: DECON removed three 10,000-gallon USTs in the presence of San Mateo County Health Services Agency (SMCHSA) inspectors. On January 6, 1999, at the request of the SMCHSA inspection, RRM obtained six soil samples from native soils underlying the USTs and had the samples analyzed for TPHg, BTEX, and MtBE. TPHg was detected in all six samples at concentrations up to 9,000 ppm. Benzene was detected in all six samples at concentrations up to 20 ppm. MtBE was detected in one of six soil samples at a concentration of 93ppm. At the request of the SMCHSA, DECON expanded the tank excavation to the maximum extent possible, considering the presence of utility lines and structures. On January 7, 1999, SMCHSA inspectors directed RRM to obtain nine confirmation soil samples at 5 feet bgs from the excavation sidewalls. The samples were analyzed for TPHg, BTEX, and MtBE. TPHg was detected in three of nine soil samples at concentrations up to 2,000 ppm. Benzene was detected in two of nine soil samples at concentrations up to 1.4 ppm. MtBE was detected in three of nine soil samples at concentrations up to 51 pmm. The highest contaminant concentrations were detected in soil samples collected from the floor of the excavation beneath the area of the former USTs. In all, approximately 500 tons of contaminated soil was transported to BFI Ox Mountain Landfill for disposal. DECON dewatered the excavation periodically from January 6, 1999 to January 20, 1999. Approximately 151,500 gallons of water were removed from the excavation during this period. DECON treated the water prior to discharge (under permit) to the sewer. Additional groundwater was removed from the excavation as part of UST installation work. From January 27 to February 15, 1999, DECON treated and discharge to the sewer an additional 80,000 gallons of water. On September 5, 2001, two groundwater-monitoring wells (MW-7 and MW-8) were installed under the supervision of RRM. The wells were installed according to an RRM work plan dated December 16, 1999, and approved by the SMCHSA. Four soil samples each were collected from wells MW-7 and MW-8 for chemical analysis. TPHg was detected in one of eight soil samples at 150 ppm. This sample was collected from Well MW-7 at a depth of

AUTOPRIDE CAR WASH (Continued) **S104493509**

approximately 6 feet bgs. Benzene was detected in two of eight soil samples. The sample collected from Well MW-7 at approximately 6 feet bgs contained 0.24 ppm benzene, and the sample collected from Well MW-8 at approximately 6 feet bgs contained 0.14 ppm benzene. MtBE was detected in three of eight soil samples; the maximum concentration, 0.17 ppm, was detected in the soil sample collected firm MW-8 at a depth of approximately 11 feet bgs. A door-to-door well survey was performed for the site at the request of the SMCHSA. The methodology for the door-to-door well survey was presented in RRM's October24, 2002 letter titled Proposed Well Survey Radius. A well survey radius of 188 feet was proposed in the latter. SMCHSA approved the proposed survey methodology in an October 29, 2002 correspondence. Five properties were located within the survey radius. Property representatives for each of the sites indicated that no wells or basements with sumppumps are located on the properties. Currently, monitoring wells MW-1 through MW-8 are monitored and sampled on a quarterly basis. Wells MW-1 through MW-6 have been monitored and sampled since December 1998. Wells MW-7 and MW-8 have been monitored and sampled since September 2001. Groundwater samples are analyzed for TPHg, total petroleum hydrocarbons as diesel (TPHd), BTEX and MtBE. From December 1998 to June 2000, groundwater samples collected from wells MW-1 through MW-6 were also analyzed for chlorinated solvents.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100954
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100954
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100954
Status:	Completed - Case Closed
Status Date:	06/30/2011

Global Id:	T0608100954
Status:	Open - Case Begin Date
Status Date:	06/14/1996

Global Id:	T0608100954
Status:	Open - Remediation
Status Date:	11/17/2004

AUTOPRIDE CAR WASH (Continued) **S104493509**

Global Id: T0608100954
Status: Open - Site Assessment
Status Date: 06/14/1996

Global Id: T0608100954
Status: Open - Site Assessment
Status Date: 07/01/2001

Global Id: T0608100954
Status: Open - Verification Monitoring
Status Date: 04/04/2007

Regulatory Activities:
Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 10/01/1996
Action: Notice of Responsibility - #1

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 08/23/2006
Action: Staff Letter - #20060823

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 01/25/2005
Action: Staff Letter - #20050125

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 10/29/2002
Action: Staff Letter - #20021029

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 09/11/2007
Action: Staff Letter - #20070911

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 06/06/2006
Action: Staff Letter - #20060606

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 11/17/2004
Action: Staff Letter - #20041117

Global Id: T0608100954
Action Type: RESPONSE
Date: 10/16/2009
Action: Other Report / Document

Global Id: T0608100954
Action Type: RESPONSE
Date: 02/15/2004
Action: Monitoring Report - Quarterly

AUTOPRIDE CAR WASH (Continued) **S104493509**

Global Id: T0608100954
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: Other
Date: 06/14/1996
Action: Leak Discovery

Global Id: T0608100954
Action Type: Other
Date: 10/01/1996
Action: Leak Reported

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 05/14/2009
Action: Staff Letter - #20090514

Global Id: T0608100954
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Annually

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 07/21/2010
Action: Notification - Fee Title Owners Notice - #20100721

Global Id: T0608100954
Action Type: RESPONSE
Date: 01/15/2011
Action: Well Destruction Report

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 08/28/2008
Action: Staff Letter - #20080828A

Global Id: T0608100954
Action Type: RESPONSE
Date: 03/17/2009
Action: Other Report / Document

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 07/07/2009
Action: Staff Letter - #20090707

Global Id: T0608100954
Action Type: RESPONSE
Date: 12/21/2006
Action: CAP/RAP - Other Report

Global Id: T0608100954
Action Type: RESPONSE

AUTOPRIDE CAR WASH (Continued) **S104493509**

Date: 08/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 02/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 05/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 08/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 11/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 08/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 02/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 08/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 02/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100954
Action Type: RESPONSE
Date: 01/19/2005
Action: Soil and Water Investigation Workplan

Global Id: T0608100954
Action Type: RESPONSE
Date: 05/24/2005
Action: Soil and Water Investigation Report

AUTOPRIDE CAR WASH (Continued) **S104493509**

Global Id: T0608100954
Action Type: RESPONSE
Date: 08/01/2006
Action: CAP/RAP - Feasibility Study Report

Global Id: T0608100954
Action Type: RESPONSE
Date: 01/27/2011
Action: Clean Up Fund - 5-Year Review Summary - Regulator Responded

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 06/30/2011
Action: Closure/No Further Action Letter - #20110630

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 09/01/2010
Action: Staff Letter - #20100901

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 08/28/2008
Action: Staff Letter - #20080828B

Global Id: T0608100954
Action Type: ENFORCEMENT
Date: 09/14/2010
Action: Staff Letter - #20100914

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Preliminary site assessment underway
Case Number: 660080
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 1/1/1965
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660080
Facility Status: 9- Case Closed
Global ID: T0608100954
APN Number: 026234020
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

AUTOPRIDE CAR WASH (Continued) **S104493509**

HAZNET:

envid:	S104493509
Year:	2013
GEPAID:	CAL000377306
Contact:	TIM MITCHELL/PRES
Telephone:	6503061070
Mailing Name:	Not reported
Mailing Address:	909 WOODSIDE RD
Mailing City,St,Zip:	REDWOOD CITY, CA 940613610
Gen County:	San Mateo
TSD EPA ID:	CAD980887418
TSD County:	Alameda
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.14595
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not reported

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-1041

BA766 **BROADWAY LOCKSMITH** **LUST** **S104568025**
NW **1009 CALIFORNIA** **HIST CORTESE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.808 mi.
4265 ft. **Site 2 of 4 in cluster BA**

Relative:
Lower

Actual:
14 ft.

LUST:

Region:	STATE
Global Id:	T0608100094
Latitude:	37.5859189182338
Longitude:	-122.360127568245
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/30/2000
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0099
LOC Case Number:	660035
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100094
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board

BROADWAY LOCKSMITH (Continued) **S104568025**

Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100094
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100094
Status: Completed - Case Closed
Status Date: 03/30/2000

Global Id: T0608100094
Status: Open - Case Begin Date
Status Date: 01/01/1985

Regulatory Activities:
Global Id: T0608100094
Action Type: Other
Date: 01/01/1985
Action: Leak Discovery

Global Id: T0608100094
Action Type: Other
Date: 08/13/1985
Action: Leak Reported

Global Id: T0608100094
Action Type: ENFORCEMENT
Date: 03/18/1991
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660035
Facility Status: 9- Case Closed
Global ID: T0608100094
APN Number: 026194090
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0099

BA767 **BROADWAY LOCKSMITH** **LUST** **S104493504**
NW **1009 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.808 mi.
4265 ft. **Site 3 of 4 in cluster BA**

Relative:
Lower

Actual:
14 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660035
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

AZ768 **GOLDEN GATE DRYWALL** **LUST** **S104161688**
NE **399 BEACH** **HIST CORTESE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.812 mi.
4288 ft. **Site 2 of 3 in cluster AZ**

Relative:
Lower

Actual:
11 ft.

LUST:

Region:	STATE
Global Id:	T0608100992
Latitude:	37.588019
Longitude:	-122.337742
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/04/2002
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1081
LOC Case Number:	660069
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100992
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id: T0608100992

GOLDEN GATE DRYWALL (Continued) **S104161688**

Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100992
Status: Completed - Case Closed
Status Date: 10/04/2002

Global Id: T0608100992
Status: Open - Case Begin Date
Status Date: 11/18/1993

Regulatory Activities:
Global Id: T0608100992
Action Type: Other
Date: 11/18/1993
Action: Leak Reported

Global Id: T0608100992
Action Type: ENFORCEMENT
Date: 03/03/1994
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660069
Facility Status: 9- Case Closed
Global ID: T0608100992
APN Number: 026331480
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1081

AZ769 **GOLDEN GATE DRYWALL** **LUST** **S101622918**
NE **399 BEACH RD** **HIST UST** **N/A**
1/2-1 **BURLINGAME, CA 94011** **CA FID UST**
0.812 mi.
4288 ft. **Site 3 of 3 in cluster AZ**

Relative:
Lower

Actual:
11 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660069
How Discovered: OM

GOLDEN GATE DRYWALL (Continued) **S101622918**

Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST UST:
File Number: 0002BEF0
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BEF0.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 41002283
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4153487033
Mail To: Not reported
Mailing Address: 399 BEACH RD
Mailing Address 2: Not reported
Mailing City,St,Zip: BURLINGAME 94011
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

BA770 **MARTINELLI PROPERTY** **LUST** **S104493505**
NW **1015 CALIFORNIA** **HIST CORTESE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.814 mi.
4298 ft. **Site 4 of 4 in cluster BA**

Relative:
Lower

Actual:
14 ft.

LUST:

Region:	STATE
Global Id:	T0608100936
Latitude:	37.585969
Longitude:	-122.36042
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/17/2000
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1023
LOC Case Number:	660079
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100936
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100936
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100936
Status:	Completed - Case Closed
Status Date:	05/17/2000

Global Id:	T0608100936
Status:	Open - Case Begin Date
Status Date:	03/13/1997

Regulatory Activities:

Global Id:	T0608100936
Action Type:	Other
Date:	03/13/1997
Action:	Leak Reported

MARTINELLI PROPERTY (Continued) **S104493505**

Global Id: T0608100936
Action Type: ENFORCEMENT
Date: 03/28/1997
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660079
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660079
Facility Status: 9- Case Closed
Global ID: T0608100936
APN Number: 026194080
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1023

BB771 **JORDAN RESIDENCE** **LUST** **S104567897**
SSE **245 W BELLEVUE** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.826 mi.
4362 ft. **Site 1 of 2 in cluster BB**

Relative:
Higher

Actual:
84 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 118074
Facility Status: 9- Case Closed
Global ID: T0608100187
APN Number: 032022160
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Active
Comp Number: 110164

JORDAN RESIDENCE (Continued) **S104567897**

Number:	2
Board Of Equalization:	Not reported
Referral Date:	11-10-93
Action Date:	11-10-93
Created Date:	07-07-92
Owner Tank Id:	2
SWRCB Tank Id:	41-000-110164-000002
Tank Status:	A
Capacity:	500
Active Date:	07-07-92
Tank Use:	OIL
STG:	W
Content:	WASTE OIL
Number Of Tanks:	2

Status:	Active
Comp Number:	110164
Number:	2
Board Of Equalization:	Not reported
Referral Date:	11-10-93
Action Date:	11-10-93
Created Date:	07-07-92
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110164-000003
Tank Status:	A
Capacity:	500
Active Date:	07-07-92
Tank Use:	OIL
STG:	P
Content:	HEATING OIL
Number Of Tanks:	Not reported

BC772 **PRIVATE RESIDENCE** **LUST** **S110655281**
SW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.835 mi.
4407 ft. **Site 1 of 2 in cluster BC**

Relative:
Higher

Actual:
110 ft.

LUST:

Region:	STATE
Global Id:	T0608159713
Latitude:	37.572045
Longitude:	-122.360104
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/19/1995
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	118001
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

PRIVATE RESIDENCE (Continued) **S110655281**

Contact:
Global Id: T0608159713
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608159713
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608159713
Status: Completed - Case Closed
Status Date: 09/19/1995

Global Id: T0608159713
Status: Open - Case Begin Date
Status Date: 09/12/1995

Regulatory Activities:
Global Id: T0608159713
Action Type: ENFORCEMENT
Date: 09/14/1995
Action: * Historical Enforcement - #1

Global Id: T0608159713
Action Type: REMEDIATION
Date: 09/14/1995
Action: Not reported

Global Id: T0608159713
Action Type: Other
Date: 09/12/1995
Action: Leak Reported

BD773 **SPRINT** **LUST** **S104493472**
North **828 AIRPORT** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.848 mi.
4479 ft. **Site 1 of 2 in cluster BD**

Relative:
Lower

Actual:
6 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660084

SPRINT (Continued) **S104493472**

How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

BD774 **SPRINT** **LUST** **S102267558**
North **828 AIRPORT** **HIST CORTESE** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.848 mi.
4479 ft. **Site 2 of 2 in cluster BD**

Relative:
Lower

Actual:
6 ft.

LUST:
Region: STATE
Global Id: T0608101111
Latitude: 37.591732
Longitude: -122.350106
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 10/04/2000
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1215
LOC Case Number: 660084
File Location: Local Agency Warehouse
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608101111
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608101111
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

SPRINT (Continued) **S102267558**

Status History:
Global Id: T0608101111
Status: Completed - Case Closed
Status Date: 10/04/2000

Global Id: T0608101111
Status: Open - Case Begin Date
Status Date: 10/10/1998

Regulatory Activities:
Global Id: T0608101111
Action Type: Other
Date: 10/10/1998
Action: Leak Reported

Global Id: T0608101111
Action Type: ENFORCEMENT
Date: 10/26/1998
Action: Notice of Responsibility - #1

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660084
Facility Status: 9- Case Closed
Global ID: T0608101111
APN Number: 026342360
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1215

AY775 **PRIVATE RESIDENCE** **LUST** **S110655242**
SW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.856 mi.
4519 ft. **Site 2 of 2 in cluster AY**

Relative:
Higher

Actual:
99 ft.

LUST:
Region: STATE
Global Id: T0608100916
Latitude: 37.569761
Longitude: -122.357905
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 09/17/1996
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1002
LOC Case Number: 878011
File Location: Local Agency

PRIVATE RESIDENCE (Continued) **S110655242**

Potential Media Affect: Soil
Potential Contaminants of Concern: Heating Oil / Fuel Oil
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100916
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100916
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100916
Status: Completed - Case Closed
Status Date: 09/17/1996

Global Id: T0608100916
Status: Open - Case Begin Date
Status Date: 04/23/1996

Regulatory Activities:
Global Id: T0608100916
Action Type: Other
Date: 04/23/1996
Action: Leak Reported

Global Id: T0608100916
Action Type: ENFORCEMENT
Date: 04/23/1996
Action: Notice of Responsibility - #1

BC776 **DURCATO RESIDENCE** **LUST** **S104493746**
SW **1888 FLORIBUNDA** **HIST CORTESE** **N/A**
1/2-1 **HILLSBOROUGH, CA**
0.871 mi.
4600 ft. **Site 2 of 2 in cluster BC**

Relative:
Higher

Actual:
120 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 118001
Facility Status: 9- Case Closed
Global ID: T0608159713

DURCATO RESIDENCE (Continued) **S104493746**

APN Number: 028210050
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0931

BB777 **PRIVATE RESIDENCE** **LUST** **S110655216**
SSE **PRIVATE RESIDENCE** **N/A**
1/2-1 **SAN MATEO, CA 94402**
0.871 mi.
4601 ft. **Site 2 of 2 in cluster BB**

Relative:
Higher

Actual:
78 ft.

LUST:
Region: STATE
Global Id: T0608100187
Latitude: 37.567016
Longitude: -122.343903
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 07/15/2002
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0196
LOC Case Number: 118074
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100187
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100187
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100187

PRIVATE RESIDENCE (Continued) **S110655216**

Status: Completed - Case Closed
Status Date: 07/15/2002

Global Id: T0608100187
Status: Open - Case Begin Date
Status Date: 05/06/1992

Regulatory Activities:
Global Id: T0608100187
Action Type: Other
Date: 09/25/1992
Action: Leak Discovery

Global Id: T0608100187
Action Type: Other
Date: 05/06/1992
Action: Leak Reported

Global Id: T0608100187
Action Type: ENFORCEMENT
Date: 09/17/1992
Action: Notice of Responsibility - #1

---

778 NNW 1/2-1 0.877 mi. 4628 ft. **BURLINGAME DISPOSAL SITE** **SWF/LF** **S102362433**
1001 S AIRPORT ROAD **N/A**
BURLINGAME, CA

Relative: Lower

Actual: 7 ft.

SWF/LF (SWIS):
Region: STATE
Facility ID: 41-CR-0014
Lat/Long: 37.591100 / -122.35880
Owner Name: City Of Burlingame
Owner Telephone: 6505587246
Owner Address: Not reported
Owner Address2: 501 Primrose Road
Owner City,St,Zip: Burlingame, CA 94010
Operational Status: Closed
Operator: Not reported
Operator Phone: Not reported
Operator Address: Not reported
Operator Address2: Not reported
Operator City,St,Zip: Not reported
Permit Date: Not reported
Permit Status: Not reported
Permitted Acreage: $0.00
Activity: Solid Waste Disposal Site
Regulation Status: Permitted
Landuse Name: Not reported
GIS Source: Map
Category: Disposal
Unit Number: 01
Inspection Frequency: None
Accepted Waste: Not reported
Closure Date: Not reported

BURLINGAME DISPOSAL SITE (Continued) **S102362433**

Closure Type: Not reported
Disposal Acreage: $0.00
SWIS Num: 41-CR-0014
Waste Discharge Requirement Num: Not reported
Program Type: Not reported
Permitted Throughput with Units: Not reported
Actual Throughput with Units: Not reported
Permitted Capacity with Units: Not reported
Remaining Capacity: Not reported
Remaining Capacity with Units: Not reported
Lat/Long: 37.591100 / -122.35880

BE779 **GREENE, JAMES & MARRITJE** **LUST** **S103892539**
SSW **725 HILLSBOROUGH BLVD** **SWEEPS UST** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010** **HIST CORTESE**
0.884 mi.
4669 ft. **Site 1 of 6 in cluster BE**

Relative:
Higher

Actual:
111 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 878007
Facility Status: 9- Case Closed
Global ID: T0608100706
APN Number: 031032060
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 870024
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-870024-000001
Tank Status: Not reported
Capacity: 2000
Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: Not reported
Number Of Tanks: 1

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0746

BF780 **CLEVELAND PROPERTY** **LUST** **S104493753**
SW **2215 RALSTON** **HIST CORTESE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.896 mi.
4731 ft. **Site 1 of 2 in cluster BF**

Relative:
Higher

Actual:
101 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	878008
Facility Status:	9- Case Closed
Global ID:	T0608194884
APN Number:	028251020
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0808

BE781 **PRIVATE RESIDENCE** **LUST** **S110655228**
SSW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.901 mi.
4758 ft. **Site 2 of 6 in cluster BE**

Relative:
Higher

Actual:
114 ft.

LUST:

Region:	STATE
Global Id:	T0608100706
Latitude:	37.56772
Longitude:	-122.355569
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	02/27/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0746
LOC Case Number:	878007
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100706
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100706
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY

PRIVATE RESIDENCE (Continued) **S110655228**

Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608100706
Status: Completed - Case Closed
Status Date: 02/27/2001

Global Id: T0608100706
Status: Open - Case Begin Date
Status Date: 06/10/1993

Regulatory Activities:
Global Id: T0608100706
Action Type: Other
Date: 06/10/1993
Action: Leak Reported

Global Id: T0608100706
Action Type: ENFORCEMENT
Date: 06/10/1993
Action: Notice of Responsibility - #1

---

782 South 1/2-1 0.904 mi. 4773 ft. **UST SITE - RESIDENTIAL** **LUST S118496976**
505 OCCIDENTAL **San Mateo Co. BI N/A**
SAN MATEO, CA 94402

Relative: Higher

Actual: 107 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 118188
Facility Status: 3B- Preliminary Assessment Underway
Global ID: T10000008170
APN Number: 031051100
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0059143
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0081867
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

BE783 **YUAN PROPERTY** **LUST** **S103892553**
SSW **839 SEABURY** **HIST CORTESE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.904 mi.
4774 ft. **Site 3 of 6 in cluster BE**

Relative:
Higher

Actual:
127 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	870016
Facility Status:	9- Case Closed
Global ID:	T0608100971
APN Number:	031072090
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-1059

BE784 **PRIVATE RESIDENCE** **LUST** **S110655262**
SSW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.905 mi.
4776 ft. **Site 4 of 6 in cluster BE**

Relative:
Higher

Actual:
123 ft.

LUST:

Region:	STATE
Global Id:	T0608101061
Latitude:	37.56723
Longitude:	-122.354446
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/05/1996
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1000
LOC Case Number:	878012
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608101061
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608101061
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY

PRIVATE RESIDENCE (Continued) **S110655262**

Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608101061
Status: Completed - Case Closed
Status Date: 06/05/1996

Global Id: T0608101061
Status: Open - Case Begin Date
Status Date: 03/13/1996

Regulatory Activities:
Global Id: T0608101061
Action Type: Other
Date: 03/13/1996
Action: Leak Discovery

Global Id: T0608101061
Action Type: Other
Date: 05/03/1996
Action: Leak Reported

Global Id: T0608101061
Action Type: ENFORCEMENT
Date: 05/03/1996
Action: Notice of Responsibility - #1

BE785 **PRIVATE RESIDENCE** **LUST** **S110655252**
SSW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.913 mi.
4818 ft. **Site 5 of 6 in cluster BE**

Relative:
Higher

Actual:
132 ft.

LUST:
Region: STATE
Global Id: T0608100971
Latitude: 37.566889
Longitude: -122.353779
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 12/17/1997
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-1059
LOC Case Number: 870016
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

PRIVATE RESIDENCE (Continued) **S110655252**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100971
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100971
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100971
Status:	Completed - Case Closed
Status Date:	12/17/1997

Global Id:	T0608100971
Status:	Open - Case Begin Date
Status Date:	10/29/1997

Regulatory Activities:

Global Id:	T0608100971
Action Type:	ENFORCEMENT
Date:	12/11/1997
Action:	Notice of Responsibility - #1

Global Id:	T0608100971
Action Type:	Other
Date:	10/29/1997
Action:	Leak Reported

BF786 **PRIVATE RESIDENCE** **LUST** **S110655296**
SW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.919 mi.
4854 ft. **Site 2 of 2 in cluster BF**

Relative:
Higher

Actual:
105 ft.

LUST:

Region:	STATE
Global Id:	T0608194884
Latitude:	37.569231
Longitude:	-122.358905
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	03/14/1994

PRIVATE RESIDENCE (Continued) **S110655296**

Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0808
LOC Case Number: 878008
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608194884
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608194884
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608194884
Status: Completed - Case Closed
Status Date: 03/14/1994

Global Id: T0608194884
Status: Open - Case Begin Date
Status Date: 03/14/1994

Regulatory Activities:
Global Id: T0608194884
Action Type: ENFORCEMENT
Date: 03/14/1994
Action: Notice of Responsibility - #1

BG787 **UNITED TRANSMISSION INC** **LUST** **S101438206**
WNW **1131 CALIFORNIA** **SWEEPS UST** **N/A**
1/2-1 **BURLINGAME, CA 94010** **HIST CORTESE**
0.929 mi.
4903 ft. **Site 1 of 6 in cluster BG**

Relative:
Lower

Actual:
15 ft.

LUST:
Region: STATE
Global Id: T0608100229
Latitude: 37.586996

UNITED TRANSMISSION INC (Continued) **S101438206**

Longitude:	-122.361722
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/20/1996
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0240
LOC Case Number:	660053
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Stoddard solvent / Mineral Spriits / Distillates
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100229
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100229
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100229
Status:	Completed - Case Closed
Status Date:	11/20/1996

Global Id:	T0608100229
Status:	Open - Case Begin Date
Status Date:	09/28/1990

Regulatory Activities:

Global Id:	T0608100229
Action Type:	ENFORCEMENT
Date:	05/24/1991
Action:	Notice of Responsibility - #1

Global Id:	T0608100229
Action Type:	Other
Date:	09/28/1990
Action:	Leak Discovery

Global Id:	T0608100229
Action Type:	Other

UNITED TRANSMISSION INC (Continued) **S101438206**

Date: 05/28/1991
Action: Leak Reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660053
Facility Status: 9- Case Closed
Global ID: T0608100229
APN Number: 029191070
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 660037
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: 0

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0240

BG788 **UNITED TRANSMISSION** **RCRA-SQG** **1000597271**
WNW **1131 CALIFORNIA DR** **LUST** **CAD983612748**
1/2-1 **BURLINGAME, CA 94010** **CA FID UST**
0.929 mi. **FINDS**
4903 ft. **Site 2 of 6 in cluster BG** **ECHO**

Relative:
Lower

Actual:
15 ft.

RCRA-SQG:
Date form received by agency: 11/01/1991
Facility name: UNITED TRANSMISSION
Facility address: 1131 CALIFORNIA DR
BURLINGAME, CA 94010
EPA ID: CAD983612748
Contact: GILBERTO RODRIGUEZ
Contact address: 1131 CALIFORNIA DR
BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 342-4047
Contact email: Not reported
EPA Region: 09

UNITED TRANSMISSION (Continued) **1000597271**

Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: JOHN GARBO
Owner/operator address: 798 JULY WAY
REDDING, CA 94010
Owner/operator country: Not reported
Owner/operator telephone: (916) 246-1008
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660053
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

CA FID UST:
Facility ID: 41000250

UNITED TRANSMISSION (Continued) **1000597271**

Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4150000000
Mail To:	Not reported
Mailing Address:	1131 CALIFORNIA DR
Mailing Address 2:	Not reported
Mailing City,St,Zip:	BURLINGAME 94010
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

FINDS:

Registry ID: 110002864589

Environmental Interest/Information System

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ECHO:

Envid:	1000597271
Registry ID:	110002864589
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002864589

BH789 **ARCO FACILITY #725** **LUST** **S101593661**
SE **402 N EL CAMINO REAL** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94401** **CA FID UST**
0.934 mi. **HAZNET**
4933 ft. **Site 1 of 4 in cluster BH**

Relative:
Lower

Actual:
25 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110011
Facility Status:	7- Remedial Action Underway
Global ID:	T0608100037
APN Number:	032171280
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SWEEPS UST:

ARCO FACILITY #725 (Continued) **S101593661**

Status: Not reported
Comp Number: 110068
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000006
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: 1

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000001
Tank Status: A
Capacity: 10000
Active Date: 04-18-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 6

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94
Created Date: 10-13-88
Owner Tank Id: 2
SWRCB Tank Id: 41-000-110068-000002
Tank Status: A
Capacity: 10000
Active Date: 04-18-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94

ARCO FACILITY #725 (Continued) **S101593661**

Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000003
Tank Status: A
Capacity: 10000
Active Date: 04-18-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000004
Tank Status: A
Capacity: 10000
Active Date: 04-18-94
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000005
Tank Status: A
Capacity: 550
Active Date: 04-18-94
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Active
Comp Number: 110068
Number: 1
Board Of Equalization: Not reported
Referral Date: 05-11-94
Action Date: 05-11-94
Created Date: 10-13-88
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110068-000007
Tank Status: A
Capacity: 550
Active Date: 07-06-92

ARCO FACILITY #725 (Continued) **S101593661**

Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 41000068
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4153435544
Mail To: Not reported
Mailing Address: 17315 STUDEBAKER RD
Mailing Address 2: Not reported
Mailing City,St,Zip: SAN MATEO 94401
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

HAZNET:
envid: S101593661
Year: 2014
GEPAID: CAL000382941
Contact: AL NAJDAWI
Telephone: 4158663055
Mailing Name: Not reported
Mailing Address: 402 N EL CAMINO REAL
Mailing City,St,Zip: SAN MATEO, CA 944013710
Gen County: San Mateo
TSD EPA ID: NVT330010000
TSD County: 99
Waste Category: Other organic solids
Disposal Method: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.0375
Cat Decode: Other organic solids
Method Decode: Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County: San Mateo

envid: S101593661
Year: 2013
GEPAID: CAL000382941
Contact: AL NAJDAWI
Telephone: 4158663055
Mailing Name: Not reported
Mailing Address: 402 N EL CAMINO REAL
Mailing City,St,Zip: SAN MATEO, CA 944013710
Gen County: San Mateo
TSD EPA ID: NVT330010000
TSD County: 99

ARCO FACILITY #725 (Continued) **S101593661**

Waste Category:	Not reported
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.025
Cat Decode:	Not reported
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	Not reported

BH790 **AAA SPEEDY SMOG** **LUST** **S101303230**
SE **402 EL CAMINO** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401** **HIST CORTESE**
0.934 mi.
4933 ft. **Site 2 of 4 in cluster BH**

Relative:
Lower

Actual:
25 ft.

LUST:

Region:	STATE
Global Id:	T0608100037
Latitude:	37.57012698906
Longitude:	-122.335301041603
Case Type:	LUST Cleanup Site
Status:	Open - Site Assessment
Status Date:	06/30/2011
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	DGM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0038
LOC Case Number:	110011
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from Stantec's February 5, 2010 Remedial Evaluation Report, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is an active ARCO auto repair and gasoline retail outlet located at the intersection of North El Camino Real and Poplar Avenue in San Mateo, California. The facilities at the site include a station building, four 10,000-gallon gasoline underground storage tanks (USTs), one 550-gallon waste-oil UST, associated product piping, and two fuel dispenser islands. There are currently eight groundwater monitoring wells (MW-1 and MW-5 through MW-11) at and in the vicinity of the site. Also present at the site is a groundwater extraction and treatment (GWET) system, which includes four groundwater extraction wells (EW-1 through EW-4), associated lateral piping, and a granulated activated carbon (GAC) groundwater treatment system. A waste-oil UST was removed from the site in 1986. The background section of a Converse Environmental West (CEW) Groundwater Monitoring Well Installation Plan dated October 4, 1990 indicates the former waste-oil UST was removed after it failed a tank integrity test. In February 1989, the San Mateo County Department of Health Services reportedly confirmed that no further action would be required related to the 1986 former waste-oil UST. An Unauthorized Release Report dated March 31, 1988 indicates San Mateo County was notified of an unauthorized release of fuel at the site. The potentially leaking system was identified as the super unleaded vapor or vent lines since the product lines and USTs were tested and found to be tight. In July 1989, CEW advanced four soil borings (SB-1 through SB-4). CEW concluded that soil around the perimeter of the

AAA SPEEDY SMOG (Continued) **S101303230**

USTs had been contaminated by gasoline hydrocarbons. Based on the soil analytical data, hydrocarbon impacts appeared to be located primarily in the southern portion of the UST area. In November 1990, CEW installed groundwater monitoring wells MW-1 through MW-4. The monitoring wells were each installed at approximate depths of 30 feet bgs. Results of initial groundwater monitoring and sampling indicated depth to water ranged from 15.5 to 18 feet bgs. Separate phase hydrocarbons (SPH) were measured in well MW-3 at a thickness of 0.53 feet and product sheen was observed in well MW-2. Passive product (SPH) skimmers were installed in wells MW-2 and MW-3 in February 1992. Product sheen and SPH were observed in wells MW-2 and MW-3 prior to their destruction in June 1992. The maximum thickness of SPH was measured in well MW-3 at 5.28 feet in March 1991. From December 1990 to May 1991, Roux Associates were present at the site to observe the excavation and removal of four gasoline USTs, fuel dispensers, and associated product piping. After removal, the USTs were inspected and a small hole that measured approximately onesixteenth of an inch was found in the center at the base of Tank T-2. Tank T-2 is northern most UST in the line of three tanks located south of SB-4. The three other USTs appeared to be in good condition. Due to indications of petroleum hydrocarbon impact (petroleum staining and strong hydrocarbon odor), the former UST area was over-excavated to a depth of approximately 21 feet bgs in January 1991. Groundwater was observed in the excavation at approximately 18 feet bgs. The UST excavation was expanded laterally toward North El Camino Real and East Poplar Avenue to the maximum extent possible within the safe operating limits of the equipment or to which point further excavation would have endangered the surrounding streets or station building. During UST soil excavation activities, the fuel dispensers and product lines were removed and soil underlying the fuel dispensers was excavated to a depth of approximately 6 feet bgs to remove impacted soil. Excavation was then discontinued due to the lack of space onsite to stockpile the excavated soil. On January 8, 1991, approximately 2,000 gallons of groundwater and gasoline were removed from the UST excavation using a vacuum truck. The groundwater and gasoline mixture was transported offsite for disposal. The deepest portion of the UST excavation was backfilled with clean, imported pea gravel to bring the excavation up to approximately 17 feet bgs. As part of the station renovation completed in 1991, two hydraulic lifts were removed from the former service station bays. The hoists are located within the footprint of the former station building. Although the total volume of soil excavated was not reported, up to 950 cubic yards of soil appears to have been removed during the 1991 facility renovation. The final disposition of the excavated soil was not documented. Additional assessment conducted by Roux included advancement of three hand auger soil borings in the area of the former fuel dispensers (HB-1 through HB-3). The soil borings were advanced while standing in the six foot deep soil excavation and extended approximately 9.5 to 12 feet below the excavation to total depths ranging from 15.5 to 18 feet bgs. A report by CEW indicates that a 280 gallon waste oil UST had been removed from the site. In April 1992, CEW installed offsite groundwater monitoring wells MW-5, MW-6, MW-7, and MW-8. The wells were constructed with 15 feet of well screen installed at total depths ranging from 28.7 to 30 feet bgs. During drilling, groundwater was first encountered at depths of approximately 16 to 19 feet bgs. Static water levels in the wells approximately one week after

AAA SPEEDY SMOG (Continued) **S101303230**

installation were measured at approximately 10 feet bgs indicating semi-confined groundwater conditions. In June 1992, CEW conducted hydraulic stress testing at the site to determine various hydrologic parameters of the shallow groundwater aquifer using well MW-3 as the extraction well. Groundwater was pumped from well MW-3 at a constant rate of 0.4 gallons per minute (gpm) for 25.3 hours. The thickness of SPH in well MW-3 increased from 0.8 feet prior to the test to 1.72 feet at the conclusion. Results of hydraulic stress testing indicated the shallow groundwater aquifer had relatively low permeability with hydraulic conductivity ranging from 0.34 to 9.36 feet per day (ft/day) and a storativity of 0.071. CEW concluded the wide variation in conductivity values indicated a high degree of non-homogeneous sediments beneath the site. Hydraulic conductivity appeared to higher to the northeast (from MW-3 to MW-6) and lower to the southeast (from MW-3 to MW-8). Hydrocarbon impacted groundwater extracted from well MW-3 during the pump test was transported for offsite disposal.
Between February and July 1992, CEW conducted soil excavation and sampling at the site to remove hydrocarbon impacted soil and establish the extent of hydrocarbon contamination in the areas of the former waste oil UST and fuel dispensers. At the time of the investigation, all of the former onsite structures which included the station building, four gasoline USTs ranging from 4,000 to 6,000 gallon capacity, a 280 gallon waste oil UST, and two fuel dispenser islands had been removed. Initial activities conducted at the site included excavation of two test pits near the former waste oil UST to investigate the extent of waste oil in soil. Test pit CON-1 was placed near the former waste oil UST. A second test pit (CON-2) was excavated further west of CON-1 to evaluate the lateral extent of waste oil in soil. In March and April 1992, soil excavation was conducted in the areas of the former fuel dispensers, station building, waste oil UST and new gasoline USTs. Soil excavation was performed to remove all accessible hydrocarbon impacted soil from the site. A total of 2,625 cubic yards of soil was removed during the excavation project and transported for offsite disposal. The excavation was partially filled with clean, imported fill material.
In June 1992, the soil excavation was enlarged to remove additional hydrocarbon impacted soil along the western and northeastern margins of the March and April 1992 excavation. Monitoring wells MW-2 and MW-3 were destroyed during the excavation activities to remove hydrocarbon impacted soil in those areas. Wells were removed by direct excavation of the well casing and sand pack. Well MW-4 was damaged during soil excavation activities and destroyed in July 1992. Until their destruction in June 1992, a total of 0.84 and 9.26 gallons of SPH were removed from well MW-2 and MW-3, respectively, by hand bailing and the use of passive skimmers. Additional soil was excavated in July 1992 to allow installation of the new (currently existing) gasoline USTs and in the vicinity of the former waste oil UST. Additional soil excavation near the former waste oil UST was conducted to remove hydrocarbon impacted soil at the northern extent of the June 1992 excavation where soil samples SW-4A and SW-4B were collected. Additional soil was not removed in the area of soil sample SS-4 due to the presence of a retaining wall which was installed along the northeastern property line as part of the new service station construction. In June 1993, CEW installed groundwater extraction wells EW-1 though EW-4 east and southeast of the former gasoline UST pit. Extraction wells EW-1 through EW-4 were installed in fill material backfilled during 1992 soil excavation activities.

AAA SPEEDY SMOG (Continued) **S101303230**

Fill material was encountered at depths of 10 to 21 feet bgs during installation of the wells. The wells were constructed with 6-inch diameter well screen from 7 to 32 feet bgs. Offsite well MW-9 was installed with well screen from 10 to 24.5 feet bgs. A groundwater extraction and treatment (GWET) system was installed in 1993 and operated at the site from 1993 through 2003. The system included four extraction wells (EW-1 through EW-4) that recovered groundwater at an approximate rate of 1.3 gallons per minute. The extracted groundwater was treated with a liquid phase carbon bed, and then discharged to the sanitary sewer. Hydrocarbon mass removal rates had reached an asymptotic state, with mass removal rates since December 2000 ranging from 0.0013 to 0.0546 pounds per day. With the approval of GPP, the GWET system was shut down on September 3, 2003. By the time the system was shutdown, a total of approximately 5,059,351 gallons of groundwater had been extracted, treated, and discharged to the sanitary sewer and the GWET system had removed approximately 255 pounds of TPHg, 65 pounds of BTEX, and 1.69 pounds of MtBE. In January 1995, SECOR installed offsite wells MW-10 and MW-11. The wells were installed with screened intervals from 7 to 22 feet bgs. In November 1997, SECOR submitted a Risk-Based Corrective Action Evaluation Report for Off-site Residential Receptors (RBCA). The RBCA evaluation was performed using residual concentrations of petroleum hydrocarbons in soil and groundwater to evaluate potential impacts to residential properties east of the site. The exposure pathway evaluated was inhalation of chemicals volatilizing from groundwater to indoor air. SECOR concluded that concentrations of BTEX and methyl tert-butyl ether (MTBE) were unlikely to pose a significant human health hazard for the offsite residential receptors and the exposure pathway evaluated. In 1998, SECOR conducted a door to door well survey within a 1,120 foot radius of the site. Two wells were identified at distances of 675 and 850 feet upgradient (west) of the site. Both wells were not in use, and one well was covered. SECOR submitted a Dual Phase Extraction Feasibility Study Work Plan (Work Plan) dated November 30, 2001. As part of the feasibility study, SECOR conducted an evaluation of the GWET system which had been operating at the site since 1993. The evaluation was conducted to assess whether GWET system operational enhancements and/or modifications could be implemented to augment system performance and increaseSPH removal from the subsurface. While evaluating current site conditions, SECOR noted that although GWET remedial efforts may have reduced hydrocarbon impact within the (UST) source area, the GWET system radius of influence did not appear to extend sufficiently offsite to address the area between wells MW-6, MW-7, and MW-9. In review of historical files for the site, it does not appear dual phase extraction testing has been performed at the site. The background section of the SECOR 2001 Work Plan discusses a 1991 soil vapor extraction (SVE) pilot test conducted at the site by Geraghty & Miller. According to the SECOR 2001 Work Plan, the pilot test resulted in an influent vapor flow rate of 13.5 cubic feet per minute (cfm) at 84 inches of water vacuum or 6.2 inches of mercury (Hg). SECOR concluded that based on a review of the pilot test data, groundwater was drawn above the top of the well screen when the vacuum was increased from 89 to 100 inches of water or 7.4 Hg. The extractions well(s) used during the SVE test were not provided. On May 19, 2009, the California State Water Quality Control Board adopted Resolution No. 2009-0042 (Resolution 42), relating to the cleanup of Leaking Underground Storage Tanks in the State. The

AAA SPEEDY SMOG (Continued) **S101303230**

Resolution contains 14 measures aimed at improving the overall cleanup process, including measure #3, which directs agencies to reduce quarterly groundwater monitoring requirements to semi-annual or less unless site-specific needs warrant otherwise. Stantec submitted a Proposed Groundwater Monitoring and Sampling Schedule to the GPP, dated July 29, 2009. The proposal recommended monitoring and sampling on a semi-annual basis during the months of March and September. Based on discussion with GPP, the recommended monitoring and sampling schedule was implemented during the fourth quarter of 2009. In a letter dated October 28, 2009, the GPP discussed a possible correlation between increased dissolved hydrocarbon concentrations and higher groundwater elevations that suggest a source of residual hydrocarbon contamination at the site following historical remedial activities. Therefore, the GPP directed submittal of a report assessing the effectiveness of historical remedial activities to help determine whether the site poses a threat to human health and the environment. This Report fulfills requirements of the GPP letter. In December 2009, Stantec personnel performed soil sampling during excavation and replacement of fuel dispensers, underground dispenser containment (UDC) equipment, and product lines. Since the site is the subject of an open environmental case with San Mateo County since 1988 (SMCo Case No. 110011), Stantec concluded the unknown hydrocarbons(s) quantified in sample D-7 appeared to be weathered or degraded gasoline constituents within the GRO range of C6 to C12 due to the time that had elapsed since the fuel was originally released and the degradation that had occurred.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100037
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100037
Contact Type:	Local Agency Caseworker
Contact Name:	DENO MILANO
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	dmilano@smcgov.org
Phone Number:	6503726292

Status History:

Global Id:	T0608100037
Status:	Open - Case Begin Date
Status Date:	02/04/1988

Global Id:	T0608100037
Status:	Open - Remediation
Status Date:	09/02/1993

AAA SPEEDY SMOG (Continued) **S101303230**

Global Id: T0608100037
Status: Open - Site Assessment
Status Date: 06/30/2011

Regulatory Activities:
Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 03/19/2003
Action: Staff Letter - #20030319

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 08/22/2003
Action: Staff Letter - #20030822

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 03/19/2014
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 10/28/2009
Action: Staff Letter - #20091028

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 04/22/2005
Action: Staff Letter - #20050422

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 08/04/2014
Action: Staff Letter - #20140804

Global Id: T0608100037
Action Type: RESPONSE

AAA SPEEDY SMOG (Continued) **S101303230**

Date: 11/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/07/2010
Action: Site Assessment Report

Global Id: T0608100037
Action Type: RESPONSE
Date: 06/05/2014
Action: Request for Closure - Regulator Responded

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/31/2010
Action: Correspondence

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 05/22/2013
Action: Staff Letter - #20130522

Global Id: T0608100037
Action Type: RESPONSE
Date: 07/14/2011
Action: Other Report / Document

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 10/01/2014
Action: Staff Letter - #20141001

AAA SPEEDY SMOG (Continued) **S101303230**

Global Id: T0608100037
Action Type: Other
Date: 04/01/1988
Action: Leak Discovery

Global Id: T0608100037
Action Type: Other
Date: 02/04/1988
Action: Leak Reported

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 08/19/2014
Action: Technical Correspondence / Assistance / Other - #20140819

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 07/20/2005
Action: Staff Letter - #20050720

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 11/20/2007
Action: Staff Letter - #20071120

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 02/05/2009
Action: Email Correspondence - #20090205

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/31/2014
Action: Site Assessment Report

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 11/19/2010
Action: Staff Letter - #20101119

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 08/05/2014
Action: Technical Correspondence / Assistance / Other - #20140805

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 10/22/2014
Action: Notice of Violation - #20141022

Global Id: T0608100037
Action Type: ENFORCEMENT

AAA SPEEDY SMOG (Continued) **S101303230**

Date: 02/05/2015
Action: Staff Letter - #20150205

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 08/04/2014
Action: Technical Correspondence / Assistance / Other - #20140804

Global Id: T0608100037
Action Type: RESPONSE
Date: 04/16/2013
Action: Site Assessment Report

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2014
Action: Monitoring Report - Annually

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2014
Action: Electronic Reporting Submittal Due

Global Id: T0608100037
Action Type: RESPONSE
Date: 12/06/2002
Action: Other Report / Document

Global Id: T0608100037
Action Type: RESPONSE
Date: 01/20/2016
Action: Soil and Water Investigation Workplan

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: REMEDIATION
Date: 03/20/1992
Action: Excavation

Global Id: T0608100037
Action Type: REMEDIATION
Date: 01/01/1990
Action: Free Product Removal

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 06/09/2011
Action: Staff Letter - #20110609

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 07/06/2010
Action: Staff Letter - #20100706

AAA SPEEDY SMOG (Continued) **S101303230**

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 01/27/2016
Action: Staff Letter - #20160127

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608100037
Action Type: REMEDIATION
Date: 12/28/1990
Action: Excavation

Global Id: T0608100037
Action Type: REMEDIATION
Date: 09/02/1993
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE

AAA SPEEDY SMOG (Continued) **S101303230**

Date: 11/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 10/17/2003
Action: Other Workplan

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 12/19/2013
Action: Technical Correspondence / Assistance / Other - #20131219

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 12/19/2013
Action: Staff Letter - #20131219

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 01/20/2016
Action: Email Correspondence - #20160120

AAA SPEEDY SMOG (Continued) **S101303230**

Global Id: T0608100037
Action Type: RESPONSE
Date: 06/21/2005
Action: Other Report / Document

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 07/30/2009
Action: Staff Letter - #20090730

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2004
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/28/2011
Action: Other Report / Document

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 09/28/2015
Action: Staff Letter - #20150928

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 02/16/1989
Action: Notice of Responsibility - #19890216

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 09/10/2002
Action: Staff Letter - #20020910

Global Id: T0608100037
Action Type: RESPONSE
Date: 09/14/2005
Action: Other Report / Document

Global Id: T0608100037
Action Type: REMEDIATION
Date: 01/08/1991
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100037
Action Type: REMEDIATION

AAA SPEEDY SMOG (Continued) **S101303230**

Date: 06/08/1992
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100037
Action Type: REMEDIATION
Date: 12/03/2009
Action: Excavation

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 09/30/2014
Action: Technical Correspondence / Assistance / Other - #20140930

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 02/20/2014
Action: Staff Letter - #20140220

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2015
Action: Electronic Reporting Submittal Due

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 08/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 11/15/2008
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: RESPONSE
Date: 02/15/2009
Action: Monitoring Report - Quarterly

Global Id: T0608100037
Action Type: ENFORCEMENT
Date: 12/21/2011
Action: Staff Letter - #20111221

AAA SPEEDY SMOG (Continued) **S101303230**

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Remedial action (cleanup) Underway
Case Number: 110011
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: 9/2/1993
Date Post Remedial Action Monitoring Began: Not reported

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0015091
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0010806
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0015091
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0003476
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0045730
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0060661
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0045730
Prog Element Code: STORES MV FUELS OR WASTE ONLY
Record Id: PR0060660
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0016937
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0024084
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0016937
Prog Element Code: STORES MV FUELS OR WASTE ONLY

AAA SPEEDY SMOG (Continued) **S101303230**

Record Id: PR0003321
Description: STORES MV FUELS OR WASTE ONLY
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0016937
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0022135
Description: UNDERGROUND TANK - GENERAL
Facility Status: ACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0038

BI791 **PRIVATE RESIDENCE** **LUST** **S110655286**
SSW **PRIVATE RESIDENCE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.938 mi.
4953 ft. **Site 1 of 2 in cluster BI**

Relative:
Higher

Actual:
111 ft.

LUST:
Region: STATE
Global Id: T0608176244
Latitude: 37.566095
Longitude: -122.352189
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/12/1999
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-4049
LOC Case Number: 878019
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608176244
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608176244
Contact Type: Local Agency Caseworker
Contact Name: MARC MULLANEY
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS

PRIVATE RESIDENCE (Continued) **S110655286**

City: SAN MATEO
Email: mmullaney@smcgov.org
Phone Number: 6503726289

Status History:
Global Id: T0608176244
Status: Completed - Case Closed
Status Date: 03/12/1999

Global Id: T0608176244
Status: Open - Case Begin Date
Status Date: 01/11/1999

Regulatory Activities:
Global Id: T0608176244
Action Type: ENFORCEMENT
Date: 01/11/1999
Action: Notice of Responsibility - #1

Global Id: T0608176244
Action Type: Other
Date: 02/10/1999
Action: Leak Reported

792
ENE
1/2-1
0.940 mi.
4963 ft.

BOWER RESIDENCE **LUST** **S106982280**
8 PENINSULA AVE **N/A**
BURLINGAME, CA

Relative:
Lower

Actual:
11 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 668098
Facility Status: 9- Case Closed
Global ID: T0608125944
APN Number: 029305130
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

BJ793
NW
1/2-1
0.940 mi.
4964 ft.

UNOCAL #3885 **LUST** **S106117980**
1147 ROLLINS **N/A**
BURLINGAME, CA 94010

Site 1 of 2 in cluster BJ

Relative:
Lower

Actual:
9 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Post remedial action monitoring
Case Number: 660055
How Discovered: Tank Closure
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported

UNOCAL #3885 (Continued) **S106117980**

Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: 6/26/1997

BJ794 **UNOCAL** **LUST** **S103171189**
NW **1147 ROLLINS** **SWEEPS UST** **N/A**
1/2-1 **BURLINGAME, CA 94010** **HIST CORTESE**
0.940 mi.
4964 ft. **Site 2 of 2 in cluster BJ**

Relative:
Lower

Actual:
9 ft.

LUST:
Region: STATE
Global Id: T0608100566
Latitude: 37.58871079
Longitude: -122.360931656
Case Type: LUST Cleanup Site
Status: Open - Verification Monitoring
Status Date: 02/21/2012
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: DGM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0594
LOC Case Number: 660055
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Can be extracted from most recent report in Geotracker or at San Mateo County offices if submitted prior to 2005, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report.

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100566
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100566
Contact Type: Local Agency Caseworker
Contact Name: DENO MILANO
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: dmilano@smcgov.org
Phone Number: 6503726292

Status History:
Global Id: T0608100566

UNOCAL (Continued) **S103171189**

Status: Open - Case Begin Date
Status Date: 03/21/1991

Global Id: T0608100566
Status: Open - Site Assessment
Status Date: 06/26/1997

Global Id: T0608100566
Status: Open - Verification Monitoring
Status Date: 02/21/2012

Regulatory Activities:
Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2012
Action: Monitoring Report - Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2015
Action: Monitoring Report - Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 11/01/2005
Action: Staff Letter - #20051101

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 10/10/2007
Action: Staff Letter - #20071010

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 02/21/2012
Action: Staff Letter - #20120221

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 10/08/2014
Action: Technical Correspondence / Assistance / Other - #20141008

UNOCAL (Continued) **S103171189**

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 10/29/2008
Action: Staff Letter - #20081029

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2015
Action: Request for Closure - Regulator Responded

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 04/13/2005
Action: Staff Letter - #20050413

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 04/04/2006
Action: Technical Correspondence / Assistance / Other - #20060404

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 09/08/2005
Action: Staff Letter - #20050908

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 07/13/2006
Action: Staff Letter - #20061113

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 04/05/2006
Action: Technical Correspondence / Assistance / Other - #20060405

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 12/07/2009
Action: Staff Letter - #20091207

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 09/16/2004
Action: Staff Letter - #20040916A

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 09/16/2004
Action: Staff Letter - #20040916B

Global Id: T0608100566
Action Type: ENFORCEMENT

UNOCAL (Continued) **S103171189**

Date: 11/29/2004
Action: Technical Correspondence / Assistance / Other - #20041129

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2006
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 04/10/2006
Action: Soil and Water Investigation Report

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 07/24/2012
Action: Staff Letter - #20120724

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 06/30/2011
Action: Correspondence

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 07/09/2015
Action: Staff Letter - #20150709

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 11/19/2014
Action: Staff Letter - #20141119

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2014
Action: Monitoring Report - Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2013
Action: Monitoring Report - Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/10/2010
Action: Soil and Water Investigation Report

UNOCAL (Continued) **S103171189**

Global Id: T0608100566
Action Type: Other
Date: 03/27/1991
Action: Leak Discovery

Global Id: T0608100566
Action Type: Other
Date: 03/21/1991
Action: Leak Reported

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: REMEDIATION
Date: 11/21/1994
Action: Excavation

Global Id: T0608100566
Action Type: REMEDIATION
Date: 11/21/1994
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608100566
Action Type: REMEDIATION
Date: 03/26/1991
Action: Excavation

Global Id: T0608100566
Action Type: RESPONSE
Date: 08/08/2012
Action: Other Report / Document

Global Id: T0608100566
Action Type: RESPONSE
Date: 06/30/2014
Action: Soil and Water Investigation Report

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 12/10/2001
Action: Staff Letter - #20011210

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 02/09/2011
Action: Staff Letter - #20110209

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 07/23/2013
Action: Staff Letter - #20130723

Global Id: T0608100566
Action Type: RESPONSE

UNOCAL (Continued) **S103171189**

Date: 02/22/2012
Action: Electronic Reporting Submittal Due

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 06/02/2015
Action: Email Correspondence - #20150602

Global Id: T0608100566
Action Type: RESPONSE
Date: 08/25/2015
Action: Clean Up Fund - 5-Year Review Summary

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 11/22/2010
Action: Staff Letter - #20101122

Global Id: T0608100566
Action Type: RESPONSE
Date: 08/09/2015
Action: Electronic Reporting Submittal Due

Global Id: T0608100566
Action Type: REMEDIATION
Date: 07/09/2002
Action: Excavation

Global Id: T0608100566
Action Type: RESPONSE
Date: 09/22/2011
Action: Risk Assessment Report

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/25/2010
Action: Other Report / Document

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 07/21/2009
Action: Staff Letter - #20090721

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2006
Action: Monitoring Report - Semi-Annually

UNOCAL (Continued) **S103171189**

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2007
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2004
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2005
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2007
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/30/2004
Action: Soil and Water Investigation Workplan

Global Id: T0608100566
Action Type: RESPONSE
Date: 01/11/2006
Action: Sensitive Receptor Survey Report

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/25/2005
Action: Other Report / Document

Global Id: T0608100566
Action Type: RESPONSE
Date: 07/20/2005
Action: Soil and Water Investigation Workplan

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 09/30/2010
Action: Staff Letter - #20100930

Global Id: T0608100566
Action Type: RESPONSE
Date: 01/11/2006
Action: Electronic Reporting Submittal Due

Global Id: T0608100566
Action Type: RESPONSE
Date: 03/28/2008
Action: Soil and Water Investigation Workplan

Global Id: T0608100566
Action Type: RESPONSE

UNOCAL (Continued) **S103171189**

Date: 05/16/2005
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 01/27/2014
Action: Staff Letter - #20140127

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 09/12/1991
Action: Notice of Responsibility - #19910912

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 12/12/2005
Action: Staff Letter - #20051212

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/28/2009
Action: Soil and Water Investigation Report

Global Id: T0608100566
Action Type: RESPONSE
Date: 12/31/2010
Action: Correspondence

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 05/31/2011
Action: Staff Letter - #20110531

Global Id: T0608100566
Action Type: ENFORCEMENT
Date: 06/01/2015
Action: Email Correspondence - #20150601

Global Id: T0608100566
Action Type: RESPONSE
Date: 11/15/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 05/15/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0608100566
Action Type: RESPONSE
Date: 12/31/2013
Action: Soil and Water Investigation Workplan - Regulator Responded

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 660055

UNOCAL (Continued) **S103171189**

Facility Status: 5C- Pollution Characterization
Global ID: T0608100566
APN Number: 026231120
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 660049
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660049-000001
Tank Status: Not reported
Capacity: 12000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 8

Status: Not reported
Comp Number: 660049
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660049-000002
Tank Status: Not reported
Capacity: 12000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Not reported
Comp Number: 660049
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-660049-000003
Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

UNOCAL (Continued) **S103171189**

Status:	Not reported
Comp Number:	660049
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660049-000004
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660049
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660049-000005
Tank Status:	Not reported
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660049
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660049-000006
Tank Status:	Not reported
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660049
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported

UNOCAL (Continued) **S103171189**

Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660049-000007
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	660049
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660049-000008
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0594

BK795 **HAMBLIN TRUST** **LUST** **S111760486**
ENE **1065 AMPHLETT BOULEVARD** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.950 mi.
5017 ft. **Site 1 of 2 in cluster BK**

Relative:
Lower

Actual:
9 ft.

LUST:

Region:	STATE
Global Id:	T10000003674
Latitude:	37.586037
Longitude:	-122.332246
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/11/2014
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
LOC Case Number:	110176
File Location:	State Records Center
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Benzene, Toluene, Diesel, Gasoline
Site History:	See reports in Geotracker for site history

HAMBLIN TRUST (Continued) **S111760486**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T10000003674
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T10000003674
Status:	Completed - Case Closed
Status Date:	12/11/2014
Global Id:	T10000003674
Status:	Open - Case Begin Date
Status Date:	11/28/2011
Global Id:	T10000003674
Status:	Open - Eligible for Closure
Status Date:	02/11/2014
Global Id:	T10000003674
Status:	Open - Site Assessment
Status Date:	04/20/2012

Regulatory Activities:

Global Id:	T10000003674
Action Type:	RESPONSE
Date:	05/02/2012
Action:	Correspondence
Global Id:	T10000003674
Action Type:	ENFORCEMENT
Date:	09/17/2014
Action:	Staff Letter - #20140917
Global Id:	T10000003674
Action Type:	RESPONSE
Date:	02/15/2014
Action:	Monitoring Report - Quarterly - Regulator Responded
Global Id:	T10000003674
Action Type:	RESPONSE
Date:	01/09/2015
Action:	Well Destruction Workplan - Regulator Responded
Global Id:	T10000003674
Action Type:	ENFORCEMENT
Date:	09/09/2014
Action:	Staff Letter - #20140909
Global Id:	T10000003674

HAMBLIN TRUST (Continued) **S111760486**

Action Type: RESPONSE
Date: 11/15/2013
Action: Monitoring Report - Quarterly

Global Id: T10000003674
Action Type: RESPONSE
Date: 08/15/2013
Action: Monitoring Report - Quarterly

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 06/04/2013
Action: Staff Letter - #20130604

Global Id: T10000003674
Action Type: RESPONSE
Date: 05/02/2012
Action: Correspondence

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 07/09/2014
Action: Notification - Preclosure - #20140709

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 12/11/2014
Action: Closure/No Further Action Letter - #20141211

Global Id: T10000003674
Action Type: Other
Date: 11/28/2011
Action: Leak Discovery

Global Id: T10000003674
Action Type: Other
Date: 12/19/2011
Action: Leak Reported

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 11/05/2012
Action: Staff Letter - #20121105

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 06/07/2012
Action: Staff Letter - #20120607

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 04/27/2012
Action: Notice of Responsibility - #20120427

Global Id: T10000003674
Action Type: ENFORCEMENT
Date: 04/27/2012

HAMBLIN TRUST (Continued) **S111760486**

Action: Notice of Responsibility - #20120427

Global Id: T10000003674
Action Type: RESPONSE
Date: 02/15/2013
Action: Well Installation Report

Global Id: T10000003674
Action Type: Other
Date: 12/19/2011
Action: Leak Stopped

Global Id: T10000003674
Action Type: RESPONSE
Date: 08/13/2012
Action: Preliminary Site Assessment Workplan - Regulator Responded

Global Id: T10000003674
Action Type: RESPONSE
Date: 01/16/2015
Action: Well Destruction Report

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110176
Facility Status: 9- Case Closed
Global ID: TI0000003674
APN Number: 029314010/ 020
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

796
WSW
1/2-1
0.954 mi.
5037 ft.

MCALLISTO TRUST **LUST** **S104493742**
700 EUCALYPTUS **SWEEPS UST** **N/A**
HILLSBOROUGH, CA 94010 **HIST CORTESE**

Relative:
Higher

Actual:
109 ft.

LUST:
Region: STATE
Global Id: T0608100703
Latitude: 37.573406
Longitude: -122.363547
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/30/1994
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: MM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0743
LOC Case Number: 870006
File Location: Local Agency Warehouse
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

MCALLISTO TRUST (Continued) **S104493742**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100703
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100703
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608100703
Status:	Completed - Case Closed
Status Date:	03/30/1994

Global Id:	T0608100703
Status:	Open - Case Begin Date
Status Date:	05/25/1993

Regulatory Activities:

Global Id:	T0608100703
Action Type:	ENFORCEMENT
Date:	07/09/1993
Action:	Notice of Responsibility - #1

Global Id:	T0608100703
Action Type:	Other
Date:	05/25/1993
Action:	Leak Discovery

Global Id:	T0608100703
Action Type:	Other
Date:	06/04/1993
Action:	Leak Reported

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	870006
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown

MCALLISTO TRUST (Continued) **S104493742**

Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 870006
Facility Status: 9- Case Closed
Global ID: T0608100703
APN Number: 023102110
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

SWEEPS UST:
Status: Not reported
Comp Number: 870023
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-870023-000001
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0743

BE797 **MILLER PROPERTY** **LUST** **S103892554**
SSW **730 SEABURY** **HIST CORTESE** **N/A**
1/2-1 **HILLSBOROUGH, CA 94010**
0.955 mi.
5043 ft. **Site 6 of 6 in cluster BE**

Relative:
Higher

Actual:
134 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 878012
Facility Status: 9- Case Closed
Global ID: T0608101061
APN Number: 031032030
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

MILLER PROPERTY (Continued) **S103892554**

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1160

BG798 **RECTOR CADILLAC** **LUST** **S104493492**
NW **1010 CADILLAC** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.956 mi.
5050 ft. **Site 3 of 6 in cluster BG**

Relative:
Lower

Actual:
12 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660022
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

BG799 **DENT WIZARD INTERNATIONAL** **RCRA-SQG** **1000417812**
NW **1010 CADILLAC WAY** **LUST** **CAD981416365**
1/2-1 **BURLINGAME, CA 94011** **FINDS**
0.956 mi. **EMI**
5050 ft. **Site 4 of 6 in cluster BG** **HAZNET**
HIST CORTESE
Relative: **ECHO**
Lower

Actual:
12 ft.

RCRA-SQG:
Date form received by agency: 06/03/1986
Facility name: RECTOR MOTOR CAR CO
Facility address: 1010 CADILLAC WAY
BURLINGAME, CA 94010
EPA ID: CAD981416365
Contact: ENVIRONMENTAL MANAGER
Contact address: 1010 CADILLAC WAY
BURLINGAME, CA 94010
Contact country: US
Contact telephone: (415) 348-0111
Contact email: Not reported
EPA Region: 09
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Owner/Operator Summary:
Owner/operator name: NOT REQUIRED
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: County
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JIM HANNAY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, ME 99999
Owner/operator country: Not reported
Owner/operator telephone: (415) 555-1212
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

LUST:
Region: STATE
Global Id: T0608100418
Latitude: 37.58852
Longitude: -122.361752
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 06/09/1992
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0439
LOC Case Number: 660022
File Location: Local Agency
Potential Media Affect: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100418
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100418
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100418
Status:	Completed - Case Closed
Status Date:	06/09/1992

Global Id:	T0608100418
Status:	Open - Case Begin Date
Status Date:	12/17/1987

Regulatory Activities:

Global Id:	T0608100418
Action Type:	ENFORCEMENT
Date:	05/29/1991
Action:	Notice of Responsibility - #1

Global Id:	T0608100418
Action Type:	Other
Date:	12/17/1987
Action:	Leak Discovery

Global Id:	T0608100418
Action Type:	Other
Date:	12/17/1987
Action:	Leak Reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660022
Facility Status:	9- Case Closed
Global ID:	T0608100418
APN Number:	026233080
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

FINDS:

Registry ID: 110058344073

Environmental Interest/Information System
AIR EMISSIONS CLASSIFICATION UNKNOWN

Registry ID: 110009539945

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110001195313

Environmental Interest/Information System
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS AIR POLLUTANT MAJOR

EMI:

Year:	1987
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1990
County Code:	41
Air Basin:	SF

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1995
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1996
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1997
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1998
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	1999
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2000
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Year:	2001
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2002
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2003
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2004
County Code:	41
Air Basin:	SF
Facility ID:	3533

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.28
Reactive Organic Gases Tons/Yr:	0.169448
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Year:	2005
County Code:	41
Air Basin:	SF
Facility ID:	3533
Air District Name:	BA
SIC Code:	7532
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.28
Reactive Organic Gases Tons/Yr:	.169448
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HAZNET:

envid:	1000417812
Year:	2014
GEPAID:	CAD981416365
Contact:	DENNIS DOLEN
Telephone:	6503480111
Mailing Name:	Not reported
Mailing Address:	1010 CADILLAC WAY
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CAD980675276
TSD County:	Kern
Waste Category:	Other organic solids
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.18
Cat Decode:	Other organic solids
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

envid:	1000417812
Year:	2014
GEPAID:	CAD981416365
Contact:	DENNIS DOLEN
Telephone:	6503480111
Mailing Name:	Not reported

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Mailing Address: 1010 CADILLAC WAY
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CA0000084517
TSD County: Sacramento
Waste Category: Aqueous solution with total organic residues less than 10 percent
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.6506
Cat Decode: Aqueous solution with total organic residues less than 10 percent
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: 1000417812
Year: 2014
GEPAID: CAD981416365
Contact: DENNIS DOLEN
Telephone: 6503480111
Mailing Name: Not reported
Mailing Address: 1010 CADILLAC WAY
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CAD980887418
TSD County: Alameda
Waste Category: Aqueous solution with total organic residues 10 percent or more
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 2.27265
Cat Decode: Aqueous solution with total organic residues 10 percent or more
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: San Mateo

envid: 1000417812
Year: 2013
GEPAID: CAD981416365
Contact: DENNIS DOLEN
Telephone: 6503480111
Mailing Name: Not reported
Mailing Address: 1010 CADILLAC WAY
Mailing City,St,Zip: BURLINGAME, CA 940100000
Gen County: San Mateo
TSD EPA ID: CA0000084517
TSD County: Sacramento
Waste Category: Not reported
Disposal Method: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.8022
Cat Decode: Not reported
Method Decode: Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County: Not reported

envid: 1000417812
Year: 2012
GEPAID: CAD981416365

DENT WIZARD INTERNATIONAL (Continued) **1000417812**

Contact:	DENNIS DOLEN
Telephone:	6503480111
Mailing Name:	Not reported
Mailing Address:	1010 CADILLAC WAY
Mailing City,St,Zip:	BURLINGAME, CA 940100000
Gen County:	San Mateo
TSD EPA ID:	CA0000084517
TSD County:	Sacramento
Waste Category:	Not reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.9534
Cat Decode:	Not reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

Click this hyperlink while viewing on your computer to access
10 additional CA_HAZNET: record(s) in the EDR Site Report.

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0439

ECHO:

Envid:	1000417812
Registry ID:	110009539945
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110009539945
Envid:	1000417812
Registry ID:	110058344073
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110058344073
Envid:	1000417812
Registry ID:	110001195313
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110001195313

BH800 **UNION OIL SERVICE STATION 0195** **LUST** **S101593791**
SE **346 N EL CAMINO REAL** **SWEEPS UST** **N/A**
1/2-1 **SAN MATEO, CA 94402** **HIST UST**
0.966 mi. **CA FID UST**
5099 ft. **Site 3 of 4 in cluster BH**

Relative:
Lower

Actual:
24 ft.

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	110062
Facility Status:	9- Case Closed
Global ID:	T0608100582
APN Number:	Not reported
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SWEEPS UST:

Status:	Not reported

UNION OIL SERVICE STATION 0195 (Continued) **S101593791**

Comp Number:	110080
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110080-000005
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	4

Status:	Not reported
Comp Number:	110080
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110080-000006
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	110080
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-110080-000007
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Status:	Not reported
Comp Number:	110080
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported

UNION OIL SERVICE STATION 0195 (Continued) **S101593791**

Owner Tank Id: Not reported
SWRCB Tank Id: 41-000-110080-000008
Tank Status: Not reported
Capacity: 280
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Active
Comp Number: 110080
Number: 9
Board Of Equalization: Not reported
Referral Date: 11-10-93
Action Date: 11-10-93
Created Date: 10-13-88
Owner Tank Id: 0195-RU-1
SWRCB Tank Id: 41-000-110080-000002
Tank Status: A
Capacity: 10000
Active Date: 07-07-92
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110080
Number: 9
Board Of Equalization: Not reported
Referral Date: 11-10-93
Action Date: 11-10-93
Created Date: 10-13-88
Owner Tank Id: 0195-RU-2
SWRCB Tank Id: 41-000-110080-000003
Tank Status: A
Capacity: 10000
Active Date: 07-07-92
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Status: Active
Comp Number: 110080
Number: 9
Board Of Equalization: Not reported
Referral Date: 11-10-93
Action Date: 11-10-93
Created Date: 10-13-88
Owner Tank Id: 0195-WO-1
SWRCB Tank Id: 41-000-110080-000004
Tank Status: A
Capacity: 280
Active Date: 07-07-92
Tank Use: OIL

UNION OIL SERVICE STATION 0195 (Continued) **S101593791**

STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

Status: Active
Comp Number: 110080
Number: 9
Board Of Equalization: Not reported
Referral Date: 11-10-93
Action Date: 11-10-93
Created Date: 10-13-88
Owner Tank Id: 0195-SU-1
SWRCB Tank Id: 41-000-110080-000001
Tank Status: A
Capacity: 10000
Active Date: 07-07-92
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

HIST UST:
File Number: 0002C3ED
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C3ED.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 41000557
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4153434143
Mail To: Not reported
Mailing Address: 346 N EL CAMINO REAL
Mailing Address 2: Not reported

UNION OIL SERVICE STATION 0195 (Continued) **S101593791**

Mailing City,St,Zip: SAN MATEO 94402
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

BH801 **UNION OIL SERVICE STATION 0195** **LUST** **S104660357**
SE **346 EL CAMINO REAL** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401** **HIST CORTESE**
0.966 mi.
5099 ft. **Site 4 of 4 in cluster BH**

Relative:
Lower

Actual:
24 ft.

LUST:
Region: STATE
Global Id: T0608100582
Latitude: 37.5694425
Longitude: -122.3342617
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 03/18/2002
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: DGM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0610
LOC Case Number: 110062
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Contact:
Global Id: T0608100582
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100582
Contact Type: Local Agency Caseworker
Contact Name: DENO MILANO
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: dmilano@smcgov.org
Phone Number: 6503726292

Status History:
Global Id: T0608100582
Status: Completed - Case Closed
Status Date: 03/18/2002

UNION OIL SERVICE STATION 0195 (Continued) **S104660357**

Global Id: T0608100582
Status: Open - Case Begin Date
Status Date: 10/04/1991

Regulatory Activities:
Global Id: T0608100582
Action Type: Other
Date: 11/19/1991
Action: Leak Discovery

Global Id: T0608100582
Action Type: Other
Date: 10/04/1991
Action: Leak Reported

Global Id: T0608100582
Action Type: REMEDIATION
Date: 08/01/1992
Action: Excavation

Global Id: T0608100582
Action Type: ENFORCEMENT
Date: 10/23/1991
Action: Notice of Responsibility - #1

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110062
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0016948
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0025697
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA

UNION OIL SERVICE STATION 0195 (Continued) **S104660357**

Reg Id: 41-0610

802
WSW
1/2-1
0.972 mi.
5130 ft.

MCCARTHY RESIDENCE **LUST** **S111413642**
828 IRWIN DR **N/A**
HILLSBOROUGH, CA

Relative:
Higher

Actual:
89 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 878024
Facility Status: 9- Case Closed
Global ID: TI0000003500
APN Number: 028083020
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

BI803
SSW
1/2-1
0.972 mi.
5131 ft.

CHOZEN RESIDENCE **LUST** **S106981987**
640 BREWER DR **N/A**
HILLSBOROUGH, CA

Site 2 of 2 in cluster BI

Relative:
Higher

Actual:
128 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 878019
Facility Status: 9- Case Closed
Global ID: T0608176244
APN Number: 031073040
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

BG804
WNW
1/2-1
0.973 mi.
5136 ft.

ENCORE THEATRE **LUST** **S103556739**
1159 CALIFORNIA **SWEEPS UST** **N/A**
BURLINGAME, CA 94010 **HIST CORTESE**

Site 5 of 6 in cluster BG

Relative:
Lower

Actual:
16 ft.

LUST:
Region: STATE
Global Id: T0608100196
Latitude: 37.5875505
Longitude: -122.3634809
Case Type: LUST Cleanup Site
Status: Completed - Case Closed
Status Date: 09/23/1997
Lead Agency: SAN MATEO COUNTY LOP
Case Worker: JM
Local Agency: SAN MATEO COUNTY LOP
RB Case Number: 41-0206
LOC Case Number: 660041
File Location: Local Agency
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

ENCORE THEATRE (Continued) **S103556739**

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100196
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608100196
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100196
Status:	Completed - Case Closed
Status Date:	09/23/1997

Global Id:	T0608100196
Status:	Open - Case Begin Date
Status Date:	05/09/1990

Regulatory Activities:

Global Id:	T0608100196
Action Type:	Other
Date:	05/15/1990
Action:	Leak Discovery

Global Id:	T0608100196
Action Type:	Other
Date:	05/09/1990
Action:	Leak Reported

Global Id:	T0608100196
Action Type:	ENFORCEMENT
Date:	05/15/1990
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660041
Facility Status:	9- Case Closed
Global ID:	T0608100196
APN Number:	026191250
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

ENCORE THEATRE (Continued) **S103556739**

SWEEPS UST:

Status:	Not reported
Comp Number:	660081
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	41-000-660081-000001
Tank Status:	Not reported
Capacity:	1
Active Date:	Not reported
Tank Use:	OIL
STG:	PRODUCT
Content:	HEATING OIL
Number Of Tanks:	1

HIST CORTESE:

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0206

BG805 **ENCORE THEATER** **LUST** **S100233991**
WNW **1159 CALIFORNIA** **N/A**
1/2-1 **BURLINGAME, CA 94010**
0.973 mi.
5136 ft. **Site 6 of 6 in cluster BG**

Relative:
Lower

Actual:
16 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	660041
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	Not reported
Pollution Characterization Began:	Not reported
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

BL806 **SAN MATEO HIGH AUTO SHOP** **LUST** **S104973544**
ESE **506 DELAWARE** **San Mateo Co. BI** **N/A**
1/2-1 **SAN MATEO, CA 94401** **HIST CORTESE**
0.973 mi.
5139 ft. **Site 1 of 3 in cluster BL**

Relative:
Lower

Actual:
25 ft.

LUST:

Region:	STATE
Global Id:	T0608101053
Latitude:	37.578425
Longitude:	-122.329271
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/09/1998
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1149
LOC Case Number:	110115
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608101053
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608101053
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608101053
Status:	Completed - Case Closed
Status Date:	01/09/1998

Global Id:	T0608101053
Status:	Open - Case Begin Date
Status Date:	12/22/1988

Regulatory Activities:

Global Id:	T0608101053
Action Type:	Other
Date:	12/22/1988
Action:	Leak Discovery

SAN MATEO HIGH AUTO SHOP (Continued) **S104973544**

Global Id: T0608101053
Action Type: Other
Date: 12/22/1988
Action: Leak Reported

Global Id: T0608101053
Action Type: ENFORCEMENT
Date: 10/03/1997
Action: Notice of Responsibility - #1

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0012806
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0024483
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0012806
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0024482
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0022655
Prog Element Code: GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id: PR0025158
Description: GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0022655
Prog Element Code: STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id: PR0025157
Description: STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status: INACTIVE

Region: SAN MATEO
Facility ID: FA0045664
Prog Element Code: GENERATES <27 GAL/YEAR
Record Id: PR0060564
Description: GENERATES <27 GAL/YEAR
Facility Status: ACTIVE

Region: SAN MATEO
Facility ID: FA0045664
Prog Element Code: STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id: PR0060563
Description: STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status: ACTIVE

HIST CORTESE:
Region: CORTESE

SAN MATEO HIGH AUTO SHOP (Continued) **S104973544**

Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-1149

BL807 **SAN MATEO HIGH SCHOOL** **LUST** **S103472840**
ESE **506 DELAWARE** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.973 mi.
5139 ft. **Site 2 of 3 in cluster BL**

Relative:
Lower

Actual:
25 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 110115
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

BL808 **SAN MATEO UNION HIGH SCHOOL DISTRICT TRANSPORTATIO** **LUST** **S104494516**
ESE **506 N DELAWARE ST** **N/A**
1/2-1 **SAN MATEO, CA**
0.973 mi.
5139 ft. **Site 3 of 3 in cluster BL**

Relative:
Lower

Actual:
25 ft.

SAN MATEO CO. LUST:
Region: SAN MATEO
Facility ID: 110115
Facility Status: 9- Case Closed
Global ID: T0608101053
APN Number: 033010020
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

Region: SAN MATEO
Facility ID: 110173
Facility Status: 9- Case Closed
Global ID: T10000002505
APN Number: 033010020
Case Type: SAN MATEO CO. LUST
EDR Link ID: SAN MATEO CO. LUST

BK809 **J D RECYCLING** **SWRCY** **S110656462**
ENE **1015 N AMPHLETT BLVD** **NPDES** **N/A**
1/2-1 **SAN MATEO, CA 94401**
0.998 mi.
5269 ft. **Site 2 of 2 in cluster BK**

Relative:
Lower

Actual:
9 ft.

SWRCY:

Reg Id:	130155
Cert Id:	RC130155.001
Mailing Address:	822 San Mateo Ave
Mailing City:	San Bruno
Mailing State:	CA
Mailing Zip Code:	94066
Website:	Not reported
Email:	jdrecycling0@gmail.com
Phone Number:	(510) 472-3068
Grand Father:	N
Rural:	N
Operation Begin Date:	10/04/2010
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Agency:	N/A
Monday Hours Of Operation:	9:00 am - 5:00 pm; Closed 12:00 pm - 1:00 pm
Tuesday Hours Of Operation:	9:00 am - 5:00 pm; Closed 12:00 pm - 1:00 pm
Wednesday Hours Of Operation:	CLOSED
Thursday Hours Of Operation:	9:00 am - 5:00 pm; Closed 12:00 pm - 1:00 pm
Friday Hours Of Operation:	9:00 am - 5:00 pm; Closed 12:00 pm - 1:00 pm
Saturday Hours Of Operation:	9:00 am - 5:00 pm; Closed 12:00 pm - 1:00 pm
Sunday Hours Of Operation:	9:00 am - 1:00 pm
Organization ID:	130155
Organization Name:	J & D Recycling

NPDES:

Npdes Number:	CAS000001
Facility Status:	Active
Agency Id:	0
Region:	2
Regulatory Measure Id:	435083
Order No:	97-03-DWQ
Regulatory Measure Type:	Enrollee
Place Id:	Not reported
WDID:	2 41I024085
Program Type:	Industrial
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	02/19/2013
Expiration Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	J D Recyling
Discharge Address:	1015 N Amphlett Blvd
Discharge City:	San Mateo
Discharge State:	California
Discharge Zip:	94401
RECEIVED DATE:	Not reported
PROCESSED DATE:	Not reported
STATUS CODE NAME:	Not reported
STATUS DATE:	Not reported
PLACE SIZE:	Not reported

J D RECYCLING (Continued) **S110656462**

PLACE SIZE UNIT:	Not reported
FACILITY CONTACT NAME:	Not reported
FACILITY CONTACT TITLE:	Not reported
FACILITY CONTACT PHONE:	Not reported
FACILITY CONTACT PHONE EXT:	Not reported
FACILITY CONTACT EMAIL:	Not reported
OPERATOR NAME:	Not reported
OPERATOR ADDRESS:	Not reported
OPERATOR CITY:	Not reported
OPERATOR STATE:	Not reported
OPERATOR ZIP:	Not reported
OPERATOR CONTACT NAME:	Not reported
OPERATOR CONTACT TITLE:	Not reported
OPERATOR CONTACT PHONE:	Not reported
OPERATOR CONTACT PHONE EXT:	Not reported
OPERATOR CONTACT EMAIL:	Not reported
OPERATOR TYPE:	Not reported
DEVELOPER NAME:	Not reported
DEVELOPER ADDRESS:	Not reported
DEVELOPER CITY:	Not reported
DEVELOPER STATE:	Not reported
DEVELOPER ZIP:	Not reported
DEVELOPER CONTACT NAME:	Not reported
DEVELOPER CONTACT TITLE:	Not reported
CONSTYPE LINEAR UTILITY IND:	Not reported
EMERGENCY PHONE NO:	Not reported
EMERGENCY PHONE EXT:	Not reported
CONSTYPE ABOVE GROUND IND:	Not reported
CONSTYPE BELOW GROUND IND:	Not reported
CONSTYPE CABLE LINE IND:	Not reported
CONSTYPE COMM LINE IND:	Not reported
CONSTYPE COMMERTIAL IND:	Not reported
CONSTYPE ELECTRICAL LINE IND:	Not reported
CONSTYPE GAS LINE IND:	Not reported
CONSTYPE INDUSTRIAL IND:	Not reported
CONSTYPE OTHER DESRIPTION:	Not reported
CONSTYPE OTHER IND:	Not reported
CONSTYPE RECONS IND:	Not reported
CONSTYPE RESIDENTIAL IND:	Not reported
CONSTYPE TRANSPORT IND:	Not reported
CONSTYPE UTILITY DESCRIPTION:	Not reported
CONSTYPE UTILITY IND:	Not reported
CONSTYPE WATER SEWER IND:	Not reported
DIR DISCHARGE USWATER IND:	Not reported
RECEIVING WATER NAME:	Not reported
CERTIFIER NAME:	Not reported
CERTIFIER TITLE:	Not reported
CERTIFICATION DATE:	Not reported
PRIMARY SIC:	Not reported
SECONDARY SIC:	Not reported
TERTIARY SIC:	Not reported

810
NE
> 1
1.023 mi.
5404 ft.

CARUFF CALIFORNIA CORP.
350 AIRPORT BOULEVARD
BURLINGAME, CA 92201

Database(s): **Notify 65**
EDR ID Number: **S100179131**
EPA ID Number: **N/A**

Relative:
Lower

Actual:
7 ft.

NOTIFY 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported

811
NW
> 1
1.064 mi.
5620 ft.

MOBILE SERVICE STATION #10-LGK
1200 BAYSHORE HIGHWAY
BURLINGAME, CA 92201

Database(s): **Notify 65**
EDR ID Number: **S100178832**
EPA ID Number: **N/A**

Relative:
Lower

Actual:
8 ft.

NOTIFY 65:

Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported

812
NW
> 1
1.281 mi.
6764 ft.

PACIFIC CONSTRUCTION
1369 NORTH CAROLAN AVENUE
BURLINGAME, CA 94010

Database(s): **LUST**
HIST CORTESE
Notify 65
EDR ID Number: **S100179146**
EPA ID Number: **N/A**

Relative:
Lower

Actual:
8 ft.

LUST:

Region:	STATE
Global Id:	T0608100380
Latitude:	37.590189
Longitude:	-122.367561
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/13/1997
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0399
LOC Case Number:	660015
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608100380
Contact Type:	Regional Board Caseworker

PACIFIC CONSTRUCTION (Continued) **S100179146**

Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608100380
Contact Type: Local Agency Caseworker
Contact Name: JACOB MADDEN
Organization Name: SAN MATEO COUNTY LOP
Address: 2000 ALAMEDA DE LAS PULGAS
City: SAN MATEO
Email: jmadden@smcgov.org
Phone Number: 6503726298

Status History:
Global Id: T0608100380
Status: Completed - Case Closed
Status Date: 11/13/1997

Global Id: T0608100380
Status: Open - Case Begin Date
Status Date: 06/23/1989

Regulatory Activities:
Global Id: T0608100380
Action Type: ENFORCEMENT
Date: 10/10/1989
Action: Notice of Responsibility - #1

Global Id: T0608100380
Action Type: Other
Date: 06/23/1989
Action: Leak Discovery

Global Id: T0608100380
Action Type: Other
Date: 06/23/1989
Action: Leak Reported

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 660015
How Discovered: OM
Leak Cause: Unknown
Leak Source: Unknown
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: Not reported
Pollution Characterization Began: Not reported
Pollution Remediation Plan Submitted: Not reported

PACIFIC CONSTRUCTION (Continued) **S100179146**

Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

HIST CORTESE:
Region: CORTESE
Facility County Code: 41
Reg By: LTNKA
Reg Id: 41-0399

NOTIFY 65:
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported

813
ESE
> 1
1.416 mi.
7474 ft.

PURI PROPERTY **ENVIROSTOR** **S109277233**
20 NORTH RAILROAD AVENUE **SLIC** **N/A**
SAN MATEO, CA 94401 **San Mateo Co. BI**

Relative:
Lower

Actual:
28 ft.

ENVIROSTOR:
Facility ID: 60001044
Status: Refer: 1248 Local Agency
Status Date: 06/04/2006
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 1
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Berkeley
Assembly: 22
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not Applicable
Latitude: 37.56961
Longitude: -122.3250
APN: 032331150
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 032331150
Alias Type: APN
Alias Name: SL0608137877
Alias Type: GeoTracker Global ID
Alias Name: 60001044
Alias Type: Envirostor ID Number

PURI PROPERTY (Continued) **S109277233**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	06/07/2006
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	06/08/2006
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

SLIC:

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	08/21/2007
Global Id:	SL0608137877
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	119167
Latitude:	37.5695435772216
Longitude:	-122.325004106815
Case Type:	Cleanup Program Site
Case Worker:	MM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Tetrachloroethylene (PCE), Trichloroethylene (TCE)
Site History:	Can be extracted from most recent report in Geotracker or at San Mateo County offices if submitted prior to 2005, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report.

Click here to access the California GeoTracker records for this facility:

San Mateo Co. BI:

Region:	SAN MATEO
Facility ID:	FA0010573
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0026153
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

814
SE
> 1
1.473 mi.
7775 ft.

BELLA MANGIATA RESTAURANT
233 BALDWIN
SAN MATEO, CA 94401

ENVIROSTOR
LUST
San Mateo Co. BI

S108418328
N/A

Relative:
Lower

Actual:
28 ft.

ENVIROSTOR:

Facility ID:	41720090
Status:	Refer: Other Agency
Status Date:	07/29/1994
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0.04
NPL:	NO
Regulatory Agencies:	SAN MATEO COUNTY
Lead Agency:	SAN MATEO COUNTY
Program Manager:	Not reported
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Assembly:	22
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.56707
Longitude:	-122.3259
APN:	032321200
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	032321200
Alias Type:	APN
Alias Name:	41720090
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	10/15/1980
Comments:	FACILITY IDENTIFIED ACTIVE SITE ID'D BY DRIVE BY
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	08/18/2003
Comments:	Site screening completed.Site is under the oversight of the local agency.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

Schedule Revised Date: Not reported

LUST:

Region:	STATE
Global Id:	T0608125386
Latitude:	37.567064
Longitude:	-122.326029
Case Type:	LUST Cleanup Site
Status:	Open - Site Assessment
Status Date:	11/09/2006
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	MEJ
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1310
LOC Case Number:	Not reported
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water), Soil, Soil Vapor
Potential Contaminants of Concern:	Stoddard solvent / Mineral Spriits / Distillates
Site History:	Extracted from RRM's February 28, 2008 Underground Storage Tank Removal and Over-Excavation Report, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is a 30-foot wide by 130-foot long parcel of land fronting the north side of Baldwin Avenue in downtown San Mateo between North San Mateo Drive and North Ellsworth Avenue. The parcel immediately behind the site to the south at 22 N. San Mateo Drive is occupied by Mateo Garden Apartments, a group of two-story apartment buildings. The parcel to the east at 235 Baldwin is a dry cleaner. The parcel to the west at 210 Baldwin is a two-story office building. Existing site improvements include two structures that date back to the 1930s, including a main building fronting Baldwin Avenue and a separate 12-foot wide by 30-foot long building at the rear of the property. In the early 1990's, a 25-foot wide by 36-foot long building and wooden deck patio addition covering most of the remaining property was constructed at the rear of the parcel; the addition has served as the banquet hall for the Bella Mangiata Restaurant, the current tenant and leaseholder since the early 1990's. Mr. Michael Chang owns both the site and the adjacent property to the east at 235 Baldwin Avenue. Between the early 1930s to early 1980s, Sunrise Cleaners (the dry cleaner currently operating at 235 Baldwin Avenue) used the site for dry cleaning operations: the front building at the site was used as storefront. The rear building at the site was used for cleaning activities at least through the 1950's. Subsurface contamination was first documented in March 2006, following complaints of paint/solvent-like odors inside the banquet hall. A contractor was hired by the landlord to determine the cause of the odors. This led to the discovery of three vent lines and an abandoned steel UST (UST #1) positioned in a vertical configuration beneath the floor. The tank removal contractor estimated the capacity of the tank to be approximately 2,000-gallons. Upon its permitted removal during September 2006, the tank dimensions were reported to be approximately 5 feet wide by 8 feet long, or approximately 1,100 to 1,200 gallons. Use of the banquet hall was discontinued following tank removal activities. At the time of discovery, the tank was reportedly filled with a liquid that was later identified as water containing a low concentration of Stoddard solvent. Sludge at the bottom of the tank was also noted. The UST was apparently abandoned in the late 1950s or

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

early 1960s when, according to industry reports, most dry cleaners switched from Stoddard solvent to perchloroethylene (PCE). In March 2006, under contract by the property owner, Express Plumbing of San Mateo, CA performed a video inspection of the vent lines at the rear building and also inspected beneath the banquet hall deck to locate possible USTs. A series of holes were cut into the deck to enable visual and physical access to soil beneath the deck. Hand excavations were made at each location to inspect the shallow soil. One of the locations was dug to approximately 5 feet below ground surface (bgs) exposing the top of a vertically positioned steel UST. In the process of exposing the USTs Express Plumbing created a pit that was approximately 8 feet wide, 9.5 feet long and 5 feet deep. Approximately 13 bank cubic yards (bcy) of soil spoils were off-hauled and disposed off at a landfill. Five steel pipes were encountered in the tank pit and partially cut and removed. Three other pipes and several concrete slabs were partially exposed in other locations. In April and May 2006, Clearwater Environmental Mgmt Inc. of Union City, CA, (Clearwater) sampled the contents of the UST and also the soil alongside the UST. The samples were analyzed for volatile organic compounds (VOCs) semi-VOCs (SVOCs), CAM 17 metals, and Total Recoverable Petroleum Hydrocarbons (TRPH) by a CA state certified analytical laboratory. The liquid sample contained 6.4 milligrams per liter (mg/l) TRPH, and several VOCs representative of Stoddard solvent compounds including 940 micrograms per liter (ug/l) 1,2,4-trimethylbenzene, 240 ugll 1,3,5-trimethylbenzene, and trace levels of toluene and xylenes. The soil sample contained 36 milligrams per kilogram (mg/kg) TRPH and some of the same VOCs found in the liquid sample. On August 11, 2006, Geomatrix of Mountlake Terrace, Washington (contracted by the tenant) sampled the contents of the UST from the liquid surface (TANK-W1-081106). The same day, Clearwater used a vacuum tank truck to remove the liquid from the UST. Contents were hauled and disposed of at a licensed recycler under manifest. Geomatrix then collected a sample of the sludge remaining at the bottom of the tank (TANK-S-081106). Samples were analyzed for a wide range of constituents including VOCs, SVOCs, and total petroleum hydrocarbons as gasoline. Stoddard solvent, diesel, and motor oil (TPHg, TPHss, TPHd, and TPHmo, respectively) by a CA state certified analytical laboratory. Most notably, the liquid sample contained 12,000 ug/l TPHg and the sludge sample contained 20,000 mg/kg TPHg. However, the laboratory noted that the chromatographic pattern for the gasoline range organics resembled Stoddard solvent rather than gasoline. On August 31, 2006, Cruz Brothers was contracted by Clearwater to perform an underground utility survey to further locate the three suspected vent pipes. One of the pipes extended toward the adjacent property to the southwest, and the remaining two ran beneath the banquet hall addition toward the UST. A metal detector was also used to locate other possible abandoned USTs but none were found. On September 12 through 14, 2006, Clearwater transferred the sludge from the UST into a 55-gallon drum, cleaned the interior of the tank, cut the tank into pieces, and then removed it. All sludge, liquid wastes and tank debris were off-hauled and disposed of at a licensed recycling facility under manifest. According to Geomatrix, there were no holes, cracks, or obvious signs of leakage in the shell of the tank. There was; however, a strong solvent odor present in the open pit following tank removal. Geomatrix collected a bottom soil sample from beneath the tank (TANK-S-03) and one from the north sidewall (TANK-S-04) of the tank

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

pit. The bottom sample contained 17 mg/kg TPHg and 10 mg/kg TPHss: the north sidewall sample contained 4,400 mg/kg TPHg and 2,500 mg/kg TPHss. Again, the laboratory noted that the chromatographic pattern for the gasoline range organics resembled Stoddard solvent rather than gasoline. In October 2006, Geomatrix conducted a review of historic site documents including Sanborn Maps and City of San Mateo Building Department records. The review revealed that the original dry cleaning buildings were constructed in the 1930s, but no records for USTs were found. A preliminary risk assessment that included an evaluation of acute and chronic effects of worker exposure to Stoddard solvent vapors was also conducted. Based on 4,400 mglkg TPHg and 2,500 mg/kg TPHss in the soil sample collected adjacent to the tank and using conventional transport modeling with conservative default assumptions for soil porosity and attenuation, an indoor air concentration of 10,500 micrograms per cubic meter (ugIm3) was predicted. This concentration is well above the odor threshold for TPHg vapor, which is considered similar to TPHss vapor with respect to the odor emissions. However, this concentration is well below all Occupational Safety and Health Administration (OSHA) and National Institute for Occupational Safety and Health (NIOSH) ceiling levels for worker exposure to TPHss vapor, assuming 8-hour or 10-hour workdays. With respect to concerns associated with long-term exposure to low levels of Stoddard solvent vapors, Geomatrix predicted that the indoor air concentration was well above the San Francisco Regional Water Quality Control Board (RWQCB) commercial environmental screening level (ESL) for TPHg vapors which could be compared to Stoddard solvent vapors based on similar common carbon range compounds (C6 to C12). In January 2007, Advanced Geological Science, Inc. (AGS) performed a geophysical survey at the site to locate other possible USTs. They surveyed the entire banquet room area using a magnetometer and ground penetrating radar (GPR). Test results were negative. Similar to Cruz Brothers previous work, AGS applied an electrical current to the suspected vent pipes. Results differed from those of Cruz Brothers in that some of the piping routes did not match. In February 2007, ACC Environmental Consultants (ACC) of Oakland, California advanced ten soil borings (B1 through B10) to depths ranging from 8 feet to 25 feet bgs to delineate the extent of soil and groundwater contamination. Refusal at less than 2 feet bgs was met at two of the borings (B2 and B7) due to concrete slabs. Soil borings were sampled and logged at 5-foot intervals. Three grab groundwater samples and 20 soil samples were submitted for laboratory analysis. Groundwater was encountered at 25 feet bgs within more permeable sand strata that was first occurred at approximately 18 feet bgs. Groundwater samples contained 210 ug/l, 1,600 ug/1, and 130,000 ug/l TPHg with the highest concentration at Boring B4, located near the former UST. Only two of the twenty soil samples contained detectable TPHg concentrations. Concentrations were 2,100 mg/kg in Boring 84 at 18 feet and 23 mg/kg in Boring B-9 at 24 feet, both located in the capillary fringe. During the week of June 25, 2007, RRM subcontractors removed the majority of the wood deck flooring located in the banquet hall and covered patio area and the concrete floor in the former dry cleaning process room. Additionally, the wood fence at rear of the property was removed and replaced with temporary chain link fence panels to secure the sire. The section of deck covering the tank pit from UST #I was left in-place. RRM's Work Plan for Removal Actions, Interim Remedial Measures, Subsurface Investigations, and Pilot Testing was prepared in response to

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

directives set forth in County correspondence dated May 31, 2007. The work plan presented a site conceptual transport and exposure model for a restaurant banquet room with a wood-deck floor overlying the backyard of an abandoned 1930-60s era dry cleaning facility that used Stoddard solvent. The conceptual model identified potential primary and secondary source areas and gaps in existing site data. The work plan proposed the following tasks: (1) removal of remaining wood deck flooring, rear wall of the banquet room, concrete floor of the former dry cleaning process room, and all concrete surfaces in the back yard area: (2) remove all abandoned USTs and UST piping and other inactive former dry cleaning operation piping and sample and analyze any suspect material under direction of County inspectors; (3) remove up to 500 bcy of contaminated soil, if encountered, under direction of County inspectors; (4) conduct exploratory excavations to 5 feet bgs to investigate areas of concern and collect and sample and analyze any suspect material under direction of County inspectors; (5) advance up to twelve direct-push borings to collect and analyze soil. groundwater, and vapor samples: (6) collect and analyze three sub-slab soil vapor samples; (7) install, develop, and sample three groundwater monitoring wells, one air-sparge well, and one soil vapor extraction (SVE) well and (8) perform air-sparge and SVE feasibility testing. In the County correspondence dated August 6, 2007. Tasks 1, 2, 5, 6, and 7 were approved. Task 8 was denied, and additional explanation was requested for Tasks 3 and 4. In a letter dated August 20, 2007, RRM responded to questions and comments presented by the County in connection with Tasks 3 and 4 and strongly recommended that the County approve Task 8 in the interest of mitigating nuisance odors to allow the banquet hall to reopen. In their response dated August 6, 2007, the County approved Tasks 3 and 4, but again declined Task 8 on the basis that they would not approve pilot testing for interim remedial measures (IRMs) until site characterization work was complete and a feasibility study work plan was prepared and submitted. In September 2007, RRM subcontractors removed the remaining wood deck flooring and the lower half of the rear wall of the banquet hall. A mini-excavator was used to remove the concrete walkways and footings and to conduct exploratory trenching to locate and uncover other possible USTs and piping. The exploratory trenching followed the four vent lines from the southwest corner of the former dry cleaning process room and extended to depths of approximately 2 feet to 6 feet bgs. Three additional single-wall steel USTs (USTs #2 through #4) were discovered beneath the former wood deck (Figure 2). The piping connected to the USTs was exposed using the mini-excavator. Most of the piping led to the former dry cleaning process room. A 2-inch water line and an electrical conduit were identified in the area between the storage room and the main restaurant building where a previous utility survey identified a possible vent line. The approximate locations of the USTs and piping are shown on Figure 2. Also in September 2007, RRM conducted additional on-site investigation work. Seven direct-push exploratory borings were advanced up to 25 feet bgs using a limited access direct-push drill rig. A total of 16 soil samples, 5 grab-groundwater samples, and 6 soil vapor samples were collected and submitted for laboratory analysis. Analytical data is summarized in Tables 1 through 4. Sample analytical data show the presence of significant Stoddard solvent contamination in soil and groundwater including possible separate phase under the former banquet room floor. In an effort to complete the site investigation phase to the extent needed for the County to

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

approve the pilot testing and implementation of the lRMs proposed in the July 2007 work plan, RRM prepared the Preliminary Subsurface Investigation Findings and Work Plan for Additional Subsurface Investigation, Well Installation, and Interim Remediation Pilot Testing, dated October 19, 2007. The work plan proposed additional on-site and off-site investigation work and feasibility testing for proposed IRMs. The lRMs were proposed to restore the use of the banquet hall by mitigating the vapor intrusion problems created from the former USTs and associated soil and groundwater contamination.

Click here to access the California GeoTracker records for this facility:

Contact:

Global Id:	T0608125386
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not reported

Global Id:	T0608125386
Contact Type:	Local Agency Caseworker
Contact Name:	MARC MULLANEY
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	mmullaney@smcgov.org
Phone Number:	6503726289

Status History:

Global Id:	T0608125386
Status:	Open - Case Begin Date
Status Date:	04/27/2006

Global Id:	T0608125386
Status:	Open - Site Assessment
Status Date:	11/09/2006

Regulatory Activities:

Global Id:	T0608125386
Action Type:	RESPONSE
Date:	08/23/2013
Action:	Interim Remedial Action Plan - Regulator Responded

Global Id:	T0608125386
Action Type:	ENFORCEMENT
Date:	12/10/2010
Action:	Staff Letter

Global Id:	T0608125386
Action Type:	ENFORCEMENT
Date:	12/10/2010
Action:	13267 Requirement

Global Id: T0608125386

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

Action Type: RESPONSE
Date: 08/11/2012
Action: Remedial Progress Report

Global Id: T0608125386
Action Type: RESPONSE
Date: 01/02/2009
Action: Electronic Reporting Submittal Due

Global Id: T0608125386
Action Type: RESPONSE
Date: 03/31/2009
Action: Soil and Water Investigation Report

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 05/04/2010
Action: Notice of Violation - #20100504

Global Id: T0608125386
Action Type: Other
Date: 04/27/2006
Action: Leak Discovery

Global Id: T0608125386
Action Type: REMEDIATION
Date: 11/05/2007
Action: Excavation

Global Id: T0608125386
Action Type: Other
Date: 10/24/2006
Action: Leak Reported

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 11/15/2006
Action: Notice of Responsibility - #20061115

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 01/30/2007
Action: Staff Letter - #20070130

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 12/10/2008
Action: Staff Letter - #20081210

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Staff Letter - #20090709

Global Id: T0608125386
Action Type: RESPONSE
Date: 01/15/2007

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

Action: Preliminary Site Assessment Workplan

Global Id: T0608125386
Action Type: RESPONSE
Date: 06/04/2007
Action: Preliminary Site Assessment Report

Global Id: T0608125386
Action Type: RESPONSE
Date: 07/30/2007
Action: Preliminary Site Assessment Workplan

Global Id: T0608125386
Action Type: RESPONSE
Date: 12/04/2007
Action: Preliminary Site Assessment Report

Global Id: T0608125386
Action Type: RESPONSE
Date: 03/31/2009
Action: Preliminary Site Assessment Report

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 11/07/2007
Action: Staff Letter - #20071107

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 08/06/2007
Action: Staff Letter - #20070806

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 11/15/2006
Action: Staff Letter - #20061115

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 05/31/2007
Action: Staff Letter - #20070531

Global Id: T0608125386
Action Type: RESPONSE
Date: 09/03/2014
Action: Interim Remedial Action Plan

Global Id: T0608125386
Action Type: Other
Date: 08/11/2006
Action: Leak Stopped

Global Id: T0608125386
Action Type: RESPONSE
Date: 12/31/2010
Action: Unknown

BELLA MANGIATA RESTAURANT (Continued) **S108418328**

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 12/10/2010
Action: 13267 Requirement

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 12/02/2008
Action: Staff Letter - #20081202

Global Id: T0608125386
Action Type: ENFORCEMENT
Date: 01/13/2011
Action: Staff Letter

San Mateo Co. BI:
Region: SAN MATEO
Facility ID: FA0029840
Prog Element Code: UNDERGROUND TANK - GENERAL
Record Id: PR0051337
Description: UNDERGROUND TANK - GENERAL
Facility Status: INACTIVE

Count: 3 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BURLINGAME	S100186218	BROWNING-FERRIS INDUSTRIES	AIRPORT BOULEVARD NEAR BROADWA	94010	ENVIROSTOR
SAN MATEO	S101482227	BROWNING-FERRIS IND (SAN MATEO LAN	EAST 3RD AVENUE	94401	ENVIROSTOR
SAN MATEO COUNTY	S107538814		HUNNART PARK IN UNINC CO NEAR		CDL

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: N/A
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/13/2015
Date Data Arrived at EDR: 01/06/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 135

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 07/06/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/22/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 10

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/22/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Date Data Arrived at EDR: 05/29/2015
Date Made Active in Reports: 06/11/2015
Number of Days to Update: 13

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/16/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 09/11/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 53

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 03/30/2016
Date Made Active in Reports: 05/20/2016
Number of Days to Update: 51

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/28/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Annually

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 05/02/2016
Date Data Arrived at EDR: 05/04/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 48

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 05/02/2016
Date Data Arrived at EDR: 05/04/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 48

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/16/2016
Date Data Arrived at EDR: 05/18/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 34

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 05/18/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Varies

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST: Geotracker's Leaking Underground Fuel Tank Report
Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/16/2016
Number of Days to Update: 61

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

LUST REG 1: Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/09/2015
Date Data Arrived at EDR: 02/12/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 112

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/13/2015
Date Data Arrived at EDR: 10/23/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 118
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 02/25/2016
Date Data Arrived at EDR: 04/27/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 37
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/27/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 02/05/2016
Date Data Arrived at EDR: 04/29/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 35
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 07/26/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Semi-Annually

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 12/11/2015
Date Data Arrived at EDR: 02/19/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 105
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 02/17/2016
Date Data Arrived at EDR: 04/27/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 37
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

SLIC: Statewide SLIC Cases

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/16/2016
Number of Days to Update: 61

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: Quarterly

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: Semi-Annually

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: Varies

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: Semi-Annually

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: Semi-Annually

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: Annually

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 49

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities
A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 08/01/2009
Date Data Arrived at EDR: 09/10/2009
Date Made Active in Reports: 10/01/2009
Number of Days to Update: 21

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Quarterly

INDIAN UST R5: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 52

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 02/05/2016
Date Data Arrived at EDR: 04/29/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 35

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 07/26/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/29/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 67

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 07/29/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/25/2016
Date Data Arrived at EDR: 04/27/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 37

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 01/07/2016
Date Data Arrived at EDR: 01/08/2016
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 41

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 12/03/2015
Date Data Arrived at EDR: 02/04/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 120

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Semi-Annually

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 01/26/2016
Date Data Arrived at EDR: 02/05/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 119

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Date Data Arrived at EDR: 11/25/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 65

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 05/02/2016
Date Data Arrived at EDR: 05/04/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 48

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 07/01/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing
A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 02/29/2016
Date Data Arrived at EDR: 03/07/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 58

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 06/15/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/21/2016
Date Data Arrived at EDR: 03/22/2016
Date Made Active in Reports: 07/13/2016
Number of Days to Update: 113

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/22/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 03/15/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 54

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 04/07/2016
Date Data Arrived at EDR: 04/12/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 50

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 05/13/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/27/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: No Update Planned

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/04/2016
Date Data Arrived at EDR: 06/03/2016
Date Made Active in Reports: 07/13/2016
Number of Days to Update: 40

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/31/2016
Next Scheduled EDR Contact: 06/13/2016
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database
The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 05/02/2016
Date Data Arrived at EDR: 05/04/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 48

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 05/10/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 38

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Varies

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/04/2016
Date Data Arrived at EDR: 06/03/2016
Date Made Active in Reports: 07/13/2016
Number of Days to Update: 40

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/31/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 06/07/2016
Date Data Arrived at EDR: 06/09/2016
Date Made Active in Reports: 06/23/2016
Number of Days to Update: 14

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 06/01/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database
The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CA FID UST: Facility Inventory Database
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 43

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/29/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 06/06/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 43

Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 06/07/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/24/2015
Date Data Arrived at EDR: 06/26/2015
Date Made Active in Reports: 09/02/2015
Number of Days to Update: 68

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/28/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Annually

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 04/11/2016
Date Data Arrived at EDR: 04/27/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 51

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 07/26/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

LDS: Land Disposal Sites Listing

The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/16/2016
Number of Days to Update: 61

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing

The State Water Resources Control Board and nine Regional Water Quality Control Boards partner with the Department of Defense (DoD) through the Defense and State Memorandum of Agreement (DSMOA) to oversee the investigation and remediation of water quality issues at military facilities.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/16/2016
Number of Days to Update: 61

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/09/2015
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 34

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Varies

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 06/10/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Date Data Arrived at EDR: 03/09/2011
Date Made Active in Reports: 05/02/2011
Number of Days to Update: 54

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/01/2015
Date Data Arrived at EDR: 09/03/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 61

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/18/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/24/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 133
Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/24/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/25/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74
Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/07/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2015
Date Data Arrived at EDR: 08/26/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 69
Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/25/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3
Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 05/12/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

PADS: PCB Activity Database System
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 10/15/2014
Date Made Active in Reports: 11/17/2014
Number of Days to Update: 33
Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Date Data Arrived at EDR: 02/06/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 31
Source: Environmental Protection Agency
Telephone: 202-564-5088
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/18/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 28
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/09/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/10/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/29/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/07/2015
Date Data Arrived at EDR: 07/09/2015
Date Made Active in Reports: 09/16/2015
Number of Days to Update: 69
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/04/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/02/2015
Number of Days to Update: 46

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/24/2015
Date Made Active in Reports: 09/30/2015
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/27/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 12/08/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 34

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/11/2016
Date Data Arrived at EDR: 03/15/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 80

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 06/20/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Date Data Arrived at EDR: 11/26/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/08/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/20/2015
Date Data Arrived at EDR: 10/27/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 69

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/22/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/09/2016
Date Data Arrived at EDR: 03/02/2016
Date Made Active in Reports: 04/15/2016
Number of Days to Update: 44

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 06/03/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 06/03/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 07/20/2015
Date Data Arrived at EDR: 09/09/2015
Date Made Active in Reports: 11/03/2015
Number of Days to Update: 55

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 06/08/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 10/25/2015
Date Data Arrived at EDR: 01/29/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 67

Source: Department of Defense
Telephone: 571-373-0407
Last EDR Contact: 06/20/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 03/01/2016
Date Data Arrived at EDR: 03/03/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 03/30/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 40

Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 06/28/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Quarterly

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 02/08/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 04/01/2016
Number of Days to Update: 37

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 03/22/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 48

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 06/22/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 05/27/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 54

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 04/25/2016
Date Data Arrived at EDR: 04/29/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 53

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 06/01/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 49

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 10/14/2015
Date Made Active in Reports: 12/11/2015
Number of Days to Update: 58

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Annually

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 05/23/2016
Date Data Arrived at EDR: 05/25/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 56

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 04/11/2016
Date Data Arrived at EDR: 04/12/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 50

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 07/13/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Quarterly

MINES: Mines Site Location Listing

A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 03/15/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 54

Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Varies

MWMP: Medical Waste Management Program Listing

The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 43

Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 06/07/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

NPDES: NPDES Permits Listing

A listing of NPDES permits, including stormwater.

Date of Government Version: 05/16/2016
Date Data Arrived at EDR: 05/18/2016
Date Made Active in Reports: 06/23/2016
Number of Days to Update: 36

Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 05/18/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing

A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 06/06/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 43

Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 06/07/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Quarterly

PROC: Certified Processors Database

A listing of certified processors.

Date of Government Version: 03/15/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 54

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/14/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records

Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 09/10/2015
Date Data Arrived at EDR: 01/05/2016
Date Made Active in Reports: 02/12/2016
Number of Days to Update: 38

Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: No Update Planned

UIC: UIC Listing

A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 02/12/2016
Date Data Arrived at EDR: 03/16/2016
Date Made Active in Reports: 06/13/2016
Number of Days to Update: 89

Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 06/16/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing

Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water board?s review found that more than one-third of the region?s active disposal pits are operating without permission.

Date of Government Version: 04/15/2015
Date Data Arrived at EDR: 04/17/2015
Date Made Active in Reports: 06/23/2015
Number of Days to Update: 67

Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 07/15/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Varies

WDS: Waste Discharge System

Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 05/20/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13

Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 06/24/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/20/2015
Date Data Arrived at EDR: 09/23/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 103

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/22/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/24/2016
Date Data Arrived at EDR: 05/25/2016
Date Made Active in Reports: 07/13/2016
Number of Days to Update: 49

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Quarterly

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historic Gas Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 04/12/2016
Date Data Arrived at EDR: 04/14/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 48

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

Underground Tanks
Underground storage tank sites located in Alameda county.

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 04/14/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 48

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA Facility List
Cupa Facility List

Date of Government Version: 06/06/2016
Date Data Arrived at EDR: 06/09/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 12

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA Facility Listing
Cupa facility list.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/03/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 18

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 04/29/2016
Date Data Arrived at EDR: 05/03/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 45

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 06/27/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 05/26/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 22

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Varies

CONTRA COSTA COUNTY:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 05/24/2016
Date Data Arrived at EDR: 05/26/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 55

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 08/01/2016
Next Scheduled EDR Contact: 11/14/2016
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA Facility List
Cupa Facility list

Date of Government Version: 04/08/2016
Date Data Arrived at EDR: 05/03/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 50

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/14/2016
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 02/22/2016
Date Data Arrived at EDR: 02/24/2016
Date Made Active in Reports: 04/01/2016
Number of Days to Update: 37

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/14/2016
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 04/04/2016
Date Data Arrived at EDR: 04/06/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 28

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 07/13/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Semi-Annually

HUMBOLDT COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 03/16/2016
Date Data Arrived at EDR: 03/21/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 44

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

IMPERIAL COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 04/26/2016
Date Data Arrived at EDR: 04/28/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 50

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: Varies

INYO COUNTY:

CUPA Facility List
Cupa facility list.

Date of Government Version: 09/10/2013
Date Data Arrived at EDR: 09/11/2013
Date Made Active in Reports: 10/14/2013
Number of Days to Update: 33

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

KERN COUNTY:

Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 03/01/2016
Date Data Arrived at EDR: 03/03/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 67

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 05/27/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 26

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

LAKE COUNTY:

CUPA Facility List
Cupa facility list

Date of Government Version: 04/26/2016
Date Data Arrived at EDR: 04/27/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 51

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 04/18/2016
Next Scheduled EDR Contact: 08/01/2016
Data Release Frequency: Varies

LOS ANGELES COUNTY:

San Gabriel Valley Areas of Concern
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206
Source: EPA Region 9
Telephone: 415-972-3178
Last EDR Contact: 06/15/2016
Next Scheduled EDR Contact: 07/04/2016
Data Release Frequency: No Update Planned

HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 03/30/2016
Date Data Arrived at EDR: 04/01/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 38
Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 04/18/2016
Date Data Arrived at EDR: 04/20/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 42
Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 07/19/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Varies

City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2016
Date Data Arrived at EDR: 01/26/2016
Date Made Active in Reports: 03/22/2016
Number of Days to Update: 56
Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 07/18/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Varies

Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 03/29/2016
Date Data Arrived at EDR: 04/06/2016
Date Made Active in Reports: 06/13/2016
Number of Days to Update: 68
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 07/13/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Annually

City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 03/30/2015
Date Data Arrived at EDR: 04/02/2015
Date Made Active in Reports: 04/13/2015
Number of Days to Update: 11
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 07/13/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Semi-Annually

City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 11/04/2015
Date Data Arrived at EDR: 11/13/2015
Date Made Active in Reports: 12/17/2015
Number of Days to Update: 34
Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 07/25/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Annually

City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 04/05/2016
Date Data Arrived at EDR: 04/26/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 36

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 03/02/2016
Date Data Arrived at EDR: 03/07/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 58

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

MARIN COUNTY:

Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 04/07/2016
Date Data Arrived at EDR: 04/26/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 36

Source: Public Works Department Waste Management
Telephone: 415-499-6647
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 02/26/2016
Date Data Arrived at EDR: 03/01/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 64

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 06/15/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

MONO COUNTY:

CUPA Facility List
CUPA Facility List

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 06/01/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 21

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 03/15/2016
Date Data Arrived at EDR: 03/18/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 47
Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

NAPA COUNTY:

Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 12/05/2011
Date Data Arrived at EDR: 12/06/2011
Date Made Active in Reports: 02/07/2012
Number of Days to Update: 63
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: No Update Planned

Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Date Data Arrived at EDR: 01/16/2008
Date Made Active in Reports: 02/08/2008
Number of Days to Update: 23
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA Facility List
CUPA facility list.

Date of Government Version: 04/18/2016
Date Data Arrived at EDR: 05/06/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 42
Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/14/2016
Data Release Frequency: Varies

ORANGE COUNTY:

List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 05/01/2016
Date Data Arrived at EDR: 05/17/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 35
Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Annually

List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 05/01/2016
Date Data Arrived at EDR: 05/17/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 35
Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 05/01/2016
Date Data Arrived at EDR: 05/11/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 21
Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 05/11/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

PLACER COUNTY:

Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 03/07/2016
Date Data Arrived at EDR: 03/09/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 56
Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 06/15/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Semi-Annually

RIVERSIDE COUNTY:

Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 04/13/2016
Date Data Arrived at EDR: 04/15/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 24
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 06/20/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Quarterly

Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 04/13/2016
Date Data Arrived at EDR: 04/15/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 47
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 06/20/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/02/2016
Date Data Arrived at EDR: 04/06/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 56
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 07/06/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/02/2016
Date Data Arrived at EDR: 04/06/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 56
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 07/05/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Quarterly

SAN BERNARDINO COUNTY:

Hazardous Material Permits

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 06/09/2016
Date Data Arrived at EDR: 06/10/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 40

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 05/09/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 09/23/2013
Date Data Arrived at EDR: 09/24/2013
Date Made Active in Reports: 10/17/2013
Number of Days to Update: 23

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Quarterly

Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 10/31/2015
Date Data Arrived at EDR: 11/07/2015
Date Made Active in Reports: 01/04/2016
Number of Days to Update: 58

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: Varies

Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

Local Oversite Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/29/2010
Date Data Arrived at EDR: 03/10/2011
Date Made Active in Reports: 03/15/2011
Number of Days to Update: 5
Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 04/06/2016
Date Data Arrived at EDR: 04/08/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 26
Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 06/15/2016
Next Scheduled EDR Contact: 10/03/2016
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 05/23/2016
Date Data Arrived at EDR: 05/24/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 28
Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

SAN MATEO COUNTY:

Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 15
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 05/27/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Annually

Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/15/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 55
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/08/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

SANTA CLARA COUNTY:

Cupa Facility List
Cupa facility list

Date of Government Version: 05/25/2016
Date Data Arrived at EDR: 05/26/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 27

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 05/25/2016
Next Scheduled EDR Contact: 09/12/2016
Data Release Frequency: Annually

Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 05/26/2016
Date Data Arrived at EDR: 06/01/2016
Date Made Active in Reports: 07/20/2016
Number of Days to Update: 49

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA Facility List
CUPA facility listing.

Date of Government Version: 05/31/2016
Date Data Arrived at EDR: 06/02/2016
Date Made Active in Reports: 06/21/2016
Number of Days to Update: 19

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA Facility List
Cupa Facility List.

Date of Government Version: 03/18/2016
Date Data Arrived at EDR: 03/21/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 44

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 05/23/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Varies

SOLANO COUNTY:

Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/22/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 48

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/08/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 03/14/2016
Date Data Arrived at EDR: 03/21/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 44

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/08/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

SONOMA COUNTY:

Cupa Facility List
Cupa Facility list

Date of Government Version: 04/05/2016
Date Data Arrived at EDR: 04/08/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 26

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 07/07/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Varies

Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 04/01/2016
Date Data Arrived at EDR: 04/05/2016
Date Made Active in Reports: 05/09/2016
Number of Days to Update: 34

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 06/24/2016
Next Scheduled EDR Contact: 10/10/2016
Data Release Frequency: Quarterly

SUTTER COUNTY:

Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/07/2016
Date Made Active in Reports: 06/23/2016
Number of Days to Update: 16

Source: Sutter County Department of Agriculture
Telephone: 530-822-7500
Last EDR Contact: 06/02/2016
Next Scheduled EDR Contact: 09/19/2016
Data Release Frequency: Semi-Annually

TUOLUMNE COUNTY:

CUPA Facility List
Cupa facility list

Date of Government Version: 05/03/2016
Date Data Arrived at EDR: 05/10/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 38

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 07/20/2016
Next Scheduled EDR Contact: 10/07/2016
Data Release Frequency: Varies

VENTURA COUNTY:

Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 04/29/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 49

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 07/25/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 06/28/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Annually

Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 05/13/2016
Next Scheduled EDR Contact: 08/22/2016
Data Release Frequency: Quarterly

Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 03/28/2016
Date Data Arrived at EDR: 04/29/2016
Date Made Active in Reports: 06/22/2016
Number of Days to Update: 54

Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 07/25/2016
Next Scheduled EDR Contact: 11/07/2016
Data Release Frequency: Quarterly

Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 02/26/2016
Date Data Arrived at EDR: 03/17/2016
Date Made Active in Reports: 05/04/2016
Number of Days to Update: 48

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 06/16/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Quarterly

YOLO COUNTY:

Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 04/12/2016
Date Data Arrived at EDR: 04/19/2016
Date Made Active in Reports: 06/01/2016
Number of Days to Update: 43

Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 06/30/2016
Next Scheduled EDR Contact: 10/17/2016
Data Release Frequency: Annually

YUBA COUNTY:

CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 04/29/2016
Date Data Arrived at EDR: 05/03/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 45

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 07/27/2016
Next Scheduled EDR Contact: 11/14/2016
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/13/2016
Next Scheduled EDR Contact: 08/29/2016
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 07/17/2015
Date Made Active in Reports: 08/12/2015
Number of Days to Update: 26

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/11/2016
Next Scheduled EDR Contact: 10/24/2016
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 05/01/2016
Date Data Arrived at EDR: 05/06/2016
Date Made Active in Reports: 06/17/2016
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/06/2016
Next Scheduled EDR Contact: 08/15/2016
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/24/2015
Date Made Active in Reports: 08/18/2015
Number of Days to Update: 25

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/18/2016
Next Scheduled EDR Contact: 10/31/2016
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 06/19/2015
Date Made Active in Reports: 07/15/2015
Number of Days to Update: 26

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/01/2016
Next Scheduled EDR Contact: 09/05/2016
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 04/14/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 50

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/13/2016
Next Scheduled EDR Contact: 09/26/2016
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish & Game
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

DONNELLY
1214 DONNELLY
BURLINGAME, CA 94010

TARGET PROPERTY COORDINATES

Latitude (North):	37.579506 - 37° 34' 46.22''
Longitude (West):	122.347789 - 122° 20' 52.04''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	557589.6
UTM Y (Meters):	4159157.2
Elevation:	32 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5640626 SAN MATEO, CA
Version Date:	2012
West Map:	5641104 MONTARA MOUNTAIN, CA
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General North

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 32 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Target Property County	FEMA Flood Electronic Data
SAN MATEO, CA	YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property:	0650190004B - FEMA Q3 Flood data
Additional Panels in search area:	0650190002C - FEMA Q3 Flood data 0603280000B - FEMA Q3 Flood data 0603110129B - FEMA Q3 Flood data 0603200000B - FEMA Q3 Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
SAN MATEO	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
1	0 - 1/8 Mile ESE	Not Reported
2	1/8 - 1/4 Mile ESE	E, Flat
A3	1/8 - 1/4 Mile NW	Not Reported
4	1/8 - 1/4 Mile SW	N
A6	1/4 - 1/2 Mile NW	NNW
7	1/4 - 1/2 Mile NW	N

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
8	1/4 - 1/2 Mile WNW	Not Reported
B9	1/4 - 1/2 Mile ESE	SE
B10	1/4 - 1/2 Mile ESE	E
C11	1/4 - 1/2 Mile NW	N
C12	1/4 - 1/2 Mile NW	NNE
C13	1/4 - 1/2 Mile NW	NNE
D14	1/4 - 1/2 Mile ESE	E
D15	1/4 - 1/2 Mile ESE	E
16	1/4 - 1/2 Mile West	NNE
17	1/4 - 1/2 Mile WSW	Not Reported
18	1/2 - 1 Mile SSW	Not Reported
D19	1/2 - 1 Mile ESE	NE
E20	1/2 - 1 Mile ESE	NE
E21	1/2 - 1 Mile ESE	Varies
22	1/2 - 1 Mile NW	NE
23	1/2 - 1 Mile North	NNW
24	1/2 - 1 Mile SSW	Not Reported
F25	1/2 - 1 Mile South	Not Reported
F26	1/2 - 1 Mile South	NE
27	1/2 - 1 Mile SSE	NNE
28	1/2 - 1 Mile NE	N
29	1/2 - 1 Mile NE	NNE
G30	1/2 - 1 Mile WNW	N
G31	1/2 - 1 Mile WNW	N
32	1/2 - 1 Mile SE	E

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 4688986.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
LAT/LONG:	37.579506 / 122.347789	INQUIRY #:	4688986.2s
		DATE:	August 02, 2016 9:26 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches		Not reported	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 2

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches		Not reported	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 3

Soil Component Name: Orthents

Soil Surface Texture: variable

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	59 inches	variable	Not reported	Not reported	Max: Min:	Max: Min:

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
5	4839	1/4 - 1/2 Mile North

PHYSICAL SETTING SOURCE MAP - 4688986.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
LAT/LONG:	37.579506 / 122.347789	INQUIRY #:	4688986.2s
		DATE:	August 02, 2016 9:26 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

			Database	EDR ID Number
1 **ESE** **0 - 1/8 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660081 Not Reported Not Reported Not Reported 14 08/12/1997	**AQUIFLOW**	**55534**
2 **ESE** **1/8 - 1/4 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660060 E, Flat 23 22 Not Reported 02/04/1998	**AQUIFLOW**	**55439**
A3 **NW** **1/8 - 1/4 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660017 Not Reported 13.5 12.5 Not Reported 02/22/1990	**AQUIFLOW**	**55454**
4 **SW** **1/8 - 1/4 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660023 N 19.5 12.5 Not Reported 06/26/1992	**AQUIFLOW**	**55503**
5 **North** **1/4 - 1/2 Mile** **Lower**			**CA WELLS**	**4839**

Water System Information:

Prime Station Code:	04S/04W-18L03 M	User ID:	ENG
FRDS Number:	4100569001	County:	San Mateo
District Number:	04	Station Type:	WELL/AMBANT/MUN/INTAKE
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	373500.0 1222045.0	Precision:	100 Feet (one Second)
Source Name:	WELL 01		
System Number:	4100569		
System Name:	BURLINGAME HIGH SCHOOL		
Organization That Operates System:	Not Reported		
Pop Served:	86	Connections:	Unknown, Small System
Area Served:	Not Reported		

A6 **NW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660006 NNW 11.0 9.0 Not Reported 07/24/1997	**AQUIFLOW**	**55456**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
7 **NW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660061 N 7.60 3.85 Not Reported 05/12/1995	**AQUIFLOW**	**55459**
8 **WNW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660042 Not Reported 17 12.5 Not Reported 10/05/1990	**AQUIFLOW**	**55547**
B9 **ESE** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660043 SE 27.9 21.0 Not Reported 05/06/1995	**AQUIFLOW**	**55474**
B10 **ESE** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	66048 E 24.85 15.55 Not Reported 09/28/1995	**AQUIFLOW**	**55448**
C11 **NW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660034 N Not Reported Not Reported 8.40 01/03/1993	**AQUIFLOW**	**55462**
C12 **NW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0717 NNE Not Reported Not Reported 13 08/31/1993	**AQUIFLOW**	**55291**
C13 **NW** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0710 NNE Not Reported Not Reported 13 08/31/1993	**AQUIFLOW**	**55293**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
D14 **ESE** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660005 E 17.95 15.64 Not Reported 03/18/1999	**AQUIFLOW**	**55523**
D15 **ESE** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0519 E 17.95 15.64 Not Reported 03/18/1999	**AQUIFLOW**	**55525**
16 **West** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660066 NNE 8.3 6.6 Not Reported 12/05/1994	**AQUIFLOW**	**55545**
17 **WSW** **1/4 - 1/2 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	870018 Not Reported Not Reported Not Reported 10 10/30/1998	**AQUIFLOW**	**64315**
18 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	668078 Not Reported Not Reported Not Reported 13 04/01/1997	**AQUIFLOW**	**55539**
D19 **ESE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0401 NE Not Reported Not Reported 20 11/06/1986	**AQUIFLOW**	**67928**
E20 **ESE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	000289 NE Not Reported Not Reported 20 11/06/1986	**AQUIFLOW**	**67926**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
E21 **ESE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0349 Varies 21.75 24.47 Not Reported 02/19/1999	**AQUIFLOW**	**68182**
22 **NW** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	110107 NE 4.30 4.88 Not Reported 03/25/1999	**AQUIFLOW**	**67861**
23 **North** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	001533 NNW 8.5 6.0 Not Reported 01/30/1997	**AQUIFLOW**	**55469**
24 **SSW** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0289 Not Reported 17.0 20.5 Not Reported 09/11/1992	**AQUIFLOW**	**67614**
F25 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0728 Not Reported 52 Not Reported Not Reported 04/10/1996	**AQUIFLOW**	**67642**
F26 **South** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0202 NE 51.7 52 Not Reported 04/20/1991	**AQUIFLOW**	**67622**
27 **SSE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0196 NNE 12.97 16.67 Not Reported 04/22/1999	**AQUIFLOW**	**67779**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID / Direction / Distance / Elevation			Database	EDR ID Number
28 **NE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660069 N 6.75 6.50 Not Reported 03/29/1996	**AQUIFLOW**	**55445**
29 **NE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660033 NNE 5.8 5.1 Not Reported 03/19/1993	**AQUIFLOW**	**55442**
G30 **WNW** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660053 N 8.47 4.02 Not Reported 04/24/1996	**AQUIFLOW**	**55486**
G31 **WNW** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0240 N 8.47 4.02 Not Reported 04/24/1996	**AQUIFLOW**	**55484**
32 **SE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	41-0610 E 7.11 9.98 Not Reported 04/02/1999	**AQUIFLOW**	**67831**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
94010	88	2

Federal EPA Radon Zone for SAN MATEO County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 94010

Number of sites tested: 2

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	1.350 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.200 pCi/L	100%	0%	0%
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish & Game
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

OTHER STATE DATABASE INFORMATION

California Oil and Gas Well Locations
Source: Department of Conservation
Telephone: 916-323-1779
Oil and Gas well locations in the state.

RADON

State Database: CA Radon
Source: Department of Health Services
Telephone: 916-324-2208
Radon Database for California

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix 4 - Historical Topographic Maps

Donnelly

1214 Donnelly

Burlingame, CA 94010

Inquiry Number: 4688986.4

August 01, 2016

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

08/01/16

Site Name:

Donnelly
1214 Donnelly
Burlingame, CA 94010
EDR Inquiry # 4688986.4

Client Name:

Protech Consulting & Engineer.
1208 Main Street
Redwood City, CA 94063
Contact: Woody Lovejoy

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Protech Consulting & Engineer. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 601-OH16
Project: Donnelly

Coordinates:

Latitude:	37.579506 37° 34' 46" North
Longitude:	-122.347789 -122° 20' 52" West
UTM Zone:	Zone 10 North
UTM X Meters:	557588.12
UTM Y Meters:	4159361.91
Elevation:	32.00' above sea level

Maps Provided:

2012	1947
1997	1939
1993	1915
1980	1899
1973	1896
1968	
1956	
1949	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2012 Source Sheets



Montara Mountain

7.5-minute, 24000



San Mateo

7.5-minute, 24000

1997 Source Sheets



San Mateo

7.5-minute, 24000
Aerial Photo Revised 1997

1993 Source Sheets



San Mateo

7.5-minute, 24000
Aerial Photo Revised 1993

1980 Source Sheets



San Mateo

7.5-minute, 24000
Photo Revised 1980
Aerial Photo Revised 1956

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1973 Source Sheets



San Mateo

7.5-minute, 24000
Photo Revised 1973
Aerial Photo Revised 1973

1968 Source Sheets



San Mateo

7.5-minute, 24000
Photo Revised 1968
Aerial Photo Revised 1968

1956 Source Sheets



San Mateo

7.5-minute, 24000
Aerial Photo Revised 1946

1949 Source Sheets



San Mateo

7.5-minute, 24000
Aerial Photo Revised 1946

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1947 Source Sheets



San Mateo

7.5-minute, 24000
Aerial Photo Revised 1946

1939 Source Sheets



San Mateo

15-minute, 62500
Aerial Photo Revised 1939

1915 Source Sheets



San Mateo

15-minute, 62500

1899 Source Sheets



San Mateo

15-minute, 62500

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1896 Source Sheets



San Mateo

15-minute, 62500



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 2012, 7.5-minute
W, Montara Mountain, 2012, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1997, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, San Mateo, 1993, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N

Historical Topo Map

1980



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, San Mateo, 1980, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N

Historical Topo Map

1973



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, San Mateo, 1973, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N

Historical Topo Map

1968



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1968, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1956, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1949, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1947, 7.5-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1939, 15-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1915, 15-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1899, 15-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Mateo, 1896, 15-minute

SITE NAME: Donnelly
ADDRESS: 1214 Donnelly
Burlingame, CA 94010
CLIENT: Protech Consulting & Engineer.

N

Appendix 5 - Sanborn® Maps

Donnelly

1214 Donnelly

Burlingame, CA 94010

Inquiry Number: 4688986.3

August 01, 2016

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

08/01/16

Site Name:

Donnelly
1214 Donnelly
Burlingame, CA 94010
EDR Inquiry # 4688986.3

Client Name:

Protech Consulting & Engineer.
1208 Main Street
Redwood City, CA 94063
Contact: Woody Lovejoy

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Protech Consulting & Engineer. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # E677-4F0F-AE8B

PO # 601-OH16

Project Donnelly

Maps Provided:

1970
1959
1949
1946
1921
1913
1908

Sanborn® Library search results

Certification #: E677-4F0F-AE8B

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Protech Consulting & Engineer. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key


This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1970 Source Sheets




Volume 1, Sheet 15

1959 Source Sheets



Volume 1, Sheet 8



Volume 1, Sheet 15

1949 Source Sheets



Volume 1, Sheet 15

1946 Source Sheets



Volume 1, Sheet 15

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1921 Source Sheets



Volume 1, Sheet 15

1913 Source Sheets




Volume 1, Sheet 7

1908 Source Sheets



Volume 1, Sheet 1




Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #	E677-4F0F-AE8B
Copyright	1970

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #	E677-4F0F-AE8B
Copyright	1959

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 15
Volume 1, Sheet 8

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #:	E677-4F0F-AE8B
Copyright	1949

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #	E677-4F0F-AE8B
Copyright	1946

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 15

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #	E677-4F0F-AE8B
Copyright	1921

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 15

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification # E677-4F0F-AE8B

Site Name:	Donnelly
Address:	1214 Donnelly
City, ST, ZIP:	Burlingame, CA 94010
Client:	Protech Consulting & Engineer.
EDR Inquiry:	4688986.3
Order Date:	08/01/2016
Certification #	E677-4F0F-AE8B
Copyright	1913

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 7


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name: Donnelly
Address: 1214 Donnelly
City, ST, ZIP: Burlingame, CA 94010
Client: Protech Consulting & Engineer.
EDR Inquiry: 4688986.3
Order Date: 08/01/2016
Certification #: E677-4F0F-AE8B
Copyright: 1908

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 1

0 Feet 150 300 600

N

Appendix 6 - Historical Aerial Photographs

Donnelly

1214 Donnelly

Burlingame, CA 94010

Inquiry Number: 4688986.12

August 01, 2016

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

08/01/16

Site Name:

Donnelly
1214 Donnelly
Burlingame, CA 94010
EDR Inquiry # 4688986.12

Client Name:

Protech Consulting & Engineer.
1208 Main Street
Redwood City, CA 94063
Contact: Woody Lovejoy

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2010	1"=500'	Flight Year: 2010	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2005	1"=500'	Flight Year: 2005	USDA/NAIP
1998	1"=500'	Flight Date: August, 29 1998	USDA
1993	1"=500'	Acquisition Date: July, 10 1993	USGS/DOQQ
1982	1"=500'	Flight Date: July, 08 1982	USDA
1974	1"=500'	Flight Date: June, 26 1974	USGS
1968	1"=500'	Flight Date: June, 14 1968	USGS
1956	1"=500'	Flight Date: September, 08 1956	USGS
1946	1"=500'	Flight Date: July, 29 1946	USGS
1943	1"=500'	Flight Date: October, 11 1943	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 4688986.12
YEAR: 2012
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 2010
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 2009
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 2005
= 500'
N
EDR



INQUIRY #: 4688986.12
YEAR: 1998
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 1993
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 1982
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 1974
= 500'
N
EDR

[redacted]



INQUIRY #: 4688986.12

YEAR: 1968

= 500'

N

EDR


INQUIRY #: 4688986.12
YEAR: 1956
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 1946
= 500'
N
EDR


INQUIRY #: 4688986.12
YEAR: 1943
= 500'
N
EDR

Appendix 7 - City Directory

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.5
August 02, 2016

The EDR-City Directory Image Report

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2013	☑	☐	Cole Information Services
2008	☑	☐	Cole Information Services
2003	☑	☐	Cole Information Services
1999	☑	☐	Cole Information Services
1995	☑	☐	Cole Information Services
1992	☑	☐	Cole Information Services
1985	☑	☐	Haines Criss-Cross Directory
1980	☑	☐	Haines Criss-Cross Directory
1977	☑	☐	Haines Criss-Cross Directory
1970	☑	☐	Haines Criss-Cross Directory

RECORD SOURCES

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

FINDINGS

TARGET PROPERTY STREET

1214 Donnelly
Burlingame, CA 94010

Year	*CD Image*	*Source*

DONNELLY AVE

2013	pg A1	Cole Information Services
2008	pg A2	Cole Information Services
2003	pg A3	Cole Information Services
1999	pg A4	Cole Information Services
1995	pg A5	Cole Information Services
1992	pg A6	Cole Information Services
1985	pg A7	Haines Criss-Cross Directory
1985	pg A8	Haines Criss-Cross Directory
1980	pg A10	Haines Criss-Cross Directory
1980	pg A9	Haines Criss-Cross Directory
1977	pg A11	Haines Criss-Cross Directory
1970	pg A12	Haines Criss-Cross Directory

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 2013

1200	KIMBERLY VASQUEZ
1208	SUR LA TABLE
1210	RENDA ZAAROUR SALON
1212	A LOCKSMITH BURLINGAME
	BLUSH ORGANIC FROZEN YOGURT
1214	TANDEM ENTREPRENEURS
	TDA INVESTMENT GROUP INC
1215	ST CLAIRS CATERING
1218	ALFREDO GARCIA
1220	ARMANDO ROMERO
1221	DIDI SALON

Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 2008

1210	RENDA ZAAROUR SALON
1212	1212 GALLERY
	DONALD J CARRUTH
1214	DALE TURNER ASSOCIATES INC
1215	ST CLAIRS GOURMET
	ST CLIRS PERSONALIZED GRMT SERVICE
1218	ALFREDO GARCIA
	ILLIANA RUIZ
	RUKSHAN ALI
1220	ARMANDO ROMERO
	BLANCA MARTINEZ
1221	DIDI SALON
1223	401 CLOTHING BOUTIQUE
	CERES USA

Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 2003

1208	ANTIQUE MARKET OF BURLINGAME
	COMANDATORI DESIGN GROUP
1210	RENDA ZAAROUR SALON
1212	EVEREST RUGS
1214	TURNER DALE ASSOCS
1215	ST CLAIRS GOURMET
1220	JENNIFER LASICH
1221	OCCUPANT UNKNOWN
1223	CANDLE OUTLET
	CERES USA

Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 1999

1208	DONNELLY SQUARE FITNESS CLUB FOR WOMEN
1214	TDA INCORPORATED
1218	ALFREDO GARCIA
	ILLIANA RUIZ
	QUENT CORDAIR
	RUKSHAN ALI
1220	ARMANDO ROMERO
	BLANCA MARTINEZ
1221	TU SALON
1223	SIMPLY COTTON
1230	OCCUPANT UNKNOWN

Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 1995

1208	DONNELLY SQUARE FITNESS CLUB
1209	FLYING FISH TRADING CO
	HALLER CO
1212	MIKES AUTOMOTIVE SVC
1214	BROWN, JANET
	J B & ASSOC
	TURNER DEHONEY & ASSOC
1218	CORDAIR, QUENT
1221	OCCUPANT UNKNOWNN
	TU SALON
1224	OCCUPANT UNKNOWNN
1226	ANDERSON, LANE
1234	COMPUTER BOOKKEEPING SVC
	DEPENDABLE BOOKKEEPING & TAXES
	KAYLOR, ANGELA
	PENINSULA BOOKKEEPING SVC


Target Street	Cross Street	Source
✓	-	Cole Information Services

DONNELLY AVE 1992

1208	DONNELLY SQ FITNESS
1212	MIKES AUTOMOTIVE SV
1213	COMMUNIQUE
	HOME YARDAGE OFC
	KOCKOS, JOHN
1214	J B&ASSOCIATES
	TURNER DEHONEY&ASC
1218	MARLIN, LOUIS JR
1220	ABERDROTH, DIANE
1221	TU SALON
1226	ANDERSON, LANE
	HELA, ROBERT E
1234	COMPUTER BUSNS SERV
	DEPENDABLE BKKPG&TX
	PENINSULA BKKPNG SV

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

DONNELLY AVE 1985



DONNELLY AV 94010
BURLINGAME

1202	XXXX	00
1208	NEMESIA	347-2005 +5
1209	CREST OF NATURE	344-7611 +5
	E B S DATA PRCSNG	342-9292 +5
	WELLS CLIFF	344-7611 +5

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


DONNELLY AVE 1985



DONNELLY AV		94010 CONT	
1212	MIKES AUTOMOTIVE SV	344-9059	
	MIKES RADIATOR SERV	344-9059	
1213	INVESTMENT PROPERTS	348-8118	3
	MORTGAGE BANKRS FND	571-0711	+5
1214	FOUNDERS TITLE CO	348-7991	3
	NOR PEN	347-7753	2
	NOR PEN INVESTMENT	347-7753	
1215	BERTA GRAY ENTPRS	344-1286	4
1217	MASTERCRAFT PRINTRS	344-8855	4
1218	XXXX	00	
1220	SHEA M	347-6428	+5
1221	ENCORE SHOP THE	344-5226	
	MARTHAS VLG STORE	344-8684	3
	VILLAGE TELEPHONE	344-8684	
	VIVANS BEAUTY SALON	343-4122	
1224	BARTOLETTI ALDO A	347-7318	2
1226	ANDERSON LANE	344-2062	9
1230	XXXX	00	
1234	DEPENDABLE BKKPG&TX	348-2000	7
	PENINSULA BKKPNG SV	342-1228	1
	PENINSULA BKKPNG SV	342-4011	3
★	19 BUS 7 RES	6 NEW	

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

DONNELLY AVE 1980




DONNELLY AV 94010
BURLINGAME

1202★	DESSINDAY ADVR	343-0122	8
★	FEED STORE THE	343-1338	6
1208	XXXX	00	
1209★	E B S DATA PROCSSNG	342-7258	3
1212★	MIKES AUTOMOTIVE SV	344-9059	
★	MIKES RADIATOR SERV	344-9059	+0
1213★	PINE COMPANY	347-8068	9

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


DONNELLY AVE 1980



DONNELLY AV		94010 CONT
1214	XXXX	00
1218	GORRAN STEVE	347-4151+0
	LONG WILLIAM	342-2235+0
1220	MOULDING RICHARD	343-7681 9
	REITER J	347-7876+0
1221★	ENCORE SHOP THE	344-5226
★	MARTHAS VILLAGE STR	344-8684 2
★	VILLAGE TELEPHONE	344-8684 4
★	VIVANS BEAUTY SALON	343-4122
1224	XXXX	00
1226	ANDERSON LANE	344-2062 9
	EATON DOUGLAS	344-5634 2
	LETUAL WILLIAM	347-7603+0
	MINGUS JAMES L	348-3260+0
1230★	FREUND FRIEDA	344-4759
★	FRIEDAS CATERING	344-4759
1234★	DEPENDABLE BOOKKPNG	348-2000 7
★	PENSLA BOOKKEEPING	342-1228 7
★	PENSLA BOOKKEEPING	342-4011 8
★	15 BUS 11 RES	6 NEW

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

DONNELLY AVE 1977



DONNELLY AV 94010 BURLINGAME

```
1202*BOB ANDERSON SALES 344-2211+7
    *FEED STORE THE     343-1338 6
1208*BURLNG FRME&ATO BDY342-9233 5
1209*E B S DATA PROCSSNG342-7258 3
1212*MIKES AUTOMOTIVE SV344-9059
1214 LEONG KIM          342-3380+7
    *MIGUELS ANTIQUES   347-0908+7
1218 KELLY R S          342-1420+7
1220 BISHOP ELOISE MRS  342-9610
     MRAZ JAMES         344-3972 6
1221*ENCORE SHOP THE    344-5226
    *MARTHAS VILLAGE STR344-8684 2
    *VILLAGE TELEPHONE  344-8684 4
    *VIVANS BEAUTY SALON343-4122
1224 MARQUART TESSIE M  342-5014
1226 EATON DOUGLAS      344-5634 2
     SULLIVAN JOHN      344-9885 6
1230*FREUND FRIEDA      344-4759
    *FRIEDAS CATERING   344-4759
1234*DEPENDABLE BOOKKPNG348-2000+7
    *PENSLA BOOKKEEPG SV342-1228+7
    *  14 BUS    7 RES    6 NEW
```

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

DONNELLY AVE 1970

DONNELLY AV 94010 BURLINGAME

1208	*BRLNGM FRM&AUTO BDY	342-9233
1209	*PENINSULA TBLTNG SV	342-7258
	*PTS MEDICAL RECORDS	344-4693
1212	*MIKES AUTOMOTIVE SV	344-9059
1213	*WHERRETT&ASSOCIATES	347-4661
1214	*KIMS RESTAURANT	342-3380
1218	BERNHARD VERNA MRS	344-8977
	BRAUN BETTY	347-5185
	FOX MARGARET J	344-7924
	GRIBBLE DORA MRS	342-5016
1220	BISHOP ELOISE MRS	342-9610
	BROOKS LESLIE O	343-6572
	FAVALESSA MARIA	344-8189
	VASATKA B	342-7593
	WILLSTADTER H	343-4088
1221	*ENCORE SHOP THE	344-5226
	*VIVANS BEAUTY SALON	343-4122
1224	MARQUART TESSIE M	342-5014
A	FREUND PAUL W	343-5593
1226	MCLIN KATHRYN	343-1227
1230	*FREUND FRIEDA	344-4759
	*FRIEDAS CATERING	344-4759
1234	*RUPERT FISH CO INC	342-6027
	* 11 BUS 12 RES	

Appendix 8 – Environmental Liens and AUL Report

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.7
August 04, 2016

EDR Environmental Lien and AUL Search

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien and AUL Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

1214 Donnelly
Donnelly
Burlingame, CA 94010

RESEARCH SOURCE

Source 1:

San Mateo Recorder
San Mateo, CA

PROPERTY INFORMATION

Deed 1:

Type of Deed:	deed
Title is vested in:	Patricia Ann Britton Trustee
Title received from:	Patricia Ann Britton
Deed Dated	12/10/1997
Deed Recorded:	1/3/1998
Book:	NA
Page:	na
Volume:	na
Instrument:	na
Docket:	NA
Land Record Comments:	
Miscellaneous Comments:	
Legal Description:	See Exhibit
Legal Current Owner:	Patricia Ann Britton Trustee
Parcel # / Property Identifier:	029-151-160
Comments:	See Exhibit

Deed 2:

Type of Deed:	deed
Title is vested in:	Patricia Ann Britton Trustee
Title received from:	Patricia Ann Britton
Deed Dated	12/10/1997
Deed Recorded:	1/13/1998
Book:	NA
Page:	na
Volume:	NA
Instrument:	na
Docket:	na
Land Record Comments:	

Miscellaneous Comments:

Legal Description: See Exhibit

Legal Current Owner: Patricia Ann Britton Trustee

Parcel # / Property Identifier: 029-151--150

Comments: See Exhibit

Deed 3:

Type of Deed:	deed
Title is vested in:	Patricia Ann Britton Trustee
Title received from:	Patricia Ann Britton
Deed Dated	12/10/1997
Deed Recorded:	2/25/1998
Book:	NA
Page:	na
Volume:	na
Instrument:	na
Docket:	NA
Land Record Comments:	
Miscellaneous Comments:	

Legal Description: See Exhibit

Legal Current Owner: Patricia Ann Britton Trustee

Parcel # / Property Identifier: 029-151-170

Comments: See Exhibit

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

AULs: Found ☐ Not Found ☒

Deed Exhibit 1

Order No.
Escrow No.
Loan No.

WHEN RECORDED MAIL TO:

W.J. Britton & Co,
1811 El Camino Real
Burlingame, CA 94010

OFFICIAL RECORDS OF SAN MATEO COUNTY
ASSESSOR-COUNTY CLERK-RECORDER
WARREN SLOCUM

Recorded at Request of
W J BRITTON & CO

98-004330 01/13/98 01:39

Recording Fee: 8.00 RSOARES

MAIL TAX STATEMENTS TO:

W.J. Britton & Co,
1811 El Camino Real
Burlingame, CA 94010

SPACE ABOVE THIS LINE FOR RECORDER'S USE

DOCUMENTARY TRANSFER TAX $ -0- Exempt R&T 11911

..... Computed on the consideration or value of property conveyed; OR

..... Computed on the consideration or value less liens or encumbrances remaining at time of sale.

Signature of Declarant or Agent determining tax -- Firm Name

GRANT DEED

2p

FOR A VALUABLE CONSIDERATION, receipt of which is hereby acknowledged,

Patricia Ann Britton

hereby GRANT(S) to

Patricia Ann Britton as Trustee of the Patricia Ann Britton Revocable Intervivos Trust dated August 15, 1997

the real property in the City of Burlingame
County of San Mateo , State of California, described as

1218 Donnelly Avenue, Burlingame, CA

A.P. No. 029-151-160 See legal deacription attached

98-004330

Dated December 10, 1997

Patricia Ann Britton

STATE OF CALIFORNIA }
COUNTY OF San Mateo } ss.

On December 10, 1997 before me,
Sonja C. Zamora,
personally appeared Patricia Ann Britton,
personally known to me (or proved to me on the basis of satisfactory evidence) to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s) or the entity upon behalf of which the person(s) acted, executed the instrument.

WITNESS my hand and official seal.

Signature Sonja C. Zamora

SONJA C. ZAMORA
Comm. # 1133667
NOTARY PUBLIC - CALIFORNIA
San Mateo County
My Comm. Expires April 13, 2001

(This area for official notarial seal)

MAIL TAX STATEMENTS AS DIRECTED ABOVE

1002 (1/94)

LEGAL DESCRIPTION

1218 Donnelly Avenue

ASSESSOR'S PARCEL NO.: 029-151-160

LEGAL DESCRIPTION:

PARCEL ONE:

COMMENCING at a point on the Southeasterly line of Block 3, as same is designated on the map entitled "MAP NO. 2 OF THE PROPERTY OF THE BURLINGAME LAND CO., SAN MATEO CO., CAL.", which map was filed in the office of the Recorder of the County of San Mateo, State of California, on February 20, 1905 in Book "D" of Maps at page 38, and a copy entered in Book 3 of Maps at page 55, distant Southwesterly thereon 254 feet 7 inches from the Southwesterly line of Main Street, as shown on the above map, said point of commencement also being the most Westerly corner of that parcel of land conveyed by George W. Gates to Estelle M. Gates, his wife, by Deed dated May 10, 1905 and recorded May 12, 1905 in Book 117 of Deeds at page 64, Records of San Mateo County; thence from said point of commencement Southwesterly along said Southeasterly line of Block 3, 41 feet 6 inches; thence Southeasterly and parallel to the Southwesterly line of the parcel of land so conveyed in the above mentioned Deed, 109 feet, more or less, to the Northwesterly line of that certain strip of land conveyed to Carrie D. Donnelly, et al, to the City of Burlingame, by Deed dated August 1, 1917 and recorded April 26, 1919 in Book 278 of Deeds at Page 426, Records of San Mateo County, said strip of land being commonly known as Donnelly Avenue; thence Northeasterly along said Northwesterly line of Donnelly Avenue, 41 feet 6 inches, more or less, to said Southwesterly boundary line of the parcel of land conveyed to Gates above mentioned; thence Northwesterly along said Southwesterly boundary of lands so conveyed to Gates, 106 feet 6 inches, to the point of commencement.

APN 029-151-160 APN 029-015-151-16

93-043-63

Deed Exhibit 2

Order No.
Escrow No.
Loan No.

WHEN RECORDED MAIL TO:

W.J. Britton & Co.
1811 El Camino Real
Burlingame, CA 94010

OFFICIAL RECORDS OF SAN MATEO COUNTY
ASSESSOR-COUNTY CLERK-RECORDER
WARREN SLOCUM

Recorded at Request of
W J BRITTON & CO

98-004329 01/13/98 01:39

Recording Fee: 8.00 RSOARES

MAIL TAX STATEMENTS TO:

W.J. Britton & Co.
1811 El Camino Real
Burlingame, CA 94010

SPACE ABOVE THIS LINE FOR RECORDER'S USE

DOCUMENTARY TRANSFER TAX $ -0- Transfer Exempt

..... Computed on the consideration or value of property conveyed; OR

..... Computed on the consideration or value less liens or encumbrances remaining at time of sale

Signature of Declarant or Agent determining tax — Firm Name

GRANT DEED

2p

FOR A VALUABLE CONSIDERATION, receipt of which is hereby acknowledged,

Patricia Ann Britton

hereby GRANT(S) to

Patricia Ann Britton as Trustee of the Patricia Ann Britton Revocable Intervivos Trust dated August 15, 1997

the real property in the City of Burlingame
County of San Mateo , State of California, described as

1214 Donnelly Avenue, Burlingame, CA

A.P. no. 029-151-150 See legal description attached

98-004329-86

Dated December 10, 1997

Patricia Ann Britton

STATE OF CALIFORNIA)
COUNTY OF San Mateo) ss.

On December 10, 1997 before me,

Sonja C. Zamora,

personally appeared Patricia Ann Britton,

personally known to me (or proved to me on the basis of satisfactory evidence) to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s) or the entity upon behalf of which the person(s) acted, executed the instrument.

WITNESS my hand and official seal.

Signature Sonja C Zamora

SONJA C. ZAMORA
Comm. # 1133667
NOTARY PUBLIC - CALIFORNIA
San Mateo County
My Comm. Expires April 13, 2001

(This area for official notarial seal)

MAIL TAX STATEMENTS AS DIRECTED ABOVE

1002 (1/94)

LEGAL DESCRIPTION

1214 Donnelly Avenue

ASSESSOR'S PARCEL NO.: 029-151-150

LEGAL DESCRIPTION:

BEGINNING at the most Westerly corner of the one acre tract of land conveyed by Minnie M. MacDonagle and Nellie B. Moody, as the duly appointed, qualified and acting executrices of the last will and testament of William Corbet, deceased, to George W. Gates by Deed recorded May 31, 1901, in Book 91 of Deeds at Page 52, Records of San Mateo County to which reference is hereby made and the same made a part thereof, and which said point of beginning is also the most Northerly corner of the 4½ acre tract of land formerly owned by John Donnelly; thence South 41° 18' East on and along the dividing line between the parcel above referred to, 106.5 feet to the Northwesterly line of a new street commonly called Donnelly Avenue; thence Northeasterly on and along said Northwesterly line of said new street 61.71 feet; thence North 41° 18' West 100.7 feet to the Northwesterly boundary line of the parcel conveyed to George W. Gates as aforesaid; thence South 48° 30' West along said boundary line 61.45 feet to the point of beginning. Being a portion of the said one acre tract described in the Deed aforesaid.

93-004529

Deed Exhibit 3

Order No.
Escrow No.
Loan No.

WHEN RECORDED MAIL TO:

W.J. Britton & Co.
1811 El Camino Real
Burlingame, CA 94010

OFFICIAL RECORDS OF SAN MATEO COUNTY
ASSESSOR-COUNTY CLERK-RECORDER
WARREN SLOCUM

Recorded at Request of
WJ BRITTON & CO

98-024606 02/25/98 02:05

Recording Fee: 8 SMAME

MAIL TAX STATEMENTS TO

W.J. Britton & Co.
1811 El Camino Real
Burlingame, CA 94010

SPACE ABOVE THIS LINE FOR RECORDER'S USE

DOCUMENTARY TRANSFER TAX $ -0-

Computed on the consideration or value of property conveyed OR

Computed on the consideration or value less liens or encumbrances remaining at time of sale

Signature of Declarant or Agent determining tax Firm Name

GRANT DEED

FOR A VALUABLE CONSIDERATION, receipt of which is hereby acknowledged,

Patricia Ann Britton

hereby GRANT(S) to

Patricia Ann Britton as Trustee of the Patricia Ann Britton Revocable Intervivos Trust dated August 15, 1997

the real property in the City of Burlingame
County of San Mateo, State of California, described as

1220 Donnelly Avenue, Burlingame, CA

A.P. No. 029-151-170 See legal description attached

Dated December 10, 1997

Patricia Ann Britton

STATE OF CALIFORNIA }
COUNTY OF San Mateo } ss

On December 10, 1997 before me,
Sonja C. Zamora,
personally appeared Patricia Ann Britton,

personally known to me (or proved to me on the basis of satisfactory evidence) to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s) or the entity upon behalf of which the person(s) acted, executed the instrument.

WITNESS my hand and official seal.

Signature

SONJA C. ZAMORA
Comm. # 1133687
NOTARY PUBLIC-CALIFORNIA
San Mateo County
My Comm. Expires April 13, 2001

(This area for official notarial seal)

MAIL TAX STATEMENTS AS DIRECTED ABOVE

1002 (1-94)

LEGAL DESRIPTION

1220 Donnelly Avenue

ASSESSOR"S PARCEL NO.: 029-151-170

Parcel Two:

COMMENCING at a point on the Southeasterly line of Block 3, as same is shown on the map entitled "MAP NO. 2 OF THE PROPERTY OF THE BURLINGAME LAND CO., SAN MATEO CO., CAL., which map was filed in the office of the Recorder of the County of San Mateo, State of California, on February 20, 1905 in Book "D" of Maps at page 38, and a copy entered in Book 3 of Maps at page 55, distant Southwesterly thereon 296 feet 1 inch from the Southwesterly line of Main Street; thence Southeasterly and parallel with the Southerly line of that certain parcel of land conveyed by George W. Gates to Estelle M. Gates, his wife, by Deed dated May 10, 1905 and recorded May 12, 1905 in Book 117 of Deeds at Page 64, Records of San Mateo County, 109 feet to a point in the Northwesterly boundary of that certain strip of land conveyed by Carrie D. Donnelly et al, to the City of Burlingme by Deed dated August 1, 1917 and recorded April 26, 1919, in Book 278 of Deeds at Page 426, Records of San Mateo County, said strip being commonly known as Donnelly Avenue; thence Southwesterly along said line of Donnelly Avenue, 41 feet 6 inches, more or less, to the Northeasterly boundary line of that certain parcel of land conveyed by Carrie D. Donnelly et al, to Martha M. Kraft, by Deed dated March 25, 1922 and recorded March 30, 1922 in Book 33 of Official Records of San Mateo County at page 337; thence Northwesterly along said Northeasterly boundary line of lands so conveyed to Kraft, 112.80 feet, more or less, to the Southeasterly boundary line of said Block 3; thence Northeasterly along said Southeasterly boundary line of Block 3, 41 feet 6 inches to the point of commencement

APN 029-151-170 JPN 029-015-151-17

Appendix 9 – Property Tax Map Report

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.6
August 01, 2016

The EDR Property Tax Map Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.


Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



- Site Location


TAX CODE AREA
29-15
BELLEVUE AVE.
CALIFORNIA DRIVE (SAN MATEO DRIVE)
CHAPIN AVE.
ROAD
DONNELLY AVE.
PRIMROSE
LORTON (MAIN ST.)
AVE.
BURLINGAME AVE.
PARK ROAD
HATCH LN
151
152
153
BURLINGAME LAND CO. NO. 2 PTN. OF R.S.M. D/38
CITY OF BURLINGAME
S.F. ASSESSOR'S MAP COUNTY OF SAN MATEO CALIF.
11-19-76


TAX CODE AREA
29-15
BELLEVUE AVE.
CALIFORNIA DRIVE (SAN MATEO DRIVE)
CHAPIN AVE.
ROAD
DONNELLY AVE.
PRIMROSE
LORTON AVE. (MAIN ST.)
BURLINGAME AVE.
PARK ROAD
HATCH LN
151
152
153
SEE BK. 108 32
SEE BK. 108 50
BLK 2
BLK 275
1" = 100'
S.F. ASSESSOR'S MAP COUNTY OF SAN MATEO CALIF.
BURLINGAME LAND CO. NO. 2 PTN. OF R.S.M. D/38
CITY OF BURLINGAME
11-19-76

Appendix 10 – Building Permits

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.8
August 01, 2016

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Building Permit Report: Search Documentation

8/01/16

Site Name:
Donnelly
1214 Donnelly
Burlingame, CA 94010

EDR Inquiry # 4688986.8

Client Name:
Protech Consulting &
1208 Main Street
Redwood City, CA 94063

Contact: Woody Lovejoy

Search Documentation

DATA GAP

The complete collection of Building Permit data available to EDR has been searched, and as of 8/01/16, EDR does not have access to building permits in the city where your target property is located (Burlingame, CA).

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED ORIMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THEMAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALLRISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OFERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL,INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLYLIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risklevels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providingany facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by anenvironmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to beconstrued as legal advice.

Copyright 2011 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

ASTM and EPA Requirements

ASTM E 1527-13 lists building department records as a "standard historical source," as detailed in § 8.3.4.7: "Building Department Records - The term building department records means those records of the local government in which the property is located indicating permission of the local government to construct, alter, or demolish improvements on the property." ASTM also states that "Uses in the area surrounding the property shall be identified in the report, but this task is required only to the extent that this information is revealed in the course of researching the property itself."

EPA's Standards and Practices for All Appropriate Inquires (AAI) states: "§312.24: Reviews of historical sources of information. (a) Historical documents and records must be reviewed for the purposes of achieving the objectives and performance factors of §312.20(e) and (f). Historical documents and records may include, but are not limited to, aerial photographs, fire insurance maps, building department records, chain of title documents, and land use records."

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX® PROPERTY HISTORY

Appendix 11 – Vapor Encroachment Screen Report

Donnelly
1214 Donnelly
Burlingame, CA 94010

Inquiry Number: 4688986.9s
August 16, 2016

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Aerial Photography	**4**
Map Findings	**5**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Maximum Search Distance*	Summary: property	1/10	1/10 - 1/3
Federal NPL	0.333	0	0	0
Federal CERCLIS	0.333	0	0	0
Federal RCRA CORRACTS facilities list	0.333	0	0	0
Federal RCRA TSD facilities list	0.333	0	0	0
Federal RCRA generators list	property	0	-	-
Federal institutional controls / engineering controls registries	0.333	0	0	0
Federal ERNS list	property	0	-	-
State and tribal - equivalent NPL	0.333	0	0	0
State and tribal - equivalent CERCLIS	0.333	0	0	1
State and tribal landfill / solid waste disposal	0.333	0	0	0
State and tribal leaking storage tank lists	0.333	0	6	27
State and tribal registered storage tank lists	property	0	-	-
State and tribal institutional control / engineering control registries	not searched	-	-	-
State and tribal voluntary cleanup sites	0.333	0	0	0
State and tribal Brownfields sites	0.333	0	0	0
Other Standard Environmental Records	0.333	1	16	68

HISTORICAL USE RECORDS				
Former manufactured Gas Plants	0.333	0	0	0
Historical Gas Stations	0.125	0	0	0
Historical Dry Cleaners	0.125	0	3	0
Exclusive Recovered Govt. Archives	property	0	-	-

*Each category may include several separate databases, each having a different search distance. For each category, the table reports the maximum search distance applied. See the section 'Record Sources and Currency' for information on individual databases.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

DONNELLY
1214 DONNELLY
BURLINGAME, CA 94010

COORDINATES

Latitude (North):	37.579506 - 37° 34′ 46.221313″
Longitude (West):	122.347789 - 122° 20′ 52.02942″
Elevation:	32 ft. above sea level

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records.

Site	Database(s)
JOHN BRITTON 1218 DONNELLY AVE BURLINGAME, CA 94010	HAZNET GEPAID: CAC002779641

EXECUTIVE SUMMARY

PHYSICAL SETTING INFORMATION

Flood Zone:	Available
NWI Wetlands:	Available

AQUIFLOW®

Search Radius: 0.333 Mile.

Map ID Direction Distance Elevation			Database	EDR ID Number
1 **ESE** **< 1/10 mile** **Higher** (GI)	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660081 Not Reported Not Reported Not Reported 14 08/12/1997	**AQUIFLOW**	**55534**
2 **ESE** **1/10 - 1/3 mile** **Higher** (GI)	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660060 E, Flat 23 22 Not Reported 02/04/1998	**AQUIFLOW**	**55439**
A3 **NW** **1/10 - 1/3 mile** **Lower** (GI)	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660017 Not Reported 13.5 12.5 Not Reported 02/22/1990	**AQUIFLOW**	**55454**
4 **SW** **1/10 - 1/3 mile** **Higher** ↑	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660023 N 19.5 12.5 Not Reported 06/26/1992	**AQUIFLOW**	**55503**
A6 **NW** **1/10 - 1/3 mile** **Lower** ↖	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660006 NNW 11.0 9.0 Not Reported 07/24/1997	**AQUIFLOW**	**55456**

EXECUTIVE SUMMARY

Map ID Direction Distance Elevation			Database	EDR ID Number
7 **NW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660061 N 7.60 3.85 Not Reported 05/12/1995	**AQUIFLOW**	**55459**
8 **WNW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660042 Not Reported 17 12.5 Not Reported 10/05/1990	**AQUIFLOW**	**55547**
1G **NW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660006 NNW 11.0 9.0 Not Reported 07/24/1997	**AQUIFLOW**	**55456**
2G **NW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660061 N 7.60 3.85 Not Reported 05/12/1995	**AQUIFLOW**	**55459**
3G **NW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660017 Not Reported 13.5 12.5 Not Reported 02/22/1990	**AQUIFLOW**	**55454**
4G **WNW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660042 Not Reported 17 12.5 Not Reported 10/05/1990	**AQUIFLOW**	**55547**
5G **ESE** **< 1/10 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660081 Not Reported Not Reported Not Reported 14 08/12/1997	**AQUIFLOW**	**55534**

EXECUTIVE SUMMARY

Map ID Direction Distance Elevation			Database	EDR ID Number
6G (GI) **ESE** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660060 E, Flat 23 22 Not Reported 02/04/1998	**AQUIFLOW**	**55439**
7G **SW** **1/10 - 1/3 mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	660023 N 19.5 12.5 Not Reported 06/26/1992	**AQUIFLOW**	**55503**

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	Not Reported	Not reported	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 2

Soil Component Name: Urban land

Soil Surface Texture:

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	Not Reported	Not reported	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 3

Soil Component Name: Orthents

Soil Surface Texture: variable

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

EXECUTIVE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	59 inches	variable	Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 4

Soil Component Name: Orthents

Soil Surface Texture:

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	59 inches	Not Reported	Not reported	Not reported	Max: Min:	Max: Min:

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
JOHN BRITTON HAZNET: Other Standard Environmental Records	1218 DONNELLY AVE	Property	▲ A1	19
MIKES AUTOMOTIVE SERVICE San Mateo Co. BI: Other Standard Environmental Records	1212 DONNELLY	<1/10 ENE	▲ A2	20
LORTON PLACE OWNERS ASSOCIATION LUST: State and tribal leaking storage tank lists	345 LORTON AVENUE	<1/10 N	▼ A3	21
KIRKBRIDE PROPERTY LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	307 LORTON	<1/10 E	▲ B4	24
KIRKBRIDE PROPERTY LUST: State and tribal leaking storage tank lists	307 LORTON	<1/10 E	▲ B5	26
COMMERCIAL BUILDING San Mateo Co. BI: Other Standard Environmental Records	307 LORTON	<1/10 E	▲ B6	27
SABATINI TRUST LUST: State and tribal leaking storage tank lists	361 CALIFORNIA	<1/10 NE	▼ C7	28
DON SABATINI LUST: State and tribal leaking storage tank lists HAZNET: Other Standard Environmental Records	361 CALIFORNIA DR	<1/10 NE	▼ C8	30
UST SITE San Mateo Co. BI: Other Standard Environmental Records	361 CALIFORNIA	<1/10 NE	▼ C9	32
UST SITE San Mateo Co. BI: Other Standard Environmental Records	361 CALIFORNIA	<1/10 NE	▼ C10	33
UST SITE San Mateo Co. BI: Other Standard Environmental Records	401 CALIFORNIA	<1/10 N	▼ D11	34
KIM MILLS TEXACO (FORMER) LUST: State and tribal leaking storage tank lists	401 CALIFORNIA	<1/10 N	▼ D12	35
UST SITE San Mateo Co. BI: Other Standard Environmental Records	401 CALIFORNIA	<1/10 N	▼ D13	37
REDLICH JR, CHRISTOPHER San Mateo Co. BI: Other Standard Environmental Records	360 PRIMROSE	<1/10 WSW	▲ E14	38

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
VERIZON WIRELESS EL CAMINO HOWARD San Mateo Co. BI: Other Standard Environmental Records	Not Reported	<1/10 SSW	▲ E16	40
AUTAR JOHAL PROPERTY San Mateo Co. BI: Other Standard Environmental Records	1301 BURLINGAME	<1/10 SSE	▲ F17	41
PRIMROSE CLEANERS San Mateo Co. BI: Other Standard Environmental Records	339 PRIMROSE	<1/10 SSW	▲ E19	43
PRIMROSE CLEANERS DRYCLEANERS: Other Standard Environmental Records	339 PRIMROSE RD	<1/10 SSW	▲ E20	44
SEPHORA #052 San Mateo Co. BI: Other Standard Environmental Records	1205 BURLINGAME	<1/10 ESE	▲ B22	46
PICKRELL D J SEMS-ARCHIVE: Other Standard Environmental Records	1408 CHAPIN AVE	<1/10 WSW	▲ E23	47
88 PHOTO LAB San Mateo Co. BI: Other Standard Environmental Records	1109 BURLINGAME	<1/10 E	▲ B24	49
CRYO CREAM San Mateo Co. BI: Other Standard Environmental Records	240 PARK	1/10 - 1/3 SE	▲ F25	50
CTY OF SAN MATEO San Mateo Co. BI: Other Standard Environmental Records HAZNET: Other Standard Environmental Records	501 PRIMROSE RD	1/10 - 1/3 W	▼ 26	51
BURLINGAME HIGH SCHOOL DEED: Other Standard Environmental Records SCH: Other Standard Environmental Records ENVIROSTOR: State and tribal - equivalent CERCLIS	400 CAROLAN AVENUE	1/10 - 1/3 NNE	▼ 27	52
US POSTAL SERVICE LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	220 PARK	1/10 - 1/3 SE	▲ G28	83
BURLINGAME POST OFFICE LUST: State and tribal leaking storage tank lists	220 PARK	1/10 - 1/3 SE	▲ G29	84
NEXTEL-SITE ID CA-0323 San Mateo Co. BI: Other Standard Environmental Records	1420 BURLINGAME	1/10 - 1/3 SSW	▲ H30	86
SPRINT NEXTEL CELL SITE FS04XC321 San Mateo Co. BI: Other Standard Environmental Records	1420 BURLINGAME	1/10 - 1/3 SSW	▲ H31	87
UST SITE - FORMER FOX PENINSULA THEATER San Mateo Co. BI: Other Standard Environmental Records	1417-15 BURLINGAME	1/10 - 1/3 SSW	▲ H32	88
BURLINGAME ONE HOUR CLEANERS	507 CALIFORNIA	1/10 - 1/3 NNW	▼ I33	89

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
San Mateo Co. BI: Other Standard Environmental Records DRYCLEANERS: Other Standard Environmental Records				
BURLINGAME ONE HOUR CLEANERS DRYCLEANERS: Other Standard Environmental Records	507 CALIFORNIA DR	1/10 - 1/3 NNW	▼ I34	90
BURLINGAME ONE HOUR CLEANERS San Mateo Co. BI: Other Standard Environmental Records	507 CALIFORNIA	1/10 - 1/3 NNW	▼ I35	91
G&C AUTO BODY San Mateo Co. BI: Other Standard Environmental Records	251 CALIFORNIA	1/10 - 1/3 E	▲ J36	92
GERMAN CAR CARE San Mateo Co. BI: Other Standard Environmental Records	251 CALIFORNIA	1/10 - 1/3 E	▲ J37	93
BURLINGAME HIGH SCHOOL San Mateo Co. BI: Other Standard Environmental Records	1 MANGINI	1/10 - 1/3 NNW	▼ 38	94
BB STERN COMPANY San Mateo Co. BI: Other Standard Environmental Records	222 CALIFORNIA	1/10 - 1/3 E	▲ J39	95
STERLING CLEANERS (FORMER) LUST: State and tribal leaking storage tank lists	215 CALIFORNIA DRIVE	1/10 - 1/3 ESE	▲ J40	96
UST SITE San Mateo Co. BI: Other Standard Environmental Records SLIC: State and tribal leaking storage tank lists	215 CALIFORNIA	1/10 - 1/3 ESE	▲ J41	101
FEDERAL AUTO PARTS San Mateo Co. BI: Other Standard Environmental Records	231 CALIFORNIA	1/10 - 1/3 E	▲ J42	102
PANDA EXPRESS #907 San Mateo Co. BI: Other Standard Environmental Records	1453 BURLINGAME	1/10 - 1/3 SSW	▲ K43	103
UST SITE San Mateo Co. BI: Other Standard Environmental Records	1290 HOWARD	1/10 - 1/3 SE	▲ L44	104
TUCKER TRANSMISSIONS San Mateo Co. BI: Other Standard Environmental Records	215 HATCH	1/10 - 1/3 ESE	▲ M45	105
THE ARLINGTON APARTMENTS LUST: State and tribal leaking storage tank lists HAZNET: Other Standard Environmental Records	1401 FLORIBUNDA AVE	1/10 - 1/3 W	▼ N46	106
ARLINGTON APARTMENTS LUST: State and tribal leaking storage tank lists San Mateo Co. BI: Other Standard Environmental Records	1401 FLORIBUNDA	1/10 - 1/3 W	▼ N47	107
UST SITE San Mateo Co. BI: Other Standard Environmental Records	200 PARK	1/10 - 1/3 SE	▲ L48	109

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
200 PARK LUST: State and tribal leaking storage tank lists	200 PARK ROAD	1/10 - 1/3 SE	▲ L49	110
HARRIS PROPERTY LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	1234 HOWARD	1/10 - 1/3 SE	▲ L50	113
KING YEE PROPERTY LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	1200 HOWARD	1/10 - 1/3 SE	▲ L51	121
BERENSTEIN ASSOC. PROPERTY LUST: State and tribal leaking storage tank lists SLIC: State and tribal leaking storage tank lists HAZNET: Other Standard Environmental Records	1319 HOWARD	1/10 - 1/3 SSE	▲ L52	131
CAINE CLEANERS DRYCLEANERS: Other Standard Environmental Records	1321 HOWARD	1/10 - 1/3 SSE	▲ L53	133
CAINE CLEANERS San Mateo Co. BI: Other Standard Environmental Records	1321 HOWARD	1/10 - 1/3 SSE	▲ L54	134
STERLING CLEANERS LUST: State and tribal leaking storage tank lists San Mateo Co. BI: Other Standard Environmental Records SLIC: State and tribal leaking storage tank lists	1140 HOWARD AVENUE	1/10 - 1/3 ESE	▲ M55	135
STERLING CLEANERS ECHO: Other Standard Environmental Records FINDS: Other Standard Environmental Records RCRA-SQG: Federal RCRA generators list HAZNET: Other Standard Environmental Records DRYCLEANERS: Other Standard Environmental Records	1140 HOWARD AVE	1/10 - 1/3 ESE	▲ M56	137
BURLINGAME VALERO San Mateo Co. BI: Other Standard Environmental Records	601 CALIFORNIA	1/10 - 1/3 NW	▼ O57	142
SHELL LUST: State and tribal leaking storage tank lists San Mateo Co. BI: Other Standard Environmental Records	601 CALIFORNIA	1/10 - 1/3 NW	▼ O58	143
SHELL LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	601 CALIFORNIA	1/10 - 1/3 NW	▼ O59	145
PACIFIC BELL FINDS: Other Standard Environmental Records RCRA-SQG: Federal RCRA generators list ECHO: Other Standard Environmental Records LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records San Mateo Co. BI: Other Standard Environmental Records	1480 BURLINGAME AVENUE	1/10 - 1/3 SSW	▲ K60	147
PACIFIC BELL	1480 BURLINGAME AVE.	1/10 - 1/3 SSW	▲ K61	151

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
UST: State and tribal registered storage tank lists SWEEPS UST: State and tribal registered storage tank lists LUST: State and tribal leaking storage tank lists HIST UST: State and tribal registered storage tank lists				
T MOBILE WEST CORP SITE ID SF03108A San Mateo Co. BI: Other Standard Environmental Records	1480 BURLINGAME	1/10 - 1/3 SSW	▲ K62	155
AT & T MOBILITY - CENTRAL BG #13300 San Mateo Co. BI: Other Standard Environmental Records	1480 BURLINGAME	1/10 - 1/3 SSW	▲ K63	156
SBC San Mateo Co. BI: Other Standard Environmental Records	1480 BURLINGAME	1/10 - 1/3 SSW	▲ K64	157
UST SITE San Mateo Co. BI: Other Standard Environmental Records	1021 BURLINGAME	1/10 - 1/3 ENE	▼ P65	158
WALGREENS #86 San Mateo Co. BI: Other Standard Environmental Records	1420 HOWARD	1/10 - 1/3 S	▲ Q66	159
BURLINGAME DIAGNOSTIC CTR San Mateo Co. BI: Other Standard Environmental Records	270 EAST	1/10 - 1/3 E	▼ P67	160
SILVER AUTO SVC San Mateo Co. BI: Other Standard Environmental Records	270 EAST	1/10 - 1/3 E	▼ P68	161
D&R AUTO BODY & PAINT San Mateo Co. BI: Other Standard Environmental Records	270 EAST	1/10 - 1/3 E	▼ P69	162
UST SITE San Mateo Co. BI: Other Standard Environmental Records	1100 HOWARD	1/10 - 1/3 ESE	▲ M70	163
SHELL LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	1490 BURLINGAME	1/10 - 1/3 SSW	▲ K71	164
SHELL LUST: State and tribal leaking storage tank lists	1490 BURLINGAME	1/10 - 1/3 SSW	▲ K72	166
SHELL SERVICE STATION San Mateo Co. BI: Other Standard Environmental Records	1490 BURLINGAME	1/10 - 1/3 SSW	▲ K73	167
UST SITE San Mateo Co. BI: Other Standard Environmental Records	1101-07 HOWARD	1/10 - 1/3 ESE	▲ M74	168
FOUR CAR GARAGE INC San Mateo Co. BI: Other Standard Environmental Records	609 CALIFORNIA	1/10 - 1/3 NW	▼ O75	169
SAFEWAY 1547 San Mateo Co. BI: Other Standard Environmental Records	1450 HOWARD	1/10 - 1/3 S	▲ Q76	170

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
RUPPELS AUTO FIXATION San Mateo Co. BI: Other Standard Environmental Records	260 EAST	1/10 - 1/3 E	▼ R77	171
RUPPELS AUTO FIXATION San Mateo Co. BI: Other Standard Environmental Records	260 EAST	1/10 - 1/3 E	▼ R78	172
CHEVRON 9-0571 LUST: State and tribal leaking storage tank lists	260 EL CAMINO REAL	1/10 - 1/3 SSW	▲ S79	173
CURRIES CHEVRON STATION San Mateo Co. BI: Other Standard Environmental Records	260 EL CAMINO REAL	1/10 - 1/3 SSW	▲ S80	174
WALGREENS #12257 San Mateo Co. BI: Other Standard Environmental Records	260 EL CAMINO REAL	1/10 - 1/3 SSW	▲ S81	175
90571 LUST: State and tribal leaking storage tank lists HIST UST: State and tribal registered storage tank lists	260 EL CAMINO REAL	1/10 - 1/3 SSW	▲ S82	176
CHEVRON HIST CORTESE: Other Standard Environmental Records	260 EL CAMINO REAL	1/10 - 1/3 SSW	▲ S83	189
MIKE HARVEY HONDA San Mateo Co. BI: Other Standard Environmental Records	200 CALIFORNIA	1/10 - 1/3 E	▲ T84	190
MIKE HARVEY HONDA San Mateo Co. BI: Other Standard Environmental Records	200 CALIFORNIA	1/10 - 1/3 E	▲ T85	191
PUTNAM CHEVROLET CADILLAC San Mateo Co. BI: Other Standard Environmental Records	198 CALIFORNIA	1/10 - 1/3 E	▲ T86	192
ARATA PROPERTY LUST: State and tribal leaking storage tank lists	198 CALIFORNIA	1/10 - 1/3 E	▲ T87	193
PUTNAM CHEVROLET CADILLAC FINDS: Other Standard Environmental Records RCRA-SQG: Federal RCRA generators list ECHO: Other Standard Environmental Records LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	198 CALIFORNIA DR	1/10 - 1/3 E	▲ T88	194
SATURN DEVELOPMENT NORTH, LLC San Mateo Co. BI: Other Standard Environmental Records	198 CALIFORNIA	1/10 - 1/3 E	▲ T89	198
CALIFORNIA DRIVE AUTO SERVICE San Mateo Co. BI: Other Standard Environmental Records	621 CALIFORNIA	1/10 - 1/3 NW	▼ U90	199
AUTO TIGER San Mateo Co. BI: Other Standard Environmental Records	621 CALIFORNIA	1/10 - 1/3 NW	▼ U91	200


EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
BURLINGAME PRIME MOTORZ San Mateo Co. BI: Other Standard Environmental Records	621 CALIFORNIA	1/10 - 1/3 NW	▼ U92	201
PENINSULA PRIME MOTORZ LLC San Mateo Co. BI: Other Standard Environmental Records	621 CALIFORNIA	1/10 - 1/3 NW	▼ U93	202
T MOBILE SITE ID SF53613A San Mateo Co. BI: Other Standard Environmental Records	850 BURLINGAME	1/10 - 1/3 NE	▼ 94	203
CHEVRON, FORMER/EAGLE GAS STA LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	177 CALIFORNIA	1/10 - 1/3 ESE	▲ T95	204
EAGLE CAR WASH & FILL San Mateo Co. BI: Other Standard Environmental Records	177 CALIFORNIA	1/10 - 1/3 ESE	▲ T96	208
CHEVRON, FORMER/EAGLE GAS STA LUST: State and tribal leaking storage tank lists	177 CALIFORNIA	1/10 - 1/3 ESE	▲ T97	209
ALL MAKES AUTO BODY San Mateo Co. BI: Other Standard Environmental Records	257 MYRTLE	1/10 - 1/3 ENE	▼ P98	210
W. J. BRITTON COMPANY LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	701 CALIFORNIA	1/10 - 1/3 NW	▼ U99	211
DEITER BLUHM LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	1285 OAK GROVE	1/10 - 1/3 WNW	▼ 100	214
FLOYD'S AUTOMOTIVE LUST: State and tribal leaking storage tank lists	741 SAN MATEO	1/10 - 1/3 NW	▼ V101	217
FLOYDS AUTOMOTIVE SWEEPS UST: State and tribal registered storage tank lists LUST: State and tribal leaking storage tank lists HIST CORTESE: Other Standard Environmental Records	741 SAN MATEO AVE	1/10 - 1/3 NW	▼ V102	218

HISTORICAL USE RECORDS

Name	Address	Dist/Dir	Map ID	Page
345 CALIFORNIA DR EDR Hist Cleaner: Historical Dry Cleaners	345 CALIFORNIA DR	<1/10 NE	▼ C15	39
339 PRIMROSE RD EDR Hist Cleaner: Historical Dry Cleaners	339 PRIMROSE RD	<1/10 SSW	▲ E18	42
337 PRIMROSE RD EDR Hist Cleaner: Historical Dry Cleaners	337 PRIMROSE RD	<1/10 SSW	▲ E21	45


PRIMARY MAP - 4688986.9S



SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
LAT/LONG:	37.579506 / 122.347789	INQUIRY #:	4688986.9s
		DATE:	August 02, 2016 9:22 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 4688986.9S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Contour Lines
- Power transmission lines
- Pipelines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands
- Upgradient Area
- Areas of Concern

SITE NAME: Donnelly	CLIENT: Protech Consulting & Engineer.
ADDRESS: 1214 Donnelly Burlingame CA 94010	CONTACT: Woody Lovejoy
LAT/LONG: 37.579506 / 122.347789	INQUIRY #: 4688986.9s DATE: August 02, 2016 9:21 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

AERIAL PHOTOGRAPHY - 4688986.9s



SITE NAME:	Donnelly	CLIENT:	Protech Consulting & Engineer.
ADDRESS:	1214 Donnelly Burlingame CA 94010	CONTACT:	Woody Lovejoy
LAT/LONG:	37.579506 / 122.347789	INQUIRY #:	4688986.9s
		DATE:	August 02, 2016 9:23 am

Copyright © 2016 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**		EDR SITE ID NUMBER
▼ MAP ID#	Direction Distance Range (Distance feet / miles) Relative Elevation Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:
Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

JOHN BRITTON 1218 DONNELLY AVE, BURLINGAME, CA, 94010		S118217302
▲ A1	Target Property 32 ft. Above Sea Level	Other Standard Environmental Records

Worksheet:

Impact on Target Property: VEC does not exist

HAZNET: Other Standard Environmental Records

envid:	S118217302
Year:	2014
GEPAID:	CAC002779641
Contact:	JOHN BRITTON
Telephone:	4159341151
Mailing Name:	Not Reported
Mailing Address:	1218 DONNELLY AVE
Mailing City,St,Zip:	BURLINGAME, CA 94010
Gen County:	San Mateo
TSD EPA ID:	CAD981382732
TSD County:	Alameda
Waste Category:	Asbestos containing waste
Disposal Method:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.4
Cat Decode:	Asbestos containing waste
Method Decode:	Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Facility County:	San Mateo

MIKES AUTOMOTIVE SERVICE 1212 DONNELLY, BURLINGAME, CA, 94010			S113756632
▲ A2	ENE <1/10	(114 ft. / 0.022 mi.)	Other Standard Environmental Records
	Equal Elevation	32 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018039
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011855
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018039
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004635
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

LORTON PLACE OWNERS ASSOCIATION 345 LORTON AVENUE, BURLINGAME, CA, 94010			S113804525
▼ A3	N <1/10	(130 ft. / 0.025 mi.)	State and tribal leaking storage tank lists
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000004932
Latitude:	37.5801979256519
Longitude:	-122.347689136246
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/22/2013
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
LOC Case Number:	660111
File Location:	Not Reported
Potential Media Affect:	Aquifer used for drinking water supply, Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Diesel, Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000004932

Contact:

Global Id:	T10000004932
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T10000004932
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

LORTON PLACE OWNERS ASSOCIATION, 345 LORTON AVENUE, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T10000004932
Status:	Completed - Case Closed
Status Date:	10/22/2013
Global Id:	T10000004932
Status:	Open - Case Begin Date
Status Date:	02/16/2013
Global Id:	T10000004932
Status:	Open - Eligible for Closure
Status Date:	07/23/2013
Global Id:	T10000004932
Status:	Open - Site Assessment
Status Date:	07/11/2013

Regulatory Activities:

Global Id:	T10000004932
Action Type:	ENFORCEMENT
Date:	10/22/2013
Action:	Closure/No Further Action Letter - #20131022
Global Id:	T10000004932
Action Type:	ENFORCEMENT
Date:	08/07/2013
Action:	Notification - Public Notice of Case Closure - #20130807
Global Id:	T10000004932
Action Type:	RESPONSE
Date:	05/08/2013
Action:	Site Assessment Report
Global Id:	T10000004932
Action Type:	ENFORCEMENT
Date:	07/19/2013
Action:	Notice of Responsibility - #20130719
Global Id:	T10000004932
Action Type:	Other
Date:	02/16/2013
Action:	Leak Discovery
Global Id:	T10000004932
Action Type:	Other
Date:	03/21/2013
Action:	Leak Reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660111

LORTON PLACE OWNERS ASSOCIATION, 345 LORTON AVENUE, BURLINGAME, CA 94010 (Continued)

Facility Status:	9- Case Closed
Global ID:	Not Reported
APN Number:	MULTIPLE APNS
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

KIRKBRIDE PROPERTY 307 LORTON, BURLINGAME, CA, 94010		S103171184	
▲ B4	E <1/10	(308 ft. / 0.058 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100953
Latitude:	37.5794701
Longitude:	-122.346454
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/09/1997
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1040
LOC Case Number:	660081
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100953

Contact:

Global Id:	T0608100953
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100953
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO

KIRKBRIDE PROPERTY, 307 LORTON, BURLINGAME, CA 94010 (Continued)

Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100953
Status:	Completed - Case Closed
Status Date:	12/09/1997
Global Id:	T0608100953
Status:	Open - Case Begin Date
Status Date:	06/20/1997

Regulatory Activities:

Global Id:	T0608100953
Action Type:	ENFORCEMENT
Date:	06/20/1997
Action:	Notice of Responsibility - #1
Global Id:	T0608100953
Action Type:	Other
Date:	06/03/1997
Action:	Leak Discovery
Global Id:	T0608100953
Action Type:	Other
Date:	06/23/1997
Action:	Leak Reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660081
Facility Status:	9- Case Closed
Global ID:	T0608100953
APN Number:	029152110
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records 

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-1040

MAP FINDINGS

KIRKBRIDE PROPERTY 307 LORTON, BURLINGAME, CA, 94010			S104493529
▲ B5	E <1/10	(308 ft. / 0.058 mi.)	State and tribal leaking storage tank lists
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660081
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

COMMERCIAL BUILDING 307 LORTON, BURLINGAME, CA, 94010			S113757130
▲ B6	E <1/10	(308 ft. / 0.058 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0024376
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0029020
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

SABATINI TRUST 361 CALIFORNIA, BURLINGAME, CA, 94010			S103960987
▼ C7	NE <1/10	(310 ft. / 0.059 mi.)	State and tribal leaking storage tank lists
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000004188
Latitude:	37.5802678
Longitude:	-122.3470527
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/01/2012
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
LOC Case Number:	660110
File Location:	Not Reported
Potential Media Affect:	Not Reported
Potential Contaminants of Concern:	Diesel
Site History:	Site to be opened and closed
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000004188

Contact:

Global Id:	T10000004188
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T10000004188
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

SABATINI TRUST, 361 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T10000004188
Status:	Completed - Case Closed
Status Date:	08/01/2012
Global Id:	T10000004188
Status:	Open - Case Begin Date
Status Date:	06/13/2012
Global Id:	T10000004188
Status:	Open - Verification Monitoring
Status Date:	07/26/2012

Regulatory Activities:

Global Id:	T10000004188
Action Type:	ENFORCEMENT
Date:	07/25/2012
Action:	Notice of Responsibility - #20120725
Global Id:	T10000004188
Action Type:	Other
Date:	06/13/2012
Action:	Leak Discovery
Global Id:	T10000004188
Action Type:	Other
Date:	06/28/2012
Action:	Leak Reported
Global Id:	T10000004188
Action Type:	ENFORCEMENT
Date:	08/01/2012
Action:	Closure/No Further Action Letter - #20120801

DON SABATINI 361 CALIFORNIA DR, BURLINGAME, CA, 940100000			S112871639
▼ C8	NE <1/10	(310 ft. / 0.059 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

SAN MATEO CO. LUST: State and tribal leaking storage tank lists

Region:	SAN MATEO
Facility ID:	660110
Facility Status:	9- Case Closed
Global ID:	Not Reported
APN Number:	029153010
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HAZNET: Other Standard Environmental Records

envid:	S112871639
Year:	1999
GEPAID:	CAC001172856
Contact:	DON SABATINI
Telephone:	6506855666
Mailing Name:	Not Reported
Mailing Address:	300 EL PORTEL
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not Reported
TSD EPA ID:	CAD009466392
TSD County:	Not Reported
Waste Category:	Other empty containers 30 gallons or more
Disposal Method:	Recycler
Tons:	.7500
Cat Decode:	Other empty containers 30 gallons or more
Method Decode:	Recycler
Facility County:	San Mateo

envid:	S112871639
Year:	1999
GEPAID:	CAC001172856
Contact:	DON SABATINI
Telephone:	6506855666
Mailing Name:	Not Reported
Mailing Address:	300 EL PORTEL
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not Reported

DON SABATINI, 361 CALIFORNIA DR, BURLINGAME, CA 940100000 (Continued)

TSD EPA ID:	CAD980887418
TSD County:	Not Reported
Waste Category:	Not Reported
Disposal Method:	Not Reported
Tons:	3.3360
Cat Decode:	Not Reported
Method Decode:	Not Reported
Facility County:	San Mateo
envid:	S112871639
Year:	1998
GEPAID:	CAC001172856
Contact:	DON SABATINI
Telephone:	6506855666
Mailing Name:	Not Reported
Mailing Address:	300 EL PORTEL
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not Reported
TSD EPA ID:	CAL000180993
TSD County:	Not Reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Not Reported
Tons:	.9591
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Not Reported
Facility County:	San Mateo
envid:	S112871639
Year:	1998
GEPAID:	CAC001172856
Contact:	DON SABATINI
Telephone:	6506855666
Mailing Name:	Not Reported
Mailing Address:	300 EL PORTEL
Mailing City,St,Zip:	HILLSBOROUGH, CA 940100000
Gen County:	Not Reported
TSD EPA ID:	CAD088838222
TSD County:	Not Reported
Waste Category:	Unspecified oil-containing waste
Disposal Method:	Recycler
Tons:	.9591
Cat Decode:	Unspecified oil-containing waste
Method Decode:	Recycler
Facility County:	San Mateo

UST SITE 361 CALIFORNIA, BURLINGAME, CA, 94010			S113759048
▼ C9	NE <1/10	(374 ft. / 0.071 mi.)	Other Standard Environmental Records
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0051675
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0071628
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

UST SITE 361 CALIFORNIA, BURLINGAME, CA, 94010			S113757182
▼ C10	NE <1/10	(374 ft. / 0.071 mi.)	Other Standard Environmental Records
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0024618
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0029446
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

UST SITE 401 CALIFORNIA, BURLINGAME, CA, 94010			S113759022
▼ D11	N <1/10	(386 ft. / 0.073 mi.)	Other Standard Environmental Records
	3 ft. Lower Elevation	29 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0051084
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0070860
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

KIM MILLS TEXACO (FORMER) 401 CALIFORNIA, BURLINGAME, CA, 94010			S111711481
▼ D12	N <1/10	(386 ft. / 0.073 mi.)	State and tribal leaking storage tank lists
	3 ft. Lower Elevation	29 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000003636
Latitude:	37.5806028815452
Longitude:	-122.347826957703
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/15/2012
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
LOC Case Number:	660107
File Location:	Not Reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Open/Close case, Opened 3/28/2012
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000003636

Contact:

Global Id:	T10000003636
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T10000003636
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

KIM MILLS TEXACO (FORMER), 401 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T10000003636
Status:	Completed - Case Closed
Status Date:	05/15/2012
Global Id:	T10000003636
Status:	Open - Case Begin Date
Status Date:	03/21/2012
Global Id:	T10000003636
Status:	Open - Verification Monitoring
Status Date:	03/28/2012

Regulatory Activities:

Global Id:	T10000003636
Action Type:	ENFORCEMENT
Date:	04/03/2012
Action:	Notice of Responsibility - #20120403
Global Id:	T10000003636
Action Type:	ENFORCEMENT
Date:	05/15/2012
Action:	Closure/No Further Action Letter - #20120515
Global Id:	T10000003636
Action Type:	Other
Date:	03/21/2012
Action:	Leak Discovery
Global Id:	T10000003636
Action Type:	Other
Date:	03/27/2012
Action:	Leak Reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660107
Facility Status:	9- Case Closed
Global ID:	T100003636
APN Number:	029133200
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

UST SITE 401 CALIFORNIA, BURLINGAME, CA, 94010			S113759021
▼ D13	N <1/10	(386 ft. / 0.073 mi.)	Other Standard Environmental Records
	3 ft. Lower Elevation	29 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0051083
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0070859
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

REDLICH JR, CHRISTOPHER 360 PRIMROSE, BURLINGAME, CA, 94010			S113757752
▲ E14	WSW <1/10	(393 ft. / 0.074 mi.)	Other Standard Environmental Records
	Equal Elevation	32 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0027489
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0043724
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

345 CALIFORNIA DR 345 CALIFORNIA DR, BURLINGAME, CA, 94010			1015047032
▼ C15	NE <1/10	(395 ft. / 0.075 mi.)	Historical Dry Cleaners
	1 ft. Lower Elevation	31 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

EDR Historical Cleaners: Historical Dry Cleaners

Name:	J C CARPET & UPHOLSTERY CLEANING SPE
Year:	2011
Address:	345 CALIFORNIA DR
Name:	J C CARPET & UPHOLSTERY CLEANING SPE
Year:	2012
Address:	345 CALIFORNIA DR

VERIZON WIRELESS EL CAMINO HOWARD Not Reported, BURLINGAME, CA, 94010			S113757879
▲ E16	SSW <1/10	(415 ft. / 0.079 mi.)	Other Standard Environmental Records
	3 ft. Higher Elevation	35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0027902
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0045802
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE

AUTAR JOHAL PROPERTY 1301 BURLINGAME, BURLINGAME, CA, 94010			S113757785
▲ F17	SSE <1/10	(426 ft. / 0.081 mi.)	Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0027566
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0044116
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

MAP FINDINGS

339 PRIMROSE RD 339 PRIMROSE RD, BURLINGAME, CA, 94010			1015045918
▲ E18	SSW <1/10	(439 ft. / 0.083 mi.)	Historical Dry Cleaners
	3 ft. Higher Elevation	35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

EDR Historical Cleaners: Historical Dry Cleaners

Name:	PRIMROSE CLEANERS
Year:	2001
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANERS
Year:	2003
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANERS
Year:	2004
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2005
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2006
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2008
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2010
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2011
Address:	339 PRIMROSE RD
Name:	PRIMROSE CLEANER
Year:	2012
Address:	339 PRIMROSE RD

PRIMROSE CLEANERS 339 PRIMROSE, BURLINGAME, CA, 94010			S113755385
▲ E19	SSW <1/10	(439 ft. / 0.083 mi.)	Other Standard Environmental Records
	3 ft. Higher Elevation	35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0056769
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0078772
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0056769
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0078771
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0007475
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011893
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0007475
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0026812
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

MAP FINDINGS

PRIMROSE CLEANERS 339 PRIMROSE RD, BURLINGAME, CA, 94010		S103892226
▲ E20	SSW <1/10 (439 ft. / 0.083 mi.)	Other Standard Environmental Records
	3 ft. Higher Elevation 35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

DRYCLEANERS: Other Standard Environmental Records

EPA Id:	CAL000343005
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	05/15/2009
Facility Active:	No
Inactive Date:	Not Reported
Facility Addr2:	Not Reported
Owner Name:	JAMES LEE
Owner Address:	30963 SAN BENITO ST
Owner Address 2:	Not Reported
Owner Telephone:	5104895722
Contact Name:	CHONG LEE OWNER
Contact Address:	30963 SAN BENITO ST
Contact Address 2:	Not Reported
Contact Telephone:	5104895722
Mailing Name:	Not Reported
Mailing Address 1:	30963 SAN BENITO ST
Mailing Address 2:	Not Reported
Mailing City:	HAYWARD
Mailing State:	CA
Mailing Zip:	94544
Owner Fax:	2
Region Code:	0000000000

337 PRIMROSE RD 337 PRIMROSE RD, BURLINGAME, CA, 94010			1015045718
▲ E21	SSW <1/10	(442 ft. / 0.084 mi.)	Historical Dry Cleaners
	3 ft. Higher Elevation	35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

EDR Historical Cleaners: Historical Dry Cleaners

Name:	DIRTY LAUNDRY
Year:	2005
Address:	337 PRIMROSE RD

SEPHORA #052 1205 BURLINGAME, BURLINGAME, CA, 94010			S113758480
▲ B22	ESE <1/10	(451 ft. / 0.085 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0038931
Prog Element Code:	GEN <1 TONS HAZ WASTE/YR
Record Id:	PR0055206
Description:	GEN <1 TONS HAZ WASTE/YR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0038931
Prog Element Code:	BUSINESS PLAN - GENERAL
Record Id:	PR0065034
Description:	BUSINESS PLAN - GENERAL
Facility Status:	INACTIVE

PICKRELL D J 1408 CHAPIN AVE, BURLINGAME, CA, 94010			1003878368
▲ E23	WSW <1/10	(519 ft. / 0.098 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

SEMS-ARCHIVE: Other Standard Environmental Records

Site ID:	901576
EPA ID:	CAD074632522
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0901576
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:

Contact Sequence ID:	13287240.00000
Person ID:	13003854.00000
Contact Sequence ID:	13292835.00000
Person ID:	13003858.00000
Contact Sequence ID:	13298693.00000
Person ID:	13004003.00000

CERCLIS-NFRAP Assessment History:

Action:	DISCOVERY
Date Started:	/ /
Date Completed:	12/01/79
Priority Level:	Not Reported
Action:	ARCHIVE SITE
Date Started:	/ /
Date Completed:	12/01/87
Priority Level:	Not Reported
Action:	PRELIMINARY ASSESSMENT

PICKRELL D J, 1408 CHAPIN AVE, BURLINGAME, CA 94010 (Continued)

Date Started:	/ /
Date Completed:	12/01/87
Priority Level:	NFRAP-Site does not qualify for the NPL based on existing information

88 PHOTO LAB 1109 BURLINGAME, BURLINGAME, CA, 94010			S113757419
▲ B24	E <1/10	(524 ft. / 0.099 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0025962
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0037389
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0025962
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0037390
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

CRYO CREAM 240 PARK, BURLINGAME, CA, 94010			S113755187
▲ F25	SE 1/10 - 1/3	(530 ft. / 0.1 mi.)	Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0000510
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0074131
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

CTY OF SAN MATEO 501 PRIMROSE RD, BURLINGAME, CA, 940100000			S113796067
▼ 26	W 1/10 - 1/3	(610 ft. / 0.116 mi.)	Other Standard Environmental Records
	3 ft. Lower Elevation	29 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0054565
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0075252
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

HAZNET: Other Standard Environmental Records

envid:	S113796067
Year:	2012
GEPAID:	CAH111000675
Contact:	PETE SMITH
Telephone:	6505991600
Mailing Name:	Not Reported
Mailing Address:	590 HAMILTON ST 4TH FLOOR
Mailing City,St,Zip:	REDWOOD CITY, CA 940630000
Gen County:	San Mateo
TSD EPA ID:	ARD981057870
TSD County:	99
Waste Category:	Not Reported
Disposal Method:	Fuel Blending Prior To Energy Recovery At Another Site
Tons:	2.275
Cat Decode:	Not Reported
Method Decode:	Fuel Blending Prior To Energy Recovery At Another Site
Facility County:	San Mateo

BURLINGAME HIGH SCHOOL 400 CAROLAN AVENUE, BURLINGAME, CA, 94010-2708		S103986521	
▼ 27	NNE 1/10 - 1/3	(616 ft. / 0.117 mi.)	State and tribal - equivalent CERCLIS Other Standard Environmental Records
	4 ft. Lower Elevation	28 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

DEED: Other Standard Environmental Records

Envirostor ID:	41820008
Area:	ARSENIC
Sub Area:	Not Reported
Site Type:	SCHOOL CLEANUP
Status:	CERTIFIED / OPERATION & MAINTENANCE
Agency:	Not Reported
Covenant Uploaded:	Not Reported
Deed Date(s):	01/04/2013

SCH: Other Standard Environmental Records

Facility ID:	41820008
Site Type:	School Cleanup
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	22
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Mellan Songco
Supervisor:	Jose Salcedo
Division Branch:	Northern California Schools & Santa Susana
Site Code:	204083
Assembly:	22
Senate:	13
Special Program Status:	Not Reported
Status:	Certified / Operation & Maintenance
Status Date:	08/04/2011
Restricted Use:	YES
Funding:	School District
Latitude:	37.58249
Longitude:	-122.3468
APN:	026290380, 029-141-010, 029141010
Past Use:	UNKNOWN, SCHOOL - HIGH SCHOOL
Potential COC:	Arsenic, Lead, Polychlorinated biphenyls (PCBs

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Confirmed COC:	Arsenic, , Polychlorinated biphenyls (PCBs, Polychlorinated biphenyls (PCBs, Lead
Potential Description:	SOIL, SOIL
Alias Name:	BURLINGAME HIGH SCHOOOL
Alias Type:	Alternate Name
Alias Name:	SAN MATEO UHSD-BURLINGAME HIGH
Alias Type:	Alternate Name
Alias Name:	SAN MATEO UNION HIGH SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	026290380
Alias Type:	APN
Alias Name:	029-141-010
Alias Type:	APN
Alias Name:	029141010
Alias Type:	APN
Alias Name:	110021905143
Alias Type:	EPA (FRS #)
Alias Name:	204083
Alias Type:	Project Code (Site Code)
Alias Name:	41820008
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/16/2001
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	11/05/2002
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	CEQA - Notice of Exemption
Completed Date:	09/06/2007
Comments:	Office of Env. Planning & Analysis has approved the NOE. Division signatures will be added to the tracking form when the RAW is approved.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	10/01/2007
Comments:	DTSC issued approval to begin construction on the rear athletic field.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	01/25/2007
Comments:	Sharon received a draft response letter from the District that did not comply with the DNONC. Comments were written on the response; Additional internal meetings are needed to determine if an order will be issued.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/05/2007
Comments:	Held a face-to-face meeting to discuss outstanding issues for the project: Schedule for remainder of activities; Discussion regarding remediation in the planter boxes. Discussed a couple of options for the planter boxes; the District will include their final recommendation for their remediation in the arsenic RAW.
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/02/2007
Comments:	Site Visit to oversee confirmation sampling for PCB remediation.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	03/30/2007
Comments:	Phone conference to discuss 1. Fact sheet; 2. Start of the Lead/PCB removal; 3. Recent arsenic characterization; 4. Meeting in DTSC Berkeley Office to develop the dates for the remaining of the remediation activities.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	03/22/2007
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	02/08/2007
Comments:	Meet with Kim, Diane and Mark to discuss the work notice Kim prepared for Burlingame. Based on the significant amount of time that has lapsed since the last communication from DTSC to the community, Fact Sheet was recommended instead of a work notice. It will include the dates of the PCB and lead removals as well as a date on the

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

additional arsenic investigation. A reference will be made regarding the arsenic removal, but no specific date will be mentioned.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/01/2007
Comments: Project Team to discuss outstanding issues for project: fence the PCB area; financal capabilities of the District; look up the requirements for proper signage and will send it to Burlingame via email; Cost Estimates to complete all of the work at BHS- cost to complete the PCB and Lead removal actions, cost to completed and arsenic characterization; prepare another timeline of tasks that need to be completed; Stabalization of site press release and future fact sheets;

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 01/29/2007
Comments: Project team discussed Measure M (Proposition 39) that was passed in November 06 for $298,000,000. discussed if an Imminent and Substantial Endangerment order would appropriate to issue or , a Determination of Non-Compliance (DoNC) or a Fence and Post on a temporary fence

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/26/2006
Comments: Meeting to discuss: the letter of proposed Determination of Non-Compliance was signed and sent to the District and the letter sent to the City of Burlingame (Jim Nantell) . The DNONC identified three thing: Completion of removal action for lead and PCBs around the main building and a submittal of a RACR; Submittal of an SSI to document the extent of arsenic-contamination on BHS; and submittal of a RAW to address the mitigation of arsenic. District to provide a response by January 17, 2007

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: School Cleanup Agreement
Completed Date: 10/12/2005
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Correspondence
Completed Date:	08/25/2008
Comments:	DTSC issued a letter to the District outlining the current status of the project and requesting a response to DTSC comments regarding the RACR and a schedule of mitigation activities.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	12/03/2009
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operation & Maintenance Order/Agreement
Completed Date:	08/04/2009
Comments:	DTSC issued a fully executed Operation and Maintenance Agreement.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction
Completed Date:	01/04/2013
Comments:	On January 4, 2013, the County of San Mateo recorded the land use covenant for the Burlingame High School.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/10/2013
Comments:	On July 10, 2013, DTSC participated on the annual site inspection with Victor Talavera and Patrick Sing (District), and Wes Hawthorne (Locus).
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	06/18/2012
Comments:	DTSC participated in the annual arsenic inspection at the Burlingame HS with Zeke Lyles and Wes Hawthorne. The Burlingame HS is still undergoing modernization. DTSC was notified by W. Hawthorne that Victor Talaveras (Arsenic Coordinator) is aware of the project and is monitoring the progress of the modernization project to ensure that if any of the areas of concern is impacted the proper SOP will be followed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/09/2014

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Comments:	On July 9, 2014, DTSC participated on the 5-Year review inspection of the cap at the site with the District representatives Sara Dwight (Arsenic Coordinator), Ricky Carrillo (Plant Manager), Wes Hawthorne (Locus Technologies). Cap measurements were taken at two areas in Area E and both areas meet or exceeds the minimum cap thickness.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	08/21/2015
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	08/27/2009
Comments:	Project Manager Change
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	06/28/2010
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	12/04/2013
Comments:	On December 2, 2013, DTSC was notified via email from Mr. Victor Talaveras (District's Arsenic Coordinator) that Building F (Home Economics Building) will be demolished which would impact Areas G and C identified in the DTSC-approved O&M Plan. The proposed schedule for the demolition work is from December 16, 2013 until January 24, 2014. Mr. Talaveras stated that the SOP included in the approved O&M Plan will be implemented for this project.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	07/20/2011
Comments:	DTSC conducted the 2011 Annual Arsenic Inpection with Zeke Lyles, District's Arsenic Coordinator; J. Wesley Hawthorne (Locus Technologies), O&M Professional; and, George. The following were observed during the walkthrough: bare soils w/ mesh visible around some trees in Area E; some of the planters in Area F2 needs additional granite; Area C behind building C and by the library needs additional wood chips to fill bald spots around plants; a new

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

building D is almost complete - need to verify if Area C is beneath the new building; some of the Area C around the gym that is not concreted needs woodchips to fill bald spots. Z. Lyles mentioned that after the ongoing modernization he is planning on putting concrete over the grassy area around the gym instead on maintaning the grass. The trees will stay and the root area will have bark as covering. Currently, area soil is exposed. During the site inspection Z. Lyles mentioned that the parking area in the south side of the site will be re-finished in the coming months. DTSC reminded them that Area G2 is part of the parking area and therefore there's a potential for arsenic in the soil. In addition, Z. Lyles also mentioned that the track area will also be modernized in the coming months. DTSC recommended that samples be taken & that the consultants follow the SOP included in the O&M plan.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	08/20/2013
Comments:	On August 20, 2013, DTSC notified the District about the Agreement manager change.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Certification
Completed Date:	01/29/2013
Comments:	On January 29, 2013, DTSC completed the site certification.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Amendment - Order/Agreement
Completed Date:	07/07/2014
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	05/27/2015
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/02/2014
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	02/05/2004
Comments:	DTSC approved the PEA with further action required determination.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Phase 1
Completed Date:	08/07/2002
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Workplan
Completed Date:	04/06/2005
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	12/23/2002
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Workplan
Completed Date:	06/02/2005
Comments:	Not Reported
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Workplan
Completed Date:	12/19/2005
Comments:	DTSC issued conditional approval. The newspaper did not run the public comment period notification as scheduled. Conditional approval allowed the District to move forward with the removal action for lead and PCBs with the undersanding that changes to the RAW may be neccessary if significant public comments are recevied. PCB clean-up goal is 0.3 mg/kg and lead clean-up goal is 255 mg/kg.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	04/27/2007
Comments:	DTSC approved the SSI report with a remediation required determination. A Removal Action Workplan (RAW) will be prepared to address arsenic impacted soils at the site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	04/04/2006

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Comments:	District requested DTSC to assist the in solicitation of state funding by crafting a letter to CDE indicating that the removal actions on the school will take more than six months to complete.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	06/23/2006
Comments:	Delays in Investigation letter to the School District. OLC has been contacted and staff has been assigned to project.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	09/15/2005
Comments:	DTSC PM memo regarding the evaluation for concentrations of arsenic in the City Easement. Memo is part of a letter to the City of Burlingame.
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	11/14/2005
Comments:	Fast Sheet developed to announce the start of the public comment period for the lead RAW and the contamination identified on the site.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/20/2006
Comments:	DTSC put an unofficial summary together of all of the arsenic investigation for discussion purposes only.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/20/2006
Comments:	Established a new cost estimate to complete the remainder of the project. Cost estimate considered the oversight for the remainder of the lead/PCB removal, additional investigation of arsenic, the remediation of arsenic and project closure.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	05/17/2004
Comments:	Letter was constructed to encourage San Mateo Union HSD to enter into a VCA for the clean-up of elevated levels of arsenic found on the campus.

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/26/2006
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	03/12/2007
Comments:	DTSC approval of temporary mitigation for cement slurry over City's dirt easment area.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	03/15/2007
Comments:	DTSC issued Status of Investigation for arsenic Letter.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Report
Completed Date:	03/21/2007
Comments:	DTSC received (via email), reviewed and approved the TM for arsenic characterization
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	03/28/2007
Comments:	Received 2 copies of Fact Sheet. Uploaded document.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Workplan
Completed Date:	11/07/2007
Comments:	DTSC issued a RAW approval and concurrently reponded to public comments regarding the RAW (in a separate but enclosed letter) and filed the NOE.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	10/01/2007
Comments:	DTSC issued the Fact Sheet and public notice establishing the beginning of the public comment period. The public comment period will run from 10/5/07 - 11/05/07.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Date:	05/02/2007
Comments:	Following a comprehensive review of the laboratory reports on the soils to be used as fill material in the remediation at Burlingame High School, DTSC has approved the use of the proposed fill materials.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	01/18/2008
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/07/2008
Comments:	DTSC reviewed and determined that based on the results of the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/15/2008
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	11/29/2007
Comments:	DTSC/District weekly remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/06/2007
Comments:	DTSC/Distict arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/13/2007
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/27/2007
Comments:	DTSC/District arsenic remediaiton meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Other Report
Completed Date:	01/03/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	01/17/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/14/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/28/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	10/27/2008
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	10/27/2008
Comments:	DTSC developed and approved the ESD for the project. The ESD serves as a bridging document to explain that a Land Use Covenant (LUC) is needed for the project, even though the LUC was not mentioned in the removal action workplan.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Plan
Completed Date:	08/04/2011
Comments:	On July 19, 2012, DTSC received the complete revised Final O&M Plan (July 10, 2012 version)
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	05/06/2010
Comments:	DTSC approved the Removal Action Completion Report for arsenic impacted soils
Completed Area Name:	Arsenic

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	01/07/2009
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/07/2008
Comments:	DTSC reviewed and determined that based on the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Report
Completed Date:	06/06/2011
Comments:	DTSC approved the 2010 Arsenic Annual Inspection summary Report
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Report
Completed Date:	05/03/2012
Comments:	On May 3, 2012, DTSC approved the Arsenic Annual Inspection Summary Report. This letter also identified two new areas of concern located at the Athletic Field area that will be included and managed under the O&M Plan.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	*Correspondence - Received
Completed Date:	02/22/2012
Comments:	On February 22, 2012, DTSC received a notification from the SMUHGD via e-mail indicating that Mr. Victor Talavera will be the new Arsenic Coordinator (replacing Mr. Ezekiel Lyles).
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Report
Completed Date:	09/07/2012
Comments:	On September 4, 2012, DTSC approved the 2012 Annual Summary Inspection Report.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	5 Year Review Reports
Completed Date:	12/09/2014
Comments:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Report
Completed Date:	10/04/2013
Comments:	On October 2, 2013, DTSC received one hard copy of the revised 2013 Arsenic Annual Report; the e-copy was received via email on September 25, 2013.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Public Notice
Completed Date:	07/17/2014
Comments:	Final public notice for publishing before July 8, 2014.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Plan
Completed Date:	06/17/2015
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Public Notice
Completed Date:	06/20/2015
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction Monitoring Report
Completed Date:	01/15/2016
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/06/2006
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/13/2006
Comments:	Not Reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/29/2006
Comments:	Not Reported

Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	CEQA - Notice of Exemption

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Date: 11/10/2005
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/20/2006
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/27/2005
Comments: Not Reported

Completed Area Name: Lead/PCB
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 09/20/2005
Comments: Not Reported

Completed Area Name: Arsenic
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/26/2005
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 04/20/2005
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 08/03/2006
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/19/2006
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 07/18/2006
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Date:	03/23/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/15/2006
Comments:	Not Reported
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not Reported
Future Document Type:	Operations and Maintenance Report
Future Due Date:	2016
Schedule Area Name:	Not Reported
Schedule Sub Area Name:	Not Reported
Schedule Document Type:	Not Reported
Schedule Due Date:	Not Reported
Schedule Revised Date:	Not Reported

ENVIROSTOR: State and tribal - equivalent CERCLIS

Facility ID:	41820008
Status:	Certified / Operation & Maintenance
Status Date:	08/04/2011
Site Code:	204083
Site Type:	School Cleanup
Site Type Detailed:	School
Acres:	22
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Mellan Songco
Supervisor:	Jose Salcedo
Division Branch:	Northern California Schools & Santa Susana
Assembly:	22
Senate:	13
Special Program:	Not Reported
Restricted Use:	YES
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	37.58249
Longitude:	-122.3468
APN:	026290380, 029-141-010, 029141010
Past Use:	UNKNOWN, SCHOOL - HIGH SCHOOL
Potential COC:	Arsenic Lead Polychlorinated biphenyls (PCBs
Confirmed COC:	Arsenic Polychlorinated biphenyls (PCBs Lead
Potential Description:	SOIL, SOIL
Alias Name:	BURLINGAME HIGH SCHOOOL
Alias Type:	Alternate Name
Alias Name:	SAN MATEO UHSD-BURLINGAME HIGH
Alias Type:	Alternate Name

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Alias Name:	SAN MATEO UNION HIGH SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	026290380
Alias Type:	APN
Alias Name:	029-141-010
Alias Type:	APN
Alias Name:	029141010
Alias Type:	APN
Alias Name:	110021905143
Alias Type:	EPA (FRS #)
Alias Name:	204083
Alias Type:	Project Code (Site Code)
Alias Name:	41820008
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/16/2001
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	11/05/2002
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	CEQA - Notice of Exemption
Completed Date:	09/06/2007
Comments:	Office of Env. Planning & Analysis has approved the NOE. Division signatures will be added to the tracking form when the RAW is approved.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	10/01/2007
Comments:	DTSC issued approval to begin construction on the rear athletic field.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	01/25/2007
Comments:	Sharon received a draft response letter from the District that did not comply with the DNONC. Comments were written on the response; Additional internal meetings are needed to determine if an order will be issued.

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/05/2007
Comments:	Held a face-to-face meeting to discuss outstanding issues for the project: Schedule for remainder of activities; Discussion regarding remediation in the planter boxes. Discussed a couple of options for the planter boxes; the District will include their final recommendation for their remediation in the arsenic RAW.
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/02/2007
Comments:	Site Visit to oversee confirmation sampling for PCB remediation.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	03/30/2007
Comments:	Phone conference to discuss 1. Fact sheet; 2. Start of the Lead/PCB removal; 3. Recent arsenic characterization; 4. Meeting in DTSC Berkeley Office to develop the dates for the remaining of the remediation activities.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	03/22/2007
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	02/08/2007
Comments:	Meet with Kim, Diane and Mark to discuss the work notice Kim prepared for Burlingame. Based on the significant amount of time that has lapsed since the last communication from DTSC to the community, Fact Sheet was recommended instead of a work notice. It will include the dates of the PCB and lead removals as well as a date on the additional arsenic investigation. A reference will be made regarding the arsenic removal, but no specific date will be mentioned.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	02/01/2007
Comments:	Project Team to discuss outstanding issues for project: fence the PCB

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

area; financal capabilities of the District; look up the requirements for proper signage and will send it to Burlingame via email; Cost Estimates to complete all of the work at BHS- cost to complete the PCB and Lead removal actions, cost to completed and arsenic characterization; prepare another timeline of tasks that need to be completed; Stabalization of site press release and future fact sheets;

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 01/29/2007
Comments: Project team discussed Measure M (Proposition 39) that was passed in November 06 for $298,000,000. discussed if an Imminent and Substantial Endangerment order would appropriate to issue or , a Determination of Non-Compliance (DoNC) or a Fence and Post on a temporary fence

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 12/26/2006
Comments: Meeting to discuss: the letter of proposed Determination of Non-Compliance was signed and sent to the District and the letter sent to the City of Burlingame (Jim Nantell) . The DNONC identified three thing: Completion of removal action for lead and PCBs around the main building and a submittal of a RACR; Submittal of an SSI to document the extent of arsenic-contamination on BHS; and submittal of a RAW to address the mitigation of arsenic. District to provide a response by January 17, 2007

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: School Cleanup Agreement
Completed Date: 10/12/2005
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Correspondence
Completed Date: 08/25/2008
Comments: DTSC issued a letter to the District outlining the current status of the project and requesting a response to DTSC comments regarding the RACR and a schedule of mitigation activities.

Completed Area Name: Arsenic
Completed Sub Area Name: Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Correspondence
Completed Date:	12/03/2009
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operation & Maintenance Order/Agreement
Completed Date:	08/04/2009
Comments:	DTSC issued a fully executed Operation and Maintenance Agreement.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction
Completed Date:	01/04/2013
Comments:	On January 4, 2013, the County of San Mateo recorded the land use covenant for the Burlingame High School.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/10/2013
Comments:	On July 10, 2013, DTSC participated on the annual site inspection with Victor Talavera and Patrick Sing (District), and Wes Hawthorne (Locus).
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	06/18/2012
Comments:	DTSC participated in the annual arsenic inspection at the Burlingame HS with Zeke Lyles and Wes Hawthorne. The Burlingame HS is still undergoing modernization. DTSC was notified by W. Hawthorne that Victor Talaveras (Arsenic Coordinator) is aware of the project and is monitoring the progress of the modernization project to ensure that if any of the areas of concern is impacted the proper SOP will be followed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	07/09/2014
Comments:	On July 9, 2014, DTSC participated on the 5-Year review inspection of the cap at the site with the District representatives Sara Dwight (Arsenic Coordinator), Ricky Carrillo (Plant Manager), Wes Hawthorne (Locus Technologies). Cap measurements were taken at two areas in Area E and both areas meet or exceeds the minimum cap thickness.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	08/21/2015
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	08/27/2009
Comments:	Project Manager Change
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	06/28/2010
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Correspondence
Completed Date:	12/04/2013
Comments:	On December 2, 2013, DTSC was notified via email from Mr. Victor Talaveras (District's Arsenic Coordinator) that Building F (Home Economics Building) will be demolished which would impact Areas G and C identified in the DTSC-approved O&M Plan. The proposed schedule for the demolition work is from December 16, 2013 until January 24, 2014. Mr. Talaveras stated that the SOP included in the approved O&M Plan will be implemented for this project.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	07/20/2011
Comments:	DTSC conducted the 2011 Annual Arsenic Inpection with Zeke Lyles, District's Arsenic Coordinator; J. Wesley Hawthorne (Locus Technologies), O&M Professional; and, George. The following were observed during the walkthrough: bare soils w/ mesh visible around some trees in Area E; some of the planters in Area F2 needs additional granite; Area C behind building C and by the library needs additional wood chips to fill bald spots around plants; a new building D is almost complete - need to verify if Area C is beneath the new building; some of the Area C around the gym that is not concreted needs woodchips to fill bald spots. Z. Lyles mentioned that after the ongoing modernization he is planning on putting concrete over the grassy area around the gym instead on maintaning the grass. The trees will stay and the root area will have bark as covering. Currently, area soil is exposed. During the site inspection Z. Lyles

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

mentioned that the parking area in the south side of the site will be re-finished in the coming months. DTSC reminded them that Area G2 is part of the parking area and therefore there's a potential for arsenic in the soil. In addition, Z. Lyles also mentioned that the track area will also be modernized in the coming months. DTSC recommended that samples be taken & that the consultants follow the SOP included in the O&M plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Correspondence
Completed Date: 08/20/2013
Comments: On August 20, 2013, DTSC notified the District about the Agreement manager change.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Certification
Completed Date: 01/29/2013
Comments: On January 29, 2013, DTSC completed the site certification.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Amendment - Order/Agreement
Completed Date: 07/07/2014
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Correspondence
Completed Date: 05/27/2015
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/02/2014
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/05/2004
Comments: DTSC approved the PEA with further action required determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Phase 1
Completed Date: 08/07/2002
Comments: Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Workplan
Completed Date:	04/06/2005
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	12/23/2002
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Workplan
Completed Date:	06/02/2005
Comments:	Not Reported
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Workplan
Completed Date:	12/19/2005
Comments:	DTSC issued conditional approval. The newspaper did not run the public comment period notification as scheduled. Conditional approval allowed the District to move forward with the removal action for lead and PCBs with the undersanding that changes to the RAW may be neccessary if significant public comments are recevied. PCB clean-up goal is 0.3 mg/kg and lead clean-up goal is 255 mg/kg.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	04/27/2007
Comments:	DTSC approved the SSI report with a remediation required determination. A Removal Action Workplan (RAW) will be prepared to address arsenic impacted soils at the site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	04/04/2006
Comments:	District requested DTSC to assist the in solicitation of state funding by crafting a letter to CDE indicating that the removal actions on the school will take more than six months to complete.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	06/23/2006
Comments:	Delays in Investigation letter to the School District. OLC has been

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

contacted and staff has been assigned to project.

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	09/15/2005
Comments:	DTSC PM memo regarding the evaluation for concentrations of arsenic in the City Easement. Memo is part of a letter to the City of Burlingame.

Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	11/14/2005
Comments:	Fast Sheet developed to announce the start of the public comment period for the lead RAW and the contamination identified on the site.

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/20/2006
Comments:	DTSC put an unofficial summary together of all of the arsenic investigation for discussion purposes only.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/20/2006
Comments:	Established a new cost estimate to complete the remainder of the project. Cost estimate considered the oversight for the remainder of the lead/PCB removal, additional investigation of arsenic, the remediation of arsenic and project closure.

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	05/17/2004
Comments:	Letter was constructed to encourage San Mateo Union HSD to enter into a VCA for the clean-up of elevated levels of arsenic found on the campus.

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/26/2006
Comments:	Not Reported

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Date:	03/12/2007
Comments:	DTSC approval of temporary mitigation for cement slurry over City's dirt easment area.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	03/15/2007
Comments:	DTSC issued Status of Investigation for arsenic Letter.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Technical Report
Completed Date:	03/21/2007
Comments:	DTSC received (via email), reviewed and approved the TM for arsenic characterization
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	03/28/2007
Comments:	Received 2 copies of Fact Sheet. Uploaded document.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Workplan
Completed Date:	11/07/2007
Comments:	DTSC issued a RAW approval and concurrently reponded to public comments regarding the RAW (in a separate but enclosed letter) and filed the NOE.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	10/01/2007
Comments:	DTSC issued the Fact Sheet and public notice establishing the beginning of the public comment period. The public comment period will run from 10/5/07 - 11/05/07.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	05/02/2007
Comments:	Following a comprehensive review of the laboratory reports on the soils to be used as fill material in the remediation at Burlingame High School, DTSC has approved the use of the proposed fill materials.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	01/18/2008

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/07/2008
Comments:	DTSC reviewed and determined that based on the results of the analytical data provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/15/2008
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	11/29/2007
Comments:	DTSC/District weekly remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/06/2007
Comments:	DTSC/Distict arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/13/2007
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	12/27/2007
Comments:	DTSC/District arsenic remediaiton meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	01/03/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	01/17/2008
Comments:	DTSC/District arsenic remediation meeting

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/14/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/28/2008
Comments:	DTSC/District arsenic remediation meeting
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	10/27/2008
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	10/27/2008
Comments:	DTSC developed and approved the ESD for the project. The ESD serves as a bridging document to explain that a Land Use Covenant (LUC) is needed for the project, even though the LUC was not mentioned in the removal action workplan.
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Plan
Completed Date:	08/04/2011
Comments:	On July 19, 2012, DTSC received the complete revised Final O&M Plan (July 10, 2012 version)
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	05/06/2010
Comments:	DTSC approved the Removal Action Completion Report for arsenic impacted soils
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Fact Sheets
Completed Date:	01/07/2009
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Other Report
Completed Date:	02/07/2008
Comments:	DTSC reviewed and determined that based on the analytical data

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

provided, the decomposed granite from the Handley Ranch Quarry would not adversely impact the site and is suitable to use as fill material in Area B.

Completed Area Name: Arsenic
Completed Sub Area Name: Not Reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 06/06/2011
Comments: DTSC approved the 2010 Arsenic Annual Inspection summary Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 05/03/2012
Comments: On May 3, 2012, DTSC approved the Arsenic Annual Inspection Summary Report. This letter also identified two new areas of concern located at the Athletic Field area that will be included and managed under the O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: *Correspondence - Received
Completed Date: 02/22/2012
Comments: On February 22, 2012, DTSC received a notification from the SMUHGD via e-mail indicating that Mr. Victor Talavera will be the new Arsenic Coordinator (replacing Mr. Ezekiel Lyles).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 09/07/2012
Comments: On September 4, 2012, DTSC approved the 2012 Annual Summary Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: 5 Year Review Reports
Completed Date: 12/09/2014
Comments: Not Reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported
Completed Document Type: Operations and Maintenance Report
Completed Date: 10/04/2013
Comments: On October 2, 2013, DTSC received one hard copy of the revised 2013 Arsenic Annual Report; the e-copy was received via email on September 25, 2013.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Public Notice
Completed Date:	07/17/2014
Comments:	Final public notice for publishing before July 8, 2014.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Operations and Maintenance Plan
Completed Date:	06/17/2015
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Public Notice
Completed Date:	06/20/2015
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Land Use Restriction Monitoring Report
Completed Date:	01/15/2016
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/06/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/13/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/29/2006
Comments:	Not Reported
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	CEQA - Notice of Exemption
Completed Date:	11/10/2005
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/20/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	12/27/2005
Comments:	Not Reported
Completed Area Name:	Lead/PCB
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	09/20/2005
Comments:	Not Reported
Completed Area Name:	Arsenic
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/26/2005
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	04/20/2005
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	08/03/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	07/19/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	07/18/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	03/23/2006
Comments:	Not Reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not Reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	11/15/2006
Comments:	Not Reported
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not Reported

BURLINGAME HIGH SCHOOL, 400 CAROLAN AVENUE, BURLINGAME, CA 94010-2708 (Continued)

Future Document Type:	Operations and Maintenance Report
Future Due Date:	2016
Schedule Area Name:	Not Reported
Schedule Sub Area Name:	Not Reported
Schedule Document Type:	Not Reported
Schedule Due Date:	Not Reported
Schedule Revised Date:	Not Reported

US POSTAL SERVICE 220 PARK, BURLINGAME, CA, 94010		S104234098	
▲ G28	SE 1/10 - 1/3	(630 ft. / 0.119 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660040
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0096

BURLINGAME POST OFFICE 220 PARK, BURLINGAME, CA, 94010			S104493543
▲ G29	SE 1/10 - 1/3	(630 ft. / 0.119 mi.)	State and tribal leaking storage tank lists
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC Exists

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100091
Latitude:	37.5776778
Longitude:	-122.3461348
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	11/28/1995
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0096
LOC Case Number:	660040
File Location:	Local Agency Warehouse
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100091

Contact:

Global Id:	T0608100091
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100091
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

BURLINGAME POST OFFICE, 220 PARK, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T0608100091
Status:	Completed - Case Closed
Status Date:	11/28/1995
Global Id:	T0608100091
Status:	Open - Case Begin Date
Status Date:	04/23/1990

Regulatory Activities:

Global Id:	T0608100091
Action Type:	Other
Date:	04/23/1990
Action:	Leak Discovery
Global Id:	T0608100091
Action Type:	Other
Date:	04/23/1990
Action:	Leak Reported
Global Id:	T0608100091
Action Type:	ENFORCEMENT
Date:	12/05/1992
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660040
Facility Status:	9- Case Closed
Global ID:	T0608100091
APN Number:	029204250
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

NEXTEL-SITE ID CA-0323 1420 BURLINGAME, BURLINGAME, CA, 94010			S113757706
▲ H30	SSW 1/10 - 1/3	(642 ft. / 0.122 mi.)	Other Standard Environmental Records
	6 ft. Higher Elevation	38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0027316
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0043207
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

SPRINT NEXTEL CELL SITE FS04XC321 1420 BURLINGAME, BURLINGAME, CA, 94010			S113758635
▲ H31	SSW 1/10 - 1/3	(642 ft. / 0.122 mi.)	Other Standard Environmental Records
	6 ft. Higher Elevation	38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0044826
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0056965
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

UST SITE - FORMER FOX PENINSULA THEATER 1417-15 BURLINGAME, BURLINGAME, CA, 94010			S113759145
▲ H32	SSW 1/10 - 1/3	(650 ft. / 0.123 mi.)	Other Standard Environmental Records
	6 ft. Higher Elevation	38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0053257
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0073711
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

BURLINGAME ONE HOUR CLEANERS 507 CALIFORNIA, BURLINGAME, CA, 94010			S113759107
▼ I33	NNW 1/10 - 1/3	(737 ft. / 0.14 mi.)	Other Standard Environmental Records
	6 ft. Lower Elevation	26 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0052736
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0073049
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

DRYCLEANERS: Other Standard Environmental Records

EPA Id:	CAL000381651
NAICS Code:	333312
NAICS Description:	Commercial Laundry, Drycleaning, and Pressing Machine Manufacturing
SIC Code:	3582
SIC Description:	Commercial Laundry, Drycleaning and Pressing Machines
Create Date:	01/16/2013
Facility Active:	Yes
Inactive Date:	Not Reported
Facility Addr2:	Not Reported
Owner Name:	SEUNG KYUNG PARK
Owner Address:	1860 HARDING AVE
Owner Address 2:	Not Reported
Owner Telephone:	4153105000
Contact Name:	SEUNG KYUNG PARK
Contact Address:	507 CALIFORNIA DR
Contact Address 2:	Not Reported
Contact Telephone:	4153105000
Mailing Name:	Not Reported
Mailing Address 1:	507 CALIFORNIA DR
Mailing Address 2:	Not Reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940100000
Owner Fax:	2
Region Code:	0000000000

BURLINGAME ONE HOUR CLEANERS 507 CALIFORNIA DR, BURLINGAME, CA, 940100000			1002851178
▼ I34	NNW 1/10 - 1/3	(737 ft. / 0.14 mi.)	Other Standard Environmental Records
	6 ft. Lower Elevation	26 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

DRYCLEANERS: Other Standard Environmental Records

EPA Id:	CAD981171382
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	04/10/1987
Facility Active:	No
Inactive Date:	Not Reported
Facility Addr2:	Not Reported
Owner Name:	SEUNG KYUNG PARK
Owner Address:	1860 HARDING AVE.
Owner Address 2:	Not Reported
Owner Telephone:	4153105000
Contact Name:	SEUNG KYUNG PARK
Contact Address:	507 CALIFORNIA DR.
Contact Address 2:	Not Reported
Contact Telephone:	6503471875
Mailing Name:	Not Reported
Mailing Address 1:	507 CALIFORNIA DR
Mailing Address 2:	Not Reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	94010
Owner Fax:	2
Region Code:	0000000000

BURLINGAME ONE HOUR CLEANERS 507 CALIFORNIA, BURLINGAME, CA, 94010			S113756625
▼ I35	NNW 1/10 - 1/3	(737 ft. / 0.14 mi.)	Other Standard Environmental Records
	6 ft. Lower Elevation	26 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018022
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011840
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018022
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004620
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

G&C AUTO BODY 251 CALIFORNIA, BURLINGAME, CA, 94010			S113756140
▲ J36	E 1/10 - 1/3	(792 ft. / 0.15 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0015679
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011960
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0015679
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0026838
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

GERMAN CAR CARE 251 CALIFORNIA, BURLINGAME, CA, 94010			S113756147
▲ J37	E 1/10 - 1/3	(792 ft. / 0.15 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0015787
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011961
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0015787
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0028871
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

BURLINGAME HIGH SCHOOL 1 MANGINI, BURLINGAME, CA, 94010			S113755172
▼ 38	NNW 1/10 - 1/3	(866 ft. / 0.164 mi.)	Other Standard Environmental Records
	7 ft. Lower Elevation	25 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0000060
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0038069
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0000060
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0038068
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	ACTIVE

BB STERN COMPANY 222 CALIFORNIA, BURLINGAME, CA, 94010			S113757288
▲ J39	E 1/10 - 1/3	(881 ft. / 0.167 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0025127
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0033106
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

STERLING CLEANERS (FORMER) 215 CALIFORNIA DRIVE, BURLINGAME, CA, 94010			S110275436
▲ J40	ESE 1/10 - 1/3	(884 ft. / 0.167 mi.)	State and tribal leaking storage tank lists
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

Geological Attributes - Soil Geology:

Silty-clay, low-permeability soil: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000003211
Latitude:	37.5788130708654
Longitude:	-122.344790697098
Case Type:	LUST Cleanup Site
Status:	Open - Site Assessment
Status Date:	08/11/2011
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
LOC Case Number:	660105
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affect:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Stoddard solvent / Mineral Spriits / Distillates
Site History:	multiple stoddard tanks removed 3/2011. Case opened 8/11/2011 based on evidence of free-product in groundwater.
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000003211

Contact:

Global Id:	T10000003211
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported
Global Id:	T10000003211
Contact Type:	Local Agency Caseworker

STERLING CLEANERS (FORMER), 215 CALIFORNIA DRIVE, BURLINGAME, CA 94010 (Continued)

Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T10000003211
Status:	Open - Case Begin Date
Status Date:	08/11/2011
Global Id:	T10000003211
Status:	Open - Site Assessment
Status Date:	08/11/2011

Regulatory Activities:

Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	04/21/2015
Action:	Staff Letter - #20150421
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	04/25/2014
Action:	Soil Vapor Intrusion Investigation Workplan - Regulator Responded
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	01/12/2012
Action:	Staff Letter - #20120112
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	02/28/2012
Action:	Staff Letter - #20120228
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	01/19/2012
Action:	Notice of Responsibility - #20120119
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	11/21/2014
Action:	Site Assessment Report - Regulator Responded
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	09/18/2015
Action:	Proposed Plan - Regulator Responded
Global Id:	T10000003211

STERLING CLEANERS (FORMER), 215 CALIFORNIA DRIVE, BURLINGAME, CA 94010 (Continued)

Action Type:	ENFORCEMENT
Date:	02/03/2015
Action:	Staff Letter - #20150203
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	03/13/2015
Action:	Remedial Investigation Workplan - Regulator Responded
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	11/15/2015
Action:	Monitoring Report - Semi-Annually - Regulator Responded
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	02/13/2014
Action:	Staff Letter - #20140213
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	09/30/2011
Action:	Verbal Communication
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	02/15/2016
Action:	Other Report / Document
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	02/24/2012
Action:	Verbal Communication
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	07/23/2014
Action:	Staff Letter - #2014072014
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	08/11/2011
Action:	Staff Letter - #20110811
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	06/29/2012
Action:	Site Assessment Report
Global Id:	T10000003211
Action Type:	Other
Date:	03/17/2011
Action:	Leak Discovery
Global Id:	T10000003211

STERLING CLEANERS (FORMER), 215 CALIFORNIA DRIVE, BURLINGAME, CA 94010 (Continued)

Action Type:	RESPONSE
Date:	05/15/2014
Action:	Monitoring Report - Quarterly
Global Id:	T10000003211
Action Type:	Other
Date:	07/06/2011
Action:	Leak Reported
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	03/28/2013
Action:	Staff Letter - #20130328
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	04/20/2015
Action:	Correspondence
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	09/30/2015
Action:	Staff Letter - #20150930
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	02/15/2015
Action:	Monitoring Report - Quarterly
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	12/31/2015
Action:	CAP/RAP - Feasibility Study Report
Global Id:	T10000003211
Action Type:	Other
Date:	03/17/2011
Action:	Leak Stopped
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	02/15/2012
Action:	Preliminary Site Assessment Workplan - Regulator Responded
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	01/11/2013
Action:	Soil and Water Investigation Workplan - Regulator Responded
Global Id:	T10000003211
Action Type:	RESPONSE
Date:	08/15/2015
Action:	Monitoring Report - Semi-Annually
Global Id:	T10000003211

STERLING CLEANERS (FORMER), 215 CALIFORNIA DRIVE, BURLINGAME, CA 94010 (Continued)

Action Type:	RESPONSE
Date:	08/23/2013
Action:	Site Assessment Report - Regulator Responded
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	09/29/2011
Action:	Staff Letter - #20110929
Global Id:	T10000003211
Action Type:	ENFORCEMENT
Date:	09/06/2012
Action:	Staff Letter - #20120906

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660105
Facility Status:	3B- Preliminary Assessment Underway
Global ID:	T10000003211
APN Number:	029211080
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST
Region:	SAN MATEO
Facility ID:	669113
Facility Status:	3B- Preliminary Assessment Underway
Global ID:	T10000005652
APN Number:	029211080
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

UST SITE 215 CALIFORNIA, BURLINGAME, CA, 94010			S113758800
▲ J41	ESE 1/10 - 1/3	(884 ft. / 0.167 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0046059
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0061786
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

SLIC: State and tribal leaking storage tank lists

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	02/13/2014
Global Id:	T10000005652
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669113
Latitude:	37.5788353
Longitude:	-122.3444406
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
File Location:	Not Reported
Potential Media Affected:	Not Reported
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Likely PCE detected is from adjacent site, will likely close upon confirmation.
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_SLIC_ST&global_id=T10000005652

FEDERAL AUTO PARTS 231 CALIFORNIA, BURLINGAME, CA, 94010			S113756631
▲ J42	E 1/10 - 1/3	(895 ft. / 0.17 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018038
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011854
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018038
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004672
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

PANDA EXPRESS #907 1453 BURLINGAME, BURLINGAME, CA, 94010			S118584898
▲ K43	SSW 1/10 - 1/3	(907 ft. / 0.172 mi.)	Other Standard Environmental Records
	8 ft. Higher Elevation	40 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0028060
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0082163
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

UST SITE 1290 HOWARD, BURLINGAME, CA, 940110513			S113758833
▲ L44	SE 1/10 - 1/3	(947 ft. / 0.179 mi.)	Other Standard Environmental Records
	5 ft. Higher Elevation	37 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0046413
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0063109
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

TUCKER TRANSMISSIONS 215 HATCH, BURLINGAME, CA, 94010			S113755456
▲ M45	ESE 1/10 - 1/3	(948 ft. / 0.179 mi.)	Other Standard Environmental Records
	3 ft. Higher Elevation	35 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0009063
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011911
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0009063
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0029207
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

THE ARLINGTON APARTMENTS 1401 FLORIBUNDA AVE, BURLINGAME, CA, 940107506			S112978903
▼ N46	W 1/10 - 1/3	(948 ft. / 0.179 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Lower Elevation	28 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

SAN MATEO CO. LUST: State and tribal leaking storage tank lists

Region:	SAN MATEO
Facility ID:	660112
Facility Status:	9- Case Closed
Global ID:	Not Reported
APN Number:	029112320
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HAZNET: Other Standard Environmental Records

envid:	S112978903
Year:	2009
GEPAID:	CAC002643932
Contact:	ELAINE RIBAY
Telephone:	6505923960
Mailing Name:	Not Reported
Mailing Address:	1050 RALSTON AVE
Mailing City,St,Zip:	BELMONT, CA 94002
Gen County:	Not Reported
TSD EPA ID:	CAD028409019
TSD County:	Not Reported
Waste Category:	Other inorganic solid waste
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.085
Cat Decode:	Other inorganic solid waste
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	San Mateo

ARLINGTON APARTMENTS 1401 FLORIBUNDA, BURLINGAME, CA, 94010			S113758618
▼ N47	W 1/10 - 1/3	(948 ft. / 0.179 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Lower Elevation	28 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000005179
Latitude:	37.580006
Longitude:	-122.351129
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	01/29/2014
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
LOC Case Number:	660112
File Location:	Local Agency
Potential Media Affect:	Not Reported
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000005179

Contact:

Global Id:	T10000005179
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T10000005179
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

ARLINGTON APARTMENTS, 1401 FLORIBUNDA, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T10000005179
Status:	Completed - Case Closed
Status Date:	01/29/2014
Global Id:	T10000005179
Status:	Open - Case Begin Date
Status Date:	06/05/2013
Global Id:	T10000005179
Status:	Open - Eligible for Closure
Status Date:	10/02/2013

Regulatory Activities:

Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	10/23/2013
Action:	Notice of Responsibility - #20131023
Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	11/07/2013
Action:	Notification - Preclosure - #20131107
Global Id:	T10000005179
Action Type:	Other
Date:	06/05/2013
Action:	Leak Discovery
Global Id:	T10000005179
Action Type:	Other
Date:	06/11/2013
Action:	Leak Reported
Global Id:	T10000005179
Action Type:	ENFORCEMENT
Date:	01/29/2014
Action:	Closure/No Further Action Letter - #20140129

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0043363
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0073857
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

UST SITE 200 PARK, BURLINGAME, CA, 94010			S113758908
▲ L48	SE 1/10 - 1/3	(950 ft. / 0.18 mi.)	Other Standard Environmental Records
	5 ft. Higher Elevation	37 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0048379
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0066115
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

200 PARK 200 PARK ROAD, BURLINGAME, CA, 94010			S112141896
▲ L49	SE 1/10 - 1/3	(950 ft. / 0.18 mi.)	State and tribal leaking storage tank lists
	5 ft. Higher Elevation	37 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T10000004152
Latitude:	37.5774101
Longitude:	-122.3457145
Case Type:	LUST Cleanup Site
Status:	Open - Assessment & Interim Remedial Action
Status Date:	06/25/2012
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	MEJ
Local Agency:	Not Reported
RB Case Number:	41-1312
LOC Case Number:	Not Reported
File Location:	Not Reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline, Total Petroleum Hydrocarbons (TPH)
Site History:	The Site is located at the north corner of the intersection of Howard Avenue and Park Road in downtown Burlingame, California was previously the location of the former Pitts Nelson Service Station. Historic City directories show that the 200 Park Road property operated as a gasoline service station from at least 1930 to no later than 1961. The property has since been redeveloped and includes an 80 by 100 foot multi-story commercial building that roughly occupies the entire footprint of the property. A 500-1,000 gallon underground storage tank was closed in place by RRM Inc. in March 2011. (Low Threat Closure Policy Assessment and Proposed Workplan to Address Remaining Potential Environmental Impacts related to a Former Underground Fuel Storage Tank, March 31, 2015)
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T10000004152

Contact:

200 PARK, 200 PARK ROAD, BURLINGAME, CA 94010 (Continued)

Global Id:	T10000004152
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not Reported

Status History:

Global Id:	T10000004152
Status:	Open - Assessment & Interim Remedial Action
Status Date:	06/25/2012
Global Id:	T10000004152
Status:	Open - Case Begin Date
Status Date:	01/01/2012

Regulatory Activities:

Global Id:	T10000004152
Action Type:	ENFORCEMENT
Date:	10/22/2012
Action:	Staff Letter
Global Id:	T10000004152
Action Type:	RESPONSE
Date:	04/07/2015
Action:	Interim Remedial Action Plan - Regulator Responded
Global Id:	T10000004152
Action Type:	ENFORCEMENT
Date:	07/23/2012
Action:	Staff Letter
Global Id:	T10000004152
Action Type:	ENFORCEMENT
Date:	10/19/2012
Action:	Staff Letter
Global Id:	T10000004152
Action Type:	Other
Date:	01/01/2012
Action:	Leak Discovery
Global Id:	T10000004152
Action Type:	Other
Date:	01/01/2012
Action:	Leak Reported
Global Id:	T10000004152
Action Type:	RESPONSE
Date:	04/16/2012

200 PARK, 200 PARK ROAD, BURLINGAME, CA 94010 (Continued)

Action:	Other Report / Document
Global Id:	T10000004152
Action Type:	Other
Date:	01/01/2012
Action:	Leak Began

HARRIS PROPERTY 1234 HOWARD, BURLINGAME, CA, 94010		S100234001	
▲ L50	SE 1/10 - 1/3	(959 ft. / 0.182 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100253
Latitude:	37.577708
Longitude:	-122.344647
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	08/01/1989
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	MEJ
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0265
LOC Case Number:	Not Reported
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from RRM's March 17, 2010, Second Semi-annual 2009 remediation Performance and Groundwater Monitoring Report. San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. Evidence of subsurface fuel contamination at the 1234 Howard Avenue site was discovered in May 1989 during the removal of a 1,000gallon gasoline UST. Evidence of subsurface contamination at the 1200 Howard Avenue site was discovered in June 1994 during subsurface investigations associated with the 1234 Howard Avenue site. Site investigations conducted between 1994 and 1998 revealed a commingled plume of gasolineimpacted groundwater projecting southeast from the two properties. The plume crosses Howard Avenue and impacts a portion of the city block bounded by Howard, Lorton, and Park Avenues. Impacted properties include three commercial properties on

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

Howard Avenue (1201, 1205, and 1209 Howard Avenue); a portion of the Colewood Apartment complex at 137 Lorton Avenue; and a portion of the City of Burlingame public parking lot at 130 Park Avenue. As of 1999, dissolved total petroleum hydrocarbon concentrations as gasoline (TPHg) within the center of the plume exceeded 100,000 parts per billion (ppb) and separatephase hydrocarbons (SPH) on the water table surface at some locations. The groundwater table ranges seasonally between approximately 10 feet and 20 feet bgs; the soil column within this zone is also impacted. To provide a practical approach to remediate the area impacted with petroleum hydrocarbons, RRM divided the commingled plume into three sections for the purpose of addressing each section in phases as follows: Phase 1: Up to January 1997, the plume section under remediation was the portion beneath the former police station fuel UST and pump island (1234 Howard Avenue). This included the installation of an extraction well network and a treatment compound located to the northwest (rear) of the 1234 Howard Avenue property that was started up in June 1996 (Crisafi treatment compound). Phase 2: In 1997, RRM completed installation of an extraction well network for the second phase of work, which encompasses the area of the former fuel UST at 1200 Howard Avenue. The zone between 1234 Howard Avenue, and 1200 Howard Avenue; the remediation system was reactivated on July 15, 1997. Phase 3: In 19992000, RRM completed installation of an extraction well network for the third phase of work, which encompasses the area on the southeastern side of Howard Avenue (across the street from 1200 and 1234 Howard Avenues). At that time, RRM constructed a second treatment compound in the public parking lot located on the south side of Howard Avenue between Park Road and Lorton Avenue (Shaffer treatment compound). The second remediation system was activated on October 3, 2000. Collectively, the remediation well network includes 32 coextraction wells and 33 sparging wells. The treatment system compounds include the following unit processes: (1) the coextraction systems utilize regenerative blowers for the purpose of creating negative pressure gradients on the unsaturated andsaturated zones beneath the surface via the coextraction wells; (2) the extracted vapors are abated through the use of catalytic incinerators prior to atmospheric discharge; (3) the extracted groundwater is treated with

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

granular activated carbon prior to discharge to the sanitary sewer; (4) the air sparging systems utilize air compressors to inject air beneath the water table for the purpose of stripping volatiles and providing oxygen to groundwater in order to promote aerobic biodegradation of dissolved petroleum hydrocarbons; and, (3) at 1234 Howard Avenue, ozone sparging was initiated in November 2001. This process utilizes the existing sparging well network to deliver ozone to the groundwater for the purpose of chemically oxidizing dissolved petroleum hydrocarbons. As established in 19941997, the objectives of the interim site remediation program were: 1. As a priority, remove any residual SPH layers and mitigate all potential human health impacts associated with vaporphase migration of volatile gasoline constituents. 2. Meet department of Health Services maximum contaminant levels (MCLs) for benzene, toluene, ethylbenzene, and xylenes (collectively BTEX) in groundwater. 3. Meet the tentative TPHg cleanup goal for soil of 100 parts per million (ppm). 4. Cleanup petroleum impacted soils and groundwater to the extent practical, using commercially proven control technologies that best represent the current state of the art for cost effective LUFT site remediation. If such technologies prove incapable of meeting MCLs for groundwater, then reduce concentrations to an asymptotic level and/or riskbased corrective action levels. 5. Implement the program in a manner that avoids or minimizes to the greatest extent possible, any disruptions to the normal course of business on all affected properties. This includes, but is not limited to, compliance with the noise control ordinance of The City of Burlingame and careful consideration in scheduling constructionrelated work activities such as the installation of wells, piping, drainage, electrical service, and water or sewer service. Due to the pronounced seasonal fluctuations of the shallow groundwater table, RRM has limited spargingenhanced soil vapor extraction (SESVE) system operations to approximately sixmonth intervals, operating from approximately July through January. During the winter, spring, and early summer, the high water table conditions close the screened intervals of the extraction wells. The CAP approved by the County on June 3, 2005, calls for meeting the San Francisco Bay Regional Water Quality Control Boards (RWQCB) environmental screening levels (ESLs) for TPHg

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

and benzene by upgrading and expanding SESVE system. The upgrades include the following work all of which has been completed as of the third quarter 2007 except for replacement of sparging well SP3A and installation of ozone sparging unit processes: 1. Remove the treatment compound from 1234 Howard Avenue and replace it with a satellite ozonesparging system. The satellite ozonesparging system will serve the existing/expanded sparging well network on the north side of Howard Avenue and will be enclosed in a custom designed enclosure with a leakdetection/autoshutoff system. The system will also be designed/installed to shut down under lowvacuum conditions in the vapor extraction conveyance lines. RRM is currently recommending the installation of a satellite airsparging system (25 HP rotary screw air compressor) in lieu of the originally proposed satellite ozone sparging system. 2. Connect the existing/expanded extractionwell network on the north side of Howard Avenue to the extractionwell network on the south side of Howard Avenue by running subsurface conveyance piping across Howard Avenue. 3. Upgrade the remediation equipment in the existing treatment compound located in the City parking lot on the south side of Howard Avenue to include either reconfiguring the exiting vacuum pump to operate at higher vacuum or replacing it with a highvacuum liquidring pump. RRM originally proposed conducting some quick performance testing to help decide between the two options, but ultimately recommended replacing the existing pump assembly with a 400 standard cubic feet per minute (scfm) capacity clawtype vacuum pump capable of operating efficiently under both high and low vacuum conditions. 4. Install six additional extraction wells to provide complete coverage of the heavily impacted area of soil and groundwater (50,000 ppb TPHg contour) including three new wells to the south of Howard Avenue and three new wells to the north of Howard to include at least one interior well at 1200 Howard subject to the approval of the owner. In addition, existing monitoring well MW7 on the south side of Howard is to be connected into the system. Three interior vapor extraction wells were ultimately installed inside 1200 Howard based on the large amount of contamination encountered. 5. Install fourteen additional air/ozonesparging wells to provide complete coverage of the heavily impacted area of groundwater (50,000 ppb TPHg contour) including

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

eight new wells to the south of Howard Avenue and six new wells to the north of Howard to include at least one interior well at 1200 Howard subject to the approval of the owner. This includes the replacement of existing sparge well SP3A located in the basement of 1234 Howard. Three interior sparge wells were ultimately installed inside 1200 Howard based on the large amount of contamination encountered. 6. Complete slabinstallation work at 1234 Howard and install additional slabventing systems for the commercial buildings at 1200 Howard, 1209 Howard, and the northern half of 1201 Howard. Slabventing system have already been installed at 1205 Howard and 127 Lorton Avenue and are working well. The slabventing systems will provide insurance that fugitive vapors will not enter buildings during the period of active remediation.

Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100253

Contact:

Global Id:	T0608100253
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not Reported

Global Id:	T0608100253
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100253
Status:	Open - Case Begin Date
Status Date:	08/01/1989

Global Id:	T0608100253
Status:	Open - Remediation
Status Date:	08/01/1989

Regulatory Activities:

Global Id:	T0608100253

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

Action Type:	RESPONSE
Date:	08/15/2011
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	06/01/1990
Action:	Notice of Responsibility - #1
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	02/15/2010
Action:	Other Report / Document
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	10/15/2011
Action:	Site Assessment Report
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	02/15/2010
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	Other
Date:	08/01/1989
Action:	Leak Discovery
Global Id:	T0608100253
Action Type:	Other
Date:	10/10/1989
Action:	Leak Reported
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	09/18/2009
Action:	Other Workplan
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	08/15/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	04/29/2010
Action:	Staff Letter - #20100429
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	08/15/2010
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

Action Type:	REMEDIATION
Date:	10/01/1996
Action:	Soil Vapor Extraction (SVE)
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	06/08/2011
Action:	Staff Letter - #20110608
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	11/15/2007
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	02/15/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	REMEDIATION
Date:	10/01/1996
Action:	Pump & Treat (P&T) Groundwater
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	03/26/2009
Action:	Staff Letter - #20090326
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	05/24/2007
Action:	Staff Letter - #20070524
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	07/30/2010
Action:	Other Workplan - Regulator Responded
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	05/15/2008
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	03/09/2011
Action:	Staff Letter - #20110309
Global Id:	T0608100253
Action Type:	RESPONSE
Date:	02/15/2011
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100253

HARRIS PROPERTY, 1234 HOWARD, BURLINGAME, CA 94010 (Continued)

Action Type:	ENFORCEMENT
Date:	10/14/2009
Action:	Staff Letter - #20091014
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	07/07/2009
Action:	Staff Letter - #20090707
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	10/20/2009
Action:	Letter - Notice - #20091020
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	09/21/2011
Action:	Referral to Regional Board - #20110921
Global Id:	T0608100253
Action Type:	ENFORCEMENT
Date:	04/01/2011
Action:	Staff Letter - #20110401

LUST REG 2:

Region:	2
Facility Id:	Not Reported
Facility Status:	Remedial action (cleanup) Underway
Case Number:	660036
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	1/1/1965
Date Post Remedial Action Monitoring Began:	Not Reported

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0265

KING YEE PROPERTY 1200 HOWARD, BURLINGAME, CA, 94010		S102432235	
▲ L51	SE 1/10 - 1/3	(975 ft. / 0.185 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100813
Latitude:	37.577876
Longitude:	-122.344407
Case Type:	LUST Cleanup Site
Status:	Open - Remediation
Status Date:	03/03/1994
Lead Agency:	SAN FRANCISCO BAY RWQCB (REGION 2)
Case Worker:	MEJ
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0871
LOC Case Number:	Not Reported
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Excerpts extracted from RRM's March 19, 2010, second semi-annual 2009 groundwater monitoring report. San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. Beginning with the fourth quarter 2001, the activities for the 1200 Howard Avenue site and the 1234 Howard Avenue site are combined into one section, which include the twocoextraction/air sparging systems. The activities completed from January 2002 through 2008 are summarized below. 1. Attended a site meeting on January 16, 2002; representatives of the SMCHSA were present. During the meeting, water levels were gauged and an inspection was made in the basement of the restaurant at 1205 Howard Avenue in response to complaints of odors. Pursuant to the resolves of the meeting, the SESVE system serving the 1205 Howard Avenue area (the Shaffer treatment compound) was

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

deactivated due to high water table conditions and concerns regarding migrant vapors. 2. Initiated an ozone sparging pilot test at 1234 Howard Avenue on February 5, 2002. RRM conducted biweekly grab groundwater sampling of wells MW1, MW2, MW3, EW3, EW4, EW5, EW6, EW7, EW8, EW9, EW10, PSB4, and PSB5 on November 29, 2001, December 26, 2001, January 10, 2002, and January 28, 2002. 3. Initiated an ozone sparging pilot test followup groundwater monitoring event on February 15, 2002, ten days after shut down of the combined ozonesparging enhanced SVE system on February 5, 2002 using the same wells incorporated into the biweekly groundwater sampling program. 6. Performed soil vapor sampling at two locations to the rear of the restaurant property at 1205 Howard Avenue on February 1, 2002 to evaluate the potential inhalation risk to residents of the apartment complex at 137 Lorton Avenue. 11. Initiated remediation system operations at 1200 Howard Avenue on July 10, 2002 and at 1234 Howard Avenue on July 9, 2002. Began ozone sparging at 1234 Howard Avenue on July 22, 2002. 12. Between July 22, 2002 and August 30, 2002, ozone was sparged into wells EW4 through EW8 for 30 minutes every hour. From August 30, 2002 through December 30, 2002, ozone was sparged into wells EW4, EW7, EW8, and SP1 through SP4 for 30 minutes every hour. Conducted approximately six months of routine remediation system operation and maintenance at the 1200 Howard Avenue and 1234 Howard Avenue sites through mid January 2003 and December 30, 2002, respectively. Tasks included: system performance optimization; measurement of operating parameters; measurement of extracted soil vapor concentrations before and after treatment using a field instrument equipped with an FID; collection of influent and effluent soil vapor samples (contained in Tedlar bags), collection of groundwater treatment system samples, and completion of field reports. Soil vapor and groundwater samples were analyzed for TPHg and BTEX by Entech Analytical Labs, Inc. 15. Installed groundwatermonitoring wells MW9 and MW10 on April 14, 2003. Installed groundwatermonitoring well MW11 on August 15, 2003. Installed slabvapor recovery systems at 1205 Howard Avenue, and at 137 Lorton Avenue during the third and fourth quarters 2003 with the aid of Max Llanos Construction, Inc. of Poway, California. Also during this period, upgraded the basement ventilation system at 1234 Howard

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Avenue in lieu of installing a slab venting system. 27. Deactivated the remediation system at 1200 Howard Avenue (Shaffer treatment compound) on January 21, 2004. 55. During October 2005 trenched, plumbed and connected seven (7) new sparge wells (SP15 through SP21) and four (4) new vapor extraction wells (EW23 through EW26) installed south of Howard Avenue to the existing SVE treatment system. 56. In October 2005 the original vacuum pump and motor associated with the Thermtech Thermal Oxidizer unit was changedout. Procedures included removal of the old blower and motor, fabrication of a new motor mount, retrofitting the intake and exhaust piping manifold, installation of a highvolume air filter, rewiring the power supply, replacing the knockout tank, and finally mounting the new blower and motor assembly that consisted of a Rietschle Corporation Zephyr VLR 400 highefficiency 400scfm vacuum pump. 57. The SVE and air sparging unit processes were restarted on November 2, 2005 and operated near continuously through December 2005. During this period operations were cycled through three sections of the well field on the south side of Howard Avenue at approximately twoweek intervals to maximize mass removal. 62. Drilled and constructed air sparge (SP23 through SP24) and soil vapor extraction (EW27 through EW29) wells inside the building located at 1200 Howard Avenue during February 2006. Also performed underground work to plumb new wells to the existing AS and SVE subsurface piping network. 63. Developed, sampled and surveyed for elevation wells EW27 and EW28 on February 8 and 9, 2006. 64. The slab venting system installed at 1234 Howard Avenue underwent initial startup operations on February 1 and 2, 2006. 65. Continually operated the slab venting systems located at 1200, 1201, 1205 and 1209 Howard Avenue and 137 Lorton Avenue from January through March 2006. Collected compliance airbag samples of the effluent at 1200, 1201, and 1209 Howard Avenue on a monthly basis. 81. In January 2007, RRM installed the remaining air sparge well proposed in RRMs May 31, 2005 Corrective Action Implementation Workplan as well as one additional vapor extraction well in the vicinity of existing sparge well SP18. The additional sparge well was installed on the south side of Howard Avenue in front of the alleyway separating the buildings at 1205 and 1209 Howard. The new well locations were plumbed to the existing SVE conveyancepiping system. 82. On March 30, 2007, RRM

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

attended a meeting called by the City of Burlingame Building Department at the apartment complex located at 125/129 Lorton Avenue. The City called this meeting in response to complaints they had received from the property manager regarding gasoline odors in the garage and an apartment overlying the garage as well as foultasting tap water. The meeting was attended by a City of Burlingame representative, the property manager, several of the building owners, and the Court Consultant/Project Coordinator, Brian Kelleher. During the course of the meeting, RRM inspected the garage and a crawl space under the west side of the building in the presence of all parties, and took field measurements of total volatile hydrocarbons using a photoionization detector (PID). There were no detectable hydrocarbon odors or PID readings. RRM observed that there was a large hole in the ceiling of the garage surrounding a sewer drain line that would allow any exhaust fumes in the garage to enter the apartment located above the garage. RRM also collected a sample of the tap water and submitted it for certified analyses. RRM is preparing a separate report covering the site visit and test findings to include conclusions and recommendations. The property owners resolved to make immediate repairs to the ceiling of the garage. During the start of the meeting, the property manager had indicated that the fumes entering the apartment above the garage appeared to be entering from the area of the sewer drain lines. During the second and third quarters 2007, the SVE system removed and combusted approximately 3,578 pounds of gasoline vapors bringing the total mass removed to date to approximately 23,083 pounds. Through the end of September 2007, the average gasoline vapor removal rate was approximately 38.5 pounds per day. The system operated a total of 93 days during the second and third quarters 2007. 98. During the second, third, and fourth quarter 2008, RRM continued routine operation of the slab venting systems located at 1200, 1201, 1205, 1209, and 1234 Howard Avenue and 137 Lorton Avenue. RRM collected quarterly compliance airbag samples of the effluent from these systems during the months of June 2008, September 2008, and December 2008. In addition to compliance sampling, RRM performed monthly site visits to measure and record amp usage, discharge airflow, and hourmeter readings.

Click here to access the California GeoTracker records for this facility: http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100813

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Contact:

Global Id:	T0608100813
Contact Type:	Regional Board Caseworker
Contact Name:	MARK JOHNSON
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY STREET, SUITE 1400
City:	OAKLAND
Email:	mjohnson@waterboards.ca.gov
Phone Number:	Not Reported

Global Id:	T0608100813
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100813
Status:	Open - Case Begin Date
Status Date:	03/03/1994

Global Id:	T0608100813
Status:	Open - Remediation
Status Date:	03/03/1994

Regulatory Activities:

Global Id:	T0608100813
Action Type:	RESPONSE
Date:	08/15/2011
Action:	Monitoring Report - Semi-Annually

Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	04/07/2005
Action:	Staff Letter - #20050407

Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	05/24/2007
Action:	Staff Letter - #20070524

Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	06/22/2005
Action:	Staff Letter - #20050622

Global Id:	T0608100813
Action Type:	ENFORCEMENT

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Date:	05/24/2005
Action:	Staff Letter - #20050524
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	06/26/2001
Action:	Staff Letter - #20010626
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	03/15/1994
Action:	Notice of Responsibility - #1
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	02/15/2010
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	10/20/2009
Action:	Letter - Notice - #20091020
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	11/15/2007
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	09/18/2009
Action:	Other Workplan
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	10/15/2011
Action:	Site Assessment Report
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	08/15/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	01/15/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	07/15/2008
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100813
Action Type:	Other

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Date:	03/03/1994
Action:	Leak Discovery
Global Id:	T0608100813
Action Type:	REMEDIATION
Date:	10/14/1996
Action:	Pump & Treat (P&T) Groundwater
Global Id:	T0608100813
Action Type:	REMEDIATION
Date:	10/03/2000
Action:	Soil Vapor Extraction (SVE)
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	02/15/2010
Action:	Other Report / Document
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	04/29/2010
Action:	Staff Letter - #20100429
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	09/21/2011
Action:	Referral to Regional Board - #20110921
Global Id:	T0608100813
Action Type:	Other
Date:	03/03/1994
Action:	Leak Reported
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	08/15/2010
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	03/26/2009
Action:	Staff Letter - #20090326
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	03/09/2011
Action:	Staff Letter - #20110309
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	08/15/2003
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Date:	02/15/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	05/15/2005
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	02/15/2006
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	11/15/2006
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	02/15/2007
Action:	Monitoring Report - Quarterly
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	04/14/2004
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	06/02/2005
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	06/21/2005
Action:	Other Workplan
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	07/19/2005
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	10/18/2005
Action:	CAP/RAP - Other Report
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	02/12/2004
Action:	Staff Letter - #20040212
Global Id:	T0608100813
Action Type:	ENFORCEMENT

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

Date:	04/12/2005
Action:	Staff Letter - #20050412
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	07/30/2010
Action:	Other Workplan - Regulator Responded
Global Id:	T0608100813
Action Type:	RESPONSE
Date:	02/15/2011
Action:	Monitoring Report - Semi-Annually - Regulator Responded
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	10/14/2009
Action:	Staff Letter - #20091014
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	07/07/2009
Action:	Staff Letter - #20090707
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	04/01/2011
Action:	Staff Letter - #20110401
Global Id:	T0608100813
Action Type:	ENFORCEMENT
Date:	06/08/2011
Action:	Staff Letter - #20110608

LUST REG 2:

Region:	2
Facility Id:	Not Reported
Facility Status:	Remedial action (cleanup) Underway
Case Number:	660070
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	1/1/1965
Date Post Remedial Action Monitoring Began:	Not Reported

KING YEE PROPERTY, 1200 HOWARD, BURLINGAME, CA 94010 (Continued)

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0871

BERENSTEIN ASSOC. PROPERTY 1319 HOWARD, BURLINGAME, CA, 94010			S106131260
▲ L52	SSE 1/10 - 1/3	(997 ft. / 0.189 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	6 ft. Higher Elevation	38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

SAN MATEO CO. LUST: State and tribal leaking storage tank lists

Region:	SAN MATEO
Facility ID:	669096
Facility Status:	5R- Remediation Plan
Global ID:	T0608186803
APN Number:	029222040
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

SLIC: State and tribal leaking storage tank lists

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	10/19/2005
Global Id:	T0608186803
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669096
Latitude:	37.5766905377104
Longitude:	-122.345870286226
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
File Location:	Local Agency
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Extracted from RRM's April 22, 2010 Additional Site Investigation Results, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is occupied by a two-story building located at 1319 Howard Avenue in Burlingame, California. The building is approximately 45 feet wide by 100 feet long and is constructed with reinforced concrete walls, concrete floors, and flat

BERENSTEIN ASSOC. PROPERTY, 1319 HOWARD, BURLINGAME, CA 94010 (Continued)

pitch-tar and gravel roofing. The first floor, a former dry cleaning facility (Caine Cleaners), is currently vacant. The second floor, built above the front half of the building only, is occupied by an architectural design firm. The facade of the building is mostly plate glass and opens up onto the sidewalk adjacent to Howard Avenue. The rear of the building abuts asphalt-paved parking areas owned by the City of Burlingame and Bank of the West. Soil and groundwater beneath the site is known to be impacted with PCE. Soil excavation activities were completed in 2007 to remove PCE impacted soils beneath the former cleaning machinery and floor drain area inside the building to a depth of approximately 25 feet below ground surface (bgs).

Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_SLIC_ST&global_id=T0608186803

HAZNET: Other Standard Environmental Records

envid:	S106131260
Year:	2013
GEPAID:	CAR000233643
Contact:	MATT KAEMPF
Telephone:	8314758141
Mailing Name:	Not Reported
Mailing Address:	1319 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104212
Gen County:	San Mateo
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles
Waste Category:	Not Reported
Disposal Method:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.35
Cat Decode:	Not Reported
Method Decode:	Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Facility County:	Not Reported

MAP FINDINGS

CAINE CLEANERS 1321 HOWARD, BURLINGAME, CA, 940100000		S102267661
▲ L53	SSE 1/10 - 1/3 (997 ft. / 0.189 mi.)	Other Standard Environmental Records
	6 ft. Higher Elevation 38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

DRYCLEANERS: Other Standard Environmental Records

EPA Id:	CAL000017479
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	11/14/1989
Facility Active:	No
Inactive Date:	Not Reported
Facility Addr2:	Not Reported
Owner Name:	KIL HYON, CHUNG
Owner Address:	--
Owner Address 2:	Not Reported
Owner Telephone:	0000000000
Contact Name:	KIL HYON, CHUNG
Contact Address:	1321 HOWARD AVE
Contact Address 2:	Not Reported
Contact Telephone:	--
Mailing Name:	Not Reported
Mailing Address 1:	1321 HOWARD AVE
Mailing Address 2:	Not Reported
Mailing City:	BURLINGAME
Mailing State:	CA
Mailing Zip:	940100000
Owner Fax:	2
Region Code:	Not Reported

CAINE CLEANERS 1321 HOWARD, BURLINGAME, CA, 94010			S113755375
▲ L54	SSE 1/10 - 1/3	(997 ft. / 0.189 mi.)	Other Standard Environmental Records
	6 ft. Higher Elevation	38 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0007336
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011889
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0007336
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004670
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

STERLING CLEANERS 1140 HOWARD AVENUE, BURLINGAME, CA, 94010		S113756634	
▲ M55	ESE 1/10 - 1/3	(1010 ft. / 0.191 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	4 ft. Higher Elevation	36 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist
Conditions:

Chemicals of Concern: YES
Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES
Geological Attributes - Soil Geology:

Other: YES

SAN MATEO CO. LUST: State and tribal leaking storage tank lists

Region:	SAN MATEO
Facility ID:	669111
Facility Status:	3B- Preliminary Assessment Underway
Global ID:	T10000006541
APN Number:	029211130
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018042
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011857
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0018042
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004614
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

SLIC: State and tribal leaking storage tank lists

Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	03/10/2015
Global Id:	T10000006541
Lead Agency:	SAN MATEO COUNTY LOP
Lead Agency Case Number:	669116
Latitude:	37.578388

STERLING CLEANERS, 1140 HOWARD AVENUE, BURLINGAME, CA 94010 (Continued)

Longitude:	-122.3445489
Case Type:	Cleanup Program Site
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	Not Reported
File Location:	Not Reported
Potential Media Affected:	Not Reported
Potential Contaminants of Concern:	Tetrachloroethylene (PCE)
Site History:	Case opened 2015, no signed RAA, out of compliance (6/18/2015)
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_SLIC_ST&global_id=T10000006541

MAP FINDINGS

STERLING CLEANERS 1140 HOWARD AVE, BURLINGAME, CA, 94010		1000364529
▲ M56	ESE 1/10 - 1/3 (1010 ft. / 0.191 mi.) 4 ft. Higher Elevation 36 ft. Above Sea Level	Federal RCRA generators list Other Standard Environmental Records

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

ECHO: Other Standard Environmental Records

Envid:	1000364529
Registry ID:	110001153796
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110001153796

FINDS: Other Standard Environmental Records

Registry ID:	110001153796

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RCRA-SQG: Federal RCRA generators list

Date form received by agency:	09/01/1996
Facility name:	STERLING CLEANERS
Facility address:	1140 HOWARD AVE BURLINGAME, CA 94010
EPA ID:	CAD981632094
Contact:	Not Reported
Contact address:	Not Reported
Contact country:	US
Contact telephone:	Not Reported
Contact email:	Not Reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CHARLES KIM

STERLING CLEANERS, 1140 HOWARD AVE, BURLINGAME, CA 94010 (Continued)

Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not Reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not Reported
Owner/Op end date:	Not Reported
Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED NOT REQUIRED, ME 99999
Owner/operator country:	Not Reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not Reported
Owner/Op end date:	Not Reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	12/09/1986
Site name:	STERLING CLEANERS
Classification:	Large Quantity Generator
Violation Status:	No violations found

HAZNET: Other Standard Environmental Records



envid:	1000364529
Year:	1997
GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605

STERLING CLEANERS, 1140 HOWARD AVE, BURLINGAME, CA 94010 (Continued)

Mailing Name:	Not Reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not Reported
TSD EPA ID:	CA0000084517
TSD County:	Not Reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.8775
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000364529
Year:	1996
GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605
Mailing Name:	Not Reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not Reported
TSD EPA ID:	CA0000084517
TSD County:	Not Reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	1.1700
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000364529
Year:	1996
GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605
Mailing Name:	Not Reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not Reported
TSD EPA ID:	CAO000084517
TSD County:	Not Reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	.1950
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo
envid:	1000364529
Year:	1995

STERLING CLEANERS, 1140 HOWARD AVE, BURLINGAME, CA 94010 (Continued)

GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605
Mailing Name:	Not Reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not Reported
TSD EPA ID:	CAT000613950
TSD County:	Not Reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	1.0725
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

envid:	1000364529
Year:	1994
GEPAID:	CAD981632094
Contact:	STERLING CLEANERS
Telephone:	4153433605
Mailing Name:	Not Reported
Mailing Address:	1140 HOWARD AVE
Mailing City,St,Zip:	BURLINGAME, CA 940104226
Gen County:	Not Reported
TSD EPA ID:	CAT000613893
TSD County:	Not Reported
Waste Category:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	Transfer Station
Tons:	2.2050
Cat Decode:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Decode:	Transfer Station
Facility County:	San Mateo

The CA_HAZNET database contains 3 additional records for this site. Please contact your EDR Account Executive for more information.

DRYCLEANERS: Other Standard Environmental Records

EPA Id:	CAL000215134
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	01/19/2000
Facility Active:	No
Inactive Date:	Not Reported
Facility Addr2:	Not Reported
Owner Name:	STERLING CLEANERS INC
Owner Address:	1140 HOWARD AVE
Owner Address 2:	Not Reported
Owner Telephone:	6503433605
Contact Name:	DAVID PLACK/PRESIDENT

STERLING CLEANERS, 1140 HOWARD AVE, BURLINGAME, CA 94010 (Continued)

Contact Address:	1140 HOWARD AVE
Contact Address 2:	Not Reported
Contact Telephone:	6503430125
Mailing Name:	Not Reported
Mailing Address 1:	7076 FAIRWAY PL
Mailing Address 2:	Not Reported
Mailing City:	CARMEL
Mailing State:	CA
Mailing Zip:	93923
Owner Fax:	2
Region Code:	0000000000

BURLINGAME VALERO 601 CALIFORNIA, BURLINGAME, CA, 94010			S113756614
▼ O57	NW 1/10 - 1/3	(1023 ft. / 0.194 mi.)	Other Standard Environmental Records
	8 ft. Lower Elevation	24 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018003
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023920
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018003
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0004632
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018003
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022776
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

SHELL 601 CALIFORNIA, BURLINGAME, CA, 94010			S105194473
▼ O58	NW 1/10 - 1/3	(1023 ft. / 0.194 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	8 ft. Lower Elevation	24 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660017
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0059026
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0081735
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0059026
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0081734
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0059026
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0081737

SHELL, 601 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Description:	UNDERGROUND TANK - GENERAL
Facility Status:	ACTIVE

SHELL 601 CALIFORNIA, BURLINGAME, CA, 94010			S100931284
▼ O59	NW 1/10 - 1/3	(1023 ft. / 0.194 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	8 ft. Lower Elevation	24 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100487
Latitude:	37.581697
Longitude:	-122.350487
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	10/10/1991
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0511
LOC Case Number:	660017
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100487

Contact:

Global Id:	T0608100487
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100487
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

SHELL, 601 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T0608100487
Status:	Completed - Case Closed
Status Date:	10/10/1991
Global Id:	T0608100487
Status:	Open - Case Begin Date
Status Date:	10/21/1986

Regulatory Activities:

Global Id:	T0608100487
Action Type:	Other
Date:	10/21/1986
Action:	Leak Discovery
Global Id:	T0608100487
Action Type:	Other
Date:	10/21/1986
Action:	Leak Reported
Global Id:	T0608100487
Action Type:	ENFORCEMENT
Date:	10/10/1991
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660017
Facility Status:	9- Case Closed
Global ID:	T0608100487
APN Number:	029131380
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0511

PACIFIC BELL 1480 BURLINGAME AVENUE, BURLINGAME, CA, 94010			1000251378
▲ K60	SSW 1/10 - 1/3	(1047 ft. / 0.198 mi.)	Federal RCRA generators list State and tribal leaking storage tank lists Other Standard Environmental Records
	9 ft. Higher Elevation	41 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

FINDS: Other Standard Environmental Records

Registry ID: 110055778724

Environmental Interest/Information System:

STATE MASTER

Registry ID: 110002950487

Environmental Interest/Information System:

AIR EMISSIONS CLASSIFICATION UNKNOWN

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RCRA-SQG: Federal RCRA generators list

Date form received by agency: 09/01/1996
Facility name: PACIFIC BELL
Facility address: 1480 BURLINGAME AVENUE
BURLINGAME, CA 94010

EPA ID: CAT080022270
Mailing address: 2 NORTH SECOND ST ROOM 1125
SAN JOSE, CA 95113

Contact: Not Reported
Contact address: Not Reported
Contact country: US
Contact telephone: Not Reported
Contact email: Not Reported
EPA Region: 09
Classification: Small Small Quantity Generator

PACIFIC BELL, 1480 BURLINGAME AVENUE, BURLINGAME, CA 94010 (Continued)

Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	THE PACIFIC TELEPHONE AND TELEGRAPH CO
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not Reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not Reported
Owner/Op end date:	Not Reported
Owner/operator name:	NOT REQUIRED
Owner/operator address:	NOT REQUIRED
	NOT REQUIRED, ME 99999
Owner/operator country:	Not Reported
Owner/operator telephone:	(415) 555-1212
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not Reported
Owner/Op end date:	Not Reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/19/1981
Site name:	PACIFIC BELL
Classification:	Large Quantity Generator
Violation Status:	No violations found

PACIFIC BELL, 1480 BURLINGAME AVENUE, BURLINGAME, CA 94010 (Continued)

ECHO: Other Standard Environmental Records

Envid:	1000251378
Registry ID:	110055778724
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110055778724
Envid:	1000251378
Registry ID:	110002950487
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002950487

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660023
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0396

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0017985
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0049364
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0017985
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004643
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

PACIFIC BELL, 1480 BURLINGAME AVENUE, BURLINGAME, CA 94010 (Continued)

Region:	SAN MATEO
Facility ID:	FA0017985
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022765
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	ACTIVE

PACIFIC BELL 1480 BURLINGAME AVE., BURLINGAME, CA, 94010			U001595280
▲ K61	SSW 1/10 - 1/3	(1047 ft. / 0.198 mi.)	State and tribal leaking storage tank lists State and tribal registered storage tank lists
	9 ft. Higher Elevation	41 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

UST: State and tribal registered storage tank lists

Facility ID:	41-000-022765
Permitting Agency:	SAN MATEO COUNTY
Latitude:	37.5767
Longitude:	-122.34977

SWEEPS UST: State and tribal registered storage tank lists

Status:	Active
Comp Number:	660034
Number:	9
Board Of Equalization:	44-001027
Referral Date:	03-24-94
Action Date:	03-24-94
Created Date:	10-13-88
Owner Tank Id:	92
SWRCB Tank Id:	41-000-660034-000001
Tank Status:	A
Capacity:	4000
Active Date:	03-24-94
Tank Use:	PETROLEUM
STG:	P
Content:	DIESEL
Number Of Tanks:	1

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100377
Latitude:	37.5767309
Longitude:	-122.3497364
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	07/09/1992
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM

PACIFIC BELL, 1480 BURLINGAME AVE., BURLINGAME, CA 94010 (Continued)

Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0396
LOC Case Number:	660023
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100377

Contact:

Global Id:	T0608100377
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100377
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100377
Status:	Completed - Case Closed
Status Date:	07/09/1992

Global Id:	T0608100377
Status:	Open - Case Begin Date
Status Date:	11/21/1985

Regulatory Activities:

Global Id:	T0608100377
Action Type:	ENFORCEMENT
Date:	06/08/1990
Action:	Notice of Responsibility - #1

Global Id:	T0608100377
Action Type:	Other
Date:	01/31/1986
Action:	Leak Discovery

Global Id:	T0608100377
Action Type:	Other

PACIFIC BELL, 1480 BURLINGAME AVE., BURLINGAME, CA 94010 (Continued)

Date:	11/21/1985
Action:	Leak Reported

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660023
Facility Status:	9- Case Closed
Global ID:	T0608100377
APN Number:	029122999
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST UST: State and tribal registered storage tank lists



File Number:	0002C129
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002C129.pdf
Region:	STATE
Facility ID:	00000036935
Facility Type:	Other
Other Type:	SIC 4800
Contact Name:	E.J. KOEHLER
Telephone:	4155426758
Owner Name:	PACIFIC BELL
Owner Address:	370 THIRD STREET
Owner City,St,Zip:	SAN FRANCISCO, CA 94107
Total Tanks:	0002
Tank Num:	001
Container Num:	D-XX-3K
Year Installed:	Not Reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not Reported
Leak Detection:	Pressure Test
Tank Num:	002
Container Num:	D-67-3K
Year Installed:	1967
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not Reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	D-67-3K
Year Installed:	1967
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL

PACIFIC BELL, 1480 BURLINGAME AVE., BURLINGAME, CA 94010 (Continued)

Container Construction Thickness:	Not Reported
Leak Detection:	None
Click here for Geo Tracker PDF:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_HISTUST_PDF&img_id=0002C129

T MOBILE WEST CORP SITE ID SF03108A 1480 BURLINGAME, BURLINGAME, CA, 94010			S113758727
▲ K62	SSW 1/10 - 1/3	(1047 ft. / 0.198 mi.)	Other Standard Environmental Records
	9 ft. Higher Elevation	41 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0045341
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0058977
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AT & T MOBILITY - CENTRAL BG #13300 1480 BURLINGAME, BURLINGAME, CA, 94010			S113758792
▲ K63	SSW 1/10 - 1/3	(1047 ft. / 0.198 mi.)	Other Standard Environmental Records
	9 ft. Higher Elevation	41 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0045945
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0061209
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

SBC 1480 BURLINGAME, BURLINGAME, CA, 94010			S113755294
▲ K64	SSW 1/10 - 1/3	(1047 ft. / 0.198 mi.)	Other Standard Environmental Records
	9 ft. Higher Elevation	41 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0005133
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0064366
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

UST SITE 1021 BURLINGAME, BURLINGAME, CA, 94010			S113758849
▼ P65	ENE 1/10 - 1/3	(1072 ft. / 0.203 mi.)	Other Standard Environmental Records
	4 ft. Lower Elevation	28 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0046818
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0063724
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

WALGREENS #86 1420 HOWARD, BURLINGAME, CA, 94010			S113758266
▲ Q66	S 1/10 - 1/3	(1073 ft. / 0.203 mi.)	Other Standard Environmental Records
	8 ft. Higher Elevation	40 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0032087
Prog Element Code:	BUSINESS PLAN - GENERAL
Record Id:	PR0066931
Description:	BUSINESS PLAN - GENERAL
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0032087
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0051849
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

BURLINGAME DIAGNOSTIC CTR 270 EAST, BURLINGAME, CA, 94010			S113756194
▼ P67	E 1/10 - 1/3	(1115 ft. / 0.211 mi.)	Other Standard Environmental Records
	2 ft. Lower Elevation	30 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0016125
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024505
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0016125
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0024506
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

SILVER AUTO SVC 270 EAST, BURLINGAME, CA, 94010			S113755774
▼ P68	E 1/10 - 1/3	(1115 ft. / 0.211 mi.)	Other Standard Environmental Records
	2 ft. Lower Elevation	30 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0012240
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024646
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012240
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0024645
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

D&R AUTO BODY & PAINT 270 EAST, BURLINGAME, CA, 94010			S113755775
▼ P69	E 1/10 - 1/3	(1115 ft. / 0.211 mi.)	Other Standard Environmental Records
	2 ft. Lower Elevation	30 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC Exists

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0012242
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024648
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0012242
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0024647
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

UST SITE 1100 HOWARD, BURLINGAME, CA, 94010			S113758802
▲ M70	ESE 1/10 - 1/3	(1127 ft. / 0.213 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0046061
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0061788
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

SHELL 1490 BURLINGAME, BURLINGAME, CA, 94010			S103892165
▲ K71	SSW 1/10 - 1/3	(1140 ft. / 0.216 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100468
Latitude:	37.5765782
Longitude:	-122.3499433
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	08/21/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0492
LOC Case Number:	660001
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100468

Contact:

Global Id:	T0608100468
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100468
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO

SHELL, 1490 BURLINGAME, BURLINGAME, CA 94010 (Continued)

Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100468
Status:	Completed - Case Closed
Status Date:	08/21/2001
Global Id:	T0608100468
Status:	Open - Case Begin Date
Status Date:	04/25/1988

Regulatory Activities:

Global Id:	T0608100468
Action Type:	Other
Date:	08/08/1988
Action:	Leak Discovery
Global Id:	T0608100468
Action Type:	Other
Date:	04/25/1988
Action:	Leak Reported
Global Id:	T0608100468
Action Type:	REMEDIATION
Date:	09/30/1993
Action:	Not Reported
Global Id:	T0608100468
Action Type:	ENFORCEMENT
Date:	01/31/1989
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660001
Facility Status:	9- Case Closed
Global ID:	T0608100468
APN Number:	029122360
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records



Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0492

SHELL 1490 BURLINGAME, BURLINGAME, CA, 94010			S105194454
▲ K72	SSW 1/10 - 1/3	(1140 ft. / 0.216 mi.)	State and tribal leaking storage tank lists
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660001
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

SHELL SERVICE STATION 1490 BURLINGAME, BURLINGAME, CA, 94010			S113756613
▲ K73	SSW 1/10 - 1/3	(1140 ft. / 0.216 mi.)	Other Standard Environmental Records
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018002
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022775
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

UST SITE 1101-07 HOWARD, BURLINGAME, CA, 94010			S113758801
▲ M74	ESE 1/10 - 1/3	(1148 ft. / 0.217 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0046060
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0061787
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

FOUR CAR GARAGE INC 609 CALIFORNIA, BURLINGAME, CA, 94010			S113755394
▼ O75	NW 1/10 - 1/3	(1152 ft. / 0.218 mi.)	Other Standard Environmental Records
	8 ft. Lower Elevation	24 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0007603
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011866
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0007603
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004666
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

SAFEWAY 1547 1450 HOWARD, BURLINGAME, CA, 94010		S113759038
▲ Q76	S 1/10 - 1/3 (1155 ft. / 0.219 mi.)	Other Standard Environmental Records
	10 ft. Higher Elevation 42 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0051396
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0071242
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0051396
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076051
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

RUPPELS AUTO FIXATION 260 EAST, BURLINGAME, CA, 94010			S113756627
▼ R77	E 1/10 - 1/3	(1156 ft. / 0.219 mi.)	Other Standard Environmental Records
	2 ft. Lower Elevation	30 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0018024
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011842
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018024
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004621
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0018024
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0070141
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

RUPPELS AUTO FIXATION 260 EAST, BURLINGAME, CA, 94010			S113759009
▼ R78	E 1/10 - 1/3	(1156 ft. / 0.219 mi.)	Other Standard Environmental Records
	2 ft. Lower Elevation	30 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0050716
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0070419
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0050716
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0070418
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

CHEVRON 9-0571 260 EL CAMINO REAL, BURLINGAME, CA, 94010		S105030425
▲ S79	SSW 1/10 - 1/3 (1170 ft. / 0.222 mi.) 11 ft. Higher Elevation 43 ft. Above Sea Level	State and tribal leaking storage tank lists

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Pollution Characterization
Case Number:	660046
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	1/1/1965
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

CURRIES CHEVRON STATION 260 EL CAMINO REAL, BURLINGAME, CA, 94010			S113756597
▲ S80	SSW 1/10 - 1/3	(1170 ft. / 0.222 mi.)	Other Standard Environmental Records
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0023079
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004694
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0017976
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022757
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	INACTIVE

WALGREENS #12257 260 EL CAMINO REAL, BURLINGAME, CA, 94010			S113758890
▲ S81	SSW 1/10 - 1/3	(1170 ft. / 0.222 mi.)	Other Standard Environmental Records
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0047974
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0065591
Description:	GENERATES <27 GAL/YEAR
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0047974
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0076050
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

90571 260 EL CAMINO REAL, BURLINGAME, CA, 94010			U001593888
▲ S82	SSW 1/10 - 1/3	(1170 ft. / 0.222 mi.)	State and tribal leaking storage tank lists State and tribal registered storage tank lists
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100128
Latitude:	37.5764790250825
Longitude:	-122.3495221138
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/10/2013
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0135
LOC Case Number:	660046
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Extracted from CRA's April 27, 2009 WELL INSTALLATION AND DESTUCTION REPORT, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site is an inactive Chevron retail gasoline service station. The subject property was first developed in the late 1910s or early 1920s as a service station. Details of the station facilities are not available; however, historical Sanborn maps and aerial photos indicate two structures occupying the site. The property remained unchanged until approximately 1965 when the dispenser island configuration changed from a rectangular to a square structure. In June 1990, the configuration of the site went through a third change when the adjacent office/store building on the northern property was demolished and the property was merged with the subject property. At the same time, two steel 10,000-gallon gasoline, one

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

steel 5,000-gallon gasoline and one 1,000-gallon used-oil underground storage tanks (USTs) and associated product line piping were removed from beneath the site. A new station building containing an automotive service shop equipped with three hydraulic lifts was constructed in the northeast corner of the site. Two 10,000-gallon and one 5,000-gallon gasoline USTs and two fuel dispenser islands were installed in the central portion of the site, and one 1,000-gallon used-oil UST was installed next to the service bays in the eastern portion of the site. In 1998, the second generation USTs were removed and replaced with a third generation of USTs comprised of three fiberglass and steel 10,000-gallon gasoline USTs in the same location. One 1,000-gallon used-oil UST replaced the previous tank in the same location. In May 2007, as part of the debranding of the Chevron station, all USTs, dispenser islands, associated product piping, and three hydraulic lifts were removed from the site. The station building, canopy and concrete apron still occupy the site. 1990 Soil Vapor Contaminant Assessment: On June 5, 1990, EA Engineering, Science, and Technology (EA) collected soil gas samples from 15 locations. The volatile hydrocarbon distribution pattern indicated two distinct sources of petroleum hydrocarbons. EA stated that a former Shell Service Station site with a known history of UST leaks, located directly across Burlingame Avenue, may have contributed to the presence of petroleum hydrocarbons beneath the northwestern portion of the Chevron site. Furthermore, EA found that a second source of subsurface petroleum hydrocarbons originated beneath the northern portion of the Chevron tank field. 1990 UST and Product Line Removal: In June 1990, two 10,000-gallon and one 5,000-gallon gasoline, and one 1,000-gallon used-oil USTs and associated product line piping were removed. Total petroleum hydrocarbons as gasoline (TPHg) were detected as high as 4,100 milligrams per kilogram (mg/kg) in a soil sample collected from the southwest corner of the former tank pit. A September 20, 1990 Unauthorized Release Report states that an unknown volume of gasoline and used-oil was released from the site and discovered on June 13, 1990 during tank removal. To remediate impacted soil in the vicinity of the tank field, EA installed four vapor extraction pipes on the floor of the excavation and covered them with pea gravel and a heavy

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

gauge Hypalon vapor barrier before additional gravel and replacement double-walled fiberglass tanks were placed in the pit. 1990 Well Installation: Between August 20 and September 4, 1990, EA installed groundwater monitoring wells MW-1 through MW-6. Petroleum hydrocarbon concentrations in soil were generally higher in the northern and southern edges of the site. The highest detected hydrocarbon concentrations in soil were 1,100 mg/kg total petroleum hydrocarbons as diesel (TPHd), 4,100 mg/kg TPHg, and 13 mg/kg benzene from boring MW-5, located on the southeast corner of the site. Soil samples were not analyzed for methyl tertiary butyl ether (MTBE). Light non-aqueous phase liquids (LNAPL) were detected in well MW-5 upon installation. 1991 Soil Vapor Extraction Pilot Test: On February 15 and August 15, 1991, EA conducted a soil vapor extraction pilot test to evaluate soil vapor extraction feasibility for remediation of subsurface petroleum hydrocarbons at the site. EA concluded that despite relatively low soil permeability, the site could be remediated by a vapor extraction system equipped with a high vacuum pump. 1995 Well Installation: On March 13 and 14, 1995, Groundwater Technology, Inc. (GTI) installed groundwater monitoring wells MW-7 through MW-9. No benzene, toluene, ethylbenzene, or xylenes (BTEX), or TPHg were detected in soil. Soil samples were not analyzed for TPHd or MTBE. 1995 Hydrocarbon Removal from Tank Backfill: According to a December 5, 1995 unauthorized release report, approximately 2,200 gallons of gasoline were released from the northernmost UST into the tank backfill after both of the tanks fiberglass walls were ruptured during station remodeling. Vacuum trucks pumped NAPL and groundwater from the tank backfill area on December 5 and 29, 1995, recovering an estimated 2,000 gallons of NAPL. Cambria Environmental Technology, Inc. (Cambria) extracted soil vapor from two tank backfill wells between December 20, 1995 and January 17, 1996, removing an estimated 253 gallons of petroleum hydrocarbons. Therefore, remedial actions after the release appear to have recovered the released hydrocarbon mass. 1996 Area Well Survey: On October 24, 1996, Cambria performed a door-to-door area well survey of properties in an arc extending approximately 400 feet downgradient (north to northeast) from the site. No active or abandoned wells were identified. 1998 Soil Vapor Investigation: On March 11, 1998, Cambria

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

advanced soil vapor borings SB-1 through SB-4. Soil vapor samples were collected from 2 and 5 feet below grade (fbg) in each boring. The only benzene concentration detected was 0.0028 parts per million by volume in sample SB-4 collected from 2 fbg near the southeast corner of the station building. 2002-2003 Well Survey: Cambria contacted SMCHD and the City of Burlingame Water Division to obtain records of any wells within a 2000-foot radius of the site. Cambria also distributed a questionnaire to owners of all properties within 800 feet downgradient and 400 feet upgradient and crossgradient of the site to identify any wells or sumps present on their properties. Ten irrigation wells were identified over 1,500 feet upgradient and crossgradient of the site. The only wells identified downgradient of the site were groundwater monitoring wells. Cambrias February 12, 2003 Well Survey Report concluded that based on the topography, drainage patterns and groundwater gradient, it was unlikely that any wells would be impacted by petroleum hydrocarbons originating from the site. 2005 Baseline Investigation: On November 11 through 15, 2005, SECOR International, Inc. (SECOR) conducted a baseline investigation, advancing soil borings BA-1 through BA-4. Soil collected from borings BA-1 and BA-2 were analyzed for TPHg, BTEX, and oxygenates including MTBE. TPHg was only detected at 130 mg/kg in the 15 fbg sample from boring BA-2, advanced near the dispenser islands. No BTEX or oxygenates were detected in soil. Soil samples from BA-3 and BA-4 were only analyzed for TPHd. Soil samples from BA-3 contained 53 mg/kg at 15 fbg and BA-4 contained 13 mg/kg at 15 fbg. Groundwater was encountered in boring BA-1 and a grab-groundwater sample was collected. The grab-groundwater sample contained 4,400 micrograms per liter (μg/L) TPHg and 19 μg/L benzene. No fuel oxygenates, including MTBE, were detected in the grab-groundwater sample from boring BA-1. 2006 Well Installation: On November 8, 2006, Cambria installed monitoring well MW-10 to further define the downgradient extent of petroleum hydrocarbons in groundwater northeast of the site. TPHg was detected in soil from 10.5 fbg at 770 mg/kg and from 15.5 fbg at 1,100 mg/kg. No benzene or MTBE was detected in soil. 2007 Well Destruction: On May 18, 2007, Conestoga-Rovers & Associates (CRA) destroyed onsite wells MW-3 and MW-4 by pressure grouting in anticipation of station

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

demolition activities that would have compromised well integrity. The well destruction is detailed in CRAs June 1, 2007 Well Destruction Report. 2007 Station Demolition: The station was de-branded on April 2, 2007. In May 2007, CRA observed Gettler-Ryan, Inc. (G-R) of Dublin, California remove the hydraulic lifts, fuel dispensers, product lines and USTs and collected compliance soil samples. Only TPHg and ethylbenzene were detected in the three gasoline UST soil samples. TPHg concentrations ranged from 820 to 2,100 mg/kg, and ethylbenzene concentrations ranged from 5.2 to 12 mg/kg. No hydrocarbons were detected in the six soil samples collected beneath the dispenser islands. Only 1.1 mg/kg TPHd was detected in the soil sample collected from the used-oil tank pit. No total petroleum hydrocarbons as hydraulic oil (TPHho) was detected in the soil samples collected beneath the hydraulic lifts. The grab-groundwater sample collected from the gasoline UST pit contained 3,000 g/L TPHg, 23 g/L benzene, and 15 g/L MTBE. No hydrocarbons were detected in the grab-groundwater sample collected from the used-oil tank pit. The tank cavities and hydraulic lift cavity were backfilled to the surface with gravel. As a condition of the City of Burlingame permit approval, G-R was required to leave the station building and canopy intact. 2007 Soil Boring and Soil Vapor Investigation: In October and November 2007, CRA advanced soil borings B4 through B12 and installed soil vapor probes VP-1, VP-2, and VP-3 to define the extent and distribution of petroleum hydrocarbons in soil and groundwater beneath the site and to evaluate soil vapor exposure pathways in anticipation of property redevelopment. TPHg was detected in seven of the nine soil borings at concentrations ranging from 11 mg/kg in sample B7 at 20 fbg to 2,600 mg/kg in sample B5 at 15 fbg. Benzene was detected in five of the soil borings at concentrations ranging from 0.001 mg/kg in sample B12 at 20 fbg to 4.7 mg/kg in sample B5 at 15 fbg. MTBE was detected in six soil borings at concentrations ranging from 0.0008 mg/kg in sample B4 at 15 fbg to 0.088 mg/kg in sample B5 at 15 fbg. No TPHd was detected in any of the soil borings. The grab-groundwater sample collected from boring B9 contained 1,000 g/L TPHg, 1 g/L benzene, and 38 g/L MTBE. Soil vapor samples were collected in November and December 2007. No benzene was detected in

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

any of the vapor wells. Vapor probe VP-1 contained 1,000,000 micrograms per cubic meter (μg/m%) TPHg during the November sampling event and 1,100,000 g/m% during the December sampling event. Due to the lack of carcinogenic constituents detected in any of the vapor samples, it was determined remediation based solely on the soil vapor results is not necessary. On July 21, 2008, CRA destroyed onsite monitoring wells MW-1, MW-2 and MW-6 to facilitate construction of a Walgreens retail store at the site, as requested by the property owner. On February 26, 2009, CRA installed groundwater monitoring well MW-11 to define the extent of the dissolved hydrocarbon plume northeast (downgradient) of well MW-10, and destroyed vapor wells VP-1 through VP-3 to facilitate site construction.

Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100128

Contact:

Global Id:	T0608100128
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100128
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100128
Status:	Completed - Case Closed
Status Date:	05/10/2013

Global Id:	T0608100128
Status:	Open - Case Begin Date
Status Date:	07/17/1990

Global Id:	T0608100128
Status:	Open - Eligible for Closure
Status Date:	04/11/2012

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Status:	Open - Site Assessment
Status Date:	08/16/1990

Global Id:	T0608100128
Status:	Open - Verification Monitoring
Status Date:	04/27/2009

Regulatory Activities:

Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	10/29/2009
Action:	Staff Letter - #20091029

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	08/16/2006
Action:	Other Report / Document

Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	04/11/2012
Action:	Notification - Public Notice of Case Closure - #20120411

Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	01/20/2010
Action:	Staff Letter - #20100120

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	07/20/2010
Action:	Well Installation Report

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/03/2009
Action:	Soil and Water Investigation Report

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	08/16/2006
Action:	Soil and Water Investigation Workplan

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	01/04/2007
Action:	Well Installation Report

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	06/07/2007
Action:	Electronic Reporting Submittal Due

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	10/31/2007
Action:	Soil and Water Investigation Report
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	04/07/2007
Action:	Other Workplan
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2006
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/05/2005
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2004
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	03/20/2006
Action:	Other Report / Document
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	02/15/2012
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	Other
Date:	08/16/1990
Action:	Leak Discovery
Global Id:	T0608100128
Action Type:	Other
Date:	07/17/1990
Action:	Leak Reported
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	06/21/2009
Action:	Electronic Reporting Submittal Due
Global Id:	T0608100128
Action Type:	REMEDIATION
Date:	10/03/1990
Action:	Excavation

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Action Type:	REMEDIATION
Date:	10/03/1990
Action:	Other (Use Description Field)
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	08/15/2012
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	02/07/2007
Action:	* Verbal Communication - #20070207
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	10/15/2008
Action:	Staff Letter - #20081015
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	03/25/2011
Action:	Staff Letter - #20110325
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	05/10/2013
Action:	Closure/No Further Action Letter - #20130510
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	02/15/2011
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	05/10/2011
Action:	Staff Letter - #20110510
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	05/18/2012
Action:	Staff Letter - #20120518
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2005
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	07/18/1991
Action:	Notice of Responsibility - #1

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	09/07/2006
Action:	Staff Letter - #20060907
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	05/07/2007
Action:	Staff Letter - #20070507
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	01/11/2006
Action:	Staff Letter - #20060111
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	06/13/2006
Action:	Staff Letter - #20060613
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	07/18/2007
Action:	Staff Letter - #20070718
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2010
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2008
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	05/21/2009
Action:	Staff Letter - #20090521
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	07/02/2009
Action:	Staff Letter - #20090702
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2002
Action:	Monitoring Report - Semi-Annually

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2003
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2003
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2004
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2007
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2007
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/15/2006
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	08/15/2011
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/06/2011
Action:	Other Report / Document - Regulator Responded
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	08/10/2011
Action:	Site Assessment Report - Regulator Responded
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	01/27/2011
Action:	Clean Up Fund - 5-Year Review Summary - Regulator Responded
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2009
Action:	Monitoring Report - Semi-Annually

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/03/2009
Action:	Well Installation Report
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	05/18/2013
Action:	Well Destruction Report - Regulator Responded
Global Id:	T0608100128
Action Type:	RESPONSE
Date:	11/15/2008
Action:	Monitoring Report - Semi-Annually
Global Id:	T0608100128
Action Type:	ENFORCEMENT
Date:	08/09/2000
Action:	Staff Letter - #20000809

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660046
Facility Status:	9- Case Closed
Global ID:	T0608100128
APN Number:	029201320
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST UST: State and tribal registered storage tank lists

File Number:	0002BCB5
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002BCB5.pdf
Region:	STATE
Facility ID:	00000061848
Facility Type:	Gas Station
Other Type:	Not Reported
Contact Name:	SEDLEMYER, ROBERT V
Telephone:	4153446120
Owner Name:	CHEVRON U.S.A. INC.
Owner Address:	575 MARKET
Owner City,St,Zip:	SAN FRANCISCO, CA 94105
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	1971
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not Reported
Container Construction Thickness:	0000250

90571, 260 EL CAMINO REAL, BURLINGAME, CA 94010 (Continued)

Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	1971
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	Not Reported
Container Construction Thickness:	0000250
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3
Year Installed:	1979
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not Reported
Container Construction Thickness:	0000250
Leak Detection:	Stock Inventor
Click here for Geo Tracker PDF:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_HISTUST_PDF&img_id=0002BCB5

CHEVRON 260 EL CAMINO REAL, BURLINGAME, CA,			S110060516
▲ S83	SSW 1/10 - 1/3	(1170 ft. / 0.222 mi.)	Other Standard Environmental Records
	11 ft. Higher Elevation	43 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0135

MIKE HARVEY HONDA 200 CALIFORNIA, BURLINGAME, CA, 94010			S113755548
▲ T84	E 1/10 - 1/3	(1200 ft. / 0.227 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0010382
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011929
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010382
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004700
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

MIKE HARVEY HONDA 200 CALIFORNIA, BURLINGAME, CA, 94010			S113758114
▲ T85	E 1/10 - 1/3	(1200 ft. / 0.227 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0029336
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0049815
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0029336
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0049814
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	ACTIVE

PUTNAM CHEVROLET CADILLAC 198 CALIFORNIA, BURLINGAME, CA, 94010			S113757757
▲ T86	E 1/10 - 1/3	(1216 ft. / 0.23 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0027495
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0043745
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0027495
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0043746
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

MAP FINDINGS

ARATA PROPERTY 198 CALIFORNIA, BURLINGAME, CA, 94010		S104493499
▲ T87	E 1/10 - 1/3 (1216 ft. / 0.23 mi.)	State and tribal leaking storage tank lists
	1 ft. Higher Elevation 33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660060
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

PUTNAM CHEVROLET CADILLAC 198 CALIFORNIA DR, BURLINGAME, CA, 94010			1000596695
▲ T88	E 1/10 - 1/3	(1216 ft. / 0.23 mi.)	Federal RCRA generators list State and tribal leaking storage tank lists Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

FINDS: Other Standard Environmental Records

Registry ID: 110002861591

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

RCRA-SQG: Federal RCRA generators list

Date form received by agency:	03/22/2001
Facility name:	PUTNAM CHEVROLET CADILLAC
Facility address:	198 CALIFORNIA DR BURLINGAME, CA 94010
EPA ID:	CAD983606716
Contact:	RICK CORSO
Contact address:	198 CALIFORNIA DR BURLINGAME, CA 94010
Contact country:	US
Contact telephone:	(650) 342-9500
Contact email:	Not Reported
EPA Region:	09
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	JOE PUTNAM
Owner/operator address:	3 CALIFORNIA DR BURLINGAME, CA 94010
Owner/operator country:	Not Reported
Owner/operator telephone:	(650) 347-4800

PUTNAM CHEVROLET CADILLAC, 198 CALIFORNIA DR, BURLINGAME, CA 94010 (Continued)

Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not Reported
Owner/Op end date:	Not Reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status: No violations found

ECHO: Other Standard Environmental Records

Envid:	1000596695
Registry ID:	110002861591
DFR URL:	http://echo.epa.gov/detailed_facility_report?fid=110002861591

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608101044
Latitude:	37.5785749930435
Longitude:	-122.342392802238
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	12/27/2001
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-1137
LOC Case Number:	660060
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported

PUTNAM CHEVROLET CADILLAC, 198 CALIFORNIA DR, BURLINGAME, CA 94010 (Continued)

Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608101044

Contact:

Global Id:	T0608101044
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608101044
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608101044
Status:	Completed - Case Closed
Status Date:	12/27/2001

Global Id:	T0608101044
Status:	Open - Case Begin Date
Status Date:	03/25/1987

Regulatory Activities:

Global Id:	T0608101044
Action Type:	Other
Date:	05/06/1992
Action:	Leak Discovery

Global Id:	T0608101044
Action Type:	Other
Date:	03/25/1987
Action:	Leak Reported

Global Id:	T0608101044
Action Type:	ENFORCEMENT
Date:	05/06/1992
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660060

PUTNAM CHEVROLET CADILLAC, 198 CALIFORNIA DR, BURLINGAME, CA 94010 (Continued)

Facility Status:	9- Case Closed
Global ID:	T0608101044
APN Number:	029233080
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-1137

SATURN DEVELOPMENT NORTH, LLC 198 CALIFORNIA, BURLINGAME, CA, 94010			S113755547
▲ T89	E 1/10 - 1/3	(1216 ft. / 0.23 mi.)	Other Standard Environmental Records
	1 ft. Higher Elevation	33 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0010375
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0011928
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010375
Prog Element Code:	STORES HAZ MAT <1,199GAL,9,999LB,4,799FT3
Record Id:	PR0004699
Description:	STORES HAZ MAT <1,199GAL,9,999LB,4,799CF
Facility Status:	INACTIVE

CALIFORNIA DRIVE AUTO SERVICE 621 CALIFORNIA, BURLINGAME, CA, 94010			S113757362
▼ U90	NW 1/10 - 1/3	(1239 ft. / 0.235 mi.)	Other Standard Environmental Records
	10 ft. Lower Elevation	22 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0025639
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0034580
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0025639
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0034581
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

AUTO TIGER 621 CALIFORNIA, BURLINGAME, CA, 94010			S113756760
▼ U91	NW 1/10 - 1/3	(1239 ft. / 0.235 mi.)	Other Standard Environmental Records
	10 ft. Lower Elevation	22 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0022465
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0024553
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0022465
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0024554
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

BURLINGAME PRIME MOTORZ 621 CALIFORNIA, BURLINGAME, CA, 94010			S113757955
▼ U92	NW 1/10 - 1/3	(1239 ft. / 0.235 mi.)	Other Standard Environmental Records
	10 ft. Lower Elevation	22 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0058084
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0080570
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0058084
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0080569
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE
Region:	SAN MATEO
Facility ID:	FA0028258
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0046746
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE
Region:	SAN MATEO
Facility ID:	FA0028258
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0046747
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

PENINSULA PRIME MOTORZ LLC 621 CALIFORNIA, BURLINGAME, CA, 94010			S113758467
▼ U93	NW 1/10 - 1/3	(1239 ft. / 0.235 mi.)	Other Standard Environmental Records
	10 ft. Lower Elevation	22 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0038617
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0055058
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0038617
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0055057
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

T MOBILE SITE ID SF53613A 850 BURLINGAME, BURLINGAME, CA, 94010			S113758919
▼ 94	NE 1/10 - 1/3	(1267 ft. / 0.24 mi.)	Other Standard Environmental Records
	10 ft. Lower Elevation	22 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0049056
Prog Element Code:	STORES HAZ MAT <219GAL,1,999LB, 879FT3
Record Id:	PR0067005
Description:	STORES HAZ MAT <219GAL,1,999LB, 879CF
Facility Status:	INACTIVE

CHEVRON, FORMER/EAGLE GAS STA 177 CALIFORNIA, BURLINGAME, CA, 94010			S101438110
▲ T95	ESE 1/10 - 1/3	(1307 ft. / 0.248 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	2 ft. Higher Elevation	34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608194030
Latitude:	37.578459
Longitude:	-122.34303
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	05/17/2006
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0128
LOC Case Number:	660013
File Location:	Local Agency Warehouse
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608194030

Contact:

Global Id:	T0608194030
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608194030
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO

CHEVRON, FORMER/EAGLE GAS STA, 177 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608194030
Status:	Completed - Case Closed
Status Date:	05/17/2006
Global Id:	T0608194030
Status:	Open - Case Begin Date
Status Date:	08/04/1987
Global Id:	T0608194030
Status:	Open - Site Assessment
Status Date:	08/04/1987
Global Id:	T0608194030
Status:	Open - Verification Monitoring
Status Date:	11/22/2000

Regulatory Activities:

Global Id:	T0608194030
Action Type:	Other
Date:	08/04/1987
Action:	Leak Discovery
Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	05/17/2006
Action:	Closure/No Further Action Letter - #20060517
Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	10/25/2005
Action:	Staff Letter - #20051025
Global Id:	T0608194030
Action Type:	REMEDIATION
Date:	07/03/1989
Action:	Pump & Treat (P&T) Groundwater
Global Id:	T0608194030
Action Type:	Other
Date:	09/01/1987
Action:	Leak Reported
Global Id:	T0608194030
Action Type:	REMEDIATION
Date:	07/03/1989
Action:	Free Product Removal
Global Id:	T0608194030
Action Type:	RESPONSE

CHEVRON, FORMER/EAGLE GAS STA, 177 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Date:	05/15/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	05/15/2005
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	11/15/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	05/15/2002
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	10/15/2002
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	05/15/2003
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	10/15/2003
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	11/15/2005
Action:	Monitoring Report - Quarterly
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	01/06/2006
Action:	Unknown
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	01/25/2006
Action:	Unknown
Global Id:	T0608194030
Action Type:	RESPONSE
Date:	10/01/2005
Action:	Request for Closure
Global Id:	T0608194030
Action Type:	ENFORCEMENT

CHEVRON, FORMER/EAGLE GAS STA, 177 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Date:	02/27/1989
Action:	Notice of Responsibility - #1
Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	10/11/2005
Action:	Staff Letter - #20051011
Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	06/01/2005
Action:	* Verbal Communication - #20050601
Global Id:	T0608194030
Action Type:	ENFORCEMENT
Date:	08/09/2000
Action:	Staff Letter - #20000809

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660013
Facility Status:	9- Case Closed
Global ID:	T0608194030
APN Number:	029232160
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records



Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0128

EAGLE CAR WASH & FILL 177 CALIFORNIA, BURLINGAME, CA, 94010		S113756598
▲ T96	ESE 1/10 - 1/3 (1307 ft. / 0.248 mi.)	Other Standard Environmental Records
	2 ft. Higher Elevation 34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Not Applicable: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004623
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	UNDERGROUND TANK - GENERAL
Record Id:	PR0022758
Description:	UNDERGROUND TANK - GENERAL
Facility Status:	ACTIVE

Region:	SAN MATEO
Facility ID:	FA0017977
Prog Element Code:	GENERATES and RECYCLES WASTE OIL/SOLVENT
Record Id:	PR0027807
Description:	GENERATES & RECYCLES WASTE OIL/SOLVENT
Facility Status:	INACTIVE

CHEVRON, FORMER/EAGLE GAS STA 177 CALIFORNIA, BURLINGAME, CA, 94010		S104891007
▲ T97	ESE 1/10 - 1/3 (1307 ft. / 0.248 mi.)	State and tribal leaking storage tank lists
	2 ft. Higher Elevation 34 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Conditions:

Petroleum Hydrocarbon Chemicals of Concern: YES

Groundwater Flow Gradient:

Upgradient or Indeterminate: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Pollution Characterization
Case Number:	660013
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	1/1/1965
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

ALL MAKES AUTO BODY 257 MYRTLE, BURLINGAME, CA, 94010			S113755525
▼ P98	ENE 1/10 - 1/3	(1320 ft. / 0.25 mi.)	Other Standard Environmental Records
	5 ft. Lower Elevation	27 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

San Mateo Co. BI: Other Standard Environmental Records

Region:	SAN MATEO
Facility ID:	FA0010115
Prog Element Code:	GENERATES <27 GAL/YEAR
Record Id:	PR0011925
Description:	GENERATES <27 GAL/YEAR
Facility Status:	INACTIVE

Region:	SAN MATEO
Facility ID:	FA0010115
Prog Element Code:	STORES MV FUELS OR WASTE ONLY
Record Id:	PR0004697
Description:	STORES MV FUELS OR WASTE ONLY
Facility Status:	INACTIVE

W. J. BRITTON COMPANY 701 CALIFORNIA, BURLINGAME, CA, 94010			S103065158
▼ U99	NW 1/10 - 1/3	(1343 ft. / 0.254 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	11 ft. Lower Elevation	21 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100626
Latitude:	37.582236
Longitude:	-122.351484
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	06/30/1998
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0657
LOC Case Number:	660006
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100626

Contact:

Global Id:	T0608100626
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100626
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

W. J. BRITTON COMPANY, 701 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T0608100626
Status:	Completed - Case Closed
Status Date:	06/30/1998
Global Id:	T0608100626
Status:	Open - Case Begin Date
Status Date:	08/06/1986

Regulatory Activities:

Global Id:	T0608100626
Action Type:	Other
Date:	01/09/1987
Action:	Leak Discovery
Global Id:	T0608100626
Action Type:	Other
Date:	08/06/1986
Action:	Leak Reported
Global Id:	T0608100626
Action Type:	REMEDIATION
Date:	05/01/1997
Action:	Excavation
Global Id:	T0608100626
Action Type:	ENFORCEMENT
Date:	11/15/1989
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660006
Facility Status:	9- Case Closed
Global ID:	T0608100626
APN Number:	029053160
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

LUST REG 2:

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660006
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST

W. J. BRITTON COMPANY, 701 CALIFORNIA, BURLINGAME, CA 94010 (Continued)

Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

HIST CORTESE: Other Standard Environmental Records



Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0657

DEITER BLUHM 1285 OAK GROVE, BURLINGAME, CA, 94010			S103472705
▼ 100	WNW 1/10 - 1/3	(1630 ft. / 0.309 mi.)	State and tribal leaking storage tank lists Other Standard Environmental Records
	6 ft. Lower Elevation	26 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST: State and tribal leaking storage tank lists

Region:	STATE
Global Id:	T0608100073
Latitude:	37.58111
Longitude:	-122.352541
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/30/1991
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0078
LOC Case Number:	660042
File Location:	Local Agency
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Not Reported
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100073

Contact:

Global Id:	T0608100073
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100073
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

DEITER BLUHM, 1285 OAK GROVE, BURLINGAME, CA 94010 (Continued)

Status History:

Global Id:	T0608100073
Status:	Completed - Case Closed
Status Date:	09/30/1991
Global Id:	T0608100073
Status:	Open - Case Begin Date
Status Date:	05/25/1990

Regulatory Activities:

Global Id:	T0608100073
Action Type:	Other
Date:	05/25/1990
Action:	Leak Reported
Global Id:	T0608100073
Action Type:	ENFORCEMENT
Date:	09/30/1991
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660042
Facility Status:	9- Case Closed
Global ID:	T0608100073
APN Number:	029131010
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

LUST REG 2:

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660042
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

DEITER BLUHM, 1285 OAK GROVE, BURLINGAME, CA 94010 (Continued)

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0078

FLOYD'S AUTOMOTIVE 741 SAN MATEO, BURLINGAME, CA, 94010			S104493557
▼ V101	NW 1/10 - 1/3	(1661 ft. / 0.315 mi.)	State and tribal leaking storage tank lists
	14 ft. Lower Elevation	18 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

LUST REG 2: State and tribal leaking storage tank lists

Region:	2
Facility Id:	Not Reported
Facility Status:	Case Closed
Case Number:	660061
How Discovered:	OM
Leak Cause:	Unknown
Leak Source:	Unknown
Date Leak Confirmed:	Not Reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not Reported
Preliminary Site Assesment Began:	Not Reported
Pollution Characterization Began:	Not Reported
Pollution Remediation Plan Submitted:	Not Reported
Date Remediation Action Underway:	Not Reported
Date Post Remedial Action Monitoring Began:	Not Reported

FLOYDS AUTOMOTIVE 741 SAN MATEO AVE, BURLINGAME, CA, 94010			S103892239
▼ V102	NW 1/10 - 1/3	(1661 ft. / 0.315 mi.)	State and tribal leaking storage tank lists State and tribal registered storage tank lists Other Standard Environmental Records
	14 ft. Lower Elevation	18 ft. Above Sea Level	

Worksheet:

Impact on Target Property: VEC does not exist

Groundwater Flow Gradient:

Downgradient: YES

Topographically: YES

SWEEPS UST: State and tribal registered storage tank lists

Status:	Not Reported
Comp Number:	660096
Number:	Not Reported
Board Of Equalization:	Not Reported
Referral Date:	Not Reported
Action Date:	Not Reported
Created Date:	Not Reported
Owner Tank Id:	Not Reported
SWRCB Tank Id:	41-000-660096-000001
Tank Status:	Not Reported
Capacity:	550
Active Date:	Not Reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

Status:	Active
Comp Number:	660096
Number:	9
Board Of Equalization:	Not Reported
Referral Date:	10-19-93
Action Date:	10-19-93
Created Date:	07-08-92
Owner Tank Id:	Not Reported
SWRCB Tank Id:	Not Reported
Tank Status:	Not Reported
Capacity:	Not Reported
Active Date:	Not Reported
Tank Use:	Not Reported
STG:	Not Reported
Content:	Not Reported
Number Of Tanks:	Not Reported

LUST: State and tribal leaking storage tank lists

Region:	STATE

FLOYDS AUTOMOTIVE, 741 SAN MATEO AVE, BURLINGAME, CA 94010 (Continued)

Global Id:	T0608100222
Latitude:	37.5680556
Longitude:	-122.3072222
Case Type:	LUST Cleanup Site
Status:	Completed - Case Closed
Status Date:	09/05/2000
Lead Agency:	SAN MATEO COUNTY LOP
Case Worker:	JM
Local Agency:	SAN MATEO COUNTY LOP
RB Case Number:	41-0233
LOC Case Number:	660061
File Location:	Local Agency
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not Reported
Click here to access the California GeoTracker records for this facility:	http://www.web.edrnet.com/ordering/switchboard/redirect.aspx?s=GRR_CA_LUST_ST&global_id=T0608100222

Contact:

Global Id:	T0608100222
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not Reported
Phone Number:	Not Reported

Global Id:	T0608100222
Contact Type:	Local Agency Caseworker
Contact Name:	JACOB MADDEN
Organization Name:	SAN MATEO COUNTY LOP
Address:	2000 ALAMEDA DE LAS PULGAS
City:	SAN MATEO
Email:	jmadden@smcgov.org
Phone Number:	6503726298

Status History:

Global Id:	T0608100222
Status:	Completed - Case Closed
Status Date:	09/05/2000

Global Id:	T0608100222
Status:	Open - Case Begin Date
Status Date:	05/27/1992

Regulatory Activities:

Global Id:	T0608100222
Action Type:	Other
Date:	05/28/1992

FLOYDS AUTOMOTIVE, 741 SAN MATEO AVE, BURLINGAME, CA 94010 (Continued)

Action:	Leak Discovery
Global Id:	T0608100222
Action Type:	Other
Date:	05/27/1992
Action:	Leak Reported
Global Id:	T0608100222
Action Type:	ENFORCEMENT
Date:	05/28/1992
Action:	Notice of Responsibility - #1

SAN MATEO CO. LUST:

Region:	SAN MATEO
Facility ID:	660061
Facility Status:	9- Case Closed
Global ID:	T0608100222
APN Number:	029053480
Case Type:	SAN MATEO CO. LUST
EDR Link ID:	SAN MATEO CO. LUST

HIST CORTESE: Other Standard Environmental Records

Region:	CORTESE
Facility County Code:	41
Reg By:	LTNKA
Reg Id:	41-0233

RECORD SOURCES AND CURRENCY

To maintain currency of the following databases, EDR contacts the appropriate agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

PRP: Potentially Responsible Parties
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Number of Days to Update: 3
Last EDR Contact :05/12/2016

Source: EPA
Telephone: 202-564-6023

RMP: Risk Management Plans
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 08/01/2015
Number of Days to Update: 69
Last EDR Contact :07/25/2016

Source: Environmental Protection Agency
Telephone: 202-564-8600

ALAMEDA CO. UST: Underground Tanks
Standard Environmental Record Source: State and tribal registered storage tank lists
Underground storage tank sites located in Alameda county.

Date of Government Version: 04/06/2016
Number of Days to Update: 48
Last EDR Contact :07/07/2016

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700

AST: Aboveground Petroleum Storage Tank Facilities
Standard Environmental Record Source: State and tribal registered storage tank lists
Search Distance: Property

A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 08/01/2009
Number of Days to Update: 21
Last EDR Contact :07/07/2016

Source: California Environmental Protection Agency
Telephone: 916-327-5092

Alameda County CS: Contaminated Sites
Standard Environmental Record Source: State and tribal leaking storage tank lists
Search Distance: 0.333 Mile

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 04/12/2016
Number of Days to Update: 48
Last EDR Contact :07/07/2016

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700

BROWNFIELDS: Considered Brownfieds Sites Listing

Standard Environmental Record Source: State and tribal Brownfields sites
Search Distance: 0.333 Mile

A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 02/29/2016
Number of Days to Update: 58
Last EDR Contact :06/15/2016

Source: State Water Resources Control Board
Telephone: 916-323-7905

CA BOND EXP. PLAN: Bond Expenditure Plan

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Number of Days to Update: 6
Last EDR Contact :05/31/1994

Source: Department of Health Services
Telephone: 916-255-2118

CA FID UST: Facility Inventory Database

Standard Environmental Record Source: State and tribal registered storage tank lists
Search Distance: Property

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Number of Days to Update: 24
Last EDR Contact :12/28/1998

Source: California Environmental Protection Agency
Telephone: 916-341-5851

CA LA LF: City of Los Angeles Landfills

Standard Environmental Record Source: State and tribal landfill / solid waste disposal
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2016
Number of Days to Update: 56
Last EDR Contact :07/18/2016

Source: Engineering & Construction Division
Telephone: 213-473-7869

CDL: Clandestine Drug Labs

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2015

Source: Department of Toxic Substances Control

Number of Days to Update: 38
Telephone: 916-255-6504
Last EDR Contact :07/07/2016

CHMIRS: California Hazardous Material Incident Report System
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 04/11/2016
Source: Office of Emergency Services
Number of Days to Update: 51
Telephone: 916-845-8400
Last EDR Contact :07/26/2016

CONTRA COSTA CO. SITE LIST: Site List
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.25 Mile

List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 05/24/2016
Source: Contra Costa Health Services Department
Number of Days to Update: 55
Telephone: 925-646-2286
Last EDR Contact :08/01/2016

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 03/28/2016
Source: CAL EPA/Office of Emergency Information
Number of Days to Update: 40
Telephone: 916-323-3400
Last EDR Contact :06/28/2016

CUPA AMADOR: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa Facility List

Date of Government Version: 06/06/2016
Source: Amador County Environmental Health
Number of Days to Update: 12
Telephone: 209-223-6439
Last EDR Contact :06/02/2016

CUPA BUTTE: CUPA Facility Listing
Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list.

Date of Government Version: 06/02/2016
Source: Public Health Department
Number of Days to Update: 18
Telephone: 530-538-7149
Last EDR Contact :07/07/2016

CUPA CALVERAS: CUPA Facility Listing
Standard Environmental Record Source: Other Standard Environmental Records
Cupa Facility Listing

Date of Government Version: 04/29/2016
Source: Calveras County Environmental Health

Number of Days to Update: 45
Telephone: 209-754-6399
Last EDR Contact :06/27/2016

CUPA COLUSA: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list.

Date of Government Version: 05/25/2016
Source: Health & Human Services
Number of Days to Update: 22
Telephone: 530-458-0396
Last EDR Contact :05/23/2016

CUPA DEL NORTE: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa Facility list

Date of Government Version: 04/08/2016
Source: Del Norte County Environmental Health Division
Number of Days to Update: 50
Telephone: 707-465-0426
Last EDR Contact :07/27/2016

CUPA EL DORADO: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA facility list.

Date of Government Version: 02/22/2016
Source: El Dorado County Environmental Management Department
Number of Days to Update: 37
Telephone: 530-621-6623
Last EDR Contact :07/27/2016

CUPA FRESNO: CUPA Resources List
Standard Environmental Record Source: Other Standard Environmental Records
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 04/04/2016
Source: Dept. of Community Health
Number of Days to Update: 28
Telephone: 559-445-3271
Last EDR Contact :07/13/2016

CUPA HUMBOLDT: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA facility list.

Date of Government Version: 03/16/2016
Source: Humboldt County Environmental Health
Number of Days to Update: 44
Telephone: Not Reported
Last EDR Contact :05/23/2016

CUPA IMPERIAL: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list.

Date of Government Version: 04/26/2016
Source: San Diego Border Field Office
Number of Days to Update: 50
Telephone: 760-339-2777
Last EDR Contact :07/20/2016

CUPA INYO: CUPA Facility List

Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list.

Date of Government Version: 09/10/2013
Number of Days to Update: 33
Last EDR Contact :05/23/2016
Source: Inyo County Environmental Health Services
Telephone: 760-878-0238

CUPA KINGS: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 05/25/2016
Number of Days to Update: 26
Last EDR Contact :05/23/2016
Source: Kings County Department of Public Health
Telephone: 559-584-1411

CUPA LAKE: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list

Date of Government Version: 04/26/2016
Number of Days to Update: 51
Last EDR Contact :04/18/2016
Source: Lake County Environmental Health
Telephone: 707-263-1164

CUPA MADERA: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 03/02/2016
Number of Days to Update: 58
Last EDR Contact :05/23/2016
Source: Madera County Environmental Health
Telephone: 559-675-7823

CUPA MERCED: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA facility list.

Date of Government Version: 02/26/2016
Number of Days to Update: 64
Last EDR Contact :06/15/2016
Source: Merced County Environmental Health
Telephone: 209-381-1094

CUPA MONO: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA Facility List

Date of Government Version: 05/25/2016
Number of Days to Update: 21
Last EDR Contact :05/25/2016
Source: Mono County Health Department
Telephone: 760-932-5580

CUPA MONTEREY: CUPA Facility Listing
Standard Environmental Record Source: Other Standard Environmental Records

CUPA Program listing from the Environmental Health Division.

Date of Government Version: 03/15/2016
Number of Days to Update: 47
Last EDR Contact :05/23/2016

Source: Monterey County Health Department
Telephone: 831-796-1297

CUPA NEVADA: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA facility list.

Date of Government Version: 04/18/2016
Number of Days to Update: 42
Last EDR Contact :07/27/2016

Source: Community Development Agency
Telephone: 530-265-1467

CUPA SAN LUIS OBISPO: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa Facility List.

Date of Government Version: 05/23/2016
Number of Days to Update: 28
Last EDR Contact :05/23/2016

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596

CUPA SANTA BARBARA: CUPA Facility Listing
Standard Environmental Record Source: Other Standard Environmental Records
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Number of Days to Update: 28
Last EDR Contact :05/23/2016

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167

CUPA SANTA CLARA: Cupa Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa facility list

Date of Government Version: 05/25/2016
Number of Days to Update: 27
Last EDR Contact :05/23/2016

Source: Department of Environmental Health
Telephone: 408-918-1973

CUPA SANTA CRUZ: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
CUPA facility listing.

Date of Government Version: 05/31/2016
Number of Days to Update: 19
Last EDR Contact :05/23/2016

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761

CUPA SHASTA: CUPA Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Cupa Facility List.

Date of Government Version: 03/18/2016
Number of Days to Update: 44
Last EDR Contact :05/23/2016

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789

RECORD SOURCES AND CURRENCY

CUPA SONOMA: Cupa Facility List

Standard Environmental Record Source: Other Standard Environmental Records

Cupa Facility list

Date of Government Version: 04/05/2016
Number of Days to Update: 26
Last EDR Contact :07/07/2016

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174

CUPA TUOLUMNE: CUPA Facility List

Standard Environmental Record Source: Other Standard Environmental Records

Cupa facility list

Date of Government Version: 05/03/2016
Number of Days to Update: 38
Last EDR Contact :07/20/2016

Source: Divison of Environmental Health
Telephone: 209-533-5633

CUPA YUBA: CUPA Facility List

Standard Environmental Record Source: Other Standard Environmental Records

CUPA facility listing for Yuba County.

Date of Government Version: 04/29/2016
Number of Days to Update: 45
Last EDR Contact :07/27/2016

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523

DEED: Deed Restriction Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 06/06/2016
Number of Days to Update: 43
Last EDR Contact :06/07/2016

Source: DTSC and SWRCB
Telephone: 916-323-3400

DRYCLEANERS: Cleaner Facilities

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.25 Mile

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 02/08/2016
Number of Days to Update: 37
Last EDR Contact :06/02/2016

Source: Department of Toxic Substance Control
Telephone: 916-327-4498

EL SEGUNDO UST: City of El Segundo Underground Storage Tank

Standard Environmental Record Source: State and tribal registered storage tank lists

Underground storage tank sites located in El Segundo city.

Date of Government Version: 03/30/2015
Number of Days to Update: 11
Last EDR Contact :07/13/2016

Source: City of El Segundo Fire Department
Telephone: 310-524-2236

EMI: Emissions Inventory Data

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2014
Number of Days to Update: 48
Last EDR Contact :06/22/2016

Source: California Air Resources Board
Telephone: 916-322-2990

ENF: Enforcement Action Listing

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 05/25/2016
Number of Days to Update: 54
Last EDR Contact :07/20/2016

Source: State Water Resoruces Control Board
Telephone: 916-445-9379

ENVIROSTOR: EnviroStor Database

Standard Environmental Record Source: State and tribal - equivalent CERCLIS
Search Distance: 0.333 Mile

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 05/02/2016
Number of Days to Update: 48
Last EDR Contact :05/04/2016

Source: Department of Toxic Substances Control
Telephone: 916-323-3400

HAULERS: Registered Waste Tire Haulers Listing

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of registered waste tire haulers.

Date of Government Version: 04/07/2016
Number of Days to Update: 50
Last EDR Contact :05/13/2016

Source: Integrated Waste Management Board
Telephone: 916-341-6422

HAZNET: Facility and Manifest Data

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2014
Source: California Environmental Protection Agency
Number of Days to Update: 58
Telephone: 916-255-1136
Last EDR Contact :07/15/2016

HIST CAL-SITES: Calsites Database

Standard Environmental Record Source: State and tribal - equivalent CERCLIS
Search Distance: 0.333 Mile

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Source: Department of Toxic Substance Control
Number of Days to Update: 21
Telephone: 916-323-3400
Last EDR Contact :02/23/2009

HIST CORTESE: Hazardous Waste & Substance Site List

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Source: Department of Toxic Substances Control
Number of Days to Update: 76
Telephone: 916-323-3400
Last EDR Contact :01/22/2009

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report

Standard Environmental Record Source: State and tribal leaking storage tank lists
Search Distance: 0.333 Mile

A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Source: Santa Clara Valley Water District
Number of Days to Update: 22
Telephone: 408-265-2600
Last EDR Contact :03/23/2009

HIST UST: Hazardous Substance Storage Container Database

Standard Environmental Record Source: State and tribal registered storage tank lists
Search Distance: Property

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Source: State Water Resources Control Board
Number of Days to Update: 18
Telephone: 916-341-5851
Last EDR Contact :07/26/2001

HWP: EnviroStor Permitted Facilities Listing

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 05/23/2016
Source: Department of Toxic Substances Control
Number of Days to Update: 56
Telephone: 916-323-3400
Last EDR Contact :05/25/2016

HWT: Registered Hazardous Waste Transporter Database

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 04/11/2016
Source: Department of Toxic Substances Control
Number of Days to Update: 50
Telephone: 916-440-7145
Last EDR Contact :07/13/2016

KERN CO. UST: Underground Storage Tank Sites & Tank Listing

Standard Environmental Record Source: State and tribal registered storage tank lists

Kern County Sites and Tanks Listing.

Date of Government Version: 03/01/2016
Source: Kern County Environment Health Services Department
Number of Days to Update: 67
Telephone: 661-862-8700
Last EDR Contact :05/09/2016

LA Co. Site Mitigation: Site Mitigation List

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 03/29/2016
Source: Community Health Services
Number of Days to Update: 68
Telephone: 323-890-7806
Last EDR Contact :07/13/2016

LDS: Land Disposal Sites Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units.

Date of Government Version: 03/14/2016
Source: State Water Qualilty Control Board
Number of Days to Update: 61
Telephone: 866-480-1028
Last EDR Contact :06/14/2016

LIENS: Environmental Liens Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 06/02/2016
Source: Department of Toxic Substances Control
Number of Days to Update: 43
Telephone: 916-323-3400

Last EDR Contact :06/02/2016

LONG BEACH UST: City of Long Beach Underground Storage Tank

Standard Environmental Record Source: State and tribal registered storage tank lists

Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 11/04/2015
Source: City of Long Beach Fire Department
Number of Days to Update: 34
Telephone: 562-570-2563
Last EDR Contact :07/25/2016

LOS ANGELES CO. HMS: HMS: Street Number List

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 03/30/2016
Source: Department of Public Works
Number of Days to Update: 38
Telephone: 626-458-3517
Last EDR Contact :07/07/2016

LOS ANGELES CO. LF: List of Solid Waste Facilities

Standard Environmental Record Source: State and tribal landfill / solid waste disposal

Solid Waste Facilities in Los Angeles County.

Date of Government Version: 04/18/2016
Source: La County Department of Public Works
Number of Days to Update: 42
Telephone: 818-458-5185
Last EDR Contact :07/19/2016

LUST: Geotracker's Leaking Underground Fuel Tank Report

Standard Environmental Record Source: State and tribal leaking storage tank lists

Search Distance: 0.333 Mile

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 03/14/2016
Source: State Water Resources Control Board
Number of Days to Update: 61
Telephone: see region list
Last EDR Contact :06/14/2016

LUST REG 1: Active Toxic Site Investigation

Standard Environmental Record Source: State and tribal leaking storage tank lists

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Source: California Regional Water Quality Control Board North Coast (1)
Number of Days to Update: 29
Telephone: 707-570-3769
Last EDR Contact :08/01/2011

LUST REG 2: Fuel Leak List

Standard Environmental Record Source: State and tribal leaking storage tank lists

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Number of Days to Update: 30
Telephone: 510-622-2433
Last EDR Contact :09/19/2011

LUST REG 3: Leaking Underground Storage Tank Database

Standard Environmental Record Source: State and tribal leaking storage tank lists

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Source: California Regional Water Quality Control Board Central Coast Region (3)
Number of Days to Update: 14
Telephone: 805-542-4786
Last EDR Contact :07/18/2011

LUST REG 4: Underground Storage Tank Leak List

Standard Environmental Record Source: State and tribal leaking storage tank lists

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Source: California Regional Water Quality Control Board Los Angeles Region (4)
Number of Days to Update: 35
Telephone: 213-576-6710
Last EDR Contact :09/06/2011

LUST REG 5: Leaking Underground Storage Tank Database

Standard Environmental Record Source: State and tribal leaking storage tank lists

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Source: California Regional Water Quality Control Board Central Valley Region (5)
Number of Days to Update: 9
Telephone: 916-464-4834
Last EDR Contact :07/01/2011

LUST REG 6L: Leaking Underground Storage Tank Case Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Source: California Regional Water Quality Control Board Lahontan Region (6)
Number of Days to Update: 27
Telephone: 530-542-5572
Last EDR Contact :09/12/2011

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Number of Days to Update: 22
Telephone: 760-241-7365
Last EDR Contact :09/12/2011

LUST REG 7: Leaking Underground Storage Tank Case Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Number of Days to Update: 27
Telephone: 760-776-8943
Last EDR Contact :08/01/2011

LUST REG 8: Leaking Underground Storage Tanks

Standard Environmental Record Source: State and tribal leaking storage tank lists

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Source: California Regional Water Quality Control Board Santa Ana Region (8)
Number of Days to Update: 41
Telephone: 909-782-4496
Last EDR Contact :08/15/2011

LUST REG 9: Leaking Underground Storage Tank Report

Standard Environmental Record Source: State and tribal leaking storage tank lists

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Source: California Regional Water Quality Control Board San Diego Region (9)
Number of Days to Update: 28
Telephone: 858-637-5595
Last EDR Contact :09/26/2011

LUST SANTA CLARA: LOP Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Source: Department of Environmental Health
Number of Days to Update: 13
Telephone: 408-918-3417
Last EDR Contact :05/25/2016

MARIN CO. UST: Underground Storage Tank Sites

Standard Environmental Record Source: State and tribal registered storage tank lists

Currently permitted USTs in Marin County.

Date of Government Version: 04/07/2016
Source: Public Works Department Waste Management
Number of Days to Update: 36
Telephone: 415-499-6647
Last EDR Contact :06/30/2016

MCS: Military Cleanup Sites Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The State Water Resources Control Board and nine Regional Water Quality Control Boards partner with the Department of Defense (DoD) through the Defense and State Memorandum of Agreement (DSMOA) to oversee the investigation and remediation of water quality issues at military facilities.

Date of Government Version: 03/14/2016
Source: State Water Resources Control Board
Number of Days to Update: 61
Telephone: 866-480-1028
Last EDR Contact :06/14/2016

MED WASTE VENTURA: Medical Waste Program List

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 03/28/2016
Number of Days to Update: 54
Last EDR Contact :07/25/2016
Source: Ventura County Resource Management Agency
Telephone: 805-654-2813

MINES: Mines Site Location Listing
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 03/15/2016
Number of Days to Update: 54
Last EDR Contact :06/14/2016
Source: Department of Conservation
Telephone: 916-322-1080

MWMP: Medical Waste Management Program Listing
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 05/25/2016
Number of Days to Update: 43
Last EDR Contact :06/07/2016
Source: Department of Public Health
Telephone: 916-558-1784

NAPA CO. LUST: Sites With Reported Contamination
Standard Environmental Record Source: State and tribal leaking storage tank lists
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 12/05/2011
Number of Days to Update: 63
Last EDR Contact :05/25/2016
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269

NAPA CO. UST: Closed and Operating Underground Storage Tank Sites
Standard Environmental Record Source: State and tribal registered storage tank lists
Underground storage tank sites located in Napa county.

Date of Government Version: 01/15/2008
Number of Days to Update: 23
Last EDR Contact :05/25/2016
Source: Napa County Department of Environmental Management
Telephone: 707-253-4269

NOTIFY 65: Proposition 65 Records
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 09/10/2015
Source: State Water Resources Control Board

Number of Days to Update: 38 Telephone: 916-445-3846
Last EDR Contact :06/30/2016

NPDES: NPDES Permits Listing
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of NPDES permits, including stormwater.

Date of Government Version: 05/16/2016 Source: State Water Resources Control Board
Number of Days to Update: 36 Telephone: 916-445-9379
Last EDR Contact :05/18/2016

ORANGE CO. LUST: List of Underground Storage Tank Cleanups
Standard Environmental Record Source: State and tribal leaking storage tank lists
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 05/01/2016 Source: Health Care Agency
Number of Days to Update: 35 Telephone: 714-834-3446
Last EDR Contact :05/09/2016

ORANGE CO. UST: List of Underground Storage Tank Facilities
Standard Environmental Record Source: State and tribal registered storage tank lists
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 05/01/2016 Source: Health Care Agency
Number of Days to Update: 21 Telephone: 714-834-3446
Last EDR Contact :05/11/2016

Orange Co. Industrial Site: List of Industrial Site Cleanups
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Petroleum and non-petroleum spills.

Date of Government Version: 05/01/2016 Source: Health Care Agency
Number of Days to Update: 35 Telephone: 714-834-3446
Last EDR Contact :05/09/2016

PEST LIC: Pesticide Regulation Licenses Listing
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 06/06/2016 Source: Department of Pesticide Regulation
Number of Days to Update: 43 Telephone: 916-445-4038
Last EDR Contact :06/07/2016

PLACER CO. MS: Master List of Facilities
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 03/07/2016
Number of Days to Update: 56
Last EDR Contact :06/15/2016
Source: Placer County Health and Human Services
Telephone: 530-745-2363

PROC: Certified Processors Database
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

A listing of certified processors.

Date of Government Version: 03/15/2016
Number of Days to Update: 54
Last EDR Contact :06/14/2016
Source: Department of Conservation
Telephone: 916-323-3836

RESPONSE: State Response Sites
Standard Environmental Record Source: State and tribal - equivalent NPL
Search Distance: 0.333 Mile

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 05/02/2016
Number of Days to Update: 48
Last EDR Contact :05/04/2016
Source: Department of Toxic Substances Control
Telephone: 916-323-3400

RIVERSIDE CO. LUST: Listing of Underground Tank Cleanup Sites
Standard Environmental Record Source: State and tribal leaking storage tank lists
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 04/13/2016
Number of Days to Update: 24
Last EDR Contact :06/20/2016
Source: Department of Environmental Health
Telephone: 951-358-5055

RIVERSIDE CO. UST: Underground Storage Tank Tank List
Standard Environmental Record Source: State and tribal registered storage tank lists
Underground storage tank sites located in Riverside county.

Date of Government Version: 04/13/2016
Number of Days to Update: 47
Last EDR Contact :06/20/2016
Source: Department of Environmental Health
Telephone: 951-358-5055

SAN DIEGO CO. HMMD: Hazardous Materials Management Division Database
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 09/23/2013
Number of Days to Update: 23
Source: Hazardous Materials Management Division
Telephone: 619-338-2268

Last EDR Contact :06/02/2016

SAN DIEGO CO. LF: Solid Waste Facilities

Standard Environmental Record Source: State and tribal landfill / solid waste disposal

San Diego County Solid Waste Facilities.

Date of Government Version: 10/31/2015
Number of Days to Update: 58
Last EDR Contact :07/20/2016

Source: Department of Health Services
Telephone: 619-338-2209

SAN DIEGO CO. SAM: Environmental Case Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

Search Distance: 0.333 Mile

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Number of Days to Update: 24
Last EDR Contact :06/02/2016

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371

SAN FRANCISCO CO. LUST: Local Oversite Facilities

Standard Environmental Record Source: State and tribal leaking storage tank lists

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Number of Days to Update: 10
Last EDR Contact :05/06/2016

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920

SAN FRANCISCO CO. UST: Underground Storage Tank Information

Standard Environmental Record Source: State and tribal registered storage tank lists

Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/29/2010
Number of Days to Update: 5
Last EDR Contact :05/06/2016

Source: Department of Public Health
Telephone: 415-252-3920

SAN JOSE HAZMAT: Hazardous Material Facilities

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 05/26/2016
Number of Days to Update: 49
Last EDR Contact :05/23/2016

Source: City of San Jose Fire Department
Telephone: 408-535-7694

SAN MATEO CO. LUST: Fuel Leak List

Standard Environmental Record Source: State and tribal leaking storage tank lists

A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/14/2016
Number of Days to Update: 55
Last EDR Contact :06/08/2016

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921

SCH: School Property Evaluation Program

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 05/02/2016
Source: Department of Toxic Substances Control
Number of Days to Update: 48
Telephone: 916-323-3400
Last EDR Contact :05/04/2016

SLIC: Statewide SLIC Cases

Standard Environmental Record Source: State and tribal leaking storage tank lists

Search Distance: 0.333 Mile

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 03/14/2016
Source: State Water Resources Control Board
Number of Days to Update: 61
Telephone: 866-480-1028
Last EDR Contact :06/14/2016

SLIC REG 1: Active Toxic Site Investigations

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Source: California Regional Water Quality Control Board, North Coast Region (1)
Number of Days to Update: 18
Telephone: 707-576-2220
Last EDR Contact :08/01/2011

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Number of Days to Update: 30
Telephone: 510-286-0457
Last EDR Contact :09/19/2011

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Source: California Regional Water Quality Control Board Central Coast Region (3)
Number of Days to Update: 28
Telephone: 805-549-3147
Last EDR Contact :07/18/2011

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Source: Region Water Quality Control Board Los Angeles Region (4)
Number of Days to Update: 47
Telephone: 213-576-6600
Last EDR Contact :07/01/2011

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Source: Regional Water Quality Control Board Central Valley Region (5)
Number of Days to Update: 16
Telephone: 916-464-3291
Last EDR Contact :09/12/2011

SLIC REG 6L: SLIC Sites

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Source: California Regional Water Quality Control Board, Lahontan Region
Number of Days to Update: 35
Telephone: 530-542-5574
Last EDR Contact :08/15/2011

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Source: Regional Water Quality Control Board, Victorville Branch
Number of Days to Update: 22
Telephone: 619-241-6583
Last EDR Contact :08/15/2011

SLIC REG 7: SLIC List

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Source: California Regional Quality Control Board, Colorado River Basin Region
Number of Days to Update: 36
Telephone: 760-346-7491
Last EDR Contact :08/01/2011

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Source: California Region Water Quality Control Board Santa Ana Region (8)
Number of Days to Update: 11
Telephone: 951-782-3298
Last EDR Contact :09/12/2011

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

Standard Environmental Record Source: State and tribal leaking storage tank lists

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Source: California Regional Water Quality Control Board San Diego Region (9)
Number of Days to Update: 17
Telephone: 858-467-2980
Last EDR Contact :08/08/2011

SOLANO CO. LUST: Leaking Underground Storage Tanks

Standard Environmental Record Source: State and tribal leaking storage tank lists

A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 03/14/2016
Source: Solano County Department of Environmental Management
Number of Days to Update: 48
Telephone: 707-784-6770
Last EDR Contact :06/08/2016

SOLANO CO. UST: Underground Storage Tanks

Standard Environmental Record Source: State and tribal registered storage tank lists

Underground storage tank sites located in Solano county.

Date of Government Version: 03/14/2016
Source: Solano County Department of Environmental Management
Number of Days to Update: 44
Telephone: 707-784-6770
Last EDR Contact :06/08/2016

SONOMA CO. LUST: Leaking Underground Storage Tank Sites

Standard Environmental Record Source: State and tribal leaking storage tank lists

A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 04/01/2016
Source: Department of Health Services
Number of Days to Update: 34
Telephone: 707-565-6565
Last EDR Contact :06/24/2016

SUTTER CO. UST: Underground Storage Tanks

Standard Environmental Record Source: State and tribal registered storage tank lists

Underground storage tank sites located in Sutter county.

Date of Government Version: 06/02/2016
Source: Sutter County Department of Agriculture
Number of Days to Update: 16
Telephone: 530-822-7500
Last EDR Contact :06/02/2016

SWEEPS UST: SWEEPS UST Listing

Standard Environmental Record Source: State and tribal registered storage tank lists

Search Distance: Property

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Source: State Water Resources Control Board
Number of Days to Update: 35
Telephone: Not Reported
Last EDR Contact :06/03/2005

SWF/LF (SWIS): Solid Waste Information System

Standard Environmental Record Source: State and tribal landfill / solid waste disposal
Search Distance: 0.333 Mile

Active, Closed and Inactive Landfills.SWF/LF records typically contain an inventory of solid waste disposal facilities or landfills.These may be active or inactive facilities or open dumps that failed to meet RCRA Section 4004 criteriafor solid waste landfills or disposal sites.

Date of Government Version: 05/16/2016
Source: Department of Resources Recycling and Recovery
Number of Days to Update: 34
Telephone: 916-341-6320
Last EDR Contact :05/18/2016

SWRCY: Recycler Database
Standard Environmental Record Source: State and tribal landfill / solid waste disposal
Search Distance: 0.333 Mile

A listing of recycling facilities in California.

Date of Government Version: 03/15/2016
Source: Department of Conservation
Number of Days to Update: 54
Telephone: 916-323-3836
Last EDR Contact :06/14/2016

Sacramento Co. CS: Toxic Site Clean-Up List
Standard Environmental Record Source: State and tribal leaking storage tank lists
Search Distance: 0.333 Mile

List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/02/2016
Source: Sacramento County Environmental Management
Number of Days to Update: 56
Telephone: 916-875-8406
Last EDR Contact :07/06/2016

Sacramento Co. ML: Master Hazardous Materials Facility List
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/02/2016
Source: Sacramento County Environmental Management
Number of Days to Update: 56
Telephone: 916-875-8406
Last EDR Contact :07/05/2016

San Bern. Co. Permit: Hazardous Material Permits
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 06/09/2016
Source: San Bernardino County Fire Department Hazardous Materials Division
Number of Days to Update: 40
Telephone: 909-387-3041
Last EDR Contact :05/09/2016

San Mateo Co. BI: Business Inventory
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.25 Mile

List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 06/02/2016
Number of Days to Update: 15
Last EDR Contact :05/27/2016
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921

TORRANCE UST: City of Torrance Underground Storage Tank
Standard Environmental Record Source: State and tribal registered storage tank lists
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 04/05/2016
Number of Days to Update: 36
Last EDR Contact :07/07/2016
Source: City of Torrance Fire Department
Telephone: 310-618-2973

TOXIC PITS: Toxic Pits Cleanup Act Sites
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Number of Days to Update: 27
Last EDR Contact :01/26/2009
Source: State Water Resources Control Board
Telephone: 916-227-4364

UIC: UIC Listing
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 02/12/2016
Number of Days to Update: 89
Last EDR Contact :06/16/2016
Source: Deaprtment of Conservation
Telephone: 916-445-2408

UST: Active UST Facilities
Standard Environmental Record Source: State and tribal registered storage tank lists
Search Distance: Property

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 03/14/2016
Number of Days to Update: 49
Last EDR Contact :06/14/2016
Source: SWRCB
Telephone: 916-341-5851

UST MENDOCINO: Mendocino County UST Database
Standard Environmental Record Source: State and tribal registered storage tank lists
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 06/07/2016
Number of Days to Update: 14
Last EDR Contact :06/01/2016
Source: Department of Public Health
Telephone: 707-463-4466

UST SAN JOAQUIN: San Joaquin Co. UST
Standard Environmental Record Source: State and tribal registered storage tank lists

A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 04/06/2016
Number of Days to Update: 26
Last EDR Contact :06/15/2016
Source: Environmental Health Department
Telephone: Not Reported

VCP: Voluntary Cleanup Program Properties

Standard Environmental Record Source: State and tribal voluntary cleanup sites
Search Distance: 0.333 Mile

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 05/02/2016
Number of Days to Update: 48
Last EDR Contact :05/04/2016
Source: Department of Toxic Substances Control
Telephone: 916-323-3400

VENTURA CO. BWT: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 03/28/2016
Number of Days to Update: 49
Last EDR Contact :07/25/2016
Source: Ventura County Environmental Health Division
Telephone: 805-654-2813

VENTURA CO. LF: Inventory of Illegal Abandoned and Inactive Sites

Standard Environmental Record Source: State and tribal landfill / solid waste disposal
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Number of Days to Update: 49
Last EDR Contact :06/28/2016
Source: Environmental Health Division
Telephone: 805-654-2813

VENTURA CO. LUST: Listing of Underground Tank Cleanup Sites

Standard Environmental Record Source: State and tribal leaking storage tank lists
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Number of Days to Update: 37
Last EDR Contact :05/13/2016
Source: Environmental Health Division
Telephone: 805-654-2813

VENTURA CO. UST: Underground Tank Closed Sites List

Standard Environmental Record Source: State and tribal registered storage tank lists
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 02/26/2016
Number of Days to Update: 48
Last EDR Contact :06/16/2016
Source: Environmental Health Division
Telephone: 805-654-2813

WDS: Waste Discharge System

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Number of Days to Update: 9
Last EDR Contact :05/20/2016
Source: State Water Resources Control Board
Telephone: 916-341-5227

WIP: Well Investigation Program Case List

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Number of Days to Update: 13
Last EDR Contact :06/24/2016
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726

WMUDS/SWAT: Waste Management Unit Database

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Number of Days to Update: 30
Last EDR Contact :05/06/2016
Source: State Water Resources Control Board
Telephone: 916-227-4448

YOLO CO. UST: Underground Storage Tank Comprehensive Facility Report

Standard Environmental Record Source: State and tribal registered storage tank lists
Underground storage tank sites located in Yolo county.

Date of Government Version: 04/12/2016
Number of Days to Update: 43
Last EDR Contact :06/30/2016
Source: Yolo County Department of Health
Telephone: 530-666-8646

2020 COR ACTION: 2020 Corrective Action Program List

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.25 Mile

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Number of Days to Update: 6
Last EDR Contact :05/12/2016
Source: Environmental Protection Agency
Telephone: 703-308-4044

COAL ASH DOE: Steam-Electric Plant Operation Data

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Number of Days to Update: 76
Last EDR Contact :06/09/2016
Source: Department of Energy
Telephone: 202-586-8719

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Number of Days to Update: 40
Last EDR Contact :06/10/2016
Source: Environmental Protection Agency
Telephone: Not Reported

CONSENT: Superfund (CERCLA) Consent Decrees
Standard Environmental Record Source: Federal NPL
Search Distance: 0.333 Mile

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2014
Number of Days to Update: 46
Last EDR Contact :07/15/2016
Source: Department of Justice, Consent Decree Library
Telephone: Varies

CORRACTS: Corrective Action Report
Standard Environmental Record Source: Federal RCRA CORRACTS facilities list
Search Distance: 0.333 Mile

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/09/2015
Number of Days to Update: 34
Last EDR Contact :06/30/2016
Source: EPA
Telephone: 800-424-9346

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
Standard Environmental Record Source: State and tribal landfill / solid waste disposal
Search Distance: 0.333 Mile

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Number of Days to Update: 137
Last EDR Contact :07/20/2016
Source: EPA, Region 9
Telephone: 415-947-4219

DOT OPS: Incident and Accident Data
Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Number of Days to Update: 42
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595

Last EDR Contact :05/04/2016

Delisted NPL: National Priority List Deletions

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 03/07/2016 Source: EPA

Number of Days to Update: 10 Telephone: Not Reported

Last EDR Contact :07/07/2016

ECHO: Enforcement & Compliance History Information

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/20/2015 Source: Environmental Protection Agency

Number of Days to Update: 103 Telephone: 202-564-2280

Last EDR Contact :06/22/2016

EPA WATCH LIST: EPA WATCH LIST

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013 Source: Environmental Protection Agency

Number of Days to Update: 88 Telephone: 617-520-3000

Last EDR Contact :05/09/2016

ERNS: Emergency Response Notification System

Standard Environmental Record Source: Federal ERNS list

Search Distance: Property

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/28/2016 Source: National Response Center, United States Coast Guard

Number of Days to Update: 51 Telephone: 202-267-2180

Last EDR Contact :06/28/2016

FEMA UST: Underground Storage Tank Listing

Standard Environmental Record Source: State and tribal registered storage tank lists

Search Distance: Property

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010 Source: FEMA

Number of Days to Update: 55 Telephone: 202-646-5797

Last EDR Contact :07/07/2016

FINDS: Facility Index System/Facility Registry System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 07/20/2015 Source: EPA

Number of Days to Update: 55 Telephone: Not Reported

Last EDR Contact :06/08/2016

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Number of Days to Update: 25 Telephone: 202-566-1667

Last EDR Contact :05/20/2016

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Standard Environmental Record Source: Other Standard Environmental Records

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Source: EPA

Number of Days to Update: 25 Telephone: 202-566-1667

Last EDR Contact :05/20/2016

FUDS: Formerly Used Defense Sites

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015 Source: U.S. Army Corps of Engineers

Number of Days to Update: 97 Telephone: 202-528-4285

Last EDR Contact :06/10/2016

FUELS PROGRAM: EPA Fuels Program Registered Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/24/2016 Source: EPA

Number of Days to Update: 49 Telephone: 800-385-6164

Last EDR Contact :05/25/2016

FUSRAP: Formerly Utilized Sites Remedial Action Program

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/11/2016
Source: Department of Energy
Number of Days to Update: 80
Telephone: 202-586-3559
Last EDR Contact :06/20/2016

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Source: Environmental Protection Agency
Number of Days to Update: 40
Telephone: 202-564-2501
Last EDR Contact :12/17/2007

HMIRS: Hazardous Materials Information Reporting System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/24/2015
Source: U.S. Department of Transportation
Number of Days to Update: 68
Telephone: 202-366-4555
Last EDR Contact :06/28/2016

ICIS: Integrated Compliance Information System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 01/23/2015
Source: Environmental Protection Agency
Number of Days to Update: 31
Telephone: 202-564-5088
Last EDR Contact :07/07/2016

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal leaking storage tank lists

Search Distance: 0.333 Mile

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/27/2015
Source: EPA Region 1
Number of Days to Update: 67
Telephone: 617-918-1313

Last EDR Contact :07/29/2016

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 01/07/2016
Number of Days to Update: 41
Last EDR Contact :07/27/2016
Source: EPA Region 10
Telephone: 206-553-2857

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 02/05/2016
Number of Days to Update: 35
Last EDR Contact :07/26/2016
Source: EPA Region 4
Telephone: 404-562-8677

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 02/17/2016
Number of Days to Update: 37
Last EDR Contact :07/27/2016
Source: EPA, Region 5
Telephone: 312-886-7439

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 12/11/2015
Number of Days to Update: 105
Last EDR Contact :07/27/2016
Source: EPA Region 6
Telephone: 214-665-6597

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/09/2015
Number of Days to Update: 112
Last EDR Contact :07/27/2016
Source: EPA Region 7
Telephone: 913-551-7003

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/13/2015
Number of Days to Update: 118
Last EDR Contact :07/27/2016
Source: EPA Region 8
Telephone: 303-312-6271

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
Standard Environmental Record Source: State and tribal leaking storage tank lists
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 02/25/2016
Number of Days to Update: 37
Last EDR Contact :07/27/2016

Source: Environmental Protection Agency
Telephone: 415-972-3372

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Number of Days to Update: 52
Last EDR Contact :04/27/2016

Source: Environmental Protection Agency
Telephone: 703-308-8245

INDIAN UST R1: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

Search Distance: Property

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/20/2015
Number of Days to Update: 67
Last EDR Contact :07/29/2016

Source: EPA, Region 1
Telephone: 617-918-1313

INDIAN UST R10: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 01/07/2016
Number of Days to Update: 41
Last EDR Contact :07/27/2016

Source: EPA Region 10
Telephone: 206-553-2857

INDIAN UST R4: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 02/05/2016
Number of Days to Update: 35
Last EDR Contact :07/26/2016

Source: EPA Region 4
Telephone: 404-562-9424

INDIAN UST R5: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/05/2015
Number of Days to Update: 52
Last EDR Contact :07/27/2016

Source: EPA Region 5
Telephone: 312-886-6136

INDIAN UST R6: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 12/03/2015
Source: EPA Region 6
Number of Days to Update: 120
Telephone: 214-665-7591
Last EDR Contact :07/27/2016

INDIAN UST R7: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/23/2014
Source: EPA Region 7
Number of Days to Update: 65
Telephone: 913-551-7003
Last EDR Contact :07/27/2016

INDIAN UST R8: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 01/26/2016
Source: EPA Region 8
Number of Days to Update: 119
Telephone: 303-312-6137
Last EDR Contact :07/27/2016

INDIAN UST R9: Underground Storage Tanks on Indian Land

Standard Environmental Record Source: State and tribal registered storage tank lists

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/25/2016
Source: EPA Region 9
Number of Days to Update: 37
Telephone: 415-972-3368
Last EDR Contact :07/27/2016

INDIAN VCP R1: Voluntary Cleanup Priority Listing

Standard Environmental Record Source: State and tribal voluntary cleanup sites

Search Distance: Property

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Source: EPA, Region 1
Number of Days to Update: 142
Telephone: 617-918-1102
Last EDR Contact :07/01/2016

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

Standard Environmental Record Source: State and tribal voluntary cleanup sites

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Source: EPA, Region 7
Number of Days to Update: 27
Telephone: 913-551-7365
Last EDR Contact :04/20/2009

LEAD SMELTER 1: Lead Smelter Sites

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A listing of former lead smelter site locations.

Date of Government Version: 11/25/2014
Number of Days to Update: 64
Last EDR Contact :07/08/2016
Source: Environmental Protection Agency
Telephone: 703-603-8787

LEAD SMELTER 2: Lead Smelter Sites

Standard Environmental Record Source: Other Standard Environmental Records

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Number of Days to Update: 36
Last EDR Contact :12/02/2009
Source: American Journal of Public Health
Telephone: 703-305-6451

LIENS 2: CERCLA Lien Information

Standard Environmental Record Source: Federal CERCLIS

Search Distance: Property

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Number of Days to Update: 37
Last EDR Contact :07/29/2016
Source: Environmental Protection Agency
Telephone: 202-564-6023

LUCIS: Land Use Control Information System

Standard Environmental Record Source: Federal institutional controls / engineering controls registries

Search Distance: 0.333 Mile

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/28/2015
Number of Days to Update: 13
Last EDR Contact :05/16/2016
Source: Department of the Navy
Telephone: 843-820-7326

MLTS: Material Licensing Tracking System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/07/2016
Number of Days to Update: 28
Last EDR Contact :05/06/2016
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169

NPL: National Priority List

Standard Environmental Record Source: Federal NPL

Search Distance: 0.333 Mile

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 03/07/2016
Source: EPA
Number of Days to Update: 10
Telephone: Not Reported
Last EDR Contact :07/07/2016

NPL Site Boundaries

Sources:

EPA"s Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-566-0690

EPA Region 1
Telephone: 617-918-1102

EPA Region 2
Telephone: 212-637-4293

EPA Region 3
Telephone: 215-814-5418

EPA Region 4
Telephone: 404-562-8681

EPA Region 5
Telephone: 312-353-1063

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6118

EPA Region 9
Telephone: 415-947-4579

EPA Region 10
Telephone: 206-553-4479

NPL LIENS: Federal Superfund Liens

Standard Environmental Record Source: Federal NPL

Search Distance: Property

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Source: EPA
Number of Days to Update: 56
Telephone: 202-564-4267
Last EDR Contact :08/15/2011

ODI: Open Dump Inventory

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Source: Environmental Protection Agency
Number of Days to Update: 39
Telephone: 800-424-9346

Last EDR Contact :06/09/2004

PADS: PCB Activity Database System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2014 Source: EPA

Number of Days to Update: 33 Telephone: 202-566-0500

Last EDR Contact :07/15/2016

PCB TRANSFORMER: PCB Transformer Registration Database

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011 Source: Environmental Protection Agency

Number of Days to Update: 83 Telephone: 202-566-0517

Last EDR Contact :07/29/2016

Proposed NPL: Proposed National Priority List Sites

Standard Environmental Record Source: Federal NPL

Search Distance: 0.333 Mile

A site that has been proposed for listing on the NationalPriorities List through the issuance of a proposed rule in the Federal Register.EPA then accepts public comments on the site, responds to the comments,and places on the NPL those sites that continue to meet therequirements for listing.

Date of Government Version: 03/07/2016 Source: EPA

Number of Days to Update: 10 Telephone: Not Reported

Last EDR Contact :07/07/2016

RAATS: RCRA Administrative Action Tracking System

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Source: EPA

Number of Days to Update: 35 Telephone: 202-564-4104

Last EDR Contact :06/02/2008

RADINFO: Radiation Information Database

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/07/2015 Source: Environmental Protection Agency

Number of Days to Update: 69 Telephone: 202-343-9775

Last EDR Contact :07/07/2016

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/09/2015 Source: Environmental Protection Agency

Number of Days to Update: 34 Telephone: 703-308-8895

Last EDR Contact :06/30/2016

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

Standard Environmental Record Source: Federal RCRA generators list

Search Distance: Property

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015 Source: Environmental Protection Agency

Number of Days to Update: 34 Telephone: 703-308-8895

Last EDR Contact :06/30/2016

RCRA-LQG: RCRA - Large Quantity Generators

Standard Environmental Record Source: Federal RCRA generators list

Search Distance: Property

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/09/2015 Source: Environmental Protection Agency

Number of Days to Update: 34 Telephone: 703-308-8895

Last EDR Contact :06/30/2016

RCRA-SQG: RCRA - Small Quantity Generators

Standard Environmental Record Source: Federal RCRA generators list

Search Distance: Property

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/09/2015 Source: Environmental Protection Agency

Number of Days to Update: 34 Telephone: 703-308-8895

Last EDR Contact :06/30/2016

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

Standard Environmental Record Source: Federal RCRA TSD facilities list

Search Distance: 0.333 Mile

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/09/2015
Number of Days to Update: 34
Last EDR Contact :06/30/2016

Source: Environmental Protection Agency
Telephone: 703-308-8895

ROD: Records Of Decision

Standard Environmental Record Source: Federal NPL

Search Distance: 0.333 Mile

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Number of Days to Update: 74
Last EDR Contact :06/07/2016

Source: EPA
Telephone: 703-416-0223

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011
Number of Days to Update: 54
Last EDR Contact :05/20/2016

Source: Environmental Protection Agency
Telephone: 615-532-8599

SEMS: Superfund Enterprise Management System

Standard Environmental Record Source: Federal CERCLIS

Search Distance: 0.333 Mile

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 03/07/2016
Number of Days to Update: 10
Last EDR Contact :07/22/2016

Source: EPA
Telephone: 800-424-9346

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 03/07/2016 Source: EPA
Number of Days to Update: 10 Telephone: 800-424-9346
Last EDR Contact :07/22/2016

SSTS: Section 7 Tracking Systems

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Source: EPA
Number of Days to Update: 77 Telephone: 202-564-4203
Last EDR Contact :07/25/2016

TRIS: Toxic Chemical Release Inventory System

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014 Source: EPA
Number of Days to Update: 133 Telephone: 202-566-0250
Last EDR Contact :05/24/2016

TSCA: Toxic Substances Control Act

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012 Source: EPA
Number of Days to Update: 14 Telephone: 202-260-5521
Last EDR Contact :06/24/2016

UMTRA: Uranium Mill Tailings Sites

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010 Source: Department of Energy
Number of Days to Update: 146 Telephone: 505-845-0011

Last EDR Contact :05/23/2016

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/20/2015 Source: EPA

Number of Days to Update: 69 Telephone: 202-564-2496

Last EDR Contact :06/22/2016

US AIRS MINOR: Air Facility System Data

Standard Environmental Record Source: Other Standard Environmental Records

A listing of minor source facilities.

Date of Government Version: 10/20/2015 Source: EPA

Number of Days to Update: 69 Telephone: 202-564-2496

Last EDR Contact :06/22/2016

US BROWNFIELDS: A Listing of Brownfields Sites

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: 0.333 Mile

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/21/2016 Source: Environmental Protection Agency

Number of Days to Update: 113 Telephone: 202-566-2777

Last EDR Contact :06/22/2016

US CDL: Clandestine Drug Labs

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/04/2016 Source: Drug Enforcement Administration

Number of Days to Update: 40 Telephone: 202-307-1000

Last EDR Contact :05/31/2016

US ENG CONTROLS: Engineering Controls Sites List

Standard Environmental Record Source: Federal institutional controls / engineering controls registries

Search Distance: Property

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 09/10/2015
Number of Days to Update: 53
Last EDR Contact :05/25/2016

Source: Environmental Protection Agency
Telephone: 703-603-0695

US FIN ASSUR: Financial Assurance Information

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/01/2015
Number of Days to Update: 61
Last EDR Contact :05/18/2016

Source: Environmental Protection Agency
Telephone: 202-566-1917

US HIST CDL: National Clandestine Laboratory Register

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/04/2016
Number of Days to Update: 40
Last EDR Contact :05/31/2016

Source: Drug Enforcement Administration
Telephone: 202-307-1000

US INST CONTROL: Sites with Institutional Controls

Standard Environmental Record Source: Federal institutional controls / engineering controls registries

Search Distance: Property

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 09/10/2015
Number of Days to Update: 53
Last EDR Contact :05/25/2016

Source: Environmental Protection Agency
Telephone: 703-603-0695

US MINES: Mines Master Index File

Standard Environmental Record Source: Other Standard Environmental Records

Search Distance: Property

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/09/2016
Number of Days to Update: 44
Last EDR Contact :06/02/2016

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959

AOCONCERN: San Gabriel Valley Areas of Concern

Standard Environmental Record Source: State and tribal - equivalent CERCLIS

Search Distance: 0.333 Mile

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 03/30/2009
Number of Days to Update: 206
Last EDR Contact :06/15/2016

Source: EPA Region 9
Telephone: 415-972-3178

DOD: Department of Defense Sites

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: 0.333 Mile

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Number of Days to Update: 62
Last EDR Contact :07/15/2016

Source: USGS
Telephone: 888-275-8747

INDIAN RESERV: Indian Reservations

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005
Number of Days to Update: 34
Last EDR Contact :07/15/2016

Source: USGS
Telephone: 202-208-3710

PWS: Public Water System Data

Standard Environmental Record Source: Other Standard Environmental Records
Search Distance: Property

This Safe Drinking Water Information System (SDWIS) file contains public water systems name and address, population served and the primary source of water

Date of Government Version: 12/17/2013
Number of Days to Update: 279
Last EDR Contact :05/31/2016

Source: EPA
Telephone: Not Reported

RECORD SOURCES AND CURRENCY

HISTORICAL USE RECORDS

RGA LF: Recovered Government Archive Solid Waste Facilities List

Standard Environmental Record Source: Exclusive Recovered Govt. Archives

Search Distance: Property

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: Not Reported
Source: Department of Resources Recycling and Recovery
Number of Days to Update: 196
Telephone: Not Reported
Last EDR Contact :06/01/2012

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

Standard Environmental Record Source: Exclusive Recovered Govt. Archives

Search Distance: Property

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: Not Reported
Source: State Water Resources Control Board
Number of Days to Update: 182
Telephone: Not Reported
Last EDR Contact :06/01/2012

EDR Hist Auto: EDR Exclusive Historic Gas Stations

Standard Environmental Record Source: Historical Gas Stations

Search Distance: 0.125 Mile

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: 02/20/2007
Source: EDR, Inc.
Number of Days to Update: 42
Telephone: Not Reported
Last EDR Contact :02/21/2007

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

Standard Environmental Record Source: Historical Dry Cleaners

Search Distance: 0.125 Mile

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: 02/20/2007
Source: EDR, Inc.
Number of Days to Update: 42
Telephone: Not Reported
Last EDR Contact :02/21/2007

EDR MGP: EDR Proprietary Manufactured Gas Plants

Standard Environmental Record Source: Former manufactured Gas Plants

Search Distance: 0.333 Mile

RECORD SOURCES AND CURRENCY

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: 08/28/2009
Number of Days to Update: 55
Last EDR Contact :11/30/2012

Source: EDR, Inc.
Telephone: Not Reported

RECORD SOURCES AND CURRENCY

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5' minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW® Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW® Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services. The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

STREET AND ADDRESS INFORMATION

© 2006 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix 12 - Summary Resume

SHERWOOD LOVEJOY, JR., P.G., R.E.A., C.E.I., C.E.C., C.M.A., C.M.I.
Principal Consulting Hydrogeologist / Registered Environmental Assessor

Years of Experience with This Firm: 22 **with Other Firms:** 9

Education: Degree(s) / Year / Specialization:

- M.S., 1993, Environmental Science and Management, University of San Francisco
- B.A., 1982, Geology, University of Rhode Island, Kingston, Rhode Island
- B.S., 1981, Zoology, University of Rhode Island, Kingston, Rhode Island
- Graduate Studies, 1982 - 1983 Hydrology, Geophysics, Advanced Structural Geology and Geochemistry, University of Maryland, College Park, Maryland

Active Registrations:

- Professional Geologist #TN-1566, State of Tennessee
- Professional Geologist #PG-2166, State of Wyoming
- Registered Environmental Assessor # REA (I)-03171, State of California
- General Engineering Contractor's (Class A) #540389, State of California
- Class A - Hazardous Waste Removal Certification #540389, State of California
- Well Driller License (C-57), #540389, State of California
- Certified Environmental Inspector #6331, National Registration for EAA,
- Certified Environmental Consultant, #6331, National Registration for EAA
- Certified Mold Assessor, #6331, National Registration for EAA
- Certified Mold Inspector, #6331, National Registration for EAA
- 40 Hour OSHA and 8 Hour OSHA Management Training

Experience and Qualifications:

- 1991-Present - Principal Consulting Hydrogeologist, The Consulting Group (TCG)
- 1994 -1995 - President/Principal Hydrogeologist, MRD - Environmental Services, Inc.
- 1990 -1991 - President/CEO/Principal Hydrogeologist, Hawaiian Geologic Resources, Inc.
- 1988 -1991 - President/CEO/Principal Hydrogeologist, Western Geologic Resources, Inc.
  - Environmental Site Investigation & Assessment
  - Remediation Strategy Development
  - Facility Demolition/Plant Reclamation Strategy Development and Oversight
  - Underground Tank Compliance & Soil Remediation of Fuel Contamination
  - Demolition/Reconstruction Management and Oversight
  - Hydrogeological Assessment and Modeling
  - Groundwater Monitor Well Installation, Sampling, and Monitoring
  - Chemical Stabilization of Metals and pH in Soil
  - Mine Audits, Investigations, Reclamation Studies, and Reclamation Design
  - Regulatory Liaison, Negotiation, and Site Closure
  - Construction Management and Contractor Oversight

Mr. Lovejoy heads TCG's surface and subsurface contamination investigation and remediation program. Clients are well represented by Mr. Lovejoy's extensive experience and expertise in the latest soil and groundwater investigation and remediation techniques and methods. In addition, clients benefit as they are skillfully represented during regulatory agency interaction, negotiation and permitting.