Phase I Environmental Site Assessment

br40345
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752



Prepared for:
Link Logistics Real Estate
220 Commerce Drive, Suite 400
Fort Washington, Pennsylvania 19034

Citibank, N.A., Citigroup Global Markets Realty Corp. and Citi Real Estate Funding Inc.
388 Greenwich Street – 8 th Floor
New York, NY 10013

Bank of Montreal c/o BMO Capital Markets Corp.
151 West 42nd Street
New York, NY 10036

Barclays Capital Real Estate Inc.
745 Seventh Avenue
New York, NY 10019

Prepared by:
Professional Service Industries, Inc.
11980 Telegraph Rd. #104
Santa Fe Springs, California 90670

April 14, 2021 (April 1, 2021)

PSI Project Number: 00662058-13

Teira Solis, GIT
Staff Scientist

Jeff Townsend, LEP, REPA, LPG
Principal Consultant

Project Summary

Report Section		No Issues Identified	Routine Solution	REC	HREC	CREC	VEC	De-Minimis	Notes
1.2.1	Recognized Environmental Conditions	✔							
1.2.2	Controlled Recognized Environmental Conditions	✔							
1.2.3	Historical Recognized Environmental Conditions	✔							
1.2.4	Vapor Encroachment Conditions	✔							
1.2.5	De Minimis Conditions	✔							
1.3.1	VISUAL ASBESTOS SURVEY	✔							Suspect ACMs were observed.
1.3.2	VISUAL LEAD-BASED PAINT SURVEY	✔							
1.3.3	RADON RECORDS REVIEW	✔							
1.3.4	LEAD IN DRINKING WATER RECORDS REVIEW	✔							
1.3.5	HISTORICAL OIL AND GAS WELLS RECORDS REVIEW	✔							
3.0	USER-PROVIDED INFORMATION	✔							

Report Section		No Issues Identified	Routine Solution	REC	HREC	CREC	VEC	De-Minimis	Notes
5.0	SITE RECONNAISSANCE	✔							
5.2	SUBJECT PROPERTY OBSERVATIONS	✔							
5.3	OFF-SITE OBSERVATIONS	✔							
6.0	HISTORICAL USES	✔							
7.0	ENVIRONMENTAL REGULATORY RECORDS REVIEW	✔							
8.0	VAPOR ENCROACHMENT SCREENING	✔							

TABLE OF CONTENTS

LIST OF COMMONLY USED ACRONYMS AND ABBREVIATIONS . . . . . **v**

CERTIFICATION . . . . . **viii**

1.0 EXECUTIVE SUMMARY **1**

1.1 FINDINGS 1

1.2 CONCLUSIONS 3

1.3 NON-SCOPE CONSIDERATIONS - OTHER BUSINESS ENVIRONMENTAL RISKS 4

1.4 RECOMMENDATIONS 7

2.0 PHASE I ESA SCOPE AND METHODOLOGY **8**

2.1 PURPOSE OF SERVICES 8

2.2 PHASE I ESA METHODOLOGY 8

2.3 LIMITATIONS, EXCEPTIONS, DEVIATIONS AND DATA GAP 9

2.4 SIGNIFICANT ASSUMPTIONS 9

3.0 USER-PROVIDED INFORMATION **10**

3.1 USER QUESTIONNAIRE 10

3.2 TITLE RECORDS 12

3.3 SUGGESTED INFORMATION 12

3.4 HELPFUL DOCUMENTS 12

4.0 PHYSICAL SETTING **14**

5.0 SITE RECONNAISSANCE **16**

5.1 SUBJECT PROPERTY DESCRIPTION AND CURRENT USES 16

5.2 SUBJECT PROPERTY OBSERVATIONS 17

5.3 OFF-SITE OBSERVATIONS 21

6.0 HISTORICAL USES **24**

6.1 SUMMARY OF RESOURCES 24

6.2 CURRENT AND PRIOR USE INTERVIEWS 25

6.3 PRIOR INVESTIGATIONS 25

6.4 CITY DIRECTORIES 25

6.5 SUMMARY HISTORY OF SITE AND SURROUNDING AREA 25

7.0 ENVIRONMENTAL REGULATORY RECORDS REVIEW **29**

7.1 DATABASE FINDINGS 29
7.2 REGULATORY AGENCY INQUIRIES 42
8.0 VAPOR ENCROACHMENT SCREENING 44
8.1 METHODOLOGY 44
8.2 VES RESULTS 46
8.3 VES LIMITATIONS 47
9.0 NON-SCOPE CONSIDERATIONS 48
9.1 VISUAL ASBESTOS SURVEY 48
9.2 VISUAL LEAD-BASED PAINT SURVEY 49
9.3 RADON RECORDS REVIEW 49
9.4 LEAD IN DRINKING WATER RECORDS REVIEW 50
9.5 HISTORICAL OIL AND GAS WELLS RECORDS REVIEW 50
10.0 CONTRACT INFORMATION 51
10.1 STANDARD OF CARE AND WARRANTIES 51
10.2 RELIANCE 51
10.3 USE BY OTHER PARTIES 53

LIST OF APPENDICES

FIGURES
PHOTOGRAPHS
ENVIRONMENTAL DATABASE REPORT
USER QUESTIONNAIRE RESPONSES
HISTORICAL RESEARCH DOCUMENTATION
INTERVIEW DOCUMENTATION
DATA GAP WORKSHEET
SUPPLEMENTAL DOCUMENTATION
VAPOR ENCROACHMENT SCREENING DOCUMENTATION
PERSONNEL QUALIFICATIONS

LIST OF COMMONLY USED ACRONYMS AND ABBREVIATIONS

ACM	Asbestos-Containing Material
AHERA	Asbestos Hazard Emergency Response Act
AMSL	Above Mean Sea Level
APN	Assessor's Parcel Number (also referred to as a PIN)
AST	Above-Ground Storage Tank
ASTM	American Society for Testing and Materials
AUL	Activity & Use Limitation
BER	Business Environmental Risk
Bgs	Below the ground surface
BTEX	Benzene, Toluene, Ethylbenzene, Xylenes
CADC	California Department of Conservation
CADWR	California Department of Water Resources
CAEPA	California Environmental Protection Agency
CERCLA	Comprehensive Environmental Response, Compensation & Liability Act
CERCLIS	Comprehensive Environmental Response, Compensation & Liability Information System (now called SEMS)
CESQG	Conditionally Exempt Small Quantity Generator of Hazardous Waste (now called VSQG)
CFR	Code of Federal Regulations
COC	Chemical(s) of Concern
CREC	Controlled Recognized Environmental Condition
CWA	Clean Water Act
EDR	Environmental Data Resources, Inc.
EP	Environmental Professional
EPA	U.S. Environmental Protection Agency
ERIS	Environmental Risk Information Services, Inc.
ESA	Environmental Site Assessment
FEMA	Federal Emergency Management Agency
FOIA	Freedom of Information Act

HREC	Historical Recognized Environmental Condition
HUD	U.S. Department of Housing & Urban Development
HVAC	Heating, Ventilation & Air Conditioning System
LAST	Leaking Above-Ground Storage Tank
LBP	Lead-Based Paint
LLP	Landowner Liability Protection
LQG	Large Quantity Generator of Hazardous Waste
LUST/ LST	Leaking Underground Storage Tank
MCL	Maximum Concentration Level
mg/kg	Milligrams per Kilogram
mg/L	Micrograms per liter
mg/L	Milligrams per Liter
MSDS	Material Safety Data Sheet (now called Safety Data Sheet (SDS))
MTBE	Methyl Tert-Butyl Ether
ND	Not Detected
NFA	No Further Action (also called No Further Remediation (NFR))
NOV	Notice of Violation
NPDES	National Pollution Discharge Elimination System
NPL	National Priorities List (a.k.a. Superfund)
NRCS	Natural Resources Conservation Service
NWI	National Wetlands Inventory
OSHA	U.S. Occupational Safety & Health Administration
PAH	Polynuclear (Polycyclic) Aromatic Hydrocarbons
PCB	Polychlorinated Biphenyl
PCE	Perchloroethylene (also called Tetrachloroethylene)
pCi/L	Picocuries per Liter
PFAS	Per & Polyfluoroalkyl Substances
PFOA	Perfluorooctanoic Acid

PFOS	Perfluorooctanesulfonic Acid
ppb	Parts per Billion
ppm	Parts per Million
RBCA	Risk-Based Corrective Action
RCRA	Resource Conservation & Recovery Act
REC	Recognized Environmental Condition
RFI	Request for Information
SF	Square Feet
SQG	Small Quantity Generator of Hazardous Waste
SSURGO	Soil Survey Geographic Database
TCE	Trichloroethylene
TPH	Total Petroleum Hydrocarbons
USACE	U.S. Army Corps of Engineers
USDA	U.S. Department of Agriculture
USFWS	U.S. Fish & Wildlife Service
USGS	U.S. Geological Survey
UST	Underground Storage Tank
VEC	Vapor Encroachment Condition
VES	Vapore Encroachment Screening
VIC	Vapor Intrusion Condition
VOC	Volatile Organic Compound

CERTIFICATION

PSI, an Intertek company, has completed a Phase I ESA of br40345 located at 3401 Etiwanda Avenue - Bldg 1011 in Jurupa Valley, California ("the subject property"). PSI performed the Phase I ESA in accordance with ASTM E1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (the Practice). The assessment was completed at the request of Link Logistics Real Estate ("the client") in accordance with the scope of work outlined in PSI's Proposal Number 315-251172RO, which was authorized by the client on March 24, 2021.

The conclusions developed herein represent our professional judgment based on information and data available to us at the time of the assessment, and observations made at the time of our site reconnaissance. In accordance with ASTM E1527-13 § 4.6, the report is valid for a period of 180 days from the time of issuance.

Site Assessor:

Teira Solis, GIT
Staff Scientist

Reviewed by:

Jeff Townsend, LEP, REPA
Principal Consultant

Environmental Professional Certification

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 312.10 of this part. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Environmental Professional:

Teira Solis, GIT
Environmental Professional

1.0 EXECUTIVE SUMMARY

PSI, an Intertek company, performed a Phase I ESA of br40345 located at 3401 Etiwanda Avenue - Bldg 1011, in Jurupa Valley, California, 91752. PSI performed the assessment to comply with the contract between Link Logistics Real Estate (the client) and PSI.

Our assessment included a Phase I ESA, and evaluation of certain business environmental risks that are beyond the scope of ASTM E1527, as follows: visual asbestos survey, visual lead based paint survey, radon, lead in drinking water, and historical oil and gas wells evaluation.

This Phase I ESA was performed in accordance with ASTM E1527-13 Standard Practice for Environmental Assessment: The Phase I Environmental Site Assessment Process and Citi's Third Party Report Scope of Work dated June 2020.

1.1 FINDINGS

A summary of findings is provided below. The report should be read in its entirety to obtain a more complete understanding of the information provided and to aid in any decisions made or actions taken based on this information.

1.1.1 SITE DESCRIPTION AND CURRENT USE

The subject property consists of a 9.69± acre parcel located at 3401 Etiwanda Avenue - Bldg 1011 in Jurupa Valley, California. The property is developed with a 172,800 square foot (sf) single-story warehouse with associated parking and landscaping. The subject property building was constructed in 1987. The property is currently occupied by American West in units A and B, and by Hanes Industries in units C and D. On-site operations consist of furniture and geotextile distribution. No manufacturing activities are conducted on site.

1.1.2 ADJOINING PROPERTY DESCRIPTION AND USE

The adjoining property uses are detailed in the table below.

Direction	Description of Adjoining Property Use
North	One World Direct followed by Smith Cargo
East	Space Center Court industrial buildings
South	Industrial building with Surplus Asset Management and Roller Derby Skate Corp.
West	Manitou Court followed by Home Depot Distribution Center.

1.1.3 HISTORICAL USE OF SITE AND SURROUNDING AREA

According to available historical sources, the subject property was formerly undeveloped as early as 1897; developed with a storage yard between 1948 and 1985; and was developed with current structure in 1987. Tenants on the subject property have included Mira Loma Quartermaster Depot (1942-1985); Berkline (1990); Golden State (1990); Sebring Forest Industries (1990); Country Wide (1990); Haddy Warehousing (2008-2011); California Packaging (2008); American West (2014-Present) and Hanes Company (2017- Present).

To the north, the land appeared vacant or used for agriculture until at least 1938. After 1948, the land was developed with a warehouse-type building. After 1994, Inland Ave was observed farther to the north. After 2002, the land was developed with present day industrial buildings and roads.

To the east, the land appearedvacant or used for agriculture until at least 1938. After 1948, the land appeared developed with curved railroad tracks. Stacks of material were noted on and off until 1985. After 1994, the tracks appear to not be in use. After 2002, the land was developed with present day industrial buildings and roads.

To the south, the land appeared vacant or used for agriculture until at least 1938. After 1948, the land was developed with present day industrial buildings, railroad spurs, and roads. In 1977, the buildings apear to have new roofing. Railroad tracks appear to be no longer in use. No additional changes were noted until present day.

To the west, the land appeared vacant or used for agriculture until at least 1938. After 1948, the land was developed with a warehouse-type building. In 1994, a large number of storage boxes were closely parked around the building. Between 2002 and 2010, the land appears vacant with a few trailer boxes followed by present day industrial building. After 2012, the building farther to the west appeared to have been expanded into the west adjoining land.

1.1.4 GOVERNMENTAL RECORDS REVIEW

PSI subcontracted with ERIS to provide a review of governmental database records for spill sites, tanks, hazardous waste handlers, and other facilities of potential concern within proximity to the subject property.

The subject property was listed in the ERIS database report.

One or more off-site facilities were identified in the database search within the appropriate AMSD and were evaluated by PSI during this assessment.

These facilities are discussed in Section 7.1 of this report and the regulatory radius map report is appended.

1.1.5 SIGNIFICANT DATA GAPS

The ASTM E1527 Standard Practice defines a significant data gap as a lack of or inability to obtain information required by the practice that would limit our ability to draw conclusions with regard to RECs in connection with the subject property. Based on our experience, the information that we gathered and evaluated did not present significant data gaps that affected our ability to identify RECs in connection with the subject property.

1.2 CONCLUSIONS

PSI performed a Phase I ESA of the subject property in accordance with the scope and limitations of ASTM Practice E 1527-13. Any exceptions to or deletions from this practice are described in Section 2.3 of this report. The following conclusions have been made with regard to evidence of RECs, HRECs, CRECs, VECs, and de minimis conditions on the subject property, as defined in ASTM E 1527-13.

1.2.1 RECOGNIZED ENVIRONMENTAL CONDITIONS

This assessment has revealed no evidence of RECs in connection with the subject property.

1.2.2 CONTROLLED RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527 Standard Practice defines a CREC as a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of a regulatory agency with chemicals of concern allowed to remain in place subject to the implementation of institutional and/or engineering controls to prevent future exposure. In some cases, certain uses or activities (e.g., residential use) may be limited or prohibited on the property. By definition, the ASTM E1527 Standard Practice considers a CREC to also represent an REC, since residual chemicals may remain present in the subsurface

This assessment has revealed no evidence of CRECs in connection with the subject property.

1.2.3 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E1527 Standard Practice defines an HREC as a past release of hazardous substances or petroleum products that has impacted the property, but the release has been addressed to the satisfaction of a regulatory agency or meets unrestricted use criteria established by the regulatory agency without the need for institutional or engineering controls.

This assessment has revealed no evidence of HRECs in connection with the subject property.

1.2.4 VAPOR ENCROACHMENT CONDITIONS

The ASTM E1527 Standard Practice requires that the environmental professional evaluate the potential for VECs on the subject property. A VEC is defined in ASTM E2600 as the presence or likely presence of volatile chemicals in the subsurface that are caused by the release of vapors from contaminated soil or groundwater either on or near the subject property.

This assessment has revealed no VECs in connection with the subject property.

1.2.5 DE MINIMIS CONDITIONS

A de minimis condition is a condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

PSI did not identify evidence of de minimis conditions on the subject property.

1.3 NON-SCOPE CONSIDERATIONS - OTHER BUSINESS ENVIRONMENTAL RISKS

PSI conducted additional assessment to address potential environmental concerns, also known as business environmental risks or BERs, which are beyond the scope of the ASTM E1527 Standard Practice. The results of these additional investigations are described below.

1.3.1 VISUAL ASBESTOS SURVEY

Asbestos-Containing Materials (ACM) have been used extensively in buildings since the turn of the 20th century, and many buildings contain some quantity of ACM. As the adverse health effects of exposure to asbestos became known, the use and installation of many types of ACM in buildings was progressively phased out. By 1979 the EPA had banned the use of spray and troweled-on asbestos materials in building construction. In 1989, the EPA attempted to ban asbestos in all building products, however, this ban was subsequently overturned. Although this EPA ban in all products was overturned, the use of asbestos in building products saw a dramatically declined after 1989.

In addition to EPA policies related to building products, the U.S. Occupational Safety and Health Administration (OSHA) published regulations regarding the protection of workers from exposure to airborne asbestos. OSHA established the date of 1981, where surfacing materials and thermal insulation systems (TSI) must be "*Presumed"* ACM (PACM). In addition, all vinyl flooring systems installed prior to 1981 are "*designated"* as ACM by regulation. Because of the costs associated with the control, removal and disposal of certain types of ACM, it can have a significant impact on the value of a property.

The scope of work included observation of accessible areas of the building to identify suspect ACM could represent a possible "*Business Environmental Risk"* (BER) for the property. The observations were performed for due diligence purposes and were not intended to satisfy regulatory requirements for site demolition or

renovation. Our scope of work also did not include sampling or destructive/invasive methods to observe materials that were not readily observable, such as beneath carpet, inside wall cavities, beneath/behind equipment, etc.

During the site reconnaissance, PSI observed the following suspect building materials:

- Floor tile and mastic
- Baseboard and mastic
- Ceiling tiles
- Drywall systems

The observed suspect ACM materials appeared to be in [good][1] condition and no removal or corrective actions are recommended. As the building was constructed between 1981 and 1989, no building materials are required to be presumed or designated as ACM. However, limited applications of ACM may exist, and PSI recommends that an asbestos Operations and Maintenance (O&M) Plan be developed for the site until such time that all suspect ACM can be properly characterized. If renovations or demolition are planned, PSI further recommends that all impacted suspect building materials be properly sampled and analyzed for possible asbestos content.

Footnote [1] *– Assumed that the materials in these optional paragraphs were in good condition with no recommended removal or corrective actions. If we have poor conditions, we will need to modify the paragraph to discuss the condition and determine if we are going to recommend removal, corrective actions or further investigation.*

1.3.2 VISUAL LEAD-BASED PAINT SURVEY

Use of lead-based paint was widespread until the 1950s, when it became evident that exposure to lead represented a health hazard, especially to children. Decreased usage of lead-based paint continued until 1978, when the manufacture and use of lead-based paints was banned for residential applications. Leaded paint and coating products continue to be produced and utilized for certain exempt applications, and there are cases where exempted paints have been used in residences constructed after the 1978 ban. Because leaded paint abatement procedures are expensive, the presence of lead-based paint may be a BER in association with a property.

PSI conducted a reconnaissance of the interior and exterior on the subject property building(s) to evaluate the condition of painted surfaces. It should be noted that lead-based paint cannot be visually detected, and sampling and laboratory analysis would typically be required to determine the lead content of any painted surfaces. Therefore, PSI evaluated the condition of painted surfaces and noted any surfaces that were in poor condition, which might lead to unacceptable airborne concentrations of lead inside the building.

PSI noted that the painted surfaces on the interior and exterior of the building were generally in good condition, with only minor evidence of flaking or peeling. Based on the construction date of the building (1987), PSI believes it is unlikely that lead-based paint is present.

1.3.3 RADON RECORDS REVIEW

Radon is a colorless, odor-less gas that results from the decay of naturally occurring radioactive minerals in the subsurface. Radon may enter buildings through foundation cracks, utility openings, etc. and may accumulate in the indoor air space. Radon is measured in pCi/L of air. The USEPA has developed a recommended action level for radon levels in residential buildings of 4 pCi/L, but has not developed any recommendations for commercial structures. Generally, radon levels within slab-on-grade industrial and commercial structures would be expected to be lower than that found in single-family homes in the same location.

PSI performed a review of EPA records available online at the EPA's website pertaining to the potential presence of radon at the subject property. EPA has developed a radon zone map, which classifies each county within Zones 1 through 3 based on indoor radon measurements; geology; aerial radioactivity; soil permeability; and foundation type.

- **Zone 1** counties have a predicted average indoor radon screening level greater than 4 pCi/L - Highest Potential
- **Zone 2** counties have a predicted average indoor radon screening level between 2 and 4 pCi/L - Moderate Potential
- **Zone 3** counties have a predicted average indoor radon screening level less than 2 pCi/L - Low Potential

It should be noted that our work did not include sampling for radon in the building(s). While the review of the EPA Radon Zone maps provides an estimate of the potential for radon in the area, radon levels may vary on a structure by structure basis due to underlying geology and building construction characteristics.

Based on the records reviewed, the the site is located in USEPA Zone 2 and is non-residential Therefore, radon is no considered to represent a significant concern.

1.3.4 LEAD IN DRINKING WATER RECORDS REVIEW

Lead in drinking water is regulated by the U.S. EPA under 40 Code of Federal Regulation (CFR) Part 141 Subpart I. The regulation applies to community systems and non-transient, non-community water systems. The EPA has established an action level of 15 ug/L or ppb for lead in drinking water.

Potable water at the subject property is provided by Jurupa Community Services District. According to Jurupa Community Services District, the public water supply meets Federal guidelines for consumption. A copy of the most recent published Consumer Confidence Report or Water Quality Report is appended.

1.3.5 HISTORICAL OIL AND GAS WELLS RECORDS REVIEW

PSI reviewed readily-available maps showing locations of historical oil and gas wells in the vicinity of the subject property. No gas and oil production was historically performed in the geographical area of the subject property.

1.4 RECOMMENDATIONS

Based on the information that PSI gathered and our experience, PSI recommends the following:

- PSI recommends no further assessment at this time.
- Development of an Operations & Maintenance Program that meets current EPA and OSHA regulations, under which the identified suspect ACM may be monitored and controlled.

2.0 PHASE I ESA SCOPE AND METHODOLOGY

2.1 PURPOSE OF SERVICES

PSI performed the Phase I ESA in conformance with ASTM E 1527-13, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (the Practice). The purpose of the Practice was to define good commercial practice for conducting a Phase I ESA and as such, the Practice is intended to permit the user to satisfy one of the requirements to qualify for the LLPs. The goal of the processes established by the Practice is to identify RECs in connection with the property.

Based on the information provided, PSI understands that your purpose for having the Phase I ESA performed is to satisfy one of the LLPs.

This Phase I ESA was also performed in accordance Citi's Third-Party Report Scope of Work dated June 2020.

2.2 PHASE I ESA METHODOLOGY

PSI performed a Phase I ESA of the subject property. The scope of our services and general methodology is presented below.

The information sources that PSI used, including published material, material obtained from commercial and other sources, is listed below and cited as it is presented in the report. The information or excerpts thereof is appended.

This assessment included four components:

- Records review;
- Reconnaissance;
- Interviews; and,
- Preparation of this report, including our evaluation.

In addition to the ASTM E1527-13 standard and in accordance with the client's scope of work, the following non-scope items were included within the Phase I ESA:

- Visual Asbestos Survey
- Visual Lead Based Paint Survey
- Radon Records Review
- Lead in Drinking Water Records Review
- Historical Oil and Gas Wells Records Review

2.3 LIMITATIONS, EXCEPTIONS, DEVIATIONS AND DATA GAP

PSI considers that limitations, exceptions, and deviations from the Practice manifest as a lack of or inability to obtain information required by the Practice. This represents the definition of the 'data gap' contained in the Practice. PSI listed the component objectives of the Practice on the appended Data Gap Worksheet and tracked the information obtained against the objectives. Therefore the limitations, exceptions and deviations are identified in the Worksheet.

In general, when required information was incomplete, not provided, otherwise not obtained, or indicated a need for additional information, PSI attempted to use information from other sources to meet the Practices' performance objectives. When the data gaps affected the Environmental Professional's ability to identify RECs, PSI considered the data gap(s) to be significant. PSI identified significant data gaps (if any) on the Data Gap Worksheet and reported them in Section 1.1.5.

2.4 SIGNIFICANT ASSUMPTIONS

PSI made the following assumptions in developing our Phase I ESA findings and conclusions:

- Regulatory Agency Information - PSI considers all information provided by our environmental database subcontractor regarding regulatory status of facilities to be complete, accurate, and current.
- Other Regulatory Information - PSI considers all information obtained from regulatory or enforcement agencies to be complete, accurate, and current.
- Title, Lien and AUL Information - PSI considers all information provided by real estate title record review firms regarding property use or ownership, encumbrances or other limitations, if provided, to be complete, accurate and current.
- Interviews - PSI considers all information provided through interviews to be complete, unbiased and provided in good faith.
- Groundwater - PSI interpreted and inferred the direction of the shallow groundwater movement based on the information we obtained and our experience. Actual groundwater flow may be locally influenced by many factors beyond the scope of this assessment. Subsurface investigation would be necessary to determine site-specific groundwater flow direction.

3.0 USER-PROVIDED INFORMATION

PSI considers the client to be the 'User' of our assessment, defined in ASTM Practice E 1527 as "the party seeking to use ASTM E 1527 to complete a Phase I ESA of the property. A User may include, without limitation, a potential purchaser of property, a potential tenant of property, an owner of property, a lender, or a property manager. The User has specific obligations for completing a successful application of this practice...."

3.1 USER QUESTIONNAIRE

The EPA All Appropriate Inquiry Rule (40 CFR Part 312) and ASTM E1527 Section 6 require the User to answer certain questions related to the property, in order to obtain certain LLPs from CERCLA liability. To facilitate this process, PSI provided the client with a User Questionnaire, which is provided in the Appendix if it has been returned. A summary of the required questions and client responses is provided below:

Question	Yes	No	Unknown	N/A	Client did not respond
Did a review of recorded land title records or other sources identify any environmental liens filed or recorded against the subject property under federal, tribal, state or local law?					✔
Did a review of land title records or other sources identify any activity use limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place on the subject property?					✔
Do you have specialized knowledge or experience related to the subject property or nearby properties?					✔
Does the purchase price being paid for the property reasonably reflect the fair market value of the property?					✔
If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?					✔

Question	Yes	No	Unknown	N/A	Client did not respond
Are you aware of commonly known or reasonable ascertainable information about the property that would help the environmental professional to identify conditions indicative of a releases or threatened releases?					✔
Do you know of the past uses of the property?					✔
Do you know of specific chemicals that are present or were once present at the property?					✔
Do you know of spills or other chemical releases that have taken place at the property?					✔
Do you know of any environmental cleanups that have taken place at the property?					✔
Based on your knowledge and experience related to the property are there any obvious indicators that point to the presence or likely presence of contamination at the subject property?					✔
Do you know of any pending, threatened, or past litigation or administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the property?					✔
Do you know of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?					✔

NOTES

PSI was not provided with information about legal proceedings or litigation involving the subject property. However, PSI was referred to the User Questionnaire contained in the previous Phase I ESA.

3.2 TITLE RECORDS

PSI was not provided with land title records by the client in order to obtain information about the current and past owners of the subject property and past uses and tenancies. However, given the availability of other historic resources, we do not consider this limitation to represent a significant data gap.

Based on a review of the local tax assessor's records, the subject property is currently owned by BRE Space Mira Loma. The property was transferred from Space Center Mira Loma, Inc.

3.3 SUGGESTED INFORMATION

The client provided PSI with the following suggested information described by the Practice.

- The reason for performing the Phase I ESA.
- The type of property and type of property transaction.
- The complete and correct address of the property.
- The scope of services desired for the Phase I ESA, including any evaluation for business environmental risk that is beyond the scope of ASTM E1527.
- Identification of all parties who will rely upon the report.
- Identification of the key site contact and contact information.

3.4 HELPFUL DOCUMENTS

The Practice requires that the environmental professional ask the property owner, the key site manager (if any is identified), and the User for certain helpful documents about the property and certain legal proceedings involving hazardous substances and the subject property. PSI mailed or e-mailed questions or performed interviews requesting this information. The responses documenting the persons we corresponded with, and relevant information obtained, are appended where practical.

Provided reports are appended.

Report Title:	Phase I Environmental Site Assessment
Prepared For:	Space Center, Inc.
Prepared By:	Partner Engineering and Science, Inc.
Report Date:	November 20, 2018

Summary:	Partner performed a Phase I Environmental Site Assessment on the building located at 3401 Etiwanda Avenue, Building 1011 in the City of Jurupa Valley, Riverside County, California (the “subject property”). The assessment revealed no evidence of recognized environmental conditions or environmental issues in connection with the subject property. Based on the conclusions of this assessment, Partner recommended no further investigation of the subject property.

4.0 PHYSICAL SETTING

PSI reviewed a USGS topographic (topo) map, information from the USDA and/or Natural Resources Conservation Service (NRCS) and/or other information regarding the physical setting of the subject property to assist with the interpretation of subsurface water movement near the subject property. Physical setting information is summarized in the table below.

Summary of Physical Setting Information

Physical Setting Attributes	Description	Source
Subject property elevation:	Approximately 820-feet AMSL	USGS Topo Map sheets "Corona North, CA", "Fontana, CA", "Guasti, CA", "Ontario, CA", "Prado Dam, CA", and "Riverside West, CA" 7.5 minute Quadrangle, 2015
Topographic gradient:	The subject property and surrounding area slopes to the south direction.	ERIS Physical Setting Report
Closest surface water:	Day Creek, located approximately 3,700 feet to the east.	ERIS Physical Setting Report
Other resource or physical characteristics mapped on the subject property?	No	ERIS Physical Setting Report
Is a flood plain mapped on the subject property?	No	ERIS Physical Setting Report
Predominant soil type(s) mapped on the subject property:	Delhi loamy fine sand. A Class A soil with low runoff potential when thoroughly wet. Water is transmitted freely through the soil.	USDA NRCS Custom Soil Resource Report (retrieved from website on April 6, 2021)

Physical Setting Attributes	Description	Source
Geology/Hydrogeology:	The soils on the surface are a result of deeply weathered crystalline bedrock and consolidated sediments in low relief areas. A basement complex of volcanic, meta-sediments, and igneous rocks, underlies the alluvium and soils in the Chino Basin. Intrusive granitic rocks compose most of the basement complex and were deposited in the Cretaceous period. The basement complex has been the major source of material for the water bearing soils in the Chino Basin.	ERIS Physical Setting Report
Estimated depth to first groundwater:	Approximately 258 feet bgs, as of 09/01/2020	California Department of Water Resources Groundwater level report for Station 340233N1175215W001
Anticipated regional groundwater flow direction:	Groundwater is expected to flow in the same general direction as the local topography	ERIS Physical Setting Report
Oil and Gas Resources:	None mapped on or adjacent to the subject property	ERIS Physical Setting Report
Mining Resources:	None mapped on or adjacent to the subject property	ERIS Physical Setting Report

5.0 SITE RECONNAISSANCE

The location and approximate boundaries of the subject property are illustrated on the appended figures. The legal description of the subject property, if provided to PSI, is appended.

The client arranged for PSI to access the subject property. Our assessor was unescorted during the site reconnaissance.

The ground reconnaissance consisted of observing the periphery of the subject property and viewing the subject property from accessible adjoining public access areas. Visual reconnaissance of adjoining properties was limited to areas and facilities that were readily observable from the subject property or from public access areas. PSI also systematically toured the interior portions of the subject property parcels to provide an overlapping field of view.

The peripheries of surface features and/or structures, where present on the subject property, were observed along with accessible interior common areas. PSI photo-documented selected features. The photo log is included in the Appendix.

5.1 SUBJECT PROPERTY DESCRIPTION AND CURRENT USES

General Site Information	
Subject Property Address	3401 Etiwanda Avenue - Bldg 1011, Jurupa Valley, California 91752
Parcel Size (acres)	9.69±
Site Contact/Escort	Ms. Nicole Bray / Mr. Roger Duran
Date of Reconnaissance	April 1, 2021
Building Information	
Building Description	Pre-cast or tilt-up concrete wall panels with wood beam and open-web wood joist girders.
Size (square feet)	172,800
Number of Stories	Single
Approx. Construction Date	1987
Utilities	
Water	Jurupa Community Services District
Wastewater/Sewer	Jurupa Community Services District
Electricity	Southern California Edison
Natural Gas	Not provided

Heating Source	Not provided

5.2 SUBJECT PROPERTY OBSERVATIONS

A summary of the subject property uses and conditions is tabulated below. Detailed information is discussed following the summary for any "yes" answers, along with an opinion about the significance of the listing.

Identified? (check if Yes)	Item Description
Equipment/Activities/Uses	
✔	Emergency Generators
	Elevators
✔	Hydraulic Lifts
	Dry Cleaners/Laundromats
	Photo Processing
	Medical/Dental Offices - Biomedical Wastes
	Automotive/Equipment Repair
	Grease Traps and Oil/Water Separators
	Wastewater Treatment Systems
	Septic or Sewage Tanks
✔	Air Compressors
✔	Transformers or Other Mech./Elec. Equipment That Could Contain PCBs
	Pipeline Markers
	Oil and Gas Wells
	Stormwater Ponds
	Quarries, Pits, Lakes, or Lagoons
✔	Use, Storage, or Disposal of Hazardous Substances
✔	Use, Storage, or Disposal of Petroleum Products
	ASTs/USTs
	Drums or Other Bulk Chemical Containers

Identified? (check if Yes)	Item Description
	Suspect Containers/Unidentified Contents
✔	Drains and Sumps
	Drinking Water, Irrigation or Monitoring Wells
	Agrochemical Use/Application
✔	Railroad Spur/Tracks
Potential Evidence of Releases	
✔	Interior/Pavement Stains or Corrosion
	Stained Soil/Stressed Vegetation
	Chemical Odors
	Surface Water Sheen or Discoloration
	Exterior Pipe Discharges/Unknown Pipes/Effluent Discharges
	Pools of Liquid or Standing Water
✔	Solid Waste Dumping/Landfilling/Suspect Fill Material
	Construction Debris/Material Stockpiles
	Other Uses or Conditions of Concern

EMERGENCY GENERATORS

PSI observed multiple portable generators in the warehouse area on the subject property. The emergency generators appeared to be fueled by gasoline. Typically, tanks associated with emergency generators are equipped with integrated secondary containment systems. PSI did not observe evidence of leaking or staining around the base of the generators at the time of the site reconnaissance. Based on this information, the presence of the emergency generators is not considered to be evidence of a REC in connection with the subject property.

HYDRAULIC LIFTS

Leveling docks were observed at the subject property. The hydraulic reservoirs appeared in good condition with no apparent leakage or corrosion. As such, the hydraulic components are not considered to be evidence of a REC in connection with the subject property.

AIR COMPRESSORS

PSI observed air compressors located in the warehouse area of both tenants. The air compressors included a small oil reservoir. The compressors were observed with slight staining from usage and not related to any spills. The compressors were observed in overall good condition therefore, the oil staining from the air compressors is not considered evidence of a REC in connection with the subject property.

TRANSFORMERS OR OTHER ELECTRICAL OR MECHANICAL EQUIPMENT THAT COULD CONTAIN PCBS

One (1) pad-mounted electrical transformers was observed on the subject property. PSI did not observe non-PCB labeling on the transformer at the time of the site reconnaissance. PSI believes the electrical equipment is the property and responsibility of Jurupa Community Services District, the local electrical utility company, who would be responsible for cleanup related to the equipment that could not be attributed to tenant negligence. The identified electrical equipment appeared to be in good condition, with no apparent evidence of staining, leakage, or corrosion noted. Based on the age of the building, PCBs are not likely to be present. There is no evidence that PCBs represent an REC.

PSI observed a trash compactor outside on the north of the subject property building. PSI did not observe evidence of leaking or staining in connection with the hydraulic features of the compactor at the time of the site reconnaissance. Based on these observations, the presence of the trash compactor is not considered to be evidence of a REC in connection with the subject property.

USE, STORAGE, OR DISPOSAL OF HAZARDOUS SUBSTANCES

Small quantities of cleaning products were observed on the subject property. These cleaning products appeared to be stored properly, in containers of five gallons or less in size, and no leaks or stains were observed around them. Based on this information, these cleaning products are not considered evidence of a REC in connection with the subject property.

Flame resistant cabinets were observed in a maintenance storage area located in the subject property building. The cabinets appeared to contain containers of acrylic and latex paints as well as paint spray cans. No leaking or staining was observed in the vicinity of the paint storage or flame resistant cabinets. Additionally, no drain inlets were observed in the maintenance storage area. Based on this information, the presence of the flammables cabinet is not considered to be evidence of a REC in connection with the subject property.

USE, STORAGE, OR DISPOSAL OF PETROLEUM PRODUCTS

PSI observed multiple propane tanks at the subject property. These tanks are used at the subject property for the forklifts and/or describe other uses as appropriate. These tanks appeared to be in good condition and no leaks or spills were observed. These tanks were stored in a caged storage unit outside of the building on the subject property. Based on this information, these propane tanks are not considered evidence of a REC in connection with the subject property.

PSI observed gear oil and hydraulic oil stored in various size containers. These storage containers appeared to be in good condition with no apparent leaking, staining, or corrosion. Based on the observations made at the time of site reconnaissance, the storage and use of these petroleum products does not appear to be evidence of a REC in connection with the subject property.

DRAINS OR SUMPS

Floor drains were observed in the subject property building, inside restrooms. The drains appeared to be absent of staining, odor, and sheen at the time of the site reconnaissance. The drains are believed to be connected to the Jurupa Community Services District sanitary sewer system. Based on these observations, the drains do not appear to be evidence of a REC in connection with the subject property.

PSI observed storm drains in the parking and drive areas of the subject property. PSI did not observe evidence of unusual staining or improper disposal in connection with the observed storm drains, and the storm drains appeared to be in a generally good condition. The drains appear to flow into the Jurupa Community Services District system. Based on this information, the observed storm drains are not considered to be evidence of a REC in connection with the subject property.

RAILROAD SPUR/TRACKS

PSI observed an out of service railroad spur on the south side of the warehouse. No evidence of oil and grease staining of the railroad ballast along the spur. Based on this information, the presence of this railroad right-of-way is not considered to be evidence of a REC in connection with the subject property.

INTERIOR/PAVEMENT STAINS OR CORROSION

PSI observed staining of the carpeting and some tile areas of the subject property. This staining appeared to be typical of occasional spilled drinks or other customer-related staining, and not indicative of a disposal condition. This staining is not considered to be evidence of a REC in connection with the subject property.

PSI identified areas of minor staining on the paved parking area located on the subject property. The stains appear to be the result of leakage of automobile fluids and not the result of a large scale spill. PSI considers the presence of the staining a de minimis condition and, by definition, not a REC in connection with the subject property.

Apparent oil staining was identified in the areas around the sorting machinery inside the subject property warehouse area. PSI believes the observed staining is an accumulation over time of minor leakage of lubricants used in association with operation of the equipment and not evidence of a single spill incident. PSI considers the presence of the staining a de minimis condition and, by definition, not a REC in connection with the subject property.

SOLID WASTE DUMPING, LANDFILLING, OR SUSPECT FILL MATERIAL

No landfilling or suspect fill material was observed at the subject property. Solid waste trash and recycling dumpsters were observed on the subject property. The dumpsters are cleaned or emptied on a weekly basis. No adverse conditions, such as staining or improper dumping, were observed at the time of the site reconnaissance. As such, the observed dumpsters are not considered to be evidence of a REC in connection with the subject property.

5.3 OFF-SITE OBSERVATIONS

A summary of our interpretation of the current and past uses and conditions of adjoining and surrounding property based on historical records and observations is provided below.

Identified? (check if Yes)	Item Description
Equipment/Activities/Uses	
	Emergency Generators
	Elevators
	Hydraulic Lifts
	Dry Cleaners/Laundromats
	Photo Processing
	Medical/Dental Offices - Biomedical Wastes
	Automotive/Equipment Repair
	Grease Traps and Oil/Water Separators
	Wastewater Treatment Systems
	Septic or Sewage Tanks
	Air Compressors
✔	Transformers or Other Mech/Elec. Equipment That Could Contain PCBs
	Pipeline Markers

Identified? (check if Yes)	Item Description
	Oil and Gas Wells
	Stormwater Ponds
	Quarries, Pits, Lakes, or Lagoons
	Use, Storage, or Disposal of Hazardous Substances
	Use, Storage, or Disposal of Petroleum Products
	ASTs/USTs
	Drums or Other Bulk Chemical Containers
	Suspect Containers/Unidentified Contents
✔	Drains or Sumps
	Drinking Water, Irrigation or Monitoring Wells
	Agrochemical Use/Application
✔	Railroad Spur/Tracks
Potential Evidence of Releases	
✔	Interior/Pavement Stains or Corrosion
	Stained Soil/Stressed Vegetation
	Chemical Odors
	Surface Water Sheen or Discoloration
	Exterior Pipe Discharges/Unknown Pipes/Effluent Discharges
	Pools of Liquid or Standing Water
✔	Solid Waste Dumping/Landfilling/Suspect Fill Material
	Construction Debris/Material Stockpiles
	Other Uses or Conditions of Concern

TRANSFORMERS OR OTHER MECH./ELEC. EQUIPMENT THAT COULD CONTAIN PCBS

Pole-mounted and/or pad-mounted transformers were observed in the surrounding vicinity. No evidence of leakage, spillage or corrosion was observed in connection with the transformers. The transformers are owned and operated by Southern California Edison. Non-PCB labeling was apparent on each of the observed transformers. Based on the good condition of the transformers, the transformers are not considered to be evidence of a REC in connection with the subject property.

DRAINS OR SUMPS

PSI observed storm drains in the parking and drive areas adjoining the subject property. PSI did not observe evidence of unusual staining or improper disposal in connection with the observed storm drains, and the storm drains appeared to be in a generally good condition. Based on this information, the observed storm drains are not considered to be evidence of a REC in connection with the subject property.

RAILROAD SPUR/TRACKS

It should be noted that adjoining property appears to have been a railroad right-of-way. While no information indicating the misuse or misapplication of herbicides, or the misuse or improper placement of creosote-covered railroad ties was obtained during this assessment, in certain instances, the chemicals historically applied to the adjoining property and railroad ties historically placed on the adjoining property could be persistent and not biodegrade. As with any land that has been developed as a railroad right-of-way, there exists the possibility that herbicides have been applied or creosote-covered railroad ties placed which may still be present on adjoining property and which may have impacted the subject property. However, PSI does not consider the presence of this railroad right-of-way to be evidence of a REC in connection with the subject property.

INTERIOR/PAVEMENT STAINS OR CORROSION

PSI identified areas of minor staining on the paved parking areas and roads adjoining the subject property. The stains appear to be the result of leakage of automobile fluids and not the result of a large scale spill. PSI does not consider the presence of the staining a REC in connection with the subject property.

SOLID WASTE DUMPING/LANDFILLING/SUSPECT FILL MATERIAL

No landfilling or suspect fill material was observed at the subject property. Solid waste trash and recycling dumpsters were observed on the subject property. The dumpsters are cleaned or emptied on a weekly basis. No adverse conditions, such as staining or improper dumping, were observed at the time of the site reconnaissance. As such, the observed dumpsters are not considered to be evidence of a REC in connection with the subject property.

6.0 HISTORICAL USES

PSI utilized readily ascertainable historical data resources in order to research the history of the site and surrounding area. The intent of this review was to identify historical tenancies or uses of the subject property and surrounding area, which might be considered evidence of a REC. Generally, PSI reviewed the following readily ascertainable historic data resources, where they were available:

- Readily available historical topographic maps were reviewed to evaluate land development in the area over time. It should be noted that the scale of topographic maps in some cases does not allow for mapping of individual structures and developed areas may be shown by shading only.
- Selected historical aerial photographs were reviewed at 5-10 year intervals to obtain information concerning the development and history of the subject property and surroundings.
- PSI reviewed readily ascertainable historical city directories at 5-10 year intervals in order to obtain information on tenancies on the subject property and adjoining properties.
- PSI requested available historical fire insurance maps from ERIS. The Sanborn Map Company and other regional providers historically mapped urban areas for use by insurance underwriters. In some cases these maps provide useful information in evaluating previous tenancies and uses of the subject property and surrounding area.

Copies of select historical documents are provided in the report appendix; however, it should be noted that some of the resources used by PSI may be copyrighted and PSI has summarized these resources herein, but we have not included copies of these resources in the appendix.

6.1 SUMMARY OF RESOURCES

PSI reviewed the following resources in order to evaluate the historic uses of the subject property and surrounding area:

Source Type	Years Reviewed	Source
USGS Topo Maps	1897, 1900, 1903, 1953, 1954, 1966, 1973, 1981, and 2015	USGS
Aerial Photographs	1938, 1948, 1952, 1959, 1966, 1971, 19877, 1985, 1994, 2002, 2005, 2010, 2012, 2014, 2016, 2018, and 2020	ERIS and Google Earth
City Directories	1921, 1925, 1931, 1934, 1941, 1945, 1951, 1971, 1986, 1991, 1996, 2001, and 2006	ERIS
Fire Insurance Maps	Unmapped Property	ERIS

6.2 CURRENT AND PRIOR USE INTERVIEWS

PSI conducted interviews with persons who are knowledgeable of the current use and history of the site. The following individuals were interviewed:

Name	Title/Role	Date Interviewed	Affiliation
Mr. Roger Duran	Manager at American West	April 1, 2021	Mr. Duran provided information related tot he every day activities at the subject property.

No evidence of RECs were identified as a result of the interviews conducted during this assessment. Complete records of communication detailing information obtained and reviewed, have been appended to this report.

6.3 PRIOR INVESTIGATIONS

The client provided PSI with the reports or documents discussed in Section 3.4 of this report.

6.4 CITY DIRECTORIES

The following table lists the chronological city directories for the subject property and immediately adjoining properties.

Property	Address: Listing Description by Year
Subject Property	No directory listings were located
North	No directory listings were located
East	No directory listings were located
South	No directory listings were located
West	No directory listings were located

The city directory information reviewed for the subject and adjoining properties revealed no evidence of RECs.

6.5 SUMMARY HISTORY OF SITE AND SURROUNDING AREA

A chronological summary of the history/use of the subject property and immediately adjacent properties is provided in the following table.

Date	Resource	Interpreted Use/Observations
SUBJECT PROPERTY		
1897 to 1938	Topo maps and aerial photographs	The property appears as undeveloped land.
1942 to 1985	Topo maps and aerial photographs	The property was part of a military reservation. Stacks of material were observed between 1952 and 1973
1994 to present day	Topo maps and aerial photographs	The subject property was observed developed with present day building.
NORTH ADJOINING PROPERTY		
1897 to 1938	Topo maps and aerial photographs	The land appears vacant or used for agriculture.
1948 to 1994	Topo maps and aerial photographs	The land was developed with a warehouse-type building. After 1994, Inland Ave was observed farther to the north.
2002 to present day	Topo maps and aerial photographs	The land was developed with present day industrial buildings and roads.
EAST ADJOINING PROPERTY		
1897 to 1938	Topo maps and aerial photographs	The land appears vacant or used for agriculture.
1948 to 1994	Topo maps and aerial photographs	The land appeared developed with curved railroad tracks. Stacks of material were noted on and off until 1985. After 1994, the tracks appear to not be in use.
2002 to present day	Topo maps and aerial photographs	The land was developed with present day industrial buildings and roads.
SOUTH ADJOINING PROPERTY		
1897 to 1938	Topo maps and aerial photographs	The land appears vacant or used for agriculture.

Date	Resource	Interpreted Use/Observations
1948 to present day	Topo maps and aerial photographs	The land was developed with present day industrial buildings, railroad spurs, and roads. In 1977, the buildings apear to have new roofing. Railroad tracks appear to be no longer in use.
WEST ADJOINING PROPERTY		
1897 to 1938	Topo maps and aerial photographs	The land appears vacant or used for agriculture.
1948 to 1994	Topo maps and aerial photographs	The land was developed with a warehouse-type building. In 1994, a large number of storage boxes were closely parked around the building.
2002 to 2010	Topo maps and aerial photographs	The land appears vacant with a few trailer boxes followed by present day industrial building.
2012 to present day	Topo maps and aerial photographs	The building farther to the west appeared to have been expanded into the west adjoining land.

According to available historical sources, the subject property was formerly undeveloped as early as 1897; developed with a storage yard between 1948 and 1985; and was developed with current structure in 1987. Tenants on the subject property have included Mira Loma Quartermaster Depot (1942-1985); Berkline (1990); Golden State (1990); Sebring Forest Industries (1990); Country Wide (1990); Haddy Warehousing (2008-2011); California Packaging (2008); American West (2014-Present) and Hanes Company (2017- Present).

To the north, the land appears vacant or used for agriculture until at least 1938. After 1948, the land was developed with a warehouse-type building. After 1994, Inland Ave was observed farther to the north. After 2002, the land was developed with present day industrial buildings and roads.

To the east, the land appears vacant or used for agriculture until at least 1938. After 1948, the land appeared developed with curved railroad tracks. Stacks of material were noted on and off until 1985. After 1994, the tracks appear to not be in use. After 2002, the land was developed with present day industrial buildings and roads.

To the south, the land appears vacant or used for agriculture until at least 1938. After 1948, the land was developed with present day industrial buildings, railroad spurs, and roads. In 1977, the buildings apear to have new roofing. Railroad tracks appear to be no longer in use. No additional changes were noted until present day.

To the west, the land appears vacant or used for agriculture until at least 1938. After 1948, the land was developed with a warehouse-type building. In 1994, a large number of storage boxes were closely parked around the building. Between 2002 and 2010, the land appears vacant with a few trailer boxes followed by present day industrial building. After 2012, the building farther to the west appeared to have been expanded into the west adjoining land.

7.0 ENVIRONMENTAL REGULATORY RECORDS REVIEW

7.1 DATABASE FINDINGS

PSI retained ERIS to provide environmental database information attributed to the subject property and its surroundings. ERIS obtains environmental databases published by local, state, tribal, and federal agencies and maps the information for electronic searches. ERIS's service includes reporting Standard Environmental Records Sources and, in most cases, some Additional Environmental Records Sources.

The search was performed to AMSDs listed in ASTM E 1527-13. The search radius required by ASTM varies by database.

Unmappable (orphan) sites (if any were listed) having insufficient address information to be mapped were evaluated for potential location within the AMSD. Those that could be determined to be within the AMSD are discussed, as appropriate.

The distribution of listed sites with respect to the subject property is tabulated and mapped in ERIS's Database Report, which is appended. The reader is referred to the table, which can be found near the front of ERIS's report. The full names of the abbreviations and acronyms used below and in ERIS's report can be found in the appendix of the report.

7.1.1 SUBJECT PROPERTY

The subject property was listed on one or more regulatory databases, as summarized in the following table.

Facility Name & Address	Database(s)	Comments
CPS Express Inc. 3401 Etiwanda Avenue Building 1011	DELISTED COUNTY	The CPS Express Inc listing was removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC) in 07/08/2014. After further research, PSI determined that CPS Express is located at 3401 Etiwanda Ave Suite 711A and not at the subject property buildings. Based on regulatory status and incorrect address posted in the environmental report, this listing is not considered a REC in connection with the subject property.

Facility Name & Address	Database(s)	Comments
Hanes Industries 3401 Etiwanda Ave Bldg 1011 Units C&D	Riverside HZH CERS HAZ	Notice of violations related to paperwork compliance in 07/05/2017, 9/23/2016, and 06/10/2020. All cases were brought to compliance. Based on this information, this listing is not considered a REC in connection with the subject property.

7.1.2 ADJOINING PROPERTIES

Adjoining facilities as defined in ASTM Standard E 1527-13 § 3.2.4 were identified through the Federal and state environmental records review as discussed below.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Proko Industries Inc. 3401 Etiwanda Ave Building 931D	100 feet to the south.	3 feet lower	RCRA NON GEN FINDS/FRS HAZNET	This facility is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the RCRA NonGen, FINDS, and HAZNET databases. According to the database report, this facility is not listed as having violations and was not reported on any of the regulatory databases reviewed which report unauthorized releases and contamination incidents. As such, this listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Nelson-Ball Paper Products 3401 Etiwanda Ave 931A	100 feet to the south.	3 feet lower	HAZNET	The property is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET database. According to the database report, Nelson Ball Paper Products generated unspecified organic liquid mixture, other organic solids, waste oil & mixed oil and unspecified aqueous solution in 2004. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. The presence of the property on the HAZNET database is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Ecotech Consumer Products / Eddie Zhou 3401 Etiwanda Ave, 921A	100 feet to the south.	3 feet lower	FINDS/FRS RCRA TSD RCRA Non Gen	This facility is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the FINDS database. According to the database report, this facility is not listed as having violations and was not reported on any of the regulatory databases reviewed which report unauthorized releases and contamination incidents. As such, this listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Chemstar / 1X Border Trucking 3401 Etiwanda Ave Building 911D	100 feet to the south.	3 feet lower	HAZNET HIST MANIFEST	The property is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET database. According to the database report, Chemstar generated unspecified organic liquid mixture and aqueous solution with total organic residues less than 10 percent in 2004 and 2005. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
K-Swiss Sports Shoes Inc. 3177 Space Ctr.	269 feet to the north	1 ft higher	CERS HAZ Riverside HZH	The property is located adjacent to the north and situated hydrologically up-gradient. The site is listed in the CERS HAZ and Riverside HZH databases. This is a list of facilities disclosed to Riverside County Department of Environmental Health (DEH). This list is made available by Riverside County DEH which has been designated as the CUPA for the County. A business is required to establish and submit a Business Plan if the facility handles hazardous material equal to or greater than 55 gallons, 500 pounds or 200 cubic feet at any time during the year. This listing is not considered to represent a REC in connection with the subject property. Notice of violations related to this facility were located. However, the violations were regarding incomplete paperwork and not due to any environmental concern. This listing is not considered to represent a REC in connection with the subject property.

7.1.3 SURROUNDING PROPERTIES

Surrounding facilities were identified through the Federal and state environmental records review as discussed below.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Kerozakana Inc. / California Custom Design / Cargo Cats /Karis Cham 3401 Etiwanda Ave Building 811A	530 ft to the south	3 feet lower	Emissions HAZNET	The property, identified as Kerozakana Inc. at 3401 Etiwanda Ave Building 811A, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the FINDS database. FINDS is typically pointers to other databases, and is used as a tracking tool by the US EPA and State agencies. It is a compilation of the following lists: California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) and Resource Conservation and Recovery Act (RCRA). The property is listed as a FINDS site in association with the RCRA listing. No further information was provided under this listing. This listing is not considered to represent a REC in connection with the subject property. The property, identified as California Custom Design at 3401 Etiwanda Ave Building 811A, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET, RCRA SQG, FINDS, ECHO databases. FINDS and

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
				ECHO databases. FINDS and ECHO are typically pointers to other databases, and are used as a tracking tool by the US EPA and State agencies. It is a compilation of the following lists: California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) and Resource Conservation and Recovery Act (RCRA). The property is listed as a FINDS and ECHO site in association with the RCRA listing. No further information was provided under this listing. According to HAZNET listing, California Custom Design generated unspecified solvent mixture, waste oil & mixed oil and other organic solids in 1995, 1996 and 1997. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. The presence of the property on the HAZNET database is not, in itself, considered to represent an environmental concern. According to RCRA SQG listing, this facility is not listed as having violations and was not reported on any of the

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
				regulatory databases reviewed which report unauthorized releases and contamination incidents. As such, this listing is not considered to represent a significant environmental concern. The property, is also listed in the EMI database. According to the database report, Cal Custom Design was issued a permit to emit total organic hydrocarbon gas, reactive organic gas, in 1987 and 1990. No additional information was provided in the database report. This listing is not considered to represent a REC in connection with the subject property. The property, identified as Karis Cham at 3401 Etiwanda Ave Building 811A, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET and EMI databases. According to EMI listing, Karis Cham was issued a permit to emit total organic hydrocarbon gas, reactive organic gas, carbon monoxide, NOX into the air in 1993, 1995 and 1996. No additional information was provided in the database report. According to the

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
				HAZNET listing, Karis Cham generated unspecified organic liquid mixture in 2015. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property. The property, identified as Cargo Cats at 3401 Etiwanda Ave Building 811A, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET database. According to the database report, Cargo Cats generated liquids with pH<=2, other organic solids and other inorganic solid waste in 2004 and 2012. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Pacific Fabric Reels / / O'Neil Tube & Reel 3401 Etiwanda Ave Building 811C	530 ft to the south	3 feet lower	Riverside HZH RIverside HWG HAZNET CERS HAZ RCRA Non Gen FINDS/FRS	The property, identified as Pacific Fabric Reels at 3401 Etiwanda Ave Building 811C, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the HAZNET database. According to the database report, Pacific Fabric Reel generated other organic solids in 2006. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property. The property, identified as O'Neil Tube & Reel at 3401 Etiwanda Ave Building 811C, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the FINDS and HAZNET databases. FINDS is typically pointers to other databases, and is used as a tracking tool by the US EPA and State agencies. It is a compilation of the following lists: California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART)

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
				and Resource Conservation and Recovery Act (RCRA). The property is listed as a FINDS site in association with the RCRA listing. No further information was provided under this listing. According to HAZNET listing, O'Neil Tube & Reel generated other organic solids in 2013, 2015 and 2016. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Space Center Mira Loma 3401 Etiwanda Ave Building 811D	530 ft to the south	3 feet lower	CHMIRS HAZNET	The property, identified as 3401 Etiwanda Ave Building 811D, is located adjacent to the south of the subject property, and situated hydrologically cross-gradient. This site is listed in the CHMIRS database. According to the database report, this site experienced a release of 250-gallons of methylene Diphenyl Disocarnate due to a broken tote in 2004. The Riverside County Environmental Health is reportedly administering agency. Cleanup was reportedly conducted by the responsible party, whom was not identified in the regulatory database. No other details were provided in the CHMIRS listing. This listing is not considered to represent a REC in connection with the subject property.

Facility Name & Address	Distance (feet) & Direction	Elevation Difference (feet)	Database(s)	Comments
Distribution Logistics Management Inc / C Construction Inc DBA BMC West Building Materials 3401 Etiwanda Ave Building 831	530 ft to the south	3 feet lower	HAZNET	The property, identified as Distribution Logistics Management Inc. at 3401 Etiwanda Ave Building 831, is located adjacent to the south of the subject property, and situated hydrologically crossgradient. This site is listed in the HAZNET database. According to the database report, DistributionLogistics Management Inc. generated aqueous solution with total organic residues less than 10 percent in 2001. The HAZNET does not track violators and the presence of a facility on the HAZNET database not necessarily indicate that an environmental concern exists at that facility. This listing is not considered to represent a REC in connection with the subject property.

7.2 REGULATORY AGENCY INQUIRIES

PSI requested records or information about the subject property and/or surrounding area from the governmental agencies listed in the following sections. Information was requested by telephone, in person, via e-mail or through a written FOIA or equivalent request, as appropriate.

7.2.1 HEALTH DEPARTMENT/ENVIRONMENTAL DIVISION

PSI contacted the City of Jurupa Valley Records Department for information related to any spills or hazardous materials incidents on the subject property. Ms. Debra McNay, Deputy City Clerk, indicated that the records department did not have any records related to the subject property.

PSI submitted a request for information (RFI) to the Riverside County. A copy of the request is appended. However, a response has not been received as of the date of this report. This is a limitation and evaluated on the appended Data Gap Worksheet. When a response is received, it will be reviewed and if changes to the findings or conclusions of this report are warranted, an addendum will be issued.

7.2.2 REGULATORY AGENCY MAINTAINED WEBSITES

PSI reviewed the State of California GeoTracker and EnviroStor websites websites for records pertaining to underground storage tanks, hazardous material storage, spills, leaks, cleanups, violations, and releases at the subject property. No records for the subject property or adjoining property addresses were identified on the GeoTracker or EnviroStor databases.

8.0 VAPOR ENCROACHMENT SCREENING

8.1 METHODOLOGY

Vapor encroachment is an emerging concern associated with the potential for volatile chemicals, such as petroleum fuels and chlorinated solvents to migrate through the subsurface in the gas phase from contaminated soil and/or groundwater plumes. Vapor encroachment may be a concern if subsurface volatile contaminants migrate into occupied buildings through cracks and penetrations in the building slab.

The ASTM E1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment process requires the Environmental Professional to evaluate the potential for vapor encroachment onto the subject property, and to determine if such vapor encroachment constitutes evidence of a REC on the subject property. The E1527-13 Standard Practice does not specifically state the methods that must be used to screen for potential vapor encroachment issues. However, ASTM has developed a separate Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions (ASTM E2600-15). The vapor encroachment screening guidance outlines a methodology to conduct vapor encroachment screening, which will satisfy the vapor screening requirements under the Phase I ESA Standard Practice. PSI utilized the ASTM E2600-15 Standard Guide to conduct vapor encroachment screening for the subject property.

The goal of conducting Vapor Encroachment Screening (VES) is to identify a VEC, which is defined as the presence or likely presence of COC vapors in the subsurface of the subject property caused by the release of vapors from contaminated soil either on or near the subject property. If a VEC is identified, the environmental professional must determine whether the VEC represents evidence of a REC on the subject property under the context of the Phase I ESA Standard Practice. It should be noted that the identification of a VEC on the subject property does not necessarily indicate that a potential for migration of vapors into existing or proposed structures on the subject property is likely. The environmental professional will identify the VEC as a REC where the potential for vapor migration into structures is considered likely, or where the contaminant concentrations in the soil, groundwater, or soil vapors on the subject property are significant and likely to result in enforcement against on-site or off-site responsible parties.

The VES utilizes information regarding the potential presence of releases on or near the subject property that were collected as a normal part of the Phase I ESA process, such as governmental database records, review of governmental files, historical data sources, etc. No additional data was collected specifically for the purpose of the VES. In order to identify potential sites of concern within the AMSD, as available and appropriate, PSI reviewed fire insurance maps, governmental database records, regulatory agency files, aerial photographs, and other information.

VES Standard Guide prescribes a two tier approach for screening of sites for potential vapor encroachment. In Tier I, potential sites of concern within the search radii are identified and the environmental professional must determine whether a VEC exists or not based on the information that is available within the context of the Phase I ESA data gathering. If the available information indicates that a VEC exists based on available information, the environmental professional, in consultation with the User, may conduct Tier II screening to further evaluate the potential risk. Under Tier II, the environmental professional would review available

reports through the regulatory agency or other reasonably ascertainable sources to determine the status of assessment/remediation, size and migration pathways for any associated plumes, geologic conditions, and other geologic information. This information would be utilized to determine the distance between the plume and the target property boundary. For example, if the distance from the edge of a plume in a downgradient position to the subject property boundary exceeds 100 feet for VOCs or petroleum free product, or 30 feet for dissolved petroleum hydrocarbons (PHCs), then the site may be screened out and a VEC does not exist. Functionally, where Tier II information is readily available during the normal course of conducting the Phase I ESA, PSI has combined the Tier I and Tier II steps herein. Where agency files are not readily available for nearby contaminated sites within the typical schedule for a Phase I ESA, then Tier II screening might be recommended as a separate step subsequent to the Phase I ESA. Where Tier II screening is recommended, the sites of concern where data is lacking are considered a VEC until further information is available and/or further screening is completed.

The VES Standard Guide requires the environmental professional to search for potential sites of concern within the following databases and search distances, where groundwater flow is not known and/or preferential pathways for groundwater or vapor flow may exist:

Standard Environmental Records Sources	Minimum Search Distance (miles) - VOCs, excluding PHCs	Minimum Search Distance (miles) - PHCs
State and tribal HWS lists	1/3	1/10
State or tribal-equivalent NPL	1/3	1/10
State or tribal-equivalent CERCLIS list	1/3	1/10
State or tribal landfill or solid waste site list	1/3	1/10
State or tribal leaking storage tank lists	1/3	1/10
State and tribal registered tank lists	Subject property only	Subject property only
State and tribal IC/EC registries	Subject property only	Subject property only
State and tribal voluntary cleanup site lists	1/3	1/10
State and tribal brownfield sites list	1/3	1/10
Federal NPL site list	1/3	1/10
Federal CERCLIS list	1/3	1/10
Federal RCRA CORRACTS list	1/3	1/10
Federal RCRA non-CORRACTS TSD List	1/3	1/10
Federal RCRA Generators List	Subject property only	Subject property only
Federal IC/EC registries	Subject property only	Subject property only

Standard Environmental Records Sources	Minimum Search Distance (miles) - VOCs, excluding PHCs	Minimum Search Distance (miles) - PHCs
Federal ERNS list	Subject property only	Subject property only

The default search distances may be expanded or reduced in the up-gradient, down-gradient, or cross-gradient directions by the environmental professional based on experience in the local area and applying professional judgment to factors such as where a well-defined regional groundwater flow direction is identified, or whether other geologic features such as low permeability soils or hydrogeologic boundaries such as rivers or streams exist which would tend to limit the potential for migration of groundwater or vapors in a particular direction.

8.2 VES RESULTS

PSI identified four (4) sites of potential concern within the VES search radii. These sites were evaluated using the ERIS Vapor Screening Tool and the results of the VES are included in the ERIS Vapor Screening Report, which is appended. Based on that evaluation, no VECs were identified.

Site Name/ Address	Distance, Direction, Relative Elevation to the Subject Property	Does the site represent a VEC?	Comments
K-Swiss Sport Shoes Inc. 3177 Space Ctr Jurupa Valley CA 91752	~82 ft to the ENE and cross-gradient	No	Notice of violations related to this facility were located. However, the violations were regarding incomplete paperwork and not due to any environmental concern. This listing is not considered a VEC in connection with the subject property.

Site Name/ Address	Distance, Direction, Relative Elevation to the Subject Property	Does the site represent a VEC?	Comments
Gerard Daniel Worldwide Mira Loma 3265 PROGRESS CIR MIRA LOMA CA 91752	~89 ft to the ENE and cross-gradient	No	Notice of violations related to this facility were located. However, the violations were regarding incomplete paperwork and not due to any environmental concern. This listing is not considered a VEC in connection with the subject property.
Adam Nutrition 11010 Hopkins St #B Jurupa Valley CA 91752	~102 ft to the east and cross-gradient	No	Notice of violations related to paperwork compliance in 11/06/2020, 08/29/2018, 11/29/2017, and 09/09/2014. This listing is not considered a VEC in connection with the subject property.
Home Depot Distribution IDC #5645 11650 Venture Dr Jurupa Valley CA 91752	~145 ft to the north and up-gradient	No	Notice of violations related to this facility were located. However, the violations were regarding incomplete paperwork and not due to any environmental concern. This listing is not considered a VEC in connection with the subject property.

8.3 VES LIMITATIONS

The VES process is not intended to be an exhaustive screening and cannot wholly eliminate uncertainty regarding the presence of VECs in connection with the subject property. Screening is intended to reduce, but not eliminate uncertainty regarding whether or not a VEC exists in connection with the subject property.

9.0 NON-SCOPE CONSIDERATIONS

PSI conducted additional assessment to address conditions, also known as business environmental risks or BERs, beyond the scope of the Practice. Methodology and protocols used to conduct the assessment and evaluate these conditions follow.

9.1 VISUAL ASBESTOS SURVEY

Asbestos-Containing Materials (ACM) have been used extensively in buildings since the turn of the 20th century, and many buildings contain some quantity of ACM. As the adverse health effects of exposure to asbestos became known, the use and installation of many types of ACM in buildings was progressively phased out. By 1979 the EPA had banned the use of spray and troweled-on asbestos materials in building construction. In 1989, the EPA attempted to ban asbestos in all building products, however, this ban was subsequently overturned. Although this EPA ban in all products was overturned, the use of asbestos in building products saw a dramatically declined after 1989.

In addition to EPA policies related to building products, the U.S. Occupational Safety and Health Administration (OSHA) published regulations regarding the protection of workers from exposure to airborne asbestos. OSHA established the date of 1981, where surfacing materials and thermal insulation systems (TSI) must be "*Presumed"* ACM (PACM). In addition, all vinyl flooring systems installed prior to 1981 are "*designated"* as ACM by regulation. Because of the costs associated with the control, removal and disposal of certain types of ACM, it can have a significant impact on the value of a property.

The scope of work included observation of accessible areas of the building to identify suspect ACM could represent a possible "*Business Environmental Risk"* (BER) for the property. The observations were performed for due diligence purposes and were not intended to satisfy regulatory requirements for site demolition or renovation. Our scope of work also did not include sampling or destructive/invasive methods to observe materials that were not readily observable, such as beneath carpet, inside wall cavities, beneath/behind equipment, etc.

During the site reconnaissance, PSI observed the following suspect building materials:

- Floor tile and mastic
- Baseboard and mastic
- Ceiling tiles
- Drywall systems

The observed suspect ACM materials appeared to be in [good][1] condition and no removal or corrective actions are recommended. As the building was constructed between 1981 and 1989, no building materials are required to be presumed or designated as ACM. However, limited applications of ACM may exist, and PSI recommends that an asbestos Operations and Maintenance (O&M) Plan be developed for the site until such time that all suspect ACM can be properly characterized. If renovations or demolition are planned, PSI further recommends that all impacted suspect building materials be properly sampled and analyzed for possible asbestos content.

Footnote [1] *– Assumed that the materials in these optional paragraphs were in good condition with no recommended removal or corrective actions. If we have poor conditions, we will need to modify the paragraph to discuss the condition and determine if we are going to recommend removal, corrective actions or further investigation.*

9.2 VISUAL LEAD-BASED PAINT SURVEY

Use of lead-based paint was widespread until the 1950s, when it became evident that exposure to lead represented a health hazard, especially to children. Decreased usage of lead-based paint continued until 1978, when the manufacture and use of lead-based paints was banned for residential applications. Leaded paint and coating products continue to be produced and utilized for certain exempt applications, and there are cases where exempted paints have been used in residences constructed after the 1978 ban. Because leaded paint abatement procedures are expensive, the presence of lead-based paint may be a BER in association with a property.

PSI conducted a reconnaissance of the interior and exterior on the subject property building(s) to evaluate the condition of painted surfaces. It should be noted that lead-based paint cannot be visually detected, and sampling and laboratory analysis would typically be required to determine the lead content of any painted surfaces. Therefore, PSI evaluated the condition of painted surfaces and noted any surfaces that were in poor condition, which might lead to unacceptable airborne concentrations of lead inside the building.

PSI noted that the painted surfaces on the interior and exterior of the building were generally in good condition, with only minor evidence of flaking or peeling. Based on the construction date of the building (1987), PSI believes it is unlikely that lead-based paint is present.

9.3 RADON RECORDS REVIEW

Radon is a colorless, odor-less gas that results from the decay of naturally occurring radioactive minerals in the subsurface. Radon may enter buildings through foundation cracks, utility openings, etc. and may accumulate in the indoor air space. Radon is measured in pCi/L of air. The EPA has developed a recommended action level for radon levels in residential buildings of 4 pCi/L, but has not developed any recommendations for commercial structures. Generally, radon levels within slab-on-grade industrial and commercial structures would be expected to be lower than that found in single-family homes in the same location.

PSI performed a review of EPA records available online at the EPA's website pertaining to the potential presence of radon at the subject property. EPA has developed a radon zone map, which classifies each county within Zones 1 through 3 based on indoor radon measurements; geology; aerial radioactivity; soil permeability; and foundation type.

- **Zone 1** counties have a predicted average indoor radon screening level greater than 4 pCi/L - Highest Potential

- **Zone 2** counties have a predicted average indoor radon screening level between 2 and 4 pCi/L - Moderate Potential

- **Zone 3** counties have a predicted average indoor radon screening level less than 2 pCi/L - Low Potential

It should be noted that our work did not include sampling for radon in the building(s). While the review of the EPA Radon Zone maps provides an estimate of the potential for radon in the area, radon levels may vary on a structure by structure basis due to underlying geology and building construction characteristics.

The arithmetic average radon level reported in single-family homes in Riverside County is between 2 and 4 pCi/L.

Based on the records reviewed, the site is located in USEPA Zone 2 and is non-residential Therefore, radon is no considered to represent a significant concern.

9.4 LEAD IN DRINKING WATER RECORDS REVIEW

Lead in drinking water is regulated by the U.S. EPA under 40 Code of Federal Regulation (CFR) Part 141 Subpart I. The regulation applies to community systems and non-transient, non-community water systems. The EPA has established an action level of 15 micrograms per liter or parts per billion for lead in drinking water.

Potable water at the subject property is provided by Jurupa Community Services District. According to Jurupa Community Services District, the public water supply meets Federal guidelines for consumption. A copy of the most recent published Consumer Confidence Report or Water Quality Report is appended.

9.5 HISTORICAL OIL AND GAS WELLS RECORDS REVIEW

PSI reviewed readily-available maps showing locations of historical oil and gas wells in the vicinity of the subject property. No gas and oil production was historically performed in the geographical area of the subject property.

10.0 CONTRACT INFORMATION

10.1 STANDARD OF CARE AND WARRANTIES

Our services were not intended to be technically exhaustive. There is a possibility that with the proper application of methodologies, conditions may exist on the property that could not be identified within the scope of the assessment(s) or that were not reasonably identifiable from the available information.

No ESA can wholly eliminate uncertainty regarding the potential for RECs in connection with the property. The ESA was intended to reduce, but not eliminate uncertainty regarding the potential for RECs in connection with a property.

Our report is based on commonly known and reasonably ascertainable information, including limited, ground-level visual inspection of the property except where otherwise explicitly indicated, in conformance with ASTM E1527-13. Findings and conclusions derived from the methodologies described in the Practice contain all of the inherent limitations in the methodologies that are referred to in the Practice.

PSI has assumed that factual information provided to us by the client, or obtained from governmental and historical research firm, the public domain, interviews, and other sources is accurate and unbiased. PSI assumes no liability for the accuracy of data provided to us by others.

PSI did not perform exploratory probing or discovery, perform tests, operate specific equipment, or take measurements or samples to perform the ESA scope. The ESA was not a building code, safety, regulatory or environmental compliance inspection. The ESA is not intended to reduce the risk of the presence of mold and physical deficiencies conducive to mold nor the risk that mold or physical deficiencies conducive to mold may pose to the buildings and building occupants.

The methodologies include reviewing information provided by other sources. PSI treats information obtained from the record reviews and interviews concerning the property as reliable and the ASTM protocol does not require PSI to independently verify the information. Therefore, PSI cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete.

PSI has performed the services in a manner consistent with that level of care and skill ordinarily exercised by other members of our profession currently practicing in the same locality and under similar conditions, within the limitations of ASTM E1527-13 standard, and the All Appropriate Inquiries Rule established by the U.S. Environmental Protection Agency (40 C.F.R. Part 312). No other warranties are implied or expressed.

The observations and recommendations presented in this report are time dependent, and conditions will change. This report speaks only as of its date.

10.2 RELIANCE

Link Logistics Real Estate, PSI's client, may rely on this report.

This report is addressed to Citibank, N.A., Citigroup Global Markets Realty Corp. and Citi Real Estate Funding Inc. (Citigroup), and such other persons as may be designated by Citigroup and their respective successors and assigns. Special Conditions include (i) the Report may be relied upon by Citigroup in determining whether to make a loan evidenced by a note ("the Property Note") secured by the Subject Property, (ii) the Report may be relied upon by any purchaser in determining whether to purchase the Property Note from Citigroup and any rating agency rating securities issued by or representing an interest in the Mortgage Note, (iii) the Report may be referred to in and included with materials offering for sale the Property Note or an interest in the Property Note, (iv) persons who acquire the Property Note or an interest in the Property Note may rely on the Report, (v) the Report speaks only as of its date in the absence of a specific written update of the Report.

This report is for the use and benefit of, and may be relied upon by Citibank, N.A., Citigroup Global Markets Realty Corp. and Citi Real Estate Funding Inc. (Citigroup), and any of their respective affiliates, agents and advisors, the initial and subsequent holders from time to time of any debt (or any portion thereof) and/or debt securities secured, directly and indirectly, by the property which is the subject of this report, by any participation interest in any such debt (or any portion thereof), and indenture trustee, servicer or other agent acting on behalf of such holders of such debt (or any portion thereof) and/or debt securities; any rating agencies; and the institutional provider(s) from time to time of any liquidity facility or credit support for such financings, and their respective successors and assigns.

In addition, this report or a reference to this report, may be included or quoted in any offering circular, registration statement, private placement memorandum, prospectus or sales brochure (in either electronic or hard copy format) in connection with a securitization or transaction involving such debt (or any portion thereof) and or debt securities.

This report is addressed to BMO (collectively, Bank of Montreal, BMO Financial Group, BMO Capital Markets, BMO Harris Bank N.A., and any of their respective affiliates, agents and advisors (including, without limitation, investors who purchase the mortgage loan or a participation interest in the mortgage loan)). This report is for the use and benefit of, and may be relied upon by the following intended users: (i) BMO, (ii) the initial and subsequent holders from time to time of any debt (or any portion thereof) and/or debt securities secured, directly and indirectly, by the property that is the subject of this report, (iii) any participation interest in such debt (or any portion thereof), (iv) any indenture trustee, servicer or other agent acting on behalf of such holders of such debt (or any portion thereof) and/or debt securities, (v) any rating agencies, (vi) the institutional provider(s) from time to time of any liquidity facility or credit support for such financings, and (vii) any of the respective successors and assigns of any of the foregoing parties. In addition, this report or a reference to this report, may be included or quoted in any offering circular, registration statement, private placement memorandum, prospectus or sales brochure (in either electronic or hard copy format) in connection with a sale, securitization or syndication, or transaction involving such debt (or any portion thereof) and/or debt securities.

This report is addressed to Barclays Capital Real Estate Inc. ("BCREI") and its affiliates, their respective successors and assigns (including, without limitation, investors who purchase the mortgage loan or a participation interest in the mortgage loan and the trustee in a securitization that includes the mortgage loan), each servicer of the mortgage loan, and all rating agencies involved in any sale, securitization or syndication involving the mortgage loan may use and rely upon this Report, including, without limitation,

utilizing selected information from the Report in the offering materials (either in electronic or hard copy format) relating to any sale, securitization or syndication involving the mortgage loan. Intertek agrees to cooperate in answering questions by any of the above parties in connection with the sale, securitization or syndication, as communicated by BCREI personnel. In addition, this Report or a reference to this Report may be included or quoted in any offering circular, registration statement, prospectus or sales brochure (either in electronic or hard copy format) in connection with a sale, securitization or syndication, or transaction involving such debt and or debt securities. We hereby certify that we have no undisclosed interest in the property, and our employment and compensation are not contingent upon our findings. This study is subject to the comments made throughout this report and to all assumptions and limiting conditions set forth herein.

This report is for the use and benefit of, and may be relied upon by, Goldman, Sachs & Co., Goldman Sachs Mortgage Company, Goldman Sachs Bank USA, GS Commercial Real Estate LLC and any of their respective affiliates, agents and advisors, the initial and subsequent holders from time to time of any debt (or any portion thereof) and/or debt securities secured, directly and indirectly, by the property which is the subject of this report, by any participation interest in any such debt (or any portion thereof), and indenture trustee, servicer or other agent acting on behalf of such holders of such debt (or any portion thereof) and/or debt securities; any rating agencies; and the institutional provider(s) from time to time of any liquidity facility or credit support for such financings, and their respective successors and assigns.

In addition, this report or a reference to this report, may be included or quoted in any offering circular, registration statement, private placement memorandum, prospectus or sales brochure (in either electronic or hard copy format) in connection with a securitization or transaction involving such debt (or any portion thereof) and or debt securities.

10.3 USE BY OTHER PARTIES

This report was prepared pursuant to a contract between PSI and its client. That contractual relationship included an exchange of information about the property that was unique and serves as the basis upon which this report was prepared. Because of the importance of these understandings, our assessment may not be sufficient for the intended purposes of another party.

Reliance or any use of this report by anyone other than those parties identified above for which it was prepared, except with express written permission, is prohibited and therefore not foreseeable to PSI. Any unauthorized reliance on or use of this report, including any of the information or conclusions contained herein, will be at the third party's risk. No warranties or representations expressed or implied in this report are made to any such third party.

Third party reliance letters may be issued:

- upon timely request;
- subject to the permission of our original client; and
- payment of the then-current fee for such letters.

All third parties relying on our report, by such reliance, agree that such reliance is limited by our proposal and/or General Conditions, as applicable.

FIGURES




Figure 1 - Topographic Map

br40345

3401 Etiwanda Avenue - Bldg 1011

Jurupa Valley, California 91752

Work Order #: 00662058-13



Figure 2 - Site Vicinity Map

3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



Figure 3 - Site Map

br40345

3401 Etiwanda Avenue - Bldg 1011

Jurupa Valley, California 91752

Work Order #: 00662058-13

PHOTOGRAPHS



Photo 1: View of warehouse at American West.



Photo 2: View of warehouse at American West.



Photo 3: Forklifts in use at American West.



Photo 4: Portable generators observed at American West.



Photo 5: Small air compressor at American West warehouse.



Photo 6: Restrooms in the warehouse at American West.



Photo 7: Cleaning products at American West.



Photo 8: View of the subject property facing the western end from the southwest corner.



Photo 9: View of the subject property facing west from the northeast corner.



Photo 10: View of the subject property facing west from the southeast corner. The former railroad spur was observed along the southern end of the building.



Photo 11: View of Space Center Ct. followed by International Vitamin Corporation.



Photo 12: Pole-mounted transformer observed near the southeast corner of the subject property.



Photo 13: Trash compactor at the subject property.



Photo 14: View of the south adjoining building.



Photo 15: Office inside American West.




Photo 16: Office inside American West.



Photo 17: Propane tanks at American West for the forklifts.



Photo 18: Forklift charging station at American West.



Photo 19: Furniture touch up area at American West.



Photo 20: Fire-resistant cabinets at American West.



Photo 21: Warehouse at American West.



Photo 22: Office at Hanes Industries.



Photo 23: Forklifts at Hanes Industries.



Photo 24: Portable charger at Hanes Industries.



Photo 25: Warehouse entrance at Hanes Industries.



Photo 26: Warehouse with geotextiles at Hanes Industries.



Photo 27: Warehouse at Hanes Industries.



Photo 28: Warehouse with geotextiles at Hanes Industries.



Photo 29: Equipment to handle geotextiles at Hanes Industries.



Photo 30: Air compressor at Hanes Industries.



Photo 31: Air compressor and geotextiles at Hanes Industries.



Photo 32: Air compressor on plastic pallet at Hanes Industries.



Photo 33: Air compressor and hydraulic oil container at the warehouse of Hanes Industries.



Photo 34: Warehouse at Hanes Industries.



Photo 35: Forklift charging station at Hanes Industries.



Photo 36: Propane tank cage and loading bays at Hanes Industries.



Photo 37: View of the subject property loading area.



Photo 38: View of the subject property facing east from the northwest corner.



Photo 39: Storm drain located near the south adjoining building.



Photo 40: View of the southern wall of the subject property facing east.



Photo 41: View of C Street facing south from the southwest corner of the subject property.



Photo 42: Storm drain located in the loading area of the subject property.



Photo 43: Front view of Hanes Industries entrance.



Photo 44: Cleaning products at Hanes Industries.



Photo 45: Offices at Hanes Industries.

ENVIRONMENTAL DATABASE REPORT

ENVIRONMENTAL RISK INFORMATION SERVICES

DATABASE REPORT

Project Property:	*Space Center* *3401 Etiwanda Ave - Bldg 1011* *Jurupa Valley CA*
Project No:	*00662058*
Report Type:	*Database Report*
Order No:	*21032900155*
Requested by:	*Intertek PSI*
Date Completed:	*March 31, 2021*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....12
Executive Summary: Site Report Summary - Surrounding Properties.....19
Executive Summary: Summary by Data Source.....27
Map.....47
Aerial.....50
Topographic Map.....51
Detail Report.....52
Unplottable Summary.....363
Unplottable Report.....365
Appendix: Database Descriptions.....385
Definitions.....411

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*Space Center* *3401 Etiwanda Ave - Bldg 1011 Jurupa Valley CA*
Project No:		*00662058*
Coordinates:		
	Latitude:	*34.02592934*
	Longitude:	*-117.53327404*
	UTM Northing:	*3,765,159.18*
	UTM Easting:	*450,768.00*
	UTM Zone:	*11S*
Elevation:		*817 FT*

Order Information:

Order No:	*21032900155*
Date Requested:	*March 29, 2021*
Requested by:	*Intertek PSI*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (Boundaries)*
City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*
Vapor Screening Tool	*Vapor Screening Tool*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
FRP	Y	0.25	0	0	0	-	-	0
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	**1**	-	**1**
ODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	**1**	-	**1**
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	**1**	-	**1**
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	**1**	0	**2**	**4**	-	**7**
RCRA LQG	Y	0.125	0	0	-	-	-	0
RCRA SQG	Y	0.125	0	**3**	-	-	-	**3**
RCRA VSQG	Y	0.125	**1**	**1**	-	-	-	**2**
RCRA NON GEN	Y	0.125	**7**	**4**	-	-	-	**11**
FED ENG	Y	PO	0	-	-	-	-	0
FED INST	Y	PO	0	-	-	-	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
RESPONSE	Y	1	0	0	0	0	**1**	**1**
ENVIROSTOR	Y	1	**1**	**1**	0	**4**	**8**	**14**
DELISTED ENVS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	0	0	-	0
SWRCB SWF	Y	0.5	0	0	0	0	-	0
HWP	Y	1	**1**	0	0	0	**1**	**2**
SWAT	Y	0.5	0	0	0	0	-	0
LDS	Y	0.5	0	0	0	0	-	0
LUST	Y	0.5	**1**	0	**3**	**1**	-	**5**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.125	0	0	-	-	-	0
UST CLOSURE	Y	0.125	0	0	-	-	-	0
HHSS	Y	0.25	**1**	0	**2**	-	-	**3**
UST SWEEPS	Y	0.25	0	0	**1**	-	-	**1**
AST	Y	0.25	0	0	**2**	-	-	**2**
AST SWRCB	Y	0.25	0	0	**1**	-	-	**1**
TANK OIL GAS	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	0	**2**	-	-	**2**
CERS TANK	Y	0.25	0	**2**	**1**	-	-	**3**
DELISTED CTNK	Y	0.25	**1**	0	**1**	-	-	**2**
HIST TANK	Y	0.25	**1**	0	**2**	-	-	**3**
LUR	Y	PO	0	-	-	-	-	0
HLUR	Y	PO	0	-	-	-	-	0
DEED	Y	PO	0	-	-	-	-	0
VCP	Y	0.5	0	0	0	0	-	0
CLEANUP SITES	Y	0.5	0	0	0	0	-	0
DELISTED COUNTY	Y	0.25	**1**	**2**	**4**	-	-	**7**
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
INDIAN UST	Y	0.125	0	0	-	-	-	0
DELISTED ILST	Y	0.5	0	0	0	0	-	0
DELISTED IUST	Y	0.25	0	0	0	-	-	0
County								
ALAMEDA LOP	Y	0.5	0	0	0	0	-	0
UST ALAMEDA	Y	0.125	0	0	-	-	-	0
BERKELEY CUPA	Y	0.25	0	0	0	-	-	0
HAYWARD CUPA	Y	0.25	0	0	0	-	-	0
SANLEANDRO CUPA	Y	0.25	0	0	0	-	-	0
UNION UST	Y	0.125	0	0	-	-	-	0
UNION CUPA	Y	0.25	0	0	0	-	-	0
UNION CUPA	Y	0.25	0	0	0	-	-	0
LIVERMORE UST	Y	0.25	0	0	0	-	-	0
LIVERMORE AST	Y	0.25	0	0	0	-	-	0
LIVERMORE CUPA	Y	0.25	0	0	0	-	-	0
ALPINE CUPA	Y	0.25	0	0	0	-	-	0
AMADOR CUPA	Y	0.25	0	0	0	-	-	0
BUTTE CUPA	Y	0.25	0	0	0	-	-	0
CALAVERAS LF	Y	0.5	0	0	0	0	-	0
CALAVERAS LUST	Y	0.5	0	0	0	0	-	0
CALAVERAS UST	Y	0.25	0	0	0	-	-	0
CALAVERAS CUPA	Y	0.25	0	0	0	-	-	0
COLUSA CUPA	Y	0.25	0	0	0	-	-	0
CONTRACO CUPA	Y	0.25	0	0	0	-	-	0
DELNORTE CUPA	Y	0.25	0	0	0	-	-	0
ELDORADO CUPA	Y	0.25	0	0	0	-	-	0
FRESNO CUPA	Y	0.25	0	0	0	-	-	0
GLENN CUPA	Y	0.25	0	0	0	-	-	0
HUMBOLDT CUPA	Y	0.25	0	0	0	-	-	0
IMPERIAL CUPA	Y	0.25	0	0	0	-	-	0
INYO CUPA	Y	0.25	0	0	0	-	-	0
KERN UST	Y	0.25	0	0	0	-	-	0
KERN AST	Y	0.25	0	0	0	-	-	0
KERN CUPA	Y	0.25	0	0	0	-	-	0
BKRSFIELD CUPA	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
UST KINGS	Y	0.125	0	0	-	-	-	0
KINGS CUPA	Y	0.25	0	0	0	-	-	0
LAKE CUPA	Y	0.25	0	0	0	-	-	0
LASSEN CUPA	Y	0.25	0	0	0	-	-	0
LA SML	Y	0.5	0	0	0	0	-	0
LA SWF	Y	0.5	0	0	0	0	-	0
LA COUNTY CUPA	Y	0.25	0	0	0	-	-	0
LA HMS	Y	0.25	0	0	0	-	-	0
UST SANTAFESP	Y	0.125	0	0	-	-	-	0
UST LONGB	Y	0.125	0	0	-	-	-	0
BURBANK CUPA	Y	0.25	0	0	0	-	-	0
UST ELSEGUNDO	Y	0.125	0	0	-	-	-	0
UST SANTA MONICA	Y	0.125	0	0	-	-	-	0
SANTAMON AST	Y	0.25	0	0	0	-	-	0
SANTAMON CUPA	Y	0.25	0	0	0	-	-	0
UST TORRANCE	Y	0.125	0	0	-	-	-	0
UST VERNON	Y	0.125	0	0	-	-	-	0
VERNON CUPA	Y	0.25	0	0	0	-	-	0
UST LA CITY	Y	0.25	0	0	0	-	-	0
AST LA CITY	Y	0.25	0	0	0	-	-	0
LA CITY HAZMAT	Y	0.125	0	0	-	-	-	0
MADERA CUPA	Y	0.25	0	0	0	-	-	0
MARIN CUPA	Y	0.25	0	0	0	-	-	0
MARIPOSA CUPA	Y	0.25	0	0	0	-	-	0
MENDOCINO UST	Y	0.25	0	0	0	-	-	0
MENDOCINO CUPA	Y	0.25	0	0	0	-	-	0
MERCED CUPA	Y	0.25	0	0	0	-	-	0
MONO CUPA	Y	0.25	0	0	0	-	-	0
MONTEREY CUPA	Y	0.25	0	0	0	-	-	0
NAPA LOP	Y	0.5	0	0	0	0	-	0
UST NAPA	Y	0.125	0	0	-	-	-	0
NEVADA CUPA	Y	0.25	0	0	0	-	-	0
ORANGE ICP	Y	0.25	0	0	0	-	-	0
ORANGE LOP	Y	0.5	0	0	0	0	-	0
UST ORANGE CNTY	Y	0.125	0	0	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
ORANGE AST	Y	0.25	0	0	0	-	-	0
UST CLEANUP	Y	0.5	0	0	0	0	-	0
ANAHEIM UST	Y	0.125	0	0	-	-	-	0
ANAHEIM AST	Y	0.25	0	0	0	-	-	0
PLACER SML	Y	0.5	0	0	0	0	-	0
PLACER CUPA	Y	0.25	0	0	0	-	-	0
ROSEVILLE CUPA	Y	0.25	0	0	0	-	-	0
PLUMAS CUPA	Y	0.25	0	0	0	-	-	0
RIVERSIDE LOP	Y	0.5	**1**	0	**3**	**1**	-	**5**
UST RIVERSIDE	Y	0.125	0	0	-	-	-	0
SACRAMENTO TOX	Y	0.5	0	0	0	0	-	0
SACRAMENTO HAZ	Y	0.25	0	0	0	-	-	0
SAN BENITO CUPA	Y	0.25	0	0	0	-	-	0
SANBERN CUPA	Y	0.25	0	0	0	-	-	0
SANDIEGO SWF	Y	0.5	0	0	0	0	-	0
SAN DIEGO LOP	Y	0.5	0	0	0	0	-	0
SANDIEGO HAZ	Y	0.25	0	0	0	-	-	0
SANDIEGO UST	Y	0.25	0	0	0	-	-	0
SANDIEGO SAM	Y	0.5	0	0	0	0	-	0
SANFRAN LOP	Y	0.5	0	0	0	0	-	0
SANFRAN UST	Y	0.25	0	0	0	-	-	0
SANFRAN AST	Y	0.25	0	0	0	-	-	0
SANFRAN CUPA	Y	0.25	0	0	0	-	-	0
MAHER SF	Y	0.5	0	0	0	0	-	0
SJ SML	Y	0.5	0	0	0	0	-	0
SAN JOAQUIN SWF	Y	0.5	0	0	0	0	-	0
SAN JOAQUIN LOP	Y	0.5	0	0	0	0	-	0
SANJOAQUIN UST	Y	0.25	0	0	0	-	-	0
SANJOAQUIN AST	Y	0.25	0	0	0	-	-	0
SANLUISOB CUPA	Y	0.25	0	0	0	-	-	0
SANMATEO LOP	Y	0.5	0	0	0	0	-	0
SANMATEO CUPA	Y	0.25	0	0	0	-	-	0
SANTA BARB SMU	Y	0.5	0	0	0	0	-	0
SANTACLARA HSOL	Y	0.5	0	0	0	0	-	0
SANTACLARA LO	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
UST SANTACLARA	Y	0.25	0	0	0	-	-	0
SANTACLARA CUPA	Y	0.25	0	0	0	-	-	0
SANJOSE HM	Y	0.25	0	0	0	-	-	0
GILROY CUPA	Y	0.25	0	0	0	-	-	0
SUNNYVALE CUPA	Y	0.25	0	0	0	-	-	0
SC SML	Y	0.5	0	0	0	0	-	0
SANTACRUZ CUPA	Y	0.25	0	0	0	-	-	0
SHASTA CUPA	Y	0.25	0	0	0	-	-	0
SISKIYOU CUPA	Y	0.25	0	0	0	-	-	0
SOLANO LOP	Y	0.5	0	0	0	0	-	0
SOLANO UST	Y	0.25	0	0	0	-	-	0
SOLANO CUPA	Y	0.25	0	0	0	-	-	0
SONOMA LOP	Y	0.5	0	0	0	0	-	0
SONOMA CUPA	Y	0.25	0	0	0	-	-	0
PETAL CUPA	Y	0.25	0	0	0	-	-	0
STANISLAUS CUPA	Y	0.125	0	0	-	-	-	0
SUTTER CUPA	Y	0.25	0	0	0	-	-	0
TEHAMA CUPA	Y	0.25	0	0	0	-	-	0
TRINITY CUPA	Y	0.25	0	0	0	-	-	0
TULARE CUPA	Y	0.25	0	0	0	-	-	0
TUOLUMNE CUPA	Y	0.25	0	0	0	-	-	0
VENTURA HLUFT	Y	0.5	0	0	0	0	-	0
UST VENTURA INACT	Y	0.125	0	0	-	-	-	0
VENTURA CUPA	Y	0.25	0	0	0	-	-	0
OXNARD CUPA	Y	0.25	0	0	0	-	-	0
UST YOLO	Y	0.125	0	0	-	-	-	0
YOLO AST	Y	0.25	0	0	0	-	-	0
YOLO CUPA	Y	0.25	0	0	0	-	-	0
YUBA UST	Y	0.25	0	0	0	-	-	0
YUBA CUPA	Y	0.25	0	0	0	-	-	0

Additional Environmental Records

Federal

PFAS NPL	Y	0.5	0	0	0	0	-	0
FINDS/FRS	Y	PO	**16**	-	-	-	-	**16**
TRIS	Y	PO	0	-	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	**1**	0	**3**	0	**4**
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	**1**	0	**1**
URANIUM	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCB	Y	0.5	0	0	0	0	-	0
State								
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DRYC GRANT	Y	0.25	0	0	0	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
PFAS GW	Y	0.5	0	**1**	**1**	**7**	-	**9**
HWSS CLEANUP	Y	0.5	0	0	0	0	-	0
DTSC HWF	Y	0.5	0	0	0	0	-	0
INSP COMP ENF	Y	1	0	0	0	0	0	0
SCH	Y	1	0	0	0	0	0	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CHMIRS	Y	PO	**1**	-	-	-	-	**1**
HIST CHMIRS	Y	PO	0	-	-	-	-	0
HAZNET	Y	PO	**34**	-	-	-	-	**34**
HIST MANIFEST	Y	PO	**6**	-	-	-	-	**6**
HIST CORTESE	Y	0.5	0	0	0	0	-	0
CDO/CAO	Y	0.5	0	0	0	0	-	0
CERS HAZ	Y	0.125	**4**	**7**	-	-	-	**11**
DELISTED HAZ	Y	0.5	0	0	0	0	-	0
GEOTRACKER	Y	0.125	0	0	-	-	-	0
WASTE DISCHG	Y	0.25	0	0	0	-	-	0
EMISSIONS	Y	0.25	**6**	**1**	**4**	-	-	**11**
CDL	Y	0.125	0	0	-	-	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County								
SANTAMON HAZ	Y	0.125	0	0	-	-	-	0
SANTAMON HW	Y	0.125	0	0	-	-	-	0
ORANGE HW	Y	0.125	0	0	-	-	-	0
RIVERSIDE HWG	Y	0.125	**1**	**3**	-	-	-	**4**
RIVERSIDE HZH	Y	0.125	**4**	**6**	-	-	-	**10**
SJ COMPLAINTS	Y	0.5	0	0	0	0	-	0
SANJOAQUIN HM	Y	0.125	0	0	-	-	-	0
SANJOAQUIN HW	Y	0.125	0	0	-	-	-	0
VENTURA HAZR	Y	0.5	0	0	0	0	-	0
VENTURA IHW	Y	0.125	0	0	-	-	-	0
Total:			***89***	***32***	***29***	***24***	***10***	***184***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	RCRA NON GEN	PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAD000625780*	E	0.00 / 0.00	-3	52
1	RCRA NON GEN	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAD091927095*	E	0.00 / 0.00	-3	53
1	FINDS/FRS	G E RAILCAR REPAIR	3401 ETIWANDA AVENUE MIRA LOMA CA 91752-1128	E	0.00 / 0.00	-3	55
1	FINDS/FRS	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	55
1	FINDS/FRS	PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 91752	E	0.00 / 0.00	-3	56
1	FINDS/FRS	CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE BLDG 811A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	56
1	RIVERSIDE LOP	Space Center Mira Loma, Inc.	3401 Etiwanda Ave Mira Loma CA ***Site ID | Status Desc:*** *90640 | CLOSED/ACTION COMPLETED*	E	0.00 / 0.00	-3	57
1	DELISTED COUNTY	CPS Express, Inc	3401 Etiwanda Ave # 1011A Mira Loma CA 91752	E	0.00 / 0.00	-3	57
1	RIVERSIDE HZH	Jurupa Community Svcs Dist (Site 22)	3423 Space Center Ct Jurupa Valley CA 91752	E	0.00 / 0.00	-3	57
1	RIVERSIDE HZH	O'Neil Tube & Reel	3401 Etiwanda Ave #811C Jurupa Valley CA 91752	E	0.00 / 0.00	-3	57
1	RIVERSIDE HWG	O'Neil Tube & Reel	3401 Etiwanda Ave #811C Jurupa Valley CA 91752	E	0.00 / 0.00	-3	58
1	LUST	SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE MIRA LOMA CA 91752 ***Global ID | Status | Status Date:*** *T0606500200 | COMPLETED - CASE CLOSED | 1/2/1991*	E	0.00 / 0.00	-3	58
1	ENVIROSTOR	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000 ***Estor/EPA ID | Cleanup Status:*** *CAD091927095 |*	E	0.00 / 0.00	-3	60

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HWP	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000 ***Estor/EPA ID:*** *CAD091927095*	E	0.00 / 0.00	-3	60
1	CHMIRS	Riverside County Fire	3401 Etiwanda Ave. Suite 811 D Mira Loma CA ***Control No | Notified Date:*** *7/17/200402:10:32 AM*	E	0.00 / 0.00	-3	61
1	HHSS	CAMPBELL OIL COMPANY	3401 ETIWANDA AVE 502 MIRA LOMA CA 91752	E	0.00 / 0.00	-3	61
1	RIVERSIDE HZH	CPS Express, Inc	3401 Etiwanda Ave Bldg #711 Jurupa Valley CA 91752	E	0.00 / 0.00	-3	61
1	HAZNET	1X SPACE CTR MIRA LOMA INC	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	62
1	HAZNET	CPS EXPRESS INC	3401 E ETIWANDA ST MIRA LOMA CA 91752	E	0.00 / 0.00	-3	62
1	HAZNET	SWIFT TRANSPORTATION	3401 SPACE CENTER ST MIRA LOMA CA 000000000	E	0.00 / 0.00	-3	63
1	HAZNET	CHEMSTAR	3401 ETIWANDA AVE UNIT 911-D MIRA LOMA CA 91752	E	0.00 / 0.00	-3	64
1	HAZNET	CPS EXPRESS CORPORATION	3401 ETIWANDA AVE 621-B MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	64
1	HAZNET	O'NEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	E	0.00 / 0.00	-3	65
1	HAZNET	ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 917521128	E	0.00 / 0.00	-3	67
1	HAZNET	SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE BLDG 811D MIRA LOMA CA 917521128	E	0.00 / 0.00	-3	67
1	HAZNET	C CONSTRUCTION INC DBA BMC WEST BUILDING MATERIALS	3401 ETIWANDA AVE STE 831C MIRA LOMA CA 917521115	E	0.00 / 0.00	-3	69
1	HAZNET	KEYBOARD CARRIAGE INC	3401 ETIWANDA ST #731D MIRA LOMA CA 927510000	E	0.00 / 0.00	-3	69

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HAZNET	SPACE CENTER	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	70
1	HAZNET	MCVEIGH TRANSPORT	3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	72
1	HAZNET	GENERAL TELEPHONE OF CALIF	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	72
1	HAZNET	CARGO CATS, INC.	3401 ETIWANDA AVE MIRA LOMA CA 917521128	E	0.00 / 0.00	-3	73
1	HAZNET	PACIFIC FABRIC REELS INC	3401 ETIWANDA AVE #811C MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	74
1	HAZNET	PACIFIC FABRIC REELS	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 917521132	E	0.00 / 0.00	-3	74
1	HAZNET	CARGO CATS	3401 ETIWANDA AVE STE 8-11A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	75
1	HAZNET	PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	76
1	HAZNET	1X BORDEN TRUCKING INC	3401 ETIWANDA AVE, BLDG 911D MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	76
1	HAZNET	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	-3	77
1	HAZNET	CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	79
1	HAZNET	BORDEN TRUCKING INC DBA BORDEN LOGISTICS	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	82
1	HAZNET	DISTRIBUTION LOGISTICS MNGMNT INC	3401 ETIWANDA AVE BLDG 831 MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	82
1	HAZNET	NELSON-BALL PAPER PRODUCTS	3401 ETIWANDA AVE 931A MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	83

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HAZNET	SPACE CENTER	3401 ETIWANDA AVE 831D MIRA LOMA CA 917521128	E	0.00 / 0.00	-3	85
1	HAZNET	GTE SCRAP YARD	3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	86
1	HAZNET	CPS EXPRESS INC	3401 ETIWANDA AVE BLDG 621 MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	86
1	HAZNET	MCVEIGH TRANSPORTATION	3401 ETIWANDA MIRA LOMA CA 900000000	E	0.00 / 0.00	-3	87
1	HAZNET	UNION PACIFIC RAILROAD	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	87
1	HAZNET	SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	88
1	HAZNET	1X SPACE CTR MIRA LOMA INC	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	89
1	HAZNET	KARIS CHAM	3401 ETIWANDA AVE STE 811A JURUPA VALLEY CA 91752	E	0.00 / 0.00	-3	92
1	HAZNET	CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE BLDG 811A MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	92
1	HAZNET	1X PACIFIC FABRIC REELS	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	93
1	HIST MANIFEST		3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	-3	94
1	HIST MANIFEST		3401 ETIWANDA AVE, BLDG 911D MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	109
1	HIST MANIFEST		3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	110
1	HIST MANIFEST		3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	113

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HIST MANIFEST		3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	114
1	HIST MANIFEST		3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	-3	120
1	FINDS/FRS	O'NEIL TUBE & REEL	3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	E	0.00 / 0.00	-3	123
1	FINDS/FRS	SPACE CENTER	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	124
1	FINDS/FRS	CPS EXPRESSNA INC	3401 ETIWANDA AVE # 711 MIRA LOMA CA 91752	E	0.00 / 0.00	-3	124
1	FINDS/FRS	JURUPA COMMUNITY SVCS DIST(SITE 22)	3423 SPACE CENTER CT JURUPA VALLEY CA 91752	E	0.00 / 0.00	-3	125
1	FINDS/FRS	KEROZAKNA INC	3401 ETIWANDA AVE STE 811A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	125
1	RIVERSIDE HZH	Hanes Industries	3401 Etiwanda Ave Bldg 1011 Jurupa Valley CA 91752	E	0.00 / 0.00	-3	126
1	EMISSIONS	SPACE CENTER MIRA LOMA, INC	3401 ETIWANDA AVE, BLDG 1325 MIRA LOMA CA 91752	E	0.00 / 0.00	-3	126
1	EMISSIONS	JURUPA COMMUNITY SERVICES DIST	3401 ETIWANDA AV MIRA LOMA CA 91752	E	0.00 / 0.00	-3	127
1	EMISSIONS	JURUPA COMMUNITY SERVICES DIST	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	128
1	EMISSIONS	CAL CUSTOM DESIGN	3401 ETIWANDA AVE, BLDG #811-A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	129
1	EMISSIONS	G E RAILCAR REPAIR	3401 ETIWANDA AV MIRA LOMA CA 91752	E	0.00 / 0.00	-3	130
1	EMISSIONS	CAL CUSTOM DESIGN, INC RED-E-K	3401 ETIWANDA AV, BLDG 811A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	133

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	FINDS/FRS	JG HADDY SALES CO DBA CPS EXPRESS	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	133
1	FINDS/FRS	RHINO ATP INC	3401 ETIWANDA AVE #731A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	134
1	CERS HAZ	O'Neil Tube & Reel	3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	E	0.00 / 0.00	-3	135
1	CERS HAZ	CPS Express, Inc	3401 ETIWANDA AVE # 711 MIRA LOMA CA 91752	E	0.00 / 0.00	-3	139
1	CERS HAZ	Hanes Industries	3401 ETIWANDA AVE BUILDING 1011 UNITS C&D JURUPA VALLEY CA 91752	E	0.00 / 0.00	-3	141
1	HIST TANK	CAMPBELL OIL COMPANY	3401 ETIWANDA AVE, 502 MIRA LOMA CA	E	0.00 / 0.00	-3	144
1	FINDS/FRS	FRANK KAMS & ASSOC INC	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	-3	144
1	RCRA NON GEN	ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128 ***EPA Handler ID:*** *CAL000408792*	E	0.00 / 0.00	-3	145
1	RCRA NON GEN	O'NEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAL000348808*	E	0.00 / 0.00	-3	146
1	DELISTED CTNK	Jurupa Community Svcs Dist (Site 22)	3423 SPACE CENTER CT JURUPA VALLEY CA 91752	E	0.00 / 0.00	-3	147
1	FINDS/FRS	ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128	E	0.00 / 0.00	-3	147
1	FINDS/FRS	ONEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	E	0.00 / 0.00	-3	147
1	RCRA NON GEN	SPACE CENTER	3401 ETIWANDA AVE SUITE 821-A MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAC002996451*	E	0.00 / 0.00	-3	148

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	RCRA TSD	ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A ECOTECH CONSUMER PRODUCTS, LLC MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAC003011260*	E	0.00 / 0.00	-3	149
1	RCRA NON GEN	ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A ECOTECH CONSUMER PRODUCTS, LLC MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAC003011260*	E	0.00 / 0.00	-3	150
1	FINDS/FRS	ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	151
1	RCRA NON GEN	EDDIE ZHOU	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAC003057253*	E	0.00 / 0.00	-3	152
1	CERS HAZ	NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	-3	153
1	RCRA VSQG	MIRA LOMA	3401 ETIWANDA AVENUE BUILDING 811 MIRA LOMA CA 91752 ***EPA Handler ID:*** *CAR000014233*	E	0.00 / 0.00	-3	154
1	FINDS/FRS	EDDIE ZHOU	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	E	0.00 / 0.00	-3	156

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	PFAS GW		CA	ESE	0.00 / 20.08	-5	156
3	RIVERSIDE HZH	K-Swiss Sport Shoes Inc.	3177 Space Ctr Jurupa Valley CA 91752	ENE	0.05 / 269.00	10	164
3	CERS HAZ	K-Swiss Sport Shoes Inc.	3177 SPACE CTR JURUPA VALLEY CA 91752	ENE	0.05 / 269.00	10	164
4	CERS HAZ	Gerard Daniel Worldwide Mira Loma	3265 PROGRESS CIR MIRA LOMA CA 91752	ENE	0.06 / 292.53	9	169
4	RIVERSIDE HZH	Gerard Daniel Worldwide	3265 Progress Cir Jurupa Valley CA 91752	ENE	0.06 / 292.53	9	171
5	DELISTED COUNTY	Adam Nutrition	11010 Hopkins St #B Jurupa Valley CA 91752	E	0.06 / 336.18	3	171
5	RIVERSIDE HWG	International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	0.06 / 336.18	3	171
5	RIVERSIDE HZH	International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	0.06 / 336.18	3	171
5	CERS HAZ	International Vitamin Corporation	11010 HOPKINS ST #B MIRA LOMA CA 91752	E	0.06 / 336.18	3	171
5	RCRA NON GEN	INTERNATIONAL VITAMIN CORP	11010 HOPKINS ST MIRA LOMA CA 91752 ***EPA Handler ID:*** CAL000401988	E	0.06 / 336.18	3	176
6	RCRA NON GEN	ERIN FELDNER	11015 HOPKINS JURUPA VALLEY CA 91752 ***EPA Handler ID:*** CAC003053670	E	0.07 / 349.18	-2	177
7	DELISTED COUNTY	Phillips Lighting N.A.	11201 Iberia St Ste A Jurupa Valley CA 91752	ESE	0.07 / 361.88	-10	178

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
7	RIVERSIDE HZH	Triways, Inc	11201 Iberia St #B Jurupa Valley CA 91752	ESE	0.07 / 361.88	-10	178
7	CERS HAZ	Triways, Inc	11201 IBERIA ST #B MIRA LOMA CA 91752	ESE	0.07 / 361.88	-10	178
8	RCRA VSQG	IBERIA/GM BUILDING #5559	11600 IBERIA ST MIRA LOMA CA 91752 ***EPA Handler ID:*** CAR000278366	SE	0.08 / 430.39	-10	183
8	CERS HAZ	HD Pro Location #3256	11600 IBERIA ST JURUPA VALLEY CA 91752	SE	0.08 / 430.39	-10	185
9	RIVERSIDE HZH	Home Depot Distribution IDC #5645	11650 Venture Dr Jurupa Valley CA 91752	N	0.09 / 477.19	8	186
9	RIVERSIDE HWG	The Home Depot Store #5645	11650 Venture Dr Jurupa Valley CA 91752	N	0.09 / 477.19	8	186
9	ENVIROSTOR	MILLIKEN SANITARY LANDFILL	INTERSECTION: MILLIKEN AVE & MISSION BLV ONTARIO CA 91761 ***Estor/EPA ID | Cleanup Status:*** 36490106 | REFER: RWQCB AS OF 6/1/1995	N	0.09 / 477.19	8	187
9	CERS HAZ	The Home Depot Store #5645	11650 VENTURE DR MIRA LOMA CA 91752	N	0.09 / 477.19	8	188
9	RCRA SQG	HOME DEPOT USA INC HD 5645	11650 VENTURE DRIVE MIRA LOMA CA 91761 ***EPA Handler ID:*** CAR000168153	N	0.09 / 477.19	8	191
9	FUDS	MARCH COMMUNICATION ANNEX #2	SAN BERNARDINO/RIVERSIDE COUNTY LINES CA	N	0.09 / 477.19	8	192
10	RCRA NON GEN	POWER TRAIN PLUS	3227 PROGRESS CIR MIRA LOMA CA 91752 ***EPA Handler ID:*** CAL000311608	ENE	0.09 / 478.31	11	193
11	CERS TANK	Jurupa Community Svcs Dist(Site 25)	11561 IBERIA ST JURUPA VALLEY CA 91752 ***Site ID:*** 40748	SE	0.10 / 512.45	-11	194
12	RIVERSIDE HZH	Jurupa Community Svcs Dist(Site 25)	11561 Iberia St Jurupa Valley CA 91752	SE	0.10 / 515.85	-11	196

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
13	RCRA SQG	AMAZON.COM SERVICES LLC ONT1	11200 IBERIA STREET MIRA LOMA CA 91752 ***EPA Handler ID:*** CAR000311282	ESE	0.10 / 537.28	-13	196
13	CERS TANK	Amazon.com Services LLC - ONT1	11200 IBERIA ST JURUPA VALLEY CA 91752 ***Site ID:*** 568973	ESE	0.10 / 537.28	-13	199
14	RCRA SQG	CONSOLIDATE FREIGHTWAYS	11888 MISSION MIRA LOMA CA 91752 ***EPA Handler ID:*** CAD981574122	W	0.11 / 562.98	3	200
15	RIVERSIDE HWG	Mobile Modular	11450 Mission Blvd Jurupa Valley CA 91752	SSW	0.12 / 619.96	-15	202
15	CERS HAZ	Mobile Modular	11450 MISSION BLVD MIRA LOMA CA 91752	SSW	0.12 / 619.96	-15	202
15	RCRA NON GEN	MOBILE MODULAR MANAGEMENT CORP	11450 MISSION BLVD MIRA LOMA CA 91752 ***EPA Handler ID:*** CAL000298572	SSW	0.12 / 619.96	-15	206
16	EMISSIONS	PROPAK LOGISTICS, INC. REVERSE LOGISTICS	11555 IBERIA ST MIRA LOMA CA 91752	SSE	0.12 / 644.66	-13	207
17	LUST	FLYERS #462	11074 INLAND AVENUE JURUPA VALLEY CA 91752 ***Global ID | Status | Status Date:*** T10000007147 | COMPLETED - CASE CLOSED | 2/3/2017	ENE	0.13 / 688.25	15	208
17	RIVERSIDE LOP	Flyers #462	11074 Inland Jurupa Valley CA ***Site ID | Status Desc:*** 2015RO6600626 | CLOSED/ACTION COMPLETED	ENE	0.13 / 688.25	15	215
17	CERS TANK	Flyers # 462	11074 INLAND AVE MIRA LOMA CA 91752 ***Site ID:*** 144334	ENE	0.13 / 688.25	15	216
17	EMISSIONS	FLYERS ENERGY, LLC.	11074 INLAND AVE MIRA LOMA CA 91752	ENE	0.13 / 688.25	15	224
18	DELISTED COUNTY	Swift Transportation	11888 Mission Blvd Jurupa Valley CA 91752	W	0.14 / 738.66	4	225
18	HHSS	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	W	0.14 / 738.66	4	225

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
18	EMISSIONS	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	W	0.14 / 738.66	4	225
18	HIST TANK	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD. MIRA LOMA CA	W	0.14 / 738.66	4	225
19	DELISTED TNK	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD Mira Loma CA 91752	W	0.14 / 756.07	5	225
20	RIVERSIDE LOP	Consolidated Freightway	11888 Mission Blvd Mira Loma CA	W	0.16 / 843.70	4	226
			Site ID* | *Status Desc: 9915850 | CLOSED/ACTION COMPLETED				
20	UST SWEEPS	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA	W	0.16 / 843.70	4	226
			C C* | *Status: A33-000-21780 | ACTIVE ***Tank ID:*** 000005, 000009, 000001, 000011, 000006, 000010, 000007, 000013, 000002, 000004, 000008, 000012, 000014, 000003				
21	DELISTED COUNTY	Middle Atlantic Products	11150 Inland Ave Jurupa Valley CA 91752	NE	0.17 / 881.45	16	229
22	RIVERSIDE LOP	County of Riverside	11511 Venture Dr Riverside CA	N	0.17 / 910.73	12	229
			Site ID* | *Status Desc: 960074 | CLOSED/ACTION COMPLETED				
22	LUST	COUNTY OF RIVERSIDE	11511 VENTURE DR RIVERSIDE CA 91752	N	0.17 / 910.73	12	229
			Global ID* | *Status* | *Status Date: T0606500455 | COMPLETED - CASE CLOSED | 4/18/1998				
23	RCRA TSD	DEL REAL LLC	11041 INLAND AVE MIRA LOMA CA 91752-1155	ENE	0.18 / 957.02	16	232
			EPA Handler ID: CAL000348717				
24	RCRA TSD	ROADRUNNER TRANSPORTATION SERVICES, INC.	11385 VENTURE DR. MIRA LOMA CA 91752	NNE	0.18 / 970.36	16	233
			EPA Handler ID: CAC003009946				
25	PFAS GW		CA	SSE	0.20 / 1,043.65	-17	234
26	DELISTED COUNTY	Sprint Nextel CA 7208	11175 Inland Ave Jurupa Valley CA 91752	NE	0.20 / 1,050.07	18	244
26	AST	NEXTEL COMMUNICATIONS	11175 INLAND AVE. MIRA LOMA CA 91752	NE	0.20 / 1,050.07	18	244

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
26	AST	Nextel of California	11175 Inland Ave. Mira Loma CA 91752	NE	0.20 / 1,050.07	18	244
26	AST SWRCB	NEXTEL COMMUNICATIONS	11175 INLAND AVE. MIRA LOMA CA 91752	NE	0.20 / 1,050.07	18	245
27	DELISTED CTNK	GEODIS Logistics, LLC 0530	3285 DE FOREST CIR JURUPA VALLEY CA 91752	ENE	0.20 / 1,077.62	9	245
28	DELISTED TNK	POMA AUTOMATED FUELING	11074 INLAND AVE Mira Loma CA 91752	NE	0.21 / 1,122.26	20	245
29	EMISSIONS	JON RICHARDS COMPANY	11210 INLAND AVE MIRA LOMA CA 91752	NNE	0.21 / 1,123.72	19	245
30	DELISTED COUNTY	The Penn Companies	11199 Inland Ave Mira Loma CA 91752	NNE	0.23 / 1,191.22	20	245
31	LUST	FOOD GAS & GO MINI MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	-15	246
			Global ID* | *Status* | *Status Date: T0606500561 | COMPLETED - CASE CLOSED | 9/15/2009				
31	HHSS	FOOD GAS N GO MINI- MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	-15	254
31	EMISSIONS	ETIWANDA GAS MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	-15	254
31	HIST TANK	FOOD GAS N GO MINI- MART	3710 ETIWANDA AVE MIRA LOMA CA	ESE	0.23 / 1,233.00	-15	255
32	LUST	CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	WSW	0.28 / 1,500.04	1	255
			Global ID* | *Status* | *Status Date: T0606500619 | COMPLETED - CASE CLOSED | 10/20/2005				
33	ENVIROSTOR	MIRA LOMA GM DEPOT	RIVERSIDE CA	WNW	0.30 / 1,604.58	-2	258
			Estor/EPA ID* | *Cleanup Status: 80000321 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005				
33	ENVIROSTOR	MIRA LOMA AFS	MIRA LOMA CA	WNW	0.30 / 1,604.58	-2	258
			Estor/EPA ID* | *Cleanup Status: 80000319 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
33	ENVIROSTOR	QM SUPPLY DEPOT	MIRA LOMA CA	WNW	0.30 / 1,604.58	-2	259
			***Estor/EPA ID	Cleanup Status:*** 80000871 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005			
33	FUDS	MIRA LOMA AIR FORCE STATION	MIRA LOMA CA	WNW	0.30 / 1,604.58	-2	259
33	FUDS	MIRA LOMA QUARTERMASTER DEPOT	MIRA LOMA CA	WNW	0.30 / 1,604.58	-2	260
34	PFAS GW		CA	ESE	0.33 / 1,753.60	-7	260
35	PFAS GW		CA	N	0.36 / 1,901.75	29	270
36	RIVERSIDE LOP	FOOD GAS & GO MINI MART	3710 ETIWANDA AVE MIRA LOMA CA	SE	0.36 / 1,924.90	-21	280
			***Site ID	Status Desc:*** 9814821 | CLOSED/ACTION COMPLETED			
37	PFAS GW		CA	NE	0.37 / 1,949.23	29	280
38	PFAS GW		CA	ENE	0.38 / 1,999.69	12	290
39	ENVIROSTOR	MIRA LOMA ENG SUB-DEPT	RIVERSIDE CA	NE	0.41 / 2,145.17	32	300
			***Estor/EPA ID	Cleanup Status:*** 80000320 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005			
39	FUDS	MIRA LOMA ENGR SUB-DEPOT	NO CITY CA	NE	0.41 / 2,145.17	32	300
40	RCRA TSD	UNITED NATURAL FOODS INC.	WB 60 FWY @ MM 0.1 MIRA LOMA CA 91752	S	0.41 / 2,167.87	-27	300
			EPA Handler ID: CAC003012932				
41	CERCLIS	US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335	NE	0.42 / 2,200.77	33	301
			Site EPA ID: CAD028833945				
41	CERCLIS NFRAP	US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335	NE	0.42 / 2,200.77	33	303
			Site EPA ID: CAD028833945				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
41	SEMS ARCHIVE	US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335 ***EPA ID:*** CAD028833945	NE	0.42 / 2,200.77	33	304
42	MRDS	PHILADELPHIA RECYCLING MINE	RIVERSIDE COUNTY MIRA LOMA CA 91752	WNW	0.42 / 2,226.24	17	304
43	RCRA TSD	MARIA LEDEZMA	10882 WINDSOR PLACE MIRA LOMA CA 91752 ***EPA Handler ID:*** CAC003018351	ESE	0.44 / 2,319.33	-19	305
43	RCRA TSD	MARIA LEDEZMA	10882 WINDSOR PLACE MIRA LOMA CA 91752 ***EPA Handler ID:*** CAC003013651	ESE	0.44 / 2,319.33	-19	306
44	RCRA TSD	3M WEST COAST DISTRIBUTION CENTER	5151 E. PHILADELPHIA ST ONTARIO CA 91761-0000 ***EPA Handler ID:*** CAD982403966	NW	0.44 / 2,320.44	33	307
45	PFAS GW		CA	ENE	0.45 / 2,363.96	32	317
46	PFAS GW		CA	SW	0.46 / 2,439.23	-26	327
47	PFAS GW		CA	S	0.47 / 2,468.27	-28	341
48	ENVIROSTOR	MARCH COMM ANNEX	RIVERSIDE CA ***Estor/EPA ID | Cleanup Status:*** 80000081 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005	NNE	0.61 / 3,195.21	42	354
49	HWP	BUILDING MATERIALS MANUFACTURING CORP	11800 INDUSTRY AVE FONTANA CA 923370000 ***Estor/EPA ID:*** CAD021789284	NE	0.62 / 3,293.27	47	355
49	ENVIROSTOR	BUILDING MATERIALS MANUFACTURING CORP	11800 INDUSTRY AVE FONTANA CA 923370000 ***Estor/EPA ID | Cleanup Status:*** CAD021789284 |	NE	0.62 / 3,293.27	47	356
50	ENVIROSTOR	ALUMINUM DIE CASTING	10775 SAN SEVAINE WAY MIRA LOMA CA 91752 ***Estor/EPA ID | Cleanup Status:*** 71002959 | INACTIVE - NEEDS EVALUATION AS OF	ESE	0.78 / 4,093.63	-33	356
51	ENVIROSTOR	CAPITOL INDUSTRIAL PROPERTY	SOUTH END OF INDUSTRY AVE,N OF RIVERSIDE FONTANA CA 92335 ***Estor/EPA ID | Cleanup Status:*** 36280130 | NO FURTHER ACTION AS OF 9/26/1988	NE	0.79 / 4,162.80	57	357

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
52	RESPONSE	ORCHID PAPER PRODUCTS	INDUSTRY AVENUE FONTANA CA 92335	NE	0.79 / 4,163.33	57	359
			***Estor/EPA ID	Cleanup Status:*** 36260001 | CERTIFIED AS OF 12/1/1983			
52	ENVIROSTOR	ORCHID PAPER PRODUCTS	INDUSTRY AVENUE FONTANA CA 92335	NE	0.79 / 4,163.33	57	359
			***Estor/EPA ID	Cleanup Status:*** 36260001 | CERTIFIED AS OF 12/1/1983			
53	ENVIROSTOR	SIERRA ALUMINUM CO. - 11806 PACIFIC AVE.	11806 PACIFIC AVENUE FONTANA CA 92337	NE	0.87 / 4,571.64	57	360
			***Estor/EPA ID	Cleanup Status:*** 71003587 | NO ACTION REQUIRED AS OF 1/19/2001			
54	ENVIROSTOR	LORCIN ENGRG. CO., INC.	3830 WACKER DRIVE MIRA LOMA CA 91752	ESE	0.89 / 4,704.54	-37	361
			***Estor/EPA ID	Cleanup Status:*** 71003324 | INACTIVE - NEEDS EVALUATION AS OF			
55	ENVIROSTOR	SIERRA ALUMINUM CO.	11711 PACIFIC AVENUE FONTANA CA 92335	NE	0.90 / 4,748.85	57	362
			***Estor/EPA ID	Cleanup Status:*** 71002974 | NO ACTION REQUIRED AS OF			

Executive Summary: Summary by Data Source

Standard

Federal

SEMS ARCHIVE - SEMS List 8R Archive Sites

A search of the SEMS ARCHIVE database, dated Jan 28, 2021 has found that there are 1 SEMS ARCHIVE site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335 ***EPA ID**: CAD028833945*	NE	0.42 / 2,200.77	41

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335 ***Site EPA ID**: CAD028833945*	NE	0.42 / 2,200.77	41

CERCLIS NFRAP - CERCLIS - No Further Remedial Action Planned

A search of the CERCLIS NFRAP database, dated Oct 25, 2013 has found that there are 1 CERCLIS NFRAP site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
US REDUCTION CO	11600 ETIWANDA AVE FONTANA CA 92335 ***Site EPA ID**: CAD028833945*	NE	0.42 / 2,200.77	41

RCRA TSD - RCRA non-CORRACTS TSD Facilities

A search of the RCRA TSD database, dated Jan 22, 2021 has found that there are 7 RCRA TSD site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DEL REAL LLC	11041 INLAND AVE MIRA LOMA CA 91752-1155 ***EPA Handler ID**: CAL000348717*	ENE	0.18 / 957.02	23
ROADRUNNER TRANSPORTATION SERVICES, INC.	11385 VENTURE DR. MIRA LOMA CA 91752	NNE	0.18 / 970.36	24

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID**: CAC003009946*			
3M WEST COAST DISTRIBUTION CENTER	5151 E. PHILADELPHIA ST ONTARIO CA 91761-0000	NW	0.44 / 2,320.44	44
	***EPA Handler ID**: CAD982403966*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A ECOTECH CONSUMER PRODUCTS, LLC MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003011260*	E	0.00 / 0.00	1
UNITED NATURAL FOODS INC.	WB 60 FWY @ MM 0.1 MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003012932*	S	0.41 / 2,167.87	40
MARIA LEDEZMA	10882 WINDSOR PLACE MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003018351*	ESE	0.44 / 2,319.33	43
MARIA LEDEZMA	10882 WINDSOR PLACE MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003013651*	ESE	0.44 / 2,319.33	43

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Jan 22, 2021 has found that there are 3 RCRA SQG site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
HOME DEPOT USA INC HD 5645	11650 VENTURE DRIVE MIRA LOMA CA 91761 ***EPA Handler ID**: CAR000168153*	N	0.09 / 477.19	9
CONSOLIDATE FREIGHTWAYS	11888 MISSION MIRA LOMA CA 91752 ***EPA Handler ID**: CAD981574122*	W	0.11 / 562.98	14

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
AMAZON.COM SERVICES LLC ONT1	11200 IBERIA STREET MIRA LOMA CA 91752 ***EPA Handler ID**: CAR000311282*	ESE	0.10 / 537.28	13

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Jan 22, 2021 has found that there are 2 RCRA VSQG site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MIRA LOMA	3401 ETIWANDA AVENUE BUILDING 811 MIRA LOMA CA 91752 ***EPA Handler ID**: CAR000014233*	E	0.00 / 0.00	1
IBERIA/GM BUILDING #5559	11600 IBERIA ST MIRA LOMA CA 91752 ***EPA Handler ID**: CAR000278366*	SE	0.08 / 430.39	8

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Jan 22, 2021 has found that there are 11 RCRA NON GEN site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
INTERNATIONAL VITAMIN CORP	11010 HOPKINS ST MIRA LOMA CA 91752 ***EPA Handler ID**: CAL000401988*	E	0.06 / 336.18	5
POWER TRAIN PLUS	3227 PROGRESS CIR MIRA LOMA CA 91752 ***EPA Handler ID**: CAL000311608*	ENE	0.09 / 478.31	10

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A ECOTECH CONSUMER PRODUCTS, LLC MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003011260*	E	0.00 / 0.00	1
EDDIE ZHOU	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752 ***EPA Handler ID**: CAC003057253*	E	0.00 / 0.00	1
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 91752 ***EPA Handler ID**: CAD091927095*	E	0.00 / 0.00	1
O'NEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752 ***EPA Handler ID**: CAL000348808*	E	0.00 / 0.00	1
ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128 ***EPA Handler ID**: CAL000408792*	E	0.00 / 0.00	1
PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 91752 ***EPA Handler ID**: CAD000625780*	E	0.00 / 0.00	1
SPACE CENTER	3401 ETIWANDA AVE SUITE 821-A MIRA LOMA CA 91752	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***EPA Handler ID**: CAC002996451*			
ERIN FELDNER	11015 HOPKINS JURUPA VALLEY CA 91752	E	0.07 / 349.18	6
	***EPA Handler ID**: CAC003053670*			
MOBILE MODULAR MANAGEMENT CORP	11450 MISSION BLVD MIRA LOMA CA 91752	SSW	0.12 / 619.96	15
	***EPA Handler ID**: CAL000298572*			

State

RESPONSE - State Response Sites

A search of the RESPONSE database, dated Jan 13, 2021 has found that there are 1 RESPONSE site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ORCHID PAPER PRODUCTS	INDUSTRY AVENUE FONTANA CA 92335	NE	0.79 / 4,163.33	52
	***Estor/EPA ID**	**Cleanup Status**: 36260001 | CERTIFIED AS OF 12/1/1983*		

ENVIROSTOR - EnviroStor Database

A search of the ENVIROSTOR database, dated Jan 13, 2021 has found that there are 14 ENVIROSTOR site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MILLIKEN SANITARY LANDFILL	INTERSECTION: MILLIKEN AVE & MISSION BLV ONTARIO CA 91761	N	0.09 / 477.19	9
	***Estor/EPA ID**	**Cleanup Status**: 36490106 | REFER: RWQCB AS OF 6/1/1995*		
MIRA LOMA ENG SUB-DEPT	RIVERSIDE CA	NE	0.41 / 2,145.17	39
	***Estor/EPA ID**	**Cleanup Status**: 80000320 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*		
MARCH COMM ANNEX	RIVERSIDE CA	NNE	0.61 / 3,195.21	48
	***Estor/EPA ID**	**Cleanup Status**: 80000081 | INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*		
BUILDING MATERIALS MANUFACTURING CORP	11800 INDUSTRY AVE FONTANA CA 923370000	NE	0.62 / 3,293.27	49
	***Estor/EPA ID**	**Cleanup Status**: CAD021789284 |*		
CAPITOL INDUSTRIAL PROPERTY	SOUTH END OF INDUSTRY AVE,N OF RIVERSIDE FONTANA CA 92335	NE	0.79 / 4,162.80	51
	***Estor/EPA ID**	**Cleanup Status**: 36280130 | NO FURTHER ACTION AS OF 9/26/1988*		
ORCHID PAPER PRODUCTS	INDUSTRY AVENUE FONTANA CA 92335	NE	0.79 / 4,163.33	52
	***Estor/EPA ID**	**Cleanup Status**: 36260001 | CERTIFIED AS OF 12/1/1983*		

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SIERRA ALUMINUM CO. - 11806 PACIFIC AVE.	11806 PACIFIC AVENUE FONTANA CA 92337	NE	0.87 / 4,571.64	53
	***Estor/EPA ID	Cleanup Status**: 71003587	NO ACTION REQUIRED AS OF 1/19/2001*		
SIERRA ALUMINUM CO.	11711 PACIFIC AVENUE FONTANA CA 92335	NE	0.90 / 4,748.85	55
	***Estor/EPA ID	Cleanup Status**: 71002974	NO ACTION REQUIRED AS OF*		

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	1
	***Estor/EPA ID	Cleanup Status**: CAD091927095 |*		
MIRA LOMA GM DEPOT	RIVERSIDE CA	WNW	0.30 / 1,604.58	33
	***Estor/EPA ID	Cleanup Status**: 80000321	INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*		
MIRA LOMA AFS	MIRA LOMA CA	WNW	0.30 / 1,604.58	33
	***Estor/EPA ID	Cleanup Status**: 80000319	INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*		
QM SUPPLY DEPOT	MIRA LOMA CA	WNW	0.30 / 1,604.58	33
	***Estor/EPA ID	Cleanup Status**: 80000871	INACTIVE - NEEDS EVALUATION AS OF 7/1/2005*		
ALUMINUM DIE CASTING	10775 SAN SEVAINE WAY MIRA LOMA CA 91752	ESE	0.78 / 4,093.63	50
	***Estor/EPA ID	Cleanup Status**: 71002959	INACTIVE - NEEDS EVALUATION AS OF*		
LORCIN ENGRG. CO., INC.	3830 WACKER DRIVE MIRA LOMA CA 91752	ESE	0.89 / 4,704.54	54
	***Estor/EPA ID	Cleanup Status**: 71003324	INACTIVE - NEEDS EVALUATION AS OF*		

HWP - EnviroStor Hazardous Waste Facilities

A search of the HWP database, dated Jan 13, 2021 has found that there are 2 HWP site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
BUILDING MATERIALS MANUFACTURING CORP	11800 INDUSTRY AVE FONTANA CA 923370000	NE	0.62 / 3,293.27	49
	***Estor/EPA ID**: CAD021789284*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	1
	***Estor/EPA ID**: CAD091927095*			

LUST - Leaking Underground Fuel Tank Reports

A search of the LUST database, dated Nov 16, 2020 has found that there are 5 LUST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FLYERS #462	11074 INLAND AVENUE JURUPA VALLEY CA 91752	ENE	0.13 / 688.25	17
	Global ID* | *Status* | *Status Date: *T10000007147* | *COMPLETED - CASE CLOSED* | *2/3/2017*			
COUNTY OF RIVERSIDE	11511 VENTURE DR RIVERSIDE CA 91752	N	0.17 / 910.73	22
	Global ID* | *Status* | *Status Date: *T0606500455* | *COMPLETED - CASE CLOSED* | *4/18/1998*			
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	WSW	0.28 / 1,500.04	32
	Global ID* | *Status* | *Status Date: *T0606500619* | *COMPLETED - CASE CLOSED* | *10/20/2005*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
	Global ID* | *Status* | *Status Date: *T0606500200* | *COMPLETED - CASE CLOSED* | *1/2/1991*			
FOOD GAS & GO MINI MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	31
	Global ID* | *Status* | *Status Date: *T0606500561* | *COMPLETED - CASE CLOSED* | *9/15/2009*			

HHSS - Historical Hazardous Substance Storage Information Database

A search of the HHSS database, dated Aug 27, 2015 has found that there are 3 HHSS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	W	0.14 / 738.66	18

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CAMPBELL OIL COMPANY	3401 ETIWANDA AVE 502 MIRA LOMA CA 91752	E	0.00 / 0.00	1
FOOD GAS N GO MINI-MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	31

UST SWEEPS - Statewide Environmental Evaluation and Planning System

A search of the UST SWEEPS database, dated Oct 1, 1994 has found that there are 1 UST SWEEPS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA	W	0.16 / 843.70	20
	***C C | Status**: A33-000-21780 | ACTIVE* ***Tank ID**: 000005, 000009, 000001, 000011, 000006, 000010, 000007, 000013, 000002, 000004, 000008, 000012, 000014, 000003*			

AST - Aboveground Storage Tanks

A search of the AST database, dated Aug 31, 2009 has found that there are 2 AST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Nextel of California	11175 Inland Ave. Mira Loma CA 91752	NE	0.20 / 1,050.07	26
NEXTEL COMMUNICATIONS	11175 INLAND AVE. MIRA LOMA CA 91752	NE	0.20 / 1,050.07	26

AST SWRCB - SWRCB Historical Aboveground Storage Tanks

A search of the AST SWRCB database, dated Dec 1, 2007 has found that there are 1 AST SWRCB site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEXTEL COMMUNICATIONS	11175 INLAND AVE. MIRA LOMA CA 91752	NE	0.20 / 1,050.07	26

DELISTED TNK - Delisted Storage Tanks

A search of the DELISTED TNK database, dated Mar 9, 2021 has found that there are 2 DELISTED TNK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD Mira Loma CA 91752	W	0.14 / 756.07	19
POMA AUTOMATED FUELING	11074 INLAND AVE Mira Loma CA 91752	NE	0.21 / 1,122.26	28

CERS TANK - California Environmental Reporting System (CERS) Tanks

A search of the CERS TANK database, dated Feb 9, 2021 has found that there are 3 CERS TANK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Flyers # 462	11074 INLAND AVE MIRA LOMA CA 91752	ENE	0.13 / 688.25	17

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***Site ID**: 144334*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Jurupa Community Svcs Dist(Site 25)	11561 IBERIA ST JURUPA VALLEY CA 91752 ***Site ID**: 40748*	SE	0.10 / 512.45	11
Amazon.com Services LLC - ONT1	11200 IBERIA ST JURUPA VALLEY CA 91752 ***Site ID**: 568973*	ESE	0.10 / 537.28	13

DELISTED CTNK - Delisted California Environmental Reporting System (CERS) Tanks

A search of the DELISTED CTNK database, dated Feb 9, 2021 has found that there are 2 DELISTED CTNK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
GEODIS Logistics, LLC 0530	3285 DE FOREST CIR JURUPA VALLEY CA 91752	ENE	0.20 / 1,077.62	27

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Jurupa Community Svcs Dist(Site 22)	3423 SPACE CENTER CT JURUPA VALLEY CA 91752	E	0.00 / 0.00	1

HIST TANK - Historical Hazardous Substance Storage Container Information - Facility Summary

A search of the HIST TANK database, dated May 27, 1988 has found that there are 3 HIST TANK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD. MIRA LOMA CA	W	0.14 / 738.66	18

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CAMPBELL OIL COMPANY	3401 ETIWANDA AVE, 502 MIRA LOMA CA	E	0.00 / 0.00	1
FOOD GAS N GO MINI-MART	3710 ETIWANDA AVE MIRA LOMA CA	ESE	0.23 / 1,233.00	31

DELISTED COUNTY - Delisted County Records

A search of the DELISTED COUNTY database, dated Mar 23, 2021 has found that there are 7 DELISTED COUNTY site(s) within

approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Adam Nutrition	11010 Hopkins St #B Jurupa Valley CA 91752	E	0.06 / 336.18	5
Swift Transportation	11888 Mission Blvd Jurupa Valley CA 91752	W	0.14 / 738.66	18
Middle Atlantic Products	11150 Inland Ave Jurupa Valley CA 91752	NE	0.17 / 881.45	21
Sprint Nextel CA 7208	11175 Inland Ave Jurupa Valley CA 91752	NE	0.20 / 1,050.07	26
The Penn Companies	11199 Inland Ave Mira Loma CA 91752	NNE	0.23 / 1,191.22	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CPS Express, Inc	3401 Etiwanda Ave # 1011A Mira Loma CA 91752	E	0.00 / 0.00	1
Phillips Lighting N.A.	11201 Iberia St Ste A Jurupa Valley CA 91752	ESE	0.07 / 361.88	7

County

RIVERSIDE LOP - Riverside County - Local Oversight Program List

A search of the RIVERSIDE LOP database, dated Mar 23, 2021 has found that there are 5 RIVERSIDE LOP site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Flyers #462	11074 Inland Jurupa Valley CA	ENE	0.13 / 688.25	17
	Site ID* | *Status Desc: *2015RO6600626 | CLOSED/ACTION COMPLETED*			
Consolidated Freightway	11888 Mission Blvd Mira Loma CA	W	0.16 / 843.70	20
	Site ID* | *Status Desc: *9915850 | CLOSED/ACTION COMPLETED*			
County of Riverside	11511 Venture Dr Riverside CA	N	0.17 / 910.73	22
	Site ID* | *Status Desc: *960074 | CLOSED/ACTION COMPLETED*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Space Center Mira Loma, Inc.	3401 Etiwanda Ave Mira Loma CA	E	0.00 / 0.00	1
	Site ID* | *Status Desc: *90640* | *CLOSED/ACTION COMPLETED*			
FOOD GAS & GO MINI MART	3710 ETIWANDA AVE MIRA LOMA CA	SE	0.36 / 1,924.90	36
	Site ID* | *Status Desc: *9814821* | *CLOSED/ACTION COMPLETED*			

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 16 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
JURUPA COMMUNITY SVCS DIST(SITE 22)	3423 SPACE CENTER CT JURUPA VALLEY CA 91752	E	0.00 / 0.00	1
SPACE CENTER	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
CPS EXPRESSNA INC	3401 ETIWANDA AVE # 711 MIRA LOMA CA 91752	E	0.00 / 0.00	1
KEROZAKNA INC	3401 ETIWANDA AVE STE 811A MIRA LOMA CA 91752	E	0.00 / 0.00	1
JG HADDY SALES CO DBA CPS EXPRESS	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
RHINO ATP INC	3401 ETIWANDA AVE #731A MIRA LOMA CA 91752	E	0.00 / 0.00	1
FRANK KAMS & ASSOC INC	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ONEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	E	0.00 / 0.00	1
ECOTECH CONSUMER PRODUCTS	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	E	0.00 / 0.00	1
EDDIE ZHOU	3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	E	0.00 / 0.00	1
G E RAILCAR REPAIR	3401 ETIWANDA AVENUE MIRA LOMA CA 91752-1128	E	0.00 / 0.00	1
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 91752	E	0.00 / 0.00	1
PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 91752	E	0.00 / 0.00	1
CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE BLDG 811A MIRA LOMA CA 91752	E	0.00 / 0.00	1
O'NEIL TUBE & REEL	3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	E	0.00 / 0.00	1

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated Jan 28, 2020 has found that there are 4 FUDS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARCH COMMUNICATION ANNEX #2	SAN BERNARDINO/RIVERSIDE COUNTY LINES CA	N	0.09 / 477.19	9
MIRA LOMA ENGR SUB-DEPOT	NO CITY CA	NE	0.41 / 2,145.17	39

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MIRA LOMA AIR FORCE STATION	MIRA LOMA CA	WNW	0.30 / 1,604.58	33

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MIRA LOMA QUARTERMASTER DEPOT	MIRA LOMA CA	WNW	0.30 / 1,604.58	33

MRDS - Mineral Resource Data System

A search of the MRDS database, dated Mar 15, 2006 has found that there are 1 MRDS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PHILADELPHIA RECYCLING MINE	RIVERSIDE COUNTY MIRA LOMA CA 91752	WNW	0.42 / 2,226.24	42

State

PFAS GW - PFOA/PFOS Groundwater

A search of the PFAS GW database, dated Oct 22, 2020 has found that there are 9 PFAS GW site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	CA	N	0.36 / 1,901.75	35
	CA	NE	0.37 / 1,949.23	37
	CA	ENE	0.38 / 1,999.69	38
	CA	ENE	0.45 / 2,363.96	45

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	CA	ESE	0.00 / 20.08	2
	CA	SSE	0.20 / 1,043.65	25
	CA	ESE	0.33 / 1,753.60	34

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	CA	SW	0.46 / 2,439.23	46
	CA	S	0.47 / 2,468.27	47

CHMIRS - California Hazardous Material Incident Report System (CHMIRS)

A search of the CHMIRS database, dated Jan 21, 2021 has found that there are 1 CHMIRS site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Riverside County Fire	3401 Etiwanda Ave. Suite 811 D Mira Loma CA	E	0.00 / 0.00	1
	***Control No | Notified Date**: 7/17/200402:10:32 AM*			

HAZNET - Hazardous Waste Manifest Data

A search of the HAZNET database, dated Oct 24, 2016 has found that there are 34 HAZNET site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE BLDG 811A MIRA LOMA CA 917520000	E	0.00 / 0.00	1
1X PACIFIC FABRIC REELS	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
1X SPACE CTR MIRA LOMA INC	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
CPS EXPRESS INC	3401 E ETIWANDA ST MIRA LOMA CA 91752	E	0.00 / 0.00	1
SWIFT TRANSPORTATION	3401 SPACE CENTER ST MIRA LOMA CA 000000000	E	0.00 / 0.00	1
CHEMSTAR	3401 ETIWANDA AVE UNIT 911-D MIRA LOMA CA 91752	E	0.00 / 0.00	1
CPS EXPRESS CORPORATION	3401 ETIWANDA AVE 621-B MIRA LOMA CA 917520000	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
O'NEILL TUBE & REEL	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	E	0.00 / 0.00	1
ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION	3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 917521128	E	0.00 / 0.00	1
SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE BLDG 811D MIRA LOMA CA 917521128	E	0.00 / 0.00	1
C CONSTRUCTION INC DBA BMC WEST BUILDING MATERIALS	3401 ETIWANDA AVE STE 831C MIRA LOMA CA 917521115	E	0.00 / 0.00	1
KEYBOARD CARRIAGE INC	3401 ETIWANDA ST #731D MIRA LOMA CA 927510000	E	0.00 / 0.00	1
SPACE CENTER	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
MCVEIGH TRANSPORT	3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	1
GENERAL TELEPHONE OF CALIF	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
CARGO CATS, INC.	3401 ETIWANDA AVE MIRA LOMA CA 917521128	E	0.00 / 0.00	1
PACIFIC FABRIC REELS INC	3401 ETIWANDA AVE #811C MIRA LOMA CA 917520000	E	0.00 / 0.00	1
PACIFIC FABRIC REELS	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 917521132	E	0.00 / 0.00	1
CARGO CATS	3401 ETIWANDA AVE STE 8-11A MIRA LOMA CA 91752	E	0.00 / 0.00	1
PROKO INDUSTRIES, INC.	3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 917520000	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
1X BORDEN TRUCKING INC	3401 ETIWANDA AVE, BLDG 911D MIRA LOMA CA 917520000	E	0.00 / 0.00	1
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	1
CALIFORNIA CUSTOM DESIGN	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
BORDEN TRUCKING INC DBA BORDEN LOGISTICS	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
DISTRIBUTION LOGISTICS MNGMNT INC	3401 ETIWANDA AVE BLDG 831 MIRA LOMA CA 917520000	E	0.00 / 0.00	1
NELSON-BALL PAPER PRODUCTS	3401 ETIWANDA AVE 931A MIRA LOMA CA 917520000	E	0.00 / 0.00	1
SPACE CENTER	3401 ETIWANDA AVE 831D MIRA LOMA CA 917521128	E	0.00 / 0.00	1
GTE SCRAP YARD	3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	1
CPS EXPRESS INC	3401 ETIWANDA AVE BLDG 621 MIRA LOMA CA 917520000	E	0.00 / 0.00	1
MCVEIGH TRANSPORTATION	3401 ETIWANDA MIRA LOMA CA 900000000	E	0.00 / 0.00	1
UNION PACIFIC RAILROAD	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
SPACE CENTER MIRA LOMA	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
1X SPACE CTR MIRA LOMA INC	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
KARIS CHAM	3401 ETIWANDA AVE STE 811A JURUPA VALLEY CA 91752	E	0.00 / 0.00	1

HIST MANIFEST - Historical Hazardous Waste Manifest Data

A search of the HIST MANIFEST database, dated Dec 31, 1992 has found that there are 6 HIST MANIFEST site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	1
	3401 ETIWANDA AVE, BLDG 911D MIRA LOMA CA 917520000	E	0.00 / 0.00	1
	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1
	3401 ETIWANDA MIRA LOMA CA 917520000	E	0.00 / 0.00	1
	3401 ETIWANDA AVE MIRA LOMA CA 917520000	E	0.00 / 0.00	1

CERS HAZ - California Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the CERS HAZ database, dated Feb 9, 2021 has found that there are 11 CERS HAZ site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
K-Swiss Sport Shoes Inc.	3177 SPACE CTR JURUPA VALLEY CA 91752	ENE	0.05 / 269.00	3
Gerard Daniel Worldwide Mira Loma	3265 PROGRESS CIR MIRA LOMA CA 91752	ENE	0.06 / 292.53	4
International Vitamin Corporation	11010 HOPKINS ST #B MIRA LOMA CA 91752	E	0.06 / 336.18	5

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Home Depot Store #5645	11650 VENTURE DR MIRA LOMA CA 91752	N	0.09 / 477.19	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CPS Express, Inc	3401 ETIWANDA AVE # 711 MIRA LOMA CA 91752	E	0.00 / 0.00	1
NORTH AMERICAN CAR CORPORATION	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	E	0.00 / 0.00	1
Hanes Industries	3401 ETIWANDA AVE BUILDING 1011 UNITS C&D JURUPA VALLEY CA 91752	E	0.00 / 0.00	1
O'Neil Tube & Reel	3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	E	0.00 / 0.00	1
Triways, Inc	11201 IBERIA ST #B MIRA LOMA CA 91752	ESE	0.07 / 361.88	7
HD Pro Location #3256	11600 IBERIA ST JURUPA VALLEY CA 91752	SE	0.08 / 430.39	8
Mobile Modular	11450 MISSION BLVD MIRA LOMA CA 91752	SSW	0.12 / 619.96	15

EMISSIONS - Toxic Pollutant Emissions Facilities

A search of the EMISSIONS database, dated Dec 31, 2018 has found that there are 11 EMISSIONS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FLYERS ENERGY, LLC.	11074 INLAND AVE MIRA LOMA CA 91752	ENE	0.13 / 688.25	17
CONSOLIDATED FREIGHTWAYS	11888 MISSION BLVD MIRA LOMA CA 91752	W	0.14 / 738.66	18

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
JON RICHARDS COMPANY	11210 INLAND AVE MIRA LOMA CA 91752	NNE	0.21 / 1,123.72	29

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SPACE CENTER MIRA LOMA, INC	3401 ETIWANDA AVE, BLDG 1325 MIRA LOMA CA 91752	E	0.00 / 0.00	1
G E RAILCAR REPAIR	3401 ETIWANDA AV MIRA LOMA CA 91752	E	0.00 / 0.00	1
CAL CUSTOM DESIGN	3401 ETIWANDA AVE, BLDG #811-A MIRA LOMA CA 91752	E	0.00 / 0.00	1
JURUPA COMMUNITY SERVICES DIST	3401 ETIWANDA AVE MIRA LOMA CA 91752	E	0.00 / 0.00	1
JURUPA COMMUNITY SERVICES DIST	3401 ETIWANDA AV MIRA LOMA CA 91752	E	0.00 / 0.00	1
CAL CUSTOM DESIGN, INC RED-E-K	3401 ETIWANDA AV, BLDG 811A MIRA LOMA CA 91752	E	0.00 / 0.00	1
PROPAK LOGISTICS, INC. REVERSE LOGISTICS	11555 IBERIA ST MIRA LOMA CA 91752	SSE	0.12 / 644.66	16
ETIWANDA GAS MART	3710 ETIWANDA AVE MIRA LOMA CA 91752	ESE	0.23 / 1,233.00	31

County

RIVERSIDE HWG - Riverside County - Hazardous Waste Generator Sites List

A search of the RIVERSIDE HWG database, dated Mar 23, 2021 has found that there are 4 RIVERSIDE HWG site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	0.06 / 336.18	5

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Home Depot Store #5645	11650 Venture Dr Jurupa Valley CA 91752	N	0.09 / 477.19	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
O'Neil Tube & Reel	3401 Etiwanda Ave #811C Jurupa Valley CA 91752	E	0.00 / 0.00	1
Mobile Modular	11450 Mission Blvd Jurupa Valley CA 91752	SSW	0.12 / 619.96	15


RIVERSIDE HZH - Riverside County - Disclosure Facility List

A search of the RIVERSIDE HZH database, dated Nov 24, 2020 has found that there are 10 RIVERSIDE HZH site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
K-Swiss Sport Shoes Inc.	3177 Space Ctr Jurupa Valley CA 91752	ENE	0.05 / 269.00	3
Gerard Daniel Worldwide	3265 Progress Cir Jurupa Valley CA 91752	ENE	0.06 / 292.53	4
International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	0.06 / 336.18	5
Home Depot Distribution IDC #5645	11650 Venture Dr Jurupa Valley CA 91752	N	0.09 / 477.19	9

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CPS Express, Inc	3401 Etiwanda Ave Bldg #711 Jurupa Valley CA 91752	E	0.00 / 0.00	1
Jurupa Community Svcs Dist(Site 22)	3423 Space Center Ct Jurupa Valley CA 91752	E	0.00 / 0.00	1
O'Neil Tube & Reel	3401 Etiwanda Ave #811C Jurupa Valley CA 91752	E	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Hanes Industries	3401 Etiwanda Ave Bldg 1011 Jurupa Valley CA 91752	E	0.00 / 0.00	1
Triways, Inc	11201 Iberia St #B Jurupa Valley CA 91752	ESE	0.07 / 361.88	7
Jurupa Community Svcs Dist(Site 25)	11561 Iberia St Jurupa Valley CA 91752	SE	0.10 / 515.85	12



Map: 1.0 Mile Radius

Order Number: 21032900155


Address: 3401 Etiwanda Ave - Bldg 1011, Jurupa Valley, CA

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- County Boundary
- Rails
- Major Highways
- Major Highways Ramps
- Major Roads
- Major Roads Ramps
- Secondary Roads
- Secondary Roads Ramps
- Local Roads and Ramps
- State Boundary
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- State Brownfield Sites
- State Brownfield Areas
- State Superfund Areas:Dept. of Defense
- State Superfund Areas:NPL
- WQARF Areas
- Federal Lands: Dept. of Defense (owned/administered areas)

Source: © 2016 ESRI

© ERIS Information Inc.



Map: 0.5 Mile Radius

Order Number: 21032900155


Address: 3401 Etiwanda Ave - Bldg 1011, Jurupa Valley, CA

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- County Boundary
- Rails
- Major Highways
- Major Highways Ramps
- Major Roads
- Major Roads Ramps
- Secondary Roads
- Secondary Roads Ramps
- Local Roads and Ramps
- State Boundary
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- State Brownfield Sites
- State Brownfield Areas
- State Superfund Areas:Dept. of Defense
- State Superfund Areas:NPL
- WQARF Areas
- Federal Lands: Dept. of Defense (owned/administered areas)

Source: © 2016 ESRI

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 21032900155

Address: 3401 Etiwanda Ave - Bldg 1011, Jurupa Valley, CA

ENVIRONMENTAL RISK INFORMATION SERVICES

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- County Boundary
- Rails
- Major Highways
- Major Highways Ramps
- Major Roads
- Major Roads Ramps
- Secondary Roads
- Secondary Roads Ramps
- Local Roads and Ramps
- State Boundary
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- State Brownfield Sites
- State Brownfield Areas
- State Superfund Areas:Dept. of Defense
- State Superfund Areas:NPL
- WQARF Areas
- Federal Lands: Dept. of Defense (owned/administered areas)

Source: © 2016 ESRI

© ERIS Information Inc.



Aerial **Year: 2019**


Address: 3401 Etiwanda Ave - Bldg 1011, Jurupa Valley, CA

Order Number: 21032900155

ERIS ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Inc.

Source: ESRI World Imagery



Topographic Map

Year: 2015

Address: 3401 Etiwanda Ave - Bldg 1011, CA

Quadrangle(s): Guasti, CA; Fontana, CA; Corona North, CA

Source: USGS Topographic Map

Order Number: 21032900155

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 89	E	0.00 / 0.00	814.60 / -3	PROKO INDUSTRIES, INC. 3401 ETIWANDA AVE. BLDG. 931-D MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID: CAD000625780
Gen Status Universe: No Report
Contact Name: ENVIRONMENTAL MANAGER
Contact Address: 3401 ETIWANDA AVE. BLDG. 931-D , , MIRA LOMA , CA, 91752 , US
Contact Phone No and Ext: 714-681-4141
Contact Email:
Contact Country: US
County Name: RIVERSIDE
EPA Region: 09
Land Type: Other
Receive Date: 19800814
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19800814
Handler Name: PROKO INDUSTRIES, INC.
Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Street No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NOT REQUIRED	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	ME
Phone:	415-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NOT REQUIRED	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	ME
Phone:	415-555-1212	**Country:**	
Source Type:	Notification	**Zip Code:**	99999

1	2 of 89	E	0.00 / 0.00	814.60 / -3	NORTH AMERICAN CAR CORPORATION 3401 ETIWANDA AVENUE MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID:	CAD091927095
Gen Status Universe:	No Report
Contact Name:	
Contact Address:	US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	
Receive Date:	19930913
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Jan, 2021.

Evaluation Details

Evaluation Start Date:	19910723
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State Contractor/Grantee
Evaluation Start Date:	19910528
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State Contractor/Grantee
Evaluation Start Date:	19910411
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State Contractor/Grantee

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No

Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19800818
Handler Name:	NORTH AMERICAN CAR CORPORATION
Source Type:	Notification
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19930913
Handler Name:	NORTH AMERICAN CAR CORPORATION
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19940407
Handler Name:	GE RAILCAR REPAIR
Source Type:	Annual/Biennial Report
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	222 S. RIVERSIDE PLAZA
Name:	NORTH AMERICAN CAR CORPORATION	***Street 2:***	
Date Became Current:		***City:***	CITY NOT REPORTED
Date Ended Current:		***State:***	IL
Phone:	312-648-4000	***Country:***	
Source Type:	Implementer	***Zip Code:***	99999

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	222 S. RIVERSIDE PLAZA
Name:	NORTH AMERICAN CAR CORPORATION	***Street 2:***	
Date Became Current:		***City:***	CHICAGO
Date Ended Current:		***State:***	IL
Phone:	312-648-4000	***Country:***	
Source Type:	Notification	***Zip Code:***	60606

Historical Handler Details

Receive Dt:	19940407
Generator Code Description:	Large Quantity Generator
Handler Name:	GE RAILCAR REPAIR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19800818
Generator Code Description: Large Quantity Generator
Handler Name: NORTH AMERICAN CAR CORPORATION

---

1 | **3 of 89** | **E** | **0.00 / 0.00** | **814.60 / -3** | **G E RAILCAR REPAIR**
3401 ETIWANDA AVENUE
MIRA LOMA CA 91752-1128 | **FINDS/FRS**

Registry ID: 110012430173
FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 01-JUN-17
Interest Types: HAZARDOUS AIR POLLUTANT MAJOR
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110012430173
Program Acronyms:

EIS:2355911

---

1 | **4 of 89** | **E** | **0.00 / 0.00** | **814.60 / -3** | **NORTH AMERICAN CAR CORPORATION**
3401 ETIWANDA AVENUE
MIRA LOMA CA 91752 | **FINDS/FRS**

Registry ID: 110009532194
FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 29-DEC-14
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110009532194
Program Acronyms:

RCRAINFO:CAD091927095

1	5 of 89	E	0.00 / 0.00	814.60 / -3	**PROKO INDUSTRIES, INC.** **3401 ETIWANDA AVE. BLDG. 931-D** **MIRA LOMA CA 91752**	FINDS/FRS

Registry ID: 110009527388
FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 29-DEC-14
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110009527388
Program Acronyms:

RCRAINFO:CAD000625780

1	6 of 89	E	0.00 / 0.00	814.60 / -3	**CALIFORNIA CUSTOM DESIGN** **3401 ETIWANDA AVE BLDG 811A** **MIRA LOMA CA 91752**	FINDS/FRS

Registry ID: 110009552705

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 26-JAN-12
Interest Types: SQG
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110009552705
Program Acronyms:

RCRAINFO:CAR000014233

1	***7 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***Space Center Mira Loma, Inc.*** ***3401 Etiwanda Ave*** ***Mira Loma CA***	***RIVERSIDE LOP***

Site ID: 90640
Status Code: 9
Status Desc: CLOSED/ACTION COMPLETED
Case Type Code: U
Case Type Desc: UNDEFINED
Closed Code: Y
Closed Desc: CLOSED SITE
Employee: Whitehead

1	***8 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***CPS Express, Inc*** ***3401 Etiwanda Ave # 1011A*** ***Mira Loma CA 91752***	***DELISTED COUNTY***

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

1	***9 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***Jurupa Community Svcs Dist(Site 22)*** ***3423 Space Center Ct*** ***Jurupa Valley CA 91752***	***RIVERSIDE HZH***

1	***10 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***O'Neil Tube & Reel*** ***3401 Etiwanda Ave #811C***	***RIVERSIDE HZH***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Jurupa Valley CA 91752	
1	11 of 89	E	0.00 / 0.00	814.60 / -3	O'Neil Tube & Reel 3401 Etiwanda Ave #811C Jurupa Valley CA 91752	RIVERSIDE HWG
1	12 of 89	E	0.00 / 0.00	814.60 / -3	SPACE CENTER MIRA LOMA 3401 ETIWANDA AVE MIRA LOMA CA 91752	LUST

Global ID: T0606500200
Status: COMPLETED - CASE CLOSED
Status Date: 1/2/1991
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites from GeoTracker Search; LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download
County: RIVERSIDE
Latitude: 34.0261256
Longitude: -117.5244479

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail(as Nov 16 2020)

RB Case No: 083301605T
Local Case No: 90640
Begin Date: 6/22/1990
Lead Agency: RIVERSIDE COUNTY LOP
Local Agency: RIVERSIDE COUNTY LOP
CUF Case: NO
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
DWR GW Subbasin Name: Upper Santa Ana Valley - Chino (8-002.01)
Disadvantaged Community:
Site History:
Potential COC: Gasoline
How Discovered: Tank Closure
Stop Method:
Stop Description:
Case Worker: RIV
File Location:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity(as Nov 16 2020)

Action Type: Other
Date : 7/19/1990
Action: Leak Reported

Action Type: Other
Date : 6/22/1990
Action: Leak Discovery

Action Type: Other
Date : 6/22/1990
Action: Leak Stopped

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts(as Nov 16 2020)

Contact Type: Local Agency Caseworker
Contact Name: Riverside County LOP
City: RIVERSIDE
Organization Name: RIVERSIDE COUNTY LOP
Address: 3880 LEMON ST SUITE 200
Email:
Phone No: 9519558980

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History(as Nov 16 2020)

Status: Completed - Case Closed
Status Date: 1/2/1991

Status: Open - Site Assessment
Status Date: 7/30/1990

Status: Open - Case Begin Date
Status Date: 6/22/1990

LUST Sites from GeoTracker Search - Regulatory Profile (as of Oct 06, 2020)

Site Facility Name: SPACE CENTER MIRA LOMA
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
File Location:
Potential COC: GASOLINE
Facility Type:
Composting Method:
Address: 3401 ETIWANDA AVE
City: MIRA LOMA
Zip: 91752
County: RIVERSIDE
CUF Claim:
Designated Beneficial Use: MUN, AGR, IND, PROC
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0606500200
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/2/1991
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0606500200&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Santa Ana Valley - Chino (8-002.01)
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: RIVERSIDE COUNTY LOP (LEAD) - CASE #: 90640
CASEWORKER: Riverside County LOP
SANTA ANA RWQCB (REGION 8) - CASE #: 083301605T
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History (as of Oct 06, 2020)

Status: Completed - Case Closed
Date : 1/2/1991

Status: Open - Site Assessment
Date : 7/30/1990

Status: Open - Case Begin Date
Date : 6/22/1990

LUST Sites from GeoTracker Search - Regulatory Activities (as of Oct 06, 2020)

Action Type: Leak Action
Action Date: 7/19/1990
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 6/22/1990
Received Issue Date:
Action: Leak Discovery

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 6/22/1990
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	13 of 89	E	0.00 / 0.00	814.60 / -3	NORTH AMERICAN CAR CORPORATION 3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	ENVIROSTOR

Estor/EPA ID: CAD091927095
Site Code:
Nat Priority List:
APN:
Census Tract:
Site Type: PROTECTIVE FILER
Address Description: 3401 ETIWANDA AVENUE
Office:
Special Program:
Funding:
Cleanup Status:
Cleanup Oversight Agencies:
School District:
Past Use that Caused Contam:
Potential Media Affected:
Potential Contamin of Concern:

Assembly District: 60
Senate District: 31
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: RIVERSIDE
Latitude: 34.024496
Longitude: -117.525583
Acres:
Supervisor:

Site History:

NO FACILITY HISTORY HAS BEEN ENTERED FOR THIS SITE

Status: PROTECTIVE FILER
A2 Program Type: HAZ WASTE
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CAD091927095

Permit Units - Completed Activities

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

Units Undergoing Closure

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	14 of 89	E	0.00 / 0.00	814.60 / -3	NORTH AMERICAN CAR CORPORATION 3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	HWP

Estor/EPA ID: CAD091927095
Site Code:

Permit Renewal Lead:
Project Manager:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Nat Priority List:
Acres:
Special Program:
Funding:
Assembly District: 60
Senate District: 31
School District:
APN:
Cleanup Status:
Cleanup Oversight Agencies:
Site Type: PROTECTIVE FILER
Office:
Past Use that Caused Contam:
Potential Media Affected:
Potential Contamin of Concern:
Supervisor:
Public Partici Spclst:
Census Tract:
County: RIVERSIDE
Latitude: 34.024496
Longitude: -117.525583

Site History:

NO FACILITY HISTORY HAS BEEN ENTERED FOR THIS SITE

Status: PROTECTIVE FILER
Program Type: HAZ WASTE
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CAD091927095

Permit Units - Completed Activities

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

Units Undergoing Closure

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

1	***15 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***Riverside County Fire 3401 Etiwanda Ave. Suite 811 D Mira Loma CA***	***CHMIRS***

Control No:
Notified Date Time:
County: Riverside County
URL:
Notified Date: 7/17/200402:10:32 AM
Year: 2004

1	***16 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***CAMPBELL OIL COMPANY 3401 ETIWANDA AVE 502 MIRA LOMA CA 91752***	***HHSS***

County:
Pdf File Url: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0001f9b7.pdf

---

1	***17 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***CPS Express, Inc 3401 Etiwanda Ave Bldg #711 Jurupa Valley CA 91752***	***RIVERSIDE HZH***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	18 of 89	E	0.00 / 0.00	814.60 / -3	1X SPACE CTR MIRA LOMA INC 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code:
NAICS Code:
EPA ID: cac002413303
Create Date: 3/15/2002
Fac Act Ind: No
Inact Date: 2/19/2004
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 ETIWANDA AVE
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917520000
Region Code: 4
Owner Name: Space Ctr
Owner Addr 1: 3401 ETIWANDA AVE
Owner Addr 2:
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 917520000
Owner Phone: 9096855271

Contact Information
-- --
Contact Name: David Johnson
Street Address 1: 3401 ETIWANDA AVE
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 917520000
Phone: 9098628300
-- --

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	19 of 89	E	0.00 / 0.00	814.60 / -3	CPS EXPRESS INC 3401 E ETIWANDA ST MIRA LOMA CA 91752	HAZNET

SIC Code:
NAICS Code:
EPA ID: CAC002567425
Create Date: 7/9/2003
Fac Act Ind: No
Inact Date: 1/6/2004
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 E ETIWANDA ST BLDG 1011
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 91752
Region Code: 4
Owner Name: CPS EXPRESS INC
Owner Addr 1: 3401 E ETIWANDA ST BLDG 1011
Owner Addr 2:
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 91752
Owner Phone: 9096851041

Contact Information
-- --
Contact Name: DON BULLOCK
Street Address 1: 3401 E ETIWANDA ST BLDG 1011
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 91752
Phone: 9096851041
-- --
-- --
Tanner Information
-- --
Generator EPA ID: CAC002567425
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD099452708
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 221
State Waste Code Desc.: Waste oil and mixed oil
Method Code: H039
Method Description: OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RECOVERY ECT
Tons: 1.14
Year: 2011
-- --
Generator EPA ID: CAC002567425
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAT080013352
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 741
State Waste Code Desc.: Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Code: R01
Method Description: Recycler
Tons: 0.3336
Year: 2003
-- --

1	20 of 89	E	0.00 / 0.00	814.60 / -3	SWIFT TRANSPORTATION 3401 SPACE CENTER ST MIRA LOMA CA 000000000	HAZNET

SIC Code:
NAICS Code:
EPA ID: CAC002174369
Create Date: 3/16/1999
Fac Act Ind: No
Inact Date: 10/25/2000
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: PO BOX 29243
Mailing Addr 2:
Owner Fax:

Mailing City: PHOENIX
Mailing State: AZ
Mailing Zip: 850389243
Region Code: 4
Owner Name: SWIFT TRANSPORTATION
Owner Addr 1: PO BOX 29243
Owner Addr 2:
Owner City: PHOENIX
Owner State: AZ
Owner Zip: 850389243
Owner Phone: 8002794382

Contact Information
-- --
Contact Name: FRED BALEN
Street Address 1: PO BOX 29243
Street Address 2:
City: PHOENIX
State: AZ
Zip: 850389243
Phone: 8002794382
-- --
-- --
Tanner Information
-- --
Generator EPA ID: CAC002174369
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD000088252
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 611
State Waste Code Desc.: Contaminated soil from site clean-up
Method Code: H01
Method Description: Transfer station
Tons: 16.856
Year: 1996
-- --
Generator EPA ID: CAC002174369
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD000088252
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 611

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	H01
Method Description:	Transfer station
Tons:	8.428
Year:	1999
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	21 of 89	E	0.00 / 0.00	814.60 / -3	CHEMSTAR 3401 ETIWANDA AVE UNIT 911-D MIRA LOMA CA 91752	HAZNET

SIC Code:	3087	**Mailing City:**	CORONA
NAICS Code:	325991	**Mailing State:**	CA
EPA ID:	CAL000278033	**Mailing Zip:**	92881
Create Date:	1/12/2004 11:49:50 AM	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	RICK KULJIAN
Inact Date:	6/22/2006	**Owner Addr 1:**	1148 CALIFORNIA AVE
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	CORONA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	1148 CALIFORNIA AVE	**Owner Zip:**	92881
Mailing Addr 2:		**Owner Phone:**	9517356522
Owner Fax:			

Contact Information	
--	--
Contact Name:	RICK KULJIAN
Street Address 1:	1148 CALIFORNIA AVE
Street Address 2:	
City:	CORONA
State:	CA
Zip:	92881
Phone:	9097356522
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAL000278033
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	134
State Waste Code Desc.:	Aqueous solution with total organic residues less than 10 percent
Method Code:	R01
Method Description:	Recycler
Tons:	0.1092
Year:	2005
--	--
Generator EPA ID:	CAL000278033
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	AZR000002428
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	8.5
Year:	2004
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	22 of 89	E	0.00 / 0.00	814.60 / -3	CPS EXPRESS CORPORATION 3401 ETIWANDA AVE 621-B MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC002320369	**Mailing Zip:**	617520000
Create Date:	9/13/2000	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	CPS EXPRESS CORPORATION
Inact Date:	6/11/2001	**Owner Addr 1:**	PO BOX 248
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	PO BOX 248	**Owner Zip:**	617520000
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	JIM SMERBER/ MGR
Street Address 1:	PO BOX 248
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	617520000
Phone:	9092371606
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAC002320369
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	223
State Waste Code Desc.:	Unspecified oil-containing waste
Method Code:	R01
Method Description:	Recycler
Tons:	2.2935
Year:	2000
--	--
Generator EPA ID:	CAC002320369
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	T01
Method Description:	Treatment, tank
Tons:	0.187
Year:	2000
--	--
Generator EPA ID:	CAC002320369
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.7
Year:	2000
--	--

1	23 of 89	E	0.00 /	814.60 /	O'NEILL TUBE & REEL	HAZNET

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
			0.00	-3	3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	

SIC Code: 2671,9999
NAICS Code: 326112,99999
EPA ID: CAL000348808
Create Date: 12/17/2009
Fac Act Ind: Yes
Inact Date:
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 ETIWANDA AVE STE 811C
Mailing Addr 2:
Owner Fax: 0000000000

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917520000
Region Code: 4
Owner Name: REMY O'NEILL
Owner Addr 1: 6135 CAVALLERI RD
Owner Addr 2:
Owner City: MALIBU
Owner State: CA
Owner Zip: 902654015
Owner Phone: 3104579107

Contact Information
-- --
Contact Name: TORI LAYNE
Street Address 1: 3401 ETIWANDA AVE STE 811C
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 91752
Phone: 9513608600
-- --
-- --

Tanner Information
-- --
Generator EPA ID: CAL000348808
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD097030993
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 352
State Waste Code Desc.: Other organic solids
Method Code: H141
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons: 0.15
Year: 2012
-- --
Generator EPA ID: CAL000348808
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD097030993
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 352
State Waste Code Desc.: Other organic solids
Method Code: H141
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons: 0.05
Year: 2013
-- --
Generator EPA ID: CAL000348808
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD097030993
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 352
State Waste Code Desc.: Other organic solids
Method Code: H141
Method Description: STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons: 0.15

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Year:		2015				
--		--				

1 | 24 of 89 | E | 0.00 / 0.00 | 814.60 / -3 | ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION 3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 917521128 | HAZNET

SIC Code:	4212	Mailing City:	JURUPA VALLEY
NAICS Code:	562119	Mailing State:	CA
EPA ID:	CAL000408792	Mailing Zip:	917521128
Create Date:	7/27/2015 11:04:53 AM	Region Code:	4
Fac Act Ind:	Yes	Owner Name:	TODD GILENO
Inact Date:		Owner Addr 1:	3401 ETIWANDA AVE BLDG 731D
County Code:	33	Owner Addr 2:	
County Name:	Riverside	Owner City:	JURUPA VALLEY
Mail Name:		Owner State:	CA
Mailing Addr 1:	3401 ETIWANDA AVE BLDG 731D	Owner Zip:	917521128
Mailing Addr 2:		Owner Phone:	9513607721
Owner Fax:	9513607700		

Contact Information

--	--
Contact Name:	TRACY PFAFF
Street Address 1:	3401 ETIWANDA AVE BLDG 731D
Street Address 2:	
City:	JURUPA VALLEY
State:	CA
Zip:	917521128
Phone:	9513607721
--	--

1 | 25 of 89 | E | 0.00 / 0.00 | 814.60 / -3 | SPACE CENTER MIRA LOMA 3401 ETIWANDA AVE BLDG 811D MIRA LOMA CA 917521128 | HAZNET

SIC Code:		Mailing City:	MIRA LOMA
NAICS Code:		Mailing State:	CA
EPA ID:	CAC002688125	Mailing Zip:	917520000
Create Date:	3/13/2012	Region Code:	4
Fac Act Ind:	No	Owner Name:	SPACE CENTER MIRA LOMA
Inact Date:	9/10/2012	Owner Addr 1:	3401 ETIWANDA AVE
County Code:	33	Owner Addr 2:	
County Name:	Riverside	Owner City:	MIRA LOMA
Mail Name:		Owner State:	CA
Mailing Addr 1:	3401 ETIWANDA AVE	Owner Zip:	917521128
Mailing Addr 2:		Owner Phone:	9516855221
Owner Fax:			

Contact Information

--	--
Contact Name:	PATTY JETT
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	917521128
Phone:	9516855221
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	TXD077603371
TSD County Code:	99

TSD County:	Unknown
State Waste Code:	213
State Waste Code Desc.:	Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Method Code:	H061
Method Description:	FUEL BLENDING PRIOR TO ENERGY RECOVERY AT ANOTHER SITE
Tons:	0.075
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	TXD077603371
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	342
State Waste Code Desc.:	Organic liquids with metals (see 121)
Method Code:	H061
Method Description:	FUEL BLENDING PRIOR TO ENERGY RECOVERY AT ANOTHER SITE
Tons:	0.025
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H039
Method Description:	OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT
Tons:	0.075
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	TXD077603371
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	491
State Waste Code Desc.:	Unspecified sludge waste
Method Code:	H061
Method Description:	FUEL BLENDING PRIOR TO ENERGY RECOVERY AT ANOTHER SITE
Tons:	0.25
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	541
State Waste Code Desc.:	Photochemicals/photoprocessing waste
Method Code:	H039
Method Description:	OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT
Tons:	0.02
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	541

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State Waste Code Desc.:	Photochemicals/photoprocessing waste
Method Code:	H132
Method Description:	LANDFILL OR SURFACE IMPOUNDMENT THAT WILL BE CLOSED AS LANDFILL(TO INCLUDE ON-SITE TREATMENT AND/OR STABILIZATION)
Tons:	0.01
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	TXD077603371
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	541
State Waste Code Desc.:	Photochemicals/photoprocessing waste
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.075
Year:	2012
--	--
Generator EPA ID:	CAC002688125
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	
State Waste Code Desc.:	
Method Code:	H039
Method Description:	OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT
Tons:	0.025
Year:	2012
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	26 of 89	E	0.00 / 0.00	814.60 / -3	**C CONSTRUCTION INC DBA BMC WEST BUILDING MATERIALS** **3401 ETIWANDA AVE STE 831C** **MIRA LOMA CA 917521115**	HAZNET

SIC Code:	8742	**Mailing City:**	BOISE
NAICS Code:	541614	**Mailing State:**	ID
EPA ID:	CAL000336775	**Mailing Zip:**	837070106
Create Date:	9/26/2008 2:22:47 PM	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	C CONSTRUCTION INC
Inact Date:	4/23/2010	**Owner Addr 1:**	3401 ETIWANDA AVE STE 831C
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	PO BOX 70006	**Owner Zip:**	917521115
Mailing Addr 2:		**Owner Phone:**	9516858838
Owner Fax:	9516814203		

Contact Information

--	--
Contact Name:	SERGIO MORA EXT 232
Street Address 1:	3401 ETIWANDA AVE STE 831C
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	917521115
Phone:	9516858838
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	27 of 89	E	0.00 / 0.00	814.60 / -3	**KEYBOARD CARRIAGE INC** **3401 ETIWANDA ST #731D**	HAZNET

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					MIRA LOMA CA 927510000	

SIC Code:	4226	**Mailing City:**	ELIZABETHTOWN
NAICS Code:	49311	**Mailing State:**	KY
EPA ID:	CAL000223453	**Mailing Zip:**	427020000
Create Date:	5/31/2001	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	KEYBOARD CARRIAGE INC
Inact Date:	6/30/2012	**Owner Addr 1:**	3401 ETIWANDA ST STE 731D
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	PO BOX 625	**Owner Zip:**	927510000
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:	0000000000		

Contact Information

--	--
Contact Name:	JOE GAY / DIRECTOR OF SAFETY
Street Address 1:	PO BOX 625
Street Address 2:	
City:	ELIZABETHTOWN
State:	KY
Zip:	427020000
Phone:	2707375797
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	28 of 89	E	0.00 / 0.00	814.60 / -3	SPACE CENTER 3401 ETIWANDA AVE MIRA LOMA CA 91752	HAZNET

SIC Code:	7538	**Mailing City:**	MIRA LOMA
NAICS Code:	811111	**Mailing State:**	CA
EPA ID:	CAL000248557	**Mailing Zip:**	917520000
Create Date:	3/22/2002 3:47:22 PM	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	SPACE CENTER
Inact Date:	6/30/2004	**Owner Addr 1:**	3401 ETIWANDA AVE LEASING OFFICE
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:	SPACE CENTER MIRA LOMA, INC	**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVENUE	**Owner Zip:**	917520000
Mailing Addr 2:		**Owner Phone:**	9096855221
Owner Fax:			

Contact Information

--	--
Contact Name:	TOM CRUIKSHANK
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	91752
Phone:	9096855221
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	133
State Waste Code Desc.:	Aqueous solution with total organic residues 10 percent or more
Method Code:	R01
Method Description:	Recycler
Tons:	0.1251
Year:	2004

--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000613927
TSD County Code:	36
TSD County:	San Bernardino
State Waste Code:	134
State Waste Code Desc.:	Aqueous solution with total organic residues less than 10 percent
Method Code:	H01
Method Description:	Transfer station
Tons:	0.0168
Year:	2002
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000613927
TSD County Code:	36
TSD County:	San Bernardino
State Waste Code:	134
State Waste Code Desc.:	Aqueous solution with total organic residues less than 10 percent
Method Code:	H01
Method Description:	Transfer station
Tons:	0.0336
Year:	2003
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.0375
Year:	2004
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	291
State Waste Code Desc.:	Latex waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.9
Year:	2004
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008302903
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.1
Year:	2004
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	1.35
Year:	2004
--	--
Generator EPA ID:	CAL000248557
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008302903
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01
Method Description:	Transfer station
Tons:	0.25
Year:	2004
--	--

1	29 of 89	E	0.00 / 0.00	814.60 / -3	**MCVEIGH TRANSPORT** **3401 ETIWANDA** **MIRA LOMA CA 917520000**	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAL000028501	**Mailing Zip:**	917520000
Create Date:	5/10/1990	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	MCVEIGH BILL
Inact Date:	11/28/1994	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	3401 ETIWANDA	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	UNDELIVERABLE SURVEY 11-28-94
Street Address 1:	94 LC
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	--
--	--

1	30 of 89	E	0.00 / 0.00	814.60 / -3	**GENERAL TELEPHONE OF CALIF** **3401 ETIWANDA AVE** **MIRA LOMA CA 917520000**	HAZNET

SIC Code:		**Mailing City:**	CHINO
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAX000225128	**Mailing Zip:**	917100000
Create Date:	3/8/1985	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	MARTY SMITH
Inact Date:	4/30/1986	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	JACKIE MCCORMICK	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	7146276326

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Fax:

Contact Information

--	--
Contact Name:	INACTIVE PER SURVEY 12-22-94
Street Address 1:	LH
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	7149834251
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	31 of 89	E	0.00 / 0.00	814.60 / -3	CARGO CATS, INC. 3401 ETIWANDA AVE MIRA LOMA CA 917521128	HAZNET

SIC Code:	9999	**Mailing City:**	MIRA LOMA
NAICS Code:	99999	**Mailing State:**	CA
EPA ID:	CAC002710470	**Mailing Zip:**	917521128
Create Date:	11/5/2012	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	JOHN ROJAS
Inact Date:	2/4/2013	**Owner Addr 1:**	3401 ETIWANDA AVE
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE	**Owner Zip:**	917521128
Mailing Addr 2:		**Owner Phone:**	9516814220
Owner Fax:			

Contact Information

--	--
Contact Name:	JOHN ROJAS
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	917521128
Phone:	9516814220
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAC002710470
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	331
State Waste Code Desc.:	Off-specification, aged or surplus organics
Method Code:	H132
Method Description:	LANDFILL OR SURFACE IMPOUNDMENT THAT WILL BE CLOSED AS LANDFILL(TO INCLUDE ON-SITE TREATMENT AND/OR STABILIZATION)
Tons:	5
Year:	2012
--	--
Generator EPA ID:	CAC002710470
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	NVT330010000
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	791
State Waste Code Desc.:	Liquids with pH <= 2
Method Code:	H039
Method Description:	OTHER RECOVERY OF RECLAMATION FOR REUSE INCLUDING ACID REGENERATION, ORGANICS RECOVERY ECT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tons:		2.085				
Year:		2012				
--		--				

1	32 of 89	E	0.00 / 0.00	814.60 / -3	**PACIFIC FABRIC REELS INC** **3401 ETIWANDA AVE #811C** **MIRA LOMA CA 917520000**	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:	3222	**Mailing State:**	CA
EPA ID:	CAL000067726	**Mailing Zip:**	917520000
Create Date:	3/24/1992	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	ONEILL REMY
Inact Date:	6/30/2004	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	3401 ETIWANDA AVE STE 811C	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	ANA DOLAR MANAGER
Street Address 1:	3401 ETIWANDA AVE 811C
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	917520000
Phone:	9096812993
--	--

1	33 of 89	E	0.00 / 0.00	814.60 / -3	**PACIFIC FABRIC REELS** **3401 ETIWANDA AVE STE 811C** **MIRA LOMA CA 917521132**	HAZNET

SIC Code:	2671	**Mailing City:**	MIRA LOMA
NAICS Code:	326112	**Mailing State:**	CA
EPA ID:	CAL000299006	**Mailing Zip:**	917521132
Create Date:	10/3/2005 9:18:33 AM	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	BRYAN COGLEY
Inact Date:	6/30/2009	**Owner Addr 1:**	9200 MILLKEN AVE STE 6209
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	RANCHO CUCAMONGA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE STE 811C	**Owner Zip:**	917300000
Mailing Addr 2:		**Owner Phone:**	9099804468
Owner Fax:			

Contact Information

--	--
Contact Name:	BRYAN COGLEY
Street Address 1:	3401 ETIWANDA AVE STE 811C
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	917521132
Phone:	9516812993
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAL000299006
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD097030993
TSD County Code:	19

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.1
Year:	2006
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	34 of 89	E	0.00 / 0.00	814.60 / -3	CARGO CATS 3401 ETIWANDA AVE STE 8-11A MIRA LOMA CA 91752	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC002579910	**Mailing Zip:**	91752
Create Date:	7/16/2004	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	CARGO CATS
Inact Date:	3/7/2005	**Owner Addr 1:**	3401 ETIWANDA AVE STE 8-11A
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE STE 8-11A	**Owner Zip:**	91752
Mailing Addr 2:		**Owner Phone:**	9096814220
Owner Fax:			

Contact Information	
--	--
Contact Name:	SANDY ROJAS
Street Address 1:	3401 ETIWANDA AVE STE 8-11A
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	91752
Phone:	9096814220
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC002579910
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.25
Year:	2004
--	--
Generator EPA ID:	CAC002579910
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD028409019
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.45
Year:	2004
--	--
Generator EPA ID:	CAC002579910
Generator County Code:	33

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.5
Year:	2004
--	--
Generator EPA ID:	CAC002579910
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	791
State Waste Code Desc.:	Liquids with pH <= 2
Method Code:	R01
Method Description:	Recycler
Tons:	0.0834
Year:	2004
--	--

1	***35 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***PROKO INDUSTRIES, INC.*** ***3401 ETIWANDA AVE. BLDG. 931-D*** ***MIRA LOMA CA 917520000***	***HAZNET***

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAD000625780	**Mailing Zip:**	917521128
Create Date:	7/23/1982	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	RPM, INC.
Inact Date:	6/30/1998	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	3401 ETIWANDA AVE BLDG 931-D	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	--
Street Address 1:	INACT PER NONDEL 98VQ FINAL
Street Address 2:	NOTICE - CR
City:	--
State:	99
Zip:	--
Phone:	--
--	--

1	***36 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***1X BORDEN TRUCKING INC*** ***3401 ETIWANDA AVE, BLDG 911D*** ***MIRA LOMA CA 917520000***	***HAZNET***

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC000621864	**Mailing Zip:**	917520000
Create Date:	5/22/1991	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	BORDEN TRUCKING INC
Inact Date:	10/25/2000	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Mailing Addr 1:	--	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	LANCE CANSDALE/VP
Street Address 1:	--
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	7146851548
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	37 of 89	E	0.00 / 0.00	814.60 / -3	NORTH AMERICAN CAR CORPORATION 3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	HAZNET

SIC Code:		**Mailing City:**	CHICAGO
NAICS Code:	3339	**Mailing State:**	IL
EPA ID:	CAD091927095	**Mailing Zip:**	606030000
Create Date:	7/23/1982	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	NORTH AMERICAN CAR CORPORATION
Inact Date:	12/31/1899	**Owner Addr 1:**	222 S. RIVERSIDE PLAZA
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	CHICAGO
Mail Name:		**Owner State:**	IL
Mailing Addr 1:	33 WEST MONROE	**Owner Zip:**	606060000
Mailing Addr 2:		**Owner Phone:**	3126484000
Owner Fax:			

Contact Information

--	--
Contact Name:	NORTH AMERICAN CAR CORPORATION
Street Address 1:	222 S. RIVERSIDE PLAZA
Street Address 2:	
City:	CHICAGO
State:	IL
Zip:	606060000
Phone:	3126484000
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	172
State Waste Code Desc.:	Metal dust (see 121) and machining waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	200.5864
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	D80

Method Description:	Disposal, landfill
Tons:	27.8124
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008302903
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	212
State Waste Code Desc.:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Method Code:	R01
Method Description:	Recycler
Tons:	2.1417
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008302903
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	R01
Method Description:	Recycler
Tons:	1.0336
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	513
State Waste Code Desc.:	Empty containers less than 30 gallons
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	8.428
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	611
State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	51.4108
Year:	1993
--	--
Generator EPA ID:	CAD091927095
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	611
State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	
Method Description:	
Tons:	9.2708
Year:	1993
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	38 of 89	E	0.00 / 0.00	814.60 / -3	CALIFORNIA CUSTOM DESIGN 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code:
NAICS Code:
EPA ID: CAD980815468
Create Date: 5/24/1983
Fac Act Ind: No
Inact Date: 6/30/1998
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 ETIWANDA AVE BLDG 811A
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917521128
Region Code: 4
Owner Name: PREDELIVERY SVC CORP
Owner Addr 1: 3401 ETIWANDA/MIRA LOMA SPACE
Owner Addr 2:
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 917520000
Owner Phone: 7146850151

Contact Information
-- --
Contact Name: EDWARD N SILVA
Street Address 1: INACTIVE PER VQ98 - BMI
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 917520000
Phone: 9096850151
-- --
-- --
Tanner Information
-- --
Generator EPA ID: CAD980815468
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD008252405
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: ***
State Waste Code Desc.: Invalid waste code
Method Code: R01
Method Description: Recycler
Tons: 0.1334
Year: 1996
-- --
Generator EPA ID: CAD980815468
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD008252405
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 214
State Waste Code Desc.: Unspecified solvent mixture
Method Code: R01
Method Description: Recycler
Tons: 2.574
Year: 1993
-- --
Generator EPA ID: CAD980815468
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD008252405
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 214
State Waste Code Desc.: Unspecified solvent mixture
Method Code: R01
Method Description: Recycler
Tons: 2.3076

Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.234
Year:	1995
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	R01
Method Description:	Recycler
Tons:	1.2996
Year:	1996
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.9108
Year:	1997
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	
Method Description:	
Tons:	0.288
Year:	1993
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	
Method Description:	
Tons:	0.198
Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33

Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	331
State Waste Code Desc.:	Off-specification, aged or surplus organics
Method Code:	R01
Method Description:	Recycler
Tons:	2.277
Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.663
Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008302903
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	461
State Waste Code Desc.:	Paint sludge
Method Code:	R01
Method Description:	Recycler
Tons:	1.6054
Year:	1995
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080022148
TSD County Code:	36
TSD County:	San Bernardino
State Waste Code:	791
State Waste Code Desc.:	Liquids with pH <= 2
Method Code:	H01
Method Description:	Transfer station
Tons:	0.0208
Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	
State Waste Code Desc.:	
Method Code:	R01
Method Description:	Recycler
Tons:	0
Year:	1994
--	--
Generator EPA ID:	CAD980815468
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD008252405
TSD County Code:	19
TSD County:	Los Angeles

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State Waste Code:
State Waste Code Desc.:
Method Code: R01
Method Description: Recycler
Tons: 0
Year: 1997
-- --

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	39 of 89	E	0.00 / 0.00	814.60 / -3	BORDEN TRUCKING INC DBA BORDEN LOGISTICS 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code: 4214
NAICS Code: 48411
EPA ID: CAL000057014
Create Date: 7/22/1994
Fac Act Ind: No
Inact Date: 6/30/2013
County Code: 33
County Name: Riverside
Mail Name: SP CTR BLDG 911D
Mailing Addr 1: 3810 WACKER DR
Mailing Addr 2:
Owner Fax: 0000000000

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917520000
Region Code: 4
Owner Name: BORDEN TRUCKING INC
Owner Addr 1: 3810 WACKER DR
Owner Addr 2:
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 917520000
Owner Phone: 9096851548

Contact Information
-- --
Contact Name: ANTHONY STEEN-PRESIDENT
Street Address 1: 3810 WACKER DR
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 917520000
Phone: 9516851548
-- --

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	40 of 89	E	0.00 / 0.00	814.60 / -3	DISTRIBUTION LOGISTICS MNGMNT INC 3401 ETIWANDA AVE BLDG 831 MIRA LOMA CA 917520000	HAZNET

SIC Code:
NAICS Code: 4841
EPA ID: CAL000220952
Create Date: 3/20/2000
Fac Act Ind: No
Inact Date: 6/30/2002
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: PO BOX 335
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917520000
Region Code: 4
Owner Name: DISTRIBUTION LOGISTICS MNT INC
Owner Addr 1: PO BOX 335
Owner Addr 2:
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 917520000
Owner Phone: 9096858838

Contact Information
-- --
Contact Name: GREG HAYS-GENERAL MGR
Street Address 1: --
Street Address 2:
City: MIRA LOMA
State: CA
Zip: 917520000
Phone: 9096858838
-- --
-- --
Tanner Information

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

--	--
Generator EPA ID:	CAL000220952
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT000613927
TSD County Code:	36
TSD County:	San Bernardino
State Waste Code:	134
State Waste Code Desc.:	Aqueous solution with total organic residues less than 10 percent
Method Code:	H01
Method Description:	Transfer station
Tons:	0.0672
Year:	2001
--	--

1	41 of 89	E	0.00 / 0.00	814.60 / -3	NELSON-BALL PAPER PRODUCTS 3401 ETIWANDA AVE 931A MIRA LOMA CA 917520000	HAZNET

SIC Code:		Mailing City:	ONTARIO
NAICS Code:		Mailing State:	CA
EPA ID:	CAL000026964	Mailing Zip:	717610000
Create Date:	5/9/1990	Region Code:	4
Fac Act Ind:	No	Owner Name:	NELSON-BALL PAPER
Inact Date:	6/30/2005	Owner Addr 1:	3401 ETIWANDA AVE 931A
County Code:	33	Owner Addr 2:	
County Name:	Riverside	Owner City:	MIRA LOMA
Mail Name:		Owner State:	CA
Mailing Addr 1:	4502 E AIRPORT DRIVE	Owner Zip:	917520000
Mailing Addr 2:		Owner Phone:	7146855544
Owner Fax:			

Contact Information

--	--
Contact Name:	PETE MENESES
Street Address 1:	INACT 99VQ FINAL NOTICE - BATCH
Street Address 2:	4/11/00
City:	MIRA LOMA
State:	CA
Zip:	917520000
Phone:	7146855544
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	135
State Waste Code Desc.:	Unspecified aqueous solution
Method Code:	R01
Method Description:	Recycler
Tons:	0.882
Year:	2004
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	R01

Method Description:	Recycler
Tons:	0.836
Year:	2004
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	223
State Waste Code Desc.:	Unspecified oil-containing waste
Method Code:	R01
Method Description:	Recycler
Tons:	0.4587
Year:	2003
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	1.428
Year:	2001
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.374
Year:	2000
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.748
Year:	2002
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.748
Year:	2003
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.374
Year:	2004
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	R01
Method Description:	Recycler
Tons:	0.663
Year:	2004
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.1
Year:	2001
--	--
Generator EPA ID:	CAL000026964
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	R01
Method Description:	Recycler
Tons:	0.3
Year:	2004
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	42 of 89	E	0.00 / 0.00	814.60 / -3	SPACE CENTER 3401 ETIWANDA AVE 831D MIRA LOMA CA 917521128	HAZNET

SIC Code:	7538	**Mailing City:**	MIRA LOMA
NAICS Code:	811111	**Mailing State:**	CA
EPA ID:	CAC002713667	**Mailing Zip:**	91752
Create Date:	12/7/2012	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	SPACE CENTER
Inact Date:	3/8/2013	**Owner Addr 1:**	3401 ETIWANDA AVE
County Code:	33	**Owner Addr 2:**	LEASING OFFICE
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE	**Owner Zip:**	91752
Mailing Addr 2:	LEASING OFFICE	**Owner Phone:**	9516855221

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Fax: 9516853478

Contact Information

--	--
Contact Name:	PATTY JETT
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	LEASING OFFICE
City:	MIRA LOMA
State:	CA
Zip:	91752
Phone:	9516855221
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	43 of 89	E	0.00 / 0.00	814.60 / -3	GTE SCRAP YARD 3401 ETIWANDA MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	CHINO
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAD981393945	**Mailing Zip:**	917080000
Create Date:	4/10/1987	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	--
Inact Date:	1/1/1995	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	P O BOX 725	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	INACTIVE PER SURVEY 12-22-94
Street Address 1:	LH
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	--
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	44 of 89	E	0.00 / 0.00	814.60 / -3	CPS EXPRESS INC 3401 ETIWANDA AVE BLDG 621 MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAL000023295	**Mailing Zip:**	917520000
Create Date:	11/14/1989	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	CPS EXPRESS INC SPACE
Inact Date:	6/30/1995	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	P O BOX 248	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	DEACT PER 95 FEE FORM -P.H.
Street Address 1:	--
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
--		--				

1	45 of 89	E	0.00 / 0.00	814.60 / -3	MCVEIGH TRANSPORTATION 3401 ETIWANDA MIRA LOMA CA 900000000	HAZNET

SIC Code:
NAICS Code:
EPA ID: CAL000095334
Create Date: 7/13/1993
Fac Act Ind: No
Inact Date: 6/30/1994
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 ETIWANDA
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 900000000
Region Code: 4
Owner Name: --
Owner Addr 1: --
Owner Addr 2:
Owner City: --
Owner State: 99
Owner Zip: --
Owner Phone: 0000000000

Contact Information
-- --
Contact Name: UNDELIVERABLE PER FEES 6/94
Street Address 1: --
Street Address 2:
City: --
State: 99
Zip: --
Phone: --
-- --
-- --

Tanner Information
-- --
Generator EPA ID: CAL000095334
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD093459485
TSD County Code: 10
TSD County: Fresno
State Waste Code: 214
State Waste Code Desc.: Unspecified solvent mixture
Method Code: H01
Method Description: Transfer station
Tons: 0.0288
Year: 1995
-- --

1	46 of 89	E	0.00 / 0.00	814.60 / -3	UNION PACIFIC RAILROAD 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code:
NAICS Code:
EPA ID: CAC000883368
Create Date: 3/7/1994
Fac Act Ind: No
Inact Date: 10/25/2000
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 1416 DODGE ST
Mailing Addr 2:
Owner Fax:

Mailing City: OMAHA
Mailing State: NE
Mailing Zip: 601790000
Region Code: 4
Owner Name: UNION PACIFIC RAILROAD
Owner Addr 1: 1416 DODGE ST
Owner Addr 2:
Owner City: OMAHA
Owner State: NE
Owner Zip: 601790000
Owner Phone: 4022712235

Contact Information
-- --
Contact Name: DEBRA BLANCHARD/MGR COMLIANCE
Street Address 1: 1416 DODGE ST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Street Address 2:						
City:		OMAHA				
State:		NE				
Zip:		601790000				
Phone:		4022712235				
--		--				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	47 of 89	E	0.00 / 0.00	814.60 / -3	SPACE CENTER MIRA LOMA 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC001224328	**Mailing Zip:**	917520000
Create Date:	1/17/1997	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	SPACE CENTER MIRA LOMA
Inact Date:	10/25/2000	**Owner Addr 1:**	3401 ETIWANDA AVE
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MAIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE	**Owner Zip:**	917520000
Mailing Addr 2:		**Owner Phone:**	9096855221
Owner Fax:			

Contact Information	
--	--
Contact Name:	MIKE THIES
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	
City:	MAIRA LOMA
State:	CA
Zip:	917520000
Phone:	9096855221
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC001224328
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	241
State Waste Code Desc.:	Tank bottom waste
Method Code:	R01
Method Description:	Recycler
Tons:	100.7472
Year:	1997
--	--
Generator EPA ID:	CAC001224328
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	241
State Waste Code Desc.:	Tank bottom waste
Method Code:	R01
Method Description:	Recycler
Tons:	2.919
Year:	1999
--	--
Generator EPA ID:	CAC001224328
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD982484933
TSD County Code:	36

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TSD County:	San Bernardino
State Waste Code:	512
State Waste Code Desc.:	Other empty containers 30 gallons or more
Method Code:	R01
Method Description:	Recycler
Tons:	12
Year:	1997
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	48 of 89	E	0.00 / 0.00	814.60 / -3	1X SPACE CTR MIRA LOMA INC 3401 ETIWANDA AVE MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC000017970	**Mailing Zip:**	917520000
Create Date:	6/18/1987	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	--
Inact Date:	12/31/1899	**Owner Addr 1:**	--
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	3401 ETIWANDA AVE	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information	
--	--
Contact Name:	MIKE THIES
Street Address 1:	--
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	7146855221
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	AZC950823111
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	151
State Waste Code Desc.:	Asbestos containing waste
Method Code:	H132
Method Description:	LANDFILL OR SURFACE IMPOUNDMENT THAT WILL BE CLOSED AS LANDFILL(TO INCLUDE ON-SITE TREATMENT AND/OR STABILIZATION)
Tons:	4
Year:	2010
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD009007626
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	151
State Waste Code Desc.:	Asbestos containing waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.927
Year:	1993
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33

Generator County:	Riverside
TSD EPA ID:	CAD009007626
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	151
State Waste Code Desc.:	Asbestos containing waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.4214
Year:	1997
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD028409019
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.125
Year:	2011
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.7
Year:	2001
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.1
Year:	1998
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.6
Year:	1999
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD028409019
TSD County Code:	19

TSD County:	Los Angeles
State Waste Code:	181
State Waste Code Desc.:	Other inorganic solid waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.675
Year:	2002
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	331
State Waste Code Desc.:	Off-specification, aged or surplus organics
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.3
Year:	1999
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D99
Method Description:	Disposal, other
Tons:	2.5284
Year:	1994
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01
Method Description:	Transfer station
Tons:	5.0568
Year:	1996
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD028409019
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01
Method Description:	Transfer station
Tons:	0.5
Year:	2003
--	--
Generator EPA ID:	CAC000017970
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD028409019
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Method Description:	Transfer station
Tons:	0.2
Year:	2004
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	49 of 89	E	0.00 / 0.00	814.60 / -3	KARIS CHAM 3401 ETIWANDA AVE STE 811A JURUPA VALLEY CA 91752	HAZNET

SIC Code:	5093	**Mailing City:**	JURUPA VALLEY
NAICS Code:	42193	**Mailing State:**	CA
EPA ID:	CAC002819510	**Mailing Zip:**	91752
Create Date:	6/24/2015	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	KARIS CHAM
Inact Date:	9/23/2015	**Owner Addr 1:**	3401 ETIWANDA AVE
County Code:	33	**Owner Addr 2:**	STE 811A
County Name:	Riverside	**Owner City:**	JURUPA VALLEY
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE	**Owner Zip:**	91752
Mailing Addr 2:	STE 811A	**Owner Phone:**	9516819100
Owner Fax:			

Contact Information	
--	--
Contact Name:	VICCI YANG
Street Address 1:	3401 ETIWANDA AVE
Street Address 2:	STE 811A
City:	JURUPA VALLEY
State:	CA
Zip:	91752
Phone:	9516819100
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAC002819510
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD982444481
TSD County Code:	36
TSD County:	San Bernardino
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.748
Year:	2015
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	50 of 89	E	0.00 / 0.00	814.60 / -3	CALIFORNIA CUSTOM DESIGN 3401 ETIWANDA AVE BLDG 811A MIRA LOMA CA 917520000	HAZNET

SIC Code:		**Mailing City:**	MIRA LOMA
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAR000014233	**Mailing Zip:**	917520000
Create Date:	2/26/1997	**Region Code:**	4
Fac Act Ind:	No	**Owner Name:**	PREDELIVERY SERVICE CORP
Inact Date:	6/1/1997	**Owner Addr 1:**	4500 ETIWANDA AVE BLDG A
County Code:	33	**Owner Addr 2:**	
County Name:	Riverside	**Owner City:**	MIRA LOMA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	3401 ETIWANDA AVE BLDG 811A	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Information	
--	--
Contact Name:	PREDELIVERY SERVICE CORP
Street Address 1:	4500 ETIWANDA AVE BLDG A
Street Address 2:	
City:	MIRA LOMA
State:	CA
Zip:	--
Phone:	--
--	--
--	--
Tanner Information	
--	--
Generator EPA ID:	CAR000014233
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	H01
Method Description:	Transfer station
Tons:	0.072
Year:	1997
--	--
Generator EPA ID:	CAR000014233
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAT080013352
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	R01
Method Description:	Recycler
Tons:	0.114
Year:	1997
--	--
Generator EPA ID:	CAR000014233
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01
Method Description:	Transfer station
Tons:	0.325
Year:	1997
--	--
Generator EPA ID:	CAR000014233
Generator County Code:	33
Generator County:	Riverside
TSD EPA ID:	CAD000088252
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	512
State Waste Code Desc.:	Other empty containers 30 gallons or more
Method Code:	H01
Method Description:	Transfer station
Tons:	0.1
Year:	1997
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	*51 of 89*	*E*	*0.00 / 0.00*	*814.60 / -3*	*1X PACIFIC FABRIC REELS 3401 ETIWANDA AVE*	*HAZNET*

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					MIRA LOMA CA 917520000	

SIC Code:
NAICS Code:
EPA ID: CAC000867176
Create Date: 5/5/1993
Fac Act Ind: No
Inact Date: 10/25/2000
County Code: 33
County Name: Riverside
Mail Name:
Mailing Addr 1: 3401 ETIWANDA AVE
Mailing Addr 2:
Owner Fax:

Mailing City: MIRA LOMA
Mailing State: CA
Mailing Zip: 917520000
Region Code: 3
Owner Name: PACIFIC FABRIC REELS
Owner Addr 1: --
Owner Addr 2:
Owner City: --
Owner State: 99
Owner Zip: --
Owner Phone: 0000000000

Contact Information
-- --
Contact Name: P.F.R. ENVIRONMENTAL SRV
Street Address 1: --
Street Address 2:
City: --
State: 99
Zip: --
Phone: 8189606106
-- --
-- --

Tanner Information
-- --
Generator EPA ID: CAC000867176
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD000088252
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: ***
State Waste Code Desc.: Invalid waste code
Method Code: H01
Method Description: Transfer station
Tons: 0.1
Year: 1993
-- --
Generator EPA ID: CAC000867176
Generator County Code: 33
Generator County: Riverside
TSD EPA ID: CAD000088252
TSD County Code: 19
TSD County: Los Angeles
State Waste Code: 221
State Waste Code Desc.: Waste oil and mixed oil
Method Code: H01
Method Description: Transfer station
Tons: 0.228
Year: 1993
-- --

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	52 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	HIST MANIFEST

Gen EPA ID: CAD091927095
Create Date: 7/23/1982 0:00:00
Inact Date: 01/01/1900 0:00
Facility Mail Street: 33 WEST MONROE
Facility Mail City: CHICAGO
Facility Mail State: IL
Facility Mail Zip: 606030000
Contact Phone(s): 3126484000
File Year(s): 1983; 1984; 1985; 1986; 1987; 1988; 1989; 1990; 1991; 1992
Contact Name(s): NORTH AMERICAN CAR CORPORATION

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: AZT050010180

Tanner Information

Method Description:
Tons: 0.22
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code: 223
State Waste Code Desc: Unspecified oil-containing waste
Tsd Epa ID: AZT050010180

Tanner Information

Method Description:
Tons: 1.23
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 212
State Waste Code Desc: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: AZT050010180

Tanner Information

Method Description:
Tons: 3.66
Year: 1991
Generator County Code: 33

Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 135
State Waste Code Desc: Unspecified aqueous solution
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 4.21
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 101.13
Year: 1984
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 1.14
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 2.75
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: 1
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 155.91
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 25.28
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 10.11
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 15.17
Year: 1990
Generator County Code: 33
Generator County: Riverside

Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD028409019

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0.12
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 12.64
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0
Year: 1984
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0.12
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 212
State Waste Code Desc: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 8.42
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: 3

Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 19.53
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0.45
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0.91
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: T01
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 341
State Waste Code Desc: Organic liquids (nonsolvents) with halogens
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0.12
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0.22
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 213
State Waste Code Desc: Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 136.53
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 491
State Waste Code Desc: Unspecified sludge waste
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 25.28
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 16

Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1985
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0.41
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: 1
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 212
State Waste Code Desc: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 2.06
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 352
State Waste Code Desc: Other organic solids
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0.91
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code: 212
State Waste Code Desc: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Tsd Epa ID: AZT050010180

Tanner Information

Method Description:
Tons: 0.45
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 513
State Waste Code Desc: Empty containers less than 30 gallons
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 29.49
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0.06
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 16
Tsd County: Kings

State Waste Code: 341
State Waste Code Desc: Organic liquids (nonsolvents) with halogens
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 1.27
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: 1
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 2.29
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 135
State Waste Code Desc: Unspecified aqueous solution
Tsd Epa ID: CAD028409019

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:

Tons: 0
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 5.59
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 0
Tsd County:
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: ILD098642424

Tanner Information

Method Description:
Tons: 0.03
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 0
Tsd County:
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: ILD098642424

Tanner Information

Method Description:
Tons: 12.64
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:

State Waste Code Desc:
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 22.75
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 181
State Waste Code Desc: Other inorganic solid waste
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 15.17
Year: 1985
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 491
State Waste Code Desc: Unspecified sludge waste
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 6.74
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 181
State Waste Code Desc: Other inorganic solid waste
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0

Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 21.07
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 491
State Waste Code Desc: Unspecified sludge waste
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 32.02
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 48.89
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 352
State Waste Code Desc: Other organic solids
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 2.08
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: 14
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:

Tsd Epa ID: AZT050010180

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 4.35
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: T01
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 331
State Waste Code Desc: Off-specification, aged or surplus organics
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 7.77
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 341
State Waste Code Desc: Organic liquids (nonsolvents) with halogens
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 16.85
Year: 1987

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 0
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 210.7
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 611
State Waste Code Desc: Contaminated soil from site clean-up
Tsd Epa ID: CAT000646117

Tanner Information

Method Description:
Tons: 15.17
Year: 1985
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 16
Tsd County: Kings
State Waste Code: 491
State Waste Code Desc: Unspecified sludge waste
Tsd Epa ID: CAT000646117

1	53 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA AVE, BLDG 911D MIRA LOMA CA 917520000	HIST MANIFEST

Gen EPA ID: CAC000621864
Create Date: 5/22/1991 0:00:00
Inact Date: 10/25/2000 0:00:00
Facility Mail Street: --
Facility Mail City: MIRA LOMA
Facility Mail State: CA
Facility Mail Zip: 917520000
Contact Phone(s): 7146851548
File Year(s): 1991
Contact Name(s): LANCE CANSDALE/VP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 15
Tsd County: Kern
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980883177

Tanner Information

Method Description:
Tons: 0.12
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 15
Tsd County: Kern
State Waste Code: 241
State Waste Code Desc: Tank bottom waste
Tsd Epa ID: CAD980883177

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	54 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA AVE MIRA LOMA CA 917520000	HIST MANIFEST

Gen EPA ID: CAC000017970
Create Date: 6/18/1987 0:00:00
Inact Date: 01/01/1900 0:00
Facility Mail Street: 3401 ETIWANDA AVE
Facility Mail City: MIRA LOMA
Facility Mail State: CA
Facility Mail Zip: 917520000
Contact Phone(s): 7146855221
File Year(s): 1987; 1989; 1990; 1991; 1992
Contact Name(s): MIKE THIES

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 99
Tsd County: Unknown
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: AZC000000150

Tanner Information

Method Description:
Tons: 0
Year: 1989
Generator County Code: 33

Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: AZC000000150

Tanner Information

Method Description:
Tons: 7.5
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 15
Tsd County: Kern
State Waste Code: 241
State Waste Code Desc: Tank bottom waste
Tsd Epa ID: CAD980883177

Tanner Information

Method Description:
Tons: 0
Year: 1991
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 15
Tsd County: Kern
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980883177

Tanner Information

Method Description:
Tons: 16.01
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 99
Tsd County: Unknown
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: AZC000000150

Tanner Information

Method Description:
Tons: 8.2
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 99
Tsd County: Unknown
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: AZC000000150

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 15
Tsd County: Kern
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980883177

Tanner Information

Method Description:
Tons: 5
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 15
Tsd County: Kern
State Waste Code: 241
State Waste Code Desc: Tank bottom waste
Tsd Epa ID: CAD980883177

Tanner Information

Method Description:
Tons: 0
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: AZC000000150

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 45
Tsd County: Shasta
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD981388952

Tanner Information

Method Description:
Tons: 3.38
Year: 1987
Generator County Code: 33
Generator County: Riverside

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Method Code: D80
Tsd County Code: 45
Tsd County: Shasta
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: CAD981388952

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 99
Tsd County: Unknown
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: AZC000000150

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	55 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA AVE MIRA LOMA CA 917520000	HIST MANIFEST

Gen EPA ID: CAX000225128
Create Date: 03/08/1985 0:00
Inact Date: 4/30/1986 0:00:00
Facility Mail Street: JACKIE MCCORMICK
Facility Mail City: CHINO
Facility Mail State: CA
Facility Mail Zip: 917100000
Contact Phone(s): 7149834251
File Year(s): 1986
Contact Name(s): INACTIVE PER SURVEY 12-22-94

Tanner Information

Method Description:
Tons: 0.3
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 261
State Waste Code Desc: Polychlorinated biphenyls and material containing PCBs
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	56 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA MIRA LOMA CA 917520000	HIST MANIFEST

Gen EPA ID: CAD981393945
Create Date: 04/10/1987 0:00
Inact Date: 01/01/1995 0:00
Facility Mail Street: P O BOX 725
Facility Mail City: CHINO
Facility Mail State: CA
Facility Mail Zip: 917080000
Contact Phone(s): --
File Year(s): 1987; 1988; 1989; 1990
Contact Name(s): INACTIVE PER SURVEY 12-22-94

Tanner Information

Method Description:
Tons: 0.18
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 512
State Waste Code Desc: Other empty containers 30 gallons or more
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0.06
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 512
State Waste Code Desc: Other empty containers 30 gallons or more
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:

Tsd County Code: 39
Tsd County: San Joaquin
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD990794133

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 0
Tsd County:
State Waste Code:
State Waste Code Desc:
Tsd Epa ID:

Tanner Information

Method Description:
Tons: 3.24
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 261
State Waste Code Desc: Polychlorinated biphenyls and material containing PCBs
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 1
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 123
State Waste Code Desc: Unspecified alkaline solution
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0.06
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: 14
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0.06
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 214
State Waste Code Desc: Unspecified solvent mixture
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0.01
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 343
State Waste Code Desc: Unspecified organic liquid mixture
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0.25
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42

Tsd County: Santa Barbara
State Waste Code: 512
State Waste Code Desc: Other empty containers 30 gallons or more
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 3.57
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: 14
Tsd County Code: 0
Tsd County:
State Waste Code: 261
State Waste Code Desc: Polychlorinated biphenyls and material containing PCBs
Tsd Epa ID:

Tanner Information

Method Description:
Tons: 0.05
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 39
Tsd County: San Joaquin
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD990794133

Tanner Information

Method Description:
Tons: 0.91
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: 14
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0.5
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0.7
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 272
State Waste Code Desc: Polymeric resin waste
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 34
Tsd County: Sacramento

State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0.02
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 343
State Waste Code Desc: Unspecified organic liquid mixture
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 0
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: 3
Tsd County Code: 39
Tsd County: San Joaquin
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: CAD990794133

Tanner Information

Method Description:
Tons: 0
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD067786749

Tanner Information

Method Description:
Tons: 0.12
Year: 1988
Generator County Code: 33
Generator County: Riverside
Method Code: UNK
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 512
State Waste Code Desc: Other empty containers 30 gallons or more
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:

Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 4.21
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 39
Tsd County: San Joaquin
State Waste Code: 151
State Waste Code Desc: Asbestos containing waste
Tsd Epa ID: CAD990794133

Tanner Information

Method Description:
Tons: 5.15
Year: 1989
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 261
State Waste Code Desc: Polychlorinated biphenyls and material containing PCBs
Tsd Epa ID: CAD980884183

Tanner Information

Method Description:
Tons: 1.6
Year: 1990
Generator County Code: 33
Generator County: Riverside
Method Code: H01
Tsd County Code: 34
Tsd County: Sacramento
State Waste Code: 261
State Waste Code Desc: Polychlorinated biphenyls and material containing PCBs
Tsd Epa ID: CAD980884183

1	57 of 89	E	0.00 / 0.00	814.60 / -3	3401 ETIWANDA AVE MIRA LOMA CA 917520000	HIST MANIFEST

Gen EPA ID: CAD980815468
Create Date: 5/24/1983 0:00:00
Inact Date: 6/30/1998 0:00:00
Facility Mail Street: 3401 ETIWANDA AVE BLDG 811A
Facility Mail City: MIRA LOMA
Facility Mail State: CA
Facility Mail Zip: 917521128
Contact Phone(s): 9096850151

File Year(s): 1983; 1986; 1987; 1992
Contact Name(s): EDWARD N SILVA

Tanner Information

Method Description:
Tons: 0
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD089446710

Tanner Information

Method Description:
Tons: 2.08
Year: 1992
Generator County Code: 33
Generator County: Riverside
Method Code: D99
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 214
State Waste Code Desc: Unspecified solvent mixture
Tsd Epa ID: CAD089446710

Tanner Information

Method Description:
Tons: 1.2
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 271
State Waste Code Desc: Organic monomer waste (includes unreacted resins)
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 3.9
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 461
State Waste Code Desc: Paint sludge
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0

Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD981161128

Tanner Information

Method Description:
Tons: 0.83
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 221
State Waste Code Desc: Waste oil and mixed oil
Tsd Epa ID: CAD981161128

Tanner Information

Method Description:
Tons: 0
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0
Year: 1986
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code:
State Waste Code Desc:
Tsd Epa ID: CAD020748125

Tanner Information

Method Description:
Tons: 0
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code:
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code:
State Waste Code Desc:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 3.09
Year: 1983
Generator County Code: 33
Generator County: Riverside
Method Code: R01
Tsd County Code: 19
Tsd County: Los Angeles
State Waste Code: 214
State Waste Code Desc: Unspecified solvent mixture
Tsd Epa ID: CAD008302903

Tanner Information

Method Description:
Tons: 6.4
Year: 1987
Generator County Code: 33
Generator County: Riverside
Method Code: D80
Tsd County Code: 42
Tsd County: Santa Barbara
State Waste Code: 461
State Waste Code Desc: Paint sludge
Tsd Epa ID: CAD020748125

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	58 of 89	E	0.00 / 0.00	814.60 / -3	O'NEIL TUBE & REEL 3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	FINDS/FRS

Registry ID: 110065772211
FIPS Code:
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 13-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065772211
Program Acronyms:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CA-ENVIROVIEW:139145

---

1 | **59 of 89** | **E** | **0.00 / 0.00** | **814.60 / -3** | **SPACE CENTER**
3401 ETIWANDA AVE
MIRA LOMA CA 91752 | **FINDS/FRS**

Registry ID:	110065202569
FIPS Code:	06065
HUC Code:	18070203
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	10-OCT-15
Update Date:	
Interest Types:	OTHER HAZARDOUS WASTE ACTIVITIES, STATE MASTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	493110
NAICS Code Descriptions:	GENERAL WAREHOUSING AND STORAGE.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	44
Census Block Code:	060650406072100
EPA Region Code:	09
County Name:	RIVERSIDE
US/Mexico Border Ind:	
Latitude:	34.026175
Longitude:	-117.530945
Reference Point:	ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	50
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065202569
Program Acronyms:	

CA-ENVIROVIEW:234004, RCRAINFO:CAC002996451

---

1 | **60 of 89** | **E** | **0.00 / 0.00** | **814.60 / -3** | **CPS EXPRESSNA INC**
3401 ETIWANDA AVE # 711
MIRA LOMA CA 91752 | **FINDS/FRS**

Registry ID:	110066163001
FIPS Code:	
HUC Code:	18070203
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	14-OCT-15
Update Date:	
Interest Types:	STATE MASTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066163001
Program Acronyms:

CA-ENVIROVIEW:108634

1	61 of 89	E	0.00 / 0.00	814.60 / -3	**JURUPA COMMUNITY SVCS DIST (SITE 22)** **3423 SPACE CENTER CT** **JURUPA VALLEY CA 91752**	FINDS/FRS

Registry ID: 110065518050
FIPS Code:
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 13-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072086
EPA Region Code: 09
County Name: RIVERSIDE COUNTY
US/Mexico Border Ind:
Latitude: 34.02662
Longitude: -117.52705
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065518050
Program Acronyms:

CA-ENVIROVIEW:40747

1	62 of 89	E	0.00 / 0.00	814.60 / -3	**KEROZAKNA INC** **3401 ETIWANDA AVE STE 811A** **MIRA LOMA CA 91752**	FINDS/FRS

Registry ID: 110065847846

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FIPS Code:
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 13-OCT-15
Update Date:
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072100
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.026175
Longitude: -117.530945
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110065847846
Program Acronyms:

CA-ENVIROVIEW:358629

1	***63 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***Hanes Industries 3401 Etiwanda Ave Bldg 1011 Jurupa Valley CA 91752***	***RIVERSIDE HZH***

1	***64 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***SPACE CENTER MIRA LOMA, INC 3401 ETIWANDA AVE, BLDG 1325 MIRA LOMA CA 91752***	***EMISSIONS***

1990 Criteria Data

Facility ID: 72988
Facility SIC Code: 9661
CO: 33
Air Basin: SC
District: SC
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:
TOGT: .1
ROGT: .08785
COT: .5
NOXT: 1.9
SOXT: 0
PMT: .2
PM10T: .1952

1990 Toxic Data

Facility ID: 72988
Facility SIC Code: 9661
CO: 33
Air Basin: SC
District: SC
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

1993 Criteria Data

Facility ID:	72988	***CERR Code:***	
Facility SIC Code:	9661	***TOGT:***	0
CO:	33	***ROGT:***	0
Air Basin:	SC	***COT:***	.4
District:	SC	***NOXT:***	0
COID:	RIV	***SOXT:***	0
DISN:	SOUTH COAST AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

1993 Toxic Data

Facility ID:	72988	***COID:***	RIV
Facility SIC Code:	9661	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

1995 Criteria Data

Facility ID:	72988	***CERR Code:***	
Facility SIC Code:	9661	***TOGT:***	0
CO:	33	***ROGT:***	0
Air Basin:	SC	***COT:***	.4
District:	SC	***NOXT:***	0
COID:	RIV	***SOXT:***	0
DISN:	SOUTH COAST AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

1995 Toxic Data

Facility ID:	72988	***COID:***	RIV
Facility SIC Code:	9661	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	***65 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***JURUPA COMMUNITY SERVICES DIST*** ***3401 ETIWANDA AV*** ***MIRA LOMA CA 91752***	***EMISSIONS***

1993 Criteria Data

Facility ID:	78802	***CERR Code:***	
Facility SIC Code:	4941	***TOGT:***	2
CO:	33	***ROGT:***	.1828

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Basin:	SC	**COT:**	.6
District:	SC	**NOXT:**	5.1
COID:	RIV	**SOXT:**	0
DISN:	SOUTH COAST AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1993 Toxic Data

Facility ID:	78802	**COID:**	RIV
Facility SIC Code:	4941	**DISN:**	SOUTH COAST AQMD
CO:	33	**CHAPIS:**	
Air Basin:	SC	**CERR Code:**	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1995 Criteria Data

Facility ID:	78802	**CERR Code:**	
Facility SIC Code:	4941	**TOGT:**	2
CO:	33	**ROGT:**	.1828
Air Basin:	SC	**COT:**	.6
District:	SC	**NOXT:**	5.1
COID:	RIV	**SOXT:**	0
DISN:	SOUTH COAST AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1995 Toxic Data

Facility ID:	78802	**COID:**	RIV
Facility SIC Code:	4941	**DISN:**	SOUTH COAST AQMD
CO:	33	**CHAPIS:**	
Air Basin:	SC	**CERR Code:**	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	66 of 89	E	0.00 / 0.00	814.60 / -3	JURUPA COMMUNITY SERVICES DIST 3401 ETIWANDA AVE MIRA LOMA CA 91752	EMISSIONS

1996 Criteria Data

Facility ID:	78802	**CERR Code:**	
Facility SIC Code:	4941	**TOGT:**	.4
CO:	33	**ROGT:**	.03656
Air Basin:	SC	**COT:**	.1
District:	SC	**NOXT:**	.4
COID:	RIV	**SOXT:**	
DISN:	SOUTH COAST AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1996 Toxic Data

Facility ID:	78802	**COID:**	RIV
Facility SIC Code:	4941	**DISN:**	SOUTH COAST AQMD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CHAPIS:
CERR Code:

1998 Toxic Data

Facility ID: 78802
Facility SIC Code: 4941
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1999 Toxic Data

Facility ID: 78802
Facility SIC Code: 4941
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

2000 Toxic Data

Facility ID: 78802
Facility SIC Code: 4941
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

2001 Toxic Data

Facility ID: 78802
Facility SIC Code: 4941
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1	***67 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***CAL CUSTOM DESIGN*** ***3401 ETIWANDA AVE, BLDG #811-A*** ***MIRA LOMA CA 91752***	***EMISSIONS***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

1987 Criteria Data

Facility ID:	23906	***CERR Code:***	
Facility SIC Code:	2834	***TOGT:***	8
CO:	33	***ROGT:***	7.46452
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	.2
CHAPIS:		***PM10T:***	.1534

1987 Toxic Data

Facility ID:	23906	***COID:***	RIV
Facility SIC Code:	2834	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1990 Criteria Data

Facility ID:	23906	***CERR Code:***	
Facility SIC Code:	3999	***TOGT:***	5.8
CO:	33	***ROGT:***	1.66944
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	.4
CHAPIS:		***PM10T:***	.3068

1990 Toxic Data

Facility ID:	23906	***COID:***	RIV
Facility SIC Code:	3999	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	***68 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***G E RAILCAR REPAIR 3401 ETIWANDA AV MIRA LOMA CA 91752***	***EMISSIONS***

1987 Criteria Data

Facility ID:	58612	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	16
CO:	33	***ROGT:***	15.488
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1987 Toxic Data

Facility ID:	58612	***COID:***	RIV
Facility SIC Code:	3479	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1990 Criteria Data

Facility ID:	58612	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	.5
CO:	33	***ROGT:***	.484
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1990 Toxic Data

Facility ID:	58612	***COID:***	RIV
Facility SIC Code:	3479	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1993 Criteria Data

Facility ID:	58612	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	2.4
CO:	33	***ROGT:***	2.3232
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1993 Toxic Data

Facility ID:	58612	***COID:***	RIV
Facility SIC Code:	3479	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1995 Criteria Data

Facility ID:	58612	***CERR Code:***	
Facility SIC Code:	3479	***TOGT:***	2.4
CO:	33	***ROGT:***	2.3232

Air Basin: SC
District: SC
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
COT:
NOXT:
SOXT:
PMT:
PM10T:

1995 Toxic Data

Facility ID: 58612
Facility SIC Code: 3479
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1996 Toxic Data

Facility ID: 58612
Facility SIC Code: 3479
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1997 Toxic Data

Facility ID: 58612
Facility SIC Code: 3479
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1998 Toxic Data

Facility ID: 58612
Facility SIC Code: 3479
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

1999 Toxic Data

Facility ID: 58612
Facility SIC Code: 3479
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2000 Toxic Data

Facility ID:	58612	***COID:***	RIV
Facility SIC Code:	3479	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2001 Toxic Data

Facility ID:	58612	***COID:***	RIV
Facility SIC Code:	3479	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	***69 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***CAL CUSTOM DESIGN, INC RED-E-K*** ***3401 ETIWANDA AV, BLDG 811A*** ***MIRA LOMA CA 91752***	***EMISSIONS***

1990 Criteria Data

Facility ID:	51422	***CERR Code:***	
Facility SIC Code:	5561	***TOGT:***	3.9
CO:	33	***ROGT:***	3.7752
Air Basin:	SC	***COT:***	0
District:	SC	***NOXT:***	0
COID:	RIV	***SOXT:***	0
DISN:	SOUTH COAST AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

1990 Toxic Data

Facility ID:	51422	***COID:***	RIV
Facility SIC Code:	5561	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	***70 of 89***	***E***	***0.00 / 0.00***	***814.60 / -3***	***JG HADDY SALES CO DBA CPS EXPRESS*** ***3401 ETIWANDA AVE*** ***MIRA LOMA CA 91752***	***FINDS/FRS***

Registry ID: 110070091020

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 07-AUG-17
Update Date:
Interest Types: ICIS-NPDES NON-MAJOR, STORM WATER INDUSTRIAL
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: ICIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072085
EPA Region Code: 09
County Name: RIVERSIDE COUNTY
US/Mexico Border Ind:
Latitude: 34.02659
Longitude: -117.52451
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070091020
Program Acronyms:

NPDES:CAZ400732

1	71 of 89	E	0.00 / 0.00	814.60 / -3	RHINO ATP INC 3401 ETIWANDA AVE #731A MIRA LOMA CA 91752	FINDS/FRS

Registry ID: 110070096544
FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 07-AUG-17
Update Date:
Interest Types: ICIS-NPDES NON-MAJOR, STORM WATER INDUSTRIAL
SIC Codes: 4226
SIC Code Descriptions: SPECIAL WAREHOUSING AND STORAGE, NOT ELSEWHERE CLASSIFIED
NAICS Codes:
NAICS Code Descriptions:
Conveyor: ICIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072103
EPA Region Code: 09
County Name: RIVERSIDE COUNTY
US/Mexico Border Ind:
Latitude: 34.02499
Longitude: -117.53554
Reference Point:
Coord Collection Method:
Accuracy Value:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070096544
Program Acronyms:

NPDES:CAZ473094

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	72 of 89	E	0.00 / 0.00	814.60 / -3	O'Neil Tube & Reel 3401 ETIWANDA AVE #811C MIRA LOMA CA 91752	CERS HAZ

Site ID: 398465
Latitude: 34.025920
Longitude: -117.533260
County:

Regulated Programs

EI ID: 10328143 **EI Description:** Hazardous Waste Generator

EI ID: 10328143 **EI Description:** Chemical Storage Facilities

Violations

Violation Date: 09/18/2019 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Riverside County Department of Env Health
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: Observed both 55 gallon drums that were missing proper labels. CORRECTIVE ACTION: Owner/operator shall label hazardous waste containers with all the required information. Label shall include at least: the words ""hazardous waste"", generator name and address, accumulation start date, composition and physical state of waste, and hazardous property statement. Submit photos to this department, if applicable.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 09/18/2019 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Riverside County Department of Env Health
Citation: 40 CFR 1 265.33 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.33
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: Observed inoperable or lack of adequate fire-fighting equipment. The extinguishers are in need to recertification. CORRECTIVE ACTION: Owner/operator shall ensure fire-fighting equipment is available on site ready for use and properly certified.

Violation Description:

Failure to test and maintain as necessary all facility communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment to assure its proper operation in time of emergency.

Violations

Violation Date: 09/18/2019 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Riverside County Department of Env Health
Citation: 40 CFR 1 262.34(d)(5)(ii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(ii)
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: Observed no/incomplete emergency response information postings. CORRECTIVE ACTION: Owner/operator shall post required information next to the phone.

Violation Description:

Failure to post the following information next to the telephone:
(A) The name and telephone number of the emergency coordinator;
(B) Location of fire extinguishers and spill control material, and, if present, fire alarm; and
(C) The telephone number of the fire department, unless the facility has a direct alarm.

Violations

Violation Date: 09/18/2019 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: Observed spilled oil and used absorbent around machines that has not been cleaned up. CORRECTIVE ACTION: Owner/operator shall clean up areas and placed used absorbent into proper containers, and manage according to Title 22 hazardous waste regulations. Submit a statement and supporting documentation (photos) explaining how this waste was managed to this department.

Violation Description:

Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.

Violations

Violation Date: 09/18/2019 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: No emergency contact posting was observed. CORRECTIVE ACTION: Owner/operator shall post emergency contact information in a conspicuous location and shall include but not be limited to all of the following: 911; local appropriate hospital name and phone number; primary facility emergency contact person's name and phone number; Riverside County Environmental Health Hazardous Materials Program name and phone number; California Office of Emergency Services name and phone number; National Response Center name and phone number; Poison Control Center name and phone number; and if applicable the name and phone number of a licensed hazardous materials cleanup contractor and location of fire extinguishers, spill control materials, and fire alarm.

Violation Description:

Business Plan Program - Administration/Documentation - General Local Ordinance

Violations

Violation Date: 09/18/2019 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Notes:

Returned to compliance on 07/02/2020. OBSERVATION: Observed 55 gallon drums on site that operator stated only gets picked up annually. CORRECTIVE ACTION: Owner/operator shall ensure all hazardous wastes are transported off site within 180 days of the accumulation start date. Owner/operator shall have both drums hazardous waste properly hauled off site by a registered hazardous waste transporter.

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met:
(1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Evaluations

Eval Date: 05/09/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/09/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/18/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 07/02/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

HW gen follow up; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/18/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Facility have water based adhesive totes and propane; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/02/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval Notes:

HM follow up; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: O'Neil Tube & Reel
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: O'Neill Tube & Reel
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 360-8600

Affil Type Desc: Legal Owner
Entity Name: Remy O'Neill
Entity Title:
Address: 6135 Cavalleri Rd
City: Malibu
State: CA
Country: United States
Zip Code: 90265
Phone: (951) 360-8600

Affil Type Desc: Document Preparer
Entity Name: Tori Layne
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Identification Signer
Entity Name: Remy O'Neill
Entity Title: Owner
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Name: Mailing Address
Entity Title:
Address: 3401 Etiwanda Ave. #811-C
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Environmental Contact
Entity Name: TORI LAYNE
Entity Title:
Address: 3401 Etiwanda Ave #811C
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	73 of 89	E	0.00 / 0.00	814.60 / -3	CPS Express, Inc 3401 ETIWANDA AVE # 711 MIRA LOMA CA 91752	CERS HAZ

Site ID: 390742
Latitude: 34.025920
Longitude: -117.533260
County:

Regulated Programs

EI ID: 10322131 **EI Description:** Chemical Storage Facilities

Evaluations

Eval Date: 06/28/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/16/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/16/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations (help w/ CERS); Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: CPS Express, Inc
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Operator
Entity Name: Jay Sorg
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 685-1041

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO Box 248
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Jay Sorg
Entity Title:
Address: P.O. Box 248
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Document Preparer
Entity Name: Jeff Woolsey
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: J.G. Haddy Sales Co., Inc

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Title:
Address: PO Box 248
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 685-1041

Affil Type Desc: Identification Signer
Entity Name: Jeff Woolsey
Entity Title: Controller
Address:
City:
State:
Country:
Zip Code:
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	74 of 89	E	0.00 / 0.00	814.60 / -3	Hanes Industries 3401 ETIWANDA AVE BUILDING 1011 UNITS C&D JURUPA VALLEY CA 91752	CERS HAZ

Site ID: 394329
Latitude: 34.025920
Longitude: -117.533260
County:

Regulated Programs

EI ID: 10656598 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 08/09/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/14/2017.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 07/05/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/14/2017.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 09/23/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health

Citation: Un-Specified
Violation Notes:

Returned to compliance on 09/12/2017.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 09/23/2016
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 07/03/2017.

Violation Description:

Business Plan Program - Administration/Documentation - General Local Ordinance

Evaluations

Eval Date: 07/05/2017
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/10/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations observed.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/23/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

002 @ Hanes 3401 Etiwanda; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/09/2017
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Operator
Entity Name: Doug Wynn
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (714) 864-9111

Affil Type Desc: Document Preparer
Entity Name: Tim Williams
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Tim Williams
Entity Title:
Address: 500 N. McLin Creek Rd
City: Conover
State: NC
Country:
Zip Code: 28613
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 3401 Etiwanda Ave building 1011 Units C&D
City: Jurupa VAlley
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Legal Owner
Entity Name: HANES INDUSTRIES
Entity Title:
Address: 3401 Etiwanda Ave building 1011 Units C&D
City: Jurupa VAlley
State: CA
Country: United States
Zip Code: 91752
Phone: (562) 217-1317

Affil Type Desc: Parent Corporation
Entity Name: HANES INDUSTRIES
Entity Title:
Address:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Derek Cooperberg
Entity Title: Branch Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

1	75 of 89	E	0.00 / 0.00	814.60 / -3	CAMPBELL OIL COMPANY 3401 ETIWANDA AVE, 502 MIRA LOMA CA	HIST TANK

Owner Name: SPACE CENTER MIRA LOMA, INC.
Owner Street: 3401 ETIWANDA AVE, 503
Owner City: MIRA LOMA
Owner State: CA
Owner Zip: 91752
No of Containers: 2
County: RIVERSIDE
Facility State: CA
Facility Zip: 91752

1	76 of 89	E	0.00 / 0.00	814.60 / -3	FRANK KAMS & ASSOC INC 3401 ETIWANDA AVE MIRA LOMA CA 91752	FINDS/FRS

Registry ID: 110070287030
FIPS Code:
HUC Code:
Site Type Name:
Location Description:
Supplemental Location:
Create Date: 27-SEP-18
Update Date:
Interest Types: OSHA ESTABLISHMENT
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 321912
NAICS Code Descriptions: CUT STOCK, RESAWING LUMBER, AND PLANING.
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name:
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070287030
Program Acronyms:

OSHA-OIS:340508662

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	77 of 89	E	0.00 / 0.00	814.60 / -3	ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION 3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128	RCRA NON GEN

EPA Handler ID: CAL000408792
Gen Status Universe: No Report
Contact Name: TRACY PFAFF
Contact Address: 3401 ETIWANDA AVE BLDG 731D , , JURUPA VALLEY , CA, 91752 ,
Contact Phone No and Ext: 951-360-7721
Contact Email: TRACY@GILENO.COM
Contact Country:
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 20150727
Location Latitude: 34.027533
Location Longitude: -117.52902

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20150727
Handler Name: ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: TRACY PFAFF
Date Became Current:
Date Ended Current:
Phone: 951-360-7721
Source Type: Implementer
Street No:
Street 1: 3401 ETIWANDA AVE BLDG 731D
Street 2:
City: JURUPA VALLEY
State: CA
Country:
Zip Code: 91752

Owner/Operator Ind: Current Owner
Street No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Other	**Street 1:**	13555 CANYON CREST RD.
Name:	ADAMS NEVADA EQUIPMENT CO	**Street 2:**	
Date Became Current:		**City:**	YUCAIPA
Date Ended Current:		**State:**	CA
Phone:	951-360-7721	**Country:**	
Source Type:	Implementer	**Zip Code:**	92399

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	78 of 89	E	0.00 / 0.00	814.60 / -3	O'NEILL TUBE & REEL 3401 ETIWANDA AVE STE 811C MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID:	CAL000348808
Gen Status Universe:	No Report
Contact Name:	TORI LAYNE
Contact Address:	3401 ETIWANDA AVE STE 811C , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	951-360-8600
Contact Email:	TORI@ONEILLREEL.COM
Contact Country:	
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	
Receive Date:	20091217
Location Latitude:	34.027533
Location Longitude:	-117.52902

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20091217
Handler Name:	O'NEILL TUBE & REEL
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6135 CAVALLERI RD
Name:	REMY O'NEILL	**Street 2:**	
Date Became Current:		**City:**	MALIBU

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Ended Current:
Phone: 310-457-9107
Source Type: Implementer

Owner/Operator Ind: Current Operator
Type: Other
Name: TORI LAYNE
Date Became Current:
Date Ended Current:
Phone: 951-360-8600
Source Type: Implementer

State: CA
Country:
Zip Code: 90265-4015

Street No:
Street 1: 3401 ETIWANDA AVE STE 811C
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	79 of 89	E	0.00 / 0.00	814.60 / -3	Jurupa Community Svcs Dist(Site 22) 3423 SPACE CENTER CT JURUPA VALLEY CA 91752	DELISTED CTNK

Site ID: 40747
County:
Original Source: CTNK

Latitude:
Longitude:
Record Date: 06-MAY-2019

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	80 of 89	E	0.00 / 0.00	814.60 / -3	ADAMS NEVADA EQUIPMENT CO INC DBA GILENO DISTRIBUTION 3401 ETIWANDA AVE BLDG 731D JURUPA VALLEY CA 91752-1128	FINDS/FRS

Registry ID: 110070422180
FIPS Code: 06065
HUC Code:
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 31-DEC-18
Update Date:
Interest Types: OTHER HAZARDOUS WASTE ACTIVITIES
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 562119
NAICS Code Descriptions: OTHER WASTE COLLECTION.
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070422180
Program Acronyms:

RCRAINFO:CAL000408792

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	81 of 89	E	0.00 / 0.00	814.60 / -3	ONEILL TUBE & REEL 3401 ETIWANDA AVE STE 811C	FINDS/FRS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					MIRA LOMA CA 91752	

Registry ID: 110070389426
FIPS Code: 06065
HUC Code: 18070203
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 07-DEC-18
Update Date:
Interest Types: ICIS-NPDES NON-MAJOR, OTHER HAZARDOUS WASTE ACTIVITIES, STORM WATER INDUSTRIAL, TRANSPORTER
SIC Codes: 2671
SIC Code Descriptions: PACKAGING PAPER AND PLASTICS FILM, COATED AND LAMINATED
NAICS Codes: 326112
NAICS Code Descriptions: PLASTICS PACKAGING FILM AND SHEET (INCLUDING LAMINATED) MANUFACTURING.
Conveyor: ICIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 44
Census Block Code: 060650406072014
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude: 34.02607
Longitude: -117.5244
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070389426
Program Acronyms:

NPDES:CAZ502310, RCRAINFO:CAL000348808

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	82 of 89	E	0.00 / 0.00	814.60 / -3	SPACE CENTER 3401 ETIWANDA AVE SUITE 821-A MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID: CAC002996451
Gen Status Universe: No Report
Contact Name: TOM CRUIKSHANK
Contact Address: 3401 ETIWANDA AVE , LEASING OFFICE , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext: 909-685-5221
Contact Email: TCRUIKSHANK@SPACECENTERINC.COM
Contact Country:
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 20190114
Location Latitude: 34.027533
Location Longitude: -117.52902

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190114
Handler Name:	SPACE CENTER
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	3401 ETIWANDA AVE
Name:	SPACE CENTER	***Street 2:***	LEASING OFFICE
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	909-685-5221	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	3401 ETIWANDA AVE
Name:	TOM CRUIKSHANK	***Street 2:***	LEASING OFFICE
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	909-685-5221	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	83 of 89	E	0.00 / 0.00	814.60 / -3	***ECOTECH CONSUMER PRODUCTS*** ***3401 ETIWANDA AVE #921A*** ***ECOTECH CONSUMER PRODUCTS,LLC*** ***MIRA LOMA CA 91752***	***RCRA TSD***

EPA Handler ID:	CAC003011260
Gen Status Universe:	No Report
Contact Name:	EDDIE ZHOU
Contact Address:	3401 ETIWANDA AVE #921A , ECOTECH CONSUMER PRODUCTS,LLC , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	626-699-5573
Contact Email:	EDDIEZHOU@ECOTECHINTL.COM
Contact Country:	
Land Type:	
County Name:	RIVERSIDE
EPA Region:	09
Receive Date:	20190422
Location Latitude:	34.027533
Location Longitude:	-117.52902

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190422
Handler Name:	ECOTECH CONSUMER PRODUCTS
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	11015 HOPKINS STREET
Name:	LYDIA HSU	**Street 2:**	
Date Became Current:		**City:**	MIRA LOMA
Date Ended Current:		**State:**	CA
Phone:	951-681-8888	**Country:**	
Source Type:	Implementer	**Zip Code:**	91752
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	3401 ETIWANDA AVE #921A
Name:	EDDIE ZHOU	**Street 2:**	ECOTECH CONSUMER PRODUCTS,LLC
Date Became Current:		**City:**	MIRA LOMA
Date Ended Current:		**State:**	CA
Phone:	626-699-5573	**Country:**	
Source Type:	Implementer	**Zip Code:**	91752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	84 of 89	E	0.00 / 0.00	814.60 / -3	ECOTECH CONSUMER PRODUCTS 3401 ETIWANDA AVE #921A ECOTECH CONSUMER PRODUCTS,LLC MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID:	CAC003011260
Gen Status Universe:	No Report
Contact Name:	EDDIE ZHOU
Contact Address:	3401 ETIWANDA AVE #921A , ECOTECH CONSUMER PRODUCTS,LLC , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	626-699-5573
Contact Email:	EDDIEZHOU@ECOTECHINTL.COM
Contact Country:	
County Name:	RIVERSIDE
EPA Region:	09

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Land Type:
Receive Date: 20190422
Location Latitude: 34.027533
Location Longitude: -117.52902

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20190422
Handler Name: ECOTECH CONSUMER PRODUCTS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: EDDIE ZHOU
Date Became Current:
Date Ended Current:
Phone: 626-699-5573
Source Type: Implementer
Street No:
Street 1: 3401 ETIWANDA AVE #921A
Street 2: ECOTECH CONSUMER PRODUCTS,LLC
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Owner/Operator Ind: Current Owner
Type: Other
Name: LYDIA HSU
Date Became Current:
Date Ended Current:
Phone: 951-681-8888
Source Type: Implementer
Street No:
Street 1: 11015 HOPKINS STREET
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

1	85 of 89	E	0.00 / 0.00	814.60 / -3	ECOTECH CONSUMER PRODUCTS 3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	FINDS/FRS

Registry ID: 110070576213
FIPS Code: 06065
HUC Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	ECOTECH CONSUMER PRODUCTS,LLC
Create Date:	20-AUG-19
Update Date:	
Interest Types:	OTHER HAZARDOUS WASTE ACTIVITIES, TRANSPORTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	09
County Name:	RIVERSIDE
US/Mexico Border Ind:	
Latitude:	
Longitude:	
Reference Point:	
Coord Collection Method:	
Accuracy Value:	
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070576213
Program Acronyms:	

RCRAINFO:CAC003011260

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	86 of 89	E	0.00 / 0.00	814.60 / -3	EDDIE ZHOU 3401 ETIWANDA AVE #921A MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID:	CAC003057253
Gen Status Universe:	No Report
Contact Name:	EDDIE ZHOU
Contact Address:	3401 ETIWANDA AVE #921A , ECOTECH CONSUMER PRODUCTS,LLC , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	626-699-5573
Contact Email:	EDDIEZHOU@ECOTECHINTL.COM
Contact Country:	
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	
Receive Date:	20200224
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20200224
Handler Name: EDDIE ZHOU
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: EDDIE ZHOU
Date Became Current:
Date Ended Current:
Phone: 626-699-5573
Source Type: Implementer

Street No:
Street 1: 3401 ETIWANDA AVE #921A
Street 2: ECOTECH CONSUMER PRODUCTS,LLC
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Owner/Operator Ind: Current Owner
Type: Other
Name: LYDIA HSU
Date Became Current:
Date Ended Current:
Phone: 951-681-8888
Source Type: Implementer

Street No:
Street 1: 11015 HOPKINS STREET
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	87 of 89	E	0.00 / 0.00	814.60 / -3	NORTH AMERICAN CAR CORPORATION 3401 ETIWANDA AVENUE MIRA LOMA CA 917570000	CERS HAZ

Site ID: 258475
Latitude: 34.026868
Longitude: -117.524359
County:

Regulated Programs

EI ID: CAD091927095
EI Description: Hazardous Waste

Affiliations

Affil Type Desc: Facility Owner
Entity Name: NORTH AMERICAN CAR CORPORATION
Entity Title:
Address: 222 S. RIVERSIDE PLAZA
City: CHICAGO
State: IL
Country:
Zip Code: 606060000
Phone: 3126484000

Affil Type Desc: Facility Contact

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Name: NORTH AMERICAN CAR CORPORATION
Entity Title:
Address: 222 S. RIVERSIDE PLAZA
City: CHICAGO
State: IL
Country:
Zip Code: 606060000
Phone: 3126484000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	88 of 89	E	0.00 / 0.00	814.60 / -3	MIRA LOMA 3401 ETIWANDA AVENUE BUILDING 811 MIRA LOMA CA 91752	RCRA VSQG

EPA Handler ID: CAR000014233
Gen Status Universe: VSG
Contact Name: ROBERT SWITZER
Contact Address: 3401 , ETIWANDA AVENUE , BUILDING 811 , MIRA LOMA , CA, 91752 , US
Contact Phone No and Ext: 615-476-7878
Contact Email:
Contact Country: US
County Name: RIVERSIDE
EPA Region: 09
Land Type: Private
Receive Date: 20200627
Location Latitude: 34.025508
Location Longitude: -117.53094

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960801
Handler Name: CALIFORNIA CUSTOM DESIGN
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 2

Receive Date: 20200627
Handler Name: MIRA LOMA
Federal Waste Generator Code: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D023
Waste Code Description: O-CRESOL

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: D025
Waste Code Description: P-CRESOL

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D037
Waste Code Description: PENTACHLOROPHENOL

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BRE SPACE MIRA LOMA LLC
Date Became Current:
Date Ended Current:
Phone:
Source Type: Notification
Street No: 220
Street 1: COMMERCE DRIVE
Street 2: 4TH FLOOR
City: FORT WASHINGTON
State: PA
Country: US
Zip Code: 19034

Owner/Operator Ind: Current Owner
Type: Private
Name: PREDELIVERY SERVICE CORP
Date Became Current:
Date Ended Current:
Phone: 909-681-2111
Source Type: Notification
Street No:
Street 1: 4500 ETIWANDA AVE BLDG A
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Owner/Operator Ind: Current Operator
Type: Private
Name: BRE SPACE MIRA LOMA LLC
Date Became Current:
Date Ended Current:
Phone:
Source Type: Notification
Street No: 220
Street 1: COMMERCE DRIVE
Street 2: 4TH FLOOR
City: FORT WASHINGTON
State: PA
Country: US
Zip Code: 19034

Historical Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19960801
Generator Code Description: Small Quantity Generator
Handler Name: CALIFORNIA CUSTOM DESIGN

---

1 | **89 of 89** | **E** | **0.00 / 0.00** | **814.60 / -3** | **EDDIE ZHOU**
3401 ETIWANDA AVE #921A
MIRA LOMA CA 91752 | **FINDS/FRS**

Registry ID: 110070804836
FIPS Code: 06065
HUC Code:
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 10-JUN-20
Update Date:
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 326140
NAICS Code Descriptions: POLYSTYRENE FOAM PRODUCT MANUFACTURING.
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: RIVERSIDE
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070804836
Program Acronyms:

RCRAINFO:CAC003057253

---

2 | **1 of 1** | **ESE** | **0.00 / 20.08** | **811.90 / -5** | **CA** | **PFAS GW**

Well ID: 3310021-033
Latitude: 34.024367
Longitude: -117.527412
Data Source(s): Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical: PFOA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctanoic Acid

Chemical: PFOA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctanoic Acid

Chemical: PFOA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctanoic Acid

Chemical: PFOA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	

Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS

Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22

Well Depth (ft):

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-033
Other Names: WELL 22

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-033
Well Type:	MUNICIPAL	***Other Names:***	WELL 22
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-033
Well Type:	MUNICIPAL	**Other Names:**	WELL 22
Well Depth (ft):			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 2	ENE	0.05 / 269.00	827.08 / 10	K-Swiss Sport Shoes Inc. 3177 Space Ctr Jurupa Valley CA 91752	RIVERSIDE HZH

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	2 of 2	ENE	0.05 / 269.00	827.08 / 10	K-Swiss Sport Shoes Inc. 3177 SPACE CTR JURUPA VALLEY CA 91752	CERS HAZ

Site ID:	40908
Latitude:	34.027060
Longitude:	-117.527110
County:	

Regulated Programs

EI ID:	10321045	**EI Description:**	Chemical Storage Facilities

Violations

Violation Date:	09/09/2016	**Violation Source:**	CERS

Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 09/12/2016.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 11/28/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 12/14/2017. 3-7-18: CERS was updated 12-14-17.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 09/09/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 104D] Emergency equipment has been posted appropriately.

Violation Description:

Business Plan Program - Operations/Maintenance - General

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 101C] Approved HMBP accessible on site and available for review.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 104A] NFPA 704 sign(s) have been posted appropriately.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 06/17/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/12/2016.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Enforcements

Enf Action Date: 08/26/2014 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 06/17/2016
Enf Action Program: HMRRP
Enf Action Type: AEO - Unified Program
Enf Action Source: CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Administrative Enforcement Order Based on the Unified Program Statute
Enf Action Notes:

Fines/Penalties Assessed: $1,500.00.

Evaluations

Eval Date: 06/15/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/17/2016
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Non inspection related violation: Failure to submit HMBP electronically.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/09/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure & help w/ CERS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/26/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/28/2017
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: K-Swiss Sport Shoes Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner
Entity Name: K Swiss Inc.
Entity Title:
Address: 3177 Space Ctr
City: Jurupa Valley
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-7500

Affil Type Desc: Environmental Contact
Entity Name: Vidal Menjivar
Entity Title:
Address: 3177 Space Center Ct.
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Identification Signer
Entity Name: Vidal Menjivar
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: K-Swiss Sport Shoes, Inc.
Entity Title:
Address: 3177 Space Ctr
City: Jurupa Valley
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-7500

Affil Type Desc: Operator
Entity Name: Vidal
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 966-0667

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 3177 Space Ctr
City: Jurupa Valley
State: CA
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code: 91752
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of 2	ENE	0.06 / 292.53	826.43 / 9	Gerard Daniel Worldwide Mira Loma 3265 PROGRESS CIR MIRA LOMA CA 91752	CERS HAZ

Site ID: 434645
Latitude: 34.028870
Longitude: -117.526680
County:

Regulated Programs

EI ID: 10757782 **EI Description:** Chemical Storage Facilities

Violations

Violation Date: 02/14/2020 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 04/14/2020.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 02/14/2020 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Riverside County Department of Env Health
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 04/14/2020.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Evaluations

Eval Date: 02/14/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP

Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Legal Owner
Entity Name: GERARD DANIEL WORLDWIDE
Entity Title:
Address: 3265 Progress Cir
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-1111

Affil Type Desc: Identification Signer
Entity Name: Todd Snelbaker
Entity Title: General Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: AEM
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Gerard Daniel Worldwide Mira Loma
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 3265 Progress Cir
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Property Owner
Entity Name: GERARD DANIEL WORLDWIDE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Title:
Address: 13055 Jurupa Avenue
City: Fontana
State: CA
Country: United States
Zip Code: 92337
Phone: (951) 361-1111

Affil Type Desc: Environmental Contact
Entity Name: TODD SNELBAKER
Entity Title:
Address: 3265 Progress Cir
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Operator
Entity Name: GERARD DANIEL WORLDWIDE
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 361-1111

4	2 of 2	ENE	0.06 / 292.53	826.43 / 9	Gerard Daniel Worldwide 3265 Progress Cir Jurupa Valley CA 91752	RIVERSIDE HZH

5	1 of 5	E	0.06 / 336.18	820.57 / 3	Adam Nutrition 11010 Hopkins St #B Jurupa Valley CA 91752	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

5	2 of 5	E	0.06 / 336.18	820.57 / 3	International Vitamin Corporation (IVC) 11010 Hopkins St Ste B Jurupa Valley CA 91752	RIVERSIDE HWG

5	3 of 5	E	0.06 / 336.18	820.57 / 3	International Vitamin Corporation (IVC) 11010 Hopkins St Ste B Jurupa Valley CA 91752	RIVERSIDE HZH

5	4 of 5	E	0.06 / 336.18	820.57 / 3	International Vitamin Corporation 11010 HOPKINS ST #B MIRA LOMA CA 91752	CERS HAZ

Site ID: 3046
Latitude: 34.027600
Longitude: -117.525830
County:

Regulated Programs

EI ID: 10322089 ***EI Description:*** Hazardous Waste Generator

EI ID: 10322089 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 07/27/2017.

Violation Description:

Failure to obtain and/or maintain an Active EPA ID.

Violations

Violation Date: 11/06/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: The chemical inventory description page submitted for all chemicals contained incorrect information. Facility is using the obsolete federal hazard categories. Owner/operator shall update each material listed with the new 24 federal hazard categories. CORRECTIVE ACTION: Owner/operator shall update the chemical inventory page for all chemicals and submit to the statewide information management system (e.g. CERS) at http://cers.calepa.ca.gov. Please refer to a current Safety Data Sheet (SDS) for guidance.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.11 25404.1 - California Health and Safety Code, Chapter 6.11, Section(s) 25404.1
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Failure to obtain and/or maintain an active hazardous waste generator permit.

Violations

Violation Date: 11/06/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: Required NFPA-704 signs were not posted. CORRECTIVE ACTION: Owner/operator shall research chemical safety data sheets and post proper NFPA-704 signs. Signs shall be posted at the entrance of the facility. Submit photos to this department.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/29/2018 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/25/2018.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Enforcements

Enf Action Date: 09/09/2014 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 09/09/2014 ***Enf Action Program:*** HW
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 09/09/2014

Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator @ IVC, 11010 Hopkins; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/06/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to Alfredo Ferradas. - Employee training is completed online annually. ; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/09/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure @ IVC, 11010 Hopkins; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/29/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/29/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/29/2018
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 11/06/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to Alfredo Ferradas. - Facility manufactures protein powder and the following waste streams are generated (laboratory waste from QA/QC): solvent waste (methanol and acetone), acid waste (HCL and nitric acid), electronic waste - Soiled textiles are laundered through Aramark. - Facility's waste hauler is Triumvirate Environmental Services. - Facility has downsized (both staff and production) in the past year and will be reclassified to the 1-10 hazardous waste generator permit category.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Legal Owner
Entity Name: Steven Dai
Entity Title:
Address: 11010 Hopkins Suite B
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-1120

Affil Type Desc: Document Preparer
Entity Name: Alfredo Ferradas
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: International Vitamin Corporation
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Alfredo Ferradas
Entity Title:
Address: 11010 Hopkins Suite B
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	11010 Hopkins Suite B
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	Operator
Entity Name:	IVC-Mira Loma Front Desk
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(951) 361-1120

Affil Type Desc:	Identification Signer
Entity Name:	Alfredo Ferradas
Entity Title:	Operations Supervisor
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	5 of 5	E	0.06 / 336.18	820.57 / 3	INTERNATIONAL VITAMIN CORP 11010 HOPKINS ST MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID:	CAL000401988
Gen Status Universe:	No Report
Contact Name:	ALFREDO FERRADAS
Contact Address:	11010 HOPKINS ST STE B , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	951-749-4449
Contact Email:	ALFREDO.FERRADAS@IVCINC.COM
Contact Country:	
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	
Receive Date:	20141105
Location Latitude:	34.026644
Location Longitude:	-117.525843

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20141105
Handler Name: INTERNATIONAL VITAMIN CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: ALFREDO FERRADAS
Date Became Current:
Date Ended Current:
Phone: 951-749-4449
Source Type: Implementer
Street No:
Street 1: 11010 HOPKINS ST STE B
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Owner/Operator Ind: Current Owner
Type: Other
Name: STEVEN DAI
Date Became Current:
Date Ended Current:
Phone: 951-361-1120
Source Type: Implementer
Street No:
Street 1: 11010 HOPKINS ST
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

6	1 of 1	E	0.07 / 349.18	815.64 / -2	ERIN FELDNER 11015 HOPKINS JURUPA VALLEY CA 91752	RCRA NON GEN

EPA Handler ID: CAC003053670
Gen Status Universe: No Report
Contact Name: ERIN FELDNER
Contact Address: 4 PARK PLAZA, SUITE 900 , , IRVINE , CA, 92614 ,
Contact Phone No and Ext: 949-217-9584
Contact Email: ERIN.FELDNER@AM.JLL.COM
Contact Country:
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 20200130
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20200130
Handler Name: ERIN FELDNER
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: ERIN FELDNER
Date Became Current:
Date Ended Current:
Phone: 949-217-9584
Source Type: Implementer
Street No:
Street 1: 4 PARK PLAZA, SUITE 900
Street 2:
City: IRVINE
State: CA
Country:
Zip Code: 92614

Owner/Operator Ind: Current Owner
Type: Other
Name: BRE SPACE ABLUO LLC
Date Became Current:
Date Ended Current:
Phone: 949-217-9584
Source Type: Implementer
Street No:
Street 1: 11015 HOPKINS
Street 2:
City: JURUPA VALLEY
State: CA
Country:
Zip Code: 91752

7	1 of 3	ESE	0.07 / 361.88	807.55 / -10	**Phillips Lighting N.A.** **11201 Iberia St Ste A** **Jurupa Valley CA 91752**	**DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

7	2 of 3	ESE	0.07 / 361.88	807.55 / -10	**Triways, Inc** **11201 Iberia St #B** **Jurupa Valley CA 91752**	**RIVERSIDE HZH**

7	3 of 3	ESE	0.07 / 361.88	807.55 / -10	**Triways, Inc** **11201 IBERIA ST #B** **MIRA LOMA CA 91752**	**CERS HAZ**

Site ID: 404384
Latitude: 34.023680
Longitude: -117.529010
County:

Regulated Programs

EI ID: 10322107 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 03/16/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 05/30/2017.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 11/05/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Notes:

OBSERVATION: Owner/operator is not meeting the HMBP annual recertification. Last submittal was on 5/2/2019. CORRECTIVE ACTION: Owner/operator shall re certify their HMBP on an annual basis before their permit expiration date (9/30).

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 11/05/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25505(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(c)
Violation Notes:

OBSERVATION: Facility personnel were unable to access/locate a current copy of the business plan during the inspection. CORRECTIVE ACTION: Owner/operator shall ensure a current copy of the hazardous materials business plan is readily available on site at all times when the facility is staffed.

Violation Description:

Failure to have a business plan readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training.

Violations

Violation Date: 03/16/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 05/30/2017.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 11/05/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health

Citation: Un-Specified
Violation Notes:

OBSERVATION: Owner/ operator failed to maintain Safety Data Sheets for all hazardous material stored on site. Specifically, the Safety Data Sheet for diesel and electrolyte/ sulfuric acid was not available on site. CORRECTIVE ACTION: Owner/operator shall have Safety Data Sheets as defined in Title 8 CCR, readily accessible or maintained on site for each hazardous material stored/handled at the facility. Email missing SDS to kestrada@rivco.org for correction.

Violation Description:

Business Plan Program - Administration/Documentation - General Local Ordinance

Violations

Violation Date: 11/05/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

OBSERVATION: The chemical inventory description page submitted for petroleum gas, diesel fuel, and electrolyte/ sulfuric acid contained incorrect information. The federal hazardous classes were not completed for each material. Additionally, the maximum daily amounts for diesel fuel and electrolyte/ sulfuric acid are incorrect. The units were electrolyte/ sulfuric acid are reported in pounds when they should be reported in gallons. CORRECTIVE ACTION: Owner/operator shall update the chemical inventory page for petroleum gas, diesel fuel, and electrolyte/ sulfuric acid and submit to the statewide information management system (e.g. CERS) at http://cers.calepa.ca.gov. Please refer to a current Safety Data Sheet (SDS) for guidance. Confirm the gallonage for the diesel fuel tank and the battery electrolyte with the manufacturer specifications.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 03/16/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 05/30/2017.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 11/05/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

OBSERVATION: Site map submitted in CERS was missing the emergency shut off for gas, water, and electrical. CORRECTIVE ACTION: Owner/operator shall complete an annotated site map which includes all elements outlined in CA Health and Safety Code: north orientation, loading areas, internal roads, adjacent streets, storm and sewer drain, access and exit points, emergency shut offs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. Submit site map into the statewide information management system (e.g. CERS) at http://cers.calepa.ca.gov.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 11/05/2020
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

OBSERVATION: No training records observed/provided during inspection. CORRECTIVE ACTION: Owner/operator shall provide training to all employees. Documentation shall be retained and be made available for inspection for a minimum period of 3 years from the date of the training. Sample training document was emailed to Maria Ortiz. Provide training to employees and submit paperwork to kestrada@rivco.org.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 11/05/2020
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

OBSERVATION: Owner/operator has previously submitted a business plan into the statewide information management system which had one or more sections rejected. Specifically, the facility information section and hazardous materials inventory submittal were rejected for not meeting minimum standards. CORRECTIVE ACTION: Owner/operator shall review the rejection comments attached to the previously submitted business plan, make required corrections, and resubmit corrected sections into the statewide information management system (e.g. CERS) at http://cers.calepa.ca.gov.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 11/05/2020
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

OBSERVATION: The Business Activities page included in the hazardous materials business plan contained incorrect information. Specifically, the hazardous materials question is currently marked as 'NO' when it should be marked as "Yes" CORRECTIVE ACTION: Complete and submit an updated Business Activities page in the statewide information management system (e.g. CERS)at http://cers.calepa.ca.gov. Update the business activities page in CERS and resubmit.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Evaluations

Eval Date: 11/05/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Facility is a warehouse storing propane and lead acid batteries for their fork lifts and diesel fuel for their fire pump.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/16/2017

Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/25/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Identification Signer
Entity Name: Jorge Olmos
Entity Title: Human Resources Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: Jorge Olmos
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: Gary Arredondo
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 361-4840

Affil Type Desc: Environmental Contact
Entity Name: Jorge Olmos
Entity Title:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address:	11201 Iberia st STE B
City:	mira loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	Parent Corporation
Entity Name:	Triways, Inc
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	11201 Iberia st STE B
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	Legal Owner
Entity Name:	John Jauregui
Entity Title:	
Address:	john@tri-way.com
City:	Mira Loma
State:	CA
Country:	United States
Zip Code:	91752
Phone:	(951) 361-4840

Affil Type Desc:	Property Owner
Entity Name:	Space Center
Entity Title:	
Address:	11015 Hopkins St
City:	Mira loma
State:	CA
Country:	United States
Zip Code:	91752
Phone:	(951) 685-5221

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	1 of 2	SE	0.08 / 430.39	806.91 / -10	IBERIA/GM BUILDING #5559 11600 IBERIA ST MIRA LOMA CA 91752	RCRA VSQG

EPA Handler ID:	CAR000278366
Gen Status Universe:	VSG
Contact Name:	ASHLEY CAMPBELL
Contact Address:	5151 , SAN FELIPE ST STE 1000 , , HOUSTON , TX, 77056 , US
Contact Phone No and Ext:	713-958-5472
Contact Email:	ASHLEY.CAMPBELL@STERICYCLE.COM
Contact Country:	US
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	Private
Receive Date:	20171227
Location Latitude:	34.022902
Location Longitude:	-117.526764

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20171227
Handler Name:	IBERIA/GM BUILDING #5559
Federal Waste Generator Code:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	121
Waste Code Description:	Alkaline solution (pH >12.5) with metals (antimony, arsenic, barium, beryllium, cadmium, chromium, cobalt, copper, lead, mercury, molybdenum, nickel, selenium, silver, thallium, vanadium, and zinc)
Hazardous Waste Code:	212
Waste Code Description:	Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Hazardous Waste Code:	223
Waste Code Description:	Unspecified oil-containing waste
Hazardous Waste Code:	331
Waste Code Description:	Off-specification, aged, or surplus organics
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	D016
Waste Code Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Hazardous Waste Code:	D018
Waste Code Description:	BENZENE
Hazardous Waste Code:	D035
Waste Code Description:	METHYL ETHYL KETONE

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**	2455
Type:	Private	**Street 1:**	PACES FERRY RD
Name:	THE HOME DEPOT	**Street 2:**	
Date Became Current:	20171201	**City:**	ATLANTA
Date Ended Current:		**State:**	GA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	30339

Owner/Operator Ind:	Current Owner	**Street No:**	3401
Type:	Private	**Street 1:**	ETIWANDA AVENUE, LEASING OFFICE
Name:	SPACE CENTER MIRA LOMA, INC.	**Street 2:**	
Date Became Current:	20010101	**City:**	MIRA LOMA
Date Ended Current:		**State:**	CA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	91752

8	2 of 2	SE	0.08 / 430.39	806.91 / -10	HD Pro Location #3256 11600 IBERIA ST JURUPA VALLEY CA 91752	CERS HAZ

Site ID: 443395
Latitude: 34.023653
Longitude: -117.533489
County:

Regulated Programs

EI ID:	10752244	**EI Description:**	Hazardous Waste Generator
EI ID:	10752244	**EI Description:**	Chemical Storage Facilities

Affiliations

Affil Type Desc: Legal Owner
Entity Name: The Home Depot U.S.A., Inc.
Entity Title:
Address: 2455 Paces Ferry Road, C-19
City: Atlanta
State: GA
Country: United States
Zip Code: 30339
Phone: (770) 433-8211

Affil Type Desc: Identification Signer
Entity Name: Bryan Chen, Agent for The Home Depot
Entity Title: Regulatory Compliance Specialist
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: The Home Depot USA, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: The Home Depot U.S.A., Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (770) 433-8211

Affil Type Desc: Document Preparer
Entity Name: ARCADIS U.S., Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 213 Court Street, Suite 700 c/o Compliance Dept.
City: Middletown
State: CT
Country:
Zip Code: 06457
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Environmental Contact
Entity Name: ARCADIS U.S., Inc.
Entity Title:
Address: 213 Court Street, Suite 700 c/o Compliance Dept.
City: Middletown
State: CT
Country:
Zip Code: 06457
Phone:

Coordinates

Env Int Type Code: HMBP
Program ID: 10752244
Latitude: 34.022940
Longitude: -117.531470
Coord Name:
Ref Point Type Desc: Center of a facility or station.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	*1 of 6*	*N*	*0.09 / 477.19*	*825.49 / 8*	***Home Depot Distribution IDC #5645*** ***11650 Venture Dr*** ***Jurupa Valley CA 91752***	***RIVERSIDE HZH***
9	*2 of 6*	*N*	*0.09 / 477.19*	*825.49 / 8*	***The Home Depot Store #5645*** ***11650 Venture Dr*** ***Jurupa Valley CA 91752***	***RIVERSIDE HWG***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	3 of 6	N	0.09 / 477.19	825.49 / 8	MILLIKEN SANITARY LANDFILL INTERSECTION: MILLIKEN AVE & MISSION BLV ONTARIO CA 91761	ENVIROSTOR

Estor/EPA ID: 36490106
Site Code: 401055
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6071001400
Site Type: * HISTORICAL
Address Description: INTERSECTION: MILLIKEN AVE & MISSION BLV
Office: CLEANUP CYPRESS
Special Program:
Funding:
Cleanup Status: REFER: RWQCB AS OF 6/1/1995
Cleanup Oversight Agencies: US EPA - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Assembly District:
Senate District:
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN BERNARDINO
Latitude: 34.0633443
Longitude: -117.6508876
Acres: NONE SPECIFIED
Supervisor:

Status: REFER: RWQCB
A2 Program Type: HISTORICAL
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36490106

Completed Activities

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 10/8/1991
Comments: SI Report was reviewed by Region 4 staff. EPA recommended Listing Site Inspection under CERCLA. Report sent to file. Location Information: Site is located in Township 1 South, Range 7 West, Section 36.

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 4/25/1995
Comments: OPEN SITE-REEVALUATION OF HRS (SCORE). NFA FOR DTSC.

Title: Discovery
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Discovery
Date Completed: 4/30/1990
Comments: FACILITY IDENTIFIED EPA CERCLA SCREENING SITE INSPECTION EPA COMPLETED CERCLA SCREENING SITE INSPECTION AND RECOMMEND LISTING SITE INSPECTION. EPA/CERCLA SITE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 10/27/1994
Comments: U.S. EPA is conducting reevaluation of HRS.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	4 of 6	N	0.09 / 477.19	825.49 / 8	The Home Depot Store #5645 11650 VENTURE DR MIRA LOMA CA 91752	CERS HAZ

Site ID: 403850
Latitude: 34.028206
Longitude: -117.536407
County:

Regulated Programs

EI ID: 10140279 **EI Description:** Chemical Storage Facilities

EI ID: 10140279 **EI Description:** Hazardous Waste Generator

Violations

Violation Date: 06/22/2018 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 12/12/2018. 03 reinspection performed on 12-12-18 for this program.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 09/12/2014 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 10/01/2014. [LOCAL ORDINANCE VIOLATION 101C] Approved HMBP accessible on site and available for review.

Violation Description:

Business Plan Program - Administration/Documentation - General

Enforcements

Enf Action Date: 09/12/2014 **Enf Action Program:** HMRRP
Enf Action Type: Notice of Violation (Unified Program) **Enf Action Source:** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 09/12/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 09/12/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/22/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 213 Court Street, Suite 700 c/o Compliance Dept.
City: Middletown
State: CT
Country:
Zip Code: 06457

Phone:

Affil Type Desc: Legal Owner
Entity Name: The Home Depot U.S.A., Inc.
Entity Title:
Address: 2455 Paces Ferry Road, C-19
City: Atlanta
State: GA
Country: United States
Zip Code: 30339
Phone: (770) 433-8211

Affil Type Desc: Parent Corporation
Entity Name: The Home Depot USA, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: ARCADIS U.S., Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: ARCADIS U.S., Inc.
Entity Title:
Address: 213 Court Street, Suite 700 c/o Compliance Dept.
City: Middletown
State: CT
Country:
Zip Code: 06457
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Identification Signer
Entity Name: John Falcetti, Agent for The Home Depot
Entity Title: Regulatory Compliance Specialist
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: The Home Depot U.S.A., Inc.
Entity Title:
Address:
City:
State:
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code:
Phone: (770) 433-8211

Coordinates

Env Int Type Code:	HMBP	***Longitude:***	-117.536410
Program ID:	10140279	***Coord Name:***	
Latitude:	34.028210	***Ref Point Type Desc:***	Center of a facility or station.

9	5 of 6	N	0.09 / 477.19	825.49 / 8	**HOME DEPOT USA INC HD 5645** **11650 VENTURE DRIVE** **MIRA LOMA CA 91761**	RCRA SQG

EPA Handler ID:	CAR000168153
Gen Status Universe:	Small Quantity Generator
Contact Name:	ROBERT PERKINS
Contact Address:	1905 ASTON AVE , STE 100 , CARLSBAD , CA, 92008 , US
Contact Phone No and Ext:	760-602-8700
Contact Email:	RPERKINS@3ECOMPANY.COM
Contact Country:	US
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	Private
Receive Date:	20050629
Location Latitude:	34.029661
Location Longitude:	-117.536409

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20050629
Handler Name:	HOME DEPOT USA INC HD 5645
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code: D001

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2455 PACES FERRY RD
Name:	HOME DEPOT USA	**Street 2:**	
Date Became Current:	20001106	**City:**	ATLANTA
Date Ended Current:		**State:**	GA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	30339

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	HOME DEPOT USA	**Street 2:**	
Date Became Current:	20001106	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	6 of 6	N	0.09 / 477.19	825.49 / 8	MARCH COMMUNICATION ANNEX #2 SAN BERNARDINO/RIVERSIDE COUNTY LINES CA	FUDS

FUDS No:	J09CA0120	**EPA Region:**	09
INST ID:	CA99799F532300	**CONG DIST:**	35
Object ID:	4652	**County:**	SAN BERNARDINO
NPL Status:	Not Listed	**County Code:**	Los Angeles District (SPL)
Status:	Properties without projects	**Latitude:**	34.03694444
FY:	2018	**Longitude:**	-117.52638889
Eligibility:	Eligible	**Has Projects:**	No
Current Owner:	Local Government; Other Federal Government; Private Sector		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=60976					
10	1 of 1	ENE	0.09 / 478.31	828.63 / 11	POWER TRAIN PLUS 3227 PROGRESS CIR MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID: CAL000311608
Gen Status Universe: No Report
Contact Name: DARYLL LYNNES
Contact Address: 3227 PROGRESS CIR , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext: 951-681-9215
Contact Email: POWERTRAINPLUS@SBCGLOBAL.NET
Contact Country:
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 20060915
Location Latitude: 34.029356
Location Longitude: -117.526169

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20060915
Handler Name: POWER TRAIN PLUS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: DARYLL LYNNES
Date Became Current:
Date Ended Current:
Phone: 951-681-9215
Source Type: Implementer

Street No:
Street 1: 3227 PROGRESS CIR
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	23855 HAZELWOOD DR
Name:	DARYLL LYNNES	**Street 2:**	
Date Became Current:		**City:**	MORENO VALLEY
Date Ended Current:		**State:**	CA
Phone:	951-681-9215	**Country:**	
Source Type:	Implementer	**Zip Code:**	92557-0000

11	1 of 1	SE	0.10 / 512.45	805.90 / -11	Jurupa Community Svcs Dist(Site 25) 11561 IBERIA ST JURUPA VALLEY CA 91752	CERS TANK

Site ID:	40748	**Latitude:**	34.022985
Longitude:	-117.531166		

Regulated Programs

EI ID:	10327060
EI Description:	Aboveground Petroleum Storage

EI ID:	10327060
EI Description:	Chemical Storage Facilities

Evaluations

Eval Date:	06/27/2016
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	10/01/2019
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Facility uses diesel for generator and hypochlorite for water treatment. No violations observed during inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	04/29/2020
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

Eval Date:	02/02/2017
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health

Eval Program: APSA
Eval Source: CERS
Eval Notes:

APSA - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 11201 Harrel St
City: Jurupa Valley
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Jurupa Community Svcs Dist(Site 25)
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Jurupa Community Services Dist
Entity Title:
Address: 11201 Harrell St
City: Jurupa Valley
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 685-7434

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Environmental Contact
Entity Name: Jaime Godoy
Entity Title:
Address: 11201 Harrel Street
City: Mira Loma
State: CA
Country:
Zip Code: 91752
Phone:

Affil Type Desc: Operator
Entity Name: Jurupa Community Services District
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 685-7434

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Document Preparer
Entity Name: Jaime Godoy
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Jaime Godoy
Entity Title: Facilities/Fleet Supervisor
Address:
City:
State:
Country:
Zip Code:
Phone:

Coordinates

Env Int Type Code: HMBP
Program ID: 10327060
Latitude: 34.022990
Longitude: -117.531170
Coord Name:
Ref Point Type Desc: Center of a facility or station.

12	1 of 1	SE	0.10 / 515.85	806.16 / -11	Jurupa Community Svcs Dist(Site 25) 11561 Iberia St Jurupa Valley CA 91752	RIVERSIDE HZH

13	1 of 2	ESE	0.10 / 537.28	804.83 / -13	AMAZON.COM SERVICES LLC ONT1 11200 IBERIA STREET MIRA LOMA CA 91752	RCRA SQG

EPA Handler ID: CAR000311282
Gen Status Universe: Small Quantity Generator
Contact Name: NATALIE WAID
Contact Address: PO BOX 80842 , , SEATTLE , WA, 98108 , US
Contact Phone No and Ext: 206-266-1036
Contact Email: WAIDNATA@AMAZON.COM
Contact Country: US
County Name: RIVERSIDE
EPA Region: 09
Land Type: Private
Receive Date: 20200828
Location Latitude: 34.022902
Location Longitude: -117.526764

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No

Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200828
Handler Name:	AMAZON.COM SERVICES LLC ONT1
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Hazardous Waste Code:	122
Waste Code Description:	Alkaline solution without metals (pH > 12.5)
Hazardous Waste Code:	123
Waste Code Description:	Unspecified alkaline solution
Hazardous Waste Code:	131
Waste Code Description:	Aqueous solution (2 < pH < 12.5) containing reactive anions (azide, bromate, chlorate, cyanide, fluoride, hypochlorite, nitrite, perchlorate, and sulfide anions)
Hazardous Waste Code:	135
Waste Code Description:	Unspecified aqueous solution
Hazardous Waste Code:	141
Waste Code Description:	Off-specification, aged, or surplus inorganics
Hazardous Waste Code:	181
Waste Code Description:	Other inorganic solid waste
Hazardous Waste Code:	213
Waste Code Description:	Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)
Hazardous Waste Code:	214
Waste Code Description:	Unspecified solvent mixture
Hazardous Waste Code:	221
Waste Code Description:	Waste oil and mixed oil
Hazardous Waste Code:	223
Waste Code Description:	Unspecified oil-containing waste
Hazardous Waste Code:	281
Waste Code Description:	Adhesives
Hazardous Waste Code:	311
Waste Code Description:	Pharmaceutical waste
Hazardous Waste Code:	331
Waste Code Description:	Off-specification, aged, or surplus organics
Hazardous Waste Code:	343
Waste Code Description:	Unspecified organic liquid mixture
Hazardous Waste Code:	352

Waste Code Description: Other organic solids

Hazardous Waste Code: 512
Waste Code Description: Other empty containers 30 gallons or more

Hazardous Waste Code: 513
Waste Code Description: Empty containers less than 30 gallons

Hazardous Waste Code: 561
Waste Code Description: Detergent and soap

Hazardous Waste Code: 725
Waste Code Description: Liquids with mercury > 20 mg/l

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D024
Waste Code Description: M-CRESOL

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U129
Waste Code Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U205
Waste Code Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	220
Type:	Private	***Street 1:***	COMMERCE DRIVE 4TH FLOOR
Name:	SPACE CENTER MIRA LOMA, INC	***Street 2:***	
Date Became Current:	20200409	***City:***	FORT WASHINGTON
Date Ended Current:		***State:***	PA
Phone:	951-685-5221	***Country:***	US
Source Type:	Notification	***Zip Code:***	19034

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 80842
Name:	AMAZON.COM SERVICES LLC	***Street 2:***	
Date Became Current:	20200721	***City:***	SEATTLE
Date Ended Current:		***State:***	WA
Phone:	206-266-1036	***Country:***	US
Source Type:	Notification	***Zip Code:***	98108

13	*2 of 2*	*ESE*	*0.10 / 537.28*	*804.83 / -13*	***Amazon.com Services LLC - ONT1*** ***11200 IBERIA ST*** ***JURUPA VALLEY CA 91752***	***CERS TANK***

Site ID: 568973 ***Latitude:*** 34.021640
Longitude: -117.530320

Regulated Programs

EI ID: 10853563
EI Description: Hazardous Waste Generator

EI ID: 10853563
EI Description: Chemical Storage Facilities

EI ID: 10853563
EI Description: Aboveground Petroleum Storage

Affiliations

Affil Type Desc: Document Preparer
Entity Name: Hunter Gowans
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO Box 80842
City: Seattle
State: WA
Country:
Zip Code: 98108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Legal Owner
Entity Name: Amazon.com Services LLC
Entity Title:
Address: PO Box 80842
City: Seattle
State: WA
Country: United States
Zip Code: 98108
Phone: (916) 606-1485

Affil Type Desc: Operator
Entity Name: Amazon.com Services LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (916) 606-1485

Affil Type Desc: Parent Corporation
Entity Name: Amazon.com Services LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Amber Nickens
Entity Title:
Address: PO Box 80842
City: Seattle
State: WA
Country:
Zip Code: 98108
Phone:

Affil Type Desc: Identification Signer
Entity Name: Hunter Gowans
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

14	1 of 1	W	0.11 / 562.98	820.73 / 3	CONSOLIDATE FREIGHTWAYS 11888 MISSION MIRA LOMA CA 91752	RCRA SQG

EPA Handler ID: CAD981574122
Gen Status Universe: Small Quantity Generator

Contact Name:
Contact Address: US
Contact Phone No and Ext:
Contact Email:
Contact Country: US
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 19960901
Location Latitude: 34.026224
Location Longitude: -117.544999

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Jan, 2021.

Evaluation Details

Evaluation Start Date: 19921128
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:
Return to Compliance Date:
Evaluation Agency: State Contractor/Grantee

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19860930
Handler Name: CONSOLIDATE FREIGHTWAYS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960901
Handler Name: CONSOLIDATE FREIGHTWAYS
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19960901
Handler Name: CONSOLIDATE FREIGHTWAYS
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: NOT REQUIRED
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:
Zip Code: 99999

Owner/Operator Ind: Current Owner
Type: Private
Name: CONSOLIDATED FREIGHTWAYS
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:
Zip Code: 99999

Historical Handler Details

Receive Dt: 19960901
Generator Code Description: Large Quantity Generator
Handler Name: CONSOLIDATE FREIGHTWAYS

Receive Dt: 19860930
Generator Code Description: Large Quantity Generator
Handler Name: CONSOLIDATE FREIGHTWAYS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	1 of 3	SSW	0.12 / 619.96	802.44 / -15	Mobile Modular 11450 Mission Blvd Jurupa Valley CA 91752	RIVERSIDE HWG

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	2 of 3	SSW	0.12 / 619.96	802.44 / -15	Mobile Modular 11450 MISSION BLVD MIRA LOMA CA 91752	CERS HAZ

Site ID: 397724
Latitude: 34.021625
Longitude: -117.535434
County:

Regulated Programs

EI ID: 10326655
EI Description: Chemical Storage Facilities

EI ID: 10326655
EI Description: Hazardous Waste Generator

Violations

Violation Date: 11/13/2020
Violation Program: HW
Violation Source: CERS
Violation Division: Riverside County Department of Env Health
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: No manifests (for latex paint) available during inspection. CORRECTIVE ACTION: Owner/operator shall obtain all manifests for hazardous waste shipments which occurred in the past 3 years. Manifests shall be made available for inspection.

Violation Description:

Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.

Violations

Violation Date: 11/13/2020 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: Observed the intermediate bulk container (tote) holding latex paint waste on site with accumulation start date of 09/06/2018. CORRECTIVE ACTION: Owner/operator shall ensure all hazardous wastes are transported off site within 180 days of the accumulation start date. Owner/operator shall have latex paint waste properly hauled off site by a registered hazardous waste transporter.

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met:
(1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violations

Violation Date: 11/13/2020 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: Observed boxes holding fluorescent light bulbs that were missing proper labels. CORRECTIVE ACTION: Owner/operator shall label universal waste containers with all the required information. Label shall include at least: the words ""universal waste"" and accumulation start date. Submit photos to this department, if applicable.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 09/05/2014 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: 22 CCR 23 66273.34 - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.34
Violation Notes:

Returned to compliance on 09/12/2017.

Violation Description:

Failure to properly label the following categories of universal waste as:
1) Each batteries or the container in which the batteries are contained as "Universal Waste-Battery(ies)".
2) Each mercury-containing equipment or the container in which the mercury-containing equipment is contained as "Universal Waste -Mercury-Containing Equipment".
3) Each Florescent lamp or the container or package in which the lamps are contained as "Universal Waste-Lamp(s)".
4) Each electronic devices or the container or pallet in or on which the electronic devices are contained as "Universal Waste-Electronic Device(s)".

5) Each CRTs or the container or pallet in or on which the CRTs are contained as "Universal Waste-CRT(s)".
6) A container of CRT glass shall be labeled or marked clearly with the following phrase: "Universal Waste-CRT glass".
7) In lieu of labeling individual electronic devices, CRTs, and/or containers of CRT glass pursuant to subsections d) through f) of this section, a universal waste handler may combine, package, and accumulate those universal wastes in appropriate containers or within a designated area demarcated by boundaries that are clearly labeled with the applicable portion(s) of the following phrase: "Universal Waste-Electronic Device(s)/Universal Waste - CRT (s)/Universal Waste-CRT Glass".

Enforcements

Enf Action Date: 09/05/2014
Enf Action Program: HW
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Source: CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 11/17/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/13/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to the e-mail address provided by the Safety Coordinator. - Facility rents/sells modulars and the following waste streams are generated (not limited to): latex paint, fluorescent light bulbs, contaminated absorbent. - Due to manifests not being available for the latex paint, the following violations were marked NA: 38, 40,41,42, 48 ; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/13/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to the e-mail address provided by the Safety Coordinator. - Facility rents/sells modulars. - Facility's SDSs are online. - Facility conducts employee training online (annually) and also conduct weekly refresher trainings (in person) - A copy of the hazardous material business plan was provided to the Safety Coordinator during the inspection. ; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/05/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval Notes:

generator; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/17/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/05/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Legal Owner
Entity Name: Mobile Modular
Entity Title:
Address: 11450 Mission Blvd
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 360-6600

Affil Type Desc: Document Preparer
Entity Name: Phil Couto
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: Mobile Modular Managment Corp
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (951) 360-6600

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 11450 Mission Blvd
City: Mira Loma
State: CA
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code: 91752
Phone:

Affil Type Desc: Identification Signer
Entity Name: Phil Couto
Entity Title: EHS Director
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Mobile Modular
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Property Owner
Entity Name: McGrath RentCorp
Entity Title:
Address: 5700 Las Positas Road
City: Livermore
State: CA
Country: United States
Zip Code: 94551
Phone: (925) 453-6069

Affil Type Desc: Environmental Contact
Entity Name: Phil Couto
Entity Title:
Address: 5700 Las Positas Road
City: Livermore
State: CA
Country:
Zip Code: 94551
Phone:

Coordinates

Env Int Type Code: HMBP
Program ID: 10326655
Latitude: 34.021630
Longitude: -117.535430
Coord Name:
Ref Point Type Desc: Center of a facility or station.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	3 of 3	SSW	0.12 / 619.96	802.44 / -15	MOBILE MODULAR MANAGEMENT CORP 11450 MISSION BLVD MIRA LOMA CA 91752	RCRA NON GEN

EPA Handler ID: CAL000298572
Gen Status Universe: No Report
Contact Name: MIGUEL PINTO

Contact Address: 11450 MISSION BLVD , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext: 951-360-5142
Contact Email: MIGUEL.PINTO@MOBILEMODULAR.COM
Contact Country:
County Name: RIVERSIDE
EPA Region: 09
Land Type:
Receive Date: 20050919
Location Latitude: 34.021576
Location Longitude: -117.535372

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050919
Handler Name: MOBILE MODULAR MANAGEMENT CORP
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: MCGRATH RENT CORPORATION
Date Became Current:
Date Ended Current:
Phone: 925-606-9200
Source Type: Implementer
Street No:
Street 1: 5700 LAS POSITAS RD
Street 2:
City: LIVERMORE
State: CA
Country:
Zip Code: 94551-0000

Owner/Operator Ind: Current Operator
Type: Other
Name: MIGUEL PINTO
Date Became Current:
Date Ended Current:
Phone: 951-360-5142
Source Type: Implementer
Street No:
Street 1: 11450 MISSION BLVD
Street 2:
City: MIRA LOMA
State: CA
Country:
Zip Code: 91752

16	1 of 1	SSE	0.12 / 644.66	804.51 / -13	PROPAK LOGISTICS, INC. REVERSE LOGISTICS	EMISSIONS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					11555 IBERIA ST MIRA LOMA CA 91752	

2015 Toxic Data

Facility ID:	158249	***COID:***	RIV
Facility SIC Code:	9999	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of 4	ENE	0.13 / 688.25	832.09 / 15	FLYERS #462 11074 INLAND AVENUE JURUPA VALLEY CA 91752	LUST

Global ID:	T10000007147	***County:***	RIVERSIDE
Status:	COMPLETED - CASE CLOSED	***Latitude:***	34.0297110675738
Status Date:	2/3/2017	***Longitude:***	-117.526488512897
Case Type:	LUST CLEANUP SITE		
Date Source:	LUST Cleanup Sites from GeoTracker Search; LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download		

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail(as Nov 16 2020)

RB Case No:		***Potential COC:***	Diesel
Local Case No:	2015RO6600626	***How Discovered:***	Subsurface Monitoring
Begin Date:	7/15/2015	***Stop Method:***	Replace product piping
Lead Agency:	RIVERSIDE COUNTY LOP	***Stop Description:***	upgrade product piping
Local Agency:		***Case Worker:***	
CUF Case:	YES	***File Location:***	Local Agency
Potential Media of Concern:	Soil		
How Discovered Description:	soil samples taken and analyzed during piping upgrade		
Calwater Watershed Name:	Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)		
DWR GW Subbasin Name:	Upper Santa Ana Valley - Chino (8-002.01)		
Disadvantaged Community:			
Site History:			

SITE HISTORY/RELEASE INFORMATION: June 15, 2015--Six soil samples were taken at the under-dispenser sumps at the point of connection during a product piping replacement project. The soil sample taken under dispenser 15 at feet had 17300 ppm TPHd, 121 ppb ethylbenzene, 7.9J ppb total xylenes, 530 ppb 1,3,5-TMB, 85.9 ppb n-butylbenzene, and 5.2J ppb naphthalene. The site was placed into LOP July 15, 2015. ASSESSMENT: November 3, 2015--Three soil borings (SP-1 through SP-3) were drilled surrounding dispenser 15. SB-1 was drilled to 50 feet, SB-2 was drilled to 29 feet where it hit refusal and SB-3 was drilled to 70 feet. Hydrocarbons were limited to between 3 and 20 feet bgs in all three borings and the site was defined vertically. TPHd in SB-1 was detected at 2900, 6000, 6700 and 2800 ppm at 5, 10, 15, and 20 feet and TPHg was detected at 1800, 340, 390 and 300 ppm at 5, 10, 15 and 20 feet. TPHd in SB-2 was detected at 250, 14000, 1000 and 3500 at 3, 5, 10, and 15 feet and TPHg was detected at 3300, 120 and 180 ppm at 5, 10 and 15 feet. TPHd in SB-3 was detected at 9100, 1500, 4100, and 2200 ppm at 5, 10, 15, and 20 feet and TPHg was detected at 1300, 420, 200 and 110 ppm at 5, 10, 15, and 20 feet. No Benzene or MTBE was detected in any of the soil samples. Additional lateral assessment was requested. February 22, 2016-- Three soil borings(SB-4 through SB-6) were completed to 40 feet bgs using direct push technologies surrounding the original three borings. A total of 24 soil samples were collected at depths ranging from 5 to 40 feet bgs. No analyte was detected above the laboratory reporting limit in the soil samples. Groundwater was not encountered. REMEDIATION: No active remediation was completed. GROUNDWATER:: Groundwater was not encountered in the 70 foot depth explored and is anticipated to be greater than 200 feet bgs. CLOSEST WELLS: According to GeoTracker, six wells are located within 1/2 mile with the closest well at 1300 feet from the site MASS REMAINING IN-SITU: TPHd is soil is limited in extent near dispenser island pump #15 and has been delineated to a vertical extent of 25 feet or less and laterally between 20 to 60 feet from dispenser #15. Other information: The site is a card lock fueling facility and is expected to remain in use as a commercial petroleum fueling facility in the future. A UST system is currently installed and operating at the site. The piping were replaced in June 2015 and the leak has been stopped. The site has been adequately characterized. Residual impacts remain at the site between 3 and 20 feet bgs in the soils near dispenser #15. No water wells, surface waters, or other sensitive receptors are likely to be impacted.

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity(as Nov 16 2020)

Action Type:	ENFORCEMENT

Date : 2/3/2017
Action: File review - #RCDEH uploaded site file

Action Type: ENFORCEMENT
Date : 2/3/2017
Action: Closure/No Further Action Letter - #RCDEH site closure

Action Type: RESPONSE
Date : 1/16/2017
Action: Email Correspondence

Action Type: RESPONSE
Date : 11/18/2016
Action: Correspondence

Action Type: ENFORCEMENT
Date : 8/19/2016
Action: Staff Letter - #RCDEH 081916

Action Type: ENFORCEMENT
Date : 6/2/2016
Action: LOP Case Closure Summary to RB - #RCDEH

Action Type: RESPONSE
Date : 4/1/2016
Action: Request for Closure - Regulator Responded

Action Type: RESPONSE
Date : 3/29/2016
Action: Site Assessment Report

Action Type: ENFORCEMENT
Date : 3/23/2016
Action: File review - #RCDEH site summary

Action Type: ENFORCEMENT
Date : 1/7/2016
Action: File review - #RCDEH uploaded site file 1/7/2016

Action Type: RESPONSE
Date : 12/11/2015
Action: Preliminary Site Assessment Report - Regulator Responded

Action Type: RESPONSE
Date : 9/30/2015
Action: Preliminary Site Assessment Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date : 9/10/2015
Action: Notice of Responsibility - #RCDEH 091015

Action Type: ENFORCEMENT
Date : 7/28/2015
Action: Staff Letter - #RCDEH 072815

Action Type: Other
Date : 7/15/2015
Action: Leak Discovery

Action Type: Other
Date : 7/15/2015
Action: Leak Reported

Action Type: Other
Date : 6/15/2015
Action: Leak Stopped

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History(as Nov 16 2020)

Status: Completed - Case Closed
Status Date: 2/3/2017

Status: Open - Eligible for Closure
Status Date: 5/26/2016

Status: Open - Case Begin Date
Status Date: 7/15/2015

Status: Open - Site Assessment
Status Date: 7/15/2015

LUST Sites from GeoTracker Search - Regulatory Profile (as of Oct 06, 2020)

Site Facility Name: FLYERS #462
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig: C
CUF Amount Paid: $20,500
Potential COC: DIESEL
Facility Type:
Composting Method:
Address: 11074 INLAND AVENUE
City: JURUPA VALLEY
Zip: 91752
County: RIVERSIDE
CUF Claim: 20316
File Location: LOCAL AGENCY
Designated Beneficial Use: MUN, AGR, IND, PROC
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000007147
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 2/3/2017
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000007147&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Santa Ana Valley - Chino (8-002.01)
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
Post Closure Site Management: NOTIFY PRIOR TO CHANGE IN LAND USE
NOTIFY PRIOR TO DEVELOPMENT
Future Land Use: COMMERCIAL
Cleanup Oversight Agencies: RIVERSIDE COUNTY LOP (LEAD) - CASE #: 2015RO6600626
SANTA ANA RWQCB (REGION 8)
CASEWORKER: Ken Williams
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply
Site History:

SITE HISTORY/RELEASE INFORMATION:

June 15, 2015--Six soil samples were taken at the under-dispenser sumps at the point of connection during a product piping replacement project. The soil sample taken under dispenser 15 at feet had 17300 ppm TPHd, 121 ppb ethylbenzene, 7.9J ppb total xylenes, 530 ppb 1,3,5-TMB, 85.9 ppb n-butylbenzene, and 5.2J ppb naphthalene. The site was placed into LOP July 15, 2015.

ASSESSMENT:

November 3, 2015--Three soil borings (SP-1 through SP-3) were drilled surrounding dispenser 15. SB-1 was drilled to 50 feet, SB-2 was drilled to 29 feet where it hit refusal and SB-3 was drilled to 70 feet. Hydrocarbons were limited to between 3 and 20 feet bgs in all three borings and the site was defined vertically. TPHd in SB-1 was detected at 2900, 6000, 6700 and 2800 ppm at 5, 10, 15, and 20 feet and TPHg was detected at 1800, 340, 390 and 300 ppm at 5, 10, 15 and 20 feet. TPHd in SB-2 was detected at 250, 14000, 1000 and 3500 at 3, 5, 10, and 15 feet and TPHg was detected at 3300, 120 and 180 ppm at 5, 10 and 15 feet. TPHd in SB-3 was detected at 9100, 1500, 4100, and 2200 ppm at 5, 10, 15, and 20 feet and TPHg was detected at 1300, 420, 200 and 110 ppm at 5, 10, 15, and 20 feet. No Benzene or MTBE was detected in any of the soil samples. Additional lateral assessment was requested.

February 22, 2016-- Three soil borings(SB-4 through SB-6) were completed to 40 feet bgs using direct push technologies surrounding the original three borings. A total of 24 soil samples were collected at depths ranging from 5 to 40 feet bgs. No analyte was detected above the laboratory reporting limit in the soil samples. Groundwater was not encountered.

REMEDIATION:

No active remediation was completed.

GROUNDWATER::

Groundwater was not encountered in the 70 foot depth explored and is anticipated to be greater than 200 feet bgs.

CLOSEST WELLS:
According to GeoTracker, six wells are located within 1/2 mile with the closest well at 1300 feet from the site

MASS REMAINING IN-SITU:
TPHd is soil is limited in extent near dispenser island pump #15 and has been delineated to a vertical extent of 25 feet or less and laterally between 20 to 60 feet from dispenser #15.

Other information:

The site is a card lock fueling facility and is expected to remain in use as a commercial petroleum fueling facility in the future. A UST system is currently installed and operating at the site. The piping were replaced in June 2015 and the leak has been stopped. The site has been adequately characterized. Residual impacts remain at the site between 3 and 20 feet bgs in the soils near dispenser #15. No water wells, surface waters, or other sensitive receptors are likely to be impacted.

LUST Sites from GeoTracker Search - Cleanup Status History (as of Oct 06, 2020)

Status: Completed - Case Closed
Date : 2/3/2017

Status: Open - Eligible for Closure
Date : 5/26/2016

Status: Open - Case Begin Date
Date : 7/15/2015

Status: Open - Site Assessment
Date : 7/15/2015

LUST Sites from GeoTracker Search - Regulatory Activities (as of Oct 06, 2020)

Action Type: Other Regulatory Actions
Action Date: 2/3/2017
Received Issue Date: 2/3/2017
Action: Closure/No Further Action Letter - #RCDEH site closure
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6312922&temptable=ENFORCEMENT
Title Description Comments:

Site Closure

Action Type: Other Regulatory Actions
Action Date: 2/3/2017
Received Issue Date: 2/3/2017
Action: File review - #RCDEH uploaded site file
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6276249&temptable=ENFORCEMENT
Title Description Comments:

RCDEH uploaded site file 02/03/2017

Action Type: Response Requested - Other
Action Date: *1/16/2017
Received Issue Date: 1/16/2017
Action: Email Correspondence
Doc Link:
Title Description Comments:

60 day public comment period over - RCDEH did not receive Public Comments regarding this site

Action Type: Response Requested - Other
Action Date: *11/18/2016
Received Issue Date: 2/8/2017
Action: Correspondence
Doc Link:
Title Description Comments:

record of distribution - RCDEH received and reviewed the Public Notice Record of Distribution

Action Type: Other Regulatory Actions
Action Date: 8/19/2016
Received Issue Date: 8/19/2016
Action: Staff Letter - #RCDEH 081916
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6295561&temptable=ENFORCEMENT
Title Description Comments:

RCDEH sent out pre-closure letter and docs

Action Type: Other Regulatory Actions
Action Date: 6/2/2016
Received Issue Date: 6/2/2016
Action: LOP Case Closure Summary to RB - #RCDEH
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6286587&temptable=ENFORCEMENT
Title Description Comments:

RCDEH requested closure concurrence from RB

Action Type: Response Requested - Other
Action Date: 4/1/2016
Received Issue Date: 4/1/2016
Action: Request for Closure - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000007147&doc_id=5890005
Title Description Comments:

Soil Investigation Report and Request for No Further Action - RCDEH determined site is ready for closure.

Action Type: Response Requested - Reports
Action Date: 3/29/2016
Received Issue Date: 4/1/2016
Action: Site Assessment Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000007147&doc_id=5877088
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 3/23/2016
Received Issue Date: 3/23/2016
Action: File review - #RCDEH site summary
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6280088&temptable=ENFORCEMENT
Title Description Comments:

RCDEH site summary 3/23/2016

Action Type: Other Regulatory Actions
Action Date: 1/7/2016
Received Issue Date: 1/7/2016
Action: File review - #RCDEH uploaded site file 1/7/2016
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6271937&temptable=ENFORCEMENT
Title Description Comments:

RCDEH uploaded site file 1/7/2016

Action Type: Response Requested - Reports
Action Date: 12/11/2015
Received Issue Date: 1/5/2016
Action: Preliminary Site Assessment Report - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000007147&doc_id=5862228
Title Description Comments:

Action Type: Response Requested - Workplans
Action Date: 9/30/2015
Received Issue Date: 10/1/2015
Action: Preliminary Site Assessment Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000007147&doc_id=5851511
Title Description Comments:

Action Type: Notices
Action Date: 9/10/2015
Received Issue Date: 9/10/2015
Action: Notice of Responsibility - #RCDEH 091015
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6260070&temptable=ENFORCEMENT
Title Description Comments:

additional RP for site letters

Action Type: Other Regulatory Actions
Action Date: 7/28/2015
Received Issue Date: 7/28/2015
Action: Staff Letter - #RCDEH 072815
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6255705&temptable=ENFORCEMENT
Title Description Comments:

new site letters sent out

Action Type: Leak Action
Action Date: 7/15/2015
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 7/15/2015
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 6/15/2015
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

LUST Sites from GeoTracker Search - Site Maps (as of Oct 06, 2020)

Title: SOIL INVESTIGATION REPORT AND REQUEST FOR NO FURTHER ACTION (SB-4)

Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8409849703/T10000007147.PDF
Size : 63 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: SOIL INVESTIGATION REPORT AND REQUEST FOR NO FURTHER ACTION (SB-5)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3993516921/T10000007147.PDF
Size : 66 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8680045783/T10000007147.PDF
Size : 216 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: SOIL INVESTIGATION REPORT AND REQUEST FOR NO FURTHER ACTION (SB-6)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7521501541/T10000007147.PDF
Size : 67 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: SOIL INVESTIGATION REPORT AND SOIL INVESTIGATION WORK PLAN (SB-2)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9747709810/T10000007147.PDF
Size : 466 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: SOIL INVESTIGATION REPORT AND SOIL INVESTIGATION WORK PLAN (SB-3)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8303976476/T10000007147.PDF
Size : 655 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

Title: SOIL INVESTIGATION REPORT AND SOIL INVESTIGATION WORK PLAN (SB-1)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5992033541/T10000007147.PDF
Size : 423 KB
Submitted By: GREG MCIVER (AUTH_RP)
Submitted: 6/21/2016

LUST Sites from GeoTracker Search - Documents (as of Oct 06, 2020)

Document Type: Site Documents
Document Date: 2/3/2017
Type: CLOSURE/NO FURTHER ACTION LETTER
Title: SITE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6312922
Size :
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 2/3/2017
Type: FILE REVIEW
Title: RCDEH UPLOADED SITE FILE 02/03/2017
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6276249
Size :
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 8/19/2016
Type: STAFF LETTER
Title: RCDEH SENT OUT PRE-CLOSURE LETTER AND DOCS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6295561
Size :
Submitted By: LINDA SHURLOW (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 6/2/2016
Type: LOP CASE CLOSURE SUMMARY TO RB
Title: RCDEH REQUESTED CLOSURE CONCURRENCE FROM RB
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6286587
Size :
Submitted By: LINDA SHURLOW (REGULATOR)
Submitted:

Document Type: Site Documents
Size : 15,903 KB

Document Date: 4/1/2016 **Submitted By:** GREG MCIVER (AUTH_RP)
Type: REQUEST FOR CLOSURE **Submitted:**
Title: SOIL INVESTIGATION REPORT AND REQUEST FOR NO FURTHER ACTION
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8116526007/T10000007147.PDF

Document Type: Site Documents **Size :**
Document Date: 3/23/2016 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: FILE REVIEW **Submitted:**
Title: RCDEH SITE SUMMARY 3/23/2016
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6280088

Document Type: Site Documents **Size :**
Document Date: 1/7/2016 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: FILE REVIEW **Submitted:**
Title: RCDEH UPLOADED SITE FILE 1/7/2016
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6271937

Document Type: Site Documents **Size :** 16,844 KB
Document Date: 1/5/2016 **Submitted By:** GREG MCIVER (AUTH_RP)
Type: OTHER WORKPLAN **Submitted:**
Title: SOIL INVESTIGATION REPORT AND SOIL INVESTIGATION WORK PLAN
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1472670137/T10000007147.PDF

Document Type: Site Documents **Size :**
Document Date: 1/5/2016 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: PRELIMINARY SITE ASSESSMENT REPORT **Submitted:**
Title: UNKNOWN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&document_id=5862228

Document Type: Site Documents **Size :**
Document Date: 10/1/2015 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: PRELIMINARY SITE ASSESSMENT WORKPLAN **Submitted:**
Title: UNKNOWN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&document_id=5851511

Document Type: Site Documents **Size :** 3,973 KB
Document Date: 9/30/2015 **Submitted By:** GREG MCIVER (AUTH_RP)
Type: SOIL AND WATER INVESTIGATION WORKPLAN **Submitted:**
Title: SITE INVESTIGATION WORK PLAN
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5944666266/T10000007147.PDF

Document Type: Site Documents **Size :**
Document Date: 9/10/2015 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: NOTICE OF RESPONSIBILITY **Submitted:**
Title: ADDITIONAL RP FOR SITE LETTERS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6260070

Document Type: Site Documents **Size :**
Document Date: 7/28/2015 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: NEW SITE LETTERS SENT OUT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000007147&enforcement_id=6255705

Document Type: Site Documents **Size :** 1,038 KB
Document Date: 7/15/2015 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: UPDATES AND INFORMATION - NEWS RELEASE **Submitted:**
Title: POSSIBLE HAZARDOUS MATERIAL EXPOSURE-PROP 65
Title Link: http://geotracker.waterboards.ca.gov/community_involvement/8655515372/Finalized%20Prop%2065%2DRO6600626%2Epdf

---

17	2 of 4	ENE	0.13 / 688.25	832.09 / 15	Flyers #462 11074 Inland Jurupa Valley CA	RIVERSIDE LOP

Site ID: 2015RO6600626 **Closed Code:** Y

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status Code: 9
Closed Desc: CLOSED SITE
Status Desc: CLOSED/ACTION COMPLETED
Employee: Shurlow-LOP
Case Type Code: S
Case Type Desc: SOIL ONLY IS IMPACTED

---

17 | **3 of 4** | **ENE** | **0.13 / 688.25** | **832.09 / 15** | **Flyers # 462**
11074 INLAND AVE
MIRA LOMA CA 91752 | **CERS TANK**

Site ID: 144334
Latitude: 34.029884
Longitude: -117.526512

Regulated Programs

EI ID: 10206820
EI Description: Underground Storage Tank

EI ID: 10206820
EI Description: Chemical Storage Facilities

EI ID: 10206820
EI Description: Hazardous Waste Generator

Violations

Violation Date: 03/04/2019
Violation Source: CERS
Violation Program: UST
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Notes:

Returned to compliance on 04/24/2019. OBSERVATION: Observed 87 fill spill bucket to be leaking and would not hold liquid. CORRECTIVE ACTION: Owner/operator shall repair/replace the leaking spill bucket so that bucket is able to hold liquid and contain release until detected. This Department shall be notified of the test date.

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

"

Violations

Violation Date: 03/04/2020
Violation Source: CERS
Violation Program: UST
Violation Division: Riverside County Department of Env Health
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Notes:

Returned to compliance on 07/22/2020.

Violation Description:

Failure to comply with one or more of the following overfill prevention equipment requirements:
Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018.

For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter.

For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter.

Inspected within 30 days after a repair to the overfill prevention equipment.

Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Inspected by a certified UST service technician.

Maintain records of overfill prevention equipment inspection for 36 months.

Violations

Violation Date: 03/05/2015 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.7 25284 - California Health and Safety Code, Chapter 6.7, Section(s) 25284
Violation Notes:

Returned to compliance on 03/31/2016.

Violation Description:

Failure to obtain and maintain a valid operation permit from the CUPA.

Violations

Violation Date: 03/05/2015 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.11 25404.1 - California Health and Safety Code, Chapter 6.11, Section(s) 25404.1
Violation Notes:

Returned to compliance on 03/31/2016.

Violation Description:

Failure to obtain and/or maintain an active hazardous waste generator permit.

Violations

Violation Date: 01/22/2019 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Riverside County Department of Env Health
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Notes:

Returned to compliance on 07/23/2020. Overfill has been completed

Violation Description:

Failure to comply with one or more of the following overfill prevention equipment requirements:
Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95

percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or
Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018.

For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter.

For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter.

Inspected within 30 days after a repair to the overfill prevention equipment.

Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Inspected by a certified UST service technician.

Maintain records of overfill prevention equipment inspection for 36 months.

Violations

Violation Date: 03/05/2015 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 03/31/2016.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 03/02/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Notes:

Returned to compliance on 09/12/2017.

Violation Description:

Failure to test the spill bucket annually.

Violations

Violation Date: 03/03/2020 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Riverside County Department of Env Health
Citation: 23 CCR 16 2632(c)(2)(A)&(B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(c)(2)(A)&(B)
Violation Notes:

Returned to compliance on 03/03/2020. Annular for diesel was stuck and testing could not be performed. Technician have requested for annular to be evaluated and repair as necessary. Submit report within 30 days to this department. Technician was able to do the test and facility passed. Violation have been corrected.

Violation Description:

Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system.

Enforcements

Enf Action Date: 03/05/2015 ***Enf Action Program:*** HW
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 03/05/2015 ***Enf Action Program:*** UST
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 03/05/2015 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 03/05/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/22/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 03/02/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/12/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/03/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/04/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 03/12/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/03/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/05/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/05/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/12/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/22/2019
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 03/02/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2020
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 03/03/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/03/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 03/04/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 03/04/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: UST Permit Applicant
Entity Name: Elizabeth Orizaga
Entity Title: Compliance Coordinator

Address:
City:
State:
Country:
Zip Code:
Phone: (530) 885-0401

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503
Phone: (951) 358-5055

Affil Type Desc: Parent Corporation
Entity Name: Flyers Energy LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Tank Owner
Entity Name: Flyers Energy LLC
Entity Title:
Address: 2360 Lindbergh Street
City: Auburn
State: CA
Country: United States
Zip Code: 95602
Phone: (530) 885-0401

Affil Type Desc: Legal Owner
Entity Name: Flyers Energy LLC
Entity Title:
Address: 2360 Lindbergh Street
City: Auburn
State: CA
Country: United States
Zip Code: 95602
Phone: (530) 885-0401

Affil Type Desc: Environmental Contact
Entity Name: Anais Maurel
Entity Title:
Address: 2360 Lindbergh Street
City: Auburn
State: CA
Country:
Zip Code: 95602
Phone:

Affil Type Desc: Operator
Entity Name: Flyers Energy LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (530) 885-0401

Affil Type Desc: UST Property Owner Name
Entity Name: Stella Group Investments

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Title:
Address: 45-483 Espinazo Court
City: Indian Wells
State: CA
Country: United States
Zip Code: 92210
Phone: (909) 877-1518

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 2360 Lindbergh Street
City: Auburn
State: CA
Country:
Zip Code: 95602
Phone:

Affil Type Desc: Document Preparer
Entity Name: Anais Maurel
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Anais Maurel
Entity Title: Compliance Administrator
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Tank Operator
Entity Name: Flyers Energy LLC
Entity Title:
Address: 2360 Lindbergh Street
City: Auburn
State: CA
Country: United States
Zip Code: 95602
Phone: (530) 885-0401

Coordinates

Env Int Type Code: HWG
Program ID: 10206820
Latitude: 34.029880
Longitude: -117.526510
Coord Name:
Ref Point Type Desc: Center of a facility or station.

17	4 of 4	ENE	0.13 / 688.25	832.09 / 15	FLYERS ENERGY, LLC. 11074 INLAND AVE MIRA LOMA CA 91752	EMISSIONS

2016 Toxic Data

Facility ID: 179148
Facility SIC Code: 5541
CERR CODE:
COID: RIV
CO: 33
TS:
HRA:
CH Index:
AH Index:
Air Basin: SC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

DISN: SOUTH COAST AQMD
District: SC
CHAPIS:

2017 Toxic Data

Facility ID: 179148
COID: RIV
Facility SIC Code: 5541
DISN: SOUTH COAST AQMD
CO: 33
CHAPIS:
Air Basin: SC
CERR Code:
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2018 Toxic Data

Facility ID: 179148
COID: RIV
Facility SIC Code: 5541
DISN: SOUTH COAST AQMD
CO: 33
CHAPIS:
Air Basin: SC
CERR Code:
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

18	1 of 4	W	0.14 / 738.66	821.24 / 4	Swift Transportation 11888 Mission Blvd Jurupa Valley CA 91752	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Riverside County - Underground Storage Tanks List
Record Date: 08-FEB-2019

18	2 of 4	W	0.14 / 738.66	821.24 / 4	CONSOLIDATED FREIGHTWAYS 11888 MISSION BLVD MIRA LOMA CA 91752	HHSS

County:
Pdf File Url: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0001f568.pdf

---

18	3 of 4	W	0.14 / 738.66	821.24 / 4	CONSOLIDATED FREIGHTWAYS 11888 MISSION BLVD MIRA LOMA CA 91752	EMISSIONS

18	4 of 4	W	0.14 / 738.66	821.24 / 4	CONSOLIDATED FREIGHTWAYS 11888 MISSION BLVD. MIRA LOMA CA	HIST TANK

Owner Name: CONSOLIDATED FREIGHTWAYS
No of Containers: 15
Owner Street: 175 LINFIELD DRIVE
County: RIVERSIDE
Owner City: MENLO PARK
Facility State: CA
Owner State: CA
Facility Zip: 91752
Owner Zip: 94025

19	1 of 1	W	0.14 / 756.07	822.16 / 5	CONSOLIDATED FREIGHTWAYS 11888 MISSION BLVD	DELISTED TNK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Mira Loma CA 91752	

Delisted Storage Tanks

Facility ID:	237	**Latitude:**	34.0256306
Permitting Agency:	RIVERSIDE COUNTY	**Longitude:**	-117.5440391
County:	Riverside		
Original Source:	UST		
Record Date:	30-JAN-2017		

---

20 | **1 of 2** | **W** | **0.16 / 843.70** | **821.76 / 4** | **Consolidated Freightway**
11888 Mission Blvd
Mira Loma CA | **RIVERSIDE LOP**

Site ID:	9915850	**Closed Code:**	Y
Status Code:	9	**Closed Desc:**	CLOSED SITE
Status Desc:	CLOSED/ACTION COMPLETED	**Employee:**	Boltinghous-LOP
Case Type Code:	S		
Case Type Desc:	SOIL ONLY IS IMPACTED		

---

20 | **2 of 2** | **W** | **0.16 / 843.70** | **821.76 / 4** | **CONSOLIDATED FREIGHTWAYS**
11888 MISSION BLVD
MIRA LOMA CA | **UST SWEEPS**

C C:	A33-000-21780	**D Filename:**	SITE16A
BOE:	44-000859	**Page No:**	57
Comp:	21780	**County:**	RIVERSIDE
Status:	ACTIVE	**State :**	CA
No of Tanks:	14	**Zip:**	91752
Jurisdict:	RIVERSIDE COUNTY	**Latitude:**	34.03239
Agency:	ENVIRONMENTAL HEALTH - U.S.T.	**Longitude:**	-117.558036
Phone:		**Georesult:**	S5HPNTSCZA

Tank Details

Tank ID:	000005	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000005	**Storage :**	
Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	DIESEL
Capac:	20000	**ONA:**	
Tank Use:	M.V. FUEL	**D File Name:**	TANK16A

Tank Details

Tank ID:	000009	**S Contain:**	
O Tank ID:	000352	**Stg:**	W
SWRCB No:	33-000-021780-000009	**Storage :**	
Removed:		**Storag Type:**	WASTE
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	WASTE OIL
Capac:	10000	**ONA:**	
Tank Use:	OIL	**D File Name:**	TANK16A

Tank Details

Tank ID:	000001	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000001	**Storage :**	

Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	DIESEL
Capac:	10000	**ONA:**	
Tank Use:	M.V. FUEL	**D File Name:**	TANK16A

Tank Details

Tank ID:	000011	**S Contain:**	
O Tank ID:	000352	**Stg:**	W
SWRCB No:	33-000-021780-000011	**Storage :**	
Removed:		**Storag Type:**	WASTE
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	WASTE OIL
Capac:	6000	**ONA:**	
Tank Use:	OIL	**D File Name:**	TANK16A

Tank Details

Tank ID:	000006	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000006	**Storage :**	
Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	DIESEL
Capac:	20000	**ONA:**	
Tank Use:	M.V. FUEL	**D File Name:**	TANK16A

Tank Details

Tank ID:	000010	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000010	**Storage :**	
Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	MOTOR OIL
Capac:	10000	**ONA:**	
Tank Use:	UNKNOWN	**D File Name:**	TANK16A

Tank Details

Tank ID:	000007	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000007	**Storage :**	
Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	MOTOR OIL
Capac:	10000	**ONA:**	
Tank Use:	UNKNOWN	**D File Name:**	TANK16A

Tank Details

Tank ID:	000013	**S Contain:**	
O Tank ID:	000352	**Stg:**	P
SWRCB No:	33-000-021780-000013	**Storage :**	
Removed:		**Storag Type:**	PRODUCT
Installed:		**P Contain:**	
A Date:	10-28-92	**Content:**	UNKNOWN
Capac:	6000	**ONA:**	
Tank Use:	UNKNOWN	**D File Name:**	TANK16A

Tank Details

Tank ID: 000002
O Tank ID: 000352
SWRCB No: 33-000-021780-000002
Removed:
Installed:
A Date: 10-28-92
Capac: 20000
Tank Use: M.V. FUEL

S Contain:
Stg: P
Storage :
Storag Type: PRODUCT
P Contain:
Content: DIESEL
ONA:
D File Name: TANK16A

Tank Details

Tank ID: 000004
O Tank ID: 000352
SWRCB No: 33-000-021780-000004
Removed:
Installed:
A Date: 10-28-92
Capac: 20000
Tank Use: M.V. FUEL

S Contain:
Stg: P
Storage :
Storag Type: PRODUCT
P Contain:
Content: DIESEL
ONA:
D File Name: TANK16A

Tank Details

Tank ID: 000008
O Tank ID: 000352
SWRCB No: 33-000-021780-000008
Removed:
Installed:
A Date: 10-28-92
Capac: 10000
Tank Use: UNKNOWN

S Contain:
Stg: P
Storage :
Storag Type: PRODUCT
P Contain:
Content: ANTIFREEZE
ONA:
D File Name: TANK16A

Tank Details

Tank ID: 000012
O Tank ID: 000352
SWRCB No: 33-000-021780-000012
Removed:
Installed:
A Date: 10-28-92
Capac: 6000
Tank Use: UNKNOWN

S Contain:
Stg: W
Storage :
Storag Type: WASTE
P Contain:
Content: UNKNOWN
ONA:
D File Name: TANK16A

Tank Details

Tank ID: 000014
O Tank ID: WW-1
SWRCB No: 33-000-021780-000014
Removed:
Installed:
A Date: 10-28-92
Capac: 10000
Tank Use: OIL

S Contain:
Stg: W
Storage :
Storag Type: WASTE
P Contain:
Content: WASTE OIL
ONA:
D File Name: TANK16A

Tank Details

Tank ID: 000003
O Tank ID: 000352
SWRCB No: 33-000-021780-000003
Removed:
Installed:
A Date: 10-28-92
Capac: 20000

S Contain:
Stg: P
Storage :
Storag Type: PRODUCT
P Contain:
Content: DIESEL
ONA:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Use:	M.V. FUEL			**D File Name:**	TANK16A	

21	1 of 1	NE	0.17 / 881.45	833.73 / 16	**Middle Atlantic Products** **11150 Inland Ave** **Jurupa Valley CA 91752**	**DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 18-MAY-2016

22	1 of 2	N	0.17 / 910.73	829.87 / 12	**County of Riverside** **11511 Venture Dr** **Riverside CA**	**RIVERSIDE LOP**

Site ID: 960074
Status Code: 9
Status Desc: CLOSED/ACTION COMPLETED
Case Type Code: S
Case Type Desc: SOIL ONLY IS IMPACTED
Closed Code: Y
Closed Desc: CLOSED SITE
Employee: Malloy

22	2 of 2	N	0.17 / 910.73	829.87 / 12	**COUNTY OF RIVERSIDE** **11511 VENTURE DR** **RIVERSIDE CA 91752**	**LUST**

Global ID: T0606500455
Status: COMPLETED - CASE CLOSED
Status Date: 4/18/1998
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites from GeoTracker Search; LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download
County: RIVERSIDE
Latitude: 34.0298929839762
Longitude: -117.529474609248

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail(as Nov 16 2020)

RB Case No: 083302806T
Local Case No: 960074
Begin Date: 1/24/1996
Lead Agency: RIVERSIDE COUNTY LOP
Local Agency: RIVERSIDE COUNTY LOP
CUF Case: NO
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
DWR GW Subbasin Name: Upper Santa Ana Valley - Chino (8-002.01)
Disadvantaged Community:
Site History:
Potential COC: Diesel
How Discovered: Tank Closure
Stop Method: Close and Remove Tank
Stop Description:
Case Worker: SCB
File Location: Local Agency Warehouse

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity(as Nov 16 2020)

Action Type: ENFORCEMENT
Date : 4/18/1998
Action: Closure/No Further Action Letter - #RCDEH0415

Action Type: ENFORCEMENT
Date : 4/17/1998
Action: File review - #RCDEH Upload Site File 8/21/2015

Action Type: REMEDIATION
Date : 1/7/1997
Action: Excavation

Action Type: Other

Date : 1/24/1996
Action: Leak Discovery

Action Type: Other
Date : 1/24/1996
Action: Leak Reported

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts(as Nov 16 2020)

Contact Type: Local Agency Caseworker
Contact Name: SHARON BOLTINGHOUSE
City: RIVERSIDE
Organization Name: RIVERSIDE COUNTY LOP
Address: 3880 LEMON ST SUITE 200
Email: sbolting@rivco.org
Phone No: 9519558980

Contact Type: Regional Board Caseworker
Contact Name: CARL BERNHARDT
City: RIVERSIDE
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
Email: carl.bernhardt@waterboards.ca.gov
Phone No: 9517824495

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History(as Nov 16 2020)

Status: Completed - Case Closed
Status Date: 4/18/1998

Status: Open - Remediation
Status Date: 1/7/1997

Status: Open - Site Assessment
Status Date: 9/17/1996

Status: Open - Case Begin Date
Status Date: 1/24/1996

Status: Open - Site Assessment
Status Date: 1/24/1996

LUST Sites from GeoTracker Search - Regulatory Profile (as of Oct 06, 2020)

Site Facility Name: COUNTY OF RIVERSIDE
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
Potential COC: DIESEL
Facility Type:
Composting Method:
Address: 11511 VENTURE DR
City: RIVERSIDE
Zip: 91752
County: RIVERSIDE
CUF Claim:

File Location: LOCAL AGENCY WAREHOUSE
Designated Beneficial Use: MUN, AGR, IND, PROC
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0606500455
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 4/18/1998
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0606500455&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Santa Ana Valley - Chino (8-002.01)
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: RIVERSIDE COUNTY LOP (LEAD) - CASE #: 960074
CASEWORKER: SHARON BOLTINGHOUSE
SANTA ANA RWQCB (REGION 8) - CASE #: 083302806T
CASEWORKER: CARL BERNHARDT
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply

Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History (as of Oct 06, 2020)

Status: Completed - Case Closed
Date : 4/18/1998

Status: Open - Remediation
Date : 1/7/1997

Status: Open - Site Assessment
Date : 9/17/1996

Status: Open - Case Begin Date
Date : 1/24/1996

Status: Open - Site Assessment
Date : 1/24/1996

LUST Sites from GeoTracker Search - Cleanup Action Report (as of Oct 06, 2020)

Action Type: EXCAVATION
Phase: Soil
Contaminant Mass Removed:
Description: RECYCLED AT CDE
Begin Date: 1/7/1997
End Date: 1/28/1997

LUST Sites from GeoTracker Search - Regulatory Activities (as of Oct 06, 2020)

Action Type: Other Regulatory Actions
Action Date: 4/18/1998
Received Issue Date: 4/18/1998
Action: Closure/No Further Action Letter - #RCDEH0415
Doc Link:
Title Description Comments:

Riv Co LOP issued NFA letter dated 4/18/1998

Action Type: Other Regulatory Actions
Action Date: 4/17/1998
Received Issue Date: 4/17/1998
Action: File review - #RCDEH Upload Site File 8/21/2015
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500455&enforcement_id=6050405&temptable=ENFORCEMENT
Title Description Comments:

RCDEH Upload Site File 8/21/2015

Action Type: Cleanup Action
Action Date: 1/7/1997
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

RECYCLED AT CDE

Action Type: Leak Action
Action Date: 1/24/1996
Received Issue Date:
Action: Leak Discovery

Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 1/24/1996
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

LUST Sites from GeoTracker Search - Documents (as of Oct 06, 2020)

Document Type: Site Documents ***Size :*** 49 KB
Document Date: 6/18/2008 ***Submitted By:*** RIVERSIDE COUNTY LOP (REGULATOR)
Type: LETTER ***Submitted:***
Title: RCDEH CASE CLOSURE LETTER
Title Link: http://geotracker.waterboards.ca.gov/site_documents/6890110611/Closure%20Letter%2Epdf

Document Type: Site Documents ***Size :*** 188 KB
Document Date: 6/18/2008 ***Submitted By:*** RIVERSIDE COUNTY LOP (REGULATOR)
Type: REPORT ***Submitted:***
Title: RCDEH CASE CLOSURE SUMMARY
Title Link: http://geotracker.waterboards.ca.gov/site_documents/8833160221/Case%20Closure%20Summary%2Epdf

Document Type: Site Documents ***Size :*** 95 KB
Document Date: 6/18/2008 ***Submitted By:*** RIVERSIDE COUNTY LOP (REGULATOR)
Type: REPORT ***Submitted:***
Title: RCDEH URR
Title Link: http://geotracker.waterboards.ca.gov/site_documents/9699177384/URR%2Epdf

Document Type: Site Documents ***Size :***
Document Date: 4/17/1998 ***Submitted By:*** LINDA SHURLOW (REGULATOR)
Type: FILE REVIEW ***Submitted:***
Title: RCDEH UPLOAD SITE FILE 8/21/2015
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500455&enforcement_id=6050405

---

23 ***1 of 1*** ***ENE*** ***0.18 / 957.02*** ***833.07 / 16*** ***DEL REAL LLC***
11041 INLAND AVE
MIRA LOMA CA 91752-1155 ***RCRA TSD***

EPA Handler ID: CAL000348717
Gen Status Universe: No Report
Contact Name: JANETH ALVAREZ
Contact Address: 11041 INLAND AVE , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext: 909-827-9894
Contact Email: JALVAREZ@DELREALFOODS.COM
Contact Country:
Land Type:
County Name: RIVERSIDE
EPA Region: 09
Receive Date: 20091215
Location Latitude: 34.030361
Location Longitude: -117.525155

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No

Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20091215
Handler Name:	DEL REAL LLC
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	11041 INLAND AVE
Name:	DEL REAL FOODS INC	***Street 2:***	
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	951-681-0395	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752-1155
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	11041 INLAND AVE
Name:	JANETH ALVAREZ	***Street 2:***	
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	909-827-9894	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

24	***1 of 1***	***NNE***	***0.18 / 970.36***	***832.93 / 16***	***ROADRUNNER TRANSPORTATION SERVICES, INC.*** ***11385 VENTURE DR.*** ***MIRA LOMA CA 91752***	***RCRA TSD***

EPA Handler ID:	CAC003009946
Gen Status Universe:	No Report
Contact Name:	EMEM OBOT
Contact Address:	4900 S. PENNSYLVANIA AVE , , CUDAHY , WI, 53110 ,
Contact Phone No and Ext:	440-349-2700
Contact Email:	EOBOT@ERTSONLINE.COM
Contact Country:	
Land Type:	
County Name:	RIVERSIDE
EPA Region:	09
Receive Date:	20190412
Location Latitude:	34.029753
Location Longitude:	-117.531983

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190412
Handler Name:	ROADRUNNER TRANSPORTATION SERVICES, INC.
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	4900 S. PENNSYLVANIA AVE
Name:	ROADRUNNER CORP.	***Street 2:***	
Date Became Current:		***City:***	CUDAHY
Date Ended Current:		***State:***	WI
Phone:	888-281-7232	***Country:***	
Source Type:	Implementer	***Zip Code:***	53110

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	4900 S. PENNSYLVANIA AVE
Name:	EMEM OBOT	***Street 2:***	
Date Became Current:		***City:***	CUDAHY
Date Ended Current:		***State:***	WI
Phone:	440-349-2700	***Country:***	
Source Type:	Implementer	***Zip Code:***	53110

---

25 ***1 of 1*** ***SSE*** ***0.20 / 1,043.65*** ***800.21 / -17*** ***CA*** ***PFAS GW***

Well ID:	3310021-043
Latitude:	34.021534
Longitude:	-117.531918
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS

Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25

Well Depth (ft):

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.8
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK

Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.8
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 1.8
Date : 12/27/2019
RL: UNK
Top of Screen (ft):
Screen Length (ft):

Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/07/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043
Well Type:	MUNICIPAL	**Other Names:**	WELL 25
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-043

Well Type: MUNICIPAL
Well Depth (ft):
Other Names: WELL 25

Perfluorononanoic acid

Chemical: PFNA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorononanoic acid

Chemical: PFNA
Results: 1.8
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorooctadecanoic acid

Chemical: PFNDCA
Results: 1.8
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/07/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-043
Well Type:	MUNICIPAL	***Other Names:***	WELL 25
Well Depth (ft):			

Perfluoroundecanoic acid

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Chemical: PFUNDCA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroundecanoic acid

Chemical: PFUNDCA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroundecanoic acid

Chemical: PFUNDCA
Results: 1.7
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

Perfluoroundecanoic acid

Chemical: PFUNDCA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-043
Other Names: WELL 25

26	1 of 4	NE	0.20 / 1,050.07	835.51 / 18	Sprint Nextel CA 7208 11175 Inland Ave Jurupa Valley CA 91752	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

26	2 of 4	NE	0.20 / 1,050.07	835.51 / 18	NEXTEL COMMUNICATIONS 11175 INLAND AVE. MIRA LOMA CA 91752	AST

Total Capacity(Gal): 9,300
CUPA: Riverside
Owner Name: NEXTEL OF CALIFORNIA
County: Riverside

26	3 of 4	NE	0.20 / 1,050.07	835.51 / 18	Nextel of California 11175 Inland Ave. Mira Loma CA 91752	AST

Total Capacity(Gal): 3,000
CUPA: Riverside
Owner Name: Nextel of California
County: Riverside

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	4 of 4	NE	0.20 / 1,050.07	835.51 / 18	NEXTEL COMMUNICATIONS 11175 INLAND AVE. MIRA LOMA CA 91752	AST SWRCB

Total Gals: 9300
Owner Name: NEXTEL OF CALIFORNIA
Data Source: SWRCB Aboveground Storage Tanks Listing 2003;SWRCB Aboveground Storage Tanks Listing 2005;SWRCB Aboveground Storage Tanks Listing 2007;SWRCB Aboveground Storage Tanks Listing 2006

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	1 of 1	ENE	0.20 / 1,077.62	826.67 / 9	GEODIS Logistics, LLC 0530 3285 DE FOREST CIR JURUPA VALLEY CA 91752	DELISTED CTNK

Site ID: 139709
County:
Original Source: CTNK
Latitude: 34.027220
Longitude: -117.522320
Record Date: 20-OCT-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	1 of 1	NE	0.21 / 1,122.26	837.14 / 20	POMA AUTOMATED FUELING 11074 INLAND AVE Mira Loma CA 91752	DELISTED TNK

Delisted Storage Tanks

Facility ID: 595
Permitting Agency: RIVERSIDE COUNTY
County: Riverside
Original Source: UST
Record Date: 30-JAN-2017
Latitude: 34.031235
Longitude: -117.525163

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	1 of 1	NNE	0.21 / 1,123.72	836.59 / 19	JON RICHARDS COMPANY 11210 INLAND AVE MIRA LOMA CA 91752	EMISSIONS

2015 Toxic Data

Facility ID: 126555
Facility SIC Code: 3449
CO: 33
Air Basin: SC
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: RIV
DISN: SOUTH COAST AQMD
CHAPIS:
CERR Code:

2016 Toxic Data

Facility ID: 126555
Facility SIC Code: 3449
CERR CODE:
COID: RIV
CO: 33
DISN: SOUTH COAST AQMD
CHAPIS:
TS:
HRA:
CH Index:
AH Index:
Air Basin: SC
District: SC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	1 of 1	NNE	0.23 / 1,191.22	837.62 / 20	The Penn Companies 11199 Inland Ave	DELISTED COUNTY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Mira Loma CA 91752	

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

31	1 of 4	ESE	0.23 / 1,233.00	802.07 / -15	FOOD GAS & GO MINI MART 3710 ETIWANDA AVE MIRA LOMA CA 91752	LUST

Global ID: T0606500561
Status: COMPLETED - CASE CLOSED
Status Date: 9/15/2009
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites from GeoTracker Search; LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download
County: RIVERSIDE
Latitude: 34.0200068
Longitude: -117.5241548

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail(as Nov 16 2020)

RB Case No: 083303354T
Local Case No: 9814821
Begin Date: 12/11/1998
Lead Agency: RIVERSIDE COUNTY LOP
Local Agency: RIVERSIDE COUNTY LOP
CUF Case: YES
Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
DWR GW Subbasin Name: Upper Santa Ana Valley - Chino (8-002.01)
Disadvantaged Community:
Site History:
Potential COC: Gasoline
How Discovered: Tank Closure
Stop Method:
Stop Description:
Case Worker: SCB
File Location: Local Agency Warehouse

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity(as Nov 16 2020)

Action Type: ENFORCEMENT
Date : 9/15/2009
Action: Closure/No Further Action Letter - #RCDEH Closure Documents

Action Type: ENFORCEMENT
Date : 9/14/2009
Action: File review - #RCDEH Upload Site File 5/25/2010

Action Type: RESPONSE
Date : 7/15/2009
Action: Well Destruction Report

Action Type: RESPONSE
Date : 6/29/2009
Action: Well Destruction Report

Action Type: ENFORCEMENT
Date : 4/6/2009
Action: Staff Letter - #RCDEH 040609

Action Type: RESPONSE
Date : 10/26/2008
Action: Request for Closure

Action Type: RESPONSE
Date : 8/5/2008
Action: Monitoring Report - Quarterly

Action Type: RESPONSE

Date : 4/20/2008
Action: Request for Closure

Action Type: RESPONSE
Date : 4/15/2008
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date : 2/20/2008
Action: Staff Letter - #RCDEH 022008

Action Type: RESPONSE
Date : 1/15/2008
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date : 12/10/2007
Action: File review

Action Type: RESPONSE
Date : 10/15/2007
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date : 8/17/2007
Action: Other Report / Document

Action Type: ENFORCEMENT
Date : 5/11/2007
Action: Technical Correspondence / Assistance / Other - #RCDEH 051107

Action Type: REMEDIATION
Date : 3/4/2005
Action: Soil Vapor Extraction (SVE)

Action Type: REMEDIATION
Date : 1/27/1999
Action: Excavation

Action Type: Other
Date : 12/31/1998
Action: Leak Discovery

Action Type: Other
Date : 12/31/1998
Action: Leak Reported

Action Type: Other
Date : 12/11/1998
Action: Leak Stopped

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts(as Nov 16 2020)

Contact Type: Regional Board Caseworker
Contact Name: MIGUEL OVIEDO
City: RIVERSIDE
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
Email: miguel.oviedo@waterboards.ca.gov
Phone No: 9517823238

Contact Type: Local Agency Caseworker
Contact Name: SHARON BOLTINGHOUSE
City: RIVERSIDE
Organization Name: RIVERSIDE COUNTY LOP
Address: 3880 LEMON ST SUITE 200
Email: sbolting@rivco.org
Phone No: 9519558980

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History(as Nov 16 2020)

Status: Completed - Case Closed
Status Date: 9/15/2009

Status: Open - Verification Monitoring
Status Date: 5/11/2007

Status: Open - Remediation
Status Date: 3/4/2005

Status: Open - Site Assessment
Status Date: 9/6/2002

Status: Open - Remediation
Status Date: 1/27/1999

Status: Open - Site Assessment
Status Date: 12/31/1998

Status: Open - Case Begin Date
Status Date: 12/11/1998

LUST Sites from GeoTracker Search - Regulatory Profile (as of Oct 06, 2020)

Site Facility Name: FOOD GAS & GO MINI MART
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig: C
CUF Amount Paid: $508,845
Potential COC: GASOLINE
Facility Type:
Composting Method:
Address: 3710 ETIWANDA AVE
City: MIRA LOMA
Zip: 91752
County: RIVERSIDE
CUF Claim: 17611
File Location: LOCAL AGENCY WAREHOUSE
Designated Beneficial Use: MUN, AGR, IND, PROC
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0606500561
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 9/15/2009
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0606500561&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Santa Ana Valley - Chino (8-002.01)
Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
Post Closure Site Management: NOTIFY PRIOR TO CHANGE IN LAND USE
Future Land Use: COMMERCIAL
Cleanup Oversight Agencies: RIVERSIDE COUNTY LOP (LEAD) - CASE #: 9814821
CASEWORKER: SHARON BOLTINGHOUSE
SANTA ANA RWQCB (REGION 8) - CASE #: 083303354T
CASEWORKER: MIGUEL OVIEDO
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History (as of Oct 06, 2020)

Status: Completed - Case Closed
Date : 9/15/2009

Status: Open - Verification Monitoring
Date : 5/11/2007

Status: Open - Remediation
Date : 3/4/2005

Status: Open - Site Assessment
Date : 9/6/2002

Status: Open - Remediation
Date : 1/27/1999

Status: Open - Site Assessment
Date : 12/31/1998

Status: Open - Case Begin Date
Date : 12/11/1998

LUST Sites from GeoTracker Search - Cleanup Action Report (as of Oct 06, 2020)

Action Type: SOIL VAPOR EXTRACTION (SVE) ***Begin Date:*** 3/4/2005
Phase: Soil ***End Date:*** 1/9/2007
Contaminant Mass Removed: 6,324 Pounds
Description: SVE phase operations

Action Type: EXCAVATION ***Begin Date:*** 1/27/1999
Phase: Soil ***End Date:*** 1/27/1999
Contaminant Mass Removed:
Description: soil excavated from UST/dispenser area

LUST Sites from GeoTracker Search - Regulatory Activities (as of Oct 06, 2020)

Action Type: Other Regulatory Actions
Action Date: 9/15/2009
Received Issue Date: 9/15/2009
Action: Closure/No Further Action Letter - #RCDEH Closure Documents
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6030947&temptable=ENFORCEMENT
Title Description Comments:

Case Closure RCDEH issued NFA letter dated 9/15/2009.

Action Type: Other Regulatory Actions
Action Date: 9/14/2009
Received Issue Date: 9/14/2009
Action: File review - #RCDEH Upload Site File 5/25/2010
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6051938&temptable=ENFORCEMENT
Title Description Comments:

RCDEH Upload Site File 5/25/2010

Action Type: Response Requested - Reports
Action Date: 7/15/2009
Received Issue Date: 7/15/2009
Action: Well Destruction Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0606500561&doc_id=5650352
Title Description Comments:

Well Abandonment Report

Action Type: Response Requested - Reports
Action Date: *6/29/2009
Received Issue Date: 8/17/2009
Action: Well Destruction Report
Doc Link:
Title Description Comments:

- Report documenting removal of wells & waste and landowner notification due 5/29/09

Action Type: Other Regulatory Actions
Action Date: 4/6/2009

Received Issue Date: 4/6/2009
Action: Staff Letter - #RCDEH 040609
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6008933&temptable=ENFORCEMENT
Title Description Comments:

DIRECTIVE RCDEH sent letter requesting well destruction, waste removal, and landowner notification of County's intent to issue closure letter. Documentation due 5/29/2009.

Action Type: Response Requested - Other
Action Date: 10/26/2008
Received Issue Date: 11/26/2008
Action: Request for Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0606500561&doc_id=5627126
Title Description Comments:

- Additional information requested for the closure report.

Action Type: Response Requested - Reports
Action Date: 8/5/2008
Received Issue Date: 8/5/2008
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Q2-08 GW Monitoring Report - Q2-08 GW Mon. Report

Action Type: Response Requested - Other
Action Date: 4/20/2008
Received Issue Date: 4/20/2008
Action: Request for Closure
Doc Link:
Title Description Comments:

Request for Closure - Closure report due 4/20/2008

Action Type: Response Requested - Reports
Action Date: 4/15/2008
Received Issue Date: 4/15/2008
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarter 1-08

Action Type: Other Regulatory Actions
Action Date: 2/20/2008
Received Issue Date: 2/20/2008
Action: Staff Letter - #RCDEH 022008
Doc Link:
Title Description Comments:

RCDEH sent letter requesting closure document. Report due 4/20/2008

Action Type: Response Requested - Reports
Action Date: 1/15/2008
Received Issue Date: 1/15/2008
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarter 4-07

Action Type: Other Regulatory Actions

Action Date: 12/10/2007
Received Issue Date: 12/10/2007
Action: File review
Doc Link:
Title Description Comments:

Quarterly gw remediation progress report

Action Type: Response Requested - Reports
Action Date: 10/15/2007
Received Issue Date: 12/5/2007
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 3rd Quarter Monitoring Report

Action Type: Response Requested - Other
Action Date: 8/17/2007
Received Issue Date: 12/19/2007
Action: Other Report / Document
Doc Link:
Title Description Comments:

Other Report / Document - Report for confirmation soil borings and SVE testing due 8/17/07

Action Type: Other Regulatory Actions
Action Date: 5/11/2007
Received Issue Date: 5/11/2007
Action: Technical Correspondence / Assistance / Other - #RCDEH 051107
Doc Link:
Title Description Comments:

Letter accepted wp for confirmation borings and SVE testing

Action Type: Cleanup Action
Action Date: 3/4/2005
Received Issue Date:
Action: Soil Vapor Extraction (SVE)
Doc Link:
Title Description Comments:

SVE phase operations

Action Type: Cleanup Action
Action Date: 1/27/1999
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

soil excavated from UST/dispenser area

Action Type: Leak Action
Action Date: 12/31/1998
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 12/31/1998
Received Issue Date:

Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 12/11/1998
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

LUST Sites from GeoTracker Search - Site Maps (as of Oct 06, 2020)

Title: GEO_BORE (MW-1)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6829038858/T0606500561.pdf
Size : 220 KB
Submitted By: C. UALANI QUARTERO (AUTH_RP)
Submitted: 3/22/2006

Title: GEO_BORE (VE-2)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1880247354/T0606500561.pdf
Size : 135 KB
Submitted By: C. UALANI QUARTERO (AUTH_RP)
Submitted: 3/22/2006

Title: GEO_BORE (VE-3)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3012388467/T0606500561.pdf
Size : 139 KB
Submitted By: C. UALANI QUARTERO (AUTH_RP)
Submitted: 3/22/2006

Title: GEO_BORE (VE-1)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7086805045/T0606500561.pdf
Size : 173 KB
Submitted By: C. UALANI QUARTERO (AUTH_RP)
Submitted: 3/22/2006

LUST Sites from GeoTracker Search - Documents (as of Oct 06, 2020)

Document Type: Site Documents
Document Date: 9/15/2009
Type: CLOSURE/NO FURTHER ACTION LETTER
Title: CASE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6030947
Size :
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 9/14/2009
Type: FILE REVIEW
Title: RCDEH UPLOAD SITE FILE 5/25/2010
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6051938
Size :
Submitted By: STEVEN COOK (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 7/15/2009
Type: WELL DESTRUCTION REPORT
Title: WELL ABANDONMENT REPORT - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&document_id=5650352
Size :
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 4/6/2009
Type: STAFF LETTER
Title: DIRECTIVE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500561&enforcement_id=6008933
Size :
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)
Submitted:

Document Type: Site Documents
Document Date: 12/18/2008
Size : 40 KB
Submitted By: SHARON BOLTINGHOUSE (REGULATOR)

Type: DRAFT DOCUMENTS FOR REVIEW - REMEDIAL ACTION PLAN **Submitted:**
Title: NOTICE OF PROPOSED CORRECTIVE ACTION PLAN
Title Link: http://geotracker.waterboards.ca.gov/community_involvement/6298261344/Food%20Gas%20%26%20Go%2ENotCAP%2Epdf

Document Type: Site Documents **Size :** 5,383 KB
Document Date: 11/14/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: SITE CLOSURE REQUEST DOCUMENT-UPDATED
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4989655017/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 219 KB
Document Date: 8/6/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: FIRST QMR 2008
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6764219522/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 1,877 KB
Document Date: 5/19/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: FOURTH QUARTERLY MONITORING REPORT 2006
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6654726922/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 5,093 KB
Document Date: 5/19/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: FOURTH QUARTERLY MONITORING REPORT 2005
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9346678793/T0606500561.PDF

Document Type: Site Documents **Size :** 3,587 KB
Document Date: 4/21/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: REPORTS - CLOSURE RPT. **Submitted:**
Title: SITE CLOSURE REQUEST DOCUMENT 2008
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5964510858/T0606500561.PDF

Document Type: Site Documents **Size :** 120 KB
Document Date: 2/20/2008 **Submitted By:** SHARON BOLTINGHOUSE (REGULATOR)
Type: LETTER **Submitted:**
Title: RCDEH 022008 LETTER
Title Link: http://geotracker.waterboards.ca.gov/site_documents/8146652042/Food%20Gas%20N%20Go%20022008%20letter%2Epdf

Document Type: Monitoring Reports **Size :** 3,932 KB
Document Date: 1/30/2008 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: FOURTH QUARTERLY MONITORING REPORT 2007
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8906690835/T0606500561.PDF

Document Type: Site Documents **Size :** 4,858 KB
Document Date: 12/13/2007 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: REPORTS - OTHER **Submitted:**
Title: FORMAL REBOUND AND THIRD QUARTERLY MONITORING REPORT 2007
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4962681651/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 6,217 KB
Document Date: 7/17/2007 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: SECOND QUARTERLY MONITORING REPORT 2007
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7001798868/T0606500561.PDF

Document Type: Site Documents **Size :** 168 KB
Document Date: 5/11/2007 **Submitted By:** SHARON BOLTINGHOUSE (REGULATOR)
Type: LETTER **Submitted:**
Title: RCDEH 051107 LETTER
Title Link: http://geotracker.waterboards.ca.gov/site_documents/8460743546/Food%20Gas%20N%20Go%20051107%20letter%2Epdf

Document Type: Monitoring Reports **Size :** 5,700 KB

Document Date: 4/26/2007 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: FIRST QUARTER MONITORING REPORT 2007
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3221485972/T0606500561.PDF

Document Type: Site Documents **Size :** 6,429 KB
Document Date: 3/20/2007 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: WORKPLANS - OTHER WP **Submitted:**
Title: ADDENDUM FORMAL REBOUND AND CONFIRMATION BORING WORK PLAN
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8963210880/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 4,050 KB
Document Date: 11/17/2006 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: 1ST QMR 2006
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8609372794/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 3,131 KB
Document Date: 11/17/2006 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: 3RD QMR 2006
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2595141351/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 3,330 KB
Document Date: 11/17/2006 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: 2ND QMR 2006
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8112594425/T0606500561.PDF

Document Type: Monitoring Reports **Size :** 1,678 KB
Document Date: 3/30/2006 **Submitted By:** C. UALANI QUARTERO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: THIRD QUARTER MONITORING REPORT
Title Link: http://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7688169717/T0606500561.PDF

31	2 of 4	ESE	0.23 / 1,233.00	802.07 / -15	FOOD GAS N GO MINI-MART 3710 ETIWANDA AVE MIRA LOMA CA 91752	HHSS

County:
Pdf File Url: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002d916.pdf

---

31	3 of 4	ESE	0.23 / 1,233.00	802.07 / -15	ETIWANDA GAS MART 3710 ETIWANDA AVE MIRA LOMA CA 91752	EMISSIONS

2015 Toxic Data

Facility ID: 169585 **COID:** RIV
Facility SIC Code: 5541 **DISN:** SOUTH COAST AQMD
CO: 33 **CHAPIS:**
Air Basin: SC **CERR Code:**
District: SC
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2016 Toxic Data

Facility ID: 169585 **TS:**
Facility SIC Code: 5541 **HRA:**
CERR CODE: **CH Index:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

COID:	RIV	**AH Index:**	
CO:	33	**Air Basin:**	SC
DISN:	SOUTH COAST AQMD	**District:**	SC
CHAPIS:			

2017 Toxic Data

Facility ID:	169585	**COID:**	RIV
Facility SIC Code:	5541	**DISN:**	SOUTH COAST AQMD
CO:	33	**CHAPIS:**	
Air Basin:	SC	**CERR Code:**	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Toxic Data

Facility ID:	169585	**COID:**	RIV
Facility SIC Code:	5541	**DISN:**	SOUTH COAST AQMD
CO:	33	**CHAPIS:**	
Air Basin:	SC	**CERR Code:**	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

31	4 of 4	ESE	0.23 / 1,233.00	802.07 / -15	FOOD GAS N GO MINI-MART 3710 ETIWANDA AVE MIRA LOMA CA	HIST TANK

Owner Name:	ALBERT P. RAMIREZ	**No of Containers:**	3
Owner Street:	1175 SHEILA COURT	**County:**	RIVERSIDE
Owner City:	UPLAND	**Facility State:**	CA
Owner State:	CA	**Facility Zip:**	91752
Owner Zip:	91786		

32	1 of 1	WSW	0.28 / 1,500.04	818.19 / 1	CONSOLIDATED FREIGHTWAYS 11888 MISSION BLVD MIRA LOMA CA 91752	LUST

Global ID:	T0606500619	**County:**	RIVERSIDE
Status:	COMPLETED - CASE CLOSED	**Latitude:**	34.0229773250493
Status Date:	10/20/2005	**Longitude:**	-117.545033609787
Case Type:	LUST CLEANUP SITE		
Date Source:	LUST Cleanup Sites from GeoTracker Search; LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download		

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail(as Nov 16 2020)

RB Case No:	083303617T	**Potential COC:**	Diesel
Local Case No:	9915850	**How Discovered:**	Tank Closure
Begin Date:	3/30/1999	**Stop Method:**	
Lead Agency:	RIVERSIDE COUNTY LOP	**Stop Description:**	
Local Agency:	RIVERSIDE COUNTY LOP	**Case Worker:**	SCB
CUF Case:	NO	**File Location:**	
Potential Media of Concern:	Soil		
How Discovered Description:			
Calwater Watershed Name:	Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)		
DWR GW Subbasin Name:	Upper Santa Ana Valley - Chino (8-002.01)		
Disadvantaged Community:			

Site History:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity(as Nov 16 2020)

Action Type: ENFORCEMENT
Date : 10/19/2005
Action: File review - #RCDEH upoaded site file 2/13/2015

Action Type: Other
Date : 12/2/1999
Action: Leak Reported

Action Type: Other
Date : 11/29/1999
Action: Leak Discovery

Action Type: Other
Date : 3/30/1999
Action: Leak Stopped

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts(as Nov 16 2020)

Contact Type: Regional Board Caseworker
Contact Name: ROSE SCOTT
City: RIVERSIDE
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
Email: rose.scott@waterboards.ca.gov
Phone No: 9513206375

Contact Type: Local Agency Caseworker
Contact Name: SHARON BOLTINGHOUSE
City: RIVERSIDE
Organization Name: RIVERSIDE COUNTY LOP
Address: 3880 LEMON ST SUITE 200
Email: sbolting@rivco.org
Phone No: 9519558980

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History(as Nov 16 2020)

Status: Completed - Case Closed
Status Date: 10/20/2005

Status: Open - Site Assessment
Status Date: 11/29/1999

Status: Open - Case Begin Date
Status Date: 3/30/1999

LUST Sites from GeoTracker Search - Regulatory Profile (as of Oct 06, 2020)

Site Facility Name: CONSOLIDATED FREIGHTWAYS
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
File Location:
Potential COC: DIESEL
Facility Type:
Composting Method:
Address: 11888 MISSION BLVD
City: MIRA LOMA
Zip: 91752
County: RIVERSIDE
CUF Claim:
Designated Beneficial Use: MUN, AGR, IND, PROC
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0606500619
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/20/2005
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0606500619&tabname=regulatoryhistory
Potential Media of Concern: SOIL
User Defined Beneficial Use:
DWR GW Sub Basin: Upper Santa Ana Valley - Chino (8-002.01)

Calwater Watershed Name: Santa Ana River - Middle Santa Ana River - Chino (Split) (801.21)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: RIVERSIDE COUNTY LOP (LEAD) - CASE #: 9915850
CASEWORKER: SHARON BOLTINGHOUSE
SANTA ANA RWQCB (REGION 8) - CASE #: 083303617T
CASEWORKER: ROSE SCOTT
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History (as of Oct 06, 2020)

Status: Completed - Case Closed
Date : 10/20/2005

Status: Open - Site Assessment
Date : 11/29/1999

Status: Open - Case Begin Date
Date : 3/30/1999

LUST Sites from GeoTracker Search - Regulatory Activities (as of Oct 06, 2020)

Action Type: Other Regulatory Actions
Action Date: 10/19/2005
Received Issue Date: 10/19/2005
Action: File review - #RCDEH upoaded site file 2/13/2015
Doc Link: http://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500619&enforcement_id=6236012&temptable=ENFORCEMENT
Title Description Comments:

RCDEH uploaded site file 2/13/2015

Action Type: Leak Action
Action Date: 12/2/1999
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 11/29/1999
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 3/30/1999
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

LUST Sites from GeoTracker Search - Documents (as of Oct 06, 2020)

Document Type: Site Documents
Document Date: 10/24/2005
Size : 4,527 KB
Submitted By: (REGULATOR)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type: **Submitted:**
Title: CASE CLOSURE LETTER AND SUMMARY
Title Link: http://geotracker.waterboards.ca.gov/site_documents/1205509781/closure%209915850%2Epdf

Document Type: Site Documents **Size :**
Document Date: 10/19/2005 **Submitted By:** LINDA SHURLOW (REGULATOR)
Type: FILE REVIEW **Submitted:**
Title: RCDEH UPLOADED SITE FILE 2/13/2015
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0606500619&enforcement_id=6236012

---

33 | 1 of 5 | WNW | 0.30 / 1,604.58 | 815.32 / -2 | MIRA LOMA GM DEPOT | ENVIROSTOR

RIVERSIDE CA

Estor/EPA ID: 80000321 **Assembly District:** 60
Site Code: **Senate District:** 31
Nat Priority List: NO **Permit Renewal Lead:**
APN: NONE SPECIFIED **Public Partici Spclst:**
Census Tract: 6065040607 **Project Manager:**
Site Type: FUDS **County:** RIVERSIDE
Address Description: **Latitude:** 34.0291666666667
Office: CLEANUP CYPRESS **Longitude:** -117.545833333333
Special Program: **Acres:** NONE SPECIFIED
Funding: DERA **Supervisor:** DOUGLAS BAUTISTA
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000321

---

33 | 2 of 5 | WNW | 0.30 / 1,604.58 | 815.32 / -2 | MIRA LOMA AFS | ENVIROSTOR

MIRA LOMA CA

Estor/EPA ID: 80000319 **Assembly District:** 60
Site Code: **Senate District:** 31
Nat Priority List: NO **Permit Renewal Lead:**
APN: NONE SPECIFIED **Public Partici Spclst:**
Census Tract: 6065040607 **Project Manager:**
Site Type: FUDS **County:** RIVERSIDE
Address Description: **Latitude:** 34.0291666666667
Office: CLEANUP CYPRESS **Longitude:** -117.545833333333
Special Program: **Acres:** NONE SPECIFIED
Funding: DERA **Supervisor:** DOUGLAS BAUTISTA
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION

A2 Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000319

Completed Activities

Title: USACE INPR Summary J0CA048700 4 June 1991
Title Link: http://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80000319&doc_id=5010999
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Inventory Project Report (INPR)
Date Completed: 6/4/1991
Comments:

---

33 | 3 of 5 | WNW | 0.30 / 1,604.58 | 815.32 / -2 | QM SUPPLY DEPOT, MIRA LOMA CA | ENVIROSTOR

Estor/EPA ID: 80000871
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6065040607
Site Type: FUDS
Address Description:
Office: CLEANUP CYPRESS
Special Program:
Funding: DERA
Assembly District: 60
Senate District: 31
Permit Renewal Lead:
Public Partici Spclst: TIMOTHY CHAUVEL
Project Manager:
County: VENTURA
Latitude: 34.0291666666667
Longitude: -117.545833333333
Acres: NONE SPECIFIED
Supervisor: DOUGLAS BAUTISTA
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000871

Completed Activities

Title: USACE INPR Summary J0CA716900 10 May 1999
Title Link: http://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80000871&doc_id=5011181
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Inventory Project Report (INPR)
Date Completed: 5/10/1999
Comments:

---

33 | 4 of 5 | WNW | 0.30 / 1,604.58 | 815.32 / -2 | MIRA LOMA AIR FORCE STATION, MIRA LOMA CA | FUDS

FUDS No: J09CA0487
INST ID: CA99799F552000
EPA Region: 09
CONG DIST: 41

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Object ID:	4998	**County:**	RIVERSIDE
NPL Status:	Not Listed	**County Code:**	Los Angeles District (SPL)
Status:	Properties without projects	**Latitude:**	34.02916667
FY:	2018	**Longitude:**	-117.54583333
Eligibility:	Ineligible	**Has Projects:**	No
Current Owner:	Other		
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=61111		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
33	5 of 5	WNW	0.30 / 1,604.58	815.32 / -2	MIRA LOMA QUARTERMASTER DEPOT MIRA LOMA CA	FUDS

FUDS No:	J09CA0489	**EPA Region:**	09
INST ID:	CA99799F552200	**CONG DIST:**	41
Object ID:	5000	**County:**	RIVERSIDE
NPL Status:	Not Listed	**County Code:**	Los Angeles District (SPL)
Status:	Properties without projects	**Latitude:**	34.02916667
FY:	2018	**Longitude:**	-117.54583333
Eligibility:	Eligible	**Has Projects:**	No
Current Owner:	Other		
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=61112		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
34	1 of 1	ESE	0.33 / 1,753.60	810.39 / -7	CA	PFAS GW

Well ID:	3310021-024
Latitude:	34.023345
Longitude:	-117.521437
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	4.4	**Top of Screen (ft):**	230
Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	5.7	**Top of Screen (ft):**	230
Date :	12/30/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	6	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18

Well Depth (ft):

Perfluorooctanoic Acid

Chemical: PFOA
Results: 4.9
Date : 09/12/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

Perfluorooctanoic Acid

Chemical: PFOA
Results: 5
Date : 12/26/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 11/06/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

4,8-Dioxa-3H-perfluorononanoic acid

Chemical: ADONA
Results: 1.7
Date : 12/26/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 230
Screen Length (ft): 160
Source: DHS
Source Name: 3310021-024
Other Names: WELL 18

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	2.2	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	11/06/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	01/09/2020	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	09/12/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	12/26/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	230
Date :	12/30/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.2	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK

Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	230
Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.2	**Top of Screen (ft):**	230
Date :	12/30/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	230
Date :	12/30/2019	**Screen Length (ft):**	160

Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024

Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	01/09/2020	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	09/12/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	12/26/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	11/06/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	12/26/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	01/09/2020	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	11/06/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	09/12/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	01/09/2020	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	12/26/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	09/12/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	11/06/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	230
Date :	12/30/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	230
Date :	11/06/2019	***Screen Length (ft):***	160
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-024
Well Type:	MUNICIPAL	***Other Names:***	WELL 18
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	230
Date :	12/30/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	12/26/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	01/09/2020	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230

Date :	11/06/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	230
Date :	09/12/2019	**Screen Length (ft):**	160
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-024
Well Type:	MUNICIPAL	**Other Names:**	WELL 18
Well Depth (ft):			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	1 of 1	N	0.36 / 1,901.75	846.83 / 29	CA	PFAS GW

Well ID:	3310021-025
Latitude:	34.033255
Longitude:	-117.53255
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181

Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025

Well Type: MUNICIPAL
Well Depth (ft):
Other Names: WELL 19

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	297
Date :	12/30/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	12/27/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	11/07/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	01/09/2020	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	11/07/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	12/27/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	01/09/2020	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	09/12/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	297
Date :	12/30/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	12/27/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	09/12/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	01/09/2020	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297

Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	297
Date :	12/30/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS

Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	11/07/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	12/27/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	01/09/2020	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19

Well Depth (ft):

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 297
Screen Length (ft): 181
Source: DHS
Source Name: 3310021-025
Other Names: WELL 19

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	01/09/2020	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	09/12/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	297
Date :	12/30/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	01/09/2020	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	11/07/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	297
Date :	12/27/2019	***Screen Length (ft):***	181
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-025
Well Type:	MUNICIPAL	***Other Names:***	WELL 19
Well Depth (ft):			

Perfluoroundecanoic acid

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	297
Date :	09/12/2019	**Screen Length (ft):**	181
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-025
Well Type:	MUNICIPAL	**Other Names:**	WELL 19
Well Depth (ft):			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	1 of 1	SE	0.36 / 1,924.90	795.97 / -21	FOOD GAS & GO MINI MART 3710 ETIWANDA AVE MIRA LOMA CA	RIVERSIDE LOP

Site ID:	9814821	**Closed Code:**	Y
Status Code:	9	**Closed Desc:**	CLOSED SITE
Status Desc:	CLOSED/ACTION COMPLETED	**Employee:**	Boltinghous-LOP
Case Type Code:	S		
Case Type Desc:	SOIL ONLY IS IMPACTED		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	1 of 1	NE	0.37 / 1,949.23	846.37 / 29	CA	PFAS GW

Well ID:	3310021-003
Latitude:	34.033258
Longitude:	-117.525002
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198

Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS

Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06

Well Depth (ft):

Perfluorohexanoic acid

Chemical: PFHA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluorohexanoic acid

Chemical: PFHA
Results: 1.7
Date : 12/26/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluorohexanoic acid

Chemical: PFHA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 198
Screen Length (ft): 138
Source: DHS
Source Name: 3310021-003
Other Names: WELL 06

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	01/09/2020	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	12/26/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	01/09/2020	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	198
Date :	12/30/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	12/26/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	09/12/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK

Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	09/12/2019	**Screen Length (ft):**	138

Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	12/26/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	11/07/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	198
Date :	01/09/2020	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003
Well Type:	MUNICIPAL	**Other Names:**	WELL 06
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	198
Date :	12/30/2019	**Screen Length (ft):**	138
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-003

Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	12/26/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	09/12/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	11/07/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	01/09/2020	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	09/12/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	198
Date :	12/30/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	198
Date :	12/26/2019	***Screen Length (ft):***	138
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-003
Well Type:	MUNICIPAL	***Other Names:***	WELL 06
Well Depth (ft):			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
38	1 of 1	ENE	0.38 / 1,999.69	829.64 / 12	CA	PFAS GW

Well ID:	3310021-023
Latitude:	34.029167
Longitude:	-117.520556
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	32	***Top of Screen (ft):***	250
Date :	01/09/2020	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	23	***Top of Screen (ft):***	250
Date :	09/12/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	29	***Top of Screen (ft):***	250
Date :	12/26/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	20	***Top of Screen (ft):***	250
Date :	11/06/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	30	***Top of Screen (ft):***	250
Date :	12/30/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	01/09/2020	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	250
Date :	12/30/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	11/06/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	09/12/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	12/26/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.8
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 11/06/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorobutanesulfonic acid

Chemical: PFBSA
Results: 1.7
Date : 12/26/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 11/06/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorododecanoic acid

Chemical: PFDOA
RL: UNK

Results:	1.7	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	250
Date :	12/30/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	09/12/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	7.5	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	4.2	**Top of Screen (ft):**	250
Date :	11/06/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	6.1	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140

Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	5.8	**Top of Screen (ft):**	250
Date :	12/30/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	6.4	**Top of Screen (ft):**	250
Date :	09/12/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	3.1	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	3.8	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	3.3	**Top of Screen (ft):**	250
Date :	12/30/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2.1	**Top of Screen (ft):**	250
Date :	11/06/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-023

Well Type: MUNICIPAL
Well Depth (ft):
Other Names: WELL 17

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 3.3
Date : 09/12/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 2.8
Date : 12/30/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 2.2
Date : 09/12/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 3.7
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 2.7
Date : 12/26/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 2.1
Date : 11/06/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 250
Screen Length (ft): 140
Source: DHS
Source Name: 3310021-023
Other Names: WELL 17

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	11/06/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	01/09/2020	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	12/26/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	09/12/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	250
Date :	12/30/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	12/26/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	11/06/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	09/12/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	01/09/2020	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	250
Date :	12/30/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	250
Date :	11/06/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	250
Date :	12/30/2019	***Screen Length (ft):***	140
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-023
Well Type:	MUNICIPAL	***Other Names:***	WELL 17
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	09/12/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	11/06/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	09/12/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	250

Date :	12/30/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	11/06/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	250
Date :	12/30/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	09/12/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	01/09/2020	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-023
Well Type:	MUNICIPAL	**Other Names:**	WELL 17
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	250
Date :	12/26/2019	**Screen Length (ft):**	140
Units:	NG/L	**Source:**	DHS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
Source Name: 3310021-023
Other Names: WELL 17

---

39 | **1 of 2** | **NE** | **0.41 / 2,145.17** | **849.04 / 32** | **MIRA LOMA ENG SUB-DEPT** | **ENVIROSTOR**

RIVERSIDE CA

Estor/EPA ID: 80000320
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6065040503
Site Type: FUDS
Address Description:
Office: CLEANUP CYPRESS
Special Program:
Funding: DERA
Assembly District: 60
Senate District: 31
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: RIVERSIDE
Latitude: 34.0333333333333
Longitude: -117.523611111111
Acres: NONE SPECIFIED
Supervisor: DOUGLAS BAUTISTA
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 86-90%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000320

---

39 | **2 of 2** | **NE** | **0.41 / 2,145.17** | **849.04 / 32** | **MIRA LOMA ENGR SUB-DEPOT** | **FUDS**

NO CITY CA

FUDS No: J09CA0488
INST ID: CA99799F552100
Object ID: 4999
NPL Status: Not Listed
Status: Properties without projects
FY: 2018
Eligibility: Eligible
Current Owner: Private Sector
EMS Map Link: https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=53901
EPA Region: 09
CONG DIST: 41
County:
County Code: Los Angeles District (SPL)
Latitude: 34.03333333
Longitude: -117.52361111
Has Projects: No

---

40 | **1 of 1** | **S** | **0.41 / 2,167.87** | **790.03 / -27** | **UNITED NATURAL FOODS INC.** | **RCRA TSD**

WB 60 FWY @ MM 0.1
MIRA LOMA CA 91752

EPA Handler ID: CAC003012932
Gen Status Universe: No Report
Contact Name: JESSE CLARK
Contact Address: 313 IRON HORSE WAY , , PROVIDENCE , RI, 02908 ,
Contact Phone No and Ext: 909-912-4781
Contact Email: JTEJEDA@PATRIOTENVIRONMENTAL.COM
Contact Country:
Land Type:
County Name: RIVERSIDE
EPA Region: 09
Receive Date: 20190501
Location Latitude: 34.01783
Location Longitude: -117.533037

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190501
Handler Name:	UNITED NATURAL FOODS INC.
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	313 IRON HORSE WAY
Name:	JESSE CLARK	***Street 2:***	
Date Became Current:		***City:***	PROVIDENCE
Date Ended Current:		***State:***	RI
Phone:	909-912-4781	***Country:***	
Source Type:	Implementer	***Zip Code:***	02908

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	313 IRON HORSE WAY
Name:	UNITED NATURAL FOODS INC.	***Street 2:***	
Date Became Current:		***City:***	PROVIDENCE
Date Ended Current:		***State:***	RI
Phone:	909-912-4781	***Country:***	
Source Type:	Implementer	***Zip Code:***	02908

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	1 of 3	NE	0.42 / 2,200.77	850.46 / 33	US REDUCTION CO 11600 ETIWANDA AVE FONTANA CA 92335	CERCLIS

Site ID:	0900043	***RNPL Status Code:***	N
Site EPA ID:	CAD028833945	***NPL Status:***	Not on the NPL
Site Street Address 2:		***RFED Facility Code:***	N
Site County Name:	SAN BERNARDINO	***RFED Facility Desc:***	Not a Federal Facility
Site FIPS Code:	06071	***USGS Hydro Unit No.:***	18070203
Region Code:	09	***Site Cong. Dist. Code:***	36
Site SMSA No.:	6780	***ROT Desc:***	Private
Site Prim. Latitude:	34D06M00S	***FR NPL Update No.:***	

Site Prim. Longitude: 117D26M00S **RFRA Code:**
Lat Long Source:
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS Assess History

OU ID: 00 **RALT Short Name:** EPA Fund
Act Code ID: 001 **Act Start Date:**
RAT Code: PA **Act Complete Date:** 7/24/1989 00:00:00
RAT Short Name: PA **AGT Order No.:** 130
RAT Name: PRELIMINARY ASSESSMENT **SH OU:**
RAT Hist. Only Flag: **SH Code:**
RAT NSI Indicator: B **SH Seq:**
RAT Level: 1 **SH Start Date:**
RAT DEF OU: 00 **SH Complete Date:**
RFBS Code: P **SH Lead:**
SPA Code: 13
RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID: 00 **RALT Short Name:**
Act Code ID: **Act Start Date:**
RAT Code: **Act Complete Date:**
RAT Short Name: **AGT Order No.:** 0
RAT Name: **SH OU:**
RAT Hist. Only Flag: **SH Code:**
RAT NSI Indicator: **SH Seq:**
RAT Level: **SH Start Date:**
RAT DEF OU: **SH Complete Date:**
RFBS Code: **SH Lead:**
SPA Code:
RAT Def:
Site Desc: No description available
.
Site Alias: No alias data available

CERCLIS Assess History

OU ID: 00 **RALT Short Name:** EPA In-House
Act Code ID: 001 **Act Start Date:**
RAT Code: VS **Act Complete Date:** 7/24/1989 00:00:00
RAT Short Name: ARCH SITE **AGT Order No.:** 1500
RAT Name: ARCHIVE SITE **SH OU:**
RAT Hist. Only Flag: **SH Code:**
RAT NSI Indicator: B **SH Seq:**
RAT Level: 1 **SH Start Date:**
RAT DEF OU: 00 **SH Complete Date:**
RFBS Code: **SH Lead:**
SPA Code: 13
RAT Def: The decision is made that no further activity is planned at the site.
Site Desc:
Site Alias:

CERCLIS Assess History

OU ID: 00 **RALT Short Name:** State (Fund)
Act Code ID: 001 **Act Start Date:**
RAT Code: DS **Act Complete Date:** 12/1/1987 00:00:00
RAT Short Name: DISCVRY **AGT Order No.:** 10
RAT Name: DISCOVERY **SH OU:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAT Hist. Only Flag:		**SH Code:**	
RAT NSI Indicator:	B	**SH Seq:**	
RAT Level:	1	**SH Start Date:**	
RAT DEF OU:	00	**SH Complete Date:**	
RFBS Code:		**SH Lead:**	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	2 of 3	NE	0.42 / 2,200.77	850.46 / 33	US REDUCTION CO 11600 ETIWANDA AVE FONTANA CA 92335	CERCLIS NFRAP

Site ID:	900043	**Site FIPS Code:**	6071
Site EPA ID:	CAD028833945	**Region Code:**	9
Site Parent ID:		**Site Cong. Dist. Code:**	36
Site County Name:	SAN BERNARDINO	**Federal Facility:**	
Parent Site Name:			

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	
Act Code ID:	1	**Act Complete Date:**	12/1/1987
RAT Code:	DS	**AGT Order No.:**	10
RAT Short Name:	DISCVRY	**SH OU:**	
RAT Name:	DISCOVERY	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:		**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	
RALT Short Name:	State (Fund)	**RNPL Status Code:**	N

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	
Act Code ID:	1	**Act Complete Date:**	7/24/1989
RAT Code:	PA	**AGT Order No.:**	130
RAT Short Name:	PA	**SH OU:**	
RAT Name:	PRELIMINARY ASSESSMENT	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	
RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:	P	**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	NFRAP
RALT Short Name:	EPA Fund	**RNPL Status Code:**	N

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assess History

OU ID:	0	**Act Start Date:**	
Act Code ID:	1	**Act Complete Date:**	7/24/1989
RAT Code:	VS	**AGT Order No.:**	1500
RAT Short Name:	ARCH SITE	**SH OU:**	
RAT Name:	ARCHIVE SITE	**SH Code:**	
RAT Hist. Only Flag:		**SH Seq:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAT NSI Indicator:	B	**SH Start Date:**	
RAT Level:	1	**SH Complete Date:**	
RAT DEF OU:	00	**SH Lead:**	
RFBS Code:		**SH Qual:**	
SPA Code:	13	**RAQ Act. Qual Short:**	
RALT Short Name:	EPA In-House	**RNPL Status Code:**	N
RAT Def:	The decision is made that no further activity is planned at the site.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

---

41 | **3 of 3** | **NE** | **0.42 / 2,200.77** | **850.46 / 33** | **US REDUCTION CO**
11600 ETIWANDA AVE
FONTANA CA 92335 | **SEMS ARCHIVE**

Site ID:	0900043	**FIPS Code:**	06071
EPA ID:	CAD028833945	**Cong District:**	36
Superfund Alt Agmt:	No	**Region:**	09
Federal Facility:	No	**County:**	SAN BERNARDINO
FF Docket:	No		
NPL:	Not on the NPL		
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information		

Action Information

Operable Units:	00	**Start Actual:**	
Action Code:	VS	**Finish Actual:**	07/23/1989
Action Name:	ARCH SITE	**Qual:**	
SEQ:	1	**Curr Action Lead:**	EPA Perf In-Hse
Operable Units:	00	**Start Actual:**	
Action Code:	PA	**Finish Actual:**	07/23/1989
Action Name:	PA	**Qual:**	N
SEQ:	1	**Curr Action Lead:**	EPA Perf
Operable Units:	00	**Start Actual:**	11/30/1987
Action Code:	DS	**Finish Actual:**	11/30/1987
Action Name:	DISCVRY	**Qual:**	
SEQ:	1	**Curr Action Lead:**	St Perf

---

42 | **1 of 1** | **WNW** | **0.42 / 2,226.24** | **834.40 / 17** | **PHILADELPHIA RECYCLING MINE**
RIVERSIDE COUNTY
MIRA LOMA CA 91752 | **MRDS**

Dep ID:	10164184	**I1:**	19
Dev Status:	PRODUCER	**Latitude:**	34.030884
Code List:	SDG	**Longitude:**	-117.546692
Url:	http://mrdata.usgs.gov/mrds/show-mrds.php?dep_id=10164184		

Commodity

I1:	34	**Line:**	1
Code:	SDG	**Inserted By:**	MAS migration
Commodity:	Sand and Gravel, Cons	**Insert Date:**	29-OCT-2002 09:00:24
Commodity Type:	Non-metallic	**Updated By:**	USGS
Commodity Group:	Sand and Gravel	**Update Date:**	29-OCT-2002 09:01:38
Importance:	Primary		

Names

I1:	33	**Inserted By:**	MAS migration
Status:	Previous	**Insert Date:**	29-OCT-02
Site Name:	Triangle Rock Products, Ind	**Updated By:**	USGS
Line:	1	**Update Date:**	29-OCT-02

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Names

I1:	33	***Inserted By:***	MAS migration
Status:	Current	***Insert Date:***	29-OCT-02
Site Name:	Philadelphia Recycling Mine	***Updated By:***	USGS
Line:	3	***Update Date:***	29-OCT-02

Names

I1:	33	***Inserted By:***	MAS migration
Status:	Previous	***Insert Date:***	29-OCT-02
Site Name:	Triangle Rock Products Pit	***Updated By:***	USGS
Line:	2	***Update Date:***	29-OCT-02

43	*1 of 2*	*ESE*	*0.44 / 2,319.33*	*798.08 / -19*	***MARIA LEDEZMA 10882 WINDSOR PLACE MIRA LOMA CA 91752***	***RCRA TSD***

EPA Handler ID:	CAC003018351
Gen Status Universe:	No Report
Contact Name:	MARIA LEDEZMA
Contact Address:	10882 WINDSOR PLACE , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	951-870-9766
Contact Email:	ANAB@PWSEI.COM
Contact Country:	
Land Type:	
County Name:	RIVERSIDE
EPA Region:	09
Receive Date:	20190605
Location Latitude:	34.019593
Location Longitude:	-117.521714

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190605
Handler Name:	MARIA LEDEZMA
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	10882 WINDSOR PLACE
Name:	MARIA LEDEZMA	***Street 2:***	
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	951-870-9766	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	10882 WINDSOR PLACE
Name:	MARIA LEDEZMA	***Street 2:***	
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	951-870-9766	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

43	***2 of 2***	***ESE***	***0.44 / 2,319.33***	***798.08 / -19***	***MARIA LEDEZMA 10882 WINDSOR PLACE MIRA LOMA CA 91752***	***RCRA TSD***

EPA Handler ID:	CAC003013651
Gen Status Universe:	No Report
Contact Name:	MARIA LEDEZMA
Contact Address:	10882 WINDSOR PLACE , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	951-870-9766
Contact Email:	VIANCATARANGO@ALLIANCE-ENVIRO.COM
Contact Country:	
Land Type:	
County Name:	RIVERSIDE
EPA Region:	09
Receive Date:	20190506
Location Latitude:	34.019593
Location Longitude:	-117.521714

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1

Receive Date:	20190506
Handler Name:	MARIA LEDEZMA
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	10882 WINDSOR PLACE
Name:	MARIA LEDEZMA	**Street 2:**	
Date Became Current:		**City:**	MIRA LOMA
Date Ended Current:		**State:**	CA
Phone:	951-870-9766	**Country:**	
Source Type:	Implementer	**Zip Code:**	91752

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	10882 WINDSOR PLACE
Name:	MARIA LEDEZMA	**Street 2:**	
Date Became Current:		**City:**	MIRA LOMA
Date Ended Current:		**State:**	CA
Phone:	951-870-9766	**Country:**	
Source Type:	Implementer	**Zip Code:**	91752

44	1 of 1	NW	0.44 / 2,320.44	849.99 / 33	**3M WEST COAST DISTRIBUTION CENTER** **5151 E. PHILADELPHIA ST** **ONTARIO CA 91761-0000**	RCRA TSD

EPA Handler ID:	CAD982403966
Gen Status Universe:	Large Quantity Generator
Contact Name:	GENE GEIGER
Contact Address:	5151 , E. PHILADELPHIA ST , , ONTARIO , CA, 91761-0000 , US
Contact Phone No and Ext:	909-974-6033
Contact Email:	GPGEIGER@MMM.COM
Contact Country:	US
Land Type:	Private
County Name:	SAN BERNARDINO
EPA Region:	09
Receive Date:	20180228
Location Latitude:	34.033464
Location Longitude:	-117.541621

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Jan, 2021.

Violation Details

Citation:	
Violation Short Description:	Generators - Pre-transport
Violation Type:	262.C
Violation Determined Date:	20160909
Scheduled Compliance Date:	
Return to Compliance:	Documented
Actual Return to Compl:	20161205
Violation Responsible Agency:	State

Violation Details

Citation:	
Violation Short Description:	Generators - General

Violation Type: 262.A
Violation Determined Date: 20080312
Scheduled Compliance Date:
Return to Compliance:
Actual Return to Compl:
Violation Responsible Agency: State

Violation Details

Citation:
Violation Short Description: Generators - General
Violation Type: 262.A
Violation Determined Date: 20080312
Scheduled Compliance Date:
Return to Compliance: Documented
Actual Return to Compl: 20080516
Violation Responsible Agency: State

Evaluation Details

Evaluation Start Date: 20160909
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - Pre-transport
Return to Compliance Date: 20161205
Evaluation Agency: State

Evaluation Start Date: 20080312
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date:
Evaluation Agency: State

Evaluation Start Date: 20080312
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description: Generators - General
Return to Compliance Date: 20080516
Evaluation Agency: State

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19900226
Handler Name: 3 M WEST COAST DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19920331
Handler Name: 3M WEST COAST DISTRIBUTION CTR.
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 19940302
Handler Name: 3M ONTARIO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 19960227
Handler Name: 3M ONTARIO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960901
Handler Name: 3 M WEST COAST DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Implementer

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 19990304
Handler Name: 3M COMPANY (WEST COAST DIST. CENTER)
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 5
Receive Date: 20001012
Handler Name: 3M COMPANY (WEST COAST DISTR. CENTER)
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 6
Receive Date: 20020222
Handler Name: 3M WEST COAST DISTRIBUTION CENTER
Federal Waste Generator Code: 1

Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20031105
Handler Name: 3M WEST COAST DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Handler Details

Sequence No: 7
Receive Date: 20040219
Handler Name: 3M WESTERN DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Handler Details

Sequence No: 8
Receive Date: 20060223
Handler Name: 3M WESTERN DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: 134
Waste Code Description: Aqueous solution with <10% total organic residues

Hazardous Waste Code: 141
Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 221
Waste Code Description: Waste oil and mixed oil

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: 352
Waste Code Description: Other organic solids

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Handler Details

Sequence No: 9
Receive Date: 20080407
Handler Name: 3M WESTERN DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20120307
Handler Name: EXEL LOGISTICS (WDC) ONTARIO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20140301
Handler Name: 3M ONTARIO
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20160122
Handler Name: 3M
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20180228

Handler Name: 3M WEST COAST DISTRIBUTION CENTER
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report update with Notification

Waste Code Details

Hazardous Waste Code: 281
Waste Code Description: Adhesives

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: 3 M COMPANY
Date Became Current: 19890201
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: 3M
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: 3M COMPANY
Date Became Current: 19890201
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Operator
Type: Private
Name: 3M COMPANY
Date Became Current: 19900219
Date Ended Current:
Phone:
Source Type: Annual/Biennial Report
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: GENE GEIGER
Date Became Current: 20160101
Date Ended Current:
Phone: 909-974-6033
Source Type: Annual/Biennial Report update with Notification
Street No: 5151
Street 1: E. PHILADELPHIA ST
Street 2:
City: ONTARIO
State: CA
Country: US
Zip Code: 91761-0000

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 33331
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19890201	**City:**	ST. PAUL
Date Ended Current:		**State:**	MN
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	55133-3331

Owner/Operator Ind:	Current Owner	**Street No:**	5151
Type:	Private	**Street 1:**	E PHILADELPHIA ST
Name:	3M ONTARIO	**Street 2:**	
Date Became Current:	19900301	**City:**	ONTARIO
Date Ended Current:		**State:**	CA
Phone:	909-974-9003	**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	91761

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	PO BOX 33331
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19900219	**City:**	ST. PAUL
Date Ended Current:		**State:**	MN
Phone:		**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	55133-3331

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	EXEL LOGISTICS	**Street 2:**	
Date Became Current:	20110409	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19890201	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	3M	**Street 2:**	
Date Became Current:	19881201	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	5151
Type:	Private	**Street 1:**	E. PHILADELPHIA ST
Name:	3M	**Street 2:**	
Date Became Current:	20160101	**City:**	ONTARIO
Date Ended Current:		**State:**	CA
Phone:	909-974-6033	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	91761-0000

Owner/Operator Ind:	Current Owner	**Street No:**	5151
Type:	Private	**Street 1:**	E. PHILADELPHIA ST
Name:	GENE GEIGER	**Street 2:**	
Date Became Current:	20160101	**City:**	ONTARIO
Date Ended Current:		**State:**	CA
Phone:	909-974-6033	**Country:**	US
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	91761

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	EXEL LOGISTICS	**Street 2:**	
Date Became Current:	20110411	**City:**	
Date Ended Current:		**State:**	

Phone:		**Country:**	
Source Type:	Annual/Biennial Report update with Notification	**Zip Code:**	
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	NOT REQUIRED
Name:	NOT REQUIRED	**Street 2:**	
Date Became Current:		**City:**	NOT REQUIRED
Date Ended Current:		**State:**	ME
Phone:	415-555-1212	**Country:**	
Source Type:	Implementer	**Zip Code:**	99999
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	I94 AND MCKNIGHT ROAD
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19890201	**City:**	ST. PAUL
Date Ended Current:		**State:**	MN
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	55144
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19890201	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	I94 AND MCKNIGHT RD
Name:	3M COMPANY	**Street 2:**	
Date Became Current:	19890201	**City:**	ST PAUL
Date Ended Current:		**State:**	MN
Phone:		**Country:**	US
Source Type:	Annual/Biennial Report	**Zip Code:**	55144

Historical Handler Details

Receive Dt:	20160122
Generator Code Description:	Large Quantity Generator
Handler Name:	3M
Receive Dt:	20140301
Generator Code Description:	Large Quantity Generator
Handler Name:	3M ONTARIO
Receive Dt:	20120307
Generator Code Description:	Large Quantity Generator
Handler Name:	EXEL LOGISTICS (WDC) ONTARIO
Receive Dt:	20080407
Generator Code Description:	Large Quantity Generator
Handler Name:	3M WESTERN DISTRIBUTION CENTER
Receive Dt:	20060223
Generator Code Description:	Large Quantity Generator
Handler Name:	3M WESTERN DISTRIBUTION CENTER
Receive Dt:	20040219
Generator Code Description:	Large Quantity Generator
Handler Name:	3M WESTERN DISTRIBUTION CENTER
Receive Dt:	20031105
Generator Code Description:	Large Quantity Generator
Handler Name:	3M WEST COAST DISTRIBUTION CENTER
Receive Dt:	20020222
Generator Code Description:	Large Quantity Generator
Handler Name:	3M WEST COAST DISTRIBUTION CENTER

Receive Dt: 20001012
Generator Code Description: Large Quantity Generator
Handler Name: 3M COMPANY (WEST COAST DISTR. CENTER)

Receive Dt: 19990304
Generator Code Description: Large Quantity Generator
Handler Name: 3M COMPANY (WEST COAST DIST. CENTER)

Receive Dt: 19960901
Generator Code Description: Large Quantity Generator
Handler Name: 3 M WEST COAST DISTRIBUTION CENTER

Receive Dt: 19960227
Generator Code Description: Large Quantity Generator
Handler Name: 3M ONTARIO

Receive Dt: 19940302
Generator Code Description: Large Quantity Generator
Handler Name: 3M ONTARIO

Receive Dt: 19920331
Generator Code Description: Large Quantity Generator
Handler Name: 3M WEST COAST DISTRIBUTION CTR.

Receive Dt: 19900226
Generator Code Description: Large Quantity Generator
Handler Name: 3 M WEST COAST DISTRIBUTION CENTER

---

45 **1 of 1** **ENE** **0.45 / 2,363.96** **849.05 / 32** **CA** **PFAS GW**

Well ID: 3310021-019
Latitude: 34.033033
Longitude: -117.521862
Data Source(s): Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical: PFOA
Results: 2.3
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorooctanoic Acid

Chemical: PFOA
Results: 3.9
Date : 12/30/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorooctanoic Acid

Chemical: PFOA
Results: 2.4
Date : 11/07/2019
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226

Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	2.5	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	11	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	01/09/2020	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019

Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	01/09/2020	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	11/07/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	12/26/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	11/07/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	01/09/2020	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	12/26/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	11/07/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.9	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	4.8	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	01/09/2020	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	12/26/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	01/09/2020	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	01/09/2020	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	220

Date :	12/30/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	01/09/2020	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	220
Date :	12/30/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS

Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	220
Date :	12/30/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	01/09/2020	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	09/12/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13

Well Depth (ft):

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 11/07/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.7
Date : 12/26/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotetradecanoic acid

Chemical: PFTEDA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 12/26/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft): 220
Screen Length (ft): 226
Source: DHS
Source Name: 3310021-019
Other Names: WELL 13

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	11/07/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	220
Date :	12/30/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	09/12/2019	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	220
Date :	01/09/2020	***Screen Length (ft):***	226
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-019
Well Type:	MUNICIPAL	***Other Names:***	WELL 13
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	12/26/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	220
Date :	11/07/2019	**Screen Length (ft):**	226
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-019
Well Type:	MUNICIPAL	**Other Names:**	WELL 13
Well Depth (ft):			

---

46 **1 of 1** **SW** **0.46 / 2,439.23** **791.82 / -26** **CA** ***PFAS GW***

Well ID:	3310021-057
Latitude:	34.018983
Longitude:	-117.543247
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	5.1	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	5.5	**Top of Screen (ft):**	
Date :	12/17/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	6.1	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	7.2	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	5.3	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	6.9	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	

Date :	12/17/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	4	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	**RL:**	UNK
Results:	2.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS

Qualifer:		***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	4.2	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	2.6	***Top of Screen (ft):***	
Date :	12/03/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	3.5	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	2.9	***Top of Screen (ft):***	
Date :	12/17/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28

Well Depth (ft):

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 12/17/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 12/27/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 11/06/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorododecanoic acid

Chemical: PFDOA
Results: 2
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.8
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorododecanoic acid

Chemical: PFDOA
Results: 1.7
Date : 12/03/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 5.5
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 3.4
Date : 12/03/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 4.2
Date : 12/17/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 5.1
Date : 12/30/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 1.8
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical: PFHA
Results: 4.2
Date : 12/27/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	4.2	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2.1	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2.1	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2.8	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK

Results: 2.3
Date : 12/27/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluoroheptanoic acid

Chemical: PFHPA
Results: 2.4
Date : 12/17/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 9.3
Date : 12/27/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 9.9
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 7.4
Date : 11/06/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 8.4
Date : 12/17/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-057
Other Names: WELL 28

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 1.8
Date : 09/12/2019
RL: UNK
Top of Screen (ft):
Screen Length (ft):

Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	11	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	**RL:**	UNK
Results:	7.3	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/17/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057

Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/03/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/17/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/03/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/03/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/17/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/27/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-057
Well Type:	MUNICIPAL	***Other Names:***	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/17/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	

Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/03/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/17/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/27/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Qualifer:	<	**Source Name:**	3310021-057
Well Type:	MUNICIPAL	**Other Names:**	WELL 28
Well Depth (ft):			

---

47 | **1 of 1** | **S** | **0.47 / 2,468.27** | **789.15 / -28** | **CA** | **PFAS GW**

Well ID:	3310021-056
Latitude:	34.017237
Longitude:	-117.532242
Data Source(s):	Perfluorooctanoic Acid; 4,8-Dioxa-3H-perfluorononanoic acid; Perfluorobutanesulfonic acid; Perfluorododecanoic acid; Perfluorohexanoic acid; Perfluoroheptanoic acid; Perfluorohexanesulfonic acid; Perfluorononanoic acid; Perfluorooctadecanoic acid; Perfluorotetradecanoic acid; Perfluorotridecanoic acid; Perfluoroundecanoic acid

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	4.8	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	2.6	**Top of Screen (ft):**	
Date :	12/26/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	2.7	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	4.4	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	**RL:**	UNK
Results:	5.1	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056

Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	2.5	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorooctanoic Acid

Chemical:	PFOA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	06/18/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

4,8-Dioxa-3H-perfluorononanoic acid

Chemical:	ADONA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	06/18/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorobutanesulfonic acid

Chemical:	PFBSA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/26/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorododecanoic acid

Chemical:	PFDOA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.8	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.4	**Top of Screen (ft):**	

Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	04/21/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	3.3	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	12/26/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	2.2	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorohexanoic acid

Chemical:	PFHA	**RL:**	UNK
Results:	5.1	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS

Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	04/21/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/26/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:		**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluoroheptanoic acid

Chemical:	PFHPA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27

Well Depth (ft):

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 2
Date : 04/21/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 3.6
Date : 12/26/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 8.3
Date : 11/06/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 8.3
Date : 09/12/2019
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 5.7
Date : 06/18/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical: PFHXSA
Results: 3.5
Date : 01/09/2020
Units: NG/L
Qualifer:
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorohexanesulfonic acid

Chemical:	PFHXSA	***RL:***	UNK
Results:	5	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:		***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	06/18/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorononanoic acid

Chemical:	PFNA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	04/21/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	12/26/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	09/12/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	11/06/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK

Results:	1.8	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorooctadecanoic acid

Chemical:	PFNDCA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.8	**Top of Screen (ft):**	
Date :	12/30/2019	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	04/21/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	1.7	**Top of Screen (ft):**	
Date :	01/09/2020	**Screen Length (ft):**	
Units:	NG/L	**Source:**	DHS
Qualifer:	<	**Source Name:**	3310021-056
Well Type:	MUNICIPAL	**Other Names:**	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	**RL:**	UNK
Results:	2	**Top of Screen (ft):**	
Date :	06/18/2020	**Screen Length (ft):**	

Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotetradecanoic acid

Chemical:	PFTEDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	09/12/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluorotridecanoic acid

Chemical:	PFTRIDA	***RL:***	UNK
Results:	1.8	***Top of Screen (ft):***	
Date :	12/30/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056

Well Type: MUNICIPAL
Well Depth (ft):
Other Names: WELL 27

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 01/09/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 2
Date : 06/18/2020
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluorotridecanoic acid

Chemical: PFTRIDA
Results: 1.7
Date : 11/06/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluoroundecanoic acid

Chemical: PFUNDCA
Results: 1.7
Date : 09/12/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluoroundecanoic acid

Chemical: PFUNDCA
Results: 1.8
Date : 12/30/2019
Units: NG/L
Qualifer: <
Well Type: MUNICIPAL
Well Depth (ft):
RL: UNK
Top of Screen (ft):
Screen Length (ft):
Source: DHS
Source Name: 3310021-056
Other Names: WELL 27

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	01/09/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	11/06/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	04/21/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	1.7	***Top of Screen (ft):***	
Date :	12/26/2019	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

Perfluoroundecanoic acid

Chemical:	PFUNDCA	***RL:***	UNK
Results:	2	***Top of Screen (ft):***	
Date :	06/18/2020	***Screen Length (ft):***	
Units:	NG/L	***Source:***	DHS
Qualifer:	<	***Source Name:***	3310021-056
Well Type:	MUNICIPAL	***Other Names:***	WELL 27
Well Depth (ft):			

---

48 | ***1 of 1*** | ***NNE*** | ***0.61 / 3,195.21*** | ***858.97 / 42*** | ***MARCH COMM ANNEX RIVERSIDE CA*** | ***ENVIROSTOR***

Estor/EPA ID:	80000081	***Assembly District:***	52
Site Code:		***Senate District:***	20
Nat Priority List:	NO	***Permit Renewal Lead:***	
APN:	NONE SPECIFIED	***Public Partici Spclst:***	
Census Tract:	6071012700	***Project Manager:***	
Site Type:	FUDS	***County:***	SAN BERNARDINO
Address Description:		***Latitude:***	34.0369444444444

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Office: CLEANUP CYPRESS
Special Program:
Funding: DERA
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF 7/1/2005
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Longitude: -117.526388888889
Acres: NONE SPECIFIED
Supervisor: DOUGLAS BAUTISTA

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 76-80%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80000081

49	1 of 2	NE	0.62 / 3,293.27	864.76 / 47	BUILDING MATERIALS MANUFACTURING CORP 11800 INDUSTRY AVE FONTANA CA 923370000	HWP

Estor/EPA ID: CAD021789284
Site Code:
Nat Priority List:
Acres:
Special Program:
Funding:
Assembly District: 47
Senate District: 20
School District:
APN:
Cleanup Status:
Cleanup Oversight Agencies:
Site Type: CLOSED
Office:
Past Use that Caused Contam:
Potential Media Affected:
Potential Contamin of Concern:

Site History:

4/12/2017- Building Materials Manufacturing Corp is a generator only and was never regulated as a TSDF. The HWTS database shows that they have been a generator from 1993 - present. Also see enforcement order as it refers to this facility as a hazardous waste generator. Therefore, this facility is being administrative closed due to never being regulated as a TSDF.

Permit Renewal Lead:
Project Manager:
Supervisor:
Public Partici Spclst:
Census Tract:
County: SAN BERNARDINO
Latitude: 34.036439
Longitude: -117.522602

Status: CLOSED
Program Type: HAZ WASTE - RCRA
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CAD021789284

Permit Units - Completed Activities

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

Units Undergoing Closure

Unit: UNIT1
Event Description: CLOSURE ADMINISTRATIVE - ISSUE CLOSURE VERIFICATION
Date: 4/12/2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Doc Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_final_documents?global_id=CAD021789284&link_key=1235&document_category=CLOSURE+VERIFICATION&event_description=Closure+Administrative+%2D+ISSUE+CLOSURE+VERIFICATION+&mytype=pa

---

49 | **2 of 2** | **NE** | **0.62 / 3,293.27** | **864.76 / 47** | **BUILDING MATERIALS MANUFACTURING CORP**
11800 INDUSTRY AVE
FONTANA CA 923370000 | **ENVIROSTOR**

Estor/EPA ID: CAD021789284
Site Code:
Nat Priority List:
APN:
Census Tract:
Site Type: CLOSED
Address Description: 11800 INDUSTRY AVE
Office:
Special Program:
Funding:
Cleanup Status:
Cleanup Oversight Agencies:
School District:
Past Use that Caused Contam:
Potential Media Affected:
Potential Contamin of Concern:

Assembly District: 47
Senate District: 20
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN BERNARDINO
Latitude: 34.036439
Longitude: -117.522602
Acres:
Supervisor:

Site History:

4/12/2017- Building Materials Manufacturing Corp is a generator only and was never regulated as a TSDF. The HWTS database shows that they have been a generator from 1993 - present. Also see enforcement order as it refers to this facility as a hazardous waste generator. Therefore, this facility is being administrative closed due to never being regulated as a TSDF.

Status: CLOSED
A2 Program Type: HAZ WASTE - RCRA
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_profile_report?global_id=CAD021789284

Permit Units - Completed Activities

Unit: NO PERMIT ACTIVITIES HAVE BEEN COMPLETED FOR THIS SITE
Event Description:
Date:
Doc Link:

Units Undergoing Closure

Unit: UNIT1
Event Description: CLOSURE ADMINISTRATIVE - ISSUE CLOSURE VERIFICATION
Date: 4/12/2017
Doc Link: http://www.envirostor.dtsc.ca.gov/public/hwmp_final_documents?global_id=CAD021789284&link_key=1235&document_category=CLOSURE+VERIFICATION&event_description=Closure+Administrative+%2D+ISSUE+CLOSURE+VERIFICATION+&mytype=pa

---

50 | **1 of 1** | **ESE** | **0.78 / 4,093.63** | **784.88 / -33** | **ALUMINUM DIE CASTING**
10775 SAN SEVAINE WAY
MIRA LOMA CA 91752 | **ENVIROSTOR**

Estor/EPA ID: 71002959
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6065040503
Site Type: TIERED PERMIT
Address Description: 10775 SAN SEVAINE WAY

Assembly District: 60
Senate District: 31
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: RIVERSIDE
Latitude: 34.0164848705212

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Office: CLEANUP CYPRESS
Special Program:
Funding:
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Longitude: -117.517594117038
Acres: NONE SPECIFIED
Supervisor:

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: TIERED PERMIT
CalEnviroScreen Score: 86-90%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71002959

Completed Activities

Title: Phase I Non-Submittal
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1 Non-Submittal
Date Completed: 11/14/2000
Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
51	1 of 1	NE	0.79 / 4,162.80	874.19 / 57	CAPITOL INDUSTRIAL PROPERTY SOUTH END OF INDUSTRY AVE,N OF RIVERSIDE FONTANA CA 92335	ENVIROSTOR

Estor/EPA ID: 36280130
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6071002204
Site Type: * HISTORICAL
Address Description: SOUTH END OF INDUSTRY AVE,N OF RIVERSIDE
Office: CLEANUP CYPRESS
Special Program: * CERC2
Funding:
Cleanup Status: NO FURTHER ACTION AS OF 9/26/1988
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: AGRICULTURAL - ROW CROPS, MANUFACTURING - OTHER
Potential Media Affected: SOIL
Potential Contamin of Concern:

NO CONTAMINANTS FOUND

Site History:

During a 1987 drive by inspection performed by Department of Health Services, no drums containing hazardous or other waste were seen, no evidence of any hazardous, toxic or other wastes was noted. The entire Site was observed as being paved. According to historical records, groundwater is approximately 200 feet below ground surface.

Assembly District: 47
Senate District: 20
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN BERNARDINO
Latitude: 34.0387012048192
Longitude: -117.52165
Acres: 2 ACRES
Supervisor: PATRICK HSIEH

Status: NO FURTHER ACTION
A2 Program Type: HISTORICAL
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36280130

Completed Activities

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 3/19/1989
Comments: SITE SCREENING DONE NFA UNDER SITE MITIGATION; NO EVIDENCE OF HAZARDOUS MATERIAL ON SITE

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 10/25/1994
Comments: Database verification project; NFA confirmed.

Title: Preliminary Assessment Report
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Assessment Report
Date Completed: 9/29/1987
Comments: PRELIM ASSESS DONE COMPANY OFFICALS CLAIM DRUMS REMOVED BEFORE VALMONT MOVED-IN, SITE RECENTLY REPAVED,CONTENTS OF DRUMS UNKNOWN NO EVIDENCE OF CONTAMINATION ON SITE

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 9/26/1988
Comments: SITE SCREENING DONE NFA UNDER CERCLA

Title: Discovery
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Discovery
Date Completed: 6/10/1983
Comments: FACILITY IDENTIFIED DRIVEBY. INACTIVE FACILITY. FACILITY DRIVE-BY SOME DRUMS LABELED "CORROSIVE". 25 55-GALLON DRUMS IN YARD.

Title: Internal file review.
Title Link: http://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=36280130&enforcement_id=60441841
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 3/6/2018
Comments:

Title: Site Screening

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 3/10/1987
Comments: SITE SCREENING DONE FURTHER RECORD SEARCH NEEDED TO DETER- MINE EXACT OPERATION.

---

52 | 1 of 2 | NE | 0.79 / 4,163.33 | 874.19 / 57 | ORCHID PAPER PRODUCTS INDUSTRY AVENUE FONTANA CA 92335 | RESPONSE

Estor/EPA ID: 36260001
Site Code:
Nat Priority List: NO
Acres: 1 ACRES
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 47
Senate District: 20
School District:
APN: NONE SPECIFIED
Cleanup Status: CERTIFIED AS OF 12/1/1983
Cleanup Oversight Agencies: NONE SPECIFIED
Site Type: STATE RESPONSE OR NPL
Office: CLEANUP CYPRESS
Past Use that Caused Contam: ILLEGAL DUMPING
Potential Media Affected: SOIL
Potential Contamin of Concern:

PYRIDINE

Permit Renewal Lead:
Project Manager:
Supervisor: THOMAS COTA
Public Partici Spclst:
Census Tract: 6071002204
County: SAN BERNARDINO
Latitude: 34.0386759036145
Longitude: -117.521575

Site History:

In 1983 hazardous wastes from Orchid Paper Company, Fontana, were dumped in a vacant lot adjacent to the facility. An investigation began to find who was responsible for the illegal dumping. About twenty-eight (28) 55 gallon drums containing glue, paper and small amounts of a carcinogenic chemical. In 1985 the company agreed to pay $100,000 in settlement fees for a civil suit to San Bernardino County. File Room cleanup conducted on February 22, 2018 revealed that there are NO files for this Facility exist in the File Room.

Status: CERTIFIED
Program Type: STATE RESPONSE
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36260001

Completed Activities

Title: Certification
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Date Completed: 12/1/1983
Comments: Our records do not indicate the actual date this site was certified. Our records show 12/1983. We have used 12/01/1983 because this gives us the earliest statute of limitations.

---

52 | 2 of 2 | NE | 0.79 / 4,163.33 | 874.19 / 57 | ORCHID PAPER PRODUCTS INDUSTRY AVENUE FONTANA CA 92335 | ENVIROSTOR

Estor/EPA ID: 36260001
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Assembly District: 47
Senate District: 20
Permit Renewal Lead:
Public Partici Spclst:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Census Tract: 6071002204
Site Type: STATE RESPONSE OR NPL
Address Description: INDUSTRY AVENUE
Office: CLEANUP CYPRESS
Special Program:
Funding: RESPONSIBLE PARTY
Cleanup Status: CERTIFIED AS OF 12/1/1983
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: ILLEGAL DUMPING
Potential Media Affected: SOIL
Site History:

Project Manager:
County: SAN BERNARDINO
Latitude: 34.0386759036145
Longitude: -117.521575
Acres: 1 ACRES
Supervisor: THOMAS COTA

In 1983 hazardous wastes from Orchid Paper Company, Fontana, were dumped in a vacant lot adjacent to the facility. An investigation began to find who was responsible for the illegal dumping. About twenty-eight (28) 55 gallon drums containing glue, paper and small amounts of a carcinogenic chemical. In 1985 the company agreed to pay $100,000 in settlement fees for a civil suit to San Bernardino County. File Room cleanup conducted on February 22, 2018 revealed that there are NO files for this Facility exist in the File Room.

Potential Contamin of Concern:

PYRIDINE

Status: CERTIFIED
A2 Program Type: STATE RESPONSE
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36260001

Completed Activities

Title: Certification
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Date Completed: 12/1/1983
Comments: Our records do not indicate the actual date this site was certified. Our records show 12/1983. We have used 12/01/1983 because this gives us the earliest statute of limitations.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
53	1 of 1	NE	0.87 / 4,571.64	874.45 / 57	SIERRA ALUMINUM CO. - 11806 PACIFIC AVE. 11806 PACIFIC AVENUE FONTANA CA 92337	ENVIROSTOR

Estor/EPA ID: 71003587
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6071002204
Site Type: TIERED PERMIT
Address Description: 11806 PACIFIC AVENUE
Office: CLEANUP CYPRESS
Special Program:
Funding:
Cleanup Status: NO ACTION REQUIRED AS OF 1/19/2001
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: MANUFACTURING - METAL
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

Assembly District: 47
Senate District: 20
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN BERNARDINO
Latitude: 34.038884
Longitude: -117.519145
Acres: NONE SPECIFIED
Supervisor:

NONE SPECIFIED

Site History:

Status: NO ACTION REQUIRED
A2 Program Type: TIERED PERMIT
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003587

Completed Activities

Title: Phase I Inspection Completed
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 1/16/2007
Comments:

Title: Phase I Non-Submittal
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1 Non-Submittal
Date Completed: 1/19/2001
Comments:

Title: Inspection - Phase I Verification
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase I Verification
Date Completed: 1/16/2007
Comments:

54	*1 of 1*	*ESE*	*0.89 / 4,704.54*	*780.75 / -37*	***LORCIN ENGRG. CO., INC.*** ***3830 WACKER DRIVE*** ***MIRA LOMA CA 91752***	***ENVIROSTOR***

Estor/EPA ID: 71003324
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6065040503
Site Type: TIERED PERMIT
Address Description: 3830 WACKER DRIVE
Office: CLEANUP CYPRESS
Special Program:
Funding:
Assembly District: 60
Senate District: 31
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: RIVERSIDE
Latitude: 34.016959
Longitude: -117.514454
Acres: NONE SPECIFIED
Supervisor:
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
A2 Program Type: TIERED PERMIT
CalEnviroScreen Score: 86-90%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003324

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
55	1 of 1	NE	0.90 / 4,748.85	874.83 / 57	SIERRA ALUMINUM CO. 11711 PACIFIC AVENUE FONTANA CA 92335	ENVIROSTOR

Estor/EPA ID: 71002974
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6071002204
Site Type: TIERED PERMIT
Address Description: 11711 PACIFIC AVENUE
Office: CLEANUP CYPRESS
Special Program:
Funding:
Cleanup Status: NO ACTION REQUIRED AS OF
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: MANUFACTURING - METAL
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Assembly District: 47
Senate District: 20
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SAN BERNARDINO
Latitude: 34.038882
Longitude: -117.517501
Acres: NONE SPECIFIED
Supervisor:

Status: NO ACTION REQUIRED
A2 Program Type: TIERED PERMIT
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71002974

Completed Activities

Title: Phase I Inspection Completed
Title Link: http://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=71002974&doc_id=60253777
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 1/16/2007
Comments:

Unplottable Summary

Total: 18 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
CDL		ON ON WINEVILLE ROAD, CROSS BOCA	MIRA LOMA CA	92509	820121613
CDL		WINEVILLE, SW CORNER OF GAGELENA	CA		820111211
CHMIRS	UPRR	Mira Loma Auto Facility, Etiwanda Ave ***Control No* | *Notified Date:*** 12-5839 |	Riverside CA	91752	821765031
CHMIRS	UPRR	Mira Loma Yard - Mission Blvd. x Etiwanda ***Control No* | *Notified Date:*** 12-4454 |	Mira Loma CA	91752	821825520
CHMIRS	UPRR	Mira Loma Auto Facility, Etiwanda Ave ***Control No* | *Notified Date:*** 12-5838 |	Riverside CA	91752	821844678
EMISSIONS	TWIRL JET SPA	BLDG 633, SPACE CENTER	MIRA LOMA CA	92502	861204166
EMISSIONS	PREDELIVERY SERVICE CORP	N/E CORNER ETIWANDA BLVD	MIRA LOMA CA	91752	861196379
ERNS		ETIWANDA AVE HWY 60	JURUPA VALLEY CA	91752	885694475
HAZNET	ONTARIO MONTCLAIR SCHOOL DISTRICT	EAST 6TH STREET	ONTARIO CA	91764	826873375
HAZNET	1X THE HAYES-ODLE CO	WINEVILLE RD	ONTARIO CA	917640000	826152361
HHSS	FACILITY 1305	MARCH AFB 8TH STREET	RIVERSIDE CA	92518	822940389

HIST TANK	STOP-N-GO MARKETS	(NOT LEGIBLE) ETIWANDA AVE.	MIRA LOMA CA		865060892
HMIRS		MISSION BLVD	MIRA LOMA CA		818234885
HMIRS		MISSION BLVD	MIRA LOMA CA		818204568
HMIRS		MISSION BLVD	MIRA LOMA CA		818377552
HMIRS		MISSION BLVD	MIRA LOMA CA		818447143
HMIRS		CF YARD MISSION BLVD	MIRA LOMA CA		818557395
SWF/LF	East County Line	Philadelphia Ave & Flood Control Basin	Mira Loma CA	92509	820222465

Act Opl Status* | *Activity: Closed | Solid Waste Disposal Site

Unplottable Report

Site:
ON ON WINEVILLE ROAD, CROSS BOCA MIRA LOMA CA 92509 CDL

Clue: 2002-06-087
Date: 6/19/2002
County: RIVERSIDE
Lab Type: A
Lab Type Description: Abandoned Drug Lab Waste - location away from an actual illegal drug lab where drug lab waste and/or equipment were abandoned.

Site:
WINEVILLE, SW CORNER OF GAGELENA CA CDL

Clue: 1999-11-145
Date: 11/24/1999
County: RIVERSIDE
Lab Type: A
Lab Type Description: Abandoned Drug Lab Waste - location away from an actual illegal drug lab where drug lab waste and/or equipment were abandoned.

Site: ***UPRR***
Mira Loma Auto Facility, Etiwanda Ave Riverside CA 91752 CHMIRS

Control No: 12-5839
Notified Date:
Notified Date Time:
Year: 2012
County: Riverside County
URL: https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/56941862270c020488257a870057b368?OpenDocument

Spill Report View

Amount 1:
Amount 2:
Amount 3:
Type: UNSPECIFIED
Water:
On Scene:
Other on Scene:
Other Notified:
Document Title: SPILL Report
Spill Site: Rail Road
Cause Desc for Other:
Person Notifying Cal OES:
Creation Date: 09/28/2012 08:57 AM
Received By:
Admin Agency:
Admin Agency 2:
Additional County:
Phone No:
Ext:
Pag Cell:

Hazardous Materials Spill Report

Control Cal OES: 12-5839
Control NRC:
Date : 09/28/2012
Incident Date: 09/28/2012
Time: 0857
Incident Time: 0847
Water Involved: No
Drink Wtr Impact:
Qty 1: =
Measure 1: Gal(s)
Type 3:
Other 3:
Pipeline 3: No
Ves >= 300 Tons 3: No
Name:
Phone:
Ext:
Pag Cell:
PRS Name:
PRS Phone:

Type 1:	UNSPECIFIED	***PRS Ext:***	
Pipeline 1:	No	***PRS Pag Cell:***	
Ves >= 300 Tons 1:	No	***Received By:***	
Qty 2:	=	***Header Unknown:***	SOUTH COAST AQMD
Amount 2:		***Incident Desc:***	
Measure 2:		***R R Crssing < 50 Ft:***	
Type 2:		***Uprr Rim :***	
Other 2:		***Notification Info:***	
Pipeline 2:	No	***Notification List:***	
Vessel >= 300 Tns 2:	No	***DOG Unit:***	
Qty 3:	=	***RWQCB Unit:***	8
Amount 3:		***Injuries:***	No
Measure 3:		***Fatality:***	No

Incident Location:	Mira Loma Auto Facility, Etiwanda Ave
Reported Cause:	Unknown
Amount 1:	2-3
Substance 1:	Unknown Liquid
Substance 2:	
Substance 3:	
Waterway:	
Contained:	Yes
Known Impact:	
Other 1:	
Detail for Other:	
Site:	Rail Road
On Scene:	
Other on Scene:	
Other Notified:	
Evacuation:	No
Cleanup By:	Reporting Party
Agency:	UPRR
PRS Agency:	
Admin Agency:	Riverside City Fire Department
Sec Agency:	Riverside County Environmental Health
Additional County:	
Admin Agency 2:	
Description:	Caller is reporting the release of an unknown liquid to the asphalt at the Mira Loma Auto Facility. Absorbents have been applied. This release occurred at a different location at the auto facility from spill # 12-5838.

Site: ***UPRR***
Mira Loma Yard - Mission Blvd. x Etiwanda Mira Loma CA 91752 CHMIRS

Control No:	12-4454	***Notified Date:***	
Notified Date Time:		***Year:***	2012
County:	Riverside County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/d83e6a384fe802c788257a4c005d6a77?OpenDocument		

Spill Report View

Amount 1:		***Creation Date:***	07/31/2012 10:00 AM
Amount 2:		***Received By:***	
Amount 3:		***Admin Agency:***	
Type:	PETROLEUM	***Admin Agency 2:***	
Water:		***Additional County:***	
On Scene:		***Phone No:***	
Other on Scene:		***Ext:***	
Other Notified:		***Pag Cell:***	
Document Title:	SPILL Report		
Spill Site:	Rail Road		
Cause Desc for Other:			
Person Notifying Cal OES:			

Hazardous Materials Spill Report

Control Cal OES:	12-4454	***Type 3:***	
Control NRC:		***Other 3:***	
Date :	07/31/2012	***Pipeline 3:***	No

Incident Date:	07/31/2012	***Ves >= 300 Tons 3:***	No
Time:	1000	***Name:***	
Incident Time:	0940	***Phone:***	
Water Involved:	No	***Ext:***	
Drink Wtr Impact:	No	***Pag Cell:***	
Qty 1:	=	***PRS Name:***	
Measure 1:	Gal(s)	***PRS Phone:***	
Type 1:	PETROLEUM	***PRS Ext:***	
Pipeline 1:	No	***PRS Pag Cell:***	
Ves >= 300 Tons 1:	No	***Received By:***	
Qty 2:	=	***Header Unknown:***	SOUTH COAST AQMD
Amount 2:		***Incident Desc:***	
Measure 2:		***R R Crssing < 50 Ft:***	
Type 2:		***Uprr Rim :***	
Other 2:		***Notification Info:***	
Pipeline 2:	No	***Notification List:***	
Vessel >= 300 Tns 2:	No	***DOG Unit:***	
Qty 3:	=	***RWQCB Unit:***	8
Amount 3:		***Injuries:***	No
Measure 3:		***Fatality:***	No

Incident Location:	Mira Loma Yard - Mission Blvd. x Etiwanda
Reported Cause:	Unknown
Amount 1:	.5 - 1
Substance 1:	Gasoline
Substance 2:	
Substance 3:	
Waterway:	
Contained:	Yes
Known Impact:	None
Other 1:	
Detail for Other:	
Site:	Rail Road
On Scene:	
Other on Scene:	
Other Notified:	Riverside County 911
Evacuation:	No
Cleanup By:	Reporting Party
Agency:	UPRR
PRS Agency:	
Admin Agency:	Riverside County Environmental Health
Sec Agency:	
Additional County:	
Admin Agency 2:	
Description:	Caller states: A contractor in the Mira Loma Yard drove a vehicle in the yard and the fuel pump failed on the vehicle causing the release to the ground.

Site: ***UPRR***
Mira Loma Auto Facility, Etiwanda Ave Riverside CA 91752

CHMIRS

Control No:	12-5838	***Notified Date:***	
Notified Date Time:		***Year:***	2012
County:	Riverside County		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/526a6a6e0245e82488257a8700574604?OpenDocument		

Spill Report View

Amount 1:		***Creation Date:***	09/28/2012 08:53 AM
Amount 2:		***Received By:***	
Amount 3:		***Admin Agency:***	
Type:	UNSPECIFIED	***Admin Agency 2:***	
Water:		***Additional County:***	
On Scene:		***Phone No:***	
Other on Scene:		***Ext:***	
Other Notified:		***Pag Cell:***	
Document Title:	SPILL Report		
Spill Site:	Rail Road		
Cause Desc for Other:			
Person Notifying Cal OES:			

Hazardous Materials Spill Report

Control Cal OES:	12-5838	***Type 3:***	
Control NRC:		***Other 3:***	
Date :	09/28/2012	***Pipeline 3:***	No
Incident Date:	09/28/2012	***Ves >= 300 Tons 3:***	No
Time:	0853	***Name:***	
Incident Time:	0847	***Phone:***	
Water Involved:	No	***Ext:***	
Drink Wtr Impact:		***Pag Cell:***	
Qty 1:	=	***PRS Name:***	
Measure 1:	Gal(s)	***PRS Phone:***	
Type 1:	UNSPECIFIED	***PRS Ext:***	
Pipeline 1:	No	***PRS Pag Cell:***	
Ves >= 300 Tons 1:	No	***Received By:***	
Qty 2:	=	***Header Unknown:***	SOUTH COAST AQMD
Amount 2:		***Incident Desc:***	
Measure 2:		***R R Crssing < 50 Ft:***	
Type 2:		***Uprr Rim :***	
Other 2:		***Notification Info:***	
Pipeline 2:	No	***Notification List:***	
Vessel >= 300 Tns 2:	No	***DOG Unit:***	
Qty 3:	=	***RWQCB Unit:***	8
Amount 3:		***Injuries:***	No
Measure 3:		***Fatality:***	No

Incident Location:	Mira Loma Auto Facility, Etiwanda Ave
Reported Cause:	Unknown
Amount 1:	7
Substance 1:	Unknown Liquid
Substance 2:	
Substance 3:	
Waterway:	
Contained:	Yes
Known Impact:	
Other 1:	Probably Oil based per caller
Detail for Other:	
Site:	Rail Road
On Scene:	
Other on Scene:	
Other Notified:	
Evacuation:	No
Cleanup By:	Responsible Party
Agency:	UPRR
PRS Agency:	
Admin Agency:	Riverside City Fire Department
Sec Agency:	Riverside County Environmental Health
Additional County:	
Admin Agency 2:	
Description:	Released from a Toyota Transport truck. Absorbents have been applied.

Site: ***TWIRL JET SPA***
BLDG 633, SPACE CENTER MIRA LOMA CA 92502

EMISSIONS

1987 Criteria Data

Facility ID:	21440	***CERR Code:***	
Facility SIC Code:	2821	***TOGT:***	.4
CO:	33	***ROGT:***	.4
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

1987 Toxic Data

Facility ID:	21440	***COID:***	RIV
Facility SIC Code:	2821	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Site: ***PREDELIVERY SERVICE CORP***
N/E CORNER ETIWANDA BLVD MIRA LOMA CA 91752

EMISSIONS

1990 Criteria Data

Facility ID:	63263	***CERR Code:***	
Facility SIC Code:	7542	***TOGT:***	9
CO:	33	***ROGT:***	8.14596
Air Basin:	SC	***COT:***	
District:	SC	***NOXT:***	
COID:	RIV	***SOXT:***	
DISN:	SOUTH COAST AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

1990 Toxic Data

Facility ID:	63263	***COID:***	RIV
Facility SIC Code:	7542	***DISN:***	SOUTH COAST AQMD
CO:	33	***CHAPIS:***	
Air Basin:	SC	***CERR Code:***	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Site:
ETIWANDA AVE HWY 60 JURUPA VALLEY CA 91752

ERNS

NRC Report No:	1275171	***Latitude Degrees:***	
Type of Incident:	MOBILE	***Latitude Minutes:***	
Incident Cause:	OPERATOR ERROR	***Latitude Seconds:***	
Incident Date:	4/10/2020 7:30	***Longitude Degrees:***	
Incident Location:	HWY 60	***Longitude Minutes:***	
Incident Dtg:	OCCURRED	***Longitude Seconds:***	
Distance from City:		***Lat Quad:***	
Distance Units:		***Long Quad:***	
Direction from City:		***Location Section:***	
Location County:	RIVERSIDE	***Location Township:***	
Potential Flag:	No	***Location Range:***	
Year:	Year 2020 Reports		

Description of Incident: CALLER IS REPORTING A RELEASE OF 80 GALLONS OF DIESEL FUEL ONTO THE GROUND AND INTO 2 STORM DRAINS FROM THE SADDLE TANK OF A TRACTOR TRAILER THAT RAN OFF THE ROAD ON HWY 60 AND FELL ONTO ETIWANDA AVE DUE TO OPERATOR ERROR.

Material Spill Information

Chris Code:	ODS	***Unit of Measure:***	GALLON(S)
CAS No:	000000-00-0	***If Reached Water:***	YES
UN No:		***Amount in Water:***	80
Name of Material:	OIL: DIESEL	***Unit Reach Water:***	UNKNOWN AMOUNT
Amount of Material:	80		

Calls Information

Date Time Received:	4/10/2020 1:55:00 PM	***Responsible City:***	ONTARIO
Date Time Complete:	4/10/2020 2:30:00 PM	***Responsible State:***	CA
Call Type:	INC	***Responsible Zip:***	91761
Resp Company:	CRST GARNDNER TRUCKING	***Source:***	TELEPHONE
Resp Org Type:	PRIVATE ENTERPRISE		

Incident Information

Tank ID:		***Building ID:***	
Tank Regulated:	U	***Location Area ID:***	
Tank Regulated By:		***Location Block ID:***	
Capacity of Tank:		***OCSG No:***	
Capacity Tank Units:		***OCSP No:***	
Description of Tank:		***State Lease No:***	
Actual Amount:		***Pier Dock No:***	
Actual Amount Units:		***Berth Slip No:***	
Tank Above Ground:	ABOVE	***Brake Failure:***	U
NPDES:		***Airbag Deployed:***	U
NPDES Compliance:	U	***Transport Contain:***	U
Init Contin Rel No:		***Location Subdiv:***	
Contin Rel Permit:		***Platform Rig Name:***	
Contin Release Type:		***Platform Letter:***	
Aircraft ID:		***Allision:***	U
Aircraft Runway No:		***Type of Structure:***	
Aircraft Spot No:		***Structure Name:***	
Aircraft Type:		***Structure Oper:***	U
Aircraft Model:		***Transit Bus Flag:***	
Aircraft Fuel Cap:		***Date Time Norm Serv:***	
Aircraft Fuel Cap U:		***Serv Disrupt Time:***	
Aircraft Fuel on Brd:		***Serv Disrupt Units:***	
Aircraft Fuel OB U:		***CR Begin Date:***	
Aircraft Hanger:		***CR End Date:***	
Road Mile Marker:		***CR Change Date:***	
Power Gen Facility:	U	***FBI Contact:***	
Generating Capacity:		***FBI Contact Dt Tm:***	
Type of Fixed Obj:		***Passenger Handling:***	
Type of Fuel:		***Passenger Route:***	XXX
DOT Crossing No:		***Passenger Delay:***	XXX
DOT Regulated:	U	***Sub Part C Test Req:***	XXX
Pipeline Type:		***Conductor Test:***	
Pipeline Abv Ground:	ABOVE	***Engineer Test:***	
Pipeline Covered:	U	***Trainman Test:***	
Exposed Underwater:	N	***Yard Foreman Test:***	
Railroad Hotline:		***RCL Operator Test:***	
Railroad Milepost:		***Brakeman Test:***	
Grade Crossing:	U	***Train Dispat Test:***	
Crossing Device Ty:		***Signalman Test:***	
Ty Vehicle Involved:		***Oth Employee Test:***	
Device Operational:	U	***Unknown Test:***	

Incident Details Information

Release Secured:	Y	***State Agen Report No:***	COEM 20-1965
Release Rate:		***State Agen on Scene:***	CSPD
Release Rate Unit:		***State Agen Notified:***	
Release Rate Rate:		***Fed Agency Notified:***	COEM,
Est Duration of Rel:		***Oth Agency Notified:***	
Desc Remedial Act:	BOOMS APPLIED, ABSORBENTS APPLIED, MATERIAL CONTAINED, CLEAN UP CREW ON-SITE	***Body of Water:***	STORM DRAINS
Fire Involved:	N	***Tributary of:***	
Fire Extinguished:	U	***Near River Mile Make:***	
Any Evacuations:	N	***Near River Mile Mark:***	
No Evacuated:		***Offshore:***	N
Who Evacuated:		***Weather Conditions:***	RAINY
Radius of Evacu:		***Air Temperature:***	
Any Injuries:	N	***Wind Direction:***	
No. Injured:		***Wind Speed:***	
No. Hospitalized:		***Wind Speed Unit:***	

No. Fatalities:		***Water Supp Contam:***	U
Any Fatalities:	N	***Water Temperature:***	
Any Damages:	N	***Wave Condition:***	
Damage Amount:		***Current Speed:***	
Air Corridor Closed:	N	***Current Direction:***	
Air Corridor Desc:		***Current Speed Unit:***	
Air Closure Time:		***EMPL Fatality:***	
Waterway Closed:	N	***Pass Fatality:***	
Waterway Desc:		***Community Impact:***	
Waterway Close Time:		***Passengers Transfer:***	NO
Road Closed:	Y	***Passenger Injuries:***	
Road Desc:	HWY 60 & ETIWANDA AVE	***Employee Injuries:***	
Road Closure Time:	5.5	***Occupant Fatality:***	
Road Closure Units:		***Sheen Size:***	
Closure Direction:	ALL	***Sheen Size Units:***	
Major Artery:	Yes	***Sheen Size Length:***	
Track Closed:	N	***Sheen Size Length U:***	
Track Desc:		***Sheen Size Width:***	
Track Closure Time:		***Sheen Size Width U:***	
Track Closure Units:		***Sheen Color:***	
Track Close Dir:		***Dir of Sheen Travel:***	
Media Interest:	UNKNOWN	***Sheen Odor Desc:***	
Medium Desc:	WATER	***Duration Unit:***	
Addl Medium Info:	2 STORM DRAINS	***Additional Info:***	

Site: ***ONTARIO MONTCLAIR SCHOOL DISTRICT***
EAST 6TH STREET ONTARIO CA 91764

HAZNET

SIC Code:	8211	***Mailing City:***	ONTARIO
NAICS Code:	61111	***Mailing State:***	CA
EPA ID:	CAC002775617	***Mailing Zip:***	917623026
Create Date:	6/20/2014	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	ONTARIO MONTCLAIR SCHOOL DISTRICT
Inact Date:	9/19/2014	***Owner Addr 1:***	950 W D ST
County Code:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	ONTARIO
Mail Name:		***Owner State:***	CA
Mailing Addr 1:	950 W D ST	***Owner Zip:***	917623026
Mailing Addr 2:		***Owner Phone:***	9094186366
Owner Fax:	9094592550		

Contact Information

--	--
Contact Name:	RUDOLPH PEREZ
Street Address 1:	950 W D ST
Street Address 2:	
City:	ONTARIO
State:	CA
Zip:	91762
Phone:	9094186366
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAC002775617
Generator County Code:	36
Generator County:	San Bernardino
TSD EPA ID:	CAD009007626
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	151
State Waste Code Desc.:	Asbestos containing waste
Method Code:	H132
Method Description:	LANDFILL OR SURFACE IMPOUNDMENT THAT WILL BE CLOSED AS LANDFILL(TO INCLUDE ON-SITE TREATMENT AND/OR STABILIZATION)
Tons:	0.4
Year:	2014
--	--

Site: ***1X THE HAYES-ODLE CO***
WINEVILLE RD ONTARIO CA 917640000

HAZNET

SIC Code:		***Mailing City:***	COSTA MESA
NAICS Code:		***Mailing State:***	CA
EPA ID:	CAC000678112	***Mailing Zip:***	926260000
Create Date:	3/18/1992	***Region Code:***	4
Fac Act Ind:	No	***Owner Name:***	THE HAYES-ODLE CO
Inact Date:	10/25/2000	***Owner Addr 1:***	--
County Code:	36	***Owner Addr 2:***	
County Name:	San Bernardino	***Owner City:***	--
Mail Name:		***Owner State:***	99
Mailing Addr 1:	--	***Owner Zip:***	--
Mailing Addr 2:		***Owner Phone:***	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	ROBERT ODLE/GENERAL PARTNER
Street Address 1:	--
Street Address 2:	
City:	--
State:	99
Zip:	--
Phone:	7145456566
--	--

Site: ***FACILITY 1305***
MARCH AFB 8TH STREET RIVERSIDE CA 92518

HHSS

County:	Riverside
Pdf File Url:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0001fac6.pdf

---

Site: ***STOP-N-GO MARKETS***
(NOT LEGIBLE) ETIWANDA AVE. MIRA LOMA CA

HIST TANK

Owner Name:	NATIONAL CONVENIENCE STORES	***No of Containers:***	3
Owner Street:	100 WAUGH DR.	***County:***	SAN BERNARDINO
Owner City:	HOUSTAN	***Facility State:***	CA
Owner State:	TX	***Facility Zip:***	91752
Owner Zip:	77007		

Site:
MISSION BLVD MIRA LOMA CA

HMIRS

Incident County: RIVERSIDE

HMIR Incident Reports

Report No:	I-1990110403	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-10-21	***Report Submit Src:***	Paper
Time of Incident:	1500	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	AMINOTRI METHYLENE	***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	5	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	MIRA LOMA

What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	91752
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	0
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	ALBRIGHT & WILSON INC
Cont1 Pkging Type:		***Shipper Street Name:***	6666 MYKAWA
Cont1 Const Mat:		***Shipper City:***	HOUSTON
Cont1 Head Type:		***Shipper State:***	TX
Cont1 Pkg Capacity:	55	***Shipper Postal:***	77033
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	358-047690
Cont1 Pkg No:	15	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	BRIQUEST	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	CITY OF INDUSTRY
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	91744
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	LAWRENCE E BAKER JR
Damage > 500:	No	***Contact Title:***	CLAIMS MANAGER
Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	500	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	500	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No

Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: AT APPROXIMATELY 1500 HOURS ON OCTOBER 21, 1990, MR . CROOM WAS TRIPING TRAILER SOWN-3225 IN THE 63 BAY AND PUNCTURED ONE DRUM OF CORROSIVE LIQUID WITH HIS TOWMOTOR. HE NOTIFIED HIS SUPERVISOR AND THE SPILL WAS CONTAINED WITH THE LOSS OF APPROXIMATELY 5 GALLONS. CONTAINERIZED CHEMICAL CO WAS CALLED IN FOR THE CLEANUP AND PROPER RECOVERY OF THE CORROSIVE MATERIAL.

Recommend Actions Taken:

Site:

MISSION BLVD MIRA LOMA CA HMIRS

Incident County: RIVERSIDE

HMIR Incident Reports

Report No:	I-1990110462	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-11-10	***Report Submit Src:***	Paper
Time of Incident:	1800	***Inc Multiple Rows:***	Yes
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CAUSTIC ALKALI LIQUIDS,	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	CAUSTIC ALKALI LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1719	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	0.046875	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	97152
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	0
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	AKEMI PLASTICS INC
Cont1 Pkging Type:		***Shipper Street Name:***	5265 S CLINTON TRAIL
Cont1 Const Mat:		***Shipper City:***	EATON RAPIDS
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	0.023438	***Shipper Postal:***	48827
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	391-743461
Cont1 Pkg No:	5	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	AKEMI PLASTICS INC	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	HUNTINGTON BEACH
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	92647
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0

C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	ANTHONY J ALLMOND
Damage > 500:	Yes	***Contact Title:***	YARD COORDINATOR
Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	1600	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1600	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	INSIDE CONTAIN
Haz Hosp Old Form:	0	***HMIS Container Code:***	CONT PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic container, no capacity or description given
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: TRAILER 43-937 WAS DISCOVERED LEAKING BY A YARD HOSTLER WHO REPORTED THE INCIDENT TO HIS SUPERVISOR. A CONTAINERIZED CHEMICAL TEAM WAS IMMEDIATELY CALLED. SOON AFTER ARRIVAL, THEY BEGAN CLEANING UP THE SPILL AND DETERMINED IT TO BE A COMBINATION OF CORROSIVE LIQUID AND FLAMMABLE LIQUID. IT WAS DETERMINED THAT THE SPILL OCCURRED IN TRANSIT. THE CONTAINERS WERE DAMAGED DUE TO COLLISION OF FREIGHT IN THE TRAILER. WASTE DISPOSAL PERFORMED BY CONTAINERIZED CHEMICAL.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	I-1990110462	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-11-10	***Report Submit Src:***	Paper
Time of Incident:	1800	***Inc Multiple Rows:***	Yes
Haz Class Code:		***Inc Non US State:***	

Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	RESIN SOLUTION, FLAMMABLE	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	RESIN SOLUTION, FLAMMABLE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1866	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	2	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	97152
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	0
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	AKEMI PLASTICS INC
Cont1 Pkging Type:		***Shipper Street Name:***	5265 S CLINTON TRAIL
Cont1 Const Mat:		***Shipper City:***	EATON RAPIDS
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:	1	***Shipper Postal:***	48827
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	391-743461
Cont1 Pkg No:	4	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	2	***Origin City:***	
Cont1 Pkg Mnfctr:	AKEMI PLASTICS INC	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	HUNTINGTON BEACH
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	92647
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	ANTHONY J ALLMOND
Damage > 500:	Yes	***Contact Title:***	YARD COORDINATOR

Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	1600	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1600	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM NON-METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM PLS
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Plastic drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: TRAILER 43-937 WAS DISCOVERED LEAKING BY A YARD HOSTLER WHO REPORTED THE INCIDENT TO HIS SUPERVISOR. A CONTAINERIZED CHEMICAL TEAM WAS IMMEDIATELY CALLED. SOON AFTER ARRIVAL, THEY BEGAN CLEANING UP THE SPILL AND DETERMINED IT TO BE A COMBINATION OF CORROSIVE LIQUID AND FLAMMABLE LIQUID. IT WAS DETERMINED THAT THE SPILL OCCURRED IN TRANSIT. THE CONTAINERS WERE DAMAGED DUE TO COLLISION OF FREIGHT IN THE TRAILER. WASTE DISPOSAL PERFORMED BY CONTAINERIZED CHEMICAL.

Recommend Actions Taken:

Site:

MISSION BLVD MIRA LOMA CA HMIRS

Incident County: RIVERSIDE

HMIR Incident Reports

Report No:	I-1990100432	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-09-14	***Report Submit Src:***	Paper
Time of Incident:	0530	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	2.3	***Mode Transport:***	Highway
Commodity Short Nm:	COMPRESSED OR LIQUEFIED	***Transport Phase:***	Unloading
Commodity Long Nm:	COMPRESSED OR LIQUEFIED GASES, TOXIC, N.O.S.	***Incident Occrrnce:***	
Trade Name:	POISON GAS	***Mat Ship Approval?:***	No
ID No:	UN1955	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	0	***CR Street Name:***	11888 MISSION BOULEVARD
Unit of Measure:		***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	0
Failure Cause Code:	526	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Loose Closure, Component, or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	ALPHAGZ
Cont1 Pkging Type:		***Shipper Street Name:***	2445 SOUTH STREET
Cont1 Const Mat:		***Shipper City:***	LONG BEACH
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	5	***Shipper Postal:***	90805
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	354076800
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	

C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	BILLINGS
C1 Pkg Dsign Pres.:	0	***Destination State:***	MONTANA
C1 Dsign Press UOM:		***Destination Postal:***	59101
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	Yes
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	95
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	Yes	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	MARK EPSTEIN
Damage > 500:	No	***Contact Title:***	FREIGHT OPERATIONS MNGR
Material Loss:	50	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	0	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	50	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	Yes
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	Yes
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: CYLINDER WAS FOUND AT THE 147 BAY, LEAKING COLORED GAS. VALVE RE-TIGHTENED-EMERGENCY TEAMS CALLED-NO CLEAN UP NECESSARY.

Recommend Actions Taken:

Site:

MISSION BLVD MIRA LOMA CA

HMIRS

Incident County: RIVERSIDE

HMIR Incident Reports

Report No:	I-1990110404	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-10-12	***Report Submit Src:***	Paper
Time of Incident:	1400	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	In Transit Storage
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	CYANIMID CYANACHEM	***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	10	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:	Liquid - Gallon	***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	91752
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	0
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	WEYERHAUSER CO
Cont1 Pkging Type:		***Shipper Street Name:***	101 E MARINE VIEW DR
Cont1 Const Mat:		***Shipper City:***	EVERETT
Cont1 Head Type:		***Shipper State:***	WA
Cont1 Pkg Capacity:	55	***Shipper Postal:***	98201
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	347262753
Cont1 Pkg No:	9	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA PAULA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	93060
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0

Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	PABLO DIAZ
Damage > 500:	Yes	***Contact Title:***	OFFICE MANAGER
Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	1000	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	1000	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	DRUM METAL
Haz Hosp Old Form:	0	***HMIS Container Code:***	DRUM MTL
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Metal drum
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: INBOUND UNIT DISPATCHED TO MLC, DISCOVERED LEAKING AT 1406/12 FROM THE NOSE OF TRAILER. CONTAINERIZED CHEMICAL DISPOSAL WAS CALLED TO HANDLE INCIDENT AND UNLOADED COMPLETE TRAILER AND FOUND 1 DRUM PUNTURED BY FORLIFT IN NOSE OF TRAILER. RECOUPED IN AN 85 GALLON CONTAINER AND SHIPPED ON. NO OTHER FREIGHT WAS DAMAGED.

Recommend Actions Taken:

Site:

CF YARD MISSION BLVD MIRA LOMA CA HMIRS

Incident County: RIVERSIDE

HMIR Incident Reports

Report No:	I-1990110196	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-10-30	***Report Submit Src:***	Paper
Time of Incident:	0800	***Inc Multiple Rows:***	Yes
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	BUTYRIC ACID	***Transport Phase:***	Unloading
Commodity Long Nm:	BUTYRIC ACID	***Incident Occrrnce:***	
Trade Name:	BUTYRIC ACID	***Mat Ship Approval?:***	No
ID No:	UN2820	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	0	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:		***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	91752
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	0

Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MAY'S CHEM CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	7760 E 89TH ST
Cont1 Const Mat:		***Shipper City:***	INDIANAPOLIS
Cont1 Head Type:		***Shipper State:***	IN
Cont1 Pkg Capacity:	5	***Shipper Postal:***	46256
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	351696273
Cont1 Pkg No:	7	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	7	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	BUENA PARK
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	LAWRENCE E BAKER JR
Damage > 500:	No	***Contact Title:***	FREIGHT OPERATIONS MNGR
Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	500	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	500	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No

Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	INSIDE CONTAIN
Haz Hosp Old Form:	0	***HMIS Container Code:***	2U
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Polyethylene containers over one gallon capacity RHNA*
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: RECEIVED METAL RECOUP DRUM FROM LOS ALAMITOS WITH CORROSIVE ACID INSIDE. SHIPMENT WAS REFUSED BY KRAFT IN MAY 1990. LOS ALAMITOS FORWARDED DRUM TO MIRA LOMA FOR DISPOSAL PER AUTHORIZATION FROM JIM VANCURA - GENERAL CLAIMS. CONTAINERIZED CHEMICAL DISP. WAS CALLED TO PROPERLY PACKAGE AND DISPOSE OF MATERIAL.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	I-1990110196	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1990-10-30	***Report Submit Src:***	Paper
Time of Incident:	0800	***Inc Multiple Rows:***	Yes
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	PROPIONIC ACID WITH NOT	***Transport Phase:***	Unloading
Commodity Long Nm:	PROPIONIC ACID WITH NOT LESS THAN 10% AND LESS THAN 90% ACID BY MASS	***Incident Occrrnce:***	
Trade Name:	PROPIONIC ACID	***Mat Ship Approval?:***	No
ID No:	UN1848	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	CONSOLIDATED FREIGHTWAYS
Qty Released:	0	***CR Street Name:***	11888 MISSION BLVD
Unit of Measure:		***CR City:***	MIRA LOMA
What Failed:		***CR State:***	CA
What Failed Desc:		***CR Postal Code:***	91752
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	0
Failure Cause Code:		***CR Hazmat Reg ID:***	
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MAY'S CHEM CO INC
Cont1 Pkging Type:		***Shipper Street Name:***	7760 E 89TH ST
Cont1 Const Mat:		***Shipper City:***	INDIANAPOLIS
Cont1 Head Type:		***Shipper State:***	IN
Cont1 Pkg Capacity:	5	***Shipper Postal:***	46256
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	351696273
Cont1 Pkg No:	7	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	7	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	BUENA PARK
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	

RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	No	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	LAWRENCE E BAKER JR
Damage > 500:	No	***Contact Title:***	FREIGHT OPERATIONS MNGR
Material Loss:	0	***Contact Business:***	
Carrier Damage:	0	***Contact Street:***	
Property Damage:	0	***Contact City:***	
Response Cost:	0	***Contact State:***	
Remediation Cost:	500	***Contact Postal:***	
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	500	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	INSIDE CONTAIN
Haz Hosp Old Form:	0	***HMIS Container Code:***	2U
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Polyethylene containers over one gallon capacity RHNA*
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: RECEIVED METAL RECOUP DRUM FROM LOS ALAMITOS WITH CORROSIVE ACID INSIDE. SHIPMENT WAS REFUSED BY KRAFT IN MAY 1990. LOS ALAMITOS FORWARDED DRUM TO MIRA LOMA FOR DISPOSAL PER AUTHORIZATION FROM JIM VANCURA - GENERAL CLAIMS. CONTAINERIZED CHEMICAL DISP. WAS CALLED TO PROPERLY PACKAGE AND DISPOSE OF MATERIAL.

Recommend Actions Taken:

Site: ***East County Line***
Philadelphia Ave & Flood Control Basin Mira Loma CA 92509

SWF/LF

SWIS No:	33-CR-0033	***Latitude:***	34.14837
EPA Fed Registry ID:		***Longitude:***	-117.30364
Operational Status:	Closed	***County:***	Riverside
Regulatory Status:	Pre-regulation	***Site ZIP:***	92509
Site is Archived:	No	***ARB District:***	South Coast
Absorbed on:		***SWRCB Region:***	Santa Ana
Absorbed by:		***Site Point of Contact:***	Angela Gomez

Site Inert Debris Eng Fill:	No
Closed Illegal Aband:	Yes
Closed Illegal Aband Cat:	C2
Finance Assuran Responsible:	No
Incorporated City:	Riverside County (Unincorporated)
Local Government:	Riverside County (Unincorporated)
Reporting Agency Legal Name:	County of Riverside
Reporting Agency Department:	Department of Environmental Health

Enforcing Agency Legal Name: County of Riverside
Enforcing Agency Department: Department of Environmental Health

Site Owners

Site Type: Disposal Only
Owner Name: SPSSM Investments-IX, LP
Owner Address: 4900 Santa Anita Ave. Suite 2C
Owner City: El Monte
Owner State: CA
Owner ZIP Code: 91713
Owner Phone:
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On: 1/4/2021

Site Activities (Search Result)

Waste Disch Req No:
Site Regulatory Stat: Pre-regulation
Act Opl Status: Closed
Act Regulatory Stat: Pre-regulations
Activity Category: Disposal
Act Classification: Solid Waste Disposal Site
Activity is Archived: No
WDR Landfill Class:
Cease Operation: 5/31/1965
Cease Oper Type: Actual
Inspection Frequency: Annual
Site Name: East County Line
Activity: Solid Waste Disposal Site
Max Permitted Throughput: 0
Inert Debris Engineered Fill: No
Throughput UOM:
Remaining Capacity: 0
Remaining Cap Date:
Max Permit Capacity: 0
Capacity UOM:
Total Acreage: 0
Disposal Acreage: 0
Permitted Elevation: 0
Permitted Elev Type:
Permitted Depth: 0
Permitted Depth Type:

Site Operators

Site Type: Disposal Only
Operator Name: County Of Riverside Waste Mgmt Dept
Operator Address: 14310 Frederick St
Operator City: Moreno Valley
Operator State: CA
Operator ZIP Code: 92553
Operator Phone: (951) 486-3200
Is Archived: No
Contact Name: Joseph R. McCann
Contact First Name: Joseph R.
Contact Last Name: McCann
Contact Title: General Manager - Chief Engineer
Contact Email:
Started on: 8/22/1995

Extra Details

Enforcement Agency (LEA/EA): Riverside County

Site Activities (Export)

WDR No:
WDR Landfill Class:
Act is Archived: No
Act Opl Status: Closed
Act Regulatory Stat: Pre-regulations
Activity Category: Disposal
Act Classification: Solid Waste Disposal Site
Cease Operation: 5/31/1965
Cease Operation Tp: Actual
Insp Frequency: Annual
Site Name: East County Line
Site Point of Contact: Angela Gomez
Activity: Solid Waste Disposal Site
Max Permitted Throughput: 0
Throughput UOM:
Remaining Capacity: 0
Remaining Cap Dt:
Max Permit Cap: 0
Capacity UOM:
Total Acreage: 0.00
Disposal Acreage: 0.00
Permitted Elev : 0
Permitted Elev Tp:
Permitted Depth: 0
Permitted Depth Tp:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Facility Response Plan: FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Mar 26, 2020

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List: NPL

National Priorities List (Superfund)-NPL: EPA's (United States Environmental Protection Agency) list of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action.

Government Publication Date: Feb 23, 2021

National Priority List - Proposed: PROPOSED NPL

Includes sites proposed (by the EPA, the state, or concerned citizens) for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment.

Government Publication Date: Feb 23, 2021

Deleted NPL: DELETED NPL

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Government Publication Date: Feb 23, 2021

SEMS List 8R Active Site Inventory: SEMS

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Jan 28, 2021

SEMS List 8R Archive Sites: SEMS ARCHIVE

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Jan 28, 2021

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Jan 22, 2021

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Jan 22, 2021

RCRA Generator List: RCRA LQG

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Jan 22, 2021

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Jan 22, 2021

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Jan 22, 2021

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Jan 22, 2021

Federal Engineering Controls-ECs: FED ENG

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 26, 2020

Federal Institutional Controls- ICs: FED INST

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: Aug 26, 2020

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Nov 9, 2020

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Jan 6, 2021

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Jul 10, 2020

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Apr 28, 2020

LIEN on Property: SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program.

Government Publication Date: Jan 28, 2021

Superfund Decision Documents: SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: Feb 23, 2021

State

State Response Sites: RESPONSE

A list of identified confirmed release sites where the Department of Toxic Substances Control (DTSC) is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. This database is state equivalent NPL.

Government Publication Date: Jan 13, 2021

EnviroStor Database: ENVIROSTOR

The EnviroStor Data Management System is made available by the Department of Toxic Substances Control (DTSC). Includes Corrective Action sites, Tiered Permit sites, Historical Sites and Evaluation/Investigation sites. This database is state equivalent CERCLIS.

Government Publication Date: Jan 13, 2021

Delisted State Response Sites: DELISTED ENVS

Sites removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC).

Government Publication Date: Jan 13, 2021

Solid Waste Information System (SWIS): SWF/LF

The Solid Waste Information System (SWIS) database made available by the Department of Resources Recycling and Recovery (CalRecycle) contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites.

Government Publication Date: Feb 8, 2021

Solid Waste Disposal Sites with Waste Constituents Above Hazardous Waste Levels: SWRCB SWF

This is a list of solid waste disposal sites identified by California State Water Resources Control Board with waste constituents above hazardous waste levels outside the waste management unit.

Government Publication Date: Sep 20, 2006

EnviroStor Hazardous Waste Facilities: HWP

A list of hazardous waste facilities including permitted, post-closure and historical facilities found in the Department of Toxic Substances Control (DTSC) EnviroStor database.

Government Publication Date: Jan 13, 2021

Sites Listed in the Solid Waste Assessment Test (SWAT) Program Report: SWAT

In a 1993 Memorandum of Understanding, the State Water Resources Control Board (SWRCB) agreed to submit a comprehensive report on the Solid Waste Assessment Test (SWAT) Program to the California Integrated Waste Management Board (CIWMB). This report summarizes the work completed to date on the SWAT Program, and addresses both the impacts that leakage from solid waste disposal sites (SWDS) may have upon waters of the State and the actions taken to address such leakage.

Government Publication Date: Dec 31, 1995

Land Disposal Sites: LDS

Land Disposal Sites in GeoTracker, the State Water Resources Control Board (SWRCB)'s data management system. The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units. Waste management units include waste piles, surface impoundments, and landfills.

Government Publication Date: Nov 16, 2020

Leaking Underground Fuel Tank Reports: LUST

List of Leaking Underground Storage Tanks within the Cleanup Sites data in GeoTracker database. GeoTracker is the State Water Resources Control Board's (SWRCB) data management system for managing sites that impact groundwater, especially those that require groundwater cleanup (Underground Storage Tanks, Department of Defense and Site Cleanup Program) as well as permitted facilities such as operating Underground Storage Tanks. The Leak Prevention Program that overlooks LUST sites is the SWRCB in California's Environmental Protection Agency.

Government Publication Date: Nov 16, 2020

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Underground Storage Tanks (LUST) cleanup sites removed from GeoTracker, the State Water Resources Control Board (SWRCB)'s database system, as well as sites removed from the SWRCB's list of UST Case closures.

Government Publication Date: Feb 2, 2021

Permitted Underground Storage Tank (UST) in GeoTracker: UST

List of Permitted Underground Storage Tank (UST) sites made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA).

Government Publication Date: Mar 23, 2021

Proposed Closure of Underground Storage Tank Cases: UST CLOSURE

List of UST cases that are being considered for closure by either the California Environmental Protection Agency, State Water Resources Control Board or the Executive Director that have been posted for a 60-day public comment period.

Government Publication Date: Feb 2, 2021

Historical Hazardous Substance Storage Information Database: HHSS

The Historical Hazardous Substance Storage database contains information collected in the 1980s from facilities that stored hazardous substances. The information was originally collected on paper forms, was later transferred to microfiche, and recently indexed as a searchable database. When using this database, please be aware that it is based upon self-reported information submitted by facilities which has not been independently verified. It is unlikely that every facility responded to the survey and the database should not be expected to be a complete inventory of all facilities that were operating at that time. This database is maintained by the California State Water Resources Control Board's (SWRCB) Geotracker.

Government Publication Date: Aug 27, 2015

Statewide Environmental Evaluation and Planning System: UST SWEEPS

The Statewide Environmental Evaluation and Planning System (SWEEPS) is a historical listing of active and inactive underground storage tanks made available by the California State Water Resources Control Board (SWRCB).

Government Publication Date: Oct 1, 1994

Aboveground Storage Tanks: AST

A statewide list from 2009 of aboveground storage tanks (ASTs) made available by the Cal FIRE Office of the State Fire Marshal (OSFM). This list is no longer maintained or updated by the Cal FIRE OSFM.

Government Publication Date: Aug 31, 2009

SWRCB Historical Aboveground Storage Tanks: AST SWRCB

A list of aboveground storage tanks made available by the California State Water Resources Control Board (SWRCB). Effective January 1, 2008, the Certified Unified Program Agencies (CUPAs) are vested with the responsibility and authority to implement the Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Dec 1, 2007

Oil and Gas Facility Tanks: TANK OIL GAS

Locations of oil and gas tanks that fall under the jurisdiction of the Geologic Energy Management Division of the California Department of Conservation (CalGEM) (CCR 1760). CalGEM was formerly the Division of Oil, Gas, and Geothermal Resources (DOGGR).

Government Publication Date: Feb 12, 2021

Delisted Storage Tanks: DELISTED TNK

This database contains a list of storage tank sites that were removed by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA) and the Cal FIRE Office of State Fire Marshal (OSFM).

Government Publication Date: Mar 9, 2021

California Environmental Reporting System (CERS) Tanks: CERS TANK

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Feb 9, 2021

Delisted California Environmental Reporting System (CERS) Tanks: DELISTED CTNK

This database contains a list of Aboveground Petroleum Storage and Underground Storage Tank sites that were removed from in the California Environmental Protection Agency (CalEPA) Regulated Site Portal.

Government Publication Date: Feb 9, 2021

Historical Hazardous Substance Storage Container Information - Facility Summary: HIST TANK

The State Water Resources Control Board maintained the Hazardous Substance Storage Containers listing and inventory in th 1980s. This facility summary lists historic tank sites where the following container types were present: farm motor vehicle fuel tanks; waste tanks; sumps; pits, ponds, lagoons, and others; and all other product tanks. This set, published in May 1988, lists facility and owner information, as well as the number of containers. This data is historic and will not be updated.

Government Publication Date: May 27, 1988

Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions: LUR

The Department of Toxic Substances Control (DTSC) Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents land use restrictions that are active. Some sites have multiple land use restrictions.

Government Publication Date: Jan 13, 2021

Hazardous Waste Management Program Facility Sites with Deed / Land Use Restrictions: HLUR

The Department of Toxic Substances Control (DTSC) Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Government Publication Date: Feb 18, 2021

Deed Restrictions and Land Use Restrictions: DEED

List of Deed Restrictions, Land Use Restrictions and Covenants in GeoTracker made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency. A deed restriction (land use covenant) may be required to facilitate the remediation of past environmental contamination and to protect human health and the environment by reducing the risk of exposure to residual hazardous materials.

Government Publication Date: Nov 16, 2020

Voluntary Cleanup Program: VCP

List of sites in the Voluntary Cleanup Program made available by the Department of Toxic Substances and Control (DTSC). The Voluntary Cleanup Program was designed to respond to lower priority sites. Under the Voluntary Cleanup Program, DTSC enters site-specific agreements with project proponents for DTSC oversight of site assessment, investigation, and/or removal or remediation activities, and the project proponents agree to pay DTSC's reasonable costs for those services.

Government Publication Date: Jan 13, 2021

GeoTracker Cleanup Program Sites: CLEANUP SITES

A list of Cleanup Program sites in the state of California made available by The State Water Resources Control Board (SWRCB) of the California Environmental Protection Agency (EPA). SWRCB tracks leaking underground storage tank cleanups as well as other water board cleanups.

Government Publication Date: Nov 16, 2020

Delisted County Records: DELISTED COUNTY

Records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Mar 23, 2021

Tribal

Leaking Underground Storage Tanks (LUSTs) on Indian Lands: INDIAN LUST

LUSTs on Tribal/Indian Lands in Region 9, which includes California.

Government Publication Date: Apr 8, 2020

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST

USTs on Tribal/Indian Lands in Region 9, which includes California.

Government Publication Date: Apr 8, 2020

Delisted Tribal Leaking Storage Tanks: DELISTED ILST

Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA.

Government Publication Date: Apr 14, 2020

Delisted Tribal Underground Storage Tanks: DELISTED IUST

Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.

Government Publication Date: Apr 14, 2020

County

Alameda County - LOP Sites List: ALAMEDA LOP

List of sites in the Alameda County Department of Environmental Health's (ACDEH) Local Oversight Program (LOP). The ACDEH LOP program oversees the investigation and cleanup of hazardous materials releases to the environment under two programs. The Leaking Underground Fuel Tank (LUFT) program is specific to unauthorized releases associated with petroleum underground storage tank systems. The Site Cleanup Program (SCP) oversees the investigation and cleanup of releases from hazardous materials, including but not limited to releases of pesticides, heavy metals, dry cleaner solvents, etc., including redevelopment of sites with residual contamination from historic uses.

Government Publication Date: Jan 16, 2019

Alameda County - UST List: UST ALAMEDA

A list of registered Underground Storage Tanks (USTs) in the County of Alameda. The list is made available by Alameda County Department of Environmental Health.

Government Publication Date: Jul 9, 2019

Alameda County - City of Berkeley CUPA Facilities: BERKELEY CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs at the City of Berkeley in Alameda County. This list is maintained by the Toxics Management Division at the City of Berkeley.

Government Publication Date: Dec 16, 2020

Alameda County - Hayward City CUPA List: HAYWARD CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Hayward City. This list is maintained by the Hayward City Fire Department.

Government Publication Date: Jul 16, 2019

Alameda County - San Leandro City CUPA Facilities List: SANLEANDRO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Leandro City, Alameda County. This list is made available by San Leandro City Environmental Services Section.

Government Publication Date: Apr 11, 2019

Alameda County - Union City USTs: UNION UST

A list of Underground Storage Tanks (USTs) in the city of Union in Alameda County. This data is made available by the Environmental Programs Division of Economic & Community Development, Union City.

Government Publication Date: Dec 31, 2020

Alameda County - Union City CERS CUPA List: UNION CUPA

A list of CERS registered facilities associated with various Certified Unified Program Agency (CUPA) programs in the City of Union. This list is made available by the City of Union Economic and Community Development Department.

Government Publication Date: Dec 31, 2020

Alameda County - Union City CUPA Facilities: UNION CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the City of Union. Includes facilities with active and inactive statuses. This list is made available by the City of Union Economic and Community Development Department.

Government Publication Date: Sep 30, 2020

Alameda County - City of Livermore and Pleasanton UST List: LIVERMORE UST

A list of registered Underground Storage Tank (UST) in City of Livermore and City of Pleasanton, Alameda County. This list is maintained by the Livermore-Pleasanton Fire Department.

Government Publication Date: May 1, 2019

Alameda County - City of Livermore and Pleasanton AST List: LIVERMORE AST

A list of registered Aboveground Storage Tank (AST) in City of Livermore and City of Pleasanton, Alameda County. This list is maintained by the Livermore-Pleasanton Fire Department.

Government Publication Date: May 1, 2019

Alameda County - City of Livermore and Pleasanton CUPA Facilities: LIVERMORE CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in City of Livermore and City of Pleasanton in Alameda County. This list is maintained by the Livermore-Pleasanton Fire Department.

Government Publication Date: May 1, 2019

Alpine County - CUPA List: ALPINE CUPA

The Alpine County Health Department has been certified by Cal / EPA to implement the Unified program and maintains a list of Certified Unified Program Agency (CUPA) facilities.

Government Publication Date: Jun 4, 2018

Amador County - CUPA List: AMADOR CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Amador County. This list is made available by Amador County Environmental Health Department which is the CUPA for Amador County and administers a consolidated hazardous materials program.

Government Publication Date: Sep 6, 2019

Butte County -CUPA List: BUTTE CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Butte County. This list is made available by Butte County Public Health Department, Environmental Health Division which was certified by the California Environmental Protection Agency as the CUPA for Butte County.

Government Publication Date: Dec 20, 2017

Calaveras County - Landfills List: CALAVERAS LF

A list of landfills in Calaveras County. This list is made available by Calaveras County Environmental Health Department which has been designated as the CUPA for the County.

Government Publication Date: Dec 2, 2020

Calaveras County - UST Remediation Sites: CALAVERAS LUST

A list of Leaking Underground Storage Tank (LUST) facilities in Calaveras County. This list is made available by Calaveras County Environmental Health Department. Local Implementing Agency (LIA) provides oversight of site remediation with soil contamination while CalEPA - California Regional Water Quality Control Board - Central Valley Region oversees remediation of sites with groundwater contamination.

Government Publication Date: Dec 2, 2020

Calaveras County - Underground Storage Tanks List: CALAVERAS UST

A list of Underground Storage Tanks (UST) in Calaveras County provided by the Calaveras County Environmental Health Department.

Government Publication Date: Dec 2, 2020

Calaveras County - CUPA Facilities List: CALAVERAS CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Calaveras. This list is made available by Calaveras County Environmental Health Department which has been certified by CalEPA to implement the Unified program as a CUPA.

Government Publication Date: Dec 2, 2020

Colusa County - CUPA List: COLUSA CUPA

A list of facilities associated with Business Plan and Hazardous Generator programs in the County of Colusa. This list is made available by Colusa County Environmental Health which was certified by the California Environmental Protection Agency as Certified Unified Program Agency for Colusa County.

Government Publication Date: Jul 30, 2019

Contra Costa County - CUPA List: CONTRACO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Contra Costa. This list is made available by Contra Costa County which has been certified by CalEPA to implement the Unified program as a CUPA.

Government Publication Date: Mar 1, 2021

Del Norte County - CUPA Facility List: DELNORTE CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Del Norte County. This list is made available by Del Norte County Environmental Health Division which is the designated CUPA for the county.

Government Publication Date: Dec 27, 2019

El Dorado County - CUPA Facility List: ELDORADO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in El Dorado County. This list is made available by El Dorado County Department of Environmental Management - Hazardous Waste Division which is approved by CalEPA as CUPA for El Dorado County.

Government Publication Date: Oct 19, 2020

Fresno County - CUPA/Solid Waste Programs Resource List: FRESNO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Fresno County. This list is made available by Fresno County Department of Environmental Health Division which is approved by Cal-EPA as CUPA for the County.

Government Publication Date: Jan 14, 2021

Glenn County - CUPA List: GLENN CUPA

The Glenn County Air Pollution Control District is the Administering Agency and the Certified Unified Program Agency (CUPA) for Glenn County with responsibility for regulating hazardous materials handlers, hazardous waste generators, underground storage tank facilities, above ground storage tanks, and stationary sources handling regulated substances.

Government Publication Date: Jan 16, 2018

Humboldt County - CUPA Facility List: HUMBOLDT CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Humboldt County. This list is made available by Humboldt County Division of Environmental Health which is approved by the State Secretary for Environmental Protection as CUPA for the County.

Government Publication Date: Jan 13, 2021

Imperial County - CUPA Facility List: IMPERIAL CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Imperial County. This list is made available by the California Department of Toxic Substances Control (DTSC) which is appointed as CUPA for Imperial County.

Government Publication Date: Jan 28, 2021

Inyo County - CUPA Facility List: INYO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Inyo. This list is made available by the Inyo County Environmental Health Services Department which has been certified by CalEPA to implement the Unified program as a CUPA.

Government Publication Date: Nov 28, 2017

Kern County - UST List: KERN UST

A list of active and inactive Underground Storage Tanks made available by the Environmental Health Division of Kern County, California.

Government Publication Date: Jan 29, 2021

Kern County - AST List: KERN AST

A list of aboveground storage tanks in the county of Kern. This list is made available by Kern County Public Health Services Department.

Government Publication Date: Jan 29, 2021

Kern County - CUPA List: KERN CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Kern. This list is made available by Kern County Environmental Health Services Department which has been certified by CalEPA to implement the Unified program as a CUPA for Kern County.

Government Publication Date: Jan 29, 2021

Kern County - City of Bakersfield CUPA List: BKRSFIELD CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the City of Bakersfield. This list is made available by the City of Bakersfield Fire Department.

Government Publication Date: Dec 2, 2020

Kings County - Underground Storage Tanks: UST KINGS

List of Underground Storage Tanks made avaiable by Kings County Environmental Health Services.

Government Publication Date: Dec 3, 2020

Kings County - CUPA Facility List: KINGS CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Kings County. This list is made available by Kings County Department of Public Health which is appointed as CUPA for the county.
Government Publication Date: Dec 3, 2020

Lake County - CUPA Facility List: LAKE CUPA
A list of facilities associated with various Certified Unified Program Agency (CUPA) and Solid Waste programs in Lake County. This list is made available by Lake County Division of Environmental Health which is CUPA for the entire county.
Government Publication Date: Dec 17, 2020

Lassen County - CUPA List: LASSEN CUPA
The Environmental Health Program of Lassen County tracks Certified Unified Program Agencies (CUPA) facilities.
Government Publication Date: Jan 30, 2020

Los Angeles County - Site Mitigation List: LA SML
A Site Mitigation List in the County of Los Angeles. The list is made available by Los Angeles County Fire Department. Site mitigation is handled by the Site Mitigation Unit (SMU) which facilitates completion of site clean-up projects of contaminated sites in an expeditious manner in all cities of the Los Angeles County except El Segundo, Glendale, Long Beach, Santa Fe Springs, and Vernon.
Government Publication Date: Mar 2, 2021

Los Angeles County - Solid Waste Sites: LA SWF
List of permitted solid waste facilities, closed landfills, historical dumpsites and other solid waste sites in Los Angeles County, made available by the Department of Public Works in Los Angeles County.
Government Publication Date: Mar 23, 2021

Los Angeles County - CUPA Program Records: LA COUNTY CUPA
A list of inspection and enforcement records for active and inactive CUPA Program facilities, made available by the Health Hazardous Materials Division (HHMD) of the County of Los Angeles Fire Department. Includes Hazardous Materials Business Plan (HMBP), California Accidental Release Prevention Plan (CalARP), Hazardous Waste Generator (HWG), and the Aboveground Petroleum Storage Act Programs (APSA). Inactive programs include facilities that are out of business or no longer regulated by the HHMD.
Government Publication Date: Mar 25, 2020

Los Angeles County - HMS List: LA HMS
List of sites in the Los Angeles County Department of Public Works Hazardous Materials System (HMS) Database which have or have had permits for Industrial Waste, Underground Storage Tanks, or Stormwater in the county of Los Angeles.
Government Publication Date: Nov 5, 2020

Los Angeles County - Santa Fe Springs Underground Storage Tank: UST SANTAFESP
A list of registered active Underground Storage Tanks (USTs) in the City of Santa Fe Springs. This list is made available by Santa Fe Springs Department of Fire-Rescue.
Government Publication Date: Dec 17, 2020

Los Angeles County - Long Beach UST List: UST LONGB
List of registered Underground Storage Tanks (USTs) in the City of Long Beach, Los Angeles County, made available by the Long Beach Certified Unified Program Agency (CUPA). The Long Beach CUPA operates under oversight shared by the Long Beach Fire Department and Health Department.
Government Publication Date: Jul 9, 2018

Los Angeles County - Burbank City CUPA List: BURBANK CUPA
A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the City of Burbank. This list is made available by the City of Burbank Fire Department.
Government Publication Date: Aug 21, 2019

Los Angeles County - El Segundo City Underground Storage Tanks List: UST ELSEGUNDO
List of registered Underground Storage Tanks (USTs) in the City of El Segundo of Los Angeles County, made available by El Segundo City Fire Department.
Government Publication Date: Jan 17, 2017

Los Angeles County - Santa Monica City Underground Storage Tank List: UST SANTA MONICA

A list of registered active Underground Storage Tanks (USTs) in the City of Santa Monica made available by Santa Monica Fire Prevention Division.

Government Publication Date: Dec 3, 2020

Los Angeles County - Santa Monica City Aboveground Storage Tank List: SANTAMON AST

List of registered Aboveground Storage Tanks (ASTs) made available by the Santa Monica Fire Department in the City of Santa Monica of Los Angeles County, California.

Government Publication Date: Dec 3, 2020

Los Angeles County - Santa Monica City CUPA Facilities List: SANTAMON CUPA

The Santa Monica Fire Department's office maintains a list of CUPA Facilities located in Santa Monica city.

Government Publication Date: Dec 3, 2020

Los Angeles County - Torrance City Underground Storage Tanks: UST TORRANCE

A list of registered Underground Storage Tank (UST) sites in Torrance City of Los Angeles County. This list is made available by Torrance City Office of Clerk.

Government Publication Date: Feb 2, 2021

Los Angeles County - Vernon City UST List: UST VERNON

A list of Underground Storage Tanks (UST) in Vernon City provided by the Vernon City Fire Department.

Government Publication Date: Mar 7, 2021

Los Angeles County - Vernon City CUPA List: VERNON CUPA

The Vernon City Fire Department's office maintains a list of CUPA Facilities located in Vernon city.

Government Publication Date: Mar 7, 2021

Los Angeles County - City of Los Angeles UST List: UST LA CITY

A list of active and inactive underground storage tank facilities made available by the Los Angeles Fire Department CUPA.

Government Publication Date: Jun 1, 2019

Los Angeles County - City of Los Angeles AST List: AST LA CITY

A list of active and inactive above ground petroleum storage tanks made available by the Los Angeles Fire Department CUPA.

Government Publication Date: Jun 1, 2019

Los Angeles County - City of Los Angeles Hazardous Materials Facilities: LA CITY HAZMAT

A list of active and inactive hazardous materials facilities made available by the Los Angeles Fire Department CUPA.

Government Publication Date: Jun 1, 2019

Madera County - CUPA Facility List: MADERA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Madera County. This list is made available by Madera County Environmental Health Department which is CUPA for the entire county.

Government Publication Date: Jul 8, 2020

Marin County - CUPA List: MARIN CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Marin. This list is made available by Marin County which has been certified by CalEPA to implement the Unified program as a CUPA.

Government Publication Date: Jul 3, 2018

Mariposa County - CUPA List: MARIPOSA CUPA

Mariposa County Health Department, Environmental Health Services, is certified by Cal-EPA as the Certified Unified Program Agency (CUPA) that administers specific hazardous materials/hazardous waste programs.

Government Publication Date: May 28, 2018

Mendocino County - UST List: MENDOCINO UST

A list of facilities in Mendocino County with active Underground Storage Tanks (USTs). This list is made available by Mendocino County Environmental Health.

Government Publication Date: Dec 21, 2020

Mendocino County - CUPA Facilities List: MENDOCINO CUPA

A list of Certified Unified Program Agency (CUPA) facilities in Mendocino County. This list is made available by the Mendocino County Environmental Health Division.

Government Publication Date: Feb 10, 2020

Merced County - CUPA Facilities List: MERCED CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Merced. This list is made available by Merced County which has been certified by CalEPA to implement the Unified program as a CUPA for the entire county.

Government Publication Date: Mar 8, 2021

Mono County - CUPA Facility List: MONO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Mono County. This list is made available by Mono County Environmental Health Department which has been certified by CalEPA to implement the Unified program as a CUPA for the entire county.

Government Publication Date: Feb 22, 2021

Monterey County - CUPA Facility List: MONTEREY CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Monterey County. This list is made available by Monterey County Hazardous Materials Management Services which is designated as the CUPA in Monterey County.

Government Publication Date: Aug 13, 2020

Napa County - LOP Site List: NAPA LOP

A list of Local Oversight Program (LOP) and non-LOP sites in Napa County, including leaking underground storage tanks. This list is made available by the Napa County Environmental Health Division.

Government Publication Date: Jun 11, 2018

Napa County - UST List: UST NAPA

List of registered Underground Storage Tanks (USTs) in the County of Napa. Includes records of withdrawn, pending, and closed licences. This list is made available by Napa County Environmental Health Division.

Government Publication Date: Dec 29, 2020

Nevada County - CUPA Facility List: NEVADA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Nevada County. This list is made available by Nevada County Department of Environmental Health which is the CUPA for all cities and unincorporated areas within Nevada County.

Government Publication Date: Mar 2, 2021

Orange County - Industrial Cleanup Program Cases Listing: ORANGE ICP

Orange County Health Care Agency's Environmental Health Division has an Industrial Cleanup (IC) program which oversees the voluntary cleanup of contaminated property. This is a list of cases (by city) which the IC program has overseen in the past, or is currently overseeing.

Government Publication Date: Feb 1, 2021

Orange County - LOP Lead Cases List: ORANGE LOP

The Local Oversight Program of the County of Orange provides regulatory cleanup oversight for cleanup of leaking underground storage tanks (USTs). This dataset is provided by the Orange County Health Care Agency.

Government Publication Date: Feb 1, 2021

Orange County - Underground Storage Tanks Listing: UST ORANGE CNTY

A list of registered Underground Storage Tank (UST) sites in Orange County. This list is made available by Orange County Health Care Agency (OCHCA), Environmental Health Division which oversees the underground storage tank inspection program in most of the cities of Orange County, with the exception of Anaheim, Fullerton, and Orange.

Government Publication Date: Feb 1, 2021

Orange County - Aboveground Petroleum Storage Tank Listing: ORANGE AST

A list of Aboveground Petroleum Storage Tank (APST) facilities inspected by Orange County Certified Unified Program Agency (CUPA) Under the Aboveground Petroleum Storage Act (APSA). This list is made available by the Environmental Health Division of Orange County Health Care Agency.

Government Publication Date: Feb 1, 2021

Orange County - Anaheim City UST Cleanup Cases: UST CLEANUP

A list of UST Cleanup Cases in the City of Anaheim in Orange County. As part of its Groundwater Protection Program, the City of Anaheim managed the UST Cleanup Oversight Program from April 1991 to June 2014. This list is published by the City of Anaheim Underground Storage Tank Cleanup Program.

Government Publication Date: May 26, 2015

Orange County - Anaheim City UST List: ANAHEIM UST

A list of Underground Storage Tanks in Anaheim City, Orange County. This list is made available by Anaheim Fire & Rescue Department.

Government Publication Date: Mar 16, 2021

Orange County - Anaheim City AST List: ANAHEIM AST

List of Aboveground Storage Tanks (ASTs) in Anaheim City, Orange County made available by Anaheim Fire & Rescue.

Government Publication Date: Mar 16, 2021

Placer County - Site Mitigation List: PLACER SML

A list of active and inactive Site Clean-up Mitigation facilities in Placer County, provided by the County's Health and Human Services Department. This is not a complete list of contaminated sites in Placer County.

Government Publication Date: Nov 18, 2020

Placer County - CUPA Facilities List: PLACER CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Placer County. This list is made available by Placer County Environmental Health which is designated CUPA for all areas of the county except for the City of Roseville.

Government Publication Date: Jan 11, 2021

Placer County - City of Roseville CUPA Facilities: ROSEVILLE CUPA

List of CUPA facilities for the City of Roseville, California. Maintained by the Roseville City Fire Department.

Government Publication Date: Dec 8, 2020

Plumas County - CUPA List: PLUMAS CUPA

In Plumas County, the Environmental Health Department is the designated Certified Unified Program Agency (CUPA) that consolidates and coordinates administrative activities such as permits, inspections, and enforcement. CUPA Programs include Hazardous Materials Business Plan (HMBP), Underground Storage Tanks (USTs), Above Ground Storage Tanks (AGTs), Hazardous Waste Generators (HWG) and CAL-ARP.

Government Publication Date: Apr 17, 2019

Riverside County - Local Oversight Program List: RIVERSIDE LOP

A list of Leaking Underground Storage Tank (LUST) facilities in Riverside County. This list is made available by Riverside County Department of Environmental Health. Environmental Cleanup Program provides oversight of assessments and cleanups at properties that have been, or may have been, contaminated with hazardous substances from LUSTs or releases associated with other commercial/industrial use.

Government Publication Date: Mar 23, 2021

Riverside County - Underground Storage Tanks List: UST RIVERSIDE

A list of registered Underground Storage Tank (UST) sites in Riverside County. This list is made available by Riverside County Department of Environmental Health. The Hazardous Materials Management Branch (HMMB) regulates and oversees the inspections of constructions, repairs, upgrades, system operation and removal of UST systems.

Government Publication Date: Mar 23, 2021

Sacramento County - Toxic Site Cleanup List: SACRAMENTO TOX

Sacramento County Environmental Management Department (EMD)'s Toxic Site Cleanup List includes sites where unauthorized releases of potentially hazardous materials have occurred. The EMD's Site Assessment & Mitigation Program, also referred to as Toxic Site Cleanup Program, provides mandated regulatory oversight of the assessment and remediation of properties on which there has been a release of hazardous materials to soil and/or groundwater.

Government Publication Date: Feb 18, 2020

Sacramento County - Master Hazardous Materials Facility List: SACRAMENTO HAZ

A list of Hazardous Materials Facilities in Sacramento County. This list is made available by Sacramento County Environmental Management Department which has been designated as the Certified Unified Program Agency (CUPA) for the County.

Government Publication Date: Feb 24, 2020

San Benito County - CUPA List: SAN BENITO CUPA

List of Certified Unified Program Agency (CUPA) facilities made available by the San Benito County Environmental Health Department.

Government Publication Date: Mar 4, 2021

San Bernardino County - CUPA List: SANBERN CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Bernardino County. This list is made available by San Bernardino County Fire Department which is the CUPA for all areas of the County except the city of Victorville.

Government Publication Date: Mar 4, 2021

San Diego County - Solid Waste Facility List: SANDIEGO SWF

A list of open and closed Solid Waste Facilities in the County of San Diego. The County of San Diego Department of Environmental Health Solid Waste Local Enforcement Agency (LEA) is certified by the California Department of Resources Recycling and Recovery to enforce state solid waste laws and regulations in San Diego County, excluding the City of San Diego. The list is made available by San Diego County Department of Environmental Health.

Government Publication Date: Dec 2, 2020

San Diego County - Local Oversight Program List: SAN DIEGO LOP

A list of Underground Storage Tank (UST) release sites in the County of San Diego. This list is made available by San Diego County Department of Environmental Health.

Government Publication Date: Jun 15, 2020

San Diego County - Hazardous Materials Management Division Database: SANDIEGO HAZ

A list of facilities with Unified Program Facility Permit in San Diego County. This list has been made available by County of San Diego Environmental Health.

Government Publication Date: Jan 4, 2021

San Diego County - UST List: SANDIEGO UST

A list of registered Underground Storage Tanks in the County of San Diego. The list is made available by the San Diego County Hazardous Materials Division.

Government Publication Date: Dec 9, 2020

San Diego County - Site Assessment and Mitigation Investigation Sites: SANDIEGO SAM

List of sites which have undergone a Site Assessment and Mitigation investigation. This list is made available by the County of San Diego Department of Environmental Health.

Government Publication Date: Jun 30, 2020

San Francisco County - LOP Sites: SANFRAN LOP

A list of Underground Storage Tank (UST) release sites in the County of San Francisco. This list is made available by San Francisco County Department of Public Health Environmental Health Protection Branch.

Government Publication Date: Aug 8, 2017

San Francisco County - UST List: SANFRAN UST

A list of registered Underground Storage Tanks (USTs) in the County of San Francisco. This ist is made available by San Francisco County Environmental Health Division. The Hazardous Materials and Waste Program provides regulatory oversight for the construction, operation, repair and removal of USTs in San Francisco.

Government Publication Date: Feb 4, 2021

San Francisco County - Aboveground Storage Tanks List: SANFRAN AST

A list of Aboveground Storage Tanks (ASTs) facilities inspected by San Francisco Department of Public Health's (SFDPH) Hazardous Materials and Waste Program. Aboveground storage containers or tanks include oil-filled equipment (such as hydraulic systems/reservoirs and heat transfer systems) which have a petroleum storage capacity of 55 gallons or greater.

Government Publication Date: Feb 4, 2021

San Francisco County - CUPA Facilities List: SANFRAN CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Francisco County. This list is made available by San Francisco County Hazardous Materials and Waste Program which is the CUPA for all areas of the County.

Government Publication Date: Feb 4, 2021

San Francisco County - Maher Ordinance: MAHER SF

List of development projects that are located on sites with known or suspected soil and/or groundwater contamination are subject to the provisions of Health Code Article 22A, which is administered by the San Francisco County Department of Public Health (DPH).

Government Publication Date: Feb 11, 2021

San Joaquin County - Site Mitigation List: SJ SML

A list of Site Mitigation sites in San Joaquin County. The county's Site Mitigation Program includes: the permitting and inspection of well installations and destructions at all local, state, and federal assessment and cleanup sites, as well as the oversight of local cleanup of releases pursuant to California Health and Safety, Sections 5412 and 101480. Activities in this program are similar to those in the Local Oversight Program but are directed at cases that do not meet criteria for the LOP and are within the scope of Environmental Health Department (EHD) staff expertise. This list is provided by San Joaquin County EHD.

Government Publication Date: Mar 8, 2021

San Joaquin County - Solid Waste Facilities: SAN JOAQUIN SWF

A list of Solid Waste Program Facilities in San Joaquin County. The list is made available by San Joaquin County Environmental Health Department.

Government Publication Date: Mar 8, 2021

San Joaquin County - LOP Sites List: SAN JOAQUIN LOP

An archived list of Local Oversight Program clean-up sites in San Joaquin County. The program has since returned to the State of California's oversight. This list is made available by San Joaquin County Environmental Health Department (EHD).

Government Publication Date: Mar 8, 2021

San Joaquin County - UST List: SANJOAQUIN UST

A list of registered Underground Storage Tanks in the County of San Joaquin. The list is made available by San Joaquin County Environmental Health Division.

Government Publication Date: Mar 8, 2021

San Joaquin County - Aboveground Tank List: SANJOAQUIN AST

A list of Aboveground Storage Tanks (ASTs) inspected by San Joaquin County Environmental Health Department (SJCEHD) under Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Mar 8, 2021

San Luis Obispo County - CUPA Facilities List: SANLUISOB CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Luis Obispo County. This list is made available by County of San Luis Obispo Environmental Health Services Division which has been designated as the CUPA for the County.

Government Publication Date: Dec 1, 2020

San Mateo County - LOP List: SANMATEO LOP

A list of Leaking Underground Storage Tank (LUST) facilities in San Mateo County. This list is made available by San Mateo County Environmental Health Services Division.

Government Publication Date: Dec 14, 2020

San Mateo County - CUPA Facilities List: SANMATEO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in San Mateo County. This list is made available by San Mateo County Environmental Health Department which has been designated as the CUPA for the County.

Government Publication Date: Feb 20, 2020

Santa Barbara County - Site Mitigation Unit (SMU) Master Site List: SANTA BARB SMU

The Site Mitigation Unit Program (SMU) oversees the assessment and mitigation of hazardous substances releases that occur (which are not related with the Leaking Underground Fuel Tank Program). The SMU Master Site List is maintained by the Santa Barbara County Public Health Department Environmental Health Services Division.

Government Publication Date: Mar 5, 2021

Santa Clara County - Historic Solvent Case Listing: SANTACLARA HSOL

The Santa Clara Valley Water District was responsible for the oversight of solvent and toxic release cases and maintained a list of historic solvent cases in Santa Clara County.

Government Publication Date: Aug 22, 2016

Santa Clara County - Local Oversight Program Listing: SANTACLARA LO

A list of Leaking Underground Storage Tanks (LUST) facilities in Santa Clara County Provided by Santa Clara Department of Environmental Health (DEH). Since July 1, 2004 the DEH has served as the oversight agency for investigations and clean-up of petroleum releases from underground storage tanks through implementation of the Local Oversight Program (LOP) contract with the State Water Resources Control Board.

Government Publication Date: Jun 14, 2017

Santa Clara County - Underground Storage Tanks: UST SANTACLARA

List of underground storage tanks made available by the County of Santa Clara's Hazardous Materials Compliance Division.

Government Publication Date: Mar 9, 2021

Santa Clara County - CUPA Facilities List: SANTACLARA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Santa Clara County. This list is made available by Santa Clara County Department of Environmental health (DEH). DEH's Hazardous Materials Compliance Division (HMCD) is CUPA for the county with jurisdiction within the Cities of Los Altos Hills, Monte Sereno, and Saratoga; and in all unincorporated areas of Santa Clara County, including Moffett Field, San Martin, and Stanford.

Government Publication Date: Mar 13, 2021

Santa Clara County - City of San Jose Hazardous Material Facilities: SANJOSE HM

A list of facilities with hazardous materials, including underground and aboveground tanks. This list is maintained by the City of San Jose Fire Department.

Government Publication Date: Oct 15, 2020

Santa Clara County - Gilroy City CUPA Facilities List: GILROY CUPA

The Gilroy City Fire Marshal's office maintains a list of CUPA Facilities located in Gilroy City.

Government Publication Date: Sep 21, 2020

Santa Clara County - Sunnyvale City CUPA List: SUNNYVALE CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Sunnyvale City, Santa Clara County. This list is made available by the Fire Prevention & Hazardous Materials division of the Sunnyvale Department of Public Safety.

Government Publication Date: Jul 16, 2019

Santa Cruz County - Site Mitigation List: SC SML

A list of Site Mitigation sites that may have become contaminated with toxic chemicals through illegal dumping or disposal, from leaking underground storage tanks, or through industrial or commercial activities. This list is provided by County of Santa Cruz Department of Enviornmental Health.

Government Publication Date: Dec 3, 2018

Santa Cruz County - CUPA Facility List: SANTACRUZ CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Santa Cruz County. This list is made available by Santa Cruz County Environmental Health Services (EHS) Division which has been designated as the CUPA for the County.

Government Publication Date: Jul 2, 2019

Shasta County - CUPA Facility List: SHASTA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Shasta County. This list is made available by Shasta County Environmental Health Division which has been designated as the CUPA for Shasta County by CalEPA.

Government Publication Date: Jan 25, 2021

Siskiyou County - CUPA List: SISKIYOU CUPA

The Hazardous Materials Management Group of Siskiyou County's Environmental Health Division Certified Unified Program Agency (CUPA) regulates underground tanks, hazardous materials (including but not limited to: hazardous substances, hazardous waste, and any material which a handler or the CUPA has reasonable basis for believing that it would be injurious to the health and safety of persons or harmful to the environment if released into the workplace or the environment.

Government Publication Date: Oct 7, 2016

Solano County - Local Oversight Program List: SOLANO LOP

A list of Leaking Underground Storage Tank (LUST) facilities in the Solano County. This list is made available by the Solano County Environmental Health Services. Since April 1993, the State Water Resources Control Board has contracted with the County of Solano to provide regulatory oversight for the cleanup of LUSTs under Local Oversight Program (LOP) contract.

Government Publication Date: Aug 20, 2019

Solano County - Underground Storage Tanks List: SOLANO UST

A list of registered Underground Storage Tanks (USTs) in the County of Solano made available by the Solano County Environmental Health Services Division. There are approximately 190 facilities throughout the county that are subject to the regulatory requirements of the UST program.

Government Publication Date: Dec 3, 2020

Solano County - CUPA List: SOLANO CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in the County of Solano. This list is made available by Solano County Environmental Health Division which has been certified by CalEPA to implement the Unified program as a CUPA.

Government Publication Date: Dec 3, 2020

Sonoma County - LOP Site List: SONOMA LOP

A list of Leaking Underground Storage Tank (LUST) facilities in Sonoma County. This list is made available by Sonoma County Department of Health Services. Sonoma County Local Oversight Program (LOP) oversees the investigation and cleanup of fuel releases from underground storage tanks in all areas of the County with the exception of the Cities of Santa Rosa and Healdsburg.

Government Publication Date: Jan 5, 2021

Sonoma County - CUPA Facilities List: SONOMA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Sonoma County. This list is made available by Sonoma County Hazardous Materials (HazMat) Division which has been designated as the CUPA for the County.

Government Publication Date: Mar 9, 2021

Sonoma County - Petaluma City CUPA Facilities: PETAL CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Petaluma City, as well as Closed files including pre-CUPA sites. This list is made available by Petaluma Fire Prevention Bureau which is the CUPA for Petaluma City in Sonoma County.

Government Publication Date: Feb 25, 2021

Stanislaus County - CUPA List: STANISLAUS CUPA

The Environmental Resources Department of Stanislaus County maintains a list of Certified Unified Program Agency (CUPA) facilities.

Government Publication Date: Mar 1, 2021

Sutter County - CUPA List: SUTTER CUPA

A list of facilities associated with Aboveground Petroleum Storage Tank (APSA) regulation, Hazardous Materials Business Plan (HMBP) Program and Underground Storage Tank (UST) regulation of Certified Unified Program Agency (CUPA) programs in Sutter County. This list is made available by Sutter County Enviornmental Health Division which has been designated as the CUPA for the County.

Government Publication Date: May 26, 2020

Tehama County - CUPA List: TEHAMA CUPA

A list of facilities that report to the Environmental Health Department (EHD) of Tehama County under a Certified Unified Program Agency (CUPA) program, or are known to the Tehama County EHD for other activities including: injection wells, solid waste facilities, hazardous waste generation. Includes exempt facilities.

Government Publication Date: Jan 13, 2021

Trinity County - CUPA List: TRINITY CUPA

On January 1, 2005, the Department of Toxic Substances Control (DTSC) was authorized by the California Environmental Protection Agency (Cal/EPA) as the Trinity County Certified Unified Program Agency (CUPA). This CUPA list was made available by the DTSC.

Government Publication Date: Feb 25, 2021

Tulare County - CUPA List: TULARE CUPA

The Certified Unified Program Agency (CUPA) unifies and consolidates under one roof the various requirements for businesses handling hazardous materials, generating or treating hazardous wastes, or operating aboveground or underground storage tanks. CUPA thereby enhances consistency, reduces duplication, and simplifies compliance for the regulated public. The Tulare County Environmental Health Division was certified as a CUPA in December, 1996.

Government Publication Date: Jan 11, 2021

Tuolumne County - CUPA Facility List: TUOLUMNE CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Tuolumne County. This list is made available by Tuolumne County Environmental Health which is the CUPA for all areas of the County.

Government Publication Date: Feb 28, 2020

Ventura County - Leaking Underground Fuel Tanks - Historic: VENTURA HLUFT

A historical list of cleanup oversight of the Leaking Underground Fuel Tank (LUFT) program provided by Ventura County Environmental Health Division. All new and existing underground fuel storage tank releases are now referred to the Los Angeles Regional Water Quality Control Board.

Government Publication Date: May 31, 2008

Ventura County - Inactive Underground Storage Tanks Sites: UST VENTURA INACT

A list of inactive Underground Storage Tank (UST) sites in Ventura County. This list is made available by Ventura County Environmental Health Division.

Government Publication Date: Mar 1, 2021

Ventura County - CUPA Facilities List: VENTURA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Ventura County. This list is made available by Ventura County Environmental health Division.

Government Publication Date: Jan 26, 2021

Ventura County - City of Oxnard CUPA Facility List: OXNARD CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Oxnard City. This list is made available by Oxnard City Fire Department which is the CUPA for Oxnard City in Ventura County.

Government Publication Date: Jul 2, 2018

Yolo County - UST List: UST YOLO

A list of registered Underground Storage Tank (UST) sites in Yolo County. This list is made available by Yolo County Environmental Health Department which regulates the construction, operation, repair and removal of USTs throughout Yolo County.

Government Publication Date: Feb 1, 2021

Yolo County - AST List: YOLO AST

A list of registered Aboveground Storage Tank (AST) in Yolo County. This list is made available by Yolo County Department of Community Services, Division of Environmental Health.

Government Publication Date: Feb 1, 2021

Yolo County - CUPA List: YOLO CUPA

The Department of Community Services, Division of Environmental Health of Yolo County maintains a list of Certified Unified Program Agency (CUPA) facilities.

Government Publication Date: Feb 1, 2021

Yuba County - UST List: YUBA UST

A list of inactive UST sites, active UST sites and active UST tank information. This is provided by the Yuba County Environmental Health Department.

Government Publication Date: Jan 9, 2017

Yuba County - CUPA Facilities List: YUBA CUPA

A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Yuba County. This list is made available by Yuba County Environmental Health Division which is the CUPA for all areas of the County.

Government Publication Date: Feb 21, 2021

Additional Environmental Record Sources

Federal

PFOA/PFOS Contaminated Sites: PFAS NPL

List of sites where PFOA or PFOS contaminants have been found in drinking water or soil. Made available by the Federal Environmental Protection Agency (EPA).

Government Publication Date: Mar 1, 2021

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program: TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.

Government Publication Date: Feb 19, 2020

Perfluorinated Alkyl Substances (PFAS) Releases: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.

Government Publication Date: Feb 19, 2020

Perfluorinated Alkyl Substances (PFAS) Water Quality: PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jul 20, 2020

Hazardous Materials Information Reporting System: HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Oct 5, 2020

Toxic Substances Control Act: TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: Feb 23, 2021

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Jan 6, 2021

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Feb 17, 2021

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: Feb 17, 2021

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: Jan 28, 2020

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 1, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: Aug 5, 2020

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) contains mine identification numbers issued by the Department of Labor Mine Safety and Health Administration (MSHA) for mines active or opened since 1971. Note that addresses may or may not correspond with the physical location of the mine itself.

Government Publication Date: Nov 3, 2020

Surface Mining Control and Reclamation Act Sites: SMCRA

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Dec 18, 2020

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2006

Uranium Mill Tailings Radiation Control Act Sites: URANIUM

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations: ALT FUELS

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: Jan 18, 2021

Registered Pesticide Establishments: SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Mar 31, 2020

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Nov 19, 2020

State

Dry Cleaning Facilities: DRYCLEANERS

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial, linen supply, commercial laundry, dry cleaning and pressing machines - Coin Operated Laundry and Dry Cleaning. This is provided by the Department of Toxic Substance Control.

Government Publication Date: Feb 22, 2021

Delisted Drycleaners: DELISTED DRYCLEANERS

Sites removed from the list of drycleaner related facilities that have EPA ID numbers, made available by the California Department of Toxic Substance Control.

Government Publication Date: Feb 22, 2021

Non-Toxic Dry Cleaning Incentive Program: DRYC GRANT

A list of grant recipients of the Non-Toxic Dry Cleaning Incentive Program made available by the California Air Resources Board (CARB). The program provides grants to eligible dry cleaning businesses to assist them in transitioning away from PERC machines to alternative non-toxic and non-smog forming technologies.

Government Publication Date: Feb 28, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of sites from the State Water Resources Control Board (SWRCB)'s GeoTracker at which one or more of the potential contaminants of concern are in the PFAS Master List of PFAS Substances made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 16, 2020

PFOA/PFOS Groundwater: PFAS GW

A list of water wells from the Groundwater Ambient Monitoring and Assessment Program (GAMA) Groundwater Information System with the groundwater chemical perfluorooctanoic acid (PFOA) (NL = 0.014 UG/L) or perfluorooctanoic sulfonate (PFOS) (NL = 0.013 UG/L). The GAMA Groundwater Information System search is made available by California Water Boards.

Government Publication Date: Oct 22, 2020

Hazardous Waste and Substances Site List - Site Cleanup: HWSS CLEANUP

The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements in providing information about the location of hazardous materials release sites. This list is published by California Department of Toxic Substance Control.

Government Publication Date: Nov 10, 2020

List of Hazardous Waste Facilities Subject to Corrective Action: DTSC HWF

This is a list of hazardous waste facilities identified in Health and Safety Code (HSC) § 25187.5. These facilities are those where Department of Toxic Substances Control (DTSC) has taken or contracted for corrective action because a facility owner/operator has failed to comply with a date for taking corrective action in an order issued under HSC § 25187, or because DTSC determined that immediate corrective action was necessary to abate an imminent or substantial endangerment.

Government Publication Date: Jul 18, 2016

EnviroStor Inspection, Compliance, and Enforcement: INSP COMP ENF

A list of permitted facilities with inspections and enforcements tracked in the Department of Toxic Substance Control (DTSC) EnviroStor.

Government Publication Date: Oct 7, 2020

School Property Evaluation Program Sites: SCH

A list of sites registered with The Department of Toxic Substances Control (DTSC) School Property Evaluation and Cleanup (SPEC) Division. SPEC is responsible for assessing, investigating and cleaning up proposed school sites. The Division ensures that selected properties are free of contamination or, if the properties were previously contaminated, that they have been cleaned up to a level that protects the students and staff who will occupy the new school.

Government Publication Date: Jan 13, 2021

California Hazardous Material Incident Report System (CHMIRS): CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS). This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Jan 21, 2021

Historical California Hazardous Material Incident Report System (CHMIRS): HIST CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS) prior to 1993. This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Jan 1, 1993

Hazardous Waste Manifest Data: HAZNET

A list of hazardous waste manifests received each year by Department of Toxic Substances Control (DTSC). The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Oct 24, 2016

Historical Hazardous Waste Manifest Data: HIST MANIFEST

A list of historic hazardous waste manifests received by the Department of Toxic Substances Control (DTSC) from year the 1980 to 1992. The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Dec 31, 1992

Historical Cortese List: HIST CORTESE

List of sites which were once included on the Cortese list. The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements for providing information about the location of hazardous sites.

Government Publication Date: Nov 13, 2008

Cease and Desist Orders and Cleanup and Abatement Orders: CDO/CAO

The California Environment Protection Agency "Cortese List" of active Cease and Desist Orders (CDO) and Cleanup and Abatement Orders (CAO). This list contains many CDOs and CAOs that do NOT concern the discharge of wastes that are hazardous materials. Many of the listed orders concern, as examples, discharges of domestic sewage, food processing wastes, or sediment that do not contain hazardous materials, but the Water Boards' database does not distinguish between these types of orders.

Government Publication Date: Feb 16, 2012

California Environmental Reporting System (CERS) Hazardous Waste Sites: CERS HAZ

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Feb 9, 2021

Delisted Environmental Reporting System (CERS) Hazardous Waste Sites: DELISTED HAZ

This database contains a list of sites that were removed from the California Environmental Protection Agency (CalEPA) in the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator.

Government Publication Date: Nov 29, 2018

Sites in GeoTracker: GEOTRACKER

GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. This is a list of sites in GeoTracker that aren't otherwise categorized as LUST, Land Disposal Sites (LDS), Cleanup Sites, or sites having Waste Discharge Requirements (WDR). This listing includes program types such as Underground Injection Control (UIC), Confined Animal Facilities (CAF), Irrigated Lands Regulatory Program, plans, and non-case information.

Government Publication Date: Nov 16, 2020

Waste Discharge Requirements: WASTE DISCHG

List of sites in California State Water Resources Control Board (SWRCB) Waste Discharge Requirements (WDRs) Program in California, made available by the SWRCB via GeoTracker. The WDR program regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Government Publication Date: Nov 16, 2020

Toxic Pollutant Emissions Facilities: EMISSIONS

A list of criteria and toxic pollutant emissions data for facilities in California made available by the California Environmental Protection Agency - Air Resources Board (ARB). Risk data may be based on previous inventory submittals. The toxics data are submitted to the ARB by the local air districts as requirement of the Air Toxics "Hot Spots" Program. This program requires emission inventory updates every four years.

Government Publication Date: Dec 31, 2018

Clandestine Drug Lab Sites: CDL

The Department of Toxic Substances Control (DTSC) maintains a listing of drug lab sites. DTSC is responsible for removal and disposal of hazardous substances discovered by law enforcement officials while investigating illegal/clandestine drug laboratories.

Government Publication Date: Jan 19, 2021

Tribal

No Tribal additional environmental record sources available for this State.

County

Los Angeles County - Santa Monica City Hazardous Materials Facilities: SANTAMON HAZ

A list of Hazardous Materials Facilities in the City of Santa Monica, Los Angeles county. This list is made available by Santa Monica Fire Prevention Division which has been designated as the CUPA for the City.

Government Publication Date: Mar 12, 2020

Los Angeles County - Santa Monica City Hazardous Waste Facilities: SANTAMON HW

A list of Hazardous Waste Facilities in Los Angeles County, City of Santa Monica. This list is made available by Santa Monica Fire Prevention Division.

Government Publication Date: Jul 19, 2019

Orange County - Hazardous Waste Facilities: ORANGE HW

A list of Hazardous Waste Facilities in Orange County. This list is made available by Orange County Environmental Health Department.

Government Publication Date: Feb 1, 2021

Riverside County - Hazardous Waste Generator Sites List: RIVERSIDE HWG

A list of Hazardous Waste Generator Sites in the County of Riverside. This list is made available by Riverside County Department of Environmental Health which has been designated as the CUPA for the County.

Government Publication Date: Mar 23, 2021

Riverside County - Disclosure Facility List: RIVERSIDE HZH

A list of facilities disclosed to Riverside County Department of Environmental Health (DEH). This list is made available by Riverside County DEH which has been designated as the CUPA for the County. A business is required to establish and submit a Business Plan if the facility handles hazardous material equal to or greater than 55 gallons, 500 pounds or 200 cubic feet at any time during the year.

Government Publication Date: Nov 24, 2020

San Joaquin County - Complaints and Incident Reports: SJ COMPLAINTS

A list of sites associated with complaints received by San Joaquin County Environmental Health Department, including spill and release reports.

Government Publication Date: Mar 8, 2021

San Joaquin County - Hazardous Materials Facilities List: SANJOAQUIN HM

A list of Hazardous Materials Facilities in San Joaquin County. This list is made available by San Joaquin County Environmental Health Department which has been designated as the CUPA for the County.

Government Publication Date: Mar 8, 2021

San Joaquin County - Hazardous Waste Facilities: SANJOAQUIN HW

A list of Hazardous Waste Facilities in San Joaquin County. This list is made available by San Joaquin County Environmental Health Department which has been designated as the CUPA for the County.

Government Publication Date: Mar 8, 2021

Ventura County - Hazardous Material Release (Prop 65) Sites: VENTURA HAZR

A historic list of hazardous material releases from the Hazardous Material Release Report collected by the Environmental Health Division of Ventura County. As per the department this report contains records from 1987 to 2017.

Government Publication Date: Mar 19, 2021

Ventura County - Inactive Hazardous Waste Sites: VENTURA IHW

A list of Inactive Hazardous Waste Sites in Ventura County collected by Ventura County's Environmental Health Division.

Government Publication Date: Dec 28, 2020

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

USER QUESTIONNAIRE RESPONSES

USER QUESTIONNAIRE

Pursuant to ASTM E1527, ASTM E2600, and the EPA All Appropriate Inquiry Rule, the User of the report must answer specific questions regarding the property and supply this information to the Environmental Professional. While we understand that you may have only limited knowledge of the property, please answer the questions to the best of your ability based on your current knowledge and return the completed questionnaire to Intertek.

Phase I ESA Questions *Please see previous Phase I Reports provided*

1. Did a review of land title records (or judicial records where appropriate) identify any environmental cleanup liens filed or recorded against the subject property under federal, tribal, state or local law?
   ☐ No ☐ Yes ☐ Unknown (if yes, please briefly discuss on the next page or as an attachment)

2. Did a review of land title records (or judicial records where appropriate) identify any activity and land use limitations (AULs), such as engineering controls, land use restrictions or institutional controls that are in place at the subject property and/or have been filed or recorded in a registry under federal, tribal, state, or local law?
   ☐ No ☐ Yes ☐ Unknown (if yes, please briefly discuss on the next page or as an attachment)

3. Do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

4. Does the purchase price being paid reasonably reflect the fair market value of the subject property?
   ☐ No ☐ Yes ☐ Not Applicable

   If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?
   ☐ No ☐ Yes

5. Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example:

   (a) Do you know of the past uses of the property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

   (b) Do you know of specific chemicals that are present or were once present at the property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

   (c) Do you know of spills or other chemical releases that have taken place at the property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

   (d) Do you know of any environmental cleanups that have taken place at the property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

6. Based on your knowledge and experience related to the subject property are there any obvious indicators that point to the presence or likely presence of contamination at the subject property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

7. Do you know of any pending, threatened, or past litigation or administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the property?
   ☐ No ☐ Yes (if yes, please briefly discuss on the next page or as an attachment)

8. Do you know of any notices from any governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products?
   ☐ No ☐ Yes (if yes, please briefly discuss below or as an attachment)

Further Explain any Answers Requiring Clarification:

_____

_____

_____

Vapor Encroachment Screening Questions

1. Currently, what type of property is the subject property?
   ☐ Commercial ☐ Industrial ☐ Residential ☐ Multi-Tenant ☐ Vacant Land

2. Are there buildings on the subject property?
   ☐ Yes ☐ No ☐ Unknown (if yes, indicate number and construction type):

   _____

3. Will buildings or structures be constructed on the subject property in the future?
   ☐ Yes ☐ No ☐ Unknown (if yes, indicate number and construction type)

   _____

4. If buildings exist or are proposed, do/will they have elevators?
   ☐ No ☐ Yes ☐ Unknown

5. What type of below-grade level exists or is proposed?
   ☐ Full/Partial Basement ☐ Crawl Space ☐ Parking Garage ☐ Multi-Level
   ☐ None/Unknown (if none/unknown, skip to question 11)

6. Is there ventilation currently/proposed in the below-grade level?
   ☐ No ☐ Yes ☐ Unknown

7. Are there sump pumps, floor drains or trenches existing or proposed in the below-grade level?
   ☐ No ☐ Yes ☐ Unknown

8. Is there a radon or methane mitigation system installed or proposed?
   ☐ No ☐ Yes ☐ Unknown (If yes, please indicate if ☐passive or ☐active)

9. What type of heating system exists or is proposed in the building? (check all that apply)
   ☐ Hot Air Circulation ☐ Hot Air Radiation ☐ Hot Water Radiation
   ☐ Hot Water Circulation ☐ Fireplace ☐ Radiant Floor Heat ☐ Fuel Oil Furnace
   ☐ Electric Baseboard ☐ Heat Pump ☐ Wood Stove ☐ Steam Radiation
   ☐ Coal Furnace ☐ Kerosene Heater ☐ Used Oil Heater ☐ Natural Gas Furnace
   ☐ Other

10. How are the utility systems fueled/powered or proposed to be fueled/powered? (check all that apply)
    ☐ Natural Gas ☐ Propane ☐ Kerosene ☐ Coal ☐ Wood ☐ Electricity
    ☐ Fuel Oil ☐ Solar ☐ Wind ☐ Other

11. Have there ever been any environmental problems at the subject property?
    ☐ No ☐ Yes ☐ Unknown (if yes, please describe)

12. Does/will a gas station or dry cleaner operate anywhere on the subject property?
    ☐ No ☐ Yes ☐ Unknown

13. Do/will any of the tenants use hazardous chemicals in relatively large quantities on the subject property?
    ☐ No ☐ Yes ☐ Unknown

14. Have any tenants ever complained about odors in the building or experienced health-related problems that may have been associated with the building?
☐ No ☐ Yes ☐ Unknown

15. Are the current or proposed operations on the subject property going to require/require special OSHA or EPA permitting?
☐ No ☐ Yes ☐ Unknown

16. Are there any existing or proposed underground or aboveground storage tanks (ASTs/USTs) on the subject property?
☐ No ☐ Yes ☐ Unknown (if yes, please describe)

17. Are there sensitive receptors (for example: children, elderly, people in poor health, and so forth) that occupy or will occupy the subject property?
☐ No ☐ Yes ☐ Unknown

Further Explain any Answers Requiring Clarification:

PLease see previous Phase I Reports provided

Helpful Documents Checklist

Pursuant to ASTM E 1527 §10.8, do you know whether any of the following documents exist related to the subject property, and if so, whether copies will be provided to Intertek for review? If so, please submit such documentation to Intertek as soon as practical. Please check all that apply.

☐ Environmental site assessment reports (for example: Phase I/II ESAs or RBCA reports)

☐ Environmental compliance audit reports; or risk assessments

☐ Environmental permits or hazardous waste generation notices or reports

☐ Registrations for above or underground storage tanks, or underground injection systems

☐ Safety data sheets (formerly known as Material Safety Data Sheets or MSDSs)

☐ Community right-to-know plans; safety plans; preparedness and prevention plans; spill prevention, countermeasure and control (SPCC) plans; etc.

☐ Notices or other correspondence from any governmental agency relating to past or current violations of environmental laws with respect to the property or relating to environmental liens on the property

☐ Geotechnical studies; or reports regarding hydrogeologic conditions on the property or vicinity

☐ Recorded activity and land use limitations (AULs)

Nicole Bray	Senior Transaction Analyst
Name (Authorized User Representative)	Title
Nicole Bray	4/6/21
Signature	Date

HISTORICAL RESEARCH DOCUMENTATION



US Aerial 1938

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1948

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1952

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1959

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1966

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1973

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1977

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1985

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 1994

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 2002

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 2005

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13

intertek psi



US Aerial 2010

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Aerial 2012

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 2014

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Aerial 2016


Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13

intertek psi




US Aerial 2018

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Aerial 2020

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1897 15

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1900 15

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1903 15

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1953 7.5

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1954 15

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1966 7.5

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13




US Topo 1973 7.5

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Topo 1981 7.5

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13



US Topo 2015 7.5

Project Falcon
3401 Etiwanda Avenue - Bldg 1011
Jurupa Valley, California 91752
Work Order #: 00662058-13

INTERVIEW DOCUMENTATION

Eliza Sahakian

From: Jurupa Valley Public Records <jurupavalleyca@govqa.us>
Sent: Friday, April 2, 2021 10:17 AM
To: Eliza Sahakian
Subject: [External] [Records Center] Public Records Request :: R000138-032921

--- Please respond above this line ---

RE: PUBLIC RECORDS REQUEST of March 29, 2021, Reference # R000138-032921.

Dear Eliza Sahakian,

The City of Jurupa Valley received a Public Record Act request from you on March 29, 2021. Your request is set forth below:

"We are conducting a Phase I ESA and requesting any files related to Fire, Demo, CUPA, LUST, and hazardous materials. Records pertaining to underground storage tanks, spills, leaks, cleanups, and releases at the subject property.
Address: 3401 Etiwanda Avenue, Jurupa Velley, CA 91752
APN: 156150069"

The City of Jurupa Valley has reviewed its files and has located responsive records to your request. Please log in to the Public Records Center at the following link to retrieve the appropriate responsive documents.

Public Records Request - R000138-032921 [u8387778.ct.sendgrid.net]

Code Enforcement provided records relating to a closed code enforcement matter. The City of Jurupa Valley does not issue permits for underground storage tanks, aboveground storage tanks, or hazardous materials use or storage on the property. The Riverside County Fire Department (http://www.rvcfire.org/ [u8387778.ct.sendgrid.net]) may have records relating to the release or spillage of hazardous materials and contaminated ground water or soil records.

This concludes the City of Jurupa Valley's response to your Public Records Act request.

Sincerely,

City of Jurupa Valley
Debra McNay
Deputy City Clerk

To monitor the progress or update this request please log into the Public Records Center [u8387778.ct.sendgrid.net]

This message is from an EXTERNAL SENDER - please be CAUTIOUS, particularly with links and attachments.

Eliza Sahakian

From: Jurupa Valley Public Records <jurupavalleyca@govqa.us>
Sent: Wednesday, April 7, 2021 10:31 AM
To: Eliza Sahakian
Subject: [External] [Records Center] Public Records Request :: R000142-040121

--- Please respond above this line ---

RE: PUBLIC RECORDS REQUEST of April 01, 2021, Reference # R000142-040121

Dear Eliza Sahakian,

The City of Jurupa Valley received a Public Record Act request from you on April 01, 2021. Your request is set forth below:

"We are conducting a Phase I ESA and requesting any files related to Fire, Demo, CUPA, LUST, and hazardous materials. Records pertaining to underground storage tanks, spills, leaks, cleanups, and releases at the subject property.
Address: 1011 Space Center Ct, Mira Loma, CA 91752
APN: portion of 156150069"

The City of Jurupa Valley has reviewed its files and has determined there are no responsive documents to your request. 1011 Space Center Court is not a recognized address in the City of Jurupa Valley. The Building Department does not have any records for the APN listed.

Many of these services are not provided by the City of Jurupa Valley. The City has no records relating to storage tanks, flammable material storage, demolition/renovation permits, spills, environmental issues, fire code violations, water connection or violations or sewer connection or discharge permits. The Riverside County Fire Department (http://www.rvcfire.org/) may have records relating to hazardous or flammable materials, spills, fire code violations or potential environmental issues. The Jurupa Community Services District (https://www.jcsd.us/) or the Rubidoux Community Services District (https://www.rcsd.org/) may have records relating to the water and sewer connection for this address.

This concludes the City of Jurupa Valley's response to your Public Records Act request.

Sincerely,

City of Jurupa Valley
Debra McNay
Deputy City Clerk

To monitor the progress or update this request please log into the Public Records Center [u8387778.ct.sendgrid.net]

This message is from an EXTERNAL SENDER - please be CAUTIOUS, particularly with links and attachments.

Teira Solis

From: Eliza Sahakian
Sent: Wednesday, April 7, 2021 4:40 PM
To: Teira Solis
Subject: FW: [External] [Records Center] Public Records Request :: R000142-040121
Attachments: FOIA City 1011.pdf

00662058-13 for 1011 Space Center (3401 is leasing office address for this industrial park). Still waiting on the County response for this address.

Eliza Sahakian
Geologist/Environmental Scientist
Building & Construction
Intertek-PSI

Mobile +1 562 325 1572
Direct +1 562 758 1460
Office +1 714 484 8600
Email eliza.sahakian@intertek.com
www.intertek.com/building

Intertek-PSI, 11980 Telegraph Rd. #104 Santa Fe Springs, CA 90670

From: Jurupa Valley Public Records <jurupavalleyca@govqa.us>
Sent: Wednesday, April 7, 2021 10:31 AM
To: Eliza Sahakian <eliza.sahakian@intertek.com>
Subject: [External] [Records Center] Public Records Request :: R000142-040121

--- Please respond above this line ---

RE: PUBLIC RECORDS REQUEST of April 01, 2021, Reference # R000142-040121

Dear Eliza Sahakian,

The City of Jurupa Valley received a Public Record Act request from you on April 01, 2021. Your request is set forth below:

"We are conducting a Phase I ESA and requesting any files related to Fire, Demo, CUPA, LUST, and hazardous materials. Records pertaining to underground storage tanks, spills, leaks, cleanups, and releases at the subject property.
Address: 1011 Space Center Ct, Mira Loma, CA 91752
APN: portion of 156150069"

The City of Jurupa Valley has reviewed its files and has determined there are no responsive documents to your request. 1011 Space Center Court is not a recognized address in the City of Jurupa Valley. The Building Department does not have any records for the APN listed.


Many of these services are not provided by the City of Jurupa Valley. The City has no records relating to storage tanks, flammable material storage, demolition/renovation permits, spills, environmental issues, fire code violations, water connection or violations or sewer connection or discharge permits. The Riverside County Fire Department (http://www.rvcfire.org/) may have records relating to hazardous or flammable materials, spills, fire code violations or potential environmental issues. The Jurupa Community Services District (https://www.jcsd.us/) or the Rubidoux Community Services District (https://www.rcsd.org/) may have records relating to the water and sewer connection for this address.

This concludes the City of Jurupa Valley's response to your Public Records Act request.

Sincerely,

City of Jurupa Valley
Debra McNay
Deputy City Clerk

To monitor the progress or update this request please log into the Public Records Center [u8387778.ct.sendgrid.net]



This message is from an EXTERNAL SENDER - please be CAUTIOUS, particularly with links and attachments.

DATA GAP WORKSHEET

Project Name: br40345
Work Order Number: 00662058-13

DATA GAP WORKSHEET

Requirement	Status			Other Sources of Information	SDG*
Category Activity	**N/A**	**Complete**	**Incomplete**	**Reference Source(s) Obtained or What Sources PSI Used to Try To Close Data Gap**	**Blank if None**
User Responsibilities					
User Knowledge and Information		☐	☒	PSI was not provided with a User Questionnaire. However, the client directed Psi to the ones in previous Phase Is.	
Environmental Lien and AUL Information		☐	☒		
PSI Obtained Environmental Lien/AUL Search on Behalf of Client (**BOLD YES or NO**)		YES	**NO**		
PSI Obtained Chain-of-Title on Behalf of Client (**BOLD YES or NO**)		YES	**NO**		
Environmental Records Review					
Standard Environmental Records Source Information		☒	☐		
Discretionary or Local Environmental Records Source Information	☐	☒	☐		
Physical Setting Sources Review					
Standard Physical Setting Record Information (topo map)		☒	☐		
Additional Physical Setting Record Information	☐	☒	☐		
Historical Data Sources Review					
Property History Identified to 1940		☒	☒		
Property History Identified to First Developed Use		☒	☐		
Gaps of >5 Years in Historical Data Sources (**BOLD YES (there or gaps) or NO (no gaps)**)		**YES**	NO		
Surrounding Property History Information		☒	☐		

Project Name: br40345
Work Order Number: 00662058-13

DATA GAP WORKSHEET

Requirement	Status			Other Sources of Information	SDG*
Category Activity	**N/A**	**Complete**	**Incomplete**	**Reference Source(s) Obtained or What Sources PSI Used to Try To Close Data Gap**	**Blank if None**
Site Reconnaissance					
Observations: Exterior areas of the Subject Property		☒	☐		
Observations: Interior of Buildings on the Subject Property	☐	☒	☐		
Current and Past Uses of the Subject Property		☒	☐		
Observations: Adjoining Property		☒	☐		
Current and Past Uses of the Adjoining Property		☒	☐		
Uses of the Surrounding Property		☒	☐		
Interviews (with…)					
Current Owner		☐	☒		
Identified Key Site Manager	☐	☒	☐		
Non-Residential Major Occupants	☐	☐	☒		
Occupants with Operations Likely to Indicate RECs	☐	☐	☒		
Past Owners, Operators, and/or Occupants	☐	☐	☒		
If Subject Property Abandoned or Vacant, Owner or Occupants of Neighboring Properties	☒	☐	☐		
State or Local Government Official		☐	☒		

Project Name: br40345
Work Order Number: 00662058-13

DATA GAP WORKSHEET

Requirement	Status			Other Sources of Information	SDG*
Category Activity	**N/A**	**Complete**	**Incomplete**	**Reference Source(s) Obtained or What Sources PSI Used to Try To Close Data Gap**	**Blank if None**
FOIAs (to…)					
Fire Department	☐	☐	☒		
City of Jurupa Valley	☐	☒	☐		
State-Equivalent Environmental Department	☐	☐	☒	Awaiting response	
	☐	☐	☐		

Comments and Explanations Regarding Incomplete Data

*** SDG = Significant Data Gap. List Identified SDG(s) in Section 1.1.5 of the Report**

SUPPLEMENTAL DOCUMENTATION

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		21032900155p
Date Completed:		April 1, 2021
Project Number:		00662058
Project Property:		Space Center 3401 Etiwanda Ave - Bldg 1011 Jurupa Valley CA
Coordinates:		
	Latitude:	34.02592934
	Longitude:	-117.53327404
	UTM Northing:	3765159.1827 Meters
	UTM Easting:	450767.998263 Meters
	UTM Zone:	UTM Zone 11S
	Elevation:	817.40 ft
	Slope Direction:	S

Topographic Information....2
Hydrologic Information....12
Geologic Information....20
Soil Information....23
Wells and Additional Sources....31
Summary....33
Detail Report....34
Radon Information....36
Appendix....37
Liability Notice....39


The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2015)

0 0.2 0.4 0.8 1.2 1.6 Miles


N

Quadrangle(s): Corona North,CA; Fontana,CA; Guasti,CA; Ontario,CA; Prado Dam,CA; Riverside West,CA

Source: USGS 7.5 Minute Topographic Map

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Topographic Information



Current USGS Topo - Page 1

0 0.2 0.4 0.8 Miles


N

Quadrangle(s): Guasti,CA

Source: USGS 7.5 Minute Topographic Map

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Topographic Information




Current USGS Topo - Page 2

Quadrangle(s): Fontana,CA; Guasti,CA

Source: USGS 7.5 Minute Topographic Map

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Topographic Information



Current USGS Topo - Page 3

0 0.2 0.4 0.8 Miles


N

Quadrangle(s): Guasti,CA

Source: USGS 7.5 Minute Topographic Map

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Topographic Information



Current USGS Topo - Page 4

0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Fontana,CA; Guasti,CA

Source: USGS 7.5 Minute Topographic Map


ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Topographic Information


The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:


Elevation:	817.40 ft
Slope Direction:	S




Topographic Information




Topographic Information



Topographic Information



Topographic Information



Hydrologic Information



Wetland

0 0.125 0.25 0.5 Miles

N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Wetland Type - Page 1

0 0.125 0.25 0.5 Miles


N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information




Flood Hazard Zones

Miles
0 0.2 0.4 0.8

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.


A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED

N



ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Flood Hazard Zones - Page 1

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

Miles
0 0.2 0.4


N

06071C8633J
06065C0016G
06071C8641J
06065C0017G
06071C8642J

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Flood Hazard Zones - Page 2

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED


0 0.2 0.4 Miles

N

06071C8634J
06065C0017G
06071C8642J
06071C8665H

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Flood Hazard Zones - Page 3

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED


0 0.2 0.4 Miles

N

06071C8641J
06071C8643H
06065C0018G

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information



Flood Hazard Zones - Page 4

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

Miles
0 0.2 0.4

N

06071C8642J
06065C0036G
06071C8644H
06065C0038G
06071C8665H

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.

Available FIRM Panels in area:	06065C0016G(effective:2008-08-28) 06065C0019G(effective:2008-08-28) 06071C8644H(effective:2008-08-28) 06071C8643H(effective:2008-08-28) 06071C8642J(effective:2014-09-26) 06071C8641J(effective:2016-09-02) 06065C0018G(effective:2008-08-28) 06065C0017G(effective:2008-08-28)

Flood Zone A-01

Zone:	A
Zone subtype:	

Flood Zone AE-11

Zone:	AE
Zone subtype:	FLOODWAY

Flood Zone AE-12

Zone:	AE
Zone subtype:	FLOODWAY CONTAINED IN CHANNEL

Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Geologic Information



Miles
0 0.2 0.4


N

Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Geologic Information



Geologic Units - Page 1

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES


Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.

Geologic Unit Q

Unit Name:	Quaternary alluvium and marine deposits
Unit Age:	Pliocene to Holocene
Primary Rock Type:	alluvium
Secondary Rock Type:	terrace
Unit Description:	Alluvium, lake, playa, and terrace deposits; unconsolidated and semi-consolidated. Mostly nonmarine, but includes marine deposits near the coast.

Soil Information



SSURGO Soils


0 0.2 0.4 Miles

N

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Soil Information



SSURGO Soils - Page 1

Miles
0 0.2 0.4

N

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit DaD2 (2.63%)

Map Unit Name:	Delhi fine sand, 2 to 15 percent slopes, wind-eroded
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Delhi(85%)

horizon H1(0cm to 25cm)	Fine sand
horizon H2(25cm to 122cm)	Sand
horizon H3(122cm to 152cm)	Fine sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: DaD2 - Delhi fine sand, 2 to 15 percent slopes, wind-eroded

Component: Delhi (85%)
The Delhi component makes up 85 percent of the map unit. Slopes are 2 to 15 percent. This component is on alluvial fans, dunes. The parent material consists of wind modified alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 3e. This soil does not meet hydric criteria.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Component: Unnamed (5%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Component: Hilmar (5%)
Generated brief soil descriptions are created for major soil components. The Hilmar soil is a minor component.

Map Unit Db (38.07%)

Map Unit Name:	Delhi fine sand
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Delhi(85%)

horizon H1(0cm to 46cm)	Fine sand
horizon H2(46cm to 152cm)	Sand

Component Description:

Soil Information

Minor map unit components are excluded from this report.

Map Unit: Db - Delhi fine sand

Component: Delhi (85%)
The Delhi component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans. The parent material consists of sandy alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 3e. This soil does not meet hydric criteria.

Component: Unnamed (5%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Component: Unnamed (5%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Map Unit DbA (1.68%)

Map Unit Name:	Delhi loamy fine sand, 0 to 2 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Delhi(85%)

horizon H1(0cm to 25cm)	Loamy fine sand
horizon H2(25cm to 122cm)	Sand
horizon H3(122cm to 152cm)	Fine sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: DbA - Delhi loamy fine sand, 0 to 2 percent slopes

Component: Delhi (85%)
The Delhi component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans, dunes. The parent material consists of wind modified alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 2e. This soil does not meet hydric criteria.

Component: Hilmar (10%)
Generated brief soil descriptions are created for major soil components. The Hilmar soil is a minor component.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Map Unit GlC (1.23%)

Map Unit Name:	Gorgonio loamy sand, deep, 2 to 8 percent slopes

Soil Information

Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Gorgonio(85%)

horizon H1(0cm to 38cm)	Loamy sand
horizon H2(38cm to 152cm)	Stratified gravelly loamy sand to gravelly loamy fine sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: GlC - Gorgonio loamy sand, deep, 2 to 8 percent slopes

Component: Gorgonio (85%)
The Gorgonio component makes up 85 percent of the map unit. Slopes are 2 to 8 percent. This component is on alluvial fans. The parent material consists of alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 2e. This soil does not meet hydric criteria.

Component: Hanford (5%)
Generated brief soil descriptions are created for major soil components. The Hanford soil is a minor component.

Component: Soboba (5%)
Generated brief soil descriptions are created for major soil components. The Soboba soil is a minor component.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Map Unit GP (0.12%)

Map Unit Name:	Gravel pits

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: GP - Gravel pits

Component: Gravel pits (100%)
Generated brief soil descriptions are created for major soil components. The Gravel pits is a miscellaneous area.

Map Unit HgA (0.13%)

Map Unit Name:	Hanford fine sandy loam, 0 to 2 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Hanford(85%)

horizon H1(0cm to 20cm)	Fine sandy loam
horizon H2(20cm to 102cm)	Fine sandy loam
horizon H3(102cm to 152cm)	Stratified loamy sand to coarse sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: HgA - Hanford fine sandy loam, 0 to 2 percent slopes

Component: Hanford (85%)
The Hanford component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans. The parent material consists of alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD029CA Loamy (1975) ecological site. Nonirrigated land capability classification is 3c. Irrigated land capability classification is 1 This soil does not meet hydric criteria.

Component: Ramona (5%)
Generated brief soil descriptions are created for major soil components. The Ramona soil is a minor component.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Component: Greenfield (5%)
Generated brief soil descriptions are created for major soil components. The Greenfield soil is a minor component.

Map Unit HlA (0.05%)

Map Unit Name:	Hilmar loamy very fine sand, 0 to 2 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Moderately well drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Hilmar(85%)

horizon H1(0cm to 41cm)	Loamy fine sand
horizon H2(41cm to 183cm)	Loamy fine sand
horizon H2(41cm to 183cm)	Loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: HlA - Hilmar loamy very fine sand, 0 to 2 percent slopes

Component: Hilmar (85%)
The Hilmar component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans. The parent material consists of alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 3e. Irrigated land capability classification is 2e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 32 within 30 inches of the soil surface.

Component: Delhi (5%)
Generated brief soil descriptions are created for major soil components. The Delhi soil is a minor component.

Soil Information

Component: Chino (5%)
Generated brief soil descriptions are created for major soil components. The Chino soil is a minor component.

Component: Tujunga (5%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Map Unit TuB (55.84%)

Map Unit Name:	Tujunga loamy sand, 0 to 5 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Tujunga(85%)

horizon A(0cm to 15cm)	Loamy sand
horizon C1(15cm to 46cm)	Loamy sand
horizon C2(46cm to 152cm)	Loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: TuB - Tujunga loamy sand, 0 to 5 percent slopes

Component: Tujunga (85%)
The Tujunga, loamy sand component makes up 85 percent of the map unit. Slopes are 0 to 5 percent. This component is on alluvial fans, alluvial plains. The parent material consists of alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 4e. This soil does not meet hydric criteria.

Component: Tujunga (10%)
Generated brief soil descriptions are created for major soil components. The Tujunga soil is a minor component.

Component: Hanford (5%)
Generated brief soil descriptions are created for major soil components. The Hanford soil is a minor component.

Map Unit TwC (0.24%)

Map Unit Name:	Tujunga gravelly loamy sand, 0 to 8 percent slopes
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Tujunga(85%)

horizon H1(0cm to 25cm)	Gravelly loamy sand
horizon H2(25cm to 152cm)	Loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: TwC - Tujunga gravelly loamy sand, 0 to 8 percent slopes

Soil Information

Component: Tujunga (85%)
The Tujunga component makes up 85 percent of the map unit. Slopes are 0 to 8 percent. This component is on alluvial fans, flood plains. The parent material consists of sandy alluvium derived from granite. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 4s. This soil does not meet hydric criteria.

Component: Delhi (10%)
Generated brief soil descriptions are created for major soil components. The Delhi soil is a minor component.

Component: Soboba (5%)
Generated brief soil descriptions are created for major soil components. The Soboba soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

- ▲ Sites with Higher Elevation
- ■ Sites with Same Elevation
- ▼ Sites with Lower Elevation
- ○ Sites with Unknown Elevation

N

0 0.15 0.3 0.6 Miles

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Wells and Additional Sources



Wells & Additional Sources - Page 1

- ▲ Sites with Higher Elevation
- ■ Sites with Same Elevation
- ▼ Sites with Lower Elevation
- ○ Sites with Unknown Elevation

Miles
0 0.15 0.3 0.6

N

ERIS
ENVIRONMENTAL RISK INFORMATION SERVICES

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	ID	Distance (ft)	Direction
	No records found		

Safe Drinking Water Information System (SDWIS)

Map Key	ID	Distance (ft)	Direction
	No records found		

USGS National Water Information System

Map Key	ID	Distance (ft)	Direction
	No records found		

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Periodic Groundwater Level Measurement Locations

Map Key	ID	Distance (ft)	Direction
	No records found		

Well Completion Reports

Map Key	WCR No	Distance (ft)	Direction
1	WCR1929-000176	0.00	-
1	WCR2004-011975	0.00	-
1	WCR1776-007658	0.00	-
1	WCR1949-000494	0.00	-
1	WCR2006-012799	0.00	-

Wells and Additional Sources Detail Report

Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	817.71	WATER WELLS

WCR No:	WCR1929-000176	County:	Riverside
County(OSWCR):	Riverside	Decimal Latitude:	34.02607
Decimal Lat(OSWCR):	34.02607	Decimal Longitude:	-117.53309
Decim Long(OSWCR):	-117.53309		
Location(OSWCR):	COUNTY LINE RD, ETIWANDA AVE, RIVERSIDE		
City(OSWCR):	WINEVILLE		
Location:	COUNTY LINE RD, ETIWANDA AVE, RIVERSIDE		
City:	WINEVILLE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers), as of Apr 29, 2020; California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	817.71	WATER WELLS

WCR No:	WCR2004-011975	County:	Riverside
County(OSWCR):	Riverside	Decimal Latitude:	34.02607
Decimal Lat(OSWCR):	34.02607	Decimal Longitude:	-117.53309
Decim Long(OSWCR):	-117.53309		
Location(OSWCR):	Space Center Dr		
City(OSWCR):	Mira Loma		
Location:	Space Center Dr		
City:	Mira Loma		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers), as of Apr 29, 2020; California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	817.71	WATER WELLS

WCR No:	WCR1776-007658	County:	Riverside
County(OSWCR):	Riverside	Decimal Latitude:	34.02607
Decimal Lat(OSWCR):	34.02607	Decimal Longitude:	-117.53309
Decim Long(OSWCR):	-117.53309		
Location(OSWCR):	COUNTY LINE RD, ETIWANDA AVE		
City(OSWCR):	WINEVILLE		
Location:	COUNTY LINE RD, ETIWANDA AVE		
City:	WINEVILLE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers), as of Apr 29, 2020; California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

1	-	0.00	0.00	817.71	WATER WELLS

WCR No:	WCR1949-000494	County:	Riverside
County(OSWCR):	Riverside	Decimal Latitude:	34.02607
Decimal Lat(OSWCR):	34.02607	Decimal Longitude:	-117.53309
Decim Long(OSWCR):	-117.53309		
Location(OSWCR):	QUARTERMASTER DEPOT		
City(OSWCR):	Mira Loma		
Location:	QUARTERMASTER DEPOT		
City:	Mira Loma		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers), as of Apr 29, 2020; California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	817.71	WATER WELLS

WCR No:	WCR2006-012799	County:	Riverside
County(OSWCR):	Riverside	Decimal Latitude:	34.02607
Decimal Lat(OSWCR):	34.02607	Decimal Longitude:	-117.53309
Decim Long(OSWCR):	-117.53309		
Location(OSWCR):	Etiwanda Avenue		
City(OSWCR):	Mira Loma		
Location:	Etiwanda Avenue		
City:	Mira Loma		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers), as of Apr 29, 2020; California Department of Water Resources - Well Completion Reports		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *RIVERSIDE* County: **2**
Federal EPA Radon Zone for *SAN BERNARDINO* County: **2**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SAN BERNARDINO* County

No Measures/Homes:	17
Geometric Mean:	0.5
Arithmetic Mean:	0.7
Median:	0.7
Standard Deviation:	1
Maximum:	2.9
% >4 pCi/L:	0
% >20 pCi/L:	0
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of California conducted during 1989-90. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Federal Area Radon Information for *RIVERSIDE* County

No Measures/Homes:	24
Geometric Mean:	0.3
Arithmetic Mean:	0.3
Median:	0.5
Standard Deviation:	0.8
Maximum:	1.7
% >4 pCi/L:	0
% >20 pCi/L:	0
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of California conducted during 1989-90. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

List of drinking water violations and enforcement actions from the Safe Drinking Water Information System (SDWIS) made available by the Drinking Water Protection Division of the US EPA's Office of Groundwater and Drinking Water. Enforcement sensitive actions are not included in the data released by the EPA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

The Safe Drinking Water Information System (SDWIS) contains information about public water systems as reported to US Environmental Protection Agency (EPA) by the states. Addresses may correspond with the location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey (USGS)'s National Water Information System (NWIS) is the nation's principal repository of water resources data. This database includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data.

State Sources

Oil and Gas Wells — **OGW**

A list of Oil and Gas well locations. This is provided by California's Department of Conservation Division of

Appendix

Oil, Gas and Geothermal Resources.

Periodic Groundwater Level Measurement Locations **MONITOR WELLS**

Locations of groundwater level monitoring wells in the Department of Water Resources (DWR)'s Periodic Groundwater Levels dataset. The DWR Periodic Groundwater Levels dataset contains seasonal and long-term groundwater level measurements collected by the Department of Water Resources and cooperating agencies.

Well Completion Reports **WATER WELLS**

List of wells from the Well Completion Reports data made available by the California Department of Water Resources' (DWR) Online System for Well Completion Reports (OSWCR). Please note that the majority of well completion reports have been spatially registered to the center of the 1x1 mile Public Land Survey System section that the well is located in.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

STATE WATER RESOURCES CONTROL BOARD

GEOTRACKER

CASE SUMMARY

REPORT DATE
7/19/1990

HAZARDOUS MATERIAL INCIDENT REPORT FILED WITH OES?

I. REPORTED BY -

UNKNOWN

CREATED BY

UNKNOWN

III. SITE LOCATION

FACILITY NAME
SPACE CENTER MIRA LOMA

FACILITY ID

FACILITY ADDRESS
3401 ETIWANDA AVE
MIRA LOMA, CA 91752
RIVERSIDE COUNTY

ORIENTATION OF SITE TO STREET

CROSS STREET

V. SUBSTANCES RELEASED / CONTAMINANT(S) OF CONCERN

GASOLINE

VI. DISCOVERY/ABATEMENT

DATE DISCHARGE BEGAN

DATE DISCOVERED	HOW DISCOVERED	DESCRIPTION
6/22/1990	Tank Closure	

DATE STOPPED	STOP METHOD	DESCRIPTION
6/22/1990		

VII. SOURCE/CAUSE

SOURCE OF DISCHARGE
Tank

CAUSE OF DISCHARGE
Unknown

DISCHARGE DESCRIPTION

VIII. CASE TYPE

CASE TYPE
Soil

IX. REMEDIAL ACTION

NO REMEDIAL ACTIONS ENTERED

X. GENERAL COMMENTS

XI. CERTIFICATION

I HEREBY CERTIFY THAT THE INFORMATION REPORTED HEREIN IS TRUE AND ACCURATE TO THE BEST OF MY KNOWLEDGE.

XII. REGULATORY USE ONLY

LOCAL AGENCY CASE NUMBER
90640

REGIONAL BOARD CASE NUMBER
083301605T

LOCAL AGENCY

CONTACT NAME	INITIALS	ORGANIZATION_NAME	EMAIL ADDRESS
Riverside County LOP	RIV	RIVERSIDE COUNTY LOP	

ADDRESS	CONTACT DESCRIPTION
3880 LEMON ST SUITE 200 RIVERSIDE, CA 92501	Riverside County Closed & Transferred Sites assigned to this "general contact"

PHONE TYPE	PHONE NUMBER	EXTENSION
PHONE	(951)-955-8980	

REGIONAL BOARD

UNKNOWN

Copyright © 2021 State of California

Radon Zone Map (with State Information)

Bookmark

- Hawaii
- Guam
- Puerto Rico
- Virgin Islands
- Alaska
- CONUS


Legend

State Radon Information including State Contacts

Radon

Radon Data

- Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
- Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
- Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L



All rights reserved

Assessor - County Clerk - Recorder
Riverside County, CA

Property Detail

3401 SPACE CENTER CT JURUPA VALLEY CA 91752

Assessment No.	156150069
APN	156150069
Property Type	Light Industrial
Neighborhood	Industrial - Eastvale / Jurupa Valley / Norco
Acreage	105.43

Legal Description

105.43 ACRES M/L IN POR SEC 5 T2S R6W FOR TOTAL DESCRIPTION SEE ASSESSORS MAPS TownshipN 2 Acres 105.43 M/L Section 05 Portion 1/2 Range 06 RangeDirection W

Value History (Part 1)

Year	Reason Date	Market Value				Factored Base Year Value			
		Land	Improvement	Living Improvement	Total	Land	Improvement	Living Improvement	Total
2017	Other 01/01/2017					$1,290,026	$10,214,124		$11,504,150
2018	Other 01/01/2018					$1,315,826	$10,418,406		$11,734,232
2018	Transfer 20/03/2019	$36,000,000	$28,000,000		$64,000,000	$36,000,000	$28,000,000		$64,000,000
2019	01/01/2019					$1,342,142	$10,626,774		$11,968,916
2019	Transfer 20/03/2019	$36,000,000	$28,000,000		$64,000,000	$36,000,000	$28,000,000		$64,000,000
2020	01/01/2020					$36,720,000	$28,560,000		$65,280,000

Value History (Part 2)

Year	Restricted Value				Assessed Value				Penalty	Exemption	Net Taxable Value
	Land	Improvement	Living Improvement	Total	Land	Improvement	Living Improvement	Total			
2017					$1,290,026	$10,214,124		$11,504,150			$11,504,150
2018					$1,315,826	$10,418,406		$11,734,232			$11,734,232
2018					$34,684,174	$17,581,594		$52,265,768			$52,265,768
2019					$1,342,142	$10,626,774		$11,968,916			$11,968,916
2019					$34,657,858	$17,373,226		$52,031,084			$52,031,084
2020					$36,720,000	$28,560,000		$65,280,000			$65,280,000

Transfer History

Doc #	Sales Price	Date	Vacant Land
2019-0093026	$0	3/20/2019	False
2011-0266776-C	$0	6/16/2011	False

Features

Land Details

Primary Use	Land Type	Acres	Eff. Frontage	Eff. Depth
Commercial	LandLine 01 / 156150069 / Commercial	105.43	0.00	0.00

Building 1 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 10 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1776

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 2 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 3 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 4 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 5 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 6 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 7 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 8 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Building 9 - Building Details

Address 3401 SPACE CENTER CT
Type Light Industrial
Year Built 1941

Image: Sketch Image

Structural Elements

Use	Detail
Foundation	Concrete
Lighting	Average

Floor Areas

Description	Level	Gross Area	Finished Area	Construction Type
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)

Riverside County is not liable for erroneous or incomplete data.
California Revenue and Taxation Code Sec. 408.3 (d)

Date Printed: 4/6/2021

General Information

Property Address	3401 SPACE CENTER CT JURUPA VALLEY, CA 91752
Assessment No. (PIN)	156150069
APN (GeoCode)	156150069
Property Type	Light Industrial
TAG	028-066 JURUPA VALLEY
Acreage	105.43
Doing Business As	

Legal Description
105.43 ACRES M/L IN POR SEC 5 T2S R6W FOR TOTAL DESCRIPTION SEE ASSESSORS MAPS TownshipN 2 Acres 105.43 M/L Section 05 Portion 1/2 Range 06 RangeDirection W



Valuation data as of: **Monday, April 05, 2021**

Valuation data updated weekly.

Transfer History

Date	Document #	Sale Price
3/20/2019	2019-0093026	$0
6/16/2011	2011-0266776-C	$0

Buildings

Building 1 | Building 10 | Building 2 | Building 3 | Building 4 | Building 5 | Building 6 | Building 7 | Building 8 | Building 9

Floor Areas | Structural Elements | Units/Costs

DESCRIPTION	TYPE	GROSS	FINISHED	CONSTRUCTION
Unknown / Unable to Convert	Ground	0.00	0.00	Wood or Light Steel (D)
Total Area			**0.00**	

Address 3401 SPACE CENTER CT

Grade Light Industrial

Year Built 1941

Features does not exist for this account.

Land

Primary Use	Land Type	Acres	Eff. Frontage	Eff. Depth
Commercial	LandLine 01 / 156150069 / Commercial	105.43	0.00	0.00

Land Use Detail does not exist for this account.

Copyright 2021 by Aumentum Technologies

United States Department of Agriculture

NRCS

Natural Resources Conservation Service

A product of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local participants

Custom Soil Resource Report for Western Riverside Area, California

br40345



April 6, 2021

Preface

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (https://offices.sc.egov.usda.gov/locator/app?agency=nrcs) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2_053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

Contents

Preface.....2
How Soil Surveys Are Made.....5
Soil Map.....8
Soil Map.....9
Legend.....10
Map Unit Legend.....11
Map Unit Descriptions.....11
Western Riverside Area, California.....13
DbA—Delhi loamy fine sand, 0 to 2 percent slopes.....13
References.....15

How Soil Surveys Are Made

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.


After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

Soil Map

The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.

Custom Soil Resource Report
Soil Map



Map Scale: 1:1,940 if printed on A landscape (11" x 8.5") sheet.

N

Meters: 0 25 50 100 150

Feet: 0 50 100 200 300

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 11N WGS84

MAP LEGEND

Area of Interest (AOI)
- Area of Interest (AOI)

Soils
- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

Special Point Features
- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

Water Features
- Streams and Canals

Transportation
- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

Background
- Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:15,800.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Western Riverside Area, California
Survey Area Data: Version 13, May 27, 2020

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: May 10, 2018—Jun 5, 2018

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
DbA	Delhi loamy fine sand, 0 to 2 percent slopes	10.4	100.0%
Totals for Area of Interest		**10.4**	**100.0%**

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An *association* is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

Western Riverside Area, California

DbA—Delhi loamy fine sand, 0 to 2 percent slopes

Map Unit Setting

National map unit symbol: hcsy
Elevation: 200 to 1,400 feet
Mean annual precipitation: 13 inches
Mean annual air temperature: 63 degrees F
Frost-free period: 225 to 310 days
Farmland classification: Prime farmland if irrigated

Map Unit Composition

Delhi and similar soils: 85 percent
Minor components: 15 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Delhi

Setting

Landform: Alluvial fans, dunes
Landform position (three-dimensional): Tread
Down-slope shape: Linear
Across-slope shape: Linear, convex
Parent material: Wind modified alluvium derived from granite

Typical profile

H1 - 0 to 10 inches: loamy fine sand
H2 - 10 to 48 inches: sand
H3 - 48 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 2 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Somewhat excessively drained
Runoff class: Negligible
Capacity of the most limiting layer to transmit water (Ksat): High (1.98 to 5.95 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Available water capacity: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 2e
Land capability classification (nonirrigated): 4e
Hydrologic Soil Group: A
Ecological site: R019XD035CA
Hydric soil rating: No

Minor Components

Hilmar

Percent of map unit: 10 percent
Hydric soil rating: No

Tujunga

Percent of map unit: 5 percent
Hydric soil rating: No

References

American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.

American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.

Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.

Federal Register. July 13, 1994. Changes in hydric soils of the United States.

Federal Register. September 18, 2002. Hydric soils of the United States.

Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.

National Research Council. 1995. Wetlands: Characteristics and boundaries.

Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262

Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053577

Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053580

Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.

United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.

United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2_053374

United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624


United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf

Groundwater Level Report

Station 340233N1175215W001

Station Data | Groundwater Level Data

Groundwater Levels for Well 340233N1175215W001



Download Data

Measurement Date (PST)	Reference Point Elevation	Ground Surface Elevation	Distance from RP to WS	Groundwater Elevation	Ground Surface to Water Surface	Measurement Issue	Collecting Agency	Water Level Measurement Comments
04/01/2020 00:00:00	810.400	810.400	238	572.4	238		Chino Basin Watermaster...	
05/01/2020 00:00:00	810.400	810.400	243	567.4	243		Chino Basin Watermaster...	
06/01/2020 00:00:00	810.400	810.400	224	586.4	224		Chino Basin Watermaster...	
07/01/2020 00:00:00	810.400	810.400	250	560.4	250		Chino Basin Watermaster...	
08/01/2020 00:00:00	810.400	810.400	255	555.4	255		Chino Basin Watermaster...	
09/01/2020 00:00:00	810.400	810.400	258	552.4	258		Chino Basin Watermaster...	

201 to 206 of 206 records

‹ 1 2 3 4 5 6 7 8 9 ›

Copyright © 2020 State of California


text

Groundwater Level Report

Station 340233N1175215W001

Station Data | Groundwater Level Data

State Well Number:	02S06W04M002S
Local Well Name:	CHINO-1003469
Site Code:	340233N1175215W001
Latitude (NAD83):	34.023337
Longitude (NAD83):	-117.521465
Basin Subbasin Name (Code):	Chino (8-002.01)
Well Use Type:	Residential
Well Status:	Active
WCR Number:	351358
Reference Point Elevation (NAVD88 ft):	810.400
Ground Surface Elevation (NAVD88 ft):	810.400
Well Depth (feet bgs):	400
Perforated Interval Depths (feet bgs):	230.000 390.000




Copyright © 2020 State of California

Well Report

JURUPA COMMUNITY SD (JURUPA VALLEY)
WELL 22
11201 Harrel Street
JURUPA VALLEY , CA 91752

State Well #: 3310021-033
Well Source: Groundwater
Well Status: Active Raw

Detailed Well Information | Water Quality Data



DATE	PARAMETER	RESULT	UNITS	MCL
8/12/2020	LEAD	< 5	UG/L	NA
8/15/2019	LEAD	< 5	UG/L	NA
7/17/2018	LEAD	< 5	UG/L	NA
8/8/2017	LEAD	< 5	UG/L	NA
8/2/2016	LEAD	< 5	UG/L	NA
8/13/2015	LEAD	< 5	UG/L	NA
8/12/2014	LEAD	< 5	UG/L	NA
8/6/2013	LEAD	< 5	UG/L	NA
8/8/2012	LEAD	< 5	UG/L	NA
8/3/2011	LEAD	< 5	UG/L	NA
8/4/2010	LEAD	< 5	UG/L	NA
8/6/2009	LEAD	< 5	UG/L	NA
8/7/2008	LEAD	< 5	UG/L	NA
7/10/2007	LEAD	< 5	UG/L	NA
9/20/2006	LEAD	< 5	UG/L	NA
8/5/2005	LEAD	< 5	UG/L	NA
5/26/2005	LEAD	< 5	UG/L	NA
6/7/2004	LEAD	< 0	UG/L	NA

FROM DATE: TO DATE: GRAPH SIZE: Medium NORMALIZED: Redraw

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92505
951-332-6464

PLCK No:	Permit No: 2011-0432
Date:	Date: 10/21/11
Amount:	Amount: 187.64
Ck #:	Ck #:

Building Combination Permit

Permit # 2011-0432		Date	
Jobsite Address 3401 Etiwanda #			Space # 811D
City Mira Loma	State CA	Zip Code 91752	Assessors Parcel Number 156-150-063
Property Owner's Last Name, First Name Mira Loma Space Center			Phone Number
Permit Use: Meter Reset			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name:		First	
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ **OWNER BUILDER** __X__ **CONTRACTOR**

Contractor - Name Multer Electric		Type C1	License # 296043
Mailing Address 11098 Venture Dr "D"		City Mira Loma	State Ca / Zip Code 91752
Phone Number (951) 360 3424	Fax Number 951 360 3429	Email (optional)	
Architect or Engineer		Type	License#
Mailing Address	City		State / Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map #				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits				

Finaled: 10-24-2011

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92505
951-332-6464

PLCK No: 2012-0711	Permit No:
Date: 1/24/12	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

issued 2/15/12

Permit # 2012-0711 | Date 1-24-12

Jobsite Address 3401 ETIWANDA AVE BLDG. 1011 | Space # A, B & C

City MIRA LOMA | State CA | Zip Code 91752 | Assessors Parcel Number 156150063-9

Property Owner's Last Name, First Name SPACE CENTER | Phone Number 951-685-5221

Permit Use: OCCUPANCY PERMIT – Furniture Storage W/H

PP 3/18

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: BAUCOM | First DAVID

Mailing Address 8390 MAPLE PLACE #140 | City RANCHO CUCAMONGA | State CA | Zip Code 91730

Phone Number (909) 481-1950 x201 | Fax Number 909-481-1959 | Email (optional) DAVID@DBAAINC.COM

Check one: X **OWNER BUILDER** ____ **CONTRACTOR**

Contractor -Name | Type | License #

Mailing Address | City | State | Zip Code

Phone Number ( ) | Fax Number | Email (optional)

Architect or Engineer DBA ARCHITECTS INC. | Type | License# C 22017

Mailing Address 8390 MAPLE PL. #140 | City RANCHO CUCAMONGA | State CA | Zip Code 91730

Phone Number: (909) 481-1950 x201 | Fax Number 909-481-1959 | Email (optional) DAVID@DBAAINC.COM

FOR OFFICE USE ONLY

Planning Case # PP 9097 | Parcel/Tract Map # Docs - 16 Plans

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Plans - 3 Val - 15,000

Final: 02-17-2012

fire submittal

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3232
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3232			Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE			Space #
City Jurupa	State CA	Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER			Phone Number
Permit Use: Reroof Building 921 - Section A (Layover - No Tear off)			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING		First Ray	
Mailing Address	City	State	Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING	Type C-39	License # 475568	
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	
Architect or Engineer	Type	License#	
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000				(B) E P M
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3233
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3233	Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE	Space #
City JURUPA / State CA / Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER	Phone Number
Permit Use: Reroof Building 721 - Section A (Layover - No Tearoff)	

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING	First Ray		
Mailing Address	City	State	Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING	Type C-39	License # 475568	
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	
Architect or Engineer	Type	License#	
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000 (B) E P M				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3234
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3234			Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE			Space #
City JURUPA	State CA	Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER			Phone Number
Permit Use: Reroof Building 911 - Section C & D (Layover - No Tearoff			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING		First Ray	
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING		Type C-39	License # 475568
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	

Architect or Engineer		Type	License#
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000 (B) E P M				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2014-5250
Date:	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2014-5250 | Date

Jobsite Address: 3401 E Temescal Ave | Space # Bldg. 8 11

City: Jurupa | State: CA | Zip Code | Assessors Parcel Number

Property Owner's Last Name, First Name: Space Center Mira Loma Inc | Phone Number

Permit Use: Reroof Section A, B, C (layover)

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Evans | First: Ray

Mailing Address | City | State | Zip Code

Phone Number: (909) 973 1600 | Fax Number | Email (optional)

Check one: ____**OWNER BUILDER** ____**CONTRACTOR**

Contractor -Name: Howard's Roofing Company | Type: C-39 | License #: 475568

Mailing Address: 245 N. Mountain View Ave | City: Ontario | State: CA | Zip Code: 91762

Phone Number: (909) 622-5598 | Fax Number | Email (optional)

Architect or Engineer | Type | License#

Mailing Address | City | State | Zip Code

Phone Number: ( ) | Fax Number | Email (optional)

FOR OFFICE USE ONLY

Planning Case # Lot / Tract | Parcel/Tract Map # Val = B E P M

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs - Plans -

Final: 11-04-2014

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2014-5251
Date:	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit #	Date
Jobsite Address: 3401 E Rubidoux Blvd	Space # Bldg 921
City: Jurupa	State: CA / Zip Code / Assessors Parcel Number
Property Owner's Last Name, First Name: Space Center Mira Loma Inc	Phone Number
Permit Use: Reroof Section B (layover)	

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Evans	First: Ray
Mailing Address	City / State / Zip Code
Phone Number: (909) 973 1606	Fax Number / Email (optional)

Check one: ____ **OWNER BUILDER** ____ **CONTRACTOR**

Contractor -Name: Howard Roofing Company	Type: C-39	License #: 475560
Mailing Address: 245 N. Mountain View Ave	City: Pomona	State: CA / Zip Code: 91767
Phone Number: (909) 622-5598	Fax Number / Email (optional)	
Architect or Engineer	Type / License#	
Mailing Address	City / State / Zip Code	
Phone Number: ( )	Fax Number / Email (optional)	

FOR OFFICE USE ONLY

Planning Case # Lot / Tract	Parcel/Tract Map # Val =						
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits: Doc 5-		Plans-		

Final: 11-04-2014

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2014-5473	Permit No: 2014-5473
Date: 10/10/14	Date: 1/7/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2014-5473 — Issued Date 1/7/15

Jobsite Address: 3401 ETIWANDA BUILDING D SECTION 921 — Space #:

City: JURUPA VALLEY — State: CA — Zip Code: 91752 — Assessors Parcel Number: 156-150-069

Property Owner's Last Name, First Name: CRUIKSHANK TOM — Phone Number: 951-685-5221

Permit Use: NEW 3,000 AMP 2 SERVICE

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: LEE — First: WAYNE

Mailing Address: 12461 E. FRANCIS ST — City: ONTARIO — State: CA — Zip Code: 91761

Phone Number: (909) 923-0070 — Fax Number: 909-923-0858 — Email (optional): WAYNE@VALELECTRIC.COM

Check one: ____ **OWNER BUILDER** X **CONTRACTOR**

Contractor -Name: VAL ELECTRIC INC. — Type: C10 — License #: 576817

Mailing Address: 12461 E. FRANCIS — City: ONTARIO — State: CA — Zip Code: 91761

Phone Number: (909) 923-0070 — Fax Number: 923-0858 — Email (optional):

Architect or Engineer — Type — License#

Mailing Address — City — State — Zip Code

Phone Number: ( ) — Fax Number — Email (optional)

FOR OFFICE USE ONLY

Planning Case # Lot / Tract — Parcel/Tract Map # Val = BEPM

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs-2 Plans-1

Final: 02-18-2015

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2015-6817	Permit No: 2015-6817
Date:	Date: 5/22/15
Amount:	Amount:
Chk #:	Chk #:

Building Combination Permit

Permit # 2015-6817			Date Issued 5/22/15
Jobsite Address: 3401 Etiwanda Avenue			Space #: Building 1011, Sections C and D - 86,400 s.f.
City: Jurupa Valley	State: CA	Zip Code: 91752	Assessors Parcel Number: 156150069-5
Property Owner's Last Name, First Name: Space Center Mira Loma, Inc.			Phone Number: 951-685-5221
Permit Use: 86,400 square feet existing-Change of Tenancy and Pallet Racking Plans-3401 Etiwanda Ave., Bldg. 1011, Sections C & D			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL suupplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Hanes Companies, Inc. (New Tenant) MARTINEZ			First: JOHN
Mailing Address: ~~500 Mullin Creek Road~~ 565 PORTER WAY		City: ~~Grasmere~~ PLACENTIA	State: ~~ID~~ Zip Code: ~~2~~ 92870
Phone Number: ~~208-465-1078~~ 714.269.8693	Fax Number: ~~208-486-0723~~	Email (optional): JOHN@WAREHOUSEPERMITS.COM ~~pat.hollet@hanescompanies.com~~	

Check one: ○ OWNER BUILDER ◉ CONTRACTOR

Contractor - Name: RACK US UP	Type: C61/D24	License #: 863780		
Mailing Address: 8620 SORENSEN AVE #8		City: SANTA FE SPRINGS	State: CA	Zip Code: 90670
Phone Number: 526-713-1104	Fax Number:	Email (optional): RACKUSUP@YAHOO.COM		
Architect or Engineer: STRUCTURAL CONCEPTS ENG.	Type: CIVIL	License #: 69381		
Mailing Address: 1615 YEAGER AVE		City: LA VERNE	State: CA	Zip Code: 91750
Phone Number: 909.596.1350	Fax Number:	Email (optional): MAIL@SCEINC.NET		

FOR OFFICE USE ONLY

Planning Case #				Parcel/Tract Map #			
Legal Zone	SP/PA	Lot Size	FBS	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire - Y/N	Flood - Y/N	Thomas Guide		Assoc Permts			

Final: 08-14-2015

val - 60,000
Plans - 5
Docs - 31

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2015-8268
Date:	Date: 9/25/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2015-8268			Date 9-25-15
Jobsite Address 3401 E Etiwanda ave			Space #
City Mira loma	State CA	Zip Code 91752	Assessors Parcel Number
Property Owner's Last Name, First Name Allianz of America inc			Phone Number
Permit Use: Reroof Comml Bldg			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Marlowe		First William	
Mailing Address 525 new Jersey st	City Redlands	State CA	Zip Code 92373
Phone Number (909) 335 6300	Fax Number 909-335-6790	Email (optional)	

Check one: ____**OWNER BUILDER** ____**CONTRACTOR**

Contractor -Name clark Roofing Company		Type C39	License # 765388
Mailing Address 525 new Jersey st	City Redlands	State CA	Zip Code 92373
Phone Number (909) 335-6300	Fax Number 909 335 6790	Email (optional)	
Architect or Engineer		Type	License#
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case # Lot / Tract			Parcel/Tract Map # Val = 524 K BEPM				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs-		Plans-		

Final: 01-14-2016

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2012-1072	Permit No:
Date: 5/4/12	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2012-1072 — Date 05-03-12 — issued 6/22/12

Jobsite Address: 3401 Etiwanda Ave Bldg.1011			Space # A
City: Jurupa Valley	State: CA	Zip Code: 91752	Assessors Parcel Number: 156-140-10
Property Owner's Last Name, First Name: Space Center			Phone Number: 951-685-5221
Permit Use: Tenant Improvement – Restrooms			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Gomez		First: Junior	
Mailing Address: 8390 Maple Place #140		City: Rancho Cucamonga	State: CA / Zip Code: 91730
Phone Number: (909) 481-1920x205	Fax Number: 909-481-1952	Email (optional): Porfirio@dbaainc.com	

Check one: ____OWNER BUILDER ____CONTRACTOR

Contractor -Name		Type	License #
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Architect or Engineer: DBA Architects INC.		Type	License#: C 22017
Mailing Address: 8390 Maple Place #140	City: Rancho Cucamonga	State: CA	Zip Code: 91730
Phone Number: (909) 481-1920x201	Fax Number: 909-481-1952	Email (optional): David@dbaainc.com	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val – 15,000 DEPM				
Legal Zone	SP/PA	Lot Size	FSB	Lf. SB	Rt. SB	R.SB...	SEPTIC/SEWER
High Fire – Y/N	Flood – Y/N	Thomas Guide	Assoc Permits Plans – 7 Docs –				

5.4 F

Final: 07-31-2012

1603.95

P
N

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2015-7600
Date:	Date: 7/9/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2015-7600	Date 7-9-15

Jobsite Address: 3401 ETIWANDA AVE #1011 | Space #:

City: JURUPA VALLEY | State: CA | Zip Code: | Assessors Parcel Number:

Property Owner's Last Name, First Name: MIKE WAKSMUNSKI | Phone Number: 336-747-1678

Permit Use: SIGN PERMIT - Hanes Industries

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: EMPERADO | First: RUDY

Mailing Address: 4774 MURRIETA ST. #1 | City: CHINO | State: CA | Zip Code: 91710

Phone Number: (909) 364-8135 | Fax Number: 909-364-8314 | Email (optional): rudyemp@AOL.com

Check one: ____ **OWNER BUILDER** __X__ **CONTRACTOR**

Contractor -Name: SIGNSPLUS | Type: C45 | License #: 812259

Mailing Address: 4774 MURRIETA ST #1 | City: CHINO | State: CA | Zip Code: 91710

Phone Number: (909) 364-8135 | Fax Number: 909-364-8374 | Email (optional): chinosignsplus@AOL.com

Architect or Engineer: | Type: | License#:

Mailing Address: | City: | State: | Zip Code:

Phone Number: ( ) | Fax Number: | Email (optional):

FOR OFFICE USE ONLY

Planning Case # Lot / Tract | Parcel/Tract Map # Val=1200 (B) E P M

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs- 5 Plans-

Final: 07-29-2015

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15893	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 811-A			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752

Permit Description:

Meter Release

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number / Fax Number	Email (optional)		
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number / Fax Number	Email (optional)		

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15894	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 811-B			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752

Permit Description:

Meter Release

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15895	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 1011-B			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752
Permit Description: Meter Release			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2019-19021	Date Submitted: 07/24/2019		Date Issued: 07/24/2019
Project Address: 3401 Etiwanda Ave			Assessors Parcel Number: 156150069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Fullmer Construction	First Name:		Phone Number:
Property Owner's Address:	City:	State:	Zip Code:

Permit Description:

100 amp Temp Power pole, 1 sub distro 100 amp pole, 1 transformer. Construction Trailer. 30' High. No Encroachment Required.

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Same as Contractor	First:		
Mailing Address:	City:	State:	Zip Code:
Phone Number:	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name Temp Power Systems	License # 696713	Classification C-10	Business Registration #:	Exp. Date
Mailing Address 625 Fee Ana	City Placentia	State CA	Zip Code 92870	
Phone Number 714-767-0199	Fax Number	Email (optional)		
Architect or Engineer	License #	Type		
Mailing Address	City	State	Zip Code	
Phone Number	Fax Number	Email (optional)		

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 4,000.00	BEPM
Permit Tech Initials: DM		Docs: 4	Plans: 2

Final: 07-31-2019

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

City of Jurupa Valley
Building & Safety Department
Building Permit Application

Permit No: B19-000836
Status: Closed - Final - 10/09/2020
Submittal Date: 11/07/2019
Issue Date: 04/29/2020

Project Address/Location: 3401 ETIWANDA AVE	**Assessor's Parcel Number: 156150069**

Description of Work: HIGH PILE STORAGE RACKS

Tract #:	Lot #:	Valuation: $58,000.00
Owner: C/O TRACY L PFAFF 3401 ETIWANDA AVE MIRA LOMA CA 91752	*Applicant: THE RACK DEPOT INC 10226 GREENLEAF AVE SANTA FE SPRINGS CA 90670 5627779809	Site Contact:
Contractor: THE RACK DEPOT INC 10226 GREENLEAF AVE SANTA FE SPRINGS CA 90670 5627779809 853858	Architect:	Engineer:

For inspection requests, please use our online service by going to www.JurupaValley.org. Select Online Inspection Requests. If you have difficulties scheduling your inspection, please call our inspection request line at (951) 332-0790.

"This permit expires in 365 days after the issuance of the permit if no substantial progress is verified by city staff"

Type of Project: Commercial	Code Year: 2016 CA

Constuction Type:	Occupancy Group:	Square Footage
Fire Sprinklers:	Use:	Occupant Load:

Building Department Fees Paid = 905.79
Balance Due = 0.00
*Note: The "Applicant" will be financially responsible for all supplemental billings, fees and refunds for this permit per Ordinance 457. Any changes to the "Applicant" information must be made in writing and submitted to the Building Department for approval.

APPLICANT'S ACCEPTANCE:

Applicant Signature **Date**

CITY APPROVAL:

for Keith Clarke, Chief Building Official

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

NOTICE OF VIOLATION AND ORDER TO COMPLY

SPACE CENTER MIRA LOMA INC
3401 ETIWANDA AVE # 503
MIRA LOMA, CA 91752-1128

APN: 156-150-069
Case No: CE-19-0573

Date: April 4, 2019

Re: 3401 ETIWANDA AVE

To SPACE CENTER MIRA LOMA INC,

A recent inspection of your property at 3401 ETIWANDA AVE JURUPA VALLEY, CA 91752-1128 revealed that it contained conditions which violate the City of Jurupa Valley Municipal Code because of the following defects:

1. **Solid Waste Collection & Disposal-**No person shall collect, transfer or remove solid waste in the city without a valid permit or franchise issued by the city. - Jurupa Valley Municipal Code § 6.75.030
   Corrective Action Required: There are tenants on your property that are collecting, transferring, and/or removing waste in the city that are not properly using the franchisee contracted by the City. We have evidence that multiple sub tenants are using third party waste removal companies other than the City of Jurupa Valley's franchisee BURRTEC. Please notify your tenants that they have a responsibility to use the proper franchisee BURRTEC only for solid waste removal. Failure to comply will result in further administrative action.

Section 17920.3 of the California Health & Safety Code declares all such substandard buildings a public nuisance and requires the abatement thereof by repair, if practical, rehabilitation or by demolition. Conditions caused, maintained, and/or permitted to exist are public nuisances in violation of Jurupa Valley Municipal Code section 1.16.020.

As the owner of record, you are hereby notified to comply with the requirements of the above Codes, and to correct the conditions listed. All such work shall be completed within 30 days after receipt of this letter.

This notice will be posted on the property. If, in your opinion, you disagree or cannot comply with the above findings or Order, you may request an Appeal Hearing.

The request for an Appeal Hearing must be made within 30 days after posting of this notice on the property and must be in writing directed to the Jurupa Valley Chief Building Official, Building & Safety Department, 8930 Limonite Avenue, Jurupa Valley, California 92509. The request must be accompanied by a payment of $100.00 (One hundred dollars) hearing fee. If you prevail, the hearing fee will be returned to you.

Permits for repair, or demolition are required before starting the work and may be obtained at the City of Jurupa Valley Building & Safety office at 8930 Limonite Avenue, Jurupa Valley, California. Plans are required for corrective action. Submit plans to the Building & Safety Department. It IS necessary to bring this NOTICE with you when you apply for your permits. If you have any questions regarding this matter, please contact Benny Zimmermann at between 8:30 & 9:30 am, Monday through Friday.

Sincerely,

Benny Zimmermann
Code Enforcement Officer

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

NOTICE OF VIOLATION AND ORDER TO COMPLY

Occupant
3401 ETIWANDA AVE
JURUPA VALLEY, CA 91752-1128

APN: 156-150-069
Case No: CE-19-0573

Date: April 4, 2019

Re: 3401 ETIWANDA AVE

To OCCUPANT,

A recent inspection of your property at 3401 ETIWANDA AVE JURUPA VALLEY, CA 91752-1128 revealed that it contained conditions which violate the City of Jurupa Valley Municipal Code because of the following defects:

1. **Solid Waste Collection & Disposal-**No person shall collect, transfer or remove solid waste in the city without a valid permit or franchise issued by the city. - Jurupa Valley Municipal Code § 6.75.030
   Corrective Action Required: There are tenants on your property that are collecting, transferring, and/or removing waste in the city that are not properly using the franchisee contracted by the City. We have evidence that multiple sub tenants are using third party waste removal companies other than the City of Jurupa Valley's franchisee BURRTEC. Please notify your tenants that they have a responsibility to use the proper franchisee BURRTEC only for solid waste removal. Failure to comply will result in further administrative action.

Section 17920.3 of the California Health & Safety Code declares all such substandard buildings a public nuisance and requires the abatement thereof by repair, if practical, rehabilitation or by demolition. Conditions caused, maintained, and/or permitted to exist are public nuisances in violation of Jurupa Valley Municipal Code section 1.16.020.

As the owner of record, you are hereby notified to comply with the requirements of the above Codes, and to correct the conditions listed. All such work shall be completed within 30 days after receipt of this letter.

This notice will be posted on the property. If, in your opinion, you disagree or cannot comply with the above findings or Order, you may request an Appeal Hearing.

The request for an Appeal Hearing must be made within 30 days after posting of this notice on the property and must be in writing directed to the Jurupa Valley Chief Building Official, Building & Safety Department, 8930 Limonite Avenue, Jurupa Valley, California 92509. The request must be accompanied by a payment of $100.00 (One hundred dollars) hearing fee. If you prevail, the hearing fee will be returned to you.

Permits for repair, or demolition are required before starting the work and may be obtained at the City of Jurupa Valley Building & Safety office at 8930 Limonite Avenue, Jurupa Valley, California. Plans are required for corrective action. Submit plans to the Building & Safety Department. It IS necessary to bring this NOTICE with you when you apply for your permits. If you have any questions regarding this matter, please contact Benny Zimmermann at between 8:30 & 9:30 am, Monday through Friday.

Sincerely,

Benny Zimmermann
Code Enforcement Officer

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92505
951-332-6464

PLCK No:	Permit No: 2011-0432
Date:	Date: 10/21/11
Amount:	Amount: 187.64
Ck #:	Ck #:

Building Combination Permit

Permit # 2011-0432		Date	
Jobsite Address 3401 Etiwanda #			Space # 811D
City Mira Loma	State CA	Zip Code 91752	Assessors Parcel Number 156-150-063
Property Owner's Last Name, First Name Mira Loma Space Center			Phone Number
Permit Use: Meter Reset			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name:		First	
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ **OWNER BUILDER** __X__ **CONTRACTOR**

Contractor - Name Multer Electric		Type C1	License # 296043
Mailing Address 11098 Venture Dr "D"		City Mira Loma	State Ca / Zip Code 91752
Phone Number (951) 360 3424	Fax Number 951 360 3429	Email (optional)	

Architect or Engineer		Type	License#
Mailing Address	City		State / Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map #				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits				

Finaled: 10-24-2011

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92505
951-332-6464

PLCK No: 2012-0711	Permit No:
Date: 1/24/12	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

issued 2/15/12

Permit # 2012-0711 | Date 1-24-12

Jobsite Address 3401 ETIWANDA AVE BLDG. 1011 | Space # A, B & C

City MIRA LOMA | State CA | Zip Code 91752 | Assessors Parcel Number 156150063-9

Property Owner's Last Name, First Name SPACE CENTER | Phone Number 951-685-5221

Permit Use: OCCUPANCY PERMIT – Furniture Storage W/H

PP 3/18

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: BAUCOM | First DAVID

Mailing Address 8390 MAPLE PLACE #140 | City RANCHO CUCAMONGA | State CA | Zip Code 91730

Phone Number (909) 481-1950 x201 | Fax Number 909-481-1959 | Email (optional) DAVID@DBAAINC.COM

Check one: X **OWNER BUILDER** ____ **CONTRACTOR**

Contractor -Name | Type | License #

Mailing Address | City | State | Zip Code

Phone Number ( ) | Fax Number | Email (optional)

Architect or Engineer DBA ARCHITECTS INC. | Type | License# C 22017

Mailing Address 8390 MAPLE PL. #140 | City RANCHO CUCAMONGA | State CA | Zip Code 91730

Phone Number: (909) 481-1950 x201 | Fax Number 909-481-1959 | Email (optional) DAVID@DBAAINC.COM

FOR OFFICE USE ONLY

Planning Case # PP 9097 | Parcel/Tract Map # Docs - 16 Plans

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Plans - 3 Val - 15,000

Final: 02-17-2012

fire submittal

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3232
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3232			Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE			Space #
City Jurupa	State CA	Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER			Phone Number
Permit Use: Reroof Building 921 - Section A (Layover - No Tear off)			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING		First Ray	
Mailing Address	City	State	Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING	Type C-39	License # 475568	
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	
Architect or Engineer	Type	License#	
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000				(B) E P M
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3233
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3233	Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE	Space #
City JURUPA / State CA / Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER	Phone Number
Permit Use: Reroof Building 721 - Section A (Layover - No Tearoff)	

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING	First Ray		
Mailing Address	City	State	Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING	Type C-39	License # 475568	
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	
Architect or Engineer	Type	License#	
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000 (B) E P M				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2013-3234
Date:	Date: 10/22/13
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2013-3234			Date 10/22/13
Jobsite Address 3401 ETIWANDA AVE			Space #
City JURUPA	State CA	Zip Code	Assessors Parcel Number 156-150-069
Property Owner's Last Name, First Name SPACE CENTER			Phone Number
Permit Use: Reroof Building 911 - Section C & D (Layover - No Tearoff			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: HOWARD ROOFING		First Ray	
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Check one: ____ OWNER BUILDER ✓ CONTRACTOR

Contractor -Name HOWARD ROOFING		Type C-39	License # 475568
Mailing Address 245 N. MOUNTAIN VIEW AVE	City POMONA	State CA	Zip Code 91767
Phone Number (909) 622-5598	Fax Number 909 623 2927	Email (optional)	

Architect or Engineer		Type	License#
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val = 225,000 (B) E P M				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs - 2		Plans -		

Final: 12-19-2013

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2014-5250
Date:	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2014-5250 | Date

Jobsite Address: 3401 E Temescal Ave | Space # Bldg. 8 11

City: Jurupa | State: CA | Zip Code | Assessors Parcel Number

Property Owner's Last Name, First Name: Space Center Mira Loma Inc | Phone Number

Permit Use: Reroof Section A, B, C (layover)

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Evans | First: Ray

Mailing Address | City | State | Zip Code

Phone Number: (909) 973 1600 | Fax Number | Email (optional)

Check one: ____**OWNER BUILDER** ____**CONTRACTOR**

Contractor -Name: Howard's Roofing Company | Type: C-39 | License #: 475568

Mailing Address: 245 N. Mountain View Ave | City: Ontario | State: CA | Zip Code: 91762

Phone Number: (909) 622-5598 | Fax Number | Email (optional)

Architect or Engineer | Type | License#

Mailing Address | City | State | Zip Code

Phone Number: ( ) | Fax Number | Email (optional)

FOR OFFICE USE ONLY

Planning Case # Lot / Tract | Parcel/Tract Map # Val = B E P M

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs - Plans -

Final: 11-04-2014

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2014-5251
Date:	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit #	Date
Jobsite Address: 3401 E Rubidoux Blvd	Space # Bldg 921
City: Jurupa	State: CA / Zip Code / Assessors Parcel Number
Property Owner's Last Name, First Name: Space Center Mira Loma Inc	Phone Number
Permit Use: Reroof Section B (layover)	

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Evans	First: Ray
Mailing Address	City / State / Zip Code
Phone Number: (909) 973 1606	Fax Number / Email (optional)

Check one: ____ **OWNER BUILDER** ____ **CONTRACTOR**

Contractor -Name: Howard Roofing Company	Type: C-39	License #: 475560
Mailing Address: 245 N. Mountain View Ave	City: Pomona	State: CA / Zip Code: 91767
Phone Number: (909) 622-5598	Fax Number / Email (optional)	
Architect or Engineer	Type / License#	
Mailing Address	City / State / Zip Code	
Phone Number: ( )	Fax Number / Email (optional)	

FOR OFFICE USE ONLY

Planning Case # Lot / Tract	Parcel/Tract Map # Val =						
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits: Doc 5-		Plans-		

Final: 11-04-2014

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2014-5473	Permit No: 2014-5473
Date: 10/10/14	Date: 1/7/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2014-5473 — Issued Date 1/7/15

Jobsite Address: 3401 ETIWANDA BUILDING D SECTION 921 — Space #:

City: JURUPA VALLEY — State: CA — Zip Code: 91752 — Assessors Parcel Number: 156-150-069

Property Owner's Last Name, First Name: CRUIKSHANK TOM — Phone Number: 951-685-5221

Permit Use: NEW 3,000 AMP 2 SERVICE

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: LEE — First: WAYNE

Mailing Address: 12461 E. FRANCIS ST — City: ONTARIO — State: CA — Zip Code: 91761

Phone Number: (909) 923-0070 — Fax Number: 909-923-0858 — Email (optional): WAYNE@VALELECTRIC.COM

Check one: ____ **OWNER BUILDER** X **CONTRACTOR**

Contractor -Name: VAL ELECTRIC INC. — Type: C10 — License #: 576817

Mailing Address: 12461 E. FRANCIS — City: ONTARIO — State: CA — Zip Code: 91761

Phone Number: (909) 923-0070 — Fax Number: 923-0858 — Email (optional):

Architect or Engineer — Type — License#

Mailing Address — City — State — Zip Code

Phone Number: ( ) — Fax Number — Email (optional)

FOR OFFICE USE ONLY

Planning Case # Lot / Tract — Parcel/Tract Map # Val = BEPM

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs-2 Plans-1

Final: 02-18-2015

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2015-6817	Permit No: 2015-6817
Date:	Date: 5/22/15
Amount:	Amount:
Chk #:	Chk #:

Building Combination Permit

Permit # 2015-6817			Date Issued 5/22/15
Jobsite Address: 3401 Etiwanda Avenue			Space #: Building 1011, Sections C and D - 86,400 s.f.
City: Jurupa Valley	State: CA	Zip Code: 91752	Assessors Parcel Number: 156150069-5
Property Owner's Last Name, First Name: Space Center Mira Loma, Inc.			Phone Number: 951-685-5221
Permit Use: 86,400 square feet existing-Change of Tenancy and Pallet Racking Plans-3401 Etiwanda Ave., Bldg. 1011, Sections C & D			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL suupplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Hanes Companies, Inc. (New Tenant) MARTINEZ			First: JOHN
Mailing Address: ~~500 Mullin Creek Road~~ 565 PORTER WAY		City: ~~Grasmere~~ PLACENTIA	State: ~~ID~~ Zip Code: ~~2~~ 92870
Phone Number: ~~208-465-1078~~ 714.269.8693	Fax Number: ~~208-486-0723~~	Email (optional): JOHN@WAREHOUSEPERMITS.COM ~~pat.hollet@hanescompanies.com~~	

Check one: ○ OWNER BUILDER ◉ CONTRACTOR

Contractor - Name: RACK US UP	Type: C61/D24	License #: 863780		
Mailing Address: 8620 SORENSEN AVE #8		City: SANTA FE SPRINGS	State: CA	Zip Code: 90670
Phone Number: 526-713-1104	Fax Number:	Email (optional): RACKUSUP@YAHOO.COM		
Architect or Engineer: STRUCTURAL CONCEPTS ENG.	Type: CIVIL	License #: 69381		
Mailing Address: 1615 YEAGER AVE		City: LA VERNE	State: CA	Zip Code: 91750
Phone Number: 909.596.1350	Fax Number:	Email (optional): MAIL@SCEINC.NET		

FOR OFFICE USE ONLY

Planning Case #				Parcel/Tract Map #			
Legal Zone	SP/PA	Lot Size	FBS	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire - Y/N	Flood - Y/N	Thomas Guide		Assoc Permts			

Final: 08-14-2015

val - 60,000
Plans - 5
Docs - 31

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2015-8268
Date:	Date: 9/25/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2015-8268			Date 9-25-15
Jobsite Address 3401 E Etiwanda ave			Space #
City Mira loma	State CA	Zip Code 91752	Assessors Parcel Number
Property Owner's Last Name, First Name Allianz of America inc			Phone Number
Permit Use: Reroof Comml Bldg			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Marlowe		First William	
Mailing Address 525 new Jersey st	City Redlands	State CA	Zip Code 92373
Phone Number (909) 335 6300	Fax Number 909-335-6790	Email (optional)	

Check one: ____**OWNER BUILDER** ____**CONTRACTOR**

Contractor -Name clark Roofing Company		Type C39	License # 765388
Mailing Address 525 new Jersey st	City Redlands	State CA	Zip Code 92373
Phone Number (909) 335-6300	Fax Number 909 335 6790	Email (optional)	
Architect or Engineer		Type	License#
Mailing Address	City	State	Zip Code
Phone Number: ( )	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Planning Case # Lot / Tract			Parcel/Tract Map # Val = 524 K BEPM				
Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER
High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits Docs-		Plans-		

Final: 01-14-2016

CITY OF JURUPA VALLEY
8304 Limonite Avenue, Suite M
Jurupa Valley, California 92509
951-332-6464

PLCK No: 2012-1072	Permit No:
Date: 5/4/12	Date:
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2012-1072 — Date 05-03-12 — issued 6/22/12

Jobsite Address: 3401 Etiwanda Ave Bldg.1011			Space # A
City: Jurupa Valley	State: CA	Zip Code: 91752	Assessors Parcel Number: 156-140-10
Property Owner's Last Name, First Name: Space Center			Phone Number: 951-685-5221
Permit Use: Tenant Improvement – Restrooms			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Gomez		First: Junior	
Mailing Address: 8390 Maple Place #140		City: Rancho Cucamonga	State: CA / Zip Code: 91730
Phone Number: (909) 481-1920x205	Fax Number: 909-481-1952	Email (optional): Porfirio@dbaainc.com	

Check one: ____OWNER BUILDER ____CONTRACTOR

Contractor -Name		Type	License #
Mailing Address		City	State / Zip Code
Phone Number ( )	Fax Number	Email (optional)	

Architect or Engineer: DBA Architects INC.		Type	License#: C 22017
Mailing Address: 8390 Maple Place #140	City: Rancho Cucamonga	State: CA	Zip Code: 91730
Phone Number: (909) 481-1920x201	Fax Number: 909-481-1952	Email (optional): David@dbaainc.com	

FOR OFFICE USE ONLY

Planning Case #			Parcel/Tract Map # Val – 15,000 DEPM				
Legal Zone	SP/PA	Lot Size	FSB	Lf. SB	Rt. SB	R.SB...	SEPTIC/SEWER
High Fire – Y/N	Flood – Y/N	Thomas Guide	Assoc Permits Plans – 7 Docs –				

5.4 F

Final: 07-31-2012

1603.95

P
N

CITY OF JURUPA VALLEY
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

PLCK No:	Permit No: 2015-7600
Date:	Date: 7/9/15
Amount:	Amount:
Ck #:	Ck #:

Building Combination Permit

Permit # 2015-7600	Date 7-9-15

Jobsite Address: 3401 ETIWANDA AVE #1011 | Space #:

City: JURUPA VALLEY | State: CA | Zip Code: | Assessors Parcel Number:

Property Owner's Last Name, First Name: MIKE WAKSMUNSKI | Phone Number: 336-747-1678

Permit Use: SIGN PERMIT - Hanes Industries

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457.
Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: EMPERADO | First: RUDY

Mailing Address: 4774 MURRIETA ST. #1 | City: CHINO | State: CA | Zip Code: 91710

Phone Number: (909) 364-8135 | Fax Number: 909-364-8314 | Email (optional): rudyemp@AOL.com

Check one: ____ **OWNER BUILDER** __X__ **CONTRACTOR**

Contractor -Name: SIGNSPLUS | Type: C45 | License #: 812259

Mailing Address: 4774 MURRIETA ST #1 | City: CHINO | State: CA | Zip Code: 91710

Phone Number: (909) 364-8135 | Fax Number: 909-364-8374 | Email (optional): chinosignsplus@AOL.com

Architect or Engineer: | Type: | License#:

Mailing Address: | City: | State: | Zip Code:

Phone Number: ( ) | Fax Number: | Email (optional):

FOR OFFICE USE ONLY

Planning Case # Lot / Tract | Parcel/Tract Map # Val=1200 (B) E P M

Legal Zone	SP/PA	Lot Size	FSB	Lf SB	Rt SB	R SB	SEPTIC/SEWER

High Fire – Y/N	Flood– Y/N	Thomas Guide	Assoc Permits
			Docs- 5 Plans-

Final: 07-29-2015

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15893	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 811-A			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752

Permit Description:

Meter Release

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number / Fax Number	Email (optional)		
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number / Fax Number	Email (optional)		

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509
951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15894	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 811-B			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752

Permit Description:

Meter Release

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2018-15895	Date Submitted: 04/26/2018		Date Issued: 04/26/2018
Project Address: 3401 Etiwanda Ave 1011-B			Assessors Parcel Number: 156-150-069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Space Center Mira Loma Inc	First Name:		Phone Number: 951-685-5221
Property Owner's Address:	City: Jurupa Valley	State: CA	Zip Code: 91752
Permit Description: Meter Release			

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Space center Mira Loma Inc	First:		
Mailing Address: 3401 Etiwanda Ave	City: Jurupa Valley	State: CA	Zip Code: 91752
Phone Number: 951-685-5221	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name	License #	Classification	Business Registration #: Exp. Date
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	
Architect or Engineer	License #	Type	
Mailing Address	City	State	Zip Code
Phone Number	Fax Number	Email (optional)	

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 0.00	BEPM
Permit Tech Initials: DM		Docs: 6	Plans:

Final: 04-27-2018

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

CITY OF JURUPA VALLEY
Building Department

This form to be filled out by the City of Jurupa Valley Permit Technicians Only

Building Permit Application Form

Permit # 2019-19021	Date Submitted: 07/24/2019		Date Issued: 07/24/2019
Project Address: 3401 Etiwanda Ave			Assessors Parcel Number: 156150069
City: Jurupa Valley	State: CA	Zip Code: 91752	Owner's Email: (optional)
Property Owner's Last Name: Fullmer Construction	First Name:		Phone Number:
Property Owner's Address:	City:	State:	Zip Code:

Permit Description:

100 amp Temp Power pole, 1 sub distro 100 amp pole, 1 transformer. Construction Trailer. 30' High. No Encroachment Required.

APPLICANT INFORMATION

Note: As the applicant you will be financially responsible for ALL supplemental billings, fees and refunds for any and all permits per Ordinance 457. Any changes in applicant information must be made in writing by the original applicant to the Building Department.

Applicants Last Name: Same as Contractor	First:		
Mailing Address:	City:	State:	Zip Code:
Phone Number:	Fax Number:	Email (optional):	

Check one: ☐ **OWNER BUILDER** ☑ **CONTRACTOR**

Contractor - Name Temp Power Systems	License # 696713	Classification C-10	Business Registration #:	Exp. Date
Mailing Address 625 Fee Ana	City Placentia	State CA	Zip Code 92870	
Phone Number 714-767-0199	Fax Number	Email (optional)		
Architect or Engineer	License #	Type		
Mailing Address	City	State	Zip Code	
Phone Number	Fax Number	Email (optional)		

FOR OFFICE USE ONLY

Tract#	Lot#	Valuation: 4,000.00	BEPM
Permit Tech Initials: DM		Docs: 4	Plans: 2

Final: 07-31-2019

City of Jurupa Valley Building Department
8930 Limonite Avenue
Jurupa Valley, California 92509

951-332-6464

City of Jurupa Valley
Building & Safety Department
Building Permit Application

Permit No: B19-000836
Status: Closed - Final - 10/09/2020
Submittal Date: 11/07/2019
Issue Date: 04/29/2020

Project Address/Location: 3401 ETIWANDA AVE	**Assessor's Parcel Number: 156150069**

Description of Work: HIGH PILE STORAGE RACKS

Tract #:	Lot #:	Valuation: $58,000.00
Owner: C/O TRACY L PFAFF 3401 ETIWANDA AVE MIRA LOMA CA 91752	*Applicant: THE RACK DEPOT INC 10226 GREENLEAF AVE SANTA FE SPRINGS CA 90670 5627779809	Site Contact:
Contractor: THE RACK DEPOT INC 10226 GREENLEAF AVE SANTA FE SPRINGS CA 90670 5627779809 853858	Architect:	Engineer:

For inspection requests, please use our online service by going to www.JurupaValley.org. Select Online Inspection Requests. If you have difficulties scheduling your inspection, please call our inspection request line at (951) 332-0790.

"This permit expires in 365 days after the issuance of the permit if no substantial progress is verified by city staff"

Type of Project: Commercial	Code Year: 2016 CA

Constuction Type:	Occupancy Group:	Square Footage
Fire Sprinklers:	Use:	Occupant Load:

Building Department Fees Paid = 905.79
Balance Due = 0.00
*Note: The "Applicant" will be financially responsible for all supplemental billings, fees and refunds for this permit per Ordinance 457. Any changes to the "Applicant" information must be made in writing and submitted to the Building Department for approval.

APPLICANT'S ACCEPTANCE:

Applicant Signature **Date**

CITY APPROVAL:

for Keith Clarke, Chief Building Official

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

NOTICE OF VIOLATION AND ORDER TO COMPLY

BRE SPACE MIRA LOMA
222 S RIVERSIDE PLAZA STE 2000
CHICAGO, IL 60606

APN: 156-150-069
Case No: CE-20-2347

Date: September 21, 2020

Re: 3401 ETIWANDA AVE # 831 D

To BRE SPACE MIRA LOMA,

A recent inspection of your property at 3401 ETIWANDA AVE # 831 D JURUPA VALLEY, CA 91752 revealed that it contained conditions which violate the City of Jurupa Valley Municipal Code because of the following defects:

1. **Zone M-M** (Manufacturing-Medium)- Unpermitted Land Use - Jurupa Valley Municipal Code § 9.150.020
   Corrective Action Required: Illegal LAND Use, Pallet Storage not allow on this Zoning M-M. the only zoning allow is M-H (Manufacturing-Heavy) Zone with a Conditional Use Permit from Planning Department. Please remove all the PALLETS or Citations will start $ 200 $ 500 and $ 1000 everyday.
2. **Business Registration**. Every person conducting or carrying on a business as defined in this ordinance anywhere in the City of Jurupa Valley shall register by obtaining a business registration certificate. A separate business registration certificate shall be obtained for each physical location (including branch establishments) or for each business operated on a mobile basis by a mobile operator as defined herein. - Jurupa Valley Municipal Code § 5.05.030
   Corrective Action Required: Storage of Yard Pallets Not allow on this Zoning. Please remove all the PALLETS or Citations will start $ 200 $ 500 and $ 1000 everyday. Section. 9.240.530 Pallet Yards will give more information of the Ordinance.
3. **Building Violations: Permits Required**. No person, firm or corporation shall erect, re-erect, construct, enlarge, alter, repair, move, improve, remove, convert or demolish any building or other structure in the city, without obtaining a valid building permit prior to commencement of any work. - California Building Code 2019 § 105.1
   Corrective Action Required: Obtain all necessary permits from the Building Department and Planning Department. Permit are require to run a Pallets Business M-M Zoning are not allow to storage pallets, remove all the pallets or citations will start.

Section 17920.3 of the California Health & Safety Code declares all such substandard buildings a public nuisance and requires the abatement thereof by repair, if practical, rehabilitation or by demolition. Conditions caused, maintained, and/or permitted to exist are public nuisances in violation of Jurupa Valley Municipal Code section 1.16.020.

As the owner of record, you are hereby notified to comply with the requirements of the above Codes, and to correct the conditions listed. All such work shall be completed within 30 days after receipt of this letter.

This notice will be posted on the property. If, in your opinion, you disagree or cannot comply with the above findings or Order, you may request an Appeal Hearing.

The request for an Appeal Hearing must be made within 30 days after posting of this notice on the property and must be in writing directed to the Jurupa Valley Chief Building Official, Building & Safety Department, 8930 Limonite Avenue, Jurupa Valley, California 92509. The request must be accompanied by a payment of $100.00 (One hundred dollars) hearing fee. If you prevail, the hearing fee will be returned to you.

Permits for repair, or demolition are required before starting the work and may be obtained at the City of Jurupa Valley Building & Safety office at 8930 Limonite Avenue, Jurupa Valley, California. Plans are required for corrective action. Submit plans to the Building & Safety Department. It IS necessary to bring this NOTICE with you when you apply for your permits. If you have any questions regarding this matter, please contact Gilmar Tenes at (951) 332-6464 between 8:30 & 9:30 am, Monday through Friday.

Sincerely,

Gilmar Tenes
Code Enforcement Officer

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

NOTICE OF VIOLATION AND ORDER TO COMPLY

SMART DRAYAGE INC.
3401 ETIWANDA AVE # 831 D
JURUPA VALLEY, CA 91752

APN: 156-150-069
Case No: CE-20-2347

Date: September 21, 2020

Re: 3401 ETIWANDA AVE # 831 D

To SMART DRAYAGE INC.,

A recent inspection of your property at 3401 ETIWANDA AVE # 831 D JURUPA VALLEY, CA 91752 revealed that it contained conditions which violate the City of Jurupa Valley Municipal Code because of the following defects:

1. **Zone M-M** (Manufacturing-Medium)- Unpermitted Land Use - Jurupa Valley Municipal Code § 9.150.020
   Corrective Action Required: Illegal LAND Use, Pallet Storage not allow on this Zoning M-M. the only zoning allow is M-H (Manufacturing-Heavy) Zone with a Conditional Use Permit from Planning Department. Please remove all the PALLETS or Citations will start $ 200 $ 500 and $ 1000 everyday.
2. **Business Registration**. Every person conducting or carrying on a business as defined in this ordinance anywhere in the City of Jurupa Valley shall register by obtaining a business registration certificate. A separate business registration certificate shall be obtained for each physical location (including branch establishments) or for each business operated on a mobile basis by a mobile operator as defined herein. - Jurupa Valley Municipal Code § 5.05.030
   Corrective Action Required: Storage of Yard Pallets Not allow on this Zoning. Please remove all the PALLETS or Citations will start $ 200 $ 500 and $ 1000 everyday. Section. 9.240.530 Pallet Yards will give more information of the Ordinance.
3. **Building Violations: Permits Required**. No person, firm or corporation shall erect, re-erect, construct, enlarge, alter, repair, move, improve, remove, convert or demolish any building or other structure in the city, without obtaining a valid building permit prior to commencement of any work. - California Building Code 2019 § 105.1
   Corrective Action Required: Obtain all necessary permits from the Building Department and Planning Department. Permit are require to run a Pallets Business M-M Zoning are not allow to storage pallets, remove all the pallets or citations will start.

Section 17920.3 of the California Health & Safety Code declares all such substandard buildings a public nuisance and requires the abatement thereof by repair, if practical, rehabilitation or by demolition. Conditions caused, maintained, and/or permitted to exist are public nuisances in violation of Jurupa Valley Municipal Code section 1.16.020.

As the owner of record, you are hereby notified to comply with the requirements of the above Codes, and to correct the conditions listed. All such work shall be completed within 30 days after receipt of this letter.

This notice will be posted on the property. If, in your opinion, you disagree or cannot comply with the above findings or Order, you may request an Appeal Hearing.

The request for an Appeal Hearing must be made within 30 days after posting of this notice on the property and must be in writing directed to the Jurupa Valley Chief Building Official, Building & Safety Department, 8930 Limonite Avenue, Jurupa Valley, California 92509. The request must be accompanied by a payment of $100.00 (One hundred dollars) hearing fee. If you prevail, the hearing fee will be returned to you.

Permits for repair, or demolition are required before starting the work and may be obtained at the City of Jurupa Valley Building & Safety office at 8930 Limonite Avenue, Jurupa Valley, California. Plans are required for corrective action. Submit plans to the Building & Safety Department. It IS necessary to bring this NOTICE with you when you apply for your permits. If you have any questions regarding this matter, please contact Gilmar Tenes at (951) 332-6464 between 8:30 & 9:30 am, Monday through Friday.

Sincerely,

Gilmar Tenes
Code Enforcement Officer

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

SPACE CENTER MIRA LOMA INC
3401 ETIWANDA AVE # 503
MIRA LOMA, CA 91752-1128

APN: 156-150-069
Case No: CE-14-1011

Date: May 15, 2015

Re: 3401 ETIWANDA AVE # 50

To SPACE CENTER MIRA LOMA INC,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: **JUNE 8, 2015**

ABATEMENT MUST INCLUDE:

1. **REMOVAL OF ALL TUBMELWEEDS FROM THE PROPERTY AND ADJACENT PARKWAY AREAS.**
2. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
3. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
4. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8930 Limonite Street
Jurupa Valley, CA 92509

Our mailing address is:
8930 Limonite Street
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8930 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

Occupant
3401 ETIWANDA AVE # 50
JURUPA VALLEY, CA 91752-1128

APN: 156-150-069
Case No: CE-14-1011

Date: May 15, 2015

Re: 3401 ETIWANDA AVE # 50

To OCCUPANT,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: **JUNE 8, 2015**

ABATEMENT MUST INCLUDE:

1. **REMOVAL OF ALL TUBMELWEEDS FROM THE PROPERTY AND ADJACENT PARKWAY AREAS.**
2. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
3. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
4. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8930 Limonite Street
Jurupa Valley, CA 92509

Our mailing address is:
8930 Limonite Street
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

SPACE CENTER MIRA LOMA INC
3401 ETIWANDA AVE # 503
MIRA LOMA, CA 91752-1128

APN: 156-140-044
Case No: CE-14-1013

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To SPACE CENTER MIRA LOMA INC,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

Occupant

JURUPA VALLEY, CA 91752

APN: 156-140-044
Case No: CE-14-1013

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To OCCUPANT,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

SPACE CENTER MIRA LOMA INC
3401 ETIWANDA AVE # 503
MIRA LOMA, CA 91752-1128

APN: 156-140-042
Case No: CE-14-1011

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To SPACE CENTER MIRA LOMA INC,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

Occupant

JURUPA VALLEY, CA 91752

APN: 156-140-042
Case No: CE-14-1011

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To OCCUPANT,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

SPACE CENTER MIRA LOMA INC
3401 ETIWANDA AVE # 503
MIRA LOMA, CA 91752-1128

APN: 156-140-043
Case No: CE-14-1012

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To SPACE CENTER MIRA LOMA INC,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

City of Jurupa Valley

BUILDING AND SAFETY/CODE ENFORCEMENT DEPARTMENT, 8304 LIMONITE AVENUE, JURUPA VALLEY, CALIFORNIA 92509-5183 (951) 332-6464

HAZARD REDUCTION ABATEMENT NOTICE

Occupant

JURUPA VALLEY, CA 91752

APN: 156-140-043
Case No: CE-14-1012

Date: November 5, 2014

Re: NO ADDRESS ASSIGNED

To OCCUPANT,

As owner(s) shown on the last equalized assessment roll of the parcel identified above you are hereby given notice that all weeds, dry vegetation, rubble, junk, trash, debris, objects, discarded auto bodies, parts and other waste matter upon the premises is a public nuisance and must be abated (R.C.Per ord.#695). At this time you should make a full and complete inspection of your property and abate (remove) any of the above items by:

COMPLIANCE DATE: December 4, 2014

ABATEMENT MUST INCLUDE:

1. Handwork along perimeters: Removal of weeds/debris from parkway area and edge of street pavement to property; removal of concrete, junk, trash, asphalt, tires, etc. disking more than once :where soil has not adequately mixed with grass; disking twice where tumbleweeds exist.
2. Removal of tree limbs (branches) to provide a minimum of an 8' clearance from ground to branches.
3. Fire officials may require additional abatement work to maximize fire hazard reduction. You may be held liable for costs associated with any Fire Suppression Services that occur on your property which result from dry vegetation or other types of combustible material.

REGROWTH MAY BE SUBJECT TO REMOVAL WITHOUT FURTHER NOTICE:

It is your responsibility to maintain property in good condition at all times. Failure to abate such recurring conditions will result as stated above.

IMPOSED CITY COSTS. FINES AND RIGHTS:

If said items listed are not removed by the compliance date above, the City of Jurupa Valley may order an abatement without further notice and the cost of said abatement shall be assessed against the property as a **Special Tax Lien** . In addition, the City will also impose and assess an administrative fee for each parcel abated and any other recovery costs. If the violations have not been corrected, the City has the authority to issue an Administrative Citation against the property owner and/or parties maintaining the violation and/or commence administrative abatement action. Administrative citations carry a fine from $100.00 for the first occurrence up to $500.00 for the third occurrence of the same violation. Each day that the offense exists constitutes a separate offense.

APPEAL PROCESS

You may appeal to the Fire Marshall of the City of Jurupa Valley and show cause, if any, why the City should not abate the public nuisance. Such appeal shall be in writing and filed with the Fire Prevention Bureau within ten (10) days from the date of this Notice. The Fire Prevention Bureau is located at:

City Hall
8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Our mailing address is:

8304 Limonite Street, Suite M.
Jurupa Valley, CA 92509

Further questions concerning this notice can be directed to the Weed Abatement Hotline at: (951) 332-6464

STATE WATER RESOURCES CONTROL BOARD
HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR RIVERSIDE COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
SPACE CENTER MIRA LOMA, INC.
3401 ETIWANDA AVE, 503 MIRA LOMA CA 91752

II FACILITY

	MAILING ADDRESS TOWNSHIP/RANGE/SECTION	DEALER/FOREMAN/SUPERVISOR TELEPHONE	TYPE OF BUSINESS NO. OF CONTAINERS
CAMPBELL OIL COMPANY 3401 ETIWANDA AVE, 502 MIRA LOMA CA 91752	3010 11TH STREET RIVERSIDE CA 92507	SCOTTY CAMPBELL (714) 686-1676	GASOLINE STATION 2
CROSS STREET : HWY 60	T2 /R6 /S 5		

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: SPACE CENTER OFFICE (714) 685-5221 NIGHT: SCOTT SEC. GUARD (714) 685-5223

********** OWNER ASSIGNED CONTAINER NUMBER: 1 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 0000021548001 **********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG:
C. YEAR INSTALLED : 1947
D. CAPACITY (GALLONS) : 11,640
E. REPAIRS : UNKN IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: DIESEL

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS: B. VAULTING: NON-VAULTED C. WALLING: SINGLE
D. MATERIAL : STAINLESS STEEL
E. LINING : UNKNOWN
F. WRAPPING : UNKNOWN

VI PIPING
A. ABOVEGROUND PIPING : B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : UNKN IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
STOCK INVENTORY 0

COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
12034 DIESEL MOTOR VEHICLE FUEL

PAGE 3132 STATE WATER RESOURCES CONTROL BOARD 06/01/88

HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR RIVERSIDE COUNTY

CONTAINER TYPES: 1,2,3,4,5

(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

********** OWNER ASSIGNED CONTAINER NUMBER: 2 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 00000021548002 **********

IV DESCRIPTION
- A. CONTAINER TYPE : TANK
- B. MANUFACTURER/YR OF MFG: /
- C. YEAR INSTALLED : 1947
- D. CAPACITY (GALLONS) : 11,640
- E. REPAIRS : UNKN IF YES WHEN :
- F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
- G. STORES : PRODUCT
- H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: DIESEL

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
- A. THICKNESS:
- B. VAULTING: NON-VAULTED
- C. WALLING: SINGLE
- D. MATERIAL : STAINLESS STEEL
- E. LINING : UNKNOWN
- F. WRAPPING : UNKNOWN

VI PIPING
- A. ABOVEGROUND PIFING :
- B. UNDERGROUND PIPING : SUCTION
- C. REPAIRS : UNKN IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
STOCK INVENTORY 0

COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER

12034 DIESEL MOTOR VEHICLE FUEL

Well Finder

CalGEM GIS

- Well Status and Well Type Filter
- Search
- Zoom to Field
- Measurement
- Layers



- [x] Notice and Permit
- [x] Well
  - [x] Well
  - [x] Geothermal Well
- [x] Facility
  - [x] Tank
  - [x] Pit/Sump
  - [x] Setting
  - [x] Facility Boundary (non-wellstar)
- [x] Underground Gas Storage
- [x] Well Stimulation
- [x] TR26 Onshore Seep Count
- [x] Oil/Gas Field
  - [x] Oil/Gas Field Boundary
  - [x] Oil/Gas Field Interior

STATE WATER RESOURCES CONTROL BOARD
HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR RIVERSIDE COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
UNITED STATES AIR FORCE
22 CSG/DE MARCH AFB RIVERSIDE CA 92518

II FACILITY

FACILITY 7051
3041 ETIWANDA AVE
MIRA LOMA CA 92518

CROSS STREET :
ETIWANDA AVE

MAILING ADDRESS
TOWNSHIP/RANGE/SECTION
22 CSG/DE MARCH AFB
RIVERSIDE CA 92518

DEALER/FOREMAN/SUPERVISOR
TELEPHONE
(714) 655-4858

TYPE OF BUSINESS
NO. OF CONTAINERS
POWER GENERATOR
1

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: 24 HOUR SERVICE CALL DESK (714) 655-2976 NIGHT: ( ) -

********** OWNER ASSIGNED CONTAINER NUMBER: 7051-01 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 00000031132001 *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: UNKNOWN /
C. YEAR INSTALLED : UNK
D. CAPACITY (GALLONS) : 1,000
E. REPAIRS : UNKN IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: DIESEL

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS:
B. VAULTING: NON-VAULTED
C. WALLING: SINGLE
D. MATERIAL : CARBON STEEL
E. LINING : UNKNOWN
F. WRAPPING : UNKNOWN

VI PIPING
A. ABOVEGROUND PIPING :
B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : UNKN IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
VISUAL 0

COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
12034 DIESEL MOTOR VEHICLE FUEL

2019

WATER QUALITY REPORT

Jurupa Community Services District (JCSD) tests the quality of drinking water through an independent laboratory for the constituents required by state and federal regulations. This report shows the results of our monitoring for the period of January 1, 2019 – December 31, 2019. Last year, as in years past, your metered tap water met all U.S. Environmental Protection Agency (U.S. EPA) and State Drinking Water Health Standards.

This report contains important information about your drinking water. Translate it or speak with someone who understands it.

Este informe está disponible en español en línea en JCSD.us/WaterQualityReport

由于此报告书包含着有关饮用水的重要信 息,因此希望各位跟能够翻译或理解报告书 内容的人对话。

Báo cáo này chứa đựng thông tin quan trọng về nước uống của bạn. Hãy đọc hoặc nhờ người dịch cho quý vị.

Chi tiết này thật quan trọng. Xin nhờ người dịch cho quý vị.

Itong documento ay naglalaman nang mahalagang impormasyon tungkol sa tubig na maaring inumin. Maaring isalin sa taong nakakaintidi.

이 보고서는 당신의 식수와 관련된 중요한 정보 를 포함하고 있으니 번역하시거나 보고서의 내용 을 이해할 수 있는 분과 이야기 하시기 바랍니다.

jurupa
COMMUNITY SERVICES DISTRICT
Serving Jurupa Valley and Eastvale



Services: Water / Sewer / Streetlights / Frontage Maintenance / Graffiti Abatement / Parks & Recreation

01

MAINTAINING THE SAFETY OF OUR WATER, NOW AND INTO THE FUTURE

As the General Manager of Jurupa Community Services District (JCSD), I take pride in being part of the team that serves the community and continues the legacy of providing safe and reliable drinking water to our customers since 1966.

Our dedicated team of water professionals has demonstrated resilience and determination in the face of adversity during the current global COVID-19 crisis. Uninterrupted service was possible due to years of preparation and planning as well as our team's unwavering commitment to public service and the community. Through unprecedented times, JCSD's staff continued to reliably deliver water and wastewater services and will continue to do so into the future.



In alignment with the California State Water Resources Control Board Division of Drinking Water, we provide detailed information about the safety of your drinking water in our 2019 Annual Water Quality Report. We look forward to sharing this information on the water system and the water professionals who ensure that our customers receive highly treated and tested water every day. I encourage you to read this report to learn more about the District and your water supply.

Chris Berch
General Manager
Jurupa Community Services District

Exceptional Water Quality

JCSD is committed to proactively and transparently providing our customers with water that meets or exceeds all water quality standards.

From time to time, our customers may hear about contaminants in water that are affecting local, national and worldwide water quality, including recent stories on perfluoroalkyl and polyfluoroalkyl chemicals (known as PFAS).

We vigilantly test our water thousands of times per year and continuously monitor regulations to ensure our customers receive safe drinking water. Water quality information is available year-round on our website as well as this report.


About PFAS



Found in non-stick cookware, firefighting foam and stain resistant household coatings



PFAS is found in water; however, water agencies don't add these chemicals to water



PFAS enters our water supply as a result of manufacturing, landfills and wastewater discharge



JCSD meets all regulatory levels for PFAS

ABOUT JCSD.

1956 Founded

40.8 Square Mile Service Area

140,150 Customers

32,330 Service Connections

459 Miles of Water Lines

100% Groundwater from Local Wells

THE VALUE OF YOUR TAP WATER

Did you know that the tap water in your home costs less than one cent per gallon? In comparison to bottled water, which is less regulated and loosely monitored, tap water must meet rigorous scientific testing before it enters your home. Your tap water is an exceptional value, especially considering the amount of resources that it takes to pump, test and deliver this resource to your home. Here's a breakdown to explain your water bill:

Monthly Service Charge – This charge covers the majority of the costs to treat and deliver tap water to your home or business. These include maintaining, repairing and replacing water infrastructure, pumping and water quality testing.

Tiered Water Costs – JCSD's rate structure is a tiered system. This means that you pay more when you use more water. Water is billed in HCF or hundred cubic feet. Each HCF is 748 gallons.

Tier 1
1-12 HCF
(748-8,976 gallons)
Generally covers all inside uses including cooking, cleaning and personal use.
- Cheapest Water -

Tier 2
13-20 HCF
(9,724-14,960 gallons)
Generally for efficient outdoor use.

Tier 3
21-30 HCF
(15,708-22,440 gallons)
Generally used by residences with larger landscapes.

Tier 4
30+ HCF
(22,440 gallons or more)
Generally for large landscapes or inefficient water usage.

Sewer Base Charge – This charge covers the majority of the costs to safely remove and treat wastewater from your toilets, sinks, showers and washing machines. Dirty water is then delivered to one of two wastewater treatment plants where contaminants are removed and water is returned into the water cycle with minimum impact to the environment. This includes maintaining, repairing and replacing sewer infrastructure.

Sewer HCF Charge – This charge is based on water use and capped at 8 HCF. It directly relates to the average amount of wastewater generated from indoor uses.

Water Use Efficiency - Small changes can make a big difference. JCSD offers customers many resources to help achieve their water saving goals.

- Free Irrigation System Audit
- Rebates
- Turf Replacement Program
- YardScapes Program
- Flume Program
- Landscape Classes
- Water-saving tips

<$0.01

The cost of one gallon of tap water

03

RATEPAYER $ HARD AT WORK



Granite Hill Pipeline (GHP)

JCSD has benefitted from local groundwater aquifers to supply our water throughout the last 64 years. During that time, several things have changed in the region to impact our water supply including an increase in population, reoccurring droughts and new regulations.

JCSD staff has sought solutions to mitigate these and other changes. Two important components of water supply are reliability and redundancy. This means that multiple water sources or pipelines are available in the event that one or more become inoperative for any reason. On a regular basis, JCSD staff proposes, plans and budgets for projects to improve both reliability and redundancy. These projects can be found in the Water Master Plan and the 2020-2021 Annual Budget. Both documents are located on JCSD's website: www.JCSD.us

The GHP is a water infrastructure project that will meet JCSD's goals of cost efficiency, improved reliability, and redundancy. Currently in the planning and design phase, the project will allow more efficient delivery of water between two pressure zones. This will save a significant amount of energy associated with reduced pump operations. Additionally, the pipeline may be used to convey water between regional partners at a later date. The GHP will be constructed in two phases and the first phase of the work is scheduled to be completed by 2022.

Projects of this scope and scale require a significant amount of time and planning but they are the cornerstone of water supply reliability. It is one more way to ensure safe and reliable drinking water, now and in the future.

INFORMATION ABOUT YOUR WATER

Jurupa Community Services District (JCSD) tests the quality of drinking water through an independent laboratory for many constituents as required by State and Federal Regulations.

This report shows the results of our monitoring for the period of January 1, 2019 - December 31, 2019.

Last year, as in years past, your metered tap water met all U.S. Environmental Protection Agency (USEPA) and State Drinking Water Health Standards.

Este informe contiene información muy importante sobre su agua de beber. Tradúzcalo ó hable con alguien que lo entienda bien.

All water delivered in 2019 was produced from wells.

- JCSD wells are located near Interstate 15 and Highway 60
- Chino I Desalter wells are located in Chino near Chino Airport
- Roger D. Teagarden Ion Exchange Treatment Plant is located near Interstate 15 and Highway 60
- Wells 17/18 Ion Exchange Treatment Facility is located near Interstate 15 and Highway 60
- Chino II Desalter wells are located near Interstate 15 and Bellegrave Ave.

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activity.

In order to ensure that tap water is safe to drink, the U.S. Environmental Protection Agency (USEPA) and the State Water Resources Control Board (State Board) Division of Drinking Water prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. State Board regulations also establish limits for contaminants in bottled water that provide the same protection for public health.

Tables 1, 2, 3, 4, 5 and 6 list all of the drinking water contaminants that were detected during the most recent sampling for the constituent. The presence of these contaminants in the water does not necessarily indicate that the water poses a health risk. The State Board requires all water systems to monitor for certain contaminants less than once per year because the concentrations of these contaminants are not expected to vary significantly from year to year.

Terms Used In This Report:

Maximum Contaminant Level (MCL): The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

Maximum Contaminant Level Goal (MCLG): The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the U.S. Environmental Protection Agency (USEPA).

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

Notification Level (NL): The level is a non-regulatory, health-based advisory level established for contaminants in drinking water for which maximum contaminant level has not been established.

Primary Drinking Water Standard (PDWS): MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements and water treatment requirements.

Public Health Goal (PHG): The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency.

Regulatory Action Level (AL): The concentration of a contaminant, which, if exceeded, triggers treatment or other requirements that a water system must follow.

Secondary Drinking Water Standards (SDWS): MCLs for contaminants that affect taste, odor, or appearance of the drinking water. Contaminants with SDWS do not affect health at the MCL levels.

Treatment Technique (TT): A required process intended to reduce the level of a contaminant in a drinking water.

Additional General Information On Drinking Water:

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the USEPA Safe Drinking Water Hotline (1-800-426-4791).

Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. USEPA Centers for Disease Control (CDC) guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Nitrate (as N) in drinking water at levels above 10 mg/L is a health risk for infants of less than six months of age. Such nitrate levels in drinking water can interfere with the capacity of the infant's blood to carry oxygen, resulting in serious illness; symptoms include shortness of breath and blueness of the skin (methemoglobinemia or Blue-Baby Syndrome). Nitrate (as N) levels above 10 mg/L may also affect the ability of the blood to carry oxygen in other individuals, such as pregnant women and those with certain specific enzyme deficiencies. If you are caring for an infant or you are pregnant, you should ask advice from your health care provider.

If lead in drinking water is present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. JCSD is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or online at www.epa.gov/lead.

Fluoride is a naturally occurring compound. JCSD does not add fluoride to its water supply.

Abbreviations

mg/L — milligrams per liter = parts per million (ppm) (1 ppm is equivalent to 1 second in 11.5 days)

NTU — Nephelometric Turbidity Units

pCi/L — pico Curies per liter (a measure of radiation)

NA — Not Applicable

µg/L — micrograms per liter = parts per billion (ppb)

ND — Not Detectable at testing limit

ng/L — nanograms per liter = parts per trillion (ppt)

µS/cm — microsiemens per centimeter, a unit of conductance (1 µS/cm = 1 µmho/cm)

State Water Resources Control Board (State Board) Division of Drinking Water Fluoridation website link:
https://www.waterboards.ca.gov/drinking_water/certlic/drinkingwater/Fluoridation

USEPA Web site link: www.epa.gov/ccr/how-water-systems-comply-ccr-requirements

Contaminants that may be present in source water include:

Microbial contaminants, such as viruses and bacteria that may come from sewage treatment plants, septic systems, agricultural livestock operations and wildlife.

Inorganic contaminants, such as salts and metals that can be naturally occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining or farming.

Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban storm water runoff and residential uses.

Organic chemical contaminants, including synthetic and volatile organic chemicals that are byproducts of industrial processes and petroleum production and can also come from gas stations, urban storm-water runoff, agricultural application and septic systems.

Radioactive contaminants, that can be naturally occurring or be the result of oil and gas production and mining activities.

Primary Drinking Water Standards

Table 1 - Sampling Results Showing Detection of Coliform Bacteria

Microbiological Constituents	[1] 1110 Zone (Chino II)		[1] 980 Zone (JCSD)		[1] 870 Zor
	Highest % of Monthly Positives	No. of Months in Violation	Highest % of Monthly Positives	No. of Months in Violation	Highest % of Monthly Positives
Total Coliform Bacteria (State Total Coliform Rule)	0	0	0	0	0
Fecal Coliform or E. coli (State Total Coliform Rule)	0	0	0	0	0

Table 2 - Sampling Results Showing Detection of Lead and Copper

Lead and Copper	Reporting Unit	No. of Samples	90th % Level Detected	No. of Samples	90th % Level Detected	No. of Samples (Collected in 2019)
Lead (Pb)	µg/L	NA	NA	NA	NA	55
Copper (Cu)	mg/L	NA	NA	NA	NA	55

Table 3 - Sampling Results Showing Detection of Primary Constituents

Constituents	Reporting Unit	Average Level Detected	Range of Detection	Average Level Detected	Range of Detection	Average Level Detected
Chromium (Total Cr)	µg/L	ND	ND - 4.2	3.9	3.7 - 4.1	3.4
Fluoride (F)	mg/L	ND	ND - 0.16	0.13	0.12 - 0.13	0.12
Nitrate (as N)	mg/L	4.8	3.3 - 5.7	6.9	3.2 - 8.8	5.5
Gross Alpha Particle Activity	pCi/L	ND	ND	[2] ND	[2] ND - 3.23	ND
Uranium	pCi/L	ND	ND	1.25	1.25	NA
Total THM's (Trihalomethanes)	µg/L	ND	ND	ND	ND	8.9
Chlorine	mg/L	1.44	1.05 - 1.79	1.43	0.71 - 1.77	1.31

Secondary Drinking Water Standards

Table 4 - Sampling Results Showing Detection of Secondary Constituents

Water Standards	Reporting Unit	Average Level Detected	Range of Detection	Average Level Detected	Range of Detection	Average Level Detected
Chloride (Cl)	mg/L	78	12 - 82	68	58 - 77	86
Specific Conductance (E.C.)	µmho/cm	602	350 - 720	555	530 - 580	597
Sulfate (SO4)	mg/L	11	10 - 13	23	21 - 24	21
Total Dissolved Solids (TDS)	mg/L	434	220 - 500	490	480 - 500	502
Turbidity	NTU	ND	ND - 0.40	ND	ND - 0.11	ND
Foaming Agents (MBAS)	µg/L	ND	ND	ND	ND	ND

Unregulated Constituents

Table 5 - Sampling Results Showing Detection of Unregulated Constituents

Constituents	Reporting Unit	Average Level Detected	Range of Detection	Average Level Detected	Range of Detection	Average Level Detected
Hexavalent Chromium	µg/L	2.3	0.66 - 4.2	3.5	3.1 - 3.9	3.2
Calcium (Ca)	mg/L	56	42 - 57	69	67 - 71	84
Magnesium (Mg)	mg/L	8.8	5.6 - 9.0	7.9	7.3 - 8.4	6.7
Potassium (K)	mg/L	1.6	1.5 - 2.0	2.4	2.3 - 2.5	2.4
pH	pH Units	8.0	7.9 - 8.1	8.0	8.0	8.0
Total Alkalinity	mg/L	112	100 - 140	140	140	142
Total Silica	mg/L	15	12 - 16	24	23 - 24	21
Sodium (Na)	mg/L	28	25 - 28	29	26 - 31	27
Total Hardness (CaCO3)	mg/L	177	130 - 180	205	200 - 210	239

Table 6 - Sampling Results Showing Detection of Constituents with Notification Level

Constituents	Reporting Unit	Average Level Detected	Range of Detection	Average Level Detected	Range of Detection	Average Level Detected
N-Nitrosodimethylamine (NDMA)	ng/L	ND	ND	NA	NA	ND
(1) Perfluorooctanoic Acid (PFOA)	ng/L	ND	ND	[3] 6.1	[3] ND - 12	[3] 3.1
(1) Perfluorooctanesulfonic Acid (PFOS)	ng/L	ND	ND	[3] ND	[3] ND	[3] 47

Footnotes:

(1) NOTE: All water quality data reported in 2019 CCR table were taken from treated water sample locations with the exemption of PFAS data from 870 Zone (JCSD).
(2) NOTE: For 980 Zone (JCSD), the data for gross alpha from 980 blend points A and B were taken in 2015.
(3) NOTE: There is currently not an MCL or sampling requirements for JCSD regarding PFAS chemicals. JCSD sampled PFAS chemicals independently and went above and beyond any requirements. Any source of water that exceeded the Notification Level (NL) has been put on emergency stand-by and would only be used in time of emergencies. All sources above the Response Level (RL) have been removed from the system and will not be used until treatment is in place.
(4) NOTE: The July 2018 notification levels for PFOA of 14 ng/L and for PFOS of 13 ng/L were superseded on August 22, 2019, with new notification levels 5.1 ng/L for PFOA and 6.5 ng/L for PFOS.

JCSD uses Sodium Hypochlorite (Chlorine) for disinfection. JCSD does not use Chloramines.

ne (JCSD)	[1] 870 Zone (Chino I)		Drinking Water Standard Information		
No. of Months in Violation	Highest % of Monthly Positives	No. of Months in Violation	MCL	PHG (MCLG)	Typical Source of Bacteria
0	0	0	5% of monthly samples are positive	(0)	Naturally present in the environment
0	0	0	A routine sample and a repeat sample are total coliform positive, and one of these is also fecal coliform or E coli positive.	(0)	Human and animal fecal waste

90th % Level Detected	No. of Samples	90th % Level Detected	Number of Sites Exceeding (AL)	Action Level (AL)	PHG (MCLG)	Typical Source of Contamination
ND	NA	NA	0	15	0.2	Internal corrosion of household plumbing systems; discharges from industrial manufacturers: erosion of natural deposits
0.10	NA	NA	0	1.3	0.3	Internal corrosion of household plumbing systems; erosion of natural deposits; leaching from wood preservatives

Range of Detection	Average Level Detected	Range of Detection	MCL [MRDL]	PHG (MCLG) [MRDLG]	Major Sources in Drinking Water
2.0 - 5.1	ND	ND	50	(100)	Discharge from steel and pulp mills and chrome plating; erosion of natural deposits
0.10 - 0.14	ND	ND	2.0	1	Erosion of natural deposits; water additive which promotes strong teeth; discharge from fertilizer & aluminum factories
2.9 - 8.0	4.0	2.0 - 6.0	10	10	Runoff and leaching from fertilizer use; leaching from septic tanks and sewage; erosion of natural deposits
ND	ND	ND	15	(0)	Erosion of natural deposits
NA	ND	ND	20	0.43	Erosion of natural deposits
5.2 - 12.5	ND	ND	80	NA	By-product of drinking water disinfection
0.57 - 1.74	0.98	0.64 - 1.66	[4.0 (as Cl2)]	[4 (as Cl2)]	Drinking water disinfectant added for treatment

Range of Detection	Average Level Detected	Range of Detection	MCL [MRDL]	PHG (MCLG)	Major Sources in Drinking Water
23 - 160	109	98 - 120	500	NA	Runoff, leaching from natural deposits; seawater influence
440 - 790	610	500 - 720	1600	NA	Substances that form ions when in water; seawater influence
16 - 25	3.2	0.52 - 5.8	500	NA	Runoff, leaching from natural deposits; industrial wastes
280 - 790	470	340 - 600	1000	NA	Runoff, leaching
ND - 0.26	0.15	0.12 - 0.18	5	NA	Soil runoff
ND - 90	ND	ND	500	NA	Leaching from natural deposits

Range of Detection	Average Level Detected	Range of Detection	MCL [MRDL]	PHG (MCLG)	Major Sources in Drinking Water
1.7 - 5.0	ND	ND	NA	0.02	Discharge from electroplating factories, leather tanneries, wood preservation, chemical synthesis, refractory production, and textile manufacturing facilities; erosion of natural deposits
62 - 110	55	48 - 62	NA	NA	One of the elements that make up the earths crust's as components of many rock-forming minerals
6.2 - 12	12.5	11.0 - 14.0	NA	NA	One of the elements that make up the earths crust's as components of many rock-forming minerals
1.9 - 2.9	1.4	1.1 - 1.6	NA	NA	One of the elements that make up the earths crust's as components of many rock-forming minerals
8.0	8.0	7.9 - 8.0	NA	NA	Erosion of natural deposits
130 - 160	97	94 - 100	NA	NA	Leaching out from rocks and natural deposits
16 -25	11	11	NA	NA	NA
19 - 35	28	27 - 28	NA	NA	Generally found in ground and surface water
180 - 310	190	170 - 210	NA	NA	Generally found in ground and surface water

Range of Detection	Average Level Detected	Range of Detection	Notification Level	PHG (MCLG)	Health Effects
ND	4.0	4.0	10	3	NDMA and other Nitrosamines can cause cancer in laboratory animals. The NTP identifies a number of them as reasonably anticipated to be human carcinogens (NTP,201) and US EPA classifies a number of them as probable human carcinogens.
[3] ND - 6.9	ND	ND	[4] 5.1	NA	Perfluorooctanoic acid exposures resulted in increased liver weight in laboratory animals.
[3] ND - 200	ND	ND	[4] 6.5	NA	Perfluorooctanesulfonic acid exposures resulted in immune suppression, specifically, a decrease in antibody response to an exogenous antigen challenge.

An assessment of the drinking water sources for Jurupa Community Services District was completed in July 2017. The sources are considered most vulnerable to the following activities not associated with contaminants detected in the water supply: Known Contaminant Plumes, Plastics/Synthetics Producers, Junk/Scrap/Salvage Yards, Metal plating/finishing/fabricating, Fleet/truck/bus terminals, and Gas Stations. A copy of the complete assessment is available at 11201 Harrel Street. You may request a summary of the assessment to be sent to you by contacting the Water Quality Department at: (951) 685-7434 Ext. 104. Total of 9 schools from Corona-Norco Unified School District have requested to conduct lead sampling and the results can be found at **www.waterboards.ca.gov/drinking_water/certlic/drinkingwater/leadsamplinginschools.html** and total of 15 schools from Jurupa Unified School District were sampled by an independent group and the results can be found at their own website at **www.jurupausd.org/our-district/planning/mo/Pages/AB-746-Potable-Water-Systems—Lead-Testing.aspx**

Find us on Social Media:

@JCSDISTRICT

@JCSDISTRICT

@JCSDISTRICT

@JCSDVIDEOS

jurupa
COMMUNITY SERVICES DISTRICT
Serving Jurupa Valley and Eastvale

11201 Harrel Street
Jurupa Valley, CA 91752

Information About Your Drinking Water

For more information about this report, please contact the Water Quality Department at JCSD at (951) 685-7434 Ext. 104 or visit JCSD.us/WaterQualityReport. JCSD holds regular Board of Directors meetings on the second and fourth Monday of each month at 6 p.m. at the District Office, 11201 Harrel Street, Jurupa Valley.

Board of Directors

President Richard "Dickie" Simmons
Division No. 4

Vice President Betty Folsom
Division No. 3

Director Kenneth J. McLaughlin
Division No. 1

Director Betty A. Anderson
Division No. 2

Director Jane F. Anderson
Division No. 5



VAPOR ENCROACHMENT SCREENING DOCUMENTATION

VAPOR SCREENING

Project Property:	*Space Center* *3401 Etiwanda Ave - Bldg 1011* *Jurupa Valley CA*
Project No:	*00662058*
Report Type:	*Vapor Report with Database Details*
Order No:	*21032900155v*
Requested by:	*Intertek PSI*
Date Completed:	*April 9, 2021*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Map.....6
Detail Report.....8
Appendix: Database Descriptions.....33

Notice: IMPORTANT INFORMATION:

Service: Client has used a service offered by ERIS Information Inc. ("**ERIS**") to generate this report based upon certain search parameters set by Client, or in the case of ERIS's Vapor Encroachment Screening Tool and Checklist, certain search parameters set by ERIS and modified by Client (the "**Service**"). This report contains the results of a search conducted by ERIS of environmental records maintained by third parties. ERIS does not maintain, and has no responsibility for the accuracy or completeness of, such records.

Agreement: Client's use of the Service and any report generated thereby is subject to the Master Services Agreement previously entered into by Client and ERIS, or the terms and conditions accepted by Client in electronically submitting a request for the Service, (the "**Agreement**") and no provision of this Notice shall modify the Agreement. To the extent there is a conflict between any provision of this Notice and any provision of the Agreement, the latter shall control.

Liability Limitation: ERIS's liability for the Service and this report shall be limited to the amount paid by Client for this report and as otherwise set forth in the Agreement. Although in preparing this report ERIS has endeavored to present information that is accurate, ERIS will not have any liability for any errors, omissions or inaccuracies in such information, even if ERIS sets, or Client modifies, the parameters used to conduct the search.

Reliance on Report: This report (1) applies only to the address and the date specified on the cover page of this report and (2) is not a substitute for a Phase I Environmental Site Assessment, a Vapor Encroachment Assessment or any other similar assessment. It is solely intended to be used as a database search of current environmental records maintained by third parties, and Client should not rely on this report for any purpose for which it is not intended. Client may, in Client's discretion, modify search parameters within some of the tools of the Service that may affect the results for which ERIS is not responsible.

License for Use of Report: Client is licensed to use this report solely for its intended purpose as set forth in this Notice and the Agreement. No page of this report may be used by Client without including this report's cover page, this Notice and the project property identifier.

Client Liability: Use of the Service or this report in a manner contrary to this Notice or the Agreement will be a breach of contract and an infringement of ERIS's copyright and other intellectual property rights, for which ERIS will be entitled to damages and other remedies. In addition, upon any such breach or infringement, ERIS may terminate the Agreement, Client's account with ERIS, Client's license to use any reports previously generated for Client pursuant to the Service, and Client's future use of the Service.

Warranty Disclaimer: **EXCEPT AS EXPRESSLY SET FORTH IN THE AGREEMENT, ERIS MAKES NO WARRANTY OR REPRESENTATION REGARDING THE SERVICE, THIS REPORT OR THE RESULTS OF ANY SEARCH CONDUCTED BY CLIENT USING THE SERVICE.**

Ownership: Client may not use any of ERIS's trademarks or attribute any work product to ERIS other than as expressly set forth in this Notice or the Agreement. The Service and this reports are owned by ERIS (or its licensors) and protected by copyright and other intellectual property rights. No portion of this report may be, in whole or in part, modified, reproduced or transferred to a third party by Client, without the prior written consent of ERIS.

Executive Summary

This Report was produced through the ERIS Vapor Screening Tool. The ERIS Vapor Screening Tool and this report output are designed to help those in conducting a Vapor Encroachment Screening on a Property Involved in Real Estate Transactions under the ASTM Standard Designation E2600 – 15.

The following table lists the data sources searched and any hits in the Area of Concern (AOC) that have been included in the report. The search distances listed are based on search distances used in the Database Report and the search results are grouped based on the minimum default search distances for Chemicals of Concern (COCs) and Petroleum Hydrocarbon Chemicals of Concern (PHCOCs) as outlined in E2600-15. The default AOC may be expanded or reduced by the environmental professional (adjusted AOC) using experience and professional judgment.

Standard Environmental Sources	***Search Distance (miles)****	***Project Property***	***Within 1/10***	***1/10 plus***	***Total***
Federal NPL site list	1.0	0	0	0	0
Federal Delisted NPL site list	0.5	0	0	0	0
Federal CERCLIS list	1.0	0	0	0	0
Federal CERCLIS NFRAP site list	0.5	0	0	0	0
Federal RCRA CORRACTS facilities list	1.0	0	0	0	0
Federal RCRA non-CORRACTS TSD facilities list	0.5	1	0	0	1
Federal RCRA generators list	0.125	8	2	0	10
Federal institutional control/engineering control registries	0.5	0	0	0	0
Federal ERNS list	PO	0	0	0	0
State and tribal equivalent NPL	1.0	0	0	0	0
State and tribal equivalent CERCLIS	1.0	1	1	0	2
State and tribal landfill and/or solid waste disposal site lists	0.5	0	0	0	0
State and tribal leaking storage tank lists	0.5	3	1	0	4
State and Tribal registered storage tank lists	0.25	3	0	0	3
State and tribal institutional control/engineering control registries	PO	0	0	0	0
State and tribal voluntary cleanup sites	0.5	0	0	0	0
State Hazardous Waste Facilities	1.0	1	0	0	1
Others	0.5	0	0	0	0
Non Standard Environmental Sources					
Federal Spill sites list	0.125	0	0	0	0
Federal Drycleaner Facilities	0.5	0	0	0	0
State and tribal leaking storage tank lists	0.5	0	0	0	0
State Hazardous Waste Facilities	0.5	4	4	0	8
State and Tribal Spill sites list	PO	1	0	0	1
State and Tribal Dry Cleaner Facilities	0.25	0	0	0	0
Others	1.0	67	7	0	74
Federal PFAS sites list	0.5	0	0	0	0
State and Tribal PFAS site list	0.5	0	0	0	0

** Please refer to the Appendix of this report to view specific databases searched within each category. Search distances within each category may vary by database - the largest search radius per category will be displayed.*

Executive Summary: Report Summary

Project Property:	Space Center 3401 Etiwanda Ave - Bldg 1011 Jurupa Valley CA	**PO No:**	00662058
		Order No:	21032900155v
Coordinates:	34.02592934, -117.53327404	**Elevation:**	817.4 ft

Project Property - Results


Map Key	DB	Company/Site Name	Address	Direction	Distance (m/ft)	Elev Diff (ft)	Page Number

No records for the project property.

Surrounding Properties - Results

Map Key	DB	Company/Site Name	Address	Direction	Distance (m/ft)	Elev Diff (ft)	Page Number
3	RIVERSIDE HZH	K-Swiss Sport Shoes Inc.	3177 Space Ctr Jurupa Valley CA 91752	ENE	24.99 / 81.99	10.0	8
3	CERS HAZ	K-Swiss Sport Shoes Inc.	3177 SPACE CTR JURUPA VALLEY CA 91752	ENE	24.99 / 81.99	10.0	8
4	CERS HAZ	Gerard Daniel Worldwide Mira Loma	3265 PROGRESS CIR MIRA LOMA CA 91752	ENE	27.18 / 89.16	9.0	13
4	RIVERSIDE HZH	Gerard Daniel Worldwide	3265 Progress Cir Jurupa Valley CA 91752	ENE	27.18 / 89.16	9.0	13
5	DELISTED COUNTY	Adam Nutrition	11010 Hopkins St #B Jurupa Valley CA 91752	E	31.23 / 102.47	3.0	16
5	RIVERSIDE HWG	International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	31.23 / 102.47	3.0	16
5	RIVERSIDE HZH	International Vitamin Corporation (IVC)	11010 Hopkins St Ste B Jurupa Valley CA 91752	E	31.23 / 102.47	3.0	16
5	CERS HAZ	International Vitamin Corporation	11010 HOPKINS ST #B MIRA LOMA CA 91752	E	31.23 / 102.47	3.0	16
5	RCRA NON GEN	INTERNATIONAL VITAMIN CORP	11010 HOPKINS ST MIRA LOMA CA 91752	E	31.23 / 102.47	3.0	16

Map Key	DB	Company/Site Name	Address	Direction	Distance (m/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: CAL000401988				
9	RIVERSIDE HZH	Home Depot Distribution IDC #5645	11650 Venture Dr Jurupa Valley CA 91752	N	44.33 / 145.45	8.0	24
9	RIVERSIDE HWG	The Home Depot Store #5645	11650 Venture Dr Jurupa Valley CA 91752	N	44.33 / 145.45	8.0	24
9	ENVIROSTOR	MILLIKEN SANITARY LANDFILL	INTERSECTION: MILLIKEN AVE & MISSION BLV ONTARIO CA 91761	N	44.33 / 145.45	8.0	24
			Estor/EPA ID | Cleanup Status: 36490106 | REFER: RWQCB AS OF 6/1/1995				
9	CERS HAZ	The Home Depot Store #5645	11650 VENTURE DR MIRA LOMA CA 91752	N	44.33 / 145.45	8.0	24
9	RCRA SQG	HOME DEPOT USA INC HD 5645	11650 VENTURE DRIVE MIRA LOMA CA 91761	N	44.33 / 145.45	8.0	24
			EPA Handler ID: CAR000168153				
9	FUDS	MARCH COMMUNICATION ANNEX #2	SAN BERNARDINO/RIVERSIDE COUNTY LINES CA	N	44.33 / 145.45	8.0	24




Address: 3401 Etiwanda Ave - Bldg 1011,Jurupa Valley,CA

Order No: 21032900155v

- Sites with Lower Elevation
- Sites with Same Elevation
- Sites with Higher Elevation
- Up-gradient
- Down-gradient
- Cross-gradients
- Leaking Tank site

© ERIS Information Inc.



Address: 3401 Etiwanda Ave - Bldg 1011,Jurupa Valley,CA

Order No: 21032900155v

- Sites with Lower Elevation
- Leaking Tank site
- Sites with Same Elevation
- Sites with Higher Elevation

© ERIS Information Inc.

Detail Report

Map Key	Company/Site Name	Address	Distance (m/ft)	Elev Diff (ft)
3	K-Swiss Sport Shoes Inc.	3177 SPACE CTR 3177 Space Ctr	24.99 / 81.99	10.0

ASTM Category: State Hazardous Waste Facilities
Others

Vapor Encroachment Details

Impact on Target Property: VEC does not exist
Conditions: Non-Petroleum Chemicals of Concern (NPCOC)
Groundwater Flow Gradient: Up-Gradient
Flow is based on the following:
Preferential Pathway:
Geological Attributes - Hydraulic Barrier:
Geological Attributes - Physical Barrier: Low-permeability soil
Geological Attributes - Soil Geology: Low-permeability soil
Comments:

The standard environmental record sources are reviewed and identified that there are not known or suspected sources of COC-contamination within the established area of concern (AOC). (ASTM E2600 8.3.1)

RIVERSIDE HZH ***K-Swiss Sport Shoes Inc.*** ***3177 Space Ctr Jurupa Valley 91752*** ***Others***

ï¿½

CERS HAZ ***K-Swiss Sport Shoes Inc.*** ***3177 SPACE CTR JURUPA VALLEY 91752*** ***State Hazardous Waste Facilities***

Site ID: 40908
Latitude: 34.027060
Longitude: -117.527110
County:
ï¿½

Regulated Programs
ï¿½
EI ID: 10321045 ***EI Description:*** Chemical Storage Facilities
ï¿½

Violations
ï¿½
Violation Date: 09/09/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 09/12/2016.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 11/28/2017
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 12/14/2017. 3-7-18: CERS was updated 12-14-17.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 09/09/2016
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/26/2014
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 104D] Emergency equipment has been posted appropriately.

Violation Description:

Business Plan Program - Operations/Maintenance - General

Violations

Violation Date: 08/26/2014
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 101C] Approved HMBP accessible on site and available for review.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 09/12/2016. [LOCAL ORDINANCE VIOLATION 104A] NFPA 704 sign(s) have been posted appropriately.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 06/17/2016 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/17/2017.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/26/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/12/2016.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Enforcements

Enf Action Date: 08/26/2014 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 06/17/2016
Enf Action Program: HMRRP
Enf Action Type: AEO - Unified Program
Enf Action Source: CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Administrative Enforcement Order Based on the Unified Program Statute
Enf Action Notes:

Fines/Penalties Assessed: $1,500.00.

Evaluations

Eval Date: 06/15/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 06/17/2016
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Non inspection related violation: Failure to submit HMBP electronically.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/09/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure & help w/ CERS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/26/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	11/28/2017
Violations Found:	Yes
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Affiliations

Affil Type Desc:	Parent Corporation
Entity Name:	K-Swiss Sport Shoes Inc.
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Property Owner
Entity Name:	K Swiss Inc.
Entity Title:	
Address:	3177 Space Ctr
City:	Jurupa Valley
State:	CA
Country:	United States
Zip Code:	91752
Phone:	(951) 361-7500

Affil Type Desc:	Environmental Contact
Entity Name:	Vidal Menjivar
Entity Title:	
Address:	3177 Space Center Ct.
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	Identification Signer
Entity Name:	Vidal Menjivar
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Legal Owner
Entity Name:	K-Swiss Sport Shoes, Inc.
Entity Title:	
Address:	3177 Space Ctr
City:	Jurupa Valley
State:	CA
Country:	United States
Zip Code:	91752
Phone:	(951) 361-7500

Affil Type Desc:	Operator
Entity Name:	Vidal
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(951) 966-0667

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	3177 Space Ctr
City:	Jurupa Valley
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	CUPA District
Entity Name:	Riverside Cnty Env Health
Entity Title:	
Address:	4065 County Circle Drive, Room 104
City:	Riverside
State:	CA
Country:	
Zip Code:	92503
Phone:	(951) 358-5055

Map Key	***Company/Site Name***	***Address***	***Distance (m/ft)***	***Elev Diff (ft)***
4	Gerard Daniel Worldwide Gerard Daniel Worldwide Mira Loma	3265 PROGRESS CIR 3265 Progress Cir	27.18 / 89.16	9.0

ASTM Category: State Hazardous Waste Facilities
Others

Vapor Encroachment Details

Impact on Target Property:	VEC does not exist
Conditions:	Non-Petroleum Chemicals of Concern (NPCOC)
Groundwater Flow Gradient:	Up-Gradient
Flow is based on the following:	

Preferential Pathway:

Geological Attributes - Hydraulic Barrier:

Geological Attributes - Physical Barrier: Low-permeability soil

Geological Attributes - Soil Geology: Low-permeability soil

Comments:

Professional judgment and reasonably ascertainable information related to the TP and the area within the established AOC have not identified any known or suspected Chemical Of Concern COC-contaminated sites within the established AOC. (ASTM E2600 8.5.1.2, 8.5.1.3).

CERS HAZ ***Gerard Daniel Worldwide Mira Loma*** ***3265 PROGRESS CIR MIRA LOMA 91752*** ***State Hazardous Waste Facilities***

Site ID: 434645
Latitude: 34.028870
Longitude: -117.526680
County:

Regulated Programs

EI ID: 10757782 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 02/14/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 04/14/2020.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 02/14/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 04/14/2020.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Evaluations

Eval Date: 02/14/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP

Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Legal Owner
Entity Name: GERARD DANIEL WORLDWIDE
Entity Title:
Address: 3265 Progress Cir
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-1111

Affil Type Desc: Identification Signer
Entity Name: Todd Snelbaker
Entity Title: General Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: AEM
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Gerard Daniel Worldwide Mira Loma
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Riverside Cnty Env Health
Entity Title:
Address: 4065 County Circle Drive, Room 104
City: Riverside
State: CA
Country:
Zip Code: 92503

Phone:	(951) 358-5055
Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	3265 Progress Cir
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	
Affil Type Desc:	Property Owner
Entity Name:	GERARD DANIEL WORLDWIDE
Entity Title:	
Address:	13055 Jurupa Avenue
City:	Fontana
State:	CA
Country:	United States
Zip Code:	92337
Phone:	(951) 361-1111
Affil Type Desc:	Environmental Contact
Entity Name:	TODD SNELBAKER
Entity Title:	
Address:	3265 Progress Cir
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	
Affil Type Desc:	Operator
Entity Name:	GERARD DANIEL WORLDWIDE
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(951) 361-1111

RIVERSIDE HZH	***Gerard Daniel Worldwide***	***3265 Progress Cir Jurupa Valley 91752***	***Others***

Map Key	***Company/Site Name***	***Address***	***Distance (m/ft)***	***Elev Diff (ft)***
5	Adam Nutrition INTERNATIONAL VITAMIN CORP International Vitamin Corporation International Vitamin Corporation (IVC)	11010 HOPKINS ST 11010 HOPKINS ST #B 11010 Hopkins St #B 11010 Hopkins St Ste B	31.23 / 102.47	3.0

ASTM Category: Federal RCRA generators list
State and tribal leaking storage tank lists
State Hazardous Waste Facilities
Others

Vapor Encroachment Details

Impact on Target Property:	VEC does not exist
Conditions:	Non-Petroleum Chemicals of Concern (NPCOC)
Groundwater Flow Gradient:	Up-Gradient
Flow is based on the following:	
Preferential Pathway:	
Geological Attributes - Hydraulic Barrier:	
Geological Attributes - Physical Barrier:	Low-permeability soil
Geological Attributes - Soil Geology:	Low-permeability soil

Comments:

Professional judgment and reasonably ascertainable information related to the TP and the area within the established AOC have not identified any known or suspected Chemical Of Concern COC-contaminated sites within the established AOC. (ASTM E2600 8.5.1.2, 8.5.1.3).

DELISTED COUNTY | ***Adam Nutrition*** | ***11010 Hopkins St #B Jurupa Valley 91752*** | ***State and tribal leaking storage tank lists***

Original Source Facility ID:
Original Source Name: Riverside County Disclosure Facility List
Record Date: 08-Jul-2014

RIVERSIDE HWG | ***International Vitamin Corporation (IVC)*** | ***11010 Hopkins St Ste B Jurupa Valley 91752*** | ***Others***

RIVERSIDE HZH | ***International Vitamin Corporation (IVC)*** | ***11010 Hopkins St Ste B Jurupa Valley 91752*** | ***Others***

CERS HAZ | ***International Vitamin Corporation*** | ***11010 HOPKINS ST #B MIRA LOMA 91752*** | ***State Hazardous Waste Facilities***

Site ID: 3046
Latitude: 34.027600
Longitude: -117.525830
County:

Regulated Programs

EI ID: 10322089 ***EI Description:*** Hazardous Waste Generator

EI ID: 10322089 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS

Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 07/27/2017.

Violation Description:

Failure to obtain and/or maintain an Active EPA ID.

Violations

Violation Date: 11/06/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: The chemical inventory description page submitted for all chemicals contained incorrect information. Facility is using the obsolete federal hazard categories. Owner/operator shall update each material listed with the new 24 federal hazard categories. CORRECTIVE ACTION: Owner/operator shall update the chemical inventory page for all chemicals and submit to the statewide information management system (e.g. CERS) at http://cers.calepa.ca.gov. Please refer to a current Safety Data Sheet (SDS) for guidance.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.11 25404.1 - California Health and Safety Code, Chapter 6.11, Section(s) 25404.1
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Failure to obtain and/or maintain an active hazardous waste generator permit.

Violations

Violation Date: 11/06/2020 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 12/03/2020. OBSERVATION: Required NFPA-704 signs were not posted. CORRECTIVE ACTION: Owner/operator shall research chemical safety data sheets and post proper NFPA-704 signs. Signs shall be posted at the entrance of the facility. Submit photos to this department.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS

Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 09/09/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Notes:

Returned to compliance on 06/28/2017.

Violation Description:

Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/29/2018 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 09/25/2018.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Enforcements

Enf Action Date: 09/09/2014 ***Enf Action Program:*** HMRRP
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Enf Action Date: 09/09/2014 ***Enf Action Program:*** HW
Enf Action Type: Notice of Violation (Unified Program) ***Enf Action Source:*** CERS
Enf Action Division: Riverside County Department of Env Health
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 09/09/2014
Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator @ IVC, 11010 Hopkins; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/06/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to Alfredo Ferradas. - Employee training is completed online annually. ; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/09/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure @ IVC, 11010 Hopkins; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/29/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

disclosure - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/29/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

generator - no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/29/2018

Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 11/06/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

- Unable to obtain signature due to COVID-19 restrictions. - Inspection report will be sent to Alfredo Ferradas. - Facility manufactures protein powder and the following waste streams are generated (laboratory waste from QA/QC): solvent waste (methanol and acetone), acid waste (HCL and nitric acid), electronic waste - Soiled textiles are laundered through Aramark. - Facility's waste hauler is Triumvirate Environmental Services. - Facility has downsized (both staff and production) in the past year and will be reclassified to the 1-10 hazardous waste generator permit category.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Legal Owner
Entity Name: Steven Dai
Entity Title:
Address: 11010 Hopkins Suite B
City: Mira Loma
State: CA
Country: United States
Zip Code: 91752
Phone: (951) 361-1120

Affil Type Desc: Document Preparer
Entity Name: Alfredo Ferradas
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: International Vitamin Corporation
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc:	Environmental Contact
Entity Name:	Alfredo Ferradas
Entity Title:	
Address:	11010 Hopkins Suite B
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	CUPA District
Entity Name:	Riverside Cnty Env Health
Entity Title:	
Address:	4065 County Circle Drive, Room 104
City:	Riverside
State:	CA
Country:	
Zip Code:	92503
Phone:	(951) 358-5055

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	11010 Hopkins Suite B
City:	Mira Loma
State:	CA
Country:	
Zip Code:	91752
Phone:	

Affil Type Desc:	Operator
Entity Name:	IVC-Mira Loma Front Desk
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(951) 361-1120

Affil Type Desc:	Identification Signer
Entity Name:	Alfredo Ferradas
Entity Title:	Operations Supervisor
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

EPA Handler ID:	CAL000401988
Gen Status Universe:	No Report
Contact Name:	ALFREDO FERRADAS
Contact Address:	11010 HOPKINS ST STE B , , MIRA LOMA , CA, 91752 ,
Contact Phone No and Ext:	951-749-4449
Contact Email:	ALFREDO.FERRADAS@IVCINC.COM
Contact Country:	
County Name:	RIVERSIDE
EPA Region:	09
Land Type:	
Receive Date:	20141105
Location Latitude:	34.026644
Location Longitude:	-117.525843

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20141105
Handler Name:	INTERNATIONAL VITAMIN CORP
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	11010 HOPKINS ST STE B
Name:	ALFREDO FERRADAS	***Street 2:***	

Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	951-749-4449	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	11010 HOPKINS ST
Name:	STEVEN DAI	***Street 2:***	
Date Became Current:		***City:***	MIRA LOMA
Date Ended Current:		***State:***	CA
Phone:	951-361-1120	***Country:***	
Source Type:	Implementer	***Zip Code:***	91752

Map Key	***Company/Site Name***	***Address***	***Distance (m/ft)***	***Elev Diff (ft)***
9	HOME DEPOT USA INC HD 5645 Home Depot Distribution IDC #5645 MARCH COMMUNICATION ANNEX #2 MILLIKEN SANITARY LANDFILL The Home Depot Store #5645	11650 VENTURE DR 11650 VENTURE DRIVE 11650 Venture Dr INTERSECTION: MILLIKEN AVE & MISSION BLV	44.33 / 145.45	8.0

ASTM Category:
Federal RCRA generators list
State and tribal equivalent CERCLIS
State Hazardous Waste Facilities
Others

Vapor Encroachment Details

Impact on Target Property:	VEC does not exist
Conditions:	Non-Petroleum Chemicals of Concern (NPCOC)
Groundwater Flow Gradient:	Cross-Gradient
Flow is based on the following:	
Preferential Pathway:	
Geological Attributes - Hydraulic Barrier:	
Geological Attributes - Physical Barrier:	Low-permeability soil
Geological Attributes - Soil Geology:	Low-permeability soil
Comments:	

RIVERSIDE HZH	***Home Depot Distribution IDC #5645***	***11650 Venture Dr Jurupa Valley 91752***	***Others***

RIVERSIDE HWG	***The Home Depot Store #5645***	***11650 Venture Dr Jurupa Valley 91752***	***Others***

ENVIROSTOR	***MILLIKEN SANITARY LANDFILL***	***INTERSECTION: MILLIKEN AVE & MISSION BLV ONTARIO 91761***	***State and tribal equivalent CERCLIS***

Estor/EPA ID:	36490106	***Assembly District:***	
Site Code:	401055	***Senate District:***	

Nat Priority List:	NO	***Permit Renewal Lead:***	
APN:	NONE SPECIFIED	***Public Partici Spclst:***	
Census Tract:	6071001400	***Project Manager:***	
Site Type:	* HISTORICAL	***County:***	SAN BERNARDINO
Address Description:	INTERSECTION: MILLIKEN AVE & MISSION BLV	***Latitude:***	34.0633443
Office:	CLEANUP CYPRESS	***Longitude:***	-117.6508876
Special Program:		***Acres:***	NONE SPECIFIED
Funding:		***Supervisor:***	

Cleanup Status: REFER: RWQCB AS OF 6/1/1995
Cleanup Oversight Agencies: US EPA - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: REFER: RWQCB
A2 Program Type: HISTORICAL
CalEnviroScreen Score: 96-100%
Summary Link: http://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=36490106

Completed Activities

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 10/8/1991
Comments: SI Report was reviewed by Region 4 staff. EPA recommended Listing Site Inspection under CERCLA. Report sent to file. Location Information: Site is located in Township 1 South, Range 7 West, Section 36.

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 4/25/1995
Comments: OPEN SITE-REEVALUATION OF HRS (SCORE). NFA FOR DTSC.

Title: Discovery
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Discovery

Date Completed: 4/30/1990
Comments: FACILITY IDENTIFIED EPA CERCLA SCREENING SITE INSPECTION EPA COMPLETED CERCLA SCREENING SITE INSPECTION AND RECOMMEND LISTING SITE INSPECTION. EPA/CERCLA SITE

Title: Site Screening
Title Link:
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 10/27/1994
Comments: U.S. EPA is conducting reevaluation of HRS.

CERS HAZ ***The Home Depot Store #5645*** ***11650 VENTURE DR MIRA LOMA 91752*** ***State Hazardous Waste Facilities***

Site ID: 403850
Latitude: 34.028206
Longitude: -117.536407
County:

Regulated Programs

EI ID: 10140279 ***EI Description:*** Chemical Storage Facilities

EI ID: 10140279 ***EI Description:*** Hazardous Waste Generator

Violations

Violation Date: 06/22/2018 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: Un-Specified
Violation Notes:

Returned to compliance on 12/12/2018. 03 reinspection performed on 12-12-18 for this program.

Violation Description:

Business Plan Program - Operations/Maintenance - General Local Ordinance

Violations

Violation Date: 09/12/2014 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Riverside County Department of Env Health
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 10/01/2014. [LOCAL ORDINANCE VIOLATION 101C] Approved HMBP accessible on site and available for review.

Violation Description:

Business Plan Program - Administration/Documentation - General

Enforcements

Enf Action Date:	09/12/2014	***Enf Action Program:***	HMRRP
Enf Action Type:	Notice of Violation (Unified Program)	***Enf Action Source:***	CERS
Enf Action Division:	Riverside County Department of Env Health		
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection		
Enf Action Notes:			

Evaluations

Eval Date:	09/12/2014
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/12/2018
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Eval Date:	09/12/2014
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

generator-no violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/22/2018
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Riverside County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

disclosure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2018

Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Riverside County Department of Env Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 213 Court Street, Suite 700 c/o Compliance Dept.
City: Middletown
State: CT
Country:
Zip Code: 06457
Phone:

Affil Type Desc: Legal Owner
Entity Name: The Home Depot U.S.A., Inc.
Entity Title:
Address: 2455 Paces Ferry Road, C-19
City: Atlanta
State: GA
Country: United States
Zip Code: 30339
Phone: (770) 433-8211

Affil Type Desc: Parent Corporation
Entity Name: The Home Depot USA, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: ARCADIS U.S., Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: ARCADIS U.S., Inc.
Entity Title:

Address:	213 Court Street, Suite 700 c/o Compliance Dept.
City:	Middletown
State:	CT
Country:	
Zip Code:	06457
Phone:	

Affil Type Desc:	CUPA District
Entity Name:	Riverside Cnty Env Health
Entity Title:	
Address:	4065 County Circle Drive, Room 104
City:	Riverside
State:	CA
Country:	
Zip Code:	92503
Phone:	(951) 358-5055

Affil Type Desc:	Identification Signer
Entity Name:	John Falcetti, Agent for The Home Depot
Entity Title:	Regulatory Compliance Specialist
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Operator
Entity Name:	The Home Depot U.S.A., Inc.
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(770) 433-8211

Coordinates

Env Int Type Code:	HMBP	***Longitude:***	-117.536410
Program ID:	10140279	***Coord Name:***	
Latitude:	34.028210	***Ref Point Type Desc:***	Center of a facility or station.

RCRA SQG ***HOME DEPOT USA INC HD 5645*** ***11650 VENTURE DRIVE MIRA LOMA 91761*** ***Federal RCRA generators list***

EPA Handler ID:	CAR000168153
Gen Status Universe:	Small Quantity Generator
Contact Name:	ROBERT PERKINS
Contact Address:	1905 ASTON AVE , STE 100 , CARLSBAD , CA, 92008 , US
Contact Phone No and Ext:	760-602-8700
Contact Email:	RPERKINS@3ECOMPANY.COM
Contact Country:	US

County Name: RIVERSIDE
EPA Region: 09
Land Type: Private
Receive Date: 20050629
Location Latitude: 34.029661
Location Longitude: -117.536409

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050629
Handler Name: HOME DEPOT USA INC HD 5645
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D016

Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	2455 PACES FERRY RD
Name:	HOME DEPOT USA	***Street 2:***	
Date Became Current:	20001106	***City:***	ATLANTA
Date Ended Current:		***State:***	GA
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	30339

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	HOME DEPOT USA	***Street 2:***	
Date Became Current:	20001106	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

FUDS ***MARCH COMMUNICATION ANNEX #2*** ***Others***

SAN BERNARDINO/RIVERSIDE COUNTY LINES

FUDS No:	J09CA0120	***EPA Region:***	09
INST ID:	CA99799F532300	***CONG DIST:***	35
Object ID:	4652	***County:***	SAN BERNARDINO
NPL Status:	Not Listed	***County Code:***	Los Angeles District (SPL)
Status:	Properties without projects	***Latitude:***	34.03694444
FY:	2018	***Longitude:***	-117.52638889
Eligibility:	Eligible	***Has Projects:***	No
Current Owner:	Local Government; Other Federal Government; Private Sector		
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=60976		

Appendix: Database Descriptions

The following are data source listings found in the attached report. For full descriptions, please refer to the associated ERIS Database Report.

DB	*Database Name*	*Publication Date*	*Source*	*Classification*	*ASTM Category*
DELISTED COUNTY	Delisted County Records	Mar 23, 2021	State	Standard	State and tribal leaking storage tank lists
ENVIROSTOR	EnviroStor Database	Jan 13, 2021	State	Standard	State and tribal equivalent CERCLIS
RCRA NON GEN	RCRA Non-Generators	Jan 22, 2021	Federal	Standard	Federal RCRA generators list
RCRA SQG	RCRA Small Quantity Generators List	Jan 22, 2021	Federal	Standard	Federal RCRA generators list
CERS HAZ	California Environmental Reporting System (CERS) Hazardous Waste Sites	Feb 9, 2021	State	Non Standard	State Hazardous Waste Facilities
FUDS	Formerly Used Defense Sites	Jan 28, 2020	Federal	Non Standard	Others
RIVERSIDE HWG	Riverside County - Hazardous Waste Generator Sites List	Mar 23, 2021	County	Non Standard	Others
RIVERSIDE HZH	Riverside County - Disclosure Facility List	Nov 24, 2020	County	Non Standard	Others

PERSONNEL QUALIFICATIONS

Professional Service Industries, Inc.

All Appropriate Inquiries Environmental Professional

Jeffery Townsend

Meets the education, training, and experience requirements as set forth in 40 CFR §312.10

October 4, 2006

Chief Learning Officer

JEFFERY P. TOWNSEND, LEP, REPA

SENIOR SPECIALIST/PRINCIPAL CONSULTANT

ORLANDO, FLORIDA

TOTAL YEARS OF EXPERIENCE: 32 / YEARS WITH INTERTEK-PSI: 32

Education

- Associate in Science, Valencia College, Orlando, Florida, 1994
- Aerospace Engineering Studies, Kansas University 1985-87

Certifications/Registrations/Technical Training

- Licensed Environmental Professional #144
- Registered Environmental Property Assessor #5999
- Environmental Professional-Phase I ESA, PSI
- Phase I & II Environmental Site Assessment Field Methods, PSI
- EPA AHERA Asbestos Inspector
- Lead Inspector
- RMD LPA-1 Certified
- OSHA 40-Hour HAZWOPER
- U.S. Housing of Urban Development (HUD) Environmental Review Procedures Training

Memberships/Affiliations

- Florida Environmental Assessors Association, Inc.
- International Society of Technical Environmental Professionals, Inc. (INSTEP)
- National Registry of Environmental Professionals

Professional Experience

Mr. Townsend has over 32 years of experience in the environmental engineering field. He is responsible for senior technical review of Phase I ESAs, employee development and quality control for those performing Phase I ESAs, and has been assigned as one of PSI's Principal Consultants for the Phase I ESA Program in Orlando, Florida and other Florida operations, conducting ESAs and surveys to include components relevant to the All Appropriate Inquiry (AAI), U.S. Housing and Urban Development (HUD), and Federal Communication Commission (FCC) National Environmental Policy Act (NEPA). He serves as the point of contact on projects to provide a fluid project for the client from beginning to end.

One of Mr. Townsend's responsibilities is interacting with clients to discuss environmental concerns and issues, as well as determining the best course of action to address concerns identified. Mr. Townsend is an EPA-certified asbestos and lead inspector and a Licensed Environmental Professional. His current responsibilities include conducting Phase I ESAs, CSERs, asbestos, lead-based paint, and indoor air quality projects. The ESAs have included both developed and undeveloped properties to include agricultural, commercial, industrial, and residential properties, and large acre tracts of land.

Representative Large-Acre Tract Project Experience

- South Florida Water Management District - Phase I ESA Project Manager and Team Leader for 187,000± acre transaction that included cultivated lands and industrial assets (citrus plant, railroad maintenance yards, and sugar mills). The Project Team included personnel from select consulting firms. Mr. Townsend was responsible for ensuring that the Project Team assigned to the project completed daily tasks, implemented quality control, discussed findings with PSI's Chief Engineer and the client. The Phase I ESA team was responsible for identifying point source locations to conduct Phase II ESA.
- Confidential Clients - Conducted Phase I ESAs on tracts of land located in surrounding Central Florida counties that included agriculturally developed land. The properties ranged in size from 5± to 30,000± acres. The site reconnaissance included traversing the property on the ground and aerial fly-overs. The areas of concerns identified included, but were not limited to, chemical storage areas, storage tanks, fleet maintenance repair areas, landfilling activities, and historical agricultural activities.
- Four Winds Hotel, Osceola County, Florida - Performed Senior Review of Phase I ESA for a Neighborhood Stabilization Program (NSP3) on a two-story 52-unit hotel structure in Kissimmee, Florida.
- Donald W. McIntosh - Conducted Phase I ESA on a 4,100± acre tract of land in Orange County, Florida utilized for citrus production, shooting ranges, and cattle grazing. Areas of concern identified chemical mixing/storage areas, maintenance repair facilities, and the shooting ranges and associated ponds.
- Florida Crushed Stone - Performed Phase I ESAs for industrial properties involved in mining operations and concrete manufacturing in Florida. The sites ranged in size from 900 to 1,500 acres. Involved in identifying conditions requiring additional investigation.
- McLin and Burnsed, Florida - Performed Phase I ESAs in Lake, Sumter, and Marion Counties, Florida on properties ranging in size up to 4,000± acres of agriculturally developed land. Concerns identified included cattle dipping vats, former underground storage tanks, and equipment maintenance areas. Determined further investigation was necessary and assisted in Phase II ESA effort.
- Maury L. Carter & Associates, Inc. - Performed Phase I ESA on 400 acre tract in Orange County, Florida. Traversed the land on the ground to identify potential areas of concern. Areas of concern included agricultural activities.

Representative Phase I/II Environmental Site Assessment Projects

- The City of Orlando (City) hired PSI in September 2013 to perform a Phase I ESA for two city blocks in downtown Orlando. PSI performed Phase II ESA and Supplemental Site Assessment (SSA) activities in 2014. The remedial activities were initiated in February 2015 and extended into May 2015. PSI assisted the City with paperwork to receive Brownfields Reimbursement of Remediation costs. PSI continues to work with the project team to complete the assessment activities for the areas of soil and groundwater impacts located outside of the stadium project site. Mr. Townsend provided assessment and senior technical review.
- South of Downtown Orlando (SoDo) Redevelopment Project, Orlando, Florida - Performed Phase I ESA for a proposed mixed use development encompassing a city block. Identified on-site and off-site concerns to include auto maintenance, dry cleaning facilities, paint mixing facilities, petroleum spillage, and former UST/AST locations.

- American Portable Telecom; Orlando, Florida - Performed Phase I ESAs on multiple proposed communication tower sites in Central Florida.
- Orange County Public Schools; Orlando, Florida - Involved in conducting Phase I ESAs on numerous properties throughout Orange County for proposed school facilities. Conducted Phase I ESA on a proposed bus facility for the school district that was identified during the Phase I ESA to have been historically used as a disposal site for construction and demolition debris and used dry cell batteries.
- Orlando Regional Healthcare; Orlando, Florida - Involved in conducting Phase I ESAs on numerous properties throughout Orange County for healthcare facilities. Conducted Phase I ESA on a facility for that was identified during the Phase I ESA to have been historically contaminated with solvents.
- Prudential Real Estate Investments, Florida - Involved in conducting Phase I ESAs on numerous properties throughout Florida. Conducted Phase I ESA on site that was a portion of the former Orlando Naval Training Center facility. Site was identified during the Phase I ESA to have been historically impacted with solvents.
- University of Central Florida (UCF) - Worked with UCF and The UCF Research Foundation on various due diligence projects including the UCF College of Medicine, Bennett Research Park (a research and technology center housing UCF's business incubator program), and the UCF Photovoltaic Manufacturing Consortium (PVMC) Center formerly known as Building 54 of the former Harris Corporation and current Intersil Site, both semiconductor manufacturing operations. This building was used for semiconductor wafer manufacturing operations and consists of more than 100,000 square feet of office space, manufacturing and cleanroom facilities, and five acres of land and is located within an approximate 310-acre area that has been investigated and assessed by the U.S. Environmental Protection Agency (EPA). Remedial activities have included extraction and treatment of impacted groundwater, and based on the decreased contaminant concentrations, the Site is currently under natural attenuation. The EPA has issued a Ready for Reuse Determination concluding that the site may be used for commercial and industrial land uses. Based on the assessment activities, Building 54 was identified not to be a source of the known impact.

Representative HUD, NEPA, and Environmental Review (ER) Project Experience

- Ivanhoe Place Propco LLC - Performed FCC NEPA work including Section 106 and tribal submissions for cell tower relocation that achieved State Historic Preservation Office (SHPO) and Tribal Historic Preservation Office (THPO) concurrence.
- Conducted a NEPA review on a proposed cellular tower site situated at latitude/longitude N 28 30 03.60 / W 81 36 25.40 World Geodetic System 1984 (WGS84), according to the 8-point NEPA Land Use Screening Checklist. Review of the NEPA Checklist for the 8 items found that based on information provided, the scope of work and sources documented, the NEPA Review determined that the preparation and filing of an Environmental Assessment (EA) will not be required.
- Conducted a NEPA Review pursuant to 47 CFR 1.1301-1.1319, as amended. The Site was located at latitude and longitude N 28 43 32.69 / W 81 33 45.04 World Geodetic System 1984 (WGS84) and consisted of vegetated, undeveloped land.
- Florida Housing Finance Corporation (FHFC), Various Locations, Florida - Perform ERs for projects that are seeking HUD funding. PSI has held the contract to perform the ERs for FHFC to the past decade.

- City of Sanford, Sanford, Florida - Performed ERs under Community Development Block Grants (CDBG) and Neighborhood Stabilization Program (NSP2 and NSP3) for individual properties, Hopper Academy, Redding Gardens, and the historic Goldsboro and Georgetown neighborhoods. The property areas included 4.73±, 220±, 540±, and 635± acres in size.
- Florida S.P.E.C.S, Kissimmee, Florida - Performed and reviewed ERs under NSP2 for individual properties.
- First Housing Development Corporation, Orlando, Florida - Performed Phase I ESAs and senior technical review, which included HUD NEPA components.

Representative Educational Facility Project Experience

- Orange County Public Schools (OCPS) - OCPS contracted PSI to perform due diligence services to include Phase I and II ESAs for a planned school development in Orlando. Due to the confidential nature of the project and the number of property owners, OCPS requested that PSI prepare separate Phase I and II ESA reports for each individually owned property. The project involved a significant amount of planning and coordination with numerous parties in order to perform the due diligence services in a timely manner within OCPS' budget, while accommodating schedules of the various owners and tenants of the properties. Mr. Townsend provided oversight, field management, and senior technical review.
- Seminole County Public Schools - Managed and conducted Phase I ESAs for over 20 properties from 1993 to 2005. The properties have included proposed school sites and the administration building and established school properties. Involved with the senior technical review of the Phase I ESA reports and identifying sites requiring additional investigation and communicating findings of Phase I ESAs to the School Board of Seminole County.
- Osceola County Public Schools - Managed and conducted Phase I ESAs for proposed school sites within Osceola County, Florida. Properties have included former convention centers, residential properties, and agricultural land to undeveloped, raw land. Communicate findings to the School Board and discuss sites requiring additional investigation.
- Seminole State College - Managed and conducted Phase I ESAs for properties surrounding the Seminole County, Florida campus for due diligence during real estate transactions. Involved with the senior technical review of reports and communicating findings to the clients.

Professional Service Industries, Inc.

TEIRA SOLIS, GIT

Staff Scientist / Project Manager
Environmental Professional



Education
PhD Student in Geological Sciences, University of Texas at El Paso (in progress)

Master of Science in Geophysics, University of Texas at El Paso, 2013

Bachelor of Science in Geological Sciences, University of Texas at El Paso, 2010

Certifications/Registrations/ Technical Training
Geologist in Training (#GIT-403)
PSI Project Manager Certification Program
PSI ASTM E 1527-13 Certification
Accredited Building Inspector for Asbestos. TDSHS No. 603537
Qualified Compliance Inspector of Storm Water Pollution Prevention Plans (Texas)
Qualified Preparer of Storm Water Pollution Prevention Plans (Texas)

Affiliations/Memberships
American Society of Testing Materials (2018)
Society of Exploration Geophysicists (2011)
American Geophysical Union (2010)
American Association of Petroleum Geologists (2006)
National Association of Geoscience Teachers (2018)

Years of experience with other firms: 3
Year started with PSI: 2016

PROFESSIONAL EXPERIENCE

Ms. Solis is a trained geophysicist and is in the process of learning and gaining experience in the environmental field. Ms. Solis's responsibilities include conducting Phase I Environmental Site Assessments for national and local clients; as well as asbestos inspections, indoor air quality monitoring, lead-based paint, and environmental noise surveys in west Texas, the Texas panhandle, New Mexico, Arizona, and selected locations in southern California. Conducts Refraction Microtremor (ReMi) geophysical surveys for soil characterization. She is currently preparing for the Professional Geologist License examination for the state of Texas.
Additionally, as Adjunct Faculty of the Geological Sciences Department at the University of Texas at El Paso, Ms. Solis teaches GIS courses to undergraduate and graduate students.

Representative Project Experience

- **HACEP Machuca Apartments:** Phase I ESA (original and update), Asbestos survey, Lead-Based Paint, Mold, Environmental Noise Survey, and HEROS Report – El Paso, TX
- **HACEP Villa Alegre Apartments:** Asbestos survey on 70 units – El Paso, TX
- **HACEP Emergence Health Network**: Asbestos survey - El Paso, TX
- **Blue Beacon Phase I ESA** – El Paso, Midland, and Odessa, TX
- **Top Golf ESA** – Tucson, AZ; Albuquerque, NM; El Paso, TX.
- **Dollar General** Phase I ESA, Asbestos, Lead-Based Paint, and Mold - Multiple locations in Texas and New Mexico
- **Sears North Plains Mall** Phase I ESA, Asbestos, Lead-Based Paint and Mold survey – Clovis, NM
- **Sealy Portfolio**: Phase I ESA Project Manager at 5 locations in El Paso, TX
- **Republic National Distributing Center Portfolio**: Phase I ESA Project Manager at 3 locations in Albuquerque, NM, El Paso, TX, and Lubbock, TX.
- **Cracker Barrel Portfolio**: Phase I ESA Project Manager at 7 locations in Arizona.
- **VA Community Based Outpatient Clinic** Phase I ESA Project Manager – Phoenix, AZ and Lubbock, TX
- **Caliber Collision** Phase I ESA – Multiple locations in Arizona, Nevada, New Mexico, and Texas.
- **Service First Auto Center** Phase I ESA – Goodyear, Litchfield, Tempe, and Queen Creek, AZ
- **El Paso International Airport Warehouse** Asbestos Survey – El Paso, TX
- **Las Cruces Country Club** Phase I ESA, Asbestos and Lead-Based Paint survey – Las Cruces, NM
- **Canutillo ISD** COVID-19 Disinfection Consultation and Sampling – El Paso, TX
- **Figure 2 Ranch Phase V Headquarters Addition** Refraction Microtremor survey – Van Horn, TX
- **El Paso Fence Replacement:** Refraction Microtremor survey – Columbus, NM
- **Carvana** Phase I ESA – Albuquerque, NM
- **Oakmont Senior Housing Portfolio:** Phase I ESA – Multiple locations in Southern California
- **UTEP Parking Garage III** Refraction Microtremor Survey – El Paso, TX
- **XTO and Jayhawk Compressor Stations:** Refraction Microtremor and Electrical Resistivity Surveys – Carlsbad, NM

intertek psi