PUBLIC REVIEW DRAFT

ENVIRONMENTAL IMPACT REPORT

FOR THE

GOSPEL CENTER RESCUE MISSION NEW LIFE HOMELESS DORMITORY

Stockton, CA

October 2022

Prepared for:

Community Development Department
City of Stockton
345 N. El Dorado St
Stockton, CA 95202

Prepared by:

BaseCamp Environmental, Inc.
802 W. Lodi Avenue
Lodi, CA 95240



PUBLIC REVIEW DRAFT

ENVIRONMENTAL IMPACT REPORT

FOR THE

GOSPEL CENTER RESCUE MISSION NEW LIFE HOMELESS DORMITORY Stockton, CA

October 2022

Prepared for:

Community Development Department
City of Stockton
345 N. El Dorado St
Stockton, CA 95202
209-937-8561

Prepared by:

BaseCamp Environmental, Inc.
802 W. Lodi Avenue
Lodi, CA 95240
209-224-8213
www.basecampenv.com

TABLE OF CONTENTS

			Page
INTRODUCTION, SUMMARY, AND PROJECT DESCRIPTION			
1.0	Introduction		
	1.1	Project and EIR Overview	1-1
	1.2	Project Background	1-1
	1.3	EIR Requirements and Processing Under CEQA	1-2
	1.4	CEQA Procedures for the EIR	1-3
2.0	Summary		
	2.1	Project Description	2-1
	2.2	Environmental Impacts and Mitigation Measures	2-1
	2.3	Areas of Controversy	2-1
	2.4	Summary of Alternatives	2-2
	2.5	Summary of Other CEQA Issues	2-2
3.0	Project Description		
	3.1	Project Location	3-1
	3.2	Project Objectives	3-1
	3.3	Project Details	3-1
	3.4	Permits and Approvals	3-2
ENVIRONMENTAL ISSUES			
4.0	Aesthetics and Visual Resources		4-1
5.0	Air Quality		5-1
6.0	Biological Resources		6-1
7.0	Cultural Resources		7-1
8.0	Geology and Soils		8-1

9.0 Greenhouse Gas Emissions 9-1
10.0 Hazards and Hazardous Materials 10-1
11.0 Hydrology and Water Quality 11-1
12.0 Land Use, Agriculture, and Population 12-1
13.0 Noise 13-1
14.0 Public Services and Recreation 14-1
15.0 Transportation 15-1
16.0 Utilities and Energy 16-1
CUMULATIVE IMPACTS, ALTERNATIVES, AND OTHER CEQA ISSUES
17.0 Cumulative Impacts
17.1 Introduction to Cumulative Impacts 17-1
17.2 Cumulative Impact Setting 17-2
17.3 Cumulative Impacts of Project 17-2
18.0 Alternatives
18.1 Introduction 18-1
18.2 Selection of Alternatives 18-1
18.3 Alternatives Not Considered in Detail 18-3
18.4 Alternatives Considered in Detail 18-4
18.5 Environmentally Superior Alternative 18-5
19.0 Other CEQA Issues
19.1 Significant and Unavoidable Environmental Impacts 19-1
19.2 Irreversible Environmental Commitments 19-1
19.3 Growth-Inducing Impacts 19-2
19.4 Environmental Justice 19-3

SOURCES

20.0 Sources

20.1 References Cited 20-1

20.2 Persons Consulted 20-4

20.3 EIR Preparers 20-4

APPENDICES

A. Notice of Preparation and NOP Comments

B. Air Quality Modeling Results

C. Page and Turnbull, Inc. Primary Records

D. Historic American Buildings Survey Report

E. Central California Information Center Report

F. Biological Database Reports

G. AB 52 Notification and Consultation Information

H. Phase I ESA

LIST OF FIGURES

1-1. Regional Project Location 1-5

1-2. Street Map 1-6

1-3. USGS Map 1-7

1-4. Aerial Photo 1-8

1-5. Assessor Parcel Map 1-9

4-1. Existing On-Site Structures 4-6

4-2. Project Neighborhood Views – Ground 4-7

4-3. Project Neighborhood Views – Aerial 4-8

3-1. Project Site 3-3

3-2. Floor Plans 3-4

3-3. Elevations 3-5
3-4. Architectural Renderings 3-6
12-1. General Plan Amendment 12-8
12-2. Zoning Map 12-9

LIST OF TABLES

1-1 NOP Letters Received 1-3
2-1. Summary of Impacts and Mitigation Measures 2-3
5-1. National and California Ambient Air Quality Standards 5-4
5-2. San Joaquin Valley Air Basin Attainment Status 5-5
5-3. SJVAPCD Significance Thresholds and Predicted Project Air Pollutant Emissions 5-8
8-1. Modified Mercalli Intensity Scale 8-2
9-1. Project GHG Emissions 9-4
12-1. Population of Stockton, San Joaquin County and California 12-3
13-1. Exterior Hourly Noise Level Standards for Stationary Noise Sources 13-3
13-2. Construction Equipment Noise 13-4
19-1. SB 1000 Topics and Project Impacts 19-5

ACRONYMS AND ABBREVIATIONS USED IN THIS DOCUMENT

AB	Assembly Bill
APN	Assessor's Parcel Number
ARB	California Air Resources Board
BMP	Best Management Practice
CalEEMod	California Emissions Estimator Model
CalEnviroScreen	California Communities Environmental Health Screening Tool
CalEPA	California Environmental Protection Agency
Cal Fire	California Department of Forestry and Fire Protection
CALGreen	California Green Building Standards Code
Caltrans	California Department of Transportation
CDFW	California Department of Fish and Wildlife
CEQA	California Environmental Quality Act
CERCLA	Comprehensive Environmental Response Compensation and Liability Act
CESA	California Endangered Species Act
CNDDB	California Natural Diversity Data Base
CO	carbon monoxide
CO_2e	carbon dioxide equivalent
Corps	U.S. Army Corps of Engineers
CUPA	Certified Unified Program Agency
dB	decibel
dBA	A-weighted decibel
DTSC	California Department of Toxic Substances Control
DWR	California Department of Water Resources
EIR	Environmental Impact Report
EPA	U. S. Environmental Protection Agency
ESA	Endangered Species Act (federal)
FEMA	Federal Emergency Management Agency
GAMAQI	Guide for Assessing and Mitigating Air Quality Impacts
GHG	greenhouse gas
GSA	Groundwater Sustainability Agency
IPCC	United Nations Intergovernmental Panel on Climate Change
kWh	kilowatt hours
L_{dn}	Day-Night Average Sound Level
L_{eq}	Equivalent Sound Level
LOS	Level of Service
LUSD	Livingston Union School District
MCAG	Merced County Association of Governments

mgd	million gallons per day
MID	Merced Irrigation District
MRZ	Mineral Resource Zone
MS4	Municipal Separate Storm Sewer System
MUHSD	Merced Union High School District
NO_x	nitrogen oxides
NOP	Notice of Preparation
NPDES	National Pollutant Discharge Elimination System
OPR	Governor's Office of Planning and Research
PM	particulate matter
PM_{10}	particulate matter 10 micrometers or less in diameter
$PM_{2.5}$	particulate matter 2.5 micrometers or less in diameter
RCRA	Resource Conservation and Recovery Act
ROG	reactive organic gases
RTP	Regional Transportation Plan
RWQCB	Regional Water Quality Control Board
SB	Senate Bill
SCS	Sustainable Communities Strategy
SJVAPCD	San Joaquin Valley Air Pollution Control District
SR	State Route
SWMP	Storm Water Management Program
SWPPP	Storm Water Pollution Prevention Plan
SWRCB	State Water Resources Control Board
TAC	toxic air contaminant
USFWS	U.S. Fish and Wildlife Service
UWMP	Urban Water Management Plan
VMT	vehicle miles traveled

1.0 INTRODUCTION

1.1 PROJECT AND EIR OVERVIEW

This document is an Environmental Impact Report (EIR) for the Gospel Center Rescue Mission, Inc.'s (GCRM) 178-bed Homeless New Life Dormitory Men's Home project (project) on South San Joaquin Street in Stockton. California. The project would replace 19 existing beds in two existing buildings on one existing lot at 429-431 and 435-437 South San Joaquin (Figures 1-1 to 1-5). This EIR has been prepared in compliance with the requirements of the California Environmental Quality Act (CEQA). For the purposes of CEQA, the City of Stockton (City) is the Lead Agency for the project.

This EIR evaluates the potential environmental effects of the project, which is the demolition of two 117-year old buildings and construction of a new 144-bed, three-story residential building and associated improvements on the 0.21-acre project site; up to 178 beds of capacity can be provided under pandemic or other overflow conditions. The building would include primarily dormitory rooms together with common restrooms and community facilities including meeting rooms, classrooms, laundry, elevator and lobby. A dayroom, gym and computer center would be located on the third floor. Site improvements would include pedestrian ways. The project would connect to existing City water, wastewater and storm drainage lines in the adjoining street. Food and social services to residents would be provided from adjacent existing GCRM facilities.

The project would require approval of an Administrative Use Permit by the Stockton Planning Commission and Site Plan/Design Review and parking waiver at the staff level.

1.2 PROJECT BACKGROUND

The Gospel Center Rescue Mission is a non-profit corporation that has been providing transient housing, meals and other support to homeless and addicted persons in central Stockton since 1940. Among its other support programs, GCRM's New Life Program provides two-year and longer transitional housing for both men and women; New Life Phase 1 provides a range of services supporting transition from addiction to recovery, including spiritual needs, emotional and physical health classes, work therapy and positive community activities. Phase 2 and 3 of the program provide continuing opportunities for community service, employment and vocational training, education and transitional housing leading to sustainable permanent housing.

Like many larger cities in California, the City of Stockton and a number of associated non-profit agencies including the Stockton Shelter for the Homeless, GCRM, the Stoctkton Women's Shelter and several other smaller agencies described in the Stockton Housing Element Background Report are actively addressing what Governor Gavin

Newsom termed a homelessness crisis in his 2020 and 2021 "State of the State Addresses."

The City of Stockton has seen a significant rise in the homeless population over the last several years. According to the San Joaquin County Continuum of Care Point in Time Count completed in January 2019, Stockton contributed to 58% of the County's unsheltered homeless population, with a total count of 921, 65% being male. The same count generated in January 2017 reported the same demographic as a total count of 567. (SJCoC, 2019)

With the renewed availability of state and federal funding that was projected, GCRM has renewed its plans to augment its other housing and services with the proposed homeless dormitory. This would be accomplished by demolishing two existing buildings to be replaced by the new 3 story, ADA accessible, elevator-equipped dormitory.

Once completed, the project will raise the homeless bed capacity at GCRM and create the largest men's long-term (over 6 months) homeless regeneration single campus/city program in northern California to complement one of the largest similar programs for women and children in America.

1.3 EIR REQUIREMENTS AND PROCESSING UNDER CEQA

CEQA, enacted in 1970, requires that public agencies document and consider the potential environmental effects of the agency's actions that meet CEQA's definition of a "project." Briefly summarized, a "project" is an action that has the potential to result in direct or indirect physical changes in the environment. A project includes the agency's direct activities as well as related activities that involve public agency approvals or funding. The proposed project, including site approvals and development, is considered a project as defined by CEQA.

This EIR has been prepared in accordance with the requirements of CEQA and the State CEQA Guidelines (California Code of Regulations Title 14, Chapter 3). The CEQA Guidelines contain advisory and mandatory requirements for the application of CEQA to development projects. CEQA requires the designation of a "lead agency" for a project. As defined in the CEQA Guidelines, the lead agency is the public agency that has the principal responsibility for carrying out or approving a project. Since the City has approval authority over the proposed project, it is the lead agency for CEQA purposes.

An EIR is intended to inform decision-makers and the public about the potentially significant adverse environmental effects of a project and to describe mitigation measures that would reduce or avoid these effects. This EIR generally follows the sequence of the latest Environmental Checklist in CEQA Guidelines Appendix G in the analysis of project impacts on environmental issues. The EIR includes consideration of cumulative impacts, growth-inducing impacts, irreversible environmental effects, and alternatives to the proposed project as required by CEQA.

Proposed demolition of the two existing buildings on the site may result in a significant effect on the environment (CEQA Guidelines 150645(b). Best available mitigation may not reduce the potential effect to a less than significant level; therefore, the project applicant has elected to proceed with the preparation of this EIR.

1.4 CEQA PROCEDURES FOR THE EIR

On ___, 2021, the City circulated a Notice of Preparation (NOP) inviting comments from interested agencies and the public as to environmental concerns that should be considered in the EIR. A DRAFT NOP HAS BEEN SUBMITTED TO CITY STAFF FOR REVIEW AND APPROVAL

The NOP was received and published by the State Clearinghouse on __, 2022, and the 30-day NOP comment period closed on __, 2022. Appendix A contains the NOP and letters received during the comment period from agencies and interested persons. Table 1-1 summarizes the content of these comment letters.

TABLE 1-1
NOP LETTERS RECEIVED

#	Date	Commenter	Concern
1	6/7/22	SJC Environmental Health	Advise of permit requirements for geotechnical drilling
2	5/24/22	SJCOG Habitat	Advises of required participation in SJMSCP
3	5/25/22	Comcast	Provided maps of nearby facilities
4	6/17/22	RWQCB	Advises of potentially applicable WQ requirements
5	6/15/22	SJVAPCD	Regulatory requirements. No project-specific concern


With the release of this Public Review Draft EIR and accompanying Notice of Availability, regulatory agencies and members of the public will have the opportunity to comment on the adequacy of the environmental review during a 45-day review period. After the close of the public review period, the City will provide written responses to the comments received, and these responses will be published in a Final EIR.

Prior to a decision on the project, the City decision-makers must first certify that 1) the Final EIR was completed in compliance with the provisions of CEQA, 2) the City has reviewed and considered the information in the Final EIR, and 3) the Final EIR reflects the independent judgment of the City on the environmental impacts of the project. The City is also required to make specific findings related to each of the significant effects identified in the EIR as specified in Sections 15091-15093 of the CEQA Guidelines. If mitigation measures are included in the Final EIR, the City also must adopt a Mitigation Monitoring and Reporting Program that will ensure the mitigation measures are implemented.

In accordance with CEQA Guidelines Section 15163(c), this EIR is available for public review and comment at the locations and between the dates specified in the NOA, located


inside of the cover of this document. Any comments or questions regarding this EIR should be submitted to the City at the following address before the close of the public review period:

City of Stockton
Community Development Department
Attention: Nicole Moore, LEED-AP
345 North El Dorado Street
Stockton, CA 95202
nicole.moore.ctr@stocktonca.gov



BaseCamp Environmental


Figure 1-1
REGIONAL PROJECT LOCATION



SOURCE: Google Earth

BaseCamp Environmental

Figure 1-2
STREET MAP



SOURCE: Stockton West USGS Map, 1968, T1N, R6E. No Section number exists for this site



SOURCE: Google Earth




Figure 1-5
ASSESSOR PARCEL MAP

2.0 SUMMARY

2.1 PROJECT DESCRIPTION

The project site is located at 429-431 and 435 to 437 S. San Joaquin Street in the City of Stockton. The proposed project includes the demolition of two existing buildings and construction of a three-story dormitory for homeless people. The proposed dormitory would include 14,577 square feet of floor area which would provide sleeping rooms accommodating one to four beds, a classroom or common area, common rest-shower rooms, commercial and resident laundry, computer center, counseling offices, janitorial-supply room and either a classroom or recreation room on each floor. Utility services would be extended to the site from existing City water, sewer, storm drain and public utility lines in S. San Joaquin Street. An elevator would provide ADA access throughout the building. The building would be capable of accommodating up to 178 homeless persons under pandemic or other overflow conditions.

The proposed dormitory is consistent with the current Stockton General Plan designation of Commercial, and the current zoning of CG General Commercial. The project could require City approval of a Use Permit. The project development would also require Site Plan/Design Review and parking waiver that would be issued at the staff level.

2.2 ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

The potentially significant impacts of the project, and the mitigation measures proposed to minimize these effects, are shown in Table 2-1 at the end of this chapter. Table 2-1 provides an indication of the significance of impacts, both before and after application of available mitigation measures. With proposed mitigation measures, all the potentially significant impacts of the project would be reduced to a level that is less than significant with the exception of one cultural resources effect which is considered significant and unavoidable.

2.3 AREAS OF CONTROVERSY

A NOP for this EIR was issued with a request for comment from public agencies and interested persons. Table 1-1 lists the five comment letters received in response to the NOP. Responses to the NOP advised the City of various regulatory requirements, which are discussed in this EIR. The responses did not raise any substantive environmental issues or concerns.

2.4 SUMMARY OF ALTERNATIVES

Chapter 18.0, Alternatives, identifies and discusses reasonable alternatives to the proposed project. Only one such alternative was identified – the No Project Alternative. The alternatives analysis briefly considered but declined further analysis of Alternative Sites, Alternative Site Design and a Reduced Development Alternative.

The No Project Alternative would eliminate or avoid the potential environmental effects of the proposed project, including the demolition of two existing buildings on the site. However, the No Project Alternative would not meet the objectives of the proposed project in terms of providing shelter for homeless persons. It is likely that the existing buildings on the site will need to be demolished whether or not the project is approved.

2.5 SUMMARY OF OTHER CEQA ISSUES

Chapter 19.0, Other CEQA Issues, discusses significant environmental impacts of the project that cannot be avoided or mitigated to a level that would be less than significant. One significant and unavoidable environmental effect is identified in the EIR: the loss of historical resources with the proposed demolition of two existing residential buildings.

Irreversible environmental commitments associated with the project were analyzed. The project would involve the irreversible commitment of construction materials to the construction of building and supporting infrastructure. These materials would not be used in highly significant or unusual quantities when compared to similar projects and would be obtained from existing commercial sources. The project site has already been committed to urban use, which would be unchanged by the project.

The potential growth-inducing impacts of the project were evaluated. The proposed project is within a developed urban area, and existing infrastructure is available. The project would help meet existing shelter needs for homeless persons, which are a significant presence in the project area. The project is not expected to encourage any other new development in the area. The project would not have a growth-inducing impact.

Although not incorporated as part of CEQA, the State of California has recently emphasized the incorporation of environmental justice in land use and environmental planning. The project site is within Census Tract 6077000700, which is defined as a disadvantaged community; thus, environmental impacts in this area could involve potential environmental justice issue. This EIR does not identify any potential environmental impacts that could affect members of the disadvantaged community. By increasing the availability of shelter for homeless persons, the project would have beneficial impacts for the population in the area.

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
4.0 AESTHETICS AND VISUAL RESOURCES			
Impact AES-1: Scenic Vistas. There are no scenic vistas within the project area.	NI	None required.	-
Impact AES-2: Scenic Resources. There are no significant scenic resources on the project site.	LS	None required.	-
Impact AES-3: Visual Character and Quality. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact AES-4: Light and Glare. This issue area will have a less than significant effect on the project site.	LS	None required.	.
5.0 AIR QUALITY			
Impact AIR-1: Consistency with Air Quality Plans and Standards. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact AIR-2: Exposure of Sensitive Receptors to Pollutants. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact AIR-3: Odors and Other Emissions. This project area will have no impact.	NI	None required.	-
6.0 BIOLOGICAL RESOURCES			
Impact BIO-1: Special-Status Species and Habitats. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact BIO-2: Riparian and Other Sensitive Habitats. This issue area will have a less than significant effect on the project site.	LS	None required.	-

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
Impact BIO-3: Waters of the U.S. and Wetlands. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact BIO-4: Fish and Wildlife Migration. This issue area will have a less than significant effect on the project site.	LS	None required	-
Impact BIO-5: Local Biological Resource Policies and Ordinances. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact BIO-6: Habitat Conservation Plans. This issue area will have a less than significant effect on the project site.	LS	None required.	-
7.0 CULTURAL RESOURCES AND TRIBAL CULTURAL RESOURCES			
Impact CULT-1: Historical Resources. This issue area will have a less than significant effect on the project site.	PS	CULT-1: GCRM shall take reasonable steps to make the two residential buildings on the site available for acquisition and relocation prior to demolition, provided that all costs, insurance, permitting and other related requirements will be borne by the buyer. CULT-2: GCRM will complete required HABS documentation for the two existing buildings and submit the documentation to the City for review and a determination as to where and how the documentation should be filed.	Significant Unavoidable
Impact CULT-2: Archaeological Resources. This is a potentially significant issue area.	PS	CULT-3: If any subsurface cultural resources are encountered during construction of the project, all construction activities within 50 feet of the encounter shall be halted until a qualified archaeologist can examine these materials, determine their significance, and if significant recommend further mitigation measures that would reduce potential effects to a level that is less than significant. Recommended mitigation measures could include, but are	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
		not limited to, 1) preservation in place, or 2) excavation, recovery, and curation by qualified professionals. The City of Stockton Community Development Department shall be notified, and the project developer shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in a written report to the City's Community Development Department, consistent with the requirements of the CEQA Guidelines. CULT-4: If burial resources or tribal cultural resources are discovered, the archaeologist and/or City shall notify the appropriate tribal representative, who may examine the materials with the archaeologist and advise the City as to their significance. The archaeologist, in consultation with the tribal representative if contacted, shall recommend mitigation measures needed to reduce potential cultural resource effects to a level that is less than significant in a written report to the City, with a copy to the tribal representative. The City shall be responsible for implementing the report recommendations. Avoidance is the preferred means of disposition of tribal cultural resources. The contractor shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in written reports to the City.	
Impact CULT-3: Human Burials. This is a potentially significant issue area.	PS	CULT-5: If project construction encounters evidence of human burial or scattered human remains, the contractor shall immediately notify the County Coroner and the Stockton Community Development Department. On advice from the NAHC, the Community Development Department notify the appropriate tribal representatives and other federal and State agencies as required. The City will be responsible for compliance with the requirements of California Health and	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
		Safety Code Section 7050.5 and with any direction provided by the County Coroner. CULT-6: If the human remains are determined to be Native American, the County Coroner shall notify the Native American Heritage Commission, which will notify and appoint a Most Likely Descendant. The Most Likely Descendant shall work with the City and a qualified archaeologist to decide the proper treatment of the human remains and any associated funerary objects in accordance with California Public Resources Code Sections 5097.98 and 5097.991. Avoidance is the preferred means of disposition of the burial resources.	
Impact CULT-4: Tribal Cultural Resources. This is a potentially significant issue area.	PS	CULT-7: If any subsurface archaeological resources, including human burials and associated funerary objects, are encountered during construction, all construction activities within a 50-foot radius of the encounter shall be immediately halted until a qualified archaeologist can examine these materials and evaluate their significance. The City shall be immediately notified in the event of a discovery. If burial resources or tribal cultural resources are discovered, the City shall notify the appropriate tribal representative, who may examine the materials with the archaeologist and advise the City as to their significance. The archaeologist, in consultation with the tribal representative if contacted, shall recommend mitigation measures needed to reduce potential cultural resource effects to a level that is less than significant in a written report to the City, with a copy to the tribal representative. The City shall be responsible for implementing the report recommendations. Avoidance is the preferred means of disposition of tribal cultural resources. The contractor shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
		mitigation efforts in written reports to the City.	
8.0 GEOLOGY AND SOILS			
Impact GEO-1: Faulting and Seismicity. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact GEO-2: Other Geologic Hazards. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact GEO-3: Soil Erosion. This issue area will have a less than significant effect on the project site.	LS	None required	-
Impact GEO-4: Expansive Soils. This project area will have no impact.	NI	None required.	-
Impact GEO-5: Paleontological Resources and Unique Geological Features. This is a potentially significant issue area.	PS	GEO-1: If any subsurface paleontological resources are encountered during construction of the project, all construction activities within 50 feet of the encounter shall be halted until a qualified paleontologist can examine these materials, determine their significance, and if significant recommend further mitigation measures that would reduce potential effects to a level that is less than significant. Recommended measures could include, but are not limited to, 1) preservation in place, or 2) excavation, recovery, and curation by qualified professionals. The City of Stockton Development Department shall be notified, and the project developer shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in a written report to the City's Community Development Department, consistent with the requirements of the CEQA Guidelines.	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
Impact GEO-6: Access to Mineral Resources. This project area will have no impact.	NI	None required.	-
9.0 GREENHOUSE GAS EMISSIONS			
Impact GHG-1: Project GHG Emissions and Consistency with Applicable Plans and Policies. This issue area will have a less than significant effect on the project site.	LS	None required.	-
10.0 HAZARDS AND HAZARDOUS MATERIALS			
Impact HAZ-1: Hazardous Material Transportation, Use, and Storage. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact HAZ-2: Hazardous Material Releases. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact HAZ-3: Hazardous Material Sites. This is a potentially significant issue area. A Phase I Environmental Site Assessment (ESA) was prepared for the project site.	PS	HAZ-1: Upon building removal, exposed soils adjacent to the structures shall be analyzed for lead and chlorinated pesticides in comparison to the applicable standard. Soil exceeding allowable contamination standards shall be remediated in accordance with a Phase II study. HAZ-2: If warranted by soil testing results, a Phase II Environmental Site Assessment shall be conducted to determine the location and extent of soil contamination and exceedance of applicable regulatory standards, and to make recommendations for remediation of any contamination determined to present a potential risk to human health. All recommendations shall be implemented prior to the start of building construction.	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
Impact HAZ-4: Airport Hazards. This project area will have no impact.	NI	None required.	-
Impact HAZ-5: Interference with Emergency Vehicle Access and Evacuations. This is a potentially significant issue area.	PS	HAZ-3: Prior to project construction involving work in off-site streets, the contractor shall coordinate with the City Department of Public Works and the Stockton Police Department and the Stockton Fire Department if construction will require road closures or lane restrictions.	LS
Impact HAZ-6: Wildfire Hazards. This issue area will have a less than significant effect on the project site.	LS	None required.	-
11.0 HYDROLOGY AND WATER QUALITY			
Impact HYDRO-1: Surface Water Resources and Quality. This issue area will have a less than significant effect on the project site.	LS	None required	-
Impact HYDRO-2: Groundwater Resources. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact HYDRO-3: Drainage Patterns and Runoff. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact HYDRO-4: Flood Hazards. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact HYDRO-5: Seiche, Tsunami, and Mudflow Hazards. This project area will have no impact.	NI	None required.	-

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
12.0 LAND USE, AGRICULTURE, AND POPULATION			
Impact LUP-1: Division of Communities. This project area will have no impact.	NI	None required.	-
Impact LUP-2: Conflict with Applicable Plans, Policies, and Regulations. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact LUP-3: Conversion of Farmland. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact LUP-4: Agricultural Zoning and Williamson Act. This project area will have no impact.	NI	None required.	-
Impact LUP-5: Indirect Conversion of Agricultural Lands. This project area will have no impact.	NI	None required.	-
Impact LUP-6: Inducement of Unplanned Population Growth. This project area will have no impact.	NI	None required.	-
Impact LUP-7: Displacement of Housing and People. This project area will have no impact.	NI	None required.	-
13.0 NOISE			
Impact NOISE-1: Generation of or Exposure to Noise Levels in Excess of Standards – Project Operations. This issue area will have a less than significant effect on the project site.	LS	None Required	-
Impact NOISE-2: Project Construction Noise. This is a potentially significant issue area.	PS	NOISE-1: Project construction shall be restricted to the hours of 7:00 a.m. to 7:00 p.m. Monday through Saturday. No construction shall occur on Sundays or national holidays without prior approval from the Community Development Director.	LS

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
		NOISE-2: All equipment used on the construction site during all project phases shall be fitted with mufflers in accordance with manufacturers' specifications. Mufflers shall be installed on the equipment at all times on the construction site.	
Impact NOISE-3: Groundborne Vibrations. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact NOISE-4: Airport and Airstrip Noise. This project area will have no impact.	NI	None required.	-
14.0 PUBLIC SERVICES AND RECREATION			
Impact PSR-1: Fire Protection Service. This is a potentially significant issue area.	PS	SERV-1: The developer shall incorporate water supply and other fire suppression and emergency access/response needs in the proposed project design and shall provide for adequate fire control during construction in coordination with the Fire Department.	LS
Impact PSR-2: Police Protection. This is a potentially significant issue area.	PS	The developer shall coordinate with the Stockton Police Department as required to establish adequate security and visibility of the construction site. Measures that the Police Department may require include, but are not limited to, secured fencing around the project site, a licensed uniformed security guard present when the project site is not active, or video surveillance 24 hours per day.	-
Impact PSR-3: Schools. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact PSR-4: Parks and Recreational Facilities. This issue area will have a less than significant effect on the	LS	None required.	-

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
project site.			
Impact PSR-5: Other Public Facilities. This issue area will have a less than significant effect on the project site.	LS	None required.	-
15.0 TRANSPORTATION			
Impact TRANS-1: Conflict with Traffic Plans, Ordinances, and Policies. This issue area will have a less than significant effect on the project site.	LS	None required	-
Impact TRANS-2: Conflicts with Non-Motor Vehicle Transportation Plans This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact TRANS-3: Consistency with CEQA Guidelines Section 15064.3(b). This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact TRANS-4: Safety Hazards. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact TRANS-5: Emergency Access. This issue area will have a less than significant effect on the project site.	LS	None required.	-
16.0 UTILITIES AND ENERGY			
Impact UTIL-1 Wastewater Services and Facilities. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact UTIL-2: Water Services and Facilities. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact UTIL-3: Stormwater Services and Facilities. This project area will have no impact.	NI	None required.	-

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

TABLE 2-1
SUMMARY OF IMPACTS AND MITIGATION MEASURES

Potential Impact	Significance Before Mitigation	Mitigation Measures	Significance After Mitigation
Impact UTIL-4: Solid Waste. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact UTIL-5: Energy and Telecommunications Facilities. This issue area will have a less than significant effect on the project site.	LS	None required.	-
Impact UTIL-6: Project Energy Consumption. This issue area will have a less than significant effect on the project site.	LS	None required.	-
17.0 CUMULATIVE IMPACTS			
		Cumulative impacts are discussed in Chapter 18.0 of the EIR. The project would not involve any considerable contributions to Significant Cumulative Impacts. These impacts are deemed less than significant.	

Notes: PS = Potentially Significant, LS = Less than Significant, NI = No Impact, NA = Not Applicable

3.0 PROJECT DESCRIPTION

3.1 PROJECT LOCATION

The Gospel Center Rescue Mission's (GCRM) proposed Homeless New Life Dormitory is located at 429-431 and 435 to 437 S. San Joaquin Street in Stockton, California (see Figures 1-1 to 1-5). The project site consists of one parcel, identified as Assessor Parcel Number (APN) 149-066-070. The site is shown in an un-sectioned portion of U.S. Geological Survey's Stockton West, California, 7.5-minute quadrangle map as being within Township 1 North and Range 6 East of the Mt. Diablo Base and Meridian. The approximate latitude and longitude of the project site is 37º 56' 55" North and 121º 17' 11" West, respectively.

3.2 PROJECT OBJECTIVES

Homelessness in Stockton is a significant problem being addressed by the City and several non-profit agencies including the GCRM. The need for beds greatly exceeds availability. GCRM currently operates a total of 225 women's and 131 men's homeless beds at other sites in the project vicinity but can only meet a portion of the community need for housing.

The objective of the proposed New Life Men's Building project is to expand existing housing availability and support opportunities for homeless persons by construction of the proposed dormitory building at 435 South San Joaquin Street. Expansion of bed capacity will allow GCRM to extend sleeping quarters, food service, medical care, counseling and other services to men committed to recovering from addiction.

Proposed building construction requires demolition of the two buildings; building demolition is integral to the project objectives. The two existing buildings provide a total of 19 existing beds that would be replaced by the proposed facility.

3.3 PROJECT DETAILS

The proposed project includes the demolition of two existing residential structures and the construction of one new three story 144-bed homeless persons shelter building. Additional project components include pedestrian circulation and utility improvements. Figure 3-1 shows the project site plan. Figures 3-2 through 3-4 show the typical floor plan and exterior appearance of the building.

The proposed building would provide a total of approximately 14,577 square feet of floor area including sleeping rooms accommodating from one to four beds, a classroom or

common area, common rest-shower rooms, commercial and resident laundry, computer center, counseling offices, janitorial-supply room and either a classroom or recreation room on each floor. An elevator would provide ADA access throughout the building. The normal capacity of the building would be 144 persons, but additional overflow capacity of up to 178 beds can be accommodated for disaster relief or winter shelter

Non-building portions of the site would consist of required adjacent building offsets, pedestrian ways, no parking areas, and no landscaping. Utility services would be extended to the site from existing City water, sewer, storm drain and public utility lines in S San Joaquin Street.


Project architecture features vertical and horizontal variations in wall surfaces, materials and color, and a range of complementary exterior finishes including splitface CMU on the ground floor, and brick and stucco on the second and third floors.

The existing site and vicinity are shown in photos included in Chapter 4.0. The appearance and design of the proposed building are shown in Chapter 3.0 together with proposed exterior finishes also shown in the appendix.

During construction replacements for the 19 existing beds would be provided elsewhere on the GCRM campus.


3.4 PERMITS AND APPROVALS

The proposed men's facility is consistent with the current Stockton General Plan designation of Commercial, and it is permitted under the current zoning CG – General Commercial with a Commission Use Permit, which requires the approval of the Stockton Planning Commission. Specific development standards for emergency shelters are established in Section 16.80.155 of the Stockton Development Code. Homeless shelters are permitted "by right" only in the IL and IG industrial and PF Public Facilities zones. The project would require Design Review approval which is granted at the staff level as a non-discretionary approval.



SOURCE: WMB Architects

Figure 3-1
PROJECT SITE



SOURCE: WMB Architects

Figure 3-2
FLOOR PLANS



SOURCE: WMB Architects

Figure 3-3
ELEVATIONS



SOURCE: WMB Architects

Figure 3-4
ARCHITECTUAL RENDERINGS

4.0 AESTHETICS AND VISUAL RESOURCES

ENVIRONMENTAL SETTING

Aesthetics/Visual Resource Background

Aesthetic values and sensitivity vary significantly from person to person, which makes aesthetic and visual resource impacts challenging to assess. The following analysis provides a qualitative assessment of the project's effect on aesthetic and visual resource values.

Visual/aesthetic values of a geographic area are a function of the character of the landscape or built environment, the distance between the affected landscape and viewers, and the number and sensitivity of those viewers to change. Landscape or built environment character may be defined as distinctive, common, or minimal; "distinctive" viewscapes in urban areas being those with unique or aesthetically pleasing design or landscaping elements. View distance in urban areas is generally a foreground area. Viewer sensitivity is related to the nature and expectations of users. Areas of high sensitivity could include recreation sites, scenic routes or areas with high of architectural or historic interest.

A recent change to the Environmental Checklist in CEQA Guidelines Appendix G emphasizes aesthetic and visual resource impacts on public views in non-urbanized areas. As defined in Appendix G, "public views" are views that are experienced from publicly accessible vantage points. Although not specifically defined, "publicly accessible vantage points" are assumed to include, though not necessarily limited to, public roads, parks, trails, and vista turnouts. For this project, publicly accessible vantage points would include public streets in the immediate vicinity of the project site. The appearance of the site and surrounding lands are illustrated on Figures 4-1, 4-2 and 4-3.

Aesthetic/Visual Resources on Project Site and in Vicinity

The project site and vicinity are 100% urbanized. Lands on and surrounding the site are densely developed with commercial and residential structures with relatively small street setbacks. Most of these structures, were constructed in first half of the 20th century and are of historic age. However, property conditions vary widely; most of the older structures are in deteriorated condition; many are vacant or boarded up. The project neighborhood is frequented by a large proportion of the City's homeless population.

As a result of the developmental density and surrounding structure height, there are no scenic vistas available from the site or vicinity. There are no notable trees, rocks or other scenic resources in the project site or vicinity.

The project site contains two multi-family/two-story residential buildings of historic age but in relatively poor condition. GCRM utilizes these buildings to provide shelter to homeless persons. These structures their age condition and historic values are discussed in more detail in Chapter 8.0 Cultural Resources. Figures 4-1 and 4-2 show these existing buildings.

Neither building is of notable aesthetic importance; Each has a small porch and front yard turf area which is obscured by six-foot steel ("wrought iron") fencing, and landscaping is minimal. Views of and from the back of the properties include a small, paved parking area accessed from the south and nearby GCRM buildings including the GCRM offices, loading docks, clinic and Women's Center buildings adjacent to the site. The rear exterior of two on-site structures have been substantially modified to extend the life of these deteriorating buildings and allow their use for homeless shelter. Safety features, plumbing and electrical improvements have been accomplished on the outside of the building. Portions of the original siding have been replaced with plywood.

Lands surrounding the project area are in mixed urban uses. Project views east and south consist of older residential and multi-family residential buildings, a small corner store, the Gospel Rescue Mission campus buildings, boarded up buildings and a Jene Wah, Inc., a center for Chinese elderly. Views south along South San Joaquin Street include the relatively wide street, sidewalks, street trees, mixed commercial and residential uses, vacant lots and electrical transmission lines. Views north of the project site include the Gleason Center, the GCRM Women's Shelter, the Cosmos Hotel and mixed residential uses. Views to the north along South San Joaquin Street include sidewalks, cars, fence lines, some trees, the Crosstown Freeway overcrossing and downtown multi-story buildings in the background.

Existing lighting in the project vicinity consists of street lighting at existing intersections with South San Joaquin Street and security lighting on the site, nearby properties and the parking areas in the rear areas of these properties.

REGULATORY FRAMEWORK

California Scenic Highway Program

California's Scenic Highway Program was created by the Legislature in 1963 to preserve and protect scenic highway corridors from change which would diminish the aesthetic value of lands adjacent to highways. The state laws governing the Scenic Highway Program are found in the Streets and Highways Code, Section 260 *et seq*. A highway may be designated scenic depending upon how much of the natural landscape can be seen by travelers, the scenic quality of the landscape, and the extent to which development intrudes upon the traveler's enjoyment of the view.

The State Scenic Highway System list, maintained by the California Department of Transportation (Caltrans), includes highways that are either designated as scenic highways or are eligible for such designation. There are only two officially designated

State Scenic Highways within San Joaquin County: portions of Interstate 5 and 580 in the southwest portions of the County (Caltrans 2018). The City of Stockton does not include any designated scenic highways.

City of Stockton Municipal Code

As required by Stockton Development Code, the project requires City approvals for a Use Permit and Design Review. The purpose of these reviews is to assure design compatibility, harmony in appearance in neighborhoods, reduction of negative aesthetic impacts and orderly development of the community. Use Permit approval is the responsibility of the Stockton Planning Commission. Design Review occurs in the Community Development at the staff level.

City of Stockton Design Guidelines

The City has adopted Design Guidelines, which provide standards for physical design of new commercial, industrial and multi-family residential uses, including site planning, architecture, use of open spaces, lot configurations, circulation, and similar issues (City of Stockton 2004). The Design Guide serves as a reference for use by City staff, the Planning Commission, the City Council in their review of new development projects, and by the development community during project planning and design.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on aesthetics and visual resources if it would:

- Have a substantial adverse effect on a scenic vista,
- Substantially damage scenic resources, including but not limited to trees, rock outcroppings, and historic buildings within a state scenic highway),
- In non-urbanized areas, substantially degrade the existing visual character or quality of public views of the site and its surroundings; or, if the project is in an urbanized area, conflict with applicable zoning and other regulations governing scenic quality, or
- Create a new source of substantial light or glare which would adversely affect day or nighttime views in the area.

A recent revision to the aesthetics questions in Appendix G notes California Public Resources Code Section 21099, which states that the aesthetic and parking impacts of residential, mixed-use residential, or employment center projects on an infill site within a transit priority area shall not be considered significant effects under CEQA. The project is

residential in nature but is not located in a transit priority area and is, therefore, exempt from Public Resources Code Section 21099.

Impact AES-1: Scenic Vistas

The project proposes the construction of a new three-story structure in an area dominated by multi-story structures. The project would be comparable in height to existing structures and would not result in any known or substantial view blockage. There are, in any event, no scenic vistas available on the site or in the project vicinity; the project would have no impact on scenic vistas.

Level of Significance: No impact

Mitigation Measures: None required

Impact AES-2: Scenic Resources

The project site is a developed urban parcel containing existing multi-family residential structures in poor condition. Existing structures would be demolished and replaced by the proposed GCRM men's facility.

The project site does not contain any existing scenic resources of significance, such as mature native trees or rock outcroppings. There are no State Scenic Highways or locally designated scenic roads in the project area. Consequently, development of the project would have no adverse impact on existing scenic resources.

Existing residential buildings on the project site are of historic age and may be considered a historic resource. See Chapter 8.0 Cultural Resources. Apart from these historical distinctions, which are addressed in Chapter 8.0 Cultural Resources of this document, these dilapidated residential buildings are not of aesthetic importance.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact AES-3: Visual Character and Quality

The proposed men's residential facility structure would be consistent in height and design with other commercial, emergency shelter and high-density residential land uses in the vicinity. The appearance of the project (Figures 3-3 and 3-4) would result in a substantial change and improvement in on-site aesthetics as viewed from S. San Joaquin Street and adjoining land uses. This change would represent revitalization of the neighborhood, consistent with the existing General Plan designation and zoning.

The project will include removal of the existing wrought iron fencing that encloses the site and its replacement by the architect-designed building (see Figures 3-3 and 3-4). The project will also include the replacement of deteriorated sections of sidewalk, curb and gutter of the adjoining section of San Joaquin Street.

The proposed structure would be subject to City of Stockton design requirements and would contribute to the ongoing revitalization of the Stockton downtown area. The project would not involve any adverse aesthetic impact as viewed from the adjacent streets, which are the main public viewing areas in the project vicinity.

The proposed project would be subject to Design Review by the City, which is intended to promote consistency in appearance and design of neighborhoods and to reduce aesthetic impacts of new development. The project also would be required to comply with other applicable standards of the Stockton Development Code. As a result, project impacts on visual quality would be beneficial and, in any event less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact AES-4: Light and Glare

The project would replace existing security lighting of existing structures on the site with updated building lighting systems that would improve illumination of the site as well as the adjacent streetscape. The project would implement a Lighting Plan that would be consistent with California's 2016 Building Energy Efficiency Standards, Title 24, Part 6, which includes lighting controls such as the use of light-emitting diode fixtures, time switches, and motion sensors for all exterior lighting. Pole-mounted light fixtures would be appropriately angled to minimize light and glare effects on nearby properties.

Project plans will be required to identify any exterior light sources and areas subject to potential off-site illumination. Additional lighting in the area would be generally considered beneficial, but potential off-site lighting impacts would be subject to detailed consideration during City design review. Additional lighting control measures needed to reduce indirect illumination of adjacent properties, if necessary, would be prescribed during this process. As a result, project impacts on light and glare would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required



Existing residential structures , 435-437 S. San Joaquin Street



Existing residential structures , 429-431 S. San Joaquin Street



View north along S San Joaquin from vicinity of project site



View south along S San Joaquin from vicinity of project site

Figure 4-2
PROJECT NEIGHBORHOOD VIEWS - GROUND



BaseCamp Environmental

Figure 4-3
PROJECT NEIGHBORHOOD VIEW-AERIAL

5.0. AIR QUALITY

This chapter analyzes impacts on air quality, specifically as they relate to pollutants regulated by federal and California Clean Air Acts. Greenhouse gases (GHGs), gases that trap heat generated by the sun, are regulated separately from other air pollutants. Chapter 9.0, Greenhouse Gas Emissions, discusses the potential environmental impacts of the project as they relate to GHG emissions.

ENVIRONMENTAL SETTING

The project site is within the San Joaquin Valley Air Basin. The San Joaquin Valley Air Pollution Control District (SJVAPCD), which includes San Joaquin County and Stockton, has jurisdiction over most air quality matters in the Air Basin. The SJVAPCD is tasked with implementing programs and regulations required by both the federal and California Clean Air Acts. Under their respective Clean Air Acts, both the State of California and the federal government have established ambient air quality standards for six criteria air pollutants: ozone, particulate matter, carbon monoxide, nitrogen dioxide, sulfur dioxide, and lead. California has standards for four additional criteria pollutants under its Clean Air Act.

Air Pollutants

Pollutants of concern in the Stockton area include the following:

- Ozone. Ozone is not directly produced by automobile fuel combustion; rather, it is a secondary pollutant that is formed from reactive organic gases (ROG) and nitrogen oxides (NO_x) in the presence of sunlight. Automobile emissions represent the principal source of these pollutants. Ozone causes eye irritation and respiratory function impairment. It also damages natural ecosystems, agricultural crops, and manmade materials such as rubber and plastics. To control ozone pollution, it is necessary to control emissions of ROG and NO_x.

- Particulate Matter and Fine Particulate Matter (PM_{10} and $PM_{2.5}$). Particulates include any solid matter suspended in air. Standards are applied to particulates less than 10 micrometers in diameter (PM_{10}), because these particles (when inhaled) are not filtered out prior to reaching the lungs, where they can aggravate respiratory diseases. Particulates originate from automobile traffic, urban construction, grading, farm tilling, and other activities that expose soil and dust. Dry summer conditions and daily winds can increase particulate concentrations.

  Separate standards have been established for particulate matter that is 2.5 micrometers or less in size ($PM_{2.5}$), sometimes referred to as "fine particulate matter." The $PM_{2.5}$ standards reflect additional health concerns related to

respiration of these smaller particles, which may be drawn deeper into the lungs. Fine particulates include sulfates, nitrates, organics, ammonium, and lead compounds originating from activities in urban areas.

- Carbon Monoxide (CO). The primary source of CO emissions in the project vicinity is from the combustion of petroleum fuel, particularly from automobiles. Because of its ability to readily combine with hemoglobin and displace oxygen in the human body, high levels of CO can produce hazardous conditions, especially for elderly people or individuals with respiratory ailments, including fatigue, headache, confusion, and dizziness.

In 2019, approximately 1,017 tons of ROG and 218 tons of NO_x were emitted each day from sources in the San Joaquin Valley Air Basin. Approximately 316 tons of PM_{10}, of which approximately 103 tons were $PM_{2.5}$, were emitted daily. Areawide sources account for most of the ROG emissions; major sources include farming operations, solvent evaporation, cleaning and surface coatings, and waste disposal. Major sources of PM_{10} emissions are also areawide; these include farming operations, road and fugitive windblown dust, and wildfires. Most of the NO_x emissions were caused primarily by mobile sources, i.e., motor vehicles. Wildfires were a major source of CO emissions in 2019, along with mobile sources (ARB 2020a).

Toxic Air Contaminants

Toxic air contaminants (TACs) are of particular concern. TACs are non-criteria pollutants that cause or may cause cancer or other serious health effects such as birth defects, neurological disorders, or chronic eye, lung, or skin irritation, along with adverse environmental and ecological effects. The State's Air Toxics Inventory includes more than 250 substances considered TACs (ARB 2008a). Most of these TACs are emitted by industrial processes and thus are confined to industrial facilities.

Diesel particulate matter (diesel PM) is designated by the State of California as a TAC. Diesel PM, a potential source of both cancer and non-cancer health effects, is of concern because it is present at some concentration in all developed areas of the state. The California Air Resources Board (ARB) has identified diesel PM as a major contributor to ambient cancer risk levels; while diesel PM accounts for only about 4% of air toxic emissions in the state, it accounted for more than 70% of the 2000 cancer risk associated with outdoor ambient levels of all TACs. General risks can be elevated with proximity to the source, which for diesel PM includes freeways, ports and railyards, and distribution centers (ARB 2005), as well as other locations of concentrated diesel engine use. No such sources are located in the immediate project vicinity.

REGULATORY FRAMEWORK

Federal Clean Air Act

Federal air quality regulation stems from the federal Clean Air Act. The Clean Air Act requires the U.S. Environmental Protection Agency (EPA) to establish air quality standards for criteria pollutants, which are known as the National Ambient Air Quality Standards. As shown in Table 5-1, the Clean Air Act establishes six criteria pollutants: ozone, carbon monoxide, particulate matter, nitrogen dioxide, sulfur dioxide and lead. The adopted primary standards are designed to protect human health, based on EPA medical research and specific concentration thresholds derived therefrom. Secondary standards are intended to protect the public welfare from effects such as visibility reduction, soiling, nuisance, and other forms of damage.

Regions of the country are classified with respect to their attainment or nonattainment of these standards. The Clean Air Act requires the states to submit a State Implementation Plan for nonattainment areas. The State Implementation Plans are reviewed and approved by the EPA, subject to a determination of their adequacy in demonstrating how the federal standards will be achieved. Table 5-2 shows the corresponding attainment/nonattainment designations for the Air Basin.

State Laws

California Clean Air Act

The California Clean Air Act provides the planning framework for California air quality. It establishes the State's own set of ambient air quality standards for criteria pollutants, known as the California Ambient Air Quality Standards (see Table 5-1). The state standards are generally more stringent than the corresponding federal standards; in addition, the state standards cover four other pollutants besides the six criteria pollutants of the federal Clean Air Act. Responsibility for implementation of the California Clean Air Act requirements, and for preparation of the State Implementation Plan under the Clean Air Act, rests with the ARB; the local air pollution or air quality management districts are responsible for preparation of the Air Quality Attainment Plan, which are input to the State Implementation Plan.

Areas where these standards are exceeded are considered "nonattainment" areas and are subject to more intensive air quality management and more stringent regulation. Table 5-2 shows the attainment status of the Air Basin for state ambient air quality standards. The Air Basin is designated Nonattainment/Extreme by the federal government, and Nonattainment/Severe by the state, for ozone. Both the state and federal governments classify the basin as Nonattainment for fine particulate matter ($PM_{2.5}$). The state also classifies the basin as Nonattainment for particulate matter (PM_{10}). Except for the Fresno urbanized area, the Air Basin is in attainment of, or unclassified for, carbon monoxide and other applicable standards. The California Clean Air Act requires areas that are

designated nonattainment to achieve a 5% annual reduction in emissions until the standards are met.

TABLE 5-1
NATIONAL AND CALIFORNIA AMBIENT AIR QUALITY STANDARDS

Air Pollutant	Averaging Time	California Standards	Primary National Standards[1]	Secondary National Standards[2]
Ozone	1 Hour	0.090 ppm	--	--
	8 Hour	0.070 ppm	0.070 ppm	0.070 ppm
PM_{10}	24 Hour	50 µg/m^3	150 µg/m^3	150 µg/m^3
	Annual Mean	20 µg/m^3	--	--
$PM_{2.5}$	24 Hour	--	35 µg/m^3	35 µg/m^3
	Annual Mean	12 µg/m^3	12 µg/m^3	15 µg/m^3
Carbon Monoxide	1 Hour	20 ppm	35 ppm	--
	8 Hour	9 ppm	9 ppm	--
Nitrogen Dioxide	1 Hour	0.18 ppm	100 ppb	--
	Annual Mean	0.030 ppm	0.053 ppm	0.053 ppm
Sulfur Dioxide	1 Hour	0.25 ppm	75 ppb	--
	3 Hour	--	--	0.5 ppm
	24 Hour	0.04 ppm	0.14 ppm*	--
	Annual Mean	--	0.030 ppm*	--
Lead	30 Day Avg.	1.5 µg/m^3	--	--
	Calendar Qtr.	--	1.5 µg/m^3	1.5 µg/m^3
	3 Month Average	--	0.15 µg/m^3	0.15 µg/m^3
Sulfates	24 Hour	25 µg/m^3	N/A	N/A
Hydrogen Sulfide	1 Hour	0.03 ppm	N/A	N/A
Vinyl Chloride	24 Hour	0.01 ppm	N/A	N/A
Visibility Reducing Particles	8 Hour	Extinction coefficient of 0.23 per kilometer.	N/A	N/A

Notes: ppm – parts per million; ppb – parts per billion; µg/m^3– micrograms per cubic meter; N/A – not applicable
[1] National Primary Standards: The levels of air quality necessary, with an adequate margin of safety, to protect the public health.
[2] National Secondary Standards: The levels of air quality necessary to protect the public welfare from any known or anticipated adverse effects of a pollutant.
* For certain areas.
Source: ARB 2016.

TABLE 5-2
SAN JOAQUIN VALLEY AIR BASIN ATTAINMENT STATUS

	Designation/Classification	
Pollutant	**Federal Primary Standards**	**State Standards**
Ozone - One hour	No Federal Standard[a]	Nonattainment/Severe
Ozone - Eight hour	Nonattainment/Extreme[b]	Nonattainment
PM_{10}	Attainment[c]	Nonattainment
$PM_{2.5}$	Nonattainment[d]	Nonattainment
Carbon Monoxide	Attainment/Unclassified	Attainment/Unclassified
Nitrogen Dioxide	Attainment/Unclassified	Attainment
Sulfur Dioxide	Attainment/Unclassified	Attainment
Lead (Particulate)	No Designation/Classification	Attainment
Hydrogen Sulfide	No Federal Standard	Unclassified
Sulfates	No Federal Standard	Attainment
Visibility Reducing Particles	No Federal Standard	Unclassified
Vinyl Chloride	No Federal Standard	Attainment

[a] Effective June 15, 2005, EPA revoked the federal 1-hour ozone standard, including associated designations and classifications. EPA had previously classified the Air Basin as Extreme nonattainment for this standard. EPA approved the 2004 Extreme Ozone Attainment Demonstration Plan in 2010. Many applicable requirements for Extreme 1-hour ozone nonattainment areas continue to apply to the Air Basin.

b Though the Valley was initially classified as Serious nonattainment for the 1997 8-hour ozone standard, EPA approved Valley reclassification to Extreme nonattainment in the Federal Register in 2010.

[c] In 2008, the U.S. Environmental Protection Agency (EPA) redesignated the San Joaquin Valley to attainment for the PM_{10} National Ambient Air Quality Standard (NAAQS) and approved the PM_{10} Maintenance Plan.

[d] The Valley is designated nonattainment for the 1997 $PM_{2.5}$ NAAQS. EPA designated the Valley as nonattainment for the 2006 PM2.5 NAAQS in 2009.

Source: SJVAPCD 2020.

Toxic Air Contaminants

The State regulates TACs primarily through the Tanner Air Toxics Act (AB 1807) and the Air Toxics Hot Spots Information and Assessment Act of 1987 (AB 2588). Under these programs, the State is responsible for an inventory of TACs, for analysis of exposure and risk and for planning to reduce risk. Like other federal and state air quality requirements, the various elements of the state air toxics program are implemented by the local air districts.

San Joaquin Valley Air Pollution Control District

Projects within the Air Basin are subject to the regulatory authority of the San Joaquin Valley Air Pollution Control District (SJVAPCD), which implements and enforces air quality regulations in eight counties, from San Joaquin County in the north to western Kern County in the south. The SJVAPCD's responsibilities include air quality standard attainment planning, regulation of emissions from non-transportation sources, and mitigation of emissions from on-road sources.

Air Quality Plans

Air quality plans adopted by the SJVAPCD to meet Clean Air Act standards include the 1-Hour and 8-Hour Ozone Plan, the PM_{10} Plan and the $PM_{2.5}$ Plan. All the plans include measures that would be implemented through rule making or program funding to reduce air pollutant emissions in the Air Basin. SJVAPCD Rules address the potential air quality impacts of new development.

Rules and Regulations

Likewise, the SJVAPCD has adopted several regulations that are directly applicable to new development projects. These regulations include

> *Regulation VIII, w*hich addresses control of fugitive dust generation during construction and demolition activities,
>
> *Rule 4101, which* prohibits emissions of visible air contaminants to the atmosphere and applies to any source operation that emits or may emit air contaminants,
>
> *Rule 4601, which* limits emissions of volatile organic compounds from architectural coatings, and
>
> *Rule 9510,* also known as the Indirect Source Rule, requires reduction or mitigation of NO_x and PM_{10} emissions from new development. Rule 9510 applies to residential development projects of at least 50 units.

Significance Thresholds

According to the recently updated Appendix G of the CEQA Guidelines, a project may have a significant impact on air quality if it would:

- Conflict with or obstruct implementation of an applicable air quality plan,
- Result in a cumulatively considerable net increase of any criteria pollutant for which the project region is non-attainment under an applicable federal or state ambient air quality standard [Chapter 17.0, Cumulative Impacts, discusses the potential cumulative air quality impacts of the project],
- Expose sensitive receptors to substantial pollutant concentrations, or
- Result in other emissions, such as those leading to odors, adversely affecting a substantial number of people.

CEQA Guidelines Appendix G states that, where available, significance criteria established by the applicable air quality management or air pollution control district may be relied upon to make significance determinations. In 2015, the SJVAPCD adopted a revised Guide for Assessing and Mitigating Air Quality Impacts (GAMAQI). The GAMAQI defines methodology and thresholds of significance for the assessment of air quality impacts for projects within SJVAPCD's jurisdiction, along with mitigation measures for identified impacts.

Table 5-3 below shows predicted criteria pollutant emissions associated with project construction and operation in comparison to the air quality impact significance thresholds established by SJVAPCD in the GAMAQI. Operational emissions are limited by the very low vehicular trip generation associated with the project. The population of the Homeless New Life Dormitory will in almost all cases be composed of non-drivers. The values shown in Table 5-3 are overstated, and probably substantially so. The CalEEMod model used to predict emissions does not provide inputs for emergency shelter land uses. To provide approximate but conservative values for the project, the model's land use selection was set for "Retirement Community."

The SJVAPCD's thresholds of significance for criteria pollutants are applied to evaluate regional impacts of project-specific emissions of air pollutants. Regional impacts of a project can be characterized in terms of total annual emissions of criteria pollutants and their impact on SJVAPCD's ability to reach attainment (SJVAPCD 2015).

TABLE 5-3
SJVAPCD SIGNIFICANCE THRESHOLDS AND
PREDICTED PROJECT AIR POLLUTANT EMISSIONS

	ROG	NO_x	CO	SO_x	PM_{10}	$PM_{2.5}$
SJVAPCD Significance Thresholds[1]	**10**	**10**	**100**	**27**	**15**	**15**
Construction Emissions[2]	0.11	0.60	0.72	<0.01	0.06	0.04
Above Threshold?	*No*	*No*	*No*	*No*	*No*	*No*
Operational Emissions[3]	0.12	0.13	0.79	<0.01	0.09	0.03
Above Threshold?	*No*	*No*	*No*	*No*	*No*	*No*

Note: All figures are in tons per year.
[1] Applicable to both construction and operational emissions.
[2] Maximum emissions in a calendar year.
[3] Unmitigated emissions.
Sources: CalEEMod Version 2016.3.2, SJVAPCD 2015.

The SJVAPCD significance thresholds are based on offset thresholds established under the New Source Review program (SJVAPCD Rule 2201). Under New Source Review, all new permitted sources with emission increases exceeding two pounds per day for any criteria pollutant are required to implement best available control technology (BACT). Furthermore, all permitted sources emitting more than the New Source Review offset thresholds for any criteria pollutant must offset all emission increases in excess of the thresholds. The SJVAPCD's attainment plans demonstrate that project-specific emissions below the offset thresholds will have a less-than-significant impact on air quality. Thus, the SJVAPCD concludes that use of the New Source Review offset thresholds as the thresholds of significance for criteria pollutants is an appropriate and effective means of promoting consistency in significance determinations within the environmental review process, and the thresholds are applicable to both stationary and non-stationary emissions sources (SJVAPCD 2015).

Impact AIR-1: Consistency with Air Quality Plans and Standards

Construction and operational air pollutant emissions of the project were estimated using the CalEEMod computer program, a modeling program recommended by SJVAPCD. The CalEEMod results are shown in Appendix B of this EIR and summarized in Table 5-3 above. The unusual nature of the project required that a number of non-standard input values be used in order to more accurately characterize the project's emissions. The estimates shown in Table 5-3 are "unmitigated" emissions, meaning emissions that would otherwise occur without the incorporation of any special project features and conformance with applicable regulations that would mitigate air quality impacts. Chapter 9.0, Greenhouse Gas Emissions, describes some of these conditions and regulations not otherwise addressed below.

As indicated in Table 5-3, the predicted construction and operational emissions of the project would not approach or exceed any of the applicable SJVAPCD significance thresholds. In fact, the predicted emissions would amount to only a fraction of the threshold value. As noted above, since the project-specific emissions are below New Source Review offset thresholds, the project's air pollutant emissions are considered less than significant.

The project may or may not be required to comply with SJVAPCD Rule 9510, due to the unusual nature of the project. If compliance is required, Rule 9510 would require additional reductions of NO_x and PM_{10} from the incidental predicted emissions shown in Table 5-3.

Dust emissions during construction would be limited due to the small size of the site and controlled through required implementation of SJVAPCD Regulation VIII, enforcement of which is the responsibility of the SJVAPCD. Conformance with SJVAPCD dust control standards will be facilitated by inclusion of SJVAPCD dust control requirements in the project conditions of approval.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact AIR-2: Exposure of Sensitive Receptors to Pollutants

"Sensitive receptors" refer to those segments of the population most susceptible to poor air quality (i.e., children, the elderly, and those with pre-existing serious health problems affected by air quality). Land uses where sensitive individuals are most likely to spend time also may be called sensitive receptors; these include schools and schoolyards, parks and playgrounds, daycare centers, nursing homes, hospitals, and residential communities (SJVAPCD 2015). The project is adjacent to and near some existing residential areas that provide predominantly transitional housing.

As noted, project construction and operational emissions would be a fraction of SJVAPCD significance thresholds for criteria pollutants and would involve no concentrated emission sources. Implementation of applicable SJVAPCD rules and regulations may further reduce emissions, making them even less likely to affect nearby sensitive land uses.

CO in high concentrations can have adverse health impacts, as previously described. A CO "hotspot" is an area of localized CO pollution that is caused by severe vehicle congestion on major roadways, typically near intersections. CO hotspots have the potential to expose receptors to emissions that violate state and/or federal CO standard even if the broader Basin is in attainment for federal and state levels. The GAMAQI indicates that a project would create no violations of the CO standards if neither of the following criteria are met (SJVAPCD 2015):

- A traffic study for the project indicates that the Level of Service (LOS) on one or more streets or at one or more intersections in the project vicinity will be reduced

to LOS E or F; or

- A traffic study indicates that the project will substantially worsen an already existing LOS F on one or more streets or at one or more intersections in the project vicinity (See Chapter 15.0, Transportation, for an explanation of LOS).

As noted in Chapter 15.0, Transportation, and in Chapter 17.0, Cumulative Impacts, the project is not expected to result in any significant contribution to traffic or congestion at intersections in the project vicinity. Therefore, the project would have no adverse impact related to CO emissions.

Project construction would involve limited emissions of diesel PM as quantified in Table 5-3. Diesel PM emissions would have adverse effects only for people that experience long-term exposure, and construction emissions would cease once work is completed. No emissions of diesel PM from the project site would occur after construction work is completed, other than possibly from diesel-engine vehicles making occasional visits. Therefore, impacts of diesel PM construction and operational emissions on nearby sensitive receptors are considered less than significant.

Overall, the pollutant emissions estimated to be generated by the project are unlikely to reach nearby sensitive receptors at levels that would have an adverse impact. The potential exposure of sensitive receptors to pollutant emissions would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact AIR-3: Odors and Other Emissions

No other air emissions are associated with the project, other than potentially odors, which are more of a nuisance than an environmental hazard. Nevertheless, the Environmental Checklist in CEQA Guidelines Appendix G regards emission of odors as a potentially adverse significant environmental impact. In accordance with this, the GAMAQI states that a project should be evaluated to determine the likelihood that it would result in nuisance odors (SJVAPCD 2015).

Emergency shelters do not typically generate any substantial odors that could affect nearby land uses. Food service for residents of the project would be provided by other existing GCRM facilities in the immediate project area. The project would not generate substantial amounts of other emissions such as TACs. The project would have no impact related to odors or other emissions.

Level of Significance: No impact

Mitigation Measures: None required

6.0 BIOLOGICAL RESOURCES

ENVIRONMENTAL SETTING

The project site is in an urban, entirely developed area of the city of Stockton. The area in which the project site is located consists of mixed commercial and residential uses. Landscaping is the primary vegetation in the project vicinity, mainly street trees, lawns and shrubbery at residences. Wildlife in the project vicinity would consist mainly of wildlife adaptable to urban areas, primarily birds, rodents and other small mammals. The nearest substantial open space area near the project site are the riparian areas along the Mormon Slough channel, approximately 0.15 miles south of the project site.

Special-status species are plants and animals that are legally protected under the federal Endangered Species Act, the California Endangered Species Act (CESA), or other regulations. Special-status wildlife species also includes species that are considered rare enough by the scientific community and trustee agencies to warrant special consideration, particularly with regard to protection of isolated populations, nesting or denning locations, communal roosts, and other essential habitat.

Preparation of this EIR included a search of the California Natural Diversity Database (CNDDB) that is managed by the California Department of Fish and Wildlife, and a review of the IPaC Trust Resource Report of the U.S. Fish and Wildlife Service. Appendix B contains copies of the CNDDB and IPaC documents. The IPac Report covers San Joaquin County, while the search area for the CNDDB covers the U.S. Geological Survey Stockton West quadrangle map.

According to the CNDDB Quick View Report and the IPaC Trust Resource Report, nine special-status species are known to occur in the search area that includes the project site: one mammal, one reptile, two amphibians, one fish, one insect, two crustaceans, and one plant. Due to past urbanization, there is no suitable habitat for these species on the site or on surrounding lands.

The project site is 100% urbanized. There are no wetlands or surface water resources, riparian area of other sensitive habitat areas located on or adjacent to the site.

REGULATORY FRAMEWORK

San Joaquin County Multi-Species Habitat Conservation and Open Space Plan

The project area is within the coverage area of the San Joaquin County Multi-Species Open Space and Habitat Conservation Plan (SJMSCP), a habitat conservation plan adopted by San Joaquin County and its incorporated cities that provides coverage for new

development under the federal and State Endangered Species Acts. On "greenfield" sites, SJMSCP requires payment of a habitat conservation fee and conformance with Incidental Take Minimization Measures that prevent unnecessary impacts to special-status species (SJCOG 2000). Participation in the SJMSCP will avoid or minimizing impacts on covered special-status species. The project site and most developed areas in Stockton are located with SJMSCP Category A No Fee areas.

City of Stockton Heritage Tree Ordinance

Stockton Municipal Code Chapter 16.130 governs the removal of Heritage Trees, regardless of location on a property or condition of the tree(s). A Heritage Tree is defined as any valley oak, coast live oak, and interior live oak tree which has a trunk diameter of 16 inches or more, measured at 24 inches above actual grade. Except for an emergency removal in compliance with Section 16.130.050, removal of any Heritage Tree requires a City permit. There are no Heritage Trees on or adjacent to the project site.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on biological resources if it would:

- Have a substantial adverse effect, either directly or through habitat modifications, on any species identified as a candidate, sensitive, or special-status species in local or regional plans, policies, or regulations, or by the CDFW or USFWS,
- Have a substantial adverse effect on any riparian habitat or other sensitive natural community identified in local or regional plans, policies, or regulations or by the CDFW or USFWS,
- Have a substantial adverse effect on state or federally protected wetlands (including, but not limited to marsh, vernal pool, coastal wetlands, etc.) through direct removal, filling, hydrological interruption, or other means,
- Interfere substantially with the movement of any native resident or migratory fish or wildlife species or with established native resident or migratory wildlife corridors, or impede the use of native wildlife nursery sites.
- Conflict with local policies or ordinances protecting biological resources, such as a tree preservation policy or ordinance, or
- Conflict with the provisions of an adopted Habitat Conservation Plan, Natural Community Conservation Plan, or other approved local, regional, or state habitat conservation plan.

Impact BIO-1: Special-Status Species and Habitats

The project site is urbanized site located within a broader urban landscape which includes very limited open spaces that provide habitat for special status species. The closest open space area is the Mormon Slough corridor located approximately 0.15 miles south of the project site. The project site and surroundings are extensively disturbed, and do not include any substantial areas of habitat for the potentially occurring special-status species described in the Environmental Setting section above and listed in Appendix E.

The project would involve demolition and new construction on this urbanized site, which would perpetuate its existing urbanized condition for the long term. While construction could involve temporary impacts on species commonly found in an urbanized environment, it is unlikely that any special-status species would be adversely affected by project construction or its operations, and therefore the project would have a less than significant effect on special-status species.

The project site is within the coverage area of the San Joaquin County Open Space and Habitat Conservation Plan (SJMSCP). Participation in the SJMSCP would further reduce any other potential special-status species effects of the project to a less than significant level.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact BIO-2: Riparian and Other Sensitive Habitats

The project site is not located on, adjacent to or near any stream or surface water resource. No riparian habitat exists on the site. No sensitive natural communities have been identified on or adjacent to the project site. The project would have no impact on sensitive habitats.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact BIO-3: Waters of the U.S. and Wetlands

No potentially jurisdictional Waters of the U.S. or wetlands were observed on or adjacent to the project site. The nearest potential jurisdictional waters are located within the Mormon Slough corridor, which the project would not disturb. The project would have no impact on wetlands and Waters of the U.S.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact BIO-4: Fish and Wildlife Migration

The project would not affect any waterways that could be used by migratory fish in the area, since the site is not located on or adjacent to such waterways. Trees on and near the project site may be subject to use by birds protected by the Migratory Bird Treaty Act of 1918 and/or the California Fish and Game Code. However, no substantial amount of habitat exists for these species on or near the site. As a result the project would have less than significant effects on migratory birds.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact BIO-5: Local Biological Resource Policies and Ordinances

The Stockton Municipal Code is intended to protect and preserve Heritage trees on private property. A permit is required for the removal of any Heritage tree. There is one tree on the project site, which is not a Heritage Oak Tree or a large mature tree. Project construction would not result in a significant effect on Heritage trees or on local biological resource policies and ordinances.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact BIO-6: Habitat Conservation Plans

The project is within the coverage area of the SJMSCP but would not convert any existing open space areas to developed land uses. The SJMSCP Habitat Map indicates that the project site is a Category A site, which applies mainly to developed areas and exempts designated areas from SJMSCP fees. Participation in the SJMSCP is required by the City of Stockton. As a result, the project would involve no conflict with the SJMSCP. No other habitat conservation plans apply to the project site. Project impacts related to habitat conservation plans would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

7.0 CULTURAL RESOURCES

Technical information presented in this chapter is drawn primarily from an Historic American Buildings Survey (HABS) report addressing the two existing residential structures on the project site (Evans and DeShazo 2021). Other information sources include the Stockton General Plan and the results of a record search of the California Historical Resources Information System (CHRIS) conducted by the Central California Information Center (CCIC) at California State University Stanislaus. The HABS and CCIC reports are shown in Appendices D and E of this EIR. Information related to notification of and consultation with Native American tribes pursuant to AB 52 is included in Appendix G of this EIR.

ENVIRONMENTAL SETTING

Prehistoric Setting

Human occupation in the Sacramento-San Joaquin Delta region may have occurred as early as 12,000 years ago, but few archaeological sites pre-dating 5,000 years before the present (BP) have been documented in the Delta or the broader Central Valley. The project site is considered to be within North Valley Yokuts territory. The Northern Valley Yokuts occupied the land on either side of the San Joaquin River from the Sacramento-San Joaquin Delta to south of Mendota. The Diablo Range probably marked the western boundary of Yokuts territory; the eastern boundary would have lain along the Sierra Nevada foothills. The Yokuts had gradually expanded their lands northward and clearly occupied the project site and vicinity during the Spanish colonial period.

The North Valley Yokuts were organized into at least 11 small political units or tribes. Each tribe had a population of approximately 300 people, most of who lived within one principal settlement that usually had the same name as the political unit. Acorns, ground into flour, was a staple of the Yokuts diet, along with seeds and other gathered plant materials. The hunting of terrestrial game such as tule elk, mule deer, antelope, pronghorn, rabbits, squirrels, and gophers was considered important, but it was subsidiary to collected foods that could be stored year-round. In riparian areas, fishing and the hunting of waterfowl were also utilized to supplement dietary intake.

The late prehistoric Yokuts may have been the largest ethnic group in pre-contact California. However, the Yokuts were severely impacted by Euro-American settlement. Missionization and exposure to disease decimated the population. The influx of Europeans during the Gold Rush era further reduced the population because of disease and violent encounters with the miners. Because of this, the North Valley Yokuts are generally not well documented in the ethnographic record.

A database search by the Central California Information Center (Appendix E) found no record of any prehistoric resources on the project site; the CCIC report advised that such features have been recorded elsewhere within the boundary of the Stockton West USGS quadrangle. The project site, which is 100% developed with buildings, paving and landscaping, was not surveyed for prehistoric resources.

AB 52 Notification and Consultation

In 2015, the California Legislature enacted AB 52, which focuses on consultation with Native American tribes to avoid or mitigate potential impacts on tribal cultural resources, which are defined as "sites, features, places, cultural landscapes, sacred places, and objects with cultural value to a California Native American tribe." When a tribe requests placement on a notification list for projects that may be within its traditionally and culturally affiliated geographical area, the lead agency must provide the tribe with notice of a proposed project and an invitation to consult within 14 days of a project application being deemed complete or when the lead agency decides to undertake the project if it is the agency's own project. The tribe has up to 30 days to respond to the notice and request consultation; if consultation is requested, then the local agency has up to 30 days to initiate consultation.

Matters which may be subjects of AB 52 consultation include the type of CEQA environmental review necessary, the significance of tribal cultural resources, and project alternatives or appropriate measures for preservation or mitigation of the tribal cultural resource that the tribe may recommend to the lead agency. The consultation process ends when either (1) the resource in question is not considered significant, (2) the parties agree to mitigate or avoid a significant effect on a tribal cultural resource, or (3) a party, acting in good faith and after reasonable effort, concludes that mutual agreement cannot be reached. Regardless of the outcome, a lead agency is still obligated under CEQA to mitigate for any significant environmental effects, as explicitly noted in AB 52.

The City as the CEQA Lead Agency sent notification letters dated _____, 2022 to the Buena Vista Rancheria, the California Valley Miwok and the Northern Valley Yokuts inviting them to consult on the project per AB 52. No responses from the tribes have been received as of the date of publication of this EIR. Responses to the City's notification and the results of any tribal consultation activities will be reported in the Final EIR.

Historic Setting

The HABS report for the project (Evans and De Shazo 2021) contains a detailed history of Stockton and the project vicinity, which is highlighted below.

Early exploration and settlement in the Central Valley was pursued by fur trappers, including members of the Hudson Bay Company. The Canadians established French Camp, located to the south of Stockton, and Alex McLeod of the Hudson Bay Company lent his name to several landscape features, such as McLeod Lake. In 1845, Charles Weber acquired land in present-day Stockton, where he established a settlement. Weber named his settlement in honor of Commodore Robert Stockton, who was active in the

Mexican-American War, which led to the treaty of Cahuenga. “Stockton” was considered an improvement over two of its previous names, Tuleberg, and Mudville. On January 24, 1848, the discovery of gold near the American River, east of Sacramento, transformed the small settlement of Stockton into a growing commercial center. Captain Weber built the first permanent residence in San Joaquin Valley, on what is now known as Weber Point (City of Stockton 2018b).

In 1850, California was admitted to the Union, and on July 23, 1850, the town of Stockton was officially incorporated. During the early 1850s, the growth in population not only created land disputes within “El Rancho del Campo de los Franceses” and stimulated commercial development where eager entrepreneurs set up businesses in support of miners and mining. Stockton quickly became a supply and transportation center to California’s gold mines, and by 1854, it was the fourth largest city in California. By the end of the Gold Rush, many former gold miners settled in the Central Valley, where they established farms, ranches, and lumber mills in the areas surrounding Stockton. With successful agricultural development, and, being situated at the head of a navigable channel with access to the San Francisco Bay, Stockton grew rapidly.

In 1869, the transcontinental railroad route from Promontory Summit in Utah to Sacramento was completed by Central Pacific Railroad (CPRR), which later connected Sacramento with Oakland via Stockton. The Central Pacific employed over 15,000 Chinese immigrants to lay the lines for the railroad. Completion of the transcontinental railroad saw an increase in the settlement of the newly unemployed Chinese laborers who provided seasonal labor for agriculture. At about the same time, a series of anti-immigrant laws and practices.

By the 1890s, Stockton had grown into a major transportation, commercial, and agricultural center. Several railroads, including the Southern Pacific, Santa Fe, Western Pacific, Tidewater Southern, Stockton Terminal & Eastern, and Central California Traction, operated on the rail lines. During this time, the manufacturing of agricultural tools became a major industry in Stockton, and several local inventions revolutionized farming techniques, including the invention of the “Stockton Gang Plow.” During this time, Benjamin Holt invented and sold farm machinery as Holt Manufacturing Company, and in the early 1900s, Holt invented the Caterpillar tractor. With the establishment of flour mills, carriage and wagon factories, iron foundries, and shipyards, Stockton became one of the most industrialized cities in California.

By the 1900s, Stockton and the surrounding area consisted of a diverse group of residents, including Italians, Mexicans, Chinese, Japanese, and Filipinos, who brought their unique cultures to the area. By 1906, Stockton had one of the largest Chinese communities with over 5,000 Chinese and Chinese Americans. During this time, Stockton was also developing into a popular city for families to live and visit.

By the 1920s, the City of Stockton included a substantial downtown with civic and commercial buildings lined up along a one mile stretch of Pacific Avenue, known as the “Miracle Mile”, where various shops and amenities were located. In 1924, the University of the Pacific (known initially as the College of the Pacific) relocated its San Jose campus

to Stockton, making it the first private four-year university. During this time, the Stockton Channel was also bustling with ferry boats and cargo ships.

Despite the economic effects of the Great Depression (1929 – 1933), Stockton pushed forward with the opening of the "Port of Stockton" in 1933, the first inland seaport in California. During the 1930s, the WPA and the PWA constructed many projects in Stockton, including projects at the Port of Stockton, where workers completed general improvement projects including dredging and wharf and warehouse construction.

During World War II, the War Relocation Authority (WRA) was created by Executive Order #9102, which resulted in the removal and relocation of approximately 110,000 Japanese American persons to internment camps. As a part of this process, many Japanese Americans were sent to detention centers, one of which was located in Stockton at the San Joaquin County Fairground – the Stockton Assembly Center. Over 4,000 people that were confined to the assembly before being sent to internment camps in Arkansas and Arizona. In Stockton, approximately 850 Japanese and Japanese Americans (mainly farmers) were interned.

The "Rough and Ready Island Naval Supply Depot" west of the Port of Stockton, was the location of the former U.S. Navy installation, that supported the San Joaquin Depot, the Tracy Depot Facility and the Sharpe Depot Facility. At the end of WWII, there was a significant surge in commercial and residential development throughout Stockton, particularly in undeveloped areas north and northeast of the downtown. By the 1950s, the City of Stockton included a world-renown civic theater, symphony, ballet, and chorale groups. During the 1960s and 1970s, Stockton continued to expand its boundaries, converting former agricultural land to new residential housing and commercial development.

EXISTING BUILDINGS ON THE PROJECT SITE

The two 1904 multi-family buildings within the property were built in the U.S. during a time when multi-family buildings that mimicked single-family houses were being built, particularly in urban neighborhoods, including downtown Stockton. During this time, numerous two-family houses were constructed with identical apartment flats stacked on top of the other, often within a deep narrow parcel. During the early 1900s, the multi-family buildings typically featured architectural details such as clapboards, wood shingle or stucco siding, gabled or hipped roofs with gable roof dormers, angular or square two-story bay windows, decorative Palladian-style windows at the attic, multi-light double-hung wood windows, and prominent front porches. These buildings were designed to allow working-class families to achieve a middle-class quality of life but for less cost. During this time, the early 20th-century working-class neighborhoods often consisted of multi-unit structures, including duplexes, two stacked and three stacked houses, and larger multi-unit apartment complexes.

The two multi-family buildings located on the project site embody the distinctive characteristics of two architectural styles, including Queen Anne and Colonial Revival, often referred to as Queen Anne Free Classic, which is a subtype of the Queen Anne

style, which uses classical elements from the Colonial architectural vocabulary. Detailed architectural descriptions of each building can be reviewed in Appendices C and D.

The buildings are, however, in bad condition. Owned by GCRM, the buildings have been pressed into service in order to provide shelter for as many homeless people as possible. The buildings included antiquated plumbing and electrical fixtures. When required, fire escapes, plumbing and electrical improvements have been made on the side and rear walls of the buildings, and interior wall and floor repairs have been hastily made without concern for long-term use. The owner (Richardson pers. comm.) indicates that, had the proposed building and EIR preparation not been adequately funded by outside sources, GCRM would have instead elected to board up the buildings, leading ultimately to their condemnation and demolition. The owner has considered but rejected the option of improving the existing buildings to the current, which could be done; however, this option would be entirely cost-prohibitive; the improved buildings would have the potential to house perhaps 16 persons at an estimated cost of $2-3 million.

Despite their condition, the two 1904 buildings are considered historical resources as defined in CEQA Guidelines Section 15064.5. Both structures were evaluated by qualified historians (see Appendix C) and found to be eligible for listing under the National Register of Historic Places (Criterion C), the California Register of Historical Resources (Criterion 3) and locally (Page and Turnbull, 2019). Additional detail regarding the design, setting and eligibility of the structures is provided in the Primary Records (Page and Turnbull 2019 Appendix C) and the HABS report (Appendix D).

The subject buildings are not currently listed as historic resources at the federal, state or local levels. The buildings are not included in the Downtown Stockton Historic Resources Survey (2000). The project site is not located within a local historic district or historic zoning overlay area. The site and buildings are not listed as City of Stockton Landmarks, Historic Sites, or Structures of Merit.

REGULATORY FRAMEWORK

CEQA Guidelines Section 15064.5

Criteria specified in CEQA Guidelines Section 15064.5 suggest that a "historically significant resource" is one that meets one or more of the criteria for listing on the California Register of Historical Resources (CRHR), including the following:

1. Is associated with events that have made a significant contribution to the broad patterns of California’s history and cultural heritage;

2. Is associated with the lives of persons important in California’s past;

3. Embodies the distinctive characteristics of a type, period, region, or method of construction, or represents the work of an important creative individual, or possesses high artistic value; or

4. Has yielded, or may be likely to yield, information important in prehistory or history.

A resource that is not listed in, or determined to be eligible for listing in, the California Register of Historical Resources, or is not included in a local register of historical resources or identified in a historical resources survey, does not preclude a lead agency from determining that a resource may be a historical resource. The two existing buildings on the site have been found to be eligible for CRHR listing under Criterion 3 as described above.

AB 52

In 2014, the State Legislature enacted Assembly Bill (AB) 52, which focuses on CEQA consultation with Native American tribes on projects that could potentially affect resources of value to the tribes. The intent of this consultation is to avoid or mitigate potential impacts on "tribal cultural resources," which are defined as sites, features, places, cultural landscapes, sacred places, and objects with cultural value to a California Native American tribe that are either of the following:

- Included or determined to be eligible for inclusion in the California Register of Historical Resources, or
- Included in a local register of historical resources as defined in subdivision (k) of public Resources Code Section 5020.1.

The tribal cultural resource must be a tangible resource for CEQA purposes, but the meaning or value attributed to that resource may be intangible. Only tribes that request to be on a lead agency's notice list shall be consulted on a project. The project must be within the geographic area that is traditionally and culturally affiliated with the tribes.

Under AB 52, consultation with tribes on a notice list shall be initiated prior to the release of the CEQA document for public review. When a tribe requests consultation with a CEQA lead agency on projects within its traditionally and culturally affiliated geographical area, the lead agency must provide the tribe with notice of a proposed project after the project application is deemed complete, or when the lead agency decides to undertake the project if it is the agency's own project. The tribe has up to 30 days to respond to the notice, in writing. In the response, the tribe must designate a lead contact person for the consultation if it is requested. If the tribe requests consultation, then the lead agency has up to 30 days to initiate formal consultation.

Once initiated, the AB 52 consultation process ends either (1) when the parties agree to mitigate or avoid a significant effect on a tribal cultural resource, or (2) a party, acting in good faith and after reasonable effort, concludes that mutual agreement cannot be reached.

Significance Thresholds

According to the recently updated Appendix G of the CEQA Guidelines, a project may have a significant impact on cultural resources if it would:

- Cause a substantial adverse change in the significance of a historical resource as defined in CEQA Guidelines Section 15064.5,
- Cause a substantial adverse change in the significance of an archaeological resource as defined in CEQA Guidelines Section 15064.5, or
- Disturb any human remains, including those interred outside of formal cemeteries.

Also, according to Appendix G, a project may have a significant impact on the environment if it would cause a substantial adverse change in the significance of a tribal cultural resource, defined in California Public Resources Code Section 21074 as a site, feature, place, sacred place, cultural landscape that is geographically defined in terms of the size and scope of the landscape, or object with cultural value to a California Native American tribe, and that is:

- Listed or eligible for listing in the California Register of Historical Resources, or in a local register of historical resources as defined in Public Resources Code Section 5020.1(k), or
- A resource determined by the lead agency, in its discretion and supported by substantial evidence, to be significant pursuant to criteria set forth in subdivision (c) of Public Resources Code Section 5024.1. In applying the criteria set forth in subdivision (c) of Public Resources Code Section 5024.1, the lead agency shall consider the significance of the resource to a California Native American tribe.

Impact CULT-1: Historical Resources

The project site is occupied by two existing residential buildings that date to 1904 and have been determined to be eligible for listing in the CRHR. Both buildings have been evaluated by qualified architectural historians documented the architectural attributes of the buildings leading to this eligibility determination in the site records shown in Appendix C. The existing buildings are therefore considered “historical resources” and may be considered “historically significant” by the Lead Agency, as defined in CEQA Guidelines Section 15064.5(a).

The proposed project, requires the demolition and removal of the two existing buildings. This element of the project would result in “a substantial adverse change in the significance of a historical resource” and may, therefore, have a significant effect on the environment as defined in CEQA Guidelines Section 15064.5(b).

Alternatives to the project, including alternatives to the proposed building demolition, are discussed in Chapter 18.0 Alternatives of this EIR. There is no practicable alternative to removal of the existing structures from the project; of the alternatives described in Chapter 18.0 of this EIR, only the No Project Alternative is "feasible," in that it is capable of being done. However, the No Project Alternative is entirely inconsistent with the project objectives described of providing additional shelter for homeless persons, as in Chapter 3.0 Project Description.

There exist potential mitigation measures that would address the adverse effect of the project on the significant historic resources on the site. None of these mitigation measures would avoid the project's effects on historical resources, but they would to a greater or lesser degree offset or reduce those effects. These measures would include relocation of one or both of the existing structures to another property, to the extent that demand exists, and documenting the historic attributes of the existing buildings in reports, photographs and as-built plans prepared for archival storage.

Relocation of one or both of the structures is not considered feasible by GCRM. Relocation would require a suitable site for placement of the relocated buildings, the availability of a suitable means for relocation, which could include disassembly and reconstruction, ability to preserve the building's historical attributes through the moving process, physical obstructions to the moving process and costs. Relocation is beyond the means of the project applicant. The buildings are designed for residential use by the working class of 1904 and would not present a desirable prospect for a commercial use. Renovation costs would not be consistent with long-term residential use. If it exists, feasibility of relocating the buildings would need to be determined by a buyer. As provided in Mitigation Measure CULT-1 below, the GCRM will take reasonable steps to make the buildings available for acquisition and relocation prior to demolition, provided all costs are to be borne by the buyer. The owner is opposed to this option.

Documentation of historic resources can mitigate or compensate for impacts to significant properties by preparing archival quality drawings, reports, and large-format photographs of historic buildings. Archival standards are set by the Historic American Building Survey (HABS); HABS and related programs were established beginning in 1933 as a public archive of America's architectural heritage. HABS documentation consists of measured drawings, historical reports, and large-format black and white photographs. Creation of the program was motivated primarily by the perceived need to mitigate the negative effects of adverse effects on or loss of architectural resources.

HABS documentation is considered by some to be the "gold standard" for historic documentation. HABS is responsible for the development of standards for the production of drawings, histories, and photographs and the criteria for preparing archival documentation consistent the Secretary of the Interior's Standards and Guidelines for Architecture and Engineering. Historic documentation may be archived locally or submitted to the Library of Congress.

The project applicant has prepared HABS documentation for the existing buildings on the project site as mitigation for the project's historic resource effect. The documentation would be submitted to the City for filing or submittal as appropriate. It is recognized that

HABS documentation is only partial mitigation; the documentation would record the historic value of the existing buildings but would only partially compensate for their removal. As a result, the project would result in a significant and unavoidable effect on historic resources.

Level of Significance: Significant

Mitigation Measures:

CULT-1: GCRM shall take reasonable steps to make the two residential buildings on the site available for acquisition and relocation prior to demolition, provided that all costs, insurance, permitting and other related requirements will be borne by the buyer.

CULT-2: GCRM will complete required HABS documentation for the two existing buildings and submit the documentation to the City for review and a determination as to where and how the documentation should be filed.

Significance After Mitigation: Potentially significant, no feasible mitigation, unavoidable impact. The City will need to adopt a Statement of Overriding Considerations prior to project approval.

Impact CULT-2: Archaeological Resources

As noted, the Central California Information Center records search found no documented prehistoric resources on or within one-eighth mile of the project site. BaseCamp Environmental contacted the Native American Heritage Commission (NAHC) during the preparation of this EIR requesting a search of the NAHC's Sacred Lands File for occurrences on or near the project site; the NAHC report was negative. The NAHC provided a list of tribes that should be contacted regarding potential tribal cultural resources.

Due to the extent of past urbanization of the site and surrounding lands, it is unlikely that intact archaeological resources would be encountered on the project site. However, it is nonetheless possible that excavation associated with the project could unearth archaeological materials of significance that are currently unknown. Procedures to address archaeological discoveries if they should occur are set forth in the mitigation measure below. Implementation of this mitigation would reduce potential impacts on inadvertently discovered archaeological resources to a level that would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

CULT-3: If any subsurface cultural resources are encountered during construction of the project, all construction activities within 50 feet

of the encounter shall be halted until a qualified archaeologist can examine these materials, determine their significance, and if significant recommend further mitigation measures that would reduce potential effects to a level that is less than significant. Recommended mitigation measures could include, but are not limited to, 1) preservation in place, or 2) excavation, recovery, and curation by qualified professionals. The City of Stockton Community Development Department shall be notified, and the project developer shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in a written report to the City's Community Development Department, consistent with the requirements of the CEQA Guidelines.

CULT-4: If burial resources or tribal cultural resources are discovered, the archaeologist and/or City shall notify the appropriate tribal representative, who may examine the materials with the archaeologist and advise the City as to their significance.

The archaeologist, in consultation with the tribal representative if contacted, shall recommend mitigation measures needed to reduce potential cultural resource effects to a level that is less than significant in a written report to the City, with a copy to the tribal representative. The City shall be responsible for implementing the report recommendations. Avoidance is the preferred means of disposition of tribal cultural resources. The contractor shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in written reports to the City.

Significance After Mitigation: Less than significant

Impact CULT-3: Human Burials

As with other archaeological resources discussed above, it is unlikely that Native American or any other human burials would be uncovered by project construction. However, it is conceivable that excavation associated with the project could uncover a previously unknown burial.

CEQA Guidelines Section 15064.5(e) describes the procedure to be followed when human remains are uncovered in a location outside a dedicated cemetery. All work in the vicinity of the find shall be halted, and the County Coroner shall be notified to determine if an investigation of the death is required. If the Coroner determines that the remains are Native American in origin, then the Coroner must contact the Native American Heritage Commission within 24 hours. The Native American Heritage Commission shall identify the most likely descendants of the deceased Native American, and the most likely descendants may make recommendations on the disposition of the remains and any

associated grave goods with appropriate dignity. If a most likely descendant cannot be identified, the descendant fails to make a recommendation, or the landowner rejects the recommendations of the most likely descendant, then the landowner shall rebury the remains and associated grave goods with appropriate dignity on the property in a location not subject to further disturbance.

Mitigation presented below requires compliance with CEQA Guidelines Section 15064.5(e). Implementation of the mitigation measure would ensure that any human remains and associated grave goods encountered during project construction would be treated with appropriate dignity. Project impacts on human remains would, with the inclusion of mitigation measures, be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

CULT-5: If project construction encounters evidence of human burial or scattered human remains, the contractor shall immediately notify the County Coroner and the Stockton Community Development Department. On advice from the NAHC, the Community Development Department notify the appropriate tribal representatives and other federal and State agencies as required. The City will be responsible for compliance with the requirements of California Health and Safety Code Section 7050.5 and with any direction provided by the County Coroner.

CULT-6: If the human remains are determined to be Native American, the County Coroner shall notify the Native American Heritage Commission, which will notify and appoint a Most Likely Descendant. The Most Likely Descendant shall work with the City and a qualified archaeologist to decide the proper treatment of the human remains and any associated funerary objects in accordance with California Public Resources Code Sections 5097.98 and 5097.991. Avoidance is the preferred means of disposition of the burial resources.

Significance after Mitigation: Less than significant

Impact CULT-4: Tribal Cultural Resources

The CCIC record search did not identify any known prehistoric resources on or near the project site but noted that such features have been recorded elsewhere within the boundary of the Stockton West USGS quadrangle.

Contact with the NAHC did not indicate the potential presence of a Sacred Land on or near the project site. The City's AB 52 tribal notification has been completed, but no response to the notification has been received. The City has received no other information that would indicate that significant tribal cultural resources are present on the site. Even

though the project site and surrounding lands have been extensively disturbed by urbanization, it is nonetheless conceivable that tribal cultural resources could be encountered during project construction. Disturbance or damage to such resources would be a potentially significant impact. Mitigation measures that would take effect if and when potentially significant tribal cultural resources are identified during project construction are discussed below. These measures will be reviewed, and may need to be amended or updated, based on the tribes' response to the City's notification.

Requirements related to cultural resource protection during construction have been addressed by the Stockton Municipal Code, which requires construction activity to be halted at an inadvertently disturbed archaeological site until it is evaluated. Mitigation measures CULT-2 and CULT-3 above provide more direction in complying with these requirements of the Stockton Municipal Code. These measures also would address the potential concerns of Native American tribes should potential tribal cultural resources be encountered. Implementation of these mitigation measures would reduce potential impacts on archaeological resources and tribal cultural resources to a level that would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

CULT-7: If any subsurface archaeological resources, including human burials and associated funerary objects, are encountered during construction, all construction activities within a 50-foot radius of the encounter shall be immediately halted until a qualified archaeologist can examine these materials and evaluate their significance. The City shall be immediately notified in the event of a discovery. If burial resources or tribal cultural resources are discovered, the City shall notify the appropriate tribal representative, who may examine the materials with the archaeologist and advise the City as to their significance.

The archaeologist, in consultation with the tribal representative if contacted, shall recommend mitigation measures needed to reduce potential cultural resource effects to a level that is less than significant in a written report to the City, with a copy to the tribal representative. The City shall be responsible for implementing the report recommendations. Avoidance is the preferred means of disposition of tribal cultural resources. The contractor shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in written reports to the City.

Significance After Mitigation: Less than significant

8.0 GEOLOGY AND SOILS

This chapter analyzes the potential environmental impacts of the project as to exposure to seismic, soil and geological hazard. It also discusses potential for project impacts on paleontological resources and mineral resources.

ENVIRONMENTAL SETTING

Geomorphology and General Geology

The site is located on the east-central portion of the Great Valley Province. The Great Valley is an asymmetrical synclinal trough with a gently dipping eastern limb. The trough is filled with a thick (up to 60,000 feet thick) sequence of sedimentary units. The deepest part of the basin is near the western edge, west of the present axis. The thin eastern valley deposits overlap the metamorphic terrains of the Sierran Foothills and the polycrystalline basement of the Sierra Nevada Block. The project site is generally flat, with no discernable slope.

Most of the soils in the San Joaquin Valley consist of sand, silt, loamy clay alluvium, peat, and other organic sediments. These soils are the result of long-term natural soil deposition and the decomposition of marshland vegetation. The Geologic Map of the Sacramento Quadrangle (Wagner et al. 1981) designates the underlying geology of the project site as the Modesto Formation, consisting of Quaternary sediments.

Seismic and Geological Conditions

Seismicity

There are several faults and potential fault traces located within the County, concentrated along its eastern and western margins. Faults are classified as to their potential for seismic activity based on evidence of past activity. An “active” fault is defined as one along which displacement has been demonstrated to occur within the past 11,700 years. A fault is considered “potentially active” if there is evidence of movement within the past 700,000 years and further movement is considered likely. An “inactive fault” shows no evidence of movement within the last 1.6 million years, and renewal activity is not considered likely. Fault rupture is a potential hazard that occurs within active earthquake fault zones. A fault zone has significant width, ranging from a few feet to several miles (Bryant and Hart 2007).

According to the Stockton General Plan 2040 EIR, there are no active or potentially active faults located in the Stockton vicinity (City of Stockton 2018a). Based on the 2010 Fault Activity Map of California prepared by the Department of Mines and Geology, the

nearest faults are the Midland Fault, Marsh Creek/Greenville Fault, and the Bear Mountain Fault zone. The Midland Fault is 18 miles to the west and has had no movement in recent geological time (last 800,000 years). The Marsh Creek/Greenville Fault is 30 miles west and has shown movement in the last 10,000 years. The Bear Mountain Fault has not shown movement in the last 1.6 million years (Gularte and Associates 2017). Portions of the Concord-Green Valley and Hayward fault zones, 35 and 50 miles west of Stockton, and the Calaveras fault zone, approximately 40 miles southwest of Stockton, have been rated as active within the last 200 years. The project site, along with the rest of San Joaquin County, is subject to seismic shaking from these two faults, as well as the San Andreas Fault (San Joaquin County 2016b).

Liquefaction

Soil compaction and settlement can result from seismic ground shaking. If the sediments that compact during an earthquake are saturated, soils may lose strength and become fluid – a process called liquefaction. Based on known information, areas of the County with groundwater less than 50 feet from ground surface in unconsolidated sediment are susceptible to liquefaction, including lands near river courses (San Joaquin County 2016b).

TABLE 8-1
MODIFIED MERCALLI INTENSITY SCALE

Intensity	Shaking	Description
I	Not felt	Not felt except by a very few under especially favorable conditions.
II	Weak	Felt only by a few persons at rest, especially on upper floors of buildings. Delicately suspended objects may swing.
III	Weak	Felt quite noticeably by persons indoors, especially on upper floors of buildings. Many people do not recognize it as an earthquake. Standing motor cars may rock slightly. Vibrations similar to the passing of a truck. Duration estimated.
IV	Light	Felt indoors by many, outdoors by few during the day. At night, some awakened. Dishes, windows, doors disturbed; walls make cracking sound. Sensation like heavy truck striking building. Standing motor cars rocked noticeably.
V	Moderate	Felt by nearly everyone; many awakened. Some dishes, windows broken. Unstable objects overturned. Pendulum clocks may stop.
VI	Strong	Felt by all, many frightened. Some heavy furniture moved; a few instances of fallen plaster. Damage slight.
VII	Very strong	Damage negligible in buildings of good design and construction; slight to moderate in well-built ordinary structures; considerable damage in poorly built or badly designed structures; some chimneys broken.
VIII	Severe	Damage slight in specially designed structures; considerable damage in ordinary substantial buildings with partial collapse. Damage great in poorly built structures. Fall of chimneys, factory stacks, columns, monuments, walls. Heavy furniture overturned.
IX	Violent	Damage considerable in specially designed structures; well-designed frame

		structures thrown out of plumb. Damage great in substantial buildings, with partial collapse. Buildings shifted off foundations.
X	Extreme	Some well-built wooden structures destroyed; most masonry and frame structures destroyed with foundations. Rails bent.
XI	Extreme	Few, if any (masonry) structures remain standing. Bridges destroyed. Rails bent greatly.
XII	Extreme	Damage total. Lines of sight and level are distorted. Objects thrown into the air.

Source: U.S. Geological Survey 1989

Soils and Soil Conditions

Most of the soils in the San Joaquin Valley consist of sand, silt, loamy clay alluvium, peat, and other organic sediments. These soils are the result of long-term natural soil deposition and the decomposition of marshland vegetation. According to a custom soil survey by the Natural Resources Conservation Service, the soil on the project site is Yellowlark Gravelly Loam. This soil is made up of primarily gravelly loam with clay loam present at 54-59 inches. This soil is well drained and moderately deep with high runoff capability.

Paleontological Resources

Paleontological resources are fossils or groups of fossils that are unique, unusual, rare, uncommon or important, and those that can add to the existing body of knowledge in specific areas. Surface examination of a study or project area often does not reveal whether paleontological resources are present. Most of the Stockton area is located on the lower terraces of the San Joaquin River just east of the Delta; the Quaternary lake and marsh deposits that make up these deposits have the potential for fossils to occur. Occurrences, if any, are likely to be encountered below the upper five to ten feet of sediment (City of Stockton 2007). The project site is underlain by the Modesto Formation, a geologic formation that has yielded paleontological resources.

Paleontological resources have been encountered in San Joaquin County, including areas within the Modesto Formation. A record search of the Museum of Paleontology at the University of California in Berkeley indicated that 97 paleontological finds have been made in the County. The majority of specimens from the County have been found in rock formations in the foothills of the Diablo Mountain Range. However, remains of extinct animals, such as mammoth, could be found virtually anywhere in the County, especially along watercourses such as the San Joaquin River and its tributaries (San Joaquin County 2016b). Paleontological resources have been encountered during deep excavations in the downtown area; There are no known paleontological resources on the project site.

Mineral Resources

As described in Chapter 9.0, Geology and Soils, the project site is within the Great Valley geomorphic province. Mineral resources within San Joaquin County, where they occur, are primarily sand, gravel, and other construction material deposits in the alluvial portion of the valley floor. Sand and gravel deposits have been identified along the Stanislaus River in San Joaquin and Stanislaus Counties (DMG 1977); no such resources are located on or near the project site. Portland cement concrete aggregate deposits also have been identified within San Joaquin County; however, none are located on or near the project site (DMG 1988).

Oil and natural gas deposits have been identified at various location throughout the Central Valley, although most of the deposits in the Stockton area are of natural gas. The project site does not contain any documented oil or natural gas fields. The nearest such field is the abandoned Stockton natural gas field which is located outside the City limits. The nearest active field is the French Camp natural gas field south of Stockton (DOGGR 2001).

REGULATORY FRAMEWORK

Alquist-Priolo Earthquake Fault Zoning Act

The Alquist-Priolo Earthquake Fault Zoning Act, enacted in 1972 and subsequently amended, prohibits the location of most structures for human occupancy across the traces of active faults and thereby mitigates the hazard of fault rupture. Under the Act, the State Geologist is required to delineate Earthquake Fault Zones along known active faults in California. Cities and counties affected by the zones must regulate development projects within the zones (Bryant and Hart 2007). The project site is not located with an area mapped by the State Geologist as a "Zone of Required Investigation," including Alquist-Priolo Earthquake Fault Zones and Seismic Hazards Mapping Act zones.

California Building Code

The California Building Code (CBC) is included in Title 24 of the California Code of Regulations. The CBC incorporates the International Building Code, a model building code adopted across the United States. The CBC is updated every three years, and the current 2016 version took effect January 1, 2017. The City of Stockton adopted the CBC by reference pursuant to Title 15, Chapter 15.40, Section 15.40.010 of the City's Municipal Code. The CBC contains building requirements that address likely ground shaking hazards that may occur in Stockton. It can require detailed soils and/or geotechnical studies in areas of suspected geological hazards, such as unstable geologic units that may be subject to collapse, subsidence, land slides, liquefaction, or lateral spreading.

Stockton Municipal Code

Section 15.48.050 of the Stockton Municipal Code, entitled Construction and Application, includes a requirement that seeks to mitigate hazards associated with erosion, stating that "During construction, construction activities shall be designed and conducted to minimize runoff of sediment and all other pollutants onto public properties, other private properties and into the waters of the United States." Section 15.48.110, entitled Erosion Control Requirements, contains specific provisions for erosion control for those construction projects where a grading permit is not required. Section 15.48.070 includes requirements for a grading permit that apply to most construction projects. Such permits require implementation of erosion control measures, often referred to as BMPs.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to the recently updated Appendix G of the CEQA Guidelines, a project may have a significant impact on the environment if it would:

- Expose people or structures to potential substantial adverse effects, including the risk of loss, injury, or death, involving rupture of a known earthquake fault, strong seismic ground shaking, seismic-related ground failure (including liquefaction), or landslides,
- Result in substantial soil erosion or the loss of topsoil,
- Be located on a geologic unit or soil that is unstable, or that would become unstable as a result of the project, and potentially result in on- or off-site landslide, lateral spreading, subsidence, liquefaction, or collapse,
- Be located on expansive soil as defined in Table 18-1-B of the Uniform Building Code,
- Have soils incapable of adequately supporting the use of septic tanks or alternative wastewater disposal systems where sewers are not available for the disposal of wastewater,
- Directly or indirectly destroy a unique paleontological resource or site or unique geologic feature,
- Result in the loss of availability of a known mineral resource that would be of value to the region and residents of the state, or Result in the loss of availability of a locally important mineral resource recovery site delineated on a local general plan, specific plan, or other land use plan.

Impact GEO-1: Faulting and Seismicity

As previously noted, there are no active or potentially active faults within or near the project site. The project site is not within an Alquist-Priolo Earthquake Fault Zone. The project would have no impact related to fault rupture.

The project site, along with the rest of the County, is subject to seismic shaking from fault features east and west of the County. The site is subject to a relatively low to moderate level of ground shaking for California.

Proposed structures and site improvements would be required to incorporate engineering design features that would be in accordance with the latest version of the CBC, which has been adopted by the City. Design criteria in the CBC that address seismicity would enable structures to withstand anticipated seismic shaking. Based on the above information, project impacts related to seismic hazards would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact GEO-2: Other Geologic Hazards

The project site and its surroundings are flat and not prone to landslide hazards. Risk of lateral spreading from landslides and liquefaction is considered to be very low. The project site resides in a low-risk seismic zone; soils data does not suggest the presence of liquefiable soils. The soils underlying the project site have not been identified as inherently unstable or prone to failure. Appropriate engineering design as required by the Building Code and the Building Division of the Stockton Community Development Department would avoid potential adverse effects. The project would have no impact on the stability of soils or local geology.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact GEO-3: Soil Erosion

Soils on the project site has a relatively low potential for erosion, and the area of exposure to erosion would be small. The project would be required to comply with State and local storm water quality controls, including those established by City ordinances and the City of Stockton's MS4 permit.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact GEO-4: Expansive Soils

Expansive soils are associated with soils with substantial clay content. The Yellowlark soil on the project site is gravelly with some clay content and is not flagged as potentially expansive. The project would have no impact related to expansive soils.

Level of Significance: No impact

Mitigation Measures: None required

Impact GEO-5: Paleontological Resources and Unique Geological Features

The project site is flat and contains no geological features that may be considered unique. The project site is underlain by the Modesto Formation, which has been a source of paleontological finds in the past. It is unlikely that any intact paleontological resources would be encountered during project construction, but it is also conceivable that currently unknown resources may be uncovered during project construction activities. Procedures to address paleontological discoveries if they should occur are set forth in the mitigation measure below. Implementation of this mitigation would reduce potential paleontological impacts to a level that would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

GEO-2: If any subsurface paleontological resources are encountered during construction of the project, all construction activities within 50 feet of the encounter shall be halted until a qualified paleontologist can examine these materials, determine their significance, and if significant recommend further mitigation measures that would reduce potential effects to a level that is less than significant. Recommended measures could include, but are not limited to, 1) preservation in place, or 2) excavation, recovery, and curation by qualified professionals. The City of Stockton Development Department shall be notified, and the project developer shall be responsible for retaining qualified professionals, implementing recommended mitigation measures, and documenting mitigation efforts in a written report to the City's Community Development Department, consistent with the requirements of the CEQA Guidelines.

Significance After Mitigation: Less than significant

Impact GEO-6: Access to Mineral Resources

As described above, there are no identified mineral resources areas on or near the project site, including oil and gas fields. There are no active mining operations on or near the project site. The project would have no effect on the availability of or access to locally

designated or known mineral resources. The project would have no impact on mineral resources.

Level of Significance: No impact

Mitigation Measures: None required

9.0 GREENHOUSE GAS EMISSIONS

ENVIRONMENTAL SETTING

Global Climate Change and Greenhouse Gases

Global climate change is a change in the average weather conditions, such as temperature and rainfall, of the Earth over a long period of time. Recent scientific observations and studies indicate that global climate change, linked to an increase in the average global temperature that has been observed, is now occurring. There is a consensus among climate scientists that the primary cause of this change is human activities that generate emissions of greenhouse gases (GHGs) (CAPCOA 2009). GHGs are gases that trap heat in the earth's atmosphere. They include carbon dioxide, the most abundant GHG, as well as methane, nitrous oxide, and other, less abundant gases. Although each GHG has heat-trapping properties, they vary in the amount of heat they can trap. Measurements of GHG emissions are commonly expressed in carbon dioxide equivalent (CO_2e), in which emissions of all other GHGs are converted to equivalent CO_2 emissions.

GHG emissions in California in 2018, the most recent year for which data are available, were estimated at approximately 425 million metric tons CO_2e – a decrease of approximately 13% from the peak level in 2004. Transportation was the largest contributor to GHG emissions in California, with approximately 40% of total emissions. Other significant sources include industrial activities, with approximately 21% of total emissions, and electric power generation, both in-state and imported, with approximately 15% of total emissions (ARB 2020b).

Concerns related to global climate change include the direct consequences of a warmer climate, but also include indirect effects such as reduced air quality, reduced snowpack, higher-intensity storms, and rising sea levels. All these changes have implications for the human environment, as well as existing ecosystems and the species that depend on them. The United Nations Intergovernmental Panel on Climate Change (IPCC) has concluded that stabilization of greenhouse gases at a concentration of 400-450 parts per million (ppm) CO_2e is required to keep mean global warming below 2° Celsius, which is considered necessary to avoid dangerous impacts of climate change (IPCC 2001). According to data collected by the National Oceanic and Atmospheric Administration, the carbon dioxide concentration in the atmosphere was 413.92 ppm in June 2019 (NOAA 2019).

The State of California, through a collaboration of three agencies, has prepared Climate Change Assessments that provide scientific assessments on the potential impacts of climate change in California and reports potential adaptation responses. The most recent report, issued in 2019, includes assessments of climate change impacts by region,

including the San Joaquin Valley. Potential climate change impacts occurring in the San Joaquin Valley include the following (Westerling et al. 2018):

- Acceleration of warming across the region and state.
- More intense and frequent heat waves.
- Higher frequency of catastrophic floods.
- More intense and frequent drought.
- More severe and frequent wildfires.

REGULATORY FRAMEWORK

Federal

Unlike the criteria air pollutants described in Chapter 6.0, Air Quality, GHGs have no "attainment" standards established by either the federal or state governments. Nevertheless, the EPA has found that GHG emissions endanger both the public health and public welfare under Section 202(a) of the Clean Air Act, due to their impacts associated with climate change (EPA 2009).

In 2015, the Paris Agreement was reached among 196 countries, with each country pledging to take actions to decrease GHG emissions to reach the overall goal of limiting the increase in global temperature to no more than 2° Celsius. Although the United States signed the Paris Agreement, the US withdrew from the agreement during the Trump administration. A new international agreement, with US participation was reached in 2021 in the Glasgow Climate Pact.

State

California has addressed climate change on its own initiative as early as 1988, when the California Energy Commission was designated as the lead agency for climate change issues. However, the most significant state activities have occurred since 2005, when various executive orders and State legislation established the current framework for dealing with climate change. These actions are listed below.

Executive Order S-3-05 (Schwarzenegger)

Executive Order B-30-15 (Brown)

Assembly Bill 32 Global Warming Solutions Act of 2006

Climate Change Scoping Plan of 2008

Climate Change Scoping Plan Update of 2014

Executive Order B-55-18 (Brown) Carbon Neutrality 2045

Regional and Local Agencies

San Joaquin Valley Air Pollution Control District

In August 2008, the SJVAPCD adopted its Climate Change Action Plan. The goals of the Climate Change Action Plan are, among others, to establish processes for assessing the significance of project-specific GHG impacts for projects permitted by the SJVAPCD, and to assist local land use agencies, developers and the public by identifying and quantifying GHG emission reduction measures for development projects (SJVAPCD 2008). In 2009, the SJVAPCD adopted an approach to determine the significance of project-specific GHG emissions.

City of Stockton Climate Action Plan

The City of Stockton adopted a Climate Action Plan (CAP) in 2014 that "outlines a framework to feasibly reduce community GHG emissions in a manner that is supportive of AB 32 and is consistent with the Settlement Agreement and 2035 General Plan policy" (City of Stockton 2014). To achieve this target, the CAP incorporates a Development Review Process through which development projects document the incorporation of measures that would produce targeted GHG reductions. The project is exempt from participation in this program.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact related to GHG emissions if it would:

- Generate GHG emissions, either directly or indirectly, that may have a significant impact on the environment, or
- Conflict with any applicable plan, policy or regulation of an agency adopted for the purpose of reducing the emissions of greenhouse gases.

This EIR conducted its GHG analysis in accordance with CEQA Guidelines Section 15064.4, which states that a lead agency should make a good-faith effort, based to the extent possible on scientific and factual data, to describe, calculate or estimate the amount of greenhouse gas emissions resulting from a project.

Impact GHG-1: Project GHG Emissions and Consistency with Applicable Plans and Policies

The CalEEMod model discussed in Chapter 5.0 Air Quality was used to estimate the total GHG construction and operational emissions associated with the project; the results are available in Appendix B of this EIR. Table 9-1 presents the results of the CalEEMod run.

TABLE 9-1
PROJECT GHG EMISSIONS

GHG Emission Type	Unmitigated Emissions (metric tons CO_2e)	Mitigated Emissions (metric tons CO_2e)
Construction[1]	120.4	120.4
Operational[2]	198.8	164.7

[1] Total emissions for construction period.
[2] Annual emissions.
Source: California Emissions Estimator Model v. 2016.3.2.

Based on results from the CalEEMod run, project construction GHG emissions for would be approximately 120 metric tons CO_2e for the construction period. Neither the State nor SJVAPCD has established significance thresholds for GHG emissions from construction activities or from project operations. However, the predicted emissions are incidental, and construction emissions would cease once work is completed.

Project operational GHG emissions would be approximately 199 metric tons CO_2e annually under "unmitigated" conditions (i.e., without implementation of any project features or regulations that would reduce GHG emissions). The CalEEMod run incorporated the following project features and regulations that would reduce GHG emissions:

- Installation of sidewalk along currently unimproved frontage per City standards and connection with other sidewalks in area.
- Availability of existing public transit service.
- Proximity to downtown/job center.
- Use of LED lighting.
- In accordance with SB X7-7, new development would implement water conservation measures that lead to a 20% reduction in indoor and outdoor water use.

With incorporation of these measures, estimated operational GHG emissions would be reduced to approximately 164.7 metric tons CO_2e annually, an approximate 17.3% reduction in GHG emissions from unmitigated levels.

Approximately 83% of the GHG emission reduction programs in the California Scoping Plan counted toward meeting the 29% objective for 2020 are State-level programs, with

the remaining 17% to be achieved by programs at the local government level, including development review. Thus, the local action share of the 29% reduction would be 4.93%. Based on this, it can be assumed that a development project that achieves at least a 4.93% reduction in GHG emissions from business-as-usual levels would be consistent with the objectives of both State and SJVAPCD GHG reduction plans. The 17.3% reduction associated with the project would exceed this local share.

The project would also be consistent with the goal of reducing per capita GHG emissions through compact growth, as set forth in the RTP/SCS. One of the RTP/SCS strategies is to direct growth to existing communities through investments that provide a range of housing choices for existing and new residents. The project would be consistent with this strategy. Overall, impacts related to GHG emissions and GHG reduction plans would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

10.0 HAZARDS AND HAZARDOUS MATERIALS

This chapter of the EIR focuses on hazards associated with human or environmental exposure to hazardous materials, airports and aircraft operations and wildfire. Hazards associated with Toxic Air Contaminants (TACs) are discussed in Chapter 5.0, Air Quality; geologic and soil instability hazards are addressed in Chapter 8.0, Geology; and potential flooding hazards are addressed in Chapter 11.0, Hydrology.

ENVIRONMENTAL SETTING

Hazardous Materials and Wastes

During the preparation of this EIR, BaseCamp retained Condor Earth on behalf of GCRM to complete a Phase I Environmental Site Assessment (ESA) of the project site in accordance with the American Society for Testing and Materials (ASTM) Standard Practice E 1527-13 guidelines, subject to the limitations identified in the Phase I ESA Report (Condor Earth 2021). Condor's assessment was based on information obtained from a site reconnaissance, an EDR GeoCheck database report of the ASTM-specified data bases, USGS topographic maps and Federal Emergency Management Agency Flood Insurance Rate maps. The complete report of the Condor analysis are shown in Appendix H of this EIR.

The EDR database search returned a total of 309 database entries including numerous leaking underground storage tanks (LUSTs), State registered underground storage tanks (USTs), and State registered aboveground storage tanks (ASTs) among the other listings detailed in the Condor ESA. These records included other underground storage tanks, auto service and cleaning facilities and a Manufactured Gas Plants (MGP). None of the databases entries pertain directly to the project site.

Condor did not perform a comprehensive review of every database listing but focused on adjoining listed properties, properties with open/active cases, and listed properties upgradient from the site with respect to groundwater. All but one of the LUST cases within 1,000 feet have been granted regulatory closure status. Listed sites of note in the project vicinity include:

Gospel Center Rescue Mission Inc., 445 South San Joaquin Street, adjacent to the site. Asbestos containing waste was generated and disposed of at a licensed disposal facility in 2018. Condor found that this property does not pose a risk to the site.

Historic dry cleaner facilities were recorded 300 feet north-northeast of the site. Condor found that these locations do not appear to pose a risk to the site.

PG&E Gas Load Center, approximately 1,000 feet west-southwest of the site. This PG&E former Manufactured Gas Plant (MGP) produced gas from coal and/or crude oil from 1860 through 1930 and was shut down in 1955. The site is monitored by a total of 34 wells, now monitored semiannually. Remediation currently is by natural attenuation. In May 2000, contaminated soil was removed by excavation followed by paving and capping the area. Benzene was detected in groundwater during a March 2018 sampling event. Condor found that his location does not appear to pose a significant risk to the site.

H/S Auto Repair at 300 California Street is located approximately 1,000 feet northeast of the site. This facility, which appears on multiple lists, involved several fuel USTs and one waste oil UST removed in 1992 but which impacted site soils. Since 2007, groundwater extraction, on-site treatment, and discharge to the City of Stockton sewer system is ongoing.

The Condor assessment revealed no evidence of recognized environmental conditions, controlled recognized environmental conditions, or historical recognized environmental conditions in connection with the site except for the following:

It is Condor's opinion that the likely application of termiticides and lead-based paint around the structures constitutes a recognized environmental condition pursuant to the ASTM E 1527-13. Painted wood structures pre-dating the 1970s were likely painted with lead-based paint, and lead may be elevated in soil around the building perimeters. Soil around the building perimeters is also likely to contain chlorinated pesticides from termiticide application.

Airport Hazards

Development near airports is subject to hazards from accidents associated with aircraft arrivals and departures. In general, development that concentrates residents or employees near airports is discouraged. Airport land use compatibility plans for public airports generally delineate safety zones with specific information on the type of development allowed within each zone.

There are no public or public-use airports in the project area. The nearest airport to the project site is Stockton Metropolitan Airport, approximately 3.7 miles south of the project site. The airport offers scheduled passenger air service, along with general aviation and air cargo services. The project site is not within the Airport's land use compatibility planning area and therefore new development does not require airspace review or land use intensity review.

Wildfire Hazards

Wildland fires are an annual hazard in San Joaquin County. Wildland fires burn natural vegetation on undeveloped lands and include rangeland, brush, and grass fires as well as forest fires. Long, hot, and dry summers with temperatures often exceeding 100°F add to the county's wildland fire hazard. Human activities are among the major causes of wildland fires, which also include lightning. High hazard areas for wildland fires are the

grass-covered areas in the east and the southwest foothills of the county (San Joaquin County 2016b). The project site and surrounding areas are entirely urbanized and are not subject to wildfire risks.

REGULATORY FRAMEWORK

Federal Hazardous Material Regulations

At the federal level, the principal agency regulating the generation, transport and disposal of hazardous substances is the EPA, under the authority of the Resource Conservation and Recovery Act (RCRA). The RCRA established a federal hazardous substance "cradle-to-grave" regulatory program that regulates the generation, transportation, treatment, storage, and disposal of hazardous substances. Under RCRA, individual states may implement their own hazardous substance management programs if they are consistent with, and at least as strict as, the RCRA and receive EPA approval.

The EPA regulates hazardous waste sites under the Comprehensive Environmental Response Compensation and Liability Act (CERCLA), commonly referred to as Superfund. The purpose of CERCLA is to provide authorities the ability to respond to uncontrolled releases of hazardous substances from inactive hazardous waste sites that endanger public health and the environment. The Superfund Amendments and Reauthorization Act amended the CERCLA to, among other things, expand EPA's response authority, strengthen enforcement activities at Superfund sites, and broaden the application of the law to include federal facilities. In addition, new provisions were added dealing with emergency planning and community "right to know."

The U.S. Department of Transportation regulates the interstate transport of hazardous materials and wastes through implementation of the Hazardous Materials Transportation Act. This act specifies driver-training requirements, load labeling procedures, and container design and safety specifications. Transporters of hazardous wastes must also meet the requirements of additional statutes such as RCRA.

State Hazardous Material Regulations

Several state agencies regulate the transportation and use of hazardous materials to minimize potential risks to public health and safety, including the California Environmental Protection Agency (CalEPA) and the Office of Emergency Services. The California Highway Patrol and California Department of Transportation (Caltrans) enforce regulations specifically related to hazardous materials transport. Within CalEPA, the DTSC has primary authority to enforce hazardous materials regulations for the generation, transport and disposal of hazardous substances under the authority of the Hazardous Waste Control Law, with delegation of enforcement to local jurisdictions that enter into agreements with the agency.

Under both RCRA and the Hazardous Waste Control Law, the generator of hazardous waste must complete a manifest that accompanies the waste from the point of generation

to the ultimate treatment, storage, or disposal location. The manifest describes the waste, its intended destination, and other regulatory information. Copies must be filed with the DTSC. Generators must also match copies of waste manifests with receipts from the treatment, storage, or disposal facility to which it sends waste.

Local Hazardous Material Regulations

The Unified Hazardous Waste and Hazardous Management Regulatory Program, enacted in 1993, is a state and local effort to consolidate, coordinate, and make consistent existing programs regulating hazardous waste and hazardous materials management. CalEPA adopted implementing regulations for the Unified Program in 1996. The Unified Program is implemented at the local level by a Certified Unified Program Agency (CUPA), which, in San Joaquin County, is the San Joaquin County Environmental Health Department. As the CUPA, the Environmental Health Department administers various programs to minimize potential risks to public health and safety, such as the California Accidental Release Prevention, Hazardous Waste Generator, and aboveground and underground storage tank programs.

Another program for which the CUPA is responsible is the Hazardous Material Business Plan program. A Hazardous Material Business Plan must be prepared by any facility that handles a hazardous material or mixture containing a hazardous material that has a quantity equal to or greater than 55 gallons for liquids, 500 pounds for solids, or 200 cubic feet for a compressed gas at any one time during the reporting year.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact related to hazards and hazardous materials if it would:

- Create a significant hazard to the public or the environment through the routine transport, use, or disposal of hazardous materials,
- Create a significant hazard to the public or the environment through reasonably foreseeable upset and accident conditions involving the release of hazardous materials into the environment,
- Emit hazardous emissions or handle hazardous or acutely hazardous materials within one-quarter mile of an existing or proposed school,
- Be located on a site included on a list of hazardous material sites compiled pursuant to Government Code Section 65962.5, and as a result create a significant hazard to the public or the environment,

- For a project located within an airport land use plan or within two miles of a public or public-use airport if no plan has been adopted, result in a safety hazard or excessive noise for people residing or working in the project area,

- Impair implementation of or physically interfere with an adopted emergency response plan or emergency evacuation plan, or

- Expose people or structures, either directly or indirectly, to a significant risk of loss, injury, or death involving wildland fires.

CEQA Guidelines Appendix G also has a Wildfire section that states a project located in or near a State Responsibility Area or lands classified as being in a Very High Fire Hazard Severity Zone may have a significant impact on the environment if it would:

- Substantially impair an adopted emergency response plan or emergency evacuation plan,

- Due to slope, prevailing winds, and other factors, exacerbate wildfire risks, and thereby expose project occupants to, pollutant concentrations from a wildfire or the uncontrolled spread of a wildfire,

- Require the installation or maintenance of associated infrastructure (such as roads, fuel breaks, emergency water sources, power lines or other utilities) that may exacerbate fire risk or that may result in temporary or ongoing impacts to the environment, or

- Expose people or structures to significant risks, including downslope or downstream flooding or landslides, as a result of runoff, post-fire slope instability, or drainage changes.

Impact HAZ-1: Hazardous Material Transportation, Use, and Storage

Hazardous materials that are likely to be used and stored on the project site would include cleaning products and landscaping chemicals such as pesticides, herbicides, and fertilizers. The amount of these potential hazardous materials that would be stored for normal use would likely be below the threshold for preparation of a Hazardous Material Business Plan that would be submitted to the County Environmental Health Department. Anticipated quantities that would be used or stored would not present a health hazard to residents either onsite or in the vicinity. Project impacts related to transport, use, or storage of hazardous materials would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HAZ-2: Hazardous Material Releases

As noted in a) above, the proposed residential project would not involve the transport, use, or storage of hazardous materials in substantial quantities. Hazardous material storage and use on site would be confined to maintenance and cleaning activities. These materials are not expected to be used or stored in quantities large enough to pose a threat to human health and the environment if released.

Construction activities on the project site may involve the use of hazardous materials such as fuels and solvents, and thus create a potential for hazardous material spills. Construction and maintenance vehicles would transport and use fuels in ordinary quantities. Fuel spills, if any occur, would be minimal and would not typically have significant adverse effects. Contractors ordinarily have absorbent materials at construction sites to clean up minor spills. Other substances used in the construction process would be stored in approved containers and used in relatively small quantities, in accordance with the manufacturers' recommendations and/or applicable regulations.

As noted in the Significance Thresholds, a project could have a significant impact if it emits hazardous emissions or handles hazardous or acutely hazardous materials within one-quarter mile of an existing or proposed school. The nearest school to the project site is Spanos Elementary School, approximately 0.2 miles to the east. However, as noted above, project construction and operations would not require the handling or transport of acutely hazardous materials or waste that would endanger schools or the public. The use of small quantities of hazardous materials during project construction would be limited to the project site and would not occur near any schools. The project would not generate any substantial hazardous emissions. Overall, impacts related to releases of hazardous materials would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HAZ-3: Hazardous Material Sites

A Phase I ESA prepared by Condor Earth did not identify any recognized environmental conditions with the exception of potential contamination of soils surrounding the existing structures by termiticides and/or lead based paint. The Condor ESA indicates it is likely that termiticides and lead-based paint have been applied to and around the existing residential structures. This would involve a recognized environmental condition pursuant to the ASTM E 1527-13 as lead may be elevated in soils around the building perimeters, and these soils are also likely to contain chlorinated pesticides from termiticide application. Condor recommends that upon building removal, exposed soils adjacent to the structures be analyzed for lead and chlorinated pesticides, and that contaminated soil be remediated consistent with applicable regulatory standards, as provided in the mitigation measure specified below.

Level of Significance: Potentially significant

Mitigation Measures:

HAZ-1: Upon building removal, exposed soils adjacent to the structures shall be analyzed for lead and chlorinated pesticides in comparison to the applicable standard. Soil exceeding allowable contamination standards shall be subject to a Phase II study.

HAZ-2: If warranted by soil testing results, a Phase II Environmental Site Assessment shall be conducted to determine the location and extent of soil contamination and exceedance of applicable regulatory standards, and to make recommendations for remediation of any contamination determined to present a potential risk to human health. All recommendations shall be implemented prior to the start of building construction.

Significance After Mitigation: Less than significant

Impact HAZ-4: Airport Hazards

As noted, there are no public or public-use airports in the project area. There are no public or public-use airports in the project area. The nearest airport to the project site is Stockton Metropolitan Airport, approximately 3.7 miles south of the project site. The project site is not within the Airport Influence Area of Stockton Metropolitan Airport nor within any of its safety zones. It is also not within the Airport Influence Area of any other airports in San Joaquin County. The project would have no impact related to airport hazards.

Level of Significance: No impact

Mitigation Measures: None required

Impact HAZ-5: Interference with Emergency Vehicle Access and Evacuations

The project is not expected to obstruct South San Joaquin Street or any other public street during construction or once construction is completed. Project construction work would mostly occur on the project site. However, the project would involve minor improvement of the adjacent sidewalks and connections made to utility lines beneath San Joaquin Street. While construction work would be temporary and would cease once work is completed, it has the potential of restricting its use for emergency response or emergency evacuation. Mitigation presented below would ensure that adequate access would be maintained along public streets during construction activities thereby reducing potential impacts to a level that would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

HAZ-3: Prior to project construction involving work in off-site streets, the contractor shall coordinate with the City Department of Public

Works and the Stockton Police Department and the Stockton Fire Department if construction will require road closures or lane restrictions.

Significance After Mitigation: Less than significant

Impact HAZ-6: Wildfire Hazards

The project site is not in a region subject to wildfire hazards. The project would reduce any existing fire hazard on the site by replacing the existing old wood structures with a new building designed to current building codes and including sprinkler systems. Project impacts related to wildfires would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

11.0 HYDROLOGY AND WATER QUALITY

ENVIRONMENTAL SETTING

Surface Waters

The project site is located in the City of Stockton, which abuts the Sacramento-San Joaquin Delta. The Delta is a 600-square-mile area of waterways and islands of reclaimed land at the confluence of the Sacramento and San Joaquin Rivers. The Delta receives runoff from a watershed that covers approximately 45 percent of the State's land area, including flows from the Sacramento, San Joaquin, Mokelumne, and Cosumnes Rivers (Lund et al. 2007). Portions of the Stockton area are within the legally defined boundaries of the Delta, but the project site is not.

There are no streams or other surface waters on or adjacent to the project site. The nearest stream course is Mormon Slough, located approximately 0.13 miles south of the project site. The Slough near the project site does not typically support surface flows, which are diverted to a box culvert east of Wilson Way. Drainage in the project area is accommodated by the City of Stockton storm drainage system, elements of which are located in the streets surrounding the site. Natural streams elsewhere in the Stockton area have been extensively modified and are confined within levee systems.

Groundwater

The project site is within the Eastern San Joaquin County groundwater subbasin. The groundwater in the Stockton vicinity generally follows the surface topography, gradually sloping from east to west. As noted in Chapter 9.0, Geology and Soils, groundwater levels at the project site are 30-40 feet below the ground surface.

Groundwater in the San Joaquin County area moves from sources of recharge to areas of withdrawal. The project site is not in an area of substantial groundwater recharge in that the site and vicinity are extensively urbanized. Most recharge to the aquifer system occurs from the Delta and along active stream channels where extensive sand and gravel deposits exist.

The project site would connect to the water supply system of California Water Service (Cal Water); it would not involve any direct withdrawal of groundwater via new groundwater wells. Water supply for the site would be obtained from the available Cal Water supply, less than one-quarter of which comes from groundwater sources (Cal Water 2016). Chapter 16.0, Utilities and Service Systems, discusses project impacts on water supplies and concludes that project demands can be met by Cal Water with no significant impact on water supplies, including groundwater.

Flooding

According to the Flood Insurance Rate Maps prepared by the Federal Emergency Management Agency (FEMA), the project site lies within an area classified as Zone X. Zone X denotes areas outside the 100-year floodplain, but within the 500-year floodplain (FEMA 2009). Based on information provided by the San Joaquin County Public Works Department, the project site would not be subject to a 200-year flood at a depth of three feet or greater (SJCPWD 2016), which is the standard for urban flood protection in the Central Valley under SB 5 and companion bills.

The proposed project site, along with most of the Stockton area, is exposed to potential flooding from catastrophic failure of large dams located in the foothill areas to the east of the City. According to a dam failure plan prepared by the County Office of Emergency Services, the project site is potentially subject to inundation from failure of Camanche Dam, the south dikes of Camanche Reservoir, Pardee Dam, and Salt Springs Dam (San Joaquin County OES 2003). The risk of failure of these facilities has been judged to be low, because the likelihood of dam failure is low (City of Stockton 2007).

REGULATORY FRAMEWORK

Water Quality Control Plan

Surface water quality in the Central Valley is managed by the Central Valley RWQCB by means of the Water Quality Control Plan for the Sacramento River and San Joaquin River Basins (Basin Plan), revised in June 2015. The beneficial uses of surface waters in the region include municipal and domestic water supply; industrial service and process supply; agricultural irrigation; groundwater recharge; navigation; contact and non-contact recreation; commercial and sport fishing; migration of aquatic organisms; wildlife habitat; and habitat for rare, threatened, and endangered species. The RWQCB has determined that the quality of these waters does not fully support all the beneficial uses assigned to the water bodies in the project vicinity (RWQCB 2015). Water quality impacts are a result of tidal fluctuations; Sacramento River and San Joaquin River inflows; local agricultural, industrial, and municipal diversions and returns; and inadequate channel capacities.

National Pollutant Discharge Elimination System

The SWRCB has the responsibility under the federal Clean Water Act through the National Pollutant Discharge Elimination System (NPDES) for the regulation of storm water quality. SWRCB has adopted general permits for construction activity and industrial and commercial use. The Construction General Permit covers all construction activities that disturb at least one acre of soil.

As noted in Chapter 9.0, Geology and Soils, discharges subject to the Construction General Permit must develop and implement a SWPPP, which includes a site map and description of construction activities and identifies the Best Management Practices

(BMPs) that will be employed to prevent soil erosion and discharge of other construction-related pollutants that could contaminate nearby water resources.

Additional storm water regulation is established in the NPDES area-wide municipal separate storm sewer system (MS4) permit system administered by the SWRCB, which requires affected jurisdictions, including the City of Stockton, to adopt and implement a Storm Water Management Program (SWMP). The City of Stockton has adopted a SWMP, which is intended to minimize the potential storm water quality impacts of development. Program elements most applicable to land development include construction storm water discharge requirements and, the incorporation of post-construction BMPs in new development. The requirements of the SWMP are enforced primarily through the City's Phase 1 Storm Water NPDES permit, issued by the RWQCB, Central Valley Region (Order No. R5-2002-0181).

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on hydrology and water quality if it would:

- Violate any water quality standards or waste discharge requirements, or otherwise substantially degrade water quality,
- Substantially deplete groundwater supplies or interfere substantially with groundwater recharge such that there would be a net deficit in aquifer volume or a lowering of the local groundwater table,
- Substantially alter the existing drainage pattern of the area, including through the alteration of the course of a stream or river, in a manner which would result in substantial erosion or siltation on- or off-site,
- Substantially alter the existing drainage pattern of the area, including through the alteration of the course of a stream or river, or substantially increase the rate or amount of surface runoff in a manner which would result in flooding on- or off-site,
- Create or contribute runoff water which would exceed the capacity of existing or planned stormwater drainage systems or provide substantial additional sources of polluted runoff,
- Place housing within a 100-year floodplain as mapped on a federal Flood Hazard Boundary or Flood Insurance Rate Map or other flood hazard delineation map,
- Place within a 100-year flood hazard area structures which would impede or redirect flood flows,

- Expose people or structures to a significant risk of loss, injury, or death involving flooding, including flooding as a result of the failure of a dam or levee, or
- Inundation by seiche, tsunami, or mudflow.

Impact HYDRO-1: Surface Water Resources and Quality

As previously noted, there are no surface water resources on the site or in the project vicinity. Therefore, the project would have no direct effect surface waters. However, as noted in Chapter 9.0, Geology and Soils, construction activities would disturb soils, which could be transported off-site by runoff and could eventually enter surface waters. This potential impact would, however be reduced to a less than significant level by the City's standard implementation of its various storm water pollution prevention requirements.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HYDRO-2: Groundwater Resources

The project would not draw directly from groundwater but would be connected to the California Water Service (Cal Water) system. Less than one-quarter of the Cal Water which comes from groundwater sources (Cal Water 2016). Chapter 16.0, Utilities and Service Systems, discusses project impacts on water supplies and concludes that project demands can be met by Cal Water with no significant impact on water supplies, including groundwater.

Development of the project would replace existing residential uses land with more intensive residential development. As the project site is already urbanized, the project would not substantially reduce the amount of precipitation that currently percolates into the ground. Project impacts on groundwater are considered less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HYDRO-3: Drainage Patterns and Runoff

Proposed residential development of the site would further alter existing storm drainage patterns with the installation of new buildings, pavement and storm drainage facilities. In addition, proposed improvements on the project site would result in a small increase in the generation of additional runoff due to the introduction of impervious surfaces. This increase, if any, would be reduced by required implementation of City post-construction storm drainage requirements. As a result, the project would have a less than significant effect on drainage patterns and runoff.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HYDRO-4: Flood Hazards

The project site is in FEMA Zone X, which is outside the 100-year floodplain. The project involves the construction of new housing but not within the 100-year floodplain. The project is within the 200-year floodplain, which is more extensive than the 100-year floodplain; however, the project site would not be subject to 200-year flooding greater than three feet in depth, which would be consistent with required SB 5 findings related to 200-year flooding.

The project site is subject to potential inundation from failure of dams and dikes associated with foothill water storage reservoirs as well as levees confining the flows of project area streams. The probability of failure of these facilities is low at a given time, and these facilities are subject to maintenance, inspection and improvement as required to address predicted flows and flooding potential. Project impacts related to flooding are considered less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact HYDRO-5: Seiche, Tsunami, and Mudflow Hazards

The project site is in a topographically flat area distant from large bodies of open water. Because of this, the project would not be subject to any significant seiche, tsunami or mudflow hazards. The project would have a less than significant effect in this issue area.

Level of Significance: No impact

Mitigation Measures: None required

12.0 LAND USE, AGRICULTURE, POPULATION AND HOUSING

ENVIRONMENTAL SETTING

Land Use Patterns

The project site is located in the southern portion of the original town plat of the City of Stockton. This portion of the "downtown" area is bounded by Interstate 5 on the west, the Crosstown Freeway (SR 4) on the north, Charter Way on the south and Airport Way on the east. Land uses near the project north of Mormon Slough and Hazelton Avenue are a mix of residential and small-scale commercial uses, which include numerous structures dating to the early 20th century, and some areas of more modern development, including recent affordable housing, City park and school improvement projects between California and Stanislaus Streets.

Commercial uses in the area are concentrated along Lafayette, El Dorado and Center Streets and mixed with single- and multi-family residential uses west of South San Joaquin Street. East of South San Joaquin Street, residential uses of mixed ages and densities are predominant near the project site. Structures of historic age but mostly undetermined historical importance are common in this vicinity. East of Grant Street and extending to Union Street, industrial uses are predominant.

The block containing the project site is entirely urbanized, containing mostly older commercial and residential structures. The project site is occupied by two multi-family residential structures dating to the early 1900s. These structures, to be demolished by the project, are documented as being historically important. Additional information related to these historic structures is provided in Chapter 7.0 Cultural Resources and documented in detail in Appendices C and D. Existing land uses adjacent to the site include the GCRM offices to the south, a health clinic and GCRM Women's Facility to the north, other GCRM facilities, offices, retail commercial and residences to the west.

The Stockton General Plan designates the project site and surrounding area for Commercial use. From Center Street east, the City of Stockton zoning for Downtown Commercial, General Commercial and High-Density Residential uses. Lands in the eastern portion of the area are designated for General and Limited Industrial use. The project site is zoned for Commercial, General (CG) use; the Commercial, General designation can accommodate a range of commercial and residential land uses, including the proposed development with a Planning Commission Use Permit.

Agricultural Resources

Agriculture is an important part of the San Joaquin County economy. However, the project is not and has not been in agricultural use, or near other areas of agriculture, over the history of the City. The project site and surrounding lands were included in the original City plat and have been developed for urban uses since at least the early 1900s; the existing residences on the project site date from this period as well.

During preparation of the Phase 1 ESA for the project, Condor Earth Technologies obtained and reviewed Sanborn Fire Insurance Maps for the project site and vicinity. Briefly summarized, these maps indicated site uses in 1895 to include a residence, stable, windmill and water tank. By 1917, the stable and storage tank were removed, and two two-story residential structures had been constructed on the site. These structures remain on the 1950 Sanborn map and are present on the site to this day.

The California Important Farmland Maps, prepared by the California Department of Conservation, designate the viability of lands statewide for farmland use. The project site and vicinity are designated Urban/Built-up Land and do not have agricultural value. The project site and vicinity are not Prime Farmland.

Forest products such as timber are considered agricultural products. There are no designated forest lands (i.e., National Forest lands, State forests, or lands zoned for timber production) on the project site or within the City. Therefore, impacts on forestry resources will not be analyzed in this EIR.

The Land Conservation Act of 1965, commonly known as the Williamson Act, was enacted to preserve farmland in California. Under the Williamson Act, a contract is executed between landowners and local governments to voluntarily restrict development on property in exchange for lower property tax assessments based on the existing agricultural land use. The Williamson Act program is inapplicable to the project site; there are no Williamson Act contracts applicable to the project site.

Population and Housing

As of January 1, 2020, the population of Stockton was estimated at 318,522, an increase of 9.2% from its 2010 population as recorded by the U.S. Census Bureau (California Department of Finance 2020). Table 13-2 below shows population and growth trends in Stockton, San Joaquin County, and the State of California from 2010 to 2020. The U.S. Census Bureau recently completed the 2020 U.S. Census; results are not yet available.

As of January 1, 2020, Stockton had an estimated 101,235 housing units. Single-family detached units (typical houses) accounted for approximately 64.4% of total housing units in Stockton, with multifamily units of two or more per building accounting for approximately 26.9%. The remaining units were single-family attached units and mobile homes (California Department of Finance 2020).

TABLE 12-1
POPULATION OF STOCKTON, SAN JOAQUIN COUNTY, AND CALIFORNIA

Jurisdiction	Population April 1, 2010	Population January 1, 2020	Population Growth 2010-2020
Stockton	291,707	318,522	9.2%
San Joaquin County	685,306	770,385	12.4%
State of California	37,253,956	39,782,870	6.8%

Source: California Department of Finance 2020.

Employment data from the California Employment Development Department indicate that in the Stockton-Lodi Metropolitan Statistical Area, which covers San Joaquin County, the average annual unemployment rate was 5.9% in 2019, the most recent year such data were available. This marked a decrease from 6.1% in 2018 and from a peak of 16.5% in 2010 (EDD 2020a). By comparison, the unemployment rate in California in 2019 was 4.0% (EDD 2020b). Unemployment rates in 2020 increased dramatically because of business closures and labor force reductions from the COVID-19 pandemic and actions to contain its spread. While there has been a recent decrease in the unemployment rate, the employment situation in the Stockton area remains uncertain.

As discussed in Chapter 1.0, Like many larger cities in California, the City of Stockton has seen a significant rise in the homeless population over the last several years. According to the San Joaquin County Continuum of Care Point in Time Count completed in January 2019, Stockton contributed to 58% of the County's homeless population, with a total count of 921, 65% being male. The same count generated in January 2017 reported the same demographic as a total count of 567 (SJCoC, 2019). A large proportion of the homeless population is concentrated in the area south of the Crosstown Freeway extending to Mormon Slough and including the immediate project area. The GCRM, the Stockton Shelter for the Homeless, Stockton Women's Shelter and several other agencies are actively addressing what Governor Newsom termed a homelessness crisis in his 2020 and 2021 State of the State Addresses.

REGULATORY FRAMEWORK

City of Stockton General Plan 2040

The City of Stockton adopted its current General Plan 2040 in 2018. The Stockton General Plan is a long-range plan to guide physical, social, and economic development within its Planning Area. It accomplishes this by setting objectives, policies, and standards that will guide future growth within the Planning Area to the year 2040. The General Plan consolidates the State-mandated general plan elements into four multi-faceted chapters, plus the Housing Element. The General Plan Land Use Map illustrates the preferred development pattern for the City, allocating portions of the City for specific

types of development, such as residential, commercial, and industrial, among others. The current City General Plan designation for the project area is Commercial.

City of Stockton Housing Element

In 2016, the City adopted the City of Stockton 2015-2023 Housing Element as part of its General Plan. The Housing Element, one of the required elements of a General Plan, establishes goals and objectives that encourage availability and development of housing adequate to meet the needs of residents at all income levels during the planning period, including the homeless. The following goals and policies are of particular relevance to the project.

> Goal E-7. Provide a range of housing opportunities and services for households with special needs, including extremely low-income residents, farmworkers, persons with language barriers, seniors, large households, single mothers, persons with disabilities, persons diagnosed with HIV/AIDS, and homeless persons.
>
> > Policy HE-7.1 Special Needs Accommodation. The City shall seek to accommodate housing and shelter for residents with special needs through appropriate zoning standards and permit processes.
> >
> > Policy HE-7.2 Homeless Needs. The City shall strive to address the shelter needs of its homeless residents and continue to support the provision of facilities and services to meet the needs of homeless individuals and families.
> >
> > Implementation Measure 23. Continue to Support Organizations Assisting Homeless Persons: The City shall annually apply for and continue to pursue State and Federal funds available to the City, private donations, and volunteer assistance to support homeless shelters. The City shall continue to provide financial assistance from its Emergency Solutions Grant (ESG) funding to homeless service providers and continue to support additional development of shelter facilities as requested by shelter providers. In addition, the City shall review the need for additional shelter facilities and services when it updates its Consolidated Plan.

Non-profit contributions to housing, including the proposed project and other GCRM programs, are supported by the City. Project planning, environmental studies and preparation of this EIR are funded by a City of Stockton grant.

Emergency shelter and transitional housing programs in Stockton are parts of an overall Continuum of Care program oriented to assisting homeless persons in moving from homelessness to transitional housing to permanent housing and independent living. Non-profit entities like GCRM and the Stockton Shelter for the Homeless contribute to this effort while other organizations and agencies like the Housing Authority of the County of San Joaquin, Visionary Home Builders and the Central Valley Low Income Housing

Corporation contribute to develop and make available permanent and transitional housing facilities of low-income persons.

Stockton Municipal Code – Development Code

Title 16 of the Stockton Municipal Code contains the zoning and development regulations for the City. The zoning regulations provide for specific guidelines for the development of the City in accordance with the Stockton General Plan. Zones are designated for various types of development, and the land uses allowed within each zone are specified. Some land uses in a zone are allowed "by right," while others are allowed with City approval.

The current zoning for the project site is CG, General Commercial. The CG zone allows for development of Social Services Facilities, including Emergency Shelters, subject to a Planning Commission Use Permit.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on land use and population if it would:

- Physically divide an established community,
- Cause a significant environmental impact due to a conflict with any land use plan, policy, or regulation adopted for the purpose of avoiding or mitigating an environmental effect,
- Convert Prime Farmland, Unique Farmland, or Farmland of Statewide Importance (Farmland), as shown on the maps prepared pursuant to the Farmland Mapping and Monitoring Program, to non-agricultural use,
- Conflict with existing zoning for agricultural use or a Williamson Act contract,
- Involve other changes in the existing environment which, due to their location or nature, could result in conversion of Farmland to non-agricultural use,
- Induce substantial unplanned population growth in an area, either directly (for example, by proposing new homes and businesses) or indirectly (for example, through extension of roads or other infrastructure), or
- Displace substantial numbers of existing people or housing, necessitating the construction of replacement housing elsewhere.

Impact LUP-1: Division of Communities

The project site is a part of a existing residential/commercial area that is subject to daily use by numerous homeless persons. The project would provide additional housing units for homeless persons contributing up to 178 beds to the supply of emergency shelter facilities in the project vicinity. The project would not divide existing residential

communities in the area but would accommodate homeless persons in a modern building contributing aesthetically to the existing downtown commercial and residential streetscape. The project would have no impact on division of established communities.

Level of Significance: No impact

Mitigation Measures: None required

Impact LUP-2: Conflict with Applicable Plans, Policies, and Regulations

The proposed project is consistent with existing Stockton General Plan designations and zoning, both of which allow for the residential services encompassed proposed by the project. The project would be consistent with and substantially contribute to implementing portions of the Stockton Housing Element related to provision of emergency shelter facilities.

With proposed mitigation, the project would have no known significant effect on environmental resources and would increase the supply of housing for the homeless population. Therefore, the project is not expected to conflict with any City plans and ordinance containing provisions designed to avoid or minimize environmental effects.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact LUP-3: Conversion of Farmland

The project site contains no farmland and supports no agricultural uses. Development of the proposed residential facility would have no farmland conversion effect.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact LUP-4: Agricultural Zoning and Williamson Act

The project site is designated and zoned for urban development. The project site is not under a Williamson Act contract nor within a Farmland Security Zone. The project would have no impact on this issue.

Level of Significance: No impact

Mitigation Measures: None required

Impact LUP-5: Indirect Conversion of Agricultural Lands

Neither the project site nor any lands in the general project vicinity are in agricultural use. The project would not convert existing agricultural lands and would have no other direct or substantial indirect effect on agriculture in the Stockton vicinity. The project would have no effect on indirect conversion of Farmland.

Level of Significance: No impact

Mitigation Measures: None required

Impact LUP-6: Inducement of Unplanned Population Growth

The purpose of the project is to meet shelter needs of the existing Stockton homeless population. The project would have no known direct or indirect effect on population growth in Stockton.

Level of Significance: No impact


Mitigation Measures: None required

Impact LUP-7: Displacement of Housing and People

The project site is currently occupied by two residential structures housing approximately 10 people on an ongoing basis. Prior to project construction, existing residents will be relocated to other available GCRM beds. These existing residential beds will be replaced by 144 new beds plus potential overflow capacity. The project would have no impact on displacement of people or housing, and involve a beneficial impact on housing supply for homeless persons.

Level of Significance: No impact


Mitigation Measures: None required



SOURCE: City of Stockton

BaseCamp Environmental

Figure 12-1
GENERAL PLAN AMENDMENT



SOURCE: City of Stockton

Figure 12-2
ZONING MAP

13.0 NOISE

ENVIRONMENTAL SETTING

Noise Background

Noise is "unwanted sound," or sound that is annoying and/or harmful due to its loudness, pitch, or duration. Adverse effects of noise include annoyance, sleep and speech interference, and hearing loss. Noise analysis criteria are related to both annoyance and environmental health levels. Exposure of existing receptors to elevated noise levels can result from construction activities near existing residences, increases in traffic, or added noise sources.

The decibel (dB) scale was devised to provide a manageable way to measure sound loudness, which is dependent upon sound pressure level and frequency, among other things. Within the usual range of environmental noise levels, perception of loudness is relatively predictable, and can be approximated by the A-weighting network, which represents the way the human ear perceives noise.

Community noise is commonly described in terms of the "ambient" noise level as measured by the equivalent sound level (L_{eq}), or “average” noise level. The L_{eq} is the foundation for other community noise metrics such as the Day-Night Average Level (L_{dn}), which is weighted +10 dB during the hours between 10:00 p.m. and 7:00 a.m. to account for greater noise sensitivity during those times.

Existing Noise Conditions

Existing ambient noise in Stockton was measured during preparation of the Noise Element of the Stockton General Plan; ambient noise measurements were taken at several locations, the nearest to the project site being site LT-1, in the downtown area north of the Crosstown Freeway. Ambient noise at this location ranged from a minimum of 51 dB to a maximum of to 104 dB; the Community Noise Equivalent Level at this location (CNEL) was measured at 75 dB.

The noise environment at the project site and vicinity is primarily related to traffic noise on South San Joaquin Street and noise from the Crosstown Freeway (SR 4), which is approximately 0.14 miles north of the site. The Noise Element of the Stockton General Plan indicates that the project vicinity will be subject to noise levels of between 60 and 65 dB during the planning period. South San Joaquin Street, which is designated as a Collector street in the Stockton General Plan, supports traffic levels of approximately 2,460 trips per day, which would produce minor traffic noise relative to noise from the Crosstown Freeway.

Groundborne Vibration

Groundborne vibration is not a common environmental problem. It is typically associated with transportation facilities, although it is unusual for vibration from sources such as buses and trucks to be perceptible, except in locations very close to major roads. Some common sources of groundborne vibration are heavy trucks, trains, buses on rough roads, and construction activities such as blasting, pile driving, and operating heavy earth-moving equipment. The project site is not subject to known existing vibration sources; traffic along South San Joaquin Street is generally composed of light vehicles.

REGULATORY FRAMEWORK

Stockton General Plan Noise Element

The Noise Element is one of the required elements of a General Plan. In Stockton, the Noise Element sets forth objectives and policies that are intended to protect City citizens from the harmful and annoying effects of exposure to excessive noise, to prevent noise-producing uses from encroaching upon existing or planned noise-sensitive uses, and to emphasize the reduction of noise impacts through planning and project design.

The Noise Element Land Use Compatibility Table indicates that noise levels of up to 60 dB are considered acceptable for Residential land uses and up to 70 dB for Urban Residential Infill projects. Noise levels of up to 70 dB and 80 dB respectively are Conditionally Acceptable.

Chapter 16.60 - Noise Standards

Stockton Municipal Code Chapter 16.60 incorporates the City's Noise Control Ordinance. Section 16.60.040 states that new or expanded commercial, industrial, and other land use-related noise sources shall mitigate their noise levels such that they do not adversely impact noise-sensitive land uses (e.g., residences) and do not exceed City noise standards.

Table 14-3 shows the City noise standards that would apply to the project. The Stockton Municipal Code specifies other noise standards applicable to industrial land uses. The maximum sound level produced by industrial land uses or by other permitted noise-generating activities within an industrial (IL, IG, or PT) or public facilities (PF) zone shall not exceed 80 dB, and the L_{eq} from these land uses shall not exceed 70 dB during daytime or nighttime hours as measured at the property line of any other adjoining IL, IG, PT, or PF zone.

Section 16.60.030 deems the following activities as violations of the Noise Control Ordinance: construction noise between the hours of 10:00 p.m. and 7:00 a.m., loading and unloading operations between the hours of 10:00 p.m. and 7:00 a.m., public nuisance noise, and stationary non-emergency signaling devices, among other activities. Regarding construction noise, Section 16.60.030 also includes restrictions on construction noise. This section prohibits operating or causing the operation of tools or equipment on private

property used in alteration, construction, demolition, drilling, or repair work between the hours of 10:00 p.m. and 7:00 a.m. so that the sound creates a noise disturbance across a residential property line, except for emergency work of public service utilities.

TABLE 13-1
EXTERIOR HOURLY NOISE LEVEL STANDARDS
FOR STATIONARY NOISE SOURCES

	Outdoor Activity Areas	
Noise Level Descriptor	**Day (7:00 a.m. to 10:00 p.m.)**	**Night (10:00 p.m. to 7:00 a.m.)**
Hourly L_{eq}, dB	55	45
Maximum level, dB	75	65

Note: Each of the noise level standards specified above shall be increased by 5 dBA for simple tone, noise consisting primarily of speech or music, or recurring impulsive noises.
Source: Stockton Municipal Code Section 16.60.040.

Stockton Metropolitan Airport Land Use Compatibility Plan

As described in Chapter 11.0, Hazards, the nearest public airport is Stockton Metropolitan Airport, approximately 3.7 miles southwest of the site. The ALUCP establishes noise contours around Stockton Metropolitan Airport based upon forecasted aircraft activity. The outermost noise contour (60 dB), as delineated in the Stockton Metropolitan Airport ALUCP, does not extend to the project site.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to the recently updated Appendix G of the CEQA Guidelines, a project may have a significant impact related to noise if it would result in:

- Generation of a substantial temporary or permanent increase in ambient noise levels in the vicinity of the project in excess of standards established in the local general plan or noise ordinance, or applicable standards of other agencies,
- Generation of excessive groundborne vibration or groundborne noise levels, or
- For a project located within the vicinity of a private airstrip or an airport land use plan, or within two miles of a public or public use airport if no plan has been adopted, expose people residing or working in the project area to excessive noise levels.

Impact NOISE-1: Generation of or Exposure to Noise Levels in Excess of Standards – Project Operations

Operation of the project once constructed is not expected to result in any substantial increases in noise on the site or in the project vicinity. All activity related to emergency shelter operations would occur within the proposed structure or in outdoor areas already in use by GCRM and its clients. The project is not expected to result in any substantial change in traffic on roadways serving the project area. Traffic generated by the project is expected to be none to minimal and not of any volume that could result in a measurable change in ambient noise.

Existing ambient noise on and near the project is within acceptable noise levels for outdoor uses in residential areas. As a result, the project will be able to achieve the maximum allowable interior noise level for residential uses of 45 dB using conventional construction.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact NOISE-2: Project Construction Noise

Construction of the proposed project would involve temporary increases in ambient noise levels on and near the site. Equipment involved in construction would generate maximum noise levels ranging from 76 to 90 dB at a distance of 50 feet, as indicated in Table 13-4. Additional construction noise would be generated by increased truck traffic during the construction phase.

TABLE 13-2
CONSTRUCTION EQUIPMENT NOISE

Type of Equipment	**Maximum Level, dB at 50 feet**
Backhoe	78
Compactor	83
Compressor (air)	78
Concrete Saw	90
Dozer	82
Dump Truck	76
Excavator	81
Generator	81
Jackhammer	89
Pneumatic Tools	85

Source: FHWA 2006.

Although project construction noise would cease once construction work is completed, this is considered a potentially significant short-term impact, as the project site is near other existing residential development, including homes across South San Joaquin Street. Temporary noise impacts resulting from project construction would be minimized by implementation of mitigation measures, specified below, that would restrict construction days and hours and would require the use of mufflers on construction equipment. The mitigation measures would reduce construction noise to a level that would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

NOISE-1: Project construction shall be restricted to the hours of 7:00 a.m. to 7:00 p.m. Monday through Saturday. No construction shall occur on Sundays or national holidays without prior approval from the Community Development Director.

NOISE-2: All equipment used on the construction site during all project phases shall be fitted with mufflers in accordance with manufacturers' specifications. Mufflers shall be installed on the equipment at all times on the construction site.

Significance After Mitigation: Less than significant

Impact NOISE-3: Groundborne Vibrations

As noted, some common sources of groundborne vibration are trains, buses on rough roads, and construction activities such as blasting, pile driving, and operating heavy earth-moving equipment. The project would not involve, or be in proximity to, any of these potential sources. The project would not be exposed to groundborne vibrations.

Equipment used in project construction activities could generate groundborne vibration that may be detected in sensitive land uses nearby. In most cases, vibration caused by typical construction equipment does not result in adverse effects on people or structures. Construction noise itself typically overshadows any meaningful ground vibration effects on people (Caltrans 2013). Project impacts related to groundborne vibrations would therefore be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact NOISE-4: Airport and Airstrip Noise

As discussed in Chapter 10.0, Hazards and Hazardous Materials, there are no airports, airstrips or aircraft operations in the project area. The project would have no impact related to airport or airstrip noise.

Level of Significance: No impact

Mitigation Measures: None required

14.0 PUBLIC SERVICES AND RECREATION

This section addresses the potential direct and indirect environmental effects of the proposed project on providers of the following public services:

- Fire protection
- Police protection
- School
- Parks and recreation
- Other public services (e.g., libraries, hospitals, courthouses)

Chapter 16.0 Utilities and Energy describes public utilities services in the project area, along with utility services provided by private companies.

ENVIRONMENTAL SETTING

Fire Protection

The Stockton Fire Department is responsible for fire protection services for the project site. The Fire Department has 12 stations throughout the Stockton metropolitan area. The closest station to the project site is Station 2, an engine company with three on-duty firefighters located at 110 West Sonora Street, approximately 0.3 miles west of the project site. Response time to the project site would be less than five minutes. The second responder would be Station 9, another single engine company with three firefighters, located at 550 East Harding Way, approximately 1.4 miles north of the project site. All public fire protection agencies in San Joaquin County operate under a master mutual aid agreement, under which other fire agencies may be called upon to assist should the resources of one agency be exhausted (San Joaquin County 2016b).

Police Protection

The Stockton Police Department is responsible for law enforcement service to the project site and vicinity. The main station is located at 22 East Market Street, approximately .2 miles northwest of the project site. The Police Department has over 400 sworn officers. It is the Police Department's policy to respond to all emergency calls within a three- to five-minute period. The Police Department has no adopted service levels.

Schools

The project site is within the boundaries of the Stockton Unified School District, which provides school services from kindergarten to 12th grade for approximately 40,000 students at 54 school locations. The nearest school facilities to the site include Hazelton Elementary School, located at 535 West Jefferson Street, approximately 1.1 miles southwest of the project site, Spanos Elementary School, located at 536 South California Street, approximately two blocks east of the project site, and Edison High School Located at 100 Martin Luther King, Jr. Blvd., approximately 1.0 miles south of the site.

Parks and Recreational Services

The City of Stockton provides park and recreational services to the project site and the City as a whole. Eden Gleason Park is the nearest City park, approximately 0.2 miles east of the project site and is equipped with picnic tables, playgrounds, a sports field, and restrooms. San Joaquin County manages Micke Grove Regional Park and Zoo, approximately 9 miles northeast of the project site. Facilities at Micke Grove include a zoo, Wortley Lake with a 40-foot water fountain, the Japanese Garden, the San Joaquin County Historic Museum, and the Fun Town at Micke Grove. The park also has numerous playgrounds, picnic areas, a disc golf course, and a water play area. San Joaquin County also manages Oak Grove Regional Park, approximately 8.5 miles northwest of the project site. Oak Grove Regional Park provides 180-acres of recreation with two nature trails, a 10-acre lake, nature center, several picnic shelters and playgrounds.

Other Public Services and Facilities

Other public facilities include public libraries and courthouses. Libraries in San Joaquin County have merged with the library system of the City of Stockton. The nearest library to the project site is the Cesar Chavez Central Library, located at 605 N El Dorado Street, approximately 1.0 miles north of the site. All county courthouses are staffed and maintained by the State of California. San Joaquin County has its main courthouse in Stockton, approximately 0.4 miles north of the site, with branches in Lodi and Manteca.

REGULATORY FRAMEWORK

SB 50

SB 50, enacted in 1998, created the present School Facility Program, which is a State/local match program for the funding of new kindergarten-12th grade school facilities and the modernization of existing facilities. SB 50 also created several statutory changes in development fees for school facilities, the most notable effect being the pre-emption of school mitigation by the State. Satisfaction of the development fee process outlined in the statute is deemed to be "full and complete mitigation" of the impacts upon school

facilities by new development, regardless of the identified level of impact, including mitigation for CEQA purposes.

SB 50 established a base fee for both residential and commercial/industrial development. This base has been adjusted for inflation every two years. School districts must establish the nexus between the development and the need for school facilities via a fee justification study to impose the biannual increase. Fees are levied and collected at the time the building permit is issued. District certification of the payment of the applicable fee is required before a city or county can issue the building permit.

City of Stockton Public Facility Fees

The City has established Public Facility Fees to be imposed on residential and non-residential development to defray the costs of new or expanded public facilities that may be necessary to serve the new development. Among the facilities that would be supported by these fees are fire stations, police station expansion, parkland, community recreation centers, and libraries. These fees are revised annually by the City Council based on inflation, indices, and fee studies. The Public Facility Fees are imposed by ordinance and collected when building permits are issued.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on the environment related to public services if it would result in substantial adverse physical impacts associated with the provision of new or physically altered governmental facilities, or generate a need for new or physically altered governmental facilities, the construction of which could cause significant environmental impacts, in order to maintain acceptable service ratios, response times or other performance objectives for:

- Fire protection,
- Police protection,
- Schools,
- Parks, or
- Other public facilities.

For recreational facilities and services, CEQA Guidelines Appendix G indicates that a project may have a significant impact on the environment if it would:

- Increase the use of existing neighborhood and regional parks or other recreational facilities such that substantial physical deterioration of the facility would occur or be accelerated, or

- Include recreational facilities or require the construction or expansion of recreational facilities which might have an adverse physical effect on the environment.

Impact PSR-1: Fire Protection

The project would result in the removal of two 100+ year old multi-family residential structures providing 19 beds for homeless men and replace them with a single new building providing shelter for 144 homeless people. It is anticipated that replacement of the existing wooden structures with a modern residential building equipped with adequate access, alarm services and fire sprinklers, would not generate any substantial new demand for fire protection services. Fire services needs associated with the project will be served by the Stockton Fire Department from existing facilities and will not require development of new or expanded fire protection facilities. The project, along with other new development, will be required to pay Public Facility Fees to the City for future expansion of Fire Department facilities required by urban expansion.

The location of construction materials and equipment on the project site during project construction may involve temporary new fire risk if fire suppression access and water supply is not in place. This concern would be addressed by the mitigation measure below. With implementation of this mitigation measure, impacts on fire protection services would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

SERV-1: The contractor shall incorporate adequate access, water supply, alarm and other fire suppression and emergency access/response needs in the proposed project design and shall provide for adequate fire control during construction in coordination with the Fire Department.

Significance After Mitigation: Less than significant

Impact PSR-2: Police Protection

Development of new housing for homeless persons would likely involve an incremental net reduction in policing demands associated with the homeless population. The proposed facility would be incorporated into the existing GCRM campus, which maintains 24-hour manned security. These demands can be served by the Stockton Police Department without new or expanded police protection facilities. The project will be required to pay Public Facility Fees to the City to provide for future construction of Police Department

facilities that may be required to serve continuing urban development in the City as a whole.

Project construction would, through the concentration of construction materials and equipment on the site, involve new crime opportunities during the construction period. This issue would be addressed by providing for adequate security on the construction especially after hours, as required by the mitigation measure below. With implementation of this mitigation measure, impacts on police protection services would be less than significant.

Level of Significance: Potentially significant

Mitigation Measures:

SERV-2: The developer shall coordinate with the Stockton Police Department as required to establish adequate security and visibility of the construction site. Measures that the Police Department may require include, but are not limited to, secured fencing around the project site, a licensed uniformed security guard present when the project site is not active, or video surveillance 24 hours per day.

Significance After Mitigation: Less than significant

Impact PSR-3: Schools

The project site is within the boundaries of the Stockton Unified School District. The project, which would be age-restricted to 18 years of age and older, would not generate new student load. It is assumed that GCRM would, however, be required to contribute school impact fees toward the construction of new schools, which would be a benefit to the school district. Under the provisions of SB 50, the payment of impact fees is considered adequate mitigation for CEQA purposes. Project impacts on schools would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact PSR-4: Parks and Recreational Facilities

The project would not involve any direct effects on parks or recreational facilities, none of which are located in the immediate project vicinity. Since the project is unlikely to generate a population increase, it would not generate a demand for new or expanded parks or recreational facilities or services. Project impacts on recreational facilities are considered less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact PSR-5: Other Public Facilities

Since the project is unlikely to generate a population increase, it is anticipated that the project would not generate a demand for additional library, hospital, or courthouse services. Provision of shelter to a portion of the homeless population could be expected to incrementally reduce demands on these other public facilities and services. No new or expanded facilities would be required. Project impacts on other public facilities would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

15.0 TRANSPORTATION

ENVIRONMENTAL SETTING

Vehicular access to and from the project site, the project vicinity and downtown Stockton is provided by the Crosstown Freeway (SR 4), which provides access to central and south-central Stockton and connects Interstate 5 to the west and SR 99 to the east. Access from the freeway to surface streets is provided at El Dorado/Center Streets and Stanislaus Street interchanges.

South San Joaquin Street is a designated Collector street that intersects the east-west streets of the downtown grid; South San Joaquin Street is continuous across SR 4 as an undercrossing. The street provides four travel lanes with on-street parking and wide sidewalks on both sides within an 80-foot right-of-way. Existing average daily traffic on South San Joaquin street amounts to approximately 3,000 vehicle trips per day (2019 Traffic Volume Flow Map, City of Stockton).

Lafayette Street, which parallels SR 4 two blocks north of the project site, is a one-way east-west Collector street with daily traffic of approximately 3,000 vehicle trips per day near the project site. Lafayette Street is a two-lane street with on-street parking and wide sidewalks on both sides within an approximately 60-foot right-of-way.

Hazelton Avenue, two blocks south of the project site, is an east-west Collector with daily traffic of approximately 4,400 vehicle trips per day. This four-lane street has sidewalks and on-street parking on both sides. Right-of-way width along South San Joaquin Street widens from 80 feet to 100 feet at South San Joaquin Street; west of South San Joaquin, Hazelton Avenue is median-divided.

Streets at and near the site have concrete sidewalks of varying widths on both sides. There are no existing or planned bikeway designations along South San Joaquin Street.

The San Joaquin Regional Transit District (SJRTD) is the primary provider of public transportation service in Stockton, offering fixed-route, flexible fixed-route, and dial-a-ride services in Stockton. Fixed route services within the Stockton Metropolitan Area are provided by standard service buses that provide connections to most areas of Stockton and Metro Express buses with increased frequencies along major corridors in Stockton. Most fixed-route buses stop within 0.5 miles of the project site at the Downtown Transit Center.

SJRTD also offers Metro Hopper, a deviated fixed route bus service which serves popular destinations throughout Stockton. There are eight Metro Hopper routes within the city limit that run approximately every hour. These lines can deviate from their route up to approximately one mile which increases transit coverage to approximately 75 percent of

the Stockton Metro Area for Americans with Disabilities Act-certified customers. The project site is reachable by Metro Hopper Routes 5 and 9 (Stockton 2040 General Plan Update, SJRTD 2019).

There are no railroads in the immediate vicinity of the project site. Railroad lines are located about four blocks to the south and seven blocks to the east. A relatively large railroad switching and makeup yard extends southernly from a point on this line at Charter Way.

There are no airports or airstrips in the vicinity of the project site.

REGULATORY FRAMEWORK

CEQA Guidelines Section 15064.3

SB 743 into CEQA analysis. SB 743 was enacted in 2013 with the intent to balance congestion management needs and the mitigation of the environmental impacts of traffic with statewide GHG emission reduction goals, mainly by developing an alternative mechanism for evaluating transportation impacts. Section 15064.3 of the CEQA Guidelines states that VMT is the preferred method for evaluating transportation impacts, rather than the commonly used LOS. The VMT metric measures the total miles traveled by vehicles as a result of a project. VMT accounts for the total environmental impact of transportation associated with a project, including use of non-vehicle travel modes.

City of Stockton General Plan

The Transportation and Circulation Element of the Stockton General Plan sets forth policies and implementation measures related to transportation in the City. Policy TC-2.1 of the Circulation Element states that the City shall maintain LOS D or better for all City streets, with some exceptions that do not include East Hammer Lane and Maranatha Drive adjacent to the project site.

City of Stockton Public Facility Fees

The City has established Public Facility Fees to be imposed on residential and non-residential development to defray the costs of new or improved streets that may be necessary to serve the new development. Among the facilities that would be supported by these fees are street improvements and traffic signals. These fees are revised periodically by the City Council based

City of Stockton Bicycle Master Plan

On December 2017, the City adopted an update to its Bicycle Master Plan, which was originally adopted in 2007. The 2007 Plan was developed and adopted as part of the City's General Plan update to provide a comprehensive system of bicycle lanes on

arterial streets, bicycle routes on residential streets, and bicycle paths. The 2017 update reorients the selection and prioritization of investments in bicycle facilities and describes the highest priority projects to improve connectivity, safety, and mode shift and access. Neither existing nor proposed bicycle facilities have been designated in the immediate vicinity of the project site.

Regional Transportation Plans

Regional transportation plans applicable to Stockton have been prepared by SJCOG. SJCOG is a joint powers authority comprised of the County of San Joaquin and the cities of Stockton, Lodi, Manteca, Tracy, Ripon, Escalon, and Lathrop. The primary role of SJCOG is to foster intergovernmental coordination within San Joaquin County. SJCOG is overseen by a Board of Directors which allocates funding for transportation improvements. The Board also establishes regional transportation policies and programs. SJCOG transportation plans include the Regional Transportation Plan/Sustainable Communities Strategy, Regional Congestion Management Plan and regional plans for Bicycle, Pedestrian, and Safe Routes to Schools and Regional Transit Systems among several others with limited relevance to the project; these plans are not discussed further here.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact related to transportation if it would:

- Conflict with a program, plan, ordinance, or policy addressing the circulation system, including transit, roadway, bicycle, and pedestrian facilities,
- Conflict or be inconsistent with CEQA Guidelines Section 15064.3, subdivision (b),
- Substantially increase safety hazards due to a geometric design feature (e.g., sharp curves or dangerous intersections) or incompatible uses (e.g., farm equipment), or
- Result in inadequate emergency access.

Impact TRANS-1: Conflict with Traffic Plans, Ordinances, and Policies

The proposed project is intended to provide emergency shelter for the existing population of homeless men in Stockton. By and large, few members of the target population have automobiles for transportation and are thus independent of non-public surface transportation. The GCRM estimates that approximately 10% of the project population, or 15-20 men at any one time, may have the use of motor vehicles for work, school or

other transportation purposes. Transportation needs of other project residents will typically be met by walking, bicycling or use public transit systems. Increased staffing associated with the project will consist of three new full-time or full-time equivalent Case Managers.

Resident-owned and employee vehicles will not initially be provided with on-site parking and would need to be parked in on-street spaces or existing parking garages in the downtown area. There is a small area of existing parking on the west end of the project site but no new parking will be added.

This would result in a small varying demand on parking in the general project vicinity. Based on the provisions of its proposed strategic plan, the purchase of campus-adjacent parking areas will be a #1 priority. Vehicular traffic generated by the project will therefore be distributed to the general project neighborhood. Traffic generated by these few persons would amount to less than 100 trips per day, perhaps 10 trips during AM or PM peak hours; traffic generation would in any event be minor from a transportation planning perspective and would not warrant preparation of a Traffic Impact Assessment under City guidelines.

Project-related traffic would not result in any foreseeable effect on City or regional transportation policies or transportation management plans. Project effects on traffic plans, ordinances, and policies would be less than significant.

Level of Significance: Less than significant.

Mitigation Measures: None required

Impact TRANS-2: Conflicts with Non-Motor Vehicle Transportation Plans

The project would not result in any known direct increase in demand for public transit service. However, it can be expected that SJRTD bus routes will be able to accommodate the additional passengers the project would generate. This would be consistent with SJRTD goals that encourage further use of public transit. Project effects on public transit are considered less than significant.

The project would not result in any known direct increase in demand for bicycle and pedestrian facilities. The project is thoroughly served by existing streets and sidewalks, which will not be adversely affected by project construction. Project impacts on bicycle and pedestrian facilities would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact TRANS-3: Consistency with CEQA Guidelines Section 15064.3(b)

As discussed above, VMT is now the preferred method for evaluating transportation impacts, rather than LOS. The City is considering adoption of VMT impact standards,

scheduled for hearing in October 2022. VMT impacts associated with low-income or affordable housing are generally acknowledged to be so low as to be negligible and are typically "screened out" of the need for impact analysis. The proposed is unlikely to result in any substantial VMT effect, much less an adverse effect. The proposed project is clearly in the low-income or affordable housing, and as stated by GCRM, only a fraction of residents will have motor vehicles available for their use. The future population of the project will be drawn from the existing homeless population of Stockton and would not represent new motor vehicle travel in the downtown area.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact TRANS-4: Safety Hazards

The proposed project would not involve addition of new access or parking facilities or involve any adverse effect existing street or sidewalk improvements in the immediate project vicinity. Access to the proposed facility would be from existing pavement areas within the GCRM campus. Construction of the proposed dormitory will include the replacement of existing damaged sidewalks, curb and gutter along the project's South San Joaquin Street frontage.

The project would not result in any known potential safety concerns.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact TRANS-5: Emergency Access

As described in Chapter 3.0, Project Description, the project would be designed and constructed in accordance with the adopted Building Code and would include ADA accessibility on all floors. The project would therefore be adequately accessible for emergency services. The proposal building would be accessible to emergency services from South San Joaquin Street as well as from the existing GCRM campus. Project impacts related to emergency access would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

16.0 UTILITIES AND ENERGY

ENVIRONMENTAL SETTING

Wastewater/Sewer Systems

Sanitary sewer services to the project site and area are provided by the City of Stockton. The City of Stockton's sanitary sewer system includes approximately 914 miles of gravity sewers and force mains (pressure pipelines), ranging from less than 6 inches to 72 inches in diameter, and 27 sewer pump stations. Wastewater in the system generally flows westerly to the Stockton Regional Wastewater Control Facility on Navy Drive, where it is treated and discharged to the San Joaquin River.

The Regional Wastewater Control Facility consists of a main treatment plant with a capacity of 48 million gallons per day (mgd), and a tertiary treatment plant with 55 mgd capacity. The tertiary treatment plant includes approximately 630 acres of oxidation ponds, an engineered wetland, disinfection facilities, and a river outfall discharge system. Average dry-weather flows to the Regional Wastewater Control Facility were about 27 mgd in 2017 (City of Stockton 2018b).

The proposed project would connect to the City system at one of the existing City lines serving the project area, at either the six-inch line that flows north along South San Joaquin Street, or at one of two lines flowing west along Church Street.

Water Systems

The California Water Service Company, Stockton District, (Cal Water) serves the central part of the City of Stockton with purchased water and groundwater. Cal Water purchases water from the Stockton East Water District (SEWD), which obtains surface water supplies from the New Hogan Reservoir on the Calaveras River and the New Melones Reservoir on the Stanislaus River. Raw purchased water is treated at SEWD's treatment immediately east of the city. Cal Water produces groundwater from the East San Joaquin Subbasin of the San Joaquin Valley Groundwater Basin. Cal Water provides potable water to the range of land uses, including the project site, in the downtown area via pipelines located in the public streets.

Storm Drainage

Storm water in the City is collected by the City storm drain system and discharged to the San Joaquin River and other terminal drainages in the City. The City's storm drainage system includes 620 miles of 4-inch to 96-inch storm drains. Multiple pump stations and lift stations are used to pump drainage into receiving waters. Major receiving waters

include the San Joaquin River and Walker/French Camp Slough, among other channels. Chapter 12.0, Hydrology, discusses regulations applicable to the collection of storm water drainage. A 15-inch City storm drain is located in South San Joaquin Street at the project frontage.

Solid Waste

The City's exclusive franchise haulers, Republic Services and Waste Management, Inc., provide solid waste collection in Stockton, including source-separated curbside recycling, to both residential and commercial uses. Currently, residential solid waste generation comprises approximately 22% of the total annual solid waste generation; commercial solid waste generation comprises approximately 78%.

Solid waste is disposed at existing private and County-owned landfill facilities. According to the General Plan 2035 Background Report, the City's solid waste is transported and disposed of primarily at three active sanitary landfills: the Forward Landfill on South Austin Road with available capacity to 2020, the North County Landfill on East Harney Lane with available capacity to 2048, and the Foothill Sanitary Landfill on North Waverly Road with available capacity to 2082 (CalRecycle 2021).

AB 939, state legislation enacted in 1989, requires local jurisdictions to divert at least 50% of their solid waste from landfills by 2000. The City's existing 50% recycling rate places the City in compliance with AB 939. More recent legislation, AB 341, increases the recycling requirement to 75% of solid waste by 2020.

Stockton Municipal Code Sections 8.28.020 through 8.28.070 requires that all building permit applicants identify the debris the project will generate and recycle to meet the waste diversion requirement of at least 50 percent of materials generated as discards by the project.

Electrical and Communications Systems

Electrical usage within the City is served from a transmission network owned by PG&E. PG&E electrical facilities in the project area include overhead and underground 12-kilovolt distribution lines within existing streets and public utility easements. Centralized natural gas service is available from PG&E, the only provider of such service, from existing lines located in streets adjacent to the project.

AT&T provides telephone services to the Stockton area. Services are available to the project site from existing lines located on joint pole systems with PG&E electrical facilities. Comcast provides cable television services to the City of Stockton and vicinity; cable facilities are also generally located on the electrical pole system. These state-regulated franchise utilities are obligated to extend services to new development site as necessary.

Energy

CEQA requires that an EIR includes a discussion of the potential energy impacts of a proposed project, with emphasis on avoiding or reducing inefficient, wasteful and unnecessary consumption of energy. Appendix F of the CEQA Guidelines provides guidance for a discussion of energy impacts. Subjects may include identifying wasteful, inefficient and unnecessary consumption of energy during project construction, operation, maintenance and/or removal that cannot be feasibly mitigated, and the pre-emption of future energy development or future energy conservation. The most recent revisions to the CEQA Guidelines contain a new section in the Environmental Checklist in Appendix G that addresses energy.

Energy Usage

According to the latest information from the U.S. Energy Information Administration, California consumed 7,830 trillion British thermal units (BTUs) of energy in 2016. Only Texas consumed more energy. However, consumption per capita in California was 197 million BTUs, which was 49th among all states and the District of Columbia. Transportation accounted for approximately 39.8% of the energy consumed in California, followed by industrial with 23.7%, commercial with 18.9%, and residential with 17.7%. Natural gas accounted for approximately 2,250 trillion BTUs of the energy consumed in California, while motor gasoline accounted for approximately 1,700 trillion BTUs. California ranked third in the U.S. in petroleum production, third in conventional hydroelectric generation, second in net electricity generation from all other renewable energy resources combined, and first as a producer of electricity from solar, geothermal, and biomass resources (EIA 2017).

Electricity is a major energy source for residences and businesses in California. In 2016, electricity consumption in California totaled approximately 285,701 gigawatt-hours (GWh) (CEC 2018a). In San Joaquin County, electricity consumption in 2016 totaled approximately 5,457 million kilowatt-hours (kWh) [5,457 gigawatt-hours], of which approximately 3,698 million kWh were consumed by non-residential uses and the remainder by residential uses (CEC 2018b). As indicated above, natural gas is another major energy source. In 2016, natural gas consumption in California totaled approximately 12,750 million therms (CEC 2018a). In San Joaquin County, natural gas consumption in 2016 totaled approximately 195 million therms, of which approximately 115 million therms were consumed by non-residential uses and the remainder by residential uses (CEC 2018c).

Motor vehicle use accounts for substantial energy usage. The SJCOG estimated countywide vehicle miles traveled (VMT) daily was 17,868,785 miles in 2015, which led to the consumption of approximately 511 million gallons of gasoline and diesel fuel in 2015 (SJCOG 2018). Travel mileage in San Joaquin County is influenced by the County's relative jobs/housing imbalance and the resulting commute patterns, which involve relatively long commute trips. Approximately 30% of the employed workforce living within San Joaquin County commute to out-of-county job sites (SJCOG 2018).

Energy Systems and Facilities

Electrical usage within most of the County, including Stockton, is served from a transmission and distribution network owned by PG&E. Principal elements of the PG&E network are several transmission lines ranging in voltage from 115 kilovolts (kV) to 500 kV, the highest voltage lines that are in the southwestern corner of the County. PG&E electrical facilities in the project vicinity include overhead and underground 12-kV electrical distribution lines within existing streets and utility easements. Centralized natural gas service is available in Stockton from PG&E, the only provider of such service. As with the communications systems, these state-regulated energy franchise utilities are obligated to extend services to new development sites as necessary.

REGULATORY FRAMEWORK

City of Stockton Public Facility Fees

The City has established Public Facility Fees to be imposed on residential and non-residential development to defray the costs of new or expanded public facilities that may be necessary to serve the new development. Among the facilities that would be supported by these fees are water and wastewater facilities, which are also supported from other revenue sources. These fees are revised annually by the City Council based on inflation, indices, and fee studies. The Public Facility Fees are imposed by ordinance and collected when building permits are issued.

Public Utilities

Electrical, gas, communications and waste disposal services typically operate in cities subject to a franchise agreement with the city and requirements of the California Public Utilities Code. The franchisee is obligated to provide service throughout the city and maintain its facilities in good working order and entitled to collect fees from customers.

Solid Waste Regulations

The California Integrated Waste Management Act (AB 939), State legislation enacted in 1989 and subsequently amended, requires local jurisdictions to divert at least 50% of their solid waste from landfills by 2000. The City's 50% solid waste recycling rate places it in compliance with AB 939. More recent legislation, AB 341, increased the recycling requirement to 75% of solid waste by 2020.

Stockton Municipal Code Sections 8.28.020 through 8.28.070 is the City's Construction and Demolition Debris Waste Reduction Ordinance. The ordinance requires all permit applicants identify the debris the project will generate and recycle accordingly. Permit applicants for covered project are required to meet the waste diversion requirement of at least 50 percent of materials generated as discards by the project, regardless of whether the permit applicant performs the work or hires contractors, subcontractors or others to perform the work.

California Energy Efficiency Regulations

California has implemented numerous energy efficiency and conservation programs that have resulted in substantial energy savings. The State has adopted comprehensive energy efficiency standards as part of its Building Standards Code, California Codes of Regulations, Title 24. Part 6 of Title 24, also known as the California Energy Code, contains energy conservation standards applicable to all residential and non-residential buildings throughout California, including schools and community colleges. These standards are occasionally updated. The City of Stockton has adopted the 2013 version of the California Energy Code as part of its building codes.

In 2002, California adopted a Renewables Portfolio Standard, and subsequently modified it in 2006 and 2011. Under the 2011 modifications, all electricity retailers in the state must generate 20% of electricity they sell from renewable energy sources (i.e., solar, wind, geothermal, hydroelectric from small generators, etc.) by the end of 2013, 25% by the end of 2016, and 33% by the end of 2020. As of the end of 2017, California derived 30% of its electricity from renewable sources, which is within 3% of the 2020 target and within 20% of the 2030 target (CEC 2018a).

In 2015, SB 350 was signed into law, which increased the electricity generation requirement from renewable sources to 50% by 2030. Most recently, in 2018, SB 100 was enacted. SB 100 accelerated the schedule for 50% electricity generation from renewable sources to 2026 and set a goal of 60% electrical generation from renewable sources by 2030. It also set the goal that, by the end of 2045, eligible renewable energy resources and zero-carbon resources will supply 100% of retail sales of electricity to California end-use customers and 100% of electricity procured to serve all State agencies.

ENVIRONMENTAL IMPACTS AND MITIGATION MEASURES

Significance Thresholds

According to Appendix G of the CEQA Guidelines, a project may have a significant impact on the environment if it would:

- Require or result in the relocation or construction of new or expanded water, wastewater treatment, storm water drainage, electric power, natural gas, or telecommunications facilities, the construction or relocation of which could cause significant environmental effects,
- Have sufficient water supplies available to serve the project and reasonably foreseeable future development during normal, dry, and multiple dry years,
- Result in a determination by the wastewater treatment provider which serves or may serve the project that it has inadequate capacity to serve the project's projected demand in addition to the provider's existing commitments,

- Generate solid waste in excess of State or local standards, or in excess of the capacity of local infrastructure, or otherwise impair the attainment of solid waste reduction goals, or

- Not comply with federal, state, and local statutes and regulations related to solid waste.

Recently, the Environmental Checklist in CEQA Guidelines Appendix G was updated to include questions regarding energy consumption and conservation. The updated checklist indicates that a project may have a significant impact on the environment if it would:

- Result in potentially significant impacts due to wasteful, inefficient, or unnecessary consumption of energy resources during project construction or operation, or

- Conflict with or obstruct a state or local plan for renewable energy or energy efficiency.

Impact UTIL-1: Wastewater Services and Facilities

The project would connect to existing sanitary sewer lines within City streets adjacent to the GCRM. The City has indicated that there is adequate capacity in the system to accommodate the proposed project. The RWCF currently has substantial additional treatment capacity - approximately 22 mgd - to serve additional development. Project impacts on the City's wastewater system would be less than significant.

The project would not require or result in the construction of new sewers or wastewater treatment facilities, or expansion of existing facilities, the construction of which would potentially cause significant environmental effects.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact UTIL-2: Water Services and Facilities

The proposed project would obtain potable water service from existing Cal Water lines in streets adjoining the GCRM and project site. Cal Water has indicated that adequate capacity is available in the existing water system to accommodate the proposed project. The General Plan 2040 EIR states that adequate water supply is available to meet project urban water needs through the planning period. Project impacts on the Cal Water system would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact UTIL-3: Stormwater Services and Facilities

The project site is composed entirely of impervious surfaces that drain to existing City of Stockton storm drainage facilities. The project would replace existing impervious rooftops and paving with new impervious areas that tie into an existing 15-inch City storm drain in South San Joaquin Street. The project would not result in the construction of new impermeable surfaces that would increase runoff from the site.

Level of Significance: No impact

Mitigation Measures: None required

Impact UTIL-4: Solid Waste

As indicated in the Environmental Setting above, solid waste generated by the project would be collected by existing City franchise haulers and disposed to existing landfills in the County. These existing landfills would have adequate capacity to accommodate the amount of solid waste that would be generated by the project. The project would have less than significant impacts related to solid waste.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact UTIL-5: Energy and Telecommunications Facilities

As noted above, existing electrical, natural gas, telephone, and cable television lines are available near the project site, and services would be extended to the project in accordance with these existing franchises. The project would have access to these services without requiring significant expansion. Project impacts on energy and communications systems would be less than significant. Chapter 23.0, Other CEQA Issues, evaluates project impacts related to energy consumption and conservation.

Level of Significance: Less than significant

Mitigation Measures: None required

Impact UTIL-6: Project Energy Consumption

Project construction would consume energy in the course of demolishing existing buildings and constructing the new dormitory structure and site improvements. The project site is a flat urban lot, which would not involve any extraordinary excavation or grading requirements or unusual construction activities. Project construction is not expected to involve substantially inefficient, wasteful, or unnecessary consumption of energy.

Project operations would involve a substantial increase in energy usage compared to the existing structures, but the proposed new structure would be designed in accordance with

current energy conservation requirements incorporated into the Uniform Building Code as adopted by the City. There is no indication that the project would consume energy in in greater quantities than other comparable residential facilities or that the project would involve substantially inefficient, wasteful, or unnecessary consumption of energy. Overall, impacts of the project on energy consumption would be less than significant.

Level of Significance: Less than significant

Mitigation Measures: None required

17.0 CUMULATIVE IMPACTS

17.1 INTRODUCTION TO CUMULATIVE IMPACTS

A cumulative impact, as defined by CEQA Guidelines Section 15355, is an environmental effect that may result from the combination of two or more environmental effects associated with the proposed project, or from the combination of one or more project environmental effects with related environmental effects caused by other closely related projects. Cumulative impacts may also result when a project's environmental effects compound or increase other environmental impacts. Cumulative impacts can result from individually minor but collectively significant projects taking place over time.

CEQA Guidelines Section 15130 states that an EIR must discuss the cumulative environmental impacts of a project "when the project's incremental effect is cumulatively considerable." As described in CEQA Guidelines Section 15065(a)(3), "cumulatively considerable" effects occur when the incremental effects of an individual project are significant when viewed in connection with the effects of other closely related projects, including past projects, current projects, and probable future projects.

If the project does not involve a cumulatively considerable contribution to a significant cumulative effect, the project's effect does not need to be considered significant, and discussion in the EIR can be limited to the basis for that conclusion. Projects that do involve cumulatively considerable contributions may involve significant cumulative impacts. A project's contribution is less than cumulatively considerable if the project is required to implement or fund its fair share of a mitigation measure or measures designed to alleviate the cumulative impact. As provided in *San Joaquin Raptor/Wildlife Rescue Center v. County of Stanislaus* (1996) a project's cumulatively considerable contribution to a significant cumulative impact can be reduced to a less-than-considerable level with mitigation measures.

The analysis of cumulative impacts is to be based on either 1) a list of past, present, and probable future projects producing related or cumulative impacts, or 2) on a summary of projections contained in an adopted general plan or related planning document, or in a prior certified environmental document which described or evaluated regional or area-wide conditions contributing to the cumulative impact. Where significant cumulative impacts are identified, the EIR must examine reasonable, feasible options for mitigating or avoiding the project's contribution to a less than considerable level. In some cases, the only feasible mitigation may involve the adoption of ordinances or regulations. For this EIR, the summary approach is used.

The following cumulative impact analysis determines for each environmental discipline:

- The geographic context for the analysis,
- Whether there exists the potential for a significant cumulative impact in that environmental discipline,
- Whether the project would make a cumulatively considerable contribution to a significant cumulative impact, or make significant an impact that was otherwise less than significant, and
- Whether and how a significant cumulative impact or a considerable contribution to that impact can feasibly be avoided or reduced to a less than significant or less than considerable level.

Where relevant, the analysis and mitigation measures from the Stockton General Plan EIR are summarized in the following chapter sections. As set forth below, the proposed project would not involve any known change in, or any considerable new contribution to, the significant cumulative impacts identified in the Stockton General Plan EIR.

17.2 CUMULATIVE IMPACT SETTING

The project site is within the jurisdiction of the City of Stockton. As described in Chapter 12.0, Land Use, the project site is subject to the Stockton General Plan 2040. The Stockton General Plan EIR considered the cumulative environmental effects of the development of lands designated in the General Plan for development, including the project site (City of Stockton 2018).

The proposed project would contribute to the long-range cumulative environmental impacts identified in the Stockton General Plan EIR, including potential cumulative impacts of planned urban development on the resources and environmental conditions addressed at a project level in this EIR. Where appropriate, the Stockton General Plan 2040 and associated EIR will be cited in this chapter.

17.3 CUMULATIVE IMPACTS OF PROJECT

17.3.1 Aesthetics and Visual Resources

Cumulative impacts on aesthetics are assumed to be localized; that is, aesthetic changes at a site will not generally impact aesthetics at another site if the sites are not visually connected in some fashion. A visual connection between sites could be established by juxtaposition or by location along a travel corridor, among other possibilities. For the purposes of this EIR, the geographic context for cumulative analysis is defined as the "project vicinity," defined more precisely as the area within the APE identified in the Historic Resource Evaluation for the project (see Chapter 7.0, Cultural Resources).

The project would result in the removal of two residential buildings considered to have historical and architectural value. This would alter the visual landscape of the project vicinity. However, the buildings are not in a designated historic district and are in relatively poor condition. The Stockton General Plan EIR concluded that aesthetic impacts would be less than significant with implementation of applicable General Plan policies and actions. The design of the proposed project will be required to meet adopted community standards through the Site Plan and Design Review process, which would improve the visual appearance of the area. Scenic vistas identified in the Stockton General Plan would not be affected. The project would not result in a considerable contribution to any cumulatively significant aesthetic effect.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.2 Air Quality

Cumulative impacts on air resources may be assessed at both a regional and local level. The project would involve contributions to potential air quality impacts at the regional level, defined as the San Joaquin Valley Air Basin, and at the local level, defined as the project vicinity. Regional air quality conditions are described in detail in Chapter 5.0, Air Quality. Past and present agricultural, urban, and other development within the Air Basin has resulted in significant air quality impacts, mainly the designation of the Air Basin as nonattainment for federal and/or state ambient air quality standards for ozone and particulate matter.

The potential cumulative air quality impacts of the Stockton General Plan were addressed in the General Plan EIR. General Plan policies and actions that address air quality issues were noted, and mitigation measures were identified. However, even with implementation of mitigation measures, impacts related to consistency with air quality plans, short-term and long-term pollutant emissions, and violation of air quality standards were found to be significant and unavoidable.

Chapter 5.0 quantifies the criteria air pollutant contributions of the proposed project to existing and predicted future levels of these pollutants. While SJVAPCD air quality management plans and programs are oriented to the reduction of existing air pollution and attainment of ambient air quality standards, air pollution generated by the project would at least contribute to existing, significant exceedances of ozone and particulate matter standards.

As described in Chapter 5.0, estimates of air pollutant emissions indicate that the project would not approach, much less exceed, SJVAPCD construction or operational significance thresholds. The GAMAQI notes that emissions from a project may be cumulatively considerable even if they are below SJVAPCD significance thresholds. However, as discussed in Chapter 5.0, the significance thresholds are used to evaluate impacts of project-specific emissions on regional air quality and the ability of the Air Basin to reach attainment of air quality standards. The proposed project's contributions

would be small and would not result in a considerable contribution to a significant cumulative air quality impact in the Air Basin.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.3 Biological Resources

Cumulative impacts on biological resources can be addressed in terms of habitat areas for individual sensitive species, watersheds, or bioregions. The proposed project site is in an area that has been entirely urbanized and is not biologically diverse or sensitive. For the purposes of this EIR, the geographic context for cumulative biological resource analysis is defined as the project vicinity.

The project vicinity has been subject to significant biological resource impacts because of past urban development. As a result, and as characterized in Chapter 6.0, Biological Resources, the project vicinity does not support populations of common or sensitive wildlife species. Biological resources impacts discussed in the Stockton General Plan EIR focus mainly on the consequences of conversion of open space, which is not found on the project site or in the immediate vicinity. The project site is developed for urban uses and has no habitat for either resident or migratory species. No streams or other Waters of the U.S. or State are on or near the project site. Because of this, the proposed project would not result in a considerable contribution to a significant cumulative biological resource impact.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.4 Cultural Resources and Tribal Cultural Resources

The geography of cultural resource impacts can be defined by region, by political subdivision or by the geography of the cultural resources present in an area, where adequate inventory data are available to define it. Resource information is ordinarily available only for small percentages of a given area – those areas that have been intensively surveyed. This is true for the project site, which has geomorphology and land use history in common with the City of Stockton as a whole. For the purposes of this EIR, the geographic context for cumulative analysis of cultural resources and tribal cultural resources is defined as the City of Stockton.

As described in Chapter 7.0, Cultural Resources and Tribal Cultural Resources, no known tribal cultural resources are located on the project site, and no tribes have yet expressed interest in response to the City's AB 52 notification.

The project site contains two buildings that have been determined to be cultural resources of significance, due to their historic age and their architectural value. These buildings are currently not listed on federal or State historical registers, and they have not been

designated a historical resource by the City of Stockton. However, both buildings have been determined eligible for inclusion on the federal and State registers; as discussed in Chapter 7.0 of this EIR; as noted in Chapter 7.0, the proposed demolition of these buildings will have a significant and unavoidable impact at the project level.

The Stockton General Plan EIR does not indicate that general plan implementation would result in a cumulatively significant effect on historical resources (Impact CULT-1). While the project would involve a significant cultural resources impact at the project level, since no significant historic resources impact was identified at the cumulative level, it would not result in a considerable contribution to a significant cumulative historic resource impact, sine none is identified in the GPEIR.

The Stockton General Plan EIR discussed the potential impacts on historical architectural resources. It concluded that impacts would be less than significant with implementation of General Plan policies and actions. In particular, Actions LU-3.1.B and LU-3.1.C direct the City to require historical resources surveys when development is proposed in areas containing buildings 50 years old or older, and to require historic structures and surrounding features to be maintained, restored, or repaired wherever possible. However, as discussed in Chapter 7.0, there are no feasible mitigation measures that would avoid or minimize project impacts on the two buildings. Therefore, the proposed project would involve a considerable contribution to cumulative cultural resource impacts in the Stockton area.

Contribution to Significant Cumulative Impacts: Considerable

Mitigation Measures: None feasible

17.3.5 Geology and Soils

Potential cumulative impacts associated with geology and soils are assumed to be localized. Potential geology and soil impacts include potential project exposure to geologic hazards, seismic shaking, soil-related hazards, and soil erosion. These issues were determined to have impacts that are limited to the project or its occupants and are not inherently accumulative. The Stockton General Plan EIR did not identify any significant impacts associated with geology and soils with the implementation of applicable General Plan policies and actions.

The project could have potential impacts on paleontological resources, but these can be mitigated to a level that would be less than significant. Other potential impacts would be addressed by application of existing State and local regulations. The project would not make a considerable contribution to any cumulative geology or soils impacts.

The geographic context for cumulative mineral resource analysis is defined as the City of Stockton. As discussed in Chapter 8.0, Geology and Soils, there are no mineral resources on the project site. The Stockton General Plan EIR noted the potential presence of oil or gas wells in the northwest section of Stockton, which is several miles from the project site. The project would not contribute to cumulative mineral resource impacts in the County.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.6 Greenhouse Gas Emissions

GHG emissions are related to global climate change. Global climate change is a distinct CEQA issue in that, while a project may generate GHG emissions, the impacts of such emissions are global. As such, the impacts of a project's GHG emissions are considered cumulative in nature. The analysis in Chapter 9.0, Greenhouse Gas Emissions, addresses the potential cumulative impacts of the project related to GHG emissions; The project would involve no hazardous emissions or wastes; any cumulative GHG impacts are not discussed further in this chapter.

17.3.7 Hazards and Hazardous Materials

Potential cumulative impacts associated with hazards and/or hazardous materials are assumed to be localized. Any project exposure to hazards would occur on or in the immediate vicinity of the site, and any potential on- or off-site impact of hazardous materials use associated with the project would also be limited to the immediate vicinity. For the purposes of this EIR, the geographic context for cumulative analysis of hazards and hazardous materials is defined as the project vicinity.

The Stockton General Plan EIR did not identify any significant impacts related to hazards or hazardous materials with the implementation of applicable General Plan policies and actions. A Phase I ESA was conducted for the project site, as described in Chapter 10.0, Hazards and Hazardous Materials, and a recognized environmental condition was identified for lead-based paint and termiticides applied to the two residential buildings proposed for demolition. However, this condition is confined to just these buildings and soil around the building perimeters, and this EIR identified mitigation measures that address this recognized environmental condition. No other contamination was identified. Hazardous material use by the project would be limited. No significant wildland fire hazards were identified in the project vicinity. The project would not involve a contribution to hazards that would be cumulatively considerable.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.8 Hydrology and Water Quality

Cumulative hydrologic impacts are logically analyzed on a watershed basis, or at an aquifer level in the case of groundwater. The project site is within several miles of the San Joaquin River, but it is isolated from the river by the relatively flat topography and by urban and freeway development. The project site is located within the Eastern San Joaquin Groundwater Subbasin, but the project would involve no demands on groundwater that would have potential effects that could reasonably extend outside the

project vicinity. For the purposes of this EIR, the geographic context for cumulative hydrologic analysis is defined as the project vicinity.

The project site contains no surface water features. The project would obtain potable water from the Cal Water system, which derives a portion of its supply from groundwater. The Stockton General Plan EIR did not identify significant impacts of general plan buildout on groundwater supply. Also, as described in Chapter 11.0, Hydrology and Water Quality, the City will participate in the implementation of the Groundwater Sustainability Plan for the Eastern San Joaquin Groundwater Subbasin, the objective of which is to ensure sustainable use of this groundwater resource.

The project's potential impacts on surface water quality would be mitigated by compliance with the provisions of the City's Stormwater Management Plan and MS4 General Permit. By complying with these plans and permits, the projects would not involve surface water resource effects or contribute significantly to groundwater demands or water quality effects.

The Stockton General Plan EIR identified a potentially significant impact associated with polluted runoff, but also identified a mitigation measure for this impact – the updated storm drainage master plan for Stockton. The project would not involve substantial contributions to polluted runoff, as the project will not involve any substantial use of motor vehicles. As noted, the project would comply with the provisions of the City's SWMP and MS4 General Permit. The project would not involve a considerable contribution to any significant cumulative hydrology or water quality effects.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.9 Land Use, Agriculture/Forestry, and Population

The potential for cumulative land use impacts is related to the scale of the project and the presence or absence of a defined community or land use entity; the geographic context for cumulative land use analysis can range from a project site and adjacent parcels to an entire community or region, depending on project size. For the purposes of this EIR, the geographic context for cumulative land use analysis is defined as the project vicinity.

The project vicinity is a mix of urban residential and commercial land uses. As noted in Chapter 3.0, Project Description, the proposed project would be consistent with the existing general plan designation and zoning for the project site. The proposed project would not involve a considerable contribution to a significant cumulative land use effect.

The project proposes construction of a shelter for homeless persons. The project would not provide permanent housing, but it would beneficially affect a portion of the homeless population in the City. As noted in Chapter 12.0, Land Use and Population, the project would not lead directly or indirectly to population growth. The proposed project would not involve an adverse contribution to a cumulative population and housing impact as described in the Stockton General Plan.

The project is located on developed land in an existing urban area with no nearby agriculture. The project would not convert any agricultural land or contribute to any other impact on agricultural land. As there is no forest land in the Stockton area, the project likewise would not have a cumulatively considerable impact on forest land.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.10 Noise

Cumulative noise impacts are assumed to be localized; the impacts of noise are reduced with distance, and unless there is a very significant existing or proposed noise source, the potential for cumulative impacts will ordinarily be limited to a few hundred yards. The Crosstown Freeway, located to the north of the project site, is the major source of existing noise in the project area. There are no other major noise sources in the project vicinity. For the purposes of this EIR, the geographic context for cumulative noise analysis is defined as the project vicinity.

The Stockton General Plan EIR identified potential noise sources associated with General Plan development. It concluded that impacts associated with these noise sources would be reduced to a level that would be less than significant with implementation of the polices and standards of the Noise Element, except for traffic noise along identified roadway segments. The project site is not adjacent to any of these segments. The project would not generate any significant operational noise.

The project would have construction noise impacts that are potentially significant, but with implementation of mitigation measures described in Chapter 13.0, Noise, project construction would be consistent with the policies and standards of the Noise Element. The project would not involve a contribution to noise impacts that would be cumulatively considerable.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.11 Public Services and Recreation

Potential cumulative impacts related to public services are appropriately addressed at a community level. The proposed project is in the City, so the City and special districts with jurisdiction (e.g., SUSD) would provide most of the services.

The Stockton General Plan EIR did not identify any significant impact associated with public services with implementation of the applicable General Plan policies and actions, including payment of SUSD impact fees. As described in Chapter 14.0, the project would place demands on such services but would be required to pay fees for the future construction of police facilities, schools, and other municipal buildings. With the fee

payments, the project would not make a considerable contribution to cumulative impacts on public services.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.12 Transportation

Cumulative transportation impacts, primarily vehicular traffic, are addressed within the area potentially impacted by a proposed project, typically within a defined radius from the project site. This is also the case with respect to the potential traffic impacts of the project, which are addressed in detail in Chapter 15.0, Transportation.

The project's potential for cumulatively considerable contributions to traffic impacts is considered minimal; shelter residents will not typically own vehicles. As a result, the only vehicle trips generated by the project would be associated with incremental increases in employee and delivery vehicles. Project trips would not noticeably affect traffic flow on nearby streets. As discussed in Chapter 15.0, Transportation, the project is not expected to have a substantial impact on VMT. The project would not make a considerable contribution to cumulative impacts on public services.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

17.3.13 Utilities and Energy

Cumulative utility impacts are appropriately considered at the level of the service area of the potentially affected utilities. For sewer, storm drainage, and solid waste services, this would be the City of Stockton, as the City either provides these services directly or contracts these services out to franchisees. Water services would be provided by Cal Water, a private company. For energy and communications services, the service area is regional or statewide, but potential project effects would not extend outside the immediate project vicinity. For the purposes of this EIR, the geographic context for cumulative analysis of these systems is defined as the project vicinity.

The project would be served by utilities provided by the City of Stockton and other agencies. As analyzed in Chapter 16.0, Utilities and Energy, adequate water, wastewater, and storm drainage capacity would be available to serve the project with required onsite improvements. Energy consumption by the project was determined not to be wasteful, inefficient, or necessary. Additionally, both projects would use electricity that would rely less on its generation by fossil fuels, in accordance with the RPS targets, and structures at both sites would be required to comply with the adopted California Energy Code and CALGreen, which include energy efficiency provisions. The project would not result in a considerable contribution to cumulative impacts on utilities or energy.

Contribution to Significant Cumulative Impacts: Less than considerable

Mitigation Measures: None required

18.0 ALTERNATIVES

18.1 INTRODUCTION

CEQA Guidelines Section 15126.6(a) requires an EIR to "describe a range of reasonable alternatives to the project, or to the location of the project, which would feasibly attain most of the basic objectives of the project but would avoid or substantially lessen any of the significant effects of the project and evaluate the comparative merits of the alternatives." It further states the EIR shall "consider a reasonable range of potentially feasible alternatives that will foster informed decision making and public participation." The alternatives analysis must identify the potential alternatives and include adequate information about each one to allow meaningful evaluation, analysis, and comparison with the proposed project. The EIR must consider a range of alternatives that can feasibly attain most of the basic project objectives and would avoid or substantially lessen one or more of the significant effects of the proposed project, even if an alternative would impede to some degree the attainment of the project objectives or would be more costly.

There are no set rules governing the nature and scope of the alternatives to be discussed, other than the "rule of reason." If an alternative is not feasible or does not provide an opportunity to avoid or substantially reduce environmental effects, the alternative need not be analyzed in detail; if this is the case, the reasons for limiting the analysis should be identified. The environmentally superior alternative must be identified among the alternatives considered.

The following sections describe the process used to select alternatives for evaluation in this chapter. Selected alternatives to the project are analyzed in detail, while alternatives that were considered but not subjected to detailed analysis are noted. The alternatives analysis conforms to the guidelines of CEQA and the CEQA Guidelines and represents the best professional opinion of the EIR preparer, City staff, and their technical reviewers. However, the authority for the approval of the proposed project, the selection of or rejection of alternatives, and the feasibility or infeasibility of alternatives ultimately rests with the County decision-makers.

18.2 SELECTION OF ALTERNATIVES

Alternatives to the project were selected for evaluation in this EIR based on the criteria set forth in CEQA Guidelines Section 15126.6. These criteria include 1) ability of the alternative to meet most of the basic objectives of the project, 2) feasibility of the alternative, and 3) ability of the alternative to avoid or substantially reduce one or more of the significant environmental effects of the project. These criteria are discussed in more detail below.

Ability of the Alternative to Meet Project Objectives

Potential alternatives to the project were evaluated with respect to the objectives of the project, as identified and discussed in Section 3.2 of this EIR. These objectives are to develop the site to provide emergency shelter for 178 homeless people. The objectives set forth for the project may have a bearing on the selection and evaluation of alternatives.

Feasibility of the Alternative

Alternatives to the project were evaluated with respect to the "rule of reason" and general feasibility criteria suggested by the CEQA Guidelines. Such criteria include the suitability of the site or alternative site, the economic viability of the alternative, the availability of infrastructure, the consistency of the alternative with general plan designations, zoning or other plans or regulatory limitations, the effect of applicable jurisdictional boundaries, and whether the proponent can reasonably acquire, control or otherwise have access to an alternative site, including consideration of whether or not the site is already owned by the applicant. For this project, the applicant owns the project site. The application of these criteria to potential alternatives to the proposed project is described in Sections 18.2 and 18.3.

Avoidance or Substantial Reduction of Significant Effects

The evaluation of alternatives must also consider the potential of the alternative to avoid or substantially lessen any of the significant effects of the project, as identified in Chapters 4.0 through 17.0 of this EIR. The potential environmental effects of the project are summarized in Chapter 2.0, Summary. All the potentially significant impacts of the project identified in this EIR can be reduced to a level that would be less than significant with the implementation of mitigation measures, except for the impacts on historical resources. No feasible mitigation measures to avoid or minimize this impact could be identified.

The alternatives analysis accounts for the potentially significant environmental effects of the alternatives as compared to the proposed project. Some of the potential environmental effects of the project, and the alternatives, are common to virtually all development in Stockton and would not vary from alternative to alternative. Similarly, certain environmental effects are addressed by routine requirements that would apply uniformly to any alternative. Since the focus of the alternatives analysis is comparison to the proposed project, issues that do not vary between the alternatives are not extensively analyzed. The only environmental effect requiring analysis is the impact on historical resources. The proposed project would demolish two residential buildings determined to have historical value; this analysis focuses on alternatives to building demolition.

18.3 ALTERNATIVES NOT CONSIDERED IN DETAIL

The following alternative was not addressed in detail, as it did not meet the criteria for detailed analysis defined above. That is, the following alternatives 1) would not meet most of the basic objectives of the project, 2) were clearly infeasible, or 3) did not have the ability to avoid or substantially lessen the significant environmental effects of the project.

18.3.1 Alternative Sites

CEQA Guidelines Section 15126.6(f)(2) indicates that alternative locations for a proposed project should be considered if any of the significant effects of the project would be avoided or substantially lessened at an alternative location. Only locations that have the potential to avoid or substantially reduce any of the significant effects of the project need be considered for inclusion in the EIR. The availability of an alternative site that would support the proposed development at a viable location sought by the project was considered; mainly, a site similar in acreage and available for multifamily residential development within the City of Stockton. There are several parcels in Stockton of similar size that conceivably are available for multi-unit developments.

However, development of an alternative site would have similar impacts associated with project development, and most such impacts would be merely shifted from one area to another. Depending on location, development of an alternative site may have greater impact on issues such as traffic, air quality, biological resources, and noise. None of the alternative sites conceivably available would likely reduce the potentially significant environmental impacts identified with the project.

Additionally, the project applicant owns the proposed project site and has existing adjacent facilities that provide services to homeless people. Development of an alternative site would not be consistent with the project objective of serving homeless people, as residents would be moved away from a facility that offers services to the homeless. Also, an alternative site would need to be acquired or leased, and there would be obstacles related to financing and willingness of property owners to deal with the project applicant. In many conceivable alternative sites, neighboring residents and businesses would likely be opposed to having a homeless facility in their area.

In summary, there are no other sites in the Stockton area that would be reduce environmental impacts and would meet project objectives. Because of this, alternative sites were not analyzed further.

18.3.2 Alternative Site Design

Changes in the design of a project could avoid or substantially lessen one or more of the project's potentially significant effects. However, potential design changes to the proposed project would be very limited. The project would be on only 0.21 acres, so the project would not be able to expand. The proposed project is three stories in height; additional stories to reduce building footprint would increase building construction and

maintenance costs, as well as have an increased visual impact. None of the potential design changes would likely avoid demolition of the two buildings, which was determined to have a potentially adverse cultural resource impact. The project, no matter the design, would still be required to follow City codes and standards for building construction, which would avoid or minimize most potential environmental impacts. Design changes would not significantly change the environmental impacts of the proposed project; therefore, alternative site design was not analyzed further.

18.4.2 Reduced Development Alternative

Under this alternative, the number of stories of the proposed building would be reduced from three to two, and the number of beds the building would accommodate would be reduced from 178 to 128. For this analysis, the total number of beds provided by the proposed project was reduced by the number of beds that would have been made available on the third floor.

A few of the environmental impacts of the proposed project may be reduced under this alternative. With one less story, construction noise impacts would not be as extended in time, and visual impacts would be less. In addition, this alternative would meet the project objectives, albeit at a reduced level. However, impacts in general would be similar to the proposed project. More importantly, this alternative would still require the demolition of the two buildings with potential historical value, which is the most significant impact of the proposed project. As with the No Project Alternative, this alternative would reduce the availability of shelter for homeless persons.

In summary, the Reduced Development Alternative would not achieve the project objectives as fully as under the proposed project, and it would only slightly reduce some environmental impacts while creating others or leaving some significant impacts unchanged. Therefore, this alternative was not analyzed further.

18.4 ALTERNATIVES CONSIDERED IN DETAIL

The alternatives to the proposed project that have been considered in detail are addressed in the following sections. Only one alternative is considered feasible – the No Project Alternative.

18.4.1 No Project Alternative

CEQA Guidelines Section 15126.6(e) states that the alternatives analysis must include evaluation of a "no project" alternative. For a development project, the No Project Alternative typically compares the environmental impacts of the project site remaining in its existing state against the environmental impacts of the proposed project. Where failure to proceed with the project will not result in the preservation of existing environmental conditions, the analysis should identify the practical result of the project's non-approval.

Under the No Project Alternative, no development as proposed by the project would occur. The project site is currently zoned C-G, General Commercial. Therefore, if the proposed project is not approved, then the site would be available for another development consistent with the C-G zone. The C-G zone allows for a variety of retail, business/professional, and service uses, either by right or with approval of a permit. Also, the No Project Alternative would avoid the demolition of the two existing residential buildings, considered a significant and unavoidable impact of the proposed project.

However, the No Project Alternative would not meet the proposed project objective of providing a shelter to homeless persons. With no additional shelter, more homeless persons would be outdoors, which would have adverse health and safety impacts for them. This alternative would also be contrary to policies in the Housing Element of the City's General Plan that address the homeless population.

In addition, any proposed alternative commercial development would have environmental impacts that are similar to those under the proposed project, and many of them would be greater. For example, traffic would likely increase with a commercial development, with its attendant air quality and noise impacts. More importantly, alternative development would still likely include the demolition of the two residential buildings with potential historical value. Even if demolition of the buildings was avoided, reuse of the buildings may be financially infeasible, due to their age and likely application of historical preservation requirements. Consequently, the buildings may deteriorate, decreasing the quality of the visual landscape and posing a potential health and safety hazard

In summary, while the No Project Alternative would likely avoid some of the environmental impacts of the proposed project, it would involve other adverse impacts, some of which would greater than under the proposed project. It also would not meet the objectives of the proposed project.

18.5 ENVIRONMENTALLY SUPERIOR ALTERNATIVE

The No Project Alternative is the only feasible alternative to the proposed project; as such, it is considered the environmentally superior alternative. While the No Project Alternative would likely eliminate potential environmental effects associated with the proposed project, it would not meet the project objectives, while it could generate adverse environmental impacts of its own. It also may not avoid the demolition of two residential buildings of historic value, which was identified as a significant and unavoidable impact of the proposed project. It should be noted all that potential environmental impacts of the proposed project, except for the impact on historical resources, would be reduced to levels that are less than significant with the implementation of mitigation measures, while still realizing the project objectives.

19.0 OTHER CEQA ISSUES

19.1 SIGNIFICANT AND UNAVOIDABLE ENVIRONMENTAL IMPACTS

CEQA Guidelines Section 15126.2(b) states that an EIR shall discuss significant environmental effects that cannot be avoided if a proposed project is implemented. This includes significant impacts that can be mitigated but not reduce to a level of insignificance. Where there are impacts that cannot be alleviated without imposing an alternative design, the implications of these impacts, and the reasons why the project is being proposed notwithstanding their effects, should be described.

Table 2-1 identifies all the potentially significant environmental effects of the project and the mitigation measures to address the identified significant effects. All the proposed mitigation measures would be effective in reducing potentially significant environmental effects to levels that would be less than significant, except for historical resources. As discussed in Chapter 5.0, Cultural Resources, the project would involve the demolition of two residential buildings considered to have historical and architectural value. There are no feasible mitigation measures to avoid or minimize this impact. As discussed in Chapter 17.0, Cumulative Impacts, no significant and unavoidable cumulative impacts were identified with the project except for historical resources.

19.2 IRREVERSIBLE ENVIRONMENTAL COMMITMENTS

CEQA Guidelines Section 15126.2(c) states that an EIR shall discuss significant irreversible environmental changes which would be involved in a proposed project should it be implemented. CEQA Guidelines Section 15126.2(c) states, in part:

> "Uses of nonrenewable resources during the initial and continued phases of the project may be irreversible since a large commitment of such resources makes removal or nonuse thereafter unlikely. Primary impacts and, particularly, secondary impacts (such as highway improvement which provides access to a previously inaccessible area) generally commit future generations to similar uses. Also irreversible damage can result from environmental accidents associated with the project. Irretrievable commitments of resources should be evaluated to assure that such current consumption is justified."

The project would involve the irreversible commitment of construction materials to the construction of buildings, parking spaces, and supporting infrastructure. Construction materials would involve sand and gravel, concrete, asphalt, plastics, and metals, along with renewable resources such as wood. These materials would not be used in highly significant or unusual quantities when compared to similar projects and would be obtained from existing commercial sources. Some of these materials could be recycled if

some or all the project facilities were demolished in the future, such as concrete and metals. As noted in Chapter 16.0, Utilities and Energy, the City requires all construction, demolition and renovation projects within the City with total costs that are, or projected to be, equal to or greater than $20,000 to reuse or recycle at least 50% of all construction and demolition debris.

There are no other changes associated with the project, or resources impacted by the project, that are irreversible. No open space uses exist on the project site. The project site has already been committed to urban use, and the project would not change that commitment.

19.3 GROWTH-INDUCING IMPACTS

CEQA Guidelines Section 15126.2(d) requires an EIR to discuss the potential growth-inducing impacts of a project or program. "Growth-inducing impacts" are ways in which a proposed project could foster economic or population growth, or the construction of additional housing, either directly or indirectly, in the surrounding environment. CEQA Guidelines Section 15126.2(d) further notes that it must not be assumed that growth in any area is necessarily beneficial, detrimental, or of little significance to the environment.

Growth can be induced in a variety of ways. New development can create demands for other types of development. For example, new industrial development which provides jobs may attract new residents to an area, creating a demand for more housing. The same project in an area with a readily available supply of labor may have no growth-inducing effect at all. Development of new amenities, such as recreational facilities, can spur development of new housing for people wishing to take advantage of them. In a more general sense, new urban development in rural areas may induce growth by providing both a nucleus for a change in land use and economic incentives for conversion of nearby agricultural lands.

Growth may also be induced through the removal of obstacles to development. One potential obstacle is the lack of utilities or infrastructure to support development. The provision of new utilities or other infrastructure that can serve development, particularly in an area that is undeveloped, may induce growth. For example, construction of new or larger domestic water systems to unserved areas may facilitate development of these areas. Expansion of other utility systems, like electrical systems, can have similar effects. But in some cases, the extension of new infrastructure may not have a distinguishable growth-inducing effect, outside of its indirect contribution as an element of the proposed development.

The proposed project is within a developed urban area, containing no open space areas outside of parks and other public places. Existing infrastructure is available; no new or expanded utility lines would be installed other than connecting lines from the project to existing mains. The project is a shelter for homeless people, which is not expected to encourage new development in the area that would increase population growth. Given these conditions, the project would not have a growth-inducing impact.

19.4 ENVIRONMENTAL JUSTICE

The State of California has recently emphasized the incorporation of environmental justice in land use and environmental planning. State law defines "environmental justice" as "the fair treatment of all races, cultures, and incomes with respect to the development, adoption, implementation, and enforcement of environmental laws, regulations, and policies." Low-income residents, communities of color, tribal nations, and immigrant communities have historically experienced disproportionate environmental burdens and related health problems. This has led to development patterns that concentrate pollution emissions and environmental hazards in communities that have not had the political power to protect themselves. Although environmental justice is not an issue that is explicitly incorporated within CEQA, it is discussed in this EIR due to its potential connections to project environmental impacts.

Relevant State Laws and Local Plans

SB 535 – Disadvantaged Communities

In 2012, the Legislature passed SB 535, directing that 25 percent of the proceeds from the Greenhouse Gas Reduction Fund go to projects that provide a benefit to "disadvantaged communities." To assist in identifying a disadvantaged community for the purposes of SB 535, the California Office of Environmental Health Hazard Assessment has developed the California Communities Environmental Health Screening Tool (CalEnviroScreen). CalEnviroScreen measures pollution and population characteristics using 20 indicators such as air and drinking water quality, waste sites, toxic emissions, asthma rates, and poverty. It applies a formula to each U.S. Census tract in California to generate a score that rates the level of cumulative impacts on each area. A census tract with a higher score is one that experiences higher pollution burdens and vulnerability than one with a lower score. A census tract that scores in the top 25% under the CalEnviroScreen formula is considered a disadvantaged community.

The project site is within Census Tract 6077000100, which includes much of downtown Stockton and the area south of SR 4. This Census tract has a CalEnviroScreen score in the 100 percentile, which makes it a disadvantaged community as defined by SB 535. The tract, the population of which is 54.2% Hispanic and 19.4% African American, had high indicator scores related to diesel particulate matter, lead from housing, groundwater threats, hazardous waste, and solid waste among others. Unemployment, poverty, education, housing burden, and linguistic isolation also were issues of concern (OEHHA 2021).

SB 1000 – Environmental Justice and General Plans

SB 1000, signed into law in 2016, requires cities and counties to adopt an Environmental Justice element or to integrate environmental justice goals, objectives, and policies into other elements of their General Plans. The Environmental Justice Element or integrated

environmental justice policies must reduce the unique or compounded health risks in disadvantaged communities.

The City of Stockton General Plan 2040 does not have an Environmental Justice Element. However, it does include numerous policies and actions throughout its elements that address environmental justice issues. These policies and actions are listed in the Environmental Justice section of Appendix A of the General Plan. Among them, Policy CH-4.2, from the Community Health Element, states that the City shall support homeless members of the Stockton community with programs to improve quality of life.

Analysis and Conclusions

As noted, the project site is within a Census tract that is a disadvantaged community as defined by SB 535. Project impacts related to environmental burdens on the disadvantaged community are described below.

- Air pollutant emissions, including criteria pollutants and diesel particulate matter, generated by the project could adversely affect nearby residents. However, as described in Chapter 5.0, Air Quality, project operational emissions would be well below SJVAPCD significance thresholds, which were established, in part, to ensure that project emissions did not interfere with the implementation of air quality management plans designed to meet federal and State air quality standards.

- Another project impact that could adversely affect well-being in the community is increased noise from project construction. As discussed in Chapter 13.0, Noise, construction noise impacts would be less than significant with implementation of mitigation measures. Project operations are not expected to generate substantial, particularly since very little traffic would be involved.

- The project would not contribute to existing environmental burdens identified in the Census tract. The project would not generate hazardous waste or release toxic emissions, and it would not contribute contaminants to local groundwater aquifers. The project would provide a shelter to homeless people, who are more vulnerable to health issues than the general population. As such, it would reduce health burdens. The project would also alleviate shelter issues arising from poverty and unemployment.

As noted above, SB 1000 recommends the integration of environmental justice topics in land use planning. Some of these topics are connected to potential project impacts on the physical environment. Table 19-1 lists the SB 1000 environmental justice topics potentially relevant to CEQA analysis and the project's impacts related to these topics.

TABLE 19-1
SB 1000 TOPICS AND PROJECT IMPACTS

SB 1000 Topic	Project Impacts
Pollution Exposure and Air Quality	The project would generate air pollutant emissions that are below SJVAPCD significance thresholds designed to assist in achieving federal and state air quality standards. The nearest major air pollution or toxics emission source is State Route 4, the edge of which is approximately 600 feet to the north. The project would connect to the City's water, wastewater, and storm drainage systems, so water pollution is not an issue. (Chapter 5.0, Air Quality; Chapter 10.0, Hazards; Chapter 11.0, Hydrology; Chapter 16.0, Utilities).
Public Facilities	The project would be connected to the City's water and wastewater systems. It would not be located near any undesirable land uses such as landfills or waste collection facilities. The project would be close to existing bus stops (Chapter 14.0, Public Services; Chapter 15.0, Transportation; Chapter 16.0, Utilities).
Food Access	The project would provide additional shelter for homeless people, which would include services such as meals provided from adjacent GCRM facilities, thereby providing greater availability of food to a population that is food-insecure.
Safe and Sanitary Homes	Although no permanent housing units would be constructed, the project would provide additional indoor beds to homeless people, thereby providing expanded options for sheltering indoors. The project would not be exposed to substantial pollution sources such as industrial activities (Chapter 11.0, Hazards; Chapter 13.0, Land Use).
Physical Activity	No effects relevant to this issue.
Civil or Community Engagement	The project seeks to engage with the homeless members of the Stockton Community by providing additional shelter, along with services that address issues associated with homelessness (Chapter 2.0, Project Description, also see environmental justice discussion in this chapter).
Improvements and Programs That Address the Needs of Disadvantaged Communities	The project would provide additional shelter to homeless people. Homelessness is a significant issue in the disadvantaged community within which the project is located (Chapter 1.0, Introduction).

This EIR evaluated potential environmental impacts of the projects, and no significant impacts of any type were identified that could not be mitigated to a level that would be less than significant. The project would have no significant adverse impacts on environmental justice communities in the City and vicinity. In fact, the project is expected to have a beneficial impact on homeless people by providing a facility where they can sleep indoors and receive services. It also would provide a benefit for the

disadvantaged community as a whole by expanding housing options and reducing the number of homeless people on the street.

20.0 SOURCES AND PREPARERS OF THE EIR

20.1 REFERENCES CITED

Bryant, William A. and Earl W. Hart. 2007. Fault-Rupture Hazard Zones in California: Alquist-Priolo Earthquake Fault Zoning Act with Index to Earthquake Fault Zones Maps. Department of Conservation, California Geological Survey Special Publication 42. Interim Revision 2007.

California Air Pollution Control Officers Association (CAPCOA). 2009. Model Policies for Greenhouse Gases in General Plans: A Resource for Local Government to Incorporate General Plan Policies to Reduce Greenhouse Gas Emissions. June 2009.

California Air Resources Board (ARB). 2005. Air Quality and Land Use Handbook: A Community Health Perspective. April 2005.

_____. 2008. 2008 California Toxics Inventory. Available online at http://www.arb.ca.gov/ei/cti.xls.

_____. 2016. Ambient Air Quality Standards. May 4, 2016.

_____. 2017. California's 2017 Climate Change Scoping Plan. November 2017.

_____. 2020a. CEPAM: 2016 SIP - Standard Emission Tool, Emission Projections by Summary Category. Available online at https://www.arb.ca.gov/app/emsinv/fcemssumcat/cepam_emssumcat_query_v5.php. Accessed December 22, 2020.

_____. 2020b. California Greenhouse Gas Emissions for 2000 to 2018.

California Department of Conservation, Division of Land Resources Protection, Farmland Mapping and Monitoring Program. 2018. San Joaquin County Important Farmland 2016, Sheet 1 of 2 (map). February 2018.

California Department of Finance. 2019. Report E-5 - Population and Housing Estimates for Cities, Counties, and the State, January 1, 2011-2021, with 2010 Benchmark. Released May 1, 2021.

California Department of Toxic Substances Control (DTSC). 2021. EnviroStor database, www.envirostor.dtsc.ca.gov. Accessed 2021.

_____. 2018. List of Officially Designated State Scenic Highways. Available online at http://www.dot.ca.gov/hq/LandArch/16_livability/scenic_highways/scenic_hwy.htm.

California Department of Water Resources (DWR). 2018. California's Groundwater. DWR Bulletin 118. Last update June 2017.

_____. 2016b. List of "Active" CDO and CAO from Water Board. Available online at http://www.calepa.ca.gov/SiteCleanup/CorteseList/default.htm. Accessed September 23, 2018.

California Office of Environmental Health Hazard Assessment (OEHHA). 2020. CalEnviroScreen 3.0. Available online at oehha.ca.gov/calenviroscreen/report/calenviroscreen-30. Accessed October 6, 2020.

California Water Service Company (Cal Water). 2016. 2015 Urban Water Management Plan - Stockton District. June 2016.

Central California Information Center. 2021. Re: Project: Gospel Center Men's Dorm, 435/437 S. San Joaquin Street, Stockton, CA, APN 149-066-070. July 20, 2021.

City of Stockton. 2018a. General Plan (GP) – Envision Stockton 2040. Adopted December 2018

_____. 2018. Envision Stockton 2040 General Plan Update and Utility Master Plan, Supplemental Final EIR and Mitigation Monitoring and Reporting Program. SCH No. 2017052062. October 2018. Prepared by Placeworks.

Condor Earth Phase I Environmental Site Assessment. 2021. New Life Men's Facility 429-431 and 435-437 South San Joaquin Street, Stockton, San Joaquin County, CA. 2021

Evans and DeShazo, 2022. Photographs, Written Historical and Descriptive Data for 429-431 and 435-437 S. San Joaquin Street, Stockton, San Joaquin County, California. Prepared for Historic American Building Survey, National Park Service. February 2022.

Federal Emergency Management Agency. 2009. Flood Insurance Rate Map (FEMA #06077C0460F). San Joaquin County, California. Map revised October 16, 2009.

Federal Highway Administration (FHWA). 2006. Roadway Construction Noise Model User's Guide. FHWA-HEP-05-054. January 2006.

Governor's Office of Planning and Research (OPR). 2018. Technical Advisory on Evaluating Transportation Impacts in CEQA. December 2018.

Harris, Cyril M. 1991. Handbook of Acoustical Measurements and Noise Control. McGraw-Hill, Inc., New York.

National Oceanic and Atmospheric Administration (NOAA). 2019. Monthly Average Mauna Loa CO_2. Data collected by Earth System Research Laboratory, Global Monitoring Division. Available online at https://www.esrl.noaa.gov/gmd/ccgg/trends/. Accessed July 25, 2019.

Page and Turnbull, 2019. California Department of Parks and Recreation, Primary Record for Wills House 435-437 S San Joaquin Street, Stockton, San Joaquin County, California. October 31, 2019.

Page and Turnbull, 2019. California Department of Parks and Recreation, Primary Record for Wills House 429-431 S San Joaquin Street, Stockton, San Joaquin County, California. November 4, 2019.

San Joaquin County Airport Land Use Commission (ALUC). 2018. San Joaquin County Airport Land Use Compatibility Plan Update. Prepared by Coffman Associates, Inc. Adopted May 2016, Amended February 2018.

San Joaquin County Continuum of Care (SJCCoC), 2019. San Joaquin County Continuum of Care Report on the 2019 Point in Time Count. http://www.sanjoaquincoc.org/. Accessed February 1, 2022.

San Joaquin Valley Air Pollution Control District (SJVAPCD). 2008. Climate Change Action Plan Staff Report. November 2008.

_____. 2009. Final Staff Report – Climate Change Action Plan: Addressing Greenhouse Gas Emissions Impact under the San Joaquin Valley Air Pollution Control District.

_____. 2015. Guide for Assessing and Mitigating Air Quality Impacts (GAMAQI). March 19, 2015.

_____. 2018. 2018 Plan for the 1997, 2006, and 2012 $PM_{2.5}$ Standards. November 15, 2018.

_____. 2020. Ambient Air Quality Standards and Valley Attainment Status. Available online at http://www.valleyair.org/aqinfo/attainment.htm. Accessed August 7, 2020.

State Water Resources Control Board (SWRCB). 2018. GeoTracker website, www.geotracker.swrcb.ca.gov. Accessed September 22, 2021.

United Nations Intergovernmental Panel on Climate Change (IPCC). 2001. Climate Change 2001: The Scientific Basis. Contribution of Working Group I to the Third Assessment Report of the Intergovernmental Panel on Climate Change.

U.S. Department of Agriculture, Natural Resources Conservation Service (NRCS). 2020. Custom Soil Resource Report for San Joaquin County, California. December 22, 2021.

U.S. Energy Information Administration (EIA). 2017. California State Energy Profile. Last updated October 19, 2017.

_____. 2018. 2015 Residential Energy Consumption Survey: Energy Consumption and Expenditures Tables. Table CE4.10: Annual household site end-use consumption by fuel in the West - averages, 2015. Release date May 2018.

U.S. Environmental Protection Agency (EPA). 2009. Endangerment and Cause of Contribute Findings for Greenhouse Gases Under Section 202(a) of the Clean Air Act. Federal Register Vol. 74, No. 239, pp. 66496-66546. December 15, 2009.

Wagner, D. L., E. J. Bortugno, and R. D. McJunkin. 1981. Geologic Map of the Sacramento Quadrangle, California, 1:250,000. California Division of Mines and Geology, Regional Geologic Map Series.

Westerling, Leroy, Josue Medellin-Azuara, Joshua Viers. 2018. San Joaquin Valley Summary Report. California's Fourth Climate Change Assessment. Publication number: SUM-CCCA4-2018-003.

20.2 PERSONS CONSULTED

Nicole Moore. LEED-AP. City of Stockton Community Development Department

Wayne Richardson. CEO. Gospel Center Rescue Mission, Inc.

William Brown. Gospel Center Rescue Mission, Inc.

Melanie Vieux. Principal Architect. WMB Architects.

Stacey DeShazo. Architectural Historian. Evans and De Shazo, Inc.

20.3 EIR PREPARERS

This IS/MND was prepared by BaseCamp Environmental, Inc. for use by and under the supervision of the City of Stockton Department of Community Development. The following persons were involved in preparation of the IS/MND:

BaseCamp Environmental, Inc.

Charlie Simpson, Principal
Terry Farmer, AICP, Senior Environmental Planner
Rayanna Beck, Environmental Planner
Krista Simpson, Graphic Artist

APPENDIX A
NOTICE OF PREPARATION AND NOP COMMENTS

CITY OF STOCKTON
NOTICE OF PREPARATION OF A DRAFT ENVIRONMENTAL IMPACT REPORT

DATE: May 18, 2022

TO: Responsible and Trustee Agencies, Organizations, and Interested Parties

FROM: City of Stockton, Community Development Department (Lead Agency)

SUBJECT: **NOTICE OF PREPARATION, EIR FOR GCRM HOMELESS NEW LIFE DORMITORY**

PROJECT TITLE: Gospel Center Rescue Mission Homeless New Life Dormitory

CITY PROJECT FILE #: P21-1188

The City of Stockton will prepare an Environmental Impact Report (EIR) for the Gospel Center Rescue Mission Homeless New Life Dormitory (hereafter, the "Project") pursuant to Section 15021 of the California Environmental Quality Act (CEQA) Guidelines. Section 15082 of the CEQA Guidelines requires that the City prepare this Notice of Preparation (NOP) to provide to the Office of Planning and Research, responsible and trustee agencies, and other interested parties with sufficient information describing the Project and its potential environmental effects to enable the responsible agencies and other parties to make a meaningful response. The project description, location and the probable environmental effects to be addressed in the EIR are contained in the attached materials.

As specified by the CEQA Guidelines, the NOP will be circulated for a 30-day review period running from May 23, 2022, to June 21, 2022. The City welcomes your input regarding the content of the EIR during the NOP review period. In the event the City has not received either a response or a well-justified request for additional time by a responsible agency by the end of the review period, the City may presume that the responsible agency has no response to the NOP (CEQA Guidelines Section 15082[b][2]).

If you have any questions regarding this matter, or would like to submit comments on behalf of your agency/organization or as an individual, please contact or submit your comments to the City's Project Manager at:

City of Stockton
Community Development Department
Attention: Nicole Moore
345 N. El Dorado Street
Stockton, CA 95202
Nicole.Moore@stocktonca.gov.

ATTACHMENT A

NOTICE OF PREPARATION
ENVIRONMENTAL IMPACT REPORT
GOSPEL CENTER RESCUE MISSION HOMELESS
NEW LIFE DORMITORY

A.1 PROJECT LOCATION

The Gospel Center's proposed New Life Dormitory is located at 435 South San Joaquin Street in Stockton, California. The project site is a single parcel occupied by two existing residential structures; the site is identified as Assessor Parcel Number (APN) 149-066-070. The site is shown in an un-sectioned portion of U.S. Geological Survey's Stockton West, California, 7.5-minute quadrangle map as being within Township 1 North and Range 6 East of the Mt. Diablo Base and Meridian. The approximate latitude and longitude of the project site is 37º 56' 55" North and 121º 17' 11" West, respectively.

A.2 BACKGROUND

The project is in an existing urban area and the site is presently occupied by two residential structures constructed in 1904. The existing buildings contain 19 residential beds currently used by the Gospel Center Rescue Mission for homeless housing. Both structures are of historic age and have been evaluated for their potential historic significance by qualified architectural historians. Both structures were deemed eligible for listing on the National Register of Historic Places, the California Register and as a City of Stockton Landmark and are considered historically significant. The buildings embody the distinctive characteristics of a multi-family house built in the Free Classic Queen Anne style.

The proposed project will involve demolition of the two existing structures, and construction of the proposed 178-bed shelter. The project will therefore have a significant adverse effect on historic resources. There is no known feasible alternative or mitigation measure that would reduce the effect of the project on historic properties to a less than significant level. Therefore, the project requires the preparation of an Environmental Impact Report (EIR).

The EIR will be focused on the cultural resources effect of the project associated with demolition of the existing buildings. The EIR will, however, address the range of other potential environmental effects of the proposed project as listed in Appendix G of the CEQA Guidelines. The level of analysis will be scaled to the potential for occurrence of significant environmental effects in each environmental issue area.

A.3 PROJECT DESCRIPTION

The proposed project is the demolition of two existing buildings on the project site and the construction and operation of the proposed, three-story 178-bed, dormitory for homeless people in the City of Stockton and vicinity. The facility will include one to four-bed sleeping rooms and be equipped with laundry facilities, counseling and educational resources, fitness gym, and activity rooms.

The project site is designated and zoned for general commercial development in the City of Stockton, and the project is allowable with a Use Permit. In addition to a Use Permit, the project would require Site Plan/Design Review approval, building and grading permits from the City, and encroachment permits for work in City streets.

A.4 ISSUES TO BE ANALYZED IN THE EIR

The City of Stockton has determined that an Environmental Impact Report (EIR) will be prepared for the project. The EIR, which is in preparation, will consider the potential environmental effects of the project, any mitigation measures needed to reduce significant environmental effects to a less than significant level and alternatives to the project. Concerns to be addressed in the EIR are summarized below.

Aesthetics and Visual Resources

The EIR will consider the asthetic e ffects of building demolition, the size and architectural character of the proposed structure and related improvements, their relationship to surrounding development and general consistency with City of Stockton design standards, together with potential lighting impacts.

Air Quality

The EIR will quantify demolition, construction and operational air pollutant emissions associated with the project, their relationship to state and federal standards and applicable emissions thresholds.

Biological Resources

The EIR will document the existing biological resources of the project site and the potential biological effects of building demolition and construction. The EIR will describe the project's effects on sensitive wildlife resources, if any, and mitigation for such effects provided by the San Joaquin County Multi-Species Habitat Conservation and Open Space Plan.

Cultural Resources

The EIR will document the results of a cultural resources record search and historical resource evaluation of the two existing buildings on the site and their historic significance. The EIR will describe the potential historic resources effect of the demolition of the structures; the EIR will explore and discuss potential mitigation options and project alternatives that could conceivably reduce potential cultural resources effects to a less than significant level. The EIR will also include consideration of the potential effects of proposed development on as yet-undiscovered historical and/or archaeological resources.

Energy

The EIR will consider and discuss predicted energy consumption associated with the project, along with conservation measures associated with the siting and operation of the project generally and those that would be incorporated into proposed buildings.

Geology, Soils, and Mineral Resources

The EIR will describe the general geology of the project area, geotechnical and seismic hazards, soil quality and erosion potential, suitability of soil for development, potential project impact on accessibility of mineral resources, and potential effects on paleontological resources.

Greenhouse Gas (GHG) Emissions

The EIR will quantify the significance of construction and operational GHG emissions associated with the project and the project's consistency with applicable GHG management plans, including the Stockton Climate Action Plan.

Hazards and Hazardous Materials

The EIR will document the presence or absence of any documented environmental contamination on and near the project site based on a Phase 1 Environmental Site Assessment prepared for the project.

Hydrology and Water Quality

The EIR will briefly describe the surface and groundwater hydrologic resources of the project site and exposure to flooding hazards. Storm water volume and quality and required conformance with adopted City of Stockton storm water quality protection and treatment standards will also be addressed.

Land Use, Population, and Housing

The EIR will document the project's consistency with the Stockton General Plan, zoning, and other applicable land use plans and ordinances, along with the potential direct and indirect impacts of the project on population growth and housing needs.

Noise

The EIR will describe the existing noise environment and the potential effects of project construction and operation on sensitive land uses adjacent to and near the project.

Public Services and Recreation

The EIR will document existing public service providers responsible for the project on completion. The EIR will consider the need for new or expanded facilities for fire protection, police protection, schools, and parks and recreation, and the potential impacts of any new or expanded public facilities on the environment.

Transportation

The EIR will document existing transportation systems serving the project site and vicinity and quantify new traffic associated with project residents. The EIR will consider the effect of any new transportation demands on existing transportation systems.

Utilities

The EIR will describe existing utility systems serving the project site and any necessary extension of water, wastewater, storm drainage, solid waste or other utilities to serve the project and the potential environmental impacts of those extensions.

Cumulative Impacts

The EIR will consider the potential cumulative impacts of the project in all of the above-listed resource areas, based primarily on the analysis of citywide environmental effects in the recently adopted Envision Stockton General Plan 2040 EIR.

Alternatives to the Proposed Project


The EIR will evaluate the comparative environmental effects of a reasonable range of alternatives to the proposed project, including the required No Project Alternative. The alternatives to be analyzed is to be determined.

Growth-Inducing Impacts

The EIR will consider direct and indirect potential effects of the proposed project on planned or potential urban development in the project vicinity.


Environmental Justice

The State is taking a more active role on environmental justice issues in land use and environmental planning. The EIR will discuss environmental justice concerns as they apply to the project.




BaseCamp Environmental

Figure 1
REGIONAL PROJECT LOCATION



BaseCamp Environmental

Figure 2
STREET MAP



SOURCE: Stockton West USGS Map, 1968, T1N, R6E. No Section number exists for this site



SOURCE: Google Earth




Figure 5
ASSESSOR PARCEL MAP

S J C O G, Inc.

555 East Weber Avenue ● Stockton, CA 95202 ● (209) 235-0600 ● FAX (209) 235-0438

San Joaquin County Multi-Species Habitat Conservation & Open Space Plan (SJMSCP)

SJMSCP RESPONSE TO LOCAL JURISDICTION (RTLJ) ADVISORY AGENCY NOTICE TO SJCOG, Inc.

To: Nicole Moore, City of Stockton, Community Development Department

From: Laurel Boyd, SJCOG, Inc. Phone: (209) 235-0574 Email: boyd@sjcog.org

Date: May 24, 2022

Local Jurisdiction Project Title: Notice of Preparation of an Environmental Impact Report for the Gospel Center Rescue Mission Homeless New Life Dormitory

Assessor Parcel Number(s): 149-065-07

Local Jurisdiction Project Number: N/A

Total Acres to be converted from Open Space Use: Unknown

Habitat Types to be Disturbed: Urban Habitat Land

Species Impact Findings: Findings to be determined by SJMSCP biologist.

Dear Ms. Moore:

SJCOG, Inc. has reviewed the Notice of Preparation of an Environmental Impact Report for the Gospel Center Rescue Mission Homeless New Life Dormitory Project. This project consists of the demolition of two existing structures on the project site and the construction and operation of the proposed, three-story 178-bed, dormitory for homeless people in the City of Stockton and vicinity. The facility will include one to four-bed sleeping rooms and be equipped with laundry facilities, counseling and educational resources, fitness gym and activity rooms.

The City of Stockton is a signatory to San Joaquin County Multi-Species Habitat Conservation and Open Space Plan (SJMSCP). Participation in the SJMSCP satisfies requirements of both the state and federal endangered species acts, and ensures that the impacts are mitigated below a level of significance in compliance with the California Environmental Quality Act (CEQA). The LOCAL JURISDICTION retains responsibility for ensuring that the appropriate Incidental Take Minimization Measure are properly implemented and monitored and that appropriate fees are paid in compliance with the SJMSCP. Although participation in the SJMSCP is voluntary, Local Jurisdiction/Lead Agencies should be aware that if project applicants choose against participating in the SJMSCP, they will be required to provide alternative mitigation in an amount and kind equal to that provided in the SJMSCP.

This project is not subject to participate at this time due to structure and ground disturbance already existing. *Any future structures that require ground disturbance on this or subsequent divided parcels will be subject to participate in the SJMSCP and should be resubmitted to this agency.*

It should be noted that if this project has any potential impacts to waters of the United States [pursuant to Section 404 Clean Water Act], it would require the project to seek voluntary coverage through the unmapped process under the SJMSCP which could take up to 90 days. It may be prudent to obtain a preliminary wetlands map from a qualified consultant. If waters of the United States are confirmed on the project site, the Corps and the Regional Water Quality Control Board (RWQCB) would have regulatory authority over those mapped areas [pursuant to Section 404 and 401 of the Clean Water Act respectively] and permits would be required from each of these resource agencies prior to grading the project site.

If you have any questions, please call (209) 235-0600.

From: **Nicole Moore.Ctr** Nicole.Moore.Ctr@stocktonca.gov
Subject: Fw: Notice of Preparation – Gospel Center Rescue Mission
Date: May 25, 2022 at 2:11 PM
To: Charlie Simpson csimpson@basecampenv.com, Rayanna Beck rbeck@basecampenv.com

NM

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

FYI:

Nicole D. Moore, LEED-AP
Contract Planner
Community Development Department
345 N. El Dorado Street, Stockton CA 95202
Office: 209.937.8266 Direct: 323-955-5501

For City of Stockton Updates on COVID-19 please visit:
Twitter @stocktonUpdates
Facebook @CityofStockton
City Website http://www.stocktonca.gov

From: Cal - Design <Cal_Design@comcast.com>
Sent: Wednesday, May 25, 2022 1:21 PM
To: Rayanna Beck <rbeck@basecampenv.com>; Henson, Thomas <Tommy_Henson@comcast.com>
Cc: Nicole Moore.Ctr <Nicole.Moore.Ctr@stocktonca.gov>
Subject: RE: Notice of Preparation – Gospel Center Rescue Mission

CAUTION: This email originated from outside the City of Stockton. Do not click any links or open attachments if this is unsolicited email.
Hello,

Attached is a map of Comcast's facilities/plants in the area you requested. Please let me know if you need any additional information or have any questions.

Thank you,

Evan Teung-Ouk,
Planning & Design Coordinator
3011 Triad Place, Livermore, CA

From: Rayanna Beck <rbeck@basecampenv.com>

From: Rayanna Beck <rbeck@basecampenv.com>
Sent: Monday, May 23, 2022 12:18 PM
To: Cal - Design <Cal_Design@cable.comcast.com>; Henson, Thomas <Tommy_Henson@cable.comcast.com>
Subject: [EXTERNAL] Notice of Preparation – Gospel Center Rescue Mission

Please see the attached Notice of Preparation of a Draft Environmental Impact Report for the Gospel Center Rescue Mission Homeless New Life Dormitory.

Please address any project concerns to Nicole Moore at the City of Stockton Community Development Department : Nicole.moore@stocktonca.gov

For document accessibility concerns, please reply to this email for assistance.

Thank you for your time.

Rayanna Beck
BaseCamp Environmental, Inc.
802 West Lodi Ave
Lodi, CA 95240
Office: 209-224-8213
Ext:104



435 S San Joaquin St.pdf



429 S San Joaquin St.pdf

SAN JOAQUIN COUNTY
Greatness grows here.

Environmental Health Department
Jasjit Kang, REHS, Director
Muniappa Naidu, REHS, Assistant Director
PROGRAM COORDINATORS
Robert McClellon, REHS
Jeff Carruesco, REHS, RDI
Willy Ng, REHS
Melissa Nissim, REHS
Steven Shih, REHS
Michelle Henry, REHS
Elena Manzo, REHS

June 7, 2022

To: San Joaquin County Community Development Department
Attention: Nicole D. Moore

From: Michael Suszycki (209) 598-7001
Senior Registered Environmental Health Specialist

RE: **Gospel Center Rescue Mission, P21-1188, SU0014960 (2675 429 to 431 and 435 to 437 San Joaquin Street, Stockton**

The San Joaquin County Environmental Health Department (EHD) has the following comments for consideration:

1. Any geotechnical drilling shall be conducted under permit and inspection by The Environmental Health Department (San Joaquin County Development Title, Section 9-1115.3 and 9-1115.6).

San Joaquin Valley
AIR POLLUTION CONTROL DISTRICT

HEALTHY AIR LIVING

June 15, 2022

Nicole Moore
City of Stockton
Community Development Department
345 N. El Dorado Street
Stockton, CA, 95202

Project: Notice of Preparation for an Environmental Impact Report for Gospel Center Rescue Mission Homeless New Life Dormitory

District CEQA Reference No: 20220716

Dear Ms. Moore:

The San Joaquin Valley Air Pollution Control District (District) has reviewed the Notice of Preparation (NOP) for the City of Stockton (City) for the Gospel Center Rescue Mission Homeless New Life Dormitory. Per the NOP, the project consists of the demolition of two existing structures and the construction of a proposed 178 bed shelter (Project). The Project is located at 435 South San Joaquin Street in Stockton, CA, 95203. The Project lies within one of the communities in the state selected by the California Air Resources Board (CARB) for investment of additional air quality resources and attention under Assembly Bill (AB) 617 (Garcia) in an effort to reduce air pollution exposure in impacted disadvantaged communities.

The District offers the following comments regarding the Project:

1) Assembly Bill 617

AB 617 requires CARB and air districts to develop and implement Community Emission Reduction Programs (CERPs) in an effort to reduce air pollution exposure in impacted disadvantaged communities, like those in which the Project is located. The Stockton AB 617 community is one of the statewide communities selected by CARB for development and implementation of a CERP.

Following extensive community engagement and collaboration with the Community Steering Committee, the CERP for the Stockton Community was adopted by the District's Governing Board in March 2021 and by CARB in July 2021.

Samir Sheikh
Executive Director/Air Pollution Control Officer

Northern Region
4800 Enterprise Way
Modesto, CA 95356-8718
Tel: (209) 557-6400 FAX: (209) 557-6475

Central Region (Main Office)
1990 E. Gettysburg Avenue
Fresno, CA 93726-0244
Tel: (559) 230-6000 FAX: (559) 230-6061

Southern Region
34946 Flyover Court
Bakersfield, CA 93308-9725
Tel: (661) 392-5500 FAX: (661) 392-5585

www.valleyair.org www.healthyairliving.com

Printed on recycled paper.

During the development of the CERP, the Community Steering Committee expressed concerns regarding the proximity of emission sources to nearby sensitive receptors like schools, homes, day care centers, and hospitals, and the potential future industrial development within the community that may exacerbate the cumulative exposure burden for community residents. The Community Steering Committee also expressed the desire for more meaningful avenues of engagement surrounding the land-use decisions in the area. As these issues can most effectively be addressed through strong partnerships between community members and local land-use agencies. Furthermore, the District recommends the City assess the emission reductions measures and strategies included in the CERP and address them in the EIR, as appropriate, to align the City work with the air pollution and exposure reduction strategies and measures outlined in the CERP.

For more information regarding the CERP approved for Stockton, please visit the District's website at:

http://community.valleyair.org/selected-communities/stockton/

2) Project Related Emissions

Based on information provided to the District, Project specific annual criteria pollutant emissions from construction and operation are not expected to exceed any of the significance thresholds as identified in the District's Guidance for Assessing and Mitigating Air Quality Impacts (GAMAQI): https://www.valleyair.org/transportation/GAMAQI.pdf.

2a) Construction Emissions

The District recommends, to reduce impacts from construction-related diesel exhaust emissions, the Project should utilize the cleanest available off-road construction equipment, including the latest tier equipment.

3) Health Risk Screening/Assessment

The City should evaluate the risk associated with the Project for sensitive receptors (residences, businesses, hospitals, day-care facilities, health care facilities, etc.) in the area and mitigate any potentially significant risk to help limit exposure of sensitive receptors to emissions.

To determine potential health impacts on surrounding receptors (residences, businesses, hospitals, day-care facilities, health care facilities, etc.) a Prioritization and/or a Health Risk Assessment (HRA) should be performed for the Project. These health risk determinations should quantify and characterize potential Toxic Air Contaminants (TACs) identified by the Office of Environmental Health Hazard

Assessment/California Air Resources Board (OEHHA/CARB) that pose a present or potential hazard to human health.

Health risk analyses should include all potential air emissions from the project, which include emissions from construction of the project, including multi-year construction, as well as ongoing operational activities of the project. Note, two common sources of TACs can be attributed to diesel exhaust emitted from heavy-duty off-road earth moving equipment during construction, and from ongoing operation of heavy-duty on-road trucks.

Prioritization (Screening Health Risk Assessment):
A "Prioritization" is the recommended method for a conservative screening-level health risk assessment. The Prioritization should be performed using the California Air Pollution Control Officers Association's (CAPCOA) methodology.

The District recommends that a more refined analysis, in the form of an HRA, be performed for any project resulting in a Prioritization score of 10 or greater. This is because the prioritization results are a conservative health risk representation, while the detailed HRA provides a more accurate health risk evaluation.

To assist land use agencies and project proponents with Prioritization analyses, the District has created a prioritization calculator based on the aforementioned CAPCOA guidelines, which can be found here:
http://www.valleyair.org/busind/pto/emission_factors/Criteria/Toxics/Utilities/PRIORITIZATION-CALCULATOR.xls

Health Risk Assessment:
Prior to performing an HRA, it is strongly recommended that land use agencies/ project proponents develop and submit for District review a health risk modeling protocol that outlines the sources and methodologies that will be used to perform the HRA. This step will ensure all components are addressed when performing the HRA.

A development project would be considered to have a potentially significant health risk if the HRA demonstrates that the project-related health impacts would exceed the District's significance threshold of 20 in a million for carcinogenic risk, or 1.0 for either the Acute or Chronic Hazard Indices.

A project with a significant health risk would trigger all feasible mitigation measures. The District strongly recommends that development projects that result in a significant health risk not be approved by the land use agency.

The District is available to review HRA protocols and analyses. For HRA submittals please provide the following information electronically to the District for review:

- HRA (AERMOD) modeling files
- HARP2 files
- Summary of emissions source locations, emissions rates, and emission factor calculations and methodologies.

For assistance, please contact the District's Technical Services Department by:

- E-Mailing inquiries to: hramodeler@valleyair.org
- Calling (559) 230-5900

Recommended Measure: Development projects resulting in TAC emissions should be located an adequate distance from residential areas and other sensitive receptors in accordance to CARB's Air Quality and Land Use Handbook: A Community Health Perspective located at https://ww3.arb.ca.gov/ch/handbook.pdf.

4) Ambient Air Quality Analysis

An Ambient Air Quality Analysis (AAQA) uses air dispersion modeling to determine if emissions increases from a project will cause or contribute to a violation of State or National Ambient Air Quality Standards. The District recommends an AAQA be performed for the Project if emissions exceed 100 pounds per day of any pollutant

An acceptable analysis would include emissions from both project-specific permitted and non-permitted equipment and activities. The District recommends consultation with District staff to determine the appropriate model and input data to use in the analysis.

Specific information for assessing significance, including screening tools and modeling guidance, is available online at the District's website: www.valleyair.org/ceqa.

5) Vegetative Barriers and Urban Greening

There are residential units located in close proximity on all sides of the Project. The District suggests the City consider the feasibility of incorporating vegetative barriers and urban greening as a measure to further reduce air pollution exposure on sensitive receptors (e.g., residential units).

While various emission control techniques and programs exist to reduce air quality emissions from mobile and stationary sources, vegetative barriers have been shown

to be an additional measure to potentially reduce a population's exposure to air pollution through the interception of airborne particles and the update of gaseous pollutants. Examples of vegetative barriers include, but are not limited to the following: trees, bushes, shrubs, or a mix of these. Generally, a higher and thicker vegetative barrier with full coverage will result in greater reductions in downwind pollutant concentrations. In the same manner, urban greening is also a way to help improve air quality and public health in addition to enhancing the overall beautification of a community with drought tolerant, low-maintenance greenery.

6) Clean Lawn and Garden Equipment in the Community

Since the Project consists of residential development, gas-powered residential lawn and garden equipment have the potential to result in an increase of NOx and PM2.5 emissions. Utilizing electric lawn care equipment can provide residents with immediate economic, environmental, and health benefits. The District recommends the Project proponent consider the District's Clean Green Yard Machines (CGYM) program which provides incentive funding for replacement of existing gas powered lawn and garden equipment. More information on the District CGYM program and funding can be found at: http://www.valleyair.org/grants/cgym.htm and http://valleyair.org/grants/cgym-commercial.htm.

7) On-Site Solar Deployment

It is the policy of the State of California that renewable energy resources and zero-carbon resources supply 100% of retail sales of electricity to California end-use customers by December 31, 2045. While various emission control techniques and programs exist to reduce air quality emissions from mobile and stationary sources, the production of solar energy is contributing to improving air quality and public health. The District suggests that the City consider incorporating solar power systems as an emission reduction strategy for the Project.

8) Electric Vehicle Chargers

To support and accelerate the installation of electric vehicle charging equipment and development of required infrastructure, the District offers incentives to public agencies, businesses, and property owners of multi-unit dwellings to install electric charging infrastructure (Level 2 and 3 chargers). The purpose of the District's Charge Up! Incentive program is to promote clean air alternative-fuel technologies and the use of low or zero-emission vehicles. The District recommends that the City and project proponents install electric vehicle chargers at project sites, and at strategic locations.

Please visit www.valleyair.org/grants/chargeup.htm for more information.

9) District Rules and Regulations

The District issues permits for many types of air pollution sources, and regulates some activities that do not require permits. A project subject to District rules and regulations would reduce its impacts on air quality through compliance with the District's regulatory framework. In general, a regulation is a collection of individual rules, each of which deals with a specific topic. As an example, Regulation II (Permits) includes District Rule 2010 (Permits Required), Rule 2201 (New and Modified Stationary Source Review), Rule 2520 (Federally Mandated Operating Permits), and several other rules pertaining to District permitting requirements and processes.

The list of rules below is neither exhaustive nor exclusive. Current District rules can be found online at: www.valleyair.org/rules/1ruleslist.htm. To identify other District rules or regulations that apply to future projects, or to obtain information about District permit requirements, the project proponents are strongly encouraged to contact the District's Small Business Assistance (SBA) Office at (209) 557-6446.

9a) District Rules 2010 and 2201 - Air Quality Permitting for Stationary Sources

Stationary Source emissions include any building, structure, facility, or installation which emits or may emit any affected pollutant directly or as a fugitive emission. District Rule 2010 (Permits Required) requires operators of emission sources to obtain an Authority to Construct (ATC) and Permit to Operate (PTO) from the District. District Rule 2201 (New and Modified Stationary Source Review) requires that new and modified stationary sources of emissions mitigate their emissions using Best Available Control Technology (BACT).

This Project may be subject to District Rule 2010 (Permits Required) and Rule 2201 (New and Modified Stationary Source Review) and may require District permits. Prior to construction, the Project proponent should submit to the District an application for an ATC. For further information or assistance, the project proponent may contact the District's SBA Office at (209) 557-6446.

9b) District Rule 9510 - Indirect Source Review (ISR)

The Project is subject to District Rule 9510 because it will receives a project-level discretionary approval from a public agency and will equal or exceed 50 units of residential development.

The purpose of District Rule 9510 is to reduce the growth in both NOx and PM emissions associated with development and transportation projects from mobile and area sources; specifically, the emissions associated with the construction

and subsequent operation of development projects. The ISR Rule requires developers to mitigate their NOx and PM emissions by incorporating clean air design elements into their projects. Should the proposed development project clean air design elements be insufficient to meet the required emission reductions, developers must pay a fee that ultimately funds incentive projects to achieve off-site emissions reductions.

Per Section 5.0 of the ISR Rule, an Air Impact Assessment (AIA) application is required to be submitted no later than applying for project-level approval from a public agency. As of the date of this letter, the District has not received an AIA application for this Project. Please inform the project proponent to immediately submit an AIA application to the District to comply with District Rule 9510. One AIA application should be submitted for the entire Project. It is preferable for the applicant to submit an AIA application as early as possible in the City's approval process so that proper mitigation and clean air design under ISR can be incorporated into the City's analysis.

Information about how to comply with District Rule 9510 can be found online at: http://www.valleyair.org/ISR/ISRHome.htm.

The AIA application form can be found online at: http://www.valleyair.org/ISR/ISRFormsAndApplications.htm.

District staff is available to provide assistance and can be reached by phone at (559) 230-5900 or by email at ISR@valleyair.org.

9c) District Rule 4002 (National Emissions Standards for Hazardous Air Pollutants)

The Project will be subject to District Rule 4002 since the Project will require an existing building to be renovated, partially demolished or removed. This rule requires a thorough inspection for asbestos to be conducted before any regulated facility is demolished or renovated.

Information on how to comply with District Rule 4002 can be found online at: http://www.valleyair.org/busind/comply/asbestosbultn.htm.

9d) District Rule 4601 (Architectural Coatings)

The Project may be subject to District Rule 4601 since it may utilize architectural coatings. Architectural coatings are paints, varnishes, sealers, or stains that are applied to structures, portable buildings, pavements or curbs. The purpose of this rule is to limit VOC emissions from architectural coatings. In addition, this rule specifies architectural coatings storage, cleanup and labeling requirements. Additional information on how to comply with District

Rule 4601 requirements can be found online at:
http://www.valleyair.org/rules/currntrules/r4601.pdf

9e) District Regulation VIII (Fugitive PM10 Prohibitions)

The project proponent may be required to submit a Construction Notification Form or submit and receive approval of a Dust Control Plan prior to commencing any earthmoving activities as described in Regulation VIII, specifically Rule 8021 – *Construction, Demolition, Excavation, Extraction, and Other Earthmoving Activities.*

Should the project result in at least 1-acre in size, the project proponent shall provide written notification to the District at least 48 hours prior to the project proponents intent to commence any earthmoving activities pursuant to District Rule 8021 (Construction, Demolition, Excavation, Extraction, and Other Earthmoving Activities). Also, should the project result in the disturbance of 5-acres or more, or will include moving, depositing, or relocating more than 2,500 cubic yards per day of bulk materials, the project proponent shall submit to the District a Dust Control Plan pursuant to District Rule 8021 (Construction, Demolition, Excavation, Extraction, and Other Earthmoving Activities). For additional information regarding the written notification or Dust Control Plan requirements, please contact District Compliance staff at (559) 230-5950.

The application for both the Construction Notification and Dust Control Plan can be found online at:
https://www.valleyair.org/busind/comply/PM10/forms/DCP-Form.docx

Information about District Regulation VIII can be found online at:
http://www.valleyair.org/busind/comply/pm10/compliance_pm10.htm

9f) District Rule 4901 - Wood Burning Fireplaces and Heaters

The purpose of this rule is to limit emissions of carbon monoxide and particulate matter from wood burning fireplaces, wood burning heaters, and outdoor wood burning devices. This rule establishes limitations on the installation of new wood burning fireplaces and wood burning heaters. Specifically, at elevations below 3,000 feet in areas with natural gas service, no person shall install a wood burning fireplace, low mass fireplace, masonry heater, or wood burning heater.

Information about District Rule 4901 can be found online at:
http://valleyair.org/rule4901/

9g) Other District Rules and Regulations

The Project may also be subject to the following District rules: Rule 4102 (Nuisance), Rule 4601 (Architectural Coatings), and Paving and Maintenance Operations).

10) District Comment Letter

The District recommends that a copy of the District's comments be provided to the Project proponent.

If you have any questions or require further information, please contact Matt Crow by e-mail at Matt.Crow@valleyair.org or by phone at (559) 230-5931.

Sincerely,

Brian Clements
Director of Permit Services



For: Mark Montelongo
Program Manager

17 June 2022

Nicole Moore
City of Stockton, LEED-AP
345 North El Dorado Street
Stockton, CA 95202
Nicole.Moore@stocktonca.gov

COMMENTS TO REQUEST FOR REVIEW FOR THE NOTICE OF PREPARATION FOR THE DRAFT ENVIRONMENTAL IMPACT REPORT, GOSPEL CENTER RESCUE MISSION HOMELESS NEW LIFE DORMITORY PROJECT, SCH#2022050393, SAN JOAQUIN COUNTY

Pursuant to the State Clearinghouse's 18 May 2022 request, the Central Valley Regional Water Quality Control Board (Central Valley Water Board) has reviewed the *Request for Review for the Notice of Preparation for the Draft Environmental Impact Report* for the Gospel Center Rescue Mission Homeless New Life Dormitory Project, located in San Joaquin County.

Our agency is delegated with the responsibility of protecting the quality of surface and groundwaters of the state; therefore, our comments will address concerns surrounding those issues.

I. Regulatory Setting

Basin Plan

The Central Valley Water Board is required to formulate and adopt Basin Plans for all areas within the Central Valley region under Section 13240 of the Porter-Cologne Water Quality Control Act. Each Basin Plan must contain water quality objectives to ensure the reasonable protection of beneficial uses, as well as a program of implementation for achieving water quality objectives with the Basin Plans. Federal regulations require each state to adopt water quality standards to protect the public health or welfare, enhance the quality of water and serve the purposes of the Clean Water Act. In California, the beneficial uses, water quality objectives, and the Antidegradation Policy are the State's water quality standards. Water quality standards are also contained in the National Toxics Rule, 40 CFR Section 131.36, and the California Toxics Rule, 40 CFR Section 131.38.

The Basin Plan is subject to modification as necessary, considering applicable laws, policies, technologies, water quality conditions and priorities. The original Basin Plans were adopted in 1975, and have been updated and revised periodically as required, using Basin Plan amendments. Once the Central Valley Water Board has

adopted a Basin Plan amendment in noticed public hearings, it must be approved by the State Water Resources Control Board (State Water Board), Office of Administrative Law (OAL) and in some cases, the United States Environmental Protection Agency (USEPA). Basin Plan amendments only become effective after they have been approved by the OAL and in some cases, the USEPA. Every three (3) years, a review of the Basin Plan is completed that assesses the appropriateness of existing standards and evaluates and prioritizes Basin Planning issues. For more information on the *Water Quality Control Plan for the Sacramento and San Joaquin River Basins*, please visit our website:
http://www.waterboards.ca.gov/centralvalley/water_issues/basin_plans/

Antidegradation Considerations

All wastewater discharges must comply with the Antidegradation Policy (State Water Board Resolution 68-16) and the Antidegradation Implementation Policy contained in the Basin Plan. The Antidegradation Implementation Policy is available on page 74 at:
https://www.waterboards.ca.gov/centralvalley/water_issues/basin_plans/sacsjr_201805.pdf

In part it states:

Any discharge of waste to high quality waters must apply best practicable treatment or control not only to prevent a condition of pollution or nuisance from occurring, but also to maintain the highest water quality possible consistent with the maximum benefit to the people of the State.

This information must be presented as an analysis of the impacts and potential impacts of the discharge on water quality, as measured by background concentrations and applicable water quality objectives.

The antidegradation analysis is a mandatory element in the National Pollutant Discharge Elimination System and land discharge Waste Discharge Requirements (WDRs) permitting processes. The environmental review document should evaluate potential impacts to both surface and groundwater quality.

II. Permitting Requirements

Construction Storm Water General Permit

Dischargers whose project disturb one or more acres of soil or where projects disturb less than one acre but are part of a larger common plan of development that in total disturbs one or more acres, are required to obtain coverage under the General Permit for Storm Water Discharges Associated with Construction and Land Disturbance Activities (Construction General Permit), Construction General Permit Order No. 2009-0009-DWQ. Construction activity subject to this permit includes clearing, grading, grubbing, disturbances to the ground, such as stockpiling, or excavation, but does not include regular maintenance activities performed to restore the original line, grade, or capacity of the facility. The Construction General Permit requires the development and implementation of a Storm Water Pollution Prevention Plan (SWPPP). For more information on the Construction General Permit, visit the

State Water Resources Control Board website at:
http://www.waterboards.ca.gov/water_issues/programs/stormwater/constpermits.shtml

Phase I and II Municipal Separate Storm Sewer System (MS4) Permits[1]

The Phase I and II MS4 permits require the Permittees reduce pollutants and runoff flows from new development and redevelopment using Best Management Practices (BMPs) to the maximum extent practicable (MEP). MS4 Permittees have their own development standards, also known as Low Impact Development (LID)/post-construction standards that include a hydromodification component. The MS4 permits also require specific design concepts for LID/post-construction BMPs in the early stages of a project during the entitlement and CEQA process and the development plan review process.

For more information on which Phase I MS4 Permit this project applies to, visit the Central Valley Water Board website at:
http://www.waterboards.ca.gov/centralvalley/water_issues/storm_water/municipal_permits/

For more information on the Phase II MS4 permit and who it applies to, visit the State Water Resources Control Board at:
http://www.waterboards.ca.gov/water_issues/programs/stormwater/phase_ii_municipal.shtml

Industrial Storm Water General Permit

Storm water discharges associated with industrial sites must comply with the regulations contained in the Industrial Storm Water General Permit Order No. 2014-0057-DWQ. For more information on the Industrial Storm Water General Permit, visit the Central Valley Water Board website at:
http://www.waterboards.ca.gov/centralvalley/water_issues/storm_water/industrial_general_permits/index.shtml

Clean Water Act Section 404 Permit

If the project will involve the discharge of dredged or fill material in navigable waters or wetlands, a permit pursuant to Section 404 of the Clean Water Act may be needed from the United States Army Corps of Engineers (USACE). If a Section 404 permit is required by the USACE, the Central Valley Water Board will review the permit application to ensure that discharge will not violate water quality standards. If the project requires surface water drainage realignment, the applicant is advised to contact the Department of Fish and Game for information on Streambed Alteration Permit requirements. If you have any questions regarding the Clean Water Act

[1] Municipal Permits = The Phase I Municipal Separate Storm Water System (MS4) Permit covers medium sized Municipalities (serving between 100,000 and 250,000 people) and large sized municipalities (serving over 250,000 people). The Phase II MS4 provides coverage for small municipalities, including non-traditional Small MS4s, which include military bases, public campuses, prisons and hospitals.

Section 404 permits, please contact the Regulatory Division of the Sacramento District of USACE at (916) 557-5250.

Clean Water Act Section 401 Permit – Water Quality Certification

If an USACE permit (e.g., Non-Reporting Nationwide Permit, Nationwide Permit, Letter of Permission, Individual Permit, Regional General Permit, Programmatic General Permit), or any other federal permit (e.g., Section 10 of the Rivers and Harbors Act or Section 9 from the United States Coast Guard), is required for this project due to the disturbance of waters of the United States (such as streams and wetlands), then a Water Quality Certification must be obtained from the Central Valley Water Board prior to initiation of project activities. There are no waivers for 401 Water Quality Certifications. For more information on the Water Quality Certification, visit the Central Valley Water Board website at: https://www.waterboards.ca.gov/centralvalley/water_issues/water_quality_certification/

Waste Discharge Requirements – Discharges to Waters of the State

If USACE determines that only non-jurisdictional waters of the State (i.e., "non-federal" waters of the State) are present in the proposed project area, the proposed project may require a Waste Discharge Requirement (WDR) permit to be issued by Central Valley Water Board. Under the California Porter-Cologne Water Quality Control Act, discharges to all waters of the State, including all wetlands and other waters of the State including, but not limited to, isolated wetlands, are subject to State regulation. For more information on the Waste Discharges to Surface Water NPDES Program and WDR processes, visit the Central Valley Water Board website at:https://www.waterboards.ca.gov/centralvalley/water_issues/waste_to_surface_water/

Projects involving excavation or fill activities impacting less than 0.2 acre or 400 linear feet of non-jurisdictional waters of the state and projects involving dredging activities impacting less than 50 cubic yards of non-jurisdictional waters of the state may be eligible for coverage under the State Water Resources Control Board Water Quality Order No. 2004-0004-DWQ (General Order 2004-0004). For more information on the General Order 2004-0004, visit the State Water Resources Control Board website at: https://www.waterboards.ca.gov/board_decisions/adopted_orders/water_quality/2004/wqo/wqo2004-0004.pdf

Dewatering Permit

If the proposed project includes construction or groundwater dewatering to be discharged to land, the proponent may apply for coverage under State Water Board General Water Quality Order (Low Threat General Order) 2003-0003 or the Central Valley Water Board's Waiver of Report of Waste Discharge and Waste Discharge Requirements (Low Threat Waiver) R5-2018-0085. Small temporary construction dewatering projects are projects that discharge groundwater to land from excavation activities or dewatering of underground utility vaults. Dischargers seeking coverage

under the General Order or Waiver must file a Notice of Intent with the Central Valley Water Board prior to beginning discharge.

For more information regarding the Low Threat General Order and the application process, visit the Central Valley Water Board website at: http://www.waterboards.ca.gov/board_decisions/adopted_orders/water_quality/2003/wqo/wqo2003-0003.pdf

For more information regarding the Low Threat Waiver and the application process, visit the Central Valley Water Board website at: https://www.waterboards.ca.gov/centralvalley/board_decisions/adopted_orders/waivers/r5-2018-0085.pdf

Limited Threat General NPDES Permit

If the proposed project includes construction dewatering and it is necessary to discharge the groundwater to waters of the United States, the proposed project will require coverage under a National Pollutant Discharge Elimination System (NPDES) permit. Dewatering discharges are typically considered a low or limited threat to water quality and may be covered under the General Order for *Limited Threat Discharges to Surface Water* (Limited Threat General Order). A complete Notice of Intent must be submitted to the Central Valley Water Board to obtain coverage under the Limited Threat General Order. For more information regarding the Limited Threat General Order and the application process, visit the Central Valley Water Board website at: https://www.waterboards.ca.gov/centralvalley/board_decisions/adopted_orders/general_orders/r5-2016-0076-01.pdf

NPDES Permit

If the proposed project discharges waste that could affect the quality of surface waters of the State, other than into a community sewer system, the proposed project will require coverage under a National Pollutant Discharge Elimination System (NPDES) permit. A complete Report of Waste Discharge must be submitted with the Central Valley Water Board to obtain a NPDES Permit. For more information regarding the NPDES Permit and the application process, visit the Central Valley Water Board website at: https://www.waterboards.ca.gov/centralvalley/help/permit/

If you have questions regarding these comments, please contact me at (916) 464-4684 or Peter.Minkel2@waterboards.ca.gov.

Peter Minkel

Peter Minkel
Engineering Geologist

cc: State Clearinghouse unit, Governor's Office of Planning and Research, Sacramento

APPENDIX B
AIR QUALITY MODELING RESULTS

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

Gospel Center Men's Shelter

San Joaquin County, Annual

1.0 Project Characteristics

1.1 Land Usage

Land Uses	Size	Metric	Lot Acreage	Floor Surface Area	Population
Homeless Shelter	54.00	Dwelling Unit	0.21	14,577.00	178

1.2 Other Project Characteristics

Urbanization	Urban	**Wind Speed (m/s)**	2.7	**Precipitation Freq (Days)**	51
Climate Zone	2			**Operational Year**	2024
Utility Company	Pacific Gas and Electric Company				
CO2 Intensity (lb/MWhr)	203.98	**CH4 Intensity (lb/MWhr)**	0.033	**N2O Intensity (lb/MWhr)**	0.004

1.3 User Entered Comments & Non-Default Data

Project Characteristics -

Land Use - Adjusted for shelter size and population.

Construction Phase - Anticipated construction activity.

Grading - Actual site acreage.

Architectural Coating - Per SJVAPCD Rule 4601.

Vehicle Trips - Estimated daily trips based on information from project applicant.

Woodstoves - No fireplaces.

Area Coating - Per SJVAPCD Rule 4601.

Construction Off-road Equipment Mitigation - Default values for project.

Mobile Land Use Mitigation -

Area Mitigation - Per SJVAPCD Rule 4601.

Water Mitigation -

Gospel Center Men's Shelter - San Joaquin County, Annual

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

Waste Mitigation -

Table Name	Column Name	Default Value	New Value
tblArchitecturalCoating	EF_Residential_Exterior	150.00	50.00
tblArchitecturalCoating	EF_Residential_Interior	150.00	50.00
tblAreaCoating	Area_EF_Residential_Exterior	150	50
tblAreaCoating	Area_EF_Residential_Interior	150	50
tblAreaMitigation	UseLowVOCPaintResidentialExteriorValue	150	50
tblAreaMitigation	UseLowVOCPaintResidentialInteriorValue	150	50
tblConstDustMitigation	WaterExposedAreaPM10PercentReduction	0	55
tblConstDustMitigation	WaterExposedAreaPM25PercentReduction	0	55
tblConstructionPhase	NumDays	5.00	10.00
tblConstructionPhase	NumDays	100.00	150.00
tblConstructionPhase	NumDays	10.00	20.00
tblFireplaces	NumberGas	29.70	54.00
tblFireplaces	NumberNoFireplace	24.30	0.00
tblGrading	AcresOfGrading	0.50	0.20
tblGrading	AcresOfGrading	1.50	0.20
tblLandUse	LandUseSquareFeet	54,000.00	14,577.00
tblLandUse	LotAcreage	10.80	0.21
tblLandUse	Population	171.00	178.00
tblVehicleTrips	ST_TR	2.03	1.48
tblVehicleTrips	SU_TR	1.95	1.48
tblVehicleTrips	WD_TR	2.40	1.48
tblWoodstoves	NumberCatalytic	0.21	0.00
tblWoodstoves	NumberNoncatalytic	0.21	0.00

2.0 Emissions Summary

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

2.1 Overall Construction

Unmitigated Construction

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Year	tons/yr										MT/yr					
2023	0.1127	0.5986	0.7172	1.3400e-003	0.0355	0.0286	0.0642	0.0104	0.0265	0.0369	0.0000	119.0681	119.0681	0.0281	1.8700e-003	120.3293
Maximum	**0.1127**	**0.5986**	**0.7172**	**1.3400e-003**	**0.0355**	**0.0286**	**0.0642**	**0.0104**	**0.0265**	**0.0369**	**0.0000**	**119.0681**	**119.0681**	**0.0281**	**1.8700e-003**	**120.3293**

Mitigated Construction

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Year	tons/yr										MT/yr					
2023	0.1127	0.5986	0.7172	1.3400e-003	0.0313	0.0286	0.0599	8.8000e-003	0.0265	0.0353	0.0000	119.0680	119.0680	0.0281	1.8700e-003	120.3292
Maximum	**0.1127**	**0.5986**	**0.7172**	**1.3400e-003**	**0.0313**	**0.0286**	**0.0599**	**8.8000e-003**	**0.0265**	**0.0353**	**0.0000**	**119.0680**	**119.0680**	**0.0281**	**1.8700e-003**	**120.3292**

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio-CO2	Total CO2	CH4	N20	CO2e
Percent Reduction	**0.00**	**0.00**	**0.00**	**0.00**	**11.88**	**0.00**	**6.58**	**15.55**	**0.00**	**4.39**	**0.00**	**0.00**	**0.00**	**0.00**	**0.00**	**0.00**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

Quarter	Start Date	End Date	Maximum Unmitigated ROG + NOX (tons/quarter)	Maximum Mitigated ROG + NOX (tons/quarter)
1	4-1-2023	6-30-2023	0.2730	0.2730
2	7-1-2023	9-30-2023	0.3154	0.3154
		Highest	0.3154	0.3154

2.2 Overall Operational

Unmitigated Operational

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Area	0.0778	0.0413	0.4164	2.6000e-004		5.1900e-003	5.1900e-003		5.1900e-003	5.1900e-003	0.0000	43.1880	43.1880	1.4400e-003	7.8000e-004	43.4565
Energy	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	54.9873	54.9873	4.1100e-003	1.0400e-003	55.3985
Mobile	0.0377	0.0602	0.3612	8.5000e-004	0.0863	7.0000e-004	0.0870	0.0231	6.5000e-004	0.0237	0.0000	78.8012	78.8012	4.2700e-003	4.1300e-003	80.1373
Waste						0.0000	0.0000		0.0000	0.0000	5.0423	0.0000	5.0423	0.2980	0.0000	12.4921
Water						0.0000	0.0000		0.0000	0.0000	1.1162	2.4797	3.5959	0.1151	2.7600e-003	7.2932
Total	**0.1189**	**0.1306**	**0.7899**	**1.3000e-003**	**0.0863**	**8.2300e-003**	**0.0946**	**0.0231**	**8.1800e-003**	**0.0313**	**6.1585**	**179.4563**	**185.6148**	**0.4229**	**8.7100e-003**	**198.7775**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

2.2 Overall Operational

Mitigated Operational

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Area	0.0778	0.0413	0.4164	2.6000e-004		5.1900e-003	5.1900e-003		5.1900e-003	5.1900e-003	0.0000	43.1880	43.1880	1.4400e-003	7.8000e-004	43.4565
Energy	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	54.9873	54.9873	4.1100e-003	1.0400e-003	55.3985
Mobile	0.0327	0.0460	0.2776	6.0000e-004	0.0604	5.0000e-004	0.0609	0.0162	4.7000e-004	0.0166	0.0000	55.8425	55.8425	3.5000e-003	3.1500e-003	56.8673
Waste						0.0000	0.0000		0.0000	0.0000	1.2606	0.0000	1.2606	0.0745	0.0000	3.1230
Water						0.0000	0.0000		0.0000	0.0000	0.8930	1.9838	2.8767	0.0920	2.2000e-003	5.8346
Total	**0.1139**	**0.1163**	**0.7064**	**1.0500e-003**	**0.0604**	**8.0300e-003**	**0.0685**	**0.0162**	**8.0000e-003**	**0.0242**	**2.1535**	**156.0015**	**158.1551**	**0.1756**	**7.1700e-003**	**164.6799**

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio-CO2	Total CO2	CH4	N20	CO2e
Percent Reduction	**4.17**	**10.91**	**10.57**	**19.23**	**30.00**	**2.43**	**27.60**	**30.01**	**2.20**	**22.74**	**65.03**	**13.07**	**14.79**	**58.48**	**17.68**	**17.15**

3.0 Construction Detail

Construction Phase

Phase Number	Phase Name	Phase Type	Start Date	End Date	Num Days Week	Num Days	Phase Description
1	Demolition	Demolition	4/1/2023	4/28/2023	5	20	
2	Site Preparation	Site Preparation	4/15/2023	4/17/2023	5	1	
3	Grading	Grading	4/18/2023	4/19/2023	5	2	

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

4	Building Construction	Building Construction	4/20/2023	11/15/2023	5	150	
5	Paving	Paving	9/7/2023	9/13/2023	5	5	
6	Architectural Coating	Architectural Coating	9/14/2023	9/27/2023	5	10	

Acres of Grading (Site Preparation Phase): 0.2

Acres of Grading (Grading Phase): 0.2

Acres of Paving: 0

Residential Indoor: 29,518; Residential Outdoor: 9,839; Non-Residential Indoor: 0; Non-Residential Outdoor: 0; Striped Parking Area: 0 (Architectural Coating – sqft)

OffRoad Equipment

Phase Name	Offroad Equipment Type	Amount	Usage Hours	Horse Power	Load Factor
Architectural Coating	Air Compressors	1	6.00	78	0.48
Paving	Cement and Mortar Mixers	4	6.00	9	0.56
Demolition	Concrete/Industrial Saws	1	8.00	81	0.73
Building Construction	Cranes	1	4.00	231	0.29
Building Construction	Forklifts	2	6.00	89	0.20
Grading	Graders	1	6.00	187	0.41
Site Preparation	Graders	1	8.00	187	0.41
Paving	Pavers	1	7.00	130	0.42
Paving	Rollers	1	7.00	80	0.38
Demolition	Rubber Tired Dozers	1	1.00	247	0.40
Grading	Rubber Tired Dozers	1	6.00	247	0.40
Building Construction	Tractors/Loaders/Backhoes	2	8.00	97	0.37
Demolition	Tractors/Loaders/Backhoes	2	6.00	97	0.37
Grading	Tractors/Loaders/Backhoes	1	7.00	97	0.37
Paving	Tractors/Loaders/Backhoes	1	7.00	97	0.37
Site Preparation	Tractors/Loaders/Backhoes	1	8.00	97	0.37

Gospel Center Men's Shelter - San Joaquin County, Annual

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

Trips and VMT

Phase Name	Offroad Equipment Count	Worker Trip Number	Vendor Trip Number	Hauling Trip Number	Worker Trip Length	Vendor Trip Length	Hauling Trip Length	Worker Vehicle Class	Vendor Vehicle Class	Hauling Vehicle Class
Architectural Coating	1	8.00	0.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT
Building Construction	5	39.00	6.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT
Demolition	4	10.00	0.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT
Grading	3	8.00	0.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT
Paving	7	18.00	0.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT
Site Preparation	2	5.00	0.00	0.00	10.80	7.30	20.00	LD_Mix	HDT_Mix	HHDT

3.1 Mitigation Measures Construction

Water Exposed Area

3.2 Demolition - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					2.9600e-003	0.0000	2.9600e-003	4.5000e-004	0.0000	4.5000e-004	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	6.4600e-003	0.0578	0.0739	1.2000e-004		2.8200e-003	2.8200e-003		2.7000e-003	2.7000e-003	0.0000	10.4182	10.4182	1.9000e-003	0.0000	10.4656
Total	**6.4600e-003**	**0.0578**	**0.0739**	**1.2000e-004**	**2.9600e-003**	**2.8200e-003**	**5.7800e-003**	**4.5000e-004**	**2.7000e-003**	**3.1500e-003**	**0.0000**	**10.4182**	**10.4182**	**1.9000e-003**	**0.0000**	**10.4656**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.2 Demolition - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	2.9000e-004	1.9000e-004	2.2700e-003	1.0000e-005	8.0000e-004	0.0000	8.0000e-004	2.1000e-004	0.0000	2.2000e-004	0.0000	0.6259	0.6259	2.0000e-005	2.0000e-005	0.6317
Total	**2.9000e-004**	**1.9000e-004**	**2.2700e-003**	**1.0000e-005**	**8.0000e-004**	**0.0000**	**8.0000e-004**	**2.1000e-004**	**0.0000**	**2.2000e-004**	**0.0000**	**0.6259**	**0.6259**	**2.0000e-005**	**2.0000e-005**	**0.6317**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					1.3300e-003	0.0000	1.3300e-003	2.0000e-004	0.0000	2.0000e-004	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	6.4600e-003	0.0578	0.0739	1.2000e-004		2.8200e-003	2.8200e-003		2.7000e-003	2.7000e-003	0.0000	10.4182	10.4182	1.9000e-003	0.0000	10.4655
Total	**6.4600e-003**	**0.0578**	**0.0739**	**1.2000e-004**	**1.3300e-003**	**2.8200e-003**	**4.1500e-003**	**2.0000e-004**	**2.7000e-003**	**2.9000e-003**	**0.0000**	**10.4182**	**10.4182**	**1.9000e-003**	**0.0000**	**10.4655**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.2 Demolition - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	2.9000e-004	1.9000e-004	2.2700e-003	1.0000e-005	8.0000e-004	0.0000	8.0000e-004	2.1000e-004	0.0000	2.2000e-004	0.0000	0.6259	0.6259	2.0000e-005	2.0000e-005	0.6317
Total	**2.9000e-004**	**1.9000e-004**	**2.2700e-003**	**1.0000e-005**	**8.0000e-004**	**0.0000**	**8.0000e-004**	**2.1000e-004**	**0.0000**	**2.2000e-004**	**0.0000**	**0.6259**	**0.6259**	**2.0000e-005**	**2.0000e-005**	**0.6317**

3.3 Site Preparation - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					1.1000e-004	0.0000	1.1000e-004	1.0000e-005	0.0000	1.0000e-005	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	2.7000e-004	3.0900e-003	1.9600e-003	0.0000		1.1000e-004	1.1000e-004		1.0000e-004	1.0000e-004	0.0000	0.4275	0.4275	1.4000e-004	0.0000	0.4309
Total	**2.7000e-004**	**3.0900e-003**	**1.9600e-003**	**0.0000**	**1.1000e-004**	**1.1000e-004**	**2.2000e-004**	**1.0000e-005**	**1.0000e-004**	**1.1000e-004**	**0.0000**	**0.4275**	**0.4275**	**1.4000e-004**	**0.0000**	**0.4309**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.3 Site Preparation - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.0000e-005	0.0000	6.0000e-005	0.0000	2.0000e-005	0.0000	2.0000e-005	1.0000e-005	0.0000	1.0000e-005	0.0000	0.0157	0.0157	0.0000	0.0000	0.0158
Total	**1.0000e-005**	**0.0000**	**6.0000e-005**	**0.0000**	**2.0000e-005**	**0.0000**	**2.0000e-005**	**1.0000e-005**	**0.0000**	**1.0000e-005**	**0.0000**	**0.0157**	**0.0157**	**0.0000**	**0.0000**	**0.0158**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					5.0000e-005	0.0000	5.0000e-005	1.0000e-005	0.0000	1.0000e-005	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	2.7000e-004	3.0900e-003	1.9600e-003	0.0000		1.1000e-004	1.1000e-004		1.0000e-004	1.0000e-004	0.0000	0.4275	0.4275	1.4000e-004	0.0000	0.4309
Total	**2.7000e-004**	**3.0900e-003**	**1.9600e-003**	**0.0000**	**5.0000e-005**	**1.1000e-004**	**1.6000e-004**	**1.0000e-005**	**1.0000e-004**	**1.1000e-004**	**0.0000**	**0.4275**	**0.4275**	**1.4000e-004**	**0.0000**	**0.4309**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.3 Site Preparation - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.0000e-005	0.0000	6.0000e-005	0.0000	2.0000e-005	0.0000	2.0000e-005	1.0000e-005	0.0000	1.0000e-005	0.0000	0.0157	0.0157	0.0000	0.0000	0.0158
Total	**1.0000e-005**	**0.0000**	**6.0000e-005**	**0.0000**	**2.0000e-005**	**0.0000**	**2.0000e-005**	**1.0000e-005**	**0.0000**	**1.0000e-005**	**0.0000**	**0.0157**	**0.0157**	**0.0000**	**0.0000**	**0.0158**

3.4 Grading - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					4.6200e-003	0.0000	4.6200e-003	2.4900e-003	0.0000	2.4900e-003	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	9.3000e-004	0.0102	5.5500e-003	1.0000e-005		4.2000e-004	4.2000e-004		3.9000e-004	3.9000e-004	0.0000	1.2381	1.2381	4.0000e-004	0.0000	1.2481
Total	**9.3000e-004**	**0.0102**	**5.5500e-003**	**1.0000e-005**	**4.6200e-003**	**4.2000e-004**	**5.0400e-003**	**2.4900e-003**	**3.9000e-004**	**2.8800e-003**	**0.0000**	**1.2381**	**1.2381**	**4.0000e-004**	**0.0000**	**1.2481**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.4 Grading - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	2.0000e-005	2.0000e-005	1.8000e-004	0.0000	6.0000e-005	0.0000	6.0000e-005	2.0000e-005	0.0000	2.0000e-005	0.0000	0.0501	0.0501	0.0000	0.0000	0.0505
Total	**2.0000e-005**	**2.0000e-005**	**1.8000e-004**	**0.0000**	**6.0000e-005**	**0.0000**	**6.0000e-005**	**2.0000e-005**	**0.0000**	**2.0000e-005**	**0.0000**	**0.0501**	**0.0501**	**0.0000**	**0.0000**	**0.0505**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Fugitive Dust					2.0800e-003	0.0000	2.0800e-003	1.1200e-003	0.0000	1.1200e-003	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	9.3000e-004	0.0102	5.5500e-003	1.0000e-005		4.2000e-004	4.2000e-004		3.9000e-004	3.9000e-004	0.0000	1.2381	1.2381	4.0000e-004	0.0000	1.2481
Total	**9.3000e-004**	**0.0102**	**5.5500e-003**	**1.0000e-005**	**2.0800e-003**	**4.2000e-004**	**2.5000e-003**	**1.1200e-003**	**3.9000e-004**	**1.5100e-003**	**0.0000**	**1.2381**	**1.2381**	**4.0000e-004**	**0.0000**	**1.2481**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.4 Grading - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	2.0000e-005	2.0000e-005	1.8000e-004	0.0000	6.0000e-005	0.0000	6.0000e-005	2.0000e-005	0.0000	2.0000e-005	0.0000	0.0501	0.0501	0.0000	0.0000	0.0505
Total	**2.0000e-005**	**2.0000e-005**	**1.8000e-004**	**0.0000**	**6.0000e-005**	**0.0000**	**6.0000e-005**	**2.0000e-005**	**0.0000**	**2.0000e-005**	**0.0000**	**0.0501**	**0.0501**	**0.0000**	**0.0000**	**0.0505**

3.5 Building Construction - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Off-Road	0.0474	0.4814	0.5323	8.6000e-004		0.0240	0.0240		0.0221	0.0221	0.0000	75.1563	75.1563	0.0243	0.0000	75.7640
Total	**0.0474**	**0.4814**	**0.5323**	**8.6000e-004**		**0.0240**	**0.0240**		**0.0221**	**0.0221**	**0.0000**	**75.1563**	**75.1563**	**0.0243**	**0.0000**	**75.7640**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.5 Building Construction - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	4.7000e-004	0.0199	5.8600e-003	9.0000e-005	2.9700e-003	1.3000e-004	3.1000e-003	8.6000e-004	1.2000e-004	9.8000e-004	0.0000	8.6701	8.6701	4.0000e-005	1.3100e-003	9.0618
Worker	8.5000e-003	5.6200e-003	0.0665	2.0000e-004	0.0233	1.1000e-004	0.0234	6.1900e-003	1.1000e-004	6.3000e-003	0.0000	18.3078	18.3078	5.6000e-004	5.3000e-004	18.4784
Total	**8.9700e-003**	**0.0255**	**0.0724**	**2.9000e-004**	**0.0263**	**2.4000e-004**	**0.0265**	**7.0500e-003**	**2.3000e-004**	**7.2800e-003**	**0.0000**	**26.9780**	**26.9780**	**6.0000e-004**	**1.8400e-003**	**27.5402**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Off-Road	0.0474	0.4814	0.5323	8.6000e-004		0.0240	0.0240		0.0221	0.0221	0.0000	75.1562	75.1562	0.0243	0.0000	75.7639
Total	**0.0474**	**0.4814**	**0.5323**	**8.6000e-004**		**0.0240**	**0.0240**		**0.0221**	**0.0221**	**0.0000**	**75.1562**	**75.1562**	**0.0243**	**0.0000**	**75.7639**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.5 Building Construction - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	4.7000e-004	0.0199	5.8600e-003	9.0000e-005	2.9700e-003	1.3000e-004	3.1000e-003	8.6000e-004	1.2000e-004	9.8000e-004	0.0000	8.6701	8.6701	4.0000e-005	1.3100e-003	9.0618
Worker	8.5000e-003	5.6200e-003	0.0665	2.0000e-004	0.0233	1.1000e-004	0.0234	6.1900e-003	1.1000e-004	6.3000e-003	0.0000	18.3078	18.3078	5.6000e-004	5.3000e-004	18.4784
Total	**8.9700e-003**	**0.0255**	**0.0724**	**2.9000e-004**	**0.0263**	**2.4000e-004**	**0.0265**	**7.0500e-003**	**2.3000e-004**	**7.2800e-003**	**0.0000**	**26.9780**	**26.9780**	**6.0000e-004**	**1.8400e-003**	**27.5402**

3.6 Paving - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Off-Road	1.5300e-003	0.0138	0.0176	3.0000e-005		6.6000e-004	6.6000e-004		6.2000e-004	6.2000e-004	0.0000	2.3498	2.3498	6.8000e-004	0.0000	2.3669
Paving	0.0000					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Total	**1.5300e-003**	**0.0138**	**0.0176**	**3.0000e-005**		**6.6000e-004**	**6.6000e-004**		**6.2000e-004**	**6.2000e-004**	**0.0000**	**2.3498**	**2.3498**	**6.8000e-004**	**0.0000**	**2.3669**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.6 Paving - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.3000e-004	9.0000e-005	1.0200e-003	0.0000	3.6000e-004	0.0000	3.6000e-004	1.0000e-004	0.0000	1.0000e-004	0.0000	0.2817	0.2817	1.0000e-005	1.0000e-005	0.2843
Total	**1.3000e-004**	**9.0000e-005**	**1.0200e-003**	**0.0000**	**3.6000e-004**	**0.0000**	**3.6000e-004**	**1.0000e-004**	**0.0000**	**1.0000e-004**	**0.0000**	**0.2817**	**0.2817**	**1.0000e-005**	**1.0000e-005**	**0.2843**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Off-Road	1.5300e-003	0.0138	0.0176	3.0000e-005		6.6000e-004	6.6000e-004		6.2000e-004	6.2000e-004	0.0000	2.3498	2.3498	6.8000e-004	0.0000	2.3669
Paving	0.0000					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Total	**1.5300e-003**	**0.0138**	**0.0176**	**3.0000e-005**		**6.6000e-004**	**6.6000e-004**		**6.2000e-004**	**6.2000e-004**	**0.0000**	**2.3498**	**2.3498**	**6.8000e-004**	**0.0000**	**2.3669**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.6 Paving - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.3000e-004	9.0000e-005	1.0200e-003	0.0000	3.6000e-004	0.0000	3.6000e-004	1.0000e-004	0.0000	1.0000e-004	0.0000	0.2817	0.2817	1.0000e-005	1.0000e-005	0.2843
Total	**1.3000e-004**	**9.0000e-005**	**1.0200e-003**	**0.0000**	**3.6000e-004**	**0.0000**	**3.6000e-004**	**1.0000e-004**	**0.0000**	**1.0000e-004**	**0.0000**	**0.2817**	**0.2817**	**1.0000e-005**	**1.0000e-005**	**0.2843**

3.7 Architectural Coating - 2023

Unmitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Archit. Coating	0.0456					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	9.6000e-004	6.5100e-003	9.0600e-003	1.0000e-005		3.5000e-004	3.5000e-004		3.5000e-004	3.5000e-004	0.0000	1.2766	1.2766	8.0000e-005	0.0000	1.2785
Total	**0.0466**	**6.5100e-003**	**9.0600e-003**	**1.0000e-005**		**3.5000e-004**	**3.5000e-004**		**3.5000e-004**	**3.5000e-004**	**0.0000**	**1.2766**	**1.2766**	**8.0000e-005**	**0.0000**	**1.2785**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.7 Architectural Coating - 2023

Unmitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.2000e-004	8.0000e-005	9.1000e-004	0.0000	3.2000e-004	0.0000	3.2000e-004	8.0000e-005	0.0000	9.0000e-005	0.0000	0.2504	0.2504	1.0000e-005	1.0000e-005	0.2527
Total	**1.2000e-004**	**8.0000e-005**	**9.1000e-004**	**0.0000**	**3.2000e-004**	**0.0000**	**3.2000e-004**	**8.0000e-005**	**0.0000**	**9.0000e-005**	**0.0000**	**0.2504**	**0.2504**	**1.0000e-005**	**1.0000e-005**	**0.2527**

Mitigated Construction On-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Archit. Coating	0.0456					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Off-Road	9.6000e-004	6.5100e-003	9.0600e-003	1.0000e-005		3.5000e-004	3.5000e-004		3.5000e-004	3.5000e-004	0.0000	1.2766	1.2766	8.0000e-005	0.0000	1.2785
Total	**0.0466**	**6.5100e-003**	**9.0600e-003**	**1.0000e-005**		**3.5000e-004**	**3.5000e-004**		**3.5000e-004**	**3.5000e-004**	**0.0000**	**1.2766**	**1.2766**	**8.0000e-005**	**0.0000**	**1.2785**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

3.7 Architectural Coating - 2023

Mitigated Construction Off-Site

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Hauling	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Vendor	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Worker	1.2000e-004	8.0000e-005	9.1000e-004	0.0000	3.2000e-004	0.0000	3.2000e-004	8.0000e-005	0.0000	9.0000e-005	0.0000	0.2504	0.2504	1.0000e-005	1.0000e-005	0.2527
Total	**1.2000e-004**	**8.0000e-005**	**9.1000e-004**	**0.0000**	**3.2000e-004**	**0.0000**	**3.2000e-004**	**8.0000e-005**	**0.0000**	**9.0000e-005**	**0.0000**	**0.2504**	**0.2504**	**1.0000e-005**	**1.0000e-005**	**0.2527**

4.0 Operational Detail - Mobile

4.1 Mitigation Measures Mobile

Increase Density

Improve Destination Accessibility

Increase Transit Accessibility

Improve Pedestrian Network

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Mitigated	0.0327	0.0460	0.2776	6.0000e-004	0.0604	5.0000e-004	0.0609	0.0162	4.7000e-004	0.0166	0.0000	55.8425	55.8425	3.5000e-003	3.1500e-003	56.8673
Unmitigated	0.0377	0.0602	0.3612	8.5000e-004	0.0863	7.0000e-004	0.0870	0.0231	6.5000e-004	0.0237	0.0000	78.8012	78.8012	4.2700e-003	4.1300e-003	80.1373

4.2 Trip Summary Information

	Average Daily Trip Rate			Unmitigated	Mitigated
Land Use	Weekday	Saturday	Sunday	Annual VMT	Annual VMT
Homeless Shelter	79.92	79.92	79.92	231,594	162,115
Total	79.92	79.92	79.92	231,594	162,115

4.3 Trip Type Information

	Miles			Trip %			Trip Purpose %		
Land Use	H-W or C-W	H-S or C-C	H-O or C-NW	H-W or C-W	H-S or C-C	H-O or C-NW	Primary	Diverted	Pass-by
Homeless Shelter	10.80	7.30	7.50	45.60	19.00	35.40	86	11	3

4.4 Fleet Mix

Land Use	LDA	LDT1	LDT2	MDV	LHD1	LHD2	MHD	HHD	OBUS	UBUS	MCY	SBUS	MH
Homeless Shelter	0.536987	0.052416	0.169237	0.150872	0.026159	0.006241	0.012518	0.016886	0.000471	0.000325	0.023246	0.001119	0.003522

5.0 Energy Detail

Historical Energy Use: N

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

5.1 Mitigation Measures Energy

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Electricity Mitigated						0.0000	0.0000		0.0000	0.0000	0.0000	21.3977	21.3977	3.4600e-003	4.2000e-004	21.6093
Electricity Unmitigated						0.0000	0.0000		0.0000	0.0000	0.0000	21.3977	21.3977	3.4600e-003	4.2000e-004	21.6093
NaturalGas Mitigated	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	33.5895	33.5895	6.4000e-004	6.2000e-004	33.7891
NaturalGas Unmitigated	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	33.5895	33.5895	6.4000e-004	6.2000e-004	33.7891

5.2 Energy by Land Use - NaturalGas

Unmitigated

	NaturalGas Use	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Land Use	kBTU/yr	tons/yr										MT/yr					
Homeless Shelter	629444	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	33.5895	33.5895	6.4000e-004	6.2000e-004	33.7891
Total		**3.3900e-003**	**0.0290**	**0.0123**	**1.9000e-004**		**2.3400e-003**	**2.3400e-003**		**2.3400e-003**	**2.3400e-003**	**0.0000**	**33.5895**	**33.5895**	**6.4000e-004**	**6.2000e-004**	**33.7891**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

5.2 Energy by Land Use - NaturalGas

Mitigated

	NaturalGas Use	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Land Use	kBTU/yr	tons/yr										MT/yr					
Homeless Shelter	629444	3.3900e-003	0.0290	0.0123	1.9000e-004		2.3400e-003	2.3400e-003		2.3400e-003	2.3400e-003	0.0000	33.5895	33.5895	6.4000e-004	6.2000e-004	33.7891
Total		**3.3900e-003**	**0.0290**	**0.0123**	**1.9000e-004**		**2.3400e-003**	**2.3400e-003**		**2.3400e-003**	**2.3400e-003**	**0.0000**	**33.5895**	**33.5895**	**6.4000e-004**	**6.2000e-004**	**33.7891**

5.3 Energy by Land Use - Electricity

Unmitigated

	Electricity Use	Total CO2	CH4	N2O	CO2e
Land Use	kWh/yr	MT/yr			
Homeless Shelter	231267	21.3977	3.4600e-003	4.2000e-004	21.6093
Total		**21.3977**	**3.4600e-003**	**4.2000e-004**	**21.6093**

5.3 Energy by Land Use - Electricity

Mitigated

	Electricity Use	Total CO2	CH4	N2O	CO2e
Land Use	kWh/yr	MT/yr			
Homeless Shelter	231267	21.3977	3.4600e-003	4.2000e-004	21.6093
Total		**21.3977**	**3.4600e-003**	**4.2000e-004**	**21.6093**

6.0 Area Detail

6.1 Mitigation Measures Area

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
Category	tons/yr										MT/yr					
Mitigated	0.0778	0.0413	0.4164	2.6000e-004		5.1900e-003	5.1900e-003		5.1900e-003	5.1900e-003	0.0000	43.1880	43.1880	1.4400e-003	7.8000e-004	43.4565
Unmitigated	0.0778	0.0413	0.4164	2.6000e-004		5.1900e-003	5.1900e-003		5.1900e-003	5.1900e-003	0.0000	43.1880	43.1880	1.4400e-003	7.8000e-004	43.4565

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

6.2 Area by SubCategory

Unmitigated

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
SubCategory	tons/yr										MT/yr					
Architectural Coating	4.5600e-003					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Consumer Products	0.0569					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Hearth	4.3000e-003	0.0367	0.0156	2.3000e-004		2.9700e-003	2.9700e-003		2.9700e-003	2.9700e-003	0.0000	42.5331	42.5331	8.2000e-004	7.8000e-004	42.7858
Landscaping	0.0121	4.6200e-003	0.4008	2.0000e-005		2.2200e-003	2.2200e-003		2.2200e-003	2.2200e-003	0.0000	0.6550	0.6550	6.3000e-004	0.0000	0.6707
Total	**0.0778**	**0.0414**	**0.4164**	**2.5000e-004**		**5.1900e-003**	**5.1900e-003**		**5.1900e-003**	**5.1900e-003**	**0.0000**	**43.1880**	**43.1880**	**1.4500e-003**	**7.8000e-004**	**43.4565**

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

6.2 Area by SubCategory

Mitigated

	ROG	NOx	CO	SO2	Fugitive PM10	Exhaust PM10	PM10 Total	Fugitive PM2.5	Exhaust PM2.5	PM2.5 Total	Bio- CO2	NBio- CO2	Total CO2	CH4	N2O	CO2e
SubCategory	tons/yr										MT/yr					
Architectural Coating	4.5600e-003					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Consumer Products	0.0569					0.0000	0.0000		0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
Hearth	4.3000e-003	0.0367	0.0156	2.3000e-004		2.9700e-003	2.9700e-003		2.9700e-003	2.9700e-003	0.0000	42.5331	42.5331	8.2000e-004	7.8000e-004	42.7858
Landscaping	0.0121	4.6200e-003	0.4008	2.0000e-005		2.2200e-003	2.2200e-003		2.2200e-003	2.2200e-003	0.0000	0.6550	0.6550	6.3000e-004	0.0000	0.6707
Total	**0.0778**	**0.0414**	**0.4164**	**2.5000e-004**		**5.1900e-003**	**5.1900e-003**		**5.1900e-003**	**5.1900e-003**	**0.0000**	**43.1880**	**43.1880**	**1.4500e-003**	**7.8000e-004**	**43.4565**

7.0 Water Detail

7.1 Mitigation Measures Water

Apply Water Conservation Strategy

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

	Total CO2	CH4	N2O	CO2e
Category	MT/yr			
Mitigated	2.8767	0.0920	2.2000e-003	5.8346
Unmitigated	3.5959	0.1151	2.7600e-003	7.2932

7.2 Water by Land Use

Unmitigated

	Indoor/Outdoor Use	Total CO2	CH4	N2O	CO2e
Land Use	Mgal	MT/yr			
Homeless Shelter	3.51832 / 2.21807	3.5959	0.1151	2.7600e-003	7.2932
Total		**3.5959**	**0.1151**	**2.7600e-003**	**7.2932**

7.2 Water by Land Use

Mitigated

	Indoor/Outdoor Use	Total CO2	CH4	N2O	CO2e
Land Use	Mgal	MT/yr			
Homeless Shelter	2.81465 / 1.77446	2.8767	0.0920	2.2000e-003	5.8346
Total		**2.8767**	**0.0920**	**2.2000e-003**	**5.8346**

8.0 Waste Detail

8.1 Mitigation Measures Waste

Institute Recycling and Composting Services

Category/Year

	Total CO2	CH4	N2O	CO2e
	MT/yr			
Mitigated	1.2606	0.0745	0.0000	3.1230
Unmitigated	5.0423	0.2980	0.0000	12.4921

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

8.2 Waste by Land Use

Unmitigated

	Waste Disposed	Total CO2	CH4	N2O	CO2e
Land Use	tons	MT/yr			
Homeless Shelter	24.84	5.0423	0.2980	0.0000	12.4921
Total		**5.0423**	**0.2980**	**0.0000**	**12.4921**

Mitigated

	Waste Disposed	Total CO2	CH4	N2O	CO2e
Land Use	tons	MT/yr			
Homeless Shelter	6.21	1.2606	0.0745	0.0000	3.1230
Total		**1.2606**	**0.0745**	**0.0000**	**3.1230**

9.0 Operational Offroad

Equipment Type	Number	Hours/Day	Days/Year	Horse Power	Load Factor	Fuel Type

EMFAC Off-Model Adjustment Factors for Gasoline Light Duty Vehicle to Account for the SAFE Vehicle Rule Not Applied

10.0 Stationary Equipment

Fire Pumps and Emergency Generators

Equipment Type	Number	Hours/Day	Hours/Year	Horse Power	Load Factor	Fuel Type

Boilers

Equipment Type	Number	Heat Input/Day	Heat Input/Year	Boiler Rating	Fuel Type

User Defined Equipment

Equipment Type	Number

11.0 Vegetation

APPENDIX C
PAGE AND TURNBULL, INC. PRIMARY RECORDS

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #_____
HRI #_____
Trinomial_____
NRHP Status Code 3S, 3CS, 5S2
Other Listings_____
Review Code_____ Reviewer_____ Date_____

Resource name(s) or number (assigned by recorder) 435-437 S. San Joaquin Street

P1. Another Identifier: Wills House
***P2. Location:** ☐Not for Publication ☒Unrestricted ***a. County** San Joaquin
***b. USGS 7.5' Quad** Stockton West, CA **Date** 2018
***c. Address** 435-437 S. San Joaquin Street **City** Stockton **Zip** 95203
***e. Other Locational Data:** San Joaquin County Assessor's Parcel Number 149-066-070

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
435-437 S. San Joaquin Street is a two-story, wood-frame multiple-family residence that was built around 1904 in a mixture of Queen Anne and Colonial Revival styles. It is located on a 9,150-square-foot lot on the west side of S. San Joaquin Street between E. Sonora Street and E. Church Street. The building is located on the same parcel as 429-431 S. San Joaquin Street, a second multiple-family residence that was built at the same time in a similar architectural style. The building has a rectangular footprint and a moderately pitched front-gabled roof that is clad with composition shingles. The building is clad with wood lap siding and has a concrete foundation. Typical windows consist of wood sash windows with molded wood trim.

***P3b. Resource Attributes:** (list attributes and codes) HP3. Multiple family property

***P4. Resources Present:** ☒Building ☐Structure ☐Object ☐Site ☐District ☐Element of District ☐Other

P5a. Photo



P5b. Photo: (view and date)
Primary (northeast) façade, view south, October 11, 2019.

***P6. Date Constructed/Age and Sources:** ☒historic
ca. 1904, historic newspaper articles, city directories, Sanborn Map Co. fire insurance maps

***P7. Owner and Address:**
Gospel Center Rescue Mission, Inc.
445 S. San Joaquin St.
Stockton, CA 95203

***P8. Recorded by:**
Page & Turnbull, Inc.
2401 C Street, Ste. B
Sacramento, CA 95816

***P9. Date Recorded:**
October 11, 2019

***P10. Survey Type:**
Intensive

***P11. Report Citation:** None

***Attachments:** ☐None ☐Location Map ☐Sketch Map ☒Continuation Sheet ☒Building, Structure, and Object Record
☐Archaeological Record ☐District Record ☐Linear Feature Record ☐Milling Station Record ☐Rock Art Record
☐Artifact Record ☐Photograph Record ☐ Other (list)



Figure 1. Aerial photograph of 435-437 S. San Joaquin Street. Subject parcel outlined orange. Source: Google Earth 2019, edited by Page & Turnbull.

Northeast Façade
The primary, northeast façade features a projecting front-facing gable that is decorated with alternating carved wood modillions and dentils along the cornice (**Figure 2**). The gable end has a small rectangular window. A full-width porch projects from the first story of the building and has a flat roof with overhanging eaves that are decorated with wood modillions and dentils to match those of the roof above. The roof of the porch is supported by three wood Tuscan columns that are mounted on top of solid wood railings; the railings are clad with wood lap siding that has been covered with a brick veneer wall (**Figure 3**). At the south end of the façade, a set of poured concrete steps lead up to the porch and main entry. The entry consists of a pair of wood panel doors with integrated glazing set behind wood screen doors. A grouped window, consisting of two tall, narrow wood sash windows on each side of a wider wood sash window, completes the fenestration on the first story. On the second story, two wood sash windows frame a door opening that appears to have been filled in with plywood. The wood trim of these windows is more elaborate than those of the first story and has a projecting lintel decorated with dentils.

Southeast Façade
The southeast façade is partially obscured behind an adjacent one-story brick building at 445 S. San Joaquin Street (**Figure 4**). The façade has a molded wood drip course that separates the crawl space from the first floor above. Six windows are visible, three in the first floor and three in the second floor. The four windows at the west end of the façade have been altered; those in the first floor have been covered with plywood, while those in the second floor have been replaced with vinyl sash windows with flat wood trim. Sets of paired windows adjacent to the brick building appear to retain their original wood sashes (**Figure 5**). A small brick chimney is visible on the roof above.

Southwest Facade
The rear (southwest) façade features two stacked recessed entries, one above the other, on the first and second stories at the north end of the facade (**Figure 6**). The first-story entry consists of a wood panel door that is set at the back of a small recessed porch with poured concrete steps and solid wood railings (**Figure 7**). Hinges and an infilled transom indicate that the porch was once enclosed by an additional door. The second-story entry above is located at the top of a long, angled wood staircase with flat wood railings, wood support beams, and one intermediate landing. It contains a wood door with an infilled transom. Fenestration consists of two plywood access doors at the crawl space and a small rectangular wood sash window next to a taller rectangular

window on both the first and second stories. The taller window at the first story has been infilled with plywood and an air conditioning unit, while the bottom sash of both of the second-story windows have been replaced with vinyl sliders. Pipes and utility meters are attached to the south end of the façade. Four cylindrical metal chimneys are visible on the roof above.

Northwest Façade

The northwest façade begins with the northwest walls and supports of the front porch (**Figure 8**). At the main section of the façade, a molded wood drip course divides the crawl space from the first floor. A hinged access door has been cut into the crawl space siding at the east end of the façade, while a second crawl space opening has been covered with wire mesh and partially filled with bricks at the west end. The first and second stories feature identical window configurations. From left to right, they consist of a single wood sash window, followed by paired wood sash windows, and a shorter wood sash window. At the far west end of the façade, four unglazed openings open to the rear, first-story porch, while a set of paired wood sash windows open to the enclosed second-story entry above.



Figure 2. Gable end of northeast facade, view south.



Figure 3. Porch at northeast façade, view southwest.



Figure 4. The southeast façade, view northeast.




Figure 5. Altered windows at the east end of the southeast façade, view northeast.



Figure 6. Southwest façade, view northeast.



Figure 7. Rear porch, view east.



Figure 8. Northwest façade, view southwest.

Site Features

As previously mentioned, the subject building is one of two multiple family residences on the parcel. The second, addressed as 429-431 S. San Joaquin Street, appears to have been constructed at the same time as the subject building and is located directly to the northwest (**Figure 9**). The narrow space between the two buildings has been paved with concrete (**Figure 10**). Landscaping in front of the building consists of a small front yard with a lawn and small concrete patio that is enclosed by a tall metal fence along the front and northwest property lines (**Figure 11**). A concrete walkway extends from the sidewalk to the building's front entrance, and a narrow strip of brick pavers leads to a second concrete walkway that separates the subject building from the adjacent building on the lot. The rear portion of the lot is also paved with concrete, except for a small space immediately to the rear of 429-431 S. San Joaquin Street, in which trees have been planted. An outdoor seating area with wood picnic tables and a wood lattice covering is located at the southwest corner of the lot. The rest of the rear portion of the lot is used as a driveway and parking lot for the complex (**Figure 12**).



Figure 9. The subject property (left) and 429-431 S. San Joaquin Street, view northeast.



Figure 10. Concrete walkway between the subject property and 435-437 S. San Joaquin Street, view west.



Figure 11. Front yard, view north.



Figure 12. Paved area at the rear of the building, view northeast.

Surrounding Site Context

435-437 S. San Joaquin Street is located on the block bounded by S. San Joaquin Street to the northeast, E. Church Street to the southeast, S. Hunter Street to the southwest, and E. Sonora Street to the northwest in the heart of the original street grid of Stockton and one-and-one-half blocks south of the California State Route 4 highway. The surrounding area is characterized primarily by a mix of two- to three-story residential buildings and a few brick commercial buildings that appear to have been built around the turn of the twentieth century. 429-431 S. San Joaquin Street was constructed in the same style as the subject property around 1904 (**Figure 13**). The Gleason House, located directly to the northwest of the subject parcel at 423 S. San Joaquin Street, is a Queen Anne style house constructed in 1895 (**Figure 14**). 420 S. San Joaquin Street, directly across from the subject property, is a two-story, Queen Anne style house built in 1905 (**Figure 15**). Next door, 430 S. San Joaquin is a two-story vernacular style foursquare that was built in 1900 (**Figure 16**).



Figure 13. 435-437 S. San Joaquin Street, built 1904.



Figure 14. The Gleason House at 423 S. San Joaquin Street, built 1895.



Figure 15. 420 S. San Joaquin Street, built 1905.



Figure 16. 430 S. San Joaquin Street, built 1900.

BUILDING, STRUCTURE, AND OBJECT RECORD

***NRHP Status Code** 3S, 3CS, 5S2
***Resource Name or #** 435-437 S. San Joaquin Street

B1. Historic name: Wills House
B2. Common name: 435-437 S. San Joaquin Street
B3. Original Use: Multiple Family Residence
B4. Present use: Multiple Family Residence
***B5. Architectural Style:** Queen Anne/Colonial Revival
***B6. Construction History:** (Construction date, alterations, and date of alterations)

The parcel on which 435-437 S. San Joaquin Street is located was owned by Bee Hoult by 1900. Two earlier wood frame buildings that were present on the site at the time burned down in a fire that spread from the Agricultural Pavilion building, located two blocks north on Lafeyette Street between S. Hunter, and destroyed nearly six city blocks in September 1902.[1] The 1904 Stockton city directory records that Hoult's husband, David, was living at the adjacent building at 431 S. San Joaquin Street, indicating it had been completed by this time to replace the buildings that had been destroyed by the fire.[2] It is likely that the subject building was constructed at the same time. The 1917 fire insurance map by the Sanborn Map Company shows the building as a two-story wood frame building that consisted of two flats over a basement (**Figure 17**). It had a two-story porch that spanned the front façade and an angled exterior rear staircase. The 1950 Sanborn fire insurance map shows that by 1950, the building had been reconfigured into a two-and-one-half-story building, likely by converting the basement into livable space. No other changes are visible. (**Figure 18**). Aerial photographs from the 1930s and 1970s indicate that the overall footprint of the building has remained relatively unchanged over time (**Figure 19** and **Figure 20**). (See Continuation Sheet, page 8)

***B7. Moved?** ☒**No** ☐**Yes** ☐**Unknown Date:** N/A **Original Location:** N/A
***B8. Related Features:** _____ B9a. Architect: Unknown b. Builder: Unknown


***B10. Significance: Theme** Residential Architecture **Area** Stockton, California
Period of Significance 1904 **Property Type** Multiple-Family Residential **Applicable Criteria** C/3

City of Stockton
Native American through Early American Period:
Numerous Native American groups called the Central Valley home for thousands of years before the arrival of European and American settlers. The Stockton area was settled by the Yatchicumne, a group of the Northern Valley Yokuts people whose villages were established across a vast expanse of California from the confluence of the Sacramento and San Joaquin rivers as far as the Tehachapi Mountains, 250 miles to the south. At least two Yatchicumne villages were located in the Stockton area, including one called Pasasimas, situated on a mound near the Stockton Channel in present-day Downtown Stockton. (See Continuation Sheet, page 9)

B11. Additional Resource Attributes: (List attributes and codes)

***B12. References:** See Footnotes and Continuation Sheet, page 18
B13. Remarks: None
***B14. Evaluator:** Clare Flynn, Page & Turnbull, Inc.
***Date of Evaluation:** October 31, 2019

(This space reserved for official comments.)



Location Map: San Joaquin County Assessor's Office, 2019. Subject parcel shaded orange. Edited by Page & Turnbull.

[1] "Conflagration in the Heart of Stockton Leaves Record of Death and Injury, and Devastation of Wide Area," *The San Francisco Call*, September 30, 1902.
[2] Stockton, California, City Directory, 1904.

***B6. Construction History: (continued)**




Figure 17. Excerpt from 1917 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.




Figure 18. Excerpt from 1950 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.



Figure 19. 1930 aerial photograph, approximate subject location outlined in orange. Source: Fairchild Aerial Surveys, Flight C-975A, Frame Z-252, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 20. 1970 aerial photograph, approximate subject location outlined in orange. Source: Cartwright Aerial Surveys, Flight CAS-2874, Frame 102, collection of UC Santa Barbara Library. Edited by Page & Turnbull.

Google Street View images show that there was a balcony above the front porch in 2012. Sometime between 2012 and 2015, a railing around this balcony was removed, and a door opening that led from the second story interior to the balcony was infilled. Building permits on file at the City of Stockton Permit Center document repairs to the building's foundation and plumbing and electrical work. Additional alterations that are not documented in permits include window replacements, the addition of brick veneer cladding on the northwest façade, removal of the second-story balcony railing, and alterations to the rear porch.




Figure 21. The northwest facade in April 2012. Source: Google Street View, 2012.

Table 1. Permits on File at the City of Fremont Community Development Department

Permit Number	Date	Applicant	Description
31996	12/1949	Ila Stevenson	Foundation for apartment house
9599	6/9/1959	Illegible	Plumbing
66400	1/12/1987	Robert Hong	Electrical

***B10. Significance: (continued)**

Local rivers and streams provided an abundant source of food for the native population and also attracted European and American fur trappers to the area, who began exploring the area in the early nineteenth century in search of beaver and otter pelts.[3] These early explorers included Jedediah Strong Smith, who established a base camp to the southeast of present-day Stockton in 1827, and Alex McCleod, a fur trapper from the Hudson's Bay Company, whose camp near McCleod Lake gave the lake its name.[4] While the fur trappers reaped the benefits of the region's rich natural resources, they also brought diseases with them that led to the decimation of much of the local Native American population.[5]

The presence of French-Canadian fur trappers provided the inspiration for the name of the Mexican land grant that encompassed the present-day site of Stockton and its immediate vicinity during the Mexican period, after Mexico achieved independence from Spain in 1821. Rancho Campo de los Franceses, as the grant was known, was filled with numerous waterways, grassy hills, and oak trees. It was this landscape that German immigrant Captain Charles Maria Weber, founder of the city of Stockton, experienced when he traveled through the area on his way to San Jose in 1842.[6] Recognizing the area's potential, Weber and his business partner, Guillermo (William) Gulnac, acquired roughly 55 square kilometers of Rancho Campo de los Franceses on the east side of the San Joaquin River from the Mexican governor in 1843. Weber eventually bought Gulnac out of the land and built his first

[3] City of Stockton, "History: A Look into Stockton's Past," accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html; Lori Gilbert, "Our Diversity: Native Americans first to call Stockton home," *The Record*, November 29, 2014, accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.
[4] R. Coke Wood, "The Rise of Stockton," *San Joaquin Historian* IX, no. 1 (January-March 1973), San Joaquin County Historical Society, 2.
[5] Architectural Resources Group, Stockton Downtown Draft Historic Resources Survey, 2000, 6.
[6] Wood, 2.

structures on the site in 1847.[7] The first survey of the settlement, initially known as Tuleberg, was completed by Jasper O'Farrell the same year.[8]

Formation of Stockton

Like many cities in Northern California, Stockton grew from a small, rural outpost into a booming city as a result of the Gold Rush. When gold was discovered at Coloma in 1848, one year after Weber established the settlement of Tuleberg, he initially joined the fervor and spent months mining in the goldfields. He soon realized, however, that he had a better chance of making his fortune by selling goods and supplies to the floods of miners who were traveling into the area.[9] Advantageously located at the head of the Stockton Channel, a tributary of the San Joaquin River, Weber's settlement emerged as the gateway to and major supply center for California's southern mining areas as ships traveling from San Francisco brought streams of miners to the area (Error! Reference source not found.).[10]

As the settlement's population grew, so did urban development. In 1849, Major R. P. Hammond completed a second survey that laid out the first street grid between Weber Avenue, Center Street, Main Street, and Commerce Street.[11] In 1850, the same year the California achieved statehood, the settlement was officially incorporated as a city and renamed Stockton, after Commodore Robert F. Stockton, the American Navy officer who drove the last Mexican forces out of California in 1848.[12] Over the next five years, the city's population swelled from 1,000 to roughly 7,000. By the 1890s, it had exploded to approximately 23,000 residents.[13]

The streets between El Dorado Avenue, Main Street, Commerce Street, and Levee (now Weber) Avenue formed the core of the city's commercial area in the nineteenth century. The first residential districts, meanwhile, developed to the southwest and north. Floods were common in the winter months due to the city's location near miles of waterways that made up the Sacramento-San Joaquin River Delta.[14]

After the Gold Rush ended in the mid-1850s, the Central Valley's rich soil and temperate climate contributed to the development of Stockton into a major center for agricultural industries. Wheat and grains were the area's largest crop in the nineteenth century and spurred the construction of grain warehousing facilities and flour mills in the area, including the Sperry Flour Company. By the early twentieth century, fruit orchards, nuts, vegetables, potatoes, and other crops were also grown on the farms around the city.[15] Surrounded by this abundance of agricultural wealth, the city's economy developed around businesses that processed, cultivated, and transported agricultural goods. Several of Stockton's most prominent businesses, including Matteson & Williamson and Holt Brothers Manufacturing Company, made names for themselves as the manufacturers of agricultural tools and equipment that increased the productivity of the area's farms.

Stockton's location along a variety of important transportation corridors—including the Stockton Channel, with its deep water shipping access, and the Central Pacific Railroad—contributed to Stockton's industrial development and emergence as a regional transportation hub.[16] Shipyards, iron foundries, warehouses, and factories were established along the channel and its tributaries.[17]

Burgeoning with economic activity and a growing population, Stockton experienced a building boom from the 1880s until the 1930s, during which the majority of buildings in the city's downtown and nearby residential areas were constructed. In the late nineteenth century, many of the city's downtown commercial buildings were constructed of locally produced red brick, inspiring one of the Stockton's nicknames, "The Brick City."[18] Five high rises were constructed between 1910 and 1917 alone.[19] Two- and three-story masonry residential hotels were also constructed during this period in order to provide affordable, temporary housing for the large population of migrant laborers who worked on the surrounding farms. These residential hotels, many of which had commercial retail spaces on the first floor and exhibited Classical architectural detailing, became a common building type in downtown Stockton as a result.[20] The downtown area was also home to the largest Chinatown in California, as many Chinese families relocated from San Francisco after the 1906 earthquake.[21]

[7] Idem.
[8] Idem.
[9] Idem.
[10] Architectural Resources Group, 7.
[11] Architectural Resources Group, 7.
[12] Ibid., 6.
[13] Ibid., 7-8.
[14] Daniel Kasser, *Downtown Stockton* (San Francisco: Arcadia Publishing, 2005), 15.
[15] Architectural Resources Group, 13-14.
[16] Ibid., 17.
[17] "A Historical Study of Stockton, California," Visit Stockton, accessed June 19, 2019, https://www.visitstockton.org/about-us/stockton-history/.
[18] Architectural Resources Group, 12.
[19] Ibid., 16.
[20] Ibid., 9.
[21] Ibid., 8.

Other immigrant groups, in addition to the Chinese, made up a large portion of Stockton's population. After the passage of the Chinese Exclusion Act in 1882, Filipino, Japanese, and Sikh immigrants gradually replaced the Chinese as the main labor force in the city's packing houses, farms, and domestic industries. By the 1920s, Filipino men and women made up the majority of Stockton's agricultural labor force, giving the city the nickname, the "Manila of California."[22] From the late nineteenth century to the 1920s, Italians also arrived in Stockton in large numbers, during a wave of migration that took place after the unification of Italy around 1861.[23]

Construction during the late nineteenth and early twentieth centuries also included civic and institutional establishments. A San Joaquin County Courthouse was completed on a public square a short distance from the channel in 1854 and was replaced in 1890. In 1924, the University of the Pacific relocated from San Jose to Stockton, bringing one of the city's most influential and long-standing establishments to the city.[24]
Infrastructural improvements further enhanced Stockton's continuing development. Electric trolleys began service in the last decades of the nineteenth century. As the automobile became increasingly popular and affordable at the start of the twentieth century, an auto row developed at El Dorado Street and Miner Avenue.[25] In 1911, a new diverting channel was completed to address issues with frequent flooding.[26]

Stockton's varied economy, based on the agricultural industry and other industries centered around the shipping channel, helped soften the impact of the Great Depression. Starting in 1927, work to expand and deepen Stockton Channel provided employment for hundreds of workers. The new Port of Stockton opened in 1933 as the largest inland port in California at the time. Opportunities for work in the region's surrounding farms, meanwhile, attracted families from the Midwest and large populations of immigrant workers to the area.

World War II to the Present
The outbreak of World War II and the resulting demand for war-related goods stimulated Stockton's local industries. Shipbuilding, based at the city's many shipyards, became the largest source of employment, while the opening of an Army Air Force base at Old Stockton Field and the Stockton Naval Supply depot created new job opportunities. The war also created an agricultural labor shortage. Mexican workers, sponsored by the federal Bracero Program, filled the void and became part of the city's rich multicultural makeup.[27]

The postwar period reshaped the city. Stockton struggled to maintain its status as a major shipping center because the Stockton Channel was not large or deep enough to accommodate the increasing size of shipping vessels. In response, the local economy began to shift toward warehousing and the production of farming machinery and commercial boats. The completion of new residential neighborhoods, shopping malls, and of the Crosstown and Interstate 5 freeways, as well as the migration of affluent residents outside of the city center, diverted economic and commercial activity away from Stockton's historic downtown core. By the 1950s, the area was considered blighted. In the 1960s, the area became the target of urban renewal efforts, which resulted in the demolition of all but three buildings on nine square blocks of downtown. Longstanding residents, many of whom were of Chinese or Filipino descent, were displaced during the redevelopment.[28]

In the 1980s, Stockton's downtown began to experience a resurgence of development. Activity around the canal refocused around recreation-related uses and building projects. Boats plied its waters, and restaurants, a shopping mall, and housing developments were constructed along the waterfront.[29]

In the 2010s, agriculture remains important to the city's economy. Asparagus, cherries, tomatoes, walnuts, and almonds have replaced wheat and grain as the area's major crops. In spite of the changes that have taken place over time, Stockton continues to be characterized by its agricultural industry, the Stockton Channel, its history of brick buildings downtown, and a diverse, multi-cultural population.[30]

The Queen Anne Style: Free Classic Subtype
The Queen Anne style was a popular architectural style among the elite during the Victorian era of the late nineteenth century. First

[22] Architectural Resource Group, 9-10, 21.
[23] Pacific Italian Alliance and Ralph A. Clark, *Italians of San Joaquin County* (Charleston, SC: Arcadia Publishing, 2014), 7.
[24] "A Historical Study of Stockton, California."
[25] Ibid., 8-9
[26] "A Historical Study of Stockton, California."
[27] Ibid., 10.
[28] Ibid., 11.
[29] Ibid., 11.
[30] "History: A Look Into Stockton's Past."

used in England, this style referred back to the reign of Queen Anne (1702-1714) when craftsmanship and simplicity of construction were emphasized in the architectural vernacular.[31] One of the main innovators and architects of this style was Richard Norman Shaw, who popularized the Queen Anne style in England with his half-timbered designs that borrowed from late Medieval buildings from the Elizabethan and Jacobean periods. American architects introduced this style into the mainstream during the late 1870s and soon added subtypes of the style with spindlework and classical architectural elements. By the 1880s, the Queen Anne style had become the leading architectural style for the Victorian elite and upper to middle classes.

The Queen Anne style is characterized by its variety of features and combination of ornamentation. Typical features of the Queen Anne style include steeply pitched roofs, irregular rooflines, gable projections, cutaway bay windows, asymmetrical compositions, and swag and garland appliqués.[32] The result of this fusion of ornamentation and composition was a highly textured and varied residence, which achieved the elegance and grace desired by the people of this era. Commonly, other architectural styles, such as Eastlake and Stick, were combined with the Queen Anne style to produce asymmetrical and varied compositions.

Approximately 35 percent of Queen Anne houses are considered to be a subtype of the style called Free Classic. The style became common after 1890, with a peak from 1900 until 1910, and shares some features with early Colonial Revival houses, which became the dominant architectural style in the years afterward. The Free Classic subtype is characterized by its use of classical columns that are typically grouped together in units of two or three. Other classical features – such as cornice-line dentils, swags, garlands, or Palladian windows – are also common.[33]

Owner and Occupant History

The sequence of owners and occupants of the subject property, developed from records maintained at the San Joaquin Recorder-County Clerk's offices, historic city directories, census records, and historical newspaper articles is summarized in Table 2. Brief biographies of long-term or notable owners and occupants follow the table.

Table 2. Owners and Occupants of 435-437 S. San Joaquin Street, Stockton

Year(s)	Owner[34]	Occupant[35]
ca. 1900-1949	Bee Hoult	435 S. San Joaquin Street 1910 – Frank H. Bileski, dry goods merchant 1915 – William R. Holmes, bartender 1920 – Harry A. Smith, mechanic 1930-1940 – Bee Hoult 1945 - Lee C. Preston, shoe repairer 437 S. San Joaquin Street 1910 – Emma R. Small 1915-1920 – Thomas A. King, cigars 1925 – Vacant 1930 – Valerie Brown 1935-1940 – Emma R. Small 1945 - Joseph Smith, driver
1949	Bee Hoult Estate c/o Bob Stevenson	
1949-1960	Ila H. Stevenson	435 S. San Joaquin Street 1950 – Clyde H. Dunsing, engineer NSD 1955-1960 - Thomas Iriarte, welder 437 S. San Joaquin Street 1950 – Joseph Smith, driver 1955 - Julia J. George, saleswoman for Smith & Lang 1960 – Mary Leyva
1960-1972	S.L. Fong Lum Bow Yum Fong	435 S. San Joaquin Street 1965 - Vacant 1970-1975 – Abdul S. Ahmad, retired 435a S. San Joaquin Street

[31] Lester Walker, *American Shelter* (New York: The Overlook Press, Inc., 1997), 152.
[32] Virginia Savage McAlester, *A Field Guide to American Houses* (New York: Alfred A. Knopf, 2014), 345-347.
[33] Idem.
[34] Information from San Joaquin County Recorder-County Clerk.
[35] Information from United States Census and city directories, Ancestry.com. Directory listings do not include occupations for all residents.

Year(s)	Owner[34]	Occupant[35]
		1965 – Vacant 437 S. San Joaquin Street 1965 – Vacant 1970 – Janet Hood
1972-1977	Elizabeth Fong Wills John Fong	435 S. San Joaquin Street 1970-1975 – Abdul S. Ahmad, retired 435b S. San Joaquin Street 1975 – Leopoldo Laue, farm worker 437 S. San Joaquin Street 1975 – Alla and Dee Stewart, retired
1977-1985	Elizabeth Fong Wills John Fong Christopher James Robertson Wills Elizabeth Mei Sit Fong Wills	435 S. San Joaquin Street 1980 – Abdott Ahmed 1985 – Jenny Davis, retired 437 S. San Joaquin Street 1980 – Fletcher and Sylvia Turner 1985 – James Turner, retired
1985-1989	Robert W. Hong Mee Yoke Hong Haye B. Chan Conde T. Chan Bak F. Hong Judith Hong Michael Attanasio Noreen E. Chan	435 S. San Joaquin Street 1986 – Jenny Davis, retired 437 S. San Joaquin Street 1986 – James Turner, retired
1989-2003	Gospel Center	435-437 S. San Joaquin Street 1989-2003 - Gospel Center (Annex)
2003-2019	Gospel Center Rescue Mission, Inc.	435-437 S. San Joaquin Street 2003-2019 - Gospel Center Rescue Mission, Inc.

The Hoult Family, Owners and Occupants, ca. 1900-1949

As previously mentioned, the subject building appears to have been originally owned and constructed for Bee Hoult and her family around 1904, after a fire destroyed earlier buildings on the lot. Born Bee Delia O'Brien in Ireland around 1861, Bee immigrated to the United States in 1883. In 1887, she married David James Hoult, a foreman of Houser & Haines Manufacturing Co.[36] The couple had one child, a son named Urban.[37] The family lived together at the adjacent house on the lot at 431 S. San Joaquin Street in 1910 through at least 1915.[38] As an adult, Urban worked for the firm of Radcliffe & Hoult, publishers of the *Mercury Sun* newspaper in Merced. He died of pneumonia in 1924 at the age of 35. David died just four years later at the age of 65.[39] Bee continued to own the subject property after their deaths and moved to the subject building at 435 S. San Joaquin Street until her own death sometime around 1949, after which the property passed to her niece, Ila H. Stevenson. Research did not uncover any additional information about the life or contributions of Bee, David, or Urban Hoult. City directories do not list Stevenson as a resident of the subject property.

Gospel Center Rescue Mission, Inc., Owner, 1989-2019

Gospel Center Rescue Mission (GCRM) is a faith-based non-profit that serves the homeless and addicted of San Joaquin County. The non-profit was founded in 1940 in Ripon, California out of a concern for the post-Depression era homeless population. Over time, GCRM added programs to provide food, shelter, clothing, addiction treatment, and medical care to the homeless.[40] Today, the agency serves over 1,000 men, women, and children at its Stockton campus each day and offers eight programs, including the only Homeless Recuperative Care Program and non-profit payee service in San Joaquin County.[41]

Significance Evaluation: National Register of Historic Places and California Register of Historical Resources

The subject property at 435-437 S. San Joaquin Street is not currently listed in the National Register of Historic Places (National Register) or the California Register of Historical Resources (California Register). The building is included in the California Historical

[36] San Joaquin County Clerk-Recorder
[37] 1900 United States Federal Census, Ancestry.com.
[38] 1910 United States Federal Census, Ancestry.com; Stockton City Directory, 1915.
[39] California, County Birth and Death Records, 1800-1994, FamilySearch.org.
[40] "Our Mission," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us/Mission-History.
[41] "Wayne G. Richardson," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us.

Resources Information System (CHRIS) as of 2012 with the status code, "5S2," indicating that the property has been identified as an "Individual property that is eligible for local listing or designation."

In order for a property to be eligible for listing in the National Register, it must be found significant under one or more of the following criteria:

Criterion A (Event): Properties associated with events that have made a significant contribution to the broad patterns of our history.

Criterion B (Person): Properties associated with the lives of persons significant in our past.

Criterion C (Design/Construction): Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction.

Criterion D (Information Potential): Properties that have yielded, or may be likely to yield, information important in prehistory or history.

In order for a property to be eligible for listing in the California Register, it must be found significant under one or more of the following criteria:

Criterion 1 (Events): Resources that are associated with events that have made a significant contribution to the broad patterns of local or regional history, or the cultural heritage of California.

Criterion 2 (Persons): Resources that are associated with the lives of persons important to California history.

Criterion 3 (Architecture): Resources that embody the distinctive characteristics of a type, period, region, or method of construction, or represent the work of a master, or possess high artistic values.

Criterion 4 (Information Potential): Resources or sites that have yielded or have the potential to yield information important to the prehistory or history of California.

The following section examines the eligibility of the building at 435-437 S. San Joaquin Street for *individual* listing in the National Register or California Register.

Criterion A/1 (Events)
The subject property does not appear to be eligible for individual listing under Criterion A/1 for association with events that have made a significant contribution to the broad patterns of local, state, or national history. The multi-family house was constructed around 1904, more than fifty years after Stockton was incorporated in 1850, and, thus, it is not significant for being one of the first or earliest residential buildings constructed in the city. Rather, it was constructed at a time when Stockton was experiencing a building boom that lasted from the 1880s until the 1930s. This building boom, however, is most closely associated with commercial and institutional development in Stockton's urban core and the city's emergence as a transportation hub and center for agricultural industries. Although residential development occurred during the same period, the subject building is not an exceptional example of a residential building constructed during the period and does not appear to have had an impact on the development of the surrounding area. Therefore, the building is not considered to be a notable representative of Stockton's development in the early twentieth century and does not appear to rise to the level of significance necessary to be individually eligible for listing on the California Register or National Register under Criterion A/1.

Criterion B/2 (Persons)
The subject property does not appear eligible for individual listing under Criterion B/2 for association with the lives of persons important to local, state, or national history. Bee Delia Hoult owned the property from at least 1900 until 1949, and the subject building appears to have been constructed for Hoult and her family around 1904 after a fire in 1902 destroyed earlier buildings on the site. Hoult appears to have lived in the subject building after the deaths of her husband and son from approximately 1920 until her death around 1949. Research did not reveal information about Bee Hoult's occupation or shed any further light on the activities or contributions of the Hoult family to Stockton or the surrounding area. From 1960 to 1985, the building was owned by a number of individuals that appear to have been associated with the Fong family. City directories do not list these owners as residents of the building or of Stockton, and research did not uncover the occupations or activities of these individuals necessary to evaluate their contributions to history. As a multi-family residence, a large number of people have lived at the subject building over time. Throughout its history, residents appear to have primarily been working class individuals employed in a number of industries.

Through the 1960s, city directories list a blacksmith, welder, mechanic, bartender, dry goods merchant, driver, shoe repairer, and saleswoman as residents of the house. Starting in the 1970s, residents were primarily farm workers and retired individuals. Research did not indicate that any of these individuals gained notable importance within their professions. Therefore, none of the owners or occupants that were identified during research for this report appear to have made significant contributions to local, state, or national history in a manner that rises to the level of significance necessary to merit designation under Criterion 2.

Criterion C/3 (Architecture)
The subject property does appear eligible under Criterion C/3 as a resource that embodies the distinctive characteristics of a multi-family house built in the Queen Anne style. More specifically, the house is an example of the Free Classic subtype of Queen Anne style houses. The building was originally constructed around 1904, during the peak period of popularity of Free Classic Queen Anne houses in the United States; however, a scan of the area surrounding the subject building suggests that this style was relatively uncommon in Stockton or that few examples survive in the city today. The subject building exhibits many of the defining characteristics of the style, including a dominant front-gabled roof and full-width front porch, that are representative of the broader Queen Anne style, as well as the use of Tuscan columns as porch supports and cornice-line carved wood modillions and dentils that are indicative of the Free Classic subtype. The building also has surviving original window trim and doors with decorative carved dentils. The subject property, therefore, appears to be significant under Criterion C/3.

The property's period of significance under Criterion C/3 is 1904, when the building was originally constructed.

Criterion D/4 (Information Potential)
The subject property does not appear to be individually eligible under Criterion D/4 as a building that has the potential to provide information important to the prehistory or history of the City of Fremont, state, or nation. It does not appear to feature construction or material types, or embody engineering practices that would, with additional study, provide important information. Page & Turnbull's evaluation of this property was limited to age-eligible resources above ground and did not involve survey or evaluation of the subject property for the purposes of archaeological information.

Evaluation (Integrity)
In order to qualify for listing in any local, state, or national historic register, a property or landscape must possess significance under at least one evaluative criterion as described above and retain integrity. Integrity is defined by the California Office of Historic Preservation as "the authenticity of an historical resource's physical identity evidenced by the survival of characteristics that existed during the resource's period of significance," or more simply defined by the National Park Service as "the ability of a property to convey its significance."[42] Established integrity standards are outlined by the *National Register Bulletin: How to Apply the National Register Criteria for Evaluation*. Seven variables, or aspects, that define integrity are used to evaluate a resource's integrity: location, setting, design, materials, workmanship, feeling, and association. A property must retain integrity under most or all of these aspects in order to retain overall integrity. If a property does not retain integrity, it can no longer convey its significance and is therefore not eligible for listing in local, state, or national registers.

1. *Location* is the place where the historic property was constructed.
2. *Design* is the combination of elements that create the form, plans, space, structure and style of the property.
3. *Setting* addresses the physical environment of the historic property inclusive of the landscape and spatial relationships of the building(s).
4. *Materials* refer to the physical elements that were combined or deposited during a particular period of time and in a particular pattern of configuration to form the historic property.
5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history.
6. *Feeling* is the property's expression of the aesthetic or historic sense of a particular period of time.
7. *Association* is the direct link between an important historic event or person and a historic property.

435-437 S. San Joaquin Street retains all seven of the aspects of integrity. The building has not been moved since its construction and, thus, retains integrity of location. Although the surrounding area has changed over time, a number of single- and multi-family houses and commercial buildings also dating to the late nineteenth and early twentieth centuries remain at their original locations directly next to or across from the subject property on S. San Joaquin Boulevard. As a result, the subject property retains its integrity of setting. Although the second-story balcony has been altered and brick veneer cladding has been added to the front façade and alterations to windows on the side and rear facades are evident, the building's essential exterior features and materials that convey its significance as a multi-family house constructed in the Free Classic subtype of the Queen Anne style – including prominent front gable with cornice line modillions and dentils, full-width front porch, Tuscan column porch supports, original wood

[42] California Office of Historic Preservation, *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources* (Sacramento: California Office of State Publishing, 4 September 2001), 11; U.S. Department of the Interior, National Park Service, *National Register Bulletin: How to Apply the National Register Criteria for Evaluation* (Washington, D.C.: National Park Service, 1995), 44.

windows and doors, and wood lap siding – remain intact. Integrity of design, materials, workmanship, feeling, and association have also been retained.

Based on this analysis, 435-437 S. San Joaquin Street retains sufficient integrity to convey its significance under Criterion 3/C and, therefore qualifies for listing on the National and California Registers.

Character-Defining Features
For a property to be eligible for national, state, or local designation, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. To be eligible, a property must clearly contain enough of those characteristics, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials. The character-defining features of 435-437 S. San Joaquin Street include:

- Projecting front-facing gabled roof
- Cornice with wood modillions and dentils
- Full-width front porch with Tuscan column supports mounted on solid wood railing
- Wood lap siding
- Wood panel doors and sash windows with molded wood trim, some with decorative carved dentils
- Entries to multiple units at front and rear façades

Significance Evaluation: City of Stockton Landmark, Historic Site, or Structure of Merit
The subject building is not included in the Downtown Stockton Historic Resources Survey (2000) and is not located within a local historic district or zoning overlay or listed as a City of Stockton Landmark, Historic Site, or Structure of Merit. It is therefore not currently listed locally as a historic resource.

Landmarks
According to the Stockton Municipal Code Section 16.220.070, "In considering an artifact, natural feature, or structure for designation as a Landmark, the Board shall apply any or all of the following criteria:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Architectural Craftsmanship**. Its embodiment of elements demonstrating outstanding attention to architectural and/or engineering craftsmanship, design, detail, or materials;
3. **Architectural Style.** Its exemplification of a particular architectural style or way of life important to the City, the State, or the Nation;
4. **Architectural Type.** Its exemplification of the best remaining architectural type in the City;
5. **Historic Event.** Its location as a site of a significant historic event;
6. **Heritage.** Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
7. **Visual Feature.** Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
8. **Relationship to Another Landmark.** Its relationship to any other landmark, if its preservation is essential to the integrity of that landmark;
9. **Significant Person.** Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation;
10. **Work of a Significant Person.** Its identification as the creation, design, or work of a person(s) whose effort has significantly influenced the heritage of the City, the State, or the Nation; or
11. **Natural Environment.** Its integrity as a natural environment that strongly contributes to the well-being of the people of the City, the State, or the Nation."[43]

Historic Sites & Structures of Merit
Historic Sites and Structures of Merit are designated by the same criteria. According to the Stockton Municipal Code Sections 16.220.090 and 16.220.100, the criteria for designating Historic Sites and Structures of Merit are the following:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Heritage**. Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
3. **Visual Feature of the City**. Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
4. **Way of Life.** Its exemplification of a particular way of life important to the City, the State, or the Nation;

[43] Stockton Municipal Code: 16.220.070, "Landmarks," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_070&frames=on.

5. **Historic Event.** Its location as a site of a significant historic event regardless of its current configuration, development, or use;
6. **Significant Person**. Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation; or
7. **Significant Person of a Specific National Origin.** Its identification with a person(s) representative of a specific national origin who have contributed to the culture and development of the City, the State, or the Nation."[44]

As evidenced in the previous evaluation, 435-437 S. San Joaquin Street appears to be significant at the local level under Criterion C/3 of the National Register and California Register and possesses sufficient integrity to be eligible for listing. The City of Stockton's criteria for the designation of Landmarks, Historic Sites, and Structures of Merit correspond approximately with those of the National Register and California Register; however, they do not appear to include an integrity requirement. In particular, criteria 2, 3, and 4 above for listing as a City of Stockton Landmark appear to correspond with Criterion C/3 of the National Register and California Register. Thus, the above evaluation for National Register and California Register Criteria C/3 can be extended to local designation under the corresponding criteria for listing as a City of Stockton Landmark, and the property appears to merit local designation as a City Landmark.

Conclusion
435-437 S. San Joaquin Street does appear to be eligible for individual listing in the National Register under Criterion C, the California Register under Criterion 3, and as a City of Stockton Landmark under Criteria 2, 3, and 4. The subject building was constructed in 1904 and embodies the distinctive characteristics that are representative of a multi-family house that was built in the Free Classic Queen Anne style. As such, the California Historical Resource Status Codes (CHRSC) of "3S," "3CS," and "5S2" have been assigned to the property, meaning that it has been found eligible for the National Register and California Register as an individual property through survey evaluation.[45]

[44] Stockton Municipal Code: 16.220.090, "Historic sites," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_090&frames=on; Stockton Municipal Code: 16.220.100, "Structures of merit," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_100&frames=on.
[45] California State Office of Historic Preservation Department of Parks and Recreation, *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory,* Sacramento, November 2004.

***B12. References:**

Publications

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume I*. 2000.

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume II*. 2000.

California Office of Historic Preservation. *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources,* Sacramento: California Department of Parks and Recreation, 2001.
———. *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory*. Sacramento: California Department of Parks and Recreation, 2004.

Gilbert, Lori. "Our Diversity: Native Americans First to Call Stockton home." *The Record*. November 29, 2014. Accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.

"History: A Look into Stockton's Past." Accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html.

Kasser, Daniel. *Downtown Stockton*. San Francisco: Arcadia Publishing, 2005.

McAlester, Virginia Savage. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 2014.

Wood, R. Coke. "The Rise of Stockton." *San Joaquin Historian* IX., no. 1 (January-March 1973). San Joaquin County Historical Society.

Repositories (specific documents cited in footnotes)

Ancestry.com.

Cesar Chavez Public Library, Stockton, California.

City of Stockton Permit Center, Stockton, CA.

David Rumsey Historic Map Collection.

Newspapers.com.

San Joaquin County Assessor's Office, Stockton, CA.

San Joaquin County Historical Society & Museum, Lodi, CA.

San Joaquin County Recorder/Clerk's Office, Stockton, CA.

San Joaquin County Public Library Obituary Index, 1850-1991, FamilySearch.org.

UC Santa Barbara Library, Aerial Photograph Collection.

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #_____
HRI #_____
Trinomial_____
NRHP Status Code 3S, 3CS, 5S
Other Listings_____
Review Code_____ Reviewer_____ Date_____

Resource name(s) or number (assigned by recorder) 429-431 S. San Joaquin Street

P1. Another Identifier: Wills House

***P2. Location:** ☐Not for Publication ☒Unrestricted ***a. County** San Joaquin

***b. USGS 7.5' Quad** Stockton West, CA **Date** 2018

***c. Address** 429-431 S. San Joaquin Street **City** Stockton **Zip** 95203


***e. Other Locational Data:** San Joaquin County Assessor's Parcel Number 149-066-070

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
429-431 S. San Joaquin Street is a two-story, wood-frame multiple-family residence that was built around 1904 in a mixture of Queen Anne and Colonial Revival styles. It is located on a 9,150-square-foot lot on the west side of S. San Joaquin Street between E. Sonora Street and E. Church Street. The building is on the same parcel as 435-437 S. San Joaquin Street, a second multiple-family residence that was built at the same time in a similar architectural style. The building has a roughly rectangular footprint and a moderately pitched front-gabled roof with flared overhanging eaves and composition shingle cladding. The building is clad with wood lap siding and has a concrete foundation. Typical windows consist of wood sash windows with molded wood trim.

***P3b. Resource Attributes:** (list attributes and codes) HP3. Multiple family property

***P4. Resources Present:** ☒Building ☐Structure ☐Object ☐Site ☐District ☐Element of District ☐Other

P5a. Photo



P5b. Photo: (view and date)
Primary (northeast) façade, view southwest, October 11, 2019.

***P6. Date Constructed/Age and Sources:** ☒historic
ca. 1904, historic newspaper articles, city directories, Sanborn Map Co. fire insurance maps

***P7. Owner and Address:**
Gospel Center Rescue Mission, Inc.
445 S. San Joaquin St.
Stockton, CA 95203

***P8. Recorded by:**
Page & Turnbull, Inc.
2401 C Street, Ste. B
Sacramento, CA 95816

***P9. Date Recorded:**
October 11, 2019

***P10. Survey Type:**
Intensive

***P11. Report Citation:** None

***Attachments:** ☐None ☐Location Map ☐Sketch Map ☒Continuation Sheet ☒Building, Structure, and Object Record ☐Archaeological Record ☐District Record ☐Linear Feature Record ☐Milling Station Record ☐Rock Art Record ☐Artifact Record ☐Photograph Record ☐ Other (list)



Figure 1. Aerial photograph of 429-431 S. San Joaquin Street. Subject parcel outlined orange. Source: Google Earth 2019, edited by Page & Turnbull.

Northeast Façade

The primary, northeast façade features a prominent front-facing gable with flared, broadly overhanging eaves that are decorated with alternating carved wood modillions and dentils (**Figure 2**). The gable end has a rectangular metal air vent with a circular wood surround carved in a wreath-like design and is clad with stucco, possibly decorated to imitate swallows' nests. A full-width porch projects from the first story of the building and displays a shallow hipped roof with overhanging eaves that are decorated with wood modillions and dentils to match those of the roof above. The roof has been altered and is cut out above the entry to the porch. The roof of the porch, itself, is supported by paired wood Tuscan columns that are mounted on top of solid wood railings clad with wood lap siding to match the building's exterior cladding, except at the far north end, where the railing has been covered with brick veneer cladding. A set of poured concrete steps with a metal handrail leads up to the porch at the north end of the façade (**Figure 3**). The porch entrance is framed by a wood lap fascia and vertical wood support beams. Fenestration on the first story consists of, from left to right, a wood panel door with an integrated lite, set behind a wood screen door that is grouped together with two wood sash windows; a set of paired wood sash windows; and a second wood panel door and screen door at the far north end. On the second story, two wood sash windows frame a smaller, fixed wood frame window. The wood trim of these windows is more elaborate than those of the first story and has a projecting lintel decorated with dentils. Windows on both the first and second stories have been altered to accommodate air conditioning units.

Southeast Façade

The southeast façade, from left to right, consists of the southeast walls and wood supports of a recessed rear porch at the southwest corner of the building followed by a number of windows in the main portion of the building. The walls immediately above the porch opening are clad with narrow vertical wood siding and wood lap siding that matches the rest of the building above (**Figure 4**). At the main portion of the building, a molded wood drip course visually separates the crawl space from the first floor. The walls above the drip course contain a number of windows of varying sizes and configurations (**Figure 5**). From left to right, windows on the first floor consist of one small wood sash window followed by a taller wood sash window, a set of paired wood sash windows, and two additional single wood sash windows. On the second floor, a small aluminum slider window with flat wood trim is followed by a larger rectangular window with decorative wood trim that has been replaced with an aluminum slider (**Figure 6**). To the right, a set of paired wood sash windows and a single wood sash window flank a canted, cutaway bay window. The bay is capped by a small, gabled roof with flared eaves like those of the northeast façade. Pipes, conduits, and electrical fixtures have

been attached to the walls in various locations. Cylindrical metal chimneys, metal equipment, and a small brick chimney are visible on the roof above.

Southwest Facade
The rear (southwest) façade features a projecting rectangular bay that contains a recessed first-story porch at its southwest corner (**Figure 7**). The roof over the bay has wide projecting eaves with exposed rafter tails. A wood staircase with flat wood handrails and wood beam supports offers access to the porch before continuing along the façade to a second entry in the second story. As at the southeast façade, the walls above the porch opening are clad with narrow vertical wood siding, with wood lap siding above to match the exterior cladding of the rest of the building. To the left, a small wood access door offers access to the crawl space. Windows on the façade consist of three aluminum sliders with flat wood trim, two of which are located at the north end of the façade and the third of which is centered in the rectangular bay. Siding next to this window has recently been replaced with new wood lap siding.

Northwest Façade
Like the southeast façade, the northwest façade has a molded wood drip course that divides the crawl space from the first floor (**Figure 8**). The façade also features two additional entries. At the east end, a wood staircase with flat wood handrails and wood beam supports lead to a door at an intermediate level between the first and second stories, possibly at an interior stair landing (**Figure 9**). A transom and window above this door, as well as a larger rectangular opening to the left, have been infilled. The second entry, located in a small cut out at the west end of the façade, consists of a wood panel door with integrated glazing. This door is accessed via a small uncovered porch, also with flat wood handrails and supports. A small access door has been cut into the wood siding to the right, and several areas of the adjacent walls have been replaced with new wood alternative siding. The majority of windows on this façade consist of replacement aluminum slider windows with flat wood trim, some of which appear to have replaced larger, original window openings.


Figure 2. Northeast facade, view northwest.


Figure 3. Porch entry at northeast façade, view southwest.


Figure 4. South end of southeast façade with portion of recessed rear porch, view northwest.


Figure 5. Southeast façade, view west.



Figure 6. Aluminum slider windows, chimney, and ventilation pipes on roof above the southeast façade, view northeast.



Figure 7. Southwest façade, view northeast.



Figure 8. Northwest façade, view east.



Figure 9. East section of northwest façade, view east.

Site Features

As previously mentioned, the subject building is one of two multiple family residences on the parcel. The second, addressed as 435-437 S. San Joaquin Street, appears to have been constructed at the same time as the subject building and is located directly to the southeast (**Figure 10**). The narrow space between the two buildings has been paved with concrete (**Figure 11**). Landscaping in front of the building consists of a small front yard with a lawn and small concrete patio that is enclosed by a tall metal fence along the front and northwest property lines (**Figure 12**). A concrete walkway extends from the sidewalk to the building's front entrance, and a narrow strip of brick pavers lead to a second concrete walkway that separates the subject building from the adjacent building on the lot. The rear portion of the lot is also paved with concrete, except for a small space immediately to the rear of the building, in which trees have been planted. An outdoor seating area with wood picnic tables and a wood lattice covering is located at the southwest corner of the lot. The rest of the rear portion of the lot is used as a driveway and parking lot for the complex (**Figure 13**).



Figure 10. The subject property (left) and 435-437 S. San Joaquin Street, view northeast.



Figure 11. Concrete walkway between the subject property and 435-437 S. San Joaquin Street, view west.



Figure 12. Front yard, view south.



Figure 13. Paved area at the rear of the building, view northeast.

Surrounding Site Context

429-431 S. San Joaquin Street is located on the block bounded by S. San Joaquin Street to the northeast, E. Church Street to the southeast, S. Hunter Street to the southwest, and E. Sonora Street to the northwest in the heart of the original street grid of Stockton and one-and-one-half blocks south of the California State Route 4 highway. The surrounding area is characterized primarily by a mix of two- to three-story residential buildings and a few brick commercial buildings that appear to have been built around the turn of the twentieth century. 435-437 S. San Joaquin Street was constructed in a similar architectural style around 1904 (**Figure 14**). The Gleason House, located directly to the northwest of the subject property at 423 S. San Joaquin Street, is a Queen Anne style house constructed in 1895 (**Figure 15**). 420 S. San Joaquin Street, directly across from the subject property, is a two-story, Queen Anne style house built in 1905 (**Figure 16**). Next door, 430 S. San Joaquin is a two-story vernacular style foursquare that was built in 1900 (**Figure 17**).



Figure 14. 435-437 S. San Joaquin Street, built 1904.



Figure 15. The Gleason House at 423 S. San Joaquin Street, built 1895.



Figure 16. 420 S. San Joaquin Street, built 1905.



Figure 17. 430 S. San Joaquin Street, built 1900.

BUILDING, STRUCTURE, AND OBJECT RECORD

***NRHP Status Code** 3S, 3CS, 5S2
***Resource Name or #** 429-431 S. San Joaquin Street

B1. Historic name: Wills House
B2. Common name: 429-431 S. San Joaquin Street
B3. Original Use: Multiple Family Residence
B4. Present use: Multiple Family Residence
***B5. Architectural Style:** Queen Anne/Colonial Revival
***B6. Construction History:** (Construction date, alterations, and date of alterations)

The parcel on which 429-431 S. San Joaquin Street is located was owned by Bee Hoult by 1900. Two earlier wood frame buildings that were present on the site at the time burned down in a fire that spread from the Agricultural Pavilion building, located two blocks north on Lafeyette Street between S. Hunter, and destroyed nearly six city blocks in September 1902.[1] The 1904 Stockton city directory records that Hoult's husband, David, was living at 431 S. San Joaquin Street, indicating that the subject building had been completed by this time to replace the buildings that had been destroyed by the fire.[2] It is likely that Bee was living there at the time, as well, as she is listed as residing at the same address with her husband and son in the 1910 federal census.[3] The 1917 fire insurance map by the Sanborn Map Company shows the building as a two-story wood frame building that consisted of two flats over a basement (**Figure 18**). It had a one-story porch that spanned the front façade, a canted bay on the southeast façade, and an agglomeration of one- and two-story porches at the rear. The second-story rear porch appears to have been accessed by a long exterior staircase. A few subsequent alterations are apparent in the 1950 Sanborn map (**Figure 19**). By this time, the building had been subdivided into four flats, and an additional one-story porch had been added at the south end of the northwest façade. The configuration of the porches and stairs at the rear façade also appear to have been altered. These changes are not clearly visible in aerial photographs from the 1930s and 1970s; however, they indicate that the overall footprint of the building has remained relatively unchanged over time (**Figure 20** and **Figure 21**). (See Continuation Sheet, page 8)

***B7. Moved?** ☒**No** ☐**Yes** ☐**Unknown Date:** N/A **Original Location:** N/A
***B8. Related Features:** _ B9a. Architect: Unknown b. Builder: Unknown


***B10. Significance: Theme** Residential Architecture **Area** Stockton, California
Period of Significance 1904 **Property Type** Multiple-Family Residential **Applicable Criteria** C/3

City of Stockton
Native American through Early American Period:
Numerous Native American groups called the Central Valley home for thousands of years before the arrival of European and American settlers. The Stockton area was settled by the Yatchicumne, a group of the Northern Valley Yokuts people whose villages were established across a vast expanse of California from the confluence of the Sacramento and San Joaquin rivers as far as the Tehachapi Mountains, 250 miles to the south. At least two Yatchicumne villages were located in the Stockton area, including one called Pasasimas, situated on a mound near the Stockton Channel in present-day Downtown Stockton. (See Continuation Sheet, page 9)

B11. Additional Resource Attributes: (List attributes and codes)

***B12. References:** See Footnotes and Continuation Sheet, page 18
B13. Remarks: None
***B14. Evaluator:** Clare Flynn, Page & Turnbull, Inc.
***Date of Evaluation:** November 4, 2019

(This space reserved for official comments.)



Location Map: San Joaquin County Assessor's Office, 2019. Subject parcel shaded orange. Edited by Page & Turnbull.

[1] "Conflagration in the Heart of Stockton Leaves Record of Death and Injury, and Devastation of Wide Area," *The San Francisco Call*, September 30, 1902.
[2] Stockton, California, City Directory, 1904.
[3] 1910 United States Federal Census, Ancestry.com.

***B6. Construction History: (continued)**




Figure 18. Excerpt from 1917 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.




Figure 19. Excerpt from 1950 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento. Edited by Page & Turnbull.



Figure 20. 1930 aerial photograph, approximate subject location outlined in orange. Source: Fairchild Aerial Surveys, Flight C-975A, Frame Z-252, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 21. 1970 aerial photograph, approximate subject location outlined in orange. Source: Cartwright Aerial Surveys, Flight CAS-2874, Frame 102, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 22. The northwest facade in April 2012. Source: Google Street View, 2012.

Google Street View images show that the front porch entry had a different configuration and was in a deteriorated condition in 2012 (**Figure 22**). This does not appear to have been the original porch entry and was replaced with the existing configuration sometime between 2012 and 2015.[4] Building permits on file at the City of Stockton Permit Center document repairs to the building's foundation, electrical work, and repairs from fire damage. Additional alterations that are not documented in permits include the addition of a porch and stairs on the northwest façade; window replacements, additions, and removals; alterations to the front and rear porches; and re-roofing.

Table 1. Permits on File at the City of Fremont Community Development Department

Permit Number	Date	Applicant	Description
31995	12/5/1949	Ila Stevenson	Foundation for apartment house
25820	4/16/1962	S.L. Fong	Repair apartment foundation underpinning
66399	1/12/1987	Robert Hong	Electrical
04783	10/05/1998	Gospel Center	Repair sheetrock and one plug from fire damage

***B10. Significance: (continued)**

Local rivers and streams provided an abundant source of food for the native population and also attracted European and American fur trappers to the area, who began exploring the area in the early nineteenth century in search of beaver and otter pelts.[5] These early explorers included Jedediah Strong Smith, who established a base camp to the southeast of present-day Stockton in 1827, and Alex McCleod, a fur trapper from the Hudson's Bay Company, whose camp near McCleod Lake gave the lake its name.[6] While the fur trappers reaped the benefits of the region's rich natural resources, they also brought diseases with them that led to the decimation of much of the local Native American population.[7]

The presence of French-Canadian fur trappers provided the inspiration for the name of the Mexican land grant that encompassed the present-day site of Stockton and its immediate vicinity during the Mexican period, after Mexico achieved independence from Spain in 1821. Rancho Campo de los Franceses, as the grant was known, was filled with numerous waterways, grassy hills, and oak trees. It was this landscape that German immigrant Captain Charles Maria Weber, founder of the city of Stockton, experienced

[4] Google Street View, April 2012, accessed October 25, 2019, Google.com.
[5] City of Stockton, "History: A Look into Stockton's Past," accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html; Lori Gilbert, "Our Diversity: Native Americans first to call Stockton home," *The Record*, November 29, 2014, accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.
[6] R. Coke Wood, "The Rise of Stockton," *San Joaquin Historian* IX, no. 1 (January-March 1973), San Joaquin County Historical Society, 2.
[7] Architectural Resources Group, Stockton Downtown Draft Historic Resources Survey, 2000, 6.

when he traveled through the area on his way to San Jose in 1842.[8] Recognizing the area's potential, Weber and his business partner, Guillermo (William) Gulnac, acquired roughly 55 square kilometers of Rancho Campo de los Franceses on the east side of the San Joaquin River from the Mexican governor in 1843. Weber eventually bought Gulnac out of the land and built his first structures on the site in 1847.[9] The first survey of the settlement, initially known as Tuleberg, was completed by Jasper O'Farrell the same year.[10]

Formation of Stockton

Like many cities in Northern California, Stockton grew from a small, rural outpost into a booming city as a result of the Gold Rush. When gold was discovered at Coloma in 1848, one year after Weber established the settlement of Tuleberg, he initially joined the fervor and spent months mining in the goldfields. He soon realized, however, that he had a better chance of making his fortune by selling goods and supplies to the floods of miners who were traveling into the area.[11] Advantageously located at the head of the Stockton Channel, a tributary of the San Joaquin River, Weber's settlement emerged as the gateway to and major supply center for California's southern mining areas as ships traveling from San Francisco brought streams of miners to the area (Error! Reference source not found.).[12]

As the settlement's population grew, so did urban development. In 1849, Major R. P. Hammond completed a second survey that laid out the first street grid between Weber Avenue, Center Street, Main Street, and Commerce Street.[13] In 1850, the same year the California achieved statehood, the settlement was officially incorporated as a city and renamed Stockton, after Commodore Robert F. Stockton, the American Navy officer who drove the last Mexican forces out of California in 1848.[14] Over the next five years, the city's population swelled from 1,000 to roughly 7,000. By the 1890s, it had exploded to approximately 23,000 residents.[15]

The streets between El Dorado Avenue, Main Street, Commerce Street, and Levee (now Weber) Avenue formed the core of the city's commercial area in the nineteenth century. The first residential districts, meanwhile, developed to the southwest and north. Floods were common in the winter months due to the city's location near miles of waterways that made up the Sacramento-San Joaquin River Delta.[16]

After the Gold Rush ended in the mid-1850s, the Central Valley's rich soil and temperate climate contributed to the development of Stockton into a major center for agricultural industries. Wheat and grains were the area's largest crop in the nineteenth century and spurred the construction of grain warehousing facilities and flour mills in the area, including the Sperry Flour Company. By the early twentieth century, fruit orchards, nuts, vegetables, potatoes, and other crops were also grown on the farms around the city.[17] Surrounded by this abundance of agricultural wealth, the city's economy developed around businesses that processed, cultivated, and transported agricultural goods. Several of Stockton's most prominent businesses, including Matteson & Williamson and Holt Brothers Manufacturing Company, made names for themselves as the manufacturers of agricultural tools and equipment that increased the productivity of the area's farms.

Stockton's location along a variety of important transportation corridors—including the Stockton Channel, with its deep water shipping access, and the Central Pacific Railroad—contributed to Stockton's industrial development and emergence as a regional transportation hub.[18] Shipyards, iron foundries, warehouses, and factories were established along the channel and its tributaries.[19]

Burgeoning with economic activity and a growing population, Stockton experienced a building boom from the 1880s until the 1930s, during which the majority of buildings in the city's downtown and nearby residential areas were constructed. In the late nineteenth century, many of the city's downtown commercial buildings were constructed of locally produced red brick, inspiring one of the Stockton's nicknames, "The Brick City."[20] Five high rises were constructed between 1910 and 1917 alone.[21] Two- and three-story masonry residential hotels were also constructed during this period in order to provide affordable, temporary housing for the large population of migrant laborers who worked on the surrounding farms. These residential hotels, many of which had

[8] Wood, 2.
[9] Idem.
[10] Idem.
[11] Idem.
[12] Architectural Resources Group, 7.
[13] Architectural Resources Group, 7.
[14] Ibid., 6.
[15] Ibid., 7-8.
[16] Daniel Kasser, *Downtown Stockton* (San Francisco: Arcadia Publishing, 2005), 15.
[17] Architectural Resources Group, 13-14.
[18] Ibid., 17.
[19] "A Historical Study of Stockton, California," Visit Stockton, accessed June 19, 2019, https://www.visitstockton.org/about-us/stockton-history/.
[20] Architectural Resources Group, 12.
[21] Ibid., 16.

commercial retail spaces on the first floor and exhibited Classical architectural detailing, became a common building type in downtown Stockton as a result.[22] The downtown area was also home to the largest Chinatown in California, as many Chinese families relocated from San Francisco after the 1906 earthquake.[23]

Other immigrant groups, in addition to the Chinese, made up a large portion of Stockton's population. After the passage of the Chinese Exclusion Act in 1882, Filipino, Japanese, and Sikh immigrants gradually replaced the Chinese as the main labor force in the city's packing houses, farms, and domestic industries. By the 1920s, Filipino men and women made up the majority of Stockton's agricultural labor force, giving the city the nickname, the "Manila of California."[24] From the late nineteenth century to the 1920s, Italians also arrived in Stockton in large numbers, during a wave of migration that took place after the unification of Italy around 1861.[25]

Construction during the late nineteenth and early twentieth centuries also included civic and institutional establishments. A San Joaquin County Courthouse was completed on a public square a short distance from the channel in 1854 and was replaced in 1890. In 1924, the University of the Pacific relocated from San Jose to Stockton, bringing one of the city's most influential and long-standing establishments to the city.[26]
Infrastructural improvements further enhanced Stockton's continuing development. Electric trolleys began service in the last decades of the nineteenth century. As the automobile became increasingly popular and affordable at the start of the twentieth century, an auto row developed at El Dorado Street and Miner Avenue.[27] In 1911, a new diverting channel was completed to address issues with frequent flooding.[28]

Stockton's varied economy, based on the agricultural industry and other industries centered around the shipping channel, helped soften the impact of the Great Depression. Starting in 1927, work to expand and deepen Stockton Channel provided employment for hundreds of workers. The new Port of Stockton opened in 1933 as the largest inland port in California at the time. Opportunities for work in the region's surrounding farms, meanwhile, attracted families from the Midwest and large populations of immigrant workers to the area.

World War II to the Present
The outbreak of World War II and the resulting demand for war-related goods stimulated Stockton's local industries. Shipbuilding, based at the city's many shipyards, became the largest source of employment, while the opening of an Army Air Force base at Old Stockton Field and the Stockton Naval Supply depot created new job opportunities. The war also created an agricultural labor shortage. Mexican workers, sponsored by the federal Bracero Program, filled the void and became part of the city's rich multicultural makeup.[29]

The postwar period reshaped the city. Stockton struggled to maintain its status as a major shipping center because the Stockton Channel was not large or deep enough to accommodate the increasing size of shipping vessels. In response, the local economy began to shift toward warehousing and the production of farming machinery and commercial boats. The completion of new residential neighborhoods, shopping malls, and of the Crosstown and Interstate 5 freeways, as well as the migration of affluent residents outside of the city center, diverted economic and commercial activity away from Stockton's historic downtown core. By the 1950s, the area was considered blighted. In the 1960s, the area became the target of urban renewal efforts, which resulted in the demolition of all but three buildings on nine square blocks of downtown. Longstanding residents, many of whom were of Chinese or Filipino descent, were displaced during the redevelopment.[30]

In the 1980s, Stockton's downtown began to experience a resurgence of development. Activity around the canal refocused around recreation-related uses and building projects. Boats plied its waters, and restaurants, a shopping mall, and housing developments were constructed along the waterfront.[31]

In the 2010s, agriculture remains important to the city's economy. Asparagus, cherries, tomatoes, walnuts, and almonds have replaced wheat and grain as the area's major crops. In spite of the changes that have taken place over time, Stockton continues to

[22] Ibid., 9.
[23] Ibid., 8.
[24] Architectural Resource Group, 9-10, 21.
[25] Pacific Italian Alliance and Ralph A. Clark, *Italians of San Joaquin County* (Charleston, SC: Arcadia Publishing, 2014), 7.
[26] "A Historical Study of Stockton, California."
[27] Ibid., 8-9
[28] "A Historical Study of Stockton, California."
[29] Ibid., 10.
[30] Ibid., 11.
[31] Ibid., 11.

be characterized by its agricultural industry, the Stockton Channel, its history of brick buildings downtown, and a diverse, multi-cultural population.[32]

The Queen Anne Style: Free Classic Subtype

The Queen Anne style was a popular architectural style among the elite during the Victorian era of the late nineteenth century. First used in England, this style referred back to the reign of Queen Anne (1702-1714) when craftsmanship and simplicity of construction were emphasized in the architectural vernacular.[33] One of the main innovators and architects of this style was Richard Norman Shaw, who popularized the Queen Anne style in England with his half-timbered designs that borrowed from late Medieval buildings from the Elizabethan and Jacobean periods. American architects introduced this style into the mainstream during the late 1870s and soon added subtypes of the style with spindlework and classical architectural elements. By the 1880s, the Queen Anne style had become the leading architectural style for the Victorian elite and upper to middle classes.

The Queen Anne style is characterized by its variety of features and combination of ornamentation. Typical features of the Queen Anne style include steeply pitched roofs, irregular rooflines, gable projections, cutaway bay windows, asymmetrical compositions, and swag and garland appliqués.[34] The result of this fusion of ornamentation and composition was a highly textured and varied residence, which achieved the elegance and grace desired by the people of this era. Commonly, other architectural styles, such as Eastlake and Stick, were combined with the Queen Anne style to produce asymmetrical and varied compositions.

Approximately 35 percent of Queen Anne houses are considered to be a subtype of the style called Free Classic. The style became common after 1890, with a peak from 1900 until 1910, and shares some features with early Colonial Revival houses, which became the dominant architectural style in the years afterward. The Free Classic subtype is characterized by its use of classical columns that are typically grouped together in units of two or three. Other classical features – such as cornice-line dentils, swags, garlands, or Palladian windows – are also common.[35]

Owner and Occupant History

The sequence of owners and occupants of the subject property, developed from records maintained at the San Joaquin Recorder-County Clerk's offices, historic city directories, census records, and historical newspaper articles is summarized in Table 2. Brief biographies of long-term or notable owners and occupants follow the table.

Table 2. Owners and Occupants of 429-431 S. San Joaquin Street, Stockton

Year(s)	Owner[36]	Occupant[37]
ca. 1900-1949	Bee Hoult	429 S. San Joaquin Street 1910-1915 - Llewella Hicklin 1920 - Geo Kosta. restaurant manager 1920 - John Stimbogiani, waiter 1925 - Charles Pefferling, salesman 1930 - Ada Partrick, widow 1935 - H.A. Pile, blacksmith helper 1940 - Vacant 1945 – Henry L. Olechea 429a S. San Joaquin Street 1920 - Fermin Alustiza, sheepman 1925 - J.A. Bennett 1945 - Mrs. W.E. Warren 431 S. San Joaquin Street 1908-1915 – David J. and Bee Hoult, foreman of Houser & Haines Manufacturing Co. 1925 - W.A. Morrow, assembler 1935 – Vacant 1940 – James Ramos, cook 1945 - Thomas Iriarte, machinist
1949	Bee Hoult Estate	

[32] "History: A Look Into Stockton's Past."
[33] Lester Walker, *American Shelter* (New York: The Overlook Press, Inc., 1997), 152.
[34] Virginia Savage McAlester, *A Field Guide to American Houses* (New York: Alfred A. Knopf, 2014), 345-347.
[35] Idem.
[36] Information from San Joaquin County Recorder-County Clerk.
[37] Information from United States Census and city directories, Ancestry.com. Directory listings do not include occupations for all residents.

Year(s)	Owner[36]	Occupant[37]
	c/o Bob Stevenson	
1949-1960	Ila H. Stevenson	429 S. San Joaquin Street 1950 - Vernon E. Gresham, salesman 1955-1960 - Ila H. Stevenson, widow 429a S. San Joaquin Street 1950 – Agnes Sanchez, clerk 1955 - Peter Laperena, laborer 1960 – Jessie Villasenor, cannery worker 431 S. San Joaquin Street 1950 – Thomas Iriarte, welder 1960 - Lupe Carranza, cook 431a S. San Joaquin Street 1950 – Rufino Echandi, employee AAWCo; Grace Echandi, bookkeeper; and Joseph Echandi 1960 - Carmen D. Quirarte
1960-1972	S.L. Fong Lum Bow Yum Fong	429 S. San Joaquin Street 1965 – Vacant 1970 – Seopoldo Gutierrez, farm worker 429a S. San Joaquin Street 1965 – Leonidez Galeviz 1970 – Quong Wee Lee 431 S. San Joaquin Street 1965 – Olivas Suant, farm worker 1970 – Jenny M. Huante 431a S. San Joaquin Street 1965-1970 – Paul Tearo, retired
1972-1977	Elizabeth Fong Wills John Fong	429 S. San Joaquin Street 1975 – Olivias Huante 429a S. San Joaquin Street 1975 – Dina Aguilar, retired 431 S. San Joaquin Street 1975 – Lepoldo Gutierras 431a S. San Joaquin Street 1975 – Gregory Hernandez, retired
1977-1985	Elizabeth Fong Wills John Fong Christopher James Robertson Wills Elizabeth Mei Sit Fong Wills	429 S. San Joaquin Street 1980 – Jenny Huante, retired 1985 - Vacant 429a S. San Joaquin Street 1980 – Javier Olivos 1985 – Phoeng Soeung 431 S. San Joaquin Street 1980-1985 – Louie and Marie Godoy 431a S. San Joaquin Street 1980-1985 – Gregory Hernandez, retired
1985-1989	Robert W. Hong Mee Yoke Hong Haye B. Chan Conde T. Chan Bak F. Hong Judith Hong Michael Attanasio Noreen E. Chan	429a S. San Joaquin Street 1986 –Phoeung Soeung 429b S. San Joaquin Street 1986 – Thont Hong 431a S. San Joaquin Street 1986 – Saren Sao 431b S. San Joaquin Street 1986 – Saol Pol, student
1989-2003	Gospel Center	429-431 S. San Joaquin Street 1989-2003 – Gospel Center (Annex)
2003-2019	Gospel Center Rescue Mission, Inc.	429-431 S. San Joaquin Street 2003-2019 – Gospel Center Rescue Mission, Inc.

The Hoult Family, Owners and Occupants, ca. 1900-1949

As previously mentioned, the subject building appears to have been originally owned and constructed for Bee Hoult and her family around 1904, after a fire destroyed earlier buildings on the lot. Born Bee Delia O'Brien in Ireland around 1861, Bee immigrated to the United States in 1883. In 1887, she married David James Hoult, a foreman of Houser & Haines Manufacturing Co.[38] The couple had one child, a son named Urban.[39] The family lived together at 431 S. San Joaquin Street in 1910 through at least 1915.[40] As an adult, Urban worked for the firm of Radcliffe & Hoult, publishers of the *Mercury Sun* newspaper in Merced. He died of pneumonia in 1924 at the age of 35. David died just four years later at the age of 65.[41] Bee continued to own the subject property after their deaths and moved to the neighboring house at 435 S. San Joaquin Street until her own death sometime around 1949, after which the property passed to her niece, Ila H. Stevenson. Research did not uncover any additional information about the life or contributions of Bee, David, or Urban Hoult. City directories do not list Stevenson as a resident of the subject property.

Gospel Center Rescue Mission, Inc., Owner, 1989-2019
Gospel Center Rescue Mission (GCRM) is a faith-based non-profit that serves the homeless and addicted of San Joaquin County. The non-profit was founded in 1940 in Ripon, California out of a concern for the post-Depression era homeless population. Over time, GCRM added programs to provide food, shelter, clothing, addiction treatment, and medical care to the homeless.[42] Today, the agency serves over 1,000 men, women, and children at its Stockton campus each day and offers eight programs, including the only Homeless Recuperative Care Program and non-profit payee service in San Joaquin County.[43]

Significance Evaluation: National Register of Historic Places and California Register of Historical Resources
The subject property at 429-431 S. San Joaquin Street is not currently listed in the National Register of Historic Places (National Register) or the California Register of Historical Resources (California Register). The building is included in the California Historical Resources Information System (CHRIS) as of 2012 with the status code, "5S2," indicating that the property has been identified as an "Individual property that is eligible for local listing or designation."

In order for a property to be eligible for listing in the National Register, it must be found significant under one or more of the following criteria:

Criterion A (Event): Properties associated with events that have made a significant contribution to the broad patterns of our history.

Criterion B (Person): Properties associated with the lives of persons significant in our past.

Criterion C (Design/Construction): Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction.

Criterion D (Information Potential): Properties that have yielded, or may be likely to yield, information important in prehistory or history.

In order for a property to be eligible for listing in the California Register, it must be found significant under one or more of the following criteria:

Criterion 1 (Events): Resources that are associated with events that have made a significant contribution to the broad patterns of local or regional history, or the cultural heritage of California.

Criterion 2 (Persons): Resources that are associated with the lives of persons important to California history.

Criterion 3 (Architecture): Resources that embody the distinctive characteristics of a type, period, region, or method of construction, or represent the work of a master, or possess high artistic values.

Criterion 4 (Information Potential): Resources or sites that have yielded or have the potential to yield information important to the prehistory or history of California.

The following section examines the eligibility of the building at 429-431 S. San Joaquin Street for *individual* listing in the National

[38] San Joaquin County Clerk-Recorder
[39] 1900 United States Federal Census, Ancestry.com.
[40] 1910 United States Federal Census, Ancestry.com; Stockton City Directory, 1915.
[41] California, County Birth and Death Records, 1800-1994, FamilySearch.org.
[42] "Our Mission," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us/Mission-History.
[43] "Wayne G. Richardson," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us.

Register or California Register.

Criterion A/1 (Events)
The subject property does not appear to be eligible for individual listing under Criterion A/1 for association with events that have made a significant contribution to the broad patterns of local, state, or national history. The multi-family house was constructed around 1904, more than fifty years after Stockton was incorporated in 1850, and, thus, it is not significant for being one of the first or earliest residential buildings constructed in the city. Rather, it was constructed at a time when Stockton was experiencing a building boom that lasted from the 1880s until the 1930s. This building boom, however, is most closely associated with commercial and institutional development in Stockton's urban core and the city's emergence as a transportation hub and center for agricultural industries. Although residential development occurred during the same period, the subject building is not an exceptional example of a residential building constructed during the period and does not appear to have had an impact on the development of the surrounding area. Therefore, the building is not considered to be a notable representative of Stockton's development in the early twentieth century and does not appear to rise to the level of significance necessary to be individually eligible for listing on the California Register or National Register under Criterion A/1.

Criterion B/2 (Persons)
The subject property does not appear eligible for individual listing under Criterion B/2 for association with the lives of persons important to local, state, or national history. Bee Delia Hoult owned the property from at least 1900 until 1949, and the subject building appears to have been constructed for Hoult and her family around 1904 after a fire in 1902 destroyed earlier buildings on the site. Hoult appears to have lived in the subject building with her husband, David, and son, Urban, from roughly the time of its construction until around 1915. David worked as a foreman for Houser & Haines Manufacturing Co., while Urban worked for the firm that published the *Mercury Sun* newspaper in Merced. Research did not reveal information about Bee Hoult's occupation or shed any further light on the activities or contributions of the Hoult family to Stockton or the surrounding area. From 1960 to 1985, the building was owned by a number of individuals that appear to have been associated with the Fong family. City directories do not list these owners as residents of the building or of Stockton, and research did not uncover the occupations or activities of these individuals necessary to evaluate their contributions to history. As a multi-family residence, a large number of people have lived at the subject building over time. Throughout its history, residents appear to have primarily been working class individuals employed in a number of industries. In the first half of the twentieth century, city directories list restaurant workers, blacksmiths, machinists, and agricultural workers as residents of the house. From the 1940s to the 1960s, clerks, salesmen, cannery workers, and laborers from other industries resided there. Starting in the 1960s, residents were primarily farm workers and retired individuals. Research did not indicate that any of these individuals gained notable importance within their professions. Therefore, none of the owners or occupants that were identified during research for this report appear to have made significant contributions to local, state, or national history in a manner that rises to the level of significance necessary to merit designation under Criterion 2.

Criterion C/3 (Architecture)
The subject property does appear eligible under Criterion C/3 as a resource that embodies the distinctive characteristics of a multi-family house built in the Queen Anne style. More specifically, the house is a representative example of the Free Classic subtype of Queen Anne style houses. The building was originally constructed around 1904, during the peak period of popularity of Free Classic Queen Anne houses in the United States; however, a scan of the area surrounding the subject building suggests that this style was relatively uncommon in Stockton or that few examples survive in the city today. The subject building exhibits many of the defining characteristics of the style, including a dominant front-gabled roof; one-story, full-width front porch; a side bay window; and asymmetrical composition, that are representative of the broader Queen Anne style, as well as the use of paired Tuscan columns as porch supports and cornice-line carved wood modillions and dentils that are indicative of the Free Classic subtype. The building also has some additional notable design features, including flared overhanging eaves and surviving original window trim and doors with decorative carved dentils. The subject property, therefore, appears to be significant under Criterion C/3.

The property's period of significance under Criterion C/3 is 1904, when the building was originally constructed.

Criterion D/4 (Information Potential)
The subject property does not appear to be individually eligible under Criterion D/4 as a building that has the potential to provide information important to the prehistory or history of the City of Fremont, state, or nation. It does not appear to feature construction or material types, or embody engineering practices that would, with additional study, provide important information. Page & Turnbull's evaluation of this property was limited to age-eligible resources above ground and did not involve survey or evaluation of the subject property for the purposes of archaeological information.

Evaluation (Integrity)
In order to qualify for listing in any local, state, or national historic register, a property or landscape must possess significance under at least one evaluative criterion as described above and retain integrity. Integrity is defined by the California Office of Historic Preservation as "the authenticity of an historical resource's physical identity evidenced by the survival of characteristics that existed during the resource's period of significance," or more simply defined by the National Park Service as "the ability of a property to

convey its significance."[44] Established integrity standards are outlined by the *National Register Bulletin: How to Apply the National Register Criteria for Evaluation*. Seven variables, or aspects, that define integrity are used to evaluate a resource's integrity: location, setting, design, materials, workmanship, feeling, and association. A property must retain integrity under most or all of these aspects in order to retain overall integrity. If a property does not retain integrity, it can no longer convey its significance and is therefore not eligible for listing in local, state, or national registers.

1. *Location* is the place where the historic property was constructed.
2. *Design* is the combination of elements that create the form, plans, space, structure and style of the property.
3. *Setting* addresses the physical environment of the historic property inclusive of the landscape and spatial relationships of the building(s).
4. *Materials* refer to the physical elements that were combined or deposited during a particular period of time and in a particular pattern of configuration to form the historic property.
5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history.
6. *Feeling* is the property's expression of the aesthetic or historic sense of a particular period of time.
7. *Association* is the direct link between an important historic event or person and a historic property.

429-431 S. San Joaquin Street retains all seven of the aspects of integrity. The building has not been moved since its construction and, thus, retains integrity of location. Although the surrounding area has changed over time, a number of single- and multi-family houses and commercial buildings also dating to the late nineteenth and early twentieth centuries remain at their original locations directly next to or across from the subject property on S. San Joaquin Boulevard. As a result, the subject property retains its integrity of setting. Although some exterior alterations to the front porch, gable end, and rear and side windows are evident, the building's essential exterior features and materials that convey its significance as a multi-family house constructed in the Free Classic subtype of the Queen Anne style – including prominent front gable, wide flared eaves with cornice line modillions and dentils, full-width front porch, paired Tuscan column porch supports, original wood windows and doors, and wood lap siding – remain intact. Integrity of design, materials, workmanship, feeling, and association have also been retained.

Based on this analysis, 429-432 S. San Joaquin Street retains sufficient integrity to convey its significance under Criterion 3/C and therefore qualifies for listing on the National and California Registers.

Character-Defining Features

For a property to be eligible for national, state, or local designation, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. To be eligible, a property must clearly contain enough of those characteristics, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials. The character-defining features of 429-431 S. San Joaquin Street include:

- Prominent front-facing gabled roof with wide, flared eaves
- Cornice with wood modillions and dentils
- One-story full-width front porch with paired Tuscan column supports mounted on solid wood railing
- Side cutaway bay window with gabled roof with flared eaves
- Wood lap siding
- Wood panel doors and sash windows with molded wood trim, some with decorative carved dentils
- Entries to multiple units at front and rear façades

Significance Evaluation: City of Stockton Landmark, Historic Site, or Structure of Merit

The subject building is not included in the Downtown Stockton Historic Resources Survey (2000) and is not located within a local historic district or zoning overlay or listed as a City of Stockton Landmark, Historic Site, or Structure of Merit. It is therefore not currently listed locally as a historic resource.

Landmarks

According to the Stockton Municipal Code Section 16.220.070, "In considering an artifact, natural feature, or structure for designation as a Landmark, the Board shall apply any or all of the following criteria:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Architectural Craftsmanship**. Its embodiment of elements demonstrating outstanding attention to architectural and/or engineering craftsmanship, design, detail, or materials;

[44] California Office of Historic Preservation, *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources* (Sacramento: California Office of State Publishing, 4 September 2001), 11; U.S. Department of the Interior, National Park Service, *National Register Bulletin: How to Apply the National Register Criteria for Evaluation* (Washington, D.C.: National Park Service, 1995), 44.

3. **Architectural Style.** Its exemplification of a particular architectural style or way of life important to the City, the State, or the Nation;
4. **Architectural Type.** Its exemplification of the best remaining architectural type in the City;
5. **Historic Event.** Its location as a site of a significant historic event;
6. **Heritage.** Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
7. **Visual Feature.** Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
8. **Relationship to Another Landmark.** Its relationship to any other landmark, if its preservation is essential to the integrity of that landmark;
9. **Significant Person.** Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation;
10. **Work of a Significant Person.** Its identification as the creation, design, or work of a person(s) whose effort has significantly influenced the heritage of the City, the State, or the Nation; or
11. **Natural Environment.** Its integrity as a natural environment that strongly contributes to the well-being of the people of the City, the State, or the Nation."[45]

Historic Sites & Structures of Merit
Historic Sites and Structures of Merit are designated by the same criteria. According to the Stockton Municipal Code Sections 16.220.090 and 16.220.100, the criteria for designating Historic Sites and Structures of Merit are the following:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Heritage**. Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
3. **Visual Feature of the City**. Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
4. **Way of Life.** Its exemplification of a particular way of life important to the City, the State, or the Nation;
5. **Historic Event.** Its location as a site of a significant historic event regardless of its current configuration, development, or use;
6. **Significant Person**. Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation; or
7. **Significant Person of a Specific National Origin.** Its identification with a person(s) representative of a specific national origin who have contributed to the culture and development of the City, the State, or the Nation."[46]

As evidenced in the previous evaluation, 429-431 S. San Joaquin Street appears to be significant at the local level under Criterion C/3 of the National Register and California Register and possesses sufficient integrity to be eligible for listing. The City of Stockton's criteria for the designation of Landmarks, Historic Sites, and Structures of Merit correspond approximately with those of the National Register and California Register; however, they do not appear to include an integrity requirement. In particular, criteria 2, 3, and 4 above for listing as a City of Stockton Landmark appear to correspond with Criterion C/3 of the National Register and California Register. Thus, the above evaluation for National Register and California Register Criteria C/3 can be extended to local designation under the corresponding criteria for listing as a City of Stockton Landmark, and the property appears to merit local designation as a City Landmark.

Conclusion
429-431 S. San Joaquin Street does appear to be eligible for individual listing in the National Register under Criterion C, the California Register under Criterion 3, and as City of Stockton Landmark under Criteria 2, 3, and 4. The subject building was constructed in 1904 and embodies the distinctive characteristics that are representative of a multi-family house that was built in the Free Classic subtype of the Queen Anne style. As such, the California Historical Resource Status Codes (CHRSC) of "3S," "3CS," and "5S2" have been assigned to the property, meaning that it has been found eligible for the National Register and California Register as an individual property through survey evaluation.[47]

[45] Stockton Municipal Code: 16.220.070, "Landmarks," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_070&frames=on.
[46] Stockton Municipal Code: 16.220.090, "Historic sites," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_090&frames=on; Stockton Municipal Code: 16.220.100, "Structures of merit," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_100&frames=on.
[47] California State Office of Historic Preservation Department of Parks and Recreation, *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory,* Sacramento, November 2004.

***B12. References:**

Publications

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume I*. 2000.

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume II*. 2000.

California Office of Historic Preservation. *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources,* Sacramento: California Department of Parks and Recreation, 2001.
———. *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory*. Sacramento: California Department of Parks and Recreation, 2004.

Gilbert, Lori. "Our Diversity: Native Americans First to Call Stockton home." *The Record*. November 29, 2014. Accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.

"History: A Look into Stockton's Past." Accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html.

Kasser, Daniel. *Downtown Stockton*. San Francisco: Arcadia Publishing, 2005.

McAlester, Virginia Savage. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 2014.

Wood, R. Coke. "The Rise of Stockton." *San Joaquin Historian* IX., no. 1 (January-March 1973). San Joaquin County Historical Society.

Repositories (specific documents cited in footnotes)

Ancestry.com.

Cesar Chavez Public Library, Stockton, California.

City of Stockton Permit Center, Stockton, CA.

David Rumsey Historic Map Collection.

Newspapers.com.

San Joaquin County Assessor's Office, Stockton, CA.

San Joaquin County Historical Society & Museum, Lodi, CA.

San Joaquin County Recorder/Clerk's Office, Stockton, CA.

San Joaquin County Public Library Obituary Index, 1850-1991, FamilySearch.org.

UC Santa Barbara Library, Aerial Photograph Collection.

APPENDIX D
HISTORIC AMERICAN BUILDINGS SURVEY REPORT

HABS CA-xxx

429-431 and 435-437 S. San Joaquin Street
Stockton, San Joaquin County,
California

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
U.S. Department of the Interior
909 1st Ave
Seattle, WA 98104

HISTORIC AMERICAN BUILDINGS SURVEY

429-431 and 435-437 S. San Joaquin Street

HABS NO CA-xxxx

Location: 429-431 and 435-437 S. San Joaquin Street, Stockton, San Joaquin County, California, USGS 7.5' Stockton West Quadrangle, 2018

Coordinates: The following coordinates were obtained on May 20, 2021, using Google Earth (WGS84). There is no restriction on its release to the public.

The coordinates are from each corner of Assessor's Parcel Number 149-066-070, containing the two multi-unit houses.

NW corner: Lat: 37°56'55.32"; Long: 121°17'11.29"
NE corner: Lat: 37°56'55.54"; Long: 121°17'10.14"
SW corner: Lat: 37°56'54.72"; Long: 121°17'11.09"
SE corner: Lat: 37°56'54.92"; Long: 121°17'10.00"

Present Owner: City of Stocton

Present Occupant: The Gospel Center Rescue Mission, Inc.

Present Use: Homeless housing

Significance: The two multi-family buildings located at 429-431 and 435-437 S. San Joaquin Street in Stockton embody the distinctive characteristics of two architectural styles, including Queen Anne and Colonial Revival, often referred to as Queen Anne Free Classic, which is a subtype of the Queen Anne style that uses classical elements from the Colonial architectural design. Both buildings have a period of significance of 1904.

The Queen Anne style (also known as Queen Anne Revival) is associated with the Victorian era that flourished between 1870 and 1910 during the reign of Queen Anne in England. Introduced in the 1860s by English architect Richard Norman Shaw, Queen Anne architecture resembled Victorian architecture but was much less formal. The Queen Anne style evolved from the early English designs to distinctly American, with numerous and sometimes regional variations. While the Queen Anne style can embody various forms, there are certain key elements of the Queen Anne style that are reflective of an opulent lifestyle. These key elements include steeply pitched complex roofs, slate or patterned wood shingles (referred to as fish scales), faux half-timbering, brightly painted exterior facades with contrasting trim, large brick or stone chimneys, front-facing towers, turrets and gables, second-story balconies, wrap-around porches, bay windows, stained-glass windows, tall double-hung windows accented with art glass or decorative

patterns, spindle railings, and ornamental trim, which are considered character-defining features of this style.

The Colonial Revival style refers to a rebirth of interest in the early English and Dutch colonial houses of the Atlantic Seaboard, re-introduced to America at the Philadelphia Exposition of 1876, which marked the centennial of the signing of the Declaration of Independence. Many of the buildings designed for the Exposition were based on historically significant colonial designs. At about the same time, several national organizations publicized a series of articles on eighteenth-century American architecture, which appeared in the American Architect and Harpers magazines. The renewed interest in colonial architecture fueled by the centennial and the exposure of the Colonial Revival style received in national publications helped make it popular throughout the country from the 1880s to the 1940s. Character-defining features of the Colonial Revival style include symmetrical façades, fanlights, and sidelights around the main door, double-hung sash wood windows, often set in pairs. Subtypes of this style also include asymmetrical, hipped roof designs with and without full-width porches, side-gable roofs, centered gable, gambrel roofs, second-story overhang, and one-to-three-story, some with built-in garages.

The **1904 building at 429-431 S. San Joaquin Street** exhibits many of the character-defining elements of the Queen Anne Free Classic subtype, including a dominant front-gabled roof, full-width front porch, a side bay window, and asymmetrical design that are representative of the Queen Anne style. In addition, there are paired Tuscan-style columns utilized as porch supports and a decorative cornice with carved wood modillions and dentils, and a dominant front pediment roof gable with a slight overhang, which is indicative of Colonial Revival design. The building also has prominent design features, including flared overhanging eaves and original wood window trim, some of which have projecting lintels with decorative dentils and wood panel doors representing the ornate designs often found in revival architecture during the early 1900s. Together, these elements of Queen Anne and Colonial Revival design are representative of the Queen Anne Free Classic subtype.

The **1904 building at 435-437 S. San Joaquin Street** exhibits many of the defining characteristics of the Queen Anne Free Classic subtype, including a dominant front-gabled roof and a full-width front porch that are representative of the Queen Anne style, as well as the use of Tuscan columns as porch supports with cornice-line carved wood modillions and dentils, and a dominate front pediment roof gable with a slight overhang, typical of Colonial Revival design. The building also consists of original wood window trim and wood panel doors with decorative carved dentils. Together, these elements of Queen Anne and Colonial Revival design are representative of the Queen Anne Free Classic subtype.

Historian: Author and Researcher: Stacey De Shazo, M.A., Architectural Historian/Historian, Evans & De Shazo, Inc. July 6, 2021.

Project Information: The HABS photo documentation of the two 1904 multi-family buildings was completed by HABS Photographer: Dennis Hill, Dennis Hill Content Creation.

Part 1. Historical Information

A. Physical History:

1. **Date of Erection:** The two multi-family buildings were constructed in 1904.

2. **Architect:** Unknown.

3. **Original and subsequent owners, occupants, use:**

1900 –1949 Owner: Bridget "Bee" Delia O'Brien Hoult

The property containing the two 1904 multi-family buildings was first owned by Bridget "Bee" Delia O'Brien Hoult from 1900 to 1949. When Bee purchased the property, there were two previous wood-framed buildings; however, in 1902, a fire destroyed the two buildings.[1] In 1904, the two current 1904 multi-family buildings were constructed within the property.

Bee was born in 1863 in Ireland and immigrated to the United States (U.S.) in 1883. In 1887, she married David James Hoult. David was born in 1862 in West Virginia to John Cunningham Hoult (1832-1905), inventor of the first combined harvester to be used in the U.S.[2] David was a foreman at Houser & Haines Manufacturing Co., a company located in Stockton that sold agricultural tools and machinery.[3] Bee and David had one child, a son named Urban James Hoult, born in 1889 in Stockton.[4] The family lived together within the property in the first floor of the house at 431 S. San Joaquin Street from 1904 to approximately 1915.[5] During this time, Urban was a "druggist" working at a drugstore in Stockton.[6] In 1924, Urban, who was now living in Merced, died of pneumonia, and in 1929, David died. After the deaths of Urban and David, Bee continued to live at the property, but it appears that she moved from the house at 431 S. San Joaquin Street to the adjacent 1904 house at 435 S. San Joaquin Street, where she lived until she died in

[1] Ancestry.com, Stockton, California, City Directory, 1904.

[2] Newspapers.com, "Aged Pioneer Dies", The San Francisco Call San Francisco, California, March 10, 1905.

[3] Ancestry.com, 1910; Census Place: Stockton Ward 1, San Joaquin, California; Roll: T624_103; Page: 7B; Enumeration District: 0127; FHL microfilm: 1374116

[4] Ancestry.com, Stockton, California, City Directory, 1922.

[5] Ancestry.com, Stockton City Directory, 1915.

[6] Ancestry.com, U.S. World War I Draft Registration Card (1917=1918) *California;* Registration County: *Merced County.*

1948. After Bee died, the property was placed in a trust and then was deeded to her niece, Ila H. Stevenson.

During the time Bee owned the property, she rented out rooms within the two multi-family buildings to various occupants. At this time, the building at 429-431 S. San Joaquin Street contained two flats, one on each floor, and the building at 435-437 S. San Joaquin Street consisted of four rooms for rent with a shared kitchen and diningroom. The names of the occupants and their occupations, if known, are detailed below.

<u>429 S. San Joaquin Street</u>
1910-1915 - Llewella Hicklin
1920 - George Kosta, restaurant manager
1920 - John Stimbogiani, waiter
1925 - Charles Pefferling, salesman
1930 - Ada Partrick, widow
1935 - H.A. Pile, blacksmith helper
1940 - Vacant
1945 – Henry L. Olechea

<u>429a S. San Joaquin Street</u>
1920 - Fermin Alustiza, sheepman
1925 - J.A. Bennett
1945 - Mrs. W.E. Warren

<u>431 S. San Joaquin Street</u>
1925 - W.A. Morrow, assembler
1935 – Vacant
1940 – James Ramos, cook
1945 - Thomas Iriarte, machinist

<u>435 S. San Joaquin Street</u>
1910 – Frank H. Bileski, dry goods merchant
1915 – William R. Holmes, bartender
1920 – Harry A. Smith, mechanic
1945 - Lee C. Preston, shoe repairer

<u>437 S. San Joaquin Street</u>
1910 – Emma R. Small
1915-1920 – Thomas A. King, cigar salesman
1925 – Vacant

1930 – Valerie Brown
1935-1940 – Emma R. Small
1945 - Joseph Smith, driver

1948-1949 After Bee's death in 1948, the property was placed within the Bee Hoult Estate, which was overseen by Bob Stevenson as the executor of the estate. In 1949, the property was deeded to Bee's niece, Ila M. Hoult Stevenson, Bob Stevenson's mother.

1949-1960 Owner: Ila M. Hoult Stevenson

Ila M. Hoult Stevenson was the daughter of William John Holt, David James Hoult's brother and Bee's brother-in-law. Ila was born in 1898 in Stockton, California, to William John Hoult and Maria O'Brien Hoult,[7] who immigrated from Ireland in 1895. Ila was married to Bernard Leroy Stevenson, who died in 1947, and they had one son, Robert "Bob" Hoult Stevenson, born in 1920. When Ila owned the two 1904 multi-family buildings, it appears that she lived within the lower floor unit at 429 S. San Joaquin Street from 1950 to 1960.

Between 1950 and 1960, Ila rented out rooms within the two multi-family buildings to various occupants. The names of the occupants and their occupations, if known, are detailed below.

429 S. San Joaquin Street
1950 - Vernon E. Gresham, salesman

429a S. San Joaquin Street
1950 – Agnes Sanchez, clerk
1955 - Peter Laperena, laborer
1960 – Jessie Villasenor, cannery worker

431 S. San Joaquin Street
1950 – Thomas Iriarte, welder
1960 - Lupe Carranza, cook

431a S. San Joaquin Street
1950 – Rufino Echandi, who worked at AAWCo, Grace Echandi, who worked as bookkeeper, and their son, Joseph Echandi
1960 - Carmen D. Quirarte

[7] The relationship between Bridget "Bee" Delia O'Brien Hoult and Maria O'Brien Hoult is not known, but it is likely that Maria and Bee were cousins.

435 S. San Joaquin Street
1950 – Clyde H. Dunsing, engineer for NSD
1955-1960 - Thomas Iriarte, welder

437 S. San Joaquin Street
1950 – Joseph Smith, driver
1955 - Julia J. George, saleswoman for Smith & Lang
1960 – Mary Leyva

1960-1972 Owner: S.L. Fong and Lum Bow Yum Fong

S.L. Fong and his wife Lum Bow Yum Fong (aka Lang G. Fong) purchased the property in 1960 as an income property and continued to live in a nearby house at 325 S. San Joaquin Street (no longer extant).

Between 1960 and 1972, rooms within the two 1904 multi-family buildings were rented to various occupants. The names of the occupants and their occupations, if known, are detailed below.

429 S. San Joaquin Street
1965 – Vacant
1970 – Seopoldo Gutierrez, farm worker

429a S. San Joaquin Street
1965 – Leonidez Galeviz
1970 – Quong Wee Lee

431 S. San Joaquin Street
1965 – Olivas Suant, farm worker
1970 – Jenny M. Huante

431a S. San Joaquin Street
1965-1970 – Paul Tearo, retired

435 S. San Joaquin Street
1965 - Vacant
1970-1975 – Abdul S. Ahmad, retired

435a S. San Joaquin Street
1965 – Vacant

437 S. San Joaquin Street

1965 – Vacant
1970 – Janet Hood

1972-1985 From 1972 to 1985, the property was owned by numerous members of the Fong family, including Elizabeth Fong Wills, John Fong, Christopher James Robertson Fong, and Elizabeth Mei Sit Fong Wills. During this time, the units within the two buildings were rented to various occupants. None of the Fong family members lived within the property during this time.

<u>429 S. San Joaquin Street</u>
1975 – Olivias Huante

<u>429a S. San Joaquin Street</u>
1975 – Dina Aguilar, retired

<u>431 S. San Joaquin Street</u>
1975 – Lepoldo Gutierras

<u>431a S. San Joaquin Street</u>
1975 – Gregory Hernandez, retired

<u>435 S. San Joaquin Street</u>
1970-1975 – Abdul S. Ahmad, retired

<u>435b S. San Joaquin Street</u>
1975 – Leopoldo Laue, farm worker

<u>437 S. San Joaquin Street</u>
1975 – Alla and Dee Stewart, retired

1985 – 1989 From 1985 to 1989 the property was owned by numerous members of the Hong family, including Robert W. Hong and Mee Yoke Hong, Haye B. Chan, Conde T. Chan, Bak F. Hong, Judith Hong, Michael Attanasio, and Noreen E. Chan. During this time, the property was rented to various occupants, who are not listed due to lack of information found during the research. None of the Hong family members lived within the property.

1989-2003 Gospel Center 429-431 S. San Joaquin Street

2003-2019 Gospel Center Rescue Mission, Inc.

4. Building, contractor, suppliers: Unknown.

5. Original plans and construction: The original plans were not located, and it is likely they no longer exist.

6. Alterations and additions: No architect or construction firm is associated with any alternations or additions to the two 1904 multi-family buildings.

B. Historical Context

History of Stockton

In 1850, California was admitted to the Union, and on July 23, 1850, the town of Stockton was officially incorporated. The city was named after Commodore Robert F. Stockton, a naval officer who had given Captain Weber his commission in 1846.[8] [9] During the early 1850s, the growth in population not only created land disputes within "El Rancho del Campo de los Franceses", but it also stimulated commercial development in the Central Valley, where the developing town of Stockton is located, and where eager entrepreneurs set up businesses in support of miners and mining operations. Stockton quickly became a supply and transportation center to California's gold mines, and by 1854, it was the fourth largest city in California.[10] By the end of the Gold Rush, in 1855, many of the former gold miners settled in the Central Valley, where they established farms, ranches, and lumber mills in the areas surrounding the town of Stockton.[11] With the successful development of agriculture that thrived in California's Central Valley due to the soil and climate, the city of Stockton grew rapidly, but Stockton's success was also tied to it having the advantage of being situated at the head of a navigable channel with access to the San Francisco Bay, and Stockton businesses prospered from their ability to process and transport agricultural products to the markets of the world.

In 1858, George West acquired the former rancho and established "El Pinal Winery", the first commercial winery in the region. George West arrived in California in 1849 in search of gold; however, he soon turned to farming and growing grapes. George became a pioneer in viticulture in California and produced one of the most successful and well-known wines, a port wine that

[8] Erwin Gustav Gudde, and William Bright, *California Place Names: The Origin and Etymology of Current Geographical Names*. University of California Press. 1998.

[9] Commodore Stockton was also responsible for driving the Mexican forces out of California during the Mexican-American War.

[10] Visit Stockton, *Stockton's History*, accessed 9/12/2021, https://www.visitstockton.org/about-us/stockton-history/.

[11] R. Bailey, *Heart of the Golden Empire: An Illustrated History of Stockton*, Woodland Hills, CA. Windsor Publications, Inc. 1994.

won a special premium at the California State Fair in 1867.[12]

In 1869, the transcontinental railroad route from Promontory Summit in Utah to Sacramento was completed by Central Pacific Railroad (CPRR), which later connected Sacramento with Oakland via Stockton. The Central Pacific employed over 15,000 Chinese immigrants to lay the lines for the railroad. When the transcontinental railroad was finished, the cities in San Joaquin County, including Stockton, saw an increase in the settlement of the newly unemployed Chinese laborers.[13] During this time, many farmers relied on the seasonal labor of Chinese immigrants; however, in 1875, California's senators pressured their fellow lawmakers in Washington D.C. to pass the Page Act, which was an act that "prohibited convicted felons, prostitutes, and Asian contract laborers" from entering the U.S.[14] This resulted in a series of anti-immigrant laws and practices, of which the most sweeping "Anti-Chinese" law was the "Chinese Exclusion Act" of 1882 that banned all Chinese laborers from entering the U.S., with the exception of students, merchants, teachers, travelers, and diplomate.[15] [16] Soon anti-Chinese leagues developed, joining together to prevent the employment of any Chinese laborers, who were thought to be a threat to the employment of European-Americans citizens in the U.S.

By the 1890s, Stockton had grown into a major transportation, commercial, and agricultural center. Several railroads included the Southern Pacific, Santa Fe, Western Pacific, Tidewater Southern, Stockton Terminal & Eastern, and Central California Traction, operated on the rail lines.[17] During this time, the manufacturing of agricultural tools became a major industry in Stockton, and several local inventions revolutionized farming techniques, including the invention of the "Stockton Gang Plow", which allowed more land to be simultaneously plowed with multiple plowshares sold throughout the nation by H.C. Shaw and Co. During this time, Benjamin Holt also invented and sold farm machinery through his business, Holt Manufacturing Company, and in the early 1900s, Holt invented the Caterpillar tractor. Throughout the late 1890s, many other industries, such as flour mills, carriage and wagon factories, iron foundries, and shipyards, flourished in Stockton, making it one of the most industrialized cities in California by the end of the nineteenth century.

By the 1900s, Stockton and the surrounding area consisted of a diverse group of residents,

---

[12] Ernest P. Peninou, "A History of the San Joaquin Viticultural District", originally published in 1965 (republished by Nomis Press, 2004).

[13] James Wager "The San Joaquin and Sierra Nevada Railroad" San Joaquin Historical Society, September 1975.

[14] Adam M. McKeown, *Melancholy Order: Asian Migration and the Globalization of Borders*, (New York: Columbia University Press, 2008) 133-134.

[15] Ibid.

[16] Anti-immigrant laws Congress passed in the late 19th and early twentieth century also included a range of laws barring Chinese from securing business licenses (1872), owning real estate (1872, 1913, 1920), wearing queues (1873), and walking on sidewalks while carrying loads with pole and baskets (1870), prohibition of interracial marriages in California, even women who married Chinese men lost their own U.S. citizenships (1922).

[17] Robert W. Scott, *Stockton's Street Runners*, accessed 9/10/2021, http://railroadsillustrated.com/stocktons-street-runners/.

including Italians, Mexicans, Chinese, Japanese, and Filipinos, who brought their unique cultures to the area. By 1906, Stockton had one of the largest Chinese communities with over 5,000 Chinese and Chinese Americans, with Chinatown situated on East Washington Street in downtown Stockton with its own business, language schools, stores, and other business.[18] During this time, Stockton was also developing into a popular city for families to live and visit. In the 1900s, Oak Park, a picnic area previously known as "Goodwater Grove" became so well known that it drew people from across the state.[19] In 1918, the City of Stockton purchased the 30-acre park and later added an ice rink.

By the 1920s, the City of Stockton included a substantial downtown with civic and commercial buildings lined up along a one-mile stretch of Pacific Avenue, known as the "Miracle Mile", where various shops and amenities were located. In 1924, the University of the Pacific (known initially as the College of the Pacific) relocated its San Jose campus to Stockton, making it the first private four-year university in California.[20] During this time, the Stockton Channel was also bustling with ferry boats and cargo ships.

By the 1930s, the U.S. was in the midst of the Great Depression (1929 – 1933), which created a surge of bank closures, resulting in a decrease of available capital that significantly impacted agricultural communities and led to reduced market prices.[21] However, the city pushed forward with the opening of the "Port of Stockton" in 1933, the first inland seaport in California.[22] Soon, ships from all over the world arrived at the inland port located in the center of one of the nation's richest agricultural areas. By the mid-1930s, the country was emerging from the Great Depression, and in 1933, five days after taking the oath of office, President Franklin Delano Roosevelt called a conference with the secretaries of Agriculture, Interior, and War, along with several others to discuss his ideas for recruiting 500,000 men to work in the nations forests and eroded farmlands. Roosevelt's vision was to provide work opportunities, primarily for young men to repair the land from decades of poor management and over-use, which became known as the "New Deal". As part of the New Deal, on March 31, 1933, the Emergency Conservation Work (ECW) Act was established under Executive Order No. 6101 and created the Civilian Conservation Corps (CCC), the Works Progress Administration (WPA), and the Public Works Administration (PWA). The CCC, WPA, and the PWA were established to create work opportunities that would not interfere with regular employment. As such, they were directed toward the conservation of natural resources

---

[18] Michael Bennett, The San Joaquin Historian, *On-Lock Sam, I the Heart of the Third City*, Published by San Joaquin County Historical Society & Museum, Fall 2000.

[19] Visit Stockton, *Stockton's History*, accessed 9/12/2021, https://www.visitstockton.org/about-us/stockton-history/.

[20] University of the Pacific, *History & Mission*, accessed 9/15/2021, https://www.pacific.edu/about-pacific/history-mission.

[21] Lou Ann Speulda and Rhoda Owen Lewis, "Region 6: Historical and Architectural Assessment of the Depression Era Work Projects", 2002.

[22] The California State Military Museum, *Historic California Posts: Stockton Ordnance Depot,* accessed 9/14/2021, californiamilitaryhistory.org.

and transportation projects.

During the 1930s, the WPA and the PWA constructed many projects in Stockton, including projects at the Port of Stockton, where workers completed general improvement projects including dredging and wharf and warehouse construction.[23] To stabilize the agricultural markets and ensure continued agricultural production, on July 22, 1937, Congress also passed the Bankhead-Jones Farm Tenant Act, which authorized a modest credit program to assist tenant farmers in purchasing land. During this time, tenant farmers lined up to apply for assistance. In addition, agricultural workers were often brought in from other areas to work on farms in Central Valley, including areas within and near Stockton.

The U.S. entered World War II (WWII) on December 9, 1942. Then on February 19, 1942, President Roosevelt signed Executive Order #9066 authorizing the Secretary of War or any military commander designated by the Secretary to establish military areas and to exclude, from any or all person to enter, remain in, or leave shall be subject to whatever restrictions the Secretary of War or the appropriate Military Commander may impose in his discretion. On March 18, 1942, the War Relocation Authority (WRA) was created by Executive Order #9102. The Government Organization Manual of 1942 describes the purpose of WRA:

> "*To provide for removal from designated areas of persons whose removal is necessary in the interest of national security, and for their relocation, maintenance and super-vision ... And to provide insofar as feasible and desirable for the employment of such persons at useful work in industry, commerce, agricultural or public projects, prescribe the terms and conditions of such public employment, and safeguard the public interest in the private employment of such persons.*"[24]

The relocation order in the spring and summer of 1942 resulted in the removal and relocation of approximately 110,000 Japanese-American persons removed from designated locations. Prior to being sent to internment camps, many Japanese Americans were sent to detention centers, one located in Stockton at the San Joaquin County Fairground – the Stockton Assembly Center. The assembly hall included 125 barracks and had over 4,000 people that were confined to the assembly before being sent to internment camps in Arkansas and Arizona.[25] [26] [27] In Stockton, approximately 850 Japanese and Japanese Americans (mainly farmers) were interned.[28]

---

[23] Living the New Deal, *Port of Stockton – Stockton CA*, accessed 9/15/2020, https://livingnewdeal.org/?s=stockton+.

[24] Franklin D. Roosevelt, Executive Order 9102 Establishing the War Relocation Authority. Online by Gerhard Peters and John T. Woolley, The American Presidency Project https://www.presidency.ucsb.edu/node/210476

[25] Kat Elliot "Remembering Japanese American Internment in Stockton", University of Pacific World Press, Feb. 8th 2016 (https://collegeofthepacific.wordpress.com/2016/02/08/remembering-japanese-american-internment/)

[26] Ibid.

[27] The assembly center is listed as part of California Historical Landmark #934, named in 1980.

[28] Newspapers.com, "Stockton Japanese Get Moving Orders", No author, The Sacramento Bee, April 22, 1942.

During WWII, the "Rough and Ready Island Naval Supply Depot" (present-day "Ruff and Ready Island"), which is located on the Stockton Channel approximately 3 miles west of the Port of Stockton, was the location of the former U.S. Navy installation, which was where a supply depot was constructed, supporting the San Joaquin Depot that operated the nearby Tracy Depot Facility and the Sharpe Depot Facility. At the end of WWII, there was a significant surge in commercial and residential development throughout Stockton, particularly in undeveloped areas north and northeast of downtown Stockton. By the 1950s, the City of Stockton included a world-renown civic theater, symphony, ballet, and chorale groups. During the 1960s and 1970s, Stockton continued to expand its boundaries, and nearly all the former agricultural land consisted of new residential housing and commercial development.

History of Multi-Family Housing (ca. 1900–1930)

The two 1904 multi-family buildings within the property were built in the U.S. during a time when multi-family buildings that mimicked houses were being built, particularly in urban neighborhoods, including downtown Stockton. During this time, numerous two-family houses were constructed with identical apartment flats stacked on top of the other, often within a deep narrow parcel. During the early 1900s, the multi-family buildings typically featured architectural details such as clapboards, wood shingle or stucco siding, gabled or hipped roofs with gable roof dormers, angular or square two-story bay windows, decorative Palladian-style windows at the attic, multi-light double-hung wood windows, and prominent front porches.[29] These buildings were designed to allow working-class families to achieve a middle-class quality of life but for less cost. During this time, the early 20th-century working-class neighborhoods often consisted of multi-unit structures, including duplexes, two stacked and three stacked houses, and larger multi-unit apartment complexes.

Part II. Architectural Information

A. General statement

1. Architectural character:

The two multi-family buildings were each constructed in 1904. The buildings demonstrate character-defining features of the Queen Anne Free Classic subtype, including Queen Anne and Colonial Revival architectural elements typical of this subtype from the early 1900s.

2. Condition of fabric:

The condition of the two buildings is good to moderate. Structurally, the two buildings appear to be sound.

[29] Thomas C. Hubka and Judith T. Kenny, "Examining the American Dream: Housing Standards and the Emergence of a National Housing Culture, 1900-1930" *Perspectives in Vernacular Architecture (Vol 13:1, 2006).*

429-431 S. San Joaquin Street

The exterior is clad in narrow wood lap siding and vertical wood siding that is good to fair condition. There is also a cut-out section of the original front porch roof; however, most of the original porch remains intact. The building maintains a majority of its original fenestrations and the original decorative window trim. However, two of the lower windows sashes along the second floor of the primary façade (northeast elevation) have been removed and replaced with aluminum sliding sashes, and the windows along the southwest and northwest elevation consist of replacement aluminum sliding windows. The interior of the building includes original solid wood five panel doors, two sets of wood panel pocket doors, a pivoting solid wood door with steel components, original hardware, built-in cabinetry, and an elaborate fireplace mantel with decorative woodwork and glazed tiles on the first floor. The original wood floors are covered in various flooring materials. Overall, the condition of the building's exterior and interior walls, doors, windows, and decorative elements is fair to good. Currently, the exterior retains a medium level of integrity with a medium level of integrity on the interior with moderate alterations to the fabric.

435-437 S. San Joaquin Street

The exterior is clad in narrow wood lap siding that is good to fair condition. The flat roof front porch support with Tuscan-style wood columns remains intact. The building maintains the majority of its original fenestrations with decorative trim, including a grouping of windows along the primary façade (northeast elevation) consisting of two tall, narrow, double-hung wood windows on each side of a wider double-hung wood window along the first floor, and two double-hung wood windows along the second floor with elaborate wood trim consisting of projecting lintel and decorative dentil. However, four original double-hung wood windows along the southeast façade have replacement vinyl windows, and several windows along this elevation are covered in plywood. The interior of the building consists of original wood panel doors, original hardware, built-in cabinetry, and an elaborate fireplace mantel with decorative woodwork and glazed tiles on the first floor. The original wood floors are covered in various flooring materials. Overall, the condition of the exterior and interior walls, doors, windows, and decorative elements is fair to good. Currently, the exterior retains a medium level of integrity with a medium level of integrity on the interior with moderate alterations to the fabric.

B. Description of Exterior

1. Overall dimensions:

429-431 S. San Joaquin Street

The main form of the building is a two-story rectangular plan. The length of the main rectangle is 57'5" long and 31'5" wide.

435-437 S. San Joaquin Street

The main form of the building is a two-story rectangular plan. The length of the main rectangle is 53'5" long and 20'5" wide.

2. Foundations:

Each of the 1904 multi-family buildings has a concrete slab foundation.

3. Walls:

429-431 S. San Joaquin Street

The wood-framed walls are clad in narrow wood lap siding, and the primary facade roof gable is clad in stucco applied in an unusual pattern, consisting of large dots applied throughout the roof gable. The wood cladding is original and shows minor wear, such as cracking and peeling paint. The stucco is not original to the building and likely replaced original wood or shingle cladding. The decorative motifs within the roof gable, including a centered circular wood-carved wreath-like design and decorative leafing, appear to be original to the building. There is decorative brick veneer along a narrow portion of the front porch wall at the northeast corner of the building, which is not original and was likely added 1990s. The windows along the walls of the building consist of projecting wood trim and elaborate lintels.

435-437 S. San Joaquin Street

The wood-framed walls are clad in narrow wood lap siding. The wood cladding shows minor wear, such as cracking and peeling paint. There is a decorative brick veneer along the entire front porch wall that was likely added in the 1990s and likely covers the original wood cladding. The windows along the walls consist of projecting wood trim and elaborate lintels.

4. Structural system, framing:

The two 1904 multi-family buildings are wood-framed structures, likely constructed with 2x4” studs spaced at 16” on center.

5. Porches, stoops, balconies, porticoes, bulkheads:

429-431 S. San Joaquin Street

The hipped roof front porch is supported by paired wood Tuscan-style columns mounted on top of solid wood railings clad with wood lap siding to match the building’s exterior cladding, except at the northeast end of the porch wall, which is covered in brick veneer. Along the northeast section of the porch are concrete steps flanked by low concrete and wood porch walls and a metal handrail, which is not original to the building, providing access to the front entry door. The porch consists of the original wood shiplap ceiling; however, the porch floor is covered with a contemporary flooring membrane, likely added for safety in the 1990s. Along the rear façade (southwest elevation), an exterior wooden staircase with flat wood handrails and square wood support columns provides access to the first-floor rear entrance porch and a second-floor stair landing. Along the northwest elevation, there are two stair landings, one along the first floor and a second landing that provides access at an intermediate level between the first and second stories of the building.

435-437 S. San Joaquin Street

The flat roof front porch is supported by paired wood Tuscan-style columns mounted on top of solid wood railings clad with wood lap siding that is currently covered in brick veneer. Along the southeast section of the porch are concrete steps flanked by low concrete and wood porch walls, providing access to the two front entry doors, one to the first floor and one to the second floor. The porch consists of the original wood shiplap ceiling; however, the porch floor is covered with a contemporary flooring membrane, likely added for safety in the 1990s. Along the rear façade (southwest elevation), the first floor is a narrow recessed porch with poured concrete steps and solid wood railings topped with square-shaped columns supporting the open "canted style" porch. However, evidence, including hinges and an infilled transom, indicates that the exterior first-floor rear porch was originally enclosed. There is also a second-story landing accessed via a set of wooden stairs.

6. Chimney:

Each of the two 1904 multi-family buildings consists of an interior brick chimney set along the ridgeline of each building.

7. Openings

a. Doorways and doors:

429-431 S. San Joaquin Street

The exterior of the building consists of five doorways and five doors. The doors included one wood panel front door with an integrated lite and wood screen door and four five-panel wood doors.

435-437 S. San Joaquin Street

The exterior of the building consists of four doorways and four doors. The doors included two wood panel front doors with an integrated lite and wood screen door, and two five-panel wood doors.

b. Windows and shutters:

429-431 S. San Joaquin Street

The building maintains approximately half of its original double-hung wood windows; however, two of the lower windows sashes along the second floor of the primary façade (northeast elevation) have been removed and replaced with aluminum sliding sashes, and the majority of the windows along the southwest and northwest elevation consist of replacement aluminum sliding windows. The majority of the windows appear to sit within the original window openings. The original wood windows maintain decorative trim, including projecting lintel and decorative dentil along and wide window trim; however, the replacement windows are cased in flat, narrow, wood window trim.

435-437 S. San Joaquin Street

The building maintains the majority of its original windows, including a grouping of windows along the primary façade (northeast elevation) consisting of two tall, narrow, double-hung wood windows on each

side of a wider double-hung wood window along the first floor, and two double-hung wood windows along the second floor with elaborate wood trim consisting of projecting lintel and decorative dentil. There are wood windows along the side and rear elevations consisting of double-hung wood windows; however, four windows at the west end of the southeast elevation have replacement vinyl windows with flat wood trim. All the windows appear to sit within the original window openings, and the wood windows maintain the original decorative window trim.

8. Roof

a. Shape, covering:

429-431 S. San Joaquin Street

The roof is a moderate pitched front-gabled and hipped roof, clad in composite shingles.

435-437 S. San Joaquin Street

The roof is a moderate pitched front-gabled roof, clad in composite shingles.

b. Cornice, eaves:

429-431 S. San Joaquin Street

The cornice consists of decorative wood modillions and dentils set under flared overhanging eaves.

435-437 S. San Joaquin Street

The cornice consists of decorative wood modillions and dentils set under narrow overhang eaves.

c. Dormers, cupolas, towers:

There are no dormers, cupolas, or towers.

C. Description of Interior

1. Floor plans:

429-431 S. San Joaquin Street

The original floorplan of the building appears to have included two units, one on the first floor and one of the second floor. Currently, the floor plan appears primarily unaltered.

435-437 S. San Joaquin Street

The original floorplan of the building appears to have included four units, two on the first floor and two on the second floor. Currently, the floor plan appears primarily unaltered.

2. Stairways:

429-431 S. San Joaquin Street

The building appears to include one stairway. The stairway is not within the main entrance of the house but is located near the northwest section of the interior floorplan. The stair consists of wood risers and treads.

435-437 S. San Joaquin Street

The building has one interior stairway, accessed via the front entrance door nearest the eastern corner of the northeast elevation (primary façade). The stairs are u-shaped consisting of wood risers and treads that lead to an intermediate landing that then leads to additional stairs that provide access to the second floor.

3. Flooring:

429-431 S. San Joaquin Street

The floors throughout the building utilize various materials, including original wood floors, parquet flooring tiles, sheet vinyl with different patterns, and ceramic tile.

435-437 S. San Joaquin Street

The floors throughout the building utilize various materials, including original wood floors, sheet vinyl with different patterns, and ceramic tile.

4. Wall and ceiling finish:

429-431 S. San Joaquin Street

The interior walls of the building are gypsum wallboard painted white, and vertical wood paneling sheets, which were likely added in the 1960s or 1970s. The ceiling finish appears to be smooth stucco or plaster painted white.

435-437 S. San Joaquin Street

The interior walls of the building are gypsum wallboard painted white. The ceiling finish appears to be smooth stucco or plaster painted white.

5. Openings

a. Doorways and doors:

429-431 S. San Joaquin Street

The interior doorway openings all appear to be original. The doors consist of solid five-paneled wood doors, two sets of large solid wood-paneled pocket doors, and a pivoting solid wood door with steel components.

435-437 S. San Joaquin Street

The interior doorway openings all appear to be original. The doors consist of solid five-paneled wood doors.

b. Windows:

429-431 S. San Joaquin Street

The window openings along the interior walls consist of solid wood trim around all the original wood windows. The window trim around replacement windows is narrow wood trim.

435-437 S. San Joaquin Street

The window openings along the interior walls consist of solid wood trim around all the original wood windows. The window trim around replacement windows is narrow wood trim.

6. Decorative features and trim:

429-431 S. San Joaquin Street

Decorative features include built-in cabinetry, and an elaborate fireplace mantel with decorative woodwork and brown glazed tiles within the living room of the first floor. There are also coved ceilings in the living room and dining room. Throughout the building, there is also wide wood baseboard trim.

435-437 S. San Joaquin Street

Decorative features include built-in cabinetry, and an elaborate fireplace mantel with decorative woodwork and green glazed tiles. Throughout the building, there is also wide wood baseboard trim.

7. Hardware:

429-431 S. San Joaquin Street

The original hardware within the building includes interior doorknobs, hinges, and pulls; however, some doorknobs on exterior doors have been replaced with contemporary doorknobs.

435-437 S. San Joaquin Street

The original hardware within the building includes interior doorknobs, hinges, and pulls; however, some doorknobs on exterior doors have been replaced with contemporary doorknobs.

8. Mechanical equipment:

a. Heating, air conditioning, ventilation:

429-431 S. San Joaquin Street

The building includes portable heating and air conditioning units, some of which are situated within the lower open sashes of window openings. There are also metal foundation vents, and a rectangular metal air vent along the front gable of the roof. An original fireplace is located within the first-floor living room with decorative woodwork and brown glazed tiles.

435-437 S. San Joaquin Street

The building includes portable heating and air conditioning units, some of which are situated within the lower open sashes of window openings. There are metal foundation vents, and a rectangular opening along the front gable of the roof that likely had a vent but it is currently covered in plywood. There is an original fireplace located within the dining room of the first floor of the building with decorative woodwork and green glazed tiles.

b. Lighting:

429-431 S. San Joaquin Street

The lighting fixtures in the building have been replaced with contemporary lighting.

435-437 S. San Joaquin Street

The lighting fixtures in the building have been replaced with contemporary lighting.

c. Plumbing: The plumbing in the two 1904 multi-family buildings is unknown.

9. Original furnishings: N/A

D. Site

1. Historic landscape design:

The two 1904 multi-family buildings are located within a 9,150-square-foot parcel situated on the west side of S. San Joaquin Street between E. Sonora Street and E. Church Street. The two buildings are set back from the streets with minimal landscaping in the front yard of each building, including a grass lawn area and small concrete patio enclosed by a tall metal fence that runs the length of the property adjacent to the northeast elevation. The rear portion of the property is covered in concrete, except for a small section to the northwest of the buildings where trees have been planted. There is an outdoor seating area in the rear with wooden picnic tables and a wood lattice covering located near the southwest corner of the property. At the rear of the buildings, there is a parking lot and a driveway that provides rear access to the buildings via an entrance along E. Church Street.

2. Outbuildings:

There are no outbuildings within the property associated with this HABS document.

Part III. Sources of Information

Bibliography:

Ancestry.com,

Stockton, California, City Directory, 1904.

1910; Census Place: Stockton Ward 1, San Joaquin, California; Roll: T624_103; Page: 7B; Enumeration District: 0127; FHL microfilm: 1374116

Stockton, California, City Directory, 1922.

Stockton City Directory, 1915.

U.S. World War I Draft Registration Card (1917=1918) California; Registration County: Merced County.

Bailey, R, *Heart of the Golden Empire: An Illustrated History of Stockton*, Woodland Hills, CA. Windsor Publications, Inc. 1994.

Bancroft, Hubert Howe. History of California: 1801 – 1924. A.L. Bancroft. 1885.

Bennett, Michael, "On-Lock Sam, I the Heart of the Third City", The San Joaquin Historian, Published by San Joaquin County Historical Society & Museum, Fall 2000.

Kat Elliot "Remembering Japanese American Internment in Stockton", University of Pacific World Press, Feb. 8th 2016, accessed July 29, 2021, https://collegeofthepacific.wordpress.com/2016/02/08/remembering-japanese-american-internment/

Gudde, Erwin Gustav and William Bright, *California Place Names: The Origin and Etymology of Current Geographical Names.* University of California Press. 1998.

Hubka, Thomas C. and Judith T. Kenny, "Examining the American Dream: Housing Standards and the Emergence of a National Housing Culture, 1900-1930" Perspectives in Vernacular Architecture (Vol 13:1, 2006).

Library of Congress. *Historic American Buildings Survey Guidelines for Historical Reports,* Accessed September 15, 2020, and March 12, 2021, http://www.loc.gov/pictures/collection/hh/technote.html.

McAlester, Virginia and Lee McAlester. *A Field Guild to American Houses*. New York: Alfred A. Knopf. 2013.

McKeown, Adam M., Melancholy Order: Asian Migration and the Globalization of Borders, (New York: Columbia University Press, 2008) 133-134.

National Park Service. National Register Bulletin: How to Apply the National Register Criteria for Evaluation. Washington, D.C.: United States Department of the Interior. 1990, revised 1997.

Newspapers.com

"Aged Pioneer Dies", The San Francisco Call San Francisco, California, March 10, 1905.

No author "Stockton Japanese Get Moving Orders", The Sacramento Bee, April 22, 1942.

Office of Historic Preservation

California Historical Landmarks by County. Accessed September 8, 2021, http://ohp.parks.ca.gov/?page_id=21520.

California Inventory of Historical Resources. California Office of Historic Preservation, Sacramento, California. 1976.

Directory of Properties in the Historic Property Data File for Belmont, California, dated 2012. List on file at the Northwest Information Center, Rohnert Park, California. 2012.

Peninou, Ernest P., "A History of the San Joaquin Viticultural District", originally published in 1965 (republished by Nomis Press, 2004).

Scott, Robert W., Stockton's Street Runners, accessed 9/10/2021, http://railroadsillustrated.com/stocktons-street-runners/.

Speulda, Lou Ann and Rhoda Owen Lewis, "Region 6: Historical and Architectural Assessment of the Depression Era Work Projects", 2002.

Tyler, Norman et al. *Historic Preservation, An Introduction to the History, Principals, and Practices*. W.W. Norton & Company, New York, 2009.

University of the Pacific, History & Mission, accessed 9/15/2020, https://www.pacific.edu/about-pacific/history-mission.

Visit Stockton, Stockton's History, accessed September 12, 2021, https://www.visitstockton.org/about-us/stockton-history/.

Wager, James "The San Joaquin and Sierra Nevada Railroad" San Joaquin Historical Society, September 1975.

San Joaquin County Assessor and Recorders Office

Deed records, tax assessment information, and additional documents related to the two 1904 multi-unit houses at 429-431 and 435-437 S. San Joaquin Street, Stockton.

Stockton Historical Museum

Historic photograph and map collections were reviewed for this HABS.

San Jose Public Library

Digital Sanborn maps, 1867-1970. California [electronic resource] on file with the San Jose Public Library were reviewed for this HABS.

A. Architectural drawings:

The following As-Built Documentation included in the report was created and provided by 3D Virtual Design Technology, Inc. The elevations and floorplans are generated using 3D Laser Scanning.


B. Photographs:

During research conducted on the property, no historic photographs were located showing the either of the two 1904 multi-family buildings.

429-431 South San Joaquin Street, Stockton



C1_DAH7553.jpg



C2_DAH7559.jpg




C3_DAH7566.jpg




C4_DAH7586.jpg




D1_DAH7567.jpg




D2_DAH7582.jpg




F1_DAH7554.jpg



F2_DAH7569.jpg




F4_DAH7587.jpg



F4_DAH7592.jpg



I1_DAH7578.jpg




I2_DAH7581.jpg


435-437 South San Joaquin Street, Stockton




C1_DAH7550.jpg



C2_DAH7560.jpg



C3_DAH7563.jpg




C4_DAH7585.jpg




D1_DAH7574.jpg



D2_DAH7572.jpg




D3_DAH7590.jpg



F1_DAH7556.jpg




F2_DAH7583.jpg




F3_DAH7589.jpg



F4_DAH7591.jpg



I1_DAH7570.jpg



I2_DAH7571.jpg

APPENDIX E
CENTRAL CALIFORNIA INFORMATION CENTER REPORT

CENTRAL CALIFORNIA INFORMATION CENTER
California Historical Resources Information System
Department of Anthropology – California State University, Stanislaus
One University Circle, Turlock, California 95382
(209) 667-3307

Alpine, Calaveras, Mariposa, Merced, San Joaquin, Stanislaus & Tuolumne Counties

Date: 7/20/2021

Records Search File#: #11887L
Project: Gospel Center Men's Dorm
435/437 S. San Joaquin Street, Stockton, CA 95203

Rayanna Beck
BaseCamp Environmental, Inc.
802 W. Lodi Ave.
Lodi, CA 95240
209-224-8213

rbeck@basecampenv.com

Dear Ms. Beck:

We have conducted a non-confidential extended records search as per your request for the above-referenced project area located on the Stockton West USGS 7.5-minute quadrangle map in San Joaquin County.

Search of our files includes review of our maps for the specific project area and the immediate vicinity of the project area, and review of the following:

National Register of Historic Places (NRHP)
California Register of Historical Resources (CRHR)
California Inventory of Historic Resources (1976)
California Historical Landmarks
California Points of Historical Interest listing
Office of Historic Preservation Built Environment Resource Directory (BERD) and the Archaeological Determinations of Eligibility (ADOE)
Survey of Surveys (1989)
Caltrans State and Local Bridges Inventory
General Land Office Plats
Other pertinent historic data available at the CCaIC for each specific county

The following details the results of the records search:

Prehistoric or historic resources within the project area:

- There are no formally recorded prehistoric or historic archaeological resources within the project area.

- The Office of Historic Preservation Built Environment Resource Directory (BERD) (dated 12/19/2019) lists P-39-002402, the Wills House, at 435 S. San Joaquin Street,

Stockton (Historic Resource Inventory number 5208-1518-0000). The residence was constructed in 1904 and has a National Register of Historic Places evaluation rating of "5S2": "Individual property that is eligible for local listing or designation."

- The General Land Office Survey Plat for T1N R6E (dated 1879) shows the project area within the Rancho Campo de los Franceses Mexican land grant.

- Map Number Two in *History of San Joaquin County California with Illustrations* (1979; 1968 reprint), the Map of the County of San Joaquin, California (1883), and the 1913 edition of the Stockton 15' USGS map show the project area within the City of Stockton street layout.

Prehistoric or historic resources within the immediate vicinity of the project area:

- There are no formally recorded prehistoric or historic archaeological resources within the immediate vicinity of the project area, but we do advise you that such features have been recorded elsewhere within the boundary of the Stockton West USGS quadrangle.

- Properties at 429, 440, and 445 S. San Joaquin Street, Stockton, are also listed with National Register of Historic Places ratings of 5S2 in the Office of Historic Preservation Built Environment Resource Directory (BERD).

Resources that are known to have value to local cultural groups: None has been formally reported to the Information Center.

Previous investigations within the project area: The historic buildings referenced were recorded during an Office of Historic Preservation sponsored historic resource inventory reported upon in the following three documents:

CCaIC Report SJ-02219
Stockton, City of (City of Stockton)
1979 *Historic Survey Project Agreement, Final Report; Project Period June 1, 1978 to March 31, 1979.*

CCaIC Report SJ-02246

Hermenau, H. (City of Stockton)
1980 *Completion Report, Historic Survey Project Agreement No. 36-09-006, Stockton, California; Project Period April 1, 1979 to March 31, 1980.*

CCaIC Report SJ-02247

Rapp, Linda (City of Stockton)
1980 *Stockton Historic Resource Inventory II: Analysis Report, June 1980.*

Recommendations/Comments:

Please be advised that a historical resource is defined as a building, structure, object, prehistoric or historic archaeological site, or district possessing physical evidence of human activities over 45 years old. Such resources can be manifested on the surface or in subsurface context.

If the current project does not include ground disturbance, further study for archaeological resources is not recommended at this time. If ground disturbance is considered a part of the current project, we recommend further review for the possibility of identifying prehistoric or historic-era archaeological resources.

If the proposed project contains buildings or structures that meet the minimum age requirement (45 years in age or older) it is recommended that the resource/s be assessed by a professional familiar with architecture and history of the county. Review of the available historic building/structure data has included only those sources listed above and should not be considered comprehensive.

If at any time you might require the services of a qualified professional the Statewide Referral List for Historical Resources Consultants is posted for your use on the internet at http://chrisinfo.org

If archaeological resources are encountered during project-related activities**,** work should be temporarily halted in the vicinity of the discovered materials and workers should avoid altering the materials and their context until a qualified professional archaeologist has evaluated the situation and provided appropriate recommendations. Project personnel should not collect cultural resources.

If human remains are discovered, California Health and Safety Code Section 7050.5 requires you to protect the discovery and notify the county coroner, who will determine if the find is Native American. If the remains are recognized as Native American, the coroner shall then notify the Native American Heritage Commission (NAHC). California Public Resources Code Section 5097.98 authorizes the NAHC to appoint a Most Likely Descendant (MLD) who will make recommendations for the treatment of the discovery.

Due to processing delays and other factors, not all of the historical resource reports and resource records that have been submitted to the State Office of Historic Preservation are available via this records search. Additional information may be available through the federal, state, and local agencies that produced or paid for historical resource management work in the search area. Additionally, Native American tribes have historical resource information not in the CHRIS Inventory, and you should contact the California Native American Heritage Commission for information on local/regional tribal contacts.

The California Office of Historic Preservation (OHP) contracts with the California Historical Resources Information System's (CHRIS) regional Information Centers (ICs) to maintain information in the CHRIS inventory and make it available to local, state, and federal agencies, cultural resource professionals, Native American tribes, researchers, and the public.

Recommendations made by IC coordinators or their staff regarding the interpretation and application of this information are advisory only. Such recommendations do not necessarily represent the evaluation or opinion of the State Historic Preservation Officer in carrying out the OHP's regulatory authority under federal and state law.

We thank you for contacting this office regarding historical resource preservation. Please let us know when we can be of further service. Thank you for submitting the completed **Access Agreement Short Form.**

Note: Billing will be transmitted separately via email from the Financial Services office ($150.00), payable within 60 days of receipt of the invoice.

If you wish to include payment by Credit Card, you must wait to receive the official invoice from Financial Services so that you can reference the CMP # (Invoice Number), and then contact the link below:

https://commerce.cashnet.com/ANTHROPOLOGY

Sincerely,

E. A. Greathouse

E. A. Greathouse, Coordinator
Central California Information Center
California Historical Resources Information System

* Invoice Request sent to: ARBilling@csustan.edu, CSU Stanislaus Financial Services

APPENDIX F
BIOLOGICAL DATABASE REPORTS

Element_Typ	Scientific_Na	Common_Na	Element_Coc	Federal_Stat	State_Status	CDFW_Statu	CA_Rare_Pla	Quad_Code	Quad_Name	Data_Status	Taxonomic_Sort
Animals - An	Ambystoma	California tig	AAAAA01181	Threatened	Threatened	WL	-	3712183	STOCKTON W	Mapped	Animals - Amphibians - Ambystomatidae - Ambystoma californiense pop. 1
Animals - An	Spea hammc	western spa	AAABF02020	None	None	SSC	-	3712183	STOCKTON W	Mapped	Animals - Amphibians - Scaphiopodidae - Spea hammondii
Animals - Bir	Accipiter coo	Cooper's hav	ABNKC12040	None	None	WL	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Accipitridae - Accipiter cooperii
Animals - Bir	Buteo swains	Swainson's h	ABNKC19070	None	Threatened	-	-	3712183	STOCKTON W	Mapped and	Animals - Birds - Accipitridae - Buteo swainsoni
Animals - Bir	Elanus leucu	white-tailed	ABNKC06010	None	None	FP	-	3712183	STOCKTON W	Mapped	Animals - Birds - Accipitridae - Elanus leucurus
Animals - Bir	Ardea alba	great egret	ABNGA04040	None	None	-	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Ardeidae - Ardea alba
Animals - Bir	Ardea herodi	great blue he	ABNGA04010	None	None	-	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Ardeidae - Ardea herodias
Animals - Bir	Charadrius m	mountain plo	ABNNB03100	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Charadriidae - Charadrius montanus
Animals - Bir	Pica nuttalli	yellow-billed	ABPAV09020	None	None	-	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Corvidae - Pica nuttalli
Animals - Bir	Progne subis	purple marti	ABPAU01010	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Hirundinidae - Progne subis
Animals - Bir	Agelaius tric	tricolored bla	ABPBXB0020	None	Threatened	SSC	-	3712183	STOCKTON W	Mapped	Animals - Birds - Icteridae - Agelaius tricolor
Animals - Bir	Icteria virens	yellow-breas	ABPBX24010	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Icteriidae - Icteria virens
Animals - Bir	Setophaga pe	yellow warbl	ABPBX03010	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Parulidae - Setophaga petechia
Animals - Bir	Asio flamme	short-eared o	ABNSB13040	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Birds - Strigidae - Asio flammeus
Animals - Bir	Athene cunic	burrowing ov	ABNSB10010	None	None	SSC	-	3712183	STOCKTON W	Mapped and	Animals - Birds - Strigidae - Athene cunicularia
Animals - Bir	Vireo bellii p	least Bell's v	ABPBW0111	Endangered	Endangered	-	-	3712183	STOCKTON W	Mapped	Animals - Birds - Vireonidae - Vireo bellii pusillus
Animals - Fis	Acipenser tra	white sturge	AFCAA01050	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Acipenseridae - Acipenser transmontanus
Animals - Fis	Lavinia exilic	Sacramento	AFCJB19012	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Cyprinidae - Lavinia exilicauda exilicauda
Animals - Fis	Pogonichthys	Sacramento	AFCJB34020	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Cyprinidae - Pogonichthys macrolepidotus
Animals - Fis	Hypomesus t	Delta smelt	AFCHB01040	Threatened	Endangered	-	-	3712183	STOCKTON W	Mapped and	Animals - Fish - Osmeridae - Hypomesus transpacificus
Animals - Fis	Spirinchus th	longfin smel	AFCHB03010	Candidate	Threatened	-	-	3712183	STOCKTON W	Mapped	Animals - Fish - Osmeridae - Spirinchus thaleichthys
Animals - Fis	Entosphenus	Pacific lampı	AFBAA02100	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Petromyzontidae - Entosphenus tridentatus
Animals - Fis	Lampetra ayı	western rive	AFBAA02030	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Petromyzontidae - Lampetra ayresii
Animals - Fis	Oncorhynchu	steelhead - C	AFCHA0209K	Threatened	None	-	-	3712183	STOCKTON W	Mapped	Animals - Fish - Salmonidae - Oncorhynchus mykiss irideus pop. 11
Animals - Fis	Oncorhynchu	chinook salm	AFCHA0205L	Threatened	Threatened	-	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Salmonidae - Oncorhynchus tshawytscha pop. 11
Animals - Fis	Oncorhynchu	chinook salm	AFCHA0205N	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Fish - Salmonidae - Oncorhynchus tshawytscha pop. 13
Animals - Mo	Anodonta cal	California flo	IMBIV04220	None	None	-	-	3712183	STOCKTON W	Unprocessed	Animals - Mollusks - Unionidae - Anodonta californiensis
Animals - Mo	Anodonta ore	Oregon float	IMBIV04110	None	None	-	-	3712183	STOCKTON W	Unprocessed	Animals - Mollusks - Unionidae - Anodonta oregonensis
Animals - Mo	Gonidea ang	western ridg	IMBIV19010	None	None	-	-	3712183	STOCKTON W	Mapped	Animals - Mollusks - Unionidae - Gonidea angulata
Animals - Re	Emys marmo	western pon	ARAAD02030	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Reptiles - Emydidae - Emys marmorata
Animals - Re	Thamnophis	giant garters	ARADB3615(	Threatened	Threatened	-	-	3712183	STOCKTON W	Mapped	Animals - Reptiles - Natricidae - Thamnophis gigas
Animals - Re	Phrynosoma	coast horned	ARACF12100	None	None	SSC	-	3712183	STOCKTON W	Unprocessed	Animals - Reptiles - Phrynosomatidae - Phrynosoma blainvillii
Plants - Vasc	Sagittaria sa	Sanford's arr	PMALI040Q0	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Alismataceae - Sagittaria sanfordii
Plants - Vasc	Blepharizoni	big tarplant	PDAST1C011	None	None	-	1B.1	3712183	STOCKTON W	Mapped	Plants - Vascular - Asteraceae - Blepharizonia plumosa
Plants - Vasc	Symphyotrich	Suisun Marsl	PDASTE8470	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Asteraceae - Symphyotrichum lentum
Plants - Vasc	Brasenia sch	watershield	PDCAB01010	None	None	-	2B.3	3712183	STOCKTON W	Mapped	Plants - Vascular - Cabombaceae - Brasenia schreberi
Plants - Vasc	Atriplex cord	heartscale	PDCHE040B0	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Chenopodiaceae - Atriplex cordulata var. cordulata
Plants - Vasc	Extriplex joa	San Joaquin	PDCHE041F3	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Chenopodiaceae - Extriplex joaquinana
Plants - Vasc	Astragalus te	alkali milk-ve	PDFAB0F8R1	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Fabaceae - Astragalus tener var. tener
Plants - Vasc	Lathyrus jeps	Delta tule pe	PDFAB250D2	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Fabaceae - Lathyrus jepsonii var. jepsonii
Plants - Vasc	Trifolium hyc	saline clover	PDFAB400R5	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Fabaceae - Trifolium hydrophilum
Plants - Vasc	Hibiscus lasi	woolly rose-r	PDMAL0H0R2	None	None	-	1B.2	3712183	STOCKTON W	Mapped	Plants - Vascular - Malvaceae - Hibiscus lasiocarpos var. occidentalis
Plants - Vasc	Chloropyron	palmate-bra	PDSCR0J0J0	Endangered	Endangered	-	1B.1	3712183	STOCKTON W	Mapped	Plants - Vascular - Orobanchaceae - Chloropyron palmatum

IPaC **U.S. Fish & Wildlife Service**

IPaC resource list

This report is an automatically generated list of species and other resources such as critical habitat (collectively referred to as *trust resources*) under the U.S. Fish and Wildlife Service's (USFWS) jurisdiction that are known or expected to be on or near the project area referenced below. The list may also include trust resources that occur outside of the project area, but that could potentially be directly or indirectly affected by activities in the project area. However, determining the likelihood and extent of effects a project may have on trust resources typically requires gathering additional site-specific (e.g., vegetation/species surveys) and project-specific (e.g., magnitude and timing of proposed activities) information.

Below is a summary of the project information you provided and contact information for the USFWS office(s) with jurisdiction in the defined project area. Please read the introduction to each section that follows (Endangered Species, Migratory Birds, USFWS Facilities, and NWI Wetlands) for additional information applicable to the trust resources addressed in that section.

Location

San Joaquin County, California



NOT FOR CONSULTATION

Local office

Sacramento Fish And Wildlife Office

(916) 414-6600
(916) 414-6713

Federal Building
2800 Cottage Way, Room W-2605
Sacramento, CA 95825-1846

NOT FOR CONSULTATION

Endangered species

This resource list is for informational purposes only and does not constitute an analysis of project level impacts.

The primary information used to generate this list is the known or expected range of each species. Additional areas of influence (AOI) for species are also considered. An AOI includes areas outside of the species range if the species could be indirectly affected by activities in that area (e.g., placing a dam upstream of a fish population, even if that fish does not occur at the dam site, may indirectly impact the species by reducing or eliminating water flow downstream). Because species can move, and site conditions can change, the species on this list are not guaranteed to be found on or near the project area. To fully determine any potential effects to species, additional site-specific and project-specific information is often required.

Section 7 of the Endangered Species Act **requires** Federal agencies to "request of the Secretary information whether any species which is listed or proposed to be listed may be present in the area of such proposed action" for any project that is conducted, permitted, funded, or licensed by any Federal agency. A letter from the local office and a species list which fulfills this requirement can **only** be obtained by requesting an official species list from either the Regulatory Review section in IPaC (see directions below) or from the local field office directly.

For project evaluations that require USFWS concurrence/review, please return to the IPaC website and request an official species list by doing the following:

1. Draw the project location and click CONTINUE.
2. Click DEFINE PROJECT.
3. Log in (if directed to do so).
4. Provide a name and description for your project.
5. Click REQUEST SPECIES LIST.

Listed species[1] and their critical habitats are managed by the Ecological Services Program of the U.S. Fish and Wildlife Service (USFWS) and the fisheries division of the National Oceanic and Atmospheric Administration (NOAA Fisheries[2]).

Species and critical habitats under the sole responsibility of NOAA Fisheries are **not** shown on this list. Please contact NOAA Fisheries for species under their jurisdiction.

NOT FOR CONSULTATION

1. Species listed under the Endangered Species Act are threatened or endangered; IPaC also shows species that are candidates, or proposed, for listing. See the listing status page for more information.
2. NOAA Fisheries, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce.

The following species are potentially affected by activities in this location:

Mammals

NAME	STATUS
Riparian Brush Rabbit Sylvilagus bachmani riparius No critical habitat has been designated for this species. https://ecos.fws.gov/ecp/species/6189	Endangered

Reptiles

NAME	STATUS
Giant Garter Snake Thamnophis gigas No critical habitat has been designated for this species. https://ecos.fws.gov/ecp/species/4482	Threatened

Amphibians

NAME	STATUS
California Red-legged Frog Rana draytonii There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/2891	Threatened
California Tiger Salamander Ambystoma californiense There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/2076	Threatened

NOT FOR CONSULTATION

Fishes

NAME	STATUS
Delta Smelt Hypomesus transpacificus There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/321	Threatened

Insects

NAME	STATUS
Valley Elderberry Longhorn Beetle Desmocerus californicus dimorphus There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/7850	Threatened

Crustaceans

NAME	STATUS
Vernal Pool Fairy Shrimp Branchinecta lynchi There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/498	Threatened
Vernal Pool Tadpole Shrimp Lepidurus packardi There is **final** critical habitat for this species. Your location is outside the critical habitat. https://ecos.fws.gov/ecp/species/2246	Endangered

Flowering Plants

NAME	STATUS
Palmate-bracted Bird's Beak Cordylanthus palmatus No critical habitat has been designated for this species. https://ecos.fws.gov/ecp/species/1616	Endangered

NOT FOR CONSULTATION

Critical habitats

Potential effects to critical habitat(s) in this location must be analyzed along with the endangered species themselves.

THERE ARE NO CRITICAL HABITATS AT THIS LOCATION.

Migratory birds

Certain birds are protected under the Migratory Bird Treaty Act[1] and the Bald and Golden Eagle Protection Act[2].

Any person or organization who plans or conducts activities that may result in impacts to migratory birds, eagles, and their habitats should follow appropriate regulations and consider implementing appropriate conservation measures, as described below.

1. The Migratory Birds Treaty Act of 1918.
2. The Bald and Golden Eagle Protection Act of 1940.

Additional information can be found using the following links:

- Birds of Conservation Concern http://www.fws.gov/birds/management/managed-species/birds-of-conservation-concern.php
- Measures for avoiding and minimizing impacts to birds http://www.fws.gov/birds/management/project-assessment-tools-and-guidance/conservation-measures.php
- Nationwide conservation measures for birds http://www.fws.gov/migratorybirds/pdf/management/nationwidestandardconservationmeasures.pdf

The birds listed below are birds of particular concern either because they occur on the USFWS Birds of Conservation Concern (BCC) list or warrant special attention in your project location. To learn more about the levels of concern for birds on your list and how this list is generated, see the FAQ below. This is not a list of every bird you may find in this location, nor a guarantee that every bird on this list will be found in your project area. To see exact locations of where birders and the general public have sighted birds in and around your project area, visit the E-bird data mapping tool (Tip: enter your location, desired date

NOT FOR CONSULTATION

range and a species on your list). For projects that occur off the Atlantic Coast, additional maps and models detailing the relative occurrence and abundance of bird species on your list are available. Links to additional information about Atlantic Coast birds, and other important information about your migratory bird list, including how to properly interpret and use your migratory bird report, can be found below.

For guidance on when to schedule activities or implement avoidance and minimization measures to reduce impacts to migratory birds on your list, click on the PROBABILITY OF PRESENCE SUMMARY at the top of your list to see when these birds are most likely to be present and breeding in your project area.

NAME	BREEDING SEASON (IF A BREEDING SEASON IS INDICATED FOR A BIRD ON YOUR LIST, THE BIRD MAY BREED IN YOUR PROJECT AREA SOMETIME WITHIN THE TIMEFRAME SPECIFIED, WHICH IS A VERY LIBERAL ESTIMATE OF THE DATES INSIDE WHICH THE BIRD BREEDS ACROSS ITS ENTIRE RANGE. "BREEDS ELSEWHERE" INDICATES THAT THE BIRD DOES NOT LIKELY BREED IN YOUR PROJECT AREA.)
Lawrence's Goldfinch Carduelis lawrencei This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/9464	Breeds Mar 20 to Sep 20
Long-billed Curlew Numenius americanus This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska. https://ecos.fws.gov/ecp/species/5511	Breeds elsewhere
Nuttall's Woodpecker Picoides nuttallii This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA https://ecos.fws.gov/ecp/species/9410	Breeds Apr 1 to Jul 20

NOT FOR CONSULTATION

Oak Titmouse Baeolophus inornatus — Breeds Mar 15 to Jul 15
This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.
https://ecos.fws.gov/ecp/species/9656

Song Sparrow Melospiza melodia — Breeds Feb 20 to Sep 5
This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA

Spotted Towhee Pipilo maculatus clementae — Breeds Apr 15 to Jul 20
This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA
https://ecos.fws.gov/ecp/species/4243

Yellow-billed Magpie Pica nuttalli — Breeds Apr 1 to Jul 31
This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.
https://ecos.fws.gov/ecp/species/9726

Probability of Presence Summary

The graphs below provide our best understanding of when birds of concern are most likely to be present in your project area. This information can be used to tailor and schedule your project activities to avoid or minimize impacts to birds. Please make sure you read and understand the FAQ "Proper Interpretation and Use of Your Migratory Bird Report" before using or attempting to interpret this report.

Probability of Presence (■)

Each green bar represents the bird's relative probability of presence in the 10km grid cell(s) your project overlaps during a particular week of the year. (A year is represented as 12 4-week months.) A taller bar indicates a higher probability of species presence. The survey effort (see below) can be used to establish a level of confidence in the presence score. One can have higher confidence in the presence score if the corresponding survey effort is also high.

How is the probability of presence score calculated? The calculation is done in three steps:

NOT FOR CONSULTATION

1. The probability of presence for each week is calculated as the number of survey events in the week where the species was detected divided by the total number of survey events for that week. For example, if in week 12 there were 20 survey events and the Spotted Towhee was found in 5 of them, the probability of presence of the Spotted Towhee in week 12 is 0.25.
2. To properly present the pattern of presence across the year, the relative probability of presence is calculated. This is the probability of presence divided by the maximum probability of presence across all weeks. For example, imagine the probability of presence in week 20 for the Spotted Towhee is 0.05, and that the probability of presence at week 12 (0.25) is the maximum of any week of the year. The relative probability of presence on week 12 is 0.25/0.25 = 1; at week 20 it is 0.05/0.25 = 0.2.
3. The relative probability of presence calculated in the previous step undergoes a statistical conversion so that all possible values fall between 0 and 10, inclusive. This is the probability of presence score.

To see a bar's probability of presence score, simply hover your mouse cursor over the bar.


Breeding Season (▪)
Yellow bars denote a very liberal estimate of the time-frame inside which the bird breeds across its entire range. If there are no yellow bars shown for a bird, it does not breed in your project area.

Survey Effort (|)
Vertical black lines superimposed on probability of presence bars indicate the number of surveys performed for that species in the 10km grid cell(s) your project area overlaps. The number of surveys is expressed as a range, for example, 33 to 64 surveys.

To see a bar's survey effort range, simply hover your mouse cursor over the bar.


No Data (–)
A week is marked as having no data if there were no survey events for that week.

Survey Timeframe
Surveys from only the last 10 years are used in order to ensure delivery of currently relevant information. The exception to this is areas off the Atlantic coast, where bird returns are based on all years of available data, since data in these areas is currently much more sparse.



NOT FOR CONSULTATION


Lawrence's Goldfinch
BCC Rangewide (CON) (This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.)



Long-billed Curlew
BCC Rangewide (CON) (This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.)



Nuttall's Woodpecker
BCC - BCR (This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA)



Oak Titmouse
BCC Rangewide (CON) (This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.)



Song Sparrow
BCC - BCR (This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA)



Spotted Towhee
BCC - BCR (This is a Bird of Conservation Concern (BCC) only in particular Bird Conservation Regions (BCRs) in the continental USA)



Yellow-billed Magpie
BCC Rangewide (CON) (This is a Bird of Conservation Concern (BCC) throughout its range in the continental USA and Alaska.)



NOT FOR CONSULTATION

Tell me more about conservation measures I can implement to avoid or minimize impacts to migratory birds.

Nationwide Conservation Measures describes measures that can help avoid and minimize impacts to all birds at any location year round. Implementation of these measures is particularly important when birds are most likely to occur in the project area. When birds may be breeding in the area, identifying the locations of any active nests and avoiding their destruction is a very helpful impact minimization measure. To see when birds are most likely to occur and be breeding in your project area, view the Probability of Presence Summary. Additional measures and/or permits may be advisable depending on the type of activity you are conducting and the type of infrastructure or bird species present on your project site.

What does IPaC use to generate the migratory birds potentially occurring in my specified location?

The Migratory Bird Resource List is comprised of USFWS Birds of Conservation Concern (BCC) and other species that may warrant special attention in your project location.

The migratory bird list generated for your project is derived from data provided by the Avian Knowledge Network (AKN). The AKN data is based on a growing collection of survey, banding, and citizen science datasets and is queried and filtered to return a list of those birds reported as occurring in the 10km grid cell(s) which your project intersects, and that have been identified as warranting special attention because they are a BCC species in that area, an eagle (Eagle Act requirements may apply), or a species that has a particular vulnerability to offshore activities or development.

Again, the Migratory Bird Resource list includes only a subset of birds that may occur in your project area. It is not representative of all birds that may occur in your project area. To get a list of all birds potentially present in your project area, please visit the E-bird Explore Data Tool.

What does IPaC use to generate the probability of presence graphs for the migratory birds potentially occurring in my specified location?

The probability of presence graphs associated with your migratory bird list are based on data provided by the Avian Knowledge Network (AKN). This data is derived from a growing collection of survey, banding, and citizen science datasets .

Probability of presence data is continuously being updated as new and better information becomes available. To learn more about how the probability of presence graphs are produced and how to interpret them, go the Probability of Presence Summary and then click on the "Tell me about these graphs" link.

How do I know if a bird is breeding, wintering, migrating or present year-round in my project area?

To see what part of a particular bird's range your project area falls within (i.e. breeding, wintering, migrating or year-round), you may refer to the following resources: The Cornell Lab of Ornithology All About Birds Bird Guide, or (if you are unsuccessful in locating the bird of interest there), the Cornell Lab of Ornithology Neotropical Birds guide. If a bird on your migratory bird species list has a breeding season associated with it, if that bird does occur in your project area, there may be nests present at some point within the timeframe specified. If "Breeds elsewhere" is indicated, then the bird likely does not breed in your project area.

NOT FOR CONSULTATION

What are the levels of concern for migratory birds?

Migratory birds delivered through IPaC fall into the following distinct categories of concern:

1. "BCC Rangewide" birds are Birds of Conservation Concern (BCC) that are of concern throughout their range anywhere within the USA (including Hawaii, the Pacific Islands, Puerto Rico, and the Virgin Islands);
2. "BCC - BCR" birds are BCCs that are of concern only in particular Bird Conservation Regions (BCRs) in the continental USA; and
3. "Non-BCC - Vulnerable" birds are not BCC species in your project area, but appear on your list either because of the Eagle Act requirements (for eagles) or (for non-eagles) potential susceptibilities in offshore areas from certain types of development or activities (e.g. offshore energy development or longline fishing).

Although it is important to try to avoid and minimize impacts to all birds, efforts should be made, in particular, to avoid and minimize impacts to the birds on this list, especially eagles and BCC species of rangewide concern. For more information on conservation measures you can implement to help avoid and minimize migratory bird impacts and requirements for eagles, please see the FAQs for these topics.

Details about birds that are potentially affected by offshore projects

For additional details about the relative occurrence and abundance of both individual bird species and groups of bird species within your project area off the Atlantic Coast, please visit the Northeast Ocean Data Portal. The Portal also offers data and information about other taxa besides birds that may be helpful to you in your project review. Alternately, you may download the bird model results files underlying the portal maps through the NOAA NCCOS Integrative Statistical Modeling and Predictive Mapping of Marine Bird Distributions and Abundance on the Atlantic Outer Continental Shelf project webpage.

Bird tracking data can also provide additional details about occurrence and habitat use throughout the year, including migration. Models relying on survey data may not include this information. For additional information on marine bird tracking data, see the Diving Bird Study and the nanotag studies or contact Caleb Spiegel or Pam Loring.

What if I have eagles on my list?

If your project has the potential to disturb or kill eagles, you may need to obtain a permit to avoid violating the Eagle Act should such impacts occur.

Proper Interpretation and Use of Your Migratory Bird Report

The migratory bird list generated is not a list of all birds in your project area, only a subset of birds of priority concern. To learn more about how your list is generated, and see options for identifying what other birds may be in your project area, please see the FAQ “What does IPaC use to generate the migratory birds potentially occurring in my specified location”. Please be aware this report provides the “probability of presence” of birds within the 10 km grid cell(s) that overlap your project; not your exact project footprint. On the graphs provided, please also look carefully at the survey effort (indicated by the black vertical bar) and for the existence of the “no data” indicator (a red horizontal bar). A high survey effort is the key component. If the survey effort is high, then the probability of presence score can be viewed as more dependable. In

NOT FOR CONSULTATION

contrast, a low survey effort bar or no data bar means a lack of data and, therefore, a lack of certainty about presence of the species. This list is not perfect; it is simply a starting point for identifying what birds of concern have the potential to be in your project area, when they might be there, and if they might be breeding (which means nests might be present). The list helps you know what to look for to confirm presence, and helps guide you in knowing when to implement conservation measures to avoid or minimize potential impacts from your project activities, should presence be confirmed. To learn more about conservation measures, visit the FAQ "Tell me about conservation measures I can implement to avoid or minimize impacts to migratory birds" at the bottom of your migratory bird trust resources page.

Facilities

Wildlife refuges and fish hatcheries

REFUGE AND FISH HATCHERY INFORMATION IS NOT AVAILABLE AT THIS TIME

Wetlands in the National Wetlands Inventory

Impacts to NWI wetlands and other aquatic habitats may be subject to regulation under Section 404 of the Clean Water Act, or other State/Federal statutes.

For more information please contact the Regulatory Program of the local U.S. Army Corps of Engineers District.

THERE ARE NO KNOWN WETLANDS AT THIS LOCATION.

Data limitations

The Service's objective of mapping wetlands and deepwater habitats is to produce reconnaissance level information on the location, type and size of these resources. The maps are prepared from the analysis of high altitude imagery. Wetlands are identified based on vegetation, visible hydrology and geography. A margin of error is inherent in the use of imagery; thus, detailed on-the-ground inspection of any particular site may result in revision of the wetland boundaries or classification established through image analysis.

The accuracy of image interpretation depends on the quality of the imagery, the experience of the image analysts, the amount and quality of the collateral data and the amount of ground truth verification work conducted. Metadata should be consulted to determine the date of the source imagery used and any mapping problems.

NOT FOR CONSULTATION

Wetlands or other mapped features may have changed since the date of the imagery or field work. There may be occasional differences in polygon boundaries or classifications between the information depicted on the map and the actual conditions on site.

Data exclusions

Certain wetland habitats are excluded from the National mapping program because of the limitations of aerial imagery as the primary data source used to detect wetlands. These habitats include seagrasses or submerged aquatic vegetation that are found in the intertidal and subtidal zones of estuaries and nearshore coastal waters. Some deepwater reef communities (coral or tuberficid worm reefs) have also been excluded from the inventory. These habitats, because of their depth, go undetected by aerial imagery.

Data precautions

Federal, state, and local regulatory agencies with jurisdiction over wetlands may define and describe wetlands in a different manner than that used in this inventory. There is no attempt, in either the design or products of this inventory, to define the limits of proprietary jurisdiction of any Federal, state, or local government or to establish the geographical scope of the regulatory programs of government agencies. Persons intending to engage in activities involving modifications within or adjacent to wetland areas should seek the advice of appropriate federal, state, or local agencies concerning specified agency regulatory programs and proprietary jurisdictions that may affect such activities.

NOT FOR CONSULTATION

APPENDIX G
AB 52 NOTIFICATION AND INFORMATION

NATIVE AMERICAN HERITAGE COMMISSION

CHAIRPERSON
Laura Miranda
Luiseño

VICE CHAIRPERSON
Reginald Pagaling
Chumash

PARLIAMENTARIAN
Russell Attebery
Karuk

COMMISSIONER
William Mungary
Paiute/White Mountain Apache

COMMISSIONER
Isaac Bojorquez
Ohlone-Costanoan

COMMISSIONER
Sara Dutschke
Miwok

COMMISSIONER
Buffy McQuillen
Yokayo Pomo, Yuki, Nomlaki

COMMISSIONER
Wayne Nelson
Luiseño

COMMISSIONER
Stanley Rodriguez
Kumeyaay

EXECUTIVE SECRETARY
Christina Snider
Pomo

NAHC HEADQUARTERS
1550 Harbor Boulevard
Suite 100
West Sacramento,
California 95691
(916) 373-3710
nahc@nahc.ca.gov
NAHC.ca.gov

January 25, 2022

Rayanna Beck
BaseCamp Environmental, Inc.

Via Email to: rbeck@basecampenv.com

Re: Gospel Center Rescue Mission New Life Men's Homeless Shelter Project, San Joaquin County

Dear Ms. Beck:

A record search of the Native American Heritage Commission (NAHC) Sacred Lands File (SLF) was completed for the information you have submitted for the above referenced project. The results were negative. However, the absence of specific site information in the SLF does not indicate the absence of cultural resources in any project area. Other sources of cultural resources should also be contacted for information regarding known and recorded sites.

Attached is a list of Native American tribes who may also have knowledge of cultural resources in the project area. This list should provide a starting place in locating areas of potential adverse impact within the proposed project area. I suggest you contact all of those indicated; if they cannot supply information, they might recommend others with specific knowledge. By contacting all those listed, your organization will be better able to respond to claims of failure to consult with the appropriate tribe. If a response has not been received within two weeks of notification, the Commission requests that you follow-up with a telephone call or email to ensure that the project information has been received.

If you receive notification of change of addresses and phone numbers from tribes, please notify me. With your assistance, we can assure that our lists contain current information.

If you have any questions or need additional information, please contact me at my email address: Cameron.Vela@nahc.ca.gov.

Sincerely,

Cameron Vela

Cameron Vela
Cultural Resources Analyst

Attachment

Native American Heritage Commission
Native American Contact List
San Joaquin County
1/25/2022

Buena Vista Rancheria of Me-Wuk Indians
Rhonda Morningstar Pope, Chairperson
1418 20th Street, Suite 200 — Me-Wuk
Sacramento, CA, 95811
Phone: (916) 491 - 0011
Fax: (916) 491-0012
rhonda@buenavistatribe.com

California Valley Miwok Tribe
14807 Avenida Central — Miwok
La Grange, CA, 95329
Phone: (209) 931 - 4567
Fax: (209) 931-4333

California Valley Miwok Tribe
AKA Sheep Rancheria of Me-Wuk Indians of CA,
P.O. Box 395 — Miwok
West Point, CA, 95255
Phone: (209) 293 - 4179
l.ewilson@yahoo.com

Ione Band of Miwok Indians
Sara Dutschke, Chairperson
9252 Bush Street — Miwok
Plymouth, CA, 95669
Phone: (209) 245 - 5800
consultation@ionemiwok.net

Muwekma Ohlone Indian Tribe of the SF Bay Area
Monica Arellano, Vice Chairwoman
20885 Redwood Road, Suite 232 — Costanoan
Castro Valley, CA, 94546
Phone: (408) 205 - 9714
marellano@muwekma.org

North Valley Yokuts Tribe
Timothy Perez,
P.O. Box 717 — Costanoan
Linden, CA, 95236 — Northern Valley
Phone: (209) 662 - 2788 — Yokut
huskanam@gmail.com

North Valley Yokuts Tribe
Katherine Perez, Chairperson
P.O. Box 717 — Costanoan
Linden, CA, 95236 — Northern Valley
Phone: (209) 887 - 3415 — Yokut
canutes@verizon.net

Tule River Indian Tribe
Kerri Vera, Environmental Department
P. O. Box 589 — Yokut
Porterville, CA, 93258
Phone: (559) 783 - 8892
Fax: (559) 783-8932
kerri.vera@tulerivertribe-nsn.gov

Tule River Indian Tribe
Joey Garfield, Tribal Archaeologist
P. O. Box 589 — Yokut
Porterville, CA, 93258
Phone: (559) 783 - 8892
Fax: (559) 783-8932
joey.garfield@tulerivertribe-nsn.gov

Tule River Indian Tribe
Neil Peyron, Chairperson
P.O. Box 589 — Yokut
Porterville, CA, 93258
Phone: (559) 781 - 4271
Fax: (559) 781-4610
neil.peyron@tulerivertribe-nsn.gov

Wilton Rancheria
Jesus Tarango, Chairperson
9728 Kent Street — Miwok
Elk Grove, CA, 95624
Phone: (916) 683 - 6000
Fax: (916) 683-6015
jtarango@wiltonrancheria-nsn.gov

Wilton Rancheria
Dahlton Brown, Director of Administration
9728 Kent Street — Miwok
Elk Grove, CA, 95624
Phone: (916) 683 - 6000
dbrown@wiltonrancheria-nsn.gov

This list is current only as of the date of this document. Distribution of this list does not relieve any person of statutory responsibility as defined in Section 7050.5 of the Health and Safety Code, Section 5097.94 of the Public Resource Section 5097.98 of the Public Resources Code.

This list is only applicable for contacting local Native Americans with regard to cultural resources assessment for the proposed Gospel Center Rescue Mission New Life Men's Homeless Shelter Project, San Joaquin County.

Wilton Rancheria
Steven Hutchason, THPO
9728 Kent Street
Elk Grove, CA, 95624
Phone: (916) 683 - 6000
Fax: (916) 863-6015
shutchason@wiltonrancheria-nsn.gov

Miwok

Wuksache Indian Tribe/Eshom Valley Band
Kenneth Woodrow, Chairperson
1179 Rock Haven Ct.
Salinas, CA, 93906
Phone: (831) 443 - 9702
kwood8934@aol.com

Foothill Yokut
Mono

The Confederated Villages of Lisjan
Corrina Gould, Chairperson
10926 Edes Avenue
Oakland, CA, 94603
Phone: (510) 575 - 8408
cvltribe@gmail.com

Bay Miwok
Ohlone
Delta Yokut

This list is current only as of the date of this document. Distribution of this list does not relieve any person of statutory responsibility as defined in Section 7050.5 of the Health and Safety Code, Section 5097.94 of the Public Resource Section 5097.98 of the Public Resources Code.

This list is only applicable for contacting local Native Americans with regard to cultural resources assessment for the proposed Gospel Center Rescue Mission New Life Men's Homeless Shelter Project, San Joaquin County.

APPENDIX H
PHASE I ESA

PHASE I
ENVIRONMENTAL SITE ASSESSMENT
REPORT

NEW LIFE MEN'S FACILITY
APN 149-066-070

429-431 AND 435-437 SOUTH SAN JOAQUIN STREET
STOCKTON, SAN JOAQUIN COUNTY, CALIFORNIA

Prepared for
Base Camp Environmental, Inc.
802 West Lodi Avenue
Lodi, CA 95240
(209) 224-8213

Prepared by
Condor Earth
188 Frank West Circle, Suite I
Stockton, CA 95206
(209) 234-0518

September 8. 2021
Condor Project No. 8639

Copyright © 2021, Condor Earth
All Rights Reserved

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT
NEW LIFE MEN'S FACILITY
APN 149-066-070
429-431 AND 435-437 SOUTH SAN JOAQUIN STREET
STOCKTON, SAN JOAQUIN COUNTY, CALIFORNIA

EXECUTIVE SUMMARY

September 8, 2021

This ASTM E 1527-13 Phase I Environmental Site Assessment (ESA) was performed by Condor Earth (Condor) at the request of Base Camp Environmental (Client). The assessment was performed on Assessor's Parcel Number (APN) 149-066-070 (Site), totaling approximately 0.21 acres. The Site is located at 429-431 and 435-439 South San Joaquin Street located in Stockton, San Joaquin County, California (Figures 1 through 3, **Appendix A**).

Address numbers 429-431 and 435-439 differentiate the two two-story residential buildings to the north and south, respectively. Both buildings were constructed around 1904. A mixed lawn and paved area are located on the eastern side of the Site and a paved mix of concrete and asphalt is located on the west side of the Site. A wooden gazebo is located on the southwest corner of the Site. Wooden exterior staircases to the second story of the buildings are located on the western side of the residential buildings, as well as one staircase located on the north side of the northern residential building. Both buildings are covered with white, painted wooden siding that appeared slightly degraded, and a brick wall covers the eastern exterior wall of the southern residential building and partially covers the northeast corner of the northern residential building. Four PG&E gas meters were observed on the eastern side of the structure, as well as the gas piping. Access to the respective basements were located on the western exterior walls. The crawlspaces were observed with minor amounts of debris and wooden material, as well as a wooden cabinet-like structure in the southern residential building. The corridor between the buildings was paved and office and construction material packaging were located along the walls of the structures, including 5 empty 55-gallon drums that were unlabeled, but were intended to be used as trash cans. Strips of bare soil are exposed along the western exterior walls, as well as the eastern lawn area. An iron barred fence separates the front of the Site from the public sidewalk on the east side.

Groundwater flows toward the southeast and is anticipated to be between 20-25 feet bgs. Based on historical document review, there are no historic fuel stations or dry-cleaning operations proximal to the Site, and none of the surrounding properties appear to pose a risk to the Site.

It is Condor's opinion that the likely application of termiticides and lead-based paint around the structures constitutes a *recognized environmental condition* pursuant to the ASTM E 1527-13. Painted wood structures pre-dating the 1970s were likely painted with lead-based paint, and lead may be elevated in soil around the building perimeters. Soil around the building perimeters is also likely to contain chlorinated pesticides from termiticide application.

LIMITATIONS TO EXECUTIVE SUMMARY

This executive summary should only be read in conjunction with the full report text. Terminology is defined in the Glossary of Terms and Acronyms in **Appendix G**. The scope of work, significant assumptions, limitations, and exceptions should be understood prior to reading the Site-specific information, findings, opinions, and conclusions.

TABLE OF CONTENTS

1.0 INTRODUCTION 1
1.1 PURPOSE 1
1.2 USER RELIANCE, LIMITATIONS, AND EXCEPTIONS 2
1.3 SIGNIFICANT ASSUMPTIONS 2
1.4 SPECIAL TERMS AND CONDITIONS 2
2.0 SITE DESCRIPTION 3
2.1 SITE LOCATION, LEGAL DESCRIPTION, AND PHYSICAL SETTING 3
2.2 SITE GEOLOGY 3
2.3 CURRENT USES OF THE PROPERTY 4
2.4 DESCRIPTIONS OF STRUCTURES, ROADS, OTHER IMPROVEMENTS ON SITE 4
2.5 CURRENT USES OF THE ADJOINING PROPERTIES 4
3.0 USER PROVIDED INFORMATION 4
3.1 ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS 4
3.2 SPECIALIZED KNOWLEDGE 4
3.3 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES 4
3.4 OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION 4
3.5 REASON FOR PERFORMING PHASE I ESA 5
3.6 OTHER 5
4.0 RECORDS REVIEW 5
4.1 STANDARD ENVIRONMENTAL RECORD SOURCES 5
4.2 ADDITIONAL ENVIRONMENTAL RECORD SOURCES 6
4.2.1 State Water Resource's Control Board 6
4.3 HISTORICAL USE INFORMATION FOR THE SITE 6
4.4 HISTORICAL USE INFORMATION FOR ADJOINING PROPERTIES 7
5.0 SITE RECONNAISSANCE 8
5.1 METHODOLOGY AND LIMITING CONDITIONS 8
5.2 EXTERIOR OBSERVATIONS 8
5.3 INTERIOR OBSERVATIONS 9
5.3.1 Heating/Cooling 9
5.3.2 Stains/Corrosion 9
5.3.3 Drains and Sumps 9
6.0 INTERVIEWS 9
7.0 ADDITIONAL SERVICES 9
8.0 FINDINGS 9
9.0 OPINIONS AND CONCLUSIONS 10
10.0 DEVIATIONS AND DATA GAPS 10
11.0 REFERENCES 11
12.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL 11

13.0 ENVIRONMENTAL PROFESSIONAL'S STATEMENT AND SIGNATURE 12

APPENDICES

APPENDIX A
Figure 1 Vicinity Map
Figure 2 Site Map
Figure 3 APN Map

APPENDIX B
Site Photographs

APPENDIX C
EDR™ Radius Map with GeoCheck®

APPENDIX D
Historical Topographic Maps
Aerial Photographs
Sanborn Fire Insurance Maps
City Directories Information

APPENDIX E
Transaction Screen Questionnaire
User Questionnaire

APPENDIX F
Scope of Work

APPENDIX G
Glossary of Terms and Acronyms

APPENDIX H
Client Provided Documents

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT
NEW LIFE MEN'S FACILITY
APN 149-066-070
429-431 AND 435-437 SOUTH SAN JOAQUIN STREET
STOCKTON, SAN JOAQUIN COUNTY, CALIFORNIA

September 8, 2021

1.0 INTRODUCTION

Base Camp Environmental, Inc. (Client) retained Condor Earth (Condor) to conduct a Phase I Environmental Site Assessment (ESA) for Assessor's Parcel Number (APN) 149-066-070 (referred to hereinafter as "Site"), totaling approximately 0.21 acres. The Site is located at 429-431 and 435-437 South San Joaquin Street in Stockton, San Joaquin County, California (Figures 1 through 3, **Appendix A**).

The Phase I ESA was performed in accordance with the guidelines set forth in Practice E 1527-13, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process,* published November 2013 by the American Society for Testing and Materials (ASTM) and in accordance with the prevailing standard of care for completing such assessments in California at this time. Included is a discussion of the purpose for the work, a description of the Site and adjacent properties, a discussion of the information gathered from records, interviews, and Site visits, and Condor's findings and conclusions. Figures referenced in the report are included with the appendices. Photographs of the Site are located in **Appendix B**. The results of researched ASTM-recommended government databases [Environmental Data Resources, Inc. (EDR™) Radius Map with GeoCheck®] are contained in **Appendix C**. Historical topographic maps, aerial photographs, Sanborn fire insurance maps, and city directories information are contained in **Appendix D**. The User questionnaire and Owner transaction screening questionnaire are contained in **Appendix E**. A copy of the Scope of Work is contained in **Appendix F.** The glossary of terms associated with an ASTM Phase I ESA is contained in **Appendix G**. Information provided by Base Camp is contained in **Appendix H**.

1.1 PURPOSE

The purpose of the ASTM Phase I ESA is to conduct an appropriate inquiry into previous ownership and uses of the property to satisfy one of the requirements to qualify for the *Landowner Liability Protections* (*LLPs*) limitations on liability under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) "*landowner liability protections*" or "*LLPs*". These potential environmental conditions are identified as *recognized environmental conditions* and *historical recognized environmental conditions*. (See **Appendix G** for definitions.)

The goal of this assessment is <u>not</u> to demonstrate that no hazardous materials are present at the Site. The assessment is necessary, however, to complete "...all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" [42 USC § 9601 (35) (B)]. The use of an environmental professional in the performance of this assessment will minimize environmental risks, but cannot completely eliminate these risks.

1.2 USER RELIANCE, LIMITATIONS, AND EXCEPTIONS

The scope of this project was presented in our proposal and contract number 8639 dated July 7, 2021 and subsequently approved by the Client (see **Appendix F** for Scope of Work).

This ASTM Phase I ESA is thorough, but it is not intended to identify all potential concerns, or to eliminate all risk of the subject properties bearing some degree of environmental liability. Condor cannot and will not warrant or certify that the Site is free of contaminants because it is impossible to know if such a condition exists. Although risks can never be eliminated, more detailed and extensive investigations yield more information, thereby further minimizing risk.

Land use, Site conditions (both on-site and off-site), and other factors will change over time. Site activities and regulations beyond Condor's control could change at any time after the completion of this report. Our observations, findings, and opinions can be considered valid only as of the date of the Site visit/reconnaissance, **August 18, 2021**. If any changes are made or errors found in the information used for this report, the interpretations and conclusions contained herein shall not be considered valid unless the changes or errors are reviewed by Condor and either appropriately modified or re-approved in writing. This report should not be relied upon after 180 days from the date of issuance, but can be updated (ASTM E 1527-13, Section 4.6).

The property owner is solely responsible for notifying all governmental agencies, and the public at large, of the existence, release, treatment, or disposal of any hazardous materials observed at the Site, either before or during performance of Condor's services. Condor assumes no responsibility or liability whatsoever for any claim, loss of property value, damage, or injury which results from pre-existing hazardous materials being encountered or present on the project site, or from the discovery of such hazardous materials.

Condor, as an independent contractor, has completed the ASTM Phase I ESA in accordance with the ASTM guidelines and with the customary state of the practice and the prevailing standard of care for completing such assessments for the state of California at this time. Condor shall not be subject to any express or implied warranties whatsoever.

This report and other instruments or service are prepared and made available for the sole use of the officers and representatives of the Client. The contents thereof may not be used or relied upon by any other person(s) without the expressed written consent and authorization of the Client and Condor.

1.3 SIGNIFICANT ASSUMPTIONS

An assumed southeasterly groundwater gradient direction was utilized when assessing the potential risk posed to the Site from off-site locations. This assumed groundwater gradient is based upon a previous groundwater monitoring report associated with the Olivarez Property (Former Skip's Station) located approximately 950 feet northeast of the Site[1]. It should be noted, however, that groundwater gradients in this area have fluctuated significantly over time.

1.4 SPECIAL TERMS AND CONDITIONS

None noted.

[1] *First Quarter 2021 Groundwater Monitoring Report, Olivarez Property (Former Skip's Station), 300 South California Street, Stockton, California*, dated March 16, 2021, Ground Zero Analysis, Inc.

2.0 SITE DESCRIPTION

This section provides a brief description of the Site and surrounding areas. More information regarding the Site and its description, including historical data, is included in Sections 4.0 and 5.0.

2.1 SITE LOCATION, LEGAL DESCRIPTION, AND PHYSICAL SETTING

The Site is located south of downtown Stockton, San Joaquin County, California. The Site parcel is approximately 0.21 acres designated as APN 149-066-070 and is located in a primarily mixed residential and commercial area. The Site is depicted in the Site reconnaissance photographs (**Appendix B**) and in Figures 1 through 3 (**Appendix A**).

The sources used for determining the physical setting of the Site were the GeoCheck® Physical Setting Source Summary, provided by EDR™ (**Appendix C**), the USGS Stockton West, California 7.5-Minute Topographic Map dated 2012 (Figure 1, **Appendix A**), information from the current Federal Emergency Management Agency (FEMA) Flood Insurance Rate Map (FIRM) and Site reconnaissance. The property is included within the southwestern portion of Section 20 of the Campo de Los Franceses land grant, Mount Diablo Base and Meridian at approximately North Latitude 37.9486 and West Longitude -121.2864. The average elevation of the Site is approximately 16 feet above mean sea level with flat topography.

The Site is located in the northern portion of the San Joaquin Valley in the City of Stockton, California State Route 4 is approximately 678 feet north of the Site. South San Joaquin Street adjoins the eastern portion of the Site. East Church Street is approximately 150 feet south of the Site, South Hunter Street is approximately 250 feet west of Site and East Sonora Street is approximately 205 feet north of the Site. The Mormon Slough is located approximately 760 feet south of the Site. The Union Pacific Railroad is approximately 0.5 miles east of the Site. The FEMA FIRM map indicates that the Site is within Zone X: an area with reduced flood risk due to levees.

2.2 SITE GEOLOGY

The Site is located in the Great Valley Geomorphic Province in the northern San Joaquin Valley. The San Joaquin Valley is a northwest-trending, structural depression, filled with up to six vertical miles of lithified non-marine and marine sediments and unlithified non-marine sediments. Regionally, the lithology of the upper 3,000 feet of sediments is indicative of uplift and erosion of the Sierra Nevada to the east and, to lesser degree, the Coast Range Mountains to the west.

The Coast Range Mountains generally consist of northwest trending ridges with Franciscan Assemblage and granitic basement rocks. The Sierra Nevada Province is an asymmetric range, with a steep fault-bounded eastern front and gentle western slope that dips under the sediments of the Great Valley to the west. The bedrock complex of the Sierra Nevada Mountains generally consists of metamorphosed sedimentary and volcanic rocks of Paleozoic and Mesozoic age (150 to 300 million years old) and plutonic rocks (chiefly granitic types) of Mesozoic age (80 to 150 million years old). The Site soil type as mapped by the US Department of Agriculture is Yellowlark gravelly loam with Class C hydrologic group (slow infiltration rate) and Jacktone clay with hydrologic Class D (very slow infiltration rates). Groundwater beneath the Site is anticipated to range from approximately 20-25 feet below ground surface (bgs) based the Olivarez Property (Former Skip's Station) located approximately 950 feet northeast of the Site[2].
Two Pacific Gas and Electric (PG&E) Company plugged gas wells are located approximately 0.5 miles north of the Site and two PG&E plugged gas wells are located approximately 0.5 miles west of the Site.

[2] *First Quarter 2021 Groundwater Monitoring Report, Olivarez Property (Former Skip's Station), 300 South California Street, Stockton, California, dated March 16, 2021, Ground Zero Analysis, Inc.*

The wells were not production wells, and the Site is within the Stockton Gas gas field. This area of Stockton had historic natural gas resources in the late 19th and early 20th centuries. The natural gas resource was approximately 1,000-1,400 feet deep and was largely exhausted by the early 20th century. The historic natural gas does not appear to pose a risk to the Site. An active PG&E natural gas line runs east/west along East Church Street turns south along South Hunter Street approximately 250 feet southwest of the Site, and then turns to run east/west along East Hazelton Avenue approximately 525 feet south of the Site.

2.3 CURRENT USES OF THE PROPERTY

San Joaquin County Assessor's Office property use for the Site is indicated as residential multiple family. Based on Site reconnaissance, the Site is currently residential properties.

2.4 DESCRIPTIONS OF STRUCTURES, ROADS, OTHER IMPROVEMENTS ON SITE

The Site consists of two two-story structures with a lawn and paved walkway. A gated paved parking area is located behind the two structures with a paved walking path connecting to it from the street side going east to west between the structures. An iron-barred fence separates the front of the Site from the public sidewalk on the east side. A street light is present on the sidewalk at the northeast corner of the Site.

2.5 CURRENT USES OF THE ADJOINING PROPERTIES

The eastern properties (across South San Joaquin Street) are residential. The southern adjoining property is the Gospel Center Rescue Mission and New Hope Family Shelter. The northern adjoining property is Gleason House Community Medical Centers. The western adjoining property is a residence.

3.0 USER PROVIDED INFORMATION

3.1 ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS

An environmental lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property. The Client indicated that no environmental liens have been placed on the Site property (User Questionnaire, **Appendix E**). No evidence of any environmental lien placed on the Site property was revealed in the course of this investigation.

3.2 SPECIALIZED KNOWLEDGE

Condor reviewed the State of California – The Resource Agency, Department of Parks and Recreation's Primary Records on the Site, obtained from the Client. The documents indicate that the two structures are two-story, wood-frame multiple family residences that were built around 1904 (**Appendix H**).

3.3 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES

The Client indicated that the purchase price reasonably reflects fair market value for the Site property (User Questionnaire, **Appendix E**). Although an evaluation of property value was not included or performed during this ESA, no valuation reduction for environmental issues was revealed during review of historical information.

3.4 OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION

Information obtained from the ParcelQuest indicated the current owner of the Site parcel as Gospel Center Rescue Mission In which has owned the property since mid-2003.

3.5 REASON FOR PERFORMING PHASE I ESA

This Phase I ESA was performed to evaluate the Site for *recognized environmental conditions* pursuant to the ASTM Standard Practice E 1527-13 as part of the Client's due diligence process for inclusion in a California Environmental Quality Act document.

3.6 OTHER

None noted.

4.0 RECORDS REVIEW

4.1 STANDARD ENVIRONMENTAL RECORD SOURCES

Locations identified in the ASTM specified databases within the specified search radii are included in the EDR™ Radius Map with GeoCheck® report in **Appendix C**.

The databases specified by ASTM are commonly subject to infrequent and partial updating. This is especially true of those locations that no longer warrant inclusion in a given database. It is therefore not unusual to fail to find supporting documentation for locations identified in the ASTM specified database search on file with local regulatory agencies. A total of 309 database entries were returned including 32 leaking underground storage tanks (LUSTs), 18 State registered underground storage tanks (USTs), and 2 State registered aboveground storage tanks (ASTs). Additional environmental record sources included in the EDR™ report included 15 SWEEPS USTs, 17 historic USTs, 15 CA FID USTs, and 3 CERS tanks. High risk historical records indicate 24 records of historic auto service listings, 10 record cleaner facility listings, and 1 Manufactured Gas Plants (MGP). None is the listed databases entries pertain to the Site. A comprehensive review of every listing was not practically reviewable, so Condor focused on adjoining listed properties, those with open/active cases, and listed properties upgradient with respect to groundwater flow direction. All LUST cases within 1,000 feet have been granted regulatory closure status except for one, which is explained in greater detail below.

Gospel Center Rescue Mission Inc. is listed at 445 South San Joaquin Street which is the southern adjoining property. This is the location where asbestos containing waste was generated and disposed of at a licensed disposal facility in 2018. This property does not pose a risk to the Site since the waste disposal is documented in the HAZNET database.

Property addresses 329 and 348 South San Joaquin Street which are approximately 300 feet north-northeast of the Site Street are listed on the historic dry cleaner databases. These locations do not appear to pose a risk to the Site because of cross gradient direction and distance.

PG&E Gas Load Center is listed at 535, 530, and 540 South Center Street which is approximately 1,000 feet west-southwest of the Site. This location is described further in the following section.

H/S Auto Repair is listed at 300 California Street and is located approximately 1,000 feet northeast of the Site. This location is listed on the LUST, CORTESE, HIST CORTESE, and CERS databases. This is the location of the former Skips Service Station where five fuel USTs and one waste oil UST were removed in November 1992. Laboratory soil data results showed soil impacted with petroleum. San Joaquin Environmental Health Department (SJCEHD) filed notification of hazardous waste discharge on February 26, 1993. Monitoring wells were installed and collected samples contained high concentrations of petroleum. In October 2007, groundwater extraction, onsite treatment, and discharge to the City of Stockton sewer system began and is ongoing. This location does not pose a risk to the Site due to distance and groundwater flow direction.

4.2 ADDITIONAL ENVIRONMENTAL RECORD SOURCES

4.2.1 State Water Resource's Control Board

Selected off-site properties had electronic files available for review on State of California websites.

535 South Center Street: PG&E – Stockton Former Manufactured Gas Plant (MGP) which produced gas from coal and/or crude oil from 1860 through 1930. The MGP was shut down in 1955. A total of 34 monitoring wells were installed at the former gasification plant. Groundwater monitoring has been performed from 1987 until present and is currently monitored semiannually. Remediation by monitoring natural attenuation of the petroleum hydrocarbon constituents of potential concern, which include: polynuclear aromatic hydrocarbons (PAH); benzene, toluene, ethylbenzene, and xylenes (BTEX); and total petroleum hydrocarbons quantified as gasoline (TPH-g) and diesel (TPH-d). In May 2000, the soil was remediated by excavating the affected soil, followed by paving and capping the area. Benzene was detected in groundwater at concentrations ranging from 2.7 micrograms per liter (µg/L) in MW-4 to 1,400 µg/L in MW-27 during the March 2018 sampling event[3]. This location does not appear to pose a significant risk to the Site based on lack of detected constituents in recent groundwater monitoring in the wells immediately upgradient with respect to the Site.

4.3 HISTORICAL USE INFORMATION FOR THE SITE

Historical use information pertaining to the Site was researched using historical USGS topographic maps, aerial photographs, Sanborn Fire Insurance maps, and city directories information provided by EDR™. Copies of the maps, photographs, and directories are included in **Appendix D**.

Topographic Maps

USGS topographic maps dated 1913, 1952, 1968, 1976, 1987, and 2012 were reviewed. The **1913** map indicates that the Site is located in an urban area of downtown Stockton with relatively level topography with one or two buildings on Site. The **1952** map shows no buildings on the Site. There are no significant changes on the subsequent maps.

Aerial Photographs

Aerial photographs dated 1937, 1940, 1957, 1963, 1968, 1975, 1982, 1984, 1993, 1998, 2006, 2009, 2012, and 2016 were reviewed. In the **1937** photo, the Site appears to have two building structures along the eastern boundary. Subsequent photos show no apparent changes to the Site until **1998** which shows small structures along the western Site boundary. The **2012** photo shows vehicles parked on west side of the Site. The **2016** photo shows no significant changes to the Site.

Sanborn Fire Insurance Maps

Sanborn Fire Insurance Maps dated 1895, 1917, 1950, and 1972 were reviewed. The **1895** map shows a dwelling with one story on the west side and two stories on the east side in the east portion of the Site. A stable and another structure are located on the west side of the Site. An elevated tank and windmill are shown on the center north of the dwelling. The **1917** map shows the stable and the storage tank have been removed. The eastern portion of the Site shows two two-story structures labeled as two flats. Two small structures are shown in the northwest corner of the Site. The **1950** map shows the northern dwelling is labeled 4-F (flats) and the southern dwelling is labeled 2-F. An elongated structure is shown on the western portion of the map. There are no significant changes on the **1972** map.

[3] *2018 Annual Groundwater Monitoring Report, Former Stockton Manufactured Gas Plant, Pacific Gas and Electric Company, 535 Center Street, Stockton, California,* ETIC, December 28, 2018.

City Directories
City directory information for the Site was reviewed for the Site addresses of 429-431 and 435-437 South San Joaquin Street and are listed as primarily residential.

4.4 HISTORICAL USE INFORMATION FOR ADJOINING PROPERTIES

Historical use information pertaining to the adjoining properties was researched using historical USGS topographic maps, aerial photographs, and city directories information provided by EDR™. Copies of the maps, photographs, and directories are included in **Appendix D**.

Topographic Maps
USGS topographic maps dated 1913, 1952, 1968, 1976, 1987, and 2012 were reviewed for the adjoining properties. The **1913** map indicates the adjoining properties are urban with relatively level topography and multiple buildings shown on each city block. Mormon Slough is located south of the Site. Railroad lines are located south of Mormon Slough. The **1952** map shows three tanks west-southwest of the Site and no longer shows buildings on adjoining properties. Lafayette School is indicated approximately 0.25 miles to the east of the Site. Secondary highways are shown west and north of the Site. The **1968** map shows South Center Street and El Dorado Street to the west are one-way roads and secondary highways and California Street to the east as a secondary highway. Two tanks are located west-southwest of the Site. The construction of Interstate 5 is shown west of the Site. The **1976** map shows an extension of California State Route 4 to the north of the Site. There are no significant changes on the **1987** map. The **2012** map shows the completion of State Highway 4.

Aerial Photographs
Aerial photographs dated 1937, 1940, 1957, 1963, 1968, 1975, 1982, 1984, 1993, 1998, 2006, 2009, 2012, and 2016 were reviewed for the adjoining properties. In the **1937** photo, the adjoining properties are urban housing and commercial businesses. Three large tanks are shown west-southwest of the Site. Mormon Slough is shown west and south of the Site. There are no significant changes in the **1940** photograph. In the **1957** photograph, there are two large tanks shown west-southwest of the Site. The **1963** and **1968** photographs show no significant changes. The **1975** photograph shows the tanks west-southwest of the Site have been removed. A highway has been constructed north of the Site. There are no significant changes in subsequent photographs.

Sanborn Fire Insurance Maps
Sanborn Fire Insurance Maps dated 1895, 1917, 1950, and 1972 were reviewed for adjoining properties. The **1985** map shows the adjoining properties as dwellings with stables. The southeastern adjoining property across San Joaquin Street is a dwelling with doctors. The **1917** map shows the southern adjoining properties as vacant, a dwelling, and The San Joaquin Veterinary Hospital. The property on the northwest portion of the Site's block is labeled Chinese Laundry and the property on the northeast corner of the Site's block is vacant. The eastern adjoining properties across San Joaquin Street are dwellings and a two-story building with furnished rooms. The **1950** map shows the southern adjoining properties as Sheet Metal Works with concrete and wooden floor, a dwelling, and another dwelling with a large storage area. A hotel with a dining room and stores is shown on the northeast corner of the Sites block. The **1972** map shows the southern adjoining property from the southwest corner of the Site as the Stockton Gospel Mission with a dormitory. The dwelling in between the Stockton Gospel Mission and the Sheet Metal Works building with a store has been removed. The western adjoining properties are a dwelling and a parking lot.

City Directories
City directory information for adjoining properties was reviewed and adjoining properties are primarily residential. **445 South San Joaquin Street** is the southern adjoining property and is list as Fraser Furnace

Co and Fermin Alusitiza in 1940; as Eraser Heating Co contrs in 1970; as Fraser Heating Co in 1975 and 1979; as Inner City Christian Academy and Gospel Center Rescue Ministries in 1990; as Gospel Center Rescue Mission in 1994; as Gospel Cneter Rescue Mission Main Office, Thomas Frank, Moore Karen R, Mission indvdl family svcs, and Gospel Center Rescue in 1999; as Gospel Ctr Rescue Mission in 2004; and as Gospel Center in 2009. **423 South San Joaquin Street** is the northern adjoining property and is listed as primarily residential from 1916 through 1960. **229 and 237 East Church Street** are the southern adjoining properties and are listed as primarily residential from 1916 through 2003. **418 and 430 South Hunter Street** are the western adjoining properties are listed as primarily residential. **424 South Hunter Street** is a western adjoining property and is listed primarily as residential from 1916 through 1955, and as Turks Parking lot in 1960.

5.0 SITE RECONNAISSANCE

5.1 METHODOLOGY AND LIMITING CONDITIONS

A walking reconnaissance of the Site and surrounding area was performed on August 18, 2021 in accordance with the ASTM practice by the Environmental Professional.

5.2 EXTERIOR OBSERVATIONS

The exterior of the Site and two residential buildings were observed during the Site reconnaissance. Address numbers 429-431 and 435-439 differentiate the two two-story residential buildings to the north and south, respectively. Painted wooden siding covers the exterior walls and were observed to be peeling off and slightly degraded on both residential buildings. Four PG&E gas meters were observed on the eastern side of each of the buildings. The eastern landscape was observed to be lawn and paved walkways. A brick wall covers the eastern side of the southern building exterior wall and the northeastern corner of the northern building. Wooden exterior staircases to the second story of the buildings are located on the western side of the residential buildings, as well as one staircase located on the north side of the northern residential building. Access to the respective basements were located on the western exterior walls. The crawlspaces were observed with minor amounts of debris, bicycles, and wooden material, as well as a wooden cabinet-like structure in the southern residential building. The western side of the Site was observed to be a paved parking lot with a wooden gazebo on the southwest corner. Various 5-gallon or smaller containers of paint products were observed under the gazebo, that were associated with renovations being conducted on the southwestern adjoining property. The corridor between 429-431 and 435-437 was paved and office and construction material packaging were located along the walls of the structures, including 5 empty 55-gallon drums that were unlabeled, but are intended to be used as trash cans. An iron barred fence separates the front of the Site from the public sidewalk on the east side. Photographs of the Site are contained in **Appendix B**.

The following items were <u>not</u> observed at the Site during the Site reconnaissance unless otherwise noted.

1. Source of potable water: **Potable water is provided by California Water Service Co**.
2. Sewage disposal: **Sanitary sewer service is provided by the City of Stockton**.
3. Hazardous substances and petroleum products in connection with identified uses
4. Storage tanks
5. Odors
6. Pools of liquid
7. Drums: **5 empty 55-gallon drums used for trash cans.**
8. Hazardous substances and petroleum products containers
9. Unidentified Substance Containers
10. Polychlorinated biphenyls (PCBs)
11. Stained soil or pavement

12. Pits, ponds, or lagoons
13. Stressed vegetation
14. Solid waste
15. Waste water
16. Wells
17. Septic Systems

5.3 INTERIOR OBSERVATIONS

The interior of the residential structures were not observed during the Site reconnaissance. The interiors of the residential structure crawl spaces for the residential buildings were observed from outside of the crawlspace access panels. Observations of the crawl spaces are described in Section 5.2.

5.3.1 Heating/Cooling

Electrical (cooling) and natural gas (heating).

5.3.2 Stains/Corrosion

None observed.

5.3.3 Drains and Sumps

None.

6.0 INTERVIEWS

The User completed the User Questionnaire which is included in **Appendix E.** The Site questionnaire was completed by a representative of the Site owner and is also located in **Appendix E** of this report. During the Site reconnaissance, the Site manager indicated the 55-gallon drums are used for trash bins.

7.0 ADDITIONAL SERVICES

A Tier one vapor encroachment screen was performed in accordance with the ASTM Standard. No nearby or on-Site sources of contamination were identified that would pose a subsurface vapor intrusion risk to occupants of the Site.

8.0 FINDINGS

The 0.21-acre Site comprises two two-story residential structures located at 429-431 and 435-437 South San Joaquin Street in a primarily mixed residential and commercial neighborhood of Stockton, California. Address numbers 429-431 and 435-439 differentiate the two two-story residential buildings to the north and south, respectively. Both buildings were constructed around 1904. A mixed lawn and paved area are located on the eastern side of the Site and a paved mixed concrete and asphalt is located on the west side of the Site. A wooden gazebo is located on the southwest corner of the Site. Wooden exterior staircases to the second story of the buildings are located on the western side of the residential buildings, as well as one staircase located on the north side of the northern residential building. Both buildings are covered with white, painted wooden siding that appeared slightly degraded, and a brick wall covers the eastern exterior wall of the southern residential building and partially covers the northeast corner of the northern residential building. Four PG&E gas meters were observed on the eastern side of the structure, as well as the gas piping. Access to the respective basements were located on the western exterior wall. The crawlspaces were observed with minor amounts of debris and wooden material, as well as a wooden cabinet-like structure in the southern residential building. The corridor between the buildings was paved and office and construction

material packaging were located along the walls of the structures, including 5 empty 55-gallon drums that were unlabeled, but were intended to be used as trash cans. Strips of bare soil are exposed along the western exterior walls, as well as the eastern lawn area. An iron barred fence separates the front of the Site from the public sidewalk on the east side.

Groundwater flows toward the southeast and is anticipated to be between 20-25 feet bgs. Based on historical document review, there are no historic fuel stations or dry-cleaning operations proximal to the Site, and none of the surrounding properties appear to pose a risk to the Site. 535 South Center Street: PG&E – Stockton Former Manufactured Gas Plant (MGP) which produced gas from coal and/or crude oil from 1860 through 1930. The MGP was shut down in 1955. A total of 34 monitoring wells were installed at the former gasification plant. Groundwater monitoring was performed quarterly from 2000 until 2004 and is currently monitored semiannually. Remediation by monitoring natural attenuation of the constituents of potential concern, which include: PAHs; BTEX; and TPH-g and TPH-d. In May 2000, the soil was remediated by excavating the affected soil, followed by paving and capping the area. Benzene was detected in groundwater at concentrations ranging from 2.7 µg/L in MW-4 to 1,400 µg/L in MW-27 during the March 2018 sampling event[4]. This location does not appear to pose a significant risk to the Site based on lack of detected constituents in recent groundwater monitoring in the wells immediately upgradient with respect to the Site.

9.0 OPINIONS AND CONCLUSIONS

We (Condor) have performed a Phase I ESA in conformance with the scope and limitations of ASTM E 1527-13 for APN 149-066-070, located at 429-431 and 435-437 South San Joaquin Street, Stockton, San Joaquin County, California. Any exceptions to, or deletions from, this practice are described in Section 10.0 of this report. This assessment has revealed no evidence of *recognized environmental conditions*, *controlled recognized environmental conditions*, or *historical recognized environmental conditions* in connection with the Site except for the following:

It is Condor's opinion that the likely application of termiticides and lead-based paint around the structures constitutes a *recognized environmental condition* pursuant to the ASTM E 1527-13. Painted wood structures pre-dating the 1970s were likely painted with lead-based paint, and lead may be elevated in soil around the building perimeters. Soil around the building perimeters is also likely to contain chlorinated pesticides from termiticide application.

It is Condor's opinion that the various debris observed in the crawl spaces of the residential buildings constitute a *de mimimus condition* pursuant to the ASTM E 1527-13.

Condor recommends that upon building removal, exposed soils adjacent to the structures be analyzed for lead and chlorinated pesticides and any contaminated soil should be remediated.

10.0 DEVIATIONS AND DATA GAPS

This ASTM Phase I ESA was performed by Condor according to the scope and limitations of ASTM Practice E 1527-13, except for the following:

- Past owner interviews were not conducted. The contact information for past owners was not readily available.

This is not considered a significant deviation since the Site use is well documented.

[4] *2018 Annual Groundwater Monitoring Report, Former Stockton Manufactured Gas Plant, Pacific Gas and Electric Company, 535 Center Street, Stockton, California,* ETIC, December 28, 2018.

11.0 REFERENCES

SITE AND VICINITY GENERAL CHARACTERISTICS AND SETTING

1. FEMA National Flood Insurance Program on-line information, http://store.msc.fema.gov/; and FIRM Map Index for City of Stockton, California, 06077C0460F, dated October 16, 2009.

2. GeoCheck® Physical Setting Source Summary, provided by EDR™, dated August 5, 2021.

3. Parcel Quest®, parcel identification, on-line information, http://www.parcelquest.com.

4. Site reconnaissance, August 18, 2021.

5. USGS Stockton West, California 7.5-minute topographic quadrangle map dated 2012.

6. Wagner, D.L., E.J. Bortugno, and R.D. McJunkin, Geologic Map of the San Francisco-San Jose Quadrangle, California, 1:250,000, 1991.

CURRENT USES OF THE ADJOINING PROPERTIES

7. Site reconnaissance, August 18, 2021.

HISTORICAL USE INFORMATION ON SITE AND ADJOINING PROPERTIES

8. Aerial photographs dated 1937, 1940, 1957, 1963, 1968, 1975, 1982, 1984, 1993, 1998, 2006, 2009, 2012, and 2016 obtained from EDR™.

9. Historical USGS topographic maps dated 1913, 1952, 1968, 1976, 1987, and 2012, obtained from EDR™.

10. Sanborn Maps dated 1895, 1917, 1950, and 1972, obtained from EDR™.

RECORDS REVIEW

11. California State Water Resource Control Board website: http://geotracker.swrcb.ca.gov/reports.

12. California Water Service Company website: https://www.calwater.com/

13. EDR™ Radius Map and Report, dated August 5, 2021.

REPORT STANDARDS

14. ASTM E 1527-13.

12.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL

Condor has over six decades of aggregate experience in the performance of Phase I ESAs and environmental audits for financial institutions, attorneys, private companies and public agencies. Experienced environmental professionals perform assessments and audits that provide a standard of care consistent with industry practice and employ guidelines developed by the ASTM Practice E 1527-13. Luke Castle, California Professional Geologist, performed this assessment under the supervision of Alexander B. Dewitt. Mr. Castle, California Professional Geologist, has several years of professional experience. Mr. Dewitt has

over 19 years of experience conducting environmental assessments in California for public agencies and commercial businesses.


13.0 ENVIRONMENTAL PROFESSIONAL'S STATEMENT AND SIGNATURE

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR 312. Further, we declare that we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Respectfully submitted,

CONDOR EARTH


ENVIRONMENTAL PROFESSIONALS:



Luke Castle, CA PG No. 9945
Associate Geologist

September 8, 2021

REVIEWED BY:




September 8, 2021

Alexander B. Dewitt, CA PG No. 7502
Vice President, Environmental Services

X:\Project\8000_prj\8639 Phase I ESA New Life Mens Facility\Reports\FR 20210908 New Life Men's Facility ESA.docx

APPENDIX A



USGS The National Map: National Boundaries Dataset, 3DEP Elevation Program, Geographic Names Information System, National Hydrography Dataset, National Land Cover Database, National Structures Dataset, and National Transportation Dataset; USGS Global Ecosystems; U.S. Census Bureau TIGER/Line data; USFS Road Data; Natural Earth Data; U.S. Department of State Humanitarian Information Unit; and NOAA National Centers for Environmental Information, U.S. Coastal Relief Model. Data refreshed June, 2020.

CONDOR EARTH
21663 Brian Lane
P.O. Box 3905
Sonora, CA 95370
(209) 532-0361
fax (209) 532-0773
www.condorearth.com

Job No.	8639
Date	16 Aug 2021
Scale	AS SHOWN
Drawn	JW
Chk'd	LC

VICINITY MAP
PHASE I ESA
NEW LIFE MEN'S FACILITY
429-431 & 435-437 S. SAN JOAQUIN STREET
STOCKTON, CALIFORNIA

FIGURE 1

8639_Phasel.aprx

P:\GIS\Current Project\8639_Phasel\8639_Phasel.aprx



CONDOR EARTH
21663 Brian Lane
P.O. Box 3905
Sonora, CA 95370
(209) 532-0361
fax (209) 532-0773
www.condorearth.com


Job No.	8639
Date	16 Aug 2021
Scale	AS SHOWN
Drawn	JW
Chk'd	LC

SITE MAP
PHASE I ESA
NEW LIFE MEN'S FACILITY
429-431 & 435-437 S. SAN JOAQUIN STREET
STOCKTON, CALIFORNIA

FIGURE
2

8639_Phasel.aprx

P:\GIS\Current Project\8639_Phasel\8639_Phasel.aprx



CONDOR EARTH
21663 Brian Lane
P.O. Box 3905
Sonora, CA 95370
(209) 532-0361
fax (209) 532-0773
www.condorearth.com

Job No.	Date	Scale	Drawn	Chk'd
8639	16 Aug 2021	AS SHOWN	JW	LC

APN MAP
PHASE I ESA
NEW LIFE MEN'S FACILITY
429-431 & 435-437 S. SAN JOAQUIN STREET
STOCKTON, CALIFORNIA

FIGURE
3

8639_Phasel.aprx

P:\GIS\Current Project\8639_Phasel\8639_Phasel.aprx

APPENDIX B



Photo 1: View from the northeast corner of the Site, looking south.



Photo 2: View from the southeast corner of the Site, looking north.



Photo 3: View of the eastern entrance of 435-437 San Joaquin Street, looking west.



Photo 4: View of the corridor between 435-437 South San Joaquin Street (left) and 429-431 South San Joaquin Street (right), with empty 55-gallon drums, a trash can, and boxed construction materials, looking west.



Photo 5: View of PG&E gas meters and piping located on the eastern side of 429-431 South San Joaquin Street, looking west.



Photo 6: View of PG&E gas meters and piping located on the eastern side of 435-437 South San Joaquin Street, looking west.



Photo 7: View of the corridor between 435-437 South San Joaquin Street (left) and 429-431 South San Joaquin Street (right), with spare office equipment and construction parts, looking west.



Photo 8: View form the southwest corner of the Site, with 5-gallon buckets of corrosive material associated with renovations on the southwest adjoining property, looking north.



Photo 9: View from the southwest corner of the Site, with construction material and 5-gallon containers of paint products, associated with renovations on the southwest adjoining property, looking east.



Photo 10: View form the northwest corner of the Site, with a paved parking lot and a view of the western sides of 435-437 South San Joaquin Street (right) and 429-431 South San Joaquin Street (left), looking east.



Photo 11: View of the western side of 429-431 South San Joaquin Street, looking east.



Photo 12: View of the western side of 435-437 South San Joaquin street, looking southeast.



Photo 13: View of the crawlspace under 435-437 South San Joaquin Street with various debris, solid waste, a built-in cabinet and sewer, gas and water lines along the ceiling.



Photo 14: View of the crawlspace under 429-431 South San Joaquin Street, with various debris.

APPENDIX C

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203

Inquiry Number: 6607856.2s
August 05, 2021

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	1058
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-25
Physical Setting Source Map Findings	A-27
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

COORDINATES

Latitude (North):	37.9486290 - 37° 56' 55.06''
Longitude (West):	121.2863670 - 121° 17' 10.92''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	650566.6
UTM Y (Meters):	4201294.5
Elevation:	17 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5640424 STOCKTON WEST, CA
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140628
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Reg	MCCORMICK & BAXTER C	1214 W WASHINGTON ST	NPL, SEMS, CORRACTS, RCRA-TSDF, RCRA-SQG, US ENG..	Same	3915, 0.741, WSW
A1	GOSPEL CENTER RESCUE	445 S. SAN JOAQUIN S	HAZNET, HWTS	Higher	5, 0.001,
A2	GOSPEL CENTER RESCUE	445 S. SAN JOAQUIN S	RCRA NonGen / NLR	Higher	5, 0.001,
A3	GOSPEL CENTER RESCUE	445 S. SAN JOAQUIN S	FINDS, ECHO	Higher	5, 0.001,
B4	A SALABER FRANK DO	348 S SAN JOAQUIN ST	EDR Hist Cleaner	Higher	248, 0.047, NNE
C5	LOUIE'S GARAGE	336 S HUNTER ST	RCRA NonGen / NLR	Lower	275, 0.052, NW
C6	LOUIES GARAGE AUTO R	336 S HUNTER ST	EDR Hist Auto	Lower	275, 0.052, NW
B7	NING TOM LAUNDRY	329 S SAN JOAQUIN ST	EDR Hist Cleaner	Higher	324, 0.061, North
C8	CHOY BEN AUTO SERVIC	336 HUNTER ST S	EDR Hist Auto	Lower	335, 0.063, NW
B9	ACME CLNS	348 SAN JOAQUIN S	EDR Hist Cleaner	Higher	356, 0.067, North
B10	A SALOBER FRANK INDY	344 SAN JOAQUIN S	EDR Hist Cleaner	Higher	371, 0.070, North
B11	A ECKERT C W AUTO RE	302 S SAN JOAQUIN ST	EDR Hist Auto	Higher	461, 0.087, North
B12	SAITO K LNDY	246 S SAN JOAQUIN ST	EDR Hist Cleaner	Higher	490, 0.093, North
C13	ATROXELL AGNES MRS C	243 HUNTER S	EDR Hist Cleaner	Lower	492, 0.093, NW
C14	LOUIES GARAGE AUTO R	325 S HUNTER ST	EDR Hist Auto	Lower	494, 0.094, WNW
D15	SKEETERS AUTO TRANSM	430 S EL DORADO ST	UST	Lower	509, 0.096, WSW
D16	OCHOA (SKEETERS AUTO	448 S EL DORADO ST	SWEEPS UST, CA FID UST	Lower	525, 0.099, WSW
D17	SKEETERS AUTOMATIC T	448 S EL DORADO ST	EDR Hist Auto	Lower	525, 0.099, WSW
D18	CANHAM M L GAS STA	440 S EL DORADO ST	EDR Hist Auto	Lower	525, 0.099, WSW
D19	ROMERO AUTO REPAIR	410 S EL DORADO ST	CERS HAZ WASTE, CERS	Lower	526, 0.100, West
D20	ALCON TIRE SHOP AUTO	410 S EL DORADO ST	EDR Hist Auto	Lower	526, 0.100, West
D21	ROMERO AUTO REPAIR	410 S EL DORADO	RCRA NonGen / NLR	Lower	526, 0.100, West
D22	A FUJIMOTO R Y GAS S	502 S EL DORADO ST	EDR Hist Auto	Higher	532, 0.101, SW
23	EILAT MARCELI AUTO	318 E LAFAYETTE ST	EDR Hist Auto	Higher	534, 0.101, NNE
D24	ASONORA SERV STA	402 S EL DORADO ST	EDR Hist Auto	Lower	550, 0.104, West
D25	BRIDGESTONE/FIRESTON	400 EL DORADO ST N	LUST, Cortese, HIST CORTESE, CERS	Lower	553, 0.105, West
D26	KNOWLES SERV STA NO	447 EL DORADO S	EDR Hist Auto	Lower	565, 0.107, West
E27	JIMMIE M. RISHWAIN F	138 E. LAFAYETTE ST.	RCRA NonGen / NLR	Lower	565, 0.107, NW
D28	AH TYE BROS	448 EL DORADO S	EDR Hist Auto	Lower	567, 0.107, West
D29	SKEETERS AUTOMATIC	448 EL DORADO ST S	EDR Hist Auto	Lower	567, 0.107, West
D30	TOYS GARAGE AUTO REP	410 EL DORADO ST S	EDR Hist Auto	Lower	581, 0.110, West
D31	TOYS CHEVRON SERV	410 EL DORADO S	EDR Hist Auto	Lower	581, 0.110, West
D32	A GOOLD BROS GAS STA	502 EL DORADO S	EDR Hist Auto	Higher	583, 0.110, WSW
D33	AH TYE DILLY GAS STA	402 EL DORADO S	EDR Hist Auto	Lower	590, 0.112, West
D34	RED D SERV GAS STA	401 EL DORADO S	EDR Hist Auto	Lower	591, 0.112, West
D35	NOMELLINIS ENCO SERV	401 EL DORADO ST S	EDR Hist Auto	Lower	591, 0.112, West
D36	FORD BERT AUTO REPR	518 EL DORADO S	EDR Hist Auto	Higher	591, 0.112, WSW
D37	ERNST BENJ AUTO REPR	520 EL DORADO S	EDR Hist Auto	Higher	593, 0.112, WSW
F38	WASH HOUSE THE SELF	613 S SAN JOAQUIN ST	EDR Hist Cleaner	Higher	598, 0.113, SSE

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
E39	COLONIAL CLEANERS	130 E LAFAYETTE ST	EDR Hist Cleaner	Lower	612, 0.116, NW
40	A IWAHASHI TOM AUTO	520 S EL DORADO ST	EDR Hist Auto	Higher	612, 0.116, SW
G41	HERNANDO R C MRS CLD	346 EL DORADO S	EDR Hist Cleaner	Lower	625, 0.118, WNW
F42	CHINESE NOODLE FACTO	308 E HAZELTON	SWEEPS UST, CA FID UST	Higher	646, 0.122, SSE
F43	CHINA NOODLE FACTORY	308 E HAZELTON AVE	UST	Higher	646, 0.122, SSE
E44	AKAJIWARA H AUTO REP	135 E LAFAYETTE ST	EDR Hist Auto	Lower	647, 0.123, NW
D45	CARTER F H GAS STA	401 S EL DORADO ST	EDR Hist Auto	Lower	653, 0.124, West
E46	CALIFORNIA LNDY	118 E LAFAYETTE ST	EDR Hist Cleaner	Lower	659, 0.125, NW
E47	DEN'S AUTO REPAIR, I	308 S EL DORADO ST	CERS HAZ WASTE, CERS	Lower	690, 0.131, WNW
E48	AHTYE BROS.	308 S EL DORADO ST	HIST UST	Lower	690, 0.131, WNW
E49	DEN'S AUTO REPAIR	308 S EL DORADO	LUST, SWEEPS UST, CA FID UST, Cortese, HIST...	Lower	690, 0.131, WNW
E50	DENS AUTO REPAIR	308 S EL DORADO ST B	RCRA NonGen / NLR	Lower	690, 0.131, WNW
E51	DENS AUTO REPAIR INC	308 S EL DORADO ST	UST	Lower	690, 0.131, WNW
E52	AHTYE BROS	308 SOUTH EL DORADO	HIST UST	Lower	690, 0.131, WNW
G53	GATEWAY PROJECT	325 S EL DORADO ST	UST	Lower	705, 0.134, WNW
G54	GATEWAY PROJECT	325 EL DORADO ST S	LUST, Cortese, HIST CORTESE, CERS	Lower	705, 0.134, WNW
H55	HOUSING AUTHORITY CO	448 S. CENTER STREET	RCRA NonGen / NLR	Lower	886, 0.168, WSW
I56	PG&E GAS PLANT STOCK	CENTER HAZELTON COMM	SEMS-ARCHIVE	Higher	904, 0.171, SW
J57	COMMUNITY FABRICARE	711 S SAN JOAQUIN ST	SWEEPS UST, CA FID UST	Higher	924, 0.175, SSE
J58	COMMUNITY FABRICARE	711 S SAN JOAQUIN ST	UST	Higher	924, 0.175, SSE
J59	FABRICARE	711 SAN JOAQUIN	LUST, Cortese, HIST CORTESE, CERS	Higher	924, 0.175, SSE
K60	E.W. AVILA ESTATE	328 S CALIFORNIA ST	SWEEPS UST, CA FID UST	Higher	930, 0.176, ENE
K61	E W AVILA ESTATE	328 S CALIFORNIA ST	UST	Higher	930, 0.176, ENE
I62	P G AND E SUBSTATION	540 SOUTH CENTER	RCRA-LQG, FINDS, ECHO	Higher	932, 0.177, WSW
I63	PG&E	540 SOUTH CENTER STR	RCRA NonGen / NLR	Higher	932, 0.177, WSW
I64	PACIFIC GAS & ELECTR	540 S. CENTER ST.	RCRA-LQG	Higher	932, 0.177, WSW
H65	PG&E, STOCKTON	530 CENTER	ENVIROSTOR, VCP, DEED, HIST CORTESE	Higher	938, 0.178, WSW
H66	PG AND E GAS PLANT S	530 S CENTER ST (IS	EDR MGP	Higher	938, 0.178, WSW
L67	KEYSTONE AUTOMOTIVE	632 S EL DORADO ST	UST	Higher	951, 0.180, SSW
L68	STOCKTON PLATING INC	632 S EL DORADO ST	ENVIROSTOR, LUST, SWEEPS UST, HIST UST, CA FID...	Higher	951, 0.180, SSW
M69	UNITED #5449	322 S CENTER ST	RCRA NonGen / NLR	Lower	987, 0.187, WNW
M70	APRO LLC	322 S CENTER ST	CERS HAZ WASTE, CERS TANKS, EMI, CERS	Lower	987, 0.187, WNW
M71	UNITED #5449	322 S CENTER ST	UST	Lower	987, 0.187, WNW
K72	SKIPS SERVICE STATIO	300 S CALIFORNIA ST	UST	Higher	988, 0.187, NE
K73	SKIPS SERVICE STATIO	300 S CALIFORNIA ST	HIST UST	Higher	988, 0.187, NE
K74	MICHAEL & SHARON OLI	300 S CALIFORNIA ST	RCRA-LQG	Higher	988, 0.187, NE
K75	SKIPS SERVICE STATIO	300 S CALIFORNIA ST	SWEEPS UST, CA FID UST	Higher	988, 0.187, NE
K76	H/S AUTO REPAIR	300 CALIFORNIA	LUST, Cortese, HIST CORTESE, CERS	Higher	995, 0.188, NE
K77	USN COMMUNICATION ST	ROUGH AND READY ISLA	SWF/LF, CERS	Higher	1008, 0.191, ENE

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
78	ALEX G. SPANOS ELEME	EAST CHURCH STREET/A	ENVIROSTOR, SCH	Higher	1037, 0.196, East
I79	P G & E - GAS LOAD C	535 S CENTER	SWEEPS UST, CA FID UST	Higher	1058, 0.200, WSW
I80	PG&E: STOCKTON GAS P	535 S CENTER ST	CERS HAZ WASTE, CERS	Higher	1058, 0.200, WSW
I81	PG&E STOCKTON GAS PL	535 S CENTER	AST	Higher	1058, 0.200, WSW
I82	PG&E: STOCKTON GAS P	535 S CENTER ST	RCRA-LQG, US FIN ASSUR, FINDS	Higher	1058, 0.200, WSW
I83	PACIFIC GAS & ELECTR	535 S CENTER ST	HIST UST, EMI, CERS	Higher	1058, 0.200, WSW
I84	GAS LOAD CENTER	535 S CENTER ST	HIST UST	Higher	1058, 0.200, WSW
I85	PG&E: STOCKTON GAS P	535 S CENTER ST	UST	Higher	1058, 0.200, WSW
I86	PG&E GAS LOAD CENTER	535 CENTER	CPS-SLIC, CHMIRS, HIST CORTESE, CERS	Higher	1058, 0.200, WSW
N87	OKAMOTO SERVICE	145 S SUTTER ST	SWEEPS UST, CA FID UST	Higher	1080, 0.205, North
N88	SAN JOAQUIN COUNTY	145 S SUTTER ST	HIST UST, HAZNET, HWTS	Higher	1080, 0.205, North
N89	OKAMOTO SERVICE	145 S SUTTER ST	HIST UST	Higher	1080, 0.205, North
N90	SJ COUNTY	145 S SUTTER ST	UST	Higher	1080, 0.205, North
O91	SHELL BULK PLANT	38 SONORA	HIST CORTESE	Lower	1107, 0.210, West
N92	MARKET ST. PARKING	134 S SUTTER ST	SWEEPS UST, CA FID UST	Higher	1117, 0.212, NNE
N93	CLARK GARAGE	125 S SUTTER ST	SWEEPS UST, HIST UST, CA FID UST	Higher	1143, 0.216, North
N94	CLARK GARAGE	125 S SUTTER ST	HIST UST	Higher	1143, 0.216, North
N95	SJ COUNTY	125 S SUTTER ST	UST	Higher	1143, 0.216, North
P96	MOTOR POOL GARAGE	121 S SAN JOAQUIN ST	RCRA NonGen / NLR	Lower	1152, 0.218, North
P97	SJ COUNTY PARKING GA	121 S SAN JOAQUIN ST	CERS TANKS, CERS	Lower	1152, 0.218, North
P98	SJ COUNTY PARKING GA	121 S SAN JOAQUIN ST	UST	Lower	1152, 0.218, North
N99	MARKET ST PARKING ST	124 S SUTTER ST	UST	Higher	1155, 0.219, NNE
N100	HENRY APARTMENTS	121 S SUTTER ST	SWEEPS UST, CA FID UST	Higher	1155, 0.219, North
N101	HENRY APARTMENTS	121 S SUTTER ST	UST	Higher	1155, 0.219, North
Q102	DELTA PUMPS, INC.	646 CALIFORNIA ST S	CPS-SLIC	Higher	1170, 0.222, ESE
N103	HUMAN SERVICES AGENC	145 SUTTER	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Higher	1180, 0.223, NNE
O104	SNOW CLEANERS INC	38 W SONORA ST	RCRA-SQG, CERS HAZ WASTE, CERS TANKS, US AIRS,...	Lower	1204, 0.228, West
O105	MORTON PAINT CO	38 W SONORA ST	UST	Lower	1204, 0.228, West
O106	MORTON PAINT COMPANY	38 W SONORA ST	SWEEPS UST, CA FID UST	Lower	1204, 0.228, West
O107	SNOW CLEANERS INC	38 WEST SONORA STREE	HIST UST, HAZNET, HWTS	Lower	1204, 0.228, West
O108	SNOW CLEANERSINC	38 W SONORA ST	HIST UST, EMI	Lower	1204, 0.228, West
O109	SNOW CLEANERS INC	38 W SONORA ST	AST, HIST UST, DRYCLEANERS, CIWQS	Lower	1204, 0.228, West
N110	MARKET STREET PARKIN	134 SUTTER ST S	LUST, Cortese, CERS	Higher	1215, 0.230, NNE
N111	MARKET STREET PARKIN	134 SUTTER	HIST CORTESE	Higher	1229, 0.233, North
Q112	MALAN VAN & STORAGE	707 S CALIFORNIA ST	UST	Higher	1248, 0.236, SE
Q113	MALAN VAN & STORAGE	707 S CALIFORNIA ST	SWEEPS UST, HIST UST, CA FID UST	Higher	1248, 0.236, SE
Q114	MALAN VAN & STORAGE	707 SO. CALIF ST.	HIST UST	Higher	1248, 0.236, SE
115	STOCKTON, CITY OF(RE	310 S AMERICAN ST	UST	Higher	1273, 0.241, ENE
Q116	DELTA PUMPS, INC.	646 SOUTH CALIFORNIA	CPS-SLIC, CERS	Higher	1291, 0.245, ESE

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q117	STOCKTON ARMATURE &	646 S CALIFORNIA ST	HIST UST, CHMIRS	Higher	1291, 0.245, ESE
Q118	DELTA PUMP INC DELTA	646 S CALIFORNIA ST	RCRA NonGen / NLR	Higher	1291, 0.245, ESE
Q119	STOCKTON ARMATURE AN	646 S CALIFORNIA STR	RCRA NonGen / NLR	Higher	1291, 0.245, ESE
Q120	STOCKTON ARMATURE AN	646 S CALIFORNIA ST	CERS HAZ WASTE, SWEEPS UST, HIST UST, CA FID UST,...	Higher	1291, 0.245, ESE
P121	HIGRADE CLEANERS	47 SOUTH SAN JOAQUIN	SEMS-ARCHIVE	Lower	1320, 0.250, North
R122	STOCKTON POLICE DEPA	22 MARKET ST E	LUST, Cortese, HIST CORTESE	Lower	1325, 0.251, NW
123	CANLIS BLDG	24 HUNTER ST S	LUST, Cortese, HIST CORTESE, CERS	Lower	1448, 0.274, NNW
R124	CHEVRON #9-0557	139 CENTER ST S	LUST, Cortese, HIST CORTESE, CERS	Lower	1475, 0.279, NW
125	THE RECORD	530 MARKET	LUST, Cortese, CERS	Higher	1501, 0.284, NNE
126	FIRE ENGINE COMPANY	110 SONORA	LUST, Cortese, HIST CORTESE, CERS	Higher	1531, 0.290, WSW
127	H AND B RECYCLING	521 S STANISLAUS ST	SWRCY	Higher	1546, 0.293, East
128	GLEASON PARK APARTME	411 S. STANISLAUS ST	ENVIROSTOR, VCP, DEED	Higher	1548, 0.293, ENE
129	GREYHOUND LINES INC	121 CENTER ST S	LUST, Cortese, HIST CORTESE, CERS	Lower	1591, 0.301, WNW
130	REYNOSO CONCRETE CON	729 COMMERCE ST S	LUST, Cortese, HIST CORTESE, CERS	Lower	1801, 0.341, SW
S131	STOCKTON COURTHOUSE	180 EAST WEBER AVE	CPS-SLIC, CERS	Lower	1824, 0.345, NNW
132	SIEBOLD CONSTRUCTION	820 AMERICAN ST S	LUST, Cortese, HIST CORTESE, CERS	Higher	1928, 0.365, SE
S133	SAN JOAQUIN COUNTY C	222 WEBER AVE E	LUST, Cortese, HIST CORTESE, CERS	Lower	1929, 0.365, NNW
T134	CONCRET, INC	749 STANISLAUS ST	LUST, Cortese, HIST CORTESE, CERS	Higher	1944, 0.368, ESE
U135	R V CIRCUITS	916 SOUTH CENTER STR	RESPONSE, ENVIROSTOR, CERS	Higher	1965, 0.372, SSW
U136	GREAT WESTERN CHEMIC	826 SOUTH CENTER ST	RCRA-SQG, RESPONSE, ENVIROSTOR, HIST Cal-Sites,...	Higher	1972, 0.373, SSW
V137	RITE WAY CLEANERS	700 EAST MARKET STRE	SEMS-ARCHIVE	Higher	2067, 0.391, NE
V138	RITE WAY CLEANERS	700 EAST MARKET STRE	ENVIROSTOR	Higher	2067, 0.391, NE
W139	SOUTH POINT (AREA 1)	100 WEBER AVE E	US BROWNFIELDS	Lower	2071, 0.392, NNW
W140	AREA 4	100 WEBER AVE E	US BROWNFIELDS	Lower	2071, 0.392, NNW
W141	WEBER BLOCK (AREA 9)	100 WEBER AVE E	US BROWNFIELDS	Lower	2071, 0.392, NNW
W142	WEBER BLOCK	WEBER AVE. AND EL DO	ENVIROSTOR, VCP, DEED	Lower	2071, 0.392, NNW
V143	GOODWILL INDUSTRIES	129 GRANT ST S	LUST, Cortese, CERS	Higher	2077, 0.393, NE
X144	MAIN STREET INVESTOR	601 E. MAIN STREET	LUST	Higher	2126, 0.403, NNE
X145	MAIN STREET INVESTOR	601 E. MAIN STREET	LUST, Cortese, CERS	Higher	2126, 0.403, NNE
W146	MINER'S LEVEE (AREA	UNKNOWN	US BROWNFIELDS, FINDS	Lower	2146, 0.406, NW
W147	AREA 20 (NORTH SHORE	UNKNOWN	US BROWNFIELDS, FINDS	Lower	2146, 0.406, NW
W148	STOCKTON IRON WORKS	UNKNOWN	US BROWNFIELDS	Lower	2146, 0.406, NW
W149	MARINA TOWERS EAST (	LINDSAY STREET	US BROWNFIELDS	Lower	2146, 0.406, NW
V150	GOODWILL INDUSTRIES	129 GRANT	CERS HAZ WASTE, HIST UST, HIST CORTESE	Higher	2164, 0.410, NE
T151	DELTA PLATING, INC	818 S. STANISLAUS ST	RCRA-LQG, ENVIROSTOR, SWEEPS UST, HIST UST, CA FID...	Higher	2178, 0.412, ESE
152	SIERRA LUMBER CASE #	375 HAZELTON AVENUE	LUST, Cortese, CERS	Lower	2208, 0.418, WSW
Y153	PARKING GARAGE	130 HUNTER	LUST, Cortese, HIST CORTESE, CERS	Lower	2246, 0.425, NNW
154	HICKINBOTHAM BROS LT	635 AURORA	LUST, Cortese, HIST CORTESE, CERS	Higher	2318, 0.439, East
Z155	WEBER ENTERPRISES	141 EL DORADO ST N	LUST, Cortese, HIST CORTESE, CERS	Lower	2321, 0.440, NNW

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Y156	AMERICAN SAVINGS BAN	222 EL DORADO ST N	CPS-SLIC, CERS	Lower	2325, 0.440, NNW
AA157	CAPITOL VENTURE ENTE	400 AURORA ST S	LUST, Cortese, CERS	Higher	2363, 0.448, ENE
AA158	BEAULIEU CHEM CO	400 S AURORA	SEMS-ARCHIVE	Higher	2405, 0.455, ENE
AA159	BEAULIEU INDUSTRIES	400 S AURORA	ENVIROSTOR, VCP, SWEEPS UST, CA FID UST	Higher	2405, 0.455, ENE
Z160	FORMER AMERICA SAVIN	CHANNEL ST. & EL DOR	US BROWNFIELDS	Lower	2438, 0.462, NNW
Z161	GLASS PRO BUILDING (	CHANNEL ST. & EL DOR	US BROWNFIELDS	Lower	2438, 0.462, NNW
162	E.F. MITCHLER CO	400 LINCOLN	LUST, Cortese, HIST CORTESE, CERS	Lower	2452, 0.464, WSW
AA163	BEAULIEU CHEMICAL CO	400 AURORA	HIST CORTESE	Higher	2471, 0.468, ENE
164	ARCO #4493	205 N CENTER ST	LUST, SWEEPS UST, CA FID UST, Cortese, HIST...	Lower	2521, 0.477, NW
165	SIERRA LUMBER CASE #	375 HAZELTON AVE W	LUST, Cortese, HIST CORTESE, CERS	Lower	2536, 0.480, WSW
AB166	VALLEY MOTORS	800 MAIN ST E	LUST, CPS-SLIC, Cortese, HIST CORTESE, CERS	Higher	2552, 0.483, NE
AB167	CHLORINATED SOLVENT	EAST MAIN STREET & S	CPS-SLIC, CERS	Higher	2555, 0.484, NE
AB168	CITY OF STOCKTON	800 EAST MAIN STREET	LUST, Cortese, CERS	Higher	2574, 0.488, NE
169	CITY OF STOCKTON RED	216 CALIFORNIA	LUST, Cortese, Notify 65, CERS	Lower	2585, 0.490, North
170	SUTTER OFFICE CENTER	242 SUTTER ST	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	2756, 0.522, North
171	CANCUN RESTAURANT	135 MINER	LUST, Cortese, Notify 65, CERS	Lower	2821, 0.534, NNW
172	COMMUNITY MEDICAL CE	701 E CHANNEL ST	ENVIROSTOR, HAZNET, HWTS	Higher	2970, 0.562, NNE
173	WORK NET PROJECT, ST	40 LINCOLN STREET (B	ENVIROSTOR, VCP	Lower	3077, 0.583, WNW
174	OVERMYER MACHINE WOR	1019 S AURORA	ENVIROSTOR	Higher	3146, 0.596, ESE
175	CHILDREN'S MUSEUM OF	402 W. WEBER AVENUE	ENVIROSTOR, VCP	Lower	3152, 0.597, WNW
176	ACME-STOCKTON GALVAN	540 WEST SCOTTS AVEN	RESPONSE, ENVIROSTOR, CPS-SLIC, HIST Cal-Sites,...	Lower	3417, 0.647, WSW
AC177	SOUTH SHORE PROPERTY	WEST WEBER AVENUE	ENVIROSTOR, VCP	Lower	3669, 0.695, WNW
178	J.C. TRUCKING	1207 S AURORA ST	LUST, SWEEPS UST, CA FID UST, Cortese, HIST...	Higher	3700, 0.701, SE
179	DELTA GATEWAY APARTM	720/802 WEST WEBER A	ENVIROSTOR, VCP	Lower	3774, 0.715, WNW
AC180	MORTON PAINT COMPANY	SOUTH LINCOLN & WEST	ENVIROSTOR	Lower	3790, 0.718, WNW
AD181	GASCO	749 CHARTER WAY E	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Higher	3845, 0.728, SE
AE182	CHASE CHEVROLET CO	432 N. MADISON	RCRA-SQG, LUST, FINDS, ECHO, Cortese, HAZNET, HIST...	Lower	3911, 0.741, NW
AE183	CHASE CHEVROLET CO.	423 N MADISON	ENVIROSTOR, VCP, SWEEPS UST, CA FID UST, DEED	Lower	3911, 0.741, NW
184	CRYSTAL CREAM & BUTT	404 FREMONT	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	3920, 0.742, NW
185	THOMPSONS AUTO REPAI	945 S PILGRIM ST	ENVIROSTOR	Higher	3934, 0.745, ESE
186	ANCHOR VILLAGE	133 EAST OAK STREET	ENVIROSTOR, VCP	Lower	3946, 0.747, NNW
187	STALLWORTH AUTO DETA	602 CALIFORNIA ST N	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Higher	3968, 0.752, North
AD188	MORITA BROTHERS	814 CHARTER	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Higher	4001, 0.758, SE
189	GENE GABBARD INC	640 EL DORADO ST	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	4119, 0.780, NNW
AF190	ARCO #2168 (FORMER)	441 CHARTER WAY W	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	4341, 0.822, SSW
AF191	TEXACO	440 CHARTER	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	4382, 0.830, SSW
192	UNION ICE CORP	425 UNION ST N	ENVIROSTOR, LUST, VCP, Cortese, HIST CORTESE, CERS	Higher	4471, 0.847, NNE
193	THE TRANSMISSION STO	515 CHARTER WAY W	LUST, Cortese, HIST CORTESE, Notify 65, CERS	Lower	4518, 0.856, SSW
194	STOCKTON IRON WORKS	600 W. LINDSAY STREE	ENVIROSTOR	Lower	4530, 0.858, WNW

MAPPED SITES SUMMARY

Target Property Address:
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
195	WIGHT ENTERPRISES #2	130 S WILSON WAY	LUST, SWEEPS UST, CA FID UST, Cortese, EMI, HIST...	Higher	4810, 0.911, ENE
196	SOUTHPOINTE PROPERTY	WEBER AVENUE + STOCK	ENVIROSTOR, VCP	Lower	4883, 0.925, WNW
197	ROTOR BLADE INCE	1514 E SCOTTS AVE	ENVIROSTOR, VCP, SWEEPS UST, CA FID UST, LIENS,...	Higher	4954, 0.938, East
198	STOCKTON DEVELOPMENT	1252 STANISLAUS ST	LUST, Cortese, Notify 65, CERS	Higher	5098, 0.966, NNE
199	NORTHERN 2-ACRE PORT	848 W. FREMONT STREE	ENVIROSTOR, VCP, SWEEPS UST, CA FID UST	Lower	5141, 0.974, WNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-VSQG ---------- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

INDIAN UST ---- Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

INDIAN VCP ---- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS ---- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ---- Waste Management Unit Database
HAULERS ---- Registered Waste Tire Haulers Listing
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
CDL ---- Clandestine Drug Labs
Toxic Pits ---- Toxic Pits Cleanup Act Sites
US CDL ---- National Clandestine Laboratory Register
PFAS ---- PFAS Contamination Site Location Listing

Local Land Records

LIENS ---- Environmental Liens Listing
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
CHMIRS ---- California Hazardous Material Incident Report System
LDS ---- Land Disposal Sites Listing
MCS ---- Military Cleanup Sites Listing
SPILLS 90 ---- SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
RMP ---- Risk Management Plans

RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
CUPA Listings	CUPA Resources List
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
ICE	ICE
HWT	Registered Hazardous Waste Transporter Database
MINES	Mines Site Location Listing
MWMP	Medical Waste Management Program Listing
NPDES	NPDES Permits Listing
PEST LIC	Pesticide Regulation Licenses Listing
PROC	Certified Processors Database
UIC	UIC Listing
UIC GEO	UIC GEO (GEOTRACKER)
WASTEWATER PITS	Oil Wastewater Pits Listing
WDS	Waste Discharge System
WIP	Well Investigation Program Case List
MILITARY PRIV SITES	MILITARY PRIV SITES (GEOTRACKER)
PROJECT	PROJECT (GEOTRACKER)
WDR	Waste Discharge Requirements Listing
CIWQS	California Integrated Water Quality System
CERS	CERS
NON-CASE INFO	NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS	OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS	PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT	SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ	Well Stimulation Project (GEOTRACKER)
HWTS	Hazardous Waste Tracking System
MINES MRDS	Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF	Recovered Government Archive Solid Waste Facilities List

EXECUTIVE SUMMARY

RGA LUST..... Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 04/27/2021 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C Cerclis ID:: 901129 EPA Id: CAD009106527	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 04/27/2021 has revealed that there are 4 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E GAS PLANT STOCK	CENTER HAZELTON COMM	SW 1/8 - 1/4 (0.171 mi.)	I56	244

Site ID: 0902390 EPA Id: CAD981415862				
RITE WAY CLEANERS	700 EAST MARKET STRE	NE 1/4 - 1/2 (0.391 mi.)	V137	628
BEAULIEU CHEM CO Site ID: 0903215 EPA Id: CAD009449935	400 S AURORA	ENE 1/4 - 1/2 (0.455 mi.)	AA158	757

Lower Elevation	Address	Direction / Distance	Map ID	Page
HIGRADE CLEANERS	47 SOUTH SAN JOAQUIN	N 1/8 - 1/4 (0.250 mi.)	P121	560

Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/22/2021 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C EPA ID:: CAD009106527	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/22/2021 has revealed that there are 4 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
P G AND E SUBSTATION EPA ID:: CAD983617408	***540 SOUTH CENTER***	***WSW 1/8 - 1/4 (0.177 mi.)***	***I62***	***253***
PACIFIC GAS & ELECTR EPA ID:: CAC002914832	540 S. CENTER ST.	WSW 1/8 - 1/4 (0.177 mi.)	I64	259
MICHAEL & SHARON OLI EPA ID:: CAL000328371	300 S CALIFORNIA ST	NE 1/8 - 1/4 (0.187 mi.)	K74	361
PG&E: STOCKTON GAS P EPA ID:: CAD980886873	***535 S CENTER ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I82***	***391***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/22/2021 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SNOW CLEANERS INC	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O104***	***456***
EPA ID:: CAR000001032				

State- and tribal - equivalent NPL

RESPONSE: Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

A review of the RESPONSE list, as provided by EDR, has revealed that there are 3 RESPONSE sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
R V CIRCUITS	***916 SOUTH CENTER STR***	***SSW 1/4 - 1/2 (0.372 mi.)***	***U135***	***611***
Database: RESPONSE, Date of Government Version: 04/23/2021				
Status: No Further Action				
Facility Id: 39340027				
GREAT WESTERN CHEMIC	***826 SOUTH CENTER ST***	***SSW 1/4 - 1/2 (0.373 mi.)***	***U136***	***614***
Database: RESPONSE, Date of Government Version: 04/23/2021				
Status: Certified				
Facility Id: 39280008				

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACME-STOCKTON GALVAN	***540 WEST SCOTTS AVEN***	***WSW 1/2 - 1 (0.647 mi.)***	***176***	***849***
Database: RESPONSE, Date of Government Version: 04/23/2021				
Status: Certified O&M - Land Use Restrictions Only				
Facility Id: 39340018				

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk

characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 04/23/2021 has revealed that there are 27 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***
Facility Id: 39240001 Facility Id: 80001587 Status: Active Status: Refer: SMBRP				
PG&E, STOCKTON	***530 CENTER***	***WSW 1/8 - 1/4 (0.178 mi.)***	***H65***	***262***
Facility Id: 39490015 Status: Certified / Operation & Maintenance				
STOCKTON PLATING INC	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
Facility Id: 60000493 Facility Id: 71002280 Status: Inactive - Needs Evaluation				
ALEX G. SPANOS ELEME	***EAST CHURCH STREET/A***	***E 1/8 - 1/4 (0.196 mi.)***	***78***	***379***
Facility Id: 39390001 Status: Certified				
GLEASON PARK APARTME	***411 S. STANISLAUS ST***	***ENE 1/4 - 1/2 (0.293 mi.)***	***128***	***577***
Facility Id: 60001130 Status: Certified O&M - Land Use Restrictions Only				
R V CIRCUITS	***916 SOUTH CENTER STR***	***SSW 1/4 - 1/2 (0.372 mi.)***	***U135***	***611***
Facility Id: 39340027 Status: No Further Action				
GREAT WESTERN CHEMIC	***826 SOUTH CENTER ST***	***SSW 1/4 - 1/2 (0.373 mi.)***	***U136***	***614***
Facility Id: 39280008 Status: Certified				
RITE WAY CLEANERS	700 EAST MARKET STRE	NE 1/4 - 1/2 (0.391 mi.)	V138	630
Facility Id: 60001402 Status: Inactive - Needs Evaluation				
DELTA PLATING, INC	***818 S. STANISLAUS ST***	***ESE 1/4 - 1/2 (0.412 mi.)***	***T151***	***686***
Facility Id: 71003777 Status: Inactive - Action Required				
BEAULIEU INDUSTRIES	***400 S AURORA***	***ENE 1/4 - 1/2 (0.455 mi.)***	***AA159***	***759***
Facility Id: 39280007 Status: No Further Action				
COMMUNITY MEDICAL CE	***701 E CHANNEL ST***	***NNE 1/2 - 1 (0.562 mi.)***	***172***	***841***
Facility Id: 39800001 Status: No Action Required				
OVERMYER MACHINE WOR	1019 S AURORA	ESE 1/2 - 1 (0.596 mi.)	174	846
Facility Id: 39350019 Status: Refer: Other Agency				
THOMPSONS AUTO REPAI	945 S PILGRIM ST	ESE 1/2 - 1 (0.745 mi.)	185	948
Facility Id: 39750003 Status: Refer: Other Agency				
UNION ICE CORP	***425 UNION ST N***	***NNE 1/2 - 1 (0.847 mi.)***	***192***	***1000***

Facility Id: 60001427
Status: No Further Action

ROTOR BLADE INCE	***1514 E SCOTTS AVE***	***E 1/2 - 1 (0.938 mi.)***	***197***	***1036***
Facility Id: 39760006 Facility Id: 71002606 Status: Active Status: Refer: SMBRP				

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEBER BLOCK	***WEBER AVE. AND EL DO***	***NNW 1/4 - 1/2 (0.392 mi.)***	***W142***	***646***
Facility Id: 39750009 Status: Certified O&M - Land Use Restrictions Only				
WORK NET PROJECT, ST	***40 LINCOLN STREET (B***	***WNW 1/2 - 1 (0.583 mi.)***	***173***	***843***
Facility Id: 39240018 Status: Refer: RWQCB				
CHILDREN'S MUSEUM OF	***402 W. WEBER AVENUE***	***WNW 1/2 - 1 (0.597 mi.)***	***175***	***847***
Facility Id: 60000351 Status: Inactive - Needs Evaluation				
ACME-STOCKTON GALVAN	***540 WEST SCOTTS AVEN***	***WSW 1/2 - 1 (0.647 mi.)***	***176***	***849***
Facility Id: 39340018 Status: Certified O&M - Land Use Restrictions Only				
SOUTH SHORE PROPERTY	***WEST WEBER AVENUE***	***WNW 1/2 - 1 (0.695 mi.)***	***AC177***	***868***
Facility Id: 39290009 Status: Refer: RWQCB				
DELTA GATEWAY APARTM	***720/802 WEST WEBER A***	***WNW 1/2 - 1 (0.715 mi.)***	***179***	***878***
Facility Id: 39000004 Status: Refer: RWQCB				
MORTON PAINT COMPANY	SOUTH LINCOLN & WEST	WNW 1/2 - 1 (0.718 mi.)	AC180	881
Facility Id: 39280010 Status: Refer: Other Agency				
CHASE CHEVROLET CO.	***423 N MADISON***	***NW 1/2 - 1 (0.741 mi.)***	***AE183***	***914***
Facility Id: 39750010 Status: Certified O&M - Land Use Restrictions Only				
ANCHOR VILLAGE	***133 EAST OAK STREET***	***NNW 1/2 - 1 (0.747 mi.)***	***186***	***949***
Facility Id: 60002477 Status: No Further Action				
STOCKTON IRON WORKS	600 W. LINDSAY STREE	WNW 1/2 - 1 (0.858 mi.)	194	1022
Facility Id: 60001556 Status: Refer: EPA				
SOUTHPOINTE PROPERTY	***WEBER AVENUE + STOCK***	***WNW 1/2 - 1 (0.925 mi.)***	***196***	***1034***
Facility Id: 60001406 Status: Inactive - Needs Evaluation				
NORTHERN 2-ACRE PORT	***848 W. FREMONT STREE***	***WNW 1/2 - 1 (0.974 mi.)***	***199***	***1049***
Facility Id: 60002155 Facility Id: 39440001 Status: Active				

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
USN COMMUNICATION ST	***ROUGH AND READY ISLA***	***ENE 1/8 - 1/4 (0.191 mi.)***	***K77***	***377***
Database: SWF/LF (SWIS), Date of Government Version: 05/10/2021 Facility ID: 39-AA-0006 Operational Status: Closed Regulation Status: Unpermitted				

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 32 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FABRICARE	***711 SAN JOAQUIN***	***SSE 1/8 - 1/4 (0.175 mi.)***	***J59***	***249***
Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 03/08/2021 Status: Completed - Case Closed Status: Case Closed Global Id: T0607700254				
STOCKTON PLATING INC	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 03/08/2021 Status: Completed - Case Closed Status: Remedial action (cleanup) Underway Global Id: T0607700077				
H/S AUTO REPAIR	***300 CALIFORNIA***	***NE 1/8 - 1/4 (0.188 mi.)***	***K76***	***366***
Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 03/08/2021 Status: Open - Site Assessment Status: Remedial action (cleanup) Underway Global Id: T0607700605				
HUMAN SERVICES AGENC	***145 SUTTER***	***NNE 1/8 - 1/4 (0.223 mi.)***	***N103***	***443***
Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 03/08/2021 Status: Open - Remediation Status: Remediation Plan Global Id: T0607700218				
MARKET STREET PARKIN	***134 SUTTER ST S***	***NNE 1/8 - 1/4 (0.230 mi.)***	***N110***	***537***
Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 03/08/2021				

Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700278

THE RECORD ***530 MARKET*** ***NNE 1/4 - 1/2 (0.284 mi.)*** ***125*** ***571***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607712799

FIRE ENGINE COMPANY ***110 SONORA*** ***WSW 1/4 - 1/2 (0.290 mi.)*** ***126*** ***574***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700084

SIEBOLD CONSTRUCTION ***820 AMERICAN ST S*** ***SE 1/4 - 1/2 (0.365 mi.)*** ***132*** ***596***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Pollution Characterization
Global Id: T0607700303

CONCRET, INC ***749 STANISLAUS ST*** ***ESE 1/4 - 1/2 (0.368 mi.)*** ***T134*** ***608***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700655

GOODWILL INDUSTRIES ***129 GRANT ST S*** ***NE 1/4 - 1/2 (0.393 mi.)*** ***V143*** ***654***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700178

MAIN STREET INVESTOR 601 E. MAIN STREET NNE 1/4 - 1/2 (0.403 mi.) X144 656
Database: LUST, Date of Government Version: 03/08/2021
Status: Open - Site Assessment
Global Id: T0607762422

MAIN STREET INVESTOR ***601 E. MAIN STREET*** ***NNE 1/4 - 1/2 (0.403 mi.)*** ***X145*** ***662***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Status: Leak being confirmed

HICKINBOTHAM BROS LT ***635 AURORA*** ***E 1/4 - 1/2 (0.439 mi.)*** ***154*** ***749***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700229

CAPITOL VENTURE ENTE ***400 AURORA ST S*** ***ENE 1/4 - 1/2 (0.448 mi.)*** ***AA157*** ***755***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700582

VALLEY MOTORS ***800 MAIN ST E*** ***NE 1/4 - 1/2 (0.483 mi.)*** ***AB166*** ***795***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021

Status: Completed - Case Closed
Status: Remediation Plan
Global Id: T0607700430

CITY OF STOCKTON ***800 EAST MAIN STREET*** ***NE 1/4 - 1/2 (0.488 mi.)*** ***AB168*** ***812***
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Global Id: T10000007010

Lower Elevation	Address	Direction / Distance	Map ID	Page

BRIDGESTONE/FIRESTON ***400 EL DORADO ST N*** ***W 0 - 1/8 (0.105 mi.)*** ***D25*** ***204***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700804
Global Id: T0607700476

DEN'S AUTO REPAIR ***308 S EL DORADO*** ***WNW 1/8 - 1/4 (0.131 mi.)*** ***E49*** ***226***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Leak being confirmed
Global Id: T0607700715

GATEWAY PROJECT ***325 EL DORADO ST S*** ***WNW 1/8 - 1/4 (0.134 mi.)*** ***G54*** ***239***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700905

STOCKTON POLICE DEPA ***22 MARKET ST E*** ***NW 1/4 - 1/2 (0.251 mi.)*** ***R122*** ***562***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700169

CANLIS BLDG ***24 HUNTER ST S*** ***NNW 1/4 - 1/2 (0.274 mi.)*** ***123*** ***564***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700548

CHEVRON #9-0557 ***139 CENTER ST S*** ***NW 1/4 - 1/2 (0.279 mi.)*** ***R124*** ***566***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Preliminary site assessment underway
Global Id: T0607700391

GREYHOUND LINES INC ***121 CENTER ST S*** ***WNW 1/4 - 1/2 (0.301 mi.)*** ***129*** ***585***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed

Global Id: T0607700505

REYNOSO CONCRETE CON ***729 COMMERCE ST S*** ***SW 1/4 - 1/2 (0.341 mi.)*** ***130*** ***592***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700571

SAN JOAQUIN COUNTY C ***222 WEBER AVE E*** ***NNW 1/4 - 1/2 (0.365 mi.)*** ***S133*** ***605***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Post remedial action monitoring
Global Id: T0607700478

SIERRA LUMBER CASE # ***375 HAZELTON AVENUE*** ***WSW 1/4 - 1/2 (0.418 mi.)*** ***152*** ***742***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Status: Leak being confirmed

PARKING GARAGE ***130 HUNTER*** ***NNW 1/4 - 1/2 (0.425 mi.)*** ***Y153*** ***743***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Open - Site Assessment
Status: Leak being confirmed
Global Id: T0607700689

WEBER ENTERPRISES ***141 EL DORADO ST N*** ***NNW 1/4 - 1/2 (0.440 mi.)*** ***Z155*** ***752***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700423

E.F. MITCHLER CO ***400 LINCOLN*** ***WSW 1/4 - 1/2 (0.464 mi.)*** ***162*** ***768***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607700555

ARCO #4493 ***205 N CENTER ST*** ***NW 1/4 - 1/2 (0.477 mi.)*** ***164*** ***771***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Pollution Characterization
Global Id: T0607700462

SIERRA LUMBER CASE # ***375 HAZELTON AVE W*** ***WSW 1/4 - 1/2 (0.480 mi.)*** ***165*** ***778***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Completed - Case Closed
Status: Preliminary site assessment underway
Global Id: T0607726897
Global Id: T0607700185

CITY OF STOCKTON RED ***216 CALIFORNIA*** ***N 1/4 - 1/2 (0.490 mi.)*** ***169*** ***816***
Database: LUST REG 5, Date of Government Version: 07/01/2008
Database: LUST, Date of Government Version: 03/08/2021
Status: Open - Site Assessment
Global Id: T0607755189

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 7 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E GAS LOAD CENTER	***535 CENTER***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I86***	***399***
Database: SLIC REG 5, Date of Government Version: 04/01/2005 Database: CPS-SLIC, Date of Government Version: 03/08/2021 Facility Status: Open - Verification Monitoring Global Id: SL205122996				
DELTA PUMPS, INC.	646 CALIFORNIA ST S	ESE 1/8 - 1/4 (0.222 mi.)	Q102	443
Database: SLIC REG 5, Date of Government Version: 04/01/2005				
DELTA PUMPS, INC.	***646 SOUTH CALIFORNIA***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q116***	***542***
Database: CPS-SLIC, Date of Government Version: 03/08/2021 Facility Status: Completed - Case Closed Global Id: SLT5S1193159				
VALLEY MOTORS	***800 MAIN ST E***	***NE 1/4 - 1/2 (0.483 mi.)***	***AB166***	***795***
Database: SLIC REG 5, Date of Government Version: 04/01/2005				
CHLORINATED SOLVENT	***EAST MAIN STREET & S***	***NE 1/4 - 1/2 (0.484 mi.)***	***AB167***	***811***
Database: CPS-SLIC, Date of Government Version: 03/08/2021 Facility Status: Open - Inactive Global Id: SLT5S3083344				

Lower Elevation	Address	Direction / Distance	Map ID	Page
STOCKTON COURTHOUSE	***180 EAST WEBER AVE***	***NNW 1/4 - 1/2 (0.345 mi.)***	***S131***	***595***
Database: CPS-SLIC, Date of Government Version: 03/08/2021 Facility Status: Open - Assessment & Interim Remedial Action Global Id: T10000006328				
AMERICAN SAVINGS BAN	***222 EL DORADO ST N***	***NNW 1/4 - 1/2 (0.440 mi.)***	***Y156***	***754***
Database: SLIC REG 5, Date of Government Version: 04/01/2005 Database: CPS-SLIC, Date of Government Version: 03/08/2021 Facility Status: Completed - Case Closed Global Id: SL185632931				

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 18 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHINA NOODLE FACTORY	308 E HAZELTON AVE	SSE 0 - 1/8 (0.122 mi.)	F43	215
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018				

Facility Id: FA0004972
Tank Status: 02 - Inactive, non-billable

COMMUNITY FABRICARE	711 S SAN JOAQUIN ST	SSE 1/8 - 1/4 (0.175 mi.)	J58	248
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0005000 Tank Status: 02 - Inactive, non-billable				
E W AVILA ESTATE	328 S CALIFORNIA ST	ENE 1/8 - 1/4 (0.176 mi.)	K61	252
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0003661 Tank Status: 02 - Inactive, non-billable				
KEYSTONE AUTOMOTIVE	632 S EL DORADO ST	SSW 1/8 - 1/4 (0.180 mi.)	L67	288
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0002387 Tank Status: 02 - Inactive, non-billable				
SKIPS SERVICE STATIO	300 S CALIFORNIA ST	NE 1/8 - 1/4 (0.187 mi.)	K72	357
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0004522 Tank Status: 02 - Inactive, non-billable				
PG&E: STOCKTON GAS P	535 S CENTER ST	WSW 1/8 - 1/4 (0.200 mi.)	I85	398
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0009476 Tank Status: 02 - Inactive, non-billable				
SJ COUNTY	145 S SUTTER ST	N 1/8 - 1/4 (0.205 mi.)	N90	408
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0006013 Tank Status: 02 - Inactive, non-billable				
SJ COUNTY	125 S SUTTER ST	N 1/8 - 1/4 (0.216 mi.)	N95	416
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0004980 Tank Status: 02 - Inactive, non-billable				
MARKET ST PARKING ST	124 S SUTTER ST	NNE 1/8 - 1/4 (0.219 mi.)	N99	440
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0004977 Tank Status: 02 - Inactive, non-billable				
HENRY APARTMENTS	121 S SUTTER ST	N 1/8 - 1/4 (0.219 mi.)	N101	442
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0005285 Tank Status: 02 - Inactive, non-billable				
MALAN VAN & STORAGE	707 S CALIFORNIA ST	SE 1/8 - 1/4 (0.236 mi.)	Q112	539
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0005475 Tank Status: 02 - Inactive, non-billable				
STOCKTON, CITY OF(RE	310 S AMERICAN ST	ENE 1/8 - 1/4 (0.241 mi.)	115	542
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0013884 Tank Status: 02 - Inactive, non-billable				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SKEETERS AUTO TRANSM	430 S EL DORADO ST	WSW 0 - 1/8 (0.096 mi.)	D15	188
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018				

Facility Id: FA0003975
Tank Status: 02 - Inactive, non-billable

DENS AUTO REPAIR INC	308 S EL DORADO ST	WNW 1/8 - 1/4 (0.131 mi.)	E51	235
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0003520 Tank Status: 02 - Inactive, non-billable				
GATEWAY PROJECT	325 S EL DORADO ST	WNW 1/8 - 1/4 (0.134 mi.)	G53	238
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0012146 Tank Status: 02 - Inactive, non-billable				
UNITED #5449	322 S CENTER ST	WNW 1/8 - 1/4 (0.187 mi.)	M71	356
Database: UST, Date of Government Version: 03/08/2021 Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0012628 Tank Status: 01 - Active, billable				
SJ COUNTY PARKING GA	121 S SAN JOAQUIN ST	N 1/8 - 1/4 (0.218 mi.)	P98	439
Database: UST, Date of Government Version: 03/08/2021 Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0004573 Facility Id: FA0004573 Tank Status: 01 - Active, billable				
MORTON PAINT CO	38 W SONORA ST	W 1/8 - 1/4 (0.228 mi.)	O105	518
Database: UST SAN JOAQUIN, Date of Government Version: 06/22/2018 Facility Id: FA0005982 Tank Status: 02 - Inactive, non-billable				

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, has revealed that there are 2 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E STOCKTON GAS PL	535 S CENTER	WSW 1/8 - 1/4 (0.200 mi.)	I81	390
Database: AST, Date of Government Version: 07/06/2016				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SNOW CLEANERS INC	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O109***	***533***
Database: AST, Date of Government Version: 07/06/2016				

State and tribal voluntary cleanup sites

VCP: Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

A review of the VCP list, as provided by EDR, and dated 04/23/2021 has revealed that there are 4 VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E, STOCKTON	***530 CENTER***	***WSW 1/8 - 1/4 (0.178 mi.)***	***H65***	***262***
Status: Certified / Operation & Maintenance Facility Id: 39490015				
GLEASON PARK APARTME	***411 S. STANISLAUS ST***	***ENE 1/4 - 1/2 (0.293 mi.)***	***128***	***577***
Status: Certified O&M - Land Use Restrictions Only Facility Id: 60001130				
BEAULIEU INDUSTRIES	***400 S AURORA***	***ENE 1/4 - 1/2 (0.455 mi.)***	***AA159***	***759***
Status: No Further Action Facility Id: 39280007				

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEBER BLOCK	***WEBER AVE. AND EL DO***	***NNW 1/4 - 1/2 (0.392 mi.)***	***W142***	***646***
Status: Certified O&M - Land Use Restrictions Only Facility Id: 39750009				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 03/15/2021 has revealed that there are 9 US BROWNFIELDS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTH POINT (AREA 1) ACRES property ID: 14278 Cleanup Completion Date: -	100 WEBER AVE E	NNW 1/4 - 1/2 (0.392 mi.)	W139	631
AREA 4 ACRES property ID: 14281 Cleanup Completion Date: -	100 WEBER AVE E	NNW 1/4 - 1/2 (0.392 mi.)	W140	633
WEBER BLOCK (AREA 9) ACRES property ID: 14268 Cleanup Completion Date: 09/30/2000	100 WEBER AVE E	NNW 1/4 - 1/2 (0.392 mi.)	W141	638
MINER'S LEVEE (AREA ACRES property ID: 14285 Cleanup Completion Date: -	***UNKNOWN***	***NW 1/4 - 1/2 (0.406 mi.)***	***W146***	***663***
AREA 20 (NORTH SHORE ACRES property ID: 19381 ACRES property ID: 19382 ACRES property ID: 14277 Cleanup Completion Date: -	***UNKNOWN***	***NW 1/4 - 1/2 (0.406 mi.)***	***W147***	***666***
STOCKTON IRON WORKS	UNKNOWN	NW 1/4 - 1/2 (0.406 mi.)	W148	676

ACRES property ID: 14271 Cleanup Completion Date: -				
MARINA TOWERS EAST (ACRES property ID: 14273 Cleanup Completion Date: -	LINDSAY STREET	NW 1/4 - 1/2 (0.406 mi.)	W149	678
FORMER AMERICA SAVIN ACRES property ID: 14269 Cleanup Completion Date: -	CHANNEL ST. & EL DOR	NNW 1/4 - 1/2 (0.462 mi.)	Z160	763
GLASS PRO BUILDING (ACRES property ID: 14276 Cleanup Completion Date: -	CHANNEL ST. & EL DOR	NNW 1/4 - 1/2 (0.462 mi.)	Z161	766

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 03/09/2021 has revealed that there is 1 SWRCY site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
H AND B RECYCLING Cert Id: RC6617	521 S STANISLAUS ST	E 1/4 - 1/2 (0.293 mi.)	127	577

Local Lists of Hazardous waste / Contaminated Sites

HIST Cal-Sites: Formerly known as ASPIS, this database contains both known and potential hazardous substance sites. The source is the California Department of Toxic Substance Control. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

A review of the HIST Cal-Sites list, as provided by EDR, and dated 08/08/2005 has revealed that there are 3 HIST Cal-Sites sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***
GREAT WESTERN CHEMIC	***826 SOUTH CENTER ST***	***SSW 1/4 - 1/2 (0.373 mi.)***	***U136***	***614***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
ACME-STOCKTON GALVAN	***540 WEST SCOTTS AVEN***	***WSW 1/2 - 1 (0.647 mi.)***	***176***	***849***

SCH: This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category. depending on the level of threat to public health and safety or the. environment they pose.

A review of the SCH list, as provided by EDR, and dated 04/23/2021 has revealed that there is 1 SCH site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ALEX G. SPANOS ELEME	***EAST CHURCH STREET/A***	***E 1/8 - 1/4 (0.196 mi.)***	***78***	***379***
Facility Id: 39390001				
Status: Certified				

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 04/19/2021 has revealed that there are 6 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E: STOCKTON GAS P	***535 S CENTER ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I80***	***385***
STOCKTON ARMATURE AN	***646 S CALIFORNIA ST***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q120***	***550***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ROMERO AUTO REPAIR	***410 S EL DORADO ST***	***W 0 - 1/8 (0.100 mi.)***	***D19***	***192***
DEN'S AUTO REPAIR, I	***308 S EL DORADO ST***	***WNW 1/8 - 1/4 (0.131 mi.)***	***E47***	***216***
APRO LLC	***322 S CENTER ST***	***WNW 1/8 - 1/4 (0.187 mi.)***	***M70***	***327***
SNOW CLEANERS INC	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O104***	***456***

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 15 SWEEPS UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHINESE NOODLE FACTO	***308 E HAZELTON***	***SSE 0 - 1/8 (0.122 mi.)***	***F42***	***214***
Comp Number: 2570				
COMMUNITY FABRICARE	***711 S SAN JOAQUIN ST***	***SSE 1/8 - 1/4 (0.175 mi.)***	***J57***	***246***
Comp Number: 1245				
E.W. AVILA ESTATE	***328 S CALIFORNIA ST***	***ENE 1/8 - 1/4 (0.176 mi.)***	***K60***	***252***
Comp Number: 2258				
STOCKTON PLATING INC	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
Comp Number: 1986				
SKIPS SERVICE STATIO	***300 S CALIFORNIA ST***	***NE 1/8 - 1/4 (0.187 mi.)***	***K75***	***363***
Status: A				
Tank Status: A				
Comp Number: 1038				
P G & E - GAS LOAD C	***535 S CENTER***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I79***	***384***
Comp Number: 1043				
OKAMOTO SERVICE	***145 S SUTTER ST***	***N 1/8 - 1/4 (0.205 mi.)***	***N87***	***402***

Comp Number: 1257				
MARKET ST. PARKING	***134 S SUTTER ST***	***NNE 1/8 - 1/4 (0.212 mi.)***	***N92***	***411***
Comp Number: 2339				
CLARK GARAGE	***125 S SUTTER ST***	***N 1/8 - 1/4 (0.216 mi.)***	***N93***	***413***
Comp Number: 1892				
HENRY APARTMENTS	***121 S SUTTER ST***	***N 1/8 - 1/4 (0.219 mi.)***	***N100***	***441***
Comp Number: 1851				
MALAN VAN & STORAGE	***707 S CALIFORNIA ST***	***SE 1/8 - 1/4 (0.236 mi.)***	***Q113***	***540***
Comp Number: 1031				
STOCKTON ARMATURE AN	***646 S CALIFORNIA ST***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q120***	***550***
Comp Number: 1030				

Lower Elevation	Address	Direction / Distance	Map ID	Page
OCHOA (SKEETERS AUTO	***448 S EL DORADO ST***	***WSW 0 - 1/8 (0.099 mi.)***	***D16***	***190***
Status: A				
Tank Status: A				
Comp Number: 2369				
DEN'S AUTO REPAIR	***308 S EL DORADO***	***WNW 1/8 - 1/4 (0.131 mi.)***	***E49***	***226***
Status: A				
Tank Status: A				
Comp Number: 1085				
MORTON PAINT COMPANY	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O106***	***522***
Status: A				
Comp Number: 1254				

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 17 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STOCKTON PLATING INC	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
Facility Id: 00000014552				
SKIPS SERVICE STATIO	300 S CALIFORNIA ST	NE 1/8 - 1/4 (0.187 mi.)	K73	359
Facility Id: 00000001407				
PACIFIC GAS & ELECTR	***535 S CENTER ST***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I83***	***395***
GAS LOAD CENTER	535 S CENTER ST	WSW 1/8 - 1/4 (0.200 mi.)	I84	397
Facility Id: 00000024753				
SAN JOAQUIN COUNTY	***145 S SUTTER ST***	***N 1/8 - 1/4 (0.205 mi.)***	***N88***	***404***
OKAMOTO SERVICE	145 S SUTTER ST	N 1/8 - 1/4 (0.205 mi.)	N89	407
Facility Id: 00000049766				
CLARK GARAGE	***125 S SUTTER ST***	***N 1/8 - 1/4 (0.216 mi.)***	***N93***	***413***
CLARK GARAGE	125 S SUTTER ST	N 1/8 - 1/4 (0.216 mi.)	N94	415
Facility Id: 00000006823				
MALAN VAN & STORAGE	***707 S CALIFORNIA ST***	***SE 1/8 - 1/4 (0.236 mi.)***	***Q113***	***540***
MALAN VAN & STORAGE	707 SO. CALIF ST.	SE 1/8 - 1/4 (0.236 mi.)	Q114	541
Facility Id: 00000012851				
STOCKTON ARMATURE &	***646 S CALIFORNIA ST***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q117***	***543***

Facility Id: 00000018268

STOCKTON ARMATURE AN	***646 S CALIFORNIA ST***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q120***	***550***

Lower Elevation	Address	Direction / Distance	Map ID	Page
AHTYE BROS. Facility Id: 00000068920	308 S EL DORADO ST	WNW 1/8 - 1/4 (0.131 mi.)	E48	225
AHTYE BROS Facility Id: 00000052051	308 SOUTH EL DORADO	WNW 1/8 - 1/4 (0.131 mi.)	E52	236
SNOW CLEANERS INC	***38 WEST SONORA STREE***	***W 1/8 - 1/4 (0.228 mi.)***	***O107***	***526***
SNOW CLEANERSINC Facility Id: 00000042134	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O108***	***530***
SNOW CLEANERS INC Facility Id: 00000008382	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O109***	***533***

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 15 CA FID UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHINESE NOODLE FACTO Facility Id: 39003797 Status: I	***308 E HAZELTON***	***SSE 0 - 1/8 (0.122 mi.)***	***F42***	***214***
COMMUNITY FABRICARE Facility Id: 39000268 Status: I	***711 S SAN JOAQUIN ST***	***SSE 1/8 - 1/4 (0.175 mi.)***	***J57***	***246***
E.W. AVILA ESTATE Facility Id: 39002622 Status: I	***328 S CALIFORNIA ST***	***ENE 1/8 - 1/4 (0.176 mi.)***	***K60***	***252***
STOCKTON PLATING INC Facility Id: 39000004 Status: I	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
SKIPS SERVICE STATIO Facility Id: 39000618 Status: A	***300 S CALIFORNIA ST***	***NE 1/8 - 1/4 (0.187 mi.)***	***K75***	***363***
P G & E - GAS LOAD C Facility Id: 39000256 Status: I	***535 S CENTER***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I79***	***384***
OKAMOTO SERVICE Facility Id: 39000227 Status: I	***145 S SUTTER ST***	***N 1/8 - 1/4 (0.205 mi.)***	***N87***	***402***
MARKET ST. PARKING Facility Id: 39000264 Status: I	***134 S SUTTER ST***	***NNE 1/8 - 1/4 (0.212 mi.)***	***N92***	***411***
CLARK GARAGE Facility Id: 39001169 Status: I	***125 S SUTTER ST***	***N 1/8 - 1/4 (0.216 mi.)***	***N93***	***413***
HENRY APARTMENTS	***121 S SUTTER ST***	***N 1/8 - 1/4 (0.219 mi.)***	***N100***	***441***

Facility Id: 39003561
Status: I

MALAN VAN & STORAGE	***707 S CALIFORNIA ST***	***SE 1/8 - 1/4 (0.236 mi.)***	***Q113***	***540***
Facility Id: 39003430 Status: I				
STOCKTON ARMATURE AN	***646 S CALIFORNIA ST***	***ESE 1/8 - 1/4 (0.245 mi.)***	***Q120***	***550***
Facility Id: 39000714 Status: I				

Lower Elevation	Address	Direction / Distance	Map ID	Page
OCHOA (SKEETERS AUTO	***448 S EL DORADO ST***	***WSW 0 - 1/8 (0.099 mi.)***	***D16***	***190***
Facility Id: 39002227 Status: A				
DEN'S AUTO REPAIR	***308 S EL DORADO***	***WNW 1/8 - 1/4 (0.131 mi.)***	***E49***	***226***
Facility Id: 39003033 Status: A				
MORTON PAINT COMPANY	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O106***	***522***
Facility Id: 39003374 Status: A				

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 04/19/2021 has revealed that there are 3 CERS TANKS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
APRO LLC	***322 S CENTER ST***	***WNW 1/8 - 1/4 (0.187 mi.)***	***M70***	***327***
SJ COUNTY PARKING GA	***121 S SAN JOAQUIN ST***	***N 1/8 - 1/4 (0.218 mi.)***	***P97***	***419***
SNOW CLEANERS INC	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O104***	***456***

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 03/02/2021 has revealed that there are 3 DEED sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG&E, STOCKTON	***530 CENTER***	***WSW 1/8 - 1/4 (0.178 mi.)***	***H65***	***262***
Status: CERTIFIED / OPERATION & MAINTENANCE Envirostor ID: 39490015				
GLEASON PARK APARTME	***411 S. STANISLAUS ST***	***ENE 1/4 - 1/2 (0.293 mi.)***	***128***	***577***
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY Envirostor ID: 60001130				

Lower Elevation	Address	Direction / Distance	Map ID	Page
WEBER BLOCK	***WEBER AVE. AND EL DO***	***NNW 1/4 - 1/2 (0.392 mi.)***	***W142***	***646***

Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Envirostor ID: 39750009

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/22/2021 has revealed that there are 12 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOSPEL CENTER RESCUE EPA ID:: CAC002988264	445 S. SAN JOAQUIN S	0 - 1/8 (0.001 mi.)	A2	179
PG&E EPA ID:: CAC003048730	540 SOUTH CENTER STR	WSW 1/8 - 1/4 (0.177 mi.)	I63	257
STOCKTON PLATING INC EPA ID:: CAD009212929	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
DELTA PUMP INC DELTA EPA ID:: CAL000452314	646 S CALIFORNIA ST	ESE 1/8 - 1/4 (0.245 mi.)	Q118	545
STOCKTON ARMATURE AN EPA ID:: CAL000218979	646 S CALIFORNIA STR	ESE 1/8 - 1/4 (0.245 mi.)	Q119	548

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOUIE'S GARAGE EPA ID:: CAL000226184	336 S HUNTER ST	NW 0 - 1/8 (0.052 mi.)	C5	183
ROMERO AUTO REPAIR EPA ID:: CAL000453482	410 S EL DORADO	W 0 - 1/8 (0.100 mi.)	D21	201
JIMMIE M. RISHWAIN F	138 E. LAFAYETTE ST.	NW 0 - 1/8 (0.107 mi.)	E27	208
DENS AUTO REPAIR EPA ID:: CAL000413322	308 S EL DORADO ST B	WNW 1/8 - 1/4 (0.131 mi.)	E50	232
HOUSING AUTHORITY CO EPA ID:: CAC003018110	448 S. CENTER STREET	WSW 1/8 - 1/4 (0.168 mi.)	H55	242
UNITED #5449 EPA ID:: CAL000406980	322 S CENTER ST	WNW 1/8 - 1/4 (0.187 mi.)	M69	324
MOTOR POOL GARAGE EPA ID:: CAL000295835	121 S SAN JOAQUIN ST	N 1/8 - 1/4 (0.218 mi.)	P96	417

EXECUTIVE SUMMARY

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 04/27/2021 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C EPA ID:: CAD009106527	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 02/03/2021 has revealed that there is 1 FINDS site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOSPEL CENTER RESCUE Registry ID:: 110070441029	***445 S. SAN JOAQUIN S***	***0 - 1/8 (0.001 mi.)***	***A3***	***182***

ECHO: ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A review of the ECHO list, as provided by EDR, and dated 04/04/2021 has revealed that there is 1 ECHO site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOSPEL CENTER RESCUE Registry ID: 110070441029	***445 S. SAN JOAQUIN S***	***0 - 1/8 (0.001 mi.)***	***A3***	***182***

CA BOND EXP. PLAN: Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

A review of the CA BOND EXP. PLAN list, as provided by EDR, and dated 01/01/1989 has revealed that there is 1 CA BOND EXP. PLAN site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ACME-STOCKTON GALVAN	***540 WEST SCOTTS AVEN***	***WSW 1/2 - 1 (0.647 mi.)***	***176***	***849***

EXECUTIVE SUMMARY

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 03/22/2021 has revealed that there are 31 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FABRICARE	***711 SAN JOAQUIN***	***SSE 1/8 - 1/4 (0.175 mi.)***	***J59***	***249***
Cleanup Status: COMPLETED - CASE CLOSED				
STOCKTON PLATING INC	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
Cleanup Status: COMPLETED - CASE CLOSED				
H/S AUTO REPAIR	***300 CALIFORNIA***	***NE 1/8 - 1/4 (0.188 mi.)***	***K76***	***366***
Cleanup Status: OPEN - SITE ASSESSMENT				
HUMAN SERVICES AGENC	***145 SUTTER***	***NNE 1/8 - 1/4 (0.223 mi.)***	***N103***	***443***
Cleanup Status: OPEN - REMEDIATION				
MARKET STREET PARKIN	***134 SUTTER ST S***	***NNE 1/8 - 1/4 (0.230 mi.)***	***N110***	***537***
Cleanup Status: COMPLETED - CASE CLOSED				
THE RECORD	***530 MARKET***	***NNE 1/4 - 1/2 (0.284 mi.)***	***125***	***571***
Cleanup Status: COMPLETED - CASE CLOSED				
FIRE ENGINE COMPANY	***110 SONORA***	***WSW 1/4 - 1/2 (0.290 mi.)***	***126***	***574***
Cleanup Status: COMPLETED - CASE CLOSED				
SIEBOLD CONSTRUCTION	***820 AMERICAN ST S***	***SE 1/4 - 1/2 (0.365 mi.)***	***132***	***596***
Cleanup Status: COMPLETED - CASE CLOSED				
CONCRET, INC	***749 STANISLAUS ST***	***ESE 1/4 - 1/2 (0.368 mi.)***	***T134***	***608***
Cleanup Status: COMPLETED - CASE CLOSED				
GOODWILL INDUSTRIES	***129 GRANT ST S***	***NE 1/4 - 1/2 (0.393 mi.)***	***V143***	***654***
Cleanup Status: COMPLETED - CASE CLOSED				
MAIN STREET INVESTOR	***601 E. MAIN STREET***	***NNE 1/4 - 1/2 (0.403 mi.)***	***X145***	***662***
Cleanup Status: OPEN - SITE ASSESSMENT				
HICKINBOTHAM BROS LT	***635 AURORA***	***E 1/4 - 1/2 (0.439 mi.)***	***154***	***749***
Cleanup Status: COMPLETED - CASE CLOSED				
CAPITOL VENTURE ENTE	***400 AURORA ST S***	***ENE 1/4 - 1/2 (0.448 mi.)***	***AA157***	***755***
Cleanup Status: COMPLETED - CASE CLOSED				
VALLEY MOTORS	***800 MAIN ST E***	***NE 1/4 - 1/2 (0.483 mi.)***	***AB166***	***795***
Cleanup Status: COMPLETED - CASE CLOSED				
CITY OF STOCKTON	***800 EAST MAIN STREET***	***NE 1/4 - 1/2 (0.488 mi.)***	***AB168***	***812***
Cleanup Status: COMPLETED - CASE CLOSED				

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRIDGESTONE/FIRESTON	***400 EL DORADO ST N***	***W 0 - 1/8 (0.105 mi.)***	***D25***	***204***
Cleanup Status: COMPLETED - CASE CLOSED				
DEN'S AUTO REPAIR	***308 S EL DORADO***	***WNW 1/8 - 1/4 (0.131 mi.)***	***E49***	***226***
Cleanup Status: COMPLETED - CASE CLOSED				
GATEWAY PROJECT	***325 EL DORADO ST S***	***WNW 1/8 - 1/4 (0.134 mi.)***	***G54***	***239***
Cleanup Status: COMPLETED - CASE CLOSED				
STOCKTON POLICE DEPA	***22 MARKET ST E***	***NW 1/4 - 1/2 (0.251 mi.)***	***R122***	***562***
Cleanup Status: COMPLETED - CASE CLOSED				
CANLIS BLDG	***24 HUNTER ST S***	***NNW 1/4 - 1/2 (0.274 mi.)***	***123***	***564***

Cleanup Status: COMPLETED - CASE CLOSED

CHEVRON #9-0557	***139 CENTER ST S***	***NW 1/4 - 1/2 (0.279 mi.)***	***R124***	***566***
Cleanup Status: COMPLETED - CASE CLOSED				
GREYHOUND LINES INC	***121 CENTER ST S***	***WNW 1/4 - 1/2 (0.301 mi.)***	***129***	***585***
Cleanup Status: COMPLETED - CASE CLOSED				
REYNOSO CONCRETE CON	***729 COMMERCE ST S***	***SW 1/4 - 1/2 (0.341 mi.)***	***130***	***592***
Cleanup Status: COMPLETED - CASE CLOSED				
SAN JOAQUIN COUNTY C	***222 WEBER AVE E***	***NNW 1/4 - 1/2 (0.365 mi.)***	***S133***	***605***
Cleanup Status: COMPLETED - CASE CLOSED				
SIERRA LUMBER CASE #	***375 HAZELTON AVENUE***	***WSW 1/4 - 1/2 (0.418 mi.)***	***152***	***742***
Cleanup Status: COMPLETED - CASE CLOSED				
PARKING GARAGE	***130 HUNTER***	***NNW 1/4 - 1/2 (0.425 mi.)***	***Y153***	***743***
Cleanup Status: OPEN - SITE ASSESSMENT				
WEBER ENTERPRISES	***141 EL DORADO ST N***	***NNW 1/4 - 1/2 (0.440 mi.)***	***Z155***	***752***
Cleanup Status: COMPLETED - CASE CLOSED				
E.F. MITCHLER CO	***400 LINCOLN***	***WSW 1/4 - 1/2 (0.464 mi.)***	***162***	***768***
Cleanup Status: COMPLETED - CASE CLOSED				
ARCO #4493	***205 N CENTER ST***	***NW 1/4 - 1/2 (0.477 mi.)***	***164***	***771***
Cleanup Status: COMPLETED - CASE CLOSED				
SIERRA LUMBER CASE #	***375 HAZELTON AVE W***	***WSW 1/4 - 1/2 (0.480 mi.)***	***165***	***778***
Cleanup Status: COMPLETED - CASE CLOSED				
CITY OF STOCKTON RED	***216 CALIFORNIA***	***N 1/4 - 1/2 (0.490 mi.)***	***169***	***816***
Cleanup Status: OPEN - SITE ASSESSMENT				

DRYCLEANERS: A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners' agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

A review of the DRYCLEANERS list, as provided by EDR, has revealed that there is 1 DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SNOW CLEANERS INC	***38 W SONORA ST***	***W 1/8 - 1/4 (0.228 mi.)***	***O109***	***533***
Database: DRYCLEANERS, Date of Government Version: 03/01/2021				
EPA Id: CAR000001032				

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency. This database begins with calendar year 1993.

A review of the HAZNET list, as provided by EDR, and dated 12/31/2019 has revealed that there is 1 HAZNET site within approximately 0.001 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GOSPEL CENTER RESCUE GEPAID: CAC002988264	***445 S. SAN JOAQUIN S***	***0 - 1/8 (0.001 mi.)***	***A1***	***178***

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 29 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FABRICARE Reg Id: 390340	***711 SAN JOAQUIN***	***SSE 1/8 - 1/4 (0.175 mi.)***	***J59***	***249***
PG&E, STOCKTON Reg Id: 39490015	***530 CENTER***	***WSW 1/8 - 1/4 (0.178 mi.)***	***H65***	***262***
STOCKTON PLATING INC Reg Id: 390106	***632 S EL DORADO ST***	***SSW 1/8 - 1/4 (0.180 mi.)***	***L68***	***289***
H/S AUTO REPAIR Reg Id: 390772	***300 CALIFORNIA***	***NE 1/8 - 1/4 (0.188 mi.)***	***K76***	***366***
PG&E GAS LOAD CENTER Reg Id: 390377	***535 CENTER***	***WSW 1/8 - 1/4 (0.200 mi.)***	***I86***	***399***
HUMAN SERVICES AGENC Reg Id: 390296	***145 SUTTER***	***NNE 1/8 - 1/4 (0.223 mi.)***	***N103***	***443***
MARKET STREET PARKIN Reg Id: 390368	134 SUTTER	N 1/8 - 1/4 (0.233 mi.)	N111	539
FIRE ENGINE COMPANY Reg Id: 390115	***110 SONORA***	***WSW 1/4 - 1/2 (0.290 mi.)***	***126***	***574***
SIEBOLD CONSTRUCTION Reg Id: 390394	***820 AMERICAN ST S***	***SE 1/4 - 1/2 (0.365 mi.)***	***132***	***596***
CONCRET, INC Reg Id: 390827	***749 STANISLAUS ST***	***ESE 1/4 - 1/2 (0.368 mi.)***	***T134***	***608***
GOODWILL INDUSTRIES Reg Id: 390249	***129 GRANT***	***NE 1/4 - 1/2 (0.410 mi.)***	***V150***	***683***
HICKINBOTHAM BROS LT Reg Id: 390312	***635 AURORA***	***E 1/4 - 1/2 (0.439 mi.)***	***154***	***749***
BEAULIEU CHEMICAL CO Reg Id: 39280007 Reg Id: 390747	400 AURORA	ENE 1/4 - 1/2 (0.468 mi.)	AA163	770
VALLEY MOTORS Reg Id: 390546	***800 MAIN ST E***	***NE 1/4 - 1/2 (0.483 mi.)***	***AB166***	***795***

Lower Elevation	Address	Direction / Distance	Map ID	Page
BRIDGESTONE/FIRESTON Reg Id: 390608 Reg Id: 390983	***400 EL DORADO ST N***	***W 0 - 1/8 (0.105 mi.)***	***D25***	***204***
DEN'S AUTO REPAIR	***308 S EL DORADO***	***WNW 1/8 - 1/4 (0.131 mi.)***	***E49***	***226***

Reg Id: 390889				
GATEWAY PROJECT Reg Id: 391090	***325 EL DORADO ST S***	***WNW 1/8 - 1/4 (0.134 mi.)***	***G54***	***239***
SHELL BULK PLANT Reg Id: 390247	38 SONORA	W 1/8 - 1/4 (0.210 mi.)	O91	411
STOCKTON POLICE DEPA Reg Id: 390238	***22 MARKET ST E***	***NW 1/4 - 1/2 (0.251 mi.)***	***R122***	***562***
CANLIS BLDG Reg Id: 390710	***24 HUNTER ST S***	***NNW 1/4 - 1/2 (0.274 mi.)***	***123***	***564***
CHEVRON #9-0557 Reg Id: 390502	***139 CENTER ST S***	***NW 1/4 - 1/2 (0.279 mi.)***	***R124***	***566***
GREYHOUND LINES INC Reg Id: 390654	***121 CENTER ST S***	***WNW 1/4 - 1/2 (0.301 mi.)***	***129***	***585***
REYNOSO CONCRETE CON Reg Id: 390735	***729 COMMERCE ST S***	***SW 1/4 - 1/2 (0.341 mi.)***	***130***	***592***
SAN JOAQUIN COUNTY C Reg Id: 390610	***222 WEBER AVE E***	***NNW 1/4 - 1/2 (0.365 mi.)***	***S133***	***605***
PARKING GARAGE Reg Id: 390862	***130 HUNTER***	***NNW 1/4 - 1/2 (0.425 mi.)***	***Y153***	***743***
WEBER ENTERPRISES Reg Id: 390538	***141 EL DORADO ST N***	***NNW 1/4 - 1/2 (0.440 mi.)***	***Z155***	***752***
E.F. MITCHLER CO Reg Id: 390717	***400 LINCOLN***	***WSW 1/4 - 1/2 (0.464 mi.)***	***162***	***768***
ARCO #4493 Reg Id: 390586	***205 N CENTER ST***	***NW 1/4 - 1/2 (0.477 mi.)***	***164***	***771***
SIERRA LUMBER CASE # Reg Id: 390257	***375 HAZELTON AVE W***	***WSW 1/4 - 1/2 (0.480 mi.)***	***165***	***778***

HWP: Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

A review of the HWP list, as provided by EDR, and dated 05/14/2021 has revealed that there is 1 HWP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MCCORMICK & BAXTER C EPA ID: CAD009106527 Cleanup Status: CLOSED	***1214 W WASHINGTON ST***	***WSW 1/2 - 1 (0.741 mi.)***	***0***	***9***

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 03/12/2021 has revealed that there are 17 Notify 65 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HUMAN SERVICES AGENC	***145 SUTTER***	***NNE 1/8 - 1/4 (0.223 mi.)***	***N103***	***443***

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
J.C. TRUCKING	*1207 S AURORA ST*	*SE 1/2 - 1 (0.701 mi.)*	*178*	*870*
GASCO	*749 CHARTER WAY E*	*SE 1/2 - 1 (0.728 mi.)*	*AD181*	*882*
STALLWORTH AUTO DETA	*602 CALIFORNIA ST N*	*N 1/2 - 1 (0.752 mi.)*	*187*	*951*
MORITA BROTHERS	*814 CHARTER*	*SE 1/2 - 1 (0.758 mi.)*	*AD188*	*965*
WIGHT ENTERPRISES #2	*130 S WILSON WAY*	*ENE 1/2 - 1 (0.911 mi.)*	*195*	*1023*
STOCKTON DEVELOPMENT	*1252 STANISLAUS ST*	*NNE 1/2 - 1 (0.966 mi.)*	*198*	*1047*

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO #4493	*205 N CENTER ST*	*NW 1/4 - 1/2 (0.477 mi.)*	*164*	*771*
CITY OF STOCKTON RED	*216 CALIFORNIA*	*N 1/4 - 1/2 (0.490 mi.)*	*169*	*816*
SUTTER OFFICE CENTER	*242 SUTTER ST*	*N 1/2 - 1 (0.522 mi.)*	*170*	*823*
CANCUN RESTAURANT	*135 MINER*	*NNW 1/2 - 1 (0.534 mi.)*	*171*	*832*
CHASE CHEVROLET CO	*432 N. MADISON*	*NW 1/2 - 1 (0.741 mi.)*	*AE182*	*897*
CRYSTAL CREAM & BUTT	*404 FREMONT*	*NW 1/2 - 1 (0.742 mi.)*	*184*	*938*
GENE GABBARD INC	*640 EL DORADO ST*	*NNW 1/2 - 1 (0.780 mi.)*	*189*	*970*
ARCO #2168 (FORMER)	*441 CHARTER WAY W*	*SSW 1/2 - 1 (0.822 mi.)*	*AF190*	*975*
TEXACO	*440 CHARTER*	*SSW 1/2 - 1 (0.830 mi.)*	*AF191*	*988*
THE TRANSMISSION STO	*515 CHARTER WAY W*	*SSW 1/2 - 1 (0.856 mi.)*	*193*	*1006*

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PG AND E GAS PLANT S	530 S CENTER ST (IS	WSW 1/8 - 1/4 (0.178 mi.)	H66	287

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 24 EDR Hist Auto

sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A ECKERT C W AUTO RE	302 S SAN JOAQUIN ST	N 0 - 1/8 (0.087 mi.)	B11	187
A FUJIMOTO R Y GAS S	502 S EL DORADO ST	SW 0 - 1/8 (0.101 mi.)	D22	204
EILAT MARCELI AUTO	318 E LAFAYETTE ST	NNE 0 - 1/8 (0.101 mi.)	23	204
A GOOLD BROS GAS STA	502 EL DORADO S	WSW 0 - 1/8 (0.110 mi.)	D32	212
FORD BERT AUTO REPR	518 EL DORADO S	WSW 0 - 1/8 (0.112 mi.)	D36	213
ERNST BENJ AUTO REPR	520 EL DORADO S	WSW 0 - 1/8 (0.112 mi.)	D37	213
A IWAHASHI TOM AUTO	520 S EL DORADO ST	SW 0 - 1/8 (0.116 mi.)	40	214

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOUIES GARAGE AUTO R	336 S HUNTER ST	NW 0 - 1/8 (0.052 mi.)	C6	185
CHOY BEN AUTO SERVIC	336 HUNTER ST S	NW 0 - 1/8 (0.063 mi.)	C8	186
LOUIES GARAGE AUTO R	325 S HUNTER ST	WNW 0 - 1/8 (0.094 mi.)	C14	188
SKEETERS AUTOMATIC T	448 S EL DORADO ST	WSW 0 - 1/8 (0.099 mi.)	D17	192
CANHAM M L GAS STA	440 S EL DORADO ST	WSW 0 - 1/8 (0.099 mi.)	D18	192
ALCON TIRE SHOP AUTO	410 S EL DORADO ST	W 0 - 1/8 (0.100 mi.)	D20	201
ASONORA SERV STA	402 S EL DORADO ST	W 0 - 1/8 (0.104 mi.)	D24	204
KNOWLES SERV STA NO	447 EL DORADO S	W 0 - 1/8 (0.107 mi.)	D26	208
AH TYE BROS	448 EL DORADO S	W 0 - 1/8 (0.107 mi.)	D28	211
SKEETERS AUTOMATIC	448 EL DORADO ST S	W 0 - 1/8 (0.107 mi.)	D29	211
TOYS GARAGE AUTO REP	410 EL DORADO ST S	W 0 - 1/8 (0.110 mi.)	D30	211
TOYS CHEVRON SERV	410 EL DORADO S	W 0 - 1/8 (0.110 mi.)	D31	211
AH TYE DILLY GAS STA	402 EL DORADO S	W 0 - 1/8 (0.112 mi.)	D33	212
RED D SERV GAS STA	401 EL DORADO S	W 0 - 1/8 (0.112 mi.)	D34	212
NOMELLINIS ENCO SERV	401 EL DORADO ST S	W 0 - 1/8 (0.112 mi.)	D35	212
AKAJIWARA H AUTO REP	135 E LAFAYETTE ST	NW 0 - 1/8 (0.123 mi.)	E44	216
CARTER F H GAS STA	401 S EL DORADO ST	W 0 - 1/8 (0.124 mi.)	D45	216

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 10 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A SALABER FRANK DO	348 S SAN JOAQUIN ST	NNE 0 - 1/8 (0.047 mi.)	B4	182
NING TOM LAUNDRY	329 S SAN JOAQUIN ST	N 0 - 1/8 (0.061 mi.)	B7	186
ACME CLNS	348 SAN JOAQUIN S	N 0 - 1/8 (0.067 mi.)	B9	186
A SALOBER FRANK INDY	344 SAN JOAQUIN S	N 0 - 1/8 (0.070 mi.)	B10	187
SAITO K LNDY	246 S SAN JOAQUIN ST	N 0 - 1/8 (0.093 mi.)	B12	187
WASH HOUSE THE SELF	613 S SAN JOAQUIN ST	SSE 0 - 1/8 (0.113 mi.)	F38	213

Lower Elevation	Address	Direction / Distance	Map ID	Page
ATROXELL AGNES MRS C	243 HUNTER S	NW 0 - 1/8 (0.093 mi.)	C13	187
COLONIAL CLEANERS	130 E LAFAYETTE ST	NW 0 - 1/8 (0.116 mi.)	E39	213
HERNANDO R C MRS CLD	346 EL DORADO S	WNW 0 - 1/8 (0.118 mi.)	G41	214

EXECUTIVE SUMMARY


Lower Elevation	Address	Direction / Distance	Map ID	Page
CALIFORNIA LNDY	118 E LAFAYETTE ST	NW 0 - 1/8 (0.125 mi.)	E46	216

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 8 records.

Site Name	Database(s)
SAN JOAQUIN COUNTY MOTOR POOL	LUST, Cortese
SAN JOAQUIN COUTY MOTOR POOL	LUST
EL DORADO APARTMENTS DEVELOPMENT (	CPS-SLIC
KOPPEL STOCKTON TERMINAL	CPS-SLIC
HYDROAGRI NORTH AMERICA, HJ BAKER	CPS-SLIC
UNION ICE COMPANY [ARCHIVED]	CPS-SLIC
MULTI-MODAL SIX-BLOCK PROJECT	CPS-SLIC
STOCKTON REDEVEL AGENCY- NORTHSHOR	CPS-SLIC

OVERVIEW MAP - 6607856.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/4 1/2 1 Miles

Indian Reservations BIA

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands


Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	New Life Mens Facility	CLIENT:	Condor Earth Technologies, Inc
ADDRESS:	429 S. San Joaquin Street Stockton CA 95203	CONTACT:	Rebecca Selvage
LAT/LONG:	37.948629 / 121.286367	INQUIRY #:	6607856.2s
		DATE:	August 05, 2021 1:34 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6607856.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	New Life Mens Facility	CLIENT:	Condor Earth Technologies, Inc
ADDRESS:	429 S. San Joaquin Street Stockton CA 95203	CONTACT:	Rebecca Selvage
LAT/LONG:	37.948629 / 121.286367	INQUIRY #:	6607856.2s
		DATE:	August 05, 2021 1:36 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	2	2	NR	NR	4
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	1	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	4	NR	NR	NR	4
RCRA-SQG	0.250		0	1	NR	NR	NR	1
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
RESPONSE	1.000		0	0	2	1	NR	3
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.000		0	3	7	17	NR	27
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	1	0	NR	NR	1
State and tribal leaking storage tank lists								
LUST	0.500		1	7	24	NR	NR	32

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		0	3	4	NR	NR	7
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		2	16	NR	NR	NR	18
AST	0.250		0	2	NR	NR	NR	2
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
VCP	0.500		0	1	3	NR	NR	4
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	9	NR	NR	9
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	1	NR	NR	1
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	1	2	NR	3
SCH	0.250		0	1	NR	NR	NR	1
CDL	0.001		0	NR	NR	NR	NR	0
CERS HAZ WASTE	0.250		1	5	NR	NR	NR	6
Toxic Pits	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250		2	13	NR	NR	NR	15
HIST UST	0.250		0	17	NR	NR	NR	17
CA FID UST	0.250		2	13	NR	NR	NR	15
CERS TANKS	0.250		0	3	NR	NR	NR	3
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
DEED	0.500		0	1	2	NR	NR	3
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		4	8	NR	NR	NR	12
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	1	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		1	NR	NR	NR	NR	1
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		1	NR	NR	NR	NR	1
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	1	NR	1
Cortese	0.500		1	7	23	NR	NR	31
CUPA Listings	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DRYCLEANERS	0.250		0	1	NR	NR	NR	1
EMI	0.001		0	NR	NR	NR	NR	0
ENF	0.001		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
HAZNET	0.001		1	NR	NR	NR	NR	1
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500		1	10	18	NR	NR	29
HWP	1.000		0	0	0	1	NR	1
HWT	0.250		0	0	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	1	2	14	NR	17
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	0.001		0	NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
CIWQS	0.001		0	NR	NR	NR	NR	0
CERS	0.001		0	NR	NR	NR	NR	0
NON-CASE INFO	0.001		0	NR	NR	NR	NR	0
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
HWTS	TP		NR	NR	NR	NR	NR	0
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	1	0	0	NR	1
EDR Hist Auto	0.125		24	NR	NR	NR	NR	24
EDR Hist Cleaner	0.125		10	NR	NR	NR	NR	10
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals --		0	51	121	98	39	0	309

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

NPL
Region
WSW
1/2-1
3915 ft.

MCCORMICK & BAXTER CREOSOTING CO.
1214 W WASHINGTON ST
STOCKTON, CA 95203

Database(s):
NPL
SEMS
CORRACTS
RCRA-TSDF
RCRA-SQG
US ENG CONTROLS
US INST CONTROLS
ENVIROSTOR
UST
HIST Cal-Sites
SWEEPS UST
HIST UST
CA FID UST
DEED
ROD
PRP
Cortese
HWP
CERS

EDR ID Number: 1000341540
EPA ID Number: CAD009106527

NPL:

EPA Region:	9
EPA ID:	CAD009106527
Site ID:	901129
Name:	MCCORMICK & BAXTER CREOSOTING CO.
Address:	1214 W WASHINGTON ST
City,State,Zip:	STOCKTON, CA 95203
Federal:	N
Final Date:	1992-10-14 00:00:00
Latitude:	37.947851
Longitude:	-121.306635
Site Score:	74.859999999999999

NPL:

NPL Status:	Currently on the Final NPL
Substance ID:	C049
CAS Number:	100-41-4
Substance:	ETHYLBENZENE
Pathway:	GROUND WATER PATHWAY
Scoring:	2

NPL Status:	Currently on the Final NPL
Substance ID:	C178
CAS Number:	Not reported
Substance:	COPPER AND COMPOUNDS
Pathway:	NO PATHWAY INDICATED
Scoring:	1

NPL Status:	Currently on the Final NPL
Substance ID:	C247
CAS Number:	Not reported
Substance:	ZINC AND COMPOUNDS
Pathway:	NO PATHWAY INDICATED
Scoring:	1

NPL Status:	Currently on the Final NPL
Substance ID:	C332
CAS Number:	85-01-8
Substance:	PHENANTHRENE
Pathway:	GROUND WATER PATHWAY

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Scoring:	2
NPL Status:	Currently on the Final NPL
Substance ID:	C334
CAS Number:	83-32-9
Substance:	ACENAPHTHENE
Pathway:	GROUND WATER PATHWAY
Scoring:	2
NPL Status:	Currently on the Final NPL
Substance ID:	C385
CAS Number:	129-00-0
Substance:	PYRENE
Pathway:	NO PATHWAY INDICATED
Scoring:	1
NPL Status:	Currently on the Final NPL
Substance ID:	C431
CAS Number:	86-73-7
Substance:	FLUORENE
Pathway:	GROUND WATER PATHWAY
Scoring:	2
NPL Status:	Currently on the Final NPL
Substance ID:	Not reported
CAS Number:	Not reported
Substance:	Not reported
Pathway:	Not reported
Scoring:	Not reported
NPL Status:	Currently on the Final NPL
Substance ID:	A009
CAS Number:	207-08-9
Substance:	BENZO(K)FLUORANTHENE
Pathway:	NO PATHWAY INDICATED
Scoring:	1
NPL Status:	Currently on the Final NPL
Substance ID:	A083
CAS Number:	4901-51-3
Substance:	TETRACHLOROPHENOL, 2,3,4,5-
Pathway:	GROUND WATER PATHWAY
Scoring:	2
NPL Status:	Currently on the Final NPL
Substance ID:	A084
CAS Number:	935-95-5
Substance:	TETRACHLOROPHENOL, 2,3,5,6-
Pathway:	GROUND WATER PATHWAY
Scoring:	2
NPL Status:	Currently on the Final NPL
Substance ID:	A090
CAS Number:	609-19-8
Substance:	TRICHLOROPHENOL, 3,4,5-
Pathway:	GROUND WATER PATHWAY
Scoring:	2

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

NPL Status: Currently on the Final NPL
Substance ID: C013
CAS Number: 120-12-7
Substance: ANTHRACENE
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: C448
CAS Number: 205-99-2
Substance: BENZOFLUORANTHENE, 3,4-
Pathway: SURFACE WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: C516
CAS Number: 1300-71-6
Substance: DIMETHYLPHENOL
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: D004
CAS Number: 7440-38-2
Substance: ARSENIC
Pathway: AIR PATHWAY
Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: D004
CAS Number: 7440-38-2
Substance: ARSENIC
Pathway: GROUND WATER PATHWAY
Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: D007
CAS Number: 7440-47-3
Substance: CHROMIUM
Pathway: GROUND WATER PATHWAY
Scoring: 4

NPL Status: Currently on the Final NPL
Substance ID: U022
CAS Number: 50-32-8
Substance: BENZO(A)PYRENE
Pathway: SURFACE WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U050
CAS Number: 218-01-9
Substance: CHRYSENE
Pathway: NO PATHWAY INDICATED
Scoring: 1

NPL Status: Currently on the Final NPL

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Substance ID: U063
CAS Number: 53-70-3
Substance: DIBENZ(A,H)ANTHRACENE
Pathway: SURFACE WATER PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U081
CAS Number: 120-83-2
Substance: DICHLOROPHENOL, 2,4-
Pathway: AIR PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U081
CAS Number: 120-83-2
Substance: DICHLOROPHENOL, 2,4-
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U120
CAS Number: 206-44-0
Substance: BENZO(J,K)FLUORENE
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U165
CAS Number: 91-20-3
Substance: NAPHTHALENE
Pathway: AIR PATHWAY
Scoring: 3

NPL Status: Currently on the Final NPL
Substance ID: U165
CAS Number: 91-20-3
Substance: NAPHTHALENE
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U170
CAS Number: 100-02-7
Substance: NITROPHENOL, 4-
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U188
CAS Number: 108-95-2
Substance: PHENOL
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U220

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

CAS Number: 108-88-3
Substance: TOLUENE
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U239
CAS Number: 1330-20-7
Substance: XYLENE
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U242
CAS Number: 87-86-5
Substance: PENTACHLOROPHENOL (PCP)
Pathway: AIR PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U242
CAS Number: 87-86-5
Substance: PENTACHLOROPHENOL (PCP)
Pathway: GROUND WATER PATHWAY
Scoring: 2

NPL Status: Currently on the Final NPL
Substance ID: U242
CAS Number: 87-86-5
Substance: PENTACHLOROPHENOL (PCP)
Pathway: SURFACE WATER PATHWAY
Scoring: 2

Summary Details:

Conditions at Proposal February 7, 1992): McCormick Baxter Creosoting Co. formerly operated a wood-preserving facility at 1214 West Washington Street in Stockton, San Joaquin County, California. The 29-acre site is in a light industrial area near the Port of Stockton. Old Mormon Slough, a tributary to the San Joaquin River, borders the site to the north. Except for an 8- acre portion of the site owned and leased by Southern Pacific Railroad Co. since the 1950s, McCormick Baxter owns the entire site property. From 1942 to 1990, McCormick Baxter treated utility poles and railroad ties with creosote, pentachlorophenol PCP), and arsenic compounds. Waste oils generated from the wood-treatment processes were disposed of in unlined ponds and concrete tanks on-site. Surface water runoff from the site was discharged to the slough until 1978, when it began to collect in two storm water collection ponds. In 1983 and 1984, a consultant to McCormickBaxter found that soils throughout the site were contaminated with arsenic, chromium, copper, PCP, and polycyclic aromatic hydrocarbons PAHs), which are constituents of creosote. Soil contamination extends to depths of 40 feet below ground surface bgs) in some areas. The consultant s sampling in 1984-88 indicates that the shallow aquifer beneath the site is contaminated with many of the same substances to a depth of 175 feet bgs. Beneath the site, the shallow aquifer is interconnected with the deep aquifer. The deep aquifer within 4 miles of the site provides drinking water to approximately 97,000 people. In 1989, the California Department of Toxic Substances Control CDTSC) detected arsenic and PCP air particulates on-site.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Approximately 105,000 people live and work within 4 miles of the site. In 1977, the California Department of Fish and Game CDFG) investigated a fish kill in Old Mormon Slough and the Port of Stockton. The CDFG investigationconcluded that the fish kill resulted from PCB-contaminated storm water runoff from the site. The California Regional Water Quality Control Board issued a Cleanup and Abatement Order to McCormick Baxter in January 1978. In response, McCormick Baxter installed two storm water collection ponds and a perimeter dike around the site. People currently fish in Old Mormon Slough and the San Joaquin River. In October 1984, McCormick Baxter received a permit for a concrete oily-water treatment tank and a drum storage area under Subtitle C of the Resource Conservation and Recovery Act RCRA). With CDTSC approval, the company completed a RCRA clean closure of the permitted units in 1990. The storm water collection ponds are under Interim Status as RCRA ha ardous waste management units. Status October 1992): The site is being added to the NPL because it satisfies a component of EPA s NPL/RCRA policy: in December 1988, the company filed for protectionunder Chapter 11 of the Federal bankruptcy code. In July 1992, EPA emergency staff took measures to improve site security and to inventory chemicals and sludges remaining on- site. EPA has conducted a search to identify parties potentially responsible for wastes associated with the site and will solicit the participation of those identified in cleaning up the site. The description of the site release) is based on information available at the time the site was scored.The description may change as additional information is gathered on the sources and extent of contamination. See FR 5600, February 11, 1991 or subsequent FR notices.)

NPL:
NPL Name: MCCORMICK & BAXTER CREOSOTING CO.

NPL:
EPA Region: 09
Site ID: 0901129
Site Status: F
Federal Site: N
Date Deleted: Not reported
Date Finalized: 10/14/92
Date Proposed: 02/07/92

NPL:
Proposed Date: 02/07/1992
Final Date: 10/14/1992
Deleted Date: Not reported
NPL Status: Final

SEMS:
Site ID: 0901129
EPA ID: CAD009106527
Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
Cong District: 11,9
FIPS Code: 06077
Latitude: 37.947851

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Longitude: -121.306635
FF: N
NPL: Currently on the Final NPL
Non NPL Status: Not reported

SEMS Detail:

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: MA
Action Name: ST COOP
SEQ: 1
Start Date: 1991-09-30 04:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: FE
Action Name: 5 YEAR
SEQ: 1
Start Date: 2008-09-10 04:00:00
Finish Date: 9/10/2008 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: CR
Action Name: CI
SEQ: 1
Start Date: 2006-01-12 05:00:00
Finish Date: 1/12/2006 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 03

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Action Code:	RA
Action Name:	RA
SEQ:	2
Start Date:	1999-09-30 04:00:00
Finish Date:	6/10/2015 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1984-04-01 06:00:00
Finish Date:	4/1/1984 6:00:00 AM
Qual:	H
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	RV
Action Name:	RMVL
SEQ:	3
Start Date:	2006-06-29 04:00:00
Finish Date:	9/30/2007 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	RV
Action Name:	RMVL
SEQ:	4
Start Date:	2007-06-05 04:00:00
Finish Date:	9/4/2007 4:00:00 AM
Qual:	C
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

NPL:	F
FF:	N
OU:	00
Action Code:	MA
Action Name:	ST COOP
SEQ:	2
Start Date:	2010-10-07 04:00:00
Finish Date:	10/7/2010 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	MA
Action Name:	ST COOP
SEQ:	3
Start Date:	2010-10-07 04:00:00
Finish Date:	10/7/2010 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	MA
Action Name:	ST COOP
SEQ:	4
Start Date:	2010-10-07 04:00:00
Finish Date:	10/7/2010 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	01
Action Code:	RD
Action Name:	RD
SEQ:	3
Start Date:	1999-03-31 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	FE
Action Name:	5 YEAR
SEQ:	2
Start Date:	2013-09-26 05:00:00
Finish Date:	9/26/2013 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	1992-02-07 05:00:00
Finish Date:	2/7/1992 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	03
Action Code:	CO
Action Name:	RI/FS
SEQ:	3
Start Date:	1994-09-28 04:00:00
Finish Date:	3/31/1999 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	02
Action Code:	RD
Action Name:	RD
SEQ:	1
Start Date:	1999-03-31 05:00:00
Finish Date:	9/28/2006 4:00:00 AM
Qual:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 2
Start Date: 1996-08-19 04:00:00
Finish Date: 9/26/1997 4:00:00 AM
Qual: C
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1998-09-15 04:00:00
Finish Date: 9/15/1998 4:00:00 AM
Qual: E
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: FE
Action Name: 5 YEAR
SEQ: 3
Start Date: 2018-09-24 05:00:00
Finish Date: 9/24/2018 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Start Date: 1979-10-01 04:00:00
Finish Date: 10/1/1979 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1984-04-01 06:00:00
Finish Date: 4/1/1984 6:00:00 AM
Qual: L
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 01
Action Code: RO
Action Name: ROD
SEQ: 1
Start Date: 1999-03-31 05:00:00
Finish Date: 3/31/1999 5:00:00 AM
Qual: R
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 01
Action Code: CO
Action Name: RI/FS
SEQ: 1
Start Date: 1992-06-30 04:00:00
Finish Date: 3/31/1999 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 00

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Action Code:	RV
Action Name:	RMVL
SEQ:	1
Start Date:	1992-07-08 04:00:00
Finish Date:	9/26/1997 4:00:00 AM
Qual:	P
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	1992-12-30 05:00:00
Finish Date:	12/30/1992 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	03
Action Code:	RD
Action Name:	RD
SEQ:	2
Start Date:	1999-03-31 05:00:00
Finish Date:	8/23/1999 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	ES
Action Name:	ESI
SEQ:	1
Start Date:	1989-09-19 04:00:00
Finish Date:	6/10/1991 4:00:00 AM
Qual:	G
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

NPL:	F
FF:	N
OU:	00
Action Code:	NF
Action Name:	NPL FINL
SEQ:	1
Start Date:	1992-10-14 04:00:00
Finish Date:	10/14/1992 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	HR
Action Name:	HAZRANK
SEQ:	1
Start Date:	1984-04-01 06:00:00
Finish Date:	4/1/1984 6:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	CR
Action Name:	CI
SEQ:	2
Start Date:	2018-02-26 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	01
Action Code:	CO
Action Name:	RI/FS
SEQ:	4
Start Date:	2008-09-30 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	02
Action Code:	BE
Action Name:	PRP RD
SEQ:	1
Start Date:	2006-09-28 04:00:00
Finish Date:	9/30/2008 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	02
Action Code:	BF
Action Name:	PRP RA
SEQ:	1
Start Date:	2008-09-30 04:00:00
Finish Date:	9/28/2012 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	00
Action Code:	BB
Action Name:	PRP RV
SEQ:	1
Start Date:	2006-06-24 04:00:00
Finish Date:	6/25/2006 4:00:00 AM
Qual:	S
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901129
EPA ID:	CAD009106527
Site Name:	MCCORMICK & BAXTER CREOSOTING CO.
NPL:	F
FF:	N
OU:	03
Action Code:	OM
Action Name:	OM
SEQ:	1
Start Date:	2015-06-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Current Action Lead: St Perf

Region: 09
Site ID: 0901129
EPA ID: CAD009106527
Site Name: MCCORMICK & BAXTER CREOSOTING CO.
NPL: F
FF: N
OU: 02
Action Code: OM
Action Name: OM
SEQ: 2
Start Date: 2012-09-28 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: St Perf

CORRACTS:

Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W WASHINGTON ST
Address 2: Not reported
EPA ID: CAD009106527
Area Name: ENTIRE FACILITY
Corrective Action: CA PRIORITIZATION-HIGH CA PRIORITY
Actual Date: 00:00.0
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W WASHINGTON ST
Address 2: Not reported
EPA ID: CAD009106527
Area Name: ENTIRE FACILITY
Corrective Action: REFERRED TO A NON-RCRA AUTHORITY-REFERRED TO CERCLA
Actual Date: 00:00.0
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W WASHINGTON ST
Address 2: Not reported
EPA ID: CAD009106527
Area Name: ENTIRE FACILITY
Corrective Action: REFERRED TO A NON-RCRA AUTHORITY-REFERRED TO CERCLA
Actual Date: 00:00.0
Air Release Indicator: Not reported
Groundwater Release Indicator: Not reported
Soil Release Indicator: Not reported
Surface Water Release Indicator: Not reported

RCRA-SQG:

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date Form Received by Agency:	2019-10-31 00:00:00.0
Handler Name:	MCCORMICK & BAXTER CREOSOTING CO
Handler Address:	1214 W WASHINGTON ST
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAD009106527
Contact Name:	MARK SAMOLIS
Contact Address:	1214 W WASHINGTON ST
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	415-947-4273
Contact Fax:	Not reported
Contact Email:	SAMOLIS.MARK@EPA.GOV
Contact Title:	Not reported
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	1
Mailing Address:	POST OFFICE BOX FIRST THOUSAND
Mailing City,State,Zip:	STOCKTON, CA 95201
Owner Name:	CHARLIE MCCORMICK
Owner Type:	Private
Operator Name:	MCCORMICK AND BAXTER CREOSOTING COMPANY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Storage, Treatment
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Storage, Treatment
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	Yes
Corrective Action Priority Ranking:	High
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-10-31 14:40:18.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: D011
Waste Description: SILVER

Waste Code: D012
Waste Description: ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE)

Waste Code: D013
Waste Description: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

Waste Code: D014
Waste Description: METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)

Waste Code: D015
Waste Description: TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D017
Waste Description: 2,4,5-TP SILVEX (2,4,5-TRICHLOROPHENOXYPROPIONIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D019
Waste Description: CARBON TETRACHLORIDE

Waste Code: D020
Waste Description: CHLORDANE

Waste Code: D021
Waste Description: CHLOROBENZENE

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D023
Waste Description: O-CRESOL

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D025
Waste Description: P-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D028
Waste Description: 1,2-DICHLOROETHANE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: D029
Waste Description: 1,1-DICHLOROETHYLENE

Waste Code: D030
Waste Description: 2,4-DINITROTOLUENE

Waste Code: D031
Waste Description: HEPTACHLOR (AND ITS EPOXIDE)

Waste Code: D032
Waste Description: HEXACHLOROBENZENE

Waste Code: D033
Waste Description: HEXACHLOROBUTADIENE

Waste Code: D034
Waste Description: HEXACHLOROETHANE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D036
Waste Description: NITROBENZENE

Waste Code: D037
Waste Description: PENTACHLOROPHENOL

Waste Code: D038
Waste Description: PYRIDINE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: D041
Waste Description: 2,4,5-TRICHLOROPHENOL

Waste Code: D042
Waste Description: 2,4,6-TRICHLOROPHENOL

Waste Code: D043
Waste Description: VINYL CHLORIDE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste Code: F007
Waste Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Waste Code: F008
Waste Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F009
Waste Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F010
Waste Description: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F011
Waste Description: SPENT CYANIDE SOLUTIONS FROM SLAT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.

Waste Code: F012
Waste Description: QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F019
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM, EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.

Waste Code: F020
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- OR TETRACHLOROPHENOL OR OF INTERMEDIATES USED TO PRODUCE THEIR PESTICIDE DERIVATIVES. (THIS LISTING DOES NOT INCLUDE WASTES FROM THE PRODUCTION OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F021
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF PENTACHLOROPHENOL, OR OF INTERMEDIATES USED TO PRODUCE DERIVATIVES.

Waste Code: F022
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENES UNDER ALKALINE CONDITIONS.

Waste Code: F023
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- AND TETRACHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE WASTES FROM EQUIPMENT USED ONLY FOR THE PRODUCTION OR USE OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F024
Waste Description: PROCESS WASTES INCLUDING, BUT NOT LIMITED TO, DISTILLATION RESIDUES, HEAVY ENDS, TARS, AND REACTOR CLEAN-OUT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION. (THIS LISTING DOES NOT INCLUDE WASTEWATERS, WASTEWATER TREATMENT SLUDGE, SPENT

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

CATALYSTS, AND WASTES LISTED IN SECTIONS 261.31. OR 261.32)

Waste Code: F025
Waste Description: CONDENSED LIGHT ENDS, SPENT FILTERS AND FILTER AIDS, AND SPENT DESICCANT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION.

Waste Code: F026
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENE UNDER ALKALINE CONDITIONS.

Waste Code: F027
Waste Description: DISCARDED UNUSED FORMULATIONS CONTAINING TRI-, TETRA-, OR PENTACHLOROPHENOL OR DISCARDED UNUSED FORMULATIONS CONTAINING COMPOUNDS DERIVED FROM THESE CHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE FORMULATIONS CONTAINING HEXACHLOROPHENE SYNTHESIZED FROM PREPURIFIED 2,4,5-TRICHLOROPHENOL AS THE SOLE COMPONENT.)

Waste Code: F028
Waste Description: RESIDUES RESULTING FROM THE INCINERATION OR THERMAL TREATMENT OF SOIL CONTAMINATED WITH EPA HAZARDOUS WASTE NOS. F020, F021, F022, F023, F026, AND F027.

Waste Code: F032
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT CURRENTLY USE, OR HAVE PREVIOUSLY USED, CHLOROPHENOLIC FORMULATIONS [EXCEPT POTENTIALLY CROSS-CONTAMINATED WASTES THAT HAVE HAD THE F032 WASTE CODE DELETED IN ACCORDANCE WITH SECTION 261.35 (I.E., THE NEWLY PROMULGATED EQUIPMENT CLEANING OR REPLACEMENT STANDARDS), AND WHERE THE GENERATOR DOES NOT RESUME OR INITIATE USE OF CHLOROPHENOLIC FORMULATIONS]. (THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSE THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.)

Waste Code: F034
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: F035
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE INORGANIC PRESERVATIVES CONTAINING ARSENIC OR CHROMIUM. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: F037

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: PETROLEUM REFINERY PRIMARY OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE GENERATED FROM THE GRAVITATIONAL SEPARATION OF OIL/WATER/SOLIDS DURING THE STORAGE OR TREATMENT OF PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH SLUDGES INCLUDE, BUT ARE NOT LIMITED TO, THOSE GENERATED IN OIL/WATER/SOLIDS SEPARATORS; TANKS AND IMPOUNDMENTS; DITCHES AND OTHER CONVEYANCES; SUMPS; AND STORM WATER UNITS RECEIVING DRY WEATHER FLOW. SLUDGES GENERATED IN STORM WATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F038
Waste Description: PETROLEUM REFINERY SECONDARY (EMULSIFIED) OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE AND/OR FLOAT GENERATED FROM THE PHYSICAL AND/OR CHEMICAL SEPARATION OF OIL/WATER/SOLIDS IN PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH WASTES INCLUDE, BUT ARE NOT LIMITED TO, ALL SLUDGES AND FLOATS GENERATED IN INDUCED AIR FLOTATION (IAF) UNITS, TANKS AND IMPOUNDMENTS, AND ALL SLUDGES GENERATED IN DAF UNITS. SLUDGES GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND F037, K048, AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F039
Waste Description: LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Waste Code: K001
Waste Description: BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATERS FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: K002
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME YELLOW AND ORANGE PIGMENTS.

Waste Code: K003
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF MOLYBDATE ORANGE PIGMENTS.

Waste Code: K004
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF ZINC YELLOW PIGMENTS.

Waste Code: K005
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME GREEN PIGMENTS.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K006
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS (ANHYDROUS AND HYDRATED).

Waste Code: K007
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF IRON BLUE PIGMENTS.

Waste Code: K008
Waste Description: OVEN RESIDUE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS.

Waste Code: K009
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K010
Waste Description: DISTILLATION SIDE CUTS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K011
Waste Description: BOTTOM STREAM FROM THE WASTEWATER STRIPPER IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K013
Waste Description: BOTTOM STREAM FROM THE ACETONITRILE COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K014
Waste Description: BOTTOMS FROM THE ACETONITRILE PURIFICATION COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K015
Waste Description: STILL BOTTOMS FROM THE DISTILLATION OF BENZYL CHLORIDE.

Waste Code: K016
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE PRODUCTION OF CARBON TETRACHLORIDE.

Waste Code: K017
Waste Description: HEAVY ENDS (STILL BOTTOMS) FROM THE PURIFICATION COLUMN IN THE PRODUCTION OF EPICHLOROHYDRIN.

Waste Code: K018
Waste Description: HEAVY ENDS FROM THE FRACTIONATION COLUMN IN ETHYL CHLORIDE PRODUCTION.

Waste Code: K019
Waste Description: HEAVY ENDS FROM THE DISTILLATION OF ETHYLENE DICHLORIDE IN ETHYLENE DICHLORIDE PRODUCTION.

Waste Code: K020
Waste Description: HEAVY ENDS FROM THE DISTILLATION OF VINYL CHLORIDE IN VINYL CHLORIDE MONOMER PRODUCTION.

Waste Code: K021
Waste Description: AQUEOUS SPENT ANTIMONY CATALYST WASTE FROM FLUOROMETHANE PRODUCTION.

Waste Code: K022
Waste Description: DISTILLATION BOTTOM TARS FROM THE PRODUCTION OF PHENOL/ACETONE FROM

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

CUMENE.

Waste Code: K023
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K024
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K025
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF NITROBENZENE BY THE NITRATION OF BENZENE.

Waste Code: K026
Waste Description: STRIPPING STILL TAILS FROM THE PRODUCTION OF METHYL ETHYL PYRIDINES.

Waste Code: K027
Waste Description: CENTRIFUGE AND DISTILLATION RESIDUES FROM TOLUENE DIISOCYANATE PRODUCTION.

Waste Code: K028
Waste Description: SPENT CATALYST FROM THE HYDROCHLORINATOR REACTOR IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K029
Waste Description: WASTE FROM THE PRODUCT STEAM STRIPPER IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K030
Waste Description: COLUMN BOTTOMS OR HEAVY ENDS FROM THE COMBINED PRODUCTION OF TRICHLOROETHYLENE AND PERCHLOROETHYLENE.

Waste Code: K031
Waste Description: BY-PRODUCT SALTS GENERATED IN THE PRODUCTION OF MSMA AND CACODYLIC ACID.

Waste Code: K032
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHLORDANE.

Waste Code: K033
Waste Description: WASTEWATER AND SCRUB WATER FROM THE CHLORINATION OF CYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K034
Waste Description: FILTER SOLIDS FROM THE FILTRATION OF HEXACHLOROCYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K035
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED IN THE PRODUCTION OF CREOSOTE.

Waste Code: K036
Waste Description: STILL BOTTOMS FROM TOLUENE RECLAMATION DISTILLATION IN THE PRODUCTION OF DISULFOTON.

Waste Code: K037
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF DISULFOTON.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K038
Waste Description: WASTEWATER FROM THE WASHING AND STRIPPING OF PHORATE PRODUCTION.

Waste Code: K039
Waste Description: FILTER CAKE FROM THE FILTRATION OF DIETHYLPHOSPHORODITHIOIC ACID IN THE PRODUCTION OF PHORATE.

Waste Code: K040
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF PHORATE.

Waste Code: K041
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K042
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE DISTILLATION OF TETRACHLOROBENZENE IN THE PRODUCTION OF 2,4,5-T.

Waste Code: K043
Waste Description: 2,6-DICHLOROPHENOL WASTE FROM THE PRODUCTION OF 2,4-D.

Waste Code: K044
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING AND PROCESSING OF EXPLOSIVES.

Waste Code: K045
Waste Description: SPENT CARBON FROM THE TREATMENT OF WASTEWATER CONTAINING EXPLOSIVES.

Waste Code: K046
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING, FORMULATION, AND LOADING OF LEAD-BASED INITIATING COMPOUNDS.

Waste Code: K047
Waste Description: PINK/RED WATER FROM TNT OPERATIONS.

Waste Code: K048
Waste Description: DISSOLVED AIR FLOTATION (DAF) FLOAT FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K049
Waste Description: SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K050
Waste Description: HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K051
Waste Description: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K052
Waste Description: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K060
Waste Description: AMMONIA STILL LIME SLUDGE FROM COKING OPERATIONS.

Waste Code: K061
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K062
Waste Description: SPENT PICKLE LIQUOR FROM STEEL FINISHING OPERATIONS OF PLANTS THAT PRODUCE IRON OR STEEL.

Waste Code: K069
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K071
Waste Description: BRINE PURIFICATION MUDS FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION, IN WHICH SEPARATELY PREPURIFIED BRINE IS NOT USED.

Waste Code: K073
Waste Description: CHLORINATED HYDROCARBON WASTE FROM THE PURIFICATION STEP OF THE DIAPHRAGM CELL PROCESS USING GRAPHITE ANODES IN CHLORINE PRODUCTION.

Waste Code: K083
Waste Description: DISTILLATION BOTTOMS FROM ANILINE PRODUCTION.

Waste Code: K084
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED DURING THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K085
Waste Description: DISTILLATION OR FRACTIONATION COLUMN BOTTOMS FROM THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K086
Waste Description: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

Waste Code: K087
Waste Description: DECANTER TANK TAR SLUDGE FROM COKING OPERATIONS.

Waste Code: K088
Waste Description: SPENT POTLINERS FROM PRIMARY ALUMINUM REDUCTION.

Waste Code: K093
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Waste Code: K094
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Waste Code: K095
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K096
Waste Description: HEAVY ENDS FROM THE HEAVY ENDS COLUMN FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K097
Waste Description: VACUUM STRIPPER DISCHARGE FROM THE CHLORDANE CHLORINATOR IN THE PRODUCTION OF CHLORDANE.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K098
Waste Description: UNTREATED PROCESS WASTEWATER FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K099
Waste Description: UNTREATED WASTEWATER FROM THE PRODUCTION OF 2,4-D.

Waste Code: K100
Waste Description: WASTE LEACHING SOLUTION FROM ACID LEACHING OF EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K101
Waste Description: DISTILLATION TAR RESIDUES FROM THE DISTILLATION OF ANILINE-BASED COMPOUNDS IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K102
Waste Description: RESIDUE FROM THE USE OF ACTIVATED CARBON FOR DECOLORIZATION IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K103
Waste Description: PROCESS RESIDUES FROM ANILINE EXTRACTION FROM THE PRODUCTION OF ANILINE.

Waste Code: K104
Waste Description: COMBINED WASTEWATERS GENERATED FROM NITROBENZENE/ANILINE PRODUCTION.

Waste Code: K105
Waste Description: SEPARATED AQUEOUS STREAM FROM THE REACTOR PRODUCT WASHING STEP IN THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K106
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION.

Waste Code: K107
Waste Description: COLUMN BOTTOMS FROM PRODUCT SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE (UDMH) FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K108
Waste Description: CONDENSED COLUMN OVERHEADS FROM PRODUCT SEPARATION AND CONDENSED REACTOR VENT GASES FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K109
Waste Description: SPENT FILTER CARTRIDGES FROM PRODUCT PURIFICATION FROM THE PRODUCT OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K110
Waste Description: CONDENSED COLUMN OVERHEADS FROM INTERMEDIATE SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K111
Waste Description: PRODUCT WASHWATERS FROM THE PRODUCTION OF DINITROTOLUENE VIA NITRATION OF TOLUENE.

Waste Code: K112

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: REACTION BY-PRODUCT WATER FROM THE DRYING COLUMN IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K113
Waste Description: CONDENSED LIQUID LIGHT ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K114
Waste Description: VICINALS FROM THE PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K115
Waste Description: HEAVY ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K116
Waste Description: ORGANIC CONDENSATE FROM THE SOLVENT RECOVERY COLUMN IN THE PRODUCTION OF TOLUENE DIISOCYANATE VIA PHOSGENATION OF TOLUENEDIAMINE.

Waste Code: K117
Waste Description: WASTEWATER FROM THE REACTOR VENT GAS SCRUBBER IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K118
Waste Description: SPENT ADSORBENT SOLIDS FROM PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K123
Waste Description: PROCESS WASTEWATER (INCLUDING SUPERNATES, FILTRATES, AND WASHWATERS) FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K124
Waste Description: REACTOR VENT SCRUBBER WATER FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K125
Waste Description: FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K126
Waste Description: BAGHOUSE DUST AND FLOOR SWEEPINGS IN MILLING AND PACKAGING OPERATIONS FROM PRODUCTION OR FORMULATION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K131
Waste Description: WASTEWATER FROM THE REACTOR AND SPENT SULFURIC ACID FROM THE ACID DRYER FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K132
Waste Description: SPENT ABSORBENT AND WASTEWATER SEPARATOR SOLIDS FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K136
Waste Description: STILL BOTTOMS FROM THE PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K141

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF COAL TAR, INCLUDING, BUT NOT LIMITED TO, TAR COLLECTING SUMP RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL. THIS LISTING DOES NOT INCLUDE K087 (DECANTER TANK SLUDGE FROM COKING OPERATIONS).

Waste Code: K142
Waste Description: TANK STORAGE RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR FROM THE RECOVERY OF COKE BY-PRODUCTS FROM COAL.

Waste Code: K143
Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF LIGHT OIL, INCLUDING, BUT NOT LIMITED TO, THOSE GENERATED IN STILLS, DECANTERS, AND WASH OIL RECOVERY UNITS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K144
Waste Description: WASTEWATER SUMP RESIDUES FROM LIGHT OIL REFINING, INCLUDING, BUT NOT LIMITED TO, INTERCEPTING OR CONTAMINATION SUMP SLUDGES FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K145
Waste Description: RESIDUES FROM NAPHTHALENE COLLECTION AND RECOVERY OPERATIONS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K147
Waste Description: TAR STORAGE RESIDUES FROM COAL TAR REFINING.

Waste Code: K148
Waste Description: RESIDUES FROM COAL TAR DISTILLATION, INCLUDING, BUT NOT LIMITED TO, STILL BOTTOMS.

Waste Code: K149
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, RING-CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS. [THIS WASTE DOES NOT INCLUDE STILL BOTTOMS FROM THE DISTILLATION OF BENZOYL CHLORIDE]

Waste Code: K150
Waste Description: ORGANIC RESIDULES EXCLUDING SPENT CARBON ADSORBENT, FROM THE SPENT CHLORINE GAS AND HYDROCHLORIC ACID RECOVERY PROCESSES ASSOCIATED WITH THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Waste Code: K151
Waste Description: WASTEWATER TREATMENT SLUDGES, EXCLUDING NEUTRALIZATION AND BIOLOGICAL SLUDGES, GENERATED DURING THE TREATMENT OF WASTEWATERS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Waste Code: K156
Waste Description: ORGANIC WASTE (INCLUDING HEAVY ENDS, STILL BOTTOMS, LIGHT ENDS, SPENT SOLVENTS, FILTRATES, AND DECANTATES) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K157
Waste Description: WASTEWATERS (INCLUDING SCRUBBER WATERS, CONDENSER WATERS, WASHWATERS,

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

AND SEPARATION WATERS) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K158
Waste Description: BAG HOUSE DUSTS AND FILTER/SEPARATION SOLIDS FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K159
Waste Description: ORGANICS FROM THE TREATMENT OF THIOCARBAMATE WASTES.

Waste Code: K161
Waste Description: PURIFICATION SOLIDS (INCLUDING FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS), BAG HOUSE DUST AND FLOOR SWEEPINGS FROM THE PRODUCTION OF DITHIOCARBAMATE ACIDS AND THEIR SALTS. (THIS LISTING DOES NOT INCLUDE K125 OR K126).

Waste Code: K169
Waste Description: K169

Waste Code: K170
Waste Description: K170

Waste Code: K171
Waste Description: K171

Waste Code: K172
Waste Description: K172

Waste Code: K174
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF ETHLYENE DICHLORIDE OR VINYL CHLORIDE

Waste Code: K175
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF VINYL CHLORIDE MONOMER..

Waste Code: K176
Waste Description: BAGHOUSE FILTERS FROM THE PRODUCTION OF ANTIMONY OXIDE, INCLUDING FILTERS FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K177
Waste Description: SLAG FROM THE PRODUCTION OF ANTIMONY OXIDE THAT IS SPECULATIVELY ACCUMULATED OR DISPOSED,INCLUDING SLAG FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K178
Waste Description: RESIDUES FROM MANUFACTURING AND MANUFACTURING-SITE STORAGE OF FERRIC CHLORIDE FROM ACIDS FORMED DURING THE PRODUCTION OF TITANIUM DIOXIDE USING THE CHLORIDE-ILMENITE PROCESS.

Waste Code: K181
Waste Description: Nonwastewaters from the production of dyes and/or pigments.

Waste Code: LABP
Waste Description: LABP

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code:	P001
Waste Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Waste Code:	P002
Waste Description:	1-ACETYL-2-THIOUREA (OR) ACETAMIDE, N-(AMINOTHIOXOMETHYL)-
Waste Code:	P003
Waste Description:	2-PROPENAL (OR) ACROLEIN
Waste Code:	P004
Waste Description:	1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5ALPHA, 8ALPHA, 8ABETA)- (OR) ALDRIN
Waste Code:	P005
Waste Description:	2-PROPEN-1-OL (OR) ALLYL ALCOHOL
Waste Code:	P006
Waste Description:	ALUMINUM PHOSPHIDE (R,T)
Waste Code:	P007
Waste Description:	3(2H)-ISOXAZOLONE, 5-(AMINOMETHYL)- (OR) 5-(AMINOMETHYL)-3-ISOXAZOLOL
Waste Code:	P008
Waste Description:	4-AMINOPYRIDINE (OR) 4-PYRIDINAMINE
Waste Code:	P009
Waste Description:	AMMONIUM PICRATE (R) (OR) PHENOL, 2,4,6-TRINITRO-, AMMONIUM SALT (R)
Waste Code:	P010
Waste Description:	ARSENIC ACID H3ASO4
Waste Code:	P011
Waste Description:	ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE
Waste Code:	P012
Waste Description:	ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE
Waste Code:	P013
Waste Description:	BARIUM CYANIDE
Waste Code:	P014
Waste Description:	BENZENETHIOL (OR) THIOPHENOL
Waste Code:	P015
Waste Description:	BERYLLIUM
Waste Code:	P016
Waste Description:	DICHLOROMETHYL ETHER (OR) METHANE, OXYBIS[CHLORO-
Waste Code:	P017
Waste Description:	2-PROPANONE, 1-BROMO- (OR) BROMOACETONE
Waste Code:	P018
Waste Description:	BRUCINE (OR) STRYCHNIDIN-10-ONE, 2,3-DIMETHOXY-

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P020
Waste Description: DINOSEB (OR) PHENOL, 2-(1-METHYLPROPYL)-4,6-DINITRO-

Waste Code: P021
Waste Description: CALCIUM CYANIDE (OR) CALCIUM CYANIDE CA(CN)2

Waste Code: P022
Waste Description: CARBON DISULFIDE

Waste Code: P023
Waste Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Waste Code: P024
Waste Description: BENZENAMINE, 4-CHLORO- (OR) P-CHLORANILINE

Waste Code: P026
Waste Description: 1-(O-CHLOROPHENYL)THIOUREA (OR) THIOUREA, (2-CHLOROPHENYL)-

Waste Code: P027
Waste Description: 3-CHLOROPROPIONITRILE (OR) PROPANENITRILE, 3-CHLORO-

Waste Code: P028
Waste Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Waste Code: P029
Waste Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Waste Code: P030
Waste Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste Code: P031
Waste Description: CYANOGEN (OR) ETHANEDINITRILE

Waste Code: P033
Waste Description: CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL

Waste Code: P034
Waste Description: 2-CYCLOHEXYL-4,6-DINITROPHENOL (OR) PHENOL, 2-CYCLOHEXYL-4,6-DINITRO-

Waste Code: P036
Waste Description: ARSONOUS DICHLORIDE, PHENYL- (OR) DICHLOROPHENYLARSINE

Waste Code: P037
Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2AALPHA, 3BETA, 6BETA, 6AALPHA, 7BETA, 7AALPHA)- (OR) DIELDRIN

Waste Code: P038
Waste Description: ARSINE, DIETHYL- (OR) DIETHYLARSINE

Waste Code: P039
Waste Description: DISULFOTON (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[2-(ETHYLTHIO)ETHYL] ESTER

Waste Code: P040
Waste Description: O,O-DIETHYL O-PYRAZINYL PHOSPHOROTHIOATE (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL O-PYRAZINYL ESTER

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P041
Waste Description: DIETHYL-P-NITROPHENYL PHOSPHATE (OR) PHOSPHORIC ACID, DIETHYL 4-NITROPHENYL ESTER

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P043
Waste Description: DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER

Waste Code: P044
Waste Description: DIMETHOATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIMETHYL S-[2-(METHYLAMINO)-2-OXOETHYL] ESTER

Waste Code: P045
Waste Description: 2-BUTANONE, 3,3-DIMETHYL-1-(METHYLTHIO)-, O-[METHYLAMINO)CARBONYL] OXIME (OR) THIOFANOX

Waste Code: P046
Waste Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Waste Code: P047
Waste Description: 4,6-DINITRO-O-CRESOL, & SALTS (OR) PHENOL, 2-METHYL-4,6-DINITRO-, & SALTS

Waste Code: P048
Waste Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Waste Code: P049
Waste Description: DITHIOBIURET (OR) THIOIMIDODICARBONIC DIAMIDE [(H2N)C(S)]2NH

Waste Code: P050
Waste Description: 6,9-METHANO-2,4,3-BENZODIOXATHIEPIN,6,7,8,9,10,10-HEXACHLORO-1,5,5A,6, 9,9A-HEXAHYDRO-,3-OXIDE (OR) ENDOSULFAN

Waste Code: P051
Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2ABETA, 3ALPHA, 6ALPHA, 6ABETA, 7BETA, 7AALPHA)- & METABOLITES (OR) ENDRIN (OR) ENDRIN, & METABOLITES

Waste Code: P054
Waste Description: AZIRIDINE (OR) ETHYLENEIMINE

Waste Code: P056
Waste Description: FLUORINE

Waste Code: P057
Waste Description: ACETAMIDE, 2-FLUORO- (OR) FLUOROACETAMIDE

Waste Code: P058
Waste Description: ACETIC ACID, FLUORO-, SODIUM SALT (OR) FLUOROACETIC ACID, SODIUM SALT

Waste Code: P059

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 4,7-METHANO-1H-INDENE, 1,4,5,6,7,8,8-HEPTACHLORO-3A,4,7,7A-TETRAHYDRO- (OR) HEPTACHLOR

Waste Code: P060
Waste Description: 1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5BETA, 8BETA, 8ABETA)- (OR) ISODRIN

Waste Code: P062
Waste Description: HEXAETHYL TETRAPHOSPHATE (OR) TETRAPHOSPHORIC ACID, HEXAETHYL ESTER

Waste Code: P063
Waste Description: HYDROCYANIC ACID (OR) HYDROGEN CYANIDE

Waste Code: P064
Waste Description: METHANE, ISOCYANATO- (OR) METHYL ISOCYANATE

Waste Code: P065
Waste Description: FULMINIC ACID, MERCURY(2+) SALT (R,T) (OR) MERCURY FULMINATE (R,T)

Waste Code: P066
Waste Description: ETHANIMIDOTHIOIC ACID, N-[[(METHYLAMINO)CARBONYL]OXY]-, METHYL ESTER (OR) METHOMYL

Waste Code: P067
Waste Description: 1,2-PROPYLENIMINE (OR) AZIRIDINE, 2-METHYL-

Waste Code: P068
Waste Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Waste Code: P069
Waste Description: 2-METHYLLACTONITRILE (OR) PROPANENITRILE, 2-HYDROXY-2-METHYL-

Waste Code: P070
Waste Description: ALDICARB (OR) PROPANAL, 2-METHYL-2-(METHYLTHIO)-, O-[(METHYLAMINO)CARBONYL]OXIME

Waste Code: P071
Waste Description: METHYL PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O,-DIMETHYL O-(4-NITROPHENYL) ESTER

Waste Code: P072
Waste Description: ALPHA-NAPHTHYLTHIOUREA (OR) THIOUREA, 1-NAPHTHALENYL-

Waste Code: P073
Waste Description: NICKEL CARBONYL (OR) NICKEL CARBONYL NI(CO)4, (T-4)-

Waste Code: P074
Waste Description: NICKEL CYANIDE (OR) NICKEL CYANIDE NI(CN)2

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P076
Waste Description: NITRIC OXIDE (OR) NITROGEN OXIDE NO

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P077
Waste Description: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

Waste Code: P078
Waste Description: NITROGEN DIOXIDE (OR) NITROGEN OXIDE NO2

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P082
Waste Description: METHANIMINE, N-METHYL-N-NITROSO- (OR) N-NITROSODIMETHYLAMINE

Waste Code: P084
Waste Description: N-NITROSOMETHYLVINYLAMINE (OR) VINYLAMINE, N-METHYL-N-NITROSO-

Waste Code: P085
Waste Description: DIPHOSPHORAMIDE, OCTAMETHYL- (OR) OCTAMETHYLPYROPHOSPHORAMIDE

Waste Code: P087
Waste Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Waste Code: P088
Waste Description: 7-OXABICYCLO[2.2.1]HEPTANE-2,3-DICARBOXYLIC ACID (OR) ENDOTHALL

Waste Code: P089
Waste Description: PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL-O-(4-NITROPHENYL) ESTER

Waste Code: P092
Waste Description: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

Waste Code: P093
Waste Description: PHENYLTHIOUREA (OR) THIOUREA, PHENYL-

Waste Code: P094
Waste Description: PHORATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[(ETHYLTHIO)METHYL] ESTER

Waste Code: P095
Waste Description: CARBONIC DICHLORIDE (OR) PHOSGENE

Waste Code: P096
Waste Description: HYDROGEN PHOSPHIDE (OR) PHOSPHINE

Waste Code: P097
Waste Description: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

Waste Code: P098
Waste Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Waste Code: P099
Waste Description: ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE

Waste Code: P101
Waste Description: ETHYL CYANIDE (OR) PROPANENITRILE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P102
Waste Description: 2-PROPYN-1-OL (OR) PROPARGYL ALCOHOL

Waste Code: P103
Waste Description: SELENOUREA

Waste Code: P104
Waste Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Waste Code: P105
Waste Description: SODIUM AZIDE

Waste Code: P106
Waste Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Waste Code: P108
Waste Description: STRYCHNIDIN-10-ONE, & SALTS (OR) STRYCHNINE, & SALTS

Waste Code: P109
Waste Description: TETRAETHYLDITHIOPYROPHOSPHATE (OR) THIODIPHOSPHORIC ACID, TETRAETHYL ESTER

Waste Code: P110
Waste Description: PLUMBANE, TETRAETHYL- (OR) TETRAETHYL LEAD

Waste Code: P111
Waste Description: DIPHOSPHORIC ACID, TETRAETHYL ESTER (OR) TETRAETHYL PYROPHOSPHATE

Waste Code: P112
Waste Description: METHANE, TETRANITRO- (R) (OR) TETRANITROMETHANE (R)

Waste Code: P113
Waste Description: THALLIC OXIDE (OR) THALLIUM OXIDE TL2O3

Waste Code: P114
Waste Description: SELENIOUS ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SELENITE

Waste Code: P115
Waste Description: SULFURIC ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SULFATE

Waste Code: P116
Waste Description: HYDRAZINECARBOTHIOAMIDE (OR) THIOSEMICARBAZIDE

Waste Code: P118
Waste Description: METHANETHIOL, TRICHLORO- (OR) TRICHLOROMETHANETHIOL

Waste Code: P119
Waste Description: AMMONIUM VANADATE (OR) VANADIC ACID, AMMONIUM SALT

Waste Code: P120
Waste Description: VANADIUM OXIDE V2O5 (OR) VANADIUM PENTOXIDE

Waste Code: P121
Waste Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

Waste Code: P122
Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 10%

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

(R,T)

Waste Code: P123
Waste Description: TOXAPHENE

Waste Code: P124
Waste Description: ACTINOMYCIN D

Waste Code: P127
Waste Description: P127

Waste Code: P128
Waste Description: P128

Waste Code: P185
Waste Description: 1,3-DITHIOLANE-2-CARBOXALDEHYDE, 2,4-DIMETHYL-, O-[(METHYLAMINO)-CARBONYL]OXIME (OR) TIRPATE

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: P189
Waste Description: CARBAMIC ACID, [(DIBUTYLAMINO)-THIO]METHYL-, 2,3-DIHYDRO-2,2-DIMETHYL -7-BENZOFURANYL ESTER (OR) CARBOSULFAN

Waste Code: P190
Waste Description: CARBAMIC ACID, METHYL-, 3-METHYLPHENYL ESTER (OR) METOLCARB

Waste Code: P191
Waste Description: CARBAMIC ACID, DIMETHYL-, 1-[(DIMETHYL-AMINO)CARBONYL]- 5-METHYL-1H-PYRAZOL-3-YL ESTER (OR) DIMETILAN

Waste Code: P192
Waste Description: ISOLAN (OR) CARBAMIC ACID, DIMETHYL-, 3-METHY-L-(1-METHYLETHYL)-1H-PYRAZOL-5-YL ESTER

Waste Code: P194
Waste Description: ETHANIMIDOTHIOC ACID, 2-(DIMETHYLAMINO)-N-[[(METHYLAMINO) CARBONYL]OXY]-2-OXO-, METHYL ESTER (OR) OXAMYL

Waste Code: P196
Waste Description: MANGANESE DIMETHYLDITHIOCARBAMATE (OR) MANGANESE, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-,

Waste Code: P197
Waste Description: FORMPARANATE (OR) METHANIMIDAMIDE, N,N-DIMETHYL-N'-[2-METHYL-4-[[(METHYLAMINO)CARBONYL]OXY]PHENYL]

Waste Code: P198
Waste Description: METHANIMIDAMIDE, N,N-DIMETHYL-N'-[3-[[(METHYLAMINO)-CARBONYL]OXY]PHENYL]-, MONOHYDROCHLORIDE (OR) FORMETANATE HYDROCHLORIDE

Waste Code: P199
Waste Description: P199

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P201
Waste Description: PHENOL, 3-METHYL-5-(1-METHYLETHYL)-, METHYL CARBAMATE (OR) PROMECARB

Waste Code: P202
Waste Description: M-CUMENYL METHYLCARBAMATE (OR) 3-ISOPROPYLPHENYL N-METHYLCARBAMATE (OR) PHENOL, 3-(1-METHYLETHYL)-, METHYL CARBAMATE

Waste Code: P203
Waste Description: ALDICARB SULFONE (OR) PROPANAL, 2-METHYL-2-(METHYL-SULFONYL)-, O-[(METHYLAMINO)CARBONYL] OXIME

Waste Code: P204
Waste Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Waste Code: P205
Waste Description: ZINC, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-, (OR) ZIRAM

Waste Code: U001
Waste Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U003
Waste Description: ACETONITRILE (I,T)

Waste Code: U004
Waste Description: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

Waste Code: U005
Waste Description: 2-ACETYLAMINOFLUORENE (OR) ACETAMIDE, N-9H-FLUOREN-2-YL

Waste Code: U006
Waste Description: ACETYL CHLORIDE (C,R,T)

Waste Code: U007
Waste Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Waste Code: U008
Waste Description: 2-PROPENOIC ACID (I) (OR) ACRYLIC ACID (I)

Waste Code: U009
Waste Description: 2-PROPENENITRILE (OR) ACRYLONITRILE

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-MET HOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U011
Waste Description: 1H-1,2,4-TRIAZOL-3-AMINE (OR) AMITROLE

Waste Code: U012
Waste Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U014
Waste Description: AURAMINE (OR) BENZENAMINE, 4,4'-CARBONIMIDOYLBIS[N,N-DIMETHYL-

Waste Code: U015
Waste Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Waste Code: U016
Waste Description: BENZ[C]ACRIDINE

Waste Code: U017
Waste Description: BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-

Waste Code: U018
Waste Description: BENZ[A]ANTHRACENE

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U020
Waste Description: BENZENESULFONIC ACID CHLORIDE (C,R) (OR) BENZENESULFONYL CHLORIDE (C,R)

Waste Code: U021
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE (OR) BENZIDINE

Waste Code: U022
Waste Description: BENZO[A]PYRENE

Waste Code: U023
Waste Description: BENZENE, (TRICHLOROMETHYL)- (OR) BENZOTRICHLORIDE (C,R,T)

Waste Code: U024
Waste Description: DICHLOROMETHOXY ETHANE (OR) ETHANE, 1,1'-[METHYLENEBIS(OXY)]BIS[2-CHLORO-

Waste Code: U025
Waste Description: DICHLOROETHYL ETHER (OR) ETHANE, 1,1'-OXYBIS[2-CHLORO-

Waste Code: U026
Waste Description: CHLORNAPHAZIN (OR) NAPHTHALENAMINE, N,N'-BIS(2-CHLOROETHYL)-

Waste Code: U027
Waste Description: DICHLOROISOPROPYL ETHER (OR) PROPANE, 2,2'-OXYBIS[2-CHLORO-

Waste Code: U028
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER (OR) DIETHYLHEXYL PHTHALATE

Waste Code: U029
Waste Description: METHANE, BROMO- (OR) METHYL BROMIDE

Waste Code: U030
Waste Description: 4-BROMOPHENYL PHENYL ETHER (OR) BENZENE, 1-BROMO-4-PHENOXY-

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U032
Waste Description: CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT

Waste Code: U033
Waste Description: CARBON OXYFLUORIDE (R,T) (OR) CARBONIC DIFLUORIDE

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U036
Waste Description: 4,7-METHANO-1H-INDENE, 1,2,4,5,6,7,8,8-OCTACHLORO-2,3,3A,4,7,7A-HEXAHYDRO- (OR) CHLORDANE, ALPHA & GAMMA ISOMERS

Waste Code: U037
Waste Description: BENZENE, CHLORO- (OR) CHLOROBENZENE

Waste Code: U038
Waste Description: BENZENEACETIC ACID, 4-CHLORO-ALPHA-(4-CHLOROPHENYL)-ALPHA-HYDROXY-, ETHYL ESTER (OR) CHLOROBENZILATE

Waste Code: U039
Waste Description: P-CHLORO-M-CRESOL (OR) PHENOL, 4-CHLORO-3-METHYL-

Waste Code: U041
Waste Description: EPICHLOROHYDRIN (OR) OXIRANE, (CHLOROMETHYL)-

Waste Code: U042
Waste Description: 2-CHLOROETHYL VINYL ETHER (OR) ETHENE, (2-CHLOROETHOXY)-

Waste Code: U043
Waste Description: ETHENE, CHLORO- (OR) VINYL CHLORIDE

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U045
Waste Description: METHANE, CHLORO- (I,T) (OR) METHYL CHLORIDE (I,T)

Waste Code: U046
Waste Description: CHLOROMETHYL METHYL ETHER (OR) METHANE, CHLOROMETHOXY-

Waste Code: U047
Waste Description: BETA-CHLORONAPHTHALENE (OR) NAPHTHALENE, 2-CHLORO-

Waste Code: U048
Waste Description: O-CHLOROPHENOL (OR) PHENOL, 2-CHLORO-

Waste Code: U049
Waste Description: 4-CHLORO-O-TOLUIDINE, HYDROCHLORIDE (OR) BENZENAMINE, 4-CHLORO-2-METHYL-, HYDROCHLORIDE

Waste Code: U050
Waste Description: CHRYSENE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U051
Waste Description: CREOSOTE

Waste Code: U052
Waste Description: CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-

Waste Code: U053
Waste Description: 2-BUTENAL (OR) CROTONALDEHYDE

Waste Code: U055
Waste Description: BENZENE, (1-METHYLETHYL)- (I) (OR) CUMENE (I)

Waste Code: U056
Waste Description: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

Waste Code: U057
Waste Description: CYCLOHEXANONE (I)

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U060
Waste Description: BENZENE, 1,1'-(2,2-DICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDD

Waste Code: U061
Waste Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT

Waste Code: U062
Waste Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3-DICHLORO-2-PROPENYL) ESTER (OR) DIALLATE

Waste Code: U063
Waste Description: DIBENZ[A,H]ANTHRACENE

Waste Code: U064
Waste Description: BENZO[RST]PENTAPHENE (OR) DIBENZO[A,I]PYRENE

Waste Code: U066
Waste Description: 1,2-DIBROMO-3-CHLOROPROPANE (OR) PROPANE, 1,2-DIBROMO-3-CHLORO-

Waste Code: U067
Waste Description: ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE

Waste Code: U068
Waste Description: METHANE, DIBROMO- (OR) METHYLENE BROMIDE

Waste Code: U069
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

Waste Code: U070

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U071
Waste Description: BENZENE, 1,3-DICHLORO- (OR) M-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U073
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DICHLORO- (OR) 3,3'-DICHLOROBENZIDINE

Waste Code: U074
Waste Description: 1,4-DICHLORO-2-BUTENE (I,T) (OR) 2-BUTENE, 1,4-DICHLORO- (I,T)

Waste Code: U075
Waste Description: DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-

Waste Code: U076
Waste Description: ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE

Waste Code: U077
Waste Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Waste Code: U078
Waste Description: 1,1-DICHLOROETHYLENE (OR) ETHENE, 1,1-DICHLORO-

Waste Code: U079
Waste Description: 1,2-DICHLOROETHYLENE (OR) ETHENE, 1,2-DICHLORO-,(E)-

Waste Code: U080
Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U081
Waste Description: 2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-

Waste Code: U082
Waste Description: 2,6-DICHLOROPHENOL (OR) PHENOL, 2,6-DICHLORO-

Waste Code: U083
Waste Description: PROPANE, 1,2-DICHLORO- (OR) PROPYLENE DICHLORIDE

Waste Code: U084
Waste Description: 1,3-DICHLOROPROPENE (OR) 1-PROPENE, 1,3-DICHLORO-

Waste Code: U085
Waste Description: 1,2:3,4-DIEPOXYBUTANE (I,T) (OR) 2,2'-BIOXIRANE

Waste Code: U086
Waste Description: HYDRAZINE, 1,2-DIETHYL- (OR) N,N'-DIETHYLHYDRAZINE

Waste Code: U087
Waste Description: O,O-DIETHYL S-METHYL DITHIOPHOSPHATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-METHYL ESTER

Waste Code: U088
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U090
Waste Description: 1,3-BENZODIOXOLE, 5-PROPYL- (OR) DIHYDROSAFROLE

Waste Code: U091
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHOXY- (OR) 3,3'-DIMETHOXYBENZIDINE

Waste Code: U092
Waste Description: DIMETHYLAMINE (I) (OR) METHANAMINE, N-METHYL- (I)

Waste Code: U093
Waste Description: BENZENAMINE, N,N-DIMETHYL-4-(PHENYLAZO)- (OR) P-DIMETHYLAMINOAZOBENZENE

Waste Code: U094
Waste Description: 7,12-DIMETHYLBENZ[A]ANTHRACENE (OR) BENZ[A]ANTHRACENE, 7,12-DIMETHYL-

Waste Code: U095
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHYL- (OR) 3,3'-DIMETHYLBENZIDINE

Waste Code: U096
Waste Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Waste Code: U097
Waste Description: CARBAMIC CHLORIDE, DIMETHYL- (OR) DIMETHYLCARBAMOYL CHLORIDE

Waste Code: U098
Waste Description: 1,1-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,1-DIMETHYL-

Waste Code: U099
Waste Description: 1,2-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U101
Waste Description: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

Waste Code: U102
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER (OR) DIMETHYL PHTHALATE

Waste Code: U103
Waste Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Waste Code: U105
Waste Description: 2,4-DINITROTOLUENE (OR) BENZENE, 1-METHYL-2,4-DINITRO-

Waste Code: U106
Waste Description: 2,6-DINITROTOLUENE (OR) BENZENE, 2-METHYL-1,3-DINITRO-

Waste Code: U107
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE

Waste Code: U108

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Waste Code: U109
Waste Description: 1,2-DIPHENYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U110
Waste Description: 1-PROPANIMINE, N-PROPYL-(I) (OR) DIPROPYLAMINE (I)

Waste Code: U111
Waste Description: 1-PROPANAMINE, N-NITROSO-N-PROPYL- (OR) DI-N-PROPYLNITROSAMINE

Waste Code: U112
Waste Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U113
Waste Description: 2-PROPENOIC ACID, ETHYL ESTER (I) (OR) ETHYL ACRYLATE (I)

Waste Code: U114
Waste Description: CARBAMODITHIOIC ACID, 1,2-ETHANEDIYLBIS-, SALTS & ESTERS (OR) ETHYLENEBISDITHIOCARBAMIC ACID, SALTS & ESTERS

Waste Code: U115
Waste Description: ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)

Waste Code: U116
Waste Description: 2-IMIDAZOLIDINETHIONE (OR) ETHYLENETHIOUREA

Waste Code: U117
Waste Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Waste Code: U118
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, ETHYL ESTER (OR) ETHYL METHACRYLATE

Waste Code: U119
Waste Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Waste Code: U120
Waste Description: FLUORANTHENE

Waste Code: U121
Waste Description: METHANE, TRICHLOROFLUORO- (OR) TRICHLOROMONOFLUOROMETHANE

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U123
Waste Description: FORMIC ACID (C,T)

Waste Code: U124
Waste Description: FURAN (I) (OR) FURFURAN (I)

Waste Code: U125
Waste Description: 2-FURANCARBOXALDEHYDE (I) (OR) FURFURAL (I)

Waste Code: U126
Waste Description: GLYCIDYLALDEHYDE (OR) OXIRANECARBOXYALDEHYDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U127
Waste Description: BENZENE, HEXACHLORO- (OR) HEXACHLOROBENZENE

Waste Code: U128
Waste Description: 1,3-BUTADIENE, 1,1,2,3,4,4-HEXACHLORO- (OR) HEXACHLOROBUTADIENE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U130
Waste Description: 1,3-CYCLOPENTADIENE, 1,2,3,4,5,5-HEXACHLORO- (OR) HEXACHLOROCYCLOPENTADIENE

Waste Code: U131
Waste Description: ETHANE, HEXACHLORO- (OR) HEXACHLOROETHANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U133
Waste Description: HYDRAZINE (R,T)

Waste Code: U134
Waste Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Waste Code: U135
Waste Description: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

Waste Code: U136
Waste Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Waste Code: U137
Waste Description: INDENO[1,2,3-CD]PYRENE

Waste Code: U138
Waste Description: METHANE, IODO- (OR) METHYL IODIDE

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U141
Waste Description: 1,3-BENZODIOXOLE, 5-(1-PROPENYL)- (OR) ISOSAFROLE

Waste Code: U142
Waste Description: 1,3,4-METHENO-2H-CYCLOBUTA[CD]PENTALEN-2-ONE, 1,1A,3,3A,4,5,5,5A,5B,6-DECACHLOROOCTAHYDRO- (OR) KEPONE

Waste Code: U143
Waste Description: 2-BUTENOIC ACID, 2-METHYL-, 7-[[2,3-DIHYDROXY-2-(1-METHOXYETHYL)-3-METHYL-1-OXOBUTOXY]METHYL]-2,3,5,7A-TETRAHYDRO-1H-PYRROLIZIN-1-YL ESTER, [1S-[1ALPHA(Z), 7(2S*,3R*), 7AALPHA]]- (OR) LASIOCARPINE

Waste Code: U144
Waste Description: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U145
Waste Description: LEAD PHOSPHATE (OR) PHOSPHORIC ACID, LEAD(2+) SALT (2:3)

Waste Code: U146
Waste Description: LEAD SUBACETATE (OR) LEAD, BIS(ACETATO-O)TETRAHYDROXYTRI-

Waste Code: U147
Waste Description: 2,5-FURANDIONE (OR) MALEIC ANHYDRIDE

Waste Code: U148
Waste Description: 3,6-PYRIDAZINEDIONE, 1,2-DIHYDRO- (OR) MALEIC HYDRAZIDE

Waste Code: U149
Waste Description: MALONONITRILE (OR) PROPANEDINITRILE

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U152
Waste Description: 2-PROPENENITRILE, 2-METHYL- (I,T) (OR) METHACRYLONITRILE (I,T)

Waste Code: U153
Waste Description: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U155
Waste Description: 1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE

Waste Code: U156
Waste Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Waste Code: U157
Waste Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Waste Code: U158
Waste Description: 4,4'-METHYLENEBIS(2-CHLOROANILINE) (OR) BENZENAMINE, 4,4'-METHYLENEBIS[2-CHLORO-

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U160
Waste Description: 2-BUTANONE, PEROXIDE (R,T) (OR) METHYL ETHYL KETONE PEROXIDE (R,T)

Waste Code: U161
Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U162
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, METHYL ESTER (I,T) (OR) METHYL

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

METHACRYLATE (I,T)

Waste Code: U163
Waste Description: GUANIDINE, N-METHYL-N'-NITRO-N-NITROSO- (OR) MNNG

Waste Code: U164
Waste Description: 4(1H)-PYRIMIDINONE, 2,3-DIHYDRO-6-METHYL-2-THIOXO- (OR) METHYLTHIOURACIL

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U166
Waste Description: 1,4-NAPHTHALENEDIONE (OR) 1,4-NAPHTHOQUINONE

Waste Code: U167
Waste Description: 1-NAPTHALENAMINE (OR) ALPHA-NAPHTHYLAMINE

Waste Code: U168
Waste Description: 2-NAPTHALENAMINE (OR) BETA-NAPHTHYLAMINE

Waste Code: U169
Waste Description: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

Waste Code: U170
Waste Description: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

Waste Code: U171
Waste Description: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)

Waste Code: U172
Waste Description: 1-BUTANAMINE, N-BUTYL-N-NITROSO- (OR) N-NITROSODI-N-BUTYLAMINE

Waste Code: U173
Waste Description: ETHANOL, 2,2'-(NITROSOIMINO)BIS- (OR) N-NITROSODIETHANOLAMINE

Waste Code: U174
Waste Description: ETHANAMINE, N-ETHYL-N-NITROSO- (OR) N-NITROSODIETHYLAMINE

Waste Code: U176
Waste Description: N-NITROSO-N-ETHYLUREA (OR) UREA, N-ETHYL-N-NITROSO-

Waste Code: U177
Waste Description: N-NITROSO-N-METHYLUREA (OR) UREA, N-METHYL-N-NITROSO-

Waste Code: U178
Waste Description: CARBAMIC ACID, METHYLNITROSO-, ETHYL ESTER (OR) N-NITROSO-N-METHYLURETHANE

Waste Code: U179
Waste Description: N-NITROSOPIPERIDINE (OR) PIPERIDINE, 1-NITROSO-

Waste Code: U180
Waste Description: N-NITROSOPYRROLIDINE (OR) PYRROLIDINE, 1-NITROSO-

Waste Code: U181
Waste Description: 5-NITRO-O-TOLUIDINE (OR) BENZENAMINE, 2-METHYL-5-NITRO

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U182
Waste Description: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

Waste Code: U183
Waste Description: BENZENE, PENTACHLORO- (OR) PENTACHLOROBENZENE

Waste Code: U184
Waste Description: ETHANE, PENTACHLORO- (OR) PENTACHLOROETHANE

Waste Code: U185
Waste Description: BENZENE, PENTACHLORONITRO- (OR) PENTACHLORONITROBENZENE (PCNB)

Waste Code: U186
Waste Description: 1,3-PENTADIENE (I) (OR) 1-METHYLBUTADIENE (I)

Waste Code: U187
Waste Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Waste Code: U188
Waste Description: PHENOL

Waste Code: U189
Waste Description: PHOSPHORUS SULFIDE (R) (OR) SULFUR PHOSPHIDE (R)

Waste Code: U190
Waste Description: 1,3-ISOBENZOFURANDIONE (OR) PHTHALIC ANHYDRIDE

Waste Code: U191
Waste Description: 2-PICOLINE (OR) PYRIDINE, 2-METHYL-

Waste Code: U192
Waste Description: BENZAMIDE, 3,5-DICHLORO-N-(1,1-DIMETHYL-2-PROPYNYL)- (OR) PRONAMIDE

Waste Code: U193
Waste Description: 1,2-OXATHIOLANE, 2,2-DIOXIDE (OR) 1,3-PROPANE SULTONE

Waste Code: U194
Waste Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Waste Code: U196
Waste Description: PYRIDINE

Waste Code: U197
Waste Description: 2,5-CYCLOHEXADIENE-1,4-DIONE (OR) P-BENZOQUINONE

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U203
Waste Description: 1,3-BENZODIOXOLE, 5-(2-PROPENYL)- (OR) SAFROLE

Waste Code: U204

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U207
Waste Description: 1,2,4,5-TETRACHLOROBENZENE (OR) BENZENE, 1,2,4,5-TETRACHLORO-

Waste Code: U208
Waste Description: 1,1,1,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,1,2-TETRACHLORO-

Waste Code: U209
Waste Description: 1,1,2,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,2,2-TETRACHLORO-

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U213
Waste Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Waste Code: U214
Waste Description: ACETIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) ACETATE

Waste Code: U215
Waste Description: CARBONIC ACID, DITHALLIUM(1+) SALT (OR) THALLIUM(I) CARBONATE

Waste Code: U216
Waste Description: THALLIUM CHLORIDE TLCL (OR) THALLIUM(I) CHLORIDE

Waste Code: U217
Waste Description: NITRIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) NITRATE

Waste Code: U218
Waste Description: ETHANETHIOAMIDE (OR) THIOACETAMIDE

Waste Code: U219
Waste Description: THIOUREA

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U221
Waste Description: BENZENEDIAMINE, AR-METHYL- (OR) TOLUENEDIAMINE

Waste Code: U222
Waste Description: BENZENAMINE, 2-METHYL-, HYDROCHLORIDE (OR) O-TOLUIDINE HYDROCHLORIDE

Waste Code: U223
Waste Description: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T) (OR) TOLUENE DIISOCYANATE (R,T)

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U225
Waste Description: BROMOFORM (OR) METHANE, TRIBROMO-

Waste Code: U226
Waste Description: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Waste Code: U227
Waste Description: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

Waste Code: U228
Waste Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Waste Code: U234
Waste Description: 1,3,5-TRINITROBENZENE (R,T) (OR) BENZENE, 1,3,5-TRINITRO-

Waste Code: U235
Waste Description: 1-PROPANOL, 2,3-DIBROMO-, PHOSPHATE (3:1) (OR) TRIS(2,3,-DIBROMOPROPYL) PHOSPHATE

Waste Code: U236
Waste Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO -4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Waste Code: U237
Waste Description: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Waste Code: U238
Waste Description: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Waste Code: U240
Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U243
Waste Description: 1-PROPENE, 1,1,2,3,3,3-HEXACHLORO- (OR) HEXACHLOROPROPENE

Waste Code: U244
Waste Description: THIOPEROXYDICARBONIC DIAMIDE [(H2N)C(S)]2S2, TETRAMETHYL- (OR) THIRAM

Waste Code: U246
Waste Description: CYANOGEN BROMIDE (CN)BR

Waste Code: U247
Waste Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-METHOXY- (OR) METHOXYCHLOR

Waste Code: U248
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Waste Code: U249

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Waste Code: U271
Waste Description: BENOMYL (OR) CARBAMIC ACID, [1-[(BUTYLAMINO)CARBONYL]-1H-BENZIMIDAZOL-2-YL]-, METHYL ESTER

Waste Code: U278
Waste Description: BENDIOCARB (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-, METHYL CARBAMATE

Waste Code: U279
Waste Description: U279

Waste Code: U280
Waste Description: BARBAN (OR) CARBAMIC ACID, (3-CHLOROPHENYL)-, 4-CHLORO-2-BUTYNYL ESTER

Waste Code: U328
Waste Description: BENZENAMINE, 2-METHYL- (OR) O-TOLUIDINE

Waste Code: U353
Waste Description: BENZENAMINE, 4-METHYL- (OR) P-TOLUIDINE

Waste Code: U359
Waste Description: ETHANOL, 2-ETHOXY- (OR) ETHYLENE GLYCOL MONOETHYL ETHER

Waste Code: U364
Waste Description: BENDIOCARB PHENOL (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-

Waste Code: U367
Waste Description: 7-BENZOFURANOL, 2,3-DIHYDRO-2,2-DIMETHYL- (OR) CARBOFURAN PHENOL

Waste Code: U372
Waste Description: CARBAMIC ACID, 1H-BENZIMIDAZOL-2-YL, METHYL ESTER (OR) CARBENDAZIM

Waste Code: U373
Waste Description: CARBAMIC ACID, PHENYL-, 1-METHYLETHYL ESTER (OR) PROPHAM

Waste Code: U378
Waste Description: CARBAMODITHIOIC ACID, (HYDROXYMETHYL) METHYL-, MONOPOTASSIUM SALT (OR) POTASSIUM N-HYDROXYMETHYL- N-METHYLDI-THIOCARBAMATE

Waste Code: U387
Waste Description: CARBAMOTHIOIC ACID, DIPROPYL-, S-(PHENYLMETHYL) ESTER (OR) PROSULFOCARB

Waste Code: U389
Waste Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3,3-TRICHLORO-2-PROPENYL) ESTER (OR) TRIALLATE

Waste Code: U394
Waste Description: A2213 (OR) ETHANIMIDOTHIOIC ACID, 2-(DIMETHYLAMINO)-N-HYDROXY-2-OXO-, METHYL ESTER

Waste Code: U395
Waste Description: DIETHYLENE GLYCOL, DICARBAMATE (OR) ETHANOL, 2,2'-OXYBIS-, DICARBAMATE

Waste Code: U404
Waste Description: U404

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U409
Waste Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Waste Code: U410
Waste Description: ETHANIMIDOTHIOIC ACID, N,N'-[THIOBIS[(METHYLIMINO)CARBONYLOXY]]BIS-, DIMETHYL ESTER (OR) THIODICARB

Waste Code: U411
Waste Description: U411

Waste Code: U480
Waste Description: 2,4,6, TRIBROMPHENOL (I.E.; DISCARDED COMMERCIAL CHEMICAL PRODUCTS, OFF-SPECIFICATION SPECIES, CONTAINER RESIDUES, AND SPILL RESIDUES THEREOF)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: CITY NOT REPORTED, CA 99999
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: STOCKTON, CA 95201
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: CITY NOT REPORTED, CA 99999
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CHARLIE MCCORMICK
Legal Status: Private
Date Became Current: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date Ended Current: Not reported
Owner/Operator Address: 1214 WEST WASHINGTON
Owner/Operator City,State,Zip: STOCKTON, CA 95203
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 1996-09-01 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1980-06-30 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2019-10-31 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 1990-03-23 00:00:00.0
Handler Name: MCCORMICK AND BAXTER CREOSOTING CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 321114
NAICS Description: WOOD PRESERVATION

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1986-08-04 00:00:00.0
Actual Return to Compliance Date: 1988-12-06 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 1986-09-04 00:00:00.0
Enforcement Identifier: 002
Date of Enforcement Action: 1986-08-04 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	1990-06-18 00:00:00.0
Actual Return to Compliance Date:	1990-08-16 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	1990-10-31 00:00:00.0
Enforcement Identifier:	004
Date of Enforcement Action:	1990-08-02 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	1986-06-13 00:00:00.0
Actual Return to Compliance Date:	1988-02-24 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	1991-10-10 00:00:00.0
Actual Return to Compliance Date:	1992-03-17 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	1992-01-31 00:00:00.0
Enforcement Identifier:	005
Date of Enforcement Action:	1991-10-07 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	200
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	1986-02-14 00:00:00.0
Actual Return to Compliance Date:	1986-06-13 00:00:00.0
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action:	1987-03-13 00:00:00.0
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R9EPA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	1985-04-05 00:00:00.0
Actual Return to Compliance Date:	1985-04-30 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action: 1985-04-05 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD - Financial Requirements
Date Violation was Determined:	1988-02-05 00:00:00.0
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	003
Date of Enforcement Action:	1988-06-03 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	60000
Final Monetary Amount:	5000
Paid Amount:	5000
Final Count:	1
Final Amount:	5000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD - Financial Requirements
Date Violation was Determined:	1987-12-08 00:00:00.0
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	003
Date of Enforcement Action:	1988-06-03 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	60000
Final Monetary Amount:	5000
Paid Amount:	5000
Final Count:	1
Final Amount:	5000
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	1986-08-04 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Scheduled Compliance Date:	1986-09-04 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1990-06-29 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1990-06-18 00:00:00.0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1990-08-16 00:00:00.0
Scheduled Compliance Date:	1990-10-31 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-08-07 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-01-22 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1986-06-13 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-02-24 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1991-09-18 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Actual Return to Compliance Date:	1992-03-17 00:00:00.0
Scheduled Compliance Date:	1992-01-31 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1986-02-14 00:00:00.0
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9EPA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1986-06-13 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-04-30 00:00:00.0
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9EPA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1988-02-24 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-04-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1985-04-30 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Former Citation:	Not reported
Evaluation Date:	1993-03-09 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-02-14 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-06-13 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1988-02-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1987-12-08 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1993-03-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

RCRA-SQG:

Date Form Received by Agency:	2019-10-31 00:00:00.0
Handler Name:	MCCORMICK & BAXTER CREOSOTING CO
Handler Address:	1214 W WASHINGTON ST
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAD009106527
Contact Name:	MARK SAMOLIS
Contact Address:	1214 W WASHINGTON ST
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	415-947-4273
Contact Fax:	Not reported
Contact Email:	SAMOLIS.MARK@EPA.GOV
Contact Title:	Not reported
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	1
Mailing Address:	POST OFFICE BOX FIRST THOUSAND
Mailing City,State,Zip:	STOCKTON, CA 95201
Owner Name:	CHARLIE MCCORMICK
Owner Type:	Private
Operator Name:	MCCORMICK AND BAXTER CREOSOTING COMPANY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Storage, Treatment
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Storage, Treatment
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	Yes
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	Yes
Corrective Action Priority Ranking:	High
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-10-31 14:40:18.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER
Waste Code:	D012
Waste Description:	ENDRIN (1,2,3,4,10,10-HEXACHLORO-1,7-EPOXY-1,4,4A,5,6,7,8,8A-OCTAHYDRO-1,4-ENDO, ENDO-5,8-DIMETH-ANO-NAPHTHALENE)
Waste Code:	D013
Waste Description:	LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)
Waste Code:	D014
Waste Description:	METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)
Waste Code:	D015
Waste Description:	TOXAPHENE (C10 H10 CL8, TECHNICAL CHLORINATED CAMPHENE, 67-69 PERCENT CHLORINE)
Waste Code:	D016
Waste Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Waste Code:	D017
Waste Description:	2,4,5-TP SILVEX (2,4,5-TRICHLOROPHENOXYPROPIONIC ACID)
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D019
Waste Description:	CARBON TETRACHLORIDE
Waste Code:	D020
Waste Description:	CHLORDANE
Waste Code:	D021
Waste Description:	CHLOROBENZENE
Waste Code:	D022
Waste Description:	CHLOROFORM
Waste Code:	D023
Waste Description:	O-CRESOL
Waste Code:	D024
Waste Description:	M-CRESOL
Waste Code:	D025
Waste Description:	P-CRESOL
Waste Code:	D026
Waste Description:	CRESOL
Waste Code:	D027
Waste Description:	1,4-DICHLOROBENZENE
Waste Code:	D028

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 1,2-DICHLOROETHANE

Waste Code: D029
Waste Description: 1,1-DICHLOROETHYLENE

Waste Code: D030
Waste Description: 2,4-DINITROTOLUENE

Waste Code: D031
Waste Description: HEPTACHLOR (AND ITS EPOXIDE)

Waste Code: D032
Waste Description: HEXACHLOROBENZENE

Waste Code: D033
Waste Description: HEXACHLOROBUTADIENE

Waste Code: D034
Waste Description: HEXACHLOROETHANE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D036
Waste Description: NITROBENZENE

Waste Code: D037
Waste Description: PENTACHLOROPHENOL

Waste Code: D038
Waste Description: PYRIDINE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: D041
Waste Description: 2,4,5-TRICHLOROPHENOL

Waste Code: D042
Waste Description: 2,4,6-TRICHLOROPHENOL

Waste Code: D043
Waste Description: VINYL CHLORIDE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F004
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Waste Code: F007
Waste Description: SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS.

Waste Code: F008
Waste Description: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: F009
Waste Description: SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F010
Waste Description: QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F011
Waste Description: SPENT CYANIDE SOLUTIONS FROM SLAT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.

Waste Code: F012
Waste Description: QUENCHING WASTEWATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS IN WHICH CYANIDES ARE USED IN THE PROCESS.

Waste Code: F019
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM, EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.

Waste Code: F020
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- OR TETRACHLOROPHENOL OR OF INTERMEDIATES USED TO PRODUCE THEIR PESTICIDE DERIVATIVES. (THIS LISTING DOES NOT INCLUDE WASTES FROM THE PRODUCTION OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F021
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF PENTACHLOROPHENOL, OR OF INTERMEDIATES USED TO PRODUCE DERIVATIVES.

Waste Code: F022
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENES UNDER ALKALINE CONDITIONS.

Waste Code: F023
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE PRODUCTION OR MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TRI- AND TETRACHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE WASTES FROM EQUIPMENT USED ONLY FOR THE PRODUCTION OR USE OF HEXACHLOROPHENE FROM HIGHLY PURIFIED 2,4,5-TRICHLOROPHENOL.)

Waste Code: F024
Waste Description: PROCESS WASTES INCLUDING, BUT NOT LIMITED TO, DISTILLATION RESIDUES, HEAVY ENDS, TARS, AND REACTOR CLEAN-OUT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION. (THIS LISTING DOES NOT INCLUDE WASTEWATERS, WASTEWATER TREATMENT SLUDGE, SPENT CATALYSTS, AND WASTES LISTED IN SECTIONS 261.31. OR 261.32)

Waste Code: F025
Waste Description: CONDENSED LIGHT ENDS, SPENT FILTERS AND FILTER AIDS, AND SPENT DESICCANT WASTES FROM THE PRODUCTION OF CERTAIN CHLORINATED ALIPHATIC HYDROCARBONS BY FREE RADICAL CATALYZED PROCESSES. THESE CHLORINATED ALIPHATIC HYDROCARBONS ARE THOSE HAVING CARBON CHAIN LENGTHS RANGING FROM ONE TO, AND INCLUDING FIVE, WITH VARYING AMOUNTS AND POSITIONS OF CHLORINE SUBSTITUTION.

Waste Code: F026
Waste Description: WASTES (EXCEPT WASTEWATER AND SPENT CARBON FROM HYDROGEN CHLORIDE PURIFICATION) FROM THE PRODUCTION OF MATERIALS ON EQUIPMENT PREVIOUSLY USED FOR THE MANUFACTURING USE (AS A REACTANT, CHEMICAL INTERMEDIATE, OR COMPONENT IN A FORMULATING PROCESS) OF TETRA-, PENTA-, OR HEXACHLOROBENZENE UNDER ALKALINE CONDITIONS.

Waste Code: F027
Waste Description: DISCARDED UNUSED FORMULATIONS CONTAINING TRI-, TETRA-, OR PENTACHLOROPHENOL OR DISCARDED UNUSED FORMULATIONS CONTAINING COMPOUNDS DERIVED FROM THESE CHLOROPHENOLS. (THIS LISTING DOES NOT INCLUDE FORMULATIONS CONTAINING HEXACHLOROPHENE SYNTHESIZED FROM PREPURIFIED 2,4,5-TRICHLOROPHENOL AS THE SOLE COMPONENT.)

Waste Code: F028
Waste Description: RESIDUES RESULTING FROM THE INCINERATION OR THERMAL TREATMENT OF SOIL CONTAMINATED WITH EPA HAZARDOUS WASTE NOS. F020, F021, F022, F023, F026, AND F027.

Waste Code: F032
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT CURRENTLY USE, OR HAVE PREVIOUSLY USED, CHLOROPHENOLIC FORMULATIONS [EXCEPT POTENTIALLY CROSS-CONTAMINATED WASTES THAT HAVE HAD THE F032 WASTE CODE DELETED IN ACCORDANCE WITH SECTION 261.35 (I.E., THE NEWLY PROMULGATED EQUIPMENT CLEANING OR REPLACEMENT STANDARDS), AND WHERE THE GENERATOR DOES NOT RESUME OR INITIATE USE OF CHLOROPHENOLIC FORMULATIONS]. (THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSE THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.)

Waste Code: F034
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE CREOSOTE FORMULATIONS. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: F035
Waste Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT USE INORGANIC PRESERVATIVES CONTAINING ARSENIC OR CHROMIUM. THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: F037
Waste Description: PETROLEUM REFINERY PRIMARY OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE GENERATED FROM THE GRAVITATIONAL SEPARATION OF OIL/WATER/SOLIDS DURING THE STORAGE OR TREATMENT OF PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH SLUDGES INCLUDE, BUT ARE NOT LIMITED TO, THOSE GENERATED IN OIL/WATER/SOLIDS SEPARATORS; TANKS AND IMPOUNDMENTS; DITCHES AND OTHER CONVEYANCES; SUMPS; AND STORM WATER UNITS RECEIVING DRY WEATHER FLOW. SLUDGES GENERATED IN STORM WATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F038
Waste Description: PETROLEUM REFINERY SECONDARY (EMULSIFIED) OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE AND/OR FLOAT GENERATED FROM THE PHYSICAL AND/OR CHEMICAL SEPARATION OF OIL/WATER/SOLIDS IN PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH WASTES INCLUDE, BUT ARE NOT LIMITED TO, ALL SLUDGES AND FLOATS GENERATED IN INDUCED AIR FLOTATION (IAF) UNITS, TANKS AND IMPOUNDMENTS, AND ALL SLUDGES GENERATED IN DAF UNITS. SLUDGES GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND F037, K048, AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F039
Waste Description: LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Waste Code: K001
Waste Description: BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATERS FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.

Waste Code: K002
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME YELLOW AND ORANGE PIGMENTS.

Waste Code: K003
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF MOLYBDATE ORANGE PIGMENTS.

Waste Code: K004
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF ZINC YELLOW PIGMENTS.

Waste Code: K005
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME GREEN

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

PIGMENTS.

Waste Code: K006
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS (ANHYDROUS AND HYDRATED).

Waste Code: K007
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF IRON BLUE PIGMENTS.

Waste Code: K008
Waste Description: OVEN RESIDUE FROM THE PRODUCTION OF CHROME OXIDE GREEN PIGMENTS.

Waste Code: K009
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K010
Waste Description: DISTILLATION SIDE CUTS FROM THE PRODUCTION OF ACETALDEHYDE FROM ETHYLENE.

Waste Code: K011
Waste Description: BOTTOM STREAM FROM THE WASTEWATER STRIPPER IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K013
Waste Description: BOTTOM STREAM FROM THE ACETONITRILE COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K014
Waste Description: BOTTOMS FROM THE ACETONITRILE PURIFICATION COLUMN IN THE PRODUCTION OF ACRYLONITRILE.

Waste Code: K015
Waste Description: STILL BOTTOMS FROM THE DISTILLATION OF BENZYL CHLORIDE.

Waste Code: K016
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE PRODUCTION OF CARBON TETRACHLORIDE.

Waste Code: K017
Waste Description: HEAVY ENDS (STILL BOTTOMS) FROM THE PURIFICATION COLUMN IN THE PRODUCTION OF EPICHLOROHYDRIN.

Waste Code: K018
Waste Description: HEAVY ENDS FROM THE FRACTIONATION COLUMN IN ETHYL CHLORIDE PRODUCTION.

Waste Code: K019
Waste Description: HEAVY ENDS FROM THE DISTILLATION OF ETHYLENE DICHLORIDE IN ETHYLENE DICHLORIDE PRODUCTION.

Waste Code: K020
Waste Description: HEAVY ENDS FROM THE DISTILLATION OF VINYL CHLORIDE IN VINYL CHLORIDE MONOMER PRODUCTION.

Waste Code: K021
Waste Description: AQUEOUS SPENT ANTIMONY CATALYST WASTE FROM FLUOROMETHANE PRODUCTION.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K022
Waste Description: DISTILLATION BOTTOM TARS FROM THE PRODUCTION OF PHENOL/ACETONE FROM CUMENE.

Waste Code: K023
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K024
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM NAPHTHALENE.

Waste Code: K025
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF NITROBENZENE BY THE NITRATION OF BENZENE.

Waste Code: K026
Waste Description: STRIPPING STILL TAILS FROM THE PRODUCTION OF METHYL ETHYL PYRIDINES.

Waste Code: K027
Waste Description: CENTRIFUGE AND DISTILLATION RESIDUES FROM TOLUENE DIISOCYANATE PRODUCTION.

Waste Code: K028
Waste Description: SPENT CATALYST FROM THE HYDROCHLORINATOR REACTOR IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K029
Waste Description: WASTE FROM THE PRODUCT STEAM STRIPPER IN THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K030
Waste Description: COLUMN BOTTOMS OR HEAVY ENDS FROM THE COMBINED PRODUCTION OF TRICHLOROETHYLENE AND PERCHLOROETHYLENE.

Waste Code: K031
Waste Description: BY-PRODUCT SALTS GENERATED IN THE PRODUCTION OF MSMA AND CACODYLIC ACID.

Waste Code: K032
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF CHLORDANE.

Waste Code: K033
Waste Description: WASTEWATER AND SCRUB WATER FROM THE CHLORINATION OF CYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K034
Waste Description: FILTER SOLIDS FROM THE FILTRATION OF HEXACHLOROCYCLOPENTADIENE IN THE PRODUCTION OF CHLORDANE.

Waste Code: K035
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED IN THE PRODUCTION OF CREOSOTE.

Waste Code: K036
Waste Description: STILL BOTTOMS FROM TOLUENE RECLAMATION DISTILLATION IN THE PRODUCTION OF DISULFOTON.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K037
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF DISULFOTON.

Waste Code: K038
Waste Description: WASTEWATER FROM THE WASHING AND STRIPPING OF PHORATE PRODUCTION.

Waste Code: K039
Waste Description: FILTER CAKE FROM THE FILTRATION OF DIETHYLPHOSPHORODITHIOIC ACID IN THE PRODUCTION OF PHORATE.

Waste Code: K040
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF PHORATE.

Waste Code: K041
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K042
Waste Description: HEAVY ENDS OR DISTILLATION RESIDUES FROM THE DISTILLATION OF TETRACHLOROBENZENE IN THE PRODUCTION OF 2,4,5-T.

Waste Code: K043
Waste Description: 2,6-DICHLOROPHENOL WASTE FROM THE PRODUCTION OF 2,4-D.

Waste Code: K044
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING AND PROCESSING OF EXPLOSIVES.

Waste Code: K045
Waste Description: SPENT CARBON FROM THE TREATMENT OF WASTEWATER CONTAINING EXPLOSIVES.

Waste Code: K046
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE MANUFACTURING, FORMULATION, AND LOADING OF LEAD-BASED INITIATING COMPOUNDS.

Waste Code: K047
Waste Description: PINK/RED WATER FROM TNT OPERATIONS.

Waste Code: K048
Waste Description: DISSOLVED AIR FLOTATION (DAF) FLOAT FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K049
Waste Description: SLOP OIL EMULSION SOLIDS FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K050
Waste Description: HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K051
Waste Description: API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K052
Waste Description: TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY.

Waste Code: K060
Waste Description: AMMONIA STILL LIME SLUDGE FROM COKING OPERATIONS.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K061
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM THE PRIMARY PRODUCTION OF STEEL IN ELECTRIC FURNACES.

Waste Code: K062
Waste Description: SPENT PICKLE LIQUOR FROM STEEL FINISHING OPERATIONS OF PLANTS THAT PRODUCE IRON OR STEEL.

Waste Code: K069
Waste Description: EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K071
Waste Description: BRINE PURIFICATION MUDS FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION, IN WHICH SEPARATELY PREPURIFIED BRINE IS NOT USED.

Waste Code: K073
Waste Description: CHLORINATED HYDROCARBON WASTE FROM THE PURIFICATION STEP OF THE DIAPHRAGM CELL PROCESS USING GRAPHITE ANODES IN CHLORINE PRODUCTION.

Waste Code: K083
Waste Description: DISTILLATION BOTTOMS FROM ANILINE PRODUCTION.

Waste Code: K084
Waste Description: WASTEWATER TREATMENT SLUDGES GENERATED DURING THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K085
Waste Description: DISTILLATION OR FRACTIONATION COLUMN BOTTOMS FROM THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K086
Waste Description: SOLVENT WASHES AND SLUDGES, CAUSTIC WASHES AND SLUDGES, OR WATER WASHES AND SLUDGES FROM CLEANING TUBS AND EQUIPMENT USED IN THE FORMULATION OF INK FROM PIGMENTS, DRIERS, SOAPS, AND STABILIZERS CONTAINING CHROMIUM AND LEAD.

Waste Code: K087
Waste Description: DECANTER TANK TAR SLUDGE FROM COKING OPERATIONS.

Waste Code: K088
Waste Description: SPENT POTLINERS FROM PRIMARY ALUMINUM REDUCTION.

Waste Code: K093
Waste Description: DISTILLATION LIGHT ENDS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Waste Code: K094
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF PHTHALIC ANHYDRIDE FROM ORTHO-XYLENE.

Waste Code: K095
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

Waste Code: K096
Waste Description: HEAVY ENDS FROM THE HEAVY ENDS COLUMN FROM THE PRODUCTION OF 1,1,1-TRICHLOROETHANE.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: K097
Waste Description: VACUUM STRIPPER DISCHARGE FROM THE CHLORDANE CHLORINATOR IN THE PRODUCTION OF CHLORDANE.

Waste Code: K098
Waste Description: UNTREATED PROCESS WASTEWATER FROM THE PRODUCTION OF TOXAPHENE.

Waste Code: K099
Waste Description: UNTREATED WASTEWATER FROM THE PRODUCTION OF 2,4-D.

Waste Code: K100
Waste Description: WASTE LEACHING SOLUTION FROM ACID LEACHING OF EMISSION CONTROL DUST/SLUDGE FROM SECONDARY LEAD SMELTING.

Waste Code: K101
Waste Description: DISTILLATION TAR RESIDUES FROM THE DISTILLATION OF ANILINE-BASED COMPOUNDS IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K102
Waste Description: RESIDUE FROM THE USE OF ACTIVATED CARBON FOR DECOLORIZATION IN THE PRODUCTION OF VETERINARY PHARMACEUTICALS FROM ARSENIC OR ORGANO-ARSENIC COMPOUNDS.

Waste Code: K103
Waste Description: PROCESS RESIDUES FROM ANILINE EXTRACTION FROM THE PRODUCTION OF ANILINE.

Waste Code: K104
Waste Description: COMBINED WASTEWATERS GENERATED FROM NITROBENZENE/ANILINE PRODUCTION.

Waste Code: K105
Waste Description: SEPARATED AQUEOUS STREAM FROM THE REACTOR PRODUCT WASHING STEP IN THE PRODUCTION OF CHLOROBENZENES.

Waste Code: K106
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE MERCURY CELL PROCESS IN CHLORINE PRODUCTION.

Waste Code: K107
Waste Description: COLUMN BOTTOMS FROM PRODUCT SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE (UDMH) FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K108
Waste Description: CONDENSED COLUMN OVERHEADS FROM PRODUCT SEPARATION AND CONDENSED REACTOR VENT GASES FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K109
Waste Description: SPENT FILTER CARTRIDGES FROM PRODUCT PURIFICATION FROM THE PRODUCT OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K110
Waste Description: CONDENSED COLUMN OVERHEADS FROM INTERMEDIATE SEPARATION FROM THE PRODUCTION OF 1,1-DIMETHYLHYDRAZINE FROM CARBOXYLIC ACID HYDRAZIDES.

Waste Code: K111

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: PRODUCT WASHWATERS FROM THE PRODUCTION OF DINITROTOLUENE VIA NITRATION OF TOLUENE.

Waste Code: K112
Waste Description: REACTION BY-PRODUCT WATER FROM THE DRYING COLUMN IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K113
Waste Description: CONDENSED LIQUID LIGHT ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K114
Waste Description: VICINALS FROM THE PURIFICATION OF TOLUENEDIAMINE IN PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K115
Waste Description: HEAVY ENDS FROM PURIFICATION OF TOLUENEDIAMINE IN THE PRODUCTION OF TOLUENEDIAMINE VIA HYDROGENATION OF DINITROTOLUENE.

Waste Code: K116
Waste Description: ORGANIC CONDENSATE FROM THE SOLVENT RECOVERY COLUMN IN THE PRODUCTION OF TOLUENE DIISOCYANATE VIA PHOSGENATION OF TOLUENEDIAMINE.

Waste Code: K117
Waste Description: WASTEWATER FROM THE REACTOR VENT GAS SCRUBBER IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K118
Waste Description: SPENT ADSORBENT SOLIDS FROM PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K123
Waste Description: PROCESS WASTEWATER (INCLUDING SUPERNATES, FILTRATES, AND WASHWATERS) FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K124
Waste Description: REACTOR VENT SCRUBBER WATER FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K125
Waste Description: FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS FROM THE PRODUCTION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K126
Waste Description: BAGHOUSE DUST AND FLOOR SWEEPINGS IN MILLING AND PACKAGING OPERATIONS FROM PRODUCTION OR FORMULATION OF ETHYLENEBISDITHIOCARBAMIC ACID AND ITS SALTS.

Waste Code: K131
Waste Description: WASTEWATER FROM THE REACTOR AND SPENT SULFURIC ACID FROM THE ACID DRYER FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K132
Waste Description: SPENT ABSORBENT AND WASTEWATER SEPARATOR SOLIDS FROM THE PRODUCTION OF METHYL BROMIDE.

Waste Code: K136

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: STILL BOTTOMS FROM THE PURIFICATION OF ETHYLENE DIBROMIDE IN THE PRODUCTION OF ETHYLENE DIBROMIDE VIA BROMINATION OF ETHENE.

Waste Code: K141
Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF COAL TAR, INCLUDING, BUT NOT LIMITED TO, TAR COLLECTING SUMP RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL. THIS LISTING DOES NOT INCLUDE K087 (DECANTER TANK SLUDGE FROM COKING OPERATIONS).

Waste Code: K142
Waste Description: TANK STORAGE RESIDUES FROM THE PRODUCTION OF COKE FROM COAL OR FROM THE RECOVERY OF COKE BY-PRODUCTS FROM COAL.

Waste Code: K143
Waste Description: PROCESS RESIDUES FROM THE RECOVERY OF LIGHT OIL, INCLUDING, BUT NOT LIMITED TO, THOSE GENERATED IN STILLS, DECANTERS, AND WASH OIL RECOVERY UNITS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K144
Waste Description: WASTEWATER SUMP RESIDUES FROM LIGHT OIL REFINING, INCLUDING, BUT NOT LIMITED TO, INTERCEPTING OR CONTAMINATION SUMP SLUDGES FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K145
Waste Description: RESIDUES FROM NAPHTHALENE COLLECTION AND RECOVERY OPERATIONS FROM THE RECOVERY OF COKE BY-PRODUCTS PRODUCED FROM COAL.

Waste Code: K147
Waste Description: TAR STORAGE RESIDUES FROM COAL TAR REFINING.

Waste Code: K148
Waste Description: RESIDUES FROM COAL TAR DISTILLATION, INCLUDING, BUT NOT LIMITED TO, STILL BOTTOMS.

Waste Code: K149
Waste Description: DISTILLATION BOTTOMS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, RING-CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS. [THIS WASTE DOES NOT INCLUDE STILL BOTTOMS FROM THE DISTILLATION OF BENZOYL CHLORIDE]

Waste Code: K150
Waste Description: ORGANIC RESIDULES EXCLUDING SPENT CARBON ADSORBENT, FROM THE SPENT CHLORINE GAS AND HYDROCHLORIC ACID RECOVERY PROCESSES ASSOCIATED WITH THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Waste Code: K151
Waste Description: WASTEWATER TREATMENT SLUDGES, EXCLUDING NEUTRALIZATION AND BIOLOGICAL SLUDGES, GENERATED DURING THE TREATMENT OF WASTEWATERS FROM THE PRODUCTION OF ALPHA (OR METHYL-) CHLORINATED TOLUNES, BENZOYL CHLORIDES, AND COMPOUNDS WITH MIXTURES OF THESE FUNCTIONAL GROUPS.

Waste Code: K156
Waste Description: ORGANIC WASTE (INCLUDING HEAVY ENDS, STILL BOTTOMS, LIGHT ENDS, SPENT SOLVENTS, FILTRATES, AND DECANTATES) FROM THE PRODUCTION OF CARBAMATES

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

AND CARBAMOYL OXIMES.

Waste Code: K157
Waste Description: WASTEWATERS (INCLUDING SCRUBBER WATERS, CONDENSER WATERS, WASHWATERS, AND SEPARATION WATERS) FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K158
Waste Description: BAG HOUSE DUSTS AND FILTER/SEPARATION SOLIDS FROM THE PRODUCTION OF CARBAMATES AND CARBAMOYL OXIMES.

Waste Code: K159
Waste Description: ORGANICS FROM THE TREATMENT OF THIOCARBAMATE WASTES.

Waste Code: K161
Waste Description: PURIFICATION SOLIDS (INCLUDING FILTRATION, EVAPORATION, AND CENTRIFUGATION SOLIDS), BAG HOUSE DUST AND FLOOR SWEEPINGS FROM THE PRODUCTION OF DITHIOCARBAMATE ACIDS AND THEIR SALTS. (THIS LISTING DOES NOT INCLUDE K125 OR K126).

Waste Code: K169
Waste Description: K169

Waste Code: K170
Waste Description: K170

Waste Code: K171
Waste Description: K171

Waste Code: K172
Waste Description: K172

Waste Code: K174
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE PRODUCTION OF ETHLYENE DICHLORIDE OR VINYL CHLORIDE

Waste Code: K175
Waste Description: WASTEWATER TREATMENT SLUDGE FROM THE PRODUCTION OF VINYL CHLORIDE MONOMER..

Waste Code: K176
Waste Description: BAGHOUSE FILTERS FROM THE PRODUCTION OF ANTIMONY OXIDE, INCLUDING FILTERS FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K177
Waste Description: SLAG FROM THE PRODUCTION OF ANTIMONY OXIDE THAT IS SPECULATIVELY ACCUMULATED OR DISPOSED,INCLUDING SLAG FROM THE PRODUCTION OF INTERMEDIATES (E.G.,ANTIMONY METAL OR CRUDE ANTIMONY OXIDE)

Waste Code: K178
Waste Description: RESIDUES FROM MANUFACTURING AND MANUFACTURING-SITE STORAGE OF FERRIC CHLORIDE FROM ACIDS FORMED DURING THE PRODUCTION OF TITANIUM DIOXIDE USING THE CHLORIDE-ILMENITE PROCESS.

Waste Code: K181
Waste Description: Nonwastewaters from the production of dyes and/or pigments.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: LABP
Waste Description: LABP

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P002
Waste Description: 1-ACETYL-2-THIOUREA (OR) ACETAMIDE, N-(AMINOTHIOXOMETHYL)-

Waste Code: P003
Waste Description: 2-PROPENAL (OR) ACROLEIN

Waste Code: P004
Waste Description: 1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5ALPHA, 8ALPHA, 8ABETA)- (OR) ALDRIN

Waste Code: P005
Waste Description: 2-PROPEN-1-OL (OR) ALLYL ALCOHOL

Waste Code: P006
Waste Description: ALUMINUM PHOSPHIDE (R,T)

Waste Code: P007
Waste Description: 3(2H)-ISOXAZOLONE, 5-(AMINOMETHYL)- (OR) 5-(AMINOMETHYL)-3-ISOXAZOLOL

Waste Code: P008
Waste Description: 4-AMINOPYRIDINE (OR) 4-PYRIDINAMINE

Waste Code: P009
Waste Description: AMMONIUM PICRATE (R) (OR) PHENOL, 2,4,6-TRINITRO-, AMMONIUM SALT (R)

Waste Code: P010
Waste Description: ARSENIC ACID H3ASO4

Waste Code: P011
Waste Description: ARSENIC OXIDE AS2O5 (OR) ARSENIC PENTOXIDE

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P013
Waste Description: BARIUM CYANIDE

Waste Code: P014
Waste Description: BENZENETHIOL (OR) THIOPHENOL

Waste Code: P015
Waste Description: BERYLLIUM

Waste Code: P016
Waste Description: DICHLOROMETHYL ETHER (OR) METHANE, OXYBIS[CHLORO-

Waste Code: P017
Waste Description: 2-PROPANONE, 1-BROMO- (OR) BROMOACETONE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P018
Waste Description: BRUCINE (OR) STRYCHNIDIN-10-ONE, 2,3-DIMETHOXY-

Waste Code: P020
Waste Description: DINOSEB (OR) PHENOL, 2-(1-METHYLPROPYL)-4,6-DINITRO-

Waste Code: P021
Waste Description: CALCIUM CYANIDE (OR) CALCIUM CYANIDE CA(CN)2

Waste Code: P022
Waste Description: CARBON DISULFIDE

Waste Code: P023
Waste Description: ACETALDEHYDE, CHLORO- (OR) CHLOROACETALDEHYDE

Waste Code: P024
Waste Description: BENZENAMINE, 4-CHLORO- (OR) P-CHLORANILINE

Waste Code: P026
Waste Description: 1-(O-CHLOROPHENYL)THIOUREA (OR) THIOUREA, (2-CHLOROPHENYL)-

Waste Code: P027
Waste Description: 3-CHLOROPROPIONITRILE (OR) PROPANENITRILE, 3-CHLORO-

Waste Code: P028
Waste Description: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

Waste Code: P029
Waste Description: COPPER CYANIDE (OR) COPPER CYANIDE CU(CN)

Waste Code: P030
Waste Description: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste Code: P031
Waste Description: CYANOGEN (OR) ETHANEDINITRILE

Waste Code: P033
Waste Description: CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL

Waste Code: P034
Waste Description: 2-CYCLOHEXYL-4,6-DINITROPHENOL (OR) PHENOL, 2-CYCLOHEXYL-4,6-DINITRO-

Waste Code: P036
Waste Description: ARSONOUS DICHLORIDE, PHENYL- (OR) DICHLOROPHENYLARSINE

Waste Code: P037
Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2AALPHA, 3BETA, 6BETA, 6AALPHA, 7BETA, 7AALPHA)- (OR) DIELDRIN

Waste Code: P038
Waste Description: ARSINE, DIETHYL- (OR) DIETHYLARSINE

Waste Code: P039
Waste Description: DISULFOTON (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[2-(ETHYLTHIO)ETHYL] ESTER

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P040
Waste Description: O,O-DIETHYL O-PYRAZINYL PHOSPHOROTHIOATE (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL O-PYRAZINYL ESTER

Waste Code: P041
Waste Description: DIETHYL-P-NITROPHENYL PHOSPHATE (OR) PHOSPHORIC ACID, DIETHYL 4-NITROPHENYL ESTER

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P043
Waste Description: DIISOPROPYLFLUOROPHOSPHATE (DFP) (OR) PHOSPHOROFLUORIDIC ACID, BIS(1-METHYLETHYL) ESTER

Waste Code: P044
Waste Description: DIMETHOATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIMETHYL S-[2-(METHYLAMINO)-2-OXOETHYL] ESTER

Waste Code: P045
Waste Description: 2-BUTANONE, 3,3-DIMETHYL-1-(METHYLTHIO)-, O-[METHYLAMINO)CARBONYL] OXIME (OR) THIOFANOX

Waste Code: P046
Waste Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Waste Code: P047
Waste Description: 4,6-DINITRO-O-CRESOL, & SALTS (OR) PHENOL, 2-METHYL-4,6-DINITRO-, & SALTS

Waste Code: P048
Waste Description: 2,4-DINITROPHENOL (OR) PHENOL, 2,4-DINITRO-

Waste Code: P049
Waste Description: DITHIOBIURET (OR) THIOIMIDODICARBONIC DIAMIDE [(H2N)C(S)]2NH

Waste Code: P050
Waste Description: 6,9-METHANO-2,4,3-BENZODIOXATHIEPIN,6,7,8,9,10,10-HEXACHLORO-1,5,5A,6,9,9A-HEXAHYDRO-,3-OXIDE (OR) ENDOSULFAN

Waste Code: P051
Waste Description: 2,7:3,6-DIMETHANONAPHTH[2,3-B]OXIRENE, 3,4,5,6,9,9-HEXACHLORO-1A,2,2A,3,6,6A,7,7A-OCTAHYDRO-, (1AALPHA, 2BETA, 2ABETA, 3ALPHA, 6ALPHA, 6ABETA, 7BETA, 7AALPHA)- & METABOLITES (OR) ENDRIN (OR) ENDRIN, & METABOLITES

Waste Code: P054
Waste Description: AZIRIDINE (OR) ETHYLENEIMINE

Waste Code: P056
Waste Description: FLUORINE

Waste Code: P057
Waste Description: ACETAMIDE, 2-FLUORO- (OR) FLUOROACETAMIDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P058
Waste Description: ACETIC ACID, FLUORO-, SODIUM SALT (OR) FLUOROACETIC ACID, SODIUM SALT

Waste Code: P059
Waste Description: 4,7-METHANO-1H-INDENE, 1,4,5,6,7,8,8-HEPTACHLORO-3A,4,7,7A-TETRAHYDRO- (OR) HEPTACHLOR

Waste Code: P060
Waste Description: 1,4,5,8-DIMETHANONAPHTHALENE, 1,2,3,4,10,10-HEXA-CHLORO-1,4,4A,5,8,8A,-HEXAHYDRO-, (1ALPHA, 4ALPHA, 4ABETA, 5BETA, 8BETA, 8ABETA)- (OR) ISODRIN

Waste Code: P062
Waste Description: HEXAETHYL TETRAPHOSPHATE (OR) TETRAPHOSPHORIC ACID, HEXAETHYL ESTER

Waste Code: P063
Waste Description: HYDROCYANIC ACID (OR) HYDROGEN CYANIDE

Waste Code: P064
Waste Description: METHANE, ISOCYANATO- (OR) METHYL ISOCYANATE

Waste Code: P065
Waste Description: FULMINIC ACID, MERCURY(2+) SALT (R,T) (OR) MERCURY FULMINATE (R,T)

Waste Code: P066
Waste Description: ETHANIMIDOTHIOIC ACID, N-[[(METHYLAMINO)CARBONYL]OXY]-, METHYL ESTER (OR) METHOMYL

Waste Code: P067
Waste Description: 1,2-PROPYLENIMINE (OR) AZIRIDINE, 2-METHYL-

Waste Code: P068
Waste Description: HYDRAZINE, METHYL- (OR) METHYL HYDRAZINE

Waste Code: P069
Waste Description: 2-METHYLLACTONITRILE (OR) PROPANENITRILE, 2-HYDROXY-2-METHYL-

Waste Code: P070
Waste Description: ALDICARB (OR) PROPANAL, 2-METHYL-2-(METHYLTHIO)-, O-[(METHYLAMINO)CARBONYL]OXIME

Waste Code: P071
Waste Description: METHYL PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O,-DIMETHYL O-(4-NITROPHENYL) ESTER

Waste Code: P072
Waste Description: ALPHA-NAPHTHYLTHIOUREA (OR) THIOUREA, 1-NAPHTHALENYL-

Waste Code: P073
Waste Description: NICKEL CARBONYL (OR) NICKEL CARBONYL NI(CO)4, (T-4)-

Waste Code: P074
Waste Description: NICKEL CYANIDE (OR) NICKEL CYANIDE NI(CN)2

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P076
Waste Description: NITRIC OXIDE (OR) NITROGEN OXIDE NO

Waste Code: P077
Waste Description: BENZENAMINE, 4-NITRO- (OR) P-NITROANILINE

Waste Code: P078
Waste Description: NITROGEN DIOXIDE (OR) NITROGEN OXIDE NO2

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P082
Waste Description: METHANIMINE, N-METHYL-N-NITROSO- (OR) N-NITROSODIMETHYLAMINE

Waste Code: P084
Waste Description: N-NITROSOMETHYLVINYLAMINE (OR) VINYLAMINE, N-METHYL-N-NITROSO-

Waste Code: P085
Waste Description: DIPHOSPHORAMIDE, OCTAMETHYL- (OR) OCTAMETHYLPYROPHOSPHORAMIDE

Waste Code: P087
Waste Description: OSMIUM OXIDE OSO4, (T-4)- (OR) OSMIUM TETROXIDE

Waste Code: P088
Waste Description: 7-OXABICYCLO[2.2.1]HEPTANE-2,3-DICARBOXYLIC ACID (OR) ENDOTHALL

Waste Code: P089
Waste Description: PARATHION (OR) PHOSPHOROTHIOIC ACID, O,O-DIETHYL-O-(4-NITROPHENYL) ESTER

Waste Code: P092
Waste Description: MERCURY, (ACETATO-O)PHENYL- (OR) PHENYLMERCURY ACETATE

Waste Code: P093
Waste Description: PHENYLTHIOUREA (OR) THIOUREA, PHENYL-

Waste Code: P094
Waste Description: PHORATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-[(ETHYLTHIO)METHYL] ESTER

Waste Code: P095
Waste Description: CARBONIC DICHLORIDE (OR) PHOSGENE

Waste Code: P096
Waste Description: HYDROGEN PHOSPHIDE (OR) PHOSPHINE

Waste Code: P097
Waste Description: FAMPHUR (OR) PHOSPHOROTHIOIC ACID O-[4-[(DIMETHYLAMINO)SULFONYL]PHENYL] O,O-DIMETHYL ESTER

Waste Code: P098
Waste Description: POTASSIUM CYANIDE (OR) POTASSIUM CYANIDE K(CN)

Waste Code: P099
Waste Description: ARGENTATE (1-), BIS(CYANO-C)-, POTASSIUM (OR) POTASSIUM SILVER CYANIDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P101
Waste Description: ETHYL CYANIDE (OR) PROPANENITRILE

Waste Code: P102
Waste Description: 2-PROPYN-1-OL (OR) PROPARGYL ALCOHOL

Waste Code: P103
Waste Description: SELENOUREA

Waste Code: P104
Waste Description: SILVER CYANIDE (OR) SILVER CYANIDE AG(CN)

Waste Code: P105
Waste Description: SODIUM AZIDE

Waste Code: P106
Waste Description: SODIUM CYANIDE (OR) SODIUM CYANIDE NA(CN)

Waste Code: P108
Waste Description: STRYCHNIDIN-10-ONE, & SALTS (OR) STRYCHNINE, & SALTS

Waste Code: P109
Waste Description: TETRAETHYLDITHIOPYROPHOSPHATE (OR) THIODIPHOSPHORIC ACID, TETRAETHYL ESTER

Waste Code: P110
Waste Description: PLUMBANE, TETRAETHYL- (OR) TETRAETHYL LEAD

Waste Code: P111
Waste Description: DIPHOSPHORIC ACID, TETRAETHYL ESTER (OR) TETRAETHYL PYROPHOSPHATE

Waste Code: P112
Waste Description: METHANE, TETRANITRO- (R) (OR) TETRANITROMETHANE (R)

Waste Code: P113
Waste Description: THALLIC OXIDE (OR) THALLIUM OXIDE TL2O3

Waste Code: P114
Waste Description: SELENIOUS ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SELENITE

Waste Code: P115
Waste Description: SULFURIC ACID, DITHALLIUM (1+) SALT (OR) THALLIUM(I) SULFATE

Waste Code: P116
Waste Description: HYDRAZINECARBOTHIOAMIDE (OR) THIOSEMICARBAZIDE

Waste Code: P118
Waste Description: METHANETHIOL, TRICHLORO- (OR) TRICHLOROMETHANETHIOL

Waste Code: P119
Waste Description: AMMONIUM VANADATE (OR) VANADIC ACID, AMMONIUM SALT

Waste Code: P120
Waste Description: VANADIUM OXIDE V2O5 (OR) VANADIUM PENTOXIDE

Waste Code: P121
Waste Description: ZINC CYANIDE (OR) ZINC CYANIDE ZN(CN)2

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P122
Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 10% (R,T)

Waste Code: P123
Waste Description: TOXAPHENE

Waste Code: P124
Waste Description: ACTINOMYCIN D

Waste Code: P127
Waste Description: P127

Waste Code: P128
Waste Description: P128

Waste Code: P185
Waste Description: 1,3-DITHIOLANE-2-CARBOXALDEHYDE, 2,4-DIMETHYL-, O-[(METHYLAMINO)-CARBONYL]OXIME (OR) TIRPATE

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: P189
Waste Description: CARBAMIC ACID, [(DIBUTYLAMINO)-THIO]METHYL-, 2,3-DIHYDRO-2,2-DIMETHYL -7-BENZOFURANYL ESTER (OR) CARBOSULFAN

Waste Code: P190
Waste Description: CARBAMIC ACID, METHYL-, 3-METHYLPHENYL ESTER (OR) METOLCARB

Waste Code: P191
Waste Description: CARBAMIC ACID, DIMETHYL-, 1-[(DIMETHYL-AMINO)CARBONYL]- 5-METHYL-1H-PYRAZOL-3-YL ESTER (OR) DIMETILAN

Waste Code: P192
Waste Description: ISOLAN (OR) CARBAMIC ACID, DIMETHYL-, 3-METHY-L-(1-METHYLETHYL)-1H-PYRAZOL-5-YL ESTER

Waste Code: P194
Waste Description: ETHANIMIDOTHIOC ACID, 2-(DIMETHYLAMINO)-N-[[(METHYLAMINO) CARBONYL]OXY]-2-OXO-, METHYL ESTER (OR) OXAMYL

Waste Code: P196
Waste Description: MANGANESE DIMETHYLDITHIOCARBAMATE (OR) MANGANESE, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-,

Waste Code: P197
Waste Description: FORMPARANATE (OR) METHANIMIDAMIDE, N,N-DIMETHYL-N'-[2-METHYL-4-[[(METHYLAMINO)CARBONYL]OXY]PHENYL]

Waste Code: P198
Waste Description: METHANIMIDAMIDE, N,N-DIMETHYL-N'-[3-[[(METHYLAMINO)-CARBONYL]OXY]PHENYL]-, MONOHYDROCHLORIDE (OR) FORMETANATE HYDROCHLORIDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: P199
Waste Description: P199

Waste Code: P201
Waste Description: PHENOL, 3-METHYL-5-(1-METHYLETHYL)-, METHYL CARBAMATE (OR) PROMECARB

Waste Code: P202
Waste Description: M-CUMENYL METHYLCARBAMATE (OR) 3-ISOPROPYLPHENYL N-METHYLCARBAMATE (OR) PHENOL, 3-(1-METHYLETHYL)-, METHYL CARBAMATE

Waste Code: P203
Waste Description: ALDICARB SULFONE (OR) PROPANAL, 2-METHYL-2-(METHYL-SULFONYL)-, O-[(METHYLAMINO)CARBONYL] OXIME

Waste Code: P204
Waste Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Waste Code: P205
Waste Description: ZINC, BIS(DIMETHYLCARBAMODITHIOATO-S,S')-, (OR) ZIRAM

Waste Code: U001
Waste Description: ACETALDEHYDE (I) (OR) ETHANAL (I)

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U003
Waste Description: ACETONITRILE (I,T)

Waste Code: U004
Waste Description: ACETOPHENONE (OR) ETHANONE, 1-PHENYL-

Waste Code: U005
Waste Description: 2-ACETYLAMINOFLUORENE (OR) ACETAMIDE, N-9H-FLUOREN-2-YL

Waste Code: U006
Waste Description: ACETYL CHLORIDE (C,R,T)

Waste Code: U007
Waste Description: 2-PROPENAMIDE (OR) ACRYLAMIDE

Waste Code: U008
Waste Description: 2-PROPENOIC ACID (I) (OR) ACRYLIC ACID (I)

Waste Code: U009
Waste Description: 2-PROPENENITRILE (OR) ACRYLONITRILE

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-MET HOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U011
Waste Description: 1H-1,2,4-TRIAZOL-3-AMINE (OR) AMITROLE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U012
Waste Description: ANILINE (I,T) (OR) BENZENAMINE (I,T)

Waste Code: U014
Waste Description: AURAMINE (OR) BENZENAMINE, 4,4'-CARBONIMIDOYLBIS[N,N-DIMETHYL-

Waste Code: U015
Waste Description: AZASERINE (OR) L-SERINE, DIAZOACETATE (ESTER)

Waste Code: U016
Waste Description: BENZ[C]ACRIDINE

Waste Code: U017
Waste Description: BENZAL CHLORIDE (OR) BENZENE, (DICHLOROMETHYL)-

Waste Code: U018
Waste Description: BENZ[A]ANTHRACENE

Waste Code: U019
Waste Description: BENZENE (I,T)

Waste Code: U020
Waste Description: BENZENESULFONIC ACID CHLORIDE (C,R) (OR) BENZENESULFONYL CHLORIDE (C,R)

Waste Code: U021
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE (OR) BENZIDINE

Waste Code: U022
Waste Description: BENZO[A]PYRENE

Waste Code: U023
Waste Description: BENZENE, (TRICHLOROMETHYL)- (OR) BENZOTRICHLORIDE (C,R,T)

Waste Code: U024
Waste Description: DICHLOROMETHOXY ETHANE (OR) ETHANE, 1,1'-[METHYLENEBIS(OXY)]BIS[2-CHLORO-

Waste Code: U025
Waste Description: DICHLOROETHYL ETHER (OR) ETHANE, 1,1'-OXYBIS[2-CHLORO-

Waste Code: U026
Waste Description: CHLORNAPHAZIN (OR) NAPHTHALENAMINE, N,N'-BIS(2-CHLOROETHYL)-

Waste Code: U027
Waste Description: DICHLOROISOPROPYL ETHER (OR) PROPANE, 2,2'-OXYBIS[2-CHLORO-

Waste Code: U028
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER (OR) DIETHYLHEXYL PHTHALATE

Waste Code: U029
Waste Description: METHANE, BROMO- (OR) METHYL BROMIDE

Waste Code: U030
Waste Description: 4-BROMOPHENYL PHENYL ETHER (OR) BENZENE, 1-BROMO-4-PHENOXY-

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U032
Waste Description: CALCIUM CHROMATE (OR) CHROMIC ACID H2CRO4, CALCIUM SALT

Waste Code: U033
Waste Description: CARBON OXYFLUORIDE (R,T) (OR) CARBONIC DIFLUORIDE

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U036
Waste Description: 4,7-METHANO-1H-INDENE, 1,2,4,5,6,7,8,8-OCTACHLORO-2,3,3A,4,7,7A-HEXAHYDRO- (OR) CHLORDANE, ALPHA & GAMMA ISOMERS

Waste Code: U037
Waste Description: BENZENE, CHLORO- (OR) CHLOROBENZENE

Waste Code: U038
Waste Description: BENZENEACETIC ACID, 4-CHLORO-ALPHA-(4-CHLOROPHENYL)-ALPHA-HYDROXY-, ETHYL ESTER (OR) CHLOROBENZILATE

Waste Code: U039
Waste Description: P-CHLORO-M-CRESOL (OR) PHENOL, 4-CHLORO-3-METHYL-

Waste Code: U041
Waste Description: EPICHLOROHYDRIN (OR) OXIRANE, (CHLOROMETHYL)-

Waste Code: U042
Waste Description: 2-CHLOROETHYL VINYL ETHER (OR) ETHENE, (2-CHLOROETHOXY)-

Waste Code: U043
Waste Description: ETHENE, CHLORO- (OR) VINYL CHLORIDE

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U045
Waste Description: METHANE, CHLORO- (I,T) (OR) METHYL CHLORIDE (I,T)

Waste Code: U046
Waste Description: CHLOROMETHYL METHYL ETHER (OR) METHANE, CHLOROMETHOXY-

Waste Code: U047
Waste Description: BETA-CHLORONAPHTHALENE (OR) NAPHTHALENE, 2-CHLORO-

Waste Code: U048
Waste Description: O-CHLOROPHENOL (OR) PHENOL, 2-CHLORO-

Waste Code: U049
Waste Description: 4-CHLORO-O-TOLUIDINE, HYDROCHLORIDE (OR) BENZENAMINE, 4-CHLORO-2-METHYL-, HYDROCHLORIDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code:	U050
Waste Description:	CHRYSENE
Waste Code:	U051
Waste Description:	CREOSOTE
Waste Code:	U052
Waste Description:	CRESOL (CRESYLIC ACID) (OR) PHENOL, METHYL-
Waste Code:	U053
Waste Description:	2-BUTENAL (OR) CROTONALDEHYDE
Waste Code:	U055
Waste Description:	BENZENE, (1-METHYLETHYL)- (I) (OR) CUMENE (I)
Waste Code:	U056
Waste Description:	BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)
Waste Code:	U057
Waste Description:	CYCLOHEXANONE (I)
Waste Code:	U058
Waste Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Waste Code:	U059
Waste Description:	5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN
Waste Code:	U060
Waste Description:	BENZENE, 1,1'-(2,2-DICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDD
Waste Code:	U061
Waste Description:	BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO- (OR) DDT
Waste Code:	U062
Waste Description:	CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3-DICHLORO-2-PROPENYL) ESTER (OR) DIALLATE
Waste Code:	U063
Waste Description:	DIBENZ[A,H]ANTHRACENE
Waste Code:	U064
Waste Description:	BENZO[RST]PENTAPHENE (OR) DIBENZO[A,I]PYRENE
Waste Code:	U066
Waste Description:	1,2-DIBROMO-3-CHLOROPROPANE (OR) PROPANE, 1,2-DIBROMO-3-CHLORO-
Waste Code:	U067
Waste Description:	ETHANE, 1,2-DIBROMO- (OR) ETHYLENE DIBROMIDE
Waste Code:	U068
Waste Description:	METHANE, DIBROMO- (OR) METHYLENE BROMIDE
Waste Code:	U069

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIBUTYL ESTER (OR) DIBUTYL PHTHALATE

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U071
Waste Description: BENZENE, 1,3-DICHLORO- (OR) M-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U073
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DICHLORO- (OR) 3,3'-DICHLOROBENZIDINE

Waste Code: U074
Waste Description: 1,4-DICHLORO-2-BUTENE (I,T) (OR) 2-BUTENE, 1,4-DICHLORO- (I,T)

Waste Code: U075
Waste Description: DICHLORODIFLUOROMETHANE (OR) METHANE, DICHLORODIFLUORO-

Waste Code: U076
Waste Description: ETHANE, 1,1-DICHLORO- (OR) ETHYLIDENE DICHLORIDE

Waste Code: U077
Waste Description: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

Waste Code: U078
Waste Description: 1,1-DICHLOROETHYLENE (OR) ETHENE, 1,1-DICHLORO-

Waste Code: U079
Waste Description: 1,2-DICHLOROETHYLENE (OR) ETHENE, 1,2-DICHLORO-,(E)-

Waste Code: U080
Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U081
Waste Description: 2,4-DICHLOROPHENOL (OR) PHENOL, 2,4-DICHLORO-

Waste Code: U082
Waste Description: 2,6-DICHLOROPHENOL (OR) PHENOL, 2,6-DICHLORO-

Waste Code: U083
Waste Description: PROPANE, 1,2-DICHLORO- (OR) PROPYLENE DICHLORIDE

Waste Code: U084
Waste Description: 1,3-DICHLOROPROPENE (OR) 1-PROPENE, 1,3-DICHLORO-

Waste Code: U085
Waste Description: 1,2:3,4-DIEPOXYBUTANE (I,T) (OR) 2,2'-BIOXIRANE

Waste Code: U086
Waste Description: HYDRAZINE, 1,2-DIETHYL- (OR) N,N'-DIETHYLHYDRAZINE

Waste Code: U087
Waste Description: O,O-DIETHYL S-METHYL DITHIOPHOSPHATE (OR) PHOSPHORODITHIOIC ACID, O,O-DIETHYL S-METHYL ESTER

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U088
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIETHYL ESTER (OR) DIETHYL PHTHALATE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U090
Waste Description: 1,3-BENZODIOXOLE, 5-PROPYL- (OR) DIHYDROSAFROLE

Waste Code: U091
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHOXY- (OR) 3,3'-DIMETHOXYBENZIDINE

Waste Code: U092
Waste Description: DIMETHYLAMINE (I) (OR) METHANAMINE, N-METHYL- (I)

Waste Code: U093
Waste Description: BENZENAMINE, N,N-DIMETHYL-4-(PHENYLAZO)- (OR) P-DIMETHYLAMINOAZOBENZENE

Waste Code: U094
Waste Description: 7,12-DIMETHYLBENZ[A]ANTHRACENE (OR) BENZ[A]ANTHRACENE, 7,12-DIMETHYL-

Waste Code: U095
Waste Description: [1,1'-BIPHENYL]-4,4'-DIAMINE, 3,3'-DIMETHYL- (OR) 3,3'-DIMETHYLBENZIDINE

Waste Code: U096
Waste Description: ALPHA,ALPHA-DIMETHYLBENZYLHYDROPEROXIDE (R) (OR) HYDROPEROXIDE, 1-METHYL-1-PHENYLETHYL- (R)

Waste Code: U097
Waste Description: CARBAMIC CHLORIDE, DIMETHYL- (OR) DIMETHYLCARBAMOYL CHLORIDE

Waste Code: U098
Waste Description: 1,1-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,1-DIMETHYL-

Waste Code: U099
Waste Description: 1,2-DIMETHYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U101
Waste Description: 2,4-DIMETHYLPHENOL (OR) PHENOL, 2,4-DIMETHYL-

Waste Code: U102
Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIMETHYL ESTER (OR) DIMETHYL PHTHALATE

Waste Code: U103
Waste Description: DIMETHYL SULFATE (OR) SULFURIC ACID, DIMETHYL ESTER

Waste Code: U105
Waste Description: 2,4-DINITROTOLUENE (OR) BENZENE, 1-METHYL-2,4-DINITRO-

Waste Code: U106
Waste Description: 2,6-DINITROTOLUENE (OR) BENZENE, 2-METHYL-1,3-DINITRO-

Waste Code: U107

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 1,2-BENZENEDICARBOXYLIC ACID, DIOCTYL ESTER (OR) DI-N-OCTYL PHTHALATE

Waste Code: U108
Waste Description: 1,4-DIETHYLENEOXIDE (OR) 1,4-DIOXANE

Waste Code: U109
Waste Description: 1,2-DIPHENYLHYDRAZINE (OR) HYDRAZINE, 1,2-DIPHENYL-

Waste Code: U110
Waste Description: 1-PROPANIMINE, N-PROPYL-(I) (OR) DIPROPYLAMINE (I)

Waste Code: U111
Waste Description: 1-PROPANAMINE, N-NITROSO-N-PROPYL- (OR) DI-N-PROPYLNITROSAMINE

Waste Code: U112
Waste Description: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U113
Waste Description: 2-PROPENOIC ACID, ETHYL ESTER (I) (OR) ETHYL ACRYLATE (I)

Waste Code: U114
Waste Description: CARBAMODITHIOIC ACID, 1,2-ETHANEDIYLBIS-, SALTS & ESTERS (OR) ETHYLENEBISDITHIOCARBAMIC ACID, SALTS & ESTERS

Waste Code: U115
Waste Description: ETHYLENE OXIDE (I,T) (OR) OXIRANE (I,T)

Waste Code: U116
Waste Description: 2-IMIDAZOLIDINETHIONE (OR) ETHYLENETHIOUREA

Waste Code: U117
Waste Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Waste Code: U118
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, ETHYL ESTER (OR) ETHYL METHACRYLATE

Waste Code: U119
Waste Description: ETHYL METHANESULFONATE (OR) METHANESULFONIC ACID, ETHYL ESTER

Waste Code: U120
Waste Description: FLUORANTHENE

Waste Code: U121
Waste Description: METHANE, TRICHLOROFLUORO- (OR) TRICHLOROMONOFLUOROMETHANE

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U123
Waste Description: FORMIC ACID (C,T)

Waste Code: U124
Waste Description: FURAN (I) (OR) FURFURAN (I)

Waste Code: U125
Waste Description: 2-FURANCARBOXALDEHYDE (I) (OR) FURFURAL (I)

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U126
Waste Description: GLYCIDYLALDEHYDE (OR) OXIRANECARBOXYALDEHYDE

Waste Code: U127
Waste Description: BENZENE, HEXACHLORO- (OR) HEXACHLOROBENZENE

Waste Code: U128
Waste Description: 1,3-BUTADIENE, 1,1,2,3,4,4-HEXACHLORO- (OR) HEXACHLOROBUTADIENE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U130
Waste Description: 1,3-CYCLOPENTADIENE, 1,2,3,4,5,5-HEXACHLORO- (OR) HEXACHLOROCYCLOPENTADIENE

Waste Code: U131
Waste Description: ETHANE, HEXACHLORO- (OR) HEXACHLOROETHANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U133
Waste Description: HYDRAZINE (R,T)

Waste Code: U134
Waste Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Waste Code: U135
Waste Description: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

Waste Code: U136
Waste Description: ARSINIC ACID, DIMETHYL- (OR) CACODYLIC ACID

Waste Code: U137
Waste Description: INDENO[1,2,3-CD]PYRENE

Waste Code: U138
Waste Description: METHANE, IODO- (OR) METHYL IODIDE

Waste Code: U140
Waste Description: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

Waste Code: U141
Waste Description: 1,3-BENZODIOXOLE, 5-(1-PROPENYL)- (OR) ISOSAFROLE

Waste Code: U142
Waste Description: 1,3,4-METHENO-2H-CYCLOBUTA[CD]PENTALEN-2-ONE, 1,1A,3,3A,4,5,5,5A,5B,6-DECACHLOROOCTAHYDRO- (OR) KEPONE

Waste Code: U143
Waste Description: 2-BUTENOIC ACID, 2-METHYL-, 7-[[2,3-DIHYDROXY-2-(1-METHOXYETHYL)-3-METHYL-1-OXOBUTOXY]METHYL]-2,3,5,7A-TETRAHYDRO-1H-PYRROLIZIN-1-YL ESTER, [1S-[1ALPHA(Z), 7(2S*,3R*), 7AALPHA]]- (OR) LASIOCARPINE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U144
Waste Description: ACETIC ACID, LEAD(2+) SALT (OR) LEAD ACETATE

Waste Code: U145
Waste Description: LEAD PHOSPHATE (OR) PHOSPHORIC ACID, LEAD(2+) SALT (2:3)

Waste Code: U146
Waste Description: LEAD SUBACETATE (OR) LEAD, BIS(ACETATO-O)TETRAHYDROXYTRI-

Waste Code: U147
Waste Description: 2,5-FURANDIONE (OR) MALEIC ANHYDRIDE

Waste Code: U148
Waste Description: 3,6-PYRIDAZINEDIONE, 1,2-DIHYDRO- (OR) MALEIC HYDRAZIDE

Waste Code: U149
Waste Description: MALONONITRILE (OR) PROPANEDINITRILE

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Waste Code: U152
Waste Description: 2-PROPENENITRILE, 2-METHYL- (I,T) (OR) METHACRYLONITRILE (I,T)

Waste Code: U153
Waste Description: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U155
Waste Description: 1,2-ETHANEDIAMINE, N,N-DIMETHYL-N'-2-PYRIDINYL-N'-(2-THIENYLMETHYL)- (OR) METHAPYRILENE

Waste Code: U156
Waste Description: CARBONOCHLORIDIC ACID, METHYL ESTER, (I,T) (OR) METHYL CHLOROCARBONATE (I,T)

Waste Code: U157
Waste Description: 3-METHYLCHOLANTHRENE (OR) BENZ[J]ACEANTHRYLENE, 1,2-DIHYDRO-3-METHYL-

Waste Code: U158
Waste Description: 4,4'-METHYLENEBIS(2-CHLOROANILINE) (OR) BENZENAMINE, 4,4'-METHYLENEBIS[2-CHLORO-

Waste Code: U159
Waste Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U160
Waste Description: 2-BUTANONE, PEROXIDE (R,T) (OR) METHYL ETHYL KETONE PEROXIDE (R,T)

Waste Code: U161
Waste Description: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U162
Waste Description: 2-PROPENOIC ACID, 2-METHYL-, METHYL ESTER (I,T) (OR) METHYL METHACRYLATE (I,T)

Waste Code: U163
Waste Description: GUANIDINE, N-METHYL-N'-NITRO-N-NITROSO- (OR) MNNG

Waste Code: U164
Waste Description: 4(1H)-PYRIMIDINONE, 2,3-DIHYDRO-6-METHYL-2-THIOXO- (OR) METHYLTHIOURACIL

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U166
Waste Description: 1,4-NAPHTHALENEDIONE (OR) 1,4-NAPHTHOQUINONE

Waste Code: U167
Waste Description: 1-NAPTHALENAMINE (OR) ALPHA-NAPHTHYLAMINE

Waste Code: U168
Waste Description: 2-NAPTHALENAMINE (OR) BETA-NAPHTHYLAMINE

Waste Code: U169
Waste Description: BENZENE, NITRO- (OR) NITROBENZENE (I,T)

Waste Code: U170
Waste Description: P-NITROPHENOL (I,T) (OR) PHENOL, 4-NITRO-

Waste Code: U171
Waste Description: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)

Waste Code: U172
Waste Description: 1-BUTANAMINE, N-BUTYL-N-NITROSO- (OR) N-NITROSODI-N-BUTYLAMINE

Waste Code: U173
Waste Description: ETHANOL, 2,2'-(NITROSOIMINO)BIS- (OR) N-NITROSODIETHANOLAMINE

Waste Code: U174
Waste Description: ETHANAMINE, N-ETHYL-N-NITROSO- (OR) N-NITROSODIETHYLAMINE

Waste Code: U176
Waste Description: N-NITROSO-N-ETHYLUREA (OR) UREA, N-ETHYL-N-NITROSO-

Waste Code: U177
Waste Description: N-NITROSO-N-METHYLUREA (OR) UREA, N-METHYL-N-NITROSO-

Waste Code: U178
Waste Description: CARBAMIC ACID, METHYLNITROSO-, ETHYL ESTER (OR) N-NITROSO-N-METHYLURETHANE

Waste Code: U179
Waste Description: N-NITROSOPIPERIDINE (OR) PIPERIDINE, 1-NITROSO-

Waste Code: U180
Waste Description: N-NITROSOPYRROLIDINE (OR) PYRROLIDINE, 1-NITROSO-

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U181
Waste Description: 5-NITRO-O-TOLUIDINE (OR) BENZENAMINE, 2-METHYL-5-NITRO

Waste Code: U182
Waste Description: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

Waste Code: U183
Waste Description: BENZENE, PENTACHLORO- (OR) PENTACHLOROBENZENE

Waste Code: U184
Waste Description: ETHANE, PENTACHLORO- (OR) PENTACHLOROETHANE

Waste Code: U185
Waste Description: BENZENE, PENTACHLORONITRO- (OR) PENTACHLORONITROBENZENE (PCNB)

Waste Code: U186
Waste Description: 1,3-PENTADIENE (I) (OR) 1-METHYLBUTADIENE (I)

Waste Code: U187
Waste Description: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

Waste Code: U188
Waste Description: PHENOL

Waste Code: U189
Waste Description: PHOSPHORUS SULFIDE (R) (OR) SULFUR PHOSPHIDE (R)

Waste Code: U190
Waste Description: 1,3-ISOBENZOFURANDIONE (OR) PHTHALIC ANHYDRIDE

Waste Code: U191
Waste Description: 2-PICOLINE (OR) PYRIDINE, 2-METHYL-

Waste Code: U192
Waste Description: BENZAMIDE, 3,5-DICHLORO-N-(1,1-DIMETHYL-2-PROPYNYL)- (OR) PRONAMIDE

Waste Code: U193
Waste Description: 1,2-OXATHIOLANE, 2,2-DIOXIDE (OR) 1,3-PROPANE SULTONE

Waste Code: U194
Waste Description: 1-PROPANAMINE (I,T) (OR) N-PROPYLAMINE (I,T)

Waste Code: U196
Waste Description: PYRIDINE

Waste Code: U197
Waste Description: 2,5-CYCLOHEXADIENE-1,4-DIONE (OR) P-BENZOQUINONE

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U203

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Description: 1,3-BENZODIOXOLE, 5-(2-PROPENYL)- (OR) SAFROLE

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U207
Waste Description: 1,2,4,5-TETRACHLOROBENZENE (OR) BENZENE, 1,2,4,5-TETRACHLORO-

Waste Code: U208
Waste Description: 1,1,1,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,1,2-TETRACHLORO-

Waste Code: U209
Waste Description: 1,1,2,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,2,2-TETRACHLORO-

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U211
Waste Description: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

Waste Code: U213
Waste Description: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

Waste Code: U214
Waste Description: ACETIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) ACETATE

Waste Code: U215
Waste Description: CARBONIC ACID, DITHALLIUM(1+) SALT (OR) THALLIUM(I) CARBONATE

Waste Code: U216
Waste Description: THALLIUM CHLORIDE TLCL (OR) THALLIUM(I) CHLORIDE

Waste Code: U217
Waste Description: NITRIC ACID, THALLIUM(1+) SALT (OR) THALLIUM(I) NITRATE

Waste Code: U218
Waste Description: ETHANETHIOAMIDE (OR) THIOACETAMIDE

Waste Code: U219
Waste Description: THIOUREA

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U221
Waste Description: BENZENEDIAMINE, AR-METHYL- (OR) TOLUENEDIAMINE

Waste Code: U222
Waste Description: BENZENAMINE, 2-METHYL-, HYDROCHLORIDE (OR) O-TOLUIDINE HYDROCHLORIDE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U223
Waste Description: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T) (OR) TOLUENE DIISOCYANATE (R,T)

Waste Code: U225
Waste Description: BROMOFORM (OR) METHANE, TRIBROMO-

Waste Code: U226
Waste Description: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Waste Code: U227
Waste Description: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

Waste Code: U228
Waste Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Waste Code: U234
Waste Description: 1,3,5-TRINITROBENZENE (R,T) (OR) BENZENE, 1,3,5-TRINITRO-

Waste Code: U235
Waste Description: 1-PROPANOL, 2,3-DIBROMO-, PHOSPHATE (3:1) (OR) TRIS(2,3,-DIBROMOPROPYL) PHOSPHATE

Waste Code: U236
Waste Description: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO -4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Waste Code: U237
Waste Description: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Waste Code: U238
Waste Description: CARBAMIC ACID, ETHYL ESTER (OR) ETHYL CARBAMATE (URETHANE)

Waste Code: U239
Waste Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Waste Code: U240
Waste Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Waste Code: U243
Waste Description: 1-PROPENE, 1,1,2,3,3,3-HEXACHLORO- (OR) HEXACHLOROPROPENE

Waste Code: U244
Waste Description: THIOPEROXYDICARBONIC DIAMIDE [(H2N)C(S)]2S2, TETRAMETHYL- (OR) THIRAM

Waste Code: U246
Waste Description: CYANOGEN BROMIDE (CN)BR

Waste Code: U247
Waste Description: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-METHOXY- (OR) METHOXYCHLOR

Waste Code: U248
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS,

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Waste Code: U249
Waste Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Waste Code: U271
Waste Description: BENOMYL (OR) CARBAMIC ACID, [1-[(BUTYLAMINO)CARBONYL]-1H-BENZIMIDAZOL-2-YL]-, METHYL ESTER

Waste Code: U278
Waste Description: BENDIOCARB (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-, METHYL CARBAMATE

Waste Code: U279
Waste Description: U279

Waste Code: U280
Waste Description: BARBAN (OR) CARBAMIC ACID, (3-CHLOROPHENYL)-, 4-CHLORO-2-BUTYNYL ESTER

Waste Code: U328
Waste Description: BENZENAMINE, 2-METHYL- (OR) O-TOLUIDINE

Waste Code: U353
Waste Description: BENZENAMINE, 4-METHYL- (OR) P-TOLUIDINE

Waste Code: U359
Waste Description: ETHANOL, 2-ETHOXY- (OR) ETHYLENE GLYCOL MONOETHYL ETHER

Waste Code: U364
Waste Description: BENDIOCARB PHENOL (OR) 1,3-BENZODIOXOL-4-OL, 2,2-DIMETHYL-

Waste Code: U367
Waste Description: 7-BENZOFURANOL, 2,3-DIHYDRO-2,2-DIMETHYL- (OR) CARBOFURAN PHENOL

Waste Code: U372
Waste Description: CARBAMIC ACID, 1H-BENZIMIDAZOL-2-YL, METHYL ESTER (OR) CARBENDAZIM

Waste Code: U373
Waste Description: CARBAMIC ACID, PHENYL-, 1-METHYLETHYL ESTER (OR) PROPHAM

Waste Code: U378
Waste Description: CARBAMODITHIOIC ACID, (HYDROXYMETHYL) METHYL-, MONOPOTASSIUM SALT (OR) POTASSIUM N-HYDROXYMETHYL- N-METHYLDI-THIOCARBAMATE

Waste Code: U387
Waste Description: CARBAMOTHIOIC ACID, DIPROPYL-, S-(PHENYLMETHYL) ESTER (OR) PROSULFOCARB

Waste Code: U389
Waste Description: CARBAMOTHIOIC ACID, BIS(1-METHYLETHYL)-, S-(2,3,3-TRICHLORO-2-PROPENYL) ESTER (OR) TRIALLATE

Waste Code: U394
Waste Description: A2213 (OR) ETHANIMIDOTHIOIC ACID, 2-(DIMETHYLAMINO)-N-HYDROXY-2-OXO-, METHYL ESTER

Waste Code: U395
Waste Description: DIETHYLENE GLYCOL, DICARBAMATE (OR) ETHANOL, 2,2'-OXYBIS-, DICARBAMATE

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Waste Code: U404
Waste Description: U404

Waste Code: U409
Waste Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Waste Code: U410
Waste Description: ETHANIMIDOTHIOIC ACID, N,N'-[THIOBIS[(METHYLIMINO)CARBONYLOXY]]BIS-, DIMETHYL ESTER (OR) THIODICARB

Waste Code: U411
Waste Description: U411

Waste Code: U480
Waste Description: 2,4,6, TRIBROMPHENOL (I.E.; DISCARDED COMMERCIAL CHEMICAL PRODUCTS, OFF-SPECIFICATION SPECIES, CONTAINER RESIDUES, AND SPILL RESIDUES THEREOF)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: CITY NOT REPORTED, CA 99999
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: STOCKTON, CA 95201
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 1728
Owner/Operator City,State,Zip: CITY NOT REPORTED, CA 99999
Owner/Operator Telephone: 209-465-5768
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Owner/Operator Name: CHARLIE MCCORMICK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1214 WEST WASHINGTON
Owner/Operator City,State,Zip: STOCKTON, CA 95203
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 1996-09-01 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1980-06-30 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2019-10-31 00:00:00.0
Handler Name: MCCORMICK & BAXTER CREOSOTING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 1990-03-23 00:00:00.0
Handler Name: MCCORMICK AND BAXTER CREOSOTING CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 321114
NAICS Description: WOOD PRESERVATION

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1986-08-04 00:00:00.0
Actual Return to Compliance Date: 1988-12-06 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 1986-09-04 00:00:00.0
Enforcement Identifier: 002
Date of Enforcement Action: 1986-08-04 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1990-06-18 00:00:00.0
Actual Return to Compliance Date: 1990-08-16 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 1990-10-31 00:00:00.0
Enforcement Identifier: 004
Date of Enforcement Action: 1990-08-02 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1986-06-13 00:00:00.0
Actual Return to Compliance Date: 1988-02-24 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1991-10-10 00:00:00.0
Actual Return to Compliance Date: 1992-03-17 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 1992-01-31 00:00:00.0
Enforcement Identifier: 005
Date of Enforcement Action: 1991-10-07 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: 200
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 1986-02-14 00:00:00.0
Actual Return to Compliance Date: 1986-06-13 00:00:00.0
Return to Compliance Qualifier: Unverifiable

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 1987-03-13 00:00:00.0
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9EPA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	1985-04-05 00:00:00.0
Actual Return to Compliance Date:	1985-04-30 00:00:00.0
Return to Compliance Qualifier:	Observed

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 1985-04-05 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD - Financial Requirements
Date Violation was Determined: 1988-02-05 00:00:00.0
Actual Return to Compliance Date: 1988-12-06 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 003
Date of Enforcement Action: 1988-06-03 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	60000
Final Monetary Amount:	5000
Paid Amount:	5000
Final Count:	1
Final Amount:	5000
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	TSD - Financial Requirements
Date Violation was Determined:	1987-12-08 00:00:00.0
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	003
Date of Enforcement Action:	1988-06-03 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	60000
Final Monetary Amount:	5000
Paid Amount:	5000
Final Count:	1
Final Amount:	5000
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 1986-08-04 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: R9STA
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 1988-12-06 00:00:00.0
Scheduled Compliance Date: 1986-09-04 00:00:00.0
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 1990-06-29 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier: R9STA
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Former Citation:	Not reported
Evaluation Date:	1990-06-18 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1990-08-16 00:00:00.0
Scheduled Compliance Date:	1990-10-31 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1985-08-07 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1985-01-22 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-06-13 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-02-24 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1991-09-18 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1992-03-17 00:00:00.0
Scheduled Compliance Date:	1992-01-31 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-02-14 00:00:00.0
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9EPA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1986-06-13 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1985-04-30 00:00:00.0
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9EPA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1988-02-24 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1985-04-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1985-04-30 00:00:00.0
Scheduled Compliance Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1993-03-09 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-02-14 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1986-06-13 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	1988-02-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Evaluation Date:	1987-12-08 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1988-12-06 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1993-03-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

SIte:

Name:	MCCORMICK & BAXTER CREOSOTING CO.
Address:	1214 W WASHINGTON ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95203
Event Code:	Not reported
Action Taken Date:	09/27/2005
EPA ID:	CAD009106527
Action Name:	Explanation of Significant Differences
Action ID:	1
Operable Unit:	03
Contaminated Media:	Soil
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2005
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

Media:

EPA ID:	CAD009106527
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	03
Action Name:	Explanation of Significant Differences
Action Taken Date:	09/27/2005
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2005
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	03
Action Name:	Explanation of Significant Differences
Action Taken Date:	09/27/2005
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2005
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

EPA ID:	CAD009106527
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Sediment
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Soil
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Sediment
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID: CAD009106527

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Contaminated Media:	Soil
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL
Superfund Alternative Agreement:	N
Latitude:	37.947851
Longitude:	-121.306635

EPA ID:	CAD009106527
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	03
Action Name:	Record of Decision
Action Taken Date:	03/31/1999
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1999
NPL Status:	Currently on the Final NPL

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Superfund Alternative Agreement: N
Latitude: 37.947851
Longitude: -121.306635

EPA ID: CAD009106527
Contaminated Media: Soil
Action ID: 1
Operable Unit: 01
Action Name: Record of Decision
Action Taken Date: 03/31/1999
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: 37.947851
Longitude: -121.306635

US INST CONTROLS:
Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 03/31/1999
Contaminated Media: Soil
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: 37.947851
Longitude: -121.306635

Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
Action Name: Record of Decision
Action ID: 2
Operable Unit: 03
Actual Date: 03/31/1999
Contaminated Media: Soil
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Event: Not reported
Federal Facility: N
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: 37.947851
Longitude: -121.306635

Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 03/31/1999
Contaminated Media: Sediment
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1999
NPL Status: Currently on the Final NPL
Superfund Alternative Agreement: N
Latitude: 37.947851
Longitude: -121.306635

ENVIROSTOR:
Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W. WASHINGTON STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 39240001
Status: Active
Status Date: 05/01/1986
Site Code: 100108
Site Type: Federal Superfund
Site Type Detailed: State Response or NPL
Acres: 29
NPL: YES
Regulatory Agencies: SMBRP, RWQCB 5S - Central Valley, US EPA
Lead Agency: US EPA
Program Manager: Christine Parent
Supervisor: William Beckman
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: EPA - Multi-Site Cooperative Agreement
Restricted Use: YES
Site Mgmt Req: NONE SPECIFIED
Funding: Joint State/Federal-Funded
Latitude: 37.94860
Longitude: -121.3065
APN: 1451910, 1451911, 14520001, 1452001, 14520010, 1452010, 1452013, 1452014
Past Use: MANUFACTURING - LUMBER/WOOD PRODUCTS

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Potential COC: Arsenic Pentachlorophenol Polynuclear aromatic hydrocarbons (PAHs Acenaphthene Anthracene Fluorene Naphthalene Pyrene 2,3,7,8-TCDD (dioxin
Confirmed COC: Arsenic Polynuclear aromatic hydrocarbons (PAHs Acenaphthene Anthracene Fluorene Naphthalene Pyrene 2,3,7,8-TCDD (dioxin Pentachlorophenol
Potential Description: OTH, SED, SOIL, SURFW
Alias Name: MCCORMICK & BAXTER CREOSOTING COMPANY
Alias Type: Alternate Name
Alias Name: MCCORMICK AND BAXTER
Alias Type: Alternate Name
Alias Name: MCCORMICK AND BAXTER CREOSOTING CO
Alias Type: Alternate Name
Alias Name: 1451910
Alias Type: APN
Alias Name: 1451911
Alias Type: APN
Alias Name: 14520001
Alias Type: APN
Alias Name: 1452001
Alias Type: APN
Alias Name: 14520010
Alias Type: APN
Alias Name: 1452010
Alias Type: APN
Alias Name: 1452013
Alias Type: APN
Alias Name: 1452014
Alias Type: APN
Alias Name: CAD009106527
Alias Type: EPA Identification Number
Alias Name: 110002147891
Alias Type: EPA (FRS #)
Alias Name: T0607700208
Alias Type: GeoTracker Global ID
Alias Name: P12045
Alias Type: PCode
Alias Name: 100108
Alias Type: Project Code (Site Code)
Alias Name: 39240001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Settlement - Administrative
Completed Date: 07/30/1984
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 08/15/1981
Comments: Facility Identified: Permit ISD.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Design/Implementation Workplan

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Completed Date: 09/30/1999
Comments: DES/SED - Remediation of the Surface Water and Sediment Operable Unit with a two foot sand cap and log boom to prevent water traffic.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Plan
Completed Date: 03/31/1999
Comments: RAP - The ROD for the McCormick & Baxter site was signed on 3/31/99. Final remedies for vadose zone soils and Old Mormon Slough sediments and the interim remedy for groundwater were presented in the ROD.

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 03/31/1999
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 03/31/1999
Comments: RIFS/SWSED -- RI/FS SUBMITTED FOR DTSC REVIEW/COMMENTS PROVIDED AND RESPONSE RECEIVED FROM EPA, DRAFT PROPOSED PLAN SUBMITTED FOR DTSC REVIEW INDICATING END OF RI/FS PHASE. RIFS/SOLGW -- FI/FS SUBMITTED FOR DTSC REVIEW/COMMENTS PROVIDED AND RESPONSE RECEIVED FROM EPA, DRAFT PROPOSED PLAN SUBMITTED FOR DTSC REVIEW INDICATING END OF RI/FS PHASE.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 07/03/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 06/27/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Participation Plan / Community Relations Plan
Completed Date: 02/28/1989
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/09/1987
Comments: Site Screening Done: Mitre Model required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 04/30/1985

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments:	Initial groundwater removal.
Completed Area Name:	OU #3 Surface Water/Sediment
Completed Sub Area Name:	Not reported
Completed Document Type:	Record of Decision w/ESD
Completed Date:	09/21/2005
Comments:	DTSC concurred with ESD for changes to the Sediment Cap Remedy. Once the associated State Superfund Contract is Amended, the remedy will be implemented. ESD added bank stabilization (sheet piling) component to support bank erosion and removal of a squatter barge from slough.
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Design/Implementation Workplan
Completed Date:	09/25/2008
Comments:	On this date DTSC, at the request of USEPA accepted the SAP as complete.
Completed Area Name:	OU #3 Surface Water/Sediment
Completed Sub Area Name:	Not reported
Completed Document Type:	Remedial Action Completion Report
Completed Date:	05/09/2007
Comments:	Not reported
Completed Area Name:	OU #3 Surface Water/Sediment
Completed Sub Area Name:	Not reported
Completed Document Type:	Remedial Action Implementation Workplan
Completed Date:	08/22/2006
Comments:	The Remedial Action Management Plan (RAMP) prepared by Montgomery Watson Harza, under contract managed by the US Army Corps of Engineers for US EPA was submitted for review.
Completed Area Name:	OU #2 Groundwater
Completed Sub Area Name:	Not reported
Completed Document Type:	Feasibility Study Workplan
Completed Date:	04/15/2009
Comments:	On This Date DTSC issued a letter accepting the FFS Management Plan as written. DTSC requested that EPA address remaining comments during implementation of the FFS Report.
Completed Area Name:	OU #2 Groundwater
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	04/30/2009
Comments:	According to EPA the sampling for the groundwater focused feasibility study occurred in April 2007,, October 2007, Oct 2008 and April 2009. Please note that the work plan was not completed until September 2008. Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Design/Implementation Workplan
Completed Date:	12/14/2007
Comments:	Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Completed Document Type: Design/Implementation Workplan
Completed Date: 12/10/2007
Comments: The RD/RA Work Plan for the site was revised and resubmitted following the previous conditional approval. The sampling and analysis plan is not approved at this time. The Site Management Plan was approved. The HASP was not reviewed, and has been submitted. DTSC staff conducting oversight of the Remedy will be familiar with and comply with safety procedures of the HASP when on-site.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 04/11/2008
Comments: The correlation study was approved by EPA. DTSC will examine the data and review whether or not this method can be reliably used at the site.

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 02/11/2009
Comments: DTSC accepts the bathymetric survey which indicates that the depth to the surface of the cap is as much as 0.5 feet lower than the previous survey. These areas where the surface of the cap is lower are most likely due to the consolidation of the sediments. The results presented accurately reflect the depth to the surface of the cap, not the overall cap thickness. It is reasonable to conclude that consolidation is occurring and that the vessels did not damage the cap. DTSC accepts these results as adequate to commence Remedy Shakedown as described in paragraph 22.A of the State Superfund Contract. Further, DTSC concurs that the memorandum adequately documents the condition of the cap which when viewed in conjunction with other inspection reports, documents completion of the requirements of paragraph 24.B of the State Superfund Contract.

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Manual
Completed Date: 10/02/2012
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Design - Preliminary/Intermediate
Completed Date: 06/04/2009
Comments: On This date DTSC notified EPA and representatives of UPRR that review of the technical memorandum entitled Brown Sand Backfill Source Sampling Summary, Soil Remedy Implementation dated June 1, 2009 which was received electronically June 2, 2009 was complete. The purpose of the review was to determine if the work performed to date supported the contention that the material from this source was suitable for use imported backfill material as that term is defined in the Consent Decree (CD) for Civil Case number 2:06-cv-2841-FCD-KJM. Based on the data submitted the material is acceptable to DTSC for import to the Site with the condition that the Construction Quality Assurance Project plan (CQAPP) Sampling be revised to reflect the sample collection and analysis of material as

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

it is placed at the site. The site cleanup standards and the screening levels presented in Table 1 of the technical memorandum are acceptable to define suitable material. Revision of the CQAPP should be completed with sufficient time for agency review before fill is delivered to the site.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Implementation Workplan
Completed Date: 09/11/2009
Comments: On this date EPA issued a letter approving the CQAPP as revised.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Implementation Workplan
Completed Date: 09/11/2009
Comments: On this date, EPA accepted the revised Sampling and Analysis Plan as meeting the specifications and requirements of the Consent Decree.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 07/07/2010
Comments: DTSC completed review excavation is complete in the majority of subarea X and technical memoranda have been prepared that describe additional excavation to be completed.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 04/07/2010
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan Amendment
Completed Date: 04/07/2010
Comments: The schedule as presented to DTSC in the Monthly Progress report submitted on April 7, 2010 is accepted without further comment.

Completed Area Name: OU #2 Groundwater
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/14/2011
Comments: The technical memorandum is an adequate response to previous comments presented to EPA by DTSC.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/12/2011
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/23/2011

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments:	The report indicates that approval for discharge to the storm drain is pending. Completion of this task is beyond the control of UPRR, EPA or DTSC. Final inspection is tentatively scheduled for May 31, 2011. Although the lack of progress toward obtaining the final permit makes this date unlikely. The report was accepted without objection as written.
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	06/09/2011
Comments:	Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	07/08/2011
Comments:	Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	08/15/2011
Comments:	Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	09/13/2011
Comments:	On this date DTSC accepted the monthly report as written.
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	10/24/2011
Comments:	On this date, DTSC accepted the Monthly Summary Report as presented.
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	11/28/2011
Comments:	On this date, DTSC informed EPA that DTSC had no objection to accepting the report as presented.
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	12/19/2011
Comments:	Not reported
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	01/19/2012
Comments:	On this date DTSC project staff completed review of the December 2011 Monthly Status Report. The review concluded that the report adequately summarizes the events that occurred during the month of

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

December. DTSC also noted that EPA has made no formal determination regarding the completion of construction. EPA was notified that DTSC had no objection to accepting the report as presented.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/02/2012
Comments: On this date, DTSC completed the review of the January 2012 Monthly Status Report and found that the report adequately summarized the events that occurred during the month.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/13/2012
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/08/2012
Comments: On this date, DTSC notified EPA that it has no objection to accepting the March 2012 Monthly Status Report as presented. The report summarizes the events that occurred during the month. It was noted that the table attached to the report indicates that the Remedial Action Report was completed on 3/30/2012; the document submitted on 3/30/2112 was missing tables, figures and a few appendices; ARCADIS eventually corrected the report and a complete report was received on April 12, 2012. Although later than previously promised, DTSC issued formal comments on the O&M manual on April 30, 2012.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/14/2012
Comments: Following review of the report which presents a discussion of the activities that were conducted under the CD during the month of April 2012, DTSC determined that the report met the minimum requirements presented in the CD. DTSC project staff informed EPA that DTSC had no objection to acceptance of the report as presented. As a result of the review it was noted that it appears that discharge from the basins will not occur this year as the minimal runoff collected is evaporating. The basins have yet to operate as designed due to a number of factors, the most prevalent being the lack of significant rainfall. It is unclear whether actual operation of the valves is necessary under the CD.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/16/2012
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Manual

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Completed Date: 10/31/2014
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 06/20/2012
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: On this date, DTSC presented it findings with respect to the May 2012 report. The report summarizes the events that occurred during the month It is noted that the table attached to the report indicates that the samples collected exceed the discharge limits set by the Stockton MUD. DTSC accepted the report as presented without objection.
Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: The report summarizes the activities that occurred during the month. This report notes that the completion of preparation of both the Remedial Action Report and the O&M manual is pending written comments from EPA. DTSC has provided written feedback on both items. DTSC has no objection to accepting the report as presented.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: On this date, DTSC presented it findings with respect to the July 2012 report. The report summarizes the activities that occurred during the month. This report notes that the completion of preparation of both the Remedial Action Report and the O&M manual is pending written comments from EPA. DTSC has provided written feedback on both items. DTSC accepted the report as presented without objection.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: On this date, DTSC presented it findings with respect to the August 2012 report. The report summarizes the activities that occurred during the month. This report notes that the completion of preparation of both the Remedial Action Report and the O&M manual is still pending. DTSC accepted the report as presented without objection.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments: On this date, DTSC presented it findings with respect to the September 2012 report. The report summarizes the activities that occurred during the month. The completion of both the Remedial Action Report and the O&M manual is pending. DTSC accepted the report as presented without objection.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: On this date, DTSC presented it findings with respect to the October 2012 report. The report summarizes the activities that occurred during the month. This report notes that the Remedial Action Report and the O&M manual are not yet complete. DTSC accepted the report as presented without objection.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/17/2012
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 01/11/2013
Comments: Not reported

Completed Area Name: OU #2 Groundwater
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 10/31/2014
Comments: Not reported

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Manual
Completed Date: 06/04/2015
Comments: US EPA Final

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 11/06/2014
Comments: Single HERO email

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Feasibility Study Workplan
Completed Date: 06/22/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 06/23/2015
Comments: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Feasibility Study Report
Completed Date:	06/10/2015
Comments:	.
Completed Area Name:	OU #2 Groundwater
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	01/25/2016
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	03/30/2017
Comments:	Site Inspection and Sampling Event Report, February 2017
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	06/01/2016
Comments:	Site Inspection June 2016
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	02/05/2016
Comments:	Site Inspection February 2016
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	02/05/2018
Comments:	Site Inspection Report, 10/2017
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Cost Recovery Settlements/Decrees
Completed Date:	03/12/2007
Comments:	Agreement to perform consolidate and cap and $900,000 to DTSC to be placed 294 account
Completed Area Name:	On-Site Cap OU#1
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	12/31/2007
Comments:	the Land Use Covenant was filed by the San Joaquin County Recorders office as Document Number 2007-217435.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Consent Settlement - Administrative
Completed Date:	04/08/2011
Comments:	On this date EPA, McCormick & DTSC entered into a tolling agreement that extended the "tolling Period." The period now runs from July 1, 2008 through January 1, 2012.

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Settlement - Administrative
Completed Date: 09/24/2010
Comments: On this date US EPA returned the Tolling Agreement to DTSC.

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: State/Federal Funded Site Contract Fiscal Approval (CFA)
Completed Date: 01/19/2012
Comments: On this date DTSC completed the internal review to confirm the availability of funds for this contract. As no funds are being added the review focused on whether or not the funding had expired.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/19/2012
Comments: On this date, the letter responding to EPA was signed and placed in the mail. Electronic copies were distributed to DTSC NPL Chief, DTSC OLC Staff Attorney, The USEPA RPM Patricia Bowlin, and her Manager Fred Schauffler.

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/03/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/21/2014
Comments: Not reported

Completed Area Name: OU #3 Surface Water/Sediment
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 11/21/2014
Comments: US EPA transfers O&M to State as of 1/1/2015

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 05/08/2015
Comments: Not reported

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/21/2014
Comments: US EPA Certification of Completion

Completed Area Name: OU #2 Groundwater
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/30/2015

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 01/24/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 06/06/2019
Comments: HARP

Completed Area Name: On-Site Cap OU#1
Completed Sub Area Name: Not reported
Completed Document Type: State/Federal Funded Site Contract
Completed Date: 01/24/2020
Comments: Delay in Contracts.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Order
Completed Date: 05/13/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PRP Identification Memorandum
Completed Date: 01/22/2020
Comments: Closed by OLC

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Litigation Support
Completed Date: 02/05/2019
Comments: Single document finalized 2/5/2019

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 11/06/1990
Comments: Order Confirming 1st Amended Plan of Reorganization

Future Area Name: OU #3 Surface Water/Sediment
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2023
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2025
Future Area Name: On-Site Cap OU#1
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2024
Schedule Area Name: OU #2 Groundwater

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Schedule Sub Area Name: Not reported
Schedule Document Type: Remedial Investigation / Feasibility Study
Schedule Due Date: 07/01/2020
Schedule Revised Date: 07/16/2021

Name: MCCORMICK AND BAXTER CREOSOTING COMPANY
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 952030000
Facility ID: 80001587
Status: Refer: SMBRP
Status Date: 06/19/2013
Site Code: Not reported
Site Type: Corrective Action
Site Type Detailed: Corrective Action
Acres: 0
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: MBR
Program Manager: Not reported
Supervisor: * Unknown
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.94835
Longitude: -121.3098
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAD009106527
Alias Type: EPA Identification Number
Alias Name: T0607700208
Alias Type: GeoTracker Global ID
Alias Name: 39240001
Alias Type: Envirostor ID Number
Alias Name: 80001587
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 04/01/1984
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 04/01/1984
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

UST SAN JOAQUIN:
Name: ARCADIS
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 95203
Region: SJ
Facility Id: FA0005508
Mail Address: 1900 POWELL ST 12TH FLOOR ST
Mail Address 2: Not reported
Mail Care of: Not reported
Mail City,St,Zip: EMERYVILLE, CA 94608

Tank Rec ID: Not reported
Tank Number: 1
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 2
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 3000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Tank Rec ID: Not reported
Tank Number: 3
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 10000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 10
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Calsite:
Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W. WASHINGTON STREET
City: STOCKTON
Region: SACRAMENTO
Facility ID: 39240001
Facility Type: NPJF
Type: NPL SITE, JOINT STATE/FEDERAL-FUNDED
Branch: CC
Branch Name: CENTRAL CALIFORNIA
File Name: Not reported
State Senate District: 05011986
Status: ANNUAL WORKPLAN (AWP) - ACTIVE SITE
Status Name: ANNUAL WORKPLAN - ACTIVE SITE
Lead Agency: DEPT OF TOXIC SUBSTANCES CONTROL
NPL: Listed
SIC Code: 24
SIC Name: MANU - LUMBER & WOOD PRODUCTS
Access: Not reported
Cortese: Not reported
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Confirmed
Staff Member Responsible for Site: Not reported
Supervisor Responsible for Site: Not reported
Region Water Control Board: CV
Region Water Control Board Name: CENTRAL VALLEY
Lat/Long Direction: Not reported
Lat/Long (dms): 0 0 0 / 0 0 0
Lat/long Method: Not reported
Lat/Long Description: Not reported
State Assembly District Code: 17
State Senate District Code: 05
Facility ID: 39240001
Activity: DISC
Activity Name: DISCOVERY
AWP Code: Not reported
Proposed Budget: 0
AWP Completion Date: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Revised Due Date:	Not reported
Comments Date:	08151981
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	ORDER
Activity Name:	I/SE, IORSE, FFA, FFSRA, VCA, EA
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	07301984
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RA
Activity Name:	REMOVAL ACTION
AWP Code:	GW
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	04301985
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	SS
Activity Name:	SITE SCREENING
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	02091987
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	PPP
Activity Name:	PUBLIC PARTICIPATION PLAN
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	02281989
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Facility ID:	39240001
Activity:	COST
Activity Name:	COST RECOVERY
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	11301990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RA
Activity Name:	REMOVAL ACTION
AWP Code:	LIQ
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	06271991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	N
Activity Comments:	SITE MOTHBALLING BEGAN IN JULY 1990 AND IS CONTINUING TO DATE. REMOVALOF THE LIQUIDS AND SLUDGES FROM PROCESS EQUIPMENT WAS COMPLETED 5/91,WITH SOME RESIDUAL WORK DONE 6/91.
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RA
Activity Name:	REMOVAL ACTION
AWP Code:	DUST
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments Date:	07031991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	N
Activity Comments:	AMBIENT AIR MONITORING RESULTS SHOWED AN IMPACT TO AIR QUALITY. ALLOF WORK DONE ON 6/17/91, WITH SOME RESIDUAL WORK DONE 7/91.
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RIFS
Activity Name:	REMEDIAL INVESTIGATION / FEASIBILITY STUDY
AWP Code:	SOIGW
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03311998
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RIFS
Activity Name:	REMEDIAL INVESTIGATION / FEASIBILITY STUDY
AWP Code:	SWSED
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03311998
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	07312007
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	OM
Activity Name:	OPERATION & MAINTENANCE
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	01312021
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Facility ID:	39240001
Activity:	RAP
Activity Name:	REMEDIAL ACTION PLAN / RECORD OF DECISION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03311999
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RMDL
Activity Name:	REMEDIAL ACTION (RAP REQUIRED)
AWP Code:	SED
Proposed Budget:	0
AWP Completion Date:	09302005
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	DES
Activity Name:	DESIGN
AWP Code:	SED
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	09301999
Est Person-Yrs to complete:	0

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	DES
Activity Name:	DESIGN
AWP Code:	GW
Proposed Budget:	0
AWP Completion Date:	12312005
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	RMDL
Activity Name:	REMEDIAL ACTION (RAP REQUIRED)
AWP Code:	GW
Proposed Budget:	0
AWP Completion Date:	07312006
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39240001
Activity:	COST
Activity Name:	COST RECOVERY
AWP Code:	PSET
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	12111998
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	AWP
Definition of Status:	ANNUAL WORKPLAN - ACTIVE SITE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Alternate Address:	WASHINGTON & PERSHING STREETS
Alternate City,St,Zip:	STOCKTON, CA 95208
Alternate Address:	1214 W. WASHINGTON STREET
Alternate City,St,Zip:	STOCKTON, CA 95203
Background Info:	The McCormick & Baxter Superfund Site (M & B) is a 29-acre former wood-preserving facility located in an industrial area near the Port of Stockton. Approximately 105,000 people live and work within 4 miles of the site. The site is bordered on the north by Old Mormon Slough, which is connected to the Stockton Deepwater Channel. From 1942 to 1990, M & B treated utility poles and railroad ties with creosote, pentachlorophenol (PCP), and compounds of arsenic, chromium and copper. Wood treating chemicals and oily waste generated by the wood-treatment processes were stored in tanks and unlined ponds. Soil and groundwater are contaminated with PCP, dioxin, polycyclic aromatic hydrocarbons (PAHs), arsenic, chromium, and copper. In addition, non-aqueous phase liquids (NAPLs) attributable to creosote and petroleum oils use, are widespread beneath the site. Sediment in Old Mormon Slough adjacent to the site is also contaminated, primarily with PAHs and dioxin. Contaminants have been detected in fish caught in the vicinity of the site. The site is fenced to prevent trespassing and posted with warning signs to advise against fishing and consuming fish caught. In 1977 a fish kill in New Mormon Slough and the Stockton Deepwater Channel was attributed to a release of pentachlorophenol (PCP) contaminated stormwater runoff. The

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

California Regional Water Quality Control Board issued a Cleanup and Abatement Order to M & B in January 1978. In 1978 perimeter berms and collection ponds were constructed to prevent stormwater runoff. The unlined oily waste ponds were closed in 1981. In 1984, M & B entered into an agreement with the California Department of Health Services (DHS), now the Department of Toxic Substances Control (DTSC) to investigate and clean up contamination at the site. The owner filed for protection under Chapter 11 of the Federal Bankruptcy Code in 1988. The Environmental Protection Agency (EPA) listed M & B on the National Priorities List (NPL) in October 1992 and became the lead agency for cleanup. A Record of Decision was signed on March 31, 1999. Cleanup of the site is being completed through Federal actions.
EPA has conducted extensive surface and subsurface soils and groundwater sampling to characterize the site. Site security was improved and chemicals and sludges remaining at the site were disposed. Demolition of all site treatment vessels, structures and above-ground tanks and piping was done in 1994. A 437-foot sheeting piling wall was installed along the shoreline of Old Mormon Slough, during 1996-1997, to control seepage from the former oil waste ponds. Approximately 12,000 cubic yards of oily waste have been excavated and backfilled with clean fill. A cap was installed in the central site to prevent water infiltration and to control dust migration. Groundwater monitoring to ascertain contamination migration from the site is continuing. Additional alternatives to cleanup soil and groundwater are currently being evaluated.

Comments Date: 02072000
Comments: Capping of the Old Mormon Slough sediments is scheduled for
Comments Date: 02072000
Comments: completion in 2000. Additional investigations of site soils to
Comments Date: 02072000
Comments: further determine the extent of contamination is also scheduled
Comments Date: 02072000
Comments: to continue this year.
Comments Date: 02091987
Comments: Site Screening Done: Mitre Model required.
Comments Date: 03311998
Comments: RIFS/SWSED -- RI/FS SUBMITTED FOR DTSC REVIEW/COMMENTS
Comments Date: 03311998
Comments: PROVIDED AND RESPONSE RECEIVED FROM EPA, DRAFT PROPOSED
Comments Date: 03311998
Comments: PLAN SUBMITTED FOR DTSC REVIEW INDICATING END OF RI/FS PHASE.
Comments Date: 03311998
Comments: RIFS/SOLGW -- FI/FS SUBMITTED FOR DTSC REVIEW/COMMENTS
Comments Date: 03311998
Comments: PROVIDED AND RESPONSE RECEIVED FROM EPA, DRAFT PROPOSED
Comments Date: 03311998
Comments: PLAN SUBMITTED FOR DTSC REVIEW INDICATING END OF RI/FS PHASE.
Comments Date: 03311999
Comments: RAP - The ROD for the McCormick & Baxter site was signed on
Comments Date: 03311999
Comments: 3/31/99. Final remedies for vadose zone soils and Old Mormon
Comments Date: 03311999
Comments: Slough sediments and the interim remedy for groundwater were
Comments Date: 03311999

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Comments:	presented in the ROD.
Comments Date:	04301985
Comments:	Initial groundwater removal.
Comments Date:	04301991
Comments:	Process liquid removal.
Comments Date:	05311986
Comments:	This is the date the site was first listed pursuant to
Comments Date:	05311986
Comments:	section 25356.
Comments Date:	07251991
Comments:	Wood treatment facility. Contaminants include PCP, creosote
Comments Date:	07251991
Comments:	(PNA), As, Cu, Cr, Zn, and dioxins.
Comments Date:	07311991
Comments:	Removal Action: Ambient air monitoring results showed an
Comments Date:	07311991
Comments:	impact to air quality. With the site in mothball status,
Comments Date:	07311991
Comments:	application of a polymer dust suppressant would reduce
Comments Date:	07311991
Comments:	fugitive dust emissions. Approximately 13 acres on the
Comments Date:	07311991
Comments:	western side of the facility received the dust suppresant.
Comments Date:	08151981
Comments:	Facility Identified: Permit ISD.
Comments Date:	09151981
Comments:	RWQCB & HWMB/Enforcement Inspection: Samples taken.
Comments Date:	09301999
Comments:	DES/SED - Remediation of the Surface Water and Sediment Operable
Comments Date:	09301999
Comments:	Unit with a two foot sand cap and log boom to prevent water
Comments Date:	09301999
Comments:	traffic.
Comments Date:	10151981
Comments:	Records Search.
Comments Date:	10201992
Comments:	Site was listed on NPL on October 14, 1992.
Comments Date:	12111998
Comments:	COST/PSET - A letter agreement settling the DTSC’s post petition
Comments Date:	12111998
Comments:	environmental costs for $143,271.74 was completed on December 11,
Comments Date:	12111998
Comments:	1998. This amount pursuant to the Agreement Re Environmental
Comments Date:	12111998
Comments:	Remediation of Stockton Facility is made payable through the
Comments Date:	12111998
Comments:	Stockton Environmental Trust Account.
ID Name:	BEP DATABASE PCODE
ID Value:	P12045
ID Name:	EPA IDENTIFICATION NUMBER
ID Value:	CAD009106527
ID Name:	CALSTARS CODE
ID Value:	100108
Alternate Name:	MCCORMICK & BAXTER CREOSOTING COMPANY
Alternate Name:	MCCORMICK AND BAXTER
Alternate Name:	MCCORMICK AND BAXTER CREOSOTING CO
Alternate Name:	MCCORMICK & BAXTER CREOSOTING CO

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Alternate Name: Not reported
Special Programs Code: MSCA
Special Programs Name: MULTI-SITE COOPERATIVE AGREEMENT

SWEEPS UST:
Name: MCCORMICK & BAXTER CREOSOTING
Address: 1214 W WASHINGTON
City: STOCKTON
Status: Not reported
Comp Number: 1281
Number: Not reported
Board Of Equalization: 44-024621
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001281-000001
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: 3

Name: MCCORMICK & BAXTER CREOSOTING
Address: 1214 W WASHINGTON
City: STOCKTON
Status: Not reported
Comp Number: 1281
Number: Not reported
Board Of Equalization: 44-024621
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001281-000002
Tank Status: Not reported
Capacity: 3000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Name: MCCORMICK & BAXTER CREOSOTING
Address: 1214 W WASHINGTON
City: STOCKTON
Status: Not reported
Comp Number: 1281
Number: Not reported
Board Of Equalization: 44-024621
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001281-000003

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: OIL
STG: PRODUCT
Content: FUEL OIL
Number Of Tanks: Not reported

HIST UST:
Name: MCCORMICK AND BAXTER CREOSOTIN
Address: 1214 W WASHINGTON STREET
City,State,Zip: STOCKTON, CA 95203
File Number: 0002FF0B
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FF0B.pdf
Region: STATE
Facility ID: 00000016663
Facility Type: Other
Other Type: WOOD PRESERVATION
Contact Name: BILL FEGLEY
Telephone: 2094655767
Owner Name: MCCORMICK AND BAXTER CREOSOTE
Owner Address: 6900 N EDGEWATER
Owner City,St,Zip: PORTLAND, OR 97203
Total Tanks: 0019

Tank Num: 001
Container Num: 001
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 002
Container Num: 002
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 003
Container Num: 003
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Visual, Groundwater Monitoring Well

Tank Num: 004
Container Num: 004
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Type of Fuel:	Not reported
Container Construction Thickness:	1/8"
Leak Detection:	Groundwater Monitoring Well
Tank Num:	005
Container Num:	005
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/8"
Leak Detection:	Groundwater Monitoring Well
Tank Num:	006
Container Num:	006
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	007
Container Num:	007
Year Installed:	1960
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	008
Container Num:	008
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Visual, Groundwater Monitoring Well
Tank Num:	009
Container Num:	009
Year Installed:	1981
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Visual, Groundwater Monitoring Well
Tank Num:	010
Container Num:	010
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Tank Num: 011
Container Num: 011
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 012
Container Num: 012
Year Installed: 1965
Tank Capacity: 00000000
Tank Used for: WASTE
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 013
Container Num: 013
Year Installed: 1978
Tank Capacity: 00500000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Visual, Groundwater Monitoring Well

Tank Num: 014
Container Num: 014
Year Installed: 1978
Tank Capacity: 01000000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Visual, Groundwater Monitoring Well

Tank Num: 015
Container Num: 015
Year Installed: 1980
Tank Capacity: 00080000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: 8
Leak Detection: Visual, Groundwater Monitoring Well

Tank Num: 016
Container Num: 016
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 017
Container Num: 017
Year Installed: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 018
Container Num: 018
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 019
Container Num: 019
Year Installed: Not reported
Tank Capacity: 00000000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 39000179
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094655767
Mail To: Not reported
Mailing Address: 1214 W WASHINGTON
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

DEED:
Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W. WASHINGTON STREET
City,State,Zip: STOCKTON, CA 95203
Envirostor ID: 39240001
Area: ON-SITE CAP OU#1
Sub Area: Not reported
Site Type: FEDERAL SUPERFUND
Status: ACTIVE
Agency: Not reported
Covenant Uploaded: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

ROD:
Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
RG: 9
Site ID: 901129
Action: GOVT Decision Document (ROD)
Operable Unit Number: GROUNDWATER (& SITE-WIDE ROD)
SEQ ID: 1
Action Completion: 1999-03-31 00:00:00
NPL Status: Final
Non NPL Status: Not reported

Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
RG: 9
Site ID: 901129
Action: GOVT Decision Document (ROD)
Operable Unit Number: SEDIMENT
SEQ ID: 2
Action Completion: 1999-03-31 00:00:00
NPL Status: Final
Non NPL Status: Not reported

Name: MCCORMICK & BAXTER CREOSOTING CO.
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAD009106527
RG: 9
Site ID: 901129
Action: GOVT ESD
Operable Unit Number: SEDIMENT
SEQ ID: 1
Action Completion: 2005-09-27 00:00:00
NPL Status: Final
Non NPL Status: Not reported

PRP:
PRP Name: HELLER, EHRMAN, WHITE & MCAULIFFE
MCCORMICK & BAXTER CREOSOTING CO.
SOUTHERN PACIFIC TRANSPORTATION COMPANY
SOUTHERN PACIFIC TRANSPORTATION COMPANY

CORTESE:
Name: MCCORMICK & BAXTER CREOSOTING CO
Address: 1214 W. WASHINGTON STREET
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: 39240001
Global ID: Not reported
Site/Facility Type: FEDERAL SUPERFUND - LISTED

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Cleanup Status:	ACTIVE - LAND USE RESTRICTIONS
Status Date:	05/01/1986
Site Code:	100108
Latitude:	37.948603
Longitude:	-121.30650
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	envirostor
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Haz Waste & Substances Sites

HWP:

EPA ID:	CAD009106527
Name:	MCCORMICK AND BAXTER CREOSOTING CO
Address:	1214 W WASHINGTON ST
Cleanup Status:	CLOSED
Latitude:	37.94835
Longitude:	-121.3098
Facility Type:	Historical - Non-Operating
Facility Size:	Not reported
Supervisor:	Not reported
Site Code:	Not reported
Senate District:	05
Assembly District:	13
Public Information Officer:	Not reported
Commercial Offsite Facility Types:	Not reported
Quarterly Update:	Not reported
Project Manager Lead:	Not reported
Project Manager:	Not reported
Permit Type:	Not reported
Permit Effective Date:	Not reported
Permit Expiration Date:	Not reported
Calenviroscreen Score:	96-100% (highest scores)
Total Planned Hours:	Not reported
Total Planned Amount:	Not reported
Total Actual Hours:	Not reported

Activities:

EPA ID:	CAD009106527
Facility Type:	Historical - Non-Operating
Facility Name:	MCCORMICK AND BAXTER CREOSOTING CO
Project Manager:	Not reported
Project Manager Lead:	Not reported
Supervisor:	Not reported
Facility Status:	CLOSED
Activity Type:	New Operating Permit
Permit Being Renewed:	Not reported
Permit Being Modified:	Not reported
Final Date:	1984-10-15 00:00:00
Type:	Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - APPLICATION PART A RECEIVED
Actual Date: 11/19/1980

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported
Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - APPLICATION PART B RECEIVED
Actual Date: 01/20/1983

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported
Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - FINAL PERMIT (EFFECTIVE)
Actual Date: 10/15/1984

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - FINAL PERMIT
Actual Date: 10/15/1984

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported
Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - PUBLIC COMMENT (BEGIN)
Actual Date: 11/08/1984

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported
Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - CALL-IN LETTER ISSUED
Actual Date: 11/17/1982

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Status: CLOSED
Activity Type: New Operating Permit
Permit Being Renewed: Not reported
Permit Being Modified: Not reported
Final Date: 1984-10-15 00:00:00
Type: Not reported

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

Title Description: Imported 12/2011:PERMIT1
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: New Operating Permit - FINAL PERMIT (EXPIRES)
Actual Date: 10/15/1989

Closure:
EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Size: Not reported
Facility Status: CLOSED
Activity Type: Closure Final
Final Date: Not reported
Type: Not reported
Title Description: Closure
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: Closure Final - RECEIVE CLOSURE CERTIFICATION
Actual Date: 09/26/1989

EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Facility Size: Not reported
Facility Status: CLOSED
Activity Type: Closure Final
Final Date: Not reported
Type: Not reported
Title Description: Closure
Due Date: Not reported
Comments: Not reported
Unit Names: CONTAIN1, TANKSTR1, TANKTRT1
Event Description: Closure Final - ISSUE CLOSURE VERIFICATION
Actual Date: 11/16/1990

Alias:
EPA ID: CAD009106527
Facility Type: Historical - Non-Operating
Facility Name: MCCORMICK AND BAXTER CREOSOTING CO
Facility Status: CLOSED
Project Manager: Not reported
Project Manager Lead: Not reported
Supervisor: Not reported
Alias Type: Envirostor ID Number
Alias: 39240001

MCCORMICK & BAXTER CREOSOTING CO. (Continued) **1000341540**

CERS:
Name: MCCORMICK AND BAXTER CREOSOTING CO
Address: 1214 W WASHINGTON ST
City,State,Zip: STOCKTON, CA 952030000
Site ID: 231542
CERS ID: CAD009106527
CERS Description: Hazardous Waste

Affiliation:
Affiliation Type Desc: Facility Owner
Entity Name: MCCORMICK AND BAXTER CREOSOTING CO
Entity Title: Not reported
Affiliation Address: PO BOX 1728
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 952010000
Affiliation Phone: 2094655767

Affiliation Type Desc: Facility Contact
Entity Name: ENV MGR
Entity Title: Not reported
Affiliation Address: PO BOX 1728
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 952010000
Affiliation Phone: 2094655767

A1 **GOSPEL CENTER RESCUE MISSION INC.** **HAZNET S124706455**
445 S. SAN JOAQUIN STREET **HWTS N/A**
< 1/8 **STOCKTON, CA 95206**
0.001 mi.
5 ft. **Site 1 of 3 in cluster A**

Relative: Higher
Actual: 17 ft.

HAZNET:
Name: GOSPEL CENTER RESCUE MISSION INC.
Address: 445 S. SAN JOAQUIN STREET
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95206
Contact: WAYNE RICHARSON
Telephone: 2094662138
Mailing Name: Not reported
Mailing Address: 445 S. SAN JOAQUIN STREET

Year: 2018
Gepaid: CAC002988264
TSD EPA ID: CAL000190080
CA Waste Code: 151 - Asbestos containing waste
Disposal Method: H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 0.69000

HWTS:
Name: GOSPEL CENTER RESCUE MISSION, INC.

GOSPEL CENTER RESCUE MISSION INC. (Continued) **S124706455**

Address:	445 S. SAN JOAQUIN STREET
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95206
EPA ID:	CAC002988264
Inactive Date:	02/06/2019
Create Date:	11/07/2018
Last Act Date:	02/07/2019
Mailing Name:	Not reported
Mailing Address:	445 S. SAN JOAQUIN STREET
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 95206
Owner Name:	GOSPEL CENTER RESCUE MISSION, INC.
Owner Address:	445 S. SAN JOAQUIN STREET
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA 95206
Contact Name:	WAYNE RICHARSON
Contact Address:	445 S. SAN JOAQUIN STREET
Contact Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95206

NAICS:

EPA ID:	CAC002988264
Create Date:	2018-11-07 10:47:43.180
NAICS Code:	999999
NAICS Description:	Not Otherwise Specified
Issued EPA ID Date:	2018-11-07 10:47:43.21000
Inactive Date:	2019-02-06 10:47:43.18000
Facility Name:	GOSPEL CENTER RESCUE MISSION, INC.
Facility Address:	445 S. SAN JOAQUIN STREET
Facility Address 2:	Not reported
Facility City:	STOCKTON
Facility County:	Not reported
Facility State:	CA
Facility Zip:	95206

A2 **GOSPEL CENTER RESCUE MISSION, INC.** **RCRA NonGen / NLR** **1024768382**
445 S. SAN JOAQUIN STREET **CAC002988264**
< 1/8 **STOCKTON, CA 95206**
0.001 mi.
5 ft. **Site 2 of 3 in cluster A**

Relative: **Higher**
Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2018-11-07 00:00:00.0
Handler Name:	GOSPEL CENTER RESCUE MISSION, INC.
Handler Address:	445 S. SAN JOAQUIN STREET
Handler City,State,Zip:	STOCKTON, CA 95206
EPA ID:	CAC002988264
Contact Name:	WAYNE RICHARSON
Contact Address:	445 S. SAN JOAQUIN STREET
Contact City,State,Zip:	STOCKTON, CA 95206
Contact Telephone:	209-466-2138
Contact Fax:	209-932-0606
Contact Email:	MEGEARATH@YAHOO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

GOSPEL CENTER RESCUE MISSION, INC. (Continued) **1024768382**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	445 S. SAN JOAQUIN STREET
Mailing City,State,Zip:	STOCKTON, CA 95206
Owner Name:	GOSPEL CENTER RESCUE MISSION, INC.
Owner Type:	Other
Operator Name:	WAYNE RICHARSON
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

GOSPEL CENTER RESCUE MISSION, INC. (Continued) **1024768382**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-11-20 16:30:52.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GOSPEL CENTER RESCUE MISSION, INC.
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	445 S. SAN JOAQUIN STREET
Owner/Operator City,State,Zip:	STOCKTON, CA 95206
Owner/Operator Telephone:	209-466-2138
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WAYNE RICHARSON
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	445 S. SAN JOAQUIN STREET
Owner/Operator City,State,Zip:	STOCKTON, CA 95206
Owner/Operator Telephone:	209-466-2138
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2018-11-07 00:00:00.0
Handler Name:	GOSPEL CENTER RESCUE MISSION, INC.
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

GOSPEL CENTER RESCUE MISSION, INC. (Continued) **1024768382**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A3 **GOSPEL CENTER RESCUE MISSION, INC.** **FINDS** **1024652641**
445 S. SAN JOAQUIN STREET **ECHO** **N/A**
< 1/8 **STOCKTON, CA 95206**
0.001 mi.
5 ft. **Site 3 of 3 in cluster A**

Relative:
Higher

Actual:
17 ft.

FINDS:
Registry ID: 110070441029

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1024652641
Registry ID:	110070441029
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110070441029
Name:	GOSPEL CENTER RESCUE MISSION, INC.
Address:	445 S. SAN JOAQUIN STREET
City,State,Zip:	STOCKTON, CA 95206

B4 **A SALABER FRANK DO** **EDR Hist Cleaner** **1014148499**
NNE **348 S SAN JOAQUIN ST** **N/A**
< 1/8 **STOCKTON, CA**
0.047 mi.
248 ft. **Site 1 of 6 in cluster B**

Relative:
Higher

Actual:
17 ft.

EDR Hist Cleaner

Year:	Name:	Type:
1940	A SALABER FRANK DO	CLOTHES PRESSERS AND CLEANERS

C5
NW
< 1/8
0.052 mi.
275 ft.

LOUIE'S GARAGE
336 S HUNTER ST
STOCKTON, CA 95203

Site 1 of 5 in cluster C

RCRA NonGen / NLR | **1024801288** / **CAL000226184**

Relative:
Lower

Actual:
16 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2002-03-01 00:00:00.0
Handler Name:	LOUIE'S GARAGE	
Handler Address:		336 S HUNTER ST
Handler City,State,Zip:		STOCKTON, CA 95203-0000
EPA ID:		CAL000226184
Contact Name:		VICTOR LOUIE
Contact Address:		336 S HUNTER ST
Contact City,State,Zip:		STOCKTON, CA 95203
Contact Telephone:		209-948-2241
Contact Fax:		Not reported
Contact Email:		VICTHEMECHANIC@YAHOO.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		336 S HUNTER ST
Mailing City,State,Zip:		STOCKTON, CA 95203-0000
Owner Name:		VICTOR LOUIE
Owner Type:		Other
Operator Name:		VICTOR LOUIE
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

LOUIE'S GARAGE (Continued) **1024801288**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:45:30.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	VICTOR LOUIE
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	336 S HUNTER ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203-0000
Owner/Operator Telephone:	209-221-5371
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	VICTOR LOUIE
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	336 S HUNTER ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203
Owner/Operator Telephone:	209-948-2241
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

LOUIE'S GARAGE (Continued) **1024801288**

Historic Generators:
Receive Date: 2002-03-01 00:00:00.0
Handler Name: LOUIE'S GARAGE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C6 **LOUIES GARAGE AUTO RPR** **EDR Hist Auto** **1014176963**
NW **336 S HUNTER ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.052 mi.
275 ft. **Site 2 of 5 in cluster C**

Relative: EDR Hist Auto
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1975	LOUIES GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1975	LOUIES GARAGE	General Automotive Repair Shops
1976	LOUIES GARAGE	General Automotive Repair Shops
1977	LOUIES GARAGE	General Automotive Repair Shops
1978	LOUIES GARAGE	General Automotive Repair Shops
1979	LOUIES GARAGE	General Automotive Repair Shops
1980	LOUIES GARAGE	General Automotive Repair Shops
1982	LOUIES GARAGE	General Automotive Repair Shops
1983	LOUIES GARAGE	General Automotive Repair Shops
1985	LOUIES GARAGE	General Automotive Repair Shops
1986	LOUIES GARAGE	General Automotive Repair Shops
1987	LOUIES GARAGE	General Automotive Repair Shops
1988	LOUIES GARAGE	General Automotive Repair Shops
1989	LOUIES GARAGE	General Automotive Repair Shops
1990	LOUIES GARAGE AUTO REPR	AUTOMOBILE REPAIRING
1990	LOUIES GARAGE	General Automotive Repair Shops
1991	LOUIES GARAGE	General Automotive Repair Shops
1992	LOUIES GARAGE	General Automotive Repair Shops
1993	LOUIES GARAGE	General Automotive Repair Shops
1994	LOUIES GARAGE	General Automotive Repair Shops
1995	LOUIES GARAGE	General Automotive Repair Shops
1996	LOUIES GARAGE	General Automotive Repair Shops

LOUIES GARAGE AUTO RPR (Continued) **1014176963**

1997	LOUIES GARAGE	General Automotive Repair Shops
1998	LOUIES GARAGE	General Automotive Repair Shops
1999	LOUIES GARAGE AUTO RPR	AUTOMOBILE REPAIRING & SERVICE
1999	LOUIES GARAGE	General Automotive Repair Shops
2000	LOUIES GARAGE	General Automotive Repair Shops
2001	LOUIES GARAGE	General Automotive Repair Shops
2002	LOUIES GARAGE	General Automotive Repair Shops
2003	LOUIES GARAGE	General Automotive Repair Shops
2004	LOUIES GARAGE	General Automotive Repair Shops
2005	LOUIES GARAGE	General Automotive Repair Shops
2006	LOUIES GARAGE	General Automotive Repair Shops
2007	LOUIES GARAGE	General Automotive Repair Shops
2008	LOUIES GARAGE	General Automotive Repair Shops
2009	LOUIES GARAGE	General Automotive Repair Shops
2010	LOUIES GARAGE	General Automotive Repair Shops
2011	LOUIES GARAGE	General Automotive Repair Shops
2012	LOUIES GARAGE	General Automotive Repair Shops
2013	LOUIES GARAGE	General Automotive Repair Shops
2014	LOUIES GARAGE	General Automotive Repair Shops

B7 **NING TOM LAUNDRY** **EDR Hist Cleaner** **1014158991**
North **329 S SAN JOAQUIN ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.061 mi.
324 ft. **Site 2 of 6 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1970	NING TOM LAUNDRY	LAUNDRIES
1975	NING TOM LAUNDRY	LAUNDRIES AND DRY CLEANERS

C8 **CHOY BEN AUTO SERVICE AUTO** **EDR Hist Auto** **1014175243**
NW **336 HUNTER ST S** **N/A**
< 1/8 **STOCKTON, CA**
0.063 mi.
335 ft. **Site 3 of 5 in cluster C**

Relative: EDR Hist Auto
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1965	CHOY BEN AUTO SERVICE AUTO	AUTOMOBILE REPAIRING

B9 **ACME CLNS** **EDR Hist Cleaner** **1014146221**
North **348 SAN JOAQUIN S** **N/A**
< 1/8 **STOCKTON, CA**
0.067 mi.
356 ft. **Site 3 of 6 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1946	ASALABER FRANK CLDO	CLOTHES PRESSERS AND CLEANERS
1950	A BERNAZZANI A W CLDO	CLEANERS AND DYERS
1955	ACME CLNS	CLEANERS AND DYERS

ACME CLNS (Continued) **1014146221**

1955	ACME CLNS	CLOTHES PRESSERS AND CLEANERS
1960	ACME CLN DCLO PRSRS	CLEANERS AND DYERS

B10 **A SALOBER FRANK INDY** **EDR Hist Cleaner** **1014152969**
North **344 SAN JOAQUIN S** **N/A**
< 1/8 **STOCKTON, CA**
0.070 mi.
371 ft. **Site 4 of 6 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1950	A SALOBER FRANK INDY	LAUNDRIES
1955	FRENCH CURTAIN LNDRY	CURTAIN CLEANERS

B11 **A ECKERT C W AUTO REPR** **EDR Hist Auto** **1014178764**
North **302 S SAN JOAQUIN ST** **N/A**
< 1/8 **STOCKTON, CA**
0.087 mi.
461 ft. **Site 5 of 6 in cluster B**

Relative: EDR Hist Auto
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1911	SKINNER JOHN C AGT MITCHELL MOT	AUTOMOBILE REPAIRERS
1940	A ECKERT C W AUTO REPR	AUTOMOBILE REPAIRING

B12 **SAITO K LNDY** **EDR Hist Cleaner** **1014152407**
North **246 S SAN JOAQUIN ST** **N/A**
< 1/8 **STOCKTON, CA**
0.093 mi.
490 ft. **Site 6 of 6 in cluster B**

Relative: EDR Hist Cleaner
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1911	SAITO K LNDY	LAUNDRIES

C13 **ATROXELL AGNES MRS CLDO** **EDR Hist Cleaner** **1014155378**
NW **243 HUNTER S** **N/A**
< 1/8 **STOCKTON, CA**
0.093 mi.
492 ft. **Site 4 of 5 in cluster C**

Relative: EDR Hist Cleaner
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1950	ATROXELL AGNES MRS CLDO	CLEANERS AND DYERS

C14 **LOUIES GARAGE AUTO REPR** **EDR Hist Auto** **1014176962**
WNW **325 S HUNTER ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.094 mi.
494 ft. **Site 5 of 5 in cluster C**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1979 LOUIES GARAGE AUTO REPR AUTOMOBILE REPAIRING
1984 LOUIES GARAGE AUTO REPR AUTOMOBILE REPAIRING

D15 **SKEETERS AUTO TRANSMISSIONS** **UST** **U004260272**
WSW **430 S EL DORADO ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.096 mi.
509 ft. **Site 1 of 22 in cluster D**

Relative: UST SAN JOAQUIN:
Lower

Actual:
16 ft.

Name:	SKEETERS AUTO TRANSMISSIONS
Address:	430 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0003975
Mail Address:	PO BOX 2121
Mail Address 2:	Not reported
Mail Care of:	KHALID AMBER
Mail City,St,Zip:	MILL VALLEY, CA 94942
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	0
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	0
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9

SKEETERS AUTO TRANSMISSIONS (Continued) **U004260272**

Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 3
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 0
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 4
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 550
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 5
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 550
Product Type Desc: (none)
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9

SKEETERS AUTO TRANSMISSIONS (Continued) **U004260272**

Common Name: Not reported
Date Installed: 1/1/1986
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

D16 **OCHOA (SKEETERS AUTO)** **SWEEPS UST S101593106**
WSW **448 S EL DORADO ST** **CA FID UST N/A**
< 1/8 **STOCKTON, CA 95203**
0.099 mi.
525 ft. **Site 2 of 22 in cluster D**

Relative: SWEEPS UST:
Lower
Actual: Name: OCHOA (SKEETERS AUTO)
16 ft. Address: 448 S EL DORADO ST
City: STOCKTON
Status: Active
Comp Number: 2369
Number: 2
Board Of Equalization: 44-025014
Referral Date: 09-02-92
Action Date: 09-02-92
Created Date: 03-13-89
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002369-000001
Tank Status: A
Capacity: 1
Active Date: 03-13-89
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: 4

Name: OCHOA (SKEETERS AUTO)
Address: 448 S EL DORADO ST
City: STOCKTON
Status: Active
Comp Number: 2369
Number: 2
Board Of Equalization: 44-025014
Referral Date: 09-02-92
Action Date: 09-02-92
Created Date: 03-13-89
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002369-000002
Tank Status: A
Capacity: 1
Active Date: 03-13-89
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: OCHOA (SKEETERS AUTO)
Address: 448 S EL DORADO ST
City: STOCKTON
Status: Active
Comp Number: 2369

OCHOA (SKEETERS AUTO) (Continued) **S101593106**

Number: 2
Board Of Equalization: 44-025014
Referral Date: 09-02-92
Action Date: 09-02-92
Created Date: 03-13-89
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002369-000003
Tank Status: A
Capacity: 1
Active Date: 03-13-89
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: OCHOA (SKEETERS AUTO)
Address: 448 S EL DORADO ST
City: STOCKTON
Status: Active
Comp Number: 2369
Number: 2
Board Of Equalization: 44-025014
Referral Date: 09-02-92
Action Date: 09-02-92
Created Date: 03-13-89
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002369-000004
Tank Status: A
Capacity: 550
Active Date: 03-13-89
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39002227
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094668678
Mail To: Not reported
Mailing Address: 1330 S PLEASANT AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

D17
WSW
< 1/8
0.099 mi.
525 ft.

SKEETERS AUTOMATIC TRANSMISSION & AUTO REPAIR
448 S EL DORADO ST
STOCKTON, CA 95203

EDR Hist Auto **1014168584**
N/A

Site 3 of 22 in cluster D

Relative:
Lower

Actual:
16 ft.

EDR Hist Auto

Year:	Name:	Type:
1969	MOSQUEDA GEORGE	Gasoline Service Stations
1970	SKEETERS AUTOMATIC TRANSMISSION	AUTOMOBILE REPAIRING
1970	MOSQUEDA GEORGE	Gasoline Service Stations
1971	MOSQUEDA GEORGE	Gasoline Service Stations
1972	MOSQUEDA GEORGE	Gasoline Service Stations
1973	MOSQUEDA GEORGE	Gasoline Service Stations
1974	MOSQUEDA GEORGE	Gasoline Service Stations
1975	SKEETERS AUTOMATIC TRANSMISSION	AUTOMOBILE REPAIRING
1975	MOSQUEDA GEORGE	Gasoline Service Stations
1976	MOSQUEDA GEORGE	Gasoline Service Stations
1977	MOSQUEDA GEORGE	Gasoline Service Stations
1978	MOSQUEDA GEORGE	Gasoline Service Stations
1979	SKEETERS AUTOMATIC TRANSMISSION	AUTOMOBILE TRANSMISSION SERVICE
1979	SKEETERS AUTOMATIC TRANSMISSION	AUTOMOBILE REPAIRING
1979	MOSQUEDA GEORGE	Gasoline Service Stations
1980	MOSQUEDA GEORGE	General Automotive Repair Shops
1982	MOSQUEDA GEORGE	General Automotive Repair Shops
1983	SKEETERS AUTOMATIC	General Automotive Repair Shops
1984	SKEETERS AUTOMATIC TRANSMISSION	AUTOMOBILE REPAIRING
1985	SKEETERS AUTMTC TRANSMISSIONS	General Automotive Repair Shops
1986	SKEETERS AUTMTC TRANSMISSIONS	General Automotive Repair Shops
1987	SKEETERS AUTMTC TRANSMISSIONS	General Automotive Repair Shops
1988	SKEETERS AUTMTC TRANSMISSIONS	General Automotive Repair Shops

---

D18
WSW
< 1/8
0.099 mi.
525 ft.

CANHAM M L GAS STA
440 S EL DORADO ST
STOCKTON, CA

EDR Hist Auto **1014179915**
N/A

Site 4 of 22 in cluster D

Relative:
Lower

Actual:
16 ft.

EDR Hist Auto

Year:	Name:	Type:
1940	CANHAM M L GAS STA	GASOLINE AND OIL SERVICE STATIONS

D19
West
< 1/8
0.100 mi.
526 ft.

ROMERO AUTO REPAIR
410 S EL DORADO ST
STOCKTON, CA 95203

CERS HAZ WASTE **S123532543**
CERS **N/A**

Site 5 of 22 in cluster D

Relative:
Lower

Actual:
16 ft.

CERS HAZ WASTE:

Name:	ROMERO AUTO REPAIR
Address:	410 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	520453
CERS ID:	10787053
CERS Description:	Hazardous Waste Generator

ROMERO AUTO REPAIR (Continued) **S123532543**

CERS:
Name: ROMERO AUTO REPAIR
Address: 410 S EL DORADO ST
City,State,Zip: STOCKTON, CA 95203
Site ID: 520453
CERS ID: 10787053
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 02-20-2020
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: Returned to compliance on 03/18/2020. OBSERVATION: This business does not have a hazardous waste ID number in the California Department of Toxic Substances Control (DTSC) database for this business at this address. REGULATION GUIDANCE: A hazardous waste generator shall not treat, store, dispose of, transport or offer for transportation, hazardous waste without having received an Environmental Protection Agency (EPA) Identification (ID) Number. A State EPA ID number is required for generators of less than 100 kg RCRA hazardous waste per month, less than one kg of acutely hazardous waste per month or any amount of non-RCRA hazardous waste. ID numbers are unique to a business and site location. CORRECTIVE ACTION: Go to the DTSC web site at https://dtsc.ca.gov/apply-for-hazardous-waste-epa-id-number/ to obtain a permanent State ID number that starts with CAL. This facility does not qualify for a temporary CAC number since hazardous waste is stored on site every day. Immediately apply for your ID number and submit
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 02-20-2020
Citation: HSC 6.5 25144.6 (b) - California Health and Safety Code, Chapter 6.5, Section(s) 25144.6 (b)
Violation Description: Failure to properly manage reusable soiled textile materials prior to being sent for laundering.
Violation Notes: Returned to compliance on 03/18/2020. OBSERVATION: The operator sends reusable soiled shop textiles to a commercial laundry service but could not provide laundry service receipts. REGULATION GUIDANCE: HSC 25144.6 (a) As used in this section, G reusable soiled textile materialsG means textile items, including, but not limited to, shop towels, uniforms, gloves, and linens and towels which may become soiled with hazardous waste during commercial or industrial use, and are made reusable by laundering or comparable methods of cleaning. (b) Reusable soiled textile materials which meet all of the following requirements are exempt from Section 25205.5 and from Article 6 (commencing with Section 25160) and Article 6.5 (commencing with Section 25167.1): (1) The materials or the management of the materials are not otherwise regulated by the Environmental Protection Agency

ROMERO AUTO REPAIR (Continued) **S123532543**

pursuant to the federal act. (2) The materials are not used to clean up or control a spill or release that is required to be reported to any state or fede

Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 03-01-2019
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 03/20/2019. Employee training records were not available at the time of inspection. The business plan shall include provisions for ensuring that appropriate personnel receive initial and annual refresher training. This training shall be documented electronically or by hard copy and shall be made available for a minimum of three years. Immediately provide employee training for appropriate personnel and submit a copy of the training records to the EHD.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 03-01-2019
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 03/22/2019. The business plan information has not been reviewed and resubmitted in the California Environmental Reporting System (CERS) annually. The hazardous materials inventory shall be submitted by January 15 of each calendar year and may be submitted beginning November 1 of the previous year. Immediately log into the CERS at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 02-20-2020
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

ROMERO AUTO REPAIR (Continued) **S123532543**

Violation Notes:	Returned to compliance on 02/20/2020. OBSERVATION: Hazardous waste containers were observed on-site with incomplete labeling. One 55 gallon drum of used oil and one 30 gallon container of coolant did not have hazardous waste labeling. REGULATION GUIDANCE: All hazardous waste containers shall be marked with the following information: the words G Hazardous WasteG , name and address of generator, hazardous properties, physical state, composition (contents), and accumulation start date. CORRECTIVE ACTION: The violation was corrected during the inspection by adding complete hazardous waste labels to the hazardous waste containers. No further action is required to correct this violation.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 03/22/2019. A site map was not completed or submitted as part of the business plan. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. If a site map element is not applicable for your facility then list it on the map and label as G NA". Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 03/22/2019. Three 55 gallon drums of waste oil were found on site that have not been reported. Any material that meets or exceeds the reportable quantity shall be reported in the facility's business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, add the materials to the hazardous material inventory, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair

ROMERO AUTO REPAIR (Continued) **S123532543**

Violation Date:	03-01-2019
Citation:	HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Description:	Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 03/22/2019. A Hazardous Materials Business Plan has not been established or implemented. A Hazardous Materials Business Plan shall be established and implemented for emergency response to a release or threatened release of a hazardous material when storing hazardous materials at or above the thresholds quantities of 55 gallons for materials that are liquids, 500 pounds for solids, or 200 cubic feet for compressed gas, at standard temperature and pressure. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the required information, and submit for review by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 03/22/2019. A training program was not submitted. Training programs for all employees and annual training, including refresher courses, shall include safety procedures for the event of a release or threatened release of a hazardous material, including, but not limited to, familiarity with the facility's emergency response plans and procedures. These training programs may take into consideration of each employee. Immediately prepare or update the facility's training program, log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes:	Returned to compliance on 03/22/2019. The Business Owner/Operator Identification form has not been submitted. This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health

ROMERO AUTO REPAIR (Continued) **S123532543**

Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 03/22/2019. The emergency response procedures have not been submitted. A business plan shall include the following emergency response procedures for a release or threatened release of hazardous materials, including, but not limited to, the following: - Immediate notification of local emergency personnel and the Environmental Health Department (EHD) - Procedures for the mitigation of a release or threatened release to minimize any potential harm or damage to persons, property, or the environment - Evacuation plans and procedures, including immediate notice, for the site Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 03/22/2019. The facility's business plan was not submitted electronically to the California Environmental Reporting System (CERS). As of January 1, 2013, all businesses were required to submit all business plans electronically. Immediately log into the CERS at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	520453
Site Name:	Romero Auto Repair
Violation Date:	03-01-2019
Citation:	HSC 6.95 25505(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(c)
Violation Description:	Failure to have a business plan readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training.
Violation Notes:	Returned to compliance on 03/22/2019. Facility could not provide the Emergency Response Plan and the Chemical inventory upon request. The emergency response plans and procedures, the inventory of information required by this article, and the site map required by this section

ROMERO AUTO REPAIR (Continued) **S123532543**

shall be readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training pursuant to this section. Immediately make arrangements to have the business plan readily available for review.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 520453
Site Name: Romero Auto Repair
Violation Date: 02-20-2020
Citation: HSC 6.5 25160.2 - California Health and Safety Code, Chapter 6.5, Section(s) 25160.2
Violation Description: Failure of a generator of hazardous waste that meets the conditions to be transported on a consolidated manifest to comply with one or more of the required consolidated manifesting procedures and retain copies of receipts for three years.
Violation Notes: Returned to compliance on 03/18/2020. OBSERVATION: Consolidated manifest receipts found on-site for disposal of hazardous waste contained incomplete information. Several consolidated manifest receipts observed on site contained the incorrect EPA ID number for the waste generator. The consolidated manifest receipts were dated 1-7-19, 4-22-19, 5-24-19, 7-17-19, 9-5-19, 10-30-19, and 2-19-20 for used oil and coolant. REGULATION GUIDANCE: (4) All copies of each receipt shall contain all of the following information: (A) The name, address, identification number, contact person, and telephone number of the generator, and the signature of the generator or the generatorG s representative. (B) The date of the shipment. (C) The manifest number. (D) The volume or quantity of each waste stream received, its California and RCRA waste codes, the wastestream type listed in subdivision (c), and its proper shipping description, including the hazardous class and United Nations/North America (UN/NA) identification number, if appli
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-20-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 3-20-20 . Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Documents provided during inspection: County small business hazardous waste facility brochure. Facility has full contingency plan. Waste streams found: Used oil, used antifreeze, oil filters (metal and paper commingled), vehicle batteries, oily rags Business moved to this location in December of 2018
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

ROMERO AUTO REPAIR (Continued) **S123532543**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-01-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the completed inspection report. Business has been at this location since at least October 2018. Facility does not have internal roads, emergency shutoffs and these elements were not addressed on the site map. Please address this by either writing G NAG for not applicable or a statement that says the element is not on site. Please correct this by the next submittal. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS

Coordinates:

Site ID:	520453
Facility Name:	Romero Auto Repair
Env Int Type Code:	HMBP
Program ID:	10787053
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	37.948610
Longitude:	-121.288430

Affiliation:

Affiliation Type Desc:	Document Preparer
Entity Name:	Linda Allen
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	Romero Auto Repair
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	9503
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Linda Allen
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported

ROMERO AUTO REPAIR (Continued) **S123532543**

Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Linda Allen
Entity Title:	Not reported
Affiliation Address:	322 Poplar Ave
Affiliation City:	Manteca
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95336
Affiliation Phone:	(559) 668-7940
Affiliation Type Desc:	Operator
Entity Name:	Romero auto Repair
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(559) 668-7940
Affiliation Type Desc:	CUPA District
Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205-6232
Affiliation Phone:	(209) 468-3420
Affiliation Type Desc:	Environmental Contact
Entity Name:	Linda Allen
Entity Title:	Not reported
Affiliation Address:	322 Poplar
Affiliation City:	Manteca
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95336
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	Ramiro Auto Repair
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

D20 **ALCON TIRE SHOP AUTO RPR** **EDR Hist Auto** **1014160063**
West **410 S EL DORADO ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.100 mi.
526 ft. **Site 6 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1969	TOYS GARAGE	Automotive Repair Shops, NEC
1971	TOYS GARAGE	Automotive Repair Shops, NEC
1972	TOYS GARAGE	Automotive Repair Shops, NEC
1973	TOYS GARAGE	Automotive Repair Shops, NEC
1974	TOYS GARAGE	Automotive Repair Shops, NEC
1975	TOYS GARAGE	Automotive Repair Shops, NEC
1989	ALCON TIRE SHOP	General Automotive Repair Shops
1991	ALCON TIRE SHOP	General Automotive Repair Shops
1992	ALCON TIRE SHOP	General Automotive Repair Shops
1993	ALCON TIRE SHOP	General Automotive Repair Shops
1994	ALCON TIRE SHOP	General Automotive Repair Shops
1995	ALCON TIRE SHOP	General Automotive Repair Shops
1996	ALCON TIRE SHOP	General Automotive Repair Shops
1997	ALCON TIRE SHOP	General Automotive Repair Shops
1998	ALCON TIRE SHOP	General Automotive Repair Shops
1999	ALCON TIRE SHOP AUTO RPR	AUTOMOBILE REPAIRING & SERVICE
1999	ALCON TIRE SHOP	General Automotive Repair Shops
2000	ALCON TIRE SHOP	General Automotive Repair Shops
2001	ALCON TIRE SHOP	General Automotive Repair Shops
2002	ALCON TIRE SHOP	General Automotive Repair Shops

D21 **ROMERO AUTO REPAIR** **RCRA NonGen / NLR** **1026057286**
West **410 S EL DORADO** **CAL000453482**
< 1/8 **STOCKTON, CA 95302**
0.100 mi.
526 ft. **Site 7 of 22 in cluster D**

Relative: RCRA NonGen / NLR:
Lower

Actual: **16 ft.**

Date Form Received by Agency:		2020-03-13 00:00:00.0
Handler Name:	ROMERO AUTO REPAIR	
Handler Address:		410 S EL DORADO
Handler City,State,Zip:		STOCKTON, CA 95302
EPA ID:		CAL000453482
Contact Name:		LINDA ALLEN
Contact Address:		322 POPLAR AVE
Contact City,State,Zip:		MANTECA, CA 95336
Contact Telephone:		559-668-7940
Contact Fax:		Not reported
Contact Email:		ALLENZOEY49@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		322 POPLAR AVE
Mailing City,State,Zip:		MANTECA, CA 95336

ROMERO AUTO REPAIR (Continued) **1026057286**

Owner Name:	LINDA ALLEN
Owner Type:	Other
Operator Name:	LINDA ALLEN
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-13 17:51:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No

ROMERO AUTO REPAIR (Continued) **1026057286**

Manifest Broker: No
Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: LINDA ALLEN
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 322 POPLAR AVE
Owner/Operator City,State,Zip: MANTECA, CA 95336
Owner/Operator Telephone: 559-668-7940
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: LINDA ALLEN
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 322 POPLAR AVE
Owner/Operator City,State,Zip: MANTECA, CA 95336
Owner/Operator Telephone: 559-668-7940
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-03-13 00:00:00.0
Handler Name: ROMERO AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D22
SW
< 1/8
0.101 mi.
532 ft.

A FUJIMOTO R Y GAS STA
502 S EL DORADO ST
STOCKTON, CA

EDR Hist Auto **1014169442**
N/A

Site 8 of 22 in cluster D

Relative:
Higher

Actual:
17 ft.

EDR Hist Auto

Year:	Name:	Type:
1940	A FUJIMOTO R Y GAS STA	GASOLINE AND OIL SERVICE STATIONS

23
NNE
< 1/8
0.101 mi.
534 ft.

EILAT MARCELI AUTO
318 E LAFAYETTE ST
STOCKTON, CA

EDR Hist Auto **1014189854**
N/A

Relative:
Higher

Actual:
17 ft.

EDR Hist Auto

Year:	Name:	Type:
1940	EILAT MARCELI AUTO	AUTOMOBILE REPAIRING

D24
West
< 1/8
0.104 mi.
550 ft.

ASONORA SERV STA
402 S EL DORADO ST
STOCKTON, CA

EDR Hist Auto **1014174559**
N/A

Site 9 of 22 in cluster D

Relative:
Lower

Actual:
16 ft.

EDR Hist Auto

Year:	Name:	Type:
1940	ASONORA SERV STA	GASOLINE AND OIL SERVICE STATIONS

D25
West
< 1/8
0.105 mi.
553 ft.

BRIDGESTONE/FIRESTONE -SITE 1
400 EL DORADO ST N
STOCKTON, CA 95203

LUST **S104403470**
Cortese **N/A**
HIST CORTESE
CERS

Site 10 of 22 in cluster D

Relative:
Lower

Actual:
16 ft.

LUST:

Name:	WASSERMAN FAMILY TRUST -SITE 2
Address:	400 EL DORADO ST N
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700804
Global Id:	T0607700804
Latitude:	37.957084
Longitude:	-121.290645
Status:	Completed - Case Closed
Status Date:	01/22/2002
Case Worker:	Not reported
RB Case Number:	390983
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	506606
Potential Media Affect:	Aquifer used for drinking water supply

BRIDGESTONE/FIRESTONE -SITE 1 (Continued) **S104403470**

Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607700804
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700804
Action Type: Other
Date: 04/18/1997
Action: Leak Discovery

Global Id: T0607700804
Action Type: Other
Date: 07/30/1997
Action: Leak Reported

Global Id: T0607700804
Action Type: RESPONSE
Date: 01/11/1996
Action: Other Report / Document

LUST:
Global Id: T0607700804
Status: Open - Case Begin Date
Status Date: 04/18/1997

Global Id: T0607700804
Status: Open - Site Assessment
Status Date: 04/18/1997

Global Id: T0607700804
Status: Open - Verification Monitoring
Status Date: 10/10/2001

Global Id: T0607700804
Status: Completed - Case Closed
Status Date: 01/22/2002

Name: BRIDGESTONE/FIRESTONE -SITE 1
Address: 400 EL DORADO ST N
City,State,Zip: STOCKTON, CA 95203
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700476
Global Id: T0607700476
Latitude: 37.957084
Longitude: -121.290645
Status: Completed - Case Closed

BRIDGESTONE/FIRESTONE -SITE 1 (Continued) **S104403470**

Status Date: 03/19/1996
Case Worker: Not reported
RB Case Number: 390608
Local Agency: Not reported
File Location: Not reported
Local Case Number: 2516
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607700476
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700476
Action Type: Other
Date: 05/06/1991
Action: Leak Discovery

Global Id: T0607700476
Action Type: Other
Date: 05/07/1991
Action: Leak Reported

LUST:
Global Id: T0607700476
Status: Open - Case Begin Date
Status Date: 05/06/1991

Global Id: T0607700476
Status: Open - Remediation
Status Date: 05/06/1991

Global Id: T0607700476
Status: Completed - Case Closed
Status Date: 03/19/1996

LUST REG 5:
Name: BRIDGESTONE/FIRESTONE -SITE 1
Address: 400 EL DORADO ST N
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390608
Case Type: Soil only
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local

BRIDGESTONE/FIRESTONE -SITE 1 (Continued) **S104403470**

Program: LUST
MTBE Code: 0

CORTESE:

Name:	BRIDGESTONE/FIRESTONE -SITE 1
Address:	400 EL DORADO ST N
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700476
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	BRIDGESTONE/FIRESTONE -SI
edr_fadd1:	400 EL DORADO
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390608

edr_fname:	WESSERMAN FAMILY TRUST -S
edr_fadd1:	400 EL DORADO
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390983

CERS:

Name:	BRIDGESTONE/FIRESTONE -SITE 1
Address:	400 EL DORADO ST N
City,State,Zip:	STOCKTON, CA 95203
Site ID:	210723
CERS ID:	T0607700476
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker

BRIDGESTONE/FIRESTONE -SITE 1 (Continued) **S104403470**

Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

D26 **KNOWLES SERV STA NO 2 GAS STA** **EDR Hist Auto** **1014195662**
West **447 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.107 mi.
565 ft. **Site 11 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1955	KNOWLES GAS STA 4 HO	GASOLINE STATIONS
1960	KNOWLES SERV STA NO 2 GAS STA	GASOLINE STATIONS

E27 **JIMMIE M. RISHWAIN FAMILY TRUST** **RCRA NonGen / NLR** **1026480323**
NW **138 E. LAFAYETTE ST.** **CAC003086278**
< 1/8 **STOCKTON, CA 95203**
0.107 mi.
565 ft. **Site 1 of 10 in cluster E**

Relative: RCRA NonGen / NLR:
Lower

Actual: **16 ft.**

Date Form Received by Agency:	2020-09-30 00:00:00.0
Handler Name:	JIMMIE M. RISHWAIN FAMILY TRUST
Handler Address:	138 E. LAFAYETTE ST.
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAC003086278
Contact Name:	MARTIN THORPE
Contact Address:	2130 COUNTRY CLUB #A
Contact City,State,Zip:	STOCKTON, CA 95204
Contact Telephone:	209-329-5481
Contact Fax:	Not reported
Contact Email:	PROJECT@ETABATEMENT.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	2130 COUNTRY CLUB #A
Mailing City,State,Zip:	STOCKTON, CA 95204
Owner Name:	JIMMIE M. RISHWAIN FAMILY TRUST
Owner Type:	Other
Operator Name:	MARTIN THORPE
Operator Type:	Other

JIMMIE M. RISHWAIN FAMILY TRUST (Continued) **1026480323**

Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-10-08 18:50:12.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

JIMMIE M. RISHWAIN FAMILY TRUST (Continued) **1026480323**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARTIN THORPE
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2130 COUNTRY CLUB #A
Owner/Operator City,State,Zip:	STOCKTON, CA 95204
Owner/Operator Telephone:	209-329-5481
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JIMMIE M. RISHWAIN FAMILY TRUST
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2130 COUNTRY CLUB #A
Owner/Operator City,State,Zip:	STOCKTON, CA 95204
Owner/Operator Telephone:	209-329-5481
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-09-30 00:00:00.0
Handler Name:	JIMMIE M. RISHWAIN FAMILY TRUST
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56291
NAICS Description:	REMEDIATION SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D28 **AH TYE BROS** **EDR Hist Auto** **1014169642**
West **448 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.107 mi.
567 ft. **Site 12 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1955 AH TYE BROS GASOLINE STATIONS

D29 **SKEETERS AUTOMATIC** **EDR Hist Auto** **1014187280**
West **448 EL DORADO ST S** **N/A**
< 1/8 **STOCKTON, CA**
0.107 mi.
567 ft. **Site 13 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1965 SKEETERS AUTOMATIC AUTOMOBILE REPAIRING

D30 **TOYS GARAGE AUTO REPR** **EDR Hist Auto** **1014197118**
West **410 EL DORADO ST S** **N/A**
< 1/8 **STOCKTON, CA**
0.110 mi.
581 ft. **Site 14 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1965 TOYS GARAGE AUTO REPR AUTOMOBILE REPAIRING
1965 TOYS CHEVRON SERVICE GASOLINE STATIONS

D31 **TOYS CHEVRON SERV** **EDR Hist Auto** **1014193448**
West **410 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.110 mi.
581 ft. **Site 15 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1955 BENS AUTO SERV AUTOMOBILE REPAIRING
1960 TOYS CHEVRON SERV GASOLINE STATIONS
1960 TOYS GARAGE AUTO REPR 4 H AUTOMOBILE REPAIRING

D32 **A GOOLD BROS GAS STA** **EDR Hist Auto** **1014174043**
WSW **502 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.110 mi.
583 ft. **Site 16 of 22 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: Year: Name: Type:
17 ft. 1946 A GOOLD BROS GAS STA GASOLINE AND OIL SERVICE STATIONS
1950 MAURICIO D F GAS STA GASOLINE STATIONS
1960 RAYS ASSOC SERV D GASOLINE STATIONS

D33 **AH TYE DILLY GAS STA** **EDR Hist Auto** **1014174292**
West **402 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.112 mi.
590 ft. **Site 17 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1946 AH TYE DILLY GAS STA GASOLINE AND OIL SERVICE STATIONS
1950 AH TYE BROS GAS STA GASOLINE STATIONS

D34 **RED D SERV GAS STA** **EDR Hist Auto** **1014189816**
West **401 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.112 mi.
591 ft. **Site 18 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1946 EVANS C L GAS GTA GASOLINE AND OIL SERVICE STATIONS
1950 RBEACON SERVICE STA GASOLINE STATIONS
1960 RED D SERV GAS STA GASOLINE STATIONS

D35 **NOMELLINIS ENCO SERVICE** **EDR Hist Auto** **1014196332**
West **401 EL DORADO ST S** **N/A**
< 1/8 **STOCKTON, CA**
0.112 mi.
591 ft. **Site 19 of 22 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
16 ft. 1965 NOMELLINIS ENCO SERVICE GASOLINE STATIONS

D36 **FORD BERT AUTO REPR** **EDR Hist Auto** **1014166534**
WSW **518 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.112 mi.
591 ft. **Site 20 of 22 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1950	FORD BERT AUTO REPR	AUTOMOBILE REPAIRING
1955	FORD BERT AUTO REPR	AUTOMOBILE REPAIRING
1960	FORDS GARAGE AUTO REPR	AUTOMOBILE REPAIRING

D37 **ERNST BENJ AUTO REPR** **EDR Hist Auto** **1014171099**
WSW **520 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.112 mi.
593 ft. **Site 21 of 22 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1946	ERNST BENJ AUTO REPR	AUTOMOBILE REPAIRING

F38 **WASH HOUSE THE SELF SERV LAUNDROMAT** **EDR Hist Cleaner** **1014143974**
SSE **613 S SAN JOAQUIN ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.113 mi.
598 ft. **Site 1 of 3 in cluster F**

Relative: EDR Hist Cleaner
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1970	WASH HOUSE THE SELF SERV LAUNDR	LAUNDRIES-SELF SERVE
1975	WASH HOUSE THE SELF SERV LAUNDR	LAUNDRIES-SELF SERVE
1979	WASH HOUSE THE SELF SERV LAUNDR	LAUNDRIES-SELF SERVE
1984	WASH HOUSE THE SELF SERV LAUNDR	LAUNDRIES-SELF SERVE

E39 **COLONIAL CLEANERS** **EDR Hist Cleaner** **1014149012**
NW **130 E LAFAYETTE ST** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.116 mi.
612 ft. **Site 2 of 10 in cluster E**

Relative: EDR Hist Cleaner
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1970	COLONIAL CLEANERS	CLEANERS AND DYERS
1974	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1975	COLONIAL CLEANERS	CLEANERS AND DYERS
1975	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1976	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1977	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1978	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1979	COLONIAL CLEANERS	CLEANERS AND DYERS
1979	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1980	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

COLONIAL CLEANERS (Continued) **1014149012**

1982	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1983	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1985	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1986	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1987	COLONIAL CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

---

40 **A IWAHASHI TOM AUTO** **EDR Hist Auto** **1014164549**
SW **520 S EL DORADO ST** **N/A**
< 1/8 **STOCKTON, CA**
0.116 mi.
612 ft.

Relative: EDR Hist Auto
Higher

Actual: **17 ft.**

Year:	Name:	Type:
1940	A IWAHASHI TOM AUTO	AUTOMOBILE REPAIRING

G41 **HERNANDO R C MRS CLDO** **EDR Hist Cleaner** **1014144944**
WNW **346 EL DORADO S** **N/A**
< 1/8 **STOCKTON, CA**
0.118 mi.
625 ft. **Site 1 of 3 in cluster G**

Relative: EDR Hist Cleaner
Lower

Actual: **16 ft.**

Year:	Name:	Type:
1946	HERNANDO R C MRS CLDO	CLOTHES PRESSERS AND CLEANERS
1950	UNSOD DIONICIO CLDO	CLEANERS AND DYERS

F42 **CHINESE NOODLE FACTORY** **SWEEPS UST** **S101593368**
SSE **308 E HAZELTON** **CA FID UST** **N/A**
< 1/8 **STOCKTON, CA 95205**
0.122 mi.
646 ft. **Site 2 of 3 in cluster F**

Relative: SWEEPS UST:
Higher

Actual: **17 ft.**

Name:	CHINESE NOODLE FACTORY
Address:	308 E HAZELTON
City:	STOCKTON
Status:	Not reported
Comp Number:	2570
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002570-000001
Tank Status:	Not reported
Capacity:	500
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

CHINESE NOODLE FACTORY (Continued) **S101593368**

CA FID UST:

Facility ID:	39003797
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	1466 S TUXEDO
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95205
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

F43 **CHINA NOODLE FACTORY** **UST** **U004260388**
SSE **308 E HAZELTON AVE** **N/A**
< 1/8 **STOCKTON, CA 95203**
0.122 mi.
646 ft. **Site 3 of 3 in cluster F**

Relative:
Higher

Actual:
17 ft.

UST SAN JOAQUIN:

Name:	CHINA NOODLE FACTORY
Address:	308 E HAZELTON AVE
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0004972
Mail Address:	308 E HAZELTON AVE
Mail Address 2:	Not reported
Mail Care of:	EDMOND HUANG
Mail City,St,Zip:	STOCKTON, CA 95203
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	500
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	37.9470020595
Longitude:	-121.2851135356

E44
NW
< 1/8
0.123 mi.
647 ft.

AKAJIWARA H AUTO REPR
135 E LAFAYETTE ST
STOCKTON, CA

EDR Hist Auto **1014183685**
N/A

Site 3 of 10 in cluster E

Relative:
Lower

EDR Hist Auto

Actual:
16 ft.

Year:	Name:	Type:
1940	AKAJIWARA H AUTO REPR	AUTOMOBILE REPAIRING

D45
West
< 1/8
0.124 mi.
653 ft.

CARTER F H GAS STA
401 S EL DORADO ST
STOCKTON, CA

EDR Hist Auto **1014194241**
N/A

Site 22 of 22 in cluster D

Relative:
Lower

EDR Hist Auto

Actual:
16 ft.

Year:	Name:	Type:
1940	CARTER F H GAS STA	GASOLINE AND OIL SERVICE STATIONS

E46
NW
< 1/8
0.125 mi.
659 ft.

CALIFORNIA LNDY
118 E LAFAYETTE ST
STOCKTON, CA

EDR Hist Cleaner **1014148872**
N/A

Site 4 of 10 in cluster E

Relative:
Lower

EDR Hist Cleaner

Actual:
16 ft.

Year:	Name:	Type:
1940	CALIFORNIA LNDY	LAUNDRIES-STEAM

E47
WNW
1/8-1/4
0.131 mi.
690 ft.

DEN'S AUTO REPAIR, INC.
308 S EL DORADO ST
STOCKTON, CA 95203

CERS HAZ WASTE **S121739028**
CERS **N/A**

Site 5 of 10 in cluster E

Relative:
Lower

Actual:
16 ft.

CERS HAZ WASTE:

Name:	DEN'S AUTO REPAIR, INC.
Address:	308 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	111004
CERS ID:	10181197
CERS Description:	Hazardous Waste Generator

CERS:

Name:	DEN'S AUTO REPAIR, INC.
Address:	308 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	111004
CERS ID:	10181197
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	111004

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	04-28-2016
Citation:	22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description:	Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes:	Returned to compliance on 08/29/2016. A 55 gallon drum of used oil filters was observed overflowing with the lid resting on top of the filters. Used oil filters shall be drained of free-flowing oil, stored in a closed, rainproof container, labeled as G drained used oil filters,G and marked with an accumulation start date. Immediately place all filters in properly closed and labeled containers and ensure that all used oil filters are managed in this way.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	02-27-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 02/27/2019. The business plan information has not been reviewed and resubmitted in the California Environmental Reporting System (CERS) annually. The hazardous materials inventory shall be submitted by January 15 of each calendar year and may be submitted beginning November 1 of the previous year. Immediately log into the CERS at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	02-27-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 02/27/2019. The map does not show storm and sewer drains. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. If a site map element is not applicable for your facility then list it on the map and label as G NA". Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	12-09-2015
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 01/13/2016. A training program has not been submitted. Training programs for all employees and annual training, including refresher courses, shall include safety procedures for the event of a release or threatened release of a hazardous material, including, but not limited to, familiarity with the facility's emergency response plans and procedures. These training programs may take into consideration of each employee. Immediately prepare or update the facility's training program, log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	02-27-2019
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 02/27/2019. One 55 gallon drum of waste antifreeze was found on site that have not been reported and the Hazardous Materials Inventory forms for the waste oil was not complete/accurate; the annual waste amount for the waste oil has not been completed and the type of container in which the waste oil is stored has changed to plastic drums and the information has not been updated. This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	02-27-2019
Citation:	HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)
Violation Description:	Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

	requires modification to any portion of the business plan.
Violation Notes:	Returned to compliance on 02/27/2019. During the inspection, one 55 gallon drum of waste antifreeze was found on site and the updated information has not been submitted. Within 30 days of one the following events, business shall electronically update the information submitted to the California Environmental Reporting System (CERS): - A 100 percent or more increase in the quantity of a previously disclosed material. - Any handling of a previously undisclosed hazardous materials - A change of business address, business ownership, or business name. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	12-09-2015
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 12/23/2015. A site map has not been submitted. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	111004
Site Name:	DEN'S AUTO REPAIR, INC.
Violation Date:	12-09-2015
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 01/13/2016. Proof of employee training was not available at the time of inspection. The business plan shall include provisions for ensuring that appropriate personnel receive initial and annual refresher training. This training shall be documented electronically or by hard copy and shall be made available for a minimum of three years. Immediately provide employee training for appropriate personnel and submit a copy of the training records to the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Violation Date: 04-28-2016
Citation: 40 CFR 1 265.33 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.33
Violation Description: Failure of the facility to test and maintain all communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment.
Violation Notes: Returned to compliance on 08/29/2016. Oily liquid was observed in the spill containment under the used oil drums. All facility communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment, where required, shall be tested and maintained as necessary to assure its proper operation in time of emergency. Spill containment shall be maintained clean and dry at all times. Immediately begin this practice.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Violation Date: 04-28-2016
Citation: 22 CCR 12 66262.40(c) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(c)
Violation Description: Failure to determine if the waste generated is a hazardous waste and to maintain analysis results for three years.
Violation Notes: Returned to compliance on 08/29/2016. According to Mr. Loch, mop water from cleaning the facility floor, including oily staining, is being placed into the toilet for disposal in the sewer system. No hazardous waste determination has been made for this waste. Any person who generates a waste shall determine if the waste is a hazardous waste. Immediately stop pouring oily mop water into the toilet, make a hazardous waste determination for the mop water, and manage it according the Title 22 hazardous waste regulations. Submit a statement and supporting documentation explaining how this waste was managed.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Violation Date: 12-09-2015
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.
Violation Notes: Returned to compliance on 01/13/2016. The emergency response procedures have not been submitted. A business plan shall include the following emergency response procedures for a release or threatened release of hazardous materials, including, but not limited to, the following: - immediate notification of local emergency personnel and the Environmental Health Department (EHD) - procedures for the mitigation of a release or threatened release to minimize any potential harm or damage to persons, property, or the environment - evacuation plans and procedures, including immediate notice, for the site Immediately log into the California Environmental Reporting

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Violation Date: 04-28-2016
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes: Returned to compliance on 10/18/2016. The following containers were observed in the shop with missing and incomplete hazardous waste labeling: -Three rolling red oil drain containers with no labeling. According to Mr. Loch, these containers are emptied into the used oil drums approximately every 3-4 weeks. -A 55 gallon drum of used antifreeze was observed with a hazardous property of "other". -Four 55 gallon drums of used oil and a 55 gallon drum of used antifreeze were observed with incorrect accumulation start dates of 8/20/15. According to the disposal records on site, the used oil and used antifreeze were picked up on 1/21/16. All hazardous waste containers shall be marked with the following information: - the words G Hazardous WasteG - name and address of generator - hazardous properties (ignitable, corrosive, reactive, toxic) - physical state (liquid, solid) - composition (contents) - accumulation start date Immediately label these containers and ensure that all hazardous [Truncated]
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-27-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Corrections to the hazardous materials inventory and site map were completed at the time of inspection. Map was updated to add storm drains and to indicate no internal roads and no emergency shutoffs are present at the facility. Assistance with CERS access and submittal was provided at the time of inspection. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420.
Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-28-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

paperwork, by May 28, 2016. Please be aware as of January 1, 2013, all businesses are required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous waste activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields. Wastes generated at this facility: Used oil, used antifreeze, used oil filters, spent lead acid batteries Documents reviewed: Consolidated manifests for used oil and used antifreeze, Bills of lading for used oil filters, modified contingency plan, training records Documents provided: Return to Compliance Certification form, Schedule of free CUPA classes

Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-09-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork by January 9, 2016. A copy of the inspection report and inspection photos was provided to Pano Loch. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields.
Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Enforcement Action:
Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Site Address: 308 S EL DORADO ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 04-28-2016
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HW
Enf Action Source: CERS

Site ID: 111004
Site Name: DEN'S AUTO REPAIR, INC.
Site Address: 308 S EL DORADO ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 12-09-2015
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

Enf Action Program: HMRRP
Enf Action Source: CERS

Coordinates:
Site ID: 111004
Facility Name: DEN'S AUTO REPAIR, INC.
Env Int Type Code: HWG
Program ID: 10181197
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 37.949620
Longitude: -121.288510

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: San Joaquin Cnty Env Health
Entity Title: Not reported
Affiliation Address: 1868 East Hazelton Avenue
Affiliation City: Stockton
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95205-6232
Affiliation Phone: (209) 468-3420

Affiliation Type Desc: Environmental Contact
Entity Name: SEAINHAC PANO LOCH
Entity Title: Not reported
Affiliation Address: 308 S EL DORADO ST
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95203
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: SEAINHAC PANO LOCH
Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 308 S EL DORADO ST
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95203
Affiliation Phone: Not reported

Affiliation Type Desc: Document Preparer
Entity Name: SEAINHAC PANO LOCH

DEN'S AUTO REPAIR, INC. (Continued) **S121739028**

Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	DEN'S AUTO REPAIR, INC.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	SEAINHAC PANO LOCH
Entity Title:	Not reported
Affiliation Address:	308 S EL DORADO ST
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95203
Affiliation Phone:	(209) 462-1262
Affiliation Type Desc:	Legal Owner
Entity Name:	SEAINHAC PANO LOCH
Entity Title:	Not reported
Affiliation Address:	10141 TIZIANO DRIVE
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95212
Affiliation Phone:	(209) 696-9512
Affiliation Type Desc:	Operator
Entity Name:	DEN'S AUTO REPAIR, INC.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(209) 696-9512

E48
WNW
1/8-1/4
0.131 mi.
690 ft.

AHTYE BROS.
308 S EL DORADO ST
STOCKTON, CA 95207

Site 6 of 10 in cluster E

HIST UST **U001603764**
N/A

Relative:
Lower

Actual:
16 ft.

HIST UST:

Name:	AHTYE BROS.
Address:	308 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95207
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000068920
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	SAM FONG
Telephone:	2094649027
Owner Name:	EDWARD AHTYE
Owner Address:	2211 FERNVALE DRIVE
Owner City,St,Zip:	STOCKTON, CA 95207
Total Tanks:	0004
Tank Num:	001
Container Num:	#2
Year Installed:	1960
Tank Capacity:	00007000
Tank Used for:	WASTE
Type of Fuel:	2
Container Construction Thickness:	X
Leak Detection:	Visual
Tank Num:	002
Container Num:	#3
Year Installed:	1960
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	4
Year Installed:	1960
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	004
Container Num:	#1
Year Installed:	1975
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Visual

E49 **DEN'S AUTO REPAIR** **LUST** **S101593160**
WNW **308 S EL DORADO** **SWEEPS UST** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **CA FID UST**
0.131 mi. **Cortese**
690 ft. **Site 7 of 10 in cluster E** **HIST CORTESE**

Relative:
Lower

Actual:
16 ft.

LUST:

Name:	DEN'S AUTO REPAIR
Address:	308 EL DORADO ST S
City,State,Zip:	STOCKTON, CA 95203
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700715
Global Id:	T0607700715
Latitude:	37.949664
Longitude:	-121.2888932
Status:	Completed - Case Closed
Status Date:	08/22/2013
Case Worker:	Not reported
RB Case Number:	390889
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	1085
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Other Solvent or Non-Petroleum Hydrocarbon
Site History:	May 1995 - Four USTs and associated piping were removed from the site. June 1997 - Soil borings B-1 through B-3 were advanced on-site. September 1997 - Three soil borings (B-4 through B-6) were advanced and completed as monitoring wells (B-4/MW-1, B-5/MW-2, and B-6/MW-3). November 2002 - Cone penetration test (CPT) boring CPT-1 was advanced on-site; CPT-2 was advanced on-site without sounding; CPT-3 and CPT-4 were advanced off-site. September 2005 - MW-4 through MW-7 were installed. Additional investigation is needed to define the lateral extent of the petroleum hydrocarbon plume. An ozone injection bench-scale pilot test has been conditionally approved by the San Joaquin County Environmental Health Department. Remediation was not performed. All thirteen monitoring wells were destroyed in May and June 2013.

LUST:

Global Id:	T0607700715
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700715
Action Type:	ENFORCEMENT
Date:	05/27/2009
Action:	File review

Global Id:	T0607700715
Action Type:	ENFORCEMENT
Date:	12/28/2009
Action:	File review

DEN'S AUTO REPAIR (Continued) **S101593160**

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 03/07/2013
Action: LOP Case Closure Summary to RB

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 04/15/2010
Action: Technical Correspondence / Assistance / Other - #04/15/2010

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 12/31/2010
Action: File review

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 07/21/2010
Action: Technical Correspondence / Assistance / Other - #07/21/2010

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: Technical Correspondence / Assistance / Other - #05/10/2011

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 02/18/2011
Action: Technical Correspondence / Assistance / Other - #02/18/2011

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 08/30/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700715
Action Type: RESPONSE
Date: 04/30/2013
Action: Well Destruction Workplan - Regulator Responded

Global Id: T0607700715
Action Type: RESPONSE
Date: 12/21/2012
Action: Request for Closure - Regulator Responded

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 11/10/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 08/23/2013
Action: Staff Letter

Global Id: T0607700715
Action Type: ENFORCEMENT

DEN'S AUTO REPAIR (Continued) **S101593160**

Date: 11/15/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 06/20/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 02/06/2014
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 07/13/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700715
Action Type: Other
Date: 04/25/1995
Action: Leak Discovery

Global Id: T0607700715
Action Type: Other
Date: 06/21/1995
Action: Leak Reported

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 05/21/1996
Action: Notice of Reimbursement

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 03/22/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700715
Action Type: RESPONSE
Date: 07/01/2009
Action: Correspondence

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 08/05/2008
Action: Staff Letter - #08/05/2008

DEN'S AUTO REPAIR (Continued) **S101593160**

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 08/22/2013
Action: Closure/No Further Action Letter

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 01/09/2009
Action: File review

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 04/01/2009
Action: Staff Letter - #04/01/2009

Global Id: T0607700715
Action Type: ENFORCEMENT
Date: 03/29/2013
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700715
Status: Open - Case Begin Date
Status Date: 04/25/1995

Global Id: T0607700715
Status: Open - Site Assessment
Status Date: 04/25/1995

Global Id: T0607700715
Status: Open - Site Assessment
Status Date: 09/11/1997

Global Id: T0607700715
Status: Open - Eligible for Closure
Status Date: 11/22/2005

Global Id: T0607700715
Status: Open - Site Assessment
Status Date: 11/22/2005

Global Id: T0607700715
Status: Completed - Case Closed
Status Date: 08/22/2013

LUST REG 5:
Name: DEN'S AUTO REPAIR
Address: 308 EL DORADO ST S
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 390889
Case Type: Drinking Water Aquifer affected
Substance: HYDROCARBONS
Staff Initials: JLB

DEN'S AUTO REPAIR (Continued) **S101593160**

Lead Agency: Local
Program: LUST
MTBE Code: 4

SWEEPS UST:
Name: DEN'S AUTO REPAIR
Address: 308 S EL DORADO
City: STOCKTON
Status: Active
Comp Number: 1085
Number: 2
Board Of Equalization: 44-024527
Referral Date: 05-17-89
Action Date: 08-30-91
Created Date: 07-05-88
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001085-000001
Tank Status: A
Capacity: 8000
Active Date: 05-17-89
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Name: DEN'S AUTO REPAIR
Address: 308 S EL DORADO
City: STOCKTON
Status: Active
Comp Number: 1085
Number: 2
Board Of Equalization: 44-024527
Referral Date: 05-17-89
Action Date: 08-30-91
Created Date: 07-05-88
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001085-000002
Tank Status: A
Capacity: 7000
Active Date: 05-17-89
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: DEN'S AUTO REPAIR
Address: 308 S EL DORADO
City: STOCKTON
Status: Active
Comp Number: 1085
Number: 2
Board Of Equalization: 44-024527
Referral Date: 05-17-89
Action Date: 08-30-91
Created Date: 07-05-88
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001085-000003

DEN'S AUTO REPAIR (Continued) **S101593160**

Tank Status: A
Capacity: 5000
Active Date: 05-17-89
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: DEN'S AUTO REPAIR
Address: 308 S EL DORADO
City: STOCKTON
Status: Active
Comp Number: 1085
Number: 2
Board Of Equalization: 44-024527
Referral Date: 05-17-89
Action Date: 08-30-91
Created Date: 07-05-88
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001085-000004
Tank Status: A
Capacity: 500
Active Date: 05-17-89
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39003033
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094662924
Mail To: Not reported
Mailing Address: 308 S EL DORADO
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

CORTESE:
Name: DEN'S AUTO REPAIR
Address: 308 EL DORADO ST S
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700715
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED

DEN'S AUTO REPAIR (Continued) **S101593160**

Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	DEN'S AUTO REPAIR
edr_fadd1:	308 EL DORADO
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390889

E50 **DENS AUTO REPAIR** **RCRA NonGen / NLR** **1026054741**
WNW **308 S EL DORADO ST BLDG A** **CAL000413322**
1/8-1/4 **STOCKTON, CA 95203**
0.131 mi.
690 ft. **Site 8 of 10 in cluster E**

Relative: RCRA NonGen / NLR:
Lower

Actual: **16 ft.**

Date Form Received by Agency:		2015-12-18 00:00:00.0
Handler Name:	DENS AUTO REPAIR	
Handler Address:		308 S EL DORADO ST BLDG A
Handler City,State,Zip:		STOCKTON, CA 95203-3404
EPA ID:		CAL000413322
Contact Name:		SEAINHAC PANO LOCH
Contact Address:		10141 TIZIANO DR
Contact City,State,Zip:		STOCKTON, CA 95212
Contact Telephone:		209-696-9512
Contact Fax:		Not reported
Contact Email:		KHMERGURU@YAHOO.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		10141 TIZIANO DR
Mailing City,State,Zip:		STOCKTON, CA 95212
Owner Name:		LOCH SEAINHAC PANO

DENS AUTO REPAIR (Continued) **1026054741**

Owner Type:	Other
Operator Name:	SEAINHAC PANO LOCH
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-13 17:51:56.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

DENS AUTO REPAIR (Continued) **1026054741**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: SEAINHAC PANO LOCH
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10141 TIZIANO DR
Owner/Operator City,State,Zip: STOCKTON, CA 95212
Owner/Operator Telephone: 209-696-9512
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: LOCH SEAINHAC PANO
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 10141 TIZIANO DR
Owner/Operator City,State,Zip: STOCKTON, CA 95212
Owner/Operator Telephone: 209-696-9512
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2015-12-18 00:00:00.0
Handler Name: DENS AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E51
WNW
1/8-1/4
0.131 mi.
690 ft.

DENS AUTO REPAIR INC
308 S EL DORADO ST
STOCKTON, CA 95203

Site 9 of 10 in cluster E

UST **U004260159**
N/A

Relative:
Lower

Actual:
16 ft.

UST SAN JOAQUIN:

Name:	DENS AUTO REPAIR INC
Address:	308 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0003520
Mail Address:	308 S EL DORADO ST
Mail Address 2:	Not reported
Mail Care of:	DEN'S AUTO REPAIR, INC.
Mail City,St,Zip:	STOCKTON, CA 95203
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	8000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10181197
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	37.9495446700
Longitude:	-121.2888769342
Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	7000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10181197
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	37.9495446700
Longitude:	-121.2888769342
Tank Rec ID:	Not reported
Tank Number:	3
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	5000

DENS AUTO REPAIR INC (Continued) **U004260159**

Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10181197
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	37.9495446700
Longitude:	-121.2888769342

Tank Rec ID:	Not reported
Tank Number:	4
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	500
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10181197
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	37.9495446700
Longitude:	-121.2888769342

E52 **AHTYE BROS** **HIST UST** **U001603263**
WNW **308 SOUTH EL DORADO STREET** **N/A**
1/8-1/4 **STOCKTON, CA 95207**
0.131 mi.
690 ft. **Site 10 of 10 in cluster E**

Relative: HIST UST:
Lower

Name:	AHTYE BROS
Address:	308 SOUTH EL DORADO STREET
City,State,Zip:	STOCKTON, CA 95207
File Number:	0002FBB6
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FBB6.pdf
Region:	STATE
Facility ID:	00000052051
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	SAME FONG
Telephone:	2094662924
Owner Name:	AH TYE BROS.
Owner Address:	308 S. EL DORADO
Owner City,St,Zip:	STOCKTON, CA 95203
Total Tanks:	0004

Actual:
16 ft.

Tank Num:	001
Container Num:	02

AHTYE BROS (Continued) **U001603263**

Year Installed:	1960
Tank Capacity:	00007000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	001
Container Num:	02
Year Installed:	1960
Tank Capacity:	00007000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	002
Container Num:	03
Year Installed:	1960
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	002
Container Num:	03
Year Installed:	1960
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	01
Year Installed:	1960
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	01
Year Installed:	1960
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE

AHTYE BROS (Continued) **U001603263**

Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

G53 **GATEWAY PROJECT** **UST** **U004261028**
WNW **325 S EL DORADO ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.134 mi.
705 ft. **Site 2 of 3 in cluster G**

Relative: UST SAN JOAQUIN:
Lower

Actual:
16 ft.

Name:	GATEWAY PROJECT
Address:	325 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95202
Region:	SJ
Facility Id:	FA0012146
Mail Address:	22 E WEBER AVE ROOM 350
Mail Address 2:	Not reported
Mail Care of:	RON PALMQUIST
Mail City,St,Zip:	STOCKTON, CA 95202
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1000
Product Type Desc:	(none)
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1500
Product Type Desc:	(none)
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete

GATEWAY PROJECT (Continued) **U004261028**

Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

G54 **GATEWAY PROJECT** **LUST** **S104403644**
WNW **325 EL DORADO ST S** **Cortese** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **HIST CORTESE**
0.134 mi. **CERS**
705 ft. **Site 3 of 3 in cluster G**

Relative: **Lower**

Actual: **16 ft.**

LUST:

Name:	GATEWAY PROJECT
Address:	325 EL DORADO ST S
City,State,Zip:	STOCKTON, CA 95203
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700905
Global Id:	T0607700905
Latitude:	37.9495441
Longitude:	-121.2889525
Status:	Completed - Case Closed
Status Date:	06/08/2000
Case Worker:	Not reported
RB Case Number:	391090
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	0000701
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700905
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700905
Action Type:	RESPONSE
Date:	04/18/2000
Action:	Soil and Water Investigation Report

Global Id:	T0607700905
Action Type:	RESPONSE
Date:	06/06/2000
Action:	Other Report / Document

GATEWAY PROJECT (Continued) **S104403644**

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 05/08/2000
Action: Closure Summary

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 07/03/2000
Action: Staff Letter

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 01/11/2000
Action: Notice of Responsibility

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 05/02/2000
Action: Unauthorized Release Form

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 06/07/2000
Action: Closure/No Further Action Letter

Global Id: T0607700905
Action Type: Other
Date: 10/28/1999
Action: Leak Discovery

Global Id: T0607700905
Action Type: Other
Date: 02/04/2000
Action: Leak Reported

Global Id: T0607700905
Action Type: REMEDIATION
Date: 02/04/2000
Action: Not reported

Global Id: T0607700905
Action Type: ENFORCEMENT
Date: 01/11/2000
Action: Notice of Responsibility

LUST:
Global Id: T0607700905
Status: Open - Case Begin Date
Status Date: 10/28/1999

Global Id: T0607700905
Status: Completed - Case Closed
Status Date: 06/08/2000

LUST REG 5:

GATEWAY PROJECT (Continued) **S104403644**

Name: GATEWAY PROJECT
Address: 325 EL DORADO ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 391090
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 1

CORTESE:

Name:	GATEWAY PROJECT
Address:	325 EL DORADO ST S
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700905
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	GATEWAY PROJECT
edr_fadd1:	325 EL DORADO
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	391090

CERS:

Name:	GATEWAY PROJECT
Address:	325 EL DORADO ST S
City,State,Zip:	STOCKTON, CA 95203
Site ID:	193923
CERS ID:	T0607700905
CERS Description:	Leaking Underground Storage Tank Cleanup Site

GATEWAY PROJECT (Continued) **S104403644**

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

H55 **HOUSING AUTHORITY COUNTY OF SAN JOAQUIN** **RCRA NonGen / NLR** **1025838514**
WSW **448 S. CENTER STREET** **CAC003018110**
1/8-1/4 **STOCKTON, CA 95203**
0.168 mi.
886 ft. **Site 1 of 3 in cluster H**

Relative: **Lower**

Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2019-06-04 00:00:00.0
Handler Name:	HOUSING AUTHORITY COUNTY OF SAN JOAQUIN
Handler Address:	448 S. CENTER STREET
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAC003018110
Contact Name:	HOUSING AUTHORITY COUNTY OF SAN JOA
Contact Address:	2575 GRAND CANAL BLVD.
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	209-460-5042
Contact Fax:	Not reported
Contact Email:	GJONES@HACSJ.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	2575 GRAND CANAL BLVD.
Mailing City,State,Zip:	STOCKTON, CA 95203
Owner Name:	HOUSING AUTHORITY COUNTY OF SAN JOA
Owner Type:	Other
Operator Name:	HOUSING AUTHORITY COUNTY OF SAN JOA
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes

HOUSING AUTHORITY COUNTY OF SAN JOAQUIN (Continued) **1025838514**

Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-06-27 14:19:29.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	HOUSING AUTHORITY COUNTY OF SAN JOA
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2575 GRAND CANAL BLVD.
Owner/Operator City,State,Zip:	STOCKTON, CA 95203
Owner/Operator Telephone:	209-460-5042
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

HOUSING AUTHORITY COUNTY OF SAN JOAQUIN (Continued) **1025838514**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: HOUSING AUTHORITY COUNTY OF SAN JOA
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2575 GRAND CANAL BLVD.
Owner/Operator City,State,Zip: STOCKTON, CA 95203
Owner/Operator Telephone: 209-460-5042
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2019-06-04 00:00:00.0
Handler Name: HOUSING AUTHORITY COUNTY OF SAN JOAQUIN
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I56 **PG&E GAS PLANT STOCKTON** **SEMS-ARCHIVE** **1003878926**
SW **CENTER HAZELTON COMMERCE CHURC** **CAD981415862**
1/8-1/4 **STOCKTON, CA 95203**
0.171 mi.
904 ft. **Site 1 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

SEMS Archive:
Site ID: 0902390
EPA ID: CAD981415862
Name: PG&E GAS PLANT STOCKTON
Address: CENTER HAZELTON COMMERCE CHURC
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
Cong District: 14
FIPS Code: 06077
FF: N
NPL: Not on the NPL

PG&E GAS PLANT STOCKTON (Continued) **1003878926**

Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0902390
EPA ID:	CAD981415862
Site Name:	PG&E GAS PLANT STOCKTON
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1996-01-23 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	09
Site ID:	0902390
EPA ID:	CAD981415862
Site Name:	PG&E GAS PLANT STOCKTON
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1987-12-01 05:00:00
Qual:	L
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0902390
EPA ID:	CAD981415862
Site Name:	PG&E GAS PLANT STOCKTON
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	Not reported
Finish Date:	1989-09-08 04:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0902390
EPA ID:	CAD981415862
Site Name:	PG&E GAS PLANT STOCKTON
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

PG&E GAS PLANT STOCKTON (Continued) **1003878926**

Start Date:	1986-07-01 04:00:00
Finish Date:	1986-07-01 04:00:00
Qual:	Not reported
Current Action Lead:	Other

J57 **COMMUNITY FABRICARE** **SWEEPS UST** **S101592738**
SSE **711 S SAN JOAQUIN ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95201**
0.175 mi.
924 ft. **Site 1 of 3 in cluster J**

Relative: **Higher**

Actual: **17 ft.**

SWEEPS UST:

Name:	COMMUNITY FABRICARE
Address:	711 S SAN JOAQUIN ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1245
Number:	Not reported
Board Of Equalization:	44-032226
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001245-000001
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	4

Name:	COMMUNITY FABRICARE
Address:	711 S SAN JOAQUIN ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1245
Number:	Not reported
Board Of Equalization:	44-032226
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001245-000002
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported

Name:	COMMUNITY FABRICARE
Address:	711 S SAN JOAQUIN ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1245

COMMUNITY FABRICARE (Continued) **S101592738**

Number: Not reported
Board Of Equalization: 44-032226
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001245-000003
Tank Status: Not reported
Capacity: 5000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Name: COMMUNITY FABRICARE
Address: 711 S SAN JOAQUIN ST
City: STOCKTON
Status: Not reported
Comp Number: 1245
Number: Not reported
Board Of Equalization: 44-032226
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001245-000004
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000268
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094655788
Mail To: Not reported
Mailing Address: 12609 N WEST LANE
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95201
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

J58 **COMMUNITY FABRICARE INC** **UST** **U004260409**
SSE **711 S SAN JOAQUIN ST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.175 mi.
924 ft. **Site 2 of 3 in cluster J**

Relative:
Higher

Actual:
17 ft.

UST SAN JOAQUIN:

Name:	COMMUNITY FABRICARE INC
Address:	711 S SAN JOAQUIN ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0005000
Mail Address:	1667 W WASHINGTON BLVD
Mail Address 2:	Not reported
Mail Care of:	LOUIS ZIPPERMAN
Mail City,St,Zip:	LOS ANGELES, CA 90007

Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	10000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	5000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	Not reported
Tank Number:	3
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	5000

COMMUNITY FABRICARE INC (Continued) **U004260409**

Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	Not reported
Tank Number:	4
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	2000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

J59 **FABRICARE** **LUST** **S101302815**
SSE **711 SAN JOAQUIN** **Cortese** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **HIST CORTESE**
0.175 mi. **CERS**
924 ft. **Site 3 of 3 in cluster J**

Relative: **Higher**

Actual: **17 ft.**

LUST:

Name:	FABRICARE
Address:	711 SAN JOAQUIN ST S
City,State,Zip:	STOCKTON, CA 95203
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700254
Global Id:	T0607700254
Latitude:	37.946025
Longitude:	-121.285924
Status:	Completed - Case Closed
Status Date:	08/11/1999
Case Worker:	Not reported
RB Case Number:	390340
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	1245
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline

FABRICARE (Continued) **S101302815**

Site History: Not reported

LUST:
Global Id: T0607700254
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700254
Action Type: Other
Date: 02/03/1989
Action: Leak Discovery

Global Id: T0607700254
Action Type: Other
Date: 02/03/1989
Action: Leak Reported

LUST:
Global Id: T0607700254
Status: Open - Case Begin Date
Status Date: 02/03/1989

Global Id: T0607700254
Status: Open - Remediation
Status Date: 02/03/1989

Global Id: T0607700254
Status: Completed - Case Closed
Status Date: 08/11/1999

LUST REG 5:
Name: FABRICARE
Address: 711 SAN JOAQUIN ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390340
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: FABRICARE
Address: 711 SAN JOAQUIN ST S
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE

FABRICARE (Continued) **S101302815**

Envirostor Id:	Not reported
Global ID:	T0607700254
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	FABRICARE
edr_fadd1:	711 SAN JOAQUIN
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390340

CERS:

Name:	FABRICARE
Address:	711 SAN JOAQUIN ST S
City,State,Zip:	STOCKTON, CA 95203
Site ID:	254834
CERS ID:	T0607700254
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

K60 **E.W. AVILA ESTATE** **SWEEPS UST** **S101593132**
ENE **328 S CALIFORNIA ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.176 mi.
930 ft. **Site 1 of 8 in cluster K**

Relative:
Higher

Actual:
17 ft.

SWEEPS UST:

Name:	E.W. AVILA ESTATE
Address:	328 S CALIFORNIA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2258
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002258-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	1

CA FID UST:

Facility ID:	39002622
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2097593588
Mail To:	Not reported
Mailing Address:	18437 E COLLIER RD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95206
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

K61 **E W AVILA ESTATE** **UST** **U004023743**
ENE **328 S CALIFORNIA ST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.176 mi.
930 ft. **Site 2 of 8 in cluster K**

Relative:
Higher

Actual:
17 ft.

UST SAN JOAQUIN:

Name:	E W AVILA ESTATE
Address:	328 S CALIFORNIA ST
City,State,Zip:	STOCKTON, CA 95206
Region:	SJ
Facility Id:	FA0003661
Mail Address:	328 S CALIFORNIA ST

E W AVILA ESTATE (Continued) **U004023743**

Mail Address 2:	Not reported
Mail Care of:	E W AVILA ESTATE
Mail City,St,Zip:	STOCKTON, CA 95206
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

I62 **P G AND E SUBSTATION A** **RCRA-LQG** **1000597714**
WSW **540 SOUTH CENTER** **FINDS** **CAD983617408**
1/8-1/4 **STOCKTON, CA 95203** **ECHO**
0.177 mi.
932 ft. **Site 2 of 12 in cluster I**

Relative: **Higher**

Actual: **17 ft.**

RCRA-LQG:

Date Form Received by Agency:		2018-05-30 00:00:00.0
Handler Name:	P G AND E SUBSTATION A	
Handler Address:		540 SOUTH CENTER
Handler City,State,Zip:		STOCKTON, CA 95203
EPA ID:		CAD983617408
Contact Name:		STEVE DIOSZEGI
Contact Address:		E HIGHWAY 140 (@ N TOWER RD)
Contact City,State,Zip:		MERCED, CA 95340
Contact Telephone:		209-814-4504
Contact Fax:		Not reported
Contact Email:		SLDN@PGE.COM
Contact Title:		ENVIRONMENTAL FIELD SPECIALIST
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PG&E MANIFETSS - PO BOX 7640
Mailing City,State,Zip:		SAN FRANCISCO, CA 94120
Owner Name:		PACIFIC GAS AND ELECTRIC CO
Owner Type:		Private
Operator Name:		PACIFIC GAS & ELECTRIC COMPANY
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No

P G AND E SUBSTATION A (Continued) **1000597714**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-05-30 18:27:05.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D008

P G AND E SUBSTATION A (Continued) **1000597714**

Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PACIFIC GAS & ELECTRIC COMPANY
Legal Status:	Private
Date Became Current:	1905-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94105
Owner/Operator Telephone:	209-814-4504
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	SLDN@PGE.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PACIFIC GAS AND ELECTRIC CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94106
Owner/Operator Telephone:	415-973-7746
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PACIFIC GAS AND ELECTRIC CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94106
Owner/Operator Telephone:	415-973-7746
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PACIFIC GAS AND ELECTRIC CO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94106
Owner/Operator Telephone:	415-973-7746
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2018-02-13 00:00:00.0
Handler Name:	P G AND E SUBSTATION A
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported

P G AND E SUBSTATION A (Continued) **1000597714**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 1992-01-30 00:00:00.0
Handler Name: P G AND E SUBSTATION A
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2018-05-30 00:00:00.0
Handler Name: P G AND E SUBSTATION A
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002867764

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

P G AND E SUBSTATION A (Continued) **1000597714**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000597714
Registry ID:	110002867764
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002867764
Name:	P G AND E SUBSTATION A
Address:	540 SOUTH CENTER
City,State,Zip:	STOCKTON, CA 95203

I63 **PG&E** **RCRA NonGen / NLR** **1026042542**
WSW **540 SOUTH CENTER STREET** **CAC003048730**
1/8-1/4 **STOCKTON, CA 95201**
0.177 mi.
932 ft. **Site 3 of 12 in cluster I**

Relative: **Higher**

Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2019-12-27 00:00:00.0
Handler Name:	PG&E	
Handler Address:		540 SOUTH CENTER STREET
Handler City,State,Zip:		STOCKTON, CA 95201
EPA ID:		CAC003048730
Contact Name:		PG&E CLEARY
Contact Address:		2225 FOLSOM ST
Contact City,State,Zip:		SAN FRANCISCO, CA 94110-2009
Contact Telephone:		800-743-5000
Contact Fax:		Not reported
Contact Email:		BLUEGER@CAL-INC.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		2225 FOLSOM ST
Mailing City,State,Zip:		SAN FRANCISCO, CA 94110-2009
Owner Name:		PG&E CLEARY
Owner Type:		Other
Operator Name:		PG&E CLEARY
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

PG&E (Continued) **1026042542**

Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-02-10 17:51:52.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PG&E CLEARY
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2225 FOLSOM ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94110-2009
Owner/Operator Telephone:	800-743-5000
Owner/Operator Telephone Ext:	Not reported

PG&E (Continued) **1026042542**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PG&E CLEARY
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 2225 FOLSOM ST
Owner/Operator City,State,Zip: SAN FRANCISCO, CA 94110-2009
Owner/Operator Telephone: 800-743-5000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2019-12-27 00:00:00.0
Handler Name: PG&E
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 335311
NAICS Description: POWER, DISTRIBUTION, AND SPECIALTY TRANSFORMER MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I64 **PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS** **RCRA-LQG** **1024744242**
WSW **540 S. CENTER ST.** **CAC002914832**
1/8-1/4 **STOCKTON, CA 95203**
0.177 mi.
932 ft. **Site 4 of 12 in cluster I**

Relative: Higher
Actual: 17 ft.

RCRA-LQG:
Date Form Received by Agency: 2018-02-27 00:00:00.0
Handler Name: PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS
Handler Address: 540 S. CENTER ST.
Handler City,State,Zip: STOCKTON, CA 95203
EPA ID: CAC002914832
Contact Name: STEVE DIOSZEGI
Contact Address: E HIGHWAY 140
Contact City,State,Zip: MERCED, CA 95340
Contact Telephone: 209-814-4504

PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS (Continued) **1024744242**

Contact Fax:	Not reported
Contact Email:	LDN@PGE.COM
Contact Title:	NVIRONMENTAL FIELD SPECIALIST S
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	7640
Mailing City,State,Zip:	SAN FRANCISCO, CA 94120
Owner Name:	PACIFIC GAS AND ELECTRIC COMPANY
Owner Type:	Private
Operator Name:	PACIFIC GAS AND ELECTRIC COMPANY
Operator Type:	Private
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS (Continued) **1024744242**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-11-26 18:57:03.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D004
Waste Description: ARSENIC

Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PACIFIC GAS AND ELECTRIC COMPANY
Legal Status:	Private
Date Became Current:	1906-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94105
Owner/Operator Telephone:	209-323-9617
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	LEAH.UPCHURCH@PGE.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PACIFIC GAS AND ELECTRIC COMPANY
Legal Status:	Private
Date Became Current:	1906-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	77 BEALE ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94105
Owner/Operator Telephone:	209-323-9617
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	LEAH.UPCHURCH@PGE.COM

Historic Generators:

PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS (Continued) **1024744242**

Receive Date:	2018-02-27 00:00:00.0
Handler Name:	PACIFIC GAS & ELECTRIC, STATION A SUB, MANIFESTS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

H65 **PG&E, STOCKTON** **ENVIROSTOR** **S105026763**
WSW **530 CENTER** **VCP** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **DEED**
0.178 mi. **HIST CORTESE**
938 ft. **Site 2 of 3 in cluster H**

Relative: Higher

Actual: 17 ft.

ENVIROSTOR:

Name:	PG&E, STOCKTON
Address:	530 SOUTH CENTER STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39490015
Status:	Certified / Operation & Maintenance
Status Date:	07/14/2007
Site Code:	100190
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	4
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Mera Golo
Supervisor:	Fernando A. Amador
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	YES
Site Mgmt Req:	REM, ASP, FOUN, DAY, ELD, HOS, LUC, MON, EX, GW, OIL, NOWN, NDAM, NUSE, NDEV, NSUB, SCH, FOOD, COV, RES
Funding:	Responsible Party
Latitude:	37.94712
Longitude:	-121.2897

PG&E, STOCKTON (Continued) **S105026763**

APN:	137-32-2-A, 137-32-2-B, 137-32-2-C, 137-32-2-D, 137-32-2-E, 137-32-2-F, 137-32-2-G, 137-32-2-H, 137-32-2-I, 137-32-2-J, 137-32-2-K, 137-32-4-J1
Past Use:	MANUFACTURED GAS PLANT
Potential COC:	Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas TPH-MOTOR OIL
Confirmed COC:	Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas TPH-MOTOR OIL
Potential Description:	OTH, SOIL
Alias Name:	PACIFIC GAS & ELECTRIC - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E / STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E MGP SQ-SK-STK
Alias Type:	Alternate Name
Alias Name:	PG&E PNA SITE - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E PNA SITE/STOCKTON
Alias Type:	Alternate Name
Alias Name:	137-32-2-A
Alias Type:	APN
Alias Name:	137-32-2-B
Alias Type:	APN
Alias Name:	137-32-2-C
Alias Type:	APN
Alias Name:	137-32-2-D
Alias Type:	APN
Alias Name:	137-32-2-E
Alias Type:	APN
Alias Name:	137-32-2-F
Alias Type:	APN
Alias Name:	137-32-2-G
Alias Type:	APN
Alias Name:	137-32-2-H
Alias Type:	APN
Alias Name:	137-32-2-I
Alias Type:	APN
Alias Name:	137-32-2-J
Alias Type:	APN
Alias Name:	137-32-2-K
Alias Type:	APN
Alias Name:	137-32-4-J1
Alias Type:	APN
Alias Name:	CAD981415862
Alias Type:	EPA Identification Number
Alias Name:	110033611410
Alias Type:	EPA (FRS #)
Alias Name:	SL205122996
Alias Type:	GeoTracker Global ID
Alias Name:	P14058
Alias Type:	PCode
Alias Name:	100190
Alias Type:	Project Code (Site Code)
Alias Name:	39490009
Alias Type:	Envirostor ID Number

PG&E, STOCKTON (Continued) **S105026763**

Alias Name: 39490015
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 03/31/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 06/28/1991
Comments: Enforcement Agreement issued.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 09/30/2005
Comments: Installed additional sentry monitoring well to address extent of the groundwater plume.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 06/27/1992
Comments: OFFSL

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 07/10/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 11/13/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/09/1987
Comments: Facility identified by PG&E. Responsible Party Preliminary Assessment (PA) conducted. Sample results: Lead 4600 parts per million (ppm), Polyaromatic Hydrocarbons 260 ppm, Arsenic 42 ppm, Cyanide 19.3 ppm. No cleanup documented.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/07/1987
Comments: Site Screening Done: Environmental Protection Agency completed Screening Site Inspection and recommends Listing Site Inspection. Location Information: Site may be located at 535 South Center Street. Site is located in the block of Hazelton, Center, Church, and

PG&E, STOCKTON (Continued) **S105026763**

Commerce one mile south of downtown Stockton.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/14/2007
Comments: PG&E submitted the 4th quarter of the 2006 Groundwater report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/03/2008
Comments: DTSC received a copy of the Second Quarter 2007 Groundwater Monitoring Report. PG&E will continue to collect groundwater samples quarterly. In 2005, PG&E installed an additional monitoring well because the groundwater plume was moving. PG&E will submit another groundwater report in six months.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 07/08/2008
Comments: DTSC received the 2008 annual groundwater report for the PG&E Stockton site. Recent groundwater results show the groundwater plume is currently stable and is slowly decreasing.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 10/28/2008
Comments: DTSC approved a soil management plan fpr PG&E to install a new pole.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 12/30/2008
Comments: DTSC approved the soil management plan completion report. DTSC approved a soil management plan via email in 2008. The completion report letter documents the work.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 08/05/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/02/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 07/12/2010
Comments: DTSC received notification about repairing a guy wire.

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Operation and Maintenance Report
Completed Date:	08/17/2010
Comments:	DTSC approved the 2010 Groundwater Report. The 2010 groundwater results support the conclusion that the groundwater plume is slowly decreasing through natural attenuation, except for acenaphthene. groundwater concentration does not appear to be decreasing. As noted in the Report on page 13, MW-26R has shown a slight increase in acenaphthene while MR-23R, which is located up-gradient from MW-26R, has shown a decrease in acenaphthene. Both wells have historically been above the groundwater cleanup goal for acenaphthene, which is 20 micrograms per liter listed in the RAP. The acenaphthene groundwater concentration in the up-gradient wells MW-20 and -23R appear to be decreasing while the concentration in well -26R appears to be stagnated or increasing. Since the RAP was approved, new wells have been installed down-gradient to monitor the expanding groundwater plume. The RAP predicted that the groundwater plume would continue to degrade within its original boundaries. In 2006, PG&E installed an additional monitoring well (MW-27) down-gradient to monitor the acenaphthene plume in MW-23 and -26R. This well (MW-27) is located approximately 0.1 miles down-gradient from MW-26R and has never detected acenaphthene. In the next groundwater report, PG&E should assess site conditions relative to the remedial action objectives listed in the RAP (e.g., containment, volume reduction, etc), and discuss what, if any, adjustments may be necessary to achieve the required goals.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	5 Year Review Reports
Completed Date:	06/16/2014
Comments:	DTSC received PG&E response to comments. DTSC concurred with PG&E response and concurred with the 5-year review if PG&E incorporated the changes into the 5-year review report.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Operation and Maintenance Report
Completed Date:	12/01/2010
Comments:	DTSC received and concurred with the report’s conclusions.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/14/2011
Comments:	DTSC and the RWQCB reviewed the assessment of groundwater conditions report and provided comments.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Correspondence - Received
Completed Date:	06/17/2011
Comments:	DTSC received PG&E response to DTSC and the RWQCB comments on the 2011 Groundwater Report. PG&E will submit a workplan to conduct additional investigation.

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 08/08/2011
Comments: DTSC approved the 2011 Annual Groundwater Report. The groundwater plume is currently stablized and slowly decreasing through natural attenuation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 12/06/2011
Comments: DTSC received a work plan to install monitoring wells and collect soil samples from the boreholes.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 06/19/2012
Comments: PG&E installed six new monitoring wells and submitted the first quarter groundwater results. PG&E will collect semi-annual groundwater results from the new wells. DTSC received the groundwater report and did not have any comments.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 05/05/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/16/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 01/31/2012
Comments: DTSC completed a work notice to inform the community about the installation of six new monitoring wells.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/04/2013
Comments: DTSC received the 2012 Annual Ground Water Monitoring Report (Report) dated December 2012 for the Pacific Gas and Electric Company (PG&E) former Manufactured Gas Plant located at 535 Center Street, Stockton, California. The Report was submitted pursuant to the requirements of the PG&E Stockton Operation and Maintenance (O&M) Agreement.The report presents the analytical results for groundwater samples collected in March and September 2012 at the site. The report describes the field sampling activities and analytical results for the annual sampling of 24 monitoring wells and semiannual sampling of nine monitoring wells based on the groundwater monitoring program and

PG&E, STOCKTON (Continued) **S105026763**

sampling frequency decision tree submitted in the O&M Plan and revised in 2004.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 11/14/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 03/04/2014
Comments: DTSC prepared the 5-year reveiw public notice and emailed a copy to the consultant to be published in the local newspaper.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/30/2014
Comments: PG&E placed a public notice in the Stockton newspaper to conclude the 5-year review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 04/30/2015
Comments: DTSC concurred with PG&E updated cost estimate for financial assurance.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 09/19/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/15/2015
Comments: DTSC received the 2014 Groundwater Report which documents the results from the 2014 sampling events.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 06/30/2000
Comments: DTSC received an concurred with the Construction Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Design/Implementation Workplan
Completed Date: 05/19/1999
Comments: DTSC received and concurred with the design workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

PG&E, STOCKTON (Continued) **S105026763**

Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/12/2014
Comments: DTSC received the annual 2014 Land Use and Cap Inspection Report and concurred with the Report's recommendations to seal cracks.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/04/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/28/2017
Comments: DTSC reviewed and concurred with the Annual Groundwater Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/27/2017
Comments: DTSC concurred with the Annual Land Use Covenant Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/15/2017
Comments: DTSC met with the Sacramento Regional Water Quality Control Board, PG&E, and PG&E's consultant to discuss the O&M requirements related to future groundwater events. PG&E prepared minutes notes that are available on the web.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/03/2017
Comments: DTSC, the Sacramento Regional Water Quality Control Board, met with PG&E and their consultant to discuss the status of the PG&E site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 10/06/2017
Comments: DTSC mailed a conditional approval letter on the vapor intrusion work plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/17/2017
Comments: DTSC and the Regional Water Quality Control Board reviewed PG&E proposal to discontinue the groundwater monitoring network and determined that PG&E can not discontinue the groundwater monitoring program at this time. PG&E may reduce the frequency and / or properly destroy some of the monitoring wells.

Completed Area Name: PROJECT WIDE

PG&E, STOCKTON (Continued) **S105026763**

Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 06/23/2005
Comments: ORDER/O&M (ORDER/OPERATION & MAINTENANCE). THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL AND PG&E HAVE ENTERED INTO AN O&M AGREEMENT. PG&E WILL CONTINUE ONGOING MAINTENANCE OF AN ASPHALT CAP AND MONITORING THE GROUNDWATER PLUME.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 02/11/2005
Comments: PG&E RECORDED A DEED RESTRICTION ON THE PG&E STOCKTON SITE LOCATED AT 530 SOUTH CENTER STREET. THE DEED RESTRICTION LIMITS THE LAND USE TO EITHER INDUSTRIAL AND/OR COMMERCIAL USE. THE DEED RESTRICTION PROHIBITS RESIDENTIAL USE AND INSTALLING DRINKING WATER WELLS.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/27/2008
Comments: DTSC approved the land use convenant inspection report. The report indicated that the asphalt cap is in good condition and is effective in controlling exposures.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 06/30/2007
Comments: DTSC certified the PG&E Stockton site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 12/31/2008
Comments: DTSC approved the land use convenant inspection report. The report indicated that the asphalt cap is in good condition and is effective in controlling exposures.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 12/15/2009
Comments: PG&E consultant, Arcadis, submitted a land use inspection report (Report) for the PG&E Stockton site. The cap at the site was in good condition, however; the Report recommended the cleaning and sealing of minor cracks in Parcel B, -G, -J1, and -K and to continue to have Pest Masters monitor and treat re-growth and small vegetation on the parcel.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/18/2012
Comments: DTSC concurred with the recommendations in the 2012 Cap inspection report that maintanence is needed on the asphalt cap.

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/08/2015
Comments: DTSC mailed a letter to PG&E that a financial review findings had been conducted. DTSC did not find any violations.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 12/05/2016
Comments: DTSC prepared and mailed an annual cost estimate to the Responsible Party.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/17/2017
Comments: DTSC Annual Cost Estimate for oversight from July 1, 2017 - June 30, 2018.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/12/2017
Comments: DTSC received PG&E response letter related to ceasing the groundwater monitoring program.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/18/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/29/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Design/Implementation Workplan
Completed Date: 12/17/1998
Comments: DES -- DTSC APPROVED THE REMEDIAL DESIGN AND IMPLEMENTATION PLAN FOR THE REMEDIAL ACTION PRESENTED IN THE APPROVED REMEDIAL ACTION PLAN (1998).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Plan
Completed Date: 03/31/1998
Comments: RAP -- DTSC HAS APPROVED THE FINAL RAP. THE FINAL RAP OUTLINES THE CONCEPTUAL PROCESS FOR REMEDIATION OF SOIL AND GROUNDWATER CONTAMINATION. THE SELECTED REMEDY INVOLVES EXCAVATION OF SOIL TO MEET THE NON-DETECT GOAL AT THE SITE, OF GROUNDWATER IN ZONES A,B, AND C TO ENSURE THAT NATURAL BIODEGRADATION OF COPC'S CONTINUES, AND

PG&E, STOCKTON (Continued) **S105026763**

MAINTAINING CONTROLS TO LIMIT EXPOSURE. SOIL IS TO BE EXCAVATED FROM THREE FORMER MGP STRUCTURE AREAS TO 25 FEET, 24 FEET, AND 8 FEET, RESPECT- IVELY, AS WELL AS EXCAVATION OF SOIL FROM SIX OTHER AREAS ADJACENT TO AREAS OF HIGH COPC CONCENTRATION.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 09/18/2000
Comments: RMDL - The Department approved the completion report which documents completion of remedial activities and identifies the ongoing operation and maintenance activities and land use restrictions that will be required for the subject site. The soil remedy included excavation and off site disposal of 24,020 tons of material contaminated primarily with polycyclic aromatic hydro carbons and to a lesser extent petroleum hydrocarbons. Ongoing maintenance of an asphalt cap will includ periodic inspection and repair. Groundwater will continue to be monitored for evidence of intrinsic bioremediation and for contaminant concentration reduc- tion.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 06/18/1997
Comments: RIFS -- Approval of the feasibility study completed to address PAH impacts to soil and groundwater. Based on the Risk Assess- ment, cleanup of soil is driven primarily by impacts to groundwater and not by exposure to human health. The recommended alternative includes excavacation and removal of targeted soil intervals identified by modeling soils data and intrinsic remediation of a groundwater contaminant plume. The selected alternative includes institutional controls, asphalt batching of hazardous waste contaminanted soil or Class II landfill disposal if not hazardous waste, and continued monitoring of groundwater for contaminants and intrinsic remediation parameters. This alternative includes an enhancement component consisting of introducing oxygen releasing compounds to the watertable and a contingency measure to provide control of the plume if plume expansion is detected.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Participation Plan / Community Relations Plan
Completed Date: 08/14/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 08/16/2006
Comments: DTSC approved the Monitoring Well Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Well Decommissioning Workplan
Completed Date: 04/24/2018
Comments: DTSC reviewed and concurred with the well destruction permit.

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/22/2018
Comments: DTSC received a notification that PG&E was going to collect additional soil gas samples.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Workplan
Completed Date: 08/03/2018
Comments: DTSC concurs with 5-year work plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/06/2018
Comments: DTSC approved a work plan to properly destroy several monitoring wells
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/10/2019
Comments: DTSC concurred with the groundwater report that groundwater concentrations are slowly decreasing through monitored natural attenuation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 01/10/2019
Comments: DTSC concurred with the cap inspection report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 04/22/2019
Comments: A public notice appeared in the local newspaper informing the community about the 5-year review

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 05/14/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 10/09/2019
Comments: Public Notice published on The Record

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/30/2019

PG&E, STOCKTON (Continued) **S105026763**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/22/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/16/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Risk Assessment Report
Completed Date: 12/16/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 01/30/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/27/2020
Comments: Upon completion of activity, RP will submit Well Destruction Completion Report to DTSC

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/11/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Well Decommissioning Report
Completed Date: 08/31/2020
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: PG&E, STOCKTON

PG&E, STOCKTON (Continued) **S105026763**

Address:	530 SOUTH CENTER STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39490015
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	REM, ASP, FOUN, DAY, ELD, HOS, LUC, MON, EX, GW, OIL, NOWN, NDAM, NUSE, NDEV, NSUB, SCH, FOOD, COV, RES
Acres:	4
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Mera Golo
Supervisor:	Fernando A. Amador
Division Branch:	Cleanup Sacramento
Site Code:	100190
Assembly:	13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Certified / Operation & Maintenance
Status Date:	07/14/2007
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.94712 / -121.2897
APN:	137-32-2-A, 137-32-2-B, 137-32-2-C, 137-32-2-D, 137-32-2-E, 137-32-2-F, 137-32-2-G, 137-32-2-H, 137-32-2-I, 137-32-2-J, 137-32-2-K, 137-32-4-J1
Past Use:	MANUFACTURED GAS PLANT
Potential COC:	30019, 30024, 30025, 3002502
Confirmed COC:	30019,30024,30025,3002502
Potential Description:	OTH, SOIL
Alias Name:	PACIFIC GAS & ELECTRIC - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E / STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E MGP SQ-SK-STK
Alias Type:	Alternate Name
Alias Name:	PG&E PNA SITE - STOCKTON
Alias Type:	Alternate Name
Alias Name:	PG&E PNA SITE/STOCKTON
Alias Type:	Alternate Name
Alias Name:	137-32-2-A
Alias Type:	APN
Alias Name:	137-32-2-B
Alias Type:	APN
Alias Name:	137-32-2-C
Alias Type:	APN
Alias Name:	137-32-2-D
Alias Type:	APN
Alias Name:	137-32-2-E
Alias Type:	APN
Alias Name:	137-32-2-F
Alias Type:	APN
Alias Name:	137-32-2-G
Alias Type:	APN

PG&E, STOCKTON (Continued) **S105026763**

Alias Name: 137-32-2-H
Alias Type: APN
Alias Name: 137-32-2-I
Alias Type: APN
Alias Name: 137-32-2-J
Alias Type: APN
Alias Name: 137-32-2-K
Alias Type: APN
Alias Name: 137-32-4-J1
Alias Type: APN
Alias Name: CAD981415862
Alias Type: EPA Identification Number
Alias Name: 110033611410
Alias Type: EPA (FRS #)
Alias Name: SL205122996
Alias Type: GeoTracker Global ID
Alias Name: P14058
Alias Type: PCode
Alias Name: 100190
Alias Type: Project Code (Site Code)
Alias Name: 39490009
Alias Type: Envirostor ID Number
Alias Name: 39490015
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 03/31/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 06/28/1991
Comments: Enforcement Agreement issued.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 09/30/2005
Comments: Installed additional sentry monitoring well to address extent of the groundwater plume.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 06/27/1992
Comments: OFFSL

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 07/10/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE

PG&E, STOCKTON (Continued) **S105026763**

Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 11/13/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/09/1987
Comments: Facility identified by PG&E. Responsible Party Preliminary Assessment (PA) conducted. Sample results: Lead 4600 parts per million (ppm), Polyaromatic Hydrocarbons 260 ppm, Arsenic 42 ppm, Cyanide 19.3 ppm. No cleanup documented.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/07/1987
Comments: Site Screening Done: Environmental Protection Agency completed Screening Site Inspection and recommends Listing Site Inspection. Location Information: Site may be located at 535 South Center Street. Site is located in the block of Hazelton, Center, Church, and Commerce one mile south of downtown Stockton.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/14/2007
Comments: PG&E submitted the 4th quarter of the 2006 Groundwater report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/03/2008
Comments: DTSC received a copy of the Second Quarter 2007 Groundwater Monitoring Report. PG&E will continue to collect groundwater samples quarterly. In 2005, PG&E installed an additional monitoring well because the groundwater plume was moving. PG&E will submit another groundwater report in six months.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 07/08/2008
Comments: DTSC received the 2008 annual groundwater report for the PG&E Stockton site. Recent groundwater results show the groundwater plume is currently stable and is slowly decreasing.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 10/28/2008
Comments: DTSC approved a soil management plan fpr PG&E to install a new pole.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan

PG&E, STOCKTON (Continued) **S105026763**

Completed Date: 12/30/2008
Comments: DTSC approved the soil management plan completion report. DTSC approved a soil management plan via email in 2008. The completion report letter documents the work.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 08/05/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/02/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 07/12/2010
Comments: DTSC received notification about repairing a guy wire.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 08/17/2010
Comments: DTSC approved the 2010 Groundwater Report. The 2010 groundwater results support the conclusion that the groundwater plume is slowly decreasing through natural attenuation, except for acenaphthene. groundwater concentration does not appear to be decreasing. As noted in the Report on page 13, MW-26R has shown a slight increase in acenaphthene while MR-23R, which is located up-gradient from MW-26R, has shown a decrease in acenaphthene. Both wells have historically been above the groundwater cleanup goal for acenaphthene, which is 20 micrograms per liter listed in the RAP. The acenaphthene groundwater concentration in the up-gradient wells MW-20 and -23R appear to be decreasing while the concentration in well -26R appears to be stagnated or increasing. Since the RAP was approved, new wells have been installed down-gradient to monitor the expanding groundwater plume. The RAP predicted that the groundwater plume would continue to degrade within its original boundaries. In 2006, PG&E installed an additional monitoring well (MW-27) down-gradient to monitor the acenaphthene plume in MW-23 and -26R. This well (MW-27) is located approximately 0.1 miles down-gradient from MW-26R and has never detected acenaphthene. In the next groundwater report, PG&E should assess site conditions relative to the remedial action objectives listed in the RAP (e.g., containment, volume reduction, etc), and discuss what, if any, adjustments may be necessary to achieve the required goals.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/16/2014
Comments: DTSC received PG&E response to comments. DTSC concurred with PG&E response and concurred with the 5-year review if PG&E incorporated

PG&E, STOCKTON (Continued) **S105026763**

the changes into the 5-year review report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/01/2010
Comments: DTSC received and concurred with the report's conclusions.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/14/2011
Comments: DTSC and the RWQCB reviewed the assessment of groundwater conditions report and provided comments.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 06/17/2011
Comments: DTSC received PG&E response to DTSC and the RWQCB comments on the 2011 Groundwater Report. PG&E will submit a workplan to conduct additional investigation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 08/08/2011
Comments: DTSC approved the 2011 Annual Groundwater Report. The groundwater plume is currently stablized and slowly decreasing through natural attenuation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 12/06/2011
Comments: DTSC received a work plan to install monitoring wells and collect soil samples from the boreholes.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 06/19/2012
Comments: PG&E installed six new monitoring wells and submitted the first quarter groundwater results. PG&E will collect semi-annual groundwater results from the new wells. DTSC received the groundwater report and did not have any comments.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 05/05/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/16/2011

PG&E, STOCKTON (Continued) **S105026763**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Work Notice
Completed Date: 01/31/2012
Comments: DTSC completed a work notice to inform the community about the installation of six new monitoring wells.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/04/2013
Comments: DTSC received the 2012 Annual Ground Water Monitoring Report (Report) dated December 2012 for the Pacific Gas and Electric Company (PG&E) former Manufactured Gas Plant located at 535 Center Street, Stockton, California. The Report was submitted pursuant to the requirements of the PG&E Stockton Operation and Maintenance (O&M) Agreement.The report presents the analytical results for groundwater samples collected in March and September 2012 at the site. The report describes the field sampling activities and analytical results for the annual sampling of 24 monitoring wells and semiannual sampling of nine monitoring wells based on the groundwater monitoring program and sampling frequency decision tree submitted in the O&M Plan and revised in 2004.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 11/14/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 03/04/2014
Comments: DTSC prepared the 5-year reveiw public notice and emailed a copy to the consultant to be published in the local newspaper.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 06/30/2014
Comments: PG&E placed a public notice in the Stockton newspaper to conclude the 5-year review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 04/30/2015
Comments: DTSC concurred with PG&E updated cost estimate for financial assurance.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 09/19/2019

PG&E, STOCKTON (Continued) **S105026763**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/15/2015
Comments: DTSC received the 2014 Groundwater Report which documents the results from the 2014 sampling events.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 06/30/2000
Comments: DTSC received an concurred with the Construction Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Design/Implementation Workplan
Completed Date: 05/19/1999
Comments: DTSC received and concurred with the design workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/12/2014
Comments: DTSC received the annual 2014 Land Use and Cap Inspection Report and concurred with the Report's recommendations to seal cracks.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/04/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 03/28/2017
Comments: DTSC reviewed and concurred with the Annual Groundwater Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/27/2017
Comments: DTSC concurred with the Annual Land Use Covenant Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/15/2017
Comments: DTSC met with the Sacramento Regional Water Quality Control Board, PG&E, and PG&E's consultant to discuss the O&M requirements related to future groundwater events. PG&E prepared minutes notes that are available on the web.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

PG&E, STOCKTON (Continued) **S105026763**

Completed Document Type: Other Report
Completed Date: 05/03/2017
Comments: DTSC, the Sacramento Regional Water Quality Control Board, met with PG&E and their consultant to discuss the status of the PG&E site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 10/06/2017
Comments: DTSC mailed a conditional approval letter on the vapor intrusion work plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/17/2017
Comments: DTSC and the Regional Water Quality Control Board reviewed PG&E proposal to discontinue the groundwater monitoring network and determined that PG&E can not discontinue the groundwater monitoring program at this time. PG&E may reduce the frequency and / or properly destroy some of the monitoring wells.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 06/23/2005
Comments: ORDER/O&M (ORDER/OPERATION & MAINTENANCE). THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL AND PG&E HAVE ENTERED INTO AN O&M AGREEMENT. PG&E WILL CONTINUE ONGOING MAINTENANCE OF AN ASPHALT CAP AND MONITORING THE GROUNDWATER PLUME.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 02/11/2005
Comments: PG&E RECORDED A DEED RESTRICTION ON THE PG&E STOCKTON SITE LOCATED AT 530 SOUTH CENTER STREET. THE DEED RESTRICTION LIMITS THE LAND USE TO EITHER INDUSTRIAL AND/OR COMMERCIAL USE. THE DEED RESTRICTION PROHIBITS RESIDENTIAL USE AND INSTALLING DRINKING WATER WELLS.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/27/2008
Comments: DTSC approved the land use convenant inspection report. The report indicated that the asphalt cap is in good condition and is effective in controlling exposures.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 06/30/2007
Comments: DTSC certified the PG&E Stockton site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit

PG&E, STOCKTON (Continued) **S105026763**

Completed Date:	12/31/2008
Comments:	DTSC approved the land use convenant inspection report. The report indicated that the asphalt cap is in good condition and is effective in controlling exposures.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction - Site Inspection/Visit
Completed Date:	12/15/2009
Comments:	PG&E consultant, Arcadis, submitted a land use inspection report (Report) for the PG&E Stockton site. The cap at the site was in good condition, however; the Report recommended the cleaning and sealing of minor cracks in Parcel B, -G, -J1, and -K and to continue to have Pest Masters monitor and treat re-growth and small vegetation on the parcel.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	12/18/2012
Comments:	DTSC concurred with the recommendations in the 2012 Cap inspection report that maintanence is needed on the asphalt cap.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	07/08/2015
Comments:	DTSC mailed a letter to PG&E that a financial review findings had been conducted. DTSC did not find any violations.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	12/05/2016
Comments:	DTSC prepared and mailed an annual cost estimate to the Responsible Party.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/17/2017
Comments:	DTSC Annual Cost Estimate for oversight from July 1, 2017 - June 30, 2018.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	12/12/2017
Comments:	DTSC received PG&E response letter related to ceasing the groundwater monitoring program.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/18/2019
Comments:	Not reported

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/29/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Design/Implementation Workplan
Completed Date: 12/17/1998
Comments: DES -- DTSC APPROVED THE REMEDIAL DESIGN AND IMPLEMENTATION PLAN FOR THE REMEDIAL ACTION PRESENTED IN THE APPROVED REMEDIAL ACTION PLAN (1998).

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Plan
Completed Date: 03/31/1998
Comments: RAP -- DTSC HAS APPROVED THE FINAL RAP. THE FINAL RAP OUTLINES THE CONCEPTUAL PROCESS FOR REMEDIATION OF SOIL AND GROUNDWATER CONTAMINATION. THE SELECTED REMEDY INVOLVES EXCAVATION OF SOIL TO MEET THE NON-DETECT GOAL AT THE SITE, OF GROUNDWATER IN ZONES A,B, AND C TO ENSURE THAT NATURAL BIODEGRADATION OF COPC'S CONTINUES, AND MAINTAINING CONTROLS TO LIMIT EXPOSURE. SOIL IS TO BE EXCAVATED FROM THREE FORMER MGP STRUCTURE AREAS TO 25 FEET, 24 FEET, AND 8 FEET, RESPECT- IVELY, AS WELL AS EXCAVATION OF SOIL FROM SIX OTHER AREAS ADJACENT TO AREAS OF HIGH COPC CONCENTRATION.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 09/18/2000
Comments: RMDL - The Department approved the completion report which documents completion of remedial activities and identifies the ongoing operation and maintenance activities and land use restrictions that will be required for the subject site. The soil remedy included excavation and off site disposal of 24,020 tons of material contaminated primarily with polycyclic aromatic hydro carbons and to a lesser extent petroleum hydrocarbons. Ongoing maintenance of an asphalt cap will includ periodic inspection and repair. Groundwater will continue to be monitored for evidence of intrinsic bioremediation and for contaminant concentration reduc- tion.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 06/18/1997
Comments: RIFS -- Approval of the feasibility study completed to address PAH impacts to soil and groundwater. Based on the Risk Assess- ment, cleanup of soil is driven primarily by impacts to groundwater and not by exposure to human health. The recommended alternative includes excavacation and removal of targeted soil intervals identified by modeling soils data and intrinsic remediation of a groundwater contaminant plume. The selected alternative includes institutional controls, asphalt batching of hazardous waste contaminanted soil or Class II landfill disposal if not hazardous waste, and continued monitoring of groundwater for contaminants and intrinsic remediation

PG&E, STOCKTON (Continued) **S105026763**

parameters. This alternative includes an enhancement component consisting of introducing oxygen releasing compounds to the watertable and a contingency measure to provide control of the plume if plume expansion is detected.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Participation Plan / Community Relations Plan
Completed Date: 08/14/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 08/16/2006
Comments: DTSC approved the Monitoring Well Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Well Decommissioning Workplan
Completed Date: 04/24/2018
Comments: DTSC reviewed and concurred with the well destruction permit.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 04/22/2018
Comments: DTSC received a notification that PG&E was going to collect additional soil gas samples.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Workplan
Completed Date: 08/03/2018
Comments: DTSC concurs with 5-year work plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 11/06/2018
Comments: DTSC approved a work plan to properly destroy several monitoring wells Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/10/2019
Comments: DTSC concurred with the groundwater report that groundwater concentrations are slowly decreasing through monitored natural attenuation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 01/10/2019
Comments: DTSC concurred with the cap inspection report.

PG&E, STOCKTON (Continued) **S105026763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 04/22/2019
Comments: A public notice appeared in the local newspaper informing the community about the 5-year review

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 05/14/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 10/09/2019
Comments: Public Notice published on The Record

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation and Maintenance Report
Completed Date: 12/30/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/22/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/16/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Risk Assessment Report
Completed Date: 12/16/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 01/30/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 03/27/2020
Comments: Upon completion of activity, RP will submit Well Destruction Completion Report to DTSC

Completed Area Name: PROJECT WIDE

PG&E, STOCKTON (Continued) **S105026763**

Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/11/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Well Decommissioning Report
Completed Date: 08/31/2020
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

DEED:
Name: PG&E, STOCKTON
Address: 530 SOUTH CENTER STREET
City,State,Zip: STOCKTON, CA 95203
Envirostor ID: 39490015
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED / OPERATION & MAINTENANCE
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

HIST CORTESE:
edr_fname: PG&E, STOCKTON
edr_fadd1: 530 CENTER
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Facility County Code: 39
Reg By: CALSI
Reg Id: 39490015

H66 **PG AND E GAS PLANT STOCKTON** **EDR MGP** **1008407781**
WSW **530 S CENTER ST (IS CENTER OF TWO BLOCK AREA)** **N/A**
1/8-1/4 **STOCKTON, CA 95201**
0.178 mi.
938 ft. **Site 3 of 3 in cluster H**

Relative: **Higher**

Actual: **17 ft.**

Manufactured Gas Plants:

The site was the location of a former gasification plant. Residues and waste from the manufactured gas process were stored and disposed onsite. In addition, petroleum leaked from onsite storage tanks. There are several residents who live near theThe site was the location of a former gasification plant. Residues and waste from the manufactured gas process were stored and disposed onsite. In addition, petroleum leaked from onsite storage tanks.

PG AND E GAS PLANT STOCKTON (Continued) **1008407781**

Contaminants found onsite in soil and groundwatersite.r include polyaromatic hydrocarbons (PAH), total petroleum hydrocarbons (TPH), heavy metals, benzene, toluene, xylene, and ethylene. The contaminants in soil are currently covered by a large paved area used for parking. Residents in the area of the ssite use municipal water. PG AND E completed a preliminary Remedial Investigation (RI) in April 1988 which confirmed the presence of contaminants in soil and groundwater

---

L67 **KEYSTONE AUTOMOTIVE INDUSTRIES INC** **UST** **U004260115**
SSW **632 S EL DORADO ST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.180 mi.
951 ft. **Site 1 of 2 in cluster L**

Relative: UST SAN JOAQUIN:
Higher

Actual: Name: KEYSTONE AUTOMOTIVE INDUSTRIES INC
17 ft. Address: 632 S EL DORADO ST
City,State,Zip: STOCKTON, CA 95203
Region: SJ
Facility Id: FA0002387
Mail Address: 1627 ARMY CT STE 7
Mail Address 2: Not reported
Mail Care of: Not reported
Mail City,St,Zip: STOCKTON, CA 95206-4100

Tank Rec ID: Not reported
Tank Number: 1
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 2000
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: 37.9459400281
Longitude: -121.2873550613

Tank Rec ID: Not reported
Tank Number: 2
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported

KEYSTONE AUTOMOTIVE INDUSTRIES INC (Continued) **U004260115**

Latitude: 37.9459400281
Longitude: -121.2873550613

L68 **STOCKTON PLATING INC** **ENVIROSTOR** **1000173666**
SSW **632 S EL DORADO ST** **LUST** **CAD009212929**
1/8-1/4 **STOCKTON, CA 95203** **SWEEPS UST**
0.180 mi. **HIST UST**
951 ft. **Site 2 of 2 in cluster L** **CA FID UST**
RCRA NonGen / NLR
Relative: **Cortese**
Higher **HAZNET**
Actual: **HIST CORTESE**
17 ft. **WDS**
CIWQS
CERS
HWTS

ENVIROSTOR:
Name: STOCKTON PLATING
Address: 632 SOUTH EL DORADO STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60000493
Status: Inactive - Needs Evaluation
Status Date: 05/10/2007
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 1.8
NPL: NO
Regulatory Agencies: RWQCB 5F - Central Valley, SAN JOAQUIN COUNTY
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Assembly: 13
Senate: 05
Special Program: EPA - PASI
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: EPA Grant
Latitude: 37.94594
Longitude: -121.2872
APN: 14907033
Past Use: MACHINE SHOP, METAL PLATING - OTHER, PAINT/DEPAINT FACILITY, SAND BLASTING
Potential COC: Lead Methyl tertbutyl ether (MTBE Zinc
Confirmed COC: 30013-NO Methyl tertbutyl ether (MTBE 30594-NO
Potential Description: OTH, SOIL
Alias Name: 71002280
Alias Type: Alternate Name
Alias Name: 14907033
Alias Type: APN
Alias Name: 60000493
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Completed Document Type: Site Screening
Completed Date: 06/15/2007
Comments: Site Screening Assessment (SS) completed under DTSC grant with USEPA (PA/SI Grant). Results from SS identified historical small releases at the site, no large releases identified. County Environmental Health is overseeing groundwater remediation from fuel tank releases. USEPA recommendation is No Further Remedial Action Planned (NFRAP). Site is currently being considered for further evaluation by DTSC's Corrective Action program.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Name: STOCKTON PLATING, INC.
Address: 632 S. EL DORADO STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 71002280
Status: Inactive - Needs Evaluation
Status Date: Not reported
Site Code: Not reported
Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Not reported
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.94608
Longitude: -121.2879
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 60000493
Alias Type: Alternate Name
Alias Name: CAD009212929
Alias Type: EPA Identification Number
Alias Name: 71002280
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST:
Name: STOCKTON PLATING INC
Address: 632 EL DORADO ST S
City,State,Zip: STOCKTON, CA 95203
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700077
Global Id: T0607700077
Latitude: 37.94583369
Longitude: -121.2871681
Status: Completed - Case Closed
Status Date: 11/04/2010
Case Worker: Not reported
RB Case Number: 390106
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 1986
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline, MTBE / TBA / Other Fuel Oxygenates
Site History: All USTs removed from this site, soil and ground water investigation completed, remedial action via VE and Pump and Treat, currently conducting post remedial ground water monitoring.

LUST:
Global Id: T0607700077
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 07/08/2003
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 01/21/2010

STOCKTON PLATING INC (Continued) **1000173666**

Action: File review

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 07/19/2010
Action: File review

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 07/07/2008
Action: Staff Letter

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 08/06/2010
Action: Closure/No Further Action Letter

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 11/05/2010
Action: Closure Summary

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 09/08/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 01/31/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700077
Action Type: Other
Date: 08/20/1986
Action: Leak Began

Global Id: T0607700077
Action Type: Other
Date: 01/31/1991
Action: Leak Discovery

Global Id: T0607700077
Action Type: Other
Date: 08/20/1986
Action: Leak Stopped

Global Id: T0607700077
Action Type: Other
Date: 08/20/1986
Action: Leak Reported

Global Id: T0607700077
Action Type: REMEDIATION
Date: 10/31/2007
Action: Pump & Treat (P&T) Groundwater

STOCKTON PLATING INC (Continued) **1000173666**

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 12/12/2008
Action: Site Visit / Inspection / Sampling

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 07/21/2008
Action: Staff Letter - #07/21/2008

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 04/10/2009
Action: File review

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 11/02/2010
Action: Closure/No Further Action Letter

Global Id: T0607700077
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700077
Status: Open - Case Begin Date
Status Date: 08/20/1986

Global Id: T0607700077
Status: Open - Site Assessment
Status Date: 01/31/1991

Global Id: T0607700077
Status: Open - Remediation
Status Date: 10/01/1997

Global Id: T0607700077
Status: Open - Remediation
Status Date: 12/09/2003

Global Id: T0607700077
Status: Completed - Case Closed
Status Date: 11/04/2010

LUST REG 5:
Name: STOCKTON PLATING INC
Address: 632 EL DORADO ST S
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390106
Case Type: Drinking Water Aquifer affected
Substance: Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 5

SWEEPS UST:
Name: STOCKTON PLATING INC
Address: 632 S EL DORADO
City: STOCKTON
Status: Not reported
Comp Number: 1986
Number: Not reported
Board Of Equalization: 44-024951
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001986-000001
Tank Status: Not reported
Capacity: 2000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 2

Name: STOCKTON PLATING INC
Address: 632 S EL DORADO
City: STOCKTON
Status: Not reported
Comp Number: 1986
Number: Not reported
Board Of Equalization: 44-024951
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001986-000002
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

HIST UST:
Name: STOCKTON PLATING INC
Address: 632 SO EL DORADO STREET
City,State,Zip: STOCKTON, CA 95206
File Number: 0002B3F7
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002B3F7.pdf
Region: STATE
Facility ID: 00000014552
Facility Type: Other
Other Type: PLATING FIRM

STOCKTON PLATING INC (Continued) **1000173666**

Contact Name:	ART HOLMAN
Telephone:	2099481101
Owner Name:	STOCKTON PLATING, INC.
Owner Address:	632 SO. EL DORADO STREET
Owner City,St,Zip:	STOCKTON, CA 95206
Total Tanks:	0007
Tank Num:	001
Container Num:	#1
Year Installed:	Not reported
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	002
Container Num:	#2
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	#3
Year Installed:	83
Tank Capacity:	00001875
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	6
Leak Detection:	Visual
Tank Num:	004
Container Num:	#4
Year Installed:	83
Tank Capacity:	00001875
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	6"X6"X6
Leak Detection:	Visual
Tank Num:	005
Container Num:	#5
Year Installed:	83
Tank Capacity:	00001875
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	6
Leak Detection:	Visual
Tank Num:	006
Container Num:	#6
Year Installed:	84
Tank Capacity:	00002000
Tank Used for:	WASTE

STOCKTON PLATING INC (Continued) **1000173666**

Type of Fuel: Not reported
Container Construction Thickness: 6
Leak Detection: Visual

Tank Num: 007
Container Num: #7
Year Installed: 84
Tank Capacity: 00002000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: 6
Leak Detection: Visual

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 39000004
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2099481101
Mail To: Not reported
Mailing Address: 632 S EL DORADO
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95206
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

RCRA NonGen / NLR:
Date Form Received by Agency: 1998-02-09 00:00:00.0
Handler Name: STOCKTON PLATING INC
Handler Address: 632 S EL DORADO ST
Handler City,State,Zip: STOCKTON, CA 95203-3407
EPA ID: CAD009212929
Contact Name: ROBERT E HUNTLEY
Contact Address: 632 S EL DORADO ST
Contact City,State,Zip: STOCKTON, CA 95203-3407
Contact Telephone: 209-948-1101
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 09
Land Type: Other
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Mailing Address:	PO BOX 6096
Mailing City,State,Zip:	STOCKTON, CA 95206
Owner Name:	NICK J SMITH
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:23:19.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

STOCKTON PLATING INC (Continued) **1000173666**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NICK J SMITH
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: STOCKTON PLATING INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1997-01-24 00:00:00.0
Handler Name: STOCKTON PLATING INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Electronic Manifest Broker: Not reported

Receive Date: 1997-01-24 00:00:00.0
Handler Name: STOCKTON PLATING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1998-02-09 00:00:00.0
Handler Name: STOCKTON PLATING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1991-04-03 00:00:00.0
Handler Name: STOCKTON PLATING INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1992-03-25 00:00:00.0
Handler Name: STOCKTON PLATING, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1994-02-17 00:00:00.0
Handler Name: STOCKTON PLATING INC
Federal Waste Generator Description: Large Quantity Generator

STOCKTON PLATING INC (Continued) **1000173666**

State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1996-05-01 00:00:00.0
Handler Name: STOCKTON PLATING INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332813
NAICS Description: ELECTROPLATING, PLATING, POLISHING, ANODIZING, AND COLORING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

CORTESE:
Name: STOCKTON PLATING INC
Address: 632 EL DORADO ST S
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700077
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported

STOCKTON PLATING INC (Continued) **1000173666**

WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HAZNET:
Name: STOCKTON PLATING INC
Address: 632 S EL DORADO ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 952060000
Contact: RICHARD LELAND
Telephone: 2094775405
Mailing Name: Not reported
Mailing Address: 3826 GLENEAGLES DRIVE

Year: 1997
Gepaid: CAD009212929
TSD EPA ID: CAT000613968
CA Waste Code: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: H01 - Transfer Station
Tons: 0.018

Year: 1997
Gepaid: CAD009212929
TSD EPA ID: CA0000084517
CA Waste Code: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: H01 - Transfer Station
Tons: 0.072

Year: 1996
Gepaid: CAD009212929
TSD EPA ID: CAO000084517
CA Waste Code: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: H01 - Transfer Station
Tons: 0.018

Year: 1996
Gepaid: CAD009212929
TSD EPA ID: CA0000084517
CA Waste Code: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
Disposal Method: H01 - Transfer Station
Tons: 0.31

Year: 1996
Gepaid: CAD009212929
TSD EPA ID: NVD980895338
CA Waste Code: 792 - Liquids with pH <= 2 with metals
Disposal Method: -
Tons: 5.004

Year: 1996
Gepaid: CAD009212929
TSD EPA ID: NVD980895338
CA Waste Code: 711 - Liquids with cyanides >= 1,000 Mg./L
Disposal Method: T01 - Treatment, Tank
Tons: 6.2466

STOCKTON PLATING INC (Continued) **1000173666**

Year:	1996
Gepaid:	CAD009212929
TSD EPA ID:	NVD980895338
CA Waste Code:	791 - Liquids with pH <= 2
Disposal Method:	T01 - Treatment, Tank
Tons:	4.1283

Year:	1996
Gepaid:	CAD009212929
TSD EPA ID:	NVD980895338
CA Waste Code:	792 - Liquids with pH <= 2 with metals
Disposal Method:	T01 - Treatment, Tank
Tons:	81.6496

Year:	1996
Gepaid:	CAD009212929
TSD EPA ID:	NVD980895338
CA Waste Code:	726 - Liquids with nickel >= 134 Mg./L
Disposal Method:	T01 - Treatment, Tank
Tons:	2.502

Year:	1996
Gepaid:	CAD009212929
TSD EPA ID:	NVD980895338
CA Waste Code:	792 - Liquids with pH <= 2 with metals
Disposal Method:	R01 - Recycler
Tons:	1.6054

Click this hyperlink while viewing on your computer to access
50 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	1997
Gen EPA ID:	CAD009212929
Shipment Date:	19970505
Creation Date:	7/17/1997 0:00:00
Receipt Date:	19970505
Manifest ID:	96796789
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970401
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970403
Manifest ID:	96635628
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970306
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970310
Manifest ID:	96374567
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970206
Creation Date:	5/30/1997 0:00:00
Receipt Date:	19970210
Manifest ID:	96378564
Trans EPA ID:	ILD984908202
Trans Name:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970115
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970117
Manifest ID:	96360166
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1996
Gen EPA ID:	CAD009212929

Shipment Date:	19961218
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19961219
Manifest ID:	96651638
Trans EPA ID:	CAD982417255
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD009452657
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	F001
Meth Code:	R01 - Recycler
Quantity Tons:	0.2085
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961211
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961216
Manifest ID:	96472660
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961114
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961118
Manifest ID:	96459327
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961017
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961021
Manifest ID:	96460313
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961017
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961021
Manifest ID:	96460313
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960927
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19960927
Manifest ID:	96041935
Trans EPA ID:	CA0000367755

STOCKTON PLATING INC (Continued) **1000173666**

Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	D99 - Disposal, Other
Quantity Tons:	33.712
Waste Quantity:	40
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960923
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19960927
Manifest ID:	96577788
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	791 - Liquids with pH < 2 792 Liquids with pH < 2 with metals
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	4.1283
Waste Quantity:	990
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960923
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19960927
Manifest ID:	96577788
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	792 - Not reported
RCRA Code:	D002

STOCKTON PLATING INC (Continued) **1000173666**

Meth Code:	R01 - Recycler
Quantity Tons:	1.6054
Waste Quantity:	385
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960917
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19960919
Manifest ID:	96513849
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960820
Creation Date:	5/30/1997 0:00:00
Receipt Date:	19960821
Manifest ID:	96503061
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Additional Info:

Year:	1993
Gen EPA ID:	CAD009212929
Shipment Date:	19931229
Creation Date:	9/14/1995 0:00:00
Receipt Date:	19940103
Manifest ID:	92684274
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.6
Waste Quantity:	1200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19931229
Creation Date:	9/14/1995 0:00:00
Receipt Date:	19940103
Manifest ID:	92684274
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.3
Waste Quantity:	600
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19931215
Creation Date:	9/14/1995 0:00:00
Receipt Date:	19931221
Manifest ID:	93024431
Trans EPA ID:	ILD984908202

STOCKTON PLATING INC (Continued) **1000173666**

Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19931116
Creation Date:	9/14/1995 0:00:00
Receipt Date:	19931118
Manifest ID:	93029781
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19931019
Creation Date:	9/13/1995 0:00:00
Receipt Date:	19931021
Manifest ID:	93085609
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005

STOCKTON PLATING INC (Continued) **1000173666**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19930921
Creation Date:	9/12/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	93088302
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	- Not reported
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19930901
Creation Date:	9/11/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	92290616
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	- Not reported
Quantity Tons:	0.675
Waste Quantity:	1350
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Shipment Date:	19930901
Creation Date:	9/11/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	92290616
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	- Not reported
Quantity Tons:	1.2
Waste Quantity:	2400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19930827
Creation Date:	9/12/1995 0:00:00
Receipt Date:	19930902
Manifest ID:	93003726
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19930727
Creation Date:	9/8/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	93220786
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893

STOCKTON PLATING INC (Continued) **1000173666**

Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	- Not reported
Quantity Tons:	0.0135
Waste Quantity:	27
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAD009212929
Shipment Date:	19951214
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951218
Manifest ID:	95818484
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951114
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951120
Manifest ID:	95773065
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005

STOCKTON PLATING INC (Continued) **1000173666**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951106
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951106
Manifest ID:	93635900
Trans EPA ID:	MOD095038998
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	16.856
Waste Quantity:	20
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951018
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951023
Manifest ID:	95754845
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Shipment Date:	19951004
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951004
Manifest ID:	93183173
Trans EPA ID:	MOD095038998
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	D99 - Disposal, Other
Quantity Tons:	16.856
Waste Quantity:	20
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950823
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950828
Manifest ID:	95560695
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950725
Creation Date:	4/3/1996 0:00:00
Receipt Date:	19950731
Manifest ID:	95635027
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950

STOCKTON PLATING INC (Continued) **1000173666**

Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950712
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950712
Manifest ID:	95668680
Trans EPA ID:	MOD095038998
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	D99 - Disposal, Other
Quantity Tons:	16.856
Waste Quantity:	20
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950627
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950628
Manifest ID:	95429064
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P

STOCKTON PLATING INC (Continued) **1000173666**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950531
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950602
Manifest ID:	95417592
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1994
Gen EPA ID:	CAD009212929
Shipment Date:	19941220
Creation Date:	3/28/1996 0:00:00
Receipt Date:	19941220
Manifest ID:	93634186
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	D99 - Disposal, Other
Quantity Tons:	16.856
Waste Quantity:	20
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

STOCKTON PLATING INC (Continued) **1000173666**

Shipment Date:	19941212
Creation Date:	3/28/1996 0:00:00
Receipt Date:	19941214
Manifest ID:	95099923
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19941121
Creation Date:	3/28/1996 0:00:00
Receipt Date:	19941123
Manifest ID:	93765709
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19941111
Creation Date:	3/28/1996 0:00:00
Receipt Date:	19941111
Manifest ID:	93553735
Trans EPA ID:	CAD982417255
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD083166728

STOCKTON PLATING INC (Continued) **1000173666**

Trans Name:	Not reported
TSDF Alt EPA ID:	CAD083166728
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.688
Waste Quantity:	165
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19941028
Creation Date:	3/28/1996 0:00:00
Receipt Date:	19941031
Manifest ID:	93791718
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19940927
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940929
Manifest ID:	93603111
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.75
Waste Quantity:	1500
Quantity Unit:	P

STOCKTON PLATING INC (Continued) **1000173666**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940927
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940929
Manifest ID:	93603111
Trans EPA ID:	ILD099202681
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000646117
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000646117
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	F006
Meth Code:	D99 - Disposal, Other
Quantity Tons:	0.3
Waste Quantity:	600
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940927
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940930
Manifest ID:	95061406
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940825
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940829

STOCKTON PLATING INC (Continued) **1000173666**

Manifest ID:	93457775
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19940801
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940804
Manifest ID:	93654090
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0145
Waste Quantity:	29
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HIST CORTESE:

edr_fname:	STOCKTON PLATING INC
edr_fadd1:	632 EL DORADO
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390106

WDS:

Name:	KEYSTONE AUTOMOTIVE INDINC

STOCKTON PLATING INC (Continued) **1000173666**

Address:	632 S El Dorado St
City:	STOCKTON
Facility ID:	5S 39I013273
Facility Type:	Industrial - Facility that treats and/or disposes of liquid or semisolid wastes from any servicing, producing, manufacturing or processing operation of whatever nature, including mining, gravel washing, geothermal operations, air conditioning, ship building and repairing, oil production, storage and disposal operations, water pumping.
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board
Subregion:	0
Facility Telephone:	2099481101
Facility Contact:	DEL PARKS
Agency Name:	KEYSTONE AUTOMOTIVE IND INC
Agency Address:	632 S El Dorado St
Agency City,St,Zip:	Stockton 952033407
Agency Contact:	ROBERT E HUNTLEY
Agency Telephone:	2099481101
Agency Type:	?
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste Type:	Not reported
Primary Waste:	Not reported
Waste Type2:	Not reported
Waste2:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type:	Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported
POTW:	Not reported
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order should cause a relatively minor impairment of beneficial uses compared to a major or minor threat. Not: All nurds without a TTWQ will be considered a minor threat to water quality unless coded at a higher Level. A Zero (0) may be used to code those NURDS that are found to represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as cooling water dischargers or thosewho must comply through best management practices, facilities with passive waste treatment and disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as dairy waste ponds.

CIWQS:

Name:	STOCKTON PLATING INC
Address:	632 S EL DORADO ST
City,State,Zip:	STOCKTON, CA 95203
Agency:	Stockton Plating Inc
Agency Address:	PO Box 6096, Stockton, CA 95206
Place/Project Type:	Industrial - Electroplating, Plating, Polishing, Anodizing, and Coloring
SIC/NAICS:	3471

STOCKTON PLATING INC (Continued) **1000173666**

Region:	5S
Program:	INDSTW
Regulatory Measure Status:	Terminated
Regulatory Measure Type:	Storm water industrial
Order Number:	2014-0057-DWQ
WDID:	5S39I004380
NPDES Number:	CAS000001
Adoption Date:	01/01/1900
Effective Date:	04/06/1992
Termination Date:	10/31/1997
Expiration/Review Date:	01/01/1900
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	37.94724
Longitude:	-121.28827

CERS:

Name:	STOCKTON PLATING INC
Address:	632 EL DORADO ST S
City,State,Zip:	STOCKTON, CA 95203
Site ID:	240362
CERS ID:	T0607700077
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

HWTS:

Name:	STOCKTON PLATING INC
Address:	632 S EL DORADO ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952060000
EPA ID:	CAD009212929
Inactive Date:	06/30/1998
Create Date:	07/23/1982
Last Act Date:	08/10/2004
Mailing Name:	Not reported
Mailing Address:	3826 GLENEAGLES DRIVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 952191832
Owner Name:	RICHARD LELAND
Owner Address:	3826 GLENEAGLES DRIVE
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA 952191832

STOCKTON PLATING INC (Continued) **1000173666**

Contact Name: RICHARD LELAND
Contact Address: INACTIVE PER VQ98 - BMI
Contact Address 2: Not reported
City,State,Zip: STOCKTON, CA 952191832

NAICS:
EPA ID: CAD009212929
Create Date: 2002-03-14 16:36:26.000
NAICS Code: 332813
NAICS Description: Electroplating, Plating, Polishing, Anodizing, and Coloring
Issued EPA ID Date: 1982-07-23 00:00:00
Inactive Date: 1998-06-30 00:00:00
Facility Name: STOCKTON PLATING INC
Facility Address: 632 S EL DORADO ST
Facility Address 2: Not reported
Facility City: STOCKTON
Facility County: Not reported
Facility State: CA
Facility Zip: 952060000

EPA ID: CAD009212929
Create Date: 2002-03-14 16:36:26.000
NAICS Code: 332813
NAICS Description: Electroplating, Plating, Polishing, Anodizing, and Coloring
Issued EPA ID Date: 1982-07-23 00:00:00
Inactive Date: 1998-06-30 00:00:00
Facility Name: STOCKTON PLATING INC
Facility Address: 632 S EL DORADO ST
Facility Address 2: Not reported
Facility City: STOCKTON
Facility County: Not reported
Facility State: CA
Facility Zip: 952060000

M69 **UNITED #5449** **RCRA NonGen / NLR** **1024849892**
WNW **322 S CENTER ST** **CAL000406980**
1/8-1/4 **STOCKTON, CA 95203**
0.187 mi.
987 ft. **Site 1 of 3 in cluster M**

Relative: **Lower**
Actual: **16 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 2015-05-19 00:00:00.0
Handler Name: UNITED #5449
Handler Address: 322 S CENTER ST
Handler City,State,Zip: STOCKTON, CA 95203
EPA ID: CAL000406980
Contact Name: TOM ROBINS
Contact Address: 4130 COVER STREET
Contact City,State,Zip: LONG BEACH, CA 90808
Contact Telephone: 310-323-3992
Contact Fax: Not reported
Contact Email: TOM.ROBINS@UNITEDPACIFIC.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported

UNITED #5449 (Continued) **1024849892**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	4130 COVER STREET
Mailing City,State,Zip:	LONG BEACH, CA 90808-0000
Owner Name:	APRO LLC
Owner Type:	Other
Operator Name:	TOM ROBINS
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

UNITED #5449 (Continued) **1024849892**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-06 17:06:09.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	APRO LLC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4130 COVER STREET
Owner/Operator City,State,Zip:	LONG BEACH, CA 90808-0000
Owner/Operator Telephone:	310-323-3992
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TOM ROBINS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	4130 COVER STREET
Owner/Operator City,State,Zip:	LONG BEACH, CA 90808
Owner/Operator Telephone:	310-323-3992
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2015-05-19 00:00:00.0
Handler Name: UNITED #5449	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44719
NAICS Description:	OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:

UNITED #5449 (Continued) **1024849892**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

M70 **APRO LLC** **CERS HAZ WASTE** **S107622091**
WNW **322 S CENTER ST** **CERS TANKS** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **EMI**
0.187 mi. **CERS**
987 ft. **Site 2 of 3 in cluster M**

Relative:
Lower

Actual:
16 ft.

CERS HAZ WASTE:
Name: UNITED #5449
Address: 322 S CENTER ST
City,State,Zip: STOCKTON, CA 95203
Site ID: 14402
CERS ID: 10184311
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: UNITED #5449
Address: 322 S CENTER ST
City,State,Zip: STOCKTON, CA 95203
Site ID: 14402
CERS ID: 10184311
CERS Description: Underground Storage Tank

EMI:
Name: STOCKTON GATEWAY, LLC
Address: 322 S. CENTER ST.
City,State,Zip: STOCKTON, CA 95203
Year: 2004
County Code: 39
Air Basin: SJV
Facility ID: 4419
Air District Name: SJU
SIC Code: 5541
Air District Name: SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.362115834
Reactive Organic Gases Tons/Yr: 1.355335118
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: STOCKTON GATEWAY, LLC
Address: 322 S. CENTER ST.
City,State,Zip: STOCKTON, CA 95203
Year: 2005
County Code: 39
Air Basin: SJV
Facility ID: 4419

APRO LLC (Continued) **S107622091**

Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.362115833578193366
Reactive Organic Gases Tons/Yr:	1.3553351175
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	STOCKTON GATEWAY, LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA
Year:	2006
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.261768956262718612
Reactive Organic Gases Tons/Yr:	1.255095
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	STOCKTON GATEWAY, LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2007
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.044813234800197327
Reactive Organic Gases Tons/Yr:	1.0392868364868169
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	STOCKTON GATEWAY, LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2008

APRO LLC (Continued) **S107622091**

County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.9599881581396002179
Reactive Organic Gases Tons/Yr:	.954775612609864
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	STOCKTON GATEWAY, LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2009
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.95998815813960003
Reactive Organic Gases Tons/Yr:	0.95477561260986399
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	STOCKTON GATEWAY, LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2010
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.96002491954542502
Reactive Organic Gases Tons/Yr:	0.95481223800000004
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CONVENIENCE RETAILERS LLC

APRO LLC (Continued) **S107622091**

Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2011
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CONVENIENCE RETAILERS LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2012
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.55645881078
Reactive Organic Gases Tons/Yr:	0.55343734967
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CONVENIENCE RETAILERS LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2013
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.553470784
Reactive Organic Gases Tons/Yr:	0.553470784
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

APRO LLC (Continued) **S107622091**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Name:	APRO LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2014
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.50230192346
Reactive Organic Gases Tons/Yr:	0.50230192346
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	APRO LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2015
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.292996456
Reactive Organic Gases Tons/Yr:	0.292996456
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	APRO LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2016
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.518978384
Reactive Organic Gases Tons/Yr:	0.518978384
Carbon Monoxide Emissions Tons/Yr:	Not reported

APRO LLC (Continued) **S107622091**

NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	APRO LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2017
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.55502607
Reactive Organic Gases Tons/Yr:	0.55502607
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	APRO LLC
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2018
County Code:	39
Air Basin:	SJV
Facility ID:	4419
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.518103034
Reactive Organic Gases Tons/Yr:	0.518103034
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

CERS:

Name:	APRO LLC
Address:	322 S. CENTER ST.
City,State,Zip:	STOCKTON, CA 95203-3401
Site ID:	496399
CERS ID:	110038015929
CERS Description:	US EPA Air Emission Inventory System (EIS)

Name:	UNITED #5449
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	14402

APRO LLC (Continued) **S107622091**

CERS ID: 10184311
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 14402
Site Name: United #5449
Violation Date: 07-19-2017
Citation: 23 CCR 16 2632(d)(1)(C), 2641(h), 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(d)(1)(C), 2641(h), 2711(a)(8)
Violation Description: Failure to submit or update a plot plan.
Violation Notes: Returned to compliance on 07/20/2017. An accurate UST Monitoring Site Plan was not submitted. The locations of the 87 and 91 tanks are incorrectly labeled. In addition, identify that the turbine is located inside a sump for clarity. A site plan must be submitted identifying the locations where monitoring will be performed. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/ and upload a copy of the UST Monitoring Site Plan.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-30-2018
Citation: HSC 6.7 25292.1(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.1(a)
Violation Description: Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills.
Violation Notes: Returned to compliance on 07/18/2019. The fuel filters under the dispensers are not located to allow drips and leaks to drain back into the UDC. The underground storage tank system shall be operated to prevent unauthorized releases. Immediately provide approved secondary containment for the filters under permit and inspection by the EHD.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-29-2015
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description: Failure of the spill bucket to have a minimum capacity of five gallons.
Violation Notes: Returned to compliance on 07/29/2015. The 91 product direct-bury spill container failed when tested. All spill containers shall have a minimum capacity of five gallons and be capable of containing a spill or overfill until it is detected or cleaned up. The technician replaced the drain valve and the spill container was retested and the test passed. This was corrected on site.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449

APRO LLC (Continued) **S107622091**

Violation Date:	10-28-2016
Citation:	19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes:	Returned to compliance on 09/06/2018. The Business Owner/Operator Identification form was not complete. The first and last name of a representative who has full facility access, site familiarity, and authority to make decisions for the business has not been identified. This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	10-28-2016
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 09/20/2018. The site map did not contain a north orientation, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, all hazardous material handling and storage areas and emergency response equipment. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Not reported
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-30-2018
Citation:	HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7,

APRO LLC (Continued) **S107622091**

Section(s) 25284, 25286
Violation Description: Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.
Violation Notes: Returned to compliance on 07/18/2019. UST Tank Information forms for the 87 and 91 tank systems are not current in CERS. The tank forms incorrectly state that the vent lines are single-walled steel pipe and the vapor recovery lines are single-walled fiberglass pipe. Both were observed to be double-walled fiberglass piping. Any change of information must be updated in CERS within 30 days of the changes. Immediately log into CERS, update the required information, and submit for review by the EHD.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-29-2015
Citation: HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Description: Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.
Violation Notes: Returned to compliance on 08/05/2015. The Certificate of Financial Responsibility in CERS is more than 365 days old. Current financial responsibility documents are required to be submitted annually. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, and upload the required documents.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 03-13-2020
Citation: HSC 6.5 25123.3(h) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)
Violation Description: Failure to determine the status of any hazardous waste if a signed copy of the manifest isnG t received within 35 days of the date the waste was accepted by the initial transporter and/or to submit an Exception Report to DTSC if a signed copy of the manifest isnG t received within 60 days of the date the waste was accepted by the initial transporter.
Violation Notes: OBSERVATION: The facility did not have exception reports on site for the following Uniform Hazardous Waste Manifests (UHWM): 020061524JJK (12/15/19). REGULATION GUIDANCE: (a) A generator who does not receive a copy of the manifest with the handwritten signature of the owner or operator of the designated facility within 35 days of the date the waste was accepted by the initial transporter shall contact the transporter and/or the owner or operator of the designated facility to determine the status of the hazardous waste. (c) A hazardous waste generator who does not receive a copy of the manifest with the handwritten signature of the owner or operator of the facility to which the generator's waste is submitted, within 60 days from the date that the hazardous waste was accepted by the initial transporter, shall submit to the department a legible copy of the manifest, with some indication that the generator has not received confirmation of

APRO LLC (Continued) **S107622091**

delivery. (d) Generators shall submit t
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-18-2019
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Description: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.
Violation Notes: The designated operator failed to check and note all required items on the visual inspection reports. -The 7/11/19 inspection report t left blank section VI. -The 04/12/19 inspection report was signed by the owner/operator on 04/15/19, 24 hours late. The owner/operator is expected to sign the designated operator report within 48hours from the date of the report. -The 11/14/18 inspection report was signed by the owner/operator on 11/30/18., 14days late. The owner/operator is expected to sign the designated operator report within 48hours from the date of the report -The 10/20/16 inspection report was signed by the owner/operator on 10/31/18, nine days late. The owner/operator is expected to sign the designated operator report within 48hours from the date of the report During the visual inspection, the designated operator shall check that all required testing and maintenance for the UST system have been completed and shall check all required items on the report. Ensure that desig
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 08-29-2013
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Description: Haz Waste Generator Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 09/04/2014.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449

APRO LLC (Continued) **S107622091**

Violation Date:	03-12-2020
Citation:	23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Description:	For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.
Violation Notes:	OBSERVATION: The designated operator failed to check and note all required items on the visual inspection reports. The incorrect and missing information included the following from the inspection reports: -The DO report of 6/2/2020, did not include the owner/operator name, signature and date signed. REGULATION GUIDANCE: During the visual inspection, the designated operator shall check that all required testing and maintenance for the UST system have been completed and shall check all required items on the report. CORRECTIVE ACTION: Ensure that designated operators performing visual inspections at this facility are including all of the required information on the reports.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	08-29-2013
Citation:	HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description:	UST Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 12/12/2013.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Description:	Failure to properly manage used oil and/or fuel filters in accordance with the requirements.
Violation Notes:	OBSERVATION: This facility generates drained used metal oil filters. A complete three year bill of lading record for used oil filter recycling was not observed during the inspection. No bills of lading were observed. REGULATION GUIDANCE: Persons generating, transporting, or receiving used metal oil filters shall use a bill of lading to record the transfer of used oil filters. Bills of lading must indicate

APRO LLC (Continued) **S107622091**

generator, transporter, and receiving company names, addresses, telephone numbers, the quantity and size of used oil filter containers transferred, and the date of transfer. A copy of each bill of lading must be kept on the premises of the generator, transporter, and receiving facility where the used oil filters were handled. Copies of bills of lading shall be kept for a period of three years. CORRECTIVE ACTION: Immediately obtain all missing bill of lading recycling records that can be found. Used metal oil filters not stored, handled and disposed of according to this sec

Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-20-2016
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description: Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes: Returned to compliance on 03/06/2017. Facilities who generate less than 1000 kg of hazardous waste per month and do not exceed 6000 kg of waste stored on site at any time may store waste on site up to 180 days. A black 55 gallon drum of used absorbent with gasoline labeled as solid waste inside the dumpster area did not have a start date. Since it cannot be determined how long the hazardous waste has been on site, immediately contact a licensed hazardous waste hauler to dispose of this waste under manifest. Submit a copy of the manifest to the EHD within 30 days.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-20-2016
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: Returned to compliance on 03/06/2017. Copies of uniform manifests for the disposal of hazardous waste for July 20, 2013 through December 2015 were not found on site. Hazardous waste generators shall retain copies of all manifests signed off by the disposal facility and all receipts used in a consolidated manifesting procedure on site for three years and have them readily available for review. Immediately locate a copy of all manifests and receipts for the last three years,

APRO LLC (Continued) **S107622091**

	maintain them on site, and submit copies to the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	08-29-2013
Citation:	HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description:	UST Program - Design/Construction - General
Violation Notes:	Returned to compliance on 12/12/2013.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes:	OBSERVATION: The following open hazardous waste storage containers were observed on-site: Two clear plastic bags of used fuel-contaminated absorbent were observed in the hazardous waste storage area and were not sealed shut. REGULATION GUIDANCE: A container holding hazardous waste shall always be closed during transfer and storage, except when it is necessary to add or remove waste. CORRECTIVE ACTION: Immediately close these containers and ensure all hazardous waste containers are closed when not adding or removing waste. Provide a corrective action statement and supporting documentation to the San Joaquin County Environmental Health Department within 30 days.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	08-21-2014
Citation:	HSC 6.7 25291(e) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(e)
Violation Description:	Failure to remove, contain, analyze, and dispose of properly, water removed from the secondary containment by the owner or operator.
Violation Notes:	Returned to compliance on 08/21/2014. Liquid was observed in the 87 and 91 STP sumps. If water could enter into the secondary containment by precipitation or infiltration, it must be removed and disposed of properly. The service technician removed approximately 5 gallons of liquid from the two sumps. Ensure that all sumps and annular spaces are maintained free of liquid. This is a repeat violation, Class II.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST

APRO LLC (Continued) **S107622091**

Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-18-2019
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description:	"Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes:	The 91 product direct bury spill bucket failed when tested. All USTs shall be equipped with a spill container that has a minimum capacity of five gallons and a drain valve that allows drainage of the collected spill into the primary container or provide a means to keep the container empty. Immediately contact a properly licensed, trained, and certified contractor to install an approved spill container under permit and inspection of the EHD. If a spill container canG t be installed immediately, there is a possibility that the 91 UST system may be red tagged to prevent fuel inputs.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-18-2019
Citation:	23 CCR 16 2715(c)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(4)
Violation Description:	Failure to maintain a list of employees trained by the designated operator on-site or off-site at a readily available location, if approved by the UPA. For training that occurs on or after October 1, 2018, failure to maintain a copy of the "Facility Employee Training Certificate" on-site or off-site at a readily available location, if approved by the UPA.
Violation Notes:	The Facility Employee Training Certificate dated 5/12/19 and 7/11/19 did not contain the name of shane Franklin (employee hired on 5/23/19). All site employees must be trained prior to taking responsibility as a facility employee if after October 1, 2018, or within 30 days of hire if prior to October 1, 2018. The Facility Employee Training Certificate shall contain accurate information for all employees trained. Update the Facility Employee Training Certificate to contain the accurate information and submit a copy of the updated form to the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-20-2016

APRO LLC (Continued) **S107622091**

Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 03/06/2017. Containers of hazardous waste not properly labeled: - A black 55 gallon drum of solid waste inside the dumpster area did not have a start accumulation date and no hazardous property. - A black 55 gallon drum of liquid waste inside the dumpster area was labeled as oily water and not gasoline water and it did not have hazardous property listed. All hazardous waste containers shall be marked with the following information: - the words G Hazardous WasteG - name and address of generator - hazardous properties - physical state - composition (contents) - accumulation start date Immediately label these containers and ensure that all hazardous waste containers are marked with all the required information.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	40 CFR 1 262.34(d)(5)(i) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(i)
Violation Description:	Failure to have at least one employee either on the premises or on call (i.e., available to respond to an emergency by reaching the facility within a short period of time) with the responsibility for coordinating all emergency response measures.
Violation Notes:	OBSERVATION: A complete modified contingency plan with an assigned emergency coordinator was not posted at the facility. Neither of the emergency coordinators listed (Solve One and Allen Faass) meet the definition of an emergency coordinator per 22 CCR 66265.55. REGULATION GUIDANCE: The emergency coordinator or his designee must respond to any emergencies that arise. The business operator must post the following information next to telephones or in areas directly involved in the generation and accumulation of hazardous waste: the name and emergency telephone number of the emergency coordinator, the location of fire extinguishers and spill control material, and the telephone number of the fire department unless the facility has a direct alarm. CORRECTIVE ACTION: Immediately post the required information at the facility. Provide a statement to the San Joaquin County Environmental Health Department that the correction is complete.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.

APRO LLC (Continued) **S107622091**

Violation Notes:	Not reported
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Not reported
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-12-2020
Citation:	23 CCR 16 2712(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(f)
Violation Description:	Failure to implement the corrections specified in the inspection report within 30 days of receiving an inspection report from either the UPA or special inspector.
Violation Notes:	OBSERVATION: An inspection was last done on 7/18/2019 and an inspection report was issued identifying information to be submitted to bring this site into compliance. This information was required to be submitted by August 17, 2019. This information has not been received resulting in a non-compliant status for this facility. REGULATION GUIDANCE: An operator that receives an inspection report shall have 30 days to implement the corrections specified in the inspection report and comply with permit conditions. The corrective action shall include all of the recommendations made in the report. The operator shall submit a written response that includes a statement documenting corrective actions taken or proposing corrective actions which will be taken. CORRECTIVE ACTION: Ensure that a written response documenting corrective actions taken or proposed is submitted and all corrections implemented within 30 days of receiving an inspection report.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-20-2016
Citation:	23 CCR 6.7 25284, 25286 - California Code of Regulations, Title 23, Chapter 6.7, Section(s) 25284, 25286
Violation Description:	Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.
Violation Notes:	Returned to compliance on 03/06/2017. UST Tank Information forms for all tanks are not current in CERS. In the section Tank Construction, the Overfill Protection is listed as Ball Float and Fill Tube Shut-Off Valve. The overfill protection is Fill Tube Shut-Off Valve and should be the only overfill listed. Any change of information must be updated

APRO LLC (Continued) **S107622091**

	in CERS within 30 days of the changes. Immediately log into CERS, update the required information, and submit for review by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.
Violation Notes:	Not reported
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-18-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Overfill prevention testing was conducted on 10/25/18. This testing was required to be conducted by October 13, 2018. Ensure all future testing is conducted within required time frames.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449

APRO LLC (Continued) **S107622091**

Violation Date:	07-18-2019
Citation:	23 CCR 16 2712(b)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(2)
Violation Description:	Failure to maintain monitoring records for release detection and/or maintain records of appropriate follow-up actions.
Violation Notes:	Maintenance and monitoring records for the last three years were not found on site. The 2017 and 2016 monitoring certification test results were missing. These records shall be maintained on site for at least three years. Monitoring records include: (1) date and time of all monitoring or sampling; (2) monitoring equipment calibration and maintenance records; (3) results of any visual observations; (4) results of sample analysis performed a lab or in the field; (5) logs of all readings of gauges or other monitoring equipment, ground water elevations, or other test results; (6) results of inventory readings and reconciliations. Immediately locate and maintain all maintenance and monitoring records for the last three years on site and submit copies to the EHD
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-20-2016
Citation:	23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)
Violation Description:	Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.
Violation Notes:	Returned to compliance on 07/20/2016. The sensor in UDC 7-8 was leaning over inside the sump and not located to detect a leak at the earliest opportunity. Monitoring equipment shall be maintained to be able to detect a leak at the earliest possible opportunity. The sensor was relocated to the lowest point of the sump by the service technician. Ensure that all monitoring equipment is maintained to detect a leak at the earliest opportunity.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	08-29-2013
Citation:	HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description:	UST Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 12/12/2013.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste",

APRO LLC (Continued) **S107622091**

	name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	OBSERVATION: Hazardous waste containers were observed on-site with incomplete labeling. The containers were: Two clear plastic bags of used fuel-contaminated absorbent were observed in the hazardous waste storage area with no labeling. REGULATION GUIDANCE: All hazardous waste containers shall be marked with the following information: the words G Hazardous WasteG , name and address of generator, hazardous properties, physical state, composition (contents), accumulation start date CORRECTIVE ACTION: Immediately label the containers as required for hazardous waste. Provide a corrective action statement and supporting documentation to the San Joaquin County Environmental Health Department (EHD) within 30 days.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-30-2018
Citation:	HSC 6.7 25290.1(c),25290.2(c),25291(a)(2),2529.1(e) - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(c),25290.2(c),25291(a)(2),2529.1(e)
Violation Description:	Failure to maintain secondary containment (e.g., failure of secondary containment testing).
Violation Notes:	Returned to compliance on 07/18/2019. The fuel filters under the dispensers are not located to allow drips and leaks to drain back into the UDC. Secondary containment shall be provided for all single-walled UST components. Immediately provide approved secondary containment for the filters under permit and inspection by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-30-2018
Citation:	23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)
Violation Description:	Failure of the double-walled pressurized piping to be continuously monitored with a system that activates an audible and visual alarm or stops flow at the dispenser when a leak is detected.
Violation Notes:	Returned to compliance on 07/30/2018. The 91 STP sump sensor failed to activate an audible and visual alarm when tested to ensure continuous monitoring of the tank system. All monitoring equipment shall be maintained to activate an audible and visual alarm or stop the flow of product at the dispenser when it detects a leak. The sensor was flipped upside down, shaken, and retested during the inspection. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-19-2017

APRO LLC (Continued) **S107622091**

Citation:	HSC 6.7 Multiple - California Health and Safety Code, Chapter 6.7, Section(s) Multiple
Violation Description:	UST Program - Administration/Documentation - General - Must include violation description, proper statute and regulation citation in the "comment" section.
Violation Notes:	Returned to compliance on 07/19/2017. Liquid was observed in the 87 and 91 submersible turbine pump sump. If water could enter into the secondary containment by precipitation or infiltration, it must be removed and disposed of properly. The service technician removed approximately four cups of liquid from the 91 STP sump, and 3 cups of liquid from the 87 STP sump. Ensure that all sumps and annular spaces are maintained free of liquid. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	07-18-2019
Citation:	HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Description:	Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.
Violation Notes:	Financial responsibility documents have not been submitted to the EHD. The most recent financial responsibility documents in CERS are dated 5/23/18. Current financial responsibility documents are required to be submitted annually. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, and upload the required documents.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	14402
Site Name:	United #5449
Violation Date:	03-13-2020
Citation:	40 CFR 1 262.34(d)(5)(ii) - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 262.34(d)(5)(ii)
Violation Description:	Failure to post the following information next to the telephone: (A) The name and telephone number of the emergency coordinator; (B) Location of fire extinguishers and spill control material, and, if present, fire alarm; and (C) The telephone number of the fire department, unless the facility has a direct alarm.
Violation Notes:	OBSERVATION: A complete modified contingency plan was not posted at the facility. The plan posted included outdated and inaccurate information for emergency coordinators, listing Solve One and Allen Faass. Solve One is a call center and Allen Faass is no longer the site contact. REGULATION GUIDANCE: The business operator must post the following information next to telephones or in areas directly involved in the generation and accumulation of hazardous waste: the name and emergency telephone number of the emergency coordinator, the location of fire extinguishers and spill control material, and the telephone number of the fire department unless the facility has a direct alarm. CORRECTIVE ACTION: Immediately post the required information at the facility. Provide a statement to the San Joaquin County Environmental Health Department that the correction is complete.
Violation Division:	San Joaquin County Environmental Health

APRO LLC (Continued) **S107622091**

Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-18-2019
Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)
Violation Description: Failure to have an approved UST Monitoring Plan.
Violation Notes: The monitoring plan is not current and /or not approved by the EHD. Major changes have been made to the previously CERS submittal (06/06/19)and a copy was not available on site during inspection. Ensure a copy is available for inspection at any time.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 03-13-2020
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: OBSERVATION: Designated facility signed copies of Uniform Hazardous Waste Manifest (UHWM) number 020061524JJK (12/15/2019) were not found on-site. REGULATION GUIDANCE: A hazardous waste generator shall keep a copy of each manifest signed in accordance with section 66262.23(a) for three years or until the generator receives a signed copy from the designated facility which received the waste. This signed copy shall be retained as a record for at least three years from the date the waste was accepted by the initial transporter. The hazardous waste generator must submit a copy of the manifest to the California Department of Toxic Substances Control (DTSC) within 60 days if the destination facility signed manifest copy is not received from the transporter or designated facility. CORRECTIVE ACTION: Locate a copy of the destination facility signed manifests and send a copy to the San Joaquin County Environmental Health Department (EHD). If the destination facility signed manifest
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-29-2015
Citation: 23 CCR 16 2712(b) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)
Violation Description: Failure to maintain leak detection alarm logs and/or maintain records of appropriate follow-up actions
Violation Notes: Returned to compliance on 08/20/2015. Maintenance records for two L1 alarms were not found on site. L1 - Fuel alarm - June 10, 2015 L1 - Fuel alarm - December 20, 2014. Maintenance records shall be maintained on site for at least three years. Monitoring records

APRO LLC (Continued) **S107622091**

include: (1) date and time of all monitoring or sampling; (2) monitoring equipment calibration and maintenance records; (3) results of any visual observations; (4) results of sample analysis performed a lab or in the field; (5) logs of all readings of gauges or other monitoring equipment, ground water elevations, or other test results; (6) results of inventory readings and reconciliations. Immediately locate and maintain the service receipts for the alarms noted above and submit copies to the EHD.

Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 14402
Site Name: United #5449
Violation Date: 07-20-2016
Citation: 23 CCR 16 2632, 2634, 2712(b) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2712(b)
Violation Description: Failure to maintain monitoring and maintenance records (e.g., alarm logs) and/or maintain records of appropriate follow-up actions.
Violation Notes: Returned to compliance on 07/20/2016. Liquid was observed in the 87 STP sump on the south west side and in the 91 STP sump on the south west side and north east side. If water could enter into the secondary containment by precipitation or infiltration, it must be removed and disposed of properly. The service technician removed one gallon of liquid from the 87 and 91 STP sump. Ensure that all sumps and annular spaces are maintained free of liquid. This was corrected on site.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-12-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: The monitoring system certification was conducted today, 2/6/2020 and was not witnessed by EHD. Looked inside all sumps and UDCs. Verified sensor locations. Paperwork inspection is still needed. A checklist was provided at the time of inspection. A complete report will be provided at the time of paperwork inspection.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-13-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: An inspection checklist was provided to the facility operator at the time of inspection. The inspector will provide a complete report to the facility operator within the next few weeks. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the complete inspection report. Training with REHS Stacy Rivera
Eval Division: San Joaquin County Environmental Health

APRO LLC (Continued) **S107622091**

Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-13-2020
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by April 12, 2020. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Documents provided during inspection: Return to compliance certification form, corrective action form, aand list of schedule CUPA free classes. Waste streams found: Fuel filters, Fuel contaminated liquids and fuel contaminated solids. Training with REHS Stacy Rivera
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-18-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by August 17, 2019. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Documents provided: Return to Compliance Certification Form, and list of free CUPA classes.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-19-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 8/18/17. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if applicable, can be stored at the facility or uploaded into CERS.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection

APRO LLC (Continued) **S107622091**

Eval Date:	07-20-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	An inspection checklist was provided to the facility operator at the time of inspection. The EHD will provide a complete report to the facility operator within 65 days of the inspection. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the complete inspection report. Notes: - Verified sensors at lowest point
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-20-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	An inspection checklist was provided to the facility operator at the time of inspection. The EHD will provide a complete report to the facility operator within 65 days of the inspection. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the complete inspection report. Notes: - Provided label information
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-29-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by August 31, 2015 .
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-30-2018
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by August 29, 2018. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if

APRO LLC (Continued) **S107622091**

applicable, can be stored at the facility or uploaded into CERS. Documents provided: Return to Compliance Certification form, schedule of free CUPA classes

Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-21-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by September 20, 2014. Consent to perform the inspection, take photos and collect samples was given by Jerry McIntosh, store manager. This facilityG s designated operator is Eva Traylor (ICC expiration date: 4/6/15) . The service technician was Richard Thomas (ICC expiration date: 12/27/14), who had the following manufacturerG s certifications: VR x. 12/9/14, VMI x. 12/17/14. Please be aware that facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Owner/Operator: Written Agreement (if applicable), UST Letter from Chief Financial Officer, and Owner Statement of Designated UST [Truncated]

Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-29-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-29-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-28-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the completed inspection report. Please be aware as of January 1, 2013, all businesses were

APRO LLC (Continued) **S107622091**

required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields. For assistance with CERS, contact Lisa Medina at 209-468-3455.

Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Enforcement Action:
Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 07-19-2017
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 07-20-2016
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HW
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 07-20-2016
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 07-29-2015
Enf Action Type: Notice of Violation (Unified Program)

APRO LLC (Continued) **S107622091**

Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 08-21-2014
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 08-29-2013
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HW
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 08-29-2013
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 14402
Site Name: United #5449
Site Address: 322 S CENTER ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 10-28-2016
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HMRRP
Enf Action Source: CERS

APRO LLC (Continued) **S107622091**

Affiliation:

Affiliation Type Desc:	Identification Signer
Entity Name:	Tom Robins
Entity Title:	Staff Geologist
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Operator
Entity Name:	APRO LLC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(310) 323-3992

Affiliation Type Desc:	Parent Corporation
Entity Name:	APRO LLC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	UST Tank Operator
Entity Name:	APRO LLC
Entity Title:	Not reported
Affiliation Address:	4130 Cover Street
Affiliation City:	Long Beach
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90808
Affiliation Phone:	(310) 323-3992

Affiliation Type Desc:	Document Preparer
Entity Name:	Tom Robins
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Legal Owner
Entity Name:	APRO LLC
Entity Title:	Not reported
Affiliation Address:	4130 Cover Street
Affiliation City:	Long Beach
Affiliation State:	CA

APRO LLC (Continued) **S107622091**

Affiliation Country:	United States
Affiliation Zip:	90808
Affiliation Phone:	(310) 323-3992
Affiliation Type Desc:	UST Tank Owner
Entity Name:	APRO LLC
Entity Title:	Not reported
Affiliation Address:	4130 Cover Street
Affiliation City:	Long Beach
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90808
Affiliation Phone:	(310) 323-3992
Affiliation Type Desc:	Environmental Contact
Entity Name:	Tom Robins
Entity Title:	Not reported
Affiliation Address:	4130 Cover Street
Affiliation City:	Long Beach
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90808
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	4130 Cover Street
Affiliation City:	Long Beach
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90808
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205-6232
Affiliation Phone:	(209) 468-3420
Affiliation Type Desc:	Property Owner
Entity Name:	Sam & joanne Investments Co.
Entity Title:	Not reported
Affiliation Address:	2917 Sea View Pkwy
Affiliation City:	Alameda
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94502
Affiliation Phone:	(510) 586-4542
Affiliation Type Desc:	UST Permit Applicant
Entity Name:	ALLEN FAASS
Entity Title:	CALIFORNIA COMPLIANCE MANAGER

APRO LLC (Continued) **S107622091**

Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(949) 289-5286
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	Sam & Joanne Investment Co,
Entity Title:	Not reported
Affiliation Address:	2917 Sea View Pkwy
Affiliation City:	Alameda
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94512
Affiliation Phone:	(510) 586-4542

M71 **UNITED #5449** **UST** **U004024946**
WNW **322 S CENTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.187 mi.
987 ft. **Site 3 of 3 in cluster M**

Relative: UST:
Lower

Actual:
16 ft.

Name:	UNITED #5449
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	Not reported
Permitting Agency:	San Joaquin County Environmental Health
Latitude:	37.9494
Longitude:	-121.2899
Name:	UNITED #5449
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	Not reported
Permitting Agency:	San Joaquin County Environmental Health
Latitude:	37.9494
Longitude:	-121.2899

UST SAN JOAQUIN:

Name:	UNITED #5449
Address:	322 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0012628
Mail Address:	4130 Cover Street
Mail Address 2:	Not reported
Mail Care of:	APRO LLC
Mail City,St,Zip:	Long Beach, CA 90808
Tank Rec ID:	TA0515543
Tank Number:	1
Tank Status:	01 - Active, billable
Tank Capacity:	20000
Product Type Desc:	1a - REGULAR UNLEADED

UNITED #5449 (Continued) **U004024946**

Program Element: 2361
Decode for Program Element: 2361 - UST FACILITY
Chemical Form: (none)
CAS#: Not reported
CERS ID: 10184311
Cross Ref Tank ID: Not reported
LEA ID: 1
Common Name: Not reported
Date Installed: 4/1/2001
Date of Closure: Not reported
Latitude: 37.9490869581
Longitude: -121.2901285147

Tank Rec ID: TA0515544
Tank Number: 2
Tank Status: 01 - Active, billable
Tank Capacity: 15000
Product Type Desc: 1b - PREMIUM UNLEADED
Program Element: 2361
Decode for Program Element: 2361 - UST FACILITY
Chemical Form: (none)
CAS#: Not reported
CERS ID: 10184311
Cross Ref Tank ID: Not reported
LEA ID: 1
Common Name: Not reported
Date Installed: 4/1/2001
Date of Closure: Not reported
Latitude: 37.9490869581
Longitude: -121.2901285147

K72 **SKIPS SERVICE STATION** **UST** **U004260292**
NE **300 S CALIFORNIA ST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.187 mi.
988 ft. **Site 3 of 8 in cluster K**

Relative: UST SAN JOAQUIN:
Higher
Actual: Name: SKIPS SERVICE STATION
17 ft. Address: 300 S CALIFORNIA ST
City,State,Zip: STOCKTON, CA 95206
Region: SJ
Facility Id: FA0004522
Mail Address: 436 W SCOTTS
Mail Address 2: Not reported
Mail Care of: MICHAEL OLIVAREZ
Mail City,St,Zip: STOCKTON, CA 95208

Tank Rec ID: Not reported
Tank Number: 1
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 3000
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported

SKIPS SERVICE STATION (Continued) **U004260292**

CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 2
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1000
Product Type Desc: 03 - DIESEL
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 3
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 2000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 4
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 6000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported

SKIPS SERVICE STATION (Continued) **U004260292**

CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 5
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 10000
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 6
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 0
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

K73 **SKIPS SERVICE STATION** **HIST UST** **U001603727**
NE **300 S CALIFORNIA ST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.187 mi.
988 ft. **Site 4 of 8 in cluster K**

Relative: HIST UST:
Higher
Name: SKIPS SERVICE STATION
Actual: Address: 300 S CALIFORNIA ST
17 ft. City,State,Zip: STOCKTON, CA 95206
File Number: 0002B37F

SKIPS SERVICE STATION (Continued) **U001603727**

URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002B37F.pdf
Region:	STATE
Facility ID:	00000001407
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	SKIP SMUTS
Telephone:	2094660005
Owner Name:	SKIPS SERVICE STATION
Owner Address:	300 S CALIFORNIA ST
Owner City,St,Zip:	STOCKTON, CA 95206
Total Tanks:	0005
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00003000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	004
Container Num:	4
Year Installed:	1982
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Visual
Tank Num:	005
Container Num:	5
Year Installed:	1982
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Visual

SKIPS SERVICE STATION (Continued) **U001603727**

Click here for Geo Tracker PDF:

K74 **MICHAEL & SHARON OLIVAREZ** **RCRA-LQG** **1016954468**
NE **300 S CALIFORNIA ST** **CAL000328371**
1/8-1/4 **STOCKTON, CA 92503**
0.187 mi.
988 ft. **Site 5 of 8 in cluster K**

Relative: **Higher**
Actual: **17 ft.**

RCRA-LQG:

Date Form Received by Agency:	2014-03-01 00:00:00.0
Handler Name:	MICHAEL & SHARON OLIVAREZ
Handler Address:	300 S CALIFORNIA ST
Handler City,State,Zip:	STOCKTON, CA 92503
EPA ID:	CAL000328371
Contact Name:	SHARON R OLIVAREZ
Contact Address:	W SCOTTS AVE
Contact City,State,Zip:	STOCKTON, CA 92503
Contact Telephone:	209-481-5360
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	OWNER
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	W SCOTTS AVE
Mailing City,State,Zip:	STOCKTON, CA 92503
Owner Name:	MICHAEL & SHARON OLIVAREZ
Owner Type:	Private
Operator Name:	MICHAEL & SHARON OLIVAREZ
Operator Type:	Private
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported

MICHAEL & SHARON OLIVAREZ (Continued) **1016954468**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-11-20 17:13:31.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MICHAEL & SHARON OLIVAREZ
Legal Status:	Private
Date Became Current:	1989-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	540 W SCOTTS AVE
Owner/Operator City,State,Zip:	STOCKTON, CA 92503
Owner/Operator Telephone:	209-481-5360
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MICHAEL & SHARON OLIVAREZ (Continued) **1016954468**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MICHAEL & SHARON OLIVAREZ
Legal Status:	Private
Date Became Current:	1989-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2014-03-01 00:00:00.0
Handler Name:	MICHAEL & SHARON OLIVAREZ
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811198
NAICS Description:	ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

K75 **SKIPS SERVICE STATION** **SWEEPS UST** **S101625617**
NE **300 S CALIFORNIA ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.187 mi.
988 ft. **Site 6 of 8 in cluster K**

Relative:
Higher

Actual:
17 ft.

SWEEPS UST:

Name:	SKIPS SERVICE STATION
Address:	300 S CALIFORNIA ST
City:	STOCKTON
Status:	Active
Comp Number:	1038
Number:	1
Board Of Equalization:	44-024502
Referral Date:	06-30-92
Action Date:	06-30-92
Created Date:	06-29-88
Owner Tank Id:	001
SWRCB Tank Id:	39-000-001038-000001

SKIPS SERVICE STATION (Continued) **S101625617**

Tank Status:	A
Capacity:	3000
Active Date:	06-30-92
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	5
Name:	SKIPS SERVICE STATION
Address:	300 S CALIFORNIA ST
City:	STOCKTON
Status:	Active
Comp Number:	1038
Number:	1
Board Of Equalization:	44-024502
Referral Date:	06-30-92
Action Date:	06-30-92
Created Date:	06-29-88
Owner Tank Id:	002
SWRCB Tank Id:	39-000-001038-000002
Tank Status:	A
Capacity:	1000
Active Date:	06-30-92
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Name:	SKIPS SERVICE STATION
Address:	300 S CALIFORNIA ST
City:	STOCKTON
Status:	Active
Comp Number:	1038
Number:	1
Board Of Equalization:	44-024502
Referral Date:	06-30-92
Action Date:	06-30-92
Created Date:	06-29-88
Owner Tank Id:	003
SWRCB Tank Id:	39-000-001038-000003
Tank Status:	A
Capacity:	2000
Active Date:	06-30-92
Tank Use:	M.V. FUEL
STG:	P
Content:	LEADED
Number Of Tanks:	Not reported
Name:	SKIPS SERVICE STATION
Address:	300 S CALIFORNIA ST
City:	STOCKTON
Status:	Active
Comp Number:	1038
Number:	1
Board Of Equalization:	44-024502
Referral Date:	06-30-92
Action Date:	06-30-92

SKIPS SERVICE STATION (Continued) **S101625617**

Created Date: 06-29-88
Owner Tank Id: 004
SWRCB Tank Id: 39-000-001038-000004
Tank Status: A
Capacity: 6000
Active Date: 06-30-92
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: SKIPS SERVICE STATION
Address: 300 S CALIFORNIA ST
City: STOCKTON
Status: Active
Comp Number: 1038
Number: 1
Board Of Equalization: 44-024502
Referral Date: 06-30-92
Action Date: 06-30-92
Created Date: 06-29-88
Owner Tank Id: 005
SWRCB Tank Id: 39-000-001038-000005
Tank Status: A
Capacity: 10000
Active Date: 06-30-92
Tank Use: M.V. FUEL
STG: P
Content: GASHOL
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000618
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 436 W SCOTTS AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95206
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

K76 **H/S AUTO REPAIR** **LUST** **S101302617**
NE **300 CALIFORNIA** **Cortese** **N/A**
1/8-1/4 **STOCKTON, CA 95206** **HIST CORTESE**
0.188 mi. **CERS**
995 ft. **Site 7 of 8 in cluster K**

Relative: Higher
Actual: 17 ft.

LUST:

Name:	FORMER SKIPS SERVICE STATION (AKA OLIVAREZ PROPERTY)
Address:	300 CALIFORNIA ST S
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700605
Global Id:	T0607700605
Latitude:	37.950517542
Longitude:	-121.28349185
Status:	Open - Site Assessment
Status Date:	01/24/2018
Case Worker:	VJF
RB Case Number:	390772
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Five fuel USTs and one waste oil UST removed November 1992. Laboratory soil data received shows soil impacted with petroleum. The EHD files Notification of Hazardous Waste Discharge on February 26, 1993. Three monitoring wells installed March 1995. Monitoring well water samples contain high concentrations of petroleum. Additional monitoring wells installed from July 1999 to April 2001 and seven CPTs installed from September 1999 to December 2004. Ground water extraction well EW-1 installed August 2002. October 2007 ground water extraction, onsite treatment, and discharge of water to CIty sewer begins. Work plan due for lateral gw plume delineation. CUF payments not received. RP unable to continue GAC change outs or work plan submittal. EHD oks wp due date to November 9, 2009. December 17, 2009: EHD approves work plan revision for offsite MW-10 & MW-11 installs. July 13, 2010: MW-10 & 11 installed offsite. May 5, 2011: EHD denies request to keep GWE offline and directs reactivation of RAP and eval on cost-effectiveness to be submitted.

LUST:

Global Id:	T0607700605
Contact Type:	Regional Board Caseworker
Contact Name:	VERA FISCHER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	vera.fischer@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700605
Action Type:	RESPONSE
Date:	06/27/2001
Action:	Other Report / Document

Global Id: T0607700605

H/S AUTO REPAIR (Continued) **S101302617**

Action Type: RESPONSE
Date: 11/15/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607700605
Action Type: RESPONSE
Date: 07/07/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 11/10/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 07/11/2001
Action: Well Installation Report

Global Id: T0607700605
Action Type: RESPONSE
Date: 01/19/1995
Action: Preliminary Site Assessment Report

Global Id: T0607700605
Action Type: RESPONSE
Date: 05/09/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 11/01/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 10/24/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 08/03/2015
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 09/09/1996
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 01/18/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 08/01/1995

H/S AUTO REPAIR (Continued) **S101302617**

Action: Site Assessment Report

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/17/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 11/17/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700605
Action Type: RESPONSE
Date: 02/26/1997
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 08/02/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/10/2010
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/15/2014
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 05/22/2014
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 05/05/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 04/01/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/01/2015
Action: Staff Letter

H/S AUTO REPAIR (Continued) **S101302617**

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 03/05/2015
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/21/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 10/21/2010
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/29/2015
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/28/2015
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/13/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/19/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/29/2010
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 08/22/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 11/09/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 11/15/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT

H/S AUTO REPAIR (Continued) **S101302617**

Date: 06/29/2018
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 08/21/2017
Action: Email Correspondence

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 04/23/2018
Action: Email Correspondence

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/30/2017
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/24/2018
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/17/2020
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/28/2019
Action: Staff Letter

Global Id: T0607700605
Action Type: RESPONSE
Date: 07/31/2015
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607700605
Action Type: RESPONSE
Date: 10/30/2015
Action: Other Workplan - Regulator Responded

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/29/2011
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/31/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 03/23/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

H/S AUTO REPAIR (Continued) **S101302617**

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/31/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/10/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700605
Action Type: Other
Date: 02/12/1993
Action: Leak Discovery

Global Id: T0607700605
Action Type: Other
Date: 02/26/1993
Action: Leak Reported

Global Id: T0607700605
Action Type: RESPONSE
Date: 05/01/2019
Action: Soil and Water Investigation Workplan - Addendum - Regulator Responded

Global Id: T0607700605
Action Type: RESPONSE
Date: 05/03/2018
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 10/24/2012
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 04/17/2013
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/27/2013
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 10/21/2013
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/22/2013
Action: File review

Global Id: T0607700605
Action Type: RESPONSE

H/S AUTO REPAIR (Continued) **S101302617**

Date: 01/26/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 07/13/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 03/25/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 10/25/1999
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 01/15/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 02/05/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 02/06/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: REMEDIATION
Date: 06/25/2004
Action: Pump & Treat (P&T) Groundwater

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 02/25/2008
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/28/2008
Action: Staff Letter

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/26/2008
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/02/2009
Action: File review

H/S AUTO REPAIR (Continued) **S101302617**

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/28/2008
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 03/05/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 08/03/2007
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/27/2008
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/16/2008
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 01/15/2009
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/18/2008
Action: Site Visit / Inspection / Sampling

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/05/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/05/2012
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 12/04/2013
Action: File review

Global Id: T0607700605
Action Type: RESPONSE
Date: 04/23/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE

H/S AUTO REPAIR (Continued) **S101302617**

Date: 07/30/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 03/14/2001
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 08/14/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 03/30/2001
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 05/25/1995
Action: Preliminary Site Assessment Report

Global Id: T0607700605
Action Type: RESPONSE
Date: 05/17/2000
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 10/30/2015
Action: Electronic Reporting Submittal Due

Global Id: T0607700605
Action Type: RESPONSE
Date: 09/27/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700605
Action Type: RESPONSE
Date: 07/10/2000
Action: Other Report / Document

Global Id: T0607700605
Action Type: RESPONSE
Date: 12/17/1999
Action: Preliminary Site Assessment Report

Global Id: T0607700605
Action Type: RESPONSE
Date: 01/25/1999
Action: Other Report / Document

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 06/01/2007
Action: Notification - Public Notice of ROD/RAP/CAP

H/S AUTO REPAIR (Continued) **S101302617**

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 05/01/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 05/08/2009
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 07/07/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 08/18/2009
Action: File review

Global Id: T0607700605
Action Type: ENFORCEMENT
Date: 09/04/2009
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700605
Status: Open - Case Begin Date
Status Date: 02/12/1993

Global Id: T0607700605
Status: Open - Site Assessment
Status Date: 02/12/1993

Global Id: T0607700605
Status: Open - Site Assessment
Status Date: 03/31/1995

Global Id: T0607700605
Status: Open - Remediation
Status Date: 06/24/2004

Global Id: T0607700605
Status: Open - Remediation
Status Date: 06/25/2004

Global Id: T0607700605
Status: Open - Site Assessment
Status Date: 12/06/2004

Global Id: T0607700605
Status: Open - Remediation
Status Date: 01/01/2009

Global Id: T0607700605
Status: Open - Remediation
Status Date: 03/20/2013

H/S AUTO REPAIR (Continued) **S101302617**

Global Id: T0607700605
Status: Open - Verification Monitoring
Status Date: 06/30/2017

Global Id: T0607700605
Status: Open - Site Assessment
Status Date: 01/24/2018

LUST REG 5:
Name: H/S AUTO REPAIR
Address: 300 CALIFORNIA ST S
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390772
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 4

CORTESE:
Name: FORMER SKIPS SERVICE STATION (AKA OLIVAREZ PROPERTY)
Address: 300 CALIFORNIA ST S
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700605
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - SITE ASSESSMENT
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: H/S AUTO REPAIR
edr_fadd1: 300 CALIFORNIA
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA

H/S AUTO REPAIR (Continued) **S101302617**

Reg Id: 390772

CERS:
Name: FORMER SKIPS SERVICE STATION (AKA OLIVAREZ PROPERTY)
Address: 300 CALIFORNIA ST S
City,State,Zip: STOCKTON, CA 95206
Site ID: 252932
CERS ID: T0607700605
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

K77 **USN COMMUNICATION STATION LANDFILL** **SWF/LF** **S107591770**
ENE **ROUGH AND READY ISLAND** **CERS** **N/A**
1/8-1/4 **STOCKTON, CA 99999**
0.191 mi.
1008 ft. **Site 8 of 8 in cluster K**

Relative:
Higher

Actual:
18 ft.

SWF/LF (SWIS):
Name: USN COMMUNICATION STATION LANDFILL
Address: ROUGH AND READY ISLAND
City,State,Zip: STOCKTON, CA 99999
Region: STATE
Facility ID: 39-AA-0006
SWIS Number: 39-AA-0006
Point of Contact: Aman DeGeorge
Is Archived: No
Is Closed Illegal Abandoned: Yes
Is Site Inert Debris Engineered Fill: No
Is Financial Assurances Responsible: No
Absorbed On: Not reported
Operational Status: Closed
Absorbed By: Not reported
Closed Illegal Abandoned Category: D
EPA Federal Registry ID: Not reported
ARB District: San Joaquin Valley Unified
SWRCB Region: Central Valley
Local Government: Stockton
Reporting Agency Legal Name: City of Stockton
Reporting Agency Department: --
Enforcing Agency Legal Name: Department of Resources Recycling and Recovery
Enforcing Agency Department: Waste Permitting, Compliance and Mitigation Division
Regulation Status: Unpermitted

Activity:
SWIS Number: 39-AA-0006
Site Name: USN Communication Station Landfill
Activity: Solid Waste Disposal Site

USN COMMUNICATION STATION LANDFILL (Continued) **S107591770**

Activity Is Archived:	No
Category:	Disposal
Activity Classification:	Solid Waste Disposal Site
WDR Number:	Not reported
WDR Landfill Class:	Not reported
Cease Operation:	12/31/1981
Cease Operation Type:	Estimated
Inspection Frequency:	None
Throughput:	0
Throughput Units:	Not reported
Remaining Capacity:	0
Remaining Capacity Date:	Not reported
Capacity:	0
Capacity Units:	Not reported
Total Acreage:	0
Disposal Acreage:	0
Permitted Elevation:	0
Permitted Elevation Type:	Not reported
Permitted Depth:	0
Permitted Depth Type:	Not reported
Point of Contact:	Aman DeGeorge
Site Operational Status:	Closed
Site Regulatory Status:	Unpermitted
Site Is Archived:	No
Is Closed Illegal Abandoned:	Yes
Is Site Inert Debris Engineered Fill:	No
Is Financial Assurances Responsible:	No
Absorbed On:	Not reported
Absorbed By:	Not reported
Closed Illegal Abandoned Category:	D
EPA Federal Registry ID:	Not reported
County:	San Joaquin
ARB District:	San Joaquin Valley Unified
SWRCB Region:	Central Valley
Local Government:	Stockton
Street Address:	Rough And Ready Island
City:	Stockton
State:	CA
ZIP Code:	99999
Reporting Agency Legal Name:	City of Stockton
Reporting Agency Department:	--
Enforcing Agency Legal Name:	Department of Resources Recycling and Recovery
Enforcing Agency Department:	Waste Permitting, Compliance and Mitigation Division

Owner:

SWIS Number:	39-AA-0006
Owner:	US Dept Of Navy-Stockton
Owner Address:	Naval Communications Station
Owner City:	Stockton
Owner State:	CA
Owner Zip:	95203
Site Name:	USN Communication Station Landfill
Site Operational Status:	Closed
Site Type:	Disposal Only
Site Regulatory Status:	Unpermitted
Latitude:	37.95
Longitude:	-121.28333

USN COMMUNICATION STATION LANDFILL (Continued) **S107591770**

Is Archived:	No
Started On:	8/16/1994
Contact Name:	Dennis Field
Contact Title:	Environmental Technician
Contact Email:	Not reported
Contact Phone:	(209) 944-0244

CERS:

Name:	USN COMMUNICATION STATION LANDFILL
Address:	ROUGH AND READY ISLAND
City,State,Zip:	STOCKTON, CA
Site ID:	512710
CERS ID:	39-AA-0006
CERS Description:	Solid Waste and Recycle Sites

Affiliation:

Affiliation Type Desc:	Legal Owner
Entity Name:	US Dept Of Navy-Stockton
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95203
Affiliation Phone:	2099440244

78
East
1/8-1/4
0.196 mi.
1037 ft.

Relative:
Higher

Actual:
17 ft.

ALEX G. SPANOS ELEMENTARY SCHOOL **ENVIROSTOR** **S106153076**
EAST CHURCH STREET/AMERICAN STREET **SCH** **N/A**
STOCKTON, CA 95203

ENVIROSTOR:

Name:	ALEX G. SPANOS ELEMENTARY SCHOOL
Address:	EAST CHURCH STREET/AMERICAN STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39390001
Status:	Certified
Status Date:	09/20/2007
Site Code:	104379
Site Type:	School Cleanup
Site Type Detailed:	School
Acres:	2.1
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Jose Luevano
Supervisor:	Mark Malinowski
Division Branch:	Northern California Schools & Santa Susana
Assembly:	13
Senate:	05
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	37.94834

ALEX G. SPANOS ELEMENTARY SCHOOL (Continued) **S106153076**

Longitude: -121.2825
APN: NONE SPECIFIED
Past Use: RESIDENTIAL AREA
Potential COC: Arsenic Lead Methyl tertbutyl ether (MTBE Polychlorinated biphenyls (PCBs Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas TPH-MOTOR OIL Barium and compounds Chromium III Copper and compounds Mercury and compounds Nickel Zinc
Confirmed COC: Polychlorinated biphenyls (PCBs Polynuclear aromatic hydrocarbons (PAHs 30024-NO 30025-NO 30067-NO 30152-NO 30156-NO Mercury and compounds 30407-NO Arsenic Lead 30016-NO TPH-MOTOR OIL 30594-NO
Potential Description: SOIL
Alias Name: ALEX G. SPANOS ELEMENTARY SCHOOL
Alias Type: Alternate Name
Alias Name: STOCKTON UNIFIED SCHOOL DISTRICT
Alias Type: Alternate Name
Alias Name: STOCKTON USD-PROPOSED ALEX G SPANOS
Alias Type: Alternate Name
Alias Name: 110033614097
Alias Type: EPA (FRS #)
Alias Name: 104379
Alias Type: Project Code (Site Code)
Alias Name: 39390001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 06/19/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 03/16/2006
Comments: The revised PEA Workplan adequately addresses DTSC’s comments and is hereby approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 07/11/2006
Comments: DTSC approved the PEA Report with a further action required determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 11/28/2006
Comments: RAW approved by DTSC to remove approximately 6,000 cubic yards of soil impacted by lead, arsenic, mercury, PCBs and polyaromatic hydrocarbons.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 10/20/2006
Comments: Fact Sheet for the Proposed AG Spanos Elementary School site has been

ALEX G. SPANOS ELEMENTARY SCHOOL (Continued) **S106153076**

finalized and translated into Spanish.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 4.15 Request
Completed Date: 06/25/2007
Comments: DTSC approved the SFPD Form 4.15 and committed to completing a removal action with the District.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 09/20/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 11/27/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/18/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 09/21/2007
Comments: DTSC signed a site certification package.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 12/04/2003
Comments: DTSC entered into an Environmental Oversight Agreement (Docket Number HSA-A 03/04-067) with the Stockton Unified School District to provide oversight for a Preliminary Endangerment Assessment for the proposed Alex G. Spanos Elementary School.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 02/01/2008
Comments: CRU Memo approved.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ALEX G. SPANOS ELEMENTARY SCHOOL (Continued) **S106153076**

SCH:

Name:	ALEX G. SPANOS ELEMENTARY SCHOOL
Address:	EAST CHURCH STREET/AMERICAN STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39390001
Site Type:	School Cleanup
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	2.1
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Jose Luevano
Supervisor:	Mark Malinowski
Division Branch:	Northern California Schools & Santa Susana
Site Code:	104379
Assembly:	13
Senate:	05
Special Program Status:	Not reported
Status:	Certified
Status Date:	09/20/2007
Restricted Use:	NO
Funding:	School District
Latitude:	37.94834
Longitude:	-121.2825
APN:	NONE SPECIFIED
Past Use:	RESIDENTIAL AREA
Potential COC:	Arsenic, Lead, Methyl tertbutyl ether (MTBE, Polychlorinated biphenyls (PCBs, Polynuclear aromatic hydrocarbons (PAHs, TPH-diesel, TPH-gas, TPH-MOTOR OIL, Barium and compounds, Chromium III, Copper and compounds, Mercury and compounds, Nickel, Zinc
Confirmed COC:	Polychlorinated biphenyls (PCBs, Polynuclear aromatic hydrocarbons (PAHs, 30024-NO, 30025-NO, 30067-NO, 30152-NO, 30156-NO, Mercury and compounds, 30407-NO, Arsenic, Lead, 30016-NO, TPH-MOTOR OIL, 30594-NO
Potential Description:	SOIL
Alias Name:	ALEX G. SPANOS ELEMENTARY SCHOOL
Alias Type:	Alternate Name
Alias Name:	STOCKTON UNIFIED SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	STOCKTON USD-PROPOSED ALEX G SPANOS
Alias Type:	Alternate Name
Alias Name:	110033614097
Alias Type:	EPA (FRS #)
Alias Name:	104379
Alias Type:	Project Code (Site Code)
Alias Name:	39390001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	06/19/2006
Comments:	Not reported

ALEX G. SPANOS ELEMENTARY SCHOOL (Continued) **S106153076**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 03/16/2006
Comments: The revised PEA Workplan adequately addresses DTSC's comments and is hereby approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 07/11/2006
Comments: DTSC approved the PEA Report with a further action required determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 11/28/2006
Comments: RAW approved by DTSC to remove approximately 6,000 cubic yards of soil impacted by lead, arsenic, mercury, PCBs and polyaromatic hydrocarbons.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 10/20/2006
Comments: Fact Sheet for the Proposed AG Spanos Elementary School site has been finalized and translated into Spanish.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 4.15 Request
Completed Date: 06/25/2007
Comments: DTSC approved the SFPD Form 4.15 and committed to completing a removal action with the District.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 09/20/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 11/27/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 02/18/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification

ALEX G. SPANOS ELEMENTARY SCHOOL (Continued) **S106153076**

Completed Date:	09/21/2007
Comments:	DTSC signed a site certification package.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	12/04/2003
Comments:	DTSC entered into an Environmental Oversight Agreement (Docket Number HSA-A 03/04-067) with the Stockton Unified School District to provide oversight for a Preliminary Endangerment Assessment for the proposed Alex G. Spanos Elementary School.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	02/01/2008
Comments:	CRU Memo approved.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

I79 **P G & E - GAS LOAD CENTER** **SWEEPS UST** **S101592732**
WSW **535 S CENTER** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.200 mi.
1058 ft. **Site 5 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

SWEEPS UST:

Name:	P G & E - GAS LOAD CENTER
Address:	535 S CENTER
City:	STOCKTON
Status:	Not reported
Comp Number:	1043
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001043-000001
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	2
Name:	P G & E - GAS LOAD CENTER
Address:	535 S CENTER
City:	STOCKTON

P G & E - GAS LOAD CENTER (Continued) **S101592732**

Status:	Not reported
Comp Number:	1043
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001043-000002
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

CA FID UST:

Facility ID:	39000256
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2094435568
Mail To:	Not reported
Mailing Address:	P O BOX 930
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95202
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

I80 **PG&E: STOCKTON GAS PLANT** **CERS HAZ WASTE** **S121745116**
WSW **535 S CENTER ST** **CERS** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.200 mi.
1058 ft. **Site 6 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

CERS HAZ WASTE:

Name:	PG&E: STOCKTON GAS PLANT
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	143517
CERS ID:	10148343
CERS Description:	Hazardous Waste Generator

CERS:

Name:	PG&E: STOCKTON GAS PLANT
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	143517
CERS ID:	10148343
CERS Description:	Chemical Storage Facilities

PG&E: STOCKTON GAS PLANT (Continued) **S121745116**

Violations:

Site ID:	143517
Site Name:	PG&E: Stockton Gas Plant
Violation Date:	05-20-2020
Citation:	40 CFR 1 265.33 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.33
Violation Description:	Failure to test and maintain as necessary all facility communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment to assure its proper operation in time of emergency.
Violation Notes:	Returned to compliance on 06/18/2020. OBSERVATION: The eyewash next to the hazardous waste storage area did not produce a flow of water when tested. The water reservoir was approximately 10% full. The water contained sediment. REGULATION GUIDANCE: All facility communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment, where required, shall be tested and maintained as necessary to assure its proper operation in time of emergency. CORRECTIVE ACTION: Bring the eyewash iinto proper working order by repair or replacement. Provide a corrective action statement to the San Joaquin County Environmental Health Department within 30 days.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Site ID:	143517
Site Name:	PG&E: Stockton Gas Plant
Violation Date:	12-05-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 01/03/2018. The Hazardous Materials Inventory form for the odorant was not complete/accurate. The containers of odorant were labeled G Mercaptans, liquid, flammable, n.o.s., UN3336G vs. G FLAMMABLE LIQUID, N.O.S." This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	143517
Site Name:	PG&E: Stockton Gas Plant
Violation Date:	12-05-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 01/03/2018. The site map did not show the storage/handling location of the mercaptans UN3336 and the NDK steam cleaning detergent; the site map still shows the spill control and the T&R storage containers that have been removed; codes (2) and (5) are not included in the map legend. A site map shall contain a north

PG&E: STOCKTON GAS PLANT (Continued) **S121745116**

orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 143517
Site Name: PG&E: Stockton Gas Plant
Violation Date: 05-20-2020
Citation: 22 CCR 12 66262.40(c) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(c)
Violation Description: Failure to keep records of any test results, waste analyses, or other determinations made in accordance with section 66262.11 for at least three years from the date that the waste was last sent to on-site or off-site treatment, storage, or disposal.
Violation Notes: Returned to compliance on 06/18/2020. OBSERVATION: Sand blast media waste is being disposed of as non-hazardous waste. The business operator does not have hazardous waste determination records that support the current handling and disposal of the waste. REGULATION GUIDANCE: A business operator shall keep records of any hazardous waste determinations made in accordance with Title 22 California Code of Regulations (CCR) section 66262.11 for at least three years from the date that the waste was last sent to an on-site or off-site treatment, storage, or disposal facility. The records may include Safety Data Sheets (SDS), waste test results or other hazardous waste determination documentation. CORRECTIVE ACTION: Assemble the hazardous waste determination documentation for the sand blast media waste, maintain on site and submit a copy to the San Joaquin County Environmental Health Department (EHD).
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-20-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by June 20, 2020. To minimize person to person contact EHD is choosing to write the name of person receiving the report instead of having them sign. Hazardous waste streams found: oil, oily solids, paint, gasoline, lead contaminated solids, waste corrosive liquids, adhesives. Universal waste streams found: aerosols, lithium metal batteries, lead acid batteries, electronic devices Nonhazardous waste streams found: nonfriable asbestos, sandblast media
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

PG&E: STOCKTON GAS PLANT (Continued) **S121745116**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	12-05-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	An inspection report was provided to the Emergency Coordinator on the day of inspection. The report was amended by the EHD. This amended report replaces the initial report. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the amended inspection report. Note, the copy of the Hazardous Materials Business Plan maintained at the facility and presented at the time of inspection was not updated with the current CERS submittal and did not include the odorant, mercaptan. The current CERS submittal does contain the odorant; however the chemical name and common name identified in the CERS submittal are not accurate. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting [Truncated]
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS

Enforcement Action:

Site ID:	143517
Site Name:	PG&E: Stockton Gas Plant
Site Address:	535 S CENTER ST
Site City:	STOCKTON
Site Zip:	95203
Enf Action Date:	12-05-2017
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	HMRRP
Enf Action Source:	CERS

Coordinates:

Site ID:	143517
Facility Name:	PG&E: Stockton Gas Plant
Env Int Type Code:	HWG
Program ID:	10148343
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	37.947000
Longitude:	-121.290270

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	Alex Steele
Entity Title:	Not reported
Affiliation Address:	1108 Murphy Grade Road
Affiliation City:	Angels Camp
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95222

PG&E: STOCKTON GAS PLANT (Continued) **S121745116**

Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: Pacific Gas and Electric Company
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (209) 406-7926

Affiliation Type Desc: Identification Signer
Entity Name: Daniel Sanchez
Entity Title: Hazardous Materials & Water Quality Manager
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: PG&E
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District
Entity Name: San Joaquin Cnty Env Health
Entity Title: Not reported
Affiliation Address: 1868 East Hazelton Avenue
Affiliation City: Stockton
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95205-6232
Affiliation Phone: (209) 468-3420

Affiliation Type Desc: Document Preparer
Entity Name: Liza Marfori, Parsons
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO Box 7640
Affiliation City: San Francisco

PG&E: STOCKTON GAS PLANT (Continued) **S121745116**

Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94120
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Pacific Gas and Electric Company
Entity Title:	Not reported
Affiliation Address:	c/o Environmental Services, 3401, Crow Canyon Road
Affiliation City:	San Ramon
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(415) 973-7000

I81 **PG&E STOCKTON GAS PLANT** **AST** **A100338331**
WSW **535 S CENTER** **N/A**
1/8-1/4 **STOCKTON, CA**
0.200 mi.
1058 ft. **Site 7 of 12 in cluster I**

Relative: **Higher**

Actual: **17 ft.**

AST:

Name:	PG&E STOCKTON GAS PLANT
Address:	535 S CENTER
City/Zip:	STOCKTON,
Certified Unified Program Agencies:	San Joaquin
Owner:	PACIFIC GAS & ELECTRIC COMPANY
Total Gallons:	2,000
CERSID:	Not reported
Facility ID:	Not reported
Business Name:	Not reported
Phone:	Not reported
Fax:	Not reported
Mailing Address:	Not reported
Mailing Address City:	Not reported
Mailing Address State:	Not reported
Mailing Address Zip Code:	Not reported
Operator Name:	Not reported
Operator Phone:	Not reported
Owner Phone:	Not reported
Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	Not reported

I82 **PG&E: STOCKTON GAS PLANT** **RCRA-LQG** **1000198856**
WSW **535 S CENTER ST** **US FIN ASSUR** **CAD980886873**
1/8-1/4 **STOCKTON, CA 95203** **FINDS**
0.200 mi.
1058 ft. **Site 8 of 12 in cluster I**

Relative: **Higher**
Actual: **17 ft.**

RCRA-LQG:

Date Form Received by Agency:	1985-08-15 00:00:00.0
Handler Name:	PG&E STOCKTON GAS LOAD CTR
Handler Address:	535 S CENTER
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAD980886873
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	535 S CENTER
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	209-487-7094
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Other
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	1
Mailing Address:	1401 FULTON ST
Mailing City,State,Zip:	FRESNO, CA 93760
Owner Name:	NOT REQUIRED
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

PG&E: STOCKTON GAS PLANT (Continued) **1000198856**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:22:57.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1985-08-15 00:00:00.0
Handler Name:	PG&E STOCKTON GAS LOAD CTR
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

PG&E: STOCKTON GAS PLANT (Continued) **1000198856**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1990-04-13 00:00:00.0
Handler Name: PG&E STOCKTON GAS LOAD CTR
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2000-10-12 00:00:00.0
Handler Name: STOCKTON GAS LOAD CENTER
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

Facility Has Received Notices of Violation:
Found Violation: Unknown
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported

PG&E: STOCKTON GAS PLANT (Continued) **1000198856**

Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	2006-09-22 00:00:00.0
Evaluation Responsible Agency:	EPA Contractor/Grantee
Found Violation:	Undetermined
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	KSAVA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

US FIN ASSUR:

Name:	PG&E STOCKTON GAS LOAD CTR
Address:	535 S CENTER
City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAD980886873
County:	Not reported
Mechanism type:	F
Mechanism Type Description:	FINANCIAL TEST
Cost estimate:	2000000
Face value:	2000000
Effective date:	2017-03-24 00:00:00
Provider:	PG&E
EPA region:	9

Name:	PG&E STOCKTON GAS LOAD CTR
Address:	535 S CENTER
City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAD980886873
County:	Not reported
Mechanism type:	F
Mechanism Type Description:	FINANCIAL TEST
Cost estimate:	529784
Face value:	529784
Effective date:	2011-03-10 00:00:00
Provider:	PG&E

PG&E: STOCKTON GAS PLANT (Continued) **1000198856**

EPA region: 9

FINDS:
Registry ID: 110055817941

Click Here:

Environmental Interest/Information System:
STATE MASTER
Registry ID: 110002674204

Click Here:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

I83 **PACIFIC GAS & ELECTRIC CO.** **HIST UST** **S108432784**
WSW **535 S CENTER ST** **EMI** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **CERS**
0.200 mi.
1058 ft. **Site 9 of 12 in cluster I**

Relative: **Higher**
Actual: **17 ft.**

HIST UST:

Name:	GAS LOAD CENTER
Address:	535 S CENTER STREET
City,State,Zip:	STOCKTON, CA 95202
File Number:	0002FFAE
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FFAE.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

PACIFIC GAS & ELECTRIC CO. (Continued) **S108432784**

Click here for Geo Tracker PDF:

EMI:

Name:	PACIFIC GAS & ELECTRIC CO.
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2005
County Code:	39
Air Basin:	SJV
Facility ID:	605
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0087814911643540617
Reactive Organic Gases Tons/Yr:	.008738015275478372
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PACIFIC GAS & ELECTRIC CO.
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2006
County Code:	39
Air Basin:	SJV
Facility ID:	605
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0089332371361255640
Reactive Organic Gases Tons/Yr:	.008889009974956525
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PACIFIC GAS & ELECTRIC CO.
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 959480000
Year:	2007
County Code:	39
Air Basin:	SJV
Facility ID:	605
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0063350772035120044
Reactive Organic Gases Tons/Yr:	.006303713155269628

PACIFIC GAS & ELECTRIC CO. (Continued) **S108432784**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PACIFIC GAS & ELECTRIC CO.
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2008
County Code:	39
Air Basin:	SJV
Facility ID:	605
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.0063350772035120044
Reactive Organic Gases Tons/Yr:	.006303713155269628
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CERS:

Name:	PACIFIC GAS & ELECTRIC CO.
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203-3451
Site ID:	485497
CERS ID:	110037967527
CERS Description:	US EPA Air Emission Inventory System (EIS)

I84 **GAS LOAD CENTER** **HIST UST** **U001603238**
WSW **535 S CENTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.200 mi.
1058 ft. **Site 10 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

HIST UST:

Name:	GAS LOAD CENTER
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95202
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000024753
Facility Type:	Other
Other Type:	PUBLIC UTILITY
Contact Name:	WILLIAM J. FRAZIER
Telephone:	2094636805
Owner Name:	PACIFIC GAS AND ELECTRIC COMPA
Owner Address:	77 BEALE STREET
Owner City,St,Zip:	SAN FRANCISCO, CA 94106
Total Tanks:	0001

GAS LOAD CENTER (Continued) **U001603238**

Tank Num:	001
Container Num:	8
Year Installed:	1979
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

I85 **PG&E: STOCKTON GAS PLANT** **UST** **U004260964**
WSW **535 S CENTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.200 mi.
1058 ft. **Site 11 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

UST SAN JOAQUIN:

Name:	PG&E: STOCKTON GAS PLANT
Address:	535 S CENTER ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0009476
Mail Address:	PO Box 7640
Mail Address 2:	Not reported
Mail Care of:	Pacific Gas and Electric Company
Mail City,St,Zip:	San Francisco, CA 94120
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	5000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10148343
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	0.0000000000
Longitude:	0.0000000000
Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10148343
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported

PG&E: STOCKTON GAS PLANT (Continued) **U004260964**

Date Installed: Not reported
Date of Closure: Not reported
Latitude: 0.0000000000
Longitude: 0.0000000000

I86 **PG&E GAS LOAD CENTER** **CPS-SLIC S101302623**
WSW **535 CENTER** **CHMIRS N/A**
1/8-1/4 **STOCKTON, CA 95201** **HIST CORTESE**
0.200 mi. **CERS**
1058 ft. **Site 12 of 12 in cluster I**

Relative:
Higher

Actual:
17 ft.

SLIC REG 5:
Name: PG&E Former Manufactured Gas Plant, Stockton
Address: 535 Center St
City: Stockton
Region: 5
Facility Status: Phase IV RI
Unit: Facility is a Spill or site
Pollutant: PNAs, Pb, As, Hg
Lead Agency: GJD
Date Filed: / /
Report Date: / /
Date Added: Not reported
Date Closed: Not reported

CPS-SLIC:
Name: PG&E - STOCKTON FORMER MGP
Address: 535 SOUTH CENTER ST
City,State,Zip: STOCKTON, CA 95203-5203
Region: STATE
Facility Status: **Open - Verification Monitoring**
Status Date: 06/08/2010
Global Id: SL205122996
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Lead Agency Case Number: 39490015
Latitude: 37.946735717122
Longitude: -121.290392875671
Case Type: Cleanup Program Site
Case Worker: DW
Local Agency: DEPARTMENT OF TOXIC SUBSTANCES CONTROL
RB Case Number: SL205122996
File Location: Regional Board
Potential Media Affected: Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Diesel, Gasoline, Polynuclear aromatic hydrocarbons (PAHs)
Site History: The site was the location of a former gasification plant. Residues and waste from the manufactured gas process were stored and disposed onsite. In addition, petroleum leaked from onsite storage tanks. There are several residents who live near the site. This site "PG&E Gas Plant Stockton" was also entered into the Site Mitigation and Brownfields Reuse Database as CalSites (now EnviroStor) number 39490009 which has been deleted. Historical comments under the deleted listing showed that on 7-28-1993 DTSC made the comment that "An EPA "report of individual site' stated a Hazard Ranking System (HRS) score was need on 6-17-92." and on 10-26-1995 a comment was made that "EPA is lead on this Site. Refer to EPA." A review of the United States Environmental Protection Agency's Comprehensive Environmental Response Compensation Liability Information System

PG&E GAS LOAD CENTER (Continued) **S101302623**

Database shows that the site was assigned a status of "No Further Response Action Planned" on 1-23-96.

Click here to access the California GeoTracker records for this facility:

CHMIRS:

Name:	Not reported
Address:	535 SOUTH CENTER ST
City,State,Zip:	STOCKTON, CA 95203
OES Incident Number:	13-6006
OES notification:	09/24/2013
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Other
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Lbs.
Other:	Not reported
Date/Time:	1700
Year:	2013
Agency:	NRC
Incident Date:	9/23/2013
Admin Agency:	San Joaquin County Environmental Health
Amount:	Not reported
Contained:	Unknown
Site Type:	Not reported
E Date:	Not reported
Substance:	Mercury

PG&E GAS LOAD CENTER (Continued) **S101302623**

Quantity Released:	2.5
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Per NRC: "Caller is reporting a release of metallic mercury from old instruments (gas measurement instruments) due to an unknown cause at this time." Remedial Actions: "Caller states the material is contained, the material will be vacuumed up and cleanup is underway. The floor boards were also pulled up." Additional Info: "Caller will notify San Joaquin Environmental."

HIST CORTESE:

edr_fname:	PG&E GAS LOAD CENTER
edr_fadd1:	535 CENTER
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390377

CERS:

Name:	PG&E - STOCKTON FORMER MGP
Address:	535 SOUTH CENTER ST
City,State,Zip:	STOCKTON, CA 95203-5203
Site ID:	211873
CERS ID:	SL205122996
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	AIMEE PHIRI - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Drive, Suite #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644746

N87 **OKAMOTO SERVICE** **SWEEPS UST** **S101625451**
North **145 S SUTTER ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.205 mi.
1080 ft. **Site 1 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

SWEEPS UST:

Name:	OKAMOTO SERVICE
Address:	145 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1257
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001257-000001
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	5

Name:	OKAMOTO SERVICE
Address:	145 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1257
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001257-000002
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	OKAMOTO SERVICE
Address:	145 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1257
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001257-000003

OKAMOTO SERVICE (Continued) **S101625451**

Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Name: OKAMOTO SERVICE
Address: 145 S SUTTER ST
City: STOCKTON
Status: Not reported
Comp Number: 1257
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001257-000004
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: OIL
STG: WASTE
Content: WASTE OIL
Number Of Tanks: Not reported

Name: OKAMOTO SERVICE
Address: 145 S SUTTER ST
City: STOCKTON
Status: Not reported
Comp Number: 1257
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001257-000005
Tank Status: Not reported
Capacity: 1
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: AVIA. GAS
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000227
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 222 E WEBER AVE

OKAMOTO SERVICE (Continued) **S101625451**

Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95206
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

N88 **SAN JOAQUIN COUNTY** **HIST UST** **S112981965**
North **145 S SUTTER ST** **HAZNET** **N/A**
1/8-1/4 **STOCKTON, CA 95202** **HWTS**
0.205 mi.
1080 ft. **Site 2 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

HIST UST:

Name:	OKAMOTO SERVICE
Address:	145 SOUTH SUTTER
City,State,Zip:	STOCKTON, CA 95202
File Number:	0002FC2F
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FC2F.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

HAZNET:

Name:	SAN JOAQUIN COUNTY
Address:	145 S SUTTER ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95202
Contact:	RICK DELATORRE
Telephone:	2094683255
Mailing Name:	Not reported
Mailing Address:	44 N SAN JOAQUIN ST FL 5 STE 590
Year:	2011
Gepaid:	CAC002657182
TSD EPA ID:	CAD980887418

SAN JOAQUIN COUNTY (Continued) **S112981965**

CA Waste Code: 135 - Unspecified aqueous solution
Disposal Method: H135 - Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Tons: 2.31

Year: 2011
Gepaid: CAC002657182
TSD EPA ID: CAD980887418
CA Waste Code: 352 - Other organic solids
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 5.75

Year: 2010
Gepaid: CAC002657182
TSD EPA ID: CAT080013352
CA Waste Code: 241 - Tank bottom waste
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 8.1315

Additional Info:
Year: 2010
Gen EPA ID: CAC002657182

Shipment Date: 20100915
Creation Date: 12/16/2010 18:30:33
Receipt Date: 20100920
Manifest ID: 002128935FLE
Trans EPA ID: CAT080016116
Trans Name: NIETO AND SONS TRUCKING INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAT080013352
Trans Name: DEMENNO KERDOON
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 241 - Tank bottom waste 251 Still bottoms with halogenated organics
RCRA Code: Not reported
Meth Code: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons: 8.1315
Waste Quantity: 1950
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2011
Gen EPA ID: CAC002657182

Shipment Date: 20110131

SAN JOAQUIN COUNTY (Continued) **S112981965**

Creation Date:	3/31/2011 18:30:21
Receipt Date:	20110203
Manifest ID:	006047908JJK
Trans EPA ID:	CAD982413262
Trans Name:	EVERGREEN ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	EVERGREEN OIL INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D007
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	5.75
Waste Quantity:	11500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20110131
Creation Date:	3/30/2011 18:30:08
Receipt Date:	20110201
Manifest ID:	006047906JJK
Trans EPA ID:	CAD982468183
Trans Name:	DECON ENVIRONMENTAL SERVICE INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	EVERGREEN OIL INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	135 - Unspecified aqueous solution
RCRA Code:	Not reported
Meth Code:	H135 - Discharge To Sewer/Potw Or Npdes(With Prior Storage--With Or Without Treatment)
Quantity Tons:	2.31
Waste Quantity:	550
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	SAN JOAQUIN COUNTY
Address:	145 S SUTTER ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95202
EPA ID:	CAC002657182
Inactive Date:	02/23/2011
Create Date:	08/26/2010

SAN JOAQUIN COUNTY (Continued) **S112981965**

Last Act Date:	01/17/2012
Mailing Name:	Not reported
Mailing Address:	44 N SAN JOAQUIN ST FL 5 STE 590
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 95202
Owner Name:	SAN JOAQUIN COUNTY
Owner Address:	44 N SAN JOAQUIN ST FL 5 STE 590
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA 95202
Contact Name:	RICK DELATORRE
Contact Address:	44 N SAN JOAQUIN ST FL 5 STE 590
Contact Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95202

N89 **OKAMOTO SERVICE** **HIST UST** **U001603244**
North **145 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.205 mi.
1080 ft. **Site 3 of 14 in cluster N**

Relative: HIST UST:
Higher

Name:	OKAMOTO SERVICE
Address:	145 S SUTTER ST
City,State,Zip:	STOCKTON, CA 95202
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000049766
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	KATSUMI UYEDA
Telephone:	2099431158
Owner Name:	FRANCES F. OKAMOTO
Owner Address:	431 WEST JEFFERSON
Owner City,St,Zip:	STOCKTON, CA 95206
Total Tanks:	0004
Tank Num:	001
Container Num:	I
Year Installed:	1968
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	1968
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	III
Year Installed:	1968

Actual:
17 ft.

OKAMOTO SERVICE (Continued) **U001603244**

Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	004
Container Num:	IV
Year Installed:	1968
Tank Capacity:	00001000
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None

N90 **SJ COUNTY** **UST** **U004024850**
North **145 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.205 mi.
1080 ft. **Site 4 of 14 in cluster N**

Relative: UST SAN JOAQUIN:
Higher

Actual:
17 ft.

Name:	SJ COUNTY
Address:	145 S SUTTER ST
City,State,Zip:	STOCKTON, CA 95206
Region:	SJ
Facility Id:	FA0006013
Mail Address:	222 E WEBER AVE RM 678
Mail Address 2:	Not reported
Mail Care of:	SJ COUNTY
Mail City,St,Zip:	STOCKTON, CA 95206
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	5000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	10000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete

SJ COUNTY (Continued) **U004024850**

Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 3
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 10000
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 4
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1000
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 5
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 0
Product Type Desc: 1a - REGULAR UNLEADED
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete

SJ COUNTY (Continued) **U004024850**

Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: TA0519869
Tank Number: 6
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1
Product Type Desc: (none)
Program Element: 2362
Decode for Program Element: 2362 - UST FACILITY & 1 TANK
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: 12/8/2010
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: TA0519870
Tank Number: 7
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1
Product Type Desc: (none)
Program Element: 2362
Decode for Program Element: 2362 - UST FACILITY & 1 TANK
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: 12/8/2010
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: TA0519871
Tank Number: 8
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1
Product Type Desc: (none)
Program Element: 2362
Decode for Program Element: 2362 - UST FACILITY & 1 TANK

SJ COUNTY (Continued) **U004024850**

Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	12/8/2010
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	TA0519872
Tank Number:	9
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1
Product Type Desc:	(none)
Program Element:	2362
Decode for Program Element:	2362 - UST FACILITY & 1 TANK
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	12/8/2010
Latitude:	Not reported
Longitude:	Not reported

O91 **SHELL BULK PLANT** **HIST CORTESE** **S101302823**
West **38 SONORA** **N/A**
1/8-1/4 **STOCKTON, CA 95201**
0.210 mi.
1107 ft. **Site 1 of 7 in cluster O**

Relative: **Lower**
Actual: **16 ft.**

HIST CORTESE:

edr_fname:	SHELL BULK PLANT
edr_fadd1:	38 SONORA
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390247

N92 **MARKET ST. PARKING** **SWEEPS UST** **S101592736**
NNE **134 S SUTTER ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.212 mi.
1117 ft. **Site 5 of 14 in cluster N**

Relative: **Higher**
Actual: **17 ft.**

SWEEPS UST:

Name:	MARKET ST. PARKING
Address:	134 S SUTTER ST
City:	STOCKTON
Status:	Not reported

MARKET ST. PARKING (Continued) **S101592736**

Comp Number: 2339
Number: Not reported
Board Of Equalization: 44-003226
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002339-000001
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: 4

Name: MARKET ST. PARKING
Address: 134 S SUTTER ST
City: STOCKTON
Status: Not reported
Comp Number: 2339
Number: Not reported
Board Of Equalization: 44-003226
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002339-000002
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Name: MARKET ST. PARKING
Address: 134 S SUTTER ST
City: STOCKTON
Status: Not reported
Comp Number: 2339
Number: Not reported
Board Of Equalization: 44-003226
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002339-000003
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: PETROLEUM
STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Name: MARKET ST. PARKING

MARKET ST. PARKING (Continued) **S101592736**

Address:	134 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2339
Number:	Not reported
Board Of Equalization:	44-003226
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002339-000004
Tank Status:	Not reported
Capacity:	1200
Active Date:	Not reported
Tank Use:	OIL
STG:	PRODUCT
Content:	UNKNOWN
Number Of Tanks:	Not reported

CA FID UST:

Facility ID:	39000264
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	425 N EL DORADO ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95202
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

N93 **CLARK GARAGE** **SWEEPS UST** **S101625449**
North **125 S SUTTER ST** **HIST UST** **N/A**
1/8-1/4 **STOCKTON, CA 95202** **CA FID UST**
0.216 mi.
1143 ft. **Site 6 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

SWEEPS UST:

Name:	CLARK GARAGE
Address:	125 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1892
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001892-000001

CLARK GARAGE (Continued) **S101625449**

Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: 2

Name: CLARK GARAGE
Address: 125 S SUTTER ST
City: STOCKTON
Status: Not reported
Comp Number: 1892
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001892-000002
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

HIST UST:
Name: CLARK GARAGE
Address: 125 SO SUTTER STREET
City,State,Zip: STOCKTON, CA 95202
File Number: 0002FB7E
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FB7E.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

Click here for Geo Tracker PDF:

CLARK GARAGE (Continued) **S101625449**

CA FID UST:

Facility ID:	39001169
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	222 E WEBER ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95202
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

N94 **CLARK GARAGE** **HIST UST** **U001603234**
North **125 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.216 mi.
1143 ft. **Site 7 of 14 in cluster N**

Relative: **Higher**

Actual: **17 ft.**

HIST UST:

Name:	CLARK GARAGE
Address:	125 S SUTTER ST
City,State,Zip:	STOCKTON, CA 95202
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000006823
Facility Type:	Other
Other Type:	GARAGE
Contact Name:	DOUGLAS J. TROTTER
Telephone:	2099469183
Owner Name:	DOUGLAS J. TROTTER
Owner Address:	125 SO. SUTTER STREET
Owner City,St,Zip:	STOCKTON, CA 95202
Total Tanks:	0002
Tank Num:	001
Container Num:	ONE
Year Installed:	1947
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	1/2
Leak Detection:	Visual, Stock Inventor
Tank Num:	002
Container Num:	TWO
Year Installed:	1947
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED

CLARK GARAGE (Continued) **U001603234**

Container Construction Thickness: 1/2
Leak Detection: Visual, Stock Inventor

N95 **SJ COUNTY** **UST** **U004260395**
North **125 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.216 mi.
1143 ft. **Site 8 of 14 in cluster N**

Relative: UST SAN JOAQUIN:
Higher

Actual: Name: SJ COUNTY
17 ft. Address: 125 S SUTTER ST
City,State,Zip: STOCKTON, CA 95202
Region: SJ
Facility Id: FA0004980
Mail Address: 222 E WEBER
Mail Address 2: Not reported
Mail Care of: SJ COUNTY
Mail City,St,Zip: STOCKTON, CA 95202

Tank Rec ID: Not reported
Tank Number: 1
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 500
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: 37.9516380600
Longitude: -121.2860751606

Tank Rec ID: Not reported
Tank Number: 2
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 500
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: 37.9516380600
Longitude: -121.2860751606

P96 **MOTOR POOL GARAGE** **RCRA NonGen / NLR** **1024811606**
North **121 S SAN JOAQUIN ST** **CAL000295835**
1/8-1/4 **STOCKTON, CA 95202**
0.218 mi.
1152 ft. **Site 1 of 4 in cluster P**

Relative: **Lower**
Actual: **16 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2005-06-29 00:00:00.0
Handler Name:	MOTOR POOL GARAGE	
Handler Address:		121 S SAN JOAQUIN ST
Handler City,State,Zip:		STOCKTON, CA 95202-3206
EPA ID:		CAL000295835
Contact Name:		DAVID B. MYERS
Contact Address:		444 S WILSON WAY
Contact City,State,Zip:		STOCKTON, CA 95205
Contact Telephone:		209-468-9745
Contact Fax:		209-468-3098
Contact Email:		DBMYERS@SJGOV.ORG
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		444 S WILSON WAY
Mailing City,State,Zip:		STOCKTON, CA 95205-0000
Owner Name:		COUNTY OF SAN JOAQUIN
Owner Type:		Other
Operator Name:		DAVID B. MYERS
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

MOTOR POOL GARAGE (Continued) **1024811606**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 20:27:26.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF SAN JOAQUIN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1810
Owner/Operator City,State,Zip:	STOCKTON, CA 95201-1810
Owner/Operator Telephone:	209-468-3099
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DAVID B. MYERS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	444 S WILSON WAY
Owner/Operator City,State,Zip:	STOCKTON, CA 95205
Owner/Operator Telephone:	209-468-9745
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MOTOR POOL GARAGE (Continued) **1024811606**

Historic Generators:
- Receive Date: 2005-06-29 00:00:00.0
- Handler Name: MOTOR POOL GARAGE
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 811111
- NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

P97 **SJ COUNTY PARKING GARAGE** **CERS TANKS** **S121746998**
North **121 S SAN JOAQUIN ST** **CERS** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.218 mi.
1152 ft. **Site 2 of 4 in cluster P**

Relative: **Lower**

Actual: **16 ft.**

CERS TANKS:
- Name: SJ COUNTY PARKING GARAGE
- Address: 121 S SAN JOAQUIN ST
- City,State,Zip: STOCKTON, CA 95202
- Site ID: 153905
- CERS ID: 10181667
- CERS Description: Underground Storage Tank

CERS:
- Name: SJ COUNTY PARKING GARAGE
- Address: 121 S SAN JOAQUIN ST
- City,State,Zip: STOCKTON, CA 95202
- Site ID: 153905
- CERS ID: 10181667
- CERS Description: Chemical Storage Facilities

Violations:
- Site ID: 153905
- Site Name: SJ COUNTY PARKING GARAGE
- Violation Date: 07-18-2014
- Citation: Un-Specified
- Violation Description: UST Program - Administration/Documentation - For use of Local Ordinance only
- Violation Notes: Returned to compliance on 07/18/2014.
- Violation Division: San Joaquin County Environmental Health

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	HSC 6.5 25123.3(h) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)
Violation Description:	Failure to determine the status of any hazardous waste if a signed copy of the manifest isnG t received within 35 days of the date the waste was accepted by the initial transporter and/or to submit an Exception Report to DTSC if a signed copy of the manifest isnG t received within 60 days of the date the waste was accepted by the initial transporter.
Violation Notes:	Returned to compliance on 12/23/2019. Manifest number 004475063JJK from 8-9-13 was found without a signed off copy from the destination facility. Hazardous waste generators shall retain copies of all manifests signed off by the destination facility on site for three years and have them readily available for review. If the generator did not receive a copy of the manifest with the handwritten signature of the owner or operator of the facility to which the generatorG s waste was submitted within 60 days of the date the waste was accepted by the initial transporter, the generator shall submit a legible copy of the missing manifest, with some indication that the generator has not received confirmation of delivery. This information shall be submitted to: DTSC Report Repository Generator Information Services Section P.O. Box 806 Sacramento, CA 95812-0806 Immediately locate a copy of the missing manifests or prepare and submit the required information to DTSC. Submit to the EHD a copy of the signed off
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-30-2013
Citation:	HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description:	UST Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 08/21/2013. HSC 25404(e)(4) CERS submittal requirement not met
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	10-01-2014
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 10/13/2014. The emergency response procedures have not been submitted . A business plan shall include the following emergency response procedures for a release or threatened release of hazardous materials, including, but not limited to, the

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

following: - immediate notification of local emergency personnel and the Environmental Health Department (EHD) - procedures for the mitigation of a release or threatened release to minimize any potential harm or damage to persons, property, or the environment - evacuation plans and procedures, including immediate notice, for the site Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval. This is a repeat violation, Class II.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 10-01-2014
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes: Returned to compliance on 10/13/2014. The Business Activities Page and the Business Owner/Operator Identification form was not is not complete/accurate. The Business Activities Page indicates the this site is not a hazardous waste generator and the EPA ID# has not been identified; the Business Owner/Operator Page does not identify the name and contact information for the Secondary Emergency Contact. This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This is a Class II violation.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-27-2016
Citation: 23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)
Violation Description: Failure to have a UST Monitoring Plan available on site.
Violation Notes: Returned to compliance on 08/23/2016. An approved copy of the monitoring plans were not available for inspection. A copy of these plans shall be accessible on site at all times. Immediately locate and retain a copy on site.

Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-24-2015
Citation: HSC 6.7 25291(e) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(e)
Violation Description: Failure to remove, contain, analyze, and dispose of properly, water removed from the secondary containment by the owner or operator.
Violation Notes: Returned to compliance on 07/24/2015. Liquid was observed in the 1 cup

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

of liquid in 87 turbine sump. If water could enter into the secondary containment by precipitation or infiltration, it must be removed and disposed of properly. The designated operator removed 1 cup of liquid from the 87 turbine sump. Ensure that all sumps and annular spaces are maintained free of liquid.

Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-26-2019
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description: Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes: Returned to compliance on 08/27/2019. The overfill prevention conducted on 10/12/2018, a copy of the test results was not found on site during inspection. Immediately locate and maintain a copy of the overfill test results on site.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-24-2015
Citation: 23 CCR 16 2715 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715
Violation Description: Failure to comply with one or more of the designated operator monthly inspection requirements: failed to inspect the monthly alarm history report; attach a copy of the alarm history; failed to inspect for the presence of liquid or debris in the spill container/spill bucket and under dispenser containment; failed to inspect the under dispenser containment to ensure that monitoring equipment is placed in the

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

proper position; failure to inspect for liquid or debris in the containment sump where an alarm occurred or for which there is no record of a service visit; or failure to check that all testing and maintenance has been completed and documented.

Violation Notes: Returned to compliance on 08/17/2015. The designated operator failed to check and note the correct test dates for the secondary containment testing, monitoring system certification and spill container testing on the August 2014 to June 2015 designated operator monthly inspection report. The following had the incorrect test dates listed: 1) monitoring system certification was listed as 7/20/14 for the monthly reports of August 2014 to June 2015 2) secondary containment test date was listed as 7/30/12 for the monthly reports of August 2014 to June 2015 3) spill container test date was listed as 1/23/12 for monthly reports of July 2014 to November 2014 During the monthly inspection, the designated operator shall check that all required testing and maintenance for the UST system have been completed and document the dates they were done. Ensure that designated operators performing monthly inspections at this facility are including all of the required information on the reports. The designated operator [Truncated]

Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 02-13-2019
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Violation Description: Failure to complete and electronically submit a site map with all required content.

Violation Notes: Returned to compliance on 02/28/2019. The map does not show loading areas (fuel), evacuation staging areas, emergency response equipment (fire extinguishers), and a legend to identify the number code (5) used on the map #3. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. If a site map element is not applicable for your facility then list it on the map and label as G NA". Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-24-2020
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)

Violation Description: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violation Notes: OBSERVATION: The designated operator inspections for the following months were performed more than 30 days after the previous inspection: - Initial inspection on 10/31/2019, next inspection performed on 12/3/2019 , 33days between the two dates. REGULATION GUIDANCE: The designated operator visual inspections shall be conducted within 30 days or less of the previous inspection. CORRECTIVE ACTION: Ensure that all designated operator inspections are performed within the required time frames.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-24-2017
Citation: 23 CCR 16 2632(d)(1)(C), 2641(h), 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(d)(1)(C), 2641(h), 2711(a)(8)
Violation Description: Failure to submit or update a plot plan.
Violation Notes: Returned to compliance on 08/21/2017. An accurate UST Monitoring Site Plan was not submitted. The current site plan is missing the leak detector, and incorrectly identifies the UDC sump sensors as VR209. A site plan must be submitted identifying the locations where monitoring will be performed. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/ and upload a copy of the UST Monitoring Site Plan.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 10-01-2014
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes: Returned to compliance on 10/13/2014. A training program has not been submitted. Training programs for all employees and annual training, including refresher courses, shall include safety procedures for the event of a release or threatened release of a hazardous material, including, but not limited to, familiarity with the facility's emergency response plans and procedures. These training programs may take into consideration of each employee. Immediately prepare or update the facility's training program, log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

	approval. This is a Class II violation.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description:	Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes:	Returned to compliance on 12/23/2019. Manifest numbers 004475063JJK from 8-9-13 was found without a signed off copy from the destination facility. Hazardous waste generators shall retain copies of all manifests signed off by the destination facility on site for three years and have them readily available for review. If the generator did not receive a copy of the manifest with the handwritten signature of the owner or operator of the facility to which the generatorG s waste was submitted within 60 days of the date the waste was accepted by the initial transporter, the generator shall submit a legible copy of the missing manifest, with some indication that the generator has not received confirmation of delivery. This information shall be submitted to: DTSC Report Repository Generator Information Services Section P.O. Box 806 Sacramento, CA 95812-0806 Immediately locate a copy of the missing manifests or prepare and submit the required information to DTSC. Submit to the EHD a copy of the signed o
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-24-2017
Citation:	23 CCR 16 2715(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)
Violation Description:	Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been properly trained.
Violation Notes:	Returned to compliance on 08/21/2017. The designated operator failed to document all the alarms from the attached alarm history on the February designated operator monthly inspection report and failed to check that they were responded to appropriately. The missing alarms include: L2 STP fuel alarm. During the monthly inspection, the designated operator shall review the alarm history for the previous month, check that each alarm was documented and responded to

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

	appropriately, and attach a copy of the alarm history with documentation taken in response to any alarms to the monthly report. Ensure that designated operators performing monthly inspections at this facility are including all of the required information on the reports.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-24-2015
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description:	Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.
Violation Notes:	Returned to compliance on 07/24/2015. The 87 VMI line leak detector failed to detect a leak when tested. All line leak detectors shall be capable of detecting a 3-gallon per hour leak at 10 psi. The service technician adjusted the leak detector twice, retested it, and it passed.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	23 CCR 16 2632, 2634, 2712(b) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2712(b)
Violation Description:	Failure to maintain monitoring and maintenance records (e.g., alarm logs) and/or maintain records of appropriate follow-up actions.
Violation Notes:	Returned to compliance on 08/23/2016. Liquid was found in the 87 vapor pot sump and turbine sump. Secondary containment shall be constructed to prevent any water intrusion into the system by precipitation, infiltration, or surface runoff. The service technician removed less than a gallon of liquid from these sumps and returned the sensor to its proper location. Immediately contact a properly licensed, trained, and certified contractor to address the water intrusion into the sumps under permit and inspection of the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-26-2019
Citation:	HSC 6.7 25291(b) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(b)
Violation Description:	Failure of the UST system to be designed and constructed with a monitoring system capable of detecting the entry of the hazardous substance into the secondary containment.
Violation Notes:	Returned to compliance on 07/26/2019. The 87 vapor sump sensor was found leaning and not located to detect a leak at the earliest

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

opportunity. Monitoring equipment shall be maintained to be able to detect a leak at the earliest possible opportunity. The sensor was repositioned vertically by the service technician after testing. Ensure that all monitoring equipment is maintained to detect a leak at the earliest opportunity. This was corrected on site.

Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-26-2019
Citation: 23 CCR 16 2715(c)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(4)
Violation Description: Failure to maintain a list of employees trained by the designated operator on-site or off-site at a readily available location, if approved by the UPA. For training that occurs on or after October 1, 2018, failure to maintain a copy of the "Facility Employee Training Certificate" on-site or off-site at a readily available location, if approved by the UPA.
Violation Notes: Returned to compliance on 08/27/2019.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-25-2018
Citation: 23 CCR 16 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2711(a)(8)
Violation Description: Failure to submit or maintain a current facility plot plan.
Violation Notes: Returned to compliance on 08/27/2018. An accurate UST Monitoring Site Plan was not submitted. Site plan indicates two sensors in two separate sumps. The site plan also incorrectly indicates an annular sensor is located within a sump, and needs to indicate in the "Key" legend as annular sensor. A site plan must be submitted identifying the locations where monitoring will be performed. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/ and upload a copy of the UST Monitoring Site Plan.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-27-2016
Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)
Violation Description: Failure to have an approved UST Monitoring Plan.
Violation Notes: Returned to compliance on 08/23/2016. The monitoring plan is not current and not approved by the EHD. The submitted monitoring plan indicates YES for UDC monitoring stops the flow of product at the dispenser. This should be marked NO. Tank monitoring is performed using the following methods has programmed tank tests listed as .1 GPH, but should be listed as .2 GPH. Under dispenser containment monitoring UDC monitoring stops flow of product at dispenser is listed

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

	as YES, but should be listed as NO. The monitoring plan must be uploaded to the California Environmental Reporting System (CERS). Immediately log into CERS, make the necessary changes, and submit for review by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-30-2013
Citation:	HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description:	UST Program - Design/Construction - General
Violation Notes:	Returned to compliance on 07/30/2013.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-30-2013
Citation:	HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Description:	Haz Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 08/09/2013.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 07/27/2016. The five gallon bucket of hazardous waste oily debris did not have a hazardous property and accumulation start date marked. All hazardous waste containers shall be marked with the following information: - the words G Hazardous WasteG - name and address of generator - hazardous properties - physical state - composition (contents) - accumulation start date During the inspection, Connie Warden marked the hazardous waste property of toxic and the accumulation start date of 7-27-16 and ensure that all hazardous waste containers are marked with all the required information. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-26-2019

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Citation:	HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286
Violation Description:	Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.
Violation Notes:	Returned to compliance on 08/27/2019. The UST Tank information form for 87 is not current in CERS. The 87 tank form the list is inaccurate overfill prevention methods (audible/visual alarms- NO and fill tube shut off valve - YES. Any change of information must be updated in CERS within 30days of the changes immediately log into CERS. Update the required information, and submit for review by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-24-2017
Citation:	23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)
Violation Description:	Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.
Violation Notes:	Returned to compliance on 08/21/2017. The 87 submersible turbine pump sump sensor was leaning and not located to detect a leak at the earliest opportunity. Monitoring equipment shall be maintained to be able to detect a leak at the earliest possible opportunity. The sensor was repositioned vertically by the service technician after testing. Ensure that all monitoring equipment is maintained to detect a leak at the earliest opportunity.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	23 CCR 6.7 25284, 25286 - California Code of Regulations, Title 23, Chapter 6.7, Section(s) 25284, 25286
Violation Description:	Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.
Violation Notes:	Returned to compliance on 08/23/2016. UST Tank Information is not current in CERS. The UST Tank information submitted lists YES for overfill protection audible/visual alarms. This should be listed as NO. The under dispenser containment construction material is listed as FIBERGLASS. This should be listed as RIGID PLASTIC Any change of information must be updated in CERS within 30 days of the changes. Immediately log into CERS, update the required information, and submit for review by the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Violation Date:	07-27-2016
Citation:	23 CCR 16 2715(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)
Violation Description:	Failure to comply with one or more of the following designated

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

operator (DO) monthly inspection requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been properly trained.

Violation Notes: Returned to compliance on 08/23/2016. The designated operator failed to check and note the correct test dates for the secondary containment test on the 7-24-15 designated operator monthly inspection report. The secondary containment test was listed as 7-30-12. It should have been listed as 7-11-12. During the monthly inspection, the designated operator shall check that all required testing and maintenance for the UST system have been completed and document the dates they were done. Ensure that designated operators performing monthly inspections at this facility are including all of the required information on the reports.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-26-2019
Citation: 23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)
Violation Description: Failure to retain a copy of the permit to operate at the facility.
Violation Notes: Returned to compliance on 08/27/2019. A permit to operate the UST system has not been issued. No person may own or operate an UST unless a permit for its operation has been issued by the local agency to the owner or operator of the UST system. Immediately obtain a permit to operate a UST system from the EHD. An G Operating without a PermitG penalty applies.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 07-30-2013
Citation: HSC 6.7 Multiple Sections - California Health and Safety Code, Chapter 6.7, Section(s) Multiple Sections
Violation Description: UST Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 08/21/2013.
Violation Division: San Joaquin County Environmental Health
Violation Program: UST
Violation Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Violation Date: 02-13-2019
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violation Notes: Returned to compliance on 02/26/2019. Employee training records were not available at the time of inspection. The business plan shall include provisions for ensuring that appropriate personnel receive initial and annual refresher training. This training shall be documented electronically or by hard copy and shall be made available for a minimum of three years. Immediately provide employee training for appropriate personnel and submit a copy of the training records to the EHD.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-24-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 8/23/17. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if applicable, can be stored at the facility or uploaded into CERS.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-24-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 08/23/2020 . To minimize person to person contact EHD is choosing to write the name of person receiving the report instead of having them sign. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Documents provided during inspection: Return to compliance certification form, corrective action statement form and list of approve CUPA free training classes.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-25-2018
Violations Found: Yes
Eval Type: Routine done by local agency

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork within 30 days of receipt of this report. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if applicable, can be stored at the facility or uploaded into CERS.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-26-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by August 25, 2019. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Documents provided: Return to Compliance Certification Form, and a scheduled of free CUPA classes.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-27-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	On site to conduct a routine hazardous waste inspection. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 8-27-16. Please be aware as of January 1, 2013, all businesses are required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous waste activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-27-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	On site to conduct a routine inspection and witness the annual monitoring system certification testing. Complete and submit a copy of the Return to Compliance Certification form to the EHD with a

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by 8-27-16. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if applicable, can be stored at the facility or uploaded into CERS.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-30-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-30-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-01-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by October 31, 2014. Inspection facilitated by Dave Myers, Management Analyst II. Consent to perform the inspection and take photos was given by Dave Myers. No photos taken. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields.
Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-13-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

that have been or will be taken for each violation, and any supporting paperwork, within 30 days of receiving the completed inspection report. Facility does not have internal roads and this element was not addressed on the site map. Please address this by either writing G NAG for not applicable or a statement that says the element is not on site. Please correct this by the next submittal. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420.

Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-18-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: B: 204. RTC met on site.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-24-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by August 23, 2015. Please be aware that as of January 1, 2014, facility operators are required to upload the following UST program documents into the California Environmental Reporting System (CERS): UST Monitoring Site Plan, UST Certification of Financial Responsibility, UST Response Plan, UST Letter from Chief Financial Officer (if applicable), and the Owner Statement of Designated Operator Compliance. The UST Owner/Operator: Written Agreement, if applicable, can be stored at the facility or uploaded into CERS.
Eval Division: San Joaquin County Environmental Health
Eval Program: UST
Eval Source: CERS

Enforcement Action:
Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Site Address: 121 S SAN JOAQUIN ST
Site City: STOCKTON
Site Zip: 95202
Enf Action Date: 07-18-2014
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Site Address: 121 S SAN JOAQUIN ST

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Site City:	STOCKTON
Site Zip:	95202
Enf Action Date:	07-24-2015
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	UST
Enf Action Source:	CERS

Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Site Address:	121 S SAN JOAQUIN ST
Site City:	STOCKTON
Site Zip:	95202
Enf Action Date:	07-24-2017
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	UST
Enf Action Source:	CERS

Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Site Address:	121 S SAN JOAQUIN ST
Site City:	STOCKTON
Site Zip:	95202
Enf Action Date:	07-25-2018
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	UST
Enf Action Source:	CERS

Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Site Address:	121 S SAN JOAQUIN ST
Site City:	STOCKTON
Site Zip:	95202
Enf Action Date:	07-27-2016
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	HW
Enf Action Source:	CERS

Site ID:	153905
Site Name:	SJ COUNTY PARKING GARAGE
Site Address:	121 S SAN JOAQUIN ST
Site City:	STOCKTON
Site Zip:	95202
Enf Action Date:	07-27-2016
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Site Address: 121 S SAN JOAQUIN ST
Site City: STOCKTON
Site Zip: 95202
Enf Action Date: 07-30-2013
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HW
Enf Action Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Site Address: 121 S SAN JOAQUIN ST
Site City: STOCKTON
Site Zip: 95202
Enf Action Date: 07-30-2013
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: UST
Enf Action Source: CERS

Site ID: 153905
Site Name: SJ COUNTY PARKING GARAGE
Site Address: 121 S SAN JOAQUIN ST
Site City: STOCKTON
Site Zip: 95202
Enf Action Date: 10-01-2014
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HMRRP
Enf Action Source: CERS

Coordinates:
Site ID: 153905
Facility Name: SJ COUNTY PARKING GARAGE
Env Int Type Code: HMBP
Program ID: 10181667
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 37.951770
Longitude: -121.287490

Affiliation:
Affiliation Type Desc: CUPA District

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205-6232
Affiliation Phone:	(209) 468-3420
Affiliation Type Desc:	Document Preparer
Entity Name:	David B. Myers
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	County of San Joaquin
Entity Title:	Not reported
Affiliation Address:	444 S. Wilson Way
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95205
Affiliation Phone:	(209) 468-3099
Affiliation Type Desc:	Property Owner
Entity Name:	County of San Joaquin
Entity Title:	Not reported
Affiliation Address:	444 S. Wilson Way
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95205
Affiliation Phone:	(209) 468-3099
Affiliation Type Desc:	UST Tank Operator
Entity Name:	County of San Joaquin
Entity Title:	Not reported
Affiliation Address:	444 S Wilson Way
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95205
Affiliation Phone:	(209) 468-3099
Affiliation Type Desc:	Environmental Contact
Entity Name:	David B. Myers
Entity Title:	Not reported
Affiliation Address:	444 S. Wilson Way
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: SJ CO MOTOR POOL SHOP
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: David B. Myers
Entity Title: Managment Analyst II
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: County of San Joaquin Public Works Fleet Services
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (209) 468-3099

Affiliation Type Desc: UST Permit Applicant
Entity Name: David B. Myers
Entity Title: Management Analyst II
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (209) 468-9745

Affiliation Type Desc: UST Tank Owner
Entity Name: County of San Joaquin
Entity Title: Not reported
Affiliation Address: 444 S Wilson Way
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95205
Affiliation Phone: (209) 468-3099

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 444 S. Wilson Way
Affiliation City: Stockton

SJ COUNTY PARKING GARAGE (Continued) **S121746998**

Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	County of San Joaquin
Entity Title:	Not reported
Affiliation Address:	444 S Wilson Way
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95205
Affiliation Phone:	(209) 468-3099

P98 **SJ COUNTY PARKING GARAGE** **UST** **U004024857**
North **121 S SAN JOAQUIN ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.218 mi.
1152 ft. **Site 3 of 4 in cluster P**

Relative: **Lower**

Actual: **16 ft.**

UST:

Name:	SJ COUNTY PARKING GARAGE
Address:	121 S SAN JOAQUIN ST
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	FA0004573
Permitting Agency:	San Joaquin County Environmental Health
Latitude:	37.95177
Longitude:	-121.28749

UST SAN JOAQUIN:

Name:	SJ COUNTY PARKING GARAGE
Address:	121 S SAN JOAQUIN ST
City,State,Zip:	STOCKTON, CA 95202
Region:	SJ
Facility Id:	FA0004573
Mail Address:	444 S. Wilson Way
Mail Address 2:	Not reported
Mail Care of:	County of San Joaquin Public Works Fleet Services
Mail City,St,Zip:	Stockton, CA 95205
Tank Rec ID:	TA0504865
Tank Number:	1
Tank Status:	01 - Active, billable
Tank Capacity:	10000
Product Type Desc:	1a - REGULAR UNLEADED
Program Element:	2360
Decode for Program Element:	2360 - UST - PER TANK FEE
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	10181667
Cross Ref Tank ID:	Not reported
LEA ID:	1
Common Name:	Not reported
Date Installed:	4/13/1993
Date of Closure:	Not reported

SJ COUNTY PARKING GARAGE (Continued) **U004024857**

Latitude: 37.9518790347
Longitude: -121.2868459754

N99 **MARKET ST PARKING STRUCTURE** **UST** **U004260392**
NNE **124 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.219 mi.
1155 ft. **Site 9 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

UST SAN JOAQUIN:

Name:	MARKET ST PARKING STRUCTURE
Address:	124 S SUTTER ST
City,State,Zip:	STOCKTON, CA 95202
Region:	SJ
Facility Id:	FA0004977
Mail Address:	425 N EL DORADO ST
Mail Address 2:	Not reported
Mail Care of:	CITY OF STOCKTON PUBLIC WORKS
Mail City,St,Zip:	STOCKTON, CA 95202
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	Not reported
Tank Number:	2
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

MARKET ST PARKING STRUCTURE (Continued) **U004260392**

Tank Rec ID:	Not reported
Tank Number:	3
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	500
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Tank Rec ID:	Not reported
Tank Number:	4
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	1200
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

N100 **HENRY APARTMENTS** **SWEEPS UST** **S101593249**
North **121 S SUTTER ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.219 mi.
1155 ft. **Site 10 of 14 in cluster N**

Relative: **Higher**

Actual: **17 ft.**

SWEEPS UST:

Name:	HENRY APARTMENTS
Address:	121 S SUTTER ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1851
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001851-000001
Tank Status:	Not reported
Capacity:	1000

HENRY APARTMENTS (Continued) **S101593249**

Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: Not reported
Number Of Tanks: 1

CA FID UST:
Facility ID: 39003561
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094645869
Mail To: Not reported
Mailing Address: 7 E INGRAM
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95206
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

N101 **HENRY APARTMENTS** **UST** **U004023989**
North **121 S SUTTER ST** **N/A**
1/8-1/4 **STOCKTON, CA 95206**
0.219 mi.
1155 ft. **Site 11 of 14 in cluster N**

Relative: UST SAN JOAQUIN:
Higher Name: HENRY APARTMENTS
Address: 121 S SUTTER ST
Actual: City,State,Zip: STOCKTON, CA 95206
17 ft. Region: SJ
Facility Id: FA0005285
Mail Address: 7 E INGRAM
Mail Address 2: Not reported
Mail Care of: RODNEY CROCKER
Mail City,St,Zip: STOCKTON, CA 95204

Tank Rec ID: TA0501966
Tank Number: 1
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 1000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2322
Decode for Program Element: 2322 - EXEMPT UST
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported

HENRY APARTMENTS (Continued) **U004023989**

Latitude: Not reported
Longitude: Not reported

Q102 **DELTA PUMPS, INC.** **CPS-SLIC** **S106230406**
ESE **646 CALIFORNIA ST S** **N/A**
1/8-1/4 **STOCKTON, CA**
0.222 mi.
1170 ft. **Site 1 of 9 in cluster Q**

Relative: **Higher**
Actual: **17 ft.**

SLIC REG 5:
Name: Delta Pumps, Inc.
Address: 646 California St S
City: Stockton
Region: 5
Facility Status: RI
Unit: Facility is a Spill or site
Pollutant: chloroform, toluene, benzene
Lead Agency: Not reported
Date Filed: / /
Report Date: 07/01/98
Date Added: Not reported
Date Closed: Not reported

N103 **HUMAN SERVICES AGENCY** **LUST** **S101302830**
NNE **145 SUTTER** **Cortese** **N/A**
1/8-1/4 **STOCKTON, CA 95202** **HIST CORTESE**
0.223 mi. **Notify 65**
1180 ft. **Site 12 of 14 in cluster N** **CERS**

Relative: **Higher**
Actual: **17 ft.**

LUST:
Name: HUMAN SERVICES AGENCY
Address: 145 SUTTER ST S
City,State,Zip: STOCKTON, CA 95202
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700218
Global Id: T0607700218
Latitude: 37.951916
Longitude: -121.2857082
Status: Open - Remediation
Status Date: 04/24/2020
Case Worker: AMB
RB Case Number: 390296
Local Agency: Not reported
File Location: Regional Board
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Benzene, Gasoline
Site History: This site is at the current location of the County of San Joaquin Human Services Administration. April 1988- Nine underground storage tanks were removed from the site. Soil samples were collected from beneath the tanks; laboratory analysis reported petroleum hydrocarbon impact. December 1988- A site investigation began with the installation of groundwater monitoring wells. Petroleum hydrocarbon impact to the groundwater was reported. August 1991-August 1996- Additional groundwater monitoring wells were installed to define the

HUMAN SERVICES AGENCY (Continued) **S101302830**

lateral extent of the plume. January 1998- A Corrective Action Plan for the site was submitted; recommendation was for remediation by natural attenuation. June 2006- The Corrective Action Plan was reviewed and additional data collection was recommended by the consultant. The site is not vertically defined. June 2008- Fieldwork began to install a deep boring and a deep well. The boring was completed, but during the well installation additional underground storage tanks were discovered beneath the sidewalk of Sutter Street at the corner with Washington Street. Ground penetrating radar was used to try and determine how many tanks were there; appears to be two. A tank removal plan and continuation of the site investigation is pending.

LUST:
Global Id: T0607700218
Contact Type: Regional Board Caseworker
Contact Name: ALAN M. BUEHLER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 Sun Center Dr
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: 9164644615

LUST:
Global Id: T0607700218
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607700218
Action Type: RESPONSE
Date: 01/21/1998
Action: Other Report / Document

Global Id: T0607700218
Action Type: RESPONSE
Date: 12/01/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 03/01/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 11/01/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/09/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 09/01/2000

HUMAN SERVICES AGENCY (Continued) **S101302830**

Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/01/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 01/01/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 12/01/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 03/01/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 08/01/1995
Action: Site Assessment Report

Global Id: T0607700218
Action Type: RESPONSE
Date: 02/01/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 04/01/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 03/03/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 10/22/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/01/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 10/01/1996
Action: Monitoring Report - Quarterly

HUMAN SERVICES AGENCY (Continued) **S101302830**

Global Id: T0607700218
Action Type: RESPONSE
Date: 01/23/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/18/2009
Action: Meeting

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 01/14/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/06/2014
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700218
Action Type: RESPONSE
Date: 08/29/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/09/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 09/01/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 03/01/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/01/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 06/01/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: ENFORCEMENT

HUMAN SERVICES AGENCY (Continued) **S101302830**

Date: 10/29/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/27/2010
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/23/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/08/1988
Action: Notification - Proposition 65

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/08/1988
Action: Unauthorized Release Form

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/26/2011
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/26/2011
Action: Site Visit / Inspection / Sampling

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 01/31/2011
Action: Site Visit / Inspection / Sampling

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 07/18/2014
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 03/21/2018
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/01/2014
Action: Other Report

HUMAN SERVICES AGENCY (Continued) **S101302830**

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/29/1989
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 10/14/2010
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/01/1992
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/12/1993
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/07/1988
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/21/1989
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/15/1986
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 02/20/1989
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/29/2018
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/21/1989
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/05/1989
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT

HUMAN SERVICES AGENCY (Continued) **S101302830**

Date: 09/25/2018
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 02/04/1994
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 07/16/2018
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 02/01/1996
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/30/2019
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 07/31/2019
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 11/05/2019
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 10/28/2019
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 01/30/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 03/07/2013
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/24/2020
Action: Staff Letter

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 10/08/2018
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

HUMAN SERVICES AGENCY (Continued) **S101302830**

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/30/2019
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 11/05/2019
Action: Other Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 12/02/2020
Action: Staff Letter

Global Id: T0607700218
Action Type: Other
Date: 09/08/1988
Action: Leak Discovery

Global Id: T0607700218
Action Type: Other
Date: 04/01/1988
Action: Leak Stopped

Global Id: T0607700218
Action Type: Other
Date: 09/08/1988
Action: Leak Reported

Global Id: T0607700218
Action Type: RESPONSE
Date: 09/30/2015
Action: Soil and Water Investigation Report

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/30/2015
Action: Soil and Water Investigation Report

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 08/06/2013
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/05/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/17/2013
Action: File review

Global Id: T0607700218
Action Type: RESPONSE

HUMAN SERVICES AGENCY (Continued) **S101302830**

Date: 08/31/2015
Action: Monitoring Report - Other

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Other

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/30/2015
Action: Soil and Water Investigation Workplan

Global Id: T0607700218
Action Type: REMEDIATION
Date: 07/01/1998
Action: Monitored Natural Attenuation

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/17/2013
Action: File review

Global Id: T0607700218
Action Type: RESPONSE
Date: 02/04/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 02/02/2006
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/01/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 11/01/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 11/09/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 11/17/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/14/1993
Action: Monitoring Report - Quarterly

HUMAN SERVICES AGENCY (Continued) **S101302830**

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/01/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/29/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/01/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 10/15/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/09/2008
Action: Technical Correspondence / Assistance / Other - #04/09/2008

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/30/2008
Action: Site Visit / Inspection / Sampling - #09/30/2008

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 02/19/2009
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 09/24/2007
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/18/2009
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 04/09/2009
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/25/2012
Action: File review

Global Id: T0607700218
Action Type: RESPONSE

HUMAN SERVICES AGENCY (Continued) **S101302830**

Date: 01/01/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 10/01/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/20/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 05/14/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 02/01/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 06/22/1995
Action: Other Report / Document

Global Id: T0607700218
Action Type: RESPONSE
Date: 01/01/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 07/01/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 11/02/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 06/01/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 03/01/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700218
Action Type: RESPONSE
Date: 06/01/1992
Action: Monitoring Report - Quarterly

HUMAN SERVICES AGENCY (Continued) **S101302830**

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 06/29/1989
Action: Notice of Reimbursement

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 10/16/2009
Action: File review

Global Id: T0607700218
Action Type: ENFORCEMENT
Date: 05/08/2015
Action: Staff Letter

LUST:
Global Id: T0607700218
Status: Open - Case Begin Date
Status Date: 04/01/1988

Global Id: T0607700218
Status: Open - Site Assessment
Status Date: 07/01/1989

Global Id: T0607700218
Status: Open - Site Assessment
Status Date: 12/30/1989

Global Id: T0607700218
Status: Open - Remediation
Status Date: 07/01/1998

Global Id: T0607700218
Status: Open - Site Assessment
Status Date: 12/19/2008

Global Id: T0607700218
Status: Open - Remediation
Status Date: 04/24/2020

LUST REG 5:
Name: HUMAN SERVICES AGENCY
Address: 145 SUTTER ST S
City: STOCKTON
Region: 5
Status: Remediation Plan
Case Number: 390296
Case Type: Drinking Water Aquifer affected
Substance: Not reported
Staff Initials: JLB

HUMAN SERVICES AGENCY (Continued) **S101302830**

Lead Agency: Local
Program: LUST
MTBE Code: 1

CORTESE:

Name:	HUMAN SERVICES AGENCY
Address:	145 SUTTER ST S
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700218
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	OPEN - REMEDIATION
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	HUMAN SERVICES AGENCY
edr_fadd1:	145 SUTTER
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390296

NOTIFY 65:

Name:	HUMAN SERVICES AGENCY
Address:	145 SUTTER ST S
City,State,Zip:	STOCKTON, CA 95202
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	09/08/1988
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	HUMAN SERVICES AGENCY

HUMAN SERVICES AGENCY (Continued) **S101302830**

Address: 145 SUTTER ST S
City,State,Zip: STOCKTON, CA 95202
Site ID: 195620
CERS ID: T0607700218
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

O104 **SNOW CLEANERS INC** **RCRA-SQG** **1000984994**
West **38 W SONORA ST** **CERS HAZ WASTE** **CAR000001032**
1/8-1/4 **STOCKTON, CA 95203** **CERS TANKS**
0.228 mi. **US AIRS**
1204 ft. **Site 2 of 7 in cluster O** **FINDS**
ECHO
Relative: **HAZNET**
Lower **CERS**
Actual: **HWTS**
16 ft.

RCRA-SQG:
Date Form Received by Agency: 1995-02-27 00:00:00.0
Handler Name: SNOW CLEANERS INC
Handler Address: 38 W SONORA ST
Handler City,State,Zip: STOCKTON, CA 95203
EPA ID: CAR000001032
Contact Name: HAROLD TURNER
Contact Address: 38 W SONORA ST
Contact City,State,Zip: STOCKTON, CA 95203
Contact Telephone: 209-547-1454
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 09
Land Type: Private
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: PO BOX 1849
Mailing City,State,Zip: STOCKTON, CA 95201
Owner Name: HAROLD M TURNER
Owner Type: Private
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No

SNOW CLEANERS INC (Continued) **1000984994**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:37:34.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:
Owner/Operator Indicator: Owner

SNOW CLEANERS INC (Continued) **1000984994**

Owner/Operator Name:	HAROLD M TURNER
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1849
Owner/Operator City,State,Zip:	STOCKTON, CA 95201
Owner/Operator Telephone:	209-547-1454
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1995-02-27 00:00:00.0
Handler Name: SNOW CLEANERS INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CERS HAZ WASTE:

Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	154401
CERS ID:	10183557
CERS Description:	Hazardous Waste Generator

CERS TANKS:

Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	154401
CERS ID:	10183557
CERS Description:	Aboveground Petroleum Storage

US AIRS (AFS):

Envid:	1000984994
Region Code:	09

SNOW CLEANERS INC (Continued) **1000984994**

County Code: CA077
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
D and B Number: Not reported
Facility Site Name: SNOW CLEANERS INC
Primary SIC Code: 7219
NAICS Code: 999999
Default Air Classification Code: MAJ
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS (AFS):
Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-01-27 00:00:00
Activity Status Date: 2015-02-19 14:54:17
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-01-27 00:00:00
Activity Status Date: 2015-02-26 13:13:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-03-26 00:00:00
Activity Status Date: 2015-04-03 13:13:24
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-04-16 00:00:00
Activity Status Date: 2015-04-20 13:13:12
Activity Group: Compliance Monitoring

SNOW CLEANERS INC (Continued) **1000984994**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2015-12-30 00:00:00
Activity Status Date: 2016-01-07 08:13:06
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-01-11 00:00:00
Activity Status Date: 2016-01-15 11:14:01
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:17:14
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:17:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

SNOW CLEANERS INC (Continued) **1000984994**

Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:05
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:23
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:30
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-08-08 08:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-08-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715

SNOW CLEANERS INC (Continued) **1000984994**

Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-12-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-01-30 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-02-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2015-04-16 00:00:00
Activity Status Date: 2015-04-21 11:13:08
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:17:27
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

SNOW CLEANERS INC (Continued) **1000984994**

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:02
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:16
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:28
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:36
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:18:58
Activity Group: Compliance Monitoring

SNOW CLEANERS INC (Continued) **1000984994**

Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:19:38
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:20:13
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:20:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:21:15
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits

SNOW CLEANERS INC (Continued) **1000984994**

Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:21:41
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-18 10:22:03
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2016-04-19 00:00:00
Activity Status Date: 2016-07-19 11:26:25
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2012-11-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASJV00006077N3076
Facility Registry ID: 110009551715
Air Operating Status Code: OPR
Default Air Classification Code: MAJ
Air Program: Title V Permits
Activity Date: 2013-12-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110009551715

SNOW CLEANERS INC (Continued) **1000984994**

Click Here:

Environmental Interest/Information System:

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS AIR POLLUTANT MAJOR
STATE MASTER
AIR MAJOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000984994
Registry ID:	110009551715
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009551715
Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203

HAZNET:

Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952030000
Contact:	HAROLD M TURNER
Telephone:	2095471454
Mailing Name:	Not reported
Mailing Address:	PO BOX 1849
Year:	2016
Gepaid:	CAR000001032
TSD EPA ID:	CAD980884183
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.4

SNOW CLEANERS INC (Continued) **1000984994**

Year:	2015
Gepaid:	CAR000001032
TSD EPA ID:	NVD980895338
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.545
Year:	2015
Gepaid:	CAR000001032
TSD EPA ID:	CAD980884183
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.25
Year:	2013
Gepaid:	CAR000001032
TSD EPA ID:	NVD980895338
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.45
Year:	2010
Gepaid:	CAR000001032
TSD EPA ID:	CA0000084517
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.6
Year:	2010
Gepaid:	CAR000001032
TSD EPA ID:	TXD077603371
CA Waste Code:	351 - Organic solids with halogens
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1.48
Year:	2010
Gepaid:	CAR000001032
TSD EPA ID:	NVT330010000
CA Waste Code:	291 - Latex waste
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.6
Year:	2010
Gepaid:	CAR000001032
TSD EPA ID:	NVT330010000
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.05
Year:	2008

SNOW CLEANERS INC (Continued) **1000984994**

Gepaid:	CAR000001032
TSD EPA ID:	CA0000084517
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	1
Year:	2007
Gepaid:	CAR000001032
TSD EPA ID:	TXD077603371
CA Waste Code:	342 - Organic liquids with metals (Alkaline solution (pH >= 12.5) with metals)
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.45

Click this hyperlink while viewing on your computer to access
30 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	1997
Gen EPA ID:	CAR000001032
Shipment Date:	19971210
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971210
Manifest ID:	97463179
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19971210
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971210
Manifest ID:	97463179
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968

SNOW CLEANERS INC (Continued) **1000984994**

Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19971118
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971118
Manifest ID:	97350231
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970917
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19970917
Manifest ID:	96855844
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970917
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19970917
Manifest ID:	96855844
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.195
Waste Quantity:	390
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970612
Creation Date:	12/4/1997 0:00:00
Receipt Date:	19970613
Manifest ID:	96623391
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.6825
Waste Quantity:	1365
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970303
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970305

SNOW CLEANERS INC (Continued) **1000984994**

Manifest ID:	96368272
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.78
Waste Quantity:	1560
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970303
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970305
Manifest ID:	96676104
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	- Not reported
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970114
Creation Date:	5/30/1997 0:00:00
Receipt Date:	Not reported
Manifest ID:	96466255
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970114
Creation Date:	5/30/1997 0:00:00
Receipt Date:	Not reported
Manifest ID:	96466255
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.175
Waste Quantity:	350
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2013
Gen EPA ID:	CAR000001032
Shipment Date:	20130708
Creation Date:	12/27/2013 22:15:22
Receipt Date:	20130801
Manifest ID:	000081885DAT
Trans EPA ID:	CAR000210617
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF CALIFORNIA LP
Trans 2 EPA ID:	CAD982523433
Trans 2 Name:	DILLARD ENVIRONMENTAL SERVICES
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF NEVADA LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.45

SNOW CLEANERS INC (Continued) **1000984994**

Waste Quantity:	900
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2003
Gen EPA ID:	CAR000001032
Shipment Date:	20031203
Creation Date:	7/30/2004 18:31:14
Receipt Date:	20031208
Manifest ID:	22959773
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	Not reported
Waste Quantity:	2560
Quantity Unit:	Not reported
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20031203
Creation Date:	7/30/2004 18:31:14
Receipt Date:	20031208
Manifest ID:	22959773
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.24
Waste Quantity:	480
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20031203
Creation Date:	7/30/2004 18:31:14
Receipt Date:	20031208
Manifest ID:	22959775
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0575
Waste Quantity:	115
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030725
Creation Date:	7/29/2004 7:44:50
Receipt Date:	20030731
Manifest ID:	22370032
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.45
Waste Quantity:	900
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030401
Creation Date:	7/12/2003 18:31:23
Receipt Date:	20030407
Manifest ID:	22325951
Trans EPA ID:	TXR000050930
Trans Name:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0575
Waste Quantity:	115
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030401
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22432687
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	- Not reported
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	Not reported
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030401
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22432687
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station

SNOW CLEANERS INC (Continued) **1000984994**

Quantity Tons:	0.0925
Waste Quantity:	185
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030401
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22432687
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	- Not reported
Quantity Tons:	0.8325
Waste Quantity:	1665
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2016
Gen EPA ID:	CAR000001032
Shipment Date:	20150804
Creation Date:	10/5/2015 22:15:07
Receipt Date:	20150817
Manifest ID:	000118688DAT
Trans EPA ID:	CAR000210617
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF CALIFORNIA LP
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980884183
Trans Name:	GENERAL ENVIRONMENTAL MGT LLC DBA PSC ENVIRONMENTAL SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.25
Waste Quantity:	500
Quantity Unit:	P
Additional Code 1:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20150313
Creation Date:	8/18/2015 22:15:10
Receipt Date:	20150320
Manifest ID:	000117635DAT
Trans EPA ID:	CAR000210617
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF CALIFORNIA LP
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF NEVADA LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.545
Waste Quantity:	1090
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2015
Gen EPA ID:	CAR000001032
Shipment Date:	20150804
Creation Date:	10/5/2015 22:15:07
Receipt Date:	20150817
Manifest ID:	000118688DAT
Trans EPA ID:	CAR000210617
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF CALIFORNIA LP
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980884183
Trans Name:	GENERAL ENVIRONMENTAL MGT LLC DBA PSC ENVIRONMENTAL SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.25
Waste Quantity:	500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 5:	Not reported
Shipment Date:	20150313
Creation Date:	8/18/2015 22:15:10
Receipt Date:	20150320
Manifest ID:	000117635DAT
Trans EPA ID:	CAR000210617
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF CALIFORNIA LP
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY ENVIRONMENTAL MANAGEMENT OF NEVADA LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.545
Waste Quantity:	1090
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2010
Gen EPA ID:	CAR000001032
Shipment Date:	20100802
Creation Date:	1/27/2011 18:30:23
Receipt Date:	20100816
Manifest ID:	003357445FLE
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	351 - Organic solids with halogens
RCRA Code:	D039
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	1.48
Waste Quantity:	2960
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20100802

SNOW CLEANERS INC (Continued) **1000984994**

Creation Date:	9/30/2010 18:30:56
Receipt Date:	20100806
Manifest ID:	003357446FLE
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.5
Waste Quantity:	1000
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D029
Additional Code 4:	D007
Additional Code 5:	Not reported
Shipment Date:	20100205
Creation Date:	11/30/2010 18:30:08
Receipt Date:	20100222
Manifest ID:	002370964SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY KLEEN SYSTEMS
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	291 - Latex waste
RCRA Code:	Not reported
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.6
Waste Quantity:	1200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20100205
Creation Date:	11/30/2010 18:30:08
Receipt Date:	20100222
Manifest ID:	002370964SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY KLEEN SYSTEMS
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

TSDF EPA ID: NVT330010000
Trans Name: US ECOLOGY NEVADA
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 221 - Waste oil and mixed oil
RCRA Code: Not reported
Meth Code: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons: 0.05
Waste Quantity: 100
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 20100115
Creation Date: 3/11/2010 18:30:23
Receipt Date: 20100121
Manifest ID: 002184453SKS
Trans EPA ID: TXR000050930
Trans Name: SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CA0000084517
Trans Name: SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code: F002
Meth Code: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons: 1.1
Waste Quantity: 2200
Quantity Unit: P
Additional Code 1: D040
Additional Code 2: D039
Additional Code 3: D029
Additional Code 4: D007
Additional Code 5: Not reported

Additional Info:
Year: 2001
Gen EPA ID: CAR000001032

Shipment Date: 20011101
Creation Date: 1/16/2002 0:00:00
Receipt Date: 20011108
Manifest ID: 21477068
Trans EPA ID: SCR000075150
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CA0000084517
Trans Name: Not reported
TSDF Alt EPA ID: Not reported

SNOW CLEANERS INC (Continued) **1000984994**

TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20011101
Creation Date:	1/16/2002 0:00:00
Receipt Date:	20011108
Manifest ID:	21477068
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010417
Creation Date:	7/10/2001 0:00:00
Receipt Date:	20010423
Manifest ID:	20332779
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.68
Waste Quantity:	1360
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1999
Gen EPA ID:	CAR000001032
Shipment Date:	19991006
Creation Date:	12/16/1999 0:00:00
Receipt Date:	19991012
Manifest ID:	99024757
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.42
Waste Quantity:	840
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19990826
Creation Date:	11/18/1999 0:00:00
Receipt Date:	19990830
Manifest ID:	99052823
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19990701

SNOW CLEANERS INC (Continued) **1000984994**

Creation Date:	9/21/1999 0:00:00
Receipt Date:	19990706
Manifest ID:	99236470
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.07
Waste Quantity:	140
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19990701
Creation Date:	8/19/1999 0:00:00
Receipt Date:	19990706
Manifest ID:	99271140
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19990311
Creation Date:	5/17/1999 0:00:00
Receipt Date:	19990315
Manifest ID:	98869763
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.195
Waste Quantity:	390
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAR000001032
Shipment Date:	19951226
Creation Date:	7/29/1996 0:00:00
Receipt Date:	19951228
Manifest ID:	95511845
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951226
Creation Date:	7/29/1996 0:00:00
Receipt Date:	19951228
Manifest ID:	95511845
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station

SNOW CLEANERS INC (Continued) **1000984994**

Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951130
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951201
Manifest ID:	95814715
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19951019
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951023
Manifest ID:	95758339
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Shipment Date:	19951019
Creation Date:	7/26/1996 0:00:00
Receipt Date:	19951023
Manifest ID:	95758339
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950810
Creation Date:	4/3/1996 0:00:00
Receipt Date:	19950816
Manifest ID:	95549653
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19950726
Creation Date:	4/3/1996 0:00:00
Receipt Date:	19950731
Manifest ID:	95636865
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950

SNOW CLEANERS INC (Continued) **1000984994**

Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.585
Waste Quantity:	1170
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950726
Creation Date:	4/3/1996 0:00:00
Receipt Date:	19950731
Manifest ID:	95636865
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0975
Waste Quantity:	195
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950602
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950607
Manifest ID:	95415767
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950602
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950607
Manifest ID:	95415767
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.195
Waste Quantity:	390
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2004
Gen EPA ID:	CAR000001032
Shipment Date:	20040715
Creation Date:	11/5/2004 18:32:00
Receipt Date:	20040722
Manifest ID:	23509634
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	- Not reported
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	Not reported
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Shipment Date:	20040715
Creation Date:	11/5/2004 18:32:00
Receipt Date:	20040722
Manifest ID:	23509634
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.7225
Waste Quantity:	1445
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2002
Gen EPA ID:	CAR000001032

Shipment Date:	20020826
Creation Date:	1/27/2003 18:31:12
Receipt Date:	20020903
Manifest ID:	21747928
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	1.4625
Waste Quantity:	2925
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20020826
Creation Date:	1/27/2003 18:31:12
Receipt Date:	20020903
Manifest ID:	21970741
Trans EPA ID:	SCR000075150

SNOW CLEANERS INC (Continued) **1000984994**

Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0575
Waste Quantity:	115
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20020503
Creation Date:	7/17/2002 18:35:51
Receipt Date:	20020513
Manifest ID:	21560695
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0575
Waste Quantity:	115
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20020503
Creation Date:	7/17/2002 18:34:52
Receipt Date:	20020513
Manifest ID:	21591337
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002

SNOW CLEANERS INC (Continued) **1000984994**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.525
Waste Quantity:	1050
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2007
Gen EPA ID:	CAR000001032
Shipment Date:	20071009
Creation Date:	3/18/2008 18:30:12
Receipt Date:	20071022
Manifest ID:	000636266SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD TRANSPORT INC
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	D040
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.9
Waste Quantity:	1800
Quantity Unit:	P
Additional Code 1:	D039
Additional Code 2:	D007
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070514
Creation Date:	12/28/2007 18:30:19
Receipt Date:	20070525
Manifest ID:	000283980SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	D040
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.08
Waste Quantity:	160

SNOW CLEANERS INC (Continued) **1000984994**

Quantity Unit:	P
Additional Code 1:	D039
Additional Code 2:	D007
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070514
Creation Date:	12/28/2007 18:30:19
Receipt Date:	20070525
Manifest ID:	000283980SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	D040
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	1.16
Waste Quantity:	2320
Quantity Unit:	P
Additional Code 1:	D039
Additional Code 2:	D007
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070507
Creation Date:	12/20/2007 18:30:34
Receipt Date:	20070518
Manifest ID:	000276789SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	D040
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.4
Waste Quantity:	800
Quantity Unit:	P
Additional Code 1:	D039
Additional Code 2:	D007
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Shipment Date:	20070507
Creation Date:	10/10/2007 18:30:16
Receipt Date:	20070508
Manifest ID:	000276791SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.16
Waste Quantity:	320
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20070507
Creation Date:	10/10/2007 18:30:16
Receipt Date:	20070508
Manifest ID:	000276791SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.12
Waste Quantity:	240
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20070507
Creation Date:	12/20/2007 18:30:34
Receipt Date:	20070518
Manifest ID:	000276789SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791

SNOW CLEANERS INC (Continued) **1000984994**

Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	D040
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.52
Waste Quantity:	1040
Quantity Unit:	P
Additional Code 1:	D039
Additional Code 2:	D007
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070117
Creation Date:	8/28/2007 18:30:13
Receipt Date:	20070130
Manifest ID:	000007790SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	OKD981588791
Trans 2 Name:	TRIAD
TSDF EPA ID:	TXD077603371
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	342 - Organic liquids with metals (see 121
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.45
Waste Quantity:	900
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070117
Creation Date:	4/19/2007 18:32:27
Receipt Date:	20070119
Manifest ID:	000196292CEX
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002

SNOW CLEANERS INC (Continued) **1000984994**

Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	1.125
Waste Quantity:	2250
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20070117
Creation Date:	4/19/2007 18:32:27
Receipt Date:	20070119
Manifest ID:	000196292CEX
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.15
Waste Quantity:	300
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2008
Gen EPA ID:	CAR000001032
Shipment Date:	20081218
Creation Date:	2/2/2009 18:30:25
Receipt Date:	20081223
Manifest ID:	001586660SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	1

SNOW CLEANERS INC (Continued) **1000984994**

Waste Quantity:	2000
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1998
Gen EPA ID:	CAR000001032
Shipment Date:	19981231
Creation Date:	3/17/1999 0:00:00
Receipt Date:	19990111
Manifest ID:	98658443
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19981231
Creation Date:	3/17/1999 0:00:00
Receipt Date:	19990111
Manifest ID:	98658443
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.105
Waste Quantity:	210
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19981022
Creation Date:	1/13/1999 0:00:00
Receipt Date:	19981029
Manifest ID:	98567115
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	SCD987574647
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980824
Creation Date:	11/2/1998 0:00:00
Receipt Date:	19980827
Manifest ID:	97489492
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.105
Waste Quantity:	210
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980610
Creation Date:	8/3/1998 0:00:00
Receipt Date:	19980616
Manifest ID:	98187408
Trans EPA ID:	ILD984908202
Trans Name:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19980513
Creation Date:	7/15/1998 0:00:00
Receipt Date:	19980515
Manifest ID:	97372059
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19980218
Creation Date:	4/16/1998 0:00:00
Receipt Date:	19980224
Manifest ID:	97476560
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station

SNOW CLEANERS INC (Continued) **1000984994**

Quantity Tons:	0.35
Waste Quantity:	700
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2006
Gen EPA ID:	CAR000001032
Shipment Date:	20060403
Creation Date:	7/27/2006 18:33:32
Receipt Date:	20060404
Manifest ID:	24624154
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.225
Waste Quantity:	450
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20060403
Creation Date:	7/27/2006 18:33:32
Receipt Date:	20060404
Manifest ID:	24624154
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.75
Waste Quantity:	1500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2005
Gen EPA ID:	CAR000001032
Shipment Date:	20050107
Creation Date:	3/17/2005 18:34:39
Receipt Date:	20050113
Manifest ID:	24114222
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.4875
Waste Quantity:	975
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2000
Gen EPA ID:	CAR000001032
Shipment Date:	20001219
Creation Date:	3/6/2001 0:00:00
Receipt Date:	20010102
Manifest ID:	20380365
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20001219
Creation Date:	3/6/2001 0:00:00
Receipt Date:	20001221
Manifest ID:	20541387
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20000825
Creation Date:	11/13/2000 0:00:00
Receipt Date:	20000901
Manifest ID:	20020702
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	- Not reported
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.01
Waste Quantity:	20
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20000825
Creation Date:	11/13/2000 0:00:00
Receipt Date:	20000901
Manifest ID:	20020702
Trans EPA ID:	SCR000075150

SNOW CLEANERS INC (Continued) **1000984994**

Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.49
Waste Quantity:	980
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20000627
Creation Date:	8/14/2000 0:00:00
Receipt Date:	20000706
Manifest ID:	20014991
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20000627
Creation Date:	8/16/2000 0:00:00
Receipt Date:	20000706
Manifest ID:	20014976
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002

SNOW CLEANERS INC (Continued) **1000984994**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2
Waste Quantity:	400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1996
Gen EPA ID:	CAR000001032
Shipment Date:	19961211
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961216
Manifest ID:	96467420
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.175
Waste Quantity:	350
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961211
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19961216
Manifest ID:	96467420
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0975
Waste Quantity:	195
Quantity Unit:	P
Additional Code 1:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961104
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19961108
Manifest ID:	96493507
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.105
Waste Quantity:	210
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961104
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19961108
Manifest ID:	96493507
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.4875
Waste Quantity:	975
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19961028
Creation Date:	5/21/1997 0:00:00
Receipt Date:	19961030
Manifest ID:	96491961

SNOW CLEANERS INC (Continued) **1000984994**

Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19960912
Creation Date:	5/30/1997 0:00:00
Receipt Date:	19960916
Manifest ID:	96510231
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.585
Waste Quantity:	1170
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19960912
Creation Date:	5/30/1997 0:00:00
Receipt Date:	19960916
Manifest ID:	96510231
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l

SNOW CLEANERS INC (Continued) **1000984994**

RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960618
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19960624
Manifest ID:	96092257
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.39
Waste Quantity:	780
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19960618
Creation Date:	5/20/1997 0:00:00
Receipt Date:	19960624
Manifest ID:	96092257
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0975
Waste Quantity:	195
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Additional Code 5:	Not reported
Shipment Date:	19960501
Creation Date:	10/29/1996 0:00:00
Receipt Date:	19960503
Manifest ID:	96257319
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.
RCRA Code:	F005
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.056
Waste Quantity:	112
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	154401
CERS ID:	10183557
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	154401
Site Name:	SNOW CLEANERS INC
Violation Date:	06-05-2014
Citation:	HSC 6.95 25504(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25504(a)
Violation Description:	Failure to complete and/or submit hazardous material inventory forms for all reportable hazardous materials on site.
Violation Notes:	Returned to compliance on 07/01/2014. A 55 gallon drum of MultiPhase was found on site and has not been reported. Any material that meets or exceeds the reportable quantity shall be reported in the facility's business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, add the materials to the hazardous material inventory, and submit to the EHD for approval. This is a minor violation.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	154401
Site Name:	SNOW CLEANERS INC
Violation Date:	06-26-2020
Citation:	22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter

SNOW CLEANERS INC (Continued) **1000984994**

	12, Section(s) 66262.12
Violation Description:	Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes:	OBSERVATION: This business has an inactive hazardous waste ID number in the California Department of Toxic Substances Control (DTSC) database. The inactive number is CAR000001032. REGULATION GUIDANCE: A hazardous waste generator shall not treat, store, dispose of, transport or offer for transportation, hazardous waste without having received an Environmental Protection Agency (EPA) Identification (ID) Number. A State EPA ID number is required for generators of less than 100 kg RCRA hazardous waste per month, less than 1 kg of acutely hazardous waste per month or any amount of non-RCRA hazardous waste. ID numbers are unique to a business and site location. CORRECTIVE ACTION: Go to the DTSC web site at https://dtsc.ca.gov/apply-for-hazardous-waste-epa-id-number/ to reactivate your ID number . Immediately reactivate your ID number and submit evidence to the San Joaquin County Environmental Health Department within 30 days.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	154401
Site Name:	SNOW CLEANERS INC
Violation Date:	06-26-2020
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes:	Returned to compliance on 07/27/2020. OBSERVATION: The following open hazardous waste storage containers were observed on-site: Four 40-gallon containers of spent dry cleaning solvent had lids that were not secured with barrel bands. REGULATION GUIDANCE: A container holding hazardous waste shall always be closed during transfer and storage, except when it is necessary to add or remove waste. CORRECTIVE ACTION: Immediately close these containers and ensure all hazardous waste containers are closed when not adding or removing waste. Provide a corrective action statement and supporting documentation to the San Joaquin County Environmental Health Department within 30 days.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	154401
Site Name:	SNOW CLEANERS INC
Violation Date:	06-26-2020
Citation:	HSC 6.11 25404(e)(4) - California Health and Safety Code, Chapter 6.11, Section(s) 25404(e)(4)
Violation Description:	Failure to report program data electronically.
Violation Notes:	Returned to compliance on 07/27/2020. OBSERVATION: This business's EPA number is incorrect in the business activities section of the

SNOW CLEANERS INC (Continued) **1000984994**

California Environmental Reporting System (CERS) website. REGULATION GUIDANCE: Each regulated business shall report program data electronically on the CERS website. CORRECTIVE ACTION: Immediately update the CERS website with the correct EPA ID number, CAR000001032. Provide a corrective action statement to the San Joaquin County Environmental Health Department within 30 days.

Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 154401
Site Name: SNOW CLEANERS INC
Violation Date: 06-05-2014
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 07/01/2014. The Consolidated Emergency Response/Contingency Plan and Employee Training Plan was not uploaded to CERS. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This is a minor violation.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-26-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by July 26, 2020 . To minimize person to person contact EHD is choosing to write the name of person receiving the report instead of having them sign. Waste streams found: Dry cleaning machine filters, Dry cleaning spent solvent. One box of waste dry cleaning machine filters was labeled as hazardous waste during the inspection.
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-05-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and upload the submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by July 5, 2014. Consent to perform the inspection, take photos and collect samples was given by Plant Engineer and Jose Gilbert; Dry Cleaner. A copy of photos taken at the time of inspection were provided to Jose Gilbert; Dry Cleaner. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be

SNOW CLEANERS INC (Continued) **1000984994**

sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields.
Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Enforcement Action:
Site ID: 154401
Site Name: SNOW CLEANERS INC
Site Address: 38 W SONORA ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 06-05-2014
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HMRRP
Enf Action Source: CERS

Coordinates:
Site ID: 154401
Facility Name: SNOW CLEANERS INC
Env Int Type Code: HWG
Program ID: 10183557
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 37.947880
Longitude: -121.290690

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Clyde H. Carter Jr.
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: HAROLD TURNER
Entity Title: Not reported
Affiliation Address: 38 W SONORA ST
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Harold And Lorraine Turner
Entity Title: Not reported
Affiliation Address: PO Box 1849

SNOW CLEANERS INC (Continued) **1000984994**

Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95201
Affiliation Phone:	(209) 649-4883
Affiliation Type Desc:	Environmental Contact
Entity Name:	CLYDE CARTER
Entity Title:	Not reported
Affiliation Address:	5507 WILKINS AVE
Affiliation City:	OAKDALE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	Clyde Carter
Entity Title:	Not reported
Affiliation Address:	5507 Wilkins Ave
Affiliation City:	Oakdale
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95361
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	SNOW CLEANERS INC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	PO BOX 1849
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95201
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Clyde H. Carter Jr.
Entity Title:	Plant Engineer
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner

SNOW CLEANERS INC (Continued) **1000984994**

Entity Name:	HAROLD & LORRAINE TURNER
Entity Title:	Not reported
Affiliation Address:	POBOX 1849
Affiliation City:	STOCKTON
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205-6232
Affiliation Phone:	(209) 468-3420
Affiliation Type Desc:	Legal Owner
Entity Name:	TURNER, HAROLD
Entity Title:	Not reported
Affiliation Address:	PO BOX 1849
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95201
Affiliation Phone:	(209) 649-4883
Affiliation Type Desc:	Operator
Entity Name:	Clyde Carter
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(209) 649-4891
Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Site ID:	154401
CERS ID:	110009551715
CERS Description:	US EPA Air Emission Inventory System (EIS)

Violations:

Site ID:	154401
Site Name:	SNOW CLEANERS INC
Violation Date:	06-05-2014
Citation:	HSC 6.95 25504(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25504(a)
Violation Description:	Failure to complete and/or submit hazardous material inventory forms for all reportable hazardous materials on site.
Violation Notes:	Returned to compliance on 07/01/2014. A 55 gallon drum of MultiPhase was found on site and has not been reported. Any material that meets or exceeds the reportable quantity shall be reported in the facility's

SNOW CLEANERS INC (Continued) **1000984994**

business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, add the materials to the hazardous material inventory, and submit to the EHD for approval. This is a minor violation.

Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 154401
Site Name: SNOW CLEANERS INC
Violation Date: 06-26-2020
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: OBSERVATION: This business has an inactive hazardous waste ID number in the California Department of Toxic Substances Control (DTSC) database. The inactive number is CAR000001032. REGULATION GUIDANCE: A hazardous waste generator shall not treat, store, dispose of, transport or offer for transportation, hazardous waste without having received an Environmental Protection Agency (EPA) Identification (ID) Number. A State EPA ID number is required for generators of less than 100 kg RCRA hazardous waste per month, less than 1 kg of acutely hazardous waste per month or any amount of non-RCRA hazardous waste. ID numbers are unique to a business and site location. CORRECTIVE ACTION: Go to the DTSC web site at https://dtsc.ca.gov/apply-for-hazardous-waste-epa-id-number/ to reactivate your ID number . Immediately reactivate your ID number and submit evidence to the San Joaquin County Environmental Health Department within 30 days.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 154401
Site Name: SNOW CLEANERS INC
Violation Date: 06-26-2020
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description: Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes: Returned to compliance on 07/27/2020. OBSERVATION: The following open hazardous waste storage containers were observed on-site: Four 40-gallon containers of spent dry cleaning solvent had lids that were not secured with barrel bands. REGULATION GUIDANCE: A container holding hazardous waste shall always be closed during transfer and storage, except when it is necessary to add or remove waste. CORRECTIVE ACTION: Immediately close these containers and ensure all hazardous waste containers are closed when not adding or removing waste. Provide a corrective action statement and supporting documentation to the San Joaquin County Environmental Health Department within 30 days.

SNOW CLEANERS INC (Continued) **1000984994**

Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 154401
Site Name: SNOW CLEANERS INC
Violation Date: 06-26-2020
Citation: HSC 6.11 25404(e)(4) - California Health and Safety Code, Chapter 6.11, Section(s) 25404(e)(4)
Violation Description: Failure to report program data electronically.
Violation Notes: Returned to compliance on 07/27/2020. OBSERVATION: This business's EPA number is incorrect in the business activities section of the California Environmental Reporting System (CERS) website. REGULATION GUIDANCE: Each regulated business shall report program data electronically on the CERS website. CORRECTIVE ACTION: Immediately update the CERS website with the correct EPA ID number, CAR000001032. Provide a corrective action statement to the San Joaquin County Environmental Health Department within 30 days.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 154401
Site Name: SNOW CLEANERS INC
Violation Date: 06-05-2014
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 07/01/2014. The Consolidated Emergency Response/Contingency Plan and Employee Training Plan was not uploaded to CERS. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This is a minor violation.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-26-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by July 26, 2020 . To minimize person to person contact EHD is choosing to write the name of person receiving the report instead of having them sign. Waste streams found: Dry cleaning machine filters, Dry cleaning spent solvent. One box of waste dry cleaning machine filters was labeled as hazardous waste during the inspection.
Eval Division: San Joaquin County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-05-2014

SNOW CLEANERS INC (Continued) **1000984994**

Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Complete and upload the submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by July 5, 2014. Consent to perform the inspection, take photos and collect samples was given by Plant Engineer and Jose Gilbert; Dry Cleaner. A copy of photos taken at the time of inspection were provided to Jose Gilbert; Dry Cleaner. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields.
Eval Division: San Joaquin County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Enforcement Action:
Site ID: 154401
Site Name: SNOW CLEANERS INC
Site Address: 38 W SONORA ST
Site City: STOCKTON
Site Zip: 95203
Enf Action Date: 06-05-2014
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes: Not reported
Enf Action Division: San Joaquin County Environmental Health
Enf Action Program: HMRRP
Enf Action Source: CERS

Coordinates:
Site ID: 154401
Facility Name: SNOW CLEANERS INC
Env Int Type Code: HWG
Program ID: 10183557
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 37.947880
Longitude: -121.290690

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Clyde H. Carter Jr.
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: HAROLD TURNER

SNOW CLEANERS INC (Continued) **1000984994**

Entity Title: Not reported
Affiliation Address: 38 W SONORA ST
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Harold And Lorraine Turner
Entity Title: Not reported
Affiliation Address: PO Box 1849
Affiliation City: Stockton
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95201
Affiliation Phone: (209) 649-4883

Affiliation Type Desc: Environmental Contact
Entity Name: CLYDE CARTER
Entity Title: Not reported
Affiliation Address: 5507 WILKINS AVE
Affiliation City: OAKDALE
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: Clyde Carter
Entity Title: Not reported
Affiliation Address: 5507 Wilkins Ave
Affiliation City: Oakdale
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95361
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: SNOW CLEANERS INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: PO BOX 1849
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95201
Affiliation Phone: Not reported

SNOW CLEANERS INC (Continued) **1000984994**

Affiliation Type Desc: Identification Signer
Entity Name: Clyde H. Carter Jr.
Entity Title: Plant Engineer
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: HAROLD & LORRAINE TURNER
Entity Title: Not reported
Affiliation Address: POBOX 1849
Affiliation City: STOCKTON
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District
Entity Name: San Joaquin Cnty Env Health
Entity Title: Not reported
Affiliation Address: 1868 East Hazelton Avenue
Affiliation City: Stockton
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95205-6232
Affiliation Phone: (209) 468-3420

Affiliation Type Desc: Legal Owner
Entity Name: TURNER, HAROLD
Entity Title: Not reported
Affiliation Address: PO BOX 1849
Affiliation City: STOCKTON
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95201
Affiliation Phone: (209) 649-4883

Affiliation Type Desc: Operator
Entity Name: Clyde Carter
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (209) 649-4891

HWTS:
Name: SNOW CLEANERS INC
Address: 38 W SONORA ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 952030000
EPA ID: CAR000001032

SNOW CLEANERS INC (Continued) **1000984994**

Inactive Date:	06/30/2015
Create Date:	12/08/1995
Last Act Date:	01/27/2016
Mailing Name:	Not reported
Mailing Address:	PO BOX 1849
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 952011849
Owner Name:	HAROLD M TURNER
Owner Address:	PO BOX 1849
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA 952011849
Contact Name:	HAROLD M TURNER
Contact Address:	PO BOX 1849
Contact Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952011849

NAICS:

EPA ID:	CAR000001032
Create Date:	2002-03-14 16:36:30.000
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
Issued EPA ID Date:	1995-12-08 00:00:00
Inactive Date:	2015-06-30 00:00:00
Facility Name:	SNOW CLEANERS INC
Facility Address:	38 W SONORA ST
Facility Address 2:	Not reported
Facility City:	STOCKTON
Facility County:	Not reported
Facility State:	CA
Facility Zip:	952030000

O105 **MORTON PAINT CO** **UST** **U004260731**
West **38 W SONORA ST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.228 mi.
1204 ft. **Site 3 of 7 in cluster O**

Relative: **Lower**

Actual: **16 ft.**

UST SAN JOAQUIN:

Name:	MORTON PAINT CO
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Region:	SJ
Facility Id:	FA0005982
Mail Address:	PO BOX 591AS ST
Mail Address 2:	Not reported
Mail Care of:	WILLIAM RUFFINI
Mail City,St,Zip:	STOCKTON, CA 95201
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	8000
Product Type Desc:	09 - OTHER PETROLEUM
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported

MORTON PAINT CO (Continued) **U004260731**

CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 10
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 2
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 3
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported

MORTON PAINT CO (Continued) **U004260731**

CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 4
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 5
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 6
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported

MORTON PAINT CO (Continued) **U004260731**

CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 7
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 8
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported
CERS ID: Not reported
Cross Ref Tank ID: Not reported
LEA ID: 9
Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Tank Rec ID: Not reported
Tank Number: 9
Tank Status: 02 - Inactive, non-billable
Tank Capacity: 8000
Product Type Desc: 09 - OTHER PETROLEUM
Program Element: 2380
Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form: (none)
CAS#: Not reported

MORTON PAINT CO (Continued) **U004260731**

CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

O106 **MORTON PAINT COMPANY** **SWEEPS UST** **S101625462**
West **38 W SONORA ST** **CA FID UST** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.228 mi.
1204 ft. **Site 4 of 7 in cluster O**

Relative: **Lower**

Actual: **16 ft.**

SWEEPS UST:

Name:	MORTON PAINT COMPANY
Address:	38 W SONORA ST
City:	STOCKTON
Status:	Active
Comp Number:	1254
Number:	1
Board Of Equalization:	44-024606
Referral Date:	03-23-92
Action Date:	03-23-92
Created Date:	07-07-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

Name:	MORTON PAINT COMPANY
Address:	38 W SONORA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1254
Number:	Not reported
Board Of Equalization:	44-024606
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001254-000001
Tank Status:	Not reported
Capacity:	8000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	CHEMICAL PRO
Number Of Tanks:	10

Name:	MORTON PAINT COMPANY
Address:	38 W SONORA ST

MORTON PAINT COMPANY (Continued) **S101625462**

City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000002
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000003
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT
Content: CHEMICAL PRO
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000004
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT
Content: CHEMICAL PRO
Number Of Tanks: Not reported

MORTON PAINT COMPANY (Continued) **S101625462**

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000005
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000006
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT
Content: CHEMICAL PRO
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000007
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT

MORTON PAINT COMPANY (Continued) **S101625462**

Content: CHEMICAL PRO
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000008
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: AVIA. GAS
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000009
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT
Content: CHEMICAL PRO
Number Of Tanks: Not reported

Name: MORTON PAINT COMPANY
Address: 38 W SONORA ST
City: STOCKTON
Status: Not reported
Comp Number: 1254
Number: Not reported
Board Of Equalization: 44-024606
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001254-000010
Tank Status: Not reported
Capacity: 8000

MORTON PAINT COMPANY (Continued) **S101625462**

Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: AVIA. GAS
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39003374
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094664541
Mail To: Not reported
Mailing Address: P O BOX 591
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

O107 **SNOW CLEANERS INC** **HIST UST** **S113066813**
West **38 WEST SONORA STREET** **HAZNET** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **HWTS**
0.228 mi.
1204 ft. **Site 5 of 7 in cluster O**

Relative: **Lower**
Actual: **16 ft.**

HIST UST:
Name: MORTON PAINT CO
Address: 38 WEST SONORA ST
City,State,Zip: STOCKTON, CA 95203
File Number: 0002B50D
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002B50D.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Not reported

SNOW CLEANERS INC (Continued) **S113066813**

Click here for Geo Tracker PDF:

HAZNET:

Name:	SNOW CLEANERS INC
Address:	38 WEST SONORA STREET
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952030000
Contact:	HAROLD TURNER
Telephone:	2095471454
Mailing Name:	Not reported
Mailing Address:	PO BOX 1849
Year:	1995
Gepaid:	CAL000117094
TSD EPA ID:	CAT000613950
CA Waste Code:	-
Disposal Method:	H01 - Transfer Station
Tons:	0.8775
Year:	1995
Gepaid:	CAL000117094
TSD EPA ID:	CAT000613950
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H01 - Transfer Station
Tons:	0.78
Year:	1994
Gepaid:	CAL000117094
TSD EPA ID:	CAT000613950
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H01 - Transfer Station
Tons:	1.1775

Additional Info:

Year:	1994
Gen EPA ID:	CAL000117094
Shipment Date:	19941215
Creation Date:	10/19/1995 0:00:00
Receipt Date:	19941216
Manifest ID:	93657411
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.585
Waste Quantity:	1170
Quantity Unit:	P

SNOW CLEANERS INC (Continued) **S113066813**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19941118
Creation Date:	10/19/1995 0:00:00
Receipt Date:	19941122
Manifest ID:	93657454
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2925
Waste Quantity:	585
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19941027
Creation Date:	10/19/1995 0:00:00
Receipt Date:	19941031
Manifest ID:	93657474
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.195
Waste Quantity:	390
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19941027
Creation Date:	10/19/1995 0:00:00
Receipt Date:	19941031

SNOW CLEANERS INC (Continued) **S113066813**

Manifest ID:	93657474
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.105
Waste Quantity:	210
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAL000117094
Shipment Date:	19950223
Creation Date:	3/29/1996 0:00:00
Receipt Date:	19950224
Manifest ID:	93657394
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613950
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.78
Waste Quantity:	1560
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950119
Creation Date:	10/19/1995 0:00:00
Receipt Date:	19950120
Manifest ID:	93657448
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported

SNOW CLEANERS INC (Continued) **S113066813**

TSDF EPA ID:	CAT000613950
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	- Not reported
RCRA Code:	D007
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.8775
Waste Quantity:	1755
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	SNOW CLEANERS INC
Address:	38 WEST SONORA STREET
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952030000
EPA ID:	CAL000117094
Inactive Date:	06/01/1997
Create Date:	10/13/1994
Last Act Date:	04/08/1998
Mailing Name:	Not reported
Mailing Address:	PO BOX 1849
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 952010000
Owner Name:	HAROLD & LORRAINE TURNER
Owner Address:	PO BOX 1849
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA --
Contact Name:	HAROLD TURNER
Contact Address:	38 WEST SONORA STREET
Contact Address 2:	Not reported
City,State,Zip:	STOCKTON, CA --

O108 **SNOW CLEANERSINC** **HIST UST** **U001603285**
West **38 W SONORA ST** **EMI** **N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.228 mi.
1204 ft. **Site 6 of 7 in cluster O**

Relative:
Lower

Actual:
16 ft.

HIST UST:

Name:	MORTON PAINT CO.
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000042134
Facility Type:	Other
Other Type:	MANUFACTURING
Contact Name:	CHRISTOPHER POON
Telephone:	2094664541
Owner Name:	U.S. CHEMICAL & PLASTICS

SNOW CLEANERSINC (Continued) **U001603285**

Owner Address:	1446 W. TUSCARAWAS ST.
Owner City,St,Zip:	CANTON, OH 44702
Total Tanks:	0010
Tank Num:	001
Container Num:	10
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor
Tank Num:	002
Container Num:	1
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor
Tank Num:	003
Container Num:	9
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor
Tank Num:	004
Container Num:	6
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor
Tank Num:	005
Container Num:	7
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor
Tank Num:	006
Container Num:	8
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor

SNOW CLEANERSINC (Continued) **U001603285**

Tank Num:	007
Container Num:	4
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor

Tank Num:	008
Container Num:	3
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor

Tank Num:	009
Container Num:	5
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor

Tank Num:	010
Container Num:	2
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	0.250
Leak Detection:	Visual, Stock Inventor

EMI:

Name:	SNOW CLEANERSINC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2011
County Code:	39
Air Basin:	SJV
Facility ID:	3076
Air District Name:	SJU
SIC Code:	7216
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.4980000108
Reactive Organic Gases Tons/Yr:	4.4980000108
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

SNOW CLEANERSINC (Continued) **U001603285**

Name:	SNOW CLEANERSINC
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Year:	2012
County Code:	39
Air Basin:	SJV
Facility ID:	3076
Air District Name:	SJU
SIC Code:	7216
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3.2484499216
Reactive Organic Gases Tons/Yr:	3.2484499216
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

O109 **SNOW CLEANERS INC** **AST** **U001603284**
West **38 W SONORA ST** **HIST UST** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **DRYCLEANERS**
0.228 mi. **CIWQS**
1204 ft. **Site 7 of 7 in cluster O**

Relative: **Lower**

Actual: **16 ft.**

AST:

Name:	SNOW CLEANERS INC
Address:	38 W SONORA ST
City/Zip:	STOCKTON,95203
Certified Unified Program Agencies:	Not reported
Owner:	TURNER, HAROLD
Total Gallons:	Not reported
CERSID:	10183557
Facility ID:	Not reported
Business Name:	SNOW CLEANERS INC
Phone:	(209) 547-1454
Fax:	(209) 466-7669
Mailing Address:	PO BOX 1849
Mailing Address City:	STOCKTON
Mailing Address State:	CA
Mailing Address Zip Code:	95201
Operator Name:	Clyde Carter
Operator Phone:	(209) 649-4891
Owner Phone:	(209) 649-4883
Owner Mail Address:	PO BOX 1849
Owner State:	CA
Owner Zip Code:	95201
Owner Country:	United States
Property Owner Name:	Harold And Lorraine Turner
Property Owner Phone:	209-649-4883
Property Owner Mailing Address:	PO Box 1849
Property Owner City:	Stockton
Property Owner Stat :	CA
Property Owner Zip Code:	95201
Property Owner Country:	United States
EPAID:	CA0000084517

SNOW CLEANERS INC (Continued) **U001603284**

HIST UST:

Name:	MORTON PAINT CO
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
File Number:	0002FF54
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FF54.pdf
Region:	STATE
Facility ID:	00000008382
Facility Type:	Other
Other Type:	PAINT MFG.
Contact Name:	JOHN JOHNSON
Telephone:	2094664541
Owner Name:	MORTON PAINT COMPANY
Owner Address:	38 W. SONORA ST.
Owner City,St,Zip:	STOCKTON, CA 95203
Total Tanks:	0010
Tank Num:	001
Container Num:	#01
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	002
Container Num:	#03
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	#04
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	004
Container Num:	#05
Year Installed:	1983
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	005
Container Num:	#66
Year Installed:	1983
Tank Capacity:	00008000

SNOW CLEANERS INC (Continued) **U001603284**

Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 006
Container Num: #07
Year Installed: 1983
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 1/4
Leak Detection: None

Tank Num: 007
Container Num: #08
Year Installed: 1983
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 1/4
Leak Detection: None

Tank Num: 008
Container Num: #10
Year Installed: 1983
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 1/4
Leak Detection: None

Tank Num: 009
Container Num: #09
Year Installed: 1983
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 1/4
Leak Detection: None

Tank Num: 010
Container Num: #02
Year Installed: 1983
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 1/4
Leak Detection: None

Click here for Geo Tracker PDF:

DRYCLEANERS:
Name: SNOW CLEANERS INC
Address: 38 W SONORA ST
City,State,Zip: STOCKTON, CA 952030000
EPA Id: CAR000001032

SNOW CLEANERS INC (Continued) **U001603284**

NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	12/08/1995
Facility Active:	No
Inactive Date:	06/30/2015
Facility Addr2:	Not reported
Owner Name:	HAROLD M TURNER
Owner Address:	PO BOX 1849
Owner Address 2:	Not reported
Owner Telephone:	2095471454
Contact Name:	HAROLD M TURNER
Contact Address:	PO BOX 1849
Contact Address 2:	Not reported
Contact Telephone:	2095471454
Contact Fax:	0
Mailing Name:	Not reported
Mailing Address 1:	PO BOX 1849
Mailing Address 2:	Not reported
Mailing City:	STOCKTON
Mailing State:	CA
Mailing Zip:	952011849
Owner Fax:	0
Region Code:	1
Latitude:	37.948495
Longitude:	-121.290481

CIWQS:

Name:	MORTON PAINT CO
Address:	38 W SONORA ST
City,State,Zip:	STOCKTON, CA 95203
Agency:	US Chemical & Plastics
Agency Address:	1446 Tuscarawas St W, Canton, OH 44702
Place/Project Type:	Industrial - Paints, Varnishes, Lacquers, Enamels, and Allied Products
SIC/NAICS:	2851
Region:	5S
Program:	INDSTW
Regulatory Measure Status:	Terminated
Regulatory Measure Type:	Storm water industrial
Order Number:	2014-0057-DWQ
WDID:	5S39I009306
NPDES Number:	CAS000001
Adoption Date:	01/01/1900
Effective Date:	11/13/1992
Termination Date:	01/01/1900
Expiration/Review Date:	01/01/1900
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	37.9485
Longitude:	-121.29055

N110 **MARKET STREET PARKING GARAGE** **LUST** **S104403409**
NNE **134 SUTTER ST S** **Cortese** **N/A**
1/8-1/4 **STOCKTON, CA 95202** **CERS**
0.230 mi.
1215 ft. **Site 13 of 14 in cluster N**

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	MARKET STREET PARKING GARAGE
Address:	134 SUTTER ST S
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700278
Global Id:	T0607700278
Latitude:	37.951729
Longitude:	-121.2854112
Status:	Completed - Case Closed
Status Date:	12/29/1998
Case Worker:	Not reported
RB Case Number:	390368
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	2339
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

LUST:

Global Id:	T0607700278
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700278
Action Type:	Other
Date:	02/10/1989
Action:	Leak Discovery
Global Id:	T0607700278
Action Type:	Other
Date:	11/07/1988
Action:	Leak Reported
Global Id:	T0607700278
Action Type:	ENFORCEMENT
Date:	04/19/1994
Action:	Notice of Reimbursement

LUST:

Global Id:	T0607700278
Status:	Open - Case Begin Date
Status Date:	11/07/1988
Global Id:	T0607700278

MARKET STREET PARKING GARAGE (Continued) **S104403409**

Status: Open - Site Assessment
Status Date: 02/10/1989

Global Id: T0607700278
Status: Completed - Case Closed
Status Date: 12/29/1998

LUST REG 5:
Name: MARKET STREET PARKING GARAGE
Address: 134 SUTTER ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390368
Case Type: Soil only
Substance: DIESEL
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: MARKET STREET PARKING GARAGE
Address: 134 SUTTER ST S
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700278
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

CERS:
Name: MARKET STREET PARKING GARAGE
Address: 134 SUTTER ST S
City,State,Zip: STOCKTON, CA 95202
Site ID: 204896
CERS ID: T0607700278
CERS Description: Leaking Underground Storage Tank Cleanup Site

MARKET STREET PARKING GARAGE (Continued) **S104403409**

Affiliation:
- Affiliation Type Desc: Regional Board Caseworker
- Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
- Entity Title: Not reported
- Affiliation Address: 11020 SUN CENTER DRIVE #200
- Affiliation City: RANCHO CORDOVA
- Affiliation State: CA
- Affiliation Country: Not reported
- Affiliation Zip: Not reported
- Affiliation Phone: Not reported

N111 **MARKET STREET PARKING GAR** **HIST CORTESE** **S101302829**
North **134 SUTTER** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.233 mi.
1229 ft. **Site 14 of 14 in cluster N**

Relative: **Higher**
Actual: **17 ft.**

HIST CORTESE:
- edr_fname: MARKET STREET PARKING GAR
- edr_fadd1: 134 SUTTER
- City,State,Zip: STOCKTON, CA 95202
- Region: CORTESE
- Facility County Code: 39
- Reg By: LTNKA
- Reg Id: 390368

Q112 **MALAN VAN & STORAGE** **UST** **U004024292**
SE **707 S CALIFORNIA ST** **N/A**
1/8-1/4 **STOCKTON, CA 95202**
0.236 mi.
1248 ft. **Site 2 of 9 in cluster Q**

Relative: **Higher**
Actual: **17 ft.**

UST SAN JOAQUIN:
- Name: MALAN VAN & STORAGE
- Address: 707 S CALIFORNIA ST
- City,State,Zip: STOCKTON, CA 95202
- Region: SJ
- Facility Id: FA0005475
- Mail Address: 1408 BENJAMIN HOLT
- Mail Address 2: Not reported
- Mail Care of: RAY MALAN
- Mail City,St,Zip: STOCKTON, CA 95207

- Tank Rec ID: Not reported
- Tank Number: 1
- Tank Status: 02 - Inactive, non-billable
- Tank Capacity: 1000
- Product Type Desc: 09 - OTHER PETROLEUM
- Program Element: 2380
- Decode for Program Element: 2380 - ADDITIONAL EXISTING UST - obsolete
- Chemical Form: (none)
- CAS#: Not reported
- CERS ID: Not reported
- Cross Ref Tank ID: Not reported
- LEA ID: 9

MALAN VAN & STORAGE (Continued) **U004024292**

Common Name: Not reported
Date Installed: Not reported
Date of Closure: Not reported
Latitude: Not reported
Longitude: Not reported

Q113 **MALAN VAN & STORAGE** **SWEEPS UST** **S101625447**
SE **707 S CALIFORNIA ST** **HIST UST** **N/A**
1/8-1/4 **STOCKTON, CA 95203** **CA FID UST**
0.236 mi.
1248 ft. **Site 3 of 9 in cluster Q**

Relative: Higher

Actual: 17 ft.

SWEEPS UST:
Name: MALAN VAN & STORAGE
Address: 707 S CALIFORNIA ST
City: STOCKTON
Status: Not reported
Comp Number: 1031
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001031-000001
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: DIESEL
Number Of Tanks: 1

HIST UST:
Name: MALAN VAN AND STORAGE
Address: 707 SO CALIF ST
City,State,Zip: STOCKTON, CA 95201
File Number: 0002FEDD
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FEDD.pdf
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported
Owner Name: Not reported
Owner Address: Not reported
Owner City,St,Zip: Not reported
Total Tanks: Not reported

Tank Num: Not reported
Container Num: Not reported
Year Installed: Not reported
Tank Capacity: Not reported
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported

MALAN VAN & STORAGE (Continued) **S101625447**

Leak Detection: Not reported

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 39003430
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 1408 W BENJAMIN HOLT DR
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

Q114 **MALAN VAN & STORAGE** **HIST UST** **U001603213**
SE **707 SO. CALIF ST.** **N/A**
1/8-1/4 **STOCKTON, CA 95201**
0.236 mi.
1248 ft. **Site 4 of 9 in cluster Q**

Relative:
Higher

Actual:
17 ft.

HIST UST:
Name: MALAN VAN & STORAGE
Address: 707 SO. CALIF ST.
City,State,Zip: STOCKTON, CA 95201
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000012851
Facility Type: Other
Other Type: MOVING
Contact Name: CRAIG MALAN
Telephone: 2094664785
Owner Name: MALAN VAN & STORAGE INC.
Owner Address: 715-707 SO. CALIF ST.
Owner City,St,Zip: STOCKTON, CA 95201
Total Tanks: 0001

Tank Num: 001
Container Num: #1
Year Installed: 1974
Tank Capacity: 00001000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: Not reported
Leak Detection: None

115
ENE
1/8-1/4
0.241 mi.
1273 ft.

STOCKTON, CITY OF(REDEVELOPMENT)
310 S AMERICAN ST
STOCKTON, CA 95202

UST **U004024973**
N/A

Relative:
Higher

Actual:
18 ft.

UST SAN JOAQUIN:

Name:	STOCKTON, CITY OF(REDEVELOPMENT)
Address:	310 S AMERICAN ST
City,State,Zip:	STOCKTON, CA 95202
Region:	SJ
Facility Id:	FA0013884
Mail Address:	305 N EL DORADO ST
Mail Address 2:	Not reported
Mail Care of:	Not reported
Mail City,St,Zip:	STOCKTON, CA 95202
Tank Rec ID:	Not reported
Tank Number:	1
Tank Status:	02 - Inactive, non-billable
Tank Capacity:	500
Product Type Desc:	03 - DIESEL
Program Element:	2380
Decode for Program Element:	2380 - ADDITIONAL EXISTING UST - obsolete
Chemical Form:	(none)
CAS#:	Not reported
CERS ID:	Not reported
Cross Ref Tank ID:	Not reported
LEA ID:	9
Common Name:	Not reported
Date Installed:	Not reported
Date of Closure:	Not reported
Latitude:	Not reported
Longitude:	Not reported

Q116
ESE
1/8-1/4
0.245 mi.
1291 ft.

DELTA PUMPS, INC.
646 SOUTH CALIFORNIA STREET
STOCKTON, CA

Site 5 of 9 in cluster Q

CPS-SLIC **S106486438**
CERS **N/A**

Relative:
Higher

Actual:
17 ft.

CPS-SLIC:

Name:	DELTA PUMPS, INC.
Address:	646 SOUTH CALIFORNIA STREET
City,State,Zip:	STOCKTON, CA
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	07/02/1998
Global Id:	SLT5S1193159
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Lead Agency Case Number:	Not reported
Latitude:	37.9470664722277
Longitude:	-121.281951433838
Case Type:	Cleanup Program Site
Case Worker:	ZZZ
Local Agency:	Not reported
RB Case Number:	SLT5S119
File Location:	Not reported
Potential Media Affected:	Other Groundwater (uses other than drinking water), Under Investigation

DELTA PUMPS, INC. (Continued) **S106486438**

Potential Contaminants of Concern: Not reported
Site History: Owner contacted the board about a potential benzene leak. Caseworker decided that based on the information, RWQCB would not require Delta Pumps to conduct and investigation.

Click here to access the California GeoTracker records for this facility:

CERS:
Name: DELTA PUMPS, INC.
Address: 646 SOUTH CALIFORNIA STREET
City,State,Zip: STOCKTON, CA
Site ID: 250354
CERS ID: SLT5S1193159
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: zzz - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Q117 **STOCKTON ARMATURE & MOTOR WORK** **HIST UST U001603301**
ESE **646 S CALIFORNIA ST** **CHMIRS N/A**
1/8-1/4 **STOCKTON, CA 95203**
0.245 mi.
1291 ft. **Site 6 of 9 in cluster Q**

Relative:
Higher

Actual:
17 ft.

HIST UST:
Name: STOCKTON ARMATURE & MOTOR WORK
Address: 646 S CALIFORNIA ST
City,State,Zip: STOCKTON, CA 95203
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000018268
Facility Type: Other
Other Type: PUMP MFG. & SALES
Contact Name: ROBERT M. CROW
Telephone: 2094669625
Owner Name: DELTA PUMPS
Owner Address: 646 SOUTH CALIFORNIA STREET
Owner City,St,Zip: STOCKTON, CA 95203
Total Tanks: 0001

Tank Num: 001
Container Num: 1
Year Installed: 1964
Tank Capacity: 00000550
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: 12
Leak Detection: Stock Inventor, None

STOCKTON ARMATURE & MOTOR WORK (Continued) **U001603301**

CHMIRS:

Name:	Not reported
Address:	646 SOUTH CALIFORNIA STREET
City,State,Zip:	STOCKTON, CA
OES Incident Number:	18-1485
OES notification:	03/07/2018
OES Date:	Not reported
OES Time:	Not reported
Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Merchant/Business
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Type:	PETROLEUM
Measure:	Gal(s)
Other:	Not reported
Date/Time:	2146
Year:	2018
Agency:	PG&E
Incident Date:	03/06/2018
Admin Agency:	San Joaquin County Environmental Health
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Insulating Oil
Quantity Released:	5
Unknown:	Not reported

STOCKTON ARMATURE & MOTOR WORK (Continued) **U001603301**

Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
#1 Pipeline:	No
#2 Pipeline:	No
#3 Pipeline:	No
#1 Vessel >= 300 Tons:	No
#2 Vessel >= 300 Tons:	No
#3 Vessel >= 300 Tons:	No
Evacs:	No
Injuries:	No
Fatals:	No
Comments:	Not reported
Description:	RP States: A vehicle struck a pole causing a release of 5 gallons of insulating oil onto the asphalt. The release is contained. No waterways were impacted and clean up is being arranged.

Q118 **DELTA PUMP INC DELTA PUMP CO** **RCRA NonGen / NLR** **1026056127**
ESE **646 S CALIFORNIA ST** **CAL000452314**
1/8-1/4 **STOCKTON, CA 95203**
0.245 mi.
1291 ft. **Site 7 of 9 in cluster Q**

Relative: **Higher**

Actual: **17 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-01-30 00:00:00.0
Handler Name:	DELTA PUMP INC DELTA PUMP CO
Handler Address:	646 S CALIFORNIA ST
Handler City,State,Zip:	STOCKTON, CA 95203
EPA ID:	CAL000452314
Contact Name:	IGNACIO ROMERO
Contact Address:	646 S CALIFORNIA ST
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	209-466-9625
Contact Fax:	209-466-1324
Contact Email:	DELTAPUMPCO@GMAIL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	646 S CALIFORNIA ST
Mailing City,State,Zip:	STOCKTON, CA 95203
Owner Name:	DELTA PUMP INC
Owner Type:	Other
Operator Name:	IGNACIO ROMERO
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

DELTA PUMP INC DELTA PUMP CO (Continued) **1026056127**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-02-10 17:54:19.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	IGNACIO ROMERO
Legal Status:	Other

DELTA PUMP INC DELTA PUMP CO (Continued) **1026056127**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	646 S CALIFORNIA ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203
Owner/Operator Telephone:	209-466-9625
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	DELTA PUMP INC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	646 S CALIFORNIA ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203
Owner/Operator Telephone:	209-466-9625
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-01-30 00:00:00.0
Handler Name:	DELTA PUMP INC DELTA PUMP CO
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	333914
NAICS Description:	MEASURING, DISPENSING, AND OTHER PUMPING EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Q119
ESE
1/8-1/4
0.245 mi.
1291 ft.

STOCKTON ARMATURE AND MOTOR WORDS DBA DELTA PUMP C
646 S CALIFORNIA STREET
STOCKTON, CA 95203

RCRA NonGen / NLR

1024800241
CAL000218979

Site 8 of 9 in cluster Q

Relative:
Higher

Actual:
17 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2001-01-09 00:00:00.0
Handler Name:	STOCKTON ARMATURE AND MOTOR WORDS DBA DELTA PUMP CO
Handler Address:	646 S CALIFORNIA STREET
Handler City,State,Zip:	STOCKTON, CA 95203-0000
EPA ID:	CAL000218979
Contact Name:	IGNACIO ROMERO
Contact Address:	646 S CALIFORNIA ST
Contact City,State,Zip:	STOCKTON, CA 95203
Contact Telephone:	209-466-9625
Contact Fax:	209-466-1234
Contact Email:	DELTAPUMP@SBCGLOBAL.NET
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	646 S CALIFORNIA ST
Mailing City,State,Zip:	STOCKTON, CA 95203-0000
Owner Name:	DELTA PUMP INC
Owner Type:	Other
Operator Name:	IGNACIO ROMERO
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

STOCKTON ARMATURE AND MOTOR WORDS DBA DELTA PUMP CO (Continued) **1024800241**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:45:11.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	IGNACIO ROMERO
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	646 S CALIFORNIA ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203
Owner/Operator Telephone:	209-466-9625
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DELTA PUMP INC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	646 S CALIFORNIA ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95203-0000
Owner/Operator Telephone:	209-466-9625
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

STOCKTON ARMATURE AND MOTOR WORDS DBA DELTA PUMP CO (Continued) **1024800241**

Historic Generators:
Receive Date: 2001-01-09 00:00:00.0
Handler Name: STOCKTON ARMATURE AND MOTOR WORDS DBA DELTA PUMP CO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 333911
NAICS Description: PUMP AND PUMPING EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Q120
ESE
1/8-1/4
0.245 mi.
1291 ft.

Relative:
Higher

Actual:
17 ft.

STOCKTON ARMATURE AND MOTOR WORKS INC
646 S CALIFORNIA ST
STOCKTON, CA 95203

Site 9 of 9 in cluster Q

CERS HAZ WASTE
SWEEPS UST
HIST UST
CA FID UST
HAZNET
HWTS

S101625470
N/A

CERS HAZ WASTE:
Name: DELTA PUMP, INC.
Address: 646 S CALIFORNIA ST
City,State,Zip: STOCKTON, CA 95203
Site ID: 570820
CERS ID: 10834372
CERS Description: Hazardous Waste Generator

Violations:
Site ID: 570820
Site Name: Delta Pump, Inc.
Violation Date: 01-20-2016
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 02/08/2016. Proof of relevant employee training was not available at the time of inspection. The business plan shall include provisions for ensuring that appropriate personnel receive initial and annual refresher training. This training shall be documented electronically or by hard copy and shall be made available for a minimum of three years. Immediately provide employee training

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

	for appropriate personnel and submit a copy of the training records to the EHD.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	01-20-2016
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 01/20/2016. The emergency response procedures have not been submitted. A business plan shall include the following emergency response procedures for a release or threatened release of hazardous materials, including, but not limited to, the following: - immediate notification of local emergency personnel and the Environmental Health Department (EHD) - procedures for the mitigation of a release or threatened release to minimize any potential harm or damage to persons, property, or the environment - evacuation plans and procedures, including immediate notice, for the site Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	01-20-2016
Citation:	19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes:	Returned to compliance on 01/20/2016. The Business Activities Form is not complete. The form wrongly indicates the business is not a hazardous waste generator and hazardous materials are not present at this facility in reportable quantities at any one time of the year. This information must be current and submitted as part of the business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	09-12-2013
Citation:	HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Description:	Haz Waste Generator Program - Operations/Maintenance - General

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Violation Notes:	Returned to compliance on 12/10/2018.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	09-12-2013
Citation:	HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Description:	Haz Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 12/10/2018.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	01-20-2016
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 01/20/2016. A 55 gallon drum of waste oil, a 55 gallon drum of acetone, greater than 200 cubic feet of compressed oxygen and greater than 200 cubic feet of acetylene flammable gas were found on site that have not been reported. Any material that meets or exceeds the reportable quantity shall be reported in the facility's business plan. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, add the materials to the hazardous material inventory, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	12-10-2018
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 12/10/2018. In the hazardous waste storage area: -One blue 55 gallon poly drum containing oily debris (1/4 full) was observed with a hazardous waste label missing the contents, physical state, and hazardous properties. -One blue 55 gallon steel drum containing used oil (3/4 full) was observed with a hazardous waste label missing the accumulation start date, hazardous properties, physical state, name and address of the generator, and the words "hazardous waste." All hazardous waste containers shall be marked with the following information: - the words G Hazardous WasteG - name and address of generator - hazardous properties - physical state -

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

composition (contents) - accumulation start date This was corrected on site.

Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 570820
Site Name: Delta Pump, Inc.
Violation Date: 01-20-2016
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit a site map with all required content.
Violation Notes: Returned to compliance on 01/20/2016. A site map has not been submitted. A site map shall contain a north orientation, loading areas, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shutoffs, evacuation staging areas, hazardous material handling and storage areas, and emergency response equipment. Immediately log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division: San Joaquin County Environmental Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 570820
Site Name: Delta Pump, Inc.
Violation Date: 12-10-2018
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Description: Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.
Violation Notes: Returned to compliance on 10/21/2020. Copies of uniform manifests for the disposal of hazardous waste for the first half of 2018 for metal shavings, oily absorbent, and oil filters were not found on site. Hazardous waste generators shall retain copies of all manifests signed off by the disposal facility and all receipts used in a consolidated manifesting procedure on site for three years and have them readily available for review. Immediately locate a copy of all manifests and receipts for the last three years, maintain them on site, and submit records of the missing copies to the EHD.
Violation Division: San Joaquin County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 570820
Site Name: Delta Pump, Inc.
Violation Date: 01-20-2016
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Violation Notes:	Returned to compliance on 01/20/2016. The facility's business plan was not submitted electronically to the California Environmental Reporting System (CERS). As of January 1, 2013, all businesses were required to submit all business plans electronically. Immediately log into the CERS at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	01-20-2016
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes:	Returned to compliance on 01/20/2016. A training program has not been submitted. Training programs for all employees and annual training, including refresher courses, shall include safety procedures for the event of a release or threatened release of a hazardous material, including, but not limited to, familiarity with the facility's emergency response plans and procedures. These training programs may take into consideration of each employee. Immediately prepare or update the facility's training program, log into the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov/, upload the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	570820
Site Name:	Delta Pump, Inc.
Violation Date:	01-20-2016
Citation:	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description:	Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes:	Returned to compliance on 01/20/2016. The business plan information has not been reviewed and resubmitted in the California Environmental Reporting System (CERS) annually. The hazardous materials inventory shall be submitted by January 15 of each calendar year and may be submitted beginning November 1 of the previous year. Immediately log into the CERS at http://cers.calepa.ca.gov/, enter the correct or updated information, and submit to the EHD for approval. This was corrected on site.
Violation Division:	San Joaquin County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-20-2016
Violations Found:	Yes

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork by February 19, 2016. Assistance with CERS access and submittal at the time of inspection. Copies of the inspection report and inspection photos were provided to Austin Loock. Please be aware as of January 1, 2013, all businesses were required to submit all hazardous materials information online to the California Environmental Reporting System (CERS) at http://cers.calepa.ca.gov. Be sure to include your hazardous material activity in the Businesses Activities section in CERS in addition to any other relevant activities and required fields. For assistance with CERS, contact Lisa Medina at 209-468-3455.
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-12-2013
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	12-10-2018
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Complete and submit a copy of the Return to Compliance Certification form to the EHD with a statement documenting the corrective actions that have been or will be taken for each violation, and any supporting paperwork, by January 9, 2019. Starting September 1, 2018, all in-office CERS help will be provided at EHD hourly rate ($152). To schedule an appointment, please call (209) 468-3420. Waste Streams: used oil, metal fines, oil filters, paint waste, parts washer, sand blaster
Eval Division:	San Joaquin County Environmental Health
Eval Program:	HW
Eval Source:	CERS

Enforcement Action:

Site ID:	570820
Site Name:	Delta Pump, Inc.
Site Address:	646 S CALIFORNIA ST
Site City:	STOCKTON
Site Zip:	95203
Enf Action Date:	01-20-2016
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	HMRRP
Enf Action Source:	CERS

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Site ID:	570820
Site Name:	Delta Pump, Inc.
Site Address:	646 S CALIFORNIA ST
Site City:	STOCKTON
Site Zip:	95203
Enf Action Date:	09-12-2013
Enf Action Type:	Notice of Violation (Unified Program)
Enf Action Description:	Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:	Not reported
Enf Action Division:	San Joaquin County Environmental Health
Enf Action Program:	HW
Enf Action Source:	CERS

Coordinates:

Site ID:	570820
Facility Name:	Delta Pump, Inc.
Env Int Type Code:	HWG
Program ID:	10834372
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	37.946780
Longitude:	-121.282240

Affiliation:

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	646 S California St.
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95203
Affiliation Phone:	Not reported

Affiliation Type Desc:	Property Owner
Entity Name:	Austin Loock
Entity Title:	Not reported
Affiliation Address:	646 S CALIFORNIA ST
Affiliation City:	STOCKTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	952033705
Affiliation Phone:	(209) 649-7217

Affiliation Type Desc:	CUPA District
Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95205-6232
Affiliation Phone:	(209) 468-3420

Affiliation Type Desc:	Parent Corporation
Entity Name:	Delta Pump Co

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	Austin Loock
Entity Title:	Not reported
Affiliation Address:	646 S California St
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95203
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	Austin Loock
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(209) 649-7127
Affiliation Type Desc:	Document Preparer
Entity Name:	Shannon Loock
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Austin Loock
Entity Title:	CEO
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Austin Loock
Entity Title:	Not reported
Affiliation Address:	210 Meadowlark Way
Affiliation City:	LODI
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95240
Affiliation Phone:	(209) 466-9625

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

SWEEPS UST:

Name:	STOCKTON ARMATURE & MOTOR WORK
Address:	646 S CALIFORNIA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	1030
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001030-000001
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	1

HIST UST:

Name:	STOCKTON ARMATURE AND MOTOR WORK
Address:	646 SOUTH CALIFORNIA STREET
City,State,Zip:	STOCKTON, CA 95203
File Number:	0002FB44
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FB44.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	39000714
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2094669625

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Mail To: Not reported
Mailing Address: P O BOX 1927
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

HAZNET:
Name: STOCKTON ARMATURE AND MOTOR WORKS INC
Address: 646 S CALIFORNIA ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
Contact: TRACY MILLER
Telephone: 2094669625
Mailing Name: Not reported
Mailing Address: 646 S CALIFORNIA ST

Year: 2013
Gepaid: CAC002749852
TSD EPA ID: CAD982042475
CA Waste Code: 151 - Asbestos containing waste
Disposal Method: H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons: 4

Additional Info:
Year: 2013
Gen EPA ID: CAC002749852

Shipment Date: 20131205
Creation Date: 1/29/2014 22:15:13
Receipt Date: 20131204
Manifest ID: 010193798JJK
Trans EPA ID: CAR000037283
Trans Name: WORLD ENVIRONMENTAL & ENERGY INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD982042475
Trans Name: RECOLOGY HAY ROAD LANDFILL
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 151 - Asbestos-containing waste
RCRA Code: Not reported
Meth Code: H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons: 4
Waste Quantity: 10
Quantity Unit: Y
Additional Code 1: Not reported
Additional Code 2: Not reported

STOCKTON ARMATURE AND MOTOR WORKS INC (Continued) **S101625470**

Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

HWTS:
Name: STOCKTON ARMATURE AND MOTOR WORKS INC
Address: 646 S CALIFORNIA ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203
EPA ID: CAC002749852
Inactive Date: 02/03/2014
Create Date: 11/04/2013
Last Act Date: 02/04/2014
Mailing Name: Not reported
Mailing Address: 646 S CALIFORNIA ST
Mailing Address 2: Not reported
Mailing City,State,Zip: STOCKTON, CA 95203
Owner Name: TRACY MILLER
Owner Address: 646 S CALIFORNIA ST
Owner Address 2: Not reported
Owner City,State,Zip: STOCKTON, CA 95203
Contact Name: TRACY MILLER
Contact Address: 646 S CALIFORNIA ST
Contact Address 2: Not reported
City,State,Zip: STOCKTON, CA 95203

P121 **HIGRADE CLEANERS** **SEMS-ARCHIVE** **1003073279**
North **47 SOUTH SAN JOAQUIN STREET** **CAL000127552**
1/8-1/4 **STOCKTON, CA 95202**
0.250 mi.
1320 ft. **Site 4 of 4 in cluster P**

Relative:
Lower

Actual:
16 ft.

SEMS Archive:
Site ID: 0905667
EPA ID: CAL000127552
Name: HIGRADE CLEANERS
Address: 47 SOUTH SAN JOAQUIN STREET
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95202
Cong District: Not reported
FIPS Code: 06077
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:
Region: 09
Site ID: 0905667
EPA ID: CAL000127552
Site Name: HIGRADE CLEANERS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 2013-11-08 05:00:00

HIGRADE CLEANERS (Continued) **1003073279**

Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse
Region:	09
Site ID:	0905667
EPA ID:	CAL000127552
Site Name:	HIGRADE CLEANERS
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	2003-02-01 05:00:00
Finish Date:	2006-07-25 04:00:00
Qual:	N
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0905667
EPA ID:	CAL000127552
Site Name:	HIGRADE CLEANERS
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	2000-03-15 05:00:00
Finish Date:	2000-03-15 05:00:00
Qual:	Not reported
Current Action Lead:	St Perf
Region:	09
Site ID:	0905667
EPA ID:	CAL000127552
Site Name:	HIGRADE CLEANERS
NPL:	N
FF:	N
OU:	00
Action Code:	HX
Action Name:	PRE-CERC
SEQ:	1
Start Date:	Not reported
Finish Date:	2000-03-15 05:00:00
Qual:	Not reported
Current Action Lead:	St Perf

R122 **STOCKTON POLICE DEPARTMENT** **LUST** **S104403378**
NW **22 MARKET ST E** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95201** **HIST CORTESE**
0.251 mi.
1325 ft. **Site 1 of 2 in cluster R**

Relative:
Lower

Actual:
15 ft.

LUST:

Name:	STOCKTON POLICE DEPARTMENT
Address:	22 MARKET ST E
City,State,Zip:	STOCKTON, CA 95201
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700169
Global Id:	T0607700169
Latitude:	37.951136
Longitude:	-121.290028
Status:	Completed - Case Closed
Status Date:	09/12/1996
Case Worker:	Not reported
RB Case Number:	390238
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	1178
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700169
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700169
Action Type:	Other
Date:	06/27/1988
Action:	Leak Discovery

Global Id:	T0607700169
Action Type:	Other
Date:	06/27/1988
Action:	Leak Reported

LUST:

Global Id:	T0607700169
Status:	Open - Case Begin Date
Status Date:	06/27/1988

Global Id:	T0607700169
Status:	Open - Site Assessment
Status Date:	06/27/1988

Global Id:	T0607700169
Status:	Completed - Case Closed

STOCKTON POLICE DEPARTMENT (Continued) **S104403378**

Status Date: 09/12/1996

LUST REG 5:

Name:	STOCKTON POLICE DEPARTMENT
Address:	22 MARKET ST E
City:	STOCKTON
Region:	5
Status:	Case Closed
Case Number:	390238
Case Type:	Soil only
Substance:	GASOLINE
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	N/A

CORTESE:

Name:	STOCKTON POLICE DEPARTMENT
Address:	22 MARKET ST E
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700169
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	STOCKTON POLICE DEPARTMEN
edr_fadd1:	22 MARKET
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390238

123
NNW
1/4-1/2
0.274 mi.
1448 ft.

CANLIS BLDG
24 HUNTER ST S
STOCKTON, CA 95201

LUST
Cortese
HIST CORTESE
CERS

S104403496
N/A

Relative:
Lower

Actual:
16 ft.

LUST:

Name:	CANLIS BLDG
Address:	24 HUNTER ST S
City,State,Zip:	STOCKTON, CA 95201
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700548
Global Id:	T0607700548
Latitude:	37.952495
Longitude:	-121.287952
Status:	Completed - Case Closed
Status Date:	12/30/1997
Case Worker:	Not reported
RB Case Number:	390710
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	2372
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

LUST:

Global Id:	T0607700548
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700548
Action Type:	Other
Date:	04/20/1992
Action:	Leak Discovery

Global Id:	T0607700548
Action Type:	Other
Date:	04/20/1992
Action:	Leak Reported

LUST:

Global Id:	T0607700548
Status:	Open - Case Begin Date
Status Date:	04/20/1992

Global Id:	T0607700548
Status:	Completed - Case Closed
Status Date:	12/30/1997

CANLIS BLDG (Continued) **S104403496**

LUST REG 5:
Name: CANLIS BLDG
Address: 24 HUNTER ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390710
Case Type: Soil only
Substance: DIESEL
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: CANLIS BLDG
Address: 24 HUNTER ST S
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700548
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: CANLIS BLDG
edr_fadd1: 24 HUNTER
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390710

CERS:
Name: CANLIS BLDG
Address: 24 HUNTER ST S
City,State,Zip: STOCKTON, CA 95201
Site ID: 224761
CERS ID: T0607700548

CANLIS BLDG (Continued) **S104403496**

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

R124 **CHEVRON #9-0557** **LUST** **S104403436**
NW **139 CENTER ST S** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95205** **HIST CORTESE**
0.279 mi. **CERS**
1475 ft. **Site 2 of 2 in cluster R**

Relative: **Lower**
Actual: **14 ft.**

LUST:
Name: CHEVRON #9-0557
Address: 139 CENTER ST S
City,State,Zip: STOCKTON, CA 95205
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700391
Global Id: T0607700391
Latitude: 37.950597521
Longitude: -121.290659921
Status: Completed - Case Closed
Status Date: 12/05/2014
Case Worker: Not reported
RB Case Number: 390502
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 1039
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: April 1990 - Four USTs were removed and replaced with four USTs. February 1991 - MW-1, MW-2, MW-3, and MW-4 were installed. November 1992 - MW-5 was installed. September 1993 - MW-6 was installed. October 1997 - MW-8, MW-9, and SV-1 were installed. September 2001 - MW-9S, MW-9A, MW-10, MW-11, and MW-12 were installed. February 2002 - four ozone-paired sparging wells (OS-1S/1D, OS-2S/2D, OS-3S/3D, and OS-4S/4D) were installed. June 2002 - MW-13 was installed. January 2003 - destroyed MW-1, -2, -4, -9, -9A, -9S, -10, -11, -12, OS-1S/1D, OS-2S/2D, OS-3S/3D, and OS-4S/4D. February 2003 - four USTs were removed. March/April 2004 - MW-14, -15, -15D, 16, and 17 were installed. November 2007 - MW-18D2 was installed.

LUST:
Global Id: T0607700391
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov

CHEVRON #9-0557 (Continued) **S104403436**

Phone Number: Not reported

LUST:

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 07/18/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 03/11/2014
Action: State Water Board Closure Order

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 05/06/2010
Action: Technical Correspondence / Assistance / Other - #05/06/2010

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 03/21/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 08/30/2011
Action: File review

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 12/03/2014
Action: Closure/No Further Action Letter

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 11/20/2014
Action: Email Correspondence

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 06/30/2014
Action: Staff Letter

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 12/21/2010
Action: Technical Correspondence / Assistance / Other - #12/21/2010

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 09/10/2010
Action: File review

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 05/16/2011
Action: Technical Correspondence / Assistance / Other - #05/16/2011

CHEVRON #9-0557 (Continued) **S104403436**

Global Id: T0607700391
Action Type: RESPONSE
Date: 05/30/2013
Action: Correspondence

Global Id: T0607700391
Action Type: RESPONSE
Date: 03/26/2013
Action: Request for Closure - Regulator Responded

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 02/29/2012
Action: File review

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 06/20/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 07/13/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700391
Action Type: Other
Date: 04/05/1990
Action: Leak Discovery

Global Id: T0607700391
Action Type: Other
Date: 04/05/1990
Action: Leak Stopped

Global Id: T0607700391
Action Type: Other
Date: 04/16/1990
Action: Leak Reported

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 04/19/1990
Action: * No Action

Global Id: T0607700391
Action Type: ENFORCEMENT

CHEVRON #9-0557 (Continued) **S104403436**

Date: 09/19/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700391
Action Type: RESPONSE
Date: 09/30/2009
Action: Correspondence

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 08/06/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 08/19/2013
Action: Staff Letter

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 07/17/2013
Action: LOP Case Closure Summary to RB

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 04/03/2008
Action: File review

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 04/29/2009
Action: Staff Letter - #04/29/2009

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 11/06/2013
Action: Clean Up Fund - Letter to RP

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 03/19/2009
Action: File review

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 07/02/2009
Action: Technical Correspondence / Assistance / Other - #07/02/2009

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 06/26/2009
Action: Technical Correspondence / Assistance / Other - #06/26/2009

Global Id: T0607700391
Action Type: ENFORCEMENT
Date: 11/06/2013
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

CHEVRON #9-0557 (Continued) **S104403436**

LUST:

Global Id:	T0607700391
Status:	Open - Case Begin Date
Status Date:	04/05/1990
Global Id:	T0607700391
Status:	Open - Site Assessment
Status Date:	04/05/1990
Global Id:	T0607700391
Status:	Open - Site Assessment
Status Date:	04/16/1990
Global Id:	T0607700391
Status:	Open - Site Assessment
Status Date:	08/14/2009
Global Id:	T0607700391
Status:	Open - Eligible for Closure
Status Date:	06/28/2013
Global Id:	T0607700391
Status:	Completed - Case Closed
Status Date:	12/05/2014

LUST REG 5:

Name:	CHEVRON #9-0557
Address:	139 CENTER ST S
City:	STOCKTON
Region:	5
Status:	Preliminary site assessment underway
Case Number:	390502
Case Type:	Drinking Water Aquifer affected
Substance:	GASOLINE
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	5

CORTESE:

Name:	CHEVRON #9-0557
Address:	139 CENTER ST S
City,State,Zip:	STOCKTON, CA 95205
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700391
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported

CHEVRON #9-0557 (Continued) **S104403436**

Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	CHEVRON #9-0557
edr_fadd1:	139 CENTER
City,State,Zip:	STOCKTON, CA 95205
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390502

CERS:

Name:	CHEVRON #9-0557
Address:	139 CENTER ST S
City,State,Zip:	STOCKTON, CA 95205
Site ID:	208044
CERS ID:	T0607700391
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

125
NNE
1/4-1/2
0.284 mi.
1501 ft.

THE RECORD **LUST** **S105791071**
530 MARKET **Cortese** **N/A**
STOCKTON, CA 95201 **CERS**

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	THE RECORD
Address:	530 MARKET
City,State,Zip:	STOCKTON, CA 95201
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607712799
Global Id:	T0607712799
Latitude:	37.952318
Longitude:	-121.283496
Status:	Completed - Case Closed
Status Date:	05/08/2003

THE RECORD (Continued) **S105791071**

Case Worker: Not reported
RB Case Number: 391143
Local Agency: Not reported
File Location: Not reported
Local Case Number: 0001478
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607712799
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607712799
Action Type: ENFORCEMENT
Date: 05/02/2003
Action: Closure/No Further Action Letter

Global Id: T0607712799
Action Type: Other
Date: 01/14/2003
Action: Leak Discovery

Global Id: T0607712799
Action Type: Other
Date: 01/14/2003
Action: Leak Stopped

Global Id: T0607712799
Action Type: Other
Date: 02/11/2003
Action: Leak Reported

LUST:
Global Id: T0607712799
Status: Open - Case Begin Date
Status Date: 01/14/2003

Global Id: T0607712799
Status: Open - Site Assessment
Status Date: 03/03/2003

Global Id: T0607712799
Status: Completed - Case Closed
Status Date: 05/08/2003

LUST REG 5:
Name: THE RECORD

THE RECORD (Continued) **S105791071**

Address: 530 MARKET
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 391143
Case Type: Soil only
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: THE RECORD
Address: 530 MARKET
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607712799
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

CERS:
Name: THE RECORD
Address: 530 MARKET
City,State,Zip: STOCKTON, CA 95201
Site ID: 225212
CERS ID: T0607712799
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

126
WSW
1/4-1/2
0.290 mi.
1531 ft.

FIRE ENGINE COMPANY #2
110 SONORA
STOCKTON, CA 95205

LUST
Cortese
HIST CORTESE
CERS

S101302822
N/A

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	FIRE ENGINE COMPANY #2
Address:	110 SONORA ST W
City,State,Zip:	STOCKTON, CA 95205
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700084
Global Id:	T0607700084
Latitude:	37.947746
Longitude:	-121.291835
Status:	Completed - Case Closed
Status Date:	05/15/2007
Case Worker:	Not reported
RB Case Number:	390115
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	1253
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700084
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700084
Action Type:	ENFORCEMENT
Date:	03/28/1990
Action:	Notice of Reimbursement
Global Id:	T0607700084
Action Type:	ENFORCEMENT
Date:	03/12/2007
Action:	LOP Case Closure Summary to RB
Global Id:	T0607700084
Action Type:	Other
Date:	10/28/1993
Action:	Leak Discovery
Global Id:	T0607700084
Action Type:	Other
Date:	04/01/1987
Action:	Leak Stopped
Global Id:	T0607700084

FIRE ENGINE COMPANY #2 (Continued) **S101302822**

Action Type: Other
Date: 12/10/1987
Action: Leak Reported

Global Id: T0607700084
Action Type: REMEDIATION
Date: 10/01/2001
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700084
Action Type: REMEDIATION
Date: 10/01/2001
Action: In Situ Physical/Chemical Treatment (other than SVE)

LUST:
Global Id: T0607700084
Status: Open - Case Begin Date
Status Date: 04/01/1987

Global Id: T0607700084
Status: Open - Site Assessment
Status Date: 10/28/1993

Global Id: T0607700084
Status: Open - Site Assessment
Status Date: 09/06/1996

Global Id: T0607700084
Status: Open - Verification Monitoring
Status Date: 12/30/2005

Global Id: T0607700084
Status: Completed - Case Closed
Status Date: 05/15/2007

LUST REG 5:
Name: FIRE ENGINE COMPANY #2
Address: 110 SONORA ST W
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390115
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

CORTESE:
Name: FIRE ENGINE COMPANY #2
Address: 110 SONORA ST W
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Envirostor Id: Not reported

FIRE ENGINE COMPANY #2 (Continued) **S101302822**

Global ID:	T0607700084
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	FIRE ENGINE COMPANY #2
edr_fadd1:	110 SONORA
City,State,Zip:	STOCKTON, CA 95205
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390115

CERS:

Name:	FIRE ENGINE COMPANY #2
Address:	110 SONORA ST W
City,State,Zip:	STOCKTON, CA 95205
Site ID:	247286
CERS ID:	T0607700084
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

127
East
1/4-1/2
0.293 mi.
1546 ft.

H AND B RECYCLING
521 S STANISLAUS ST
STOCKTON, CA 95203

SWRCY **S107137086**
N/A

Relative:
Higher

Actual:
17 ft.

SWRCY:

Name:	H AND B RECYCLING
Address:	521 S STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95203
Reg Id:	18558
Cert Id:	RC6617
Mailing Address:	521 S Stanislaus St
Mailing City:	Stockton
Mailing State:	CA
Mailing Zip Code:	95203
Website:	Not reported
Email:	Not reported
Phone Number:	(209) 933-9268
Rural:	N
Operation Begin Date:	10/08/1995
Aluminium:	Y
Glass:	Y
Plastic:	Y
Bimetal:	Y
Hours of Operation:	Mon - Sun 8:00 am - 4:30 pm
Organization ID:	18558
Organization Name:	H and B Recycling

128
ENE
1/4-1/2
0.293 mi.
1548 ft.

GLEASON PARK APARTMENT
411 S. STANISLAUS STREET
STOCKTON, CA 95203

ENVIROSTOR **S109425059**
VCP **N/A**
DEED

Relative:
Higher

Actual:
18 ft.

ENVIROSTOR:

Name:	GLEASON PARK APARTMENT
Address:	411 S. STANISLAUS STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	60001130
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	11/08/2010
Site Code:	102016
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	3.5
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Melessia Downham
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	YES
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.94985
Longitude:	-121.2810

GLEASON PARK APARTMENT (Continued) **S109425059**

APN: NONE SPECIFIED
Past Use: NONE
Potential COC: Lead
Confirmed COC: Lead
Potential Description: SOIL
Alias Name: 102016
Alias Type: Project Code (Site Code)
Alias Name: 60001130
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/08/2010
Comments: No Further Action Letter dated 11/8/2010.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 10/07/2010
Comments: LUC Recorded with County Recorder’s office on 10/7/2010

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 07/28/2009
Comments: Executed VCA signed by DTSC on 7/28/2009.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 02/15/2012
Comments: LUC Annual Report submitted by Mercy Housing cover letter dated 2.15.2012, Annual Report dated 2.10.2012.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/02/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/06/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/16/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/17/2015

GLEASON PARK APARTMENT (Continued) **S109425059**

Comments: Email sent approving 2016 Annual LUC Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 01/10/2017
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/07/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: complteted

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/01/2018
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2019
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/15/2020
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 10/07/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE

GLEASON PARK APARTMENT (Continued) **S109425059**

Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/24/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 01/15/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/12/2017
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

GLEASON PARK APARTMENT (Continued) **S109425059**

Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/02/2019
Comments: 2019 LUC Inspection Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/20/2019
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/19/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/10/2021
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: GLEASON PARK APARTMENT
Address: 411 S. STANISLAUS STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60001130
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 3.5
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Melessia Downham
Supervisor: Lora Jameson
Division Branch: Northern California Schools & Santa Susana
Site Code: 102016
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: Certified O&M - Land Use Restrictions Only
Status Date: 11/08/2010
Restricted Use: YES
Funding: Responsible Party
Lat/Long: 37.94985 / -121.2810

GLEASON PARK APARTMENT (Continued) **S109425059**

APN: NONE SPECIFIED
Past Use: NONE
Potential COC: 30013
Confirmed COC: 30013
Potential Description: SOIL
Alias Name: 102016
Alias Type: Project Code (Site Code)
Alias Name: 60001130
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/08/2010
Comments: No Further Action Letter dated 11/8/2010.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 10/07/2010
Comments: LUC Recorded with County Recorder’s office on 10/7/2010

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 07/28/2009
Comments: Executed VCA signed by DTSC on 7/28/2009.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 02/15/2012
Comments: LUC Annual Report submitted by Mercy Housing cover letter dated 2.15.2012, Annual Report dated 2.10.2012.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/02/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/06/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/16/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/17/2015

GLEASON PARK APARTMENT (Continued) **S109425059**

Comments: Email sent approving 2016 Annual LUC Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 01/10/2017
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/07/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: complteted

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/01/2018
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2019
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/15/2020
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 10/07/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE

GLEASON PARK APARTMENT (Continued) **S109425059**

Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/24/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 01/15/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/12/2017
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

GLEASON PARK APARTMENT (Continued) **S109425059**

Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/02/2019
Comments: 2019 LUC Inspection Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 12/20/2019
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/19/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/10/2021
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

DEED:
Name: GLEASON PARK APARTMENT
Address: 411 S. STANISLAUS STREET
City,State,Zip: STOCKTON, CA 95203
Envirostor ID: 60001130
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

---

129 **GREYHOUND LINES INC** **LUST** **S104403480**
WNW **121 CENTER ST S** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95201** **HIST CORTESE**
0.301 mi. **CERS**
1591 ft.

Relative: **Lower**

Actual: **14 ft.**

LUST:
Name: GREYHOUND LINES INC
Address: 121 CENTER ST S
City,State,Zip: STOCKTON, CA 95201
Lead Agency: SAN JOAQUIN COUNTY

GREYHOUND LINES INC (Continued) **S104403480**

Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700505
Global Id:	T0607700505
Latitude:	37.9509029
Longitude:	-121.291392
Status:	Completed - Case Closed
Status Date:	05/29/1997
Case Worker:	Not reported
RB Case Number:	390654
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	1041
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Diesel
Site History:	Not reported

LUST:

Global Id:	T0607700505
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700505
Action Type:	RESPONSE
Date:	06/15/1993
Action:	Monitoring Report - Other
Global Id:	T0607700505
Action Type:	RESPONSE
Date:	06/11/1992
Action:	Correspondence
Global Id:	T0607700505
Action Type:	RESPONSE
Date:	07/07/1994
Action:	Correspondence
Global Id:	T0607700505
Action Type:	RESPONSE
Date:	07/13/1992
Action:	Monitoring Report - Other
Global Id:	T0607700505
Action Type:	RESPONSE
Date:	07/03/1991
Action:	Other Report / Document
Global Id:	T0607700505
Action Type:	RESPONSE
Date:	10/22/1996
Action:	Monitoring Report - Quarterly

GREYHOUND LINES INC (Continued) **S104403480**

Global Id: T0607700505
Action Type: RESPONSE
Date: 04/02/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 12/19/1994
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 12/15/1992
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 03/19/1997
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 08/12/1993
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 01/14/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 03/08/1993
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 05/06/1997
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 11/11/1992
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 08/28/1992
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 02/03/1997
Action: Closure/No Further Action Letter

Global Id: T0607700505
Action Type: ENFORCEMENT

GREYHOUND LINES INC (Continued) **S104403480**

Date: 09/29/1992
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 05/29/1997
Action: Closure/No Further Action Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 01/15/1997
Action: Closure/No Further Action Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 08/06/1997
Action: Closure/No Further Action Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 06/03/1997
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 02/14/1997
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 01/26/1994
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 11/13/1992
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 10/29/1991
Action: Notice of Reimbursement

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 12/05/1995
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 02/03/1995
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 07/09/1993
Action: Staff Letter

GREYHOUND LINES INC (Continued) **S104403480**

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 04/05/1996
Action: Clean Up Fund - Letter to RP

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 08/12/1991
Action: Unauthorized Release Form

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 08/12/1994
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 07/28/1992
Action: Staff Letter

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 10/03/1991
Action: Notice of Reimbursement

Global Id: T0607700505
Action Type: ENFORCEMENT
Date: 05/25/1993
Action: Staff Letter

Global Id: T0607700505
Action Type: Other
Date: 07/05/1991
Action: Leak Discovery

Global Id: T0607700505
Action Type: Other
Date: 08/12/1991
Action: Leak Reported

Global Id: T0607700505
Action Type: RESPONSE
Date: 02/12/1993
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 05/05/1993
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 08/14/1991
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE

GREYHOUND LINES INC (Continued) **S104403480**

Date: 01/09/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 10/31/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 10/06/1992
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 08/07/1992
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 07/12/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 10/15/1992
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 04/12/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 10/28/1992
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 11/30/1991
Action: Other Report / Document

Global Id: T0607700505
Action Type: RESPONSE
Date: 10/12/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 01/13/1994
Action: Monitoring Report - Other

Global Id: T0607700505
Action Type: RESPONSE
Date: 04/13/1993
Action: Monitoring Report - Quarterly

GREYHOUND LINES INC (Continued) **S104403480**

Global Id: T0607700505
Action Type: RESPONSE
Date: 01/12/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 07/20/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700505
Action Type: RESPONSE
Date: 07/18/1994
Action: Monitoring Report - Semi-Annually

Global Id: T0607700505
Action Type: RESPONSE
Date: 01/14/1997
Action: Monitoring Report - Quarterly

LUST:
Global Id: T0607700505
Status: Open - Case Begin Date
Status Date: 07/05/1991

Global Id: T0607700505
Status: Open - Site Assessment
Status Date: 08/12/1991

Global Id: T0607700505
Status: Completed - Case Closed
Status Date: 05/29/1997

LUST REG 5:
Name: GREYHOUND LINES INC
Address: 121 CENTER ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390654
Case Type: Soil only
Substance: DIESEL
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: GREYHOUND LINES INC
Address: 121 CENTER ST S
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700505
Site/Facility Type: LUST CLEANUP SITE

GREYHOUND LINES INC (Continued) **S104403480**

Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	GREYHOUND LINES INC
edr_fadd1:	121 CENTER
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390654

CERS:

Name:	GREYHOUND LINES INC
Address:	121 CENTER ST S
City,State,Zip:	STOCKTON, CA 95201
Site ID:	204714
CERS ID:	T0607700505
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

130
SW
1/4-1/2
0.341 mi.
1801 ft.

REYNOSO CONCRETE CONST.
729 COMMERCE ST S
STOCKTON, CA 95203

LUST **S101302650**
Cortese **N/A**
HIST CORTESE
CERS

Relative:
Lower

Actual:
16 ft.

LUST:

Name:	REYNOSO CONCRETE CONST.
Address:	729 COMMERCE ST S
City,State,Zip:	STOCKTON, CA 95203

REYNOSO CONCRETE CONST. (Continued) **S101302650**

Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700571
Global Id:	T0607700571
Latitude:	37.944643
Longitude:	-121.29092
Status:	Completed - Case Closed
Status Date:	10/05/1998
Case Worker:	Not reported
RB Case Number:	390735
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	2556
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700571
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700571
Action Type:	Other
Date:	04/14/1992
Action:	Leak Discovery

Global Id:	T0607700571
Action Type:	Other
Date:	06/12/1992
Action:	Leak Reported

LUST:

Global Id:	T0607700571
Status:	Open - Case Begin Date
Status Date:	04/14/1992

Global Id:	T0607700571
Status:	Open - Site Assessment
Status Date:	04/19/1992

Global Id:	T0607700571
Status:	Completed - Case Closed
Status Date:	10/05/1998

LUST REG 5:

Name:	REYNOSO CONCRETE CONST.
Address:	729 COMMERCE ST S
City:	STOCKTON

REYNOSO CONCRETE CONST. (Continued) **S101302650**

Region: 5
Status: Case Closed
Case Number: 390735
Case Type: Soil only
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: REYNOSO CONCRETE CONST.
Address: 729 COMMERCE ST S
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700571
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: REYNDSO CONCRETE CONST.
edr_fadd1: 729 COMMERCE
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390735

CERS:
Name: REYNOSO CONCRETE CONST.
Address: 729 COMMERCE ST S
City,State,Zip: STOCKTON, CA 95203
Site ID: 202344
CERS ID: T0607700571
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)

REYNOSO CONCRETE CONST. (Continued) **S101302650**

Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

S131 **STOCKTON COURTHOUSE REDEVELOPMENT SITE** **CPS-SLIC** **S117338929**
NNW **180 EAST WEBER AVE** **CERS** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.345 mi.
1824 ft. **Site 1 of 2 in cluster S**

Relative:
Lower

Actual:
15 ft.

CPS-SLIC:

Name:	STOCKTON COURTHOUSE REDEVELOPMENT SITE
Address:	180 EAST WEBER AVE
City,State,Zip:	STOCKTON, CA 95202
Region:	STATE
Facility Status:	**Open - Assessment & Interim Remedial Action**
Status Date:	07/16/2014
Global Id:	T10000006328
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Lead Agency Case Number:	Not reported
Latitude:	37.953685723246
Longitude:	-121.289246563229
Case Type:	Cleanup Program Site
Case Worker:	KC
Local Agency:	Not reported
RB Case Number:	2050519
File Location:	Regional Board
Potential Media Affected:	Aquifer used for drinking water supply, Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Polynuclear aromatic hydrocarbons (PAHs), Total Petroleum Hydrocarbons (TPH)
Site History:	On July 16, 2014, a previously unknown UST and the presence of stained soil in a seperate area were discovered during demolition and excavation of the existing buildings the site. An additional UST was discovered on July 29, 2014. Both USTs were removed under permit with SJEHD. The property will be the site of the new Stockton Courthouse.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	STOCKTON COURTHOUSE REDEVELOPMENT SITE
Address:	180 EAST WEBER AVE
City,State,Zip:	STOCKTON, CA 95202
Site ID:	187924
CERS ID:	T10000006328
CERS Description:	Cleanup Program Site

132
SE
1/4-1/2
0.365 mi.
1928 ft.

SIEBOLD CONSTRUCTION CO
820 AMERICAN ST S
STOCKTON, CA 95206

LUST **S101302595**
Cortese **N/A**
HIST CORTESE
CERS

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	SIEBOLD CONSTRUCTION CO
Address:	820 AMERICAN ST S
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700303
Global Id:	T0607700303
Latitude:	37.9452883195277
Longitude:	-121.280527310446
Status:	Completed - Case Closed
Status Date:	12/08/2020
Case Worker:	AMB
RB Case Number:	390394
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Lead, Benzene, Diesel, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Naphthalene, Toluene, Xylene
Site History:	The case was opened following an unauthorized release from an underground storage tank system at the subject site. Corrective action is underway as directed by the CVRWQCB. Corrective action may consist of preliminary site investigation, planning and implementation of remedial action, verification monitoring, or a combination thereof. A summary of the site history is available by clicking on either the "Cleanup Status History", "Regulatory Activities" or the "Site Maps/Documents" tab. For a complete site history the case file at the CVRWQCB should be consulted.

LUST:

Global Id:	T0607700303
Contact Type:	Regional Board Caseworker
Contact Name:	ALAN M. BUEHLER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Dr
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	9164644615

LUST:

Global Id:	T0607700303
Action Type:	RESPONSE
Date:	06/07/2011
Action:	Correspondence
Global Id:	T0607700303
Action Type:	RESPONSE
Date:	01/30/2016
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607700303
Action Type:	ENFORCEMENT

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Date: 02/13/2001
Action: Staff Letter - #1

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/15/2002
Action: Staff Letter - #2

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2012
Action: Soil and Water Investigation Report

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/09/2011
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 04/15/2014
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 01/30/2015
Action: Meeting

Global Id: T0607700303
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: RESPONSE
Date: 10/30/2012
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 12/09/2002
Action: Staff Letter - #3

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 06/08/2011
Action: Site Visit / Inspection / Sampling

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 01/12/2011
Action: Meeting

Global Id: T0607700303
Action Type: RESPONSE
Date: 10/30/2016
Action: Monitoring Report - Semi-Annually

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2017
Action: Monitoring Report - Semi-Annually

Global Id: T0607700303
Action Type: RESPONSE
Date: 08/24/2011
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 08/02/2011
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 12/12/2011
Action: Correspondence - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 05/30/2012
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/25/2011
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 09/01/2010
Action: Notice of Public Hearing / Board Action

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 07/08/2010
Action: Meeting

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 07/18/2016
Action: Staff Letter

Global Id: T0607700303
Action Type: RESPONSE
Date: 12/15/2008
Action: Other Report / Document

Global Id: T0607700303
Action Type: RESPONSE
Date: 09/16/2013
Action: Correspondence - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Date: 12/23/2013
Action: Correspondence - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Other - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2014
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 05/02/2008
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 09/20/2007
Action: Staff Letter - #5

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/07/2007
Action: Meeting - #4

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 11/08/2011
Action: Site Visit / Inspection / Sampling

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 12/14/2011
Action: Site Visit / Inspection / Sampling

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 04/26/2018
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 03/05/2019
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 10/23/2018
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 05/04/2018
Action: Staff Letter

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 07/25/2017
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 04/10/2018
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 01/15/2020
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/18/2020
Action: Staff Letter

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2008
Action: Soil and Water Investigation Workplan

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2014
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/21/2008
Action: Other Report / Document

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 01/31/2008
Action: Staff Letter - #6

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 03/30/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 03/15/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 12/06/2017
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700303
Action Type: ENFORCEMENT

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Date: 12/04/2017
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 03/03/2016
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 12/08/2020
Action: Closure/No Further Action Letter

Global Id: T0607700303
Action Type: Other
Date: 05/24/1989
Action: Leak Began

Global Id: T0607700303
Action Type: Other
Date: 05/17/1989
Action: Leak Discovery

Global Id: T0607700303
Action Type: Other
Date: 05/24/1989
Action: Leak Stopped

Global Id: T0607700303
Action Type: Other
Date: 05/24/1989
Action: Leak Reported

Global Id: T0607700303
Action Type: RESPONSE
Date: 07/24/2017
Action: Request for Closure - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 09/27/2017
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 09/27/2018
Action: Request for Closure - Regulator Responded

Global Id: T0607700303
Action Type: RESPONSE
Date: 10/01/2002
Action: Other Workplan

Global Id: T0607700303
Action Type: RESPONSE
Date: 07/30/2014
Action: Monitoring Report - Quarterly

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Global Id: T0607700303
Action Type: RESPONSE
Date: 10/30/2014
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: RESPONSE
Date: 01/30/2015
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: REMEDIATION
Date: 05/24/1989
Action: Monitored Natural Attenuation

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 09/15/2008
Action: Staff Letter

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 04/24/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 05/01/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 08/23/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2014
Action: Correspondence

Global Id: T0607700303
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: RESPONSE
Date: 04/30/2015
Action: Monitoring Report - Quarterly

Global Id: T0607700303
Action Type: REMEDIATION
Date: 01/15/2014
Action: Monitored Natural Attenuation

Global Id: T0607700303
Action Type: REMEDIATION

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

Date: 10/18/2012
Action: Monitored Natural Attenuation

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 10/15/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 02/04/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 09/13/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700303
Action Type: RESPONSE
Date: 09/22/2010
Action: Verbal Communication

Global Id: T0607700303
Action Type: RESPONSE
Date: 12/07/2015
Action: Soil and Water Investigation Report

Global Id: T0607700303
Action Type: ENFORCEMENT
Date: 11/27/2013
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700303
Status: Open - Case Begin Date
Status Date: 05/17/1989

Global Id: T0607700303
Status: Open - Site Assessment
Status Date: 05/24/1989

Global Id: T0607700303
Status: Open - Remediation
Status Date: 10/18/2012

Global Id: T0607700303
Status: Open - Site Assessment
Status Date: 09/29/2017

Global Id: T0607700303
Status: Open - Eligible for Closure
Status Date: 10/23/2018

Global Id: T0607700303
Status: Completed - Case Closed
Status Date: 12/08/2020

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

LUST REG 5:
Name: SIEBOLD CONSTRUCTION CO
Address: 820 AMERICAN ST S
City: STOCKTON
Region: 5
Status: Pollution Characterization
Case Number: 390394
Case Type: Drinking Water Aquifer affected
Substance: Not reported
Staff Initials: JLB
Lead Agency: Regional
Program: LUST
MTBE Code: 0

CORTESE:
Name: SIEBOLD CONSTRUCTION CO
Address: 820 AMERICAN ST S
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700303
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: SIEBOLD CONSTRUCTION CO
edr_fadd1: 820 AMERICAN
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390394

CERS:
Name: SIEBOLD CONSTRUCTION CO
Address: 820 AMERICAN ST S
City,State,Zip: STOCKTON, CA 95206
Site ID: 234939
CERS ID: T0607700303

SIEBOLD CONSTRUCTION CO (Continued) **S101302595**

CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

S133 **SAN JOAQUIN COUNTY COURTHOUSE** **LUST** **S104403471**
NNW **222 WEBER AVE E** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **HIST CORTESE**
0.365 mi. **CERS**
1929 ft. **Site 2 of 2 in cluster S**

Relative:
Lower

Actual:
15 ft.

LUST:
Name: SAN JOAQUIN COUNTY COURTHOUSE
Address: 222 WEBER AVE E
City,State,Zip: STOCKTON, CA 95202
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700478
Global Id: T0607700478
Latitude: 37.953673792
Longitude: -121.2874388
Status: Completed - Case Closed
Status Date: 12/11/2008
Case Worker: Not reported
RB Case Number: 390610
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 1285
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607700478
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700478
Action Type: Other
Date: 05/15/1991
Action: Leak Discovery

Global Id: T0607700478

SAN JOAQUIN COUNTY COURTHOUSE (Continued) **S104403471**

Action Type: Other
Date: 05/15/1991
Action: Leak Reported

Global Id: T0607700478
Action Type: RESPONSE
Date: 11/08/2008
Action: Correspondence

Global Id: T0607700478
Action Type: RESPONSE
Date: 09/18/2008
Action: Request for Closure

Global Id: T0607700478
Action Type: RESPONSE
Date: 10/15/2008
Action: Well Destruction Workplan

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 08/08/2008
Action: LOP Case Closure Summary to RB - #08/08/2008

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 08/18/2008
Action: Staff Letter - #08/18/2008

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 10/10/2008
Action: Staff Letter - #10/10/2008

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 09/10/2008
Action: Staff Letter - #09/10/2008

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 12/11/2008
Action: Closure/No Further Action Letter - #12/11/2008

Global Id: T0607700478
Action Type: ENFORCEMENT
Date: 04/10/1997
Action: * No Action

LUST:
Global Id: T0607700478
Status: Open - Case Begin Date
Status Date: 05/15/1991

Global Id: T0607700478
Status: Open - Remediation
Status Date: 05/15/1991

SAN JOAQUIN COUNTY COURTHOUSE (Continued) **S104403471**

Global Id:	T0607700478
Status:	Open - Site Assessment
Status Date:	02/03/2001
Global Id:	T0607700478
Status:	Open - Verification Monitoring
Status Date:	07/13/2002
Global Id:	T0607700478
Status:	Open - Site Assessment
Status Date:	01/13/2007
Global Id:	T0607700478
Status:	Open - Site Assessment
Status Date:	01/12/2008
Global Id:	T0607700478
Status:	Open - Verification Monitoring
Status Date:	08/12/2008
Global Id:	T0607700478
Status:	Completed - Case Closed
Status Date:	12/11/2008

LUST REG 5:

Name:	SAN JOAQUIN COUNTY COURTHOUSE
Address:	222 WEBER AVE E
City:	STOCKTON
Region:	5
Status:	Post remedial action monitoring
Case Number:	390610
Case Type:	Drinking Water Aquifer affected
Substance:	GASOLINE
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	2

CORTESE:

Name:	SAN JOAQUIN COUNTY COURTHOUSE
Address:	222 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700478
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active

SAN JOAQUIN COUNTY COURTHOUSE (Continued) **S104403471**

Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	MOTOR POOL
edr_fadd1:	222 WEBER
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390610

CERS:

Name:	SAN JOAQUIN COUNTY COURTHOUSE
Address:	222 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Site ID:	242544
CERS ID:	T0607700478
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

T134 **CONCRET, INC** **LUST** **S101302826**
ESE **749 STANISLAUS ST** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95206** **HIST CORTESE**
0.368 mi. **CERS**
1944 ft. **Site 1 of 2 in cluster T**

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	CONCRET, INC
Address:	749 STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700655
Global Id:	T0607700655
Latitude:	37.9471704
Longitude:	-121.2800939
Status:	Completed - Case Closed
Status Date:	08/09/1994
Case Worker:	Not reported

CONCRET, INC (Continued) **S101302826**

RB Case Number: 390827
Local Agency: Not reported
File Location: Not reported
Local Case Number: 6342
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:
Global Id: T0607700655
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700655
Action Type: Other
Date: 03/01/1994
Action: Leak Discovery

Global Id: T0607700655
Action Type: Other
Date: 03/01/1994
Action: Leak Reported

LUST:
Global Id: T0607700655
Status: Open - Case Begin Date
Status Date: 03/01/1994

Global Id: T0607700655
Status: Completed - Case Closed
Status Date: 08/09/1994

LUST REG 5:
Name: CONCRET, INC
Address: 749 STANISLAUS ST
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390827
Case Type: Soil only
Substance: DIESEL
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: CONCRET, INC
Address: 749 STANISLAUS ST

CONCRET, INC (Continued) **S101302826**

City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700655
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	CONCRET, INC
edr_fadd1:	749 STANISLAUS
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390827

CERS:

Name:	CONCRET, INC
Address:	749 STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Site ID:	252487
CERS ID:	T0607700655
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

U135
SSW
1/4-1/2
0.372 mi.
1965 ft.

R V CIRCUITS
916 SOUTH CENTER STREET
STOCKTON, CA 95206

RESPONSE
ENVIROSTOR
CERS

1000106974
N/A

Site 1 of 2 in cluster U

Relative:
Higher

Actual:
17 ft.

RESPONSE:

Name:	R V CIRCUITS
Address:	916 SOUTH CENTER STREET
City,State,Zip:	STOCKTON, CA 95206
Facility ID:	39340027
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	0.5
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Site Code:	600520
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	13
Senate:	05
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	05/14/2002
Restricted Use:	NO
Funding:	* Unknown
Latitude:	37.94323
Longitude:	-121.2881
APN:	14714036
Past Use:	MANUFACTURING - ELECTRONIC, METAL PLATING - OTHER
Potential COC :	Chromium III Copper and compounds Zinc
Confirmed COC:	Chromium III Copper and compounds Zinc
Potential Description:	SOIL
Alias Name:	RV CIRCUITS
Alias Type:	Alternate Name
Alias Name:	14714036
Alias Type:	APN
Alias Name:	110033612712
Alias Type:	EPA (FRS #)
Alias Name:	600520
Alias Type:	Project Code (Site Code)
Alias Name:	39340027
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	05/14/2002
Comments:	PEA -- A Preliminary Endangerment Assessment (PEA) was completed for the site after approximately 30 tons of contaminated soil had been removed by the property owner. The PEA looked at the hazard and risk posed by the current site conditions as compared to background concentrations for metals, cyanide, volatile and semi-volatile organic compounds. It found that the risk/hazard posed was acceptable for DTSC to grant no further action status. The scope of the PEA did not address lead-based paint or asbestos containing building

R V CIRCUITS (Continued) **1000106974**

materials on site which will be addressed by the city through the building occupancy requirements.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 09/25/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/21/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/14/2002
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: R V CIRCUITS
Address: 916 SOUTH CENTER STREET
City,State,Zip: STOCKTON, CA 95206
Facility ID: 39340027
Status: No Further Action
Status Date: 05/14/2002
Site Code: 600520
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 0.5
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: * Unknown
Latitude: 37.94323
Longitude: -121.2881
APN: 14714036

R V CIRCUITS (Continued) **1000106974**

Past Use: MANUFACTURING - ELECTRONIC, METAL PLATING - OTHER
Potential COC: Chromium III Copper and compounds Zinc
Confirmed COC: Chromium III Copper and compounds Zinc
Potential Description: SOIL
Alias Name: RV CIRCUITS
Alias Type: Alternate Name
Alias Name: 14714036
Alias Type: APN
Alias Name: 110033612712
Alias Type: EPA (FRS #)
Alias Name: 600520
Alias Type: Project Code (Site Code)
Alias Name: 39340027
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/14/2002
Comments: PEA -- A Preliminary Endangerment Assessment (PEA) was completed for the site after approximately 30 tons of contaminated soil had been removed by the property owner. The PEA looked at the hazard and risk posed by the current site conditions as compared to background concentrations for metals, cyanide, volatile and semi-volatile organic compounds. It found that the risk/hazard posed was acceptable for DTSC to grant no further action status. The scope of the PEA did not address lead-based paint or asbestos containing building materials on site which will be addressed by the city through the building occupancy requirements.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 09/25/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/21/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 05/14/2002
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

R V CIRCUITS (Continued) **1000106974**

CERS:
- Name: R V CIRCUITS
- Address: 916 SOUTH CENTER STREET
- City,State,Zip: STOCKTON, CA 95206
- Site ID: 341988
- CERS ID: 39340027
- CERS Description: State Response

Affiliation:
- Affiliation Type Desc: Supervisor
- Entity Name: STEVEN BECKER
- Entity Title: Not reported
- Affiliation Address: Not reported
- Affiliation City: Not reported
- Affiliation State: Not reported
- Affiliation Country: Not reported
- Affiliation Zip: Not reported
- Affiliation Phone: Not reported

U136 **GREAT WESTERN CHEMICAL COMPANY** **RCRA-SQG** **1000158761**
SSW **826 SOUTH CENTER ST** **RESPONSE** **CAD070153473**
1/4-1/2 **STOCKTON, CA 95206** **ENVIROSTOR**
0.373 mi. **HIST Cal-Sites**
1972 ft. **Site 2 of 2 in cluster U** **FINDS**
ECHO

Relative:
Higher

Actual:
17 ft.

RCRA-SQG:

Date Form Received by Agency:	1996-09-01 00:00:00.0
Handler Name:	GREAT WESTERN CHEMICAL COMPANY
Handler Address:	826 SOUTH CENTER ST
Handler City,State,Zip:	STOCKTON, CA 95206
EPA ID:	CAD070153473
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	1
Mailing Address:	826 SOUTH CENTER ST
Mailing City,State,Zip:	STOCKTON, CA 95206
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	MCCALL OIL AND CHEMICAL CORPORATION
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:21:37.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MCCALL OIL AND CHEMICAL CORPORATION

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	808 SW 15TH AVENUE
Owner/Operator City,State,Zip:	CITY NOT REPORTED, OR 99999
Owner/Operator Telephone:	503-228-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MCCALL OIL AND CHEMICAL CORPORATION
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	808 SW 15TH AVENUE
Owner/Operator City,State,Zip:	PORTLAND, OR 97205
Owner/Operator Telephone:	503-228-2600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name:	GREAT WESTERN CHEMICAL COMPANY
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1980-08-14 00:00:00.0
Handler Name:	GREAT WESTERN CHEMICAL COMPANY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1992-02-19 00:00:00.0
Handler Name:	GREAT WESTERN CHEMICAL
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42269
NAICS Description: OTHER CHEMICAL AND ALLIED PRODUCTS WHOLESALERS

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1985-04-18 00:00:00.0
Actual Return to Compliance Date: 1985-04-18 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Enforcement Identifier:	001
Date of Enforcement Action:	1985-04-18 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R9STA
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	1985-04-18 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-04-18 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	FOCUSED COMPLIANCE INSPECTION
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1985-04-18 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

RESPONSE:

Name:	GREAT WESTERN CHEMICAL COMPANY
Address:	826 SOUTH CENTER STREET
City,State,Zip:	STOCKTON, CA 95206
Facility ID:	39280008
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	Not reported
National Priorities List:	NO
Cleanup Oversight Agencies:	NONE SPECIFIED
Lead Agency Description:	Not reported
Project Manager:	Not reported
Supervisor:	* Egarcia2
Division Branch:	Cleanup Sacramento
Site Code:	100324
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	13
Senate:	05
Special Program Status:	Not reported
Status:	Certified
Status Date:	10/21/1994
Restricted Use:	NO
Funding:	Responsible Party
Latitude:	37.94388
Longitude:	-121.2886
APN:	NONE SPECIFIED
Past Use:	DISTRIBUTOR - CHEMICAL
Potential COC :	* UNSPECIFIED AQUEOUS SOLUTION Arsenic
Confirmed COC:	10195-NO Arsenic
Potential Description:	SOIL
Alias Name:	CHEMICAL AND ALLIED PRODUCTS
Alias Type:	Alternate Name
Alias Name:	FRIEDMAN BAG CO
Alias Type:	Alternate Name
Alias Name:	110002656000
Alias Type:	EPA (FRS #)
Alias Name:	100324
Alias Type:	Project Code (Site Code)
Alias Name:	39280008
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Cost Recovery Settlements/Decrees
Completed Date:	06/11/1997
Comments:	COST/STLMT -- The Deputy Attorney General on behalf of DTSC executed a verbal agreement with the PRP. The agreement was for the PRP to pay $9K of the $11.7K in outstanding costs at the site. Payment was made on 6/11/97.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	07/22/1993
Comments:	Final PEA report approved. No further action status will be contingent upon an additional removal of arsenic contamina- ted soil

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

from the Santa Fe Railroad property. The Removal Action is required before the site status will be changed to NFA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Expedited Response Action
Completed Date: 06/15/1993
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 07/27/1990
Comments: SITE SCREENING DONE NEED TO ADDRESS TCE SPILL. RECOMMEND MEDIUM PRIORITY PRELIMINARY ENDANGERMENT ASSESSMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/18/1987
Comments: SITE SCREENING DONE NO CLEANUP DOCUMENTED.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 10/21/1994
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 09/01/1981
Comments: FACILITY IDENTIFIED PERMIT ISD

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: GREAT WESTERN CHEMICAL COMPANY
Address: 826 SOUTH CENTER STREET
City,State,Zip: STOCKTON, CA 95206
Facility ID: 39280008
Status: Certified
Status Date: 10/21/1994
Site Code: 100324
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: * Egarcia2
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.94388
Longitude: -121.2886
APN: NONE SPECIFIED
Past Use: DISTRIBUTOR - CHEMICAL
Potential COC: * UNSPECIFIED AQUEOUS SOLUTION Arsenic
Confirmed COC: 10195-NO Arsenic
Potential Description: SOIL
Alias Name: CHEMICAL AND ALLIED PRODUCTS
Alias Type: Alternate Name
Alias Name: FRIEDMAN BAG CO
Alias Type: Alternate Name
Alias Name: 110002656000
Alias Type: EPA (FRS #)
Alias Name: 100324
Alias Type: Project Code (Site Code)
Alias Name: 39280008
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Cost Recovery Settlements/Decrees
Completed Date: 06/11/1997
Comments: COST/STLMT -- The Deputy Attorney General on behalf of DTSC executed a verbal agreement with the PRP. The agreement was for the PRP to pay $9K of the $11.7K in outstanding costs at the site. Payment was made on 6/11/97.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 07/22/1993
Comments: Final PEA report approved. No further action status will be contingent upon an additional removal of arsenic contamina- ted soil from the Santa Fe Railroad property. The Removal Action is required before the site status will be changed to NFA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Expedited Response Action
Completed Date: 06/15/1993
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 07/27/1990
Comments: SITE SCREENING DONE NEED TO ADDRESS TCE SPILL. RECOMMEND MEDIUM

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

PRIORITY PRELIMINARY ENDANGERMENT ASSESSMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/18/1987
Comments: SITE SCREENING DONE NO CLEANUP DOCUMENTED.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 10/21/1994
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 09/01/1981
Comments: FACILITY IDENTIFIED PERMIT ISD

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Calsite:
Name: GREAT WESTERN CHEMICAL COMPANY
Address: 826 SOUTH CENTER STREET
City: STOCKTON
Region: SACRAMENTO
Facility ID: 39280008
Facility Type: RP
Type: RESPONSIBLE PARTY
Branch: CC
Branch Name: CENTRAL CALIFORNIA
File Name: Not reported
State Senate District: 10211994
Status: CERTIFIED AS HAVING BEEN REMEDIED SATISFACTORILY UNDER DTSC OVERSIGHT
Status Name: CERTIFIED
Lead Agency: N/A
NPL: Not reported
SIC Code: 28
SIC Name: MANU - CHEMICALS & ALLIED PRODUCTS
Access: Controlled
Cortese: Not reported
Hazardous Ranking Score: Not reported
Date Site Hazard Ranked: Not reported
Groundwater Contamination: Not reported
Staff Member Responsible for Site: EGARCIA2
Supervisor Responsible for Site: Not reported
Region Water Control Board: CV
Region Water Control Board Name: CENTRAL VALLEY

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported
State Assembly District Code:	17
State Senate District Code:	05
Facility ID:	39280008
Activity:	DISC
Activity Name:	DISCOVERY
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	09011981
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	SS
Activity Name:	SITE SCREENING
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	02181987
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	SS
Activity Name:	SITE SCREENING

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	07271990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	ERA
Activity Name:	EXPEDITED RESPONSE ACTION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	06151993
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	19
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	N
Activity Comments:	REMOVAL OF SOIL CONTAMINATED WITH ARSENIC.
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	PEA
Activity Name:	PRELIMINARY ENDANGERMENT ASSESSMENT
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	07221993
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	10211994
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	COST
Activity Name:	COST RECOVERY
AWP Code:	SOF
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	05091997
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39280008
Activity:	COST
Activity Name:	COST RECOVERY
AWP Code:	STLMT
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	06111997
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	CERT
Definition of Status:	CERTIFIED
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Alternate Address:	826 SOUTH CENTER STREET
Alternate City,St,Zip:	STOCKTON, CA 95206
Background Info:	Not reported
Comments Date:	02181987
Comments:	SITE SCREENING DONE NO CLEANUP DOCUMENTED.
Comments Date:	04071993
Comments:	ERA - removed approximately 19 cubic yards of soil
Comments Date:	04071993
Comments:	contaminated with aresenic. Approx. cost = $10,200.00
Comments Date:	04071993
Comments:	Not reported
Comments Date:	04071993
Comments:	Not reported
Comments Date:	04071993
Comments:	Not reported
Comments Date:	04121982
Comments:	QUEST SENT
Comments Date:	04181985
Comments:	INSPECTION(STATE) DHS GENERATOR INSPECTION: SAMPLES SHOWED
Comments Date:	04181985
Comments:	CONTAMINATION WITH COPPER.
Comments Date:	05091997
Comments:	COST/SOF -- Prepared Statement of Facts for referral to the
Comments Date:	05091997
Comments:	Attorney General's Office for recovery of DTSC's costs.
Comments Date:	05131982
Comments:	FACILITY DRIVE-BY NO BERMS BUT POSTED & FENCED
Comments Date:	05141982
Comments:	EPA SIC # 5161 - CHEMICAL & ALLIED PROD
Comments Date:	06011990

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Comments: INSPECTION(OTHER) SAMPLING CONDUCTED BY LEVINE & FRICKE
Comments Date: 06011990
Comments: SHOWED COPPER AND ARSENIC CONTAMINATION.
Comments Date: 06111997
Comments: COST/STLMT -- The Deputy Attorney General on behalf of DTSC
Comments Date: 06111997
Comments: executed a verbal agreement with the PRP. The agreement was
Comments Date: 06111997
Comments: for the PRP to pay $9K of the $11.7K in outstanding costs at
Comments Date: 06111997
Comments: the site. Payment was made on 6/11/97.
Comments Date: 07221993
Comments: Final PEA report approved. No further action status will be
Comments Date: 07221993
Comments: contingent upon an additional removal of arsenic contamina-
Comments Date: 07221993
Comments: ted soil from the Santa Fe Railroad property. The Removal
Comments Date: 07221993
Comments: Action is required before the site status will be changed to
Comments Date: 07221993
Comments: NFA.
Comments Date: 07271990
Comments: SITE SCREENING DONE NEED TO ADDRESS TCE SPILL. RECOMMEND
Comments Date: 07271990
Comments: MEDIUM PRIORITY PRELIMINARY ENDANGERMENT
Comments Date: 07271990
Comments: ASSESSMENT.
Comments Date: 08301982
Comments: Q RECEIVED CLAIMS NO WASTE DISPOSED
Comments Date: 08311994
Comments: Final removal of arsenic contaminated soil completed in June
Comments Date: 08311994
Comments: 1994.
Comments Date: 09011981
Comments: FACILITY IDENTIFIED PERMIT ISD
Comments Date: 09141981
Comments: INSPECTION(STATE) HWMB/ENF INSPECTION
Comments Date: 09281981
Comments: HWMB/ENF
Comments Date: 10291982
Comments: FINAL STRATEGY SITE REFERRED: TO HWMB/ENF,CO HLTH.
Comments Date: 11031981
Comments: RWQCB
Comments Date: 11091981
Comments: PHONE FOLLOW UP-NO WASTE DISPOSAL
ID Name: CALSTARS CODE
ID Value: 100324
Alternate Name: GREAT WESTERN CHEMICAL COMPANY
Alternate Name: CHEMICAL AND ALLIED PRODUCTS
Alternate Name: FRIEDMAN BAG CO
Alternate Name: Not reported
Special Programs Code: Not reported
Special Programs Name: Not reported

FINDS:
Registry ID: 110002656000

GREAT WESTERN CHEMICAL COMPANY (Continued) **1000158761**

Click Here:

Environmental Interest/Information System:
California Department of Toxic Substances Control EnviroStor System (DTSC-EnviroStor) is an online search and Geographic Information System (GIS) tool for identifying sites that have known contamination or sites for which there may be reasons to investigate further. The EnviroStor database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000158761
Registry ID:	110002656000
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002656000
Name:	GREAT WESTERN CHEMICAL COMPANY
Address:	826 SOUTH CENTER ST
City,State,Zip:	STOCKTON, CA 95206

V137 **RITE WAY CLEANERS** **SEMS-ARCHIVE** **1003109067**
NE **700 EAST MARKET STREET** **CAN000905714**
1/4-1/2 **STOCKTON, CA 95202**
0.391 mi.
2067 ft. **Site 1 of 4 in cluster V**

Relative: **Higher**
Actual: **18 ft.**

SEMS Archive:

Site ID:	0905714
EPA ID:	CAN000905714
Name:	RITE WAY CLEANERS
Address:	700 EAST MARKET STREET
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 95202
Cong District:	Not reported
FIPS Code:	06077
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0905714
EPA ID:	CAN000905714
Site Name:	RITE WAY CLEANERS
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE

RITE WAY CLEANERS (Continued) **1003109067**

SEQ: 1
Start Date: Not reported
Finish Date: 2013-11-08 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0905714
EPA ID: CAN000905714
Site Name: RITE WAY CLEANERS
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 2000-07-05 04:00:00
Finish Date: 2000-07-05 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0905714
EPA ID: CAN000905714
Site Name: RITE WAY CLEANERS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 2010-06-29 05:00:00
Finish Date: 2010-08-10 04:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 09
Site ID: 0905714
EPA ID: CAN000905714
Site Name: RITE WAY CLEANERS
NPL: N
FF: N
OU: 00
Action Code: HX
Action Name: PRE-CERC
SEQ: 1
Start Date: Not reported
Finish Date: 2000-07-05 04:00:00
Qual: Not reported
Current Action Lead: St Perf

V138 **RITE WAY CLEANERS** **ENVIROSTOR** **S110711856**
NE **700 EAST MARKET STREET** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.391 mi.
2067 ft. **Site 2 of 4 in cluster V**

Relative: **Higher**

Actual: **18 ft.**

ENVIROSTOR:

Name:	RITE WAY CLEANERS
Address:	700 EAST MARKET STREET
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	60001402
Status:	Inactive - Needs Evaluation
Status Date:	02/01/2011
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	0.25
NPL:	NO
Regulatory Agencies:	SMBRP, US EPA, SAN JOAQUIN COUNTY
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup San Joaquin
Assembly:	13
Senate:	05
Special Program:	EPA - PASI
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not Applicable
Latitude:	37.95299
Longitude:	-121.2815
APN:	149-220-11, 149-220-12
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	149-220-11
Alias Type:	APN
Alias Name:	149-220-12
Alias Type:	APN
Alias Name:	CAN000905714
Alias Type:	CERCLIS ID
Alias Name:	CAD981642382
Alias Type:	EPA Identification Number
Alias Name:	110002736166
Alias Type:	EPA (FRS #)
Alias Name:	60001402
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	06/10/2010
Comments:	USEPA completed a Preliminary Assessment for the site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	PA/SI Discovery
Completed Date:	06/30/1998

RITE WAY CLEANERS (Continued) **S110711856**

Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	PA/SI Site Screening
Completed Date:	07/05/2000
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

W139 **SOUTH POINT (AREA 1)** **US BROWNFIELDS** **1012237419**
NNW **100 WEBER AVE E** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.392 mi.
2071 ft. **Site 1 of 8 in cluster W**

Relative: **Lower**

Actual: **14 ft.**

US BROWNFIELDS:

Name:	SOUTH POINT (AREA 1)
Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	5.7
Latitude:	37.95362
Longitude:	-121.290719
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14278
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N

SOUTH POINT (AREA 1) (Continued) **1012237419**

Cooperative Agreement Number:	99944601
Start Date:	12/31/1999
Ownership Entity:	-
Completion Date:	12/31/1999
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	N
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-

SOUTH POINT (AREA 1) (Continued) **1012237419**

Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09
Unemployed Number:	337
Unemployed Percent:	13.35

W140 **AREA 4** **US BROWNFIELDS** **1012237398**
NNW **100 WEBER AVE E** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.392 mi.
2071 ft. **Site 2 of 8 in cluster W**

Relative: US BROWNFIELDS:
Lower

Name:	AREA 4
Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of

Actual:
14 ft.

AREA 4 (Continued) **1012237398**

Grant Type:	Assessment
Property Number:	-
Parcel size:	-
Latitude:	37.95362
Longitude:	-121.290719
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14281
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/1998
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/2001
Ownership Entity:	-
Completion Date:	09/30/2001
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	N
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-

AREA 4 (Continued) **1012237398**

Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-

AREA 4 (Continued) **1012237398**

Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09
Unemployed Number:	337
Unemployed Percent:	13.35

Name:	AREA 4
Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	-
Latitude:	37.95362
Longitude:	-121.290719
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14281
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/1998
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/2001
Ownership Entity:	-
Completion Date:	09/30/2001
Current Owner:	-

AREA 4 (Continued) **1012237398**

Did Owner Change:	-
Cleanup Required:	N
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-

AREA 4 (Continued) **1012237398**

Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09
Unemployed Number:	337
Unemployed Percent:	13.35

W141 **WEBER BLOCK (AREA 9)** **US BROWNFIELDS** **1012236986**
NNW **100 WEBER AVE E** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.392 mi.
2071 ft. **Site 3 of 8 in cluster W**

Relative: US BROWNFIELDS:
Lower

Actual: Name:	WEBER BLOCK (AREA 9)
14 ft. Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	10
Latitude:	37.95362
Longitude:	-121.290719

WEBER BLOCK (AREA 9) (Continued) **1012236986**

HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14268
IC Data Access:	-
Start Date:	09/30/2000
Redev Completition Date:	-
Completed Date:	09/30/2000
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2000
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	12/31/1998
Ownership Entity:	-
Completion Date:	12/31/1998
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09
Unemployed Number:	337
Unemployed Percent:	13.35

Name:	WEBER BLOCK (AREA 9)
Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	10
Latitude:	37.95362
Longitude:	-121.290719
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14268
IC Data Access:	-
Start Date:	09/30/2000
Redev Completition Date:	-
Completed Date:	09/30/2000
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2000
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	12/31/1998
Ownership Entity:	-
Completion Date:	12/31/1998
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09
Unemployed Number:	337
Unemployed Percent:	13.35

Name:	WEBER BLOCK (AREA 9)
Address:	100 WEBER AVE E
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	10
Latitude:	37.95362
Longitude:	-121.290719
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14268
IC Data Access:	-
Start Date:	09/30/2000
Redev Completition Date:	-
Completed Date:	09/30/2000
Acres Cleaned Up:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2000
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	12/31/1998
Ownership Entity:	-
Completion Date:	12/31/1998
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-

WEBER BLOCK (AREA 9) (Continued) **1012236986**

Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1226
Below Poverty Percent:	48.57
Meidan Income:	2215
Meidan Income Number:	2092
Meidan Income Percent:	82.88
Vacant Housing Number:	299
Vacant Housing Percent:	20.09

WEBER BLOCK (AREA 9) (Continued) **1012236986**

Unemployed Number: 337
Unemployed Percent: 13.35

W142 **WEBER BLOCK** **ENVIROSTOR** **S103393831**
NNW **WEBER AVE. AND EL DORADO ST.** **VCP** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **DEED**
0.392 mi.
2071 ft. **Site 4 of 8 in cluster W**

Relative: **Lower**

Actual: **14 ft.**

ENVIROSTOR:

Name:	WEBER BLOCK
Address:	WEBER AVE. AND EL DORADO ST.
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	39750009
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	11/08/2002
Site Code:	100980
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	1.9
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Melessia Downham
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	YES
Site Mgmt Req:	REM, DAY, ELD, HOS, LUC, MON, EX, NOWN, NSUB, EXT, HS, SCH, RES
Funding:	Responsible Party
Latitude:	37.95411
Longitude:	-121.2908
APN:	139-090-02, 13909002
Past Use:	ENGINE TESTING/REPAIR, FUEL - VEHICLE STORAGE/ REFUELING
Potential COC:	* OXYGENATED SOLVENTS * CONTAMINATED SOIL
Confirmed COC:	NONE SPECIFIED
Potential Description:	OTH, SED, SOIL
Alias Name:	WEBER BLOCK
Alias Type:	Alternate Name
Alias Name:	139-090-02
Alias Type:	APN
Alias Name:	13909002
Alias Type:	APN
Alias Name:	110033614435
Alias Type:	EPA (FRS #)
Alias Name:	100980
Alias Type:	Project Code (Site Code)
Alias Name:	39750009
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	10/09/1998
Comments:	VCOMP/SAMPL -- DTSC ENTERED INTO A VOLUNTARY CLEANUP AGREEMENT WITH

WEBER BLOCK (Continued) **S103393831**

THE STOCKTON DEPARTMENT OF HOUSING AND DEVELOPMENT TO REVIEW AND APPROVE A SITE SAMPLING PLAN AND OVERSEE SAMPLING ACTIVITIES. THESE ACTIVITIES HAVE BEEN COMPLETED PER THE TERMS OF THE AGREEMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 11/02/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 11/04/2002
Comments: DEED - PEA conditionally approved on March 27, 2000. Deed restriction recorded in the San Joaquin County Recorder's office on November 4, 2002. DTSC issued a No Further Action letter to the City of Stockton on November 8, 2002.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 08/27/1999
Comments: ORDER/VCA - Oversight and Consultation Agreement (i.e. VCA) signed by DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/05/1998
Comments: ORDER/VCA -- AN AGREEMENT WAS ENTERED INTO WITH THE STOCKTON REDEVELOPMENT AGENCY TO REVIEW A PROPOSED SAMPLING WORKPLAN FOR THE WEBER BLOCK PROPERTY AND OVERSEE FIELDWORK APPROVED IN THE WORKPLAN.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/08/2002
Comments: DTSC ISSUE A NO FURTHER ACTION LETTER DATED 11/8/2002 TO THE CITY OF STOCKTON HOUSING AND REDEVELOPMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/15/2011
Comments: 2012 LUC Annual Report conducted on 12/15/2011 by DTSC staff.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/24/2017
Comments: 2017 LUC Inspection and Report completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/31/2018

WEBER BLOCK (Continued) **S103393831**

Comments:	completed 5/31/2018
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	04/04/2019
Comments:	completed
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	05/19/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	06/27/2013
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	02/05/2015
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Land Use Restriction Monitoring Report
Completed Date:	05/31/2016
Comments:	2016 Annual LUC Inspection
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	03/15/2000
Comments:	PEA/VCOMP - PEA approved; Further action required, specifically deed restriction to restrict certain land uses.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	01/01/1993
Comments:	RA -- GROUNDWATER EXTRACTION AND TREATMENT
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	01/01/1991
Comments:	RA -- 1 OIL UST REMOVED
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	01/01/1981
Comments:	RA -- 3 UST REMOVED. SHELL OIL COMPANY OPERATED AT 141 EL DORADO STREET BETWEEN 1955 AND 1984. AN UNIDENTIFIED AUTOMOTIVE REPAIR SHOP

WEBER BLOCK (Continued) **S103393831**

OPERATED AT THE SITE AFTER 1984.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/31/2018
Comments: completed 5/31/2018

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2016
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2015/2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2017
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/01/2021

WEBER BLOCK (Continued) **S103393831**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/18/2020
Comments: completed

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: WEBER BLOCK
Address: WEBER AVE. AND EL DORADO ST.
City,State,Zip: STOCKTON, CA 95202
Facility ID: 39750009
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: REM, DAY, ELD, HOS, LUC, MON, EX, NOWN, NSUB, EXT, HS, SCH, RES
Acres: 1.9
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Melessia Downham
Supervisor: Lora Jameson
Division Branch: Northern California Schools & Santa Susana
Site Code: 100980
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: Certified O&M - Land Use Restrictions Only
Status Date: 11/08/2002
Restricted Use: YES
Funding: Responsible Party
Lat/Long: 37.95411 / -121.2908
APN: 139-090-02, 13909002
Past Use: ENGINE TESTING/REPAIR, FUEL - VEHICLE STORAGE/ REFUELING
Potential COC: 10067, 10097
Confirmed COC: NONE SPECIFIED
Potential Description: OTH, SED, SOIL
Alias Name: WEBER BLOCK
Alias Type: Alternate Name
Alias Name: 139-090-02
Alias Type: APN
Alias Name: 13909002
Alias Type: APN
Alias Name: 110033614435
Alias Type: EPA (FRS #)
Alias Name: 100980

WEBER BLOCK (Continued) **S103393831**

Alias Type: Project Code (Site Code)
Alias Name: 39750009
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 10/09/1998
Comments: VCOMP/SAMPL -- DTSC ENTERED INTO A VOLUNTARY CLEANUP AGREEMENT WITH THE STOCKTON DEPARTMENT OF HOUSING AND DEVELOPMENT TO REVIEW AND APPROVE A SITE SAMPLING PLAN AND OVERSEE SAMPLING ACTIVITIES. THESE ACTIVITIES HAVE BEEN COMPLETED PER THE TERMS OF THE AGREEMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 11/02/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 11/04/2002
Comments: DEED - PEA conditionally approved on March 27, 2000. Deed restriction recorded in the San Joaquin County Recorder's office on November 4, 2002. DTSC issued a No Further Action letter to the City of Stockton on November 8, 2002.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 08/27/1999
Comments: ORDER/VCA - Oversight and Consultation Agreement (i.e. VCA) signed by DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/05/1998
Comments: ORDER/VCA -- AN AGREEMENT WAS ENTERED INTO WITH THE STOCKTON REDEVELOPMENT AGENCY TO REVIEW A PROPOSED SAMPLING WORKPLAN FOR THE WEBER BLOCK PROPERTY AND OVERSEE FIELDWORK APPROVED IN THE WORKPLAN.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/08/2002
Comments: DTSC ISSUE A NO FURTHER ACTION LETTER DATED 11/8/2002 TO THE CITY OF STOCKTON HOUSING AND REDEVELOPMENT.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 12/15/2011
Comments: 2012 LUC Annual Report conducted on 12/15/2011 by DTSC staff.

Completed Area Name: PROJECT WIDE

WEBER BLOCK (Continued) **S103393831**

Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/24/2017
Comments: 2017 LUC Inspection and Report completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/31/2018
Comments: completed 5/31/2018

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 04/04/2019
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/19/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 06/27/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 02/05/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 05/31/2016
Comments: 2016 Annual LUC Inspection

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/15/2000
Comments: PEA/VCOMP - PEA approved; Further action required, specifically deed restriction to restrict certain land uses.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/01/1993
Comments: RA -- GROUNDWATER EXTRACTION AND TREATMENT

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report

WEBER BLOCK (Continued) **S103393831**

Completed Date: 01/01/1991
Comments: RA -- 1 OIL UST REMOVED

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/01/1981
Comments: RA -- 3 UST REMOVED. SHELL OIL COMPANY OPERATED AT 141 EL DORADO STREET BETWEEN 1955 AND 1984. AN UNIDENTIFIED AUTOMOTIVE REPAIR SHOP OPERATED AT THE SITE AFTER 1984.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/31/2018
Comments: completed 5/31/2018

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2016
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2015/2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2017
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE

WEBER BLOCK (Continued) **S103393831**

Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/01/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 02/18/2020
Comments: completed

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

DEED:
Name: WEBER BLOCK
Address: WEBER AVE. AND EL DORADO ST.
City,State,Zip: STOCKTON, CA 95202
Envirostor ID: 39750009
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

V143 **GOODWILL INDUSTRIES** **LUST** **S105034675**
NE **129 GRANT ST S** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **CERS**
0.393 mi.
2077 ft. **Site 3 of 4 in cluster V**

Relative:
Higher

Actual:
18 ft.

LUST:
Name: GOODWILL INDUSTRIES
Address: 129 GRANT ST S
City,State,Zip: STOCKTON, CA 95202
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700178
Global Id: T0607700178
Latitude: 37.9526619
Longitude: -121.280873

GOODWILL INDUSTRIES (Continued) **S105034675**

Status:	Completed - Case Closed
Status Date:	03/19/1996
Case Worker:	Not reported
RB Case Number:	390249
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	0001397
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

LUST:

Global Id:	T0607700178
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700178
Action Type:	Other
Date:	06/21/1988
Action:	Leak Discovery

Global Id:	T0607700178
Action Type:	Other
Date:	06/21/1988
Action:	Leak Reported

LUST:

Global Id:	T0607700178
Status:	Open - Case Begin Date
Status Date:	06/21/1988

Global Id:	T0607700178
Status:	Completed - Case Closed
Status Date:	03/19/1996

LUST REG 5:

Name:	GOODWILL INDUSTRIES
Address:	129 GRANT ST S
City:	STOCKTON
Region:	5
Status:	Case Closed
Case Number:	390249
Case Type:	Soil only
Substance:	MOTOR OIL
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	N/A

GOODWILL INDUSTRIES (Continued) **S105034675**

CORTESE:

Name:	GOODWILL INDUSTRIES
Address:	129 GRANT ST S
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700178
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	GOODWILL INDUSTRIES
Address:	129 GRANT ST S
City,State,Zip:	STOCKTON, CA 95202
Site ID:	195457
CERS ID:	T0607700178
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

X144 **MAIN STREET INVESTORS** **LUST** **S108196285**
NNE **601 E. MAIN STREET** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.403 mi.
2126 ft. **Site 1 of 2 in cluster X**

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	MAIN STREET INVESTORS
Address:	601 E. MAIN STREET
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)

MAIN STREET INVESTORS (Continued) **S108196285**

Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607762422
Global Id:	T0607762422
Latitude:	37.954035
Longitude:	-121.282986
Status:	Open - Site Assessment
Status Date:	04/09/2015
Case Worker:	VJF
RB Case Number:	391157
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	Not reported
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Heating Oil / Fuel Oil
Site History:	SMALL 3000 GAL UST DISCOVERED DURING SIDE WALK REPLACEMENT JULY 2004. HEAVY PETROLEUM PRODUCT INSIDE OOZES TO SOIL AFTER BACKHOE RIPS UST OPEN. MOST LIQUID AND IMPACTED SOIL REMOVED. SITE ENTERS EHD-LOP JULY 9, 2004. BUILDING OWNER AND CITY OF STOCKTON NAMED RPs. SOIL BORINGS AND GW GRAB SAMPLES COLLECTED MARCH 2009. TPHG&D DETECTED IN GW. EHD MAY 29, 2009 LETTER REQUIRES ADDITIONAL LATERAL GW INVESTIGATION. 2-16-10: WP FOR ADDNL SB RECEIVED AND EHD 2-23-10 LETTER CONDITIONALLY APPROVES. 3-23-10: WP ADDN REC'D AND LETTER 3-29-10 CONDITIONALLY APPROVES. APRIL 8, 2010: CONFIRMATION SOIL BORING B-3 DRILLED OFFSITE TODAY. MAY 24, 2010: REPORT OF FINDINGS, BORING B-3 RECEIVED ON GT. 5-28-2010: EHD comment letter on report & NFAR request. Jan 18, 2011: Receive "Closure Summary Report. April 15, 2011: EHD comment letter to closure-request additional data. Oct 6, 2011; Still no progress towards NFA-data missing still not submitted.

LUST:

Global Id:	T0607762422
Contact Type:	Regional Board Caseworker
Contact Name:	VERA FISCHER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	vera.fischer@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607762422
Action Type:	ENFORCEMENT
Date:	12/09/2009
Action:	Verbal Enforcement
Global Id:	T0607762422
Action Type:	ENFORCEMENT
Date:	07/07/2015
Action:	Staff Letter
Global Id:	T0607762422
Action Type:	ENFORCEMENT
Date:	02/23/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607762422
Action Type:	ENFORCEMENT

MAIN STREET INVESTORS (Continued) **S108196285**

Date: 03/29/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/24/2010
Action: File review

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 04/08/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/28/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 04/09/2015
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/20/2016
Action: Staff Letter

Global Id: T0607762422
Action Type: RESPONSE
Date: 03/06/2019
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/01/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 10/12/2015
Action: Staff Letter

Global Id: T0607762422
Action Type: RESPONSE
Date: 02/12/2014
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 04/15/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 01/18/2011
Action: File Review - Closure

MAIN STREET INVESTORS (Continued) **S108196285**

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/04/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/06/2018
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 07/27/2017
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 06/02/2017
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 03/26/2020
Action: Staff Letter

Global Id: T0607762422
Action Type: RESPONSE
Date: 06/02/2017
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 04/23/2019
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 10/29/2020
Action: Staff Letter

Global Id: T0607762422
Action Type: Other
Date: 07/02/2004
Action: Leak Discovery

Global Id: T0607762422
Action Type: Other
Date: 07/02/2004
Action: Leak Stopped

Global Id: T0607762422
Action Type: Other
Date: 07/02/2004
Action: Leak Reported

Global Id: T0607762422
Action Type: ENFORCEMENT

MAIN STREET INVESTORS (Continued) **S108196285**

Date: 11/14/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: RESPONSE
Date: 08/13/2007
Action: Correspondence

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/08/2007
Action: Meeting

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/14/2007
Action: Meeting

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 10/21/2008
Action: Notice to Comply

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/01/2007
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 08/06/2007
Action: Warning Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 08/21/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 10/09/2007
Action: Staff Letter

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 10/04/2007
Action: Notice of Violation

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/08/2012
Action: File review

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 06/06/2013
Action: Technical Correspondence / Assistance / Other

MAIN STREET INVESTORS (Continued) **S108196285**

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 01/13/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/28/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 05/29/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 11/02/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 04/23/2009
Action: File review

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 03/25/2009
Action: Site Visit / Inspection / Sampling

Global Id: T0607762422
Action Type: ENFORCEMENT
Date: 09/16/2014
Action: Staff Letter

LUST:
Global Id: T0607762422
Status: Open - Case Begin Date
Status Date: 07/02/2004

Global Id: T0607762422
Status: Open - Site Assessment
Status Date: 07/02/2004

Global Id: T0607762422
Status: Open - Eligible for Closure
Status Date: 03/19/2015

Global Id: T0607762422
Status: Open - Site Assessment
Status Date: 04/09/2015

X145 **MAIN STREET INVESTORS** **LUST** **S106447531**
NNE **601 E. MAIN STREET** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **CERS**
0.403 mi.
2126 ft. **Site 2 of 2 in cluster X**

Relative:
Higher

Actual:
17 ft.

LUST REG 5:

Name:	MAIN STREET INVESTORS
Address:	601 E. MAIN STREET
City:	STOCKTON
Region:	5
Status:	Leak being confirmed
Case Number:	391157
Case Type:	Soil only
Substance:	HEATER FUEL
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	N/A

CORTESE:

Name:	MAIN STREET INVESTORS
Address:	601 E. MAIN STREET
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607762422
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	OPEN - SITE ASSESSMENT
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	MAIN STREET INVESTORS
Address:	601 E. MAIN STREET
City,State,Zip:	STOCKTON, CA 95202
Site ID:	193771
CERS ID:	T0607762422
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200

MAIN STREET INVESTORS (Continued) **S106447531**

Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

W146 **MINER'S LEVEE (AREA 17)** **US BROWNFIELDS** **1016352552**
NW **UNKNOWN** **FINDS** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.406 mi.
2146 ft. **Site 5 of 8 in cluster W**

Relative: **Lower**

Actual: **14 ft.**

US BROWNFIELDS:

Name:	MINER'S LEVEE (AREA 17)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14285
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	03/31/2005
Ownership Entity:	Government
Completion Date:	03/31/2005
Current Owner:	City of Stockton
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	-
Institutional Controls Required:	N
IC Category Proprietary Controls:	-

MINER'S LEVEE (AREA 17) (Continued) **1016352552**

IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-

MINER'S LEVEE (AREA 17) (Continued) **1016352552**

Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403
Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05

FINDS:
Registry ID: 110039554372

Click Here:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

W147 **AREA 20 (NORTH SHORE)** **US BROWNFIELDS** **1012237022**
NW **UNKNOWN** **FINDS** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.406 mi.
2146 ft. **Site 6 of 8 in cluster W**

Relative: **Lower**

Actual: **14 ft.**

US BROWNFIELDS:

Name:	AREA 20 (NORTH SHORE)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	19381
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	99944601
Start Date:	-
Ownership Entity:	-
Completion Date:	-
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	Y
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403
Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05

Name:	AREA 21 (NORTH SHORE)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	19382
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	-
Accomplishment Count:	-
Cooperative Agreement Number:	99944601
Start Date:	-
Ownership Entity:	-
Completion Date:	-
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	Y
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403
Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05

Name:	BANNER ISLAND (AREA 10)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14277
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/2001
Ownership Entity:	-
Completion Date:	09/30/2001
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y
Video Available:	-
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1331
Below Poverty Percent:	31.53
Meidan Income:	4200
Meidan Income Number:	2393
Meidan Income Percent:	56.69
Vacant Housing Number:	348
Vacant Housing Percent:	15.68
Unemployed Number:	357
Unemployed Percent:	8.46

Name:	BANNER ISLAND (AREA 10)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14277
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/2001
Ownership Entity:	-
Completion Date:	09/30/2001
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Video Available:	-
Photo Available:	Y
Institutional Controls Required:	N
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1331
Below Poverty Percent:	31.53
Meidan Income:	4200
Meidan Income Number:	2393
Meidan Income Percent:	56.69
Vacant Housing Number:	348
Vacant Housing Percent:	15.68
Unemployed Number:	357
Unemployed Percent:	8.46

FINDS:
Registry ID: 110070068912

Click Here:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.
Registry ID: 110070068913

Click Here:

Environmental Interest/Information System:
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

AREA 20 (NORTH SHORE) (Continued) **1012237022**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

W148 **STOCKTON IRON WORKS (AREA 13)** **US BROWNFIELDS** **1012237218**
NW **UNKNOWN** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.406 mi.
2146 ft. **Site 7 of 8 in cluster W**

Relative: **Lower**
Actual: **14 ft.**

US BROWNFIELDS:

Name:	STOCKTON IRON WORKS (AREA 13)
Address:	UNKNOWN
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	Former Use: Heavy equipment manufacturing
Datum:	-
Acres Property ID:	14271
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/1997
Ownership Entity:	Private
Completion Date:	09/30/1997
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	Y
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-

STOCKTON IRON WORKS (AREA 13) (Continued) **1012237218**

IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-

STOCKTON IRON WORKS (AREA 13) (Continued) **1012237218**

SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	Heavy equipment manufacturing
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403
Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05

W149 **MARINA TOWERS EAST (AREA 11)** **US BROWNFIELDS** **1012237251**
NW **LINDSAY STREET** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.406 mi.
2146 ft. **Site 8 of 8 in cluster W**

Relative: US BROWNFIELDS:
Lower

Actual: Name:	MARINA TOWERS EAST (AREA 11)
14 ft. Address:	LINDSAY STREET
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14273
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-

MARINA TOWERS EAST (AREA 11) (Continued) **1012237251**

Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/1997
Ownership Entity:	-
Completion Date:	09/30/1997
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	Y
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-

MARINA TOWERS EAST (AREA 11) (Continued) **1012237251**

Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403

MARINA TOWERS EAST (AREA 11) (Continued) **1012237251**

Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05
Name:	MARINA TOWERS EAST (AREA 11)
Address:	LINDSAY STREET
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	0
Latitude:	37.953602
Longitude:	-121.290718
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14273
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	09/30/2005
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	09/30/1997
Ownership Entity:	-
Completion Date:	09/30/1997
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	Y
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-

MARINA TOWERS EAST (AREA 11) (Continued) **1012237251**

Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-

MARINA TOWERS EAST (AREA 11) (Continued) **1012237251**

Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1677
Below Poverty Percent:	50.15
Meidan Income:	2390
Meidan Income Number:	2887
Meidan Income Percent:	86.33
Vacant Housing Number:	403
Vacant Housing Percent:	20.92
Unemployed Number:	403
Unemployed Percent:	12.05

V150 **GOODWILL INDUSTRIES** **CERS HAZ WASTE** **U001603239**
NE **129 GRANT** **HIST UST** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **HIST CORTESE**
0.410 mi.
2164 ft. **Site 4 of 4 in cluster V**

Relative:
Higher

Actual:
18 ft.

CERS HAZ WASTE:

Name:	GOODWILL INDUSTRIES OF SJV
Address:	129 S GRANT ST
City,State,Zip:	STOCKTON, CA 95202
Site ID:	447492
CERS ID:	10779607
CERS Description:	Hazardous Waste Generator

Coordinates:

Site ID:	447492
Facility Name:	Goodwill Industries of SJV
Env Int Type Code:	HWG
Program ID:	10779607
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	37.952620
Longitude:	-121.280850

Affiliation:

Affiliation Type Desc:	CUPA District
Entity Name:	San Joaquin Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	1868 East Hazelton Avenue
Affiliation City:	Stockton
Affiliation State:	CA

GOODWILL INDUSTRIES (Continued) **U001603239**

Affiliation Country: Not reported
Affiliation Zip: 95205-6232
Affiliation Phone: (209) 468-3420

Affiliation Type Desc: Document Preparer
Entity Name: Anna Castro
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: Stericycle
Entity Title: Not reported
Affiliation Address: 11855 White Rock Rd
Affiliation City: Rancho Cordova
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95742
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: Goodwill Industries of SJV
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner
Entity Name: Goodwill Industries of SJV
Entity Title: Not reported
Affiliation Address: 129 S Grant St
Affiliation City: Stockton
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95202
Affiliation Phone: (209) 466-2311

Affiliation Type Desc: Operator
Entity Name: Goodwill Industries of SJV
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (209) 466-2311

Affiliation Type Desc: Property Owner
Entity Name: Goodwill Industries of SJV
Entity Title: Not reported

GOODWILL INDUSTRIES (Continued) **U001603239**

Affiliation Address:	129 S Grant St.
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95202
Affiliation Phone:	(209) 466-2311
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	129 S Grant St
Affiliation City:	Stockton
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95202
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Anna Castro
Entity Title:	Director of Operations
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

HIST UST:

Name:	GOODWILL INDUSTRIES OF SAN JOA
Address:	129 S GRANT ST
City,State,Zip:	STOCKTON, CA 95202
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000036521
Facility Type:	Other
Other Type:	REHABILITATION FACIL
Contact Name:	DARYL D. DAVENPORT
Telephone:	2094662311
Owner Name:	GOODWILL INDUSTRIES OF SAN JOA
Owner Address:	129 SOUTH GRANT
Owner City,St,Zip:	STOCKTON, CA 95202
Total Tanks:	0002
Tank Num:	001
Container Num:	1
Year Installed:	1967
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	0.25
Leak Detection:	Visual
Tank Num:	002
Container Num:	2
Year Installed:	1967

GOODWILL INDUSTRIES (Continued) **U001603239**

Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	0.25
Leak Detection:	Visual

HIST CORTESE:

edr_fname:	GOODWILL INDUSTRIES
edr_fadd1:	129 GRANT
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390249

T151 **DELTA PLATING, INC** **RCRA-LQG** **1000395328**
ESE **818 S. STANISLAUS ST** **ENVIROSTOR** **CAD068845254**
1/4-1/2 **STOCKTON, CA 95206** **SWEEPS UST**
0.412 mi. **HIST UST**
2178 ft. **Site 2 of 2 in cluster T** **CA FID UST**
EMI
Relative: **HAZNET**
Higher **CERS**
Actual: **HWTS**
17 ft.

RCRA-LQG:

Date Form Received by Agency:		2006-02-25 00:00:00.0
Handler Name:	DELTA PLATING, INC	
Handler Address:		818 S. STANISLAUS ST
Handler City,State,Zip:		STOCKTON, CA 95206
EPA ID:		CAD068845254
Contact Name:		DOUGLAS BAKER
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		209-948-2768
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2005
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		6112 SLATON CT.
Mailing City,State,Zip:		STOCKTON, CA 95206
Owner Name:		GEORGE ABD SANDRA BAKER
Owner Type:		Private
Operator Name:		DOUGLAS BAKER
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No

DELTA PLATING, INC (Continued) **1000395328**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2006-11-15 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

DELTA PLATING, INC (Continued) **1000395328**

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: G. DOUGLAS BAKER
Legal Status: Private
Date Became Current: 1984-10-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NOT REQUIRED
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, ME 99999
Owner/Operator Telephone: 415-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED

DELTA PLATING, INC (Continued) **1000395328**

Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE ABD SANDRA BAKER
Legal Status:	Private
Date Became Current:	1979-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	6112 SLATON CT
Owner/Operator City,State,Zip:	STOCKTON, CA 95286
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	DOUGLAS BAKER
Legal Status:	Private
Date Became Current:	1984-10-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE AND SANDRA BAKER
Legal Status:	Private
Date Became Current:	1979-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	G DOUGLAS BAKER
Legal Status:	Private
Date Became Current:	1984-10-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	GEORGE AND SANDRA BAKER
Legal Status:	Private

DELTA PLATING, INC (Continued) **1000395328**

Date Became Current:	1979-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	818 S STANISLAUS ST
Owner/Operator City,State,Zip:	STOCKTON, CA 95206
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: DELTA PLATING	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1981-02-11 00:00:00.0
Handler Name: DELTA PLATING	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1991-09-03 00:00:00.0
Handler Name: DELTA PLATING,INC.	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1992-01-20 00:00:00.0
Handler Name: DELTA PLATING, INC.	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DELTA PLATING, INC (Continued) **1000395328**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1994-03-14 00:00:00.0
Handler Name: DELTA PLATING, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1999-03-04 00:00:00.0
Handler Name: DELTA PLATING INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2000-10-12 00:00:00.0
Handler Name: DELTA PLATING, INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2002-02-24 00:00:00.0
Handler Name: DELTA PLATING INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

DELTA PLATING, INC (Continued) **1000395328**

Receive Date: 2004-02-29 00:00:00.0
Handler Name: DELTA PLATING, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2006-02-25 00:00:00.0
Handler Name: DELTA PLATING, INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 332813
NAICS Description: ELECTROPLATING, PLATING, POLISHING, ANODIZING, AND COLORING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported

DELTA PLATING, INC (Continued) **1000395328**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported

DELTA PLATING, INC (Continued) **1000395328**

Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 2004-04-20 00:00:00.0
Actual Return to Compliance Date: 2004-09-14 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported

DELTA PLATING, INC (Continued) **1000395328**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 2004-04-20 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier: Not reported

DELTA PLATING, INC (Continued) **1000395328**

Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1984-02-17 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2004-09-14 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NOT A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2004-04-20 00:00:00.0
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	2004-09-14 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1986-10-08 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R9
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Request Agency: Not reported
Former Citation: Not reported

ENVIROSTOR:
Name: DELTA PLATING, INC.
Address: 818 SOUTH STANISLAUS STREET
City,State,Zip: STOCKTON, CA 95206
Facility ID: 71003777
Status: Inactive - Action Required
Status Date: 11/04/2020
Site Code: 550006
Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: 0.5
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Gregory Ruiz
Supervisor: Fernando A. Amador
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.94576
Longitude: -121.2793
APN: 147-294-12
Past Use: METAL PLATING - OTHER
Potential COC: Chromium VI Copper and compounds Cyanide (free Nickel
Confirmed COC: Chromium VI Copper and compounds Cyanide (free Nickel
Potential Description: SOIL
Alias Name: 147-294-12
Alias Type: APN
Alias Name: CAD068845254
Alias Type: EPA Identification Number
Alias Name: 110021363576
Alias Type: EPA (FRS #)
Alias Name: 102371
Alias Type: Project Code (Site Code)
Alias Name: 550006
Alias Type: Project Code (Site Code)
Alias Name: 71003777
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase I Verification
Completed Date: 06/23/2004
Comments: Inspection report sent on 6/23/2004

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement

DELTA PLATING, INC (Continued) **1000395328**

Completed Date: 03/17/2005
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase I Verification
Completed Date: 05/20/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/17/2015
Comments: DTSC notification letter for Implementation of the removal action workplan

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/03/2015
Comments: Second Request for Status Update of Remedial Action Letter

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 03/30/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 10/13/2013
Comments: DTSC request for status update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/22/2019
Comments: This is the signed Start Work Order for this orphan tiered permitting site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 02/18/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Access Agreement
Completed Date: 03/05/2020
Comments: Access granted by property owner for sampling

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 10/23/2020

DELTA PLATING, INC (Continued) **1000395328**

Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	06/24/2019
Comments:	Executed contract for work to take place at an orphan tiered permit site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	10/28/2020
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	12/18/2007
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Workplan
Completed Date:	01/05/2009
Comments:	Removal Action Workplan Approved.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Workplan
Completed Date:	12/09/2019
Comments:	Workplan is approved.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	04/16/2020
Comments:	DTSC mobilized to the Site to oversee the contractor outline the boundaries of the former plating room on 4/2/2020. Contractor remobilized to the Site on 4/16/2020 to advance borings and collect soil and soil gas samples.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	08/06/2020
Comments:	Previously identified contaminated soil appears to have been removed from the Site. The Site does not appear to have contaminated soil gas. Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Schedule Due Date: Not reported
Schedule Revised Date: Not reported

SWEEPS UST:
Name: DELTA PLATING INC
Address: 818 S STANISLAUS
City: STOCKTON
Status: Not reported
Comp Number: 1255
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001255-000001
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 2

Name: DELTA PLATING INC
Address: 818 S STANISLAUS
City: STOCKTON
Status: Not reported
Comp Number: 1255
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001255-000002
Tank Status: Not reported
Capacity: 1
Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: Not reported
Number Of Tanks: Not reported

HIST UST:
Name: DELTA PLATING
Address: 818 S STANISLAUS
City,State,Zip: STOCKTON, CA 95206
File Number: 0002FC8F
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002FC8F.pdf
Region: STATE
Facility ID: 00000010908
Facility Type: Other
Other Type: ELECTROPLATING
Contact Name: Not reported
Telephone: 2099482768

DELTA PLATING, INC (Continued) **1000395328**

Owner Name:	GEORGE BAKER D.B.A. DELTA PLAT
Owner Address:	818 S. STANISLAUS
Owner City,St,Zip:	STOCKTON, CA 95206
Total Tanks:	0001
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	39001862
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	Not reported
Mail To:	Not reported
Mailing Address:	818 S STANISLAUS
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95206
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

EMI:

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Year:	2000
County Code:	39
Air Basin:	SJV
Facility ID:	3000
Air District Name:	SJU
SIC Code:	3471
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

DELTA PLATING, INC (Continued) **1000395328**

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Year:	2001
County Code:	39
Air Basin:	SJV
Facility ID:	3000
Air District Name:	SJU
SIC Code:	3471
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Year:	2002
County Code:	39
Air Basin:	SJV
Facility ID:	3000
Air District Name:	SJU
SIC Code:	3471
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95206
Year:	2003
County Code:	39
Air Basin:	SJV
Facility ID:	3000
Air District Name:	SJU
SIC Code:	3471
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

DELTA PLATING, INC (Continued) **1000395328**

Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: DELTA PLATING INC
Address: 818 S STANISLAUS ST
City,State,Zip: STOCKTON, CA 95206
Year: 2004
County Code: 39
Air Basin: SJV
Facility ID: 3000
Air District Name: SJU
SIC Code: 3471
Air District Name: SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0.1495
Reactive Organic Gases Tons/Yr: 0.144716
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0.00000108
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0.00000108

Name: DELTA PLATING INC
Address: 818 S STANISLAUS ST
City,State,Zip: STOCKTON, CA 95206
Year: 2005
County Code: 39
Air Basin: SJV
Facility ID: 3000
Air District Name: SJU
SIC Code: 3471
Air District Name: SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: .0772210743801652892
Reactive Organic Gases Tons/Yr: .07475
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: DELTA PLATING INC
Address: 818 S STANISLAUS ST
City,State,Zip: STOCKTON, CA 95206
Year: 2006
County Code: 39
Air Basin: SJV
Facility ID: 3000
Air District Name: SJU
SIC Code: 3471
Air District Name: SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: .0772210743801652892
Reactive Organic Gases Tons/Yr: .07475

DELTA PLATING, INC (Continued) **1000395328**

Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

HAZNET:

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952061518
Contact:	DOUG BAKER
Telephone:	2099315826
Mailing Name:	Not reported
Mailing Address:	818 S STANISLAUS ST
Year:	2006
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	D80 - Disposal, Land Fill
Tons:	0.4
Year:	2006
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	122 - Alkaline solution without metals pH >= 12.5
Disposal Method:	T01 - Treatment, Tank
Tons:	0.1251
Year:	2006
Gepaid:	CAD068845254
TSD EPA ID:	CAT000613968
CA Waste Code:	134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method:	H01 - Transfer Station
Tons:	0.105
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	791 - Liquids with pH <= 2
Disposal Method:	T01 - Treatment, Tank
Tons:	0.72975
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	171 - Metal sludge (Alkaline solution (pH >= 12.5) with metals)
Disposal Method:	D80 - Disposal, Land Fill
Tons:	11.55
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	792 - Liquids with pH <= 2 with metals
Disposal Method:	T01 - Treatment, Tank

DELTA PLATING, INC (Continued) **1000395328**

Tons:	3.3692
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	D80 - Disposal, Land Fill
Tons:	11.45
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	NVD980895338
CA Waste Code:	122 - Alkaline solution without metals pH >= 12.5
Disposal Method:	T01 - Treatment, Tank
Tons:	3.44025
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	CAT000613968
CA Waste Code:	134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method:	H01 - Transfer Station
Tons:	0.5964
Year:	2005
Gepaid:	CAD068845254
TSD EPA ID:	WAD991281767
CA Waste Code:	791 - Liquids with pH <= 2
Disposal Method:	T01 - Treatment, Tank
Tons:	1.14675

Click this hyperlink while viewing on your computer to access
57 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	1998
Gen EPA ID:	CAD068845254
Shipment Date:	19981209
Creation Date:	1/28/1999 0:00:00
Receipt Date:	19981218
Manifest ID:	98026477
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	3
Waste Quantity:	6000
Quantity Unit:	P

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980904
Creation Date:	12/7/1998 0:00:00
Receipt Date:	19980914
Manifest ID:	98022230
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.25
Waste Quantity:	4500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980605
Creation Date:	9/3/1998 0:00:00
Receipt Date:	19980610
Manifest ID:	98022013
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.75
Waste Quantity:	5500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19980310
Creation Date:	5/26/1998 0:00:00
Receipt Date:	19980319

DELTA PLATING, INC (Continued) **1000395328**

Manifest ID:	97326667
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.5
Waste Quantity:	5000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAD068845254
Shipment Date:	19951205
Creation Date:	7/29/1996 0:00:00
Receipt Date:	19951214
Manifest ID:	95880511
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	1.75
Waste Quantity:	3500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950619
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950706
Manifest ID:	95179056
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	CAD980584510
Trans 2 Name:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: AZD980735500
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: R01 - Recycler
Quantity Tons: 1.9
Waste Quantity: 3800
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19950320
Creation Date: 3/29/1996 0:00:00
Receipt Date: 19950328
Manifest ID: 95184850
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: AZD980735500
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: R01 - Recycler
Quantity Tons: 3
Waste Quantity: 6000
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 1999
Gen EPA ID: CAD068845254

Shipment Date: 19991207
Creation Date: 2/15/2000 0:00:00
Receipt Date: 19991228
Manifest ID: 99427469
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: NVD980895338
Trans Name: Not reported
TSDF Alt EPA ID: NVD980895338
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121

DELTA PLATING, INC (Continued) **1000395328**

RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	3.3712
Waste Quantity:	4
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19990909
Creation Date:	10/27/1999 0:00:00
Receipt Date:	19990914
Manifest ID:	99427275
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	5
Waste Quantity:	10000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19990611
Creation Date:	8/16/1999 0:00:00
Receipt Date:	19990625
Manifest ID:	99292961
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	4.214
Waste Quantity:	5
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 5:	Not reported
Shipment Date:	19990312
Creation Date:	5/4/1999 0:00:00
Receipt Date:	19990317
Manifest ID:	99293228
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	5
Waste Quantity:	10000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1997
Gen EPA ID:	CAD068845254
Shipment Date:	19971208
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19971216
Manifest ID:	97329871
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970903
Creation Date:	7/23/1998 0:00:00
Receipt Date:	19970909

DELTA PLATING, INC (Continued) **1000395328**

Manifest ID:	96615304
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	1.8
Waste Quantity:	3600
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970603
Creation Date:	12/4/1997 0:00:00
Receipt Date:	19970619
Manifest ID:	95878029
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	1.75
Waste Quantity:	3500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19970305
Creation Date:	6/26/1997 0:00:00
Receipt Date:	19970314
Manifest ID:	96777002
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2005
Gen EPA ID:	CAD068845254
Shipment Date:	20051206
Creation Date:	3/22/2006 18:30:36
Receipt Date:	20051216
Manifest ID:	24783767
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.75
Waste Quantity:	1500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20051206
Creation Date:	3/22/2006 18:30:36
Receipt Date:	20051216
Manifest ID:	24783767
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	791 - Liquids with pH < 2 792 Liquids with pH < 2 with metals
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	0.72975
Waste Quantity:	175

DELTA PLATING, INC (Continued) **1000395328**

Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20051129
Creation Date:	1/2/2007 18:30:32
Receipt Date:	20051207
Manifest ID:	24783684
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20051129
Creation Date:	1/2/2007 18:30:32
Receipt Date:	20051207
Manifest ID:	24783684
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	3.5
Waste Quantity:	7000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20051129
Creation Date:	1/2/2007 18:30:32

DELTA PLATING, INC (Continued) **1000395328**

Receipt Date:	20051207
Manifest ID:	24783684
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	4
Waste Quantity:	8000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20051122
Creation Date:	3/14/2007 18:30:14
Receipt Date:	20051129
Manifest ID:	24786543
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	UTR000007708
Trans 2 Name:	SLT EXPRESS
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	7.2
Waste Quantity:	14400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20051122
Creation Date:	3/14/2007 18:30:14
Receipt Date:	20051129
Manifest ID:	24786543
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	UTR000007708
Trans 2 Name:	SLT EXPRESS
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338

DELTA PLATING, INC (Continued) **1000395328**

TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20050801
Creation Date:	3/10/2006 10:49:15
Receipt Date:	20050812
Manifest ID:	24576451
Trans EPA ID:	CAR000052803
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	TXR000025072
Trans 2 Name:	ROCKETLINE CARRIER SERVICES
TSDF EPA ID:	WAD991281767
Trans Name:	BURLINGTON ENVIRONMENTAL INC KENT
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.5
Waste Quantity:	1000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20050801
Creation Date:	3/10/2006 10:49:15
Receipt Date:	20050812
Manifest ID:	24576451
Trans EPA ID:	CAR000052803
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	TXR000025072
Trans 2 Name:	ROCKETLINE CARRIER SERVICES
TSDF EPA ID:	WAD991281767
Trans Name:	BURLINGTON ENVIRONMENTAL INC KENT
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	1
Waste Quantity:	2000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20050801
Creation Date:	3/10/2006 10:49:15
Receipt Date:	20050812
Manifest ID:	24576451
Trans EPA ID:	CAR000052803
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	TXR000025072
Trans 2 Name:	ROCKETLINE CARRIER SERVICES
TSDF EPA ID:	WAD991281767
Trans Name:	BURLINGTON ENVIRONMENTAL INC KENT
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	791 - Liquids with pH < 2 792 Liquids with pH < 2 with metals
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	1.14675
Waste Quantity:	275
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2006
Gen EPA ID:	CAD068845254
Shipment Date:	20060421
Creation Date:	8/1/2006 18:30:24
Receipt Date:	20060501
Manifest ID:	25134854
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	UTR000007708
Trans 2 Name:	SLT EXPRESS
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	D007
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	0.4
Waste Quantity:	800
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20060421

DELTA PLATING, INC (Continued) **1000395328**

Creation Date:	8/1/2006 18:30:24
Receipt Date:	20060501
Manifest ID:	25134854
Trans EPA ID:	CAR000164012
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	UTR000007708
Trans 2 Name:	SLT EXPRESS
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	122 - Alkaline solution without metals (pH > 12.5
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	0.1251
Waste Quantity:	30
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20060203
Creation Date:	5/27/2006 18:31:40
Receipt Date:	20060203
Manifest ID:	24351750
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.105
Waste Quantity:	25
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2000
Gen EPA ID:	CAD068845254

Shipment Date:	20001212
Creation Date:	2/1/2001 0:00:00
Receipt Date:	20001220
Manifest ID:	20200491
Trans EPA ID:	NVD980895338
Trans Name:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20001013
Creation Date:	12/13/2000 0:00:00
Receipt Date:	20001013
Manifest ID:	20520417
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	D001
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1084
Waste Quantity:	26
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20000915
Creation Date:	10/30/2000 0:00:00
Receipt Date:	20000920
Manifest ID:	20586531
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler

DELTA PLATING, INC (Continued) **1000395328**

Quantity Tons:	4.214
Waste Quantity:	5
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20000607
Creation Date:	9/11/2000 0:00:00
Receipt Date:	20000721
Manifest ID:	20204626
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	4
Waste Quantity:	8000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20000309
Creation Date:	5/3/2000 0:00:00
Receipt Date:	20000320
Manifest ID:	99085871
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	5
Waste Quantity:	10000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Info:

Year:	1993
Gen EPA ID:	CAD068845254
Shipment Date:	19931111
Creation Date:	9/14/1995 0:00:00
Receipt Date:	19931111
Manifest ID:	93195926
Trans EPA ID:	CA0000023648
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD000628149
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD000628149
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	H01 - Transfer Station
Quantity Tons:	2.2
Waste Quantity:	4400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19930810
Creation Date:	9/12/1995 0:00:00
Receipt Date:	19930811
Manifest ID:	93195632
Trans EPA ID:	CAD000628149
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD000628149
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD000628149
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	H01 - Transfer Station
Quantity Tons:	3.2
Waste Quantity:	6400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19930510
Creation Date:	9/9/1995 0:00:00
Receipt Date:	19930511
Manifest ID:	92732915
Trans EPA ID:	CAD000628149

DELTA PLATING, INC (Continued) **1000395328**

Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD000628149
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	H01 - Transfer Station
Quantity Tons:	3
Waste Quantity:	6000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19930212
Creation Date:	9/15/1995 0:00:00
Receipt Date:	19930212
Manifest ID:	92686173
Trans EPA ID:	CAD000628149
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD000628149
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD000628149
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	H01 - Transfer Station
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2003
Gen EPA ID:	CAD068845254

Shipment Date:	20031230
Creation Date:	8/12/2004 8:09:46
Receipt Date:	20031230
Manifest ID:	22590326
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	SAFETY-KLEEN SYSTEMS INC

DELTA PLATING, INC (Continued) **1000395328**

TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.168
Waste Quantity:	40
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20031209
Creation Date:	7/30/2004 18:31:14
Receipt Date:	20031212
Manifest ID:	21629537
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	4.5
Waste Quantity:	9000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20031008
Creation Date:	8/3/2004 15:03:33
Receipt Date:	20031008
Manifest ID:	22525126
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.168
Waste Quantity:	40
Quantity Unit:	G
Additional Code 1:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030911
Creation Date:	8/2/2004 9:36:58
Receipt Date:	20030912
Manifest ID:	21629293
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	8.1
Waste Quantity:	16200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030717
Creation Date:	7/23/2004 13:22:40
Receipt Date:	20030717
Manifest ID:	22884186
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.189
Waste Quantity:	45
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030611
Creation Date:	7/22/2004 7:51:02
Receipt Date:	20030625
Manifest ID:	22697949

DELTA PLATING, INC (Continued) **1000395328**

Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	NVD980895338
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	3.75
Waste Quantity:	7500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20030415
Creation Date:	7/12/2003 18:31:23
Receipt Date:	20030415
Manifest ID:	22443565
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1512
Waste Quantity:	36
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20030312
Creation Date:	1/5/2007 18:30:36
Receipt Date:	20030318
Manifest ID:	21626104
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121

DELTA PLATING, INC (Continued) **1000395328**

RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	1.8
Waste Quantity:	3600
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030128
Creation Date:	5/18/2003 14:30:16
Receipt Date:	20030128
Manifest ID:	22104886
Trans EPA ID:	TXR000050930
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2002
Gen EPA ID:	CAD068845254
Shipment Date:	20021217
Creation Date:	3/27/2003 18:31:27
Receipt Date:	20021223
Manifest ID:	22095593
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	NVD980895338
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	3
Waste Quantity:	6000
Quantity Unit:	P

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021104
Creation Date:	2/21/2003 10:41:38
Receipt Date:	20021111
Manifest ID:	21908318
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1722
Waste Quantity:	41
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020911
Creation Date:	1/27/2003 18:33:26
Receipt Date:	20020918
Manifest ID:	22232065
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	NVD980895338
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020814
Creation Date:	1/27/2003 18:31:12
Receipt Date:	20020826

DELTA PLATING, INC (Continued) **1000395328**

Manifest ID:	21747058
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1512
Waste Quantity:	36
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20020614
Creation Date:	1/14/2003 18:31:21
Receipt Date:	20020621
Manifest ID:	21629791
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20020522
Creation Date:	7/29/2002 18:43:18
Receipt Date:	20020529
Manifest ID:	21595440
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.252
Waste Quantity:	60
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020311
Creation Date:	7/29/2002 18:32:31
Receipt Date:	20020329
Manifest ID:	21626458
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	NVD980895338
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020226
Creation Date:	7/25/2002 18:31:53
Receipt Date:	20020304
Manifest ID:	21495211
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1848
Waste Quantity:	44
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 1996
Gen EPA ID: CAD068845254

Shipment Date: 19961212
Creation Date: 6/26/1997 0:00:00
Receipt Date: 19961219
Manifest ID: 96400691
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: AZD980735500
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: - Not reported
Quantity Tons: 1.75
Waste Quantity: 3500
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19960911
Creation Date: 5/21/1997 0:00:00
Receipt Date: 19960925
Manifest ID: 96579580
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: R01 - Recycler
Quantity Tons: 2.2
Waste Quantity: 4400
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19960607
Creation Date: 5/30/1997 0:00:00

DELTA PLATING, INC (Continued) **1000395328**

Receipt Date:	19960624
Manifest ID:	95883591
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	3.5
Waste Quantity:	7000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19960313
Creation Date:	10/16/1996 0:00:00
Receipt Date:	19960315
Manifest ID:	95913521
Trans EPA ID:	CAD980584510
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2
Waste Quantity:	4000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2001
Gen EPA ID:	CAD068845254

Shipment Date:	20011211
Creation Date:	2/13/2002 0:00:00
Receipt Date:	20011228
Manifest ID:	21348376
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20011203
Creation Date:	1/29/2002 0:00:00
Receipt Date:	20011205
Manifest ID:	21322433
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1764
Waste Quantity:	42
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20010911
Creation Date:	11/1/2001 0:00:00
Receipt Date:	20010913
Manifest ID:	21398369
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1848

DELTA PLATING, INC (Continued) **1000395328**

Waste Quantity:	44
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010910
Creation Date:	11/1/2001 0:00:00
Receipt Date:	20010913
Manifest ID:	21038994
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	5
Waste Quantity:	10000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010620
Creation Date:	8/29/2001 0:00:00
Receipt Date:	20010625
Manifest ID:	21133079
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2646
Waste Quantity:	63
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010611

DELTA PLATING, INC (Continued) **1000395328**

Creation Date:	8/14/2001 0:00:00
Receipt Date:	20010619
Manifest ID:	21038814
Trans EPA ID:	NVD980895338
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	4
Waste Quantity:	8000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20010330
Creation Date:	6/12/2001 0:00:00
Receipt Date:	20010405
Manifest ID:	20621849
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000075150
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.1512
Waste Quantity:	36
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20010330
Creation Date:	6/12/2001 0:00:00
Receipt Date:	20010405
Manifest ID:	20621849
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000075150
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

TSDF Alt EPA ID:	CA0000084517
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0462
Waste Quantity:	11
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010314
Creation Date:	5/16/2001 0:00:00
Receipt Date:	20010329
Manifest ID:	20801272
Trans EPA ID:	CAR000052803
Trans Name:	Not reported
Trans 2 EPA ID:	CAD063547996
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	Not reported
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	6.25
Waste Quantity:	12500
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20010102
Creation Date:	3/22/2001 0:00:00
Receipt Date:	20010104
Manifest ID:	20385497
Trans EPA ID:	SCR000075150
Trans Name:	Not reported
Trans 2 EPA ID:	SCR000074591
Trans 2 Name:	Not reported
TSDF EPA ID:	CA0000084517
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.2016
Waste Quantity:	48
Quantity Unit:	G
Additional Code 1:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 1994
Gen EPA ID: CAD068845254

Shipment Date: 19941208
Creation Date: 3/28/1996 0:00:00
Receipt Date: 19941222
Manifest ID: 92847288
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: AZD980735500
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: R01 - Recycler
Quantity Tons: 3.3712
Waste Quantity: 4
Quantity Unit: Y
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19940923
Creation Date: 3/28/1996 0:00:00
Receipt Date: 19941003
Manifest ID: 93596446
Trans EPA ID: CAD063547996
Trans Name: Not reported
Trans 2 EPA ID: CAD980584510
Trans 2 Name: Not reported
TSDF EPA ID: AZD980735500
Trans Name: Not reported
TSDF Alt EPA ID: AZD980735500
TSDF Alt Name: Not reported
Waste Code Description: 171 - Metal sludge (see 121
RCRA Code: F006
Meth Code: R01 - Recycler
Quantity Tons: 2
Waste Quantity: 4000
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

DELTA PLATING, INC (Continued) **1000395328**

Shipment Date:	19940622
Creation Date:	10/10/1995 0:00:00
Receipt Date:	19940630
Manifest ID:	93714455
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	AZD980735500
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	2.5284
Waste Quantity:	3
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19940330
Creation Date:	3/25/1996 0:00:00
Receipt Date:	Not reported
Manifest ID:	93189949
Trans EPA ID:	CAD063547996
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZD980735500
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	- Not reported
Quantity Tons:	2.4
Waste Quantity:	4800
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2004
Gen EPA ID:	CAD068845254

Shipment Date:	20041222
Creation Date:	3/16/2005 18:31:03
Receipt Date:	20041230
Manifest ID:	24147299
Trans EPA ID:	NVD980895338

DELTA PLATING, INC (Continued) **1000395328**

Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	R01 - Recycler
Quantity Tons:	3.6
Waste Quantity:	7200
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20041208
Creation Date:	2/17/2005 18:32:22
Receipt Date:	20041215
Manifest ID:	22987571
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	792 - Not reported
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	2.2935
Waste Quantity:	550
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20041130
Creation Date:	2/17/2005 18:32:22
Receipt Date:	20041130
Manifest ID:	23723176
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.189
Waste Quantity:	45
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20041116
Creation Date:	1/20/2005 18:31:32
Receipt Date:	20041117
Manifest ID:	22987531
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	792 - Not reported
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	2.2935
Waste Quantity:	550
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20041112
Creation Date:	1/14/2005 10:18:48
Receipt Date:	20041116
Manifest ID:	22987521
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	791 - Liquids with pH < 2 792 Liquids with pH < 2 with metals
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	2.2935
Waste Quantity:	550
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

DELTA PLATING, INC (Continued) **1000395328**

Shipment Date:	20041101
Creation Date:	1/20/2005 18:31:32
Receipt Date:	20041112
Manifest ID:	22987513
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	791 - Liquids with pH < 2 792 Liquids with pH < 2 with metals
RCRA Code:	D002
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	2.2935
Waste Quantity:	550
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20040910
Creation Date:	1/6/2005 18:32:03
Receipt Date:	20040917
Manifest ID:	22987421
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	5.0568
Waste Quantity:	6
Quantity Unit:	Y
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20040908
Creation Date:	3/16/2007 18:31:12
Receipt Date:	20040908
Manifest ID:	23711034
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968

DELTA PLATING, INC (Continued) **1000395328**

Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.189
Waste Quantity:	45
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20040617
Creation Date:	11/1/2004 9:00:46
Receipt Date:	20040617
Manifest ID:	23510420
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613968
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613968
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.21
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20040611
Creation Date:	11/1/2004 9:00:46
Receipt Date:	20040618
Manifest ID:	22987177
Trans EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMI
TSDF Alt EPA ID:	NVD980895338
TSDF Alt Name:	Not reported
Waste Code Description:	171 - Metal sludge (see 121
RCRA Code:	F006
Meth Code:	- Not reported
Quantity Tons:	3.25
Waste Quantity:	6500
Quantity Unit:	P

DELTA PLATING, INC (Continued) **1000395328**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	DELTA PLATING INC
Address:	818 SOUTH STANISLAUS STREET
City,State,Zip:	STOCKTON, CA 95206-1518
Site ID:	464252
CERS ID:	110000782859
CERS Description:	US EPA Air Emission Inventory System (EIS)

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	DOUGLAS BAKER
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

HWTS:

Name:	DELTA PLATING INC
Address:	818 S STANISLAUS ST
Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952061518
EPA ID:	CAD068845254
Inactive Date:	06/30/2007
Create Date:	07/23/1982
Last Act Date:	10/25/2007
Mailing Name:	Not reported
Mailing Address:	818 S STANISLAUS ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	STOCKTON, CA 952060000
Owner Name:	SANDRA BAKER
Owner Address:	818 S STANISLAUS ST
Owner Address 2:	Not reported
Owner City,State,Zip:	STOCKTON, CA 952060000
Contact Name:	DOUG BAKER
Contact Address:	818 S STANISLAUS ST
Contact Address 2:	Not reported
City,State,Zip:	STOCKTON, CA 952061518

NAICS:

EPA ID:	CAD068845254
Create Date:	2002-03-14 16:36:26.000
NAICS Code:	332813
NAICS Description:	Electroplating, Plating, Polishing, Anodizing, and Coloring
Issued EPA ID Date:	1982-07-23 00:00:00
Inactive Date:	2007-06-30 16:24:40
Facility Name:	DELTA PLATING INC
Facility Address:	818 S STANISLAUS ST

DELTA PLATING, INC (Continued) **1000395328**

Facility Address 2:	Not reported
Facility City:	STOCKTON
Facility County:	Not reported
Facility State:	CA
Facility Zip:	952061518
EPA ID:	CAD068845254
Create Date:	2002-03-14 16:36:26.000
NAICS Code:	332813
NAICS Description:	Electroplating, Plating, Polishing, Anodizing, and Coloring
Issued EPA ID Date:	1982-07-23 00:00:00
Inactive Date:	2007-06-30 16:24:40
Facility Name:	DELTA PLATING INC
Facility Address:	818 S STANISLAUS ST
Facility Address 2:	Not reported
Facility City:	STOCKTON
Facility County:	Not reported
Facility State:	CA
Facility Zip:	952061518

---

152 **SIERRA LUMBER CASE #2** **LUST** **S106716410**
WSW **375 HAZELTON AVENUE** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95203** **CERS**
0.418 mi.
2208 ft.

Relative:
Lower

Actual:
10 ft.

LUST REG 5:

Name:	SIERRA LUMBER CASE #2
Address:	375 HAZELTON AVENUE
City:	STOCKTON
Region:	5
Status:	Leak being confirmed
Case Number:	391168
Case Type:	Drinking Water Aquifer affected
Substance:	GASOLINE
Staff Initials:	JLB
Lead Agency:	Local
Program:	LUST
MTBE Code:	N/A

CORTESE:

Name:	SIERRA LUMBER CASE #2
Address:	375 HAZELTON AVENUE
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607726897
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported

SIERRA LUMBER CASE #2 (Continued) **S106716410**

Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	SIERRA LUMBER CASE #2
Address:	375 HAZELTON AVENUE
City,State,Zip:	STOCKTON, CA 95203
Site ID:	216839
CERS ID:	T0607726897
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Dr
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644615

Y153 **PARKING GARAGE** **LUST** **S102428436**
NNW **130 HUNTER** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **HIST CORTESE**
0.425 mi. **CERS**
2246 ft. **Site 1 of 2 in cluster Y**

Relative:
Lower

Actual:
15 ft.

LUST:

Name:	PARKING GARAGE
Address:	130 HUNTER ST N
City,State,Zip:	STOCKTON, CA 95205
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700689
Global Id:	T0607700689
Latitude:	37.9545979309084
Longitude:	-121.288798795701
Status:	Open - Site Assessment
Status Date:	02/04/2005
Case Worker:	VJF
RB Case Number:	390862
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	June 1994 - Two soil borings (B1 and B2) were advanced adjacent to the two USTs. November 1994 - There was an unauthorized release and gasoline was discovered during a subsurface investigation. August

PARKING GARAGE (Continued) **S102428436**

1996 - Two USTs were removed. February 2001 - Three soil borings (G1 through G3) were advanced at the site. July 2002 - Four monitoring wells (MW-1 through MW-4) were installed. March 2004 - Three soil borings (G4 through G6) were advanced. November 2004 - Soil borings SB-4 and SB-5 were advanced. December 2004 - Soil borings SB-5A, SB-5B, SB-2 and SB-3 were advanced. February 2005 - Soil borings SB-6 and SB-7 were advanced and monitoring wells MW-1 through MW-4 were destroyed. Additional site investigation is needed.

LUST:
Global Id: T0607700689
Contact Type: Regional Board Caseworker
Contact Name: VERA FISCHER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: vera.fischer@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700689
Action Type: RESPONSE
Date: 06/27/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700689
Action Type: RESPONSE
Date: 04/06/2005
Action: Other Report / Document

Global Id: T0607700689
Action Type: RESPONSE
Date: 11/21/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700689
Action Type: RESPONSE
Date: 04/04/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 04/02/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 01/11/2010
Action: Meeting

Global Id: T0607700689
Action Type: ENFORCEMENT

PARKING GARAGE (Continued) **S102428436**

Date: 01/03/2011
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 10/14/2011
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 12/09/2014
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 12/12/2014
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 01/09/2015
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 08/04/2010
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 06/17/2011
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 06/21/2016
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 05/19/2017
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 05/29/2018
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 05/28/2019
Action: Staff Letter

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 05/29/2018
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

PARKING GARAGE (Continued) **S102428436**

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 10/28/2020
Action: Email Correspondence

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 01/21/2021
Action: 13267 Monitoring Program

Global Id: T0607700689
Action Type: Other
Date: 10/07/1994
Action: Leak Discovery

Global Id: T0607700689
Action Type: Other
Date: 11/10/1994
Action: Leak Reported

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 11/09/2004
Action: Referral to Local Agency

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 04/17/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 07/02/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 08/25/2008
Action: Technical Correspondence / Assistance / Other - #08/25/2008

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 01/25/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700689
Action Type: RESPONSE
Date: 01/09/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700689
Action Type: RESPONSE
Date: 05/07/2004
Action: Other Report / Document

Global Id: T0607700689
Action Type: RESPONSE

PARKING GARAGE (Continued) **S102428436**

Date: 09/29/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700689
Action Type: RESPONSE
Date: 04/16/2001
Action: Preliminary Site Assessment Report

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 12/02/2008
Action: Staff Letter - #12/02/2008

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 07/29/2013
Action: Staff Letter

Global Id: T0607700689
Action Type: RESPONSE
Date: 09/27/2002
Action: Well Installation Report

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 06/02/2009
Action: File review

Global Id: T0607700689
Action Type: ENFORCEMENT
Date: 06/20/2014
Action: File review

LUST:
Global Id: T0607700689
Status: Open - Case Begin Date
Status Date: 10/07/1994

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 10/07/1994

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 02/02/2001

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 07/11/2002

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 03/26/2004

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 11/12/2004

PARKING GARAGE (Continued) **S102428436**

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 12/20/2004

Global Id: T0607700689
Status: Open - Site Assessment
Status Date: 02/04/2005

LUST REG 5:
Name: PARKING GARAGE
Address: 130 HUNTER ST N
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 390862
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 2

CORTESE:
Name: PARKING GARAGE
Address: 130 HUNTER ST N
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700689
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - SITE ASSESSMENT
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: PARKING GARAGE
edr_fadd1: 130 HUNTER
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA

PARKING GARAGE (Continued) **S102428436**

Reg Id: 390862

CERS:
Name: PARKING GARAGE
Address: 130 HUNTER ST N
City,State,Zip: STOCKTON, CA 95205
Site ID: 192393
CERS ID: T0607700689
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

154
East
1/4-1/2
0.439 mi.
2318 ft.

HICKINBOTHAM BROS LTD
635 AURORA
STOCKTON, CA 95201

LUST **S101302601**
Cortese **N/A**
HIST CORTESE
CERS

Relative:
Higher

Actual:
18 ft.

LUST:
Name: HICKINBOTHAM BROS LTD
Address: 635 AURORA ST S
City,State,Zip: STOCKTON, CA 95201
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700229
Global Id: T0607700229
Latitude: 37.947685
Longitude: -121.278124
Status: Completed - Case Closed
Status Date: 06/17/1993
Case Worker: Not reported
RB Case Number: 390312
Local Agency: Not reported
File Location: Not reported
Local Case Number: 506770
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607700229
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

HICKINBOTHAM BROS LTD (Continued) **S101302601**

LUST:
Global Id: T0607700229
Action Type: ENFORCEMENT
Date: 08/01/1990
Action: Other Report

Global Id: T0607700229
Action Type: ENFORCEMENT
Date: 12/19/1988
Action: Unauthorized Release Form

Global Id: T0607700229
Action Type: Other
Date: 12/19/1988
Action: Leak Discovery

Global Id: T0607700229
Action Type: Other
Date: 12/19/1988
Action: Leak Reported

Global Id: T0607700229
Action Type: ENFORCEMENT
Date: 08/01/1990
Action: Unauthorized Release Form

Global Id: T0607700229
Action Type: ENFORCEMENT
Date: 12/19/1988
Action: Other Report

LUST:
Global Id: T0607700229
Status: Open - Case Begin Date
Status Date: 12/19/1988

Global Id: T0607700229
Status: Completed - Case Closed
Status Date: 06/17/1993

LUST REG 5:
Name: HICKINBOTHAM BROS LTD
Address: 635 AURORA ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390312
Case Type: Soil only
Substance: UNLEAD GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

HICKINBOTHAM BROS LTD (Continued) **S101302601**

CORTESE:

Name:	HICKINBOTHAM BROS LTD
Address:	635 AURORA ST S
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700229
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	HICKINBOTHAM BROS LTD
edr_fadd1:	635 AURORA
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390312

CERS:

Name:	HICKINBOTHAM BROS LTD
Address:	635 AURORA ST S
City,State,Zip:	STOCKTON, CA 95201
Site ID:	199627
CERS ID:	T0607700229
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Z155 **WEBER ENTERPRISES** **LUST** **S101308463**
NNW **141 EL DORADO ST N** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **HIST CORTESE**
0.440 mi. **CERS**
2321 ft. **Site 1 of 3 in cluster Z**

Relative:
Lower

Actual:
13 ft.

LUST:

Name:	WEBER ENTERPRISES
Address:	141 EL DORADO ST N
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700423
Global Id:	T0607700423
Latitude:	37.954112
Longitude:	-121.29084
Status:	Completed - Case Closed
Status Date:	07/17/2002
Case Worker:	Not reported
RB Case Number:	390538
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	2436
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700423
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700423
Action Type:	ENFORCEMENT
Date:	06/27/2002
Action:	Closure/No Further Action Letter
Global Id:	T0607700423
Action Type:	Other
Date:	09/01/1990
Action:	Leak Reported

LUST:

Global Id:	T0607700423
Status:	Open - Case Begin Date
Status Date:	09/01/1990
Global Id:	T0607700423
Status:	Open - Site Assessment
Status Date:	09/01/1990
Global Id:	T0607700423
Status:	Open - Remediation

WEBER ENTERPRISES (Continued) **S101308463**

Status Date: 08/22/1996

Global Id: T0607700423
Status: Completed - Case Closed
Status Date: 07/17/2002

LUST REG 5:
Name: WEBER ENTERPRISES
Address: 141 EL DORADO ST N
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390538
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 6

CORTESE:
Name: WEBER ENTERPRISES
Address: 141 EL DORADO ST N
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700423
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: WEBER ENTERPRISES
edr_fadd1: 141 EL DORADO
City,State,Zip: STOCKTON, CA
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390538

WEBER ENTERPRISES (Continued) **S101308463**

CERS:
Name: WEBER ENTERPRISES
Address: 141 EL DORADO ST N
City,State,Zip: STOCKTON, CA 95202
Site ID: 208506
CERS ID: T0607700423
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Y156 **AMERICAN SAVINGS BANK** **CPS-SLIC** **S106230418**
NNW **222 EL DORADO ST N** **CERS** **N/A**
1/4-1/2 **STOCKTON, CA**
0.440 mi.
2325 ft. **Site 2 of 2 in cluster Y**

Relative:
Lower

Actual:
15 ft.

SLIC REG 5:
Name: American Savings Bank
Address: 222 El Dorado St N
City: Stockton
Region: 5
Facility Status: Closed by RB
Unit: Facility is a Spill or site
Pollutant: TPH-d,g benzene
Lead Agency: Not reported
Date Filed: 04/06/00
Report Date: 01/08/99
Date Added: Not reported
Date Closed: Not reported

CPS-SLIC:
Name: AMERICAN SAVINGS BANK
Address: 222 EL DORADO
City,State,Zip: STOCKTON, CA
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 04/06/2000
Global Id: SL185632931
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Lead Agency Case Number: Not reported
Latitude: 37.954695
Longitude: -121.289322
Case Type: Cleanup Program Site
Case Worker: ZZZ
Local Agency: Not reported
RB Case Number: SL185632931
File Location: Not reported

AMERICAN SAVINGS BANK (Continued) **S106230418**

Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: From 1917 to 1956, the Site was used as an automotive repair facility which also dispensed gasoline. State Savings and Load constructed a two-story office building at the Site in 1961 and operated it as a bank until 1982. American Savings and Loan used the building from 1984 to 1988. The building is currently vacant. There are no records of a tank at the Site. The tank was likely excavated during construction of the building in 1961.

Click here to access the California GeoTracker records for this facility:

CERS:
Name: AMERICAN SAVINGS BANK
Address: 222 EL DORADO
City,State,Zip: STOCKTON, CA
Site ID: 211154
CERS ID: SL185632931
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: zzz - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

AA157 **CAPITOL VENTURE ENTERPRISES** **LUST** **S104403503**
ENE **400 AURORA ST S** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95201** **CERS**
0.448 mi.
2363 ft. **Site 1 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

LUST:
Name: CAPITOL VENTURE ENTERPRISES
Address: 400 AURORA ST S
City,State,Zip: STOCKTON, CA 95201
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700582
Global Id: T0607700582
Latitude: 37.950228
Longitude: -121.27749
Status: Completed - Case Closed
Status Date: 06/03/1996
Case Worker: Not reported
RB Case Number: 390747
Local Agency: Not reported
File Location: Not reported
Local Case Number: 0001367
Potential Media Affect: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

CAPITOL VENTURE ENTERPRISES (Continued) **S104403503**

LUST:
Global Id: T0607700582
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700582
Action Type: ENFORCEMENT
Date: 08/10/1992
Action: Other Report

Global Id: T0607700582
Action Type: ENFORCEMENT
Date: 07/10/1992
Action: Unauthorized Release Form

Global Id: T0607700582
Action Type: Other
Date: 07/10/1992
Action: Leak Discovery

Global Id: T0607700582
Action Type: Other
Date: 08/10/1992
Action: Leak Reported

LUST:
Global Id: T0607700582
Status: Open - Case Begin Date
Status Date: 07/10/1992

Global Id: T0607700582
Status: Completed - Case Closed
Status Date: 06/03/1996

LUST REG 5:
Name: CAPITOL VENTURE ENTERPRISES
Address: 400 AURORA ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390747
Case Type: Soil only
Substance: TRANSMSSN FLUID
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CAPITOL VENTURE ENTERPRISES (Continued) **S104403503**

CORTESE:

Name:	CAPITOL VENTURE ENTERPRISES
Address:	400 AURORA ST S
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700582
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	CAPITOL VENTURE ENTERPRISES
Address:	400 AURORA ST S
City,State,Zip:	STOCKTON, CA 95201
Site ID:	189636
CERS ID:	T0607700582
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AA158 **BEAULIEU CHEM CO** **SEMS-ARCHIVE** **1002850381**
ENE **400 S AURORA** **CAD009449935**
1/4-1/2 **STOCKTON, CA 95202**
0.455 mi.
2405 ft. **Site 2 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

SEMS Archive:

Site ID:	0903215
EPA ID:	CAD009449935
Name:	BEAULIEU CHEM CO
Address:	400 S AURORA

BEAULIEU CHEM CO (Continued) **1002850381**

Address 2: Not reported
City,State,Zip: STOCKTON, CA 95202
Cong District: 14
FIPS Code: 06077
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 09
Site ID: 0903215
EPA ID: CAD009449935
Site Name: BEAULIEU CHEM CO
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1988-08-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0903215
EPA ID: CAD009449935
Site Name: BEAULIEU CHEM CO
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1988-08-01 04:00:00
Qual: N
Current Action Lead: St Perf

Region: 09
Site ID: 0903215
EPA ID: CAD009449935
Site Name: BEAULIEU CHEM CO
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1987-12-01 05:00:00
Finish Date: 1987-12-01 05:00:00
Qual: Not reported
Current Action Lead: St Perf

AA159 **BEAULIEU INDUSTRIES** **ENVIROSTOR** **S101592888**
ENE **400 S AURORA** **VCP** **N/A**
1/4-1/2 **STOCKTON, CA 95204** **SWEEPS UST**
0.455 mi. **CA FID UST**
2405 ft. **Site 3 of 4 in cluster AA**

Relative: Higher

Actual: 18 ft.

ENVIROSTOR:

Name:	BEAULIEU CHEMICAL COMPANY
Address:	400 S AURORA ST
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39280007
Status:	No Further Action
Status Date:	06/28/1995
Site Code:	100438
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	2.48
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup San Joaquin
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.95022
Longitude:	-121.2774
APN:	15126037
Past Use:	MANUFACTURING - CHEMICALS, MANUFACTURING - CHEMICALS
Potential COC:	* DETERGENT & SOAP * ACID SOLUTION WITHOUT METALS * UNSPECIFIED ACID SOLUTION * UNSPECIFIED ALKALINE SOLUTIONS Nitrate Phosphoric acid Sulfuric Acid
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL, SOIL
Alias Name:	15126037
Alias Type:	APN
Alias Name:	110011463148
Alias Type:	EPA (FRS #)
Alias Name:	100438
Alias Type:	Project Code (Site Code)
Alias Name:	39280007
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	02/23/1995
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	06/28/1995
Comments:	A Preliminary Endangerment Assessment was completed to assess soil contamination which resulted from a soap manu- facturing operation.

BEAULIEU INDUSTRIES (Continued) **S101592888**

The PEA concluded that no further action was required at the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 03/24/1988
Comments: ENFORCEMENT(OTHER) THIS SITE IS REFERRED TO ENFORCEMENT TO VERIFY IF ABANDONED RAW MATERIAL HAS BEEN CLEANED UP AT THIS SITE. PRELIM ASSESS DONE REFERRED TO ENFORCEMENT TO VERIFY CLEANUP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment/Site Inspection Report (PA/SI)
Completed Date: 08/18/1988
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/28/1995
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: BEAULIEU CHEMICAL COMPANY
Address: 400 S AURORA ST
City,State,Zip: STOCKTON, CA 95203
Facility ID: 39280007
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 2.48
National Priorities List: NO
Cleanup Oversight Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Lead Agency Description: Not reported
Project Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Site Code: 100438
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: No Further Action
Status Date: 06/28/1995
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.95022 / -121.2774

BEAULIEU INDUSTRIES (Continued) **S101592888**

APN: 15126037
Past Use: MANUFACTURING - CHEMICALS, MANUFACTURING - CHEMICALS
Potential COC: 10098, 10120, 10193, 10194, 30409, 30461, 305251
Confirmed COC: NONE SPECIFIED
Potential Description: SOIL, SOIL
Alias Name: 15126037
Alias Type: APN
Alias Name: 110011463148
Alias Type: EPA (FRS #)
Alias Name: 100438
Alias Type: Project Code (Site Code)
Alias Name: 39280007
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 02/23/1995
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 06/28/1995
Comments: A Preliminary Endangerment Assessment was completed to assess soil contamination which resulted from a soap manu- facturing operation. The PEA concluded that no further action was required at the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 03/24/1988
Comments: ENFORCEMENT(OTHER) THIS SITE IS REFERRED TO ENFORCEMENT TO VERIFY IF ABANDONED RAW MATERIAL HAS BEEN CLEANED UP AT THIS SITE. PRELIM ASSESS DONE REFERRED TO ENFORCEMENT TO VERIFY CLEANUP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment/Site Inspection Report (PA/SI)
Completed Date: 08/18/1988
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/28/1995
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

BEAULIEU INDUSTRIES (Continued) **S101592888**

SWEEPS UST:

Name:	BEAULIEU INDUSTRIES
Address:	400 S AURORA
City:	STOCKTON
Status:	Not reported
Comp Number:	1016
Number:	Not reported
Board Of Equalization:	44-024492
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001016-000001
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	3

Name:	BEAULIEU INDUSTRIES
Address:	400 S AURORA
City:	STOCKTON
Status:	Not reported
Comp Number:	1016
Number:	Not reported
Board Of Equalization:	44-024492
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001016-000002
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported

Name:	BEAULIEU INDUSTRIES
Address:	400 S AURORA
City:	STOCKTON
Status:	Not reported
Comp Number:	1016
Number:	Not reported
Board Of Equalization:	44-024492
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001016-000003
Tank Status:	Not reported
Capacity:	1400
Active Date:	Not reported
Tank Use:	M.V. FUEL

BEAULIEU INDUSTRIES (Continued) **S101592888**

STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000598
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094664151
Mail To: Not reported
Mailing Address: 326 LA ESPRAL
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95204
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

Z160 **FORMER AMERICA SAVINGS (AREA 7)** **US BROWNFIELDS** **1012237609**
NNW **CHANNEL ST. & EL DORADO ST.** **N/A**
1/4-1/2 **STOCKTON, CA 95202**
0.462 mi.
2438 ft. **Site 2 of 3 in cluster Z**

Relative: **Lower**

Actual: **14 ft.**

US BROWNFIELDS:
Name: FORMER AMERICA SAVINGS (AREA 7)
Address: CHANNEL ST. & EL DORADO ST.
City,State,Zip: STOCKTON, CA 95202
Recipient Name: Stockton, City of
Grant Type: Assessment
Property Number: -
Parcel size: -
Latitude: 37.95464
Longitude: -121.290319
HCM Label: -
Map Scale: -
Point of Reference: -
Highlights: -
Datum: -
Acres Property ID: 14269
IC Data Access: -
Start Date: -
Redev Completition Date: -
Completed Date: -
Acres Cleaned Up: -
Cleanup Funding: -
Cleanup Funding Source: -
Assessment Funding: -
Assessment Funding Source: -
Redevelopment Funding: -
Redev. Funding Source: -
Redev. Funding Entity Name: -

FORMER AMERICA SAVINGS (AREA 7) (Continued) **1012237609**

Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	06/30/2001
Ownership Entity:	-
Completion Date:	06/30/2001
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-
Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-

FORMER AMERICA SAVINGS (AREA 7) (Continued) **1012237609**

Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-
Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1786
Below Poverty Percent:	51.89
Meidan Income:	1813
Meidan Income Number:	2923
Meidan Income Percent:	84.92
Vacant Housing Number:	440
Vacant Housing Percent:	21.76
Unemployed Number:	356
Unemployed Percent:	10.34

Z161
NNW
1/4-1/2
0.462 mi.
2438 ft.

GLASS PRO BUILDING (AREA 8)
CHANNEL ST. & EL DORADO ST.
STOCKTON, CA 95202

Site 3 of 3 in cluster Z

US BROWNFIELDS **1012236935**
N/A

Relative:
Lower

Actual:
14 ft.

US BROWNFIELDS:

Name:	GLASS PRO BUILDING (AREA 8)
Address:	CHANNEL ST. & EL DORADO ST.
City,State,Zip:	STOCKTON, CA 95202
Recipient Name:	Stockton, City of
Grant Type:	Assessment
Property Number:	-
Parcel size:	-
Latitude:	37.95464
Longitude:	-121.290319
HCM Label:	-
Map Scale:	-
Point of Reference:	-
Highlights:	-
Datum:	-
Acres Property ID:	14276
IC Data Access:	-
Start Date:	-
Redev Completition Date:	-
Completed Date:	-
Acres Cleaned Up:	-
Cleanup Funding:	-
Cleanup Funding Source:	-
Assessment Funding:	-
Assessment Funding Source:	-
Redevelopment Funding:	-
Redev. Funding Source:	-
Redev. Funding Entity Name:	-
Redevelopment Start Date:	-
Assessment Funding Entity:	-
Cleanup Funding Entity:	-
Grant Type:	-
Accomplishment Type:	Phase I Environmental Assessment
Accomplishment Count:	N
Cooperative Agreement Number:	99944601
Start Date:	06/30/2001
Ownership Entity:	-
Completion Date:	06/30/2001
Current Owner:	-
Did Owner Change:	-
Cleanup Required:	-
Video Available:	-
Photo Available:	-
Institutional Controls Required:	-
IC Category Proprietary Controls:	-
IC Cat. Info. Devices:	-
IC Cat. Gov. Controls:	-
IC Cat. Enforcement Permit Tools:	-
IC in place date:	-
IC in place:	U
State/tribal program date:	-
State/tribal program ID:	-
State/tribal NFA date:	-

GLASS PRO BUILDING (AREA 8) (Continued) **1012236935**

Air cleaned:	-
Asbestos found:	-
Asbestos cleaned:	-
Controled substance found:	-
Controled substance cleaned:	-
Drinking water affected:	-
Drinking water cleaned:	-
Groundwater affected:	-
Groundwater cleaned:	-
Lead contaminant found:	-
Lead cleaned up:	-
No media affected:	Not reported
Unknown media affected:	-
Other cleaned up:	-
Other metals found:	-
Other metals cleaned:	-
Other contaminants found:	-
Other contams found description:	-
PAHs found:	-
PAHs cleaned up:	-
PCBs found:	-
PCBs cleaned up:	-
Petro products found:	-
Petro products cleaned:	-
Sediments found:	-
Sediments cleaned:	-
Soil affected:	-
Soil cleaned up:	-
Surface water cleaned:	-
VOCs found:	-
VOCs cleaned:	-
Cleanup other description:	-
Num. of cleanup and re-dev. jobs:	-
Past use greenspace acreage:	-
Past use residential acreage:	-
Surface Water:	-
Past use commercial acreage:	-
Past use industrial acreage:	-
Future use greenspace acreage:	-
Future use residential acreage:	-
Future use commercial acreage:	-
Future use industrial acreage:	-
Superfund Fed. landowner flag:	-
Arsenic cleaned up:	-
Cadmium cleaned up:	-
Chromium cleaned up:	-
Copper cleaned up:	-
Iron cleaned up:	-
mercury cleaned up:	-
Nickel Cleaned Up:	-
No clean up:	-
Pesticides cleaned up:	-
Selenium cleaned up:	-
SVOCs cleaned up:	-
Unknown clean up:	-
Arsenic contaminant found:	-
Cadmium contaminant found:	-

GLASS PRO BUILDING (AREA 8) (Continued) **1012236935**

Chromium contaminant found:	-
Copper contaminant found:	-
Iron contaminant found:	-
Mercury contaminant found:	-
Nickel contaminant found:	-
No contaminant found:	-
Pesticides contaminant found:	-
Selenium contaminant found:	-
SVOCs contaminant found:	-
Unknown contaminant found:	-
Future Use: Multistory	-
Media affected Bluiding Material:	-
Media affected indoor air:	-
Building material media cleaned up:	-
Indoor air media cleaned up:	-
Unknown media cleaned up:	-
Past Use: Multistory	Not reported
Property Description:	-
Below Poverty Number:	1786
Below Poverty Percent:	51.89
Meidan Income:	1813
Meidan Income Number:	2923
Meidan Income Percent:	84.92
Vacant Housing Number:	440
Vacant Housing Percent:	21.76
Unemployed Number:	356
Unemployed Percent:	10.34

162
WSW
1/4-1/2
0.464 mi.
2452 ft.

E.F. MITCHLER CO
400 LINCOLN
STOCKTON, CA 95203

LUST **S101302734**
Cortese **N/A**
HIST CORTESE
CERS

Relative:
Lower

Actual:
13 ft.

LUST:

Name:	E.F. MITCHLER CO
Address:	400 LINCOLN ST S
City,State,Zip:	STOCKTON, CA 95203
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700555
Global Id:	T0607700555
Latitude:	37.946922
Longitude:	-121.294875
Status:	Completed - Case Closed
Status Date:	05/18/1992
Case Worker:	Not reported
RB Case Number:	390717
Local Agency:	Not reported
File Location:	Not reported
Local Case Number:	0001411
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607700555
Contact Type:	Regional Board Caseworker

E.F. MITCHLER CO (Continued) **S101302734**

Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700555
Action Type: Other
Date: 09/13/1991
Action: Leak Discovery

Global Id: T0607700555
Action Type: Other
Date: 10/14/1991
Action: Leak Reported

LUST:
Global Id: T0607700555
Status: Open - Case Begin Date
Status Date: 09/13/1991

Global Id: T0607700555
Status: Completed - Case Closed
Status Date: 05/18/1992

LUST REG 5:
Name: E.F. MITCHLER CO
Address: 400 LINCOLN ST S
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390717
Case Type: Soil only
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: E.F. MITCHLER CO
Address: 400 LINCOLN ST S
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700555
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported

E.F. MITCHLER CO (Continued) **S101302734**

Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	E.F. MITCHLER CO
edr_fadd1:	400 LINCOLN
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390717

CERS:

Name:	E.F. MITCHLER CO
Address:	400 LINCOLN ST S
City,State,Zip:	STOCKTON, CA 95203
Site ID:	255245
CERS ID:	T0607700555
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AA163 **BEAULIEU CHEMICAL COMPANY** **HIST CORTESE** **S101302600**
ENE **400 AURORA** **N/A**
1/4-1/2 **STOCKTON, CA 95201**
0.468 mi.
2471 ft. **Site 4 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

HIST CORTESE:

edr_fname:	BEAULIEU CHEMICAL COMPANY
edr_fadd1:	400 AURORA
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	CALSI
Reg Id:	39280007

BEAULIEU CHEMICAL COMPANY (Continued) **S101302600**

edr_fname:	CAPITOL VENTURE ENTERPRIS
edr_fadd1:	400 AURORA
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390747

164
NW
1/4-1/2
0.477 mi.
2521 ft.

Relative: Lower

Actual: 12 ft.

ARCO #4493
205 N CENTER ST
STOCKTON, CA 95202

LUST **S101592834**
SWEEPS UST **N/A**
CA FID UST
Cortese
HIST CORTESE
Notify 65
CERS

LUST:

Name:	ARCO #4493 (FORMER)
Address:	205 CENTER ST N
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700462
Global Id:	T0607700462
Latitude:	37.9544579
Longitude:	-121.2917114
Status:	Completed - Case Closed
Status Date:	01/26/2011
Case Worker:	Not reported
RB Case Number:	390586
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	1042
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	July 1997 groundwater contamination containing MtBE was noted at a non-operating Shell Station site located down-gradient from the ARCO station. February 1999 three 12,000 gallon underground storage tanks removed, contamination was noted under the tanks. The site investigation began after this with the installation of four groundwater monitoring wells. Between June 2000 and May 2004 additional groundwater monitoring wells, both shallow and deep, were installed. The site is defined; the problem area is around the MW-4/MW-8M/MW-8D/MW-12 cluster of wells located near the former dispenser island area. The EHD has requested interim remediation of these wells to lower contaminant concentrations. Quarterly batch extractions began in third quarter 2008. The EHD sent notification to the Regional Water Quality Control Board on 6/10/10 of their intent to close the site. In preparation for closure, destruction of all groundwater monitoring wells began on 10/18/10.

LUST:

Global Id:	T0607700462
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA

ARCO #4493 (Continued) **S101592834**

Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 09/25/2009
Action: File review

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 02/03/2010
Action: File review

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 06/10/2010
Action: LOP Case Closure Summary to RB

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 04/26/2010
Action: File review

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 06/15/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 04/29/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 08/17/1998
Action: Unauthorized Release Form

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 10/29/1999
Action: Notice of Responsibility

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 09/09/1998
Action: Notification - Proposition 65

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 01/24/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 01/26/2011

ARCO #4493 (Continued) **S101592834**

Action: Closure/No Further Action Letter

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 06/30/2010
Action: File Review - Closure

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 10/20/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700462
Action Type: Other
Date: 11/01/1993
Action: Leak Discovery

Global Id: T0607700462
Action Type: Other
Date: 02/24/1999
Action: Leak Stopped

Global Id: T0607700462
Action Type: Other
Date: 09/10/1998
Action: Leak Reported

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 05/28/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 09/15/1998
Action: Notice of Responsibility

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 09/30/2008
Action: Technical Correspondence / Assistance / Other - #09/30/2008

Global Id: T0607700462
Action Type: REMEDIATION
Date: 10/10/2008
Action: Other (Use Description Field)

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 01/13/2009
Action: Site Visit / Inspection / Sampling

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 03/27/2009
Action: File review

ARCO #4493 (Continued) **S101592834**

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 05/08/2009
Action: File review

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 06/18/2009
Action: File review

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 04/20/2009
Action: Technical Correspondence / Assistance / Other - #04/20/2009

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 07/15/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700462
Action Type: ENFORCEMENT
Date: 07/01/2009
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700462
Status: Open - Case Begin Date
Status Date: 12/16/1987

Global Id: T0607700462
Status: Open - Remediation
Status Date: 12/16/1987

Global Id: T0607700462
Status: Open - Site Assessment
Status Date: 02/11/1999

Global Id: T0607700462
Status: Open - Site Assessment
Status Date: 05/09/2002

Global Id: T0607700462
Status: Open - Site Assessment
Status Date: 12/05/2003

Global Id: T0607700462
Status: Open - Assessment & Interim Remedial Action
Status Date: 01/13/2009

Global Id: T0607700462
Status: Completed - Case Closed
Status Date: 01/26/2011

LUST REG 5:

ARCO #4493 (Continued) **S101592834**

Name: FORMER ARCO STATION #4493
Address: 205 CENTER ST N
City: STOCKTON
Region: 5
Status: Pollution Characterization
Case Number: 390586
Case Type: Drinking Water Aquifer affected
Substance: UNLEAD GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 7

SWEEPS UST:
Name: ARCO #4493
Address: 205 N CENTER ST
City: STOCKTON
Status: Active
Comp Number: 1042
Number: 1
Board Of Equalization: 44-000506
Referral Date: 06-10-92
Action Date: 06-10-92
Created Date: 06-15-88
Owner Tank Id: 001
SWRCB Tank Id: 39-000-001042-000001
Tank Status: A
Capacity: 12000
Active Date: 06-10-92
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 3

Name: ARCO #4493
Address: 205 N CENTER ST
City: STOCKTON
Status: Active
Comp Number: 1042
Number: 1
Board Of Equalization: 44-000506
Referral Date: 06-10-92
Action Date: 06-10-92
Created Date: 06-15-88
Owner Tank Id: 002
SWRCB Tank Id: 39-000-001042-000002
Tank Status: A
Capacity: 12000
Active Date: 06-10-92
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: ARCO #4493
Address: 205 N CENTER ST
City: STOCKTON

ARCO #4493 (Continued) **S101592834**

Status:	Active
Comp Number:	1042
Number:	1
Board Of Equalization:	44-000506
Referral Date:	06-10-92
Action Date:	06-10-92
Created Date:	06-15-88
Owner Tank Id:	003
SWRCB Tank Id:	39-000-001042-000003
Tank Status:	A
Capacity:	12000
Active Date:	06-10-92
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

CA FID UST:

Facility ID:	39000478
Regulated By:	UTNKA
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2099480838
Mail To:	Not reported
Mailing Address:	17315 STUDEBAKER ROAD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95202
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

CORTESE:

Name:	ARCO #4493 (FORMER)
Address:	205 CENTER ST N
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700462
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported

ARCO #4493 (Continued) **S101592834**

Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: ARCO #4493
edr_fadd1: 205 CENTER
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390586

NOTIFY 65:
Name: ARCO #4493 (FORMER)
Address: 205 CENTER ST N
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 09/09/1998
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: ARCO #4493 (FORMER)
Address: 205 CENTER ST N
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: ARCO #4493 (FORMER)
Address: 205 CENTER ST N
City,State,Zip: STOCKTON, CA 95202
Site ID: 256816
CERS ID: T0607700462
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA

ARCO #4493 (Continued) **S101592834**

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

---

165 SIERRA LUMBER CASE #1 **LUST S104162927**
WSW 375 HAZELTON AVE W **Cortese N/A**
1/4-1/2 STOCKTON, CA 95203 **HIST CORTESE**
0.480 mi. **CERS**
2536 ft.

Relative: Lower

Actual: 10 ft.

LUST:
Name: SIERRA LUMBER CASE #2
Address: 375 HAZELTON AVENUE
City,State,Zip: STOCKTON, CA 95203
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607726897
Global Id: T0607726897
Latitude: 37.9460081040611
Longitude: -121.293590068817
Status: Completed - Case Closed
Status Date: 03/26/2020
Case Worker: AMB
RB Case Number: 391168
Local Agency: Not reported
File Location: Regional Board
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: All known USTs removed from this site. One UST was removed at Case #2 location before 1980, not records at EHD. CAP (DPE) approved and remediation began 2012. This case is linked to on-site Case 1 (which is an open case that could be considered for NFAR) for SWRCB C.F. reimbursement.

LUST:
Global Id: T0607726897
Contact Type: Regional Board Caseworker
Contact Name: ALAN M. BUEHLER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 Sun Center Dr
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: 9164644615

LUST:
Global Id: T0607726897
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Other

Global Id: T0607726897
Action Type: RESPONSE
Date: 02/01/2006
Action: Monitoring Report - Quarterly

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607726897
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607726897
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Quarterly

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/25/2014
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 01/20/2010
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/21/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/26/2010
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 06/30/2014
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

Global Id: T0607726897
Action Type: RESPONSE
Date: 06/13/2018
Action: Other Report / Document

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/23/2011
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 08/12/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 03/15/2016
Action: Staff Letter

Global Id: T0607726897
Action Type: RESPONSE
Date: 03/20/2019
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 08/04/2011
Action: Notification - Public Participation Document

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/30/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/15/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 11/18/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 04/11/2017
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 01/08/2008
Action: Other Report

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/23/2017
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 01/22/2016
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 01/29/2018
Action: Staff Letter

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 11/01/2017
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/23/2014
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 06/26/2018
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/25/2019
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 10/16/2018
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 04/08/2019
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 08/22/2019
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 03/26/2020
Action: Closure/No Further Action Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 11/25/2019
Action: Staff Letter

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 08/22/2019
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 12/02/2019
Action: Staff Letter

Global Id: T0607726897
Action Type: RESPONSE

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 10/20/2014
Action: Preliminary Site Assessment Workplan - Addendum - Regulator Responded

Global Id: T0607726897
Action Type: RESPONSE
Date: 02/29/2016
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/27/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/09/2019
Action: Staff Letter

Global Id: T0607726897
Action Type: Other
Date: 06/22/2004
Action: Leak Discovery

Global Id: T0607726897
Action Type: Other
Date: 01/01/1979
Action: Leak Stopped

Global Id: T0607726897
Action Type: Other
Date: 10/15/2004
Action: Leak Reported

Global Id: T0607726897
Action Type: RESPONSE
Date: 07/01/2015
Action: Preliminary Site Assessment Report

Global Id: T0607726897
Action Type: RESPONSE
Date: 11/26/2019
Action: Well Destruction Workplan - Regulator Responded

Global Id: T0607726897
Action Type: RESPONSE
Date: 06/15/2018
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607726897
Action Type: RESPONSE
Date: 03/24/2017
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 10/18/2004
Action: Notice of Responsibility

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 05/29/2013
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 06/08/2012
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/15/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 01/15/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607726897
Action Type: REMEDIATION
Date: 01/24/2011
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/27/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/10/2013
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/27/2013
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 02/25/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/15/2013
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 07/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Other

Global Id: T0607726897
Action Type: RESPONSE
Date: 05/31/2005
Action: Monitoring Report - Quarterly

Global Id: T0607726897
Action Type: RESPONSE
Date: 11/15/2005
Action: Well Installation Report

Global Id: T0607726897
Action Type: RESPONSE
Date: 07/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 12/16/2008
Action: Site Visit / Inspection / Sampling

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/03/2008
Action: Staff Letter - #07/03/2008

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 12/28/2012
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 08/23/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 08/01/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 09/25/2012
Action: File review

Global Id: T0607726897
Action Type: RESPONSE
Date: 05/18/2006
Action: Well Installation Report

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607726897
Action Type: RESPONSE
Date: 11/07/2005
Action: Monitoring Report - Quarterly

Global Id: T0607726897
Action Type: RESPONSE
Date: 10/30/2015
Action: Monitoring Report - Other

Global Id: T0607726897
Action Type: RESPONSE
Date: 02/29/2016
Action: Correspondence

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 04/09/2009
Action: File review

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 07/16/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607726897
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

LUST:
Global Id: T0607726897
Status: Open - Case Begin Date
Status Date: 06/22/2004

Global Id: T0607726897
Status: Open - Site Assessment
Status Date: 06/22/2004

Global Id: T0607726897
Status: Open - Site Assessment
Status Date: 10/18/2004

Global Id: T0607726897
Status: Open - Assessment & Interim Remedial Action
Status Date: 10/11/2012

Global Id: T0607726897
Status: Open - Remediation
Status Date: 10/11/2012

Global Id: T0607726897
Status: Open - Verification Monitoring
Status Date: 01/29/2018

Global Id: T0607726897
Status: Open - Eligible for Closure

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Status Date: 09/09/2019

Global Id: T0607726897
Status: Completed - Case Closed
Status Date: 03/26/2020

Name: SIERRA LUMBER CASE #1
Address: 375 HAZELTON AVE W
City,State,Zip: STOCKTON, CA 95203
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700185
Global Id: T0607700185
Latitude: 37.94507416
Longitude: -121.2945402
Status: Completed - Case Closed
Status Date: 03/26/2020
Case Worker: AMB
RB Case Number: 390257
Local Agency: Not reported
File Location: Regional Board
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: One 1000-gasoline UST removed in Site Case #1 area. 8 MWs were installed, remedial wells installed, and active SVE/IAS was conducted. Post remediation monitoring evaluation conducted, soil vapor samples collected post remediation which pass ESLs and CHHL's. This site will be evaluated for NFAR, but this case is linked to on-site Case 2 C.F. reimbursement.

LUST:
Global Id: T0607700185
Contact Type: Regional Board Caseworker
Contact Name: ALAN M. BUEHLER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 Sun Center Dr
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: 9164644615

LUST:
Global Id: T0607700185
Action Type: RESPONSE
Date: 08/26/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 02/18/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 07/06/1996
Action: Monitoring Report - Quarterly

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607700185
Action Type: RESPONSE
Date: 03/04/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 11/21/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 10/23/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 05/02/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 03/26/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 02/14/2006
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 07/20/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 10/01/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 07/07/2000
Action: Remedial Progress Report

Global Id: T0607700185
Action Type: RESPONSE
Date: 03/02/1999
Action: Remedial Progress Report

Global Id: T0607700185
Action Type: RESPONSE
Date: 12/07/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 08/25/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 06/04/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 04/09/2009
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 01/20/2010
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 09/19/2014
Action: Staff Letter

Global Id: T0607700185
Action Type: RESPONSE
Date: 01/08/2008
Action: Soil Vapor Intrusion Investigation Report

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 01/26/2011
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 08/04/2011
Action: File review

Global Id: T0607700185
Action Type: RESPONSE
Date: 04/06/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 08/04/2010
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 12/28/2017
Action: Staff Letter

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 06/14/2017
Action: Email Correspondence

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 10/16/2018
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 06/26/2018
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 02/25/2019
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 03/26/2020
Action: Closure/No Further Action Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 11/25/2019
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 12/02/2019
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 01/31/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 04/08/2019
Action: Staff Letter

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 09/09/2019
Action: Staff Letter

Global Id: T0607700185
Action Type: Other
Date: 08/01/1988
Action: Leak Discovery

Global Id: T0607700185
Action Type: Other

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 08/01/1988
Action: Leak Stopped

Global Id: T0607700185
Action Type: Other
Date: 08/19/1988
Action: Leak Reported

Global Id: T0607700185
Action Type: RESPONSE
Date: 02/20/2019
Action: Request for Closure - Regulator Responded

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 07/23/2012
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 03/27/2013
Action: File Review - Closure

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 11/04/2013
Action: File Review - Closure

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 09/25/2012
Action: File review

Global Id: T0607700185
Action Type: RESPONSE
Date: 02/15/2000
Action: Final Remedial Action Report / Corrective Action Report

Global Id: T0607700185
Action Type: RESPONSE
Date: 11/10/1994
Action: Other Report / Document

Global Id: T0607700185
Action Type: RESPONSE
Date: 01/29/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 11/07/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 04/22/2002
Action: Monitoring Report - Quarterly

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607700185
Action Type: RESPONSE
Date: 03/02/1999
Action: Unauthorized Release Form

Global Id: T0607700185
Action Type: RESPONSE
Date: 09/17/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 12/10/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 10/29/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 09/03/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 07/28/1994
Action: Other Report / Document

Global Id: T0607700185
Action Type: RESPONSE
Date: 04/06/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 01/03/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 06/20/1994
Action: Site Assessment Report

Global Id: T0607700185
Action Type: RESPONSE
Date: 03/29/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 12/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: REMEDIATION

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Date: 08/25/1999
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607700185
Action Type: REMEDIATION
Date: 08/25/1999
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 07/15/2013
Action: File review

Global Id: T0607700185
Action Type: RESPONSE
Date: 05/24/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 08/24/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 11/08/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 06/08/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 08/03/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 06/27/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: RESPONSE
Date: 11/25/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700185
Action Type: REMEDIATION
Date: 04/01/2001
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 04/11/1994
Action: Notice of Reimbursement

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 06/25/2014
Action: File review

Global Id: T0607700185
Action Type: ENFORCEMENT
Date: 03/30/2015
Action: Staff Letter

LUST:
Global Id: T0607700185
Status: Open - Case Begin Date
Status Date: 08/01/1988

Global Id: T0607700185
Status: Open - Site Assessment
Status Date: 04/11/1994

Global Id: T0607700185
Status: Open - Remediation
Status Date: 04/18/2001

Global Id: T0607700185
Status: Open - Verification Monitoring
Status Date: 11/01/2005

Global Id: T0607700185
Status: Open - Eligible for Closure
Status Date: 09/09/2019

Global Id: T0607700185
Status: Completed - Case Closed
Status Date: 03/26/2020

LUST REG 5:
Name: SIERRA LUMBER
Address: 375 HAZELTON AVE W
City: STOCKTON
Region: 5
Status: Preliminary site assessment underway
Case Number: 390257
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

CORTESE:
Name: SIERRA LUMBER CASE #1
Address: 375 HAZELTON AVE W
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported

SIERRA LUMBER CASE #1 (Continued) **S104162927**

Global ID:	T0607700185
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	SIERRA LUMBER
edr_fadd1:	375 HAZELTON
City,State,Zip:	STOCKTON, CA 95203
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390257

CERS:

Name:	SIERRA LUMBER CASE #1
Address:	375 HAZELTON AVE W
City,State,Zip:	STOCKTON, CA 95203
Site ID:	258527
CERS ID:	T0607700185
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Dr
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644615

AB166 **VALLEY MOTORS** **LUST** **S104403450**
NE **800 MAIN ST E** **CPS-SLIC** **N/A**
1/4-1/2 **STOCKTON, CA 95201** **Cortese**
0.483 mi. **HIST CORTESE**
2552 ft. **Site 1 of 3 in cluster AB** **CERS**

Relative: Higher
Actual: 18 ft.

LUST:

Name:	VALLEY MOTORS
Address:	800 MAIN ST E
City,State,Zip:	STOCKTON, CA 95201
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700430
Global Id:	T0607700430
Latitude:	37.954196502
Longitude:	-121.2805411
Status:	Completed - Case Closed
Status Date:	12/03/2014
Case Worker:	AMB
RB Case Number:	390546
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	1166
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	**********START Public notes********** Two USTs removed 10-22-1990. Contamination noted in laboratory soil samples. Site enters LOP February 5, 1993. Eight monitoring wells installed from Sept 1995 to April 2003. Soil vapor extraction remediation conducted Dec 2005 to Third Quarter 2006. EHD requires additional remediation. IAS tested by not feasible. GWE tested June 2009. Results pending. Ground water extraction/treat/discharge currently being pilot tested, October, 2009. 3-8-2010: Receive and review report of GWE pilot test. 5-27-10: EHD comment letter of report of GWE-require Feasibility Study by June 30, 2010. Review NOT submitted as of 12-08-2010. April 21, 2011: EHD directive letter to submit many missing Geotracker submittals by May 27, 2011. July 1, 2011: Many, but NOT all Geotracker submittals uploaded by consultant on June 2, 2011-Work plan for two GW extraction wells and addn'l pump test submitted also. July 13, 2011: EHD approves workplan to continue GWE pilot and requires schedule for all activities to be submitted by July 29, 2011. July 29, 2011: Upgradient consulting submits schedule. Aug 3, 2011: EHD recieves WP addendum to already approved GWE workplan and reduces all work/wells. Aug 5, 2011: EHD approves GWE WPaddn and directs multiple dates for all activities to be completed with report of findings and feasibility study due Nov 18, 2011. Reports not submitted, work not done, monitoring not continuing-site referred to CVRWQCB in letter dated Jan 13, 2012. <<<<<<<<<<<<<<<END of public notes>>>>>>>>>>>>>

LUST:

Global Id:	T0607700430
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

VALLEY MOTORS (Continued) **S104403450**

LUST:

Global Id:	T0607700430
Action Type:	RESPONSE
Date:	10/23/1990
Action:	Other Report / Document
Global Id:	T0607700430
Action Type:	RESPONSE
Date:	06/25/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	09/17/2009
Action:	Site Visit / Inspection / Sampling
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	12/09/2009
Action:	File review
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	12/11/1995
Action:	Other Report
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	03/25/1997
Action:	Staff Letter
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	11/06/2008
Action:	Staff Letter
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	04/07/1997
Action:	Staff Letter
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	08/22/1994
Action:	Staff Letter
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	06/24/1993
Action:	Staff Letter
Global Id:	T0607700430
Action Type:	ENFORCEMENT
Date:	01/13/2012
Action:	Staff Letter
Global Id:	T0607700430

VALLEY MOTORS (Continued) **S104403450**

Action Type: ENFORCEMENT
Date: 12/19/2003
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/23/1999
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/16/1997
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/24/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/06/1998
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/16/1997
Action: Verbal Communication

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/30/2013
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/09/1999
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/04/2014
Action: Notification - Public Notice of Case Closure

Global Id: T0607700430
Action Type: RESPONSE
Date: 09/21/2012
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/08/2010
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/23/2009

VALLEY MOTORS (Continued) **S104403450**

Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/07/2010
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/27/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/03/2011
Action: Verbal Enforcement

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/31/2006
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/12/2005
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/29/1997
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/03/2014
Action: Closure/No Further Action Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/22/2013
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/10/2013
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/24/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/25/2008
Action: Staff Letter

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/09/2007
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/10/1995
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/12/2014
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/21/2014
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/09/2013
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/10/1993
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/21/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/20/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/14/2009
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/05/2008
Action: Email Correspondence

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/27/2012
Action: Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT

VALLEY MOTORS (Continued) **S104403450**

Date: 08/01/2011
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 07/14/2011
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/01/2013
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/25/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/21/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/11/1999
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 09/21/1999
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/14/1999
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/27/2010
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/10/2008
Action: Staff Letter

Global Id: T0607700430
Action Type: RESPONSE
Date: 04/30/2012
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/15/2012
Action: Correspondence - Regulator Responded

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/21/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 04/27/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 05/10/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 05/24/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 06/08/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 06/22/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/20/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/05/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/03/2011
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/25/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 07/13/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT

VALLEY MOTORS (Continued) **S104403450**

Date: 07/01/2011
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/21/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: RESPONSE
Date: 04/30/2013
Action: Monitoring Report - Annually

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/08/2014
Action: Tank Removal Report / UST Sampling Report

Global Id: T0607700430
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/08/2013
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 11/15/2012
Action: Other Report / Document - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 10/30/2013
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/30/2013
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 11/19/2013
Action: Verbal Communication - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 01/30/2014
Action: Correspondence - Regulator Responded

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/28/2014
Action: Fact Sheets - Public Participation - Regulator Responded

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/15/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/08/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 07/29/2011
Action: File review

Global Id: T0607700430
Action Type: RESPONSE
Date: 03/11/2014
Action: Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/14/2012
Action: Meeting

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/14/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/24/2012
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/13/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/25/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/20/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: ENFORCEMENT

VALLEY MOTORS (Continued) **S104403450**

Date: 07/13/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 09/19/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700430
Action Type: Other
Date: 10/22/1990
Action: Leak Discovery

Global Id: T0607700430
Action Type: Other
Date: 10/25/1990
Action: Leak Reported

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/15/2014
Action: Well Destruction Report

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/23/2012
Action: Staff Letter

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/14/2009
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0607700430
Action Type: RESPONSE
Date: 05/02/2014
Action: Fact Sheets - Public Participation

Global Id: T0607700430
Action Type: RESPONSE
Date: 05/30/2014
Action: Correspondence

Global Id: T0607700430
Action Type: REMEDIATION
Date: 08/13/2007
Action: In Situ Physical/Chemical Treatment (other than SVE)

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: REMEDIATION
Date: 01/01/2010
Action: Pump & Treat (P&T) Groundwater

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/17/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/07/2013
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/10/2012
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/27/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/01/2013
Action: Staff Letter

Global Id: T0607700430
Action Type: RESPONSE
Date: 02/18/2014
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE
Date: 03/06/2007
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE
Date: 04/25/2012
Action: Correspondence

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/09/2010
Action: Correspondence

Global Id: T0607700430
Action Type: RESPONSE
Date: 09/11/2012
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE

VALLEY MOTORS (Continued) **S104403450**

Date: 04/24/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/02/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/19/2008
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/09/2008
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/14/2009
Action: Notice of Responsibility

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 04/15/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/12/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/20/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/06/2009
Action: Meeting

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/18/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/28/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/09/2009
Action: Technical Correspondence / Assistance / Other

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/15/2009
Action: Letter - Notice

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/12/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/16/2008
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/05/2008
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/02/2009
Action: File review

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 07/18/2012
Action: Verbal Enforcement

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/07/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/21/2012
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 05/01/2012
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/09/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 11/08/2013
Action: Staff Letter

Global Id: T0607700430
Action Type: RESPONSE

VALLEY MOTORS (Continued) **S104403450**

Date: 07/31/2014
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE
Date: 08/22/2013
Action: Correspondence

Global Id: T0607700430
Action Type: RESPONSE
Date: 03/19/2012
Action: Monitoring Report - Quarterly

Global Id: T0607700430
Action Type: RESPONSE
Date: 10/25/1990
Action: Unauthorized Release Form

Global Id: T0607700430
Action Type: RESPONSE
Date: 06/07/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700430
Action Type: RESPONSE
Date: 03/02/1992
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE
Date: 10/31/2003
Action: Other Report / Document

Global Id: T0607700430
Action Type: RESPONSE
Date: 07/31/2012
Action: Other Report / Document

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/30/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/27/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/01/2009
Action: Site Visit / Inspection / Sampling

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 08/10/2009
Action: File review

VALLEY MOTORS (Continued) **S104403450**

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 01/08/2014
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/04/2014
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 06/23/2012
Action: Email Correspondence

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 10/23/1995
Action: Other Report

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 12/13/1995
Action: Staff Letter

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 02/05/1993
Action: Notice of Reimbursement

Global Id: T0607700430
Action Type: ENFORCEMENT
Date: 03/12/2014
Action: Email Correspondence

LUST:
Global Id: T0607700430
Status: Open - Case Begin Date
Status Date: 10/22/1990

Global Id: T0607700430
Status: Open - Site Assessment
Status Date: 10/25/1990

Global Id: T0607700430
Status: Open - Remediation
Status Date: 12/19/2003

Global Id: T0607700430
Status: Open - Site Assessment
Status Date: 08/13/2007

Global Id: T0607700430
Status: Open - Remediation
Status Date: 01/01/2010

Global Id: T0607700430

VALLEY MOTORS (Continued) **S104403450**

Status: Open - Verification Monitoring
Status Date: 12/31/2013

Global Id: T0607700430
Status: Open - Eligible for Closure
Status Date: 04/24/2014

Global Id: T0607700430
Status: Completed - Case Closed
Status Date: 12/03/2014

LUST REG 5:
Name: VALLEY MOTORS
Address: 800 MAIN ST E
City: STOCKTON
Region: 5
Status: Remediation Plan
Case Number: 390546
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 4

SLIC REG 5:
Name: Valley Motors, Inc.
Address: 800 Main St E
City: Stockton
Region: 5
Facility Status: Phase Two Remedial Investigation
Unit: Facility is a Spill or site
Pollutant: TPH, MTBE, BTEX
Lead Agency: Not reported
Date Filed: 04/07/97
Report Date: 07/26/96
Date Added: Not reported
Date Closed: Not reported

CORTESE:
Name: VALLEY MOTORS
Address: 800 MAIN ST E
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700430
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported

VALLEY MOTORS (Continued) **S104403450**

Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	VALLEY MOTORS
edr_fadd1:	800 MAIN
City,State,Zip:	STOCKTON, CA 95201
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390546

CERS:

Name:	VALLEY MOTORS
Address:	800 MAIN ST E
City,State,Zip:	STOCKTON, CA 95201
Site ID:	250536
CERS ID:	T0607700430
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AB167 **CHLORINATED SOLVENT CASE - CORNER OF EAST MAIN STR** **CPS-SLIC** **S118154690**
NE **EAST MAIN STREET & SOUTH GRANT STREET** **CERS** **N/A**
1/4-1/2 **STOCKTON, CA**
0.484 mi.
2555 ft. **Site 2 of 3 in cluster AB**

Relative:
Higher
Actual:
18 ft.

CPS-SLIC:

Name:	CHLORINATED SOLVENT CASE - CORNER OF EAST MAIN STREET AND SOUTH GRANT STREET
Address:	EAST MAIN STREET & SOUTH GRANT STREET
City,State,Zip:	STOCKTON, CA
Region:	STATE
Facility Status:	**Open - Inactive**
Status Date:	07/07/2015
Global Id:	SLT5S3083344
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Lead Agency Case Number:	Not reported
Latitude:	37.9542553282031

CHLORINATED SOLVENT CASE - CORNER OF EAST MAIN STREET AND SO (Continued) **S118154690**

Longitude:	-121.280644648224
Case Type:	Cleanup Program Site
Case Worker:	ZZZ
Local Agency:	Not reported
RB Case Number:	SLT5S308
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Other Chlorinated Hydrocarbons, Other Solvent or Non-Petroleum Hydrocarbon, Other Petroleum, Waste Oil / Motor / Hydraulic / Lubricating
Site History:	a fuel investigation for Valley Motors revealed PCE, TCE in groundwater that is coming from an upgradient source. PCE 625 ug/L. TCE 340 ug/L, trans 1,2-DCE 227 ug/L.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	CHLORINATED SOLVENT CASE - CORNER OF EAST MAIN STREET AND SOUTH GRANT STREET
Address:	EAST MAIN STREET & SOUTH GRANT STREET
City,State,Zip:	STOCKTON, CA
Site ID:	202961
CERS ID:	SLT5S3083344
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	zzz - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AB168 **CITY OF STOCKTON** **LUST** **S106486578**
NE **800 EAST MAIN STREET** **Cortese** **N/A**
1/4-1/2 **STOCKTON, CA 95202** **CERS**
0.488 mi.
2574 ft. **Site 3 of 3 in cluster AB**

Relative: Higher

Actual: 18 ft.

LUST:

Name:	CITY OF STOCKTON
Address:	800 EAST MAIN STREET
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T10000007010
Global Id:	T10000007010
Latitude:	37.95423
Longitude:	-121.28048
Status:	Completed - Case Closed
Status Date:	07/20/2017
Case Worker:	AMB
RB Case Number:	392000
Local Agency:	Not reported

CITY OF STOCKTON (Continued) **S106486578**

File Location: Regional Board
Local Case Number: Not reported
Potential Media Affect: Soil, Under Investigation
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: ABANDONED UST IN SIDEWALK WAS DISCOVERED DURING UST SITE INVESTIGATION AND CLEANUP OF ADJACENT PROPERTY. ADJACENT PROPERTY OWNER CLAIMED NO KNOWLEDGE OF UST AND COURT DECREE RELIEVED THEM OF RESPONSIBILITY. CITY OF STOCKTON HAS TAKEN RESPONSIBLITY FOR REMOVAL OF ABANDONED UST IN A LETTER DATED 10 MARCH 2014..

LUST:
Global Id: T10000007010
Contact Type: Regional Board Caseworker
Contact Name: ALAN M. BUEHLER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 Sun Center Dr
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: 9164644615

LUST:
Global Id: T10000007010
Action Type: RESPONSE
Date: 01/30/2016
Action: Tank Removal Report / UST Sampling Report

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 09/01/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 11/08/2013
Action: Staff Letter

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 12/14/2015
Action: Email Correspondence

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 04/03/2017
Action: Staff Letter

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 10/05/2015
Action: Staff Letter

Global Id: T10000007010
Action Type: ENFORCEMENT
Date: 01/26/2017
Action: Staff Letter

Global Id: T10000007010

CITY OF STOCKTON (Continued) **S106486578**

Action Type: ENFORCEMENT
Date: 07/20/2017
Action: Closure/No Further Action Letter

Global Id: T10000007010
Action Type: RESPONSE
Date: 08/06/2001
Action: Correspondence

Global Id: T10000007010
Action Type: RESPONSE
Date: 03/10/2014
Action: Correspondence - Regulator Responded

Global Id: T10000007010
Action Type: RESPONSE
Date: 11/30/2016
Action: Request for Closure - Regulator Responded

Global Id: T10000007010
Action Type: RESPONSE
Date: 02/14/2017
Action: Request for Closure - Regulator Responded

Global Id: T10000007010
Action Type: RESPONSE
Date: 11/30/2016
Action: Request for Closure - Regulator Responded

Global Id: T10000007010
Action Type: Other
Date: 08/06/2001
Action: Leak Reported

Global Id: T10000007010
Action Type: RESPONSE
Date: 03/06/2007
Action: Correspondence

Global Id: T10000007010
Action Type: RESPONSE
Date: 02/28/2007
Action: Correspondence

Global Id: T10000007010
Action Type: RESPONSE
Date: 09/29/2015
Action: Email Correspondence

LUST:
Global Id: T10000007010
Status: Open - Case Begin Date
Status Date: 08/06/2001

Global Id: T10000007010
Status: Open - Site Assessment
Status Date: 11/08/2013

CITY OF STOCKTON (Continued) **S106486578**

Global Id: T10000007010
Status: Open - Site Assessment
Status Date: 06/03/2015

Global Id: T10000007010
Status: Completed - Case Closed
Status Date: 07/20/2017

CORTESE:
Name: CITY OF STOCKTON
Address: 800 EAST MAIN STREET
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T10000007010
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

CERS:
Name: CITY OF STOCKTON
Address: 800 EAST MAIN STREET
City,State,Zip: STOCKTON, CA 95202
Site ID: 277032
CERS ID: T10000007010
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

169
North
1/4-1/2
0.490 mi.
2585 ft.

CITY OF STOCKTON REDEVELOPMENT AGENCY
216 CALIFORNIA
STOCKTON, CA 95202

LUST **S106716784**
Cortese **N/A**
Notify 65
CERS

Relative:
Lower

Actual:
16 ft.

LUST:

Name:	CITY OF STOCKTON REDEVELOPMENT AGENCY
Address:	216 CALIFORNIA
City,State,Zip:	STOCKTON, CA 95202
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607755189
Global Id:	T0607755189
Latitude:	37.9558634977304
Longitude:	-121.285023595245
Status:	Open - Site Assessment
Status Date:	04/22/2013
Case Worker:	VJF
RB Case Number:	391160
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply, Soil
Potential Contaminants of Concern:	Gasoline
Site History:	December 3, 2004- One underground storage tank (UST), located in the city of Stockton right-of-way under the west sidewalk, was removed. Soil samples were collected from beneath the tank. Analytical results of the soil reported petroleum hydrocarbon impact. January 2005- The tank pit area was excavated to try and dig out the contamination; they did not, deeper soil samples more highly impacted than the shallow ones. February 19, 2008- Soil boring SB-1 was advanced within the former tank pit to 50 ft. below surface grade (bsg). Analytical results yielded 590,000 micrograms per liter (a%g/L) of total petroleum hydrocarbons as diesel (TPH-d) in groundwater sampled at 34 ft. bsg. TPH-d was also detected in 4 soil samples collected within SB-1 between 20-48 ft. bsg; the highest concentration being 4,500 milligrams per kilogram (mg/kg) at 29.5 ft. bsg. (Report dated 3/24/2008) November 12 and 13, 2008- CPT borings were advanced up to 100 ft. bsg. CPT-1 (4 separate borings) yielded as high as 3,600 a%g/L TPH-d in groundwater sampled at 61 ft. bsg and yielded as high as 3,500 mg/kg TPH-d in soil sampled at 60 ft. bsg. CPT-2 (3 separate borings) yielded 5,800 a%g/L TPG-d in the sole groundwater sample taken from 41 ft. bsg and yielded as high as 4,600 mg/kg TPH-d in soil sampled at 35 ft. bsg. CPT-3 (one boring) has no available chemical analytical data. (Report dated 1/5/2009)

LUST:

Global Id:	T0607755189
Contact Type:	Regional Board Caseworker
Contact Name:	VERA FISCHER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	vera.fischer@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607755189

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Action Type: ENFORCEMENT
Date: 07/31/2009
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 08/21/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 10/29/2009
Action: Meeting

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 11/16/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 02/23/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 01/13/2010
Action: Meeting

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 06/02/2010
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/20/2014
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 08/24/2010
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 01/09/2015
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 11/15/2010

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/19/2017
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 11/09/2011
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 06/21/2016
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 02/09/2018
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/15/2018
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/24/2018
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/28/2019
Action: Staff Letter

Global Id: T0607755189
Action Type: RESPONSE
Date: 01/03/2018
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 12/22/2004
Action: Notice of Responsibility

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 01/31/2008
Action: Meeting

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 12/21/2004
Action: Notification - Proposition 65 - #04-071

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 12/21/2004
Action: Unauthorized Release Form

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 01/23/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 11/20/2007
Action: Meeting

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 09/25/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 04/30/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 11/02/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 01/10/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 08/31/2005
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 03/09/2005
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 02/19/2008
Action: Site Visit / Inspection / Sampling

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 06/21/2013
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Date: 01/21/2021
Action: Email Correspondence

Global Id: T0607755189
Action Type: Other
Date: 12/03/2004
Action: Leak Discovery

Global Id: T0607755189
Action Type: Other
Date: 12/21/2004
Action: Leak Reported

Global Id: T0607755189
Action Type: RESPONSE
Date: 03/30/2018
Action: Other Workplan - Regulator Responded

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 12/28/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: RESPONSE
Date: 12/05/2008
Action: Soil and Water Investigation Workplan

Global Id: T0607755189
Action Type: RESPONSE
Date: 03/05/2009
Action: Soil and Water Investigation Report

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 10/30/2008
Action: Staff Letter - #10/30/2008

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 08/03/2012
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/10/2012
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 06/28/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 09/05/2013
Action: File review

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Global Id: T0607755189
Action Type: REMEDIATION
Date: 01/26/2005
Action: Excavation

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 10/15/2008
Action: Staff Letter - #10/15/2008

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 02/19/2009
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/15/2009
Action: File review

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 03/11/2009
Action: Staff Letter - #03/11/2009

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 05/21/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 10/13/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 12/12/2014
Action: Staff Letter

Global Id: T0607755189
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

LUST:
Global Id: T0607755189
Status: Open - Case Begin Date
Status Date: 12/03/2004

Global Id: T0607755189
Status: Open - Site Assessment
Status Date: 02/19/2008

Global Id: T0607755189
Status: Open - Inactive
Status Date: 05/25/2010

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Global Id: T0607755189
Status: Open - Site Assessment
Status Date: 04/22/2013

LUST REG 5:
Name: CITY OF STOCKTON REDEVELOPMENT AGENCY
Address: 216 CALIFORNIA
City: STOCKTON
Region: 5
Status: Not reported
Case Number: 391160
Case Type: Soil only
Substance: MISC MVF
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: CITY OF STOCKTON REDEVELOPMENT AGENCY
Address: 216 CALIFORNIA
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607755189
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - SITE ASSESSMENT
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

NOTIFY 65:
Name: CITY OF STOCKTON REDEVELOPMENT AGENCY
Address: 216 CALIFORNIA
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 12/21/2004
Incident Description: Not reported

CITY OF STOCKTON REDEVELOPMENT AGENCY (Continued) **S106716784**

Global ID: Not reported
Status: Not reported

Name: CITY OF STOCKTON REDEVELOPMENT AGENCY
Address: 216 CALIFORNIA
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: CITY OF STOCKTON REDEVELOPMENT AGENCY
Address: 216 CALIFORNIA
City,State,Zip: STOCKTON, CA 95202
Site ID: 221327
CERS ID: T0607755189
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

---

170 North 1/2-1 0.522 mi. 2756 ft. **SUTTER OFFICE CENTER** **LUST S102438274**
242 SUTTER ST **Cortese N/A**
STOCKTON, CA 95902 **HIST CORTESE**
Notify 65
CERS

Relative: Lower
Actual: 16 ft.

LUST:
Name: SUTTER OFFICE CENTER
Address: 242 SUTTER ST
City,State,Zip: STOCKTON, CA 95902
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700732
Global Id: T0607700732
Latitude: 37.9563199805419
Longitude: -121.285613150124
Status: Completed - Case Closed
Status Date: 02/24/2016
Case Worker: EMC
RB Case Number: 390910
Local Agency: Not reported
File Location: Local Agency

SUTTER OFFICE CENTER (Continued) **S102438274**

Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Site is located on the southwest corner of California Street and East Miner Avenue in Stockton, in the parking lot for the building at 242 Sutter Street. The location is the site of a former Chevron facility; at least two generations of tanks are documented at the site, but there are no records of the tank removals. Site investigation activites were initiated by the current property owner, Sutter Office Center, in May 2000 with the installation of geoprobe soil borings. Soil and grab groundwater samples were collected for analysis and confirmed there are petroleum hydrocarbons in the subsurface soil and groundwater. Groundwater monitoring wells were first installed in 2001; CPT borings in 2003; additional groundwater monitoring wells in 2005, 2007 and 2009; additional borings in 2007. Chevron was named a responsible party and took over the site investigation in 2006.

LUST:
Global Id: T0607700732
Contact Type: Regional Board Caseworker
Contact Name: EMILY CUSHMAN
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 Sun Center Drive #200
City: RANCHO CORDOVA
Email: emily.cushman@waterboards.ca.gov
Phone Number: 9164644696

LUST:
Global Id: T0607700732
Action Type: RESPONSE
Date: 07/10/2000
Action: Risk Assessment Report

Global Id: T0607700732
Action Type: RESPONSE
Date: 12/05/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 07/11/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 03/10/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/08/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 08/13/2009
Action: File review

SUTTER OFFICE CENTER (Continued) **S102438274**

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 12/16/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 11/06/2009
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 12/07/2009
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 01/13/2010
Action: Meeting

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 04/26/2010
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 09/27/2011
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/21/2010
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/08/2014
Action: Staff Letter

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 06/25/2014
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT

SUTTER OFFICE CENTER (Continued) **S102438274**

Date: 01/13/2016
Action: Email Correspondence

Global Id: T0607700732
Action Type: RESPONSE
Date: 07/31/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 09/19/2000
Action: Risk Assessment Report

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 12/23/2010
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 06/20/2011
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 02/24/2016
Action: Closure/No Further Action Letter

Global Id: T0607700732
Action Type: RESPONSE
Date: 04/24/2013
Action: Request for Closure - Regulator Responded

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 01/25/1996
Action: Notification - Proposition 65

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/01/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/13/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 03/03/2011
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/09/2015
Action: Email Correspondence

SUTTER OFFICE CENTER (Continued) **S102438274**

Global Id: T0607700732
Action Type: RESPONSE
Date: 05/27/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 11/21/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 09/17/2014
Action: Well Destruction Workplan - Regulator Responded

Global Id: T0607700732
Action Type: RESPONSE
Date: 01/26/2016
Action: Well Destruction Report - Regulator Responded

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 04/29/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700732
Action Type: Other
Date: 01/25/1996
Action: Leak Discovery

Global Id: T0607700732
Action Type: Other
Date: 01/25/1996
Action: Leak Reported

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/29/2013
Action: Notification - Preclosure

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/01/2013
Action: Notification - Fee Title Owners Notice

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/28/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 09/10/2013
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT

SUTTER OFFICE CENTER (Continued) **S102438274**

Date: 10/07/2013
Action: Notification - Public Participation Document

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 05/25/2012
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 02/19/2013
Action: File review

Global Id: T0607700732
Action Type: RESPONSE
Date: 05/25/2009
Action: Well Installation Report

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 07/31/2013
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/01/2013
Action: LOP Case Closure Summary to RB

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 11/01/2012
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 08/12/2013
Action: File review

Global Id: T0607700732
Action Type: RESPONSE
Date: 02/02/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 02/18/2002
Action: Risk Assessment Report

Global Id: T0607700732
Action Type: RESPONSE
Date: 10/25/2002
Action: Site Assessment Report

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 11/05/2008
Action: Staff Letter - #11/05/2008

SUTTER OFFICE CENTER (Continued) **S102438274**

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 09/29/2008
Action: Technical Correspondence / Assistance / Other - #09/29/2008

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 01/26/2009
Action: Site Visit / Inspection / Sampling

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 05/20/2009
Action: File review

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 08/21/2013
Action: File Review - Closure

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 08/19/2013
Action: File Review - Closure

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 11/13/2012
Action: File review

Global Id: T0607700732
Action Type: RESPONSE
Date: 08/10/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE
Date: 12/29/1999
Action: Risk Assessment Report

Global Id: T0607700732
Action Type: RESPONSE
Date: 01/28/2005
Action: Well Installation Report

Global Id: T0607700732
Action Type: RESPONSE
Date: 10/23/2000
Action: Site Assessment Report

Global Id: T0607700732
Action Type: RESPONSE
Date: 10/21/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700732
Action Type: RESPONSE

SUTTER OFFICE CENTER (Continued) **S102438274**

Date: 10/17/2003
Action: Other Report / Document

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 03/27/2006
Action: Notice of Responsibility

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 10/05/2007
Action: Technical Correspondence / Assistance / Other - #10/05/2007

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 02/27/1997
Action: Notice of Responsibility

Global Id: T0607700732
Action Type: ENFORCEMENT
Date: 12/24/2007
Action: Technical Correspondence / Assistance / Other - #12/24/2007

LUST:
Global Id: T0607700732
Status: Open - Case Begin Date
Status Date: 01/25/1996

Global Id: T0607700732
Status: Open - Site Assessment
Status Date: 05/02/2000

Global Id: T0607700732
Status: Open - Site Assessment
Status Date: 01/25/2007

Global Id: T0607700732
Status: Open - Eligible for Closure
Status Date: 06/25/2014

Global Id: T0607700732
Status: Completed - Case Closed
Status Date: 02/24/2016

LUST REG 5:
Name: SUTTER OFFICE CENTER
Address: 242 SUTTER ST
City: STOCKTON
Region: 5
Status: Not reported
Case Number: 390910
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local

SUTTER OFFICE CENTER (Continued) **S102438274**

Program: LUST
MTBE Code: 2

CORTESE:

Name:	SUTTER OFFICE CENTER
Address:	242 SUTTER ST
City,State,Zip:	STOCKTON, CA 95902
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700732
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	SUTTER OFFICE CENTER
edr_fadd1:	242 SUTTER
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390910

NOTIFY 65:

Name:	SUTTER OFFICE CENTER
Address:	242 SUTTER ST
City,State,Zip:	STOCKTON, CA 95902
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	01/25/1996
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Name:	SUTTER OFFICE CENTER
Address:	242 SUTTER ST
City,State,Zip:	STOCKTON, CA 95902
Date Reported:	Not reported

SUTTER OFFICE CENTER (Continued) **S102438274**

Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: SUTTER OFFICE CENTER
Address: 242 SUTTER ST
City,State,Zip: STOCKTON, CA 95902
Site ID: 231596
CERS ID: T0607700732
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: EMILY CUSHMAN - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Drive #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644696

---

171 NNW 1/2-1 0.534 mi. 2821 ft. **CANCUN RESTAURANT** **LUST S108996997**
135 MINER **Cortese N/A**
STOCKTON, CA 95202 **Notify 65**
CERS

Relative: Lower
Actual: 14 ft.

LUST:
Name: CANCUN RESTAURANT
Address: 135 MINER
City,State,Zip: STOCKTON, CA 95202
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607715874
Global Id: T0607715874
Latitude: 37.956249
Longitude: -121.289682
Status: Open - Site Assessment
Status Date: 02/12/2008
Case Worker: VJF
RB Case Number: 391173
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply, Soil, Soil Vapor
Potential Contaminants of Concern: Gasoline
Site History: January 2008- One underground storage tank was removed from beneath the sidewalk (City of Stockton right-of-way) near the corner of Minor Street and Hunter. Soil samples were collected; laboratory analytical results reported petroleum hydrocarbon impact to the samples. June

CANCUN RESTAURANT (Continued) **S108996997**

2008- A site investigation began with the installation of four geoprobe soil borings; soil and grab groundwater samples were collected; laboratory analytical results confirmed the petroleum hydrocarbon impact to both soil and groundwater. July through August 2010- Five monitoring wells were installed (MW-1A, MW-1B, MW-2B, MW-3B, MW-4B). December 2013 through January 2014- In-Situ Chemical Oxidation (ISCO) pilot study was conducted.

LUST:
Global Id: T0607715874
Contact Type: Regional Board Caseworker
Contact Name: VERA FISCHER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: vera.fischer@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/28/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 01/21/2010
Action: Clean Up Fund - Letter to RP

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/23/2014
Action: Complaint

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 04/01/2015
Action: Notice of Responsibility

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 04/06/2015
Action: Staff Letter

Global Id: T0607715874
Action Type: RESPONSE
Date: 08/01/2016
Action: Monitoring Report - Quarterly

Global Id: T0607715874
Action Type: RESPONSE
Date: 09/01/2016
Action: Pilot Study/ Treatability Report

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/03/2010

CANCUN RESTAURANT (Continued) **S108996997**

Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 11/30/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 06/30/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 06/15/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 01/21/2015
Action: Verbal Communication

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 10/28/2014
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 05/12/2014
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/13/2008
Action: Notice of Responsibility

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/04/2008
Action: Notification - Proposition 65 - #08-019

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 10/08/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/24/2014
Action: Complaint

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/19/2016
Action: Staff Letter

CANCUN RESTAURANT (Continued) **S108996997**

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/29/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: RESPONSE
Date: 05/31/2013
Action: Pilot Study / Treatability Workplan - Regulator Responded

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/12/2008
Action: Unauthorized Release Form

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 04/27/2011
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/30/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 12/21/2016
Action: Staff Letter

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/21/2017
Action: Email Correspondence

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 06/19/2017
Action: Staff Letter

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/31/2018
Action: Staff Letter

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 05/02/2019
Action: Staff Letter

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 10/09/2019
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607715874
Action Type: RESPONSE

CANCUN RESTAURANT (Continued) **S108996997**

Date: 11/01/2016
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/03/2012
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/05/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/19/2016
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607715874
Action Type: Other
Date: 02/04/2008
Action: Leak Discovery

Global Id: T0607715874
Action Type: Other
Date: 01/17/2008
Action: Leak Stopped

Global Id: T0607715874
Action Type: Other
Date: 02/04/2008
Action: Leak Reported

Global Id: T0607715874
Action Type: RESPONSE
Date: 03/12/2019
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 06/04/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 02/26/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/19/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 04/17/2008
Action: Technical Correspondence / Assistance / Other - #04/17/2008

CANCUN RESTAURANT (Continued) **S108996997**

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 04/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 10/22/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/19/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 03/04/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/09/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/02/2013
Action: File review

Global Id: T0607715874
Action Type: REMEDIATION
Date: 01/27/2014
Action: In Situ Biological Treatment

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 10/14/2008
Action: Technical Correspondence / Assistance / Other - #10/14/2008

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 08/01/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/19/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 09/27/2012
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT

CANCUN RESTAURANT (Continued) **S108996997**

Date: 12/28/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 11/14/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 11/19/2013
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 12/24/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: REMEDIATION
Date: 12/12/2013
Action: In Situ Biological Treatment

Global Id: T0607715874
Action Type: REMEDIATION
Date: 12/24/2013
Action: In Situ Biological Treatment

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 12/10/2008
Action: Staff Letter - #12/10/2008

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 05/13/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 05/13/2009
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/31/2009
Action: File review

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 12/24/2013
Action: Site Visit / Inspection / Sampling

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 01/23/2015
Action: Site Visit / Inspection / Sampling

CANCUN RESTAURANT (Continued) **S108996997**

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607715874
Action Type: ENFORCEMENT
Date: 07/14/2014
Action: Site Visit / Inspection / Sampling

LUST:
Global Id: T0607715874
Status: Open - Case Begin Date
Status Date: 01/17/2008

Global Id: T0607715874
Status: Open - Site Assessment
Status Date: 02/12/2008

LUST REG 5:
Name: CANCUN RESTAURANT
Address: 135 MINER
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 391173
Case Type: Soil only
Substance: MISC MVF
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

CORTESE:
Name: CANCUN RESTAURANT
Address: 135 MINER
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607715874
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - SITE ASSESSMENT
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported

CANCUN RESTAURANT (Continued) **S108996997**

Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

NOTIFY 65:
Name: CANCUN RESTAURANT
Address: 135 MINER
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 02/04/2008
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: CANCUN RESTAURANT
Address: 135 MINER
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: CANCUN RESTAURANT
Address: 135 MINER
City,State,Zip: STOCKTON, CA 95202
Site ID: 253833
CERS ID: T0607715874
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

172 NNE 1/2-1 0.562 mi. 2970 ft. — **COMMUNITY MEDICAL CENTERS INC PHARMACY**, **701 E CHANNEL ST**, **STOCKTON, CA 95202** — **ENVIROSTOR HAZNET HWTS** — **S118756913 N/A**

Relative: Higher

Actual: 18 ft.

ENVIROSTOR:

Name:	CHANNEL STREET CLINIC
Address:	701 E. CHANNEL STREET
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	39800001
Status:	No Action Required
Status Date:	07/07/1994
Site Code:	100457
Site Type:	Calmortgage
Site Type Detailed:	Calmortgage
Acres:	0
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	William Beckman
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	CalMortgage
Latitude:	37.95638
Longitude:	-121.2820
APN:	NONE SPECIFIED
Past Use:	NONE
Potential COC:	NONE SPECIFIED No Contaminants found
Confirmed COC:	No Contaminants found
Potential Description:	NMA
Alias Name:	100457
Alias Type:	Project Code (Site Code)
Alias Name:	39800001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	07/07/1994
Comments:	Pursuant to the MOU, DTSC has reviewed a Phase I Environmental assessment report and a preliminary asbestos survey for the Channel Street Clinic. The property, owned by the Agricultural Workers' Health Centers, Inc. (AWHC), contains two vacant connected buildings which previously housed a children's day care center. AWHC is proposing to remodel the buildings to accommodate the relocation of thier current Stockton health clinic. A Supplemental Phase I Environmental Assessment Report was prepared by DTSC and concluded that no action was needed for this property, there is no contamination on the property.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported

COMMUNITY MEDICAL CENTERS INC PHARMACY (Continued) **S118756913**

Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HAZNET:
Name: COMMUNITY MEDICAL CENTERS INC PHARMACY
Address: 701 E CHANNEL ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95201
Contact: DAVID LOPEZ
Telephone: 2093732887
Mailing Name: Not reported
Mailing Address: PO BOX 779

Year: 2018
Gepaid: CAL000410993
TSD EPA ID: NVD980895338
CA Waste Code: 311 - Pharmaceutical waste
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.02250

Year: 2015
Gepaid: CAL000410993
TSD EPA ID: CAD980884183
CA Waste Code: 311 - Pharmaceutical waste
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0275

Additional Info:
Year: 2015
Gen EPA ID: CAL000410993

Shipment Date: 20151014
Creation Date: 1/5/2016 22:35:46
Receipt Date: 20151014
Manifest ID: 007425624FLE
Trans EPA ID: MNS000110924
Trans Name: STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD980884183
Trans Name: GENERAL ENVIRONMENTAL MGT LLC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 311 - Pharmaceutical waste
RCRA Code: D024
Meth Code: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons: 0.0275
Waste Quantity: 55

COMMUNITY MEDICAL CENTERS INC PHARMACY (Continued) **S118756913**

Quantity Unit: P
Additional Code 1: D022
Additional Code 2: D007
Additional Code 3: D005
Additional Code 4: D001
Additional Code 5: Not reported

HWTS:
Name: COMMUNITY MEDICAL CENTERS INC PHARMACY
Address: 701 E CHANNEL ST
Address 2: Not reported
City,State,Zip: STOCKTON, CA 95202
EPA ID: CAL000410993
Inactive Date: Not reported
Create Date: 10/07/2015
Last Act Date: 10/26/2020
Mailing Name: Not reported
Mailing Address: PO BOX 779
Mailing Address 2: Not reported
Mailing City,State,Zip: STOCKTON, CA 95201
Owner Name: COMMUNITY MEDICAL CENTERS INC
Owner Address: 7210 MURRAY DR
Owner Address 2: Not reported
Owner City,State,Zip: STOCKTON, CA 95210
Contact Name: DAVID LOPEZ
Contact Address: 7210 MURRAY DR
Contact Address 2: Not reported
City,State,Zip: STOCKTON, CA 95210

NAICS:
EPA ID: CAL000410993
Create Date: 2015-10-07 14:53:33.770
NAICS Code: 42221
NAICS Description: Drugs and Druggists Sundries Wholesalers
Issued EPA ID Date: 2015-10-07 14:53:33.77000
Inactive Date: Not reported
Facility Name: COMMUNITY MEDICAL CENTERS INC PHARMACY
Facility Address: 701 E CHANNEL ST
Facility Address 2: Not reported
Facility City: STOCKTON
Facility County: Not reported
Facility State: CA
Facility Zip: 95202

---

173 **WORK NET PROJECT, STOCKTON** **ENVIROSTOR** **S106568315**
WNW **40 LINCOLN STREET (BOUND BY LINCOLN ST** **VCP** **N/A**
1/2-1 **STOCKTON, CA 95202**
0.583 mi.
3077 ft.

Relative:
Lower

Actual:
12 ft.

ENVIROSTOR:
Name: WORK NET PROJECT, STOCKTON
Address: 40 LINCOLN STREET (BOUND BY LINCOLN ST
City,State,Zip: STOCKTON, CA 95202
Facility ID: 39240018
Status: Refer: RWQCB
Status Date: 07/10/2007

WORK NET PROJECT, STOCKTON (Continued) **S106568315**

Site Code: 101727
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 2.4
NPL: NO
Regulatory Agencies: SMBRP, RWQCB 5S - Central Valley
Lead Agency: RWQCB 5S - Central Valley
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup Sacramento
Assembly: 21
Senate: 05
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.95103
Longitude: -121.2969
APN: NONE SPECIFIED
Past Use: MANUFACTURING - LUMBER/WOOD PRODUCTS, RAILROAD RIGHT OF WAY
Potential COC: * CONTAMINATED SOIL Lead TPH-diesel TPH-MOTOR OIL
Confirmed COC: TPH-diesel Lead * CONTAMINATED SOIL TPH-MOTOR OIL
Potential Description: OTH, SOIL
Alias Name: STOCKTON WORK NET PROJECT
Alias Type: Alternate Name
Alias Name: 110033620954
Alias Type: EPA (FRS #)
Alias Name: 101727
Alias Type: Project Code (Site Code)
Alias Name: 39240018
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 09/02/2004
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 04/24/2007
Comments: DTSC 30 day notice of VCA Termination letter issued on 4/24/2007. At end of 30 days a DTSC close-out memo to accounting will be submitted.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 10/01/2004
Comments: ORDER/VCA -- VOLUNTARY CLEANUP AGREEMENT (VCA). THE VCA SIGNED BY THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL ON OCTOBER 1, 2004.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 06/07/2007
Comments: DTSC VCA Close-out memo dated 6/7/2007 sent to Accounting.

WORK NET PROJECT, STOCKTON (Continued) **S106568315**

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	WORK NET PROJECT, STOCKTON
Address:	40 LINCOLN STREET (BOUND BY LINCOLN ST
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	39240018
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	2.4
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, RWQCB 5S - Central Valley
Lead Agency:	RWQCB 5S - Central Valley
Lead Agency Description:	RWQCB 5S - Central Valley
Project Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Site Code:	101727
Assembly:	21
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: RWQCB
Status Date:	07/10/2007
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.95103 / -121.2969
APN:	NONE SPECIFIED
Past Use:	MANUFACTURING - LUMBER/WOOD PRODUCTS, RAILROAD RIGHT OF WAY
Potential COC:	10097, 30013, 30024, 3002502
Confirmed COC:	30024,30013,10097,3002502
Potential Description:	OTH, SOIL
Alias Name:	STOCKTON WORK NET PROJECT
Alias Type:	Alternate Name
Alias Name:	110033620954
Alias Type:	EPA (FRS #)
Alias Name:	101727
Alias Type:	Project Code (Site Code)
Alias Name:	39240018
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	09/02/2004
Comments:	Not reported

Completed Area Name:	PROJECT WIDE

WORK NET PROJECT, STOCKTON (Continued) **S106568315**

Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	04/24/2007
Comments:	DTSC 30 day notice of VCA Termination letter issued on 4/24/2007. At end of 30 days a DTSC close-out memo to accounting will be submitted.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	10/01/2004
Comments:	ORDER/VCA -- VOLUNTARY CLEANUP AGREEMENT (VCA). THE VCA SIGNED BY THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL ON OCTOBER 1, 2004.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	06/07/2007
Comments:	DTSC VCA Close-out memo dated 6/7/2007 sent to Accounting.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

174
ESE
1/2-1
0.596 mi.
3146 ft.

OVERMYER MACHINE WORKS
1019 S AURORA
STOCKTON, CA 95206

ENVIROSTOR **S100190160**
N/A

Relative:
Higher

Actual:
18 ft.

ENVIROSTOR:

Name:	OVERMYER MACHINE WORKS
Address:	1019 S AURORA
City,State,Zip:	STOCKTON, CA 95206
Facility ID:	39350019
Status:	Refer: Other Agency
Status Date:	11/16/1994
Site Code:	Not reported
Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported

OVERMYER MACHINE WORKS (Continued) **S100190160**

Latitude: 37.94409
Longitude: -121.2768
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: AMS (GARAGE)
Alias Type: Alternate Name
Alias Name: 39350019
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 09/15/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 05/26/1982
Comments: Facility identified from industrial index.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

175 **CHILDREN'S MUSEUM OF STOCKTON** **ENVIROSTOR** **S108054486**
WNW **402 W. WEBER AVENUE** **VCP** **N/A**
1/2-1 **STOCKTON, CA 95203**
0.597 mi.
3152 ft.

Relative:
Lower

Actual:
12 ft.

ENVIROSTOR:
Name: CHILDREN'S MUSEUM OF STOCKTON
Address: 402 W. WEBER AVENUE
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60000351
Status: Inactive - Needs Evaluation
Status Date: 10/04/2018
Site Code: 101797
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 1.41
NPL: NO
Regulatory Agencies: SMBRP, RWQCB 5F - Central Valley, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin

CHILDREN'S MUSEUM OF STOCKTON (Continued) **S108054486**

Assembly: 21, 13
Senate: 05
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.95213
Longitude: -121.2974
APN: NONE SPECIFIED
Past Use: RAILROAD RIGHT OF WAY
Potential COC: Lead TPH-diesel TPH-gas
Confirmed COC: TPH-diesel TPH-gas Lead
Potential Description: OTH, SOIL
Alias Name: 110033620464
Alias Type: EPA (FRS #)
Alias Name: SL0607727524
Alias Type: GeoTracker Global ID
Alias Name: T10000001127
Alias Type: GeoTracker Global ID
Alias Name: T10000001128
Alias Type: GeoTracker Global ID
Alias Name: 101797
Alias Type: Project Code (Site Code)
Alias Name: 60000351
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 09/07/2006
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: CHILDREN'S MUSEUM OF STOCKTON
Address: 402 W. WEBER AVENUE
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60000351
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 1.41
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP, RWQCB 5F - Central Valley, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Not reported

CHILDREN'S MUSEUM OF STOCKTON (Continued) **S108054486**

Supervisor:	Steven Becker
Division Branch:	Cleanup San Joaquin
Site Code:	101797
Assembly:	21, 13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Inactive - Needs Evaluation
Status Date:	10/04/2018
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.95213 / -121.2974
APN:	NONE SPECIFIED
Past Use:	RAILROAD RIGHT OF WAY
Potential COC:	30013, 30024, 30025
Confirmed COC:	30024,30025,30013
Potential Description:	OTH, SOIL
Alias Name:	110033620464
Alias Type:	EPA (FRS #)
Alias Name:	SL0607727524
Alias Type:	GeoTracker Global ID
Alias Name:	T10000001127
Alias Type:	GeoTracker Global ID
Alias Name:	T10000001128
Alias Type:	GeoTracker Global ID
Alias Name:	101797
Alias Type:	Project Code (Site Code)
Alias Name:	60000351
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	09/07/2006
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

176
WSW
1/2-1
0.647 mi.
3417 ft.

Relative: Lower

Actual: 12 ft.

ACME-STOCKTON GALVANIZING WORKS
540 WEST SCOTTS AVENUE
STOCKTON, CA 95203

RESPONSE **S100833160**
ENVIROSTOR **N/A**
CPS-SLIC
HIST Cal-Sites
DEED
CA BOND EXP. PLAN
CERS

RESPONSE:

Name:	ACME-STOCKTON GALVANIZING WORKS
Address:	540 WEST SCOTTS AVENUE
City,State,Zip:	STOCKTON, CA 95203

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Facility ID:	39340018
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	2.8
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Kenneth Gath
Supervisor:	Fernando A. Amador
Division Branch:	Cleanup Sacramento
Site Code:	100001
Site Mgmt. Req.:	ASP, DAY, ELD, HOS, LUC
Assembly:	13
Senate:	05
Special Program Status:	Not reported
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	01/29/2015
Restricted Use:	YES
Funding:	Responsible Party
Latitude:	37.94369
Longitude:	-121.2967
APN:	147-040-48, 14704048
Past Use:	METAL PLATING - OTHER
Potential COC :	* ACID SOLUTION 2>PH WITH METALS Lead Zinc
Confirmed COC:	Lead * ACID SOLUTION 2>PH WITH METALS Zinc
Potential Description:	SOIL
Alias Name:	ACME GALVANIZING, STOCKTON
Alias Type:	Alternate Name
Alias Name:	147-040-48
Alias Type:	APN
Alias Name:	14704048
Alias Type:	APN
Alias Name:	110033613089
Alias Type:	EPA (FRS #)
Alias Name:	SLT5S0283069
Alias Type:	GeoTracker Global ID
Alias Name:	P12106
Alias Type:	PCode
Alias Name:	100001
Alias Type:	Project Code (Site Code)
Alias Name:	39340018
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Public Participation Plan / Community Relations Plan
Completed Date:	03/30/1989
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	06/30/1987
Comments:	Preliminary Assessment Done: Recommend Site Inspection -- onsite contamination is documented.
Completed Area Name:	PROJECT WIDE

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/09/1987
Comments: Site Screening Done: Mitre Model required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/08/2007
Comments: Jesus Sotelo performed an inspection on the property and a report was produced and sent to all parties. These inspections are anticipated to be performed by the present property owner and sent to DTSC. DTSC will need to remind the owner at the beginning of every year. Five of these inspections would constitute a five year review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 04/29/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 06/10/2010
Comments: Reviewed self-inspection form. No deficiencies

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 03/20/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/20/2015
Comments: DTSC has accepted the submitted Inspection Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/01/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 08/17/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/10/2017
Comments: LUC Inspection Report received and accepted

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 10/14/1992
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 01/27/1999
Comments: 5YEAR -- A FIVE YEAR REVIEW AND RE-EVALUATION HAS BEEN COM- PLETED. SITE CONTAMINANTS (LEAD AND ZINC) REMAIN STABILIZED UNDER AN ASPHALT CAP WITH NO CONTAMINANT MIGRATION DETECTED BELOW THE STABILIZED MATERIAL. DUE TO DETERIORATION, THE ASPHALT CAP REQUIRED REPAIR AND THREE GROUNDWATER MONITORING WELLS REQUIRED DESTRUCTION. THESE REPAIR ACTIVITIES HAVE BEEN COMPLETED UNDER DTSC OVERSIGHT AS A FOLOWUP TO THE 5 YEAR REVIEW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/26/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 06/30/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 03/31/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 08/17/1989
Comments: Restriction related to Area A described on attached map. Use shall not be for residences, hospitals, schools for persons under age 21, day-care centers or permanently occupied human habitation, including hotels or motels which are used as a permanent residence by employees. No excavation and removal off-site of any soils from underneath the overlying asphalt cap. No use of the property shall be allowed that may disturn the integrity of the final cap.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 12/26/1990
Comments: The Enforceable Agreement is for Operation and Maintenance of the Cap. Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Document Type: Certification
Completed Date: 01/30/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 01/25/1991
Comments: Restricted land use prohibitiing residences, hospitals, schools for persons under age 21, day-care center or permenantly occupied human habitation, including hotels or motels which are used as a permanent residence by employees. Restriction also to not allow activities that may disturb the integraity of the final asphalt and/or concrete cap over the stabilized soil that has been redeposited into the ground in the area defined and delineated by the southern on/half portion of the building located on the property .

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date: 11/30/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 03/20/1982
Comments: Facility identified from Industrial Index.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/19/2009
Comments: Received LUC self-Inspection of Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 06/26/2003
Comments: Found old inspection report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/14/2011
Comments: Received inspection report from RP

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/06/2010
Comments: Letter sent asking for payment on outstanding balence.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/11/2013

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/06/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2020
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: ACME-STOCKTON GALVANIZING WORKS
Address: 540 WEST SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95203
Facility ID: 39340018
Status: Certified O&M - Land Use Restrictions Only
Status Date: 01/29/2015
Site Code: 100001
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 2.8
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Kenneth Gath
Supervisor: Fernando A. Amador
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: YES
Site Mgmt Req: ASP, DAY, ELD, HOS, LUC
Funding: Responsible Party
Latitude: 37.94369
Longitude: -121.2967
APN: 147-040-48, 14704048
Past Use: METAL PLATING - OTHER
Potential COC: * ACID SOLUTION 2>PH WITH METALS Lead Zinc
Confirmed COC: Lead * ACID SOLUTION 2>PH WITH METALS Zinc
Potential Description: SOIL
Alias Name: ACME GALVANIZING, STOCKTON
Alias Type: Alternate Name
Alias Name: 147-040-48

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Alias Type: APN
Alias Name: 14704048
Alias Type: APN
Alias Name: 110033613089
Alias Type: EPA (FRS #)
Alias Name: SLT5S0283069
Alias Type: GeoTracker Global ID
Alias Name: P12106
Alias Type: PCode
Alias Name: 100001
Alias Type: Project Code (Site Code)
Alias Name: 39340018
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Participation Plan / Community Relations Plan
Completed Date: 03/30/1989
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 06/30/1987
Comments: Preliminary Assessment Done: Recommend Site Inspection -- onsite contamination is documented.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/09/1987
Comments: Site Screening Done: Mitre Model required.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 05/08/2007
Comments: Jesus Sotelo performed an inspection on the property and a report was produced and sent to all parties. These inspections are anticipated to be performed by the present property owner and sent to DTSC. DTSC will need to remind the owner at the beginning of every year. Five of these inspections would constitute a five year review.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 04/29/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 06/10/2010
Comments: Reviewed self-inspection form. No deficiencies

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Document Type: 5 Year Review Reports
Completed Date: 03/20/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/20/2015
Comments: DTSC has accepted the submitted Inspection Report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/01/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 08/17/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/10/2017
Comments: LUC Inspection Report received and accepted

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 10/14/1992
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 01/27/1999
Comments: 5YEAR -- A FIVE YEAR REVIEW AND RE-EVALUATION HAS BEEN COM- PLETED. SITE CONTAMINANTS (LEAD AND ZINC) REMAIN STABILIZED UNDER AN ASPHALT CAP WITH NO CONTAMINANT MIGRATION DETECTED BELOW THE STABILIZED MATERIAL. DUE TO DETERIORATION, THE ASPHALT CAP REQUIRED REPAIR AND THREE GROUNDWATER MONITORING WELLS REQUIRED DESTRUCTION. THESE REPAIR ACTIVITIES HAVE BEEN COMPLETED UNDER DTSC OVERSIGHT AS A FOLOWUP TO THE 5 YEAR REVIEW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/26/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 06/30/1990
Comments: Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 03/31/1990
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 08/17/1989
Comments: Restriction related to Area A described on attached map. Use shall not be for residences, hospitals, schools for persons under age 21, day-care centers or permanently occupied human habitation, including hotels or motels which are used as a permanent residence by employees. No excavation and removal off-site of any soils from underneath the overlying asphalt cap. No use of the property shall be allowed that may disturn the integrity of the final cap.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 12/26/1990
Comments: The Enforceable Agreement is for Operation and Maintenance of the Cap.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/30/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 01/25/1991
Comments: Restricted land use prohibitiing residences, hospitals, schools for persons under age 21, day-care center or permenantly occupied human habitation, including hotels or motels which are used as a permanent residence by employees. Restriction also to not allow activities that may disturb the integraity of the final asphalt and/or concrete cap over the stabilized soil that has been redeposited into the ground in the area defined and delineated by the southern on/half portion of the building located on the property .

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date: 11/30/1987
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 03/20/1982
Comments: Facility identified from Industrial Index.

Completed Area Name: PROJECT WIDE

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/19/2009
Comments: Received LUC self-Inspection of Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 06/26/2003
Comments: Found old inspection report

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/14/2011
Comments: Received inspection report from RP

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/06/2010
Comments: Letter sent asking for payment on outstanding balence.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 04/11/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction - Site Inspection/Visit
Completed Date: 03/06/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2020
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

CPS-SLIC:
Name: ACME GALVANIZING
Address: 540 WEST SCOTTS
City,State,Zip: STOCKTON, CA
Region: STATE
Facility Status: **Open - Inactive**

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Status Date:	04/04/1992
Global Id:	SLT5S0283069
Lead Agency:	DEPARTMENT OF TOXIC SUBSTANCES CONTROL
Lead Agency Case Number:	39340018
Latitude:	37.9437726781745
Longitude:	-121.296301511917
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	SLT5S028
File Location:	DTSC
Potential Media Affected:	Under Investigation
Potential Contaminants of Concern:	Other Metal
Site History:	ACME Galvanizing Co., Inc. operated at the site from 1968 to 1982 producing galvanized metal parts. Two know spills of hazardous materials occurred during operations. The site is located within an area marked by light/medium industry and residential dwelling. located within three blocks west of the site is Hazelton School. Washington School and Edison High School are within one mile radius. The area features numerous schools within a three mile radius. Stockton State Hospital is located one and one half miles northeast of the site, The site is flanked on the west by Interstate 5.

Click here to access the California GeoTracker records for this facility:

Calsite:

Name:	ACME-STOCKTON GALVANIZING WORKS
Address:	540 WEST SCOTTS AVENUE
City:	STOCKTON
Region:	SACRAMENTO
Facility ID:	39340018
Facility Type:	RP
Type:	RESPONSIBLE PARTY
Branch:	CC
Branch Name:	CENTRAL CALIFORNIA
File Name:	Not reported
State Senate District:	01301991
Status:	CERTIFIED OPERATION AND MAINTENANCE, ALL PLANNED ACTIVITIES IMPLEMENTED, REMEDIATION CONTINUES
Status Name:	CERTIFIED / OPERATION & MAINTENANCE
Lead Agency:	DEPT OF TOXIC SUBSTANCES CONTROL
NPL:	Not Listed
SIC Code:	34
SIC Name:	MANU - FABRICATED METAL PRODUCTS
Access:	Uncontrolled
Cortese:	Not reported
Hazardous Ranking Score:	Not reported
Date Site Hazard Ranked:	Not reported
Groundwater Contamination:	Unknown
Staff Member Responsible for Site:	FAMADOR
Supervisor Responsible for Site:	Not reported
Region Water Control Board:	CV
Region Water Control Board Name:	CENTRAL VALLEY
Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

State Assembly District Code:	17
State Senate District Code:	05
Facility ID:	39340018
Activity:	DISC
Activity Name:	DISCOVERY
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03201982
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	SS
Activity Name:	SITE SCREENING
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	02091987
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	ORDER
Activity Name:	I/SE, IORSE, FFA, FFSRA, VCA, EA
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Comments Date:	11301987
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	PPP
Activity Name:	PUBLIC PARTICIPATION PLAN
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03301989
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	RIFS
Activity Name:	REMEDIAL INVESTIGATION / FEASIBILITY STUDY
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	03311990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	DES
Activity Name:	DESIGN
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	06301990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	FRA
Activity Name:	FINAL REMEDIAL ACTION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	10261990
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Activity:	DEED
Activity Name:	DEED RESTRICTIONS
AWP Code:	RESTR
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	01251991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	CERT
Activity Name:	CERTIFICATION
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	01301991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	1270
Liquids Treated (Gals):	0
Action Included Capping:	X
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	N
Activity Comments:	1270 TONS OF LEAD, ZINC & LOW PH CONTAMINATED SOIL WERE EXCAVATED,CHEMICALLY STABILIZED INTO A FORM OF CONCRETE SLURRY AND REDISPOSEDONSITE INTO A TRENCH TO COMPLETE THE FINAL HARDENING PROCESS.
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	ORDER
Activity Name:	I/SE, IORSE, FFA, FFSRA, VCA, EA
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Comments Date:	03291991
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	COST
Activity Name:	COST RECOVERY
AWP Code:	AGRFL
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	10141992
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	5YEAR
Activity Name:	FIVE-YEAR REVIEW REQUIRED BY CERCLA
AWP Code:	Not reported
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	05111998
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Facility ID:	39340018
Activity:	DEED
Activity Name:	DEED RESTRICTIONS
AWP Code:	AREAA
Proposed Budget:	0
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	08171989
Est Person-Yrs to complete:	0
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	COM
Definition of Status:	CERTIFIED / OPERATION & MAINTENANCE
Liquids Removed (Gals):	0
Liquids Treated (Gals):	0
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	0
For Industrial Reuse:	0
For Residential Reuse:	0
Unknown Type:	0
Alternate Address:	540 WEST SCOTTS AVENUE
Alternate City,St,Zip:	STOCKTON, CA 95203
Background Info:	Lead and zinc contaminated soil was excavated to heath based soil cleanup levels, chemically stabilized, and redisposed onsite into a trench and capped with asphalt. Acidic soil was also neutralized. A deed restriction and O & M Agreement for continued maintenance of the cap have been recorded. The site was certified in January 1991.
Comments Date:	12011985
Comments:	Sample Results: Zinc 18,000 mg/kg; Lead 440 mg/kg; Low PH.
Comments Date:	02091987
Comments:	Site Screening Done: Mitre Model required.
Comments Date:	03201982
Comments:	Facility identified from Industrial Index.
Comments Date:	04151982
Comments:	Records Search (RWQCB): IT Corp hauls wastes. Prior to
Comments Date:	04151982
Comments:	1972, would dump waste down storm drain.
Comments Date:	04221982
Comments:	Records Search: Municipal Utility District has waste
Comments Date:	04221982
Comments:	hauled out; no problems.
Comments Date:	05011986
Comments:	this is the date the site was first listed AWP pursuant to
Comments Date:	05011986

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Comments: Section 25356.
Comments Date: 05111998
Comments: 5YEAR -- A FIVE YEAR REVIEW AND RE-EVALUATION HAS BEEN COM-
Comments Date: 05111998
Comments: PLETED. SITE CONTAMINANTS (LEAD AND ZINC) REMAIN STABILIZED
Comments Date: 05111998
Comments: UNDER AN ASPHALT CAP WITH NO CONTAMINANT MIGRATION DETECTED
Comments Date: 05111998
Comments: BELOW THE STABILIZED MATERIAL. DUE TO DETERIORATION, THE
Comments Date: 05111998
Comments: ASPHALT CAP REQUIRED REPAIR AND THREE GROUNDWATER
Comments Date: 05111998
Comments: MONITORING WELLS REQUIRED DESTRUCTION. THESE REPAIR
Comments Date: 05111998
Comments: ACTIVITIES HAVE BEEN COMPLETED UNDER DTSC OVERSIGHT AS A
Comments Date: 05111998
Comments: FOLOWUP TO THE 5 YEAR REVIEW.
Comments Date: 06031982
Comments: Questionnaire mailed.
Comments Date: 06151982
Comments: Facility Drive-by: No activity; no wastes seen.
Comments Date: 06301987
Comments: Preliminary Assessment Done: Recommend Site Inspection --
Comments Date: 06301987
Comments: onsite contamination is documented.
Comments Date: 07271982
Comments: Phone follow-up: Site has been closed & will remain closed
Comments Date: 07271982
Comments: until next year.
Comments Date: 08151989
Comments: Former zinc galvanizing operation. Contaminants include
Comments Date: 08151989
Comments: lead, zinc, and low PH.
Comments Date: 08191991
Comments: Records Search: Site Certified in January 1991. An
Comments Date: 08191991
Comments: operation & maintenance agreement has been signed with the
Comments Date: 08191991
Comments: responsible party for monitoring of the cap and a deed
Comments Date: 08191991
Comments: restriction has been recorded.
ID Name: BEP DATABASE PCODE
ID Value: P12106
ID Name: CALSTARS CODE
ID Value: 100001
Alternate Name: ACME GALVANIZING, STOCKTON
Alternate Name: ACME-STOCKTON GALVANIZING WORKS
Alternate Name: Not reported
Special Programs Code: Not reported
Special Programs Name: Not reported

DEED:
Name: ACME-STOCKTON GALVANIZING WORKS
Address: 540 WEST SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95203
Envirostor ID: 39340018
Area: PROJECT WIDE

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Sub Area: Not reported
Site Type: STATE RESPONSE
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

Name: ACME-STOCKTON GALVANIZING WORKS
Address: 540 WEST SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95203
Envirostor ID: 39340018
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: STATE RESPONSE
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

CA BOND EXP. PLAN:
Reponsible Party: RESPONSIBLE PARTY-LEAD SITE CLEANUP WORKPLAN
Project Revenue Source Company: Acme Galvanizing Company, Inc.
Project Revenue Source Addr: 1655 17th Street
Project Revenue Source City,St,Zip: Oakland, CA 94607
Project Revenue Source Desc: DHS has budgeted $50,000 for related direct costs. DHS will recover 100 percent of direct costs plus staff costs and overhead related to the project. The responsible parties will pay all costs associated with remedial investigations and cleanup activities. The property owner is funding the site characterization and remedial action at the site. State Bond funds may be expended for oversight activities.
Site Description: Acme Galvanizing was in operation prior to February, 1982. A molten zinc dip bath was used to coat metal objects that were cleaned using sulfuric acid and caustic. The site was closed when the zinc bath developed a leak and caused molten zinc to spill onto the ground.
Hazardous Waste Desc: Acid soil, lead and zinc are the principle contaminants at this site.
Threat To Public Health & Env: The soil is contaminated to at least 12 feet. Ground water may be affected, but has not been sampled. Ground water contamination would provide the most likely pathway for human contact in the area.
Site Activity Status: A preliminary investigation indicated high levels of zinc and lead contamination in the soil. DHS issued the final RAO on November 17, 1987. A RI/FS work plan was submitted to DHS on February 1, 1988. A revised RI/FS work plan was approved on August10, 1988.

CERS:
Name: ACME GALVANIZING
Address: 540 WEST SCOTTS
City,State,Zip: STOCKTON, CA
Site ID: 253520
CERS ID: SLT5S0283069
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: zzz - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported

ACME-STOCKTON GALVANIZING WORKS (Continued) **S100833160**

Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AC177 **SOUTH SHORE PROPERTY** **ENVIROSTOR** **S104549152**
WNW **WEST WEBER AVENUE** **VCP** **N/A**
1/2-1 **STOCKTON, CA 95203**
0.695 mi.
3669 ft. **Site 1 of 2 in cluster AC**

Relative:
Lower

Actual:
12 ft.

ENVIROSTOR:

Name:	SOUTH SHORE PROPERTY
Address:	WEST WEBER AVENUE
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39290009
Status:	Refer: RWQCB
Status Date:	07/18/2000
Site Code:	101244
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	RWQCB 5S - Central Valley
Lead Agency:	RWQCB 5S - Central Valley
Program Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.95167
Longitude:	-121.2988
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	SOUTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	STOCKTON BROWNFIELDS
Alias Type:	Alternate Name
Alias Name:	110033616816
Alias Type:	EPA (FRS #)
Alias Name:	101244
Alias Type:	Project Code (Site Code)
Alias Name:	39290009
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

SOUTH SHORE PROPERTY (Continued) **S104549152**

Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	07/18/2001
Comments:	GSU comment memo dated 7/12/2000.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	05/12/2000
Comments:	VCP - Oversight and Consultation Agreement was finalized/ signed by DTSC on May 12, 2000 to oversee work conducted by the City of Stockton Redevelopment Agency.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	SOUTH SHORE PROPERTY
Address:	WEST WEBER AVENUE
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39290009
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	Not reported
National Priorities List:	NO
Cleanup Oversight Agencies:	RWQCB 5S - Central Valley
Lead Agency:	RWQCB 5S - Central Valley
Lead Agency Description:	RWQCB 5S - Central Valley
Project Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Site Code:	101244
Assembly:	13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: RWQCB
Status Date:	07/18/2000
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.95167 / -121.2988
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	SOUTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	STOCKTON BROWNFIELDS
Alias Type:	Alternate Name
Alias Name:	110033616816

SOUTH SHORE PROPERTY (Continued) **S104549152**

Alias Type: EPA (FRS #)
Alias Name: 101244
Alias Type: Project Code (Site Code)
Alias Name: 39290009
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 07/18/2001
Comments: GSU comment memo dated 7/12/2000.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 05/12/2000
Comments: VCP - Oversight and Consultation Agreement was finalized/ signed by DTSC on May 12, 2000 to oversee work conducted by the City of Stockton Redevelopment Agency.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

178 **J.C. TRUCKING** **LUST** **S101592890**
SE **1207 S AURORA ST** **SWEEPS UST** **N/A**
1/2-1 **STOCKTON, CA 95206** **CA FID UST**
0.701 mi. **Cortese**
3700 ft. **HIST CORTESE**
Notify 65
Relative: **CERS**
Higher

Actual: **18 ft.**

LUST:
Name: J.C. TRUCKING
Address: 1207 AURORA ST S
City,State,Zip: STOCKTON, CA 95206
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700584
Global Id: T0607700584
Latitude: 37.9425262
Longitude: -121.2763338
Status: Completed - Case Closed
Status Date: 06/04/2010
Case Worker: Not reported
RB Case Number: 390749
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 2571
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline

J.C. TRUCKING (Continued) **S101592890**

Site History: May 1992- Four underground storage tanks were removed from the site, the tanks were located in two separate tank pit locations. Soil samples for analysis were collected from the tank pits; laboratory results reported petroleum hydrocarbon impact to the soil. August 1997- A site investigation began with the installation of geoprobe soil borings. Soil and grab groundwater samples were collected for analysis, petroleum hydrocarbon impact was confirmed. April 1999-May 2001- Additonal soil borings and groundwater monitoring wells were installed both on and offsite. December 2004- Site remediation of the impacted groundwater by ozone infusion was started. June 2009- Soil vapor samples were collected for analysis and review of potential for vapor intrusion from remaining contamination. A Closure Report was submitted on November 16, 2009; A concurrance request was submitted to the Regional Water Quality Control Board on November 19, 2009. Concurrence was received on December 21, 2009. Monitoring and remediaion wells were destroyed in April 2010. No Further Action letter issued June 9, 2010.

LUST:
Global Id: T0607700584
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 04/03/2002
Action: Staff Letter

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/24/2003
Action: Site Visit / Inspection / Sampling

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 06/17/2009
Action: Site Visit / Inspection / Sampling

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 11/12/2009
Action: File review

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 12/23/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 12/21/2009

J.C. TRUCKING (Continued) **S101592890**

Action: Technical Correspondence / Assistance / Other

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 11/19/2009
Action: LOP Case Closure Summary to RB

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/10/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 04/22/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 06/09/2010
Action: Closure/No Further Action Letter

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 11/27/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 08/18/1992
Action: Notification - Proposition 65

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 08/18/1992
Action: Unauthorized Release Form

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 11/29/1995
Action: Notice of Responsibility

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/18/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

J.C. TRUCKING (Continued) **S101592890**

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700584
Action Type: Other
Date: 07/23/1992
Action: Leak Discovery

Global Id: T0607700584
Action Type: Other
Date: 05/04/1992
Action: Leak Stopped

Global Id: T0607700584
Action Type: Other
Date: 08/18/1992
Action: Leak Reported

Global Id: T0607700584
Action Type: RESPONSE
Date: 04/19/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700584
Action Type: RESPONSE
Date: 04/19/2002
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700584
Action Type: REMEDIATION
Date: 12/06/2004
Action: Other (Use Description Field)

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/02/2009
Action: File review

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 06/19/2008
Action: Technical Correspondence / Assistance / Other - #06/19/2008

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 09/11/2008
Action: File review

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 12/23/2008
Action: File review

Global Id: T0607700584
Action Type: ENFORCEMENT

J.C. TRUCKING (Continued) **S101592890**

Date: 05/13/2009
Action: Technical Correspondence / Assistance / Other - #05/13/2009

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 03/06/2009
Action: Technical Correspondence / Assistance / Other - #03/06/2009

Global Id: T0607700584
Action Type: ENFORCEMENT
Date: 07/31/2009
Action: File review

LUST:
Global Id: T0607700584
Status: Open - Case Begin Date
Status Date: 05/04/1992

Global Id: T0607700584
Status: Open - Site Assessment
Status Date: 05/04/1992

Global Id: T0607700584
Status: Open - Site Assessment
Status Date: 09/23/2004

Global Id: T0607700584
Status: Open - Remediation
Status Date: 12/06/2004

Global Id: T0607700584
Status: Open - Verification Monitoring
Status Date: 04/07/2010

Global Id: T0607700584
Status: Open - Inactive
Status Date: 04/23/2010

Global Id: T0607700584
Status: Completed - Case Closed
Status Date: 06/04/2010

LUST REG 5:
Name: J.C. TRUCKING
Address: 1207 AURORA ST S
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 390749
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

J.C. TRUCKING (Continued) **S101592890**

SWEEPS UST:

Name:	J.C. TRUCKING
Address:	1207 S AURORA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2571
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002571-000001
Tank Status:	Not reported
Capacity:	4000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	4

Name:	J.C. TRUCKING
Address:	1207 S AURORA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2571
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002571-000002
Tank Status:	Not reported
Capacity:	4000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

Name:	J.C. TRUCKING
Address:	1207 S AURORA ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2571
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002571-000003
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL

J.C. TRUCKING (Continued) **S101592890**

STG: PRODUCT
Content: DIESEL
Number Of Tanks: Not reported

Name: J.C. TRUCKING
Address: 1207 S AURORA ST
City: STOCKTON
Status: Not reported
Comp Number: 2571
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002571-000004
Tank Status: Not reported
Capacity: 5000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000600
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094663282
Mail To: Not reported
Mailing Address: P O BOX 6008
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95206
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

CORTESE:
Name: J.C. TRUCKING
Address: 1207 AURORA ST S
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700584
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported

J.C. TRUCKING (Continued) **S101592890**

Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	J.C. TRUCKING
edr_fadd1:	1207 AURORA
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390749

NOTIFY 65:

Name:	J.C. TRUCKING
Address:	1207 AURORA ST S
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	08/18/1992
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	J.C. TRUCKING
Address:	1207 AURORA ST S
City,State,Zip:	STOCKTON, CA 95206
Site ID:	196371
CERS ID:	T0607700584
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

179 WNW 1/2-1 0.715 mi. 3774 ft. | **DELTA GATEWAY APARTMENTS, STOCKTON**
720/802 WEST WEBER AVENUE
STOCKTON, CA 95203 | **ENVIROSTOR VCP** | **S106568313 N/A**

Relative: Lower

Actual: 11 ft.

ENVIROSTOR:

Name:	DELTA GATEWAY APARTMENTS, STOCKTON
Address:	720/802 WEST WEBER AVENUE
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39000004
Status:	Refer: RWQCB
Status Date:	04/14/2008
Site Code:	101350
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	8.78
NPL:	NO
Regulatory Agencies:	RWQCB 5S - Central Valley
Lead Agency:	RWQCB 5S - Central Valley
Program Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.95105
Longitude:	-121.3006
APN:	NONE SPECIFIED
Past Use:	FUEL TERMINALS
Potential COC:	Benzene Lead Methane Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas TPH-MOTOR OIL
Confirmed COC:	Benzene Lead Methane Polynuclear aromatic hydrocarbons (PAHs TPH-diesel TPH-gas TPH-MOTOR OIL
Potential Description:	OTH, SOIL, SV, IA
Alias Name:	DELTA GATEWAY APARTMENTS, STOCKTON
Alias Type:	Alternate Name
Alias Name:	DELTA VIEW APARTMENTS, STOCKTON
Alias Type:	Alternate Name
Alias Name:	L&M Operable Unit (OU)
Alias Type:	Alternate Name
Alias Name:	SOUTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	110033617566
Alias Type:	EPA (FRS #)
Alias Name:	101350
Alias Type:	Project Code (Site Code)
Alias Name:	39000004
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Risk Assessment Report
Completed Date:	06/17/2008
Comments:	DTSC VCA Termination Notification letter dated/mailed on 4/14/2008.

DELTA GATEWAY APARTMENTS, STOCKTON (Continued) **S106568313**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	04/14/2008
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	01/06/2003
Comments:	The final VCA was signed by DTSC on 1/6/03. The VCA scope of work required a completed Health Risk Assessment for the L&M Operable Unit site which includes the Delta View Apartments (formerly known as the Delta Gateway Apartments). The Regional Water Quality Control Board requested suspension of the HRA at the end of 2005 and confirmed this request at the beginning of 2006.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	06/17/2008
Comments:	VCA termination letter dated 4/14/2008 due to the request of RWQCB to assume oversight of cleanup. DTSC Accounting Closeout email dated 6/17/2008

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	DELTA GATEWAY APARTMENTS, STOCKTON
Address:	720/802 WEST WEBER AVENUE
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39000004
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	8.78
National Priorities List:	NO
Cleanup Oversight Agencies:	RWQCB 5S - Central Valley
Lead Agency:	RWQCB 5S - Central Valley
Lead Agency Description:	RWQCB 5S - Central Valley
Project Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup Sacramento
Site Code:	101350
Assembly:	13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Refer: RWQCB
Status Date:	04/14/2008

DELTA GATEWAY APARTMENTS, STOCKTON (Continued) **S106568313**

Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	37.95105 / -121.3006
APN:	NONE SPECIFIED
Past Use:	FUEL TERMINALS
Potential COC:	30003, 30013, 30015, 30019, 30024, 30025, 3002502
Confirmed COC:	30003,30013,30015,30019,30024,30025,3002502
Potential Description:	OTH, SOIL, SV, IA
Alias Name:	DELTA GATEWAY APARTMENTS, STOCKTON
Alias Type:	Alternate Name
Alias Name:	DELTA VIEW APARTMENTS, STOCKTON
Alias Type:	Alternate Name
Alias Name:	L&M Operable Unit (OU)
Alias Type:	Alternate Name
Alias Name:	SOUTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	110033617566
Alias Type:	EPA (FRS #)
Alias Name:	101350
Alias Type:	Project Code (Site Code)
Alias Name:	39000004
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Risk Assessment Report
Completed Date:	06/17/2008
Comments:	DTSC VCA Termination Notification letter dated/mailed on 4/14/2008.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	04/14/2008
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	01/06/2003
Comments:	The final VCA was signed by DTSC on 1/6/03. The VCA scope of work required a completed Health Risk Assessment for the L&M Operable Unit site which includes the Delta View Apartments (formerly known as the Delta Gateway Apartments). The Regional Water Quality Control Board requested suspension of the HRA at the end of 2005 and confirmed this request at the beginning of 2006.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Voluntary Cleanup Agreement Completion
Completed Date:	06/17/2008
Comments:	VCA termination letter dated 4/14/2008 due to the request of RWQCB to assume oversight of cleanup. DTSC Accounting Closeout email dated 6/17/2008

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported

DELTA GATEWAY APARTMENTS, STOCKTON (Continued) **S106568313**

Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

AC180 **MORTON PAINT COMPANY** **ENVIROSTOR** **S100190082**
WNW **SOUTH LINCOLN & WEST MAIN** **N/A**
1/2-1 **STOCKTON, CA 95201**
0.718 mi.
3790 ft. **Site 2 of 2 in cluster AC**

Relative:
Lower

Actual:
11 ft.

ENVIROSTOR:
Name: MORTON PAINT COMPANY
Address: SOUTH LINCOLN & WEST MAIN
City,State,Zip: STOCKTON, CA 95201
Facility ID: 39280010
Status: Refer: Other Agency
Status Date: 11/16/1994
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.9515
Longitude: -121.2993
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: * Sludge - Paint
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 39280010
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 06/17/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 10/01/1981
Comments: Not reported

MORTON PAINT COMPANY (Continued) **S100190082**

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

AD181 **GASCO** **LUST** **S104164965**
SE **749 CHARTER WAY E** **Cortese** **N/A**
1/2-1 **STOCKTON, CA 95206** **HIST CORTESE**
0.728 mi. **Notify 65**
3845 ft. **Site 1 of 2 in cluster AD** **CERS**

Relative: Higher
Actual: 18 ft.

LUST:

Name:	GASCO
Address:	749 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700347
Global Id:	T0607700347
Latitude:	37.940714212
Longitude:	-121.2771538
Status:	Open - Verification Monitoring
Status Date:	07/30/2003
Case Worker:	AMB
RB Case Number:	390443
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	11/14/1989, Four USTs removed, contamination noted. 11/21/1989, Soil contamination verified, Prop 65 and UAR filed. 1/12/1990, waste oil UST removed, contamination noted. 1/31/1990, MW-1 through MW-3 installed. 4/20/1990, Groundwater contamination verified, Prop 65 filed. 7/7/1997 to 7/10/2003, SVE remediation system operated to address impacted soil. DPE proposed to address remaining impacted soil and groundwater.

LUST:

Global Id:	T0607700347
Contact Type:	Regional Board Caseworker
Contact Name:	ALAN M. BUEHLER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Dr
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	9164644615

LUST:

Global Id:	T0607700347
Action Type:	RESPONSE
Date:	02/01/1990
Action:	Other Report / Document

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/28/1989
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 03/04/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 09/23/1998
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/25/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/18/1998
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/06/2003
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 09/06/1992
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/01/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/07/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/13/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/25/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE

GASCO (Continued) **S104164965**

Date: 04/23/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/10/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 06/30/1995
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/05/1999
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 09/14/1995
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/16/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/15/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/07/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/13/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/25/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/23/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/09/2002
Action: Monitoring Report - Quarterly

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/18/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/31/2006
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/08/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 12/30/2009
Action: File review

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 08/14/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/06/2014
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 05/23/2017
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 07/28/2005
Action: Notice of Responsibility

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 11/21/1989
Action: Notification - Proposition 65

Global Id: T0607700347
Action Type: ENFORCEMENT

GASCO (Continued) **S104164965**

Date: 04/20/1990
Action: Notification - Proposition 65

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/10/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 10/25/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 10/18/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 10/23/2000
Action: Notice of Responsibility

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 11/21/1996
Action: Notification - Public Notice of ROD/RAP/CAP

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 07/09/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 10/08/2010
Action: File review

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 05/20/2010
Action: File review

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 12/29/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/01/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 11/01/2017
Action: Staff Letter

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 08/29/2018
Action: 13267 Requirement - #R5-2018-0820

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 05/16/2018
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 12/14/2018
Action: Notice of Violation

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/05/2018
Action: Other Report

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 01/02/2018
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/05/2020
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 08/28/2019
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 01/06/2020
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 08/31/2020
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/24/2020
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/29/2020
Action: Staff Letter

Global Id: T0607700347
Action Type: RESPONSE

GASCO (Continued) **S104164965**

Date: 08/30/2014
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 02/08/2012
Action: File review

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/13/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/16/2013
Action: Staff Letter

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 03/23/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 01/24/2017
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/13/2017
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 04/13/2017
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 01/10/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700347
Action Type: Other
Date: 11/14/1989
Action: Leak Discovery

Global Id: T0607700347
Action Type: Other
Date: 11/21/1989
Action: Leak Reported

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 05/03/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 07/22/2013
Action: Staff Letter

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/19/2008
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700347
Action Type: REMEDIATION
Date: 07/14/1997
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/30/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/16/1998
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/25/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/24/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/08/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/10/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/31/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE

GASCO (Continued) **S104164965**

Date: 11/29/1993
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/05/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 09/01/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/22/1996
Action: Monitoring Report - Semi-Annually

Global Id: T0607700347
Action Type: RESPONSE
Date: 06/10/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 03/19/1996
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/25/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/14/2000
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/18/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/17/2003
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/20/1992
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/27/1997
Action: Monitoring Report - Quarterly

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/03/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/05/1995
Action: Preliminary Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/21/1998
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 03/18/1993
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/18/1997
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/08/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/02/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/03/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/14/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/01/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/24/2005
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE

GASCO (Continued) **S104164965**

Date: 12/11/1991
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 12/29/1989
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/31/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/13/2003
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/20/1998
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/09/2000
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 03/15/1995
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/25/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/05/1990
Action: Tank Removal Report / UST Sampling Report

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 12/05/2008
Action: Staff Letter

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/12/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/31/1990
Action: Other Report / Document

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: RESPONSE
Date: 08/21/1998
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607700347
Action Type: RESPONSE
Date: 04/30/1992
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/26/1992
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/19/1990
Action: Soil and Water Investigation Report

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/23/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 04/28/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/24/1990
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 11/05/1998
Action: Other Report / Document

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/21/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/14/1997
Action: Site Assessment Report

Global Id: T0607700347
Action Type: RESPONSE

GASCO (Continued) **S104164965**

Date: 09/22/1995
Action: Correspondence

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/18/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 05/03/2006
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/26/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/14/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/27/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 02/23/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 07/23/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 10/25/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700347
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 08/28/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 12/22/1989
Action: Notice of Reimbursement

GASCO (Continued) **S104164965**

Global Id: T0607700347
Action Type: ENFORCEMENT
Date: 06/15/2009
Action: File review

LUST:
Global Id: T0607700347
Status: Open - Case Begin Date
Status Date: 11/14/1989

Global Id: T0607700347
Status: Open - Site Assessment
Status Date: 11/21/1989

Global Id: T0607700347
Status: Open - Remediation
Status Date: 07/16/1997

Global Id: T0607700347
Status: Open - Site Assessment
Status Date: 07/15/1999

Global Id: T0607700347
Status: Open - Remediation
Status Date: 12/01/2000

Global Id: T0607700347
Status: Open - Verification Monitoring
Status Date: 07/30/2003

LUST REG 5:
Name: GASCO
Address: 749 CHARTER WAY E
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390443
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 5

CORTESE:
Name: GASCO
Address: 749 CHARTER WAY E
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700347
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - VERIFICATION MONITORING
Status Date: Not reported
Site Code: Not reported

GASCO (Continued) **S104164965**

Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	GASCO
edr_fadd1:	749 CHARTER
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390443

NOTIFY 65:

Name:	GASCO
Address:	749 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	04/20/1990
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Name:	GASCO
Address:	749 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	11/21/1989
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	GASCO
Address:	749 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Site ID:	224134

GASCO (Continued) **S104164965**

CERS ID: T0607700347
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

AE182 **CHASE CHEVROLET CO** **RCRA-SQG** **1000378971**
NW **432 N. MADISON** **LUST** **CAD006914337**
1/2-1 **STOCKTON, CA 95202** **FINDS**
0.741 mi. **ECHO**
3911 ft. **Site 1 of 2 in cluster AE** **Cortese**
HAZNET
Relative: **HIST CORTESE**
Lower **Notify 65**
CERS
Actual: **HWTS**
13 ft.

RCRA-SQG:
Date Form Received by Agency: 1996-09-01 00:00:00.0
Handler Name: CHASE CHEVROLET CO
Handler Address: 432 N. MADISON
Handler City,State,Zip: STOCKTON, CA 95202
EPA ID: CAD006914337
Contact Name: Not reported
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: CA
State District: 1
Mailing Address: PO BOX 1969
Mailing City,State,Zip: STOCKTON, CA 95201
Owner Name: Not reported
Owner Type: Not reported
Operator Name: NOT REQUIRED
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No

CHASE CHEVROLET CO (Continued) **1000378971**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:23:55.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHASE WILLIAMS K
Legal Status:	Private

CHASE CHEVROLET CO (Continued) **1000378971**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: CHASE CHEVROLET CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1986-08-21 00:00:00.0
Handler Name: CHASE CHEVROLET CO	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CHASE CHEVROLET CO (Continued) **1000378971**

Evaluations: No Evaluations Found

LUST:
Name: CHASE CHEVROLET
Address: 423 MADISON ST N
City,State,Zip: STOCKTON, CA 95202
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700081
Global Id: T0607700081
Latitude: 37.9563709
Longitude: -121.2950425
Status: Completed - Case Closed
Status Date: 02/20/2013
Case Worker: Not reported
RB Case Number: 390110
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 1163457
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: May 1986- Three underground storage tanks were removed from the site. The site is one of several properties located on West Fremont Street and currently owned by the City of Stockton; it is the location of the Stockton Area and Stockton Ballpark. The site has undergone investigation, and some remediation prior to the city redevelopment project but the monitoring wells have not yet been reinstalled.

LUST:
Global Id: T0607700081
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700081
Action Type: RESPONSE
Date: 01/10/1995
Action: Monitoring Report - Other

Global Id: T0607700081
Action Type: RESPONSE
Date: 02/23/1995
Action: Correspondence

Global Id: T0607700081
Action Type: RESPONSE
Date: 02/27/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE

CHASE CHEVROLET CO (Continued) **1000378971**

Date: 05/15/2003
Action: Interim Remedial Action Report

Global Id: T0607700081
Action Type: RESPONSE
Date: 04/24/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 02/10/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 06/09/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 02/17/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 08/12/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 08/15/1989
Action: Notice of Reimbursement

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 08/28/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 01/11/2010
Action: Meeting

Global Id: T0607700081
Action Type: RESPONSE
Date: 04/21/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 06/02/2010
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 01/10/1991
Action: Notification - Proposition 65

CHASE CHEVROLET CO (Continued) **1000378971**

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 11/12/1992
Action: Notification - Proposition 65

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/24/2004
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 08/24/2010
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 11/09/2011
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/01/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/01/2012
Action: Notice of Responsibility

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 04/04/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/20/2013
Action: Closure/No Further Action Letter

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 03/21/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 04/10/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT

CHASE CHEVROLET CO (Continued) **1000378971**

Date: 04/23/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/06/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700081
Action Type: Other
Date: 05/14/1986
Action: Leak Discovery

Global Id: T0607700081
Action Type: Other
Date: 05/14/1986
Action: Leak Stopped

Global Id: T0607700081
Action Type: Other
Date: 08/22/1989
Action: Leak Reported

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 10/22/2012
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 12/20/2012
Action: LOP Case Closure Summary to RB

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 01/13/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 11/13/2012
Action: File review

Global Id: T0607700081
Action Type: REMEDIATION
Date: 04/01/2004
Action: Excavation

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 11/16/2010
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 08/11/2008
Action: Technical Correspondence / Assistance / Other - #08/11/08

CHASE CHEVROLET CO (Continued) **1000378971**

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 01/10/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 11/02/2012
Action: File Review - Closure

Global Id: T0607700081
Action Type: RESPONSE
Date: 01/20/1997
Action: Other Report / Document

Global Id: T0607700081
Action Type: RESPONSE
Date: 01/25/1995
Action: Monitoring Report - Other

Global Id: T0607700081
Action Type: RESPONSE
Date: 01/29/1996
Action: Site Assessment Report

Global Id: T0607700081
Action Type: RESPONSE
Date: 10/09/2001
Action: Other Report / Document

Global Id: T0607700081
Action Type: RESPONSE
Date: 10/03/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 10/04/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 07/30/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 08/29/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 05/23/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE

CHASE CHEVROLET CO (Continued) **1000378971**

Date: 04/04/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 02/27/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 10/31/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 02/13/2009
Action: File review

Global Id: T0607700081
Action Type: RESPONSE
Date: 03/20/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 11/14/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 06/26/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 08/22/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: RESPONSE
Date: 12/20/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 06/02/2009
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 07/13/2009
Action: File review

Global Id: T0607700081
Action Type: ENFORCEMENT
Date: 07/21/2009
Action: File review

CHASE CHEVROLET CO (Continued) **1000378971**

LUST:
Global Id: T0607700081
Status: Open - Case Begin Date
Status Date: 05/14/1986

Global Id: T0607700081
Status: Open - Site Assessment
Status Date: 08/22/1989

Global Id: T0607700081
Status: Open - Inactive
Status Date: 05/25/2010

Global Id: T0607700081
Status: Open - Eligible for Closure
Status Date: 12/20/2012

Global Id: T0607700081
Status: Completed - Case Closed
Status Date: 02/20/2013

LUST REG 5:
Name: CHASE CHEVROLET
Address: 423 MADISON ST N
City: STOCKTON
Region: 5
Status: Preliminary site assessment underway
Case Number: 390110
Case Type: Drinking Water Aquifer affected
Substance: UNLEAD GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 1

FINDS:
Registry ID: 110002630118

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000378971
Registry ID: 110002630118
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002630118
Name: CHASE CHEVROLET CO

CHASE CHEVROLET CO (Continued) **1000378971**

Address: 432 N. MADISON
City,State,Zip: STOCKTON, CA 95202

CORTESE:
Name: CHASE CHEVROLET
Address: 423 MADISON ST N
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700081
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HAZNET:
Name: CHASE CHEVROLET CO
Address: 432 N. MADISON
Address 2: Not reported
City,State,Zip: STOCKTON, CA 952020000
Contact: UNDELIVERABLE 1996 FEES FORM
Telephone: --
Mailing Name: Not reported
Mailing Address: PO BOX 1969

Year: 1995
Gepaid: CAD006914337
TSD EPA ID: CAD093459485
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H01 - Transfer Station
Tons: 0.018

Year: 1994
Gepaid: CAD006914337
TSD EPA ID: CAD980887418
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: H01 - Transfer Station
Tons: 2.226

Year: 1994
Gepaid: CAD006914337

CHASE CHEVROLET CO (Continued) **1000378971**

TSD EPA ID: CAD093459485
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: -
Tons: 0.0834

Year: 1993
Gepaid: CAD006914337
TSD EPA ID: CAD980887418
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: -
Tons: 0.756

Year: 1993
Gepaid: CAD006914337
TSD EPA ID: CAD980887418
CA Waste Code: 221 - Waste oil and mixed oil
Disposal Method: R01 - Recycler
Tons: 2.451

Year: 1993
Gepaid: CAD006914337
TSD EPA ID: CAD980887418
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: H01 - Transfer Station
Tons: 1.47

Year: 1991
Gepaid: CAD006914337
TSD EPA ID: CAD009452657
CA Waste Code: 343 - Unspecified organic liquid mixture
Disposal Method: R01 - Recycler
Tons: 0.3252

Year: 1991
Gepaid: CAD006914337
TSD EPA ID: CAT000613950
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H01 - Transfer Station
Tons: 0.135

Year: 1989
Gepaid: CAD006914337
TSD EPA ID: CAT000613968
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: -
Tons: 0.2627

Year: 1989
Gepaid: CAD006914337
TSD EPA ID: CAT000613968
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: H01 - Transfer Station
Tons: 0.3794

CHASE CHEVROLET CO (Continued) **1000378971**

Click this hyperlink while viewing on your computer to access additional CA HAZNET: detail in the EDR Site Report.

Additional Info:

Year:	1994
Gen EPA ID:	CAD006914337
Shipment Date:	19940503
Creation Date:	3/25/1996 0:00:00
Receipt Date:	19940503
Manifest ID:	93125623
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD980887418
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	1.176
Waste Quantity:	280
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940307
Creation Date:	9/15/1995 0:00:00
Receipt Date:	19940307
Manifest ID:	93161096
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	1.05
Waste Quantity:	250
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940127

CHASE CHEVROLET CO (Continued) **1000378971**

Creation Date:	9/14/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	93124566
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD093459485
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	D008
Meth Code:	- Not reported
Quantity Tons:	0.0834
Waste Quantity:	20
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1995
Gen EPA ID:	CAD006914337
Shipment Date:	19951215
Creation Date:	7/29/1996 0:00:00
Receipt Date:	19951218
Manifest ID:	95556575
Trans EPA ID:	ILD984908202
Trans Name:	Not reported
Trans 2 EPA ID:	ILD984908202
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD093459485
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	D039
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.018
Waste Quantity:	5
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1993
Gen EPA ID:	CAD006914337
Shipment Date:	19931007

CHASE CHEVROLET CO (Continued) **1000378971**

Creation Date:	9/13/1995 0:00:00
Receipt Date:	19931007
Manifest ID:	93292088
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.84
Waste Quantity:	200
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19930902
Creation Date:	9/13/1995 0:00:00
Receipt Date:	19930902
Manifest ID:	93292035
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD980887418
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.63
Waste Quantity:	150
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19930617
Creation Date:	9/8/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	93292399
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported

CHASE CHEVROLET CO (Continued) **1000378971**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	- Not reported
Quantity Tons:	0.756
Waste Quantity:	180
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19930127
Creation Date:	9/15/1995 0:00:00
Receipt Date:	19930128
Manifest ID:	92092703
Trans EPA ID:	CAD980695761
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD980887418
TSDF Alt Name:	Not reported
Waste Code Description:	221 - Waste oil and mixed oil
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	2.451
Waste Quantity:	645
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HIST CORTESE:

edr_fname:	CHASE CHEVROLET
edr_fadd1:	423 MADISON
City,State,Zip:	STOCKTON, CA 95202
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390110

NOTIFY 65:

Name:	CHASE CHEVROLET
Address:	423 MADISON ST N
City,State,Zip:	STOCKTON, CA 95202
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported

CHASE CHEVROLET CO (Continued) **1000378971**

Issue Date: 11/12/1992
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: CHASE CHEVROLET
Address: 423 MADISON ST N
City,State,Zip: STOCKTON, CA 95202
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 01/10/1991
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: CHASE CHEVROLET
Address: 423 MADISON ST N
City,State,Zip: STOCKTON, CA 95202
Site ID: 236340
CERS ID: T0607700081
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

HWTS:
Name: CHASE CHEVROLET CO
Address: 432 N. MADISON
Address 2: Not reported
City,State,Zip: STOCKTON, CA 952020000
EPA ID: CAD006914337
Inactive Date: 06/30/1996
Create Date: 04/10/1987
Last Act Date: 09/14/2004
Mailing Name: Not reported
Mailing Address: PO BOX 1969
Mailing Address 2: Not reported
Mailing City,State,Zip: STOCKTON, CA 952010000
Owner Name: JOHN CHASE
Owner Address: 423 N MADISON
Owner Address 2: Not reported
Owner City,State,Zip: STOCKTON, CA 952020000
Contact Name: UNDELIVERABLE 1996 FEES FORM
Contact Address: --

CHASE CHEVROLET CO (Continued) **1000378971**

Contact Address 2: Not reported
City,State,Zip: --, 99 --

AE183 **CHASE CHEVROLET CO.** **ENVIROSTOR** **S101592763**
NW **423 N MADISON** **VCP** **N/A**
1/2-1 **STOCKTON, CA 95203** **SWEEPS UST**
0.741 mi. **CA FID UST**
3911 ft. **Site 2 of 2 in cluster AE** **DEED**

Relative:
Lower

Actual:
13 ft.

ENVIROSTOR:

Name:	NORTH SHORE PROPERTY
Address:	423 N MADISON ST
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	39750010
Status:	Certified O&M - Land Use Restrictions Only
Status Date:	08/07/2006
Site Code:	102255 (OU2)
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	14.5
NPL:	NO
Regulatory Agencies:	SMBRP, RWQCB 5S - Central Valley
Lead Agency:	SMBRP
Program Manager:	Melessia Downham
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	YES
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.95495
Longitude:	-121.2973
APN:	13741001, 13741002, 13741004, 13741005, 13741014, 13741015, 13741017, 13742001
Past Use:	FUEL - VEHICLE STORAGE/ REFUELING, FUEL TERMINALS, RAILROAD RIGHT OF WAY, SHIPYARD - SHIP BUILDING/REPAIR, VEHICLE MAINTENANCE
Potential COC:	* HYDROCARBON SOLVENTS * OXYGENATED SOLVENTS Arsenic Lead
Confirmed COC:	NONE SPECIFIED
Potential Description:	OTH, SOIL
Alias Name:	Marina Towers LLC
Alias Type:	Alternate Name
Alias Name:	NORTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	University Plaza Waterfront Hotel
Alias Type:	Alternate Name
Alias Name:	13741001
Alias Type:	APN
Alias Name:	13741002
Alias Type:	APN
Alias Name:	13741004
Alias Type:	APN
Alias Name:	13741005
Alias Type:	APN
Alias Name:	13741014
Alias Type:	APN
Alias Name:	13741015

CHASE CHEVROLET CO. (Continued) **S101592763**

Alias Type: APN
Alias Name: 13741017
Alias Type: APN
Alias Name: 13742001
Alias Type: APN
Alias Name: OU1 (APN13741015)
Alias Type: EPA (FRS #)
Alias Name: 110033611955
Alias Type: GeoTracker Global ID
Alias Name: OU2 (APN13742001)
Alias Type: GeoTracker Global ID
Alias Name: SL0607769439
Alias Type: GeoTracker Global ID
Alias Name: SLT5S2713308
Alias Type: GeoTracker Global ID
Alias Name: 101243
Alias Type: Project Code (Site Code)
Alias Name: 101606
Alias Type: Project Code (Site Code)
Alias Name: 102254 (OU1)
Alias Type: Project Code (Site Code)
Alias Name: 102255 (OU2)
Alias Type: Project Code (Site Code)
Alias Name: 39750010
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 07/14/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Plan
Completed Date: 08/30/2001
Comments: RAP - The Remedial Action Plan has been approved. Implementation of the RAP will occur once a redevelopment project is approved. A seperate agreement will be prepared for this oversight activity. Project Site Code 101243 was terminated upon approval of the RAP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 06/04/2001
Comments: RIFS - The Remedial Investigation Report and Feasibility Study Report for this Site, in addition to subsequent revisions to the original submittals, have been approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/08/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/13/2020
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/26/2021
Comments: approved

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/19/2015
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: completed under 1 report

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/20/2020
Comments: completed 1/8/20, received by DTSC on 2/20/20

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020

CHASE CHEVROLET CO. (Continued) **S101592763**

Comments: Terradex Monitoring completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/05/2015
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 11/24/2015
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: completed under 1 report

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2019
Comments: 2019 LUC Report completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/16/2020
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/29/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 08/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 01/09/2004
Comments: VCA -- THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL (DTSC) SIGNED A VOLUNTARY CLEANUP AGREEMENT (VCA) JANUARY 9, 2004 WITH THE CITY OF STOCKTON OFR REVIEW, APPROVAL AND OVERSIGHT OF REMEDIAL DESIGN AND IMPLEMENTATION PLAN, REVIEW AND APPROVAL OF A COMPLETION REPORT, DEED RESTRICTION(S) FOR THE PROJECT PARCELS, AND ISSUANCE OF A REMEDIAL ACTION CERTIFICATE LETTER OR AN APPROVAL OF A PARTIAL REMEDIATION LETTER. DES (DESIGN)-- DTSC ISSUED AN APPROVAL LETTER DATED, MARCH 12, 2004 TO THE CITY OF STOCKTON FOR THE REMEDIAL DESIGN AND IMPLEMENTATION PLAN FOR THE NORTH SHORE PARCELS.

Completed Area Name: PROJECT WIDE

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 09/10/2001
Comments: The signed Notice of Determination, Negative Declaration Approval Form, Special Initial Study, Negative Declaration and the NOD filing checklist were sent to DTSC's Office of Program Audits and Environmental Analysis on 08/29/2001, with The Notice of Determination Certification of Fee Exemption being dated 09/10/2001.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 12/28/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 08/07/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/24/2008
Comments: Excavated soils were taken offsite from the property that has environmental restrictions under a land use convenant. A noncompliance letter dated 6/24/2008 was issued to the City Manager's (City of Stockton) office outlining the options for disposal of the soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/19/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 04/21/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 04/21/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/17/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2019
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2019
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2014
Comments: 2014.15 Annual Cost Estimate Letter dated 10.23.2014

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: complete

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2014
Comments: 2014.15 Annual Cost Estimate Letter dated 10.23.14

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2019
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/12/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Date: 11/15/2005
Comments: DTSC approval letter issued to the City of Stockton approving the report titled Remediation Completion Report, North Shore Parcels dated August 11, 2005.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 03/12/2004
Comments: DTSC letter to the City of Stockton approves the Remedial Design and Implementation Plan.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/11/2016
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/26/2021
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Date: 01/26/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: complete

Future Area Name: OU2 (APN13742001)
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Future Area Name: OU1 (APN13741015)
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: NORTH SHORE PROPERTY
Address: 423 N MADISON ST
City,State,Zip: STOCKTON, CA 95202
Facility ID: 39750010
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 14.5
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP, RWQCB 5S - Central Valley
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Melessia Downham
Supervisor: Lora Jameson
Division Branch: Northern California Schools & Santa Susana
Site Code: 102255 (OU2)
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: Certified O&M - Land Use Restrictions Only
Status Date: 08/07/2006
Restricted Use: YES
Funding: Responsible Party
Lat/Long: 37.95495 / -121.2973
APN: 13741001, 13741002, 13741004, 13741005, 13741014, 13741015, 13741017, 13742001
Past Use: FUEL - VEHICLE STORAGE/ REFUELING, FUEL TERMINALS, RAILROAD RIGHT OF WAY, SHIPYARD - SHIP BUILDING/REPAIR, VEHICLE MAINTENANCE
Potential COC: 10009, 10067, 30001, 30013

CHASE CHEVROLET CO. (Continued) **S101592763**

Confirmed COC:	NONE SPECIFIED
Potential Description:	OTH, SOIL
Alias Name:	Marina Towers LLC
Alias Type:	Alternate Name
Alias Name:	NORTH SHORE PROPERTY
Alias Type:	Alternate Name
Alias Name:	University Plaza Waterfront Hotel
Alias Type:	Alternate Name
Alias Name:	13741001
Alias Type:	APN
Alias Name:	13741002
Alias Type:	APN
Alias Name:	13741004
Alias Type:	APN
Alias Name:	13741005
Alias Type:	APN
Alias Name:	13741014
Alias Type:	APN
Alias Name:	13741015
Alias Type:	APN
Alias Name:	13741017
Alias Type:	APN
Alias Name:	13742001
Alias Type:	APN
Alias Name:	OU1 (APN13741015)
Alias Type:	EPA (FRS #)
Alias Name:	110033611955
Alias Type:	GeoTracker Global ID
Alias Name:	OU2 (APN13742001)
Alias Type:	GeoTracker Global ID
Alias Name:	SL0607769439
Alias Type:	GeoTracker Global ID
Alias Name:	SLT5S2713308
Alias Type:	GeoTracker Global ID
Alias Name:	101243
Alias Type:	Project Code (Site Code)
Alias Name:	101606
Alias Type:	Project Code (Site Code)
Alias Name:	102254 (OU1)
Alias Type:	Project Code (Site Code)
Alias Name:	102255 (OU2)
Alias Type:	Project Code (Site Code)
Alias Name:	39750010
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	07/14/2006
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Remedial Action Plan
Completed Date:	08/30/2001
Comments:	RAP - The Remedial Action Plan has been approved. Implementation of the RAP will occur once a redevelopment project is approved. A

CHASE CHEVROLET CO. (Continued) **S101592763**

seperate agreement will be prepared for this oversight activity.
Project Site Code 101243 was terminated upon approval of the RAP.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 06/04/2001
Comments: RIFS - The Remedial Investigation Report and Feasibility Study Report for this Site, in addition to subsequent revisions to the original submittals, have been approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 06/20/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/08/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/13/2020
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/26/2021
Comments: approved

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/19/2015
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: completed under 1 report

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/20/2020
Comments: completed 1/8/20, received by DTSC on 2/20/20

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016

CHASE CHEVROLET CO. (Continued) **S101592763**

Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/05/2015
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 11/24/2015
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: completed under 1 report

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2019
Comments: 2019 LUC Report completed

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/16/2020
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/09/2015
Comments: Annual Terradex monitoring activities have been conducted throughout fiscal year 2014/2015.

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/26/2016
Comments: Annual Terradex monitoring activities have been conducted since recording the LUC for the site in 2016.

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/19/2017
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 07/01/2018
Comments: update

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2019
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/30/2020
Comments: Terradex Monitoring completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/29/2019
Comments: complete

Completed Area Name: PROJECT WIDE

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Sub Area Name: Not reported
Completed Document Type: *Voluntary Cleanup Agreement Completion
Completed Date: 08/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 01/09/2004
Comments: VCA -- THE DEPARTMENT OF TOXIC SUBSTANCES CONTROL (DTSC) SIGNED A VOLUNTARY CLEANUP AGREEMENT (VCA) JANUARY 9, 2004 WITH THE CITY OF STOCKTON OFR REVIEW, APPROVAL AND OVERSIGHT OF REMEDIAL DESIGN AND IMPLEMENTATION PLAN, REVIEW AND APPROVAL OF A COMPLETION REPORT, DEED RESTRICTION(S) FOR THE PROJECT PARCELS, AND ISSUANCE OF A REMEDIAL ACTION CERTIFICATE LETTER OR AN APPROVAL OF A PARTIAL REMEDIATION LETTER. DES (DESIGN)-- DTSC ISSUED AN APPROVAL LETTER DATED, MARCH 12, 2004 TO THE CITY OF STOCKTON FOR THE REMEDIAL DESIGN AND IMPLEMENTATION PLAN FOR THE NORTH SHORE PARCELS.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Initial Study/ Neg. Declaration
Completed Date: 09/10/2001
Comments: The signed Notice of Determination, Negative Declaration Approval Form, Special Initial Study, Negative Declaration and the NOD filing checklist were sent to DTSC's Office of Program Audits and Environmental Analysis on 08/29/2001, with The Notice of Determination Certification of Fee Exemption being dated 09/10/2001.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 12/28/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 08/07/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/24/2008
Comments: Excavated soils were taken offsite from the property that has environmental restrictions under a land use convenant. A noncompliance letter dated 6/24/2008 was issued to the City Manager's (City of Stockton) office outlining the options for disposal of the soil.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/19/2012
Comments: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 04/21/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 04/21/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Land Use Restriction Monitoring Report
Completed Date: 03/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/17/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2019
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2019
Comments: completed

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2014
Comments: 2014.15 Annual Cost Estimate Letter dated 10.23.2014

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2014
Comments: 2014.15 Annual Cost Estimate Letter dated 10.23.14

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 08/27/2015
Comments: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2016
Comments: complete

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/14/2019
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/12/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 11/15/2005
Comments: DTSC approval letter issued to the City of Stockton approving the report titled Remediation Completion Report, North Shore Parcels dated August 11, 2005.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 03/12/2004
Comments: DTSC letter to the City of Stockton approves the Remedial Design and Implementation Plan.

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/18/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: completed

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/11/2016
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/24/2019
Comments: complete

CHASE CHEVROLET CO. (Continued) **S101592763**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 02/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 03/23/2017
Comments: Not reported

Completed Area Name: OU1 (APN13741015)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/26/2021
Comments: Not reported

Completed Area Name: OU2 (APN13742001)
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/26/2021
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: 5 Year Review Reports
Completed Date: 02/14/2018
Comments: complete

Future Area Name: OU2 (APN13742001)
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Future Area Name: OU1 (APN13741015)
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2023
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

SWEEPS UST:
Name: CHASE CHEVROLET CO.
Address: 423 N MADISON
City: STOCKTON
Status: Not reported
Comp Number: 1163
Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported

CHASE CHEVROLET CO. (Continued) **S101592763**

Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001163-000001
Tank Status:	Not reported
Capacity:	250
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	8

Name:	CHASE CHEVROLET CO.
Address:	423 N MADISON
City:	STOCKTON
Status:	Not reported
Comp Number:	1163
Number:	Not reported
Board Of Equalization:	44-024569
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001163-000002
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

Name:	CHASE CHEVROLET CO.
Address:	423 N MADISON
City:	STOCKTON
Status:	Not reported
Comp Number:	1163
Number:	Not reported
Board Of Equalization:	44-024569
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-001163-000003
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	OIL
STG:	PRODUCT
Content:	REGULAR UNLE
Number Of Tanks:	Not reported

Name:	CHASE CHEVROLET CO.
Address:	423 N MADISON
City:	STOCKTON
Status:	Not reported
Comp Number:	1163

CHASE CHEVROLET CO. (Continued) **S101592763**

Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001163-000004
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CHASE CHEVROLET CO.
Address: 423 N MADISON
City: STOCKTON
Status: Not reported
Comp Number: 1163
Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001163-000005
Tank Status: Not reported
Capacity: 2000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CHASE CHEVROLET CO.
Address: 423 N MADISON
City: STOCKTON
Status: Not reported
Comp Number: 1163
Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001163-000006
Tank Status: Not reported
Capacity: 2000
Active Date: Not reported
Tank Use: OIL
STG: PRODUCT
Content: TRANSMISSION
Number Of Tanks: Not reported

Name: CHASE CHEVROLET CO.
Address: 423 N MADISON

CHASE CHEVROLET CO. (Continued) **S101592763**

City: STOCKTON
Status: Not reported
Comp Number: 1163
Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001163-000007
Tank Status: Not reported
Capacity: 5000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CHASE CHEVROLET CO.
Address: 423 N MADISON
City: STOCKTON
Status: Not reported
Comp Number: 1163
Number: Not reported
Board Of Equalization: 44-024569
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-001163-000008
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: UNKNOWN
STG: PRODUCT
Content: Not reported
Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39000319
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2099466605
Mail To: Not reported
Mailing Address: 2431 W MARCH LANE
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95203
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

CHASE CHEVROLET CO. (Continued) **S101592763**

DEED:
Name: NORTH SHORE PROPERTY
Address: 423 N MADISON ST
City,State,Zip: STOCKTON, CA 95202
Envirostor ID: 39750010
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: CERTIFIED O&M - LAND USE RESTRICTIONS ONLY
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

---

184 **CRYSTAL CREAM & BUTTER** **LUST** **S101302694**
NW **404 FREMONT** **Cortese** **N/A**
1/2-1 **STOCKTON, CA 95203** **HIST CORTESE**
0.742 mi. **Notify 65**
3920 ft. **CERS**

Relative: **Lower**

Actual: **12 ft.**

LUST:
Name: CRYSTAL CREAM & BUTTER
Address: 404 FREMONT ST W
City,State,Zip: STOCKTON, CA 95203
Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700029
Global Id: T0607700029
Latitude: 37.9565269
Longitude: -121.2977805
Status: Open - Verification Monitoring
Status Date: 10/16/2018
Case Worker: VJF
RB Case Number: 390041
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: The site is currently owned by the City of Stockton; it is located on West Fremont Street near the area of the Waterfront Hotel, Stockton Arena and Stockton Ballpark. September 1986- One underground storage tank was removed, petroleum hydrocarbon contamination was noted in the soil beneath the tank. October 1986- A site investigation began with the installation of soil borings and groundwater monitoring wells. Some overexcavation of the tank pit area was done. January + July 1987- Additional overexcavations were conducted, final depth of tank pit area 22 feet bsg. January 1991-February 2002- additional borings, groundwater monitoring wells and remediation wells were installed. Site work was halted for the City redevelopment project, and should resume.

LUST:
Global Id: T0607700029
Contact Type: Regional Board Caseworker
Contact Name: VERA FISCHER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

City: RANCHO CORDOVA
Email: vera.fischer@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700029
Action Type: RESPONSE
Date: 06/28/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 07/10/1997
Action: Site Assessment Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 08/12/1996
Action: Site Assessment Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/16/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 02/05/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 11/19/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/23/1987
Action: Soil and Water Investigation Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 10/13/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 03/12/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/08/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: ENFORCEMENT

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Date: 08/31/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 12/22/2009
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 01/11/2010
Action: Meeting

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 12/18/2014
Action: Meeting

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 01/09/2015
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 12/12/2014
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 06/02/2010
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/01/2014
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/10/2011
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 12/23/2014
Action: Email Correspondence

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/19/2017
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 06/21/2016
Action: Staff Letter

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 08/10/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 11/18/1986
Action: Notification - Proposition 65

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 11/09/2011
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 06/27/2018
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 09/18/2018
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 09/10/2018
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 10/21/2019
Action: Staff Letter

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 07/16/2012
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 01/21/2021
Action: Email Correspondence

Global Id: T0607700029
Action Type: Other
Date: 09/15/1986
Action: Leak Discovery

Global Id: T0607700029
Action Type: Other
Date: 09/15/1986
Action: Leak Stopped

Global Id: T0607700029
Action Type: Other

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Date: 07/03/1987
Action: Leak Reported

Global Id: T0607700029
Action Type: RESPONSE
Date: 05/10/2018
Action: Other Workplan - Regulator Responded

Global Id: T0607700029
Action Type: RESPONSE
Date: 07/26/2018
Action: Soil and Water Investigation Workplan - Addendum - Regulator Responded

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 01/14/1991
Action: Notice of Reimbursement

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/30/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700029
Action Type: REMEDIATION
Date: 02/20/2002
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 08/11/2008
Action: Technical Correspondence / Assistance / Other - #08/11/08

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 11/16/2010
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 08/03/2012
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 09/05/2013
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 02/11/2013
Action: File review

Global Id: T0607700029
Action Type: RESPONSE
Date: 02/11/1997
Action: Monitoring Report - Quarterly

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/27/1994
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 08/02/1995
Action: Risk Assessment Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 04/30/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 08/31/2001
Action: Remedial Progress Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 11/20/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 03/17/1994
Action: Risk Assessment Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 03/30/1993
Action: Soil and Water Investigation Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/17/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 04/04/1995
Action: Other Report / Document

Global Id: T0607700029
Action Type: RESPONSE
Date: 12/10/1997
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 02/12/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Date: 05/09/1991
Action: Other Report / Document

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 02/13/2009
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/15/2009
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 07/22/2013
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 05/10/2012
Action: File review

Global Id: T0607700029
Action Type: RESPONSE
Date: 12/21/1999
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 06/12/2000
Action: Site Assessment Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 06/15/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 01/13/1998
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 02/06/1996
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 08/20/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 04/30/2003
Action: Monitoring Report - Quarterly

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Global Id: T0607700029
Action Type: RESPONSE
Date: 11/17/1986
Action: Other Report / Document

Global Id: T0607700029
Action Type: RESPONSE
Date: 09/02/1994
Action: Interim Remedial Action Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 02/13/1996
Action: Soil and Water Investigation Report

Global Id: T0607700029
Action Type: RESPONSE
Date: 10/07/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 05/18/1995
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: RESPONSE
Date: 10/06/1999
Action: Monitoring Report - Quarterly

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 07/21/2009
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 12/17/2014
Action: File review

Global Id: T0607700029
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

LUST:
Global Id: T0607700029
Status: Open - Case Begin Date
Status Date: 09/15/1986

Global Id: T0607700029
Status: Open - Site Assessment
Status Date: 10/07/1986

Global Id: T0607700029
Status: Open - Remediation
Status Date: 02/20/2002

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

Global Id: T0607700029
Status: Open - Site Assessment
Status Date: 07/21/2009

Global Id: T0607700029
Status: Open - Inactive
Status Date: 05/25/2010

Global Id: T0607700029
Status: Open - Inactive
Status Date: 02/11/2013

Global Id: T0607700029
Status: Open - Site Assessment
Status Date: 04/22/2013

Global Id: T0607700029
Status: Open - Verification Monitoring
Status Date: 10/16/2018

LUST REG 5:
Name: CRYSTAL CREAM & BUTTER
Address: 404 FREMONT ST W
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390041
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 4

CORTESE:
Name: CRYSTAL CREAM & BUTTER
Address: 404 FREMONT ST W
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700029
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - VERIFICATION MONITORING
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported

CRYSTAL CREAM & BUTTER (Continued) **S101302694**

WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: CRYSTAL CREAM & BUTTER
edr_fadd1: 404 FREMONT
City,State,Zip: STOCKTON, CA 95203
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390041

NOTIFY 65:
Name: CRYSTAL CREAM & BUTTER
Address: 404 FREMONT ST W
City,State,Zip: STOCKTON, CA 95203
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 11/18/1986
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: CRYSTAL CREAM & BUTTER
Address: 404 FREMONT ST W
City,State,Zip: STOCKTON, CA 95203
Site ID: 206364
CERS ID: T0607700029
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: VERA FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

185
ESE
1/2-1
0.745 mi.
3934 ft.

THOMPSONS AUTO REPAIR & DISMANTLING
945 S PILGRIM ST
STOCKTON, CA 95205

ENVIROSTOR **S101482175**
N/A

Relative:
Higher

Actual:
17 ft.

ENVIROSTOR:

Name:	THOMPSONS AUTO REPAIR & DISMANTLING
Address:	945 S PILGRIM ST
City,State,Zip:	STOCKTON, CA 95205
Facility ID:	39750003
Status:	Refer: Other Agency
Status Date:	11/16/1994
Site Code:	Not reported
Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Sacramento
Assembly:	13
Senate:	05
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported
Latitude:	37.94535
Longitude:	-121.2734
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	39750003
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	04/12/1982
Comments:	FACILITY IDENTIFIED FROM INDUSTRIAL INDEX.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

186
NNW
1/2-1
0.747 mi.
3946 ft.

ANCHOR VILLAGE
133 EAST OAK STREET
STOCKTON, CA 95202

ENVIROSTOR **S120714321**
VCP **N/A**

Relative:
Lower

Actual:
15 ft.

ENVIROSTOR:

Name:	ANCHOR VILLAGE
Address:	133 EAST OAK STREET
City,State,Zip:	STOCKTON, CA 95202
Facility ID:	60002477
Status:	No Further Action
Status Date:	09/19/2017
Site Code:	102331
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	0.7
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Gregory Ruiz
Supervisor:	Fernando A. Amador
Division Branch:	Cleanup Sacramento
Assembly:	, 13
Senate:	, 05
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.95930
Longitude:	-121.2905
APN:	NONE SPECIFIED
Past Use:	VEHICLE MAINTENANCE
Potential COC:	Tetrachloroethylene (PCE
Confirmed COC:	30022-NO
Potential Description:	NMA, SV
Alias Name:	102331
Alias Type:	Project Code (Site Code)
Alias Name:	60002477
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	02/13/2017
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	03/15/2017
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	03/29/2017
Comments:	Not reported

ANCHOR VILLAGE (Continued) **S120714321**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/10/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 09/14/2017
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: ANCHOR VILLAGE
Address: 133 EAST OAK STREET
City,State,Zip: STOCKTON, CA 95202
Facility ID: 60002477
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 0.7
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Gregory Ruiz
Supervisor: Fernando A. Amador
Division Branch: Cleanup Sacramento
Site Code: 102331
Assembly: , 13
Senate: , 05
Special Programs Code: Voluntary Cleanup Program
Status: No Further Action
Status Date: 09/19/2017
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.95930 / -121.2905
APN: NONE SPECIFIED
Past Use: VEHICLE MAINTENANCE
Potential COC: 30022
Confirmed COC: 30022-NO
Potential Description: NMA, SV
Alias Name: 102331
Alias Type: Project Code (Site Code)
Alias Name: 60002477
Alias Type: Envirostor ID Number

ANCHOR VILLAGE (Continued) **S120714321**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	02/13/2017
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	03/15/2017
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	03/29/2017
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/10/2017
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	09/14/2017
Comments:	Not reported

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

187
North
1/2-1
0.752 mi.
3968 ft.

STALLWORTH AUTO DETAIL
602 CALIFORNIA ST N
STOCKTON, CA 95205

LUST **S101302615**
Cortese **N/A**
HIST CORTESE
Notify 65
CERS

Relative:
Higher

Actual:
17 ft.

LUST:

Name:	STALLWORTH AUTO DETAIL
Address:	602 CALIFORNIA ST N
City,State,Zip:	STOCKTON, CA 95205
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700523
Global Id:	T0607700523
Latitude:	37.959658409
Longitude:	-121.286131288

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Status: Open - Remediation
Status Date: 09/15/2010
Case Worker: VJF
RB Case Number: 390675
Local Agency: Not reported
File Location: Regional Board
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: May 1991- Four underground storage tanks, three product and one waste oil, were removed from the site. Soil samples for analysis were collected from beneath the tanks. Laboratory reported petroleum hydrocarbon contamination under the product tank #3 North. February 2000- Site assessment began with the installation of geoprobe soil borings; soil and grab groundwater samples were collected. May 2000 thru March 2008- Groundwater monitoring wells, geoprobe soil borings, CPT soil borings were installed both on and off site to define the plume. The site is not defined. Site remediation has been directed since 2007. Soil Vapor Extraction system began operation 9/10.

LUST:
Global Id: T0607700523
Contact Type: Regional Board Caseworker
Contact Name: VERA J. FISCHER
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: vera.fischer@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700523
Action Type: RESPONSE
Date: 04/07/2006
Action: Site Assessment Report

Global Id: T0607700523
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/27/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 12/01/2009
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/22/2014
Action: File review

Global Id: T0607700523

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Action Type: ENFORCEMENT
Date: 05/16/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/30/2015
Action: Referral to Regional Board

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 01/14/2015
Action: Email Correspondence

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/29/2015
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/05/2014
Action: Site Visit / Inspection / Sampling

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 01/26/2015
Action: Site Visit / Inspection / Sampling

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 02/11/2010
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/28/2010
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/21/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/09/2014
Action: File Review - Closure

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/27/2014
Action: Notification - Public Notice of ROD/RAP/CAP

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/25/2014

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/19/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/27/2014
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/18/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/19/2014
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/15/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 12/29/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/06/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 10/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/29/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/25/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/17/2014
Action: File review

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/05/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 10/07/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 11/30/2010
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/25/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 02/14/2011
Action: File review

Global Id: T0607700523
Action Type: RESPONSE
Date: 10/14/2013
Action: CAP/RAP - Other Report

Global Id: T0607700523
Action Type: RESPONSE
Date: 05/16/2014
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/14/2014
Action: Corrective Action Plan / Remedial Action Plan - Regulator Responded

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/06/1991
Action: Notification - Proposition 65

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/06/1991
Action: Unauthorized Release Form

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 02/26/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Date: 09/08/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 10/11/2010
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 07/28/2011
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/17/2018
Action: Waste Discharge Requirements - #R5-2015-0012-040

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/29/2018
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 10/25/2016
Action: Email Correspondence

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 02/23/2018
Action: Email Correspondence

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 11/14/2019
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: RESPONSE
Date: 08/15/2015
Action: Other Report / Document

Global Id: T0607700523
Action Type: RESPONSE
Date: 04/23/2014
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/14/2014
Action: Corrective Action Plan / Remedial Action Plan - Regulator Responded

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 12/28/2007
Action: Technical Correspondence / Assistance / Other

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/25/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 12/06/2011
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 12/15/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/14/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/05/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 07/13/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 09/06/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/08/2018
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 11/06/2013
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/19/2019
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: ENFORCEMENT

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Date: 06/20/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700523
Action Type: Other
Date: 06/24/1991
Action: Leak Discovery

Global Id: T0607700523
Action Type: Other
Date: 06/24/1991
Action: Leak Stopped

Global Id: T0607700523
Action Type: Other
Date: 08/06/1991
Action: Leak Reported

Global Id: T0607700523
Action Type: RESPONSE
Date: 09/30/2015
Action: Other Workplan

Global Id: T0607700523
Action Type: RESPONSE
Date: 08/15/2015
Action: Correspondence

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/23/1996
Action: Notice of Reimbursement

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/18/2012
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 07/24/2013
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 10/10/2012
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/09/2012
Action: File review

Global Id: T0607700523
Action Type: RESPONSE
Date: 01/03/2009
Action: Well Installation Workplan

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Global Id: T0607700523
Action Type: RESPONSE
Date: 08/15/2015
Action: Other Report / Document

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/08/2008
Action: Staff Letter - #08/08/08

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 09/05/2008
Action: Staff Letter - #09/05/08

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 08/03/2012
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/16/2013
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/10/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: RESPONSE
Date: 08/17/2000
Action: Risk Assessment Report

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/06/2006
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 12/10/2004
Action: Other Report / Document

Global Id: T0607700523
Action Type: RESPONSE
Date: 10/30/2000
Action: Site Assessment Report

Global Id: T0607700523
Action Type: RESPONSE
Date: 11/14/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Date: 05/06/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/21/2002
Action: Other Report / Document

Global Id: T0607700523
Action Type: RESPONSE
Date: 11/26/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 11/07/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 05/10/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/21/2002
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 07/11/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 05/24/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 11/14/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: REMEDIATION
Date: 07/17/2007
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/19/2008
Action: Technical Correspondence / Assistance / Other - #06/19/2008

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/06/2012
Action: Technical Correspondence / Assistance / Other

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 09/05/2013
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 09/05/2013
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 11/26/2013
Action: Staff Letter

Global Id: T0607700523
Action Type: RESPONSE
Date: 02/25/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 08/17/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 01/11/2001
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 01/15/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 01/12/2004
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 03/24/2005
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 03/07/2003
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: RESPONSE
Date: 10/13/2000
Action: Monitoring Report - Quarterly

Global Id: T0607700523
Action Type: REMEDIATION

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Date: 05/29/2012
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607700523
Action Type: REMEDIATION
Date: 09/14/2010
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 01/22/2009
Action: Staff Letter - #01/22/2009

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 05/18/2009
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 07/01/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 06/16/2014
Action: File review

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 03/24/2014
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 07/07/2015
Action: Staff Letter

Global Id: T0607700523
Action Type: ENFORCEMENT
Date: 04/29/2014
Action: Technical Correspondence / Assistance / Other

LUST:
Global Id: T0607700523
Status: Open - Case Begin Date
Status Date: 06/24/1991

Global Id: T0607700523
Status: Open - Site Assessment
Status Date: 06/24/1991

Global Id: T0607700523
Status: Open - Site Assessment
Status Date: 06/15/2004

Global Id: T0607700523

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Status: Open - Site Assessment
Status Date: 01/20/2006

Global Id: T0607700523
Status: Open - Site Assessment
Status Date: 04/18/2007

Global Id: T0607700523
Status: Open - Remediation
Status Date: 07/17/2007

Global Id: T0607700523
Status: Open - Site Assessment
Status Date: 02/05/2008

Global Id: T0607700523
Status: Open - Remediation
Status Date: 03/13/2008

Global Id: T0607700523
Status: Open - Site Assessment
Status Date: 03/13/2008

Global Id: T0607700523
Status: Open - Remediation
Status Date: 09/15/2010

LUST REG 5:
Name: STALLWORTH AUTO DETAIL
Address: 602 CALIFORNIA ST N
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 390675
Case Type: Drinking Water Aquifer affected
Substance: Not reported
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 6

CORTESE:
Name: STALLWORTH AUTO DETAIL
Address: 602 CALIFORNIA ST N
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700523
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - REMEDIATION
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported

STALLWORTH AUTO DETAIL (Continued) **S101302615**

Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	STALLWORTH AUTO DETAIL
edr_fadd1:	602 CALIFORNIA
City,State,Zip:	STOCKTON, CA 95205
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390675

NOTIFY 65:

Name:	STALLWORTH AUTO DETAIL
Address:	602 CALIFORNIA ST N
City,State,Zip:	STOCKTON, CA 95205
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	08/06/1991
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	STALLWORTH AUTO DETAIL
Address:	602 CALIFORNIA ST N
City,State,Zip:	STOCKTON, CA 95205
Site ID:	200334
CERS ID:	T0607700523
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	VERA J. FISCHER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AD188 **MORITA BROTHERS** **LUST** **S104162962**
SE **814 CHARTER** **Cortese** **N/A**
1/2-1 **STOCKTON, CA 95206** **HIST CORTESE**
0.758 mi. **Notify 65**
4001 ft. **Site 2 of 2 in cluster AD** **CERS**

Relative: Higher

Actual: 18 ft.

LUST:

Name:	MORITA BROTHERS
Address:	814 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	SAN JOAQUIN COUNTY
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700542
Global Id:	T0607700542
Latitude:	37.9403862
Longitude:	-121.2767128
Status:	Completed - Case Closed
Status Date:	08/18/2010
Case Worker:	Not reported
RB Case Number:	390703
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	1061
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	12/27/1991, four USTs removed. 2/18/1992, UAR and Prop 65 notifications completed. 3/25/1992, seven soil borings, TH-1 through TH-7, advanced on site. 4/2/1992, NOR issued to Frank Morita. 9/29,30/1992, MW-1, MW-2 and MW-3 installed. Between 9/1999 and 12/2003 16 additional monitoring wells installed (19 total MWs). 3/31/1993 and 5/17/1993, two phases of overexcavation of former tank pit. 4/29/2008, Risk evaluation and soil &soil gas investigation report issued. 2/05/2009, the EHD concurred that the risk and hazard of vapor intrusion was minimal. 5/20/2009, the EHD the site status to Regional Board for possible closure consideration. 9/10/2009, site consultant issued Site Closure Summary Report recommending site closure. 10/29/2009, the EHD sent the 30-day notification of site closure to the Central Valley Regional Water Quality Control Board. 11/18/2009; the Reional Board issued a concurrence letter for site closure. 12/01/2009, the EHD issued letter notifying the RPs that site closure was pending, directing destruction of the site monitoring wells, and requesting an updated certification of Record Fee Title Owners. 4/24/2010 through 4/28/2010; EHD witnessed destruction of 17 groundwater monitoring wells. Two wells were transferred to RP for the 749 E. Charter Way site. 8/16/2010; the EHD received by email a properly signed hazardous waste manifest for disposal of investigation derived wastes. 8/18/2010; the EHD issued a No Further Action Required Letter closing the site and updated GeoTracker.

LUST:

Global Id:	T0607700542
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

MORITA BROTHERS (Continued) **S104162962**

LUST:

Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	05/29/1992
Action:	* Corrective Action Orders
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	02/24/1993
Action:	* Corrective Action Orders
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	10/28/2009
Action:	File review
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	03/22/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	12/01/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	08/18/2010
Action:	Closure/No Further Action Letter
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	05/03/2000
Action:	Staff Letter
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	07/06/2000
Action:	* Corrective Action Orders
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	02/18/1992
Action:	Notification - Proposition 65
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	02/18/1992
Action:	Unauthorized Release Form
Global Id:	T0607700542
Action Type:	ENFORCEMENT
Date:	06/29/2007
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607700542

MORITA BROTHERS (Continued) **S104162962**

Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 07/12/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700542
Action Type: Other
Date: 02/18/1992
Action: Leak Discovery

Global Id: T0607700542
Action Type: Other
Date: 02/18/1992
Action: Leak Reported

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 05/03/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700542
Action Type: REMEDIATION
Date: 03/31/1993
Action: Excavation

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 02/05/1993
Action: Meeting

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 07/27/1998
Action: * Corrective Action Orders

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 11/24/2004
Action: * Corrective Action Orders

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 05/03/2000
Action: * Corrective Action Orders

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 02/06/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 04/24/2002

MORITA BROTHERS (Continued) **S104162962**

Action: * Corrective Action Orders

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 09/06/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 04/02/1992
Action: Notice of Reimbursement

Global Id: T0607700542
Action Type: ENFORCEMENT
Date: 07/20/2009
Action: Staff Letter

LUST:
Global Id: T0607700542
Status: Open - Case Begin Date
Status Date: 02/18/1992

Global Id: T0607700542
Status: Open - Site Assessment
Status Date: 03/25/1992

Global Id: T0607700542
Status: Open - Site Assessment
Status Date: 02/24/1993

Global Id: T0607700542
Status: Open - Remediation
Status Date: 04/01/1993

Global Id: T0607700542
Status: Completed - Case Closed
Status Date: 08/18/2010

LUST REG 5:
Name: MORITA BROTHERS
Address: 814 CHARTER WAY E
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390703
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

CORTESE:
Name: MORITA BROTHERS
Address: 814 CHARTER WAY E

MORITA BROTHERS (Continued) **S104162962**

City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700542
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	MORITA BROTHERS
edr_fadd1:	814 CHARTER
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390703

NOTIFY 65:

Name:	MORITA BROTHERS
Address:	814 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	02/18/1992
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	MORITA BROTHERS
Address:	814 CHARTER WAY E
City,State,Zip:	STOCKTON, CA 95206
Site ID:	256093
CERS ID:	T0607700542
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker

MORITA BROTHERS (Continued) **S104162962**

Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

189
NNW
1/2-1
0.780 mi.
4119 ft.

GENE GABBARD INC
640 EL DORADO ST
STOCKTON, CA 95201

LUST **S103286284**
Cortese **N/A**
HIST CORTESE
Notify 65
CERS

Relative:
Lower

Actual:
15 ft.

LUST:

Name:	GENE GABBARD INC
Address:	640 EL DORADO ST
City,State,Zip:	STOCKTON, CA 95201
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700825
Global Id:	T0607700825
Latitude:	37.959425483733
Longitude:	-121.291208267212
Status:	Completed - Case Closed
Status Date:	08/10/2009
Case Worker:	AMB
RB Case Number:	391005
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	1090
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

LUST:

Global Id:	T0607700825
Contact Type:	Regional Board Caseworker
Contact Name:	Alan Buehler
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 SUN CENTER DRIVE #200
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607700825
Action Type:	ENFORCEMENT
Date:	04/10/1998
Action:	Unauthorized Release Form

Global Id:	T0607700825
Action Type:	ENFORCEMENT
Date:	05/17/2000
Action:	Notice of Responsibility

GENE GABBARD INC (Continued) **S103286284**

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 05/19/2000
Action: Notification - Fee Title Owners Notice

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 04/10/1998
Action: Notification - Proposition 65

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 06/12/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 03/18/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 01/31/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 11/19/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700825
Action Type: Other
Date: 03/26/1997
Action: Leak Discovery

Global Id: T0607700825
Action Type: Other
Date: 03/26/1997
Action: Leak Stopped

Global Id: T0607700825
Action Type: Other
Date: 04/10/1998
Action: Leak Reported

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 06/13/2008
Action: Referral to Regional Board

Global Id: T0607700825
Action Type: RESPONSE
Date: 10/10/2008
Action: Other Report / Document

Global Id: T0607700825
Action Type: RESPONSE

GENE GABBARD INC (Continued) **S103286284**

Date: 01/05/2009
Action: Fact Sheets - Public Participation

Global Id: T0607700825
Action Type: RESPONSE
Date: 01/30/2009
Action: Fact Sheets - Public Participation

Global Id: T0607700825
Action Type: RESPONSE
Date: 02/20/2009
Action: Other Report / Document

Global Id: T0607700825
Action Type: RESPONSE
Date: 11/10/2008
Action: Other Report / Document

Global Id: T0607700825
Action Type: RESPONSE
Date: 08/10/2008
Action: Other Report / Document

Global Id: T0607700825
Action Type: RESPONSE
Date: 10/30/2008
Action: Monitoring Report - Quarterly

Global Id: T0607700825
Action Type: RESPONSE
Date: 09/10/2008
Action: Other Report / Document

Global Id: T0607700825
Action Type: RESPONSE
Date: 06/30/2009
Action: Well Destruction Report

Global Id: T0607700825
Action Type: RESPONSE
Date: 01/30/2009
Action: Well Destruction Workplan

Global Id: T0607700825
Action Type: REMEDIATION
Date: 09/21/2001
Action: Free Product Removal

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 10/20/2008
Action: Verbal Enforcement

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 09/09/2008
Action: Staff Letter

GENE GABBARD INC (Continued) **S103286284**

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 02/03/2009
Action: Staff Letter

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 12/01/2008
Action: Staff Letter

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 02/23/2009
Action: Staff Letter

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 01/02/2009
Action: Staff Letter

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 06/02/1998
Action: Notice of Reimbursement

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 08/01/2008
Action: 13267 Requirement

Global Id: T0607700825
Action Type: ENFORCEMENT
Date: 07/15/2009
Action: Closure/No Further Action Letter

LUST:
Global Id: T0607700825
Status: Open - Case Begin Date
Status Date: 03/26/1997

Global Id: T0607700825
Status: Open - Site Assessment
Status Date: 03/26/1997

Global Id: T0607700825
Status: Open - Remediation
Status Date: 09/21/2001

Global Id: T0607700825
Status: Open - Site Assessment
Status Date: 05/23/2003

Global Id: T0607700825
Status: Open - Verification Monitoring
Status Date: 09/25/2008

Global Id: T0607700825

GENE GABBARD INC (Continued) **S103286284**

Status: Completed - Case Closed
Status Date: 07/15/2009

Global Id: T0607700825
Status: Completed - Case Closed
Status Date: 08/10/2009

LUST REG 5:
Name: GENE GABBARD INC
Address: 640 EL DORADO ST
City: STOCKTON
Region: 5
Status: Pollution Characterization
Case Number: 391005
Case Type: Drinking Water Aquifer affected
Substance: WASTE OIL
Staff Initials: JLB
Lead Agency: Regional
Program: LUST
MTBE Code: 0

CORTESE:
Name: GENE GABBARD INC
Address: 640 EL DORADO ST
City,State,Zip: STOCKTON, CA 95201
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700825
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: GENE GABBARD INC
edr_fadd1: 640 EL DORADO
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 391005

GENE GABBARD INC (Continued) **S103286284**

NOTIFY 65:

Name:	GENE GABBARD INC
Address:	640 EL DORADO ST
City,State,Zip:	STOCKTON, CA 95201
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	04/10/1998
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Name:	GENE GABBARD INC
Address:	640 EL DORADO ST
City,State,Zip:	STOCKTON, CA 95201
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	GENE GABBARD INC
Address:	640 EL DORADO ST
City,State,Zip:	STOCKTON, CA 95201
Site ID:	223542
CERS ID:	T0607700825
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 SUN CENTER DRIVE #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

AF190 **ARCO #2168 (FORMER)** **LUST** **S101302639**
SSW **441 CHARTER WAY W** **Cortese** **N/A**
1/2-1 **STOCKTON, CA 95206** **HIST CORTESE**
0.822 mi. **Notify 65**
4341 ft. **Site 1 of 2 in cluster AF** **CERS**

Relative: LUST:
Lower

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206

Actual:
12 ft.

ARCO #2168 (FORMER) (Continued) **S101302639**

Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700508
Global Id:	T0607700508
Latitude:	37.93795371
Longitude:	-121.2936061
Status:	Open - Remediation
Status Date:	02/26/2013
Case Worker:	AMB
RB Case Number:	390657
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Benzene, Ethylbenzene, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Toluene, Xylene
Site History:	All workplans, monitoring reports, and associated remedial reports are submitted to ARCO site as CPA combined reports by ARCO, 441 W. Charter Way for Former Texaco, 440 W. Charter Way; Columbo/Toscana, 1444 S. Lincoln St.; and Chevron, 508 W. Charter Way. See 441 W. Charter Way for electronic copy. This site operated as a retail gasoline station until 1995. The underground storage tanks were removed in 1996, petroleum contamination was noted in the soil beneath the tanks. A site investigation began in July 1991; groundwater monitoring wells and soil vapor extraction wells were installed through 2006. SVE remediation was conducted from January 1997 through February 1998; estimate was that 1,600 gallons of petroleum hydrocarbons were removed. During 2005 nearly all groundwater and remediation wells were destroyed to allow for redevelopment of the site, and reinstalled in different locations. Additional air sparging wells were also installed. Soil vapor extraction/air sparging remediation was started in October 2006; in March 2009 pulse operation began, two weeks on two weeks off.

LUST:

Global Id:	T0607700508
Contact Type:	Regional Board Caseworker
Contact Name:	ALAN M. BUEHLER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Dr
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	9164644615

LUST:

Global Id:	T0607700508
Action Type:	RESPONSE
Date:	04/15/2011
Action:	Other Report / Document
Global Id:	T0607700508
Action Type:	RESPONSE
Date:	10/15/2011
Action:	Other Report / Document
Global Id:	T0607700508
Action Type:	RESPONSE

ARCO #2168 (FORMER) (Continued) **S101302639**

Date: 05/30/2011
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700508
Action Type: RESPONSE
Date: 06/19/2012
Action: CAP/RAP - Other Report

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/30/2015
Action: Monitoring Report - Other

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/26/2016
Action: Other Report / Document

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/01/2009
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 09/15/2009
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 09/17/2014
Action: Staff Letter

Global Id: T0607700508
Action Type: RESPONSE
Date: 11/30/2011
Action: Other Report / Document

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 04/15/2012
Action: Monitoring Report - Other

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/02/2012
Action: Correspondence

ARCO #2168 (FORMER) (Continued) **S101302639**

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 02/26/2010
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/17/2010
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/04/2010
Action: Referral to Regional Board

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 05/04/2010
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 06/22/2010
Action: Meeting

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 07/16/2014
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/04/2015
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 10/30/2014
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 05/20/2014
Action: Staff Letter

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Other

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/30/2012
Action: Other Report / Document

Global Id: T0607700508
Action Type: ENFORCEMENT

ARCO #2168 (FORMER) (Continued) **S101302639**

Date: 06/01/2011
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/30/2011
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 07/18/2010
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 01/25/2011
Action: Meeting

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 03/20/2012
Action: Pilot Study/ Treatability Report - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 04/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 09/15/2011
Action: Well Destruction Workplan - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 06/27/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 02/17/2011
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/16/2011
Action: Meeting

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 09/26/2005
Action: Staff Letter

ARCO #2168 (FORMER) (Continued) **S101302639**

Global Id: T0607700508
Action Type: RESPONSE
Date: 12/19/2012
Action: Other Report / Document - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 06/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 05/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/30/2013
Action: Monitoring Report - Other - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 06/30/2014
Action: Other Report / Document - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/16/2014
Action: Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/18/1992
Action: Notice of Reimbursement

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 04/19/1993
Action: Notification - Proposition 65

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/16/1991
Action: Notification - Proposition 65

Global Id: T0607700508
Action Type: ENFORCEMENT

ARCO #2168 (FORMER) (Continued) **S101302639**

Date: 04/29/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 04/12/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 10/13/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 09/16/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/17/2011
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 10/10/2005
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/30/2015
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/05/2016
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/14/2016
Action: Clean Up Fund - Letter to RP

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 01/31/2019
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/26/2020
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 01/02/2020
Action: Staff Letter

ARCO #2168 (FORMER) (Continued) **S101302639**

Global Id: T0607700508
Action Type: RESPONSE
Date: 04/30/2014
Action: Monitoring Report - Other

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/09/2015
Action: Correspondence

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/31/2014
Action: Other Workplan - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2014
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 06/10/2016
Action: Other Workplan - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 02/29/2016
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607700508
Action Type: RESPONSE
Date: 02/29/2016
Action: Other Workplan - Regulator Responded

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 07/10/2012
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 02/16/2012
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 10/02/2020
Action: Staff Letter

Global Id: T0607700508
Action Type: Other
Date: 05/01/1992
Action: Leak Began

Global Id: T0607700508
Action Type: Other

ARCO #2168 (FORMER) (Continued) **S101302639**

Date: 08/15/1991
Action: Leak Discovery

Global Id: T0607700508
Action Type: Other
Date: 02/07/1996
Action: Leak Stopped

Global Id: T0607700508
Action Type: Other
Date: 08/15/1991
Action: Leak Reported

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 05/01/2010
Action: Correspondence

Global Id: T0607700508
Action Type: RESPONSE
Date: 05/20/2015
Action: Correspondence

Global Id: T0607700508
Action Type: RESPONSE
Date: 10/30/2015
Action: Other Report / Document

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/28/1991
Action: Notice of Reimbursement

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 03/26/2013
Action: Meeting

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 04/23/2013
Action: Staff Letter

ARCO #2168 (FORMER) (Continued) **S101302639**

Global Id: T0607700508
Action Type: RESPONSE
Date: 02/15/2011
Action: Well Installation Workplan

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/14/2011
Action: Conceptual Site Model

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: REMEDIATION
Date: 08/30/1997
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700508
Action Type: REMEDIATION
Date: 11/01/2006
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700508
Action Type: REMEDIATION
Date: 01/01/2007
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 10/11/2010
Action: Verbal Enforcement

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 11/23/2010
Action: Meeting

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/20/2012
Action: Staff Letter

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/02/2012
Action: Meeting

Global Id: T0607700508
Action Type: RESPONSE
Date: 08/30/2010
Action: Correspondence

Global Id: T0607700508
Action Type: RESPONSE

ARCO #2168 (FORMER) (Continued) **S101302639**

Date: 11/30/2010
Action: Monitoring Report - Other

Global Id: T0607700508
Action Type: RESPONSE
Date: 07/30/2010
Action: Other Workplan

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 12/26/2008
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 09/12/2008
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 04/08/2009
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 05/15/2013
Action: Staff Letter

Global Id: T0607700508
Action Type: RESPONSE
Date: 01/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607700508
Action Type: RESPONSE
Date: 03/15/2011
Action: Other Workplan

Global Id: T0607700508
Action Type: RESPONSE
Date: 02/28/2011
Action: Verbal Communication

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 05/08/2009
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/03/2009
Action: File review

ARCO #2168 (FORMER) (Continued) **S101302639**

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 05/28/2009
Action: File review

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 07/08/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700508
Action Type: ENFORCEMENT
Date: 08/24/2009
Action: File review

LUST:
Global Id: T0607700508
Status: Open - Case Begin Date
Status Date: 08/15/1991

Global Id: T0607700508
Status: Open - Site Assessment
Status Date: 04/27/1992

Global Id: T0607700508
Status: Open - Remediation
Status Date: 02/20/1997

Global Id: T0607700508
Status: Open - Site Assessment
Status Date: 08/12/2000

Global Id: T0607700508
Status: Open - Remediation
Status Date: 11/01/2006

Global Id: T0607700508
Status: Open - Verification Monitoring
Status Date: 09/30/2011

Global Id: T0607700508
Status: Open - Remediation
Status Date: 02/26/2013

Global Id: T0607700508
Status: Open - Verification Monitoring
Status Date: 02/26/2013

LUST REG 5:
Name: ARCO #2168 (FORMER)
Address: 441 CHARTER WAY W
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 390657

ARCO #2168 (FORMER) (Continued) **S101302639**

Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

CORTESE:

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607700508
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	OPEN - REMEDIATION
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	ARCO #2168 (FORMER)
edr_fadd1:	441 CHARTER
City,State,Zip:	STOCKTON, CA 95206
Region:	CORTESE
Facility County Code:	39
Reg By:	LTNKA
Reg Id:	390657

NOTIFY 65:

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	04/19/1993
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

ARCO #2168 (FORMER) (Continued) **S101302639**

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	08/16/1991
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	ARCO #2168 (FORMER)
Address:	441 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Site ID:	189607
CERS ID:	T0607700508
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Dr
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644615

AF191 **TEXACO** **LUST** **S104164483**
SSW **440 CHARTER** **Cortese** **N/A**
1/2-1 **STOCKTON, CA 95206** **HIST CORTESE**
0.830 mi. **Notify 65**
4382 ft. **Site 2 of 2 in cluster AF** **CERS**

Relative:
Lower

Actual:
12 ft.

LUST:

Name:	FORMER TEXACO STATION
Address:	440 CHARTER WAY W
City,State,Zip:	STOCKTON, CA 95206
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site

TEXACO (Continued) **S104164483**

Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700195
Global Id:	T0607700195
Latitude:	37.937317488
Longitude:	-121.293510358
Status:	Open - Remediation
Status Date:	02/13/2013
Case Worker:	AMB
RB Case Number:	390268
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Benzene, Ethylbenzene, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Toluene, Xylene
Site History:	All workplans, monitoring reports, and associated remedial reports are submitted to ARCO site as CPA combined reports by ARCO, 441 W. Charter Way for Former Texaco, 440 W. Charter Way; Columbo/Toscana, 1444 S. Lincoln St.; and Chevron, 508 W. Charter Way. See 441 W. Charter Way for electronic copy. October 1988- Soil contaminated with petroleum hydrocarbons was discovered during dispenser replacement activities. Minor overexcavation was performed. May 1989-May 1990- Soil borings and groundwater monitoring wells were installed. April 1992- Soil vapor extraction wells were installed and a vapor extraction pilot test was performed. September 1993- Additional groundwater montoring wells were installed. June 1999- Four underground storage tanks were removed from the site. Nov 2000, Nov 2001+ Sept 2004- Cone penetrometor test borings were installed. August 2002- Deep groundwater montioring wells were installed. 3/4/2010- Case transferred to Regional Board for commingled plume account. October 2005- Additional deep groundwater monitoring wells were installed. October 2007- Additional shallow and deep groundwater monitoring wells were installed. The site is still not defined; a work plan for additional investigation was approved for implementation by the EHD on March 24, 2009. Shell is trying to get offsite access.

LUST:

Global Id:	T0607700195
Contact Type:	Regional Board Caseworker
Contact Name:	ALAN M. BUEHLER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Dr
City:	RANCHO CORDOVA
Email:	alan.buehler@waterboards.ca.gov
Phone Number:	9164644615

LUST:

Global Id:	T0607700195
Action Type:	RESPONSE
Date:	05/30/2011
Action:	CAP/RAP - Feasibility Study Report

Global Id:	T0607700195
Action Type:	RESPONSE
Date:	02/15/2011
Action:	Soil and Water Investigation Workplan

TEXACO (Continued) **S104164483**

Global Id: T0607700195
Action Type: RESPONSE
Date: 04/15/2011
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/15/2011
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 06/19/2012
Action: CAP/RAP - Other Report

Global Id: T0607700195
Action Type: RESPONSE
Date: 03/20/2012
Action: Pilot Study/ Treatability Report

Global Id: T0607700195
Action Type: RESPONSE
Date: 02/29/2016
Action: Other Workplan

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/30/2016
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 02/29/2016
Action: Soil and Water Investigation Workplan

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/26/2009
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 08/14/2009
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/01/2009
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/28/2009
Action: File review

Global Id: T0607700195
Action Type: RESPONSE

TEXACO (Continued) **S104164483**

Date: 01/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/17/2010
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/04/2010
Action: Referral to Regional Board

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 05/04/2010
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 06/22/2010
Action: Meeting

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/30/2012
Action: Other Report / Document

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/25/2011
Action: Meeting

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/16/2011
Action: Meeting

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 08/18/2010
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 05/20/2014
Action: Staff Letter

TEXACO (Continued) **S104164483**

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/03/2014
Action: Staff Letter

Global Id: T0607700195
Action Type: RESPONSE
Date: 04/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/17/2011
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 02/17/2011
Action: Staff Letter

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 12/19/2012
Action: Other Report / Document - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE
Date: 06/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE
Date: 05/15/2013
Action: Remedial Progress Report - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/30/2013
Action: Monitoring Report - Other - Regulator Responded

Global Id: T0607700195
Action Type: RESPONSE

TEXACO (Continued) **S104164483**

Date: 07/30/2014
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 05/10/1999
Action: Notification - Fee Title Owners Notice

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/28/1999
Action: Notification - Proposition 65

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 06/25/1999
Action: Unauthorized Release Form

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/10/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/24/2006
Action: Notice of Responsibility

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/13/2010
Action: Site Visit / Inspection / Sampling

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/05/2016
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/30/2015
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/31/2019
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/14/2016
Action: Clean Up Fund - Letter to RP

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/26/2020
Action: Staff Letter

TEXACO (Continued) **S104164483**

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/02/2020
Action: Staff Letter

Global Id: T0607700195
Action Type: RESPONSE
Date: 04/30/2014
Action: Monitoring Report - Other

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/30/2015
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/11/2010
Action: Verbal Enforcement

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 11/19/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/02/2020
Action: Staff Letter

Global Id: T0607700195
Action Type: Other
Date: 10/27/1988
Action: Leak Began

Global Id: T0607700195
Action Type: Other
Date: 10/27/1988
Action: Leak Discovery

Global Id: T0607700195
Action Type: Other
Date: 10/27/1988
Action: Leak Stopped

Global Id: T0607700195
Action Type: Other

TEXACO (Continued) **S104164483**

Date: 10/27/1988
Action: Leak Reported

Global Id: T0607700195
Action Type: RESPONSE
Date: 05/01/2010
Action: Correspondence

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 04/30/2010
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/09/2015
Action: Correspondence

Global Id: T0607700195
Action Type: RESPONSE
Date: 06/30/2014
Action: Other Report / Document

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 05/07/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/27/1988
Action: Unauthorized Release Form

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 05/15/2013
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 12/20/2012
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 07/10/2012
Action: Staff Letter

TEXACO (Continued) **S104164483**

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/14/2011
Action: Other Report / Document

Global Id: T0607700195
Action Type: RESPONSE
Date: 05/20/2015
Action: Correspondence

Global Id: T0607700195
Action Type: REMEDIATION
Date: 01/30/1996
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 04/23/2013
Action: Staff Letter

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 08/02/2012
Action: Meeting

Global Id: T0607700195
Action Type: RESPONSE
Date: 11/30/2010
Action: Monitoring Report - Other

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: RESPONSE
Date: 07/30/2010
Action: Other Workplan

Global Id: T0607700195
Action Type: RESPONSE
Date: 10/30/2015
Action: Monitoring Report - Other

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/02/2008
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 06/19/2008
Action: Technical Correspondence / Assistance / Other - #06/19/2008

Global Id: T0607700195
Action Type: ENFORCEMENT

TEXACO (Continued) **S104164483**

Date: 05/18/2009
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/14/2009
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/24/2009
Action: Staff Letter - #03/24/2009

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/26/2013
Action: Meeting

Global Id: T0607700195
Action Type: RESPONSE
Date: 01/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 10/11/2010
Action: Verbal Enforcement

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 01/14/1991
Action: Notice of Reimbursement

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 04/21/2009
Action: File review

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700195
Action Type: ENFORCEMENT
Date: 03/04/2015
Action: Staff Letter

LUST:
Global Id: T0607700195
Status: Open - Case Begin Date
Status Date: 10/27/1988

Global Id: T0607700195
Status: Open - Site Assessment
Status Date: 05/30/1989

TEXACO (Continued) **S104164483**

Global Id: T0607700195
Status: Open - Remediation
Status Date: 08/30/1995

Global Id: T0607700195
Status: Open - Verification Monitoring
Status Date: 03/30/1998

Global Id: T0607700195
Status: Open - Site Assessment
Status Date: 08/26/2002

Global Id: T0607700195
Status: Open - Verification Monitoring
Status Date: 05/26/2011

Global Id: T0607700195
Status: Open - Remediation
Status Date: 02/13/2013

LUST REG 5:
Name: FORMER TEXACO STATION
Address: 440 CHARTER WAY W
City: STOCKTON
Region: 5
Status: Pollution Characterization
Case Number: 390268
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 3

CORTESE:
Name: FORMER TEXACO STATION
Address: 440 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700195
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - REMEDIATION
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported

TEXACO (Continued) **S104164483**

WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: TEXACO
edr_fadd1: 440 CHARTER
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390268

NOTIFY 65:
Name: FORMER TEXACO STATION
Address: 440 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 12/28/1999
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: FORMER TEXACO STATION
Address: 440 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: FORMER TEXACO STATION
Address: 440 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Site ID: 253517
CERS ID: T0607700195
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA

TEXACO (Continued) **S104164483**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

192
NNE
1/2-1
0.847 mi.
4471 ft.

Relative:
Higher

Actual:
19 ft.

UNION ICE CORP
425 UNION ST N
STOCKTON, CA 95205

ENVIROSTOR **S101302847**
LUST **N/A**
VCP
Cortese
HIST CORTESE
CERS

ENVIROSTOR:
Name: PG&E NORTH UNION STREET
Address: 425 NORTH UNION STREET
City,State,Zip: STOCKTON, CA 95205
Facility ID: 60001427
Status: No Further Action
Status Date: 10/22/2014
Site Code: 102106
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 0.25
NPL: NO
Regulatory Agencies: SMBRP, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Program Manager: Dean Wright
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Assembly: 13
Senate: 05
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.95935
Longitude: -121.2781
APN: NONE SPECIFIED
Past Use: TRANSFORMER REPAIR
Potential COC: Polychlorinated biphenyls (PCBs
Confirmed COC: Polychlorinated biphenyls (PCBs
Potential Description: SOIL
Alias Name: PG&E
Alias Type: Alternate Name
Alias Name: 102106
Alias Type: Project Code (Site Code)
Alias Name: 60001427
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/05/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

UNION ICE CORP (Continued) **S101302847**

Completed Document Type: Site Characterization Workplan
Completed Date: 04/04/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 08/28/2013
Comments: Field work complete.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 10/01/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 06/06/2014
Comments: Accepted Work Plan for Offsite Soil Investigation as Final.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 08/14/2011
Comments: Meeting held as scheduled.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/04/2011
Comments: Final signed VCA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/04/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/01/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2013
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported

UNION ICE CORP (Continued) **S101302847**

Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST:
Name: UNION ICE CORP
Address: 425 UNION ST N
City,State,Zip: STOCKTON, CA 95205
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700342
Global Id: T0607700342
Latitude: 37.9591869
Longitude: -121.277942
Status: Completed - Case Closed
Status Date: 11/15/1999
Case Worker: Not reported
RB Case Number: 390437
Local Agency: Not reported
File Location: Not reported
Local Case Number: 241434
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

LUST:
Global Id: T0607700342
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700342
Action Type: Other
Date: 09/22/1989
Action: Leak Discovery

Global Id: T0607700342
Action Type: Other
Date: 10/26/1989
Action: Leak Reported

LUST:
Global Id: T0607700342
Status: Open - Case Begin Date
Status Date: 09/22/1989

Global Id: T0607700342
Status: Open - Site Assessment
Status Date: 10/26/1989

UNION ICE CORP (Continued) **S101302847**

Global Id: T0607700342
Status: Completed - Case Closed
Status Date: 11/15/1999

LUST REG 5:
Name: UNION ICE CORP
Address: 425 UNION ST N
City: STOCKTON
Region: 5
Status: Case Closed
Case Number: 390437
Case Type: Drinking Water Aquifer affected
Substance: WASTE OIL
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: N/A

VCP:
Name: PG&E NORTH UNION STREET
Address: 425 NORTH UNION STREET
City,State,Zip: STOCKTON, CA 95205
Facility ID: 60001427
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 0.25
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Dean Wright
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Site Code: 102106
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: No Further Action
Status Date: 10/22/2014
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.95935 / -121.2781
APN: NONE SPECIFIED
Past Use: TRANSFORMER REPAIR
Potential COC: 30018
Confirmed COC: 30018
Potential Description: SOIL
Alias Name: PG&E
Alias Type: Alternate Name
Alias Name: 102106
Alias Type: Project Code (Site Code)
Alias Name: 60001427
Alias Type: Envirostor ID Number

UNION ICE CORP (Continued) **S101302847**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	05/05/2011
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Workplan
Completed Date:	04/04/2013
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	08/28/2013
Comments:	Field work complete.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Report
Completed Date:	10/01/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Workplan
Completed Date:	06/06/2014
Comments:	Accepted Work Plan for Offsite Soil Investigation as Final.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	08/14/2011
Comments:	Meeting held as scheduled.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	03/04/2011
Comments:	Final signed VCA.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/04/2012
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/01/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

UNION ICE CORP (Continued) **S101302847**

Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2013
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

CORTESE:
Name: UNION ICE CORP
Address: 425 UNION ST N
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700342
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: UNION ICE CORP
edr_fadd1: 425 UNION
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 390437

CERS:
Name: UNION ICE CORP
Address: 425 UNION ST N
City,State,Zip: STOCKTON, CA 95205
Site ID: 238650
CERS ID: T0607700342
CERS Description: Leaking Underground Storage Tank Cleanup Site

UNION ICE CORP (Continued) **S101302847**

Affiliation:
- Affiliation Type Desc: Regional Board Caseworker
- Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
- Entity Title: Not reported
- Affiliation Address: 11020 SUN CENTER DRIVE #200
- Affiliation City: RANCHO CORDOVA
- Affiliation State: CA
- Affiliation Country: Not reported
- Affiliation Zip: Not reported
- Affiliation Phone: Not reported

---

193 SSW 1/2-1 0.856 mi. 4518 ft. **THE TRANSMISSION STORE** **LUST S102438909**
515 CHARTER WAY W **Cortese N/A**
STOCKTON, CA 95206 **HIST CORTESE**
Notify 65
CERS

Relative: Lower
Actual: 12 ft.

LUST:
- Name: THE TRANSMISSION STORE
- Address: 515 CHARTER WAY W
- City,State,Zip: STOCKTON, CA 95206
- Lead Agency: CENTRAL VALLEY RWQCB (REGION 5S)
- Case Type: LUST Cleanup Site
- Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700717
- Global Id: T0607700717
- Latitude: 37.9376720657987
- Longitude: -121.294172907275
- Status: Open - Remediation
- Status Date: 06/02/2017
- Case Worker: AMB
- RB Case Number: 390891
- Local Agency: Not reported
- File Location: Regional Board
- Local Case Number: Not reported
- Potential Media Affect: Aquifer used for drinking water supply
- Potential Contaminants of Concern: Benzene, Ethylbenzene, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Other Petroleum, Toluene, Xylene
- Site History: The case was opened following an unauthorized release from an underground storage tank system at the subject site. Corrective action is underway as directed by the CVRWQCB. Corrective action may consist of preliminary site investigation, planning and implementation of remedial action, verification monitoring, or a combination thereof. A summary of the site history is available by clicking on either the "Cleanup Status History", "Regulatory Activities" or the "Site Maps/Documents" tab. For a complete site history the case file at the CVRWQCB should be consulted.

LUST:
- Global Id: T0607700717
- Contact Type: Regional Board Caseworker
- Contact Name: ALAN M. BUEHLER
- Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
- Address: 11020 Sun Center Dr
- City: RANCHO CORDOVA
- Email: alan.buehler@waterboards.ca.gov
- Phone Number: 9164644615

THE TRANSMISSION STORE (Continued) **S102438909**

LUST:

Global Id:	T0607700717
Action Type:	RESPONSE
Date:	01/30/2016
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607700717
Action Type:	RESPONSE
Date:	08/10/2016
Action:	Other Report / Document
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	03/24/2003
Action:	Site Visit / Inspection / Sampling - #2
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	10/19/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	09/29/2009
Action:	Staff Letter
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	12/23/2009
Action:	Verbal Enforcement
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	11/16/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607700717
Action Type:	ENFORCEMENT
Date:	03/14/2014
Action:	Staff Letter
Global Id:	T0607700717
Action Type:	RESPONSE
Date:	10/15/2011
Action:	Other Report / Document
Global Id:	T0607700717
Action Type:	RESPONSE
Date:	11/07/2011
Action:	Other Report / Document
Global Id:	T0607700717
Action Type:	RESPONSE
Date:	01/30/2012
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607700717

THE TRANSMISSION STORE (Continued) **S102438909**

Action Type: RESPONSE
Date: 08/30/2016
Action: Well Installation Workplan

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 11/07/2014
Action: Staff Letter

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/18/2008
Action: Soil and Water Investigation Workplan

Global Id: T0607700717
Action Type: RESPONSE
Date: 05/30/2008
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 03/21/2008
Action: Other Workplan

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/18/2008
Action: Electronic Reporting Submittal Due

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 02/23/2015
Action: Staff Letter

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/01/2008
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 09/09/2011
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/15/2011

THE TRANSMISSION STORE (Continued) **S102438909**

Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/15/2011
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/09/2011
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/06/2011
Action: Verbal Communication - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 02/08/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/23/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 10/30/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/15/2012
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 08/09/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/05/2017
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 02/19/2016
Action: Other Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 03/23/2017
Action: Staff Letter

THE TRANSMISSION STORE (Continued) **S102438909**

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/09/2017
Action: Email Correspondence

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 03/27/2000
Action: Other Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/01/2007
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2013
Action: Other Report / Document - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 05/15/2013
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 06/15/2013
Action: Correspondence - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/30/2013
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/09/2013
Action: Other Report / Document - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/15/2013
Action: Well Installation Report - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE

THE TRANSMISSION STORE (Continued) **S102438909**

Date: 03/15/2015
Action: Other Workplan - Regulator Responded

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/05/1999
Action: Notification - Fee Title Owners Notice - #1

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 11/07/1995
Action: Unauthorized Release Form

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 11/07/1995
Action: Notification - Proposition 65

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/24/2007
Action: Technical Correspondence / Assistance / Other - #4

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/30/2007
Action: Referral to Regional Board - #5

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 06/04/2007
Action: Staff Letter - #6

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 06/18/2003
Action: Other Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 07/06/2016
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 03/13/2002
Action: Other Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 02/05/1997
Action: Other Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 06/02/2017
Action: Waste Discharge Requirements - #WDR R5-2015-0012-014

THE TRANSMISSION STORE (Continued) **S102438909**

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/17/2018
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 07/26/2018
Action: Waste Discharge Requirements - #R5-2015-0012-044

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/09/2018
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 06/01/2018
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 08/15/2018
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 11/01/2017
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 07/24/2020
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/21/2020
Action: Other Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 10/24/2019
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 12/02/2019
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 03/20/2019
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT

THE TRANSMISSION STORE (Continued) **S102438909**

Date: 07/09/2019
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: RESPONSE
Date: 02/01/2008
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/20/2007
Action: Other Workplan

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/20/2007
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 05/01/2008
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 06/02/2014
Action: Pilot Study / Treatability Workplan - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/15/2015
Action: Other Report / Document - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/31/2014
Action: Other Workplan - Regulator Responded

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 12/27/2007
Action: Staff Letter - #7

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 02/08/2012
Action: Technical Correspondence / Assistance / Other

THE TRANSMISSION STORE (Continued) **S102438909**

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 09/23/2016
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 03/22/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 12/06/2016
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/27/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607700717
Action Type: Other
Date: 01/13/1993
Action: Leak Discovery

Global Id: T0607700717
Action Type: Other
Date: 02/07/1996
Action: Leak Stopped

Global Id: T0607700717
Action Type: Other
Date: 11/07/1995
Action: Leak Reported

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/01/2007
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 02/09/2010
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/04/2019
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE

THE TRANSMISSION STORE (Continued) **S102438909**

Date: 08/06/2018
Action: Site Investigation Workplan - Regulator Responded

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/24/2017
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/31/2005
Action: Meeting - #3

Global Id: T0607700717
Action Type: RESPONSE
Date: 03/02/2009
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 02/01/2009
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 10/30/2008
Action: Pilot Study/ Treatability Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2008
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/01/2008
Action: Pilot Study / Treatability Workplan

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/08/2009
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 10/15/2009
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 06/30/2009
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 02/25/2009
Action: Correspondence

THE TRANSMISSION STORE (Continued) **S102438909**

Global Id: T0607700717
Action Type: RESPONSE
Date: 05/01/2009
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/15/2011
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2009
Action: Final Remedial Action Report / Corrective Action Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 10/15/2010
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/15/2010
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/11/2008
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE

THE TRANSMISSION STORE (Continued) **S102438909**

Date: 05/15/2009
Action: Pilot Study/ Treatability Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/01/2008
Action: Monitoring Report - Quarterly

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/02/2009
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/30/2011
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 01/13/2010
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/15/2009
Action: CAP/RAP - Feasibility Study Report

Global Id: T0607700717
Action Type: RESPONSE
Date: 08/01/2009
Action: Other Report / Document

Global Id: T0607700717
Action Type: RESPONSE
Date: 07/30/2010
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 04/30/2011
Action: Correspondence

Global Id: T0607700717
Action Type: REMEDIATION
Date: 02/13/1997
Action: Monitored Natural Attenuation

Global Id: T0607700717
Action Type: REMEDIATION
Date: 06/20/2011
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700717
Action Type: REMEDIATION
Date: 02/03/2000
Action: Soil Vapor Extraction (SVE)

THE TRANSMISSION STORE (Continued) **S102438909**

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 12/04/2008
Action: Verbal Enforcement

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 12/01/2008
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 04/11/2013
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 08/16/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700717
Action Type: REMEDIATION
Date: 06/20/2011
Action: Soil Vapor Extraction (SVE)

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 10/09/2008
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/29/2009
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/28/2009
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 04/08/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 05/02/2013
Action: Staff Letter

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/15/2010
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE

THE TRANSMISSION STORE (Continued) **S102438909**

Date: 01/18/2011
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 12/13/2010
Action: Correspondence

Global Id: T0607700717
Action Type: RESPONSE
Date: 11/30/2015
Action: Well Installation Report

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 07/10/1996
Action: Notice of Reimbursement

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 04/08/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Staff Letter

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 09/29/2009
Action: Verbal Enforcement

Global Id: T0607700717
Action Type: ENFORCEMENT
Date: 01/07/2015
Action: Staff Letter

LUST:
Global Id: T0607700717
Status: Open - Case Begin Date
Status Date: 01/13/1993

Global Id: T0607700717
Status: Open - Site Assessment
Status Date: 11/07/1995

Global Id: T0607700717
Status: Open - Remediation
Status Date: 02/03/2000

Global Id: T0607700717
Status: Open - Site Assessment
Status Date: 03/24/2003

Global Id: T0607700717
Status: Open - Remediation

THE TRANSMISSION STORE (Continued) **S102438909**

Status Date: 09/25/2008

Global Id: T0607700717
Status: Open - Verification Monitoring
Status Date: 05/30/2013

Global Id: T0607700717
Status: Open - Remediation
Status Date: 06/02/2017

LUST REG 5:
Name: THE TRANSMISSION STORE
Address: 515 CHARTER WAY W
City: STOCKTON
Region: 5
Status: Pollution Characterization
Case Number: 390891
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Regional
Program: LUST
MTBE Code: 5

CORTESE:
Name: THE TRANSMISSION STORE
Address: 515 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700717
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: OPEN - REMEDIATION
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: THE TRANSMISSION STORE
edr_fadd1: 515 CHARTER
City,State,Zip: STOCKTON, CA
Region: CORTESE

THE TRANSMISSION STORE (Continued) **S102438909**

Facility County Code: 39
Reg By: LTNKA
Reg Id: 390891

NOTIFY 65:
Name: THE TRANSMISSION STORE
Address: 515 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 11/07/1995
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: THE TRANSMISSION STORE
Address: 515 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: THE TRANSMISSION STORE
Address: 515 CHARTER WAY W
City,State,Zip: STOCKTON, CA 95206
Site ID: 244769
CERS ID: T0607700717
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: ALAN M. BUEHLER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 Sun Center Dr
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 9164644615

Name: THE TRANSMISSION STORE
Address: 515 CHARTER
City,State,Zip: STOCKTON, CA 95206
Site ID: 436449
CERS ID: 825440
CERS Description: Waste Discharge Requirements

THE TRANSMISSION STORE (Continued) **S102438909**

Affiliation:

Affiliation Type Desc:	Owner and Operator
Entity Name:	Rodgers, Don
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

---

194 WNW 1/2-1 0.858 mi. 4530 ft.

STOCKTON IRON WORKS
600 W. LINDSAY STREET
STOCKTON, CA 95203

ENVIROSTOR **S111345505**
N/A

Relative: Lower

Actual: 12 ft.

ENVIROSTOR:

Name:	STOCKTON IRON WORKS
Address:	600 W. LINDSAY STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	60001556
Status:	Refer: EPA
Status Date:	06/27/2012
Site Code:	102157
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	2
NPL:	NO
Regulatory Agencies:	SMBRP, US EPA, SAN JOAQUIN COUNTY
Lead Agency:	US EPA
Program Manager:	Not reported
Supervisor:	Steven Becker
Division Branch:	Cleanup San Joaquin
Assembly:	13
Senate:	05
Special Program:	EPA - PASI
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not Applicable
Latitude:	37.95505
Longitude:	-121.3010
APN:	NONE SPECIFIED
Past Use:	FOUNDRY, MACHINE SHOP
Potential COC:	Under Investigation
Confirmed COC:	31001-NO
Potential Description:	SOIL
Alias Name:	CAN000905779
Alias Type:	EPA Identification Number
Alias Name:	102157
Alias Type:	Project Code (Site Code)
Alias Name:	60001556
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

STOCKTON IRON WORKS (Continued) **S111345505**

Completed Document Type: PA/SI Discovery
Completed Date: 06/30/1998
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Site Screening
Completed Date: 12/13/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Reassessment
Completed Date: 06/27/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Reassessment
Completed Date: 10/01/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 01/09/2007
Comments: USEPA completed a Preliminary Assessment for the site and concluded that further assessment is required.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

195
ENE
1/2-1
0.911 mi.
4810 ft.

Relative:
Higher

Actual:
22 ft.

WIGHT ENTERPRISES #2 LLC **LUST** **S101593030**
130 S WILSON WAY **SWEEPS UST** **N/A**
STOCKTON, CA 95205 **CA FID UST**
Cortese
EMI
HIST CORTESE
Notify 65
CERS

LUST:
Name: ARCO #5469
Address: 130 WILSON WAY S
City,State,Zip: STOCKTON, CA 95205
Lead Agency: SAN JOAQUIN COUNTY
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607700888
Global Id: T0607700888
Latitude: 37.9542577413622
Longitude: -121.270843679099

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Status: Completed - Case Closed
Status Date: 08/21/2012
Case Worker: Not reported
RB Case Number: 391072
Local Agency: Not reported
File Location: Local Agency
Local Case Number: 0710
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: 3/2/1999, impacted soil discovered beneath product lines. 3/3/1999, UAR issued, release reported. 7/29/1999, Prop 65 notification issued. 2/2/2000, NOR issued to RP. 3/21/2002, Work plan approved that included installation of five C-sparge wells. 12/26/2002, Ozone injection initiated to address impacted groundwater. System operated without formal approval as a final remediation system.

LUST:
Global Id: T0607700888
Contact Type: Regional Board Caseworker
Contact Name: Alan Buehler
Organization Name: CENTRAL VALLEY RWQCB (REGION 5S)
Address: 11020 SUN CENTER DRIVE #200
City: RANCHO CORDOVA
Email: alan.buehler@waterboards.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 07/01/2009
Action: Staff Letter

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 08/13/2009
Action: File review

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 04/06/2010
Action: File review

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 10/25/2011
Action: File Review - Closure

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 02/04/2011
Action: File review

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 08/09/2010
Action: File review

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 10/03/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 10/27/2011
Action: LOP Case Closure Summary to RB

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 10/28/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 03/03/1999
Action: Unauthorized Release Form

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 07/01/2011
Action: File review

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 11/18/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 12/01/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 02/03/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607700888
Action Type: Other
Date: 03/02/1999
Action: Leak Discovery

Global Id: T0607700888
Action Type: Other
Date: 03/03/1999
Action: Leak Reported

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 07/29/1999
Action: Notification - Proposition 65

Global Id: T0607700888
Action Type: ENFORCEMENT

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Date: 08/02/2012
Action: File review

Global Id: T0607700888
Action Type: REMEDIATION
Date: 12/26/2002
Action: In Situ Physical/Chemical Treatment (other than SVE)

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 02/02/2009
Action: File review

Global Id: T0607700888
Action Type: ENFORCEMENT
Date: 02/02/2000
Action: Notice of Responsibility

LUST:
Global Id: T0607700888
Status: Open - Case Begin Date
Status Date: 03/02/1999

Global Id: T0607700888
Status: Open - Site Assessment
Status Date: 03/02/1999

Global Id: T0607700888
Status: Open - Remediation
Status Date: 12/26/2002

Global Id: T0607700888
Status: Open - Verification Monitoring
Status Date: 03/11/2010

Global Id: T0607700888
Status: Completed - Case Closed
Status Date: 08/21/2012

LUST REG 5:
Name: ARCO #5469
Address: 130 WILSON WAY S
City: STOCKTON
Region: 5
Status: Remedial action (cleanup) Underway
Case Number: 391072
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 7

SWEEPS UST:
Name: ARCO #5469

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Address:	130 S WILSON WAY
City:	STOCKTON
Status:	Active
Comp Number:	1861
Number:	1
Board Of Equalization:	44-000506
Referral Date:	07-23-92
Action Date:	07-23-92
Created Date:	07-07-88
Owner Tank Id:	001
SWRCB Tank Id:	39-000-001861-000001
Tank Status:	A
Capacity:	12000
Active Date:	07-23-92
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	3

Name:	ARCO #5469
Address:	130 S WILSON WAY
City:	STOCKTON
Status:	Active
Comp Number:	1861
Number:	1
Board Of Equalization:	44-000506
Referral Date:	07-23-92
Action Date:	07-23-92
Created Date:	07-07-88
Owner Tank Id:	002
SWRCB Tank Id:	39-000-001861-000002
Tank Status:	A
Capacity:	12000
Active Date:	07-23-92
Tank Use:	M.V. FUEL
STG:	P
Content:	PRM UNLEADED
Number Of Tanks:	Not reported

Name:	ARCO #5469
Address:	130 S WILSON WAY
City:	STOCKTON
Status:	Active
Comp Number:	1861
Number:	1
Board Of Equalization:	44-000506
Referral Date:	07-23-92
Action Date:	07-23-92
Created Date:	07-07-88
Owner Tank Id:	003
SWRCB Tank Id:	39-000-001861-000003
Tank Status:	A
Capacity:	12000
Active Date:	07-23-92
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Number Of Tanks: Not reported

CA FID UST:
Facility ID: 39001382
Regulated By: UTNKA
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 2094666633
Mail To: Not reported
Mailing Address: 17315 STUDEBAKER ROAD
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95205
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

CORTESE:
Name: ARCO #5469
Address: 130 WILSON WAY S
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607700888
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

EMI:
Name: WIGHT ENTERPRISES #2 LLC
Address: 130 S WILSON WAY
City,State,Zip: STOCKTON, CA 95205
Year: 2006
County Code: 39
Air Basin: SJV
Facility ID: 86
Air District Name: SJU

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.871123974218134910
Reactive Organic Gases Tons/Yr:	1.8612269169921875
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2007
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.619444594902894033
Reactive Organic Gases Tons/Yr:	1.61087876171875
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2008
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.589253822323402772
Reactive Organic Gases Tons/Yr:	1.5806244888916008
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2009
County Code:	39

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.14461641870655
Reactive Organic Gases Tons/Yr:	1.1384013782958899
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2010
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.14462695941306
Reactive Organic Gases Tons/Yr:	1.13841188
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2011
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.5467312673
Reactive Organic Gases Tons/Yr:	1.5383328229
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

City,State,Zip:	STOCKTON, CA 95205
Year:	2012
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.5467312673
Reactive Organic Gases Tons/Yr:	1.5383328229
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2013
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY UNIFIED APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.538307722
Reactive Organic Gases Tons/Yr:	1.538307722
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	WIGHT ENTERPRISES #2 LLC
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2014
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.5383328229
Reactive Organic Gases Tons/Yr:	1.5383328229
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Name:	MCM14 CORP
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2015
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.370356
Reactive Organic Gases Tons/Yr:	1.370356
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	MCM14 CORP
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2016
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.351411981
Reactive Organic Gases Tons/Yr:	1.351411981
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	MCM14 CORP
Address:	130 S WILSON WAY
City,State,Zip:	STOCKTON, CA 95205
Year:	2017
County Code:	39
Air Basin:	SJV
Facility ID:	86
Air District Name:	SJU
SIC Code:	5541
Air District Name:	SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.351411981
Reactive Organic Gases Tons/Yr:	1.4505465
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

Name: MCM14 CORP
Address: 130 S WILSON WAY
City,State,Zip: STOCKTON, CA 95205
Year: 2018
County Code: 39
Air Basin: SJV
Facility ID: 86
Air District Name: SJU
SIC Code: 5541
Air District Name: SAN JOAQUIN VALLEY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.385990947
Reactive Organic Gases Tons/Yr: 1.385990947
Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

HIST CORTESE:
edr_fname: ARCO #5469
edr_fadd1: 130 WILSON
City,State,Zip: STOCKTON, CA 95205
Region: CORTESE
Facility County Code: 39
Reg By: LTNKA
Reg Id: 391072

NOTIFY 65:
Name: ARCO #5469
Address: 130 WILSON WAY S
City,State,Zip: STOCKTON, CA 95205
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: 07/29/1999
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

Name: ARCO #5469
Address: 130 WILSON WAY S
City,State,Zip: STOCKTON, CA 95205
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported

WIGHT ENTERPRISES #2 LLC (Continued) **S101593030**

Global ID: Not reported
Status: Not reported

CERS:
Name: ARCO #5469
Address: 130 WILSON WAY S
City,State,Zip: STOCKTON, CA 95205
Site ID: 247909
CERS ID: T0607700888
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title: Not reported
Affiliation Address: 11020 SUN CENTER DRIVE #200
Affiliation City: RANCHO CORDOVA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Name: ARCO AM/PM 5469 ENV COMPLIANCE
Address: 130 SOUTH WILSON WAY
City,State,Zip: STOCKTON, CA 95205-5561
Site ID: 452071
CERS ID: 110013994473
CERS Description: US EPA Air Emission Inventory System (EIS)

196
WNW
1/2-1
0.925 mi.
4883 ft.

SOUTHPOINTE PROPERTY **ENVIROSTOR** **S110769664**
WEBER AVENUE + STOCKTON DEEP WATER CHANNEL **VCP** **N/A**
STOCKTON, CA 95203

Relative:
Lower

Actual:
11 ft.

ENVIROSTOR:
Name: SOUTHPOINTE PROPERTY
Address: WEBER AVENUE + STOCKTON DEEP WATER CHANNEL
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60001406
Status: Inactive - Needs Evaluation
Status Date: 10/04/2018
Site Code: 102125
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 6.5
NPL: NO
Regulatory Agencies: SMBRP, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Assembly: 13
Senate: 05
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED

SOUTHPOINTE PROPERTY (Continued) **S110769664**

Funding: Responsible Party
Latitude: 37.95218
Longitude: -121.3030
APN: NONE SPECIFIED
Past Use: RAILROAD RIGHT OF WAY
Potential COC: Lead Toxaphene Dieldrin
Confirmed COC: Lead Dieldrin Toxaphene
Potential Description: SOIL
Alias Name: 102125
Alias Type: Project Code (Site Code)
Alias Name: 60001406
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Triage Meeting
Completed Date: 08/24/2015
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: SOUTHPOINTE PROPERTY
Address: WEBER AVENUE + STOCKTON DEEP WATER CHANNEL
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60001406
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 6.5
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Not reported
Supervisor: Steven Becker
Division Branch: Cleanup San Joaquin
Site Code: 102125
Assembly: 13
Senate: 05
Special Programs Code: Voluntary Cleanup Program
Status: Inactive - Needs Evaluation
Status Date: 10/04/2018
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.95218 / -121.3030
APN: NONE SPECIFIED
Past Use: RAILROAD RIGHT OF WAY

SOUTHPOINTE PROPERTY (Continued) **S110769664**

Potential COC:	30013, 30023, 30207
Confirmed COC:	30013,30207,30023
Potential Description:	SOIL
Alias Name:	102125
Alias Type:	Project Code (Site Code)
Alias Name:	60001406
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Triage Meeting
Completed Date:	08/24/2015
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

197
East
1/2-1
0.938 mi.
4954 ft.

Relative:
Higher

Actual:
22 ft.

ROTOR BLADE INCE
1514 E SCOTTS AVE
STOCKTON, CA 95202

ENVIROSTOR **S101593318**
VCP **N/A**
SWEEPS UST
CA FID UST
LIENS
DEED

ENVIROSTOR:

Name:	ROTOR BLADES, INC
Address:	1514 EAST SCOTTS AVENUE
City,State,Zip:	STOCKTON, CA 95205
Facility ID:	39760006
Status:	Active
Status Date:	04/12/2016
Site Code:	101151
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	1.3
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Brian Mcaloon
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Assembly:	13
Senate:	05
Special Program:	Voluntary Cleanup Program
Restricted Use:	YES
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.94847
Longitude:	-121.2689
APN:	155-070-01, 15507001

ROTOR BLADE INCE (Continued) **S101593318**

Past Use: AIRCRAFT MAINTENANCE
Potential COC: * Metals - Other Inorganic Solid Waste * ORGANIC LIQUIDS WITH METALS * OXYGENATED SOLVENTS * AQUEOUS SOLUTION WITH METALS * CONTAMINATED SOIL * UNSPECIFIED ACID SOLUTION * OTHER INORGANIC SOLID WASTE
Confirmed COC: NONE SPECIFIED
Potential Description: SOIL
Alias Name: AERONAUTICAL ROTOR BLADES
Alias Type: Alternate Name
Alias Name: British Auto Service, Triumphs Only
Alias Type: Alternate Name
Alias Name: ROTOR BLADES, INC.
Alias Type: Alternate Name
Alias Name: 155-070-01
Alias Type: APN
Alias Name: 15507001
Alias Type: APN
Alias Name: CAD082447178
Alias Type: EPA Identification Number
Alias Name: 110013822293
Alias Type: EPA (FRS #)
Alias Name: 101151
Alias Type: Project Code (Site Code)
Alias Name: 39760006
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 05/08/2007
Comments: PEA report marked as complete based on DTSC acceptance of the soil characterization report as part of the Removal Action Workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 03/29/1988
Comments: PRELIMINARY ASSESSMENT COMPLETED. HEAVY METALS FOUND IN SOILS. QUALITATIVE LAB REPORTS. NO INDICATION OF CLEANUP. STATE SI (MED) RECOMMENDED. CERCLA: SI (MEDIUM) RECOMMENDED

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 02/20/1987
Comments: SITE SCREENING DONE NO CLEANUP DOCUMENTED

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 04/03/2007
Comments: Document was received and implemented prior to DTSC reviewing the sampling plan. Completion date entered as being equal to submittal date to close out this deliverable.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report

ROTOR BLADE INCE (Continued) **S101593318**

Completed Date: 05/08/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 07/15/2008
Comments: Final RAW approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 03/20/2008
Comments: Fact sheet for the project has been approved for release to public.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 09/21/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 09/24/2018
Comments: 2018 Annual Inspection Report received and filed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/08/2020
Comments: Received completed and signed document from property owner.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 08/03/2020
Comments: Email sent to property owner to provide concurrence for 2020 LUC Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 10/04/1999
Comments: On 10/04/99 DTSC entered into an agreement with the site proponents to oversee the completion of a Preliminary Endangerment Assessment.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 02/02/1981
Comments: FACILITY IDENTIFIED FROM HWMB ENFORCEMENT FILES.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/20/2007

ROTOR BLADE INCE (Continued) **S101593318**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 07/02/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Lien
Completed Date: 10/28/2011
Comments: Final lien was sent to San Joaquin County Recorders Office for posting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Triage Meeting
Completed Date: 06/03/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Form 1479 - Site and Collections Summary
Completed Date: 02/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 07/20/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 11/16/2015
Comments: Letter issued.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Settlement - Administrative
Completed Date: 12/28/2015
Comments: Agreement signed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Lien Satisfaction
Completed Date: 02/09/2016
Comments: Final Lien Release

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 05/18/2016
Comments: Final Deed restriction recorded with County.

ROTOR BLADE INCE (Continued) **S101593318**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 11/19/2020
Comments: Rotor Blades SVA fully executed on 11/19/2020, sent to Sarah Shomphe with Cover Letter via email on 11/24/2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/02/2020
Comments: FY20-21 Annual LUC Cost Estimate Letter sent out via email 11/2/2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/04/2019
Comments: Cost Estimate Letter for fiscal year 2019-2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Consultation
Completed Date: 12/16/2020
Comments: Project kick-off phone meeting 12/16/2020 with Proponent and Consultant to discuss scope of work, schedules.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 03/11/2021
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Remedial Action Completion Report
Future Due Date: 2022
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: No Further Action Letter
Future Due Date: 2022
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Name: ROTOR BLADES, INC.
Address: 1514 E. SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95205
Facility ID: 71002606
Status: Refer: SMBRP
Status Date: 09/17/2020
Site Code: Not reported

ROTOR BLADE INCE (Continued) **S101593318**

Site Type: Tiered Permit
Site Type Detailed: Tiered Permit
Acres: 1.3
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Lora Jameson
Division Branch: Cleanup Sacramento
Assembly: 13
Senate: 05
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.94851
Longitude: -121.2688
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CAD082447178
Alias Type: EPA Identification Number
Alias Name: 71002606
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: ROTOR BLADES, INC
Address: 1514 EAST SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95205
Facility ID: 39760006
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 1.3
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program

ROTOR BLADE INCE (Continued) **S101593318**

Project Manager:	Brian Mcaloon
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Site Code:	101151
Assembly:	13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Active
Status Date:	04/12/2016
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.94847 / -121.2689
APN:	155-070-01, 15507001
Past Use:	AIRCRAFT MAINTENANCE
Potential COC:	10034, 10061, 10067, 10093, 10097, 10193, 20011
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL
Alias Name:	AERONAUTICAL ROTOR BLADES
Alias Type:	Alternate Name
Alias Name:	British Auto Service, Triumphs Only
Alias Type:	Alternate Name
Alias Name:	ROTOR BLADES, INC.
Alias Type:	Alternate Name
Alias Name:	155-070-01
Alias Type:	APN
Alias Name:	15507001
Alias Type:	APN
Alias Name:	CAD082447178
Alias Type:	EPA Identification Number
Alias Name:	110013822293
Alias Type:	EPA (FRS #)
Alias Name:	101151
Alias Type:	Project Code (Site Code)
Alias Name:	39760006
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	05/08/2007
Comments:	PEA report marked as complete based on DTSC acceptance of the soil characterization report as part of the Removal Action Workplan.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	03/29/1988
Comments:	PRELIMINARY ASSESSMENT COMPLETED. HEAVY METALS FOUND IN SOILS. QUALITATIVE LAB REPORTS. NO INDICATION OF CLEANUP. STATE SI (MED) RECOMMENDED. CERCLA: SI (MEDIUM) RECOMMENDED
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Screening
Completed Date:	02/20/1987
Comments:	SITE SCREENING DONE NO CLEANUP DOCUMENTED

ROTOR BLADE INCE (Continued) **S101593318**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 04/03/2007
Comments: Document was received and implemented prior to DTSC reviewing the sampling plan. Completion date entered as being equal to submittal date to close out this deliverable.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/08/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 07/15/2008
Comments: Final RAW approved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 03/20/2008
Comments: Fact sheet for the project has been approved for release to public.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 09/21/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 09/24/2018
Comments: 2018 Annual Inspection Report received and filed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 01/08/2020
Comments: Received completed and signed document from property owner.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction Monitoring Report
Completed Date: 08/03/2020
Comments: Email sent to property owner to provide concurrence for 2020 LUC Inspection Report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 10/04/1999
Comments: On 10/04/99 DTSC entered into an agreement with the site proponents to oversee the completion of a Preliminary Endangerment Assessment.

ROTOR BLADE INCE (Continued) **S101593318**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 02/02/1981
Comments: FACILITY IDENTIFIED FROM HWMB ENFORCEMENT FILES.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/20/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 07/02/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Lien
Completed Date: 10/28/2011
Comments: Final lien was sent to San Joaquin County Recorders Office for posting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Triage Meeting
Completed Date: 06/03/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Form 1479 - Site and Collections Summary
Completed Date: 02/02/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 07/20/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 11/16/2015
Comments: Letter issued.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Settlement - Administrative
Completed Date: 12/28/2015
Comments: Agreement signed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

ROTOR BLADE INCE (Continued) **S101593318**

Completed Document Type:	Lien Satisfaction
Completed Date:	02/09/2016
Comments:	Final Lien Release
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Land Use Restriction
Completed Date:	05/18/2016
Comments:	Final Deed restriction recorded with County.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	11/19/2020
Comments:	Rotor Blades SVA fully executed on 11/19/2020, sent to Sarah Shomphe with Cover Letter via email on 11/24/2020.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	11/02/2020
Comments:	FY20-21 Annual LUC Cost Estimate Letter sent out via email 11/2/2020.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/04/2019
Comments:	Cost Estimate Letter for fiscal year 2019-2020.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Consultation
Completed Date:	12/16/2020
Comments:	Project kick-off phone meeting 12/16/2020 with Proponent and Consultant to discuss scope of work, schedules.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	CEQA - Notice of Exemption
Completed Date:	03/11/2021
Comments:	Not reported
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	5 Year Review Reports
Future Due Date:	2021
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Remedial Action Completion Report
Future Due Date:	2022
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	No Further Action Letter
Future Due Date:	2022
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported

ROTOR BLADE INCE (Continued) **S101593318**

Schedule Due Date: Not reported
Schedule Revised Date: Not reported

SWEEPS UST:
Name: ROTOR BLADE INCE
Address: 1514 E SCOTTS AVE
City: STOCKTON
Status: Not reported
Comp Number: 2296
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 39-000-002296-000001
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

CA FID UST:
Facility ID: 39003719
Regulated By: UTNKI
Regulated ID: Not reported
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: Not reported
Mail To: Not reported
Mailing Address: 1514 E SCOTTS AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: STOCKTON 95202
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

LIENS:
Name: ROTOR BLADES, INC
City,State,Zip: STOCKTON, CA 95205
Envirostor Id: 39760006
Latitude: 37.948475
Longitude: -121.26890
Project Mgr: THOMAS ANDERSON
Project Code: 101151
If Satisfied: YES
Date Satisfied: 2/9/2016
Site Status: ACTIVE
Site Type: VOLUNTARY CLEANUP
Completed: 10/28/2011

ROTOR BLADE INCE (Continued) **S101593318**

Lien Amount: $9,611.18
Amount Remaining: Not reported
APNS: 155-070-01, 15507001
Description: The 1.35 acre site was previously used for the refurbishing of helicopter rotor blades. The results of the Preliminary Endangerment Assessment indicate that elevated metals (primarily Lead) are present in shallow soils on the site in the vicinity of an area that appears to have received rinse water from cleaning of rotor blades. Additionally, elevated lead concentrations were detected in shallow soils on the site near the property boundaries near the rinse area. Additional investigation in 2007 indicated that lead is present above screening levels in the unpaved areas of the Site and a Removal Action Work Plan (RAW) was approved in 2008 which called for capping the unpaved areas of the Site for a remedy. The current owner is unable to fund the RAW at this time and thus it is still pending. However, a Land Use Covenant has been placed on the property to ensure safety in the interim.

DEED:
Name: ROTOR BLADES, INC
Address: 1514 EAST SCOTTS AVENUE
City,State,Zip: STOCKTON, CA 95205
Envirostor ID: 39760006
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: ACTIVE
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported
File Name: Envirostor Land Use Restrictions

---

198 NNE 1/2-1 0.966 mi. 5098 ft. **STOCKTON DEVELOPMENTAL CENTER**
1252 STANISLAUS ST
STOCKTON, CA 95202

LUST Cortese Notify 65 CERS **S105174036 N/A**

Relative: Higher
Actual: 19 ft.

LUST REG 5:
Name: STOCKTOn DEVELOPMENTAL CENTER
Address: 1252 STANISLAUS ST
City: STOCKTON
Region: 5
Status: Leak being confirmed
Case Number: 391087
Case Type: Drinking Water Aquifer affected
Substance: GASOLINE
Staff Initials: JLB
Lead Agency: Local
Program: LUST
MTBE Code: 8

CORTESE:
Name: STOCKTON DEVELOPMENTAL CENTER
Address: 1252 STANISLAUS ST
City,State,Zip: STOCKTON, CA 95202
Region: CORTESE

STOCKTON DEVELOPMENTAL CENTER (Continued) **S105174036**

Envirostor Id:	Not reported
Global ID:	T0607700902
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

NOTIFY 65:

Name:	STOCKTON DEVELOPMENTAL CENTER
Address:	1252 STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95202
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	12/08/1999
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Name:	STOCKTON DEVELOPMENTAL CENTER
Address:	1252 STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95202
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CERS:

Name:	STOCKTON DEVELOPMENTAL CENTER
Address:	1252 STANISLAUS ST
City,State,Zip:	STOCKTON, CA 95202
Site ID:	241828
CERS ID:	T0607700902
CERS Description:	Leaking Underground Storage Tank Cleanup Site

STOCKTON DEVELOPMENTAL CENTER (Continued) **S105174036**

Affiliation:
- Affiliation Type Desc: Regional Board Caseworker
- Entity Name: Alan Buehler - CENTRAL VALLEY RWQCB (REGION 5S)
- Entity Title: Not reported
- Affiliation Address: 11020 SUN CENTER DRIVE #200
- Affiliation City: RANCHO CORDOVA
- Affiliation State: CA
- Affiliation Country: Not reported
- Affiliation Zip: Not reported
- Affiliation Phone: Not reported

---

199 WNW 1/2-1 0.974 mi. 5141 ft. **NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS**
848 W. FREMONT STREET
STOCKTON, CA 95203

ENVIROSTOR VCP SWEEPS UST CA FID UST **S101593277 N/A**

Relative: Lower
Actual: 12 ft.

ENVIROSTOR:
- Name: NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS
- Address: 848 W. FREMONT STREET
- City,State,Zip: STOCKTON, CA 95203
- Facility ID: 60002155
- Status: Active
- Status Date: 03/17/2015
- Site Code: 102260
- Site Type: Voluntary Cleanup
- Site Type Detailed: Voluntary Cleanup
- Acres: 2
- NPL: NO
- Regulatory Agencies: SMBRP
- Lead Agency: SMBRP
- Program Manager: Dean Wright
- Supervisor: Lora Jameson
- Division Branch: Northern California Schools & Santa Susana
- Assembly: , 13
- Senate: , 05
- Special Program: Not reported
- Restricted Use: NO
- Site Mgmt Req: NONE SPECIFIED
- Funding: Responsible Party
- Latitude: 37.95514
- Longitude: -121.3027
- APN: NONE SPECIFIED
- Past Use: AGRICULTURAL - ROW CROPS, MANUFACTURING - LUMBER/WOOD PRODUCTS
- Potential COC: Arsenic
- Confirmed COC: Arsenic
- Potential Description: SOIL
- Alias Name: 102260
- Alias Type: Project Code (Site Code)
- Alias Name: 60002155
- Alias Type: Envirostor ID Number

Completed Info:
- Completed Area Name: PROJECT WIDE
- Completed Sub Area Name: Not reported
- Completed Document Type: Standard Voluntary Agreement
- Completed Date: 04/29/2015

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Comments: Executed VCA signed by DTSC on 4.28.2015

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 03/28/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/05/2017
Comments: Fiscal year cost estimate letter completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/19/2018
Comments: Fiscal Year Cost Estimate Letter 2018/2019

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 04/14/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 02/24/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 04/14/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Workplan
Completed Date: 01/07/2020
Comments: Supplemental Sampling E-Mail Approval

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 11/10/2020
Comments: DTSC E-mail Step-Out Sampling Workplan Approval

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/02/2019
Comments: Final 19/20 Fiscal Year Cost Estimate Letter

Completed Area Name: PROJECT WIDE

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/10/2020
Comments: Annual fiscal year cost estimate letter 2020/2021.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 08/20/2019
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Removal Action Completion Report
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2021
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Name: COLBERG BOAT WORKS
Address: 848 W. FREMONT STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 39440001
Status: Active
Status Date: 05/06/2020
Site Code: 102242
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 18
NPL: NO
Regulatory Agencies: SMBRP, RWQCB 5S - Central Valley, SAN JOAQUIN COUNTY
Lead Agency: SMBRP
Program Manager: Dean Wright
Supervisor: Lora Jameson
Division Branch: Northern California Schools & Santa Susana
Assembly: 13
Senate: 05
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.95428
Longitude: -121.3030
APN: 13546010
Past Use: DRY DOCKS
Potential COC: Lead TPH-diesel TPH-gas TPH-MOTOR OIL
Confirmed COC: 30024-NO 30025-NO 3002502-NO 30013-NO
Potential Description: OTH, SED, SOIL, SURFW
Alias Name: 13546010
Alias Type: APN
Alias Name: CAC002609670

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Alias Type: EPA Identification Number
Alias Name: CAL00003246
Alias Type: EPA Identification Number
Alias Name: CAN000906010
Alias Type: EPA Identification Number
Alias Name: 101667
Alias Type: Project Code (Site Code)
Alias Name: 101907
Alias Type: Project Code (Site Code)
Alias Name: 101977
Alias Type: Project Code (Site Code)
Alias Name: 102242
Alias Type: Project Code (Site Code)
Alias Name: 39440001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 06/10/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 06/02/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 06/14/2010
Comments: Accepted workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 02/16/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 11/01/2017
Comments: Accepted initial data bap analysis and Scope of Work report as final.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 03/22/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/06/2017
Comments: Fiscal year 17/18 cost estimate letter completed.

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	09/24/2018
Comments:	2018/2019 Cost Estimate Letter complete.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Reimbursement Agreement
Schedule Due Date:	02/01/2019
Schedule Revised Date:	Not reported

VCP:

Name:	COLBERG BOAT WORKS
Address:	848 W. FREMONT STREET
City,State,Zip:	STOCKTON, CA 95203
Facility ID:	39440001
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	18
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP, RWQCB 5S - Central Valley, SAN JOAQUIN COUNTY
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Dean Wright
Supervisor:	Lora Jameson
Division Branch:	Northern California Schools & Santa Susana
Site Code:	102242
Assembly:	13
Senate:	05
Special Programs Code:	Voluntary Cleanup Program
Status:	Active
Status Date:	05/06/2020
Restricted Use:	NO
Funding:	Not reported
Lat/Long:	37.95428 / -121.3030
APN:	13546010
Past Use:	DRY DOCKS
Potential COC:	30013, 30024, 30025, 3002502
Confirmed COC:	30024-NO,30025-NO,3002502-NO,30013-NO
Potential Description:	OTH, SED, SOIL, SURFW
Alias Name:	13546010
Alias Type:	APN
Alias Name:	CAC002609670
Alias Type:	EPA Identification Number
Alias Name:	CAL00003246
Alias Type:	EPA Identification Number
Alias Name:	CAN000906010
Alias Type:	EPA Identification Number
Alias Name:	101667
Alias Type:	Project Code (Site Code)
Alias Name:	101907

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Alias Type: Project Code (Site Code)
Alias Name: 101977
Alias Type: Project Code (Site Code)
Alias Name: 102242
Alias Type: Project Code (Site Code)
Alias Name: 39440001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: * Discovery
Completed Date: 06/10/2002
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 06/02/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 06/14/2010
Comments: Accepted workplan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 02/16/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 11/01/2017
Comments: Accepted initial data bap analysis and Scope of Work report as final.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 03/22/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/06/2017
Comments: Fiscal year 17/18 cost estimate letter completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/24/2018
Comments: 2018/2019 Cost Estimate Letter complete.

Future Area Name: Not reported

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Reimbursement Agreement
Schedule Due Date: 02/01/2019
Schedule Revised Date: Not reported

Name: NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS
Address: 848 W. FREMONT STREET
City,State,Zip: STOCKTON, CA 95203
Facility ID: 60002155
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 2
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Dean Wright
Supervisor: Lora Jameson
Division Branch: Northern California Schools & Santa Susana
Site Code: 102260
Assembly: , 13
Senate: , 05
Special Programs Code: Not reported
Status: Active
Status Date: 03/17/2015
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.95514 / -121.3027
APN: NONE SPECIFIED
Past Use: AGRICULTURAL - ROW CROPS, MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential COC: 30001
Confirmed COC: 30001
Potential Description: SOIL
Alias Name: 102260
Alias Type: Project Code (Site Code)
Alias Name: 60002155
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 04/29/2015
Comments: Executed VCA signed by DTSC on 4.28.2015

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 03/28/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/05/2017
Comments: Fiscal year cost estimate letter completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/19/2018
Comments: Fiscal Year Cost Estimate Letter 2018/2019

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 04/14/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 02/24/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 04/14/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Workplan
Completed Date: 01/07/2020
Comments: Supplemental Sampling E-Mail Approval

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 11/10/2020
Comments: DTSC E-mail Step-Out Sampling Workplan Approval

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/02/2019
Comments: Final 19/20 Fiscal Year Cost Estimate Letter

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/10/2020
Comments: Annual fiscal year cost estimate letter 2020/2021.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 08/20/2019
Comments: Not reported

NORTHERN 2-ACRE PORTION OF COLBERG BOAT WORKS (Continued) **S101593277**

Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Removal Action Completion Report
Future Due Date:	2021
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Certification
Future Due Date:	2021
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

SWEEPS UST:

Name:	COLBERG, INC
Address:	848 W FREMONT ST
City:	STOCKTON
Status:	Not reported
Comp Number:	2032
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	39-000-002032-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	1

CA FID UST:

Facility ID:	39003611
Regulated By:	UTNKI
Regulated ID:	Not reported
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2094667041
Mail To:	Not reported
Mailing Address:	P O BOX 1288
Mailing Address 2:	Not reported
Mailing City,St,Zip:	STOCKTON 95203
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

Count: 8 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
STOCKTON	S110655187	SAN JOAQUIN COUNTY MOTOR POOL	DELLA/HAZELTON SOUTH	95202	LUST, Cortese
STOCKTON	S105692198	SAN JOAQUIN COUTY MOTOR POOL	DELLA/HAZELTON SOUTH	95202	LUST
STOCKTON	S106230420	EL DORADO APARTMENTS DEVELOPMENT (	EL DORADO ST S		CPS-SLIC
STOCKTON	S106230434	KOPPEL STOCKTON TERMINAL	2025 HAZELTON AVE W		CPS-SLIC
STOCKTON	S106230484	HYDROAGRI NORTH AMERICA, HJ BAKER	WASHINGTON ST, EAST OF NAVY DR		CPS-SLIC
STOCKTON	S106230488	UNION ICE COMPANY [ARCHIVED]	1320 WEBER ST W		CPS-SLIC
STOCKTON	S106842923	MULTI-MODAL SIX-BLOCK PROJECT	WEBER ST		CPS-SLIC
STOCKTON	S106707872	STOCKTON REDEVEL AGENCY- NORTHSHOR	WEBER ST		CPS-SLIC

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: EPA
Telephone: N/A
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 03/30/2021
Date Made Active in Reports: 06/17/2021
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/23/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/05/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 02/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/21/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 02/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/21/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/24/2021
Date Made Active in Reports: 06/17/2021
Number of Days to Update: 85

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 77

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 05/11/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing

For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)
Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 12/22/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/02/2020
Date Data Arrived at EDR: 12/18/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 84

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/12/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/07/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/09/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)

Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/29/2021
Date Data Arrived at EDR: 02/17/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 33

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases

UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 03/05/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 04/01/2021
Number of Days to Update: 23

Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 06/04/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

UST: Active UST Facilities

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Semi-Annually

MILITARY UST SITES: Military UST Sites (GEOTRACKER)

Military ust sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

AST: Aboveground Petroleum Storage Tank Facilities

A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 06/08/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/02/2020
Date Data Arrived at EDR: 12/18/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 84

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/12/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 12/22/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 80

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/07/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/09/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 03/12/2021
Number of Days to Update: 86

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/15/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: No Update Planned

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: No Update Planned

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing

A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 06/10/2021
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/15/2021
Date Data Arrived at EDR: 03/16/2021
Date Made Active in Reports: 06/10/2021
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/10/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: No Update Planned

SWRCY: Recycler Database

A listing of recycling facilities in California.

Date of Government Version: 03/09/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/04/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing

A listing of registered waste tire haulers.

Date of Government Version: 11/23/2020
Date Data Arrived at EDR: 11/23/2020
Date Made Active in Reports: 02/08/2021
Number of Days to Update: 77

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176
Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77
Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/22/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database
The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21
Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program
This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs
A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 01/20/2021
Date Made Active in Reports: 04/08/2021
Number of Days to Update: 78
Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

CERS HAZ WASTE: CERS HAZ WASTE
List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS contaminated sites included in the GeoTracker database.

Date of Government Version: 02/24/2021
Date Data Arrived at EDR: 02/24/2021
Date Made Active in Reports: 05/14/2021
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/04/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing
Aboveground storage tank sites

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

CERS TANKS: California Environmental Reporting System (CERS) Tanks
List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

CA FID UST: Facility Inventory Database
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 03/02/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 77

Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 05/28/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/24/2021
Date Made Active in Reports: 06/17/2021
Number of Days to Update: 85

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 04/04/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)

Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)

Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 02/11/2021
Date Data Arrived at EDR: 02/17/2021
Date Made Active in Reports: 04/05/2021
Number of Days to Update: 47

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 06/17/2021
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/07/2021
Next Scheduled EDR Contact: 08/16/2021
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82
Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/17/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/16/2021
Number of Days to Update: 87
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/19/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16
Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/07/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 82
Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/14/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35
Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 12/30/2020
Date Data Arrived at EDR: 01/14/2021
Date Made Active in Reports: 03/05/2021
Number of Days to Update: 50

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

PADS: PCB Activity Database System
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/19/2020
Date Data Arrived at EDR: 01/08/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 73

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: No Update Planned

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/11/2021
Date Made Active in Reports: 05/11/2021
Number of Days to Update: 61

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/14/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 12/01/2020
Date Made Active in Reports: 02/09/2021
Number of Days to Update: 70
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/27/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/27/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/07/2021
Next Scheduled EDR Contact: 08/16/2021
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: No Update Planned

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/23/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 07/14/2021
Date Made Active in Reports: 07/16/2021
Number of Days to Update: 2

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 07/02/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 151

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/21/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/02/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/23/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/21/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 16

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: No Update Planned

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: No Update Planned

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 05/27/2021
Date Made Active in Reports: 06/10/2021
Number of Days to Update: 14

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/01/2021
Date Data Arrived at EDR: 02/24/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/27/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/27/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/23/2021
Date Data Arrived at EDR: 03/25/2021
Date Made Active in Reports: 06/17/2021
Number of Days to Update: 84

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/14/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/03/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 04/05/2021
Number of Days to Update: 33

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/17/2020
Date Made Active in Reports: 02/09/2021
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/21/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77
Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/07/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 04/04/2021
Date Data Arrived at EDR: 04/06/2021
Date Made Active in Reports: 06/25/2021
Number of Days to Update: 80
Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 81
Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/14/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Quarterly

CA BOND EXP. PLAN: Bond Expenditure Plan
Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6
Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 06/10/2021
Number of Days to Update: 79
Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing
list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 05/01/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 07/17/2019
Number of Days to Update: 64
Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 05/14/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: Varies

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 02/26/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 03/04/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 77

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Annually

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 02/23/2021
Date Data Arrived at EDR: 02/25/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 83

Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 08/28/2020
Number of Days to Update: 73

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 06/10/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 04/16/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 05/13/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 74

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 04/15/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Annually

ICE: ICE

Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 74

Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 05/14/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 74

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 05/14/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 04/05/2021
Date Data Arrived at EDR: 04/06/2021
Date Made Active in Reports: 06/23/2021
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Quarterly

MINES: Mines Site Location Listing
A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21
Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 01/29/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 78
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 05/28/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

NPDES: NPDES Permits Listing
A listing of NPDES permits, including stormwater.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 77
Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 05/11/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing
A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 03/02/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 78
Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 05/28/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 03/09/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 06/04/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 03/12/2021
Date Data Arrived at EDR: 03/16/2021
Date Made Active in Reports: 06/01/2021
Number of Days to Update: 77
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 06/08/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: No Update Planned

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 11/19/2019
Date Data Arrived at EDR: 01/07/2020
Date Made Active in Reports: 03/09/2020
Number of Days to Update: 62
Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9
Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 05/14/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 06/15/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)
Military privatized sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)
Projects sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 03/09/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 06/07/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 11/30/2020
Date Data Arrived at EDR: 12/01/2020
Date Made Active in Reports: 02/12/2021
Number of Days to Update: 73

Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 05/19/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)
Produced water ponds sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)
Sampling point - public sites

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)
Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/30/2021
Number of Days to Update: 21

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/30/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: No Update Planned

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 06/30/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: No Update Planned

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/30/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: No Update Planned

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/27/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Varies

HWTS: Hazardous Waste Tracking System

DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 04/08/2021
Date Data Arrived at EDR: 04/09/2021
Date Made Active in Reports: 04/20/2021
Number of Days to Update: 11

Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 03/17/2021
Date Data Arrived at EDR: 03/18/2021
Date Made Active in Reports: 03/25/2021
Number of Days to Update: 7

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 02/02/2021
Date Data Arrived at EDR: 02/04/2021
Date Made Active in Reports: 04/23/2021
Number of Days to Update: 78

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 06/15/2021
Date Data Arrived at EDR: 06/16/2021
Date Made Active in Reports: 07/02/2021
Number of Days to Update: 16

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 06/15/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 04/21/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 81

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 12/17/2020
Date Data Arrived at EDR: 01/28/2021
Date Made Active in Reports: 04/16/2021
Number of Days to Update: 78

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/12/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 75

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 01/14/2021
Date Data Arrived at EDR: 01/15/2021
Date Made Active in Reports: 04/05/2021
Number of Days to Update: 80

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 06/23/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 2

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 05/10/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 05/11/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 04/22/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 01/19/2021
Date Data Arrived at EDR: 01/21/2021
Date Made Active in Reports: 01/28/2021
Number of Days to Update: 7

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 12/03/2020
Date Data Arrived at EDR: 01/26/2021
Date Made Active in Reports: 04/14/2021
Number of Days to Update: 78

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List
Cupa facility list

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/12/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 75

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List
Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 06/08/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: No Update Planned

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 04/08/2021
Date Data Arrived at EDR: 04/13/2021
Date Made Active in Reports: 06/28/2021
Number of Days to Update: 76

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 06/29/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 04/12/2021
Date Data Arrived at EDR: 04/13/2021
Date Made Active in Reports: 06/28/2021
Number of Days to Update: 76

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2021
Date Data Arrived at EDR: 02/18/2021
Date Made Active in Reports: 05/10/2021
Number of Days to Update: 81

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 02/04/2021
Date Data Arrived at EDR: 04/16/2021
Date Made Active in Reports: 04/21/2021
Number of Days to Update: 5
Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 07/12/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 06/28/2021
Number of Days to Update: 11
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 03/02/2021
Date Data Arrived at EDR: 04/16/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 81
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 02/02/2021
Date Data Arrived at EDR: 04/28/2021
Date Made Active in Reports: 07/13/2021
Number of Days to Update: 76

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 05/12/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: No Update Planned

MENDOCINO COUNTY:

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 04/07/2021
Date Made Active in Reports: 06/24/2021
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/13/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 73

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 05/12/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 06/02/2021
Next Scheduled EDR Contact: 09/06/3021
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 06/23/2021
Date Data Arrived at EDR: 06/23/2021
Date Made Active in Reports: 06/24/2021
Number of Days to Update: 1

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 04/29/2021
Date Made Active in Reports: 07/15/2021
Number of Days to Update: 77

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/12/2021
Number of Days to Update: 9

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 04/29/2021
Next Scheduled EDR Contact: 08/16/2021
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 04/29/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 05/26/2021
Date Made Active in Reports: 06/01/2021
Number of Days to Update: 6

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64

Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 06/29/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 14
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 06/08/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 06/29/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 14
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 06/07/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 03/30/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/23/2021
Number of Days to Update: 83
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 03/30/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/25/2021
Number of Days to Update: 85
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 04/29/2021
Date Made Active in Reports: 05/03/2021
Number of Days to Update: 4
Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 05/19/2021
Date Data Arrived at EDR: 05/19/2021
Date Made Active in Reports: 06/07/2021
Number of Days to Update: 19

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 03/02/2021
Date Data Arrived at EDR: 03/03/2021
Date Made Active in Reports: 05/21/2021
Number of Days to Update: 79

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 05/28/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 11/23/2020
Date Made Active in Reports: 02/08/2021
Number of Days to Update: 77

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing

A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/14/2020
Date Data Arrived at EDR: 07/16/2020
Date Made Active in Reports: 09/29/2020
Number of Days to Update: 75

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing

Cupa facilities

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77

Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77

Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 06/08/2021
Next Scheduled EDR Contact: 09/27/2021
Data Release Frequency: No Update Planned

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 05/07/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 05/14/2021
Number of Days to Update: 3

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 05/06/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/10/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 06/02/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: No Update Planned

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 05/12/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 02/24/2021
Date Data Arrived at EDR: 02/26/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 82

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 05/18/2021
Next Scheduled EDR Contact: 09/06/2021
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 05/12/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 05/12/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: No Update Planned

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 03/23/2021
Date Data Arrived at EDR: 03/25/2021
Date Made Active in Reports: 06/10/2021
Number of Days to Update: 77

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 09/12/2021
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 07/02/2021
Date Data Arrived at EDR: 07/06/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 8

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 06/28/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 04/01/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/23/2021
Number of Days to Update: 83

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 06/15/2021
Next Scheduled EDR Contact: 10/04/2021
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/17/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 78

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 05/25/2021
Next Scheduled EDR Contact: 09/13/2021
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 01/13/2021
Date Data Arrived at EDR: 01/14/2021
Date Made Active in Reports: 04/06/2021
Number of Days to Update: 82

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 04/26/2021
Date Data Arrived at EDR: 04/28/2021
Date Made Active in Reports: 07/13/2021
Number of Days to Update: 76

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 03/29/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 81

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 03/29/2021
Date Data Arrived at EDR: 04/21/2021
Date Made Active in Reports: 04/23/2021
Number of Days to Update: 2

Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 03/09/2021
Date Made Active in Reports: 03/31/2021
Number of Days to Update: 22

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 06/04/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 03/26/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/23/2021
Number of Days to Update: 83

Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 06/22/2021
Next Scheduled EDR Contact: 10/11/2021
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 04/21/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 05/12/2021
Number of Days to Update: 20

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/28/2021
Number of Days to Update: 78

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/11/2021
Next Scheduled EDR Contact: 08/23/2021
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/07/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 02/11/2021
Date Made Active in Reports: 02/24/2021
Number of Days to Update: 13

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/13/2021
Next Scheduled EDR Contact: 08/30/2021
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/03/2021
Next Scheduled EDR Contact: 09/20/2021
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

NEW LIFE MENS FACILITY
429 S. SAN JOAQUIN STREET
STOCKTON, CA 95203

TARGET PROPERTY COORDINATES

Latitude (North):	37.948629 - 37° 56' 55.06''
Longitude (West):	121.286367 - 121° 17' 10.92''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	650566.6
UTM Y (Meters):	4201294.5
Elevation:	17 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5640424 STOCKTON WEST, CA
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 17 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06077C0460F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06077C0470F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
STOCKTON WEST	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles West
Site Name:	Mccormick & Baxter Creosoting Co
Site EPA ID Number:	CAD009106527
Surficial Aquifer Flow Dir.:	East
Measured Depth to Water:	16 feet to 40 feet.
Hydraulic Connection:	The surficial aquifer recharges the lower aquifer.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site-specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 6607856.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	New Life Mens Facility	CLIENT:	Condor Earth Technologies, Inc
ADDRESS:	429 S. San Joaquin Street Stockton CA 95203	CONTACT:	Rebecca Selvage
LAT/LONG:	37.948629 / 121.286367	INQUIRY #:	6607856.2s
		DATE:	August 05, 2021 1:36 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: YELLOWLARK

Soil Surface Texture: gravelly loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 107 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	7 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:
2	7 inches	38 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:
3	38 inches	46 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:
4	46 inches	53 inches	gravelly clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
5	53 inches	59 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:
6	59 inches	61 inches	cemented	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0 Min: 0	Max: Min:

Soil Map ID: 2

Soil Component Name: JACKTONE

Soil Surface Texture: clay

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 152 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	22 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
2	22 inches	33 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
3	33 inches	37 inches	indurated	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
4	37 inches	46 inches	stratified sandy loam to clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
5	46 inches	59 inches	cemented	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
J67	USGS40000186245	1/4 - 1/2 Mile NW
L89	USGS40000186228	1/4 - 1/2 Mile ESE
AB223	USGS40000186208	1/2 - 1 Mile SW
AN394	USGS40000186278	1/2 - 1 Mile NNE
421	USGS40000186224	1/2 - 1 Mile WSW
AU450	USGS40000186210	1/2 - 1 Mile WSW
AY506	USGS40000186212	1/2 - 1 Mile ESE
BB558	USGS40000186216	1/2 - 1 Mile WSW
BB597	USGS40000186217	1/2 - 1 Mile WSW
BJ679	USGS40000186209	1/2 - 1 Mile WSW
BN756	USGS40000186226	1/2 - 1 Mile WSW
BJ797	USGS40000186205	1/2 - 1 Mile WSW
820	USGS40000186293	1/2 - 1 Mile NNW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AA219	CA3900732	1/2 - 1 Mile South

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CAEDF0000076911	0 - 1/8 Mile SSW
B2	CAEDF0000087312	0 - 1/8 Mile NW
C3	CAEDF0000082278	1/8 - 1/4 Mile SW
B4	CAEDF0000078563	1/8 - 1/4 Mile WNW
A5	CAEDF0000067917	1/8 - 1/4 Mile SW
B6	CAEDF0000107774	1/8 - 1/4 Mile WNW
B7	CAEDF0000098734	1/8 - 1/4 Mile WNW
B8	CAEDF0000076740	1/8 - 1/4 Mile WNW
B9	CAEDF0000121780	1/8 - 1/4 Mile NW
D10	218	1/8 - 1/4 Mile NE
D11	217	1/8 - 1/4 Mile NE
D12	211	1/8 - 1/4 Mile NE
D13	23206	1/8 - 1/4 Mile NE
D14	23118	1/8 - 1/4 Mile NE
D15	23099	1/8 - 1/4 Mile NE
B16	CAEDF0000013613	1/8 - 1/4 Mile WNW
A17	CAEDF0000010040	1/8 - 1/4 Mile SW
A18	CAEDF0000069433	1/8 - 1/4 Mile SW
B19	CAEDF0000043496	1/8 - 1/4 Mile WNW
B20	CAEDF0000105389	1/8 - 1/4 Mile NW
B21	CAEDF0000042556	1/8 - 1/4 Mile WNW
C22	CAEDF0000062173	1/8 - 1/4 Mile SW
E23	CAEDF0000009851	1/8 - 1/4 Mile NNE
C24	CAEDF0000086265	1/8 - 1/4 Mile SW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
E25	CAEDF0000014019	1/8 - 1/4 Mile North
D26	CADDW0000021686	1/8 - 1/4 Mile ENE
E27	CAEDF0000136021	1/8 - 1/4 Mile NNE
C28	CAEDF0000042559	1/8 - 1/4 Mile WSW
D29	CAEDF0000124287	1/8 - 1/4 Mile NE
D30	CAEDF0000143503	1/8 - 1/4 Mile NE
D31	CAEDF0000037716	1/8 - 1/4 Mile NE
D32	CAEDF0000090417	1/8 - 1/4 Mile NE
E33	CAEDF0000042286	1/8 - 1/4 Mile NNE
D34	CAEDF0000070000	1/8 - 1/4 Mile NE
F35	CAEDF0000107011	1/8 - 1/4 Mile SW
D36	CAEDF0000143211	1/8 - 1/4 Mile NE
D37	CAEDF0000122050	1/8 - 1/4 Mile NE
D38	CAEDF0000112058	1/8 - 1/4 Mile NE
E39	CAEDF0000059032	1/8 - 1/4 Mile NNE
D40	CAEDF0000093810	1/8 - 1/4 Mile NE
G41	CAEDF0000001803	1/8 - 1/4 Mile NE
F42	CAEDF0000135759	1/8 - 1/4 Mile SW
E43	CAEDF0000056606	1/8 - 1/4 Mile North
G44	CAEDF0000074184	1/8 - 1/4 Mile NE
H45	CAEDF0000072227	1/8 - 1/4 Mile WNW
E46	CAEDF0000059975	1/8 - 1/4 Mile NNE
G47	CAEDF0000078558	1/8 - 1/4 Mile NE
F48	CAEDF0000072828	1/8 - 1/4 Mile SW
G49	CAEDF0000021187	1/8 - 1/4 Mile NE
F50	CAEDF0000077304	1/8 - 1/4 Mile SW
F51	CAEDF0000006856	1/8 - 1/4 Mile SW
H52	CAEDF0000112547	1/8 - 1/4 Mile WNW
F53	CAEDF0000113249	1/8 - 1/4 Mile SW
F54	CAEDF0000129440	1/8 - 1/4 Mile SW
F55	CAEDF0000069421	1/8 - 1/4 Mile WSW
G56	CAEDF0000013226	1/8 - 1/4 Mile NE
F57	CAEDF0000101376	1/8 - 1/4 Mile WSW
F58	CAEDF0000092870	1/8 - 1/4 Mile WSW
I59	CAEDF0000103974	1/4 - 1/2 Mile North
J60	CADWR0000032862	1/4 - 1/2 Mile NW
H61	CAEDF0000036945	1/4 - 1/2 Mile WNW
H62	CAEDF0000078877	1/4 - 1/2 Mile WNW
F63	CAEDF0000013892	1/4 - 1/2 Mile WSW
K64	CAEDF0000003127	1/4 - 1/2 Mile WSW
I65	CAEDF0000089947	1/4 - 1/2 Mile NNE
G66	CAEDF0000132634	1/4 - 1/2 Mile NE
K68	CAEDF0000104253	1/4 - 1/2 Mile WSW
K69	CAEDF0000127994	1/4 - 1/2 Mile WSW
H70	CAEDF0000140085	1/4 - 1/2 Mile WNW
H71	CAEDF0000116271	1/4 - 1/2 Mile WNW
K72	CAEDF0000052904	1/4 - 1/2 Mile WSW
H73	CAEDF0000109324	1/4 - 1/2 Mile WNW
H74	CAEDF0000095306	1/4 - 1/2 Mile WNW
H75	CAEDF0000127364	1/4 - 1/2 Mile WNW
H76	CAEDF0000053825	1/4 - 1/2 Mile WNW
H77	CAEDF0000058325	1/4 - 1/2 Mile WNW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
K78	CAEDF0000113857	1/4 - 1/2 Mile WSW
H79	CAEDF0000103907	1/4 - 1/2 Mile WNW
H80	CAEDF0000023008	1/4 - 1/2 Mile WNW
J81	CAEDF0000037403	1/4 - 1/2 Mile WNW
H82	CAEDF0000114722	1/4 - 1/2 Mile WNW
J83	CAEDF0000023538	1/4 - 1/2 Mile WNW
H84	CAEDF0000078357	1/4 - 1/2 Mile WNW
J85	CAEDF0000039571	1/4 - 1/2 Mile NW
J86	CAEDF0000006401	1/4 - 1/2 Mile WNW
J87	CAEDF0000106734	1/4 - 1/2 Mile WNW
J88	CAEDF0000095719	1/4 - 1/2 Mile WNW
J90	CADWR9000038004	1/4 - 1/2 Mile NW
M91	CAEDF0000019860	1/4 - 1/2 Mile NNW
92	CADWR0000023591	1/4 - 1/2 Mile SSE
M93	CAEDF0000122222	1/4 - 1/2 Mile North
M94	CAEDF0000113404	1/4 - 1/2 Mile NNW
L95	CAEDF0000032171	1/4 - 1/2 Mile SE
N96	CAEDF0000015392	1/4 - 1/2 Mile SE
N97	CAEDF0000008144	1/4 - 1/2 Mile SE
L98	CAEDF0000105594	1/4 - 1/2 Mile ESE
N99	CAEDF0000048260	1/4 - 1/2 Mile SE
N100	CAEDF0000054135	1/4 - 1/2 Mile SE
N101	CAEDF0000067734	1/4 - 1/2 Mile SE
O102	CADDW0000003016	1/4 - 1/2 Mile SSW
P103	CAEDF0000134379	1/4 - 1/2 Mile NNW
O104	219	1/4 - 1/2 Mile SSW
O105	23104	1/4 - 1/2 Mile SSW
Q106	CAEDF0000069768	1/4 - 1/2 Mile WSW
P107	CAEDF0000120623	1/4 - 1/2 Mile NNW
Q108	CAEDF0000060451	1/4 - 1/2 Mile WSW
P109	CAEDF0000084919	1/4 - 1/2 Mile NNW
P110	CAEDF0000032585	1/4 - 1/2 Mile NNW
Q111	CAEDF0000094624	1/4 - 1/2 Mile WSW
R112	CAEDF0000121099	1/4 - 1/2 Mile NNW
R113	CAEDF0000022877	1/4 - 1/2 Mile NNW
R114	CAEDF0000099669	1/4 - 1/2 Mile NW
R115	CAEDF0000014622	1/4 - 1/2 Mile NW
R116	CAEDF0000084659	1/4 - 1/2 Mile NW
S117	CAEDF0000082174	1/4 - 1/2 Mile NW
Q118	CAEDF0000096884	1/4 - 1/2 Mile WSW
R119	CAEDF0000135715	1/4 - 1/2 Mile NW
Q120	CAEDF0000077567	1/4 - 1/2 Mile WSW
Q121	CAEDF0000131650	1/4 - 1/2 Mile WSW
Q122	CAEDF0000112936	1/4 - 1/2 Mile WSW
Q123	CAEDF0000057449	1/4 - 1/2 Mile WSW
Q124	CAEDF0000116934	1/4 - 1/2 Mile WSW
Q125	CAEDF0000070072	1/4 - 1/2 Mile WSW
Q126	CAEDF0000047677	1/4 - 1/2 Mile WSW
Q127	CAEDF0000090990	1/4 - 1/2 Mile WSW
S128	CAEDF0000090033	1/4 - 1/2 Mile NW
S129	CAEDF0000072030	1/4 - 1/2 Mile NW
S130	CAEDF0000041742	1/4 - 1/2 Mile NW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
Q131	CAEDF0000021952	1/4 - 1/2 Mile WSW
Q132	CAEDF0000112111	1/4 - 1/2 Mile WSW
T133	CAEDF0000080277	1/4 - 1/2 Mile NE
R134	CAEDF0000016469	1/4 - 1/2 Mile NW
R135	CAEDF0000093846	1/4 - 1/2 Mile NW
Q136	CAEDF0000020067	1/4 - 1/2 Mile WSW
S137	CAEDF0000049496	1/4 - 1/2 Mile NW
S138	CAEDF0000126026	1/4 - 1/2 Mile NW
R139	CAEDF0000117056	1/4 - 1/2 Mile NW
T140	CAEDF0000050003	1/4 - 1/2 Mile NE
Q141	CAEDF0000121640	1/4 - 1/2 Mile WSW
T142	CAEDF0000019276	1/4 - 1/2 Mile NE
T143	CAEDF0000008571	1/4 - 1/2 Mile NE
T144	CAEDF0000077524	1/4 - 1/2 Mile NE
T145	CAEDF0000074934	1/4 - 1/2 Mile NE
S146	CAEDF0000044422	1/4 - 1/2 Mile NW
T147	CAEDF0000052137	1/2 - 1 Mile NE
T148	CAEDF0000018440	1/2 - 1 Mile NE
R149	CAEDF0000117252	1/2 - 1 Mile NNW
R150	CAEDF0000117776	1/2 - 1 Mile NNW
151	CADWR0000006709	1/2 - 1 Mile NNE
T152	CAEDF0000101272	1/2 - 1 Mile NE
T153	CAEDF0000121952	1/2 - 1 Mile NE
U154	CAEDF0000001628	1/2 - 1 Mile NNW
V155	CADWR0000031560	1/2 - 1 Mile South
W156	CAEDF0000012882	1/2 - 1 Mile North
W157	CAEDF0000110617	1/2 - 1 Mile North
W158	CAEDF0000014212	1/2 - 1 Mile North
U159	CAEDF0000019257	1/2 - 1 Mile NNW
U160	CAEDF0000143678	1/2 - 1 Mile NNW
W161	CAEDF0000125156	1/2 - 1 Mile North
U162	CAEDF0000138759	1/2 - 1 Mile NNW
X163	CAEDF0000019453	1/2 - 1 Mile WSW
W164	CAEDF0000103605	1/2 - 1 Mile North
W165	CAEDF0000069123	1/2 - 1 Mile North
V166	CAEDF0000084044	1/2 - 1 Mile South
U167	CAEDF0000122508	1/2 - 1 Mile NNW
X168	CAEDF0000068070	1/2 - 1 Mile WSW
X169	CAEDF0000123085	1/2 - 1 Mile WSW
X170	CAEDF0000044026	1/2 - 1 Mile WSW
W171	CAEDF0000105410	1/2 - 1 Mile North
W172	CAEDF0000045411	1/2 - 1 Mile North
W173	CAEDF0000045143	1/2 - 1 Mile North
W174	CAEDF0000118076	1/2 - 1 Mile North
W175	CAEDF0000023376	1/2 - 1 Mile North
W176	CAEDF0000111080	1/2 - 1 Mile North
W177	CAEDF0000137759	1/2 - 1 Mile North
W178	CAEDF0000037104	1/2 - 1 Mile North
W179	CAEDF0000072790	1/2 - 1 Mile North
Y180	CAEDF0000082615	1/2 - 1 Mile NNE
Y181	CAEDF0000000716	1/2 - 1 Mile NNE
Y182	CAEDF0000120591	1/2 - 1 Mile NNE

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
Y183	CAEDF0000114489	1/2 - 1 Mile NNE
X184	CAEDF0000115042	1/2 - 1 Mile WSW
Y185	CAEDF0000009353	1/2 - 1 Mile NNE
X186	CAEDF0000136662	1/2 - 1 Mile WSW
W187	CAEDF0000102673	1/2 - 1 Mile North
W188	CAEDF0000096184	1/2 - 1 Mile North
Y189	CAEDF0000016926	1/2 - 1 Mile NNE
Y190	CAEDF0000103395	1/2 - 1 Mile NNE
Z191	CAEDF0000079132	1/2 - 1 Mile NNE
W192	CAEDF0000123976	1/2 - 1 Mile North
X193	CAEDF0000037271	1/2 - 1 Mile WSW
W194	CAEDF0000010322	1/2 - 1 Mile North
W195	CAEDF0000121795	1/2 - 1 Mile North
W196	CAEDF0000095882	1/2 - 1 Mile North
W197	CAEDF0000034845	1/2 - 1 Mile North
W198	CAEDF0000039428	1/2 - 1 Mile North
W199	CAEDF0000128051	1/2 - 1 Mile North
W200	CAEDF0000109005	1/2 - 1 Mile North
V201	CAEDF0000140633	1/2 - 1 Mile South
V202	CAEDF0000119993	1/2 - 1 Mile South
V203	CAEDF0000085298	1/2 - 1 Mile South
AA204	CAEDF0000128528	1/2 - 1 Mile SSW
W205	CAEDF0000102989	1/2 - 1 Mile North
AA206	CAEDF0000097503	1/2 - 1 Mile South
V207	CAEDF0000031305	1/2 - 1 Mile South
Y208	CAEDF0000116424	1/2 - 1 Mile NNE
AA209	CAEDF0000052736	1/2 - 1 Mile South
AA210	CAEDF0000017580	1/2 - 1 Mile South
W211	CAEDF0000020903	1/2 - 1 Mile North
W212	CAEDF0000052411	1/2 - 1 Mile North
W213	CAEDF0000107457	1/2 - 1 Mile North
AA214	CAEDF0000134365	1/2 - 1 Mile South
AA215	CAEDF0000063767	1/2 - 1 Mile South
AA216	CAEDF0000045491	1/2 - 1 Mile South
W217	CAEDF0000078607	1/2 - 1 Mile North
W218	CAEDF0000034789	1/2 - 1 Mile North
AA220	CAEDF0000100604	1/2 - 1 Mile South
AA221	CAEDF0000085297	1/2 - 1 Mile South
Z222	CAEDF0000003554	1/2 - 1 Mile North
AB224	CADWR9000037991	1/2 - 1 Mile SW
AA225	CAEDF0000141399	1/2 - 1 Mile South
AA226	CAEDF0000089144	1/2 - 1 Mile South
AA227	CAEDF0000118673	1/2 - 1 Mile South
AA228	CAEDF0000018905	1/2 - 1 Mile SSW
Z229	CAEDF0000021064	1/2 - 1 Mile North
AA230	CAEDF0000086057	1/2 - 1 Mile South
Z231	CAEDF0000008113	1/2 - 1 Mile NNE
Z232	CAEDF0000069586	1/2 - 1 Mile NNE
Z233	CAEDF0000086108	1/2 - 1 Mile NNE
Z234	CAEDF0000038087	1/2 - 1 Mile NNE
Z235	CAEDF0000034881	1/2 - 1 Mile NNE
Z236	CAEDF0000054842	1/2 - 1 Mile NNE

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AC237	CAEDF0000113916	1/2 - 1 Mile North
AC238	CAEDF0000018892	1/2 - 1 Mile North
AC239	CAEDF0000140593	1/2 - 1 Mile NNE
AC240	CAEDF0000117666	1/2 - 1 Mile NNE
AC241	CAEDF0000045767	1/2 - 1 Mile NNE
AD242	CAEDF0000059623	1/2 - 1 Mile NNE
AD243	CAEDF0000013595	1/2 - 1 Mile NNE
AD244	CAEDF0000143294	1/2 - 1 Mile NNE
AC245	CAEDF0000089611	1/2 - 1 Mile NNE
AD246	CAEDF0000112493	1/2 - 1 Mile NNE
AD247	CAEDF0000121557	1/2 - 1 Mile NNE
AD248	CAEDF0000100591	1/2 - 1 Mile NNE
AE249	CAEDF0000076338	1/2 - 1 Mile WNW
AE250	CAEDF0000049826	1/2 - 1 Mile WNW
AF251	CAEDF0000023856	1/2 - 1 Mile SE
AE252	CAEDF0000073831	1/2 - 1 Mile WNW
AF253	CAEDF0000114606	1/2 - 1 Mile SE
AF254	CAEDF0000110699	1/2 - 1 Mile SE
AF255	CAEDF0000042103	1/2 - 1 Mile SE
AG256	CAEDF0000139513	1/2 - 1 Mile SSE
AE257	CAEDF0000138652	1/2 - 1 Mile WNW
AG258	CAEDF0000114397	1/2 - 1 Mile SSE
AH259	CAEDF0000095323	1/2 - 1 Mile WNW
AH260	CAEDF0000053119	1/2 - 1 Mile WNW
AH261	CAEDF0000045930	1/2 - 1 Mile WNW
AF262	CAEDF0000099575	1/2 - 1 Mile SE
AF263	CAEDF0000099882	1/2 - 1 Mile SE
AG264	CAEDF0000046457	1/2 - 1 Mile SSE
AG265	CAEDF0000104068	1/2 - 1 Mile SSE
AF266	CAEDF0000024123	1/2 - 1 Mile SE
AI267	CAEDF0000059536	1/2 - 1 Mile West
AI268	CAEDF0000016711	1/2 - 1 Mile West
AE269	CAEDF0000133197	1/2 - 1 Mile WNW
AH270	CAEDF0000002813	1/2 - 1 Mile WNW
AF271	CAEDF0000005265	1/2 - 1 Mile SE
AF272	CAEDF0000091608	1/2 - 1 Mile SE
AE273	CAEDF0000092001	1/2 - 1 Mile WNW
AH274	CAEDF0000078886	1/2 - 1 Mile West
AJ275	CAEDF0000005348	1/2 - 1 Mile SE
AH276	CAEDF0000114341	1/2 - 1 Mile WNW
AF277	CAEDF0000131554	1/2 - 1 Mile SE
AH278	CAEDF0000010631	1/2 - 1 Mile WNW
AE279	CAEDF0000011652	1/2 - 1 Mile WNW
AE280	CAEDF0000141752	1/2 - 1 Mile WNW
AJ281	CAEDF0000037351	1/2 - 1 Mile SE
AF282	CAEDF0000083776	1/2 - 1 Mile SE
AH283	CAEDF0000119316	1/2 - 1 Mile WNW
AJ284	CAEDF0000080077	1/2 - 1 Mile SE
AE285	CAEDF0000078319	1/2 - 1 Mile WNW
AJ286	CAEDF0000100594	1/2 - 1 Mile SE
AJ287	CAEDF0000020251	1/2 - 1 Mile SE
AJ288	CAEDF0000112665	1/2 - 1 Mile SE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AG289	CAEDF0000033216	1/2 - 1 Mile SSE
AH290	CAEDF0000088132	1/2 - 1 Mile WNW
AE291	CAEDF0000125352	1/2 - 1 Mile WNW
AH292	CAEDF0000105907	1/2 - 1 Mile WNW
AJ293	CAEDF0000097612	1/2 - 1 Mile SE
AE294	CAEDF0000076112	1/2 - 1 Mile WNW
AJ295	CAEDF0000019381	1/2 - 1 Mile SE
AJ296	CAEDF0000085474	1/2 - 1 Mile SE
AJ297	CAEDF0000114905	1/2 - 1 Mile SE
AJ298	CAEDF0000048136	1/2 - 1 Mile SE
AK299	CAEDF0000084390	1/2 - 1 Mile SE
AH300	CAEDF0000120040	1/2 - 1 Mile WNW
AJ301	CAEDF0000087019	1/2 - 1 Mile SE
AE302	CAEDF0000058752	1/2 - 1 Mile WNW
AE303	CAEDF0000046432	1/2 - 1 Mile WNW
AL304	CAEDF0000110426	1/2 - 1 Mile NNW
AJ305	CAEDF0000022395	1/2 - 1 Mile SE
AJ306	CAEDF0000074457	1/2 - 1 Mile SE
AJ307	CAEDF0000120191	1/2 - 1 Mile SE
AJ308	CAEDF0000010633	1/2 - 1 Mile SE
AH309	CAEDF0000033227	1/2 - 1 Mile WNW
AK310	CAEDF0000089060	1/2 - 1 Mile SE
AH311	CAEDF0000129528	1/2 - 1 Mile WNW
AJ312	CAEDF0000061284	1/2 - 1 Mile SE
AJ313	CAEDF0000077297	1/2 - 1 Mile SE
AJ314	CAEDF0000115445	1/2 - 1 Mile SE
AE315	CAEDF0000002101	1/2 - 1 Mile WNW
AJ316	CAEDF0000069922	1/2 - 1 Mile SE
AJ317	CAEDF0000099858	1/2 - 1 Mile SE
AE318	CAEDF0000064720	1/2 - 1 Mile WNW
AH319	CAEDF0000140183	1/2 - 1 Mile WNW
AE320	CAEDF0000088141	1/2 - 1 Mile WNW
AL321	CAEDF0000020151	1/2 - 1 Mile NNW
AL322	CAEDF0000093843	1/2 - 1 Mile NNW
AH323	CAEDF0000012839	1/2 - 1 Mile WNW
AJ324	CAEDF0000076498	1/2 - 1 Mile SE
AE325	CAEDF0000071690	1/2 - 1 Mile WNW
AE326	CAEDF0000011115	1/2 - 1 Mile WNW
AK327	CAEDF0000101422	1/2 - 1 Mile SE
AJ328	CAEDF0000043390	1/2 - 1 Mile SE
AJ329	CAEDF0000087806	1/2 - 1 Mile SE
AK330	CAEDF0000015074	1/2 - 1 Mile SE
AL331	CAEDF0000024130	1/2 - 1 Mile NNW
AE332	CAEDF0000043192	1/2 - 1 Mile WNW
AH333	CAEDF0000062723	1/2 - 1 Mile WNW
AL334	CAEDF0000069061	1/2 - 1 Mile NNW
AM335	CAEDF0000056308	1/2 - 1 Mile WNW
AK336	CAEDF0000065109	1/2 - 1 Mile SE
AM337	CAEDF0000105531	1/2 - 1 Mile WNW
AH338	CAEDF0000038035	1/2 - 1 Mile West
AK339	CAEDF0000075714	1/2 - 1 Mile SE
AK340	CAEDF0000029720	1/2 - 1 Mile SE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AL341	CAEDF0000051410	1/2 - 1 Mile NNW
AK342	CAEDF0000085755	1/2 - 1 Mile SE
AH343	CAEDF0000107819	1/2 - 1 Mile West
AL344	CAEDF0000127300	1/2 - 1 Mile NNW
AL345	CAEDF0000034500	1/2 - 1 Mile NNW
AL346	CAEDF0000134021	1/2 - 1 Mile NNW
AK347	CAEDF0000135472	1/2 - 1 Mile SE
AK348	CAEDF0000052194	1/2 - 1 Mile SE
AH349	CAEDF0000116536	1/2 - 1 Mile West
AH350	CAEDF0000102958	1/2 - 1 Mile West
AH351	CAEDF0000019950	1/2 - 1 Mile West
AL352	CAEDF0000043909	1/2 - 1 Mile North
AL353	CAEDF0000021260	1/2 - 1 Mile NNW
AM354	CAEDF0000060399	1/2 - 1 Mile WNW
AM355	CAEDF0000122903	1/2 - 1 Mile WNW
AM356	CAEDF0000131281	1/2 - 1 Mile WNW
AK357	CAEDF0000004539	1/2 - 1 Mile SE
AM358	CAEDF0000082572	1/2 - 1 Mile WNW
AM359	CAEDF0000088425	1/2 - 1 Mile WNW
AM360	CAEDF0000015388	1/2 - 1 Mile WNW
AN361	CADDW0000020544	1/2 - 1 Mile NNE
AO362	CAEDF0000089738	1/2 - 1 Mile North
AO363	CAEDF0000056284	1/2 - 1 Mile North
AO364	CAEDF0000021288	1/2 - 1 Mile North
AO365	CAEDF0000003552	1/2 - 1 Mile North
AO366	CAEDF0000045604	1/2 - 1 Mile North
AO367	CAEDF0000140092	1/2 - 1 Mile North
AO368	CAEDF0000128362	1/2 - 1 Mile North
AO369	CAEDF0000093450	1/2 - 1 Mile North
AO370	CAEDF0000116132	1/2 - 1 Mile North
AL371	CAEDF0000039101	1/2 - 1 Mile NNW
AL372	CAEDF0000090798	1/2 - 1 Mile NNW
AP373	CAEDF0000040340	1/2 - 1 Mile NNW
AL374	CAEDF0000045127	1/2 - 1 Mile NNW
AL375	CAEDF0000130878	1/2 - 1 Mile NNW
AL376	CAEDF0000070354	1/2 - 1 Mile NNW
AM377	CAEDF0000097869	1/2 - 1 Mile WNW
AM378	CAEDF0000012728	1/2 - 1 Mile WNW
AO379	CAEDF0000074282	1/2 - 1 Mile North
AO380	CAEDF0000017121	1/2 - 1 Mile North
AO381	CAEDF0000012921	1/2 - 1 Mile North
AL382	CAEDF0000126082	1/2 - 1 Mile NNW
AL383	CAEDF0000080748	1/2 - 1 Mile NNW
AO384	CAEDF0000091038	1/2 - 1 Mile North
AK385	CAEDF0000079651	1/2 - 1 Mile SE
AM386	CAEDF0000037723	1/2 - 1 Mile WNW
AO387	CAEDF0000095143	1/2 - 1 Mile North
AM388	CAEDF0000106720	1/2 - 1 Mile WNW
AP389	CAEDF0000109007	1/2 - 1 Mile NNW
AK390	CAEDF0000041060	1/2 - 1 Mile SE
AL391	CAEDF0000038712	1/2 - 1 Mile NNW
AL392	CAEDF0000097107	1/2 - 1 Mile NNW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AK393	CAEDF0000140466	1/2 - 1 Mile SE
AO395	CAEDF0000103586	1/2 - 1 Mile North
AP396	CADWR0000000816	1/2 - 1 Mile NNW
AK397	CAEDF0000070740	1/2 - 1 Mile SE
AP398	CAEDF0000032709	1/2 - 1 Mile NNW
AQ399	CAEDF0000097139	1/2 - 1 Mile SSW
AK400	CAEDF0000133509	1/2 - 1 Mile SE
AP401	CAEDF0000126427	1/2 - 1 Mile NNW
AK402	CAEDF0000072240	1/2 - 1 Mile SE
AQ403	CAEDF0000036508	1/2 - 1 Mile SSW
AL404	CAEDF0000077600	1/2 - 1 Mile NNW
AP405	CAEDF0000078723	1/2 - 1 Mile NNW
AK406	CAEDF0000063490	1/2 - 1 Mile SE
AQ407	CAEDF0000057319	1/2 - 1 Mile SSW
AM408	CAEDF0000092697	1/2 - 1 Mile WNW
AL409	CAEDF0000141228	1/2 - 1 Mile NNW
AL410	CAEDF0000120139	1/2 - 1 Mile NNW
AL411	CAEDF0000111780	1/2 - 1 Mile NNW
AM412	CAEDF0000055943	1/2 - 1 Mile WNW
AM413	CAEDF0000015701	1/2 - 1 Mile WNW
AM414	CAEDF0000091393	1/2 - 1 Mile WNW
AM415	CAEDF0000075431	1/2 - 1 Mile WNW
AR416	CAEDF0000083905	1/2 - 1 Mile North
AR417	CAEDF0000107665	1/2 - 1 Mile NNW
AS418	CAEDF0000091430	1/2 - 1 Mile SE
AS419	CAEDF0000058203	1/2 - 1 Mile SE
AP420	CAEDF0000113655	1/2 - 1 Mile NNW
AQ422	CAEDF0000132032	1/2 - 1 Mile SSW
AQ423	CAEDF0000115784	1/2 - 1 Mile SSW
AS424	CAEDF0000139579	1/2 - 1 Mile SE
AS425	CAEDF0000118106	1/2 - 1 Mile SE
AP426	CAEDF0000097615	1/2 - 1 Mile NNW
AM427	CAEDF0000126418	1/2 - 1 Mile WNW
AM428	CAEDF0000117868	1/2 - 1 Mile WNW
AS429	CAEDF0000041011	1/2 - 1 Mile SE
AQ430	CAEDF0000141020	1/2 - 1 Mile SSW
AT431	CAEDF0000038137	1/2 - 1 Mile West
AQ432	CAEDF0000115685	1/2 - 1 Mile SSW
AQ433	CAEDF0000035067	1/2 - 1 Mile SSW
AQ434	CAEDF0000077063	1/2 - 1 Mile SSW
AR435	CAEDF0000048735	1/2 - 1 Mile NNW
AT436	CAEDF0000024047	1/2 - 1 Mile West
AT437	CAEDF0000131581	1/2 - 1 Mile WNW
AT438	CAEDF0000091375	1/2 - 1 Mile WNW
AQ439	CAEDF0000062706	1/2 - 1 Mile SSW
AQ440	CAEDF0000094425	1/2 - 1 Mile SSW
AQ441	CAEDF0000115616	1/2 - 1 Mile SSW
AR442	CAEDF0000116613	1/2 - 1 Mile NNW
AU443	CAEDF0000038113	1/2 - 1 Mile WSW
AQ444	CAEDF0000138419	1/2 - 1 Mile SSW
AV445	CAEDF0000122640	1/2 - 1 Mile SSW
AT446	CAEDF0000097812	1/2 - 1 Mile West

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AT447	CAEDF0000125264	1/2 - 1 Mile West
AW448	CAEDF0000022908	1/2 - 1 Mile NNW
AQ449	CAEDF0000107382	1/2 - 1 Mile SSW
AQ451	CAEDF0000041944	1/2 - 1 Mile SSW
AW452	CAEDF0000089000	1/2 - 1 Mile NNW
AQ453	CAEDF0000130388	1/2 - 1 Mile SSW
AQ454	CAEDF0000070462	1/2 - 1 Mile SSW
AQ455	CAEDF0000034255	1/2 - 1 Mile SSW
AQ456	CAEDF0000084767	1/2 - 1 Mile SSW
AQ457	CAEDF0000069453	1/2 - 1 Mile SSW
AQ458	CAEDF0000054270	1/2 - 1 Mile SSW
AW459	CAEDF0000137400	1/2 - 1 Mile NNW
460	CADPR0000003838	1/2 - 1 Mile East
AU461	CAEDF0000076393	1/2 - 1 Mile WSW
AW462	CAEDF0000032600	1/2 - 1 Mile NNW
AR463	CAEDF0000091681	1/2 - 1 Mile North
AV464	CAEDF0000039117	1/2 - 1 Mile SSW
AW465	CAEDF0000035646	1/2 - 1 Mile NNW
AW466	CAEDF0000122962	1/2 - 1 Mile NNW
AW467	CAEDF0000097398	1/2 - 1 Mile NNW
AQ468	CAEDF0000099494	1/2 - 1 Mile SSW
AU469	CAEDF0000022118	1/2 - 1 Mile WSW
AU470	CAEDF0000112789	1/2 - 1 Mile WSW
AV471	CAEDF0000004300	1/2 - 1 Mile SSW
AQ472	CAEDF0000093229	1/2 - 1 Mile SSW
AQ473	CAEDF0000033846	1/2 - 1 Mile SSW
AW474	CAEDF0000119474	1/2 - 1 Mile NNW
AW475	CAEDF0000032785	1/2 - 1 Mile NNW
AW476	CAEDF0000098221	1/2 - 1 Mile NNW
AQ477	CAEDF0000143156	1/2 - 1 Mile SSW
AQ478	CAEDF0000110497	1/2 - 1 Mile SSW
AQ479	CAEDF0000132968	1/2 - 1 Mile SSW
AQ480	CAEDF0000016434	1/2 - 1 Mile SSW
AU481	CAEDF0000082892	1/2 - 1 Mile WSW
AW482	CAEDF0000090186	1/2 - 1 Mile NNW
AV483	CAEDF0000017833	1/2 - 1 Mile SSW
AQ484	CAEDF0000051336	1/2 - 1 Mile SSW
AQ485	CAEDF0000123062	1/2 - 1 Mile SSW
AQ486	CAEDF0000032250	1/2 - 1 Mile SSW
AQ487	CAEDF0000047831	1/2 - 1 Mile SSW
AW488	CAEDF0000009726	1/2 - 1 Mile NNW
AV489	CAEDF0000127755	1/2 - 1 Mile SSW
AQ490	CAEDF0000089970	1/2 - 1 Mile SSW
AQ491	CAEDF0000099806	1/2 - 1 Mile SSW
AV492	CAEDF0000001407	1/2 - 1 Mile SSW
AX493	CAEDF0000084417	1/2 - 1 Mile WNW
AX494	CAEDF0000057419	1/2 - 1 Mile WNW
AQ495	CAEDF0000083207	1/2 - 1 Mile SSW
AQ496	CAEDF0000044631	1/2 - 1 Mile SSW
AV497	CAEDF0000118463	1/2 - 1 Mile SSW
AV498	CAEDF0000108392	1/2 - 1 Mile SSW
499	CADDW0000008792	1/2 - 1 Mile NNE

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AV500	CAEDF0000005004	1/2 - 1 Mile SSW
AV501	CAEDF0000002174	1/2 - 1 Mile SSW
AQ502	CAEDF0000016643	1/2 - 1 Mile SSW
AQ503	CAEDF0000051048	1/2 - 1 Mile SSW
AQ504	CAEDF0000130223	1/2 - 1 Mile SSW
AQ505	CAEDF0000117313	1/2 - 1 Mile SSW
AV507	CAEDF0000107986	1/2 - 1 Mile SSW
AV508	CAEDF0000135037	1/2 - 1 Mile SSW
AV509	CAEDF0000105827	1/2 - 1 Mile SSW
AV510	CAEDF0000125820	1/2 - 1 Mile SSW
AV511	CAEDF0000020635	1/2 - 1 Mile SSW
AV512	CAEDF0000094340	1/2 - 1 Mile SSW
AV513	CAEDF0000087049	1/2 - 1 Mile SSW
AV514	CAEDF0000053996	1/2 - 1 Mile SSW
AZ515	CAEDF0000087369	1/2 - 1 Mile SW
BA516	CAEDF0000072148	1/2 - 1 Mile SSW
BA517	CAEDF0000007855	1/2 - 1 Mile SSW
AV518	CAEDF0000089634	1/2 - 1 Mile SSW
AY519	CAUSGSN00007805	1/2 - 1 Mile ESE
BA520	CAEDF0000074971	1/2 - 1 Mile SSW
BA521	CAEDF0000078894	1/2 - 1 Mile SSW
BA522	CAEDF0000121633	1/2 - 1 Mile SSW
BA523	CAEDF0000046932	1/2 - 1 Mile SSW
BA524	CAEDF0000050179	1/2 - 1 Mile SSW
BA525	CAEDF0000052173	1/2 - 1 Mile SSW
AV526	CAEDF0000142814	1/2 - 1 Mile SSW
AV527	CAEDF0000114373	1/2 - 1 Mile SSW
AV528	CAEDF0000131137	1/2 - 1 Mile SSW
AV529	CAEDF0000016647	1/2 - 1 Mile SSW
AV530	CAEDF0000021113	1/2 - 1 Mile SSW
AV531	CAEDF0000123070	1/2 - 1 Mile SSW
AV532	CAEDF0000102455	1/2 - 1 Mile SSW
AV533	CAEDF0000082142	1/2 - 1 Mile SSW
AZ534	CAEDF0000122401	1/2 - 1 Mile SW
AZ535	CAEDF0000129334	1/2 - 1 Mile SW
AZ536	CAEDF0000053899	1/2 - 1 Mile SW
AZ537	CAEDF0000092734	1/2 - 1 Mile SW
AW538	CAEDF0000060479	1/2 - 1 Mile NNW
AU539	CAEDF0000114569	1/2 - 1 Mile WSW
AW540	CAEDF0000051164	1/2 - 1 Mile NNW
AZ541	CAEDF0000044604	1/2 - 1 Mile SW
AZ542	CAEDF0000033611	1/2 - 1 Mile SW
AV543	CAEDF0000106259	1/2 - 1 Mile SSW
AV544	CAEDF0000078486	1/2 - 1 Mile SSW
AV545	CAEDF0000065412	1/2 - 1 Mile SSW
AZ546	CAEDF0000104628	1/2 - 1 Mile SW
AZ547	CAEDF0000080413	1/2 - 1 Mile SW
AZ548	CAEDF0000023729	1/2 - 1 Mile SW
AV549	CAEDF0000094154	1/2 - 1 Mile SSW
AV550	CAEDF0000088288	1/2 - 1 Mile SSW
AV551	CAEDF0000076959	1/2 - 1 Mile SSW
AV552	CAEDF0000111614	1/2 - 1 Mile SSW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AZ553	CAEDF0000137165	1/2 - 1 Mile SW
AZ554	CAEDF0000084412	1/2 - 1 Mile SW
AW555	CAEDF0000092063	1/2 - 1 Mile NNW
AZ556	CAEDF0000114332	1/2 - 1 Mile SW
AZ557	CAEDF0000103057	1/2 - 1 Mile SW
AV559	CAEDF0000105370	1/2 - 1 Mile SSW
AV560	CAEDF0000082266	1/2 - 1 Mile SSW
AZ561	CAEDF0000059033	1/2 - 1 Mile SW
BB562	CAUSGSN00004781	1/2 - 1 Mile WSW
AZ563	CAEDF0000032524	1/2 - 1 Mile SW
AZ564	CAEDF0000085585	1/2 - 1 Mile SW
AZ565	CAEDF0000120392	1/2 - 1 Mile SW
AV566	CAEDF0000064158	1/2 - 1 Mile SSW
AV567	CAEDF0000096282	1/2 - 1 Mile SSW
AV568	CAEDF0000039302	1/2 - 1 Mile SSW
AV569	CAEDF0000054367	1/2 - 1 Mile SSW
BA570	CAEDF0000056446	1/2 - 1 Mile SSW
BA571	CAEDF0000009287	1/2 - 1 Mile SSW
BC572	CAEDF0000125510	1/2 - 1 Mile WNW
BC573	CAEDF0000078237	1/2 - 1 Mile WNW
AV574	CAEDF0000135870	1/2 - 1 Mile SSW
AV575	CAEDF0000062141	1/2 - 1 Mile SSW
AZ576	CAEDF0000023469	1/2 - 1 Mile SW
BD577	CAEDF0000127601	1/2 - 1 Mile NW
BA578	CAEDF0000065283	1/2 - 1 Mile SSW
AZ579	CAEDF0000136354	1/2 - 1 Mile SW
BD580	CAEDF0000121121	1/2 - 1 Mile NW
BA581	CAEDF0000105086	1/2 - 1 Mile SSW
BA582	CAEDF0000125593	1/2 - 1 Mile SSW
BA583	CAEDF0000099122	1/2 - 1 Mile SSW
BA584	CAEDF0000104981	1/2 - 1 Mile SSW
BA585	CAEDF0000139302	1/2 - 1 Mile SSW
BA586	CAEDF0000112338	1/2 - 1 Mile SSW
AV587	CAEDF0000108278	1/2 - 1 Mile SSW
AV588	CAEDF0000080102	1/2 - 1 Mile SSW
AV589	CAEDF0000126618	1/2 - 1 Mile SSW
AV590	CAEDF0000073319	1/2 - 1 Mile SSW
AV591	CAEDF0000062101	1/2 - 1 Mile SSW
AZ592	CAEDF0000096538	1/2 - 1 Mile SW
AV593	CAEDF0000014703	1/2 - 1 Mile SSW
BA594	CAEDF0000097298	1/2 - 1 Mile SSW
AV595	CAEDF0000128388	1/2 - 1 Mile SSW
AV596	CAEDF0000074852	1/2 - 1 Mile SSW
AZ598	CAEDF0000013464	1/2 - 1 Mile SW
AZ599	CAEDF0000086278	1/2 - 1 Mile SW
AZ600	CAEDF0000100430	1/2 - 1 Mile SW
BD601	CAEDF0000054892	1/2 - 1 Mile NW
BD602	CAEDF0000016820	1/2 - 1 Mile NW
BA603	CAEDF0000111563	1/2 - 1 Mile SSW
BA604	CAEDF0000012162	1/2 - 1 Mile SSW
AV605	CAEDF0000105802	1/2 - 1 Mile SSW
AY606	CADDW0000013191	1/2 - 1 Mile ESE

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
AV607	CAEDF0000070596	1/2 - 1 Mile SSW
AV608	CAEDF0000043802	1/2 - 1 Mile SSW
BA609	CAEDF0000101608	1/2 - 1 Mile SSW
AZ610	CAEDF0000082240	1/2 - 1 Mile SW
AV611	CAEDF0000108673	1/2 - 1 Mile SSW
AV612	CAEDF0000089855	1/2 - 1 Mile SSW
BA613	CAEDF0000065958	1/2 - 1 Mile SSW
BA614	CAEDF0000083054	1/2 - 1 Mile SSW
BA615	CAEDF0000059147	1/2 - 1 Mile SSW
BD616	CAEDF0000055296	1/2 - 1 Mile NW
BD617	CAEDF0000138870	1/2 - 1 Mile NW
BD618	CAEDF0000118307	1/2 - 1 Mile NW
BD619	CAEDF0000076497	1/2 - 1 Mile NW
BA620	CAEDF0000045392	1/2 - 1 Mile SSW
BA621	CAEDF0000059290	1/2 - 1 Mile SSW
BA622	CAEDF0000121272	1/2 - 1 Mile SSW
BA623	CAEDF0000044433	1/2 - 1 Mile SSW
BA624	CAEDF0000007762	1/2 - 1 Mile SSW
BA625	CAEDF0000033868	1/2 - 1 Mile SSW
BA626	CAEDF0000036820	1/2 - 1 Mile SSW
BE627	CAEDF0000085335	1/2 - 1 Mile SSW
BE628	CAEDF0000065538	1/2 - 1 Mile SSW
BF629	CAEDF0000072703	1/2 - 1 Mile NNW
BG630	CADPR0000004676	1/2 - 1 Mile East
BF631	CAEDF0000076421	1/2 - 1 Mile NNW
BA632	CAEDF0000070135	1/2 - 1 Mile SSW
BA633	CAEDF0000045333	1/2 - 1 Mile SSW
BA634	CAEDF0000114625	1/2 - 1 Mile SSW
BA635	CAEDF0000070332	1/2 - 1 Mile SSW
BA636	CAEDF0000114279	1/2 - 1 Mile SSW
BD637	CAEDF0000051002	1/2 - 1 Mile NW
BD638	CAEDF0000021836	1/2 - 1 Mile NW
639	CADWR0000005488	1/2 - 1 Mile SE
BE640	CAEDF0000101269	1/2 - 1 Mile SSW
BA641	CAEDF0000101840	1/2 - 1 Mile SSW
BA642	CAEDF0000081668	1/2 - 1 Mile SSW
BE643	CAEDF0000074308	1/2 - 1 Mile SSW
BE644	CAEDF0000066247	1/2 - 1 Mile SSW
BE645	CAEDF0000060999	1/2 - 1 Mile SSW
BE646	CAEDF0000009767	1/2 - 1 Mile SSW
BA647	CAEDF0000107553	1/2 - 1 Mile SSW
BA648	CAEDF0000069986	1/2 - 1 Mile SSW
BA649	CAEDF0000060139	1/2 - 1 Mile SSW
BH650	221	1/2 - 1 Mile ENE
BH651	23079	1/2 - 1 Mile ENE
BI652	CAEDF0000066595	1/2 - 1 Mile ENE
BD653	CAEDF0000033606	1/2 - 1 Mile NW
AZ654	CAEDF0000120158	1/2 - 1 Mile SW
BE655	CAEDF0000045564	1/2 - 1 Mile SSW
BE656	CAEDF0000024114	1/2 - 1 Mile SSW
AZ657	CAEDF0000102378	1/2 - 1 Mile SW
AZ658	CAEDF0000122172	1/2 - 1 Mile SW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
BA659	CAEDF0000140087	1/2 - 1 Mile SSW
BA660	CAEDF0000080128	1/2 - 1 Mile SSW
BA661	CAEDF0000063203	1/2 - 1 Mile SSW
BE662	CAEDF0000101818	1/2 - 1 Mile SSW
BE663	CAEDF0000110553	1/2 - 1 Mile SSW
BE664	CAEDF0000062469	1/2 - 1 Mile SSW
BE665	CAEDF0000010811	1/2 - 1 Mile SSW
BE666	CAEDF0000059052	1/2 - 1 Mile SSW
BA667	CAEDF0000078738	1/2 - 1 Mile SSW
BA668	CAEDF0000136168	1/2 - 1 Mile SSW
BA669	CAEDF0000033552	1/2 - 1 Mile SSW
BA670	CAEDF0000000168	1/2 - 1 Mile SSW
BF671	CAEDF0000013931	1/2 - 1 Mile NNW
BI672	CAEDF0000134899	1/2 - 1 Mile ENE
BI673	CAEDF0000032696	1/2 - 1 Mile ENE
BI674	CAEDF0000086433	1/2 - 1 Mile ENE
BI675	CAEDF0000006486	1/2 - 1 Mile ENE
BI676	CAEDF0000080520	1/2 - 1 Mile ENE
BD677	CAEDF0000135342	1/2 - 1 Mile NW
BF678	CAEDF0000134883	1/2 - 1 Mile NNW
BI680	CAEDF0000070181	1/2 - 1 Mile ENE
BA681	CAEDF0000132798	1/2 - 1 Mile SSW
BA682	CAEDF0000072841	1/2 - 1 Mile SSW
BA683	CAEDF0000052261	1/2 - 1 Mile SSW
BF684	CAEDF0000099741	1/2 - 1 Mile NNW
BI685	CAEDF0000109276	1/2 - 1 Mile ENE
BI686	CAEDF0000035804	1/2 - 1 Mile ENE
BE687	CAEDF0000123744	1/2 - 1 Mile SSW
BE688	CAEDF0000001350	1/2 - 1 Mile SSW
BH689	CADDW0000017975	1/2 - 1 Mile ENE
BG690	CAEDF0000134936	1/2 - 1 Mile East
BG691	CAEDF0000137056	1/2 - 1 Mile East
BA692	CAEDF0000124934	1/2 - 1 Mile SSW
BA693	CAEDF0000094934	1/2 - 1 Mile SSW
BF694	CAEDF0000022909	1/2 - 1 Mile NNW
BF695	CAEDF0000102174	1/2 - 1 Mile NNW
BI696	CAEDF0000075845	1/2 - 1 Mile ENE
BK697	CAEDF0000139258	1/2 - 1 Mile North
BA698	CAEDF0000091652	1/2 - 1 Mile SSW
BA699	CAEDF0000023363	1/2 - 1 Mile SSW
BA700	CAEDF0000052721	1/2 - 1 Mile SSW
BA701	CAEDF0000142788	1/2 - 1 Mile SSW
BG702	CAEDF0000082583	1/2 - 1 Mile East
BG703	CAEDF0000031886	1/2 - 1 Mile East
BG704	CAEDF0000008296	1/2 - 1 Mile East
BA705	CAEDF0000122971	1/2 - 1 Mile SSW
BA706	CAEDF0000124579	1/2 - 1 Mile SSW
BA707	CAEDF0000121239	1/2 - 1 Mile SSW
BI708	CAEDF0000106881	1/2 - 1 Mile ENE
BF709	CAEDF0000050868	1/2 - 1 Mile NNW
BA710	CAEDF0000121771	1/2 - 1 Mile SSW
BA711	CAEDF0000045586	1/2 - 1 Mile SSW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
BE712	CAEDF0000064379	1/2 - 1 Mile SSW
BI713	CAEDF0000131174	1/2 - 1 Mile ENE
BG714	CAEDF0000049688	1/2 - 1 Mile East
715	CAEDF0000103529	1/2 - 1 Mile SSW
BI716	CAEDF0000051807	1/2 - 1 Mile ENE
BI717	CAEDF0000123202	1/2 - 1 Mile ENE
BG718	CAEDF0000094476	1/2 - 1 Mile East
BI719	CAEDF0000106131	1/2 - 1 Mile ENE
BI720	CAEDF0000094348	1/2 - 1 Mile ENE
BI721	CAEDF0000140549	1/2 - 1 Mile ENE
BI722	CAEDF0000061172	1/2 - 1 Mile ENE
BI723	CAEDF0000035248	1/2 - 1 Mile ENE
BI724	CAEDF0000039958	1/2 - 1 Mile ENE
BI725	CAEDF0000119233	1/2 - 1 Mile ENE
BI726	CAEDF0000015310	1/2 - 1 Mile ENE
BE727	CAEDF0000065943	1/2 - 1 Mile SSW
BI728	CAEDF0000014592	1/2 - 1 Mile ENE
BI729	CAEDF0000121752	1/2 - 1 Mile ENE
BI730	CAEDF0000096015	1/2 - 1 Mile ENE
BI731	CAEDF0000061029	1/2 - 1 Mile ENE
BI732	CAEDF0000008889	1/2 - 1 Mile ENE
BI733	CAEDF0000072702	1/2 - 1 Mile ENE
BI734	CAEDF0000034338	1/2 - 1 Mile ENE
735	CADPR0000000347	1/2 - 1 Mile ESE
BE736	CAEDF0000076276	1/2 - 1 Mile SSW
BI737	CAEDF0000086455	1/2 - 1 Mile ENE
BI738	CAEDF0000056090	1/2 - 1 Mile ENE
BI739	CAEDF0000128134	1/2 - 1 Mile ENE
BI740	CAEDF0000083945	1/2 - 1 Mile ENE
BI741	CAEDF0000128970	1/2 - 1 Mile ENE
BI742	CAEDF0000128481	1/2 - 1 Mile ENE
BI743	CAEDF0000044896	1/2 - 1 Mile ENE
BL744	CAEDF0000123155	1/2 - 1 Mile South
BL745	CAEDF0000007260	1/2 - 1 Mile South
BL746	CAEDF0000043639	1/2 - 1 Mile South
747	CADWR0000037605	1/2 - 1 Mile East
BI748	CAEDF0000105512	1/2 - 1 Mile ENE
749	CADWR9000038023	1/2 - 1 Mile NNE
BE750	CAEDF0000142273	1/2 - 1 Mile SSW
BI751	CAEDF0000118239	1/2 - 1 Mile ENE
BI752	CAEDF0000100669	1/2 - 1 Mile ENE
BM753	CAEDF0000087974	1/2 - 1 Mile SSW
BM754	CAEDF0000011978	1/2 - 1 Mile SSW
BE755	CAEDF0000123294	1/2 - 1 Mile SSW
BI757	CAEDF0000024434	1/2 - 1 Mile ENE
BI758	CAEDF0000008665	1/2 - 1 Mile ENE
BL759	CAEDF0000018501	1/2 - 1 Mile South
BI760	CAEDF0000032996	1/2 - 1 Mile ENE
BL761	CAEDF0000097481	1/2 - 1 Mile South
BO762	CADWR0000033003	1/2 - 1 Mile WSW
BO763	CADWR0000005448	1/2 - 1 Mile WSW
BO764	CADWR0000008891	1/2 - 1 Mile WSW

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
BH765	CADDW0000006375	1/2 - 1 Mile ENE
BN766	CAEDF0000134772	1/2 - 1 Mile WSW
BN767	CAEDF0000087478	1/2 - 1 Mile WSW
BH768	CADDW0000013477	1/2 - 1 Mile ENE
BE769	CAEDF0000128451	1/2 - 1 Mile SSW
BI770	CAEDF0000069436	1/2 - 1 Mile ENE
BN771	CAEDF0000032621	1/2 - 1 Mile WSW
BL772	CAEDF0000022074	1/2 - 1 Mile South
BL773	CAEDF0000063336	1/2 - 1 Mile South
BL774	CAEDF0000081360	1/2 - 1 Mile South
BE775	CAEDF0000112241	1/2 - 1 Mile SSW
BI776	CAEDF0000070239	1/2 - 1 Mile ENE
BN777	CAEDF0000029818	1/2 - 1 Mile WSW
BN778	CAEDF0000105890	1/2 - 1 Mile WSW
BP779	CAEDF0000090017	1/2 - 1 Mile NNE
BL780	CAEDF0000124497	1/2 - 1 Mile South
BN781	CAEDF0000036183	1/2 - 1 Mile WSW
BN782	CAEDF0000057078	1/2 - 1 Mile WSW
BQ783	CADWR0000031591	1/2 - 1 Mile ENE
BQ784	CADWR0000021460	1/2 - 1 Mile ENE
BQ785	CADWR0000036578	1/2 - 1 Mile ENE
BQ786	CADWR0000002600	1/2 - 1 Mile ENE
BQ787	CADWR0000027114	1/2 - 1 Mile ENE
BQ788	CADWR0000037918	1/2 - 1 Mile ENE
BQ789	CADWR0000005465	1/2 - 1 Mile ENE
BQ790	CADWR0000011490	1/2 - 1 Mile ENE
BQ791	CADWR0000010419	1/2 - 1 Mile ENE
BQ792	CADWR0000009197	1/2 - 1 Mile ENE
BP793	CAEDF0000137346	1/2 - 1 Mile NNE
BI794	CAEDF0000092253	1/2 - 1 Mile ENE
BM795	CAEDF0000073794	1/2 - 1 Mile SSW
BP796	CAEDF0000089607	1/2 - 1 Mile NNE
798	229	1/2 - 1 Mile East
BP799	CAEDF0000008621	1/2 - 1 Mile NNE
BN800	CAEDF0000055035	1/2 - 1 Mile WSW
BN801	CAEDF0000006698	1/2 - 1 Mile WSW
BN802	CAEDF0000051310	1/2 - 1 Mile WSW
BN803	CAEDF0000081804	1/2 - 1 Mile WSW
BN804	CAEDF0000003892	1/2 - 1 Mile WSW
BN805	CAEDF0000088056	1/2 - 1 Mile WSW
BN806	CAEDF0000069450	1/2 - 1 Mile WSW
BN807	CAEDF0000066851	1/2 - 1 Mile WSW
BP808	CAEDF0000096274	1/2 - 1 Mile NNE
BP809	CAEDF0000070829	1/2 - 1 Mile NNE
BP810	CAEDF0000127292	1/2 - 1 Mile NNE
BK811	CAEDF0000003884	1/2 - 1 Mile North
812	CAEDF0000080660	1/2 - 1 Mile WSW
BP813	CAEDF0000006485	1/2 - 1 Mile NNE
BP814	CAEDF0000137752	1/2 - 1 Mile NNE
BR815	CAEDF0000051049	1/2 - 1 Mile ESE
BS816	CAEDF0000055972	1/2 - 1 Mile ENE
BS817	CAEDF0000039707	1/2 - 1 Mile ENE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
BS818	CAEDF0000033218	1/2 - 1 Mile ENE
BR819	CAEDF0000125639	1/2 - 1 Mile ESE

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	CAOG14000215257	1/4 - 1/2 Mile NNW
2	CAOG14000215259	1/2 - 1 Mile NNW
A3	CAOG14000215264	1/2 - 1 Mile West
A4	CAOG14000215265	1/2 - 1 Mile West
5	CAOG14000215276	1/2 - 1 Mile NNE
6	CAOG14000215272	1/2 - 1 Mile ESE
7	CAOG14000215258	1/2 - 1 Mile NNE
8	CAOG14000215266	1/2 - 1 Mile WNW
B9	CAOG14000215273	1/2 - 1 Mile NNE
B10	CAOG14000215275	1/2 - 1 Mile NNE
B11	CAOG14000215274	1/2 - 1 Mile NNE
12	CAOG14000215260	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 6607856.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	New Life Mens Facility	CLIENT:	Condor Earth Technologies, Inc
ADDRESS:	429 S. San Joaquin Street Stockton CA 95203	CONTACT:	Rebecca Selvage
LAT/LONG:	37.948629 / 121.286367	INQUIRY #:	6607856.2s
		DATE:	August 05, 2021 1:36 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
A1 **SSW** **0 - 1/8 Mile** **Higher**	**CA WELLS**	**CAEDF0000076911**

Well ID:	SL205122996-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-20		

	Database	EDR ID Number
B2 **NW** **0 - 1/8 Mile** **Lower**	**CA WELLS**	**CAEDF0000087312**

Well ID:	T0607700715-MW3A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW3A		

	Database	EDR ID Number
C3 **SW** **1/8 - 1/4 Mile** **Higher**	**CA WELLS**	**CAEDF0000082278**

Well ID:	SL205122996-MW-28	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-28
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-28&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-28		

	Database	EDR ID Number
B4 **WNW** **1/8 - 1/4 Mile** **Lower**	**CA WELLS**	**CAEDF0000078563**

Well ID:	T0607700715-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A5
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000067917**

Well ID:	SL205122996-MW-30	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-30
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-30&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-30		

B6
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000107774**

Well ID:	T0607700715-MW2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW2A		

B7
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000098734**

Well ID:	T0607700715-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW4		

B8
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000076740**

Well ID:	T0607700715-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW5		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B9
NW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000121780**

Well ID:	T0607700715-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW8		

D10
NE
1/8 - 1/4 Mile
Higher

CA WELLS **218**

Seq:	218	Prim sta c:	01N/06E-11K01 M
Frds no:	3910001025	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 30-01 - STANDBY	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	375700.0	Longitude:	1211700.0
Precision:	8	Status:	SR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

D11
NE
1/8 - 1/4 Mile
Higher

CA WELLS **217**

Seq:	217	Prim sta c:	01N/06E-11E02 M
Frds no:	3910012015	County:	39
District:	10	User id:	PTA
System no:	3910012	Water type:	G
Source nam:	STOCKTON POLICE - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	375700.0	Longitude:	1211700.0
Precision:	8	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910012	System nam:	Stockton, City Of
Hqname:	Not Reported	Address:	2500 NAVY DRIVE
City:	STOCKTON	State:	Not Reported

Zip:	95206	Zip ext:	Not Reported
Pop serv:	96000	Connection:	28033
Area serve:	STOCKTON		

D12
NE
1/8 - 1/4 Mile
Higher

CA WELLS 211

Seq:	211	Prim sta c:	01N/06E-02Q01 M
Frds no:	3910001046	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 53-01 - STANDBY	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	375700.0	Longitude:	1211700.0
Precision:	8	Status:	SR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

D13
NE
1/8 - 1/4 Mile
Higher

CA WELLS 23206

Seq:	23206	Prim sta c:	J39/012-POLITRT
Frds no:	3910012056	County:	39
District:	10	User id:	PTA
System no:	3910012	Water type:	G
Source nam:	POLICE WELL - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	375700.0	Longitude:	1211700.0
Precision:	4	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910012	System nam:	Stockton, City Of
Hqname:	Not Reported	Address:	2500 NAVY DRIVE
City:	STOCKTON	State:	Not Reported
Zip:	95206	Zip ext:	Not Reported
Pop serv:	96000	Connection:	28033
Area serve:	STOCKTON		

D14
NE
1/8 - 1/4 Mile
Higher

CA WELLS 23118

Seq:	23118	Prim sta c:	J39/001-53-01TR
Frds no:	3910001109	County:	39

District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 53-01 - TREATED	Station ty:	WELL/AMBNT
Latitude:	375700.0	Longitude:	1211700.0
Precision:	4	Status:	AT
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

D15
NE
1/8 - 1/4 Mile
Higher

CA WELLS 23099

Seq:	23099	Prim sta c:	J39/001-30-01TR
Frds no:	3910001090	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 30-01 - TREATED	Station ty:	WELL/AMBNT
Latitude:	375700.0	Longitude:	1211700.0
Precision:	4	Status:	AT
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

B16
WNW
1/8 - 1/4 Mile
Lower

CA WELLS CAEDF0000013613

Well ID:	T0607700715-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A17
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000010040**

Well ID:	SL205122996-MW-29	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-29
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-29&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-29		

A18
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000069433**

Well ID:	SL205122996-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-21		

B19
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000043496**

Well ID:	T0607700715-MW1A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW1A		

B20
NW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000105389**

Well ID:	T0607700715-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B21
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000042556**

Well ID:	T0607700715-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700715&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700715&assigned_name=MW9		

C22
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000062173**

Well ID:	SL205122996-MW-33	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-33
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-33&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-33		

E23
NNE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000009851**

Well ID:	T0607700218-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-9		

C24
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000086265**

Well ID:	SL205122996-MW-25	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-25		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E25
North
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000014019**

Well ID:	T0607700218-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-4		

D26
ENE
1/8 - 1/4 Mile
Higher

CA WELLS **CADDW0000021686**

Well ID:	3910001-025	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 30-01 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-025&store_num=		
GeoTracker Data:	Not Reported		

E27
NNE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000136021**

Well ID:	T0607700218-MW-2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-2A		

C28
WSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000042559**

Well ID:	SL205122996-MW-27	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-27
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-27&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-27		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D29
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000124287**

Well ID:	T0607700605-MW-3R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-3R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-3R		

D30
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000143503**

Well ID:	T0607700605-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-3		

D31
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000037716**

Well ID:	T0607700605-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-2		

D32
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000090417**

Well ID:	T0607700605-MW-2R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-2R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-2R		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E33
NNE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000042286**

Well ID:	T0607700218-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-2		

D34
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000070000**

Well ID:	T0607700605-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-6		

F35
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000107011**

Well ID:	SL205122996-MW-26R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-26R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-26R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-26R		

D36
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000143211**

Well ID:	T0607700605-MW-1R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-1R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-1R		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D37
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000122050**

Well ID:	T0607700605-EW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=EW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=EW-1		

D38
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000112058**

Well ID:	T0607700605-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-1		

E39
NNE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000059032**

Well ID:	T0607700218-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-6		

D40
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000093810**

Well ID:	T0607700605-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G41
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000001803**

Well ID:	T0607700605-MW-7S	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7S
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-7S&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-7S		

F42
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000135759**

Well ID:	SL205122996-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-24		

E43
North
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000056606**

Well ID:	T0607700218-MW-3A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-3A		

G44
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000074184**

Well ID:	T0607700605-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H45
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000072227**

Well ID:	T0607700391-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-8		

E46
NNE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000059975**

Well ID:	T0607700218-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-7		

G47
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000078558**

Well ID:	T0607700605-MW-8D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-8D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-8D		

F48
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000072828**

Well ID:	SL205122996-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-18		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G49
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000021187**

Well ID:	T0607700605-MW-8S	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8S
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-8S&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-8S		

F50
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000077304**

Well ID:	SL205122996-MW-19R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-19R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-19R		

F51
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000006856**

Well ID:	SL205122996-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-22		

H52
WNW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000112547**

Well ID:	T0607700391-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F53
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000113249**

Well ID:	SL205122996-MW-23R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-23R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-23R		

F54
SW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000129440**

Well ID:	SL205122996-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-7		

F55
WSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000069421**

Well ID:	SL205122996-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-4		

G56
NE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000013226**

Well ID:	T0607700605-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F57
WSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000101376**

Well ID:	SL205122996-MW-6R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-6R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-6R		

F58
WSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000092870**

Well ID:	SL205122996-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-5		

I59
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000103974**

Well ID:	T0607700218-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-5		

J60
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CADWR0000032862**

Well ID:	01N06E11E002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E11E002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E11E002M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H61
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000036945**

Well ID:	T0607700391-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-7		

H62
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000078877**

Well ID:	T0607700391-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-13		

F63
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000013892**

Well ID:	SL205122996-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-8		

K64
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000003127**

Well ID:	SL205122996-MW-9R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-9R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-9R		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

I65
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000089947**

Well ID:	T0607700218-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700218&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700218&assigned_name=MW-8		

G66
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000132634**

Well ID:	T0607700605-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700605&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700605&assigned_name=MW-11		

J67
NW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000186245**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E11E002M	Type:	Well
Description:	Not Reported	HUC:	18040004
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

K68
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000104253**

Well ID:	SL205122996-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K69
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000127994**

Well ID:	SL205122996-MW-32	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-32
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-32&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-32		

H70
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000140085**

Well ID:	T0607700391-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-2		

H71
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000116271**

Well ID:	T0607700391-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-14		

K72
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000052904**

Well ID:	SL205122996-MW-31	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-31
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-31&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-31		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H73
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000109324**

Well ID:	T0607700391-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-10		

H74
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000095306**

Well ID:	T0607700391-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-15		

H75
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000127364**

Well ID:	T0607700391-MW-15D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-15D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-15D		

H76
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000053825**

Well ID:	T0607700391-MW-9S	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9S
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-9S&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-9S		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H77
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000058325**

Well ID:	T0607700391-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-9		

K78
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000113857**

Well ID:	SL205122996-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL205122996&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL205122996&assigned_name=MW-13		

H79
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000103907**

Well ID:	T0607700391-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-1		

H80
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000023008**

Well ID:	T0607700391-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J81
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000037403**

Well ID:	T0607700391-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-17		

H82
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000114722**

Well ID:	T0607700391-MW-18D2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18D2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-18D2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-18D2		

J83
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000023538**

Well ID:	T0607700391-MW-9A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-9A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-9A		

H84
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000078357**

Well ID:	T0607700391-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J85
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000039571**

Well ID:	T0607700391-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-3		

J86
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000006401**

Well ID:	T0607700391-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-12		

J87
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000106734**

Well ID:	T0607700391-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-4		

J88
WNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000095719**

Well ID:	T0607700391-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700391&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700391&assigned_name=MW-16		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L89
ESE
1/4 - 1/2 Mile
Higher | **FED USGS** | **USGS40000186228**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E11K001M	Type:	Well
Description:	Not Reported	HUC:	18040004
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	516
Well Depth Units:	ft	Well Hole Depth:	518
Well Hole Depth Units:	ft		

J90
NW
1/4 - 1/2 Mile
Lower | **CA WELLS** | **CADWR9000038004**

State Well #:	01N06E11E002M	Station ID:	26502
Well Name:	Not Reported	Basin Name:	Eastern San Joaquin
Well Use:	Unknown	Well Type:	Unknown
Well Depth:	215	Well Completion Rpt #:	Not Reported

M91
NNW
1/4 - 1/2 Mile
Lower | **CA WELLS** | **CAEDF0000019860**

Well ID:	T0607700478-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700478&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700478&assigned_name=MW-1		

92
SSE
1/4 - 1/2 Mile
Higher | **CA WELLS** | **CADWR0000023591**

Well ID:	01N06E11K001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E11K001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E11K001M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M93
North
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000122222**

Well ID:	T0607700478-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700478&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700478&assigned_name=MW-3		

M94
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000113404**

Well ID:	T0607700478-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700478&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700478&assigned_name=MW-2		

L95
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000032171**

Well ID:	T0607700303-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-7		

N96
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000015392**

Well ID:	T0607700303-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N97
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000008144**

Well ID:	T0607700303-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-4		

L98
ESE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000105594**

Well ID:	T0607700303-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-6		

N99
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000048260**

Well ID:	T0607700303-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-2		

N100
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000054135**

Well ID:	T0607700303-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N101
SE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000067734**

Well ID:	T0607700303-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700303&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700303&assigned_name=MW-5		

O102
SSW
1/4 - 1/2 Mile
Higher

CA WELLS **CADDW0000003016**

Well ID:	3910001-030	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 37-01 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-030&store_num=		
GeoTracker Data:	Not Reported		

P103
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000134379**

Well ID:	T0607700689-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700689&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700689&assigned_name=MW-2		

O104
SSW
1/4 - 1/2 Mile
Higher

CA WELLS **219**

Seq:	219	Prim sta c:	01N/06E-11P03 M
Frds no:	3910001030	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 37-01 - STANDBY	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	375634.0	Longitude:	1211715.0
Precision:	3	Status:	SR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

O105
SSW
1/4 - 1/2 Mile
Higher

CA WELLS 23104

Seq:	23104	Prim sta c:	J39/001-37-01TR
Frds no:	3910001095	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 37-01 - TREATED	Station ty:	WELL/AMBNT
Latitude:	375634.0	Longitude:	1211715.0
Precision:	4	Status:	AT
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

Q106
WSW
1/4 - 1/2 Mile
Lower

CA WELLS CAEDF0000069768

Well ID:	T0607726897-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607726897&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607726897&assigned_name=MW9		

P107
NNW
1/4 - 1/2 Mile
Lower

CA WELLS CAEDF0000120623

Well ID:	T0607700689-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700689&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700689&assigned_name=MW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q108
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000060451**

Well ID:	T0607726897-MW11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607726897&assigned_name=MW11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607726897&assigned_name=MW11		

P109
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000084919**

Well ID:	T0607700689-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700689&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700689&assigned_name=MW-1		

P110
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000032585**

Well ID:	T0607700689-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700689&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700689&assigned_name=MW-4		

Q111
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000094624**

Well ID:	T0607726897-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607726897&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607726897&assigned_name=MW10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R112
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000121099**

Well ID:	T0607700462-MW-11M	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11M
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-11M&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-11M		

R113
NNW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000022877**

Well ID:	T0607700462-MW-11D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-11D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-11D		

R114
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000099669**

Well ID:	T0607700462-MW-9D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-9D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-9D		

R115
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000014622**

Well ID:	T0607700462-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R116
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000084659**

Well ID:	T0607700462-MW-9M	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9M
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-9M&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-9M		

S117
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000082174**

Well ID:	T0607700462-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-3		

Q118
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000096884**

Well ID:	T0607700185-VW3	Well Type:	MONITORING
Source:	EDF	Other Name:	VW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW3		

R119
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000135715**

Well ID:	T0607700462-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q120
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000077567**

Well ID:	T0607700185-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW1		

Q121
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000131650**

Well ID:	T0607700185-VW2	Well Type:	MONITORING
Source:	EDF	Other Name:	VW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW2		

Q122
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000112936**

Well ID:	T0607700185-VW5	Well Type:	MONITORING
Source:	EDF	Other Name:	VW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW5		

Q123
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000057449**

Well ID:	T0607700185-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q124
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000116934**

Well ID:	T0607700185-MW4B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW4B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW4B		

Q125
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000070072**

Well ID:	T0607700185-MW4A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW4A		

Q126
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000047677**

Well ID:	T0607700185-VW1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW1		

Q127
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000090990**

Well ID:	T0607700185-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S128
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000090033**

Well ID:	T0607700462-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-4		

S129
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000072030**

Well ID:	T0607700462-MW-8D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-8D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-8D		

S130
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000041742**

Well ID:	T0607700462-MW-8M	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8M
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-8M&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-8M		

Q131
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000021952**

Well ID:	T0607700185-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q132
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000112111**

Well ID:	T0607700185-VW4	Well Type:	MONITORING
Source:	EDF	Other Name:	VW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW4		

T133
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000080277**

Well ID:	T0607700430-VM-5	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-5		

R134
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000016469**

Well ID:	T0607700462-MW-10D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-10D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-10D		

R135
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000093846**

Well ID:	T0607700462-MW-10M	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10M
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-10M&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-10M		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q136
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000020067**

Well ID:	T0607700185-VW6	Well Type:	MONITORING
Source:	EDF	Other Name:	VW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=VW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=VW6		

S137
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000049496**

Well ID:	T0607700462-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-1		

S138
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000126026**

Well ID:	T0607700462-MW-12D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-12D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-12D		

R139
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000117056**

Well ID:	T0607700462-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T140
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000050003**

Well ID:	T0607700430-VM-7	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-7		

Q141
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000121640**

Well ID:	T0607700185-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700185&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700185&assigned_name=MW8		

T142
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000019276**

Well ID:	T0607700430-VM-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-1		

T143
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000008571**

Well ID:	T0607700430-VM-9	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T144
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000077524**

Well ID:	T0607700430-SW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	SW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=SW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=SW-1		

T145
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000074934**

Well ID:	T0607700430-VM-2	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-2		

S146
NW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000044422**

Well ID:	T0607700462-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-2		

T147
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000052137**

Well ID:	T0607700430-VM-3	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T148
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000018440**

Well ID:	T0607700430-VM-4	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-4		

R149
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117252**

Well ID:	T0607700462-MW-13M	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13M
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-13M&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-13M		

R150
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117776**

Well ID:	T0607700462-MW-13D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700462&assigned_name=MW-13D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700462&assigned_name=MW-13D		

151
NNE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000006709**

Well ID:	01N06E02Q001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E02Q001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E02Q001M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T152
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000101272**

Well ID:	T0607700430-VM-6	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-6		

T153
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000121952**

Well ID:	T0607700430-VM-8	Well Type:	MONITORING
Source:	EDF	Other Name:	VM-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700430&assigned_name=VM-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700430&assigned_name=VM-8		

U154
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000001628**

Well ID:	T0607715874-MW4B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607715874&assigned_name=MW4B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607715874&assigned_name=MW4B		

V155
South
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000031560**

Well ID:	01N06E11P003M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E11P003M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E11P003M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W156
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012882**

Well ID:	T0607700732-MW-1D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700732&assigned_name=MW-1D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700732&assigned_name=MW-1D		

W157
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000110617**

Well ID:	T0607700732-MW-6D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700732&assigned_name=MW-6D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700732&assigned_name=MW-6D		

W158
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000014212**

Well ID:	T0607700732-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700732&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700732&assigned_name=MW-6		

U159
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000019257**

Well ID:	T0607715874-MW1A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607715874&assigned_name=MW1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607715874&assigned_name=MW1A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

U160
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000143678**

Well ID:	T0607715874-MW1B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607715874&assigned_name=MW1B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607715874&assigned_name=MW1B		

W161
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125156**

Well ID:	T0607700539-U-7	Well Type:	MONITORING
Source:	EDF	Other Name:	U-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-7		

U162
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138759**

Well ID:	T0607715874-MW2B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607715874&assigned_name=MW2B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607715874&assigned_name=MW2B		

X163
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000019453**

Well ID:	T0607799499-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W164
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000103605**

Well ID:	T0607700539-U-17	Well Type:	MONITORING
Source:	EDF	Other Name:	U-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-17		

W165
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000069123**

Well ID:	T0607700539-U-16	Well Type:	MONITORING
Source:	EDF	Other Name:	U-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-16		

V166
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000084044**

Well ID:	T0607700692-MW7A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW7A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW7A		

U167
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122508**

Well ID:	T0607715874-MW3B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607715874&assigned_name=MW3B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607715874&assigned_name=MW3B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X168
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000068070**

Well ID:	T0607799499-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW6		

X169
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123085**

Well ID:	T0607799499-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW7		

X170
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000044026**

Well ID:	T0607799499-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW1		

W171
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105410**

Well ID:	T0607700539-U-15	Well Type:	MONITORING
Source:	EDF	Other Name:	U-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-15		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W172
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045411**

Well ID:	T0607700539-U-6	Well Type:	MONITORING
Source:	EDF	Other Name:	U-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-6		

W173
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045143**

Well ID:	T0607700539-U-14	Well Type:	MONITORING
Source:	EDF	Other Name:	U-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-14		

W174
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000118076**

Well ID:	T0607700539-U-2	Well Type:	MONITORING
Source:	EDF	Other Name:	U-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-2		

W175
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000023376**

Well ID:	T0607700539-U-3	Well Type:	MONITORING
Source:	EDF	Other Name:	U-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W176
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000111080**

Well ID:	T0607700539-NP-1-111	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-1-111
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-1-111&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-1-111		

W177
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000137759**

Well ID:	T0607700539-NP-1-65	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-1-65
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-1-65&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-1-65		

W178
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000037104**

Well ID:	T0607700539-NP-1-22	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-1-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-1-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-1-22		

W179
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000072790**

Well ID:	T0607700539-UV-1	Well Type:	MONITORING
Source:	EDF	Other Name:	UV-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=UV-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=UV-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y180
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000082615**

Well ID:	T0607772370-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-6		

Y181
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000000716**

Well ID:	T0607772370-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-4		

Y182
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000120591**

Well ID:	T0607772370-MW-4D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-4D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-4D		

Y183
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000114489**

Well ID:	T0607772370-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X184
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000115042**

Well ID:	T0607799499-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW2		

Y185
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000009353**

Well ID:	T0607772370-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-1		

X186
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000136662**

Well ID:	T0607799499-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW3		

W187
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102673**

Well ID:	T0607700539-U-5	Well Type:	MONITORING
Source:	EDF	Other Name:	U-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W188
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000096184**

Well ID:	T0607700539-U-1	Well Type:	MONITORING
Source:	EDF	Other Name:	U-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-1		

Y189
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000016926**

Well ID:	T0607772370-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-5		

Y190
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000103395**

Well ID:	T0607772370-MW-3R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-3R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-3R		

Z191
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000079132**

Well ID:	T0607700539-U-26	Well Type:	MONITORING
Source:	EDF	Other Name:	U-26
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-26&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-26		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W192
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000123976**

Well ID:	T0607700539-U-8	Well Type:	MONITORING
Source:	EDF	Other Name:	U-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-8		

X193
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000037271**

Well ID:	T0607799499-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607799499&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607799499&assigned_name=MW5		

W194
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000010322**

Well ID:	T0607700539-U-4	Well Type:	MONITORING
Source:	EDF	Other Name:	U-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-4		

W195
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000121795**

Well ID:	T0607700539-U-18	Well Type:	MONITORING
Source:	EDF	Other Name:	U-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-18		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W196
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000095882**

Well ID:	T0607700539-U-19	Well Type:	MONITORING
Source:	EDF	Other Name:	U-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-19		

W197
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000034845**

Well ID:	T0607700539-NP-2-60	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-2-60
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-2-60&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-2-60		

W198
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000039428**

Well ID:	T0607700539-U-10	Well Type:	MONITORING
Source:	EDF	Other Name:	U-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-10		

W199
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128051**

Well ID:	T0607700539-NP-2-116	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-2-116
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-2-116&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-2-116		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W200
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000109005**

Well ID:	T0607700539-NP-2-22	Well Type:	MONITORING
Source:	EDF	Other Name:	NP-2-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=NP-2-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=NP-2-22		

V201
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000140633**

Well ID:	T0607700692-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW10		

V202
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000119993**

Well ID:	T0607700692-MW3B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW3B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW3B		

V203
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000085298**

Well ID:	T0607700692-MW3A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW3A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AA204
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000128528**

Well ID:	T0607700692-MW8A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW8A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW8A		

W205
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000102989**

Well ID:	T0607700539-U-9	Well Type:	MONITORING
Source:	EDF	Other Name:	U-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-9		

AA206
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097503**

Well ID:	T0607700692-MW4A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW4A		

V207
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000031305**

Well ID:	T0607700692-MW6A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW6A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y208
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000116424**

Well ID:	T0607772370-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607772370&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607772370&assigned_name=MW-7		

AA209
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000052736**

Well ID:	T0607700692-MW2B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW2B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW2B		

AA210
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000017580**

Well ID:	T0607700692-MW2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW2A		

W211
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000020903**

Well ID:	T0607700539-U-13	Well Type:	MONITORING
Source:	EDF	Other Name:	U-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-13		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

W212
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000052411**

Well ID:	T0607700539-U-12	Well Type:	MONITORING
Source:	EDF	Other Name:	U-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-12		

W213
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000107457**

Well ID:	T0607700539-U-11	Well Type:	MONITORING
Source:	EDF	Other Name:	U-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-11		

AA214
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134365**

Well ID:	T0607700692-MW5A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW5A		

AA215
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063767**

Well ID:	T0607700692-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW1		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
AA216 **South** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CAEDF0000045491**

Well ID:	T0607700157-MW5A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW5A		

	Database	EDR ID Number
W217 **North** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAEDF0000078607**

Well ID:	T0607700539-U-24	Well Type:	MONITORING
Source:	EDF	Other Name:	U-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-24		

	Database	EDR ID Number
W218 **North** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAEDF0000034789**

Well ID:	T0607700539-U-25	Well Type:	MONITORING
Source:	EDF	Other Name:	U-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-25		

	Database	EDR ID Number
AA219 **South** **1/2 - 1 Mile** **Lower**	**FRDS PWS**	**CA3900732**

Epa region:	09	State:	CA
Pwsid:	CA3900732	Pwsname:	V & P TRAILER COURT WATER SYSTEM
Cityserved:	Not Reported	Stateserved:	CA
Zipserved:	Not Reported	Fipscounty:	06077
Status:	Active	Retpopsrvd:	35
Pwssvcconn:	15	Psource longname:	Groundwater
Pwstype:	CWS	Owner:	Private
Contact:	C/O RICHARD L. MILLER	Contactorgname:	V & P TRAILER COURT WATER SYSTEM
Contactphone:	Not Reported	Contactaddress1:	196 TIFFANY CIR
Contactaddress2:	Not Reported	Contactcity:	RIPON

Contactstate:	CA	Contactzip:	95366
Pwsactivitycode:	A		
PWS ID:	CA3900732	PWS name:	V & P TRAILER PARK
Address:	Not Reported	Care of:	Not Reported
City:	STOCKTON	State:	CA
Zip:	95206	Owner:	V & P TRAILER PARK
Source code:	Ground water	Population:	35
PWS ID:	CA3900732	PWS type:	System Owner/Responsible Party
PWS name:	BEVERLY DELANO	PWS address:	Not Reported
PWS city:	STOCKTON	PWS state:	CA
PWS zip:	95206	PWS name:	V & P TRAILER COURT
PWS type code:	C	Retail population served:	35
Contact:	C/O RICHARD L. MILLER	Contact address:	196 TIFFANY CIR
Contact address:	RIPON	Contact city:	CA
Contact state:	95	Contact zip:	Not Reported
Contact telephone:	Not Reported		
PWS ID:	CA3900732	Activity status:	Active
Date system activated:	7706	Date system deactivated:	Not Reported
Retail population:	00000025	System name:	V & P TRAILER PARK
System address:	BEVERLY DELANO	System address:	3232 MUNFORD
System city:	STOCKTON	System state:	CA
System zip:	95204		
Population served:	Under 101 Persons	Treatment:	Untreated
Latitude:	375624	Longitude:	1211712
Violation id:	0200001	Orig code:	S
State:	CA	Violation Year:	2000
Contamination code:	5000	Contamination Name:	Lead and Copper Rule
Violation code:	51	Violation name:	Initial Tap Sampling for Pb and Cu
Rule code:	350	Rule name:	LCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	04/01/2000
Cmp edt:	Not Reported		
Violation id:	0200002	Orig code:	S
State:	CA	Violation Year:	2000
Contamination code:	5000	Contamination Name:	Lead and Copper Rule
Violation code:	51	Violation name:	Initial Tap Sampling for Pb and Cu
Rule code:	350	Rule name:	LCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	04/01/2000
Cmp edt:	Not Reported		
Violation id:	0400003	Orig code:	S
State:	CA	Violation Year:	2003
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	12/01/2003
Cmp edt:	12/31/2003		
Violation id:	0400004	Orig code:	S
State:	CA	Violation Year:	2004
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	24	Violation name:	Monitoring, Routine Minor (TCR)
Rule code:	110	Rule name:	TCR

Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	01/01/2004
Cmp edt:	01/31/2004		

Violation id:	0500005	Orig code:	S
State:	CA	Violation Year:	2005
Contamination code:	7000	Contamination Name:	Consumer Confidence Rule
Violation code:	71	Violation name:	CCR Complete Failure to Report
Rule code:	420	Rule name:	CCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	07/01/2005
Cmp edt:	Not Reported		

Violation id:	0600006	Orig code:	S
State:	CA	Violation Year:	2006
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	03/01/2006
Cmp edt:	03/31/2006		

Violation id:	0600007	Orig code:	S
State:	CA	Violation Year:	2006
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	04/01/2006
Cmp edt:	04/30/2006		

Violation id:	0900009	Orig code:	S
State:	CA	Violation Year:	2009
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	01/01/2009
Cmp edt:	01/31/2009		

Violation id:	0900010	Orig code:	S
State:	CA	Violation Year:	2009
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	03/01/2009
Cmp edt:	03/31/2009		

Violation id:	1100011	Orig code:	S
State:	CA	Violation Year:	2011
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)
Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	01/01/2011
Cmp edt:	01/31/2011		

Violation id:	1100012	Orig code:	S
State:	CA	Violation Year:	2011
Contamination code:	3100	Contamination Name:	Coliform (TCR)
Violation code:	22	Violation name:	MCL, Monthly (TCR)

Rule code:	110	Rule name:	TCR
Violation measur:	Not Reported	Unit of measure:	Not Reported
State mcl:	Not Reported	Cmp bdt:	02/01/2011
Cmp edt:	02/28/2011		

Violation id:	95V0001	Orig code:	F
State:	CA	Violation Year:	1993
Contamination code:	5000	Contamination Name:	Lead and Copper Rule
Violation code:	51	Violation name:	Initial Tap Sampling for Pb and Cu
Rule code:	350	Rule name:	LCR
Violation measur:	0	Unit of measure:	Not Reported
State mcl:	0	Cmp bdt:	07/01/1993
Cmp edt:	04/04/2000		

Violation ID:	0200001	Orig Code:	S
Enforcemnt FY:	2002	Enforcement Action:	01/11/2002
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0200002	Orig Code:	S
Enforcemnt FY:	2002	Enforcement Action:	01/11/2002
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0200002	Orig Code:	S
Enforcemnt FY:	2002	Enforcement Action:	03/31/2002
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0400003	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0400003	Orig Code:	S
Enforcemnt FY:	2004	Enforcement Action:	12/01/2003
Enforcement Detail:	St Public Notif received	Enforcement Category:	Informal

Violation ID:	0400004	Orig Code:	S
Enforcemnt FY:	2004	Enforcement Action:	01/01/2004
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal

Violation ID:	0500005	Orig Code:	S
Enforcemnt FY:	2006	Enforcement Action:	07/01/2006
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0600006	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0600006	Orig Code:	S
Enforcemnt FY:	2006	Enforcement Action:	03/01/2006
Enforcement Detail:	St Public Notif received	Enforcement Category:	Informal

Violation ID:	0600007	Orig Code:	S
Enforcemnt FY:	2006	Enforcement Action:	04/01/2006
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal

Violation ID:	0600007	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0900009	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving

Violation ID:	0900009	Orig Code:	S
Enforcemnt FY:	2009	Enforcement Action:	02/10/2009
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal
Violation ID:	0900010	Orig Code:	S
Enforcemnt FY:	2009	Enforcement Action:	04/10/2009
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal
Violation ID:	0900010	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving
Violation ID:	1100011	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving
Violation ID:	1100011	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	01/01/2011
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal
Violation ID:	1100012	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	02/01/2011
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving
Violation ID:	1100012	Orig Code:	S
Enforcemnt FY:	2011	Enforcement Action:	02/01/2011
Enforcement Detail:	St Public Notif requested	Enforcement Category:	Informal
Violation ID:	95V0001	Orig Code:	F
Enforcemnt FY:	2000	Enforcement Action:	04/04/2000
Enforcement Detail:	St Compliance achieved	Enforcement Category:	Resolving
PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0200002
Contaminant:	LEAD & COPPER RULE	Violation type:	Initial Tap Sampling for Pb and Cu
Compliance start date:	4/1/2000 0:00:00	Compliance end date:	3/31/2002 0:00:00
Enforcement date:	1/11/2002 0:00:00	Enforcement action:	State Violation/Reminder Notice
Violation measurement:	Not Reported		
PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0200002
Contaminant:	LEAD & COPPER RULE	Violation type:	Initial Tap Sampling for Pb and Cu
Compliance start date:	4/1/2000 0:00:00	Compliance end date:	3/31/2002 0:00:00
Enforcement date:	3/31/2002 0:00:00	Enforcement action:	State Compliance Achieved
Violation measurement:	Not Reported		
PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0400003
Contaminant:	COLIFORM (TCR)		
Violation type:	Max Contaminant Level, Monthly (TCR)		
Compliance start date:	12/1/2003 0:00:00	Compliance end date:	12/31/2003 0:00:00
Enforcement date:	12/1/2003 0:00:00	Enforcement action:	State Public Notif Received
Violation measurement:	Not Reported		
PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0400004
Contaminant:	COLIFORM (TCR)	Violation type:	Monitoring, Routine Minor (TCR)
Compliance start date:	1/1/2004 0:00:00	Compliance end date:	1/31/2004 0:00:00
Enforcement date:	1/1/2004 0:00:00	Enforcement action:	State Public Notif Requested
Violation measurement:	Not Reported		
PWS name:	V & P TRAILER COURT	Population served:	35

PWS type code:	C	Violation ID:	0500005
Contaminant:	7000	Violation type:	71
Compliance start date:	7/1/2005 0:00:00	Compliance end date:	12/31/2025 0:00:00
Enforcement date:	No Enf Action as of	Enforcement action:	7/8/2009 0:00:00
Violation measurement:	Not Reported		

PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0600006
Contaminant:	COLIFORM (TCR)		
Violation type:	Max Contaminant Level, Monthly (TCR)		
Compliance start date:	3/1/2006 0:00:00	Compliance end date:	3/31/2006 0:00:00
Enforcement date:	3/1/2006 0:00:00	Enforcement action:	State Public Notif Received
Violation measurement:	Not Reported		

PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0600007
Contaminant:	COLIFORM (TCR)		
Violation type:	Max Contaminant Level, Monthly (TCR)		
Compliance start date:	4/1/2006 0:00:00	Compliance end date:	4/30/2006 0:00:00
Enforcement date:	4/1/2006 0:00:00	Enforcement action:	State Public Notif Requested
Violation measurement:	Not Reported		

PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	0700008
Contaminant:	ARSENIC	Violation type:	2
Compliance start date:	7/1/2006 0:00:00	Compliance end date:	6/30/2007 0:00:00
Enforcement date:	10/24/2007 0:00:00	Enforcement action:	State BCA Signed
Violation measurement:	12		

PWS name:	V & P TRAILER COURT	Population served:	35
PWS type code:	C	Violation ID:	95V0001
Contaminant:	LEAD & COPPER RULE	Violation type:	Initial Tap Sampling for Pb and Cu
Compliance start date:	7/1/1993 0:00:00	Compliance end date:	4/4/2000 0:00:00
Enforcement date:	4/4/2000 0:00:00	Enforcement action:	State Compliance Achieved
Violation measurement:	0		

AA220
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000100604**

Well ID:	T0607700157-MW6B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW6B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW6B		

AA221
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000085297**

Well ID:	T0607700157-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW2&store_num=		

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW2

Z222
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000003554**

Well ID:	T0607700539-U-21	Well Type:	MONITORING
Source:	EDF	Other Name:	U-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-21		

AB223
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186208**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10R001M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19530104	Well Depth:	304
Well Depth Units:	ft	Well Hole Depth:	304
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	1	Level reading date:	1953-01-04
Feet below surface:	47.00	Feet to sea level:	Not Reported
Note:	Not Reported		

AB224
SW
1/2 - 1 Mile
Higher

CA WELLS **CADWR9000037991**

State Well #:	01N06E10R001M	Station ID:	26501
Well Name:	01N06E10R001M	Basin Name:	Eastern San Joaquin
Well Use:	Irrigation	Well Type:	Single Well
Well Depth:	304	Well Completion Rpt #:	39-1084

AA225
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141399**

Well ID:	T0607700157-MW6A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6A

GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW6A&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW6A

AA226
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089144**

Well ID: T0607700157-MW4 Well Type: MONITORING
Source: EDF Other Name: MW4
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW4&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW4

AA227
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000118673**

Well ID: T0607700157-MW3 Well Type: MONITORING
Source: EDF Other Name: MW3
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW3&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW3

AA228
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000018905**

Well ID: T0607700157-MW1 Well Type: MONITORING
Source: EDF Other Name: MW1
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700157&assigned_name=MW1&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700157&assigned_name=MW1

Z229
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000021064**

Well ID: T0607700539-U-20 Well Type: MONITORING
Source: EDF Other Name: U-20
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-20&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-20

AA230
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000086057**

Well ID: T0607700692-MW9A
Well Type: MONITORING
Source: EDF
Other Name: MW9A
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700692&assigned_name=MW9A&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700692&assigned_name=MW9A

Z231
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008113**

Well ID: T0607700544-MW-7
Well Type: MONITORING
Source: EDF
Other Name: MW-7
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-7&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-7

Z232
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000069586**

Well ID: T0607700472-MW1
Well Type: MONITORING
Source: EDF
Other Name: MW1
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700472&assigned_name=MW1&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700472&assigned_name=MW1

Z233
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000086108**

Well ID: T0607700544-MW-9
Well Type: MONITORING
Source: EDF
Other Name: MW-9
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-9&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-9

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z234
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000038087**

Well ID:	T0607700544-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-8		

Z235
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000034881**

Well ID:	T0607700472-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700472&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700472&assigned_name=MW2		

Z236
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000054842**

Well ID:	T0607700544-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-3		

AC237
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000113916**

Well ID:	T0607700539-U-22	Well Type:	MONITORING
Source:	EDF	Other Name:	U-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-22		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AC238
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000018892**

Well ID:	T0607700539-U-23	Well Type:	MONITORING
Source:	EDF	Other Name:	U-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700539&assigned_name=U-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700539&assigned_name=U-23		

AC239
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000140593**

Well ID:	T0607700544-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-2		

AC240
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000117666**

Well ID:	T0607700544-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-1		

AC241
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000045767**

Well ID:	T0607700544-VX-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VX-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=VX-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=VX-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AD242
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000059623**

Well ID:	T0607700544-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-5		

AD243
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000013595**

Well ID:	T0607700544-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-10		

AD244
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000143294**

Well ID:	T0607700544-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-11		

AC245
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089611**

Well ID:	T0607700544-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AD246
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000112493**

Well ID:	T0607700544-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-6		

AD247
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000121557**

Well ID:	T0607700544-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-13		

AD248
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000100591**

Well ID:	T0607700544-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700544&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700544&assigned_name=MW-12		

AE249
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076338**

Well ID:	SL0002050099-MW-71	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-71
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-71&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-71		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE250
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000049826**

Well ID:	SL0002050099-MW-64	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-64
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-64&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-64		

AF251
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000023856**

Well ID:	T0607700584-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-6		

AE252
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000073831**

Well ID:	SL0002050099-MW-59	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-59
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-59&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-59		

AF253
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000114606**

Well ID:	T0607700584-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AF254
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000110699**

Well ID:	T0607700584-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-8		

AF255
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000042103**

Well ID:	T0607700584-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-12		

AG256
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000139513**

Well ID:	T10000011180-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000011180&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000011180&assigned_name=MW-2		

AE257
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138652**

Well ID:	SL0002050099-MW-41	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-41
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-41&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-41		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AG258
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000114397**

Well ID:	T10000011180-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000011180&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000011180&assigned_name=MW-3		

AH259
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000095323**

Well ID:	SL0002050099-MW-46	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-46
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-46&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-46		

AH260
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000053119**

Well ID:	SL0002050099-MW-66	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-66
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-66&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-66		

AH261
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045930**

Well ID:	SL0002050099-MW-73	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-73
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-73&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-73		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AF262
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000099575**

Well ID:	T0607700584-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-5		

AF263
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000099882**

Well ID:	T0607700584-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-1		

AG264
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000046457**

Well ID:	T10000011180-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000011180&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000011180&assigned_name=MW-5		

AG265
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000104068**

Well ID:	T10000011180-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000011180&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000011180&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AF266
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000024123**

Well ID:	T0607700584-MW-7A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-7A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-7A		

AI267
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059536**

Well ID:	SL0002050099-MW-33	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-33
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-33&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-33		

AI268
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000016711**

Well ID:	SL0002050099-MW-32	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-32
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-32&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-32		

AE269
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000133197**

Well ID:	SL0002050099-SB-4	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH270
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000002813**

Well ID:	SL0002050099-MW-65	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-65
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-65&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-65		

AF271
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000005265**

Well ID:	T0607700584-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-11		

AF272
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000091608**

Well ID:	T0607700584-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-4		

AE273
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000092001**

Well ID:	SL0002050099-SB-6	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH274
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078886**

Well ID:	SL0002050099-MW-31	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-31
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-31&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-31		

AJ275
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000005348**

Well ID:	T0607700827-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-5		

AH276
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114341**

Well ID:	SL0002050099-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-16		

AF277
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000131554**

Well ID:	T0607700584-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH278
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000010631**

Well ID:	SL0002050099-MW-72	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-72
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-72&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-72		

AE279
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000011652**

Well ID:	SL0002050099-SB-3	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-3		

AE280
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141752**

Well ID:	SL0002050099-SB-5	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-5		

AJ281
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000037351**

Well ID:	T0607700827-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AF282
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000083776**

Well ID:	T0607700584-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700584&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700584&assigned_name=MW-9		

AH283
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000119316**

Well ID:	SL0002050099-DPE-12	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-12		

AJ284
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000080077**

Well ID:	T0607700802-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW5		

AE285
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078319**

Well ID:	SL0002050099-SB-2	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-2		

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

AJ286
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000100594**

Well ID:	T0607700827-CPT-1	Well Type:	MONITORING
Source:	EDF	Other Name:	CPT-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=CPT-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=CPT-1		

AJ287
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000020251**

Well ID:	T0607700827-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-1		

AJ288
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000112665**

Well ID:	T0607700827-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-3		

AG289
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000033216**

Well ID:	T10000011180-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000011180&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000011180&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH290
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088132**

Well ID:	SL0002050099-DPE-11	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-11		

AE291
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125352**

Well ID:	SL0002050099-SB-1	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-1		

AH292
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105907**

Well ID:	SL0002050099-DPE-7	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-7		

AJ293
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000097612**

Well ID:	T0607700802-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE294
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076112**

Well ID:	SL0002050099-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-10		

AJ295
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000019381**

Well ID:	T0607700802-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW1		

AJ296
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000085474**

Well ID:	T0607700827-CPT-2	Well Type:	MONITORING
Source:	EDF	Other Name:	CPT-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=CPT-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=CPT-2		

AJ297
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000114905**

Well ID:	T0607700827-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AJ298
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000048136**

Well ID:	T0607700802-MW9A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW9A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW9A		

AK299
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000084390**

Well ID:	T0607700347-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-10		

AH300
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000120040**

Well ID:	SL0002050099-DPE-3	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-3		

AJ301
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000087019**

Well ID:	T0607700802-MW11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE302
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000058752**

Well ID:	SL0002050099-MW-53	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-53
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-53&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-53		

AE303
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000046432**

Well ID:	SL0002050099-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-4		

AL304
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000110426**

Well ID:	T0607700148-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW8		

AJ305
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000022395**

Well ID:	T0607700802-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AJ306
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000074457**

Well ID:	T0607700802-MW8A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW8A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW8A		

AJ307
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000120191**

Well ID:	T0607700802-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW2		

AJ308
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000010633**

Well ID:	T0607700827-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-6		

AH309
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033227**

Well ID:	SL0002050099-DPE-2	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK310
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089060**

Well ID:	T0607700347-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-6		

AH311
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000129528**

Well ID:	SL0002050099-DPE-5	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-5		

AJ312
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000061284**

Well ID:	T0607700802-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW7		

AJ313
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000077297**

Well ID:	T0607700827-CPT-3	Well Type:	MONITORING
Source:	EDF	Other Name:	CPT-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=CPT-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=CPT-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AJ314
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000115445**

Well ID:	T0607700802-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700802&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700802&assigned_name=MW6		

AE315
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000002101**

Well ID:	SL0002050099-MW-47	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-47
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-47&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-47		

AJ316
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000069922**

Well ID:	T0607700347-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-9		

AJ317
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000099858**

Well ID:	T0607700347-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE318
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000064720**

Well ID:	SL0002050099-MW-55	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-55
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-55&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-55		

AH319
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000140183**

Well ID:	SL0002050099-DPE-4	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-4		

AE320
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088141**

Well ID:	SL0002050099-2AMW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	2AMW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=2AMW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=2AMW-13		

AL321
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000020151**

Well ID:	T0607700148-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL322
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000093843**

Well ID:	T0607700148-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW6		

AH323
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012839**

Well ID:	SL0002050099-DPE-9	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=DPE-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=DPE-9		

AJ324
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000076498**

Well ID:	T0607700347-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-3		

AE325
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000071690**

Well ID:	SL0002050099-MW-54	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-54
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-54&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-54		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AE326
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000011115**

Well ID:	SL0002050099-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-17		

AK327
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000101422**

Well ID:	T0607700347-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-16		

AJ328
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000043390**

Well ID:	T0607700827-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700827&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700827&assigned_name=MW-7		

AJ329
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000087806**

Well ID:	T0607700347-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK330
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000015074**

Well ID:	T0607700347-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-5		

AL331
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000024130**

Well ID:	T0607700148-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW1		

AE332
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000043192**

Well ID:	SL0002050099-MW-42	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-42
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-42&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-42		

AH333
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062723**

Well ID:	SL0002050099-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-22		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL334
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000069061**

Well ID:	T0607700148-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW2		

AM335
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000056308**

Well ID:	SL0002050099-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-9		

AK336
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000065109**

Well ID:	T0607700347-MW-17B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-17B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-17B		

AM337
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105531**

Well ID:	SL0002050099-SB-7	Well Type:	MONITORING
Source:	EDF	Other Name:	SB-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=SB-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=SB-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH338
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000038035**

Well ID:	SL0002050099-MW-28	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-28
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-28&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-28		

AK339
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000075714**

Well ID:	T0607700347-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-13		

AK340
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000029720**

Well ID:	T0607700347-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-8		

AL341
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051410**

Well ID:	T0607700148-AS2	Well Type:	MONITORING
Source:	EDF	Other Name:	AS2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=AS2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=AS2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK342
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000085755**

Well ID:	T0607700347-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-4		

AH343
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000107819**

Well ID:	SL0002050099-MW-27	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-27
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-27&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-27		

AL344
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000127300**

Well ID:	T0607700148-VW1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=VW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=VW1		

AL345
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000034500**

Well ID:	T0607700148-VW2	Well Type:	MONITORING
Source:	EDF	Other Name:	VW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=VW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=VW2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL346
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134021**

Well ID:	T0607700148-AS1	Well Type:	MONITORING
Source:	EDF	Other Name:	AS1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=AS1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=AS1		

AK347
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000135472**

Well ID:	T0607700347-MW-18C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-18C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-18C		

AK348
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000052194**

Well ID:	T0607700347-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-1		

AH349
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000116536**

Well ID:	SL0002050099-MW-60	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-60
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-60&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-60		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AH350
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102958**

Well ID:	SL0002050099-MW-67	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-67
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-67&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-67		

AH351
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000019950**

Well ID:	SL0002050099-MW-74	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-74
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-74&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-74		

AL352
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000043909**

Well ID:	T0607700148-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW9		

AL353
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021260**

Well ID:	T0607700148-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AM354
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000060399**

Well ID:	SL0002050099-MW-58	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-58
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-58&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-58		

AM355
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122903**

Well ID:	SL0002050099-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-18		

AM356
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000131281**

Well ID:	SL0002050099-MW-70	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-70
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-70&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-70		

AK357
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000004539**

Well ID:	T0607700347-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AM358
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082572**

Well ID:	SL0002050099-MW-63	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-63
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-63&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-63		

AM359
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088425**

Well ID:	SL0002050099-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-21		

AM360
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000015388**

Well ID:	SL0002050099-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-19		

AN361
NNE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000020544**

Well ID:	3910001-046	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 53-01 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-046&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AO362
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089738**

Well ID:	T0607700523-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW2		

AO363
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000056284**

Well ID:	T0607700523-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW5		

AO364
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000021288**

Well ID:	T0607700523-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW9		

AO365
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000003552**

Well ID:	T0607700523-MW1B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW1B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW1B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AO366
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000045604**

Well ID:	T0607700523-MW1A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW1A		

AO367
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000140092**

Well ID:	T0607700523-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW8		

AO368
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128362**

Well ID:	T0607700523-MW1C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW1C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW1C		

AO369
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000093450**

Well ID:	T0607700523-MW1D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW1D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW1D		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AO370
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000116132**

Well ID:	T0607700523-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW4		

AL371
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000039101**

Well ID:	T0607700148-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW7		

AL372
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000090798**

Well ID:	T0607700471-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-6		

AP373
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000040340**

Well ID:	T0607700825-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL374
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045127**

Well ID:	T0607700471-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-4		

AL375
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000130878**

Well ID:	T0607700148-CW	Well Type:	MONITORING
Source:	EDF	Other Name:	CW
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=CW&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=CW		

AL376
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070354**

Well ID:	T0607700148-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW5		

AM377
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097869**

Well ID:	SL0002050099-2AMW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	2AMW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=2AMW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=2AMW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AM378
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012728**

Well ID:	SL0002050099-MW-48	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-48
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-48&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-48		

AO379
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000074282**

Well ID:	T0607700523-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW3		

AO380
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000017121**

Well ID:	T0607700523-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW7		

AO381
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000012921**

Well ID:	T0607700523-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW6		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
AL382 **NNW** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CAEDF0000126082**

Well ID:	T0607700471-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-3		

	Database	EDR ID Number
AL383 **NNW** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CAEDF0000080748**

Well ID:	T0607700471-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-1		

	Database	EDR ID Number
AO384 **North** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAEDF0000091038**

Well ID:	T0607700523-MW11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW11		

	Database	EDR ID Number
AK385 **SE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAEDF0000079651**

Well ID:	T0607700347-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AM386
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000037723**

Well ID:	SL0002050099-MW-51	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-51
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-51&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-51		

AO387
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000095143**

Well ID:	T0607700523-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700523&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700523&assigned_name=MW10		

AM388
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000106720**

Well ID:	SL0002050099-MW-50	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-50
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-50&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-50		

AP389
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000109007**

Well ID:	T0607700825-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK390
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000041060**

Well ID:	T0607700542-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-3		

AL391
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000038712**

Well ID:	T0607700471-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-9		

AL392
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097107**

Well ID:	T0607700471-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-10		

AK393
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000140466**

Well ID:	T0607700347-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700347&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700347&assigned_name=MW-11		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AN394
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000186278**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E02Q001M	Type:	Well
Description:	Not Reported	HUC:	18040004
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19600501	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	564
Well Hole Depth Units:	ft		

AO395
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000103586**

Well ID:	T10000004659-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004659&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004659&assigned_name=MW-1		

AP396
NNW
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000000816**

Well ID:	01N06E02M001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E02M001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E02M001M&store_num=		
GeoTracker Data:	Not Reported		

AK397
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000070740**

Well ID:	T0607700542-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AP398
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032709**

Well ID:	T0607700825-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW3		

AQ399
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097139**

Well ID:	T0607700508-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-12		

AK400
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000133509**

Well ID:	T0607700542-MW-104	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-104
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-104&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-104		

AP401
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126427**

Well ID:	T0607700825-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK402
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000072240**

Well ID:	T0607700542-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-2		

AQ403
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036508**

Well ID:	T0607700508-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-11		

AL404
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000077600**

Well ID:	T0607700471-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-2		

AP405
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078723**

Well ID:	T0607700825-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AK406
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000063490**

Well ID:	T0607700542-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-5		

AQ407
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000057319**

Well ID:	T0607700508-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-2		

AM408
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000092697**

Well ID:	SL0002050099-MW-68	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-68
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-68&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-68		

AL409
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141228**

Well ID:	T0607700471-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AL410
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000120139**

Well ID:	T0607700471-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-12		

AL411
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000111780**

Well ID:	T0607700471-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-5		

AM412
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000055943**

Well ID:	SL0002050099-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-20		

AM413
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000015701**

Well ID:	SL0002050099-MW-62	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-62
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-62&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-62		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AM414
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000091393**

Well ID:	SL0002050099-MW-69	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-69
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-69&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-69		

AM415
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000075431**

Well ID:	SL0002050099-MW-57	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-57
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-57&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-57		

AR416
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000083905**

Well ID:	T0607700148-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700148&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700148&assigned_name=MW10		

AR417
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000107665**

Well ID:	T0607700471-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AS418
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000091430**

Well ID:	T0607700542-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-7		

AS419
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000058203**

Well ID:	T0607700542-MW-107	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-107
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-107&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-107		

AP420
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000113655**

Well ID:	T0607700825-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW6		

421
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186224**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q003M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19630315	Well Depth:	472
Well Depth Units:	ft	Well Hole Depth:	519

Well Hole Depth Units: ft

Ground water levels,Number of Measurements: 1 Level reading date: 1963-03-15
Feet below surface: 84.00 Feet to sea level: Not Reported
Note: Not Reported

AQ422
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000132032**

Well ID: T0607700508-MW-1B Well Type: MONITORING
Source: EDF Other Name: MW-1B
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-1B&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-1B

AQ423
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000115784**

Well ID: T0607700508-MW-1 Well Type: MONITORING
Source: EDF Other Name: MW-1
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-1&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-1

AS424
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000139579**

Well ID: T0607700542-MW-106 Well Type: MONITORING
Source: EDF Other Name: MW-106
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-106&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-106

AS425
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000118106**

Well ID: T0607700542-MW-6 Well Type: MONITORING
Source: EDF Other Name: MW-6
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-6&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-6

AP426
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097615**

Well ID: T0607700825-MW7
Well Type: MONITORING
Source: EDF
Other Name: MW7
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700825&assigned_name=MW7&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700825&assigned_name=MW7

AM427
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126418**

Well ID: SL0002050099-MW-61
Well Type: MONITORING
Source: EDF
Other Name: MW-61
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-61&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-61

AM428
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117868**

Well ID: SL0002050099-MW-56
Well Type: MONITORING
Source: EDF
Other Name: MW-56
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-56&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-56

AS429
SE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000041011**

Well ID: T0607700542-MW-1
Well Type: MONITORING
Source: EDF
Other Name: MW-1
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700542&assigned_name=MW-1&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700542&assigned_name=MW-1

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ430
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141020**

Well ID:	T0607700508-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-5		

AT431
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000038137**

Well ID:	SL0002050099-MW-45	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-45
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-45&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-45		

AQ432
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000115685**

Well ID:	T0607700508-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-7		

AQ433
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000035067**

Well ID:	T0607700508-MW-1C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-1C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-1C		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ434
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000077063**

Well ID:	T0607700508-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-9		

AR435
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000048735**

Well ID:	T0607700471-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-14		

AT436
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000024047**

Well ID:	SL0002050099-MW-44	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-44
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-44&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-44		

AT437
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000131581**

Well ID:	SL0002050099-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-24		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AT438
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000091375**

Well ID:	SL0002050099-MW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-23		

AQ439
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062706**

Well ID:	T0607700195-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-15		

AQ440
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094425**

Well ID:	T0607700508-SMW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-15		

AQ441
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000115616**

Well ID:	T0607700508-AMW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AR442
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000116613**

Well ID:	T0607700471-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-13		

AU443
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000038113**

Well ID:	T10000004123-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-7		

AQ444
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138419**

Well ID:	T0607700508-AMW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-12		

AV445
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122640**

Well ID:	T0607700508-AMW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AT446
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097812**

Well ID:	SL0002050099-MW-29	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-29
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-29&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-29		

AT447
West
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125264**

Well ID:	SL0002050099-MW-30	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-30
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-30&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-30		

AW448
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000022908**

Well ID:	T0607791425-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW6		

AQ449
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000107382**

Well ID:	T0607700508-AMW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AU450
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186210**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q007M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19690514	Well Depth:	652
Well Depth Units:	ft	Well Hole Depth:	780
Well Hole Depth Units:	ft		

AQ451
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000041944**

Well ID:	T0607700508-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-3		

AW452
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089000**

Well ID:	T0607791425-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW8		

AQ453
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000130388**

Well ID:	T0607700508-MW-8C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-8C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-8C		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ454
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070462**

Well ID:	T0607700508-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-8		

AQ455
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000034255**

Well ID:	T0607700508-MW-8B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-8B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-8B		

AQ456
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000084767**

Well ID:	T0607700508-AMW-1B	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-1B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-1B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-1B		

AQ457
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000069453**

Well ID:	T0607700508-AMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ458
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000054270**

Well ID:	T0607700508-AMW-1C	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-1C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-1C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-1C		

AW459
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000137400**

Well ID:	T0607791425-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW2		

460
East
1/2 - 1 Mile
Higher

CA WELLS **CADPR0000003838**

Well ID:	77857	Well Type:	UNK
Source:	Department of Pesticide Regulation		
Other Name:	77857	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DPR&samp_date=&global_id=&assigned_name=77857&store_num=		
GeoTracker Data:	Not Reported		

AU461
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076393**

Well ID:	T10000004123-MW-9A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-9A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-9A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AW462
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032600**

Well ID:	T0607791425-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW4		

AR463
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000091681**

Well ID:	T0607700471-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700471&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700471&assigned_name=MW-16		

AV464
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000039117**

Well ID:	T0607700508-AMW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-5		

AW465
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000035646**

Well ID:	T0607791425-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AW466
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122962**

Well ID:	T0607791425-MW11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW11		

AW467
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097398**

Well ID:	T0607791425-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW10		

AQ468
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099494**

Well ID:	T0607700508-AMW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-9		

AU469
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000022118**

Well ID:	T10000004123-MW-9B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-9B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-9B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AU470
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000112789**

Well ID:	T10000004123-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-6		

AV471
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000004300**

Well ID:	T0607700508-AMW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-7		

AQ472
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000093229**

Well ID:	T0607700508-SMW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-17		

AQ473
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033846**

Well ID:	T0607700195-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-17		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AW474
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000119474**

Well ID:	T0607791425-DPE1	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=DPE1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=DPE1		

AW475
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032785**

Well ID:	T0607791425-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW1		

AW476
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000098221**

Well ID:	T0607791425-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW5		

AQ477
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000143156**

Well ID:	T0607700508-SMW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ478
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000110497**

Well ID:	T0607700195-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-9		

AQ479
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000132968**

Well ID:	T0607700508-SMW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-11		

AQ480
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000016434**

Well ID:	T0607700195-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-11		

AU481
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082892**

Well ID:	T10000004123-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AW482
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000090186**

Well ID:	T0607791425-MW15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW15		

AV483
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000017833**

Well ID:	T0607700508-AMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-3		

AQ484
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051336**

Well ID:	T0607700508-SMW-11-82	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-11-82
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-11-82&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-11-82		

AQ485
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123062**

Well ID:	T0607700195-MW-11-82	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11-82
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-11-82&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-11-82		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ486
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032250**

Well ID:	T0607700195-MW-11-122	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11-122
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-11-122&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-11-122		

AQ487
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000047831**

Well ID:	T0607700508-SMW-11-122	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-11-122
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-11-122&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-11-122		

AW488
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000009726**

Well ID:	T0607791425-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW7		

AV489
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000127755**

Well ID:	T0607700508-AMW-8C	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-8C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-8C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-8C		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ490
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089970**

Well ID:	T0607700195-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-5		

AQ491
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099806**

Well ID:	T0607700508-SMW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-5		

AV492
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000001407**

Well ID:	T0607700508-AMW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-8		

AX493
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000084417**

Well ID:	SL0002050099-MW-34	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-34
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-34&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-34		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AX494
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000057419**

Well ID:	SL0002050099-MW-35	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-35
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-35&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-35		

AQ495
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000083207**

Well ID:	T0607700195-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-20		

AQ496
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000044631**

Well ID:	T0607700508-SMW20-83.5	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW20-83.5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW20-83.5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW20-83.5		

AV497
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000118463**

Well ID:	T0607700195-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV498
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000108392**

Well ID:	T0607700508-SMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-1		

499
NNE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000008792**

Well ID:	3901029-001	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 01 - INACTIVE	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3901029-001&store_num=		
GeoTracker Data:	Not Reported		

AV500
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000005004**

Well ID:	T0607700508-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=MW-6		

AV501
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000002174**

Well ID:	T0607700508-AMW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AQ502
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000016643**

Well ID:	T0607700195-MW-19-81	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19-81
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-19-81&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-19-81		

AQ503
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051048**

Well ID:	T0607700508-SMW-19-81	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-19-81
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-19-81&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-19-81		

AQ504
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000130223**

Well ID:	T0607700508-SMW-19-120	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-19-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-19-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-19-120		

AQ505
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117313**

Well ID:	T0607700195-MW-19-120	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-19-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-19-120		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AY506
ESE
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000186212**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E12N001M	Type:	Well
Description:	Not Reported	HUC:	18040004
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19600301	Well Depth:	520
Well Depth Units:	ft	Well Hole Depth:	528
Well Hole Depth Units:	ft		

AV507
SSW
1/2 - 1 Mile
Lower | **CA WELLS** | **CAEDF0000107986**

Well ID:	T0607700508-AMW-8B	Well Type:	MONITORING
Source:	EDF	Other Name:	AMW-8B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=AMW-8B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=AMW-8B		

AV508
SSW
1/2 - 1 Mile
Lower | **CA WELLS** | **CAEDF0000135037**

Well ID:	T0607700717-MW-2R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-2R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-2R		

AV509
SSW
1/2 - 1 Mile
Lower | **CA WELLS** | **CAEDF0000105827**

Well ID:	T0607700717-VW-2D	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-2D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=VW-2D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=VW-2D		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV510
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125820**

Well ID:	T0607700717-MW-9I	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9I
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-9I&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-9I		

AV511
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000020635**

Well ID:	T0607700717-MW-4RD	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4RD
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-4RD&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-4RD		

AV512
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094340**

Well ID:	T0607700717-MW-4RS	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4RS
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-4RS&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-4RS		

AV513
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000087049**

Well ID:	T0607700195-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV514
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000053996**

Well ID:	T0607700508-SMW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-4		

AZ515
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000087369**

Well ID:	T0607700323-MW28	Well Type:	MONITORING
Source:	EDF	Other Name:	MW28
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW28&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW28		

BA516
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000072148**

Well ID:	T0607700508-SMW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-23		

BA517
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000007855**

Well ID:	T0607700195-MW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-23		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV518
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089634**

Well ID:	T0607700717-VW-3D	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-3D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=VW-3D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=VW-3D		

AY519
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAUSGSN00007805**

Well ID:	USGS-375636121161601	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-375636121161601	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-375636121161601&store_num=		
GeoTracker Data:	Not Reported		

BA520
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000074971**

Well ID:	T0607700195-MW-10-81	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10-81
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-10-81&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-10-81		

BA521
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078894**

Well ID:	T0607700508-SMW-10-117	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-10-117
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-10-117&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-10-117		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA522
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000121633**

Well ID:	T0607700508-SMW-10-81	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-10-81
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-10-81&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-10-81		

BA523
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000046932**

Well ID:	T0607700508-SMW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-10		

BA524
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000050179**

Well ID:	T0607700195-MW-10-117	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10-117
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-10-117&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-10-117		

BA525
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000052173**

Well ID:	T0607700195-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV526
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000142814**

Well ID:	T0607700508-SMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-3		

AV527
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114373**

Well ID:	T0607700195-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-3		

AV528
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000131137**

Well ID:	T0607700717-VW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=VW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=VW-4		

AV529
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000016647**

Well ID:	T0607700717-MW-7S	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7S
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-7S&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-7S		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV530
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021113**

Well ID:	T0607700717-MW-11D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-11D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-11D		

AV531
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123070**

Well ID:	T0607700717-VW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=VW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=VW-1		

AV532
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102455**

Well ID:	T0607700717-VW-1D	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-1D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=VW-1D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=VW-1D		

AV533
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082142**

Well ID:	T0607700717-MW-8I	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8I
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-8I&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-8I		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ534
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122401**

Well ID:	T0607700323-MW11B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW11B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW11B		

AZ535
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000129334**

Well ID:	T0607700323-MW13A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW13A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW13A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW13A		

AZ536
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000053899**

Well ID:	T0607700323-MW11A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW11A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW11A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW11A		

AZ537
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000092734**

Well ID:	T0607700323-MW13B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW13B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW13B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW13B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AW538
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000060479**

Well ID:	T0607791425-MW13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW13		

AU539
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114569**

Well ID:	T10000004123-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-4		

AW540
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000051164**

Well ID:	T0607791425-MW14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW14		

AZ541
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000044604**

Well ID:	T0607700323-MW14A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW14A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW14A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW14A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ542
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033611**

Well ID:	T0607700323-MW14B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW14B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW14B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW14B		

AV543
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000106259**

Well ID:	T0607700717-MW-10I	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10I
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-10I&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-10I		

AV544
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078486**

Well ID:	T0607700717-MW-12D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-12D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-12D		

AV545
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065412**

Well ID:	T0607700717-MW-1R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-1R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-1R		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ546
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000104628**

Well ID:	T0607700323-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW9		

AZ547
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000080413**

Well ID:	T0607700323-MW12A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW12A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW12A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW12A		

AZ548
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000023729**

Well ID:	T0607700323-MW12B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW12B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW12B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW12B		

AV549
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094154**

Well ID:	T0607700508-SMW-3-79	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-3-79
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-3-79&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-3-79		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV550
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088288**

Well ID:	T0607700508-SMW-3-119	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-3-119
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-3-119&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-3-119		

AV551
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076959**

Well ID:	T0607700195-MW-3-119	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3-119
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-3-119&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-3-119		

AV552
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000111614**

Well ID:	T0607700195-MW-3-79	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3-79
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-3-79&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-3-79		

AZ553
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000137165**

Well ID:	T0607700323-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ554
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000084412**

Well ID:	T0607700323-EW1	Well Type:	MONITORING
Source:	EDF	Other Name:	EW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=EW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=EW1		

AW555
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000092063**

Well ID:	T0607791425-MW12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607791425&assigned_name=MW12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607791425&assigned_name=MW12		

AZ556
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114332**

Well ID:	T0607700323-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW5		

AZ557
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000103057**

Well ID:	T0607700323-MW26	Well Type:	MONITORING
Source:	EDF	Other Name:	MW26
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW26&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW26		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BB558
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186216**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q009M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Flood-Basin Deposits	Aquifer Type:	Not Reported
Construction Date:	19621018	Well Depth:	576
Well Depth Units:	ft	Well Hole Depth:	584
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	1	Level reading date:	1962-10-18
Feet below surface:	87.00	Feet to sea level:	Not Reported
Note:	Not Reported		

AV559
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105370**

Well ID:	T0607700508-SMW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-7		

AV560
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082266**

Well ID:	T0607700195-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-7		

AZ561
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059033**

Well ID:	T0607700323-MW8A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8A

GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW8A&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW8A

BB562
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAUSGSN00004781**

Well ID: USGS-375639121180101 Well Type: UNK
Source: United States Geological Survey
Other Name: USGS-375639121180101 GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-375639121180101&store_num=
GeoTracker Data: Not Reported

AZ563
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032524**

Well ID: T0607700323-MW30 Well Type: MONITORING
Source: EDF Other Name: MW30
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW30&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW30

AZ564
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000085585**

Well ID: T0607700323-MW29 Well Type: MONITORING
Source: EDF Other Name: MW29
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW29&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW29

AZ565
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000120392**

Well ID: T0607700323-MW25 Well Type: MONITORING
Source: EDF Other Name: MW25
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW25&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW25

AV566
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000064158**

Well ID:	T0607700195-MW-18-120	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-18-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-18-120		

AV567
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000096282**

Well ID:	T0607700195-MW-18-80	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18-80
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-18-80&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-18-80		

AV568
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000039302**

Well ID:	T0607700508-SMW-18-120	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-18-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-18-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-18-120		

AV569
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000054367**

Well ID:	T0607700508-SMW-18-80	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-18-80
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-18-80&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-18-80		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA570
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000056446**

Well ID:	T0607700195-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-8		

BA571
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000009287**

Well ID:	T0607700508-SMW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-8		

BC572
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125510**

Well ID:	SL0002050099-MW-25	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-25		

BC573
WNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078237**

Well ID:	SL0002050099-MW-26	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-26
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0002050099&assigned_name=MW-26&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0002050099&assigned_name=MW-26		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV574
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000135870**

Well ID:	T0607700508-SMW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-2		

AV575
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062141**

Well ID:	T0607700195-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-2		

AZ576
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000023469**

Well ID:	T0607700323-MW15A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW15A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW15A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW15A		

BD577
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000127601**

Well ID:	T0607700124-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA578
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065283**

Well ID:	T0607700653-C11	Well Type:	MONITORING
Source:	EDF	Other Name:	C11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C11		

AZ579
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000136354**

Well ID:	T0607700323-MW27	Well Type:	MONITORING
Source:	EDF	Other Name:	MW27
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW27&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW27		

BD580
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000121121**

Well ID:	T0607700124-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW5		

BA581
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105086**

Well ID:	T0607700195-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-21		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA582
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000125593**

Well ID:	T0607700508-SMW-21-80	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-21-80
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-21-80&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-21-80		

BA583
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099122**

Well ID:	T0607700508-SLMW-9-120	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-9-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-9-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-9-120		

BA584
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000104981**

Well ID:	T0607700653-CTMW-9-120	Well Type:	MONITORING
Source:	EDF	Other Name:	CTMW-9-120
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=CTMW-9-120&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=CTMW-9-120		

BA585
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000139302**

Well ID:	T0607700508-SLMW-3A	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-3A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA586
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000112338**

Well ID:	T0607700653-MW-3A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-3A		

AV587
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000108278**

Well ID:	T0607700195-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-22		

AV588
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000080102**

Well ID:	T0607700508-SMW-22-80	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-22-80
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-22-80&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-22-80		

AV589
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126618**

Well ID:	T0607700508-CMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AV590
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000073319**

Well ID:	T0607700508-CMW-5C	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-5C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-5C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-5C		

AV591
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062101**

Well ID:	T0607700702-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-3		

AZ592
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000096538**

Well ID:	T0607700323-MW6A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW6A		

AV593
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000014703**

Well ID:	T0607700717-MW-3R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700717&assigned_name=MW-3R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700717&assigned_name=MW-3R		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA594
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097298**

Well ID:	T0607700653-C8	Well Type:	MONITORING
Source:	EDF	Other Name:	C8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C8		

AV595
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000128388**

Well ID:	T0607700508-CMW-5A	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-5A		

AV596
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000074852**

Well ID:	T0607700702-MW-5A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-5A		

BB597
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186217**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q002M	Type:	Well
Description:	Not Reported	HUC:	18040003
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	970

Well Hole Depth Units: ft

AZ598
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000013464**

Well ID:	T0607700323-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW2		

AZ599
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000086278**

Well ID:	T0607700323-EW2	Well Type:	MONITORING
Source:	EDF	Other Name:	EW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=EW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=EW2		

AZ600
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000100430**

Well ID:	T0607700323-MW15B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW15B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW15B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW15B		

BD601
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000054892**

Well ID:	T0607700124-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BD602
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000016820**

Well ID:	T0607700124-OB1	Well Type:	MONITORING
Source:	EDF	Other Name:	OB1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=OB1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=OB1		

BA603
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000111563**

Well ID:	T0607700508-SMW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-6		

BA604
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012162**

Well ID:	T0607700195-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-6		

AV605
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105802**

Well ID:	T0607700702-MW-5C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-5C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-5C		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AY606
ESE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000013191**

Well ID:	3910001-043	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 50-01 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-043&store_num=		
GeoTracker Data:	Not Reported		

AV607
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070596**

Well ID:	T0607700508-SMW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-13		

AV608
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000043802**

Well ID:	T0607700195-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-13		

BA609
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000101608**

Well ID:	T0607700653-C9	Well Type:	MONITORING
Source:	EDF	Other Name:	C9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ610
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082240**

Well ID:	T0607700323-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW7		

AV611
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000108673**

Well ID:	T0607700702-MW-4C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-4C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-4C		

AV612
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089855**

Well ID:	T0607700508-CMW-4C	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-4C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-4C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-4C		

BA613
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065958**

Well ID:	T0607700204-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA614
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000083054**

Well ID:	T0607700653-MW-4A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-4A		

BA615
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059147**

Well ID:	T0607700508-SLMW-4A	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-4A		

BD616
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000055296**

Well ID:	T0607700124-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW2		

BD617
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138870**

Well ID:	T0607700124-IAS-1	Well Type:	MONITORING
Source:	EDF	Other Name:	IAS-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=IAS-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=IAS-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BD618
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000118307**

Well ID:	T0607700124-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW1		

BD619
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076497**

Well ID:	T0607700124-EW1	Well Type:	MONITORING
Source:	EDF	Other Name:	EW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=EW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=EW1		

BA620
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045392**

Well ID:	T0607700508-SLMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-1		

BA621
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059290**

Well ID:	T0607700653-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA622
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000121272**

Well ID:	T0607700508-SLMW-7D	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-7D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-7D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-7D		

BA623
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000044433**

Well ID:	T0607700653-VE-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VE-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=VE-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=VE-1		

BA624
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000007762**

Well ID:	T0607700508-SLVE-1	Well Type:	MONITORING
Source:	EDF	Other Name:	SLVE-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLVE-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLVE-1		

BA625
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033868**

Well ID:	T0607700508-SLMW-7S	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-7S
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-7S&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-7S		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA626
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036820**

Well ID:	T0607700653-MW-7D	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7D
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-7D&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-7D		

BE627
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000085335**

Well ID:	T0607700508-CMW-4A	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-4A		

BE628
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065538**

Well ID:	T0607700702-MW-4A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-4A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-4A		

BF629
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000072703**

Well ID:	SL0607793529-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BG630
East
1/2 - 1 Mile
Higher

CA WELLS **CADPR0000004676**

Well ID:	77856	Well Type:	UNK
Source:	Department of Pesticide Regulation		
Other Name:	77856	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DPR&samp_date=&global_id=&assigned_name=77856&store_num=		
GeoTracker Data:	Not Reported		

BF631
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000076421**

Well ID:	SL0607793529-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-6		

BA632
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070135**

Well ID:	T0607700653-MW-1A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-1A		

BA633
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045333**

Well ID:	T0607700508-SLMW-1A	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-1A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA634
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114625**

Well ID:	T0607700653-C2	Well Type:	MONITORING
Source:	EDF	Other Name:	C2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C2		

BA635
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070332**

Well ID:	T0607700653-C1	Well Type:	MONITORING
Source:	EDF	Other Name:	C1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C1		

BA636
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000114279**

Well ID:	T0607700653-C10	Well Type:	MONITORING
Source:	EDF	Other Name:	C10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C10		

BD637
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051002**

Well ID:	T0607700124-OB2	Well Type:	MONITORING
Source:	EDF	Other Name:	OB2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=OB2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=OB2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BD638
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021836**

Well ID:	T0607700124-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW3		

639
SE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000005488**

Well ID:	01N06E12N001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12N001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12N001M&store_num=		
GeoTracker Data:	Not Reported		

BE640
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000101269**

Well ID:	T0607700305-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-10		

BA641
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000101840**

Well ID:	T0607700204-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA642
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000081668**

Well ID:	T0607700204-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-8		

BE643
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000074308**

Well ID:	T0607700508-CMW-6A	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-6A		

BE644
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000066247**

Well ID:	T0607700702-MW-6C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-6C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-6C		

BE645
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000060999**

Well ID:	T0607700702-MW-6A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-6A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BE646
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000009767**

Well ID:	T0607700508-CMW-6C	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-6C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-6C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-6C		

BA647
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000107553**

Well ID:	T0607700653-C5	Well Type:	MONITORING
Source:	EDF	Other Name:	C5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C5		

BA648
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000069986**

Well ID:	T0607700653-C4	Well Type:	MONITORING
Source:	EDF	Other Name:	C4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C4		

BA649
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000060139**

Well ID:	T0607700508-SLMW-8-87	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-8-87
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-8-87&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-8-87		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BH650
ENE
1/2 - 1 Mile
Higher

CA WELLS **221**

Seq:	221	Prim sta c:	01N/06E-12C08 M
Frds no:	3910001001	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 01-16 - STANDBY	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	375708.0	Longitude:	1211610.0
Precision:	3	Status:	SR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

BH651
ENE
1/2 - 1 Mile
Higher

CA WELLS **23079**

Seq:	23079	Prim sta c:	J39/001-01-16TR
Frds no:	3910001070	County:	39
District:	10	User id:	PTA
System no:	3910001	Water type:	G
Source nam:	WELL 01-16 - STANDBY, TREATED	Station ty:	WELL/AMBNT
Latitude:	375708.0	Longitude:	1211610.0
Precision:	4	Status:	ST
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3910001	System nam:	California Water Service - Stockton
Hqname:	CALIFORNIA WTR SERV CO	Address:	1720 N. FIRST STREET
City:	SAN JOSE	State:	CA
Zip:	95112	Zip ext:	Not Reported
Pop serv:	155670	Connection:	40808
Area serve:	Not Reported		

BI652
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000066595**

Well ID:	T0607700253-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW1&store_num=		

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW1

BD653
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033606**

Well ID: T0607700124-MW4
Source: EDF
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW4&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW4
Well Type: MONITORING
Other Name: MW4

AZ654
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000120158**

Well ID: T0607700323-MW3
Source: EDF
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW3&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW3
Well Type: MONITORING
Other Name: MW3

BE655
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045564**

Well ID: T0607700508-CMW-2
Source: EDF
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-2&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-2
Well Type: MONITORING
Other Name: CMW-2

BE656
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000024114**

Well ID: T0607700702-MW-2
Source: EDF
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-2&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-2
Well Type: MONITORING
Other Name: MW-2

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AZ657
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102378**

Well ID:	T0607700323-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW4		

AZ658
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122172**

Well ID:	T0607700323-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700323&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700323&assigned_name=MW1		

BA659
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000140087**

Well ID:	T0607700653-C7	Well Type:	MONITORING
Source:	EDF	Other Name:	C7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=C7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=C7		

BA660
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000080128**

Well ID:	T0607700508-SLMW-2A	Well Type:	MONITORING
Source:	EDF	Other Name:	SLMW-2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SLMW-2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SLMW-2A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA661
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063203**

Well ID:	T0607700653-MW-2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=MW-2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=MW-2A		

BE662
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000101818**

Well ID:	T0607700702-MW-7A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-7A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-7A		

BE663
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000110553**

Well ID:	T0607700508-CMW-7B	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-7B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-7B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-7B		

BE664
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062469**

Well ID:	T0607700508-CMW-7A	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-7A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-7A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-7A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BE665
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000010811**

Well ID:	T0607700702-MW-7C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-7C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-7C		

BE666
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059052**

Well ID:	T0607700702-MW-7B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-7B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-7B		

BA667
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078738**

Well ID:	T0607700204-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-7		

BA668
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000136168**

Well ID:	T0607700653-CT-MW-8-87	Well Type:	MONITORING
Source:	EDF	Other Name:	CT-MW-8-87
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700653&assigned_name=CT-MW-8-87&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700653&assigned_name=CT-MW-8-87		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA669
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033552**

Well ID:	T0607700508-SMW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	SMW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=SMW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=SMW-14		

BA670
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000000168**

Well ID:	T0607700195-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700195&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700195&assigned_name=MW-14		

BF671
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000013931**

Well ID:	SL0607793529-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-2		

BI672
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000134899**

Well ID:	T0607700253-VW1A	Well Type:	MONITORING
Source:	EDF	Other Name:	VW1A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=VW1A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=VW1A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI673
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000032696**

Well ID:	T0607700253-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW7		

BI674
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000086433**

Well ID:	T0607700253-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW4		

BI675
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000006486**

Well ID:	T0607700253-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW5		

BI676
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000080520**

Well ID:	T0607700253-VW3A	Well Type:	MONITORING
Source:	EDF	Other Name:	VW3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=VW3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=VW3A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BD677
NW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000135342**

Well ID:	T0607700124-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700124&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700124&assigned_name=MW8		

BF678
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134883**

Well ID:	SL0607793529-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-4		

BJ679
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186209**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q008M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19650519	Well Depth:	635
Well Depth Units:	ft	Well Hole Depth:	655
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	1	Level reading date:	1965-05-19
Feet below surface:	68.00	Feet to sea level:	Not Reported
Note:	Not Reported		

BI680
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000070181**

Well ID:	T0607700253-VW2A	Well Type:	MONITORING
Source:	EDF	Other Name:	VW2A

GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=VW2A&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=VW2A

BA681
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000132798**

Well ID: T0607700204-MW-17 Well Type: MONITORING
Source: EDF Other Name: MW-17
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-17&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-17

BA682
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000072841**

Well ID: T0607700204-MW-16 Well Type: MONITORING
Source: EDF Other Name: MW-16
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-16&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-16

BA683
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000052261**

Well ID: T0607700204-MW-2 Well Type: MONITORING
Source: EDF Other Name: MW-2
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-2&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-2

BF684
NNW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099741**

Well ID: SL0607793529-MW-3 Well Type: MONITORING
Source: EDF Other Name: MW-3
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-3&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-3

BI685
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000109276**

Well ID:	T0607700253-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW2		

BI686
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000035804**

Well ID:	T0607700253-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW6		

BE687
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123744**

Well ID:	T0607700702-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700702&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700702&assigned_name=MW-1		

BE688
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000001350**

Well ID:	T0607700508-CMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	CMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700508&assigned_name=CMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700508&assigned_name=CMW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BH689
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000017975**

Well ID:	3910001-004	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 01-25 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-004&store_num=		
GeoTracker Data:	Not Reported		

BG690
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000134936**

Well ID:	T0607700149-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-2		

BG691
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000137056**

Well ID:	T0607700149-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-1		

BA692
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000124934**

Well ID:	T0607700204-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA693
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094934**

Well ID:	T0607700204-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-5		

BF694
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000022909**

Well ID:	SL0607793529-MW-5A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-5A		

BF695
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000102174**

Well ID:	SL0607793529-MW-5B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-5B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-5B		

BI696
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000075845**

Well ID:	T0607700253-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700253&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700253&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BK697
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000139258**

Well ID:	SL0607793529-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-8		

BA698
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000091652**

Well ID:	T0607700204-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-14		

BA699
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000023363**

Well ID:	T0607700204-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-13		

BA700
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000052721**

Well ID:	T0607700204-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA701
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000142788**

Well ID:	T0607700204-VW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=VW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=VW-1		

BG702
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000082583**

Well ID:	T0607700149-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-5		

BG703
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000031886**

Well ID:	T0607700149-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-6		

BG704
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008296**

Well ID:	T0607700149-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BA705
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000122971**

Well ID:	T0607700204-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-18		

BA706
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000124579**

Well ID:	T0607700204-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-19		

BA707
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000121239**

Well ID:	T0607700204-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-4		

BI708
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000106881**

Well ID:	T0607700888-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BF709
NNW
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000050868**

Well ID:	SL0607793529-MW-5C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-5C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-5C		

BA710
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000121771**

Well ID:	T0607700204-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-10		

BA711
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000045586**

Well ID:	T0607700204-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-15		

BE712
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000064379**

Well ID:	T0607700204-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI713
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000131174**

Well ID:	T0607700888-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-3		

BG714
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000049688**

Well ID:	T0607700149-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-7		

715
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000103529**

Well ID:	T0607700204-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700204&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700204&assigned_name=MW-1		

BI716
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000051807**

Well ID:	T0607700888-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI717
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000123202**

Well ID:	T0607700163-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-14		

BG718
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000094476**

Well ID:	T0607700149-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700149&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700149&assigned_name=MW-4		

BI719
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000106131**

Well ID:	T0607700163-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-6		

BI720
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000094348**

Well ID:	T0607700888-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI721
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000140549**

Well ID:	T0607700163-MW-16B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-16B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-16B		

BI722
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000061172**

Well ID:	T0607700163-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-4		

BI723
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000035248**

Well ID:	T0607700163-MW-16A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-16A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-16A		

BI724
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000039958**

Well ID:	T0607700888-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-13		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI725
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000119233**

Well ID:	T0607700163-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-1		

BI726
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000015310**

Well ID:	T0607700888-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-11		

BE727
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065943**

Well ID:	T0607700305-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-7		

BI728
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000014592**

Well ID:	T0607700888-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI729
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000121752**

Well ID:	T0607700163-VW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=VW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=VW-3		

BI730
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000096015**

Well ID:	T0607700163-VW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=VW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=VW-1		

BI731
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000061029**

Well ID:	T0607700163-VW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=VW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=VW-6		

BI732
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008889**

Well ID:	T0607700888-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI733
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000072702**

Well ID:	T0607700163-VW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=VW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=VW-4		

BI734
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000034338**

Well ID:	T0607700163-VW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=VW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=VW-5		

735
ESE
1/2 - 1 Mile
Higher

CA WELLS **CADPR0000000347**

Well ID:	77854	Well Type:	UNK
Source:	Department of Pesticide Regulation		
Other Name:	77854	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DPR&samp_date=&global_id=&assigned_name=77854&store_num=		
GeoTracker Data:	Not Reported		

BE736
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076276**

Well ID:	T0607700305-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI737
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000086455**

Well ID:	T0607700163-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-2		

BI738
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000056090**

Well ID:	T0607700888-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-2		

BI739
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128134**

Well ID:	T0607700163-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-3		

BI740
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000083945**

Well ID:	T0607700163-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BI741
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128970**

Well ID:	T0607700163-MW-17C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-17C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-17C		

BI742
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128481**

Well ID:	T0607700163-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-5		

BI743
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000044896**

Well ID:	T0607700163-MW-13B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-13B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-13B		

BL744
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123155**

Well ID:	T0607700632-MW-3A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-3A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-3A		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
BL745 **South** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CAEDF0000007260**

Well ID:	T0607700632-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-5		

BL746 **South** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CAEDF0000043639**

Well ID:	T0607700632-MW-5A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-5A		

---

747 **East** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CADWR0000037605**

Well ID:	01N06E12F001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12F001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12F001M&store_num=		
GeoTracker Data:	Not Reported		

BI748 **ENE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAEDF0000105512**

Well ID:	T0607700163-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-9		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

749
NNE
1/2 - 1 Mile
Higher

CA WELLS **CADWR9000038023**

State Well #:	01N06E02J002M	Station ID:	4536
Well Name:	Not Reported	Basin Name:	Eastern San Joaquin
Well Use:	Unknown	Well Type:	Unknown
Well Depth:	366	Well Completion Rpt #:	Not Reported

BE750
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000142273**

Well ID:	T0607700305-MW-4
Source:	EDF
GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-4&store_num=
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-4

Well Type:	MONITORING
Other Name:	MW-4

BI751
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000118239**

Well ID:	T0607700888-MW-8
Source:	EDF
GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-8&store_num=
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-8

Well Type:	MONITORING
Other Name:	MW-8

BI752
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000100669**

Well ID:	T0607700888-MW-10
Source:	EDF
GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-10&store_num=
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-10

Well Type:	MONITORING
Other Name:	MW-10

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BM753
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000087974**

Well ID:	T0607700305-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-9		

BM754
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000011978**

Well ID:	T0607700305-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-8		

BE755
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123294**

Well ID:	T0607700305-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-2		

BN756
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186226**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q006M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19540528	Well Depth:	263
Well Depth Units:	ft	Well Hole Depth:	263

Well Hole Depth Units: ft

Ground water levels,Number of Measurements: 1 Level reading date: 1954-05-28
Feet below surface: 52.00 Feet to sea level: Not Reported
Note: Not Reported

BI757
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000024434**

Well ID: T0607700888-MW-7 Well Type: MONITORING
Source: EDF Other Name: MW-7
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-7&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-7

BI758
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008665**

Well ID: T0607700888-MW-9 Well Type: MONITORING
Source: EDF Other Name: MW-9
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700888&assigned_name=MW-9&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700888&assigned_name=MW-9

BL759
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000018501**

Well ID: T0607700632-MW-3 Well Type: MONITORING
Source: EDF Other Name: MW-3
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-3&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-3

BI760
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000032996**

Well ID: T0607700163-MW-8 Well Type: MONITORING
Source: EDF Other Name: MW-8
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-8&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-8

BL761
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097481**

Well ID: T0607700632-MW-4
Well Type: MONITORING
Source: EDF
Other Name: MW-4
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-4&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-4

BO762
WSW
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000033003**

Well ID: 01N06E10Q007M
Well Type: UNK
Source: Department of Water Resources
Other Name: 01N06E10Q007M
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E10Q007M&store_num=
GeoTracker Data: Not Reported

BO763
WSW
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000005448**

Well ID: 01N06E10Q006M
Well Type: UNK
Source: Department of Water Resources
Other Name: 01N06E10Q006M
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E10Q006M&store_num=
GeoTracker Data: Not Reported

BO764
WSW
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000008891**

Well ID: 01N06E10Q009M
Well Type: UNK
Source: Department of Water Resources
Other Name: 01N06E10Q009M
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E10Q009M&store_num=
GeoTracker Data: Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BH765
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000006375**

Well ID:	3910001-003	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 01-24 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-003&store_num=		
GeoTracker Data:	Not Reported		

BN766
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134772**

Well ID:	T10000006482-DMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-3		

BN767
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000087478**

Well ID:	T10000003890-DMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-3		

BH768
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000013477**

Well ID:	3910001-001	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 01-16 - ABANDONED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=3910001-001&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BE769
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000128451**

Well ID:	T0607700305-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-3		

BI770
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000069436**

Well ID:	T0607700163-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-11		

BN771
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000032621**

Well ID:	T10000006482-DMW-5B	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-5B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-5B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-5B		

BL772
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000022074**

Well ID:	T0607700632-MW-2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-2A		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BL773
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063336**

Well ID:	T0607700632-VW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	VW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=VW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=VW-1		

BL774
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000081360**

Well ID:	T0607700632-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-2		

BE775
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000112241**

Well ID:	T0607700305-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-1		

BI776
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000070239**

Well ID:	T0607700163-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-12		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BN777
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000029818**

Well ID:	T10000003890-CPT-13	Well Type:	MONITORING
Source:	EDF	Other Name:	CPT-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=CPT-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=CPT-13		

BN778
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105890**

Well ID:	T10000006482-DMW-5A	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-5A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-5A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-5A		

BP779
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000090017**

Well ID:	T0607700902-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-6		

BL780
South
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000124497**

Well ID:	T0607700632-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700632&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700632&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BN781
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036183**

Well ID:	T10000003890-DMW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-4		

BN782
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000057078**

Well ID:	T10000006482-DMW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-4		

BQ783
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000031591**

Well ID:	01N06E12C011M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C011M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C011M&store_num=		
GeoTracker Data:	Not Reported		

BQ784
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000021460**

Well ID:	01N06E12C004M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C004M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C004M&store_num=		
GeoTracker Data:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BQ785
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000036578**

Well ID:	01N06E12C007M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C007M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C007M&store_num=		
GeoTracker Data:	Not Reported		

BQ786
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000002600**

Well ID:	01N06E12C003M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C003M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C003M&store_num=		
GeoTracker Data:	Not Reported		

BQ787
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000027114**

Well ID:	01N06E12C008M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C008M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C008M&store_num=		
GeoTracker Data:	Not Reported		

BQ788
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000037918**

Well ID:	01N06E12C002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C002M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BQ789
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000005465**

Well ID:	01N06E12C001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C001M&store_num=		
GeoTracker Data:	Not Reported		

BQ790
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000011490**

Well ID:	01N06E12C010M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C010M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C010M&store_num=		
GeoTracker Data:	Not Reported		

BQ791
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000010419**

Well ID:	01N06E12C009M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C009M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C009M&store_num=		
GeoTracker Data:	Not Reported		

BQ792
ENE
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000009197**

Well ID:	01N06E12C012M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	01N06E12C012M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=01N06E12C012M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BP793
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000137346**

Well ID:	T0607700902-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-2		

BI794
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000092253**

Well ID:	T0607700163-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-10		

BM795
SSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000073794**

Well ID:	T0607700305-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700305&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700305&assigned_name=MW-6		

BP796
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089607**

Well ID:	T0607700902-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BJ797
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000186205**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E10Q010M	Type:	Well
Description:	Not Reported	HUC:	18040005
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19790817	Well Depth:	480
Well Depth Units:	ft	Well Hole Depth:	525
Well Hole Depth Units:	ft		

798
East
1/2 - 1 Mile
Higher

CA WELLS **229**

Seq:	229	Prim sta c:	01N/06E-12L01 M
Frds no:	3901045001	County:	39
District:	69	User id:	39C
System no:	3901045	Water type:	G
Source nam:	WELL 01	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	375650.0	Longitude:	1211603.0
Precision:	3	Status:	AR
Comment 1:	2189 E TAYLOR STOCKTON CA 95205	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	3901045	System nam:	Bentley Trailer Court
Hqname:	Not Reported	Address:	Not Reported
City:	Not Reported	State:	Not Reported
Zip:	Not Reported	Zip ext:	Not Reported
Pop serv:	0	Connection:	0
Area serve:	Not Reported		

BP799
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008621**

Well ID:	T0607700902-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BN800
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000055035**

Well ID:	T10000003890-DMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-1		

BN801
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000006698**

Well ID:	T10000006482-DMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-1		

BN802
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051310**

Well ID:	T10000006482-DMW-6B	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-6B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-6B		

BN803
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000081804**

Well ID:	T10000003890-DMW-6B	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-6B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-6B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BN804
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000003892**

Well ID:	T10000003890-DMW-6A	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-6A		

BN805
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088056**

Well ID:	T10000006482-DMW-6A	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-6A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-6A		

BN806
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000069450**

Well ID:	T10000006482-DMW-6WT	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6WT
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000006482&assigned_name=DMW-6WT&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000006482&assigned_name=DMW-6WT		

BN807
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000066851**

Well ID:	T10000003890-DMW-6WT	Well Type:	MONITORING
Source:	EDF	Other Name:	DMW-6WT
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000003890&assigned_name=DMW-6WT&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000003890&assigned_name=DMW-6WT		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BP808
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000096274**

Well ID:	T0607700902-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-4		

BP809
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000070829**

Well ID:	T0607700902-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-7		

BP810
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000127292**

Well ID:	T0607700902-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-5		

BK811
North
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000003884**

Well ID:	SL0607793529-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL0607793529&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL0607793529&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

812
WSW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000080660**

Well ID:	T10000004123-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000004123&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000004123&assigned_name=MW-3		

BP813
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000006485**

Well ID:	T0607700902-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-9		

BP814
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000137752**

Well ID:	T0607700902-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700902&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700902&assigned_name=MW-1		

BR815
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000051049**

Well ID:	T0607700883-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700883&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700883&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

BS816
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000055972**

Well ID:	T0607700163-MW-15C	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-15C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-15C		

BS817
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000039707**

Well ID:	T0607700163-MW-15B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-15B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-15B		

BS818
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000033218**

Well ID:	T0607700163-MW-15A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700163&assigned_name=MW-15A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700163&assigned_name=MW-15A		

BR819
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000125639**

Well ID:	T0607700883-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607700883&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607700883&assigned_name=MW-9		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

820
NNW
1/2 - 1 Mile
Higher | **FED USGS** | **USGS40000186293**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	001N006E02M001M	Type:	Well
Description:	Not Reported	HUC:	18040004
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Central Valley aquifer system		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19540301	Well Depth:	451
Well Depth Units:	ft	Well Hole Depth:	451
Well Hole Depth Units:	ft		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
NNW
1/4 - 1/2 Mile

OIL_GAS **CAOG14000215257**

API #:	0407700560	Well #:	2
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Greenwood	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	06/25/1941		

2
NNW
1/2 - 1 Mile

OIL_GAS **CAOG14000215259**

API #:	0407700562	Well #:	8
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1912

A3
West
1/2 - 1 Mile

OIL_GAS **CAOG14000215264**

API #:	0407700567	Well #:	1
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Stockton	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	01/01/1896		

A4
West
1/2 - 1 Mile

OIL_GAS **CAOG14000215265**

API #:	0407700568	Well #:	3
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1890

Map ID
Direction
Distance

Database EDR ID Number

5
NNE **OIL_GAS** **CAOG14000215276**
1/2 - 1 Mile

API #:	0407720740	Well #:	1
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Greenwood	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	01/01/1893		

6
ESE **OIL_GAS** **CAOG14000215272**
1/2 - 1 Mile

API #:	0407700575	Well #:	6
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1896

7
NNE **OIL_GAS** **CAOG14000215258**
1/2 - 1 Mile

API #:	0407700561	Well #:	4
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1894

8
WNW **OIL_GAS** **CAOG14000215266**
1/2 - 1 Mile

API #:	0407700569	Well #:	7
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1898

Map ID
Direction
Distance

Database EDR ID Number

B9
NNE
1/2 - 1 Mile

OIL_GAS **CAOG14000215273**

API #:	0407720411	Well #:	1
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Stockton	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	03/12/1983		

B10
NNE
1/2 - 1 Mile

OIL_GAS **CAOG14000215275**

API #:	0407720414	Well #:	2
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Stockton	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	08/03/1983		

B11
NNE
1/2 - 1 Mile

OIL_GAS **CAOG14000215274**

API #:	0407720420	Well #:	3
Well Status:	Plugged	Well Type:	Dry Gas
Lease Name:	Stockton	Field Name:	Stockton Gas (ABD)
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	Y
Spud Date:	09/29/1983		

12
NNW
1/2 - 1 Mile

OIL_GAS **CAOG14000215260**

API #:	0407700563	Well #:	10
Well Status:	Plugged	Well Type:	Gas
Lease Name:	Lease by Pacific Gas and Electric Company		
Field Name:	Stockton Gas (ABD)	Area Name:	Any Area
GIS Source:	hud	Confidential Well:	N
Directionally Drilled:	N	Spud Date:	01/01/1889

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
95203	6	2

Federal EPA Radon Zone for SAN JOAQUIN County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SAN JOAQUIN COUNTY, CA

Number of sites tested: 20

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	2.530 pCi/L	90%	10%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	2.050 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX D

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203

Inquiry Number: 6607856.4
August 05, 2021

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

08/05/21

Site Name:	Client Name:
New Life Mens Facility	Condor Earth Technologies, Inc
429 S. San Joaquin Street	188 Frank West Circle
Stockton, CA 95203	Stockton, CA 95206
EDR Inquiry # 6607856.4	Contact: Rebecca Selvage

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Condor Earth Technologies, Inc were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:		*Coordinates:*	
P.O.#	8639	**Latitude:**	37.948629 37° 56' 55" North
Project:	New Life Men s Facility ESA	**Longitude:**	-121.286367 -121° 17' 11" West
		UTM Zone:	Zone 10 North
		UTM X Meters:	650562.82
		UTM Y Meters:	4201500.16
		Elevation:	17.00' above sea level

Maps Provided:

2012
1987
1976
1968
1952
1913

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2012 Source Sheets



Stockton West

7.5-minute, 24000

1987 Source Sheets



Stockton West

7.5-minute, 24000
Aerial Photo Revised 1982

1976 Source Sheets



Stockton West

7.5-minute, 24000
Aerial Photo Revised 1976

1968 Source Sheets



Stockton West

7.5-minute, 24000
Aerial Photo Revised 1967

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1952 Source Sheets



Stockton West

7.5-minute, 24000
Aerial Photo Revised 1949

1913 Source Sheets




Stockton

7.5-minute, 31680

Historical Topo Map

2012



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Stockton West, 2012, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N

Historical Topo Map

1987



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Stockton West, 1987, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N

Historical Topo Map

1976



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Stockton West, 1976, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Stockton West, 1968, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Stockton West, 1952, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N

Historical Topo Map

1913



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Stockton, 1913, 7.5-minute

SITE NAME: New Life Mens Facility
ADDRESS: 429 S. San Joaquin Street
Stockton, CA 95203
CLIENT: Condor Earth Technologies, Inc

N

New Life Mens Facility

429 S. San Joaquin Street

Stockton, CA 95203

Inquiry Number: 6607856.8

August 05, 2021

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

08/05/21

Site Name:

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203
EDR Inquiry # 6607856.8

Client Name:

Condor Earth Technologies, Inc
188 Frank West Circle
Stockton, CA 95206
Contact: Rebecca Selvage

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1998	1"=500'	Acquisition Date: January 01, 1998	USGS/DOQQ
1993	1"=500'	Acquisition Date: May 23, 1993	USGS/DOQQ
1984	1"=500'	Flight Date: June 08, 1984	USDA
1982	1"=500'	Flight Date: June 26, 1982	USDA
1975	1"=500'	Flight Date: November 11, 1975	Cartwright
1968	1"=500'	Flight Date: May 01, 1968	USGS
1963	1"=500'	Flight Date: June 01, 1963	USDA
1957	1"=500'	Flight Date: July 12, 1957	USDA
1940	1"=500'	Flight Date: May 26, 1940	USDA
1937	1"=500'	Flight Date: August 14, 1937	USDA


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 6607856.8
YEAR: 2016
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 2012
= 500'
N
EDR



INQUIRY #: 6607856.8
YEAR: 2009
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1998
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1993
= 500'
N
EDR
Subject boundary not shown because it exceeds image extent or image is not georeferenced.


INQUIRY #: 6607856.8
YEAR: 1984
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1982
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1975
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1968
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1963
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1957
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1940
= 500'
N
EDR


INQUIRY #: 6607856.8
YEAR: 1937
= 500'
N
EDR

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203

Inquiry Number: 6607856.3
August 06, 2021

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

08/06/21

Site Name:

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203
EDR Inquiry # 6607856.3

Client Name:

Condor Earth Technologies, Inc
188 Frank West Circle
Stockton, CA 95206
Contact: Rebecca Selvage

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Condor Earth Technologies, Inc were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # A29E-42DC-8AAA

PO # 8639

Project New Life Men s Facility ESA

Maps Provided:

1972
1950
1917
1895

Sanborn® Library search results

Certification #: A29E-42DC-8AAA

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ✔ Library of Congress
- ✔ University Publications of America
- ✔ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Condor Earth Technologies, Inc (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1972 Source Sheets


Volume 2, Sheet 74


Volume 2, Sheet 75



Volume 2, Sheet 82


Volume 2, Sheet 83


1950 Source Sheets


Volume 1, Sheet xxxx


Volume 2, Sheet 74


Volume 2, Sheet 75


Volume 2, Sheet 82


Volume 2, Sheet 83

1917 Source Sheets


Volume 1, Sheet 75


Volume 1, Sheet xxxx


Volume 1, Sheet 74


Volume 1, Sheet 82

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1917 Source Sheets



Volume 1, Sheet 83

1895 Source Sheets



Volume 1, Sheet 9



Volume 1, Sheet 10



Volume 1, Sheet 18



Volume 1, Sheet 19

Certified Sanborn® Map

1972




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	New Life Mens Facility
Address:	429 S. San Joaquin Street
City, ST, ZIP:	Stockton, CA 95203
Client:	Condor Earth Technologies, Inc
EDR Inquiry:	6607856.3
Order Date:	08/06/2021
Certification #	A29E-42DC-8AAA
Copyright	1972

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 2, Sheet 83
Volume 2, Sheet 82
Volume 2, Sheet 75
Volume 2, Sheet 74

0 Feet 150 300 600


N



Site Name: New Life Mens Facility
Address: 429 S. San Joaquin Street
City, ST, ZIP: Stockton, CA 95203
Client: Condor Earth Technologies, Inc
EDR Inquiry: 6607856.3
Order Date: 08/06/2021
Certification #: A29E-42DC-8AAA
Copyright: 1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 2, Sheet 83
Volume 2, Sheet 82
Volume 2, Sheet 75
Volume 2, Sheet 74
Volume 1, Sheet xxxx

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # A29E-42DC-8AAA

Site Name:	New Life Mens Facility
Address:	429 S. San Joaquin Street
City, ST, ZIP:	Stockton, CA 95203
Client:	Condor Earth Technologies, Inc
EDR Inquiry:	6607856.3
Order Date:	08/06/2021
Certification #	A29E-42DC-8AAA
Copyright	1917

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 83
Volume 1, Sheet 82
Volume 1, Sheet 74
Volume 1, Sheet xxxx
Volume 1, Sheet 75

0 Feet 150 300 600


N



Site Name: New Life Mens Facility
Address: 429 S. San Joaquin Street
City, ST, ZIP: Stockton, CA 95203
Client: Condor Earth Technologies, Inc
EDR Inquiry: 6607856.3
Order Date: 08/06/2021
Certification #: A29E-42DC-8AAA
Copyright: 1895

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 19
Volume 1, Sheet 18
Volume 1, Sheet 10
Volume 1, Sheet 9

0 Feet 150 300 600

N

New Life Mens Facility
429 S. San Joaquin Street
Stockton, CA 95203

Inquiry Number: 6607856.5
August 06, 2021

The EDR-City Directory Abstract

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1906 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 660 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	-	X	X	-
2014	Cole Information Services	X	X	X	-
2009	Cole Information Services	-	X	X	-
2004	Cole Information Services	-	X	X	-
2003	SBC PACIFIC BELL	-	X	X	-
1999	Cole Information Services	-	X	X	-
	R. L. Polk Co., Publishers	-	X	X	X
1996	R. L. Polk Co., Publishers	-	X	X	X
1994	Cole Information Services	-	X	X	-
1990	R. L. Polk Co., Publishers	-	X	X	X

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1990	R. L. Polk Co., Publishers	X	X	X	X
1984	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1979	R.L. Polk CO.	-	X	X	X
	R.L. Polk CO.	X	X	X	X
1975	R.L. Polk CO.	-	X	X	X
	R.L. Polk CO.	X	X	X	X
1970	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1965	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1960	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1955	R. L. Polk Co.	-	X	X	X
	R. L. Polk Co.	X	X	X	X
1950	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1946	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1940	R. L. Polk Co., Publishers	-	X	X	X
	R. L. Polk Co., Publishers	X	X	X	X
1935	R. L. Polk Co. of California, Publishers	-	X	X	X
	R. L. Polk Co. of California, Publishers	X	X	X	X
1930	R. L. Polk Co. of California, Publishers	-	X	X	X
	R. L. Polk Co. of California, Publishers	X	X	X	X
1925	R. L. Polk Co. of California, Publishers	-	X	X	X
	R. L. Polk Co. of California, Publishers	X	X	X	X
1921	Polk-Husted Directory Co., Publishers	-	X	X	X
	Polk-Husted Directory Co., Publishers	X	X	X	X
1916	Polk-Husted Directory Co.	-	X	X	X
	Polk-Husted Directory Co.	X	X	X	X
1911	Polk-Husted Directory	-	X	X	-
	Polk-Husted Directory	X	X	X	-
1906	A. KINGSBURY CO	-	X	X	-
	A. KINGSBURY CO	X	X	X	-

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Brad street. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®

Copyright©2008
All Rights Reserved

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

429 S. San Joaquin Street
Stockton, CA 95203

FINDINGS DETAIL

Target Property research detail.

S SAN JOAQUIN ST

429 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1990	a Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A16
	b Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A16
1979	a Olivos Javier	R.L. Polk CO.	Image pg. A47
	Huante Jenny Mrs	R.L. Polk CO.	Image pg. A47
1975	a Aguilar Dina Mrs	R.L. Polk CO.	Image pg. A57
	Huante Olivias	R.L. Polk CO.	Image pg. A57
1970	a Lee Quong Wee	R. L. Polk Co., Publishers	Image pg. A65
	Gutierrez Seopoldo	R. L. Polk Co., Publishers	Image pg. A65
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1911	Hicklin Agnes stngr W F & Co Exp b	Polk-Husted Directory	
	Hicklin Harlton G b	Polk-Husted Directory	
	Hicklin Mrs Luella ironer Stkn Lndy h	Polk-Husted Directory	
1906	Boyle James F lab r	A. KINGSBURY CO	
	Sunderland Victor emp S E R R r	A. KINGSBURY CO	

SAN JOAQUIN S

429 SAN JOAQUIN S

Year	Uses	Source	
1960	a Villaseno Jessie	R. L. Polk Co., Publishers	Image pg. A82
	Stevenson Ila H Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	a Laperena Peter	R. L. Polk Co.	Image pg. A90

FINDINGS

Year	Uses	Source	
1955	Stevenson Ila H Mrs	R. L. Polk Co.	Image pg. A90
1950	a Sanchez Agnes Mrs	R. L. Polk Co., Publishers	Image pg. A101
	Gresham V E	R. L. Polk Co., Publishers	Image pg. A100
1946	Olechea H L	R. L. Polk Co., Publishers	Image pg. A108
	Warren W E Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
	Pile H A	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
	Partrick Ada Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	a Bennett J A	R. L. Polk Co. of California, Publishers	Image pg. A146
	Pefferling Chas	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Bowers Mrs Barbara	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Hicklin Mrs Llewella	Polk-Husted Directory Co.	Image pg. A166

SAN JOAQUIN ST S

429 SAN JOAQUIN ST S

Year	Uses	Source	
1984	aHuyh Linh Van	R. L. Polk Co., Publishers	Image pg. A25
	b Beltran Francisco J	R. L. Polk Co., Publishers	Image pg. A25
	Lopes Juan	R. L. Polk Co., Publishers	Image pg. A25
1965	A GALEVIZ LEONIDEZ	R. L. Polk Co., Publishers	Image pg. A72
	NO RETURN	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

CHURCH E

116 CHURCH E

Year	Uses	Source	
1960	Ford Bert	R. L. Polk Co., Publishers	Image pg. A83
1955	Kazita Shataro	R. L. Polk Co.	Image pg. A91
1950	Kazita Masau	R. L. Polk Co., Publishers	Image pg. A102
1946	Dean A E	R. L. Polk Co., Publishers	Image pg. A109
1935	Morrello V B	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	King C H	R. L. Polk Co. of California, Publishers	Image pg. A134
	Giometti Wm	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Hamilton Jesse	Polk-Husted Directory Co.	Image pg. A167

118 CHURCH E

Year	Uses	Source	
1960	Lujan Natividad A Mrs	R. L. Polk Co., Publishers	Image pg. A83
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Bacigalupi Jos	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Bacigalupi Jos	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Bacigalupi Jos	Polk-Husted Directory Co.	Image pg. A167

120 CHURCH E

Year	Uses	Source	
1960	Marchi Eugenia Mrs	R. L. Polk Co., Publishers	Image pg. A83
1955	Marchi Jennie Mrs 0	R. L. Polk Co.	Image pg. A91
1950	Marchi Jennie Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	aMarchi Jennie Mrs	R. L. Polk Co., Publishers	Image pg. A109
1935	Mark Jennie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A124

FINDINGS

121 CHURCH E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A83
1955	Gee Doong	R. L. Polk Co.	Image pg. A91
1950	Canette Sixto	R. L. Polk Co., Publishers	Image pg. A102
	Lavon Lorenzo	R. L. Polk Co., Publishers	Image pg. A102
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A109
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Oriental	Polk-Husted Directory Co.	Image pg. A167

122 CHURCH E

Year	Uses	Source	
2003	Syhachack Boua	SBC PACIFIC BELL	
1960	Fed Contrs Inc bldg contr	R. L. Polk Co., Publishers	Image pg. A83
1955	Federal Home Insulation Co	R. L. Polk Co.	Image pg. A91
1950	erstripping	R. L. Polk Co., Publishers	Image pg. A102
	Giometti H J	R. L. Polk Co., Publishers	Image pg. A102
	Giomrnetti H J w eath	R. L. Polk Co., Publishers	Image pg. A102
1946	Wong Philip	R. L. Polk Co., Publishers	Image pg. A109
1935	Wong You	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Mah D S	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Gemignani Nick	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Lungo Frank	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Lungo Frank	Polk-Husted Directory Co.	Image pg. A167

127 CHURCH E

Year	Uses	Source	
1960	Mayayo Frank	R. L. Polk Co., Publishers	Image pg. A83
1955	Mayayo Frank	R. L. Polk Co.	Image pg. A91
1950	AWong H G	R. L. Polk Co., Publishers	Image pg. A102
1946	a Wong H G	R. L. Polk Co., Publishers	Image pg. A109
1935	Jacob Mary Mrs	R. L. Polk Co. of California, Publishers	Image pg. A124

FINDINGS

Year	Uses	Source	
1930	Marchi Eugenia Mrs	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Froglio E R	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Gianelli Frank Jr	Polk-Husted Directory Co.	Image pg. A167

128 CHURCH E

Year	Uses	Source	
1960	Yip Yuk How A	R. L. Polk Co., Publishers	Image pg. A83
1955	Toy You Sun	R. L. Polk Co.	Image pg. A91
1950	Lee Bill	R. L. Polk Co., Publishers	Image pg. A102
1946	Chan Harry	R. L. Polk Co., Publishers	Image pg. A109
1935	Martini Geronimo	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Fugazi Giacomo	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Fuagazi Giacomo	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Kalluchis Gust	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Nadotti Dominic	Polk-Husted Directory Co.	Image pg. A167

130 CHURCH E

Year	Uses	Source	
1960	Tom Tommy	R. L. Polk Co., Publishers	Image pg. A83
1955	Tom Tommy 0	R. L. Polk Co.	Image pg. A91
1950	Tom Tommy	R. L. Polk Co., Publishers	Image pg. A102
1946	Kearney Frances Mrs	R. L. Polk Co., Publishers	Image pg. A109
1935	Fugazi Giacomo	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Woo Hing Jung	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Buccelotto Peter	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Loos T F	Polk-Husted Directory Co.	Image pg. A167

132 CHURCH E

Year	Uses	Source	
2003	Chan Fung Helen	SBC PACIFIC BELL	
1960	Lee Lun You	R. L. Polk Co., Publishers	Image pg. A83
1955	Loo Ben Foo	R. L. Polk Co.	Image pg. A91

FINDINGS

Year	Uses	Source	
1950	Nebres G V	R. L. Polk Co., Publishers	Image pg. A102
1946	Nebres Gerald	R. L. Polk Co., Publishers	Image pg. A109
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Wong Gong	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Spanos Christ	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Holdsworth Thos	Polk-Husted Directory Co.	Image pg. A167

135 CHURCH E

Year	Uses	Source	
1955	Fuji John E	R. L. Polk Co.	Image pg. A91
1950	San Yip Assn Chi	R. L. Polk Co., Publishers	Image pg. A102
	nese	R. L. Polk Co., Publishers	Image pg. A102
1946	San Yap Assn	R. L. Polk Co., Publishers	Image pg. A109
	Chinese	R. L. Polk Co., Publishers	Image pg. A109
1935	nese	R. L. Polk Co. of California, Publishers	Image pg. A124
	San Yap Assn chi	R. L. Polk Co. of California, Publishers	Image pg. A124
	Kong King	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Bertrand Mrs Nellie	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Bertrand Mrs Nellie	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Louis	Polk-Husted Directory Co.	Image pg. A167
	Bertrand Nellie w id	Polk-Husted Directory Co.	Image pg. A167

138 CHURCH E

Year	Uses	Source	
1960	Dawson Wm R	R. L. Polk Co., Publishers	Image pg. A83
	Holdsworth Chas	R. L. Polk Co., Publishers	Image pg. A83
1955	Dawson Wm R	R. L. Polk Co.	Image pg. A91
	Holsworth Chas trucking	R. L. Polk Co.	Image pg. A91
1950	Dawson W R	R. L. Polk Co., Publishers	Image pg. A102
1946	a Dawson W R	R. L. Polk Co., Publishers	Image pg. A109
1935	Zwinge W K o	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Holdsworth Chas	R. L. Polk Co. of California, Publishers	Image pg. A134

FINDINGS

Year	Uses	Source	
1930	Zw inge W M o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Zivinge W M	R. L. Polk Co. of California, Publishers	Image pg. A147
	Holdsw orth Wm	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Holdsw orth Geo	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Holdsw orth Geo	Polk-Husted Directory Co.	Image pg. A167

142 CHURCH E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A83
1955	Toy Tom	R. L. Polk Co.	Image pg. A91
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A109
1935	Woo Hing Jung	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Yen Henry	R. L. Polk Co. of California, Publishers	Image pg. A134

144 CHURCH E

Year	Uses	Source	
1960	Toy Ben T	R. L. Polk Co., Publishers	Image pg. A83
1955	Toy Ben T 0	R. L. Polk Co.	Image pg. A91
1950	Toy B T	R. L. Polk Co., Publishers	Image pg. A102
1946	AToy B T	R. L. Polk Co., Publishers	Image pg. A109
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Yee Frank	R. L. Polk Co. of California, Publishers	Image pg. A134

201 CHURCH E

Year	Uses	Source	
1960	Sheopard J W	R. L. Polk Co., Publishers	Image pg. A83
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Garrone Angelina	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Raffanti Fiora	Polk-Husted Directory Co.	Image pg. A167

202 CHURCH E

Year	Uses	Source	
1960	Lee Bing Lee Keith F	R. L. Polk Co., Publishers	Image pg. A83
1955	Lee Bing	R. L. Polk Co.	Image pg. A91

FINDINGS

Year	Uses	Source	
1950	Lee Bing	R. L. Polk Co., Publishers	Image pg. A102

203 CHURCH E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A83
1935	Raffante Isabelle Mrs	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Raffanti Fiore	R. L. Polk Co. of California, Publishers	Image pg. A134
1916	Mariani Jos	Polk-Husted Directory Co.	Image pg. A167

204 CHURCH E

Year	Uses	Source	
1930	Amestoy Jas	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Yiarras Nicholas	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Amestoz Domingo	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Amistoy Domingo	Polk-Husted Directory Co.	Image pg. A167

205 CHURCH E

Year	Uses	Source	
2003	Garibay Acencion	SBC PACIFIC BELL	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A83
1955	Vacant	R. L. Polk Co.	Image pg. A91
1950	Theuerkauff W L	R. L. Polk Co., Publishers	Image pg. A102
1946	Wong John	R. L. Polk Co., Publishers	Image pg. A109
1935	Marraccini Bruno	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Raffanti Flora	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Rodger Baptiste	Polk-Husted Directory Co.	Image pg. A167

206 CHURCH E

Year	Uses	Source	
2003	Guan Qiu Zhun	SBC PACIFIC BELL	
1960	Tsue Bret	R. L. Polk Co., Publishers	Image pg. A83
1955	Tsue But	R. L. Polk Co.	Image pg. A91
1950	Lee Stanley	R. L. Polk Co., Publishers	Image pg. A102

FINDINGS

207 CHURCH E

Year	Uses	Source	
2003	Garibay Fernandez Pedro	SBC PACIFIC BELL	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A83
1955	Moresco Clarinda Mrs	R. L. Polk Co.	Image pg. A91
1950	Marresco Clorinda Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	Raffanti Fiore	R. L. Polk Co., Publishers	Image pg. A109
	Marracchini Bruno	R. L. Polk Co., Publishers	Image pg. A109
1935	Baffante Fiore o	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Raffanti Fiore	R. L. Polk Co. of California, Publishers	Image pg. A147

208 CHURCH E

Year	Uses	Source	
2003	Huang Lu Nong	SBC PACIFIC BELL	
1960	Nebres Gero V	R. L. Polk Co., Publishers	Image pg. A83
1955	Nebres Gero V	R. L. Polk Co.	Image pg. A91
1950	Wong Richd	R. L. Polk Co., Publishers	Image pg. A102
1946	Lee Fong	R. L. Polk Co., Publishers	Image pg. A109
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Hahn J H	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A157

211 CHURCH E

Year	Uses	Source	
1916	Vacant	Polk-Husted Directory Co.	Image pg. A167

216 CHURCH E

Year	Uses	Source	
1960	Yee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A83
1955	Yee Mary Mrs	R. L. Polk Co.	Image pg. A91
1950	Chin Sing Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	Chin Shew	R. L. Polk Co., Publishers	Image pg. A109
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A124

FINDINGS

Year	Uses	Source	
1930	Goni Anacleto	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Oriental	Polk-Husted Directory Co.	Image pg. A167

218 CHURCH E

Year	Uses	Source	
1916	Vacant	Polk-Husted Directory Co.	Image pg. A167

219 CHURCH E

Year	Uses	Source	
1960	Prater Evelyn W Mrs	R. L. Polk Co., Publishers	Image pg. A83

220 CHURCH E

Year	Uses	Source	
1960	Young Jack	R. L. Polk Co., Publishers	Image pg. A83
1955	Young Jack 0	R. L. Polk Co.	Image pg. A91
1950	Young Jack	R. L. Polk Co., Publishers	Image pg. A102

224 CHURCH E

Year	Uses	Source	
1916	Vacant	Polk-Husted Directory Co.	Image pg. A167

225 CHURCH E

Year	Uses	Source	
1960	Street continued	R. L. Polk Co., Publishers	Image pg. A83
	Jones Bessie M	R. L. Polk Co., Publishers	Image pg. A83
	Melendez Della Mlrs	R. L. Polk Co., Publishers	Image pg. A83
	Apartments	R. L. Polk Co., Publishers	Image pg. A83
	Avarca Jos	R. L. Polk Co., Publishers	Image pg. A83
	Cavera Philo	R. L. Polk Co., Publishers	Image pg. A83
1955	Mestas John	R. L. Polk Co.	Image pg. A91
1950	Pow ell Edw	R. L. Polk Co., Publishers	Image pg. A102
	Martinez John	R. L. Polk Co., Publishers	Image pg. A102
	Larranaga Reginaldo	R. L. Polk Co., Publishers	Image pg. A102
	Flores Abel	R. L. Polk Co., Publishers	Image pg. A102

FINDINGS

Year	Uses	Source	
1946	Gold Jos	R. L. Polk Co., Publishers	Image pg. A109
1935	Tong Yuk	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Tong Yuk	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Henderson J F	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Molen H E	Polk-Husted Directory Co.	Image pg. A167

227 CHURCH E

Year	Uses	Source	
1960	Samuels Ramona V Mrs	R. L. Polk Co., Publishers	Image pg. A83
1955	Samuels Ramona V Mrs	R. L. Polk Co.	Image pg. A91
1950	Echicopar Luisa Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A109

229 CHURCH E

Year	Uses	Source	
2003	Brow n William	SBC PACIFIC BELL	
1960	Ellison Carl L 4 H	R. L. Polk Co., Publishers	Image pg. A83
	Stockton Gospel Center Mission	R. L. Polk Co., Publishers	Image pg. A83
1955	Stockton Gospel Center	R. L. Polk Co.	Image pg. A91
1950	Stockton Gospel Cen	R. L. Polk Co., Publishers	Image pg. A102
	Van Der Beek Ger	R. L. Polk Co., Publishers	Image pg. A102
	hard Rev	R. L. Polk Co., Publishers	Image pg. A102
1946	Etchecopar Peter	R. L. Polk Co., Publishers	Image pg. A109
	Macstas Marcelino	R. L. Polk Co., Publishers	Image pg. A109
1935	Etchecopar Pete restr	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Yip Yuen	R. L. Polk Co. of California, Publishers	Image pg. A134
	Chew Louie	R. L. Polk Co. of California, Publishers	Image pg. A134
1916	2 Cole C F	Polk-Husted Directory Co.	Image pg. A167

230 CHURCH E

Year	Uses	Source	
1960	Auto nody Wks	R. L. Polk Co., Publishers	Image pg. A83
1955	Auto Body Wks	R. L. Polk Co.	Image pg. A91

FINDINGS

Year	Uses	Source	
1950	Beaver Chemical Co	R. L. Polk Co., Publishers	Image pg. A102
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A109
1935	Delivery Co	R. L. Polk Co. of California, Publishers	Image pg. A124
	Independent Dair y	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Delivery	R. L. Polk Co. of California, Publishers	Image pg. A134
	Independenlt Dairy	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Moore L E	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Moore L E	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Smith Mrs E C	Polk-Husted Directory Co.	Image pg. A167

237 CHURCH E

Year	Uses	Source	
1955	Roybal John	R. L. Polk Co.	Image pg. A91
1950	Villescas Michi	R. L. Polk Co., Publishers	Image pg. A102
	San Joaquin intersects	R. L. Polk Co., Publishers	Image pg. A102
	Roybal John	R. L. Polk Co., Publishers	Image pg. A102
1946	Hernandez Julio	R. L. Polk Co., Publishers	Image pg. A109
1935	Shimakaw a Kennajiro	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Tung Woo	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Weber A F W	Polk-Husted Directory Co., Publishers	Image pg. A157
	Matthew s L P	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Weber A F W	Polk-Husted Directory Co.	Image pg. A167
	Matthew s L P	Polk-Husted Directory Co.	Image pg. A167

238 CHURCH E

Year	Uses	Source	
2003	JENE WA H INC	SBC PACIFIC BELL	
1925	Ford J H	R. L. Polk Co. of California, Publishers	Image pg. A147
	Ford Kate	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	8 Ford Mrs S M	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Ford Sarah M w id Peter	Polk-Husted Directory Co.	Image pg. A167

FINDINGS

306 CHURCH E

Year	Uses	Source	
2003	Lazo Victorino	SBC PACIFIC BELL	
1960	Mordegila Jos	R. L. Polk Co., Publishers	Image pg. A83
1955	Vacant	R. L. Polk Co.	Image pg. A91
1950	Mordeglia Jos	R. L. Polk Co., Publishers	Image pg. A102

308 CHURCH E

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A91
1950	Moore L E	R. L. Polk Co., Publishers	Image pg. A102

314 CHURCH E

Year	Uses	Source	
1960	XVong How ard	R. L. Polk Co., Publishers	Image pg. A83
1955	Martinez Jos E	R. L. Polk Co.	Image pg. A91
1950	Chong Wong	R. L. Polk Co., Publishers	Image pg. A102
1946	a Baumgartner H C	R. L. Polk Co., Publishers	Image pg. A109
	Harrison H E	R. L. Polk Co., Publishers	Image pg. A109
1935	Church	R. L. Polk Co. of California, Publishers	Image pg. A124
	Uchii J K Rev	R. L. Polk Co. of California, Publishers	Image pg. A124
	San Joaquin Japanese	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Bennett Lillie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A134
	Trusty J C	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Adams Mrs Kate	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Belluomini Vincent	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	w id G H	Polk-Husted Directory Co.	Image pg. A167
	Campbell Margaret A	Polk-Husted Directory Co.	Image pg. A167
	Prato A G	Polk-Husted Directory Co.	Image pg. A167
	Mazurette Jessie	Polk-Husted Directory Co.	Image pg. A167

315 CHURCH E

Year	Uses	Source	
1960	Parker Earl AH	R. L. Polk Co., Publishers	Image pg. A83
1955	Parker Earl	R. L. Polk Co.	Image pg. A91

FINDINGS

Year	Uses	Source	
1950	Smith J A	R. L. Polk Co., Publishers	Image pg. A102
1946	Urquidi Gavina Mrs	R. L. Polk Co., Publishers	Image pg. A109
1935	French A E	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Hamilton Thos	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Murray Alvin	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Ford L A	Polk-Husted Directory Co., Publishers	Image pg. A157

320 CHURCH E

Year	Uses	Source	
1960	Lew Lee Mrs	R. L. Polk Co., Publishers	Image pg. A83
1955	Lew Paul	R. L. Polk Co.	Image pg. A91
	Lew Yee 0	R. L. Polk Co.	Image pg. A91
1950	Low Yee	R. L. Polk Co., Publishers	Image pg. A102
1946	Low Yee	R. L. Polk Co., Publishers	Image pg. A109
1935	Genecco Gus	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Genecco A F o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Genecco A F	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Genecco A F	Polk-Husted Directory Co., Publishers	Image pg. A157
1916	Genecco A F	Polk-Husted Directory Co.	Image pg. A167

321 CHURCH E

Year	Uses	Source	
2003	Abarca Leovigildo	SBC PACIFIC BELL	
1960	Chan S Harry	R. L. Polk Co., Publishers	Image pg. A83
1955	Chan S Harry 0	R. L. Polk Co.	Image pg. A91
1950	Chin S H	R. L. Polk Co., Publishers	Image pg. A102
1946	George A D Rev	R. L. Polk Co., Publishers	Image pg. A109
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Kell J W	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Brow n C H	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Carder Jas	Polk-Husted Directory Co.	Image pg. A167

FINDINGS

323 CHURCH E

Year	Uses	Source	
2003	Silverio Esteban	SBC PACIFIC BELL	
1960	Mlah Art S	R. L. Polk Co., Publishers	Image pg. A83
1955	Mah Art	R. L. Polk Co.	Image pg. A91

325 CHURCH E

Year	Uses	Source	
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A102
1946	Ramirez P H	R. L. Polk Co., Publishers	Image pg. A109
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Pappas Jos o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Egan J T	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Light Mrs Emily	Polk-Husted Directory Co., Publishers	Image pg. A158
	Gunn W F	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Conklin F L	Polk-Husted Directory Co.	Image pg. A167

328 CHURCH E

Year	Uses	Source	
1960	XVong Chinn Shee Mrs	R. L. Polk Co., Publishers	Image pg. A83
1955	Wong Chinn Shee Mrs	R. L. Polk Co.	Image pg. A91
1950	Wong W M	R. L. Polk Co., Publishers	Image pg. A102
1946	Wong W M	R. L. Polk Co., Publishers	Image pg. A109
1935	Wong Wm	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Boskovich M M	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Boskovich M M	Polk-Husted Directory Co.	Image pg. A167

329 CHURCH E

Year	Uses	Source	
1916	Vacant	Polk-Husted Directory Co.	Image pg. A167

334 CHURCH E

Year	Uses	Source
2003	Gao Yao	SBC PACIFIC BELL

FINDINGS

Year	Uses	Source	
1960	Ricketts Cora M Mirs 0	R. L. Polk Co., Publishers	Image pg. A83
1955	Ricketts Cora M Mrs	R. L. Polk Co.	Image pg. A91
1950	a Ricketts C B	R. L. Polk Co., Publishers	Image pg. A102
1946	ARicketts C B	R. L. Polk Co., Publishers	Image pg. A109
1935	Ricketts C B	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Ricketts C B o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Myers Mrs Alice	R. L. Polk Co. of California, Publishers	Image pg. A147
	Mc Ginnis J H	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Mc Ginnis J H	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Mc Ginnis J H	Polk-Husted Directory Co.	Image pg. A167

335 CHURCH E

Year	Uses	Source	
2003	Li Ben Shang	SBC PACIFIC BELL	
1960	Fong Toy 0	R. L. Polk Co., Publishers	Image pg. A83
1955	Fong Toy	R. L. Polk Co.	Image pg. A91
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A102
1946	Lee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A109
	Law son CM	R. L. Polk Co., Publishers	Image pg. A109
	Jaquez Jose	R. L. Polk Co., Publishers	Image pg. A109
	Ambrioz Ventura	R. L. Polk Co., Publishers	Image pg. A109
1935	Lee A W	R. L. Polk Co. of California, Publishers	Image pg. A124
	Kempbanee Mary Mrs	R. L. Polk Co. of California, Publishers	Image pg. A124
	Gammon F B	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Nourse A H	R. L. Polk Co. of California, Publishers	Image pg. A147
	Shook B F	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	West Wesley	Polk-Husted Directory Co., Publishers	Image pg. A158
	Dillian Mrs L J	Polk-Husted Directory Co., Publishers	Image pg. A158
	Snyder John	Polk-Husted Directory Co., Publishers	Image pg. A158

336 CHURCH E

Year	Uses	Source	
1960	Rodriguez Henry A	R. L. Polk Co., Publishers	Image pg. A83

FINDINGS

Year	Uses	Source	
1955	Adam Annie Mrs	R. L. Polk Co.	Image pg. A91
1950	Guthrey J L	R. L. Polk Co., Publishers	Image pg. A102
1946	AGuthrey J L	R. L. Polk Co., Publishers	Image pg. A109
1935	Lomeye Frank	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Martinez Jos	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Manfredi Chas	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Vacant	Polk-Husted Directory Co.	Image pg. A167

340 CHURCH E

Year	Uses	Source	
1960	Yin Herbert	R. L. Polk Co., Publishers	Image pg. A83
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A109
1935	Villanueva Florencio	R. L. Polk Co. of California, Publishers	Image pg. A124
1925	Violet Henry	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Boland C C	Polk-Husted Directory Co., Publishers	Image pg. A158

342 CHURCH E

Year	Uses	Source	
1960	Wong John	R. L. Polk Co., Publishers	Image pg. A83

343 CHURCH E

Year	Uses	Source	
2003	Lim Pheng	SBC PACIFIC BELL	
1960	Simmons Edw	R. L. Polk Co., Publishers	Image pg. A83
1955	Dong Louie	R. L. Polk Co.	Image pg. A91
1950	Huston D L	R. L. Polk Co., Publishers	Image pg. A102

344 CHURCH E

Year	Uses	Source	
1960	No Return	R. L. Polk Co., Publishers	Image pg. A83

345 CHURCH E

Year	Uses	Source	
1960	Ligid Ralph	R. L. Polk Co., Publishers	Image pg. A83
1955	Davis Cal S	R. L. Polk Co.	Image pg. A91

FINDINGS

Year	Uses	Source	
1950	Lamasney R C	R. L. Polk Co., Publishers	Image pg. A102

346 CHURCH E

Year	Uses	Source	
1960	Lee Will 1	R. L. Polk Co., Publishers	Image pg. A83

347 CHURCH E

Year	Uses	Source	
2003	Garcia David	SBC PACIFIC BELL	
1960	Lekos Louis S	R. L. Polk Co., Publishers	Image pg. A83
1955	Lekos Louis S 0	R. L. Polk Co.	Image pg. A91
1950	Willard J B	R. L. Polk Co., Publishers	Image pg. A102

349 CHURCH E

Year	Uses	Source	
1960	Wong Show Hap	R. L. Polk Co., Publishers	Image pg. A83
1955	Rackley Shade 0	R. L. Polk Co.	Image pg. A91
1950	Brown C J	R. L. Polk Co., Publishers	Image pg. A102

405 CHURCH E

Year	Uses	Source	
1930	Cantele T M o	R. L. Polk Co. of California, Publishers	Image pg. A134
	Crabb C M	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Dangers Carl	R. L. Polk Co. of California, Publishers	Image pg. A147
	Lea Mrs Mamie	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Dangers Carl	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Dangers Carl	Polk-Husted Directory Co.	Image pg. A167

410 CHURCH E

Year	Uses	Source	
1960	Paapke Ervin F	R. L. Polk Co., Publishers	Image pg. A83
1955	Prather Wm C	R. L. Polk Co.	Image pg. A91
1950	Durand H W	R. L. Polk Co., Publishers	Image pg. A102
1946	Durand H W	R. L. Polk Co., Publishers	Image pg. A109
1935	Durand H W o	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134

Year	Uses	Source	
1925	Eickhoff Albt W	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Eickhoff A W	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Behan Jas Jr	Polk-Husted Directory Co.	Image pg. A167

411 CHURCH E

Year	Uses	Source	
2003	Sandoval Juan	SBC PACIFIC BELL	
1960	Doty Katy L Mrs 4 AH	R. L. Polk Co., Publishers	Image pg. A83
	la La Barre Thos	R. L. Polk Co., Publishers	Image pg. A83
	b Cardenas Vicente Ml	R. L. Polk Co., Publishers	Image pg. A83
1955	Griffin Wm F	R. L. Polk Co.	Image pg. A91
	La Barre Thos	R. L. Polk Co.	Image pg. A91
1950	La Barre Thos	R. L. Polk Co., Publishers	Image pg. A102
	Bradbury Josie Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	a Mayer Geo	R. L. Polk Co., Publishers	Image pg. A109
1935	Tremayne J W	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Trefry H E Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Trefry Mrs H E	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Trefry Mrs H E	Polk-Husted Directory Co., Publishers	Image pg. A158
	Pairman John	Polk-Husted Directory Co., Publishers	Image pg. A158
	Lieginger Kate	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Trefrey Helen w id A P	Polk-Husted Directory Co.	Image pg. A167
	Merkle E F	Polk-Husted Directory Co.	Image pg. A167

412 CHURCH E

Year	Uses	Source	
1960	Ollarzabal Rugio	R. L. Polk Co., Publishers	Image pg. A83
1955	Tavella Anthony	R. L. Polk Co.	Image pg. A91
1950	Callison Leona Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	ACallison C R	R. L. Polk Co., Publishers	Image pg. A109
1935	Johnson F E	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Schimmelpfenig Ger	R. L. Polk Co. of California, Publishers	Image pg. A134
	trude Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Schimmelpfenig F W	R. L. Polk Co. of California, Publishers	Image pg. A147

Year	Uses	Source	
1921	Schimelpfennig F W	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Schimmelpfennig F W	Polk-Husted Directory Co.	Image pg. A167

420 CHURCH E

Year	Uses	Source	
1960	z Bradbury Josie H Mrs	R. L. Polk Co., Publishers	Image pg. A83
	Fernandez Hortensia C	R. L. Polk Co., Publishers	Image pg. A83
1955	Ternandez Hortensia C	R. L. Polk Co.	Image pg. A91
1950	Formby Donald	R. L. Polk Co., Publishers	Image pg. A102
	Munns C W	R. L. Polk Co., Publishers	Image pg. A102
1946	Anderson W C	R. L. Polk Co., Publishers	Image pg. A109
	Helmick L	R. L. Polk Co., Publishers	Image pg. A109
1935	Hoffpauir L S	R. L. Polk Co. of California, Publishers	Image pg. A124
	Posey Gladys Mrs	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
	Lieginger Kate	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Dangers Juanita	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	1/2 Jow itt Geo	Polk-Husted Directory Co., Publishers	Image pg. A158
	Beecher A H	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Clay Antonio	Polk-Husted Directory Co.	Image pg. A167

421 CHURCH E

Year	Uses	Source	
1960	Miow Lyman 0	R. L. Polk Co., Publishers	Image pg. A83
1955	Mow Lyman 0	R. L. Polk Co.	Image pg. A91
1950	Mow Lyman	R. L. Polk Co., Publishers	Image pg. A102
1946	Mow Lyman	R. L. Polk Co., Publishers	Image pg. A109
1935	Harkins J P	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Harkins J P o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Harkins J P	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Harkins J P	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Harkins J P	Polk-Husted Directory Co.	Image pg. A167

FINDINGS

422 CHURCH E

Year	Uses	Source	
1960	Stern Julia B Mrs	R. L. Polk Co., Publishers	Image pg. A83
	CHURCH E Contd	R. L. Polk Co., Publishers	Image pg. A84
1955	Stern Julia B Mrs	R. L. Polk Co.	Image pg. A91
1950	Anderson J A	R. L. Polk Co., Publishers	Image pg. A102
	Stern Dale	R. L. Polk Co., Publishers	Image pg. A102
1946	Harris Artie Mrs	R. L. Polk Co., Publishers	Image pg. A109
	Holcome L M	R. L. Polk Co., Publishers	Image pg. A109
1935	Henderson E	R. L. Polk Co. of California, Publishers	Image pg. A124
	Modlin Kenneth	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Marx Emil o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Marx E R	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Guyon Paul	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Putnam F B	Polk-Husted Directory Co.	Image pg. A167
	Morrill Harriet w id F C	Polk-Husted Directory Co.	Image pg. A167

424 CHURCH E

Year	Uses	Source	
1960	Andrama Sam	R. L. Polk Co., Publishers	Image pg. A84
1955	Moreno Gregoria L Mrs	R. L. Polk Co.	Image pg. A91
1950	Helmich L	R. L. Polk Co., Publishers	Image pg. A102
1946	Gale A R	R. L. Polk Co., Publishers	Image pg. A109
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Pendleton Bertha	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Freeman T P	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Freeman T P	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Lynde G	Polk-Husted Directory Co.	Image pg. A167
	Freeman T P	Polk-Husted Directory Co.	Image pg. A167

426 CHURCH E

Year	Uses	Source	
1960	Lee Wing	R. L. Polk Co., Publishers	Image pg. A84
1955	Lee Wing H 0	R. L. Polk Co.	Image pg. A91
1950	Lee W H	R. L. Polk Co., Publishers	Image pg. A102

FINDINGS

427 CHURCH E

Year	Uses	Source	
2003	Siu Kam H	SBC PACIFIC BELL	
1960	Chow Ngit	R. L. Polk Co., Publishers	Image pg. A84
1955	Chow Ngit 0	R. L. Polk Co.	Image pg. A91
1950	Fisher R L	R. L. Polk Co., Publishers	Image pg. A102
	Chong San tir	R. L. Polk Co., Publishers	Image pg. A102
1946	Mah Nee Seung	R. L. Polk Co., Publishers	Image pg. A109
1935	Harkins H W	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Harkins M A Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Harkins Mrs M A	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Harkins John	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Harkins John	Polk-Husted Directory Co.	Image pg. A167

433 CHURCH E

Year	Uses	Source	
1960	Madrid Lupe	R. L. Polk Co., Publishers	Image pg. A84
1955	Gianelli Dominick	R. L. Polk Co.	Image pg. A91
1950	Miramontes F R	R. L. Polk Co., Publishers	Image pg. A102
1946	AComaskey W L	R. L. Polk Co., Publishers	Image pg. A109

435 CHURCH E

Year	Uses	Source	
1960	Norton Pearl E Mrs	R. L. Polk Co., Publishers	Image pg. A84
1955	Lerach Robt L	R. L. Polk Co.	Image pg. A91
1950	Lerach Riobt	R. L. Polk Co., Publishers	Image pg. A102
1946	Gianelli D W	R. L. Polk Co., Publishers	Image pg. A109

437 CHURCH E

Year	Uses	Source	
1960	Gianelli Amelia L 0	R. L. Polk Co., Publishers	Image pg. A84
1950	Gianelli D W	R. L. Polk Co., Publishers	Image pg. A102
1946	Knudsen R N	R. L. Polk Co., Publishers	Image pg. A109

439 CHURCH E

Year	Uses	Source	
1960	Edwards Lorna Mrs	R. L. Polk Co., Publishers	Image pg. A84
1955	Norton Pearl Mrs	R. L. Polk Co.	Image pg. A91
1950	Killingen Lenora	R. L. Polk Co., Publishers	Image pg. A102
	Gianelli Amielia Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	Foss Cath	R. L. Polk Co., Publishers	Image pg. A109

443 CHURCH E

Year	Uses	Source	
1960	Corona Louise Mrs	R. L. Polk Co., Publishers	Image pg. A84
1955	Livingston Nellie Mrs	R. L. Polk Co.	Image pg. A91
1950	Livingston Nellie Mrs	R. L. Polk Co., Publishers	Image pg. A102
1946	Livingston Nellie Mrs	R. L. Polk Co., Publishers	Image pg. A109
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A124
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A134
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A147
1921	Vistica Louis	Polk-Husted Directory Co., Publishers	Image pg. A158
	Mc Carthy Wm	Polk-Husted Directory Co., Publishers	Image pg. A158
1916	Mc Carty Wm	Polk-Husted Directory Co.	Image pg. A167

CHURCH ST E

116 CHURCH ST E

Year	Uses	Source	
1984	Reyes Hilario Mrs	R. L. Polk Co., Publishers	Image pg. A26
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A73

118 CHURCH ST E

Year	Uses	Source	
1984	Gerolaga Denise	R. L. Polk Co., Publishers	Image pg. A26
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A73

120 CHURCH ST E

Year	Uses	Source	
1984	Reed Mary	R. L. Polk Co., Publishers	Image pg. A26

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A73

122 CHURCH ST E

Year	Uses	Source	
1984	Godina C	R. L. Polk Co., Publishers	Image pg. A26
1965	BLDG CONTRS H	R. L. Polk Co., Publishers	Image pg. A73
	FEDERAL CONTRACTORS INC	R. L. Polk Co., Publishers	Image pg. A73

127 CHURCH ST E

Year	Uses	Source	
1984	Perez Jose	R. L. Polk Co., Publishers	Image pg. A26
	E CUBCH ST Contd	R. L. Polk Co., Publishers	Image pg. A27
1965	FEDERAL CONTRACTORS INC	R. L. Polk Co., Publishers	Image pg. A73
	MODEL HOME	R. L. Polk Co., Publishers	Image pg. A73

128 CHURCH ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A27

130 CHURCH ST E

Year	Uses	Source	
1984	Chan Helen F	R. L. Polk Co., Publishers	Image pg. A27
1965	YIN HERBERT Y H	R. L. Polk Co., Publishers	Image pg. A73

132 CHURCH ST E

Year	Uses	Source	
1984	Fung Helen	R. L. Polk Co., Publishers	Image pg. A27
1965	YIP CHOY	R. L. Polk Co., Publishers	Image pg. A73

138 CHURCH ST E

Year	Uses	Source	
1984	Medrano	R. L. Polk Co., Publishers	Image pg. A27
1965	DAWSON W R 0 H	R. L. Polk Co., Publishers	Image pg. A73
	DAWSON WM R 0 H	R. L. Polk Co., Publishers	Image pg. A73

FINDINGS

142 CHURCH ST E

Year	Uses	Source	
1984	Yi P Suey Ouon	R. L. Polk Co., Publishers	Image pg. A27
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A73

144 CHURCH ST E

Year	Uses	Source	
1984	Yip King Sun	R. L. Polk Co., Publishers	Image pg. A27
1965	TOY BEN T a H	R. L. Polk Co., Publishers	Image pg. A73

201 CHURCH ST E

Year	Uses	Source	
1965	REDOL PAT	R. L. Polk Co., Publishers	Image pg. A73

202 CHURCH ST E

Year	Uses	Source	
1984	Lee Ng Sim Mrs	R. L. Polk Co., Publishers	Image pg. A27
1965	LEE BING 0 H	R. L. Polk Co., Publishers	Image pg. A73

203 CHURCH ST E

Year	Uses	Source	
1984	Cabero Nick	R. L. Polk Co., Publishers	Image pg. A27
1965	SARMIENTO MAX	R. L. Polk Co., Publishers	Image pg. A73

205 CHURCH ST E

Year	Uses	Source	
1984	Cabero Teofilo	R. L. Polk Co., Publishers	Image pg. A27
1965	SALOMA J S	R. L. Polk Co., Publishers	Image pg. A73

206 CHURCH ST E

Year	Uses	Source	
1984	Jong Kw ock H	R. L. Polk Co., Publishers	Image pg. A27
1965	JONG KWOCK HEE H	R. L. Polk Co., Publishers	Image pg. A73

207 CHURCH ST E

Year	Uses	Source	
1984	Bell Karen	R. L. Polk Co., Publishers	Image pg. A27
1965	CAND DANL	R. L. Polk Co., Publishers	Image pg. A73

FINDINGS

208 CHURCH ST E

Year	Uses	Source	
1984	Huie Kai	R. L. Polk Co., Publishers	Image pg. A27
1965	SOON LEE QUOCK H	R. L. Polk Co., Publishers	Image pg. A73

216 CHURCH ST E

Year	Uses	Source	
1984	Yee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A27
1965	YEE MARY MRS S H	R. L. Polk Co., Publishers	Image pg. A73

220 CHURCH ST E

Year	Uses	Source	
1984	Young Jack G	R. L. Polk Co., Publishers	Image pg. A27
1965	YOUNG JACK 0 H	R. L. Polk Co., Publishers	Image pg. A73

225 CHURCH ST E

Year	Uses	Source	
1965	HERNANDEZ SALVADORE	R. L. Polk Co., Publishers	Image pg. A73

227 CHURCH ST E

Year	Uses	Source	
1965	MAESTAS JOHN H	R. L. Polk Co., Publishers	Image pg. A73

229 CHURCH ST E

Year	Uses	Source	
1984	Porteous James P	R. L. Polk Co., Publishers	Image pg. A27
	Stockton Gospel Rescue Mission w elfare center	R. L. Polk Co., Publishers	Image pg. A27
1965	STOCKTON GOSPEL CENTER	R. L. Polk Co., Publishers	Image pg. A73
	MISSION WELFARE CENTER	R. L. Polk Co., Publishers	Image pg. A73
	ELLISON CARL L H	R. L. Polk Co., Publishers	Image pg. A73

230 CHURCH ST E

Year	Uses	Source	
1984	Reynosas Auto Body Works	R. L. Polk Co., Publishers	Image pg. A27
1965	AUTO BODY WORKS H	R. L. Polk Co., Publishers	Image pg. A73

FINDINGS

246 CHURCH ST E

Year	Uses	Source	
1984	Stockton Donor Center blood bk	R. L. Polk Co., Publishers	Image pg. A27

272 CHURCH ST E

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A74

306 CHURCH ST E

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A27
1965	MORDEGLIA JOSEPH	R. L. Polk Co., Publishers	Image pg. A75

314 CHURCH ST E

Year	Uses	Source	
1984	Lau Kw an Heeung	R. L. Polk Co., Publishers	Image pg. A27
1965	WONG HOWARD H 0 H	R. L. Polk Co., Publishers	Image pg. A75

320 CHURCH ST E

Year	Uses	Source	
1984	bAganon Romero	R. L. Polk Co., Publishers	Image pg. A27
	aBofljoc E	R. L. Polk Co., Publishers	Image pg. A27
1965	LEW LEE MRS 0 H	R. L. Polk Co., Publishers	Image pg. A75

321 CHURCH ST E

Year	Uses	Source	
1984	Nasser Othman	R. L. Polk Co., Publishers	Image pg. A27
1965	CHAN HARRY S 0 H	R. L. Polk Co., Publishers	Image pg. A75

323 CHURCH ST E

Year	Uses	Source	
1984	Mah Art S	R. L. Polk Co., Publishers	Image pg. A27
1965	MAH ART S 0 H	R. L. Polk Co., Publishers	Image pg. A75

328 CHURCH ST E

Year	Uses	Source	
1984	Lee Frank N	R. L. Polk Co., Publishers	Image pg. A27
1965	LEE FRANK 0 H	R. L. Polk Co., Publishers	Image pg. A75

FINDINGS

334 CHURCH ST E

Year	Uses	Source	
1984	Chin Jin	R. L. Polk Co., Publishers	Image pg. A27
1965	RICKETTS CORA M MRS	R. L. Polk Co., Publishers	Image pg. A75

335 CHURCH ST E

Year	Uses	Source	
1984	Louie Wing Ham	R. L. Polk Co., Publishers	Image pg. A27
1965	FONG TOY 0 H	R. L. Polk Co., Publishers	Image pg. A75

336 CHURCH ST E

Year	Uses	Source	
1984	Lam Lin Yeung	R. L. Polk Co., Publishers	Image pg. A27
1965	JUNG JUNG C	R. L. Polk Co., Publishers	Image pg. A75

340 CHURCH ST E

Year	Uses	Source	
1984	Guzmnan Jose D	R. L. Polk Co., Publishers	Image pg. A27
1965	GEE SING	R. L. Polk Co., Publishers	Image pg. A75

342 CHURCH ST E

Year	Uses	Source	
1984	Jacob Nemesio	R. L. Polk Co., Publishers	Image pg. A27

343 CHURCH ST E

Year	Uses	Source	
1984	Tien Tang D	R. L. Polk Co., Publishers	Image pg. A27

344 CHURCH ST E

Year	Uses	Source	
1984	Benedicto Mark	R. L. Polk Co., Publishers	Image pg. A27
1965	ROMONO LORENZO	R. L. Polk Co., Publishers	Image pg. A75

345 CHURCH ST E

Year	Uses	Source	
1984	Wallace Sanmmie	R. L. Polk Co., Publishers	Image pg. A27
1965	AKERS LULA MRS	R. L. Polk Co., Publishers	Image pg. A75

FINDINGS

346 CHURCH ST E

Year	Uses	Source	
1984	Besarra Andy	R. L. Polk Co., Publishers	Image pg. A27
1965	LEE WM	R. L. Polk Co., Publishers	Image pg. A75

347 CHURCH ST E

Year	Uses	Source	
1984	Garcia David W	R. L. Polk Co., Publishers	Image pg. A27
1965	LEKOS LOUt S S 0 H	R. L. Polk Co., Publishers	Image pg. A75

349 CHURCH ST E

Year	Uses	Source	
1984	Overton Win L	R. L. Polk Co., Publishers	Image pg. A27
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A75

402 CHURCH ST E

Year	Uses	Source	
1984	Ng Chum Wing	R. L. Polk Co., Publishers	Image pg. A27

404 CHURCH ST E

Year	Uses	Source	
1984	Lee Nelson W	R. L. Polk Co., Publishers	Image pg. A27

406 CHURCH ST E

Year	Uses	Source	
1984	Ly Binh	R. L. Polk Co., Publishers	Image pg. A27

408 CHURCH ST E

Year	Uses	Source	
1984	Norberte Bernard	R. L. Polk Co., Publishers	Image pg. A27

410 CHURCH ST E

Year	Uses	Source	
1984	Rivera Vincente C	R. L. Polk Co., Publishers	Image pg. A27
1965	RODRIQUEZ HENRY	R. L. Polk Co., Publishers	Image pg. A75

FINDINGS

411 CHURCH ST E

Year	Uses	Source	
1984	a Ramirez Camarillo	R. L. Polk Co., Publishers	Image pg. A27
	No Return	R. L. Polk Co., Publishers	Image pg. A27
	b Perez Patricia	R. L. Polk Co., Publishers	Image pg. A27
1965	MITCHELL MALINDA MRS	R. L. Polk Co., Publishers	Image pg. A75
	A LA BARRE THOS	R. L. Polk Co., Publishers	Image pg. A75

412 CHURCH ST E

Year	Uses	Source	
1984	Ollarzabal Refugio G	R. L. Polk Co., Publishers	Image pg. A27
1965	OLLARZABAL REFUGID	R. L. Polk Co., Publishers	Image pg. A75

420 CHURCH ST E

Year	Uses	Source	
1984	Ortega Josephine M	R. L. Polk Co., Publishers	Image pg. A27
	Markado Simm	R. L. Polk Co., Publishers	Image pg. A27
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A75
	VACANT	R. L. Polk Co., Publishers	Image pg. A75

421 CHURCH ST E

Year	Uses	Source	
1984	Mow Danl	R. L. Polk Co., Publishers	Image pg. A27
1965	MOW LYMAN a H	R. L. Polk Co., Publishers	Image pg. A75

422 CHURCH ST E

Year	Uses	Source	
1984	Nunez Fernando	R. L. Polk Co., Publishers	Image pg. A27
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A75

424 CHURCH ST E

Year	Uses	Source	
1984	Huant Rose	R. L. Polk Co., Publishers	Image pg. A27
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A75

FINDINGS

426 CHURCH ST E

Year	Uses	Source	
1984	Lee Alf	R. L. Polk Co., Publishers	Image pg. A27
1965	LEE WING H 0 H	R. L. Polk Co., Publishers	Image pg. A75

427 CHURCH ST E

Year	Uses	Source	
1984	Siu Shee C	R. L. Polk Co., Publishers	Image pg. A27
1965	SAN CHONG 0 H	R. L. Polk Co., Publishers	Image pg. A75

433 CHURCH ST E

Year	Uses	Source	
1984	Monares J A	R. L. Polk Co., Publishers	Image pg. A27
1965	BRUMMETT BARBARA A	R. L. Polk Co., Publishers	Image pg. A75

435 CHURCH ST E

Year	Uses	Source	
1984	Reyes Arturo H	R. L. Polk Co., Publishers	Image pg. A27
1965	MORELLO JOE	R. L. Polk Co., Publishers	Image pg. A75

437 CHURCH ST E

Year	Uses	Source	
1984	Quarta Maria	R. L. Polk Co., Publishers	Image pg. A27
1965	HART JANE MRS	R. L. Polk Co., Publishers	Image pg. A75

439 CHURCH ST E

Year	Uses	Source	
1984	Brrions Rosario	R. L. Polk Co., Publishers	Image pg. A27
1965	ROBBINS BEN	R. L. Polk Co., Publishers	Image pg. A75

443 CHURCH ST E

Year	Uses	Source	
1984	Gante Pedro	R. L. Polk Co., Publishers	Image pg. A27
1965	RAMOS VIDAL	R. L. Polk Co., Publishers	Image pg. A75

FINDINGS

E CHURCH ST

116 E CHURCH ST

Year	Uses	Source	
2017	LARRY GIACOVONI	Cole Information Services	
2014	ROSEMARY GOMEZ	Cole Information Services	
2009	ROSEMARY MARTINEZ	Cole Information Services	
2004	AMANDO PALACIO	Cole Information Services	
1994	GONZALEZ, FABIAN	Cole Information Services	
1990	Gonzales Fabian	R. L. Polk Co., Publishers	Image pg. A17
1979	Reyes Hilario Mrs	R.L. Polk CO.	Image pg. A48
1975	Reyes Hilario Mrs	R.L. Polk CO.	Image pg. A58
1970	Reyes Hilario	R. L. Polk Co., Publishers	Image pg. A66
1940	Kajita Shotaro	R. L. Polk Co., Publishers	Image pg. A116
1911	Hamilton Jesse farmer h	Polk-Husted Directory	
	Hamilton Grant farmer b	Polk-Husted Directory	

118 E CHURCH ST

Year	Uses	Source	
2017	ARMANDO PALACIO	Cole Information Services	
2004	YER HER	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Syhachack Boua	R. L. Polk Co., Publishers	Image pg. A1
1990	Murillo Javier	R. L. Polk Co., Publishers	Image pg. A17
1979	Garca Marie	R.L. Polk CO.	Image pg. A48
1975	Ramirez Narciso J	R.L. Polk CO.	Image pg. A58
1970	No Return	R. L. Polk Co., Publishers	Image pg. A66

120 E CHURCH ST

Year	Uses	Source	
2009	SUSAN PHILL	Cole Information Services	
2004	RUBEN OLIVAS	Cole Information Services	
1999	SUSAN PHILL	Cole Information Services	
1990	Osano Alfredo	R. L. Polk Co., Publishers	Image pg. A17
1979	Reed Mary	R.L. Polk CO.	Image pg. A48

FINDINGS

Year	Uses	Source	
1975	Reid Mary Mrs	R.L. Polk CO.	Image pg. A58
1970	Perez Enrique	R. L. Polk Co., Publishers	Image pg. A66
1940	Marchl Jennie Mrs	R. L. Polk Co., Publishers	Image pg. A116

121 E CHURCH ST

Year	Uses	Source	
1940	Matea A J	R. L. Polk Co., Publishers	Image pg. A116
1911	Aldecoa Aurora w id Antone h	Polk-Husted Directory	
	Aldecoa Lolita cashr Joe Gianelli Co b	Polk-Husted Directory	
	Aldecoa Manuelita E stngr Webster & Webster b	Polk-Husted Directory	
1906	New ell Asa R bartndr r	A. KINGSBURY CO	
	New ell Geo W w ell borer r	A. KINGSBURY CO	
	New ell John A fireman S F D r	A. KINGSBURY CO	
	New ell Mamie E Miss opr S T & T Co r	A. KINGSBURY CO	
	New ell Nellie Miss opr S T & T Co r	A. KINGSBURY CO	
	New ell Robert r	A. KINGSBURY CO	
	New ell Victor clk Eastern B House r	A. KINGSBURY CO	

122 E CHURCH ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	SUSAN CAMPBELL-HILL	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	SCHAFFER SUESS & BOYD REALTORS BETR HOMES & GARDE	Cole Information Services	
1990	Gonzales Concha R	R. L. Polk Co., Publishers	Image pg. A17
1979	Godina C Co farm labor contr	R.L. Polk CO.	Image pg. A48
1975	Martinez Amador Co	R.L. Polk CO.	Image pg. A58
1970	Federal Contractors Inc bldg contrs	R. L. Polk Co., Publishers	Image pg. A66
1940	Wong Philip	R. L. Polk Co., Publishers	Image pg. A116
1911	Lungo Frank barber h	Polk-Husted Directory	
	Loos Wm F lab b	Polk-Husted Directory	
	Loos Thos F lab City St Dept h	Polk-Husted Directory	

FINDINGS

125 E CHURCH ST

Year	Uses	Source	
1999	NEWS SENTINEL LODI	Cole Information Services	
	LODI NEWS SENTINEL	Cole Information Services	

127 E CHURCH ST

Year	Uses	Source	
2017	CLAUDIO ABARCA	Cole Information Services	
2014	LEOVIGILDO ABARCA	Cole Information Services	
2009	RUBEN OLIVAS	Cole Information Services	
2004	JEAN OCHOA	Cole Information Services	
1999	RUBEN OLIVAS	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A1
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A17
1979	Vacant	R.L. Polk CO.	Image pg. A48
1975	Mexican American Chamber Of Commerce	R.L. Polk CO.	Image pg. A58
1970	Jones Paul K	R. L. Polk Co., Publishers	Image pg. A66
1940	Fujimoto Yutsuma	R. L. Polk Co., Publishers	Image pg. A116
1911	Gianelli Frank sew er inspr City Supt Streets h	Polk-Husted Directory	
	Gianelli Frank Jr bottler C A Ziemer b	Polk-Husted Directory	
	Gianelli Marvaret clkl Hales b	Polk-Husted Directory	
	Gianelli Ralph clk J S Silva b	Polk-Husted Directory	
1906	Gianelli Frank emp Wagner Meat Co r	A. KINGSBURY CO	
	Gianelli Frank D sew er inspector r	A. KINGSBURY CO	

128 E CHURCH ST

Year	Uses	Source	
1990	Cline Beauty Shop	R. L. Polk Co., Publishers	Image pg. A17
1979	Funt Helen	R.L. Polk CO.	Image pg. A48
	Chan Helen F	R.L. Polk CO.	Image pg. A48
1975	Chan Johnson T	R.L. Polk CO.	Image pg. A58
1970	Tom Billy Y	R. L. Polk Co., Publishers	Image pg. A66
1940	Enriquez Agraciano	R. L. Polk Co., Publishers	Image pg. A116
1911	Nadotti Dominllick scavenger h	Polk-Husted Directory	

Year	Uses	Source	
1906	Mulcahy James bricklayer r	A. KINGSBURY CO	
	Mulcahy Matthew tillerman Truck No l r	A. KINGSBURY CO	
	Mulcahy Patrick lab r	A. KINGSBURY CO	
	Mulcahy Thos lab r	A. KINGSBURY CO	
	Mulcahy Timothy lab r	A. KINGSBURY CO	

130 E CHURCH ST

Year	Uses	Source	
2017	JESUS JACOBO	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2004	ELIN SALON	Cole Information Services	
	VICKIE CHAN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Chan Helen F	R. L. Polk Co., Publishers	Image pg. A1
1990	No Return	R. L. Polk Co., Publishers	Image pg. A17
1979	Vacant	R.L. Polk CO.	Image pg. A48
1975	Yip Shey	R.L. Polk CO.	Image pg. A58
1970	Cchan Lee Foo	R. L. Polk Co., Publishers	Image pg. A66
1940	Is OFugazi Giacomo	R. L. Polk Co., Publishers	Image pg. A116

132 E CHURCH ST

Year	Uses	Source	
2009	HELEN CHAN	Cole Information Services	
2004	HELEN CHANFUNG	Cole Information Services	
1999	HELEN CHAN	Cole Information Services	
	1 Fung Helen	R. L. Polk Co., Publishers	Image pg. A1
1996	Chantung Helen	R. L. Polk Co., Publishers	Image pg. A9
1994	CHAN, FUNG H	Cole Information Services	
1990	Chan Helen	R. L. Polk Co., Publishers	Image pg. A17
1979	Kong Clay K	R.L. Polk CO.	Image pg. A48
1975	Clay Kong	R.L. Polk CO.	Image pg. A58
1970	Yip Choy	R. L. Polk Co., Publishers	Image pg. A66
1940	Ursainqui P P	R. L. Polk Co., Publishers	Image pg. A116

FINDINGS

135 E CHURCH ST

Year	Uses	Source	
1940	San Yap Assn	R. L. Polk Co., Publishers	Image pg. A116
	Chinese	R. L. Polk Co., Publishers	Image pg. A116
1911	Bertrand Chas F A C clk Hales b	Polk-Husted Directory	
	Ridley Jos expmn r	Polk-Husted Directory	
	Bertrand Ellen w id Louis h	Polk-Husted Directory	
1906	Bertrand Chas F clk Hale & Co r	A. KINGSBURY CO	
	Bertrand Louis tailor r	A. KINGSBURY CO	

138 E CHURCH ST

Year	Uses	Source	
2009	DEVIN KELISH	Cole Information Services	
	GORDON JONES	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	GORDON JONES	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	DEVIN KELISH	Cole Information Services	
1996	Bounlem Malych	R. L. Polk Co., Publishers	Image pg. A9
1990	Yang Fong	R. L. Polk Co., Publishers	Image pg. A17
1979	Vacant	R.L. Polk CO.	Image pg. A48
1975	Vacant	R.L. Polk CO.	Image pg. A58
1970	Dawson Wm R	R. L. Polk Co., Publishers	Image pg. A66
1940	a Zwinge S I Mrs	R. L. Polk Co., Publishers	Image pg. A116
1911	Holdsworth Chas tmstr b	Polk-Husted Directory	
	Holdsworth Edw lab b	Polk-Husted Directory	
	Holdsworth Geo tmstr h	Polk-Husted Directory	
	Holdsworth Thos b	Polk-Husted Directory	
	Holdsworth Wm pilot b	Polk-Husted Directory	
1906	Holdsworth Chas teamster r	A. KINGSBURY CO	
	Holdsworth Edward well borer r	A. KINGSBURY CO	
	Holdsworth Geo teamster r	A. KINGSBURY CO	
	Holdsworth S Irene Miss r	A. KINGSBURY CO	
	Holdsworth Thos mate str J D Peters r	A. KINGSBURY CO	

FINDINGS

Year	Uses	Source	
1906	Holdsworth Wm capt str A C Freese r	A. KINGSBURY CO	

142 E CHURCH ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1999	Koulyoth Cheng	R. L. Polk Co., Publishers	Image pg. A1
1990	Yip Suey Ouon	R. L. Polk Co., Publishers	Image pg. A17
1979	Yep Suey Ouon	R.L. Polk CO.	Image pg. A48
1975	Toy Patk	R.L. Polk CO.	Image pg. A58
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A66
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A116

144 E CHURCH ST

Year	Uses	Source	
2009	BK LASALLE	Cole Information Services	
2004	EARL THOMAS	Cole Information Services	
1999	BK LASALLE	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A1
1990	Yip King Sun	R. L. Polk Co., Publishers	Image pg. A17
1979	Yep King Sun	R.L. Polk CO.	Image pg. A48
1975	Toy Ben T	R.L. Polk CO.	Image pg. A58
1970	Toy Ben T	R. L. Polk Co., Publishers	Image pg. A66
1940	Chinese	R. L. Polk Co., Publishers	Image pg. A116
	Vacant	R. L. Polk Co., Publishers	Image pg. A116

148 E CHURCH ST

Year	Uses	Source
1911	Taylor A A & Son A A and A P planing mill	Polk-Husted Directory

201 E CHURCH ST

Year	Uses	Source	
2017	INDALECIO JOACHIN	Cole Information Services	
2014	INDALECIO JOACHIN	Cole Information Services	
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A66

FINDINGS

202 E CHURCH ST

Year	Uses	Source	
2017	COREY LEE	Cole Information Services	
2014	COREY LEE	Cole Information Services	
2009	COREY LEE	Cole Information Services	
2004	COREY LEE	Cole Information Services	
1999	COREY LEE	Cole Information Services	
1990	Lee Ng Sim Mrs	R. L. Polk Co., Publishers	Image pg. A17
1979	Lee Ng Sim Mrs	R.L. Polk CO.	Image pg. A48
1975	Lee Ng Sim Mrs	R.L. Polk CO.	Image pg. A58
1970	Lee Ng Sim Mrs	R. L. Polk Co., Publishers	Image pg. A66

203 E CHURCH ST

Year	Uses	Source	
2017	ESTHER CAMACHO	Cole Information Services	
2014	JOSE ORTIZ	Cole Information Services	
2004	HECTOR GARIBAY	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A1
1996	Preciado Tanisha	R. L. Polk Co., Publishers	Image pg. A9
1979	Sacramento	R.L. Polk CO.	Image pg. A48
1975	Vacant	R.L. Polk CO.	Image pg. A58
1970	Rascon Herbert	R. L. Polk Co., Publishers	Image pg. A66

204 E CHURCH ST

Year	Uses	Source
1911	Amestoy Domingo sheep raiser h	Polk-Husted Directory
	Amestoy Mary L clk Henry Greenberg b	Polk-Husted Directory

205 E CHURCH ST

Year	Uses	Source
2017	AQUILEO MEJIA	Cole Information Services
2014	AQUILEO MEJIA	Cole Information Services
2009	AQUILEO MEJIA	Cole Information Services
2004	A ARCELIA	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	AQUILEO MEJIA	Cole Information Services	
	b Garibay Acencion	R. L. Polk Co., Publishers	Image pg. A1
1990	No Return	R. L. Polk Co., Publishers	Image pg. A17
1979	Cabero Teofilo	R.L. Polk CO.	Image pg. A48
1975	Cabero Teofilo	R.L. Polk CO.	Image pg. A58
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A66
1940	Oriental	R. L. Polk Co., Publishers	Image pg. A116

206 E CHURCH ST

Year	Uses	Source	
2017	QIU GUAN	Cole Information Services	
2014	QIU GUAN	Cole Information Services	
2009	QIU GUAN	Cole Information Services	
2004	QIU GUAN	Cole Information Services	
1999	QIU GUAN	Cole Information Services	
1990	Baco Fred	R. L. Polk Co., Publishers	Image pg. A17
1979	Jong Kw ock H	R.L. Polk CO.	Image pg. A48
1975	Jong Kw ock H	R.L. Polk CO.	Image pg. A58
1970	Jong Kw ock Hee H	R. L. Polk Co., Publishers	Image pg. A66

207 E CHURCH ST

Year	Uses	Source	
2014	CASTILLO GARIBAY	Cole Information Services	
2009	PEDRO GARIBAY FERNANDEZ	Cole Information Services	
2004	PEDRO FERNANDEZ	Cole Information Services	
1999	PFernandez Pedro	R. L. Polk Co., Publishers	Image pg. A1
1990	Cabero Phil	R. L. Polk Co., Publishers	Image pg. A17
1979	No Return	R.L. Polk CO.	Image pg. A48
1975	Rabanal Sam R	R.L. Polk CO.	Image pg. A58
1970	Vales James T	R. L. Polk Co., Publishers	Image pg. A66
1940	Raffanti Fiore	R. L. Polk Co., Publishers	Image pg. A116

FINDINGS

208 E CHURCH ST

Year	Uses	Source	
2014	LU HUANG	Cole Information Services	
2009	LU HUANG	Cole Information Services	
2004	LU HUANG	Cole Information Services	
1999	LU HUANG	Cole Information Services	
	Hui Yiu C	R. L. Polk Co., Publishers	Image pg. A1
	E CHURCH ST	R. L. Polk Co., Publishers	Image pg. A2
1996	Hui Yiu C	R. L. Polk Co., Publishers	Image pg. A9
1994	HUI, YIU C	Cole Information Services	
1990	Hyi Yiu Cheung	R. L. Polk Co., Publishers	Image pg. A17
1979	Huie Kai	R.L. Polk CO.	Image pg. A48
1975	Huie Kai	R.L. Polk CO.	Image pg. A58
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A66
1940	Lee Fong	R. L. Polk Co., Publishers	Image pg. A116
1911	Miller Chas R h	Polk-Husted Directory	
1906	Jacobs Hyman clothing	A. KINGSBURY CO	
	r	A. KINGSBURY CO	

216 E CHURCH ST

Year	Uses	Source	
2014	ESTHER ALMENDAREZ	Cole Information Services	
2009	ESTHER ALMENDAREZ	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	ESTHER ALMENDAREZ	Cole Information Services	
	Bautista Pablo	R. L. Polk Co., Publishers	Image pg. A2
1996	BO MAH FACTORY	R. L. Polk Co., Publishers	Image pg. A9
1994	MAH, BO	Cole Information Services	
	EURY, THO	Cole Information Services	
1990	Chan Pat Tailoring	R. L. Polk Co., Publishers	Image pg. A17
	Chew Pain Kylin	R. L. Polk Co., Publishers	Image pg. A17
1979	Yee Mary Mrs	R.L. Polk CO.	Image pg. A48
1975	Yee Mary Mrs	R.L. Polk CO.	Image pg. A58

FINDINGS

Year	Uses	Source	
1970	Yee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A66
1940	Chin Sing	R. L. Polk Co., Publishers	Image pg. A116
1911	Bone Meshak tapper Stkn Water Co h	Polk-Husted Directory	
1906	Bone Mesach emp S Water Co r	A. KINGSBURY CO	

218 E CHURCH ST

Year	Uses	Source
1911	Hulen Delmer elec P T & T Co b	Polk-Husted Directory
	Hulen Eva stngr b	Polk-Husted Directory
	Hul en Grace milliner The Sterling b	Polk-Husted Directory
	Hulen Mrs Hattie h	Polk-Husted Directory
1906	Cow ell Myron mason r	A. KINGSBURY CO

220 E CHURCH ST

Year	Uses	Source	
2017	GORDON YOUNG	Cole Information Services	
2014	GORDON YOUNG	Cole Information Services	
1999	Young Carol G & Joanne	R. L. Polk Co., Publishers	Image pg. A2
1990	Young Constance Mrs	R. L. Polk Co., Publishers	Image pg. A17
1979	Young Jack G	R.L. Polk CO.	Image pg. A48
1975	Young Jack	R.L. Polk CO.	Image pg. A58
1970	Young Jack	R. L. Polk Co., Publishers	Image pg. A66

224 E CHURCH ST

Year	Uses	Source
1911	Emmett Mrs Ellen h	Polk-Husted Directory
	Emmett John J lab b	Polk-Husted Directory
	Emmett Roy appr C C Russell b	Polk-Husted Directory
	Emmett Wm H lab b	Polk-Husted Directory
1906	Curry Jay H tinsmith r	A. KINGSBURY CO

225 E CHURCH ST

Year	Uses	Source	
1970	Caberro Phil	R. L. Polk Co., Publishers	Image pg. A66
	Caridad Anicito	R. L. Polk Co., Publishers	Image pg. A66

Year	Uses	Source	
1970	Escalona Saml	R. L. Polk Co., Publishers	Image pg. A66
	Wong Leng	R. L. Polk Co., Publishers	Image pg. A66
	Apartments	R. L. Polk Co., Publishers	Image pg. A66
1940	Gold Jos	R. L. Polk Co., Publishers	Image pg. A116
1911	Caviglio Albert w indow clnr h	Polk-Husted Directory	
	Contrucci Angelo lab h	Polk-Husted Directory	
1906	Serrano Sarah Miss r	A. KINGSBURY CO	
	Aldecoa Lolica Miss r	A. KINGSBURY CO	
	Aldecoa Aurora Mrs r	A. KINGSBURY CO	

226 E CHURCH ST

Year	Uses	Source
1906	Vinelli Chas P bartndr J P Bauman r	A. KINGSBURY CO

227 E CHURCH ST

Year	Uses	Source	
1970	Maestas David	R. L. Polk Co., Publishers	Image pg. A66
1940	Wong H G	R. L. Polk Co., Publishers	Image pg. A116

228 E CHURCH ST

Year	Uses	Source
1906	Ford Edw D emp J Gianelli r	A. KINGSBURY CO

229 E CHURCH ST

Year	Uses	Source	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	GOSPEL CENTER RESCUE MISSION GOSPEL RESCUE MISSION	Cole Information Services	
	Brow n William	R. L. Polk Co., Publishers	Image pg. A2
1996	Brow n Ada	R. L. Polk Co., Publishers	Image pg. A9
	Brow n William	R. L. Polk Co., Publishers	Image pg. A9
1990	Porteous James P	R. L. Polk Co., Publishers	Image pg. A17
	Gospel Center Inc religious org	R. L. Polk Co., Publishers	Image pg. A17
1979	Porteous James	R.L. Polk CO.	Image pg. A48
	Stockton Gospel Rescue Mission w elfare center	R.L. Polk CO.	Image pg. A48

FINDINGS

Year	Uses	Source	
1975	Ellison Carl L	R.L. Polk CO.	Image pg. A58
	Stockton Gospel Rescue Mission w elfare center	R.L. Polk CO.	Image pg. A58
1970	Ellison Carl L	R. L. Polk Co., Publishers	Image pg. A66
	Stockton Gospel Center Mission w elfare center	R. L. Polk Co., Publishers	Image pg. A66
1940	A Maestas Marcelino	R. L. Polk Co., Publishers	Image pg. A116
	Etchecopar Peter	R. L. Polk Co., Publishers	Image pg. A116
1911	Smith Marshall D Pioneer Milk Co h	Polk-Husted Directory	
	Pioneer Milk Co M D Smith	Polk-Husted Directory	
	Eastman Miralda E w id S E b	Polk-Husted Directory	
1906	Helm Chas W horse trainer r	A. KINGSBURY CO	

230 E CHURCH ST

Year	Uses	Source	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1999	REYNOSA AUTO BODY WORKS	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A2
1996	REYNOSA AUTO BODY WORKS	R. L. Polk Co., Publishers	Image pg. A9
1994	REYNOSA AUTO BODY WORKS	Cole Information Services	
1990	Reynosas Auto Body Works	R. L. Polk Co., Publishers	Image pg. A17
1979	Reynosas Auto Body Works	R.L. Polk CO.	Image pg. A48
1975	Reynosas Auto Body Works	R.L. Polk CO.	Image pg. A58
1970	Reynosas Auto Body Works	R. L. Polk Co., Publishers	Image pg. A66
1940	Moore L E milk dir	R. L. Polk Co., Publishers	Image pg. A116
1911	Thompson Wm R capt Dixon Bros r	Polk-Husted Directory	
	Moore Roger launchmn Wm Colberg b	Polk-Husted Directory	
	Moore Law rence eng Wm Colberg b	Polk-Husted Directory	
	Moore rs Ellen C h	Polk-Husted Directory	
1906	Eldridge Dudley D emp Ruhl Goodell Co r	A. KINGSBURY CO	
	Cunningham Otis emp Globe Iron Works r	A. KINGSBURY CO	
	Cunningham Floyd emp New ton & King r	A. KINGSBURY CO	

FINDINGS

237 E CHURCH ST

Year	Uses	Source	
1940	Knshida T T	R. L. Polk Co., Publishers	Image pg. A116
	Chinese	R. L. Polk Co., Publishers	Image pg. A116
1911	Weber Aug F WX mach Globe Iron Wiks h	Polk-Husted Directory	
1906	Field John H w ell borer r	A. KINGSBURY CO	
	Weber August F W emp Globe Iron Works r	A. KINGSBURY CO	

238 E CHURCH ST

Year	Uses	Source
2017	JENE WA H INC	Cole Information Services
2014	JENE WA H INC	Cole Information Services
2009	JENE WA H INC	Cole Information Services
1911	Ford Edw J dept mngr Joe Gianelli Co b	Polk-Husted Directory
	Ford Jas H sales mngr Joe Gianelli Co b	Polk-Husted Directory
	Ford Kate opr P T & T Co b	Polk-Husted Directory
	Ford Mrs Sarah M h	Polk-Husted Directory
1906	Ford Catherine Miss opr S T & T Co r	A. KINGSBURY CO
	Ford James H emp J Gianelli r	A. KINGSBURY CO
	Ford Sarah H Mrs r	A. KINGSBURY CO

246 E CHURCH ST

Year	Uses	Source	
1999	+S SAN JOAQUIN ST	R. L. Polk Co., Publishers	Image pg. A2
	BAYER CORP hlth alld svcs	R. L. Polk Co., Publishers	Image pg. A2
1994	MILES INC STOCKTON PLASMA CTR	Cole Information Services	
1990	Stockton Plasma Center blood bank	R. L. Polk Co., Publishers	Image pg. A17
1979	Stockton Donor Center blood bk	R.L. Polk CO.	Image pg. A48
1975	Stockton Donor Center blood bk	R.L. Polk CO.	Image pg. A58

257 E CHURCH ST

Year	Uses	Source
2004	DOMINIC WEATHERFORD	Cole Information Services

FINDINGS

306 E CHURCH ST

Year	Uses	Source	
2014	VICTORINO LAZO	Cole Information Services	
	RODOLFO MIETIAM	Cole Information Services	
2009	VICTORINO LAZO	Cole Information Services	
2004	VICTORINO LAZO	Cole Information Services	
1999	VICTORINO LAZO	Cole Information Services	
	JSanchez Esperanza	R. L. Polk Co., Publishers	Image pg. A2
1979	No Return	R.L. Polk CO.	Image pg. A48
1975	Singson Basilio C	R.L. Polk CO.	Image pg. A58
1970	Mordeglia Joseph	R. L. Polk Co., Publishers	Image pg. A66

314 E CHURCH ST

Year	Uses	Source	
2004	MAY LAU	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	t Leunglau Kw an	R. L. Polk Co., Publishers	Image pg. A17
1979	Wong How ard H	R.L. Polk CO.	Image pg. A48
1975	Wong How ard H	R.L. Polk CO.	Image pg. A58
1970	Wong How ard H	R. L. Polk Co., Publishers	Image pg. A66
1940	Yen Henry	R. L. Polk Co., Publishers	Image pg. A116
1911	Snell Wm H h	Polk-Husted Directory	
1906	Moon Benj bartndr The Chicago r	A. KINGSBURY CO	
	Mazurette Albert J draftsman Entr Plng Mills r	A. KINGSBURY CO	
	Masurette Odelon r	A. KINGSBURY CO	
	Masurette Albert architect Morrill & Cow ell r	A. KINGSBURY CO	
	Higdon Clarence B painter r	A. KINGSBURY CO	

315 E CHURCH ST

Year	Uses	Source	
1940	Padon W M	R. L. Polk Co., Publishers	Image pg. A116
1911	Campbell Margaret w id G H h	Polk-Husted Directory	

FINDINGS

317 E CHURCH ST

Year	Uses	Source	
2014	GARRY MEIDINGER	Cole Information Services	

320 E CHURCH ST

Year	Uses	Source	
2017	MARCELO VERNAL	Cole Information Services	
2014	MARCELO VERNAL	Cole Information Services	
2009	LEOVIGILDO ABARCA	Cole Information Services	
2004	ANDRES ORTIZ	Cole Information Services	
	JORGE DUENAS	Cole Information Services	
1999	LEOVIGILDO ABARCA	Cole Information Services	
	Avila Trena	R. L. Polk Co., Publishers	Image pg. A2
1996	Bennett Trina	R. L. Polk Co., Publishers	Image pg. A9
1990	b Larot Genaro	R. L. Polk Co., Publishers	Image pg. A17
	a Li Ping	R. L. Polk Co., Publishers	Image pg. A17
1979	bPearson Patric	R.L. Polk CO.	Image pg. A48
	Vacant	R.L. Polk CO.	Image pg. A48
1975	Dabalos Nick D	R.L. Polk CO.	Image pg. A58
1970	Lew Paul	R. L. Polk Co., Publishers	Image pg. A66
1940	Lew Yee	R. L. Polk Co., Publishers	Image pg. A116
1911	Genecco Aug F Genecco & Trucco h	Polk-Husted Directory	
1906	Cunningham John emp Stockton Trans Co r	A. KINGSBURY CO	
	Foote Marie Miss r	A. KINGSBURY CO	
	Hood Philip L printer S Independent r	A. KINGSBURY CO	

321 E CHURCH ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	LEOVIGILDO ABARCA	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A2
1996	Prado Maria	R. L. Polk Co., Publishers	Image pg. A9
1990	Prado Francisco	R. L. Polk Co., Publishers	Image pg. A17

FINDINGS

Year	Uses	Source	
1979	Chan Jimmy	R.L. Polk CO.	Image pg. A48
1975	Chan Jimmy	R.L. Polk CO.	Image pg. A58
1970	Chan Jimmy	R. L. Polk Co., Publishers	Image pg. A66
1911	Richardson John E lino opr The Independent b	Polk-Husted Directory	
	oall Florence P tchr Tackson Sch b	Polk-Husted Directory	
	Craw ford Harold D salsn Hammond J & W h	Polk-Husted Directory	
1906	BLACK JAMES W rubber stamps and supplies	A. KINGSBURY CO	
	r	A. KINGSBURY CO	

323 E CHURCH ST

Year	Uses	Source	
2014	GILBERT LOPEZ	Cole Information Services	
2009	ESTEBAN SILVERIO	Cole Information Services	
2004	MAXIMO PICHAY	Cole Information Services	
1999	ESTEBAN SILVERIO	Cole Information Services	
	Abarca Leovigildo	R. L. Polk Co., Publishers	Image pg. A2
1994	XIONG, LOU L	Cole Information Services	
1990	Mahe Kettle W	R. L. Polk Co., Publishers	Image pg. A17
1979	Mah Art S	R.L. Polk CO.	Image pg. A48
1975	Mah Art S	R.L. Polk CO.	Image pg. A58
1970	Mah Art S	R. L. Polk Co., Publishers	Image pg. A66

325 E CHURCH ST

Year	Uses	Source	
1999	CROWN MIRROR DOORS	R. L. Polk Co., Publishers	Image pg. A2
1940	Monies Paul	R. L. Polk Co., Publishers	Image pg. A116
1911	Conklin Fred L chemist Union Mills h	Polk-Husted Directory	
	Conklin Chester W salsn Daniels Doolittle Co b	Polk-Husted Directory	
1906	Conklin James E bkkpr r	A. KINGSBURY CO	
	Conklin Fredk L miller Sperry Flour Co r	A. KINGSBURY CO	
	Conklin Chester W r	A. KINGSBURY CO	

FINDINGS

328 E CHURCH ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	FRANK LEE	Cole Information Services	
2004	FRANK LEE	Cole Information Services	
1999	FRANK LEE	Cole Information Services	
	Lee Frank N	R. L. Polk Co., Publishers	Image pg. A2
1990	Lee Frank N	R. L. Polk Co., Publishers	Image pg. A17
	Lee Twi	R. L. Polk Co., Publishers	Image pg. A17
1979	No Return	R.L. Polk CO.	Image pg. A48
1975	Lee Frank	R.L. Polk CO.	Image pg. A58
1970	Lee Frank	R. L. Polk Co., Publishers	Image pg. A66
1940	a Wong Wm	R. L. Polk Co., Publishers	Image pg. A116
1911	Dozier Wm G trav frt and pass agt S Fe Ry h	Polk-Husted Directory	
1906	Woods Melvin emp Stoctkon Milling Co r	A. KINGSBURY CO	
	Woods Richard r	A. KINGSBURY CO	

329 E CHURCH ST

Year	Uses	Source
1911	Meyers Florence h	Polk-Husted Directory
	Dunn John clk h	Polk-Husted Directory
	Dunn Arthur M clk W W Bloom h	Polk-Husted Directory
	Moore Mary A h	Polk-Husted Directory

334 E CHURCH ST

Year	Uses	Source	
2014	YANLING ZHONG	Cole Information Services	
2009	YANLING ZHONG	Cole Information Services	
2004	QUAN GAO	Cole Information Services	
1999	YANLING ZHONG	Cole Information Services	
	Gao Yao	R. L. Polk Co., Publishers	Image pg. A2
	Gao Ouan Y	R. L. Polk Co., Publishers	Image pg. A2
1996	Gao Yao	R. L. Polk Co., Publishers	Image pg. A9
1990	Chin Koon	R. L. Polk Co., Publishers	Image pg. A17

FINDINGS

Year	Uses	Source	
1979	Chan Kom Yin	R.L. Polk CO.	Image pg. A48
1975	Chan Kom Yin	R.L. Polk CO.	Image pg. A58
1970	Chan Kom Yin	R. L. Polk Co., Publishers	Image pg. A66
1940	Ricketts C B	R. L. Polk Co., Publishers	Image pg. A116
1911	Myers Alice A w id J H b	Polk-Husted Directory	
	Mc Ginnis John H stage mngr Garrick Theatre h	Polk-Husted Directory	
1906	Agee Wm M agt S S Mach Co r	A. KINGSBURY CO	
	Agee Geo C r	A. KINGSBURY CO	
	Agee Roy emp Hew itts Bazaar r	A. KINGSBURY CO	

335 E CHURCH ST

Year	Uses	Source	
2017	LEE LOUIE	Cole Information Services	
2014	BEN LI	Cole Information Services	
2009	BEN LI	Cole Information Services	
2004	BEN LI	Cole Information Services	
1999	BEN LI	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	Louie Wing	R. L. Polk Co., Publishers	Image pg. A2
1996	Louie Wing H	R. L. Polk Co., Publishers	Image pg. A9
1994	LOUIE, WING H	Cole Information Services	
1990	Louie Soong	R. L. Polk Co., Publishers	Image pg. A17
1979	Lcuie Wing Har	R.L. Polk CO.	Image pg. A48
1975	Banh Kyxuong	R.L. Polk CO.	Image pg. A58
1970	Wong Ging B	R. L. Polk Co., Publishers	Image pg. A66
1940	Jaquez Jose	R. L. Polk Co., Publishers	Image pg. A116
	Alameda Adriano	R. L. Polk Co., Publishers	Image pg. A116
	Lee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A116

336 E CHURCH ST

Year	Uses	Source
2017	WEIYE LIN	Cole Information Services
2014	FEN WONG	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	FEN WONG	Cole Information Services	
2004	FEN WONG	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	FEN WONG	Cole Information Services	
1994	HEUANGVILAY, S	Cole Information Services	
1990	Lam Lin Yeung	R. L. Polk Co., Publishers	Image pg. A17
1979	Yeung Lam Lin Mrs	R.L. Polk CO.	Image pg. A48
1975	Chin Jin	R.L. Polk CO.	Image pg. A58
1970	Bermoy Marciano B	R. L. Polk Co., Publishers	Image pg. A66
1940	Holmes C R Rev	R. L. Polk Co., Publishers	Image pg. A116
1911	Black Geo H dep Sheriff h	Polk-Husted Directory	
1906	Black John J r	A. KINGSBURY CO	
	Black Geo H Dep Sheriff r	A. KINGSBURY CO	

340 E CHURCH ST

Year	Uses	Source	
2017	JOSE RODRIGUEZ	Cole Information Services	
2014	JOSE RODRIGUEZ	Cole Information Services	
2009	JOSE RODRIGUEZ	Cole Information Services	
2004	JEANETTE KUDROW	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Vang Uyoua	R. L. Polk Co., Publishers	Image pg. A2
	Thao Phia	R. L. Polk Co., Publishers	Image pg. A2
1996	Vang Choua	R. L. Polk Co., Publishers	Image pg. A9
1994	VANG, CHOUA	Cole Information Services	
1990	Yang Cha Lee	R. L. Polk Co., Publishers	Image pg. A17
1979	Guzman Jose D	R.L. Polk CO.	Image pg. A48
1975	De Gusman Jose	R.L. Polk CO.	Image pg. A58
1970	Pecolan Bennigno	R. L. Polk Co., Publishers	Image pg. A66
1940	Lee Mary Mrs	R. L. Polk Co., Publishers	Image pg. A116
	Chavez Alice Mrs	R. L. Polk Co., Publishers	Image pg. A116
1911	Irvin Isaiah T lab S Fe Ry h	Polk-Husted Directory	
1906	Gray Terrel L eng r	A. KINGSBURY CO	

FINDINGS

342 E CHURCH ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	ANGELA DILLION	Cole Information Services	
1999	ANGELA DILLION	Cole Information Services	
	DHer Yong	R. L. Polk Co., Publishers	Image pg. A2
1990	Yang Bet	R. L. Polk Co., Publishers	Image pg. A17
1979	Jacob Nemesio	R.L. Polk CO.	Image pg. A48
1975	Jacob Nemesio	R.L. Polk CO.	Image pg. A58
1970	Jacob Nemesio	R. L. Polk Co., Publishers	Image pg. A66

343 E CHURCH ST

Year	Uses	Source	
2014	DANETTA BYRD	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
	DANETTA BYRD	Cole Information Services	
1999	DANETTA BYRD	Cole Information Services	
	Lim Pheng	R. L. Polk Co., Publishers	Image pg. A2
1996	Lim Pheng	R. L. Polk Co., Publishers	Image pg. A9
1994	LIM, PHENG	Cole Information Services	
1990	Lim Pang	R. L. Polk Co., Publishers	Image pg. A17
1979	Steeles Jerry	R.L. Polk CO.	Image pg. A48
1975	Lekos Louis S	R.L. Polk CO.	Image pg. A58
1970	Pesaras Andres R	R. L. Polk Co., Publishers	Image pg. A66

344 E CHURCH ST

Year	Uses	Source	
2009	JESS OLNEY	Cole Information Services	
1999	JESS OLNEY	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1996	Vang Chong	R. L. Polk Co., Publishers	Image pg. A9
1994	VANG, CHONG	Cole Information Services	
1990	Lee Xiong L	R. L. Polk Co., Publishers	Image pg. A17
1979	Abundo Julian	R.L. Polk CO.	Image pg. A48
1975	Asuncion Mucuerro	R.L. Polk CO.	Image pg. A58

FINDINGS

Year	Uses	Source	
1970	Asuncion Mucuerro	R. L. Polk Co., Publishers	Image pg. A66

345 E CHURCH ST

Year	Uses	Source	
2014	PEDRO HERNANDEZ	Cole Information Services	
2009	PEDRO HERNANDEZ	Cole Information Services	
1999	PEDRO HERNANDEZ	Cole Information Services	
1990	Sovern Pan	R. L. Polk Co., Publishers	Image pg. A17
1979	Wallace Sammy	R.L. Polk CO.	Image pg. A48
1975	Ardesota Louie	R.L. Polk CO.	Image pg. A58
1970	Jumaoas Bart	R. L. Polk Co., Publishers	Image pg. A66

346 E CHURCH ST

Year	Uses	Source	
2017	UBALDO ENCARNACION	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Vang Sai Sec	R. L. Polk Co., Publishers	Image pg. A17
1979	Besarra Andy	R.L. Polk CO.	Image pg. A48
1970	Besarra Andy R	R. L. Polk Co., Publishers	Image pg. A66

347 E CHURCH ST

Year	Uses	Source	
2017	DAVID GARCIA	Cole Information Services	
2014	DAVID GARCIA	Cole Information Services	
2009	DAVID GARCIA	Cole Information Services	
2004	DAVID GARCIA	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A17
1979	Garcia David W	R.L. Polk CO.	Image pg. A48
1975	No Return	R.L. Polk CO.	Image pg. A58
1970	Lekos Louis S	R. L. Polk Co., Publishers	Image pg. A66

FINDINGS

349 E CHURCH ST

Year	Uses	Source	
2017	APOLINAR ROSAS	Cole Information Services	
2014	PAULINA SANDOVAL	Cole Information Services	
2009	DEMETRIO CHAVELA	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	DEMETRIO CHAVELA	Cole Information Services	
1990	Overton Wm L	R. L. Polk Co., Publishers	Image pg. A17
1979	Dunbar Albert	R.L. Polk CO.	Image pg. A48
1975	Overton Wm L	R.L. Polk CO.	Image pg. A58
1970	Dunbar Albert	R. L. Polk Co., Publishers	Image pg. A66

360 E CHURCH ST

Year	Uses	Source
1906	Greene Albert J atty	A. KINGSBURY CO
	r	A. KINGSBURY CO

402 E CHURCH ST

Year	Uses	Source	
2017	ASHLEY CORPUZ	Cole Information Services	
2014	ASHLEY CORPUZ	Cole Information Services	
2009	DONG LIN	Cole Information Services	
1999	DONG LIN	Cole Information Services	
1990	Ng Chum Wing	R. L. Polk Co., Publishers	Image pg. A17
1979	No Return	R.L. Polk CO.	Image pg. A48
1975	Ng Wang	R.L. Polk CO.	Image pg. A58

403 E CHURCH ST

Year	Uses	Source
1906	ADAMS JOSEPH A Adams & Gist r	A. KINGSBURY CO

404 E CHURCH ST

Year	Uses	Source	
2014	MARCOS GARCIA	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1990	Lee Nelson W	R. L. Polk Co., Publishers	Image pg. A17

Year	Uses	Source	
1979	Lee Nelson W	R.L. Polk CO.	Image pg. A48
1975	Lee Nelson W	R.L. Polk CO.	Image pg. A58

405 E CHURCH ST

Year	Uses	Source	
1911	Dangers Chas h	Polk-Husted Directory	
	Solomon Minnie Ovid Max b	Polk-Husted Directory	
	Dangers Juanita opr P T & T Co b	Polk-Husted Directory	
1906	Musick John W baker r	A. KINGSBURY CO	

406 E CHURCH ST

Year	Uses	Source	
2017	BERNARDO BAYBAYAN	Cole Information Services	
2014	MARY CASTILLO	Cole Information Services	
2009	MARIA PRADO	Cole Information Services	
2004	MARIA PRADO	Cole Information Services	
1999	MARIA PRADO	Cole Information Services	
1996	Ly Binh	R. L. Polk Co., Publishers	Image pg. A9
1994	LY, BINH	Cole Information Services	
1990	Ly Binh	R. L. Polk Co., Publishers	Image pg. A17
1979	Lee Silvan	R.L. Polk CO.	Image pg. A48
1975	Lee Silvan	R.L. Polk CO.	Image pg. A58

408 E CHURCH ST

Year	Uses	Source	
2017	JESUS RODRIGUEZ	Cole Information Services	
2014	JERRY PEREZ	Cole Information Services	
2009	JERRI PEREZ	Cole Information Services	
	AMBER DAVI	Cole Information Services	
1999	JERRI PEREZ	Cole Information Services	
	AMBER DAVI	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A2
1990	Remedies Sotiango	R. L. Polk Co., Publishers	Image pg. A17
1979	Madriaga Balbind	R.L. Polk CO.	Image pg. A48

Year	Uses	Source	
1975	Servantes Pedro	R.L. Polk CO.	Image pg. A58

410 E CHURCH ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1996	Melvin K A	R. L. Polk Co., Publishers	Image pg. A9
1990	Rivera Vincente C	R. L. Polk Co., Publishers	Image pg. A17
1979	Rivera Vincente C	R.L. Polk CO.	Image pg. A48
1975	Rivera Vincente C	R.L. Polk CO.	Image pg. A58
1970	Rivera Vincente	R. L. Polk Co., Publishers	Image pg. A66
1940	Durand H W	R. L. Polk Co., Publishers	Image pg. A116
1911	Wilson Wm C h	Polk-Husted Directory	
1906	Felix Frank emp M Deegan r	A. KINGSBURY CO	

411 E CHURCH ST

Year	Uses	Source	
2017	JUAN SANDOVAL	Cole Information Services	
2014	JUAN SANDOVAL	Cole Information Services	
2009	LYDIA BARRERA	Cole Information Services	
	JUAN SANDOVAL	Cole Information Services	
	CANDELARIO RUBIO	Cole Information Services	
2004	ELIJIO SANDOVAL	Cole Information Services	
	REMEDY SANDOVAL	Cole Information Services	
	SUSAN GRIMMETT	Cole Information Services	
1999	CANDELARIO RUBIO	Cole Information Services	
	Giminez Paul	R. L. Polk Co., Publishers	Image pg. A2
1996	Mezamota Nicolas	R. L. Polk Co., Publishers	Image pg. A9
1994	GONZALEZ, FERNAND	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A17
	b Vacant	R. L. Polk Co., Publishers	Image pg. A17
	a Vacant	R. L. Polk Co., Publishers	Image pg. A17
1979	Benedicto Mark	R.L. Polk CO.	Image pg. A48
	a Eda Francisco B	R.L. Polk CO.	Image pg. A48
	b Nasser Abdoh	R.L. Polk CO.	Image pg. A48

FINDINGS

Year	Uses	Source	
1975	Pagala Geo	R.L. Polk CO.	Image pg. A58
	bVallesteros Rufina	R.L. Polk CO.	Image pg. A58
	a Eda Francisco B	R.L. Polk CO.	Image pg. A58
	Benedicto Mark	R.L. Polk CO.	Image pg. A58
1970	b Conrad Margt Mrs	R. L. Polk Co., Publishers	Image pg. A66
	a Eda Francisco B	R. L. Polk Co., Publishers	Image pg. A66
	Benedicto Mark	R. L. Polk Co., Publishers	Image pg. A66
1940	Retzlaff Emil	R. L. Polk Co., Publishers	Image pg. A116
	Irion Elmer	R. L. Polk Co., Publishers	Image pg. A116
1911	Warner Lula asst B F Walker b	Polk-Husted Directory	
	Trefry Helen w id A P h	Polk-Husted Directory	
	Starr Lew is L mngr Brilliant Jew elry Co b	Polk-Husted Directory	
	Warner Mrs Annie elk Hales b	Polk-Husted Directory	
1906	Richardson John E linotype opr The Independent r	A. KINGSBURY CO	
	Trefry Avery P emp Hobbs Parsons Co r	A. KINGSBURY CO	
	Zeigler Richard B	A. KINGSBURY CO	

412 E CHURCH ST

Year	Uses	Source	
2009	KRISTINA REINERT	Cole Information Services	
1999	KRISTINA REINERT	Cole Information Services	
	Kokal Betty	R. L. Polk Co., Publishers	Image pg. A2
1990	Smith Curtis	R. L. Polk Co., Publishers	Image pg. A17
1979	Ollarzabal Refugio G	R.L. Polk CO.	Image pg. A48
1975	Ollarzabal Refugio	R.L. Polk CO.	Image pg. A58
1970	Ollarzabal Refugio	R. L. Polk Co., Publishers	Image pg. A66
1940	Johnson F E	R. L. Polk Co., Publishers	Image pg. A116

418 E CHURCH ST

Year	Uses	Source
2017	SOUA LEE	Cole Information Services
2014	SOUA LEE	Cole Information Services

FINDINGS

420 E CHURCH ST

Year	Uses	Source	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A2
	Yzquierdo Marina M	R. L. Polk Co., Publishers	Image pg. A2
1990	h No Return	R. L. Polk Co., Publishers	Image pg. A17
	Mercado Simona	R. L. Polk Co., Publishers	Image pg. A17
1979	A Ortega Josephine M	R.L. Polk CO.	Image pg. A48
	Makado Simma	R.L. Polk CO.	Image pg. A48
1975	Mercado Simona Mrs	R.L. Polk CO.	Image pg. A58
	Ortega Marie J Mrs	R.L. Polk CO.	Image pg. A58
1970	A Ortega Josephine Mrs	R. L. Polk Co., Publishers	Image pg. A66
	Yzquierdo Adolfo	R. L. Polk Co., Publishers	Image pg. A66
1940	Ash Lew is	R. L. Polk Co., Publishers	Image pg. A116
	Robey A R	R. L. Polk Co., Publishers	Image pg. A116
1911	Schimmelpfennig Frank W eng Stkn Water Co h	Polk-Husted Directory	
1906	Solomon Minnie Mrs r	A. KINGSBURY CO	
	Smerdell John Smerdell & Struich r	A. KINGSBURY CO	
	Schimmelpfennig Fred W emp Samson Iron Works r	A. KINGSBURY CO	
	Salomon Minna Mrs r	A. KINGSBURY CO	
	Dangers Juanita Miss opr S T & T Co r	A. KINGSBURY CO	

421 E CHURCH ST

Year	Uses	Source	
2009	JENG MOW	Cole Information Services	
2004	JENG MOW	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Mow Jeng G lS	R. L. Polk Co., Publishers	Image pg. A2
1996	Mow Lyman	R. L. Polk Co., Publishers	Image pg. A9
1994	MOW, LYMAN	Cole Information Services	
1990	Mao Chang	R. L. Polk Co., Publishers	Image pg. A17
1979	Mow Lyman	R.L. Polk CO.	Image pg. A48

FINDINGS

Year	Uses	Source	
1975	Mow Lyman	R.L. Polk CO.	Image pg. A58
1970	Mow Lyman	R. L. Polk Co., Publishers	Image pg. A66
1940	lim John	R. L. Polk Co., Publishers	Image pg. A116
1911	Harkins Jas P cashr W P Ry h	Polk-Husted Directory	

422 E CHURCH ST

Year	Uses	Source	
2017	MONICA FUENTES	Cole Information Services	
2014	LUIS RULES	Cole Information Services	
2009	GERARDO LOPEZ	Cole Information Services	
1999	GERARDO LOPEZ	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A2
1990	No Return	R. L. Polk Co., Publishers	Image pg. A17
	b No Return	R. L. Polk Co., Publishers	Image pg. A17
1979	a Nunez Fernand	R.L. Polk CO.	Image pg. A48
	b Nasser Othman	R.L. Polk CO.	Image pg. A48
1975	bCanton Victor	R.L. Polk CO.	Image pg. A58
1970	a Dominguez Pablo	R. L. Polk Co., Publishers	Image pg. A66
	b Burke Jesse	R. L. Polk Co., Publishers	Image pg. A66
1940	Morgan Harry	R. L. Polk Co., Publishers	Image pg. A116
1911	Briel Louis chemist r	Polk-Husted Directory	
	Dixon Curtis A painter h	Polk-Husted Directory	
	Scarlette Wm B ydmstr Santa Fe r	Polk-Husted Directory	
1906	Bliven Robert C mach r	A. KINGSBURY CO	
	Bliven Wm J clk Wilkes & Pearson r	A. KINGSBURY CO	
	Bliven Catherine Mrs r	A. KINGSBURY CO	

424 E CHURCH ST

Year	Uses	Source	
1999	Caballero Michael J Sr	R. L. Polk Co., Publishers	Image pg. A2
1990	Huante Rose	R. L. Polk Co., Publishers	Image pg. A17
1979	Gallardo Eliva	R.L. Polk CO.	Image pg. A48
1975	Huante Rosa Mrs	R.L. Polk CO.	Image pg. A58
1970	Huante Rosa Mrs	R. L. Polk Co., Publishers	Image pg. A66

FINDINGS

Year	Uses	Source	
1940	Buchanan Jack	R. L. Polk Co., Publishers	Image pg. A116
1911	h	Polk-Husted Directory	
	Sturzeneg ger Rafael A baker	Polk-Husted Directory	
1906	Rice Reuben C bkkpr Cal M P Co r	A. KINGSBURY CO	

426 E CHURCH ST

Year	Uses	Source	
2017	VICTOR LEE	Cole Information Services	
2014	VICTOR LEE	Cole Information Services	
2009	VICTOR LEE	Cole Information Services	
2004	VICTOR LEE	Cole Information Services	
1999	VICTOR LEE	Cole Information Services	
	Lee Law rence	R. L. Polk Co., Publishers	Image pg. A2
	Lee Victor	R. L. Polk Co., Publishers	Image pg. A2
1990	Lee Alf	R. L. Polk Co., Publishers	Image pg. A17
1979	Lee Wing H	R.L. Polk CO.	Image pg. A48
1975	Lee Wing H	R.L. Polk CO.	Image pg. A58
1970	Lee Wing H	R. L. Polk Co., Publishers	Image pg. A66

427 E CHURCH ST

Year	Uses	Source	
2017	HUNG LE	Cole Information Services	
2014	ALAN GRIFFIN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	ROBERT LEE	Cole Information Services	
1999	Siu Kam	R. L. Polk Co., Publishers	Image pg. A2
1996	Lee Mae J	R. L. Polk Co., Publishers	Image pg. A9
1994	LEE, MAE J	Cole Information Services	
1990	Siu Kamho	R. L. Polk Co., Publishers	Image pg. A17
1979	Siu Shee C	R.L. Polk CO.	Image pg. A48
1975	Siu Shee C	R.L. Polk CO.	Image pg. A58
1970	Siu Shee C	R. L. Polk Co., Publishers	Image pg. A66
1940	Orienxital	R. L. Polk Co., Publishers	Image pg. A116
1911	Harkins Alice F asst Nutter & Orr b	Polk-Husted Directory	

FINDINGS

Year	Uses	Source
1911	Harkins Edw in E clk Hickinbotham Bros b	Polk-Husted Directory
	Harkins Harry W clk Hickinbotham Bros b	Polk-Husted Directory
	Harkins John master mariner h	Polk-Husted Directory
1906	Harkins Alice F Mrs stenog Nicol & Orr r	A. KINGSBURY CO
	Harkins Edw in A carp r	A. KINGSBURY CO
	Harkins John D capt str Champion r	A. KINGSBURY CO
	Harkins John D bkkpr r	A. KINGSBURY CO

433 E CHURCH ST

Year	Uses	Source	
2017	PASHEN SIMS	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1999	Not Verified 3 Hses	R. L. Polk Co., Publishers	Image pg. A2
1990	Rias Feleciano	R. L. Polk Co., Publishers	Image pg. A17
1979	No Return	R.L. Polk CO.	Image pg. A48
1975	Tellaria Concepcion Mrs	R.L. Polk CO.	Image pg. A58
1970	Tellaria Concepcion Mrs	R. L. Polk Co., Publishers	Image pg. A66

435 E CHURCH ST

Year	Uses	Source	
2017	NANCI FLORES	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Lombeb Liberado	R. L. Polk Co., Publishers	Image pg. A17
1979	Sur Rene	R.L. Polk CO.	Image pg. A48
1975	Cantw ell Harold	R.L. Polk CO.	Image pg. A58
1970	Bianchini Maurice	R. L. Polk Co., Publishers	Image pg. A66

437 E CHURCH ST

Year	Uses	Source	
1990	Maglinte Edw in	R. L. Polk Co., Publishers	Image pg. A17
1979	Makinano Lucio E	R.L. Polk CO.	Image pg. A48
1975	Makinano Lucio E	R.L. Polk CO.	Image pg. A58
1970	Hart Jane Mrs	R. L. Polk Co., Publishers	Image pg. A66

FINDINGS

439 E CHURCH ST

Year	Uses	Source	
1990	Diaz Ingnacio	R. L. Polk Co., Publishers	Image pg. A17
1979	Amora Georgina	R.L. Polk CO.	Image pg. A48
1975	Amora G R	R.L. Polk CO.	Image pg. A58
1970	Spear Valerie	R. L. Polk Co., Publishers	Image pg. A66

443 E CHURCH ST

Year	Uses	Source	
2014	CATALINA ANDRADE	Cole Information Services	
2004	CATALINA ANDRADE	Cole Information Services	
1999	Andrade Catalina	R. L. Polk Co., Publishers	Image pg. A2
1990	Reynosa Luis	R. L. Polk Co., Publishers	Image pg. A17
1979	Riberal Guillerm	R.L. Polk CO.	Image pg. A48
1975	No Return	R.L. Polk CO.	Image pg. A58
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A66
1940	Retzlaff Emil	R. L. Polk Co., Publishers	Image pg. A116
	Boyts F M	R. L. Polk Co., Publishers	Image pg. A116
1911	Mc Carty Wm J driver Aubrys b	Polk-Husted Directory	
	Mc Carty Wm lab Holt Mnfg Co h	Polk-Husted Directory	
	Mc Carty M Theresa stngr G F Buck b	Polk-Husted Directory	
1906	Mc Carty Wm Jr emp Smith & Lang r	A. KINGSBURY CO	
	Mc Carty Wm emp Stockton Milling Co r	A. KINGSBURY CO	
	Mc Carty Teresa Miss r	A. KINGSBURY CO	
	Leonard Geo A clk A W More r	A. KINGSBURY CO	

E HAZELTON

319 E HAZELTON

Year	Uses	Source
1911	Taylor Mrs Emma manicurist Syndicate Barber Shop b	Polk-Husted Directory

FINDINGS

E HAZELTON AVE

219 E HAZELTON AVE

Year	Uses	Source	
2017	HUMBERTO MATIAS	Cole Information Services	
2014	HUMBERTO MATIAS	Cole Information Services	
2009	HUMBERTO MATIAS	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1996	Hong Tom	R. L. Polk Co., Publishers	Image pg. A10
1994	HONG, TOM	Cole Information Services	
1990	Hong Tom	R. L. Polk Co., Publishers	Image pg. A18
1979	Hong Tom	R.L. Polk CO.	Image pg. A49
1975	Hong Tom	R.L. Polk CO.	Image pg. A59
1970	Hong Tom	R. L. Polk Co., Publishers	Image pg. A67
1940	Lopez F L	R. L. Polk Co., Publishers	Image pg. A117
1911	Lingane Matthew clnr Wm Kerr h	Polk-Husted Directory	
1906	Gardenshire Fred M r	A. KINGSBURY CO	
	Knlow les Ansel L fireman r	A. KINGSBURY CO	

231 E HAZELTON AVE

Year	Uses	Source	
2009	PLASIDO SANDOVAL	Cole Information Services	
2004	MANUEL MEDINA	Cole Information Services	
1999	Medina Manuel T	R. L. Polk Co., Publishers	Image pg. A3
	+S SAN JOAQUIN ST	R. L. Polk Co., Publishers	Image pg. A3
1990	Modesta Medin	R. L. Polk Co., Publishers	Image pg. A18
1979	No Return	R.L. Polk CO.	Image pg. A49
1975	No Return	R.L. Polk CO.	Image pg. A59
1970	Madena Modesta Mrs	R. L. Polk Co., Publishers	Image pg. A67
1940	Bantillo Anastacio	R. L. Polk Co., Publishers	Image pg. A117
	Cozzitorti Louis	R. L. Polk Co., Publishers	Image pg. A117
1911	Fields Chas A farmer h	Polk-Husted Directory	
1906	Fields Chas r	A. KINGSBURY CO	
	Fields Chas A atdt State Hospital r	A. KINGSBURY CO	

FINDINGS

243 E HAZELTON AVE

Year	Uses	Source	
1911	Hoult T Lindsay Hoult & Co b	Polk-Husted Directory	
	Lindberg Arthur hlpr Samson I Wks r	Polk-Husted Directory	
	Pickering L Grace nurse S F Priestly b	Polk-Husted Directory	
	Hoult Elizabeth h	Polk-Husted Directory	
	Hoult J Frank carp H & H Mnfg Co	Polk-Husted Directory	
1906	Hoult Elizabeth M Miss r	A. KINGSBURY CO	
	Hoult Ellen Miss r	A. KINGSBURY CO	
	Hoult Frank J blacksmith r	A. KINGSBURY CO	
	Hoult Margaret A Miss r	A. KINGSBURY CO	
	Hoult Nellie A Miss r	A. KINGSBURY CO	
	Pulsifer Calvin solr Cal A Fence Co r	A. KINGSBURY CO	
	Pulsifer Ethel Miss r	A. KINGSBURY CO	

304 E HAZELTON AVE

Year	Uses	Source	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A18
1979	El Dorado Farm Labor Service	R.L. Polk CO.	Image pg. A49

306 E HAZELTON AVE

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A18

308 E HAZELTON AVE

Year	Uses	Source	
2017	CHINA NOODLE FACTORY	Cole Information Services	
2014	CHINA NOODLE FACTORY	Cole Information Services	
2009	CHINA NOODLE FACTORY	Cole Information Services	
2004	SUSAN WONG	Cole Information Services	
	CHINA NOODLE FACTORY	Cole Information Services	
1999	CHINA NOODLE FACTORY	Cole Information Services	
	CHINA NOODLE FACTORY macaroni spaghetti	R. L. Polk Co., Publishers	Image pg. A3
	Wong Paul T	R. L. Polk Co., Publishers	Image pg. A3

FINDINGS

Year	Uses	Source	
1996	CHINA NOODLE FACTORY	R. L. Polk Co., Publishers	Image pg. A10
1994	CHINA NOODLE FACTORY	Cole Information Services	
1990	China Noodle Fcty chinese markets	R. L. Polk Co., Publishers	Image pg. A18
1979	China Noodle Factory	R.L. Polk CO.	Image pg. A49
1975	China Noodle Factory	R.L. Polk CO.	Image pg. A59
1970	Pahl Harry Co htg & air end	R. L. Polk Co., Publishers	Image pg. A67

319 E HAZELTON AVE

Year	Uses	Source	
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A67
	Molina Mary Mrs	R. L. Polk Co., Publishers	Image pg. A67
1940	Mc Coy B P	R. L. Polk Co., Publishers	Image pg. A117
1911	Olds Harry H brtndr Maddens h	Polk-Husted Directory	
	Radcliffe Frank D cond S Fe Ry h	Polk-Husted Directory	
	Taylor John C h	Polk-Husted Directory	
1906	Ferris Wm emp A T & S F r	A. KINGSBURY CO	
	Dines Geo carp r	A. KINGSBURY CO	

321 E HAZELTON AVE

Year	Uses	Source	
1970	Craig Angie Mrs	R. L. Polk Co., Publishers	Image pg. A67
	Vacant	R. L. Polk Co., Publishers	Image pg. A67
1940	Iturria Peter	R. L. Polk Co., Publishers	Image pg. A117
	Meoqui Peter	R. L. Polk Co., Publishers	Image pg. A117
1911	Maspla Jose h	Polk-Husted Directory	
1906	Mc Ghan M Chas constable r	A. KINGSBURY CO	
	Galgiani Vincent fireman r	A. KINGSBURY CO	
	Reagan Chas D printer The Independent r	A. KINGSBURY CO	

327 E HAZELTON AVE

Year	Uses	Source
2017	JAVIER CONCHA	Cole Information Services
2014	JAVIER CONCHA	Cole Information Services
2009	JAVIER CONCHA	Cole Information Services

FINDINGS

Year	Uses	Source	
2004	MARIA HERNANDEZ	Cole Information Services	
	SERGIO AVALOS	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Concha Ramon	R. L. Polk Co., Publishers	Image pg. A3
	Concha Angela	R. L. Polk Co., Publishers	Image pg. A3
1996	Eslrada J	R. L. Polk Co., Publishers	Image pg. A10
1994	GONZALEZ, RAMON C	Cole Information Services	
1990	Lim Arthur	R. L. Polk Co., Publishers	Image pg. A18
1979	Mar Kenneth W	R.L. Polk CO.	Image pg. A49
1975	Mar Kenneth	R.L. Polk CO.	Image pg. A59
1970	Cadiran Rosie Mrs	R. L. Polk Co., Publishers	Image pg. A67
1940	Loy John	R. L. Polk Co., Publishers	Image pg. A117
1911	Englander Mrs Mary L b	Polk-Husted Directory	
	Mullally John L salsn H A Prole h	Polk-Husted Directory	
1906	Peterson Andrew Jr r	A. KINGSBURY CO	
	Peterson Victor emp Holden Drug Co r	A. KINGSBURY CO	
	Peterson Andrew carp r	A. KINGSBURY CO	

335 E HAZELTON AVE

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	ANDREA WALKER	Cole Information Services	
	ANDREAS JANITORIAL	Cole Information Services	
1999	ANDREA WALKER	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A3
1990	Mar Stephen M	R. L. Polk Co., Publishers	Image pg. A18
1979	Mar Stephen M	R.L. Polk CO.	Image pg. A49
1975	Mar Stephen M	R.L. Polk CO.	Image pg. A59
1970	Mar Pon Shee Mrs	R. L. Polk Co., Publishers	Image pg. A67
1940	Meoqui Peter	R. L. Polk Co., Publishers	Image pg. A117
	Oriental	R. L. Polk Co., Publishers	Image pg. A117
1911	White Arthur C rancher h	Polk-Husted Directory	
1906	Pendegast Kate Mrs r	A. KINGSBURY CO	

Year	Uses	Source
1906	Holt Pliny E mgr H Mfg Co r	A. KINGSBURY CO
	Holt Frances Miss r	A. KINGSBURY CO
	Holt Clara Mrs r	A. KINGSBURY CO
	Hargrave Alice Miss music teacher	A. KINGSBURY CO
	Gilmore Daniel N Gilmore Bros r	A. KINGSBURY CO

336 E HAZELTON AVE

Year	Uses	Source
1911	Lopez Antony lab b	Polk-Husted Directory
	Dias Louis lab h	Polk-Husted Directory
	Martinez Merced lab b	Polk-Husted Directory
1906	Strachan Mabel emp S W Mills r	A. KINGSBURY CO
	Strachan Wm lab r	A. KINGSBURY CO

337 E HAZELTON AVE

Year	Uses	Source
2017	NIKKOLE MITCHELL	Cole Information Services
2014	NIKKOLE MITCHELL	Cole Information Services
2009	NIKKOLE MITCHELL	Cole Information Services
1999	NIKKOLE MITCHELL	Cole Information Services

338 E HAZELTON AVE

Year	Uses	Source
1906	Bennett Wm E painter r	A. KINGSBURY CO
	Smith Jos emp Am Fish Co r	A. KINGSBURY CO

340 E HAZELTON AVE

Year	Uses	Source
1911	De Martini Anne w id Aug h	Polk-Husted Directory
1906	Holman Emma A Mrs r	A. KINGSBURY CO
	Holman Clarence eng r	A. KINGSBURY CO

342 E HAZELTON AVE

Year	Uses	Source
1911	Corr Leroy clk Holt Mnfg Co b	Polk-Husted Directory
	Corr Nellie w id Frank h	Polk-Husted Directory

Year	Uses	Source	
1911	Corr Clarence b	Polk-Husted Directory	

345 E HAZELTON AVE

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	ALBERTO ABARCA CALLEJAS	Cole Information Services	
1990	Islas Joaquina	R. L. Polk Co., Publishers	Image pg. A18
1979	Williams Lloyd	R.L. Polk CO.	Image pg. A49
1975	Williams Lloyd	R.L. Polk CO.	Image pg. A59
1970	Ross Vielym Mrs	R. L. Polk Co., Publishers	Image pg. A67

347 E HAZELTON AVE

Year	Uses	Source
1906	Burns John P emp S P Co r	A. KINGSBURY CO

364 E HAZELTON AVE

Year	Uses	Source
1906	Corr Nellie Mrs laundress r	A. KINGSBURY CO
	Corr Clarence lab r	A. KINGSBURY CO

E LAFAYETTE ST

202 E LAFAYETTE ST

Year	Uses	Source	
1940	Limon Leonora Mrs	R. L. Polk Co., Publishers	Image pg. A118
1911	De Camina Domingo lab h	Polk-Husted Directory	

206 E LAFAYETTE ST

Year	Uses	Source	
1940	Yturbid Vicenta Mrs	R. L. Polk Co., Publishers	Image pg. A118
1911	Smith Artemus I Garrick Theatre h	Polk-Husted Directory	
1906	Pease Katharine Miss clk r	A. KINGSBURY CO	
	King Harry J emp Enterprise Planing Mills r	A. KINGSBURY CO	
	Jones Harriet L Mrs r	A. KINGSBURY CO	

FINDINGS

208 E LAFAYETTE ST

Year	Uses	Source	
1940	Chinese School	R. L. Polk Co., Publishers	Image pg. A118
	Chinese Assn	R. L. Polk Co., Publishers	Image pg. A118

210 E LAFAYETTE ST

Year	Uses	Source	
1975	Chinese Association	R.L. Polk CO.	Image pg. A60
1970	Chinese Association	R. L. Polk Co., Publishers	Image pg. A68
1940	Concordia Club	R. L. Polk Co., Publishers	Image pg. A118
1906	MORRELL & COWELL R P Morrell E C Cow ell proprs Enterprise Planing Mills	A. KINGSBURY CO	
	ENTERPRISE PLANING MILLS Morrell & Cow ell proprs bar fixtures w ood matels grates tiles and general mill w ork	A. KINGSBURY CO	

212 E LAFAYETTE ST

Year	Uses	Source	
2017	CONFUCIUS CHURCH	Cole Information Services	
2014	CONFUCIUS CHURCH	Cole Information Services	
2009	CHINESE ASSOCIATION INC	Cole Information Services	
	CONFUCIUS CHURCH	Cole Information Services	
2004	QUAN YING FOUNDATION	Cole Information Services	
	ROYAL MOTOR INN	Cole Information Services	
1999	CONFUCIUS CHURCH	Cole Information Services	
	CONFUCIUS CHURCH religious orga	R. L. Polk Co., Publishers	Image pg. A4
1996	CONFUCIUS CHURCH	R. L. Polk Co., Publishers	Image pg. A11
1994	CONFUCIUS CHURCH	Cole Information Services	
1990	Confucius Church	R. L. Polk Co., Publishers	Image pg. A19
1979	Confucius Church	R.L. Polk CO.	Image pg. A50
1975	S SAN JOAQUIN ST	R.L. Polk CO.	Image pg. A60
	Confucius Church	R.L. Polk CO.	Image pg. A60
1970	Confucius Church	R. L. Polk Co., Publishers	Image pg. A68
1940	lent Assn	R. L. Polk Co., Publishers	Image pg. A118
	Ning Yung Benevo	R. L. Polk Co., Publishers	Image pg. A118

FINDINGS

214 E LAFAYETTE ST

Year	Uses	Source	
1940	Chinese Methodist	R. L. Polk Co., Publishers	Image pg. A118
	Mission	R. L. Polk Co., Publishers	Image pg. A118

219 E LAFAYETTE ST

Year	Uses	Source
1911	Hill Jacob J lab h	Polk-Husted Directory

223 E LAFAYETTE ST

Year	Uses	Source
1911	Poe Chas W ticket agt W P Ry r	Polk-Husted Directory
	Doyle Frank W clk h	Polk-Husted Directory
	Hart Perry M lab r	Polk-Husted Directory
	Mc Neff Andrew telg opr W P Ry b	Polk-Husted Directory
1906	Sleith James A emp R Powell r	A. KINGSBURY CO

227 E LAFAYETTE ST

Year	Uses	Source
1911	Chrisman Wm S adv agt h	Polk-Husted Directory
	Chrisman Sami L b	Polk-Husted Directory

236 E LAFAYETTE ST

Year	Uses	Source	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	STOCKTON TRADING COMPANY	Cole Information Services	
	STOCKTON TRADING CO grcrs rltd prds	R. L. Polk Co., Publishers	Image pg. A4
	+S SAN JOAQUIN ST	R. L. Polk Co., Publishers	Image pg. A4
1996	JENE WAH INC	R. L. Polk Co., Publishers	Image pg. A11
1990	Wah Jene Inc	R. L. Polk Co., Publishers	Image pg. A19
1970	Salvation Army Corps	R. L. Polk Co., Publishers	Image pg. A68
1940	a Atwood Printing Co	R. L. Polk Co., Publishers	Image pg. A118
	Mission	R. L. Polk Co., Publishers	Image pg. A118

FINDINGS

238 E LAFAYETTE ST

Year	Uses	Source	
1906	Atw ood Building	A. KINGSBURY CO	
	ATWOOD PRINTING CO Leroy S and A W Atw ood printers and bookbinders	A. KINGSBURY CO	

246 E LAFAYETTE ST

Year	Uses	Source	
1906	Cavagnaro Margaret Mrs r	A. KINGSBURY CO	
	Cavagnaro Albena Miss opr S T & T Co r	A. KINGSBURY CO	
	Jencsa Albert A clk H W Mosier r	A. KINGSBURY CO	
	Larson Victor lineman P T & C Co r	A. KINGSBURY CO	
	Massa Antonio bartndr A Chironi r	A. KINGSBURY CO	
	Northrop Geo electrician r	A. KINGSBURY CO	
	Santos Geo emp Stockton Independent r	A. KINGSBURY CO	

284 E LAFAYETTE ST

Year	Uses	Source	
1979	Chambers Eulis	R.L. Polk CO.	Image pg. A51

308 E LAFAYETTE ST

Year	Uses	Source	
1979	Vacant	R.L. Polk CO.	Image pg. A52
1975	Vacant	R.L. Polk CO.	Image pg. A60
1970	Graf Battery Co	R. L. Polk Co., Publishers	Image pg. A68
1940	AMc Leod Jas blksmth	R. L. Polk Co., Publishers	Image pg. A118

309 E LAFAYETTE ST

Year	Uses	Source	
1970	b Chambers Lester	R. L. Polk Co., Publishers	Image pg. A68
	a Harrison Wm	R. L. Polk Co., Publishers	Image pg. A68
1940	a Oriental	R. L. Polk Co., Publishers	Image pg. A118
	Oriental	R. L. Polk Co., Publishers	Image pg. A118

310 E LAFAYETTE ST

Year	Uses	Source
2004	LISA GUZMAN	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	2 Not Verified	R. L. Polk Co., Publishers	Image pg. A4
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A19
	Richardson Albert J	R. L. Polk Co., Publishers	Image pg. A19
	Lesley Charles	R. L. Polk Co., Publishers	Image pg. A19
	Cruz Eusebio	R. L. Polk Co., Publishers	Image pg. A19
	Escobedo Jaime A	R. L. Polk Co., Publishers	Image pg. A19
1979	Apartments	R.L. Polk CO.	Image pg. A52
	Richardson Albert J	R.L. Polk CO.	Image pg. A52
	Jackson Lorenzo	R.L. Polk CO.	Image pg. A52
	Gray Parthenia Mrs	R.L. Polk CO.	Image pg. A52
	Vacant	R.L. Polk CO.	Image pg. A52
	Kilet Annie Mrs	R.L. Polk CO.	Image pg. A52
1975	Gray Parthenia Mrs	R.L. Polk CO.	Image pg. A60
	Reed Geraldine Mrs	R.L. Polk CO.	Image pg. A60
	STREET CONTINUED	R.L. Polk CO.	Image pg. A60
	Apartments	R.L. Polk CO.	Image pg. A60
	Richardson Albert J	R.L. Polk CO.	Image pg. A60
	Jackson Lorenzo	R.L. Polk CO.	Image pg. A60
1970	Apartments	R. L. Polk Co., Publishers	Image pg. A68
	Richardson Albert J	R. L. Polk Co., Publishers	Image pg. A68
	Collins Carl	R. L. Polk Co., Publishers	Image pg. A68
	Gray Parthenia Mrs	R. L. Polk Co., Publishers	Image pg. A68
	Reed Frank	R. L. Polk Co., Publishers	Image pg. A68
1940	Zimmerman Geo	R. L. Polk Co., Publishers	Image pg. A118

311 E LAFAYETTE ST

Year	Uses	Source	
1970	b Jones Donald R	R. L. Polk Co., Publishers	Image pg. A68
	a Pearson Ernest	R. L. Polk Co., Publishers	Image pg. A68
1940	a Eymard Marie Mrs	R. L. Polk Co., Publishers	Image pg. A118
	b Oriental	R. L. Polk Co., Publishers	Image pg. A118
1911	Taillet Gustave sheep raiser h	Polk-Husted Directory	
1906	Harn Wm V clk Hale & Co r	A. KINGSBURY CO	

FINDINGS

Year	Uses	Source	
1906	Williams Richard T clothing	A. KINGSBURY CO	
	r	A. KINGSBURY CO	

312 E LAFAYETTE ST

Year	Uses	Source	
1970	Stockton Veterinary Supply Co Whse	R. L. Polk Co., Publishers	Image pg. A68

316 E LAFAYETTE ST

Year	Uses	Source
1911	KRENZ FRED W Fred W Krenz & Co h	Polk-Husted Directory

317 E LAFAYETTE ST

Year	Uses	Source	
1970	Jacques Victor	R. L. Polk Co., Publishers	Image pg. A68
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A118
1911	Ramsbottom Robt h	Polk-Husted Directory	

318 E LAFAYETTE ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A19
1940	Eilat Marceli auto	R. L. Polk Co., Publishers	Image pg. A118
1911	KRENZ FRED W & CO F W Krenz Props Builders Iron Works	Polk-Husted Directory	

320 E LAFAYETTE ST

Year	Uses	Source
1906	KRENZ FREDERICK W F W Krenz & Co r	A. KINGSBURY CO

321 E LAFAYETTE ST

Year	Uses	Source
1906	Ramsbottom Robert r	A. KINGSBURY CO

329 E LAFAYETTE ST

Year	Uses	Source	
1940	Nocce D S furn rms	R. L. Polk Co., Publishers	Image pg. A118
1911	Jones Kenzy elk h	Polk-Husted Directory	
	Dodge Benj W bkpr Pac Gas & Elec Co h	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1911	Brooks Henry carmn h	Polk-Husted Directory	
1906	Wood Rachel Mrs r	A. KINGSBURY CO	
	Berlesson tella Miss student r	A. KINGSBURY CO	
	Chipette Tillie Miss student r	A. KINGSBURY CO	
	Dodge John emp A T & S F r	A. KINGSBURY CO	
	Dodge Sadie E Miss clk Hale &Co r	A. KINGSBURY CO	
	Hunsinger Edw carp r	A. KINGSBURY CO	
	Weisser Frances Miss r	A. KINGSBURY CO	
	Wood Chas E plumber r	A. KINGSBURY CO	
	Wood Ethel Miss clk R M Lana r	A. KINGSBURY CO	
	Wood Henry A clk Chas De Carli r	A. KINGSBURY CO	

331 E LAFAYETTE ST

Year	Uses	Source	
1911	Hoff Mrs Cecelia music tchr h	Polk-Husted Directory	
	Hoff Harold I stngr Wagner Leather Co b	Polk-Husted Directory	
1906	Green G W emp Thomas & Buell r	A. KINGSBURY CO	

336 E LAFAYETTE ST

Year	Uses	Source	
2017	HARDIN ANIMAL HOSPITAL INC	Cole Information Services	
2014	HARDIN ANIMAL HOSPITAL INC	Cole Information Services	
2009	HARDIN ANIMAL HOSPITAL	Cole Information Services	
	VICUNA PATRICIO DVM	Cole Information Services	
2004	PATRICIO VICUNA	Cole Information Services	
1999	HARDIN ANIMAL HOSPITAL	Cole Information Services	
1996	HARDIN ANIMAL HOSPITAL	R. L. Polk Co., Publishers	Image pg. A11
1994	JOHN WU	Cole Information Services	
	HARDIN ANIMAL HOSPITAL	Cole Information Services	
1990	Hardin Animal Hospital	R. L. Polk Co., Publishers	Image pg. A19
1979	Stockton Veterinary Supply Co Whse	R.L. Polk CO.	Image pg. A52
	Saunders Animal Hospital	R.L. Polk CO.	Image pg. A52
	Stockton Veterinary Supply Co	R.L. Polk CO.	Image pg. A52

FINDINGS

Year	Uses	Source	
1975	Stockton Veterinary Supply Co Whse Saunders Veterinary Clinic	R.L. Polk CO.	Image pg. A60
	Stockton Veterinary Supply Co	R.L. Polk CO.	Image pg. A60
1970	Saunders Francis H veterinarian	R. L. Polk Co., Publishers	Image pg. A68
	Stockton Veterinary Supply Co	R. L. Polk Co., Publishers	Image pg. A68
1940	AHolt G H City Pound	R. L. Polk Co., Publishers	Image pg. A118
	master	R. L. Polk Co., Publishers	Image pg. A118
	Saunders F H	R. L. Polk Co., Publishers	Image pg. A118
	vet surg	R. L. Polk Co., Publishers	Image pg. A118
	Stockton Vet Supp Co	R. L. Polk Co., Publishers	Image pg. A118
1911	Eddy John H vet surg	Polk-Husted Directory	
	Kitchingman John W uphlstr Pac Carpet Clng Co b	Polk-Husted Directory	
	Maurer Louis saw ver Union Planing Mill r	Polk-Husted Directory	
	Salbach Otto S J S Co r	Polk-Husted Directory	
	Schaffer Wm L asst J H Eddy r	Polk-Husted Directory	
1906	Eddy John H veterinary	A. KINGSBURY CO	
	Maurer Louis fireman Union P Mill Co r	A. KINGSBURY CO	
	Shaffer Wm asst J H Eddy r	A. KINGSBURY CO	

337 E LAFAYETTE ST

Year	Uses	Source	
1970	Conner Ray	R. L. Polk Co., Publishers	Image pg. A68
	Centurion Aurelio G	R. L. Polk Co., Publishers	Image pg. A68
1940	Nelson F C	R. L. Polk Co., Publishers	Image pg. A118

338 E LAFAYETTE ST

Year	Uses	Source
2009	LBC MABUHAY U S A ASIAN FOODMART AN	Cole Information Services
2004	LBC MBHY U S A ASIAN FDMRT	Cole Information Services
	ASIAN FOODMART & BAKE SHOP	Cole Information Services
1999	ASIAN FOODMART & BAKE SHOP	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
	LBC MABUHAY U S A CORPORATION	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	ASIAN FOOD MART & BAKE grocery stores	R. L. Polk Co., Publishers	Image pg. A4
	Vicuna Patricio R A	R. L. Polk Co., Publishers	Image pg. A4
1996	ASIAN MABUHAY FOODMART INC	R. L. Polk Co., Publishers	Image pg. A11
1994	ASIAN MABUHAY FOODMART INC	Cole Information Services	
1990	Asian Import & Export Inc oriental foods	R. L. Polk Co., Publishers	Image pg. A19
1979	Saunders Western Wear & Tack Shop	R.L. Polk CO.	Image pg. A52
1975	Saunders Western Wear & Tack Shop	R.L. Polk CO.	Image pg. A60

339 E LAFAYETTE ST

Year	Uses	Source	
1970	Stevens Printing Service	R. L. Polk Co., Publishers	Image pg. A68
1940	Matar Jos liquors	R. L. Polk Co., Publishers	Image pg. A118
1906	Higuera Nicholas emp M Deegan r	A. KINGSBURY CO	

342 E LAFAYETTE ST

Year	Uses	Source	
1940	Bow ers J W	R. L. Polk Co., Publishers	Image pg. A118
1911	Marshall Frank S btndr Castle & Barsi h	Polk-Husted Directory	

344 E LAFAYETTE ST

Year	Uses	Source	
1940	furn rms	R. L. Polk Co., Publishers	Image pg. A118
	furn rms	R. L. Polk Co., Publishers	Image pg. A118
	Mortensen Inez Mrs	R. L. Polk Co., Publishers	Image pg. A118
1911	Williams Kitty h	Polk-Husted Directory	
	Scott Saml r	Polk-Husted Directory	
	Hansen Victor brtndr J B Bergman r	Polk-Husted Directory	
	Collins Walter S cementw kr h	Polk-Husted Directory	

412 E LAFAYETTE ST

Year	Uses	Source	
1990	bWalker Harry	R. L. Polk Co., Publishers	Image pg. A19
	aHoughton Raymond	R. L. Polk Co., Publishers	Image pg. A19
	cSalvador Perez	R. L. Polk Co., Publishers	Image pg. A19
	Ulvang Dorothy	R. L. Polk Co., Publishers	Image pg. A19

FINDINGS

Year	Uses	Source	
1979	c Gonzales Fabian C	R.L. Polk CO.	Image pg. A52
	b Patterson H M	R.L. Polk CO.	Image pg. A52
	a Harper H C	R.L. Polk CO.	Image pg. A52
1975	Harpers	R.L. Polk CO.	Image pg. A60
	Patterson	R.L. Polk CO.	Image pg. A60
1970	Oroc Jo Ethel	R. L. Polk Co., Publishers	Image pg. A68
1940	Cavalero Phillip	R. L. Polk Co., Publishers	Image pg. A118
1911	Wright Mrs Cecelia asst Stkn Coffee Club b	Polk-Husted Directory	
	Monnerie Albert V barber J L Logan r	Polk-Husted Directory	
	Mitchell Wm E boilermkr r	Polk-Husted Directory	
	Wright Wm M driver h	Polk-Husted Directory	
1906	Mapel Elijah T brick maker r	A. KINGSBURY CO	
	Dennison Lesla E Miss stenog H R Mc Noble r	A. KINGSBURY CO	
	Dennison Errol E collr The Record r	A. KINGSBURY CO	
	Dennison Edmund H emp Tesla Coal Co r	A. KINGSBURY CO	

414 E LAFAYETTE ST

Year	Uses	Source	
1990	Contreras Arturo	R. L. Polk Co., Publishers	Image pg. A19

418 E LAFAYETTE ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A118
	furn rms	R. L. Polk Co., Publishers	Image pg. A118
1906	Heiser Chas porter r	A. KINGSBURY CO	
	Heusser Chas bartndr E R Peyton r	A. KINGSBURY CO	
	Rabbe Louis W emp E L Gnekow r	A. KINGSBURY CO	
	Utt Harry C bartndr Castle & Mc Erlane r	A. KINGSBURY CO	
	Webster Jos L bartndr r	A. KINGSBURY CO	

E SONORA ST

128 E SONORA ST

Year	Uses	Source	
2004	ESTRELLA SOBRGUEL	Cole Information Services	
1994	ILOILO CIRCLE CLUB	Cole Information Services	
1990	Iloilo Circle Club Inc The	R. L. Polk Co., Publishers	Image pg. A20
1979	Iloilo Circle Club Inc The social	R.L. Polk CO.	Image pg. A53
1975	Iloilo Circle Club Inc The social	R.L. Polk CO.	Image pg. A61
1970	Iloilo Circle Club Inc The social	R. L. Polk Co., Publishers	Image pg. A69
1940	Hokubei Khoyosan	R. L. Polk Co., Publishers	Image pg. A119
	Daishiji Temple	R. L. Polk Co., Publishers	Image pg. A119
1911	Corato Jos expmn h	Polk-Husted Directory	
1906	Balenzuela Jose w aiter M Marin r	A. KINGSBURY CO	
	Gonzales Conrad cook M Marin r	A. KINGSBURY CO	
	MARIN MANUEL propr The Merchants Bar and Grill	A. KINGSBURY CO	
	r	A. KINGSBURY CO	

131 E SONORA ST

Year	Uses	Source	
1970	Montero Esperdion	R. L. Polk Co., Publishers	Image pg. A69
1940	ASato Semu Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Erricart Jean sheep raiser h	Polk-Husted Directory	

134 E SONORA ST

Year	Uses	Source	
2009	VIRGIL WILLIAMS	Cole Information Services	
2004	VIRGIL WILLIAMS	Cole Information Services	
1999	VIRGIL WILLIAMS	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A20
1979	Wong Joy	R.L. Polk CO.	Image pg. A53
1975	Galaes Bert	R.L. Polk CO.	Image pg. A61
1970	Gales Bert G	R. L. Polk Co., Publishers	Image pg. A69

FINDINGS

136 E SONORA ST

Year	Uses	Source	
1990	Leung S	R. L. Polk Co., Publishers	Image pg. A20
1979	Estante Diomedes A	R.L. Polk CO.	Image pg. A53
1975	Estante Diomedes A	R.L. Polk CO.	Image pg. A61
1970	Estante Diamiales	R. L. Polk Co., Publishers	Image pg. A69

138 E SONORA ST

Year	Uses	Source	
1990	Gomez K	R. L. Polk Co., Publishers	Image pg. A20
1979	Chan Kw ock	R.L. Polk CO.	Image pg. A53
1975	Chan Kw ock	R.L. Polk CO.	Image pg. A61
1970	Chan Kw ock	R. L. Polk Co., Publishers	Image pg. A69
1940	Daishiji Temple	R. L. Polk Co., Publishers	Image pg. A119
	Galassi J	R. L. Polk Co., Publishers	Image pg. A119
1911	Riba Bert clk I X L Clo Co b	Polk-Husted Directory	
	Riba Baptiste farmer h	Polk-Husted Directory	
1906	Pridgeon Wm r	A. KINGSBURY CO	
	Pridgeon Georgia V Miss emp Sperry Co r	A. KINGSBURY CO	
	Pridgeon Frank J emp Entrpr Plng Mills r	A. KINGSBURY CO	
	Pridgeon Carrie E Miss r	A. KINGSBURY CO	
	Pridgeon Jefferson L emp Sperry Co r	A. KINGSBURY CO	

155 E SONORA ST

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

202 E SONORA ST

Year	Uses	Source
2014	VIOLETA TACATA	Cole Information Services
2009	VIOLETA TACATA	Cole Information Services
1999	VIOLETA TACATA	Cole Information Services

204 E SONORA ST

Year	Uses	Source
2009	REGIDOR LODGE 5 CDA INC	Cole Information Services

FINDINGS

Year	Uses	Source	
2004	REGIDOR LODGE 5 CDA INC	Cole Information Services	
1999	REGIDOR LODGE 5 CDA INCORPORATED	Cole Information Services	
	REGIDOR LODGE 5 CDA civic social assns	R. L. Polk Co., Publishers	Image pg. A5
1996	REGIDOR LODGE	R. L. Polk Co., Publishers	Image pg. A12
1994	REGIDOR LODGE 5 CDA INC	Cole Information Services	
1990	Regidor Lodge No 6 C D A Inc	R. L. Polk Co., Publishers	Image pg. A20
1979	Regidor Lodge No 5 C D A Inc	R.L. Polk CO.	Image pg. A53
1975	Regidor Lodge No 5 C D A Inc	R.L. Polk CO.	Image pg. A61
1970	Regidor Lodge No 5 C D A Inc	R. L. Polk Co., Publishers	Image pg. A69
1940	Palma Alfredo	R. L. Polk Co., Publishers	Image pg. A119
1906	Grissim Montgomery brick mason r	A. KINGSBURY CO	

209 E SONORA ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119
1911	Tripp John h	Polk-Husted Directory	
	Hirschman J Christ painter H S Todman h	Polk-Husted Directory	
1906	Tripp Andrew J harnessmkr r	A. KINGSBURY CO	
	Tripp Geo W teamster r	A. KINGSBURY CO	
	Tripp Geo clk G H Altenhoff r	A. KINGSBURY CO	
	Tripp Frank clk J Capurro & Co r	A. KINGSBURY CO	
	Tripp Chas clk M Levy & Bro r	A. KINGSBURY CO	

214 E SONORA ST

Year	Uses	Source	
1940	Wilson Mary Mrs	R. L. Polk Co., Publishers	Image pg. A119
	Hunter Wm	R. L. Polk Co., Publishers	Image pg. A119
1911	Forsythe Jas WV trucker Capitol Mills h	Polk-Husted Directory	
1906	Williams Yancy X towerman A T & S F r	A. KINGSBURY CO	
	Williams Annie E Mrs r	A. KINGSBURY CO	
	Williams Henrietta M Miss opr S T & T Co r	A. KINGSBURY CO	

FINDINGS

218 E SONORA ST

Year	Uses	Source	
2009	ALICE HOY	Cole Information Services	
1999	ALICE HOY	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A5
1990	Huey Wah K	R. L. Polk Co., Publishers	Image pg. A20
1979	Hoy Wah Kue	R.L. Polk CO.	Image pg. A53
1975	Hoy Wah Kue	R.L. Polk CO.	Image pg. A61
1970	Hoy Wah Kue	R. L. Polk Co., Publishers	Image pg. A69
1940	Page Benj	R. L. Polk Co., Publishers	Image pg. A119
1911	Frazier Elisha H lab h	Polk-Husted Directory	
	Fisher Jas H lab h	Polk-Husted Directory	
1906	Real Lonie Mrs r	A. KINGSBURY CO	
	Capurro Maria Mrs r	A. KINGSBURY CO	
	Capurro Lillie Miss r	A. KINGSBURY CO	
	Capurro John painter r	A. KINGSBURY CO	

221 E SONORA ST

Year	Uses	Source	
2017	ALBERT FERNANDEZ	Cole Information Services	
	ELPIDIO RAMISCAL	Cole Information Services	
2014	ALBERT FERNANDEZ	Cole Information Services	
	ELPIDIO RAMISCAL	Cole Information Services	
2009	ELPIDIO RAMISCAL	Cole Information Services	
	HILARIO ORIBELLO	Cole Information Services	
2004	HILARIO ORIBELLO	Cole Information Services	
	ELPIDIO RAMISCAL	Cole Information Services	
1999	ELPIDIO RAMISCAL	Cole Information Services	
	HILARIO ORIBELLO	Cole Information Services	
	42 Ramiscal Elpidio	R. L. Polk Co., Publishers	Image pg. A5
	Suan Trinidad E	R. L. Polk Co., Publishers	Image pg. A5
	20 Oribello Hilario	R. L. Polk Co., Publishers	Image pg. A5
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
	Aquino Salvatore	R. L. Polk Co., Publishers	Image pg. A20

FINDINGS

Year	Uses	Source	
1979	t Sorpruna Palaha	R.L. Polk CO.	Image pg. A53
	Lucero Pio R	R.L. Polk CO.	Image pg. A53
1975	mPastor Geo	R.L. Polk CO.	Image pg. A61
	Lucero Pio R	R.L. Polk CO.	Image pg. A61
1970	Lane Harry J	R. L. Polk Co., Publishers	Image pg. A69
	Hirigoyen Gene	R. L. Polk Co., Publishers	Image pg. A69
1940	Allington L H	R. L. Polk Co., Publishers	Image pg. A119
	Lane Harry	R. L. Polk Co., Publishers	Image pg. A119
1911	Earhart Thos B b	Polk-Husted Directory	
	Fisher T Edw truckmn Truck Co 1 h	Polk-Husted Directory	

222 E SONORA ST

Year	Uses	Source	
1940	a Silva Dan I	R. L. Polk Co., Publishers	Image pg. A119

223 E SONORA ST

Year	Uses	Source	
2017	KIM PIKE	Cole Information Services	
	DAVID PIKE	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	RICARDO CAYABYAB	Cole Information Services	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A5
	Rocili Evelyn E	R. L. Polk Co., Publishers	Image pg. A5
	Cayabyab Ricardo	R. L. Polk Co., Publishers	Image pg. A5
1996	Rocili Evelyn	R. L. Polk Co., Publishers	Image pg. A12
	Celasda Jesus	R. L. Polk Co., Publishers	Image pg. A12
1994	ROCILI, EVELYN	Cole Information Services	
1990	Acio Vit	R. L. Polk Co., Publishers	Image pg. A20
	Riveral Mariano R	R. L. Polk Co., Publishers	Image pg. A20
1979	A Gallera Faustino J	R.L. Polk CO.	Image pg. A53
	Lorenzo	R.L. Polk CO.	Image pg. A53
1975	Gallera Faustino J	R.L. Polk CO.	Image pg. A61
	Rialon Vicente	R.L. Polk CO.	Image pg. A61

FINDINGS

Year	Uses	Source	
1970	Asuncion Salvador	R. L. Polk Co., Publishers	Image pg. A69
	Alquinaldo Mariano D	R. L. Polk Co., Publishers	Image pg. A69
1940	Sadington Leona	R. L. Polk Co., Publishers	Image pg. A119
	Moreing M C Mrs	R. L. Polk Co., Publishers	Image pg. A119

224 E SONORA ST

Year	Uses	Source	
2009	NEW HOPE FAMILY SERVICES	Cole Information Services	
1999	Reed Deborah	R. L. Polk Co., Publishers	Image pg. A5
1990	Manganaan Cezar	R. L. Polk Co., Publishers	Image pg. A20
1979	Ramolete Mel T	R.L. Polk CO.	Image pg. A53
1975	Ramolete Mel	R.L. Polk CO.	Image pg. A61
1970	Ramolete Mel	R. L. Polk Co., Publishers	Image pg. A69

225 E SONORA ST

Year	Uses	Source	
2017	BLANCO CARAGAN	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
	BLANCO CARAGAN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
	BLANCO CARAGAN	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A5
	Boon Tong	R. L. Polk Co., Publishers	Image pg. A5
1996	Boon Tong	R. L. Polk Co., Publishers	Image pg. A12
1994	BOON, TONG	Cole Information Services	
1990	Tong Bo On	R. L. Polk Co., Publishers	Image pg. A20
	Cabrera Alex	R. L. Polk Co., Publishers	Image pg. A20
1979	i Bo On Tong	R.L. Polk CO.	Image pg. A53
	Alcantra Severo	R.L. Polk CO.	Image pg. A53
1975	Alcantra Severo	R.L. Polk CO.	Image pg. A61
	Vacant	R.L. Polk CO.	Image pg. A61
1970	A Palahang Sofronia S	R. L. Polk Co., Publishers	Image pg. A69
	Mira Steven	R. L. Polk Co., Publishers	Image pg. A69

FINDINGS

Year	Uses	Source	
1940	AZignego Antonio	R. L. Polk Co., Publishers	Image pg. A119

226 E SONORA ST

Year	Uses	Source	
1990	Callejo Tony	R. L. Polk Co., Publishers	Image pg. A20
1979	Paje Benny P	R.L. Polk CO.	Image pg. A53
1975	Castillo Nick	R.L. Polk CO.	Image pg. A61
1970	Woo Hing Jung	R. L. Polk Co., Publishers	Image pg. A69
1911	Rimassa Louis coremkr Monarch Founidry h	Polk-Husted Directory	
	Vinelli Chas P brtndr Oscar Anderson h	Polk-Husted Directory	
1906	Vinelli Julia C Miss r	A. KINGSBURY CO	
	Vinelli Chas Jr r	A. KINGSBURY CO	
	Vinelli Antone r	A. KINGSBURY CO	

227 E SONORA ST

Year	Uses	Source	
2017	JOVITA OSIAN	Cole Information Services	
	REGGIENO ALBANO	Cole Information Services	
	ROMULO ALBANO	Cole Information Services	
2014	ROMULO ALBANO	Cole Information Services	
	JOVITA OSIAN	Cole Information Services	
2009	JULIE SIN	Cole Information Services	
	ROMULO ALBANO	Cole Information Services	
	JOVITA OSIAN	Cole Information Services	
	LARRY JULIAN	Cole Information Services	
2004	MARCELINO RAMISCAL	Cole Information Services	
	ROMULO ALBANO	Cole Information Services	
	ADELAIDA SALVADOR	Cole Information Services	
1999	JULIE SIN	Cole Information Services	
	ROMULO ALBANO	Cole Information Services	
	JOVITA OSIAN	Cole Information Services	
	LARRY JULIAN	Cole Information Services	
	Albano Romulo	R. L. Polk Co., Publishers	Image pg. A5
1996	Albano Romulo G	R. L. Polk Co., Publishers	Image pg. A12

FINDINGS

Year	Uses	Source	
1996	Romero Pruden	R. L. Polk Co., Publishers	Image pg. A12
1994	ALBANO, ROMULO G	Cole Information Services	
1990	Gervacio Ponciano	R. L. Polk Co., Publishers	Image pg. A20
	aAgudelo Felicia	R. L. Polk Co., Publishers	Image pg. A20
	bQuijalvo Rolando	R. L. Polk Co., Publishers	Image pg. A20
1979	a Hicali Danny	R.L. Polk CO.	Image pg. A53
	bAbrenica Isabe	R.L. Polk CO.	Image pg. A53
1975	aBabrencia Isabello	R.L. Polk CO.	Image pg. A61
	bBonciano Gervacio	R.L. Polk CO.	Image pg. A61
1970	a Hacali Danny	R. L. Polk Co., Publishers	Image pg. A69
	b Cortez Tony	R. L. Polk Co., Publishers	Image pg. A69
1940	Fisher T E	R. L. Polk Co., Publishers	Image pg. A119
1911	Fisher Edw T house mover h	Polk-Husted Directory	
1906	Fisher Edw house mover	A. KINGSBURY CO	

228 E SONORA ST

Year	Uses	Source	
1940	Zinosanto S N	R. L. Polk Co., Publishers	Image pg. A119
1906	Capurro Jos J Capurro & Co r	A. KINGSBURY CO	

229 E SONORA ST

Year	Uses	Source	
2017	ARCH MANGANAAN	Cole Information Services	
2014	ARTURO MANGANAAN	Cole Information Services	
2009	ARCH MANGANAAN	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
2004	MADELINE GUILLERMO	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	L ACOBA	Cole Information Services	
	CEZAR MANGANAAN	Cole Information Services	
1999	CEZAR MANGANAAN	Cole Information Services	
	Pineda Estrella W	R. L. Polk Co., Publishers	Image pg. A5
	Pineda Napoleon B	R. L. Polk Co., Publishers	Image pg. A5
	Manganaan Cezar	R. L. Polk Co., Publishers	Image pg. A5

FINDINGS

Year	Uses	Source	
1999	Manganaan Arch	R. L. Polk Co., Publishers	Image pg. A5
1996	Pineda Napole	R. L. Polk Co., Publishers	Image pg. A12
1994	WOO, JULIEN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
	Tualla Juanito	R. L. Polk Co., Publishers	Image pg. A20
1979	Eatmon Sylvester	R.L. Polk CO.	Image pg. A53
	Womble Are S	R.L. Polk CO.	Image pg. A53
1975	/Yip Lee	R.L. Polk CO.	Image pg. A61
	Mar Wong Shee Mrs	R.L. Polk CO.	Image pg. A61
1970	Mar Wong Shee Mrs	R. L. Polk Co., Publishers	Image pg. A69
	Mar Ken W	R. L. Polk Co., Publishers	Image pg. A69
1940	Oriental	R. L. Polk Co., Publishers	Image pg. A119
1911	Fisher Mary J w id Jacob h	Polk-Husted Directory	
	Fisher John E carp b	Polk-Husted Directory	
1906	Rhodes May Miss r	A. KINGSBURY CO	
	Fisher Mary J Mrs r	A. KINGSBURY CO	
	Fisher Jennie Miss r	A. KINGSBURY CO	
	Fisher John E carp r	A. KINGSBURY CO	

231 E SONORA ST

Year	Uses	Source	
1979	No Return	R.L. Polk CO.	Image pg. A53
1975	Lechi E	R.L. Polk CO.	Image pg. A61
1970	Sacs Fidel C	R. L. Polk Co., Publishers	Image pg. A69
1940	a Mow Lyman	R. L. Polk Co., Publishers	Image pg. A119
1906	Murray Anna R Miss nurse	A. KINGSBURY CO	
	Murray Jos B r	A. KINGSBURY CO	
	Murray Mary E Mliss r	A. KINGSBURY CO	
	Murray Wm r	A. KINGSBURY CO	

232 E SONORA ST

Year	Uses	Source	
1975	Gutierrez 01 C	R.L. Polk CO.	Image pg. A61
1970	Campos Maria Mrs	R. L. Polk Co., Publishers	Image pg. A69

Year	Uses	Source	
1940	Capurro L R Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Grow s Richd bellmn Yosemite Club b	Polk-Husted Directory	
	h	Polk-Husted Directory	
	Capurro Maria w id Jos clothing	Polk-Husted Directory	

233 E SONORA ST

Year	Uses	Source	
1979	No Return	R.L. Polk CO.	Image pg. A53
1975	No Return	R.L. Polk CO.	Image pg. A61
1970	Adona Victorieno	R. L. Polk Co., Publishers	Image pg. A69
1940	AWong Toy	R. L. Polk Co., Publishers	Image pg. A119

235 E SONORA ST

Year	Uses	Source	
1979	Rodriguez Christine	R.L. Polk CO.	Image pg. A53
1975	Andres Pedro	R.L. Polk CO.	Image pg. A61
1970	Passion Basilio	R. L. Polk Co., Publishers	Image pg. A69
1940	Choy Wilbur	R. L. Polk Co., Publishers	Image pg. A119

237 E SONORA ST

Year	Uses	Source	
1979	Quinliquit Michl	R.L. Polk CO.	Image pg. A53
1975	No Return	R.L. Polk CO.	Image pg. A61
1970	Quippet Numero	R. L. Polk Co., Publishers	Image pg. A69
1940	Daishiji Temple	R. L. Polk Co., Publishers	Image pg. A119
	Oriental	R. L. Polk Co., Publishers	Image pg. A119

245 E SONORA ST

Year	Uses	Source	
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A69

260 E SONORA ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	+S SAN JOAQUIN ST	R. L. Polk Co., Publishers	Image pg. A5
	Jacobsen Heather	R. L. Polk Co., Publishers	Image pg. A5

FINDINGS

277 E SONORA ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	

309 E SONORA ST

Year	Uses	Source	
2017	HO IAN	Cole Information Services	
2014	RAYMOND LOUIE	Cole Information Services	
2009	RAYMOND LOUIE	Cole Information Services	
2004	WILLIAM LOUIE	Cole Information Services	
1999	RAYMOND LOUIE	Cole Information Services	
	Louie William & Katherine	R. L. Polk Co., Publishers	Image pg. A5
1996	Louie William	R. L. Polk Co., Publishers	Image pg. A12
1994	LOUIE, WILLIAM	Cole Information Services	
1990	Louie Wm	R. L. Polk Co., Publishers	Image pg. A20
1979	Louie Wm	R.L. Polk CO.	Image pg. A53
1975	Louie Chew	R.L. Polk CO.	Image pg. A61
1970	Louie Chew	R. L. Polk Co., Publishers	Image pg. A69
1940	Capurro R J Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Lynch Jos C brtndr J G Grohman h	Polk-Husted Directory	
	Thorpe Arthur K clk Edw Dunne h	Polk-Husted Directory	
1906	Hoskins James H r	A. KINGSBURY CO	
	Manley Mary E Mrs r	A. KINGSBURY CO	

310 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	BARBARA POWELL	Cole Information Services	
1999	BARBARA POWELL	Cole Information Services	
	Caraig Albert A & Rosalinda	R. L. Polk Co., Publishers	Image pg. A5
	Martinez Angelita C E	R. L. Polk Co., Publishers	Image pg. A5
1990	r Gomez Alvara	R. L. Polk Co., Publishers	Image pg. A20
1979	Alvarez Lidia G Mrs	R.L. Polk CO.	Image pg. A53
1975	Alvarez Lydia G Mrs	R.L. Polk CO.	Image pg. A61
1970	Azavedo Annie Mrs	R. L. Polk Co., Publishers	Image pg. A69

FINDINGS

Year	Uses	Source	
1940	Meadow s L S	R. L. Polk Co., Publishers	Image pg. A119
1911	HESS ALFRED Dept Supt Record Publishing Co h	Polk-Husted Directory	
1906	Dean Benjamin bartndr R A Webb r	A. KINGSBURY CO	
	Wheeler Reese T r	A. KINGSBURY CO	

312 E SONORA ST

Year	Uses	Source	
1979	Sarrasas Carlos	R.L. Polk CO.	Image pg. A53
1975	Gomez Beto	R.L. Polk CO.	Image pg. A61
1970	Henderson Elija	R. L. Polk Co., Publishers	Image pg. A69
1940	Olson John	R. L. Polk Co., Publishers	Image pg. A119
1911	Kantie John B elk Kane & Armacost b	Polk-Husted Directory	
	Kane Jas h	Polk-Husted Directory	
	Jones Saml F Stockton Theatre r	Polk-Husted Directory	
1906	Coleman Sarah Mrs r	A. KINGSBURY CO	
	New man Wm clk J Coleman r	A. KINGSBURY CO	

314 E SONORA ST

Year	Uses	Source	
1979	Basela Patricia Mrs	R.L. Polk CO.	Image pg. A53
1975	Basela Patricia Mrs	R.L. Polk CO.	Image pg. A61
1970	Minoz Jose	R. L. Polk Co., Publishers	Image pg. A69
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119
1911	Martin Erol R b	Polk-Husted Directory	
	Euson Laura R w id J H h	Polk-Husted Directory	
1906	Euson Laura R Mrs r	A. KINGSBURY CO	
	Ault Arthur emp Pac W G Co r	A. KINGSBURY CO	
	Ault Albert emp Pac W G Co r	A. KINGSBURY CO	

315 E SONORA ST

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
2004	KO NG	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	JAKE MAK	Cole Information Services	
1990	Mak Jake S	R. L. Polk Co., Publishers	Image pg. A20
1979	Yip Bing B	R.L. Polk CO.	Image pg. A53
1975	Yip Bor Bing	R.L. Polk CO.	Image pg. A61
1970	Yip Bor Bing	R. L. Polk Co., Publishers	Image pg. A69
1940	Anderson E L	R. L. Polk Co., Publishers	Image pg. A119
1911	Fitzgerald John h	Polk-Husted Directory	
	Fitzgerald Richd S farmer b	Polk-Husted Directory	
	Fitzgerald Henry farmer b	Polk-Husted Directory	
	Fitzgerald John P farmer b	Polk-Husted Directory	

316 E SONORA ST

Year	Uses	Source	
2014	SANTANA JUACHE	Cole Information Services	
2009	JOYCE TAPLIN	Cole Information Services	
1999	JOYCE TAPLIN	Cole Information Services	
	Not Verified 2 Hses	R. L. Polk Co., Publishers	Image pg. A5
1990	No Return	R. L. Polk Co., Publishers	Image pg. A20
1979	Vacant	R.L. Polk CO.	Image pg. A53
1975	Vacant	R.L. Polk CO.	Image pg. A61
1970	Bautista Max	R. L. Polk Co., Publishers	Image pg. A69
1940	Rosos P M	R. L. Polk Co., Publishers	Image pg. A119
1911	Dean Benj brtndr Mills & Barr h	Polk-Husted Directory	
1906	Peterson L Vinton city editor Daily Record r	A. KINGSBURY CO	
	Peterson Ida M Miss profreader Daily Record r	A. KINGSBURY CO	

317 E SONORA ST

Year	Uses	Source	
2017	ZHONG ZHU	Cole Information Services	
2014	ZHONG ZHU	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1990	r Yan Jin Shu	R. L. Polk Co., Publishers	Image pg. A20
1979	Fong Robin	R.L. Polk CO.	Image pg. A53

FINDINGS

Year	Uses	Source	
1975	Yun Pinky	R.L. Polk CO.	Image pg. A61
1970	Mah Thick	R. L. Polk Co., Publishers	Image pg. A69
1940	Setralis Thos	R. L. Polk Co., Publishers	Image pg. A119
1911	Mc Ginnis Jas E barber	Polk-Husted Directory	
	h	Polk-Husted Directory	

319 E SONORA ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A20
1979	Yip Kw ong Ying	R.L. Polk CO.	Image pg. A53
1975	Yip Kw ng	R.L. Polk CO.	Image pg. A61
1970	Mar Hung S	R. L. Polk Co., Publishers	Image pg. A69
1940	Terzo Ruby Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Freitas Clarence E Avenue Drug Co h	Polk-Husted Directory	
	Merryman Mrs Jennie b	Polk-Husted Directory	

321 E SONORA ST

Year	Uses	Source	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A20
1979	Ng Sze Yau	R.L. Polk CO.	Image pg. A53
1975	Ng Sze Yau	R.L. Polk CO.	Image pg. A61
1970	Yuk Ing	R. L. Polk Co., Publishers	Image pg. A69
1940	Frausto Pauline C	R. L. Polk Co., Publishers	Image pg. A119
1911	h	Polk-Husted Directory	
	Nevin Eugene H saloon	Polk-Husted Directory	

322 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	KWOK TSOO	Cole Information Services	
2004	ROSALIE TSOO	Cole Information Services	
1999	KWOK TSOO	Cole Information Services	
	Tsoo Rosalie L	R. L. Polk Co., Publishers	Image pg. A5

FINDINGS

Year	Uses	Source	
1999	Tsoo Kw ok C	R. L. Polk Co., Publishers	Image pg. A5
1996	Tsoo Kw ok C	R. L. Polk Co., Publishers	Image pg. A12
1994	TSOO, KWOK C	Cole Information Services	
1990	Tsoo Kw ok Chuen	R. L. Polk Co., Publishers	Image pg. A20
1979	Tsoo Kw ok	R.L. Polk CO.	Image pg. A53
1975	Wong Doon Min	R.L. Polk CO.	Image pg. A61
1970	Doon Min	R. L. Polk Co., Publishers	Image pg. A69
1940	Nave Assunta Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Law rence Lew is L plasterer h	Polk-Husted Directory	
1906	Law rence Lew is L plasterer r	A. KINGSBURY CO	

325 E SONORA ST

Year	Uses	Source	
1940	Phillips Stella	R. L. Polk Co., Publishers	Image pg. A119
1911	Curnow Clarence E driver Wilkes P K Co b	Polk-Husted Directory	
	Curnow Elizabeth w id John h	Polk-Husted Directory	
	Curnow Marguerite clk Hales b	Polk-Husted Directory	
	Curnow Mildred K cashr Peerless Cash Store b	Polk-Husted Directory	
1906	r	A. KINGSBURY CO	
	Brow n Adolph bicycle dealer	A. KINGSBURY CO	

328 E SONORA ST

Year	Uses	Source	
2014	AVINESH MISTRY	Cole Information Services	
	MEL HUANG	Cole Information Services	
2009	CATARINO FABELA	Cole Information Services	
2004	CATARINO FABELA	Cole Information Services	
1999	CATARINO FABELA	Cole Information Services	
	Fabela Catarino R BD	R. L. Polk Co., Publishers	Image pg. A5
1996	Fabela Catari R	R. L. Polk Co., Publishers	Image pg. A12
1994	LONG, POCH	Cole Information Services	
1990	Davis Jeanie J	R. L. Polk Co., Publishers	Image pg. A20
1979	Yee Darryl Hong Ying	R.L. Polk CO.	Image pg. A53

FINDINGS

Year	Uses	Source	
1975	Yee Hong Ying	R.L. Polk CO.	Image pg. A61
1970	Yee Darold	R. L. Polk Co., Publishers	Image pg. A69

329 E SONORA ST

Year	Uses	Source	
1940	Mayorga Jesus	R. L. Polk Co., Publishers	Image pg. A119
1911	Kyle Stephen H sec Peerless Cash Store r	Polk-Husted Directory	

330 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	CLIFF PETERSON	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Romero Jose B	R. L. Polk Co., Publishers	Image pg. A20
1979	Boggiano Law rence	R.L. Polk CO.	Image pg. A53
1975	Boggiano Law rence	R.L. Polk CO.	Image pg. A61
1970	Boggiano Law rence	R. L. Polk Co., Publishers	Image pg. A69
1940	Robbins M T Mrs	R. L. Polk Co., Publishers	Image pg. A119
	Foote L M Mrs	R. L. Polk Co., Publishers	Image pg. A119
1911	Robbins Mary T w id H E h	Polk-Husted Directory	
	Robbins Curtis M b	Polk-Husted Directory	
1906	Robbins Mary T Mrs r	A. KINGSBURY CO	
	Robbins Mabel C Miss r	A. KINGSBURY CO	
	Robbins Henry E Robbins & Summerville r	A. KINGSBURY CO	
	Robbins L Estella Miss emp R E Wilhoit & Sons r	A. KINGSBURY CO	

331 E SONORA ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119
1911	Smith Emma w id H L h	Polk-Husted Directory	
	Smith Winona clk Spencers Millinery b	Polk-Husted Directory	
	Smith Emma clk C W Rensimer & Co b	Polk-Husted Directory	

FINDINGS

332 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	LOPEZ RUIZ	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Villardo Marilao Jr	R. L. Polk Co., Publishers	Image pg. A20
1979	Fuentes Bernardo	R.L. Polk CO.	Image pg. A53
1975	Aguila Domingo	R.L. Polk CO.	Image pg. A61
1970	Torres Antonia D Mrs	R. L. Polk Co., Publishers	Image pg. A69
1940	Hagdorn Jas	R. L. Polk Co., Publishers	Image pg. A119

334 E SONORA ST

Year	Uses	Source	
1940	Kundert H H	R. L. Polk Co., Publishers	Image pg. A119
1911	Morgan Chas L musician Garrick Theatre h	Polk-Husted Directory	

336 E SONORA ST

Year	Uses	Source	
2017	MEL HUANG	Cole Information Services	
2014	LELAND LEUNG	Cole Information Services	
2009	LELAND LEUNG	Cole Information Services	
2004	CHEW LEUNG	Cole Information Services	
1999	LELAND LEUNG	Cole Information Services	
	Leung Chew Y	R. L. Polk Co., Publishers	Image pg. A5
1996	Leung Chew	R. L. Polk Co., Publishers	Image pg. A12
1994	LEUNG, CHEW	Cole Information Services	
1990	Leung Chew	R. L. Polk Co., Publishers	Image pg. A20
1979	Lampitok Catalino	R.L. Polk CO.	Image pg. A53
1975	Lamditok Catalino	R.L. Polk CO.	Image pg. A61
1970	Ng Guey Fan	R. L. Polk Co., Publishers	Image pg. A69
1940	Robbins M T Mrs	R. L. Polk Co., Publishers	Image pg. A119
	Uria Eulogio	R. L. Polk Co., Publishers	Image pg. A119
1906	Geiger Jos mgr Western Iron Works r	A. KINGSBURY CO	

FINDINGS

340 E SONORA ST

Year	Uses	Source	
1906	Almind Kildorf capitalist Yosemite Theater Bldg r	A. KINGSBURY CO	

346 E SONORA ST

Year	Uses	Source	
2017	JAMESIA BROWN	Cole Information Services	
2014	LUCIO GONZALEZ	Cole Information Services	
2009	DRICDEN SERRANO	Cole Information Services	
2004	OLIVER RAMIREZ	Cole Information Services	
1999	DRICDEN SERRANO	Cole Information Services	
1990	Henry Gee	R. L. Polk Co., Publishers	Image pg. A20
1979	Nong Lou	R.L. Polk CO.	Image pg. A53
1975	Louie Wing Ham	R.L. Polk CO.	Image pg. A61
1970	Louie Wing Ham	R. L. Polk Co., Publishers	Image pg. A69

348 E SONORA ST

Year	Uses	Source	
2017	CARLOS BANALES	Cole Information Services	
2009	CALLEJAS VIDAL	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	CALLEJAS VIDAL	Cole Information Services	
	Saldivar	R. L. Polk Co., Publishers	Image pg. A5
1990	Wong Fook Sing	R. L. Polk Co., Publishers	Image pg. A20
1979	Wong Fook Sing	R.L. Polk CO.	Image pg. A53
1975	Wong Fook Sing	R.L. Polk CO.	Image pg. A61
1970	Wong Fook Sing	R. L. Polk Co., Publishers	Image pg. A69
1911	Potter Everett E bldg contr h	Polk-Husted Directory	
1906	Liesy John farmer r	A. KINGSBURY CO	
	Kerrick Jefferson D gardener r	A. KINGSBURY CO	

415 E SONORA ST

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

416 E SONORA ST

Year	Uses	Source	
2009	DEAN MAK	Cole Information Services	
2004	JAKE MAK	Cole Information Services	
1999	JAKE MAK	Cole Information Services	
	Mak Jake Y	R. L. Polk Co., Publishers	Image pg. A5
1996	Mak Jake Y	R. L. Polk Co., Publishers	Image pg. A12
1994	MAK, JAKE Y	Cole Information Services	
1990	Mak Jake Ying	R. L. Polk Co., Publishers	Image pg. A20
1979	La Vergne Sadie	R.L. Polk CO.	Image pg. A53
1975	La Vergne Sadie	R.L. Polk CO.	Image pg. A61
1970	La Vergne Sadie Mrs	R. L. Polk Co., Publishers	Image pg. A69
1940	Wong Thorn	R. L. Polk Co., Publishers	Image pg. A119
1911	Concle Carl painter h	Polk-Husted Directory	
	Rodger Frank driver b	Polk-Husted Directory	

418 E SONORA ST

Year	Uses	Source	
2017	DEAN MAK	Cole Information Services	
2014	DEAN MAK	Cole Information Services	
2009	LIAN MAK	Cole Information Services	
2004	LIAN MAK	Cole Information Services	
1999	LIAN MAK	Cole Information Services	
	Mak Jean L	R. L. Polk Co., Publishers	Image pg. A5
	Mak Lian Z	R. L. Polk Co., Publishers	Image pg. A5
1996	Mak Lian Z	R. L. Polk Co., Publishers	Image pg. A12
1994	DOAN, TU	Cole Information Services	
1990	Vang Voya	R. L. Polk Co., Publishers	Image pg. A20
1979	Ong Ying	R.L. Polk CO.	Image pg. A53
1975	Ying On Assn	R.L. Polk CO.	Image pg. A61
1970	La Vergne Philip	R. L. Polk Co., Publishers	Image pg. A69
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119
1911	Mitscher Oscar H H Mitscher & Son h	Polk-Husted Directory	

FINDINGS

419 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	YONG HUANG	Cole Information Services	
2004	YONG HUANG	Cole Information Services	
1999	YONG HUANG	Cole Information Services	
	Huang Yong	R. L. Polk Co., Publishers	Image pg. A5
1990	Won Mon Fone	R. L. Polk Co., Publishers	Image pg. A20
1979	Vacant	R.L. Polk CO.	Image pg. A53
1970	Siefken Marvin	R. L. Polk Co., Publishers	Image pg. A69
1940	Queirolo W L	R. L. Polk Co., Publishers	Image pg. A119

421 E SONORA ST

Year	Uses	Source	
2009	HING WONG	Cole Information Services	
2004	HING WONG	Cole Information Services	
1999	HING WONG	Cole Information Services	
	Wong Hing	R. L. Polk Co., Publishers	Image pg. A5
1996	Wong Hing C	R. L. Polk Co., Publishers	Image pg. A12
1994	WONG, HING C	Cole Information Services	
1990	Wong Chuck	R. L. Polk Co., Publishers	Image pg. A20
1979	No Return	R.L. Polk CO.	Image pg. A53
1975	Wong Sheow Young	R.L. Polk CO.	Image pg. A61
1970	Wong Sheow Y	R. L. Polk Co., Publishers	Image pg. A69
1940	t Crawford J C	R. L. Polk Co., Publishers	Image pg. A119
1911	Baldridge Chas W hlpr H & H Mnfg Co h	Polk-Husted Directory	
	rdner Fielden A inspr r	Polk-Husted Directory	
	Brown Walter L baker r	Polk-Husted Directory	
	Dodge John W clk S Fe Ry b	Polk-Husted Directory	
1906	Burr Edna Miss r	A. KINGSBURY CO	
	Burr Jessie Miss dressmkr r	A. KINGSBURY CO	
	Burr Marjorie Miss student r	A. KINGSBURY CO	
	Mowry Milton J Wilson & Mowry r	A. KINGSBURY CO	
	Mowry Wm emp G H Truman r	A. KINGSBURY CO	

FINDINGS

422 E SONORA ST

Year	Uses	Source	
2009	YUET LEE	Cole Information Services	
2004	YUET LEE	Cole Information Services	
1999	YUET LEE	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A20
1975	Wong Doon G	R.L. Polk CO.	Image pg. A61
1970	Wong Doon G	R. L. Polk Co., Publishers	Image pg. A69
1940	Echandis Thos	R. L. Polk Co., Publishers	Image pg. A119
1911	Campbell Benj R carp h	Polk-Husted Directory	
	Orr Katherine E asst Pub Library b	Polk-Husted Directory	
	Orr Linda w id Albert b	Polk-Husted Directory	
1906	Reynolds Chester P r	A. KINGSBURY CO	
	Reynolds Fredk A emp Samson Iron Works r	A. KINGSBURY CO	
	Reynolds Georgianna Mrs r	A. KINGSBURY CO	
	REYNOLDS H Reynolds & Turner r	A. KINGSBURY CO	

427 E SONORA ST

Year	Uses	Source	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A5
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
1979	County Housing Authority Purch Dept	R.L. Polk CO.	Image pg. A53
1975	Vacant	R.L. Polk CO.	Image pg. A61
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A69
1940	Mc Manus Margt E	R. L. Polk Co., Publishers	Image pg. A119
1911	Mc Manus Wm P driver City St Dept b	Polk-Husted Directory	
	Ames Belle stngr Nutter & Orr b	Polk-Husted Directory	
	Carey Mary w id Maurice h	Polk-Husted Directory	
	Mc Manus Jas C lab b	Polk-Husted Directory	
	Mc Manus Margaret E b	Polk-Husted Directory	
1906	Carey Mary Mrs r	A. KINGSBURY CO	
	Mc Manus James A r	A. KINGSBURY CO	
	Mc Manus Margaret Miss r	A. KINGSBURY CO	

FINDINGS

Year	Uses	Source	
1906	Mc Manus Rosie C Miss r	A. KINGSBURY CO	
	Mc Manus Wm P teamster r	A. KINGSBURY CO	

428 E SONORA ST

Year	Uses	Source	
2017	JAMES YEH	Cole Information Services	
2014	JAMES YEH	Cole Information Services	
2009	HSIN YEH	Cole Information Services	
2004	HSIN YEH	Cole Information Services	
1999	HSIN YEH	Cole Information Services	
	MEI MAH	Cole Information Services	
	Mah Mel L	R. L. Polk Co., Publishers	Image pg. A5
	Not Verified	R. L. Polk Co., Publishers	Image pg. A5
1996	Mah Mei L	R. L. Polk Co., Publishers	Image pg. A12
1994	LEUNG, JIMMY	Cole Information Services	
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A20
	Vacant	R. L. Polk Co., Publishers	Image pg. A20
	Vacant	R. L. Polk Co., Publishers	Image pg. A20
	Quong Joe D	R. L. Polk Co., Publishers	Image pg. A20
	Mah Mei Lin	R. L. Polk Co., Publishers	Image pg. A20
	Criespino Jose	R. L. Polk Co., Publishers	Image pg. A20
	Leung Jimmy	R. L. Polk Co., Publishers	Image pg. A20
1979	Apartments	R.L. Polk CO.	Image pg. A53
	Mah Teddy G	R.L. Polk CO.	Image pg. A53
	No Return	R.L. Polk CO.	Image pg. A53
	Mah Mei Lin	R.L. Polk CO.	Image pg. A53
	Crespino Jose	R.L. Polk CO.	Image pg. A53
	Reyes Felicino	R.L. Polk CO.	Image pg. A53
	Leung Chow Fung	R.L. Polk CO.	Image pg. A53
1975	Apartments	R.L. Polk CO.	Image pg. A61
	Mah Teddy G	R.L. Polk CO.	Image pg. A61
	Keong Kam Ah	R.L. Polk CO.	Image pg. A61
	Lee Tai Tom	R.L. Polk CO.	Image pg. A61

FINDINGS

Year	Uses	Source	
1975	Mah Mai Lin	R.L. Polk CO.	Image pg. A61
	Bu Pack	R.L. Polk CO.	Image pg. A61
	Chong Gee	R.L. Polk CO.	Image pg. A61
1970	Apartments	R. L. Polk Co., Publishers	Image pg. A69
	Mah Teddy G	R. L. Polk Co., Publishers	Image pg. A69
	Yan Yuk Poi	R. L. Polk Co., Publishers	Image pg. A69
	Vacant	R. L. Polk Co., Publishers	Image pg. A69
	Toy Wm	R. L. Polk Co., Publishers	Image pg. A69
	Vacant	R. L. Polk Co., Publishers	Image pg. A69
1940	Dutra Connie Mrs	R. L. Polk Co., Publishers	Image pg. A119
	Hoard G A	R. L. Polk Co., Publishers	Image pg. A119
	Lucky Hazel Mrs	R. L. Polk Co., Publishers	Image pg. A119
	Meneley J B	R. L. Polk Co., Publishers	Image pg. A119
1911	Castle Lillian M asst A J Gilbert b	Polk-Husted Directory	
	Castle Thos Castle & Barsi h	Polk-Husted Directory	
	Evans Richd clk F Gunzendorfer r	Polk-Husted Directory	
	glianelli Jas Gianelli & Haw s r	Polk-Husted Directory	
	Johnson Chas V v pres Peerless Cash Store r	Polk-Husted Directory	
	Kappenberg Albert clk I X L Clo Co b	Polk-Husted Directory	
	Peri Jos M clk P r	Polk-Husted Directory	
	Stearns Geo foremn Crow n Mills r	Polk-Husted Directory	
1906	Castle Lillian M Miss r	A. KINGSBURY CO	
	Castle Margaret M Miss r	A. KINGSBURY CO	
	Castle Thos Castle & Mc Erlane r	A. KINGSBURY CO	
	Gilbert Adrian J dentist	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Kappenburg Jack clk I X L r	A. KINGSBURY CO	
	Manning Robert molder r	A. KINGSBURY CO	
	Robinson Jere architect r	A. KINGSBURY CO	
	Stearns F foreman C W & W Co r	A. KINGSBURY CO	

FINDINGS

432 E SONORA ST

Year	Uses	Source	
2009	MARIA CHAVEZ	Cole Information Services	
2004	SABRINA MITCHELL	Cole Information Services	
1999	MARIA CHAVEZ	Cole Information Services	
	Reynolds Henry A	R. L. Polk Co., Publishers	Image pg. A5
1996	Reynolds Henry A	R. L. Polk Co., Publishers	Image pg. A12
1994	REYNOLDS, HENRY A	Cole Information Services	
1990	Reynolds Henry A	R. L. Polk Co., Publishers	Image pg. A20
1979	Reynolds Henry A	R.L. Polk CO.	Image pg. A53
1975	Reynolds Henry A	R.L. Polk CO.	Image pg. A61
1970	Reynolds Henry A	R. L. Polk Co., Publishers	Image pg. A69
1940	AReynolds F A	R. L. Polk Co., Publishers	Image pg. A119
1911	Miller Harry L clk W P Fuller & Co h	Polk-Husted Directory	
	Seith Carl F clk W F Kuhn r	Polk-Husted Directory	
	Seith Grover V lab S P Co r	Polk-Husted Directory	
	Smyers Chas D baggagemn S P Co r	Polk-Husted Directory	
1906	Eperson Clem emp S Trans Co r	A. KINGSBURY CO	
	Schroebel Adeline E Mrs r	A. KINGSBURY CO	
	Schroebel Daniel H bkpr J Gianelli r	A. KINGSBURY CO	
	Schroebel Richard R r	A. KINGSBURY CO	

434 E SONORA ST

Year	Uses	Source	
1940	Miller Ida Mrs	R. L. Polk Co., Publishers	Image pg. A119

436 E SONORA ST

Year	Uses	Source	
2014	MARIELA CCORCINO	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
1979	Vacant	R.L. Polk CO.	Image pg. A53
1975	Lascano Manuel	R.L. Polk CO.	Image pg. A61
1970	Manous John	R. L. Polk Co., Publishers	Image pg. A69
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119

Year	Uses	Source
1911	Barth Wm A foremn Aurora Eng Co h	Polk-Husted Directory

437 E SONORA ST

Year	Uses	Source
1911	Call Harry W messr W F & Co Exp b	Polk-Husted Directory
	Forth Wnj hlpr Builders Iron Wks b	Polk-Husted Directory
	Hopkins Bate C hlpr Stkn Trans Co b	Polk-Husted Directory
	Lemon Louis L hngr Blanchard G Co b	Polk-Husted Directory
	Lemon Walter W h	Polk-Husted Directory
	Lemon Wm W painter b	Polk-Husted Directory
1906	Boss Andrew mach Samson Iron Works r	A. KINGSBURY CO
	Buckland Martha A Mrs r	A. KINGSBURY CO
	Boss Laura Miss r	A. KINGSBURY CO
	Boss Augusta Miss opr S T & T Co r	A. KINGSBURY CO

438 E SONORA ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	CHARLES WALKER	Cole Information Services	
1999	CHARLES WALKER	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
1975	Vargas Jesus	R.L. Polk CO.	Image pg. A61
1970	Lascano Manuel	R. L. Polk Co., Publishers	Image pg. A69
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A119

440 E SONORA ST

Year	Uses	Source	
2009	MARCUS SMITH	Cole Information Services	
1999	MARCUS SMITH	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20
1975	Martinez	R.L. Polk CO.	Image pg. A61
1970	Rojo Ajapito N	R. L. Polk Co., Publishers	Image pg. A69
1940	Meneley J B	R. L. Polk Co., Publishers	Image pg. A119
	Vacant	R. L. Polk Co., Publishers	Image pg. A119

FINDINGS

442 E SONORA ST

Year	Uses	Source	
2014	JORGE ABREGO	Cole Information Services	

443 E SONORA ST

Year	Uses	Source	
1999	Todd Phillip	R. L. Polk Co., Publishers	Image pg. A5
	Escher Crystal	R. L. Polk Co., Publishers	Image pg. A5
	Phelps Nancy P	R. L. Polk Co., Publishers	Image pg. A5
	Noble David D	R. L. Polk Co., Publishers	Image pg. A5
1996	Bitanga Cristi	R. L. Polk Co., Publishers	Image pg. A12
	Smith Stanley	R. L. Polk Co., Publishers	Image pg. A12
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A20

445 E SONORA ST

Year	Uses	Source	
1979	Luneta Restaurant	R.L. Polk CO.	Image pg. A53

HAZELTON E

319 HAZELTON E

Year	Uses	Source	
1925	Maspla Jos	R. L. Polk Co. of California, Publishers	Image pg. A148
1921	Norris J A	Polk-Husted Directory Co., Publishers	Image pg. A159
	Gale J M	Polk-Husted Directory Co., Publishers	Image pg. A159
1916	Mugg 0 V	Polk-Husted Directory Co.	Image pg. A168

321 HAZELTON E

Year	Uses	Source	
1925	Clark Frank	R. L. Polk Co. of California, Publishers	Image pg. A148
1921	Giraldo A F	Polk-Husted Directory Co., Publishers	Image pg. A159
	Brow n Walter	Polk-Husted Directory Co., Publishers	Image pg. A159
1916	Amotzbehere Chas	Polk-Husted Directory Co.	Image pg. A168
	Vacant	Polk-Husted Directory Co.	Image pg. A168

FINDINGS

327 HAZELTON E

Year	Uses	Source	
1925	Taboado Marcelino	R. L. Polk Co. of California, Publishers	Image pg. A148
1921	Molen H E	Polk-Husted Directory Co., Publishers	Image pg. A159
	Mullaly J L	Polk-Husted Directory Co., Publishers	Image pg. A159
1916	Mullally J L	Polk-Husted Directory Co.	Image pg. A168
	Dean J M	Polk-Husted Directory Co.	Image pg. A168

335 HAZELTON E

Year	Uses	Source	
1925	Hoult W J	R. L. Polk Co. of California, Publishers	Image pg. A148
1921	Peri J M	Polk-Husted Directory Co., Publishers	Image pg. A159
1916	Peri J M	Polk-Husted Directory Co.	Image pg. A168

345 HAZELTON E

Year	Uses	Source	
1925	Dallas Geo	R. L. Polk Co. of California, Publishers	Image pg. A148

HAZELTON AVE E

240 HAZELTON AVE E

Year	Uses	Source	
1960	Cadloni Jas E	R. L. Polk Co., Publishers	Image pg. A85
1955	Tranquility Rooms	R. L. Polk Co.	Image pg. A92
1950	Traner J F	R. L. Polk Co., Publishers	Image pg. A103
	Johnson E A	R. L. Polk Co., Publishers	Image pg. A103
1946	Johnson E A	R. L. Polk Co., Publishers	Image pg. A110

241 HAZELTON AVE E

Year	Uses	Source	
1965	d JONES RAY C 0 H	R. L. Polk Co., Publishers	Image pg. A76

304 HAZELTON AVE E

Year	Uses	Source	
1984	El Dorado Farm Labor Service	R. L. Polk Co., Publishers	Image pg. A28

FINDINGS

308 HAZELTON AVE E

Year	Uses	Source	
2003	CHINA NOODLE FACTORY	SBC PACIFIC BELL	
1984	China Noodle Factory	R. L. Polk Co., Publishers	Image pg. A28

319 HAZELTON AVE E

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A77
1960	Burton S J	R. L. Polk Co., Publishers	Image pg. A85
	Mack Ann Mrs	R. L. Polk Co., Publishers	Image pg. A85
1955	Vacant	R. L. Polk Co.	Image pg. A92
	Crittle Vivian Mrs	R. L. Polk Co.	Image pg. A92
1950	Whiteside S B	R. L. Polk Co., Publishers	Image pg. A103
	Gatew ood Willie	R. L. Polk Co., Publishers	Image pg. A103
1946	Whiteside S B	R. L. Polk Co., Publishers	Image pg. A110
	Rubalcaba R J	R. L. Polk Co., Publishers	Image pg. A110
1935	Lopez Victor	R. L. Polk Co. of California, Publishers	Image pg. A125
1930	Villamor Roberto	R. L. Polk Co. of California, Publishers	Image pg. A135

321 HAZELTON AVE E

Year	Uses	Source	
1965	WILLIAMS HENRY	R. L. Polk Co., Publishers	Image pg. A77
	k BELL JOHN	R. L. Polk Co., Publishers	Image pg. A77
1960	Williams Emmerlee Mrs	R. L. Polk Co., Publishers	Image pg. A85
	Cox Addie Mrs	R. L. Polk Co., Publishers	Image pg. A85
1955	Williams Emmerlee Mrs	R. L. Polk Co.	Image pg. A92
	Roberson Reuben	R. L. Polk Co.	Image pg. A92
1950	Estrada Casilda Mrs	R. L. Polk Co., Publishers	Image pg. A103
	Williams Henry	R. L. Polk Co., Publishers	Image pg. A103
1946	Estrada Jos	R. L. Polk Co., Publishers	Image pg. A110
	Willisms Henry	R. L. Polk Co., Publishers	Image pg. A110
	Parker Jos	R. L. Polk Co., Publishers	Image pg. A110
1935	Meoqui Peter o	R. L. Polk Co. of California, Publishers	Image pg. A125
	Iturriria Peter	R. L. Polk Co. of California, Publishers	Image pg. A125
1930	Garay Frank	R. L. Polk Co. of California, Publishers	Image pg. A135

FINDINGS

Year	Uses	Source	
1930	Maspla J S o	R. L. Polk Co. of California, Publishers	Image pg. A135

327 HAZELTON AVE E

Year	Uses	Source	
1984	Mark Ken W	R. L. Polk Co., Publishers	Image pg. A28
1965	YOUNG FRANK 0 H	R. L. Polk Co., Publishers	Image pg. A77
1960	Young Frank	R. L. Polk Co., Publishers	Image pg. A85
1955	Young Frank 0	R. L. Polk Co.	Image pg. A92
1950	Young Frank	R. L. Polk Co., Publishers	Image pg. A103
1946	Ware Frank	R. L. Polk Co., Publishers	Image pg. A110
1935	Garay Frank	R. L. Polk Co. of California, Publishers	Image pg. A125
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A135

335 HAZELTON AVE E

Year	Uses	Source	
1984	Mar Stephen M	R. L. Polk Co., Publishers	Image pg. A28
1965	MAR PON SHEE MRS H	R. L. Polk Co., Publishers	Image pg. A77
1960	Mar Dan Sing	R. L. Polk Co., Publishers	Image pg. A85
1955	Mar Tin Shen	R. L. Polk Co.	Image pg. A92
1950	Mar Ton Hong	R. L. Polk Co., Publishers	Image pg. A103
1946	Mar Tonii Hong	R. L. Polk Co., Publishers	Image pg. A110
1935	Low Dick	R. L. Polk Co. of California, Publishers	Image pg. A125
1930	Low Dick	R. L. Polk Co. of California, Publishers	Image pg. A135

345 HAZELTON AVE E

Year	Uses	Source	
2003	Abarca Callejas Alberto	SBC PACIFIC BELL	
1984	Thamala Seth	R. L. Polk Co., Publishers	Image pg. A28
1965	MORGAN AMOS	R. L. Polk Co., Publishers	Image pg. A77
1960	Lopez Herminia Mrs	R. L. Polk Co., Publishers	Image pg. A85
1955	Lene Evelyn F Mrs	R. L. Polk Co.	Image pg. A92
1950	Fotheringham Clara	R. L. Polk Co., Publishers	Image pg. A103
1935	Carls R C Mrs	R. L. Polk Co. of California, Publishers	Image pg. A125
1930	Carde B A	R. L. Polk Co. of California, Publishers	Image pg. A135

FINDINGS

HUNTER S

213 HUNTER S

Year	Uses	Source	
1960	Bow on Assn	R. L. Polk Co., Publishers	Image pg. A86
1955	Bow On Assn	R. L. Polk Co.	Image pg. A93
1950	Bow On Assn	R. L. Polk Co., Publishers	Image pg. A104
1946	Tong Quock	R. L. Polk Co., Publishers	Image pg. A111
	Lam Geo	R. L. Polk Co., Publishers	Image pg. A111
1935	Tong Lin	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Tsue Lock Ting furn	R. L. Polk Co. of California, Publishers	Image pg. A136
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160

215 HUNTER S

Year	Uses	Source	
1960	Fung Lee Gro	R. L. Polk Co., Publishers	Image pg. A86
1955	Fung Lee Gro w hse	R. L. Polk Co.	Image pg. A93
1950	Poa S H herbs	R. L. Polk Co., Publishers	Image pg. A104
1946	Gee Duck Sang herbs	R. L. Polk Co., Publishers	Image pg. A111
1935	Bong Tee Tong genl	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yee Lee	R. L. Polk Co. of California, Publishers	Image pg. A136
	Yee Lee Co genl	R. L. Polk Co. of California, Publishers	Image pg. A136

217 HUNTER S

Year	Uses	Source	
1960	Mabini Lodge No	R. L. Polk Co., Publishers	Image pg. A86
1955	Mabini Lodge No	R. L. Polk Co.	Image pg. A93
1950	Mabini Lodge No	R. L. Polk Co., Publishers	Image pg. A104
1946	Mabini Lodge No	R. L. Polk Co., Publishers	Image pg. A111
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Lee G M cigars	R. L. Polk Co. of California, Publishers	Image pg. A136
	Oriental Herb Co	R. L. Polk Co. of California, Publishers	Image pg. A136

FINDINGS

219 HUNTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A86
1955	Vacant	R. L. Polk Co.	Image pg. A93
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A104
1946	Bing Kee Co geni	R. L. Polk Co., Publishers	Image pg. A111
1935	Bing Kee Co geniil	R. L. Polk Co. of California, Publishers	Image pg. A126
	Hong Hing	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Hong Jim genl mdse	R. L. Polk Co. of California, Publishers	Image pg. A136

221 HUNTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A86
1950	On Kon gro	R. L. Polk Co., Publishers	Image pg. A104
1946	Sun Hing Lung Co gro	R. L. Polk Co., Publishers	Image pg. A111
1935	Valverde Ralph bil	R. L. Polk Co. of California, Publishers	Image pg. A126
	liards	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Jen Hong Hung restr	R. L. Polk Co. of California, Publishers	Image pg. A136

223 HUNTER S

Year	Uses	Source	
1960	Quong Chow Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A86
	Toy Woo	R. L. Polk Co., Publishers	Image pg. A86
1955	Quong Chow Hotel	R. L. Polk Co.	Image pg. A93
	Toy v Vong	R. L. Polk Co.	Image pg. A93
1950	Toy Charley	R. L. Polk Co., Publishers	Image pg. A104
	Ouong Chow Hotel	R. L. Polk Co., Publishers	Image pg. A104
1946	Toy Suey	R. L. Polk Co., Publishers	Image pg. A111
	AQuong Chow Hotel	R. L. Polk Co., Publishers	Image pg. A111
1935	Quong Chow Hotel	R. L. Polk Co. of California, Publishers	Image pg. A126
	Suey Toy	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Sney Toy	R. L. Polk Co. of California, Publishers	Image pg. A136
	Quong Chow Hotel	R. L. Polk Co. of California, Publishers	Image pg. A136
1921	Quong Chow Hotel	Polk-Husted Directory Co., Publishers	Image pg. A160

FINDINGS

225 HUNTER S

Year	Uses	Source	
1960	Kon Sun Gro	R. L. Polk Co., Publishers	Image pg. A86
	Kon Sun	R. L. Polk Co., Publishers	Image pg. A86
1955	Kon Sun Gro	R. L. Polk Co.	Image pg. A93
	On Kon	R. L. Polk Co.	Image pg. A93
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A104
1946	ADe Lucchi Lorenzo	R. L. Polk Co., Publishers	Image pg. A111
	liquors	R. L. Polk Co., Publishers	Image pg. A111
1935	Jones Market fish	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Jones Market	R. L. Polk Co. of California, Publishers	Image pg. A137
	Low Jones	R. L. Polk Co. of California, Publishers	Image pg. A137

227 HUNTER S

Year	Uses	Source	
1960	Hoo Kee Noodle Fcty	R. L. Polk Co., Publishers	Image pg. A86
1955	Hoo Keed Noodle mfrs h	R. L. Polk Co.	Image pg. A93
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A104
1946	Yick Lung Co genl	R. L. Polk Co., Publishers	Image pg. A111
1935	Yick Lung Co genl	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yick Lung Co geni	R. L. Polk Co. of California, Publishers	Image pg. A137

229 HUNTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A86
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A104
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A111
1935	Midnight Mission	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137

231 HUNTER S

Year	Uses	Source	
1960	Park Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A86
	Takahashi Shiguero	R. L. Polk Co., Publishers	Image pg. A86
1955	Park Hotel	R. L. Polk Co.	Image pg. A93

FINDINGS

Year	Uses	Source	
1950	Park Hotel	R. L. Polk Co., Publishers	Image pg. A104
1946	Nga Cabarba	R. L. Polk Co., Publishers	Image pg. A111
	Park Hotel	R. L. Polk Co., Publishers	Image pg. A111
1935	Mitchell Bernice Mrs	R. L. Polk Co. of California, Publishers	Image pg. A126
	Venice Hotel	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yick Lung	R. L. Polk Co. of California, Publishers	Image pg. A137
	Hirano S	R. L. Polk Co. of California, Publishers	Image pg. A137
	New Venice Hotel	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	New Venice Hotel	R. L. Polk Co. of California, Publishers	Image pg. A149

233 HUNTER S

Year	Uses	Source	
1960	Besss Clothing Shop used	R. L. Polk Co., Publishers	Image pg. A86
1955	Roberts Telev Radio Serv	R. L. Polk Co.	Image pg. A93
1946	Yock Lee barber	R. L. Polk Co., Publishers	Image pg. A111
1935	Yick Lee barber	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yick Lee barber	R. L. Polk Co. of California, Publishers	Image pg. A137
	Fong Gee	R. L. Polk Co. of California, Publishers	Image pg. A137

235 HUNTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A86
1930	Choi Edw	R. L. Polk Co. of California, Publishers	Image pg. A137
	Wing Hing Co	R. L. Polk Co. of California, Publishers	Image pg. A137

237 HUNTER S

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A93
1950	AVetter Plmbg Co	R. L. Polk Co., Publishers	Image pg. A104
1946	AVetter Plmbg Co	R. L. Polk Co., Publishers	Image pg. A111
1935	Vetter Bros plmbrs	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137

FINDINGS

239 HUNTER S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Ning Yung Benev	R. L. Polk Co. of California, Publishers	Image pg. A137
	olent Assn Chin	R. L. Polk Co. of California, Publishers	Image pg. A137

241 HUNTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A86
	Linden Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A86
	Queppet Numeriano	R. L. Polk Co., Publishers	Image pg. A86
1955	Mohamed Wali	R. L. Polk Co.	Image pg. A93
	Helena Rooms	R. L. Polk Co.	Image pg. A93
1950	AHelena Rooms	R. L. Polk Co., Publishers	Image pg. A104
1946	Lamar Helen	R. L. Polk Co., Publishers	Image pg. A111
	AHelena Rooms	R. L. Polk Co., Publishers	Image pg. A111
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yee Leun	R. L. Polk Co. of California, Publishers	Image pg. A137

243 HUNTER S

Year	Uses	Source	
1960	Stevens Printing Serv	R. L. Polk Co., Publishers	Image pg. A86
1955	Vacant	R. L. Polk Co.	Image pg. A93
1950	ATroxell Agnes Mrs cldo	R. L. Polk Co., Publishers	Image pg. A104
1935	French Hotel	R. L. Polk Co. of California, Publishers	Image pg. A126
	Olcomendy lDominic	R. L. Polk Co. of California, Publishers	Image pg. A126

245 HUNTER S

Year	Uses	Source	
1960	Square Deal Liquor	R. L. Polk Co., Publishers	Image pg. A86
1955	Square Deal Liquor	R. L. Polk Co.	Image pg. A93
1950	a Paynee Ardie liquors	R. L. Polk Co., Publishers	Image pg. A104
1916	Chan Rev H F	Polk-Husted Directory Co.	Image pg. A169

FINDINGS

303 HUNTER S

Year	Uses	Source	
1925	Hotel Espanol	R. L. Polk Co. of California, Publishers	Image pg. A149
	Lagarra Mrs Eulalia	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Legara Severiano	Polk-Husted Directory Co., Publishers	Image pg. A160
	Hotel Espanol	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Legarra Severnio	Polk-Husted Directory Co.	Image pg. A169
	Hotel Espanol	Polk-Husted Directory Co.	Image pg. A169

312 HUNTER S

Year	Uses	Source	
1955	WVong Wah Sing	R. L. Polk Co.	Image pg. A93
1950	Lee Gong	R. L. Polk Co., Publishers	Image pg. A104
1946	Lee Quong	R. L. Polk Co., Publishers	Image pg. A111
1935	:114 Fong Jick	R. L. Polk Co. of California, Publishers	Image pg. A126
	Lee Quong	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Ah Fong	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Carruesco Manuel	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Rossi A M	Polk-Husted Directory Co.	Image pg. A169

314 HUNTER S

Year	Uses	Source	
1960	Cuison Cesar	R. L. Polk Co., Publishers	Image pg. A86
1955	Fong Wing Mrs	R. L. Polk Co.	Image pg. A93
1950	AYip R C	R. L. Polk Co., Publishers	Image pg. A104
1946	AFong Jick	R. L. Polk Co., Publishers	Image pg. A111
1930	Chin King	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Vacant	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Delucchi J A	Polk-Husted Directory Co.	Image pg. A169

315 HUNTER S

Year	Uses	Source
2003	EMERALD CHINESE RESTAURANT	SBC PACIFIC BELL

FINDINGS

316 HUNTER S

Year	Uses	Source	
1960	Villanueva Victorino R	R. L. Polk Co., Publishers	Image pg. A86
1955	Ling Chin	R. L. Polk Co.	Image pg. A93
1950	Ling Chin	R. L. Polk Co., Publishers	Image pg. A104
1935	Chin King	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Cham Bing	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Medina Angelina	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Medina Mrs Angelina	Polk-Husted Directory Co.	Image pg. A169

325 HUNTER S

Year	Uses	Source	
2003	WING WAH DELI MKT	SBC PACIFIC BELL	
	Pangan Andrew S	SBC PACIFIC BELL	
1960	Wool Growers Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A86
	Wool Growers Inn 0 Restr 4 H	R. L. Polk Co., Publishers	Image pg. A86
	Mariones Benj	R. L. Polk Co., Publishers	Image pg. A86
1955	Wool Growers Hotel	R. L. Polk Co.	Image pg. A93
	Wool Growers Inn tavern	R. L. Polk Co.	Image pg. A93
	Mariones Benj	R. L. Polk Co.	Image pg. A93
1950	Moriones Benj	R. L. Polk Co., Publishers	Image pg. A104
	Moriones Thleresa Mrs	R. L. Polk Co., Publishers	Image pg. A104
	liquors	R. L. Polk Co., Publishers	Image pg. A104
	Wool Growers Hotel	R. L. Polk Co., Publishers	Image pg. A104
1946	AMoriones Theresa Mrs	R. L. Polk Co., Publishers	Image pg. A111
1930	furn rms	R. L. Polk Co. of California, Publishers	Image pg. A137
	Kitahara Tachizuro	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1916	Riccolt Peter	Polk-Husted Directory Co.	Image pg. A169
	Hotel Basco	Polk-Husted Directory Co.	Image pg. A169

328 HUNTER S

Year	Uses	Source	
1960	Confucious Playground	R. L. Polk Co., Publishers	Image pg. A86

FINDINGS

333 HUNTER S

Year	Uses	Source	
2003	SUN WRONG KEE INC	SBC PACIFIC BELL	
1930	Di Bartolo Jos livery stable	R. L. Polk Co. of California, Publishers	Image pg. A137

336 HUNTER S

Year	Uses	Source
2003	LOUIES GARAGE	SBC PACIFIC BELL

341 HUNTER S

Year	Uses	Source	
1955	Trinity Presby Ch	R. L. Polk Co.	Image pg. A93
1950	ALegare M B S R tev	R. L. Polk Co., Publishers	Image pg. A104
	Trinity Presbyterian Ch	R. L. Polk Co., Publishers	Image pg. A104
1946	Legare M B Rev	R. L. Polk Co., Publishers	Image pg. A111
	Trinity Presbyterian	R. L. Polk Co., Publishers	Image pg. A111
1935	Errecart Anna Mrs	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Lacasta Edw	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Errcert John	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Royal Hotel	Polk-Husted Directory Co., Publishers	Image pg. A160
	Baijorri Pet	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Hotel Royal	Polk-Husted Directory Co.	Image pg. A169
	Hunter Carrie M	Polk-Husted Directory Co.	Image pg. A169
	Mentaberry Peter	Polk-Husted Directory Co.	Image pg. A169

401 HUNTER S

Year	Uses	Source	
1960	Toy June L Mrs	R. L. Polk Co., Publishers	Image pg. A86
1955	Street continued	R. L. Polk Co.	Image pg. A93
	Vacant	R. L. Polk Co.	Image pg. A93
	Toy Harry	R. L. Polk Co.	Image pg. A93
	Lee Shung	R. L. Polk Co.	Image pg. A93
	Ching Kee Wong	R. L. Polk Co.	Image pg. A93
	Apartments	R. L. Polk Co.	Image pg. A93
	Suey Kenneth	R. L. Polk Co.	Image pg. A93

FINDINGS

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A93
	Lee Foo	R. L. Polk Co.	Image pg. A93
1950	Chling Wong	R. L. Polk Co., Publishers	Image pg. A104
	AHui H S	R. L. Polk Co., Publishers	Image pg. A104
	Lee Mable Mrs	R. L. Polk Co., Publishers	Image pg. A104
	Lee Shung	R. L. Polk Co., Publishers	Image pg. A104
	Wong F Y	R. L. Polk Co., Publishers	Image pg. A104
	AYee Geo	R. L. Polk Co., Publishers	Image pg. A104
	AChew Jas	R. L. Polk Co., Publishers	Image pg. A104
1946	Wong Frank	R. L. Polk Co., Publishers	Image pg. A111
	Jean W K	R. L. Polk Co., Publishers	Image pg. A111
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Uriarte Thos	R. L. Polk Co. of California, Publishers	Image pg. A137
	Achurra Domingo	R. L. Polk Co. of California, Publishers	Image pg. A137
	Estrella Hotel	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Uriarte Thos	R. L. Polk Co. of California, Publishers	Image pg. A149
	Estrella Hotel	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Solaegui Jos	Polk-Husted Directory Co., Publishers	Image pg. A160
	Estrella Hotel	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Deicas Valentine	Polk-Husted Directory Co.	Image pg. A169
	Lombard Hotel	Polk-Husted Directory Co.	Image pg. A169

405 HUNTER S

Year	Uses	Source
2003	Martinez Salvador	SBC PACIFIC BELL

414 HUNTER S

Year	Uses	Source	
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Sal Ho Hong	R. L. Polk Co. of California, Publishers	Image pg. A137

415 HUNTER S

Year	Uses	Source
2003	Garcia Joaquin E	SBC PACIFIC BELL

FINDINGS

Year	Uses	Source	
1960	Trinmillos Ben M	R. L. Polk Co., Publishers	Image pg. A86
1955	Jacob Jorge A	R. L. Polk Co.	Image pg. A93
1950	Jacob J A	R. L. Polk Co., Publishers	Image pg. A104
1946	AGainza Jesusa Mrs	R. L. Polk Co., Publishers	Image pg. A111
1935	Gainza Andrtes o	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Armolea Benj	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Solaequi Jos	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Potts Mrs Anna	Polk-Husted Directory Co.	Image pg. A169

418 HUNTER S

Year	Uses	Source	
1960	Louie Yee P	R. L. Polk Co., Publishers	Image pg. A86
1955	Louie Yee P	R. L. Polk Co.	Image pg. A93
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A104
1946	Mah Frank	R. L. Polk Co., Publishers	Image pg. A111
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Gianelli G B gro	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Gianelli G B	Polk-Husted Directory Co.	Image pg. A169

420 HUNTER S

Year	Uses	Source	
1960	Wong Choon	R. L. Polk Co., Publishers	Image pg. A86
1955	Dong Kim	R. L. Polk Co.	Image pg. A93
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A104
1946	Wing Yee	R. L. Polk Co., Publishers	Image pg. A111
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Leong Edw	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Vacant	Polk-Husted Directory Co.	Image pg. A169

FINDINGS

423 HUNTER S

Year	Uses	Source	
2003	Reyes Guadalupe	SBC PACIFIC BELL	
1960	Tin Yee Kung Shaw Soc AH	R. L. Polk Co., Publishers	Image pg. A86
	Jung Jimmy	R. L. Polk Co., Publishers	Image pg. A86
1955	Loong Kong Tin Ye Society	R. L. Polk Co.	Image pg. A93
1950	Loong Kong Tin Ye	R. L. Polk Co., Publishers	Image pg. A104
	Society	R. L. Polk Co., Publishers	Image pg. A104
1946	Society Chinese	R. L. Polk Co., Publishers	Image pg. A111
	Loong Kong Tin Ye	R. L. Polk Co., Publishers	Image pg. A111
1935	Loong Kong	R. L. Polk Co. of California, Publishers	Image pg. A126
	Tin Yee Society	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Tin Yee Society	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Devereux W W	Polk-Husted Directory Co.	Image pg. A169
	Oyarbide Jos	Polk-Husted Directory Co.	Image pg. A169

424 HUNTER S

Year	Uses	Source	
1960	Turks Parking Lot	R. L. Polk Co., Publishers	Image pg. A86
1955	Liw ang Helen	R. L. Polk Co.	Image pg. A93
1950	Liw anag E R	R. L. Polk Co., Publishers	Image pg. A104
1946	Louie Frank	R. L. Polk Co., Publishers	Image pg. A111
1935	Nacito Antone o	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Nacito Antone	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Koekalin Peter	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Nocito Antonio	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Nacito Anton	Polk-Husted Directory Co.	Image pg. A169

427 HUNTER S

Year	Uses	Source	
2003	Yep Lane	SBC PACIFIC BELL	
1960	Yep Lane	R. L. Polk Co., Publishers	Image pg. A86
1955	Ling Yuet Sun	R. L. Polk Co.	Image pg. A93

Year	Uses	Source	
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A104
1946	Yip Larry	R. L. Polk Co., Publishers	Image pg. A111
1935	Toy Ben	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Toy Gong	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Carroll Michael	Polk-Husted Directory Co.	Image pg. A169

430 HUNTER S

Year	Uses	Source	
1960	Lee See Lum Mrs 1	R. L. Polk Co., Publishers	Image pg. A86
1955	Lee Geo T	R. L. Polk Co.	Image pg. A93
1950	ALee G T	R. L. Polk Co., Publishers	Image pg. A104
1946	Lee Shee Lum	R. L. Polk Co., Publishers	Image pg. A111
1935	Lee Tai Bong herbs	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Chun H K	R. L. Polk Co. of California, Publishers	Image pg. A137
	Kong C W	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Henry M J	Polk-Husted Directory Co.	Image pg. A169

436 HUNTER S

Year	Uses	Source	
1916	Brown Dora wid Chas	Polk-Husted Directory Co.	Image pg. A169

438 HUNTER S

Year	Uses	Source	
1946	Chew Chauncey	R. L. Polk Co., Publishers	Image pg. A111
1935	Brown D P Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A126
	Stevenson I B	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Brown D P Mrs	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Brown Mrs Dora	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Brown Mrs Dorothy	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Levin Leon	Polk-Husted Directory Co.	Image pg. A169

Year	Uses	Source	
1916	Carey Louis	Polk-Husted Directory Co.	Image pg. A169

439 HUNTER S

Year	Uses	Source	
1955	Dimandal Constacio V h	R. L. Polk Co.	Image pg. A93
1950	ARenna Thos	R. L. Polk Co., Publishers	Image pg. A104
1946	ARena Thos	R. L. Polk Co., Publishers	Image pg. A111
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Simpson Wm	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Oriental	Polk-Husted Directory Co.	Image pg. A169

445 HUNTER S

Year	Uses	Source	
1955	Gee Ying	R. L. Polk Co.	Image pg. A93
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A104
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A111
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Oriental	Polk-Husted Directory Co.	Image pg. A169

448 HUNTER S

Year	Uses	Source	
2003	TAQUERIA DOS HERMANOS	SBC PACIFIC BELL	
1960	Turks restr a	R. L. Polk Co., Publishers	Image pg. A86
1955	Bruno & Lena	R. L. Polk Co.	Image pg. A93
1950	liquors	R. L. Polk Co., Publishers	Image pg. A104
	Marraccini Bruno	R. L. Polk Co., Publishers	Image pg. A104
1946	liquors	R. L. Polk Co., Publishers	Image pg. A111
	Marracchini Brano	R. L. Polk Co., Publishers	Image pg. A111
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137

FINDINGS

Year	Uses	Source	
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A160

516 HUNTER S

Year	Uses	Source	
2003	Calimlim Roberto	SBC PACIFIC BELL	
1960	Umino Yonetaro 411	R. L. Polk Co., Publishers	Image pg. A86
1955	Umino Yonetaro	R. L. Polk Co.	Image pg. A93
1950	Unino Y A	R. L. Polk Co., Publishers	Image pg. A104
1946	Frietas Alesandro	R. L. Polk Co., Publishers	Image pg. A111
1935	Arribillaga Jos	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Yiarraz Nicholas	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Evans J J	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Evans J J	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Armistead T E	Polk-Husted Directory Co.	Image pg. A169

517 HUNTER S

Year	Uses	Source
2003	Thao Doua	SBC PACIFIC BELL
	Vang Kang	SBC PACIFIC BELL
	Xiong Yia	SBC PACIFIC BELL

518 HUNTER S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
	Costa Antone	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Hanchett Edw	Polk-Husted Directory Co., Publishers	Image pg. A160

520 HUNTER S

Year	Uses	Source	
1960	Chew Harry A	R. L. Polk Co., Publishers	Image pg. A86
1955	Redin Theo	R. L. Polk Co.	Image pg. A93
1950	ARedin Theo	R. L. Polk Co., Publishers	Image pg. A104
1946	ARedin Theo	R. L. Polk Co., Publishers	Image pg. A111

FINDINGS

Year	Uses	Source	
1935	Ardanaz Jose to	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Ardanaz Jose	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Ardanaz Jose	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Ardanaz Jose	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Gogni Francisco	Polk-Husted Directory Co.	Image pg. A169

527 HUNTER S

Year	Uses	Source	
2003	Lek Loeun	SBC PACIFIC BELL	
	Chanroun Om	SBC PACIFIC BELL	
1960	Chew May Mrs	R. L. Polk Co., Publishers	Image pg. A86
1955	Lao Chew	R. L. Polk Co.	Image pg. A93
1950	ALao Chew	R. L. Polk Co., Publishers	Image pg. A104
1946	Lao Chew	R. L. Polk Co., Publishers	Image pg. A111
1935	Ju See	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Young Quong	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Gonzales J M	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Staysa E G	Polk-Husted Directory Co.	Image pg. A169

528 HUNTER S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A126
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A137
1921	Lores Peter	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Perfetti Peter	Polk-Husted Directory Co.	Image pg. A169

529 HUNTER S

Year	Uses	Source	
1960	Davis Aubrey 1	R. L. Polk Co., Publishers	Image pg. A86
1955	Davis Aubrey	R. L. Polk Co.	Image pg. A93
1950	Davis Mary Mrs	R. L. Polk Co., Publishers	Image pg. A104
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A126

548 HUNTER S

Year	Uses	Source	
1930	Olcomendy Dominic	R. L. Polk Co. of California, Publishers	Image pg. A137
1925	Perez Elroy	R. L. Polk Co. of California, Publishers	Image pg. A149
1921	Basque Hotel	Polk-Husted Directory Co., Publishers	Image pg. A160
	Ospital John	Polk-Husted Directory Co., Publishers	Image pg. A160
	Perez Eloy	Polk-Husted Directory Co., Publishers	Image pg. A160
1916	Ospital John	Polk-Husted Directory Co.	Image pg. A169
	Basque Hotel	Polk-Husted Directory Co.	Image pg. A169

HUNTER ST S

201 HUNTER ST S

Year	Uses	Source	
1984	County Public Defender	R. L. Polk Co., Publishers	Image pg. A29

202 HUNTER ST S

Year	Uses	Source	
1984	County Diet Attorneys Family Support Div	R. L. Polk Co., Publishers	Image pg. A29

213 HUNTER ST S

Year	Uses	Source	
1965	BOW ON ASSN	R. L. Polk Co., Publishers	Image pg. A78

215 HUNTER ST S

Year	Uses	Source	
1965	FUNG LEE GROCERY H 05 C45	R. L. Polk Co., Publishers	Image pg. A78

217 HUNTER ST S

Year	Uses	Source	
1965	MABINI LODGE NO	R. L. Polk Co., Publishers	Image pg. A78

219 HUNTER ST S

Year	Uses	Source	
1965	SUEY SING ASSN CHAMBER OF	R. L. Polk Co., Publishers	Image pg. A78
	LABOR & COMMERCE	R. L. Polk Co., Publishers	Image pg. A78

FINDINGS

221 HUNTER ST S

Year	Uses	Source	
1965	KWONG TUCK WO CO GRO	R. L. Polk Co., Publishers	Image pg. A78

223 HUNTER ST S

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A78

225 HUNTER ST S

Year	Uses	Source	
1965	KON SUN GROCERY H	R. L. Polk Co., Publishers	Image pg. A78
	KON SUN	R. L. Polk Co., Publishers	Image pg. A78

227 HUNTER ST S

Year	Uses	Source	
1965	CHINA NOODLE FACTORY	R. L. Polk Co., Publishers	Image pg. A78

233 HUNTER ST S

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A78

237 HUNTER ST S

Year	Uses	Source	
1965	THE MAIN USED CLO	R. L. Polk Co., Publishers	Image pg. A78

241 HUNTER ST S

Year	Uses	Source	
1965	J VACANT	R. L. Polk Co., Publishers	Image pg. A78
	BONANZA HOTEL	R. L. Polk Co., Publishers	Image pg. A78
	JACKSON FRED	R. L. Polk Co., Publishers	Image pg. A78

243 HUNTER ST S

Year	Uses	Source	
1965	STEVENS PRINTING SERVICE	R. L. Polk Co., Publishers	Image pg. A78

245 HUNTER ST S

Year	Uses	Source	
1965	SQUARE DEAL LIQUOR	R. L. Polk Co., Publishers	Image pg. A78

FINDINGS

303 HUNTER ST S

Year	Uses	Source	
1984	County Assessor	R. L. Polk Co., Publishers	Image pg. A29

304 HUNTER ST S

Year	Uses	Source	
1984	County Recorder	R. L. Polk Co., Publishers	Image pg. A29

314 HUNTER ST S

Year	Uses	Source	
1984	Santana Jose	R. L. Polk Co., Publishers	Image pg. A29
	Hernandez Angel	R. L. Polk Co., Publishers	Image pg. A29
	Fabela Jose	R. L. Polk Co., Publishers	Image pg. A29
1965	RIBULTAN CRIACO	R. L. Polk Co., Publishers	Image pg. A78

315 HUNTER ST S

Year	Uses	Source	
1984	New Emerald Restaurant chinese food	R. L. Polk Co., Publishers	Image pg. A29

316 HUNTER ST S

Year	Uses	Source	
1984	Alvarez Lid	R. L. Polk Co., Publishers	Image pg. A29
1965	CUISON CESAR S	R. L. Polk Co., Publishers	Image pg. A78

325 HUNTER ST S

Year	Uses	Source	
1984	La Perla Rooms Winners Cafe	R. L. Polk Co., Publishers	Image pg. A29
	Louies Garage auto repr	R. L. Polk Co., Publishers	Image pg. A29
	Chin Bock	R. L. Polk Co., Publishers	Image pg. A29
	No Return	R. L. Polk Co., Publishers	Image pg. A29
	Sun Wong Kee restr	R. L. Polk Co., Publishers	Image pg. A29
1965	MARIONES BENJ	R. L. Polk Co., Publishers	Image pg. A78
	WOOL GROWERS HOTEL	R. L. Polk Co., Publishers	Image pg. A78
	LODGINGS H	R. L. Polk Co., Publishers	Image pg. A78
	WOOL GROWERS INN	R. L. Polk Co., Publishers	Image pg. A78

FINDINGS

336 HUNTER ST S

Year	Uses	Source	
1965	CHOY BEN AUTO SERVICE AUTO	R. L. Polk Co., Publishers	Image pg. A78
	REPAIR H	R. L. Polk Co., Publishers	Image pg. A78

401 HUNTER ST S

Year	Uses	Source	
1984	Chau Samuel W	R. L. Polk Co., Publishers	Image pg. A29
	Parel Ben	R. L. Polk Co., Publishers	Image pg. A29
1965	CHAN SAMUEL W REAL EST	R. L. Polk Co., Publishers	Image pg. A78

403 HUNTER ST S

Year	Uses	Source	
1984	Santella Carlos	R. L. Polk Co., Publishers	Image pg. A29
	Bellido Rolando	R. L. Polk Co., Publishers	Image pg. A29
	Bravo Jimmy	R. L. Polk Co., Publishers	Image pg. A29
	Villanueua Apolinario	R. L. Polk Co., Publishers	Image pg. A29
	Apartments	R. L. Polk Co., Publishers	Image pg. A29
	Carrido Fernando	R. L. Polk Co., Publishers	Image pg. A29
1965	SALUDARES SINFOROSO	R. L. Polk Co., Publishers	Image pg. A78
	ULEP VALERYN	R. L. Polk Co., Publishers	Image pg. A78
	TOMAYO HULURY S	R. L. Polk Co., Publishers	Image pg. A78
	APARTMENTS	R. L. Polk Co., Publishers	Image pg. A78
	AOITAN BILL	R. L. Polk Co., Publishers	Image pg. A78

405 HUNTER ST S

Year	Uses	Source	
1965	SALAZAR LUCY MRS	R. L. Polk Co., Publishers	Image pg. A78

415 HUNTER ST S

Year	Uses	Source	
1984	Miro Teodorico	R. L. Polk Co., Publishers	Image pg. A29
1965	REYES FAUSTINO	R. L. Polk Co., Publishers	Image pg. A78

FINDINGS

418 HUNTER ST S

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A29
1965	LOUIE VEE PAI 6 H	R. L. Polk Co., Publishers	Image pg. A78

420 HUNTER ST S

Year	Uses	Source	
1984	Louie Yee Pai	R. L. Polk Co., Publishers	Image pg. A29
1965	WONG CHOON H a H	R. L. Polk Co., Publishers	Image pg. A78

423 HUNTER ST S

Year	Uses	Source	
1984	a Vacant	R. L. Polk Co., Publishers	Image pg. A29
	Clixt Eric	R. L. Polk Co., Publishers	Image pg. A29
1965	SOCIAL H	R. L. Polk Co., Publishers	Image pg. A78
	TIN YEE KUNG SHAW SOCIETY	R. L. Polk Co., Publishers	Image pg. A78

427 HUNTER ST S

Year	Uses	Source	
1984	Yep Gin Lane	R. L. Polk Co., Publishers	Image pg. A29
1965	YEP GIN LAN 0 H	R. L. Polk Co., Publishers	Image pg. A78

430 HUNTER ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A29
1965	TSUE BUT H	R. L. Polk Co., Publishers	Image pg. A78

448 HUNTER ST S

Year	Uses	Source	
1984	Ospitals Villa Basque Inc restr	R. L. Polk Co., Publishers	Image pg. A29
1965	TURKS RESTR H	R. L. Polk Co., Publishers	Image pg. A78

516 HUNTER ST S

Year	Uses	Source	
1984	Umino Yoshi Mrs	R. L. Polk Co., Publishers	Image pg. A29
1965	UMINO ZONETARO H	R. L. Polk Co., Publishers	Image pg. A78

FINDINGS

517 HUNTER ST S

Year	Uses	Source	
1984	Slade Thelma	R. L. Polk Co., Publishers	Image pg. A29
	lHardimon How ard	R. L. Polk Co., Publishers	Image pg. A29
	Porte Joe	R. L. Polk Co., Publishers	Image pg. A29
	Apartments	R. L. Polk Co., Publishers	Image pg. A29
	Fields Earnest	R. L. Polk Co., Publishers	Image pg. A29
	Gutierrez Gregorio	R. L. Polk Co., Publishers	Image pg. A29
	Cabalar Nicholas	R. L. Polk Co., Publishers	Image pg. A29
	Cabeliza Politcarpo	R. L. Polk Co., Publishers	Image pg. A29
	Vacant	R. L. Polk Co., Publishers	Image pg. A29

520 HUNTER ST S

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A78

527 HUNTER ST S

Year	Uses	Source	
1984	Chew May Mrs	R. L. Polk Co., Publishers	Image pg. A29
1965	CHEW MAY MRS 0 H	R. L. Polk Co., Publishers	Image pg. A78

528 HUNTER ST S

Year	Uses	Source	
1984	Wor Daguhoy Lodge No	R. L. Polk Co., Publishers	Image pg. A29

529 HUNTER ST S

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A29
1965	DAVIS AUBREY a H	R. L. Polk Co., Publishers	Image pg. A78

LAFAYETTE E

202 LAFAYETTE E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A87
1955	Vacant	R. L. Polk Co.	Image pg. A94
1950	Reyes S C Mrs beauty	R. L. Polk Co., Publishers	Image pg. A105

Year	Uses	Source	
1950	shlop	R. L. Polk Co., Publishers	Image pg. A105
1946	Hadley T A	R. L. Polk Co., Publishers	Image pg. A112
1935	Nom Yip	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A150
1921	Occupant	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Belluomini Crestina w id	Polk-Husted Directory Co.	Image pg. A170
	Angelo	Polk-Husted Directory Co.	Image pg. A170

204 LAFAYETTE E

Year	Uses	Source	
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A150
1921	Occupant	Polk-Husted Directory Co., Publishers	Image pg. A161

206 LAFAYETTE E

Year	Uses	Source	
1960	St Benedict Convent	R. L. Polk Co., Publishers	Image pg. A87
	Benedectine Sisters	R. L. Polk Co., Publishers	Image pg. A87
1955	Reyes Primitivo	R. L. Polk Co.	Image pg. A94
1950	Reyes Primitivo	R. L. Polk Co., Publishers	Image pg. A105
1946	AGrinstead Ethel Mrs	R. L. Polk Co., Publishers	Image pg. A112
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Mayeda U	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A150
1921	Occupant	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Massei Aurelio	Polk-Husted Directory Co.	Image pg. A170

208 LAFAYETTE E

Year	Uses	Source	
1950	Chinese Assn	R. L. Polk Co., Publishers	Image pg. A105
	Chinese Sch	R. L. Polk Co., Publishers	Image pg. A105
1946	Chinese Sch	R. L. Polk Co., Publishers	Image pg. A112
	Chinese Aun	R. L. Polk Co., Publishers	Image pg. A112
	Chinese Methodist Oh	R. L. Polk Co., Publishers	Image pg. A112

FINDINGS

Year	Uses	Source	
1935	Chinese Assn	R. L. Polk Co. of California, Publishers	Image pg. A127
	Chinese School	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Chinese School	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A150
1921	Occupant	Polk-Husted Directory Co., Publishers	Image pg. A161

210 LAFAYETTE E

Year	Uses	Source	
1960	Chinese Assn	R. L. Polk Co., Publishers	Image pg. A87
1950	Kuo Min Tang Assn	R. L. Polk Co., Publishers	Image pg. A105
	Chinese	R. L. Polk Co., Publishers	Image pg. A105
1946	Kuo Min Tang Asn	R. L. Polk Co., Publishers	Image pg. A112
	Chinese	R. L. Polk Co., Publishers	Image pg. A112
1935	Kuo Min Tong Chin	R. L. Polk Co. of California, Publishers	Image pg. A127
	ese Nationalist Par	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Party	R. L. Polk Co. of California, Publishers	Image pg. A138
	Kuo Min Tang	R. L. Polk Co. of California, Publishers	Image pg. A138
	Chinese Nationalist	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A150

212 LAFAYETTE E

Year	Uses	Source	
2003	CONFUCIUS CHURCH	SBC PACIFIC BELL	
1960	Confucious Ch	R. L. Polk Co., Publishers	Image pg. A87
1955	Confucius Ch	R. L. Polk Co.	Image pg. A94
1950	Confucius Ch	R. L. Polk Co., Publishers	Image pg. A105
1946	Ning VYuni Benevolent	R. L. Polk Co., Publishers	Image pg. A112
1935	Ning Yung Benevolent	R. L. Polk Co. of California, Publishers	Image pg. A127
	Ming Kue Kung Wai	R. L. Polk Co. of California, Publishers	Image pg. A127
	Chinese M E Mission	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Toi Man	R. L. Polk Co. of California, Publishers	Image pg. A138

FINDINGS

214 LAFAYETTE E

Year	Uses	Source	
1950	Chinese Christian	R. L. Polk Co., Publishers	Image pg. A105
	Center	R. L. Polk Co., Publishers	Image pg. A105
1946	Chinese Christian Cen	R. L. Polk Co., Publishers	Image pg. A112
1930	Chinese M E Mission	R. L. Polk Co. of California, Publishers	Image pg. A138

236 LAFAYETTE E

Year	Uses	Source	
1960	St Peters Methodist Ch	R. L. Polk Co., Publishers	Image pg. A87
1955	Vacant	R. L. Polk Co.	Image pg. A94
1950	Christian Center Ch	R. L. Polk Co., Publishers	Image pg. A105
1946	AAtw ood Printing Co	R. L. Polk Co., Publishers	Image pg. A112
1935	Atw ood Printing Co	R. L. Polk Co. of California, Publishers	Image pg. A127
	:108 Mc Leod Jas blksmith	R. L. Polk Co. of California, Publishers	Image pg. A127

243 LAFAYETTE E

Year	Uses	Source	
1925	S Bailey C M	R. L. Polk Co. of California, Publishers	Image pg. A151

308 LAFAYETTE E

Year	Uses	Source	
1960	Graf Battery Co	R. L. Polk Co., Publishers	Image pg. A87
1955	Graf Battery Co	R. L. Polk Co.	Image pg. A95
1950	Graf R M batteries	R. L. Polk Co., Publishers	Image pg. A105
1946	a Mc Leod Jas biksmith	R. L. Polk Co., Publishers	Image pg. A112
1930	ODay D B horse	R. L. Polk Co. of California, Publishers	Image pg. A138
	shoer	R. L. Polk Co. of California, Publishers	Image pg. A138

309 LAFAYETTE E

Year	Uses	Source	
1960	a Alexander Inez C Mrs	R. L. Polk Co., Publishers	Image pg. A87
	b Gray Chas E	R. L. Polk Co., Publishers	Image pg. A87
1955	a Snell Alice C Mrs	R. L. Polk Co.	Image pg. A95
	b Campbell Willie	R. L. Polk Co.	Image pg. A95
1950	No return	R. L. Polk Co., Publishers	Image pg. A105

FINDINGS

Year	Uses	Source	
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A112
	Oriental	R. L. Polk Co., Publishers	Image pg. A112
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127
	a Lee H S	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Wong Benny	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Holman W E	R. L. Polk Co. of California, Publishers	Image pg. A152
	Levy Fredk	R. L. Polk Co. of California, Publishers	Image pg. A152
	Miller Carrie	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Holman Wm	Polk-Husted Directory Co., Publishers	Image pg. A161
	Levy Fredk	Polk-Husted Directory Co., Publishers	Image pg. A161
	Miller Carrie	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	a Brennan J P	Polk-Husted Directory Co.	Image pg. A170
	b Billings WH	Polk-Husted Directory Co.	Image pg. A170

310 LAFAYETTE E

Year	Uses	Source	
1960	Sutton Hubert	R. L. Polk Co., Publishers	Image pg. A87
	Street continued	R. L. Polk Co., Publishers	Image pg. A87
	Gray Parthenia Mrs	R. L. Polk Co., Publishers	Image pg. A87
	Jones Anna B Mrs	R. L. Polk Co., Publishers	Image pg. A87
	Richardson Albert	R. L. Polk Co., Publishers	Image pg. A87
	Apartments	R. L. Polk Co., Publishers	Image pg. A87
1955	la Buckman Kath A Mrs	R. L. Polk Co.	Image pg. A95
	Street continued	R. L. Polk Co.	Image pg. A95
	Jedkins John H	R. L. Polk Co.	Image pg. A95
	Reed Robt	R. L. Polk Co.	Image pg. A95
	Brown Willie B	R. L. Polk Co.	Image pg. A95
	Browie Mattie	R. L. Polk Co.	Image pg. A95
	Apartments	R. L. Polk Co.	Image pg. A95
1950	Terry Jesse	R. L. Polk Co., Publishers	Image pg. A105
	Smith Fred	R. L. Polk Co., Publishers	Image pg. A105
	a Jedkins J H	R. L. Polk Co., Publishers	Image pg. A105
	Ivie Rosa Mrs	R. L. Polk Co., Publishers	Image pg. A105

Year	Uses	Source	
1950	Freeman J A	R. L. Polk Co., Publishers	Image pg. A105
1946	Wiggins L R	R. L. Polk Co., Publishers	Image pg. A112
	Low ery L R	R. L. Polk Co., Publishers	Image pg. A112
	Jedkins J H	R. L. Polk Co., Publishers	Image pg. A112
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127

311 LAFAYETTE E

Year	Uses	Source	
1960	a Buckman Kath A Mrs	R. L. Polk Co., Publishers	Image pg. A87
	b Knight Theona Mrs	R. L. Polk Co., Publishers	Image pg. A87
1955	b Knight Theona	R. L. Polk Co.	Image pg. A95
1950	Buckman K A Mrs	R. L. Polk Co., Publishers	Image pg. A105
	Flavius Flavio	R. L. Polk Co., Publishers	Image pg. A105
1946	Scott Geso	R. L. Polk Co., Publishers	Image pg. A112
1935	a Eymard Marie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A127
	b Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	a Eymard Alex	R. L. Polk Co. of California, Publishers	Image pg. A138
	b Flavius Flavio	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Flavius Flavio	R. L. Polk Co. of California, Publishers	Image pg. A152
	a Eynard Alex	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Nickley J J	Polk-Husted Directory Co., Publishers	Image pg. A161
	a Eymard Alex	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	tave	Polk-Husted Directory Co.	Image pg. A170
	Lestelle Peter	Polk-Husted Directory Co.	Image pg. A170
	Molen H A	Polk-Husted Directory Co.	Image pg. A170
	Taillet Marie w id Gus	Polk-Husted Directory Co.	Image pg. A170

312 LAFAYETTE E

Year	Uses	Source	
1960	Stockton Veterinary Sup Co w hse	R. L. Polk Co., Publishers	Image pg. A87

314 LAFAYETTE E

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127

FINDINGS

316 LAFAYETTE E

Year	Uses	Source	
1930	Hunter Harry	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Krenz F W	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Krenz F W	Polk-Husted Directory Co.	Image pg. A170

317 LAFAYETTE E

Year	Uses	Source	
1960	Jacques Juanita Mrs	R. L. Polk Co., Publishers	Image pg. A87
1955	Jacques Juanita Mrs	R. L. Polk Co.	Image pg. A95
1950	Jacques Juanita Mrs	R. L. Polk Co., Publishers	Image pg. A105
1935	Kong Chin	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Elespre John	Polk-Husted Directory Co.	Image pg. A171

318 LAFAYETTE E

Year	Uses	Source	
1950	Saunders F H w hs	R. L. Polk Co., Publishers	Image pg. A105
1946	Saunders F H w hee	R. L. Polk Co., Publishers	Image pg. A112
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127

329 LAFAYETTE E

Year	Uses	Source	
1960	Brent Johnny B	R. L. Polk Co., Publishers	Image pg. A87
1955	Noce Lazaro furn rooms	R. L. Polk Co.	Image pg. A95
	Neal Lena Mrs	R. L. Polk Co.	Image pg. A95
1950	Avalos Albino	R. L. Polk Co., Publishers	Image pg. A105
	Cimintal Jos	R. L. Polk Co., Publishers	Image pg. A105
	Martinez Mercedes Mrs	R. L. Polk Co., Publishers	Image pg. A105
	Noce D S	R. L. Polk Co., Publishers	Image pg. A105
	Parra Fred	R. L. Polk Co., Publishers	Image pg. A105
	Valenzuela Hlenry	R. L. Polk Co., Publishers	Image pg. A105

FINDINGS

Year	Uses	Source	
1950	Villalobos Doyle	R. L. Polk Co., Publishers	Image pg. A105
1946	Freeman Ray	R. L. Polk Co., Publishers	Image pg. A112
	Guerrero Margarito	R. L. Polk Co., Publishers	Image pg. A112
	Martinez Jos	R. L. Polk Co., Publishers	Image pg. A112
	Noce D S	R. L. Polk Co., Publishers	Image pg. A112
1935	Noce D S o	R. L. Polk Co. of California, Publishers	Image pg. A127
	Page Benny	R. L. Polk Co. of California, Publishers	Image pg. A127
	Acosta Marcelino	R. L. Polk Co. of California, Publishers	Image pg. A127
	Lampito Catalino	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Lampitok Catlino	R. L. Polk Co. of California, Publishers	Image pg. A138
	Noce D S	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Cain Rollie	R. L. Polk Co. of California, Publishers	Image pg. A152
	Gaffney Ray	R. L. Polk Co. of California, Publishers	Image pg. A152
	Cota J C	R. L. Polk Co. of California, Publishers	Image pg. A152
	Mioonstone Apts	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Moonstone Apts	Polk-Husted Directory Co., Publishers	Image pg. A161
	Connelly J S	Polk-Husted Directory Co., Publishers	Image pg. A161
	Lehmann H C	Polk-Husted Directory Co., Publishers	Image pg. A161
	Galiano Mrs Frances	Polk-Husted Directory Co., Publishers	Image pg. A161
	Szabo Mrs Hannah	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Dodge B W	Polk-Husted Directory Co.	Image pg. A171
	Harkins H W	Polk-Husted Directory Co.	Image pg. A171
	Peterson Peter	Polk-Husted Directory Co.	Image pg. A171
	Quinn Mary w id Thos	Polk-Husted Directory Co.	Image pg. A171
	Webber Mrs Agnes	Polk-Husted Directory Co.	Image pg. A171

336 LAFAYETTE E

Year	Uses	Source	
2003	HARDIN ANIMAL HOSPITAL	SBC PACIFIC BELL	
1960	Saunders Francis H vet	R. L. Polk Co., Publishers	Image pg. A87
	Stockton Veterinary Supply Co	R. L. Polk Co., Publishers	Image pg. A87
1955	City Poundmaster	R. L. Polk Co.	Image pg. A95
	Saunders Francis H vet	R. L. Polk Co.	Image pg. A95

FINDINGS

Year	Uses	Source	
1955	Stockton Veterinary Supply Co	R. L. Polk Co.	Image pg. A95
	Anderson Estelle Mrs	R. L. Polk Co.	Image pg. A95
	Ivory Chas	R. L. Polk Co.	Image pg. A95
1950	City Poundmaster	R. L. Polk Co., Publishers	Image pg. A105
	Saunders F H vet surg	R. L. Polk Co., Publishers	Image pg. A105
	Stockton Veterinary	R. L. Polk Co., Publishers	Image pg. A105
	Sup Co	R. L. Polk Co., Publishers	Image pg. A105
1946	City Poundmaster	R. L. Polk Co., Publishers	Image pg. A112
	ASaunders F M vet	R. L. Polk Co., Publishers	Image pg. A112
1935	Saunders F H veterin	R. L. Polk Co. of California, Publishers	Image pg. A127
	arian and livestock	R. L. Polk Co. of California, Publishers	Image pg. A127
	supplies	R. L. Polk Co. of California, Publishers	Image pg. A127
	City Poundmaster	R. L. Polk Co. of California, Publishers	Image pg. A127
	County Veterinarian	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	erinarian	R. L. Polk Co. of California, Publishers	Image pg. A138
	Saunders F H vet	R. L. Polk Co. of California, Publishers	Image pg. A138
	County Veterinarian	R. L. Polk Co. of California, Publishers	Image pg. A138

337 LAFAYETTE E

Year	Uses	Source	
1960	Ivory Charlie	R. L. Polk Co., Publishers	Image pg. A87
1950	Robinson Plover	R. L. Polk Co., Publishers	Image pg. A105
	Britter L D	R. L. Polk Co., Publishers	Image pg. A105
1935	:138 Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127
	Lehmann H C	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Lehmann H C o	R. L. Polk Co. of California, Publishers	Image pg. A138
1916	Lehmann H C	Polk-Husted Directory Co.	Image pg. A171

338 LAFAYETTE E

Year	Uses	Source	
2003	ASIAN FOODMART& BAKE SHOP	SBC PACIFIC BELL	
	LBC MABUHAY U S A ASIAN FOODMART AND	SBC PACIFIC BELL	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A138

FINDINGS

339 LAFAYETTE E

Year	Uses	Source	
1960	Matar Liquor Store	R. L. Polk Co., Publishers	Image pg. A87
1955	Matar Liquor Store	R. L. Polk Co.	Image pg. A95
1950	Matar Joseph liquors	R. L. Polk Co., Publishers	Image pg. A105
1946	Matar JOe liquors	R. L. Polk Co., Publishers	Image pg. A112
1935	Lehmann H C auto	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Lehmann H C auto	R. L. Polk Co. of California, Publishers	Image pg. A138

342 LAFAYETTE E

Year	Uses	Source	
1946	Massone Frank	R. L. Polk Co., Publishers	Image pg. A112
1935	Crotzer Jess	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Moreno Jas	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Stew art Eugene	R. L. Polk Co. of California, Publishers	Image pg. A152
1916	Batemian Murrey	Polk-Husted Directory Co.	Image pg. A171

344 LAFAYETTE E

Year	Uses	Source	
1946	Irvine J R	R. L. Polk Co., Publishers	Image pg. A112
	Sutter Intersect	R. L. Polk Co., Publishers	Image pg. A112
1935	Patterson N R	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Row e Hannah Mrs	R. L. Polk Co. of California, Publishers	Image pg. A138
	Del Rey Rooms	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Szabo Mrs Hannah	R. L. Polk Co. of California, Publishers	Image pg. A152
	Rodriguez Louis	R. L. Polk Co. of California, Publishers	Image pg. A152
1916	Scott Sami	Polk-Husted Directory Co.	Image pg. A171

369 LAFAYETTE E

Year	Uses	Source	
1925	Viverous Mrs A W	R. L. Polk Co. of California, Publishers	Image pg. A152

412 LAFAYETTE E

Year	Uses	Source	
1960	Koe Lew is B AH	R. L. Polk Co., Publishers	Image pg. A87
	a Aqaw a Jas J	R. L. Polk Co., Publishers	Image pg. A87

Year	Uses	Source	
1955	a Nichols Clinton F	R. L. Polk Co.	Image pg. A95
	Koe Lew is B	R. L. Polk Co.	Image pg. A95
1950	Koe L B	R. L. Polk Co., Publishers	Image pg. A105
1946	Koe Lew is	R. L. Polk Co., Publishers	Image pg. A112
1935	Cavalero Philip	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Cavalero Philip o	R. L. Polk Co. of California, Publishers	Image pg. A138
	Cavalero Albina Mrs	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Cavalero Fillipo	R. L. Polk Co. of California, Publishers	Image pg. A152
1921	Cavalero Filippo	Polk-Husted Directory Co., Publishers	Image pg. A161
1916	Wright Cecelia w id W M	Polk-Husted Directory Co.	Image pg. A171
	Mc Cormick Chas	Polk-Husted Directory Co.	Image pg. A171

418 LAFAYETTE E

Year	Uses	Source	
1960	Ecker John F pntr AH	R. L. Polk Co., Publishers	Image pg. A87
1955	Ecker John F pntr	R. L. Polk Co.	Image pg. A95
1950	Dolan E H genl contr	R. L. Polk Co., Publishers	Image pg. A105
	AEcker J F pntr	R. L. Polk Co., Publishers	Image pg. A105
	Hanham D W acct	R. L. Polk Co., Publishers	Image pg. A105
1946	ACurtis A L acet	R. L. Polk Co., Publishers	Image pg. A112
	AEcker J F pntr	R. L. Polk Co., Publishers	Image pg. A112
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A127
1930	Lafayette Plmbg	R. L. Polk Co. of California, Publishers	Image pg. A138
	Sheet Mtl Wks	R. L. Polk Co. of California, Publishers	Image pg. A138
1925	Nielsen Andrew	R. L. Polk Co. of California, Publishers	Image pg. A152

LAFAYETTE ST E

212 LAFAYETTE ST E

Year	Uses	Source	
1984	Confucius Church	R. L. Polk Co., Publishers	Image pg. A30

236 LAFAYETTE ST E

Year	Uses	Source	
1984	Chinese Senior Citizens Center	R. L. Polk Co., Publishers	Image pg. A30

FINDINGS

310 LAFAYETTE ST E

Year	Uses	Source	
1984	Me Neil James	R. L. Polk Co., Publishers	Image pg. A30
	Cruz Eusebio	R. L. Polk Co., Publishers	Image pg. A30
	Early Ireland	R. L. Polk Co., Publishers	Image pg. A30
	Apartments I Richardson Albert J	R. L. Polk Co., Publishers	Image pg. A30

336 LAFAYETTE ST E

Year	Uses	Source	
1984	Hardin Animal Hos	R. L. Polk Co., Publishers	Image pg. A30

338 LAFAYETTE ST E

Year	Uses	Source	
1984	Stockton Veterinary Supply Co	R. L. Polk Co., Publishers	Image pg. A30

412 LAFAYETTE ST E

Year	Uses	Source	
1984	Horton Ra	R. L. Polk Co., Publishers	Image pg. A30
	a Johnson Wayne	R. L. Polk Co., Publishers	Image pg. A30

S HUNTER ST

203 S HUNTER ST

Year	Uses	Source
1906	Armenini John emp Wagner Leather Co r	A. KINGSBURY CO

207 S HUNTER ST

Year	Uses	Source
1906	Garribotto G B Del Monte & Garribotto r	A. KINGSBURY CO

213 S HUNTER ST

Year	Uses	Source	
1940	Lam Geo	R. L. Polk Co., Publishers	Image pg. A120
	Tong Quock	R. L. Polk Co., Publishers	Image pg. A120

215 S HUNTER ST

Year	Uses	Source	
1940	Gee Duck Sang herbs	R. L. Polk Co., Publishers	Image pg. A120

Year	Uses	Source	
1911	Woods Edw F horseshoer	Polk-Husted Directory	

217 S HUNTER ST

Year	Uses	Source	
1940	Mission	R. L. Polk Co., Publishers	Image pg. A120
	Victorious Gospel	R. L. Polk Co., Publishers	Image pg. A120
1906	Law rence Melinda Mrs r	A. KINGSBURY CO	
	Boyle Blanche Mrs actress r	A. KINGSBURY CO	

219 S HUNTER ST

Year	Uses	Source	
1940	Hing Hong Co	R. L. Polk Co., Publishers	Image pg. A120

221 S HUNTER ST

Year	Uses	Source	
1940	a Sun Hing Lung Co	R. L. Polk Co., Publishers	Image pg. A120

223 S HUNTER ST

Year	Uses	Source	
1940	Toy Suey	R. L. Polk Co., Publishers	Image pg. A120
	a Quong Chow Hotel	R. L. Polk Co., Publishers	Image pg. A120

225 S HUNTER ST

Year	Uses	Source	
1940	liquors	R. L. Polk Co., Publishers	Image pg. A120
	a Delucchi Lorenzo	R. L. Polk Co., Publishers	Image pg. A120
1911	MADDEN FRANK P Macldens h	Polk-Husted Directory	
	Madden Geo F appr Samson l Wks b	Polk-Husted Directory	
	Madden Jas L w ith F P Madden h	Polk-Husted Directory	
	Madden J Edw clk Lew is & Johnson b	Polk-Husted Directory	
	Phillips Geo salsn Hedges B Co r	Polk-Husted Directory	
1906	r	A. KINGSBURY CO	
	Madden Edw J student r	A. KINGSBURY CO	
	Madden James L saloon	A. KINGSBURY CO	

FINDINGS

227 S HUNTER ST

Year	Uses	Source	
1940	Yick Lung	R. L. Polk Co., Publishers	Image pg. A120
	AYick Lung Co geni	R. L. Polk Co., Publishers	Image pg. A120

229 S HUNTER ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A120

231 S HUNTER ST

Year	Uses	Source	
1940	a Venice Hotel	R. L. Polk Co., Publishers	Image pg. A120
	Graham Max	R. L. Polk Co., Publishers	Image pg. A120

233 S HUNTER ST

Year	Uses	Source	
1940	Yick Lee barber	R. L. Polk Co., Publishers	Image pg. A120

237 S HUNTER ST

Year	Uses	Source	
1940	a Vetter 0 H plmbr	R. L. Polk Co., Publishers	Image pg. A120

239 S HUNTER ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A120
1911	Cosgrove Thos H City Wharfinger h	Polk-Husted Directory	
1906	Cosgrove Mary Mrs r	A. KINGSBURY CO	
	Cosgrove Thos H r	A. KINGSBURY CO	

241 S HUNTER ST

Year	Uses	Source	
1940	Marlow Jean	R. L. Polk Co., Publishers	Image pg. A120
	Lamar Ellen	R. L. Polk Co., Publishers	Image pg. A120
	a French Hotel	R. L. Polk Co., Publishers	Image pg. A120

243 S HUNTER ST

Year	Uses	Source	
1940	a French Cafe	R. L. Polk Co., Publishers	Image pg. A120

Year	Uses	Source	
1940	Marlow Jean	R. L. Polk Co., Publishers	Image pg. A120

245 S HUNTER ST

Year	Uses	Source
1911	Arnijo Mary A h	Polk-Husted Directory
1906	Mc Culloch Wm J barber r	A. KINGSBURY CO
	Adams Claude G emp Adams & Gist r	A. KINGSBURY CO
	Tucker John E emp Adams & Gist r	A. KINGSBURY CO

303 S HUNTER ST

Year	Uses	Source
1911	CHIORINI ANDREW Bohemian Club Prop Genova Hotel h	Polk-Husted Directory
	Genova Hotel Andrew Chiorini	Polk-Husted Directory
	Verense Geo porter Stauffer & Goldsw orthy r	Polk-Husted Directory
1906	Brondello Michael r	A. KINGSBURY CO
	Chiorini Jos hotel	A. KINGSBURY CO
	Molett Edw lab r	A. KINGSBURY CO
	Damico Tony emp A Arioto r	A. KINGSBURY CO
	Farette Michael lab r	A. KINGSBURY CO
	Garsela Antonio barber r	A. KINGSBURY CO
	Genoa Hotel	A. KINGSBURY CO
	Laparte Augusto lab r	A. KINGSBURY CO
	Conti Teresa Miss r	A. KINGSBURY CO

311 S HUNTER ST

Year	Uses	Source
1906	r	A. KINGSBURY CO
	Chiorini Jos hotel	A. KINGSBURY CO

312 S HUNTER ST

Year	Uses	Source	
1940	Lee Quong	R. L. Polk Co., Publishers	Image pg. A120
1911	Wilson Chas r	Polk-Husted Directory	
	Medina Angelina h	Polk-Husted Directory	

Year	Uses	Source	
1906	Santos John W mach H Mfg Co r	A. KINGSBURY CO	
	Santos Gertrude Miss r	A. KINGSBURY CO	

314 S HUNTER ST

Year	Uses	Source	
1979	Ribultan Ciraico	R.L. Polk CO.	Image pg. A54
	Advincula Marcos A	R.L. Polk CO.	Image pg. A54
	Ribultan Steve	R.L. Polk CO.	Image pg. A54
1975	Ribultan Ciraico	R.L. Polk CO.	Image pg. A62
	Advincula Marcos A	R.L. Polk CO.	Image pg. A62
	Ribultan Steve	R.L. Polk CO.	Image pg. A62
1970	No Return	R. L. Polk Co., Publishers	Image pg. A70
1940	A Fong Jick	R. L. Polk Co., Publishers	Image pg. A120
1911	Tallent Wellington sashmkr Totten & Brandt h	Polk-Husted Directory	
1906	Shield Chas W iron w orks	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Shield Mary Miss r	A. KINGSBURY CO	

315 S HUNTER ST

Year	Uses	Source	
2009	EMERALD CHINESE RESTAURANT	Cole Information Services	
2004	EMERALD CHINESE RESTAURANT	Cole Information Services	
1999	EMERALD RESTAURANT eating places	R. L. Polk Co., Publishers	Image pg. A6
1996	EMERALD RESTAURANT	R. L. Polk Co., Publishers	Image pg. A13
1994	EMERALD RESTAURANT	Cole Information Services	
1990	New Emerald Restaurant chinese food	R. L. Polk Co., Publishers	Image pg. A21
1979	New Emerald Restaurant chinese food	R.L. Polk CO.	Image pg. A54
1975	Emerald Restaurant chinese food	R.L. Polk CO.	Image pg. A62

316 S HUNTER ST

Year	Uses	Source	
1979	Curino Fraustino E	R.L. Polk CO.	Image pg. A54
1975	Hunte S	R.L. Polk CO.	Image pg. A62
1970	Cagata Louis	R. L. Polk Co., Publishers	Image pg. A70

Year	Uses	Source	
1940	Fong Chan	R. L. Polk Co., Publishers	Image pg. A120
1911	PRING WM H Mngr San Joaquin Drug Co h	Polk-Husted Directory	

320 S HUNTER ST

Year	Uses	Source
1906	Murphy Frank J Murphy & Thorpe r	A. KINGSBURY CO

325 S HUNTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	WING WAH DELI MARKET	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	WING WAH DELI MARKET	Cole Information Services	
	WING WAH DELI MARKET grocery stores	R. L. Polk Co., Publishers	Image pg. A6
1996	WING WAH DELI MARKET	R. L. Polk Co., Publishers	Image pg. A13
1994	WING WAH DELI MARKET	Cole Information Services	
1990	Wing Wah Deli Market	R. L. Polk Co., Publishers	Image pg. A21
1979	La Perla Rooms La Perla Cafe cafe & bar	R.L. Polk CO.	Image pg. A54
	Chin Bock	R.L. Polk CO.	Image pg. A54
	Sun Wong Kee restr	R.L. Polk CO.	Image pg. A54
	Louies Garage auto repr	R.L. Polk CO.	Image pg. A54
1975	La Perla Rooms	R.L. Polk CO.	Image pg. A62
	La Perla Cafe cafe & bar	R.L. Polk CO.	Image pg. A62
1970	Wool Growers Hotel	R. L. Polk Co., Publishers	Image pg. A70
	Wool Growers Inn	R. L. Polk Co., Publishers	Image pg. A70
	Moriones Ben	R. L. Polk Co., Publishers	Image pg. A70
1940	AMariones Theresa Mrs	R. L. Polk Co., Publishers	Image pg. A120
	furn rms	R. L. Polk Co., Publishers	Image pg. A120
1911	Hotel Bilbaina Miguel Olano	Polk-Husted Directory	
	Olano Miguel Hotel La Bilbaina h	Polk-Husted Directory	
1906	Achundo Marie Miss r	A. KINGSBURY CO	
	Belca John sheep raiser r	A. KINGSBURY CO	
	Camino Domingo hotel	A. KINGSBURY CO	
	Dionio Lugi lab r	A. KINGSBURY CO	

Year	Uses	Source	
1906	French and Spanish Hotel	A. KINGSBURY CO	
	French Hotel	A. KINGSBURY CO	
	Gambetta Stefarno lab r	A. KINGSBURY CO	
	Guitterez Jose lab r	A. KINGSBURY CO	
	Hernandez Miguel lab r	A. KINGSBURY CO	
	Jacumbes Edw lab r	A. KINGSBURY CO	
	Sterri Alberto lab r	A. KINGSBURY CO	

333 S HUNTER ST

Year	Uses	Source	
2017	SUN WONG KEE INC	Cole Information Services	
2014	SUN WONG KEE INC	Cole Information Services	
2009	SUN WONG KEE INC	Cole Information Services	
2004	SUN WONG KEE INC	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1999	SUN WONG KEE INCORPORATED	Cole Information Services	
	5 UN WONG KEE grocery stores	R. L. Polk Co., Publishers	Image pg. A6
1996	SUN WONG KEE INC	R. L. Polk Co., Publishers	Image pg. A13
1994	SUN WONG KEE INC	Cole Information Services	
1990	Sun Wong Kee restr	R. L. Polk Co., Publishers	Image pg. A21

336 S HUNTER ST

Year	Uses	Source	
2017	LOUIES GARAGE	Cole Information Services	
2014	LOUIES GARAGE	Cole Information Services	
2009	LOUIES GARAGE	Cole Information Services	
2004	LOUIES GARAGE	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1999	LOUIES GARAGE	Cole Information Services	
	LOUIES GARAGE auto rpr	R. L. Polk Co., Publishers	Image pg. A6
1996	LOUIES GARAGE	R. L. Polk Co., Publishers	Image pg. A13
1994	LOUIES GARAGE	Cole Information Services	
1990	Louies Garage auto repr	R. L. Polk Co., Publishers	Image pg. A21
1975	Louies Garage auto repr	R.L. Polk CO.	Image pg. A62

FINDINGS

Year	Uses	Source	
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A70

341 S HUNTER ST

Year	Uses	Source	
1940	Legare M B Rev	R. L. Polk Co., Publishers	Image pg. A120
	Church of Christ	R. L. Polk Co., Publishers	Image pg. A120
	a United Filipino	R. L. Polk Co., Publishers	Image pg. A120
	Legare M B Rev	R. L. Polk Co., Publishers	Image pg. A120
1911	Narbaitz Raymond Hotel Royal h	Polk-Husted Directory	
	Hotel Royal Raymond Narbaitz	Polk-Husted Directory	
1906	Riba Battiste Jr clk I X L Clothing Co r	A. KINGSBURY CO	
	Riba Battista Jr clk r	A. KINGSBURY CO	
	Reba Mary A Miss clk M Levy & Bro r	A. KINGSBURY CO	
	Williams Wm R emp M P Henderson & Son r	A. KINGSBURY CO	
	Riba Marie Miss r	A. KINGSBURY CO	

401 S HUNTER ST

Year	Uses	Source	
2017	SARA CURIEL	Cole Information Services	
2014	SARA CURIEL	Cole Information Services	
2009	SARA CURIEL	Cole Information Services	
2004	SARA CURIEL	Cole Information Services	
1999	SARA CURIEL	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A21
	Vacant	R. L. Polk Co., Publishers	Image pg. A21
1979	Chan Saml W real est & ins	R.L. Polk CO.	Image pg. A54
	a Abad Juan	R.L. Polk CO.	Image pg. A54
1975	Chan Saml W real est & ins	R.L. Polk CO.	Image pg. A62
1970	Chan Saml W real eat & ins	R. L. Polk Co., Publishers	Image pg. A70
1940	Baylon Peter	R. L. Polk Co., Publishers	Image pg. A120
1911	New ell John driver Stand Oil Co h	Polk-Husted Directory	

FINDINGS

403 S HUNTER ST

Year	*Uses*	*Source*	
2014	HENDERSON JOHNSON	Cole Information Services	
2009	DARREN PAYAN	Cole Information Services	
2004	A CURIEL	Cole Information Services	
	APRIL MASON	Cole Information Services	
1999	DARREN PAYAN	Cole Information Services	
1996	Tabbay Tony	R. L. Polk Co., Publishers	Image pg. A13
1994	TABBAY, TONY	Cole Information Services	
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A21
	Villanvueva Apolinario	R. L. Polk Co., Publishers	Image pg. A21
	Sagun Bobbie	R. L. Polk Co., Publishers	Image pg. A21
	Tualla Juan	R. L. Polk Co., Publishers	Image pg. A21
	Tualla Marceleno	R. L. Polk Co., Publishers	Image pg. A21
1979	Apartments	R.L. Polk CO.	Image pg. A54
	Vacant	R.L. Polk CO.	Image pg. A54
	Buavo Jimmy C	R.L. Polk CO.	Image pg. A54
	Gallegos Ramon	R.L. Polk CO.	Image pg. A54
	Aoitan Bill	R.L. Polk CO.	Image pg. A54
	Carido Fernando	R.L. Polk CO.	Image pg. A54
1975	Tomayo Hilary S	R.L. Polk CO.	Image pg. A62
	Ulep Valentin	R.L. Polk CO.	Image pg. A62
	Paguyo Ben N	R.L. Polk CO.	Image pg. A62
	Aoitan Bill	R.L. Polk CO.	Image pg. A62
	Apartments	R.L. Polk CO.	Image pg. A62
1970	Apartments	R. L. Polk Co., Publishers	Image pg. A70
	Tomayo Hilary S	R. L. Polk Co., Publishers	Image pg. A70
	Ulep Valentin	R. L. Polk Co., Publishers	Image pg. A70
	Brovo Zosimo	R. L. Polk Co., Publishers	Image pg. A70
	Aoitan Bill	R. L. Polk Co., Publishers	Image pg. A70
1911	Bottomley Chas M Bottomley & Willson h	Polk-Husted Directory	

FINDINGS

405 S HUNTER ST

Year	Uses	Source	
2017	JOSE ONATE	Cole Information Services	
2014	JOSE ONATE	Cole Information Services	
2009	A HARRISON	Cole Information Services	
2004	SALVADOR MARTINEZ	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Mobe Benedicto	R. L. Polk Co., Publishers	Image pg. A21
1979	Tarsantan Pedro	R.L. Polk CO.	Image pg. A54
1975	No Return	R.L. Polk CO.	Image pg. A62
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A70

414 S HUNTER ST

Year	Uses	Source	
1940	Oriental	R. L. Polk Co., Publishers	Image pg. A120

415 S HUNTER ST

Year	Uses	Source	
2017	DAVID LEON	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	JOAQUIN GARCIA	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Miro Teddy & Cecile 0S	R. L. Polk Co., Publishers	Image pg. A6
1990	Miro Teodorico	R. L. Polk Co., Publishers	Image pg. A21
1979	Miro Teodorico	R.L. Polk CO.	Image pg. A54
1975	Miro Teodorico	R.L. Polk CO.	Image pg. A62
1970	Silveria Francisco	R. L. Polk Co., Publishers	Image pg. A70
1940	Gainza Jesusa Mrs	R. L. Polk Co., Publishers	Image pg. A120
1906	Hutton Mabel L Miss r	A. KINGSBURY CO	
	Hutton Josie A Mrs r	A. KINGSBURY CO	

418 S HUNTER ST

Year	Uses	Source	
2017	MONICA LOPEZ	Cole Information Services	

FINDINGS

Year	Uses	Source	
2014	JOSE GARIBAY	Cole Information Services	
2009	GREGORIO VALENZUELA	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	GREGORIO VALENZUELA	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	Tabora William	R. L. Polk Co., Publishers	Image pg. A6
1990	No Return	R. L. Polk Co., Publishers	Image pg. A21
1979	No Return	R.L. Polk CO.	Image pg. A54
1975	Louie Yee Pai	R.L. Polk CO.	Image pg. A62
1970	Louie Yee Pai	R. L. Polk Co., Publishers	Image pg. A70
1940	AUriate Thos	R. L. Polk Co., Publishers	Image pg. A120
1911	h	Polk-Husted Directory	
	Gianelli Giovanni B grocer	Polk-Husted Directory	
1906	Gianelli Giovanni B r	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	GIANELLI G B groceries w ines liquors and cigars	A. KINGSBURY CO	

420 S HUNTER ST

Year	Uses	Source	
2017	RUMALDA GARIBAY	Cole Information Services	
2014	RUMALDA GARIBAY	Cole Information Services	
2009	MERCEDES SUDEDA	Cole Information Services	
2004	TEODORO ASICAN	Cole Information Services	
	TEODORO ASICAN	Cole Information Services	
1999	MERCEDES SUDEDA	Cole Information Services	
1994	TAASIN, JUANITO	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A21
1979	Loeai Kay Pie	R.L. Polk CO.	Image pg. A54
1975	Lew Annie Mrs	R.L. Polk CO.	Image pg. A62
1970	Jow Helen Mrs	R. L. Polk Co., Publishers	Image pg. A70
1911	SCOFIELD ALBERT H Live Stock Dealer and Auctioneer	Polk-Husted Directory	

FINDINGS

423 S HUNTER ST

Year	Uses	Source	
2017	BALDEMAR RANGEL	Cole Information Services	
2014	BALDEMAR RANGEL	Cole Information Services	
2009	BALDEMAR RANGEL	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	BALDEMAR RANGEL	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A6
1990	aPetriz Francisco J	R. L. Polk Co., Publishers	Image pg. A21
	Guillermo Benino	R. L. Polk Co., Publishers	Image pg. A21
	Alatorre Evarardo	R. L. Polk Co., Publishers	Image pg. A21
1979	Sagrado Regina	R.L. Polk CO.	Image pg. A54
	aFarinatas Juan	R.L. Polk CO.	Image pg. A54
1975	Tin Yee Kung Shaw Society social	R.L. Polk CO.	Image pg. A62
1970	Tin Yee Kung Shaw Society social	R. L. Polk Co., Publishers	Image pg. A70
1940	Society Chinese	R. L. Polk Co., Publishers	Image pg. A120
	Loong Kong Tin Ye	R. L. Polk Co., Publishers	Image pg. A120
1911	Oyarbide Jos sheep raiser h	Polk-Husted Directory	
1906	YARDLEY JOHN O pianos organs and musical instruments	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Monteverde Jos M emp M Mc Cormick Co r	A. KINGSBURY CO	

424 S HUNTER ST

Year	Uses	Source	
1940	Mow Louie Sing	R. L. Polk Co., Publishers	Image pg. A120
1911	Hesplen Jonathan carp r	Polk-Husted Directory	
	Joseph Frank baker Alfred Gail r	Polk-Husted Directory	
	Sellick Wm A baker Aubrys h	Polk-Husted Directory	
1906	Morse Hiram emp R F Wilson Mfg Co r	A. KINGSBURY CO	
	Sellick Wm A baker r	A. KINGSBURY CO	

FINDINGS

427 S HUNTER ST

Year	Uses	Source	
2017	LANE YEP	Cole Information Services	
2014	LANE YEP	Cole Information Services	
2009	LANE YEP	Cole Information Services	
2004	LANE YEP	Cole Information Services	
1999	LANE YEP	Cole Information Services	
	Yep John J & Liza	R. L. Polk Co., Publishers	Image pg. A6
1996	Yap Lane	R. L. Polk Co., Publishers	Image pg. A13
1994	YEP, LANE	Cole Information Services	
1990	Yep Yet Sun Mrs	R. L. Polk Co., Publishers	Image pg. A21
1979	Yep Gin Lane	R.L. Polk CO.	Image pg. A54
1975	Yip Gin Lan	R.L. Polk CO.	Image pg. A62
1970	Yip Gin Lan	R. L. Polk Co., Publishers	Image pg. A70
1940	a Toy Ben	R. L. Polk Co., Publishers	Image pg. A120
1911	Carroll Michael police h	Polk-Husted Directory	
1906	Grohman Mary J Mrs r	A. KINGSBURY CO	
	Grohman John R farmer r	A. KINGSBURY CO	

430 S HUNTER ST

Year	Uses	Source	
2017	ACENSION GARIBAY	Cole Information Services	
2014	ESTHER CAMACHO	Cole Information Services	
2009	ACENSION GARIBAY	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	BELLO, A	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A21
1979	Tsue But	R.L. Polk CO.	Image pg. A54
1975	Tsue But	R.L. Polk CO.	Image pg. A62
1970	Tsue But	R. L. Polk Co., Publishers	Image pg. A70
1940	ALee Tai Bong herbs	R. L. Polk Co., Publishers	Image pg. A120
1911	Anton Peter w oodw kr S F Phelan r	Polk-Husted Directory	
	Henry Marie w id Mathew b	Polk-Husted Directory	

Year	Uses	Source	
1911	Henry Michael J lawyer Court House h	Polk-Husted Directory	
	Henry Rose clk Raymond Glove Co b	Polk-Husted Directory	
	Roche Ruth L b	Polk-Husted Directory	
1906	Antone Peter emp S F Phelan r	A. KINGSBURY CO	
	Henry Maria Mrs r	A. KINGSBURY CO	
	HENRY MICHAEL J attorney at law	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Henry Rose Miss bkkpr R G Fac r	A. KINGSBURY CO	

438 S HUNTER ST

Year	Uses	Source	
1940	AChew Chauncey	R. L. Polk Co., Publishers	Image pg. A120
1911	chestra h	Polk-Husted Directory	
	Brown Chas L lab S P Co b	Polk-Husted Directory	
	Browns Stockton City Band & String Orchestra	Polk-Husted Directory	
1906	BROWN CHAS Browns Stockton City Band and String Orchestra r	A. KINGSBURY CO	
	Brown Chas Jr emp Pac W G Co r	A. KINGSBURY CO	
	BROWNS STOCKTON CITY BAND & STRING ORCHESTRA Chas Brown	A. KINGSBURY CO	
	Brown Mildred Miss emp P Cahn & Co r	A. KINGSBURY CO	

439 S HUNTER ST

Year	Uses	Source	
1940	Oriental	R. L. Polk Co., Publishers	Image pg. A120
1911	Delucchi John b	Polk-Husted Directory	
	Delucchi Jos waiter Campis b	Polk-Husted Directory	
	Delucchi Antonio Jr waiter Campis b	Polk-Husted Directory	
	Delucchi Antonio porter h	Polk-Husted Directory	

445 S HUNTER ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A120
1911	Devincenzi Emile Sanguinetii & Devincenzi b	Polk-Husted Directory	
	Sanguinetti A D Sanguinetti & Devincenzi b	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1911	Devincenzi Aug b	Polk-Husted Directory	
	Devincenzi Albert brtndr b	Polk-Husted Directory	
1906	German Agnes Mrs r	A. KINGSBURY CO	
	Gernand Julia Miss dressmkr r	A. KINGSBURY CO	

446 S HUNTER ST

Year	Uses	Source	
1911	Giannini Vincenzo w aiter Campis r	Polk-Husted Directory	
	Giononio Danl b	Polk-Husted Directory	
	La Font Louis barber h	Polk-Husted Directory	
1906	Samuel Phoebe Mrs r	A. KINGSBURY CO	
	Samuel Flora Miss r	A. KINGSBURY CO	
	Samuel Manuel clk A Samuel r	A. KINGSBURY CO	
	Samuel Minnie Miss clk r	A. KINGSBURY CO	
	Samuel Ethel Miss stenog B Parkinson r	A. KINGSBURY CO	

448 S HUNTER ST

Year	Uses	Source	
2009	TAQUERIA DOS HERMANOS	Cole Information Services	
2004	TAQUERIA DOS HERMANOS	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1999	TAQUERIA DOS HERMANOS	Cole Information Services	
	TAQUERIA DOS HERMANOS eating places	R. L. Polk Co., Publishers	Image pg. A6
1994	OSPITALS VILLA BASQUE	Cole Information Services	
1990	Ospitals Villa Basque Inc restr	R. L. Polk Co., Publishers	Image pg. A21
1979	Ospitals Villa Basque Inc	R.L. Polk CO.	Image pg. A54
1975	Ospitals Villa Basque Inc	R.L. Polk CO.	Image pg. A62
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A70
1940	j Raffantis liquors	R. L. Polk Co., Publishers	Image pg. A120
	Church nitersects	R. L. Polk Co., Publishers	Image pg. A120

516 S HUNTER ST

Year	Uses	Source
2017	CESAR GUITERREZ	Cole Information Services

FINDINGS

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	ROBERTO CALIMLIM	Cole Information Services	
2004	ROBERTO CALIMLIM	Cole Information Services	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A6
1990	No Return	R. L. Polk Co., Publishers	Image pg. A21
1979	Umino Yoshi Mrs	R.L. Polk CO.	Image pg. A54
1975	Umino Yonetaro	R.L. Polk CO.	Image pg. A62
1970	Umino Yonetaro	R. L. Polk Co., Publishers	Image pg. A70
1940	Oriental	R. L. Polk Co., Publishers	Image pg. A120
1911	Bone Thos bus mngr Central Labor Council b	Polk-Husted Directory	
	Bone Mary w id Edw b	Polk-Husted Directory	
	Holden Wm C carp h	Polk-Husted Directory	
1906	HOLDEN WM C signalman A T & S F r	A. KINGSBURY CO	
	Bone Thos emp Goodell Trans Co	A. KINGSBURY CO	

517 S HUNTER ST

Year	Uses	Source
2017	SENG VANG	Cole Information Services
	XE CHANG	Cole Information Services
2014	CHU VANG	Cole Information Services
	YIA XIONG	Cole Information Services
2009	XIONG HER	Cole Information Services
	PHAZY MOUA	Cole Information Services
	CHU VANG	Cole Information Services
	CHOR CHANG	Cole Information Services
	KANG VANG	Cole Information Services
	WAO YANG	Cole Information Services
	BOUAYIA YANG	Cole Information Services
2004	YIA XIONG	Cole Information Services
	DOUA THAO	Cole Information Services
	KANG VANG	Cole Information Services
1999	XIONG HER	Cole Information Services
	CHU VANG	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	CHOR CHANG	Cole Information Services	
	WAO YANG	Cole Information Services	
	BOUAYIA YANG	Cole Information Services	
	KANG VANG	Cole Information Services	
1996	Graham Joseph S	R. L. Polk Co., Publishers	Image pg. A13
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A21
	Fields Ada Mrs	R. L. Polk Co., Publishers	Image pg. A21
	Burley Lee	R. L. Polk Co., Publishers	Image pg. A21
	Echeverria Nellie	R. L. Polk Co., Publishers	Image pg. A21
	Riley M	R. L. Polk Co., Publishers	Image pg. A21
	Gutierrez R	R. L. Polk Co., Publishers	Image pg. A21
	Garcia	R. L. Polk Co., Publishers	Image pg. A21
	Hernandez Emma	R. L. Polk Co., Publishers	Image pg. A21
	Salazar	R. L. Polk Co., Publishers	Image pg. A21
	Salazar Angelin	R. L. Polk Co., Publishers	Image pg. A21
1979	Apartments	R.L. Polk CO.	Image pg. A54
	Fields Earnset	R.L. Polk CO.	Image pg. A54
	Melvo Corine	R.L. Polk CO.	Image pg. A54
	Cabalar Nicholas	R.L. Polk CO.	Image pg. A54
	Cabeliza Politcarpo	R.L. Polk CO.	Image pg. A54
	Peterson M	R.L. Polk CO.	Image pg. A54
	Long	R.L. Polk CO.	Image pg. A54
	Porte Joe	R.L. Polk CO.	Image pg. A54
	Vacant	R.L. Polk CO.	Image pg. A54
	Vacant	R.L. Polk CO.	Image pg. A54
1975	Apartments lFelds Ernest	R.L. Polk CO.	Image pg. A62
	Hinijosa Delores	R.L. Polk CO.	Image pg. A62
	Cabalac Nicholas Q	R.L. Polk CO.	Image pg. A62
	Cabeliga Politcarpo	R.L. Polk CO.	Image pg. A62
	Allen Charles	R.L. Polk CO.	Image pg. A62
	Irons Jack	R.L. Polk CO.	Image pg. A62
	Farrow James	R.L. Polk CO.	Image pg. A62

FINDINGS

Year	Uses	Source	
1975	Gonzales Joe B	R.L. Polk CO.	Image pg. A62

520 S HUNTER ST

Year	Uses	Source	
1940	a Ardanez Petra Mrs	R. L. Polk Co., Publishers	Image pg. A120
1911	Goni Francisco sheep raiser h	Polk-Husted Directory	
1906	Canlela Louise M Miss r	A. KINGSBURY CO	
	Candella Alexander J plumber r	A. KINGSBURY CO	
	Candella Alexander Candella & Co r	A. KINGSBURY CO	

527 S HUNTER ST

Year	Uses	Source	
2014	ORN CHANROUN	Cole Information Services	
2009	ORN CHANROUN	Cole Information Services	
2004	LOEUN LEK	Cole Information Services	
	CHANSISAMAKIHA TEMPLE	Cole Information Services	
1999	ORN CHANROUN	Cole Information Services	
	Athitthano Sombun	R. L. Polk Co., Publishers	Image pg. A6
	Kruaanant Pornchai	R. L. Polk Co., Publishers	Image pg. A6
	Pulklang Sridhat	R. L. Polk Co., Publishers	Image pg. A6
	Somboom Chaiya	R. L. Polk Co., Publishers	Image pg. A6
1996	Thongkham Sombum 3522 COOB	R. L. Polk Co., Publishers	Image pg. A13
1994	THONGKHAM, SOMBUN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A21
1979	Chew May Mrs	R.L. Polk CO.	Image pg. A54
1975	Chew May Mrs	R.L. Polk CO.	Image pg. A62
1970	Chew May Mrs	R. L. Polk Co., Publishers	Image pg. A70
1940	a Low Chew	R. L. Polk Co., Publishers	Image pg. A120
1911	Young Ella w id R B h	Polk-Husted Directory	
	Brown Wm H h	Polk-Husted Directory	
	Bone Edw lab City St Dept h	Polk-Husted Directory	
1906	Hampton Mary Mrs r	A. KINGSBURY CO	
	Hampton Frank lab r	A. KINGSBURY CO	
	Fritz Jacob lab r	A. KINGSBURY CO	

Year	Uses	Source
1906	Clark David lab r	A. KINGSBURY CO
	Brooks Fred emp str Napa City r	A. KINGSBURY CO

528 S HUNTER ST

Year	Uses	Source	
1990	Wor Daguhoy Lodge No	R. L. Polk Co., Publishers	Image pg. A21
1979	Wor Daguhoy Lodge No	R.L. Polk CO.	Image pg. A54
1975	Wor Daguhoy Lodge No	R.L. Polk CO.	Image pg. A62
1970	Wor Daguhoy Lodge No	R. L. Polk Co., Publishers	Image pg. A70

529 S HUNTER ST

Year	Uses	Source	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A21
1979	No Return	R.L. Polk CO.	Image pg. A54
1975	Davis Aubrey	R.L. Polk CO.	Image pg. A62
1970	Davis Aubrey	R. L. Polk Co., Publishers	Image pg. A70
1940	Yip Sing	R. L. Polk Co., Publishers	Image pg. A120

548 S HUNTER ST

Year	Uses	Source	
1940	a Legionarios D T	R. L. Polk Co., Publishers	Image pg. A120
1911	Olhasso John J The Royal r	Polk-Husted Directory	

S SAN JOAQUIN ST

300 S SAN JOAQUIN ST

Year	Uses	Source
2017	AFFORDABLE LEGAL DOCUMENT ASSISTANCE	Cole Information Services
	SIERRA PACIFIC SOLAR	Cole Information Services
2014	HUMVEE BAIL BONDS	Cole Information Services
	GARCIA MARK A BAIL BONDS	Cole Information Services
	AFFORDABLE LEGAL DOCUMENT ASSISTANCE	Cole Information Services

FINDINGS

301 S SAN JOAQUIN ST

Year	*Uses*	*Source*
2017	LELAND LEUNG	Cole Information Services
	JUE YING	Cole Information Services
	SU CAI	Cole Information Services
	LINDA MILTON	Cole Information Services
	HOWARD WONG	Cole Information Services
	XIXI TAN-CHIN	Cole Information Services
	QUAN YANG SENIOR APARTMENTS	Cole Information Services
	LUCIANI DANIEL	Cole Information Services
	HERBERT MCKENZIE	Cole Information Services
	CORAZZINI ANNUNCIATA	Cole Information Services
	VICTOR AGUILERA	Cole Information Services
	PATRICK KOENG	Cole Information Services
2014	EDWARD MAGANA	Cole Information Services
	BAO MIAO	Cole Information Services
	BAN ZHU	Cole Information Services
	DANIEL LUCIANI	Cole Information Services
	HOWARD WONG	Cole Information Services
	LAN CHEN	Cole Information Services
	LUCIANI DANIEL	Cole Information Services
	HERBERT MCKENZIE	Cole Information Services
	CHIN TAN	Cole Information Services
2009	TU LIN	Cole Information Services
	CHIN TAN	Cole Information Services
	FU WU	Cole Information Services
	M TAMPIER	Cole Information Services
	HOWARD WONG	Cole Information Services
	JACK CHRISTENSEN	Cole Information Services
	QUN DILIU	Cole Information Services
	TONY MORALES	Cole Information Services
	QUAN YING FOUNDATION	Cole Information Services
2004	TU LIN	Cole Information Services

FINDINGS

Year	Uses	Source	
2004	VUE CHAN	Cole Information Services	
	RUIKUAN LIANG	Cole Information Services	
	FU WU	Cole Information Services	
	FREDRICK MERCADO	Cole Information Services	
	BAN ZHU	Cole Information Services	
	JERRY WILLIAMS	Cole Information Services	
	ARTEMIO MENDOZA	Cole Information Services	
	HOWARD WONG	Cole Information Services	
	XIXI TAN-CHIN	Cole Information Services	
	JULIA LETO	Cole Information Services	
	JESUS CAMACHO	Cole Information Services	
	TONY MORALES	Cole Information Services	
1999	HOWARD WONG	Cole Information Services	
	JACK CHRISTENSEN	Cole Information Services	
	QUN DILIU	Cole Information Services	
	FU WU	Cole Information Services	
	M TAMPIER	Cole Information Services	
	TU LIN	Cole Information Services	
	CHIN TAN	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1996	STOCKTON	R. L. Polk Co., Publishers	Image pg. A14
	SHELTER THE HOMELESS	R. L. Polk Co., Publishers	Image pg. A14
1994	STOCKTON SHELTER THE HOMELESS	Cole Information Services	
1990	Shelter For The Homeless Family Unit	R. L. Polk Co., Publishers	Image pg. A16
1979	Bing Kong Tong Chinese Free Mission	R.L. Polk CO.	Image pg. A47
1975	Bing Kong Tong Chinese Free Mission	R.L. Polk CO.	Image pg. A57
1970	Salvation Army Citadel church	R. L. Polk Co., Publishers	Image pg. A65
1940	Salvation Army The	R. L. Polk Co., Publishers	Image pg. A115

302 S SAN JOAQUIN ST

Year	Uses	Source
2017	NEW STOCKTON POULTRY MKT INC	Cole Information Services
2014	NEW STOCKTON POULTRY MKT INC	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	STOCKTON POULTRY	Cole Information Services	
	LUUS FAMILY CORP	Cole Information Services	
2004	NEW STOCKTON POULTRY INC	Cole Information Services	
1999	MARKET poultry poultry pr	R. L. Polk Co., Publishers	Image pg. A7
	STOCKTON POULTRY	R. L. Polk Co., Publishers	Image pg. A7
1996	POULTRY MARKET	R. L. Polk Co., Publishers	Image pg. A14
	STOCKTON	R. L. Polk Co., Publishers	Image pg. A14
1994	STOCKTON POULTRY MARKET	Cole Information Services	
1990	Stockton Poultry Market	R. L. Polk Co., Publishers	Image pg. A16
1979	Stockton Poultry Market	R.L. Polk CO.	Image pg. A47
1975	Stockton Poultry Market	R.L. Polk CO.	Image pg. A57
1970	Stockton Poultry Market	R. L. Polk Co., Publishers	Image pg. A65
1940	a Eckert C W auto repr	R. L. Polk Co., Publishers	Image pg. A115
	Alng C S phys	R. L. Polk Co., Publishers	Image pg. A121
1911	SKINNER JOHN C Agt Mitchell Motor Cars Sundries and Repairs	Polk-Husted Directory	
	MITCHELL MOTOR CARS J C Skinner Agt	Polk-Husted Directory	
1906	Hotel Dltalia S Dalporto & Co proprs	A. KINGSBURY CO	

304 S SAN JOAQUIN ST

Year	Uses	Source	
1940	APark P W dentist	R. L. Polk Co., Publishers	Image pg. A121

306 S SAN JOAQUIN ST

Year	Uses	Source	
1940	AMc Noble H R lawyer	R. L. Polk Co., Publishers	Image pg. A121
	U S Commissioner	R. L. Polk Co., Publishers	Image pg. A121

309 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Pak Hotel	R. L. Polk Co., Publishers	Image pg. A16
1940	Johnston Donald	R. L. Polk Co., Publishers	Image pg. A115
	Citadel Hotel	R. L. Polk Co., Publishers	Image pg. A115

FINDINGS

311 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Nathong Kay	R. L. Polk Co., Publishers	Image pg. A16
	Ry Van	R. L. Polk Co., Publishers	Image pg. A16
	Phan Vangsanit	R. L. Polk Co., Publishers	Image pg. A16
	Tengane	R. L. Polk Co., Publishers	Image pg. A16
	Phongsilasack	R. L. Polk Co., Publishers	Image pg. A16
	Apartments	R. L. Polk Co., Publishers	Image pg. A16
1979	Solorzano Ruben	R.L. Polk CO.	Image pg. A47
	Genaro Lapay P	R.L. Polk CO.	Image pg. A47
	Apartments	R.L. Polk CO.	Image pg. A47
1975	Apartments	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
1970	Apartments	R. L. Polk Co., Publishers	Image pg. A65
	Garcia Maximilla	R. L. Polk Co., Publishers	Image pg. A65
	Mora Silvestre D	R. L. Polk Co., Publishers	Image pg. A65
	Lapay Genro P	R. L. Polk Co., Publishers	Image pg. A65
	Autentico Emeterio	R. L. Polk Co., Publishers	Image pg. A65
	Vacant	R. L. Polk Co., Publishers	Image pg. A65
	Molhan Calobo	R. L. Polk Co., Publishers	Image pg. A65
1940	Flew ellen Wm	R. L. Polk Co., Publishers	Image pg. A115

312 S SAN JOAQUIN ST

Year	Uses	Source
1911	Larsen Peter garage	Polk-Husted Directory

315 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Rex Hotel	R. L. Polk Co., Publishers	Image pg. A115
	Collins Lee Mrs	R. L. Polk Co., Publishers	Image pg. A115

318 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Stockton Poultry Mkt addl ofc	R. L. Polk Co., Publishers	Image pg. A16

Year	Uses	Source	
1979	Day & Night Massage Service	R.L. Polk CO.	Image pg. A47
1975	Day & Night Massage Service	R.L. Polk CO.	Image pg. A57
1970	Kathys Massage Salon	R. L. Polk Co., Publishers	Image pg. A65

319 S SAN JOAQUIN ST

Year	Uses	Source	
2017	WING FUNG GROCERY	Cole Information Services	
2009	R & P CONVENIENCE	Cole Information Services	
1996	YUEN CHINESE DELI	R. L. Polk Co., Publishers	Image pg. A14
	OUONG WAH	R. L. Polk Co., Publishers	Image pg. A14
1990	Quong Wah Yuen Chinese Store gro	R. L. Polk Co., Publishers	Image pg. A16
1979	Quong Wah Yuen Chinese Store	R.L. Polk CO.	Image pg. A47
1975	Quong Wah Yuen Chinese Store	R.L. Polk CO.	Image pg. A57
1970	Rafaels Tailoring	R. L. Polk Co., Publishers	Image pg. A65
	Rafael Ignacio	R. L. Polk Co., Publishers	Image pg. A65

320 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Drive In Barber Shop	R. L. Polk Co., Publishers	Image pg. A16
1979	Drive In Barber Shop	R.L. Polk CO.	Image pg. A47
1975	Drive In Barber Shop	R.L. Polk CO.	Image pg. A57
1970	Drive In Barber Shop	R. L. Polk Co., Publishers	Image pg. A65
1940	ALittle H C oil burners	R. L. Polk Co., Publishers	Image pg. A115
1906	r	A. KINGSBURY CO	
	Haack John meat market	A. KINGSBURY CO	

321 S SAN JOAQUIN ST

Year	Uses	Source	
2004	WONG FAMILY BENEVOLENT ASCTN	Cole Information Services	
1999	WONG FAMILY BENEVOLENT ASSOCIATION	Cole Information Services	
	WONG FAMILY BENEVOLENT ASSOC busn assns	R. L. Polk Co., Publishers	Image pg. A7
1996	WONG FAMILY	R. L. Polk Co., Publishers	Image pg. A14
	BENEVOLENT ASSN	R. L. Polk Co., Publishers	Image pg. A14

FINDINGS

Year	Uses	Source	
1994	WONG FAMILY BENEVOLENT ASSN	Cole Information Services	
1990	Wong Family Benevolent Assn	R. L. Polk Co., Publishers	Image pg. A16
1979	Wong Family Benevolent Assn	R.L. Polk CO.	Image pg. A47
1975	Wong Family Benevolent Assn	R.L. Polk CO.	Image pg. A57
1970	Wong Family Benevolent Assn	R. L. Polk Co., Publishers	Image pg. A65
1940	11 Sole w eekly	R. L. Polk Co., Publishers	Image pg. A115
	11 Sole Inc pubirs	R. L. Polk Co., Publishers	Image pg. A115
1906	Tye Anastasia Miss clk Sterling C & M Co r	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Tye Hugh horseshoer	A. KINGSBURY CO	

325 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Fong S L	R. L. Polk Co., Publishers	Image pg. A16
1979	Fong S L	R.L. Polk CO.	Image pg. A47
1975	Vacant	R.L. Polk CO.	Image pg. A57
1970	Fong Suey Lung herbs	R. L. Polk Co., Publishers	Image pg. A65
1940	herbs	R. L. Polk Co., Publishers	Image pg. A115
	Suey Lung Fong	R. L. Polk Co., Publishers	Image pg. A115

326 S SAN JOAQUIN ST

Year	Uses	Source
1906	BELDING & HUSKINS C Belding S B Huskins soda w ater mfrs	A. KINGSBURY CO

328 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1911	Hall Walter M clk San Joaquin Drug Co b	Polk-Husted Directory	
	Hall Vera milliner Katten & Co b	Polk-Husted Directory	
	Hall Mary A w id W W h	Polk-Husted Directory	
	Hall Harold clk b	Polk-Husted Directory	
	Woodw ard Myrtle w id J M elk Hales b	Polk-Husted Directory	

FINDINGS

329 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Vacant	R.L. Polk CO.	Image pg. A47
1975	Ning Tom Laundry	R.L. Polk CO.	Image pg. A57
1970	Ning Tom Laundry	R. L. Polk Co., Publishers	Image pg. A65
1940	Zaremba Paul baker	R. L. Polk Co., Publishers	Image pg. A115

330 S SAN JOAQUIN ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Melton Glenn M & Diana	R. L. Polk Co., Publishers	Image pg. A7
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
	Chow B C	R. L. Polk Co., Publishers	Image pg. A115
1911	Berg Law rence F clnr Pac Carpet Cing Co h	Polk-Husted Directory	
	Breidenbach Louis F Stockton Theatre h	Polk-Husted Directory	
1906	r	A. KINGSBURY CO	
	Breidenbach Louis F w holesale liquors	A. KINGSBURY CO	

331 S SAN JOAQUIN ST

Year	Uses	Source	
1999	MY MARKET	Cole Information Services	
	MY MARKET grocery stores	R. L. Polk Co., Publishers	Image pg. A7
1994	MY MARKET	Cole Information Services	
1990	Kenley Company Market gro	R. L. Polk Co., Publishers	Image pg. A16
1979	Kenley Company Market gro	R.L. Polk CO.	Image pg. A47
1975	Kenley Market gro	R.L. Polk CO.	Image pg. A57
1970	Kenley Market gro	R. L. Polk Co., Publishers	Image pg. A65
1940	LNakashima Sami gro	R. L. Polk Co., Publishers	Image pg. A115

332 S SAN JOAQUIN ST

Year	Uses	Source
2014	IRENE MARTINEZ	Cole Information Services
2009	FRANCISCO GARCIA	Cole Information Services
2004	JESSE NAWATANI	Cole Information Services

FINDINGS

Year	Uses	Source	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A16
1979	Wong Chun Yuk	R.L. Polk CO.	Image pg. A47
1975	Chong Yee	R.L. Polk CO.	Image pg. A57
1940	a Young Lum tailor	R. L. Polk Co., Publishers	Image pg. A115
1911	Daniels Henry W ins agt r	Polk-Husted Directory	
	Mills Geo W checker MAaddens b	Polk-Husted Directory	
	Mills Albert J h	Polk-Husted Directory	

333 S SAN JOAQUIN ST

Year	Uses	Source
1911	Lew is Leo carmn C C T Co h	Polk-Husted Directory
1906	Gardner Frank clk Samson Iron Works r	A. KINGSBURY CO
	Gardner B F emp Samson Iron Works r	A. KINGSBURY CO

334 S SAN JOAQUIN ST

Year	Uses	Source	
2009	BUENAVENTURA SIERRA	Cole Information Services	
	SONYA GUERRA	Cole Information Services	
2004	BUENAVENTURA SIERRA	Cole Information Services	
	CHY SONG	Cole Information Services	
1999	BUENAVENTURA SIERRA	Cole Information Services	
	SONYA GUERRA	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1990	No Return	R. L. Polk Co., Publishers	Image pg. A16
1979	Rice Geo	R.L. Polk CO.	Image pg. A47
1975	Rice Geo	R.L. Polk CO.	Image pg. A57
1970	No Return	R. L. Polk Co., Publishers	Image pg. A65
1940	a Chew Hing herbs	R. L. Polk Co., Publishers	Image pg. A115
1911	Boyle Sarah J h	Polk-Husted Directory	
	Mc Call Robt E Mc Call & Mc Call r	Polk-Husted Directory	

335 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Alex Hotel	R. L. Polk Co., Publishers	Image pg. A16

FINDINGS

Year	Uses	Source	
1979	Gomei Silverio	R.L. Polk CO.	Image pg. A47
	Cruz Eusebio	R.L. Polk CO.	Image pg. A47
	Cisneros Jose	R.L. Polk CO.	Image pg. A47
	Alex Hotel	R.L. Polk CO.	Image pg. A47
1975	Alex Hotel	R.L. Polk CO.	Image pg. A57
1970	Alex Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A65
1940	s Pyrenees Hotel	R. L. Polk Co., Publishers	Image pg. A115
	Olson Louise Mrs	R. L. Polk Co., Publishers	Image pg. A115

337 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1940	a Wong Y herbs	R. L. Polk Co., Publishers	Image pg. A115
1911	Zignego Antonio L Williams & Zignego h	Polk-Husted Directory	
1906	Wilson Oscar D Wilson & Mow ry r	A. KINGSBURY CO	

339 S SAN JOAQUIN ST

Year	Uses	Source
1911	Feeney Geo P clk M S Arndt h	Polk-Husted Directory

341 S SAN JOAQUIN ST

Year	Uses	Source
1906	Spencer Eugene foreman W P Ry r	A. KINGSBURY CO

343 S SAN JOAQUIN ST

Year	Uses	Source	
2009	COSMOS HOTEL	Cole Information Services	
1999	Patel Kishor P	R. L. Polk Co., Publishers	Image pg. A7
	Patel Kamla P	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Orrosco Fernando	R. L. Polk Co., Publishers	Image pg. A16
	Vacant Rms	R. L. Polk Co., Publishers	Image pg. A16

FINDINGS

Year	Uses	Source	
1990	Wantland Cecil	R. L. Polk Co., Publishers	Image pg. A16
	Handey Wm	R. L. Polk Co., Publishers	Image pg. A16
	Soto Mark	R. L. Polk Co., Publishers	Image pg. A16
	Monzo Mario	R. L. Polk Co., Publishers	Image pg. A16
	Vacant Rms	R. L. Polk Co., Publishers	Image pg. A16
	Rice John	R. L. Polk Co., Publishers	Image pg. A16
	Vacant Rms	R. L. Polk Co., Publishers	Image pg. A16
	Gonzales Gary	R. L. Polk Co., Publishers	Image pg. A16
	Tran Tri	R. L. Polk Co., Publishers	Image pg. A16
	Hernandez Danl	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Colanaie Robt	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Dixon Bradley	R. L. Polk Co., Publishers	Image pg. A16
	Johnston Bradley	R. L. Polk Co., Publishers	Image pg. A16
	Patel Kishor	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Hotel Cosmos	R. L. Polk Co., Publishers	Image pg. A16
	Patel R	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Cosmos Hotel	R.L. Polk CO.	Image pg. A47
1975	Cosmos Hotel	R.L. Polk CO.	Image pg. A57
1970	Omiya Masayuki	R. L. Polk Co., Publishers	Image pg. A65
	Basconia Hotel	R. L. Polk Co., Publishers	Image pg. A65
1940	Etchevery Paul	R. L. Polk Co., Publishers	Image pg. A115
	Hotel Basque	R. L. Polk Co., Publishers	Image pg. A115
1911	Warren Frank G Warren & Nelson h	Polk-Husted Directory	
1906	Douglas Wm H r	A. KINGSBURY CO	

344 S SAN JOAQUIN ST

Year	Uses	Source
2009	CARLOS MARQUEZ	Cole Information Services
2004	CARLOS MARQUEZ	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Vacant	R.L. Polk CO.	Image pg. A47
1975	Vacant	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	Watkins J R Prod	R. L. Polk Co., Publishers	Image pg. A115
	ucts Co mfrs agts	R. L. Polk Co., Publishers	Image pg. A115
	Schow W B	R. L. Polk Co., Publishers	Image pg. A115
1906	r	A. KINGSBURY CO	
	Hart James M barber	A. KINGSBURY CO	

345 S SAN JOAQUIN ST

Year	Uses	Source	
2004	ALBERT CHEW	Cole Information Services	
	SUEY FOONG BENEVOLENT ASSOC	Cole Information Services	
1999	Chew Albert	R. L. Polk Co., Publishers	Image pg. A7
1996	Chew Albert	R. L. Polk Co., Publishers	Image pg. A14
1994	CHEW, ALBERT	Cole Information Services	
1990	Suey Sing Chamber Of Labor & Commerce	R. L. Polk Co., Publishers	Image pg. A16
1979	No Retui n	R.L. Polk CO.	Image pg. A47
1911	Conw ay Michael Thorp & Conw ay h	Polk-Husted Directory	

346 S SAN JOAQUIN ST

Year	Uses	Source
2017	MARGARITA ARMENTA	Cole Information Services
2014	MARCIELA FLORES	Cole Information Services
	MARGARITA ARMENTA	Cole Information Services
	GUANG RONG	Cole Information Services
2009	MARCIELA FLORES	Cole Information Services
	GUANG HUANG	Cole Information Services
	MARGARITA ARMENTA	Cole Information Services
	J DETTMER	Cole Information Services
2004	MARCIELA FLORES	Cole Information Services
	GUADALUPE REYES	Cole Information Services

FINDINGS

Year	Uses	Source	
2004	JESUS ALMANZA	Cole Information Services	
1999	MARGARITA ARMENTA	Cole Information Services	
	J DETTMER	Cole Information Services	
	GUANG HUANG	Cole Information Services	
	MARCIELA FLORES	Cole Information Services	
	LETICIA MARTINEZ	Cole Information Services	
	Hernandez Victor	R. L. Polk Co., Publishers	Image pg. A7
	Manrajos Ruben C	R. L. Polk Co., Publishers	Image pg. A7
	Martinez Leticia	R. L. Polk Co., Publishers	Image pg. A7
	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1994	CENTENO, ABRAHAM	Cole Information Services	
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A16
	Yee Min	R. L. Polk Co., Publishers	Image pg. A16
	Kiang Quan	R. L. Polk Co., Publishers	Image pg. A16
	No Return	R. L. Polk Co., Publishers	Image pg. A16
	Gao Yao	R. L. Polk Co., Publishers	Image pg. A16
	No Return	R. L. Polk Co., Publishers	Image pg. A16
1979	Apartments	R.L. Polk CO.	Image pg. A47
	Yee Min	R.L. Polk CO.	Image pg. A47
	Kiung Quun	R.L. Polk CO.	Image pg. A47
	Mah Q	R.L. Polk CO.	Image pg. A47
	Vacant	R.L. Polk CO.	Image pg. A47
1975	Apartments	R.L. Polk CO.	Image pg. A57
	Yee Min	R.L. Polk CO.	Image pg. A57
	Kiang Quan	R.L. Polk CO.	Image pg. A57
	Mah Lin	R.L. Polk CO.	Image pg. A57
	Lin Mar S	R.L. Polk CO.	Image pg. A57
1970	Apartments	R. L. Polk Co., Publishers	Image pg. A65
	Yip Ben H	R. L. Polk Co., Publishers	Image pg. A65
	Mar Wah Sing	R. L. Polk Co., Publishers	Image pg. A65
	Lim James	R. L. Polk Co., Publishers	Image pg. A65
	Sim Mah	R. L. Polk Co., Publishers	Image pg. A65

FINDINGS

Year	Uses	Source	
1940	Moreno Rose Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Ford Wm E driver Stkn Ice & F Co h	Polk-Husted Directory	
	Law rence Chas brtndr El Dorado Imp Co r	Polk-Husted Directory	
	Law rence John J porter G S Ladd & Co r	Polk-Husted Directory	
	Mc Gorray Kate w id S W b	Polk-Husted Directory	

347 S SAN JOAQUIN ST

Year	Uses	Source	
1990	La Perlas tavern	R. L. Polk Co., Publishers	Image pg. A16
1979	Old Peei less Inn tavern	R.L. Polk CO.	Image pg. A47
1975	Old Peerless Inn tavern	R.L. Polk CO.	Image pg. A57
1970	Old Peerless Inn tavern	R. L. Polk Co., Publishers	Image pg. A65
1940	Idiart John liquors	R. L. Polk Co., Publishers	Image pg. A115
1911	Phillips David A coremkr Monarch Foundry grocer	Polk-Husted Directory	
1906	Capurro Albert grocer	A. KINGSBURY CO	

348 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Marrs Association	R. L. Polk Co., Publishers	Image pg. A16
1979	Marra Asasn	R.L. Polk CO.	Image pg. A47
1975	Marrs Assn	R.L. Polk CO.	Image pg. A57
1970	Marrs Assn	R. L. Polk Co., Publishers	Image pg. A65
1940	ucts Co mfrs agts	R. L. Polk Co., Publishers	Image pg. A115
	a Salaber Frank do	R. L. Polk Co., Publishers	Image pg. A115
1911	Capurro Albert A grocer	Polk-Husted Directory	

401 S SAN JOAQUIN ST

Year	Uses	Source	
1940	ASocial Security Bd	R. L. Polk Co., Publishers	Image pg. A121
	Alustiza Ferminrestr	R. L. Polk Co., Publishers	Image pg. A115

402 S SAN JOAQUIN ST

Year	Uses	Source
2017	MARIAH MASTON	Cole Information Services

FINDINGS

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	PILI MAUIA	Cole Information Services	
1999	Not Verified 3 Hses	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Vacant	R.L. Polk CO.	Image pg. A47
1975	Vacant	R.L. Polk CO.	Image pg. A57
1970	Borquez Benj	R. L. Polk Co., Publishers	Image pg. A65
1940	George W H	R. L. Polk Co., Publishers	Image pg. A115
1911	Avilla Philip hlpr H & H Mnfg Co r	Polk-Husted Directory	
	Allender May F clk The Record b	Polk-Husted Directory	
	Allender May A w id Frank h	Polk-Husted Directory	

403 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	M JAIMES	Cole Information Services	
2004	M JAIMES	Cole Information Services	
1999	M JAIMES	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	GSPL CENTER RESCUE MSSN NEW HOPE FAMILY SHELTER	Cole Information Services	
1990	New Hope Family Shelter	R. L. Polk Co., Publishers	Image pg. A16
1979	Etchecopar Luise Mrs	R.L. Polk CO.	Image pg. A47
	Etchecopar Luise Mrs	R.L. Polk CO.	Image pg. A47
	California Hotel	R.L. Polk CO.	Image pg. A47
	Alustizas tavern	R.L. Polk CO.	Image pg. A47
1975	Vacant	R.L. Polk CO.	Image pg. A57
	Tandiado J	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
	Pina Philipe	R.L. Polk CO.	Image pg. A57
	Del Rio Fidel	R.L. Polk CO.	Image pg. A57
	Etchecopar Luise Mrs	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
	Tantiado Tio	R.L. Polk CO.	Image pg. A57

FINDINGS

Year	Uses	Source	
1975	Vacant	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
	California Hotel	R.L. Polk CO.	Image pg. A57
	Alustizas tavern	R.L. Polk CO.	Image pg. A57
	Vacant	R.L. Polk CO.	Image pg. A57
1970	Alustizas tavern	R. L. Polk Co., Publishers	Image pg. A65
1940	Fermin Alustiza	R. L. Polk Co., Publishers	Image pg. A115
	California Hotel	R. L. Polk Co., Publishers	Image pg. A115

404 S SAN JOAQUIN ST

Year	Uses	Source	
2017	ANALIZA FERNANDEZ	Cole Information Services	
2009	ROBERT HALL	Cole Information Services	
2004	ROBERT HALL	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Vega Jesus	R.L. Polk CO.	Image pg. A47
1975	Vega Jesus	R.L. Polk CO.	Image pg. A57
1970	Chacon Mary	R. L. Polk Co., Publishers	Image pg. A65
1940	Troxell D B	R. L. Polk Co., Publishers	Image pg. A115
1911	Mc Millen W Edw telg oprr S Fe Ry h	Polk-Husted Directory	
1906	Varian Mary L Mrs r	A. KINGSBURY CO	

405 S SAN JOAQUIN ST

Year	Uses	Source	
1940	ACoale H W jr dentist	R. L. Polk Co., Publishers	Image pg. A121
1906	Danzig Walter clk I X L r	A. KINGSBURY CO	

406 S SAN JOAQUIN ST

Year	Uses	Source	
2009	ANDREA WHITE	Cole Information Services	
1999	ANDREA WHITE	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Prado Francisco	R.L. Polk CO.	Image pg. A47

FINDINGS

Year	Uses	Source	
1975	Saroas Francisco	R.L. Polk CO.	Image pg. A57
1970	Mabia Pedro C	R. L. Polk Co., Publishers	Image pg. A65
1940	Kurth W F	R. L. Polk Co., Publishers	Image pg. A115
1911	Marshall Edw L clk Holden Drug Co h	Polk-Husted Directory	
1906	Bell Elvina Mrs r	A. KINGSBURY CO	
	Avila Joaquin A emp Hickinbotham Bros r	A. KINGSBURY CO	

407 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Gini Angelo barber	R. L. Polk Co., Publishers	Image pg. A115

408 S SAN JOAQUIN ST

Year	Uses	Source	
2017	ERIC SLOAN	Cole Information Services	
2014	ERIC SLOAN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Yep Benny	R.L. Polk CO.	Image pg. A47
1975	Yip Bennie	R.L. Polk CO.	Image pg. A57
1970	Yep Benny	R. L. Polk Co., Publishers	Image pg. A65
1940	a Fire Companies ad	R. L. Polk Co., Publishers	Image pg. A121
	justment Bureau	R. L. Polk Co., Publishers	Image pg. A121
	Green Louis	R. L. Polk Co., Publishers	Image pg. A115
1911	Campbell Mrs Helen h	Polk-Husted Directory	
1906	Lenfesty Grace Miss r	A. KINGSBURY CO	
	Lenfesty Mabel Miss clk r	A. KINGSBURY CO	
	Olson John carp r	A. KINGSBURY CO	

410 S SAN JOAQUIN ST

Year	Uses	Source
2014	JEREMY SABATE	Cole Information Services
2009	JEREMY SABATE	Cole Information Services
1999	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	A Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	b Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Mt Argel Basilio	R.L. Polk CO.	Image pg. A47
	b Vargas Adelberto	R.L. Polk CO.	Image pg. A47
	Gonzales Danny	R.L. Polk CO.	Image pg. A47
1975	Argel Basilio	R.L. Polk CO.	Image pg. A57
	b Vargas Adelberto	R.L. Polk CO.	Image pg. A57
	No Return	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
	b Vacant	R. L. Polk Co., Publishers	Image pg. A65
	Faust David N	R. L. Polk Co., Publishers	Image pg. A65
1940	Q Banuelos Hope Mrs	R. L. Polk Co., Publishers	Image pg. A115
	a Ball Edw	R. L. Polk Co., Publishers	Image pg. A115
1911	Ball Edw bldg contr h	Polk-Husted Directory	
1906	Lee Clem F carp r	A. KINGSBURY CO	
	Adams Mildred Miss asst Dr Priestley r	A. KINGSBURY CO	
	Adams Ethel Miss waitress r	A. KINGSBURY CO	
	Adams Dora Mrs r	A. KINGSBURY CO	

411 S SAN JOAQUIN ST

Year	Uses	Source	
1940	ACoblentz H C lawyer	R. L. Polk Co., Publishers	Image pg. A121

412 S SAN JOAQUIN ST

Year	Uses	Source	
2014	ADRIAN WEBSTER	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	ULVANG, DOROTHY	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Ulvang Dorothy M	R.L. Polk CO.	Image pg. A47
1975	Uluang Dorothy	R.L. Polk CO.	Image pg. A57

FINDINGS

Year	Uses	Source	
1970	Ulvang Dorothy Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Crowder C W	R. L. Polk Co., Publishers	Image pg. A115
1911	Houseman Carl W brkmn S Fe Ry h	Polk-Husted Directory	
	Volkers Mrs Wanda b	Polk-Husted Directory	
1906	Winters Chas H foreman A T & S F r	A. KINGSBURY CO	

414 S SAN JOAQUIN ST

Year	Uses	Source	
2017	LEE TAYLOR	Cole Information Services	
2014	MARGARET PREASTLY	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	ELIZABITH GRAYSON	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	Vacant	R.L. Polk CO.	Image pg. A47
1975	Soniko Frank	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1911	Paul Geo W hlpr H & H Mnfg Co h	Polk-Husted Directory	
1906	Hansen Fred W emp A T & S F r	A. KINGSBURY CO	

416 S SAN JOAQUIN ST

Year	Uses	Source	
2017	BARBARA SMITH	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	MONIQUE TAYLOR	Cole Information Services	
2004	YUMIKA DEBOIS	Cole Information Services	
1999	MONIQUE TAYLOR	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	Vacant	R. L. Polk Co., Publishers	Image pg. A16
	b Vacant	R. L. Polk Co., Publishers	Image pg. A16
1979	A Cedinio Pile	R.L. Polk CO.	Image pg. A47
	b Vacant	R.L. Polk CO.	Image pg. A47
	Wilson Shirley	R.L. Polk CO.	Image pg. A47

FINDINGS

Year	Uses	Source	
1975	Saldivas C	R.L. Polk CO.	Image pg. A57
	b Vacant	R.L. Polk CO.	Image pg. A57
	Huerta Conching	R.L. Polk CO.	Image pg. A57
1970	/ Vacant	R. L. Polk Co., Publishers	Image pg. A65
	Sepulveda Ray	R. L. Polk Co., Publishers	Image pg. A65
1940	Gonzales F C	R. L. Polk Co., Publishers	Image pg. A115
	Murray Mary Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Russell Mabel mkr Spencers Millinery b	Polk-Husted Directory	
	Russell Claude b	Polk-Husted Directory	
	Peck Willis E adv soir Comi Ptg & Pub Co r	Polk-Husted Directory	
	Murray Law rence M h	Polk-Husted Directory	
	Alcateep Jos linemn r	Polk-Husted Directory	
1906	Tarr Jeremiah emp Pac W G Co r	A. KINGSBURY CO	
	Russell May Mrs r	A. KINGSBURY CO	
	Paulina Tony bartndr r	A. KINGSBURY CO	
	Murray Law rence emp H Mfg Co r	A. KINGSBURY CO	
	Murray Dan emp H Mfg Co r	A. KINGSBURY CO	
	Lucich David cook F P Madden r	A. KINGSBURY CO	
	Connor Patrick J emp Pac W G Co r	A. KINGSBURY CO	

420 S SAN JOAQUIN ST

Year	Uses	Source	
2017	LULA BELTON	Cole Information Services	
2014	SAEED RAHMAN	Cole Information Services	
2009	RAJA MOSLEY	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	White J C Jr	R. L. Polk Co., Publishers	Image pg. A7
1990	Costa Ralph	R. L. Polk Co., Publishers	Image pg. A16
1979	Council For The Spanish Speaking	R.L. Polk CO.	Image pg. A47
1975	Philopino Bayanihan Inc	R.L. Polk CO.	Image pg. A57
1970	Filipino Sisters Convent	R. L. Polk Co., Publishers	Image pg. A65
1940	a Sanzberro Justo	R. L. Polk Co., Publishers	Image pg. A115
1911	Mc Cormick Jas b	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1911	Mc Cormick Margaret w id Jas h	Polk-Husted Directory	
	Mlc Cormick Robt b	Polk-Husted Directory	
	Pollard Geo H ctr M Mc Cormick Co r	Polk-Husted Directory	
	Stew art Richd clk r	Polk-Husted Directory	

423 S SAN JOAQUIN ST

Year	Uses	Source	
2017	CARE LINK HOMELESS PROGRAM	Cole Information Services	
2014	COMMUNITY MEDICAL CENTERSCHANNEL ME	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	COOPER, BETTY J	Cole Information Services	
1979	Baotista Aurora Mrs	R.L. Polk CO.	Image pg. A47
1975	Baotista Aurora	R.L. Polk CO.	Image pg. A57
1970	Todorovitch Stanley	R. L. Polk Co., Publishers	Image pg. A65
1940	Gleason E E Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Musto May w id John h	Polk-Husted Directory	
1906	MUSTO JOHN Musto & Ruiz r	A. KINGSBURY CO	

428 S SAN JOAQUIN ST

Year	Uses	Source	
2017	MICHELLE GARCIA	Cole Information Services	
2014	MICHELLE GARCIA	Cole Information Services	
2009	BREDNA ALMANZA	Cole Information Services	
2004	ANTONIO PALACIO	Cole Information Services	
1999	BREDNA ALMANZA	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	Palacio Antonio	R. L. Polk Co., Publishers	Image pg. A7
1990	Chan Donald	R. L. Polk Co., Publishers	Image pg. A16
1979	Lee Harry L	R.L. Polk CO.	Image pg. A47
1975	Lee Harry L	R.L. Polk CO.	Image pg. A57

FINDINGS

Year	Uses	Source	
1970	Lee Harry L	R. L. Polk Co., Publishers	Image pg. A65
1940	AWong Young Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Sievers Ferdinand R ctr F W A Sievers h	Polk-Husted Directory	

430 S SAN JOAQUIN ST

Year	Uses	Source	
2017	JOSE SALDANA	Cole Information Services	
2014	NOEMI PADILLA	Cole Information Services	
2009	NOEMI PADILLA	Cole Information Services	
2004	NOEMI PADILLA	Cole Information Services	
1999	NOEMI PADILLA	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1990	Soeung Phoeung	R. L. Polk Co., Publishers	Image pg. A22
1979	Lee Harry L phys	R.L. Polk CO.	Image pg. A47
1975	Lee Harry L phys	R.L. Polk CO.	Image pg. A57
1970	Lee Harry L phys H	R. L. Polk Co., Publishers	Image pg. A65
1940	Aldazabal Segundo	R. L. Polk Co., Publishers	Image pg. A115
1911	Gambetta Carmeleta w id John h	Polk-Husted Directory	

431 S SAN JOAQUIN ST

Year	Uses	Source	
1990	a Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A22
	b Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A22
1979	Godoy Louie	R.L. Polk CO.	Image pg. A47
	a Hei nandez Gregory	R.L. Polk CO.	Image pg. A47
1975	Gutierras Lepoldo	R.L. Polk CO.	Image pg. A57
	a Hernandez Gregory	R.L. Polk CO.	Image pg. A57
1970	a Tearo Paul	R. L. Polk Co., Publishers	Image pg. A65
	Huante Jenny M Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1911	Hoult David J foremn H & H Mnfg Co h	Polk-Husted Directory	
	Hoult Urban J clk Holden Drug Co b	Polk-Husted Directory	
1906	Hoult David J emp H & H Mfg Co r	A. KINGSBURY CO	
	Hoult Urban J clk Holden Drug Co r	A. KINGSBURY CO	

FINDINGS

432 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A16

435 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1979	b Vacant	R.L. Polk CO.	Image pg. A47
1975	Ahmad Abdul S	R.L. Polk CO.	Image pg. A57
	bLaue Leopoldo	R.L. Polk CO.	Image pg. A57
1970	Ahmad Abdul S	R. L. Polk Co., Publishers	Image pg. A65
1940	Hoult Bee Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Costello Wm F telg opr S P Co h	Polk-Husted Directory	

436 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A22

437 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Gospel Center Annex	R. L. Polk Co., Publishers	Image pg. A22
1979	Turner Fletcher	R.L. Polk CO.	Image pg. A47
1975	Stewart Dee	R.L. Polk CO.	Image pg. A57
1970	Hood Janet Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Small E R Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Osborn Geo F dept mngr Joe Gianelli Co h	Polk-Husted Directory	

440 S SAN JOAQUIN ST

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
1999	BING KONG TONG	Cole Information Services
1994	BING KONG TONG	Cole Information Services

FINDINGS

Year	Uses	Source	
1990	Tong Kong	R. L. Polk Co., Publishers	Image pg. A22
1979	Mrrtin Anaclato	R.L. Polk CO.	Image pg. A47
1975	Martin Anaclato	R.L. Polk CO.	Image pg. A57
1970	Louie Lung On	R. L. Polk Co., Publishers	Image pg. A65
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1911	Ziegler Grant L driver Torre Vassallo Co b	Polk-Husted Directory	
	Vassallo Jas pres Torre Vassallo Co h	Polk-Husted Directory	

442 S SAN JOAQUIN ST

Year	Uses	Source	
2017	LONI THORNTON	Cole Information Services	
2014	LONI THORNTON	Cole Information Services	
2009	HUON OEURN	Cole Information Services	
2004	HUON OEURN	Cole Information Services	
1999	HUON OEURN	Cole Information Services	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A22
1979	Supnet Ciriaco C	R.L. Polk CO.	Image pg. A47
1975	Supnet Ciriaco C	R.L. Polk CO.	Image pg. A57
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115

445 S SAN JOAQUIN ST

Year	Uses	Source	
2009	GOSPEL CENTER	Cole Information Services	
2004	GOSPEL CTR RESCUE MISSION	Cole Information Services	
1999	GOSPEL CENTER RESCUE MISSION MAIN OFFICE	Cole Information Services	
	Thomas Frank	R. L. Polk Co., Publishers	Image pg. A7
	Moore Karen R	R. L. Polk Co., Publishers	Image pg. A7
	MISSION indvdl family svcs	R. L. Polk Co., Publishers	Image pg. A7
	GOSPEL CENTER RESCUE	R. L. Polk Co., Publishers	Image pg. A7
1994	GOSPEL CENTER RESCUE MISSION	Cole Information Services	
1990	Inner City Christian Academy	R. L. Polk Co., Publishers	Image pg. A22
	Gospel Center Rescue Ministries	R. L. Polk Co., Publishers	Image pg. A22
1979	Fraser Heating Co	R.L. Polk CO.	Image pg. A47

FINDINGS

Year	Uses	Source	
1975	Fraser Heating Co	R.L. Polk CO.	Image pg. A57
1970	Eraser Heating Co contrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Fermin Alustiza	R. L. Polk Co., Publishers	Image pg. A115
	Fraser Furnace Co	R. L. Polk Co., Publishers	Image pg. A115

448 S SAN JOAQUIN ST

Year	Uses	Source	
2017	CATHY ERNAS	Cole Information Services	
	MARK LAO	Cole Information Services	
	EDGAR MAGSAYO	Cole Information Services	
	FELICIANO CELLERO	Cole Information Services	
	OSCAR MAGSAYO	Cole Information Services	
	MAGSAYO GAUDENCIA	Cole Information Services	
2014	GAUDENCIA MAGSAYO	Cole Information Services	
	PRUDENCIA CELLERO	Cole Information Services	
	MARK LAO	Cole Information Services	
	ARCANGELA CAJARO	Cole Information Services	
	FLORFINA OLAY	Cole Information Services	
2009	DORIS LAO	Cole Information Services	
	CATHERINE MAGSAYO	Cole Information Services	
	PRUDENCIA CELLERO	Cole Information Services	
	FRANK DALAO	Cole Information Services	
	N MAGSAYO	Cole Information Services	
2004	ROSEMARIE BONACHITA	Cole Information Services	
	OSCAR MAGSAYO	Cole Information Services	
	PRUDENCIA CELLERO	Cole Information Services	
	DELBERT COLLINS	Cole Information Services	
1999	PRUDENCIA CELLERO	Cole Information Services	
	DORIS LAO	Cole Information Services	
	FRANK DALAO	Cole Information Services	
	Acain Marivic	R. L. Polk Co., Publishers	Image pg. A7
	Cellero Prudencia B	R. L. Polk Co., Publishers	Image pg. A7
	Collins Delbert	R. L. Polk Co., Publishers	Image pg. A7

FINDINGS

Year	Uses	Source	
1999	Ernas Luz	R. L. Polk Co., Publishers	Image pg. A7
	Padua R B ED 1 A	R. L. Polk Co., Publishers	Image pg. A7
	Padua Tedfilo B	R. L. Polk Co., Publishers	Image pg. A7
	Rubi Peter	R. L. Polk Co., Publishers	Image pg. A7
	Villarta Darcyfel	R. L. Polk Co., Publishers	Image pg. A7
1994	GALACIO, GAUDENC S	Cole Information Services	
1990	Amo Apartments	R. L. Polk Co., Publishers	Image pg. A22
	Rabaca Lillia R Mrs	R. L. Polk Co., Publishers	Image pg. A22
	Racho Rudy	R. L. Polk Co., Publishers	Image pg. A22
	Maglinte Allan	R. L. Polk Co., Publishers	Image pg. A22
	Nascalo Cora	R. L. Polk Co., Publishers	Image pg. A22
	Magsayo Laureano	R. L. Polk Co., Publishers	Image pg. A22
	Ruotito Feliciano	R. L. Polk Co., Publishers	Image pg. A22
	Sison Victor	R. L. Polk Co., Publishers	Image pg. A22
	No Return	R. L. Polk Co., Publishers	Image pg. A22
1979	Riego Nida	R.L. Polk CO.	Image pg. A47
	Lomoljo Jerry L	R.L. Polk CO.	Image pg. A47
	Jung Jang	R.L. Polk CO.	Image pg. A47
	Vacant	R.L. Polk CO.	Image pg. A47
	Gascon Isabelo	R.L. Polk CO.	Image pg. A47
	Corrales Mike	R.L. Polk CO.	Image pg. A47
	Rabaca M	R.L. Polk CO.	Image pg. A47
	Ai no Apartments	R.L. Polk CO.	Image pg. A47
1975	Riego Niedo	R.L. Polk CO.	Image pg. A57
	Ruotitu C	R.L. Polk CO.	Image pg. A57
	Me Gill T	R.L. Polk CO.	Image pg. A57
	Jung Jang	R.L. Polk CO.	Image pg. A57
	Rangell Eug M	R.L. Polk CO.	Image pg. A57
	Meeker Christina	R.L. Polk CO.	Image pg. A57
	Arno Apartments	R.L. Polk CO.	Image pg. A57
	Nails Edgar	R.L. Polk CO.	Image pg. A57
1970	Cesmat Emily B	R. L. Polk Co., Publishers	Image pg. A65

FINDINGS

Year	Uses	Source	
1970	Smith Dorothy L	R. L. Polk Co., Publishers	Image pg. A65
	Gerard Gene	R. L. Polk Co., Publishers	Image pg. A65
	Jung Jang	R. L. Polk Co., Publishers	Image pg. A65
	Folmar John H	R. L. Polk Co., Publishers	Image pg. A65
	Romano Lorenzo P	R. L. Polk Co., Publishers	Image pg. A65
	Hood Robt	R. L. Polk Co., Publishers	Image pg. A65
	Arno Apartments	R. L. Polk Co., Publishers	Image pg. A65

462 S SAN JOAQUIN ST

Year	Uses	Source
2014	LAMONT DEAN	Cole Information Services

501 S SAN JOAQUIN ST

Year	Uses	Source	
1940	a Miller F A chiropo	R. L. Polk Co., Publishers	Image pg. A121

502 S SAN JOAQUIN ST

Year	Uses	Source	
2009	SANJOAQUIN GROCERY	Cole Information Services	
	CIGARETTES FOR LESS	Cole Information Services	
1999	TSU V MARKET	Cole Information Services	
	T S U V MARKET grocery stores	R. L. Polk Co., Publishers	Image pg. A7
1996	TSU V MARKET	R. L. Polk Co., Publishers	Image pg. A14
1994	UNIVERSAL MARKET	Cole Information Services	
1990	Universal Market mkt	R. L. Polk Co., Publishers	Image pg. A22
1979	Go Orient Imports	R.L. Polk CO.	Image pg. A47
1975	East & West Tv Radio Service	R.L. Polk CO.	Image pg. A57
1970	East & West Tv Radio Servica	R. L. Polk Co., Publishers	Image pg. A65
1911	Lucchesi Frank grocer	Polk-Husted Directory	
1906	BATTILANA GIUSEPPE groceries and provisions	A. KINGSBURY CO	

503 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Personal Finance Co	R. L. Polk Co., Publishers	Image pg. A121

FINDINGS

Year	Uses	Source	
1911	Schmidt Robt L clk I X L Clo Co b	Polk-Husted Directory	
	Schmidt Maurice F clk C C T Co b	Polk-Husted Directory	
	Schmidt Aurel glassw kr h	Polk-Husted Directory	
1906	CROCKETT GEO W agt Wells Fargo & Co Express r	A. KINGSBURY CO	

504 S SAN JOAQUIN ST

Year	Uses	Source	
2017	CORAZON ARELLANO	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1975	Vacant	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	Minaglia Manuel	R. L. Polk Co., Publishers	Image pg. A115
1911	Sheehan Margaret w id Timothy h	Polk-Husted Directory	
	Sheehan John A lab b	Polk-Husted Directory	
	Sheehan Ida M clk Wm Emden Co b	Polk-Husted Directory	
	Sheehan Edw J carmn S E R R Co b	Polk-Husted Directory	
1906	Schw eitzer James cond A T & S F r	A. KINGSBURY CO	
	Garren Calvin emp M P Henderson & Son r	A. KINGSBURY CO	

505 S SAN JOAQUIN ST

Year	Uses	Source	
1979	Stockton Plasma Center	R.L. Polk CO.	Image pg. A47
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	ADustin M J dentist	R. L. Polk Co., Publishers	Image pg. A121

506 S SAN JOAQUIN ST

Year	Uses	Source
2017	BENITO CELLERO	Cole Information Services
	JACKY TAN	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services
	BENITO CELLERO	Cole Information Services
2009	BENITO CELLERO	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
2004	EMMA BARIAS	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	BENITO CELLERO	Cole Information Services	
	ACUPUNCTURE CLEANING ofcs hith prnrs	R. L. Polk Co., Publishers	Image pg. A7
	CHIH CHEN CHUAN	R. L. Polk Co., Publishers	Image pg. A7
	t Corpus C	R. L. Polk Co., Publishers	Image pg. A7
	Corpus Leonardo A	R. L. Polk Co., Publishers	Image pg. A7
1996	Untalan G	R. L. Polk Co., Publishers	Image pg. A14
	OB Bongo Beverly	R. L. Polk Co., Publishers	Image pg. A14
	Corpus C M	R. L. Polk Co., Publishers	Image pg. A14
1990	Acupuncture Clinic	R. L. Polk Co., Publishers	Image pg. A22
1979	Vj Burgos Frederico Q	R.L. Polk CO.	Image pg. A47
	Roxas Manuel Club Room	R.L. Polk CO.	Image pg. A47
1975	Burgos Frederico Q	R.L. Polk CO.	Image pg. A57
	Go Orient Imports oriental	R.L. Polk CO.	Image pg. A57
1940	w Cunningham Wm	R. L. Polk Co., Publishers	Image pg. A115
	fruit shippers	R. L. Polk Co., Publishers	Image pg. A121
	AMjaurer J C & Sons	R. L. Polk Co., Publishers	Image pg. A121
1911	Ramsey Edw K trav salsn h	Polk-Husted Directory	
1906	r	A. KINGSBURY CO	
	BATTILANA GIUSEPPE groceries and provisions	A. KINGSBURY CO	

508 S SAN JOAQUIN ST

Year	Uses	Source
2014	RODOLFO MEDIAM	Cole Information Services
	GRACE MIETIAM	Cole Information Services
	MANUEL FURNIS	Cole Information Services
	REBECCA DUMO	Cole Information Services
2009	ELINNO DUMO	Cole Information Services
	RODOLFO MEDIAM	Cole Information Services
	EUGENIA FURNIS	Cole Information Services
	MANUEL BERNARDINO	Cole Information Services
2004	EUGENIA FURNIS	Cole Information Services
	MANUEL BERNARDINO	Cole Information Services
	E DUMO	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	RODOLFO MEDIAM	Cole Information Services	
	MANUEL BERNARDINO	Cole Information Services	
	ELINNO DUMO	Cole Information Services	
	EUGENIA FURNIS	Cole Information Services	
	Nuevo Benita	R. L. Polk Co., Publishers	Image pg. A7
1979	Matote Esteban	R.L. Polk CO.	Image pg. A47
1975	Matote Esteban	R.L. Polk CO.	Image pg. A57
1940	a Fairbanks E A	R. L. Polk Co., Publishers	Image pg. A115
	Moore L E	R. L. Polk Co., Publishers	Image pg. A115
1911	Nagle Edmond H dept mngr Joe Gianelli Co h	Polk-Husted Directory	
1906	Memsen James W emp Lew is & Johnson r	A. KINGSBURY CO	

509 S SAN JOAQUIN ST

Year	Uses	Source
1911	Fontana Annunciade w id Andrew h	Polk-Husted Directory
	Fontana Dede b	Polk-Husted Directory

510 S SAN JOAQUIN ST

Year	Uses	Source	
2017	HELENA CAPITAO	Cole Information Services	
2014	HELENA CAPITAO	Cole Information Services	
2009	HELENA CAPITAO	Cole Information Services	
2004	HELENA CAPITAO	Cole Information Services	
1999	Capitao Helena	R. L. Polk Co., Publishers	Image pg. A7
1990	Mendoza Julia	R. L. Polk Co., Publishers	Image pg. A22
1979	Barragan Juana	R.L. Polk CO.	Image pg. A47
1975	Shipes Cynthia	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	dancing tchr	R. L. Polk Co., Publishers	Image pg. A115
	Fairbanks Lorraine	R. L. Polk Co., Publishers	Image pg. A115
	pract	R. L. Polk Co., Publishers	Image pg. A121
	a Minturn T R jr C S	R. L. Polk Co., Publishers	Image pg. A121
	pract	R. L. Polk Co., Publishers	Image pg. A121
	AHackett I C Mrs C S	R. L. Polk Co., Publishers	Image pg. A121

Year	Uses	Source	
1911	Beckman L eng S Fe Ry r	Polk-Husted Directory	
	Truax E H eng S Fe Ry r	Polk-Husted Directory	

512 S SAN JOAQUIN ST

Year	Uses	Source	
2009	ANTHONY BOLOGNA	Cole Information Services	
2004	JOSE AGUILAR	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	ANTHONY BOLOGNA	Cole Information Services	
1979	Wilson Florence A Mrs	R.L. Polk CO.	Image pg. A47
1975	Wilson Florence A Mrs	R.L. Polk CO.	Image pg. A57
1970	Wilson Florence Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Jensen Walter dental	R. L. Polk Co., Publishers	Image pg. A121
	labty	R. L. Polk Co., Publishers	Image pg. A121
	Cunningham Mary	R. L. Polk Co., Publishers	Image pg. A115
1911	Lynch Edw farmer h	Polk-Husted Directory	

513 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Ford E J	R. L. Polk Co., Publishers	Image pg. A115

514 S SAN JOAQUIN ST

Year	Uses	Source	
2017	ELIAS LINARES	Cole Information Services	
2014	ELIAS LINARES	Cole Information Services	
2009	ELIAS LINARES	Cole Information Services	
2004	MARTIN PEGRO	Cole Information Services	
	P JOSE	Cole Information Services	
	MIGUEL MALAGA	Cole Information Services	
1999	ELIAS LINARES	Cole Information Services	
	Venegas Nestor	R. L. Polk Co., Publishers	Image pg. A7
	Yanez Isidoro	R. L. Polk Co., Publishers	Image pg. A7
1994	SINGKEO, HOM	Cole Information Services	
	PRASEUDSUK, PHONG	Cole Information Services	

FINDINGS

Year	Uses	Source	
1979	b Ning Fotng	R.L. Polk CO.	Image pg. A47
	a Toy Buck Suey	R.L. Polk CO.	Image pg. A47
1975	Gamez Mar	R.L. Polk CO.	Image pg. A57
	Ning Toy Sin	R.L. Polk CO.	Image pg. A57
1970	Ning Toy Sin	R. L. Polk Co., Publishers	Image pg. A65
	Gomez Mary Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Mullis W C	R. L. Polk Co., Publishers	Image pg. A115
	Goldstein J H	R. L. Polk Co., Publishers	Image pg. A115
1911	Crow ell Timothy J hngr Blanchard G Co h	Polk-Husted Directory	

516 S SAN JOAQUIN ST

Year	Uses	Source	
2014	AGUSTIN LOPEZ	Cole Information Services	
2009	AGUSTIN LOPEZ	Cole Information Services	
2004	AGUSTIN LOPEZ	Cole Information Services	
1999	AGUSTIN LOPEZ	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1979	Savila Louis	R.L. Polk CO.	Image pg. A47
1975	Matote L A	R.L. Polk CO.	Image pg. A57
1970	Melchor Leoncio	R. L. Polk Co., Publishers	Image pg. A65
1940	Telena Antonio	R. L. Polk Co., Publishers	Image pg. A115
1911	Gouber V mach Samson l Wks r	Polk-Husted Directory	

517 S SAN JOAQUIN ST

Year	Uses	Source	
2017	WEI HUANG	Cole Information Services	
2014	WEI HUANG	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	SINNATHA KEOMANIVONG	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	EM, HORN	Cole Information Services	
1979	Lopez Mary C	R.L. Polk CO.	Image pg. A47
1975	Placancia Patricia	R.L. Polk CO.	Image pg. A57
1970	Chu Ping	R. L. Polk Co., Publishers	Image pg. A65

FINDINGS

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115
1906	Von Detten Henry J comp Atwood Printing Co r	A. KINGSBURY CO	

518 S SAN JOAQUIN ST

Year	Uses	Source	
1999	Markowitz Roger	R. L. Polk Co., Publishers	Image pg. A7
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A22
1979	Vacant	R.L. Polk CO.	Image pg. A47
1975	Corren M And Sons Whse	R.L. Polk CO.	Image pg. A57
1970	Corren M And Sons Whse	R. L. Polk Co., Publishers	Image pg. A65
1940	Corren M & Sons w hs	R. L. Polk Co., Publishers	Image pg. A115

519 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	PHAIBOUN SOUKKASEUM	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Soukkaseum Xaiphone	R. L. Polk Co., Publishers	Image pg. A7
	Not Verified	R. L. Polk Co., Publishers	Image pg. A7
	Soukkaseum Phaiboun	R. L. Polk Co., Publishers	Image pg. A7
1979	Ramerez Ganzalo	R.L. Polk CO.	Image pg. A47
1975	Mobanic Eddy	R.L. Polk CO.	Image pg. A57
1970	Mah Wing	R. L. Polk Co., Publishers	Image pg. A65
1940	ABlair Cath Mrs	R. L. Polk Co., Publishers	Image pg. A115

521 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	CHAO TAN	Cole Information Services	
2004	T KOEMANIVONG	Cole Information Services	
1999	CHAO TAN	Cole Information Services	
	Saengkhed Mon	R. L. Polk Co., Publishers	Image pg. A7
1994	TOR, ROAUN	Cole Information Services	

FINDINGS

Year	Uses	Source	
1979	Cadiz Larry	R.L. Polk CO.	Image pg. A47
1975	Cadiz Larry	R.L. Polk CO.	Image pg. A57
1970	Cadiz Larry	R. L. Polk Co., Publishers	Image pg. A65
1940	Guidice D G Mrs	R. L. Polk Co., Publishers	Image pg. A115

522 S SAN JOAQUIN ST

Year	Uses	Source
1911	Battilana Giuseppe Battilana & Tassano real est	Polk-Husted Directory
	h	Polk-Husted Directory
	Battilana Peter b	Polk-Husted Directory
1906	Smith James A eng W P Ry r	A. KINGSBURY CO

523 S SAN JOAQUIN ST

Year	Uses	Source	
2017	JOHN YEE	Cole Information Services	
	YEE FUNG TOY FAMILY ASSOCIATION OF S	Cole Information Services	
2014	YEE FUNG TOY FAMILY ASSOCIATION OF S	Cole Information Services	
	JOHN YEE	Cole Information Services	
2009	YEE FUNG TOY FAMILY ASSOCIATION	Cole Information Services	
	JOHN YEE	Cole Information Services	
2004	JOHN YEE	Cole Information Services	
	YEE FUNG TOY FAMILY ASCTN	Cole Information Services	
1999	YEE FUNG TOY FAMILY ASSOCIATION OF STOCKTON	Cole Information Services	
	JOHN YEE	Cole Information Services	
1979	Nigrana Santago	R.L. Polk CO.	Image pg. A47
1975	Nigrana Santago	R.L. Polk CO.	Image pg. A57
1970	Fong Herbert	R. L. Polk Co., Publishers	Image pg. A65
1940	Whalen Richd	R. L. Polk Co., Publishers	Image pg. A115

528 S SAN JOAQUIN ST

Year	Uses	Source
2017	SANTIAGO RAMIREZ	Cole Information Services

FINDINGS

Year	Uses	Source	
2014	SANTIAGO RAMIREZ	Cole Information Services	
2009	SANTIAGO RAMIREZ	Cole Information Services	
2004	PABLO LOMELI	Cole Information Services	
1999	SANTIAGO RAMIREZ	Cole Information Services	
	Domench John A	R. L. Polk Co., Publishers	Image pg. A7
1990	Domench Johnny R	R. L. Polk Co., Publishers	Image pg. A22
1979	Domench Josefas Mrs	R.L. Polk CO.	Image pg. A47
	Etchecopar Luise Mrs	R.L. Polk CO.	Image pg. A55
1975	Domench Josefas Mrs	R.L. Polk CO.	Image pg. A57
1970	Domench Josefas Mrs	R. L. Polk Co., Publishers	Image pg. A65
1940	Domench Saturino	R. L. Polk Co., Publishers	Image pg. A115
1911	Kidd John H foremn S Fe Ry h	Polk-Husted Directory	
1906	Kehoe Mary A Mrs r	A. KINGSBURY CO	
	Kehoe Mary E Miss r	A. KINGSBURY CO	
	Melbourne John W emp A T & S F r	A. KINGSBURY CO	

529 S SAN JOAQUIN ST

Year	Uses	Source	
2017	REY CAMPANUR	Cole Information Services	
2014	SARAH SALAS	Cole Information Services	
2009	SAMMY RUIZ	Cole Information Services	
2004	SAMMY RUIZ	Cole Information Services	
1999	SAMMY RUIZ	Cole Information Services	
	Ruiz Frances V	R. L. Polk Co., Publishers	Image pg. A7
	Ruiz Sammy J Sr	R. L. Polk Co., Publishers	Image pg. A7
1979	Lee Wee	R.L. Polk CO.	Image pg. A55
	Lee Kw ong Wah acupunturist	R.L. Polk CO.	Image pg. A55
1975	Lee Johnny Y	R.L. Polk CO.	Image pg. A57
1970	Yip Sim	R. L. Polk Co., Publishers	Image pg. A65
1940	a Cesmat Emile	R. L. Polk Co., Publishers	Image pg. A115
1911	Reinhart Anna b	Polk-Husted Directory	
	Harelson Wm E hlpr Pavilion Garage b	Polk-Husted Directory	
	Harelson Evelyn A w id W B h	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1906	Earl Annie Mrs r	A. KINGSBURY CO	
	Earl John S clk R J Wheeler r	A. KINGSBURY CO	

530 S SAN JOAQUIN ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	JARAMILLO, MARIA M	Cole Information Services	
1970	C Y C Of Stockton	R. L. Polk Co., Publishers	Image pg. A65

534 S SAN JOAQUIN ST

Year	Uses	Source	
2017	DANNY BUN	Cole Information Services	
2014	WAN LI	Cole Information Services	
2009	SHUN LIU	Cole Information Services	
1999	SHUN LIU	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
1994	LEW, KWOK J	Cole Information Services	
1979	Wong Ming	R.L. Polk CO.	Image pg. A55
1975	Vacant	R.L. Polk CO.	Image pg. A57
1970	Nortacutte Herbarn	R. L. Polk Co., Publishers	Image pg. A65
1940	Xvhitlock H C	R. L. Polk Co., Publishers	Image pg. A115
1911	Walker Edw cond S Fe Ry h	Polk-Husted Directory	

535 S SAN JOAQUIN ST

Year	Uses	Source	
2014	KWONG TUCK WO	Cole Information Services	
2009	KWONG TUCK WO	Cole Information Services	
2004	KWONG TUCK WO	Cole Information Services	
1999	KWONG TUCK WO	Cole Information Services	
	Chin Kon J Ml	R. L. Polk Co., Publishers	Image pg. A7
	Chin Jean L	R. L. Polk Co., Publishers	Image pg. A7
	KWONG TRUCK WO CO	R. L. Polk Co., Publishers	Image pg. A7
	groceries gnrl lne	R. L. Polk Co., Publishers	Image pg. A7
1996	KWONG TUCK WO	R. L. Polk Co., Publishers	Image pg. A14

FINDINGS

Year	Uses	Source	
1994	FONG, SHU C	Cole Information Services	
	KWONG TUCK WO	Cole Information Services	
1979	Kw ong Tuck Wo Co	R.L. Polk CO.	Image pg. A55
1975	c Vacant	R.L. Polk CO.	Image pg. A57
	Kw ong Tuck Wo Co	R.L. Polk CO.	Image pg. A57
	a Chin Kon Joy	R.L. Polk CO.	Image pg. A57
	b Vacant	R.L. Polk CO.	Image pg. A57
1970	Wong Ben K	R. L. Polk Co., Publishers	Image pg. A65
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A115

536 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	SAROEUN CHHIN	Cole Information Services	
2004	SAROEUN CHHIN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	SAROEUN CHHIN	Cole Information Services	
1990	a Kw ong Tuck Wo gro	R. L. Polk Co., Publishers	Image pg. A22
	b Fong Shu Chen	R. L. Polk Co., Publishers	Image pg. A22
1979	Lopez Christian	R.L. Polk CO.	Image pg. A55
1975	No Return	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65
1940	Errecart Anna Mrs	R. L. Polk Co., Publishers	Image pg. A115
1911	Stephens Milton elk S Fe Ry h	Polk-Husted Directory	

537 S SAN JOAQUIN ST

Year	Uses	Source	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1994	VELARDE, A	Cole Information Services	
1940	Hoult Mary E	R. L. Polk Co., Publishers	Image pg. A115

538 S SAN JOAQUIN ST

Year	Uses	Source
2017	GEE TIN	Cole Information Services

FINDINGS

Year	Uses	Source	
2014	GEE TIN	Cole Information Services	
2009	GEE OAK-TIN	Cole Information Services	
2004	GEE OAKTIN	Cole Information Services	
	OAK TIN GEE	Cole Information Services	
1999	GEE OAK-TIN	Cole Information Services	
	Oak Tin Gee	R. L. Polk Co., Publishers	Image pg. A7
1994	OAKTIN, GEEHOW	Cole Information Services	
1990	&39 Chin Kon Joy	R. L. Polk Co., Publishers	Image pg. A22
	Oak Tin Gee How	R. L. Polk Co., Publishers	Image pg. A22
	Lew Kw ok J	R. L. Polk Co., Publishers	Image pg. A22
1979	Oak Tin Gee Haw Association meeting hall	R.L. Polk CO.	Image pg. A55
1975	Gee How Oak Tin Association meeting hall	R.L. Polk CO.	Image pg. A57
1970	Gee How Oak Tin Association meeting	R. L. Polk Co., Publishers	Image pg. A65
1940	Hoult W J	R. L. Polk Co., Publishers	Image pg. A115
1911	Mc Call Jas M tallymn Stkn Lbr Co h	Polk-Husted Directory	

539 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
1979	Apartments	R.L. Polk CO.	Image pg. A55
	A Chin Kon Joy	R.L. Polk CO.	Image pg. A55
	BSheung Yep C Kw an V	R.L. Polk CO.	Image pg. A55

540 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	SITHORN BUTH	Cole Information Services	
2004	SITHORN BUTH	Cole Information Services	
1999	SITHORN BUTH	Cole Information Services	
	Oung Sinath	R. L. Polk Co., Publishers	Image pg. A7
	Oung Sam	R. L. Polk Co., Publishers	Image pg. A7
1990	No Return	R. L. Polk Co., Publishers	Image pg. A22
1979	Gulindo Peter	R.L. Polk CO.	Image pg. A55
1975	Galindo	R.L. Polk CO.	Image pg. A57

FINDINGS

Year	Uses	Source	
1970	Riley Charles E	R. L. Polk Co., Publishers	Image pg. A65
1940	Mentaberry Felipa	R. L. Polk Co., Publishers	Image pg. A115

545 S SAN JOAQUIN ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	KING GEE	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A22
1979	Vacant	R.L. Polk CO.	Image pg. A55
1975	No Return	R.L. Polk CO.	Image pg. A57

547 S SAN JOAQUIN ST

Year	Uses	Source	
1994	JACKSON, JAMES D	Cole Information Services	

601 S SAN JOAQUIN ST

Year	Uses	Source	
1940	practor	R. L. Polk Co., Publishers	Image pg. A121
	Schumacher C H	R. L. Polk Co., Publishers	Image pg. A115
	ABramw ell C E chiro	R. L. Polk Co., Publishers	Image pg. A121

602 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Minaglia Manuel gro	R. L. Polk Co., Publishers	Image pg. A115

604 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A22
1979	Vacant	R.L. Polk CO.	Image pg. A47

605 S SAN JOAQUIN ST

Year	Uses	Source	
1940	Equitable Life Assur	R. L. Polk Co., Publishers	Image pg. A121
	ADonnelly C R ins	R. L. Polk Co., Publishers	Image pg. A121
	ance Society	R. L. Polk Co., Publishers	Image pg. A121

Year	Uses	Source	
1911	Murray Mrs Genevieve proofreader The Mail r	Polk-Husted Directory	

608 S SAN JOAQUIN ST

Year	Uses	Source	
1990	Matote Esteban	R. L. Polk Co., Publishers	Image pg. A22

609 S SAN JOAQUIN ST

Year	Uses	Source	
1979	Vacant	R.L. Polk CO.	Image pg. A55
1975	Community Parole Center	R.L. Polk CO.	Image pg. A57
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A65

610 S SAN JOAQUIN ST

Year	Uses	Source
1994	JONES, LAURA L	Cole Information Services
	BURK, MARCELL	Cole Information Services
	GUTIERREZ, ISRAEL	Cole Information Services
	CONNER, RAY	Cole Information Services

611 S SAN JOAQUIN ST

Year	Uses	Source	
1994	GREGORYS PRIVATE SOCIAL CLUB	Cole Information Services	
1990	Dunns Mini Mart gift shop	R. L. Polk Co., Publishers	Image pg. A22
1979	A & E Liquors	R.L. Polk CO.	Image pg. A55
1975	A & E Liquors	R.L. Polk CO.	Image pg. A57
1970	A&E Liquors	R. L. Polk Co., Publishers	Image pg. A65

612 S SAN JOAQUIN ST

Year	Uses	Source	
1990	No Return	R. L. Polk Co., Publishers	Image pg. A22
1940	AMelone G S C S pract	R. L. Polk Co., Publishers	Image pg. A121

613 S SAN JOAQUIN ST

Year	Uses	Source
2017	A & A DISCOUNT CIGARETTE	Cole Information Services
2014	A & A DISCOUNT CIGARETTE	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	A & A DISCOUNT & CIGARETTE	Cole Information Services	
	PATHWAY OF TRUTH APOSTOLIC CH	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A22
1979	Wash House The self serv laundromat	R.L. Polk CO.	Image pg. A55
1975	Wash House The self serv laundromat	R.L. Polk CO.	Image pg. A57
1970	Wash House The self serv laundromat	R. L. Polk Co., Publishers	Image pg. A65

614 S SAN JOAQUIN ST

Year	Uses	Source	
1990	a Nathong Xay	R. L. Polk Co., Publishers	Image pg. A22
	bt Eury Thos	R. L. Polk Co., Publishers	Image pg. A22

S SUTTER ST

301 S SUTTER ST

Year	Uses	Source	
1940	Pollrick Ernest restr	R. L. Polk Co., Publishers	Image pg. A122
1911	Gardella Stephano grocer	Polk-Husted Directory	
1906	Morris Wm junk	A. KINGSBURY CO	
	Morris Jennie Mrs hotel	A. KINGSBURY CO	
	Bynum Ab kalsominer r	A. KINGSBURY CO	
	Clipper Richard lab r	A. KINGSBURY CO	
	Cook Esther Miss r	A. KINGSBURY CO	
	Kemp Lizzie Miss r	A. KINGSBURY CO	
	Lee John lab r	A. KINGSBURY CO	
	Lee John lab r	A. KINGSBURY CO	
	Morris Albert jockey r	A. KINGSBURY CO	
	Morris Hotel	A. KINGSBURY CO	
	Bailey John porter r	A. KINGSBURY CO	
	Bannister John cook r	A. KINGSBURY CO	

305 S SUTTER ST

Year	Uses	Source
1911	Edmonds I M h	Polk-Husted Directory

FINDINGS

306 S SUTTER ST

Year	Uses	Source	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A8
1996	MY VINH SEWING SHOP	R. L. Polk Co., Publishers	Image pg. A15
1994	NGOC CHAU SEWING SHOP	Cole Information Services	
1990	Ngoc Chau Sew ing Shop	R. L. Polk Co., Publishers	Image pg. A23
	tow nhouses	R. L. Polk Co., Publishers	Image pg. A24
1975	Sutter Liquors	R.L. Polk CO.	Image pg. A63
1970	Sutter Liquors	R. L. Polk Co., Publishers	Image pg. A71

310 S SUTTER ST

Year	Uses	Source
1911	Murray Frank A horseshoer	Polk-Husted Directory
	h	Polk-Husted Directory
1906	Murray Frank A Fitzgerald & Murray r	A. KINGSBURY CO

313 S SUTTER ST

Year	Uses	Source
1911	Orsi Federigo M Orsi & Bro h	Polk-Husted Directory
1906	Gambetta Camelita Mrs r	A. KINGSBURY CO
	Gambetta Eugenia R Miss emp P Cahn & Co r	A. KINGSBURY CO
	Gambetta Adeline Miss opr S T & T Co r	A. KINGSBURY CO
	Gambetta Pauline Miss r	A. KINGSBURY CO
	Capurro Edna Miss stenog W J Horan r	A. KINGSBURY CO
	Capurro Rosie Mrs dressmkr	A. KINGSBURY CO

315 S SUTTER ST

Year	Uses	Source
2014	JODY SCHOBER	Cole Information Services
	BRETT OSTROM	Cole Information Services
	TAMMY GEPFORD	Cole Information Services
	ALISIA BROWN	Cole Information Services
2009	JOSE HERNANDEZ	Cole Information Services
	SIESAL KHAN	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	PAULA SUMMONS	Cole Information Services	
	WAYNE OSBORG	Cole Information Services	
	ANGELIC LALAYAMAMOTO	Cole Information Services	
	MALCOLM RICHARDSON	Cole Information Services	
	NHIA THAO	Cole Information Services	
	JODY SCHOBER	Cole Information Services	
	PETER JONES	Cole Information Services	
2004	BALTAZAR AGUIRRE	Cole Information Services	
	ALFONSO LOPEZ	Cole Information Services	
	WAYNE OSBORG	Cole Information Services	
	JOSE HERNANDEZ	Cole Information Services	
	ALEX MORA	Cole Information Services	
	ROBERT MORTON	Cole Information Services	
	HUOSDELI HERNANDEZ	Cole Information Services	
	JOSE GOMEZ	Cole Information Services	
1999	SIESAL KHAN	Cole Information Services	
	PAULA SUMMONS	Cole Information Services	
	WAYNE OSBORG	Cole Information Services	
	PETER JONES	Cole Information Services	
	NHIA THAO	Cole Information Services	
	JOSE HERNANDEZ	Cole Information Services	
	ANGELIC LALAYAMAMOTO	Cole Information Services	
	JODY SCHOBER	Cole Information Services	
	MALCOLM RICHARDSON	Cole Information Services	
	RODRIGO MALDONADO	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A8
	Dias Lorena	R. L. Polk Co., Publishers	Image pg. A8
1990	Louis Apartments	R. L. Polk Co., Publishers	Image pg. A24
	lTorrez Yesenia	R. L. Polk Co., Publishers	Image pg. A24
	r Serrano Tomas	R. L. Polk Co., Publishers	Image pg. A24
	Vacant	R. L. Polk Co., Publishers	Image pg. A24
	Rios Felipa	R. L. Polk Co., Publishers	Image pg. A24

FINDINGS

Year	Uses	Source	
1990	Dominguez Jose	R. L. Polk Co., Publishers	Image pg. A24
	Ramirez Juan	R. L. Polk Co., Publishers	Image pg. A24
	Martinez Jose	R. L. Polk Co., Publishers	Image pg. A24
	Williams Rick	R. L. Polk Co., Publishers	Image pg. A24
1975	Louis Apartments	R.L. Polk CO.	Image pg. A63
	Magana Antonio	R.L. Polk CO.	Image pg. A63
	Vacant	R.L. Polk CO.	Image pg. A63
	Vacant	R.L. Polk CO.	Image pg. A63
	Tooson Mary	R.L. Polk CO.	Image pg. A63
	Silver Dill	R.L. Polk CO.	Image pg. A63
	Garcia Bernado	R.L. Polk CO.	Image pg. A63
	Gomez Bernado	R.L. Polk CO.	Image pg. A63
	Rodriquez Gloria	R.L. Polk CO.	Image pg. A63
1970	Louis Apartments	R. L. Polk Co., Publishers	Image pg. A71
	Flores Joe	R. L. Polk Co., Publishers	Image pg. A71
	Singh Cruz	R. L. Polk Co., Publishers	Image pg. A71
1940	a Gardella Apartments	R. L. Polk Co., Publishers	Image pg. A122
	Brow n D D	R. L. Polk Co., Publishers	Image pg. A122
	Charlo John	R. L. Polk Co., Publishers	Image pg. A122
	Hurd 0 R	R. L. Polk Co., Publishers	Image pg. A122
	Neumeister Carl	R. L. Polk Co., Publishers	Image pg. A122
	North F C	R. L. Polk Co., Publishers	Image pg. A122
	Smith G N	R. L. Polk Co., Publishers	Image pg. A122

317 S SUTTER ST

Year	Uses	Source
1911	Palacio Paul lab h	Polk-Husted Directory

319 S SUTTER ST

Year	Uses	Source	
1940	Clemons Maude Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Davis Elizabeth A w id Frank h	Polk-Husted Directory	
	h	Polk-Husted Directory	
	Dale Myron C brass founder	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1911	Convey John ctr Wagner Meat Co h	Polk-Husted Directory	
	Fitchie Saml B hngr L A Danner h	Polk-Husted Directory	
1906	Smith Wm r	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	NEWCOME FRANK mines stocks bonds timber lands	A. KINGSBURY CO	
	Davis Elizabeth A Mrs r	A. KINGSBURY CO	
	Cline Chas emp Pac W G Co r	A. KINGSBURY CO	
	Bender Geo L r	A. KINGSBURY CO	

320 S SUTTER ST

Year	Uses	Source	
1970	Sarmiento Max	R. L. Polk Co., Publishers	Image pg. A71
1940	AGaribotto G B	R. L. Polk Co., Publishers	Image pg. A122
1911	Baird Chas hlpr Stkn I Wks r	Polk-Husted Directory	
	Morgan Wm B salsn h	Polk-Husted Directory	
1906	Logan James A trav agt Stockton: Paint Co r	A. KINGSBURY CO	

321 S SUTTER ST

Year	Uses	Source	
1940	Spicer Jas	R. L. Polk Co., Publishers	Image pg. A122

328 S SUTTER ST

Year	Uses	Source	
1940	Shockey F L	R. L. Polk Co., Publishers	Image pg. A122
1911	Gormann Jos adv mngr Garrick Theatre r	Polk-Husted Directory	
	Bacheller Ralph M v pres Sterling Iron Wks h	Polk-Husted Directory	
1906	Bacheller Ralph M mach S Iron Works r	A. KINGSBURY CO	
	Adkins John C r	A. KINGSBURY CO	

329 S SUTTER ST

Year	Uses	Source	
1940	Lindsay Mabel Mrs	R. L. Polk Co., Publishers	Image pg. A122
1906	Gall Bessie Miss r	A. KINGSBURY CO	
	Gall Jos M auctioneer r	A. KINGSBURY CO	

FINDINGS

333 S SUTTER ST

Year	Uses	Source	
2017	ON LOCK SAM	Cole Information Services	
2014	ON LOCK SAM	Cole Information Services	
2009	ON LOCK SAM INC	Cole Information Services	
1999	ON LOCK SAM RESTAURANT	Cole Information Services	
	ON LOCK SAM RESTAURANT eating places	R. L. Polk Co., Publishers	Image pg. A8
1996	ON LOCK SAM RESTAURANT	R. L. Polk Co., Publishers	Image pg. A15
1994	ON LOCK SAM RESTAURANT	Cole Information Services	
1990	On Lock Sam restr	R. L. Polk Co., Publishers	Image pg. A24
1975	On Lock Sam restr	R.L. Polk CO.	Image pg. A63
1970	On Lock Sam restr	R. L. Polk Co., Publishers	Image pg. A71
1906	Haack John meat market	A. KINGSBURY CO	

336 S SUTTER ST

Year	Uses	Source	
1940	a New World Sun The	R. L. Polk Co., Publishers	Image pg. A122
	Ohashi Kanzo	R. L. Polk Co., Publishers	Image pg. A122
1911	Kingsbury M Alice w id M H tchr Washn Sch h	Polk-Husted Directory	
	Kingsbury M Alice stngr b	Polk-Husted Directory	
	Kingsbury Amanda G tchr b	Polk-Husted Directory	
1906	Kingsbury M Alice Mrs teacher Washington School r	A. KINGSBURY CO	

341 S SUTTER ST

Year	Uses	Source	
1940	Mc Daniels Mary Mrs	R. L. Polk Co., Publishers	Image pg. A122
	Lancaster Lucy Mrs	R. L. Polk Co., Publishers	Image pg. A122
	Kaiser Henry	R. L. Polk Co., Publishers	Image pg. A122
	How es N E Mrs	R. L. Polk Co., Publishers	Image pg. A122
	Dorman Marie Mrs	R. L. Polk Co., Publishers	Image pg. A122
	Bow man C J	R. L. Polk Co., Publishers	Image pg. A122
1911	Sorensen Caroline w id C W h	Polk-Husted Directory	
	Oliver Wm H painter h	Polk-Husted Directory	

FINDINGS

Year	Uses	Source	
1911	Kaiser Henry farmer h	Polk-Husted Directory	
1906	Ray Fred E clk r	A. KINGSBURY CO	
	Sorensen Caroline Mrs r	A. KINGSBURY CO	
	Murray Jennie Miss r	A. KINGSBURY CO	
	Murray Geneva Mrs proofreader The Mail r	A. KINGSBURY CO	
	Kaiser Henry r	A. KINGSBURY CO	

344 S SUTTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	GEORGE CASILLAS	Cole Information Services	
2004	JUAN ZUNIGA	Cole Information Services	
1999	Wong Kin 3	R. L. Polk Co., Publishers	Image pg. A8
1994	WONG, KIN	Cole Information Services	
1990	Wong Lee S	R. L. Polk Co., Publishers	Image pg. A24
	Wong Yip	R. L. Polk Co., Publishers	Image pg. A24
1975	Wong Lee S	R.L. Polk CO.	Image pg. A63
1970	Wong Lee S	R. L. Polk Co., Publishers	Image pg. A71
	/ Kung Yit Yee	R. L. Polk Co., Publishers	Image pg. A71
1940	Ortega Leandro	R. L. Polk Co., Publishers	Image pg. A122
	Mc Daniels Mary Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Gage Amanda w id J D b	Polk-Husted Directory	
	Ladd John S h	Polk-Husted Directory	
	Ladd John S Jr b	Polk-Husted Directory	
	Orr Melvin H Nutter & Orr h	Polk-Husted Directory	
1906	Gage Amanda S Mrs r	A. KINGSBURY CO	
	Ladd John S r	A. KINGSBURY CO	
	Ladd Mary C Mrs r	A. KINGSBURY CO	
	ORR MELVIN H Nicol & Orr r	A. KINGSBURY CO	

346 S SUTTER ST

Year	Uses	Source
1906	Fairchild Fredk G meat market	A. KINGSBURY CO

FINDINGS

406 S SUTTER ST

Year	Uses	Source	
2017	MONIQUE MORENO	Cole Information Services	
	ALFREDO RAMIREZ	Cole Information Services	
2014	RICHARD HINOJOSA	Cole Information Services	
	ADELA RELLAMAS	Cole Information Services	
2009	MARISOL HERNANDEZ	Cole Information Services	
1999	MARISOL HERNANDEZ	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	2 Not Verified	R. L. Polk Co., Publishers	Image pg. A8
1996	Saldivar Cayeta	R. L. Polk Co., Publishers	Image pg. A15
1990	Cantu Domingo	R. L. Polk Co., Publishers	Image pg. A24
	Apartments	R. L. Polk Co., Publishers	Image pg. A24
	Vacant	R. L. Polk Co., Publishers	Image pg. A24
	Villanueza Juan	R. L. Polk Co., Publishers	Image pg. A24
	Elias Narceso	R. L. Polk Co., Publishers	Image pg. A24
	Miraval Mario Y	R. L. Polk Co., Publishers	Image pg. A24
	Galarza Margarito	R. L. Polk Co., Publishers	Image pg. A24
	Rocha Ruben	R. L. Polk Co., Publishers	Image pg. A24
	Salinas Pedro	R. L. Polk Co., Publishers	Image pg. A24
1975	Figueroa David	R.L. Polk CO.	Image pg. A63
1940	A Garvey P B	R. L. Polk Co., Publishers	Image pg. A122
1911	Axtell J A carmn C C T Co r	Polk-Husted Directory	
	Blain Mrs Addie b	Polk-Husted Directory	
	Camou Jean P bkpr h	Polk-Husted Directory	
	Salaun A L blksmth Holt Mnfg Co r	Polk-Husted Directory	
1906	Egan Frances Miss opr S T & T Co r	A. KINGSBURY CO	
	Camou Jean P r	A. KINGSBURY CO	
	Egan Mary Mrs r	A. KINGSBURY CO	

413 S SUTTER ST

Year	Uses	Source
1906	Overhiser Stephen B mgr Gatew ay Vehicle Co r	A. KINGSBURY CO

FINDINGS

415 S SUTTER ST

Year	Uses	Source	
2014	CLAUDIO ABARCA	Cole Information Services	
2009	CLAUDIO ABARCA	Cole Information Services	
2004	CLEMENTE CALLEJAS	Cole Information Services	
1999	CLAUDIO ABARCA	Cole Information Services	
1990	Yep Boelog	R. L. Polk Co., Publishers	Image pg. A24
1975	Alexander Porter	R.L. Polk CO.	Image pg. A63
1970	Lue A Sing	R. L. Polk Co., Publishers	Image pg. A71
1940	Snider G W	R. L. Polk Co., Publishers	Image pg. A122
1911	Liesy Margaret w id John b	Polk-Husted Directory	
	Kick Jefferson D foremn City St Dept h	Polk-Husted Directory	

420 S SUTTER ST

Year	Uses	Source	
1940	Haurigan Richd	R. L. Polk Co., Publishers	Image pg. A122
	Burge R L	R. L. Polk Co., Publishers	Image pg. A122

421 S SUTTER ST

Year	Uses	Source	
2014	JAVIER ARAUJO	Cole Information Services	
2009	JAVIER ARAUJO	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	JAVIER ARAUJO	Cole Information Services	
1996	Chuk Pum	R. L. Polk Co., Publishers	Image pg. A15
1994	CHUK, PUM	Cole Information Services	
1990	Castro Jas	R. L. Polk Co., Publishers	Image pg. A24
1975	Mar Jack	R.L. Polk CO.	Image pg. A63
1970	Mar Jack	R. L. Polk Co., Publishers	Image pg. A71
1940	Stagniaro David	R. L. Polk Co., Publishers	Image pg. A122
1911	Celayeta Saturino The Royal h	Polk-Husted Directory	
1906	Carter Geo H emp Stockton Impt Co r	A. KINGSBURY CO	

FINDINGS

422 S SUTTER ST

Year	Uses	Source	
2017	CHICK YIP	Cole Information Services	
2014	CHICK YIP	Cole Information Services	
2009	GAN YIP	Cole Information Services	
2004	GAN YIP	Cole Information Services	
1999	GAN YIP	Cole Information Services	
	Yip Gan C	R. L. Polk Co., Publishers	Image pg. A8
1990	Yip Gan Chick	R. L. Polk Co., Publishers	Image pg. A24
1975	Yip Gan Chick	R.L. Polk CO.	Image pg. A63
1970	Yip Can Chick	R. L. Polk Co., Publishers	Image pg. A71
1940	Mc Taggert C L Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Mc Taggart Royal carp h	Polk-Husted Directory	
	Mc Taggart Garrett R b	Polk-Husted Directory	
	Benton Elizabeth w id T N b	Polk-Husted Directory	
1906	Mc Taggart Royal miner r	A. KINGSBURY CO	
	Benton Elizabeth Mrs r	A. KINGSBURY CO	

423 S SUTTER ST

Year	Uses	Source	
2017	JONAS ROQUE	Cole Information Services	
2014	JONAS ROQUE	Cole Information Services	
2009	ISABEL DOMINGUEZ	Cole Information Services	
2004	ISABEL DOMINGUEZ	Cole Information Services	
1999	ISABEL DOMINGUEZ	Cole Information Services	
1994	MADRIAGA, BEN	Cole Information Services	
1990	Madriaga Ben	R. L. Polk Co., Publishers	Image pg. A24
1975	Vacant	R.L. Polk CO.	Image pg. A63
1970	Yip Bo Loy	R. L. Polk Co., Publishers	Image pg. A71

424 S SUTTER ST

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

Year	Uses	Source	
1999	Not Verified	R. L. Polk Co., Publishers	Image pg. A8
1996	Guiterrez Carlos	R. L. Polk Co., Publishers	Image pg. A15
1990	Selga Alipio	R. L. Polk Co., Publishers	Image pg. A24
	aGutierrez 0 L	R. L. Polk Co., Publishers	Image pg. A24
1975	Yip Lee Mah	R.L. Polk CO.	Image pg. A63
1970	Yip Lee Mali	R. L. Polk Co., Publishers	Image pg. A71
1940	Reyner Cath Mrs	R. L. Polk Co., Publishers	Image pg. A122
	Crabb F J	R. L. Polk Co., Publishers	Image pg. A122

425 S SUTTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	EMMANUEL RUIZ	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	EMMANUEL RUIZ	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	Monroy Eric P Sr	R. L. Polk Co., Publishers	Image pg. A8
1990	Ng Sze Yau	R. L. Polk Co., Publishers	Image pg. A24
1975	Vacant	R.L. Polk CO.	Image pg. A63
1970	Rathbun Pauline F Mrs	R. L. Polk Co., Publishers	Image pg. A71

426 S SUTTER ST

Year	Uses	Source	
2017	DAYNA MALLORY	Cole Information Services	
2009	FERNANDO GUSMAN	Cole Information Services	
1999	FERNANDO GUSMAN	Cole Information Services	
	Sandoval Ruth	R. L. Polk Co., Publishers	Image pg. A8
1990	Hernandez Maryann	R. L. Polk Co., Publishers	Image pg. A24
1975	Domingo Ed	R.L. Polk CO.	Image pg. A63
1970	No Return	R. L. Polk Co., Publishers	Image pg. A71

427 S SUTTER ST

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	FRANK DALAO	Cole Information Services	
1999	Dalao Frank A	R. L. Polk Co., Publishers	Image pg. A8
1996	Dalao Frank A	R. L. Polk Co., Publishers	Image pg. A15
1994	DALAO, FRANK A	Cole Information Services	
1990	Dalao Frank	R. L. Polk Co., Publishers	Image pg. A24
1975	Estes Joseph	R.L. Polk CO.	Image pg. A63
1970	Gn Goon	R. L. Polk Co., Publishers	Image pg. A71

428 S SUTTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	JUAN SANDOVAL	Cole Information Services	
2004	JUAN SANDOVAL	Cole Information Services	
1999	Palacios Art	R. L. Polk Co., Publishers	Image pg. A8
1990	Wong Yuk Lin Mrs	R. L. Polk Co., Publishers	Image pg. A24
1975	Wong Chew Hep	R.L. Polk CO.	Image pg. A63
1970	Wong Chew Hep	R. L. Polk Co., Publishers	Image pg. A71
1940	a Comaskey Eliz Mrs	R. L. Polk Co., Publishers	Image pg. A122
	b Meyers Jules	R. L. Polk Co., Publishers	Image pg. A122
1911	Thiel Walter hlpr Holt Mnfg Co r	Polk-Husted Directory	

429 S SUTTER ST

Year	Uses	Source	
2017	ALFREDO HERNANDEZ	Cole Information Services	
2014	ALFREDO HERNANDEZ	Cole Information Services	
2009	JOSE NAVA	Cole Information Services	
2004	KHAMDY SOURIYARANGSY	Cole Information Services	
	ENETERIO LOBANO	Cole Information Services	
1999	JOSE NAVA	Cole Information Services	
	Cordaway Christina	R. L. Polk Co., Publishers	Image pg. A8
1990	De Leon Chas	R. L. Polk Co., Publishers	Image pg. A24
1975	Martin Tony	R.L. Polk CO.	Image pg. A63
1970	Yberra Maxine G Mrs	R. L. Polk Co., Publishers	Image pg. A71

FINDINGS

Year	Uses	Source	
1911	Buhner Ernest uphlstr Mrs M Deegan h	Polk-Husted Directory	
	Stoetzer Edw driver b	Polk-Husted Directory	
1906	Marshall John miner r	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Wyman Chas H atty	A. KINGSBURY CO	

430 S SUTTER ST

Year	Uses	Source	
2014	JESUS JIMENEZ	Cole Information Services	
2009	CHRISTINE SANDOVAL	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	Sandaval Christina	R. L. Polk Co., Publishers	Image pg. A8
	Not Verified	R. L. Polk Co., Publishers	Image pg. A8
1990	Oakes Ruthan	R. L. Polk Co., Publishers	Image pg. A24
1975	Dumlao Filamino	R.L. Polk CO.	Image pg. A63
1970	Wong Wyman	R. L. Polk Co., Publishers	Image pg. A71
1940	Mowl M C Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Mc Auley Edw J clk Levy & Bro r	Polk-Husted Directory	
	Mc Cauley Edw clk r	Polk-Husted Directory	
	Mowl Milan A janitor Pub Library h	Polk-Husted Directory	
	Delaney Geo clk r	Polk-Husted Directory	
1906	Mowl Milan A atdt State Hospital r	A. KINGSBURY CO	

431 S SUTTER ST

Year	Uses	Source	
2017	KORINA DELMONT	Cole Information Services	
2014	MARIA QUEZADA	Cole Information Services	
2009	FILIBERTO DOMINGUEZ	Cole Information Services	
2004	SRONN SREIY	Cole Information Services	
1999	FILIBERTO DOMINGUEZ	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	Lim Kim	R. L. Polk Co., Publishers	Image pg. A8
1994	SOEUN, CCHEM	Cole Information Services	
1990	Vang Sa	R. L. Polk Co., Publishers	Image pg. A24

Year	Uses	Source	
1975	ABoardwell James	R.L. Polk CO.	Image pg. A63
1970	Brown Olivia	R. L. Polk Co., Publishers	Image pg. A71
1940	Kane Minnie Mrs	R. L. Polk Co., Publishers	Image pg. A122

432 S SUTTER ST

Year	Uses	Source	
1940	Tinnin W	R. L. Polk Co., Publishers	Image pg. A122
1911	Tuttle Frank painter h	Polk-Husted Directory	

435 S SUTTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	NANCY LOUR	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
1996	In Lalina	R. L. Polk Co., Publishers	Image pg. A15
1990	Her Leng	R. L. Polk Co., Publishers	Image pg. A24
1975	Ivory Louise Mrs	R.L. Polk CO.	Image pg. A63
1970	Vacant 138 Cantele Louise L Mrs	R. L. Polk Co., Publishers	Image pg. A71
1940	La Barre Alf	R. L. Polk Co., Publishers	Image pg. A122

438 S SUTTER ST

Year	Uses	Source	
2017	JESUS SAVES MINISTRIES INC	Cole Information Services	
2014	JESUS SAVES MINISTRIES INC	Cole Information Services	
2009	JESUS SAVES MINISTRIES INC	Cole Information Services	
2004	IRENE SANDOVAL	Cole Information Services	
	JESUS SSAVES MINISTRIES INC	Cole Information Services	
1999	JESUS SAVES MINISTRIES INCORPORATED	Cole Information Services	
	OCCUPANT UNKNOWN	Cole Information Services	
	JESUS SAVES MINISTRIES	R. L. Polk Co., Publishers	Image pg. A8
	Sandoval Eijio F 3	R. L. Polk Co., Publishers	Image pg. A8
	Sandoval Irene S A Ramos Hope T	R. L. Polk Co., Publishers	Image pg. A8
1996	JESUS SAVES MINISTRIES	R. L. Polk Co., Publishers	Image pg. A15

Year	Uses	Source	
1994	JESUS SAVES MINISTRIES	Cole Information Services	
1990	Jesus Sav Ministries	R. L. Polk Co., Publishers	Image pg. A24
1975	Cantele Louise L Mrs	R.L. Polk CO.	Image pg. A63

440 S SUTTER ST

Year	Uses	Source	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A24
1975	Stevens Printing Service	R.L. Polk CO.	Image pg. A63
1970	Vacant	R. L. Polk Co., Publishers	Image pg. A71
1940	ACantele T M saw filer	R. L. Polk Co., Publishers	Image pg. A122

442 S SUTTER ST

Year	Uses	Source	
2009	WARREN WONG	Cole Information Services	
2004	LISA SANDOVAL	Cole Information Services	
1999	WARREN WONG	Cole Information Services	
1994	BELLASETIN, JORGE	Cole Information Services	
1990	Vacant	R. L. Polk Co., Publishers	Image pg. A24
1975	Balbino Madriag	R.L. Polk CO.	Image pg. A63
1970	Me Quiston Harry G	R. L. Polk Co., Publishers	Image pg. A71

443 S SUTTER ST

Year	Uses	Source
1906	Adams Meda Miss r	A. KINGSBURY CO
	Adams May Miss r	A. KINGSBURY CO
	Warren Jos W clk A N Adams r	A. KINGSBURY CO

444 S SUTTER ST

Year	Uses	Source	
1940	Cantele T M	R. L. Polk Co., Publishers	Image pg. A122
	Reyner Cath Mrs	R. L. Polk Co., Publishers	Image pg. A122

503 S SUTTER ST

Year	Uses	Source	
1940	Chavez Alice	R. L. Polk Co., Publishers	Image pg. A122
	Trujillo Edw	R. L. Polk Co., Publishers	Image pg. A122

FINDINGS

Year	Uses	Source	
1911	Stephen Archibald R mach Samson I Wks h	Polk-Husted Directory	
1906	Vachon V r	A. KINGSBURY CO	
	Vachon Lew is W mach H & H Mfg Co r	A. KINGSBURY CO	
	Vachon Geo A emp H & H Mfg Co r	A. KINGSBURY CO	
	Day Ellen Mrs r	A. KINGSBURY CO	
	r	A. KINGSBURY CO	
	Dardis Thos L veterinary	A. KINGSBURY CO	
	Dardis Andrew D r	A. KINGSBURY CO	
	Bellinger Mary Mrs r	A. KINGSBURY CO	

504 S SUTTER ST

Year	Uses	Source	
1940	a Ferolio Margt Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Young Anna M w id J K h	Polk-Husted Directory	
	Stodeny Jos H eng r	Polk-Husted Directory	
	Hess Roy F plumber Br andt Bros b	Polk-Husted Directory	
	Cottle Chester E plumber Brandt Bros b	Polk-Husted Directory	
1906	Moon Minnie B Miss r	A. KINGSBURY CO	
	Moon Floyd B clk	A. KINGSBURY CO	
	Moon Alonzo L r	A. KINGSBURY CO	
	Moon Harold M emp Lew is & Johnson r	A. KINGSBURY CO	

505 S SUTTER ST

Year	Uses	Source	
1940	Vacant	R. L. Polk Co., Publishers	Image pg. A122
1911	Tardis Thos L vet surg	Polk-Husted Directory	
	Dardis Andrew D medicine mnfr	Polk-Husted Directory	
1906	Dardis Thos L veterinary	A. KINGSBURY CO	

508 S SUTTER ST

Year	Uses	Source	
1940	Blair C B	R. L. Polk Co., Publishers	Image pg. A122

FINDINGS

510 S SUTTER ST

Year	Uses	Source	
2017	HONG NGON	Cole Information Services	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	MEI HUANG	Cole Information Services	
2004	MEI HUANG	Cole Information Services	
1999	MEI HUANG	Cole Information Services	
	Huang Mei	R. L. Polk Co., Publishers	Image pg. A8
1990	No Return	R. L. Polk Co., Publishers	Image pg. A24
1975	Fong Gew Ngoy	R.L. Polk CO.	Image pg. A63
1970	Fong Gew Ngoy	R. L. Polk Co., Publishers	Image pg. A71
1911	IRVINE JAS H Pacific Transfer Co h	Polk-Husted Directory	
	Irvine John W salsn Filers Music House b	Polk-Husted Directory	
1906	Young Anna M Mrs r	A. KINGSBURY CO	
	Young Ethel M Miss milliner r	A. KINGSBURY CO	
	Young Bertram K clk A T & S F r	A. KINGSBURY CO	

515 S SUTTER ST

Year	Uses	Source	
1940	Ecker J F pntg contr	R. L. Polk Co., Publishers	Image pg. A122

518 S SUTTER ST

Year	Uses	Source	
2009	COLETTE SCOTT	Cole Information Services	
2004	COLETTE SCOTT	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	COLETTE SCOTT	Cole Information Services	
	Not Verified	R. L. Polk Co., Publishers	Image pg. A8
1990	Chavez C	R. L. Polk Co., Publishers	Image pg. A24
1975	Vacant	R.L. Polk CO.	Image pg. A63
1970	No Return	R. L. Polk Co., Publishers	Image pg. A71
1940	Daisley Geo	R. L. Polk Co., Publishers	Image pg. A122
1911	Ellis Alonzo H framemkr Totten & Brandt h	Polk-Husted Directory	
1906	Wilhite Marion F emp El Dorado Brew Co r	A. KINGSBURY CO	

FINDINGS

519 S SUTTER ST

Year	Uses	Source	
1940	Cezar Raymond	R. L. Polk Co., Publishers	Image pg. A122
1911	Palermo Angelo porter Arbois & Dalesandro h	Polk-Husted Directory	
	Nocito Antonio h	Polk-Husted Directory	
1906	Mc Donald Mary Mrs r	A. KINGSBURY CO	
	Johnson Fredk H dep County Clerk r	A. KINGSBURY CO	

521 S SUTTER ST

Year	Uses	Source	
2017	RICHARD CORPUS	Cole Information Services	
2014	RICHARD CORPUS	Cole Information Services	
2009	YUE WU	Cole Information Services	
	LEO LUI	Cole Information Services	
	SHU CHEN	Cole Information Services	
	MAO YU	Cole Information Services	
2004	MAN LUI	Cole Information Services	
1999	SHU CHEN	Cole Information Services	
	MAO YU	Cole Information Services	
	LEO LUI	Cole Information Services	
	YUE WU	Cole Information Services	
1994	GA, YAO	Cole Information Services	
1990	Gao Quan	R. L. Polk Co., Publishers	Image pg. A24
	Wong Kin Bo	R. L. Polk Co., Publishers	Image pg. A24
	Chin Bing Chou	R. L. Polk Co., Publishers	Image pg. A24
	Wong Beck Yuk	R. L. Polk Co., Publishers	Image pg. A24
	Apartments	R. L. Polk Co., Publishers	Image pg. A24
1975	Maynard Linda	R.L. Polk CO.	Image pg. A63
	Oliver Flossie L	R.L. Polk CO.	Image pg. A63
	Lyons James	R.L. Polk CO.	Image pg. A63
	Thomas Wallace	R.L. Polk CO.	Image pg. A63
	Apartments	R.L. Polk CO.	Image pg. A63
1970	King Isaac	R. L. Polk Co., Publishers	Image pg. A71

FINDINGS

Year	Uses	Source	
1970	Chalmers Precious B Mrs	R. L. Polk Co., Publishers	Image pg. A71
	Brown Doris	R. L. Polk Co., Publishers	Image pg. A71
	Apartments	R. L. Polk Co., Publishers	Image pg. A71
	Bowen Clifford	R. L. Polk Co., Publishers	Image pg. A71

522 S SUTTER ST

Year	Uses	Source	
2014	OCCUPANT UNKNOWN	Cole Information Services	
2009	OCCUPANT UNKNOWN	Cole Information Services	
2004	OCCUPANT UNKNOWN	Cole Information Services	
1999	OCCUPANT UNKNOWN	Cole Information Services	
	Montiel Miranda	R. L. Polk Co., Publishers	Image pg. A8
1994	ZAVALA, GUADALU M	Cole Information Services	
1990	Molina Mary	R. L. Polk Co., Publishers	Image pg. A24
1975	Tollel Clark	R.L. Polk CO.	Image pg. A63
1970	Me Cartv Arth L	R. L. Polk Co., Publishers	Image pg. A71
1940	Mc Carty A L	R. L. Polk Co., Publishers	Image pg. A122
1911	Wardle Elmer E glazier W P Fuller & Co h	Polk-Husted Directory	
1906	Loveridge John S bartndr Mc Collum & Lyon r	A. KINGSBURY CO	
	Zignego Antonio Williams & Zignego r	A. KINGSBURY CO	
	Zignego Emma Miss r	A. KINGSBURY CO	
	Zignego Petra Mrs r	A. KINGSBURY CO	

523 S SUTTER ST

Year	Uses	Source	
1940	Fuertes Narciso	R. L. Polk Co., Publishers	Image pg. A122
1911	Brumund Henry G carp h	Polk-Husted Directory	
1906	FLOYD EDW S W H Brown & Co r	A. KINGSBURY CO	
	Stuart Lewis W emp street dept r	A. KINGSBURY CO	

524 S SUTTER ST

Year	Uses	Source
2017	JOSEPHINE MARTINEZ	Cole Information Services
2014	JOSEPHINE MARTINEZ	Cole Information Services

FINDINGS

Year	Uses	Source	
2009	JOSEPHINE MARTINEZ	Cole Information Services	
2004	JOSEPHINE MARTINEZ	Cole Information Services	
1999	J MARTINEZ	Cole Information Services	
1990	Martinez Mercedes Mrs	R. L. Polk Co., Publishers	Image pg. A24
1975	Martinez Mercedes Mrs	R.L. Polk CO.	Image pg. A63
1970	Martinez Mercedes Mrs	R. L. Polk Co., Publishers	Image pg. A71

525 S SUTTER ST

Year	Uses	Source	
1940	Pablo P	R. L. Polk Co., Publishers	Image pg. A122

527 S SUTTER ST

Year	Uses	Source	
2017	DAISY GOLDSBERRY	Cole Information Services	
	TEOFILO YOSORES	Cole Information Services	
2014	TEOFILO YOSORES	Cole Information Services	
2009	WEI WU	Cole Information Services	
2004	QUAN WEI	Cole Information Services	
1999	WEI WU	Cole Information Services	
	Yu Qiu J	R. L. Polk Co., Publishers	Image pg. A8
	W u Fu	R. L. Polk Co., Publishers	Image pg. A8
1996	Situ Jian	R. L. Polk Co., Publishers	Image pg. A15
1990	Xu Zhi	R. L. Polk Co., Publishers	Image pg. A24
	Apartments	R. L. Polk Co., Publishers	Image pg. A24
	Lao Kei Chong	R. L. Polk Co., Publishers	Image pg. A24
	No Return	R. L. Polk Co., Publishers	Image pg. A24
	Lee Joe	R. L. Polk Co., Publishers	Image pg. A24
1975	Apartments	R.L. Polk CO.	Image pg. A63
	August Mercy Mrs	R.L. Polk CO.	Image pg. A63
	Monk Thos G	R.L. Polk CO.	Image pg. A63
	Campos Mario	R.L. Polk CO.	Image pg. A63
	Guerro Mary	R.L. Polk CO.	Image pg. A63
1970	Johnson Helen	R. L. Polk Co., Publishers	Image pg. A71
	Apartments	R. L. Polk Co., Publishers	Image pg. A71

FINDINGS

Year	Uses	Source	
1970	August Mercy	R. L. Polk Co., Publishers	Image pg. A71
	Monk Thos G	R. L. Polk Co., Publishers	Image pg. A71
	Cabarloc Ruth	R. L. Polk Co., Publishers	Image pg. A71
1940	Hook Chan Mrs	R. L. Polk Co., Publishers	Image pg. A122
1911	Smith Chas H linemn W S Gas & Elec Co h	Polk-Husted Directory	
	Gibbons Edw E brtndr Philip Taglio b	Polk-Husted Directory	
1906	Smith Chas H emp S G & E Co r	A. KINGSBURY CO	
	Finkbohner Anna Mrs r	A. KINGSBURY CO	

528 S SUTTER ST

Year	Uses	Source	
2017	DAVID JUAREZ	Cole Information Services	
	VICTOR LAWRIE	Cole Information Services	
2014	VICTOR LAWRIE	Cole Information Services	
2009	VICTOR LAWRIE	Cole Information Services	
1999	VICTOR LAWRIE	Cole Information Services	
	Not Verified 2 Hses	R. L. Polk Co., Publishers	Image pg. A8
1990	Martinez Josephine Mrs	R. L. Polk Co., Publishers	Image pg. A24
1975	Martinez Josephine Mrs	R.L. Polk CO.	Image pg. A63
1970	Martinez Josephine Mrs	R. L. Polk Co., Publishers	Image pg. A71
1940	Bloom Fred	R. L. Polk Co., Publishers	Image pg. A122
1911	Goode Jas F lab Stkn I Wks h	Polk-Husted Directory	
1906	Goode James F cook r	A. KINGSBURY CO	
	Mc Cutchan Wm A emp Stockton Iron Works r	A. KINGSBURY CO	

530 S SUTTER ST

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
	ARMANDO VELASQUEZ	Cole Information Services
1999	OCCUPANT UNKNOWN	Cole Information Services
	ARMANDO VELASQUEZ	Cole Information Services
1994	TOY, WING K	Cole Information Services

FINDINGS

Year	Uses	Source	
1990	Woey Toy	R. L. Polk Co., Publishers	Image pg. A24
	Reyes Martha	R. L. Polk Co., Publishers	Image pg. A24
1975	Chan C Y	R.L. Polk CO.	Image pg. A63
	Brow n John	R.L. Polk CO.	Image pg. A63
1970	/2 Chan C X	R. L. Polk Co., Publishers	Image pg. A71
	No Return	R. L. Polk Co., Publishers	Image pg. A71
1940	Sgheiza Alf	R. L. Polk Co., Publishers	Image pg. A122
1906	Drascovich Nicholas butcher r	A. KINGSBURY CO	

541 S SUTTER ST

Year	Uses	Source	
2014	VENCENTE ZAVALA	Cole Information Services	
	GLORIA VASQUEZ	Cole Information Services	
	JESSICA SEVERNS	Cole Information Services	
2009	GLORIA VASQUEZ	Cole Information Services	
1999	GLORIA VASQUEZ	Cole Information Services	
	Gonzalez Encarnacion	R. L. Polk Co., Publishers	Image pg. A8
	Gonzalez C	R. L. Polk Co., Publishers	Image pg. A8
1994	PRADO, JOSE	Cole Information Services	
1990	dIgnacio Raul	R. L. Polk Co., Publishers	Image pg. A24
	cSoto Josefina	R. L. Polk Co., Publishers	Image pg. A24
	bDelva Frances	R. L. Polk Co., Publishers	Image pg. A24
	aSanchez Rafael	R. L. Polk Co., Publishers	Image pg. A24
	Apartments	R. L. Polk Co., Publishers	Image pg. A24
1975	aPinkard Montel	R.L. Polk CO.	Image pg. A63
	bRodriguez J	R.L. Polk CO.	Image pg. A63
	cSmith Roosevelt	R.L. Polk CO.	Image pg. A63
	dHarris Sam	R.L. Polk CO.	Image pg. A63
1970	a Vacant	R. L. Polk Co., Publishers	Image pg. A71
	b Sandoval Joe	R. L. Polk Co., Publishers	Image pg. A71
	c Williams Loyd	R. L. Polk Co., Publishers	Image pg. A71
	d Ford Leah Mrs	R. L. Polk Co., Publishers	Image pg. A71
1940	d Bahw ell Hadon	R. L. Polk Co., Publishers	Image pg. A122

FINDINGS

Year	Uses	Source	
1940	c Peterson Signa Mrs	R. L. Polk Co., Publishers	Image pg. A122
	b Hook W H	R. L. Polk Co., Publishers	Image pg. A122
	a Rienhart A W	R. L. Polk Co., Publishers	Image pg. A122
	Sutter Flats	R. L. Polk Co., Publishers	Image pg. A122
1911	Montovani John hlpr Rasmus Stolberg r	Polk-Husted Directory	
	Marmtovani Augustini janitor h	Polk-Husted Directory	

543 S SUTTER ST

Year	Uses	Source	
2017	ELADIO CALLEJAS	Cole Information Services	
	CARMEN MARTINEZ	Cole Information Services	
2004	EUFEMIO CALLEJAS	Cole Information Services	
	MONICA MARTINEZ	Cole Information Services	
	ANTONIO MENDEZ	Cole Information Services	
1999	Cruz Chham & Rosa	R. L. Polk Co., Publishers	Image pg. A8
1994	CHAVEZ, MARIA I	Cole Information Services	
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A24
	aCosta Reuben	R. L. Polk Co., Publishers	Image pg. A24
	bMartinez Felicitas	R. L. Polk Co., Publishers	Image pg. A24
	cGutierrez Julia	R. L. Polk Co., Publishers	Image pg. A24
	dPreciado Jose	R. L. Polk Co., Publishers	Image pg. A24
1975	a Collins Lucille Mrs	R.L. Polk CO.	Image pg. A63
	b Molina Julian S	R.L. Polk CO.	Image pg. A63
	cContreas Martina	R.L. Polk CO.	Image pg. A63
	dGaines Robt	R.L. Polk CO.	Image pg. A63
1970	a Collins Lucille Mrs	R. L. Polk Co., Publishers	Image pg. A71
	b Jefferson Tommie	R. L. Polk Co., Publishers	Image pg. A71
	c Vacant	R. L. Polk Co., Publishers	Image pg. A71
	d Law rence Willie	R. L. Polk Co., Publishers	Image pg. A71
1940	d Thomas P J	R. L. Polk Co., Publishers	Image pg. A122
	c Rossiter Nancy L	R. L. Polk Co., Publishers	Image pg. A122
	b Ercoli Guido	R. L. Polk Co., Publishers	Image pg. A122
	a Anderson Louis	R. L. Polk Co., Publishers	Image pg. A122

Year	Uses	Source	
1911	Burns n P lab Union Oil Co h	Polk-Husted Directory	

545 S SUTTER ST

Year	Uses	Source	
2014	DARRYL DENNIS	Cole Information Services	
2009	VICTOR RICARDEZ	Cole Information Services	
2004	PATRICIO VARGAS	Cole Information Services	
	SERGIO GARCIA	Cole Information Services	
	IVAN BARRO	Cole Information Services	
	MANUEL CHAVEZ	Cole Information Services	
1999	VICTOR RICARDEZ	Cole Information Services	
1996	Ojeda Hildeg	R. L. Polk Co., Publishers	Image pg. A15
1990	Apartments	R. L. Polk Co., Publishers	Image pg. A24
	aLuna Sylvia	R. L. Polk Co., Publishers	Image pg. A24
	bGutierrez Gloria	R. L. Polk Co., Publishers	Image pg. A24
	cChavez Paco	R. L. Polk Co., Publishers	Image pg. A24
1975	a Bess Doris	R.L. Polk CO.	Image pg. A63
	b Patterson David	R.L. Polk CO.	Image pg. A63
	c Thomas Johnie Mrs	R.L. Polk CO.	Image pg. A63
1970	a Best Doris	R. L. Polk Co., Publishers	Image pg. A71
	b Lee Marvin	R. L. Polk Co., Publishers	Image pg. A71
	c Williams Mattie M	R. L. Polk Co., Publishers	Image pg. A71
1940	a Leonardini Madeline	R. L. Polk Co., Publishers	Image pg. A122
	b Gianelli D W	R. L. Polk Co., Publishers	Image pg. A122
	Gianelli T M	R. L. Polk Co., Publishers	Image pg. A122
1911	Williams Jesse E cond S Fe Ry h	Polk-Husted Directory	

SAN JOAQUIN S

301 SAN JOAQUIN S

Year	Uses	Source
2003	Chen Lan Fu	SBC PACIFIC BELL
	Chan Vue Kuen	SBC PACIFIC BELL
	Chin Wai Fong	SBC PACIFIC BELL

FINDINGS

Year	Uses	Source	
2003	Hucom George	SBC PACIFIC BELL	
	Wong How ard W	SBC PACIFIC BELL	
	Liang Ruikuan	SBC PACIFIC BELL	
	Morales Tony	SBC PACIFIC BELL	
	Tan Chin Xixi	SBC PACIFIC BELL	
	Zhu Ban D	SBC PACIFIC BELL	
	Wu Fu	SBC PACIFIC BELL	
	Leto Julia	SBC PACIFIC BELL	
1960	Salvation Army Corps & Welfare Dept	R. L. Polk Co., Publishers	Image pg. A82
1955	Salvation Army	R. L. Polk Co.	Image pg. A96
1950	Salvation Army	R. L. Polk Co., Publishers	Image pg. A100
1946	a Salvation Army The	R. L. Polk Co., Publishers	Image pg. A108
1935	Salvation Army Corps	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Salvation Army Corps	R. L. Polk Co. of California, Publishers	Image pg. A133
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

302 SAN JOAQUIN S

Year	Uses	Source	
2003	NEW STOCKTON POULTRY MKT INC	SBC PACIFIC BELL	
1960	Stockton Poultry Mkt 4 AH	R. L. Polk Co., Publishers	Image pg. A82
1955	Stockton Poultry Mkt	R. L. Polk Co.	Image pg. A96
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A100
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A108
1935	Eckert C W auto repr	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	auto electn	R. L. Polk Co. of California, Publishers	Image pg. A133
	Stockw ell N L	R. L. Polk Co. of California, Publishers	Image pg. A133
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

303 SAN JOAQUIN S

Year	Uses	Source	
1930	Hammond R R	R. L. Polk Co. of California, Publishers	Image pg. A139

FINDINGS

306 SAN JOAQUIN S

Year	Uses	Source	
1930	Atherton W H law	R. L. Polk Co. of California, Publishers	Image pg. A139
	Mc Dermott B G law	R. L. Polk Co. of California, Publishers	Image pg. A139
	Mc Noble H R law yer	R. L. Polk Co. of California, Publishers	Image pg. A139
	Shaughnessy M P	R. L. Polk Co. of California, Publishers	Image pg. A139
	law yer	R. L. Polk Co. of California, Publishers	Image pg. A139
	U S Commissioner	R. L. Polk Co. of California, Publishers	Image pg. A139

308 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

309 SAN JOAQUIN S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Pinkerton James	R. L. Polk Co.	Image pg. A96
	Citadel Hotel 41 HO	R. L. Polk Co.	Image pg. A96
1950	A Citadel Hotel	R. L. Polk Co., Publishers	Image pg. A100
1946	Citadel Hotel	R. L. Polk Co., Publishers	Image pg. A108
	Schina Olga Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Salvation Army Hotel	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Reimel Carl	R. L. Polk Co. of California, Publishers	Image pg. A133
	Hotel	R. L. Polk Co. of California, Publishers	Image pg. A133
	Salvation Army	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Stew art R F	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Carroll Herbert	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Smith Mrs Belle	Polk-Husted Directory Co.	Image pg. A166

310 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

311 SAN JOAQUIN S

Year	Uses	Source	
1960	Street continued	R. L. Polk Co., Publishers	Image pg. A82

FINDINGS

Year	Uses	Source	
1960	Lucero James	R. L. Polk Co., Publishers	Image pg. A82
	Perez Ramon	R. L. Polk Co., Publishers	Image pg. A82
	Chandler Lee	R. L. Polk Co., Publishers	Image pg. A82
	Yip Bing	R. L. Polk Co., Publishers	Image pg. A82
	Davis Louis	R. L. Polk Co., Publishers	Image pg. A82
	I Green Joseph	R. L. Polk Co., Publishers	Image pg. A82
	Apartments	R. L. Polk Co., Publishers	Image pg. A82
1955	Yip Benny H	R. L. Polk Co.	Image pg. A96
	Norris Pau	R. L. Polk Co.	Image pg. A96
	Nakagaw a Kunso	R. L. Polk Co.	Image pg. A96
	Metcalf Margt HO	R. L. Polk Co.	Image pg. A96
	Alcala Chas	R. L. Polk Co.	Image pg. A96
1950	Voight J A	R. L. Polk Co., Publishers	Image pg. A100
	Scheffer Geo	R. L. Polk Co., Publishers	Image pg. A100
	Mc Gillivray Zetta	R. L. Polk Co., Publishers	Image pg. A100
	St Clair A W	R. L. Polk Co., Publishers	Image pg. A100
	Buckelege W 0 B	R. L. Polk Co., Publishers	Image pg. A100
	Dobbs Maisie Mrs	R. L. Polk Co., Publishers	Image pg. A100
1946	Law son H P	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Pacific Coast Aggregates Inc	R. L. Polk Co. of California, Publishers	Image pg. A139
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1921	Phillips D A	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Phillips D A	Polk-Husted Directory Co.	Image pg. A166

312 SAN JOAQUIN S

Year	Uses	Source	
1946	Galapia J A	R. L. Polk Co., Publishers	Image pg. A108

315 SAN JOAQUIN S

Year	Uses	Source	
1955	Il Sole w eekly new spaper	R. L. Polk Co.	Image pg. A96
1950	Sole w eekly	R. L. Polk Co., Publishers	Image pg. A100
	All Sole Inc publrs	R. L. Polk Co., Publishers	Image pg. A100

FINDINGS

Year	Uses	Source	
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A108
1935	Rex Hotel	R. L. Polk Co. of California, Publishers	Image pg. A128
	Lee Patsy	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Nevada Hotel	R. L. Polk Co. of California, Publishers	Image pg. A133
	Garciacelay Silvano	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Dexter House	Polk-Husted Directory Co., Publishers	Image pg. A156
	Ratto Mrs Katherine	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Dexter House	Polk-Husted Directory Co.	Image pg. A166
	Miller E C	Polk-Husted Directory Co.	Image pg. A166
	OConnor John	Polk-Husted Directory Co.	Image pg. A166

317 SAN JOAQUIN S

Year	Uses	Source	
1930	Erro Martin gio	R. L. Polk Co. of California, Publishers	Image pg. A133

319 SAN JOAQUIN S

Year	Uses	Source	
1960	Skylark Beauty Salon AH	R. L. Polk Co., Publishers	Image pg. A82
1935	Flavius Flavio S S agt	R. L. Polk Co. of California, Publishers	Image pg. A128
	Il Sole w eekly	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Sole Steamship	R. L. Polk Co. of California, Publishers	Image pg. A133
	Agency	R. L. Polk Co. of California, Publishers	Image pg. A133
	Il Sole w eekly new spaper	R. L. Polk Co. of California, Publishers	Image pg. A133

320 SAN JOAQUIN S

Year	Uses	Source	
1960	Commercial Refgr Serv	R. L. Polk Co., Publishers	Image pg. A82
1955	Commercial Refgr Serv	R. L. Polk Co.	Image pg. A96
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A100
1946	ALittle H C Burner Co	R. L. Polk Co., Publishers	Image pg. A108
	oil burners	R. L. Polk Co., Publishers	Image pg. A108

FINDINGS

321 SAN JOAQUIN S

Year	Uses	Source	
2003	WONG FAMILY BENEVOLENT ASSN	SBC PACIFIC BELL	
1960	Normans Upholstering	R. L. Polk Co., Publishers	Image pg. A82
1946	Il Sole Inc pubirs	R. L. Polk Co., Publishers	Image pg. A108
	Il Sole w eekly	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Y 2 Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
	Gianelli J A coffee	R. L. Polk Co. of California, Publishers	Image pg. A133

323 SAN JOAQUIN S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Withers J B cigars	R. L. Polk Co. of California, Publishers	Image pg. A133

324 SAN JOAQUIN S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Perez Mrs Rufina	R. L. Polk Co. of California, Publishers	Image pg. A153
	Viliamor Andrea	R. L. Polk Co. of California, Publishers	Image pg. A153
	Kaihe Wm rear	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Florita M S	Polk-Husted Directory Co., Publishers	Image pg. A156
	Vidrierras Mrs Ronfina	Polk-Husted Directory Co., Publishers	Image pg. A156
	rear	Polk-Husted Directory Co., Publishers	Image pg. A156
	Diaz R P	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Pugh R D	Polk-Husted Directory Co.	Image pg. A166
	Harney Jos rear	Polk-Husted Directory Co.	Image pg. A166

325 SAN JOAQUIN S

Year	Uses	Source	
1960	Fong Suey Lung herbs	R. L. Polk Co., Publishers	Image pg. A82
1955	Fong Suey Lung herbs	R. L. Polk Co.	Image pg. A96
1950	A Fong Suey Lung herbs	R. L. Polk Co., Publishers	Image pg. A100

FINDINGS

Year	Uses	Source	
1946	a Suey Lung Fong herbs	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	bakers	R. L. Polk Co. of California, Publishers	Image pg. A133
	Paul A & Paul Bros	R. L. Polk Co. of California, Publishers	Image pg. A133

326 SAN JOAQUIN S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1916	Aeillo J I rear	Polk-Husted Directory Co.	Image pg. A166

327 SAN JOAQUIN S

Year	Uses	Source	
1925	Packer M M	R. L. Polk Co. of California, Publishers	Image pg. A153

328 SAN JOAQUIN S

Year	Uses	Source	
1960	Hong Bevin F	R. L. Polk Co., Publishers	Image pg. A82
1946	Yen H G	R. L. Polk Co., Publishers	Image pg. A108
1935	Chin Geo	R. L. Polk Co. of California, Publishers	Image pg. A128
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Buenafe R B	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Vacant	Polk-Husted Directory Co.	Image pg. A166

329 SAN JOAQUIN S

Year	Uses	Source	
1960	De Luxe Bakery	R. L. Polk Co., Publishers	Image pg. A82
1955	Le Luxe Bky	R. L. Polk Co.	Image pg. A96
1950	Zaremba Paul baker	R. L. Polk Co., Publishers	Image pg. A100
1946	AZaremba Paul baker	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A128

330 SAN JOAQUIN S

Year	Uses	Source	
1960	Wong Fong Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Wong Fong Mrs 41 HO	R. L. Polk Co.	Image pg. A96

FINDINGS

Year	Uses	Source	
1950	Wong S C	R. L. Polk Co., Publishers	Image pg. A100
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A108
	Wong Sai Chung	R. L. Polk Co., Publishers	Image pg. A108
1935	Filipino House of	R. L. Polk Co. of California, Publishers	Image pg. A128
	Friendship	R. L. Polk Co. of California, Publishers	Image pg. A128
	Martinez Pedro	R. L. Polk Co. of California, Publishers	Image pg. A128
	4 Oriental	R. L. Polk Co. of California, Publishers	Image pg. A128
	Deseo J J Rev	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Bong L T Chinese herbs	R. L. Polk Co. of California, Publishers	Image pg. A133
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A153
	Markham Harold	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A156
	Caffey J B	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Mc Guirk Mrs Mary	Polk-Husted Directory Co.	Image pg. A166
	Whyte Chas	Polk-Husted Directory Co.	Image pg. A166

331 SAN JOAQUIN S

Year	Uses	Source	
1960	Pyramid Mkt gro	R. L. Polk Co., Publishers	Image pg. A82
1955	Pyramid Mkt gro	R. L. Polk Co.	Image pg. A96
1950	A Pyramid Mkt gro	R. L. Polk Co., Publishers	Image pg. A100
1946	Pyramid Gro	R. L. Polk Co., Publishers	Image pg. A108
1935	Pyramid Girocery	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	lHan K I gro	R. L. Polk Co. of California, Publishers	Image pg. A133

332 SAN JOAQUIN S

Year	Uses	Source	
2003	De Leon Cruz Felix	SBC PACIFIC BELL	
1960	Yip Joe	R. L. Polk Co., Publishers	Image pg. A82
1955	Vacant	R. L. Polk Co.	Image pg. A96
	Rigney Gladys Mrs	R. L. Polk Co.	Image pg. A96
	Dale Hotel	R. L. Polk Co.	Image pg. A96
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A100

FINDINGS

Year	Uses	Source	
1950	Hing Chew	R. L. Polk Co., Publishers	Image pg. A100
1935	Young San	R. L. Polk Co. of California, Publishers	Image pg. A128
	Young Luni	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Davis E R	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Davis Mrs E R	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Mills G W	Polk-Husted Directory Co.	Image pg. A166

333 SAN JOAQUIN S

Year	Uses	Source	
1930	Fredericks J W o	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Watson P A	R. L. Polk Co. of California, Publishers	Image pg. A153
	Watson Mrs Bessie	R. L. Polk Co. of California, Publishers	Image pg. A153
1916	Mead G F	Polk-Husted Directory Co.	Image pg. A166

334 SAN JOAQUIN S

Year	Uses	Source	
1960	Vancini Peter	R. L. Polk Co., Publishers	Image pg. A82
	Nelson Fred	R. L. Polk Co., Publishers	Image pg. A82
1955	Nelson Fred	R. L. Polk Co.	Image pg. A96
	Vancini Peter	R. L. Polk Co.	Image pg. A96
1950	Hing Chew herbs	R. L. Polk Co., Publishers	Image pg. A100
1946	Hing Chew	R. L. Polk Co., Publishers	Image pg. A108
1935	Predagne John	R. L. Polk Co. of California, Publishers	Image pg. A128
	Predagne Dominica	R. L. Polk Co. of California, Publishers	Image pg. A128
	:135 Pyrenees Hotel	R. L. Polk Co. of California, Publishers	Image pg. A128
	Chew Hin herbs	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	herbs	R. L. Polk Co. of California, Publishers	Image pg. A133
	Hing Chew Chinese	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Parsons Mrs E H	R. L. Polk Co. of California, Publishers	Image pg. A153
	Parsons C E	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Beaumont W C	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Davis A P	Polk-Husted Directory Co.	Image pg. A166

FINDINGS

335 SAN JOAQUIN S

Year	Uses	Source	
1960	Nixon H otel Lodgings	R. L. Polk Co., Publishers	Image pg. A82
	Peninger Louise G Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Nixon Hotel	R. L. Polk Co.	Image pg. A96
	Peninger Louise G Mrs	R. L. Polk Co.	Image pg. A96
1950	Airport Rooms	R. L. Polk Co., Publishers	Image pg. A100
	AOlson Louise Mrs	R. L. Polk Co., Publishers	Image pg. A100
1946	AAirport Rooms	R. L. Polk Co., Publishers	Image pg. A108
	Olson Louise Mrs	R. L. Polk Co., Publishers	Image pg. A108
1930	Brow n Jos	R. L. Polk Co. of California, Publishers	Image pg. A133
	Brow n Lillian Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
	furn rms	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Cole Mrs Frances	R. L. Polk Co. of California, Publishers	Image pg. A153
	Portola Rooms	R. L. Polk Co. of California, Publishers	Image pg. A153
1921	Portola Rooms	Polk-Husted Directory Co., Publishers	Image pg. A156
	Corn Al	Polk-Husted Directory Co., Publishers	Image pg. A156
	Hotel Astor	Polk-Husted Directory Co., Publishers	Image pg. A156
	Whitaker R C	Polk-Husted Directory Co., Publishers	Image pg. A156
	Kyle S H	Polk-Husted Directory Co., Publishers	Image pg. A156

337 SAN JOAQUIN S

Year	Uses	Source	
1960	Wong Yee herbs	R. L. Polk Co., Publishers	Image pg. A82
1955	Wong Yee herbs	R. L. Polk Co.	Image pg. A96
1950	A Wong Yee herbs	R. L. Polk Co., Publishers	Image pg. A100
1946	AWong Y herbs	R. L. Polk Co., Publishers	Image pg. A108
1935	SAN JOAQUIN SOUTH Contd	R. L. Polk Co. of California, Publishers	Image pg. A123
	Wong Y herbs	R. L. Polk Co. of California, Publishers	Image pg. A128
1930	Wong Y drtgs	R. L. Polk Co. of California, Publishers	Image pg. A133
1916	Lerner Saml	Polk-Husted Directory Co.	Image pg. A166

339 SAN JOAQUIN S

Year	Uses	Source	
1916	Vacant	Polk-Husted Directory Co.	Image pg. A166

343 SAN JOAQUIN S

Year	Uses	Source	
2003	Patel Shailesh K	SBC PACIFIC BELL	
	Patel Shailesh	SBC PACIFIC BELL	
1960	Madrid Joseph E	R. L. Polk Co., Publishers	Image pg. A82
	Basconia Hotel lodgings	R. L. Polk Co., Publishers	Image pg. A82
1955	Basconia Hotel	R. L. Polk Co.	Image pg. A96
1950	Basconia Hotel	R. L. Polk Co., Publishers	Image pg. A100
	Gainza Jessie Mrs	R. L. Polk Co., Publishers	Image pg. A100
1946	a Hotel Basque	R. L. Polk Co., Publishers	Image pg. A108
1935	Hotel Bosque	R. L. Polk Co. of California, Publishers	Image pg. A123
	Ileart John	R. L. Polk Co. of California, Publishers	Image pg. A123
	Mentaberry Peter	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Hotel Astor	R. L. Polk Co. of California, Publishers	Image pg. A133
	Lichi Rene Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Hotel Astor	R. L. Polk Co. of California, Publishers	Image pg. A146
	Williams E D	R. L. Polk Co. of California, Publishers	Image pg. A146
1916	Vacant	Polk-Husted Directory Co.	Image pg. A166

344 SAN JOAQUIN S

Year	Uses	Source	
1960	Salabar Frantk	R. L. Polk Co., Publishers	Image pg. A82
1955	SAN JOAQUIN SOUTH Contd	R. L. Polk Co.	Image pg. A90
	French Curtain Lndry	R. L. Polk Co.	Image pg. A96
	Salaber Frank 4	R. L. Polk Co.	Image pg. A96
1950	A Salober Frank Indy	R. L. Polk Co., Publishers	Image pg. A100
	Salober Frank	R. L. Polk Co., Publishers	Image pg. A100
1946	Gross C H tile contr	R. L. Polk Co., Publishers	Image pg. A108
1935	Davis 1 food prod	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vlacant	R. L. Polk Co. of California, Publishers	Image pg. A133

345 SAN JOAQUIN S

Year	Uses	Source	
2003	Chew Albert	SBC PACIFIC BELL	
1935	:34 Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123

Year	Uses	Source	
1935	Ideart & Mentabherry	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	billiards	R. L. Polk Co. of California, Publishers	Image pg. A133
	Garciacelay Silvano	R. L. Polk Co. of California, Publishers	Image pg. A133
1916	Gibson Mrs H B	Polk-Husted Directory Co.	Image pg. A166

346 SAN JOAQUIN S

Year	Uses	Source	
2003	Hernandez Macaria	SBC PACIFIC BELL	
	Almanza Jesus	SBC PACIFIC BELL	
	Flores Marciela	SBC PACIFIC BELL	
1960	Street continued	R. L. Polk Co., Publishers	Image pg. A82
	Morones Joanne	R. L. Polk Co., Publishers	Image pg. A82
	Picanco Alice C	R. L. Polk Co., Publishers	Image pg. A82
	Mendez Manuel	R. L. Polk Co., Publishers	Image pg. A82
	Doughty Norman C	R. L. Polk Co., Publishers	Image pg. A82
	Apartments	R. L. Polk Co., Publishers	Image pg. A82
1955	New comb Ollie	R. L. Polk Co.	Image pg. A90
	Hall C W	R. L. Polk Co.	Image pg. A90
	Jew art H P trucking	R. L. Polk Co.	Image pg. A90
1950	Telleria Gerardo	R. L. Polk Co., Publishers	Image pg. A100
	Ford J M	R. L. Polk Co., Publishers	Image pg. A100
	Chelli E J	R. L. Polk Co., Publishers	Image pg. A100
	Fitzgerald J W	R. L. Polk Co., Publishers	Image pg. A100
1946	Eguinoa Frances	R. L. Polk Co., Publishers	Image pg. A108
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Kyle S H	R. L. Polk Co. of California, Publishers	Image pg. A146
1916	Clegg Mrs Mary	Polk-Husted Directory Co.	Image pg. A166
	Tibbetts G R	Polk-Husted Directory Co.	Image pg. A166

347 SAN JOAQUIN S

Year	Uses	Source	
1960	Jessies Place tavern	R. L. Polk Co., Publishers	Image pg. A82
1955	Jessies Place tavern	R. L. Polk Co.	Image pg. A90
1916	Vacant	Polk-Husted Directory Co.	Image pg. A166

FINDINGS

348 SAN JOAQUIN S

Year	Uses	Source	
1960	Acme Cln dclo prsrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Z Sonora hintersects	R. L. Polk Co.	Image pg. A90
	Acme Clns	R. L. Polk Co.	Image pg. A90
1950	A Bernazzani A W cldo	R. L. Polk Co., Publishers	Image pg. A100
1946	ASalaber Frank cldo	R. L. Polk Co., Publishers	Image pg. A108
1935	Aniestoy Jas beer	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Serpa M R	R. L. Polk Co. of California, Publishers	Image pg. A146

352 SAN JOAQUIN S

Year	Uses	Source	
1935	X Webb J W w atch	R. L. Polk Co. of California, Publishers	Image pg. A128

401 SAN JOAQUIN S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133

402 SAN JOAQUIN S

Year	Uses	Source	
1960	Gastella Esther Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Rodriguez Rosario G Mrs	R. L. Polk Co.	Image pg. A90
1950	Callow ay John	R. L. Polk Co., Publishers	Image pg. A100
1946	George W H	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Glameyer H E A	R. L. Polk Co. of California, Publishers	Image pg. A133
	Stockton Transportation Co	R. L. Polk Co. of California, Publishers	Image pg. A139
	Calif Vegetable Union	R. L. Polk Co. of California, Publishers	Image pg. A139
	Gormsen E M corn mer	R. L. Polk Co. of California, Publishers	Image pg. A139
1925	Glameyer H E A	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Glameyer H E A	Polk-Husted Directory Co., Publishers	Image pg. A156

FINDINGS

Year	Uses	Source	
1916	Johnson Jos	Polk-Husted Directory Co.	Image pg. A166
	Glameyer H E A	Polk-Husted Directory Co.	Image pg. A166

403 SAN JOAQUIN S

Year	Uses	Source	
1960	Alustizas Cal Hotel Buffet restr	R. L. Polk Co., Publishers	Image pg. A82
	California Hotel	R. L. Polk Co., Publishers	Image pg. A82
1955	Alustizas Cal Hotel Buffett	R. L. Polk Co.	Image pg. A90
	Alustiza Fermin	R. L. Polk Co.	Image pg. A90
	California Hotel	R. L. Polk Co.	Image pg. A90
1950	AAlustiza Fermin	R. L. Polk Co., Publishers	Image pg. A100
	California Hotel	R. L. Polk Co., Publishers	Image pg. A100
1946	Alustiza Fermin	R. L. Polk Co., Publishers	Image pg. A108
	ACalifornia Hotel	R. L. Polk Co., Publishers	Image pg. A108
1935	:California Hotel	R. L. Polk Co. of California, Publishers	Image pg. A123
	Fermin Alustija to	R. L. Polk Co. of California, Publishers	Image pg. A123
	Gini Angelo barber	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	California Hotel	R. L. Polk Co. of California, Publishers	Image pg. A133
	Alustiza Fermin	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Fermin Alustiza	R. L. Polk Co. of California, Publishers	Image pg. A146
	California Hotel	R. L. Polk Co. of California, Publishers	Image pg. A146

404 SAN JOAQUIN S

Year	Uses	Source	
1960	Estabilo Mattai	R. L. Polk Co., Publishers	Image pg. A82
1955	Estabillo Matios	R. L. Polk Co.	Image pg. A90
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A100
1946	AMason Bernice	R. L. Polk Co., Publishers	Image pg. A108
1930	Miller Laura	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Adler Saml	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Davis Mrs R F	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Langford Chas	Polk-Husted Directory Co.	Image pg. A166

FINDINGS

405 SAN JOAQUIN S

Year	Uses	Source	
1930	barber	R. L. Polk Co. of California, Publishers	Image pg. A133
	Castruccia A J	R. L. Polk Co. of California, Publishers	Image pg. A133
	Coale H W jr dentist	R. L. Polk Co. of California, Publishers	Image pg. A139
1925	Curtis Jos	R. L. Polk Co. of California, Publishers	Image pg. A146

406 SAN JOAQUIN S

Year	Uses	Source	
1960	Padin Tommy	R. L. Polk Co., Publishers	Image pg. A82
1955	Adolfo Frances Mrs	R. L. Polk Co.	Image pg. A90
1950	WVong John	R. L. Polk Co., Publishers	Image pg. A100
1946	Satterfield Abner	R. L. Polk Co., Publishers	Image pg. A108
1930	Empire Navigation Co	R. L. Polk Co. of California, Publishers	Image pg. A139
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Hunsucker J P	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Hunsucker J P	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Weber Josephine	Polk-Husted Directory Co.	Image pg. A166

407 SAN JOAQUIN S

Year	Uses	Source	
1960	Cal Hotel Barber Shop	R. L. Polk Co., Publishers	Image pg. A82
1955	California Barber Shop	R. L. Polk Co.	Image pg. A90
1950	Morello V B barber	R. L. Polk Co., Publishers	Image pg. A100
1946	Morello V B barber	R. L. Polk Co., Publishers	Image pg. A108

408 SAN JOAQUIN S

Year	Uses	Source	
1960	Yep Benny	R. L. Polk Co., Publishers	Image pg. A82
1955	Yep Benny	R. L. Polk Co.	Image pg. A90
1950	Ruiz Luis	R. L. Polk Co., Publishers	Image pg. A100
1946	Diddy Leslie	R. L. Polk Co., Publishers	Image pg. A108
1935	Tesch Otto	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Smith Mrs Flossie	R. L. Polk Co. of California, Publishers	Image pg. A146

FINDINGS

Year	Uses	Source	
1921	Salzmann Emil	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Mills T M	Polk-Husted Directory Co.	Image pg. A166

409 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

410 SAN JOAQUIN S

Year	Uses	Source	
1960	Poff Geo	R. L. Polk Co., Publishers	Image pg. A82
	Garcia Francisco G	R. L. Polk Co., Publishers	Image pg. A82
1955	Lopez Alberta Mrs	R. L. Polk Co.	Image pg. A90
1950	AJohnson G W	R. L. Polk Co., Publishers	Image pg. A100
	A Ball Edw	R. L. Polk Co., Publishers	Image pg. A100
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A108
	t Ball U Edw	R. L. Polk Co., Publishers	Image pg. A108
1935	Ball	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Italian Investment Corp	R. L. Polk Co. of California, Publishers	Image pg. A139
	Ball Edw	R. L. Polk Co. of California, Publishers	Image pg. A133
	Anderson Arth	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A146
	Ball Edw	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Ball Edw	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Ball Edw	Polk-Husted Directory Co.	Image pg. A166
	Seiffert E J	Polk-Husted Directory Co.	Image pg. A166

411 SAN JOAQUIN S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123

412 SAN JOAQUIN S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Pera Faye	R. L. Polk Co.	Image pg. A90
1950	Castro Pedro	R. L. Polk Co., Publishers	Image pg. A100

Year	Uses	Source	
1946	Castro Peter	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Hammond Mrs Esther	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Webster Mrs Anna	Polk-Husted Directory Co.	Image pg. A166

414 SAN JOAQUIN S

Year	Uses	Source	
1960	No return	R. L. Polk Co., Publishers	Image pg. A82
1955	Wong Larry	R. L. Polk Co.	Image pg. A90
1950	A Ramalho Laura E	R. L. Polk Co., Publishers	Image pg. A100
1946	Ramallk Laura E	R. L. Polk Co., Publishers	Image pg. A108
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Guidi Mrs Palmero	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Russell Claude	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Paul G W	Polk-Husted Directory Co.	Image pg. A166

416 SAN JOAQUIN S

Year	Uses	Source	
1960	Zeppa Frank	R. L. Polk Co., Publishers	Image pg. A82
	k Morales Salvador	R. L. Polk Co., Publishers	Image pg. A82
1955	Murray May Mrs	R. L. Polk Co.	Image pg. A90
1950	Stew art J W Mrs	R. L. Polk Co., Publishers	Image pg. A100
	A Murray May Mrs	R. L. Polk Co., Publishers	Image pg. A100
1946	a Murray May Mrs	R. L. Polk Co., Publishers	Image pg. A108
	Kerley J F	R. L. Polk Co., Publishers	Image pg. A108
1930	Murray L M	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Murray L M	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Murray L M	Polk-Husted Directory Co., Publishers	Image pg. A156
	Dabb Jas	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Duff W V	Polk-Husted Directory Co.	Image pg. A166
	Murray L M	Polk-Husted Directory Co.	Image pg. A166
	Alexander F I	Polk-Husted Directory Co.	Image pg. A166

FINDINGS

420 SAN JOAQUIN S

Year	Uses	Source	
2003	Mosley Raja	SBC PACIFIC BELL	
	Mosley Raja	SBC PACIFIC BELL	
1960	Sanzberro Josto	R. L. Polk Co., Publishers	Image pg. A82
1955	Sanzberro Justo	R. L. Polk Co.	Image pg. A90
1950	A Sanzberro Justo	R. L. Polk Co., Publishers	Image pg. A100
1946	Sanzberro Justo S	R. L. Polk Co., Publishers	Image pg. A108
1935	Sanzberro Justo to	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Sanzberro Justo o	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Yroz Domingo	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Yroz Domingo	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Edwards J W	Polk-Husted Directory Co.	Image pg. A166

423 SAN JOAQUIN S

Year	Uses	Source	
1960	Gleason Edna E Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Gleason Edna E Mrs	R. L. Polk Co.	Image pg. A90
1950	Gleason E E Mrs	R. L. Polk Co., Publishers	Image pg. A100
1946	Gleason E E Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Gleason V E Mrs	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Bottom S H	R. L. Polk Co. of California, Publishers	Image pg. A133
	Gleason E E Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Gleason Mrs E E	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Gleason T F	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Gleason T F	Polk-Husted Directory Co.	Image pg. A166

428 SAN JOAQUIN S

Year	Uses	Source	
1960	Lee Harry L	R. L. Polk Co., Publishers	Image pg. A82
1955	Lee Harry L	R. L. Polk Co.	Image pg. A90
1950	Lee H L	R. L. Polk Co., Publishers	Image pg. A100
1946	Yee A R	R. L. Polk Co., Publishers	Image pg. A108
	Wu Adam	R. L. Polk Co., Publishers	Image pg. A108
1935	Wong Dewey Mrs	R. L. Polk Co. of California, Publishers	Image pg. A123

FINDINGS

Year	Uses	Source	
1930	Wong Dew ey Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Attinger R E	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Sievers F R	Polk-Husted Directory Co.	Image pg. A166

430 SAN JOAQUIN S

Year	Uses	Source	
1960	Lee Harry L osteo	R. L. Polk Co., Publishers	Image pg. A82
1955	Lee Harry L osteo	R. L. Polk Co.	Image pg. A90
1950	j Lee H L osteo phlys	R. L. Polk Co., Publishers	Image pg. A101
1946	Wong Y K Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Aldazabal Segundo	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Aldazabal Secundo	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Echart Yidefonco	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Martini Dario	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Gambetta Carmelita w id	Polk-Husted Directory Co.	Image pg. A166
	John	Polk-Husted Directory Co.	Image pg. A166

431 SAN JOAQUIN S

Year	Uses	Source	
1960	a Quirarte Carmnen D Mrs	R. L. Polk Co., Publishers	Image pg. A82
	Carranza Lupe Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	a Echandi Rufino	R. L. Polk Co.	Image pg. A90
	Carranza Lupe Mrs	R. L. Polk Co.	Image pg. A90
1950	Echandi Rutflno	R. L. Polk Co., Publishers	Image pg. A101
	Irarte Thos	R. L. Polk Co., Publishers	Image pg. A101
1946	Jriarte Tohs	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Morrow W A	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Alustiza Fermin	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Trethew ay E E	Polk-Husted Directory Co.	Image pg. A166

FINDINGS

435 SAN JOAQUIN S

Year	Uses	Source	
1960	Iriarte Thos	R. L. Polk Co., Publishers	Image pg. A82
1955	Triarte Thos	R. L. Polk Co.	Image pg. A90
1950	Dunsing C H	R. L. Polk Co., Publishers	Image pg. A101
1946	Preston L C	R. L. Polk Co., Publishers	Image pg. A108
1935	Ioult Bee Mirs	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Hoult Mee Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Hoult D J	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	i Smith H A	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Holmes W R	Polk-Husted Directory Co.	Image pg. A172

437 SAN JOAQUIN S

Year	Uses	Source	
1960	Leyva Mary Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	George Julia J Mrs	R. L. Polk Co.	Image pg. A90
1950	Smith Jos	R. L. Polk Co., Publishers	Image pg. A101
1946	Smith Jos	R. L. Polk Co., Publishers	Image pg. A108
1935	Simall E i Mrs	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Brow n Valeria Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	King Thos	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	King Thos	Polk-Husted Directory Co.	Image pg. A172

440 SAN JOAQUIN S

Year	Uses	Source	
2003	BING KONG TONG	SBC PACIFIC BELL	
1960	Louie Lung On &	R. L. Polk Co., Publishers	Image pg. A82
1955	Louie Lung On	R. L. Polk Co.	Image pg. A90
1950	Louie L	R. L. Polk Co., Publishers	Image pg. A101
1946	a Yee Ckarti Louis	R. L. Polk Co., Publishers	Image pg. A108
1930	Spanos Chris	R. L. Polk Co. of California, Publishers	Image pg. A133
	Checolas Steve	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Edw ards J W	Polk-Husted Directory Co., Publishers	Image pg. A156

Year	Uses	Source	
1916	Vassallo Jas	Polk-Husted Directory Co.	Image pg. A172

442 SAN JOAQUIN S

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A90
1950	Dun Richd	R. L. Polk Co., Publishers	Image pg. A101

443 SAN JOAQUIN S

Year	Uses	Source	
1930	Fraser Furnace Co	R. L. Polk Co. of California, Publishers	Image pg. A133

444 SAN JOAQUIN S

Year	Uses	Source	
1935	Spanos Chris	R. L. Polk Co. of California, Publishers	Image pg. A123

445 SAN JOAQUIN S

Year	Uses	Source	
2003	GOSPEL CENTER RESCUE MISSION	SBC PACIFIC BELL	
1960	Fraser Air Conditioning Inc	R. L. Polk Co., Publishers	Image pg. A82
1955	Fraser Sls & Serv	R. L. Polk Co.	Image pg. A90
1950	Co heating appls	R. L. Polk Co., Publishers	Image pg. A101
	Fraser Sales & Serv	R. L. Polk Co., Publishers	Image pg. A101
1946	AFraser Furnace Co	R. L. Polk Co., Publishers	Image pg. A108
	Fraser Sales & Serv	R. L. Polk Co., Publishers	Image pg. A108
1935	office	R. L. Polk Co. of California, Publishers	Image pg. A123
	Fraser Furnace Co	R. L. Polk Co. of California, Publishers	Image pg. A123

448 SAN JOAQUIN S

Year	Uses	Source
2003	Magsayo Oscar	SBC PACIFIC BELL
	Magsayo Lochinbar	SBC PACIFIC BELL
	Cellero Prudencia B	SBC PACIFIC BELL

501 SAN JOAQUIN S

Year	Uses	Source	
1930	City National Corp	R. L. Polk Co. of California, Publishers	Image pg. A139

Year	Uses	Source	
1930	Calitalo Investment Co	R. L. Polk Co. of California, Publishers	Image pg. A139
	Vincent Frederic & Co inv	R. L. Polk Co. of California, Publishers	Image pg. A139

502 SAN JOAQUIN S

Year	Uses	Source	
2003	TSU V MARKET	SBC PACIFIC BELL	
1960	South San Joaquin Mkt	R. L. Polk Co., Publishers	Image pg. A82
1955	South San Joaquin Mkt	R. L. Polk Co.	Image pg. A90
1950	Pereira Amaro gro	R. L. Polk Co., Publishers	Image pg. A101
1946	a Baumgartner H C gro	R. L. Polk Co., Publishers	Image pg. A108
1935	Minaglia Manuel gro	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Minaglio Bros gro	R. L. Polk Co. of California, Publishers	Image pg. A133

503 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Raggio M A	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Kroeckel Geo	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Schmidt A	Polk-Husted Directory Co.	Image pg. A172

504 SAN JOAQUIN S

Year	Uses	Source	
1955	Mordeglia Joseph	R. L. Polk Co.	Image pg. A90
1950	Mordeglia Jos	R. L. Polk Co., Publishers	Image pg. A101
1946	Mordegli Jos	R. L. Polk Co., Publishers	Image pg. A108
1935	Minaglia Manuel	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Minoglio Manuel	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Minaglia Manuel	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Minaglia Manuel	Polk-Husted Directory Co., Publishers	Image pg. A156
1916	Schreiber A F	Polk-Husted Directory Co.	Image pg. A172
	Deuw ell Mrs L N	Polk-Husted Directory Co.	Image pg. A172

FINDINGS

505 SAN JOAQUIN S

Year	Uses	Source	
1930	Dustin M J dentist	R. L. Polk Co. of California, Publishers	Image pg. A139

506 SAN JOAQUIN S

Year	Uses	Source	
2003	Diamante Godofredo	SBC PACIFIC BELL	
1960	Vasques Carlos V	R. L. Polk Co., Publishers	Image pg. A82
1955	Scottys Pet Food Mkt	R. L. Polk Co.	Image pg. A90
1950	foods	R. L. Polk Co., Publishers	Image pg. A101
	Campbell D M	R. L. Polk Co., Publishers	Image pg. A101
	Campbell D M pet	R. L. Polk Co., Publishers	Image pg. A101
1946	Allec Gertrude	R. L. Polk Co., Publishers	Image pg. A108
	foods	R. L. Polk Co., Publishers	Image pg. A108
	Simmons E C pet	R. L. Polk Co., Publishers	Image pg. A108
1935	Lacondeguy leter	R. L. Polk Co. of California, Publishers	Image pg. A123
	meats	R. L. Polk Co. of California, Publishers	Image pg. A123
	Minaglia M a n u e l	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Minaglio Bros meats	R. L. Polk Co. of California, Publishers	Image pg. A133
	Maurer J C & Sons shippers	R. L. Polk Co. of California, Publishers	Image pg. A139
1921	Webster J H	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Webster J H	Polk-Husted Directory Co.	Image pg. A172

508 SAN JOAQUIN S

Year	Uses	Source	
2003	Dumo Elino	SBC PACIFIC BELL	
	Furnis Eugenia	SBC PACIFIC BELL	
1960	Martinez Frank S	R. L. Polk Co., Publishers	Image pg. A82
	k Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Vacant	R. L. Polk Co.	Image pg. A90
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A101
	Vacant	R. L. Polk Co., Publishers	Image pg. A101
1946	Amestoy Jas	R. L. Polk Co., Publishers	Image pg. A108
	Vacant	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123

FINDINGS

Year	Uses	Source	
1930	2 Frymyer J L	R. L. Polk Co. of California, Publishers	Image pg. A133
	Perez Eloi	R. L. Polk Co. of California, Publishers	Image pg. A133
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139
1925	Tibbetts Ray	R. L. Polk Co. of California, Publishers	Image pg. A146
	Goinetti Wm	R. L. Polk Co. of California, Publishers	Image pg. A146
1916	Sattui Sami	Polk-Husted Directory Co.	Image pg. A172

509 SAN JOAQUIN S

Year	Uses	Source	
1930	Ford Kate	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Gomes Mrs Anna	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Vacant	Polk-Husted Directory Co.	Image pg. A172

510 SAN JOAQUIN S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Vacant	R. L. Polk Co.	Image pg. A90
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A101
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Battilana Giuseppe	R. L. Polk Co. of California, Publishers	Image pg. A133
	pract	R. L. Polk Co. of California, Publishers	Image pg. A139
	Minturn T R jr C S	R. L. Polk Co. of California, Publishers	Image pg. A139
	pract	R. L. Polk Co. of California, Publishers	Image pg. A139
	Hackett I C Mrs C S	R. L. Polk Co. of California, Publishers	Image pg. A139
1921	Comendant Thos	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Brown C H	Polk-Husted Directory Co.	Image pg. A172

512 SAN JOAQUIN S

Year	Uses	Source	
2003	Aguilar Jose Gudalupe	SBC PACIFIC BELL	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Barber Jessie D Mrs	R. L. Polk Co.	Image pg. A90
1950	Parker Earl	R. L. Polk Co., Publishers	Image pg. A101

FINDINGS

Year	Uses	Source	
1946	Snelling H W	R. L. Polk Co., Publishers	Image pg. A108
1935	Woodw orth Lorcn	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Smith L V	R. L. Polk Co. of California, Publishers	Image pg. A133
	Webster J H	R. L. Polk Co. of California, Publishers	Image pg. A133
	Webster P M Mrs	R. L. Polk Co. of California, Publishers	Image pg. A133
	nurse	R. L. Polk Co. of California, Publishers	Image pg. A133
1921	Midas W V	Polk-Husted Directory Co., Publishers	Image pg. A162
	Canepa Jos	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Legri Chas	Polk-Husted Directory Co.	Image pg. A172

513 SAN JOAQUIN S

Year	Uses	Source	
1955	Zook Vern H Rev	R. L. Polk Co.	Image pg. A90
1950	Ford E J	R. L. Polk Co., Publishers	Image pg. A101
1946	a Ford E J	R. L. Polk Co., Publishers	Image pg. A108
1935	Ford Kate o	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Moore L E	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	New stadt Sami	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	New stadt Sami	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Bialkin Abraham	Polk-Husted Directory Co.	Image pg. A172

514 SAN JOAQUIN S

Year	Uses	Source	
2003	Jose P Martin	SBC PACIFIC BELL	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A82
1955	Matthew s Joseph	R. L. Polk Co.	Image pg. A90
1950	Cooper J	R. L. Polk Co., Publishers	Image pg. A101
	a Jones E C Mrs	R. L. Polk Co., Publishers	Image pg. A101
1946	Jones E Celia	R. L. Polk Co., Publishers	Image pg. A108
	Mow er C E	R. L. Polk Co., Publishers	Image pg. A108
1935	Mullis W C	R. L. Polk Co. of California, Publishers	Image pg. A123
	Williams G E	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Mullis W C	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Shares Albt	R. L. Polk Co. of California, Publishers	Image pg. A146

Year	Uses	Source	
1925	Dukes W S	R. L. Polk Co. of California, Publishers	Image pg. A146
	Piercefield Chas	R. L. Polk Co. of California, Publishers	Image pg. A146
	Robinson Wm	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Zissimos Geo	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Scott G R	Polk-Husted Directory Co.	Image pg. A172

516 SAN JOAQUIN S

Year	Uses	Source	
2003	Lopez Agustin	SBC PACIFIC BELL	
1960	Corren M & Sons w hse	R. L. Polk Co., Publishers	Image pg. A82
	Telena Antonio	R. L. Polk Co., Publishers	Image pg. A82
1955	Telena Antonio	R. L. Polk Co.	Image pg. A90
1950	Telena Antonio	R. L. Polk Co., Publishers	Image pg. A101
1946	Telena Anthony	R. L. Polk Co., Publishers	Image pg. A108
1930	Predegne John	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Molini H R	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Lightner C C	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Crow ell T	Polk-Husted Directory Co.	Image pg. A172

517 SAN JOAQUIN S

Year	Uses	Source	
1960	Reed Mary Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Telleria Concepcion Mrs	R. L. Polk Co.	Image pg. A90
1950	Telleria Conchita Mrs	R. L. Polk Co., Publishers	Image pg. A101
1946	Telleria Conchita Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Mattingly J	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Buffum E D	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Floyd L E	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Bable i E H	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Blair Thos	Polk-Husted Directory Co.	Image pg. A172

518 SAN JOAQUIN S

Year	Uses	Source	
1955	Corren M & Sons w hse	R. L. Polk Co.	Image pg. A90

FINDINGS

Year	Uses	Source	
1950	A Corren M & Sons w hs	R. L. Polk Co., Publishers	Image pg. A101
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Allec Bros auto repr	R. L. Polk Co. of California, Publishers	Image pg. A133

519 SAN JOAQUIN S

Year	Uses	Source	
1960	Sarmiento Phillip N	R. L. Polk Co., Publishers	Image pg. A82
1955	Hernandez Felix	R. L. Polk Co.	Image pg. A90
1950	Blair Cath Mrs	R. L. Polk Co., Publishers	Image pg. A101
1946	Blair Cath Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Blair Thos o	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Blair Thos o	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Blair Thos	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Blair Thos	Polk-Husted Directory Co., Publishers	Image pg. A162

521 SAN JOAQUIN S

Year	Uses	Source	
2003	Koemanivong T	SBC PACIFIC BELL	
1960	Caskey Martelle	R. L. Polk Co., Publishers	Image pg. A82
1955	Caskey Martelle	R. L. Polk Co.	Image pg. A90
1950	a Caskey Martelle	R. L. Polk Co., Publishers	Image pg. A101
1946	Webb B E Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Secina Ernest	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Harris Frank	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Madsen Lars	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Neves M L	Polk-Husted Directory Co., Publishers	Image pg. A162

522 SAN JOAQUIN S

Year	Uses	Source	
1921	Stevenson B L	Polk-Husted Directory Co., Publishers	Image pg. A162
	Hoult W J	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Hoult N J	Polk-Husted Directory Co.	Image pg. A172

FINDINGS

523 SAN JOAQUIN S

Year	Uses	Source	
2003	YEE FUNG TOY FAMILY ASSOCIATION OF STOCKTON	SBC PACIFIC BELL	
1960	Fong Hierbert G	R. L. Polk Co., Publishers	Image pg. A82
1955	Lee Jim	R. L. Polk Co.	Image pg. A90
1950	Casselman F C	R. L. Polk Co., Publishers	Image pg. A101
1946	Casscl man F C	R. L. Polk Co., Publishers	Image pg. A108
1935	Uren R C	R. L. Polk Co. of California, Publishers	Image pg. A123
1925	Whittle Jos	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Chirhart J M	Polk-Husted Directory Co., Publishers	Image pg. A162

528 SAN JOAQUIN S

Year	Uses	Source	
2003	Lomeli Pablo	SBC PACIFIC BELL	
1960	Domench Saturnino	R. L. Polk Co., Publishers	Image pg. A82
1955	Domench Saturmno	R. L. Polk Co.	Image pg. A90
1950	a Domench Saturnino	R. L. Polk Co., Publishers	Image pg. A101
1946	ADomencji Saturino	R. L. Polk Co., Publishers	Image pg. A108
1935	Domench Saturi no o	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Domench Saturino	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Domench S A	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Domench :S A	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Vacant	Polk-Husted Directory Co.	Image pg. A172

529 SAN JOAQUIN S

Year	Uses	Source	
2003	Ruiz F	SBC PACIFIC BELL	
1960	Cesmat Felicie Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Cesmat Felicie Mrs 0 41 HO	R. L. Polk Co.	Image pg. A90
1950	a Cesmat E L	R. L. Polk Co., Publishers	Image pg. A101
1946	ACesmat B E	R. L. Polk Co., Publishers	Image pg. A108
1935	Cesmat Emile o	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Cesmat E L	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Cemat Emile	R. L. Polk Co. of California, Publishers	Image pg. A146

Year	Uses	Source	
1921	Cesmat Emil	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Cesmat Emil	Polk-Husted Directory Co.	Image pg. A172

534 SAN JOAQUIN S

Year	Uses	Source	
1960	Tellaria Concepcion Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Leache Rospicio	R. L. Polk Co.	Image pg. A90
1950	J Leache Rospicio	R. L. Polk Co., Publishers	Image pg. A101
1946	Williams Ruth Mrs	R. L. Polk Co., Publishers	Image pg. A108
1930	Urzanqui Sebastian	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Rick Harry	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Gurtis Mrs Minnie	Polk-Husted Directory Co., Publishers	Image pg. A162
	Shinn L A	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Wauldrow D A	Polk-Husted Directory Co.	Image pg. A172

535 SAN JOAQUIN S

Year	Uses	Source	
2003	KWONG TUCK WO	SBC PACIFIC BELL	
	Situ Hui Ci	SBC PACIFIC BELL	
1955	Vacant	R. L. Polk Co.	Image pg. A90
1950	Hartman Jos	R. L. Polk Co., Publishers	Image pg. A101
	Haynes Hazel Mrs	R. L. Polk Co., Publishers	Image pg. A101
	Ryan John	R. L. Polk Co., Publishers	Image pg. A101
	Sloughman Fred	R. L. Polk Co., Publishers	Image pg. A101
	Tant Edw	R. L. Polk Co., Publishers	Image pg. A101
1946	Parr John	R. L. Polk Co., Publishers	Image pg. A108
1935	Morell Wm	R. L. Polk Co. of California, Publishers	Image pg. A123
	Trujillo Edw	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Morell Wm	R. L. Polk Co. of California, Publishers	Image pg. A133
	Larkin J E	R. L. Polk Co. of California, Publishers	Image pg. A133
	Femono L H	R. L. Polk Co. of California, Publishers	Image pg. A133
1921	Darling S W	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Heery J M	Polk-Husted Directory Co.	Image pg. A172
	Franck C F	Polk-Husted Directory Co.	Image pg. A172

Year	Uses	Source	
1916	Canepa J W	Polk-Husted Directory Co.	Image pg. A172

536 SAN JOAQUIN S

Year	Uses	Source	
1960	Alegria Antonia Mrs	R. L. Polk Co., Publishers	Image pg. A82
1955	Errecart Anna Mrs	R. L. Polk Co.	Image pg. A90
1950	a Errecart Anna Mrs	R. L. Polk Co., Publishers	Image pg. A101
1946	Errecart Anna Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Rick Harry	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Changala Domingo	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Changala Domingo	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Crane G E	Polk-Husted Directory Co.	Image pg. A172

537 SAN JOAQUIN S

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A90
1950	Hoult Mary E	R. L. Polk Co., Publishers	Image pg. A101
1946	Hoult Mary E	R. L. Polk Co., Publishers	Image pg. A108
1935	Hoult Mary E to	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Hoult Miary E o	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Hoult Emma	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Hoult Ellen	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Hoult M Elizabeth	Polk-Husted Directory Co.	Image pg. A172

538 SAN JOAQUIN S

Year	Uses	Source	
2003	Oak Tin Gee How	SBC PACIFIC BELL	
1960	Credit Union 1 H	R. L. Polk Co., Publishers	Image pg. A82
	Erro Marcele Mrs 4 H	R. L. Polk Co., Publishers	Image pg. A82
	San Joaquin County Emps	R. L. Polk Co., Publishers	Image pg. A82
1955	Errecart Dominic	R. L. Polk Co.	Image pg. A90
1950	a Hennis G C	R. L. Polk Co., Publishers	Image pg. A101
1946	Hoult W J	R. L. Polk Co., Publishers	Image pg. A108

Year	Uses	Source	
1935	Hoult W J	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Hoult W J	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Idiart John	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Idiart John	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Brinkerhoff Mrs M A	Polk-Husted Directory Co.	Image pg. A172

540 SAN JOAQUIN S

Year	Uses	Source	
1960	Tohanie Antonio	R. L. Polk Co., Publishers	Image pg. A82
1955	Robidart Marcel A	R. L. Polk Co.	Image pg. A90
1950	Robidard M A	R. L. Polk Co., Publishers	Image pg. A101
	Mentaberry Felipa Mrs	R. L. Polk Co., Publishers	Image pg. A101
1946	a Mentaberry Felipa Mrs	R. L. Polk Co., Publishers	Image pg. A108
1935	Beauregard Mrs Mrs	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A133
1925	Hall Mrs Mary	R. L. Polk Co. of California, Publishers	Image pg. A146
1921	Hall H H	Polk-Husted Directory Co., Publishers	Image pg. A162
1916	Hall Mary A w id W W	Polk-Husted Directory Co.	Image pg. A172

541 SAN JOAQUIN S

Year	Uses	Source	
1925	d New ell J A	R. L. Polk Co. of California, Publishers	Image pg. A146

601 SAN JOAQUIN S

Year	Uses	Source	
1960	Bayan Theo G	R. L. Polk Co., Publishers	Image pg. A82
1955	Durant Oscar F	R. L. Polk Co.	Image pg. A90
1950	Alberta Robt	R. L. Polk Co., Publishers	Image pg. A101
1946	Dillon J C	R. L. Polk Co., Publishers	Image pg. A108
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A123
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

602 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

FINDINGS

603 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

604 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

605 SAN JOAQUIN S

Year	Uses	Source	
1930	County Public Ad	R. L. Polk Co. of California, Publishers	Image pg. A139
	Dunn L B county	R. L. Polk Co. of California, Publishers	Image pg. A139
	ministrator	R. L. Polk Co. of California, Publishers	Image pg. A139
	pub administrator	R. L. Polk Co. of California, Publishers	Image pg. A139
	Foltz Rendon & Wal	R. L. Polk Co. of California, Publishers	Image pg. A139
	lace law yers	R. L. Polk Co. of California, Publishers	Image pg. A139
	Kennedy J B law yer	R. L. Polk Co. of California, Publishers	Image pg. A139
	Scanlan A V law yer	R. L. Polk Co. of California, Publishers	Image pg. A139

612 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

614 SAN JOAQUIN S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A139

615 SAN JOAQUIN S

Year	Uses	Source	
1930	C S pract	R. L. Polk Co. of California, Publishers	Image pg. A139
	Hansen Daw n Mrs	R. L. Polk Co. of California, Publishers	Image pg. A139
	pract	R. L. Polk Co. of California, Publishers	Image pg. A139
	Buck B S Mrs C S	R. L. Polk Co. of California, Publishers	Image pg. A139

FINDINGS

SAN JOAQUIN ST S

301 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Bing Kong Tong Chinese Free Mission	R. L. Polk Co., Publishers	Image pg. A25
1965	CHURCH H	R. L. Polk Co., Publishers	Image pg. A72
	SALVATION ARMY CITADEL	R. L. Polk Co., Publishers	Image pg. A72

302 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Stockton Poultry Market	R. L. Polk Co., Publishers	Image pg. A25
1965	STOCKTON POULTRY MARKET	R. L. Polk Co., Publishers	Image pg. A72

308 SAN JOAQUIN ST S

Year	Uses	Source	
1984	American Savings & Loan Training Dept	R. L. Polk Co., Publishers	Image pg. A25

311 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A25
	Gonzales M	R. L. Polk Co., Publishers	Image pg. A25
	Seputado	R. L. Polk Co., Publishers	Image pg. A25
	Xiong Chao	R. L. Polk Co., Publishers	Image pg. A25
	Mora D	R. L. Polk Co., Publishers	Image pg. A25
	Vacant	R. L. Polk Co., Publishers	Image pg. A25
	Vacant	R. L. Polk Co., Publishers	Image pg. A25
1965	APARTMENTS	R. L. Polk Co., Publishers	Image pg. A72
	MALHON CLAUDIO	R. L. Polk Co., Publishers	Image pg. A72
	VACANT	R. L. Polk Co., Publishers	Image pg. A72
	RIALOBIN V M	R. L. Polk Co., Publishers	Image pg. A72
	JACKSON JOE W	R. L. Polk Co., Publishers	Image pg. A72
	KUNG Y Y	R. L. Polk Co., Publishers	Image pg. A72
	LUCERO JAMES	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

318 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Thrifty Boutique Gift Shop	R. L. Polk Co., Publishers	Image pg. A25

319 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Quong Wah Yuen Chinese Store gro	R. L. Polk Co., Publishers	Image pg. A25
1965	SHOP H	R. L. Polk Co., Publishers	Image pg. A72
	BEAUTY BUNGALOW BEAUTY	R. L. Polk Co., Publishers	Image pg. A72

320 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Drive In Barber Shop	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

321 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Wong Family Benevolent Assn	R. L. Polk Co., Publishers	Image pg. A25
1965	UNDER CONSTN	R. L. Polk Co., Publishers	Image pg. A72

325 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Fong S L	R. L. Polk Co., Publishers	Image pg. A25
1965	FONG SUEV LUNG HERBS	R. L. Polk Co., Publishers	Image pg. A72

329 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Murrieta Farm Labor Serv	R. L. Polk Co., Publishers	Image pg. A25
1965	AGRICULTURAL WKRS UNION AFL CIO	R. L. Polk Co., Publishers	Image pg. A72

330 SAN JOAQUIN ST S

Year	Uses	Source	
1965	HOM JEUNG	R. L. Polk Co., Publishers	Image pg. A72

331 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Kenley Company Market gro	R. L. Polk Co., Publishers	Image pg. A25
1965	KENLEY CO MARKET GRO	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

332 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Wong Chun Yuk	R. L. Polk Co., Publishers	Image pg. A25
1965	BLAINE PHILLIP R	R. L. Polk Co., Publishers	Image pg. A72

334 SAN JOAQUIN ST S

Year	Uses	Source	
1984	aCuario Honorio J	R. L. Polk Co., Publishers	Image pg. A25
	bYan Tom	R. L. Polk Co., Publishers	Image pg. A25
1965	VANCXNI PETER	R. L. Polk Co., Publishers	Image pg. A72

335 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Alex	R. L. Polk Co., Publishers	Image pg. A25
1965	NIXON HOTEL LODGINGS	R. L. Polk Co., Publishers	Image pg. A72

337 SAN JOAQUIN ST S

Year	Uses	Source	
1965	BOBBIN UPOLSTERY SHOP	R. L. Polk Co., Publishers	Image pg. A72
	UPHOLSTERING	R. L. Polk Co., Publishers	Image pg. A72

343 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Cosmos Hotel	R. L. Polk Co., Publishers	Image pg. A25
	Super Clean Products	R. L. Polk Co., Publishers	Image pg. A25
1965	BASCONIA HOTEL H	R. L. Polk Co., Publishers	Image pg. A72

344 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

345 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Chew A	R. L. Polk Co., Publishers	Image pg. A25

FINDINGS

346 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Chin Tun Harry s Tom Wing	R. L. Polk Co., Publishers	Image pg. A25
	Kiang Quan	R. L. Polk Co., Publishers	Image pg. A25
	Yee Min	R. L. Polk Co., Publishers	Image pg. A25
	Apartments	R. L. Polk Co., Publishers	Image pg. A25
	Mah Q	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72
	MAR WAH SING	R. L. Polk Co., Publishers	Image pg. A72
	I YIP B H	R. L. Polk Co., Publishers	Image pg. A72
	APARTMENTS	R. L. Polk Co., Publishers	Image pg. A72

347 SAN JOAQUIN ST S

Year	Uses	Source	
1984	La Perlas tavern	R. L. Polk Co., Publishers	Image pg. A25
1965	JESSIES PLACE TAVERN	R. L. Polk Co., Publishers	Image pg. A72

348 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Marrs Association	R. L. Polk Co., Publishers	Image pg. A25
1965	MARRS ASSN	R. L. Polk Co., Publishers	Image pg. A72

400 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Western Empire Investment Co	R. L. Polk Co., Publishers	Image pg. A25
	5th Fl Vacant	R. L. Polk Co., Publishers	Image pg. A25

402 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Mavelot Narciso	R. L. Polk Co., Publishers	Image pg. A25
1965	GARCIA FRANCISCO	R. L. Polk Co., Publishers	Image pg. A72

403 SAN JOAQUIN ST S

Year	Uses	Source	
1984	New Hope Family Shelter	R. L. Polk Co., Publishers	Image pg. A25
1965	ALUSTIZAS CALIFORNIA	R. L. Polk Co., Publishers	Image pg. A72

Year	Uses	Source	
1965	HOTEL BUFFET RESTR	R. L. Polk Co., Publishers	Image pg. A72
	CALIFORNIA HOTEL H	R. L. Polk Co., Publishers	Image pg. A72

404 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Tran Canh D	R. L. Polk Co., Publishers	Image pg. A25
1965	ESTABILLO MATTIAS H	R. L. Polk Co., Publishers	Image pg. A72

406 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Prado Francisco	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

407 SAN JOAQUIN ST S

Year	Uses	Source	
1965	CALIFORNIA HOTEL BARBER	R. L. Polk Co., Publishers	Image pg. A72

408 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Lanogan Hilario B	R. L. Polk Co., Publishers	Image pg. A25
1965	YEP BENNY H	R. L. Polk Co., Publishers	Image pg. A72

410 SAN JOAQUIN ST S

Year	Uses	Source	
1984	b Vargas Adelberto	R. L. Polk Co., Publishers	Image pg. A25
	No Return	R. L. Polk Co., Publishers	Image pg. A25
	Yang Char	R. L. Polk Co., Publishers	Image pg. A25
1965	NO RETURN	R. L. Polk Co., Publishers	Image pg. A72

412 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Ulvang Dorothy M	R. L. Polk Co., Publishers	Image pg. A25
1965	ULVANG DOROTHY MRS	R. L. Polk Co., Publishers	Image pg. A72

414 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A25

Year	Uses	Source	
1965	GALLEGOS REYES	R. L. Polk Co., Publishers	Image pg. A72

416 SAN JOAQUIN ST S

Year	Uses	Source	
1984	b De La Cruz E	R. L. Polk Co., Publishers	Image pg. A25
	Cedinio Pile	R. L. Polk Co., Publishers	Image pg. A25
	Vang Bria Xue	R. L. Polk Co., Publishers	Image pg. A25
1965	GREEN LEON H	R. L. Polk Co., Publishers	Image pg. A72

420 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Stockton Family Shelter	R. L. Polk Co., Publishers	Image pg. A25
1965	SAINT BENEDICT CONVENT	R. L. Polk Co., Publishers	Image pg. A72

423 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Blancke Ernest	R. L. Polk Co., Publishers	Image pg. A25
1965	GLEASON EDNA E MRS	R. L. Polk Co., Publishers	Image pg. A72

428 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Lee Harry L	R. L. Polk Co., Publishers	Image pg. A25
1965	LEE HARRY L o H	R. L. Polk Co., Publishers	Image pg. A72

430 SAN JOAQUIN ST S

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A25
1965	LEE HARRY L OSTEOPHATIC	R. L. Polk Co., Publishers	Image pg. A72

431 SAN JOAQUIN ST S

Year	Uses	Source	
1984	a Hernandez Gregory	R. L. Polk Co., Publishers	Image pg. A25
	Godoy Louie	R. L. Polk Co., Publishers	Image pg. A25
1965	A TEARO PAUL H	R. L. Polk Co., Publishers	Image pg. A72
	SUANT OLIVAS H	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

435 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Davis Jenny	R. L. Polk Co., Publishers	Image pg. A25

437 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Turner	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

440 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Barroga Zoilo	R. L. Polk Co., Publishers	Image pg. A25
1965	LOUIE LUNG ON 0 H	R. L. Polk Co., Publishers	Image pg. A72

442 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Riego Rufhno	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

445 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Stockton Gospel Rescue Mission	R. L. Polk Co., Publishers	Image pg. A25
1965	FRASER HEATING CO CONTRS H	R. L. Polk Co., Publishers	Image pg. A72

448 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A25
	Tornea Ricardo	R. L. Polk Co., Publishers	Image pg. A25
	Corrales Mike	R. L. Polk Co., Publishers	Image pg. A25
	Arnmo Apartments	R. L. Polk Co., Publishers	Image pg. A25
	Rabaca Mel	R. L. Polk Co., Publishers	Image pg. A25
	Racho Rudy	R. L. Polk Co., Publishers	Image pg. A25
	Lomo Uljo Jerry L	R. L. Polk Co., Publishers	Image pg. A25
	Jung Jang	R. L. Polk Co., Publishers	Image pg. A25
1965	ARNO APARTMENTS	R. L. Polk Co., Publishers	Image pg. A72
	I CHOY WALTER	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

Year	Uses	Source	
1965	MACHADO DON	R. L. Polk Co., Publishers	Image pg. A72
	ENCISCO MARIA E	R. L. Polk Co., Publishers	Image pg. A72
	JUNG JANG	R. L. Polk Co., Publishers	Image pg. A72
	SIEVERS WILLIAM R	R. L. Polk Co., Publishers	Image pg. A72
	LEMONZA DON	R. L. Polk Co., Publishers	Image pg. A72
	LAO DAVID	R. L. Polk Co., Publishers	Image pg. A72

502 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Go Orient Imports	R. L. Polk Co., Publishers	Image pg. A25
1965	SOUTH SAN JOAQUIN MARKET	R. L. Polk Co., Publishers	Image pg. A72

504 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A25

506 SAN JOAQUIN ST S

Year	Uses	Source	
1984	S SAN JOAQUIN ST Contd	R. L. Polk Co., Publishers	Image pg. A31
	Aquino Well	R. L. Polk Co., Publishers	Image pg. A25
	Acupuncture C	R. L. Polk Co., Publishers	Image pg. A25
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

508 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Matote Esteban	R. L. Polk Co., Publishers	Image pg. A31
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72
	K VACANT	R. L. Polk Co., Publishers	Image pg. A72

510 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Garcia Juanita B	R. L. Polk Co., Publishers	Image pg. A31
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

512 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Beamon Kevin	R. L. Polk Co., Publishers	Image pg. A31
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

514 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	b Vacant	R. L. Polk Co., Publishers	Image pg. A31
	a Toy Ning	R. L. Polk Co., Publishers	Image pg. A31
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

516 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Savila Louis	R. L. Polk Co., Publishers	Image pg. A31
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A72

517 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Baco Fred	R. L. Polk Co., Publishers	Image pg. A31
1965	CADIZ LARRY	R. L. Polk Co., Publishers	Image pg. A72

518 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	S R Fagatt Co mfrs rep	R. L. Polk Co., Publishers	Image pg. A31
1965	CORREN M AND SONS WHSE	R. L. Polk Co., Publishers	Image pg. A72

519 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Rabo Rudy Hilaria	R. L. Polk Co., Publishers	Image pg. A31
1965	MAH WING HONG	R. L. Polk Co., Publishers	Image pg. A72

521 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Cadiz Larry	R. L. Polk Co., Publishers	Image pg. A31
1965	CASKEY MARTELLE H	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

523 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Nigrana Santiago	R. L. Polk Co., Publishers	Image pg. A31
1965	FONG HERBERT G H	R. L. Polk Co., Publishers	Image pg. A72

528 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Domench Johnny	R. L. Polk Co., Publishers	Image pg. A31
1965	DOMENCH SATURNINO	R. L. Polk Co., Publishers	Image pg. A72

529 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Lee Quong Wee	R. L. Polk Co., Publishers	Image pg. A31
1965	CESMAT FELLCIE MRS a	R. L. Polk Co., Publishers	Image pg. A72

534 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Lew Kwok Jew	R. L. Polk Co., Publishers	Image pg. A31
1965	TELLARIA CONCEPCION MRS	R. L. Polk Co., Publishers	Image pg. A72

535 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	a Kwong Tuck Wo gro	R. L. Polk Co., Publishers	Image pg. A31
	b Fong Shu Chen	R. L. Polk Co., Publishers	Image pg. A31
1965	STOCKTON GENL BLDG CONTRS	R. L. Polk Co., Publishers	Image pg. A72
	GUARANTEED HOMES OF	R. L. Polk Co., Publishers	Image pg. A72

536 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Wong Ring Yuk	R. L. Polk Co., Publishers	Image pg. A31
1965	NO RETURN	R. L. Polk Co., Publishers	Image pg. A72

538 SAN JOAQUIN ST S

Year	*Uses*	*Source*	
1984	Oak Tin Gee Haw Association meeting	R. L. Polk Co., Publishers	Image pg. A31
1965	CASTILLO JUAN	R. L. Polk Co., Publishers	Image pg. A72

FINDINGS

539 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Chin Ron Joy	R. L. Polk Co., Publishers	Image pg. A31
	Fong Chen Shu Chau T Y	R. L. Polk Co., Publishers	Image pg. A31

540 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Au Yang Ming Sun	R. L. Polk Co., Publishers	Image pg. A31
1965	GUTIERREZ ALEX	R. L. Polk Co., Publishers	Image pg. A72

545 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A31

606 SAN JOAQUIN ST S

Year	Uses	Source	
1984	American Savings & Loan addl ofcs	R. L. Polk Co., Publishers	Image pg. A25

609 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A31

611 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Dunns Mini Mart gift shop	R. L. Polk Co., Publishers	Image pg. A31

613 SAN JOAQUIN ST S

Year	Uses	Source	
1984	Wash House The self serv laundromat	R. L. Polk Co., Publishers	Image pg. A31

SONORA E

125 SONORA E

Year	Uses	Source	
2003	Alacar Jose T	SBC PACIFIC BELL	
1960	Ruezo Louis R	R. L. Polk Co., Publishers	Image pg. A88
1955	Wartates Marciano	R. L. Polk Co.	Image pg. A97
1950	A Wong Frank	R. L. Polk Co., Publishers	Image pg. A106

Year	Uses	Source	
1946	Wong Frank	R. L. Polk Co., Publishers	Image pg. A113
1935	Sudow Washiro	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Sudow Washiro	R. L. Polk Co. of California, Publishers	Image pg. A140
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Narbaitz Raymond	Polk-Husted Directory Co.	Image pg. A173

127 SONORA E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A88
1955	Moscoso Enrique 0	R. L. Polk Co.	Image pg. A97
1950	Unsod D V	R. L. Polk Co., Publishers	Image pg. A106
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A113
1935	Wee Poy Wong	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Vinelli Louisa Mrs	R. L. Polk Co. of California, Publishers	Image pg. A140
1925	Vinelli Mrs Louisa	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Vinelli Mrs Louisa	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Rovera Jos	Polk-Husted Directory Co.	Image pg. A173

128 SONORA E

Year	Uses	Source	
2003	Remolana Magdalena	SBC PACIFIC BELL	
	Johnson Linda	SBC PACIFIC BELL	
	Sobrguel Estrella	SBC PACIFIC BELL	
1960	Iloile Circle Club Inc The	R. L. Polk Co., Publishers	Image pg. A88
1955	Vacant	R. L. Polk Co.	Image pg. A97
1950	Chan C Y auto Indy	R. L. Polk Co., Publishers	Image pg. A106
	and gro	R. L. Polk Co., Publishers	Image pg. A106
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A113
1935	Lacoste Etienne	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A140
1925	Baijorri Peter	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Scott Saml	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Berrnezo Eladio	Polk-Husted Directory Co.	Image pg. A173

FINDINGS

131 SONORA E

Year	Uses	Source	
1960	Gregorio Dani L	R. L. Polk Co., Publishers	Image pg. A88
1955	Gregorio Danl L	R. L. Polk Co.	Image pg. A97
1950	Gregorio D L	R. L. Polk Co., Publishers	Image pg. A106
1946	Gregorio D L	R. L. Polk Co., Publishers	Image pg. A113
1935	Sato Semu Mrs	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Sato Semu Mrs	R. L. Polk Co. of California, Publishers	Image pg. A140
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Guicnou John	Polk-Husted Directory Co.	Image pg. A173

133 SONORA E

Year	Uses	Source	
1930	Valmeres Manuel	R. L. Polk Co. of California, Publishers	Image pg. A140

134 SONORA E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Him	R. L. Polk Co.	Image pg. A97
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106

136 SONORA E

Year	Uses	Source	
1960	Estante Dani	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Shew Hin	R. L. Polk Co.	Image pg. A97
1950	Yee Helman	R. L. Polk Co., Publishers	Image pg. A106

138 SONORA E

Year	Uses	Source	
1960	Wong Ki Sim	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Ki Sim 0	R. L. Polk Co.	Image pg. A97
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106
1935	Galassi 0 J o	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Galasso 0 J marble	R. L. Polk Co. of California, Publishers	Image pg. A140
1925	Galassi 0 J	R. L. Polk Co. of California, Publishers	Image pg. A154

Year	Uses	Source	
1921	Galassi 0 J	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Riba Baptista	Polk-Husted Directory Co.	Image pg. A173

141 SONORA E

Year	Uses	Source	
1925	Meagher Thos	R. L. Polk Co. of California, Publishers	Image pg. A154

164 SONORA E

Year	Uses	Source	
1930	S Boye H A o	R. L. Polk Co. of California, Publishers	Image pg. A141

203 SONORA E

Year	Uses	Source	
1916	Harper Jas	Polk-Husted Directory Co.	Image pg. A173

204 SONORA E

Year	Uses	Source	
2003	REGIDOR LODGE 5 CDA INC	SBC PACIFIC BELL	
	Oribello Hilario A	SBC PACIFIC BELL	
	Tang Danh Van	SBC PACIFIC BELL	
	Dancel Salvador	SBC PACIFIC BELL	
1960	Regidor Lodge No CDA Inc	R. L. Polk Co., Publishers	Image pg. A88
1955	Regidor Lodge No 5 C D A Inc	R. L. Polk Co.	Image pg. A97
1950	C D A Inc	R. L. Polk Co., Publishers	Image pg. A106
	Regidor Lodge No	R. L. Polk Co., Publishers	Image pg. A106
1946	a Engkabo Pastor	R. L. Polk Co., Publishers	Image pg. A113
1935	Lum Mow	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Lum Mow	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A163

209 SONORA E

Year	Uses	Source	
1960	No Return	R. L. Polk Co., Publishers	Image pg. A88
1955	Fong Joe	R. L. Polk Co.	Image pg. A97
1950	Fong Kee	R. L. Polk Co., Publishers	Image pg. A106

FINDINGS

Year	Uses	Source	
1946	Fong Kee	R. L. Polk Co., Publishers	Image pg. A113
1935	Occupant	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Tripp A F	R. L. Polk Co. of California, Publishers	Image pg. A142
	Kim Lai Wo	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Tripp A J	Polk-Husted Directory Co.	Image pg. A173

214 SONORA E

Year	Uses	Source	
1950	Parocha P	R. L. Polk Co., Publishers	Image pg. A106
1946	A Hunter Wm	R. L. Polk Co., Publishers	Image pg. A113
1935	Campbell T B	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A163

218 SONORA E

Year	Uses	Source	
1960	Wong Oing	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Oy	R. L. Polk Co.	Image pg. A97
1950	Wong Lun	R. L. Polk Co., Publishers	Image pg. A106
1946	Palaeios Cirilio	R. L. Polk Co., Publishers	Image pg. A113
1935	Garispe Louis	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Steen Nora Mrs	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Capurro Frank R	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Holzknecht J J	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Schorbohm L J	Polk-Husted Directory Co.	Image pg. A173

221 SONORA E

Year	Uses	Source	
2003	Ramiscal Elpidio	SBC PACIFIC BELL	
1960	Ospital John	R. L. Polk Co., Publishers	Image pg. A88
	21 Lane Harry J	R. L. Polk Co., Publishers	Image pg. A88

FINDINGS

Year	Uses	Source	
1955	Toy Quoon	R. L. Polk Co.	Image pg. A97
1950	Yee L K	R. L. Polk Co., Publishers	Image pg. A106
	Foong T J	R. L. Polk Co., Publishers	Image pg. A106
1946	Arnold J J	R. L. Polk Co., Publishers	Image pg. A113
	Lane Harry	R. L. Polk Co., Publishers	Image pg. A113
1935	Harliss Evelyn Mrs	R. L. Polk Co. of California, Publishers	Image pg. A129
	De Young Marie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Mc Phail L R	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Beaumont Walter	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Pershall D H	Polk-Husted Directory Co., Publishers	Image pg. A163
1916	Fisher T E rear	Polk-Husted Directory Co.	Image pg. A173
	Vacant	Polk-Husted Directory Co.	Image pg. A173

223 SONORA E

Year	Uses	Source	
2003	Cayabyab Ricardo	SBC PACIFIC BELL	
1960	Alguinaldo Mariano D	R. L. Polk Co., Publishers	Image pg. A88
	Asuncion Salvador	R. L. Polk Co., Publishers	Image pg. A88
1955	Brow n Nola	R. L. Polk Co.	Image pg. A97
1950	Lee C K	R. L. Polk Co., Publishers	Image pg. A106
	Quong J S Mrs	R. L. Polk Co., Publishers	Image pg. A106
1946	Moreing M J Mrs	R. L. Polk Co., Publishers	Image pg. A113
	Asborne Louisa Mrs	R. L. Polk Co., Publishers	Image pg. A113
1935	Davis Celia Mrs	R. L. Polk Co. of California, Publishers	Image pg. A129
	Hollenbeck A R	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	2 Barnes J L	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Wilcox W H	R. L. Polk Co. of California, Publishers	Image pg. A154
	Erickson E G	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Peterson Andrew	Polk-Husted Directory Co., Publishers	Image pg. A164
	Rieger A F	Polk-Husted Directory Co., Publishers	Image pg. A164

224 SONORA E

Year	Uses	Source	
1960	Ramolete Mel	R. L. Polk Co., Publishers	Image pg. A88

FINDINGS

Year	Uses	Source	
1955	Garronillas Francisco	R. L. Polk Co.	Image pg. A97
1950	Lam Y T	R. L. Polk Co., Publishers	Image pg. A106

225 SONORA E

Year	Uses	Source	
2003	Tacata Violeta	SBC PACIFIC BELL	
1960	Aguilar Lena Mrs	R. L. Polk Co., Publishers	Image pg. A88
	Corpioz Mariano	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Yo Hin	R. L. Polk Co.	Image pg. A97
	Yip Wut	R. L. Polk Co.	Image pg. A97
1950	Mar S W	R. L. Polk Co., Publishers	Image pg. A106
	Jong Kenneth	R. L. Polk Co., Publishers	Image pg. A106
1946	Salbach Ida Mrs	R. L. Polk Co., Publishers	Image pg. A113
	Miles Geo	R. L. Polk Co., Publishers	Image pg. A113
1935	Zignego Antonio	R. L. Polk Co. of California, Publishers	Image pg. A129
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Wright K A	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	a 1/2 Zignego A L	R. L. Polk Co. of California, Publishers	Image pg. A154
	Wiltse H W	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	1/2 Zignego A L	Polk-Husted Directory Co., Publishers	Image pg. A164
	King F R	Polk-Husted Directory Co., Publishers	Image pg. A164

226 SONORA E

Year	Uses	Source	
1960	Wong Hing	R. L. Polk Co., Publishers	Image pg. A88
1955	Woo Geo J	R. L. Polk Co.	Image pg. A97
1950	Woo G J	R. L. Polk Co., Publishers	Image pg. A106
1946	Woo Geo	R. L. Polk Co., Publishers	Image pg. A113
1935	Bevilacqua Marie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Park Y N	R. L. Polk Co. of California, Publishers	Image pg. A142
1921	Oriental	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Vinelli C P	Polk-Husted Directory Co.	Image pg. A173

FINDINGS

227 SONORA E

Year	Uses	Source	
2003	Albano Romulo G	SBC PACIFIC BELL	
	Salvador Adelaida	SBC PACIFIC BELL	
	Ramiscal Florentina	SBC PACIFIC BELL	
1960	Gong Wong W	R. L. Polk Co., Publishers	Image pg. A88
	a Eng Fung	R. L. Polk Co., Publishers	Image pg. A88
	b Toy Quong J	R. L. Polk Co., Publishers	Image pg. A88
1955	Chin Lumrn S	R. L. Polk Co.	Image pg. A97
	a Tomlinson Ruth Mrs	R. L. Polk Co.	Image pg. A97
	c Lew is Thos J	R. L. Polk Co.	Image pg. A97
1950	Quan Soon	R. L. Polk Co., Publishers	Image pg. A106
	a Wong K K	R. L. Polk Co., Publishers	Image pg. A106
	b Malloy Louise A	R. L. Polk Co., Publishers	Image pg. A106
1946	Winstead W R	R. L. Polk Co., Publishers	Image pg. A113
1935	Lidyard E W	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Fisher T E	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Fisher T E	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Fisher T E	Polk-Husted Directory Co., Publishers	Image pg. A164

229 SONORA E

Year	Uses	Source	
2003	FRT Manganaan Arch A	SBC PACIFIC BELL	
	FRT Manganaan Cezar	SBC PACIFIC BELL	
1960	Mar Wing Y	R. L. Polk Co., Publishers	Image pg. A88
1955	Mar Wing Y	R. L. Polk Co.	Image pg. A97
1950	AMar W S Mrs	R. L. Polk Co., Publishers	Image pg. A106
1946	a Mar Jos	R. L. Polk Co., Publishers	Image pg. A113
1935	Fisher T E o	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Fisher M J Mrs	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Javete Mrs Katherine	R. L. Polk Co. of California, Publishers	Image pg. A154
	Fisher Mrs M J	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Fisher Mrs Mary	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	John	Polk-Husted Directory Co.	Image pg. A173

Year	Uses	Source	
1916	Fisher Mary A wid	Polk-Husted Directory Co.	Image pg. A173

231 SONORA E

Year	Uses	Source	
1960	Toy You Sun	R. L. Polk Co., Publishers	Image pg. A88
1955	Hill Hannah Mrs	R. L. Polk Co.	Image pg. A97
1950	Lee Lim	R. L. Polk Co., Publishers	Image pg. A106
1946	Wong Tao	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Devereaux W F	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Devereux W F	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Devereux Wm	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Lynch P J	Polk-Husted Directory Co.	Image pg. A173

232 SONORA E

Year	Uses	Source	
1960	Echandi Ruffino	R. L. Polk Co., Publishers	Image pg. A88
1955	Medina Nemesio	R. L. Polk Co.	Image pg. A97
1950	Young Lim	R. L. Polk Co., Publishers	Image pg. A106
1946	Capurro John	R. L. Polk Co., Publishers	Image pg. A113
1935	Capurro F R	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Capurro F R	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Real Mrs Leonie	R. L. Polk Co. of California, Publishers	Image pg. A154
	Capurro Rosa	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Capurro Mrs Maria	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Capurro Marie wid Jos	Polk-Husted Directory Co.	Image pg. A173

233 SONORA E

Year	Uses	Source	
1960	Bernardo Jose M AH	R. L. Polk Co., Publishers	Image pg. A88
1955	Vacant	R. L. Polk Co.	Image pg. A97
1950	Wong Y F	R. L. Polk Co., Publishers	Image pg. A106
1946	A Jung Geo	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A129

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Greenfield Abraham	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Bertolucci Jos	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Vacant	Polk-Husted Directory Co.	Image pg. A173

235 SONORA E

Year	Uses	Source	
1960	Mah Jacob	R. L. Polk Co., Publishers	Image pg. A88
1955	Hayw ard Marie Mrs	R. L. Polk Co.	Image pg. A97
1950	Wong Robt	R. L. Polk Co., Publishers	Image pg. A106
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Greenfield Abr	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Kelliher Neal	R. L. Polk Co. of California, Publishers	Image pg. A154
	Diller 0 A	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Eaton Mrs Louanna	Polk-Husted Directory Co., Publishers	Image pg. A164

237 SONORA E

Year	Uses	Source	
1960	sects	R. L. Polk Co., Publishers	Image pg. A88
	S San Joaquin inter	R. L. Polk Co., Publishers	Image pg. A88
	Perez Leonarda Mrs	R. L. Polk Co., Publishers	Image pg. A88
1955	Whiteside Mansfield	R. L. Polk Co.	Image pg. A97
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A106
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A113
1935	Moore L P	R. L. Polk Co. of California, Publishers	Image pg. A129
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A142
1925	Korens Abraham	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Mulholland Mrs Roxy	Polk-Husted Directory Co., Publishers	Image pg. A164

245 SONORA E

Year	Uses	Source	
1921	Mareden S J	Polk-Husted Directory Co., Publishers	Image pg. A164

FINDINGS

255 SONORA E

Year	Uses	Source	
1935	Risso J L o	R. L. Polk Co. of California, Publishers	Image pg. A129

274 SONORA E

Year	Uses	Source	
1930	Montoya Ygnacio	R. L. Polk Co. of California, Publishers	Image pg. A143

289 SONORA E

Year	Uses	Source	
1935	Venezuela Paublo	R. L. Polk Co. of California, Publishers	Image pg. A130

303 SONORA E

Year	Uses	Source	
1935	Davis T C	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Capurro R J Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Capurro Mrs R J	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Capurro Mrs R J	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Davis Carrie w id R F	Polk-Husted Directory Co.	Image pg. A173

305 SONORA E

Year	Uses	Source	
1935	Risso J A	R. L. Polk Co. of California, Publishers	Image pg. A131

308 SONORA E

Year	Uses	Source	
1946	Higgins Alice Mrs	R. L. Polk Co., Publishers	Image pg. A113

309 SONORA E

Year	Uses	Source	
1960	Louie Chew 0	R. L. Polk Co., Publishers	Image pg. A88
1955	Louje Chew	R. L. Polk Co.	Image pg. A97
1950	ALouie L F	R. L. Polk Co., Publishers	Image pg. A106
1946	Louie Chew	R. L. Polk Co., Publishers	Image pg. A113
1935	Copeland F R	R. L. Polk Co. of California, Publishers	Image pg. A131
	Capurro R J Mrs	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Gaffery Josie nurse	R. L. Polk Co. of California, Publishers	Image pg. A144

FINDINGS

Year	Uses	Source	
1930	Gaffery Eliz Mrs	R. L. Polk Co. of California, Publishers	Image pg. A144
	Steinmetz Sarah Mrs	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Hadley Wm	R. L. Polk Co. of California, Publishers	Image pg. A154
	Gaffery Mrs Lizzie	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Cevasco E J	Polk-Husted Directory Co., Publishers	Image pg. A164
	Gnekow W H	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Wall R E	Polk-Husted Directory Co.	Image pg. A174
	Cappurro A A	Polk-Husted Directory Co.	Image pg. A173

310 SONORA E

Year	Uses	Source	
1960	Ruella G Alvia	R. L. Polk Co., Publishers	Image pg. A88
1955	Ambalong Connie D Mrs	R. L. Polk Co.	Image pg. A97
1950	Ivie Rosa Mrs	R. L. Polk Co., Publishers	Image pg. A106
1946	Ivie Rosa	R. L. Polk Co., Publishers	Image pg. A113
	Mc Donough J D	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Smith J P	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Smith J P	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Smith J P	Polk-Husted Directory Co.	Image pg. A174

312 SONORA E

Year	Uses	Source	
1960	Sorenson Louis C	R. L. Polk Co., Publishers	Image pg. A88
1955	Sorenson Louis C	R. L. Polk Co.	Image pg. A97
1950	Sorenson L C	R. L. Polk Co., Publishers	Image pg. A106
1946	Sorenson L C	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Kane J B	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Kane Mrs M A	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Kane Jas	Polk-Husted Directory Co.	Image pg. A174

314 SONORA E

Year	Uses	Source	
1960	Perez Enrique	R. L. Polk Co., Publishers	Image pg. A88
1955	Valencia Peter	R. L. Polk Co.	Image pg. A97
1950	Jackson Jos	R. L. Polk Co., Publishers	Image pg. A106
1946	Jackson Jos	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Mc Naughton R L	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Johnson L M	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Marsh L C	Polk-Husted Directory Co.	Image pg. A174
	Rogers M E	Polk-Husted Directory Co.	Image pg. A174

315 SONORA E

Year	Uses	Source	
1960	Gow Peter W	R. L. Polk Co., Publishers	Image pg. A88
1955	Ying Kim Poo	R. L. Polk Co.	Image pg. A97
1950	Oriental	R. L. Polk Co., Publishers	Image pg. A106
1946	Jeung S Y	R. L. Polk Co., Publishers	Image pg. A113
1935	Fitzgerald R S	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Fitzgerald Hanna Z	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Fitzgerald H Z	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Fitzgerald Hanna Z	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Fitzgerald John	Polk-Husted Directory Co.	Image pg. A174

316 SONORA E

Year	Uses	Source	
1960	Rosas Peter M	R. L. Polk Co., Publishers	Image pg. A88
1955	Rosas Peter M	R. L. Polk Co.	Image pg. A97
	SONORA EAST Contd	R. L. Polk Co.	Image pg. A98
1950	Rosas P M	R. L. Polk Co., Publishers	Image pg. A106
1946	A Rosos P M	R. L. Polk Co., Publishers	Image pg. A113
1935	Mc Cracken V G	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Mc Naughton R L	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Carlin Alex	R. L. Polk Co. of California, Publishers	Image pg. A154

Year	Uses	Source	
1921	Dean Benj	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Dean Benj	Polk-Husted Directory Co.	Image pg. A174

317 SONORA E

Year	Uses	Source	
1960	Gow Toy W 0	R. L. Polk Co., Publishers	Image pg. A88
1955	Toy Wong	R. L. Polk Co.	Image pg. A98
1950	Wong Toy	R. L. Polk Co., Publishers	Image pg. A106
1946	Wong Toy	R. L. Polk Co., Publishers	Image pg. A113
1935	Paul M K Mrsr	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Paul Arth	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Hadley Mrs W F	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Kreider S K	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Vacant	Polk-Husted Directory Co.	Image pg. A174

319 SONORA E

Year	Uses	Source	
1960	Wong Chuck	R. L. Polk Co., Publishers	Image pg. A88
1955	Woon June Mrs	R. L. Polk Co.	Image pg. A98
1950	Wong J H	R. L. Polk Co., Publishers	Image pg. A106
1946	Wong Jimmie	R. L. Polk Co., Publishers	Image pg. A113
1935	Ro Bbddy Blanche Mrs	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Childs W C o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Doane Beth	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Child Wendell	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Child Wendell	Polk-Husted Directory Co.	Image pg. A174

321 SONORA E

Year	Uses	Source	
1960	Ham Shew F	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Ngshee Mrs	R. L. Polk Co.	Image pg. A98
1950	Woon Jue	R. L. Polk Co., Publishers	Image pg. A106
1946	Frausto Pauline C	R. L. Polk Co., Publishers	Image pg. A113
1935	Frausto Pauline	R. L. Polk Co. of California, Publishers	Image pg. A131

FINDINGS

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Dittmer W H	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Cluck C C	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Garibaldi J A	Polk-Husted Directory Co.	Image pg. A174

322 SONORA E

Year	Uses	Source	
2003	Tsoo Kw ok Chuen	SBC PACIFIC BELL	
1960	Gong Chor	R. L. Polk Co., Publishers	Image pg. A88
1955	Gong Chor	R. L. Polk Co.	Image pg. A98
1950	Robinson Jerry	R. L. Polk Co., Publishers	Image pg. A106
	Gibbns Jas	R. L. Polk Co., Publishers	Image pg. A106
	Gibbons Jas	R. L. Polk Co., Publishers	Image pg. A106
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A113
1935	Nave Asunta Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Nave Asunta Mrs	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Nave Chas	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Nave Chas	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Law rence D L	Polk-Husted Directory Co.	Image pg. A174

325 SONORA E

Year	Uses	Source	
1960	Chew Bing S	R. L. Polk Co., Publishers	Image pg. A88
1955	Chew Bing S	R. L. Polk Co.	Image pg. A98
1950	Chew B S	R. L. Polk Co., Publishers	Image pg. A106
1946	A Chang Johnnie	R. L. Polk Co., Publishers	Image pg. A113
	a Fong Fook	R. L. Polk Co., Publishers	Image pg. A113
1935	Ling Tony Soi	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Lee Roy	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Gibson H S	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Jones J E	Polk-Husted Directory Co., Publishers	Image pg. A164
	Carlin Jos	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Munch Minnie w id Chas	Polk-Husted Directory Co.	Image pg. A174

FINDINGS

327 SONORA E

Year	Uses	Source	
1960	Woon Sat S	R. L. Polk Co., Publishers	Image pg. A88
1955	Young Jimmie	R. L. Polk Co.	Image pg. A98
1950	Eng Jas	R. L. Polk Co., Publishers	Image pg. A106

328 SONORA E

Year	Uses	Source
2003	Fabela Catarino	SBC PACIFIC BELL

329 SONORA E

Year	Uses	Source	
1960	No Return	R. L. Polk Co., Publishers	Image pg. A88
1955	Lim Nguey T	R. L. Polk Co.	Image pg. A98
1950	Chong Edmond	R. L. Polk Co., Publishers	Image pg. A106
1946	Mayorga Jesus	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Baumel J A	R. L. Polk Co. of California, Publishers	Image pg. A154
	Baumel Mrs Lena	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Gidalovitz Adolph	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Drow n E T	Polk-Husted Directory Co.	Image pg. A174
	Mock A J	Polk-Husted Directory Co.	Image pg. A174

330 SONORA E

Year	Uses	Source	
1960	Brauer Henry J	R. L. Polk Co., Publishers	Image pg. A88
	Vacant	R. L. Polk Co., Publishers	Image pg. A88
1955	Vacant	R. L. Polk Co.	Image pg. A98
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106
	Patterson R	R. L. Polk Co., Publishers	Image pg. A106
1946	Hall G	R. L. Polk Co., Publishers	Image pg. A113
	a Robbins M T Mrs	R. L. Polk Co., Publishers	Image pg. A113
1935	Robbins M T Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A131
	Foote L M Mrs	R. L. Polk Co. of California, Publishers	Image pg. A131

Year	Uses	Source	
1930	Robbins M T Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Robbins Mrs M T	R. L. Polk Co. of California, Publishers	Image pg. A154
	Overson Harry	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Robbins Mrs M T	Polk-Husted Directory Co., Publishers	Image pg. A164
	Crosby R B	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Robbins Mary T w id	Polk-Husted Directory Co.	Image pg. A174
	Fisher J H	Polk-Husted Directory Co.	Image pg. A174

331 SONORA E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Fred	R. L. Polk Co.	Image pg. A98
1950	Mah Fred	R. L. Polk Co., Publishers	Image pg. A106
1946	Cheang Wm	R. L. Polk Co., Publishers	Image pg. A113
1935	Fong Wy	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1921	Holdsw orth Thos	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Levin Chas	Polk-Husted Directory Co.	Image pg. A174

332 SONORA E

Year	Uses	Source	
1960	Sandridge Milton	R. L. Polk Co., Publishers	Image pg. A88
1946	Price T W	R. L. Polk Co., Publishers	Image pg. A113
	Hall Margrt	R. L. Polk Co., Publishers	Image pg. A113
1935	Rodriguez Refugio	R. L. Polk Co. of California, Publishers	Image pg. A131
	Lopez Leon	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Bow mn Mary	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Wilborn R W	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Danna Aug	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Emler G S	Polk-Husted Directory Co.	Image pg. A174

334 SONORA E

Year	Uses	Source	
1960	Stokes Ida Mrs	R. L. Polk Co., Publishers	Image pg. A88

FINDINGS

Year	Uses	Source	
1955	a Nasone Frank	R. L. Polk Co.	Image pg. A98
	Stokes Ida J Mrs	R. L. Polk Co.	Image pg. A98
1950	Heaslett Andy	R. L. Polk Co., Publishers	Image pg. A106
1946	Hall G L	R. L. Polk Co., Publishers	Image pg. A113
	Robinson Jack	R. L. Polk Co., Publishers	Image pg. A113
1935	Williams S B	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Smith Mrs Ethel	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Lampson Mrs G E	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Crosby Ray	Polk-Husted Directory Co.	Image pg. A174

336 SONORA E

Year	Uses	Source	
2003	Leung Chew	SBC PACIFIC BELL	
1960	Ng Guev Fan	R. L. Polk Co., Publishers	Image pg. A88
1955	Ng Guey Fan 0	R. L. Polk Co.	Image pg. A98
1950	A Ng G F	R. L. Polk Co., Publishers	Image pg. A106
1946	Ng Guey Fan	R. L. Polk Co., Publishers	Image pg. A113
1935	Uria Eulogio	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Arbios H B o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Arbios H B	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Arbios H B	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Arbios H B	Polk-Husted Directory Co.	Image pg. A174

346 SONORA E

Year	Uses	Source	
2003	Sanchez Maria B	SBC PACIFIC BELL	
1960	Wong Steven	R. L. Polk Co., Publishers	Image pg. A88
1955	Koelbel Siegfried F	R. L. Polk Co.	Image pg. A98
1950	Galli Eug	R. L. Polk Co., Publishers	Image pg. A106
1946	A Oliver M S Mrs	R. L. Polk Co., Publishers	Image pg. A113

FINDINGS

348 SONORA E

Year	Uses	Source	
2003	Pena Raul	SBC PACIFIC BELL	
1960	Ping Marie	R. L. Polk Co., Publishers	Image pg. A88
1955	Sharp Saml B	R. L. Polk Co.	Image pg. A98
1950	Shar D S B	R. L. Polk Co., Publishers	Image pg. A106
1946	Hoell J D	R. L. Polk Co., Publishers	Image pg. A113
1935	Flavius Flavio o	R. L. Polk Co. of California, Publishers	Image pg. A131
	Flavius J B	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Wiley F M	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Wiley F M	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Robbins A J	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Needham E L	Polk-Husted Directory Co.	Image pg. A174

349 SONORA E

Year	Uses	Source	
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106

403 SONORA E

Year	Uses	Source	
1930	Clay J S	R. L. Polk Co. of California, Publishers	Image pg. A144

416 SONORA E

Year	Uses	Source	
1960	Phillips Harry	R. L. Polk Co., Publishers	Image pg. A88
1955	Fong Gee Shee Mrs	R. L. Polk Co.	Image pg. A98
1950	Fong T Y	R. L. Polk Co., Publishers	Image pg. A106
1946	A Fong Rose	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Gillit A W o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Vetters Mrs Mary	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Vierth H F	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Morenzoni Henry	Polk-Husted Directory Co.	Image pg. A174

FINDINGS

418 SONORA E

Year	Uses	Source	
2003	Mak Lian Zhu	SBC PACIFIC BELL	
1960	Henley Susan A	R. L. Polk Co., Publishers	Image pg. A88
1955	Vacant	R. L. Polk Co.	Image pg. A98
1950	Lui K S	R. L. Polk Co., Publishers	Image pg. A106
1946	Oriental	R. L. Polk Co., Publishers	Image pg. A113
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Elder John	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Robbins Mrs Ethel	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Vacant	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	rear	Polk-Husted Directory Co.	Image pg. A174
	Peterson Mrs Sarah	Polk-Husted Directory Co.	Image pg. A174
	Egan Mrs Mary	Polk-Husted Directory Co.	Image pg. A174
	Camou Mrs Margaret	Polk-Husted Directory Co.	Image pg. A174

419 SONORA E

Year	Uses	Source	
2003	Huang Yong	SBC PACIFIC BELL	
1960	Siefken Marvin	R. L. Polk Co., Publishers	Image pg. A88
1955	Utter Thos C	R. L. Polk Co.	Image pg. A98
1946	A Horton Ray	R. L. Polk Co., Publishers	Image pg. A113
1935	Houseman Evelyn Mrs	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Winkleman A B	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Capps S Homer	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Ten Brook Robt	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Miller C F	Polk-Husted Directory Co.	Image pg. A174

421 SONORA E

Year	Uses	Source	
2003	Wong Hing Chuck	SBC PACIFIC BELL	
1960	Wong Sheow Young	R. L. Polk Co., Publishers	Image pg. A88
1955	Mc Crimmon Danl C	R. L. Polk Co.	Image pg. A98
1950	A Mc Crimmon Danl	R. L. Polk Co., Publishers	Image pg. A106
1946	A Dieterich A F	R. L. Polk Co., Publishers	Image pg. A113

Year	Uses	Source	
1935	Garciacelay Damasa	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Mc Crimmon D C o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Mc Crimmon D C	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Mc Crimmon D C	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Reitz F E	Polk-Husted Directory Co.	Image pg. A174

422 SONORA E

Year	Uses	Source	
1960	Wong Doon G	R. L. Polk Co., Publishers	Image pg. A88
1955	Wong Stanley Y	R. L. Polk Co.	Image pg. A98
1950	A Wong T D	R. L. Polk Co., Publishers	Image pg. A106
1946	Wong T D	R. L. Polk Co., Publishers	Image pg. A113
1935	Sherfey J E	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Stauffer B L o	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Stauffer B L	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Stauffer B L	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Stauffer B L	Polk-Husted Directory Co.	Image pg. A174

427 SONORA E

Year	Uses	Source	
1950	Yoachum Francis	R. L. Polk Co., Publishers	Image pg. A106
	Mc Manus Mary E	R. L. Polk Co., Publishers	Image pg. A106
1946	Mc Manus Margt E	R. L. Polk Co., Publishers	Image pg. A113
1935	Mc Manus Margt E	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Mc Manus Margt E	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Mc Manus W P	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Mc Manus J A	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Mc Manus J A	Polk-Husted Directory Co.	Image pg. A174

428 SONORA E

Year	Uses	Source	
1960	Apartments	R. L. Polk Co., Publishers	Image pg. A88
	Mah Teddy G	R. L. Polk Co., Publishers	Image pg. A88
	Vacant	R. L. Polk Co., Publishers	Image pg. A88

FINDINGS

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A88
	Goldsmith Juanita Mrs	R. L. Polk Co., Publishers	Image pg. A88
	Mah Eddie	R. L. Polk Co., Publishers	Image pg. A88
	Fook Chan	R. L. Polk Co., Publishers	Image pg. A88
	Chin Henry	R. L. Polk Co., Publishers	Image pg. A88
	Jew Douglas	R. L. Polk Co., Publishers	Image pg. A88
	Wong Jas K	R. L. Polk Co., Publishers	Image pg. A88
	Lim Jin G	R. L. Polk Co., Publishers	Image pg. A88
	Street continued	R. L. Polk Co., Publishers	Image pg. A88
1955	Apartments	R. L. Polk Co.	Image pg. A98
	Vacant	R. L. Polk Co.	Image pg. A98
	Vacant	R. L. Polk Co.	Image pg. A98
	Flores Margt Mrs	R. L. Polk Co.	Image pg. A98
	Jarman Albert	R. L. Polk Co.	Image pg. A98
	Mah Eddy	R. L. Polk Co.	Image pg. A98
	Yee Kenneth	R. L. Polk Co.	Image pg. A98
	Vacant	R. L. Polk Co.	Image pg. A98
	Lee Kw ong Lim	R. L. Polk Co.	Image pg. A98
	Vacant	R. L. Polk Co.	Image pg. A98
	Vacant	R. L. Polk Co.	Image pg. A98
	Street continued	R. L. Polk Co.	Image pg. A98
1950	Bucaling Justin	R. L. Polk Co., Publishers	Image pg. A106
	Crabbe Wm	R. L. Polk Co., Publishers	Image pg. A106
	King Herbt	R. L. Polk Co., Publishers	Image pg. A106
	Massoni Frank	R. L. Polk Co., Publishers	Image pg. A106
	Muller Lenna Mrs	R. L. Polk Co., Publishers	Image pg. A106
	Woods Frances Mrs	R. L. Polk Co., Publishers	Image pg. A106
1946	Barnett Estell	R. L. Polk Co., Publishers	Image pg. A113
	Bucaling Justin	R. L. Polk Co., Publishers	Image pg. A113
	King Herbt	R. L. Polk Co., Publishers	Image pg. A113
1935	Criss Geo	R. L. Polk Co. of California, Publishers	Image pg. A131
	Licht Edw	R. L. Polk Co. of California, Publishers	Image pg. A131

FINDINGS

Year	Uses	Source	
1935	Meneley J B o	R. L. Polk Co. of California, Publishers	Image pg. A131
	Penrod Florence Mrs	R. L. Polk Co. of California, Publishers	Image pg. A131
	Staiger H A	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Meneley J B o	R. L. Polk Co. of California, Publishers	Image pg. A144
	Staiger H A	R. L. Polk Co. of California, Publishers	Image pg. A144
	Fletcher Mina Mrs	R. L. Polk Co. of California, Publishers	Image pg. A144
	Jackson J E	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Brammer D H	R. L. Polk Co. of California, Publishers	Image pg. A154
	Fletcher Mrs Mina	R. L. Polk Co. of California, Publishers	Image pg. A154
	Hitt Mrs H C	R. L. Polk Co. of California, Publishers	Image pg. A154
	Kostas Thos	R. L. Polk Co. of California, Publishers	Image pg. A154
	Stafford Fred	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Gardrer C H	Polk-Husted Directory Co., Publishers	Image pg. A164
	Higdon Alonzo	Polk-Husted Directory Co., Publishers	Image pg. A164
	Hill Mrs S E	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Castle Thos	Polk-Husted Directory Co.	Image pg. A174

432 SONORA E

Year	Uses	Source	
1960	Reynolds Fredk A	R. L. Polk Co., Publishers	Image pg. A88
1955	Reynolds Frank A 0	R. L. Polk Co.	Image pg. A98
1950	AReynolds F A	R. L. Polk Co., Publishers	Image pg. A106
1946	LReynolds F A	R. L. Polk Co., Publishers	Image pg. A113
1935	Reynolds F A	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Reynolds F A	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Heckart J C	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Ingram J R	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Coleman F W	Polk-Husted Directory Co.	Image pg. A174

434 SONORA E

Year	Uses	Source	
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A113
1935	Castile D F	R. L. Polk Co. of California, Publishers	Image pg. A131

FINDINGS

436 SONORA E

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A88
1955	Vacant	R. L. Polk Co.	Image pg. A98
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106
1946	Lovelady Christine Mrs	R. L. Polk Co., Publishers	Image pg. A113
1935	Woolery F E	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Smith R D	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Berglund E	R. L. Polk Co. of California, Publishers	Image pg. A154
	Berglund Oscar	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Pease C C	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Pease C C	Polk-Husted Directory Co.	Image pg. A174

437 SONORA E

Year	Uses	Source	
1930	Cordoza Nicholas	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Marino Frank	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Roche Mrs A D	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Filler R W	Polk-Husted Directory Co.	Image pg. A174

438 SONORA E

Year	Uses	Source	
1960	Buis Andrew	R. L. Polk Co., Publishers	Image pg. A88
1955	Bradbury Josie Mrs	R. L. Polk Co.	Image pg. A98
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106
1946	A Reeves J	R. L. Polk Co., Publishers	Image pg. A113
1935	Paydon W R	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Bishop H E	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Hawk Mrs Grace	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Boydston G K	Polk-Husted Directory Co., Publishers	Image pg. A164

440 SONORA E

Year	Uses	Source	
1960	Yarbrough Arlie	R. L. Polk Co., Publishers	Image pg. A88
1955	Reasoner Raymond	R. L. Polk Co.	Image pg. A98

Year	Uses	Source	
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A106
1946	Loveland W A	R. L. Polk Co., Publishers	Image pg. A113
1935	Holman R A	R. L. Polk Co. of California, Publishers	Image pg. A131
1930	Guyman Neil	R. L. Polk Co. of California, Publishers	Image pg. A144
1925	Hayes V W	R. L. Polk Co. of California, Publishers	Image pg. A154
1921	Greenfield R R	Polk-Husted Directory Co., Publishers	Image pg. A164
1916	Von Burgen E H	Polk-Husted Directory Co.	Image pg. A174
	Rymer R S	Polk-Husted Directory Co.	Image pg. A174

443 SONORA E

Year	Uses	Source
2003	Brown Bobby	SBC PACIFIC BELL
	Fajardo Luciano	SBC PACIFIC BELL
	Lockett Yvonne	SBC PACIFIC BELL
	Hoffman Raymond	SBC PACIFIC BELL
	Jones Robert L	SBC PACIFIC BELL
	Mixon Robert	SBC PACIFIC BELL
	Clapp Kenneth	SBC PACIFIC BELL
	Westbrook Andrea	SBC PACIFIC BELL
	Florence Branda	SBC PACIFIC BELL
	FILIPINO COMMUNITY BUILDING	SBC PACIFIC BELL
	Wu Alex	SBC PACIFIC BELL

444 SONORA E

Year	Uses	Source	
1930	Brokaw J C	R. L. Polk Co. of California, Publishers	Image pg. A144

SONORA ST E

125 SONORA ST E

Year	Uses	Source	
1984	Advancula Mariano	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79
	VACANT	R. L. Polk Co., Publishers	Image pg. A79

FINDINGS

127 SONORA ST E

Year	Uses	Source	
1965	MAH SONNY	R. L. Polk Co., Publishers	Image pg. A79

128 SONORA ST E

Year	Uses	Source	
1984	Iloilo Circle Club Inc The social	R. L. Polk Co., Publishers	Image pg. A32
1965	SOCIAL CLUB H	R. L. Polk Co., Publishers	Image pg. A79
	ILOILO CIRCLE CLUB INC THE	R. L. Polk Co., Publishers	Image pg. A79

131 SONORA ST E

Year	Uses	Source	
1965	GREGORIO DANL L	R. L. Polk Co., Publishers	Image pg. A79

134 SONORA ST E

Year	Uses	Source	
1984	Wong Joy	R. L. Polk Co., Publishers	Image pg. A32
1965	WONG KI 1 H	R. L. Polk Co., Publishers	Image pg. A79

136 SONORA ST E

Year	Uses	Source	
1984	Estante Diomedes A	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

138 SONORA ST E

Year	Uses	Source	
1984	Chan Kw ock	R. L. Polk Co., Publishers	Image pg. A32
1965	CHING FAI	R. L. Polk Co., Publishers	Image pg. A79

204 SONORA ST E

Year	Uses	Source	
1984	Regidor Lodge No 5 C D A Inc	R. L. Polk Co., Publishers	Image pg. A32
1965	INC LODGE	R. L. Polk Co., Publishers	Image pg. A79
	REGIDOR LODGE NO 5 CDA	R. L. Polk Co., Publishers	Image pg. A79

209 SONORA ST E

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

FINDINGS

218 SONORA ST E

Year	Uses	Source	
1984	Hoy Wah Kue	R. L. Polk Co., Publishers	Image pg. A32
1965	HOY WAH KUE S	R. L. Polk Co., Publishers	Image pg. A79

221 SONORA ST E

Year	Uses	Source	
1984	Acoba Juanito	R. L. Polk Co., Publishers	Image pg. A32
	Reyes Y	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79
	LANE HARRY J H	R. L. Polk Co., Publishers	Image pg. A79

223 SONORA ST E

Year	Uses	Source	
1984	Gallera Faustino J	R. L. Polk Co., Publishers	Image pg. A32
	Lorenzo	R. L. Polk Co., Publishers	Image pg. A32
1965	ASUNCION SALVADOR	R. L. Polk Co., Publishers	Image pg. A79
	ALQUINALDO MARIANO D	R. L. Polk Co., Publishers	Image pg. A79

224 SONORA ST E

Year	Uses	Source	
1984	Lime I	R. L. Polk Co., Publishers	Image pg. A32
1965	RAMOLETE MEL H	R. L. Polk Co., Publishers	Image pg. A79

225 SONORA ST E

Year	Uses	Source	
1984	Alcantra Severo	R. L. Polk Co., Publishers	Image pg. A32
	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	FLORES LEN	R. L. Polk Co., Publishers	Image pg. A79
	VACANT	R. L. Polk Co., Publishers	Image pg. A79

226 SONORA ST E

Year	Uses	Source	
1984	Callejo Tony	R. L. Polk Co., Publishers	Image pg. A32
1965	WOO HING JUNG H	R. L. Polk Co., Publishers	Image pg. A79

FINDINGS

227 SONORA ST E

Year	Uses	Source	
1984	b Abrenica Isabe	R. L. Polk Co., Publishers	Image pg. A32
	a Hicali Danny	R. L. Polk Co., Publishers	Image pg. A32
1965	TOY QUONG J H	R. L. Polk Co., Publishers	Image pg. A79
	ENG FUNG H	R. L. Polk Co., Publishers	Image pg. A79
	WONG WING GONG	R. L. Polk Co., Publishers	Image pg. A79

229 SONORA ST E

Year	Uses	Source	
1984	Wilson Ted J	R. L. Polk Co., Publishers	Image pg. A32
	Bottley Willie	R. L. Polk Co., Publishers	Image pg. A32
1965	MAR WONG SHEE MRS H	R. L. Polk Co., Publishers	Image pg. A79

231 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	TOY YOU SUN	R. L. Polk Co., Publishers	Image pg. A79

232 SONORA ST E

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

233 SONORA ST E

Year	Uses	Source	
1965	WONG HONG MRS	R. L. Polk Co., Publishers	Image pg. A79

235 SONORA ST E

Year	Uses	Source	
1965	CRUZ JACK L	R. L. Polk Co., Publishers	Image pg. A79

237 SONORA ST E

Year	Uses	Source	
1965	NO RETURN	R. L. Polk Co., Publishers	Image pg. A79

309 SONORA ST E

Year	Uses	Source	
1984	Louie Wm	R. L. Polk Co., Publishers	Image pg. A32

Year	Uses	Source	
1965	LOUIE CHEW 0 H	R. L. Polk Co., Publishers	Image pg. A79

310 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	RALA DORA A MRS	R. L. Polk Co., Publishers	Image pg. A79

312 SONORA ST E

Year	Uses	Source	
1965	SORENSON MARY E MRS	R. L. Polk Co., Publishers	Image pg. A79

314 SONORA ST E

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

315 SONORA ST E

Year	Uses	Source	
1984	Jaka Mak	R. L. Polk Co., Publishers	Image pg. A32
1965	LEE SEE PING	R. L. Polk Co., Publishers	Image pg. A79

316 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

317 SONORA ST E

Year	Uses	Source	
1984	Fong Robin	R. L. Polk Co., Publishers	Image pg. A32
1965	GOW TOY WONG 0 H	R. L. Polk Co., Publishers	Image pg. A79

319 SONORA ST E

Year	Uses	Source	
1984	Yip Kw ong Ying	R. L. Polk Co., Publishers	Image pg. A32
1965	WONG CHUCK H	R. L. Polk Co., Publishers	Image pg. A79

FINDINGS

321 SONORA ST E

Year	Uses	Source	
1984	Ng Sze Yau	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

322 SONORA ST E

Year	Uses	Source	
1984	Tsoo Kwok	R. L. Polk Co., Publishers	Image pg. A32
1965	JOMAOAS BART T H	R. L. Polk Co., Publishers	Image pg. A79

327 SONORA ST E

Year	Uses	Source	
1965	WOON SAT	R. L. Polk Co., Publishers	Image pg. A79

328 SONORA ST E

Year	Uses	Source	
1984	Yee Darryl Hong Ying	R. L. Polk Co., Publishers	Image pg. A32

330 SONORA ST E

Year	Uses	Source	
1984	Lampitok Catalino	R. L. Polk Co., Publishers	Image pg. A32

332 SONORA ST E

Year	Uses	Source	
1984	Tse Jason	R. L. Polk Co., Publishers	Image pg. A32

336 SONORA ST E

Year	Uses	Source	
1984	Efsarim	R. L. Polk Co., Publishers	Image pg. A32
1965	NG GUEY FAN H	R. L. Polk Co., Publishers	Image pg. A79

344 SONORA ST E

Year	Uses	Source	
1965	WONG LEE SHEE MRS	R. L. Polk Co., Publishers	Image pg. A79

346 SONORA ST E

Year	Uses	Source	
1984	Kwaifun Hochin Wong	R. L. Polk Co., Publishers	Image pg. A32

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A79

348 SONORA ST E

Year	Uses	Source	
1984	Wong Fook Sing	R. L. Polk Co., Publishers	Image pg. A32
1965	NO RETURN	R. L. Polk Co., Publishers	Image pg. A79

416 SONORA ST E

Year	Uses	Source	
1984	Phillips Perry	R. L. Polk Co., Publishers	Image pg. A32
1965	LA VERGNE SADIE MRS	R. L. Polk Co., Publishers	Image pg. A79

418 SONORA ST E

Year	Uses	Source	
1984	Ong Ying	R. L. Polk Co., Publishers	Image pg. A32
1965	HOFFMAN DORIS 4 MRS	R. L. Polk Co., Publishers	Image pg. A79

419 SONORA ST E

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A32
1965	SIEFKEN MARVIN	R. L. Polk Co., Publishers	Image pg. A79

421 SONORA ST E

Year	Uses	Source	
1984	Yip Bing B	R. L. Polk Co., Publishers	Image pg. A32
1965	WONG SHEOW Y 0 J	R. L. Polk Co., Publishers	Image pg. A79

422 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	WONG DOON G 0 H	R. L. Polk Co., Publishers	Image pg. A79

427 SONORA ST E

Year	Uses	Source	
1984	Housing Auth Of San Joaquin County Purch Agt	R. L. Polk Co., Publishers	Image pg. A32
1965	NICOLELLI M & SONS UNIFORM	R. L. Polk Co., Publishers	Image pg. A79

FINDINGS

Year	Uses	Source	
1965	MFRS H	R. L. Polk Co., Publishers	Image pg. A79

428 SONORA ST E

Year	Uses	Source	
1984	Leung Jimmy	R. L. Polk Co., Publishers	Image pg. A32
	Apartments	R. L. Polk Co., Publishers	Image pg. A32
	Vacant	R. L. Polk Co., Publishers	Image pg. A32
	Mah Teddy G	R. L. Polk Co., Publishers	Image pg. A32
	Quong Thanh	R. L. Polk Co., Publishers	Image pg. A32
	Mah Mei Lin	R. L. Polk Co., Publishers	Image pg. A32
	Crespino Jose	R. L. Polk Co., Publishers	Image pg. A32
	Fronda Nemesio	R. L. Polk Co., Publishers	Image pg. A32
	Leung Chow Fung	R. L. Polk Co., Publishers	Image pg. A32
1965	LEE LIN	R. L. Polk Co., Publishers	Image pg. A79
	APARTMENTS	R. L. Polk Co., Publishers	Image pg. A79
	MAH T G	R. L. Polk Co., Publishers	Image pg. A79
	CHAU KING	R. L. Polk Co., Publishers	Image pg. A79
	WONG JALL	R. L. Polk Co., Publishers	Image pg. A79
	CHIN DAVE	R. L. Polk Co., Publishers	Image pg. A79
	SONORA ST EAST CONTO	R. L. Polk Co., Publishers	Image pg. A80
	MARS T	R. L. Polk Co., Publishers	Image pg. A80
	TOY WM	R. L. Polk Co., Publishers	Image pg. A80
	VACANT	R. L. Polk Co., Publishers	Image pg. A80
	STREET CONTINUED	R. L. Polk Co., Publishers	Image pg. A80
	MEH EDDY H	R. L. Polk Co., Publishers	Image pg. A79

432 SONORA ST E

Year	Uses	Source	
1984	Reynolds Henry A	R. L. Polk Co., Publishers	Image pg. A32
1965	REYNOLDS FREDK A	R. L. Polk Co., Publishers	Image pg. A80

436 SONORA ST E

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A32

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A80

438 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A80

440 SONORA ST E

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A32
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A80

443 SONORA ST E

Year	Uses	Source	
1984	Nenas Filipino Restaurant	R. L. Polk Co., Publishers	Image pg. A32

SUTIER ST S

306 SUTIER ST S

Year	Uses	Source	
1979	Rudys Fire & Security	R.L. Polk CO.	Image pg. A56

315 SUTIER ST S

Year	Uses	Source	
1979	Warner Gale	R.L. Polk CO.	Image pg. A56
	Jones Marcell	R.L. Polk CO.	Image pg. A56
	Magana Antonio	R.L. Polk CO.	Image pg. A56
	Alexander James	R.L. Polk CO.	Image pg. A56
	Thompson	R.L. Polk CO.	Image pg. A56
	Austin John	R.L. Polk CO.	Image pg. A56
	White Gars	R.L. Polk CO.	Image pg. A56
	Louis Apartments	R.L. Polk CO.	Image pg. A56
	Alverez Lidia	R.L. Polk CO.	Image pg. A56

333 SUTIER ST S

Year	Uses	Source	
1979	On Lock Sam restr	R.L. Polk CO.	Image pg. A56

FINDINGS

344 SUTIER ST S

Year	Uses	Source	
1979	Wong Lee S	R.L. Polk CO.	Image pg. A56
	Wong Kin	R.L. Polk CO.	Image pg. A56

406 SUTIER ST S

Year	Uses	Source	
1979	Apartments I Elias Narcisco	R.L. Polk CO.	Image pg. A56
	Calderon R	R.L. Polk CO.	Image pg. A56
	Elias Narciso	R.L. Polk CO.	Image pg. A56
	Castello Roberto	R.L. Polk CO.	Image pg. A56
	Avalos Marshall	R.L. Polk CO.	Image pg. A56
	Hemandez Frank	R.L. Polk CO.	Image pg. A56

415 SUTIER ST S

Year	Uses	Source	
1979	Yip Boelog	R.L. Polk CO.	Image pg. A56

421 SUTIER ST S

Year	Uses	Source	
1979	Vacant	R.L. Polk CO.	Image pg. A56

422 SUTIER ST S

Year	Uses	Source	
1979	Yip Gan Chick	R.L. Polk CO.	Image pg. A56

423 SUTIER ST S

Year	Uses	Source	
1979	Caluza Joe	R.L. Polk CO.	Image pg. A56

424 SUTIER ST S

Year	Uses	Source	
1979	a Selga Alipio	R.L. Polk CO.	Image pg. A56
	Gutierrez 01 Cruzin	R.L. Polk CO.	Image pg. A56

425 SUTIER ST S

Year	Uses	Source	
1979	Magana Pedro	R.L. Polk CO.	Image pg. A56

FINDINGS

426 SUTIER ST S

Year	Uses	Source	
1979	Vacant	R.L. Polk CO.	Image pg. A56

427 SUTIER ST S

Year	Uses	Source	
1979	Tejamo Ernesto	R.L. Polk CO.	Image pg. A56

428 SUTIER ST S

Year	Uses	Source	
1979	Wong Chew Hep	R.L. Polk CO.	Image pg. A56

429 SUTIER ST S

Year	Uses	Source	
1979	Martin Tony	R.L. Polk CO.	Image pg. A56

430 SUTIER ST S

Year	Uses	Source	
1979	Tam Chun Wah	R.L. Polk CO.	Image pg. A56

431 SUTIER ST S

Year	Uses	Source	
1979	Gonzales Alicia	R.L. Polk CO.	Image pg. A56

435 SUTIER ST S

Year	Uses	Source	
1979	Ivory Louise Mrs	R.L. Polk CO.	Image pg. A56

438 SUTIER ST S

Year	Uses	Source	
1979	Cantele Louise L Mrs	R.L. Polk CO.	Image pg. A56

440 SUTIER ST S

Year	Uses	Source	
1979	Buckeye Appliances & Furniture	R.L. Polk CO.	Image pg. A56

442 SUTIER ST S

Year	Uses	Source	
1979	Hemandez Gregory	R.L. Polk CO.	Image pg. A56

FINDINGS

510 SUTIER ST S

Year	Uses	Source	
1979	Fong Gew Ngoy	R.L. Polk CO.	Image pg. A56

518 SUTIER ST S

Year	Uses	Source	
1979	Molina Julian	R.L. Polk CO.	Image pg. A56

521 SUTIER ST S

Year	Uses	Source	
1979	Brow n K	R.L. Polk CO.	Image pg. A56
	Henderson Lorene	R.L. Polk CO.	Image pg. A56
	Miles Jeanette	R.L. Polk CO.	Image pg. A56
	Grider Opel	R.L. Polk CO.	Image pg. A56
	Apartments	R.L. Polk CO.	Image pg. A56

522 SUTIER ST S

Year	Uses	Source	
1979	Escobedo Guadalupe	R.L. Polk CO.	Image pg. A56

524 SUTIER ST S

Year	Uses	Source	
1979	Martinez Mercedes Mrs	R.L. Polk CO.	Image pg. A56

527 SUTIER ST S

Year	Uses	Source	
1979	Monk Thos G	R.L. Polk CO.	Image pg. A56
	Apartments lBanales C	R.L. Polk CO.	Image pg. A56
	Vacant	R.L. Polk CO.	Image pg. A56
	Lovelace Norma	R.L. Polk CO.	Image pg. A56

528 SUTIER ST S

Year	Uses	Source	
1979	Martinez Josephine Mrs	R.L. Polk CO.	Image pg. A56

530 SUTIER ST S

Year	Uses	Source	
1979	Rivera Lilly	R.L. Polk CO.	Image pg. A56

FINDINGS

541 SUTIER ST S

Year	Uses	Source	
1979	lc Vacant	R.L. Polk CO.	Image pg. A56
	d Harris Charles	R.L. Polk CO.	Image pg. A56
	b Sanders Ralph	R.L. Polk CO.	Image pg. A56
	a Pinkard Montel	R.L. Polk CO.	Image pg. A56

543 SUTIER ST S

Year	Uses	Source	
1979	c Mc Greg Simon F	R.L. Polk CO.	Image pg. A56
	bLeal Silvia	R.L. Polk CO.	Image pg. A56
	a Smith Roosevelt	R.L. Polk CO.	Image pg. A56
	d Gaines Robt	R.L. Polk CO.	Image pg. A56

545 SUTIER ST S

Year	Uses	Source	
1979	bSullivan John	R.L. Polk CO.	Image pg. A56
	cWildly Earnest	R.L. Polk CO.	Image pg. A56
	aLopez Soledad	R.L. Polk CO.	Image pg. A56

SUTTER S

301 SUTTER S

Year	Uses	Source	
1946	Marizold The liquors	R. L. Polk Co., Publishers	Image pg. A114
1930	Hannan E G Mrs gro	R. L. Polk Co. of California, Publishers	Image pg. A145
1921	Kennedy J B	Polk-Husted Directory Co., Publishers	Image pg. A165

306 SUTTER S

Year	Uses	Source	
1960	Moores Flying A Serv	R. L. Polk Co., Publishers	Image pg. A89
1955	Nichols Norw alk Serv	R. L. Polk Co.	Image pg. A99

310 SUTTER S

Year	Uses	Source	
1916	Garofalo Jos	Polk-Husted Directory Co.	Image pg. A175

FINDINGS

311 SUTTER S

Year	Uses	Source	
1935	Tucker N M Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A132

313 SUTTER S

Year	Uses	Source	
1921	Prenosier Frank	Polk-Husted Directory Co., Publishers	Image pg. A165
	Pena Jos	Polk-Husted Directory Co., Publishers	Image pg. A165

314 SUTTER S

Year	Uses	Source	
1960	Louis Apartments	R. L. Polk Co., Publishers	Image pg. A89
	Tagonon Petronillo	R. L. Polk Co., Publishers	Image pg. A89
	Bray Rebecca Mrs	R. L. Polk Co., Publishers	Image pg. A89
	Inastri Ludvico	R. L. Polk Co., Publishers	Image pg. A89
	Carlotte Angelo	R. L. Polk Co., Publishers	Image pg. A89
	Jarosz Arnold	R. L. Polk Co., Publishers	Image pg. A89
	King Gerry	R. L. Polk Co., Publishers	Image pg. A89
	Yturaldi Jennie	R. L. Polk Co., Publishers	Image pg. A89
	Ward Geo W	R. L. Polk Co., Publishers	Image pg. A89
	Street continued	R. L. Polk Co., Publishers	Image pg. A89

315 SUTTER S

Year	Uses	Source	
2003	Romero Urbano	SBC PACIFIC BELL	
	Lopez Alfonso	SBC PACIFIC BELL	
	Hernandez Huosdeli	SBC PACIFIC BELL	
	Hernandez Jose	SBC PACIFIC BELL	
1955	Stret continued	R. L. Polk Co.	Image pg. A99
	Ward Geo W	R. L. Polk Co.	Image pg. A99
	Vacant	R. L. Polk Co.	Image pg. A99
	Ozzolino Nick	R. L. Polk Co.	Image pg. A99
	Sanhez Manvel L	R. L. Polk Co.	Image pg. A99
	Carlotta Angelo	R. L. Polk Co.	Image pg. A99
	Kimball Fred	R. L. Polk Co.	Image pg. A99

FINDINGS

Year	Uses	Source	
1955	Ford Mace H	R. L. Polk Co.	Image pg. A99
	Barker G L	R. L. Polk Co.	Image pg. A99
	Louis Apartments	R. L. Polk Co.	Image pg. A99
1950	Marciasini Umberto	R. L. Polk Co., Publishers	Image pg. A107
	Nigris Nick	R. L. Polk Co., Publishers	Image pg. A107
	Pilkington L C	R. L. Polk Co., Publishers	Image pg. A107
	Angelini Apartments	R. L. Polk Co., Publishers	Image pg. A107
	Grasso Tony	R. L. Polk Co., Publishers	Image pg. A107
	Hurd Owen	R. L. Polk Co., Publishers	Image pg. A107
	Langton G A	R. L. Polk Co., Publishers	Image pg. A107
1946	Angelini Apartments	R. L. Polk Co., Publishers	Image pg. A114
	Crowe G A Mrs	R. L. Polk Co., Publishers	Image pg. A114
	Dutra G L	R. L. Polk Co., Publishers	Image pg. A114
	Hill B F	R. L. Polk Co., Publishers	Image pg. A114
	Ineram A J	R. L. Polk Co., Publishers	Image pg. A114
	Langton G A	R. L. Polk Co., Publishers	Image pg. A114
	Patterson E W	R. L. Polk Co., Publishers	Image pg. A114
	Pilkington L D	R. L. Polk Co., Publishers	Image pg. A114
1930	Gardella Apartments	R. L. Polk Co. of California, Publishers	Image pg. A145
	Bradshaw Irma Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
	Henne Alma	R. L. Polk Co. of California, Publishers	Image pg. A145
	Jonas Neoma	R. L. Polk Co. of California, Publishers	Image pg. A145
	Mello Jos	R. L. Polk Co. of California, Publishers	Image pg. A145
	Oldfield B C	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Faulkner Mrs Georgie	R. L. Polk Co. of California, Publishers	Image pg. A155
	Faulkner Thos	R. L. Polk Co. of California, Publishers	Image pg. A155
	Mc Carthy F J	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Collins J C	Polk-Husted Directory Co., Publishers	Image pg. A165

317 SUTTER S

Year	Uses	Source	
1921	Hunter Mrs M C	Polk-Husted Directory Co., Publishers	Image pg. A165
	Kasprovitz Michael	Polk-Husted Directory Co., Publishers	Image pg. A165

FINDINGS

Year	Uses	Source	
1916	Smith Wm	Polk-Husted Directory Co.	Image pg. A175

319 SUTTER S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Davis E A Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Wiser M A	R. L. Polk Co. of California, Publishers	Image pg. A155
	Davis E A	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Osborne H M	Polk-Husted Directory Co., Publishers	Image pg. A165
	Huston Wilbert	Polk-Husted Directory Co., Publishers	Image pg. A165
	Fitchie S B	Polk-Husted Directory Co., Publishers	Image pg. A165
	Davis Mrs E A	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Gianelli R J	Polk-Husted Directory Co.	Image pg. A175
	Fitchie S B	Polk-Husted Directory Co.	Image pg. A175
	Davis Elizabeth A wid	Polk-Husted Directory Co.	Image pg. A175

320 SUTTER S

Year	Uses	Source	
1955	Garibotto Theresa C Mrs	R. L. Polk Co.	Image pg. A99
1950	AGaribotto T C Mrs	R. L. Polk Co., Publishers	Image pg. A107
1946	Garibotto T C Mrs	R. L. Polk Co., Publishers	Image pg. A114
1930	Garibotto G B o	R. L. Polk Co. of California, Publishers	Image pg. A145
1921	Garibotto G B	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Garibotto G B	Polk-Husted Directory Co.	Image pg. A175

321 SUTTER S

Year	Uses	Source	
1950	Morgan Larry	R. L. Polk Co., Publishers	Image pg. A107
1946	Harper E F	R. L. Polk Co., Publishers	Image pg. A114
1930	Parker C S	R. L. Polk Co. of California, Publishers	Image pg. A145

326 SUTTER S

Year	Uses	Source	
1960	Huerta Ventura P	R. L. Polk Co., Publishers	Image pg. A89

FINDINGS

327 SUTTER S

Year	Uses	Source	
1955	Wong How ard H	R. L. Polk Co.	Image pg. A99
1950	Wong H H	R. L. Polk Co., Publishers	Image pg. A107
1946	APierce JC	R. L. Polk Co., Publishers	Image pg. A114

328 SUTTER S

Year	Uses	Source	
1960	Rodarti Brigido	R. L. Polk Co., Publishers	Image pg. A89
1955	Chavez Alf B	R. L. Polk Co.	Image pg. A99
1950	AChavez A B	R. L. Polk Co., Publishers	Image pg. A107
1946	Cueva Jose	R. L. Polk Co., Publishers	Image pg. A114
	Chavez A B	R. L. Polk Co., Publishers	Image pg. A114
1930	iMinnie Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
	Jumes Wm	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Adkins J C	Polk-Husted Directory Co., Publishers	Image pg. A165
	Heard Albert	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Bacheller R M	Polk-Husted Directory Co.	Image pg. A175

329 SUTTER S

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A99
1950	Loui J H	R. L. Polk Co., Publishers	Image pg. A107
1946	Wong Ella Mrs	R. L. Polk Co., Publishers	Image pg. A114
1930	Lindsay MAlabel Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Lindsay Mrs Mabel	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Gall J M	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Gall J M	Polk-Husted Directory Co.	Image pg. A175

333 SUTTER S

Year	Uses	Source
2003	ON LOCK SAM RESTAURANT	SBC PACIFIC BELL

FINDINGS

336 SUTTER S

Year	Uses	Source	
1960	Lee John W	R. L. Polk Co., Publishers	Image pg. A89
1955	Chan Yoke W	R. L. Polk Co.	Image pg. A99
1950	AChoy W Y Rev	R. L. Polk Co., Publishers	Image pg. A107
1946	Choy Wilbur Rev	R. L. Polk Co., Publishers	Image pg. A114
1930	Rickman M L Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Miller Katherine	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Kingsbury Mrs M A	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Kingsbury M Alice w id	Polk-Husted Directory Co.	Image pg. A175

341 SUTTER S

Year	Uses	Source	
1955	Street continued	R. L. Polk Co.	Image pg. A99
	Vacant	R. L. Polk Co.	Image pg. A99
	Chun Sai	R. L. Polk Co.	Image pg. A99
	Look Tai Food	R. L. Polk Co.	Image pg. A99
	Anzolene Joseph	R. L. Polk Co.	Image pg. A99
	Harden Ferrill L Mrs	R. L. Polk Co.	Image pg. A99
	Wong Doon G	R. L. Polk Co.	Image pg. A99
	Apartments	R. L. Polk Co.	Image pg. A99
1950	AAlberdi J A	R. L. Polk Co., Publishers	Image pg. A107
	Anzalone Jos	R. L. Polk Co., Publishers	Image pg. A107
	Epp Bartholomew	R. L. Polk Co., Publishers	Image pg. A107
	Wong D G	R. L. Polk Co., Publishers	Image pg. A107
	Wong M L	R. L. Polk Co., Publishers	Image pg. A107
1946	Anzalone Jos	R. L. Polk Co., Publishers	Image pg. A114
	Harris D E	R. L. Polk Co., Publishers	Image pg. A114
	Harris Glen Mrs	R. L. Polk Co., Publishers	Image pg. A114
1935	c Wichbman B Y	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Baerlocher Orlando	R. L. Polk Co. of California, Publishers	Image pg. A145
	real est	R. L. Polk Co. of California, Publishers	Image pg. A145
	Tucker R M	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Hunter Ted	R. L. Polk Co. of California, Publishers	Image pg. A155

Year	Uses	Source	
1925	Tucker R M	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Haroldson Harry	Polk-Husted Directory Co., Publishers	Image pg. A165
	Patterson Marguerite	Polk-Husted Directory Co., Publishers	Image pg. A165

344 SUTTER S

Year	Uses	Source	
1960	Wong Sai Yee	R. L. Polk Co., Publishers	Image pg. A89
	Wong Kuo Tang	R. L. Polk Co., Publishers	Image pg. A89
1955	Wong Sai Y	R. L. Polk Co.	Image pg. A99
1950	Wong S Y	R. L. Polk Co., Publishers	Image pg. A107
	Gong T Foo	R. L. Polk Co., Publishers	Image pg. A107
1946	Young Jack	R. L. Polk Co., Publishers	Image pg. A114
1935	Jacobs N A	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Revis Anna baths	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Moore Mrs Coritza	R. L. Polk Co. of California, Publishers	Image pg. A155
	Metz Chas	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Ladd J S	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Orr M H	Polk-Husted Directory Co.	Image pg. A175
	Gage Amanda S w id	Polk-Husted Directory Co.	Image pg. A175

406 SUTTER S

Year	Uses	Source	
1960	Lay Huey	R. L. Polk Co., Publishers	Image pg. A89
1955	Ng Danny	R. L. Polk Co.	Image pg. A99
1950	Huey Tung	R. L. Polk Co., Publishers	Image pg. A107
1946	Belleville J A	R. L. Polk Co., Publishers	Image pg. A114
	Eng Harry	R. L. Polk Co., Publishers	Image pg. A114
1935	Garvey J M o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Garvey J M	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Fuson Mrs Hazel	R. L. Polk Co. of California, Publishers	Image pg. A155
	Garvey Mrs Mary	R. L. Polk Co. of California, Publishers	Image pg. A155
	Campbell W L	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Bernal Danl	Polk-Husted Directory Co., Publishers	Image pg. A165
	Garvey Mary	Polk-Husted Directory Co., Publishers	Image pg. A165

FINDINGS

Year	Uses	Source	
1916	Davey Thos	Polk-Husted Directory Co.	Image pg. A175
	Garvey J M	Polk-Husted Directory Co.	Image pg. A175
	Keyes John	Polk-Husted Directory Co.	Image pg. A175
	Wilson Edw	Polk-Husted Directory Co.	Image pg. A175

409 SUTTER S

Year	Uses	Source	
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A155

413 SUTTER S

Year	Uses	Source	
1935	Stockwell E C	R. L. Polk Co. of California, Publishers	Image pg. A132

415 SUTTER S

Year	Uses	Source	
2003	Vidal Callejas Clemente	SBC PACIFIC BELL	
1960	Lue Ah Sing	R. L. Polk Co., Publishers	Image pg. A89
1955	Lu Sen	R. L. Polk Co.	Image pg. A99
1950	ASnider G WV	R. L. Polk Co., Publishers	Image pg. A107
1946	Snider G W exp	R. L. Polk Co., Publishers	Image pg. A114
1930	Calderwood H A	R. L. Polk Co. of California, Publishers	Image pg. A145
1921	Burnham J D	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Miloslavich Chas	Polk-Husted Directory Co.	Image pg. A175

418 SUTTER S

Year	Uses	Source	
1950	Irvine J R	R. L. Polk Co., Publishers	Image pg. A107
1946	Allwell R E	R. L. Polk Co., Publishers	Image pg. A114

420 SUTTER S

Year	Uses	Source	
1950	Linton Chas	R. L. Polk Co., Publishers	Image pg. A107
1946	Sholz Albertina A	R. L. Polk Co., Publishers	Image pg. A114
1935	Beck J M	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Neth Mrs Jennie	R. L. Polk Co. of California, Publishers	Image pg. A155

FINDINGS

Year	Uses	Source	
1921	Owen Mrs J M	Polk-Husted Directory Co., Publishers	Image pg. A165

421 SUTTER S

Year	Uses	Source	
1960	Jap Mar Sim	R. L. Polk Co., Publishers	Image pg. A89
1955	Jap Mar	R. L. Polk Co.	Image pg. A99
1950	AStagnaro David	R. L. Polk Co., Publishers	Image pg. A107
1946	Stagnaro David	R. L. Polk Co., Publishers	Image pg. A114
1935	Stagnaro David o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Stagnaro David	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Stagnaro David	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Stagnaro David	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Celayeta Saturnino	Polk-Husted Directory Co.	Image pg. A175

422 SUTTER S

Year	Uses	Source	
1960	Yip Chick	R. L. Polk Co., Publishers	Image pg. A89
1955	Yip Chick	R. L. Polk Co.	Image pg. A99
1950	Mc Taggart C L Mrs	R. L. Polk Co., Publishers	Image pg. A107
1946	Mc Taggert C L Mrs	R. L. Polk Co., Publishers	Image pg. A114
1935	Mc Taggart C L Mrs	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	A Tiggart C L Mrs	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Mc Taggart Mrs C L	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Mc Taggart Mrs C L	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Royal	Polk-Husted Directory Co.	Image pg. A175
	Mc Taggart Carrie wid	Polk-Husted Directory Co.	Image pg. A175

423 SUTTER S

Year	Uses	Source	
2003	Dominguez Isabel S	SBC PACIFIC BELL	
1960	Chan Sang	R. L. Polk Co., Publishers	Image pg. A89
1955	Jew Hip Shie	R. L. Polk Co.	Image pg. A99
1950	AMontgomery J W	R. L. Polk Co., Publishers	Image pg. A107

FINDINGS

424 SUTTER S

Year	Uses	Source	
1960	Vacant	R. L. Polk Co., Publishers	Image pg. A89
1955	Koelbel Karl I	R. L. Polk Co.	Image pg. A99
1950	ARicci M L Mrs	R. L. Polk Co., Publishers	Image pg. A107
	Knight Pearl Mrs	R. L. Polk Co., Publishers	Image pg. A107
1946	Knight Pearl Mrg	R. L. Polk Co., Publishers	Image pg. A114
	Jacobson Wallace	R. L. Polk Co., Publishers	Image pg. A114
1935	Bundle Arth	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Green D A	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Giraldo A F	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Conti G E	Polk-Husted Directory Co., Publishers	Image pg. A165
	Davenport Jas	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Brennan Edw	Polk-Husted Directory Co.	Image pg. A175

425 SUTTER S

Year	Uses	Source	
1960	Rathburn Pauline F Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Bowen Louis	R. L. Polk Co.	Image pg. A99
1950	AClements John	R. L. Polk Co., Publishers	Image pg. A107

426 SUTTER S

Year	Uses	Source	
1960	Sanchez Joseph	R. L. Polk Co., Publishers	Image pg. A89

427 SUTTER S

Year	Uses	Source	
2003	Manansala Concepcion	SBC PACIFIC BELL	
1960	Jang Jung	R. L. Polk Co., Publishers	Image pg. A89
1955	Southwick Alice Mrs	R. L. Polk Co.	Image pg. A99
1950	ABerelli Jos	R. L. Polk Co., Publishers	Image pg. A107

428 SUTTER S

Year	Uses	Source	
1960	Higgins Frank	R. L. Polk Co., Publishers	Image pg. A89
1955	Sheehan Estelle N Mrs	R. L. Polk Co.	Image pg. A99

FINDINGS

Year	Uses	Source	
1955	Ricci Meta L Mrs	R. L. Polk Co.	Image pg. A99
1950	Harkins H W	R. L. Polk Co., Publishers	Image pg. A107
	Grant L C	R. L. Polk Co., Publishers	Image pg. A107
1946	Harkins H W	R. L. Polk Co., Publishers	Image pg. A114
	Grant L C	R. L. Polk Co., Publishers	Image pg. A114
1935	Olsen R N	R. L. Polk Co. of California, Publishers	Image pg. A132
1925	Dennison R E	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Ross John	Polk-Husted Directory Co., Publishers	Image pg. A165
	Rich J L	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Rogers G W	Polk-Husted Directory Co.	Image pg. A175

429 SUTTER S

Year	Uses	Source	
1960	Mah Fred	R. L. Polk Co., Publishers	Image pg. A89
1955	Tadlock Cicco Mrs	R. L. Polk Co.	Image pg. A99
1950	ANorton Pearl Mrs	R. L. Polk Co., Publishers	Image pg. A107
1916	Buhner Dora w id Ern	Polk-Husted Directory Co.	Image pg. A175

430 SUTTER S

Year	Uses	Source	
1960	Velez Florentino	R. L. Polk Co., Publishers	Image pg. A89
1955	Mow l Clinton W	R. L. Polk Co.	Image pg. A99
1950	Mow l M C Mrs	R. L. Polk Co., Publishers	Image pg. A107
1946	Mow l M C Mrs	R. L. Polk Co., Publishers	Image pg. A114
1935	Miow l M A o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Viow l M 1 A o	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Mow e M A	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Mow l M A	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Mow l M A	Polk-Husted Directory Co.	Image pg. A175

431 SUTTER S

Year	Uses	Source	
1960	Bledsoe Peggy L Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Yueng Lee	R. L. Polk Co.	Image pg. A99

FINDINGS

Year	Uses	Source	
1950	Kokonas E S	R. L. Polk Co., Publishers	Image pg. A107
1946	Goldston H Ml	R. L. Polk Co., Publishers	Image pg. A114
	Watkins H M Mrs	R. L. Polk Co., Publishers	Image pg. A114
1935	Watkins Hazel Mrs	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Wallace H M	Polk-Husted Directory Co., Publishers	Image pg. A165

432 SUTTER S

Year	Uses	Source	
1960	Apiki Arth	R. L. Polk Co., Publishers	Image pg. A89
1950	ATinnin W	R. L. Polk Co., Publishers	Image pg. A107
1946	Tinnin W	R. L. Polk Co., Publishers	Image pg. A114
1935	CGunion R EF	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Greaves Aifreda Mis	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Orr Mrs A S	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Donnelly C H	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Cole W C	Polk-Husted Directory Co.	Image pg. A175

433 SUTTER S

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145

435 SUTTER S

Year	Uses	Source	
2003	Lour Nancy	SBC PACIFIC BELL	
1960	Wong John P OH	R. L. Polk Co., Publishers	Image pg. A89
1955	Buchan Clyde	R. L. Polk Co.	Image pg. A99
1950	AKokonas Manuel	R. L. Polk Co., Publishers	Image pg. A107
1946	La Barre T J	R. L. Polk Co., Publishers	Image pg. A114
	La Barre T J	R. L. Polk Co., Publishers	Image pg. A114
1935	La Barre Alf	R. L. Polk Co. of California, Publishers	Image pg. A132
1925	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Greaby W H	Polk-Husted Directory Co., Publishers	Image pg. A165

FINDINGS

438 SUTTER S

Year	Uses	Source	
2003	Sandoval Irene	SBC PACIFIC BELL	
	JESUS SAVES MINISTRIES INC	SBC PACIFIC BELL	
1960	Cantele Toby M	R. L. Polk Co., Publishers	Image pg. A89
1955	Cantele Toby M	R. L. Polk Co.	Image pg. A99
1950	ACantele T M	R. L. Polk Co., Publishers	Image pg. A107

440 SUTTER S

Year	Uses	Source	
1960	Acme Saw & Sup	R. L. Polk Co., Publishers	Image pg. A89
1955	Stockton Saw Wks	R. L. Polk Co.	Image pg. A99
1950	AStockton Saw Wks	R. L. Polk Co., Publishers	Image pg. A107
	Madigan F H saw filer	R. L. Polk Co., Publishers	Image pg. A107
1946	ACantele T M saw filer	R. L. Polk Co., Publishers	Image pg. A114
1935	Cantele T M o	R. L. Polk Co. of California, Publishers	Image pg. A132
	Stockton Saw Works	R. L. Polk Co. of California, Publishers	Image pg. A132

442 SUTTER S

Year	Uses	Source	
2003	Potter Josephine	SBC PACIFIC BELL	
	Penaflor Lisa	SBC PACIFIC BELL	
1960	Baker Robt	R. L. Polk Co., Publishers	Image pg. A89
1955	Kupiec Jos	R. L. Polk Co.	Image pg. A99
1950	AParshey D E	R. L. Polk Co., Publishers	Image pg. A107

503 SUTTER S

Year	Uses	Source	
1955	Filipino Meth Mission	R. L. Polk Co.	Image pg. A99
1950	AGonzalo D F Rev	R. L. Polk Co., Publishers	Image pg. A107
	Fabionar Aniceto	R. L. Polk Co., Publishers	Image pg. A107
	Fiipino Methodist Mis	R. L. Polk Co., Publishers	Image pg. A107
1946	Gonzalo Dionisio Rev	R. L. Polk Co., Publishers	Image pg. A114
	Mission	R. L. Polk Co., Publishers	Image pg. A114
	Filipino Methodist	R. L. Polk Co., Publishers	Image pg. A114

Year	Uses	Source	
1935	Lagriimas F E	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
	Pantillo Anastacio	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Galbrath Harvey	R. L. Polk Co. of California, Publishers	Image pg. A155
	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Ware Mrs Jessie	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Vacant	Polk-Husted Directory Co.	Image pg. A175
	Dardis T L	Polk-Husted Directory Co.	Image pg. A175

504 SUTTER S

Year	Uses	Source	
1960	Mack Siller M Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Craig Lucy Mrs	R. L. Polk Co.	Image pg. A99
1950	AAgbavani Theo	R. L. Polk Co., Publishers	Image pg. A107
1946	Agbayani T A B	R. L. Polk Co., Publishers	Image pg. A114
1935	Ferolio Margt Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Mata Jesus	R. L. Polk Co. of California, Publishers	Image pg. A145
	Row c Leo	R. L. Polk Co. of California, Publishers	Image pg. A145
1921	Moresco Mrs Clorinda	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Gragnani Torquato	Polk-Husted Directory Co.	Image pg. A175

505 SUTTER S

Year	Uses	Source	
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Dardis T L vet surg	R. L. Polk Co. of California, Publishers	Image pg. A145

506 SUTTER S

Year	Uses	Source	
1960	Ruiz Inez	R. L. Polk Co., Publishers	Image pg. A89
1955	Terrell Nathl	R. L. Polk Co.	Image pg. A99

508 SUTTER S

Year	Uses	Source	
1950	Vacant	R. L. Polk Co., Publishers	Image pg. A107
1946	Young Chan	R. L. Polk Co., Publishers	Image pg. A114

FINDINGS

Year	Uses	Source	
1935	Unruh W A	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Sweet Lucille	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Hanes Mrs Mary	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Hanes Mrs Mary	Polk-Husted Directory Co., Publishers	Image pg. A165

510 SUTTER S

Year	Uses	Source	
2003	Huang Mei Xiang	SBC PACIFIC BELL	
1960	Fong Gew Ngoy	R. L. Polk Co., Publishers	Image pg. A89
1955	Fong Gew Ng	R. L. Polk Co.	Image pg. A99
1950	AFong G N	R. L. Polk Co., Publishers	Image pg. A107
1935	Lightner C C o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Lightner C C o	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Lightner C C	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Orton Chas	Polk-Husted Directory Co., Publishers	Image pg. A165
	Nolen Alex	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Light Mrs R S	Polk-Husted Directory Co.	Image pg. A175

511 SUTTER S

Year	Uses	Source	
1935	Sutter Flats	R. L. Polk Co. of California, Publishers	Image pg. A132

515 SUTTER S

Year	Uses	Source	
1955	Vacant	R. L. Polk Co.	Image pg. A99
1950	ANix C M bldg matls	R. L. Polk Co., Publishers	Image pg. A107
1946	Vacant	R. L. Polk Co., Publishers	Image pg. A114

518 SUTTER S

Year	Uses	Source	
1960	Moresco Clorinda L Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Baldridge Fred D	R. L. Polk Co.	Image pg. A99
1950	AJolly J A	R. L. Polk Co., Publishers	Image pg. A107
1946	Nolasco Mary Mrs	R. L. Polk Co., Publishers	Image pg. A114
1935	Ellis A H	R. L. Polk Co. of California, Publishers	Image pg. A132

FINDINGS

Year	Uses	Source	
1930	Ellis A H	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Ellis A H	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Ellis A H	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Ellis A H	Polk-Husted Directory Co.	Image pg. A175

519 SUTTER S

Year	Uses	Source	
1960	Jefferson Luella May Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Christpher Levi	R. L. Polk Co.	Image pg. A99
1950	ONeal Jas	R. L. Polk Co., Publishers	Image pg. A107
1946	Garner Otto	R. L. Polk Co., Publishers	Image pg. A114
1930	Perez John	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Oriental	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Trunnell J H	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Tebeau Mrs Emma	Polk-Husted Directory Co.	Image pg. A175

522 SUTTER S

Year	Uses	Source	
1960	Mc Carty Arth L 0	R. L. Polk Co., Publishers	Image pg. A89
1955	Mc Carty Arth L 0	R. L. Polk Co.	Image pg. A99
1950	Mc Carty A L	R. L. Polk Co., Publishers	Image pg. A107
1946	Mc Carty A L	R. L. Polk Co., Publishers	Image pg. A114
1935	Mc Carty A L	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Mc Carty A L	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Mc Carty A L	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Mc Carty A L	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Wardle E E	Polk-Husted Directory Co.	Image pg. A175

523 SUTTER S

Year	Uses	Source	
1960	Benson Bertha L Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Benson Bertha Mrs	R. L. Polk Co.	Image pg. A99
1950	Knight Theona Mrs	R. L. Polk Co., Publishers	Image pg. A107
1946	Birdwell Virginia Mrs	R. L. Polk Co., Publishers	Image pg. A114

FINDINGS

Year	Uses	Source	
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Young Leon	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Woodw ard Roy	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Ehrnman L L	Polk-Husted Directory Co.	Image pg. A175

525 SUTTER S

Year	Uses	Source	
1960	ONeal Eula M Mrs 0	R. L. Polk Co., Publishers	Image pg. A89
1955	ONeal Eula M Mrs h	R. L. Polk Co.	Image pg. A99
1950	ONeal Eula M	R. L. Polk Co., Publishers	Image pg. A107
1946	Fsrrow Geo	R. L. Polk Co., Publishers	Image pg. A114
1935	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Zimmerman Dorn	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Mendoza Santiago	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Nomellini Eugenio	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Nomellini Eugene	Polk-Husted Directory Co.	Image pg. A175
	Catalani Antone	Polk-Husted Directory Co.	Image pg. A175

527 SUTTER S

Year	Uses	Source	
2003	Wei Quan Ma	SBC PACIFIC BELL	
1960	Hoffman Maretha Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Brow n Oretha Mrs	R. L. Polk Co.	Image pg. A99
1950	ASmith L n radio repr	R. L. Polk Co., Publishers	Image pg. A107
1946	Smith Leonard	R. L. Polk Co., Publishers	Image pg. A114
	Brow n Louis	R. L. Polk Co., Publishers	Image pg. A114
1935	Hook John	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Bacolanda Genaro	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Celayeta Saturnino	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Celayeta Saturnine	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Vacant	Polk-Husted Directory Co.	Image pg. A175

FINDINGS

528 SUTTER S

Year	Uses	Source	
1960	Martinez Frank P	R. L. Polk Co., Publishers	Image pg. A89
1955	Martinez Frank P h	R. L. Polk Co.	Image pg. A99
1950	Selga M R	R. L. Polk Co., Publishers	Image pg. A107
1946	Phelps G A	R. L. Polk Co., Publishers	Image pg. A114
1935	Neilson Peter	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Walters Harold	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Petersen Louis	Polk-Husted Directory Co., Publishers	Image pg. A165
	Hastie Lloyd	Polk-Husted Directory Co., Publishers	Image pg. A165
	Chenow eth K V	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Goode J F	Polk-Husted Directory Co.	Image pg. A175

530 SUTTER S

Year	Uses	Source	
2003	Velasquez Armando	SBC PACIFIC BELL	
1960	Gee May Mrs	R. L. Polk Co., Publishers	Image pg. A89
1955	Mah Jean	R. L. Polk Co.	Image pg. A99
1950	AMah G D	R. L. Polk Co., Publishers	Image pg. A107
	AChun W S	R. L. Polk Co., Publishers	Image pg. A107
1946	Williams E K	R. L. Polk Co., Publishers	Image pg. A114
1930	Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Young R F	R. L. Polk Co. of California, Publishers	Image pg. A155
	Chase G W	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Hubbard J	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Melton C C	Polk-Husted Directory Co.	Image pg. A175

541 SUTTER S

Year	Uses	Source	
1960	Sutter Flats Apartments	R. L. Polk Co., Publishers	Image pg. A89
	a Mikes Mary L Mrs	R. L. Polk Co., Publishers	Image pg. A89
	b Gutierrez Alesandro	R. L. Polk Co., Publishers	Image pg. A89
	c Bond Irving	R. L. Polk Co., Publishers	Image pg. A89
	d Patrick Albert	R. L. Polk Co., Publishers	Image pg. A89

FINDINGS

Year	Uses	Source	
1955	Sutter Flats Apartmentb	R. L. Polk Co.	Image pg. A99
	a Cerverte Fredk	R. L. Polk Co.	Image pg. A99
	b Vacant	R. L. Polk Co.	Image pg. A99
	c Vacant	R. L. Polk Co.	Image pg. A99
	d Vacant	R. L. Polk Co.	Image pg. A99
1950	Battilana D L	R. L. Polk Co., Publishers	Image pg. A107
	Miller J E Mrs	R. L. Polk Co., Publishers	Image pg. A107
	Waite F A	R. L. Polk Co., Publishers	Image pg. A107
	Rickman J E	R. L. Polk Co., Publishers	Image pg. A107
1946	Williams Vester	R. L. Polk Co., Publishers	Image pg. A114
	a White O O	R. L. Polk Co., Publishers	Image pg. A114
	b Lew ellen C C Mrs	R. L. Polk Co., Publishers	Image pg. A114
	c Anderson Helen Mrs	R. L. Polk Co., Publishers	Image pg. A114
	d Morgenstern Bernard	R. L. Polk Co., Publishers	Image pg. A114
1935	b Vacant	R. L. Polk Co. of California, Publishers	Image pg. A132
	d Weldy J A	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	Sutter Flats	R. L. Polk Co. of California, Publishers	Image pg. A145
	Gondolfo John	R. L. Polk Co. of California, Publishers	Image pg. A145
	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
	b Nixon J N	R. L. Polk Co. of California, Publishers	Image pg. A145
	c Chiti Cesare	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	Sutter Flats	R. L. Polk Co. of California, Publishers	Image pg. A155
	a Klein Reinhold	R. L. Polk Co. of California, Publishers	Image pg. A155
	b Berkley E E	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	a Vacant	Polk-Husted Directory Co., Publishers	Image pg. A165
	b Atchley H E	Polk-Husted Directory Co., Publishers	Image pg. A165
	c Tindall P L	Polk-Husted Directory Co., Publishers	Image pg. A165
	d Nauyoks F L	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Bryant E B	Polk-Husted Directory Co.	Image pg. A175

543 SUTTER S

Year	Uses	Source
2003	Mendez Antonio	SBC PACIFIC BELL

FINDINGS

Year	Uses	Source	
1960	a Ambalong Melecio Tj	R. L. Polk Co., Publishers	Image pg. A89
	b Jackson Daisy Mrs	R. L. Polk Co., Publishers	Image pg. A89
	c Willis Geraldine Mrs	R. L. Polk Co., Publishers	Image pg. A89
	d White Truman	R. L. Polk Co., Publishers	Image pg. A89
1955	a Manion Lyle	R. L. Polk Co.	Image pg. A99
	b Simpson Buel	R. L. Polk Co.	Image pg. A99
	c Ewaldt Chas W	R. L. Polk Co.	Image pg. A99
	d Vacant	R. L. Polk Co.	Image pg. A99
1950	Strohl Max	R. L. Polk Co., Publishers	Image pg. A107
	ARaglin Gola Mrs	R. L. Polk Co., Publishers	Image pg. A107
	Williams Georgia Mrs	R. L. Polk Co., Publishers	Image pg. A107
	King L B	R. L. Polk Co., Publishers	Image pg. A107
1946	Olson Wm	R. L. Polk Co., Publishers	Image pg. A114
	a Williams 0 M	R. L. Polk Co., Publishers	Image pg. A114
	b King L G	R. L. Polk Co., Publishers	Image pg. A114
	c Rogers E F	R. L. Polk Co., Publishers	Image pg. A114
	d Olsen W T	R. L. Polk Co., Publishers	Image pg. A114
1935	a Erinson Harriett Mrs	R. L. Polk Co. of California, Publishers	Image pg. A132
	b Wichman Cleveland	R. L. Polk Co. of California, Publishers	Image pg. A132
	c OConnor Eug	R. L. Polk Co. of California, Publishers	Image pg. A132
	:d Bassinger C J	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
	b Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
	c Leorardini Victor	R. L. Polk Co. of California, Publishers	Image pg. A145
	d Marchetti Edelio	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	a Lucas Mrs Myrtle	R. L. Polk Co. of California, Publishers	Image pg. A155
	c Clenio John	R. L. Polk Co. of California, Publishers	Image pg. A155
	d Dunlap L G	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Darter Flats	Polk-Husted Directory Co., Publishers	Image pg. A165
	a Easley W P	Polk-Husted Directory Co., Publishers	Image pg. A165
	b Nichols Roy	Polk-Husted Directory Co., Publishers	Image pg. A165
	c Davis Mrs N E	Polk-Husted Directory Co., Publishers	Image pg. A165

Year	Uses	Source	
1921	d Chadek Frank	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Burns J P	Polk-Husted Directory Co.	Image pg. A175

545 SUTTER S

Year	Uses	Source	
2003	Garcia Sergio Isabel	SBC PACIFIC BELL	
	Vargas Patricio	SBC PACIFIC BELL	
	Barro Ivan	SBC PACIFIC BELL	
1960	a Grey Lillie G Mrs	R. L. Polk Co., Publishers	Image pg. A89
	b Arellano Vince A	R. L. Polk Co., Publishers	Image pg. A89
1955	a Morgan Eula Mrs	R. L. Polk Co.	Image pg. A99
	b Millsop Wm	R. L. Polk Co.	Image pg. A99
1950	Sutter Flats Apart	R. L. Polk Co., Publishers	Image pg. A107
	ments	R. L. Polk Co., Publishers	Image pg. A107
	AWorthington H S	R. L. Polk Co., Publishers	Image pg. A107
	Adams B M	R. L. Polk Co., Publishers	Image pg. A107
	Logan P E	R. L. Polk Co., Publishers	Image pg. A107
1946	Sutter Flats	R. L. Polk Co., Publishers	Image pg. A114
	Worthington Hugh	R. L. Polk Co., Publishers	Image pg. A114
	a Codiga J P	R. L. Polk Co., Publishers	Image pg. A114
1935	a Gianelli T M	R. L. Polk Co. of California, Publishers	Image pg. A132
	b Leonardini Madeline	R. L. Polk Co. of California, Publishers	Image pg. A132
	Mrs o	R. L. Polk Co. of California, Publishers	Image pg. A132
1930	a Vacant	R. L. Polk Co. of California, Publishers	Image pg. A145
1925	a Stevenson Mrs Ida	R. L. Polk Co. of California, Publishers	Image pg. A155
	b Houlton W M	R. L. Polk Co. of California, Publishers	Image pg. A155
1921	Yv In riggs W i	Polk-Husted Directory Co., Publishers	Image pg. A165
	b Broker Law rence	Polk-Husted Directory Co., Publishers	Image pg. A165
	a Tatton C C	Polk-Husted Directory Co., Publishers	Image pg. A165
1916	Burnham J D	Polk-Husted Directory Co.	Image pg. A175

546 SUTTER S

Year	Uses	Source	
1925	Morris Josephus	R. L. Polk Co. of California, Publishers	Image pg. A155

FINDINGS

SUTTER ST S

301 SUTTER ST S

Year	Uses	Source	
1984	Arcano Alipio	R. L. Polk Co., Publishers	Image pg. A33
	Vacant	R. L. Polk Co., Publishers	Image pg. A33

302 SUTTER ST S

Year	Uses	Source	
1984	Rabe Hines	R. L. Polk Co., Publishers	Image pg. A33

303 SUTTER ST S

Year	Uses	Source	
1984	Lua Yolanda	R. L. Polk Co., Publishers	Image pg. A33

304 SUTTER ST S

Year	Uses	Source	
1984	De Leon Jesus	R. L. Polk Co., Publishers	Image pg. A33

305 SUTTER ST S

Year	Uses	Source	
1984	Valdez Aruaro	R. L. Polk Co., Publishers	Image pg. A33

306 SUTTER ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A34
	Vacant	R. L. Polk Co., Publishers	Image pg. A33
1965	SUTTER LIQUORS	R. L. Polk Co., Publishers	Image pg. A81

307 SUTTER ST S

Year	Uses	Source	
1984	Sfc 6z Eliz	R. L. Polk Co., Publishers	Image pg. A35

315 SUTTER ST S

Year	Uses	Source	
1984	Marning Federico	R. L. Polk Co., Publishers	Image pg. A36
	Lubrica	R. L. Polk Co., Publishers	Image pg. A36
	Silverio Frank	R. L. Polk Co., Publishers	Image pg. A36

FINDINGS

Year	Uses	Source	
1984	Malonzo	R. L. Polk Co., Publishers	Image pg. A36
	Reginaldo	R. L. Polk Co., Publishers	Image pg. A36
	Corpus	R. L. Polk Co., Publishers	Image pg. A36
	Lucero	R. L. Polk Co., Publishers	Image pg. A36
	Reyes	R. L. Polk Co., Publishers	Image pg. A36
	Louis Apartments	R. L. Polk Co., Publishers	Image pg. A36
1965	VOU EDW	R. L. Polk Co., Publishers	Image pg. A81
	OCONNOR THOS	R. L. Polk Co., Publishers	Image pg. A81
	i AYALA MANUAL	R. L. Polk Co., Publishers	Image pg. A81
	LOUIS APARTMENTS	R. L. Polk Co., Publishers	Image pg. A81
	LIM JAMES F	R. L. Polk Co., Publishers	Image pg. A81
	MCNDES MANUAL	R. L. Polk Co., Publishers	Image pg. A81
	WARD MILDRED MRS	R. L. Polk Co., Publishers	Image pg. A81
	ZEPPA FRANK	R. L. Polk Co., Publishers	Image pg. A81
	t NASTRO LOXVICO	R. L. Polk Co., Publishers	Image pg. A81

317 SUTTER ST S

Year	Uses	Source	
1965	UNDER CONSTN	R. L. Polk Co., Publishers	Image pg. A81

320 SUTTER ST S

Year	Uses	Source	
1965	ARONG B JR	R. L. Polk Co., Publishers	Image pg. A81

321 SUTTER ST S

Year	Uses	Source	
1984	Williams	R. L. Polk Co., Publishers	Image pg. A37

327 SUTTER ST S

Year	Uses	Source	
1984	Capote Jeannie	R. L. Polk Co., Publishers	Image pg. A37

328 SUTTER ST S

Year	Uses	Source	
1965	RODERTE JUANA MRS	R. L. Polk Co., Publishers	Image pg. A81

FINDINGS

333 SUTTER ST S

Year	Uses	Source	
1984	On Lock Sam	R. L. Polk Co., Publishers	Image pg. A38

344 SUTTER ST S

Year	Uses	Source	
1984	Wong Kin	R. L. Polk Co., Publishers	Image pg. A38
	Wong Lee S	R. L. Polk Co., Publishers	Image pg. A38
1965	HONG BAK F H	R. L. Polk Co., Publishers	Image pg. A81

400 SUTTER ST S

Year	Uses	Source	
1984	Winn Wilie	R. L. Polk Co., Publishers	Image pg. A39

401 SUTTER ST S

Year	Uses	Source	
1984	Perez Eugene	R. L. Polk Co., Publishers	Image pg. A39

402 SUTTER ST S

Year	Uses	Source	
1984	Lflock Grant	R. L. Polk Co., Publishers	Image pg. A39

403 SUTTER ST S

Year	Uses	Source	
1984	b Pendong Pete	R. L. Polk Co., Publishers	Image pg. A39
	Low B	R. L. Polk Co., Publishers	Image pg. A39

404 SUTTER ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A39

405 SUTTER ST S

Year	Uses	Source	
1984	Martini Edw	R. L. Polk Co., Publishers	Image pg. A39

406 SUTTER ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A40

FINDINGS

Year	Uses	Source	
1984	Lau Bock Foon	R. L. Polk Co., Publishers	Image pg. A40
	Salinas Pedro	R. L. Polk Co., Publishers	Image pg. A40
	Elias Narciso	R. L. Polk Co., Publishers	Image pg. A40
	rona Edna	R. L. Polk Co., Publishers	Image pg. A40
	Salon Danl	R. L. Polk Co., Publishers	Image pg. A39
	Hernandez Frank	R. L. Polk Co., Publishers	Image pg. A40
	Lopez Francisco	R. L. Polk Co., Publishers	Image pg. A40
	Garduno Vickie	R. L. Polk Co., Publishers	Image pg. A39
1965	HUEY LAY	R. L. Polk Co., Publishers	Image pg. A81
	CHAN K F	R. L. Polk Co., Publishers	Image pg. A81

407 SUTTER ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A41

415 SUTTER ST S

Year	Uses	Source	
1984	Yip Boelog	R. L. Polk Co., Publishers	Image pg. A42
1965	LUE AN SING	R. L. Polk Co., Publishers	Image pg. A81

421 SUTTER ST S

Year	Uses	Source	
1984	Bartolone Frank	R. L. Polk Co., Publishers	Image pg. A42
1965	JAP MAR SIM 0 H	R. L. Polk Co., Publishers	Image pg. A81

422 SUTTER ST S

Year	Uses	Source	
1984	Yip Gan Chick	R. L. Polk Co., Publishers	Image pg. A42
1965	YIP GAN CHICK S H	R. L. Polk Co., Publishers	Image pg. A81

423 SUTTER ST S

Year	Uses	Source	
1984	Madriaga Ben	R. L. Polk Co., Publishers	Image pg. A42
1965	CHAN SANG H	R. L. Polk Co., Publishers	Image pg. A81

FINDINGS

424 SUTTER ST S

Year	Uses	Source	
1984	aRegacho Alfredo R	R. L. Polk Co., Publishers	Image pg. A42
	Gutierrez 01 Cuizon	R. L. Polk Co., Publishers	Image pg. A42
1965	BIK CHUN LEE MRS	R. L. Polk Co., Publishers	Image pg. A81

425 SUTTER ST S

Year	Uses	Source	
1984	Emperador Valerio	R. L. Polk Co., Publishers	Image pg. A42
1965	RATHBUN PAULINE F MRS	R. L. Polk Co., Publishers	Image pg. A81

426 SUTTER ST S

Year	Uses	Source	
1984	Inocencio Luis	R. L. Polk Co., Publishers	Image pg. A42
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

427 SUTTER ST S

Year	Uses	Source	
1984	Dalao Frank	R. L. Polk Co., Publishers	Image pg. A42
1965	GEN JOHN H	R. L. Polk Co., Publishers	Image pg. A81

428 SUTTER ST S

Year	Uses	Source	
1984	Wong Yuk Lin Mrs	R. L. Polk Co., Publishers	Image pg. A42
1965	WONG WYMAN	R. L. Polk Co., Publishers	Image pg. A81

429 SUTTER ST S

Year	Uses	Source	
1984	Martin Tony	R. L. Polk Co., Publishers	Image pg. A42

430 SUTTER ST S

Year	Uses	Source	
1984	Justo Domingo	R. L. Polk Co., Publishers	Image pg. A42
1965	WONG CHEW HEP 0 H	R. L. Polk Co., Publishers	Image pg. A81

431 SUTTER ST S

Year	Uses	Source	
1984	Chon Ay Chung	R. L. Polk Co., Publishers	Image pg. A42

FINDINGS

Year	Uses	Source	
1965	CATO VELMA MRS	R. L. Polk Co., Publishers	Image pg. A81

432 SUTTER ST S

Year	Uses	Source	
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

435 SUTTER ST S

Year	Uses	Source	
1984	Ivory Louise Mrs	R. L. Polk Co., Publishers	Image pg. A42
1965	FLORES JOSE	R. L. Polk Co., Publishers	Image pg. A81

438 SUTTER ST S

Year	Uses	Source	
1965	CANTELE TOBY M 0 H	R. L. Polk Co., Publishers	Image pg. A81

440 SUTTER ST S

Year	Uses	Source	
1984	Faith Church	R. L. Polk Co., Publishers	Image pg. A42
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

442 SUTTER ST S

Year	Uses	Source	
1984	Ynostroa Pedro	R. L. Polk Co., Publishers	Image pg. A42
1965	MC QUISTON HARRY G	R. L. Polk Co., Publishers	Image pg. A81

501 SUTTER ST S

Year	Uses	Source	
1984	a Vacant	R. L. Polk Co., Publishers	Image pg. A43
	Young Shui K	R. L. Polk Co., Publishers	Image pg. A44

502 SUTTER ST S

Year	Uses	Source	
1984	Pressley Bill	R. L. Polk Co., Publishers	Image pg. A45

503 SUTTER ST S

Year	Uses	Source	
1984	Vacant	R. L. Polk Co., Publishers	Image pg. A45

FINDINGS

504 SUTTER ST S

Year	Uses	Source	
1984	a Henderson Tony	R. L. Polk Co., Publishers	Image pg. A45
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

505 SUTTER ST S

Year	Uses	Source	
1984	aRanson Ed	R. L. Polk Co., Publishers	Image pg. A45
	Matthew s Robt	R. L. Polk Co., Publishers	Image pg. A45

506 SUTTER ST S

Year	Uses	Source	
1984	Mc Keil Steven	R. L. Polk Co., Publishers	Image pg. A46
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

507 SUTTER ST S

Year	Uses	Source	
1984	Gullium Nancy	R. L. Polk Co., Publishers	Image pg. A46

510 SUTTER ST S

Year	Uses	Source	
1984	Fong Gew Ngoy	R. L. Polk Co., Publishers	Image pg. A46
1965	FONG GEIV NGOY 0 H	R. L. Polk Co., Publishers	Image pg. A81

518 SUTTER ST S

Year	Uses	Source	
1984	No Return	R. L. Polk Co., Publishers	Image pg. A46
1965	ISHIKAWA RICHD	R. L. Polk Co., Publishers	Image pg. A81

521 SUTTER ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A46
	Wong Beck Yuk	R. L. Polk Co., Publishers	Image pg. A46
	Vacant	R. L. Polk Co., Publishers	Image pg. A46
	Henderson Lorene	R. L. Polk Co., Publishers	Image pg. A46
	Brow n K	R. L. Polk Co., Publishers	Image pg. A46

FINDINGS

522 SUTTER ST S

Year	Uses	Source	
1984	Escobedo Guadalupe	R. L. Polk Co., Publishers	Image pg. A46
1965	MC CARTY ARTH L 0 H	R. L. Polk Co., Publishers	Image pg. A81

524 SUTTER ST S

Year	Uses	Source	
1984	Martinez Mercedes Mrs	R. L. Polk Co., Publishers	Image pg. A46
1965	HOFFMAN MARTHA MRS	R. L. Polk Co., Publishers	Image pg. A81

525 SUTTER ST S

Year	Uses	Source	
1965	BROYLES EARL 0 H	R. L. Polk Co., Publishers	Image pg. A81

527 SUTTER ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A46
	Totem Kw ok	R. L. Polk Co., Publishers	Image pg. A46
	Garcia Librada	R. L. Polk Co., Publishers	Image pg. A46
	Lee Soe	R. L. Polk Co., Publishers	Image pg. A46
	Chen Hu	R. L. Polk Co., Publishers	Image pg. A46

528 SUTTER ST S

Year	Uses	Source	
1984	Martinez Josephine Mrs	R. L. Polk Co., Publishers	Image pg. A46
1965	MARTINEZ MERCEDES MRS	R. L. Polk Co., Publishers	Image pg. A81
	HOS 4196	R. L. Polk Co., Publishers	Image pg. A81

530 SUTTER ST S

Year	Uses	Source	
1984	Rivera Lilly	R. L. Polk Co., Publishers	Image pg. A46
	Wong Geo N	R. L. Polk Co., Publishers	Image pg. A46
1965	VACANT	R. L. Polk Co., Publishers	Image pg. A81

541 SUTTER ST S

Year	Uses	Source	
1984	dSunakhenh Souk	R. L. Polk Co., Publishers	Image pg. A46

FINDINGS

Year	Uses	Source	
1984	cMorales Diane	R. L. Polk Co., Publishers	Image pg. A46
	bVanhsy Veum	R. L. Polk Co., Publishers	Image pg. A46
	a Pinkard Montel	R. L. Polk Co., Publishers	Image pg. A46
	Apartments	R. L. Polk Co., Publishers	Image pg. A46
1965	C BOND IRVIN	R. L. Polk Co., Publishers	Image pg. A81
	A PINKARD MONTEL	R. L. Polk Co., Publishers	Image pg. A81

543 SUTTER ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A46
	aSmith A	R. L. Polk Co., Publishers	Image pg. A46
	b Earnest Roberta	R. L. Polk Co., Publishers	Image pg. A46
	c Cirillo Rose Sister	R. L. Polk Co., Publishers	Image pg. A46
	dNuang Khaleck	R. L. Polk Co., Publishers	Image pg. A46
1965	A BETHANCOURT L	R. L. Polk Co., Publishers	Image pg. A81
	C WALKER JOHN	R. L. Polk Co., Publishers	Image pg. A81

545 SUTTER ST S

Year	Uses	Source	
1984	Apartments	R. L. Polk Co., Publishers	Image pg. A46
	aPeoi Thamala	R. L. Polk Co., Publishers	Image pg. A46
	b Rivas Heriberto	R. L. Polk Co., Publishers	Image pg. A46
	c Chavez Rivas	R. L. Polk Co., Publishers	Image pg. A46
1965	A HERRING LILLIE H	R. L. Polk Co., Publishers	Image pg. A81

W SONORA ST

420 W SONORA ST

Year	Uses	Source	
1975	cita Florencio	R.L. Polk CO.	Image pg. A64

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
116 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
116 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
116 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
116 E CHURCH ST	2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
118 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1911, 1906
118 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
118 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
118 E CHURCH ST	2014, 2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
120 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
120 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
120 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
120 E CHURCH ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
121 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
121 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
122 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
122 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
122 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
122 E CHURCH ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
125 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
125 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
125 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
127 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
127 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
127 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
127 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
127 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
127 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
128 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
128 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
128 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
128 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
128 E SONORA ST	2017, 2014, 2009, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
128 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
128 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
130 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
130 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
130 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
130 E CHURCH ST	2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
131 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
131 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
131 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
132 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
132 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
132 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
132 E CHURCH ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
133 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
134 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
134 E SONORA ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
134 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
134 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
135 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
135 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
136 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
136 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
136 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
138 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
138 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
138 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
138 E CHURCH ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
138 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
138 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1911, 1906
138 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
141 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
142 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1940, 1925, 1921, 1916, 1911, 1906
142 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
142 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
142 E CHURCH ST	2017, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
144 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
144 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
144 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
144 E CHURCH ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
148 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
155 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
164 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
201 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1911, 1906
201 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
201 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
201 E CHURCH ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
201 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
202 E SONORA ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
202 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
202 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
203 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1925, 1921, 1911, 1906
203 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
203 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
203 E CHURCH ST	2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
203 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
203 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
204 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
204 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
204 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
204 E SONORA ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
204 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1916, 1911, 1906
204 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
204 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
205 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
205 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
205 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
205 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
206 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
206 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
206 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
206 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
206 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
206 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
207 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1916, 1911, 1906
207 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
207 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
207 E CHURCH ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
207 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
208 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
208 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
208 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
208 E CHURCH ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
208 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
208 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1916, 1911, 1906
209 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
209 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
209 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
210 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
210 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1940, 1921, 1916, 1911, 1906
211 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
212 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
212 E LAFAYETTE ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
212 LAFAYETTE E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
212 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
213 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
213 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
213 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
214 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
214 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
214 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1935, 1925, 1921, 1916, 1911, 1906
214 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1916, 1911, 1906
215 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
215 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
215 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
216 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
216 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
216 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
216 E CHURCH ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
217 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
217 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
217 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
218 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
218 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
218 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
218 E SONORA ST	2017, 2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
218 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
218 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
219 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
219 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
219 E HAZELTON AVE	2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
219 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
219 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
219 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
219 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
220 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
220 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
220 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
220 E CHURCH ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
221 E SONORA ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
221 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
221 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1940, 1925, 1921, 1916, 1911, 1906
221 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
221 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
221 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
221 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
222 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
223 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
223 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
223 E SONORA ST	2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
223 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1916, 1911, 1906
223 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
223 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
223 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
223 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
224 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
224 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
224 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
224 E SONORA ST	2017, 2014, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
224 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
224 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
225 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
225 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
225 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
225 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
225 E SONORA ST	2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
225 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
225 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
225 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
225 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
225 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
226 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
226 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
226 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
226 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
227 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
227 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
227 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
227 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
227 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
228 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
228 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
229 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1911, 1906
229 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
229 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
229 E CHURCH ST	2017, 2014, 2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
229 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
229 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
229 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1940, 1925, 1921, 1916, 1911, 1906
229 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
229 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
229 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
230 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
230 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
230 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
230 E CHURCH ST	2017, 2014, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
231 E HAZELTON AVE	2017, 2014, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
231 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
231 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
231 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1916, 1911, 1906
231 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
231 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
231 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
232 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
232 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
232 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
233 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
233 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1940, 1925, 1921, 1916, 1911, 1906
233 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
233 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
233 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
233 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
235 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
235 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
235 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
235 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
236 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
236 E LAFAYETTE ST	2017, 2014, 2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
236 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
236 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
237 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
237 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
237 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
237 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1925, 1921, 1916, 1911, 1906
237 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
237 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
237 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
237 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
238 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
238 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
238 E CHURCH ST	2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
238 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
239 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906
239 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
240 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
241 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
241 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
241 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
241 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
243 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
243 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
243 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
243 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
243 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
245 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
245 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
245 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
245 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
245 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1916, 1911, 1906
246 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
246 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
246 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
246 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
255 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
257 E CHURCH ST	2017, 2014, 2009, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
260 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
260 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
272 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
274 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
277 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
284 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
289 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
300 S SAN JOAQUIN ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
301 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
301 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
301 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
301 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
301 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
301 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1935, 1925, 1916, 1911, 1906
301 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
302 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
302 S SAN JOAQUIN ST	2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
302 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
302 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
302 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
303 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906
303 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
303 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
303 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
303 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1911, 1906
303 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 E HAZELTON AVE	2017, 2014, 2009, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
304 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
305 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
305 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
305 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 E CHURCH ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
306 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 S SUTTER ST	2017, 2014, 2009, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
306 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
306 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
307 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 E HAZELTON AVE	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 HAZELTON AVE E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1925, 1921, 1916, 1911, 1906
308 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
308 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
308 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
309 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
309 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
309 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
309 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
309 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
309 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
309 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
309 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 E LAFAYETTE ST	2017, 2014, 2009, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
310 E SONORA ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
310 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
310 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
310 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
310 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
310 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
311 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
311 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
311 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
311 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
311 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
311 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
311 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
312 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
312 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
312 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
312 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
312 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
312 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
312 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
312 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
312 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
313 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
313 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1916, 1911, 1906
314 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
314 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
314 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
314 E CHURCH ST	2017, 2014, 2009, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
314 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
314 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
314 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
314 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
314 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
314 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
314 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
314 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
315 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
315 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
315 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
315 E SONORA ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 S HUNTER ST	2017, 2014, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 S SUTTER ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
315 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
315 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
315 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1935, 1916, 1911, 1906
315 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
316 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
316 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
316 E SONORA ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
316 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1911, 1906
316 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
316 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
316 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
316 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
316 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
317 E CHURCH ST	2017, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
317 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
317 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
317 E SONORA ST	2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
317 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1911, 1906
317 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
317 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
317 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
317 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
317 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1911, 1906
317 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
318 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
318 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1930, 1925, 1921, 1916, 1911, 1906
318 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
318 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 E HAZELTON	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
319 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
319 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
319 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 HAZELTON E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906
319 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1940, 1925, 1921, 1916, 1911, 1906
319 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 S SAN JOAQUIN ST	2014, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
319 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906
319 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
319 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
319 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1911, 1906
320 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
320 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
320 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
320 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
320 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
320 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
320 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
320 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
320 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
320 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
320 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1935, 1925, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
320 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
321 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
321 E CHURCH ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
321 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
321 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
321 HAZELTON E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906
321 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1940, 1925, 1921, 1916, 1911, 1906
321 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
321 S SAN JOAQUIN ST	2017, 2014, 2009, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1940, 1925, 1921, 1916, 1911, 1906
321 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
321 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
321 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1935, 1925, 1921, 1916, 1911, 1906
321 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
322 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
322 E SONORA ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
322 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
322 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
323 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
323 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
323 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
323 E CHURCH ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
323 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906
324 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1911, 1906
325 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1911, 1906
325 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
325 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
325 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1921, 1911, 1906
325 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
325 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
325 S HUNTER ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
325 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
325 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
325 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
325 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
326 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
326 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1911, 1906
326 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
327 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
327 E HAZELTON AVE	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
327 HAZELTON E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906
327 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1940, 1925, 1921, 1916, 1911, 1906
327 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
327 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
327 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
327 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
327 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
328 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
328 E CHURCH ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 E SONORA ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
328 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
328 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1940, 1930, 1911, 1906
328 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
328 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
328 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
329 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
329 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
329 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
329 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
329 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
329 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
329 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
329 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
329 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
329 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
329 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1935, 1911, 1906
330 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
330 E SONORA ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
330 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
330 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
330 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
330 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
330 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
330 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
331 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
331 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
331 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
331 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
331 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
331 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
331 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
332 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
332 E SONORA ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
332 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
332 S SAN JOAQUIN ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
332 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1911, 1906
332 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
332 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1940, 1911, 1906
332 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
333 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 S HUNTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
333 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
333 S SUTTER ST	2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1921, 1911, 1906
333 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
333 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
334 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
334 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
334 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
334 E CHURCH ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
334 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
334 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
334 S SAN JOAQUIN ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
334 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
334 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
334 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
335 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
335 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
335 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
335 E CHURCH ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
335 E HAZELTON AVE	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
335 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
335 HAZELTON E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1911, 1906
335 HAZELTON AVE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1940, 1925, 1921, 1916, 1911, 1906
335 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
335 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1916, 1911, 1906
335 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
336 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
336 E CHURCH ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
336 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
336 E LAFAYETTE ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
336 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 LAFAYETTE E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
336 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 S HUNTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
336 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
336 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
336 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
337 E HAZELTON AVE	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
337 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
337 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1946, 1940, 1925, 1921, 1911, 1906
337 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
337 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1911, 1906
337 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
338 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
338 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
338 E LAFAYETTE ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
338 LAFAYETTE E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
338 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
339 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
339 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
339 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
339 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
340 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1940, 1930, 1916, 1911, 1906
340 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
340 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
340 E CHURCH ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
340 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
340 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
341 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
341 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
341 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
341 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
341 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
342 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
342 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
342 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
342 E CHURCH ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
342 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
342 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
342 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1921, 1911, 1906
343 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
343 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
343 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
343 E CHURCH ST	2017, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
343 S SAN JOAQUIN ST	2017, 2014, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
343 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
343 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1911, 1906
343 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 E CHURCH ST	2017, 2014, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
344 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1921, 1911, 1906
344 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911

FINDINGS

Address Researched	Address Not Identified in Research Source
344 S SAN JOAQUIN ST	2017, 2014, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 S SUTTER ST	2017, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
344 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
344 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
344 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
344 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 E CHURCH ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 E HAZELTON AVE	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 HAZELTON E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
345 HAZELTON AVE E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1946, 1940, 1925, 1921, 1916, 1911, 1906
345 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
345 S SAN JOAQUIN ST	2017, 2014, 2009, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
345 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1911, 1906
345 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
346 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1975, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 E SONORA ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
346 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
346 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1921, 1911, 1906
346 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
346 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
347 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
347 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
347 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
347 E CHURCH ST	2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
347 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
347 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
347 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
347 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
348 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
348 E SONORA ST	2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
348 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
348 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1916, 1911, 1906
348 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
348 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
348 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
349 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
349 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
349 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
349 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
349 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
352 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
360 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
364 E HAZELTON AVE	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
369 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
400 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
400 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
401 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
401 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
401 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
401 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
401 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
401 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
401 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 E CHURCH ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
402 S SAN JOAQUIN ST	2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
402 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
402 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
403 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
403 S HUNTER ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1916, 1911, 1906
403 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
403 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
403 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
404 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
404 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
404 E CHURCH ST	2017, 2009, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
404 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
404 S SAN JOAQUIN ST	2014, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
404 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
404 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
404 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
405 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
405 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
405 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
405 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
405 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
405 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
405 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
405 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1921, 1916, 1911, 1906
405 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 E CHURCH ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
406 S SAN JOAQUIN ST	2017, 2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
406 S SUTTER ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
406 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
406 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
406 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
407 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
407 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
407 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
407 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
408 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
408 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
408 E CHURCH ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
408 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
408 S SAN JOAQUIN ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
408 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
408 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
409 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
409 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
410 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
410 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
410 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
410 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
410 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
410 S SAN JOAQUIN ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
410 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
410 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
411 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
411 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
411 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
411 E CHURCH ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
411 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
411 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
412 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
412 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
412 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
412 E CHURCH ST	2017, 2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
412 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
412 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
412 LAFAYETTE ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
412 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
412 S SAN JOAQUIN ST	2017, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
412 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
412 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
413 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
413 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
414 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
414 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906
414 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
414 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
414 S SAN JOAQUIN ST	2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
414 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
414 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
415 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
415 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 S SUTTER ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
415 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
415 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1925, 1911, 1906
415 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
416 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
416 E SONORA ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
416 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
416 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
416 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
416 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
416 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
416 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 E CHURCH ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 E LAFAYETTE ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
418 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
418 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
418 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 LAFAYETTE E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1916, 1911, 1906
418 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
418 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
418 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
418 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
419 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
419 E SONORA ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
419 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1940, 1911, 1906
419 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
420 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
420 E CHURCH ST	2017, 2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
420 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
420 S HUNTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
420 S SAN JOAQUIN ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
420 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
420 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1916, 1911, 1906
420 W SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
421 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
421 E CHURCH ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 E SONORA ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
421 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
421 S SUTTER ST	2017, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
421 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
421 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
421 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
421 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
422 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
422 E CHURCH ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 E SONORA ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
422 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
422 S SUTTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
422 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
422 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
422 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
423 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
423 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
423 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
423 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 S SUTTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
423 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
423 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
424 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
424 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
424 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
424 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
424 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
424 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
424 S SUTTER ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
424 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
424 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
424 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
425 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
425 S SUTTER ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
425 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
425 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
425 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
426 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 E CHURCH ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 S SUTTER ST	2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
426 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 CHURCH E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
427 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
427 E CHURCH ST	2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
427 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
427 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
427 S HUNTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 S SUTTER ST	2017, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1911, 1906
427 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
427 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
427 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
428 E SONORA ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
428 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
428 S SUTTER ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
428 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
428 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
428 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1911, 1906
428 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
429 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
429 S SUTTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
429 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
429 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
429 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
430 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
430 S HUNTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
430 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
430 S SUTTER ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
430 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
430 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
430 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
431 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
431 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
431 S SUTTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
431 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
431 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
431 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
431 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
431 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
432 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
432 E SONORA ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
432 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
432 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
432 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
432 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
432 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1940, 1911, 1906
432 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
433 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
433 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
433 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
433 E CHURCH ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
433 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
434 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
434 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1930, 1925, 1921, 1916, 1911, 1906
435 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 E CHURCH ST	2009, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
435 S SAN JOAQUIN ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 S SUTTER ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
435 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
435 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1916, 1911, 1906
435 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
436 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
436 E SONORA ST	2017, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
436 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1911, 1906
436 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
436 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
436 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
437 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1955, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
437 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
437 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
437 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
437 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
437 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
437 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
437 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
438 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 E SONORA ST	2017, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1940, 1911, 1906
438 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916

FINDINGS

Address Researched	Address Not Identified in Research Source
438 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 S SUTTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
438 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
438 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
439 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
439 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
439 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
439 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
439 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
440 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 E SONORA ST	2017, 2014, 2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
440 S SAN JOAQUIN ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
440 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
440 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
440 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
440 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
440 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 E SONORA ST	2017, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 S SUTTER ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
442 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
443 CHURCH E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
443 CHURCH ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
443 E CHURCH ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
443 E CHURCH ST	2017, 2009, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
443 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
443 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911
443 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
443 SONORA E	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
443 SONORA ST E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
444 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
444 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
444 SONORA E	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
445 E SONORA ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
445 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
445 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
445 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
445 S SAN JOAQUIN ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
445 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1925, 1921, 1916, 1911, 1906
445 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
446 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
448 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1925, 1916, 1911, 1906
448 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 S HUNTER ST	2017, 2014, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
448 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
462 S SAN JOAQUIN ST	2017, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
501 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
501 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
501 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
502 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
502 S SAN JOAQUIN ST	2017, 2014, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
502 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
502 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
502 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
503 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
503 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
503 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
503 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
503 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
504 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
504 S SAN JOAQUIN ST	2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
504 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
504 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
504 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
504 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
504 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
505 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
505 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
505 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
505 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1921, 1916, 1911, 1906
505 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
506 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
506 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
506 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
506 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
506 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
506 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
507 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
508 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
508 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
508 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
508 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1921, 1911, 1906
508 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
508 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1940, 1916, 1911, 1906
509 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1906
509 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
510 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
510 S SAN JOAQUIN ST	2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
510 S SUTTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
510 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
510 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1925, 1911, 1906
510 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
510 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
510 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1911, 1906
510 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
511 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
512 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
512 S SAN JOAQUIN ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
512 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1911, 1906
512 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
513 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
513 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
514 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
514 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
514 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
514 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
515 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
515 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
516 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
516 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
516 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
516 S HUNTER ST	2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
516 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
516 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
516 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
516 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 S HUNTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
517 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
517 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
517 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
518 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1916, 1911, 1906
518 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
518 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
518 S SUTTER ST	2017, 2014, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
518 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1925, 1921, 1916, 1911, 1906
518 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
518 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
518 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
518 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
519 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
519 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
519 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
519 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
519 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
519 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
520 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
520 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
520 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
521 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 S SAN JOAQUIN ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 S SUTTER ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1916, 1911, 1906
521 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
521 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
522 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916
522 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
522 S SUTTER ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
522 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1911, 1906
522 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
522 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
522 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
523 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
523 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
523 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
523 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1930, 1916, 1911, 1906
523 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
523 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
524 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
524 S SUTTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
524 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
524 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
525 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
525 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
525 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
527 HUNTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
527 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
527 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
527 S HUNTER ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
527 S SUTTER ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
527 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
527 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
527 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
527 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1925, 1911, 1906
528 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
528 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
528 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 S SUTTER ST	2004, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
528 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
528 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
528 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
528 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
529 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1946, 1940, 1930, 1925, 1921, 1916, 1911, 1906
529 HUNTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
529 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
529 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916
529 S SAN JOAQUIN ST	2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
529 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
529 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
530 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
530 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
530 S SUTTER ST	2017, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
530 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911
530 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
530 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
530 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
534 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
534 S SAN JOAQUIN ST	2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
534 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1935, 1911, 1906
534 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
535 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
535 S SAN JOAQUIN ST	2017, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
535 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1925, 1911, 1906
535 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
536 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
536 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
536 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
536 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
537 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
537 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
537 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1940, 1911, 1906
538 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
538 S SAN JOAQUIN ST	2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
538 SAN JOAQUIN S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
538 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
539 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
539 S SAN JOAQUIN ST	2017, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
539 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
540 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
540 S SAN JOAQUIN ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
540 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
540 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
541 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
541 S SUTTER ST	2017, 2004, 2003, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
541 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
541 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
541 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
541 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
543 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1996, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
543 S SUTTER ST	2014, 2009, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
543 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
543 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
543 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
545 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
545 S SAN JOAQUIN ST	2017, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
545 S SUTTER ST	2017, 2003, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
545 S SUTTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1994, 1984, 1979, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
545 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
545 SUTIER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
545 SUTTER S	2017, 2014, 2009, 2004, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1911, 1906
545 SUTTER ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
546 SUTTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1921, 1916, 1911, 1906
547 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
548 HUNTER S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1911, 1906
548 S HUNTER ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
601 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
601 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1940, 1925, 1921, 1916, 1911, 1906
602 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
602 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
603 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
604 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
604 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
605 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1906
605 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
606 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
608 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
609 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
609 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
610 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
611 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906

FINDINGS

Address Researched	Address Not Identified in Research Source
611 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
611 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
612 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1935, 1930, 1925, 1921, 1916, 1911, 1906
612 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
613 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
613 S SAN JOAQUIN ST	2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
613 SAN JOAQUIN ST S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
614 S SAN JOAQUIN ST	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1930, 1925, 1921, 1916, 1911, 1906
614 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906
615 SAN JOAQUIN S	2017, 2014, 2009, 2004, 2003, 1999, 1996, 1994, 1990, 1984, 1979, 1975, 1970, 1965, 1960, 1955, 1950, 1946, 1940, 1935, 1925, 1921, 1916, 1911, 1906

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
429 S. San Joaquin Street	2017, 2009, 2004, 2003, 1999, 1996, 1994

APPENDIX E

ALL APPROPRIATE INQUIRY (AAI)
PHASE I ENVIRONMENTAL SITE ASSESSMENT (ESA)
USER QUESTIONNAIRE

In order to qualify for one of the Landowner Liability Protections (LLPs) offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001, the user of the Phase 1 ESA must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The user should provide the following information to the environmental professional. Failure to conduct these inquiries could result in determination that "all appropriate inquiries" is not complete.

I. GENERAL INFORMATION

Site Name: New Life Men's Facility Phase I ESA

Address: 429-431 and 435-437 South San Joaquin Street, Stockton, CA

Person Completing Questionnaire: Wayne Richardson

Company Name/Title: Gospel Center Rescue Mission

Telephone Number: 209-320-2312

Date of Completion: August 18, 2021

II. REQUIRED INFORMATION

1. Environmental liens that are filed or recorded against the *property* (40 CFR 312.25)

Did a search *of recorded land title records* (or judicial records where appropriate) identify any environmental liens filed or recorded against the property under federal, tribal, state, or local law? Note 1: In certain jurisdictions, federal, tribal, state, or local statutes, or regulations specify that environmental liens and Activity Use Limitations (AULs) be filed in judicial records rather than in land title records. In such cases judicial records must be searched for environmental liens and AULs.

None.

2. Activity and land use limitation that are in place on the *property* or that have been filed or recorded against the *property* (40 CFR 312.26(a)(1)(v) and (vi)).

Did a search of *recorded land title* records (or judicial records where appropriate, see Note 1 above) identify any AULs, such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the *property* and/or have been filed or recorded against the *property* under federal, tribal, state or local law?

None.

3. Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28).

Do you have any specialized knowledge or experience related to the *property* or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the property or an *adjoining property* so that you would have specialized knowledge of the chemicals and processes used by this type of business?

None other than noted by the Environmental Professional.

4. Relationship of the purchase price to the fair market value of the *property* if it were not contaminated (40 CFR 312.29).

Does the purchase price being paid for this *property* reasonably reflect the fair market value of the *property*? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the *property*?

Not applicable as there is no change in ownership and, therefore, no purchase price.

5. Commonly known or *reasonably ascertainable* information about the *property* (40 CFR 312.30).

Are you aware of commonly known or *reasonably ascertainable* information about the *property* that would help the *environmental professional* to identify conditions indicative of releases or threatened releases? For example,

(a.) Do you know the past uses of the *property*?
(b.) Do you know of specific chemicals that are present or once were present at the *property*?
(c.) Do you know of spills or other chemical releases that have taken place at the *property*?
(d.) Do you know of any environmental cleanups that have taken place at the *property*?

None other than noted by the Environmental Professional.

6. The degree of obviousness of the presence or likely presence of contamination at the *property*, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).

Based on your knowledge and experience related to the *property* are there any *obvious* indicators that point to the presence or likely presence of releases at the *property*?

None.

III. ADDITIONAL REQUESTED INFORMATION

The following information is intended to assist the environmental professional in preparing the Phase 1 ESA but is not necessarily required to qualify for one of the LLPs.

1. State the reason why this Phase 1 ESA is required/requested:

Owner requests demolition of the two properties

2. State the type of *property* and type of *property* transaction, for example, sale, purchase, exchange, etc.

Residential property purchase.

3. State the complete and correct address for the *property* (a map or other documentation showing *property* location and boundaries is helpful, if not already provided):

   429-431 and 435-437 South San Joaquin Street, Stockton, CA APN: 149-066-070

4. State the scope of services desired for the Phase 1 ESA, including whether any parties to the *property* transaction may have a required standard scope of services on whether any considerations beyond the requirements of an AAI Phase 1 ESA are to be considered:

   None other than ASTM E 1527-13 Phase I ESA.

5. Identify all parties, if known, who will rely on the Phase 1 ESA Report:

   None.

6. Identify the site contact and how the contact can be reached:

   Myself or the Environmental Professional

7. List any special terms and conditions which must be agreed upon by the *environmental professional*:

   None.

8. Provide any other knowledge or experience with the *property* that may be pertinent to the *environmental professional*, for example, copies of any available prior *environmental site assessment reports*, documents, correspondence, etc., concerning the *property* and its environmental condition:

   None.

Please return your completed questionnaire to:

Alex Dewitt, PG
Condor Earth Technologies, Inc.
188 Frank West Circle, Suite I
Stockton, CA 95206
209-234-0518
adewitt@condorearth.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT
HAZARDOUS MATERIALS QUESTIONNAIRE

This questionnaire has been prepared by Condor Earth Technologies, Inc. (Preparer) by request of the prospective purchaser of the property. You are receiving this questionnaire because your property is being evaluated for potential hazardous materials pursuant to the due diligence process. In order to determine if hazardous materials may be present in soil, groundwater, or in building materials, all reasonably obtainable information must be solicited from persons knowledgeable about the history of the property. Hazardous materials include agricultural chemicals, petroleum products (oils and fuels), and unknown chemical spills. The questionnaire is voluntary on your part, as part of the customary practice we are conducting. Please respond to the best of your ability at your earliest convenience. When responding in the affirmative please circle or indicate property or adjoining property. To provide additional information, please describe reason for any affirmative answers on a separate sheet of paper. If you have questions, please contact Alex Dewitt at (209) 601-4631. Thank you for your attention to this matter.

	QUESTION	OBSERVED DURING SITE VISIT	OWNER	OCCUPANTS
1.	To the best of your knowledge, has the *property* or any *adjoining property* used for an industrial use presently or in the past?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
2.	To the best of your knowledge has the *property* or any *adjoining property* been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
3.	Are there currently, or to the best of your knowledge have there been previously, any damaged or discarded automobile or industrial batteries, or pesticides, paints, or other chemicals in individual containers of greater than 5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____

Initials: LBC

	QUESTION	OBSERVED DURING SITE VISIT	OWNER	OCCUPANTS
4.	Are there currently, or to the best of your knowledge have there been previously, any industrial *drums* (typically 55 gal [208 L]) or sacks of chemicals located on the property or at the facility? **Empty 55-gallon drums used for trash cans.**	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
5.	Has *fill dirt* been brought onto the property that originated from a contaminated site or that is of an unknown origin?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
6.	Are there currently, or to the best of your knowledge have there been previously, any *pits, ponds, or lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
7.	Is there currently, or to the best of your knowledge have there been previously, any stained soil on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
8.	Are there currently, or to the best of your knowledge have there been previously, any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
9.	Are there currently, or to the best of your knowledge have there been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
10.	Are there currently, or to the best of your knowledge have there been previously, any flooring, drains, or walls located within the facility that are stained by substances other than water or are emitting foul odors?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____

Initials: LBC

	QUESTION	OBSERVED DURING SITE VISIT	OWNER	OCCUPANTS
11.	Are there currently, or to the best of your knowledge have there been previously, any wells pipes open to the subsurface, or sumps located on the property.	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
12.	Does the *owner* or *occupant* of the *property* have any knowledge of *environmental liens* or governmental notification relating to the past or recurrent violations of environmental laws with respect to the *property* or any facility located on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
13.	Has the *owner* or *occupant* of the *property* been informed of the past or current existence of *hazardous substances* or petroleum *products* or environmental violations with respect to the *property* or any facility located on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
14.	Does the *property* discharge wastewater on or adjacent to the *property* other than storm water into a sanitary sewer system?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
15.	To the best of you knowledge, have any *hazardous substances* or *petroleum products*, unidentified waste materials, tires, automotive or industrial batteries or any other waste materials been dumped above grade, buried and/or burned on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____
16.	Is there a transformer, capacitor, or any hydraulic equipment for which there are any records indicating the presence of PCB's on the *property*?	Yes _____ No ___X___ Unknown ____	Yes _____ No ___X___ Unknown ____	Yes _____ No _____ Unknown ____

Initials: LBC

The **preparer** of this form must complete the following required information.

This questionnaire was completed by:

Name: Luke Castle

Title: Associate Geologist

Firm: Condor Earth

Address: 188 Frank West Circle, Stockton, CA 95206

Phone Number: 209.536.7379

Date: 8/18/2021

If the preparer is different than the user, complete the following:

Name of User: _____

Address of User: _____

Phone Number of User: _____

Relationship of Preparer to Site: _____

Relationship of Preparer to User

_____ Principal
_____ Employee
_____ Agent
_____ Consultant
_____ Other: _____

Preparer represents that to the best of his/her knowledge the above statements and facts are true and correct and to the best of his/her actual knowledge no material facts have been suppressed or misstated.

Date: 8/18/2021 Name: Luke Castle

Title: Associate Geologist

APPENDIX F

Proposal and Scope of Work
PHASE I ENVIRONMENTAL SITE ASSESSMENT

NEW LIFE MEN'S FACILITY
429 S. SAN JOAQUIN STREET
STOCKTON, CALIFORNIA

July 7, 2021
CET # 8639

INTRODUCTION

Condor Earth (Condor) will perform a Phase I Environmental Site Assessment (ESA) on property located at 429 S. San Joaquin Street, Stockton, California. The Phase I ESA will be conducted for Base Camp Environmental, Inc. (Client). The subject property is designated as Assessor's Parcel Number (APN) 149-066-07 (Site). Condor will follow the guidelines set forth in Practice E 1527-13, *Standard of Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process,* published November 2013, by the American Society for Testing and Materials (ASTM), hereinafter referred to as "the Standard." After completion, Condor will deliver a comprehensive Phase I ESA report to the Client for the Site.

PHASE I ENVIRONMENTAL SITE ASSESSMENT

The purpose of each ASTM Phase I ESA is to assist the Client with appropriate inquiry into the previous ownership and uses of the property to satisfy this element of the *innocent landowner, contiguous property owner,* or *bona fide prospective purchaser* limitations on Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability: "*landowner liability protections*" or "*LLPs.*" It should be understood that a Phase I ESA is a preliminary investigation of the Site. In the event that hazardous substances are found during the course of a Phase I ESA, or if any conditions suggesting the possibility that such substances exist, Condor recommends that a Phase II ESA be performed to further investigate existing or potential contamination. Condor will perform the four tasks listed below, which include an historical research and records review, Site reconnaissance, limited interviews, and report preparation.

Task 1. Historical Records Review

The history of the Site will be reviewed to learn about permits granted, citations issued, uses of the Site, and properties immediately adjacent to the Site. Reasonably obtainable topographic maps, real estate maps, and aerial photos will also be reviewed to assess land uses at and near the Site. If the above records are not obtainable at a reasonable cost, Condor will inform the Client of their unavailability.

Records retained by federal, state, and local agencies for properties within an approximate minimum search distance (MSD) will be reviewed for potential environmental liability. Parallel with the Standard, only non-confidential, reasonably obtainable, and practically reviewable records will be reviewed.

Client's (User's) Responsibilities

According to the Standard, it is the end user's responsibility to identify the reason why the user wants to have the Phase I ESA performed; to report to Condor any identified activity and use limitations (AULs) or environmental liens (reasonably ascertainable Title and Judicial records); and to communicate any actual knowledge and/or any commonly known or reasonably ascertainable information of environmental liens or AULs, and any specialized knowledge or experience, in regards to recognized environmental conditions, the user is aware of **before** the site reconnaissance.

Provision of Helpful Documents
According to the Standard, the property owner, the key site manager, and/or the user shall make known to Condor if any helpful documents (listed below) are reasonably available (and any other documents applicable/relating to the current and historical environmental and use conditions of the site) for review **prior** to the site reconnaissance. The following list is not totally inclusive:

- Environmental site assessment and compliance audit reports;
- Environmental permits (wastewater, hazardous waste disposal, NPDES, etc.);
- Registrations for underground and aboveground storage tanks;
- Registrations for underground injection systems;
- Material safety data sheets;
- Community right-to-know plans;
- Safety and/or prevention plans;
- Hydrogeologic reports;
- Driller/well reports;
- Notices or correspondence from any governmental agencies in regards to violations of environmental laws or liens;
- Hazardous waste generator notices/reports;
- Geotechnical studies;
- Risk assessments; and
- Recorded activity and use limitations.

Task 2. Site Reconnaissance

A visit to the Site will be made and a current description of the Site, including existing observable structures, roads, potable water supply systems, sewage disposal systems, and uses of the Site will be developed. Observations will be made on the Site, along the periphery of the Site, along the periphery of all structures on the Site, and in all areas common to the Site and adjacent properties, to assess if conditions suggest that hazardous substances are present on, or might migrate to the Site. Consistent with the Standard, the observations made during the Site visits will be limited to visual and/or physical observations in these areas where practical and/or unobstructed. Obvious terrain characteristics of concern, such as areas of distressed vegetation, ground stains, landfills, and depressions will also be identified. If accessible, the interior of any structures on the Site will also be inspected. Observations of the properties located immediately adjacent to the Site will be made from the Site and from public right-of-ways to assess whether there exists on such properties, potential sources of regulated materials that could lead to adverse environmental impacts to the Site.

Upon request by the Client, Condor will orally report specific areas of environmental concern where testing and/or subsurface investigations are required or recommended.

Task 3. Interviews

Interviews will be conducted, if reasonably possible, with present and past owners of the Site, operators, and occupants (as applicable) familiar with the Site, to evaluate the nature and extent of current and past activities on the Site and on the properties in the vicinity of the Site. The Client will be responsible for securing permission for Condor to interview the aforementioned persons. If Condor is unable to contact the aforementioned persons for any reason, Condor will inform the Client. If reasonably obtainable, interviews will also be held with representatives of state and/or local agencies.

Task 4. Evaluation and Report Preparation

Condor will provide a summary of the key issues and observations to the Client in the form of an oral report, upon request. A written report of the findings of the assessment will be prepared upon completion of Tasks 1 through 3 for the Site. The report will include information to support the conclusions reached by Condor that relate to the environmental condition of the Site, and to the potential environmental liability, if any, imposed by the Site or by neighboring properties within the search area. The deliverables will include up to one hard copy and one electronic copy of the report. Additional hard copies can be included for additional fees if requested.

EXCLUSIONS FROM SCOPE OF WORK

Chain of Title

This scope of work excludes research into the title history of the Site. Condor has learned that its clients are better served by engaging a professional title company to complete research into the title history of a property. Condor will review the title history of the Site, if provided by the Client, as part of the Site use histories. In order to fully comply with the Standard, the Client should review reasonably ascertainable recorded land title records and lien records for environmental liens or activity and use limitations.

Other Non-CERCLA Considerations

There may be risks associated with some potential hazards at some properties that parties to a real estate transaction may elect to assess, even though the hazards are not included in CERCLA's definitions of hazardous substances and are not subject to incurrence of response costs under CERCLA. Those substances include, but are not necessarily limited to:

1. Asbestos,
2. Mold,
3. Radon, and
4. Lead-based paint

The scope of work for this assessment specifically recognizes that evaluation of these non-CERCLA substances is excluded from consideration. Condor is, however, willing to negotiate a modified scope of work and cost for this investigation if an evaluation for these substances is required.

SITE ACCESS AND SITE CONDITIONS

The Client will grant or obtain free access to the Site for all equipment and personnel necessary for Condor to perform the work set forth in this Scope of Work. The Client will notify any and all possessors of the project Site that the Client has granted Condor free access to the Site.

DISCOVERY OF UNANTICIPATED HAZARDOUS MATERIALS

Condor agrees to notify the Client when unanticipated hazardous materials or suspected hazardous materials are encountered. The Client agrees to make any disclosures required by law to the appropriate governing agencies. The Client also agrees to hold Condor harmless for any and all consequences of disclosures made by Condor or the Client, which are required by governing law. In the event the project Site are not owned by the Client, the Client recognizes that it is the Client's responsibility to inform the property owner of the discovery of unanticipated hazardous materials or suspected hazardous materials.

Notwithstanding any other provision of this Scope of Work, the Client waives any claim against Condor and, to the maximum extent permitted by law, agrees to defend, indemnify, and save Condor harmless from any claim, liability, and/or defense costs for injury or loss arising from Condor's discovery of unanticipated hazardous materials or suspected hazardous materials, including, but not limited to, any costs created by delay of the project and any costs associated with possible reduction of the property's value.

LIMITATIONS

The purpose of a Phase I ESA is not to prove that no hazardous materials are present at the Site, but it is intended to assist the Client with appropriate inquiry into the previous ownership and uses of the property to satisfy this element of the *LLPs* to Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability. The use of an environmental professional will minimize and manage the risk of environmental difficulty, but it cannot completely eliminate the risk.

Condor will not warrant or certify that the Site is free of contaminants, because it is impossible to know if such a condition exists. Contaminants may be present in areas that are not accessible for inspection or sampling. Contaminants can migrate later into areas that are inspected or sampled during the ESA. A prudent and professional consultant can only supply an opinion and cannot certify that certain conditions exist when it is impossible to know that such conditions exist.

ESTIMATED SCHEDULE

Condor will commence Site assessment activities upon receipt of a signed contract for this work. Condor will complete the Scope of Work within seven weeks. Every effort will be made to complete the assessment report as soon as possible.

APPENDIX G

GLOSSARY OF TERMS AND ACRONYMS

abandoned property – *property* that can be presumed to be deserted, or an intent to relinquish possession or control can be inferred from the general disrepair or lack of activity thereon such that a reasonable person could believe that there was an intent on the on the part of the current *owner* to surrender rights to the *property*.

activity and use limitations – legal or physical restrictions or limitations on the use of, or access to, a site or facility: (1) to reduce or eliminate potential exposure to *hazardous substances* or *petroleum products* in the soil or groundwater on the *property*, or (2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or *engineering controls*, are intended to prevent adverse impacts to individuals or populations that may be exposed to *hazardous substances* and *petroleum products* in the soil, soil vapor, groundwater, and/or surface water on the *property.*

actual knowledge - the knowledge actually possessed by an individual who is a real person, rather than an entity. Actual knowledge is to be distinguished from constructive knowledge, that is, knowledge imputed to an individual or entity.

adjoining properties - any real *property* or properties the border of which is contiguous or partially contiguous with that of the *property*, or that would be contiguous or partially contiguous with that of the *property* but for a street, road, or other thoroughfare separating them.

aerial photographs – photographs taken from an aerial platform with sufficient resolution to allow identification of development and activities of areas encompassing the *property*. *Aerial photographs* are often available from government agencies or private collections unique to a local area.

all appropriate inquiry – that inquiry constituting "*all appropriate inquiry* into the previous ownership and uses of the *property* consistent with good commercial or customary practice" as defined in CERCLA, 42 USC § 9601 (35)(B) that will qualify a party to a *commercial real estate transaction* for one of the threshold criteria for satisfying the *LLPs* to CERCLA, (42 USC §9601(A) and (B) and 9607(b)(3), §9607(q); and §9607(r)) liability assuming compliance with other elements of the defense.

antecedent environmental liabilities - Liabilities that arise from a problem that is solely the result of a previous third party's activities, and yet attach to a subsequent owner and/or operator of a property.

approximate minimum search distance – the area for which records must be obtained and reviewed pursuant to Section 8 subject to the limitations provided in that section. This may include areas outside the *property* and shall be measured from the nearest *property* boundary. This term is used in lieu of radius to include irregularly shaped properties.

bona fide prospective purchaser liability protection – (42 USC §9607(r)) – a person may qualify as a bona fide prospective purchaser if, among other requirements, such person made "all appropriate inquiries into the previous ownership and uses of the facility in accordance with generally accepted good commercial and customary standards and practices." Knowledge of contamination resulting from *all appropriate inquiry* would not generally preclude this liability protection. A person must make *all appropriate inquiries* on or before the date of purchase. The facility must have been purchased after January 11, 2002.

Brownfields Amendments – amendments to CERCLA pursuant to the Small Business Liability Relief and Brownfields Revitalization Act, Pub. L. No. 107-118 (2002), 42 USC §§9601 *et seq*.

building department records – those records of the local government in which the *property* is located indicating permission of the local government to construct, alter, or demolish improvements on the *property*.

business environmental risk – a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of *commercial real estate*, not necessarily limited to those environmental issues required to be investigated.

commercial real estate - any real *property* except a *dwelling* or *property* with no more than four *dwelling* units exclusively for residential use (except that a *dwelling* or *property* with no more than four *dwelling* units exclusively for residential use is included in this term when it has a commercial function, as in the building of such *dwellings* for profit). The term includes but is not limited to undeveloped real *property* and real *property* used for industrial, retail, office, agricultural, other commercial, medical, or educational purposes; *property* used for residential purposes that has more than four residential *dwelling* units; and *property* with no more than four *dwelling* units for residential use when it has a commercial function, as in the building of such *dwellings* for profit.

commercial real estate transaction – a transfer of title to or possession of real *property* or receipt of a security interest in real *property*, except that it dos not include transfer of title to or possession of real *property* with respect to an individual *dwelling* or building containing fewer than five *dwelling* units, nor does it include the purchase of a lot or lots to construct a *dwelling* for occupancy by a purchaser, but a *commercial real estate* transaction does include real *property* purchased or leased by persons or entities in the business of building or developing *dwelling* units.

Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) – the list of sites compiled by EPA that EPA has investigated or is currently investigating for potential *hazardous substance* contamination for possible inclusion on the *National Priorities List*.

construction debris – concrete, brick, asphalt, and other such building materials discarded in the construction of a building or other improvement to *property*.

contaminated public wells – public wells used for drinking water that have been designated by a government entity as contaminated by *hazardous substances* (for example, chlorinated *solvents*), or as having water unsafe to drink without treatment.

contiguous property owner liability protection – (42 USC §9607(q)) – a person may qualify for the *contiguous property owner liability protection* if, among other requirements, such person owns real *property* that is contiguous to, and that is or may be contaminated by *hazardous substances* from real *property* that is not owned by that person. Furthermore, such person conducted *all appropriate inquiry* at the time of acquisition of the *property* and did not know or have reason to know that the *property* was or could be contaminated by a release or threatened release from the contiguous *property*. The *all appropriate inquires* must not result in knowledge or contamination. If it does, then such person did "know" or "had reason to know" of contamination and would not be eligible for the *contiguous property owner liability protection*.

controlled recognized environmental condition – a *recognized environmental condition* resulting from a past *release* of *hazardous substances* or *petroleum products* that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, *property* use restrictions, *activity and use limitations*, *institutional controls*, or *engineering controls*).

CORRACTS list – a list maintained by EPA of *hazardous waste* treatment, storage, or disposal facilities and other RCRA-regulated facilities (due to past interim status or storage of *hazardous waste* beyond 90 days) that have been notified by the US Environmental Protection Agency to undertake corrective action under RCRA. The *CORRACTS list* is a subset of the EPA database that manages RCRA data.

data failure – a failure to achieve the historical research objectives even after reviewing the *standard historical sources* that are *reasonably ascertainable* and likely to be useful.

data gap – a lack or inability to obtain information required despite *good faith* efforts by the *environmental professional* to gather information. *Data gaps* may result from incompleteness in and of the activities required by this practice, including, but not limited to *site reconnaissance* (for example, an inability to conduct the *site visit*), and *interviews* (for example, an inability to interview the *key site manager*, regulatory officials, etc.).

de minimis condition – a condition that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis conditions* are not *recognized environmental conditions* nor *controlled recognized environmental conditions.*

demolition debris – concrete, brick, asphalt, and other such building materials discarded in the demolition of a building or other improvement to *property*.

drum – a container (typically, but not necessarily, holding 55 gal (208 L) of liquid) that may be used to store *hazardous substances* or *petroleum products*.

dry wells – underground areas where soil has been removed and replaced with pea gravel, coarse sand, or large rocks. *Dry wells* are used for drainage, to control storm runoff, for the collection of spilled liquids (intentional and non-intentional) and *wastewater* disposal (often illegal).

due diligence - the process of inquiring into the environmental characteristics of a parcel of *commercial real estate* or other conditions, usually in connection with a *commercial real estate* transaction. The degree and kind of *due diligence* vary for different properties and differing purposes.

dwelling – structure or portion thereof used for residential habitation.

engineering controls (EC) – physical modifications to a site or facility (for example, capping, slurry walls, or point of use water treatment) to reduce or eliminate the potential for exposure to *hazardous substances* or *petroleum products* in the soil or groundwater on the *property*. *Engineering controls* are a type of activity and use limitation (AUL).

environmental compliance audit – the investigative process to determine if the operations of an existing facility are in compliance with applicable environmental laws and regulations. This term should not be

used to describe this practice, although an *environmental compliance audit* may include an *environmental site assessment* or, if prior audits are available, may be part of an *environmental site assessment*.

environmental lien – a charge, security, or encumbrance upon title to a *property* to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of *hazardous substances* or *petroleum products* upon a *property*, including (but not limited to) liens imposed pursuant to CERCLA 42 USC §§9607(l) & 9607(r) and similar state or local laws.

environmental professional – a person meeting the education, training, and experience requirements as set forth in 40 CFR §312.10(b). The person may be an independent contractor or an employee of the *user*.

environmental site assessment (ESA) - the process by which a person or entity seeks to determine if a particular parcel of real *property* (including improvements) is subject to *recognized environmental conditions*. At the option of the *user*, an *environmental site assessment* may include more inquiry than that constituting *all appropriate inquiry* or, if the *user* is not concerned about qualifying for the *LLPs*, less inquiry than that constituting *all appropriate inquiries*. An *environmental site assessment* is both different from, and less rigorous than, an *environmental compliance audit*.

***ERNS** list* – EPA's emergency response notification system list of reported CERCLA *hazardous substance releases* or spills in quantities greater than the reportable quantity, as maintained at the National Response Center. Notification requirements for such *releases* or spills are codified in 40 CFR Parts 302 and 355.

Federal Register, (FR) – publication of the United States government published daily (except for federal holidays and weekends) containing all proposed and final regulations and some other activities of the federal government. When regulations become final, they are included in the Code of Federal Regulations (CFR), as well as published in the *Federal Register*.

fill dirt – dirt, soil, sand, or other earth, that is obtained off-site, that is used to fill holes or depressions, create mounds, or otherwise artificially change the grade or elevation of real *property*. It does not include material that is used in limited quantities for normal landscaping activities.

fire insurance maps – maps produced for private fire insurance map companies that indicate uses of properties at specified dates and that encompass the *property*. These maps are often available at local libraries, historical societies, private resellers, or from the map companies who produced them.

good faith – the absence of any intention to seek an unfair advantage or to defraud another party; an honest and sincere intention to fulfill one's obligations in the conduct or transaction concerned.

hazardous substance - a substance defined as a hazardous substance pursuant to CERCLA 42 USC §9601(14), as interpreted by EPA regulations and the courts: "(A) any substance designated pursuant to section 1321(b)(2)(A) of Title 33, (B) any element, compound, mixture, solution, or substance designated pursuant to 9602 of this title, (C) any *hazardous waste* having the characteristics identified under or listed pursuant to section 3001 of the Resource Conservation and Recovery Act of 1976 (RCRA), as amended, (42 USC §6921) (but not including any waste the regulation of which under RCRA (42 USC §§6901 *et seq.*) has been suspended by Act of Congress), (D) any toxic pollutant listed under section 1317(a) of Title 33, (E) any hazardous air pollutant listed under section 112 of the Clean Air Act (42 USC §7412), and (F) any imminently hazardous chemical substance or mixture with respect to which the Administrator (of EPA) has taken action pursuant to section 2606 of Title 15. The term does not include petroleum, including crude oil or any fraction thereof which is not otherwise specifically listed or designated as a

hazardous substance under subparagraphs (A) through (F) of this paragraph, and the term does not include natural gas, natural gas liquids, liquefied natural gas, or synthetic gas usable for fuel (or mixtures of natural gas and such synthetic gas)."

hazardous waste - any *hazardous waste* having the characteristics identified under or listed pursuant to Section 3001 of RCRA, as amended, (42 USC §6921) (but not including any waste the regulation of which under RCRA (42 USC §§6901 – 6992k) has been suspended by Act of Congress). RCRA is sometimes also identified as the Solid Waste Disposal Act. RCRA defines *hazardous waste*, at 42 USC §6903, as: "a solid waste, or combination of solid wastes, which because of it's quantity, concentration, or physical, chemical, or infectious characteristics may - (A) cause, or significantly contribute to an increase in mortality or an increase in serious irreversible, or incapacitating illness; or (B) pose a substantial present or potential hazard to human health or environment when improperly treated, stored, transported, or disposed of, or otherwise managed."

hazardous waste/contaminated sites – sites on which a release has occurred, or is suspected to have occurred, of any *hazardous substance*, *hazardous waste*, or *petroleum products*, and that *release* or suspected *release* has been reported to a government entity.

historical recognized environmental condition – a past *release* of any *hazardous substances* or *petroleum products* that has occurred in connection with the *property* and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the *property* to any required controls (for example, *property* use restrictions, *activity use limitations, institutional controls,* or *engineering controls*).

IC/EC registries – databases of *institutional controls* or *engineering controls* that may be maintained by a federal, state or local environmental agency for purposes of tracking sites that may contain residual contamination and AULs. The names of these may vary from program to program and state to state, and include terms such as Declaration of Environmental Use Restriction database (Arizona), list of "deed restrictions" (California), environmental real covenants list (Colorado), Brownfields site list (Indiana, Missouri) and the Pennsylvania Activity and Use Limitation (PA AUL) Registry.

innocent landowner defense – (42 USC §9601(35) and §9607(b)(3)) – a person may qualify as one of three types of innocent landowners: (i) a person who "did not know and had no reason to know" that contamination existed on the *property* at the time the purchaser acquired the *property*; (ii) a government entity which acquired the *property* by escheat, or through any other involuntary transfer of acquisition, or through the exercise of eminent domain authority by purchase or condemnation; and (iii) a person who "acquired the facility by inheritance or bequest." To qualify for the innocent landowner defense, such person must have made *all appropriate inquiries* on or before the date of purchase. Furthermore, the *all appropriate inquiries* must not have resulted in knowledge of the contamination. If it does, then such person did "know" or "had reason to know" of contamination and would not be eligible for the *innocent landowner defense*. There are other necessary requirements that are beyond the scope of ASTM E1527-13.

institutional controls (IC) – a legal or administrative restriction (for example, "deed restrictions," restrictive covenants, easements, or zoning) on the use of, or access to, a site or facility to *(1)* reduce or eliminate potential exposure to *hazardous substances* or *petroleum products* in the soil or groundwater on the property, or *(2)* to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. An *institutional control* is a type of *Activity and Use Limitation (AUL).*

interviews – those portions of this practice that address questions to be asked of past and present *owners, operators*, and *occupants* of the *property* and questions to be asked of local government officials.

key site manager – the person identified by the *owner* or *operator* of a *property* as having good knowledge of the uses and physical characteristics of the *property*.

landfill - a place, location, tract of land, area, or premises used for the disposal of solid wastes as defined by state solid waste regulations. The term is synonymous with the term *solid waste disposal site* and is also known as a garbage dump, trash dump, or similar term.

Landowner Liability Protections (LLPs) – *landowner liability protections* under CERCLA; these protections include the *bona fide prospective purchaser liability protection, contiguous property owner liability protection*, and *innocent landowner defense* from CERCLA liability. See 42 USC §§9601(35)(A), 9601(40), 9607(b), 9607(q), 9607(r).

local government agencies – those agencies of municipal or county government having jurisdiction over the *property*. Municipal and county governments include but are limited to cities, parishes, townships, and similar entities.

local street directories – directories published by private (or sometimes government) sources that show ownership, occupancy, and/or use of sites by reference to street addresses. Often *local street directories* are available at libraries, or historical societies, and/or local municipal offices.

LUST sites – state lists of leaking *underground storage tank* sites. RCRA gives EPA and states, under cooperative agreements with EPA, authority to clean up *releases* from UST systems or require *owners* and *operators* to do so (42 USC §6991b).

major occupants – those tenants, subtenants, or other persons or entities each of which uses at least 40% of the leasable area of the *property* or any anchor tenant when the *property* is a shopping center.

material safety data sheets (MSDS) – written or printed material concerning a *hazardous substance* which is prepared by chemical manufacturers, importers, and employers for hazardous chemicals pursuant to OSHA's Hazard Communication Standard, 29 CFR §1910.1200.

material threat – a physically observable or *obvious* threat which is reasonably likely to lead to a *release* that, in the opinion of the *environmental professional*, is threatening and might result in impact to public health or the environment. An example might include an aboveground storage tank system that contains a *hazardous substance* and which shows evidence of damage. The damage would represent a *material threat* if it is deemed serious enough that it may cause or contribute to tank integrity failure with a *release* of contents to the *environment*.

Migrate/migration – for the purposes of ASTM E1527-13 "migrate" and "migration" refers to the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in subsurface.

National Contingency Plan (NCP) – the National Oil and Hazardous Substances Pollution Contingency Plan, found at 40 CFR Part 300, that is the EPA's blueprint on how *hazardous substances* are to be cleaned up pursuant to CERCLA.

National Priorities List (NPL) – list compiled by the EPA pursuant to CERCLA 42 USC §9605(a)(8)(B) of properties with the highest priority for cleanup pursuant to EPA's Hazard Ranking System (40 CFR Part 300).

obvious – that which is plain or evident; a condition or fact that could not be ignored or overlooked by a reasonable observer while visually or physically observing the *property*.

occupants - those tenants, subtenants, or other persons or entities using the *property* or a portion of the *property*.

operator – the person responsible for the overall operation of a facility.

other historical sources – any source or sources that are credible to a reasonable person and that identify past uses of the *property*. The term includes, but is not limited to: miscellaneous maps, newspaper archives, internet sites, community organizations, local libraries, historical societies, current *owners* or *occupants* of neighboring properties, and records in the files and/or personal knowledge of the *property owner* and/or *occupants*.

owner - generally the fee *owner* of record of the *property*.

petroleum exclusion – the exclusion from CERCLA liability provided in 42 USC §9601(14), as interpreted by the courts and EPA: "the term (*hazardous substance*) does not include petroleum, including crude oil or any fraction thereof which is not otherwise specifically listed or designated as the *hazardous substance* under subparagraphs (A) through (F) of this paragraph, and the term does not include natural gas, natural gas liquids, liquefied natural gas, or synthetic gas usable for fuel (or mixtures of natural gas and such synthetic gas)."

petroleum products - those substances included within the meaning of the *petroleum exclusion* to CERCLA, 42 USC §9601(14), as interpreted by the courts and the EPA, that is: petroleum, including crude oil or any fraction thereof which is not otherwise specifically listed or designated as a *hazardous substance* under the Subparagraphs (A) through (F) of 42 USC §9601(14), natural gas, natural gas liquids, liquefied natural gas, and synthetic gas usable for fuel (or mixtures of natural gas and such synthetic gas). (The word fraction refers to certain distillates of crude oil, including gasoline, kerosene, diesel oil, jet fuels, and fuel oil, pursuant to Standard Definitions of Petroleum Statistics) (American Petroleum Institute, Fourth Edition, 1995.)

physical setting sources – sources that provide information about the geologic, hydrogeologic, hydrologic, or topographic characteristics of a *property*.

pits, ponds, or lagoons – man-made or natural depressions in a ground surface that are likely to hold liquids or sludge containing *hazardous substances* or *petroleum products*. The likelihood of such liquids or sludge being present is determined by evidence of factors associated with the pit, pond, or lagoon, including, but not limited to, discolored water, distressed vegetation, or the presence of an *obvious wastewater* discharge.

practically reviewable - information that is *practically reviewable* means that the information is provided by the source in a manner and in a form that, upon examination, yields information relevant to the *property* without the need for extraordinary analysis of irrelevant data. The form of the information shall be such that the *user* can review the records for a limited geographic area. Records that cannot be feasibly retrieved by reference to the location of the *property* or a geographic area in which the *property* is located

are not generally *practically reviewable*. Most databases of public records are *practically reviewable* if they can be obtained from the source agency by the county, city, zip code, or other geographic area of the facilities listed in the record system. Records that are sorted, filed, organized, or maintained by the source agency only chronologically are not generally *practically reviewable*. Listings in *publically available* records which do not have adequate address information to be located geographically are not generally considered *practically reviewable*. For large databases with numerous records (such as RCRA hazardous waste generators and registered *underground storage tanks*), the records are not *practically reviewable* unless they can be obtained from the source agency in the smaller geographic area of zip codes. Even when information is provided by zip code for some large databases, it is common for an unmanageable number of sites to be identified within a given zip code. In these cases, it is not necessary to review the impact of all of the sites that are likely to be listed in any give zip code because that information would not be *practically reviewable.* In other words, when so much data is generated that it cannot be feasibly reviewed for its impact on the *property*, it is not *practically reviewable*.

property - the real *property* that is the subject of the *environmental site assessment* described in this practice. Real *property* includes buildings and other fixtures and improvements located on the *property* and affixed to the land.

property tax files – the files kept for *property* tax purposes by the local jurisdiction where the *property* is located and may include records of past ownership, appraisals, maps, sketches, photos, or other information that is *reasonably ascertainable* and pertaining to the *property*.

publicly available - information that is *publicly available* means that the source of information allows access to the information by anyone upon request.

RCRA generators – those persons or entities that generate *hazardous wastes*, as defined and regulated by RCRA.

RCRA generators list – list kept by EPA of those persons or entities that generate *hazardous wastes* as defined and regulated by RCRA.

RCRA TSD facilities – those facilities on which treatment, storage, and/or disposal of *hazardous wastes* takes place, as defined and regulated by RCRA.

RCRA TSD facilities list – list kept by EPA of those facilities on which treatment, storage, and/or disposal of *hazardous wastes* takes place, as defined and regulated by RCRA.

reasonably ascertainable - information that is *(1) publicly available*, *(2)* obtainable from its source within reasonable time and cost restraints, and *(3) practically reviewable*.

recognized environmental conditions – the presence or likely presence of any *hazardous substances* or *petroleum products* in, on, or at a *property:* (1) due to release to the environment; (2) under conditions indicative of a *release* to the *environment*; or (3) under conditions that pose a *material threat* of future *release* to the *environment. De minimis conditions* are not *recognized environmental conditions.*

recorded land title records – records of historical fee ownership, which may include leases, land contracts, and AULs on or of the *property* recorded in the place where land title records are, by law or custom, recorded for the local jurisdiction in which the *property* is located. (Often such records are kept by a municipal or county recorder or clerk.) Such records may be obtained from title companies or directly from the local government agency. Information about the title to the *property* that is recorded in a

US district court or any place other than where land title records are, by law or custom, recorded for the local jurisdiction in which the *property* is located, are not considered part of *recorded land title records*.

records of emergency release notifications EPCRA – (42 USC §11004) – requires *operators* of facilities to notify their local emergency planning committee (as defined in EPCRA) and state emergency response commission (as defined in EPCRA) of any *release* beyond the facility's boundary of any reportable quantity of any extremely *hazardous substance*. Often the local fire department is the local emergency planning committee. Records of such notifications are "Records of Emergency Release Notifications" (42 USC 11004).

records review – that part that is contained in Section 8 of ASTM E1527-13 that addresses which records shall or may be reviewed.

report – the written *report* prepared by the *environmental professional* and constituting part of a "*Phase I Environmental Site Assessment*," as required by this practice.

site reconnaissance – in connection with the *site visit*. The *site reconnaissance* includes, but is not limited to, the *site visit* done in connection with such a *Phase I Environmental Site Assessment*.

site visit – the visit to the *property* during which observations are made constituting the *site reconnaissance*.

solid waste disposal site - a place, location, tract of land, area, or premises used for the disposal of solid wastes as defined by state solid waste regulations. The term is synonymous with the term *landfill* and is also known as a garbage dump, trash dump, or similar term.

solvent – a chemical compound that is capable of dissolving another substance and may itself be a *hazardous substance*, used in a number of manufacturing/industrial processes including but not limited to the manufacture of paints and coatings for industrial and household purposes, equipment clean-up, and surface degreasing in metal fabricating industries.

standard environmental record sources – those records specified in 8.2.1 of ASTM E1527-13.

standard historical sources - those sources of information about the history of uses of property specified in the Records Review Section of the *Phase I Environmental Site Assessment* report.

standard physical setting source – a current *USGS 7.5 Minute Topographic Map* (if any) showing the area on which the *property* is located.

Standard practice – the activities set forth in ASTM E1527-13.

standard sources – sources of environmental, physical setting, or historical records.

state registered USTs – state lists of *underground storage tanks* required under Subtitle I, Section 9002 of RCRA.

sump – a pit, cistern, cesspool, or similar receptacle where liquids drain, collect, or are stored.

TSD facility – treatment, storage, or disposal facility.

underground injection – the emplacement or discharge of fluids into the subsurface by means of a well, improved sinkhole, sewage drain hole, subsurface fluid distribution system or other system, or groundwater point source.

underground storage tank (UST) – any tank, including underground piping connected to the tank, that is or has been used to contain *hazardous substances* or *petroleum products* and the volume of which is 10% or more beneath the surface of the ground.

user – the party seeking to use Practice E1527 to complete an *environmental site assessment* of the *property.* A *user* may include, without limitation, a potential purchaser of *property*, a potential tenant of *property*, an *owner* of *property*, a lender, or a *property* manager. The *user* has specific obligations for completing a successful application of this practice.

USGS 7.5 Minute Topographic Map – the map (if any) available from or produced by the United States Geological Survey, entitled "*USGS 7.5 Minute Topographic Map*," and showing the *property*.

visually and/or physically observed – during a *site visit* pursuant to this practice, this term means observations made by vision while walking through a *property* and the structures located on it and observations made by the sense of smell, particularly observations of noxious or foul odors. The term "walking through" is not meant to imply that disabled persons who cannot physically walk may not conduct a *site visit*; they may do so by the means at their disposal for moving through the *property* and the structures located on it.

wastewater - water that *(1)* is or has been used in an industrial or manufacturing process, *(2)* conveys or has conveyed sewage, or *(3)* is directly related to manufacturing, processing, or raw materials storage areas at an industrial plant. *Wastewater* does not include water originating on or passing through or adjacent to a site, such as stormwater flows, that has not been used in industrial or manufacturing processes, has not been combined with sewage, or is not directly related to manufacturing, processing, or raw materials storage areas at an industrial plant.

zoning/land use records – those records of the local government in which the *property* is located indicating the uses permitted by the local government in particular zones within its jurisdiction. The records may consist of maps and/or written records. They are often located in the planning department of a municipality or county.

Other Acronyms:

AST – Aboveground Storage Tank

AULs – *Activity and Use Limitations*

CERCLA - Comprehensive Environmental Response Compensation and Liability Act of 1980 (as amended, 42 USC §§9601 *et seq.*)

CERCLIS – Comprehensive Environmental Response, Compensation and Liability Information System (maintained by EPA)

CFR – Code of Federal Regulations

CORRACTS – facilities subject to Corrective Action under RCRA

DTSC – Department of Toxic Substances Control – California EPA

EPA – United States Environmental Protection Agency

EPCRA – Emergency Planning and Community Right to Know Act ((also known as SARA Title III), 42 USC §§11001-11050 *et seq.*

ERNS – emergency response notification system

ESA – Environmental Site Assessment (different than an *environmental compliance audit*)

FOIA – US Freedom of Information Act (5 USC §552 as amended by Public Law No. 104-231, 110 Stat.)

FR – Federal Register

ICs – *Institutional Controls*

LLP – Landowner Liability Protections under the *Brownfields Amendments*

LUST – Leaking Underground Storage Tank

MSDS – Material Safety Data Sheet

NCP – National Contingency Plan

NFRAP – former CRECLIS sites where no further remedial action is planned under CERCLA

NPDES – National Pollutant Discharge Elimination System

NPL – National Priorities List

PCBs – polychlorinated biphenyls

PRP – Potentially Responsible Party (pursuant to CERCLA 42 USC §9607(a))

RCRA – Resource Conservation and Recovery Act (as amended, 42 USC §§6901 *et seq*.)

SARA – Superfund Amendments and Reauthorization Act of 1986 (amendment to CERCLA)

TSDF – *hazardous waste* treatment, storage or disposal facility

USC – United States Code

USGS – United States Geological Survey

UST – Underground Storage Tank

APPENDIX H

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #_____
HRI #_____
Trinomial_____
NRHP Status Code 3S, 3CS, 5S2
Other Listings_____
Review Code_____ Reviewer_____ Date_____

Resource name(s) or number (assigned by recorder) 435-437 S. San Joaquin Street

P1. Another Identifier: Wills House
***P2. Location:** ☐Not for Publication ☒Unrestricted ***a. County** San Joaquin
***b. USGS 7.5' Quad** Stockton West, CA **Date** 2018
***c. Address** 435-437 S. San Joaquin Street **City** Stockton **Zip** 95203
***e. Other Locational Data:** San Joaquin County Assessor's Parcel Number 149-066-070

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
435-437 S. San Joaquin Street is a two-story, wood-frame multiple-family residence that was built around 1904 in a mixture of Queen Anne and Colonial Revival styles. It is located on a 9,150-square-foot lot on the west side of S. San Joaquin Street between E. Sonora Street and E. Church Street. The building is located on the same parcel as 429-431 S. San Joaquin Street, a second multiple-family residence that was built at the same time in a similar architectural style. The building has a rectangular footprint and a moderately pitched front-gabled roof that is clad with composition shingles. The building is clad with wood lap siding and has a concrete foundation. Typical windows consist of wood sash windows with molded wood trim.

***P3b. Resource Attributes:** (list attributes and codes) HP3. Multiple family property

***P4. Resources Present:** ☒Building ☐Structure ☐Object ☐Site ☐District ☐Element of District ☐Other

P5a. Photo



P5b. Photo: (view and date)
Primary (northeast) façade, view south, October 11, 2019.

***P6. Date Constructed/Age and Sources:** ☒historic
ca. 1904, historic newspaper articles, city directories, Sanborn Map Co. fire insurance maps

***P7. Owner and Address:**
Gospel Center Rescue Mission, Inc.
445 S. San Joaquin St.
Stockton, CA 95203

***P8. Recorded by:**
Page & Turnbull, Inc.
2401 C Street, Ste. B
Sacramento, CA 95816

***P9. Date Recorded:**
October 11, 2019

***P10. Survey Type:**
Intensive

***P11. Report Citation:** None

***Attachments:** ☐None ☐Location Map ☐Sketch Map ☒Continuation Sheet ☒Building, Structure, and Object Record
☐Archaeological Record ☐District Record ☐Linear Feature Record ☐Milling Station Record ☐Rock Art Record
☐Artifact Record ☐Photograph Record ☐ Other (list)



Figure 1. Aerial photograph of 435-437 S. San Joaquin Street. Subject parcel outlined orange. Source: Google Earth 2019, edited by Page & Turnbull.

Northeast Façade
The primary, northeast façade features a projecting front-facing gable that is decorated with alternating carved wood modillions and dentils along the cornice (**Figure 2**). The gable end has a small rectangular window. A full-width porch projects from the first story of the building and has a flat roof with overhanging eaves that are decorated with wood modillions and dentils to match those of the roof above. The roof of the porch is supported by three wood Tuscan columns that are mounted on top of solid wood railings; the railings are clad with wood lap siding that has been covered with a brick veneer wall (**Figure 3**). At the south end of the façade, a set of poured concrete steps lead up to the porch and main entry. The entry consists of a pair of wood panel doors with integrated glazing set behind wood screen doors. A grouped window, consisting of two tall, narrow wood sash windows on each side of a wider wood sash window, completes the fenestration on the first story. On the second story, two wood sash windows frame a door opening that appears to have been filled in with plywood. The wood trim of these windows is more elaborate than those of the first story and has a projecting lintel decorated with dentils.

Southeast Façade
The southeast façade is partially obscured behind an adjacent one-story brick building at 445 S. San Joaquin Street (**Figure 4**). The façade has a molded wood drip course that separates the crawl space from the first floor above. Six windows are visible, three in the first floor and three in the second floor. The four windows at the west end of the façade have been altered; those in the first floor have been covered with plywood, while those in the second floor have been replaced with vinyl sash windows with flat wood trim. Sets of paired windows adjacent to the brick building appear to retain their original wood sashes (**Figure 5**). A small brick chimney is visible on the roof above.

Southwest Facade
The rear (southwest) façade features two stacked recessed entries, one above the other, on the first and second stories at the north end of the facade (**Figure 6**). The first-story entry consists of a wood panel door that is set at the back of a small recessed porch with poured concrete steps and solid wood railings (**Figure 7**). Hinges and an infilled transom indicate that the porch was once enclosed by an additional door. The second-story entry above is located at the top of a long, angled wood staircase with flat wood railings, wood support beams, and one intermediate landing. It contains a wood door with an infilled transom. Fenestration consists of two plywood access doors at the crawl space and a small rectangular wood sash window next to a taller rectangular

window on both the first and second stories. The taller window at the first story has been infilled with plywood and an air conditioning unit, while the bottom sash of both of the second-story windows have been replaced with vinyl sliders. Pipes and utility meters are attached to the south end of the façade. Four cylindrical metal chimneys are visible on the roof above.

Northwest Façade

The northwest façade begins with the northwest walls and supports of the front porch (**Figure 8**). At the main section of the façade, a molded wood drip course divides the crawl space from the first floor. A hinged access door has been cut into the crawl space siding at the east end of the façade, while a second crawl space opening has been covered with wire mesh and partially filled with bricks at the west end. The first and second stories feature identical window configurations. From left to right, they consist of a single wood sash window, followed by paired wood sash windows, and a shorter wood sash window. At the far west end of the façade, four unglazed openings open to the rear, first-story porch, while a set of paired wood sash windows open to the enclosed second-story entry above.



Figure 2. Gable end of northeast facade, view south.



Figure 3. Porch at northeast façade, view southwest.



Figure 4. The southeast façade, view northeast.




Figure 5. Altered windows at the east end of the southeast façade, view northeast.



Figure 6. Southwest façade, view northeast.



Figure 7. Rear porch, view east.



Figure 8. Northwest façade, view southwest.

Site Features

As previously mentioned, the subject building is one of two multiple family residences on the parcel. The second, addressed as 429-431 S. San Joaquin Street, appears to have been constructed at the same time as the subject building and is located directly to the northwest (**Figure 9**). The narrow space between the two buildings has been paved with concrete (**Figure 10**). Landscaping in front of the building consists of a small front yard with a lawn and small concrete patio that is enclosed by a tall metal fence along the front and northwest property lines (**Figure 11**). A concrete walkway extends from the sidewalk to the building's front entrance, and a narrow strip of brick pavers leads to a second concrete walkway that separates the subject building from the adjacent building on the lot. The rear portion of the lot is also paved with concrete, except for a small space immediately to the rear of 429-431 S. San Joaquin Street, in which trees have been planted. An outdoor seating area with wood picnic tables and a wood lattice covering is located at the southwest corner of the lot. The rest of the rear portion of the lot is used as a driveway and parking lot for the complex (**Figure 12**).



Figure 9. The subject property (left) and 429-431 S. San Joaquin Street, view northeast.



Figure 10. Concrete walkway between the subject property and 435-437 S. San Joaquin Street, view west.



Figure 11. Front yard, view north.



Figure 12. Paved area at the rear of the building, view northeast.

Surrounding Site Context

435-437 S. San Joaquin Street is located on the block bounded by S. San Joaquin Street to the northeast, E. Church Street to the southeast, S. Hunter Street to the southwest, and E. Sonora Street to the northwest in the heart of the original street grid of Stockton and one-and-one-half blocks south of the California State Route 4 highway. The surrounding area is characterized primarily by a mix of two- to three-story residential buildings and a few brick commercial buildings that appear to have been built around the turn of the twentieth century. 429-431 S. San Joaquin Street was constructed in the same style as the subject property around 1904 (**Figure 13**). The Gleason House, located directly to the northwest of the subject parcel at 423 S. San Joaquin Street, is a Queen Anne style house constructed in 1895 (**Figure 14**). 420 S. San Joaquin Street, directly across from the subject property, is a two-story, Queen Anne style house built in 1905 (**Figure 15**). Next door, 430 S. San Joaquin is a two-story vernacular style foursquare that was built in 1900 (**Figure 16**).



Figure 13. 435-437 S. San Joaquin Street, built 1904.



Figure 14. The Gleason House at 423 S. San Joaquin Street, built 1895.



Figure 15. 420 S. San Joaquin Street, built 1905.



Figure 16. 430 S. San Joaquin Street, built 1900.

BUILDING, STRUCTURE, AND OBJECT RECORD

***NRHP Status Code** 3S, 3CS, 5S2
***Resource Name or #** 435-437 S. San Joaquin Street

B1. Historic name: Wills House
B2. Common name: 435-437 S. San Joaquin Street
B3. Original Use: Multiple Family Residence
B4. Present use: Multiple Family Residence
***B5. Architectural Style:** Queen Anne/Colonial Revival
***B6. Construction History:** (Construction date, alterations, and date of alterations)

The parcel on which 435-437 S. San Joaquin Street is located was owned by Bee Hoult by 1900. Two earlier wood frame buildings that were present on the site at the time burned down in a fire that spread from the Agricultural Pavilion building, located two blocks north on Lafeyette Street between S. Hunter, and destroyed nearly six city blocks in September 1902.[1] The 1904 Stockton city directory records that Hoult's husband, David, was living at the adjacent building at 431 S. San Joaquin Street, indicating it had been completed by this time to replace the buildings that had been destroyed by the fire.[2] It is likely that the subject building was constructed at the same time. The 1917 fire insurance map by the Sanborn Map Company shows the building as a two-story wood frame building that consisted of two flats over a basement (**Figure 17**). It had a two-story porch that spanned the front façade and an angled exterior rear staircase. The 1950 Sanborn fire insurance map shows that by 1950, the building had been reconfigured into a two-and-one-half-story building, likely by converting the basement into livable space. No other changes are visible. (**Figure 18**). Aerial photographs from the 1930s and 1970s indicate that the overall footprint of the building has remained relatively unchanged over time (**Figure 19** and **Figure 20**). (See Continuation Sheet, page 8)

***B7. Moved?** ☒**No** ☐**Yes** ☐**Unknown Date:** N/A **Original Location:** N/A
***B8. Related Features:** _____ B9a. Architect: Unknown b. Builder: Unknown


***B10. Significance: Theme** Residential Architecture **Area** Stockton, California
Period of Significance 1904 **Property Type** Multiple-Family Residential **Applicable Criteria** C/3

City of Stockton
Native American through Early American Period:
Numerous Native American groups called the Central Valley home for thousands of years before the arrival of European and American settlers. The Stockton area was settled by the Yatchicumne, a group of the Northern Valley Yokuts people whose villages were established across a vast expanse of California from the confluence of the Sacramento and San Joaquin rivers as far as the Tehachapi Mountains, 250 miles to the south. At least two Yatchicumne villages were located in the Stockton area, including one called Pasasimas, situated on a mound near the Stockton Channel in present-day Downtown Stockton. (See Continuation Sheet, page 9)

B11. Additional Resource Attributes: (List attributes and codes)

***B12. References:** See Footnotes and Continuation Sheet, page 18
B13. Remarks: None
***B14. Evaluator:** Clare Flynn, Page & Turnbull, Inc.
***Date of Evaluation:** October 31, 2019

(This space reserved for official comments.)



Location Map: San Joaquin County Assessor's Office, 2019. Subject parcel shaded orange. Edited by Page & Turnbull.

[1] "Conflagration in the Heart of Stockton Leaves Record of Death and Injury, and Devastation of Wide Area," *The San Francisco Call*, September 30, 1902.
[2] Stockton, California, City Directory, 1904.

***B6. Construction History: (continued)**




Figure 17. Excerpt from 1917 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.




Figure 18. Excerpt from 1950 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.



Figure 19. 1930 aerial photograph, approximate subject location outlined in orange. Source: Fairchild Aerial Surveys, Flight C-975A, Frame Z-252, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 20. 1970 aerial photograph, approximate subject location outlined in orange. Source: Cartwright Aerial Surveys, Flight CAS-2874, Frame 102, collection of UC Santa Barbara Library. Edited by Page & Turnbull.

Google Street View images show that there was a balcony above the front porch in 2012. Sometime between 2012 and 2015, a railing around this balcony was removed, and a door opening that led from the second story interior to the balcony was infilled. Building permits on file at the City of Stockton Permit Center document repairs to the building's foundation and plumbing and electrical work. Additional alterations that are not documented in permits include window replacements, the addition of brick veneer cladding on the northwest façade, removal of the second-story balcony railing, and alterations to the rear porch.




Figure 21. The northwest facade in April 2012. Source: Google Street View, 2012.

Table 1. Permits on File at the City of Fremont Community Development Department

Permit Number	Date	Applicant	Description
31996	12/1949	Ila Stevenson	Foundation for apartment house
9599	6/9/1959	Illegible	Plumbing
66400	1/12/1987	Robert Hong	Electrical

***B10. Significance: (continued)**

Local rivers and streams provided an abundant source of food for the native population and also attracted European and American fur trappers to the area, who began exploring the area in the early nineteenth century in search of beaver and otter pelts.[3] These early explorers included Jedediah Strong Smith, who established a base camp to the southeast of present-day Stockton in 1827, and Alex McCleod, a fur trapper from the Hudson's Bay Company, whose camp near McCleod Lake gave the lake its name.[4] While the fur trappers reaped the benefits of the region's rich natural resources, they also brought diseases with them that led to the decimation of much of the local Native American population.[5]

The presence of French-Canadian fur trappers provided the inspiration for the name of the Mexican land grant that encompassed the present-day site of Stockton and its immediate vicinity during the Mexican period, after Mexico achieved independence from Spain in 1821. Rancho Campo de los Franceses, as the grant was known, was filled with numerous waterways, grassy hills, and oak trees. It was this landscape that German immigrant Captain Charles Maria Weber, founder of the city of Stockton, experienced when he traveled through the area on his way to San Jose in 1842.[6] Recognizing the area's potential, Weber and his business partner, Guillermo (William) Gulnac, acquired roughly 55 square kilometers of Rancho Campo de los Franceses on the east side of the San Joaquin River from the Mexican governor in 1843. Weber eventually bought Gulnac out of the land and built his first

[3] City of Stockton, "History: A Look into Stockton's Past," accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html; Lori Gilbert, "Our Diversity: Native Americans first to call Stockton home," *The Record*, November 29, 2014, accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.
[4] R. Coke Wood, "The Rise of Stockton," *San Joaquin Historian* IX, no. 1 (January-March 1973), San Joaquin County Historical Society, 2.
[5] Architectural Resources Group, Stockton Downtown Draft Historic Resources Survey, 2000, 6.
[6] Wood, 2.

structures on the site in 1847.[7] The first survey of the settlement, initially known as Tuleberg, was completed by Jasper O'Farrell the same year.[8]

Formation of Stockton

Like many cities in Northern California, Stockton grew from a small, rural outpost into a booming city as a result of the Gold Rush. When gold was discovered at Coloma in 1848, one year after Weber established the settlement of Tuleberg, he initially joined the fervor and spent months mining in the goldfields. He soon realized, however, that he had a better chance of making his fortune by selling goods and supplies to the floods of miners who were traveling into the area.[9] Advantageously located at the head of the Stockton Channel, a tributary of the San Joaquin River, Weber's settlement emerged as the gateway to and major supply center for California's southern mining areas as ships traveling from San Francisco brought streams of miners to the area (Error! Reference source not found.).[10]

As the settlement's population grew, so did urban development. In 1849, Major R. P. Hammond completed a second survey that laid out the first street grid between Weber Avenue, Center Street, Main Street, and Commerce Street.[11] In 1850, the same year the California achieved statehood, the settlement was officially incorporated as a city and renamed Stockton, after Commodore Robert F. Stockton, the American Navy officer who drove the last Mexican forces out of California in 1848.[12] Over the next five years, the city's population swelled from 1,000 to roughly 7,000. By the 1890s, it had exploded to approximately 23,000 residents.[13]

The streets between El Dorado Avenue, Main Street, Commerce Street, and Levee (now Weber) Avenue formed the core of the city's commercial area in the nineteenth century. The first residential districts, meanwhile, developed to the southwest and north. Floods were common in the winter months due to the city's location near miles of waterways that made up the Sacramento-San Joaquin River Delta.[14]

After the Gold Rush ended in the mid-1850s, the Central Valley's rich soil and temperate climate contributed to the development of Stockton into a major center for agricultural industries. Wheat and grains were the area's largest crop in the nineteenth century and spurred the construction of grain warehousing facilities and flour mills in the area, including the Sperry Flour Company. By the early twentieth century, fruit orchards, nuts, vegetables, potatoes, and other crops were also grown on the farms around the city.[15] Surrounded by this abundance of agricultural wealth, the city's economy developed around businesses that processed, cultivated, and transported agricultural goods. Several of Stockton's most prominent businesses, including Matteson & Williamson and Holt Brothers Manufacturing Company, made names for themselves as the manufacturers of agricultural tools and equipment that increased the productivity of the area's farms.

Stockton's location along a variety of important transportation corridors—including the Stockton Channel, with its deep water shipping access, and the Central Pacific Railroad—contributed to Stockton's industrial development and emergence as a regional transportation hub.[16] Shipyards, iron foundries, warehouses, and factories were established along the channel and its tributaries.[17]

Burgeoning with economic activity and a growing population, Stockton experienced a building boom from the 1880s until the 1930s, during which the majority of buildings in the city's downtown and nearby residential areas were constructed. In the late nineteenth century, many of the city's downtown commercial buildings were constructed of locally produced red brick, inspiring one of the Stockton's nicknames, "The Brick City."[18] Five high rises were constructed between 1910 and 1917 alone.[19] Two- and three-story masonry residential hotels were also constructed during this period in order to provide affordable, temporary housing for the large population of migrant laborers who worked on the surrounding farms. These residential hotels, many of which had commercial retail spaces on the first floor and exhibited Classical architectural detailing, became a common building type in downtown Stockton as a result.[20] The downtown area was also home to the largest Chinatown in California, as many Chinese families relocated from San Francisco after the 1906 earthquake.[21]

[7] Idem.
[8] Idem.
[9] Idem.
[10] Architectural Resources Group, 7.
[11] Architectural Resources Group, 7.
[12] Ibid., 6.
[13] Ibid., 7-8.
[14] Daniel Kasser, *Downtown Stockton* (San Francisco: Arcadia Publishing, 2005), 15.
[15] Architectural Resources Group, 13-14.
[16] Ibid., 17.
[17] "A Historical Study of Stockton, California," Visit Stockton, accessed June 19, 2019, https://www.visitstockton.org/about-us/stockton-history/.
[18] Architectural Resources Group, 12.
[19] Ibid., 16.
[20] Ibid., 9.
[21] Ibid., 8.

Other immigrant groups, in addition to the Chinese, made up a large portion of Stockton's population. After the passage of the Chinese Exclusion Act in 1882, Filipino, Japanese, and Sikh immigrants gradually replaced the Chinese as the main labor force in the city's packing houses, farms, and domestic industries. By the 1920s, Filipino men and women made up the majority of Stockton's agricultural labor force, giving the city the nickname, the "Manila of California."[22] From the late nineteenth century to the 1920s, Italians also arrived in Stockton in large numbers, during a wave of migration that took place after the unification of Italy around 1861.[23]

Construction during the late nineteenth and early twentieth centuries also included civic and institutional establishments. A San Joaquin County Courthouse was completed on a public square a short distance from the channel in 1854 and was replaced in 1890. In 1924, the University of the Pacific relocated from San Jose to Stockton, bringing one of the city's most influential and long-standing establishments to the city.[24]
Infrastructural improvements further enhanced Stockton's continuing development. Electric trolleys began service in the last decades of the nineteenth century. As the automobile became increasingly popular and affordable at the start of the twentieth century, an auto row developed at El Dorado Street and Miner Avenue.[25] In 1911, a new diverting channel was completed to address issues with frequent flooding.[26]

Stockton's varied economy, based on the agricultural industry and other industries centered around the shipping channel, helped soften the impact of the Great Depression. Starting in 1927, work to expand and deepen Stockton Channel provided employment for hundreds of workers. The new Port of Stockton opened in 1933 as the largest inland port in California at the time. Opportunities for work in the region's surrounding farms, meanwhile, attracted families from the Midwest and large populations of immigrant workers to the area.

World War II to the Present
The outbreak of World War II and the resulting demand for war-related goods stimulated Stockton's local industries. Shipbuilding, based at the city's many shipyards, became the largest source of employment, while the opening of an Army Air Force base at Old Stockton Field and the Stockton Naval Supply depot created new job opportunities. The war also created an agricultural labor shortage. Mexican workers, sponsored by the federal Bracero Program, filled the void and became part of the city's rich multicultural makeup.[27]

The postwar period reshaped the city. Stockton struggled to maintain its status as a major shipping center because the Stockton Channel was not large or deep enough to accommodate the increasing size of shipping vessels. In response, the local economy began to shift toward warehousing and the production of farming machinery and commercial boats. The completion of new residential neighborhoods, shopping malls, and of the Crosstown and Interstate 5 freeways, as well as the migration of affluent residents outside of the city center, diverted economic and commercial activity away from Stockton's historic downtown core. By the 1950s, the area was considered blighted. In the 1960s, the area became the target of urban renewal efforts, which resulted in the demolition of all but three buildings on nine square blocks of downtown. Longstanding residents, many of whom were of Chinese or Filipino descent, were displaced during the redevelopment.[28]

In the 1980s, Stockton's downtown began to experience a resurgence of development. Activity around the canal refocused around recreation-related uses and building projects. Boats plied its waters, and restaurants, a shopping mall, and housing developments were constructed along the waterfront.[29]

In the 2010s, agriculture remains important to the city's economy. Asparagus, cherries, tomatoes, walnuts, and almonds have replaced wheat and grain as the area's major crops. In spite of the changes that have taken place over time, Stockton continues to be characterized by its agricultural industry, the Stockton Channel, its history of brick buildings downtown, and a diverse, multi-cultural population.[30]

The Queen Anne Style: Free Classic Subtype
The Queen Anne style was a popular architectural style among the elite during the Victorian era of the late nineteenth century. First

[22] Architectural Resource Group, 9-10, 21.
[23] Pacific Italian Alliance and Ralph A. Clark, *Italians of San Joaquin County* (Charleston, SC: Arcadia Publishing, 2014), 7.
[24] "A Historical Study of Stockton, California."
[25] Ibid., 8-9
[26] "A Historical Study of Stockton, California."
[27] Ibid., 10.
[28] Ibid., 11.
[29] Ibid., 11.
[30] "History: A Look Into Stockton's Past."

used in England, this style referred back to the reign of Queen Anne (1702-1714) when craftsmanship and simplicity of construction were emphasized in the architectural vernacular.[31] One of the main innovators and architects of this style was Richard Norman Shaw, who popularized the Queen Anne style in England with his half-timbered designs that borrowed from late Medieval buildings from the Elizabethan and Jacobean periods. American architects introduced this style into the mainstream during the late 1870s and soon added subtypes of the style with spindlework and classical architectural elements. By the 1880s, the Queen Anne style had become the leading architectural style for the Victorian elite and upper to middle classes.

The Queen Anne style is characterized by its variety of features and combination of ornamentation. Typical features of the Queen Anne style include steeply pitched roofs, irregular rooflines, gable projections, cutaway bay windows, asymmetrical compositions, and swag and garland appliqués.[32] The result of this fusion of ornamentation and composition was a highly textured and varied residence, which achieved the elegance and grace desired by the people of this era. Commonly, other architectural styles, such as Eastlake and Stick, were combined with the Queen Anne style to produce asymmetrical and varied compositions.

Approximately 35 percent of Queen Anne houses are considered to be a subtype of the style called Free Classic. The style became common after 1890, with a peak from 1900 until 1910, and shares some features with early Colonial Revival houses, which became the dominant architectural style in the years afterward. The Free Classic subtype is characterized by its use of classical columns that are typically grouped together in units of two or three. Other classical features – such as cornice-line dentils, swags, garlands, or Palladian windows – are also common.[33]

Owner and Occupant History

The sequence of owners and occupants of the subject property, developed from records maintained at the San Joaquin Recorder-County Clerk's offices, historic city directories, census records, and historical newspaper articles is summarized in Table 2. Brief biographies of long-term or notable owners and occupants follow the table.

Table 2. Owners and Occupants of 435-437 S. San Joaquin Street, Stockton

Year(s)	Owner[34]	Occupant[35]
ca. 1900-1949	Bee Hoult	435 S. San Joaquin Street 1910 – Frank H. Bileski, dry goods merchant 1915 – William R. Holmes, bartender 1920 – Harry A. Smith, mechanic 1930-1940 – Bee Hoult 1945 - Lee C. Preston, shoe repairer 437 S. San Joaquin Street 1910 – Emma R. Small 1915-1920 – Thomas A. King, cigars 1925 – Vacant 1930 – Valerie Brown 1935-1940 – Emma R. Small 1945 - Joseph Smith, driver
1949	Bee Hoult Estate c/o Bob Stevenson	
1949-1960	Ila H. Stevenson	435 S. San Joaquin Street 1950 – Clyde H. Dunsing, engineer NSD 1955-1960 - Thomas Iriarte, welder 437 S. San Joaquin Street 1950 – Joseph Smith, driver 1955 - Julia J. George, saleswoman for Smith & Lang 1960 – Mary Leyva
1960-1972	S.L. Fong Lum Bow Yum Fong	435 S. San Joaquin Street 1965 - Vacant 1970-1975 – Abdul S. Ahmad, retired 435a S. San Joaquin Street

[31] Lester Walker, *American Shelter* (New York: The Overlook Press, Inc., 1997), 152.
[32] Virginia Savage McAlester, *A Field Guide to American Houses* (New York: Alfred A. Knopf, 2014), 345-347.
[33] Idem.
[34] Information from San Joaquin County Recorder-County Clerk.
[35] Information from United States Census and city directories, Ancestry.com. Directory listings do not include occupations for all residents.

Year(s)	Owner[34]	Occupant[35]
		1965 – Vacant 437 S. San Joaquin Street 1965 – Vacant 1970 – Janet Hood
1972-1977	Elizabeth Fong Wills John Fong	435 S. San Joaquin Street 1970-1975 – Abdul S. Ahmad, retired 435b S. San Joaquin Street 1975 – Leopoldo Laue, farm worker 437 S. San Joaquin Street 1975 – Alla and Dee Stewart, retired
1977-1985	Elizabeth Fong Wills John Fong Christopher James Robertson Wills Elizabeth Mei Sit Fong Wills	435 S. San Joaquin Street 1980 – Abdott Ahmed 1985 – Jenny Davis, retired 437 S. San Joaquin Street 1980 – Fletcher and Sylvia Turner 1985 – James Turner, retired
1985-1989	Robert W. Hong Mee Yoke Hong Haye B. Chan Conde T. Chan Bak F. Hong Judith Hong Michael Attanasio Noreen E. Chan	435 S. San Joaquin Street 1986 – Jenny Davis, retired 437 S. San Joaquin Street 1986 – James Turner, retired
1989-2003	Gospel Center	435-437 S. San Joaquin Street 1989-2003 - Gospel Center (Annex)
2003-2019	Gospel Center Rescue Mission, Inc.	435-437 S. San Joaquin Street 2003-2019 - Gospel Center Rescue Mission, Inc.

The Hoult Family, Owners and Occupants, ca. 1900-1949

As previously mentioned, the subject building appears to have been originally owned and constructed for Bee Hoult and her family around 1904, after a fire destroyed earlier buildings on the lot. Born Bee Delia O'Brien in Ireland around 1861, Bee immigrated to the United States in 1883. In 1887, she married David James Hoult, a foreman of Houser & Haines Manufacturing Co.[36] The couple had one child, a son named Urban.[37] The family lived together at the adjacent house on the lot at 431 S. San Joaquin Street in 1910 through at least 1915.[38] As an adult, Urban worked for the firm of Radcliffe & Hoult, publishers of the *Mercury Sun* newspaper in Merced. He died of pneumonia in 1924 at the age of 35. David died just four years later at the age of 65.[39] Bee continued to own the subject property after their deaths and moved to the subject building at 435 S. San Joaquin Street until her own death sometime around 1949, after which the property passed to her niece, Ila H. Stevenson. Research did not uncover any additional information about the life or contributions of Bee, David, or Urban Hoult. City directories do not list Stevenson as a resident of the subject property.

Gospel Center Rescue Mission, Inc., Owner, 1989-2019

Gospel Center Rescue Mission (GCRM) is a faith-based non-profit that serves the homeless and addicted of San Joaquin County. The non-profit was founded in 1940 in Ripon, California out of a concern for the post-Depression era homeless population. Over time, GCRM added programs to provide food, shelter, clothing, addiction treatment, and medical care to the homeless.[40] Today, the agency serves over 1,000 men, women, and children at its Stockton campus each day and offers eight programs, including the only Homeless Recuperative Care Program and non-profit payee service in San Joaquin County.[41]

Significance Evaluation: National Register of Historic Places and California Register of Historical Resources

The subject property at 435-437 S. San Joaquin Street is not currently listed in the National Register of Historic Places (National Register) or the California Register of Historical Resources (California Register). The building is included in the California Historical

[36] San Joaquin County Clerk-Recorder
[37] 1900 United States Federal Census, Ancestry.com.
[38] 1910 United States Federal Census, Ancestry.com; Stockton City Directory, 1915.
[39] California, County Birth and Death Records, 1800-1994, FamilySearch.org.
[40] "Our Mission," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us/Mission-History.
[41] "Wayne G. Richardson," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us.

Resources Information System (CHRIS) as of 2012 with the status code, "5S2," indicating that the property has been identified as an "Individual property that is eligible for local listing or designation."

In order for a property to be eligible for listing in the National Register, it must be found significant under one or more of the following criteria:

Criterion A (Event): Properties associated with events that have made a significant contribution to the broad patterns of our history.

Criterion B (Person): Properties associated with the lives of persons significant in our past.

Criterion C (Design/Construction): Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction.

Criterion D (Information Potential): Properties that have yielded, or may be likely to yield, information important in prehistory or history.

In order for a property to be eligible for listing in the California Register, it must be found significant under one or more of the following criteria:

Criterion 1 (Events): Resources that are associated with events that have made a significant contribution to the broad patterns of local or regional history, or the cultural heritage of California.

Criterion 2 (Persons): Resources that are associated with the lives of persons important to California history.

Criterion 3 (Architecture): Resources that embody the distinctive characteristics of a type, period, region, or method of construction, or represent the work of a master, or possess high artistic values.

Criterion 4 (Information Potential): Resources or sites that have yielded or have the potential to yield information important to the prehistory or history of California.

The following section examines the eligibility of the building at 435-437 S. San Joaquin Street for *individual* listing in the National Register or California Register.

Criterion A/1 (Events)
The subject property does not appear to be eligible for individual listing under Criterion A/1 for association with events that have made a significant contribution to the broad patterns of local, state, or national history. The multi-family house was constructed around 1904, more than fifty years after Stockton was incorporated in 1850, and, thus, it is not significant for being one of the first or earliest residential buildings constructed in the city. Rather, it was constructed at a time when Stockton was experiencing a building boom that lasted from the 1880s until the 1930s. This building boom, however, is most closely associated with commercial and institutional development in Stockton's urban core and the city's emergence as a transportation hub and center for agricultural industries. Although residential development occurred during the same period, the subject building is not an exceptional example of a residential building constructed during the period and does not appear to have had an impact on the development of the surrounding area. Therefore, the building is not considered to be a notable representative of Stockton's development in the early twentieth century and does not appear to rise to the level of significance necessary to be individually eligible for listing on the California Register or National Register under Criterion A/1.

Criterion B/2 (Persons)
The subject property does not appear eligible for individual listing under Criterion B/2 for association with the lives of persons important to local, state, or national history. Bee Delia Hoult owned the property from at least 1900 until 1949, and the subject building appears to have been constructed for Hoult and her family around 1904 after a fire in 1902 destroyed earlier buildings on the site. Hoult appears to have lived in the subject building after the deaths of her husband and son from approximately 1920 until her death around 1949. Research did not reveal information about Bee Hoult's occupation or shed any further light on the activities or contributions of the Hoult family to Stockton or the surrounding area. From 1960 to 1985, the building was owned by a number of individuals that appear to have been associated with the Fong family. City directories do not list these owners as residents of the building or of Stockton, and research did not uncover the occupations or activities of these individuals necessary to evaluate their contributions to history. As a multi-family residence, a large number of people have lived at the subject building over time. Throughout its history, residents appear to have primarily been working class individuals employed in a number of industries.

Through the 1960s, city directories list a blacksmith, welder, mechanic, bartender, dry goods merchant, driver, shoe repairer, and saleswoman as residents of the house. Starting in the 1970s, residents were primarily farm workers and retired individuals. Research did not indicate that any of these individuals gained notable importance within their professions. Therefore, none of the owners or occupants that were identified during research for this report appear to have made significant contributions to local, state, or national history in a manner that rises to the level of significance necessary to merit designation under Criterion 2.

Criterion C/3 (Architecture)
The subject property does appear eligible under Criterion C/3 as a resource that embodies the distinctive characteristics of a multi-family house built in the Queen Anne style. More specifically, the house is an example of the Free Classic subtype of Queen Anne style houses. The building was originally constructed around 1904, during the peak period of popularity of Free Classic Queen Anne houses in the United States; however, a scan of the area surrounding the subject building suggests that this style was relatively uncommon in Stockton or that few examples survive in the city today. The subject building exhibits many of the defining characteristics of the style, including a dominant front-gabled roof and full-width front porch, that are representative of the broader Queen Anne style, as well as the use of Tuscan columns as porch supports and cornice-line carved wood modillions and dentils that are indicative of the Free Classic subtype. The building also has surviving original window trim and doors with decorative carved dentils. The subject property, therefore, appears to be significant under Criterion C/3.

The property's period of significance under Criterion C/3 is 1904, when the building was originally constructed.

Criterion D/4 (Information Potential)
The subject property does not appear to be individually eligible under Criterion D/4 as a building that has the potential to provide information important to the prehistory or history of the City of Fremont, state, or nation. It does not appear to feature construction or material types, or embody engineering practices that would, with additional study, provide important information. Page & Turnbull's evaluation of this property was limited to age-eligible resources above ground and did not involve survey or evaluation of the subject property for the purposes of archaeological information.

Evaluation (Integrity)
In order to qualify for listing in any local, state, or national historic register, a property or landscape must possess significance under at least one evaluative criterion as described above and retain integrity. Integrity is defined by the California Office of Historic Preservation as "the authenticity of an historical resource's physical identity evidenced by the survival of characteristics that existed during the resource's period of significance," or more simply defined by the National Park Service as "the ability of a property to convey its significance."[42] Established integrity standards are outlined by the *National Register Bulletin: How to Apply the National Register Criteria for Evaluation*. Seven variables, or aspects, that define integrity are used to evaluate a resource's integrity: location, setting, design, materials, workmanship, feeling, and association. A property must retain integrity under most or all of these aspects in order to retain overall integrity. If a property does not retain integrity, it can no longer convey its significance and is therefore not eligible for listing in local, state, or national registers.

1. *Location* is the place where the historic property was constructed.
2. *Design* is the combination of elements that create the form, plans, space, structure and style of the property.
3. *Setting* addresses the physical environment of the historic property inclusive of the landscape and spatial relationships of the building(s).
4. *Materials* refer to the physical elements that were combined or deposited during a particular period of time and in a particular pattern of configuration to form the historic property.
5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history.
6. *Feeling* is the property's expression of the aesthetic or historic sense of a particular period of time.
7. *Association* is the direct link between an important historic event or person and a historic property.

435-437 S. San Joaquin Street retains all seven of the aspects of integrity. The building has not been moved since its construction and, thus, retains integrity of location. Although the surrounding area has changed over time, a number of single- and multi-family houses and commercial buildings also dating to the late nineteenth and early twentieth centuries remain at their original locations directly next to or across from the subject property on S. San Joaquin Boulevard. As a result, the subject property retains its integrity of setting. Although the second-story balcony has been altered and brick veneer cladding has been added to the front façade and alterations to windows on the side and rear facades are evident, the building's essential exterior features and materials that convey its significance as a multi-family house constructed in the Free Classic subtype of the Queen Anne style – including prominent front gable with cornice line modillions and dentils, full-width front porch, Tuscan column porch supports, original wood

[42] California Office of Historic Preservation, *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources* (Sacramento: California Office of State Publishing, 4 September 2001), 11; U.S. Department of the Interior, National Park Service, *National Register Bulletin: How to Apply the National Register Criteria for Evaluation* (Washington, D.C.: National Park Service, 1995), 44.

windows and doors, and wood lap siding – remain intact. Integrity of design, materials, workmanship, feeling, and association have also been retained.

Based on this analysis, 435-437 S. San Joaquin Street retains sufficient integrity to convey its significance under Criterion 3/C and, therefore qualifies for listing on the National and California Registers.

Character-Defining Features
For a property to be eligible for national, state, or local designation, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. To be eligible, a property must clearly contain enough of those characteristics, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials. The character-defining features of 435-437 S. San Joaquin Street include:

- Projecting front-facing gabled roof
- Cornice with wood modillions and dentils
- Full-width front porch with Tuscan column supports mounted on solid wood railing
- Wood lap siding
- Wood panel doors and sash windows with molded wood trim, some with decorative carved dentils
- Entries to multiple units at front and rear façades

Significance Evaluation: City of Stockton Landmark, Historic Site, or Structure of Merit
The subject building is not included in the Downtown Stockton Historic Resources Survey (2000) and is not located within a local historic district or zoning overlay or listed as a City of Stockton Landmark, Historic Site, or Structure of Merit. It is therefore not currently listed locally as a historic resource.

Landmarks
According to the Stockton Municipal Code Section 16.220.070, "In considering an artifact, natural feature, or structure for designation as a Landmark, the Board shall apply any or all of the following criteria:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Architectural Craftsmanship**. Its embodiment of elements demonstrating outstanding attention to architectural and/or engineering craftsmanship, design, detail, or materials;
3. **Architectural Style.** Its exemplification of a particular architectural style or way of life important to the City, the State, or the Nation;
4. **Architectural Type.** Its exemplification of the best remaining architectural type in the City;
5. **Historic Event.** Its location as a site of a significant historic event;
6. **Heritage.** Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
7. **Visual Feature.** Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
8. **Relationship to Another Landmark.** Its relationship to any other landmark, if its preservation is essential to the integrity of that landmark;
9. **Significant Person.** Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation;
10. **Work of a Significant Person.** Its identification as the creation, design, or work of a person(s) whose effort has significantly influenced the heritage of the City, the State, or the Nation; or
11. **Natural Environment.** Its integrity as a natural environment that strongly contributes to the well-being of the people of the City, the State, or the Nation."[43]

Historic Sites & Structures of Merit
Historic Sites and Structures of Merit are designated by the same criteria. According to the Stockton Municipal Code Sections 16.220.090 and 16.220.100, the criteria for designating Historic Sites and Structures of Merit are the following:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Heritage**. Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
3. **Visual Feature of the City**. Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
4. **Way of Life.** Its exemplification of a particular way of life important to the City, the State, or the Nation;

[43] Stockton Municipal Code: 16.220.070, "Landmarks," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_070&frames=on.

5. **Historic Event.** Its location as a site of a significant historic event regardless of its current configuration, development, or use;
6. **Significant Person**. Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation; or
7. **Significant Person of a Specific National Origin.** Its identification with a person(s) representative of a specific national origin who have contributed to the culture and development of the City, the State, or the Nation."[44]

As evidenced in the previous evaluation, 435-437 S. San Joaquin Street appears to be significant at the local level under Criterion C/3 of the National Register and California Register and possesses sufficient integrity to be eligible for listing. The City of Stockton's criteria for the designation of Landmarks, Historic Sites, and Structures of Merit correspond approximately with those of the National Register and California Register; however, they do not appear to include an integrity requirement. In particular, criteria 2, 3, and 4 above for listing as a City of Stockton Landmark appear to correspond with Criterion C/3 of the National Register and California Register. Thus, the above evaluation for National Register and California Register Criteria C/3 can be extended to local designation under the corresponding criteria for listing as a City of Stockton Landmark, and the property appears to merit local designation as a City Landmark.

Conclusion

435-437 S. San Joaquin Street does appear to be eligible for individual listing in the National Register under Criterion C, the California Register under Criterion 3, and as a City of Stockton Landmark under Criteria 2, 3, and 4. The subject building was constructed in 1904 and embodies the distinctive characteristics that are representative of a multi-family house that was built in the Free Classic Queen Anne style. As such, the California Historical Resource Status Codes (CHRSC) of "3S," "3CS," and "5S2" have been assigned to the property, meaning that it has been found eligible for the National Register and California Register as an individual property through survey evaluation.[45]

[44] Stockton Municipal Code: 16.220.090, "Historic sites," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_090&frames=on; Stockton Municipal Code: 16.220.100, "Structures of merit," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_100&frames=on.

[45] California State Office of Historic Preservation Department of Parks and Recreation, *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory,* Sacramento, November 2004.

***B12. References:**

Publications

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume I*. 2000.

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume II*. 2000.

California Office of Historic Preservation. *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources,* Sacramento: California Department of Parks and Recreation, 2001.
———. *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory*. Sacramento: California Department of Parks and Recreation, 2004.

Gilbert, Lori. "Our Diversity: Native Americans First to Call Stockton home." *The Record*. November 29, 2014. Accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.

"History: A Look into Stockton's Past." Accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html.

Kasser, Daniel. *Downtown Stockton*. San Francisco: Arcadia Publishing, 2005.

McAlester, Virginia Savage. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 2014.

Wood, R. Coke. "The Rise of Stockton." *San Joaquin Historian* IX., no. 1 (January-March 1973). San Joaquin County Historical Society.

Repositories (specific documents cited in footnotes)

Ancestry.com.

Cesar Chavez Public Library, Stockton, California.

City of Stockton Permit Center, Stockton, CA.

David Rumsey Historic Map Collection.

Newspapers.com.

San Joaquin County Assessor's Office, Stockton, CA.

San Joaquin County Historical Society & Museum, Lodi, CA.

San Joaquin County Recorder/Clerk's Office, Stockton, CA.

San Joaquin County Public Library Obituary Index, 1850-1991, FamilySearch.org.

UC Santa Barbara Library, Aerial Photograph Collection.

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #_____
HRI #_____
Trinomial_____
NRHP Status Code 3S, 3CS, 5S
Other Listings_____
Review Code_____ Reviewer_____ Date_____

Resource name(s) or number (assigned by recorder) 429-431 S. San Joaquin Street


P1. Another Identifier: Wills House
***P2. Location:** ☐Not for Publication ☒Unrestricted ***a. County** San Joaquin
***b. USGS 7.5' Quad** Stockton West, CA **Date** 2018
***c. Address** 429-431 S. San Joaquin Street **City** Stockton **Zip** 95203
***e. Other Locational Data:** San Joaquin County Assessor's Parcel Number 149-066-070

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)
429-431 S. San Joaquin Street is a two-story, wood-frame multiple-family residence that was built around 1904 in a mixture of Queen Anne and Colonial Revival styles. It is located on a 9,150-square-foot lot on the west side of S. San Joaquin Street between E. Sonora Street and E. Church Street. The building is on the same parcel as 435-437 S. San Joaquin Street, a second multiple-family residence that was built at the same time in a similar architectural style. The building has a roughly rectangular footprint and a moderately pitched front-gabled roof with flared overhanging eaves and composition shingle cladding. The building is clad with wood lap siding and has a concrete foundation. Typical windows consist of wood sash windows with molded wood trim.

***P3b. Resource Attributes:** (list attributes and codes) HP3. Multiple family property

***P4. Resources Present:** ☒Building ☐Structure ☐Object ☐Site ☐District ☐Element of District ☐Other

P5a. Photo



P5b. Photo: (view and date)
Primary (northeast) façade, view southwest, October 11, 2019.

***P6. Date Constructed/Age and Sources:** ☒historic
ca. 1904, historic newspaper articles, city directories, Sanborn Map Co. fire insurance maps

***P7. Owner and Address:**
Gospel Center Rescue Mission, Inc.
445 S. San Joaquin St.
Stockton, CA 95203

***P8. Recorded by:**
Page & Turnbull, Inc.
2401 C Street, Ste. B
Sacramento, CA 95816

***P9. Date Recorded:**
October 11, 2019

***P10. Survey Type:**
Intensive

***P11. Report Citation:** None

***Attachments:** ☐None ☐Location Map ☐Sketch Map ☒Continuation Sheet ☒Building, Structure, and Object Record
☐Archaeological Record ☐District Record ☐Linear Feature Record ☐Milling Station Record ☐Rock Art Record
☐Artifact Record ☐Photograph Record ☐ Other (list)



Figure 1. Aerial photograph of 429-431 S. San Joaquin Street. Subject parcel outlined orange. Source: Google Earth 2019, edited by Page & Turnbull.

Northeast Façade

The primary, northeast façade features a prominent front-facing gable with flared, broadly overhanging eaves that are decorated with alternating carved wood modillions and dentils (**Figure 2**). The gable end has a rectangular metal air vent with a circular wood surround carved in a wreath-like design and is clad with stucco, possibly decorated to imitate swallows' nests. A full-width porch projects from the first story of the building and displays a shallow hipped roof with overhanging eaves that are decorated with wood modillions and dentils to match those of the roof above. The roof has been altered and is cut out above the entry to the porch. The roof of the porch, itself, is supported by paired wood Tuscan columns that are mounted on top of solid wood railings clad with wood lap siding to match the building's exterior cladding, except at the far north end, where the railing has been covered with brick veneer cladding. A set of poured concrete steps with a metal handrail leads up to the porch at the north end of the façade (**Figure 3**). The porch entrance is framed by a wood lap fascia and vertical wood support beams. Fenestration on the first story consists of, from left to right, a wood panel door with an integrated lite, set behind a wood screen door that is grouped together with two wood sash windows; a set of paired wood sash windows; and a second wood panel door and screen door at the far north end. On the second story, two wood sash windows frame a smaller, fixed wood frame window. The wood trim of these windows is more elaborate than those of the first story and has a projecting lintel decorated with dentils. Windows on both the first and second stories have been altered to accommodate air conditioning units.

Southeast Façade

The southeast façade, from left to right, consists of the southeast walls and wood supports of a recessed rear porch at the southwest corner of the building followed by a number of windows in the main portion of the building. The walls immediately above the porch opening are clad with narrow vertical wood siding and wood lap siding that matches the rest of the building above (**Figure 4**). At the main portion of the building, a molded wood drip course visually separates the crawl space from the first floor. The walls above the drip course contain a number of windows of varying sizes and configurations (**Figure 5**). From left to right, windows on the first floor consist of one small wood sash window followed by a taller wood sash window, a set of paired wood sash windows, and two additional single wood sash windows. On the second floor, a small aluminum slider window with flat wood trim is followed by a larger rectangular window with decorative wood trim that has been replaced with an aluminum slider (**Figure 6**). To the right, a set of paired wood sash windows and a single wood sash window flank a canted, cutaway bay window. The bay is capped by a small, gabled roof with flared eaves like those of the northeast façade. Pipes, conduits, and electrical fixtures have

been attached to the walls in various locations. Cylindrical metal chimneys, metal equipment, and a small brick chimney are visible on the roof above.

Southwest Facade
The rear (southwest) façade features a projecting rectangular bay that contains a recessed first-story porch at its southwest corner (**Figure 7**). The roof over the bay has wide projecting eaves with exposed rafter tails. A wood staircase with flat wood handrails and wood beam supports offers access to the porch before continuing along the façade to a second entry in the second story. As at the southeast façade, the walls above the porch opening are clad with narrow vertical wood siding, with wood lap siding above to match the exterior cladding of the rest of the building. To the left, a small wood access door offers access to the crawl space. Windows on the façade consist of three aluminum sliders with flat wood trim, two of which are located at the north end of the façade and the third of which is centered in the rectangular bay. Siding next to this window has recently been replaced with new wood lap siding.

Northwest Façade
Like the southeast façade, the northwest façade has a molded wood drip course that divides the crawl space from the first floor (**Figure 8**). The façade also features two additional entries. At the east end, a wood staircase with flat wood handrails and wood beam supports lead to a door at an intermediate level between the first and second stories, possibly at an interior stair landing (**Figure 9**). A transom and window above this door, as well as a larger rectangular opening to the left, have been infilled. The second entry, located in a small cut out at the west end of the façade, consists of a wood panel door with integrated glazing. This door is accessed via a small uncovered porch, also with flat wood handrails and supports. A small access door has been cut into the wood siding to the right, and several areas of the adjacent walls have been replaced with new wood alternative siding. The majority of windows on this façade consist of replacement aluminum slider windows with flat wood trim, some of which appear to have replaced larger, original window openings.


Figure 2. Northeast facade, view northwest.


Figure 3. Porch entry at northeast façade, view southwest.


Figure 4. South end of southeast façade with portion of recessed rear porch, view northwest.


Figure 5. Southeast façade, view west.



Figure 6. Aluminum slider windows, chimney, and ventilation pipes on roof above the southeast façade, view northeast.



Figure 7. Southwest façade, view northeast.



Figure 8. Northwest façade, view east.



Figure 9. East section of northwest façade, view east.

Site Features

As previously mentioned, the subject building is one of two multiple family residences on the parcel. The second, addressed as 435-437 S. San Joaquin Street, appears to have been constructed at the same time as the subject building and is located directly to the southeast (**Figure 10**). The narrow space between the two buildings has been paved with concrete (**Figure 11**). Landscaping in front of the building consists of a small front yard with a lawn and small concrete patio that is enclosed by a tall metal fence along the front and northwest property lines (**Figure 12**). A concrete walkway extends from the sidewalk to the building's front entrance, and a narrow strip of brick pavers lead to a second concrete walkway that separates the subject building from the adjacent building on the lot. The rear portion of the lot is also paved with concrete, except for a small space immediately to the rear of the building, in which trees have been planted. An outdoor seating area with wood picnic tables and a wood lattice covering is located at the southwest corner of the lot. The rest of the rear portion of the lot is used as a driveway and parking lot for the complex (**Figure 13**).



Figure 10. The subject property (left) and 435-437 S. San Joaquin Street, view northeast.



Figure 11. Concrete walkway between the subject property and 435-437 S. San Joaquin Street, view west.



Figure 12. Front yard, view south.



Figure 13. Paved area at the rear of the building, view northeast.

Surrounding Site Context

429-431 S. San Joaquin Street is located on the block bounded by S. San Joaquin Street to the northeast, E. Church Street to the southeast, S. Hunter Street to the southwest, and E. Sonora Street to the northwest in the heart of the original street grid of Stockton and one-and-one-half blocks south of the California State Route 4 highway. The surrounding area is characterized primarily by a mix of two- to three-story residential buildings and a few brick commercial buildings that appear to have been built around the turn of the twentieth century. 435-437 S. San Joaquin Street was constructed in a similar architectural style around 1904 (**Figure 14**). The Gleason House, located directly to the northwest of the subject property at 423 S. San Joaquin Street, is a Queen Anne style house constructed in 1895 (**Figure 15**). 420 S. San Joaquin Street, directly across from the subject property, is a two-story, Queen Anne style house built in 1905 (**Figure 16**). Next door, 430 S. San Joaquin is a two-story vernacular style foursquare that was built in 1900 (**Figure 17**).



Figure 14. 435-437 S. San Joaquin Street, built 1904.



Figure 15. The Gleason House at 423 S. San Joaquin Street, built 1895.



Figure 16. 420 S. San Joaquin Street, built 1905.



Figure 17. 430 S. San Joaquin Street, built 1900.

BUILDING, STRUCTURE, AND OBJECT RECORD

***NRHP Status Code** 3S, 3CS, 5S2
***Resource Name or #** 429-431 S. San Joaquin Street

B1. Historic name: Wills House
B2. Common name: 429-431 S. San Joaquin Street
B3. Original Use: Multiple Family Residence
B4. Present use: Multiple Family Residence
***B5. Architectural Style:** Queen Anne/Colonial Revival
***B6. Construction History:** (Construction date, alterations, and date of alterations)

The parcel on which 429-431 S. San Joaquin Street is located was owned by Bee Hoult by 1900. Two earlier wood frame buildings that were present on the site at the time burned down in a fire that spread from the Agricultural Pavilion building, located two blocks north on Lafeyette Street between S. Hunter, and destroyed nearly six city blocks in September 1902.[1] The 1904 Stockton city directory records that Hoult's husband, David, was living at 431 S. San Joaquin Street, indicating that the subject building had been completed by this time to replace the buildings that had been destroyed by the fire.[2] It is likely that Bee was living there at the time, as well, as she is listed as residing at the same address with her husband and son in the 1910 federal census.[3] The 1917 fire insurance map by the Sanborn Map Company shows the building as a two-story wood frame building that consisted of two flats over a basement (**Figure 18**). It had a one-story porch that spanned the front façade, a canted bay on the southeast façade, and an agglomeration of one- and two-story porches at the rear. The second-story rear porch appears to have been accessed by a long exterior staircase. A few subsequent alterations are apparent in the 1950 Sanborn map (**Figure 19**). By this time, the building had been subdivided into four flats, and an additional one-story porch had been added at the south end of the northwest façade. The configuration of the porches and stairs at the rear façade also appear to have been altered. These changes are not clearly visible in aerial photographs from the 1930s and 1970s; however, they indicate that the overall footprint of the building has remained relatively unchanged over time (**Figure 20** and **Figure 21**). (See Continuation Sheet, page 8)

***B7. Moved?** ☒**No** ☐**Yes** ☐**Unknown Date:** N/A **Original Location:** N/A
***B8. Related Features:** _ B9a. Architect: Unknown b. Builder: Unknown


***B10. Significance: Theme** Residential Architecture **Area** Stockton, California
Period of Significance 1904 **Property Type** Multiple-Family Residential **Applicable Criteria** C/3

City of Stockton
Native American through Early American Period:
Numerous Native American groups called the Central Valley home for thousands of years before the arrival of European and American settlers. The Stockton area was settled by the Yatchicumne, a group of the Northern Valley Yokuts people whose villages were established across a vast expanse of California from the confluence of the Sacramento and San Joaquin rivers as far as the Tehachapi Mountains, 250 miles to the south. At least two Yatchicumne villages were located in the Stockton area, including one called Pasasimas, situated on a mound near the Stockton Channel in present-day Downtown Stockton. (See Continuation Sheet, page 9)

B11. Additional Resource Attributes: (List attributes and codes)

***B12. References:** See Footnotes and Continuation Sheet, page 18
B13. Remarks: None
***B14. Evaluator:** Clare Flynn, Page & Turnbull, Inc.
***Date of Evaluation:** November 4, 2019

(This space reserved for official comments.)



Location Map: San Joaquin County Assessor's Office, 2019. Subject parcel shaded orange. Edited by Page & Turnbull.

[1] "Conflagration in the Heart of Stockton Leaves Record of Death and Injury, and Devastation of Wide Area," *The San Francisco Call*, September 30, 1902.
[2] Stockton, California, City Directory, 1904.
[3] 1910 United States Federal Census, Ancestry.com.

***B6. Construction History: (continued)**




Figure 18. Excerpt from 1917 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento Public Library. Edited by Page & Turnbull.




Figure 19. Excerpt from 1950 Sanborn Map Co. fire insurance map with subject building highlighted and subject parcel outlined in orange. Source: Sacramento. Edited by Page & Turnbull.



Figure 20. 1930 aerial photograph, approximate subject location outlined in orange. Source: Fairchild Aerial Surveys, Flight C-975A, Frame Z-252, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 21. 1970 aerial photograph, approximate subject location outlined in orange. Source: Cartwright Aerial Surveys, Flight CAS-2874, Frame 102, collection of UC Santa Barbara Library. Edited by Page & Turnbull.



Figure 22. The northwest facade in April 2012. Source: Google Street View, 2012.

Google Street View images show that the front porch entry had a different configuration and was in a deteriorated condition in 2012 (**Figure 22**). This does not appear to have been the original porch entry and was replaced with the existing configuration sometime between 2012 and 2015.[4] Building permits on file at the City of Stockton Permit Center document repairs to the building's foundation, electrical work, and repairs from fire damage. Additional alterations that are not documented in permits include the addition of a porch and stairs on the northwest façade; window replacements, additions, and removals; alterations to the front and rear porches; and re-roofing.

Table 1. Permits on File at the City of Fremont Community Development Department

Permit Number	Date	Applicant	Description
31995	12/5/1949	Ila Stevenson	Foundation for apartment house
25820	4/16/1962	S.L. Fong	Repair apartment foundation underpinning
66399	1/12/1987	Robert Hong	Electrical
04783	10/05/1998	Gospel Center	Repair sheetrock and one plug from fire damage

***B10. Significance: (continued)**

Local rivers and streams provided an abundant source of food for the native population and also attracted European and American fur trappers to the area, who began exploring the area in the early nineteenth century in search of beaver and otter pelts.[5] These early explorers included Jedediah Strong Smith, who established a base camp to the southeast of present-day Stockton in 1827, and Alex McCleod, a fur trapper from the Hudson's Bay Company, whose camp near McCleod Lake gave the lake its name.[6] While the fur trappers reaped the benefits of the region's rich natural resources, they also brought diseases with them that led to the decimation of much of the local Native American population.[7]

The presence of French-Canadian fur trappers provided the inspiration for the name of the Mexican land grant that encompassed the present-day site of Stockton and its immediate vicinity during the Mexican period, after Mexico achieved independence from Spain in 1821. Rancho Campo de los Franceses, as the grant was known, was filled with numerous waterways, grassy hills, and oak trees. It was this landscape that German immigrant Captain Charles Maria Weber, founder of the city of Stockton, experienced

[4] Google Street View, April 2012, accessed October 25, 2019, Google.com.
[5] City of Stockton, "History: A Look into Stockton's Past," accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html; Lori Gilbert, "Our Diversity: Native Americans first to call Stockton home," *The Record*, November 29, 2014, accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.
[6] R. Coke Wood, "The Rise of Stockton," *San Joaquin Historian* IX, no. 1 (January-March 1973), San Joaquin County Historical Society, 2.
[7] Architectural Resources Group, Stockton Downtown Draft Historic Resources Survey, 2000, 6.

when he traveled through the area on his way to San Jose in 1842.[8] Recognizing the area's potential, Weber and his business partner, Guillermo (William) Gulnac, acquired roughly 55 square kilometers of Rancho Campo de los Franceses on the east side of the San Joaquin River from the Mexican governor in 1843. Weber eventually bought Gulnac out of the land and built his first structures on the site in 1847.[9] The first survey of the settlement, initially known as Tuleberg, was completed by Jasper O'Farrell the same year.[10]

Formation of Stockton

Like many cities in Northern California, Stockton grew from a small, rural outpost into a booming city as a result of the Gold Rush. When gold was discovered at Coloma in 1848, one year after Weber established the settlement of Tuleberg, he initially joined the fervor and spent months mining in the goldfields. He soon realized, however, that he had a better chance of making his fortune by selling goods and supplies to the floods of miners who were traveling into the area.[11] Advantageously located at the head of the Stockton Channel, a tributary of the San Joaquin River, Weber's settlement emerged as the gateway to and major supply center for California's southern mining areas as ships traveling from San Francisco brought streams of miners to the area (Error! Reference source not found.).[12]

As the settlement's population grew, so did urban development. In 1849, Major R. P. Hammond completed a second survey that laid out the first street grid between Weber Avenue, Center Street, Main Street, and Commerce Street.[13] In 1850, the same year the California achieved statehood, the settlement was officially incorporated as a city and renamed Stockton, after Commodore Robert F. Stockton, the American Navy officer who drove the last Mexican forces out of California in 1848.[14] Over the next five years, the city's population swelled from 1,000 to roughly 7,000. By the 1890s, it had exploded to approximately 23,000 residents.[15]

The streets between El Dorado Avenue, Main Street, Commerce Street, and Levee (now Weber) Avenue formed the core of the city's commercial area in the nineteenth century. The first residential districts, meanwhile, developed to the southwest and north. Floods were common in the winter months due to the city's location near miles of waterways that made up the Sacramento-San Joaquin River Delta.[16]

After the Gold Rush ended in the mid-1850s, the Central Valley's rich soil and temperate climate contributed to the development of Stockton into a major center for agricultural industries. Wheat and grains were the area's largest crop in the nineteenth century and spurred the construction of grain warehousing facilities and flour mills in the area, including the Sperry Flour Company. By the early twentieth century, fruit orchards, nuts, vegetables, potatoes, and other crops were also grown on the farms around the city.[17] Surrounded by this abundance of agricultural wealth, the city's economy developed around businesses that processed, cultivated, and transported agricultural goods. Several of Stockton's most prominent businesses, including Matteson & Williamson and Holt Brothers Manufacturing Company, made names for themselves as the manufacturers of agricultural tools and equipment that increased the productivity of the area's farms.

Stockton's location along a variety of important transportation corridors—including the Stockton Channel, with its deep water shipping access, and the Central Pacific Railroad—contributed to Stockton's industrial development and emergence as a regional transportation hub.[18] Shipyards, iron foundries, warehouses, and factories were established along the channel and its tributaries.[19]

Burgeoning with economic activity and a growing population, Stockton experienced a building boom from the 1880s until the 1930s, during which the majority of buildings in the city's downtown and nearby residential areas were constructed. In the late nineteenth century, many of the city's downtown commercial buildings were constructed of locally produced red brick, inspiring one of the Stockton's nicknames, "The Brick City."[20] Five high rises were constructed between 1910 and 1917 alone.[21] Two- and three-story masonry residential hotels were also constructed during this period in order to provide affordable, temporary housing for the large population of migrant laborers who worked on the surrounding farms. These residential hotels, many of which had

[8] Wood, 2.
[9] Idem.
[10] Idem.
[11] Idem.
[12] Architectural Resources Group, 7.
[13] Architectural Resources Group, 7.
[14] Ibid., 6.
[15] Ibid., 7-8.
[16] Daniel Kasser, *Downtown Stockton* (San Francisco: Arcadia Publishing, 2005), 15.
[17] Architectural Resources Group, 13-14.
[18] Ibid., 17.
[19] "A Historical Study of Stockton, California," Visit Stockton, accessed June 19, 2019, https://www.visitstockton.org/about-us/stockton-history/.
[20] Architectural Resources Group, 12.
[21] Ibid., 16.

commercial retail spaces on the first floor and exhibited Classical architectural detailing, became a common building type in downtown Stockton as a result.[22] The downtown area was also home to the largest Chinatown in California, as many Chinese families relocated from San Francisco after the 1906 earthquake.[23]

Other immigrant groups, in addition to the Chinese, made up a large portion of Stockton's population. After the passage of the Chinese Exclusion Act in 1882, Filipino, Japanese, and Sikh immigrants gradually replaced the Chinese as the main labor force in the city's packing houses, farms, and domestic industries. By the 1920s, Filipino men and women made up the majority of Stockton's agricultural labor force, giving the city the nickname, the "Manila of California."[24] From the late nineteenth century to the 1920s, Italians also arrived in Stockton in large numbers, during a wave of migration that took place after the unification of Italy around 1861.[25]

Construction during the late nineteenth and early twentieth centuries also included civic and institutional establishments. A San Joaquin County Courthouse was completed on a public square a short distance from the channel in 1854 and was replaced in 1890. In 1924, the University of the Pacific relocated from San Jose to Stockton, bringing one of the city's most influential and long-standing establishments to the city.[26]
Infrastructural improvements further enhanced Stockton's continuing development. Electric trolleys began service in the last decades of the nineteenth century. As the automobile became increasingly popular and affordable at the start of the twentieth century, an auto row developed at El Dorado Street and Miner Avenue.[27] In 1911, a new diverting channel was completed to address issues with frequent flooding.[28]

Stockton's varied economy, based on the agricultural industry and other industries centered around the shipping channel, helped soften the impact of the Great Depression. Starting in 1927, work to expand and deepen Stockton Channel provided employment for hundreds of workers. The new Port of Stockton opened in 1933 as the largest inland port in California at the time. Opportunities for work in the region's surrounding farms, meanwhile, attracted families from the Midwest and large populations of immigrant workers to the area.

World War II to the Present
The outbreak of World War II and the resulting demand for war-related goods stimulated Stockton's local industries. Shipbuilding, based at the city's many shipyards, became the largest source of employment, while the opening of an Army Air Force base at Old Stockton Field and the Stockton Naval Supply depot created new job opportunities. The war also created an agricultural labor shortage. Mexican workers, sponsored by the federal Bracero Program, filled the void and became part of the city's rich multicultural makeup.[29]

The postwar period reshaped the city. Stockton struggled to maintain its status as a major shipping center because the Stockton Channel was not large or deep enough to accommodate the increasing size of shipping vessels. In response, the local economy began to shift toward warehousing and the production of farming machinery and commercial boats. The completion of new residential neighborhoods, shopping malls, and of the Crosstown and Interstate 5 freeways, as well as the migration of affluent residents outside of the city center, diverted economic and commercial activity away from Stockton's historic downtown core. By the 1950s, the area was considered blighted. In the 1960s, the area became the target of urban renewal efforts, which resulted in the demolition of all but three buildings on nine square blocks of downtown. Longstanding residents, many of whom were of Chinese or Filipino descent, were displaced during the redevelopment.[30]

In the 1980s, Stockton's downtown began to experience a resurgence of development. Activity around the canal refocused around recreation-related uses and building projects. Boats plied its waters, and restaurants, a shopping mall, and housing developments were constructed along the waterfront.[31]

In the 2010s, agriculture remains important to the city's economy. Asparagus, cherries, tomatoes, walnuts, and almonds have replaced wheat and grain as the area's major crops. In spite of the changes that have taken place over time, Stockton continues to

[22] Ibid., 9.
[23] Ibid., 8.
[24] Architectural Resource Group, 9-10, 21.
[25] Pacific Italian Alliance and Ralph A. Clark, *Italians of San Joaquin County* (Charleston, SC: Arcadia Publishing, 2014), 7.
[26] "A Historical Study of Stockton, California."
[27] Ibid., 8-9
[28] "A Historical Study of Stockton, California."
[29] Ibid., 10.
[30] Ibid., 11.
[31] Ibid., 11.

be characterized by its agricultural industry, the Stockton Channel, its history of brick buildings downtown, and a diverse, multi-cultural population.[32]

The Queen Anne Style: Free Classic Subtype

The Queen Anne style was a popular architectural style among the elite during the Victorian era of the late nineteenth century. First used in England, this style referred back to the reign of Queen Anne (1702-1714) when craftsmanship and simplicity of construction were emphasized in the architectural vernacular.[33] One of the main innovators and architects of this style was Richard Norman Shaw, who popularized the Queen Anne style in England with his half-timbered designs that borrowed from late Medieval buildings from the Elizabethan and Jacobean periods. American architects introduced this style into the mainstream during the late 1870s and soon added subtypes of the style with spindlework and classical architectural elements. By the 1880s, the Queen Anne style had become the leading architectural style for the Victorian elite and upper to middle classes.

The Queen Anne style is characterized by its variety of features and combination of ornamentation. Typical features of the Queen Anne style include steeply pitched roofs, irregular rooflines, gable projections, cutaway bay windows, asymmetrical compositions, and swag and garland appliqués.[34] The result of this fusion of ornamentation and composition was a highly textured and varied residence, which achieved the elegance and grace desired by the people of this era. Commonly, other architectural styles, such as Eastlake and Stick, were combined with the Queen Anne style to produce asymmetrical and varied compositions.

Approximately 35 percent of Queen Anne houses are considered to be a subtype of the style called Free Classic. The style became common after 1890, with a peak from 1900 until 1910, and shares some features with early Colonial Revival houses, which became the dominant architectural style in the years afterward. The Free Classic subtype is characterized by its use of classical columns that are typically grouped together in units of two or three. Other classical features – such as cornice-line dentils, swags, garlands, or Palladian windows – are also common.[35]

Owner and Occupant History

The sequence of owners and occupants of the subject property, developed from records maintained at the San Joaquin Recorder-County Clerk's offices, historic city directories, census records, and historical newspaper articles is summarized in Table 2. Brief biographies of long-term or notable owners and occupants follow the table.

Table 2. Owners and Occupants of 429-431 S. San Joaquin Street, Stockton

Year(s)	Owner[36]	Occupant[37]
ca. 1900-1949	Bee Hoult	429 S. San Joaquin Street 1910-1915 - Llewella Hicklin 1920 - Geo Kosta. restaurant manager 1920 - John Stimbogiani, waiter 1925 - Charles Pefferling, salesman 1930 - Ada Partrick, widow 1935 - H.A. Pile, blacksmith helper 1940 - Vacant 1945 – Henry L. Olechea 429a S. San Joaquin Street 1920 - Fermin Alustiza, sheepman 1925 - J.A. Bennett 1945 - Mrs. W.E. Warren 431 S. San Joaquin Street 1908-1915 – David J. and Bee Hoult, foreman of Houser & Haines Manufacturing Co. 1925 - W.A. Morrow, assembler 1935 – Vacant 1940 – James Ramos, cook 1945 - Thomas Iriarte, machinist
1949	Bee Hoult Estate	

[32] "History: A Look Into Stockton's Past."
[33] Lester Walker, *American Shelter* (New York: The Overlook Press, Inc., 1997), 152.
[34] Virginia Savage McAlester, *A Field Guide to American Houses* (New York: Alfred A. Knopf, 2014), 345-347.
[35] Idem.
[36] Information from San Joaquin County Recorder-County Clerk.
[37] Information from United States Census and city directories, Ancestry.com. Directory listings do not include occupations for all residents.

Year(s)	Owner[36]	Occupant[37]
	c/o Bob Stevenson	
1949-1960	Ila H. Stevenson	429 S. San Joaquin Street 1950 - Vernon E. Gresham, salesman 1955-1960 - Ila H. Stevenson, widow 429a S. San Joaquin Street 1950 – Agnes Sanchez, clerk 1955 - Peter Laperena, laborer 1960 – Jessie Villasenor, cannery worker 431 S. San Joaquin Street 1950 – Thomas Iriarte, welder 1960 - Lupe Carranza, cook 431a S. San Joaquin Street 1950 – Rufino Echandi, employee AAWCo; Grace Echandi, bookkeeper; and Joseph Echandi 1960 - Carmen D. Quirarte
1960-1972	S.L. Fong Lum Bow Yum Fong	429 S. San Joaquin Street 1965 – Vacant 1970 – Seopoldo Gutierrez, farm worker 429a S. San Joaquin Street 1965 – Leonidez Galeviz 1970 – Quong Wee Lee 431 S. San Joaquin Street 1965 – Olivas Suant, farm worker 1970 – Jenny M. Huante 431a S. San Joaquin Street 1965-1970 – Paul Tearo, retired
1972-1977	Elizabeth Fong Wills John Fong	429 S. San Joaquin Street 1975 – Olivias Huante 429a S. San Joaquin Street 1975 – Dina Aguilar, retired 431 S. San Joaquin Street 1975 – Lepoldo Gutierras 431a S. San Joaquin Street 1975 – Gregory Hernandez, retired
1977-1985	Elizabeth Fong Wills John Fong Christopher James Robertson Wills Elizabeth Mei Sit Fong Wills	429 S. San Joaquin Street 1980 – Jenny Huante, retired 1985 - Vacant 429a S. San Joaquin Street 1980 – Javier Olivos 1985 – Phoeng Soeung 431 S. San Joaquin Street 1980-1985 – Louie and Marie Godoy 431a S. San Joaquin Street 1980-1985 – Gregory Hernandez, retired
1985-1989	Robert W. Hong Mee Yoke Hong Haye B. Chan Conde T. Chan Bak F. Hong Judith Hong Michael Attanasio Noreen E. Chan	429a S. San Joaquin Street 1986 –Phoeung Soeung 429b S. San Joaquin Street 1986 – Thont Hong 431a S. San Joaquin Street 1986 – Saren Sao 431b S. San Joaquin Street 1986 – Saol Pol, student
1989-2003	Gospel Center	429-431 S. San Joaquin Street 1989-2003 – Gospel Center (Annex)
2003-2019	Gospel Center Rescue Mission, Inc.	429-431 S. San Joaquin Street 2003-2019 – Gospel Center Rescue Mission, Inc.

The Hoult Family, Owners and Occupants, ca. 1900-1949

As previously mentioned, the subject building appears to have been originally owned and constructed for Bee Hoult and her family around 1904, after a fire destroyed earlier buildings on the lot. Born Bee Delia O'Brien in Ireland around 1861, Bee immigrated to the United States in 1883. In 1887, she married David James Hoult, a foreman of Houser & Haines Manufacturing Co.[38] The couple had one child, a son named Urban.[39] The family lived together at 431 S. San Joaquin Street in 1910 through at least 1915.[40] As an adult, Urban worked for the firm of Radcliffe & Hoult, publishers of the *Mercury Sun* newspaper in Merced. He died of pneumonia in 1924 at the age of 35. David died just four years later at the age of 65.[41] Bee continued to own the subject property after their deaths and moved to the neighboring house at 435 S. San Joaquin Street until her own death sometime around 1949, after which the property passed to her niece, Ila H. Stevenson. Research did not uncover any additional information about the life or contributions of Bee, David, or Urban Hoult. City directories do not list Stevenson as a resident of the subject property.

Gospel Center Rescue Mission, Inc., Owner, 1989-2019
Gospel Center Rescue Mission (GCRM) is a faith-based non-profit that serves the homeless and addicted of San Joaquin County. The non-profit was founded in 1940 in Ripon, California out of a concern for the post-Depression era homeless population. Over time, GCRM added programs to provide food, shelter, clothing, addiction treatment, and medical care to the homeless.[42] Today, the agency serves over 1,000 men, women, and children at its Stockton campus each day and offers eight programs, including the only Homeless Recuperative Care Program and non-profit payee service in San Joaquin County.[43]

Significance Evaluation: National Register of Historic Places and California Register of Historical Resources
The subject property at 429-431 S. San Joaquin Street is not currently listed in the National Register of Historic Places (National Register) or the California Register of Historical Resources (California Register). The building is included in the California Historical Resources Information System (CHRIS) as of 2012 with the status code, "5S2," indicating that the property has been identified as an "Individual property that is eligible for local listing or designation."

In order for a property to be eligible for listing in the National Register, it must be found significant under one or more of the following criteria:

Criterion A (Event): Properties associated with events that have made a significant contribution to the broad patterns of our history.

Criterion B (Person): Properties associated with the lives of persons significant in our past.

Criterion C (Design/Construction): Properties that embody the distinctive characteristics of a type, period, or method of construction, or that represent the work of a master, or that possess high artistic values, or that represent a significant distinguishable entity whose components lack individual distinction.

Criterion D (Information Potential): Properties that have yielded, or may be likely to yield, information important in prehistory or history.

In order for a property to be eligible for listing in the California Register, it must be found significant under one or more of the following criteria:

Criterion 1 (Events): Resources that are associated with events that have made a significant contribution to the broad patterns of local or regional history, or the cultural heritage of California.

Criterion 2 (Persons): Resources that are associated with the lives of persons important to California history.

Criterion 3 (Architecture): Resources that embody the distinctive characteristics of a type, period, region, or method of construction, or represent the work of a master, or possess high artistic values.

Criterion 4 (Information Potential): Resources or sites that have yielded or have the potential to yield information important to the prehistory or history of California.

The following section examines the eligibility of the building at 429-431 S. San Joaquin Street for *individual* listing in the National

[38] San Joaquin County Clerk-Recorder
[39] 1900 United States Federal Census, Ancestry.com.
[40] 1910 United States Federal Census, Ancestry.com; Stockton City Directory, 1915.
[41] California, County Birth and Death Records, 1800-1994, FamilySearch.org.
[42] "Our Mission," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us/Mission-History.
[43] "Wayne G. Richardson," Gospel Center Rescue Mission, accessed October 21, 2019, http://www.gcrms.org/About-Us.

Register or California Register.

Criterion A/1 (Events)
The subject property does not appear to be eligible for individual listing under Criterion A/1 for association with events that have made a significant contribution to the broad patterns of local, state, or national history. The multi-family house was constructed around 1904, more than fifty years after Stockton was incorporated in 1850, and, thus, it is not significant for being one of the first or earliest residential buildings constructed in the city. Rather, it was constructed at a time when Stockton was experiencing a building boom that lasted from the 1880s until the 1930s. This building boom, however, is most closely associated with commercial and institutional development in Stockton's urban core and the city's emergence as a transportation hub and center for agricultural industries. Although residential development occurred during the same period, the subject building is not an exceptional example of a residential building constructed during the period and does not appear to have had an impact on the development of the surrounding area. Therefore, the building is not considered to be a notable representative of Stockton's development in the early twentieth century and does not appear to rise to the level of significance necessary to be individually eligible for listing on the California Register or National Register under Criterion A/1.

Criterion B/2 (Persons)
The subject property does not appear eligible for individual listing under Criterion B/2 for association with the lives of persons important to local, state, or national history. Bee Delia Hoult owned the property from at least 1900 until 1949, and the subject building appears to have been constructed for Hoult and her family around 1904 after a fire in 1902 destroyed earlier buildings on the site. Hoult appears to have lived in the subject building with her husband, David, and son, Urban, from roughly the time of its construction until around 1915. David worked as a foreman for Houser & Haines Manufacturing Co., while Urban worked for the firm that published the *Mercury Sun* newspaper in Merced. Research did not reveal information about Bee Hoult's occupation or shed any further light on the activities or contributions of the Hoult family to Stockton or the surrounding area. From 1960 to 1985, the building was owned by a number of individuals that appear to have been associated with the Fong family. City directories do not list these owners as residents of the building or of Stockton, and research did not uncover the occupations or activities of these individuals necessary to evaluate their contributions to history. As a multi-family residence, a large number of people have lived at the subject building over time. Throughout its history, residents appear to have primarily been working class individuals employed in a number of industries. In the first half of the twentieth century, city directories list restaurant workers, blacksmiths, machinists, and agricultural workers as residents of the house. From the 1940s to the 1960s, clerks, salesmen, cannery workers, and laborers from other industries resided there. Starting in the 1960s, residents were primarily farm workers and retired individuals. Research did not indicate that any of these individuals gained notable importance within their professions. Therefore, none of the owners or occupants that were identified during research for this report appear to have made significant contributions to local, state, or national history in a manner that rises to the level of significance necessary to merit designation under Criterion 2.

Criterion C/3 (Architecture)
The subject property does appear eligible under Criterion C/3 as a resource that embodies the distinctive characteristics of a multi-family house built in the Queen Anne style. More specifically, the house is a representative example of the Free Classic subtype of Queen Anne style houses. The building was originally constructed around 1904, during the peak period of popularity of Free Classic Queen Anne houses in the United States; however, a scan of the area surrounding the subject building suggests that this style was relatively uncommon in Stockton or that few examples survive in the city today. The subject building exhibits many of the defining characteristics of the style, including a dominant front-gabled roof; one-story, full-width front porch; a side bay window; and asymmetrical composition, that are representative of the broader Queen Anne style, as well as the use of paired Tuscan columns as porch supports and cornice-line carved wood modillions and dentils that are indicative of the Free Classic subtype. The building also has some additional notable design features, including flared overhanging eaves and surviving original window trim and doors with decorative carved dentils. The subject property, therefore, appears to be significant under Criterion C/3.

The property's period of significance under Criterion C/3 is 1904, when the building was originally constructed.

Criterion D/4 (Information Potential)
The subject property does not appear to be individually eligible under Criterion D/4 as a building that has the potential to provide information important to the prehistory or history of the City of Fremont, state, or nation. It does not appear to feature construction or material types, or embody engineering practices that would, with additional study, provide important information. Page & Turnbull's evaluation of this property was limited to age-eligible resources above ground and did not involve survey or evaluation of the subject property for the purposes of archaeological information.

Evaluation (Integrity)
In order to qualify for listing in any local, state, or national historic register, a property or landscape must possess significance under at least one evaluative criterion as described above and retain integrity. Integrity is defined by the California Office of Historic Preservation as "the authenticity of an historical resource's physical identity evidenced by the survival of characteristics that existed during the resource's period of significance," or more simply defined by the National Park Service as "the ability of a property to

convey its significance."[44] Established integrity standards are outlined by the *National Register Bulletin: How to Apply the National Register Criteria for Evaluation*. Seven variables, or aspects, that define integrity are used to evaluate a resource's integrity: location, setting, design, materials, workmanship, feeling, and association. A property must retain integrity under most or all of these aspects in order to retain overall integrity. If a property does not retain integrity, it can no longer convey its significance and is therefore not eligible for listing in local, state, or national registers.

1. *Location* is the place where the historic property was constructed.
2. *Design* is the combination of elements that create the form, plans, space, structure and style of the property.
3. *Setting* addresses the physical environment of the historic property inclusive of the landscape and spatial relationships of the building(s).
4. *Materials* refer to the physical elements that were combined or deposited during a particular period of time and in a particular pattern of configuration to form the historic property.
5. *Workmanship* is the physical evidence of the crafts of a particular culture or people during any given period in history.
6. *Feeling* is the property's expression of the aesthetic or historic sense of a particular period of time.
7. *Association* is the direct link between an important historic event or person and a historic property.

429-431 S. San Joaquin Street retains all seven of the aspects of integrity. The building has not been moved since its construction and, thus, retains integrity of location. Although the surrounding area has changed over time, a number of single- and multi-family houses and commercial buildings also dating to the late nineteenth and early twentieth centuries remain at their original locations directly next to or across from the subject property on S. San Joaquin Boulevard. As a result, the subject property retains its integrity of setting. Although some exterior alterations to the front porch, gable end, and rear and side windows are evident, the building's essential exterior features and materials that convey its significance as a multi-family house constructed in the Free Classic subtype of the Queen Anne style – including prominent front gable, wide flared eaves with cornice line modillions and dentils, full-width front porch, paired Tuscan column porch supports, original wood windows and doors, and wood lap siding – remain intact. Integrity of design, materials, workmanship, feeling, and association have also been retained.

Based on this analysis, 429-432 S. San Joaquin Street retains sufficient integrity to convey its significance under Criterion 3/C and therefore qualifies for listing on the National and California Registers.

Character-Defining Features

For a property to be eligible for national, state, or local designation, the essential physical features (or character-defining features) that enable the property to convey its historic identity must be evident. To be eligible, a property must clearly contain enough of those characteristics, and these features must also retain a sufficient degree of integrity. Characteristics can be expressed in terms such as form, proportion, structure, plan, style, or materials. The character-defining features of 429-431 S. San Joaquin Street include:

- Prominent front-facing gabled roof with wide, flared eaves
- Cornice with wood modillions and dentils
- One-story full-width front porch with paired Tuscan column supports mounted on solid wood railing
- Side cutaway bay window with gabled roof with flared eaves
- Wood lap siding
- Wood panel doors and sash windows with molded wood trim, some with decorative carved dentils
- Entries to multiple units at front and rear façades

Significance Evaluation: City of Stockton Landmark, Historic Site, or Structure of Merit

The subject building is not included in the Downtown Stockton Historic Resources Survey (2000) and is not located within a local historic district or zoning overlay or listed as a City of Stockton Landmark, Historic Site, or Structure of Merit. It is therefore not currently listed locally as a historic resource.

Landmarks

According to the Stockton Municipal Code Section 16.220.070, "In considering an artifact, natural feature, or structure for designation as a Landmark, the Board shall apply any or all of the following criteria:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Architectural Craftsmanship**. Its embodiment of elements demonstrating outstanding attention to architectural and/or engineering craftsmanship, design, detail, or materials;

[44] California Office of Historic Preservation, *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources* (Sacramento: California Office of State Publishing, 4 September 2001), 11; U.S. Department of the Interior, National Park Service, *National Register Bulletin: How to Apply the National Register Criteria for Evaluation* (Washington, D.C.: National Park Service, 1995), 44.

3. **Architectural Style.** Its exemplification of a particular architectural style or way of life important to the City, the State, or the Nation;
4. **Architectural Type.** Its exemplification of the best remaining architectural type in the City;
5. **Historic Event.** Its location as a site of a significant historic event;
6. **Heritage.** Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
7. **Visual Feature.** Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
8. **Relationship to Another Landmark.** Its relationship to any other landmark, if its preservation is essential to the integrity of that landmark;
9. **Significant Person.** Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation;
10. **Work of a Significant Person.** Its identification as the creation, design, or work of a person(s) whose effort has significantly influenced the heritage of the City, the State, or the Nation; or
11. **Natural Environment.** Its integrity as a natural environment that strongly contributes to the well-being of the people of the City, the State, or the Nation."[45]

Historic Sites & Structures of Merit
Historic Sites and Structures of Merit are designated by the same criteria. According to the Stockton Municipal Code Sections 16.220.090 and 16.220.100, the criteria for designating Historic Sites and Structures of Merit are the following:

1. **Archaeological Interest.** Its potential for yielding significant information of archaeological interest;
2. **Heritage**. Its character, interest, or value as a significant part of the heritage of the City, the State, or the Nation;
3. **Visual Feature of the City**. Its unique location or singular physical characteristic representing an established and familiar visual feature of the City;
4. **Way of Life.** Its exemplification of a particular way of life important to the City, the State, or the Nation;
5. **Historic Event.** Its location as a site of a significant historic event regardless of its current configuration, development, or use;
6. **Significant Person**. Its identification with a person(s) who significantly contributed to the culture and development of the City, the State, or the Nation; or
7. **Significant Person of a Specific National Origin.** Its identification with a person(s) representative of a specific national origin who have contributed to the culture and development of the City, the State, or the Nation."[46]

As evidenced in the previous evaluation, 429-431 S. San Joaquin Street appears to be significant at the local level under Criterion C/3 of the National Register and California Register and possesses sufficient integrity to be eligible for listing. The City of Stockton's criteria for the designation of Landmarks, Historic Sites, and Structures of Merit correspond approximately with those of the National Register and California Register; however, they do not appear to include an integrity requirement. In particular, criteria 2, 3, and 4 above for listing as a City of Stockton Landmark appear to correspond with Criterion C/3 of the National Register and California Register. Thus, the above evaluation for National Register and California Register Criteria C/3 can be extended to local designation under the corresponding criteria for listing as a City of Stockton Landmark, and the property appears to merit local designation as a City Landmark.

Conclusion
429-431 S. San Joaquin Street does appear to be eligible for individual listing in the National Register under Criterion C, the California Register under Criterion 3, and as City of Stockton Landmark under Criteria 2, 3, and 4. The subject building was constructed in 1904 and embodies the distinctive characteristics that are representative of a multi-family house that was built in the Free Classic subtype of the Queen Anne style. As such, the California Historical Resource Status Codes (CHRSC) of "3S," "3CS," and "5S2" have been assigned to the property, meaning that it has been found eligible for the National Register and California Register as an individual property through survey evaluation.[47]

[45] Stockton Municipal Code: 16.220.070, "Landmarks," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_070&frames=on.
[46] Stockton Municipal Code: 16.220.090, "Historic sites," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_090&frames=on; Stockton Municipal Code: 16.220.100, "Structures of merit," accessed July 9, 2019, https://qcode.us/codes/stockton/view.php?topic=16-7-16_220-16_220_100&frames=on.
[47] California State Office of Historic Preservation Department of Parks and Recreation, *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory,* Sacramento, November 2004.

***B12. References:**

Publications

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume I*. 2000.

Architectural Resources Group. *Stockton Downtown Draft Historic Resources Survey, Volume II*. 2000.

California Office of Historic Preservation. *Technical Assistance Series No. 7: How to Nominate a Resource to the California Register of Historical Resources,* Sacramento: California Department of Parks and Recreation, 2001.
———. *Technical Assistance Bulletin #8: User's Guide to the California Historical Resource Status Codes & Historical Resource Inventory Directory*. Sacramento: California Department of Parks and Recreation, 2004.

Gilbert, Lori. "Our Diversity: Native Americans First to Call Stockton home." *The Record*. November 29, 2014. Accessed June 17, 2019, https://www.recordnet.com/article/20141129/ENTERTAINMENTLIFE/141129569.

"History: A Look into Stockton's Past." Accessed June 19, 2019, http://www.stocktongov.com/discover/history/hist.html.

Kasser, Daniel. *Downtown Stockton*. San Francisco: Arcadia Publishing, 2005.

McAlester, Virginia Savage. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 2014.

Wood, R. Coke. "The Rise of Stockton." *San Joaquin Historian* IX., no. 1 (January-March 1973). San Joaquin County Historical Society.

Repositories (specific documents cited in footnotes)

Ancestry.com.

Cesar Chavez Public Library, Stockton, California.

City of Stockton Permit Center, Stockton, CA.

David Rumsey Historic Map Collection.

Newspapers.com.

San Joaquin County Assessor's Office, Stockton, CA.

San Joaquin County Historical Society & Museum, Lodi, CA.

San Joaquin County Recorder/Clerk's Office, Stockton, CA.

San Joaquin County Public Library Obituary Index, 1850-1991, FamilySearch.org.

UC Santa Barbara Library, Aerial Photograph Collection.